1		221 HW-8015B RESEARCH REPORTS	
	AEC RE	SEARCH AND	HW-80158
1	DEVELO	PMENT REPORT	
		IN-REACTOR MONITORI	NG
		OF ZIRCALOY-2 PRTR PRESSU	RE TUBES,
		PART III	
		JULY 1963 - NOVEMBER 196	3
		P. J. PANKASKIE	
7			
		DECEMBER 1963	
		DECEMBER 1903	
	HANFOR	D LABORATORIES	
		HANFORD ATOMIC PRODUCTS OPERA	TION
		RICHLAND, WASHINGTON	
		GENERAL & ELECTRI	C
e il			
			metadc100642
			illetauc100642

#### LEGAL NOTICE

This report was prepared as an account of Government sponsored work. Neither the United States, nor the Commission, nor any person acting on behalf of the Commission:

- A. Makes any warranty or representation, expressed or implied, with respect to the accuracy, completeness, or usefulness of the information contained in this report, or that the use of any information, apparatus, method, or process disclosed in this report may not infringe privately owned rights; or
- B. Assumes any liabilities with respect to the use of, or for damages resulting from the use of any information, apparatus, method, or process disclosed in this report.

As used in the above, "person acting on behalf of the Commission" includes any employee or contractor of the Commission, or employee of such contractor, to the extent that such employee or contractor of the Commission, or employee of such contractor prepares, disseminates, or provides access to, any information pursuant to his employment or contract with the Commission, or his employment with such contractor.

HW-80158

UC-25, Metals, Ceramics and Materials (TID-4500, 26th Ed.)

# $\begin{array}{c} \text{IN-REACTOR MONITORING} \\ \text{OF ZIRCALOY-2 PRTR PRESSURE TUBES,} \\ \text{PART III} \end{array}$

JULY 1963 - NOVEMBER 1963

Ву

P. J. Pankaskie

Materials Development
Reactor and Fuels Research and Development Operation
Hanford Laboratories

December 1963

FIRST UNRESTRICTED MAKE DISTRIBUTION MADE

# HANFORD ATOMIC PRODUCTS OPERATION RICHLAND, WASHINGTON

Work performed under Contract No. AT(45-1)-1350 between the Atomic Energy Commission and General Electric Company

Printed in USA. Price \$0.50. Available from the

Office of Technical Services Department of Commerce Washington 25, D.C.

Printed by/for the U. S. Atomic Energy Commission

-2- HW-80158

# IN-REACTOR MONITORING OF ZIRCALOY-2 PRTR PRESSURE TUBES, PART III

JULY 1963 - NOVEMBER 1963

#### INTRODUCTION

This is the third in a series of report on a surveillance program of in-reactor monitoring of Zircaloy-2 pressure tubes in the Plutonium Recycle Test Reactor (PRTR). The PRTR represents one of the first major elevated temperature applications of Zircaloy-2 as a load bearing structural material. In-reactor monitoring consists of (1) measuring the process tube inside diameters to detect creep, (2) measuring the gas gap between the process and aluminum calandria shroud tubes to indirectly detect bowing, (3) examining the process tube with a borescope-TV combination to detect mechanical damage or unusual localized corrosion areas, and (4) measuring the depth of marks caused from mechanical damage or localized corrosion.

The results of in-reactor inspections made before July, 1962 were reported in HW-73701 REV and HW-74731. (1, 2) The results of inspections made from July, 1962 through November, 1963 are reported here.

#### SUMMARY AND CONCLUSIONS

From July, 1962, through November, 1963, all Zircaloy-2 pressure tubes in all 85 process channels of the PRTR were inspected at least once, and a few were inspected several times. These inspections showed that approximately 1700 new fretted areas formed in the pressure tubes. There are now approximately 3200 fretted areas in all tubes in the PRTR.

An increase in fretted areas associated with the fuel element end bracket spacers appears to be roughly proportional to the number of times fuel elements were charged into each pressure tube.

During this reporting period, there was a significant increase in the number of fretted areas associated with single fuel rod wire wraps as compared to the number associated with end bracket spacers.

-3- HW-80158

There was no observable fretting corrosion associated with the circumferential fuel bundle bands on the Al-Pu or mixed oxide type fuel elements.

Enlarging the contact area of the end bracket spacers from  $\sim 1.5$  x 12.5 mm ( $\sim 1/16$  x 1/2 in.) to  $\sim 6$  x 12.5 mm ( $\sim 1/4$  x 1/2 in.) significantly reduced the severity of tube wall penetration by fretting. In no case did penetrations, associated with enlarged pads, exceed 0.025 mm (0.001 in.). There is some reason to believe that end bracket spacer pad enlargement also caused a decrease in severity of fretting associated with single rod spiral wire wraps but apparently had no effect on incidence.

Five pressure tubes were discharged during this reporting period. Two of these five were discharged because of suspected defects with depths of  $\sim 1/2$  mm ( $\sim 0.020$  in.) or greater.


#### DISCUSSION

#### Fuel Geometry

During this reporting period, the PRTR used fuel elements with a 19-rod cluster configuration and core materials of  $\rm UO_2$  and  $\rm PuO_2$ . The  $\rm UO_2$  elements are constructed differently from Al-Pu and mixed oxide elements. The Al-Pu and mixed oxide fuel elements are essentially the same except for the differences in overall weight. The essential structural difference between these and the  $\rm UO_2$  element is that the 19-rod bundle is held together by circumferential bands rather than a spiral bundle wire wrap as is the case for the  $\rm UO_2$  element (see Figure 1). Since about May, 1962, no new  $\rm UO_2$  spiral wire wrapped fuel elements were manufactured for use in the PRTR.

Beginning about May, 1962, new mixed oxide elements were constructed with enlarged area spacer pads at the upper and lower end brackets. These enlarged area pads are about 6 mm wide and 12 mm long ( $1/4 \times 1/2$  in.). Following the whole reactor inspection of June, 1962, a recommendation was made to enlarge the spacer pads on all elements then in the PRTR, providing it could be done without excessive damage to fuel elements. As a

-4- HW-80158



result, all mixed oxide elements were repadded with 6 x 12 mm (1/4 x 1/2 in.) spacers. None of the  $UO_2$  or Al-Pu type fuel elements were repadded.

The average number of  ${\rm UO}_2$  type fuel elements has decreased from 30 to 10 during this reporting period.

#### Visual Inspections

Since June, 1962, 110 visual inspections in the 85 process channels were made. These inspections show that, during this inspection period, the number of fretted areas in the pressure tubes has roughly doubled, and there are now approximately 3200 fretted areas distributed throughout the 8 ft active lengths of the pressure tubes (see Appendix B). The fretted areas are categorized according to location and cause of fretting as follows:

- (1) vertical marks associated with the spacer pads on the bracket at the top end of the fuel element
- (2) vertical marks associated with the spacer pads on the bracket at the bottom end of the fuel element
- (3) marks about 15° from vertical and associated with the wire wrap on individual fuel rods
- (4) marks about 45° from vertical and associated with the bundle wire wrap which spirals about the periphery of the bundle of 19 individual fuel rods that make up a PRTR fuel element
- (5) unclassified marks whose origin cannot be related to any of the above.

Appendix B shows the distribution of fretted areas and unclassified markings in the pressure tubes in accordance with the above categories. Since June, 1962, at which time all pressure tubes were inspected during one reactor outage, an average of about eight tubes were visually examined each reactor operating month. Several process channels were examined more frequently.

-6- HW-80158

Four process channels were reorificed to provide a flow rate about 7% above average to determine whether a slight increase in flow rate would increase the incidence and/or severity of fretting corrosion. There is not yet a clear cut effect. In fact, for these four process channels (1641, 1643, 1746, 2047) the increase in number of fretted areas appears to be less than the average for all process channels even though the four process channels operated for at least several months with spiral wire wrapped UO<sub>2</sub> fuel elements.

In about May, 1962, the first experimental "wide pad" (~ 6 x 12 mm) mixed oxide fuel element was charged into the PRTR. This element was charged into a process channel in which a new pressure tube was also installed to determine clearly the effect of enlarging the area of the end bracket spacer pads which contact the inside surface of the pressure tube. These initial experiments were made in one of the two process channels which had previously exhibited the most severe fretting with both  $\mathrm{UO}_2$  and Al-Pu fuel elements. Repeated visual examinations clearly showed that the severity of the fretting corrosion associated with the enlarged area end bracket spacer pads was reduced. Based on measurements made in subsequent inspections, it is apparent that enlarging the pad area has substantially reduced the severity of fretting corrosion associated with the end bracket spacer pads. To date no fretted areas, associated with the enlarged area pads, were found that exceeded 0.025 mm (0.001 in.) in depth. It also appears that "repadding" reduced to some extent the severity of fretting corrosion associated with the spiral wire wraps on individual fuel rods. There is, however, no evidence that the incidence of fretting corrosion has been altered.

Since the number of  ${\rm UO}_2$  fuel elements used in the PRTR was generally diminishing, and since repadding was not expected to alter either the incidence or severity of fretting associated with bundle wire wraps, none of the  ${\rm UO}_2$  type fuel elements were repadded. For similar reasons, none of the Al-Pu fuel elements were repadded.

-7- HW-80158

Considering all observations made since June, 1962, it appears that the overall severity of fretting corrosion is substantially less than was the case for reactor operation before June, 1962. Since June, 1962, five new marks, with depths greater than 0.25 mm (0.010 in.) have been found in four process channels (see Appendix A). Three of these marks originated through fretting corrosion (two associated with fuel element end bracket spacer pads and one associated with the spiral wire wrap on a single fuel rod). The origin of the other two marks are unknown and they do not now appear to be attributable to fretting action. On the whole, most newly fretted areas are less than 0.025 cm (0.001 in.) deep.

Since June, 1962, there has been an average of about 10 UO<sub>2</sub> type fuel elements used in the PRTR that were neither repadded nor redesigned. It appears that factors other than enlargement of the end bracket spacer pads on the mixed oxide fuel elements helped decrease the severity of frettting corrosion. While there are no clear cut observations to define all such factors, one that may have contributed to the reduction in severity of fretting corrosion was the replacement of the straightening vane just upstream of the inlet tee on the lower ring header. During decontamination of the primary coolant system in the latter part of 1962 a broken vane on the flow straightener was found. Failure was generally attributed to corrosion fatigue. (3)

Process channel inspection in June, 1962, showed that the majority of severely fretted process channels were close to and to the left of the inlet tee of the lower ring header. Process channels close to and to the right of the inlet tee were generally less affected. Inspection data, obtained after replacement of the flow straightener, shows no such patterns. Hence, one is inclined to conclude that the failed vane of the flow straightener did adversely affect both the incidence and severity of fretting in some of the process channels. Moreover, if the same basic cause of the severe fretting were also the cause for failure of the one vane in the flow straightener, a more uniform pattern of severe fretting in all process channels adjacent to the inlet tee would have been expected.

There now appears to be some indication that certain process channels sustain more fretting when charged with a particular fuel element. Table I lists process channels which have sustained appreciably more fretting than is typical. In about one half of these process channels, the greater incidence of fretting can be associated with a particular fuel element. In the remainder of these cases, it is attributable to either or both of two fuel elements. In Process Channel 1653, at least 52 of 71 new fretted areas were formed during the period when Fuel Element 1049 was in the channel. Both the incidence and severity was greater than average for the PRTR.

Two moderately fretted areas associated with the narrow spacer pads of the end brackets on the fuel elements were found in Process Channel 1354. In this channel the general severity of fretting is above average but the incidence is only moderately greater than average. Between the inspections of June, 1962, and June, 1963, the only fuel elements charged into this process channel were 5053 and 5066. The narrow end bracket spacer pads of either or both of these Al-Pu fuel elements caused moderately severe fretting. Process Channel 1548 sustained 28 new fretted areas while charged with Fuel Element 1099. Inspection of this fuel element in December, 1963, revealed a broken wire wrap. Although this fuel element was recharged in Process Channel 1548 eight times, it is believed that the greater incidence of fretting is attributable to the broken wire wrap since the bulk of the new fretted areas are of the bundle wire wrap category (see Appendix B). One might suspect that if this fuel element had not been recharged so frequently the severity of fretting might have been greater and the incidence reduced.

Process Channel 1647 incurred a great incidence of fretting in both the single rod and bundle wire wrap categories while charged with Fuel Elements 1067 and 1039. Based on residence time and number of rechargings, it is believed that most of the fretting was associated with Fuel Element 1067. After final discharge, Fuel Element 1067 was found to have a broken fuel rod wire wrap. The time during which this wire was broken is not known. Perhaps the incidence of fretting in the single rod wire wrap category is attributable to the broken rod wire wrap. However, the greatest incidence of

-9**-** HW-80158

TABLE I

FRETTING CORROSION BEHAVIOR OF FUEL ELEMENT AND PROCESS CHANNEL COMBINATIONS SINCE JUNE, 1962<sup>(a)</sup>

Process Channel	New Fretted Areas	Element	Element Type	Residence, Months	Times Charged Into Process Channel	Fretted Areas Associated With Listed Fuel Element
1346 <sup>(b)</sup>	52	5090 or 5171	Al-Pu Moxtyl	7 1	4 2	42
1354	20	5053 or 5066	Al-Pu Al-Pu	2 4	2 2	20 (one 0,010 in. one 0,015 in. at U&L FES; see Appendix B)
1445	30	5087 or 5060	Al-Pu Al-Pu	2 4	2 2	30
1457	32	5115 or 5131	Moxtyl Moxtyl	2 4	$\frac{2}{2}$	32
1546	36	5074 or 5030	Al-Pu Al-Pu	3 5	2 3	36
1548 <sup>(c)</sup>	28	1099	$_{ m UO}_2$	5	8	28
1552	43	1098	$_{2}^{\mathrm{UO}}$	5	4	43
1558	41	5113 or 5140	Moxtyl Moxtyl	3 10	2 4	32
1647 <sup>(d)</sup>	54	1067 or 1039	${^{\mathrm{UO}}_2}_{\mathrm{UO}_2}$	7 1	4 1	54
1659	29	1097	$^{ m UO}_2$	4	4	29
1653	71	1049	UO <sub>2</sub>	6	5	52 (one 7 mil UFES, one 12 mil SRW; see Appendix B)
1956	53	1034	UO	5	5	33+
2053	37	1030 1049	$^{\mathrm{UO}}_2$	5 1	2 1	25 (one 6-8 mil mark; see
<sub>1350</sub> (e)	20	1 050 1 021 1 033 1 034	$\begin{smallmatrix} \mathrm{UO}_2 \\ \mathrm{UO}_2 \\ \mathrm{UO}_2 \\ \mathrm{UO}_2 \\ \end{smallmatrix}$	1 3 1 2 1/2	2 3 1 3	Appendix B) 20
1651	25	1100	$UO_2$	6	4	25

<sup>(</sup>a) The fuel elements listed here are only those which exhibit unusual corrosion behavior.

<sup>(</sup>b) Experienced difficulties in charging Fuel Element 5171 on April, 1963.

<sup>(</sup>c) When examined December, 1963, Fuel Element 1099 had a broken wire wrap.

<sup>(</sup>d) When examined June, 1963, Fuel Element 1067 had a broken single fuel rod wire wrap.

<sup>(</sup>e) When examined February, 1963, Fuel Element 1050 had a broken wire wrap.


-10- HW-80158

fretting was in the bundle wire wrap category for which there is no obvious reason. Process Channel 1350 operated with  ${\rm UO}_2$  Fuel Elements 1050, 1021, 1033, and 1034 between the inspections of 6/62 and 6/63. During this period there was an increase of 13 fretted areas in bundle wire wrap category. Subsequent fuel element inspections disclosed a broken wire wrap on Fuel Element 1050; broken wraps are currently the prime suspects for the cause of the bundle wire wrap fretting. Fuel Element 1034, however, was charged into this process channel 3 times for a total residence time of about 2 1/2 months. Since the performance of Fuel Element 1034 appears to have been poor in Process Channel 1956, it may also have been the cause of the fretting in Process Channel 1350. If so its performance appears to have been somewhat better in Process Channel 1350 than in Process Channel 1956. Fuel Element 1100 was charged into Process Channel 1651 only four times for a total residence of about 6 months. During this period 25 new fretted areas were formed of which 17 were in the bundle wire wrap category. Examination in December, 1963, disclosed a broken wire wrap which is believed to be the cause of the bundle wire wrap fretting.

From data in Table I, it is apparent that unusual fretting behavior is not readily related to defective fuel elements; and, hence, there must be other reasons for such behavior. Another possibility is the relative differences in the diameters of fuel elements and pressure tubes. However, at this time, there are not sufficient data to attempt any such correlations.

The pressure tubes from Process Channels 1358 and 1558 were discharged during this reporting period for suspected defects. Figure 2 shows a positive replica of the suspected defect found in Process Channel 1358. In-reactor measurements showed this suspected defect to be about 0.5 mm (0.020 in.) deep, 3 mm (1/8 in.) wide, and 6 mm (1/4 in.) long. Destructive examinations confirmed these measurements. The origin of this suspected defect is not now known. Its location in the pressure tube does not correspond to fuel element end brackets, spiral wire rod or bundle wraps, or fuel element bands. Hence, it does not appear that this suspected defect originated from fretting action.

HW-80158



#### FIGURE 2

Suspected Defect Inside Tube in Process Channel 1358  $\sim 2-1/2 \,\mathrm{X}$ 

Negative No. 0632307

-12- HW-80158

Figure 3 shows the suspected defect found in Process Channel 1558. Its shape, location and orientation also indicate that this suspected defect did not originate from fretting action. In-reactor measurements and examination suggest a "blister" type defect. Its radial dimension is about 0.5 mm (0.020 in.). This pressure tube has not yet been destructively examined.


#### Diameter and Gas Gap Measurements

Inside diameter and gas gap measurements were made during each scheduled inspection through about June, 1963. At this time, these measurements were discontinued because of excessive radiation damage to these measuring instruments. These measurements will be resumed upon installation of new instruments scheduled for January, 1964. Results of measurements through June, 1963, showed no significant changes in inside diameter and therefore little or no creep deformation. Gas gap measurements showed that the helium gas annuli for those tubes measured were within specified limits.

#### ACKNOWLEDGMENTS

The author wishes to express his appreciation to L. D. Turner for his helpful discussions and valuable reactor operations information and to D. R. Doman and P. M. Jackson for their help in conducting the in-reactor inspection.

- 13 - HW - 80158



 $\frac{\text{FIGURE 3}}{\text{Suspected Defect Inside Tube in Process Channel 1558}} \\ \sim 2\text{-}1/2\,\text{X}$ 

Negative No. 0632607-1

-14- HW-80158


#### REFERENCES

- 1. D. R. Doman and P. J. Pankaskie. <u>In-Reactor Monitoring of Zircaloy-2</u>
  PRTR Pressure Tubes, Part I, September, 1960 May, 1962,
  HW-73701 REV. May, 1962.
- 2. D. R. Doman and P. J. Pankaskie. <u>In-Reactor Monitoring of Zircaloy-2</u>

  PRTR Pressure Tubes, Part II, May and June 1962, HW-74731.

  August, 1962.
- 3. J. J. Cadwell. Quarterly Progress Report, Metallurgy Research, October, November, and December, 1962, HW-76228. January, 1963.

-15- HW-80158



#### APPENDIX A

-16- HW-80158

 $\frac{\text{APPENDIX B}}{\text{SUMMARY OF INSPECTIONS SINCE MAY 1962}}$ 

P. C.	Inspection Dates	LFES	UFES	<u>BW</u>	SRW	Uncl.	Totals	Change
1047	6-62 10-63	4 10	3 11	$\begin{matrix} 3 \\ 12 \end{matrix}$	4	3 2	13 39	 26
1049	6-62 10-63	2 8	<b>4</b> 9	15 16	- <del>-</del> 6	<b>4</b> 3	$\begin{array}{c} 25 \\ 42 \end{array}$	 17
1051	6-62 10-63	6 15	$\frac{2}{15}$	7 8	2 4	4	$\begin{array}{c} 21 \\ 42 \end{array}$	 21
1053	5-62 2-63 10-63	3 3 12	1 3 3	1 9 9	2 2	  	5 18 27	13 9
1144	6-62 10-63	7 9	5 11	6 17	2 6	1	21 43	22
1146	6-62 10-63	8 11	<b>4</b> 5	10 16	4 4		26 36	10
1148(a)	10-63	14 23	$\begin{smallmatrix}4\\13\end{smallmatrix}$	 	 11	3	18 50	30
1150 <sup>(a)</sup>	6-62 10-63	8 21	5 16	1	1 5	2	16 43	 27
1152	6-62 11-63	$\begin{matrix} 6 \\ 12 \end{matrix}$	3 7	$\frac{1}{2}$	2 6	1	13 27	 14
1154 <sup>(a)</sup>	10-63	4 15	$\begin{array}{c} 2 \\ 10 \end{array}$	13 13	2 8	3	21 49	 28
1156 <sup>(b)</sup>	6-62 2-63 10-63	5 8 10	2 2 5	3 9 7	1 2 5	1  10	1 2 21 3 7	9 16
1243	New tube installed o	n 6-22-						
	12-62 11-63	$\frac{1}{4}$	2 6		8		3 18	15
1245	6-62 8-63	10 15	8 14			1 2	19 31	12
1247	6-62 11-62 11-63	6 9 11	4 6 9	  4	  5	  1	10 15 30	5 15
1249 <sup>(a)</sup>	6-62 8-63	6 16	9 12	- <del>-</del> 	3 15	2 5	20 48	 28
1251	6-62 8-63	3 6	2 7	2 5	 	$\frac{1}{2}$	8 20	12

<u>P.C.</u>	Inspection Dates	LFES	UFES	$\underline{\mathtt{BW}}$	SRW	Uncl.	Totals	Change
1253(b)	6-62 8-63	6 13	5 13	4 4	6 6	4	25 36	11
1255	6-62	5 12	4 8	5 2	3 2	$\frac{4}{2}$	21 26	 5
1257	New tube installed 6 12-62 11-63	-10-62 1 10	 4			 2	1 16	 15
1342	6-62 8-63	5 11	1 4		7 5		13 20	- <i>-</i> 7
1344	6-62 8-63	<b>4</b> 9	3 7	 	2 11	5 2	14 29	 15
1346 <sup>(c)</sup>	6-62 8-63	7 23	3 10	 10	 19	 	10 62	 52
1348	5-62 1-63 6-63	1 5 8	1 4 9	$\begin{matrix}1\\4\\10\end{matrix}$	  5	 3	3 13 35	10 22
1350	6-62 6-63	4 7	4 8	28 41	6 6		42 62	 20
1352 <sup>(a)</sup>	wrap found on F.E. 1050 on	5 16	4 10	3 9	6 7	2 6	20 48	28
1354 <sup>(b)</sup>	6-62 6-63	8 14	5 11	1 4	8 12	<b>4</b> 6	26 46	 20
1356	New tube installed 6 11-62 New tube installed 1	2			3		5	
	12-62 1-63	1 1 11	2 2 5	 	  2	  	3 3 18	0 15
1358 <sup>(d)</sup>	9-63	2 9 9	5 6 6	11 13 14	 5 4	2 2 3	20 35 36	15 1
1441	New tube installed 9 6-62 2-63	-4 <b>-</b> 63 3 5	4 6	3 4	10 7	1	20 23	3
1443 <sup>(a)</sup>	6-62 12-62 1-63 10-63	4 8 9 20	4 11 14 19	1	  11 18	  	9 19 34 57	10 15 23

-18- HW-80158

P. C.	Inspe	ction Dates	LFES	<u>UFES</u>	$\underline{\mathtt{BW}}$	SRW	Uncl.	Totals	Change
1445 (c)	6-62 4-63		$\begin{smallmatrix} 4\\11\end{smallmatrix}$	$\begin{matrix} 7 \\ 13 \end{matrix}$		1 18	1 1	13 43	 30
1447	6-62 4-63		3 9	$\begin{smallmatrix}2\\10\end{smallmatrix}$	8 16	2 6	1	16 41	 25
1449 <sup>(a)</sup>	5-62 4-63		5 13	1 5	 	$\begin{smallmatrix}1\\12\end{smallmatrix}$	 	7 30	 23
1451	6-62 2-63		3 6	4 4	3 14	10 6	 	20 30	10
1453	6-62 2-63		3 3	2 4	10 10	- <i>-</i> 4	2	17 21	4
1455		ube installed 4		7	6		3	22	
1457 <sup>(b, c)</sup>	4-63		3					3	
1457	6-62 4-63		$\frac{8}{12}$	3 9	5 <b>7</b>	3 19	4	19 51	32
1459	6-62	(Broken wire wrap found on F.E. 1029 on 12-63)	2 2	6 6	7 7			15 15	0
1542	6-62 4-63	12 00)	3 4	3 4	4 8	5 5		15 21	 6
1544	6-62 4-63 10-63		5 16 17	3 6 8	1 1 2	  2	5 5 4	14 28 33	 14 5
1546 <sup>(c)</sup>	4-63		5 11	4 14	1	$\begin{matrix}1\\22\end{matrix}$	 	11 47	 36
1548 <sup>(c)</sup>	6-62	(Broken wire wrap found on F.E. 1099 on 12-63)	6 6	4 8	9 29	8 12		27 55	28
1550	6-62 2-63	ube installed 6	-21-61 2 5	1 4	7 7	 		10 16	- <i>-</i> 6
1552 <sup>(c)</sup>	6-62 4-63		1 19	2 6	1 18	4		4 47	43 43
1554	6-62 4-63		10 16	3 11	10 14	 6	3 2	26 49	 23
1556	6-62 11-63		14 14	6 8	 1	5 5	2 1	27 28	1

-19- HW-80185

P.C.	Inspection Date	LFES	UFES	<u>BW</u>	SRW	Uncl.	Total	Change
1558 <sup>(c, d)</sup>	6-62 2-63 10-63 Tube discharged 10	6 8 19 -11-63	3 3 7	16 20 24	4 14 19	1 2 2	30 47 71	17 24
1641	High flow orificed ~ 6-62 (Broken wire 12-62 wrap found on F.E. 1044 on 12-62)		6 6 9	7 4 14	1 8 1	3  	17 19 29	 2 10
1643	High flow orificed ~ New tube installed 5 6-62 4-63		2 8	3	 5	3 1	11 21	 10
1645	6-62 11-62 4-63	3 3 10	$\begin{matrix}2\\2\\4\end{matrix}$	1 3	  5	  4	6 7 26	 1 19
1647 <sup>(c)</sup>	4-63	4 8	3 7	6 41	$\begin{smallmatrix}2\\11\end{smallmatrix}$	- <i>-</i> 2	15 69	 54
1649 <sup>(c)</sup>	4-63	1 5	$\frac{1}{2}$	 18	 5	- <del>-</del> 1	2 31	 29
1651 <sup>(c)</sup>	4-63	5 7	3 4	 17	- <i>-</i> 7	2	10 35	 25
1653 <sup>(b, c)</sup>	6-62 4-63 8-63 10-63	6 11 11 10	4 9 4 9	12 14 28 55	5 16 24 24	  	27 50 67 98	23 17 31
1655	6-62 4-63	7 16	10 18		4 10	2	23 44	 21
1657	6-62 4-63	5 14	4 13		1 5		10 32	 22
1659	New tube installed 1 6-62 4-63	5 6	2 3	4 17	 1		11 27	 16
1742	6-62 8-63	$\begin{matrix} 3 \\ 12 \end{matrix}$	$\begin{matrix}2\\12\end{matrix}$	9 5	5 2		19 31	 12
1744	6-62 8-63	12 18	4 14	 	$\frac{2}{1}$		18 33	 15
1746	6-62 8-63	11 14	3 7	- <del>-</del> 5	 	 	14 26	8

-20- HW-80185

<u>P.C.</u>	Inspection Date	LFES	<u>UFES</u>	$\underline{\mathbf{BW}}$	SRW	<u>Uncl.</u>	Total	Change
1748	6-62 5-63	5 15	6 5	10 7	3 13	4 3	28 43	- <b>-</b> 1 5
1750	6-62 5-63	3 3	$\frac{1}{3}$	23 29	6 7	1	34 42	- <i>-</i> 8
1752 <sup>(a)</sup>	6-62 5-63	9 16	$\begin{matrix} 5 \\ 14 \end{matrix}$	1 5	- <del>-</del>		14 41	 26
1754	6-62 11-62		4 ot reco		4	4	27	
	5-63	15	11	7	7	3	43	16
1756	Tube from P.C. 185					0	0.4	
	6-62 5-63	13 19	5 6	9 11	5 7	2 1	34 44	10
1758	6-62 5-63	5 8	6 7	8 8	1 7	1	20 31	 11
1843	6-62 9-63	<b>4</b> 9	- <i>-</i> 4	13	10 6		14 31	 17
1845	5-62 9-63	13 21	$\begin{matrix} 3 \\ 10 \end{matrix}$	 	 6		16 37	 21
1847	6-62 11-62 5-63	8 12 14	6 8 9		1  8	7 7 4	21 27 35	7 8
	New tube installed 7 8-63	1	1	1			2	
1849	6-62 9-63	$\begin{matrix} 7 \\ 14 \end{matrix}$	5 11	6 11	$\begin{matrix} 7 \\ 20 \end{matrix}$		25 56	31
1851	6-62 9-63	6 11	3 1 -	2	<b>4</b> 6		15 27	 12
1853	6-63 9-63	9 20	$7\\12$	 1	$\frac{1}{2}$	5 	22 35	 13
1855 <sup>(a)</sup>	5-62 11-63	7 13	1 11	 	 5	3	$\begin{matrix} 8 \\ 32 \end{matrix}$	 24
1857	New tube installed 9	-28-61						
	5-62 6-62 1-63	4 4 5	4 5 5	1 2 5	$egin{array}{c} 1 \ 2 \ 1 \end{array}$	3 1 	13 14 16	1 2
1944	6-62 9-63	3 9	2 8	4 4	3 12	1	13 33	 20
1946 <sup>(d)</sup>	6-62 9-63 Tube removed 11-6-	4 11 ·63	6 7	17 18	2 5		29 41	12

<u>P.C.</u>	Inspection Date	LFES	UFES	BW_	SRW	Uncl.	Total	Change
1948	6-62 11-62 12-62 1-63	8 11 No me 14	6 7 asurem 10	3  ients ob 11	3 6 tained	2	21 25 35	4
1950	6-62 9-63	5 17	5 10	 5	 4	5 	15 36	1 <u>0</u>  21
1952	6-62 9-63	10 12	5 10	2	5 10	2	24 32	- <i>-</i> 8
1954	6-62 9-63	6 13	4 15	14 8	$\begin{array}{c} 4 \\ 11 \end{array}$		28 47	 19
1956 <sup>(c)</sup>	6-62 9-63	1 10	1 4	 33	- <i>-</i> 8	- <b>-</b>	2 55	 53
2047	Hi-flow orificed 7-6-62 1-63	62 2 7	3 8	4 11	1 3	6	1 6 29	 13
2049	6-62 9-63	4 6	1 4	 11	7 6		1 2 27	 15
2051	6-62 6-63	5 11	6 13	8 10	3		19 37	 18
2053 <sup>(b, c)</sup>	6-62 8-63 9-63	$\begin{matrix} 4\\7\\12\end{matrix}$	3 5 6	11 25 28	2 4 8	  3	20 41 57	21 16
in indic Averag	-62 total marks ated number of PC's e number of marks	85	306 85	56	195 52	39	437	
As of 1 in indic	tube 1-63 total marks cated number of PC's e number of marks	~ 5 975 85	$ \begin{array}{c} \sim 4 \\ 724 \\ 85 \end{array} $	~ 6 798 63	~ 4 561 73	~ 3 110 33 38	174	
per	tube	~11	~ 8	<b>~</b> 8	<b>~</b> 8	<b>~</b> 3		
of n	ses in number narks tage increase				366 188	1 1' 0	737	
	e number of fretted e number of fretted						$\begin{array}{c} 17 \\ 37 \end{array}$	

<sup>(</sup>a) Indicates tube wherein the large increase in incidence of fretting corrosion is attributable to a large number of fuel elements charge-discharges.

<sup>(</sup>b) Indicates defect 10 mils or greater in depth.

<sup>(</sup>c) Indicates tube where the large increase in incidence of fretting corrosion is probably attributable to a specific element (see Table I).

<sup>(</sup>d) Indicates defect 20 mils or greater in depth.

# INTERNAL DISTRIBUTION

Copy Number	
1	F. W. Albaugh
2	J. A. Ayres
3	E. R. Barker
4	C. A. Bennett
5	D. C. Boyd
6	J. H. Brown
7	J. J. Cadwell
8	K. O. Creek
9	D. H. Curtiss
10	L. J. Defferding
11	R. L. Dickeman R. L. Dillon
12	R. L. Dillon
13	D. R. Doman
14	E. A. Evans
15	M. D. Freshley
16	J. M. Fox, Jr.
17	O. H. Greager
18 19	H. Harty
20	V. R. Hill
20 21	R. L. Knecht
$\frac{21}{22}$	D. R. Koberg A. P. Larrick
23	W. R. Lewis
$\frac{23}{24}$	L. M. Loeb
25	R. Neidner
26	R. E. Nightingale
27 - 39	P. J. Pankaskie
40	L. T. Pedersen
41	W. E. Roake
42	W. D. Richmond
43	D. P. Schively
44	R. I. Smith
45	J. C. Tobin
46	L. D. Turner
47	J. R. Spink
48	E. E. Voiland
49	O. J. Wick
50	R. D. Widrig
51	R. D. Widrig W. K. Winegardner N. G. Wittenbrock
52	N. G. Wittenbrock
<b>5</b> 3	300 Files
54 5 5	Record Center
55	Technical Publications
56 - 60	Extra

# EXTERNAL DISTRIBUTION (SPECIAL)

Number of Copies	
2	AEC - DRD Attn: R. M. Grube W. R. Voigt
3	AEC - RLOO Attn: P. M. Midkiff J. M. Musser O. W. Rathbun Technical Information Library
1	AEC - Washington Military Liaison Committee Attn: Captain D. E. McCoy, Staff Assistant to the Chairman
2	Atomic Energy of Canada, Ltd (AECL) Attn: P. A. Ross-Ross W. R. Thomas
1	Battelle Memorial Institute Attn: J. Kissel
1	GE-APED San Jose, California Attn: K. P. Cohen
2	G.E. Technical Data Center, Schenectady
1	G.E. Vallecitos Atomic Laboratory Pleasanton, California Attn: L. P. Bupp
1	REACTOR, A.G. Wurenlingen, Switzerland
1	United Kingdom Atomic Energy Authority Attn: E.C.W. Perryman Development and Engineering Group Culcheth, Lans, England

Ptd.	Standard Distribution	Ptd.	Standard Distribution
3	ABERDEEN PROVING GROUND	1	CHANCE YOUGHT CORPORATION
1	AEROJET-GENERAL CORPORATION	1	CHICAGO PATENT GROUP
1	AEROJET-GENERAL NUCLEONICS	1	CLEVITE CORPORATION
8	AERONAUTICAL SYSTEMS DIVISION	1	COMBUSTION ENGINEERING, INC.
1	AEROPROJECTS INCORPORATED	1	COMBUSTION ENGINEERING, INC. (NRD)
	AIR FORCE CAMBRIDGE RESEARCH	1	DEFENCE RESEARCH MEMBER
	LABORATORIES	1	DENVER RESEARCH INSTITUTE
1	AIR FORCE INSTITUTE OF TECHNOLOGY	1	DEPARTMENT OF THE ARMY
1	ALLIS-CHALMERS MANUFACTURING COMPANY	1	DOW CHEMICAL COMPANY, ROCKY FLATS
1	ALLIS-CHALMERS MANUFACTURING COMPANY, WASHINGTON	4	DU PONT COMPANY, AIKEN
1	ALLISON DIVISION-GMC	1	DU PONT COMPANY, WILMINGTON
10	ARGONNE NATIONAL LABORATORY	1	FEDERAL AVIATION AGENCY
1	ARMY ENGINEER RESEARCH AND DEVELOP-	1	FENIX AND SCISSON, INC. (LAS VEGAS)
_	MENT LABORATORIES	1	FENIX AND SCISSON, INC. (TULSA)
1	ARMY MATERIALS RESEARCH AGENCY	1	FRANKFORD ARSENAL
1	ARMY MISSILE COMMAND	1	FRANKLIN INSTITUTE OF PENNSYLVANIA
1	ARMY RESEARCH OFFICE, DURHAM	1	FUNDAMENTAL METHODS ASSOCIATION
1	ARMY TANK-AUTOMOTIVE CENTER	2	GENERAL ATOMIC DIVISION
1	ATOMIC ENERGY COMMISSION, BETHESDA	2	GENERAL DYNAMICS/FORT WORTH
1	AEC SCIENTIFIC REPRESENTATIVE, BELGIUM	2	GENERAL ELECTRIC COMPANY, CINCINNATI
1	AEC SCIENTIFIC REPRESENTATIVE, FRANCE	1	GENERAL ELECTRIC COMPANY, PLEASANTON
1	AEC SCIENTIFIC REPRESENTATIVE, JAPAN		
3	*ATOMIC ENERGY COMMISSION, WASHINGTON	1	GENERAL ELECTRIC COMPANY, SAN JOSE
4	ATOMIC ENERGY OF CANADA LIMITED	1	GENERAL NUCLEAR ENGINEERING
4	ATOMICS INTERNATIONAL	·	CORPORATION
1	AVCO CORPORATION	1	GOODYEAR ATOMIC CORPORATION
4	BABCOCK AND WILCOX COMPANY	1	IIT RESEARCH INSTITUTE
2	BATTELLE MEMORIAL INSTITUTE	2	IOWA STATE UNIVERSITY
2	BEERS (ROLAND F.), INC.	2	JET PROPULSION LABORATORY
1	BERYLLIUM CORPORATION	3	KNOLLS ATOMIC POWER LABORATORY
1	BRIDGEPORT BRASS COMPANY	1	LOCKHEED-GEORGIA COMPANY
2	BROOKHAYEN NATIONAL LABORATORY	1	LOCKHEED MISSILES AND SPACE COMPANY (NASA)
1	BUREAU OF MINES, ALBANY	3	
1	BUREAU OF SHIPS (CODE 1500)	3	LOS ALAMOS SCIENTIFIC LABORATORY
1	CARBORUNDUM COMPANY		M & C NUCLEAR, INC.
		1	MALLINCKRODT CHEMICAL WORKS

Ptd.	Standard Distribution	Ptd.	Standard Distribution
1	MARITIME ADMINISTRATION	1	SAN FRANCISCO OPERATIONS OFFICE
1	MARTIN-MARIETTA CORPORATION	2	SANDIA CORPORATION, ALBUQUERQUE
1	MATERIALS RESEARCH CORPORATION	1	SANDIA CORPORATION, LIVERMORE
1	MOUND LABORATORY	1	SPACE TECHNOLOGY LABORATORIES, INC. (NASA)
1	NASA LEWIS RESEARCH CENTER	1	STANFORD UNIVERSITY (SLAC)
1	NASA MANNED SPACECRAFT CENTER	1	SYLVANIA ELECTRIC PRODUCTS, INC.
2	NASA SCIENTIFIC AND TECHNICAL INFORMATION FACILITY	1	TENNESSEE VALLEY AUTHORITY
2	NATIONAL BUREAU OF STANDARDS	2	UNION CARBIDE CORPORATION (ORGDP)
1	NATIONAL BUREAU OF STANDARDS (LIBRARY)	5	UNION CARBIDE CORPORATION (ORNL)
2	NATIONAL LEAD COMPANY OF OHIO		UNION CARBIDE CORPORATION (ORNL-Y-12)
1	NAVAL POSTGRADUATE SCHOOL	1	UNION CARBIDE CORPORATION (PADUCAH PLANT)
3	NAVAL RESEARCH LABORATORY	2	UNITED NUCLEAR CORPORATION (NDA)
1	NEW BRUNSWICK AREA OFFICE	1	U. S. GEOLOGICAL SURVEY, DENVER
	NEW YORK OPERATIONS OFFICE	1	U. S. GEOLOGICAL SURYEY, MENLO PARK
1	NUCLEAR MATERIALS AND EQUIPMENT CORPORATION	1	U. S. GEOLOGICAL SURVEY, WASHINGTON
1	NUCLEAR METALS, INC.	1	U. S. PATENT OFFICE
1	OFFICE OF ASSISTANT GENERAL COUNSEL	2	UNIVERSITY OF CALIFORNIA, BERKELEY
	FOR PATENTS (AEC)	2	UNIVERSITY OF CALIFORNIA, LIVERMORE
2	OFFICE OF NAVAL RESEARCH	1	UNIVERSITY OF PUERTO RICO
1	OFFICE OF NAVAL RESEARCH (CODE 422)	1	WESTERN RESERVE UNIVERSITY (MAJOR)
1	PETROLEUM CONSULTANTS	4	WESTINGHOUSE BETTIS ATOMIC POWER
4	PHILLIPS PETROLEUM COMPANY (NRTS)		LABORATORY
1	PICATINNY ARSENAL	1	WESTINGHOUSE ELECTRIC CORPORATION
1	POWER REACTOR DEVELOPMENT COMPANY	1	WESTINGHOUSE ELECTRIC CORPORATION (NASA)
3	PRATT AND WHITNEY AIRCRAFT DIVISION	1	YANKEE ATOMIC ELECTRIC COMPANY
1	PURDUE UNIVERSITY	325	DIVISION OF TECHNICAL INFORMATION
1	RAND CORPORATION		EXTENSION
1	RENSSELAER POLYTECHNIC INSTITUTE	<b>75</b> †	OFFICE OF TECHNICAL SERVICES, WASHINGTON
1	RESEARCH ANALYSIS CORPORATION		

UC-25

<sup>\*</sup>New listing or change in old listing.
†These copies should be shipped directly to the Office of Technical Services, Department of Commerce, Washington 25, D. C.

