

NOTICE

CERTAIN DATA
CONTAINED IN THIS
DOCUMENT MAY BE
DIFFICULT TO READ
IN MICROFICHE
PRODUCTS.

Unclassified
By Authority [REDACTED] Fe 11 May 1973

DJK revised 5/11/73
PM Eck 5/14/42 [REDACTED]
TO: HOOD WORLINGTON

CC: 1. Hood Worthington 3-3046
2. Simon-Mackey-Smith-700-Files
3. P.W. Crane
4. C.N. Gross - 300 Files
5. F.H. Dineen
6. G.P. Kidder
7. J.A. Dahlen
8. Pink Copy
9. Yellow Copy

MAY 28, 1945

WES
JL

100-B UNIT PURGE
MAY 20, 1945

THIS DOCUMENT CONSISTS OF 5 PAGES

N 5 OF 5 COPIES, SEE 5

INTRODUCTION

The 100-B unit was purged with 100 ppm. Super-Cel for about one hour on May 20th.

CONCLUSIONS

1. Satisfactory pressure drop film removal was realized on tubes in the 0.240" and 0.175" orifice zones. Film removal was not as complete in the 0.140" zone and means of improving the purge in this zone should be considered.
2. There was essentially no plugging of header screens during the first 50 minutes of the purge. The plugging which occurred during the last few minutes of the purge was not serious enough to warrant replacing any of the header screens.

DETAILS

The purge was conducted similar to the previous solids purges made at 100-B Area. The solids feed was started at 8:33 A.M. and stopped at 9:31 A.M.

The individual riser flow rates remained essentially constant the first 50 minutes of the purge. The last few minutes of the purge the flow recorders indicated that header screens off of risers C and D started plugging. This plugging, however, was not serious enough to warrant replacing any of the screens.

Pressure Drop

The pressure drop data for Sample Room B and Panellit tubes are given in Tables I and II. These tables show the pressure drop increases before and after the purge on the basis of 0 and 250 MW power. The 250 MW data after the purge, May 24th data, were the lowest pressure drops reached after the purge. The pressure drop recoveries are given in Table III.

The pressure drop recovery on the 0.240" orifice zone is about the same as that realized on previous purges. The recovery on the 0.175" orifice zone was much better than that obtained on previous purges. On the 0.140" orifice zone, however, about 2 psi less film was removed during the purge than was deposited

DO NOT REPRODUCE

MASTER
DISTRIBUTION RESTRICTED TO U.S. ONLY

88601800 0511
AUG 05 1992
EX

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

Hood Worthington

3-3046

5-20-45

• during the interval between the two last purges. If this were allowed to continue indefinitely, an objectionable amount of film would remain in the pieces in this zone. It is felt that purging the unchilled section of the unit for a longer period of time would reduce the amount of residual film in the 0.140" orifice zone after a purge.

• The pressure drop decreases during the purge are shown in Figure I for three of the pressure drop tubes.

C. P. KIDDER
TECHNICAL DEPARTMENT

• Per P. A. Dahlen
P. A. Dahlen

CPK

ZW

SPECIAL REVIEW
FINAL DETERMINATION
DECLASSIFICATION DATE
2/24/82
BY _____ DATE _____

UNCLASSIFIED

3

SAMPLE ROOM DATA
PRESSURE DROP - FEB. 24TH BASE TUBES

Power Level-MW	PSI Above Base			
	Before Purge May 19th	May 20th	After Purge May 20th	May 24th
2465	250	0	0	250
2469	14.8	9.3	2.3	0.6
2473	17.2	10.2	0.9	-1.8
2483	18.0	8.9	0.1	-2.5
Average	16.0	9.3	0.7	-1.6

PRESSURE DROP - APRIL 29TH BASE TUBES

PSI Above Base

Power Level-MW	PSI Above Base			
	Before Purge May 19th	May 20th	After Purge May 20th	May 24th
2375	250	0	0	250
2475	15.1	7.9	1.4	-1.9
2479	16.7	9.5	0.5	-2.0
2575	15.4	8.3	1.0	-1.2
Average	13.7	9.2	0.3	-0.8
Average	15.2	8.7	0.8	-1.5

TABLE II
PANELLIT DATA
PRESSURE DROP - PSI ABOVE JAN. 29TH BASES

ORIFICE ZONES.

	0.240"	0.175"	0.140"
Before Purge (May 18th)	15	30	35
After Purge (May 22nd)	4	-3	12


TABLE III
PRESSURE DROP RECOVERY

Percent

0.240" Orifice Zone	74
0.175" Orifice Zone	110
0.140" Orifice Zone	66
2/24 Base Pressure Drop Tubes	89*

*Calculated using the low point of March 15th, -3.9
psi above base, as the zero point.

FIGURE 1
CHANGE IN TUBE PRESSURE DROP
DURING PURGE



DECLINING

3-3083

DATE

**FILED
MAY 16 1981**

3



