~~CONFIDENTIAL
RESTRICTED DATA~~

ATOMIC ENERGY ACT
OF 1954

WANL-QC-PRES-4223

MASTER

CONTROL OF REACTOR QUALITY

Title Unclassified

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

Astronuclear Laboratory
Westinghouse Electric Corporation

~~CONFIDENTIAL
RESTRICTED DATA~~

ATOMIC ENERGY ACT
OF 1954

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency Thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

DISCLAIMER

Portions of this document may be illegible in electronic image products. Images are produced from the best available original document.

32

Inps-c
64-942

WESTINGHOUSE ASTRONUCLEAR LABORATORY

~~CONFIDENTIAL~~
~~RESTRICTED DATA~~
ATOMIC ENERGY ACT
OF 1954

CONTROL OF REACTOR QUALITY

MASTER

CONTENTS

SECTION	DESCRIPTION	PAGE
I	INTRODUCTION	1
II	WANL QUALITY CONTROL PROGRAM	1
III	CONTROL OF PROCURED MATERIAL	1
	A. Supplier Evaluation	
	B. Control of Procurement Documentation	
	C. Supplier Surveillance	
	D. Receiving Inspection at WANL	
IV	CONTRACTOR FABRICATED MATERIAL	3
	A. Release for Assembly	
	B. In-Process Inspection	
	C. Inspection at WANEF	
	D. Final Inspection at WANL	
	E. Quality Surveillance During Transit	
	F. Receiving Inspection at NRDS	

V

SUMMARY

7

SPECIAL REREVIEW
FINAL
DETERMINATION
Class: U

Reviewer: TR U Class: 4-20-82

Classification cancelled (or changed to) DOC
by authority of H.F.C. TIC, date SEP 7 - 1973

~~CONFIDENTIAL~~
~~RESTRICTED DATA~~
ATOMIC ENERGY ACT
OF 1954

NOTICE
This report was prepared as an account of work sponsored by the United States Government. Neither the United States nor the United States Energy Research and Development Administration, nor any of their employees, nor any of their contractors, subcontractors, or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness or usefulness of any information, apparatus, product or process disclosed, or represents that its use would not infringe privately owned rights.

DISTRIBUTION OF THIS DOCUMENT UNLIMITED

CONTROL OF REACTOR QUALITY

I INTRODUCTION :

Close control of reactor hardware quality from the drawing board to the point of use is considered a prime requisite for the NERVA Program. The concentration of knowledgeable personnel at the Large site provides an integrated capability to resolve all quality problems during any phase of procurement, receiving or assembly in an expedient manner. Such a capability in a development program of this nature is considered essential. The WANL Quality Control operation is geared to take full advantage of this concentration of "know how" in each of its functions.

II WANL QUALITY CONTROL PROGRAM:

The Quality Control Program provides for the determination, through inspection and testing, of the conformance of the reactor hardware to the engineering drawing and specification requirements and the documentation of all variations from such requirements. The Quality Control Department exercises this control in two broad areas:

1. Contractor Procured Material
2. Contractor Fabricated Material

III CONTROL OF PROCURED MATERIAL:

A. Supplier Evaluation

Prior to order placement, suppliers of reactor hardware are evaluated by Quality Control to see that they are capable of meeting the stringent quality requirements of the Laboratory. Only those judged capable of producing a quality product are approved and used as NERVA suppliers.

B. Control of Procurement Documentation

NERVA hardware ordering is reviewed by Quality Control to see that all necessary quality requirements will be met. The requirement for process descriptions, inspection plans and other Quality controls are made a part of the ordering document at this point. Pertinent process descriptions and inspection plans resulting from such requirements are coordinated for approval with the responsible design groups by Quality Control before the supplier is authorized to start fabrication.

C. Supplier Surveillance

During the fabrication process, Quality Control monitors the suppliers quality operations and witnesses inspection or performs source inspection as necessary. Non-conforming material discovered at any point in the procurement process is handled by a variation procedure. The non-conformance is identified on a WANL Variation Request and disposition is obtained by coordination with the responsible Design Engineer, the

Reliability Engineer and Quality Engineer. Unanimous approval is required for acceptance or for rework. A single disapproval rejects the material.

Material is released for shipment from the supplier only after the Quality Control Representative is satisfied that all of the Quality requirements have been met.

D. RECEIVING INSPECTION AT WANL (Large, Pa.)

Incoming NERVA hardware is inspected prior to acceptance. This inspection is defined by the responsible Quality Engineer and will vary in degree based upon the amount of WANL Quality Control exercised in the supplier's plant and the confidence that WANL has established in the supplier. As a minimum it will require the verification of major characteristics of the material. On certain critical hardware it will consist of a complete verification of characteristics.

During the Receiving Inspection process, on the initial receipt of parts, the responsible design engineer will be contacted by the inspector so that he may witness the inspection. In this way, the designer can determine that the parts being inspected meet the full intent of the drawing and specification requirements. If necessary, the designer may call in Materials Specialists or Nuclear Specialists since all design contributors are located at the WANL site.

Non-conforming material discovered at this point is identified on a WANL Non-conforming Material Disposition Request (NMDR). The Quality Control Inspector calls in the responsible Design Engineer, Reliability Engineer and Quality Engineer and an appropriate disposition is agreed upon.

After acceptance, NERVA reactor hardware is moved to a controlled storage area to await further processing. The Quality documentation at this point permits a rapid evaluation of acceptable material variations and provides traceability by lot or serial number all the way back to its raw material.

The control steps outlined in this section (CONTROL OF PROCURED MATERIAL) provide WANL with all reasonable assurance that the NERVA reactor hardware that will be assembled at this site meets the stringent quality requirements for the NERVA reactor program.

IV CONTRACTOR FABRICATED MATERIAL:

A. Release For Assembly

Since it is recognized that materials with "conditionally approved" variations may exist on parts or sub-assemblies having identical part numbers, no material is released for additional operations until its variations are reviewed by the Design Engineer for whom the assembly is to be manufactured. When the variation action has been reviewed by the responsible engineer, Quality Control releases the material for use in a specific assembly.

B. IN-PROCESS INSPECTION AT WANL

Upon release from stores all reactor hardware is under continuous Quality Control surveillance during all phases of assembly, instrumentation and test.

The inspection operations are planned for each assembly by the responsible Quality Engineer and integrated into a Reactor Assembly Process Outline (RAPO). The RAPO defines detailed assembly operations which provide the assembly technician with all of the information (techniques, tools, fixtures and etc.) required in addition to the drawing. Where inspection operations are not complex they are detailed in the RAPO with the assembly operations. In the event that inspection operations are complex they are referenced in the RAPO and defined by a Quality Control Operation Instruction (QCOI).

A discussion of one such RAPO and QCOI combination will illustrate their contents and value. For example:

Reactor Assembly Process Outline (RAPO No. 1001) describes the orificing of a particular fuel element. It defines each assembly operation in considerable detail. It spells out the holding fixture for the element, the preparation of the fixture prior to use, the care that must be exercised in its use, the orientation of the element in the fixture and many additional points. In this RAPO the inspection operations are defined by reference to a Quality Control Operating Instruction (QCOI No. 2).

QCOI No. 2 provides all of the detailed information that the Quality Control Inspector requires to fully inspect, evaluate and document each inspection operation. Using this QCOI as an example we find that it contains the following:

- 1) A statement regarding the importance of the fuel element orificing to the overall success of the reactor operation.
- 2) The use of Assembly Inspection Data Report Form No. 1001 designed specifically for recording the results of each inspection defined by this QCOI.
- 3) A description of and calibration procedure for the special test equipment used to perform certain inspection operations.
- 4) Detailed instructions for performing each inspection operation.
- 5) Detailed instructions for documenting the results of the following inspection operations:
 - a) Verification of the weight of the fuel element.
 - b) Establishment of the average loading found by entering the Reactor Analysis Element Weight vs Loading Correlation Tables after the element weight is verified.
 - c) Verify previous inspections for
 - 1) Handling damage
 - 2) Effective channel diameter
 - 3) Length
 - 4) Bow
 - 5) Twist
 - 6) Dimension across flats
 - d) Inspection of location of each color coded orifice against proper location shown on the Reactor Analysis Orificing Document for each element.
 - e) Photograph (color) each orificed element for re-verification of orifice placement by the Reactor Analysis Section.
 - f) Verify cement cure time
 - g) Perform orifice seal test to determine that there are no leak paths around the orifice.
 - h) Monitor removal and storage of orificed elements to prevent damage.

All RAPO's and QCOI's are coordinated with the responsible engineering sections for approval prior to use.

Each time an assembly is to be made for the first time the inspector contacts the responsible Design Engineer so that he may witness the assembly and inspection operations. In this way, the designer can verify compliance with the design intent while providing guidance over and above the detailed instructions provided by the RAPO or the QCOI. A place for design sign-off is provided on the Assembly Route Card for "first of a kind" assemblies.

When non-conforming material is found at any point in the assembly process it is immediately identified by a red tag and a Non-conforming Material Disposition Request (NMDR). The inspector then calls responsible engineers from the Design, Reliability and Quality Control sections to make immediate disposition. If for any reason the disposition cannot be made promptly the non-conforming material is placed in a Quality Control Bond Room until agreement on disposition can be reached.

If, as a result of the NMDR action, rework is required it is defined by this material review team. Rework that cannot be accomplished in the assembly area is logged out by Quality Control and forwarded to the rework source. While most of the anticipated rework can be accomplished by WANL at the Large Site, tentative agreements have been reached with two cleared shops in this area to provide stand-by rework capability 24 hours a day. Should the need arise, WANL can fallback upon the capability of its own Westinghouse Laboratories and manufacturing facilities in the Pittsburgh area.

Any rework sent to an off-site source will be followed by WANL Quality Control to verify compliance to the rework instructions.

Upon completion of assembly at WANL (Large, Pennsylvania) certain items will be packaged and forwarded to WANEF (Waltz Mill, Pennsylvania) for the Preassembly Experiment. The inspection of the item immediately prior to shipment and upon arrival at WANEF will in general be conducted by the same individual.

C. INSPECTION AT WANEF (Waltz Mill, Pennsylvania)

The inspection at this facility is an extension of the WANL (Large, Pennsylvania) activity. The same assembly and inspection crew will move to the WANEF site to perform assembly and inspection operations on the PAX. Upon completion of the Pre-Assembly Experiment the reactor hardware items will be re-packaged and returned to WANL. Upon their return they will be completely disassembled and the individual parts reinspected in accordance with approved RAPO's and QCOI's to verify that no damage resulted from the PAX. These items would then be re-assembled using the same assembly procedures and inspection procedures discussed in III-B, "IN-PROCESS INSPECTION AT WANL".

D. FINAL INSPECTION AT WANL

In building up the final reactor assembly RAPO's and QUOI's will provide detailed instructions for assembly, inspection and documentation. Inspection operations must be performed and signed off by the Quality Control Representative before assembly can proceed beyond the inspection point.

Any non-conformance that is identified during the final reactor assembly is handled essentially as outlined in III-B except that in addition, the customer representative must approve any variations, re-work instructions and re-inspection instructions defined by the Non-Conforming Material Disposition Request. This requirement is also applicable to certain hardware defined as "End Items".

During final assembly all WANL-AGC interfaces will be gaged to insure the proper mating of the reactor with the pressure vessel, pressure vessel closure and the nozzle.

A substantial number of documentary photographs will be taken at all stages of final assembly. These will be used as visual standards for subsequent assemblies and to facilitate the careful visual inspection of the reactor upon receipt at NRDS. A final visual inspection check list will be used just prior to placing the reactor into the shipping container. This same check list will be available for the NRDS receiving inspection.

Upon completion of the inspection of the reactor, Quality Control will witness placement of the reactor in the Reactor Shipping Container and perform checks to insure the integrity of the container. Prior to transit, Quality Control will verify and document that the shock instrumentation package is properly calibrated and operating.

All pertinent quality documentation that has been accumulated during all phases of sub-assembly and final assembly will be compiled into a quality data package that will be transmitted to NRDS shortly after the reactor has been shipped from WANL.

E. QUALITY SURVEILLANCE DURING TRANSIT (WANL TO NRDS)

A representative of WANL Quality Control will be a member of a technical team that accompanies the reactor during the trip from WANL to NRDS. This representative will be responsible for monitoring the operation of the shock instrumentation package and other environmental data throughout the trip.

F. RECEIVING INSPECTION AT NRDS

At NRDS all work on the reactor will be monitored constantly by Quality Control. The same Quality Control Representative that accompanied the shipment will provide the continuity of quality surveillance from the assembly floor at WANL through the receiving inspection operations at NRDS.

The receiving inspection operations at NRDS will consist of the following:

1. A review of all environmental data compiled during transit.
2. A detailed visual examination of the shipping container.
3. A constant check of shock instrumentation and other environments during removal from shipping container and placement in the trunnion fixture.
4. A detailed visual inspection of the reactor using the same check list that was used during the final visual inspection at WANL.
5. An inspection of all installed instrumentation which will include continuity and resistance checks.

Upon completion of the receiving inspection operations, Quality Control over the various phases of assembly, test car preparation, transit to the test cell and test cell installation will be conducted in accordance with written instructions. These instructions will be coordinated with the appropriate design representatives to insure that all design objectives are met.

Non-conformance identified at NRDS will be documented on a Non-Conforming Material Disposition Request. The inspector will coordinate the NMDR with representatives of Design Engineering, Quality Engineering, and the Customer Material Review Representative and arrive at an appropriate disposition.

The actual inspection at NRDS will be conducted by Quality Control personnel that are resident at the Site. WANL Quality Control at Large, Pennsylvania will retain the prime responsibility for quality and will monitor the site Quality Control activity to make sure that the quality objectives of the NERVA Program are met.

V. SUMMARY:

It is our firm belief that the control of reactor quality described briefly on these pages will insure the delivery of a high quality assembled reactor to test at NRDS. In our judgement, an important part of this assurance comes from the close association of our integrated technical team with all phases of manufacture, procurement, inspection, assembly and test.

Prepared by:
W. O. Anthony
WANL Quality Control Manager
For Presentation on 22 April 1963

~~CONFIDENTIAL~~
~~RESTRICTED DATA~~
~~Atomic Energy Act 1954~~

QUALITY CONTROL OPERATING INSTRUCTION
WESTINGHOUSE ASTRONUCLEAR LABORATORY
Westinghouse Electric Corporation
P.O. Box 10864 Pittsburgh 36, Pennsylvania

QCOI NO. 1 REV. A
DATE: APRIL 18, 1963
Supersedes:
Rev. 0 Date: January 13, 1963

SUBJECT

ORIFICE JETS

FUEL CLUSTER ASSEMBLY

INSPECTION AND TEST

APPROVED:

APPROVED:

QUALITY CONTROL

RELIABILITY

APPROVED:

APPROVED:

REACTOR ANALYSIS

REACTOR MECHANICAL DESIGN

~~CONFIDENTIAL~~
~~RESTRICTED DATA~~
~~Atomic Energy Act 1954~~

QUALITY CONTROL OPERATING INSTRUCTION

Subject: Orifice Jets, Fuel Cluster Assembly

GENERAL

Purpose: This Operating Inspection Instruction is designed to afford maximum assurance that production, inspection, testing functions fully comply with the applicable drawing and specification requirement for orifice jets. Such assurance is deemed necessary in view of the most critical nature of the orifice jets, failure of which could result in fuel component failure and resultant irrevocable damage to the reactor.

Scope: This instruction is applicable to the inspection and quality control of orifice jets as received from suppliers through inspection, test and assembly, to include source surveillance of in-process and final acceptance inspection by WANL Quality Control representatives at suppliers.

IMPLEMENTATION

- I. Procurement: (A) All suppliers shall have been surveyed by WANL Quality Control Supplier Surveillance prior to the awarding of a contract to determine quality systems capabilities. Only those suppliers meeting the requirements of WANL Quality Control Specification 101 shall be approved.
- (B) Approved suppliers will furnish an inspection plan detailing characteristic by characteristic the principle gaging methods and frequency of inspection to WANL Quality Control for approval. The implementation and effectiveness of the approved plan will be monitored by WANL Quality Control Supplier Surveillance.
- (C) Material (303SST per PDS 10706FF) - Two copies of the actual ladle analysis of each heat will be supplied by the manufacturer with each shipment. This ladle analysis will show actual readings obtained for chemical composition and mechanical properties as required by PDS 10706FF.
- (D) The WANL Quality Control Department will perform sufficient surveillance and detailed source inspection to assure the supplier's continued compliance with all of the above.
- (E) Extreme care shall be exercised in handling orifice jets in order to preclude damage to the critical sharp corner and inside diameter of each piece.
- (F) Suppliers will package orifice jets for shipment in strict accordance with WANL PS 294559.

II. Receiving Inspection:

A cursory examination for shipping damage and physical count without actual handling of individual orifices, i.e., visual scanning of shipping pallets to ascertain quantities on each individual pallet, will be conducted by WANL Receiving Department.

WANL Quality Control Receiving Inspection will perform dimensional inspection of each lot of orifices in accordance with Inspection Instruction (WANL Form 1060) for applicable part number and Quality Control Sampling Plan No. 2, Rev. 1.

- (A) Inspectors will select samples at random from Shipping Pallets by lot and place on Sample Inspection Pallet.
- (B) White nylon gloves are to be worn at all times while handling orifices.
- (C) Upon loading, Sample Inspection Pallet will be degreased per WANL PS 294520, paragraph 4.1, using Trichloroethylene solvent.
- (D) The inside diameter of each piece will be determined to the nearest .0001 inch by insertion of precision plug gage pins. To afford protection to the critical sharp corner, these plug gages will be inserted carefully from the .0925 diameter end of each piece only and will not extend to the sharp corner.
- (E) The above mentioned plug gage, with the orifice still on it, will then be placed in a vee block which has previously been mounted on the optical comparator, Excello 30" screen set to 50X magnification. In this position the plug gage will be rotated for verification of all external dimensions and applicable concentricities in conjunction with the plastic overlay chart NT 400003.
- (F) The surface finish of the inside diameter, 32 micro-inch finish, and the sharp corner will be inspected visually by binocular microscope at 100X magnification.
- (G) Upon completion of dimensional inspection, the sample inspection lot will be returned to Shipping Pallet with careful handling to prevent any damage to the sharp corner. Inspector will initiate Inspection Route Sheet and forward with lot.
- (H) All Shipping Pallets for the incoming lot will be degreased per paragraph (C) above. Stamp route sheet.
- (I) After degreasing, the Shipping Pallet will be enclosed in polyethylene envelopes. Air shall be evacuated from packages by utilizing a domestic type vacuum cleaner with the hose end reduced to 1/4" diameter piece of tubing. Withdraw tubing and heat seal end.

III. Orifice Flow Test:

Upon completion of dimensional inspection, degreasing and packaging, shipping pallets will be transported to the environmentally controlled test laboratory for orifice flow inspection and final visual examination.

Orifices will be tested 100% by the Restriction Flow Comparator. In order to preclude intermixing of sizes, only one pallet of orifices will be permitted at the test stand at any one time.

Flow test will be conducted as outlined below:

(A) Restriction Comparator Calibration

1. With the Meriam micro-metering valve closed and no vacuum applied adjust dual scales until both manometers read zero.
2. Insert one of the master test orifices in the restriction adapter of the restriction flow fixture.
3. Adjust the Meriam micro-metering valve to apply exactly 54.4 inches of water primary vacuum on manometer number one.
4. Read secondary vacuum on manometer number two.

(B) Test

1. Adjust manometer tubes for a zero reading when no vacuum is applied.
2. Insert the orifice to be tested in the appropriate adapter.
3. Adjust the Meriam micro-metering valve to apply 54.4 inches of water to manometer number one.
4. On manometer number two, read the flow valve of the orifice being tested. When the flow is found to fall within the acceptance band established by Reactor Analysis, a plastic cap of the proper "D" diameter identification code color will be placed on the orifice and it will be returned to the plastic container. Those pieces which fall beyond flow band limits will be placed in a sealed, clearly identified scrap container.
5. Return the vacuum to zero.
6. Remove the orifice.
7. Insert the next orifice to be tested and repeat step "1" to "6" above.

- 4 -

8. A flow inspection record sheet shall be completed following the test of each box lot. This record will reflect the number of pieces accepted and rejected, and will provide a "Reason for Rejection" block. A copy of this report will be attached to the container of accepted pieces, and additional copies will be filed by the Quality Control Department.
9. Complete Route Sheet and Stamp.
 - (C) Visual Examination - Immediately after each orifice has been flow tested a visual inspection will be performed by microscope at 100X magnification to assure that there are no burrs, nicks or scratches at the sharp corner. Complete Route Sheet and Stamp.
 - (D) Following visual inspection, orifices of the same size shall be capped with color coded plastic caps at the sharp corner end and placed in peg holed plastic blocks and enclosed in plastic boxes which will be sealed with plastic tape and moved to the assembly area store room. Inspection Route Sheet completed to date will be forwarded with each lot of orifices.

~~Atomic Energy Act of 1954~~

ORIFICE JETS

~~CONFIDENTIAL~~
~~RESTRICTED DATA~~
~~Atomic Energy Act - 1954~~

~~CONFIDENTIAL~~
~~RESTRICTED DATA~~

~~Atomic Energy Act of 1954~~

QUALITY CONTROL OPERATING INSTRUCTION
WESTINGHOUSE ASTRONUCLEAR LABORATORY
Westinghouse Electric Corporation
P.O. Box 10864 Pittsburgh 36, Pennsylvania

QCOI NO. 2 REV. 0
DATE: APRIL 18, 1963
Supersedes:
Rev. 0 Date: January 13, 1963

SUBJECT

ORIFICE JET ASSEMBLY

INSPECTION AND TESTS

APPROVED:

APPROVED:

QUALITY CONTROL

RELIABILITY

APPROVED:

APPROVED:

REACTOR ANALYSIS

REACTOR MECHANICAL DESIGN

~~CONFIDENTIAL~~
~~RESTRICTED DATA~~

~~Atomic Energy Act of 1954~~

QUALITY CONTROL OPERATING INSTRUCTION

Subject: Jet Orifice Assembly

GENERAL

Purpose: It is the responsibility of the Quality Control Department to ensure that all assembly operations fully satisfy drawing and specification requirements. The placement of orifices into fueled elements constitutes one of the most critical of assembly and inspection responsibilities. The purpose of this QCOI is to present a detailed description of the inspection operations which will occur during orificing and to provide instruction for Quality Control technicians in the preparation and processing of Assembly Inspection Data Report No. 1001 (Ref. Attachment A).

Scope: The instructions presented herein shall be applicable during the orificing of all fueled elements at WANL.

IMPLEMENTATION

Assembly Inspection Data Report No. 1001 (hereafter referred to as AIDR No. 1001) will be used by the Assembly Inspector in conjunction with Reactor Assembly Process Outline (RAPO) 1001. All assembly and inspection operation numbers denoted on the form and herein refer directly to those designated by RAPO 1001. AIDR 1001 consists of two pages. At the top of both pages the Inspector will insert the complete element serial number and its sector, row, cluster and element location identification code. The serial number will be obtained from both the element and the applicable Reactor Analysis Crificing Document. The revision of the Crificing Document must also be recorded. Sheet 2 of AIDR 1001 will be used solely to provide a written record of the size and color code of each orifice as it is placed in the assigned element channel. Similar sheets will be provided for irregular elements. All other inspections will be recorded on Sheet 1 of the form. These inspections will be performed as follows:

Operation 15 - Record Element Weight and Average Measured Loading.

(A) Weight

Upon notification that elements are to be removed from suitcases for transfer to the orificing tables, the Assembly Inspector will verify the accuracy of the Quality Control scales to the nearest .01 gram. These scales will be located outside the Accountability cage. As the elements are passed through the window of the cage for placement on the transfer cart, the inspector will periodically weigh a series of elements and compare his findings with those which have been recorded, to the nearest .1 gram, on the Reactor Assembly Element Card. The failure of a pair of readings for any one element to coincide shall be cause for return of the complete cart lot to the vault custodian for confirmation of all previous weighings. The inspector will record the weight of every element in the applicable space of AIDR 1001.

(B) Average Measured Loading

As the inspector enters the weight of each element on AIDR 1001, he will refer immediately to the applicable Reactor Analysis Orificing Document, obtain the specified average measured loading and enter it also in the space provided. He will then refer to the Reactor Assembly Element Weight versus Loading Correlation Tables, determine the average loading and enter it on the AIDR. A deviation of $\pm 2.0\%$ from the loading specified by the Program Document shall be cause for rejection.

Operation 35

Inspect Elements for Handling Damage, Effective Channel Diameter, Length, Bow and Dimension over Hex Flats.

This operation constitutes the Quality Control Department's incoming inspection of elements at WANL. It will occur after Reactor Assembly personnel have placed the elements in the trough of the orificing table (reference drawing NT 400025). Operation Steps A and B below, will be required for 100% of the elements. The remaining Steps will apply to one element selected at random from each suitcase. The rejection of one element for any characteristic will be cause for inspection of all elements from the suitcase. All inspections will be recorded.

(A) Handling Damage

Each element will be inspected visually, but in detail, for nicks, scratches, cracks and similar defects which could be incurred during transport and storage. A 10 power glass will be employed whenever unaided inspection is deemed insufficient.

(B) Effective Channel Diameter

This inspection is to verify both the flow characteristics of individual channels and the proper orientation of the channel pattern. The inspector will first calibrate the air column indicator (Sheffield Model MP-12) by inserting the adapter nozzle into a precisely reamed standard of known channel diameter. All equipment will be identical to that employed at Cheswick. After calibration, a minimum of three channels, chosen at random, will be tested on each element. The inspector will record the channel location number and the channel diameter to the nearest .0001 in. He will then immediately refer to the Reactor Analysis Orificing Document and record the diameters of the respective channels as specified therein. A deviation of $\pm .0002$ in. between measured and specified diameter shall be cause for rejection.

(C) Length, Bow and Twist

One element from each suitcase (19 element maximum capacity) will be carefully placed in Inspection Fixture . This fixture is identical to that employed at Cheswick. The length ($52.000 \pm .005$), bow (.005/in. of face to nearest end) and twist (.008 max. any face) will be measured and recorded.

+ .000

(D) Dimension Over Hex Flats (.754 - .002)

Using a 0-1 in. micrometer with spindle graduations of .0001 in., three measurements will be taken, one from each of three adjacent sides, at different points over the length of the element. If all readings are within tolerance, record the maximum deviation from .754 in.

Operation 45

Record orificing cement type and batch identification number on AIDR 1001.

Operation 55

Record identification color code and listed orifice size as each orifice is placed in position.

As stated above, the inspector will record the insertion of each orifice on Sheet 2 of AIDR 1001, and will verify each placement, as it occurs, against the proper Reactor Analysis Orificing Document. He should at all times be alert to see that channels are orificed in sequence (1 through 19), that the area is kept clear of all foreign matter and unnecessary tooling, that a minimal amount of sealant consistent with specification requirements is applied and that the elements and the orifices are continuously handled with care. Departure from the above, or any other act or condition which might in any way jeopardize the successful completion of the program will be reported immediately to the Inspection Supervisor. If at any time an orifice should be dropped, it will be scrapped. The Inspector will denote satisfactory completion of element's orificing in the space provided on Sheet 1 of the AIDR.

Operation 65

Photograph Completely Orificed Element.

A color photograph will be taken of each element immediately upon completion of the orificing process. This will be accomplished in the manner shown by Illustration A, attached. To avoid delay, the camera (Kodak Crown Graphics) will be prepositioned on a mobile cart for ease of transport between orificing stations. Additional equipment includes Ektachrome film, Polaroid Land Film holder and reflector type flood lamps. A mirror is provided to permit the serial number of the element to become an integral part of the record. One copy of the photograph will be attached to the AIDR and filed in the office of the Inspection Supervisor. A second copy will be forwarded to Reactor Analysis for verification and filing.

Operation 85

Orifice Seal Test.

No element will be removed from the orificing table until the proper curing time (8 hour minimum) has elapsed. Following curing, the Orifice Seal Test cart bearing a tank of helium, a regulator, flow lines and 19 channel adapter will be positioned at the orifice side of the table. The adapter will be placed about the periphery of each element, evacuated and 70 psi pressure applied. Leakage, as specified by Reactor Analysis directive, will be checked at the opposite end of the element in channel sequential order (1-19), by use of an electro-chemical detection device. Care must be exercised to avoid the inadvertent omission of a channel.

ASSEMBLY INSPECTION DATA REPORT NO. 1001

ELEMENT S/N _____

CORE LOC. IDENT. _____ SECTOR _____ ROW _____ CLUSTER _____ ELEMENT _____

THIS INSPECTION OPERATION IS BASED ON THE ARRAYAL REQUIRED BY REACTOR ANALYSIS CORE ORIFICING DIRECTIVE NO. _____ REV. _____. THE ORIFICE DIAMETER AND IDENTIFICATION COLOR CODE WERE RECORDED IN EACH SPACE BELOW AT THE PLACE AND TIME OF ACTUAL ASSEMBLY.

(REFERENCE OPERATION 55 RAPO No. 1001)

DATE OF INSPECTION _____ INSPECTOR'S STAMP _____

ORIFICE ARRAYAL PHOTOGRAPH

ILLUSTRATION A

NOTE:
ALL ALUM. SURF. SHALL BE ANODIZED UNLESS OTHERWISE SPECIFIED.

REFERENCE ENG.

TOOL NO. 900025
D. SPEC. NO. 751215BT

DATE	REV	DESCRIPTION	BY
10/1/63	1	ORIFICE LEAKTEST FIXTURE DESIGN CONCEPT	14663
10/1/63	2	1709J761	14663
10/1/63	3	1709J761	14663
10/1/63	4	1709J761	14663
10/1/63	5	1709J761	14663
10/1/63	6	1709J761	14663
10/1/63	7	1709J761	14663
10/1/63	8	1709J761	14663
10/1/63	9	1709J761	14663
10/1/63	10	1709J761	14663
10/1/63	11	1709J761	14663
10/1/63	12	1709J761	14663
10/1/63	13	1709J761	14663
10/1/63	14	1709J761	14663
10/1/63	15	1709J761	14663
10/1/63	16	1709J761	14663
10/1/63	17	1709J761	14663
10/1/63	18	1709J761	14663
10/1/63	19	1709J761	14663
10/1/63	20	1709J761	14663
10/1/63	21	1709J761	14663
10/1/63	22	1709J761	14663
10/1/63	23	1709J761	14663
10/1/63	24	1709J761	14663
10/1/63	25	1709J761	14663
10/1/63	26	1709J761	14663
10/1/63	27	1709J761	14663
10/1/63	28	1709J761	14663
10/1/63	29	1709J761	14663
10/1/63	30	1709J761	14663
10/1/63	31	1709J761	14663
10/1/63	32	1709J761	14663
10/1/63	33	1709J761	14663
10/1/63	34	1709J761	14663
10/1/63	35	1709J761	14663
10/1/63	36	1709J761	14663
10/1/63	37	1709J761	14663
10/1/63	38	1709J761	14663
10/1/63	39	1709J761	14663
10/1/63	40	1709J761	14663
10/1/63	41	1709J761	14663
10/1/63	42	1709J761	14663
10/1/63	43	1709J761	14663
10/1/63	44	1709J761	14663
10/1/63	45	1709J761	14663
10/1/63	46	1709J761	14663
10/1/63	47	1709J761	14663
10/1/63	48	1709J761	14663
10/1/63	49	1709J761	14663
10/1/63	50	1709J761	14663
10/1/63	51	1709J761	14663
10/1/63	52	1709J761	14663
10/1/63	53	1709J761	14663
10/1/63	54	1709J761	14663
10/1/63	55	1709J761	14663
10/1/63	56	1709J761	14663
10/1/63	57	1709J761	14663
10/1/63	58	1709J761	14663
10/1/63	59	1709J761	14663
10/1/63	60	1709J761	14663
10/1/63	61	1709J761	14663
10/1/63	62	1709J761	14663
10/1/63	63	1709J761	14663
10/1/63	64	1709J761	14663
10/1/63	65	1709J761	14663
10/1/63	66	1709J761	14663
10/1/63	67	1709J761	14663
10/1/63	68	1709J761	14663
10/1/63	69	1709J761	14663
10/1/63	70	1709J761	14663
10/1/63	71	1709J761	14663
10/1/63	72	1709J761	14663
10/1/63	73	1709J761	14663
10/1/63	74	1709J761	14663
10/1/63	75	1709J761	14663
10/1/63	76	1709J761	14663
10/1/63	77	1709J761	14663
10/1/63	78	1709J761	14663
10/1/63	79	1709J761	14663
10/1/63	80	1709J761	14663
10/1/63	81	1709J761	14663
10/1/63	82	1709J761	14663
10/1/63	83	1709J761	14663
10/1/63	84	1709J761	14663
10/1/63	85	1709J761	14663
10/1/63	86	1709J761	14663
10/1/63	87	1709J761	14663
10/1/63	88	1709J761	14663
10/1/63	89	1709J761	14663
10/1/63	90	1709J761	14663
10/1/63	91	1709J761	14663
10/1/63	92	1709J761	14663
10/1/63	93	1709J761	14663
10/1/63	94	1709J761	14663
10/1/63	95	1709J761	14663
10/1/63	96	1709J761	14663
10/1/63	97	1709J761	14663
10/1/63	98	1709J761	14663
10/1/63	99	1709J761	14663
10/1/63	100	1709J761	14663

<u>W</u> QUALITY ENGINEERING PROCEDURE WESTINGHOUSE ASTRONUCLEAR LABORATORY Westinghouse Electric Corporation P.O.Box 10864, Pittsburgh 36, Pennsylvania	QEP No. <u>8 - 3</u> Effective Date <u>4/20/63</u> Supersedes No. _____ Date _____	
SUBJECT: <div style="text-align: center;">NON-CONFORMING MATERIAL DISPOSITION REQUEST - ELEMENTS</div>		
<div style="margin-bottom: 10px;"> 1.0 <u>PURPOSE</u> This procedure details the function, preparation and distribution of the WANL Non-Conforming Material Disposition Request - Elements (WANL Form No. 1168). </div> <div style="margin-bottom: 10px;"> 2.0 <u>REFERENCE</u> NASA Quality Publication NPC 200-2 WANL Reliability Methods and Procedures (RMP) No. 5-1 </div> <div style="margin-bottom: 10px;"> 3.0 <u>GENERAL</u> <div style="margin-left: 20px;"> 3.1 <u>Policy</u> It is the responsibility of the Quality Control Department to provide for the review, control and disposition of materials that do not conform to drawings, specifications or procurement documents. The Non-Conforming Material Disposition Request - Elements (hereafter referred to as NMDR-E) will be initiated and processed by WANL Quality Control whenever inspections of elements reveal departure from specified requirements. No element for which this form has been issued will be released for further processing prior to evaluation and disposition by the WANL Engineering Review Board (ERB). </div> <div style="margin-left: 20px;"> 3.2 <u>Scope</u> The provisions of this procedure shall be applicable at WANL receiving, in-process, assembly and final inspections of fueled and unfueled elements which are classified as Specification Grade Hardware (Ref. RMP 5-1) or for which specific inspection requirements have been established. </div> </div> <div style="margin-bottom: 10px;"> 4.0 <u>PROCEDURE</u> <div style="margin-left: 20px;"> 4.1 <u>Initiation</u> The NMDR-E will be initiated, immediately upon the disclosure of a defect, by the Quality Control technician who performed the inspection. </div> <div style="margin-left: 20px;"> 4.2 <u>Instructions for Completion</u> Completion of the form shall be as detailed below (refer to Attachment A). </div> </div>		
APPROVALS		
Quality Control Manager	Program Manager	Project Manager

QUALITY ENGINEERING PROCEDURE**WESTINGHOUSE ASTRONUCLEAR LABORATORY**
Westinghouse Electric Corporation**QEP No.** 8 - 3**Effective Date** 4/20/63

No space shall be left blank. Should a space not be applicable, insert "none". The initiator, the Inspection Supervisor and each member of the Engineering Review Board are encouraged to use the "Comments" block when additional space is required. The numbers placed in the spaces of Attachment A refer to those that follow:

- (1) Number - Preserialized reference number.
- (2) Serial Number - Complete serial number; obtain from the serialized face of the element.
- (3) Part Number - Complete part number and applicable revision; obtain from Work Order or Purchase Order. Include all dash numbers and letters if applicable. If no revision, insert "0".
- (4) Supplier - Complete name if obtainable from associated documents at time of inspection. Insert "unknown" if applicable.
- (5) Date - Month, day, year inspection completed.
- (6) Fueled/Unfueled - Check one block as applicable.
- (7) Reactor Analysis Document - Obtain from W.O., P.O., drawing or Reactor Assembly Process Outline whenever a Reactor Analysis directive or drawing is applicable at the time and place of inspection (i.e. RA Orifing Document, etc.). Insert the complete document number and revision.
- (8) Purchase Order/Work Order - Insert complete number and those of all applicable amendments.
- (9) Time - Hour and minute of completion of NMDR-E initiation by the inspector. Use military time designation.
- (10) Assembly Operation Number - Obtain from Reactor Assembly Process Outline, Assembly Route Card or QC Operating Instruction.
- (11) Reactor Assembly Process Outline - Insert complete number and revision.

QUALITY ENGINEERING PROCEDURE**WESTINGHOUSE ASTRONUCLEAR LABORATORY**
Westinghouse Electric Corporation**QEP No.** 8 - 3**Effective Date** 4/20/63

- (12) Engineering Review Board Design Responsibility - Check as applicable if nonconforming characteristic is designated by Reactor Mechanical Design (length, channel pattern, finish, etc.) or Reactor Analysis (effective channel diameter, orifice leakage, etc.).
- (13) Location - Location of defective element. May be bond or hold area, assembly area or in-process station designation.
- (14) Previous History - Insert, if applicable, from tags and associated records all previous actions due to nonconformity.
- (15) Inspection Tool/Gage - Equipment used which revealed non-conformity.
- (16) Description of Nonconformity - Complete description of each cause for initiation. Each statement must include a full description of the required characteristic, including tolerances, and the existent condition which necessitates the issuance of the NMDR-E. The location of the characteristic (drawing zone, note, paragraph, etc.) should be included when possible.
- (17) Inspector - Name of person who performed the inspection.
- (18) Inspection Stamp - QC Inspectors will apply "D" (defective) stamp.
- (19) Inspection Supervisor - Name of authorized supervisor approving the form as initiated.
- (20) Engineering Review Board Disposition - Coordinated decision of the Engineering Review Board (ERB). "X" will be placed in the applicable block. Refer to paragraph 4.4 of this procedure.
- (21) Engineering Review Board Members - Signatures of all members of the ERB. Representatives of other WANL activities which have been consulted should also sign.
- (22) Comments - To be used as necessary to provide additional information concerning the discrepancy, setup, test, disposition direction, etc.

QUALITY ENGINEERING PROCEDURE

WESTINGHOUSE ASTRONUCLEAR LABORATORY
Westinghouse Electric Corporation

QEP No. 8 - 3

Effective Date 4/20/63

- (23) Corrective Action - To be completed by the Quality Control member of the ERB at the conclusion of the dispositioning process.

4.3 Engineering Review Board Processing

The concurrence of authorized representatives from Quality Control, Reliability and Design will be required to complete the processing of any NMDR-E. The Board will meet, as a group, a maximum of one hour after the time shown in the "Time" block of the form. Competent, knowledgeable personnel assigned to other WANL activities may be consulted whenever necessary to assure proper dispositioning.

4.3.1 Notification

Following initiation and review, the Inspection Supervisor will immediately have five copies reproduced and hand carried to authorized ERB representatives of the Quality Control, Reactor Mechanical Design, Reactor Analysis and Reliability Departments. The fifth copy will be delivered, for information only, to Program Control. A decision by the responsible design activity, either Reactor Mechanical Design or Reactor Analysis, as designated by block (12) of the form, will be mandatory. Whenever the alternate design function does not wish to participate in the ERB action, the Quality Control member of the Board should be notified immediately.

4.3.2 Quality Control ERB Engineer

It shall be the responsibility of the Quality Control member of the Engineering Review Board to direct the efficient and expeditious processing of each NMDR-E. Upon receipt of the advance copy, he shall review the form completeness. It shall be his duty to contact any member of the board who fails to appear for dispositioning at least one hour after initiation. Following ERB action he shall determine that the Corrective Action proposed will preclude repetition of all nonconformities listed. The Corrective Action Statement should be clear, concise and of a positive nature.

4.4 Dispositions

The ERB must enter an "X" in the appropriate block of the NMDR-E to designate one of the following.

4.4.1 Accept As Is

Where the defect is a variation of limitations established by Design Specifications, but remains within the requirements of

QUALITY ENGINEERING PROCEDURE

WESTINGHOUSE ASTRONUCLEAR LABORATORY
Westinghouse Electric Corporation

QEP No. 8 - 3

Effective Date 4/20/63

WANL's customer, and does not adversely effect safety, interchangeability, service life, reliability or performance, the element shall be sent to the next operation.

4.4.2 Replace/Return to Stores

Where the deviation from requirements will not permit the use of an element for its predesignated assembly application, but will not prevent its use in another application, either as Specification Grade or development Hardware, such elements shall be held by the Inspection Supervisor until proper routing is obtained.

4.4.3 Return to Supplier

Where elements must be replaced by the WANL supplier they will be held in the Inspection bond area pending issuance of a WANL "L" Order and will then be released to Accountability or the Shipping Department, as applicable, for return.

4.4.4 Scrap

To be designated when the condition of an element is such as to preclude all possibility of use. Following the issuance of a Scrap Report, the element will be placed in a bonded scrap container in the Accountability Vault or Inspection area, as applicable, for disposal.

4.5 Distribution

Upon completion of dispositioning, all copies will be returned to the Inspection Supervisor's office for distribution as shown:

Original	Inspection Supervisor's file
Orange	Reliability and Quality Data Systems
Green	Reactor Assembly
White	Reactor Analysis
Goldenrod	Program Control
Pink	Quality Engineering
Blue	Reactor Mechanical Design
Yellow	Supplier Surveillance
Hardback	Attach to Element

NON-CONFORMING MATERIAL DISPOSITION REQUEST - ELEMENTS

Serial No. (2)	Part No. (3)	Rev.	Supplier (4)	Date: (5)
Unfueled ☐ Fueled ☐ (6)	Reactor Analysis Doc. No. (7)	Rev.	P. O. / W. O. (8)	Amend. (9)
Assy. Oper. No. (10)	RAPO No. (11)	Rev.	ERB Design ☐ Resp. (12) ☐	Reactor Mech. Design Reactor Analysis Location: (13)
Previous History: VR No.		NMDR No. (14)	Rec. Insp. Report	Other:
Inspection Tool/Gage: (15)				

Description of Nonconformance:

(16)

Inspector (17) Inspection Stamp (18) Inspection Supervisor (19)

ENGINEERING REVIEW BOARD DISPOSITION

☐ Accept As Is ☐ Replace/Return to Stores (20) ☐ Return to Supplier ☐ Scrap

Engineering Review Board Members (21)

Design Reliability Quality Control Other

COMMENTS:

(22)

CORRECTIVE ACTION

(23)