LEGAL NOTICE

This report was prepared as an account of Government sponsored work. Neither the United States, nor the Commission, nor any person acting on behalf of the Commission:

A. Makes any warranty or representation, express or implied, with respect to the accuracy, completeness, or usefulness of the information contained in this report, or that the use of any information, apparatus, method, or process disclosed in this report may not infringe privately owned rights; or

B. Assumes any liabilities with respect to the use of, or for damages resulting from the use of any information, apparatus, method, or process disclosed in this report.

As used in the above, "person acting on behalf of the Commission" includes any employee or contractor of the Commission to the extent that such employee or contractor prepares, handles or distributes, or provides access to, any information pursuant to his employment or contract with the Commission.

Photostat Price \$ 3.30

Microfilm Price \$ 2.40

Available from the
Office of Technical Services
Department of Commerce
Washington 25, D. C.

AECU-3206

188-55-16

PRACTICAL METHODS FOR THE REDUCTION OF STRAIN GAGE DATA

Richard C. Dove

ABSTRACT

The error that results when it is attempted to evaluate stress from a reading taken on a single element SR-4 strain gage in a biaxial stress field is discussed. A method is presented for relating SR-4 rosette strain gage readings directly to the biaxial stress state without the necessity of first converting strain gage readings to true strains. Correction formulas are presented for use when single element SR-4 gages are used as rosette elements or as stress gages.

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency Thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

DISCLAIMER

Portions of this document may be illegible in electronic image products. Images are produced from the best available original document.

DISTRIBUTION:

R. A. Bice, 5200
A. P. Gruer, 5210
T. B. Morse, 1610
H. E. Lenander, 5220
W. T. Moffat, 5240
W. C. Scrivner, 5250
D. B. Shuster, 5260
J. P. Wamsler, 1282
C. D. Maytum, 1282-1
R. L. Wagar, 1611
P. H. Adams, 1612 (10)
J. J. Miller, 5211
A. E. Bentz, 5213
R. H. Gablehouse, 5223
W. V. Hereford, 5251
G. P. Stobie, 5252
A. J. Max, 5261
D. A. Skinrood, 5261
R. D. Statler, 5262
H. J. Burns, 5262
D. Williams, Jr., 1611-4
M. McWhirter, 1612-1 (10)
E. White, 1612-2 (10)
R. L. Culley, 5213-1
K. V. Nison, 5213-3
L. L. Lathrop, 5213-3
R. W. Jack, 5213-3
R. K. Smeltzer, 1922-2
M. K. Linn, 1923 (6)

DO NOT
PHOTOSTAT

INTRODUCTION

Since most design criteria are based on stress values rather than strain values, readings obtained from electrical strain gages are commonly reduced to stress magnitudes. In a general biaxial stress field the strain gage readings are not identical with the strains along the gage axis, and further the stress along any axis is not related to the strain along the same axis by the simple expression $S = eE$. For these reasons an attempt to evaluate strain and stress in a biaxial stress field using a single element gage reading may result in an appreciable error. These errors are discussed in Part I of this paper.

In the general biaxial stress field (directions of the principal stresses unknown) three element rosette gages are required. In the past it has been customary to convert the individual rosette element readings to true strains as a first step, and then to convert strains to stresses as a second step. Part II of this paper gives a method for evaluating principal stresses directly from the strain gage readings.

It is often desirable to use standard single element electric strain gages to make two or three element rosette gages. When single element gages are used in this manner their sensitivity is affected. The correction which must be made to compensate for this sensitivity change is also discussed in Part II of this paper.

For those cases in which the direction of the maximum principal stress is known and it is desired only to evaluate the magnitude of that stress, a stress gage is used. Properly oriented single element strain gages may be used as stress gages. Part III of this paper deals with the relationship between the output of a single element strain gage used as a stress gage and the magnitude of stress.

PART I

Single element SR-4 strain gages are calibrated by the manufacturer in a uniaxial stress field (axis of applied stress parallel to the gage axis) on a material having a Poisson's ratio (μ) of 0.285. Both Brush* and Baumberger and Hines** point out that when a single element gage is used in a biaxial field the error that results in taking the gage reading as the true strain can be expressed as follows:

$$\text{Error in } e_1 = \frac{R_1 - e_1}{e_1}$$

in which,

* Brush Development Company, Universal Analyzer Operating Instructions, Brush Development Company, Cleveland, Ohio, 1950.

** Baumberger, R. and Hines F., Practical Reduction Formulas for Use on Bonded Wire Strain Gages in Two-Dimensional Stress Fields, S.E.S.A., Vol. 2, No. 1, Society for Experimental Stress Analysis, Cambridge, Mass., 1944, p. 114-115.

R_1 is the reading obtained from a gage with axis in the 1 direction, and using the gage factor given by the manufacturer.

e_1 is the true strain in the 1 direction.

The gage reading is a function not only of the gage factor and the strain parallel to the axis of the gage but, in addition, the reading is a function of the gage cross sensitivity and the strain perpendicular to the axis of the gage, hence, the error expression given above becomes:

$$\text{Error in } e_1 = \frac{K}{1 - \mu K} \left(\mu + \frac{e_3}{e_1} \right),$$

in which

K is the cross sensitivity of the gage. This value is a characteristic of a given gage type. It is available for all commercial gages*.

μ is Poisson's ratio.

e_3 is strain along the 3 axis, which is taken as perpendicular to the 1 axis.

Since in a biaxial stress field the maximum (u) and minimum (v) strain axes are perpendicular to each other, it is apparent that for a given value of K the maximum error will result when the gage is placed parallel to the axis of minimum strain (i.e., $e_1 = e_v$, $e_3 = e_u$). Values of K range between ± 0.03 for standard gage types, which indicates that considerable error may result from random placement of a single element gage in a biaxial stress field.

Even when a surface has been Stresscoated and tested to determine the direction of the maximum principal stress, there is error involved in the use of a single element strain gage. Consider the case in which Stresscoat cracks indicate the direction of the maximum tensile strain (perpendicular to the Stresscoat cracks). If a strain gage is mounted so that the gage axis is parallel to the axis of maximum tensile strain the error in taking the strain gage reading as the maximum tensile strain may still have any value between $K(\mu + 1)/1 - \mu K$ and approximately 180%. This follows from the fact that since Stresscoat cracks under the influence of the largest tensile strain the ratio of e_3/e_1 may have any value from unity to 0.0240/0.0004. The maximum value of the ratio e_3/e_1 is fixed as the ratio of the maximum flaking sensitivity divided by the minimum threshold sensitivity. Unfortunately, the magnitude of this error is unknown since e_3 remains unknown, and hence, no correction is possible.

Application of the theory of elasticity to a biaxial stress field gives the following relationships between mutually perpendicular stresses and strains**.

* Baumberger, R. and Hines, F., op. cit. p. 116.

** Murphy, Glenn, Advanced Mechanics of Materials, McGraw Hill, N.Y., 1946, p. 63.

$$S_1 = \frac{E}{1 - \mu^2} (e_1 + \mu e_3)$$

and

(1)

$$S_3 = \frac{E}{1 - \mu^2} (e_3 + \mu e_1)$$

in which E is the modulus of elasticity of the material. If a single element strain gage reading is used in an attempt to evaluate the normal stress along the gage axis using the uni-axial expression:

$$S_1 = e_1 E$$

the resulting error can be expressed as follows:

$$\text{Error in } S_1 = \frac{e_1 E - S_1}{S_1}$$

The true stress in the 1 direction (S_1) may be expressed in terms of the strains in the 1 and 3 directions using Eq. 1. Since SR-4 gages have a certain cross sensitivity (K), the strain along any axis in a biaxial stress field must be expressed in terms of strain gage readings taken in two mutually perpendicular directions. Using two single element gages with the gage factor supplied by the manufacturer, and mounted perpendicular to each other

$$\begin{aligned} e_1 &= (R_1 - KR_3) \frac{1 - \mu K}{1 - K^2} \\ e_3 &= (R_3 - KR_1) \frac{1 - \mu K}{1 - K^2} \end{aligned} \quad (2)$$

Substituting from Eq. 1 the expression for the error in S_1 becomes

$$\text{Error in } S_1 = \frac{e_1 E - \frac{E}{1 - \mu^2} (e_1 + \mu e_3)}{\frac{E}{1 - \mu^2} (e_1 + \mu e_3)}$$

Table 1 is included to indicate the magnitude of the errors made in evaluating strains and stresses when single element gage readings are used as a basis for calculations in biaxial stress fields.

PART II

Application of the theory of elasticity at a free surface (biaxial stress state) gives the following important stress-strain relationships*:

* Murphy, Glenn, op. cit., p. 41-42.

$$e_t = e_x \cos^2 \theta + e_y \sin^2 \theta - \frac{e_{xy}}{2} \sin 2\theta \quad (3)$$

$$e_u = \frac{e_x + e_y}{2} + 1/2 \sqrt{(e_x - e_y)^2 + e_{xy}^2} \quad (4)$$

$$e_v = \frac{e_x + e_y}{2} - 1/2 \sqrt{(e_x - e_y)^2 + e_{xy}^2}$$

$$\tan 2\alpha = \frac{-e_{xy}}{e_x - e_y} \quad (5)$$

$$S_u = \frac{E}{1 - \mu^2} (e_u + \mu e_v) \quad (6)$$

$$S_v = \frac{E}{1 - \mu^2} (e_v + \mu e_u)$$

in which

e - strain in inches/inch. Single subscripts denote normal strains; the direction of the normal strain corresponds to the direction of the subscript axis in Figure 1a. Double subscripts denote shearing strains.

S - stress in lb/in². Subscripts as for strains.

θ - the angle between the x and the t directions.

e_u, S_u - the subscript u is reserved to denote the direction of the maximum normal strain or stress.

e_v, S_v - the subscript v is reserved to denote the direction of the minimum normal strain or stress. The v direction is always at 90° to the u direction.

α - the angle that the principal stresses (or strains) makes with the x axis.

1a

1b

Figure 1

With these four equations, the principal (i.e. maximum and minimum) stresses at a point can be evaluated from three normal strains at that same point. Assume that the strains in the 1, 2, and 3 directions (Figure 1b) are known (a rectangular rosette). Application of Eq. 3 to the 2 direction yields:

2975

$$e_2 = e_1 \cos^2 45^\circ + e_3 \sin^2 45^\circ - \frac{e_{xy}}{2} \sin (2 \times 45^\circ)$$

$$e_{xy} = e_1 + e_3 - 2e_2 \quad (3')$$

Substitution of this result in Eq. 4 gives

$$e_{u,v} = \frac{e_1 + e_3}{2} \pm 1/2 \sqrt{(e_1 - e_3)^2 + (e_1 + e_3 - 2e_2)^2},$$

which may be rewritten as

$$e_{u,v} = \frac{e_1 + e_3}{2} \pm \frac{1}{\sqrt{2}} \sqrt{(e_1 - e_2)^2 + (e_2 - e_3)^2}$$

or

$$e_{u,v} = \frac{\Sigma 13}{2} \pm \frac{1}{\sqrt{2}} \sqrt{\Delta 12^2 + \Delta 23^2} \quad (4')$$

in which

$$\Sigma 13 = e_1 + e_3$$

$$\Delta 12 = e_1 - e_2$$

$$\Delta 23 = e_2 - e_3$$

Substitution of this result into Eq. 6 gives

$$S_u = \frac{E}{1 - \mu^2} \left[\frac{\Sigma 13}{2} + \frac{\sqrt{\Delta 12^2 + \Delta 23^2}}{\sqrt{2}} + \mu \frac{\Sigma 13}{2} - \mu \frac{\sqrt{\Delta 12^2 + \Delta 23^2}}{\sqrt{2}} \right],$$

which may be rewritten as

$$S_u = \frac{E}{2(1-\mu)} \Sigma 13 + \frac{E}{\sqrt{2}(1+\mu)} \sqrt{\Delta 12^2 + \Delta 23^2} \quad (6')$$

Likewise

$$S_v = \frac{E}{2(1-\mu)} \Sigma 13 - \frac{E}{\sqrt{2}(1+\mu)} \sqrt{\Delta 12^2 + \Delta 23^2} \quad (6')$$

Since in the practical case the strains in the 1, 2, and 3 directions will be known only through the use of strain gages we must consider how these strains are related to strain gage readings in the 1, 2, and 3 directions. For the commercially available three element rosette gages the manufacturer gives the following relationships between true strains (e_1, e_2, e_3) and the readings obtained from the individual gage elements (R_1, R_2, R_3).

$$e_1 = R_1 - KR_3$$

$$e_2 = (1 + K)R_2 - K(R_1 + R_3) \quad (7)$$

$$e_3 = R_3 - KR_1$$

in which the readings are obtained using the gage factor given by the manufacturer and K is the cross sensitivity given by the manufacturer in terms of an auxiliary gage factor (b).

$$K = \frac{1}{b}$$

When Eq. 7 is substituted into Eq. 6' the principal stresses appear as functions of the three strain gage readings.

$$S_{u,v} = \frac{E(1-K)}{2(1-\mu)} \Sigma'13' \pm \frac{E(1+K)}{\sqrt{2}(1+\mu)} \sqrt{\Delta'12^2 + \Delta'23^2} \quad (6'')$$

or

$$S_{u,v} = A \Sigma'13' \pm B \sqrt{\Delta'12^2 + \Delta'23^2}$$

in which

$$\Sigma'13' = R_1 + R_3$$

$$\Delta'12 = R_1 - R_2$$

$$\Delta'23 = R_2 - R_3$$

$$A = \frac{E(1-K)}{2(1-\mu)}$$

$$B = \frac{E(1+K)}{\sqrt{2}(1+\mu)}$$

Although this result could have been written in numerous other forms this particular form was chosen because it lends itself well to solution by nomography. Several nomographs for the solution of this equation are available. Each nomograph is constructed for the particular values of E and μ associated with a particular material and for a particular value of K associated with a given gage type.

The directions of the principal stresses may be evaluated with the aid of Eq. 5. Again, for a rectangular rosette: substitution of Eq. 3' into Eq. 5 gives

$$\tan 2\alpha = - \frac{(e_1 + e_3) + 2e_2}{e_1 - e_3},$$

which may be rewritten as

$$\tan 2\alpha = - \frac{(e_1 - e_2) + (e_2 - e_3)}{(e_1 - e_2) + (e_2 - e_3)}$$

or

$$\tan 2\alpha = \frac{\Delta 23 - \Delta 12}{\Delta 23 + \Delta 12}$$

This is the same as

$$\tan 2\alpha = \frac{\Delta'_{23} - \Delta'_{12}}{\Delta'_{23} + \Delta'_{12}} \quad (8)$$

This expression for the angle between the principal stress axis and the number 1 axis in a rectangular rosette has been arranged to involve the same terms (Δ'_{12} , Δ'_{23}) as were used in the expression for the magnitudes of the principal stresses. Charts are available for the evaluation of α from values of Δ'_{12} and Δ'_{23} .

In the case where the directions of the principal stresses are known, as when the strain gage test is preceded by a Stresscoat test, a biaxial strain gage can be used. In this case the 1 and 3 elements are oriented in the u and v directions. Substitution of Eq. 7 into Eq. 6 gives

$$S_u = \frac{E}{1 - \mu^2} (R_1 - KR_3 + \mu R_3 - \mu KR_1)$$

or

$$S_u = CR_1 + DR_3 \quad (6''')$$

in which

$$C = \frac{E(1-K\mu)}{1 - \mu^2}$$

and

$$D = \frac{E(\mu-K)}{1 - \mu^2}$$

Likewise

$$S_v = CR_3 + DR_1 \quad (6''')$$

The four terms (CR_1 , DR_3 , CR_3 , DR_1) can easily be obtained directly by proper adjustment of the output gain in the gage circuits, hence, solution for S_u and S_v requires only addition of measured quantities.

Two or three element rosettes may be constructed using 2 or 3 single element strain gages oriented along the rosette axes. The manufacturer calibrates all single element gages in a uniaxial stress field and, hence, the effect on gage output of transverse strain due to the Poisson effect has been eliminated in the calibration. This is not desired when a single element gage is to be used as an element in a rosette. Hence, the gage factor for the single element gage given by the manufacturer must be corrected. Baumberger and Hines* have developed the expression for the necessary correction. An example of how the correction is applied is in order. Consider a single element SR-4 type A-5 gage. The gage factor given by the manufacturer (F uniaxial) for

* Baumberger, R. and Hines, F., op. cit., p. 115.

this gage has been obtained by calibration in a uniaxial stress field on a material having a value of $\mu = 0.285$. The gage factor that should be used if this gage is to be used as an element in a rosette gage and give readings R_1 , R_2 , and R_3 previously referred to is

$$F_{\text{rosette}} = \frac{(1-K^2)}{(1-\mu K)} F_{\text{uniaxial}}$$

Unfortunately the value for K is not given by the manufacturer on the single element gage package. However, as noted in Part I, it is available in the literature. For the type A-5, $K = +0.035$ and we compute

$$F_{\text{rosette}} = 1.01 F_{\text{uniaxial}}$$

PART III

Under certain conditions the direction of the maximum principal stress is known. In this case, it is possible to evaluate the magnitude of the maximum principal stress using only one single element strain gage.

If the X and Y directions (Figure 1a) are replaced by u and v directions, Eq. 3 becomes

$$e_t = e_u \cos^2 \theta + e_v \sin^2 \theta \quad (9)$$

since the shearing strain on the principal planes (e_{uv}) is known to be equal to zero.

We proceed as follows to determine at what angle (θ) a single element gage should be placed so that the gage reading (R_t) will be zero for any stress applied in the v direction.

For a given S_v , $e_v = e_v$ and $e_u = -\mu e_v$, and as before

$$e_t = R_t - KR_n$$

$$e_n = R_n - KR_t$$

If these values are substituted into Eq. 9 and R_t is set equal to zero, the result is

$$\frac{\sin^2 \theta}{\cos^2 \theta} = \frac{\mu - K}{1 - K\mu}$$

or

$$\tan^2 \theta = \frac{\mu - K}{1 - K\mu}$$

That is, if a single element strain gage is oriented at an angle $\theta = \tan^{-1} \sqrt{\frac{\mu - K}{1 - K\mu}}$ with respect to the u axis it is completely insensitive to stress in the v direction. With the gage oriented at this angle θ the gage reading can be related to a stress in the u direction as follows:

Writing

$$e_t = e_u \cos^2 \theta + e_v \sin^2 \theta$$

and

$$e_n = e_u \sin^2 \theta + e_v \cos^2 \theta$$

and substituting

$$\begin{aligned} \tan^2 \theta &= \frac{(\mu-K)}{(1-K\mu)} \\ e_u &= R_u - KR_v \\ e_v &= R_v - KR_u \\ e_t &= R_t - KR_n \\ e_n &= R_n - KR_t \end{aligned}$$

we obtain

$$R_t = \frac{(1-\mu K)}{(1+\mu)(1-K)} \left[R_u + R_v \frac{(\mu-K)}{(1-\mu K)} \right] \quad (10)$$

Writing

$$S_u = \frac{E}{1-\mu^2} (e_u + \mu e_v)$$

and substituting

$$\begin{aligned} e_u &= R_u - KR_v \\ e_v &= R_v - KR_u \end{aligned}$$

gives

$$S_u = \frac{E}{1-\mu^2} \left[R_u (1-\mu K) + R_v (\mu-K) \right]$$

which may be rewritten as

$$S_u = \frac{E(1-\mu K)}{1-\mu^2} \left[R_u + \frac{R_v (\mu-K)}{(1-\mu K)} \right] \quad (11)$$

Substitution for the bracketed term in Eq. 11 in terms of Eq. 10 gives

$$S_u = \frac{E(1-K)}{(1-\mu)} R_t \quad (12)$$

In using this expression the following fact must be remembered. Since the manufacturer's relationship between true strain and gage readings ($e_t = R_t - KR_n$) was applied, Eq. 12 is strictly valid only when the gage output is read using a gage factor of F rosette. As previously explained, the appropriate gage factor F rosette can be evaluated as

$$F \text{ rosette} = \frac{(1-K^2)}{(1-\mu K)} F \text{ uniaxial}$$

If it is desirable to read the output of the single gage using the gage factor given by the manufacturer (F_{uniaxial}) then Eq. 12 must be modified as follows:

$$\begin{aligned} \frac{R_{t \text{ Rosette}}}{\text{Gage Factor}} &= \frac{R_{t \text{ Uniaxial}}}{\text{Gage Factor}} \times \frac{F_{\text{uniaxial}}}{F_{\text{rosette}}} \\ S_u &= \frac{E}{1-\mu} \frac{(1-K\mu) R_t}{(1+K)} \end{aligned} \quad (12)$$

This use of a single element strain gage to determine the magnitude of the maximum stress was originally proposed by C. C. Perry*. However, in his treatment of the subject Perry neglected the cross sensitivity of the gage (K taken as equal to zero). With $K = 0$, Perry finds

$$\theta = \tan^{-1} \sqrt{\mu}$$

and

$$S_u = \frac{E}{1-\mu} R_t$$

Since the standard single element SR-4 gages have values of K ranging between ± 0.03 , the error introduced by this omission is approximately $\pm 3\%$.

SUMMARY

When working in a general biaxial stress field (i.e., direction of principal stresses unknown) a three element strain rosette must be used. If a rectangular rosette (Figure 1b) is used the maximum and minimum principal stresses are evaluated as

$$S_{u,v} = \frac{E(1-K)}{2(1-\mu)} (R_1 + R_3) \pm \frac{E(1+K)}{\sqrt{2}(1+\mu)} \sqrt{(R_1 - R_2)^2 + (R_2 - R_3)^2}$$

The angle (α) that principal stress makes with the number 1 gage axis can be evaluated as

$$\tan 2\alpha = \frac{2R_2 - R_1 - R_3}{R_1 - R_3} = \frac{(R_2 - R_3) - (R_1 + R_2)}{(R_2 - R_3) + (R_1 - R_2)}$$

When working in a biaxial stress field in which the directions of the principal stresses are known a two-element rosette gage should be used. The principal stresses are evaluated as

$$\begin{aligned} S_u &= \frac{E}{1-\mu^2} [R_u (1-K\mu) + R_v (\mu-K)] \\ S_v &= \frac{E}{1-\mu^2} [R_v (1-K\mu) + R_u (\mu-K)] \end{aligned}$$

* Perry, C. C., Testing Topics, Vol. 8, No. 4, Baldwin-Lima-Hamilton Corp., Philadelphia, Pa., December 1953.

If two or three element rosette gages are constructed using single element SR-4 gages the gage factor to be used with the rosette is

$$F_{\text{rosette}} = \frac{(1-K^2)}{(1-\mu K)} F_{\text{Single Gage}}$$

When working in a biaxial stress field in which the directions of the principal stresses are known, either of the two (but not both) principal stresses may be evaluated from a single gage reading. The gage element should be placed at an angle θ from the axis of the desired principal strain. Where

$$\theta = \tan^{-1} \sqrt{\frac{(1-K)}{(1-K\mu)}}$$

The desired principal stress (say S_u) is then evaluated as

$$S_u = \frac{E}{1-\mu} \frac{(1-K\mu)}{(1+K)} R_{\text{gage}}$$

where the gage is read (R_{gage}) using the manufacturer's gage factor.

RICHARD C. DOVE - 1612-2

Case No. 693.00
September 7, 1955

297 12

TABLE I

ERROR IN STRAINS AND STRESSES RESULTING FROM USE OF UNIAXIAL METHODS
IN BIAXIAL STRESS FIELDS*

True Strain In 1 Direction (e_1)	True Strain 1 to 1 Direction (e_2)	% Error in Strain When Strain Is Evaluated From A Single Uniaxial Gage Reading	% Error in Stress When Stress is Evaluated as Ee_1
e_1	$+1e_1$	+4.0	-33.3
e_1	$+\frac{1}{2}e_1$	+2.5	-23.8
e_1	0	+1.0	-11.1
e_1	$-\frac{e_1}{3}$	0	0
e_1	$-1e_1$	-2.0	+33.1
e_1	$-2e_1$	-5.1	+66.2
e_1	$-3e_1$	-8.1	∞
e_1	$-4e_1$	-11.1	-366.2
e_1	$-5e_1$	-14.1	-233.1
e_1	$-10e_1$	-29.3	-138.1

* Values given are based on the following constants:

$$K = 0.03$$

$$\mu = 1/3$$

THIS PAGE
WAS INTENTIONALLY
LEFT BLANK