MASTER

**AN INVESTIGATION OF THE MAGNETIC-
PULSE FORMING PROCESS**

F. W. Jones

RELEASED FOR ANNOUNCEMENT
IN NUCLEAR SCIENCE ABSTRACTS

**UNION CARBIDE CORPORATION
NUCLEAR DIVISION
OAK RIDGE Y-12 PLANT**

operated for the **ATOMIC ENERGY COMMISSION** *under* **U. S. GOVERNMENT** **Contract W-7405 eng 26**

**UNION
CARBIDE**

OAK RIDGE Y-12 PLANT
P. O. Box Y
OAK RIDGE, TENNESSEE 37831

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency Thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

DISCLAIMER

Portions of this document may be illegible in electronic image products. Images are produced from the best available original document.

Printed in USA. Price \$4.00. Available from the Clearinghouse for Federal
Scientific and Technical Information, National Bureau of Standards,
U.S. Department of Commerce, Springfield, Virginia

— LEGAL NOTICE —

This report was prepared as an account of Government sponsored work. Neither the United States, nor the Commission, nor any person acting on behalf of the Commission:

- A. Makes any warranty or representation, expressed or implied, with respect to the accuracy, completeness, or usefulness of the information contained in this report, or that the use of any information, apparatus, method, or process disclosed in this report may not infringe privately owned rights; or
- B. Assumes any liabilities with respect to the use of, or for damages resulting from the use of any information, apparatus, method, or process disclosed in this report.

As used in the above, "person acting on behalf of the Commission" includes any employee or contractor of the Commission, or employee of such contractor, to the extent that such employee or contractor of the Commission, or employee of such contractor prepares, disseminates, or provides access to, any information pursuant to his employment or contract with the Commission, or his employment with such contractor.

Date Issued: January 10, 1966

Report Number Y-1483

Engineering and Equipment
TID-4500 (46th Edition)

UNION CARBIDE CORPORATION
Nuclear Division

Y-12 PLANT

Contract W-7405-eng-26
With the US Atomic Energy Commission

AN INVESTIGATION OF THE MAGNETIC-
PULSE FORMING PROCESS

F. W. Jones

RELEASED FOR ANNOUNCEMENT
IN NUCLEAR SCIENCE ABSTRACTS

This report is based on a study by the author as
partial fulfillment of requirements for the degree
of Master of Science in Mechanical Engineering
from The University of Tennessee.

Oak Ridge, Tennessee
December 2, 1965

Report Number Y-1483Engineering and Equipment
TID-4500 (46th Edition)

Distribution:

Ackerson, R. D.	(AFSC)	Keller, C. A.	(AEC-ORO)(4)
Bailey, E. W.		Lewis, F. O.	(ORGDP)
Ballenger, H. F.	(2)	Little, J. C.	
Bernander, N. K.		McLendon, J. D.	
Burkhart, L. E.		Mitchel, G. W.	
Center, C. E.	(ORGDP)	Patton, F. S.	
Christman, A. M.		Perry, A. E.	
Cowen, D. D.	(ORNL)	Rader, D. H.	
Ebert, J. W.		Sommerfeld, K. W.	
Evans, G. W.		Thomas, F. W.	
Fortenbery, M. J.		Trotter, T. C.	
Gritzner, V. B.		Waters, J. L.	
Harding, J. E.		Whitson, W. K.	
Harwell, W. L.	(ORGDP)(5)	Williams, J. L.	
Homphill, L. F.		Winkel, R. A.	(Paducah)
Hensley, C. E.		Yaggi, W. J.	
Huber, A. P.	(ORGDP)	Zurcher, E.	
Jennings, D. A.		Y-12 Central Files	(5)
Jones, F. W.	(15)	Y-12 Central Files	(Y-12RC)

In addition, this report is distributed in accordance with the category Engineering and Equipment, as given in the "USAEC Standard Distribution Lists for Unclassified Scientific and Technical Reports", TID-4500 (46th Edition), October 1, 1965.

ABSTRACT

This thesis presents an investigation of the magnetic-pulse forming process which is one of the newest methods of forming metals at high strain rates.

A simple method is presented for measuring strain rates of tubular-shaped parts. The strain rate of the magnetic-pulse forming process has been determined and compared with other high-strain-rate processes such as explosive forming.

Tubing has been bulged with the magnetic-pulse forming process from which calculations were made to determine the efficiency of the process. This efficiency has been compared with other high-strain-rate forming processes.

The equations necessary for predicting the performance of this new forming process are summarized. Graphs of forming pressure versus stored energy are also presented.

The problem of design and manufacture of forming coils is discussed in detail along with examples of coils that have been constructed and the experimental results of these coils.

The limitations of this new forming process are presented along with examples of parts that are ideally suited for this manufacture process.

In general, this thesis has been written in such a manner as to be utilized by the manufacturing engineer to realize the full advantages as well as the definite limitations of this new forming process.

ACKNOWLEDGEMENTS

Appreciation is expressed for the guidance received from Professors R. L. Maxwell and W. K. Stair of The University of Tennessee, and for the interest and opportunity extended by the Union Carbide Corporation, Y-12 Plant. The writer also wishes to thank Messrs. E. Zurcher, E. W. Bailey, and G. B. Lockhart of Union Carbide Corporation for their help during the course of this investigation.

SUMMARY

The magnetic-pulse forming process was investigated to determine some of the advantages and limitations that this new metal-forming process has to offer for forming metals at high strain rates. A capacitor bank was modified to furnish 13,000 joules of electrical energy. The electrical energy stored in the capacitor bank was discharged by means of a ball-gap firing switch.

The equations for predicting the performance of this forming process are summarized. For example, equations for predicting the forming pressure, velocity of metal movement, and current-penetration depth in the part to be formed are presented. Also, reference charts are included that plot the annular volume between the magnetic-pulse forming coils and the part to be formed as a function of the forming pressure available at energies from 1000 to 45,000 joules. A chart is included that plots the current-penetration depth as a function of the RLC circuit-ringing frequency.

The efficiency of the magnetic-pulse forming process was determined and compared with the explosion and electrohydraulic forming process.

The efficiency of the magnetic-pulse forming process was between 20 and 34.3 per cent which compares to 16 per cent for the explosive forming process and 19 per cent for the electrohydraulic process.

The velocity obtained by pulsing tubes at various energy levels was determined. For example, a 0.060-inch-thick, 2-inch-outside diameter aluminum

tube was found to move at a velocity of $0.06 \text{ mm}/\mu\text{sec.}$ when pulsed at an energy level of 3600 joules. A copper tube of the same diameter but with a wall thickness of 0.025 inch obtained a velocity of $0.20 \text{ mm}/\mu\text{sec.}$ when pulsed at an energy level of 10,000 joules. These velocities are considerably lower than the $2 \text{ mm}/\mu\text{sec.}$ of the explosive forming process. However, by increasing the capacity of the energy storage, it may be possible to produce strain rates comparable to the explosive forming process.

Different types of forming coils are discussed. The problems of designing and building magnetic-pulse forming coils are presented along with a solution for fabricating cylindrical, reinforced forming coils that can withstand repeated energy pulses of 20,000 joules.

Part types most readily formed with the magnetic-pulse forming process are discussed.

The use of field shapers in permanent-type cylindrical work coils are reviewed. Techniques for forming some of the low conductivity metals with the use of reuseable pushers and metal pushers are presented.

This study should present the designer and manufacturing engineer with the capabilities of the magnetic-pulse forming process.

TABLE OF CONTENTS

CHAPTER	PAGE
I. INTRODUCTION	1
II. RELATED EQUATIONS FOR MAGNETIC-PULSE FORMING	10
III. EFFICIENCY DETERMINATION OF THE MAGNETIC FORMING PROCESS	22
IV. DETERMINATION OF STRAIN RATES	35
V. COIL DESIGN	46
VI. PART TYPES MOST READILY FORMED WITH MAGNETIC- PULSE FORMING	63
BIBLIOGRAPHY	90
APPENDIX	92
SYMBOLS AND NOMENCLATURE	97

LIST OF TABLES

TABLE	PAGE
I. Efficiency Determination of a Three-Inch, 0.125-Inch-Thick Aluminum Tube Pulsed with 8200 Joules, Work Input to Tube of 2815 Joules	29
II. Efficiency Determination of a Three-Inch, 0.125-Inch-Thick Aluminum Tube Pulsed with 11,800 Joules, Work Input to Tube of 2345.9 Joules	30
III. Efficiency Determination of a Three-Inch, 0.065-Inch-Thick Aluminum Tube Pulsed with 4500 Joules, Work Input to Tube of 1229 Joules	31
IV. Efficiency Determination of a Three-Inch, 0.065-Inch-Thick Aluminum Tube Pulsed with 4500 Joules, Work Input to Tube of 1164 Joules	32
V. Efficiency Determination of a Three-Inch, 0.065-Inch-Thick Aluminum Tube Pulsed with 2020 Joules, Work Input to Tube of 422 Joules	33
VI. Summary of Clearances Before and After the Reducers Were Sized . . .	71
VII. Glass Roving Content and Hoop Tensile Strength	92
VIII. Properties of Various Coil Reinforcing Materials	93
IX. Properties of Thermoplastics	94

TABLE

PAGE

X. Properties of Thermoset Plastics	95
XI. Electrical Resistivity	96

LIST OF FIGURES

FIGURE		PAGE
1.	Cross Section of a Cylindrical Current-Carrying Coil Surrounding an Insulator	3
2.	Conducting Tube Inside a Current-Carrying Coil	5
3.	13,000-Joule Capacitor Bank	7
4.	Cross Section of a Magnetic-Pulse Forming Coil Showing the Region of Maximum Field Intensity	12
5.	Annular Volume Between the Magnetic-Pulse Forming Coil and the Part as a Function of the Forming Pressure Available at Various Energy Levels ($E = 5,000 - 45,000$ Joules)	14
6.	Annular Volume Between the Magnetic-Pulse Forming Coil and the Part as a Function of the Forming Pressure Available at Various Energy Levels ($E = 1,000 - 9,000$ Joules)	15
7.	Current Penetration Depth as a Function of the RLC Circuit Frequency	17
8.	Setup for Bulging Aluminum Tubing	23
9.	Definition of Symbols Used in Efficiency Determinations	24
10.	True Stress as a Function of the True Strain for Type 2024-0 Aluminum	27

FIGURE	PAGE
11. Cross Section of Three-Inch Aluminum Tubing as Bulged by the Magnetic-Forming Process	28
12. Test Arrangement for Measuring Strain Rates	36
13. Deformed Aluminum Tubes with Corresponding Oscilloscope Traces Showing Time vs Radial Distance	38
14. Calibration Curve for Tested Cylinders	39
15. Radial Velocity as a Function of the Bank Energy	40
16. Flash Radiographs of a Copper Cylinder Undergoing High-Speed Electromagnetic Deformation (50 to 300 Microseconds after Electromagnetic Pulse Initiation)	41
17. X-Ray Photograph Showing a 0.025-Inch-Thick Copper Cylinder 50 Microseconds after Electromagnetic Pulse Initiation	42
18. Circumferential Strain for Tube Expansion	44
19. Female Forming Coil with a Three-Inch Inside Diameter	48
20. Radial Pressure as a Function of the Energy for the Female Forming Coil	49
21. A Female Forming Coil after Failure	52
22. Male Forming Coil Construction (2.750-Inch Diameter)	54
23. Male Forming Coil after Failure at 13,000 Joules	55
24. Male Forming Coil (0.575-Inch Diameter)	56

FIGURE	PAGE
25. Male Forming Coil after Complete Failure	58
26. Pancake-Type Forming Coil	59
27. As-Wound Fourteen-Inch Hemispherical Forming Coil	60
28. Expendable Forming Coil	62
29. Swaging Type Work Coil Surrounding a Piece of Aluminum Tubing . .	64
30. Aluminum Tubing Swaged on an Internal Mandrel (0.062-Inch Thick)	65
31. Typical Pressure-Tight Joint Between Two Lengths of Tubing	66
32. Typical End-Plug Design	67
33. Typical Coil Setup for Sizing Stainless Steel Reducers	68
34. Stainless Steel Reducers Sized on Male Mandrels	70
35. End View of a Type 3 Container Prior to Sizing	72
36. Copper Plated on Stainless Steel Specimens	73
37. Field Shaper in a Swaging-Type Magnetic Forming Coil (Selected Area)	75
38. Field Shaper in a Swaging-Type Magnetic Forming Coil (Complete Area)	76
39. Hemispherical Forming Coil (2-Inch ID)	77
40. Copper Parts Formed with a Hemispherical Forming Coil	79
41. Half-Cylinder Forming Coil	80

FIGURE

PAGE

42.	Tubular Part to be Sized by a Half-Cylinder Forming Coil	81
43.	Cross Section of an Expansion-Type Forming Coil Inside a Stainless Steel Tubing after Pulsing	83
44.	A Stainless Steel Tubing Assembled into a Mock Bulkhead	84
45.	Arrangement for a Pancake-Type Forming Coil	85

CHAPTER I

INTRODUCTION

Electromagnetic force serves manufacturing engineers with versatility. Its range of usability extends from cranes lifting tons of scrap to solenoid-operated devices and even to storing manufacturing data in the magnetic core memories of computers. This already considerable range has been extended by recent research into yet another useful application—forming metals by a sudden and powerful surge of electromagnetic force.

As early as 1924, for example, Kapitsa was able to achieve field strengths of 500 kilogauss by the rapid discharge of batteries into a magnet coil.¹ Although his efforts were in conjunction with the study of magneto-optics, para and diamagnetism, and other effects of atomic origin, the ground work nevertheless was laid for the new method of forming by electromagnetic pulses.

In the intervening years, great strides were made in the development of magnetic coils for studies of matter in magnetic fields, but the practical advantage of manipulation of solid conductors by means of the magnetic field was not readily apparent; rather, this effect was considered the frustrating result that manifested itself in the destruction of the magnetic coil when structural or inertial strength was exceeded by magnetic pressure.

First known mention of the practical possibilities of forming by magnetic pressure was made about 1955 by Furth and Wanieks. About the same time, solid

sodium forging experiments were initiated by Colgate at the Lawrence Radiation Laboratory.²

Prior to this time, scientists and engineers were working to develop magnetic coils capable of continuous duty-type operation. Only by the mid 50's was it discovered that the intense transient magnetic fields held considerable promise as a practical means of manipulating solid conductors to one's advantage.

By 1957, the obvious benefits of this method of forming already were becoming well known in this field and since that time much progress has been made by several research laboratories over the country. In effect, the instrument first developed by the physicists now has become an extremely useful tool, and is on the verge of taking its rightful place in industry along with other high-energy-rate methods.

Thus, electrical energy in the form of a magnetic field can be converted directly to useful work in forming metal. By discharging a capacitor through an electrical coil over a period of microseconds, it is possible to create pulsed magnetic fields in the kilogauss range.

Figure 1 shows a cross section of a cylindrical current-carrying coil surrounding an insulator. To form metal in a brief period of time, considerable energy is required. This energy state is attained by "pumping" energy into a storage device and then releasing it suddenly. The storage device for magnetic-pulse and electrohydraulic forming is a capacitor bank shown schematically in Figure 1. Capacitors are fed with a charge to a suitable level and the charge is

FIGURE 1

CROSS SECTION OF A CYLINDRICAL CURRENT-CARRYING COIL SURROUNDING AN INSULATOR

then suddenly released into the work coil shown in Figure 1. The result of this sudden release of electrical energy into the work coil is an oscillatory or pulsed magnetic field. The time to reach maximum field strength is of considerable importance and is normally around 20 to 30 microseconds. This time interval or frequency determines the efficiency of the forming process. This subject will be discussed more fully in Chapter II, Page 10.

Flux lines illustrated in Figure 1 define the boundaries of areas that contain equal magnetic flux. A close spacing indicates a high magnetic field while a wider spacing represents a lower magnetic field. The presence of an insulator as shown in Figure 1 permits the flux lines to pass through the coil with no interaction. The flux lines are not affected by an insulator except at very high frequencies. The volume enclosed by the coil contains the majority of the magnetic field energy since the magnetic field energy is proportional to the square of the value of the field intensity. Upon discharge of the capacitor bank, the magnetic field passes through the insulator with no interaction.

In Figure 2, a tube made from conducting material has been substituted for the insulator.

As a result of a discharge from the capacitor bank into the work coil, eddy currents are induced in the surface of the conducting tube. This discharge of energy produces a mutual repulsive force between the work coil and the conducting cylinder. The induced eddy currents in the surface of the conducting tube confine the magnetic field to the annular space between the coil and the cylinder. A

FIGURE 2

CONDUCTING TUBE INSIDE A CURRENT-CARRYING COIL

pressure equal to the magnetic-field energy density is exerted on the conducting tube as a result of the absence of a magnetic field within the conducting tubes. As the conducting tube is compressed, the expanding magnetic field gives up its energy to perform the work of forming. The magnetic pressure can only be maintained for a short period of time since no metal is a perfect conductor at working temperatures. The value of the resistivity of the metal determines the rate at which the magnetic field leaks through the conducting tube so that eventually the external field pressure is balanced by the internal pressure and the net force on the tube is reduced to zero.

This process also involves the loss of energy due to resistive heating and dynamic movement of the work coil. To be effective, short pulses must be used so that the magnetic field penetration in the work piece is constrained to a shallow layer at the surface. This relationship will be discussed more fully in Chapter II, Page 10.

Figure 3 is a photograph of the equipment used to conduct the studies presented in this thesis. The equipment has an energy storage level of 13,000 joules. The capacitor bank is discharged with a conventional three-ball firing switch. Two balls are charged to a potential while the third ball is utilized to ionize the air gap with a high-voltage pulse.

Thus, magnetic-pulse forming offers industry a means of forming metals without physical contact with fluids or mating die surfaces. High metal velocities near 600 feet per second (fps) and faster can be obtained by this process compared

FIGURE 3

13,000-JOULE CAPACITOR BANK

to about 5 fps for conventional forming. A magnetic flux density of 300 kilogauss will produce around 55,000 pounds per square inch (psi).

Various metals respond to high strain rates in different manners. In general, metals can be placed into two groups. One group of metals when subjected to the high strain rates will show an increase in the total true strain to fracture up to a certain critical strain rate and then the true strain to fracture will decrease. The true strain to fracture of the other group will hold fairly constant up to a critical strain rate and then start to decrease. However, both groups will show an increase in the true stress with strain rate. Forming metals at high strain rates has the effect of increasing the given toughness of a metal as exhibited at slow strain rates until a critical strain is reached and then the toughness diminishes. Toughness is the area under the stress-strain diagram.

Thus, metals selected for magnetic forming should have a high toughness since toughness is a measure of the ability of a metal to plastically deform under shock loading, without fracture. The strain rate of the forming process should be selected that gives maximum toughness for the metal being formed. This is especially true of the group of materials that show an increase in the true strain with strain rate. One of the advantages of the magnetic forming process is that the strain rate can be reproduced very accurately since the amount of stored electrical energy can be measured.

Thus, magnetic forming can be a very important metal-working tool for industry.

This thesis is intended to outline the necessary considerations and equations that will enable the manufacturing engineer to judge when to use the magnetic-pulse forming process and how to use it. Therefore, types of forming operations possible with the process will be discussed. The efficiency of the magnetic-forming process will be compared with other types of high-energy rate-forming processes. Coil design and manufacture will be discussed. The strain rate of the magnetic-forming process will be determined and compared with other high-energy rate processes. A simple technique for measuring high strain rate will be presented.

With the data presented in this thesis, the designer and manufacturing engineer should become more familiar with the capabilities of the magnetic-pulse forming process.

CHAPTER II

RELATED EQUATIONS FOR MAGNETIC-PULSE FORMING

Theoretical equations for predicting the performance of the magnetic-pulse forming process were developed by D. H. Birdsall of the University of California during the controlled-fusion reactor program.³ These equations are presented and discussed in this chapter in order to understand better how the forming process functions.

The energy used to accomplish magnetic-pulse forming is supplied by a capacitor bank. This stored energy is a function of capacitance and voltage, as shown in Equation 1:

$$U_m = 1/2 CV^2, \quad (1)$$

where:

U_m represents the magnetic field energy,

C the capacitance, and

V the charge voltage on the capacitor bank.

When the stored energy from the charged capacitor bank is discharged into a work coil, as shown in Figure 2, Page 5, it reappears in the form of magnetic energy. The equation for this transition is:

$$U_m = 16.39 \int_0^V B^2 / 8\pi dv \times 10^{-7}, \quad (2)$$

where:

U_m represents the magnetic field energy,

B the magnetic flux density, and

v the volume of the high field intensity.

Although Equation 2 is to be taken over all space, the only portion of the integral that contributes significantly is that portion taken over the volume of high field intensity. The cross section of high field intensity is shown in Figure 4.

Obviously, the smallest and closest fitting coils will produce the highest forming pressure on the work piece.

At the half-megagauss level, the energy density of a magnetic field compares with the most effective chemical explosive. In both these contexts, energy density is associated with intense expansive pressures. Specifically, the axial magnetic field of a coil behaves like a gas in that it exerts a radial pressure mathematically identical with the $B^2/8\pi$ term in Equation 2. This term can be represented as the forming pressure available for performing useful work as shown in Equation 3:

$$P_f = B^2/8\pi \times 1.45 \times 10^{-5}, \quad (3)$$

where:

P_f represents the pressure available for
magnetic forming, and

B the magnetic flux density.

If the magnetic flux density is assumed constant over the volume of high field intensity in Equation 2, an integration of this equation results in the following expression for the pressure available for magnetic forming:

FIGURE 4

CROSS SECTION OF A MAGNETIC-PULSE FORMING COIL SHOWING
THE REGION OF MAXIMUM FLUX DENSITY

$$P_f = B^2 / 8\pi = \frac{8.85 U_m}{v}, \quad (4)$$

where the terms have the meanings previously defined.

A plot of the forming pressure as a function of the volume of the maximum magnetic flux density at various energy levels of available energy up to 45,000 joules is presented in Figures 5 and 6. Thus, if the radial clearance between the work coil and part is known, the volume of maximum magnetic flux density can be computed and the resulting pressure for magnetic forming can be selected from Figures 5 and 6 at any desired energy level up to 45,000 joules. The necessary radial clearance between the work coil and part is dictated by the amount of insulation required between the two to prevent voltage breakdown plus the added gap required for assembly clearance.

Another important consideration in magnetic forming is the skin-penetration depth of the eddy currents induced in the work piece by the magnetic field. The depth of the induced currents is a function of the resistivity of the material and the half-cycle time of the current pulse. The current flowing through the work coil reaches a maximum value at a time dictated by the resistivity, capacitance, and inductance, and inductance of the capacitor-bank circuit. The equation for estimating the depth of the induced eddy currents is:⁴

$$S = \frac{1}{\pi} \left(\frac{\eta \tau}{2} \right)^{1/2}, \quad (5)$$

FIGURE 5

ANNULAR VOLUME BETWEEN THE MAGNETIC-PULSE FORMING COIL
AND THE PART AS A FUNCTION OF THE FORMING PRESSURE
AVAILABLE AT VARIOUS ENERGY LEVELS
($E = 5,000 - 45,000$ Joules)

FIGURE 6

ANNULAR VOLUME BETWEEN THE MAGNETIC-PULSE FORMING COIL
AND THE PART AS A FUNCTION OF THE FORMING PRESSURE
AVAILABLE AT VARIOUS ENERGY LEVELS
($E = 1,000 - 9,000$ Joules)

where:

- S represents the current penetration depth,
- τ the half-cycle time of the current pulse, and
- η the resistivity of the material being formed.

Thus, consideration of the thickness of the material being formed along with current-rise time and resistivity are very important. The thickness of the part being formed must be greater than the current-penetration depth or only heating of the part will result. This effect is due to the fact that the magnetic field diffuses through the tube wall just as a gas would diffuse through a porous membrane.

Figure 7 shows the current-penetration depth of several materials as a function of the RLC circuit-ringing frequency. The ringing frequency of the capacitor bank describes the oscillatory characteristics of the current discharge through the work coil which specified the time to maximum current. Therefore, from Figure 7, and knowing the material to be formed and the ringing frequency of the capacitor-bank circuit, the minimum thickness of material that can be formed by a magnetic field can be determined.

For example, note that in Figure 7 an RLC circuit frequency of 2×10^3 cycles/second shows that the minimum thickness of stainless steel that can be formed is 0.370 inch, while for aluminum the minimum thickness is 0.082 inch. These values illustrate that a good conductor is mandatory when relatively thin materials are being formed. If, for example, a thickness of 0.082 inch of stainless steel

FIGURE 7

CURRENT PENETRATION DEPTH AS A FUNCTION OF
THE RLC CIRCUIT FREQUENCY

were pulsed with an RLC circuit frequency of 2×10^3 cycles/second, only heating of the stainless steel specimen would result.

The excellent sharpness of detail that can be obtained with the magnetic-forming process is due to the high velocities at which the metal moves. The average velocity attained by the tube in Figure 4 when moving through a radial distance equal to the wall thickness of the tube, δ , is:

$$V_a = (B^2 / 4\pi\rho)^{1/2}, \quad (6)$$

where:

B represents the magnetic flux density,

ρ the mass density of the metal,

V_a the average velocity attained when moving a distance δ , and

δ the tube wall thickness.

In this equation, B has been taken constant over the distance of movement.

V_a is the "Alfv'en velocity" of plasma physics.⁵

The time required for the tube to move through a displacement, ϵ , is:³

$$\tau_a = \frac{2(\epsilon\delta)^{1/2}}{V_a}, \quad (7)$$

where:

τ_a represents the time required to travel a distance ϵ ,

ϵ the distance traveled,

V_a the average velocity attained when
moving a distance δ , and
 δ the tube wall thickness.

The maximum current pulse time for which the magnetic field does not penetrate appreciably through the tube wall according to Equation 5 is:

$$\tau_{do} = \frac{2\pi\delta^2}{\eta}, \quad (8)$$

where:

τ_{do} represents the maximum half-cycle
current pulse time for which the
magnetic field does not penetrate through
the tube wall.

The other terms have been defined previously.

Thus, if the tube is being formed against a metal die, as shown in Figure 4, $\tau_a < \tau_{do}$ to avoid a magnetic "cushion." A magnetic "cushion" is produced when the magnetic field diffuses through the tube wall shown in Figure 4 causing the tube to rebound due to magnetic pressure after the first impact. However, if the mandrel is made of insulating material, the time required to fill the cross section with flux is:

$$\tau_{di} = \frac{2\pi R\delta}{\eta}, \quad (9)$$

where:

τ_{di} represents the time required to fill

the inside of the tube with the magnetic field,

R the inside tube radius, and δ and η have the connotations previously defined.

Thus, if the tube is being formed on an insulating mandrel $\tau_a < \tau_{di}$. Of course, the condition that $\tau_a < \tau_{do}$ imposes a condition on the minimum thickness of metal that can be formed because of current-penetration considerations.

During a magnetic field pulse, the temperature of the work piece is raised by joule heating.⁶ This temperature rise can be represented as:

$$\Delta T = \frac{0.37 B^2}{C_v} \times 10^{-9} \quad (10)$$

where:

ΔT represents the temperature rise of the part surface,

B the magnetic flux density, and

C_v the specific heat per unit volume.

The joule heating of the part is:

$$E_i = B^2 / 8\pi SA, \quad (11)$$

where:

E_i represents the joule heating,

B the magnetic flux density,

S the current penetration depth, and

A the surface area of the part.

The S factor is developed from Equation 5. The joule heating will normally be negligible compared with other contributions, provided the half-cycle time of the current pulse is equal to or less than the maximum half-cycle current pulse time for which the magnetic field does not penetrate through the tube wall, as defined by Equation 8.

CHAPTER III

EFFICIENCY DETERMINATION OF THE MAGNETIC FORMING PROCESS

The efficiency of the magnetic forming process was desired so it could be compared with other high-energy-rate processes. Magnetic-pulse forming is well suited for cylindrical geometry which makes the process ideal for swaging and expanding tubing. The basic shape chosen to determine the efficiency of the process was thus a cylindrical shape since cylindrical coils can be fabricated with ease when compared to other types of forming coils.

Figure 8 shows the male expansion coil used for expanding the tubing. The tubing was pulsed and allowed to expand freely. Three-inch-OD Type 2024-0 aluminum tubing of two different wall thicknesses (0.125 and 0.062 inch) was selected for the experiment.

The method used for computing the efficiency of the forming process utilized marked longitudinal increments of 0.200 inch width on the outside surface of the tubing. Figure 8 shows a sketch of the marked aluminum tubing on the forming coil prior to firing. Figure 9 is a sketch of the bulged aluminum tube along with a definition of the symbols used in the following analysis to arrive at an expression for work done on the tube which can be represented as:

$$W_c = \sum_{o}^n F_c \Delta S_c, \quad (12)$$

FIGURE 8

SETUP FOR BULGING ALUMINUM TUBING

FIGURE 9

DEFINITION OF SYMBOLS USED IN
EFFICIENCY DETERMINATIONS

where:

F_c represents the force in the circumferential direction, and
 ΔS_c the change in circumference at each marked increment.

Now, the force in the circumferential direction can be computed from the following equation:

$$F_c = \sigma_c A_c, \quad (13)$$

where:

σ_c represents the circumferential stress, and
 A_c the area upon which F_c acts.

The area in the circumferential direction for each increment is:

$$A_c = t_f \times \Delta, \quad (14)$$

where:

t_f represents the final tube wall thickness, and
 Δ the width of the circumferential increment.

The change in circumference of the increment is given by:

$$\Delta S_c = 2\pi (Y_n), \quad (15)$$

where:

Y_n represents the distance of the center of the increment from the initial outside tube radius.

Thus, substituting Equations 13 and 15 into 12 results in the following equation for work done on the tube.

$$W_c = 2\pi \sum_{o}^n \sigma_c A_c Y_n. \quad (16)$$

The value of σ_c for each increment can be determined from the true stress-true strain diagram shown in Figure 10 by determining the circumferential strain at each increment position.

The circumferential efficiency can be determined from the following equation:

$$C_e = \frac{W_c}{E_s} \times 100, \quad (17)$$

where:

E_s represents the stored energy in the capacitor bank = $1/2 CV^2$, and

W_c work done on the tube.

Figure 11 gives a cross-section photograph of the bulged aluminum tubes whose results are reported in Tables I and II. It was found that by increasing the number of turns of the coil per given coil length, the efficiency of the magnetic-pulse forming process increases. This result could be expected, since the magnetic field strength is a function of the number of turns of the work coil. Tables I through V summarize the results of the efficiency determinations. The coil used in Table I contained 18 turns over a length of three inches, whereas the coil for

FIGURE 10

TRUE STRESS AS A FUNCTION OF THE TRUE STRAIN
FOR TYPE 2024-O ALUMINUM

FIGURE 11

CROSS SECTION OF THREE-INCH ALUMINUM TUBING
AS BULGED BY THE MAGNETIC-FORMING PROCESS

TABLE I
EFFICIENCY DETERMINATION OF A THREE-INCH, 0.125-INCH-
THICK ALUMINUM TUBE PULSED WITH 8200 JOULES,
WORK INPUT TO TUBE OF 2815 JOULES

Point	D	t	A _c	ε _c	σ _c × 10 ⁴	Y	σ _c A _c Y
1	3.007	0.116	0.0232	0.0023	1.270	0.0035	0.000103
2	3.084	0.113	0.0226	0.028	2.285	0.042	0.002169
3	3.233	0.109	0.0218	0.077	3.062	0.1165	0.007776
4	3.449	0.104	0.0208	0.149	3.596	0.2245	0.016792
5	3.670	0.098	0.0196	0.223	3.973	0.335	0.026086
6	3.846	0.096	0.0192	0.282	4.234	0.423	0.034387
7	3.977	0.090	0.0180	0.326	4.379	0.4885	0.038504
8	4.065	0.089	0.0178	0.355	4.466	0.5325	0.042328
9	4.108	0.089	0.0178	0.369	4.524	0.554	0.044612
10	4.098	0.089	0.0178	0.366	4.500	0.549	0.043975
11	4.024	0.092	0.0184	0.341	4.448	0.5120	0.041904
12	3.893	0.092	0.0184	0.297	4.274	0.4465	0.035113
13	3.734	0.096	0.0192	0.245	4.094	0.3670	0.028846
14	3.535	0.096	0.0192	0.178	3.770	0.2675	0.019363
15	3.317	0.105	0.0210	0.106	3.306	0.1585	0.011004
16	3.146	0.110	0.0220	0.049	2.731	0.073	0.004386
17	3.024	0.113	0.0226	0.008	1.737	0.012	0.000471
18	3.006	0.117	0.0234	0.002	1.226	0.003	0.000086

$$\text{Efficiency} = \frac{2815 \text{ Joules}}{8200 \text{ Joules}} \times 100 = 34.3\%.$$

TABLE II
 EFFICIENCY DETERMINATION OF A THREE-INCH, 0.125-INCH-
 THICK ALUMINUM TUBE PULSED WITH 11,800 JOULES,
 WORK INPUT TO TUBE OF 2345.9 JOULES

Point	D	t	A _c	ε _c	σ _c × 10 ⁴	Y	σ _c A _c Y
1	3.105	0.121	0.0242	0.035	2.36	0.0525	0.002998
2	3.239	0.117	0.0234	0.080	3.079	0.1195	0.008610
3	3.425	0.113	0.0226	0.141	3.567	0.2125	0.017130
4	3.612	0.106	0.0212	0.204	3.886	0.3060	0.025208
5	3.784	0.103	0.0206	0.2613	4.164	0.392	0.033622
6	3.928	0.099	0.0198	0.309	4.338	0.464	0.039854
7	4.008	0.096	0.0192	0.336	4.408	0.504	0.042654
8	4.002	0.095	0.0190	0.334	4.396	0.501	0.041845
9	3.928	0.096	0.0192	0.309	4.344	0.464	0.038700
10	3.796	0.099	0.0198	0.265	4.176	0.398	0.032908
11	3.601	0.103	0.0206	0.200	3.886	0.3005	0.024055
12	3.374	0.109	0.0218	0.125	3.451	0.1870	0.014068
13	3.192	0.116	0.0232	0.064	2.923	0.096	0.006510
14	3.058	0.120	0.0240	0.019	2.146	0.029	0.001474

$$\text{Efficiency} = \frac{2345.9 \text{ Joules}}{11,800 \text{ Joules}} \times 100 = 20.0\%.$$

TABLE III
EFFICIENCY DETERMINATION OF A THREE-INCH, 0.065-INCH-
THICK ALUMINUM TUBE PULSED WITH 4500 JOULES,
WORK INPUT TO TUBE OF 1229 JOULES

Point	D	t	A _c	ε _c	σ _c × 10 ⁴	Y	σ _c A _c Y
1	3.012	0.0642	0.016	0.004	1.46	0.006	0.000140
2	3.010	0.0642	0.016	0.0033	1.39	0.005	0.000111
3	3.024	0.064	0.016	0.008	1.74	0.012	0.000334
4	3.084	0.064	0.016	0.028	2.37	0.042	0.001593
5	3.230	0.0592	0.0148	0.0766	3.04	0.115	0.005173
6	3.491	0.0573	0.0143	0.1636	3.68	0.2455	0.012918
7	3.634	0.0535	0.0133	0.2113	3.94	0.317	0.016610
8	3.768	0.0533	0.0133	0.2560	4.18	0.384	0.021347
9	3.826	0.0535	0.01337	0.2753	4.13	0.413	0.022800
10	3.822	0.0543	0.0135	0.274	4.09	0.411	0.022691
11	3.790	0.0545	0.0136	0.2633	4.06	0.395	0.021808
12	3.698	0.0552	0.0138	0.2326	4.02	0.349	0.019359
13	3.539	0.0572	0.0143	0.1796	3.77	0.2695	0.014528
14	3.343	0.0593	0.0148	0.1143	3.39	0.1715	0.008600
15	3.165	0.0625	0.0156	0.055	2.81	0.0825	0.003615
16	3.069	0.064	0.016	0.023	2.26	0.0345	0.001248
17	3.030	0.0642	0.01605	0.010	1.83	0.015	0.000441
18	3.020	0.0642	0.01605	0.0066	1.65	0.010	0.000265
19	3.013	0.0642	0.01605	0.0043	1.47	0.0065	0.000153

$$\text{Efficiency} = \frac{1229 \text{ Joules}}{4500 \text{ Joules}} \times 100 = 27.3\%.$$

TABLE IV
 EFFICIENCY DETERMINATION OF A THREE-INCH, 0.065-INCH-
 THICK ALUMINUM TUBE PULSED WITH 4500 JOULES,
 WORK INPUT TO TUBE OF 1164 JOULES

Point	D	t	A _c	ε _c	σ _c × 10 ⁴	Y	σ _c A _c Y
1	3.018	0.0662	0.0165	0.006	1.615	0.009	0.00024
2	3.016	0.066	0.0165	0.0053	1.57	0.008	0.000207
3	3.015	0.066	0.0165	0.005	1.545	0.0075	0.000191
4	3.061	0.065	0.01625	0.0203	2.20	0.0305	0.00109
5	3.187	0.063	0.0157	0.0623	2.90	0.0935	0.004257
6	3.349	0.061	0.0152	0.1163	3.40	0.1745	0.009018
7	3.522	0.0595	0.0148	0.174	3.78	0.261	0.014600
8	3.661	0.0595	0.0148	0.2203	3.98	0.3305	0.019466
9	3.750	0.059	0.0147	0.250	4.12	0.375	0.022710
10	3.769	0.0592	0.0148	0.2563	4.14	0.3845	0.023558
11	3.713	0.058	0.0145	0.2376	4.15	0.3565	0.021452
12	3.630	0.059	0.01475	0.2100	3.95	0.315	0.018353
13	3.499	0.0612	0.0153	0.1663	3.72	0.2495	0.0142
14	3.328	0.064	0.016	0.1093	3.33	0.164	0.008737
15	3.178	0.0652	0.0163	0.0593	2.86	0.089	0.004148
16	3.068	0.0662	0.01655	0.0226	2.24	0.034	0.001260
17	3.026	0.067	0.01675	0.0086	1.76	0.013	0.000383
18	3.022	0.068	0.0167	0.0073	1.70	0.011	0.000312
19	3.023	0.067	0.01675	0.0076	1.71	0.0115	0.000329

$$\text{Efficiency} = \frac{1164 \text{ Joules}}{4500 \text{ Joules}} \times 100 = 25.9\%.$$

TABLE V
 EFFICIENCY DETERMINATION OF A THREE-INCH, 0.065-INCH-
 THICK ALUMINUM TUBE PULSED WITH 2020 JOULES,
 WORK INPUT TO TUBE OF 422 JOULES

Point	D	t	A _c	ε _c	σ _c × 10 ⁴	Y	σ _c A _c Y
1	2.974	0.0521	0.01302	0.0013	1.1	0.002	0.000029
2	2.977	0.0522	0.01305	0.0023	1.21	0.0035	0.000055
3	3.013	0.0523	0.01307	0.0144	2.01	0.0215	0.000565
4	3.084	0.0522	0.01305	0.0383	2.39	0.057	0.001778
5	3.185	0.0502	0.0125	0.069	2.96	0.1075	0.003978
6	3.284	0.0493	0.0123	0.1057	3.30	0.157	0.006373
7	3.329	0.0485	0.0121	0.1208	3.42	0.1795	0.007428
8	3.355	0.0492	0.0123	0.1283	3.44	0.1925	0.008145
9	3.354	0.0492	0.0123	0.128	3.43	0.192	0.00810
10	3.351	0.049	0.0122	0.127	3.41	0.1905	0.007925
11	3.277	0.0495	0.0123	0.1023	3.28	0.1535	0.006193
12	3.262	0.050	0.0125	0.0973	3.16	0.146	0.005767
13	3.118	0.051	0.01275	0.0493	2.72	0.074	0.002566
14	3.041	0.0522	0.0130	0.0236	2.21	0.035	0.001006
15	3.007	0.0523	0.0130	0.0124	1.94	0.0185	0.000467
16	2.993	0.052	0.0130	0.0090	1.79	0.0115	0.000268
17	2.993	0.0521	0.0130	0.0090	1.79	0.0115	0.000268
18	2.985	0.052	0.0130	0.0050	1.55	0.0075	0.000151

$$\text{Efficiency} = \frac{422 \text{ Joules}}{2020 \text{ Joules}} \times 100 = 21\%.$$

Table II contained nine turns over a length of three inches. Tubing thickness in both cases was 0.125 inch. The efficiency for Table I was 34.3 per cent while Table II showed a result of 20 per cent.

Tables III through V summarize the efficiency results for a 0.065-inch wall tubing. The same forming coil was used for Tables III through V. The results of Tables III and IV show efficiencies of 27.3 and 25.9 per cent, respectively, while Table V shows an efficiency of 21 per cent.

In general, the efficiency of the magnetic-forming process ranges from 20 to 34.3 per cent and is dependent on the type of forming coil used. Efficiencies between 20 and 25.9 per cent could be expected when coils are fabricated from 1/4-inch copper tubing, and radial clearances of 0.030 inch are used.

Free-bulging tests of cylindrical shapes with other high-energy rate-forming processes have been conducted.^{7, 8} The results of these experiments show that the explosive-forming process has an expected efficiency of 16 per cent in the energy range used for the experiments reported in this chapter. The electrohydraulic forming process which uses an exploding wire under water has an efficiency of 19 per cent. Thus, the efficiency of the magnetic-forming process is comparable with other high-energy rate-forming processes.

CHAPTER IV

DETERMINATION OF STRAIN RATES

The determination of the strain rate of parts undergoing expansion was desired so that the magnetic-pulse forming process could be compared with other high-energy rate processes such as explosive forming. The velocity of metal movement obtained from explosive-forming process has been reported to be as high as $2 \text{ mm}/\mu\text{sec}$.⁹ It was felt that if the strain rates of the magnetic-forming process could be determined, then much of the information pertaining to the forming and sizing of parts with explosives could be used by the manufacturing engineer in utilizing the magnetic-forming process.

Experiments were conducted with 0.060-inch-thick aluminum tubes with an outside diameter of two inches. Male expansion coils were used to expand the tubing in an energy range from 2400 to 3600 joules. The test setup for determining the radial velocity is shown in Figure 12. The shadow of the metal under test is projected onto the plate of a photoelectric tube, as shown in the sketch. The output of the phototube is connected to the vertical plates of an oscilloscope which is set for a single-sweep operation. The sweep is triggered when the phototube signal level changes. Therefore, as soon as the aluminum tube begins to move, the scope is triggered and a trace is produced that is directly proportional to the radial tube movement. The resulting scope trace is photographed with a Polaroid camera, thereby giving a plot of radial tube movement as a function of time.

FIGURE 12

TEST ARRANGEMENT FOR MEASURING STRAIN RATES

Typical oscilloscope curves and corresponding metal movement are shown in Figure 13. The oscilloscope was calibrated by using a series of preformed cylinders whose deflections had been measured. Figure 14 gives the calibration curve for the tested cylinders shown in Figure 13.

This type of instrumentation worked quite well for determining strain rates. Even the exact instant a split or tear occurs, it is recorded as indicated by breaks in the curve (see bottom two cylinders, Figure 13). A plot of the test results from these data (Figure 15) show that for deforming thin tubing at low bank energies (~ 2400 joules) a velocity of $0.02 \text{ mm}/\mu\text{sec.}$ is obtained, while a bank energy of 3600 joules produces a velocity of $0.06 \text{ mm}/\mu\text{sec.}$

Flash radiographs of copper cylinders undergoing expansion were also taken during the course of determining strain rates. A 600-kv pulse X-ray system, which had a delayed-time triggering circuit, was used to record the destruction of a copper cylinder. Figure 16 shows the results of pulsing a 0.025-inch-thick copper cylinder. The heavy section in the left of each photograph is the lap solder joint in the tubing. Figure 17 presents a full-size photograph of the magnetic destruction of the 0.025-inch-thick copper cylinder. In this photograph, the construction of the coil can be seen along with the three-ball firing circuit used to trigger the recharged capacitor bank. The strain rate obtained from this test was $0.2 \text{ mm}/\mu\text{sec.}$ at a bank energy of 10,000 joules.

Only radial velocities have been discussed thus far. In sheet metal, forming velocities other than radial velocities are often considered. To illustrate this,

FIGURE 13

DEFORMED ALUMINUM TUBES WITH CORRESPONDING
OSCILLOSCOPE TRACES SHOWING
TIME vs RADIAL DISTANCE

FIGURE 14

CALIBRATION CURVE FOR TESTED CYLINDERS

FIGURE 15

RADIAL VELOCITY AS A FUNCTION OF
THE BANK ENERGY

FIGURE 16

FLASH RADIOGRAPHS OF A COPPER CYLINDER UNDERGOING
HIGH-SPEED ELECTROMAGNETIC DEFORMATION
(50 to 300 Microseconds after Electromagnetic
Pulse Initiation)

FIGURE 17

X-RAY PHOTOGRAPH SHOWING A 0.025-INCH-
THICK COPPER CYLINDER 50 MICROSECONDS
AFTER ELECTROMAGNETIC
PULSE INITIATION

equations derived by Mr. Rex A. Ford of the Chance Vought Corporation are presented.¹⁰ He considered two velocities: (1) deformation or radial velocity, defined as the time rate of change of displacement in the direction of the applied force of any point on a part blank as it is formed to the final part shape; and (2) the relative velocity between two points on the surface of a part blank with an initial gage length. If the deformation velocity can be determined, then the relative velocity can be calculated from Mr. Ford's equations which are presented below. For example, he considered the expanded tube shown in Figure 18 where the strain rates, $d\epsilon/dt$, and the relative velocity, V_r , of two points designated A and B on the tube as the tube expands are given by:

$$\frac{d\epsilon}{dt} = \frac{L_f - L_o}{L_o dt} = \frac{dL}{L_o dt} = \frac{V_r}{L_o}, \quad (18)$$

where:

$\frac{d\epsilon}{dt}$ represents the strain rate,

L_f the final gage length,

L_o the initial gage length, and

V_r the relative velocity between two points A and B on the surface of a tube of initial gage length L_o .

The strain rate of the expanding tube is given by:

FIGURE 18

CIRCUMFERENTIAL STRAIN FOR TUBE EXPANSION

$$\frac{d\epsilon}{dt} = \frac{R_f - R_o}{R_o dt} = \frac{dR}{R_o dt} = \frac{du}{R_o dt}, \quad (19)$$

where:

R_f represents the final outside tube radius,

R_o the initial outside tube radius, and

$\frac{du}{dt}$ the radial or deformation velocity.

Therefore, the relationship between the relative particle velocity and the deformation velocity would be:

$$V_r = \frac{L_o}{R_o} \frac{du}{dt}, \quad (20)$$

where:

V_r represents the relative circumferential

velocity between two points on the

surface of a tube of initial gage length

L_o , and

L_o the initial gage length.

From the data collected in this chapter, the strain rate of the magnetic-pulse forming process increases as the capacitor bank energy is increased. Thus, with higher bank energies it may be possible to obtain strain rates corresponding to the explosive-forming process.

CHAPTER V

COIL DESIGN

In applying electromagnetics to metal forming, the greatest problem to be solved after initial equipment installation is to provide adequate work coils. The energy available in the capacitor bank is equal to:

$$U_m = 1/2 CV^2, \quad (1)$$

where:

U_m represents the capacitor bank stored energy,

C the capacitance, and

V the voltage.

It is apparent from this relationship that there are only two ways to provide an adequate energy level: (1) to add to the capacitance of the bank thereby reducing the voltage level requirements to obtain a specific energy level; and (2) to increase the charge voltage in the capacitors. The first method is expensive while the second method is attractive. However, a disadvantage is that all work coils require dielectric insulating materials. Thus, this dielectric requirement imposes a limit on the maximum value of the voltage that is allowable on the work coil. For practical insulation considerations, 20,000 volts is an acceptable limit.

At the half-megagauss level, the energy density of the magnetic field compares with that of the most effective chemical explosives. Specifically, the axial magnetic field of a coil behaves like a gas in that it exerts a radial pressure

that is mathematically identical with the magnetic-energy density and can be computed from the following equation:

$$P_f = \frac{B^2}{8\pi} \times 1.45 \times 10^{-5}, \quad (3)$$

where:

P_f represents the pressure available for

magnetic forming, and

B the magnetic flux density.

The radial pressure acting on the cylindrical work coil shown in Figure 19 can be computed from this equation.

Figure 20 gives a plot of the radial pressure as a function of the bank energy for the coil shown in Figure 19.

The coil, as shown in Figure 19, has been pulsed with bank energies up to 20,000 joules with no noticeable damage. The coil was constructed by machining the current-carrying member in the form of a helix. In this case the material was Type 6061-T6 aluminum with a cross section 0.025-inch thick by 0.375-inch wide. The dielectric insulation was micarta of 0.090-inch thickness. Again, the micarta was machined in the form of a helix. The two coil sections were then fastened together to make the basic coil. Radial reinforcement of the coil was obtained by winding a continuous glass filament saturated with an epoxy resin system. Strengths of typical fiber glass layups and epoxy resins are presented in the Appendix (Tables VII through XI, Pages 92 through 96). An alternate

FIGURE 19

FEMALE FORMING COIL WITH A THREE-INCH
INSIDE DIAMETER

FIGURE 20

RADIAL PRESSURE AS A FUNCTION OF THE ENERGY FOR
THE FEMALE FORMING COIL

method for constructing the coil would be to substitute a glass-filament winding to separate the turns of the coil instead of the machined micarta. This arrangement should prove to be a more economical approach to coil manufacture.

The major remaining problem is the problem of durable insulation. The axial attraction of the conducting turns for one another, combined with the tendency of the inside edges of the conducting turns to thicken under the impact of the radial force, produces a punching effect on the intervening insulating material. The use of precompression in the axial direction decreases the tendency for the conducting edge to thicken and buckle under the radial force. Thus, the permanent coils fabricated to date to withstand high-energy pulses have been designed like the one shown in Figure 19.

The expected heating of the work coil from a forming cycle can be computed by Equation 11, Chapter II, Page 20.

The resulting net increase in the working temperature of the work coil can be derived by substituting $\frac{U_m}{V} \times 10^7$ from Equation 2, Chapter II, Page 10, for $\frac{B^2}{8\pi}$ in Equation 11, Chapter II, Page 20, and dividing by the specific heat, density, and volume of the work coil. The resulting expression is:

$$\Delta T = \frac{0.2388 \times U_m \times SA}{V C_v \rho V_c}, \quad (21)$$

where:

U_m represents the stored energy in the capacitor bank,

- S the current penetration depth,
- v the volume of the maximum field intensity,
- ρ the density of the work coil,
- V_c the metal volume of the work coil,
- A the surface area of the work coil inside
the contour,
- ΔT the temperature rise of the work coil, and
- C_v the specific heat of the work coil.

The net temperature increase for the work coil for an energy pulse of 20,000 joules is 5°C . Thus, where sufficient time is allowed between pulses, the temperature rise of the work coil would not be a serious problem. However, forced cooling of the coil would be required for automatic production operation.

The coil shown in Figure 19, Page 48, has performed remarkably well. It has been pulsed at least fifty times at an energy level of 20,000 joules with no resulting damage.

Figure 21 is a photograph of the first coil of this type to be fabricated. The type of construction is similar to the one shown in Figure 19, Page 48, except that epoxy was used to separate the machined aluminum helix. Also, instead of fiber glass filaments saturated with epoxy, fiber glass cloth impregnated with epoxy was used. In addition, epoxy was cast outside of the fiber glass layup. Note in Figure 21 that the tangential stresses have cracked the outer layer of epoxy. This

FIGURE 21

A FEMALE FORMING COIL AFTER FAILURE

type of coil construction proved to be inferior to the one in Figure 19, Page 48, because the fiber glass cloth could not be adequately saturated with epoxy. Note also that axial lines can be seen on the inside of the work resulting from the circumferential stresses. In this design an attempt was made to cast a dielectric layer of epoxy 0.030-inch thick to insulate the work coil from the workpiece. However, this arrangement did not prove successful due to the brittle nature of the epoxy. To obtain adequate insulation of the workpiece from the work coil, a layer of mylar sheet was wrapped around the workpiece before inserting it into the work coil.

Male coils to expand tubing have been constructed according to the drawing in Figure 22. This type of coil construction has proven to be very economical. Standard 1/8-inch copper tubing with two layers of 0.008-inch-thick fiber glass roving was used to wind the coils. After the coil was wound, it was placed in a mold and an epoxy and fiber glass mixture poured in. The short strands of fiber glass gave the coil added compressive strength.

Figure 23 shows a coil of this type after failing at an energy pulse of 13,000 joules. The main cause of failure was because the dielectric material broke down between turns. This type of construction could be improved by placing a more rigid insulating material between the turns such as the micarta used in the female work coil shown in Figure 19, Page 48.

Small coils have been made to fit inside of 0.750-inch stainless steel tubing. Figure 24 shows a completed coil, a coil after being wound on the plastic, and a coil after failing at an energy level of 6000 joules. The core material is

FIGURE 22
MALE FORMING COIL CONSTRUCTION
(2.750-Inch Diameter)

FIGURE 23

MALE FORMING COIL AFTER FAILURE
AT 13,000 JOULES

FIGURE 24

MALE FORMING COIL
(0.575-Inch Diameter)

Teflon with a helix machined to accept 0.085-inch-diameter copper wire. After the copper wire is wound on the plastic, glass filaments saturated with epoxy are wound to furnish the insulation between turns and the dielectric insulation between the work coil and workpiece.

As a safety precaution, all forming operations should be shielded to protect operating personnel from dangerous coil fragments in case of coil failure. Figure 25 shows what will happen when the safe operating limits of a male expansion coil are exceeded.

"Pancake"-type coils have also been constructed to accelerate flat sheet specimens into a female die cavity. Figure 26 is a photograph of a coil of this type. Again, 1/8-inch copper tubing, with two layers of 0.008-inch-thick fiber glass roving, was wound in a tight spiral and glued between several layers of fiber glass cloth. This layup was then bonded to a 3/8-inch micarta plate for mounting onto a supporting fixture.

Hemispherical forming coils have been made from 1/4-inch square copper tubing wound with glass tape. Figure 27 shows a 14-inch-diameter hemispherical coil that was wound to determine the feasibility of fabricating large forming coils. After the basic coil was wound, the coil was mounted on a winding mandrel and fiber glass filaments saturated with epoxy were wound on the periphery to furnish support for the radial forces.

Coils discussed thus far have been of a permanent-construction type which is often expensive. Another approach for magnetic-pulse forming coils is the use

FIGURE 25

MALE FORMING COIL AFTER COMPLETE FAILURE

FIGURE 26
PANCAKE-TYPE FORMING COIL

FIGURE 27

AS-WOUND FOURTEEN-INCH HEMISPHERICAL
FORMING COIL

of expendable-type coils. Figure 28 shows a coil mounted on a part just before swaging. This coil is composed of a few turns of plastic-insulated copper wire. These coils are wound on mandrels which are made the same size as the part OD and then slipped over the part end. The cost is quite reasonable for such a coil (approximately 2 to 3 cents per coil compared to hundreds of dollars per coil for the permanent type).

These coils rely on the inertia of the coil to contain the magnetic field long enough to permit the swaging operation to be completed before the coil is finally destroyed by the magnetic field. When using this type of coil it is necessary to guard against flying pieces of copper debris.

FIGURE 28
EXPENDABLE FORMING COIL

CHAPTER VI

PART TYPES MOST READILY FORMED WITH
MAGNETIC-PULSE FORMING

Tubular-type parts can be formed very effectively with magnetic-pulse forming. This can be achieved because of the low radial clearance which can be maintained between the work coil and the part to be formed. The radial clearance normally used is about 0.025 inch. As discussed in Chapter II, the forming pressure is an important function of the radial clearance that can exist between the coil and part to be formed. Figure 29 shows a swaging-type work coil surrounding a piece of aluminum tubing containing an insert. High pressure can be achieved on the outer circumference of the tube thus swaging it permanently onto the insert. Figure 30 is a photograph of thin aluminum tubes after swaging on an internal member. This type of forming is ideal for pressure-tight joints between two lengths of tubing. A typical joint design is shown in Figure 31. Pressure-vessel joints are also possible with this type of female forming coil. A drawing of a typical design which can be assembled very efficiently with the swaging-type work coil is given in Figure 32. Thus, the magnetic-forming process is ideal for swaging-type forming work.

Besides jointing and swaging operations, components can be accurately sized on precision-male mandrels by yielding the metal in compression. Figure 33 shows a typical setup for sizing a 0.012-inch stainless steel reducer on a

FIGURE 29

SWAGING TYPE WORK COIL
SURROUNDING A PIECE
OF ALUMINUM
TUBING

FIGURE 30

ALUMINUM TUBING SWAGED ON
AN INTERNAL MANDREL
(0.062-Inch Thick)

FIGURE 31

TYPICAL PRESSURE-TIGHT JOINT BETWEEN
TWO LENGTHS OF TUBING

FIGURE 32
TYPICAL END-PLUG DESIGN

FIGURE 33

TYPICAL COIL SETUP FOR SIZING STAINLESS
STEEL REDUCERS

precision-male mandrel. Three parts sized in their respective mandrels are presented in Figure 34. The clearances before and after sizing are summarized in Table VI. The data of Table VI show that a larger radial gap before pulsing produces a container with a tighter fit. However, when excess radial clearance exists, wrinkling occurs. This effect can be noticed in the Type 3 part in Figure 34. The radial gap existing prior to sizing was 0.0275 inch. After sizing, the radial gap was reduced by 92.7 per cent. Figure 35 shows an end view of the Type 3 reducer prior to sizing to illustrate the excessive radial gap.

The reducers shown in Figure 34 were formed with the use of a 0.010-inch aluminum pusher. The magnetic field forced the conducting aluminum pusher against the stainless steel, resulting in high peak pressures for forming.

As discussed in Chapter II, to move metal with a magnetic field, the current-penetration depth must be equal to or less than the thickness of the part being formed. To illustrate this fact, several stainless steel specimens were pulsed that had various thicknesses of copper plating. Since the current-penetration depth of stainless steel greatly exceeds the 0.012-inch thickness of the test specimens, the unplated specimen would be heated and not formed. Figure 36 shows the results of this experiment. Specimen B, the unplated stainless steel specimen, shows no deformation. Note also in Figure 36 that as the thickness of the copper plating increases, some degree of forming takes place. This experiment shows how the copper plating acts as a pusher.

FIGURE 34

STAINLESS STEEL REDUCERS SIZED ON MALE MANDRELS

TABLE VI
SUMMARY OF CLEARANCES BEFORE AND AFTER THE REDUCERS WERE SIZED

Energy (joules)	Mandrel Material	Part Type Number	Gap A Before Sizing	Gap A After Sizing	Reduction (%)	Gap B Before Sizing	Gap B After Sizing	Reduction (%)	Remarks
6,000	Micarta	1	0.008	0.004	50	0.006	0.0035	41.6	
6,000	Brass	2	0.0125	0.003	72	0.011	0.002	81.8	
6,000	Micarta	3	0.0275	0.002	92.7	0.0165	0.003	81.8	Wrinkling on Large Diameter

FIGURE 35

END VIEW OF A TYPE 3 CONTAINER
PRIOR TO SIZING

FIGURE 36

COPPER PLATED ON STAINLESS STEEL SPECIMENS

The implosion-type forming coil offers the manufacturing engineer an important assembly tool. Thin-metal sheaths can be compressed onto a relatively massive component without damage to the component because of the comparatively small amount of energy which can be transferred from the moving sheath. When consideration is given to the protection of the surface finish of parts, the magnetic-forming process is the only process that has no physical pressure medium in contact with the part.

The implosion-type forming coil can be very flexible in its application for forming small special one-of-a-kind parts. Since one well-built forming coil can be used with several field shapers. A field shaper is a current-carrying conductor inductively coupled to the forming coil. Beryllium-copper alloys work quite well as a shaper material because they furnish high electrical conductivity and possess adequate mechanical properties. Figures 37 and 38 show two types of field shapers. The shaded areas show the high-pressure regions. With this type of forming system, field shapers can be machined in a relatively short time to allow the manufacturing engineer to handle special one-of-a-kind parts. This method is much more economical than manufacturing a special coil for each particular part. The manufacture of special coils should only be considered when production-type quantities are being considered.

Implosion coils other than in the cylindrical geometries can be used with magnetic-pulse forming. Figure 39 shows a two-inch ID hemispherical forming coil. The small coil was constructed to study the limitations of forming with the

FIGURE 37

FIELD SHAPER IN A SWAGING-TYPE
MAGNETIC FORMING COIL
(Selected Area)

FIGURE 38

FIELD SHAPER IN A SWAGING-TYPE
MAGNETIC FORMING COIL
(Complete Area)

FIGURE 39

HEMISPHERICAL FORMING COIL
(2-Inch ID)

spherical-type coil geometry. Figure 40 shows some of the parts before and after pulsing which have been formed at an energy level of 3000 joules. Part A was formed on a grooved spherical mandrel to determine the amount of detail possible. Note that Part A after forming shows excellent detail except at the pole. The pole of the 0.030-inch copper part was not deformed because of the absence of a magnetic field in the polar region. The forming pressure reaches its maximum value at the 45-degree position and goes to zero at the pole. Part B in Figure 40 has been pulsed onto a spherical mandrel while Part C has been pulsed with no mandrel inside the part.

Hemispherical forming coils as large as 14 inches have been constructed. (Fourteen inches represented the upper size limit for the available energy.) Aluminum hemispheres 0.024-inch thick have been pulsed onto hemispherical mandrels for sizing. In this application, a close fit was not a requirement in the polar region thus overcoming the limitation of this type of coil.

The remaining type of implosion forming coil which has been studied is the design shown in Figure 41. This type of coil could be used to form one-half of a part at a time for those part types that would not permit assembly with the cylindrical-type forming coil shown in Figure 29, Page 62. Figure 42 shows a part which could be used with this type of forming coil.

The expanding-type forming coil, shown in Figure 22, Page 54, fits inside the part to be formed and expands the part to fit the external member. Split dies normally are utilized for this type of work. Usually, expanding-type forming coils can be

FIGURE 40

COPPER PARTS FORMED WITH A HEMISPHERICAL
FORMING COIL

FIGURE 41
HALF-CYLINDER FORMING COIL

FIGURE 42

TUBULAR PART TO BE SIZED BY A HALF-
CYLINDER FORMING COIL

manufactured at low cost. This advantage facilitates the use of this type of forming operation for special low-production-type parts.

The expansion-type coil has been utilized to develop techniques for assembling stainless steel tubing into heat exchangers. In this application it was important to protect the surface finish of the inside contour of the tubing due to the corrosive nature of liquids flowing in the heat exchanger. Expansion-type coils, as shown in Figure 24, Page 56, were used to develop techniques for assembling stainless steel tubing into bulkheads. Figure 43 shows a cross-section photograph of an expansion-type coil inside the stainless steel tubing after pulsing. Note that the stainless tubing has been expanded approximately 0.060 inch on the diameter. This amount was quite sufficient to give a good metal-to-metal contact. In this case, a 0.020-inch-thick aluminum pusher was used.

In later work of this type it was found that the stainless steel tubing could be expanded sufficiently without an aluminum pusher because of the thickness of the stainless steel tubing. Figure 44 is a photograph of a sample tube assembled into a mock plate representing the bulkhead. The center tube in the photograph has been expanded without constraint to an increase in diameter of 0.080 inch. For conducting tubing, this type of design would have excellent efficiency.

Figure 45 shows a typical forming setup for the "pancake"-type forming coil. This type of coil accelerates the part upward into the die. As in the hemispherical forming coil, the primary limitation is the absence of a magnetic field at the center. However, for several types of forming jobs this does not handicap the

FIGURE 43

CROSS SECTION OF AN EXPANSION-TYPE
FORMING COIL INSIDE A STAINLESS
STEEL TUBING AFTER PULSING

FIGURE 44

A STAINLESS STEEL TUBING ASSEMBLED INTO A MOCK BULKHEAD

FIGURE 45

ARRANGEMENT FOR A PANCAKE-TYPE
FORMING COIL

forming process. Stainless steel can also be formed with this type of coil with the use of a pusher. Usually, aluminum sheet is used which is destroyed after each part is formed. During the course of this investigation a reusable pusher was developed which consists of a two-layer vinyl plastic with a layer of copper screen in the center. The vinyl plastic is bonded together with the copper screen in the center. This type of pusher has been reused as many as twenty times which eliminates wasting an aluminum pusher after each shot.

In the magnetic-forming process, extremely high pressure is exerted on the metal being formed. To illustrate this, calculations were made by Mr. D. F. Brower of the General Dynamics Corporation.¹¹ These calculations showed that a sheet of 0.150-inch-thick aluminum lying on a spiral coil (as shown in Figure 45) would produce a uniform magnetic field of 300 kilogauss on its surface. Thus, this magnetic field would exert a pressure on the aluminum sheet of about 4×10^9 dynes per square centimeter. Therefore, the aluminum sheet would be accelerated at the rate of 4×10^9 cm./sec./sec. The sheet at the end of 10 microseconds would be traveling at the rate of 40,000 cm./sec. and would have traveled a distance of 2 mm. Now, if this sheet is deaccelerated over a distance of 0.020 inch an average force of 200,000 pounds per square inch would be exerted. These types of pressures are available with only the larger conventional forming machines. However, because of the short pulse realized by the magnetic-forming process, a small amount of energy is transferred to either the work coil or to the die. Therefore, the massive strength needed in conventional forming machines is not required.

The magnetic-forming process can be utilized to form a variety of materials, but the efficiency of magnetic-pulse forming depends upon the resistivity of the metal being formed. Therefore, it follows that the materials most suitable for magnetic-pulse forming operations are those with high electrical conductivity (copper, silver, gold, and aluminum down to the mild steels). Table XI (Appendix) gives the relative resistivity of some materials used in industry. For good practical results in magnetic-pulse forming, the resistivity of the material should be less than 15 micro-ohm centimeters.

Cylindrical parts ranging from 0.750 inch to 24 inches in diameter have been formed with the magnetic-pulse forming process. In general, the process is restricted to thin members due to the short time that energy is transferred to the parts. The largest area of use for the process seems to be in swaging or expanding tubular-type parts.

The process is ideal for assembly-line automation which is always an important consideration for the manufacturing engineer. Cycle time could be made low depending on the temperature rise in the forming coils. However, this problem can be solved to a certain extent by utilizing water-cooled coils constructed of copper tubing.

Thus, the process must be examined closely to obtain its maximum usefulness. For thin conductors, it is ideally suited. In some circumstances, the uniform high rate of forming that can be done by this technique makes possible the forming of certain materials which could not be formed by conventional techniques.

Ordinarily, the pressures that can be produced through a magnetic pulse are more than adequate for forming sheets and tubes. However, for forging solid metal workpieces it is, in general, not feasible. Because of the short impulse that can be applied, very little energy can be utilized in a forging operation.

BIBLIOGRAPHY

BIBLIOGRAPHY

- ¹Kaditza, P., A Method of Producing Strong Magnetic Fields, Proc. Royal Society (London), Vol. 115, (1927), p. 658.
- ²Colgate, S. A., Lawrence Radiation Laboratory Report, UCRL-4580, (1955).
- ³Birdsall, D. H., American Machinist/Metalworking Manufacturing, pp. 105, 117, (1961).
- ⁴Harwell, G. P., Principles of Electricity and Electromagnetism, McGraw-Hill Book Company, New York, (1949), p. 585.
- ⁵Cowling, T. G., Magnetohydrodynamics, Interscience, New York, (1957), p. 34.
- ⁶Kolm, H., B. Lax, F. Bitter, and R. Mills, High Magnetic Fields, The MIT Press, (1961).
- ⁷Wood, W. W., Sheet Metal Forming Technology, ASD Interim Report, 7-871 (II, III), (May 1962, September 1962).
- ⁸Wood, W. W., The Tool and Manufacturing Engineer, pp. 83, (October 1963).
- ⁹Wood, W. W., Sheet Metal Forming Technology, ASD Interim Report, 7-871 (I), (January 1962).
- ¹⁰Ford, R. A., High-Velocity Forming of Metals, Prentice-Hall, Incorporated, Englewood Cliffs, New Jersey, (1964), p. 14.
- ¹¹Brower, D. F., Magnetic-Pulse Forming, Paper presented at Society of Automotive Engineers Meeting, New York, (January 11, 1962).

APPENDIX

TABLE VII
GLASS ROVING CONTENT AND HOOP TENSILE STRENGTH

Machine Tension In Roving (lbs)	Resin Content (wt %)		Hoop Tensile Strength (psi)
	Prepreg Roving Before Wrap	Cured Ring	
6	18	18	253,000
12	18	16	260,000
18	18	15	251,000
18	16	16	260,000
18	22	19	251,000
18	25	19	216,000
24	18	15	236,000

Test ring - 3-inch diameter; 0.060-inch-thick wall.

TABLE VIII
PROPERTIES OF VARIOUS COIL REINFORCING MATERIALS

Material	Ultimate Hoop Tensile Strength (psi)	Density (lbs./inch ³)	Specific Strength ⁽¹⁾ (inch x 10 ⁻⁶)	Thermal Conductivity ⁽²⁾	Tensile Modulus of Elasticity (psi x 10 ⁻⁶)	Compressive Strength (psi)
Glass-Resin ⁽³⁾ (unidirectional)	130,000 - 170,000	0.077	1.6 - 2.1	2.0 - 5.0	6.0 - 9.0	70,000 - 175,000
Glass-Resin (bidirectional)	60,000	0.072	0.7	2.0 - 5.0	2.0 - 3.5	40,000 - 60,000
Steel Wire-Resin (bidirectional)	150,000	0.166	1.0	-	12	-
Titanium (homogeneous)	50,000	0.163	0.9	-	16.5	135,000
Steel (homogeneous)	280,000	0.280	0.9	314	30.0	-
Aluminum (homogeneous)	80,000	0.097	0.8	1,416	10.0	40,000
Magnesium (homogeneous)	32,000	0.064	0.5	-	-	-

(1) Specific strength equals ultimate tensile strength/density (approximately).

(2) BTU/hour/° F/square foot/inch.

(3) Interlaminar shear strength = 6,000 to 8,000 psi (parallel to laminations); 20,000 psi (perpendicular to laminations).

Axial bearing strength = 20,000 to 40,000 psi

Compression strength = 50,000 to 70,000 psi

TABLE IX
PROPERTIES OF THERMOPLASTICS

Material Type	Compressive Strength (psi)	Tensile Strength (psi)	Dielectric Strength (volts/mil)
<u>Polychloro-Trifluoro-Ethylene</u>			
	32,000 - 80,000	4,500 - 6,000	530
<u>Polyethylene</u>			
Ethylene-Ethyl Acrylate Copolymer	-	800 - 2,000	450 - 550
High Density	3,200	3,100 - 5,500	450 - 500
Medium Density	-	1,200 - 3,500	500 - 700
Low Density	-	1,000 - 2,300	460 - 700
<u>Polypropylene</u>			
Unmodified	6,000 - 8,000	4,800 - 6,000	500 - 660
Impact	4,000 - 8,000	3,300 - 4,800	500 - 660
<u>Polystyrene Compounds</u>			
Cold Moulded	11,500 - 16,000	5,000 - 9,000	500 - 700
Nonrefractory (organic)	3,700 - 10,000	1,400 - 3,000	50 - 75
<u>Inorganic Molded Plastics</u>			
Glass Bonded Mica	35,000 - 42,000	5,000 - 6,000	250 - 500
<u>Nylon Moulding Compounds</u>			
Type 6/6 Injection Moulding	7,200 - 13,000	7,000 - 12,000	385 - 470
Type 6 Injection Moulding	6,700 - 12,500	10,200 - 12,000	440 - 510

Plastics Properties Chart, Modern Plastics Encyclopedia (1964).

TABLE X
PROPERTIES OF THERMOSET PLASTICS

Material Type	Compressive Strength (psi)	Tensile Strength (psi)	Dielectric Strength (volts/mil)
<u>Polyester and Alkyd Moulding Materials and Compounds</u>			
Preformed Chopped Roving	15,000 - 30,000	25,000 - 30,000	350 - 500
Premix Chopped Glass Moulding Compounds	20,000 - 30,000	4,000 - 10,000	345 - 420
Woven Cloth	25,000 - 50,000	30,000 - 50,000	350 - 500
Granular and Putty Types			
Mineral Filled	18,000 - 25,000	3,000 - 8,000	350 - 450
Asbestos Filled	22,500	4,500 - 7,000	380
Synthetic Fiber Filled	20,000 - 30,000	4,500 - 6,000	365 - 400
<u>Silicone Moulding Compounds</u>			
Asbestos Filler	-	28,000 - 35,000	-
Glass Fiber Filler	10,000 - 15,000	4,000 - 5,000	125 - 300
Mineral Filler	15,000 - 18,000	3,000 - 3,500	380
<u>Urea-Formaldehyde Moulding Compound</u>			
Alpha Cellulose Filler	25,000 - 35,000	6,000 - 13,000	300 - 400
<u>Epoxy Moulding Compounds</u>			
Glass Fiber Filler	20,000 - 60,000	14,000 - 30,000	360
Mineral Filler	10,000 - 15,000	5,000 - 7,000	330 - 400
<u>Epoxy Cast Resins</u>			
No Filler	13,300 - 21,000	4,000 - 13,000	400 - 500
Silica Filler	8,000 - 14,000	7,000 - 13,000	380
<u>Diallyl Phthalate Moulding Compounds</u>			
Glass Filled	9,500 - 18,000	5,000 - 9,000	350 - 400
Mineral Filled	6,000 - 9,000	4,000 - 8,000	375 - 450
Synthetic Fiber Filled	8,500 - 11,500	4,500 - 6,000	350 - 400

Plastics Properties Chart, Modern Plastics Encyclopedia (1964).

TABLE XI
ELECTRICAL RESISTIVITY
(Microhm-cm)

Material	High(1)	Low	Material	High	Low	Material	High	Low
Polyethylenes, Low Density	1025	1023	Cellulose Acetate Butyrate	1018	1016	Low Alloy Steels (23XX)	28.4	-
Polystyrenes, GP	1025	1024	Melamines, Shock Res.	1018	1015	Molybdenum Disilicide	27.2	21.5
TFE, FEP Fluorocarbons	1025	-	Phenolics (molded), Very High Shock	1018	-	Hard Leads	27.1	22
CFE Fluorocarbon	1024	-	Polyesters (cast), Nonrigid	1018	-	Vanadium	25	-
Polymethylstyrene	5.0×10^{23}	2.0×10^{20}	Ureas	5.0×10^{17}	5×10^{16}	Low Alloy Steels (41XX)	22.3	-
Micas	1023	1019	Methylstyrene-Acrylonitrile	2.6×10^{17}	-	Low Alloy Steels (51XX, 61XX)	21	-
Modified Polystyrenes	1023	1018	Cellulose Nitrate	1.5×10^{17}	10×10^{16}	Soft Leads	20.6	-
Polypropylene	$> 10^{22}$	-	Rubber Phenolics	1017	1012	Low Alloy Steels (cast)	20	15
Polystyrenes, Glass Filled	3.5×10^{22}	-	Melamines, Glass Fiber-Filled	7.0×10^{16}	-	Tantalum Carbide	20	-
Polycarbonate	2.1×10^{22}	-	Diallyl Phthalate	2.5×10^{16}	1014	Carbon Steels	19	14.3
Acrylics, High Impact	2.0×10^{22}	-	Soda-Lime Glasses(2)	4.0×10^{15}	-	Low Alloy Steels (40XX)	19	-
Forsterite	2.0×10^{22}	-	Beryllium Carbide	1.1×10^{16}	-	Thorium	18	-
Polycrystalline Glass	2.0×10^{22}	6.3×10^9	Carbon	4600	3500	Low Alloy Steels (13XX)	17	-
Plastics Laminates, Low Pressure	1022	1017	Graphite	1300	800	Magnesium Alloys	17	5
Polyvinyl Chloride	1022	4.0×10^{17}	Gray Irons	200	50	Carbon Steels (cast)	16	13
Vinylidene Chloride	1022	1020	Titanium and Its Alloys	176	90	Phosphor Bronzes	16	3.6
Aluminum Silicate Glass(2)	$> 10^{21}$	-	Nickel-Base Superalloys	148	118	White Metal	15	-
Borosilicate Glasses(2)	$> 10^{21}$	1018	Heat Resistant Alloys (cast)	112	70	Platinum	14.9	-
Lead Silicate Glasses(2)	$> 10^{21}$	1020	Titanium Carbide	105	-	Free-Cutting Steels	14.3	-
Polyethylenes, Medium and High Density	$> 10^{21}$	-	Cr-Ni-Fe Superalloys(2)	104	91	Columbium	14.2	-
Silica Glasses(2)	$> 10^{21}$	-	Austenitic Nodular Irons	102	-	Tantalum	12.4	-
Epoxies (molded)	9.0×10^{21}	1020	Age Hardenable Stainless Steels	98	75.7	Wrought Irons	11.97	-
Nylon, Glass Filled	5.5×10^{21}	1.5×10^{21}	Cobalt-Base Superalloys	93	23.7	Grade A Tin	11.5	-
Chlorinated Polyether	5.0×10^{21}	-	Stainless Steels (cast)	90	71	Palladium(3)	10.8	-
Acrylics (cast)	1021	-	Low Expansion Nickel Alloys	81	48	Osmium	9.5	-
Cellulose Propionate	1021	1018	Austenitic Stainless Steels	78	69	Admiralty Metal, Ann.	8.9	-
Nylons 6 and 11	1021	1018	Columbium Carbide	74	-	Ruthenium(3)	7.6	-
Standard Electrical Ceramics	1021	1019	Zirconium and Its Alloys	74	40	Tin and Aluminum Brasses	7.5	6.6
Cordierite	$> 10^{20}$	-	Martensitic Stainless Steels	72	40	Leaded Brasses	6.6	4.1
Polyvinyl Butyral	$> 10^{20}$	-	Nodular Irons	68	66	Zinc Alloys (cast)	6.54	6.37
Steatite	$> 10^{20}$	-	Ferritic Stainless Steels	67	60	Yellow Brass, Ann.	6.4	-
Zircon	$> 10^{20}$	-	Nickel and Its Alloys(3)	65.3	8.3	Aluminum and Its Alloys	6.3	2.8
Acrylics, GP	1020	-	Zirconium Carbide	63.4	-	Cartridge Brass, 70%, Ann.	6.2	-
Alkyds	1020	-	Uranium	53	25	Zinc, CR	6.1	-
Epoxies (cast), GP and Ht Res.	1020	1018	Pearlitic Malleable Irons	41.2	38.2	Zinc, HR	6.06	-
Ethyl Cellulose	1020	1018	Cupro-Nickels	37	15	Beryllium Copper	5.82	4.82
Melamines, GP	1020	1018	Standard Malleable Irons	32	-	Tungsten(3)	5.48	-
ABS Resins	$> 8.0 \times 10^{19}$	0.5×10^{19}	Hafnium(3)	33	-	Low Brass, 80%, Ann.	5.4	-
Silicones (molded)	$> 5.0 \times 10^{19}$	$> 3.4 \times 10^{19}$	Low Alloy Steels (43XX, 48XX)	30	-	Iridium	5.3	-
Acetal	$> 4.0 \times 10^{19}$	-	Nitriding Steels	29	27	Molybdenum(3)	5.17	-
Nylons 66 and 610	4.5×10^{19}	-	Tin-Lead-Antimony Alloys	23.7	25.6	Beryllium	5	-
Boron Nitride	1.7×10^{19}	-				Rhodium	4.51	-
Allyls (cast)	$> 10^{19}$	-				Red Brass, 85%, Ann.	4.7	-
Cellulose Acetate	1019	1016				Commercial Bronze, 90%, Ann.	3.9	-
Melamines, Elec.	1019	1017				Gilding, 95%, Ann.	3.1	-
Phenolics, Elec.	1019	6.0×10^{18}				Gold(3)	2.35	-
Phenolics (molded), GP	1019	1015				Copper	2.03	1.71
Polyesters (cast), Rigid	1019	-				Silver	1.59	-
Phenolics (cast), Mech. and Chem.	7.0×10^{18}	1018						

(1) Values represent high and low sides of a range of typical values at room temperature except where noted.

(2) At temperatures between 120 and 212° F.

(3) At 32° F.

SYMBOLS AND NOMENCLATURE

A	=	Surface area of part (cm.^2)
A_c	=	Area upon which F_c acts (inch^2)
a	=	Inside coil radius (inch)
B	=	Magnetic flux density (Gauss)
b	=	Outside coil radius (inch)
C	=	Capacitance (microfarads)
C_v	=	Specific heat per unit volume ($\text{cal./gm., } ^\circ\text{C}$)
C_e	=	Circumferential efficiency (percent)
E_i	=	Joule heating (joules)
E_s	=	Stored energy of capacitor bank (inch pounds)
F_c	=	Force in circumferential direction (pounds)
L_f	=	Final gage length (inch)
L_o	=	Initial gage length (inch)
n	=	Increment number
P_f	=	Pressure available for magnetic forming (pounds/inch^2)
U_m	=	Magnetic field energy (joules)
R	=	Inside tube radius (inch)
R_f	=	Final outside tube radius (inch)
R_o	=	Initial outside tube radius (inch)

- r = Radius where coil stress is desired (inch)
 S = Current penetration depth (cm.)
 S_r = Radial stress (pounds/inch²)
 S_t = Tangential stress (pounds/inch²)
 t_f = Final tube wall thickness (inch)
 V = Charge voltage on capacitor bank (volts)
 V_a = Average velocity attained by tube moving through a radial distance equal to the wall thickness of the tube (cm./sec.)
 V_r = Relative circumferential velocity between two points A and B on the surface of a tube (inch/second)
 V_c = Metal volume of work coil (inch³)
 v = Volume of high field intensity (inch³)
 W_c = Work done on the tube (inch pounds)
 Y_n = Distance of center of increment from R_o (inch)
 Δ = Width of circumferential increment (inch)
 ΔS_c = Change in circumference at each marked increment (inch)
 ΔT = Temperature rise (°C)
 δ = Tube wall thickness (cm.)
 ϵ = Distance traveled (cm.)
 ρ = Mass density of metal (gm./cm.³)
 τ = Half cycle time of current pulse (second)
 τ_a = Time required for movement through displacement ϵ (second)

τ_{di} = Time required to fill inside of tube with magnetic field (second)

τ_{do} = Maximum half-cycle current pulse time for which magnetic field does not penetrate through tube wall (second)

η = Resistivity of material (abohm/cm.)

$\frac{de}{dt}$ = Strain rate (inch/inch/second)

$\frac{du}{dt}$ = Radial or deformation velocity (inch/second)

σ_c = Circumferential stress (pounds/inch²)