MARTIN MARIETTA

**ENVIRONMENTAL
RESTORATION
PROGRAM**

ORNL/ER/Sub/87-99053/32

FEB 8 1992

**Environmental, Safety, and Health Plan
for the Remedial Investigation of the
Liquid Low-Level Waste Tanks at
Oak Ridge National Laboratory,
Oak Ridge, Tennessee**

MANAGED BY
MARTIN MARIETTA ENERGY SYSTEMS, INC.
FOR THE UNITED STATES
DEPARTMENT OF ENERGY

UCN-17560 (6 7-91)

ENERGY SYSTEMS

**Bechtel National, Inc./CH2M Hill/ERCE/PEER
Oak Ridge, Tennessee**

contributed to the preparation of this document and
should not be considered an eligible contractor for its
review.

This report has been reproduced directly from the best available copy.

Available to DOE and DOE contractors from the Office of Scientific and
Technical Information, P.O. Box 62, Oak Ridge, TN 37831; prices
available from 615-576-8401, FTS 626-8401.

Available to the public from the National Technical Information Service,
U.S. Department of Commerce, 5285 Port Royal Rd., Springfield, VA
22161.

ORNL/ER/Sub--87/99053/32

DE92 007775

152

Environmental Restoration Division
ORNL Environmental Restoration Program

**Environmental, Safety, and Health Plan for the Remedial Investigation
of the Liquid Low-Level Waste Tanks at Oak Ridge
National Laboratory, Oak Ridge, Tennessee**

Manuscript Completed--July 1991
Date Issued--September 1991

Prepared by
Bechtel National, Inc./CH2M Hill/ERCE/PEER
Oak Ridge, Tennessee
under subcontract 30B-99053C

Prepared for
U.S. Department of Energy
Office of Environmental Restoration and Waste Management
under budget and reporting code EW 20

OAK RIDGE NATIONAL LABORATORY
Oak Ridge, Tennessee 37831-6285
managed by
MARTIN MARIETTA ENERGY SYSTEMS, INC.
for the
U.S. DEPARTMENT OF ENERGY
under contract DE-AC05-84OR21400

MASTER

REPRODUCTION OF THIS DOCUMENT IS UNLIMITED

CONCURRENCE

Environmental, Safety, and Health Plan
for the Remedial Investigation of the
Liquid Low-Level Waste Tanks at
Oak Ridge National Laboratory,
Oak Ridge, Tennessee
(ORNL/ER/Sub/87-99053/32)

S. DeFalco, Environmental and Health Division
Subcontractor Interface Manager

8/8/91
Date

L. L. Kaiser, Environmental Restoration Division
Inactive LLLW Tanks Project Manager

8/8/91
Date

L. E. May, Environmental Restoration Division
Health and Safety Manager

8/8/91
Date

CONTENTS

TABLES	viii
ACRONYMS	ix
EXECUTIVE SUMMARY	xi
1. INTRODUCTION	1
1.1 DESCRIPTION	1
1.2 PROGRAM PHILOSOPHY	1
1.3 ADHERENCE TO SAFETY REQUIREMENTS	1
1.4 REGULATORY REQUIREMENTS, STANDARDS AND GUIDELINES	2
1.5 ADHERENCE TO QUALITY ASSURANCE PROGRAM	3
1.6 TASK-SPECIFIC ES&H PLANS	3
2. ORGANIZATION, RESPONSIBILITIES, AND AUTHORITIES	4
2.1 ORGANIZATION	4
2.2 RESPONSIBILITIES AND AUTHORITIES	4
2.2.1 Bechtel Corporate ES&H Organization	4
2.2.2 Program Manager	6
2.2.3 Environmental, Safety, and Health Manager	6
2.2.4 Field Health and Safety, Supervisor	6
2.2.5 Health and Safety Specialists	7
2.2.6 Industrial Hygienist	7
2.2.7 Health Physicist	8
2.2.8 Industrial Safety Specialist	8
2.3 INTERFACES WITH ENERGY SYSTEMS SAFETY ORGANIZATION	8
3. HAZARDS EVALUATION	10
3.1 INTRODUCTION	10
3.2 RADIOLOGICAL HAZARDS	10
3.2.1 External Radiation Hazards	10
3.2.2 Internal Radionuclide Exposure	11
3.3 TOXIC AND HAZARDOUS CHEMICAL EXPOSURES	12
3.4 PHYSICAL HAZARDS	12
3.4.1 Fire and Explosions	12
3.4.2 Oxygen Deficiency/Confined Space and Excavations	13
3.4.3 Noise Hazards	14
3.4.4 Other Physical Hazards	14
3.5 SUMMARY	14
4. ENVIRONMENTAL AND READINESS REVIEWS	17
4.1 ENVIRONMENTAL REVIEW AND DOCUMENTATION	17
4.2 READINESS REVIEW	17
5. PROJECT ES&H PROCEDURES	18

6. PERSONAL PROTECTIVE EQUIPMENT	21
6.1 SELECTION OF PERSONAL PROTECTIVE EQUIPMENT	21
6.2 LEVELS OF PERSONAL PROTECTIVE EQUIPMENT	21
6.2.1 Level 1 PPE	21
6.2.2 Level 2 PPE	26
6.2.3 Level 3 PPE	27
6.2.4 Level 4 PPE	27
6.2.5 Level 5 PPE	28
7. RESPIRATORY PROTECTION PROGRAM	29
7.1 REGULATORY REQUIREMENTS	30
7.2 RESPONSIBILITIES AND AUTHORITIES	30
7.3 SELECTION OF RESPIRATORS	30
7.4 TRAINING	30
7.5 FITTING	31
7.5.1 Quantitative Test	31
7.5.2 Field Tests	32
7.6 INSPECTION, CLEANING, MAINTENANCE, AND STORAGE	32
7.6.1 Inspection Procedures	32
7.6.2 Defects Found During Field Inspections	33
7.6.3 Inspection During Cleaning	33
7.6.4 Cleaning and Disinfecting	33
7.7 MEDICAL ASPECTS	33
7.8 PROGRAM EVALUATION	34
7.8.1 Surveillance of the Work Area	34
7.8.2 Evaluation of Effectiveness	34
8. SITE AND CONTAMINATION CONTROL	35
8.1 WORK AREA CONTROL MEASURES	35
8.2 CONTAMINATION CONTROL	35
9. PERSONNEL DECONTAMINATION	38
9.1 INTRODUCTION	38
9.2 FACILITIES	38
9.3 DECONTAMINATION TECHNIQUES	38
9.4 RELEASE LIMITS	39
9.5 EMERGENCY DECONTAMINATION	39
10. EQUIPMENT DECONTAMINATION	40
10.1 RESPONSIBILITIES AND AUTHORITIES	40
10.2 FACILITIES	40
10.3 DECONTAMINATION CLEARANCE LIMITS	40
10.4 DISPOSAL OF CONTAMINATED FLUIDS AND MATERIALS	44
11. PERSONNEL TRAINING	45
11.1 INITIAL TRAINING	45

11.2 TASK SPECIFIC TRAINING	46
11.3 REFRESHER TRAINING	46
11.4 WEEKLY "TOOL-BOX" TRAINING	46
11.5 VISITOR POLICY	46
12. HAZARDOUS WORK PERMITS	48
12.1 CONDITIONS REQUIRING AN HWP	48
12.2 HWP INITIATION	48
12.3 POSTING REQUIREMENTS	49
12.4 CONTAMINATION CONTROL	49
12.5 TERMINATION	49
12.6 RECORD RETENTION	49
13. MEDICAL SURVEILLANCE	50
14. BIOASSAY PROGRAM	51
14.1 BASELINE BIOASSAYS	51
14.2 ROUTINE BIOASSAY PROGRAM	51
14.3 DIAGNOSTIC BIOASSAYS	54
14.4 TERMINATION BIOASSAYS	54
14.5 BNI-ENERGY SYSTEMS INTERFACE	54
15. EXTERNAL RADIATION DOSIMETRY PROGRAM	55
15.1 THERMOLUMINESCENT DOSIMETRY PROGRAM	55
15.2 SELF-READING DOSIMETER PROGRAM	55
15.3 RADIATION DOSE CONTROL PROGRAM	55
16. PERSONNEL AIR MONITORING	57
17. ALARA PROGRAM	58
17.1 POLICY STATEMENT	58
17.2 WORK-PLACE ALARA EFFORTS	59
17.3 ALARA PROGRAM ASSESSMENT	59
18. PERIMETER MONITORING	61
18.1 AIR MONITORING	61
18.2 SURFACE WATER MONITORING	61
18.3 RADIATION EXPOSURE RATE MONITORING	62
19. EMERGENCY ACTION PLAN	63
19.1 GENERAL EMERGENCY ACTION PROCEDURES	63
19.2 SITE IDENTIFICATION	63
19.3 PROCEDURES	63
20. RECORDS	65
20.1 INDIVIDUAL MASTER RECORDS	65

20.2	DOSIMETRY RECORDS	65
20.3	EXTERNAL DOSE ESTIMATES	66
20.4	INTERNAL DOSE ESTIMATES	66
20.5	EXPOSURE TO AIRBORNE CONTAMINANTS	66
20.6	ALARA ACTIVITY RECORDS	67
20.7	SUPPLEMENTAL DATA BASES	67
21.	ANALYTICAL SAMPLE PACKAGING AND SHIPMENT	68
21.1	REGULATORY REQUIREMENTS	68
21.2	RESPONSIBILITIES	68
21.3	SAMPLE SCREENING TECHNIQUES	68
21.4	PACKAGING AND LABELING	69
22.	HAZARD COMMUNICATION PROGRAM	70
22.1	WARNING LABELS	70
22.2	HAZARDOUS MATERIALS LIST	71
22.3	MATERIAL SAFETY DATA SHEETS (MSDS)	71
22.4	HAZARDS OF NON-ROUTINE TASKS	71
22.5	EMPLOYEE INFORMATION AND TRAINING	72
22.6	LOCATIONS OF HAZARDOUS MATERIALS STORAGE	72
22.7	TRAINING	74
22.8	ADDITIONAL EMPLOYEE PROTECTION TRAINING	75
22.9	EMPLOYEE PROTECTION MEASURES	75
23.	CHEMICAL HYGIENE PLAN	76
23.1	SCOPE AND APPLICATION	76
23.2	INITIAL AND PERIODIC MONITORING OF LABORATORIES AND WORKERS	76
23.2.1	Monitoring of Laboratory Spaces	76
23.2.2	Monitoring of Laboratory Workers	77
23.3	TERMINATION OF MONITORING	77
23.4	EMPLOYEE NOTIFICATION OF MONITORING RESULTS	78
23.5	STANDARD OPERATING PROCEDURES	78
23.6	ENGINEERED CONTROLS FOR LIMITING EXPOSURES	80
23.6.1	Fixed Facilities	80
23.6.2	Verification of Engineered Controls Function	80
23.6.3	Verification of Installed Safety Equipment	80
23.7	LABORATORY WORKER INFORMATION AND TRAINING	81
23.7.1	General Training Requirements	80
23.7.2	Job-Specific Chemical Agent and Technique Training	81
23.7.3	Information Available to Workers	81
23.8	MEDICAL SURVEILLANCE	81
23.9	PERSONAL PROTECTIVE EQUIPMENT	81
23.10	INDIVIDUAL RESPONSIBILITIES	82
23.10.1	Program Manager	82
23.10.2	Environmental, Safety, and Health Manager	82

23.10.3	Analytical Services Manager	82
23.10.4	Field Services and Support Manager	82
23.10.5	Close Support Laboratory Supervisor	82
23.10.6	Field Health and Safety Supervisor	82
23.10.7	Laboratory Workers	83

Appendix A	A-1
Appendix B	B-1

TABLES

3.1	Guidelines for assessing chemical, physical, and radiological hazards	15
5.1	ES&H project procedures	19
6.1	Levels of personal protective equipment	25
10.1	Surface radioactivity guides	40
10.2	Recommended maximum contamination guide for items given radiation or contamination clearance	41
10.3	Contamination guides	42
14.1	Job function categories	50
14.2	Guide for routine sampling for those who work with radioactive material	51
15.1	Dose limits	54

ACRONYMS

AE	actual exposure
ALARA	as low as reasonably achievable
ANSI	American National Standards Institute
BNI	Bechtel National, Inc.
CAA	controlled access area
CFR	Code of Federal Regulations
CSL	close support laboratory
DAC	derived air concentration
DCG	derived concentration guide
DOE	Department of Energy
DOT	Department of Transportation
ES&H	Environmental Safety and Health
FHS	field health and safety
FHSS	Field Health and Safety Supervisor
FOF	field operations facility
HSP	Health and Safety Plan
HWP	Hazardous Work Permit
IDLH	immediately dangerous to life or health
IDN	identification number
LSS	Laboratory Shift Supervisor
MSDS	material safety data sheets
MSHA	Mine Safety and Health Administration
NFPA	National Fire Protection Association
NIOSH	National Institute for Occupational Safety and Health
NRC	Nuclear Regulatory Commission
ORNL	Oak Ridge National Laboratory
OSHA	Occupational Safety and Health Administration
PCB	polychlorinated biphenyl
PE	potential exposure
PEL	permissible exposure limit
PF	protection factor
PP	project procedure
PPE	personal protective equipment
QAA	Quality Assurance Assessments
QA/QC	quality assurance/quality control
REL	recommended exposure limit
RI/FS	Remedial Investigation/Feasibility Study
SCBA	self-contained breathing apparatus
SOPs	standard operating procedures
SRDs	self-reading dosimeters
SWSA	solid waste storage area

TLD	thermoluminescent dosimeter
TLV	threshold limit value
WAG	Waste Area Grouping
WBC	whole body counts

07/16/91

X

R01-003

EXECUTIVE SUMMARY

This Environmental, Safety, and Health (ES&H) Plan for the Remedial Investigation of the Low-Level Waste (LLW) Tanks at Oak Ridge National Laboratory (ORNL) outlines the environmental safety and health approach to be used on the ORNL site remedial investigation/feasibility study (RI/FS) pertaining to inactive storage tanks containing chemical and/or radioactive materials. This ES&H Plan may be useful in determining the program elements required to maintain minimal exposures to personnel and the environment during field operations.

The plan discusses the structure of the RI/FS Project ES&H Department personnel including the reporting chain within the ES&H Department and contacts made with Energy Systems. Each job title which has the authority to halt a job is listed.

The hazards evaluation for the tanks is presented in Sect. 3. This section includes the potential hazards (i.e., radiological, chemical, and physical) which are expected to be encountered. Previous sampling results suggest that the primary contaminants of concern will be radiological (cesium-137, strontium-90, hydrogen-3, thorium-232, and plutonium-239). Both external and internal exposures to radioactive materials will be controlled by using both engineering (ventilation, containment, isolation, etc.) and administrative (procedures, training, postings, protective clothing, etc.) controls.

Sections 4 and 5 discuss the environmental readiness reviews and project procedures. These sections present two areas where compliance with Federal or State regulation and Energy Systems recommended guidance are attained. Environmental/readiness reviews are conducted for each Waste Area Grouping (WAG) or major task prior to initiation of work. Project procedures are reviewed to ensure that field operations compliant with federal regulations and/or site recommendations.

Sections 6 and 7 discuss the personal protective equipment (PPE) and respiratory protection requirements under various situations. Each section gives guidance in the selection of clothing and other protective equipment to perform the task in a safe manner.

Several following sections detail site/contamination control, personnel/equipment decontamination, and personnel training requirements. The Hazardous Work Permit (HWP) section describes the most important element of the ES&H program. HWPs are written to control access to the areas where elevated levels of exposure may occur. They present safety requirements for entering controlled access areas (CAAs). These safety requirements ensure exposures to project personnel and the environment are minimal.

The medical surveillance, bioassay, external radiation dosimetry, personnel air monitoring, ALARA, and perimeter monitoring sections give details of how project personnel are monitored. Baseline monitoring by an occupational physician before entering a CAA ensures

that previous personnel exposures are documented. Annual medical examinations thereafter are performed to detect physiological changes in the individual. Bioassay, external radiation dosimetry, personnel air monitoring, ALARA, and perimeter monitoring document personnel and environmental exposures.

The record keeping section describes the documentation that is kept in each individual's personnel file. Records are kept up-to-date and in a retrievable manner.

The final sections discuss the packaging/shipment requirements for samples, the hazard communication program and the chemical hygiene plan in use at the field laboratory.

1. INTRODUCTION

1.1 DESCRIPTION

The Environmental, Safety, and Health (ES&H) Plan presents the concepts and methodologies to be used during the Oak Ridge National Laboratory (ORNL) KI/FS project to protect the health and safety of employees, the public, and the environment. The ES&H Plan acts as a management extension for ORNL and Energy Systems to direct and control implementation of the project ES&H program. The subsections that follow describe the program philosophy, requirements, quality assurance measures, and methods for applying the ES&H program to individual task remedial investigations, project facilities, and other major tasks assigned to the project.

1.2 PROGRAM PHILOSOPHY

Bechtel National, Inc. (BNI) and its subcontractors are committed to limiting exposures to hazardous materials to levels that are as low as reasonably achievable (ALARA). The ORNL RI/FS radiation safety policy also applies ALARA principles to activities at the laboratory. Personnel working on the RI/FS project shall be informed of known and potential hazards associated with the tasks to be performed so that they can effectively apply required safety precautions.

Because of the difficulties associated with quantifying the potential hazards at many of the remedial investigation sites, a conservative approach will be used for protection of employees, members of the general public, and the environment. This conservative application of protective measures and proper training will limit exposures to ALARA levels.

1.3 ADHERENCE TO SAFETY REQUIREMENTS

Maintaining a safe and healthful work environment is the responsibility of all team members. Through a comprehensive training program team members shall be informed of hazard potentials, proper use of personal protective equipment (PPE), applicable procedural requirements, and their responsibilities for maintaining safe working environments. Trained personnel are required to adhere to all safety requirements.

Environmental protection, health, and safety violations will not be tolerated. Personnel who develop a history of safety violations or who blatantly or willfully violate environmental protection, safety, and health procedures will be reprimanded according to RI/FS Project Procedure 1203, "Safety Disciplinary Action System." The ES&H Manager has the authority to permanently remove individuals from the project based on the seriousness of the violation.

1.4 REGULATORY REQUIREMENTS, STANDARDS AND GUIDELINES

The ES&H protection requirements applicable to the ORNL RI/FS are set forth in Department of Energy (DOE) orders, Energy Systems and ORNL procedures, and applicable federal, state, and local regulations and standards. Applicable DOE orders, ORNL implementing documents, and Bechtel Corporate Safety and Health Standards, as most recently revised, include the following:

- DOE Order 1540.1, "Materials Transportation and Traffic Management;"
- DOE Order 3790.1A, "Federal Employees Occupational Safety and Health Program;"
- DOE Order 5000.3A, "Occurrence Reporting and Processing of Operations Information;"
- DOE Order 5480.1B, "Environment, Safety and Health Program for DOE Operations" (Appendix A);
- DOE Order 5480.3, "Safety Requirements for the Packaging and Transportation of Hazardous Materials, Hazardous Substances, and Hazardous Wastes;"
- DOE Order 5480.4, "Environmental Protection, Safety, and Health Protection Standards" (Appendix A);
- DOE Order 5480.10, "Contractor Industrial Hygiene Program;"
- DOE Order 5480.11, "Radiation Protection for Occupational Workers;"
- DOE Order 5481.1B, "Safety Analysis and Review System;"
- DOE Order 5482.1B, "Environmental, Safety and Health Appraisal Program;"
- DOE Order 5483.1A, "Occupational Safety and Health Program for DOE Contractor Employees at Government-Owned Contractor-Operated Facilities;"
- DOE Order 5484.1, "Environmental Protection, Safety, and Health Protection Information Reporting Requirements;"
- DOE Order 5500.1A, "Emergency Management System;"
- ORNL Health Physics Manual;
- ORNL Safety Manual;
- ORNL Industrial Hygiene Manual;
- ORNL Environmental Protection Manual;
- Bechtel Safety Manual; and
- Bechtel Safety and Health Procedures.

As a matter of policy (DOE Order 5480.10), DOE and its contractors have committed to be in compliance with applicable Occupational Safety and Health Administration (OSHA) regulations [specifically, Title 29, Code of Federal Regulations (CFR), Part 1910: *Occupational Safety and Health Standards*]. Concurrently, DOE and its contractors have adopted exposure guidelines listed in relevant American Conference of Governmental Industrial Hygienists Publications [specifically, *TLVs (Threshold Limit Values) for Chemical Substances and Physical Agents in the Workroom Environment with Intended Changes*, most current edition]. Where 29 CFR 1910 is silent for a particular chemical substance or physical agent, the values listed in the following will be used in the order given:

- American Conference of Governmental Industrial Hygienists Threshold Limit Values (TLVs), and

- National Institute of Occupational Safety and Health Recommended Exposure Limits (RELs).

For exposures to radioactive material, the limiting values or derived air concentration (DAC) limits from DOE Order 5480.11 will be applied.

Where more than one limiting value exists, whether it is from regulatory values or recommended values, the most conservative value (DAC, PEL, TLV, or REL) will be applied.

The ES&H Plan meets requirements set forth in 29 CFR 1910.120, "Hazardous Waste Operations and Emergency Response," and applicable regulatory requirements of the State of Tennessee. The packaging and shipment of samples to and from laboratory facilities shall be performed in accordance with federal Department of Transportation (DOT) regulations set forth in Title 49 of the Code of Federal Regulations and with Tennessee DOT regulations (Sect. 17.0). Other regulations applicable to safe operations include National Fire Protection Association (NFPA) codes and federal and local fire codes.

1.5 ADHERENCE TO QUALITY ASSURANCE PROGRAM

The philosophies of the RI/FS project ES&H program, its activities, and the project procedures that implement the programs's requirements comply with and complement the requirements of the project Quality Assurance/Quality Control (QA/QC) Plan. The specific ES&H procedures controlled by the QA/QC Plan are listed therein. Task specific ES&H activities will comply with requirements of task specific QA Project Plans.

1.6 TASK-SPECIFIC ES&H PLANS

Potential physical, radiological, and toxic chemical hazards that may be specific to major tasks shall be addressed in Sect. 3. "Hazards Evaluation" of specific ES&H Plans included as part of that Tasks Remedial Investigation Plan or other major task document plan. These plans shall specify the ES&H requirements necessary to protect the safety of on-site investigators, the public, and the environment (task specific work plans are also written, reviewed and approved to ensure that personnel understand the purpose and scope of the task.)

If similar tasks are scheduled in the future, the ES&H Manager shall be contacted to determine ES&H Plan applicability.

2. ORGANIZATION, RESPONSIBILITIES, AND AUTHORITIES

2.1 ORGANIZATION

The BNI Team ES&H department is an autonomous group within the RI/FS project organization. As shown in Fig. 2.1, the BNI Team ES&H Manager (hereafter written as ES&H Manager) reports to the corporate ES&H organization and works with the Program Manager to implement ES&H requirements and activities on the RI/FS Project. The BNI Team ES&H department supports field operations and directs field safety decisions through the Field Health and Safety Supervisor (FHSS). The FHSS draws upon safety specialists as required to ensure that field operations are conducted in accordance with safety requirements in the form of manuals and procedures under which the FHSS conducts the program in the field.

2.2 RESPONSIBILITIES AND AUTHORITIES

ORNL management is ultimately responsible for environmental protection, safety, and health on the Oak Ridge reservation. This responsibility includes stop work authority. For the RI/FS project, this management responsibility is extended through the Energy Systems ES&H Coordinator to the ES&H Manager.

The ES&H Manager reports directly to the Bechtel corporate ES&H organization and is responsible for compliance with all applicable DOE orders, other federal, state, and local environmental protection, safety, and health protection statutes, permits and regulations, and Energy Systems and ORNL policies and procedures.

Other responsibilities and authorities of the ES&H Manager and other RI/FS managers are described in the following subsections.

2.2.1 Bechtel Corporate ES&H Organization

Responsibility for safety and health programs rests with Bechtel's Safety and Health Services Department. The department operates under the direction of the Safety Services Manager and the Health Services Manager. The Health Services Manager is responsible for all programmatic elements of radiation safety and industrial hygiene. The Safety Services Manager is responsible for all programmatic elements of construction and industrial safety.

The corporate ES&H organization is responsible for making sure that Bechtel projects are conducted in compliance with federal, state, and local laws as well as Bechtel safety and health policies and procedures. These corporate responsibilities and authorities are delegated to project ES&H Managers. The corporate ES&H organization conducts timely audits of project activities and records and distributes audit reports to appropriate Bechtel staff and project management.

07/16/91

ESHTANK2.PLN

Fig. 2.1. ORNL RI/FS organization.

2.2.2 Program Manager

The Program Manager is the senior BNI manager for the ORNL RI/FS project and oversees the technical and programmatic activities of the ES&H program. The Program Manager is responsible for the ES&H program as implemented on the RI/FS project. The Program Manager assigns sufficient resources to maintain and implement the ES&H program. He is responsible for assuring adequate ES&H systems (policy, plans, procedures, materials, etc.) are in place and operational.

2.2.3 Environmental, Safety, and Health Manager

The ES&H Manager is responsible for the preparation, implementation, and maintenance of the project's ES&H program and its supporting elements. The ES&H Manager maintains communications with Energy Systems ES&H organizations and representatives to make sure that ORNL and Energy Systems management directions are incorporated into ES&H activities. Additionally, the ES&H Manager is directly responsible to the Program Manager and the corporate ES&H organization for all technical and regulatory aspects of environmental protection, safety, and health on the RI/FS project.

In performing his responsibilities, the ES&H Manager has autonomy within the project organization, and has the authority to immediately halt any activity that may pose a danger to employees, the public, or the environment. He can also effect operations or designs as necessary to keep radiation exposures, hazardous substances exposures, or environmental releases within established requirements and ALARA.

The ES&H Manager is responsible for developing ES&H plans, including supporting procedures, which are incorporated by reference into the plan for each WAG or task.

2.2.4 Field Health and Safety Supervisor

The FHSS is responsible for implementing the ES&H program in the field. He evaluates environmental protection, safety, and health concerns at the site level and applies the requirements specified in the ES&H Plan and project procedures. In performing his evaluations, the FHSS makes sure that the ES&H Manager is informed of his concerns. The ES&H Manager in turn communicates directly with the ORNL ES&H Coordinator. When conditions exist that are not covered by existing plans and procedures, the FHSS shall halt work and inform the ES&H Manager who will then coordinate proposed solutions with ORNL management through the ORNL ES&H Coordinator. If survey results indicate that personal protective equipment (Sect. 6) requirements may be downgraded in the HWP, the FHSS or ES&H Manager shall contact the ORNL ES&H Coordinator before changing the personal protective equipment needs.

Through discussions with the Field Services and Support Manager, the FHSS also determines the schedule of ES&H support for field activities and deploys available resources to provide required environmental, health, and safety coverage. Full-time safety and health

coverage will be provided for operations for which entry into or establishment of controlled access areas (CAA) is required.

The FHSS has the authority to halt operations that endanger the health and safety of workers, the public, and/or the environment. When site conditions differ from those on which the RI Plan is based, the FHSS will stop field activities and assess the conditions to determine whether work can proceed or whether the site needs to be reevaluated.

The FHSS shall designate a qualified individual to be responsible for site health and safety activities when he/she (FHSS) is off-site.

2.2.5 Health and Safety Specialists

The Health and Safety Specialists report directly to the FHSS. The Health and Safety Specialists include the health physics and industrial safety disciplines. To the extent practical, these technicians shall be experienced in all disciplines, but in no case shall a technician's responsibilities include areas for which the specialists are not trained. Specialists responsible for performing radiation monitoring will be required to demonstrate qualifications by passing the ORNL Health Physics Technicians examination before the beginning site activities. The Health and Safety Specialists are on-site at all times during execution of field activities and are responsible for monitoring field activities to detect and quantify hazardous materials that may be encountered. They also assist personnel in the proper use of PPE, perform release surveys of personnel and equipment, and verify adherence to environmental, health, and safety requirements.

Health and Safety Specialists also have stop work authority. When field conditions develop that are not according to plan, appear unsafe, or may cause environmental insult, the Health and Safety Technicians shall immediately stop operations and inform the FHSS.

2.2.6 Industrial Hygienist

The Industrial Hygienist reports directly to the ES&H Manager and is responsible for developing industrial hygiene-related procedures, overseeing the medical surveillance programs, and maintaining the quality of industrial hygiene-related field measurements and records. The Industrial Hygienist periodically audits RI/FS project field activities to verify compliance with federal regulations, DOE orders, ORNL and Energy Systems policies and procedures and Bechtel policies and procedures. He also conducts training as required for personnel in his disciplines.

The Industrial Hygienist has the authority to halt operations that endanger workers, the public, or the environment.

2.2.7 Health Physicist

The Health Physicist reports directly to the ES&H Manager and is responsible for developing health physics and health physics-related procedures, performing radiation hazards analyses, risk assessments, and radiation exposure assessments, and for maintaining the quality of radiation field measurements and exposure records. The Health Physicist audits RI/FS project field activities to verify compliance with DOE orders, Energy Systems and ORNL policies and procedures and Bechtel policies and procedures. The Health Physicist has the authority to halt operations that endanger the health and safety of workers, the public, or the environment.

2.2.8 Industrial Safety Specialist

The Industrial Safety Specialist reports directly to the ES&H Manager and is responsible for developing safety procedures, performing safety training, maintaining records related to worker illnesses and accidents, and reporting workman's compensation. The Industrial Safety Specialist audits RI/FS project field activities for compliance with federal regulations, DOE orders, Energy System and ORNL policies and procedures, and Bechtel policies and procedures.

The Industrial Safety Specialist has the authority to halt operations that endanger the health and safety of workers, the public, or the environment.

2.3 INTERFACES WITH ENERGY SYSTEMS SAFETY ORGANIZATION

The ORNL ES&H Coordinator is the primary contact between the ES&H Manager and the ORNL Office of Environmental and Health Protection Division, Office of Operational Safety, Environmental Restoration, and Energy Systems Central Staff Office of Environment and Safety Activities. (See the ORNL RI/FS Project Management Plan for other interfaces with the Energy Systems Safety organization.) The ORNL ES&H Coordinator provides the ES&H Manager with information pertaining to appropriate DOE orders, state and federal regulations, Energy Systems and ORNL requirements, and lines of communication. This information is then incorporated into RI/FS plans and procedures as appropriate. The ORNL ES&H Coordinator also provides review and approval of these documents and coordinates the ongoing audit of their implementation.

Through the ORNL ES&H Coordinator, the ORNL Office of Environmental and Health Protection Division will verify that the RI/FS project ES&H program is conducted in accordance with ORNL procedures and policies. ORNL will provide bioassay, external dosimetry in vivo counting, primary radiation detection instrument calibration, and initial health and safety review training for RI/FS project personnel. The records associated with portable radiation detection instrument calibration are retained by the Environmental and Health Protection Division (Bldg. 2007) while records for more "fixed" instruments are kept by the Instrumentation and Controls Division (Bldg. 3026). All RI/FS ES&H equipment

calibration records will be maintained by ORNL, with copies of results provided to the ES&H Manager on a routine and timely basis.

Each task specific ES&H Plan shall include an organizational structure for the task, including any direct interface with ORNL personnel.

3. HAZARDS EVALUATION

Potential physical, radiological, and chemical hazards that may be encountered as part of the LLLW Tanks operations are addressed in this plan. This plan outlines the ES&H requirements necessary to protect the safety of on-site investigators, the public and the environment while performing functions associated with the LLLW Tanks. The following is based upon available information applicable to the LLLW tanks. Additional information gathered as part of initial survey operations will be obtained prior to each task. The combined available information will be used to specify the protective requirements and work limitations applicable to each individual task. These protective measures will be specified and documented in individual Hazardous Work Permits [HWPs (See Sect. 12)] controlling LLLW tanks-related tasks.

A listing of tanks and tank locations to which this plan is applicable and additional task which may be covered under this ES&H Plan is contained in Appendix A to this plan.

3.1 INTRODUCTION

The RI for LLLW Tanks includes investigations that are to be conducted at the ground surface (e.g., general area inspections, radiation walkover surveys, video inspections, leak test equipment installation and monitoring, grab samples and tank gas sampling and analysis) and a series of excavations that require ground penetration (e.g., soil samples, excavating and tank riser installation). Although the hazards may vary somewhat at the various tanks, the ES&H practices and procedures will be consistent. Because of the potential for encountering radioactive materials or chemicals during tank investigations (e.g., video inspection, leak testing and grab sampling), constant monitoring will be carried out by health and safety specialists. All field work concerned with LLLW Tanks will be controlled through the use of HWPs.

3.2 RADIOLOGICAL HAZARDS

3.2.1 External Radiation Hazards

The points of access (risers, gages, manways, etc.) to many of the LLLW Tanks are located within known radiation areas. Within these areas, external dose rates greater than 0.025 mSv/h (2.5 mR/h) may be expected. Locally higher dose rates are expected to exist in many areas associated with tank components.

Some LLLW Tank operations will involve direct access to tank structures where high radiation areas can be anticipated based on sampling data available on current tank radionuclide inventories as well as any data becoming available over the duration of these tasks.

Each activity associated with LLLW Tanks work will be planned according to Project Procedure (PP) 1132, "Preparation of Project Field Work Guides." ALARA evaluation and planning will be conducted to assess the degree of potential external exposure and methods by which these exposures may be maintained as low as reasonably achievable (ALARA) and within applicable guidelines and administrative limits. Administrative external radiation exposure limits are established as part of the planning process and will become part of the controlling instruction guide.

Each field activity associated with the LLLW Tanks will be controlled by an HWP. ALARA goals established in planning will become part of the controlling limitations stated in each HWP for these tasks.

Prior to each field LLLW task the ES&H Department will conduct radiation surveys to establish initial conditions and protective levels for workers. LLLW Tanks work will be monitored continuously by qualified ES&H Specialists with appropriate and calibrated dose rate instrumentation. Individuals conducting LLLW Tanks work will be individually equipped with calibrated alarming/recording self-reading dosimeters with alarm points established so that ALARA goals and administrative limits are not exceeded.

3.2.2 Internal Radionuclide Exposure

Some LLLW Tank operations will involve direct access to tank internals or potential exposure of individuals to the internal contents of the tanks. Based on sampling data available on current tank radionuclide contents, the potential exists for the uptake by workers of a variety of radionuclides. Exposure to these radionuclides potentially could result through the oral, skin or respiratory routes.

Each field activity associated with LLLW Tanks work will be planned according to PP 1132, "Preparation of Project Field Work Guides" and controlled by an HWP. ALARA evaluation and planning will be conducted for the tanks in order to assess the degree of potential contamination and/or the potential for airborne radioactivity generation and methods by which these exposures may be maintained ALARA and within applicable guidelines and administrative limits. Combined external and internal radiation exposure administrative limits are established by project procedure. Individual work task ALARA goals and uptake mitigation methods will be established as part of the planning process and will become part of the controlling instruction guide.

Prior to each field task, the ES&H Department will conduct radiation surveys to establish initial conditions and protective levels for workers. Liquid low-level waste tanks work will be monitored continuously by qualified ES&H Specialists, with appropriate and calibrated air monitoring and/or sampling devices in order to assess airborne radioactivity conditions. Individuals conducting LLLW Tanks work will be participants in the project's in-vivo bioassay program. Bioassay will be conducted according to guidance provided in PP 1280.3, "Internal Dosimetry." Personnel air monitoring will be used to assess internal exposure potentials where airborne radioactivity is probable.

07/16/91

ESHTANK2.PLN

3.3 TOXIC AND HAZARDOUS CHEMICAL EXPOSURES

Some LLLW Tank operations will involve direct access to tank internals or potential exposure of individuals to the internal contents of the tanks. Based on sampling data available on current tank chemical and toxic chemical contents, the potential exists for the uptake by workers of a variety of toxic metals and exposure to hazardous organic compounds. Exposure to these materials could result through the oral, skin or respiratory routes. ORNL publication "Sampling and Analysis of the Inactive Waste Storage Tank contents at ORNL; ORNL/ER-13" contains the available tank contents data for the tanks to which this plan is applicable. These data will be used for planning purposes as well as any additional data becoming available for potential other tanks covered under this ES&H Plan over the duration of these tasks.

Each field activity associated with LLLW Tanks work will be planned according to PP 1132, "Preparation of Project Field Work Guides" and controlled by an HWP. ALARA evaluation and planning will be conducted for the tanks to assess the degree of potential contamination and/or the potential for respiratory exposure to volatile compounds and methods by which these exposures may be maintained within ALARA and permissible exposure limits or other applicable guidelines and administrative limits. Exposure limits are established by project procedure to the most limiting value available [permissible exposure limits (PELs) recommended exposure limit (REL), ACGIH, short-term exposure limit (STEL) threshold limit value time-weighted average (TLV), etc.]. Individual work task ALARA goals and uptake mitigation methods will be established as part of the planning process and will become part of the controlling instruction guide.

Prior to each field task, the ES&H Department will conduct chemical and hazardous materials surveys, including ambient air monitoring or sampling of environmental media in order to establish initial conditions and protective levels for workers. LLLW Tanks work will be monitored continuously by qualified ES&H Specialists with appropriate and calibrated chemical detection instrumentation. Individuals conducting LLLW Tanks work will be equipped with appropriate detection devices and/or air sampling devices to assess exposure potentials where conditions indicate.

3.4 PHYSICAL HAZARDS

3.4.1 Fire and Explosions

The potential for fire or explosion may exist at LLLW Tank work sites as the result of:

- explosive atmospheres in tanks from organic chemicals or gases stored or contained in tank residues,
- explosive atmospheres in tanks as the result of the decay of organics forming methane or hydrogen,

07/16/91

ESHTANK2.PLN

- use or transfer of fuels powering equipment, and
- welding or burning (see safety requirement in 29 CFR 1926.352).

Each activity associated with LLLW Tanks work will be planned according to PP 1132, "Preparation of Project Field Work Guides." Fire and explosion potential evaluation and planning will be conducted to assess the potential of fire or explosion and methods by which these potentials may be minimized or eliminated. Individual work task fire and/or explosion prevention methods will be established as part of the planning process and will become part of the controlling instruction guide.

Each field activity associated with the LLLW Tanks work will be controlled by an HWP. Fire and explosion prevention planning will become part of the controlling limitations stated in each HWP for these tasks.

When accessing tanks, initial and continuous monitoring for explosive atmospheres will be conducted by a qualified ES&H Specialist with appropriate and calibrated explosive and flammable atmosphere detection instrumentation. Fuels and other flammables will be handled according to OSHA requirements and National Fire Protection Association (NFPA) guidelines.

3.4.2 Oxygen Deficiency/Confined Space and Excavations

The access to some LLLW Tanks may require the entry of workers into confined spaces or excavation in order to accomplish required work. Such operations will expose workers to confined space hazards or the hazards associated with work in excavations.

Some LLLW Tank operations will involve direct access to tank internals or potential exposure of individuals to the internal contents of the tanks. Oxygen deficient atmospheres may result from oxygen displacement or consumption by tank content gases. Excavations represent both confined space hazards such as oxygen deficiency as well as the hazard of cave-in.

Each activity associated with LLLW Tanks work will be planned according to PP 1132, "Preparation of Project Field Work Guides." Where confined space entry or excavation is determined necessary to accomplish mission goals, evaluation and planning will be conducted to assess the degree of hazard to workers. Individual work task safety methods (ventilation, shoring, rescue devices, etc.) will be established as part of the planning process and will become part of the controlling instruction guide. In cases of potential confined space and/or excavation, hazard work shall be planned, conducted, controlled, and monitored according to 29 CFR 1926 Subpart P (.650-652), 29 CFR 1926.21, 29 CFR 1910.120 and applicable project procedures.

Each field activity associated with the LLLW Tanks work will be controlled by an HWP. Safety methods established in planning will become part of the controlling limitations stated in each HWP for these tasks.

Prior to each field task the ES&H Department will conduct necessary monitoring to establish initial conditions and protective levels for workers. LLLW Tanks work will be monitored continuously by qualified ES&H Specialists.

3.4.3 Noise Hazards

Long-term exposure to excessive noise from equipment operation in excess of 85db(a) has been determined to cause hearing impairment. Therefore, noise levels will be routinely evaluated and those operations with sound levels in excess of 85 db(a) shall require hearing protection. Additional hearing protection will be provided or equipment modifications implemented, as appropriate, to maintain acceptable noise levels. Noise monitoring, control, and hearing conservation procedures outlined in PP 1270, "Industrial Hygiene Practices," will be followed to control noise hazards.

3.4.4 Other Physical Hazards

Exposure to heat or cold can cause severe stress and possibly death. The procedures outlined in PP 1270 will be followed to control heat and cold stress hazards.

Improper operation of equipment or equipment malfunctions may result in injury and physical damage. Engineering controls, periodic inspections, and strict adherence to safe practices will be used to minimize the potential for injury and impairment.

3.5 SUMMARY

Once the presence and concentrations of specific chemicals or radiological materials are established, the resulting hazards shall be reassessed, as necessary, to reevaluate the hazards classification. This is accomplished by reference to standards and guidelines. Key guidelines are listed in Table 3.1.

Table 3.1. Guidelines for assessing chemical, physical, and radiological hazards

Source	Guidelines	Explanation	Sources for values ^a
Inhalation of airborne contaminants	Threshold Limit Value	One of three categories of chemical exposure levels, defined as follows:	
	Threshold Limit Value-Time-Weighted Average	The time-weighted average concentration for a normal 8-hour workday and a 40-hour work week, to which nearly all workers may be repeatedly exposed without adverse effect. Should be used as an exposure guide rather than absolute threshold.	ACGIH
	Threshold Limit Value-Short-Term Exposure Limit	A 15-minute time-weighted average exposure that should not be exceeded at any time during the work day.	ACGIH
	Threshold Limit Value-Ceiling	The concentration that should not be exceeded even instantaneously.	ACGIH
	Permissible Exposure Limit	Time-weighted average and ceiling concentrations similar to (and in many cases derived from) the threshold limit values published in 1968.	OSHA
Dermal absorption of chemicals through airborne or direct contact	Recommended Exposure Limit	Time-weighted averages and ceiling concentrations based on NIOSH evaluations.	NIOSH
	Immediately Dangerous to Life or Health	The maximum level from which a worker could escape within 30 minutes without any escape-impairing symptoms or any irreversible health effects.	NIOSH
	Designation "Skin"	The designation "skin" in the ACGIH, OSHA, and NIOSH references indicates that a substance may be readily absorbed through the intact skin; however, it is not a threshold for safe exposure. Direct exposure should be avoided. Biological monitoring should be considered to determine the relative contribution of dermal exposure to the total dose.	ACGIH/OSHA/NIOSH
		Many substances irritate the skin. Consult standard references.	
Dermal irritation		Some carcinogens have an assigned TLV.	ACGIH
	Threshold Limit Value	OSHA has individual standards for some specific carcinogens.	OSHA
	Permissible Exposure	NIOSH makes recommendations regarding exposures to carcinogens.	NIOSH
Carcinogens	Recommended Exposure Limit		

Table 3.1. (continued)

Source	Guideline	Explanation	Sources for values ^a
Noise	Threshold Limit Value	Sound pressure levels and durations of exposure that represent conditions to which it is believed that nearly all workers may be repeatedly exposed without an adverse effect on their ability to hear and understand normal speech.	ACGIH
Ionizing Radiation	Permissible Exposure Limit	Limits for acceptable noise exposure.	OSHA
	Recommended Exposure Limit	Limits for acceptable noise exposure.	NIOSH
	Derived Air Concentration	Derived Air Concentration (DAC) is the concentration of any given DOE radionuclide in air, which, if inhaled continuously during a working year (2000 hours), would irradiate a person to the annual dose equivalent limit.	DOE
Explosion	Derived Concentration Guide	Derived Concentration Guide (DCG) is the concentration of any given radionuclide in water or air, which, if ingested at reference man values would result in an effective dose equivalent of 1mSv (100m rem). The DCGs are generally applied to environmental exposures.	DOE
	Annual Limiting Values for Occupational Workers	Annual dose equivalent limit for occupational exposures.	DOE
	Lower Explosive Limit	The minimum concentration of vapor in air below which propagation of a flame will not occur in the presence of an ignition source.	NFPA
Fire	Upper Explosive Limit	The maximum concentration of a vapor in air above which propagation of a flame will not occur in the presence of an ignition source.	NFPA
	Flash Point	The lowest temperature at which the vapor of a combustible liquid can be made to ignite momentarily in air.	NFPA

^a Sources:

ACGIH. 1990-1991. Threshold Limit Values for Chemical Substances and Physical Agents in the Workplace Environment and Biological Exposure Indices. American Conference of Governmental Industrial Hygienists, Cincinnati, Ohio.

DOE Order 5400.5. 1990. "Radiation Protection of the Public and the Environment".

DOE Order 5480.11. 1988. "Radiation Protection for Occupational Workers".

NIOSH. Centers for Disease Control. NIOSH Recommendations for Occupational Health Standards. Morbidity and Mortality Weekly Report Supplement.

NIOSH. 1990 Pocket Guide to Chemical Hazards. National Institute for Occupational Safety and Health, Cincinnati, Ohio.

NFPA. 1990 Fire Protection Guide on Hazardous Materials. National Fire Protection Association, Boston, Massachusetts.

OSHA. 29 CFR Part 1910. (OSHA standards are legally binding.)

The most current standards and guidelines will be used in the above references.

07/16/91

R01-003

4. ENVIRONMENTAL AND READINESS REVIEWS

Both an environmental review and a readiness review will be conducted for each major task prior to initiation of field activities. These reviews are required to make sure that remedial investigation field activities are conducted safely, in accordance with ALARA principles, and are cost-effective. Programmatic requirements for each type of review are summarized in the following subsections.

4.1 ENVIRONMENTAL REVIEW AND DOCUMENTATION

The purpose of the environmental review is to promote compliance with all applicable environmental permits, rules, regulations and statutes; promote environmental protection by implementation of ORNL's ALARA policy; and maintain the quality of the environment throughout all activities, operations, and projects carried out at ORNL.

The RI/FS project is subject to the ORNL Environmental Review and Documentation Program requirements, and the appropriate environmental review will be conducted by Energy Systems.

4.2 READINESS REVIEW

The purpose of the readiness review is to ensure that a given activity is ready to proceed to the next increment of work by identifying and minimizing the risks associated with mission success. It will promote compliance with all applicable ORNL, Energy Systems, DOE, federal, state and local regulations, orders, procedures and guidelines. Other Task Specific documents will be included in the readiness review to assure that all possible avenues for personal and/or environmental exposures have been accounted for (i.e., Site Characterization Summary, Task Specific Remedial Investigation Implementation Plan, comprehensive work plans, and Task Specific Safety and Health Plans. The readiness review encompasses all operational divisions including health and safety).

The RI/FS project is subject to the ORNL Readiness Review and Documentation Program. Readiness review will be conducted by Energy Systems.

5. PROJECT ES&H PROCEDURES

RI/FS ES&H activities will be conducted in accordance with project procedures, which will be reviewed by Energy Systems prior to implementation. These project procedures are maintained by the ES&H Manager, the FHSS, and the Field Services and Support Manager. Where appropriate, manufacturers' instructions for equipment operation, calibration and maintenance will be used in lieu of specific procedures.

Each project procedure will be reviewed internally by Bechtel at least annually for continuing applicability and adequacy. The review will include an evaluation for compliance with applicable ES&H regulations, standards, guidelines, and Bechtel policy and procedures. Procedures which require changes to be compliant with Federal or site requirements will be revised, subsequently reviewed by Energy Systems, and reissued. A list of applicable project procedures is included in Table 5.1.

Programmatic assessments of the various ES&H programs will be performed at least quarterly to ensure proper use of the procedure.

Table 5.1 ES&H project procedures

Project procedure number	Procedure title
1201	Environmental Safety and Health Management Oversight Program
1202	Site Access Requirements
1205	Medical Surveillance
1210	ES&H Training
1220	Initial Site Survey
1225	Task Hazard Analysis
1230	Personal Protective Equipment
1235	Hazardous Work Permits
1240	Emergency Response
1245	Personnel Decontamination
1250	Equipment Decontamination and Release for Unrestricted Use
1255	Work Area and Environmental Monitoring
1260	Shipment of Hazardous Material
1260.1	Determination of Hazardous Materials Classification
1260.2	Packaging of Hazardous Materials for Shipment
1260.3	Transport Vehicle Requirements
1260.4	Transport Vehicle Operator Requirements
1260.5	Transportation Safety Requirements
1260.6	Survey, Inspection, and Marking of Transport Vehicles
1260.9	Shipping Papers
1265	ES&H Recordkeeping
1270	Industrial Hygiene Practices

Table 5.1 (continued)

Project procedure number	Procedure title
1270.1	Air Surveillance of Chemical and Radiological Contaminants
1275	Industrial Safety Practices
1275.1	Electrical Equipment and Systems
1275.2	Tagging and Lockout
1275.3	Excavations and Trenches
1275.4	Ladders
1275.5	Scaffolds
1275.6	Cranes, Heavy Equipment, and Vehicles
1275.7	Welding and Cutting
1275.8	Work in Confined or Enclosed Spaces
1275.9	Housekeeping and Sanitation
1275.10	Hand and Portable Power Tools
1275.11	Fire Prevention and Protection
1275.12	OSHA/BNI Recordkeeping
1280	Health Physics Practices
1280.1	Methodology for Performing Radiological Contamination Surveys
1280.2	Dosimetry Services
1280.3	External Radiation Dosimetry
1280.4	Internal Radiation Dosimetry
1280.5	Radiological Dose Rate Measurements
1280.6	Use of Self-Reading Dosimeters
1280.7	Posting and Labeling
1280.8	Control Point Monitoring
1280.9	Radiation Source Control

6. PERSONAL PROTECTIVE EQUIPMENT

6.1 SELECTION OF PERSONAL PROTECTIVE EQUIPMENT

Personal protective equipment (PPE) for a particular job will be selected by the FHSS or ES&H Manager based on an evaluation of the hazards anticipated or previously detected at a work site. The equipment selected will provide protection from chemical and/or radiological materials contamination known or suspected to be present, and that exhibit any potential for worker exposure. Respiratory protection (discussed in Sect. 7) may be required.

Requirements for PPE will be specified on a hazardous work permit (HWP) based on a preliminary evaluation, on-site survey for any level of PPE protection, as defined below. When conditions exist that are not covered by existing plans and procedures, the FHSS shall halt work and inform the ES&H Manager who will then coordinate proposed solutions with ORNL management through the ORNL ES&H Coordinator. This may include changing PPE requirements in the HWP. Note that numerical designations of levels of PPE are reversed from OSHA designations to more closely correspond to Energy Systems designations.

6.2 LEVELS OF PERSONAL PROTECTIVE EQUIPMENT

The levels of PPE shown in Table 6.1 will be used as a starting point for ensemble creation; however, each ensemble will be tailored to the specific situation to provide the appropriate level of protection. The following subsections describe guidelines for selection of appropriate PPE.

6.2.1 Level 1 PPE

Level 1 PPE will be used when the hazard analysis indicates that field investigations will be conducted in areas known or thought to be free of significant contamination. Use of Level 1 PPE may continue if field measurements and/or monitoring data confirm the following conditions:

- Airborne contaminants are less than 10% of the applicable limiting value [DAC, PEL, TLV, REL].
- The direct radiation dose rate is less than 25 $\mu\text{Gy/h}$ (2.5 mrad/h).
- Radioactive materials contamination is maintained at levels less than 0.3 Bq/100 cm^2 (20 dpm/100 cm^2) for removable alpha contamination; 5 Bq/100 cm^2 (300 dpm/100 cm^2) for fixed alpha contamination; 3.3 Bq/100 cm^2 (200 dpm/100 cm^2) for removable beta-gamma contamination [except for iodine-125, iodine-129 and actinium-227, for which the guide

Table 6.1 Levels of personal protective equipment

Level	Equipment description
1	<p><u>Required</u></p> <ul style="list-style-type: none"> - Nonregulated cloth work uniform - Steel-toe and steel-shank work boots - Safety glasses - Hard hat - Disposable gloves ^a - Whole-body TLD badge <p><u>Optional, As Required</u></p> <ul style="list-style-type: none"> - Work gloves ^a - Personal flotation device - Ear plugs/muffs - Two-way radio - Sweat bands - Flashlight or lantern
2	<p><u>Required</u></p> <ul style="list-style-type: none"> - Tyvek® coveralls with openings taped closed - Regulated area cloth work uniform - Chemical-resistant outer gloves ^a taped to Tyvek® coveralls - Chemical-resistant inner gloves ^a taped to cloth coveralls - Steel-toe and steel-shank work boots - Neoprene boots, or chemical-resistant boot covers^a taped to Tyvek® coveralls - Hard hat - Safety glasses - Whole-body TLD badge <p><u>Optional, As Required</u></p> <ul style="list-style-type: none"> - 0 to 200 mR pocket dosimeter ($0.025 \leq \text{mGy/h} < 1.0$)^b (or electronic equivalent) - 0 to 200 mR plus 0 to 1 R pocket dosimeter ($\geq 1.0 \text{ mGy/h}$)^b (or electronic equivalent) - Extremity dosimeters ($> 0.035 \text{ mGy/h}$)^b - Personal flotation device - Ear plugs/muffs - Two-way radio - Flashlight or lantern

Note: Areas/operations requiring Level 2 PPE shall have restricted access. Each such area shall be barricaded so that dose rates and airborne exposure levels are $< 0.025 \text{ mGy/h}$ and < 0.1 derived air concentration (DAC/PEL/TLV/REL) guide, respectively, at its boundary.

Table 6.1 (continued)

Level	Equipment description
3	<p><u>Required, Inner-Set</u></p> <ul style="list-style-type: none"> - Regulated cloth work uniform with openings taped closed - Steel-toe and steel-shank work boots - Chemical-resistant shoe covers^a taped to cloth coveralls - Chemical-resistant gloves^a taped to cloth coveralls <p><u>Required, Outer-Set</u></p> <ul style="list-style-type: none"> - Full-facepiece, air-purifying, canister-equipped respirator^c - Chemical-resistant coveralls or chemical splash suit^a with openings taped closed - Chemical-resistant hood^a taped to coveralls - Chemical-resistant gloves^a taped to chemical resistant coveralls or chemical splash suit - Neoprene boots, or chemical-resistant boot covers^a taped to coveralls - Hard hat - Whole-body TLD badge - Personal air sampler - Two-way radio <p><u>Optional, As Required</u></p> <ul style="list-style-type: none"> - 0 to 200 mR pocket dosimeter ($0.025 < \text{mGy/h} < 1.0$)^b (or electronic equivalent) - 0 to 200 mR plus 0 to 1 R pocket dosimeter ($> 1.0 \text{ mGy/h}$)^b (or electronic equivalent) - Extremity dosimeter ($> 0.035 \text{ mGy/h}$)^b - Personal flotation devices - Ear plugs/muffs - Sweat bands - Flashlight or lantern <p>Note: Areas/operations requiring Level 3 PPE shall have controlled access. Each such area shall be constructed with a two barricade system comprised of an inner "hot line," and an outer "contamination control" line. Construction and operation of a Level 3 PPE controlled access area shall ensure the environmental dose rates and airborne exposure levels are $< 0.025 \text{ mGy/h}$ and $< 0.1 \text{ DAC/PEL/TLV/REL}$, respectively.</p>
4	<p><u>Required, Inner-Set</u></p> <ul style="list-style-type: none"> - Modesty garments - Tyvek® [chemical-resistant^a as appropriate] coveralls with openings taped closed - Chemical-resistant gloves^a taped to coveralls - Steel-toe and steel-shank work boots - Chemical-resistant shoe covers^a taped to coveralls

Table 6.1 (Continued)

Level	Equipment description
	<p><u>Required, Outer-Set</u></p> <ul style="list-style-type: none"> - Pressure-demand, full-facepiece self-contained breathing apparatus (SCBA), or pressure-demand supplied-air respirator with escape SCBA provisions^c - Chemical-resistant coveralls^a or chemical-resistant splash suit^a with openings taped closed - Chemical-resistant hood^a taped to coveralls - Hard hat - Neoprene boots, or chemical-resistant boot covers^a taped to coveralls - Chemical-resistant gloves^a taped to coveralls - Whole-body TLD badge - Personal air sampler - Two-way radio <p><u>Optional, As Required</u></p> <ul style="list-style-type: none"> - 0 to 200 mR pocket dosimeter ($0.025 < \text{mGy/h} < 1.0$)^b (or electronic equivalent) - - 0 to 200 mR plus 0 to 1 R pocket dosimeter ($> 1.0 \text{ mGy/h}$)^b (or electronic equivalent) - Extremity dosimeters ($> 0.035 \text{ mGy/h}$)^b - Personal flotation device - Ear plugs/muffs - Sweat bands - Flashlight or lantern - Cooling garment <p>NOTE: The same controlled access restrictions that apply to Level 3 PPE areas also apply to Level 4 PPE areas/operations.</p>
5	<p><u>Required, Inner-Set</u></p> <ul style="list-style-type: none"> - Modesty garments - Chemical-resistant Tyvek[®] coveralls^a with openings taped closed - Steel-toe and steel-shank work boots - Chemical-resistant shoe covers^a taped to coveralls - Chemical-resistant gloves^a taped to coveralls - Two-way radio - Cooling garment <p><u>Required, Outer-Set</u></p> <ul style="list-style-type: none"> - Airline, continuous flow, full-facepiece or hood respirator with SCBA escape provisions^c, or pressure-demand, full-facepiece SCBA, or pressure-demand supplied-air respirator with escape SCBA provisions, as appropriate. - Full-encapsulating chemical-resistant suit^a with openings taped closed

Table 6.1 (Continued)

Level	Equipment description
	<ul style="list-style-type: none"> - Chemical-resistant boot covers - Personal air sampler - Whole-body TLD badge - Knife
	<u>Optional, As Required</u>
	<ul style="list-style-type: none"> - 0 to 200 mR pocket dosimeter ($0.025 < \text{mGy/h} < 1.0$)^b (or electronic equivalent) - 0 to 200 mR plus 0 to 1 R pocket dosimeter ($> 1.0 \text{ mGy/h}$)^b (or electronic equivalent) - Extremity dosimeters ($> 0.035 \text{ mGy/h}$)^b - Flashlight or lantern - Hard hat

NOTE: If Level 5 PPE work is anticipated, reasonable efforts shall be made to use engineering controls that will mitigate the hazard(s) to Level 4 PPE, or less, requirements. If such engineering controls are not feasible, a risk assessment shall be performed prior to initiating work. The risk assessment shall demonstrate that environmental dose rates and airborne exposure levels can be controlled to $< 0.025 \text{ mGy/h}$ and $< 0.1 \text{ DAC/PEL/TLV/REL}$, respectively.

^aClean or new chemical-resistant gloves should always be used when handling samples. The most appropriate chemical-protective clothing shall be chosen by the FHSS or industrial hygienist based on historical information and/or field measurements. Where data are inadequate conservative assumptions shall be used to ensure that clothing resists permeation, degradation, and penetration of chemicals.

^bRadiation dosimetry shall be issued in direct relation to field measured dose rates, as indicated. If field conditions change from those shown on the HWP, that HWP shall be terminated, PPE requirements shall be reevaluated, and a new HWP initiated.

^cThe decision to use respiratory protection for airborne concentrations in excess of the appropriate derived air concentration (DAC) and/or TLV may be based on field evaluations with a field radiation detector, Photovac-TIP, or equivalent instrument for hazardous chemical organic vapors; decisions must always be confirmed with laboratory analyses.

is 0.3 Bq/100 cm² (20dpm/100cm²); and 0.5 μGy/h (0.05 mrad/h) for fixed beta-gamma contamination.

- There are no detectable skin irritants present.

6.2.2 Level 2 PPE

Level 2 PPE will be used initially when the hazards analysis indicates that hazardous materials are present, but in quantities that do not present a potential for significant exposures to airborne and/or skin contaminants. Continued use of Level 2 PPE will be based on field measurements and/or monitoring data that confirm the following conditions:

- Airborne contaminants are greater than or equal to 10% , but less than 50%, of the applicable limiting value. If more than one contaminant is identified, the unity rule* shall be used to assign the appropriate limiting value.
- The direct radiation dose rate is greater than or equal to 25 μGy/h (2.5 mrad/h), thus requiring the use of pocket dosimeters. Elevated dose rates and contamination levels may not always be coincidental. Therefore, it may be necessary to evaluate dose rate PPE requirements as a separate issue (see Footnote b, Table 6.1).
- Radioactive materials contamination is maintained at levels less than 8.3 Bq/100 cm² (500 dpm/100 cm²) for removable alpha contamination; 41.7 Bq/100 cm² (2,500 dpm/100 cm²) for removable beta-gamma contamination (except for iodine-125, iodine-129, and actinium-227; for which the guide is 8.3 Bq/100 cm²); and 2,100 Bq/100 cm² (125,000 dpm/100 cm²) for fixed beta-gamma contamination [except for iodine-125, iodine-129 and actinium-227, for which the guide is 41.7 Bq/100 cm² (2,500 dpm/100cm²)].
- PPE for protection against skin irritants may be highly specific to the chemical constituents(s) comprising the irritant. Accordingly, choice of chemical-resistant PPE materials will be guided by knowledge of the chemical substances encountered (see Footnote a, Table 6.1).

*The unity rule:
$$\frac{C_1}{T_1} + \frac{C_2}{T_2} + \dots + \frac{C_n}{T_n} < 1$$

where C_n = atmospheric concentration of contaminant n,
 T_n = TLV, PEL, REL, or DAC of contaminant n.

6.2.3 Level 3 PPE

Level 3 PPE will be used initially when the hazards analysis indicates a potential for direct contact with hazardous contaminants that will not adversely affect exposed skin. Continued use of Level 3 PPE will be based on continuous field measurements and/or monitoring data that confirm the following conditions:

- Concentrations of individual airborne contaminants are less than 50 times the applicable limiting value. If more than one contaminant is identified, the unity rule* shall be used to assign the appropriate limiting value.
- The direct radiation dose rate is greater than or equal to 25 $\mu\text{Gy/h}$ (2.5 mrad/h), thus requiring the use of pocket dosimeters. Elevated dose rates and contamination levels may not always be coincidental. Therefore, it may be necessary to evaluate dose rate PPE requirements as a separate issue (see Footnote b, Table 6.1).
- Radioactive materials contamination is maintained at levels less than 417 Bq/100 cm^2 (25,000 dpm/100 cm^2) for removable alpha contamination; 2,100 Bq/100 cm^2 (125,000 dpm/100 cm^2) for fixed alpha contamination; 21,000 Bq/100 cm^2 ($1.25\text{E}+06$ dpm/100 cm^2) for removable beta-gamma contamination [except for iodine-125, iodine-129, and actinium-227, for which the guide is 417 Bq/100 cm^2 (25,000 dpm/100 cm^2)]; and $1.042\text{E}+05$ Bq/100 cm^2 ($6.25\text{E}+06$ dpm/100 cm^2) for fixed beta-gamma contamination [(except iodine-125, iodine-129, and actinium-227, for which the guide is 2,100 Bq/100 cm^2)].
- PPE for protection against skin irritants may be highly specific to the chemical constituents(s) comprising the irritant. Accordingly, choice of chemical resistant PPE materials shall be guided by knowledge of the chemical substances encountered (see Footnote a, Table 6.1).

6.2.4 Level 4 PPE

Level 4 PPE represents the same level of skin contaminant protection as Level 3 PPE. Level 4 PPE, however, will be used for immediately dangerous to life or health (IDLH) concentrations of specific substances that do not represent a severe skin hazard; for atmospheres containing less than 19.5% oxygen; for concentrations in excess of the protection factors for air-purifying respirators; or in the presence of incompletely identified vapors or gases as indicated by direct-reading organic vapor detection equipment. Use of Level 4 PPE will be based on continuous field measurement and/or monitoring that confirms the following conditions:

- Concentrations of individual airborne contaminants are less than 100 times the applicable limiting value. If more than one contaminant is identified, the unity rule* shall be used to assign the appropriate limiting value.

- The direct radiation dose rate is greater than or equal to $25 \mu\text{Gy/h}$ (2.5 mrad/h), thus requiring the use of pocket dosimeters. Elevated dose rates and contamination levels may not always be coincidental. Therefore, it may be necessary to evaluate dose rate PPE requirements as a separate issue (see Footnote b, Table 6.1).
- Radioactive materials contamination is maintained at levels less than 830 Bq/100 cm^2 ($50,000 \text{ dpm/100 cm}^2$) for removable alpha contamination; $4,200 \text{ Bq/100 cm}^2$ ($2.5\text{E}+05 \text{ dpm/100 cm}^2$) for fixed alpha contaminations; $4.167\text{E}+04 \text{ Bq/100 cm}^2$ ($2.5\text{E}+06 \text{ dpm/100 cm}^2$) for removable beta-gamma contamination (except for iodine-125, iodine-129 and actinium-227, for which the guide is 830 Bq/100 cm^2); and $2.83\text{E}+05 \text{ Bq/100 cm}^2$ ($1.25\text{E}+07 \text{ dpm/100 cm}^2$) for fixed beta-gamma contamination [(except for iodine-125, iodine-129 and actinium-227, for which the guide is $4,200 \text{ Bq/100 cm}^2$ ($2.5\text{E}+05 \text{ dpm/100 cm}^2$))].
- PPE for protection against skin irritants may be highly specific to the chemical constituents(s) comprising the irritant. Accordingly, choice of chemical-resistant PPE materials shall be guided by knowledge of the chemical constituents encountered (see Footnote a, Table 6.1).
- Skin irritants are present.

6.2.5 Level 5 PPE

Level 5 PPE is reserved for emergency response operations in unknown atmospheres; work in IDLH atmospheres where specific substances represent a severe skin exposure hazard; work in extremely corrosive atmospheres; work in atmospheres containing concentrations of hazardous contaminants in excess of the protection factors for pressure-demand respirators; or work in atmospheres containing known hazardous contaminants that have not been adequately evaluated. The following guidelines shall be used for selection of Level 5 PPE:

- Almost any environment that will not degrade, permeate, or penetrate the PPE, and/or jeopardize planned radiation exposure limits, may be entered with Level 5 PPE.

The foregoing PPE requirements may be modified to provide the appropriate level of protection. Except in emergency situations, special PPE requirements will be recommended by the FHSS based on field survey information and laboratory analyses where appropriate. These requirements will be approved by the ES&H Manager prior to implementation.

7. RESPIRATORY PROTECTION PROGRAM

Procedures regarding the respiratory protection program require that when engineering controls cannot maintain airborne contaminants at acceptable levels, appropriate respiratory protective devices shall be used by affected persons. An effective respiratory protection program is essential to the ES&H program for this project. Each Task Specific Safety and Health Plan will contain a description of the respiratory protection program and respiratory protection equipment to be used for each of the site tasks being performed. HWP's will be issued to document the respiratory protection requirements used by personnel in the field to minimize exposures to hazardous materials.

The respiratory protection program shall accomplish the following:

- Establish respiratory protection requirements, including selection of devices to be used for each work situation as required by hazard potentials (see Sect. 3).
- Verify that personnel who use protective devices meet medical requirements for such use, that the fit of the assigned device is acceptable, that personnel are adequately trained in the use of the devices, and that they use the devices as specified on the job.
- Verify that air supplies meet applicable requirements (such air supplies may include plant air, dedicated air supply systems, and/or air tanks).
- Provide for appropriate records of the following:
 - respirator requirements for work situations;
 - indications of medical status of individuals;
 - respirator fitting results;
 - training of employees and supervisors;
 - specification of respiratory protective requirements, e.g., on HWP;
 - actual use of respirators on jobs requiring them;
 - emergency procedures, training, and device selection;
 - respirator inspection, cleaning, and maintenance activities;
 - results of bioassay program; and
 - tests and inspections of air supplies.

The above elements of the program shall be carried out in accordance with ES&H PP 1230 "Personal Protective Equipment," which complies with applicable regulatory requirements.

7.1 REGULATORY REQUIREMENTS

The requirements of DOE Order 5480.11 and OSHA Regulations 29 CFR 1910.134 and 29 CFR 1910.120 shall be met. The American National Standards Institute (ANSI) standard "Practices for Respiratory Protection," ANSI Z88.2-1980, is incorporated in these documents by reference and serves as the basic guide for such programs.

7.2 RESPONSIBILITIES AND AUTHORITIES

Acting under the overall guidance of ORNL management and the Energy Systems ES&H Coordinator, the ES&H Manager shall have responsibility and authority for administration of the respiratory protection program. In this capacity, the ES&H Manager may designate the FHSS as responsible for making decisions regarding the need for any type of respiratory protective equipment.

7.3 SELECTION OF RESPIRATORS

Only the National Institute for Occupational Safety and Health (NIOSH), the Mine Safety and Health Administration (MSHA), or the Nuclear Regulatory Commission (NRC) approved respirators, certified by Test Certification numbers, shall be used. All component and replacement parts must also have NIOSH, MSHA, or NRC approval. In addition, respirators are approved as a system. Cartridges, canisters, filters, air lines, and regulators cannot be interchanged among equipment, even among equipment of a single manufacturer, unless specifically approved by NIOSH, MSHA, or the NRC.

Selection of approved makes and types of respirators shall be based on mutual BNI and ORNL agreement and on the rationale provided in Sect. 6.

7.4 TRAINING

Training relative to the respiratory protection program shall be included in a 48-h Hazardous Waste Operations training course, including the following:

- instruction in the nature of the hazard, whether acute, chronic, or both; and an accurate appraisal of what may happen if the respirator is not used;
- explanation of why engineering or administrative controls may not be feasible, including explanation of efforts being made to reduce or eliminate the need for respirators;
- discussion of why a certain type of respirator is used for a particular purpose;
- discussion of the respirator's capabilities and limitations;
- discussion of the proper inspection, and maintenance of the respirator;
- instruction, training, and actual use of the respirator and close, frequent supervision to ensure that it is being used properly; and

- classroom and field training in recognizing and coping with emergencies.

Instruction in the actual application of the respirator under field conditions shall include:

- opportunities to handle the respirators;
- proper fitting, including demonstrations and practice in determining the fit, donning, wearing, adjusting, and removing the respirator;
- testing the facepiece for face seal;
- a period for familiarization with wear in normal air; and
- wearing the respirator in a test atmosphere.

ES&H personnel shall receive comprehensive training concerning respirators and respiratory protection practices. This training shall include, but not necessarily be limited to, the following:

- basic respiratory protection practices;
- selection and use of respirators to protect employees against hazards to which they may be exposed;
- nature and extent of the respiratory hazard to which the employees may be exposed;
- structure and operation of the respiratory protection program, including ES&H responsibility to facilitate functioning of the program, maintenance, issuance of respirators, control of use, and evaluation of program effectiveness; and
- the legal requirements pertinent to the use of respirators.

7.5 FITTING

Employees shall be fit-tested annually (and must be kept up-to-date) by the ORNL Industrial Hygiene Department or an ORNL-approved service for each type of respirator to be worn to ensure proper seal of the respirator facepiece. Documentation of fit test results will be retained by the ES&H Manager as part of the fit testing procedure. Each employee will be evaluated to see that facial features do not interfere with proper sealing. Employees with corrective lenses shall be provided with specially designed respirator glasses (inserts) that do not interfere with respirator seal. Employees with facial hair that interferes with the respirator seal shall neither be fit tested nor allowed to enter areas where respiratory protection is required. Employees shall be clean shaven at all respirator sealing surface contact points, or they shall not be allowed in areas that require respiratory protection.

Tests to be used in respirator fitting are described below.

7.5.1 Quantitative Test

This test involves exposing the respirator wearer to a challenge atmosphere. The concentration of the particles is measured both inside and outside the respirator, and this ratio

represents the protection factor afforded by the respirator.

Personnel required to use respiratory protective devices shall be quantitatively tested. A separate test is required for each type of device to be worn by an individual.

7.5.2 Field Tests

Field tests consisting of the following will be performed before entry into any area requiring respiratory protection:

- Test 1—Negative Pressure Test. This test consists of closing off the inlets of the canister, cartridge(s) or filter(s), inhaling gently so the facepiece collapses slightly, and holding the breath for 10 seconds. If the facepiece remains slightly collapsed and no inward leakage is detected, an adequate fit has probably been obtained. This test can be used only on respirators with tightly fitting facepieces. This test shall be used only as a gross determination of fit.
- Test 2—Positive Pressure Test. This test is conducted by closing off the exhalation valve and exhaling gently into the facepiece. The fit is considered satisfactory if slight positive pressure can be built up inside the facepiece without any evidence of outward leakage.
- Test 3—Irritant Smoke Test. Irritant smoke will be directed toward all facial sealing surfaces. Fit is considered satisfactory if no irritant is detected by the wearer.

7.6 INSPECTION, CLEANING, MAINTENANCE, AND STORAGE

7.6.1 Inspection Procedures

The OSHA standard states that respirator inspection shall include the following:

- checking straps and rubber seals for signs of deterioration;
- checking tightness of the connections;
- checking the facepiece;
- inspecting valves;
- inspecting connecting tubes;
- checking canisters, filters, or cartridges; and
- checking all flexible components for wear and deterioration.

In addition, the standard states that the regulator and warning devices on a self-contained breathing apparatus (SCBA) shall be checked for proper function.

ORNL shall inspect and maintain the air purifying respirators used on the project. The air supplied respirators shall be inspected routinely by field personnel and repairs shall be performed by personnel certified to repair the particular respirator system.

7.6.2 Defects Found During Field Inspections

If defects are found during any field inspection, two remedies are possible. If the defect is minor, adjustment may be made on the spot. If a defect is major, the device shall be removed from service until it can be repaired. All air purifying respirators shall be repaired by Energy Systems while all SCBAs will be sent to the manufacturer for major reparation (i.e., regulator adjustment). Under no circumstances shall a defective device be allowed to remain in the field.

7.6.3 Inspection During Cleaning

ORNL provides inspection and cleaning of ORNL supplied respirators. Because respirator cleaning usually involves some disassembly, it presents an opportunity to thoroughly examine each respirator.

7.6.4 Cleaning and Disinfecting

ORNL-supplied respirators will be cleaned and disinfected by ORNL as a minimum, after each shift that they are used. Any Bechtel-supplied respirators shall be collected, cleaned, and disinfected in accordance with ES&H PP 1230 Section 4.2.7 "Respirator Maintenance, Cleaning, Decontamination, and Storage." Respirators used during training exercises in the field will be sanitized in the field. If needed, ORNL's cleaning services may be used. Emergency use respirators shall be cleaned and disinfected after each use.

7.7 MEDICAL ASPECTS

Employees who are required to wear a respirator must be examined annually by a physician to determine medical fitness for tasks requiring respirators. Employees shall not be assigned to a task that requires a respirator unless it has been determined that the person is physically capable of performing the work while using the respirator. A release statement, signed by the physician is kept on file in the ES&H Manager's office area.

During respirator fitting, any distress exhibited by an individual shall be reported, and reexamination by a physician may be required to determine whether the employee can continue to safely use the equipment. In addition, any evidence that an employee is having difficulty using any respiratory protective device shall be reported to the ES&H Manager. That individual shall then be reassessed by a physician.

7.8 PROGRAM EVALUATION

Two important aspects of the respiratory protection program are periodic surveillance of the work areas that require use of respirators and an evaluation of the program for effectiveness.

7.8.1 Surveillance of the Work Area

Many variables affect the need to use respirators. To determine the necessity for respiratory protection or the need for additional protection, appropriate surveillance of work conditions and the degree of employee exposure or stress is provided by RI/FS ES&H Specialists as determined by the FHSS or ES&H Manager. Program changes shall then be implemented as needed.

The results of work sampling and exposure measurement determine the selection and use of respiratory protection equipment. The respiratory protection program shall be modified as needed based on these exposure measurements.

7.8.2 Evaluation of Effectiveness

Frequent evaluation of respirator practices will determine whether appropriate respirators are being used, and whether they are being used properly. Examination of respirators in use and in storage will indicate how well the equipment is being maintained.

Improper use and/or maintenance of respirators will not be tolerated. Intentional abuse of respirators is cause for dismissal from the project.

Users will be consulted periodically about their acceptance of respirators, including the user's discomfort, resistance to breathing, and fatigue. Users will also be consulted concerning the degree to which the respirator interferes with vision and communication, restricts movement, and interferes with job performance, and the user's confidence in the respirator's effectiveness.

The results of periodic inspections of respirator use, consultation with wearers, measurements of airborne levels of contamination in work areas, bioassays, and medical surveillance of wearers will be reviewed and analyzed to determine the effectiveness of the respirator program. Any evidence of excessive exposure to hazards will be investigated to determine why adequate protection was not provided, and action will be taken to remedy the problem.

8. SITE AND CONTAMINATION CONTROL

Each Task-specific Safety and Health Plan will contain site control and contamination control measures. Site control measures are limited to the establishment of CAAs at individual work locations in accordance with the provisions of PP 1235 "Hazardous Work Permits." Overall site security is provided by ORNL Security. ORNL provides 24-hour-a-day armed intrusion protection and patrol for most of the laboratory complex.

At each major activity work location, a site map will be provided. The site map will be marked by the FHSS or designee, with the shortest evacuation route from the individual work site to a predesignated assembly area and the location of the nearest medical assistance, which is ORNL Medical located in Building 4500 North.

8.1 WORK AREA CONTROL MEASURES

Work within each CAA is controlled by PP 1235, "Hazardous Work Permits." The HWP system provides authorization for named employees to do a particular job involving exposure to radiation or radioactive contamination, hazardous chemicals, physical hazards, or other potentially dangerous work situations. The HWP system incorporates appropriate approvals for named personnel to enter areas under specified requirements. Daily entry and exit times for those personnel are also recorded. If time-exposure operations are involved, appropriate time and exposure data are recorded. The minimum work crew for operations within a CAA will be two individuals. Additional information on CAAs and the HWP system is contained in Section 12.0 of this plan. Standard operating procedures have been established to govern the establishment, entry, work activities, and monitoring of CAAs. These procedures are listed in Table 1 of Sect. 5.0.

Work areas will be controlled via an HWP system per PP 1235, "Hazardous Work Permits." HWPs will be used to control employee exposure to hazards or each work task where the evaluated potential for such exposure warrants. This system contains elements necessary to provide direction on the establishment of CAAs, including site maps, designated work zones, use of a "buddy system," site communications (e.g., emergency alerting, work practices, and procedures), and the identification of the nearest medical assistance.

8.2 CONTAMINATION CONTROL

For operations, it will be necessary to apply existing project procedures and protocols to control the spread of contaminants (radioactive, chemical, and biological) to prevent or minimize exposure to the environment, the public, and project personnel. General methods to be used are as follows:

- Contaminant protection training for worker understanding of contaminant hazards and work practices is required to prevent the spread of contaminants. See PP 1210 "ES&H Training."
- Various contamination control measures shall be initiated when CAAs are necessary. Locations where individuals are required to exit CAAs will be monitored by portable instruments to minimize the potential for spreading contaminants to the environment. Engineering and administrative controls shall be used, when applicable, to minimize personnel and environmental exposures to site generated contaminants.
- An HWP system that controls access to areas where contaminants are known to exist and specifies protective equipment for work in those areas. See PP 1235, "Hazardous Work Permits"; and 1280.7, "Posting and Labeling."
- Contaminant surveys to identify areas containing materials requiring control, to establish the boundaries of CAAs, and to provide input for HWPs. See PP 1220, "Initial Site Survey"; 1255, "Work Area and Environmental Monitoring"; and 1280.1, "Methodology for Performing Radiological Contamination Surveys."
- Use of anti-contamination clothing in areas with accessible surface contamination, and respiratory protection equipment in areas with known airborne contaminants. See PP 1230 "Personal Protective Equipment."
- Air sampling for radiological and organic compounds will be accomplished to establish the need for the level of respiratory protection required and to provide input for HWPs. At a measured concentration of 1 ppm in the breathing zone, respiratory protection and PPE will be implemented. See PP 1255, "Work Area and Environmental Monitoring"; and 1270.1, "Air Surveillance of Chemical and Radiological Contaminants."
- Monitoring and decontamination of personnel and equipment (eg. tools and vehicles) leaving CAAs to prevent the spread of contamination. See PP 1245 "Personnel Decontamination"; 1250 "Equipment Decontamination and Release for Unrestricted Use"; and 1280.8 "Control Point Monitoring."
- Review and analysis of tasks to make sure that they are, or will be, performed with the minimum spread of contamination.

Personnel monitoring for radioactive materials contamination will be required when exiting a CAA and at other times designated by the FHSS. This activity will be conducted in accordance with Sect. 4.2 of PP 1280.8 "Control Point Operations." Outer anti-contamination clothing will be surveyed and disposed of in accordance with PP 1402 "Waste Handling." Work clothing will be placed in appropriate containers for cleaning by ORNL. Respiratory protection equipment will be surveyed to segregate those items that exhibit radioactivity. Contaminated respirators will be properly packaged and labeled.

Respiratory protection equipment will be surveyed to segregate those items that exhibit radioactivity. Contaminated respirators will be properly packaged and labeled.

Work area and personnel monitoring will be conducted in accordance with PP 1280 through 1280.9, "Health Physics Practices"; 1270, "Industrial Hygiene Practices"; and 1270.1, "Air Surveillance of Chemical and Radiological Contaminants." These procedures specify the types of monitoring, instrumentations to be used and their maintenance and calibration, and the technique to be used in sampling and analysis. This is further discussed in Sect. 13 of this plan.

07/16/91

R01-003

9. PERSONNEL DECONTAMINATION

9.1 INTRODUCTION

All personnel and equipment (including tools and vehicles) exiting a contaminated zone will be monitored to detect possible contamination. Monitoring will verify that all personnel (and equipment) are free of significant contamination prior to exiting the contamination zone, and that contamination is not carried beyond the contamination zone. Personnel monitoring will be performed in accordance with PP 1245, "Personnel Decontamination;" 1280.1, "Methodology for Performing Radiological Contamination Surveys;" and PP 1280.8, "Control Point Monitoring."

When monitoring indicates that an employee has become contaminated with chemicals, biological agents, or radioactive materials, the employee's immediate supervisor notifies the FHSS, who records the details of the incident, determines if any personnel injury is involved, and, notifies the ES&H Manager, and initiates decontamination as appropriate. All contamination incidents shall be immediately reported by the ES&H Manager to ORNL management through the Laboratory Shift Supervisor (LSS) and the Environmental Restoration Division to ensure that prompt procedural notifications and appropriate emergency response actions are enacted.

9.2 FACILITIES

The ES&H Manager will designate the FHSS to verify that BNI facilities provided for personnel decontamination are maintained in acceptable condition and that supplies of decontaminating agents and other materials are kept available. Personnel decontamination facilities (located at the Field Office Facility) shall be equipped with showers, supplies of clean work clothing, decontamination agents, and a decontamination area where ES&H personnel can assist in decontaminating individuals. Provisions shall be made to retain all wash solutions for appropriate disposal, and for maintaining separation between clean and contaminated areas and materials. Provisions shall be included at the CAA boundary for decontaminating the exterior surfaces of fully encapsulating suits before removal from personnel.

9.3 DECONTAMINATION TECHNIQUES

The affected employee shall remove all contaminated clothing and equipment. If radioactive contamination is involved, ES&H specialists shall monitor the employee and notify the site FHSS if designated action levels have been exceeded.

The employee shall wash thoroughly with soap and water, and may use a soft-bristled brush for cleaning the hands and fingernails. Care shall be taken to avoid irritating or abrading the skin. If there is evidence, including radiation monitoring results, that cleaning is not complete, the washing may be repeated. When the ES&H Manager believes it is warranted (e.g., contamination of the eye, contamination abraded into the skin), any further decontamination efforts shall be carried out under the direction of a physician.

9.4 RELEASE LIMITS

The following radioactive contamination guidelines for skin and hands, used by ORNL, shall be used throughout the RI/FS project.

Item	<u>Transferable (smear)^a</u>		<u>Direct readings^a</u>	
	<u>Alpha</u>	<u>Beta-gamma</u>	<u>Alpha</u>	<u>Beta-gamma</u>
General body	0.33 (20) ^b	3.3 (200) ^b	2.5 (150)	16.67 (1000)
Hands	0.33 (20) ^b	3.3 (200) ^b	5.0 (300)	16.67 (1000)

Reference: ORNL Health Physics Procedure RP-2.5, "Radioactive Contamination Control."

^aUnits are Bq/100 cm² (dpm/100cm²).

^bRemovable skin contamination should be nondetectable. These values represent the lower limit of detection for the smear counting systems in the field. The sensitivity of standard frisking techniques is such that only the direct reading limits can be readily detected.

9.5 EMERGENCY DECONTAMINATION

In the event of personnel contamination with highly caustic, strongly acidic, and/or high levels of radioactive materials (>0.01 mGy/h), emergency shower facilities located at the Field Office Facility shall be used as a first level decontamination. These facilities shall be adequate to treat a minimum of two contaminated individuals at one time. Appropriate Energy Systems medical and radiation safety personnel will be relied upon to assist as needed. Use of these facilities shall be in accordance with PP 1245, "Personnel Decontamination."

Arrangements shall be made to coordinate actions with ORNL and the Radiation Emergency Assistance Center/Training Site (REAC/TS) at the Methodist Medical Center (Oak Ridge Hospital) to deal with injured employees who suffer concurrent contamination with hazardous chemicals or radioactivity, in accordance with PP 1240, "Emergency Response."

07/16/91

R01-003

10. EQUIPMENT DECONTAMINATION

10.1 RESPONSIBILITIES AND AUTHORITIES

The FHSS is responsible for ensuring that tools and equipment (including vehicles) are surveyed before they are removed from CAAs in accordance with PP 1280.1 "Methodology for Performing Radiological Contamination Surveys," and PP 1250 "Equipment Decontamination and Release for Unrestricted Use." The Field Activities Coordinator is responsible for ensuring that tools and equipment determined to be contaminated in excess of applicable limits are decontaminated to acceptable levels prior to release for unrestricted use.

10.2 FACILITIES

Prior to release from the CAA, tools and equipment determined to be contaminated with removable radioactive and detectable chemical materials in excess of applicable limits are manually decontaminated at the field location. Field decontamination efforts are conducted in accordance with PP 1250 "Equipment Decontamination and Release for Unrestricted Use," to prevent contamination from being spread to uncontaminated areas, facilities, or personnel.

Tools and equipment that cannot be field decontaminated to below applicable limits are appropriately packaged, removed to, and decontaminated in the BNI mobile decontamination trailer. The mobile facility is self-contained and uses recycle and cleanup technology to minimize generation of waste.

Contaminated reusable PPE is collected and packaged in contamination-free containers and taken to the contaminated clothing and respirator wash facilities located at ORNL. The facilities have integral recycle and cleanup capabilities to minimize the volume of waste generated. Chemical decontamination is performed for all items that are to be reused for additional field sampling. This decontamination is accomplished at the BNI decontamination trailer(s), or in the field as described above.

10.3 DECONTAMINATION CLEARANCE LIMITS

The radioactive materials contamination limits/guides used for release for unrestricted use are shown in Tables 10.1, 10.2, and 10.3. The limits shown in Table 10.1 may be used if the nuclide(s) have been identified. For unidentified nuclides, the more restrictive limits shown in Table 10.2 must be used. Table 10.3 addresses release of equipment, shoes, and clothing. Tools and equipment released from CAAs must always be accompanied by an ORNL Form UCN-14 ("Green Tag"), as specified in PP 1250 "Decontamination of Equipment and Release for Unrestricted Use".

Table 10.1. Surface radioactivity guides

Nuclide ^a	Removable ^{b, d}	Total ^{b, c} (Fixed plus removable)
U-nat, U-235, U-238 and associated decay products	1,000 dpm α /100 cm ² ^b	5,000 dpm α /100 cm ²
Transuranics, Ra-226, Ra-228, Th-230, Th-228, Pa-231, Ac-227, I-125, I-129	20 dpm/100 cm ² ^b	300 dpm/100 cm ²
Th-nat, Th-232, Sr-90, Ra-223, Ra-224, U-232, I-126, I-131, I-133	200 dpm/100 cm ² ^b	1,000 dpm/100 cm ²
Beta-gamma emitters (nuclides with decay modes other than alpha emission or spontaneous fission) except Sr-90 and others noted above ^e	1,000 dpm β - γ /100 cm ² ^b	5,000 dpm β - γ /100 cm ²

Source: DOE 5480.11, "Radiation Protection for Occupational Workers."

^aWhere surface contamination by both alpha- and beta-gamma-emitting nuclides exists, the limits established for alpha- and beta-gamma-emitting nuclides should apply independently.

^bAs used in this table, dpm (disintegrations per minute) means the rate of emission by radioactive materials as determined by correcting the counts per minute observed by an appropriate detector for background, efficiency, and geometric factors associated with the instrumentation.

^cThe levels may be averaged over one square meter provided the maximum surface activity in any area of 100 cm² is less than three times the guide values. For purposes of averaging, any square meter of surface shall be considered to be above the activity guide G if: (1) from measurements of a representative number of sections it is determined that $1/n \sum S_i \geq G$, where S_i is the dis/min-100 cm² determined from measurement of section i ; or (2) it is determined that the sum of the activity of all isolated spots or particles in any 100 cm² area exceeds $3G$.

^dThe amount of removable radioactive material per 100 cm² of surface area should be determined by wiping that area with dry filter or soft absorbent paper, applying moderate pressure, and assessing the amount of radioactive material on the wipe with an appropriate instrument of known efficiency. (Note - The use of dry material may not be appropriate for tritium.) When removable contamination on objects of a surface less than 100 cm² is determined, the activity per unit area should be based on the actual area and the entire surface should be wiped. Except for transuranics and Ra-226, Ra-228, Ac-227, Th-228, Th-230, and Pa-231 alpha emitters, it is not necessary to use wiping techniques to measure removable contamination levels if direct scan surveys indicate that the total residual surface contamination levels are within the limits for removable contamination.

^eThis category of radionuclides includes mixed fission products, including the Sr-90 which is present in them. It does not apply to Sr-90 which has been separated from the other fission products or mixtures where the Sr-90 has been enriched.

Table 10.2. Recommended maximum^a contamination guide for items given radiation or contamination clearance

<u>Direct survey</u>		<u>Transferable (smear)</u>	
<u>Alpha</u> Bq/100 cm ² (dpm/100 cm ²)	<u>Beta-gamma</u> Bq/100 cm ²	<u>Alpha</u> Bq/100 cm ² (dpm/100 cm ²)	<u>Beta-gamma</u> Bq/100 cm ²
5.0 (300)	17 (1000)	0.33 (20)	3.3 ^b (200)

Source: ORNL Health Physics Procedure RP-2.5.

^aNo 100 cm² area to average greater than this value.

^bExcept I-125, I-129, and Ac-227 for which the guide is 0.33 Bq/100 cm² (20 dpm/100 cm²).

Table 10.3. Contamination guides^a

	Direct survey		Transferable (smear)	
	Alpha Bq/100 cm ² (dpm/100 cm ²)	Beta-gamma Bq/100 cm ² (dpm/100 cm ²)	Alpha Bq/100 cm ² (dpm/100 cm ²)	Beta-gamma Bq/100 cm ² (dpm/100 cm ²)
Areas, work surfaces, tools, and equipment	5.0 (300)	16.7 (1000)	0.3 (20)	3.3 (200)
Skin, general body	2.5 (150)	16.7 (1000)	0.3 ^c (20)	3.3 ^c (200)
Skin, hands	5.0 (300)	16.7 (1000)	0.3 ^c (20)	3.3 ^c (200)
Shoes, personal	5.0 (300)	16.7 (1000)	0.3 (20)	3.3 (200)
Clothing, personal and company	5.0 (300)	16.7 (1000)	Not applicable	
Clothing, C-Zone Area	16.7 (1000)	250 (15,000)	Not applicable	

^aThe guides for alpha are based on the limit for transuranics, while the beta-gamma guides are based upon the limit for ⁹⁰Sr. In those cases where specific nuclides are known, these values may be adjusted by radiation protection personnel in accordance with established internal procedures.

^bThese levels may be averaged over 1 m² provided the maximum surface activity in any area of 100 cm² is less than 3 times the guide values.

^cRemovable skin contamination should be nondetectable. These values represent the lower limit of detection for the smear counting systems in the field. The sensitivity of standard frisking techniques is such that only the direct-reading limits can be readily detected.

Source: ORNL Health Physics Procedure RP-2.5, "Radioactive Contamination Control."

Chemical decontamination is performed in accordance with the product procedures based upon Environmental Protection Agency accepted procedures and PP 1250. Random sampling and analysis of final rinse solutions may be performed to check the effectiveness of the decontamination procedures.

10.4 DISPOSAL OF CONTAMINATED FLUIDS AND MATERIALS

Fluids and materials resulting from decontamination processes are contained, sampled, and analyzed for contaminants. Those materials determined to be contaminated in excess of appropriate limits are packaged in ORNL-approved containers and disposed of in accordance with the ORNL RI/FS Waste Management Plan and appropriate project procedures.

11. PERSONNEL TRAINING

11.1 INITIAL TRAINING

Initial ORNL Health and Safety orientation training is conducted for all personnel badged for site entry. The training programs are presented at levels suitable for the various types of project personnel (e.g., management, sample team members, health and safety specialists). The training will introduce BNI Team personnel to key ORNL ES&H personnel, identify potential on-site hazards, and cover PPE, work practices, and site operational procedures.

In accordance with OSHA 29 CFR 1910.120 requirements, all employees assigned to work in hazardous waste areas must receive a minimum of 40 hours training off-site prior to job assignment, and, at the time of job assignment, 3 days of actual field experience under the direct supervision of a trained and experienced supervisor. Supervisory personnel receive this same training, plus an additional 8 hours of specialized training on managing hazardous waste operations. Documentation of current training records is retained in the ES&H Manager's office area. On a monthly basis, a report is obtained from the ES&H training records database and personnel who are nearing re-training dates are scheduled. This assures that all site personnel who require training are trained and the records are up-to-date.

Basic OSHA training for all employees will include the following, in accordance with PP 1210 "ES&H Training:"

- names of personnel and alternates responsible for site safety and health;
- safety, health, and other hazards present on the site;
- use of PPE;
- work practices by which the employee can minimize risks from hazards;
- safe use of engineering controls and equipment on the site;
- medical surveillance requirements, including recognition of symptoms and signs that might indicate overexposure to hazards;
- site control measures;
- decontamination procedures;
- the site standard operating procedures;
- emergency responses;
- confined-space entry procedures; and
- use of respiratory protective devices, including actual practice in using applicable devices.

In addition to the above, on-site management and supervisors directly responsible for operations in waste areas shall receive 8 additional hours of instruction in the following:

- legal background for waste disposal activities,
- HWP applications,

07/16/91

R01-003

- spill control techniques, and
- structure and operation of the PPE program.

11.2 TASK SPECIFIC TRAINING

Detailed hazard evaluations and specific safety plans and procedures for nonroutine or unusual work shall be developed for each major task and shall be reviewed and approved by ORNL prior to implementation. Employees shall then be trained in these task specific instructions, the project ES&H Plan, and procedures prior to being assigned to work in the specific areas. Onsite training will be required prior to the start of work in accordance with PP 1210 "ES&H Training." This will be done over a 3-day period under the direction of a supervisor who is knowledgeable of hazardous waste activities. Operating personnel will review and visit all applicable areas where they will work. Each worker will be instructed in all health and safety procedures applicable to their work area, and in PP 1275 "Industrial Safety Practices," and companion procedures 1275.1 through 1275.12.

Health and safety specialists will receive on-site instruction in all ES&H procedures applicable to task operations, and each will receive specific instruction in PP 1270, "Industrial Hygiene Practices," PP 1270.1 "Air Surveillance of Chemical and Radiological Contaminants," PP 1280, "Health Physics Practices," and its companion procedures 1280.1 through 1280.9.

11.3 REFRESHER TRAINING

Employees and supervisors will receive an 8-hour annual refresher course covering the materials of the initial indoctrination and other pertinent topics.

11.4 WEEKLY "TOOL-BOX" TRAINING

To maintain a high level of safety awareness on the part of employees and supervisors, each supervisor shall hold weekly safety meetings to highlight specific safety concerns. On occasion such meetings may be replaced by more formal safety meetings, sometimes held in conjunction with other work groups.

11.5 VISITOR POLICY

Visitors are given abbreviated training in accordance with Section 4.1 of PP 1210 "ES&H Training," consisting of the following topics:

- site-specific hazards,
- conduct within work areas, and

07/16/91

R01-003

- emergency response actions.

At all times, visitors must be escorted by an individual who has completed the 40-hour hazardous waste worker training. Visitors are not allowed inside CAAs.

07/16/91

R01-003

12. HAZARDOUS WORK PERMITS

The HWP system provides authorization for named employees to do a particular job involving exposure to radiation or radioactive contamination, hazardous chemicals, physical hazards, or other potentially dangerous work situations. The HWP system incorporates appropriate approvals for named personnel to enter areas under specified requirements. The entry and exit times for those personnel are also recorded. If timed-exposure operations are involved, appropriate time and exposure data are recorded. The HWP program is conducted in accordance with PP 1235 "Hazardous Work Permit." Key aspects of the program are outlined in the following subsections.

12.1 CONDITIONS REQUIRING AN HWP

An HWP shall be required before beginning work for which any of the following conditions are anticipated or possible:

- when an individual may receive a radiation dose equivalent in excess of 0.2 mSv (20 mrem) to the total body, or 3 mSv (300 mrem) to the extremities during the work shift;
- when an individual may be exposed to a radiation dose equivalent rate greater than 1 mSv/h (100 mrem/h);
- when an individual may be exposed to airborne concentrations of radioactive materials in excess of the DAC for a 40-h week, or to airborne concentrations of hazardous chemical substances in excess of the TLV (PEL, REL);
- if a CAA is required to control the spread of known contamination and to protect observers, the public, and the environment;
- when intrusive characterization efforts may encounter radioactive and/or hazardous chemical contaminants of unknown types and/or concentrations; and
- when work may be conducted in oxygen-deficient atmospheres, high noise environments, and other such dangerous environments.

12.2 HWP INITIATION

Any project personnel familiar with work scheduled to be performed may initiate an HWP. After the initiator enters his/her name, description of work, work location, and names of involved employees, the HWP form is routed and completed as follows:

- The FHSS enters appropriate radiation and contamination data and working time limits if applicable. If hazards other than radiation or radioactive contamination are involved, the FHSS shall enter industrial hygiene and safety conditions at the work location, industrial hygiene surveys and results, and special protective equipment or safety measures to be employed.
- The FSS Manager reviews the HWP form to verify that all appropriate elements of the permit have been completed.
- A copy of the approved form is returned to the originator and is posted at the work site. A copy of the approved form is retained in an "active" file by the FHSS.

12.3 POSTING REQUIREMENTS

Any area designated in an HWP (CAA) must be protected by an appropriate barricade or flagging, with the HWP posted at the entry location of that area. Entry into the CAA requires the approval of the FHSS or designee, who verifies that all individuals involved have properly completed the appropriate log-in or log-out records and are outfitted with appropriate PPE.

12.4 CONTAMINATION CONTROL

If the spread of chemical or radioactive contamination is possible, appropriate PPE and PPE disposal bins shall be established at the perimeter of the area, along with step-off pads. PP 1280.8 "Control Point Operations," specifies protocols for establishing CAAs to control the spread of contamination.

12.5 TERMINATION

HWPs remain active until the completion of work, expiration of any pre-set time limits, or when field conditions differ from those stated in the HWP. If personnel exposure conditions and/or work practices differ significantly from those stated, the HWP shall be terminated, conditions reevaluated, and a new HWP issued. Terminated HWPs are closed out and become part of the project record.

12.6 RECORD RETENTION

Upon completion of work the supervisor in charge shall sign the HWP and forward it to the ES&H Manager for record retention.

13. MEDICAL SURVEILLANCE

The RI/FS project Medical Surveillance Program shall conform to DOE Order 5480.10, OSHA 29 CFR 1960, and OSHA 29 CFR 1910.120. Employees to be included in the Medical Surveillance Program include (1) employees who are, or may be, exposed to hazardous substances or health hazards above the permissible exposure limit or published exposure level for more than 30 days per year; (2) employees working in activities that fall under the scope of 29 CFR 1910.120 who wear a respirator for 30 or more days a year as required by 29 CFR 1910.134; and/or (3) employees who are injured due to overexposure from an emergency incident, or who show symptoms of illness that may have resulted from exposure to hazardous substances in the course of their work. Periodic physical examinations shall be offered to each employee, with the frequency of examinations related to the age of the employee and potential for exposure. In addition, a health status review shall be made for all terminating employees. The extent of these reevaluations shall be determined by the consulting physician.

Supplemental health assessments are required whenever there is an actual or suspected exposure to chemical contaminants in excess of applicable limits, or if site personnel experience any symptoms of exposure. BNI Team industrial hygienists, health physicists, and safety personnel will cooperate closely with consulting physicians to supply pertinent information concerning toxic materials involved, to assist in evaluating incidents of suspected exposure, and to optimize the maintenance of a healthful work environment.

Complete and specific details of the Medical Surveillance Program are contained in PP 1205 "Medical Surveillance."

14. BIOASSAY PROGRAM

The RI/FS project field characterization efforts will include intrusive investigations of areas of unknown, but highly probable, contamination potential. Given the uncertainties associated with this type of field work, the project internal exposure monitoring program is based on the assumption that personnel will be exposed to significant quantities of radioactive and/or hazardous chemical contaminants. Accordingly, the project internal dosimetry program will be conducted in accordance with the provisions of PP 1280.4 "Internal Radiation Dosimetry." These provisions are outlined in the following paragraphs. (Monitoring and control of internal contamination by hazardous chemical contaminants is included in the medical surveillance program, described in Sect. 13 of this document.)

14.1 BASELINE BIOASSAYS

Individuals who are assigned to field activities or who have reason to visit or inspect field activities are assigned one of the four job function categories shown in Table 14.1. All such individuals (except Category IV individuals) must submit urine samples and submit to whole body counting (WBC) prior to participation in field activities. The baseline urine samples are analyzed for the solubility Class D and Class W compounds that could reasonably be expected to be encountered at ORNL. WBCs are analyzed for the gamma-emitting radionuclides that could reasonably be expected to be encountered at ORNL.

Results of the baseline bioassay analyses are evaluated by the project Health Physicist for evidence of previous exposure. Individuals exhibiting evidence of previous internal contamination will not be permitted to enter CAAs until an evaluation of the previous exposure indicates that additional, planned radiation exposure will not result in doses in excess of applicable regulatory limits. This evaluation may include additional, rigorous sampling and/or counting to establish the physical and temporal parameters necessary to adequately assess the committed effective dose equivalent.

14.2 ROUTINE BIOASSAY PROGRAM

The routine bioassay program is used as a measure of the effectiveness of the respiratory protection and contamination control programs. As such, the bioassay frequency will be a function of potential exposure to airborne radioactive materials and will be based on the sampling periods shown in Table 14.2.

Evidence of inadequate respiratory protection will be cause for an investigation of the responsible field operation(s). The ES&H Manager is responsible for investigating and identifying probable causes of the respiratory protection program failure, and for recommending corrective actions.

07/16/91

RO1-003

Table 14.1. Job function categories

I.	Work involving full-time on-site activities for which a CAA is or may be required
II.	Work involving support activities (e.g., supervision or inspection) that does not require full-time CAA occupancy
III.	Work involving routine or frequent visits (e.g, observing, auditing, etc.) that does not require entry into CAAs, but for which CAA entry is not prohibited
IV.	Work involving nonroutine or infrequent visits (e.g., management observations) that does not require entry into CAAs, and for which CAA entry is prohibited

Table 14.2. Guide for routine sampling for those who work with radioactive material

Radioactive material	Routine sampling		
	Job function ^a Category I	Job function ^a Category II	Job function ^a Category III
Pu-241 and alpha emitters other than Class D and W Uranium	Urine each 3-4 weeks, WBC each 3-4 weeks	Urine each 6-13 weeks, WBC each 6-13 weeks	Urine each 6-12 months WBC each 6-12 mon
Sr-90 and Class D and W Uranium	Urine each 4-6 weeks	Urine each 6-13 weeks	Urine each 6-12 months
H-3 I-131	Urine each week WBC each week	Urine each month WBC each quarter	Urine each quarter Urine each quarter
Co-60 and Cs-137 All others	WBC each 3 months Consult with Energy Systems ES&H Coordinator	WBC each 6 months Consult with Energy Systems ES&H Coordinator	WBC each 6-12 months Consult with Energy Systems ES&H Coordinator

^aCategory defined in Table 14.1.

Category IV does not require routine bioassay.

14.3 DIAGNOSTIC BIOASSAYS

In accordance with the provisions of PP 1280.4, "Internal Radiation Dosimetry," diagnostic bioassays are used to quantify internal depositions that could result in an annual effective dose equivalent of 1 mSv (100 mrem) or an annual organ or tissue dose equivalent of 50 mSv (5 rem). The need for diagnostic bioassays is determined based on the routine bioassay action levels specified in PP 1280.4.

Diagnostic bioassays involve removing the individual from further internal and external exposure potentials and performing those bioassays necessary to establish the physical and temporal parameters essential for estimating the committed effective dose equivalent. The individual may return to planned exposure work once it has been determined that any such planned exposure will not result in a dose in excess of regulatory limits.

14.4 TERMINATION BIOASSAYS

All individuals participating in the bioassay program are required to submit excreta samples and submit to WBCs prior to termination from the project. Results of the termination bioassay analyses are reviewed by the project Health Physicist. Individuals may be recalled for diagnostic bioassays if they exhibit unexpectedly high results that indicate a potential for exposure in excess of regulatory limits.

14.5 BNI-ENERGY SYSTEMS INTERFACE

Energy Systems will provide all bioassay analytical services for the RI/FS project. Consequently, routine and nonroutine bioassay requirements (e.g., overexposure assessments) shall be closely coordinated with Energy Systems. The ES&H Manager is responsible for coordinating bioassay requirements with the Energy Systems ES&H Coordinator and will notify the Energy Systems ES&H Coordinator as early as possible regarding individuals to be included in the bioassay program and their assigned job function categories. In turn, Energy Systems will provide the ES&H Manager with copies of all bioassay analytical results for each member of the BNI Team included in the program.

15. EXTERNAL RADIATION DOSIMETRY PROGRAM

15.1 THERMOLUMINESCENT DOSIMETRY PROGRAM

Energy Systems will provide TLD services to the BNI Team members assigned to the RI/FS project. Energy Systems is responsible for the evaluation of dosimeter response and for maintaining permanent records. Following each dosimeter exchange, Energy Systems will provide the ES&H Manager with a copy of dosimetry results for BNI Team members.

The ES&H Manager is responsible for evaluating exposure potentials and assigning BNI Team members to the TLD program. He is also responsible for evaluating exposure data to verify that exposures are maintained at ALARA levels. He also ensures that exposure data are transmitted to the appropriate BNI Team members. Access to data will be limited to those individuals that have a need to know.

15.2 SELF-READING DOSIMETER PROGRAM

Self-reading dosimeters (SRDs) (pocket ionization chambers or electronic equivalent) are used to administratively control accrual of penetrating exposure. Field measurements are used to administratively control accrual of nonpenetrating skin exposure.

These field-received dose estimates will be recorded as a function of HWP number (providing location and work category) from SRDs for each individual (providing job function category), thereby establishing a data base for ALARA evaluations. Field dose estimating protocols are instituted when the exposure/dose rates to the whole body, skin, forearms, and the hands/feet exceed 25 $\mu\text{Gy/h}$ (2.5 mR/h), 0.1 mGy/h (10 mrad/h), 0.2 Gy/h (20 mrad/h), and 0.35 mGy/h (35 mrad/h), respectively.

15.3 RADIATION DOSE CONTROL PROGRAM

When the field-received dose estimate data indicate that an individual has accrued 3 mSv (300 mrem) over a one week period, the individual is not allowed to enter CAAs until, the individual's TLD badge is processed. The individual may be allowed to reenter CAAs only after project Health Physics review. (ORNL Health Physics shall also be contacted.) The TLD badge data is then used to update the individual's period to date (quarter, year and/or life, as appropriate) dose history and to correct the dose estimate data for ALARA evaluation purposes. The received dose estimates are then "zeroed," and the estimating protocol is reinstated. These methods will be used to ensure that the limits in Table 15.1 are not exceeded.

Table 15.1. Dose limits

Type of exposure	Condition	Limit mSv (rem)
Whole body	Annual effective dose equivalent	50.0 (5.00)
Skin of the whole body	Annual dose equivalent	500.0 (50.0)
Extremity	Annual dose equivalent	500.0 (50.0)
Organ or tissue	Annual dose equivalent	500.0 (50.0)
Lens of eye	Annual dose equivalent	150.0 (15.0)
Unborn child (entire gestation period)	Annual dose equivalent	5.0 (0.50)

Source: DOE 5480.11, "Radiation Protection for Occupational Workers."

16. PERSONNEL AIR MONITORING

The purpose of the personnel air monitoring program is to measure approximate concentrations of chemical and/or radioactive contaminants in the air breathed by RI/FS project personnel. Since the RI/FS project respiratory protection program will be designed to meet OSHA/DOE requirements, the protection factors specified for various protective devices will be considered when evaluating the actual air concentrations entering the lungs of monitored employees.

Whenever practicable, lapel-type samplers will be used in accordance with PP 1270.1, "Air Surveillance of Chemical and Radiological Contaminants," for monitoring work activities because they provide a reasonable approximation to a true breathing zone sample. Where higher flow rates of air than can be pulled with a lapel sampler are required, various configurations of AC-powered air pumps shall be used in accordance with PP 1270.1, "Air Surveillance of Chemical and Radiological Contaminants." These air pumps will be positioned to provide the closest possible approximations to true breathing zone.

Records of personnel exposures to concentrations of airborne contaminants shall be used for the following purposes:

- to establish that employees were not exposed to airborne contaminants above applicable guides,
- to determine whether respirators specified are the most appropriate types for the work,
- to provide records of contaminants to which individual personnel have been exposed with estimates of exposure levels, and
- to determine whether specific ALARA actions may be appropriate.

17. ALARA PROGRAM

This section is written to provide guidance regarding how the As Low As Reasonably Achievable (ALARA) philosophy is to be used for the ORNL RI/FS Project. ALARA is to be used by management (i.e., ES&H and support services) and the workforce at all times to minimize exposures to chemicals and radioactive materials. ALARA is to be stressed to project personnel to increase personnel awareness of how to use ALARA in day to day activities. This guidance may be in the form of tool box safety meetings, procedural and mock-up training, dosimetry reports/consultation, and HWP's.

The basic ALARA philosophy for ORNL RI/FS Project activities is simply to "limit personnel and environment chemical and radiation exposures to the lowest levels commensurate with sound economic and social considerations." This basic statement presupposes that no exposure should occur without a positive net benefit, considering technological, economic, and societal factors. Implicit in the ALARA philosophy is the assumption that any exposure, however small, carries with it some detriment or probability of detriment (i.e., risk), which should be balanced by an offsetting benefit. This philosophy for exposures to radiation/radioactive materials is based on the linear, nonthreshold hypothesis, which is based on the assumption that detriment from radiation is directly proportional to the dose incurred and that no threshold or dose exists below which there is no detriment. Indeed, this is the heart of the ALARA philosophy, and it implies that all individuals, including management and field personnel, should not stop looking for ways to minimize exposures for a given output of work, as long as the cost of the potential detrimental effect exceeds the net benefit.

A primary principle of on-the-job safety is that safety is everyone's responsibility. This principle applies also to ALARA. Day-to-day operational ALARA responsibilities are borne by all; others have additional and special responsibilities. Management is responsible for establishing support staff to provide the technical support and assistance necessary to achieve ALARA goals; and line management adopts technical, administrative, and supervisory methods applicable to the operations under their control. Each individual worker then implements ALARA principles and procedures. In addition, as in other safety-related programs, the individual worker will often make a significant contribution.

17.1 POLICY STATEMENT

It has been and continues to be the policy of BNI RI/FS management to maintain personnel exposures to radiation, radioactive materials, and other hazardous materials as low as reasonably achievable. ALARA is to be used in procedure development, work habits, facility/operation design, etc. to minimize exposure either internally or externally. The philosophy applies both to personnel exposed occupationally in controlled access areas

(CAAs) in the field and to persons exposed in uncontrolled areas due to environmental releases.

17.2 WORK-PLACE ALARA EFFORTS

Judicious application of basic time, distance, physical controls, and PPE principles will be used to limit exposures to ALARA levels. To verify that established control is adequate, workplace monitoring for radioactive materials and field instrument detectable chemicals will be conducted in direct proportion to expected and/or observed levels or exposure. Activities that result in unexpectedly high potential exposures will be terminated until provisions are made that permit work to proceed in acceptable ALARA fashion.

Hazardous Work Permits (HWPs) are used during field activities in lieu of approved operating procedures which have safety requirements spelled out. The HWP is required when there is a potential for either internal or external exposure to chemicals or radioactive materials. The FHSS notes the safety requirements on the permit. The specified requirements are used by workers to minimize potential exposures.

An electronic personal dosimeter is worn by each individual who is assigned to an HWP. Each HWP has a whole body penetrating dose equivalent action level which is assigned to each individual and inputted into the personnel access, computer database before beginning a task. The individual can not be assigned an electronic dosimeter if the action level has been exceeded. If during field operations the action level is exceeded, an audible alarm will sound and the individual exits the area. This computer database controlled, external dosimetry system is updated daily at badge exchange and maintains a record of individual daily and accumulated exposures.

17.3 ALARA PROGRAM ASSESSMENT

Personnel exposure data are maintained in the BNI RI/FS data base (refer to the Data Base Management Plan for additional information). External and internal exposures of record are comprised of TLD badge and bioassay data, respectively. Field dose calculation, direct-reading pocket meters, and event-based lapel air sampling data are used to maintain estimates of personnel exposures to both radioactive materials and hazardous chemicals. These estimates are correlated with job-specific activities (work location and work category) and individual-specific activities (job function) (see Sect. 14).

Periodic reviews of personnel exposure estimates are conducted to identify unfavorable trends and unexpectedly high potential exposures, as compared to the task hazards analysis (see Sect. 3). Activities (as functions of work location, work categories, and job functions) identified as resulting in chronically unfavorable trends will be investigated, and

recommendations will be made for additional administrative and/or physical controls, as appropriate.

All unfavorable trends and unexpectedly high potential exposures must be reported to appropriate project management by the ES&H Manager, who will also make recommendations for corrective action.

07/16/91

R01-003

18. PERIMETER MONITORING

To verify that personnel, facilities, and environs in areas adjoining work locations are not subject to chemical or radioactive exposure, perimeter monitoring around these activities will be carried out by BNI on a routine basis. The perimeter (CAA) is considered to be the boundary of the work area defined by the applicable HWP. Monitoring activities are briefly described in the following subsections.

18.1 AIR MONITORING

When an HWP is initiated in response to existing or potential airborne contamination, perimeter air sampling must be carried out during the course of the work. Because the areas defined by HWPs generally will be relatively small, air samplers may be located in specific downwind and upwind directions to be determined when the work begins. At these locations, sampling will monitor for airborne radioactive contamination and for hazardous chemicals thought to be present.

If hazardous chemical or radioactive contamination above applicable guidelines is indicated, the ORNL RI/FS Project Manager and the ORNL ES&H Coordinator will be notified. The area will be evacuated and the level of PPE required to complete the task will be upgraded, if applicable. Under the guidance of ORNL Environmental Monitoring and Compliance, appropriate investigations will then be carried out as quickly as possible by RI/FS personnel to identify the cause, evaluate possible exposures to persons in adjacent work areas, initiate any necessary bioassay or medical evaluations, and assess environmental impacts.

18.2 SURFACE WATER MONITORING

To the greatest extent practical, physical and administrative controls will be used to minimize the potential for the spread of contamination via surface water runoff. In the event that a potential exists for the spread of contamination as a result of surface water runoff, efforts shall be made to sample and analyze water from main runoff that could be affected by such contamination. If water contamination above the guidelines for water discharge from the site is found, ORNL Environmental Monitoring and Compliance will oversee an investigation by RI/FS personnel to identify and correct the cause, evaluate possible exposure to persons in adjacent work areas and off-site, and assess environmental impacts. Remedial action by BNI will be initiated to decontaminate affected areas.

18.3 RADIATION EXPOSURE RATE MONITORING

Daily exposure rate surveys will be made of each CAA perimeter. Operations resulting in exposure rates in excess of 25 $\mu\text{Gy/h}$ (2.5 mR/h) beyond the CAA boundary will be halted, the ORNL RI/FS Project Manager and ORNL ES&H Coordinator will be notified and the perimeter boundary extended, if practical. Following notification of the ORNL ES&H Coordinator, immediate actions will be taken by the FHSS to mitigate such conditions. Action may include expanding the CAA perimeter, shielding, and/or removing the source, or combinations of any or all of the foregoing depending on the magnitude of the perimeter exposure rate(s). Work will not be permitted to continue until physical and/or administrative controls are instituted to ensure that perimeter exposure rates are controlled to 25 $\mu\text{Gy/h}$ (2.5 mR/h), or less.

07/16/91

R01-003

19. EMERGENCY ACTION PLAN

19.1 GENERAL EMERGENCY ACTION PROCEDURES

RI/FS PP 1240, "Emergency Response," specifies personnel responsibilities and the actions to be taken in emergency situations. This general emergency action plan requires that the person discovering an emergency take immediate action to notify other employees and supervisors to protect personnel, property, and the environment. The ORNL ES&H Coordinator and LSS will also be notified immediately. The LSS will control and supervise the emergency response, involving Energy Systems ES&H personnel (e.g., Radiation Protection, Environmental Control) as appropriate.

Although the ORNL organization will respond to these situation, RI/FS project personnel will be responsible for lending support as required. The FHSS will verify that emergency notification information is posted in each work area.

19.2 SITE IDENTIFICATION

Each location where RI/FS project work is being conducted will be accurately identified and designated on an appropriate map, or in relation to a readily identifiable structure. This designation will be available at the work site and at the BNI field office. RI/FS personnel working in the area will be responsible for knowing this designation so requests for assistance can be made promptly and clearly. Methods for notifying other personnel (e.g., telephone numbers, radio call numbers, etc.) will also be posted as appropriate.

19.3 PROCEDURES

The following additional factors are addressed in PP 1240, "Emergency Response," and may also be contained in other detailed emergency procedures that may be developed. All procedures will be reviewed and approved by Energy Systems management before implementation.

- credible potential emergencies, i.e., pre-emergency planning, emergency recognition and prevention procedures, safety distances and places of refuge, and emergency treatment and first aid
- authorities, responsibilities, and actions to be taken by site personnel
- all situations under which the LSS will be notified for assistance
- lines of communications and criteria for notifying RI/FS project and ORNL personnel of emergency situations
- resources available from off-site sources (actual requests for off-site assistance to be initiated by the ORNL Emergency Director)

07/16/91

R01-003

- provisions for radiation monitoring of injured employees, with highest priorities being given to first aid and response to the injuries (i.e., emergency medical treatment and first aid)
- requirements for PPE, emergency, and communications equipment
- notification to employees of emergency situations outside their immediate area of activity (e.g., alerting notifications received via the National Warning System)
- evacuation of personnel
 - routes
 - situations requiring evacuation
 - plant emergency signals
 - means for notifying affected personnel
 - transportation for evacuees
 - accountability of personnel
 - procedures
- reentry planning
- critique of response and follow-up
- decontamination
- site security and control

20. RECORDS

In addition to the personnel dosimetry records maintained by Energy Systems, BNI will maintain its own set of records. This recordkeeping system will be maintained on the BNI VAX computer system and will be designed to facilitate effective employee exposure management and timely ALARA evaluations. Major elements of this recordkeeping system are described in the following subsections.

20.1 INDIVIDUAL MASTER RECORDS

A master record for each individual at a minimum will contain the following information:

- personal identification number (IDN)
- full name
- date of birth
- sex
- date of most recent medical evaluation
- medical status code
- training type IDN
- training date
- life-to-date whole body dose [Note: Whole body dose shall include contributions from internal emitters (committed effective dose equivalents)]
- quarter-to-date whole body dose
- year-to-date whole body dose
- quarter-to-date skin dose
- year-to-date skin dose
- quarter-to-date extremity dose
- year-to-date extremity dose
- annual (for current calendar year) committed effective dose to, or concentration of contaminant in:
 - organ A
 - organ B
 - organ Z
- job function category

20.2 DOSIMETRY RECORDS

This data base will contain the external radiation exposure of records, or TLD badge data. The following minimum information will be retained:

- personal IDN

07/16/91

R01-003

- penetrating radiation dose
- nonpenetrating skin radiation dose

20.3 EXTERNAL DOSE ESTIMATES

This is a secondary data base that will be used to supplement the dosimetry records and master records data bases. The following minimum information will be retained:

- personal IDN
- HWP IDN
- date/time of area entry
- date/time of area exit
- net time spent in area
- pocket dosimeter or instrument IDN
- estimated exposure

20.4 INTERNAL DOSE ESTIMATES

Internal dose estimates will be calculated from bioassay and whole body count data. The following minimum information shall be retained:

- personal IDN
- bioassay medium
- date of collection or measurement
- date of analysis
- concentration or activity of contaminants
- laboratory/report IDN

20.5 EXPOSURE TO AIRBORNE CONTAMINANTS

This is a secondary data base used for administrative control of exposures to airborne concentration of radioactive and/or non-radioactive hazardous chemical contaminants. The following minimum information will be retained:

- personal IDN
- HWP IDN
- date of measurement
- sampler IDN
- individual's assigned protection factor (PF)
- concentration of contaminants
- time of exposure

- potential (unprotected) exposure (PE)
- actual (protected) exposure (AE) (Note: $AE = PE/PF$)
- concentration worksheet IDN

20.6 ALARA ACTIVITY RECORDS

This is a secondary data base used to support any other data base or report requiring work location, work category, job function, exposure, and/or temporal data.

20.7 SUPPLEMENTAL DATA BASES

Supplemental data bases will be required to provide complete record sets and to support the foregoing data bases. The following summarizes the required data sets:

- HWP information file
- instrument calibration file
- respirator use file
- perimeter monitoring file
- medical history file
- training history file

Though all records will be maintained by Energy Systems, hard copies of supporting primary records (e.g., TLD and bioassay reports, NRC 4 forms, air sample worksheets, calibration certificates, training tests, and course outlines) will also be retained by BNI. All records will be maintained until completion of the project, at which time a copy of all records will be provided to Energy Systems.

21. ANALYTICAL SAMPLE PACKAGING AND SHIPMENT

Samples of waste, soil, sediment, biota, and water collected for analytical purposes will be packaged and transported in accordance with DOT regulations, EPA regulations, and Energy Systems protocols, as defined in PP 1260, "Shipment of Hazardous Materials." This plan presents the methodologies used to measure compliance with these requirements.

21.1 REGULATORY REQUIREMENTS

The regulatory requirements applicable to transportation of samples to and from the laboratory are contained in 49 CFR 171 et seq. and will be strictly complied with. Specific exemptions for transport of chemical samples are defined in 40 CFR 261.4(d). Samples meeting the levels of exempt, limited quantity, or low specific activity will be packaged in strong, tight containers.

21.2 RESPONSIBILITIES

The ES&H Manager is responsible for developing sample packaging and transportation procedures; developing, testing or procuring DOT containers as appropriate; and ensuring compliance with regulatory requirements. Because ORNL has ultimate responsibility for compliance with regulations, Energy Systems will exercise oversight authority to verify compliance.

The FSS Manager is responsible for the characterization of samples and proper labeling in accordance with approved procedures. The Transportation Officer is responsible for verifying that samples are appropriately packed; that sample containers are properly labeled; that accurate sample identification data are entered into the appropriate data base; and that samples are delivered to the sample shipping destination. BNI will be responsible for shipping and for maintaining records for samples on behalf of and in the name of Martin Marietta Energy Systems and the U. S. Department of Energy.

21.3 SAMPLE SCREENING TECHNIQUES

Sample screening for chemical contaminants may include historical data as well as the results of field monitoring for toxic and explosive atmospheres. Radiological screening consists of a review of field monitoring data, direct exposure rate measurements of each sample, gross alpha/beta counting, and/or gamma spectroscopy analysis, as necessary, in a field laboratory. These screening techniques are described in the Close Support Laboratory (CSL) procedures and in PP 1260.1, "Determination of Hazardous Materials Classification."

21.4 PACKAGING AND LABELING

Samples will be packaged for shipment in containers appropriate to the hazard class they represent and in accordance with 49 CFR requirements. For samples transported by the BNI Team, an exclusive-use vehicle will be used.

07/16/91

R01-003

22. HAZARD COMMUNICATION PROGRAM

The Hazard Communications Program informs RI/FS Project employees of the hazardous materials used in the conduct of operations. Within this program is a basic overview of the types of hazardous materials, their storage or use locations, the location of information concerning these materials, and the location of written programs and procedures associated with employee protection.

Regardless of the plans, procedures, documents, and programs, each employee is responsible for the safe use of hazardous materials. Each employee is also responsible for knowing what materials are used to perform a job and for obtaining available related information.

Each employee engaged in work associated with the RI/FS project will be provided a copy of this Hazard Communication program. Employees of subcontractors to the Bechtel Team will be provided a copy of this program and a copy of the most recent hazardous materials list and any changes thereto within the period of performance of the contract. Additionally, subcontractor-designated safety representatives will be provided copies of all Material Safety Data Sheets (MSDSs) applicable to the hazardous materials list.

The following describes the requirements, procedures, training, and information applicable to the RI/FS project with regard to hazardous substances.

22.1 WARNING LABELS

Warning labels are applied to containers of hazardous substances. The warning label system used for hazardous materials is a nonstandardized system. These labels vary in appearance and content but they should, as a minimum, contain the following information:

- identity of the hazardous agent or material;
- appropriate hazard warnings; and
- name and address of the manufacturer, importer, or other responsible party.

These warning labels should be read by the employee who uses or handles hazardous materials. If the label is not understood by the employee, the material or agent is not to be used. The individual's immediate supervisor shall be contacted to determine use (safety requirements needed to handle the hazardous material).

Temporary containers or secondary containers should contain: (1) the identity of the hazardous chemicals and (2) an appropriate hazard warning. All drums containing hazardous chemicals will be marked with the NFPA Diamond. This label gives information at a glance

regarding flammability, reactivity, and degree of health hazard for the material inside the container.

The FHSS should be notified immediately if labels become defaced or damaged, and the material in the container is not to be used until the label has been restored.

22.2 HAZARDOUS MATERIALS LIST

A current list of hazardous materials used on this project is maintained at the RI/FS FOF located at ORNL, Building 6565A. This list is updated frequently. These documents are available for employee viewing or copying at the FOF. Should a hazardous material be discovered that is not contained on this list, it is to be reported to the FHSS immediately.

The potential hazardous materials located at the ORNL site within the immediate area of site work are evaluated and listed in each task specific Health and Safety Plan (HSP). Employees may view the specific HSP for the task that they are working on at the FHS office located at the FOF.

22.3 MATERIAL SAFETY DATA SHEETS (MSDS)

An MSDS is available for each hazardous agent or material used on this project. Additionally, as materials are procured or purchased for project use, MSDSs for these materials are obtained prior to acceptance, storage or use. Old or outdated MSDSs will be discarded as new safety and health data is obtained. MSDSs are discarded when the chemical they represent is no longer used or stored at the FOF.

These documents are available for employee viewing at the Field Office Facility. Upon written request, employees may receive personal copies of the MSDS for hazardous materials located in their work area.

22.4 HAZARDS OF NON-ROUTINE TASKS

It is the purpose of the project in which we are engaged to locate, characterize, and evaluate environmental and public health hazards and impacts. Therefore, field work is intensely monitored for chemical, radiological, and physical hazards. The tasks with the highest potential for encountering a hazardous material are attended full time by a qualified ES&H Specialist.

Prior to the initiation of a non-routine task, the FHSS shall conduct a briefing appropriately documented per PP 1265 "ES&H Recordkeeping" on the hazards associated

with the task and protective measures to be used. Additionally, the weekly Tool Box Safety Meeting may be used as a vehicle for the distribution of hazards data.

While engaged in field work as part of the RI/FS project, employees may encounter hazards that are not related to their work. These hazards are evaluated and listed in each task HSP. Employees may view the specific HSP for the task that they are working on at the FHS office located at the FOF.

22.5 EMPLOYEE INFORMATION AND TRAINING

While engaged in field investigations at ORNL, the following general operations use hazardous materials:

1. drilling—fuels, lubricants, alcohols;
2. sample handling and analysis—acids, sodium hydroxide solution, organic solvents, radioactive materials;
3. decontamination—detergents, alcohols, nitric acid;
4. health and safety instrument calibration—methane, isobutylene, radioactive materials, chlorinated solvents, carbon monoxide, hydrogen sulfide; and
5. housekeeping—ammonia, ethylene diamine tetra acetic acid, disinfectants, detergents.

Technique-specific tasks that require the use of hazardous materials are listed in the project procedures and/or the task specific HSP. These hazards are evaluated and listed in each task HSP. Employees may view the specific HSP for the task that they are working on at the FHS office located at the FOF.

22.6 LOCATION OF HAZARDOUS MATERIALS STORAGE

Hazardous materials are stored in appropriate and compatible containers at either the point of use or at designated issue points. Points of storage for hazardous materials are as follows:

Location	Material	Custodian
Building 6556A	Commercial and consumer cleaning supplies	Field services and support manager
Storage Trailer 1	Petroleum fuels in safety cans, isopropanol, lubricating oils, chlorine bleach, detergent powders, adhesives	Field services and support manager

Location	Material	Custodian
Storage Trailer 2	Lead bricks, stannous chloride smoke tubes, lubricating oils, residual gasoline in generators	Field services and support manager/field health and safety supervisor
Container prep	Nitric acid, sodium hydroxide, hydrochloric acid	Lab supervisor instrumentation specialist
ES&H instrument trailer	Hydrogen compressed gas, isobutylene, carbon monoxide, hydrogen sulfide, compressed air, methane, radioactive materials sources, trichlorethylene	Field health and safety supervisor
Satellite accumulation area	Up to 55 gal of hazardous wastes or up to 1 quart of acutely hazardous waste	Field health safety supervisor CONTROLLED ACCESS AREA
Special techniques lab	Biohazardous materials, carcinogenic dyes, liquid scintillation fluors, acids, bases, chromatographic standards, radioactive materials, methyl alcohol, phenols, hydrogen compressed gas, helium compressed gas	Lab supervisor/ES&H manager RESTRICTED AREA
Counting lab	P-10 compressed gas, nitrogen refrigerated liquid, radioactive materials	Lab supervisor RESTRICTED AREA
Sample prep lab	Acids, bases, volatile organic standards, scintillation fluors, organic solvents, detergents, radioactive materials	Lab supervisor RESTRICTED AREA
Decontamination trailer SWSA 6	Isopropanol, detergents, lubricating oils, radioactive materials	Decon supervisor RESTRICTED AREA

Restricted areas require the custodian's authorization for entry and may or may not require HWP sign in. Controlled Access Areas require HWP sign in and authorization by the FHSS. It must be remembered that hazardous materials may be temporarily located at points of use other than that listed above. This listing is a general guide to where hazardous materials may be found in use or in storage on a routine basis.

22.7 TRAINING

All employees engaged in field work are required to be trained per PP 1210 "ES&H Training." No employee will be allowed to enter a hazardous materials area or to work with a hazardous material without completion of the following training:

- initial site entry training—48 h,
- ORNL site orientation training—4 h,
- initial RI/FS site briefing—not less than 2 h, and
- annual refresher training (if applicable)—8 h.

Each employee is provided with a training manual containing a detailed description of the RI/FS ES&H Organization, Hazard Communication, and MSDS and how to use them. Further information on employee training is contained in PP 1210 "ES&H Training."

Per PP 1210 "ES&H Training," each employee will receive approximately 16 h of training in the use of PPE.

Initial site entry training will inform the employee of the general hazards associated with both hazardous materials used in the conduct of RI/FS work as well as the potential hazards resulting from exploration of the ORNL site reservation.

The initial RI/FS site briefing will inform employees of the specific hazards associated with the use of hazardous materials in job performance and the specific potential hazards resulting from their job task at the ORNL site.

Weekly Tool Box Safety Meetings will be used as a vehicle for communication of hazards information to the employees.

Before allowing employees to use a hazardous chemical for the first time, the supervisor is responsible for providing training on the proper handling, use, disposal, and protective measures associated with that particular chemical or agent. The FHSS is responsible for providing necessary training and for documenting that training has been provided per PP 1210 "ES&H Training" and PP 1265 "ES&H Recordkeeping." It is the responsibility of each employee to seek appropriate training prior to working with a hazardous material and to comply with all protective measures assigned to that work.

Hazard communication conducted through training will be documented per PP 1210 "ES&H Training" and PP 1265 "ES&H Recordkeeping."

22.8 ADDITIONAL EMPLOYEE PROTECTION TRAINING

On the RI/FS project, the FHSS or his designee will conduct weekly safety meetings where hazardous material data will be disseminated to the field personnel in a discussion format. The FHSS, ES&H Manager, or Field Services and Support Manager may require additional training of individual employees engaged in nonroutine tasks or those required to use nonroutine PPE. This training will be on an individual basis and will be tailored to the hazards and PPE required to safely conduct the task.

Training sessions and safety meetings will be documented per PP 1210 and 1265.

22.9 EMPLOYEE PROTECTION MEASURES

Each use of hazardous material (as defined in 29 CFR) where the employee could be exposed at or near the federally defined Permissible Exposure Limit or the Threshold Limit Value, as defined by the American Council of Governmental Industrial Hygienist, requires an HWP. Where radioactive materials are handled, where employees could be exposed at or near the DAC, or where radiation levels could exceed 2.5 mR/h, an HWP will also be required. As part of the process of issuing an HWP, protective measures, monitoring requirements, and work methods are set by ES&H in order to minimize employee exposure. Project procedures associated with this process are contained in sequence 1200 and are available for employee inspection at the FHSS office or at the ES&H Manager's office.

23. CHEMICAL HYGIENE PLAN

23.1 SCOPE AND APPLICATION

In accordance with 29 CFR 1910.1450, the chemical hygiene plan outlines the methods that the BNI Team will use to limit exposure of workers in the Closed Support Laboratory (CSL) to hazardous chemicals to ALARA levels. This plan is applicable to all activities conducted within the CSL complex where exposure to hazardous chemicals is a possibility.

This plan shall be provided to all laboratory workers and posted conspicuously in all laboratory buildings and spaces. Appendix B provides general safety principles for laboratory practice.

23.2 INITIAL AND PERIODIC MONITORING OF LABORATORIES AND WORKERS

23.2.1 Monitoring of Laboratory Spaces

Laboratories will be monitored by the ES&H Department in accordance with project procedures:

- PP 1255 "Work Area and Environmental Monitoring"
- PP 1270 "Industrial Hygiene Practice"
- PP 1270.1 "Air Surveillance of Radiological and Chemical Contaminants"
- PP 1280 "Health Physics Practices"
- PP 1280.1 "Methodology for Performing Radiological Contamination Surveys"

The work environment will be initially monitored upon the establishment of new work areas, techniques, and or the introduction of new hazardous chemicals. Continuous radiological air monitoring has been established in laboratory spaces designated for the preparation of samples for radiological procedures. At least monthly, the ES&H Department will conduct radiological and chemical surveys of each laboratory and hazardous chemical storage area. In addition, the ES&H Department will conduct spot surveys and both area and personnel air monitoring upon the initiation of new laboratory procedures or the introduction of new laboratory reagents.

23.2.2 Monitoring of Laboratory Workers

Laboratory workers shall be classified as Level 1 Access in accordance with PP 1202 "Site Access Requirements." As such, they shall be participants in the medical surveillance and bioassay programs per PP 1205 "Medical Surveillance" and PP 1280.4 "Internal Radiation

Dosimetry". External exposure to ionizing radiations will be monitored in accordance with PP 1280.3 "External Radiation Dosimetry" and PP 1280.6 "Use of Self Reading Dosimeters."

Personnel exposure to hazardous chemicals will be assessed quarterly as indicated in 23.2.1. Methods of assessment shall be in accordance with PP 1270.1 "Air Surveillance of Radiological and Chemical Contaminants."

23.3 TERMINATION OF MONITORING

Monitoring of laboratory spaces and laboratory workers for a particular hazardous chemical may be suspended or terminated upon the following:

- termination of use of hazardous chemicals, and
- sampling results demonstrate statistically that at the 95% confidence interval exposures are less than 10% of the applicable limit for the hazardous chemical or that the exposure did not exceed the action level.

The provisions above do not apply to monitoring for radioactive materials.

Termination of use shall mean that hazardous chemicals are no longer used, handled, or stored relative to CSL operations.

23.4 EMPLOYEE NOTIFICATION OF MONITORING RESULTS

The results of monitoring and surveys conducted in laboratory spaces shall be posted conspicuously in each space no later than 15 days from the date of data availability.

Employees may have access to the results of personnel monitoring results in accordance with PP 1265 "ES&H Recordkeeping."

23.5 STANDARD OPERATING PROCEDURES

All methods, protocols, techniques, and tests conducted in the CSL shall be controlled by project procedures or nationally recognized analytical procedures (EPA, NIOSH, etc.). Methods, protocols, techniques, and tests not addressed by written and approved laboratory procedure or using reagents or chemicals other than that specified by procedure are unauthorized. No unauthorized work will be conducted in the CSL.

Project procedures controlling laboratory work shall be reviewed by the ES&H Department for safety and health considerations. The Manager of ES&H shall concur on all laboratory procedures.

Appendix B contains the general principles for laboratory work safety as they apply to the CSL. While hazardous chemicals or hazardous materials are present in the laboratory spaces, these areas shall be designated CAAs and will be controlled in accordance with PP 1235 "Hazardous Work Permits." Where so designated, the HWP shall delineate health and safety requirements above the general principles of laboratory work safety.

23.6 ENGINEERED CONTROLS FOR LIMITING EXPOSURES

23.6.1 Fixed Facilities

23.6.1.1 Close Support Laboratory: Sample preparation laboratory Building 6556G

- **Potential Hazards:**

- ionizing radiation (external exposure)
- internal radionuclide deposition via inhalation and absorption
- inhalation of volatile organic compounds from contaminated compounds
- skin absorption of volatile, semivolatile, and nonvolatile organic compounds from contaminated samples
- vapors, mists and fumes resulting from the use of nitric acid, hydrochloric acid, sulfuric acid, sodium hydroxide, sodium thiosulfate, and zinc acetate
- vapors from preparation of and storage of standards and reagents used to make GC standards including toluene, benzene, xylene, trichlorethylene, and trichlorethane

- **Engineered Controls:**

- Engineered controls for the minimization of inhalation hazards are in place and functioning in this laboratory. Two operational fume hoods are located in the facility, each with a minimum of 125 lfm face velocity with the sash opening set at 14 in. The total volume of air drawn by both hoods results in > 10 total air exchanges per hour. Existing laboratory standard operating procedures (SOPs) require that all sample handling activity and chemical/physical preparations will be conducted in a hood.
- Flammable material storage cabinets are to be used to contain flammable and volatile hazardous chemicals. These cabinets shall be grounded to prevent a static electrical, ignition source. The laboratory will be a no smoking area as the cabinets are vented to the lab work area. The cabinet vents to the ambient atmosphere inside the lab because of the significant negative pressure differential between the outside and the lab.

Inorganic chemicals are stored in tightly closed containers in floor level cabinets. Acids are stored separately in an acid resistant storage cabinet.

- Fixed position alpha particle and beta/gamma particulate monitors are installed near the solids preparation hood. Alarm points for these monitors are to be set at 1 (averaged over an 8 hour period) DAC for plutonium 239 and strontium 90 respectively. Alarm conditions require evacuation of the facility and special monitoring for reentry.

23.6.1.2 Close Support Laboratory: Special techniques laboratory Building 6556F

- **Hazards:**

- ionizing radiation (external exposure)
- internal radionuclide deposition via inhalation and absorption
- inhalation of volatile organic compounds from contaminated samples
- skin absorption of volatile, semivolatile, and nonvolatile organic compounds from contaminated samples
- inhalation of volatile organic compounds from liquid scintillation counting reagents
- inhalation or injection of pathogenic bacteria and viruses from contaminated samples
- vapors from standards and reagents used to make GC standards including: toluene, benzene, xylene, trichlorethylene, and trichlorethane

- **Engineered Controls:**

- Engineered controls for the abatement of inhalation hazards are in place and functioning in this laboratory. Two operational fume hoods are located in the facility each with a minimum of 125 lfm face velocity. The total volume of air drawn by both hoods results in > 10 total air exchanges per hour. Existing laboratory SOPs require that all sample handling and work with reagents or standards will be conducted in a hood.
- Storage of flammable and volatile hazardous chemicals in quantities other than that needed for immediate use is prohibited in this facility. A laminar flow high efficiency particulate air filtered cabinet is used to isolate workers from samples and media during microbiological work. The cabinet is certified by the manufacturer for National Institute of Health level P2 isolation.

23.6.1.3 Close Support Laboratory: Radiological counting laboratory Building 6556H

- **Hazards:**

- ionizing radiation (external exposure)
- internal radionuclide deposition via inhalation and absorption

- **Engineered Controls:**

- Two fume hoods, which are not presently in use, are located in the facility and have been converted to isolated work space. Laboratory SOPs require that samples be delivered for counting in prepared and fixed form to this laboratory.
- Storage of flammable and volatile hazardous chemicals in quantities more than is needed for instrument maintenance use is prohibited in this facility. Fixed position alpha particle and beta/gamma particulate monitors are not installed in the general work area because of the fixed nature of the materials counted.

23.6.2 Verification of Engineered Controls Function

The ES&H Department will conduct weekly inspections of each fume hood for operability. The ES&H Department will make monthly measurements of face velocity on each hood to verify sash position markings and filter condition. Hoods failing to maintain required sash velocity will be removed from service until repairs are made and testing demonstrates the hood to be adequate.

23.6.3 Verification of Installed Safety Equipment

Safety equipment in each laboratory consists of A-B-C type fire extinguishers, safety shower/eye wash combinations, and first aid kits. The location of safety shower/eye wash stations will be identified by signs consistent with safety shower/eye wash station signs in use at ORNL. Barricades, signs, labels and other additional equipment will be installed as hazards are identified.

The ES&H Department will test safety shower/eye-wash combinations weekly and record the test on the form attached to each unit.

Fire extinguishers will be inspected monthly by the ES&H Department and serviced annually by the ORNL Fire Department.

First aid kits will be inspected monthly by the ES&H Department.

23.7 LABORATORY WORKER INFORMATION AND TRAINING

23.7.1 General Training Requirements

Laboratory workers will be trained as Level 1 Access personnel and will receive 40 h of basic health and safety training. Three days on-the-job training will be conducted under the supervision of the Laboratory Supervisor. These workers will also be trained by the

Laboratory Supervisor in the specific requirements of each technique or method to be conducted.

Laboratory workers will be trained initially and at annual intervals relative to the project's hazardous communications program.

23.7.2 Job Specific Chemical Agent and Technique Training

As techniques and hazardous chemical usage change in the laboratory facility, the Laboratory Supervisor and the Field Health Safety Supervisor will provide additional training as needed and appropriate. This training shall include but not be limited to:

- permissible exposure limits or recommended exposure limits (eg. TLV, short-term exposure limit) where no OSHA PEL exists for chemicals in the work area;
- signs and symptoms associated with exposure to chemicals in the work area;
- location and availability of known reference material as to the safe handling, storage, and disposal of hazardous chemicals found in the laboratory including, but not limited to, MSDSs;
- the physical and health hazards associated with chemicals in the work area;
- methods and observations that may be used to detect the presence or release of a hazardous chemical; and
- worker protective measures including protective devices and emergency measures to be used in the event of a release of hazardous chemicals in the work area.

Training shall be documented as specified in PP 1210 "ES&H Training."

23.7.3 Information Available to Workers

Laboratory workers shall have access to MSDSs via the project's hazardous communications program. Upon written request, the ES&H Department will provide MSDSs to workers and additional data concerning specific chemicals that may be handled in the lab.

23.8 MEDICAL SURVEILLANCE

All laboratory workers will participate in the project's medical surveillance program. The details of this program are contained in PP 1205 "Medical Surveillance."

23.9 PERSONAL PROTECTIVE EQUIPMENT

PPE for each laboratory operation will be specified by the HWP controlling individual laboratory spaces. As a minimum, all laboratory workers will be required to use PPE Level 1 per PP 1230 "Personal Protective Equipment."

23.10 INDIVIDUAL RESPONSIBILITIES

23.10.1 Program Manager

The RI/FS Program Manager is responsible for the overall implementation of the project's plans and procedures. The Program Manager provides continuous support to the project's chemical hygiene plan.

23.10.2 Environmental, Safety, and Health Manager

The RI/FS ES&H Manager is responsible for the implementation of the health and safety aspects of this plan. The ES&H Manager is responsible for work area and worker exposure monitoring, engineered controls evaluations and approvals, laboratory procedure review and concurrence, and industrial hygiene and health physics services to the laboratories. The ES&H Manager functions as the Chemical Hygiene Officer for the project. The ES&H Manager may delegate tasks associated with chemical hygiene to members of the ES&H professional staff and may seek guidance and assistance from the Bechtel corporate safety and health organization as necessary.

23.10.3 Analytical Services Manager

The Analytical Services Manager is responsible for the development and implementation of laboratory operating procedures, specifying laboratory equipment and materials, and ensuring compliance by the laboratory staff to all applicable project ES&H procedures and the provisions of this plan.

23.10.4 Field Services and Support Manager

The FSSM is responsible for providing maintenance and facility resources in support of this plan to the CSL complex.

23.10.5 Close Support Laboratory Supervisor

The CSL Supervisor is responsible for the daily implementation of this plan within the CSL complex. The CSL Supervisor is responsible for training the individuals under his charge in safe laboratory techniques and ensuring compliance in the laboratory with the provisions of HWPs and this plan.

23.10.6 Field Health and Safety Supervisor

The FHSS is responsible for day-to-day on-site ES&H support to the CSL complex. In that capacity the FHSS is responsible for work area and worker monitoring, issuance of HWPs associated with laboratory work, and for coordination with the CSL Supervisor on ES&H matters associated with laboratory operations.

23.10.7 Laboratory Workers

Laboratory workers are responsible for the safe conduct of laboratory operations including strict adherence to the laboratory procedures and HWP provisions. Laboratory workers are responsible for maintaining housekeeping in their respective laboratory spaces. They are also responsible for being knowledgeable about the hazardous chemicals and agents used in job performance and for obtaining information related to their safe use.

Appendix A

TANKS AND TANK LOCATIONS

Table A.1. Tanks and tank locations

Building location	Tank No.	Material	Tank/type of containment system	Tank category ^a
2026	2026A (F-401)	Fission product	SS tank/concrete vault	C
2531	C-1	Radioactive material	SS tank/concrete vault	B
2531	C-2	Radioactive material	SS tank/concrete vault	B
2537	W-22	Radioactive material	SS tank/lined concrete vault	B
2537	W-23	Radioactive material	SS tank/lined concrete vault	B
2537	W-21	Radioactive material	SS tank/lined concrete vault	B
3001	3001-S	Rad waste storage empty	SS tank/no secondary containment	D
3001	3001-B	Radioactive materials	SS tank/no secondary containment	D
3002	3002A	Filter house drainage (empty)	SS tank/concrete vault	D
3003	3003A	Rad waste hold-up tank (empty)	SS tank/no secondary containment	D
3004	3004-B	Radioactive materials	SS tank/concrete vault	D
3013	3013	Radioactive materials	SS tank/no secondary containment	D
3019	P3	Radioactive materials	SS tank/concrete vault	B

^aLEGEND:

- A: New or replacement tank system(s) with secondary containment.
- B: Existing tank system(s) with secondary containment.
- C: Existing tank system(s) without secondary containment.
- D: Existing tank system(s) without secondary containment that were removed from service before the effective date of this agreement.

Table A.1 (continued)

Building location	Tank No.	Material	Tank/type of containment system	Tank category ^a
3019	P4	Radioactive materials	SS tank/concrete vault	B
3019	N-71	Radioactive materials	SS tank/concrete vault	B
3025	WC-3	Radioactive material	SS tank/no secondary containment	C
3026	WC-4	Radioactive materials	SS tank/no secondary containment	D
3028	W-11	Radioactive materials	Unknown/no secondary containment	D
3038	WC-1	Radioactive materials	SS tank/no secondary containment	D
3039	WC-2	Radioactive material	Unknown/no secondary containment	C
3047	LA-104 (F-140)	Radioactive materials	SS tank/concrete vault	C
3047	WC-19	Radioactive materials	SS tank/no secondary containment	C
3500	TH-4	Radioactive materials	Concrete/no secondary containment	D
3503	TH-1	Radioactive materials	SS tank/no secondary containment	D
3503	TH-2	Radioactive materials	SS tank/no secondary containment	D

^aLEGEND:

- A: New or replacement tank system(s) with secondary containment.
- B: Existing tank system(s) with secondary containment.
- C: Existing tank system(s) without secondary containment.
- D: Existing tank system(s) without secondary containment that were removed from service before the effective date of this agreement.

Table A.1 (continued)

Building location	Tank No.	Material	Tank/type of containment system	Tank category ^a
3503	TH-3	Radioactive materials	SS tank/no secondary containment	D
3503	WC-5	Radioactive material	SS tank/no secondary containment	D
3503	WC-6	Radioactive material	SS tank/no secondary containment	D
3503	WC-8	Radioactive material	SS tank/no secondary containment	D
3503	WC-9	Radioactive material	SS tank/no secondary containment	C
3504	WC-7	Radioactive materials	SS tank/no secondary containment	C
3505	H-209	Radioactive materials	SS tank/no secondary containment	D
3517	W-19	Cleaned out (emptied)	SS tank/no secondary containment	D
3517	W-20	Cleaned out (emptied)	SS tank/no secondary containment	D
3517	S-223	Radioactive materials	SS tank/epoxy lined concrete vault	B
3517	S-324	Radioactive materials	SS tank/epoxy lined concrete vault	B

^aLEGEND:

- A: New or replacement tank system(s) with secondary containment.
- B: Existing tank system(s) with secondary containment.
- C: Existing tank system(s) without secondary containment.
- D: Existing tank system(s) without secondary containment that were removed from service before the effective date of this agreement.

Table A.1. (continued)

Building location	Tank No.	Material	Tank/type of containment system	Tank category ^a
3517	S-523	Radioactive materials	SS tank/epoxy lined concrete vault	B
3517	S-424	Radioactive materials	Glass lined carbon steel/epoxy lined concrete vault	D
3525	F-201	Radioactive materials	SS tank/concrete vault	C
3525	F-501	Radioactive materials	Stainless steel tank/unlined concrete vault	C
3544	L-11 (3544M)	Radioactive material	Drain flows to B.V. storage tanks; 750K capacity	B
3587	WC-10	Radioactive material	SS tank/no secondary containment	C
3587	WC-11	Radioactive material	SS tank/no secondary containment	D
3587	WC-12	Radioactive material	SS tank/no secondary containment	D
3587	WC-13	Radioactive material	SS tank/no secondary containment	D
3587	WC-14	Radioactive material	SS tank/no secondary containment	D

^aLEGEND:

- A: New or replacement tank system(s) with secondary containment
- B: Existing tank system(s) with secondary containment
- C: Existing tank system(s) without secondary containment
- D: Existing tank system(s) without secondary containment that were removed from service before the effective date of this agreement.

Table A.1. (continued)

Building location	Tank No.	Material	Tank/type of containment system	Tank category ^a
3587	WC-15	Residual radioactive contents	SS tank/no secondary containment	D
3587	WC-17	Residual radioactive contents	SS tank/no secondary containment	D
4501	4501D	Radioactive material low-level U	2-in concrete elevation	D
4501	4501C	Depleted U as UO ₂ SO ₄ -solution; 8 gram PU(239) as PU(SO ₄) ₂ -solution	SS tank/concrete vault	D
4501	4501-P	50% U-232/25% AM-241/25% V-233	SS tank/no secondary containment	D
4507	T-30	Radioactive materials	SS tank/concrete vault	D
7500	7560	Radioactive materials	SS tank/no secondary containment	D
7500	7562	Radioactive materials	SS tank/no secondary containment	D
7503	7503A	Radioactive material	SS tank/concrete vault	D
7567	T-1	Radioactive material	SS tank/no secondary containment	C
7567	T-2	Radioactive material	SS tank/no secondary containment	C

^aLEGEND:

- A: New or replacement tank system(s) with secondary containment.
 B: Existing tank system(s) with secondary containment.
 C: Existing tank system(s) without secondary containment.
 D: Existing tank system(s) without secondary containment that were removed from service before the effective date of this agreement.

Table A.1. (continued)

Building location	Tank No.	Material	Tank/type of containment system	Tank category ^a
7569	WC-20	Radioactive material	SS tank/lined concrete vault	B
7830	W-24	Radioactive material	SS tank/lined concrete vault	B
7830	W-25	Radioactive material	SS tank/lined concrete vault	B
7830	W-26	Radioactive material	SS tank/lined concrete vault	B
7830	W-27	Radioactive material	SS tank/lined concrete vault	B
7830	W-28	Radioactive material	SS tank/lined concrete vault	B
7830	W-29	Radioactive material	SS tank/lined concrete vault	B
7830	W-30	Radioactive material	SS tank/lined concrete vault	B
7830	W-31	Radioactive material	SS tank/lined concrete vault	B
7860	T-13	Radioactive materials	Stainless steel tank/stainless steel-lined vault	B
7860	T-14	Radioactive material	Unlined concrete tank	D
7910	HFIR (7910A)	Radioactive material	SS tank/encased concrete vault	C
7920	F-111	Radioactive decay tank primarily basic aqueous solutions	SS tank/epoxy lined concrete vault	B

^aLEGEND:

- A: New or replacement tank system(s) with secondary containment
 B: Existing tank system(s) with secondary containment.
 C: Existing tank system(s) without secondary containment.
 D: Existing tank system(s) without secondary containment that were removed from service before the effective date of this agreement.

Table A.1 (continued)

Building location	Tank No.	Material	Tank/type of containment system	Tank category ^a
7920	F-126	Radioactive material	SS tank/epoxy lined concrete vault	B
7932	B-2-T	Rad waste collection dilute HN03	SS tank/sealed concrete pit w/monitored sump	B
7932	B-3-T	Rad waste collection dilute HN03	SS tank/sealed concrete pit w/monitored sump	B
7932	C-6-T	Rad waste collection		B
N Tank Farm	W-1	Residual radioactive contents	Concrete tank/no secondary containment	D
N Tank Farm	W-1A	Residual radioactive contents	SS tank/no secondary containment	D
N Tank Farm	W-2	Residual radioactive contents	Concrete tank/no secondary containment	D
N Tank Farm	W-3	Residual radioactive contents	Concrete tank/no secondary containment	D
N Tank Farm	W-4	Residual radioactive contents	Concrete tank/no secondary containment	D
N Tank Farm	W-13	Residual radioactive contents	SS tank/no secondary containment	D
N Tank Farm	W-14	Residual radioactive contents	SS tank/no secondary containment	D

^aLEGEND:

- A: New or replacement tank system(s) with secondary containment.
- B: Existing tank system(s) with secondary containment.
- C: Existing tank system(s) without secondary containment.
- D: Existing tank system(s) without secondary containment that were removed from service before the effective date of this agreement.

Table A.1 (continued)

Building location	Tank No.	Material	Tank/type of containment system	Tank category ^a
N Tank Farm	W-15	Residual radioactive contents	SS tank/no secondary containment	D
Old Hydrofracture	T1	Residual radioactive contents	SS tank/no secondary containment	D
Old Hydrofracture	T2	Residual radioactive contents	SS tank/no secondary containment	D
Old Hydrofracture	T3	Residual radioactive contents	SS tank/no secondary containment	D
Old Hydrofracture	T4	Residual radioactive contents	SS tank/no secondary containment	D
Old Hydrofracture	T9	Residual radioactive contents	SS tank/no secondary containment	D
S Tank Farm	W-05	Residual radioactive contents	Gunitite tank/no secondary containment	D
S Tank Farm	W-06	Residual radioactive contents	Gunitite tank/no secondary containment	D
S Tank Farm	W-07	Residual radioactive contents	Gunitite tank/no secondary containment	D
S Tank Farm	W-08	Residual radioactive contents	Gunitite tank/no secondary containment	D
S Tank Farm	W-09	Residual radioactive contents	Gunitite tank/no secondary containment	D

^aLEGEND:

- A: New or replacement tank system(s) with secondary containment.
- B: Existing tank system(s) with secondary containment.
- C: Existing tank system(s) without secondary containment.
- D: Existing tank system(s) without secondary containment that were removed from service before the effective date of this agreement.

Table A.1 (continued)

Building location	Tank No.	Material	Tank/type of containment system	Tank category ^a
S Tank Farm	W-10	Residual radioactive contents	Gunitite tank/no secondary containment	D
S Tank Farm	W-12	Radioactive material	SS tank/no secondary containment	D
S Tank Farm	W-16	Radioactive material	SS tank/no secondary containment	C
S Tank Farm	W-17	Radioactive material	SS tank/no secondary containment	D
S Tank Farm	W-18	Radioactive material	SS tank/no secondary containment	D
S Tank Farm	W-11	Residual radioactive contents	Gunitite tank/no secondary containment	D

LEGEND:

- A: New or replacement tank system(s) with secondary containment.
 B: Existing tank system(s) with secondary containment.
 C: Existing tank system(s) without secondary containment.
 D: Existing tank system(s) without secondary containment that were removed from service before the effective date of this agreement.

Appendix B

GENERAL SAFETY PRINCIPLES FOR LABORATORY PRACTICE

Appendix B

GENERAL SAFETY PRINCIPLES FOR LABORATORY PRACTICE

The following constitute the general safety rules for operations conducted in the CSL complex. Additional provisions, restrictions, and/or requirements may be found in the HWP controlling area operations and the individual laboratory procedures. These principles are in addition to other established safety work rules currently in force.

Avoidance of "Routine" Exposures

- Eating, drinking, use of tobacco or cosmetics are not permitted in any laboratory space. Food, cosmetics, and beverages shall not be stored in laboratory spaces.
- Spills of chemicals or sample materials are to be reported to the FHSS immediately. Upon notifications, the FHSS shall contact the ES&H Manager and ORNL Laboratory Shift Supervisor. In the event of a spill of hazardous chemicals or radioactive materials, the laboratory is to be evacuated and ES&H notified. If possible, the spill should be stopped and contained.
- Chemicals are not to be smelled or tasted. Apparatus that discharge toxic vapors or gasses are to be operated in a fume hood or vented to a hood sash.
- Pipetting or starting a siphon shall not be performed by mouth.
- Fume hoods (where installed) are to be operated whenever the laboratory spaces are occupied.
- Continuous air monitors (where installed) are to be operated whenever radioactive materials are present in the laboratory spaces.

Selection of Chemicals and Methods

- Procedures shall be developed so that chemicals of lowest hazard are used where practical.
- Laboratory procedures, equipment, and instruments shall be selected, procured, or developed so that hazardous chemical discharge and safety hazards are minimized.

Equipment and Glassware

- Damaged glassware and equipment are not to be used.
- Evacuated glassware such as dewar flasks are to be handled with care. Dewars not equipped with fragmentation protection (armor) are not to be used in the CSL.
- All used glassware is to be considered contaminated with hazardous agents until decontaminated.
- Under no circumstances will laboratory glassware be used for the preparation or consumption of foodstuffs or beverages.

Personal Protective Equipment

- Level 1 PPE is to be used by all workers in the laboratory complex. Use of basic eye protection is required at all times. Use of safety shoes is mandatory.
- Appropriate gloves are to be used whenever chemicals or samples are being handled. Gloves shall be inspected/tested before each use.
- Contact lenses are forbidden in laboratory spaces.
- Additional PPE as specified in the controlling HWP is mandatory.

Housekeeping

- Work areas are to be kept clean and uncluttered. Work areas are to be clean and orderly at the completion of each day's operation.
- All chemicals and apparatus are to be clearly and properly labeled.

Unattended Operations

- Only automatic or computer-supervised systems that are fail safe shall be permitted to operate unattended.

Use of Fume Hoods

- Fume hood use is mandatory at any time that work is conducted with unknown materials or when working with chemicals with a PEL or TLV of 50 ppm or less.
- Fume hoods use is mandatory for any operation that might release toxic vapors, fumes, mists, dusts, or gases.
- Ready stocks of hazardous chemicals shall be kept in fume hoods or in specified cabinets.
- When not in use, hoods shall be on and sashes closed while the laboratory space is occupied.

Waste Materials and Waste Management

- No waste material containing toxic materials, explosive or reactive materials, or concentrated acids or bases shall be discharged into the laboratory drains. These materials are to be collected separately and handled in accordance with PP 1401 "Waste Categorization" and PP 1402 "Waste Handling."
- Spills, accidents, and emergencies shall be responded to in accordance with PP 1406.

DISTRIBUTION

1. L. V. Asplund/N. W. Durfee
2. L. D. Bates
3. T. W. Burwinkle
4. C. Clark
5. J. S. Colley
6. K. W. Cook
7. S. Defalco
8. J. T. Etheridge
9. S. B. Garland II
10. C. D. Goins
11. L. D. Hyde
- 12-16. L. L. Kaiser
17. A. J. Kuhaida
18. J. R. Lawson
19. L. E. May
20. L. E. McNeese
- 21-22. P. T. Owen
23. P. A. Schrandt
24. D. W. Swindle
25. G. E. Rymer
26. R. K. White
27. A. S. Will III
28. Central Research Library
- 29-30. Laboratory Records Dept.
- 31-35. ER Document Management Center
36. Office of Assistant Manager for Energy Research and Development, Department of Energy Field Office, Oak Ridge, P.O. Box 2001, Oak Ridge, TN 37831-8600
- 37-41. J. R. Kannard, Program Manager, Rechtel National, Inc., P.O. Box 350, Oak Ridge Corporate Center, 151 Lafayette Drive, Oak Ridge, TN 37831-0350
42. P. H. Edmonds, Radian Corporation, 120 South Jefferson Circle, Oak Ridge, TN 37830
- 43-46. W. E. Murphie, Department of Energy, Office of Environmental Restoration, Eastern Area D&D Branch, EM-423 (GTN), Washington, DC 20545
- 47-48. S. S. Perkins, DOE Field Office, Oak Ridge, Information Resource Center, Administrative Record File, 105 Broadway, Oak Ridge, TN 37830
- 49-50. S. P. Riddle, Department of Energy Field Office, Oak Ridge, P.O. Box 2001, Oak Ridge, TN 37831-8541
- 51-52. R. C. Sleeman, Department of Energy Field Office, Oak Ridge, P.O. Box 2001, Oak Ridge, TN 37831-8541
53. J. T. Sweeney, Department of Energy Field Office, Oak Ridge, P.O. Box 2001, Oak Ridge, TN 37831-8541
- 54-55. Office of Scientific and Technical Information, P.O. Box 62, Oak Ridge, TN 37831

END

**DATE
FILMED
4 127 192**