MARTIN MARIETTA

ORNL/ER-63

**ENVIRONMENTAL
RESTORATION
PROGRAM**

MAY 11 1992

**Annual Summary Report on
Surveillance and Maintenance
Activities of Waste Area
Groupings at Oak Ridge National
Laboratory for Period Ending
September 30, 1991**

M. K. Ford
L. Holder, Jr.
R. G. Jones

ENERGY SYSTEMS

MANAGED BY
MARTIN MARIETTA ENERGY SYSTEMS, INC.
FOR THE UNITED STATES
DEPARTMENT OF ENERGY

UCN-17560 (6 7-91)

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

This report has been reproduced directly from the best available copy.

Available to DOE and DOE contractors from the Office of Scientific and Technical Information, P.O. Box 62, Oak Ridge, TN 37831; prices available from 615-576-8401, FTS 626-8401.

Available to the public from the National Technical Information Service, U.S. Department of Commerce, 5285 Port Royal Rd., Springfield, VA 22161.

ORNL/ER--63

DE92 008762

Environmental Restoration Division
ORNL Environmental Restoration Program

**Annual Summary Report on Surveillance and Maintenance
Activities of Waste Area Groupings at Oak Ridge
National Laboratory for Period Ending
September 30, 1991**

**M. K. Ford
L. Holder, Jr.
R. G. Jones**

Manuscript Completed—October 1991
Date Issued—December 1991

Prepared by
Office of Waste Management and Remedial Actions
Oak Ridge National Laboratory

Prepared for
U.S. Department of Energy
Office of Environmental Restoration and Waste Management
under budget and reporting codes EW 20 and EX 20

OAK RIDGE NATIONAL LABORATORY
Oak Ridge, Tennessee 37831-6285
managed by
MARTIN MARIETTA ENERGY SYSTEMS, INC.
for the
U.S. DEPARTMENT OF ENERGY
under contract DE-AC05-84OR21400

MASTER

gmb

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

Author Affiliations

M. K. Ford, L. Holder, Jr., and R. G. Jones are members of the Office of Waste Management and Remedial Actions at the Oak Ridge National Laboratory, Martin Marietta Energy Systems, Inc.

CONTENTS

TABLES	v
EXECUTIVE SUMMARY	vii
1. INTRODUCTION	1
2. SURVEILLANCE AND MAINTENANCE PLANNING	2
2.1 ENVIRONMENTAL, SAFETY, AND HEALTH UPGRADES	2
2.2 SITE-SPECIFIC SCOPING SURVEYS	2
2.2.1 White Wing Scrap Yard	2
2.2.2 Building 9204-1	3
2.2.3 Trench 6	3
2.2.4 Trench 5	3
3. ROUTINE SURVEILLANCE AND MAINTENANCE	3
3.1 ROUTINE SITE SURVEILLANCE	3
3.1.1 Solid Waste Storage Areas	4
3.1.2 Pits and Trenches	4
3.1.3 Building 7835 Sludge Waste Pond	4
3.1.4 North and South Tank Farms	4
3.1.5 Tank 7860A	5
3.1.6 Old Hydrofracture Facility Liquid Waste Tanks	5
3.1.7 Preliminary Hazard Screening	5
3.1.8 Miscellaneous Vegetation Maintenance and Cleanup	5
3.1.9 White Wing Scrap Yard and Chestnut Ridge	6
3.1.10 0800 Environmental Research Area	6
3.1.11 White Oak Creek Embayment Sediment-Control Structure	6
3.1.12 Building 3001 Storage Canal Surveillance and Maintenance	7
3.1.13 Groundwater Well Sampling	7
3.1.14 HRE Underground Storage Tanks Surveillance and Maintenance ...	7
3.2 SURVEILLANCE DATA FOR INACTIVE WASTE STORAGE TANKS	7
4. SPECIAL MAINTENANCE PROJECTS	13
4.1 CONTAMINATED GROUNDWATER COLLECTION AND TREATMENT	13
4.2 GUNITE TANK CONTINGENCY PLAN	15
4.3 ISOLATION OF WATERFOWL FROM PROCESS PONDS	15
4.4 CONTAMINATED SITES FENCING	15
4.4.1 White Wing Scrap Yard	15

4.4.2 Chestnut Ridge Environmental Research Sites	15
4.5 BUILDING 3001 STORAGE CANAL SOURCE REMOVAL	16
5. SUMMARY	17

TABLES

1	South Tank Farm surveillance data—FY 1991	8
2	North Tank Farm surveillance data—FY 1991	10
3	Old Hydrofracture Facility surveillance data—1991	11
4	Main plant area surplus tanks surveillance data—1991	12
5	Fugitive waste collected in FY 1991	14

EXECUTIVE SUMMARY

Surveillance and maintenance (S&M) of 75 sites were conducted by the Remedial Action Section for the Environmental Restoration Program for surplus facilities and sites contaminated with radioactive materials and/or hazardous chemicals. S&M activities on these sites were conducted from the end of their operating life until final facility disposal or site stabilization. The objectives of the Waste Area Grouping S&M Program are met by maintaining a program of routine S&M as well as by implementing interim corrective maintenance when deemed necessary as a result of site surveillance. This report briefly presents this program's activities and includes tables indicating tank levels and dry well data for FY 1991.

1. INTRODUCTION

The Environmental Restoration (ER) Program at Oak Ridge National Laboratory (ORNL) was designed for the management of surplus facilities and sites contaminated with radioactive materials and/or hazardous chemicals. Surveillance and maintenance (S&M) activities on these sites are being conducted from the end of their operating life until final facility disposition or site stabilization. The Waste Area Grouping (WAG) S&M Program is an integral part of the ER Program, with the objective of ensuring adequate containment and site control at the inactive waste management and environmental research sites and facilities under its control. The objectives are met by maintaining a structured program of routine S&M as well as by implementing interim corrective maintenance when deemed necessary as a result of site surveillance. These activities provide assurance that adequate site control is achieved during remedial investigations and feasibility studies until final site decommissioning or closure is accomplished. Program activities are conducted in four principal areas:

1. S&M planning—planning of surveillance schedules, evaluation of surveillance information, supervision of routine and special maintenance, and routine reporting;
2. routine S&M—scheduled site inspections, sampling and analysis of contaminated pathways, and periodic maintenance as a result of inspections and monitoring;
3. collection and treatment of contaminated groundwater—support for collection and treatment of groundwater that has infiltrated liquid-waste collection systems and contaminated facilities; and
4. special maintenance—correction of serious site deficiencies beyond the scope of routine maintenance.

The inventory of sites supported by the S&M Program includes a variety of former waste management areas, environmental research sites, and areas of incidental contamination from past operations. The list contains about 75 sites including 5 solid waste storage areas (SWSAs); the areas of SWSA 6 where interim corrective measures have been required; 7 liquid low-level waste (LLLW) seepage pits and trenches; White Oak Creek (WOC), White Oak Lake (WOL), and associated tributaries; 39 LLLW line leak sites; 14 environmental research sites; a closed landfill and scrapyard; 2 abandoned injection wells; and 4 other sites.

2. SURVEILLANCE AND MAINTENANCE PLANNING

The purpose of the S&M planning subtask is to establish and maintain an organized and systematic program of S&M. In addition to fulfilling routine reporting requirements, this element also ensures that all of the other S&M subtasks are integrated into a safe, responsive, and cost-effective effort to meet the program objectives.

2.1 ENVIRONMENTAL, SAFETY, AND HEALTH UPGRADES

The Tiger Team assessment was completed at the beginning of FY 1991. Activities to correct deficiencies were identified, and efforts to maintain a level of inactive-facility management consistent with all regulations and best management practices continued during the year. Particular attention has been given to ensure adequate environmental, safety, and health (ES&H) planning and documentation. Adherence to the Quality Assurance Standards for Nuclear Facilities plan has been emphasized during all S&M activities, as well as compliance with all other requirements of Martin Marietta Energy Systems, Inc., and the U.S. Department of Energy (DOE) (e.g., proper issuance of radiation work permits, safety work permits, and environmental review documents).

2.2 SITE-SPECIFIC SCOPING SURVEYS

Surveys are being conducted at selected contaminated sites by a team from the Measurement Applications and Development Group of the Health and Safety Research Division. High-priority sites and their surroundings are surveyed to determine the presence, nature, and extent of radiological and/or hazardous chemical surface contamination. The surveys typically consist of walkover meter surveys with limited soil sampling where required. Results from the surveys are used to establish a baseline of current conditions for planning S&M for previously uncharacterized sites. This information is also used to determine if the need exists for immediate special maintenance action to correct hazards to personnel or to avoid potential environmental risk.

2.2.1 White Wing Scrap Yard

After the discovery of some contaminated scrap metal at the White Wing Scrap Yard in November 1989 (see Sects. 3.1 and 4.5.1), a scoping survey was initiated. Plans were made to survey accessible areas first. While results of this effort have been issued, more intensive surveying was completed; these findings were published as an addendum to the first report. Initial measurements indicated that widespread surface contamination existed at the site. Clusters of small localized radioactive hot spots were found throughout most of the accessible areas, with the highest surface gamma exposure rates reaching 3.6 mR/h. Gamma spectrometric analysis of debris found at the north end of the site showed high concentrations of ^{238}U and unnaturally high concentrations of ^{235}U in two slag/rock/metal samples. A small area of surface subsidence revealed portions of buried 55-gal metal drums. On the west side of WAG 11, outside the rope boundary, elevated gamma levels

of 19 to 28 $\mu\text{R/h}$ were found to follow a wet-weather stream for at least 200 ft, which was the limit of the survey. An anomalous region, contiguous with this stream, was found to exhibit gamma exposure rates ranging from 13 to 38 $\mu\text{R/h}$. A biased soil sample was collected from this region and submitted for analysis.

2.2.2 Building 9204-1

The report *Results of a Radiological Scoping Survey of Building 9204-1 at Y-12* (ORNL/ER-38) was approved for publication.

2.2.3 Trench 6

The report *Surface Radiological Investigation of Trench 6 and Low Level Waste Line Leak Site 7.4b at the Oak Ridge National Laboratory, Oak Ridge, Tennessee* (ORNL/ER-37) has been submitted for approval and publication.

2.2.4 Trench 5

The University of Tennessee thesis "Surface Radiological Investigation at Trench 5: A Waste Disposal Site" was approved and published. The thesis has been converted to an ER report [*Surface Radiological Investigation at Trench 5 in Waste Area Grouping 7 at the Oak Ridge National Laboratory, Oak Ridge, Tennessee* (ORNL/ER-37)] and is in the approval cycle.

3. ROUTINE SURVEILLANCE AND MAINTENANCE

3.1 ROUTINE SITE SURVEILLANCE

Routine surveillance activities were conducted as scheduled at inactive waste management areas and other contaminated sites during the reporting period. In addition to routine radiological surveillance activities, detailed site inspections were conducted each week at the SWSAs, the pits and trenches, and other sites where warranted. These inspections focused on perimeter fences and barrier chains, vegetation, diversion systems, warning signs, access roads, asphalt caps, housekeeping, and general site appearance. Thorough attention was given to the surface areas of SWSAs 4 and 5 for the presence of subsided trenches because of the hazards they present to grounds maintenance personnel and equipment. Results of these inspections were logged on checklists and archived for future reference.

3.1.1 Solid Waste Storage Areas

Two large subsidences developed across the access road in SWSA 5 south, probably initiated by the heavier-than-normal rain experienced this year. The subsidences were filled with gravel, and no spread of contamination resulted. The diversion ditch on Lagoon Road opposite SWSA 4 was found to be ruptured, allowing runoff to return through potentially contaminated soil. A temporary bypass was installed to allow the affected area to dry out, after which temporary repairs were made. Preliminary cost estimates for repairing sections of the asphalt ditch have been completed. Planning for future implementation of improvements is currently under way.

A statement of work and a request for quotation for the inspection and repair of the high-density polyethylene liners that cover the Resource Conservation and Recovery Act (RCRA)-regulated areas in SWSA 6 were prepared, quotations were received and evaluated, and the contracts awarded. Routine inspections and repairs have been made. The inspection report by the contractor has been received and approved. Storm event and high-to-low temperature transition (47°F) inspections of the RCRA-capped areas in SWSA 6 were performed. No damage or detrimental effects were observed.

3.1.2 Pits and Trenches

Perimeter fences and warning placards were repaired and upgraded at Pits 2, 3, and 4, and articles of abandoned waste were removed in the ongoing effort to maintain acceptable site conditions. In addition, radiation hazard signs around WOC and WOL were replaced.

3.1.3 Building 7835 Sludge Waste Pond

Improvements were made to the fence at the Building 7835 Sludge Waste Pond to restrict access to the contaminated site. New signs were installed, and the gate was made more secure. A review of this WAG 5 sludge pond was conducted by ORNL Environmental Compliance staff to evaluate the status of inventory containment. Results of the review indicated that no additional actions are needed at this time.

3.1.4 North and South Tank Farms

Approximately 4500 gal of LLLW was transferred from inactive tank W-3 to the active LLLW system. Tank W-3 slowly collects inleakage and requires infrequent reduction in inventory as indicated by tank level surveillance.

Instrumentation and Controls Division maintenance staff have replaced a number of instrument air gages in the South Tank Farm with up-to-date units. The replaced units were still working but were very old and difficult to read because of deteriorated faces. New instrumentation has been received, and installation has been completed in the North and South Tank Farm dry wells. Viton boots on the outgassing system have been replaced.

Contaminated soil found in the South Tank Farm was removed and disposed of in SWSA 6. The soil was removed to prevent migration by wind, water, or accidental tracking.

3.1.5 Tank 7860A

Interim procedures and on-the-job training were developed to expand the inspections of Tank 7860A, an inactive tank that contains mixed waste, from 5 to 7 days per week. On-the-job training was completed for Waste Management Operations staff to perform weekend surveillance. Contents were removed in response to a DOE Tiger Team compliance finding that indicated past noncompliance with RCRA. The mixed-waste oil has been transferred to Tank 7630, and daily inspections are continuing.

3.1.6 Old Hydrofracture Facility Liquid Waste Tanks

A new compressor has been ordered, received, and installed to replace the old unit at the Old Hydrofracture Facility to operate tank level instrumentation. Age and wear determined replacement at this time. Air leaks were repaired throughout the piping systems.

3.1.7 Preliminary Hazard Screening

Preliminary hazard screening work sheets were completed for the following facilities: North Tank Farm; South Tank Farm; Waste Holding Basin; LLLW Pits 1 through 4; LLLW Trenches 5 through 7; 0800 cesium-contaminated field; and process waste sludge pond. The preliminary hazard (PH) screening process has led to the conclusion that the hazards in the facilities are benign or standard industrial hazards and that no further safety analysis is required except for the 3513 Waste Holding Basin, and the 3023 North and 3027 South Tank farms. The ORNL Safety Engineering Division has reviewed and approved all category 5 PHs and are assisting in conducting a hazard-screening analysis for the Waste Holding Basin and tank farms.

3.1.8 Miscellaneous Vegetation Maintenance and Cleanup

Two contaminated trees, a crab apple and a large red oak, were removed from the main plant area and disposed of in SWSA 6. The removal was performed to prevent further dropping of contaminated leaves in and around pedestrian thoroughfares. Contaminated shrubbery was discovered just north of the 3023 North Tank Farm during routine maintenance. Removal planning and environmental review and documentation were completed. All shrubs were removed and disposed of as solid low-level waste. The area was cleaned and covered with rock. A third area of recently discovered radioactive surface contamination was discovered south of Building 3019 on Hillside Avenue. It was cleaned up and remediated by removing soil and vegetation associated with a former LLLW line leak site. The area was covered with plastic and river rock (for aesthetic enhancement). This action was taken to prevent spread of contamination and to eliminate the need for maintenance and control of contaminated vegetation.

3.1.9 White Wing Scrap Yard and Chestnut Ridge

Four abandoned drums and other debris were removed from a creek at the White Wing Scrap Yard. Detectable contamination was found on one of the drums and on a 5-gal bucket. These two items were disposed of as solid low-level waste, and the rest of the material was disposed of as routine uncontaminated rubble. This action was taken as part of the effort to correct ES&H deficiencies at the site.

The perimeters of White Wing Scrap Yard and the Chestnut Ridge sites were roped off as a temporary measure to exclude hunters from the sites. Erection of chain link fences is planned in order to provide more positive access control. National Environmental Policy Act (NEPA) document approval is needed for construction of this fencing; however, approval by DOE Headquarters is needed to ensure erection of the fence by next fall's deer hunting season. The project is on hold pending NEPA approval. A rare plant and wetlands survey has been conducted. Energy Systems Engineering is developing a drawing that plots coordinates to reflect the wetlands area with respect to the planned fence routing.

Vegetation cleanup was completed at the inaccessible areas at White Wing Scrap Yard, thereby allowing the surface radiological investigations to be completed.

Small animal feeders left from pre-1970 experiments at the Chestnut Ridge sites have been removed and disposed of at SWSA 6. A letter that requests that the previously approved categorical exclusion for barbed wire fence installation be applied to the installation of chain-link fencing has been approved and issued. This documents the upgrading of the fence without further NEPA review. The 90% design review is underway to determine the most acceptable approach for construction.

3.1.10 0800 Environmental Research Area

The areas inside the chains surrounding the ^{137}Cs -contaminated plots at the 0800 Environmental Research Area were expanded to facilitate vegetation maintenance. These areas can now be mowed by using riding equipment, greatly reducing mowing time and promoting the ALARA (as low as reasonably achievable) principle.

3.1.11 White Oak Creek Embayment Sediment-Control Structure

Weekly and annual inspection procedures have been drafted for the White Oak Creek Embayment Sediment-Control Structure, which will be completed early in FY 1992. Weekly inspections will be performed in conjunction with the weekly site inspections of Environmental Restoration Program controlled areas and will be instituted upon construction completion. Annual inspections will be conducted at times of lowest water level. The key to the access gates will be controlled by the Office of Waste Management and Remedial Action Facility Manager. Repairs to the structure areas will be undertaken as needs are identified through routine surveillance.

3.1.12 Building 3001 Storage Canal Surveillance and Maintenance

Calibrations were performed on instrumentation for continuous monitoring of water quality and for grab samples used for rough determinations of contaminants in the canal water. Also, quality verification tests were performed for both service cranes, and new parts were installed on the monorail crane. The filtering system for canal ventilation was tested for particulate efficiency. Several decontaminations were performed in the canal area following the source removal project. Trends of radiological surveys taken prior to the source removal and following the decontamination work show similar levels.

Records management was enhanced for the storage canal surveillance performed daily by compliance to RCRA requirements. A change in format of log entries to include more information to identify personnel preparing the check was completed.

3.1.13 Groundwater Well Sampling

Sampling and analysis of 12 groundwater wells around the Homogeneous Reactor Experiment, the Old Hydrofracture Facility, and the 3513 Waste Holding Basin were completed this report period. All samples indicate that conditions have not changed, and all constituents determined during the last report period are in rough agreement with prior samplings both quantitatively and qualitatively.

3.1.14 HRE Underground Storage Tanks Surveillance and Maintenance

All surveillance data gathered on monthly site visits to the inactive underground LLLW tanks at the Homogeneous Reactor Experiment indicated normal trends and a continued integrity of the tank and proper access control.

3.2 SURVEILLANCE DATA FOR INACTIVE WASTE STORAGE TANKS

Surveillance data for the inactive waste storage tanks for FY 1991 are compiled in Tables 1 through 4.

Table 1. South. Tank Farm surveillance data—FY 1991

	SEP 90	OCT	NOV	DEC	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP	
	=====													
Gunite Tank Levels (avg. gal) (+/- from previous month)														RECAL.* INSTR.
W-5 (capacity 170,000 gal)	29,683	29,626 (57)	29,638 12	30,043 405	31,564 1,521	32,919 1,355	33,447 528	33,407 (40)	33,526 119	33,812 286	33,940 128	18,077 (15,863)	18,026 (51)	
W-6 (capacity 170,000 gal)	112,305	112,294 (11)	112,262 (32)	113,168 906	116,120 2,952	118,430 2,310	119,480 1,050	119,620 140	119,810 190	120,420 610	120,600 180	109,800 (10,800)	109,905 105	
W-7 (capacity 170,000 gal)	17,712	17,619 (93)	Lo Fail	17,600 17,600	18,000 400	Lo Fail	Lo Fail	Lo Fail	Lo Fail	5,942 5,942	7,123 1,181	5,305 (1,818)	5,309 4	
W-8 (capacity 170,000 gal)	49,377	49,416 39	49,421 5	49,841 420	51,390 1,549	52,510 1,120	52,974 464	52,946 (28)	52,950 4	52,599 (351)	53,209 610	44,970 (8,239)	44,923 (47)	
W-9 (capacity 170,000 gal)	38,829	38,880 51	39,069 189	39,423 354	40,218 795	38,940 (1,278)	29,680 (9,260)	29,665 (15)	29,724 59	31,080 1,356	31,223 143	34,211 2,988	34,223 12	
W-10 (capacity 170,000 gal)	103,164	103,097 (67)	103,203 106	103,429 226	103,990 561	105,230 1,240	105,740 510	105,940 200	106,420 480	106,890 470	107,010 120	96,288 (10,722)	96,162 (126)	
TOTAL VOLUME (average gal (+/- from previous month)	351,070	350,932 (138)	333,593 (17,339)	353,504 19,911	361,282 7,778	348,029 (13,253)	341,321 (6,708)	341,578 257	342,430 852	350,743 8,313	353,105 2,362	308,651 (44,454)	308,548 (103)	
W-11 (capacity 1,500 gal) (+/- from previous month)	264	264 0	264 0	352 88	616 264	858 242	924 66	924 0	264** (660)	278 14	286 8	308 22	286 (72)	

Table 1 (continued)

	SEP 90	OCT	NOV	DEC	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP
Gunite Tank Dry Wells (Gross beta Bq/ml)													
W-5	0.45	0.37	0.14	0.88	0.69	0.83	0.72	0.42	0.36	1.09	DRY	DRY	0.45
W-6	DRY	3.75	0.96	0.63	0.27	0.30	0.40	0.21	0.92	0.81	0.81	0.86	0.80
W-7	DRY	DRY	DRY	9.28	5.17	6.61	7.03	3.34	DRY	8.00	DRY	DRY	2.80
W-8	2.82	DRY	2.41	1.74	1.85	1.47	1.56	1.01	0.48	4.24	3.39	7.83	1.85
W-9	DRY	DRY	DRY	0.93	0.99	1.65	1.33	1.21	DRY	3.58	DRY	DRY	1.08
W-10	34.30	No Rdg	1.64	1.77	1.25	1.77	1.67	2.98	1.39	1.97	0.88	1.58	2.32

*Instruments recalibrated to remove installation error.

**An increase of 530 gal in May necessitated jetting 1190 gal to LLLW.

Table 2. North Tank Farm surveillance data—FY 1991

	SEP 90	OCT	NOV	DEC	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP
Tank Levels (avg. gal) (+/- from previous month)													
W-3 (capacity 42,500 gal)	39,368	39,664 296	39,664 0	39,960 296	37,000 (2,960)	37,296 296	37,592 296	37,296 (296)	37,592 296	37,592 0	37,592 0	37,296 (296)	37,592 296
W-4 (capacity 42,500 gal)	23,520	23,520 0	23,520 0	24,108 588	24,402 294	24,108 (294)	BROKEN STAFF	BROKEN STAFF	BROKEN STAFF	BROKEN STAFF	BROKEN STAFF	BROKEN STAFF	BROKEN STAFF
W-13 (capacity 2,000 gal)	262	262 0	262 0	262 0	262 0	262 0	262 0	262 0	262 0	262 0	262 0	262 0	262 0
W-14 (capacity 2,000 gal)	136	136 0	136 0	136 0	136 0	136 0	136 0	136 0	136 0	136 0	136 0	136 0	136 0
W-15 (capacity 2,000 gal)	570	570 0	570 0	570 0	570 0	570 0	570 0	570 0	570 0	570 0	570 0	570 0	570 0
TOTAL VOLUME (average gal (+/- from previous month)	63,856	64,152 296	64,152 0	65,036 884	62,370 (2,666)	62,372 2	38,560 (23,812)	38,264 (296)	38,560 296	38,560 0	38,560 0	38,264 (296)	38,560 296
North Tank Farm Drywell (Gross Beta Bq/ml)	15.30	17.10	14.40	12.10	14.10	9.12	13.50	13.30	14.10	10.10	10.70	2.41	13.30

Table 3. Old Hydrofracture Facility surveillance data—1991

	SEP 90	OCT	NOV	DEC	JAN	FEB	MAR	APR	MAY*	JUN*	JUL	AUG**	SEP
OHF Tank Levels (avg. gal) (+/- from previous month)													
T-1 (capacity 15,000 gal)	8,309	8,133 (176)	8,309	8,133 (176)	8,133	8,133	8,483	8,309 (174)	BAD CO	BAD CO	8,659 INSTR	8,659 ERROR	8,309
T-2 (capacity 15,000 gal)	10,381	10,381 0	10,211 (170)	10,211 0	10,041 (170)	10,381 340	10,381 0	10,381 0	BAD CO	BAD CO	10,884 INSTR	10,884 ERROR	10,381
T-3 (capacity 25,000 gal)	2,703	2,503 (200)	2,503	2,503	2,703	2,908	2,908	2,903 (5)	BAD CO	BAD CO	3,117 INSTR	3,117 ERROR	2,908
T-4 (capacity 25,000 gal)	14,947	14,947 0	14,947	14,388 (559)	14,105 (283)	14,668 563	14,947 279	14,668 (279)	BAD CO	BAD CO	15,225 INSTR	15,225 ERROR	14,947
T-9 (capacity 13,000 gal)	4,831	4,831 0	4,831	4,831	4,831	4,831	4,831	4,831 0	BAD CO	BAD CO	4,831 INSTR	4,831 ERROR	4,831
TOTAL VOLUME (average gal +/- from previous month)	41,171	40,795 (376)	40,801	40,066 (735)	37,813 (253)	40,921 1,108	41,550 629	41,092 (458)			42,716	42,716	41,376
OHF Tanks Drywells (Gross Beta Bq/ml)													
T-1	DRY	DRY	DRY	0.37	0.10	DRY	DRY	0.02	0.02	0.02	0.01	DRY	DRY
T-2	DRY	DRY	DRY	0.20	0.10	DRY	DRY	0.01	0.01	0.01	0.01	DRY	DRY
T-3 and T-4	0.06	0.03	0.02	0.01	DRY	0.03	0.03	0.03	0.05	0.04	0.06	0.12	0.05
T-9	DRY	0.03	0.02	DRY	DRY	DRY	DRY	DRY	DRY	DRY	DRY	DRY	0.09
Tanks Cathodic Protection													
(Average Volts)	70.0	70.0	70.0	70.0	70.0	69.0	70.0	70.0	74.1	72.0	72.0	70.0	70.0
(Average Amps)	2.7	2.6	2.6	2.5	2.5	2.5	2.5	3.0	2.0	2.5	2.2	2.5	2.8

*Compressor inoperative.

**New compressor installed, incorrect readings because of water-logged system.

Table 4. Main plant area surplus tanks surveillance data—1991

	OCT	NOV	DEC	JAN	FEB	MAR	APR	MAY	JUN	JUL	AUG	SEP
Tank Levels (avg. gal) (+/- from previous month)												
WC-17 (capacity 1,000 gal)	238	290	285	280	283	286	276	271	276	277	273	271
Tank Dry Wells (Gross beta Bq/ml)												
WC-1	5.14	5.08	4.66	3.71	2.96	3.33	3.37	4.59	5.04	3.11	3.69	5.64
TH-1, TH-2, TH-3	0.85	0.76	0.43	0.32	0.19	0.64	0.68	0.56	0.64	0.57	0.68	0.71
TH-4	0.42	2.64	0.28	0.75	0.21	0.46	0.08	0.52	0.34	0.76	0.38	0.48
WC-15, WC-17	0.18	0.29	2.93	0.56	0.63	0.26	0.12	2.54	0.73	0.36	0.20	0.17

4. SPECIAL MAINTENANCE PROJECTS

4.1 CONTAMINATED GROUNDWATER COLLECTION AND TREATMENT

Groundwater collected in surplus contaminated facilities and in the process waste system is considered fugitive waste and is treated as LLLW and process waste, respectively. LLLW Tank W-1A in the North Tank Farm and the T-30 tank pit associated with the surplus High-Level Chemical Development Laboratory (Building 4507) collect groundwater that is treated as LLLW. In addition, a percentage of the leakage to LLLW Tank WC-19 is considered fugitive by virtue of its connections to the Oak Ridge Graphite Reactor and its filter and fan houses.

Inleakage to Tank W1-A has been highly variable during the year, whereas inleakage to the T-30 tank pit has been relatively stable. Tank W-1A has collected approximately 34,753 gal. Substantial increases in inleakage rate are experienced during periods of heavy rain. On the other hand, inleakage to the T-30 tank pit has remained fairly constant (approximately 76 gal/month, or 911 gal) and has shown little correlation to amounts of rainfall. Inleakage to Tank WC-19, of which one-third is considered fugitive, also tends to follow the pattern of local rainfall. Total inleakage to Tank WC-19 during this reporting period was 27,388 gal.

Fugitive process waste is collected in five locations in the main plant: (1) upstream of Manhole 112 near inactive reactor facilities, (2) the isotopes area between Manholes 114 and 112, (3) Pumping Station 1 below the North and South Tank farms, (4) WC-8 dry well, and (5) WC-10 tank farm dry well. These sources of fugitive waste collect orders-of-magnitude higher volumes of water than do the LLLW collection points. However, because this waste contains much lower levels of contamination, treatment costs are considerably less. Fugitive process waste collected and treated during the report period totaled over 40 million gal.

In past years, volumes of fugitive LLLW and process waste were either measured or estimated at each location, and charges were assessed by Waste Management Operations for processing according to current charge-back rates. With the abandonment of the charge-back system for FY 1991, a constant monthly rate will be charged for processing. Quantities of fugitive waste collected during 1991 are listed in Table 5.

Table 5. Fugitive waste collected in FY 1991

	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep
<i>Fugitive low-level waste (gal)</i>												
W-1A	1894	1509	11412	1633	9252	4210	8	345	2937	422	11	1120
T-30 (WC-12)	21	15	432	42	192	52	34	37	28	23	15	20
WC-19	748	3688	5164	1042	4477	8242	1087	453	1358	602	270	257
TOTAL	2663	5212	17008	2717	13921	12504	1201	835	4323	1047	226	1397
<i>Fugitive process waste (10³ gal)</i>												
Reactors area (10% of MH112)	95.78	99.41	113.72	82.88	79.38	102.51	45.37	43.03	57.28	42.07	41.73	54.07
Isotopes area (15% of MH114)	170.91	162.53	317.93	239.94	236.19	218.19	91.25	76.21	123.71	96.24	94.66	123.14
Tank farms (P.S. #1)	998.40	997.84	1,593.46	3,024.00	3,024.00	3,780.00	3,024.00	2,538.00	2,835.00	2,268.00	2,268.00	2,835.00
WC-8 dry well	476.00	476.00	595.00	476.00	476.00	595.00	476.00	476.00	595.00	476.00	476.00	595.00
WC-9 dry well	280.00	280.00	350.00	280.00	280.00	350.00	280.00	280.00	350.00	280.00	280.00	350.00
TOTAL	2,021.09	2,015.78	2,970.11	4,102.84	4,095.57	5,045.70	3,916.62	3,413.24	3,960.99	3,162.31	3,160.39	3,957.21

4.2 GUNITE TANK CONTINGENCY PLAN

Drafting of a contingency plan to outline responses to potential emergency situations associated with the six gunite tanks in the South Tank Farm has been completed. However, extrapolations were made by using inleakage figures, and the only available figures were out-of-date (i.e., they portrayed more drought-like conditions than are currently being experienced). The increase in rainfall has been close to 20 in. per year. This factor indicates a quite different situation and has changed priorities considerably. Energy Systems Engineering has begun a task to revise the plan to include more up-to-date numbers. At the current rate, Tank W-6 will be filled to capacity in less than 2 years, obviously a more accelerated rate than previously thought. Concerns include the age of the piping and valve pits and the fact that the design does not conform to current standards. A proposal from Energy Systems Engineering to remedy the situation is currently under development.

4.3 ISOLATION OF WATERFOWL FROM PROCESS PONDS

A high-tension-wire grid system, complete with tension indicators and in-line strainers, was previously installed across the 3513 Waste Holding Basin. This grid and the allied perimeter fence are intended to discourage the use of the pond by waterfowl. Other ponds and water areas are being studied as possible sites to utilize this successful design as they are integrated into Environmental Restoration Program responsibility.

4.4 CONTAMINATED SITES FENCING

Efforts are continuing to identify previously contaminated sites and to erect fences that would restrict public access to these areas, especially during the deer hunting season.

4.4.1 White Wing Scrap Yard

After the discovery of contaminated items at the White Wing Scrap Yard, a project was initiated to erect a chain-link fence with "Radiation Hazard—Keep Out" signs attached at regular intervals around the perimeter. The project is on hold pending NEPA approval. A rare plant and wetlands survey has been conducted. Energy Systems Engineering is developing a drawing in which coordinates are plotted to reflect the wetlands areas with regard to the planned fence routing.

4.4.2 Chestnut Ridge Environmental Research Sites

Two former environmental research sites on Chestnut Ridge that had previously utilized radioactive materials were recently identified. The two sites, each approximately 5 acres, were last used in 1970. A project was initiated to erect a chain-link fence around the perimeter of each plot. NEPA review and approval have been completed, and a 90% design review is being evaluated to determine the most acceptable approach for construction.

4.5 BUILDING 3001 STORAGE CANAL SOURCE REMOVAL

Accomplishments during this report period include the successful completion of repackaging and storage of 835 ^{60}Co and 16 ^{90}Sr radioactive sources originating from the Building 3001 Storage Canal. Fourteen loads were required. The sources were repackaged into overpack canisters in the Oak Ridge Research Reactor Hot Cells, shipped to SWSA 5, and stored in retrievable wells. Five wells were utilized. Additional efforts included tumulus disposal of 200 ft³ of material used to contain and manipulate the sources underwater at the Building 3001 Storage Canal, sampling of the sediment for fissile material inventory, six carrier shipments of core piece extrusions stored in the canal from the Low-Intensity Test Reactor following that reactor shutdown, and decontamination of equipment that was used in the source removal and must be reused in the future.

Underwater radiation measurements were made in the canal this year. An ion chamber detector was lowered into an aluminum "dry tube" to make measurements in five different locations at various depths along the west wall of the north-south run of the canal. Radioactivity detected was assumed to be primarily due to ^{60}Co and ^{137}Cs and, therefore, no attenuation factor was used. Dose rate measurements taken at the bottom of the canal varied from 0.45 R/h to 375 R/h. This variance can be attributed to the non-homogeneous nature of the sediments. These bottom readings were taken by allowing the detector to rest on the bottom of the dry tube, which was designed with lead as a deterrent to buoyancy. No attenuation for lead was accounted for in the numbers given above.

5. SUMMARY

S&M activities will continue in the main task areas described in the preceding sections during FY 1992. Scoping surveys will continue to investigate sites about which additional information is needed. Routine S&M will continue as scheduled, and special projects will continue to correct serious site deficiencies that are beyond the scope of routine maintenance. These special projects will focus on isolation of additional areas containing contaminated vegetation from human intrusion and on surveillance instrumentation upgrades.

DISTRIBUTION

1. L. V. Asplund/N. W. Durfee
2. J. W. Autrey
3. L. D. Bates
4. H. M. Braunstein
5. T. W. Burwinkle
6. H. M. Butler, Jr.
7. T. R. Cannon
8. J. S. Colley
9. K. W. Cook
10. M. F. Delozier
11. W. A. Duggins
12. M. K. Ford
13. H. R. Gaddis
14. S. B. Garland II
15. C. D. Goins
16. J. L. Hammontree
17. R. L. Hendren
18. L. Holder, Jr.
19. D. D. Huff
20. L. D. Hyde
21. R. G. Jones
22. J. R. Lawson
23. L. E. McNeese
24. C. E. Nix
- 25-26. P. T. Owen
27. T. H. Row
28. G. E. Rymer
29. P. A. Schrandt
30. T. F. Scanlan
31. C. B. Scott
32. B. P. Spalding
33. J. H. Swanks
34. D. W. Swindle
35. J. R. Trabalka
36. L. D. Voorhees
37. D. R. Watkins
38. J. K. Williams
39. L. F. Willis
40. R. K. White
41. Central Research Library
42. Document Reference Section
- 43-47. ER Document Management Center
- 48-49. Laboratory Records Dept.
50. ORNL Patent Section
51. RAP/RCDB
52. Office of Assistant Manager for Energy Research and Development, DOE Field Office, Oak Ridge, P.O. Box 2001, Oak Ridge, TN 37831-8600
53. P. H. Edmonds, Radian Corporation, 120 South Jefferson Circle, Oak Ridge, TN 37830
- 54-57. W. E. Murphie, Department of Energy, Office of Environmental Restoration, Eastern Area D&D Branch, EM-423 (GTN), Washington, DC 20545
- 58-59. S. S. Perkins, DOE Field Office, Oak Ridge, Information Resource Center, 105 Broadway, Oak Ridge, TN 37830
- 60-61. S. P. Riddle, DOE Field Office, Oak Ridge, P.O. Box 2001, Oak Ridge, TN 37831-8541
62. R. C. Sleeman, DOE Field Office, Oak Ridge, P.O. Box 2001, Oak Ridge, TN 37831-8541
- 63-64. Office of Scientific and Technical Information, P.O. Box 62, Oak Ridge, TN 37831

**DATE
FILMED**

5/01/92