AIM

Association for Information and Image Management

1100 Wayne Avenue, Suite 1100
Silver Spring, Maryland 20910

301/587-8202

Centimeter

Inches

MANUFACTURED TO AIM STANDARDS
BY APPLIED IMAGE, INC.

**Cover Sheet for a Hanford
Historical Document
Released for Public Availability**

Released 1994

**Prepared for the U.S. Department of Energy
under Contract DE-AC06-76RLO 1830**

**Pacific Northwest Laboratory
Operated for the U.S. Department of Energy
by Battelle Memorial Institute**

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED
~~DISTRIBUTION RESTRICTED TO U.S. GOVT~~

MAY 04 1994
OSTI

DISCLAIMER

This is a **historical document** that is being released for public availability. This was made from the best available copy. Neither the United States Government nor any agency thereof, nor Battelle Memorial Institute, nor any of their employees, makes any **warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights.** The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

(CLASSIFICATION)

DECLASSIFIED

GENERAL ELECTRIC

HANFORD ATOMIC PRODUCTS OPERATION - RICHLAND, WASHINGTON

DOCUMENT NO.

HW-78375 RE

SERIES AND COPY NO.

DATE

July 24, 1963.

TITLE

LOW FLOW TUBES

☐ OTHER OFFICIAL CLASSIFIED INFORMATION

THIS MATERIAL CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U. S. C., SECS. 793 AND 794, THE TRANSMISSION OR REVELATION OF WHICH IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

AUTHOR

I. L. Huffman

CIRCULATING COPY

RECEIVED 100 D AREA

JUL 30 1963

RETURN TO

TECHNICAL INFORMATION FILES

ROUTE TO:

PAYROLL NO.

LOCATION

FILES ROUTE
DATE

SIGNATURE AND DATE

2423

JUL 30 1963

(CLASSIFICATION)

MASTER

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

DECLASSIFIED

HW-78375 RD

July 24, 1963

Classification Cancelled and Changed To

DECLASSIFIED

By Authority of CG-PR-2
D.S. Lewis, 3-24-94
By Jerri Moley, 4-4-94
Verified By J.E. Savely, 4-15-94

DISTRIBUTION

1. J. W. Green
2. I. L. Huffman
3. W. W. McIntosh
4. N. H. Skarshaug / A. W. Mallow
5. R. E. Spicka / E. L. Conner
6. A. N. Stinson
7. A. P. Vinther
8. 300 Files
9. Record Center

This document consists
of 5 pages.

This document is classified by:

A.P. Vinther

July 24, 1963.

DECLASSIFIED

DECLASSIFIED

HW-78375 RD

July 24, 1963

LOW FLOW TUBES

Prior to the outage of 7-19-63, a study was made of tube flows, tube temperatures and tube corrosion. From the study it was theorized that some tubes had a below-normal coolant flow because of some abnormality in the rear hardware, probably necking-down of the crossheader Parker fitting. In order to investigate this theory, several low-flow tubes were chosen for detailed inspection and reaming of the Parker fittings. Of those inspected during the 7-19-63 outage, all low-flow tubes were found to be normal except for necked-down Parker fittings. The fittings were reamed back to normal and subsequent flow checks indicated that the reaming had increased the flow as expected. The data:

<u>Tube No.</u>	<u>3293</u>	<u>3785</u>	<u>3266</u>	<u>3790</u>	<u>4278</u>
Reason for Checking	High	Normal	Low	Low	Low
Original Flow	47.9	44.8	42.1	42.2	41.7
Type Nozzle	Regular	Regular	Re-worked Front	Regular	Regular
Pigtail	Regular	Regular	Y-Block	Regular	Regular
Pigtail Check	Visual OK	Visual OK	Ball Ck:OK	Visual OK	Visual OK
Parker Fitting I.D.					
Before Reaming	.440"	.420"	.435"	.410"	.405"
After Reaming	.475	.475	.475	.475	.475
Difference	.035	.055	.040	.065	.070
Flow Before, gpm.	47.9	44.8	42.1	42.2	41.7
Flow After	47.6	44.7	44.0	44.6	44.1
Flow Difference	-.3	-.1	+1.9	+2.4	+2.3
Other Changes	None	None	(1)	(2)	None

- (1) Charge seated 24" downstream - nominal flow effect.
(2) Re-charged (E to E-N) - nominal flow effect.

It is noteworthy that necking-down was indicated on the high-flow tube (3293) and the normal flow tube (3785) also. This could have been a false indication from the type of measuring instrument used - a tapered plug gauge; it was inserted and marked with the fingernail. A burr or a slip of the fingernail could have given a false indication on any or all measurements.

DECLASSIFIED

HW-78375 RD
Page 2
July 24, 1963

The most important point is that all five fittings were reamed to the correct diameter but flow increases resulted only on the low-flow tubes.

Two of the low-flow tubes (3266 and 3790) had changes made other than reaming as indicated in the foregoing data. However, it is not likely that the other changes caused an appreciable amount of the flow increase.

Another purpose of the investigation was to attempt to find the cause of the high flow in some tubes. Only one high-flow tube (3293) was investigated; no abnormality was found that could have caused the high flow. It is probable that the cause is in the front hardware, and the most likely cause is a slightly oversized Venturi. The front hardware of some high flow tubes should be investigated in the near future. The purpose of determining the cause of high flow is to learn how to increase the flow through normal flow tubes.

The main advantage of increasing the flow on low-flow tubes is the effect it will have on tube corrosion and tube replacements. As seen from the foregoing data, the reaming increased the flow about 2.2 gpm. This is a 5.2% flow increase, and it will decrease the delta temperature of the coolant 5.2% or about 4.5° C. This will decrease the corrosion rate 20-25% and will increase the theoretical life of the tube 30-35%.

It is best at this point to use specific data for discussion. Tube 3266, in addition to being a low-flow tube, is next to a G thermocouple stringer. During the recent 60-day (180-shift) sustained run, it was one of the ten highest outlet temperature tubes for 169 shifts. A new tube was installed on 5-62 and was probologged at 41 mils on 1-63.

DECLASSIFIED

HW-78375-RD
Page 3
July 24, 1963

Its corrosion rate (9.5 mils per block cycle) was so fast that it would have corroded to 22 mils by the September 1963 outage. Therefore, it was replaced 1-63 after two metal cycles. At four metal cycles per year, this tube would cost about \$1600 per year for replacement. The 1.9 gpm flow increase will reduce its corrosion rate to less than 7 mils per cycle, and the tube will last 4 metal cycles before it corrodes 30 mils and has to be replaced. The improvement will save one tube replacement per year, worth \$800 per year.

Tube 3790 is (or was) outside the E-N block. Its past corrosion rate is not so obvious. However, it is noteworthy that the tube leaked 4-59 and had a rupture-leaker 11-62. The improved flow, and particularly this added knowledge about low-flow tubes, could possibly prevent future leaks and ruptures in the tube, worth about \$10,000 each.

Tube 4278 is well outside the Block and normally would not be expected to be troublesome. However, a quick review of the overlay maps shows that it ruptured 7-54 and required replacement 8-59 and 10-62. The previous low flow could have been a contributing factor.

It can be seen by the foregoing discussion that there probably are large gains to be made by reaming the rear Parker fittings on all low-flow tubes. The program that will be followed is:

1. Determine from the overlay maps the low-flow tubes that probably will be most troublesome from a rupture, leak and tube replacement standpoint.
2. Ream the rear Parker fittings on several of them (10-50, depending on available time) during the next unscheduled outage.

DECLASSIFIED

HW-78375-RD
Page 4
July 24, 1963

3. Ream the rear Parker fittings on all tubes that are replaced.
4. Ream the Parker fittings on all low-flow tubes during unscheduled outages as time permits. Further testing and study may justify using additional outage time for this work.
5. Inspect the Venturis on several high flow tubes during the next unscheduled outage.

I. L. Huffman
Analyst
H Processing Operation
H REACTOR OPERATION

IL Huffman:ecj

DATE

FILMED

6 / 16 / 94

END