AIM

Association for Information and Image Management

1100 Wayne Avenue, Suite 1100
Silver Spring, Maryland 20910

301/587-8202

Centimeter

Inches

MANUFACTURED TO AIM STANDARDS
BY APPLIED IMAGE, INC.

1 of 1

UNCLASSIFIED

WSRC-TR-92-552

Keywords:

Replacement Tritium Facility (233-H)
Hydride Storage Bed
Failure Analysis
Aluminum Alloy
Stainless Steel

Retention: Permanent

**MATERIALS PERFORMANCE IN PROTOTYPE THERMAL CYCLING
ABSORPTION PROCESS (TCAP) COLUMNS (U)**

NRT&SC Task No. 90-040-0

Elliot A. Clark

Savannah River Technology Center
Equipment and Materials Technology Department
Materials Technology Section

Publication Date: 21 November 1992

D. T. Rankin 11/24/92

D.T.Rankin, Authorized Derivative Classifier

MASTER

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

ym

<u>CONTENTS</u>	<u>Page</u>
Summary	1
Introduction	1
Experimental Procedures	2
Results	3
Discussion	5
Conclusions	5
Acknowledgments	6
Quality Assurance	6
References	7
Figures	8

FIGURES

	Page
1. Drawing of aluminum block Thermal Cycling Absorption Process column.	8
2. Photograph of crimped nitrogen inlet tube in AHL block TCAP.	9
3. Photograph of crack in nitrogen inlet after AHL block TCAP retired.	10
4. Fracture surface of AHL block TCAP nitrogen inlet tube.	11
5. Location of samples cut from AHL block TCAP.	12
6. SEM of exposed AHL block TCAP and unexposed new block TCAP.	13
7. Section from nitrogen header inlet on AHL block TCAP.	14
8. Exposed and unexposed AHL block TCAP aluminum alloy to stainless steel transition junction.	15
9. Diagram of Third Generation Stainless Steel Column TCAP column.	16
10. Leaking tube junction and tube junction after being cut from the remaining tube.	17
11. Interior wall of Third Generation stainless steel TCAP column.	18

APPROVALS

Date: 11/24/92
Elliot A. Clark, Author
Materials Compatibility and Joining Group
Materials Technology Section
Equipment and Materials Technology Department/SRTC

Date: 11/30/92
J.R. Knight, Customer Representative
Process Development Program
Hydrogen Technology Section
Chemical Process Technology Department/SRTC

Date: 11/24/92
M.H. Tosten, Technical Reviewer
Materials Compatibility and Joining Group
Materials Technology Section
Equipment and Materials Technology Department/SRTC

Date: 11/24/92
D.T. Rankin, Responsible Manager
Materials Compatibility and Joining Group
Materials Technology Section
Equipment and Materials Technology Department/SRTC

Date: 12/7/92
T.L. Capeletti, Manager
Materials Technology Section
Equipment and Materials Technology Department/SRTC

**MATERIALS PERFORMANCE IN PROTOTYPE THERMAL CYCLING
ABSORPTION PROCESS (TCAP) COLUMNS (U)**

Elliot A. Clark
Westinghouse Savannah River Company
Savannah River Site
Aiken, SC 29808

SUMMARY

Two prototype Thermal Cycling Absorption Process (TCAP) columns have been metallurgically examined after retirement, to determine the causes of failure and to evaluate the performance of the column container materials in this application. Leaking of the fluid heating and cooling subsystems caused retirement of both TCAP columns, not leaking of the main hydrogen-containing column. The aluminum block design TCAP column (AHL block TCAP) used in the Advanced Hydride Laboratory, Building 773-A, failed in one nitrogen inlet tube that was crimped during fabrication, which lead to fatigue crack growth in the tube and subsequent leaking of nitrogen from this tube. The Third Generation stainless steel design TCAP column (Third generation TCAP), operated in 773-A room C-061, failed in a braze joint between the freon heating and cooling tubes (made of copper) and the main stainless steel column. In both cases, stresses from thermal cycling and local constraint likely caused the nucleation and growth of fatigue cracks. No materials compatibility problems between palladium-coated kieselguhr (the material contained in the TCAP column) and either aluminum or stainless steel column materials were observed. The aluminum-stainless steel transition junction appeared to be unaffected by service in the AHL block TCAP. Also, no evidence of cracking was observed in the AHL block TCAP in a location expected to experience the highest thermal shock fatigue in this design. It is important to limit thermal stresses caused by constraint in hydride systems designed to work by temperature variation, such as hydride storage beds and TCAP columns.

INTRODUCTION

The Thermal Cycling Absorption Process (TCAP) is a semi-continuous chromatographic hydrogen isotope separation process that will be used in the 233-H Replacement Tritium Facility at the Savannah River Site¹. A TCAP column is filled with palladium coated onto kieselguhr (kieselguhr is diatomaceous earth, mainly SiO₂), or Pd/K. The large isotope effect of absorption of hydrogen by palladium results in isotope separation when the column undergoes temperature cycling². Various design configurations have been used (designed and tested by the Hydrogen Technology Section, Savannah River Technology Center) for the column: a series of connected stainless steel columns, a solid aluminum alloy block, and a stainless steel coil. Two recently retired prototype TCAP columns, the aluminum block design TCAP column (AHL block TCAP) used in the 773-A Advanced Hydride

Laboratory and the Third Generation stainless steel column design TCAP column (Third generation TCAP) used in 773-A room C-061) failed in the system carrying the heating and cooling fluid to the column.

A program to evaluate the materials compatibility between hydrides and the container³ has shown no evidence to suggest a compatibility problem between either $\text{LaNi}_{5-x}\text{Al}_x$ ($x=0.3$ or 0.75) (used in hydride storage beds) or Pd/K and stainless steel^{4,5}. This report describes a metallurgical study of the two failed TCAP columns, to determine the cause of failures and to further evaluate the materials compatibility of palladium coated kieselguhr with the column materials, aluminum and stainless steel.

Both the AHL block TCAP and the Third Generation TCAP columns provided design and operating experience in using TCAP to separate protium from deuterium, in preparation for installation of TCAP in the 233-H Replacement Tritium Facility (RTF) to separate deuterium from tritium. The AHL block TCAP column underwent more than 5000 heating and cooling cycles⁶ and the Third Generation TCAP experienced more than 3000 cycles⁷. Originally, the aluminum block was designed for the RTF. However, fabrication difficulties and other considerations led to the decision to change to a stainless steel coil design for the RTF TCAP column.

EXPERIMENTAL PROCEDURES

Samples were cut from three columns: the AHL block TCAP, a partially completed aluminum block TCAP column ("new block TCAP") that was being fabricated for the Replacement Tritium Facility, and the Third generation TCAP. The AHL block TCAP was fabricated using Type 5052 aluminum, which contains approximately 2.5% (weight) magnesium, 0.25% chromium, 0.25% maximum silicon, 0.40% maximum copper, 0.10% maximum manganese, 0.10% maximum zinc, and balance aluminum⁸. The new block TCAP was fabricated from Type 6061 aluminum, which contains approximately 1.0% magnesium, 0.20% chromium, 0.6% silicon, 0.28% copper, 0.7% maximum iron, 0.15% maximum manganese, 0.25% maximum zinc, 0.15% maximum titanium, and balance aluminum⁸. The Third Generation TCAP column was fabricated from Type 304L stainless steel with copper tubing brazed onto the outside of the column that enabled heating and cooling by freon.

After locating the leak visually in the AHL block TCAP and using a fluid to find the leak in the Third generation TCAP, parts from the leak and from other exposed areas were cut from these two columns for metallurgical examination and failure analysis. Also, parts equivalent to those from the AHL block TCAP were cut from the new block TCAP, which allowed unequivocal identification of environmental exposure effects in the AHL block TCAP. Dye-penetrant testing was used to determine whether any cracks formed from excessive thermal shock at the inlet to the nitrogen header of the AHL block TCAP, the likely location of the largest thermal shock. Finally, the performance of the stainless steel to aluminum alloy junctions in the AHL block TCAP was evaluated by scanning electron microscopic comparison of the interior junction surface with that on the new block TCAP.

The microstructure of the samples were characterized by optical metallography, scanning electron microscopy (SEM) (using both secondary and back scattered electron detection), and energy dispersive X-ray spectroscopy (EDS).

RESULTS

A. Nitrogen Inlet Tube Failure (AHL block TCAP)

One of the inlet tubes in the AHL block TCAP was crimped during manufacture (*Fig. 1*) and was photographed prior to use (*Fig. 2*). During use, a leak occurred in the nitrogen heating and cooling system, causing retirement of this TCAP column. Visual inspection of this TCAP column revealed that a crack occurred at the previously crimped region (*Fig. 3*). After removing the cracked tube, it fell apart at the crack. The fracture surface revealed a microstructure typical of fatigue, indicated by the presence of fatigue striations (*Fig. 4*).

The likely cause of failure of this inlet tube was fatigue caused by cyclic thermal stresses. The buckled crimp enabled local strains to occur under the thermal cycling necessary for operation of the TCAP, leading to fatigue crack initiation, propagation, and ultimately leaking of the tube. Visual inspection showed that none of the remaining uncrimped nitrogen inlet tubes on the AHL block TCAP cracked.

B. Materials Compatibility of Palladium-Coated Kieselguhr and Aluminum alloy (AHL block TCAP)

Three circular samples were cut from the AHL block TCAP, and three were similarly cut from the new block TCAP (*Fig. 5*). The palladium-coated kieselguhr particles made intimate contact with the interior surface at these locations. The surface microstructure revealed machine marks, "mud flat crack" regions, and remnants of powder used in the TCAP (*Fig. 6*). Both the AHL block and new block TCAPs contained "mud flat crack" regions, indicating that these cracks originate in fabrication and are unrelated to exposure to Pd/K in hydrogen environments. Further, the size of these regions appeared the same in both the exposed AHL block and unexposed new block TCAP.

EDS of the surface of the TCAPs exposed to Pd/Kieselguhr and hydrogen gas revealed regions of the aluminum base alloy, precipitates of aluminum-silicon and aluminum-iron, palladium particles and lanthanum-nickel particles. The composition of the mud flat crack regions was about the same as the base alloy. The lanthanum-nickel particles probably came from contamination from samples of $\text{LaNi}_{5-x}\text{Ni}_x$ ($x=0.3$ or 0.75), since they should not have appeared on either the AHL block or new block TCAP samples but did appear on both. In addition, the new block TCAP had particles rich in tin, in copper and in lead on the surface. The interior of the new block TCAP had a white powder on the surface, and the tin, copper and lead could have come from either fluxes or other chemicals used during

manufacturing of the partially completed TCAP block. No microscopic chemical effects were observed to indicate any compatibility problem between aluminum alloy 5052 and palladium-coated kieselguhr.

C. Aluminum Alloy-Stainless Steel Transition Junction (AHL block TCAP)

An explosively formed stainless steel to aluminum transition junction was used in both the AHL block and new block TCAP columns. Since most hydrogen and tritium processing equipment is fabricated from austenitic stainless steels (mainly Types 304L or 316L), the transition junction connects the aluminum alloy TCAP to the rest of the process. Scanning electron microscopy (using the back scattered electron detector to enhance image contrast caused by the differing average atomic number between the aluminum and the stainless steel) was used to investigate the transition region on the interior of the tube. No evidence of any cracking or other degradation of the AHL block TCAP transition region was observed (*Fig. 8*).

D. Dye Penetrant Inspection of Nitrogen Header Inlet (AHL block TCAP)

A concern was raised several years ago concerning the possibility that thermal shock fatigue of the nitrogen inlet pipe to the header of the aluminum block TCAP could lead to fatigue crack growth⁹. No evidence of cracking was found in a section of pipe cut from the AHL block TCAP at that time. A part of the AHL block TCAP aluminum alloy inlet header pipe was sectioned and investigated using dye-penetrant. This area is exposed to the largest thermal shock during operation. No indications of cracks were observed on this sample (*Fig. 7*). Lack of dye-penetrant indications is evidence that thermal gradients in this location were insufficient to cause thermal shock fatigue in the AHL block TCAP.

E. Failure in Freon Heating and Cooling Tube (Third Generation TCAP)

Liquid leak detection revealed one large leak in a copper heating and cooling tube that carried freon cooling fluid that was brazed to one of the columns in the Third generation TCAP column (*Fig. 9*). When the part was cut from the rest of the copper, it became evident that the failure occurred in the braze joint of the copper tube to the stainless steel column (*Fig. 10*). Near the failure, both the copper tube and the copper tube joint were separately brazed to the stainless steel column, with a slight gap between these two braze areas. The tube joint was much thicker than the copper tube, and thermal cycling could have caused stress and resulting thermal fatigue in the constrained region of copper tubing between the tube joint and the braze location of the copper tube to the stainless steel. As in the AHL block TCAP, the failure occurred in the heating and cooling system, not in the process (hydrogen-containing) column.

F. Materials Compatibility of Palladium-coated Kieselguhr with Stainless Steel (Third Generation TCAP)

Several samples were cut from the stainless steel column in the Third Generation Stainless Steel TCAP. Scanning electron microscopy revealed intergranular surface ditching (*Fig. 11*). This feature has been

shown to be a common feature of acid cleaned austenitic stainless steel and is unrelated to exposure of stainless steel to hydrides^{4,5}. No evidence of any other reaction was observed.

DISCUSSION

The failure of both TCAP columns occurred in locations experiencing large changes in temperature during cycling. Thermal stresses are induced when structures are either a) externally constrained from expanding or contracting (for example, when two bodies having differing coefficients of thermal expansion are connected), or b) have a non-linear variation of internal temperature¹⁰. Both these conditions existed during the use of these two TCAP columns. It is likely that the particular location that failed in each column was highly constrained, which enabled the alternating stress from thermal cycling to be high enough to result in a relatively short fatigue life. The crimped region in the AHL block TCAP inlet tube could well have experienced concentrated stress during thermal cycling, and the copper tube was brazed to both the copper tube joint (itself brazed to the column) and the stainless steel column in the Third Generation TCAP. (Indeed, the Third Generation TCAP had to be modified to include loops of copper tubing able to deform elastically during thermal cycling⁷; prior to this, several failures occurred at the top of the columns.) Thermal cycling of highly constrained locations has therefore proved to determine the life of the prototype columns. Since thermal cycling is inherent in the function of the TCAP and therefore cannot be reduced, designs of TCAP and other hydride storage systems should emphasize reducing constraint during temperature cycling as much as possible. Analysis of thermally induced stresses during operation would aid in design and assure reliability of TCAP columns or hydride storage beds.

CONCLUSIONS

Two retired prototype Thermal Cycling Absorption Process columns and one partially fabricated TCAP column identical to one of the retired TCAP columns were metallurgically evaluated. The following conclusions are drawn from this study:

1. Both TCAP columns failed in their respective process heating and cooling lines, corresponding to physically constrained areas having large thermal gradients during thermal cycling. Constraint likely contributed to localized cyclic stress and strain, leading to fatigue crack initiation and propagation.
2. No materials compatibility problem exists between palladium-coated kieselguhr and either Type 304L stainless steel or Type 5052 aluminum alloy. The surface microstructure of both column materials is the same after exposure to Pd/K under temperature cycling as that before exposure.

3. The performance of the aluminum-stainless steel transition junction in the Advanced Hydride Laboratory TCAP column was excellent.
4. No evidence of surface cracks formed by thermal shock fatigue were found in the nitrogen inlet pipe in the Advanced Hydride Laboratory TCAP, a location that experienced the largest thermal shock (most rapid temperature change) in that column.
5. Thermal stresses and strains and the role of constraint are extremely important in the design of TCAP columns and other hydride beds designed to operate with changing temperature.

ACKNOWLEDGMENTS

Technical assistance was provided by A.S. Horen and G.S. Nichols of the Hydrogen Technology Section. A.S. Horen also reviewed this report. F.A. Cheek, III performed leak detection, some photography, and initial sample cutting and preparation. F.E. Odom provided final sample preparation, photography and optical microscopy. J.R. Durden, Analytical Development Section, provided scanning electron microscopy and energy dispersive X-ray analysis.

QUALITY ASSURANCE

This report documents work performed under Task No. 90-040-0, "Compatibility of Stainless Steel and Hydride Storage Materials", under the Nuclear Reactor Technology and Scientific Computations Department Quality Assurance Program, Savannah River Technology Center, Westinghouse Savannah River Company. Data used in this report is contained in laboratory notebook WSRC-91-62.

REFERENCES

1. M.S. Ortman, L.K. Heung, A. Nobile, and R.L. Rabun, III. *Tritium Processing at the Savannah River Site (SRS): Present and Future*. J. Vacuum Science and Technology A, **8**(3), pp. 2881-2889 (May/June 1990).
2. M.W. Lee. *TCAP for Separation of Hydrogen Isotopes*. USDOE Report DP-1660, E.I. Du Pont de Nemours & Co., Savannah River Laboratory, Aiken, SC 29808 (July 30, 1983).
3. E.A. Clark. *Experimental Program Plan for Compatibility Studies of Hydride Storage Materials with Container Materials in the Replacement Tritium Facility (U)*. USDOE Report DPST-88-667, E.I. Du Pont de Nemours & Co., Savannah River Laboratory, Aiken, SC 29808 (June 29, 1988).
4. E.A. Clark. *Materials Compatibility of Hydride Storage Materials with Austenitic Stainless Steels (U)*. USDOE Report WSRC-TR-92-438, Westinghouse Savannah River Co., Savannah River Site, Aiken SC 29808 (September 21, 1992).
5. E.A. Clark. *Formation of Intergranular Surface Ditching on Annealed Type 304L Stainless Steel by Acid Cleaning (U)*. USDOE Report WSRC-TR-90-600, Westinghouse Savannah River Co., Savannah River Site, Aiken SC 29808 (December 1990).
6. A.S. Horen. Private communication, 11/3/92.
7. G.S. Nichols. Private communication, 11/3/92.
8. Metals Handbook. *Volume 2 Properties and Selection: Nonferrous Alloys and Pure Metals*. American Society for Metals, Materials Park, OH (1979), pp. 101-102, 115-116.
9. E.A. Clark. *Dye Penetrant Analysis of Retired 304L Stainless Nitrogen Heating/Cooling Pipe from the Advanced Hydride Laboratory (U)*. USDOE Report WSRC-RP-89-190, Westinghouse Savannah River Co., Aiken SC 29802 (May 3, 1989).
10. A.P. Boresi and P.P. Lynn. *Elasticity in Engineering Mechanics*. Prentice-Hall, Inc., Englewood Cliffs, NJ, pp. 394-417 (1974).

FIGURE 1. Drawing of aluminum block Thermal Cycling Absorption Process column. Location of a) leak in crimped nitrogen inlet tube, b) compatibility samples and c) stainless steel to aluminum transition junction shown.

FIGURE 2. Photograph of crimped nitrogen inlet tube in AHL block TCAP. Photograph made before use.

FIGURE 3. Photograph of crack in nitrogen inlet after AHL block TCAP retired.

FIGURE 4. Fracture surface of AHL block TCAP nitrogen inlet tube. Fatigue striations clearly seen.

FIGURE 5. Photograph revealing location of samples cut from AHL block TCAP to evaluate compatibility between palladium-coated kieselguhr and aluminum alloy 5052.

FIGURE 6. SEM of exposed (top) AHL block TCAP and unexposed (bottom) new block TCAP. Note "mud flat crack" regions on both.

FIGURE 7. Photograph of section from nitrogen header inlet on AHL block TCAP after dye penetrant and developer applied. No dye penetrant indications observed.

FIGURE 8. SEM image of exposed AHL block TCAP 5052 aluminum to stainless steel transition junction (top) and of equivalent but unexposed transition junction in new block TCAP (bottom). Back scattered electron detector used.

FIGURE 9. Diagram of original Third Generation Stainless Steel TCAP column. 5 is stainless steel column, 7 and 9 are copper heating/cooling tubes.

FIGURE 10. Photographs of leaking tube junction (top) and of tube junction after being cut from the remaining tube (bottom) in Third Generation TCAP. Note failure occurred where main tube brazed to stainless steel, not in copper tube joint.

**DATE
FILMED**

7 / 22 / 93

END