**Work Plan and Health and Safety Plan for Building 3019B
Underground Storage Tank at Oak Ridge National Laboratory, Oak
Ridge, Tennessee**

**S. N. Burman
K. S. Brown
D. C. Landguth**

Date Issued—August 1992

**Prepared by
Health and Safety Research Division
Oak Ridge National Laboratory**

**Prepared for
Oak Ridge National Laboratory
Underground Storage Tank Program
under budget and reporting code EW 30**

**OAK RIDGE NATIONAL LABORATORY
Oak Ridge, Tennessee 37831-7101
managed by
MARTIN MARIETTA ENERGY SYSTEMS, INC.
for the
U.S. DEPARTMENT OF ENERGY
under contract DE-AC05-84OR21400**

MASTER

ef

Author Affiliations

S. N. Burman, K. S. Brown, and D. C. Landguth are members of the Measurement Applications and Development Group of the Health and Safety Research Division, Oak Ridge National Laboratory.

APPROVALS

Work Plan and Health and Safety Plan
for Building 3019B Underground Storage Tank at
Oak Ridge National Laboratory,
Oak Ridge, Tennessee
(ORNL-6738)

J. D. Miller 8/26/92
J. D. Miller Date

Office of Safety and Health
Protection

A. W. Saulsbury 8/26/92
A. W. Saulsbury Date
HAZWOPER Coordinator
Office of Safety and Health
Protection

B. A. Powers 8-26-92
~~J. L. Gray~~ Date

Environmental and Health
Protection, Health Physics

S. N. Burman 8/26/92
S. N. Burman Date

ORNL/MAD Site Project Manager

R. E. Swaja 8/26/92
R. E. Swaja Date

ORNL/MAD Group Leader

CONTENTS

LIST OF FIGURES	vii
LIST OF TABLES	ix
LIST OF ACRONYMS	xi
EXECUTIVE SUMMARY	xiii
1. PROJECT DESCRIPTION	1
1.1 INTRODUCTION	1
1.2 SCOPE AND OBJECTIVES	1
2. PROJECT ORGANIZATION AND RESPONSIBILITIES	5
2.1 SECTION CHIEF/FACILITY MANAGER RESPONSIBILITIES	7
2.2 BUILDING 3019B OPERATIONS COORDINATOR RESPONSIBILITIES	7
2.3 BUILDING 3019B OPERATIONS SUPERVISOR RESPONSIBILITIES	7
2.4 BUILDING 3019B MAINTENANCE COORDINATOR RESPONSIBILITIES	7
2.5 ORNL ENVIRONMENTAL SURVEILLANCE INSTRUMENTATION GROUP LEADER	7
2.6 ORNL UST TANK MANAGEMENT GROUP LEADER RESPONSIBILITIES	7
2.7 UST PROGRAM MANAGER, ORNL ENVIRONMENTAL PROJECTS SECTION	8
2.8 ORNL/MAD QUALITY ASSURANCE OFFICER RESPONSIBILITIES	8
2.9 SITE PROJECT MANAGER RESPONSIBILITIES	8
2.10 SITE HEALTH AND SAFETY OFFICER	9
2.11 FIELD PROJECT PERSONNEL	10
2.12 PROJECT SUPPORT	11
2.13 FIELD OPERATIONS	11
2.14 ORNL INDUSTRIAL HYGIENE	12
2.15 ORNL HEALTH PHYSICS	12
2.16 ORNL INDUSTRIAL SAFETY	12
2.17 EMERGENCY CONTACTS	12
2.17.1 Emergency Phone Numbers	13
2.17.2 Emergency Preparedness	13
3. QUALITY ASSURANCE OBJECTIVES FOR MEASUREMENT DATA	16
4. SAMPLING PROCEDURES	18
4.1 EQUIPMENT DECONTAMINATION	18
4.1.1 Discussion	18

4.1.1 Discussion	18
4.1.2 Equipment	18
4.1.3 Procedure	19
5. SAMPLE DOCUMENTATION AND CUSTODY	22
6. CALIBRATION PROCEDURES	23
6.1 MONITORING PROGRAM	23
6.1.1 Instrument Calibration	23
6.1.2 Calibration Frequency	24
6.1.3 Background Readings	24
6.2 CHEMICAL MONITORING	24
6.2.1 Chemical Monitoring Equipment	24
6.2.2 Organic Vapor Monitor	24
6.2.3 Organic Vapor Monitor Calibration	25
6.2.4 HNU Photoionization Detector	27
6.2.5 HNU Photoionization Detector Calibration	28
6.2.6 Flame Ionization Detector	29
6.2.7 Flame Ionization Detector Calibration	29
6.2.8 Combustible Gas Indicator	30
6.2.9 Chemical Monitoring Frequency	30
6.2.10 Chemical Monitoring Equipment Action Limits	30
6.3 RADIOLOGICAL MONITORING	31
6.3.1 Radiological Monitoring Equipment	31
6.3.2 NaI Scintillation Detector Source Check Procedures	32
6.3.3 GM Pancake Detector Source Check Procedures	33
6.3.4 ZnS Alpha Scintillation Detector	33
6.3.5 Radiological Frequency and Action Limits	35
6.3.6 Radiological Contamination Control	36
7. ANALYTICAL PROCEDURES	37
8. DATA MANAGEMENT PROCEDURES	38
9. INTERNAL QUALITY CONTROL REQUIREMENTS	39
9.1 INTRODUCTION	39
9.2 INTERNAL QC FOR FIELD MONITORING INSTRUMENTS	39
9.2.1 Chemical Span Gases	39
9.2.2 Radiological Check Sources	39
10. PERFORMANCE AND SYSTEM AUDITS	41
10.1 AUDIT RECORDS	41
10.2 FIELD AUDITS	41
11. PREVENTIVE MAINTENANCE	43
11.1 FIELD SAMPLING INSTRUMENTS	43
11.2 RADIOLOGICAL INSTRUMENTS	44
11.3 CHEMICAL DETECTION INSTRUMENTS	44

11.3.1 Photoionization Detectors	44
11.3.2 Combustible Gas Indicator	44
11.3.3 Flame Ionization Detector	45
12. PROCEDURES USED TO ASSESS DATA PRECISION, ACCURACY, AND COMPLETENESS	46
13. CORRECTIVE ACTIONS	47
13.1 FIELD ACTIVITIES	47
13.2 OCCURRENCE REPORTING	47
13.3 FIELD CHANGES/VARIANCES	47
14. QUALITY ASSURANCE REPORTS TO MANAGEMENT	50
15. ORNL BUILDING 3019B 110-GAL UST HEALTH AND SAFETY SECTION	51
15.1 SITE ACTION PLAN	51
15.1.1 Site Preparation	51
15.1.2 Suspected Contaminants	54
15.1.3 Tank Removal	54
15.1.4 Waste Management	56
15.2 PERSONNEL PROTECTION	56
15.2.1 Personal Protective Equipment	56
15.2.2 Respiratory Protection	59
15.2.3 Personnel Decontamination Procedures	61
15.3 SITE TASK HAZARD ANALYSES	68
15.3.1 Discussion	68
15.3.2 Determination of Work Area	68
15.3.3 Standard Safe Work Practices	70
15.3.4 Special Hazards	72
16. REFERENCES	75

LIST OF FIGURES

Figure	Page
1 Building 3019B area	2
2 110-gal underground storage tank at Building 3019B	3
3 110-gal underground storage tank (overhead and side views)	4
4 Decontamination trough	20
5 Decontamination trailer	21
6 Example of information for field logbook calibration page	26
7 Field monitoring record	34
8 Field change request/variance form	48
9 Segregated equipment drop and canister or cartridge change	62
10 Minimum decontamination requirements for Level D+ protection	63
11 Minimum decontamination requirements for Level C protection	64
12 Diagram of site work zones showing exclusion zone, contamination reduction zone, and support zone	71

LIST OF TABLES

Table		Page
1	Key project personnel and affiliations	6
2	Summary of sensitivity, precision, and accuracy criteria for monitoring instrumentation	17
3	Building 3019B UST radioactive contamination release limits in dpm/100 cm ²	36
4	Building 3019B 110-gal UST site contaminants	53
5	Protective equipment for on-site activities	58
6	Safe working distances from electrical transmission lines for masted or boomed machinery	74

LIST OF ACRONYMS

CGI	combustible gas indicator
cpm	counts per minute
CRZ	contamination reduction zone
DOE	Department of Energy
dpm	disintegrations per minute
EPA	Environmental Protection Agency
EZ	exclusion zone
FID	flame ionization detector
GM	Geiger-Mueller
HASRD	Health and Safety Research Division
HAZWOPER	Hazardous Waste Operations and Emergency Response
HP	Health Physics
IH	Industrial Hygiene
LEL	lower explosive limit
LSS	Laboratory Shift Superintendent
MAD	Measurement Applications and Development Group
MMES	Martin Marietta Energy Systems, Inc.
NIST	National Institute of Science and Technology
ORNL	Oak Ridge National Laboratory
OSHA	Occupational Safety and Health Administration
OVM	organic vapor meter
PID	photoionization detector
QAO	Quality Assurance Officer
QC	quality control
RPD	relative percent difference
SHSO	Site Health and Safety Officer
SOP	standard operating procedure
SPM	Site Project Manager
UST	underground storage tank

EXECUTIVE SUMMARY

As part of the Underground Storage Tank Program at the Department of Energy's Oak Ridge National Laboratory (ORNL) in Oak Ridge, Tennessee, this Health and Safety Plan has been developed for removal of the 110-gal leaded fuel underground storage tank (UST) located in the Building 3019B area at ORNL. This Health and Safety Plan was developed by the Measurement Applications and Development Group of the Health and Safety Research Division at ORNL. The major components of the plan follow: (1) A project description that gives the scope and objectives of the 110-gal tank removal project and assigns responsibilities, in addition to providing emergency information for situations occurring during field operations; (2) a health and safety plan in Sect. 15 for the Building 3019B UST activities, which describes general site hazards and particular hazards associated with specific tasks, personnel protection requirements and mandatory safety procedures; and (3) discussion of the proper form completion and reporting requirements during removal of the UST. This document addresses Occupational Safety and Health Administration (OSHA) requirements in 29 CFR 1910.120 with respect to all aspects of health and safety involved in a UST removal. In addition, the plan follows the Environmental Protection Agency (EPA) QAMS 005/80 (1980) format with the inclusion of the health and safety section (Sect. 15).

1. PROJECT DESCRIPTION

1.1 INTRODUCTION

The Chemical Assessment Team from the Measurement Applications and Development (MAD) Group was contacted by the Oak Ridge National Laboratory (ORNL) Underground Storage Tank (UST) Program concerning a 110-gal UST located along the northern wall of Building 3019B. This health and safety plan has been developed by the MAD Group of the Health and Safety Research Division (HASRD) at ORNL for removal of the UST. ORNL/MAD will be responsible for site health and safety. The layout of Building 3019B and the surrounding area is presented in Fig. 1. Orientation of the tank to Building 3019B and all structural obstacles is depicted in Fig. 2. Overhead and side views of the UST are presented in Fig. 3.

1.2 SCOPE AND OBJECTIVES

The objectives of the project include removal of the UST, sampling for contamination that may have emanated from the tank, and subsequent "clean" closure of the area. The scope of this plan is confined to health and safety aspects of the project. The tank lies along the northern wall of the building. Leaded gasoline and radiological contaminants will be encountered at the site. Previous sampling data indicates this site was contaminated with alpha and beta contamination; it will therefore be designated as a "C" zone. A matrix of potential contaminants is presented in Sect. 15.

The project will be conducted in the following phases: (1) soil excavation, (2) removal of the top portion of the tank, (3) removal of tank contents, (4) physical extraction of the emptied tank, (5) soil sampling, (6) site closure, and (7) compilation of field observation reports, if specified. The goals and objectives of the sampling include determination of the extent and concentration of the contaminants in question. The sampling approach will be based on the State of Tennessee's Underground Storage Tank Division guidelines (TDHE 1990) and conducted by the ORNL Environmental Surveillance Section.

* Fire Alarm Box

Fig. 1. Building 3019B area.

Fig. 2. 110-gal underground storage tank at Building 3019B area.

Fig. 3. 110-gal underground storage tank (overhead and side views).

2. PROJECT ORGANIZATION AND RESPONSIBILITIES

Provisions of this plan are mandatory for all on-site employees and visitors engaged in the remediation activities for the Building 3019B UST. This document concerns operations related to the health and safety aspects of the UST removal. Radiological monitoring and chemical monitoring for potential health concerns are addressed.

At the pre-entry health and safety briefing, all field investigation personnel, including representatives from the ORNL facilities (Radiochemical Technical Section, Industrial Hygiene, Health Physics, Fire Department, Safety, Security, ORNL Engineering, Plant and Equipment (P&E), and Underground Storage Tank Program) shall receive a copy of this health and safety plan and shall complete work in accordance with this plan. The pre-entry briefing shall be held prior to the commencement of field operations so that field personnel may become familiar with potential hazards and required field procedures. Individuals will be required to sign and date the field logbook, stating that each person who may be working in the contamination reduction zone (CRZ) or exclusion zone (EZ) has received a pre-entry health and safety briefing and a copy of the work plan and the health and safety plan.

The health and safety aspects of this document conform to the Occupational Safety and Health Administration (OSHA) Standard for Hazardous Waste Operations and Emergency Response (29 CFR 1910.120), as defined by the final rule (1989). ORNL/MAD will designate a Site Health and Safety Officer (SHSO) and alternatives who will implement, monitor, and enforce this plan.

Documentation of personnel training also will be required at the pre-entry briefing, in accordance with the final rule found in 29 CFR 1910.120, in order for the SPM to verify compliance with the specified training requirements. All personnel will provide the Site Project Manager (SPM) with documentation of successful completion of training requirements, such as certificates. "Tailgate" meetings may periodically be called during field activities to apprise on-site personnel of potential health and safety concerns that arise as a result of unanticipated field conditions.

Inadequate health and safety precautions on the part of any on-site personnel or the belief that personnel are or may be exposed to an immediate health hazard shall be sufficient cause for the SHSO, in consultation with Health Physics (HP) or Industrial Hygiene (IH), to suspend or discontinue site work and require personnel to evacuate a potentially hazardous area before reentry.

Table 1 contains a listing of key project personnel and affiliations, including phone numbers, for individuals involved in the tank removal at the UST site. In addition, alternates for key project personnel are listed where appropriate. The SPM or SHSO may designate qualified alternates who are not identified in the table to conduct their respective duties in the field if a situation warrants.

Table 1. Key project personnel and affiliations

Responsibility	Name	Telephone
Laboratory Shift Superintendent		574-6606
ORNL Site Project Manager	David Landguth	576-7363 or on site
Alternative SPMs	Steve Burman	576-7364
Site Health and Safety Officer	Steve Burman	576-7364 or on site
Alternative SHSOs	Paul Abston Glen Cofer	576-7362 576-7362
ORNL/MAD Group Leader	Dick Swaja	576-5212
ORNL/MAD Quality Assurance Officer	Richard Mathis	574-5832
Radiochemical Technical Facility Manager	B.D. Patton	576-0603
Building 3019B Maintenance Coordinator	Al Farmer	574-6940
ORNL Environmental Projects Section, UST Program Manager	Jerry M. Brown	574-1069
ORNL Tank Management Group Leader	Eric Mulkey	574-2923
ORNL UST Engineering Assistant	Ernest Ryan	576-1409
Building 3019B Operations Coordinator	Alan Krichinsky	574-6940
Building 3019B Operations Supervisor	Bill Starnes	574-6940
Environmental Surveillance Section Head	John Murphy	576-7929
ORNL Industrial Safety (P&E Oversight)	M. S. McCarty	574-6682
ORNL Construction Safety Oversight	S. E. Whittenbarger	574-0254
Public Relations		574-1640
ORNL Industrial Hygiene HAZWOPER Coordinator	B. Owen Ann Saulsbury	576-6125 576-5064
ORNL Fire Department	David Baity Bob Atchley	574-6277
ORNL Engineering		574-6416
Plant and Equipment (P&E)		574-4370
ORNL Radiation Protection Division	Steve Sims	574-6690
Radiation Protection Area Supervisor	Bryce Powers	574-6703

2.1 SECTION CHIEF/FACILITY MANAGER RESPONSIBILITIES

The facility manager has final authority for any and all operations being conducted at that facility. He is the top line administrator for operations being conducted at Building 3019B and throughout the Radiochemical Technical Facility.

2.2 BUILDING 3019B OPERATIONS COORDINATOR RESPONSIBILITIES

The facility supervisor (operations coordinator) is in charge of the day-to-day operations of that facility. He reports administratively to the facility manager and will discuss with him any important developments or problems that might arise during this tank removal project.

2.3 BUILDING 3019B OPERATIONS SUPERVISOR RESPONSIBILITIES

The operations supervisor is in charge of the physical workings of the building. He is responsible for all working procedures and systems of that facility. He, along with the facility supervisor, ensures that building operations are conducted. The operations supervisor is responsible for removal of all drummed waste being generated during this project.

2.4 BUILDING 3019B MAINTENANCE COORDINATOR RESPONSIBILITIES

The maintenance coordinator is responsible for making sure the individuals that are required to do the routine maintenance within and near the building are present. He coordinates with P&E for workers, and supervises crafts people in the completion of their appointed tasks.

2.5 ORNL ENVIRONMENTAL SURVEILLANCE INSTRUMENTATION GROUP LEADER

The Environmental Surveillance Instrumentation Group Leader is responsible for the following:

1. Construction of the sampling and analysis plan.
2. Oversight of sampling activities for the Environmental Surveillance Instrumentation Group (does not include health and safety oversight).
3. Mobilization and direction of group personnel conducting sampling activities.

2.6 ORNL UST TANK MANAGEMENT GROUP LEADER RESPONSIBILITIES

The ORNL UST Tank Management Group Leader has oversight for all USTs for the ORNL Facility. He insures that ORNL complies with environmental regulations stemming from Subtitle I of the Resource Conservation and Recovery Act of 1976; these are found in

40 CFR 280 in a final rule of September 23, 1988. The UST Tank Management Group Leader is responsible for final dispensation of the tank and for meeting requirements for the State of Tennessee regarding site closure. He will be assisted by the ORNL UST Engineering Assistant, who will provide project oversight and closure documentation.

2.7 UST PROGRAM MANAGER, ORNL ENVIRONMENTAL PROJECTS SECTION

The ORNL UST Engineering Assistant is responsible for managing and coordinating tank removal activities, which may include but are not limited to the following:

1. coordinating the support personnel required for the removal,
2. notifying the Laboratory Shift Superintendent of plans and schedules for the site,
3. determining and communicating site project objectives,
4. contacting ORNL Fire Department two days prior to commencing activities,
5. communicating and assisting with regulatory matters associated with analytical and sampling parameters for USTs.

2.8 ORNL/MAD QUALITY ASSURANCE OFFICER RESPONSIBILITIES

The ORNL/MAD Quality Assurance Officer (QAO) is responsible for the following:

1. assisting the SPM in resolving quality-related issues;
2. reviewing and approving Quality Assurance Project Plans;
3. reviewing project plans and procedures to ensure that all aspects of quality requirements have been adequately considered and addressed;
4. conducting quality audits and surveillances, as necessary, for those aspects directly related to ORNL/MAD activities, to verify and document compliance with established procedures;
5. following up corrective actions associated with audit or surveillance reports; and
6. exerting stop-work authority if required by situations within his/her area of oversight.

2.9 SITE PROJECT MANAGER RESPONSIBILITIES

The SPM will oversee the ORNL Building 3019B UST activities. He will be responsible for site accessibility, safety, and QA and will delegate further responsibilities to other members of the ORNL/MAD team. Specific responsibilities of the SPM are:

1. coordinates on-site operations, including logistics;
2. interfaces with plant and project personnel;
3. assists the SHSO when necessary;
4. participates in on-site characterization activities;
5. determines in-field procedural variances necessary to respond to site-specific conditions;

6. documents and reports unforeseen site-specific changes and corrective actions;
7. ensures that all quality-related activities are conducted in accordance with prescribed QA procedures;
8. notifies appropriate personnel of project work schedules; and
9. maintains and controls all site records and the field logbook.

2.10 SITE HEALTH AND SAFETY OFFICER

The SHSO, or a designated representative, with the support of the SPM, has primary responsibility for the following:

1. Ensuring that personnel receive this plan and are aware of its provisions, are instructed in safe work practices, and are familiar with potential hazards and planned emergency procedures, prior to initiation of site activities.
2. Notifying the Hazardous Waste Operations and Emergency Response (HAZWOPER) Program Coordinator of the names of individuals who require placement on the medical surveillance program, requesting that individuals volunteer any medical information that would necessitate special consideration (e.g., allergies, diabetes, and pregnancy), and keeping the provided medical information confidential.
3. Confirming with the Technical Resources and Training Section that on-site personnel have received the health and safety training that qualifies them to work at a hazardous waste site. On-site workers, at a minimum, are required to have 24 hours of training for hazardous waste workers as well as radiation worker training. If site conditions warrant an upgrade in the level of personal protective equipment, 40-hour training will be required. Each worker will supply the SHSO with a copy of training certification or present the special access training card at the pre-entry briefing.
4. Ensuring that all prospective site personnel sign and date a statement in the field logbook to verify that Items 1 through 3 were fulfilled.
5. Implementing health and safety plans and reporting to the SPM any deviations from anticipated conditions. If an unsafe condition or hazard arises during field activities, the SHSO is responsible for ordering operations to cease, safeguarding personnel, and reestablishing safe working conditions, upon obtaining guidance from IH, HP, or Industrial Safety.
6. Maintaining on-site copies of current training records or special access training cards for all on-site personnel to verify compliance with training requirements set forth in 29 CFR 1910.120.
7. Ensuring that each site worker has an up-to-date respirator card, indicating proper training and fit-testing.

8. Establishing site work zones and required levels of protection and establishing personal decontamination stations and instructing personnel in their use.
9. Establishing and making available at the site a separate emergency action plan, with telephone numbers and appropriate radiocommunication information.
10. Identifying key plant personnel (and alternatives) who are responsible for specific safety-related areas, such as health, plant safety, health physics, and industrial hygiene. In addition, establishing a liaison with the shift superintendent's organization to facilitate emergency response.
11. Minimizing the number of personnel and the amount of equipment in the EZ that is consistent with safe site operations.
12. Checking (in the field) the calibration of all monitoring equipment that will be used on a daily basis and recording the results in the field logbook.
13. Ensuring that all monitoring equipment is operating according to the manufacturer's specifications and instructions and providing maintenance if warranted.
14. Prior to commencing field work, ensuring that the penetration/excavation permit or other necessary permits have been generated and that a signed copy is available on-site.
15. Ensuring that personnel stay clear of overhead work and temporarily suspended equipment.
16. Ensuring that personnel are frisked by HP during egress from the CRZ.
17. Assisting personnel with the completion of report form(s) if needed. Ensuring that completed forms, either originals or copies, are returned to the ORNL/MAD SPM.
18. Providing continuous chemical monitoring for potential on-site contaminants while field operations are being conducted in the EZ or CRZ.

2.11 FIELD PROJECT PERSONNEL

Project personnel involved in on-site investigations and operations are responsible for:

1. Taking all reasonable precautions to prevent injury to themselves and their fellow employees by using every sense to detect potentially harmful situations.
2. Performing only those tasks that they believe they can do safely and immediately reporting any accidents and/or unsafe conditions to the SHSO and the SPM.
3. Notifying the SHSO of any medical conditions (e.g., allergies, diabetes, and pregnancy) that require special consideration. A medical department approval and/or a physician's

recommendation may be required before an individual with a medical condition can be assigned a specific field task.

4. Avoiding contact with potentially contaminated substances (i.e., walking through puddles, pools, and mud) and avoiding placement of monitoring/sampling equipment on a potentially contaminated surface.
5. If the tank is to be washed, preventing spillage whenever possible. If a spillage occurs, containing the liquid and notifying the SPM.
6. Avoiding splashing if the tank is being cleaned.
7. Being familiar with the physical characteristics of investigations, including
 - awareness of surroundings at all times;
 - accessibility to associates, equipment, and physical barriers;
 - communications;
 - hot zones (areas of known or suspected contamination);
 - site access; and
 - nearest site emergency resources.
8. Reporting all injuries, no matter how minor, to the SHSO and the SPM.
9. Abiding by a buddy system, so that each on-site worker is responsible for keeping track of his/her partner in the event of an incident.
10. Reporting to the ORNL Health Physics Technician for frisking prior to exiting the CRZ.
11. Conducting activities according to this plan and reporting any nonconformities to the SPM or the QAO.

2.12 PROJECT SUPPORT

The Building 3019B UST removal effort necessitates the participation of various Energy Systems organizations/disciplines. Representatives of each organization/discipline will provide technical support to the project as needed. This technical support may include review of and comment on project documentation, consultation, and/or professional insight applied to project problems. Project support is a collaborative effort with responsibilities dictated by an individual's particular organization/discipline or project involvement. Project support management is responsible for supplying only qualified personnel to work on this project.

2.13 FIELD OPERATIONS

Field operations include those individuals participating in the actual fuel tank removal and

subsequent sample collection at the Building 3019B 110-gal UST site. Personnel involved in the day-to-day field work include the ORNL/MAD SPM, SHSO, and field/site remediation personnel (subcontractors and student interns included). The tasks and responsibilities for these individuals are discussed in Sect. 15, the health and safety section.

The ORNL/MAD group leader and QAO contribute to the field operations effort but do not participate in daily field activities. The ORNL/MAD group leader is the line manager for ORNL/MAD personnel, including ORNL/MAD subcontractors and students.

2.14 ORNL INDUSTRIAL HYGIENE

The ORNL Industrial Hygiene Section shall be responsible for the oversight and approval of field investigative efforts related to industrial hygiene and the requirements of 29 CFR 1910.120. Within the IH Department, the HAZWOPER coordinator shall approve all plans prior to the mobilization and commencement of field activities. In addition, IH, as well as the HAZWOPER coordinator, shall have stop-work authority and may be consulted on questions of personal protective equipment and industrial hygiene monitoring and sampling. IH may be consulted to authorize a return to work after the hazard has been removed.

2.15 ORNL HEALTH PHYSICS

ORNL HP shall be responsible for the oversight and approval of field investigative efforts related to health physics. HP shall approve all plans prior to the mobilization and commencement of field activities. In addition, HP shall have stop-work authority and may be consulted on questions of personal protective equipment and health physics monitoring. HP may authorize a return to work after the hazard has been removed. An HP representative shall be on-site for scanning out of individuals as they exit the designated work zones.

2.16 ORNL INDUSTRIAL SAFETY

ORNL Industrial Safety will be responsible for oversight and approval of field investigative efforts related to safety. Industrial Safety will approve all plans prior to the mobilization and commencement of field activities. Industrial Safety shall have stop-work and continuation authority and will be consulted on questions of safety-related issues relevant to personnel, equipment and possibly personal protective equipment.

2.17 EMERGENCY CONTACTS

The Laboratory Shift Superintendent (LSS) at the X-10 ORNL Site coordinates 24-h emergency response coverage from the Power and Shift Operation Department of the Plant Support and Protection Management (PS&P) Division. The on-duty LSS, assisted by a well-

trained plant emergency squad, is the overall coordinator responsible for directing the response to emergencies such as fires, major equipment failure, hazardous materials releases or spills, natural disasters, and sabotage.

2.17.1 Emergency Phone Numbers

- Plant Phone: 911
- Emergency Communications Center: 574-6646

Contact the Shift Superintendent first. The Superintendent is the trained emergency response director.

574-6606

Listed below are emergency groups and their telephone numbers. A cellular phone may be present in the field and available for use when workers are not in close proximity to a plant phone.

Environmental Coordinator	574-5776
Security Patrol Captain	574-6646
Health Physics	574-6690
Industrial Hygiene	574-6165
Medical	574-7431
Public Relations	574-1640
Safety (Operations)	574-4337
Industrial Safety	574-6679
Protective Services Department	574-6277

2.17.2 Emergency Preparedness

Information in this section was obtained from the *ORNL Consultant and Visitor Environmental Safety, Health and Security Handbook* and the *ORNL Construction Environmental Safety and Health Handbook*.

The on-duty LSS is the designated Plant Emergency Director who is responsible for coordinating and responding to all emergency situations. The SHSO or the SPM will notify or assign someone to notify the LSS of an emergency situation as soon as possible.

A. REPORTING AN EMERGENCY

1. Telephone

- If using the plant telephone located on the north side of Building 3019 (see Fig. 1), dial 911. On a cellular phone, dial 574-6606.
- Describe the type of emergency.
- Identify the location of the emergency.
- Identify yourself.
- *In case of an injury, tell whether an ambulance is needed.*
- Listen to and follow any instructions that are given.

2. Fire Alarm Pull Boxes

The fire alarm pull boxes are located on the west corner of Building 3100 and near the main entrance to Building 3019 (see Fig. 1). Pulling a fire alarm box automatically transmits the location of the emergency to the Fire Department and the Emergency Control Center. Remain at the alarm box if conditions warrant to supply any needed information to the responding emergency squad. Fire alarm boxes in the Building 3019 area automatically initiate the Building 3019 evacuation siren when activated.

B. ALARM SIGNALS

1. Evacuation Alarms

Evacuation alarms are given via the plant public address (PA) system. The SHSO or SPM will designate the evacuation routes. Evacuate the site or area, proceed to the assembly point defined by the SHSO or SPM, and wait for further instructions. The Building 3019 assembly point is located on the east lawn of Building 2026.

2. Radiation Alarms

Radiation alarms are denoted by rotating red/magenta beacon lights and a steady sound from a clarion horn and the Building 3019 evacuation siren. Evacuate the site or area, proceed to the assembly point defined by the SHSO or SPM, and wait for further instructions.

3. Take-Cover Alarms

Take-cover alarms are denoted by the intermittent or wailing siren sound from the plant PA system. Seek immediate protective cover in a strong sheltered part of a building. Evacuate mobile structures to a permanent building.

4. Standard Alerting Tone

The standard alerting tone is a high-low tone from the plant PA system. Listen carefully; an emergency announcement will follow.

5. Building 3019 Evacuation Alarms

The Building 3019 evacuation alarm siren is activated automatically by the Building 3019 Facility Radiation Contamination Alarm System (FRCAS) and the local fire alarm system. The Building 3019 complex will be evacuated immediately by *all* personnel when the evacuation siren sounds.

C. EVACUATION PROCEDURES

- Familiarize yourself with the specific evacuation routes that are designated by the SHSO or SPM.
- In the event of an evacuation, proceed to the predetermined assembly point and wait for further instructions.
- The SHSO or SPM and crew will follow instructions given by the Emergency Response Team upon its arrival.

D. IMPORTANT REMINDERS

- Know the telephone number of the Laboratory Shift Superintendent, *574-6606 or, if using a plant phone, 911.*
- Know how to summon an ambulance: Dial *911* from a plant phone or *574-6606* from the cellular phone and give the location. Wait for the arrival of first-aid personnel.
- Be aware of the quickest way to summon the plant emergency squad: Pull a fire alarm box and wait for the arrival of the Emergency Response Team.

3. QUALITY ASSURANCE OBJECTIVES FOR MEASUREMENT DATA

QA objectives for measurement data describe procedures for sample documentation, collection, packaging, and preservation to ensure accuracy, precision, completeness, representativeness, and comparability in collection of environmental samples and subsequent analyses. This plan for the Building 3019B UST will address only those aspects dealing with health and safety for the tank removal. QA objectives for measurement data dealing with field measurement instrumentation that will be utilized by the ORNL/MAD representatives are listed in Table 2.

Table 2. Summary of sensitivity, precision, and accuracy criteria for Level I monitoring instrumentation*

Analytes	Instrument technique	Instrument range	Sensitivity	Precision	Accuracy
Organics	OVM photoionization	0.1-2000 ppm isobutylene (C ₄ H ₈)	0.1 ppm isobutylene (C ₄ H ₈)	NA ^a	NA
Organics	HNU photoionization	0.1-2000 ppm benzene (C ₆ H ₆)	0.1 ppm benzene (C ₆ H ₆)	±1% scale deflection	NA
Organics	OVA flame ionization	0.1-1000 ppm methane (CH ₄)	0.1 ppm methane (CH ₄)	NA	NA
Combustible gas	CGI catalytic sensor	0-100% LEL natural gas	1%, 2.5% natural gas	NA	NA
Oxygen (O ₂)	CGI electrochemical cell	0-40% O ₂	0.1% O ₂	NA	NA
Hydrogen sulfide (H ₂ S)	CGI electrochemical cell	0-100 ppm H ₂ S	1 ppm H ₂ S	NA	NA
Carbon monoxide (CO)	CGI electrochemical cell	0-300 ppm CO	1 ppm CO	NA	NA
Alpha-emitters	ZnS scintillation	0-3 × 10 ⁶ dpm	25 dpm	NA	±20%
Beta-emitters	GM Pancake gas ionization	0-500 × 10 ³ dpm ⁹⁰ Sr	Background-dependent	NA	±20%
Gamma-emitters	NaI scintillation	0-3 mR/h ¹³⁷ Cs	Background-dependent	NA	±20%

*Precision and accuracy for some Level I instrumentation cannot be obtained due to the varying conditions in the field monitoring environment.

^aNA=not applicable.

4. SAMPLING PROCEDURES

Sampling during the Building 3019B UST removal project will be conducted by the ORNL Environmental Surveillance Section with guidance from the ORNL Tank Management Group. The ORNL Measurement Applications and Development Group will be concerned with health and safety oversight and will not be involved in any way in the sampling and/or analysis process.

4.1 EQUIPMENT DECONTAMINATION

The equipment decontamination personnel at Building 3019B UST may be exposed to a variety of potential hazards. The potential contaminants of concern are defined in Sect. 15. Decontamination personnel may be responsible for conducting decontamination of all equipment utilized during the excavation procedures (personnel decontamination procedures are outlined in Sect. 15). Equipment decontamination will generally require level D+ protective equipment, including eye protection. Decontamination personnel may be exposed to splash or backspray during cleaning operations; therefore, protective clothing such as Tyvek® or a protective apron will be worn, in addition to a face shield mounted on a hard hat. Hearing protection will also be required because of the high noise levels emitted from the hot-water washer if decontamination is performed at the back of the hot-water washer or within a radius of 10 ft from the engine.

4.1.1 Discussion

This procedure applies to all equipment that comes in contact with the surface and subsurface material, as well as from the inside of the drum, such as shovels, scoops, or any lifting or pulling equipment that might be involved in the actual removal process.

4.1.2 Equipment

- Personal protective equipment
- Potable water
- Plastic tubs or buckets
- Scrub brushes
- Wire brush
- Disposable wipes
- Laboratory detergent (such as Alconox)
- Plastic bags
- Deionized water in stainless steel sprayers
- Ultrapure isopropyl alcohol
- Hot-water washer with washing trough
- 55-gal drums (17-E) to containerize all wash water
- Sheet plastic
- Aluminum foil
- Ziploc-type bags

4.13 Procedure

Equipment should be washed either in a bucket containing laboratory-grade detergent or in the decontamination trough. However, if excavation equipment is muddy, it should be rinsed with high-pressure hot water/steam prior to washing. The decontamination trough is designed to collect and drain all spoils into a containment reservoir. The wash solutions are transferred to a 55-gal (17-E) drum. Steps 4 and 5 in the following decontamination sequence will be performed in a dedicated containment reservoir to segregate those solutions for waste minimization purposes. The decontamination trough is shown in Fig. 4. The decontamination trailer that may be used by the investigation team is shown in Fig. 5.

The following decontamination sequence will be used to decontaminate excavation equipment:

1. Wash and scrub with laboratory-grade detergent and potable water.
2. Rinse with potable water.
3. Rinse with deionized water.
4. Rinse with ultrapure isopropyl alcohol.
5. Rinse with deionized water.
6. Drain or capture all spoils and associated solutions and transfer into a 55-gal (17-E) drum.
7. Air dry.
8. Keep in an uncontaminated area.

The liquid generated by the cleaning operation must be containerized with other decontamination waste for appropriate disposal. All decontamination should take place in a separate staging area within the CRZ. Cleaned equipment may be temporarily placed on a polyethylene sheet away from high-traffic areas to avoid contamination. Care must be taken in the selection of the staging decontamination area to avoid fugitive dust, fuel oils, gasoline, organic solvents, or other airborne sources of contamination. All excavation equipment must be cleaned and washed prior to use.

ORNL-DWG 90-9480

Fig. 4. Decontamination trough.

ORNL-PHOTO 353-90

ORNL-PHOTO 510-90

Fig. 5. Decontamination trailer.

5. SAMPLE DOCUMENTATION AND CUSTODY

Sampling during the Building 3019B UST removal project will be conducted by the ORNL Environmental Surveillance Section with guidance from the ORNL Tank Management Group. The ORNL Measurement Applications and Development Group will be concerned with health and safety oversight and will not be involved in any way in the sampling and/or analysis process.

6. CALIBRATION PROCEDURES

Continuous real-time assessment of potentially hazardous materials concentrations will be performed on the site during the UST removal activities. The monitoring program is designed to protect members of the team from possible hazards associated with site-specific activities.

6.1 MONITORING PROGRAM

Continuous real-time assessment of potentially hazardous chemical concentrations and radiological levels will be performed by the SHSO or designated assistant while conducting operations at the UST site. The deployment of monitoring equipment will depend on the site-specific activities being conducted. Radiological monitoring equipment shall be required for all phases of the tank removal project because the tank is located within a designated radiological control area. ORNL HP will provide a technician to conduct all on-site radiological monitoring. Excavation activities require the use of specific chemical and radiological monitoring equipment. This monitoring program is designed to protect all on-site investigative personnel from potential chemical and radiological contaminants, using available information and resources. These contaminants are identified in the contaminant matrices table located in the health and safety section of this plan (Sect. 15).

The Comprehensive Environmental Response, Compensation and Liability Act of 1980 (CERCLA) defines five levels of analytical criteria for data collection. These levels are I-V and are defined in the Environmental Protection Agency (EPA) *Data Quality Objectives for Remedial Response Activities Development Process* (1987). Quality control Level I has been specified for use with field instruments.

6.1.1 Instrument Calibration

All applicable instruments shall be calibrated within the proper time frame and in accordance with the manufacturer's recommendations and specifications described in the manufacturer's standard operating procedures (SOPs). Calibration readings, the lot number from the calibration gas cylinder, the calibration gas manufacturer, each radiological source number, and other calibration information will be recorded on the Field Logbook Calibration Page (Fig. 6) located in the field logbook in a section dedicated to calibration and vital information about the instruments.

All chemical instrument calibration gases will be purchased from a laboratory instrumentation gas supply company. Each calibration gas cylinder must contain a manufacturer's label containing the lot number, manufacturer's name, type of gas, and parts per million or percentage of gas contained within the cylinder.

6.1.2 Calibration Frequency

All instruments will be calibrated or field-checked daily while in service or more frequently as recommended by the SHSO. More frequent calibrations may be deemed necessary if the instrument malfunctions, the batteries are replaced or recharged, or the first calibration does not equilibrate properly. If the instrument still does not meet manufacturer's SOP after recalibration or field check, it will be removed from service.

6.1.3 Background Readings

Before any field activities commence, background concentrations and levels near the site will be monitored and recorded as specified in this section. To obtain accurate results, daily background readings must take place away from areas of potential contamination. Background readings will be taken into account before an action level is established.

6.2 CHEMICAL MONITORING

6.2.1 Chemical Monitoring Equipment

Equipment necessary for environmental on-site monitoring could include the following: a photoionization detector (PID), such as an organic vapor monitor (OVM) or an HNU (equipped with an 11.8- or 11.7-eV lamp); a flame ionization detector (FID); or a four-sensor combustible gas indicator (CGI), such as a GasTech model GX86. Some or all of these instruments could be utilized throughout this fuel tank removal operation.

6.2.2 Organic Vapor Monitor

The OVM uses a PID to detect trace concentrations of many volatile organic chemicals, trace gases, and vapors in air. The OVM will utilize a uv (11.8-eV) lamp. Although the OVM is capable of using other lamps, the 11.8-eV lamp is necessary to detect the potential contaminants of interest at the UST site. The OVM has an operating range of 0 to 2000 ppm. The minimum concentration that the unit may detect is 0.1 ppm.

A positive displacement pump in the OVM continuously draws an air sample from the ambient-air area being monitored. The air sample is first drawn through a filter within the probe of the instrument that is designed to withdraw moisture, in the form of water, from the air stream. An inherent problem associated with PIDs is excessive water in the air stream, which can result in a negative voltage drop that can render the instrument ineffective for health and safety monitoring. In many cases, excessive numerical fluctuations in ppm displayed on the instrument are indicative of a moisture problem. In addition, the lamp window material is very hygroscopic, and accumulation of moisture can render the lamp inoperable.

From the probe, the air stream passes through the ionization chamber where trace gases and vapors that have ionization potentials close to, or below, the 11.8 eV energy may be photoionized. The positive current produced by the excitation of an electron is

then amplified, and the current is related to a representative concentration in ppm. The OVM is purely a qualitative instrument, Level I. The OVM is not designed to be chemically specific; it measures a total concentration of vapors and gases detectable in the air stream.

6.2.3 Organic Vapor Monitor Calibration

The OVM will be calibrated in accordance with the manufacturer's SOP and this plan. The following procedures are required for calibrating the OVM.

1. Disconnect the OVM from the battery charger.
2. Insert the power plug from the OVM into the Run/Chg receptacle.
3. Hold down the ON button on the far left of the key pad. The instrument should turn on, and the pump should be audible.
4. Press the Mode/Store button.
5. A message will appear on the screen asking if you wish to record the data point. Press (-) for no.
6. The menu screen will then appear. Select and press (-) again for the parameter mode of the instrument.
7. The screen will then display "Conc. Meter Reset." To change, press (+).
8. The instrument will then display "Auto Login Reset." To change, press (+).
9. The next display will be "Average = 0:01 Reset" to change. This number will enable the instrument to display an average concentration every second while monitoring. If the instrument is not averaging every second, press the reset button and change the number. The (+) will allow you to increase the time interval, while the (-) will allow you to move the cursor from one place to another. Press "Reset" when this is finished and proceed with the next step. If the instrument is already set up to average every second, depress the (+) button.
10. The next display will show that the alarm has been preset to 1.0 ppm. Depress the (+) button.
11. The next display will show that the instrument is operating with an 11.8-eV lamp. If any other than the 11.8-eV lamp is displayed, select the 11.8-eV lamp.

Instrument Number	Detection Method	Date / Military Time	Battery Check	Background Reading	Source Response to Calibrating Gas	Source No. Manufacturer/Lot No.
3490-04P	Beta/Gamma	4-22-91 10:00	OK	33 cpm	1846 cpm	S-04P
3490-21SG	Gamma	4-22-91 10:00	OK	2.5K cpm	22K cpm	3490-35
3490-14S	Alpha	4-22-91 10:00	OK	1 cpm	1022 cpm	S-1849
CGI #3	CGI	4-22-91 10:00	2.7 V	20.9% O ₂ 0% LEL CH ₄ 0 ppm H ₂ S 0 ppm CO	50% LEL CH ₄ 20.9% O ₂ 25 ppm H ₂ S 50 ppm CO	Gastech / 0069 Alphagaz / 1357 Alphagaz / 9876 Alphagaz / 0078
OVM #1	PID	4-22-91 10:00	OK	0.00 ppm	100 ppm isobutylene	HNu Systems/5656
HNu #2	PID	4-22-91 10:00	OK	1.2 ppm	Span 5.12 100 ppm isobutylene as 66 ppm benzene	HNu Systems/5656
Name of Calibrator:	X					Date:

Fig. 6. Example of information for field logbook calibration page.

12. Press "+" to continue.
13. RF = 1.00 will be displayed next. The response factor should always be set at 1.00. Press the (+) button to proceed.
14. Press the reset button to calibrate the instrument.
15. Depress the (-) button.
16. Depress the reset button to zero the instrument in the ambient air. The instrument is zeroed in the ambient air environment, as opposed to using zero air, so that natural background will be excluded.
17. When the instrument finishes zeroing itself, the display should read "Span [] of 100 ppm." Press (+) to continue. The instrument displays "Span Gas Reset When Ready." Open the Tedlar (tm) bag containing the calibration gas of choice, and attach it to the instrument. Press "Reset" to begin calibration. The instrument will display "Model 580 Calibrating." When calibration is complete, "Reset to Calibrate" appears. Detach the tubing and close the tedlar bag. Press "Mode/Store" to operate the instrument. The instrument should display "0.00 ppm" fairly consistently as the ambient air background.
18. Record calibration data in the field logbook in the section designated for calibration information (See Fig. 6).
19. A response check will be performed to ensure that the alarm will sound at a specified setting when tested against a known chemical. When the alarm sounds, it should correspond with the digital display on the instrument to reveal the specified setting (i.e., 1 ppm).

6.2.4 HNU Photoionization Detector

The HNU uses a PID to detect trace concentrations of many volatile organic chemicals, trace gases, and vapors in air. The HNU will utilize a uv (11.7-eV) lamp. Although the HNU is capable of using other lamps with separate probe combinations, the 11.7-eV lamp is necessary to detect the potential contaminants of interest with high ionization potentials. Sites that may utilize a PID that requires a lower ionization potential lamp may employ the 10.2-eV probe in combination with the HNU. The HNU has an operating range of 0 to 2000 ppm. The minimum concentration that the unit may detect is 0.2 ppm.

A fan in the HNU helps to continuously draw an air sample from the ambient-air area being monitored. The air sample is first drawn through a probe extension tube of the instrument. An inherent problem associated with PIDs is excessive water in the air stream, (i.e., high humidity), which can result in a negative voltage drop that can render

the instrument ineffective for health and safety monitoring. In many cases, excessive numerical fluctuations in ppm displayed on the instrument are indicative of a moisture problem. In addition, the lamp window material of the higher ionization potential lamps are very hygroscopic, and accumulation of moisture can render the lamp inoperable.

From the probe extension tube, the air stream passes through the ionization chamber, where trace gases and vapors that have ionization potentials close to, or below, the lamp's eV energy may be photoionized. The positive current produced by the excitation of an electron is then amplified, and the current is related to a representative concentration in ppm. The HNU is purely a qualitative instrument, Level I. The HNU is not designed to be chemically specific; it measures a total concentration of vapors and gases detectable in the air stream.

6.2.5 HNU Photoionization Detector Calibration

The HNU will be calibrated in accordance with the manufacturer's SOPs and as detailed in this general document. The procedure for calibration of the HNU follows:

1. Turn the instrument on and record the condition of the battery in the site-specific logbook.
2. Turn the function switch to standby, and zero the instrument using the zero adjust knob.
3. Turn the function switch to the 0–200 ppm scale.
4. Connect the regulator to the isobutylene span gas cylinder. Connect the tubing to the tip of the regulator and to the tip of the instrument probe extension. It is imperative that a regulator allowing approximately 0.5 L/min is utilized with this instrument. Using a regulator that allows more than 0.5 L/min span gas may cause irreparable damage to the instrument.
5. Open the regulator valve completely.
6. Unlock the span control knob, and allow the instrument to stabilize.
7. Adjust the span setting so that the needle is on the appropriate reading. The correct reading is dependent on the concentration of span gas utilized in conjunction with any response factors the SHSO requires. Always check with the SHSO to determine the appropriate span setting.
8. Lock the span control knob when the adjustment to it provides the appropriate concentration, as required by the SHSO.
9. Turn off the regulator valve and disconnect the tubing from the regulator and the probe extension. Disconnect the regulator from the span gas cylinder.

10. Turn the function switch to the standby function. Determine if the instrument has maintained a zero reading. If the instrument has retained a zero reading, turn the function switch to the 0–20 scale. Record the background concentration in the ambient air. Normally, the instrument background concentration will be approximately 1.0 ppm or less. It is possible to have a background concentration greater than 1.0 ppm. If this is the case, the instrument may be used only if the readings are stable and the instrument maintains zero. If the instrument becomes unstable through operation, it should be recalibrated.
11. Record calibration data in the field logbook in the section designated for calibration information (See Fig. 6).

6.2.6 Flame Ionization Detector

An FID such as an OVA-128 analyzer is designed to detect and measure organic vapors and gases. The instrument utilizes the principle of hydrogen flame ionization for detection and measurement of organic vapors and gases.

6.2.7 Flame Ionization Detector Calibration

Daily calibration of the FID is required prior to use in the field. Start-up and calibration procedures follow.

1. Move pump switch to the ON position and check the battery condition by moving the instrument switch to the battery position.
2. Move instrument switch to the ON position and allow 5 min for warmup.
3. Set alarm level adjustment knob on back of readout assembly to desired level.
4. Set calibration switch to the (X10) position. Use the calibration knob and set the meter to read zero.
5. Place instrument panel in vertical position and check sample flow rate indication.
6. Open the H₂ tank valve and the H₂ supply valve.
7. Depress the igniter button until burner lights. Do not depress igniter button for more than 6 s. If burner does not ignite, let instrument run for several minutes and try again.
8. Calibrate to "zero out" ambient background.
9. To shut down the OVA, close the H₂ supply valve and the H₂ tank valve. Turn the instrument switch and the pump switch to OFF.

10. Record calibration data in the field logbook in the section designated for calibration information (See Fig. 6).
11. A response check will be performed to ensure that the alarm will sound at the specified setting when tested against a known chemical. When the alarm sounds, it should correspond with the needle indication within the gauge of the instrument to reveal the specified setting.

6.2.8 Combustible Gas Indicator

A Gastech GX-86 four-sensor CGI or equivalent will be utilized on-site by the SHSO. The GX-86 is designed to detect potential hazards that may be posed by combustible gases, oxygen deficiency/enrichment, carbon monoxide, and hydrogen sulfide. The CGI utilized on-site should be equipped with circuitry that warrants the unit intrinsically safe, thereby allowing its operation in Class I, Division I, Group C or Group D hazardous atmospheres without risk of ignition.

Detection of the parameters indicated previously occurs through diffusion. The combustible gas detector is a replaceable plug-in sensor that is retained via a bayonet-shaped base. The sensor consists of a platinum catalyst and an electrically identical noncatalytic reference element. The noncatalytic element serves to compensate for noncombustible gases and temperature variations. The carbon monoxide and hydrogen sulfide detectors are secured by a bayonet-shaped fitting. The carbon monoxide detector utilizes a charcoal filter that is held in place by a rubber retaining ring. These sensors are equipped with an electrochemical cell that consists of two precious-metal electrodes in an acid electrolyte, covered with a permeable membrane composed of a fluorocarbon. The gas enters into the sensor and an electrochemical reaction produces a current that is proportional to the concentration of gas. The oxygen detector contains a sensor that consists of an electrochemical cell. The cell is composed of a gold and lead electrode in an alkaline electrolyte. The electrochemical reaction produces a current that is proportional to the percentage of oxygen in the environment.

6.2.9 Chemical Monitoring Frequency

Volatile organic and combustible gas monitoring that uses the PID, FID, CGI, or equivalents will be performed on entering a potentially hazardous site while work is being conducted within the EZ. Continuous monitoring that uses all chemical monitoring equipment required will be performed to ensure, within the levels of detection of the instrumentation employed, that the site is void of hazardous gas/vapor concentrations at the breathing zone. Some of the aforementioned instrumentation may be utilized during the tank excavation process. All data for each monitoring occurrence will be recorded. A sample Field Monitoring Record is shown in Fig. 7.

6.2.10 Chemical Monitoring Equipment Action Limits

The GX-86 is equipped with a microprocessing unit that allows continuous monitoring

of the four parameters simultaneously. Standard lower and higher factory alarm settings for the GX-86 instrument are:

LEL	10%	and	50%
O ₂	19.5%	and	22%
H ₂ S	10	and	30 ppm
CO	35	and	100 ppm

The tone emitted when a preset alarm level is reached is an intermittent pulse for the lower alarm and a continuous tone for the higher alarm. The OVM employs an alarm that is preset to 5.00 ppm. The action level for the GX-86 is equal to the lower alarm setting for the LEL, O₂, H₂S, and CO.

If volatile organic concentrations measured on the OVM, HNU or FID exceed 5 ppm above background concentrations measured in the breathing zone for more than five minutes, all personnel, at the direction of the SHSO, should evacuate the work site upwind and to the border of the CRZ and the support zone. The same requirements for work site evacuation will be employed if any of the action limits developed for the GX-86 are met or exceeded for more than 30 s in the breathing zone. An industrial hygienist representing ORNL will be summoned to the site, if not already present, to assess the potential hazard of the conditions and to determine whether or not work should continue. It may become necessary to abandon the monitoring location and proceed to the next monitoring location.

6.3 RADIOLOGICAL MONITORING

6.3.1 Radiological Monitoring Equipment

All radiological monitoring and instrumentation at the Building 3019B 110-gal UST will be the responsibility of the ORNL HP Department. A representative will be on the site throughout the entire tank removal process as well as subsequent sampling and pit closure activities. These radiological instrumentation and monitoring procedures are followed by the MAD group and may differ from those procedures followed by ORNL HP. The ORNL HP personnel will follow procedures for instrument calibration and usage as specified in the ORNL *Health Physics Manual* (1990). If at any time a representative from the MAD group is called on to render assistance to the on-site health physicist, the procedures listed below will be followed.

All radiological monitoring equipment used in the field is required to have up-to-date calibration stickers. No uncalibrated instrument will be used. Instruments are maintained on an annual calibration schedule. All instruments are calibrated by ORNL Instrumentation and Controls Division and are calibrated in accordance with National

Institute of Science and Technology (NIST) standards and procedures. It is also necessary to note that instrument and probe combinations are calibrated as a set; therefore, ratemeters and probes shall not be interchanged. If an instrument malfunctions, it will be returned to the ORNL/MAD instrument technician for repairs and/or recalibration. Instrument response check measures performed in the field are not a substitute for calibration. Radiological equipment necessary to conduct on-site monitoring shall consist of the following portable detector systems or equivalents:

<u>Meter</u>	<u>Probe</u>	<u>Purpose</u>
Bicron Analyst	Eberline HP-260, Geiger-Mueller (GM) pancake with fine mesh screen	Monitor beta-gamma surface contamination levels
Victoreen 490	Victoreen 489-55	Gross gamma monitoring/scanning
Bicron Analyst	ORNL Q2101, "beer mug," ZnS scintillator	Monitor alpha surface contamination levels

6.3.2 NaI Scintillation Detector Source Check Procedures

Each scintillation detector must undergo a daily radiation source check prior to use in the field. Affixed to each instrument is a source check validation label. Information on the label details a source number and the maximum and minimum acceptable responses that should be obtained when the instrument is checked with the indicated source. If the detector does not respond within the indicated range, the instrument must be removed from service and returned to the ORNL/MAD instrument technician. If the indicated source is unavailable, a correction factor for the desired source to be used may be obtained from the ORNL/MAD instrument technician. If the correction factor for this source is known, the instrument response to the source may be correlated with the response ranges listed on the instrument source check validation label. Source check response procedures follow:

1. Turn the scintillator on and record the condition of the battery in the logbook.
2. Record the instrument number and the source number in the logbook.
3. Turn the selector switch to the (X10) setting; record in the logbook the background in counts per minute (cpm) and where the reading was obtained.
4. Turn the selector switch to the (X100) setting.
5. Place the source against the detector portion of the probe, with the long axis of the source parallel to the long axis of the probe. Place the narrow edge of the source against the probe.
6. Rotate the source around the surface of the probe, and record the highest response in cpm in the logbook.

7. Confirm that the reading is within the acceptable range denoted on the source check validation label affixed to the side of the instrument. If it is not, return the instrument to the ORNL/MAD instrument technician.
8. If the instrument is not to be used immediately, turn it off to conserve the batteries.
9. If the instrument appears to respond abnormally during the course of its intended use, the preceding source check procedure should be repeated to ascertain whether the instrument is functioning properly.
10. Store the source in an approved storage location.

6.3.3 GM Pancake Detector Source Check Procedures

Each GM pancake detector requires a daily radiation source check to be performed prior to use in the field. Affixed to each instrument is a source check validation label and source. Information on the label details the source and the maximum and minimum acceptable responses that should be obtained when the instrument is checked with the source. If the detector does not respond within the indicated range, the instrument must be removed from service and returned to the ORNL/MAD instrument technician. If the source is not affixed to the side of the instrument, a correction factor for an alternative source to be used may be obtained from the ORNL/MAD instrument technician. If the correction factor for this source is known, the instrument response to the source may be correlated with the response ranges listed on the instrument source check validation label. Source check response procedures follow.

1. Turn the instrument on and record the condition of the battery in the logbook.
2. Record the instrument number and the source number in the logbook.
3. Obtain a 1-min background scaler reading; record this reading and where it was taken in the logbook.
4. Place the detector probe against the source and obtain a 1-min scaler reading. Record this reading in the logbook.
5. Confirm that the scaler count is within the acceptable range, as indicated on the source check validation label affixed to the instrument.
6. If the instrument is not to be used immediately, turn it off to conserve the batteries.
7. If the instrument appears to respond abnormally during the course of its intended use, the preceding source check procedure should be repeated to ascertain whether the instrument is functioning properly.

6.3.4 ZnS Alpha Scintillation Detector

Each ZnS Alpha Scintillation Detector requires a daily radiation source check to be performed prior to use in the field. Affixed to each instrument is a source check validation label. Information on the label details the source and the maximum and minimum acceptable responses that should be obtained when the instrument is checked with the source. If the detector does not respond within the indicated range, the instrument must be removed from service and returned to the ORNL/MAD instrument

[illegible]

AAA = Ambient Air; BZ = Breathing Zone; BS = Borehole Space; SS = Soil Sample; X = Background
 °O₂ and LEL are given as percent; NA = Not Applicable

UCN 1704A (2 11-91)

Fig. 7. Field monitoring record

technician. If the indicated source is unavailable, a correction factor for an alternative source may be obtained from the ORNL/MAD instrument technician. If the correction factor for this source is known, the instrument response to the source may be correlated with the response ranges listed on the instrument source check validation label. Source check response procedures follow:

1. Turn the instrument on and record the condition of the battery in the logbook.
2. Record the instrument number and the source number in the logbook.
3. Obtain a 1-min background scaler reading; record this reading and the location where it was taken in the logbook.
4. Leave the source in the storage case. Open the cover and place the probe on the source inside the opened case so that the arrow on the probe is aligned with the source case. The edge of the probe should be in contact with the hinge but should not be placed on top of the hinge.
5. Obtain a 1-min scaler and determine if the counts obtained are within the acceptable range as denoted on the source check validation label affixed to the instrument.
6. If the instrument is not to be used immediately, turn it off to conserve the batteries.
7. If the instrument appears to respond abnormally during the course of its intended use, the preceding source check procedure should be repeated to ascertain whether the instrument is functioning properly.
8. Store the source in an approved storage location.

6.3.5 Radiological Frequency and Action Limits

Radiological scanning of the soil will be performed at the Building 3019B UST throughout the entire project. Evacuation will be required when the following action levels have been reached: (1) a count rate of 2000 cpm above background at 1 ft above the ground surface, measured with the GM pancake instrument, or (2) a count rate of 800,000 cpm at 1 ft above the ground surface, measured with the NaI scintillator. Should such action levels be indicated, all personnel will move from the work site to the CRZ. The on-site health physicist will assess the potential hazard and determine whether work should continue. ORNL HP will be responsible for any necessary posting of contaminated areas identified during the site investigation and field work.

The GM pancake instrument or other instrumentation is utilized by the HP Department will be used to monitor the soil as close to the surface as possible and to monitor potential radiation levels around the workers. It should not be assumed that the breathing zone of site investigative personnel is monitored during this process. All data collected for each monitoring occurrence will be recorded by the HP or his/her designee for maintaining radiological monitoring information. The radioactive contamination release limits for equipment, clothing, and skin at the Building 3019B site are listed in Table 3.

Table 3. Building 3019B UST radioactive contamination release limits in dpm/100 cm²

	Alpha		Beta-gamma	
	Direct ^a	Removable ^b	Direct ^a	Removable ^b
Skin	150	None detectable	1000	None detectable
Clothing	300	Not applicable	1000	Not applicable
Equipment	300	20	1000	200

^aFixed plus removable.^bTransferable.

Frisking or scanning of each worker's hands and footwear will be performed, and release limits must be met before an individual can leave the CRZ. The alpha and beta-gamma instruments give readings in cpm; therefore, a conversion is required to compare field readings to contamination release limits, which are given in disintegrations per minute per 100 cm² (dpm/100 cm²). Each alpha instrument has a conversion factor posted on it. This conversion factor will normally range from 7 to 12 dpm/100 cm²/cpm. The GM pancake instruments do not have conversion factors posted on them because factors vary, depending on the nuclide of interest, the surface material (e.g., concrete, steel, and clothing), and the probe efficiency. Based on calculations made by R. L. Coleman of ORNL/MAD, a conservative conversion factor of 40 dpm/100 cm²/cpm should be used for estimating beta surface contamination levels with an Eberline HP-260 Pancake probe.

6.3.6 Radiological Contamination Control

The *ORNL Health Physics Procedures Manual* (RP-2.5) provides the guidelines and limits for control of radioactive contamination, including area, material, and personnel contamination limits.

7. ANALYTICAL PROCEDURES

The analytical procedures for total petroleum hydrocarbons (TPH) and butylene, toluene, and xylene (BTX) in soil will be the standard EPA procedures. The analytical procedures will be written by the ORNL Analytical Chemistry Division.

8. DATA MANAGEMENT PROCEDURES

All field measurement data collected at the Building 3019B UST site is subject to Level I analysis and does not require a formal validation process, according to CERCLA guidance for conducting remedial investigations and feasibility studies (EPA 1988). This data will be reviewed and maintained by the ORNL/MAD group. Copies of measurement data will be made available to ORNL IH as well as individuals from the Radiochemical Technical Section, if needed.

Field measurement data collected during the project will be recorded or documented in the site-specific Building 3019B UST field logbook and the field monitoring record (Fig. 7). This data will be recorded periodically (approximately every 10 min) in the logbook while operations are being conducted in the CRZ and/or the EZ. Field parameters measured will include oxygen, carbon monoxide, hydrogen sulfide, and combustibles.

9. INTERNAL QUALITY CONTROL REQUIREMENTS

9.1 INTRODUCTION

This section of the plan addresses quality control (QC) requirements for laboratory activities and field monitoring, which are subject to Level III and Level I quality control, respectively. Level III and Level I analyses are QC requirements for data collection. Level III applies to analytical laboratory instrumentation and is subject to all formal validation procedures and reviews. Level I analysis is used for field monitoring instrumentation and is not subject to validation procedures. Items that would be covered in laboratory QC include

- replicates,
- spiked samples,
- split samples,
- control charts,
- blanks,
- internal standards,
- zero and span gases, and
- quality control samples.

Because the scope of this plan is limited to health and safety aspects of the project, only Level I internal QC measures for field monitoring instruments will be discussed here. Laboratory analysis and field sampling concerns will be addressed in the separate Sampling and Analysis Plan to be written by the ORNL Analytical Chemistry Division.

9.2 INTERNAL QC FOR FIELD MONITORING INSTRUMENTS

9.2.1 Chemical Span Gases

Span gases for chemical monitoring instruments are secondary standards that are provided by the manufacturer or a certified supplier. Each cylinder is stamped with a specific lot number, which can be used to trace the cylinder back to its manufacturer if a problem arises. Such problems might include receiving empty bottles, damaged cylinders, or bent fill stems. All calibration cylinders are secured in a locked room or trailer when not in use.

9.2.2 Radiological Check Sources

All radiological instruments are calibrated by the procedures listed in Sect. 6. Field check sources are used to establish a reference point by which to check the validity of the instrument during the calibration period. Check sources are used as reference sources only. When comparing the calibrated instrument to a specific check source, the instrument must read within 20% of source response following primary calibration. Activity of an individual source is constant and should not vary more than 1.5% of its

value over a 6-month period. This requires that the half-life of the specific source isotope be greater than or equal to 23 years.

10. PERFORMANCE AND SYSTEM AUDITS

Audits shall be made of field activities performed by Energy System personnel and subcontractors. Audits are required to ensure "the quality of the work being performed." Audit preparation will include review of pertinent background information, procedures, and technical documents to acquaint the auditing team with the activity in question. A review of past records will assist auditors in recognizing previous problems and learning what types of corrective action were used in such situations.

The role of audits in the overall management program is verification. Although audits do not improve data quality, if all work is correctly performed, they do provide assurance that the work prescribed for the measurement program has been conducted properly.

Audits are very important to the QC program. They provide a documented means of detecting missing QC requirements and potential problem areas. Audits form one of the bases for corrective action requirements and constitute a permanent record of the conformance of measurement systems to QA requirements.

Two types of audits will be used to monitor and document conformance with the quality assurance project plan: performance and system audits. Performance audits are made to quantitatively evaluate the quality of data produced by the total measurement system. Performance audits provide objective assessments of the accuracy of the data collected by a given measurement system. They also provide identification of out-of-control measurements and systematic bias. Measurement of improvement in data quality can be obtained by comparing data from previous and current audits. System audits are qualitative on-site inspections and reviews of the total measurement system. The auditor should have extensive background experience with the measurement system being audited.

10.1 AUDIT RECORDS

Audit records include reports, responses to checklists, and corrective actions taken. These records shall be properly documented as a QA record. The ORNL/MAD QAO will evaluate findings of the audit reports along with the results of surveillance reports and any deficiency reports. Copies of any QA audits or surveillance will be supplied to the ORNL/MAD QAO for review and filing.

10.2 FIELD AUDITS

Field audits, or more appropriately, field surveillance, will involve short-duration monitoring or the observance of an item or activity, generally by a qualified person designated as a QA surveillant. The ORNL/MAD QAO will conduct surveillance of the ongoing field activities. Surveillance, as contrasted with audits, grants wide latitude to the surveillant during the course of the surveillance. The qualified person must *not* be directly involved in the performance of the activities surveilled and must have

- appropriate technical expertise in the area being surveilled;
- access to pertinent references, procedures, drawings, specifications, etc.;
- access to the area where surveillance is to be conducted.

Typical surveillance activities include:

- performing a general review of procedures, instructions, and associated documents applicable to the project and
- observing ongoing work activities and associated QA activities to verify that these work activities are being performed in accordance with project documentation.

The results of the surveillance will be discussed with the person(s) who performed the work activity. These results are documented and signed by the surveillant. The field audits and surveillance reports generated by the ORNL/MAD QAO will be maintained on file by the MAD QAO. The MAD QAO surveillance reports, including explanation of methods used to address discrepancies, will be forwarded to the MAD group leader for review and determination that problems have been adequately addressed. All reports and audits by any other surveillance organization will be the property of and maintained by that organization.

11. PREVENTIVE MAINTENANCE

In this section, preventive maintenance procedures are only described for field monitoring instruments and radiological equipment owned and maintained by ORNL/MAD.

11.1 FIELD SAMPLING INSTRUMENTS

To ensure compliance of all field sampling instruments and to minimize instrument malfunctions and/or failure, the ORNL/MAD group implements a preventive maintenance program for group-owned instruments. All ORNL/MAD instruments are sent annually to the manufacturer for maintenance and factory recalibration. See Sect. 6 for specific information on instrument calibration and maintenance. Instruments whose annual factory calibration is overdue shall not be used in the field until they have been calibrated by the manufacturer or an approved service center.

A data base is employed by the ORNL/MAD instrument technicians to track maintenance histories as well as calibration dates for each instrument maintained by the group. When an instrument is returned to the instrument technicians because of failure or expiration of the instrument's factory calibration, the technicians will record the instrument in the data base. The technicians will then repair the instrument or return it to its specific factory. On receiving the instrument from the factory, a new calibration sticker will be affixed to the side of the instrument, and the instrument will be returned to the field for use. The date and corrective action taken at the factory will be entered in the data base for future reference.

A daily calibration, or instrument response check, is performed (see Sect. 6) on each instrument before it is used in the field. Instruments that do not meet factory standards for any reason are removed from service. An instrument's removal is documented in the field logbook, and the instrument is returned to the ORNL/MAD laboratory for maintenance. If the ORNL/MAD instrument technician cannot repair it, the instrument is returned to the manufacturer or ORNL repair facility (ORNL Instrumentation and Controls Division).

Instruments belonging to the ORNL IH Department are maintained and calibrated through that department's preventive maintenance program, which ensures the reliability and compliance of its own equipment. Instrumentation used by the ORNL IH Department usually differs from instrumentation employed by ORNL/MAD; therefore, each group utilizes its own instrumentation procedures.

The nature and intended use of instruments in the field require anticipation of potential problems. To minimize down time resulting from instrument failure, backup instruments will be calibrated and maintained in the support zone (see Sect. 15.3) whenever possible.

11.2 RADIOLOGICAL INSTRUMENTS

All radiological instruments owned by the MAD group are maintained and calibrated by the ORNL/MAD instrument technician, instrument manufacturer, ORNL Instrumentation and Controls/Office of Environmental and Health Protection, and/or private contracting facilities in accordance with manufacturers' specifications and NIST standards. Response check requirements for each instrument and additional requirements for radiological field screening instrumentation may be found in Sect. 6.

Radiological Field Screening Equipment, Supplies, or Parts:

- Check sources
- Batteries

11.3 CHEMICAL DETECTION INSTRUMENTS

All chemical detection instruments are maintained and calibrated by ORNL/MAD in accordance with the manufacturer's SOP. Parts may be replaced and/or repaired without returning the instrument directly to the factory; therefore, whenever possible, maintenance of critical replacement parts is a valuable measure to ensure uninterrupted operations.

Preventive maintenance for all instruments is performed in accordance with the manufacturer's SOP. An example of a preventive maintenance schedule and a listing of critical replacement parts for each class of detection instruments most commonly kept in stock are listed below.

11.3.1 Photoionization Detectors

Preventive maintenance on the PID should be performed weekly while the instrument is in use or as needed when not in service. This maintenance consists of a general cleaning of the instrument, its lamp, and ion chamber.

Critical parts list For PID:

- Replacement lamp for each PID
- Lamp cleaning compounds/solutions
- Replacement battery packs
- Calibration equipment and gas

11.3.2 Combustible Gas Indicator

Preventive maintenance on the CGI should be performed weekly while the instrument is in use or as needed when not in service. This maintenance consists of a general cleaning of the instrument, replacement of batteries, carbon monoxide sensor filter change, and sensor changes if needed.

Critical parts list For CGI:

- Replacement sensors
- Replacement batteries
- Confined space entry kit
- Calibration equipment and gas

11.3.3 Flame Ionization Detector

Preventive maintenance for the FID should be performed weekly while the instrument is in use or as needed when not in service. This maintenance consists of a general cleaning of the instrument and recharging of the hydrogen gas cylinder.

Critical parts list For FID:

- Calibration equipment and gas
- Critical parts and backup instrumentation (currently not available)
- Supply of hydrogen gas

12. PROCEDURES USED TO ASSESS DATA PRECISION, ACCURACY, AND COMPLETENESS

The processing of QC sample results will not be addressed in this health and safety plan. In addition, all field measurement data collected at the Building 3019B UST site will meet Level I criteria and are, therefore, nonquantitative in nature and used only as indicative parameters. Equipment capability or the analytical QC implemented will limit data obtained to qualitative or, at best, semiquantitative. Thus, Level I measurement data will be used in this document only for the following: (1) delineation of contaminated zones and (2) health and safety screening. Field measurement instrumentation detection limits and precision are presented in Table 2.

13. CORRECTIVE ACTIONS

Corrective actions are those measures taken to rectify any occurrence that fails to follow QC criteria specified in this health and safety plan. Corrective action may be initiated by any person performing work or involved in support of the project at any time.

13.1 FIELD ACTIVITIES

The majority of corrective actions will be of short duration. Examples include documentation errors or failure to date and sign a field monitoring form. Corrective action will be initiated by bringing the discrepancy to the attention of the appropriate personnel. Corrections will be accomplished at the time of the disclosure under supervision of the SPM. Any discrepancies of health and safety protocol, such as the use of ineffective personal protective equipment, entering the support zone from the CRZ without frisking, or failure to calibrate a PID instrument prior to use, will also be considered short-term measures. Work will be suspended until corrective action is effected under the supervision of the SHSO.

13.2 OCCURRENCE REPORTING

Department of Energy (DOE) Order 5000.3A, Occurrence Reporting and Processing of Operations Information, became effective on August 30, 1990. The occurrence reporting system (ORS) may be initiated any time an employee, contractor, or subcontractor reports problems, concerns, conditions, or events that could adversely affect safety, the environment, health, quality, security, or operation. The occurrence is to be reported to the LSS (see Sect. 2.16, Emergency Contacts). If the event involves a real-time occurrence that requires assistance from plant emergency services, site investigation personnel should first take action to mitigate the occurrence (see Table 1). ORNL/MAD personnel will also be required to follow the ORNL occurrence reporting procedures and to notify the HASRD line manager, Dick Swaja, at 576-5212.

13.3 FIELD CHANGES/VARIANCES

Any deviation from the work plan or change in analytical procedure must be reported and recorded in a specified section of the field logbook for field changes/variances, when it occurs. A Field Change/Variance Form (Fig. 8) will be completed and signed by the appropriate parties in the event of any deviation from the document. A variance is a routine change in any aspect of the written procedure that would not affect the quality of data or analytical results. A field change is a deviation that could adversely affect the quality of data being generated. If a variance from the plan occurs, the box marked "Variance" is checked on the Field Change/Variance Form and the SPM is required to sign the form. A copy of the form is distributed to the QA representative and the original is maintained by the SPM. All personnel involved in the work process will be informed of these changes. For major alterations or field changes, the "Field Change" box on the form is checked and the additional

FIELD CHANGE REQUEST / VARIANCE FORM

☐ Field Change

Change Number: _____

☐ Variance

Date: _____

Project: _____

Site: _____

Document: _____

Substituted Method: _____

Impact on Data Quality: _____

Justification: _____

Site Project Manager: _____ Date: _____

Approvals: (Field Changes Only)

Project Manager: _____ Date: _____

QA Specialist: _____ Date: _____

QA Representative: _____ Date: _____

Analytical Representative: _____ Date: _____

Other Approvals:

Name / Organization _____ Date: _____

_____ Date: _____

_____ Date: _____

_____ Date: _____

required signatures at the bottom of the form are acquired. Changes must be explained to everyone on the investigative team. Each signee will receive a copy of the Field Change/Variance Form which records the deviation, the substituted method or rationale for the change, and an explanation of how data quality will be affected.

14. QUALITY ASSURANCE REPORTS TO MANAGEMENT

The SPM and SHSO will refer to this document if any questions arise during the tank removal process. Any deviations, deletions or additions to any phase of this project will be documented in the field logbook. Results from analyses performed by the Analytical Chemistry Department will be forwarded to the UST Engineering Assistant. Copies of any QA surveillances or audits will be forwarded to the ORNL/MAD QAO for his records. The ORNL/MAD QAO will compile any findings or discrepancies and forward copies to the SPM and the ORNL/MAD group leader. The SPM will address any outstanding discrepancies and deliver any evidence that deficiencies have been corrected to the QAO and the ORNL/MAD group leader. If any outside audits or surveillances reveal discrepancies, the SPM will address those comments as well and supply all appropriate personnel with a summary of the corrections. All correspondence should be addressed to Richard Mathis, Building 7503, MS 6382.

15. ORNL BUILDING 3019B 110-GAL UST HEALTH AND SAFETY SECTION

The work plan calls for the removal of the 110-gal UST for leaded gasoline storage. The proposed removal activities will be conducted by Martin Marietta Energy Systems, Inc. (MMES) personnel according to the guidelines/requirements in this work plan.

The 110-gal UST was placed into service approximately 25 years ago to provide fuel for a small generator located within Building 3019B. The tank was taken out of commission on June 1, 1991. The tank was drained and subsurface soil samples were taken to determine whether or not spillage or leakage had occurred that would require additional remediation. Under direction of the ORNL Underground Storage Tank Program, the tank was filled with sand (an inert material) and closed in place. Results from the soil sampling revealed that there had been some release of petroleum products into the environment from the tank. The State of Tennessee has recommended tank removal from the site, removal of all contaminated soil, and "clean" closure. As much sand as possible will be removed from inside the tank and the tank will be extracted. Because there is a remote possibility of explosion or ignition of vapors trapped within the rusting metal, extreme caution should be used at all times. If possible, the internal atmosphere of the tank will be monitored for ignitability prior to any remediation activities. The Fire Department will be notified of monitoring results and will be involved if vapor-freeing of the tank is required. Spark-resistant or grounded tools are to be used when applicable. All electrical lines will be grounded to avoid the generation of static electricity.

15.1 SITE ACTION PLAN

15.1.1 Site Preparation

A pre-entry health and safety briefing will be conducted before any further excavation can begin. All persons involved in the tank removal project (i.e., representatives from the ORNL plant, such as IH, HP, subcontractors, Safety, Security, Engineering, P&E and Radiochemical Technology Section) will be required to attend this pre-entry briefing. Other individuals may need site access after excavation begins; at that time the SHSO will explain the tank removal procedures and safety requirements in a separate health and safety briefing. All personnel who are involved in the tank removal process or might require access to the CRZ and beyond must provide copies of their training certificates to the SHSO at the time of the pre-entry briefing.

Before the site work plan is implemented, the site will be thoroughly checked and monitored for any possible ignition sources. In addition, "No Smoking" signs and other warnings will be posted in plain view. The top portion of the tank will be cut with spark-resistant tools and removed. All the sand will be removed from the tank, drummed, tagged, and removed from the site for disposal. The area beneath the tank will be sampled again for petroleum by-product contamination as specified in the separate ORNL UST Program

Sampling Plan.

The SHSO will be alert to any potential health and safety factors that might influence the project. Emergency procedures will be addressed during the health and safety pre-entry briefing, as will any questions pertaining to health and safety aspects of the tank removal project. On completion of the health and safety briefing, all personnel attending the meeting will sign the corresponding logbook to document attendance and to indicate their understanding of all aspects of the tank removal project. All involved individuals will be provided a copy of this health and safety plan for further reference.

Unusual site features and requirements of the ORNL Building 3019B UST removal project necessitate the following considerations:

- The OSHA final rule of March 6, 1989, in Sect. (e)(3)(i) of 29 CFR 1910.120 (OSHA 1989) requires that all workers on the site in a full-time capacity receive a minimum of 24 h of off-site health and safety training, in addition to a minimum of 3 d (24 h) of actual field experience under direct supervision, which is required for completion of the planned work effort.
- All individuals that will require access to the CRZ and/or EZ must have completed Radiation Worker Training and are required to provide a copy of the training certificate to the SHSO.
- Anyone requiring access to the CRZ or EZ who did not receive the pre-entry health and safety briefing at the beginning of the project will receive a separate briefing and a copy of the work plan when access is required. All personnel working on the site must have attended the pre-entry health and safety briefing, and documentation of the training must be entered in the field logbook before site access to the CRZ or EZ will be granted. All personnel will also be in the existing MMES radiological dosimetry program, and dosimeter badges assigned under that program will be required during this project.
- Those individuals with tasks involving access to the CRZ or EZ may be required to be on a medical monitoring program for hazardous work, as specified in 29 CFR 1910.120 (OSHA 1989). ORNL IH and the HAZWOPER Coordinator will be notified of the names of individuals that may require enrollment in the program. If site conditions warrant an upgrade in personal protective equipment and 40-hour training is therefore required for hazardous waste workers, the HAZWOPER Coordinator, in conjunction with ORNL Health Division, will determine which personnel will be required to participate in the hazardous waste worker medical surveillance program administered through the ORNL Health Division.
- If confined space entry is required, a certified competent person for excavation, trenching, and shoring must be on-site. Also, those individuals entering, serving as attendants in, monitoring, or supervising the confined space must complete the

Table 4. Building 3019B 110-gal UST site contaminants

Contaminant and suspected location ^a	TLV/PEL/activity or DAC ^b	STEL/IDLH ^c	Target organs/miscellaneous information ^d	Chemical and physical properties ^e
Alconox (from equipment decontamination)	TLV: 10 mg/m ³ (dust)	NA	Inhalation of powder may cause local irritation to mucous membranes	White powder, odorless, nonflammable
Gasoline (regular, leaded)	PEL: 300 ppm TLV: 300 ppm REL: NE	STEL: 500 ppm STEL: 500 ppm	Respiratory system, CNS, heart, blood, skin and eye irritant	Amber liquid with odor of gasoline, BP: 90°-437°F, FLP: -45.56°C, LFL: 1.4%, UFL: 7.6%
Isopropyl alcohol (from equipment decontamination)	PEL: 400 ppm TLV: 400 ppm REL: 400 ppm	STEL: 500 ppm STEL: 500 ppm IDLH: 12,000 ppm	Eyes, skin, respiratory system	Colorless liquid with odor like rubbing alcohol, BP: 181°F, FLP: 53°F, IP: 10.10 eV, FP: -127°F, UEL: 12.7% at 200°F, LEL: 2.0% at 200°F

^aThe potential contaminants were obtained from one or more of the following sources: groundwater data, historical data, soil data, surface water data, and storm drain data.

^bTLV — Threshold limit value, PEL — Permissible exposure limit, DAC — Derived air concentration, TWA — Time-weighted average, NE — Not established, NIOSH — National Institute for Occupational Safety and Health, OSHA — Occupational Safety and Health Administration, NA — Not available, REL — recommended exposure limit.

^cSTEL — Short-term exposure limit, NIOSH — National Institute for Occupational Safety and Health, IDLH — Immediately dangerous to life and health, NE — Not established.

^dCNS — Central nervous system, CVS — Central vascular system, GI — Gastrointestinal tract.

^eLEL — Lower explosive limit, LFL — Lower flammability limit, UFL — Upper flammability limit, FLP — Flash point, NA — Not available, SG — Specific gravity, Sol — Solubility, VP — Vapor pressure, UEL — Upper explosive limit, IP — Ionization potential, FP — Freezing point.

appropriate confined space entry training, and are required to provide the SHSO with the appropriate MMES-approved certification.

15.1.2 Suspected Contaminants

Table 4 lists possible site contaminants and associated hazards with which personnel should be familiar, in addition to physical descriptions and pertinent chemical characteristics. Chemicals are listed based on information from historic site data and conversations with individuals familiar with the operations carried out within the building and surrounding area. Chemicals used in the site decontamination activities also appear on the list.

15.1.3 Tank Removal

The tank's surface was exposed to determine the boundaries of the tank in relationship to existing barriers. At the surface the tank appears to be rusted from age, but it seems to be intact and without any visual defects that might hinder its removal. One of the major problems identified on the initial site visit was site accessibility. The tank is located along and next to the northern wall of Building 3019B. A large support pylon set in concrete is located on two sides of the pit area. Each pylon supports overhead ventilation ducts emanating from Building 3019B. The presence of these pylons and duct work could interfere with the removal process by limiting access of removal equipment at the site. In addition to physically avoiding the pylons, care must be taken to avoid undercutting earth from beneath the pylons. Because of restricted access caused by the wall, the two pylons, and the overhead obstructions, this area might be designated as a confined space by the ORNL IH Department. An IH representative trained specifically in confined space entry will be notified if an entry into the pit is required.

The tank was filled with sand, all lines and vents were capped and sealed at the tank, and lines into the building were removed. In the event that the tank cannot be removed in its entirety, the following actions will be taken: the top surface of the tank will be cut away to gain access to the prefilled sand contained inside the tank, and the sand will be shoveled from the tank or removed by another method decided upon at the site. Nonsparking tools will be utilized to cut away a large section from the top of the tank. The internal atmosphere of the tank will be monitored to ensure that no vapors are present. In the event that a combustible atmosphere is detected, readings will be conveyed to the ORNL Fire Department in order to determine actions to be taken to ensure the safe removal of the tank. This can be accomplished by inerting or purging, as described below. If levels for combustibles are not encountered, the section will be removed and the sand will be shoveled from the tank into 55-gal (17-C) drums for disposal. After the sand has been removed, the emptied tank can then be extracted from the pit. The best method of removal will be determined. Once the tank has been removed from the pit, samples will be taken to determine the degree and extent of contamination present.

The ORNL UST Program Manager will be responsible for preparing site closure documents for submittal to the Tennessee Department of Environment and Conservation.

15.1.3.1 Inerting

The process of inerting displaces the oxygen in the tank using an inert or non-reactive gas. This process reduces the flammable potential by impacting the oxygen point of the fire triangle. Inerting a tank reduces the level of oxygen in the tank below 12-14% by volume, which is required by most petroleum products for combustion.

Oxygen content in the tank can be reduced by adding solid carbon dioxide (dry ice) at a ratio of 1.5 lbs of dry ice per 100 gal of tank capacity. The dry ice should be crushed and distributed as evenly as possible over the bottom of the tank to promote rapid evaporation. As the solid carbon dioxide vaporizes, the oxygen in the tank will be reduced, and at that point all work around the excavation site will cease until the vaporization process is completed. Dry ice may cause severe burns and should be handled with insulated gloves.

A secondary (backup) inerting method is the introduction of inert gases such as carbon dioxide (CO_2) or nitrogen (N_2). The inert gas should be introduced through a single tank opening via a standpipe at a point near the bottom and end of the tank opposite the vent. Inert gases should be introduced under low pressure to avoid the generation of static electricity, and the pressure in the tank should not exceed 5 psi. The tank will be tested using a CGI with a detector (LEL/ O_2) to determine if all the vapors have been purged. These processes also affect the oxygen point of the fire triangle.

15.1.3.2 Purging

Purging a tank replaces or dilutes the flammable vapors in the tank with air. This reduces the flammable mixture of fuel and oxygen by affecting the fuel part of the fire triangle. Most petroleum products have a flammable range of 1-10% by volume in air. The goal of purging is to reduce the flammable vapors below the LEL of unleaded gasoline.

If inerting the tank is not feasible, the next step will be purging the tank. After the tank has been emptied, the concentration of flammable vapors can be reduced or eliminated by using a diffused-air blower to purge the tank. Air can be pumped into the tank through the fillpipe. The air must be introduced as deeply into the tank as possible to ensure that vapors are mixed sufficiently to be removed from the tank. The blower and pipe must be properly bonded to prevent static buildup. To avoid rupturing the tank, air pressure in the tank must not exceed 5 psi. The size of the vent opening and the rate at which the air is introduced into the tank must be taken into consideration.

As a backup method of purging, an enducter type of air mover may be utilized. Driven by compressed air, the enducter draws flammable vapors out of the tank and fresh air into the tank. The fill tube should remain in place to ensure ventilation of the tank bottom. The enducter shall be properly bonded to prevent the generation of static electricity. As a safety precaution exhaust vapors from the vapor-freeing process should be vented at a minimum of 12 feet above-grade and 3 feet above any adjacent roof lines. The atmosphere at ground level shall be checked periodically while the vapor-freeing process is in progress to ensure vapors are being vented efficiently and are not accumulating at ground level.

Vapor-freeing processes of the type described here are temporary. Substances trapped in sludge at the bottom of the tank may generate flammable vapors inside the tank; therefore, the LEL should be tested frequently inside the tank, the excavated area and any below-grade areas, as well as at ground level and especially near the vent. Readings inside the tank should be taken at the bottom, the middle and the top of the tank during each measurement activity.

15.1.4 Waste Management

The soil from the tank excavation might be drummed, labeled and transported for disposal. The Facility Manager will be responsible for disposition of the displaced soil and any other generated waste. The sand that was used for temporary closure could also be drummed and taken to a site for drum disposal. A sample of the sand inside the drum will be submitted for analysis to determine the proper disposal method for the drum. Specific procedures are explained in Sect. 15. Any compactible waste that is generated due to work at this site will be drummed in a specified 55-gal container and disposed of as compactible waste. The excavation pit will be refilled with crushed stone or whatever material is determined suitable by the ORNL UST Engineering Assistant. After closure, all barricading, flagging, and placarding will be removed to allow resumption of normal daily operations at the Building 3019B site.

All decontamination fluids and compactible waste will be drummed in appropriate waste receptacles (17-E and 17-C) and properly labeled as specified by the ORNL Waste Disposal Coordinator. The decontamination fluids will be drummed as flammable and nonflammable fluids. All drums will be stored on pallets and in an uncongested area to avoid interference with the normal daily work routine.

15.2 PERSONNEL PROTECTION

15.2.1 Personal Protective Equipment

Selection of all personal protective equipment for the different site activities, tasks, and work zones is based on the potential site-specific contaminants and may involve conservative additions to personnel protection by ORNL/MAD, ORNL IH, or ORNL HP. Selection of all personal protective equipment for the EZ is based on OSHA requirements and conservative additions to personnel protection by ORNL/MAD. Work during this project will be conducted using Level D protective equipment unless the SPM or the SHSO decide otherwise. Guidelines for personal protective equipment for site activities, tasks, and work zones are to be specified by the SHSO using Table 5 and the following list:

1. Level C Protective Equipment

- a. Full-faced, air-purifying cartridge respirator, capable of filtering out organic vapors and radionuclides
- b. Hooded chemical-resistant clothing (Tyvek®) (all seams and openings taped)
- c. Gloves (chemical-resistant inside and outside)
- d. Safety-toed footwear

- e. Hardhats
- f. Hearing protection (where heavy machinery is in use)

2. Level D+ Protective Equipment

- a. Chemical-resistant (polyethylene-lined) Tyvek® clothing
- b. Chemical-resistant disposable gloves (one pair)
- c. Safety-toed footwear
- d. Hardhats
- e. Safety glasses
- f. Gloves
- g. Hearing protection (where heavy machinery is in use)

3. Level D Protective Equipment

- a. Coveralls/field clothes
- b. Safety-toed footwear
- c. Safety glasses
- d. Hard hats
- e. Gloves
- f. Hearing protection (where heavy machinery is in use)

The outer protective garment will be of a chemical-resistant woven material (Tyvek® or equivalent). This material has the ability to form a protective barrier against detrimental chemicals for a specific period of time based on the chemical in question. **Each chemical has its own permeating ability, and the resistance of the protective clothing will vary with each chemical.** For some chemicals, the risk of chemical permeation increases when an outer protective garment becomes damp from soil or water contact. If at any time the outer protective suit becomes wet, the wet garment should be replaced as soon as possible with a clean, dry Tyvek® suit.

All respiratory equipment will be approved by the National Institute for Occupational Safety and Health and the Mine Safety and Health Administration. All personnel required to use respiratory protection shall have had an up-to-date quantitative respirator fit test and will wear only those respirators approved by the quantitative fit test. In addition, site personnel will follow a single-use respirator policy. Once the seal of the respirator has been broken (i.e., for lunch and other breaks), a new respirator will be donned in place of the previous respirator.

15.2.1.1 Protective clothing donning procedure

The purpose of the protective clothing donning procedure is to ensure that on-site personnel are instructed in the proper donning of protective clothing. Failure to adhere to this procedure may result in the protective clothing being ineffective against a potential contaminant. The following donning procedure is given as a guide and may be altered by the SHSO if procedural improvements can be made and are warranted in the field. In addition, some articles of protective clothing/equipment detailed below may not be necessary for the

particular site task. Personnel should consult the SHSO to determine what combination of protective equipment is appropriate.

1. Inspect clothing and respiratory equipment before donning.
2. Adjust hard hat to fit.
3. Place legs in suit while standing or sitting and pull safety boots through. Gather up at the waist and place arms in sleeves. Pull upper portion of the suit over the shoulders and zip the suit closed.
4. Place boot covers over the safety boots if required. Tuck pants legs into shoe covers and tape the boot covers to the legs of the suit, providing a seal, and tab the tape to permit ease of removal.
5. Don the respirator after performing the initial qualitative checks of the respirator's integrity.
6. Perform the necessary qualitative respirator fit test under the direct supervision of the SHSO.

Table 5. Protective equipment for on-site activities

Activity	Level	Protective equipment ^a
Excavating and environmental sampling, equipment decontamination ^b	D	Hard hat, safety glasses, hard-toed footwear, field work clothes, face shield ^b , gloves, hearing protection if required
Excavating and environmental sampling	D+	Same as above plus chemical-resistant polyethylene-lined Tyvek [®] clothing, chemical-resistant disposable gloves, nitrile or butyl rubber outer boots
Excavating and environmental sampling at action levels	C	Same as above with the exception of safety glasses plus full-faced respirator with organic vapor/high-efficiency dust and mist cartridge

^aChemical-resistant gloves, outer boots, and Tyvek[®] clothing may be worn by personnel to reduce the danger of potential splashing and to maintain personal hygiene. The information in this table should not be construed to mean that all personnel are required to conform to this practice. All site personnel and visitors must contact the SPM or SHSO to confirm actual personnel protection requirements prior to entering an investigation site.

^bFull-faced face shields mounted on hard hats with safety glasses will be worn during the equipment decontamination process.

7. Draw hood up around the respirator. Have someone seal exposed facial areas between the suit and the respirator with tape.
8. Don both pairs of chemical-resistant gloves; insert sleeve of work clothes inside inner glove and seal with tape. Then insert sleeve of suit inside outer glove and likewise seal with tape. Tab the tape to permit ease of removal of gloves during decontamination procedures.

15.2.1.2 Protective clothing doffing procedure

The purpose of the protective clothing doffing procedure is to ensure that all on-site personnel are instructed in the removal of protective equipment. Failure to adhere to this procedure may result in unnecessary exposure to a potential on-site contaminant. The following doffing procedure is given as a guide and may be altered by the SHSO or the on-site HP if procedural improvements can be made and are warranted in the field. In addition, some protective equipment/clothing listed below may not be required for a specific site task. Personnel should consult the SHSO, who has conferred with the ORNL HP representative, to determine what combination of protective equipment is appropriate.

1. Remove tape from outer rubber gloves.
2. Remove outer gloves.
3. Remove tape from hood and respirator.
4. Remove hood back and away from face and head.
5. Remove tape from outer shoe covers.
6. Remove or cut tape from front seam of suit.
7. Remove suit back and away from body.
8. Slide pants down to ankles or roll them inside out.
9. Cut pants off at ankles or roll pants inside out.
10. Dispose of suit in proper receptacle.
11. Remove tape from inner gloves.
12. Remove outer shoe cover.
13. Remove respiratory equipment
14. Remove inner gloves by rolling them inside out.

Personnel should familiarize themselves with this guidance and with the personnel decontamination procedures because these should be carried out in conjunction.

15.2.2 Respiratory Protection

Personnel at the Building 3019B UST site will be covered by a respiratory protection program that meets the legal requirements of 29 CFR 1910.134 or American National Standards Institute (ANSI) Z88.2, whichever is more stringent, by incorporating the following conditions:

- Program administrator.
- SOP for selecting and using respirators, based on the ORNL Respiratory Protection Program Manual, IHP-06.
- Proper selection of respirators on the basis of hazard.
- Training of personnel in respirator use and limitations.
- Regular cleaning and maintenance.
- Proper storage.
- Routine monthly inspections and inspections before and after use.
- Constant monitoring of work area for adverse conditions and worker stress.
- Continual evaluation of respiratory compliance program once in operation.
- Determination of medical fitness of potential user.
- Use of approved equipment only after proper fit testing has been performed. The fit test should be used to determine the user's ability to obtain a satisfactory fit with a negative pressure, air-purifying respirator. The results of the fit test will be used to select the specific type, make, size, and model of negative pressure, air-purifying respirator for use by the wearer.

The following policies should also be adhered to in the fitting and use of respirators:

1. An employee must have passed the quantitative fit test and medical evaluation to use a respirator.
2. If it is determined that an employee cannot obtain a good respirator-to-face seal because of facial or medical characteristics, that employee will neither use a respirator nor enter an atmosphere that requires the use of a respirator.
3. Facial hair such as beards, sideburns, and certain mustaches that may interfere with the fit test are not allowed.
4. Individuals requiring corrective lenses shall be provided with specially mounted lenses inside the full-faced mask. Under no circumstances will contact lenses or normal glasses be worn while using respirators.
5. Although fit testing for positive-pressure, self-contained breathing apparatuses is not required, a less than acceptable respirator-to-face seal will increase the use of air via leakage and therefore reduce effective breathing time. Such leaks may pose a hazard to the user if sufficient air is not available in the system to allow the wearer to reach an uncontaminated air supply.
6. Individuals may use only the specific make(s) and model(s) of air-purifying respirators for which they have obtained a satisfactory fit via the quantitative fit-testing procedures. Under no circumstances shall individuals be allowed to use any make or model of respirator for which they have not passed a fit test.

The determination of the potential user's medical fitness is generally based on evaluating the individual for physiological-psychological limitations as given in American National Standards Institute Standard Z88.6 (1984). Examples are

- pulmonary problems;
- cardiovascular problems;
- skin sensitivity, diabetes, perforated eardrum, deviated septum; and
- claustrophobia, anxiety, and discomfort.

15.2.3 Personnel Decontamination Procedures

Personnel decontamination procedures are designed to eliminate or limit the contaminated materials workers may encounter and to limit the spread of contaminated materials from the exclusion and contamination reduction zones. Decontamination procedures for levels of protective equipment C, D+, and D, which are quite similar, are described in this section.

The SHSO is responsible for the establishment of the exclusion, contamination reduction, and support zones (see Sect. 15.3.2); the construction of a site decontamination station; and the instruction of personnel on its proper use. Figures 9, 10, and 11 depict minimum requirements for decontamination stations.

The following procedures have been provided as guides for personnel decontamination. Actual procedures depend on site conditions and may be modified by the SHSO if improvements are needed. These guides are worst-case scenarios; therefore, personnel shall check with the SHSO to determine the site requirements (see also Sect. 15.2.1.2 for protective clothing doffing procedures).

15.2.3.1 Segregated Equipment Drop and Canister or Cartridge Change

Station 1: Work area.

This is the area of greatest potential for exposure to site contaminants.

Station 2a: Segregated equipment drop.

Deposit equipment used on site (tools, sampling devices, containers, monitoring equipment, clipboards, etc.) on a plastic drop cloth or in a container with a plastic liner. Either return immediately to the exclusion zone or proceed to station 2 of the decontamination process described below.

Equipment necessary: containers
plastic liners
55-gal compactible waste drum

Station 2b: Canister or cartridge change.

When the respirator canister or cartridge has been replaced, put the used canister or cartridge in a plastic bag for disposal.

Fig. 9. Segregated equipment drop and canister or cartridge change.

Fig. 10. Minimum decontamination requirements for Level D+ protection.

Fig. 11. Minimum decontamination requirements for Level C protection.

Equipment necessary: respirator cartridges or canisters
plastic trash bags

15.2.3.2 Level D Protection Decontamination

Station 1: Work area.

This is the area of greatest potential for exposure to site contaminants.

Station 2: Scrubbing and rinsing tools and agents for outer garment, boots, gloves, hard hats, safety glasses.

Scrub outer boots and gloves with a laboratory-grade detergent (Liquinox or equivalent) and rinse with potable water. Disposable boots and gloves need not be scrubbed and may be disposed of in compactible waste drums. Clean safety glasses and hard hat in same fashion. If boots must be decontaminated, all decontamination should take place while personnel are standing in large wash tubs so that decontamination solutions can be caught and drummed in accordance with this plan.

Equipment necessary: two or three washtubs
one hand-pump sprayer
water
detergent
scrub brushes
paper towels
55-gal drum with liner for paper towels
and protective clothing

Station 3: Outer garment, boot, glove, safety glasses, and hard hat removal.

Remove boots, gloves, safety glasses, and hard hats.

Station 4: Inner glove removal.

Remove inner gloves.

Station 5: Frisking.

To ensure that no radiological contamination is transferred to the support zone, personnel shall be frisked (screened for radiological contamination) by a member of the ORNL Radiation Protection department or by a member of the ORNL/MAD group after approval from the ORNL Radiation Protection department prior to leaving the contamination reduction zone for the support zone. Frisking will be performed according to standard operating procedures developed by the ORNL/MAD group or those of ORNL Radiation Protection if they perform the task.

Equipment necessary: alpha detector
beta-gamma detector

If contamination is detected, proceed to station 6, then return to station 5 and repeat the frisking procedure. If contamination is still detected after repeating station 5, the Laboratory Shift Superintendent must be notified immediately to take the worker to the health division.

Station 6: Field wash.

Thoroughly wash hands and face with soap and water and a soft-bristle brush, if necessary. Shower as soon as possible.

Equipment necessary: water
wash basin or bucket
soap

If contamination was detected at station 5, return there now and repeat the frisking procedure. If no contamination was detected, proceed to station 7.

Station 7: Step across line.

Enter the designated support zone.

15.2.3.3 Level D+ Protection Decontamination

Follow the steps for Level D decontamination; the only difference occurs at station 3. Remove the disposable chemical protective coverall and deposit it in a lined 55-gal compactible waste drum. Level D+ protective clothing is deemed necessary when sampling operations may produce excessive splashing of surface or subsurface materials, yet the action level does not require the use of a respirator and taped, protective chemical-resistant suits.

15.2.3.4 Level C Protection Decontamination

Station 1: Work area.

This is the area of greatest potential for exposure to site contaminants.

Station 2: Scrubbing and rinsing of outer garment, boots, and gloves.

Scrub outer garment, boots, and gloves with laboratory-grade detergent and water and rinse with potable water. All wash water and rinsing solutions will be disposed of in accordance with this plan. NOTE: This station is not necessary when disposable personal protective equipment is used.

Equipment necessary: washtubs
water
detergent
scrub brushes

Station 3: Outer garment, boots, and gloves removal.

Remove outer garment, boots, and outer gloves with accompanying tape. Tape and disposable gloves should be placed in a plastic trash bag and disposed of in accordance with procedures outlined in this document. Reusable outer garments and boots will be placed in plastic bags for screening by ORNL Radiation Protection. This equipment must be scanned and green-tagged before it may be reused. NOTE: This station is not necessary when disposable personal protective equipment is used.

Equipment necessary: plastic trash bags
bench or stool

Station 4: Respiratory protection and disposable inner glove removal.

The respirator is the next-to-last item for removal. Cartridges or canisters are placed in a plastic trash bag and disposed of in accordance with procedures contained within this plan. The respirator is placed in a plastic bag dedicated for used respirators. Due to the single-use respirator policy, respirators may not be reused until they have been scanned and tagged by ORNL Radiation Protection and returned to ORNL Industrial Hygiene. Finally, remove disposable inner gloves and deposit them in a plastic trash bag.

Equipment necessary: plastic trash bags

Station 5: Frisking.

To ensure that no radiological contamination is transferred to the support zone, personnel shall be frisked (screened for radiological contamination) by a member of the ORNL Radiation Protection department or by a member of the ORNL/MAD group after approval from the ORNL Radiation Protection department prior to leaving the contamination reduction zone for the support zone.

Equipment necessary: alpha detector
beta-gamma detector

If contamination is detected, proceed to station 6, then return to station 5 and repeat the frisking procedure. If contamination is still detected after repeating station 5, the Laboratory Shift Superintendent must be notified immediately to take the worker to the health division.

Station 6: Field wash.

Wash hands and face thoroughly with soap and water and a soft-bristle brush, if necessary.

If contamination was detected at station 5, return there now and repeat the frisking procedure. If no contamination was detected, proceed to station 7.

Station 7: Step across line.

Enter the designated support zone.

15.3 SITE TASK HAZARD ANALYSES

15.3.1 Discussion

The site task hazard analysis is intended to identify potential health and safety hazards that site personnel may encounter. Necessary personal protective equipment will be identified by the SHSO, the SPM, the on-site HP Technician, or the on-site IH representative, and depending on field conditions, the equipment may be upgraded or downgraded as deemed appropriate. Personnel decontamination requirements, including donning and doffing procedures for various levels of protection, are outlined previously in this section.

Additional personnel may be required for physical removal of the tank when specific logistics have been determined. Heavy-equipment operators, riggers, or laborers may be needed for the task; if so, precautions listed in the following should be taken.

15.3.1.1 Heavy-equipment operators

Personnel operating heavy equipment will use Level D personal protective equipment, although changing field conditions may require an upgrade by the SHSO. Safety precautions must be observed when equipment is operated around the site. People working around construction equipment should be aware that operators have blind spots in their field of vision. Grounding cables will be attached to the piece of equipment, crane or backhoe to prevent generation of static electricity. Every piece of heavy equipment has unique hazards associated with its use. Operation of equipment around obstacles or obstructions of which the operator is unaware could cause harm to support personnel, operators, or equipment.

15.3.1.2 Riggers and laborers

Riggers and laborers will be responsible for clearing soil and sand from the Building 3019B tank and operating jackhammers, cutting tie-down rods, and connecting cables to hoist the UST from the ground if these actions are necessary. Any individuals who might be required to make a confined space entry must have the appropriate MMES-approved training. Extra attention should be paid to safety because of the possible presence of heavy equipment. Level D personal protective equipment will be utilized unless changing field conditions warrant an upgrade, which will be determined by the SHSO, the SPM, ORNL HP, and/or the IH representative.

15.3.2 Determination of Work Area

Work zones will be cordoned off with flags and appropriate signs will be placed to enhance recognition of each zone. The following sections will be used in the determination of work zones for the site.

15.3.2.1 Zone 1: exclusion zone

The EZ is the zone where the potential of coming into contact with contamination is greatest (see Fig. 12). All personnel entering the EZ will have the prescribed level of protective clothing and training and be placed on the medical monitoring program, as determined by the SHSO. An entry and exit checkpoint will be visually defined at the periphery of the EZ to regulate the flow of personnel and equipment into and out of the zone. Prohibited items or conduct in the EZ include the following:

- Beards and long sideburns (in the event respiratory protection would be required);
- Eating, drinking, smoking, or chewing anything;
- Personal articles (e.g., watches and rings);
- Failure to inform the SPM or SHSO of any illness that could affect safety or cause health-related complications;
- Removal of respiratory protective equipment under Level C or higher protection except when exiting the exclusion zone through the decontamination line set up in the contamination reduction corridor;
- Access to the EZ by any individual not having the required health and safety training or not placed on the medical monitoring program in accordance with OSHA regulations 29 CFR 1910.120(e)1 and (e)2;
- Any individual that does not possess the appropriate credentials to gain entrance to the site;
- Any conduct or item thought to be potentially dangerous to the well-being of the remediation personnel; and
- Application of insect spray or cosmetics (because interaction of these substances with other chemicals is possible).

15.3.2.2 Zone 2: contamination reduction zone

As shown in Fig. 12, the CRZ is established outside the EZ. This zone provides a transition between the EZ (potentially contaminated zone) and the support zone (clean zone). It serves as a buffer to further reduce the possibility of support zone contamination. It provides additional assurance that the physical transfer of contaminating substances to personnel, equipment, or the air is limited through a combination of decontamination, distance between EZ and support zones, air dilution, zone restrictions, and work functions. At the boundary between the EZ and CRZ, decontamination stations for the sole purpose of personnel decontamination will be established. Each person will be monitored by the on-site HP or a designated representative upon leaving the CRZ and before entering the support zone. Access requirements for personnel entering the CRZ are the same as those described for entrance to the EZ.

15.3.2.3 Zone 3: support zone

The support zone (clean zone) is shown in Fig. 12. The support zone will be marked with flagging and appropriate signs and protected against contamination from the work site. Primary functions of the Support Zone are

- entry area for personnel, material, and equipment;
- exit area for decontaminated personnel, materials, and equipment;
- staging area for clean safety and work equipment; and
- area for rest breaks, the consumption of food and beverage, and all other activities.

15.3.3 Standard Safe Work Practices

1. Eating, drinking, chewing gum or tobacco, smoking, and applying cosmetics are prohibited in the EZ and CRZ or wherever the possibility exists for the transfer of contamination.
2. Contact with potentially contaminated substances should be avoided. Do not walk through puddles, pools, mud, etc. Whenever possible, avoid kneeling, leaning, or sitting on equipment or the ground. Do not place monitoring equipment on a potentially contaminated surface (e.g., the ground).
3. Avoid spillage of contaminated material. In the unlikely event that this occurs, notify the SPM.
4. All field crew members should use their senses (all senses) to alert them to potentially harmful situations.
5. Practice good housekeeping. Keep everything orderly and avoid potentially harmful situations.
6. Field crew members must be familiar with the physical characteristics of investigations, including
 - wind direction in relation to ground zero;
 - accessibility to associates, equipment, and vehicles;
 - communications;
 - hot zones (areas of known or suspected contamination);
 - site access; and
 - nearest water sources.
7. The number of people and equipment in the EZ should be minimized in accordance with work space requirements for safe site operation.
8. All waste generated during the Building 3019B UST project will be disposed of in accordance with provisions of this plan.
9. Report all injuries to the SHSO, no matter how minor.
10. All workers in the contamination zone will maintain verbal contact with fellow workers; if site conditions make hearing difficult, workers will maintain visual contact.
11. All individuals will make their presence known to the SPM daily, and changes in

ORNL-DWG 91-15923

Fig. 12. Diagram of site work zones showing EZ, CRZ, and support zone.

personnel will be noted. A list of workers on the job site will be maintained in the field logbook for accountability.

15.3.4 Special Hazards

In addition to the physical, chemical, and radiological hazards, other types of hazards could be present on this site. All site remediation personnel may potentially be exposed to the hazards outlined in the following.

15.3.4.1 Heat stress

Activities being conducted at the Building 3019B 110-gal UST may be physically demanding during much of the excavation efforts, possibly compounded through the use of protective clothing and equipment, moderate to heavy work loads, ambient air temperatures, relative humidity, and exposure to nonionizing radiation.

Two important factors will help personnel function in hot environments: acclimatization and consumption of fluids. Acclimatization is a physical and psychological adjustment that workers experience during the first 1 or 2 weeks of work in hot environmental conditions. Especially during this period, workers should concentrate on maintaining a balanced diet, consuming plenty of fluids throughout the day, and remaining aware of telltale signs of heat-related stress, such as headaches, dizziness, high body temperature, and increased heart rate. It is imperative that the SHSO be informed if a worker experiences such symptoms.

All activities that take place at the investigative site require the use of a "buddy" system. Observation of workers for visible signs of heat stress and fatigue will be employed as a method of monitoring workers for symptoms of heat stress. In addition, workers will monitor themselves and their work partners and report any symptoms of heat-related stress to the SHSO. The SHSO will institute a work/rest regimen to combat heat-related disorders, according to his/her best professional judgement and guidelines published by the American Conference of Governmental Industrial Hygienists (ACGIH 1990).

15.3.4.2 Cold stress

Activities could be beginning and proceeding throughout months with unpredictable weather patterns. Because variable weather conditions may be encountered, cold-related hazards will be addressed.

Two important factors will help personnel function in cold environments: acclimatization and proper clothing. Acclimatization is a physical and psychological adjustment that workers experience during the first 1 or 2 weeks of work in cold environmental conditions. Especially during this period, workers should concentrate on maintaining a balanced diet, consuming plenty of fluids throughout the day, and remaining aware of telltale signs of cold-related stress, such as headaches, numbness in digits or extremities, dizziness, low body temperature, and decreased heart rate. It is imperative that the SHSO be informed if a worker experiences these symptoms.

All activities that take place at the investigative site require the use of a "buddy" system. As field activities continue, a worker should be aware of his/her partner's condition and of signs of cold-related stress. The SHSO will institute a work/rest regimen to combat cold-related disorders, according to his/her best professional judgement and guidelines published by the ACGIH (1990).

15.3.4.3 Biological stress

Field conditions may present a variety of biological stressors, and it is the responsibility of remediation personnel to inform the SHSO of health conditions that may be affected by on-site biological stressors. Such stressors include bee stings, ticks, poison ivy, snakes, and certain pollens and grasses that might influence asthmatic conditions.

15.3.4.4 Illumination

Field activities at the Building 3019B site will be conducted during daylight hours under normal operating conditions. A minimum of 5 ft-c will be required to conduct field activities. A foot-candle is a unit of length of illumination; thus, 5 ft-c equals 5 ft. Actual field measurements of illumination will not be collected. A conservative guideline may be that field work will commence 15 min after sunrise and conclude 15 min prior to sunset. Adherence to the minimum 5 ft-c requirement will be based on the SHSO's best professional judgement.

15.3.4.5 Dust

Based on previous experience, the generation of dust will be minimal. A general rule of thumb is that a visible cloud of dust will constitute an action limit. An engineering control may be employed to control dust, such as wetting the area with deionized water, sprayed as a fine mist from a garden sprayer, but not to the extent of creating mud. In the unlikely event that engineering controls are unsuccessful, ORNL IH will be summoned to assess the situation and to provide guidance.

15.3.4.6 Ergonomics

Potential hazards related to the interaction of personnel with their working environment may be present at this site. Primary ergonomic hazards may be lifting heavy loads, equipment vibrations, body positioning, and physical obstacles associated with traversing ditches and brush. Personnel should always position themselves properly, lift from the legs when attempting to lift equipment, and rely on a "buddy" to assist in lifting loads that are too heavy for one person. Back strain, the most common ergonomic hazard in the field, may be easily avoided, provided that on-site workers ask for assistance when needed.

15.3.4.7 Location hazards

Location hazards may include, but are not limited to, movement of equipment around the site, mechanical equipment malfunctions, nonestablished roads, and potential noise hazards. The Engineering Department and a representative from the Safety Department will be

notified to determine the voltage of any overhead lines, and, if necessary, shut off power through those lines when necessary. Personal hazards, such as tripping or falling, can also have an adverse effect on the health and safety of personnel.

If there are overhead electrical transmission lines with which machinery could interfere or come into contact, special precautions must be taken. The SPM or his designee shall verify that equipment will not be operated when any part of a mast or boom enters within a minimal radial distance of 10 ft from electrical transmission lines or as specified in Table 6. All personnel shall stay clear of overhead work and temporarily suspended or moving equipment.

**Table 6. Safe working distances
from electrical transmission lines for masted
or boomed machinery**

Normal voltage (phase-to-phase) (kV)	Minimum clearance required (ft)
<i>When operating near high voltage power lines</i>	
0 to 50	10
50 to 200	17
200 to 350	22
350 to 500	27
500 to 750	35
750 to 1000	44
<i>While in transit with mast lowered</i>	
All voltages	10

Source: Crawler locomotive and truck cranes
[29 CFR 1910.180j(1)].

16. REFERENCES

American Conference of Governmental Industrial Hygienists, *Threshold Limit Values and Biological Exposure Indices for 1990-91*, 1990.

Environmental Protection Agency (EPA), *Guidance for Conducting Remedial Investigations and Feasibility Studies Under CERCLA*, EPA/540/G-89/004 (OSWER Directive 9355.3-01), Office of Emergency and Remedial Response, Environmental Protection Agency, Washington, DC, October 1988.

Environmental Protection Agency (EPA), *Data Quality Objectives for Remedial Response Activities, Development Process*, EPA/540/G-87/003 (OSWER Directive 9355.0-7B), Office of Emergency and Remedial Response and Office of Waste Programs Enforcement, Environmental Protection Agency, Washington, D.C., March 1987.

Environmental Protection Agency (EPA), *Interim Guidelines and Specifications for Preparing Quality Assurance Project Plans*, QAMS-005/80, EPA-600/4-83-004, NTIS PB-83-170514, Office of Monitoring Systems and Quality Assurance, Office of Research and Development, Environmental Protection Agency, Washington, DC, December 1980.

C. W. Kimbrough, L. W. Long, and L. W. McMahon, *Environmental Surveillance Procedures Quality Control Program*, Martin Marietta Energy Systems, Inc., ESH/Sub/87/21706/1, Rev. 1, Martin Marietta Energy Systems, Inc., Oak Ridge, Tennessee, January 1990.

Occupational Safety and Health Administration Standards for Hazardous Waste Operations and Emergency Response (29 CFR 1910.120), March 1989.

DISTRIBUTION

1. J. D. Baity	23. P. S. Rohwer
2. L. D. Bates	24. E. L. Ryan
3-5. K. J. Brown	25. A. W. Saulsbury
6-10. S. N. Burman	26. T. F. Scanlan
11. F. K. Edwards	27. C. S. Sims
12. T. L. Hatmaker	28. R. E. Swaja
13. S. V. Kaye	29. J. H. Swanks
14. F. C. Kornegay	30. M. S. Uziel
15. D. C. Landguth	31. S. E. Whittenbarger
16. P. L. Lund	32. J. K. Williams
17. R. A. Mathis	33-34. Laboratory Records
18. L. E. McNeese	35-40. MAD Records Center
19. C. E. Mulkey	41. Central Research Library
20. J. B. Murphy	42. ORNL Technical Library, Y-12
21. C. E. Nix	43. ORNL Patent Section
22. R. C. Orrin, Jr.	
-
- 44. Office of Assistant Manager for Energy Research and Development,
Department of Energy Field Office, Oak Ridge, P.O. Box 2001, Oak Ridge, TN
37831-8600
 - 45-46. R. C. Sleeman, Department of Energy Field Office, Oak Ridge, P.O. Box 2001,
Oak Ridge, TN 37831-8541
 - 47-48. J. T. Sweeney, DOE Field Office, Oak Ridge, P.O. Box 2001, Oak Ridge, TN
37831-8540
 - 49-50. Office of Scientific and Technical Information, P.O. Box 62, Oak Ridge, TN
37831

END

**DATE
FILMED**

4 / 7 / 93