NOTICE

**CERTAIN DATA
CONTAINED IN THIS
DOCUMENT MAY BE
DIFFICULT TO READ
IN MICROFICHE
PRODUCTS.**

WSRC-TR--92-42-003

DE92 019920

**ACTUATOR SYSTEM HISTORY OF SAFETY ROD LOWER
LATCH PROBLEMS REVIEW OF LATCH INSPECTION
VIDEO TAPES (U)**

by

J. J. Banks

Westinghouse Savannah River Company
Savannah River Site
Aiken, South Carolina 29808

Received by OSTI

AUG 20 1992

This report was prepared in connection with work done under Contract No. DE-AC09-89SR18035 with the U.S. Department of Energy. By acceptance of this report, the publisher and/or recipient acknowledges the U.S. Government's right to retain a nonexclusive, royalty-free license in and to any copyright covering this report, along with the right to reproduce and to authorize others to reproduce all or part of the copyrighted report.

MASTER

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

This report has been reproduced directly from the best available copy.

Available to DOE and DOE contractors from the Office of Scientific and Technical Information, P.O. Box 62, Oak Ridge, TN 37831; prices available from (615) 576-8401, FTS 626-8401.

Available to the public from the National Technical Information Service, U.S. Department of Commerce, 5285 Port Royal Rd., Springfield, VA 22161.

REACTOR ENGINEERING DEPARTMENT

WSRC-TR-92-42-003

REACTOR ENGINEERING DESIGN

KEYWORD

Technical
Reactor
K Area
Actuator
Safety Rod

**DOES NOT CONTAIN
UNCLASSIFIED CONTROLLED
NUCLEAR INFORMATION**

REVIEWING

OFFICIAL: *J. J. Banks*

RETENTION:

PERMANENT

DATE: 6/1/92

CLASSIFICATION:

UNCLASSIFIED

**ACTUATOR SYSTEM
HISTORY OF SAFETY ROD LOWER LATCH PROBLEMS
REVIEW OF LATCH INSPECTION VIDEO TAPES**

BY: J. J. BANKS

ISSUED: June 24, 1992

Author

J. J. Banks
Technical Reviewer

6/1/92
Date

6/2/92
Date

W. F. Swift for S. D. Burke
Manager, Components Handling Systems

6/3/92
Date

W. F. Swift
Manager, Process Systems

6/3/92
Date

J. J. Hendrix
Manager, Reactor Engineering Design

6/10/92
Date

Table Of Contents

<u>Section</u>	<u>Title</u>	<u>Page</u>
	Executive Summary.....	1
	Introduction.....	2
Summary		
A.	Design History.....	2
B.	Latch Inspection Video Tape review.....	2
Discussion		
A.	Design History.....	3
B.	Latch Inspection Video Tape review.....	7
Conclusions.....		8
References:		9
Attachments.....		9

ACTUATOR SYSTEM HISTORY OF LOWER LATCH PROBLEMS. REVIEW OF LATCH INSPECTION VIDEO TAPES

EXECUTIVE SUMMARY

During pre-restart testing the safety rod at position X26-Y10 bound after being driven approximately two (2) feet out of the reactor. Subsequently, the rod was manually returned to its seated position. Inspection of the lower latch showed that the latch locking plunger button (screwed on to the bottom of the plunger shaft and retained by a pin through a hole drilled through the button and the plunger shaft) was missing. The shaft failed through the hole drilled for the retaining pin. The button, with the retaining pin intact, was found lodged between the safety rod upper adapter collar and the top of the safety rod thimble top fitting. Analysis of the safety rod latch (Ref. 1) and accompanying forest guide tube design provided assurance that this type of failure would not cause binding during the "scramming" of the safety rods.

Inspection of all of the 'K' safety rod lower latches revealed six other latches with missing plunger buttons, and nine with other non-conformances which required latch replacement.

A history search conducted by Reactor Engineering Design, Components Handling Group (RED-CH), is included in this report. The history search shows that latch design modifications, as a part of initial development of the latch system and later to improve the delatching operation, were made during the 1950 and 1960 period. These modifications created a condition where latch damage could occur.

Video tapes were made during inspection of the safety rod latches in K area and control rod latches in L area. These tapes were reviewed by Reactor Engineering Design Components Handling engineers. The reviews were used for correlation of latch problems reported by the engineers/mechanics making the inspections. The K area tapes showed inspection of 65 of the 66 safety rod latches. The latch from position X49-Y55, had previously been inspected and replaced because of a missing button. Inspection of this latch was not included in the video taped inspection. The latch of the position originally found with the button missing, X26-Y10, had also been replaced prior to the tapes being made. This re-worked latch was shown in the video tape of the inspections. The review of the tapes showed the plunger buttons to be missing from five latches. RED-CH reviewed the L Area video taped inspection of 35 control rod clusters (245 latches). No non-conformances were noted.

INTRODUCTION:

This report summarizes the Reactor Engineering Design safety rod latch design history search and the video tape review of the inspections of the K area safety rod latches and the L area control rod latches.

The history search identified design changes of the safety rod latches and of the safety rod extension as contributors to the latch problems. The modification of the safety rod extension was the most significant contributor to the later latch damage.

The video tape review included recording the latch appearance and any other abnormalities.

SUMMARY:

Design History :

The safety rod latches and safety rod extensions have undergone numerous design changes since the early years of the plant. Although documented reasons for all of the changes are not available, most of the changes were made to facilitate better operation of the latch assembly. Modifications included increasing the latch jaw camming angle, increasing lock plunger button thickness, redesign of the latch guide bushings, and the addition of drain holes in the lower latch. The most significant change, which led to the recent latch failure, involved a modification to the safety rod extension.

In 1968, RTM-3206 (Ref. 2) recommended a modification to the safety rod extension to eliminate interference between the extension and the C&D machine water pan sweep. This change was successful in alleviating the problem at hand, however, it effectively eliminated critical interfacing clearances between the safety rod lower latch and the safety rod extension. The elimination of these clearances was responsible for the lower latch failures recently encountered.

Latch Inspection /Video Tape Review:

Each K Area Safety Rod lower latch was inspected by Reactor Maintenance personnel withdrawing it from the associated forest guide tube above the forest. Video tapes were made of the inspections by EES personnel. These tapes were then reviewed by Reactor Engineering Design. Five positions were noted having missing plunger buttons. One latch in which the button had been replaced was reinspected, but another, which had also been re-worked, was not inspected. Thus the tapes covered only 65 of the 66 latches. Two safety rod latches were identified as having obsolete safety rod guide bushings.

In addition, all I Area control rod latches were inspected. Reactor Engineering Design engineers reviewed the video taped inspection of the control rod latches in 35 of 61 clusters (245 of a total of 427 latches). No non-conformances were identified.

DISCUSSION

Design History

The earliest design drawing change for the safety rod lower latch involved adding a 1/32" X 45 degree chamfer to the edge of the upper flange of the latch locking plunger. No documentation has been located to indicate the reason for this modification. The date of the change, 7/52, was during the construction of the SRS reactors before the initial startup of R reactor, the first SRS reactor to start up. This change was probably found necessary during the assembly of the safety rod drive systems at that time. The other early change, 6/55, to the design drawings involved adding a concentricity tolerance (0.003" T.I.R.) for the sections of different diameter of the safety rod lower latch locking plunger stem. This may have been a correction of a deficiency of the drawing; no record of any plunger being modified as a result of this change has been found.

RTM-1190, 12/22/56, (Ref. 3) describes a problem of lower latches not satisfactorily delatching. This document notes that, during the initial operation of the latches, delatching problems were severe. It states that jaw guides had been installed on all latches but that delatching problems had continued. The RTM, based on a study by Design Engineering Division, recommended modifying latches which gave repeated problems. The latch jaws were to be replaced with those that had been tumbled to give appropriate surface characteristics, carefully gaged, and bent to a 6 degree camming angle instead of the originally specified 3° 20'. Although the RTM only recommended replacement of the jaws in those positions which had demonstrated problems in delatching, the print (D-122744) was revised to show the new requirements.

The next design change was recommended in RTM-2370, 6/28/62 (Ref. 4). This document notes that the design prints did not specify heat treatment of the jaws, jaw hanger, or jaw hanger extensions to the desired H-1025 condition. The RTM states that testing had shown that the parts were of the desired hardness. It recommended adding the heat treatment requirement to the design drawings (D-122743, D-122742, and D-122744). This same document notes that the lower latch balls were specified to be hardened PH 17-7, 17-4, or type 322 stainless steel, but inspections and chemical analyses indicated that some may have been made from type 440C stainless. The

RTM recommended that the prints (W-141309, W-141310, and W-141311) be revised to require use of type 302 SS balls with a Rockwell C hardness of 38. It further recommended that all the balls be replaced during planned outages.

Revisions to print D-141476, dated 11/5/62, changed the design of the locking plunger buttons. The changes required increasing the button thickness, adding a counterbore in the top of the button, and changing the size of the hole drilled for the retaining pin from a number 54 drill to 1/16". No documentation has been found to specify the reason for these changes.

RTM-2469, dated 11/15/62, (Ref. 5) specified modifications to improve latch draining characteristics, which had been noted to cause moderator spillage as a result of higher levels in the forest guide tube after the increase in reactor blanket gas pressure from 10" H₂O to 5 PSIG. Specifically, a 1/4" hole was to be drilled in the shoulder sleeve (D-141477) of the lower latch and a 3/16" hole was to be drilled in the jaw hanger (D-122743). The document specified that the modifications were to be made in P area, but the inference is clear that as other areas increased their blanket gas pressure similar changes would be needed.

A change on D-141476, dated 12/10/62, requires that the plunger shaft be undercut. A change on D-140959 shows the counterbore of the button and specifies that the counter bore should bottom on the shoulder when assembled.

RTM-2502, dated 1/7/63, (Ref. 6) specified a modification of the lower latch guide bushings (D-138350) to minimize the effect of the higher blanket gas pressure on the safety rod snubbing heights. A companion modification of the safety rod snubber collars was included in this RTM for the same reason.

RTM-2563, dated 4/30/63, (Ref. 7) notes that all balls in the K area lower latches had been changed (previously specified in RTM-2370) and should be changed in the other areas. No record of this work being completed has been found.

RTM-3206 (Ref. 2), dated 8/21/68, recommended that the rounded tip of the safety rod extensions be cut off 3/8" below the top of the extension to eliminate potential interference between the C&D machine water pan and the extension tip. The original extension tip was hemispherical. After the extension tip modification, accomplished by cutting the tips from the extensions on the rods by hand, the tip was flat. This modification eliminated the self correction of non-alignment of the tip to the lower latch plunger button by the hemispherical tip. Any misalignment or non-flatness

of the rod extension tip to the plunger button thus created a bending moment on the button.

This modification had the most detrimental impact on latch operation. It changed critical design clearances between latch surfaces and the safety rod extension. A high potential for latch damage was introduced as a result of load bearing surfaces being changed and required dimensions of mechanical actuation being decreased.

Project Problem 1-3359, 11/27/73, (Ref. 8) and Facility and Equipment Instruction, FEI-1137, 8/23/74, (Ref. 9) specify that existing spare parts should be modified to comply with the revisions shown on D-122743, D-141477, and D-122744. Recent investigations show that this work was never completed.

Project Problem 1-4232, 10/1/79, (Ref. 10) recommended that control and safety rod latches be checked for proper operation and the latch extensions be checked for straightness and roughness. No record of this being accomplished has been found. The following table shows the entire results of the history search:

LATCH DESIGN HISTORY SEARCH TABLE

<u>DATE</u>	<u>INITIATOR</u>	<u>CHANGE</u>	<u>REASON</u>
7/52	NO RECORD	MODIFIED CHAMFER OF PLUNGER SHAFT.	NO DOCUMENTED REASON.
10/53	NO RECORD	PIN CHANGED FROM 1.5" TO 1.437".	NO DOCUMENTED REASON.
6/55	NO RECORD	TOLERANCES FOR CONCENTRICITY OF PLUNGER SHAFT ADDED.	NO DOCUMENTED REASON.
12/56	RTM 1190	JAW TUMBLING AND CAREFULL GAGING SPECIFIED. JAW CAMMING ANGLE INCREASED FROM 30° TO 60°.	IMPROVE DELATCHING OPERATION BY DECREASING "HANGUPS".

<u>DATE</u>	<u>INITIATOR</u>	<u>CHANGE</u>	<u>REASON</u>
6/62	RTM-2370	HEAT TREATMENT OF LOWER LATCH JAWS, JAW HANGERS, AND EXTENSIONS,	CORRECT PRINT ERROR OF NOT SPECIFYING HARD- NESS.
		SPECS. OF BALLS REVISED TO ALLOW USE OF 302 SS BALLS. BALLS TO BE REPLACED.	ELIMINATE PROBLEMS OF BALL CORROSION AND WEAR
11/62	UNKNOWN	PLUNGER BUTTON COUNTER BORE ADDED.	UNDOCUMENTED.
		PLUNGER BUTTON THICKNESS FROM 3/16" TO 15/64".	UNDOCUMENTED.
11/62	UNKNOWN	PLUNGER BUTTON LOCK BORE CHANGED FROM #54 DRILL TO 1/16".	UNDOCUMENTED
11/62	RTM-2479	1/4" HOLE DRILLED IN SHOULDER SLEEVE FROM TOP END.	ALLOW BETTER DRAIN- ING OF LATCH AFTER IMPLEMENTATION OF 5 PSIG BLANKET GAS
		3/16" HOLE DRILLED IN JAW HANGER 3" FROM TOP OF LOWER LATCH.	ALLOW BETTER DRAINING OF LATCH.
12/62	UNKNOWN	UNDER CUT LOCKING PLUNGER.	UNDOCUMENTED.
		COUNTERBORE PLUNGER BUTTON.	UNDOCUMENTED.
1/63	RTM-2502	GUIDE BUSHINGS ON LOWER LATCHES AND SAFETY ROD SNUBBER COLLARS MODIFIED.	REDUCED EFFECT OF 5 PSIG BLANKET GAS ON SNUBBING HEIGHT OF SAFETY RODS.

<u>DATE</u>	<u>INITIATOR</u>	<u>CHANGE</u>	<u>REASON</u>
4/63	RTM-2563	NO CHANGE BUT DOCUMENTS THAT NON-STANDARD BALLS IN LOWER LATCHES IN K AREA HAD BEEN REPLACED. RECOMMENDED REPLACEMENT IN OTHER AREAS.	ELIMINATED BALL CORROSION AND GAVE BETTER WEAR RESISTANCE.
8/68	RTM-3206	MODIFIED SAFETY ROD EXTENSION TIP	ELIMINATE INTERFERENCE WITH C&D MACHINE WATER PAN SWEEP.
11/73	PROJ. PROB. 1-3359	NO NEW DESIGN. ORDER ISSUED FOR MODIFICATION OF EXISTING SPARE PARTS FOR PREVIOUS CHANGES.	SPARE PARTS INV. SHOWED CHANGES NEVER IMPLEMENTED IN SPARE PARTS.
8/74	FEI-1137	NO CHANGE. IMPLEMENTS PROJ. PROB. 1-3359.	SEE ABOVE.
10/79	PROJ. PROB. 1-4232	NO CHANGE	CHECK LATCHES FOR OPERATION, STRAIGHTNESS AND ROUGHNESS

Latch Inspection Video Tape Review:

An inspection was made of the safety rod lower latches in K Area, by Reactor Maintenance, by manually delatching each safety rod latch, withdrawing it up through its forest guide tube, and inspecting it on top of the forest makeup plate. As a part of the inspection, EES made a video tape of each latch which showed a bottom view of the latch. These tapes were then reviewed by Reactor Engineering Design (RED) engineers and the results of the review recorded (Attachment 1). The RED review noted the presence or absence of the lock plunger buttons and any other abnormalities. Position X49-Y55 was not inspected. This latch had previously been found to be missing its button, and thus re-worked. The lower latch of position X26-Y10 had also been re-worked but it was shown on the tape. A total of 5 positions were noted during the video tape review as having missing buttons. Other non-conformances included two latches, X23-Y37 and X27-Y85, which had obsolete safety rod guide bushings.

In addition, Reactor Engineering reviewed the video taped inspection of 35 of the 61 L Area control rod clusters (245 of 437 control rod latches) (Attachment 2). Some discoloration of latch parts was noted during review of the tapes but was attributed to the refraction of light by water on the latch parts. No other problems were noted during the inspections or the engineering review of the video tape.

IV. CONCLUSIONS:

1. Design changes were made which contributed to safety rod lower latch failures.
2. Latch deficiencies associated with the safety rod lower latches do not exist for the control rod latches.

REFERENCES:

1. RRD-RSE-92-0177, Safety Evaluation Documentation For Safety Rod Lower Latch Failures, to J. L. Hendrix from S. D. Burke, dated 1/27/92.
2. RTM 3206, Vertical Clearance Below the C&D Machines, L. W. Fox by E. C. Bertsche, to P. A. Dahlen, dated 8/21/92
3. RTM 1190, Modification of Lower Latches - Actuators, A. A. Johnson, by W. M. McGill, to F. H. Endorf, 12/22/56.
4. RTM 2370, Lower Latch Component Specifications, AG and AH Long Latch System, F. E. Kruesi, by E. C. Bertsche, to K. W. French, 5/28/62.
5. RTM 2479, Safety Rod Lower Latch Modifications, F. E. Kruesi, by J. M. Morrison, to K. W. French, 11/15/62.
6. RTM 2502, Safety Rod Snubbing Height At Increased Blanket Gas Pressure, F. E. Kruesi, by E. C. Bertsche, to K. W. French, 1/7/63.
7. RTM 2563, Actuator Lower Latch Balls, F. E. Kruesi, by E. C. Bertsche, to K. W. French, 4/30/63.
8. Project Problem 1-3359, Actuator Spare Parts, P. M. Hankinson to M. D. Moore, 11/27/73.
9. FEI 1137, Modify Actuator Spare Parts - Latch Jaws, H. T. Smoland to J. Giunnies Et Al, 8/23/74.
10. Project Problem 1-4232, Actuator Preventive Maintenance Buildings 105-PKC, W. L. Blithe to S. M. Olliff, 10/1/79.

ATTACHMENTS:

1. K Area Safety Rod Lower Latch Inspection Video Tape Review.
2. L Area Control Rod Lower Latch Inspection Video Tape Review.

ATTACHMENT 1

K AREA SAFETY ROD LOWER LATCH INSPECTION VIDEO TAPE REVIEW					
POSITION	COUNTER READING	BUTTON ON	FINGERS ON	INSERTION CHECKED	COMMENTS
TAPE NUMBER 1					
X47-Y31	1	YES	YES	YES	DENTS ON TWO FINGERS
X42-Y34	105	NO	YES		BROKEN THRU HOLE FOR PIN
X37-Y37	147	YES	YES	YES	SMALL DENTS IN BOTTOM OF JAW CAGE
X32-Y40	222	YES	YES	YES	DENT ON ONE FINGER
X27-Y43	286	YES	YES	YES	DENT ON ONE FINGER
X22-Y46	338	YES	YES	YES	SHAFT HAS NO CENTERING HOLE
X17-Y49	379	YES	YES	YES	DITTO
X12-Y52	424	YES	YES	YES	NONE
X07-Y55	474	YES	YES	YES	COUNTERBORE MAY BE DOWN
X08-Y46	537	YES	YES	YES	DENT AT THREAD INTERFACE
X13-Y43	581	NO	YES		BROKEN THRU PIN'S HOLE
TAPE NUMBER 2					
X09-Y37	1	YES	YES	YES	WOULD NOT FULLY LATCH
X23-Y79	126	YES	YES	YES	COUNTERBORE MAY BE DOWN
X27-Y85	202	YES	YES	NO	WOULD NOT LATCH, OBSOLETE GUIDE BUSHING
X46-Y40	246	YES	YES	YES	BUTTON FACE SCRATCHED (SEE NOTE BELOW)
X39-Y19	323	YES	YES	NO	WOULD NOT LATCH
X38-Y70	351	NO	YES	YES	BROKEN THRU PIN'S SLOT - SLOT OFF CENTR
X14-Y34	369	NO	YES	YES	SAME AS ABOVE
X10-Y28	387	YES	YES	YES	COUNTERBORE MAY BE DOWN-FACE SCRATCH
X15-Y25	431	YES	YES	YES	SCRATCH ACROSS END OF PLUNGER SHAFT
X11-Y61	479	YES	YES	YES	DENTS ON BUTTON
X10-Y70	524	YES	YES	YES	NONE
X14-Y76	561	YES	YES	YES	NONE
X15-Y67	595	YES	YES	YES	NONE
X16-Y58	620	YES	YES	YES	SCRATCH ON BUTTON FACE
X18-Y40	651	YES	YES	YES	NONE
X19-Y31	674	YES	YES	YES	NONE
X20-Y22	700	YES	YES	YES	DENT ON ONE FINGER
X21-Y13	729	YES	YES	YES	CAGE BROKEN AT BOTTOM EDGE
NOTE: SNUBBER ON POSITION X46-Y40 WAS NOTED ON THE TAPE TO BE MUSHROOMED					

[illegible]

ATTACHMENT 1

K AREA SAFETY ROD LOWER LATCH INSPECTION VIDEO TAPE REVIEW					
POSITION	COUNTER READING	BUTTON ON FINGERS ON	INSERTION CHECKED	COMMENTS	
TAPE NUMBER 4					
X43-Y25	1	YES	YES	NONE	
X41-Y43	42	YES	YES	NONE	
X40-Y52	73	YES	YES	NONE	
X39-Y61	111	YES	YES	NONE	
X37-Y79	145	YES	YES	DENT ON BUTTON AND ON ONE FINGER	
X42-Y76	180	YES	YES	FORIEGN MATERIAL ON END OF SHAFT	
X43-Y67	220	YES	YES	NONE	
X44-Y58	251	YES	YES	NONE	
X45-Y49	276	YES	YES	NONE	
X48-Y64	306	YES	YES	NONE	
X31-Y49	350	YES	NOT SHOWN	NONE	

ATTACHMENT 2

L AREA CONTROL ROD LOWER LATCH INSPECTION VIDEO TAPE REVIEW		
CLUSTER	BUTTON ON	COMMENTS
49	ALL	GENERAL DIS-COLORATION OF SOME BUTTONS, MAY BE RELATED TO REFRACTION OF THE LIGHT.
NUMBER NOT SHOWN	ALL	
NUMBER NOT SHOWN	ALL	
NUMBER NOT SHOWN	ALL	
4	ALL	
1	ALL	
7	ALL	
19	ALL	
37	ALL	
61	ALL	
60	ALL	
36	ALL	
18	ALL	
5	ALL	
3	ALL	
14	ALL	
29	ALL	
NUMBER NOT SHOWN	ALL	
51	ALL	
30	ALL	
15	ALL	
16	ALL	
17	ALL	
35	ALL	
59	ALL	
34	ALL	
33	ALL	
32	ALL	
31	ALL	
52	ALL	APPEARED TO HAVE SOME STRING IN THE LATCH
53	ALL	
54	ALL	
55	ALL	
56	ALL	
57	ALL	
45	ALL	
IT WAS NOT POSSIBLE TO DETERMINE WHICH LATCH IN A CLUSTER WAS BEING INSPECTED. SOME OF THE INSPECTIONS DID NOT SHOW CLUSTER NUMBERS.		

WSRC-TR-92-42-003

DOCUMENT CLASSIFICATION:

KEYWORDS

Technical
Reactor, K Area,
Actuator
Safety Rod

DISTRIBUTION

J. E. Aggas, 704-10K
H. F. Allen, 707-C
W. F. Bates, 105-11K
F. D. Benton, 707-C
F. Beranek, 773-A
M. R. Buckner, 773-A
S. D. Burke, 707-C
D. A. Busch, 773-53A
C. D. Cowfer, 705-1C
J. N. Dewes, 707-C
L. v. DeWitt, 707-C
R. Estrada, 105-K
D. E. Frederici, 105-K
D. W. Freeman, 705-1C
A. J. Garrett, 773-A
B. D. Getson, 705-1C
G. M. Hass, 704-K
A. Henderson, 723-A
J. L. Hendrix, 705-1C
S. Hunnewell, 105-K
D. R. Ketcham, 707-C
M. A. Kokovich, 707-C
J. Lahman, 105-K
R. E. Lide, 706-14C
D. R. Mason, 703-41A
C. R. Mastromonico, 707-C
W. V. Minnick, CCC-992W-1, '299
T. M. Monahan, 704-K
J. R. Murphy, 105-10K

R. E. Painter 773-54A
C. Prakash, 707-42B/3
T. M. Punch, 707-C
D. B. Rankin, 704-C
C. G. Reynolds, 704-C
J. A. Roach, 703-14C
G. R. Rose, 707-C
M. Sackash, 703-10C
R. L. Salizzoni, 707-C
C. M. Schaumann, 707-C
S. R. Smith, 707-C
K. J. Stoner, 707-5C
W. L. Stubbs, 703-41A
W. F. Swift, 707-C
R. P. Taylor, 7-4-K
J. R. Tucciarone, 707-C
A. M. Vincent, III, 707-C
B. Voegtlen, 105-K
P. R. Vormelker, 730-A
W. S. Webb, 704-22K
Document Accountability,
 % N. W. Davis, 705-1C
MTS Coordinator, 705-1C/1H
STE Copy (%D. Cato), 105-K
707-C File

END

**DATE
FILMED
9/29/92**