ORNL/NUREG/NSIC-127

MASTER

Annotated Bibliography of
Safety-Related Occurrences in
PRESSURIZED-WATER NUCLEAR POWER PLANTS
as Reported in 1975

R. L. Scott

R. B. Galloher

PREPARED FOR THE U.S. NUCLEAR REGULATORY COMMISSION
OFFICE OF NUCLEAR REGULATORY RESEARCH
UNDER INTERAGENCY AGREEMENT ERDA NO. 40-551-75 and 40-552-75

NUCLEAR SAFETY INFORMATION CENTER

NSIC

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

BLANK PAGE

AVAILABILITY OF NSIC DOCUMENTS

Recent NSIC reports that may be ordered from the National Technical Information Service, U.S. Department of Commerce, 5285 Port Royal Road, Springfield, Virginia 22161 are listed below.

<u>ORNL/ NSIC</u>	<u>Title</u>	<u>Price</u>
53	Radiography Incidents and Overexposures, by R. L. Scott and R. B. Gallaher, Dec. 1972	\$10.00
55 Vol. I	Design Data and Safety Features of Commercial Nuclear Power Plants, Vol. I, Docket No. 50-3 through 50-295, by F. A. Heddleson, Dec. 1972	\$15.00
55 Vol. II	Design Data and Safety Features of Commercial Nuclear Power Plants, Vol. II, Docket No. 50-296 through 50-395, by F. A. Heddleson, Jan. 1972	\$15.00
55 Vol. III	Design Data and Safety Features of Commercial Nuclear Power Plants, Vol. III, Docket No. 50-397 through 50-449, by F. A. Heddleson, Apr. 1974	\$15.00
55 Vol. IV	Design Data and Safety Features of Commercial Nuclear Power Plants, Vol. IV, Docket No. 50-452 through 50-503, by F. A. Heddleson, June 1975 See ORNL/NSIC-96 for Vol. V.	\$15.00
74	Calculation of Doses Due to Accidentally Released Plutonium from an LMFBR, by B. R. Fish, G. W. Keilholtz, W. S. Snyder, and S. D. Swisher, Nov. 1972	\$15.00
82	Chemical and Physical Properties of Methyl Iodide and Its Occurrence Under Reactor Accident Conditions - A Summary and Annotated Bibliography, by L. F. Parsly, Dec. 1971	\$12.00
91	Safety-Related Occurrences in Nuclear Facilities as Reported in 1970, by R. L. Scott, Dec. 1971	\$10.00
93	Summary of Recent Legislative and Regulatory Activities Affecting the Environmental Quality of Nuclear Facilities, by R. H. Bryan, B. L. Nichols, and J. W. Ramsey, May 1972	\$10.00
96	Design Data and Safety Features of Commercial Nuclear Power Plants (Fifth Volume of ORNL/NSIC-55), by F. A. Heddleson	\$15.00
97	Indexed Bibliography of Thermal Effects Literature-2, by J. G. Morgan and C. C. Coutant, May 1972	\$10.00
100	Nuclear Power and Radiation in Perspective, Selections from <i>Nuclear Safety</i> , by J. R. Buchanan, Mar. 1974	\$15.00
101	Indexed Bibliography on Environmental Monitoring for Radioactivity, by B. L. Houser, May 1972	\$10.00
102	Compilation of National and International Nuclear Standards (Excluding U.S. Activities) 8th Ed., 1972, by J. P. Blakely, June 1972	\$10.00
103	Abnormal Reactor Operating Experiences, 1969-1971, by R. L. Scott and R. B. Gallaher, May 1972	\$ 8.00
105	Indexed Bibliography on Nuclear Facility Siting, by H. B. Piper, June 1972	\$10.00
106	Safety-Related Occurrences in Nuclear Facilities as Reported in 1971, by R. L. Scott and R. B. Gallaher, Sept. 1972	\$12.00
107	Index to <i>Nuclear Safety</i> , A Technical Progress Review by Chronology, Permuted Title, and Author, Vol. 1, No. 1 through Vol. 13, No. 6, May 1973	\$ 8.00
108	Personnel Involved in Development of Nuclear Standards in U.S. - 1972, J. Paul Blakely, Chairman - Status and Recommendations Committee - American Nuclear Standards Institute, May 1973	\$15.00
109	Safety-Related Occurrences in Nuclear Facilities as Reported in 1972, by R. L. Scott and R. B. Gallaher, Dec. 1973	\$15.00
110	Indexed Bibliography of Thermal Effects Literature-3, by J. G. Morgan, July 1973	\$12.00

OAK RIDGE NATIONAL LABORATORY

OPERATED BY
UNION CARBIDE CORPORATION
NUCLEAR DIVISION

POST OFFICE BOX 7
OAK RIDGE, TENNESSEE 37830

NUCLEAR SAFETY INFORMATION CENTER
615/483-6611: 3-7253
FTS 890-7253

July 21, 1976

NUCLEAR SAFETY JOURNAL
615/483-6611: 3-6453
FTS 890-6453

ERRATA

ORNL/NUREG/NSIC-127

Note: In using the indexes (Keyword and Permuted Title) included in the report ORNL/NUREG/NSIC-127, page numbers in the indexes referring to the abstracts should be increased by 16 (e.g., a reference to p. 2 in an index actually means p. 18) due to an error in pagination.

We regret the inconvenience.

J. R. Buchanan, Assistant Director
Nuclear Safety Information Center

Contract No. W-7405-eng-26

ANNOTATED BIBLIOGRAPHY OF SAFETY-RELATED OCCURRENCES IN
PRESSURIZED-WATER NUCLEAR POWER PLANTS
AS REPORTED IN 1975

R. L. Scott
Operations Division

R. B. Gallaher
Reactor Division

NOTES
This report was prepared as an account of work sponsored by the United States Government. Neither the United States nor the United States Energy Research and Development Administration, nor any of their employees, nor any of their contractors, subcontractors, or their employees, make any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights.

Manuscript Completed - 5-26-76

Date Published - July, 1976

PREPARED FOR THE U.S. NUCLEAR REGULATORY COMMISSION OFFICE
OF NUCLEAR REGULATORY RESEARCH UNDER
INTERAGENCY AGREEMENT ERDA NO. 40-551-75 AND 40-552-75

OAK RIDGE NATIONAL LABORATORY
Oak Ridge, Tennessee 37830
operated by
UNION CARBIDE CORPORATION
for the
ENERGY RESEARCH AND DEVELOPMENT ADMINISTRATION

BLANK PAGE

Printed in the United States of America. Available from
National Technical Information Service
U.S. Department of Commerce
5285 Port Royal Road, Springfield, Virginia 22161
Price: Printed Copy \$10.75; Microfiche \$2.25

This report was prepared as an account of work sponsored by the United States Government. Neither the United States nor the Energy Research and Development Administration/United States Nuclear Regulatory Commission, nor any of their employees, nor any of their contractors, subcontractors, or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness or usefulness of any information, apparatus, product or process disclosed, or represents that its use would not infringe privately owned rights.

CONTENTS

	<u>Page</u>
FOREWORD.....	v
PARTS AND METHOD OF INDEXING ABSTRACTS.....	vii
PREVIOUS REPORTS IN THIS SERIES.....	viii
ABSTRACT.....	1
INTRODUCTION.....	1
SUMMARY OF OCCURRENCE DATA.....	3
REVIEW OF SELECTED OCCURRENCES.....	5
Reactor Coolant Pump Seal Water	
System Fails.....	6
Control System Causes Transients.....	8
Noble-Gas Release.....	10
Ice Condenser Doors Freeze.....	11
CONCLUSION.....	11
REFERENCES.....	13
BIBLIOGRAPHY.....	15
KEY-WORD INDEX.....	271
PERMUTED-TITLE INDEX.....	287

FOREWORD

The Nuclear Safety Information Center (NSIC), which was established in March 1963 at Oak Ridge National Laboratory, is principally supported by the U.S. Nuclear Regulatory Commission's Office of Nuclear Regulatory Research. Support is also provided by the Division of Reactor Development and Demonstration of the U.S. Energy Research and Development Administration. NSIC is a focal point for the collection, storage, evaluation, and dissemination of safety information to aid those concerned with the analysis, design, and operation of nuclear facilities. A system of key words is used to index the information cataloged by the Center. The title, author, installation, abstract, and key words for each document reviewed are recorded at the central computing facility in Oak Ridge. The references are cataloged according to the following categories:

1. General Safety Criteria
2. Siting of Nuclear Facilities
3. Transportation and Handling of Radioactive Materials
4. Aerospace Safety (inactive ~1970)
5. Heat Transfer and Thermal-Hydraulics
6. Reactor Transients, Kinetics, and Stability
7. Fission Product Release, Transport, and Removal
8. Sources of Energy Release under Accident Conditions
9. Nuclear Instrumentation, Control, and Safety Systems
10. Electrical Power Systems
11. Containment of Nuclear Facilities
12. Plant Safety Features - Reactor
13. Plant Safety Features - Nonreactor
14. Radionuclide Release and Movement in the Environment
(inactive September 1973)
15. Environmental Surveys, Monitoring, and Radiation Exposure
of Man (inactive September 1973)
16. Meteorological Considerations
17. Operational Safety and Experience
18. Safety Analysis and Design Reports

BLANK PAGE

19. Radiation Dose to Man from Radioactivity Release to the Environment (inactive September 1973)
20. Effects of Thermal Modifications on Ecological Systems (inactive September 1973)
21. Effects of Radionuclides and Ionizing Radiation on Ecological Systems (inactive September 1973)

Computer programs have been developed that enable NSIC to (1) operate a program of selective dissemination of information (SDI) to individuals according to their particular profile of interest, (2) make retrospective searches of the stored references, and (3) produce topical indexed bibliographies. In addition, the Center Staff is available for consultation, and the document literature at NSIC offices is available for examination. NSIC reports (i.e., those with the ORNL/NSIC and ORNL/NUREG/NSIC numbers) may be purchased from the National Technical Information Service (see inside front cover). All of the above services are free to NRC and ERDA personnel as well as their direct contractors. They are available to all others at a nominal cost as determined by the ERDA Cost Recovery Policy. Persons interested in any of the services offered by NSIC should address inquiries to:

J. R. Buchanan, Assistant Director
Nuclear Safety Information Center
P.O. Box Y
Oak Ridge National Laboratory
Oak Ridge, Tennessee 37830

Telephone 615-483-8611, Ext. 3-7253
FTS number is 850-7253

PARTS AND METHOD OF INDEXING ABSTRACTS

PREVIOUS REPORTS IN THIS SERIES

1. W. R. Casto and E. N. Cramer, *Safety-Related Occurrences in Nuclear Facilities as Reported in 1967 and 1968*, ORNL/NSIC-69 (July 1970) (available from NTIS for \$3.00).
2. R. L. Scott and W. R. Casto, *Safety-Related Occurrences in Nuclear Facilities as Reported in 1969*, ORNL/NSIC-87 (August 1971) (available from NTIS for \$3.00).
3. R. L. Scott, *Safety-Related Occurrences in Nuclear Facilities as Reported in 1970*, ORNL/NSIC-91 (December 1971) (available from NTIS for \$10.00).
4. R. L. Scott and R. B. Gallaher, *Safety-Related Occurrences in Nuclear Facilities as Reported in 1971*, ORNL/NSIC-106 (September 1972) (available from NTIS for \$12.00).
5. R. L. Scott and R. B. Gallaher, *Safety-Related Occurrences in Nuclear Facilities as Reported in 1972*, ORNL/NSIC-109 (December 1973) (available from NTIS for \$15.00).
6. R. L. Scott and R. B. Gallaher, *Annotated Bibliography of Safety-Related Occurrences in Nuclear Power Plants as Reported in 1973*, ORNL/NSIC-114 (November 1974) (available from NTIS for \$15.00).
7. R. L. Scott and R. B. Gallaher, *Annotated Bibliography of Safety-Related Occurrences in Nuclear Power Plants as Reported in 1974*, ORNL/NSIC-122 (May 1975) (available from NTIS for \$15.00).

**ANNOTATED BIBLIOGRAPHY OF SAFETY-RELATED OCCURRENCES IN
PRESSURIZED-WATER NUCLEAR POWER PLANTS
AS REPORTED IN 1975**

R. L. Scott R. B. Gallaher

ABSTRACT

This bibliography contains 100-word abstracts of reports to the U.S. Nuclear Regulatory Commission concerning operational events that occurred at pressurized-water reactor nuclear power plants in 1975. The report includes 1097 abstracts, arranged alphabetically by reactor name and then chronologically for each reactor, that describe incidents, failures, and design or construction deficiencies experienced at the facilities. Key-word and permuted-title indexes are provided to facilitate location of the subjects of interest, and tables summarizing the information contained in the bibliography are presented. The information listed in the tables includes instrument failures, equipment failures, system failures, causes of failures, deficiencies noted, and the time of occurrence (i.e., during refueling, operation, testing, or construction). A few of the unique events that occurred during the year are reviewed in detail.

INTRODUCTION

This report (along with ORNL/NUREG/NSIC-126) represents the eighth of a series issued annually by the Nuclear Safety Information Center (NSIC) which presents abstracts of safety-related occurrences reported by light-water reactor licensees in the United States during the previous year. In particular, this report contains abstracts of 1097 occurrences reported by licensees of pressurized-water reactor nuclear power plants in the United States during 1975. The seven previous reports¹⁻⁷ covered the period 1967 through 1974. In addition, four related NSIC reports⁸⁻¹¹ contain information on reactor operating experiences reported by the U.S. Nuclear Regulatory Commission (formerly AEC) for the period 1966 through 1974.

Previous reports in this series contained the occurrences for both pressurized- and boiling-water reactor facilities; however, due to the continual growth in the number of facilities and consequently in the

number of reports, it has become necessary to issue this year's occurrences in two reports. The report that contains the occurrences at boiling-water reactor nuclear power plants is ORNL/NUREG/NSIC-126, *Annotated Bibliography of Safety-Related Occurrences in Boiling-Water Nuclear Power Plants as Reported in 1975*.

The occurrence reports listed in this bibliography were submitted by power plant licensees to NRC in accordance with licensing requirements. The reporting requirements for nuclear facility licensees are included in Parts 20, 40, 50, 70, and 73 of Title 10 of the *Code of Federal Regulations* and described in detail in *AEC Regulatory Guide No. 1.16*.¹² The requirements for reporting design or construction deficiencies of facilities that have construction permits are given in 10 CFR 50.55, paragraph e.¹³

The information for this report was obtained from the computer files of NSIC in the form of 100-word abstracts of reports from power reactor licensees. Technical specialists at NSIC prepared the abstracts, with appropriate key words for computer storage and retrieval. Input to the computer is a continuing process; therefore, persons desiring an updating of the information on operating experiences at nuclear power plants may obtain a literature search by contacting NSIC.

The NSIC computer also provides a bimonthly printout of the current experiences at operating plants; these are published in each issue of the *Nuclear Safety* journal. Information on the current experiences at reactors undergoing startup testing or under construction can also be obtained by contacting the NSIC.

The 100-word abstracts in this report are arranged alphabetically according to the name of the reactor and then chronologically for each reactor. In addition, tables are presented that indicate the number of times a piece of equipment, an instrument, or a system was reported as having been involved in a malfunction. Included in the tables are causes, deficiencies, and time of occurrence (i.e., during operation, testing, refueling, or construction). This is followed by a brief discussion of four occurrences that were considered to be the most interesting of those reported during the year.

In addition to the abstracts describing each event, key-word and permuted-title indexes are provided for quickly determining abstracts that discuss a particular item of interest. For example, persons interested in the problems with flow sensors may find the abstracts listed under the key word "sensors, flow"; or, using the permuted-title index, they can find the abstracts listed with the word "sensor" or with the word "flow."

Before reviewing the bibliography, it may also be helpful to review the "Parts and Method of Indexing Abstracts," which shows a typical abstract with its component parts identified (p. vii). Note the list of key words, which gives a quick indication of the contents of the abstract. The availability of the material is indicated for all abstracts except those that appear in sources such as technical journals, which are available in most technical libraries. In these cases, the name of the journal, issue, date, and page numbers are given above the abstract. Generally the material related to licensed facilities may be found in the U.S. NRC Public Document Room, 1717 H Street, Washington, D.C. 20545, and/or the material may be purchased from the National Technical Information Service, U.S. Department of Commerce, 5285 Port Royal Road, Springfield, Virginia 22151.

SUMMARY OF OCCURRENCE DATA

The 1097 abstracts in the bibliography were reviewed and tabulations made of significant items to indicate the total number of reports concerned with those items. These tabulations indicate items that should receive more attention by reactor operators, designers, or other interested parties.

Table 1 lists the equipment, instrument, and system malfunctions. As the table indicates, the larger and more complicated systems experience the most malfunctions. Pipes, pumps, and valves are the equipment items that experience failures most frequently as has been observed in past years. Switches also continue as the instrument experiencing problems most frequently. Most of these troubles are attributable to set-point drift or calibration problems.

Table 1. Number of PWR problems by component and system

Component	Percent	Number	System	Percent	Number
Equipment					
Pipes	13	99	Reactor protection	11	78
Pumps	12	98	Feedwater	11	74
Valves	11	81	Containment isolation	10	71
Storage container	8	62	Main cooling	9	65
Seal	8	61	Safety injection	8	57
Steam generator	7	52	Electric power	5	37
Manual generator	7	50	Containment	5	35
Valve operators	5	36	Emergency power	4	31
Tubing	3	19	Auxiliary cooling	4	28
Containment air lock	2	18	Shutdown cooling	4	27
Blowers	2	17	Coolant purification	3	23
Heat exchanger	2	16	Containment spray	3	21
Shock absorber	2	15	Engineered safety feature	3	21
Filters	2	14	Pneumatic	3	20
Fastener	2	14	Containment air cooling	3	20
Check valve	2	12	Control rod drive	3	19
Motors	1	11	Containment purge	3	18
Motors	1	10	Environmental monitoring	2	14
Control rods	1	10	Pressure relief	2	14
Pressurizer	1	10	Cooler, tower	1	10
Pool	1	8	Emergency, cooling	1	9
Accumulators	<1	6	Pool storage	1	9
Bearings	<1	6	Off-gas	<1	2
Crane	<1	6			
Pressure vessel	<1	5			
Nozzle	<1	5			
Batteries	<1	5			
Flange	<1	4			
Air driers	<1	3			
Containment vacuum breakers	<1	2			
Instrumentation					
Switch	23	122			
Pressure sensor	10	50			
Electronic function unit	10	50			
Relays	9	48			
Cables and connectors	9	46			
Breakers	7	40			
Temperature sensor	6	33			
Level sensor	6	30			
Radiation monitors	5	25			
Flow sensor	3	18			
Solenoid	3	14			
Interlocks	3	15			
Accumulators	2	10			
Amplifier	1	4			
Solid-state device	1	4			
Transformer	1	4			
Recorders	1	4			

Table 2 lists causes of malfunctions, deficiencies noted, and the time at which the event occurred. Again, as in past years, design errors were the most numerous, as expected, since the design encompasses the entire plant and also involves conceptual thinking. Piping and seal leaks were the most numerous deficiency noted. The second most numerous deficiency, procedures, most frequently involved deficient procedures, but failure of operators to follow procedures is included. The listing under "time of occurrence" shows that many defective items were found during surveillance testing, and thus their adverse effect on reactor operation was prevented.

Table 2. Classification of FILL problems by cause, deficiency, and time of occurrence

	Percent	Number
Cause		
Design error	21	267
Equipment failure	18	161
Administrative error	17	137
Maintenance error	14	111
Operator error	14	111
Installation error	9	72
Fabrication error	5	43
Weather	2	15
Deficiency		
Leak	19	130
Procedures	15	101
Instrument calibration	13	85
Set-point drift	10	71
Welds	8	52
Airborne activity release	7	47
Liquid activity release	5	31
Lubrication	5	31
Quality assurance	3	19
Vibration	3	19
Corrosion	2	14
Communication	2	15
Fatigue	2	12
Flow blockage	2	12
Personnel exposure	1	9
Erosion	1	7
Contamination	<1	6
Flux tilt	<1	5
Fire	<1	3
Time of occurrence		
Operation	58	634
Testing	28	304
Construction	9	97
Refueling	5	62

REVIEW OF SELECTED OCCURRENCES

A review of the reported occurrences indicated that most were of a routine inconsequential nature; however, a few were significant or unique. Four occurrences that were considered to be the most interesting are presented here to illustrate the types of experiences that occurred in 1975.

Reactor Coolant Pump Seal Water System Fails

At the H. B. Robinson 2 nuclear power plant, the seal water system for one of the three reactor coolant pumps failed. This pressurized-water reactor plant, owned and operated by the Carolina Power & Light Co., is located in Hartsville, S.C. During the incident the leak rate exceeded the capacity of the charging pumps, but water levels in the reactor coolant system were maintained by the safety-injection pumps. Before the leak was stopped, the containment floor had been flooded to a height of 12.5 in., a total of 132,500 gal of water. However, since the plant had been designed to handle such an incident, there was no damage beyond that sustained by the reactor coolant pump.

The trouble began May 1, 1975, after the plant had just reached full power following a maintenance outage. Naturally, xenon was building up in the core, and the boron dilution procedure was under way to compensate for the gradual reactivity loss due to the xenon. During the dilution process the operators observed that the seal leakoff flow from pump C was sensitive to all additions of water to the primary system. Seal water is supplied by the charging pumps that return the letdown flow after cleanup back to the reactor coolant system. Since the seal leakoff flow was within limits and since the variations were gradual (not spiking), operation continued. Sometime later the flow spiked several times, but the reactor coolant pump vibrations were normal. The seal leakoff flow then oscillated full range several times and stabilized at greater than 6 gal/min. At this point, load reduction at 10% of total power per minute was started. When the load reached 36% of full power, power reduction was stopped and the reactor coolant pump C was shut down. Soon thereafter the reactor scrambled when the turbine tripped because of a high water level in one of the three steam generators.

Failure of the seal No. 1 on pump C permitted 540°F primary coolant to flow through the seal, heating its thermal barrier. Heating of the thermal barrier caused steam to form suddenly in the component cooling water used to control temperature in the thermal barrier. This steam formation resulted in high flow indications in the component-cooling-water return line from the pumps and automatically closed the

common component-cooling-water return valve. This time, the shift foreman ordered pumps A and B stopped when flashing of primary coolant in the No. 1 seal-water leakoff line, which is common to all pumps, threatened to cause loss of seal flow. When the first section of the C pump seal system failed, the resulting flow of primary coolant past the seal caused the flashing in the seal leakoff line. The leakoff isolation valve for the No. 1 seal of pump C was not closed prior to stopping pumps A and B, and the No. 1 seal flow was then lost on pump A. The No. 1 seal leakoff return isolation valve from pump C was shut to reduce pressure surges in the common return lines. The No. 1 seal flow was then lost on pump B.

Owing to the failure of the No. 1 seal and the subsequent failure of the thermal barrier's cooling function, hot water was entering the reactor coolant drain tank via the normal No. 2 seal leakoff line. Since this water was flashing to steam, causing a pressure buildup in the drain tank, a valve was opened to drain the tank to the containment sump.

After it was determined that the thermal-barrier cooling coils were not leaking, the common automatically controlled outlet valve on the component-cooling line for the thermal barriers was blocked open to reduce temperatures to below boiling in the thermal barrier of pump C. After temperatures were reduced, the valve was unblocked and it stayed in its normal open modulating position.

When seal-water flow could not be reestablished on pumps A and B, it was decided to operate pump C as long as the second section of its seal continued to function. Primary coolant flow was desirable for proper mixing of the boron that was being added in preparation for cooling down the system. The pump was started and operated for 93 min before failure of the second and third portions of its seal caused the pump to be shut down. The leak rate through the completely failed seal system decreased the pressurizer level drastically, and it was necessary to use the safety-injection system to maintain the pressurized level while the leak to the containment system was being stopped.

The occurrence resulted in no off-site releases or exposures, and at no time were the plant personnel in any danger. Failure of the seal caused overheating of the pump shaft and seal housing. The seals and

their housing, the pump shaft, and associated equipment were replaced before the plant was again started up.

As a result of the containment flooding to a height of 12.5 in., approximately 650 ft of stainless-steel piping was submerged. Portions of this piping were flooded for 2 days in water that had a chloride concentration of 0.25 ppm. Consequently, there was concern for the saturation of the insulation with chlorides, possible leaching out on piping, and the potential for chloride stress corrosion.

A chemical analysis of each pipe and insulation at its lowest elevation showed that both met the requirements of Westinghouse specification PS 83336 KA, which corresponds to Fig. 1 of Regulatory Guide 1.36, "Nonmetallic Thermal Insulation for Austenitic Stainless Steel." Thus the results indicate that sufficient leachable sodium and silicate ions were present to assist in minimizing the effects of chloride and fluoride.

On the basis of this evaluation, it was deemed unnecessary to remove and replace the wetted insulation; however, further sampling of the piping and insulation was to be performed at the next scheduled outage.¹⁴⁻¹⁶

Control System Causes Transients

At Oconee 3, a pressurized-water reactor (PWR) owned and operated by Duke Power Company near Clemson, S.C., a transient occurred while the reactor power level was being decreased for a routine maintenance shutdown. Prior to the unintentional transient, the reactor power was being reduced from 100% to 15% of full power by the control system. When 15% of full power was reached, the unit load demand was 65 MW(e), but the power being generated was 115 MW(e). This disparity between the unit load demand and power generation by the reactor existed because the reactor was operating at its low limit of 15% of full power while being controlled completely automatically and could not continue following the further decreasing load demand. At this point the operator placed the turbine control in manual, thus placing the control system in the "load tracking" mode. This led to an automatic rapid increase

in the unit load demand to match the reactor power output. In the meantime the main steam bypass valves opened because of excess reactor power; and, as the main steam pressure decreased, the valves closed. The control system for the feedwater flow to the steam generator could not follow the rapid change in unit load demand, and feedwater flow lagged. This caused the feedwater flow and the steam-generator water level to oscillate, which in turn caused temperature and pressure transients in the reactor coolant system. When the reactor-coolant-system pressure reached 2255 psi, a power-operated relief valve opened, as required; but the valve failed to close at 2200 psi as it should, even though the open/closed lights in the control room did not indicate that the valve was still open. The reactor coolant pressure continued down because of this open valve, the reactor tripped on low pressure, and the high-pressure safety-injection system automatically actuated.

Although the operator closed the isolation valve on the line with the failed power-operated relief valve immediately after the reactor trip to terminate the depressurization, the valve was reopened because the water level in the pressurizer was rising rapidly. The isolation valve was reclosed when the reactor coolant pressure reached 800 psi. A cooldown of 101°F occurred during the first hour when the temperature was below 530°F. The transient and associated events also caused the quench-tank rupture disk, which received the blowdown from the power-operated relief valve, to blow. This caused the insulation to separate from the bottom nozzle of the pressurizer, releasing 1500 gal of reactor coolant to the reactor-building sump.

There was no significant increase in the radiation level in the reactor building, nor was any radioactivity released to the environment. Also, the cooldown rate did not affect the safety of the reactor.

The power-operated relief valve stuck in the open position because of heat expansion, buildup of boric acid crystals on the valve lever, rubbing of the lever against the solenoid brackets, and bending of the solenoid spring bracket.

The valve was repaired and reinstalled, and the problem with the valve position indicator cleared up.

The following corrective actions have been completed:

1. The unit shutdown procedures for all Oconee units have been revised to include a change that will prevent decreasing unit load demand below 120 MW(e) before placing the control system in the tracking mode. This minimizes the error between the unit load demand and generated power and reduces the possibility of feedwater flow and reactor-coolant-system transients.
2. The power-actuated pressure-relief valves of Units 1 and 2 will be inspected as soon as possible for any indication of buildup of boric acid crystals.
3. To verify the proper functioning of power-actuated pressurizer-relief valves, they will be cycled prior to startup with a test signal corresponding to 2285 psi.
4. The quench-tank rupture disk was replaced, the bottom nozzles on the pressurizer were dye penetrant tested, and the insulation was replaced.
5. Operating personnel were advised of this incident and given specific instructions to immediately close the isolation valve.¹⁷⁻¹⁹

Noble-Gas Release

A calculated total of 63.7 Ci of radioactive gas was released at Zion power station during venting of a mixed-bed demineralizer. This station has two PWRs that are owned and operated by Commonwealth Edison Company, Chicago, Ill. The maximum release rate was calculated to be 105,600 $\mu\text{Ci/sec}$, and the rate was estimated to have exceeded the technical-specifications limit of 60,000 $\mu\text{Ci/sec}$ for 6.5 min. The procedure for venting these demineralizers requires the use of primary makeup water that contains no radioactive gases. However, this time the venting was mistakenly done with the demineralizer connected to the reactor coolant system. This resulted in a direct pathway for releasing radioactive gas from the reactor coolant system to the auxiliary building through a loose manhole cover on the equipment drain tank in the auxiliary building. Although the release had no measurable consequence off

site, the operating procedures for venting the demineralizers have been strengthened, and the manhole cover has been tightened.

The calculated release, based on the long-lived radioactive gases in the reactor coolant, was about 1 Ci of mixed noble gases. However, the noble gases with very short half-lives in the coolant system were also released. An attempt will be made to determine the quantity of these gases more accurately.^{20,21}

Ice Condenser Doors Freeze

A force greater than 675 in.-lb, the technical specifications limit, was required to open 10 of the 48 lower-inlet ice-condenser doors at the *Donald C. Cook* nuclear power plant. This plant is a PWR operated by the *Indiana and Michigan Electric Company*, and is located at Benton Harbor, Mich. At the time this surveillance test was being conducted, the reactor was shut down. Ice had formed from condensation on the outside and at the bottom of the door frames in 20 of 24 inlet bays. After the ice was removed and the doors opened manually, the opening torque for all doors was in tolerance.

The problem probably developed during the summer months when the lake water temperature was comparatively high. Since lake water is used in the cooling of the containment atmosphere, this resulted in a higher ambient temperature. As vapor from the atmosphere condensed on the cold door frame, the resultant water seeped into the insulation, which became soaked and subsequently froze. To forestall future problems, the floor cooling system controls were adjusted to increase the floor temperature to about 15°F; the soaked insulation was replaced; the inleepage areas were caulked; rubber insulating strips were added to the lower inlet-door metal frames; and periodic inspections of the doors for ice was instituted.^{22,23}

CONCLUSION

We can all profit by the experiences of others as long as there is free communication among the interested parties. This compilation was

prepared with this objective in mind, and the intent is to provide some guidance as to where additional effort can be expended to minimize the occurrence and the recurrence of incidents. In this way, the safety, reliability, and availability of nuclear facilities should be improved.

REFERENCES

1. E. N. Cramer and W. R. Casto, *Safety-Related Occurrences in Nuclear Facilities as Reported in 1967 and 1968*, ORNL/NSIC-69 (July 1970).
2. R. L. Scott and W. R. Casto, *Safety-Related Occurrences in Nuclear Facilities as Reported in 1969*, ORNL/NSIC-87 (August 1971).
3. R. L. Scott, *Safety-Related Occurrences in Nuclear Facilities as Reported in 1970*, ORNL/NSIC-91 (December 1971).
4. R. L. Scott and R. B. Gallaher, *Safety-Related Occurrences in Nuclear Facilities as Reported in 1971*, ORNL/NSIC-106 (September 1972).
5. R. L. Scott and R. B. Gallaher, *Safety-Related Occurrences in Nuclear Facilities as Reported in 1972*, ORNL/NSIC-109 (December 1973).
6. R. L. Scott and R. B. Gallaher, *Annotated Bibliography of Safety-Related Occurrences in Nuclear Power Plants as Reported in 1973*, ORNL/NSIC-114 (November 1974).
7. R. L. Scott and R. B. Gallaher, *Annotated Bibliography of Safety-Related Occurrences in Nuclear Power Plants as Reported in 1974*, ORNL/NSIC-122 (May 1975).
8. *Abnormal Reactor Operating Experiences*, ORNL/NSIC-17 (August 1966).
9. *Abnormal Reactor Operating Experiences 1966-1968*, ORNL/NSIC-64 (October 1969).
10. *Abnormal Reactor Operating Experiences 1969-1971*, ORNL/NSIC-103 (May 1972).
11. *Reactor Operating Experiences 1972-1974*, ORNL/NSIC-121 (December 1975).
12. "Reporting of Operating Information," *AEC Regulatory Guide No. 1.16*, USAEC Directorate of Regulatory Standards, Oct. 27, 1972.
13. 10 CFR 50.55(e), "Conditions of Construction Permits," *Federal Register* 37(62), 6460 (Thursday, Mar. 30, 1972).
14. "Reactor Coolant Pump Seal Water System Fails," *Nucl. Safety* 16(5), 626 (September-October 1975).
15. Letter from E. F. Utley, Carolina Power & Light Co., to Norman C. Moseley, U.S. Nuclear Regulatory Commission, Region 2, Docket 50-261, May 12, 1975, available at NRC Public Document Room.

16. Letter from E. F. Utley, Carolina Power & Light Co., to Norman C. Moseley, U.S. Nuclear Regulatory Commission, Region 2, Docket 50-261, June 13, 1975, available at NRC Public Document Room.
17. "Control System Causes Transients," Nucl. Safety 17(1), 106 (January-February 1976).
18. Letter from W. D. Parker, Jr., Vice-President, Steam Production, Duke Power Company, to N. C. Moseley, Director, Region II of the Office of Inspection and Enforcement, Nuclear Regulatory Commission, Docket 50-287, June 27, 1975, enclosing Abnormal Occurrence Report No. 50-287/75-7, available at NRC Public Document Room.
19. Letter from W. D. Parker, Jr., Vice-President, Duke Power Company, to N. C. Moseley, Director, Region II of the Office of Inspection and Enforcement, Nuclear Regulatory Commission, Docket 50-287, Aug. 8, 1975, available at NRC Public Document Room.
20. "Noble-Gas Release," Nucl. Safety 17(1), 107 (January-February 1976).
21. Letter from J. S. Bitel, Superintendent, Zion Station, Commonwealth Edison Company, to J. G. Keppler, Regional Director of Regulatory Operations, Docket 50-285, Aug. 29, 1975, enclosing Abnormal Occurrence Report 50-287/75-20, available at NRC Public Document Room.
22. "Ice Condenser Doors Freeze," Nucl. Safety 17(2) (March-April 1976).
23. Letter from R. W. Jurgensen, Plant Manager, Donald C. Cook Nuclear Plant, to J. G. Keppler, Regional Director, Nuclear Regulatory Commission, Docket No. 50-315, November 17, 1975, enclosing Abnormal Occurrence Report No. 50-315/75-69, available at NRC Public Document Room.

BIBLIOGRAPHY

PRESSURIZED WATER REACTORS

099113
PINHOLE LEAK IN REACTOR COOLANT PUMP SEAL VENT VALVE AT ARKANSAS NUCLEAR 1
ARKANSAS POWER & LIGHT COMPANY
5 PAGES, LETTER WITH AD REPORT 75/14 TO DIRECTORATE OF LICENSING (AEC), JANUARY 30, 1975, Docket 50-313, TYPE--
PWR, NRC--BWR, AE--BECHTEL

CAUSE - INSTALLATION ERROR. DURING A WALK THROUGH INSPECTION WHILE THE REACTOR WAS AT COLD
STARTUP, A PINHOLE LEAK WAS OBSERVED ON THE UPSTREAM PIPE TO VALVE WELD ON THE VENT VALVE FOR
REACTOR COOLANT PUMP SEAL. THE WELD WAS GRIND OUT AND REWELDED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

FAILURE, PIPE & WELDS & REACTOR STARTUP EXPERIENCE & SEAL & FAILURE, INSTALLATION ERROR & MAIN COOLING SYSTEM
& LEAK & ARKANSAS NUCLEAR 1 (PWR) & PUMPS & PIPES AND PIPE FITTINGS

093575
FISH IMPINGEMENT ON INTAKE SCREENS AT ARKANSAS NUCLEAR 1
ARKANSAS POWER & LIGHT COMPANY
5 PAGES, LETTER WITH ENVIRONMENTAL REPORT 75/1 TO OFFICE OF NUCLEAR REACTOR REGULATION, JANUARY 22, 1975,
DOCKET 50-313, TYPE--PWR, NRC--BWR, AE--BECHTEL

CAUSE - NATURAL DIE OFF OF SHAD. FISH IMPINGEMENT ON THE INTAKE SCREENS EXCEEDED THE 3000 LB.
LIMIT FOR A 24 HOUR PERIOD. ABOUT 3349 LBS WERE COLLECTED, 99.98 OF WHICH WERE SHAD. THE
APPARENT CAUSE WAS DUE TO NATURAL DIE OFF OF THREADFIN SHAD DURING THE WINTER SEASON.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

FILTER, SCREEN & REACTOR STARTUP EXPERIENCE & ARKANSAS NUCLEAR 1 (PWR) & ANIMAL, FISH & MORTALITY & INTAKE

093573
FISH IMPINGEMENT ON INTAKE SCREENS AT ARKANSAS NUCLEAR 1
ARKANSAS POWER & LIGHT COMPANY
5 PAGES, LETTER WITH ENVIRONMENTAL REPORT 75/2 TO OFFICE OF NUCLEAR REACTOR REGULATION, JANUARY 23, 1975,
DOCKET 50-313, TYPE--PWR, NRC--BWR, AE--BECHTEL

CAUSE - NATURAL DIE OFF OF SHAD. FISH IMPINGEMENT ON THE INTAKE SCREENS EXCEEDED THE 3000 LB
LIMIT FOR A 24 HOUR PERIOD. ABOUT 5510 LBS WERE COLLECTED, 99.98 OF WHICH WERE SHAD. THE
APPARENT CAUSE WAS DUE TO NATURAL DIE OFF OF THREADFIN SHAD DURING THE WINTER SEASON.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

FILTER, SCREEN & REACTOR STARTUP EXPERIENCE & ARKANSAS NUCLEAR 1 (PWR) & ANIMAL, FISH & MORTALITY & INTAKE

093574
FISH IMPINGEMENT ON INTAKE SCREENS AT ARKANSAS NUCLEAR 1
ARKANSAS POWER & LIGHT COMPANY
5 PAGES, LETTER WITH ENVIRONMENTAL REPORT 75/3 TO OFFICE OF NUCLEAR REACTOR REGULATION, JANUARY 23, 1975,
DOCKET 50-313, TYPE--PWR, NRC--BWR, AE--BECHTEL

CAUSE - NATURAL DIE OFF OF SHAD. FISH IMPINGEMENT ON THE INTAKE SCREENS EXCEEDED THE 3000 LB
LIMIT FOR A 24 HOUR PERIOD. ABOUT 6790 LBS WERE COLLECTED, 99.98 OF WHICH WERE SHAD. THE
APPARENT CAUSE WAS DUE TO NATURAL DIE OFF OF THREADFIN SHAD DURING THE WINTER SEASON.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

FILTER, SCREEN & REACTOR STARTUP EXPERIENCE & ARKANSAS NUCLEAR 1 (PWR) & ANIMAL, FISH & MORTALITY & INTAKE

093576
PRIMARY MAKEUP PUMP DRAIN LINE LEAKS AT ARKANSAS NUCLEAR 1
ARKANSAS POWER & LIGHT COMPANY
4 PAGES, LETTER WITH AD REPORT 75/2 TO NRC OFFICE OF NUCLEAR REACTOR REGULATIONS, JANUARY 30, 1975, DOCKET 50-
313, TYPE--PWR, NRC--BWR, AE--BECHTEL

CAUSE - IMPROPER FITUP. WHILE THE REACTOR WAS AT 98.58 PWR, A LEAK WAS FOUND ON A PRIMARY
MAKEUP PUMP DRAIN LINE WHERE THE 1/2 INCH LINE IS THREADED INTO THE CASING DISCHARGE
NOZZLE. THE CASING EXTENDED AROUND 3/4 OF THE PIPE CIRCUMFERENCE. THE APPARENT CAUSE OF FAILURE
WAS DUE TO IMPROPER FITUP OF THE THREADED SECTION OF THE DRAIN LINE. A NEW DRAIN LINE PIPE
SECTION WAS INSTALLED. A VIBRATION ANALYSIS WAS INITIATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

FAILURE, PIPE & FAILURE, INSTALLATION ERROR & LEAK & ARKANSAS NUCLEAR 1 (PWR) & FEEDWATER & PIPES AND PIPE
FITTINGS

BLANK PAGE

093577

SERVICE WATER VALVES FAIL TO OPEN AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER & LIGHT COMPANY
 7 PAGES, LETTER WITH AD REPORT 75/1 TO NRC OFFICE OF NUCLEAR REACTOR REGULATIONS, JANUARY 30, 1975, DUCRET 50-313, TYPE--PWR, NRC--BOW, AE--BECHTEL

CAUSE - LEAK OF LUBRICATION. DURING TESTING OF THE REACTOR BUILDING COILING UNITS WITH THE REACTOR AT 90.58 PWSH, A SERVICE WATER INLET VALVE FAILED TO OPEN AND AN OUTLET VALVE FAILED TO REACH FULL OPEN POSITION. THE INLET VALVE FAILURE APPEARED TO BE FROM LACK OF LUBRICATION ON THE PNEUMATIC PISTON OPERATION. CAUSE OF FAILURE OF THE OUTLET VALVE FAILURE IS UNKNOWN. BOTH VALVES WERE LUBRICATED. THE INLET VALVE OPERATED SATISFACTORILY. THE OUTLET VALVE WAS STILL BINDING. IT WILL BE REPAIRED AT THE NEXT SHUTDOWN. IT WAS MANUALLY OPENED AND LOCKED IN POSITION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTAINMENT AIR COOLING + TEST. SYSTEM OPERABILITY + FAILURE, MAINTENANCE ERROR + AUXILIARY CIRCUIT + LUBRICATION + ARKANSAS NUCLEAR 1 (PWR) + VALVES

093495

FISH IMPINGED ON INTAKE SCREEN AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER AND LIGHT COMPANY
 5 PAGES, LETTER WITH ENVIRONMENTAL REPORT 75/6 TO NRC OFFICE OF NUCLEAR REACTOR REGULATIONS, JANUARY 31, 1975, DUCRET 50-313, TYPE--PWR, NRC--BOW, AE--BECHTEL

CAUSE - NATURAL DIE OFF. DURING A 24-HR PERIOD, 3331 POUNDS OF FISH WERE IMPINGED ON THE INTAKE SCREENS. THIS EXCEEDS THE 3000 LB/DAY LIMIT. SHAD MADE UP 99.58 OF THE TOTAL WEIGHT OF FISH. THE APPARENT CAUSE WAS A NATURAL DIE OFF OF THREADFIN SHAD DURING THE WINTER SEASON.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FILTER, SCREEN + ARKANSAS NUCLEAR 1 (PWR) + ANIMAL, FISH + MORTALITY + INTAKE + CONDENSED COOLING SYSTEM

093396

ADDITIONAL INFORMATION ON REACTOR BUILDING SPRAY PIPING AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER AND LIGHT COMPANY
 45 PAGES, LETTER WITH AD REPORT 74/71A TO OFFICE OF NUCLEAR REACTOR REGULATIONS, FEBRUARY 9, 1975, DUCRET 50-313, TYPE--PWR, NRC--BOW, AE--BECHTEL

CAUSE - UNKNOWN. ON NOV. 7, 1974, A LEAK WAS FOUND IN A REACTOR BUILDING SPRAY SYSTEM PIPE WHILE THE REACTOR WAS BEING SHUT DOWN. A SECOND LEAK OCCURRED ADJACENT TO THE NEW WELD MADE DURING THE REPAIR. THREE OTHER LEAKS HAVE BEEN FOUND. INTERGRANULAR CRACKING ROUGHLY PARALLEL TO CIRCUMFERENTIAL BUTT WELDS WERE FOUND IN THE CONTINUOUS SENSITIZED REGION OF THE HEAT AFFECTED ZONE. CRACKING BEGAN ON THE INSIDE SURFACE ABOUT 1/4 INCH FROM THE ROOT OF THE WELD. THE MICROSTRUCTURE OF THE PIPE SHOWED CARBIDE PRECIPITATION. BOTH SURFACES EXHIBITED A CONTINUOUS NETWORK OF INTERGRANULAR ATTACK.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTAINMENT SPRAY + FAILURE, PIPE + WELDS + STEEL, STAINLESS + PLAN + EXAMINATION + HEAT TREATMENT + ARKANSAS NUCLEAR 1 (PWR) + PIPES AND PIPE FITTINGS

090714

FISH IMPINGED ON INTAKE SCREENS AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER & LIGHT COMPANY
 11 PAGES, LETTER WITH ENVIRONMENTAL REPORT 75/7 TO NRC OFFICE OF NUCLEAR REACTOR REGULATIONS, FEBRUARY 10, 1975, DUCRET 50-313, TYPE--PWR, NRC--BOW, AE--BECHTEL

CAUSE - NATURAL WINTER SEASON DIE OFF. DURING 3 24-HOUR SAMPLING PERIODS, THE QUANTITY OF FISH COLLECTED ON THE INTAKE SCREENS EXCEEDED THE 3000 POUND LIMIT. THE WEIGHTS COLLECTED WERE 4050, 9100, AND 10,005 POUNDS. SHAD MADE UP 99.98 OF THE TOTAL WEIGHT. THE APPARENT CAUSE WAS DUE TO A NATURAL DIE OFF OF THREADFIN SHAD DURING THE WINTER SEASON.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FILTER, SCREEN + ARKANSAS NUCLEAR 1 (PWR) + ANIMAL, FISH + MORTALITY + INTAKE + CONDENSED COOLING SYSTEM

100272

FISH KILL ON INTAKE SCREENS EXCEEDS LIMIT AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER & LIGHT COMPANY
 8 PAGES, LETTER WITH ENVIRONMENTAL REPORTS 75/10/19 TO NRC OFFICE OF NUCLEAR REACTOR REGULATIONS, FEBRUARY 25, 1975, DUCRET 50-313, TYPE--PWR, NRC--BOW, AE--BECHTEL

CAUSE - NATURAL DIE OFF OF SHAD. DURING 2 24-HOUR SAMPLE PERIODS, THE FISH COLLECTED ON THE INTAKE SCREENS EXCEEDED THE 3000 LB/DAY LIMIT. ON ONE DAY 4100 LBS WERE COLLECTED AND 5475 LBS

100074 - RECONSTRUCTION

On the subject of the total design modification, the design modification team has approved design and construction of the total design modification for the design team.

Availability - The Public Document Room, 1717 - Street, Washington, D. C. 20545 (100 CENTS/PAGE -- minimum charge \$2.00)

Filter, Screen - ammonia; nuclear; steam; oxygen; film; reactivity; system - ammonia cooling system

100075

Design modification of the total design modification at ammonia nuclear

ammonia nuclear design team

12 pages. Letter to the design modification team, 1717 - Street, Washington, D. C. 20545 (100 CENTS/PAGE -- minimum charge \$2.00)

Design - ammonia; design of the total design modification. The design modification team has approved design and construction of the total design modification for the design team. The design modification team has approved design and construction of the total design modification for the design team.

Availability - The Public Document Room, 1717 - Street, Washington, D. C. 20545 (100 CENTS/PAGE -- minimum charge \$2.00)

Filter, Screen - ammonia; nuclear; steam; oxygen; film; reactivity; system - ammonia cooling system

100076

Design modification of the total design modification at ammonia nuclear

ammonia nuclear design team

12 pages. Letter to the design modification team, 1717 - Street, Washington, D. C. 20545 (100 CENTS/PAGE -- minimum charge \$2.00)

Design - ammonia; design of the total design modification. The design modification team has approved design and construction of the total design modification for the design team. The design modification team has approved design and construction of the total design modification for the design team.

Availability - The Public Document Room, 1717 - Street, Washington, D. C. 20545 (100 CENTS/PAGE -- minimum charge \$2.00)

Filter, Screen - ammonia; nuclear; steam; oxygen; film; reactivity; system - ammonia cooling system

100077

Design modification of the total design modification at ammonia nuclear

ammonia nuclear design team

12 pages. Letter to the design modification team, 1717 - Street, Washington, D. C. 20545 (100 CENTS/PAGE -- minimum charge \$2.00)

Design - ammonia; design of the total design modification. The design modification team has approved design and construction of the total design modification for the design team. The design modification team has approved design and construction of the total design modification for the design team.

Availability - The Public Document Room, 1717 - Street, Washington, D. C. 20545 (100 CENTS/PAGE -- minimum charge \$2.00)

Filter, Screen - ammonia; nuclear; steam; oxygen; film; reactivity; system - ammonia cooling system

100078

Design modification of the total design modification at ammonia nuclear

ammonia nuclear design team

12 pages. Letter to the design modification team, 1717 - Street, Washington, D. C. 20545 (100 CENTS/PAGE -- minimum charge \$2.00)

Design - ammonia; design of the total design modification. The design modification team has approved design and construction of the total design modification for the design team. The design modification team has approved design and construction of the total design modification for the design team.

Availability - The Public Document Room, 1717 - Street, Washington, D. C. 20545 (100 CENTS/PAGE -- minimum charge \$2.00)

Ammonia; nuclear; steam; oxygen; film; reactivity; system - ammonia cooling system - ammonia

100079

Design modification of the total design modification at ammonia nuclear

ammonia nuclear design team

12 pages. Letter to the design modification team, 1717 - Street, Washington, D. C. 20545 (100 CENTS/PAGE -- minimum charge \$2.00)

103120 PLUMITIME-0

CAUSE - NEUTRALIZING TANK RELEASE. SAMPLES TAKEN IN THE IN TAKE AND DISCHARGE CANALS ON AN
 APPROXIMATE INDICATE CHEMICAL CONCENTRATIONS OF 4 PARAMETERS INCREASED ACROSS THE PLANT IN EXCESS
 OF LIMITS. THE NEUTRALIZING TANK WAS BEING DRAINED WHEN THE SAMPLES WERE TAKEN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) • CONCENTRATION • EFFLUENT • WASTE DISPOSAL • WATER QUALITY

103120

CHEMICAL CONCENTRATION IN EFFLUENT EXCEEDS LIMITS AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT COMPANY

5 PAGES, LETTER WITH ATTACHMENT, REPORT 75-29 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, MAY 27, 1975, DOCKET 50-313, TYPE--PWR, NRC--060, AR--DECHTEL

CAUSE - NEUTRALIZING TANK RELEASE. SAMPLES TAKEN FROM THE INTAKE AND DISCHARGE CANALS INDICATE
 THAT CHEMICAL CONCENTRATIONS OF 3 PARAMETERS INCREASED ACROSS THE PLANT IN EXCESS OF ETS LIMITS.
 THE NEUTRALIZING TANK, WHICH CONTAINS WATER IMPURITIES REMAINING AFTER REGENERATING CONDENSATE
 DEMINERALIZERS AND PLANT MAKEUP WATER DEMINERALIZERS, WAS BEING DRAINED WHEN SAMPLES WERE TAKEN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) • CONCENTRATION • EFFLUENT • WASTE DISPOSAL • WATER QUALITY

103000

CHEMICAL CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT CO., LITTLE ROCK

5 PAGES, LETTER WITH REPORT TO NRC OFFICE OF REACTOR REGULATION, JUNE 3, 1975, DOCKET 50-313, TYPE--PWR, NRC--
 060, AR--DECHTEL

CAUSE - UNKNOWN. SAMPLES TAKEN FROM THE INTAKE AND DISCHARGE CANALS AND AT POINT 23 FOR ONE DAY
 INDICATE THAT THE INCREASE ACROSS THE PLANT FOR TURBIDITY AND SULFATE EXCEEDED ETS LIMITS. THE
 REACTOR WAS OPERATING AT 94% POWER. NO CHEMICAL DISCHARGES WERE MADE. THE CAUSE WAS BEYOND THE
 CONTROL OF THE PLANTS. THE ENVIRONMENTAL TECH SPECS ARE BEING REVIEWED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) • CONDENSER COOLING SYSTEM • CONCENTRATION • EFFLUENT • SAMPLING • MONITORING
 PROGRAM, ENVIRONMENTAL

103006

CHEMICAL CONCENTRATION IN EFFLUENT EXCEEDS LIMITS TWICE AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT COMPANY

5 PAGES, LETTER WITH ATTACHMENT TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JUNE 9, 1975, DOCKET 50-313, TYPE--
 PWR, NRC--060, AR--DECHTEL

CAUSE - DELAYED PLANT CONTROL. ON TWO OCCASIONS SAMPLES TAKEN FROM THE DISCHARGE CANAL INDICATED
 INCREASES OF CHEMICAL CONCENTRATIONS ACROSS THE PLANT IN EXCESS OF LIMITS. ONCE CHLORINE
 INCREASED 110 MG/L COMPARED TO A 25 MG/L LIMIT. NO PLANT DISCHARGE OCCURRED DURING THIS PERIOD.
 ANOTHER TIME THE AMMONIA CONCENTRATION INCREASE EXCEEDED THE 0.05 MG/L LIMIT WHILE THE
 NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE CANAL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) • EFFLUENT • CONCENTRATION • CHLORINE • CONDENSER COOLING SYSTEM • DISCHARGE •
 WASTE DISPOSAL • MONITORING PROGRAM, ENVIRONMENTAL

103052

CHLORINE CONCENTRATION INCREASE EXCEEDS LIMITS AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT COMPANY

4 PAGES, LETTER WITH ATTACHMENT TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JUNE 11, 1975, DOCKET 50-313,
 TYPE--PWR, NRC--060, AR--DECHTEL

CAUSE - CHEMICAL DISCHARGE. WHILE OPERATING AT 93% POWER, SAMPLES TAKEN FROM POINT 20 AND THE
 DISCHARGE CANAL INDICATED THAT THE CHLORINE CONCENTRATION IN THE DISCHARGE WAS 130 MG/L HIGHER
 THAN IN THE INTAKE. THE ETS LIMIT IS 25 MG/L. SAMPLES WERE TAKEN WHILE CHEMICAL DISCHARGES WERE
 BEING MADE. THE ETS LIMITS ARE BEING REVIEWED TO DETERMINE THE BASIS FOR THE LIMITS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) • CHLORINE • CONCENTRATION • EFFLUENT • CONDENSER COOLING SYSTEM • DISCHARGE •
 WASTE DISPOSAL

103655
CHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED LIMIT THREE AT ARKANSAS NUCLEAR 1
ARKANSAS POWER & LIGHT CO.
7 PAGES, LETTER WITH ATTACHMENT TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JUNE 20, 1975, DOCKET 50-313,
TYPE--PWR, MFG--BGM, AE--DECHTEL

CAUSE - WASTE DISPOSAL. THE CHEMICAL CONCENTRATION OF SEVERAL PARAMETERS INCREASED ACROSS THE
PLANT IN EXCESS OF ETS LIMITS ON 2 DAYS. BOTH TIMES THE NEUTRALIZING TANK WAS DRAINING INTO THE
DISCHARGE CANAL. THE REACTOR WAS AT 95% POWER. ONCE THE 140% CONCENTRATION WAS 0.432 MG/L. THE
LIMIT IS 0.3. THE OTHER TIME 6 PARAMETERS INCREASED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) + CONCENTRATION + EFFLUENT + CONDENSER COOLING SYSTEM + DISCHARGE + MONITORING
PROGRAM, ENVIRONMENTAL + WASTE DISPOSAL

103658
AMMONIA CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT ARKANSAS NUCLEAR 1
ARKANSAS POWER & LIGHT CO.
5 PAGES, LETTER WITH ATTACHMENT TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JUNE 26, 1975, DOCKET 50-313,
TYPE--PWR, MFG--BGM, AE--DECHTEL

CAUSE - WASTE DISPOSAL. THE AMMONIA CONCENTRATION IN THE CONDENSER CIRCULATING WATER INCREASED
0.11 MG/L ACROSS THE PLANT. THE ETS LIMIT IS 0.05 MG/L. THE PLANT WAS AT 96% POWER. THE
NEUTRALIZING TANK WAS DRAINING TO THE DISCHARGE FLUME DURING SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) + CONCENTRATION + EFFLUENT + CONDENSER COOLING SYSTEM + DISCHARGE + MONITORING
PROGRAM, ENVIRONMENTAL + WASTE DISPOSAL

103689
REACTOR BUILDING SPRAY SYSTEM MAY NOT DRAM DOWN UNIFORMLY AT ARKANSAS NUCLEAR 1
ARKANSAS POWER & LIGHT COMPANY
5 PAGES, LETTER WITH UER 75-2 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JUNE 25, 1975, DOCKET 50-313, TYPE--
PWR, MFG--BGM, AE--DECHTEL

CAUSE - DESIGN DEFICIENCY. ANALYSIS BY AEP OF THE HYDRAULIC PERFORMANCE OF THE RBS UNDER ACCIDENT
CONDITIONS REVEALS THAT THE SODIUM THIOSULFATE AND SODIUM HYDROXIDE TANKS MAY NOT DRAW DOWN
UNIFORMLY WITH THE BOILED WATER STORAGE TANK. THIS ANALYSIS IS SENSITIVE TO THE AS-BUILT
PIPING CONFIGURATION. THE UTILITY IS RE-EVALUATING THE HYDRAULIC STUDY. PAINTS ARE BEING
CHECKED FOR COMPATIBILITY WITH PH RANGE OF 11 TO 12 FOR SHORT PERIODS OF TIME (45 MINUTES).

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) + CONTAINMENT SPRAY + ADDITIVE + FLOW, MIXING + FAILURE, DESIGN ERROR + SYSTEM
OPERABILITY IN ACCIDENT + HYDRAULIC ANALYSIS

103676
CHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS LIMITS AT ARKANSAS NUCLEAR 1
ARKANSAS POWER & LIGHT COMPANY
7 PAGES, LETTER WITH REPORTS NO. 75-37/38 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JULY 1, 1975, DOCKET 50-
313, TYPE--PWR, MFG--BGM, AE--DECHTEL

CAUSE - DRAINING NEUTRALIZING TANK. ON 2 DAYS, SAMPLES TAKEN FROM THE DISCHARGE CANAL AND AT
POINT 20 INDICATED THAT CHLORIDE CONCENTRATION IN THE DISCHARGE CANAL WAS HIGHER THAN THE ETS
LIMIT BY 102 AND 65 MG/L, RESPECTIVELY. THE ETS LIMIT IS 25 MG/L. THE NEUTRALIZING TANK WAS
BEING DRAINED INTO THE DISCHARGE FLUME WHEN SAMPLES WERE TAKEN ON BOTH DAYS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) + CHLORIDE + CONCENTRATION + EFFLUENT + CONDENSER COOLING SYSTEM + DISCHARGE +
WASTE DISPOSAL

104089
WELD IN PRESSURE SENSING LINE FROM RC PUMP SEAL CAVITY LEAKS AT ARKANSAS NUCLEAR 1
ARKANSAS POWER & LIGHT CO.
5 PAGES, LETTER WITH AOR 75-3 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JULY 3, 1975, DOCKET 50-313, TYPE--
PWR, MFG--BGM, AE--DECHTEL

CAUSE - UNKNOWN. WHILE AT HOT SHUTDOWN, A LEAK WAS DISCOVERED ON THE UPSTREAM SIDE OF THE SECOND
ISOLATION VALVE TO OUTER SEAL CAVITY PRESSURE TRANSMITTER ON REACTOR COOLANT PUMP B. LEAKAGE WAS
LESS THAN 0.2 GPM AND WAS ISOLABLE. THE OLD VALVE WAS REMOVED AND REPLACED WITH A NEW ONE. THE
CAUSE HAS NOT YET BEEN DETERMINED.

100009 PLUTONIUM
 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.000

ARKANSAS NUCLEAR 1 (PWR) • PVALVES • CONTAINMENT ISOLATION • SENSORS, PRESSURE • PLEAK • ALARMS, EQUIPMENT •
 PLAN

100041
 CHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER & LIGHT CO.
 3 PAGES, LETTER WITH REPORT 75-35 TO U.S. NRC, REGION 4, JULY 11, 1975, DOCKET 50-313, TYPE--PWR, NRC--BGM, AE--
 DECMTEL

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE DISCHARGE CANAL AND AT POINT 20 INDICATE THAT
 CHLORIDE CONCENTRATION IN THE DISCHARGE CANAL WAS HIGHER THAN THAT AT POINT 20 AT 27 MG/L. ETS
 LIMIT IS 25 MG/L. THE REACTOR WAS OPERATING AT 946 POWER AND THE NEUTRALIZING TANK WAS DRAINING
 IN THE DISCHARGE FLUME.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.000

ARKANSAS NUCLEAR 1 (PWR) • CHLORIDE • CONCENTRATION • EFFLUENT • CONDENSER COOLING SYSTEM • WATER QUALITY •
 WASTE DISPOSAL

100196
 CHLORIDE CONCENTRATION EFFLUENT EXCEEDS LIMIT AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER & LIGHT COMPANY
 3 PAGES, LETTER WITH REPORT TO U.S. NRC, REGION 4, JULY 11, 1975, DOCKET 50-313, TYPE--PWR, NRC--BGM, AE--
 DECMTEL

CAUSE - WASTE DISPOSAL. SAMPLES INDICATED THAT THE CHLORIDE CONCENTRATION IN THE DISCHARGE CANAL
 WAS 28 MG/L HIGHER THAN AT POINT 20. ETS LIMIT IS 25 MG/L. THE NEUTRALIZING TANK WAS DRAINING
 INTO THE DISCHARGE FLUME AT THE TIME OF SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.000

ARKANSAS NUCLEAR 1 (PWR) • WATER QUALITY • EFFLUENT • WASTE DISPOSAL • CONDENSER COOLING SYSTEM • CHLORIDE •
 CONCENTRATION

100296
 ADDITIONAL INFORMATION ON SERVICE WATER VALVE FAILURES AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER & LIGHT COMPANY
 3 PAGES, LETTER WITH AFR 75-1A TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JULY 16, 1975, DOCKET 50-313, TYPE--
 PWR, NRC--BGM, AE--DECMTEL

CAUSE - GALLING OF STEM IN BUSHING. AS REPORTED EARLIER A REACTOR BUILDING COOLING JMT SERVICE
 WATER OUTLET VALVE DID NOT REACH FULL OPEN POSITION DURING TESTING. THE CAUSE HAD BEEN
 DETERMINED TO BE GALLING OF THE METAL BETWEEN THE VALVE STEM AND ITS UPPER BUSHING. THE STEM
 WAS POLISHED TO REMOVE SCRATCHES AND UPSET METAL ON ITS SURFACE AND THE BUSHING WAS MORE
 SMOOTH AND LUBRICATED. THE STAINLESS STEEL STEM WITH A STAINLESS STEEL BUSHING ON EACH SIDE OF
 THE BUTTERFLY HAD NOT PREVIOUSLY BEEN LUBRICATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.000

ARKANSAS NUCLEAR 1 (PWR) • PVALVES • BEARING • AUXILIARY COOLING • FAILURE, FABRICATION ERROR • LUBRICATION

100021
 CHEMICAL CONCENTRATION IN EXCESS OF LIMITS AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER & LIGHT COMPANY, LITTLE ROCK
 6 PGS, LTR W/RT 75-41 TO NRC, REGION 4, JULY 29, 1975, DOCKET 50-313, TYPE--PWR, NRC--BGM, AE--DECMTEL

CAUSE - WASTE DISPOSAL. PH AND AMMONIA CONCENTRATION IN THE CIRCULATING WATER INCREASED IN EXCESS
 OF ETS LIMITS. THE NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE FLUME AT THE TIME OF
 SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.000

ARKANSAS NUCLEAR 1 (PWR) • CONCENTRATION • CONDENSER COOLING SYSTEM • WASTE DISPOSAL • WASTE DISPOSAL,
 LIQUID • EFFLUENT

100977
 SODIUM NITRATE CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER & LIGHT COMPANY, LITTLE ROCK
 3 PGS, LTR W/RT 75-42 TO NRC OFFICE OF ECE, REGION 4, AUG. 4, 1975, DOCKET 50-313, TYPE--PWR, NRC--BGM, AE--

104977 ARKANSAS
SECRET

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE INLET AND DISCHARGE CANALS INDICATED THAT THE SODIUM NITRATE CONCENTRATION INCREASED ACROSS THE PLANT. ITS LIMIT IS 9000 PPM. THE NEUTRALIZING TANK WAS BEING DRAINED AT THE TIME OF THE OCCURRENCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) • CONCENTRATION • EFFLUENT • CONDENSER COOLING SYSTEM • WASTE DISPOSAL • WASTE DISPOSAL, LIQUID

105200
CHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED LIMITS AT ARKANSAS NUCLEAR 1
ARKANSAS POWER & LIGHT COMPANY, LITTLE ROCK
3 PGS. LTR W/REPLY TO NRC, REGION 4, AUG. 12, 1975, DOCKET 50-313, TYPE--PWR, WSG--BEM, AE--BECHTEL

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE INLET AND DISCHARGE CANALS INDICATED THAT THE CHEMICAL CONCENTRATION OF SODIUM NITRATE, AMMONIA, AND CHLORIDE IN THE CONDENSER COOLING WATER INCREASED ACROSS THE PLANT IN EXCESS OF ETS LIMITS. THE NEUTRALIZING TANK WAS BEING DRAINED INTO THE DISCHARGE PLUME WHEN SAMPLES WERE TAKEN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) • CONCENTRATION • EFFLUENT • CONDENSER COOLING SYSTEM • WASTE DISPOSAL • WASTE DISPOSAL, LIQUID

105516
CHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED LIMITS AT ARKANSAS NUCLEAR 1
ARKANSAS POWER & LIGHT COMPANY, LITTLE ROCK
3 PGS. LTR W/REPLY TO NRC, REGION 4, AUG. 12, 1975, DOCKET 50-313, TYPE--PWR, WSG--BEM, AE--BECHTEL

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE INLET AND DISCHARGE CANALS INDICATED THAT THE CONCENTRATION OF SODIUM NITRATE, AMMONIA, AND CHLORIDE IN THE CONDENSER COOLING WATER INCREASED ACROSS THE PLANT IN EXCESS OF ETS LIMITS. THE NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE CANAL DURING SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) • CONCENTRATION • CONDENSER COOLING SYSTEM • EFFLUENT • WASTE DISPOSAL

105206
CHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED LIMITS AT ARKANSAS NUCLEAR 1
ARKANSAS POWER & LIGHT COMPANY, LITTLE ROCK
4 PGS. LTR W/REPLY TO NRC, REGION 4, AUG. 18, 1975, DOCKET 50-313, TYPE--PWR, WSG--BEM, AE--BECHTEL

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE INLET AND DISCHARGE CANALS INDICATE THAT THE CONCENTRATION OF SODIUM NITRATE, TURBIDITY, AND AMMONIA INCREASED ACROSS THE PLANT IN EXCESS OF ETS LIMITS. THE NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE PLUME AT THE TIME OF SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) • CONCENTRATION • EFFLUENT • CONDENSER COOLING SYSTEM • WASTE DISPOSAL • WASTE DISPOSAL, LIQUID

105207
CONCENTRATION OF AMMONIA IN EFFLUENT EXCEEDS LIMIT AT ARKANSAS NUCLEAR 1
ARKANSAS POWER & LIGHT COMPANY, LITTLE ROCK
4 PGS. LTR W/REPLY TO NRC, REGION 4, AUG. 21, 1975, DOCKET 50-313, TYPE--PWR, WSG--BEM, AE--BECHTEL

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE INLET AND DISCHARGE CANALS INDICATED THAT THE AMMONIA CONCENTRATION INCREASED ACROSS THE PLANT IN EXCESS OF ETS LIMITS. THE NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE PLUME AT THE TIME OF SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) • CONCENTRATION • EFFLUENT • CONDENSER COOLING SYSTEM • WASTE DISPOSAL • WASTE DISPOSAL, LIQUID

105518

105510 PLANTINTEGRITY

AMMONIA CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT ARKANSAS NUCLEAR 1
ARKANSAS POWER & LIGHT COMPANY, LITTLE ROCK

PGS: LTR WASH 75-24 TO NRC OFFICE OF I & E, REGION IV, AUG. 29, 1975, DOCKET 50-313, TYPE--PUR, NRC--BGM, AE--BECHTEL

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE INTAKE AND DISCHARGE CANALS INDICATED THAT THE AMMONIA CONCENTRATION IN EFFLUENT INCREASED ACROSS THE PLANT IN EXCESS OF ITS LIMITS. THE NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE CANAL DURING SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) • AMMONIA CONCENTRATION • EFFLUENT • CONDENSED COOLING SYSTEM • WASTE DISPOSAL

105520

PIPING REPORT ON REACTOR BUILDING SPRAY SYSTEM PIPE CRACKS AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT COMPANY, LITTLE ROCK

PGS: LTR WASH 75-24 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, AUG. 29, 1975, DOCKET 50-313, TYPE--PUR, NRC--BGM, AE--BECHTEL

CAUSE - STRESS-ASSISTED CORROSION CRACKING. SECTIONS AND SAMPLES OF THE FAILED SCHEDULE 10 STAINLESS STEEL PIPING USED IN THE REACTOR BUILDING SPRAY SYSTEM AND FROM OTHER HEAT EXCHANGERS OF SIMILAR DESIGN WERE ANALYZED. FAILURE WAS INTERGRANULAR STRESS-ASSISTED CORROSION CRACKING CAUSED BY A NUMBER OF CORROSION FACTORS. ALL LEAKS OCCURRED IN PIPE FROM ONE HEAT EXCHANGER WHICH WAS FOUND TO BE PARTIALLY SENSITIZED IN THE AS DELIVERED CONDITION. THE PIPE MATERIAL MET THE REQUIREMENTS OF ASTM-A350. THIS HEAT HAD A HIGH CARBON CONTENT. SENSITIZATION WAS DUE TO THE STILL AIR CANNING IN HEAT TREATMENT BY THE PIPE MANUFACTURER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) • PLANTINTEGRITY (SPRAY) • FAILURE, PIPE • HEAT TREATMENT • DAMAGE • CRACK • FAILURE, FABRICATION ERROR • STRESS CORROSION • PIPES AND PIPE FITTINGS

105521

PIPING REPORT ON REACTOR BUILDING SPRAY SYSTEM ANALYSIS AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT COMPANY, LITTLE ROCK

PGS: LTR WASH 75-24 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, AUG. 29, 1975, DOCKET 50-313, TYPE--PUR, NRC--BGM, AE--BECHTEL

CAUSE - DESIGN ERROR. THE HYDRAULIC PERFORMANCE OF THE REACTOR BUILDING SPRAY SYSTEM HAS BEEN RE-ANALYZED TO CHECK OLD RESULTS PRESENTED PREVIOUSLY. RE-ANALYSIS FOUND THE TIME BETWEEN DEPLETION OF THE CHEMICAL TANKS AND DEPLETION OF THE CHARGED WATER STORAGE TANK TO BE 15 MINUTES FOR 1 SPRAY PUMP OPERATION AND 6 MINUTES 25 SECONDS FOR 2 SPRAY PUMPS OPERATION. THESE FIGURES ARE SIGNIFICANTLY LESS THAN BGM'S ANALYSIS. FOR THESE SHORTER TIMES AT HIGH PH, NO DAMAGE WOULD OCCUR TO THE PIPING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) • PLANTINTEGRITY (SPRAY) • ADJUTIVE • FLOW • RATE • EFFECT, PH • FAILURE, DESIGN ERROR • HYDRAULIC ANALYSIS

106375

AMMONIA CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT CO., ARR.

PGS: LTR WASH 50-313/75-6 TO NRC OFFICE OF I & E, REGION IV, SEPT. 8, 1975, DOCKET 50-313, TYPE--PUR, NRC--BGM, AE--BECHTEL

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE INTAKE AND DISCHARGE CANAL INDICATE THAT AMMONIA CONCENTRATION IN EFFLUENT INCREASED ACROSS THE PLANT IN EXCESS OF ITS LIMITS. THE NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE CANAL AT THE TIME OF SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) • AMMONIA CONCENTRATION • EFFLUENT • CONDENSED COOLING SYSTEM • WASTE DISPOSAL

106376

EMERGENCY POND WATER DEPTH MAY HAVE BEEN BELOW LIMIT AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT CO., ARR.

PGS: LTR WASH 50-313/75-6 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, SEPT. 10, 1975, DOCKET 50-313, TYPE--PUR, NRC--BGM, AE--BECHTEL

CAUSE - DESIGN DEFICIENCY. FOLLOWING AN EMERGENCY COOLING POND SOUNDING WHICH SHOWED AN APPARENT INCREASE IN POND BOTTOM ELEVATION, A REVIEW OF RECORDS INDICATED THAT THE MINIMUM WATER DEPTH OF 2.75 FT MAY HAVE OCCURRED DURING AUG. 1974 FOR 6 DAYS DURING THE INITIAL LOW POWER PHYSICS TESTING. THIS MAY HAVE BEEN CAUSED BY FAILURE TO ALLOW FOR SWELLING OF THE CLAY ON THE POND

100176 - NO FINDINGS

SOIL OR FILLING SATURATION WITH WATER. RESULTS OF SOUNDING DO NOT INDICATE SILTING. TECH SPECS REQUIRE AT LEAST 3 FEET OF WATER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) + PLANTING PLANT + EMERGENCY COOLING + SYSTEM CAPACITY + REVIEW + SOIL PROPERTY + SILENT + PASSIVE DESIGN CODE

100187

CHLORIDE INCREASE ACROSS PLANT EXCEEDS LIMIT AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT CO., ARK.

53 PUS, LTR W/AS 50-513/75-90 TO NRC OFFICE OF I & E, REGION IV, SEPT. 23, 1975, DOCKET 50-313, TYPE--PWR, WFG--BCH, AE--SCNTEL

CAUSE - WATER DISPOSAL. WATER SAMPLES TAKEN FROM THE INTAKE AND DISCHARGE CANALS INDICATE THAT THE CHLORIDE CONCENTRATION INCREASED ACROSS THE PLANT IN EXCESS OF ITS LIMIT. THE NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE PLUME DURING SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) + WATER QUALITY + PLANTING PLANT + CHLORIDE + EFFLUENT + DISCHARGE + CONDENSER COOLING SYSTEM

100664

CHLORIDE INCREASE ACROSS PLANT EXCEEDS LIMIT AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT CO., ARK.

53 PUS, LTR W/AS 50-513/75-90 TO NRC OFFICE OF I & E, REGION IV, OCT. 1, 1975, DOCKET 50-313, TYPE--PWR, WFG--BCH, AE--SCNTEL

CAUSE - MUDDY WATER BACKED INTO DISCHARGE CANAL. SAMPLES TAKEN FROM THE INTAKE AND DISCHARGE CANALS INDICATE THAT TURBIDITY IN THE DISCHARGE WAS 11.78 GREATER THAN IN THE INTAKE. RECENT RAINS CAUSED THE ARKANSAS RIVER TO RISE AND BACK MUDDY WATER UP INTO THE DISCHARGE EMBAYMENT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) + PLANTING PLANT + EFFLUENT + CONDENSER COOLING SYSTEM + WEATHER, SEVERE

100677

ADDITIONAL DATA ON FAILED INSTRUMENT LINE WELDS AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT CO., ARK.

53 PUS, LTR W/AS 50-513/76-124 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, OCT. 7, 1975, DOCKET 50-313, TYPE--PWR, WFG--BCH, AE--SCNTEL

CAUSE - INTERDENDRITIC SHRINKAGE CRACKS. AS REPORTED EARLIER, 3 RPS INSTRUMENT LINE SOCKET WELDS FAILED. TWO SAMPLES OF WELDS WHICH SHOWED LIQUID PENETRANT INDICATIONS WERE EXAMINED. CRACKS OF BOTH WERE AT THE CENTER OF THE WELD FACE. EXAMINATION AT A HIGHER MAGNIFICATION INDICATED THAT THEY ARE INTERDENDRITIC SHRINKAGE IMPERFECTIONS. FOR THESE SAMPLES, THE DEPTH WAS 0.004 AND 0.004 INCH RESPECTIVELY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) + WELDS + PIPES AND PIPE FITTINGS + INSTRUMENTS, MISC. + CRACK + METALLURGY + EXAMINATION

100973

ADDITIONAL INFORMATION ON LEAK IN RCS DRAIN PIPING AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT CO., LITTLE ROCK

53 PUS, LTR W/AS 50-513/76-100 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, OCT. 7, 1975, DOCKET 50-313, TYPE--PWR, WFG--BCH, AE--SCNTEL

CAUSE - STRESS. ON OCT. 17, 1976, A LEAK IN A 1 1/2-IN. DRAIN LINE FROM THE PRIMARY COOLANT LOOP WAS DETECTED. THE LEAK, LOCATED IN A FIELD WELD, WAS REPAIRED. ON OCT. 25, 1976, ANOTHER LEAK WAS MODIFIED TO REMOVE STRESS AND VIBRATIONAL EFFECTS. STRESS ANALYSIS OF THE MODIFIED DESIGN SHOWS THAT IT IS ADEQUATE TO WITHSTAND THE VIBRATIONS EXPECTED. ALSO, RESULTS INDICATE THAT FAILURE WAS NOT CAUSED BY THERMAL EXPANSION OR WEIGHT STRESSES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) + PIPES AND PIPE FITTINGS + LEAK + COOLING SYSTEM, SECONDARY + STRESS + METALLURGY + VIBRATION + FAILURE, PIPE + MODIFICATION

107610
 CHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED LIMITS AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER & LIGHT CO., LITTLE ROCK, ARK.
 4 PGS. LTR W/EN 50-313/75-50 TO NRC OFFICE OF I & E, REGION IV, OCT. 8, 1975, DOCKET 50-313, TYPE--PWR, MFG--
 SCW, AE--DECHTEL

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE INTAKE AND DISCHARGE CANALS INDICATE THAT THE
 CHEMICAL CONCENTRATIONS OF SODIUM NITRITE AND CHLORIDES INCREASED ACROSS THE PLANT IN EXCESS OF
 ITS LIMITS. THE NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE FLUME AT THE TIME OF SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) + CONCENTRATION + EFFLUENT + CONDENSER COOLING SYSTEM + WASTE DISPOSAL

107611
 CHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED LIMITS AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER & LIGHT CO., LITTLE ROCK, ARK.
 4 PGS. LTR W/EN 50-313/75-51 TO NRC OFFICE OF I & E, REGION IV, OCT. 17, 1975, DOCKET 50-313, TYPE--PWR, MFG--
 SCW, AE--DECHTEL

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE INTAKE AND DISCHARGE CANALS INDICATE THAT THE
 CHEMICAL CONCENTRATIONS OF 6 PARAMETERS INCREASED ACROSS THE PLANT IN EXCESS OF ITS LIMITS. THE
 NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE FLUME AT THE TIME OF SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) + CONCENTRATION + EFFLUENT + CONDENSER COOLING SYSTEM + WASTE DISPOSAL

107701
 CHEMICAL CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER & LIGHT CO., LITTLE ROCK, ARK.
 4 PGS. LTR W/EN RPT 50-313/75-53 TO NRC OFFICE OF I & E, REGION IV, OCT. 31, 1975, DOCKET 50-313, TYPE--PWR,
 MFG--SCW, AE--DECHTEL

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE INTAKE AND DISCHARGE CANALS INDICATED THAT THE
 CONCENTRATION OF CHLORIDE AND AMMONIA INCREASED ACROSS THE PLANT IN EXCESS OF ITS LIMITS. THE
 NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE FLUME AT THE TIME OF SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) + CONCENTRATION + EFFLUENT + CONDENSER COOLING SYSTEM + WASTE DISPOSAL + CHLORIDE +
 WASTE DISPOSAL, LIQUID

107702
 ADDITIONAL INFORMATION ON REACTOR BUILDING SPRAY PIPING AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER & LIGHT CO., LITTLE ROCK, ARK.
 51 PGS. LTR W/AD RPT 50-313/74-110 TO NRC DIRECTOR OF NUCLEAR REACTOR REGULATION, OCT. 31, 1975, DOCKET 50-
 313, TYPE--PWR, MFG--SCW, AE--DECHTEL

CAUSE - CHLORIDE INDUCED CRACKS. ON NOV. 7, 1974, REACTOR BUILDING SPRAY PUMP SUCTION LINE LEAKS
 WERE REPORTED. THIS FOLLOW-UP REPORT TRANSMITS (1) CHEMICAL ANALYSIS PROCEDURE FOR CHLORIDE
 DETERMINATION IN THE PRESENCE OF SODIUM THIOSULFATE, (2) FATIGUE ANALYSIS OF SCH 10 S PIPING, AND
 (3) FOLLOW-ON EXAMINATION AND INSPECTION PROGRAM FOR PIPING ASSOCIATED WITH 2 SPECIFIC HEAT
 NUMBERS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) + PIPES AND PIPE FITTINGS + CONTAINMENT SPRAY + SURVEILLANCE PROGRAM + PROCEDURES
 AND MANUALS + CHEMICAL ANALYSIS + CHLORIDE + STRESS ANALYSIS + MATHEMATICAL TREATMENT + STRESS CORROSION

107915
 REACTOR BUILDING SPRAY PUMP PIPING LEAKS AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER & LIGHT CO., LITTLE ROCK, ARK.
 5 PGS. LTR W/AD 50-313/75-7 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, NOV. 3, 1975, DOCKET 50-313, TYPE--
 PWR, MFG--SCW, AE--DECHTEL

CAUSE - CHLORIDE INDUCED STRESS CORROSION. WHILE REDUCING POWER, A LEAK WAS DISCOVERED IN THE
 REACTOR BUILDING SPRAY PUMP SUCTION LINE ADJACENT TO A WELD JUST UPSTREAM OF THE VALVE. THE
 CRACK IN THE 10 INCH SCH 10 PIPE WAS ABOUT 2 INCHES LONG. THE SPOOL PIECE CONTAINING THE CRACK
 WILL BE REPLACED WITH A NEW ONE. THIS IS THE SIXTH OCCURRENCE OF THIS TYPE IN THE VICINITY OF A
 WELD IN THIS TYPE OF PIPE. THIS IS A FABRICATION ERROR.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

107915 - PLUMBERGEO
 ARKANSAS NUCLEAR 1 (PWR) - PIPES AND PIPE FITTINGS - PLEAK - PLACK - CONTAINMENT SPRAY - FAILURE, PIPE - FAILURE, NEUTRALIZING TANK

107914
 CHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED LIMITS AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER & LIGHT CO., LITTLE ROCK, ARK.
 4 PGS. LTR W/ENR 50-313/75-54 TO NRC OFFICE OF I & E, REGION IV, NOV. 5, 1975. DOCKET 50-313, TYPE--PWR, NRC--
 DEN, AR--BECHTEL

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE INTAKE AND DISCHARGE CANALS INDICATE THE CHEMICAL CONCENTRATIONS OF 4 PARAMETERS INCREASED ACROSS THE PLANT IN EXCESS OF ETS LIMITS. THE NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE FLOW AT THE TIME OF SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) - PLUMBERGEO - EFFLUENT - WASTE DISPOSAL - CONDENSER COOLING SYSTEM

107900
 LEAK FOUND IN BUST LINE AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER & LIGHT CO., LITTLE ROCK, ARK.
 5 PGS. LTR W/ENR 50-313/75-8 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, NOV. 11, 1975. DOCKET 50-313, TYPE--
 PWR, NRC--DEN, AR--BECHTEL

CAUSE - UNKNOWN. WHILE THE REACTOR WAS IN COLD SHUTDOWN, A LEAK WAS DISCOVERED IN THE 6-INCH, SCH 10, LINE FROM THE BUST TO THE MAKEUP PUMP. IT WAS LOCATED ABOUT 1/2 INCH FROM THE 14 X 6 INCH REDUCER-TO-PIPE WELD ON THE PIPE SIDE OF THE WELD. RADIOGRAPHS SHOWED NO EVIDENCE OF A CRACK BUT DID INDICATE PITTING. THE CAUSE IS UNKNOWN AT THIS TIME. A 2 FOOT LONG SPOOL PIECE WAS REMOVED AND REPLACED FROM THE AFFECTED AREA. WELDS DOWNSTREAM OF THIS AREA SHOWED NO EVIDENCE OF PITTING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) - PIPES AND PIPE FITTINGS - PLEAK - FAILURE, PIPE - POISON, SOLUBLE - CHEMICAL SHIM - WELDS

108077
 CHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED LIMIT AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER & LIGHT CO., LITTLE ROCK, ARK.
 3 PGS. LTR W/ENR 50-313/75-55 TO NRC OFFICE OF I & E, REGION IV, NOV. 16, 1975. DOCKET 50-313, TYPE--PWR, NRC--
 DEN, AR--BECHTEL

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE INTAKE AND DISCHARGE CANALS INDICATE THAT THE CONCENTRATION OF TURBIDITY, SULFUR NITRIDE, AND CHLORIDE INCREASED ACROSS THE PLANT IN EXCESS OF ETS LIMITS. THE NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE FLOW DURING SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) - PLUMBERGEO - EFFLUENT - CONDENSED COOLING SYSTEM - WASTE DISPOSAL

108200
 CHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED LIMITS AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER & LIGHT CO., LITTLE ROCK, ARK.
 4 PGS. LTR W/ENR 50-313/75-55 TO NRC OFFICE OF I & E, REGION IV, NOV. 16, 1975. DOCKET 50-313, TYPE--
 PWR, NRC--DEN, AR--BECHTEL

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE INTAKE AND DISCHARGE CANALS INDICATE THAT CONCENTRATIONS FOR SULFUR NITRIDE, CHLORIDES, AND TURBIDITY INCREASED ACROSS THE PLANT IN EXCESS OF ETS LIMITS. THE NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE FLOW AT THE TIME OF SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) - PLUMBERGEO - EFFLUENT - CONDENSED COOLING SYSTEM - WASTE DISPOSAL

108070
 EFFLUENT CONCENTRATION EXCEEDS LIMIT AT ARKANSAS NUCLEAR 1
 ARKANSAS POWER & LIGHT CO., LITTLE ROCK, ARK.
 4 PGS. LTR W/ENR 50-313/75-56 TO NRC OFFICE OF I & E, REGION IV, NOV. 17, 1975. DOCKET 50-313, TYPE--PWR, NRC--
 DEN, AR--BECHTEL

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE INTAKE AND DISCHARGE CANALS INDICATE THAT THE CONCENTRATIONS OF TURBIDITY AND AMMONIA INCREASED ACROSS THE PLANT IN EXCESS OF ETS LIMITS. THE NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE FLOW AT THE TIME.

100075 *CONTINUED*

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) * CONCENTRATION * EFFLUENT * CONDENSER COOLING SYSTEM * WASTE DISPOSAL

100233

CHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED LIMITS AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT CO., LITTLE ROCK, ARK.

6 PGS. LTR W/EN 50-313/75: 57 TO U.S. NRC, REGION IV, NOV. 26, 1975, DOCKET 50-313, TYPE--PWR, NFG--BEN, AE--BECHTEL

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE INTAKE AND DISCHARGE CANALS INDICATE THAT THE CONCENTRATION OF SODIUM NITRATE AND TURBIDITY INCREASED ACROSS THE PLANT IN EXCESS OF ETS LIMITS. THE NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE CANAL AT THE TIME OF SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) * CONCENTRATION * EFFLUENT * CONDENSER COOLING SYSTEM * WASTE DISPOSAL

100234

ADDITIONAL INFORMATION ON PRIMARY MAKEUP PUMP LEAK AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT CO., LITTLE ROCK, ARK.

5 PGS. LTR W/AN 50-313/75-2A TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, NOV. 26, 1975, DOCKET 50-313, TYPE--PWR, NFG--BEN, AE--BECHTEL

CAUSE - VIBRATION. WHILE OPERATING AT 90-92 POWER, A LEAK WAS DISCOVERED ON THE PRIMARY MAKEUP PUMP 1/2 INCH CASING CHAIN LINE WHERE THE LINE IS THREADED INTO THE CASING DISCHARGE NOZZLE AS REPORTED EARLIER. THE CAUSE IS BELIEVED TO BE IMPROPER FITUP OF THE THREADED SECTION. A NEW CASING CHAIN LINE PIPE SECTION WAS FABRICATED AND INSTALLED. PROPER FITUP WAS VERIFIED. THE ONLY APPARENT SOURCE OF VIBRATION IS THE OPERATION OF THE PUMP. SINCE REPAIRS WERE MADE, THE PUMP HAS RUN FOR AT LEAST 2 MONTHS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) * PIPES AND PIPE FITTINGS * FEEDWATER * MAIN COOLING SYSTEM * CRACK * FAILURE, INSTALLATION ERROR * LEAK

100520

DIESEL GENERATOR OIL COOLER OUTLET FLANGE LEAKS AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT CO., LITTLE ROCK, ARK.

6 PGS. LTR W/AN 50-313/75-9 TO NRC DIVISION OF REACTOR LICENSING, DEC. 5, 1975, DOCKET 50-313, TYPE--PWR, NFG--BEN, AE--BECHTEL

CAUSE - GASKET FAILURE. DURING TESTING OF DIESEL GENERATOR 2 WHILE THE REACTOR WAS AT 99% POWER, AN OIL LEAK DEVELOPED AT THE OIL COOLER OUTLET FLANGE. THE O-RING GASKET HAD FAILED. GASKET REPLACEMENT REQUIRED 5 HOURS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) * SEAL * LUBRICATION * HEAT EXCHANGERS * GENERATOR, DIESEL * ENGINES, INTERNAL CORROSION * TEST, SYSTEM OPERABILITY * LEAK

100540

CHEMICAL CONCENTRATIONS EXCEED LIMITS AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT CO., LITTLE ROCK, ARK.

5 PGS. LTR W/EN 50-313/75-50 TO NRC OFFICE OF I & E, REGION IV, DEC. 5, 1975, DOCKET 50-313, TYPE--PWR, NFG--BEN, AE--BECHTEL

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE INTAKE AND DISCHARGE CANALS INDICATED THAT THE CHEMICAL CONCENTRATION OF SODIUM NITRITE, CHLORIDE, AND AMMONIA INCREASED ACROSS THE PLANT IN EXCESS OF ETS LIMITS. THE NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE PLUME AT THE TIME OF SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PWR) * CONCENTRATION * EFFLUENT * CONDENSER COOLING SYSTEM * WASTE DISPOSAL

100830

CHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT CO., LITTLE ROCK, ARK.

5 PGS. LTR W/EN 50-313/75-59 TO NRC OFFICE OF I & E, REGION IV, DEC. 11, 1975, DOCKET 50-313, TYPE--PWR, NFG--BEN, AE--BECHTEL

100630 *CONTINUUM

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE DISCHARGE CANAL AND AT POINT 20 INDICATE THAT THE CHLORIDE CONCENTRATION IN THE CONDENSER COOLING WATER INCREASED ACROSS THE PLANT IN EXCESS OF ETS LIMITS. THE NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE FLUME DURING SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PHR) * CONCENTRATION * EFFLUENT * CHLORIDE * WASTE DISPOSAL * CONDENSER COOLING SYSTEM

109275

CHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED LIMIT AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT CO., LITTLE ROCK, AR

4 PGS. LTR W/ENCL. RPT 50-313/75-60 TO NRC OFFICE OF I & E, REGION IV, DEC. 15, 1975, DOCKET 50-313, TYPE--PHR, NRC--BEN, AE--BECHTEL

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE INTAKE AND DISCHARGE CANALS INDICATE THAT THE CHEMICAL CONCENTRATION OF SODIUM NITRITE AND CHLORIDE INCREASED ACROSS THE PLANT IN EXCESS OF ETS LIMITS. THE NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE FLUME AT THE TIME OF SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PHR) * CONCENTRATION * EFFLUENT * CONDENSER COOLING SYSTEM * WASTE DISPOSAL * CHLORIDE

109276

CHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED LIMIT AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT CO., LITTLE ROCK, AR

4 PGS. LTR W/ENCL. RPT 50-313/75-61 TO NRC OFFICE OF I & E, REGION IV, DEC. 26, 1975, DOCKET 50-313, TYPE--PHR, NRC--BEN, AE--BECHTEL

CAUSE - WASTE DISPOSAL. SAMPLES TAKEN FROM THE INTAKE AND DISCHARGE CANAL INDICATE THAT THE CHEMICAL CONCENTRATION OF CHLORIDE AND CONDUCTIVITY INCREASED ACROSS THE PLANT IN EXCESS OF ETS LIMITS. THE NEUTRALIZING TANK WAS DRAINING INTO THE DISCHARGE FLUME AT THE TIME OF SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PHR) * CONCENTRATION * EFFLUENT * CONDENSER COOLING SYSTEM * WASTE DISPOSAL * CHLORIDE

109276

REQUIRED OVERLAP BETWEEN OPERATING CONTROL ROD GROUPS LOST AT ARKANSAS NUCLEAR 1

ARKANSAS POWER & LIGHT CO., LITTLE ROCK, AR

6 PGS. LTR W/ENCL. RPT 50-313/75-10 TO NRC DIVISION OF REACTOR LICENSING, DEC. 30, 1975, DOCKET 50-313, TYPE--PHR, NRC--BEN, AE--BECHTEL

CAUSE - APPARENT POWER SUPPLY FAILURE. WHILE OPERATING AT 62% POWER, CONTROL ROD GROUP 6 TRIPPED CAUSING AN APPARENT VIOLATION OF THE REQUIREMENT FOR 25 PLUS OR MINUS 5% OVERLAP BETWEEN 2 SEQUENTIAL GROUPS. GROUP 6 WAS WITHDRAWN BUT TRIPPED AGAIN THE NEXT DAY. THE REACTOR WAS MANUALLY TRIPPED. THE APPARENT CAUSE WAS FAILURE OF GROUP 6 POWER SUPPLY. THE INVESTIGATION IS CONTINUING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 1 (PHR) * CONTROL RODS * CONTROL ROD DRIVE MECHANISMS * CONTROL ROD INTERACTION * FAILURE, COMPONENT * REACTOR SHUTDOWN * ELECTRIC POWER

102240

SPENT FUEL POOL WALL DEFICIENCY AT ARKANSAS NUCLEAR 2

ARKANSAS POWER AND LIGHT COMPANY

6 PAGES. LETTER WITH ATTACHMENT TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, FEBRUARY 7, 1975, DOCKET 50-308, TYPE--PHR, NRC--COMB, AE--BECHTEL

CAUSE - INSUFFICIENT DESIGN DETAIL. THE HORIZONTAL REINFORCING STEEL ON THE INSIDE FACE OF THE SPENT FUEL POOL AND THE TILT PIT IS NOT PROPERLY DETAILED TO DEVELOP THE BARS AT POINTS OF HIGH STRESS. THE STEEL IS BENT TO THE INSIDE FACE OF THE POOL RATHER THAN EXTENDING THROUGH THE WALL TO OVERLAP WITH STEEL ON THE OUTER FACE. STRESS ANALYSES WERE MADE FOR SEVERAL ACCIDENT CONDITIONS. BASED ON THE RESULTS, A STRUT WAS ADDED TO BRING SHEAR STRESS WITHIN AN ACCEPTABLE RANGE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

STEEL * FUEL STORAGE * STRESS * MODIFICATION * STORAGE CONTAINER * FAILURE, DESIGN ERROR * CONSTRUCTION * CONCRETE, REINFORCED * ARKANSAS NUCLEAR 2 (PHR)

104077
FINAL REPORT ON SPENT FUEL POOL WALL DEFICIENCY AT ARKANSAS NUCLEAR 2
ARKANSAS POWER & LIGHT COMPANY
6 PAGES, LETTER WITH ATTACHMENT TO OFFICE OF INSPECTION & ENFORCEMENT, REGION 4, MAY 5, 1975, DOCKET 50-368,
TYPE--PWR, NRC--COMB., AE--BECHTEL

CAUSE - INSUFFICIENT DETAILS IN DRAWINGS. THE HORIZONTAL REINFORCING STEEL ON THE INSIDE FACE OF THE SPENT FUEL POOL AND THE TILT PIT WAS NOT PROPERLY DETAILED SO AS TO DEVELOP THE BARS AT POINTS OF HIGH STRESS. THE STEEL WAS BENT TO FORM A 90 DEGREE BEND ON THE INSIDE FACE RATHER THAN EXTENDING THROUGH THE WALL. STRUCTURAL DESIGN CALCULATIONS WERE MADE USING 2 SEPARATE COMPUTER PROGRAMS. BASED ON ANALYSIS, A STRUT ON THE SEPARATOR WALL IS SUFFICIENT BUT 2 STRUTS WILL BE ADDED. THE CONSEQUENCES OF A WALL FAILURE WERE ANALYZED. NO HIGH RADIATION ZONE AND NO CLADDING DAMAGE WOULD OCCUR.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 2 (PWR) • CONSTRUCTION • CONCRETE, REINFORCED • STEEL • FABRICATION • FAILURE, DESIGN ERROR • FUEL STORAGE • STORAGE CONTAINER • STRESS ANALYSIS • MODIFICATION

104067
ROTARY RELAYS FAIL TO OPERATE AT ARKANSAS NUCLEAR 2
ARKANSAS POWER & LIGHT CO., LITTLE ROCK
4 PAGES, LETTER WITH REPORT TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 4, AUG. 6, 1975, DOCKET 50-368,
TYPE--PWR, NRC--COMB., AE--BECHTEL

CAUSE - BINDING FROM INSUFFICIENT END PLAY. DURING CHECKOUT OF AUXILIARY RELAY PANELS AT THE PANEL ASSEMBLY PLANT, PUTTER & BARNFIELD MON-7034 ROTARY RELAYS FAILED TO OPEN 7M SIGNAL DUE TO BINDING. EXAMINATION OF 2 FAILED UNITS SHOWED THE CAUSE OF FAILURE TO BE INSUFFICIENT SHAFT ENDPLAY. ASSEMBLY PROCEDURES WERE CHANGED TO INCREASE THE MINIMUM ENDPLAY, ADD BOLT TIGHTNESS REQUIREMENT, AND REQUIRE THE AUDITIONS OF A GLYPHIC STAKE TO THE MOTOR BOLTS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ARKANSAS NUCLEAR 2 (PWR) • CONSTRUCTION • RELAYS • TEST, SYSTEM OPERABILITY • TEST, PREOPERATIONAL • FABRICATION FACILITY • FAILURE, DESIGN ERROR • MODIFICATION • CONTROL PANEL/ROOM

100809
SOUTH MAIN STEAM PIPE RESTRAINT ERECTION DEFICIENCY AT ARKANSAS NUCLEAR 2
ARKANSAS LIGHT & POWER CO., LITTLE ROCK, AR
5 PGS, LTR W/MTI TO NRC OFFICE OF I & E, REGION IV, DEC. 10, 1975, DOCKET 50-368, TYPE--PWR, NRC--COMB., AE--BECHTEL

CAUSE - LAMELLAR TEARING. DURING ERECTION OF THE SOUTH MAIN STEAM PIPE RESTRAINT MK-66, 7 CRACKS DEVELOPED WHILE MAKING THE FIELD WELDS, 6 IN THE BASE METAL WHILE THE SEVENTH MAY HAVE STARTED IN THE BASE METAL. METALLURGICAL ANALYSIS INDICATES THAT 2 HEATS USED IN THE RESTRAINT ARE SUSCEPTIBLE TO LAMELLAR TEARING. A PROCEDURE WAS DEVELOPED FOR GOUGING OUT THE BASE MATERIAL BELOW THE LEVEL OF THE INCLUSION LAYER, BUTTERING WITH WELD MATERIAL, AND COMPLETING THE WELD. WELD SEQUENCE CONTROL AND MORE STRINGENT PREHEAT REQUIREMENTS WERE ALSO USED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONSTRUCTION • WELDS • SUPPORT STRUCTURE • PIPES AND PIPE FITTINGS • COOLING SYSTEM, SECONDARY • CRACK • METALLURGY • PLAN • FABRICATION • FAILURE, FABRICATION ERROR • ARKANSAS NUCLEAR 2 (PWR)

104076
SAFETY INJECTION SYSTEM VENT LINE CRACKS AT BEAVER VALLEY 1
DUQUESNE LIGHT COMPANY, PA.
6 PAGES, LETTER WITH REPORT TO NRC DIRECTORATE OF REGULATORY OPERATIONS, JULY 7, 1975, DOCKET 50-334, TYPE--PWR, NRC--WEST., AE--STURGE & WEBSTER

CAUSE - LACK OF SUPPORT. DURING HOT FUNCTIONAL TESTING, A LEAK WAS DETECTED AT THE SAFETY INJECTION 3/4-INCH SCH 160 HIGH POINT VENT LINE WELD CONNECTION AT THE 12-INCH SI HANGER IN LOOP C. THE LEAK WAS NON-ISOLABLE. THE PLANT WAS COOLED DOWN FOR REPAIRS. THE LEAKING JOINT WAS REMOVED. A NEW VENT LINE ASSEMBLY WAS INSTALLED AND WELDS WERE HYDROSTATICALLY TESTED. THE PIPE NIPPLE HAD FAILED AT THE TOE OF THE WELD. FAILURE WAS ATTRIBUTED TO FATIGUE SINCE THE 18 INCH HORIZONTAL ASSEMBLY WEIGH NG 32 POUNDS WAS NOT SUPPORTED. VIBRATION OCCURRED DURING IC PUMP OPERATION. A SUPPORT WAS INSTALLED ON THIS AND 3 SIMILAR INSTALLATIONS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

BEAVER VALLEY 1 (PWR) • CONSTRUCTION • PIPES AND PIPE FITTINGS • FAILURE, PIPE • LEAK • FAILURE, FATIGUE • SAFETY INJECTION • VIBRATION • FAILURE, DESIGN ERROR • SUPPORT STRUCTURE • TEST, SYSTEM OPERABILITY • TEST, PREOPERATIONAL • WELDS

109606
 REACTION CONTAINMENT JUNE PROTECTIVE COATING FAILS AT BEAVER VALLEY 1
 JAGGESSIE LIGHT CO., PITTSBURGH, PA
 1 PG, LTR W/RT TO NRC OFFICE OF I & E, DEC. 22, 1975, DOCKET 50-334, TYPE--PHR, NRC--WEST., AE--STONE &
 WEBSTER

CAUSE - PROBABLY PRIMING DEFICIENCY. AFTER THE STRUCTURAL INTEGRITY TEST AND THE INTEGRATED LEAK RATE TEST DURING WHICH THE CONTAINMENT WAS PRESSURE CYCLED REPEATEDLY, BLISTERING OF THE REACTOR CONTAINMENT DOME COATING WAS FOUND. THE DEFECTIVE AREA IS THE ONLY PORTION WHERE PRIME COATING HAD BEEN APPLIED IN 7 COATS. THIS APPEARS TO BE THE PROBLEM. THE INVESTIGATION IS CONTINUING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

BEAVER VALLEY 1 (PHR) + CONSTRUCTION + FLAM + TEST, SYSTEM OPERABILITY + TEST, PROOF + TESTING + TEST, PREOPERATIONAL + ADMISION + FAILURE, INSTALLATION ERROR + CONTAINMENT PAINT + SURFACE, PAINTED

109612
 ALTERATION OF RECORDS BY BSN REPORTED AT BELLEFONTE 1 AND 2
 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN
 + PLS, LTR W/RT TO NRC OFFICE OF I & E, DEC. 15, 1975, DOCKETS 50-638/639, TYPE--PHR, NRC--BCL, AE--TYA

CAUSE - NOT STATED. THIS INTERIM REPORT STATES THAT TYA CAN ONLY ACCEPT THE QUESTIONED MATERIAL UPON ITS ACCEPTABILITY IS PROVEN INDEPENDENT OF THE ALTERED DOCUMENTS. THE ALTERED DOCUMENTS ARE IN PROCESS RECORDS COMPRISED OF ROUTE SHEETS WHICH CONTROL THE CUTTING AND PREPARATION OF MATERIAL AND THE FABRICATION CONTROL RECORDS. THE MATERIAL AFFECTED IS UNIT 2 EMBEDDED ANGLES AND TEES WHICH BECOME BACKING BARS FOR THE BOTTOM LINER PLATE. THE UPPER PORTION OF BOTH UNIT 2 STEAM GENERATOR ANCHORAGES ARE ALSO INVOLVED. MILL MARKING, WELDER IDENTIFICATIONS, ETC., WILL BE USED TO TRACE BACK TO MILL CERTIFICATION, WELDER QUALIFICATION, ETC.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

BELLEFONTE 1 (PHR) + BELLEFONTE 2 (PHR) + CONSTRUCTION + RECORDS + QUALITY ASSURANCE + FAILURE, FABRICATION ERROR + FABRICATION FACILITY + MATERIAL + IDENTIFICATION

109939
 AXIAL FLUX OFFSET CALCULATOR DRAWER FAILS AT CALVERT CLIFFS 1
 BALTIMORE GAS & ELECTRIC CO., MD.

CAUSE - DEFECTIVE COLD SOLDER JOINT. WHILE OPERATING AT 18 POWER, THE OPERATOR OBSERVED THAT CHANNEL C AXIAL FLUX OFFSET CALCULATION SIGNAL WAS SIGNIFICANTLY DIFFERENT FROM THE OTHER 3 CHANNELS. SINCE THESE TRIP FUNCTIONS ARE INHIBITED BELOW 15% POWER, NO ACTION WAS REQUIRED. A DEFECTIVE COLD SOLDER JOINT WAS FOUND BETWEEN THE INTERCONNECTING WIRING AND THE POWER SUMMER AND SUB-CHANNEL DEVIATION CIRCUIT BOARD CONNECTOR. THE JOINT WAS REMOVED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FLUX DISTRIBUTION + INSTRUMENT, NUCLEAR + FAILURE, INSTRUMENT + REACTOR STARTUP EXPERIENCE + FAILURE, FABRICATION ERROR + INSTRUMENT, ABNORMAL INDICATION + CALVERT CLIFFS 1 (PHR) + CABLES AND CONNECTORS

099197
 CONTAINMENT RADIATION MONITOR FAILS AT CALVERT CLIFFS 1
 BALTIMORE GAS & ELECTRIC COMPANY, MARYLAND
 3 PAGES, LETTER WITH AD REPORT 74/20 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 1 (AEC), JANUARY 9, 1975, DOCKET 50-317, TYPE--PHR, NRC--CUMB., AE--BECHTEL

CAUSE - DEFECTIVE DETECTOR TUBE. ONE OF THE 3 CONTAINMENT RADIATION MONITORS WAS OBSERVED TO BE READING HIGHER THAN THE OTHERS AND WAS CHANGING CYCLICALLY. THE GEIGER-MUELLER TUBE USED AS A DETECTOR WAS DEFECTIVE. THE DEFECTIVE TUBE AND ITS IMPEDANCE MATCHING CIRCUIT ASSEMBLY WERE REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + CALVERT CLIFFS 1 (PHR) + RADIATION MONITORS

093239
 LINEAR AMPLIFIER IN NUCLEAR INSTRUMENTATION FAILS AT CALVERT CLIFFS 1
 BALTIMORE GAS AND ELECTRIC COMPANY, MARYLAND
 3 PAGES, LETTER WITH AD REPORT 75/01 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, JANUARY 14, 1975, DOCKET 50-317, TYPE--PHR, NRC--CUMB., AE--BECHTEL

CAUSE - AMPLIFIER CARD FAILURE. WHILE A TECHNICIAN WAS ADJUSTING SUBCHANNEL B OF POWER RANGE NUCLEAR INSTRUMENTATION CHANNEL D, HE NOTICED THAT THE OUTPUT OF THE LINEAR AMPLIFIER CARD WAS 80 MILLIVOLTS. THE MAXIMUM ALLOWABLE OUTPUT IS 50 MILLIVOLTS. THE LINEAR AMPLIFIER CARD WAS REPLACED. THE REACTOR WAS AT 20% POWER AT THE TIME.

092239 CONTINUED

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + REACTOR SAFETY SYSTEM + REACTOR STARTUP EXPERIENCE + INSTRUMENT, POWER RANGE + CALVERT CLIFFS 1 (PWR) + ELECTRONIC FUNCTION UNITS

099341

OUTLET NOZZLES ON HEAT EXCHANGERS OVERSTRESSED AT CALVERT CLIFFS 1

BALTIMORE GAS AND ELECTRIC COMPANY, MARYLAND

3 PAGES, LETTER TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 1 (AEC), JANUARY 15, 1975, DOCKET 50-317, TYPE--PWR, MFG--COMB., AE--BECHTEL

CAUSE - THERMAL GROWTH. DURING A DESIGN REVIEW, IT WAS FOUND THAT THE SALT WATER OUTLET NOZZLES ON THE 2 SERVICE WATER HEAT EXCHANGERS AND THE COMPONENT COOLING WATER HEAT EXCHANGERS MIGHT BE OVERSTRESSED FOLLOWING A LOCA. THE OVERSTRESSED CONDITION WAS CAUSED BY THERMAL GROWTH OF THE COMPONENTS. THE HANGERS AND RESTRAINTS WERE MODIFIED TO PROVIDE THE NEEDED FLEXIBILITY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ACCIDENT, LOSS OF COOLANT + STRESS + THERMAL MECHANICAL EFFECT + MODIFICATION + FAILURE, DESIGN ERROR + NOZZLE + SUPPORT STRUCTURE + CALVERT CLIFFS 1 (PWR) + EMERGENCY COOLING SYSTEM + HEAT EXCHANGERS

093257

SAFETY INJECTION ACTUATION SYSTEM MODULE FAILS AT CALVERT CLIFFS 1

BALTIMORE GAS AND ELECTRIC COMPANY, MARYLAND

3 PAGES, LETTER WITH AD REPORT 75/02 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, JANUARY 15, 1975, DOCKET 50-317, TYPE--PWR, MFG--COMB., AE--BECHTEL

CAUSE - COMPONENT FAILURE. DURING TESTING WHILE THE REACTOR WAS AT 20% POWER, THE SAFETY INJECTION ACTUATION SYSTEM LOGIC MODULE A-1 FAILED TO ACTUATE FOR THE CONTAINMENT PRESSURE INPUT. A PORTION OF THE DUAL FUNCTION LOGIC MODULE HAD FAILED. THE LOGIC MODULE WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + CONTROL SYSTEM + SAFETY INJECTION + REACTOR STARTUP EXPERIENCE + TEST, SYSTEM OPERABILITY + CALVERT CLIFFS 1 (PWR) + ELECTRONIC FUNCTION UNITS

093474

CONTAINMENT RADIATION AREA MONITOR FAILS AT CALVERT CLIFFS 1

BALTIMORE GAS AND ELECTRIC COMPANY, MARYLAND

3 PAGES, LETTER WITH AD REPORT 75/04 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, JANUARY 16, 1975, DOCKET 50-317, TYPE--PWR, MFG--COMB., AE--BECHTEL

CAUSE - DEFECTIVE GEIGER-MUELLER TUBE. WHILE THE UNIT WAS IN HOT SHUTDOWN CONDITION, A CONTAINMENT RADIATION MONITOR CHANNEL WAS NOTED TO BE INDICATING HIGHER THAN THE OTHER 3 CHANNELS. THE READING WAS CHANGING CYCLICALLY. THE GEIGER-MUELLER TUBE USED AS A DETECTOR WAS DEFECTIVE. THE DEFECTIVE TUBE AND IMPEDANCE MATCHING ASSEMBLY WERE REPLACED. SINCE 2 OTHER TUBE FAILURES HAVE OCCURRED, AN INVESTIGATION IS BEING PERFORMED TO SEE IF PHYSICAL CONDITIONS COULD BE CAUSING PREMATURE FAILURE OF THIS COMPONENT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + CONTAINMENT + REACTOR STARTUP EXPERIENCE + MONITOR, AREA + CALVERT CLIFFS 1 (PWR) + RADIATION MONITORS

093549

ERRATIC BEHAVIOR OF HOT LEG TEMPERATURE INPUT AT CALVERT CLIFFS 1

BALTIMORE GAS AND ELECTRIC COMPANY, MARYLAND

3 PAGES, LETTER WITH AD REPORT 75/03 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, JANUARY 16, 1975, DOCKET 50-317, TYPE--PWR, MFG--COMB., AE--BECHTEL

CAUSE - DEFECTIVE SLIDING LINKS. WHILE OPERATING AT 20% POWER, IT WAS NOTED THAT THE REACTOR COOLANT SYSTEM HOT LEG TEMPERATURE INPUT TO A REACTOR PROTECTIVE SYSTEM CHANNEL POWER CALCULATOR WAS ERRATIC. SOMETIMES IT WAS INDICATING LOWER THAN THE OTHER 3 CHANNELS AND SOMETIMES HIGHER. THE APPARENT CAUSE WAS DEFECTIVE SLIDING LINKS AT THE PANEL TERMINAL BOARD. THE TERMINAL BOARD CONTAINING THE DEFECTIVE SLIDING LINKS WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + REACTOR SAFETY SYSTEM + REACTOR STARTUP EXPERIENCE + CALVERT CLIFFS 1 (PWR) + SENSORS, TEMPERATURE

093552
SAFETY INJECTION ACTUATION SYSTEM LOGIC MODULE FAILS AT CALVERT CLIFFS 1
BALTIMORE GAS AND ELECTRIC COMPANY, MARYLAND
3 PAGES. LETTER WITH AD REPORT 75/05 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, JANUARY 16, 1975.
BUCKET 50-317, TYPE--PWR, MFG--COMB., AE--BECHTEL

CAUSE - COMPONENT FAILURE. DURING TESTING WITH THE REACTOR AT 20% POWER, A SAFETY INJECTION ACTUATION SYSTEM LOGIC MODULE FAILED TO ACTIVATE FOR THE PRESSURIZER CHANNEL D INPUT. THE APPARENT CAUSE WAS FAILURE OF THE PRESSURIZER PRESSURE PORTION OF THE DUAL FUNCTION LOGIC MODULE. THE LOGIC MODULE WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + CONTROL SYSTEM + SAFETY INJECTION + REACTOR STARTUP EXPERIENCE + TEST, SYSTEM OPERABILITY + CALVERT CLIFFS 1 (PWR) + ELECTRICAL FUNCTION UNITS

093675
CONTAINMENT RADIATION MONITOR FAILS AT CALVERT CLIFFS 1
BALTIMORE GAS AND ELECTRIC COMPANY, MARYLAND
3 PAGES. LETTER WITH AD REPORT 75/06 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, JANUARY 20, 1975.
BUCKET 50-317, TYPE--PWR, MFG--COMB., AE--BECHTEL

CAUSE - GIEGER-MUELLER TUBE FAILURE. WHILE OPERATING AT 20% POWER, A HIGH ALARM WAS RECEIVED ON CONTAINMENT RADIATION AREA MONITOR CHANNEL C. THE GIEGER-MUELLER TUBE USED AS A DETECTOR WAS DEFECTIVE. IT WAS REPLACED. AN INVESTIGATION INTO THE CAUSE OF PREMATURE FAILURES OF THIS COMPONENT IS UNDERWAY. THIS IS THE FOURTH FAILURE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + CONTAINMENT + REACTOR STARTUP EXPERIENCE + MONITOR, AREA + CALVERT CLIFFS 1 (PWR) + RADIATION MONITORS

093551
REACTOR COOL LEG TEMPERATURE INPUT TO CALCULATOR FAILS AT CALVERT CLIFFS 1
BALTIMORE GAS AND ELECTRIC COMPANY, MARYLAND
3 PAGES. LETTER WITH AD REPORT 75/07 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, JANUARY 20, 1975.
BUCKET 50-317, TYPE--PWR, MFG--COMB., AE--BECHTEL

CAUSE - DEFECTIVE INSULATION. WHILE OPERATING AT 20% POWER, IT WAS NOTED THAT THE REACTOR COOLANT SYSTEM COLD LEG TEMPERATURE TO THE CHANNEL B PROTECTIVE SYSTEM WAS VARYING SEVERAL DEGREES ABOVE THE ACTUAL TEMPERATURE. THE TEMPERATURE ELEMENT SIGNAL CABLE EXHIBITED A REDUCED RESISTANCE TO GROUND. THE LEAD INSULATION WAS DAMAGED ALLOWING INTERMITTENT CONTACT OF THE ELEMENT LEAD WIRE AND THE CABLE CONDUIT IN THE AREA OF THE RTO HEAD. THE DAMAGED INSULATION WAS WRAPPED WITH FIBERGLASS HEAT RESISTANT TAPE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

REACTOR SAFETY SYSTEM + REACTOR STARTUP EXPERIENCE + FAILURE, INSTALLATION ERROR + ELECTRICAL CONDUCTION + CALVERT CLIFFS 1 (PWR) + INSULATION + CABLES AND CONNECTORS + SENSORS, TEMPERATURE

093550
CONTAINMENT COOLER FAILS TO START AT CALVERT CLIFFS 1
BALTIMORE GAS AND ELECTRIC COMPANY, MARYLAND
3 PAGES. LETTER WITH AD REPORT 75/06 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, JANUARY 22, 1975.
BUCKET 50-317, TYPE--PWR, MFG--COMB., AE--BECHTEL

CAUSE - SUPPLY BREAKER TRIPS. DURING TESTING OF THE CONTAINMENT SPRAY ACTUATION SIGNAL B LOGIC WITH THE REACTOR AT 20% POWER, A CONTAINMENT COOLER FAN SUPPLY BREAKER TRIPPED OPEN INSTEAD OF THE FAN SHIFTING FROM FAST TO SLOW SPEED. THE BREAKER WAS CLOSED AND THE FAN STARTED. SUBSEQUENT INVESTIGATION REVEALED THAT THE MAIN LINE CONTACTOR SLOW SPEED CONTACTS AND THE FAST SPEED CONTACTS HAD ARCED. THE SLOW SPEED CONTACT CLOSED WHILE THE FAST SPEED CONTACTS WERE STILL ARCING CAUSING ARCING AT THE FAST SPEED CONTACTS. CONTACTS WERE CLEARED AND ADJUSTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + CONTAINMENT AIR COOLING + REACTOR STARTUP EXPERIENCE + TEST, SYSTEM OPERABILITY + FAILURE, MAINTENANCE ERROR + ELECTRIC ARC + CALVERT CLIFFS 1 (PWR) + BREAKER + BLOWERS

093625
SAFETY INJECTION ACTUATION SYSTEM LOGIC MODULE FAILS AT CALVERT CLIFFS 1
BALTIMORE GAS AND ELECTRIC COMPANY, MARYLAND
3 PAGES. LETTER WITH AD REPORT 75/09 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, JANUARY 23, 1975.
BUCKET 50-317, TYPE--PWR, MFG--COMB., AE--BECHTEL

093625 CONTINUED

CAUSE - COMPONENT FAILURE. WHILE TROUBLE-SHOOTING THE ENGINEERED SAFETY FEATURES ACTUATION SYSTEM AUTO-TEST CIRCUIT, A SAFETY INJECTION ACTUATION SYSTEM LOGIC MODULE FAILED TO PROPERLY ACTUATE. IT WOULD NOT PROCESS A CHANNEL A, B, C, OR TEST INPUT, BUT WOULD PROCESS A CHANNEL D INPUT. THE APPARENT CAUSE WAS FAILURE OF THE PRESSURIZER PORTION OF THE DUAL FUNCTION LOGIC MODULE. THE FAILED MODULE WAS REPLACED WITH A SPARE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 125 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTROL SYSTEM + SAFETY INJECTION + FAILURE, INSTRUMENT + REACTOR STARTUP EXPERIENCE + TEST, SYSTEM OPERABILITY + CALVERT CLIFFS 1 (PWR) + ELECTRONIC FUNCTION UNITS

093626

DOSE RATES OUTSIDE CONTAINMENT HIGHER THAN EXPECTED AT CALVERT CLIFFS 1

BALTIMORE GAS AND ELECTRIC COMPANY, PARYLAND

3 PAGES, LETTER TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, JANUARY 27, 1975, DOCKET 50-317, TYPE--PWR, NRC--COMB., AE--BECHTEL

CAUSE - INSUFFICIENT SHIELDING. BASED ON RADIATION MEASUREMENTS TAKEN OUTSIDE UNIT 1 CONTAINMENT STRUCTURE EQUIPMENT AND PERSONNEL MATCHES AT 5 TO 200 PPM/HR, DOSE RATES AT THESE POINTS ARE ESTIMATED TO HAVE EXCEEDED 0.5 MREM/HR WHEN REACTOR POWER EXCEEDED 0.18. HIGH LEVELS RESULTED FROM NEUTRON AND GAMMA STREAMING OUT OF THE ANNULUS AROUND THE REACTOR COOLANT PIPING WHERE IT PENETRATES THE PRIMARY SHIELD WALL. THE ANNULUS BETWEEN THE VESSEL FLANGE AND THE PRIMARY SHIELD WALL, AND OPENINGS AT THE SHIELD BASE. TEMPORARY SHIELDING WILL BE ADDED NOW AND PERMANENT SHIELDING LATER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 120 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTAINMENT EQUIPMENT MATCH + HIGH RADIATION + REACTOR STARTUP EXPERIENCE + FAILURE, DESIGN ERROR + SHIELDING + CALVERT CLIFFS 1 (PWR)

093626

NUCLEAR INSTRUMENTATION WIDE RANGE CHANNEL FAILS AT CALVERT CLIFFS 1

BALTIMORE GAS AND ELECTRIC COMPANY, PARYLAND

1 PAGES, LETTER WITH AD REPORT 75/10 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, JANUARY 27, 1975, DOCKET 50-317, TYPE--PWR, NRC--COMB., AE--BECHTEL

CAUSE - COMPONENT FAILURE. WHILE THE REACTOR WAS IN HOT SHUTDOWN, THE OPERATOR OBSERVED A NUCLEAR INSTRUMENTATION WIDE RANGE CHANNEL ERATICALLY VARYING. THE CHANNEL WAS PLACED IN BYPASS CONDITION. THE MANUAL EXTENDED RANGE DISCONNECT RESET POINT FOR THE CHANNEL IS 2 X 101-OTHER POWER. BECAUSE ONE HALF OF THE DUAL PROPORTIONAL COUNTER IS SHORTED, DUE TO A DETECTOR FAILURE, THE CHANNEL CIRCUIT WAS SEEING A CONDITION THAT WAS RIGHT AT THE RESET POINT AND THEREFORE AS THE PROPORTIONAL COUNTER WAS ENERGIZED, A NOISE SPIKE CAUSED AN ERRONEOUS INDICATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

NOISE + FAILURE, INSTRUMENT + REACTOR STARTUP EXPERIENCE + INSTRUMENT, STARTUP RANGE + CALVERT CLIFFS 1 (PWR)

099665

ESP STEAM GENERATOR ISOLATION SIGNAL SENSOR FAILS AT CALVERT CLIFFS 1

BALTIMORE GAS AND ELECTRIC CO., PARYLAND

2 PAGES, LETTER WITH AD REPORT 75/13 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, FEBRUARY 3, 1975, DOCKET 50-317, TYPE--PWR, NRC--COMB., AE--BECHTEL

CAUSE - COMPONENT FAILURE. DURING A PLANT COOLDOWN, THE ENGINEERED SAFETY FEATURES ACTUATION SYSTEM SENSOR CABINET DID NOT GIVE A STEAM GENERATOR ISOLATION SIGNAL OR TRIP SIGNAL AT PRESSURES SPECIFIED BY TECH SPECS. THE VOLTAGE-TO-VOLTAGE SIGNAL ISOLATION WHICH PROCESSES THE SGIS INPUT SIGNAL TO THE CABINET HAD FAILED. THE DEFECTIVE MODULE WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + REACTOR STARTUP EXPERIENCE + ENGINEERED SAFETY FEATURE + CALVERT CLIFFS 1 (PWR) + SENSORS, PRESSURE + ELECTRONIC FUNCTION UNITS

099666

RPS HOT LEG TEMPERATURE INPUT FAILS AT CALVERT CLIFFS 1

BALTIMORE GAS AND ELECTRIC CO., PARYLAND

2 PAGES, LETTER WITH AD REPORT 75/15 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, FEB. 3, 1975, DOCKET 50-317, TYPE--PWR, NRC--COMB., AE--BECHTEL

CAUSE - DEFECTIVE TEMPERATURE ELEMENT. WHILE THE PLANT WAS IN COLD SHUTDOWN, A LOOP TEST LEG TEMPERATURE INPUT TO CHANNEL A OF THE REACTOR PROTECTIVE SYSTEM FAILED IN THE HIGH DIRECTION. THE TEMPERATURE ELEMENT HAD AN OPEN CIRCUIT. THE DEFECTIVE ELEMENT WAS REPLACED.

099088 PLANTINTEUP
 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

REACTOR SAFETY SYSTEM + FAILURE, INSTRUMENT + REACTOR STARTUP EXPERIENCE + CALVERT CLIFFS 1 (PWR) + SENSORS, TEMPERATURE

100096
 STEAM GENERATOR BLOWDOWN VALVE OPEN TOO LONG AT CALVERT CLIFFS 1
 BALTIMORE GAS AND ELECTRIC COMPANY, MARYLAND
 3 PAGES, LETTER WITH AD REPORT 75/12 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, FEBRUARY 6, 1975, DOCKET 50-317, TYPE--PWR, NRG--COMB., AE--BECHTEL

CAUSE - IMPROPER PLANNING. WHILE OPERATING AT 50% POWER, THE STEAM GENERATOR BLOWDOWN ORIFICE BYPASS VALVE WAS LEFT OPEN FOR 20 HOURS. THIS VIOLATED THE TIME LIMIT. THE APPARENT CAUSE WAS DIFFICULTY IN MAKING A CONTAINMENT ENTRY TO CLOSE THE VALVE. SUPERVISORY OPERATIONS PERSONNEL WERE ADVISED OF THE IMPORTANCE OF PRE-PLANNING A CONTAINMENT ENTRY WHERE TIMELY ACTION IS NECESSARY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

REACTOR STARTUP EXPERIENCE + FAILURE, ADMINISTRATIVE CONTROL + COOLANT PURIFICATION SYSTEM + STEAM GENERATOR + CALVERT CLIFFS 1 (PWR) + BYPASS + VALVES

099672
 CONTAINMENT SUMP DRAIN VALVE FAILS TO CLOSE AT CALVERT CLIFFS 1
 BALTIMORE GAS AND ELECTRIC COMPANY, MARYLAND
 2 PAGES, LETTER WITH AD REPORT 75/14 TO NRC, REGION 1, FEBRUARY 7, 1975, DOCKET 50-317, TYPE--PWR, NRG--COMB., AE--BECHTEL

CAUSE - SLIPPED LIMIT SWITCH SETTING. AFTER DRAINING THE CONTAINMENT SUMP WITH THE REACTOR SHUT DOWN, THE CONTAINMENT SUMP NORMAL DRAIN VALVE DID NOT CLOSE. THE MOTOR OPERATOR WAS FOUND TO HAVE BEEN TRIPPED BY TORQUE WITH THE VALVE ON THE BACKSEAT. A REDUNDANT VALVE OPERATED NORMALLY. THE LIMIT SWITCH HAD SLIPPED. TWO BURRS WERE FOUND ON A GEAR OF THE LIMIT SWITCH ASSEMBLY AND AN O-RING SEAL ADJACENT TO THAT GEAR WAS BROKEN. THIS WOULD HAVE ALLOWED SLIPPAGE TO OCCUR. THESE WERE REPAIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + INSTRUMENT, SWITCH + REACTOR STARTUP EXPERIENCE + CONTAINMENT SUMP + CALVERT CLIFFS 1 (PWR) + VALVES

100873
 SADDLE MATERIAL NOT VERIFIED AT CALVERT CLIFFS 1 AND 2
 BALTIMORE GAS & ELECTRIC CO., MD.
 1 PAGE, LETTER TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, FEBRUARY 7, 1975, DOCKETS 50-317/318, TYPE--PWR, NRG--COMB., AE--BECHTEL

CAUSE - INTERPRETATION OF CODE. AN NRC INSPECTION FOUND THAT SADDLES HAVE BEEN WELDED TO CLASS II PIPING WITHOUT VERIFICATION OF THE SADDLE MATERIAL AND WITHOUT NONDESTRUCTIVE EXAMINATION OF THE WELDS. THE VENDOR'S INTERPRETATION OF ANSI B31.7 WAS THAT NO VIOLATION HAD OCCURRED. NEVERTHELESS, THE SADDLE MATERIAL HAS NOW BEEN VERIFIED AND THE WELDS EXAMINED NONDESTRUCTIVELY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CODES AND STANDARDS + WELDS + MATERIAL + TEST, NONDESTRUCTIVE + FAILURE, ADMINISTRATIVE CONTROL + CALVERT CLIFFS 1 (PWR) + CALVERT CLIFFS 2 (PWR) + CONSTRUCTION + IDENTIFICATION

100430
 WIDE RANGE NUCLEAR INSTRUMENTATION FAILS AT CALVERT CLIFFS 1
 BALTIMORE GAS AND ELECTRIC COMPANY, MD.
 3 PAGES, LETTER WITH AD REPORT 75/17 TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, REGION 1, MARCH 4, 1975, DOCKET 50-317, TYPE--PWR, NRG--COMB., AE--BECHTEL

CAUSE - POWER SUPPLY FAILURE. WHILE THE PLANT WAS OPERATING AT 50% POWER, A HIGH VOLTAGE ALARM WAS RECEIVED ON 1 OF THE 4 WIDE RANGE NUCLEAR INSTRUMENTATION CHANNELS. THE 415 VOL POWER SUPPLY HAD FAILED. THE DEFECTIVE POWER SUPPLY WAS REPLACED. FOUR PREVIOUS FAILURES OF POWER SUPPLIES HAVE OCCURRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ELECTRIC POWER + FAILURE, INSTRUMENT + REACTOR STARTUP EXPERIENCE + INSTRUMENT, WIDE RANGE + CALVERT CLIFFS 1 (PWR)

106872

SERVICE WATER SYSTEM PIPING CLASSIFICATION IN ERROR AT CALVERT CLIFFS 1
BALTIMORE GAS & ELECTRIC CO., MD.
2 PAGES, LETTER WITH NO REPORT 75/23 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, MARCH 7, 1975, Docket 50-317, TYPE--
PWR, NRC-COMB., AE--BECHTEL

CAUSE - DESIGN ERROR. DURING AN ADJUST ON UNIT 2, THE INSPECTOR FOUND THAT SERVICE WATER SYSTEM PIPING CLASS NO-22 WAS NOT SHOWN ON THE Q-LIST OF SAFETY-RELATED ITEMS IN THE CONTAINMENT. THIS ALSO APPLIES TO UNIT 1. THIS OMISSION IS AN ERROR. CERTIFICATION OF RECORDS FOR THE NO-22 PIPING IN THE CONTAINMENT HAS BEEN OBTAINED AND DOCUMENTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, DESIGN ERROR + QUALITY ASSURANCE + AUXILIARY COOLING + CALVERT CLIFFS 1 (PWR) + CERTIFICATION + CONSTRUCTION + PIPES AND PIPE FITTINGS

100910

LINEAR RANGE NUCLEAR INSTRUMENTATION FAILS AT CALVERT CLIFFS 1
BALTIMORE GAS & ELECTRIC CO., MD.
3 PAGES, LETTER WITH NO REPORT 75/23 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, MARCH 17, 1975, Docket 50-317, TYPE--PWR, NRC-COMB., AE--BECHTEL

CAUSE - POWER SUPPLY FAILURE. WHILE THE UNIT WAS OPERATING AT 20% POWER, THE OPERATOR RECEIVED THE HIGH VOLTAGE ALARM FOR CHANNEL A LINEAR RANGE NUCLEAR INSTRUMENTATION AND NOTED THAT THE INDICATED HIGH VOLTAGE WAS DECREASING. THE 15 VDC POWER SUPPLY HAD FAILED. IT WAS REPLACED. FIVE PREVIOUS FAILURES OF THIS COMPONENT HAVE OCCURRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + INSTRUMENT, NUCLEAR + FAILURE, INSTRUMENT + REACTOR STARTUP EXPERIENCE + INSTRUMENT, LINEAR + CALVERT CLIFFS 1 (PWR)

101159

AUXILIARY HIGH PRESSURE SAFETY INJECTION VALVE FAILS TO OPEN AT CALVERT CLIFFS 1
BALTIMORE GAS & ELECTRIC COMPANY
2 PAGES, LETTER WITH NO REPORT 75/25 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, MARCH 20, 1975, Docket 50-317, TYPE--PWR, NRC-COMB., AE--BECHTEL

CAUSE - TARNISHED SWITCH CONTACTS. DURING TESTING WITH THE REACTOR AT 60% POWER, AN AUXILIARY HIGH PRESSURE SAFETY INJECTION STOP VALVE FAILED TO OPEN WHEN ITS MOTOR OPERATOR RECEIVED AN OPEN SIGNAL. WHEN MANUALLY OPERATED, THE VALVE MOVED FREELY ITS FULL LENGTH OF TRAVEL. TARNISHED TORQUE SWITCH CONTACTS WERE FOUND TO PREVENT THE VALVE FROM OPENING PAST THE POINT WHERE THE CLOSE LIMIT SWITCH PARALLEL CONTACTS OPENED. THESE CONTACTS WERE CLEANED WITH A BURNISHING TOOL AND THE VALVE RETURNED TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, EQUIPMENT + SAFETY INJECTION + INSTRUMENT, SWITCH + REACTOR STARTUP EXPERIENCE + TEST, SYSTEM OPERABILITY + FAILURE, MAINTENANCE ERROR + CALVERT CLIFFS 1 (PWR) + VALVE OPERATORS + VALVES

101451

REACTOR COOLANT PUMP UPPER SEAL PRESSURE SENSING LINE LEAKS AT CALVERT CLIFFS 1
BALTIMORE GAS & ELECTRIC COMPANY
3 PAGES, LETTER WITH NO REPORT 75/25 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, MARCH 25, 1975, Docket 50-317, TYPE--PWR, NRC-COMB., AE--BECHTEL

CAUSE - CRACKED WELD. WHEN THE COMPUTED REACTOR COOLANT LEAKAGE RATE INCREASED FROM 0.3 TO 0.8 GPM, A CONTAINMENT ENTRY WAS MADE TO LOCATE THE LEAK. THE REACTOR TRIPPED ABOUT THIS TIME. THE LEAKAGE WAS FOUND TO BE FROM A CRACKED WELD ON A REACTOR COOLANT PUMP SHAFT UPPER SEAL PRESSURE SENSING LINE. THE LEAK WAS ISOLATED AND THE DEFECTIVE WELD REPAIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, PIPE + WELDS + MAIN COOLING SYSTEM + LEAK + CALVERT CLIFFS 1 (PWR) + SENSORS, PRESSURE + PIPES AND PIPE FITTINGS

101453

CONTAINMENT COOLER FAILS TO START IN SLOW SPEED AT CALVERT CLIFFS 1
BALTIMORE GAS & ELECTRIC COMPANY, MD.
3 PAGES, LETTER WITH NO REPORT 75/26 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, MARCH 25, 1975, Docket 50-317, TYPE--PWR, NRC-COMB., AE--BECHTEL

CAUSE - BREAKER TRIPPED OPEN. DURING TESTING OF THE CONTAINMENT SPRAY ACTUATION SIGNAL LOGIC WITH THE REACTOR AT 70% POWER, A CONTAINMENT COOLER FAN SUPPLY BREAKER TRIPPED OPEN INSTEAD OF

102158 CONTINUOUS

THE FAN SHIFTS FROM FAST TO SLOW SPEED. MECHANICAL INTERLOCKS PREVENT THE SLOW AND FAST SPEED CONTACTS FROM CLOSING SIMULTANEOUSLY. THE FAST SPEED SHOOTING CONTACTS ARE ONLY ELECTRICALLY INTERLOCKED TO THE SLOW SPEED CONTACTS THROUGH AUXILIARY RELAYS. SLUGGISHNESS IN THESE RELAYS COULD CAUSE THE SLOW SPEED CONTACTS TO CLOSE BEFORE THE FAST SPEED ARC HAS TERMINATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTAINMENT AIR COOLING - TEST, SYSTEM OPERABILITY - FAILURE, DESIGN ERROR - CALVERT CLIFFS 1 (PWR) - BREAKER - BLOWERS

102170

CONTAINMENT COOLING FAN FAILS AT CALVERT CLIFFS 1

BALTIMORE GAS & ELECTRIC COMPANY, MD.

3 PAGES, LETTER WITH AD REPORT 75/27 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, APRIL 3, 1975, DOCKET 50-317, TYPE--PWR, NRC--COMB., AE--BECHTEL

CAUSE - STARTER COIL FAILS. THE OPERATOR NOTED IN THE COMPUTER THAT A CONTAINMENT COOLER HAD STOPPED. THE COOLANT FUSES TO THE COOLING FAN WERE BLOWN AS A RESULT OF A FAILED STARTER MOTOR COIL FOR THE F-1 MOTOR. AS A RESULT OF PREVIOUS FAILURES, THE VENDOR WAS CONTACTED. SUFFICIENT REPLACEMENT COILS HAVE BEEN RECEIVED TO CHANGE OUT ALL COILS ASSOCIATED WITH UNIT 1 CONTAINMENT COOLERS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT - CONTAINMENT AIR COOLING - MODIFICATION - REACTOR STARTUP EXPERIENCE - FAILURE, DESIGN ERROR - CALVERT CLIFFS 1 (PWR) - MOTORS - BLOWERS

102167

EMERGENCY DIESEL GENERATOR SPEED CONTROL FAILS AT CALVERT CLIFFS 1

BALTIMORE GAS & ELECTRIC COMPANY

3 PAGES, LETTER WITH AD REPORT 75/29 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, APRIL 9, 1975, DOCKET 50-317, TYPE--PWR, NRC--COMB., AE--BECHTEL

CAUSE - BLOWN FUSE. DURING A LOSS OF OFF-SITE POWER TEST, AN EMERGENCY DIESEL SPEED CONTROL BECAME EXHAUSTED. A FUSE FOR THE SECONDARY OF POTENTIAL TRANSFORMER 3 OPENED. THIS TRANSFORMER IS THE POWER SOURCE FOR THE ELECTRIC GOVERNOR ASSEMBLY WHICH CONTROLS THE DIESEL GENERATOR SPEED. NO CAUSE COULD BE FOUND FOR THE BLOWN FUSE. WHEN THE FUSE WAS REPLACED, THE DIESEL GENERATOR OPERATED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT - INSTRUMENT, PROTECTIVE - REACTOR STARTUP EXPERIENCE - TEST, SYSTEM OPERABILITY - CALVERT CLIFFS 1 (PWR) - ENGINES, INTERNAL COMBUSTION - GENERATOR, DIESEL

102168

TURBINE RUNBACK CIRCUITS INCAPACITATED AT CALVERT CLIFFS 1

BALTIMORE GAS & ELECTRIC COMPANY, MD.

3 PAGES, LETTER WITH AD REPORT 75/28 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, APRIL 13, 1975, DOCKET 50-317, TYPE--PWR, NRC--COMB., AE--BECHTEL

CAUSE - IMPROPER SETTINGS. DURING TRAINING WITH THE REACTOR AT 80% POWER, AN OPERATOR NOTED THAT TWO TURBINE RUNBACK ACTUATION CIRCUITS WERE NOT ARMED. THE FUSES IN THE CONTROL PANEL HAD BEEN REMOVED AND ONE PNEUMATIC SUPPLY FUSE WAS BLOWN FOR ONE CIRCUIT. THESE PROBLEMS ARE THOUGHT TO BE FROM CONSTRUCTION ACTIVITY IN THE AREA. ALSO, THE SETTING OF THE PRESSURE DEVICES WHICH ARM THE CIRCUIT WERE SET TOO HIGH IN BOTH CIRCUITS. FUSES WERE REPLACED. THE SETTINGS WERE ACCORDING TO THE SETPOINT INDEX. THESE VALUES WERE LOWERED TO A VALUE CONSISTENT WITH THE TECH SPECS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INSTRUMENT, PROTECTIVE - REACTOR STARTUP EXPERIENCE - FAILURE, ADMINISTRATIVE CONTROL - TURBINE - CALVERT CLIFFS 1 (PWR) - SET POINT

102159

UNPLANNED RELEASE OF MISCELLANEOUS WASTE RECEIVER TANK AT CALVERT CLIFFS 1

BALTIMORE GAS & ELECTRIC COMPANY, MD.

3 PAGES, LETTER WITH AD REPORT 75/30 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, APRIL 17, 1975, DOCKET 50-317, TYPE--PWR, NRC--COMB., AE--BECHTEL

CAUSE - IMPROPER VALVE LINEUP. WHILE TERMINATING A ROUTINE RELEASE OF THE CONTENTS OF A REACTOR COOLANT WASTE MONITOR TANK, THE OPERATOR NOTED THE VALVE IN THE INLET PIPE FROM THE MISCELLANEOUS WASTE RECEIVER TANK WAS OPEN. THE CONTENTS OF THIS TANK HAD BEEN EMPTIED ALSO. THE WRT HAD NOT BEEN SAMPLED. A WEEKLY COMPOSITE SAMPLE WAS ANALYZED AND USED TO CALCULATE THE RELEASE. RADIATION MONITOR READING ON THE DISCHARGE PIPE WERE AS PREDICTED; THEREFORE, THIS

10289 PLUTONIUM

RELEASE WAS BELIEVED TO BE OF LITTLE SIGNIFICANCE. THE APPARENT CAUSE OF THIS OCCURRENCE WAS FAILURE OF THE OPERATOR TO PROPERLY LINE UP THE HONEY BEE DISCHARGE AS SPECIFIED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATION ERROR + PROCEDURES AND MANUALS + WASTE DISPOSAL + WASTE HANDLING + REACTION STARTUP EXPERIENCE + RADIOACTIVITY RELEASE + CALVERT CLIFFS 1 (PWR)

10280

SAFETY INJECTION VALVE FAILS TO OPEN AT CALVERT CLIFFS 1

BALTIMORE GAS & ELECTRIC COMPANY, MD.

3 PAGES, LETTER WITH AD REPORT 75/31 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, APRIL 17, 1975.

DOCKET 50-317, TYPE--PWR, NRC--COMB., AE--DECHTEL

CAUSE - LOOSE ELECTRICAL CONTACTS. DURING TESTING WITH THE REACTOR AT 100% POWER, AN AUXILIARY HIGH PRESSURE SAFETY INJECTION MAJOR STOP VALVE OPENED ONLY ABOUT 20% OF ITS NORMAL TRAVEL AND STOPPED. LOOSE ELECTRICAL CONTACTS IN THE TRIP SWITCH PREVENTED THE VALVE FROM OPENING. REASONING OCCURRED ON THE OPERATING CONTACTS. THE LOOSE NUT ON THE CONNECTION WAS TIGHTENED AND THE CONTACTS WERE CLEANED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SAFETY INJECTION + REACTOR STARTUP EXPERIENCE + TEST, SYSTEM PENABILITY + FAILURE, INSTALLATION ERROR + CALVERT CLIFFS 1 (PWR) + CABLES AND CONNECTIONS + VALVES

10281

CONDENSER TEMPERATURE GRADIENT EXCEEDS LIMIT AT CALVERT CLIFFS 1

BALTIMORE GAS & ELECTRIC COMPANY, MD.

2 PAGES, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, APRIL 17, 1975, DOCKET 50-317, TYPE--PWR,

NRC--COMB., AE--DECHTEL

CAUSE - ABNORMALLY LOW TEMP. TWO DAYS AFTER REACTOR POWER REACHED 100%, THE OUTLET CIRCULATING WATER TEMPERATURE ERROR WAS DETERMINED EXPERIMENTALLY FOR THIS POWER. TEMPERATURE SENSOR READINGS WERE 1.0 F ABOVE ACTUAL AVERAGE TEMPERATURE. AT LOWER POWER LEVELS READINGS WERE 1.2 TO 1.8 F ABOVE ACTUAL TEMPERATURE. WHEN THIS CORRECTION FACTOR WAS APPLIED TO CONDENSER DELTA T READING AT 100% POWER, THE TEMPERATURE GRADIENT WAS FOUND TO HAVE EXCEEDED THE 10 F LIMIT. AT THIS TIME ABNORMALLY HIGH NORTH WINDS, PERSISTING FOR SEVERAL DAYS, CAUSED THE LOWEST TIDES IN Chesapeake Bay in 67 YEARS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TEMPERATURE GRADIENT + REACTOR STARTUP EXPERIENCE + FLOW + WEATHER, SEVERE + CALVERT CLIFFS 1 (PWR) + CONDENSER COOLING SYSTEM

10332

WIDE RANGE NUCLEAR INSTRUMENT FAILS AT CALVERT CLIFFS 1

BALTIMORE GAS & ELECTRIC COMPANY, MD.

3 PAGES, LETTER WITH AD 75-32 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, MAY 15, 1975, DOCKET 50-

317, TYPE--PWR, NRC--COMB., AE--DECHTEL

CAUSE - POWER SUPPLY FAILURE. WHILE THE PLANT WAS IN COLD SHUTDOWN, THE HIGH VOLTAGE ALARM WAS RECEIVED ON CHANNEL C WIDE RANGE NUCLEAR INSTRUMENTS. FAILURE OF THE 915 VDC POWER SUPPLY RESULTED IN A DECREASE OF APPLIED VOLTAGE TO THE HIGH VOLTAGE POWER SUPPLY REGULATOR. THE DEFECTIVE POWER SUPPLY WAS REPLACED AND THE CHANNEL RETURNED TO NORMAL OPERATION. THIS WAS THE FOURTH FAILURE OF THIS TYPE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) + INSTRUMENT, WIDE RANGE + ELECTRIC POWER + FAILURE, COMPONENT + FAILURE, INSTRUMENT + REACTOR STARTUP EXPERIENCE

10334

WIDE RANGE NUCLEAR INSTRUMENT FAILS AT CALVERT CLIFFS 1

BALTIMORE GAS & ELECTRIC COMPANY, MD.

3 PAGES, LETTER WITH AD 75-34 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, MAY 15, 1975, DOCKET 50-

317, TYPE--PWR, NRC--COMB., AE--DECHTEL

CAUSE - UNKNOWN. WHILE THE REACTOR WAS OPERATING AT 60% POWER, THE CONTROL ROOM OPERATOR NOTICED THAT WIDE-RANGE NUCLEAR INSTRUMENTATION CHANNEL C WAS READING LOW. WHEN THE INSTRUMENT DRAWER WAS PULLED OUT FOR THE INVESTIGATION, IT WAS FOUND TO BE OPERATING NORMALLY. A BAD ELECTRICAL CONNECTION WITHIN THE DRAWER WAS APPARENTLY THE TROUBLE. THE DRAWER WAS RETURNED TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

103114 *CONTINUED*
CALVERT CLIFFS 1 (PWR) * INSTRUMENT, POWER RANGE * FAILURE, COMPONENT * CABLES AND CONNECTORS * REACTOR
STARTUP EXPERIENCE

103119
COLD LEG TEMPERATURE INPUT TO THERMAL POWER CALCULATOR FAILS AT CALVERT CLIFFS 1
BALTIMORE GAS & ELECTRIC COMPANY, MD.
3 PAGES, LETTER WITH AD 75-33 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, MAY 15, 1975, DOCKET 50-
317, TYPE--PWR, MFG--COMB., AE--BECHTEL

CAUSE - POOR ELECTRIC CONNECTION. DURING AN INVESTIGATION INTO THE THERMAL POWER CALCULATOR
MISFE, IT WAS NOTED THAT THE COLD LEG TEMPERATURE INPUT FROM A TEMPERATURE TRANSMITTER WAS NOT
PRESENT. IT WAS APPARENTLY CAUSED BY A POOR ELECTRICAL CONNECTION IN THE FIELD CIRCUITRY.
DURING TESTING, THE MALFUNCTION DISAPPEARED. THE PROBLEM HAS NOT REOCCURED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) * INSTRUMENT, POWER RANGE * FAILURE, COMPONENT * SENSORS, TEMPERATURE * CABLES AND
CONNECTORS * REACTOR STARTUP EXPERIENCE * TEST, SYSTEM OPERABILITY

103120
CONTAINMENT ISOLATION VALVE FOUND INSTALLED IMPROPERLY AT CALVERT CLIFFS 1
BALTIMORE GAS AND ELECTRIC COMPANY, MD.
2 PAGES, LETTER TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, REGION 1, MAY 21, 1975, DOCKET 50-317, TYPE--PWR,
MFG--COMB., AE--BECHTEL

CAUSE - INSTALLATION ERROR. DURING A COLD SHUTDOWN, THE CONTAINMENT ISOLATION VALVE ON THE
COMPONENT COOLING WATER RETURN LINE WAS FOUND TO FAIL IN THE OPEN POSITION UPON LOSS OF AIR. THE
VALVE SHOULD HAVE CLOSED. THE PSAR HAS INCONSISTENCIES FOR THIS VALVE. THE VALVE WAS MODIFIED
TO FAIL CLOSED. PSAR WILL BE CORRECTED AT THE NEXT UPDATE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) * VALVES * CONTAINMENT ISOLATION * AUXILIARY COOLING SYSTEM * FAILURE, INSTALLATION
ERROR * REACTOR STARTUP EXPERIENCE

103127
SAFETY INJECTION INADVERTENTLY INITIATED AT CALVERT CLIFFS 1
BALTIMORE GAS AND ELECTRIC COMPANY, MD.
4 PAGES, LETTER WITH AD 75-35 TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, REGION 1, MAY 22, 1975, DOCKET 50-
317, TYPE--PWR, MFG--COMB., AE--BECHTEL

CAUSE - BYPASS VALVE FAILURES. THE REACTOR WAS TRIPPED FROM 100% POWER ON A SIMULATED LOSS OF
LOAD. THE 4 TURBINE BYPASS VALVES OPENED AS DESIGNED. WHEN THE PRESSURE RETURNED TO 900 PSIA, 2
OF THE VALVES FAILED TO CLOSE RESULTING IN A SAFETY INJECTION ACTUATION SIGNAL AND A STEAM
GENERATOR ISOLATION SIGNAL. DURING ISOLATION OF THE 2 VALVES, AN ISOLATION VALVE COULD NOT BE
CLOSED BECAUSE ITS SHAFT/HANDWHEEL KEY WAS MISSING. THE PLUG IN THE BYPASS VALVES HAD FRACTURED.
NEW PLUGS OF A MORE DUCTILE MATERIAL WILL BE INSTALLED TO AVOID THIS METALLURGICAL FAILURE. THE
KEYS WERE STAKED TO PREVENT THEIR VIBRATING OUT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) * VALVES * BYPASS * TURBINE * TEST, SYSTEM OPERABILITY * FAILURE, COMPONENT *
FAILURE, DESIGN ERROR * BRITTLE FRACTURE * MATERIAL * MODIFICATION * REACTOR STARTUP EXPERIENCE * SAFETY
INJECTION

103133
HOT LEG TEMPERATURE TO THERMAL POWER CALCULATOR FAILS AT CALVERT CLIFFS 1
BALTIMORE GAS & ELECTRIC COMPANY, MD.
3 PAGES, LETTER WITH AD 75-37 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, MAY 22, 1975, DOCKET 50-
317, TYPE--PWR, MFG--COMB., AE--BECHTEL

CAUSE - LOOSE WIRE ON SELECTOR SWITCH. DURING A TEST WITH THE REACTOR AT 97% POWER, THE HOT LEG
TEMPERATURE INPUT TO CHANNEL C THERMAL POWER CALCULATOR WAS FOUND TO BE LOW. THERE WAS A LOOSE
WIRE ON THE THERMAL MARGIN/LOW PRESSURE CALCULATOR MODE SELECTOR SWITCH. THE LOOSE WIRE WAS
RESOLDERED AND THE TEST COMPLETED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) * SENSORS, TEMPERATURE * INSTRUMENTS, MISC. * INSTRUMENT, POWER RANGE * CABLES AND
CONNECTORS * FAILURE, FABRICATION ERROR * TEST, SYSTEM OPERABILITY * REACTOR STARTUP EXPERIENCE

103125

103125 *CONTINUED*

FEEDWATER HEADER STOP VALVES FAIL AT CALVERT CLIFFS 1
BALTIMORE GAS & ELECTRIC COMPANY, MD.

3 PAGES, LETTER WITH AG 75-36 TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, REGION 1, MAY 23, 1975, DOCKET 50-317, TYPE--PWR, NRG--COMB., AE--BECHTEL

CAUSE - QUENCHING OF HEADER STEAM VOIDS. AFTER A LOSS-OF-FEEDWATER TRIP, 3 WATER HAMMERS WERE EXPERIENCED IN THE FEEDWATER PIPING DAMAGING THE MOTOR OPERATORS OF BOTH FEEDWATER HEADER STOP VALVES. THE MANUAL HANDWHEEL ON ONE WAS ALSO DAMAGED PREVENTING MANUAL OPERATION OF THE VALVE. THE APPARENT CAUSE WAS QUENCHING OF STEAM VOIDS FORMED IN THE FEED HEADER WHILE RE-ESTABLISHING STEAM GENERATOR LEVELS FOLLOWING THE TRIP. THE VALVE OPERATORS WERE REPLACED AND RETURNED TO SERVICE. PROCEDURES WERE MODIFIED TO USE THE AUXILIARY FEED SYSTEM ONLY AT STEAM GENERATOR LEVELS IN THE AREA OF THE MAIN FEED RING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) + VALVES + FEEDWATER + VALVE OPERATORS + HYDRAULIC EFFECT + DAMAGE + FAILURE. EQUIPMENT + REACTOR STARTUP EXPERIENCE

103491

WIDE RANGE NUCLEAR INSTRUMENTATION FAILS AT CALVERT CLIFFS 1
BALTIMORE GAS & ELECTRIC COMPANY, MD.

3 PAGES, LETTER WITH AG 75-38 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, JUNE 12, 1975, DOCKET 50-317, TYPE--PWR, NRG--COMB., AE--BECHTEL

CAUSE - PRE-AMP MALFUNCTION. WHILE OPERATING THE REACTOR AT 100% POWER, THE OPERATOR NOTICED CHANNEL C WIDE RANGE LOG POWER INDICATION SHIFTING FROM 8-POWER TO CPS AND THE METER READING LOW. THE APPARENT CAUSE WAS TRACED TO A MALFUNCTION IN THE PRE-AMPLIFIER THAT DISAPPEARED SEVERAL HOURS AFTER THE INVESTIGATION HAD BEGUN. THE SYMPTOMS COULD NOT BE REPRODUCED. THE PRE-AMP WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) + INSTRUMENT, AMPLIFIER + INSTRUMENT, POWER RANGE + INSTRUMENT, LOGARITHMIC + ELECTRONIC FUNCTION UNITS + FAILURE, INSTRUMENT

104043

TEST PROCEDURAL REQUIREMENT VIOLATES TECH SPECS AT CALVERT CLIFFS 1

BALTIMORE GAS & ELECTRIC COMPANY, MD.

2 PAGES, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, JUNE 19, 1975, DOCKET 50-317, TYPE--PWR, NRG--COMB., AE--BECHTEL

CAUSE - INSUFFICIENT REVIEW. DURING TESTING OF THE ENGINEERED SAFETY FEATURES ACTUATION SYSTEM, THE PROCEDURE REQUIRED THAT BOTH LOGIC CABINETS A1 AND B1 BE BLOCKED SIMULTANEOUSLY. THIS NEGATED THE RESPONSES OF ALL 4 PRESSURIZER PRESSURE SENSOR CHANNELS VIOLATING TECH SPECS. THE CAUSES OF THIS WERE (1) AN INADEQUACY IN TEST PROCEDURE REVIEW PROCESS AND (2) LACK OF CORRECTIVE ACTION BY OPERATIONS PERSONNEL. PROCEDURES HAVE BEEN REVISED. OPERATIONS GROUP REMINDED TO REPORT ALL TECH SPEC VIOLATIONS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) + PROCEDURES AND MANUALS + TESTING + REVIEW + SENSORS, PRESSURE + FAILURE, OPERATOR ERROR + FAILURE, ADMINISTRATIVE CONTROL

105706

ATMOSPHERIC STEAM DUMP VALVE ENCLOSURE NOT INSTALLED AT CALVERT CLIFFS 1

BALTIMORE GAS & ELECTRIC COMPANY, MD.

2 PAGES, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, JUNE 20, 1975, DOCKET 50-317, TYPE--PWR, NRG--COMB., AE--BECHTEL

CAUSE - DESIGN OVERSIGHT. BECHTEL ADVISED THE UTILITY THAT THE STEAM SEAL ON THE ATMOSPHERIC STEAM DUMP VALVE ENCLOSURE HAD NOT BEEN INSTALLED. THE DESIGN CALLED FOR LINK-TYPE SEALS BUT THESE WERE DELETED WHEN ANALYSIS INDICATED THESE MIGHT CAUSE AN OVERSTRESS CONDITION. BOOT-TYPE SEALS OF MOVED FIBERGLASS WILL BE INSTALLED. LINK SEALS HAD NOT BEEN SHOWN ON THE STRESS ISOMETRIC DRAWING. DURING A REVIEW SEALS FOR THIS ENCLOSURE WERE OVERLOOKED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) + SEAL + CONTAINMENT PENETRATION, PIPE + STRESS ANALYSIS + FAILURE, DESIGN ERROR + MODIFICATION + INSTALLATION

106399

CONTAINMENT PRESSURE INPUT TO REACTOR PROTECTIVE SYSTEM FAILS AT CALVERT CLIFFS 1

BALTIMORE GAS & ELECTRIC COMPANY, MD.

3 PAGES, LETTER WITH AOR 75-40 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, JUNE 27, 1975, DOCKET 50-

104300 CONTINUED
 317, TYPE--PMR, MFG--COMB., AE--BECHTEL

CAUSE - MECHANICAL DAMAGE. THE CONTROL ROOM OPERATOR NOTED FREQUENT SPURIOUS HIGH CONTAINMENT PRESSURE TRIP ALARMS ON APS CHANNEL D WHILE THE REACTOR WAS AT 90% POWER. FAILURE WAS TRACED TO AN ISOLATION TRANSMITTER 127% CALIBRATION. MECHANICAL DAMAGE HAD BEEN SUSTAINED BY A CIGUET/RESISTOR SOLDER JOINT. THE JOINT IF DAMAGE IS UNWARRANTED. THE DEFECTIVE MODULE WAS REPLACED AND APS CHANNEL D RETURNED TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PMR) + SENSORS, PRESSURE + CABLES AND CONNECTIONS + DAMAGE + FAILURE, INSTRUMENT + REACTOR SAFETY SYSTEM + CONTAINMENT + NOISE + ELECTRONIC FUNCTION UNITS

104300
 WIDE-RANGE NUCLEAR INSTRUMENT FAILS AT CALVERT CLIFFS 1
 BALTIMORE GAS & ELECTRIC COMPANY, MD.

1 PAGE, LETTER WITH ADM 75-41 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, JULY 3, 1975, DOCKET 50-317, TYPE--PMR, MFG--COMB., AE--BECHTEL

CAUSE - DEFECTIVE PRE-AMPLIFIER. THE CONTROL ROOM OPERATOR RECEIVED CHANNEL C START-UP RATE PRE-TRIP ALARM, INSTRUMENT DRAWER HIGH VOLTAGE ALARM, AND ERRATIC COUNT-RATE INDICATIONS. FAILURES RESULTED FROM A DEFECTIVE PRE-AMPLIFIER. FAILURE CAUSED EXCESSIVE CURRENT FLOW FROM THE 15 VDC PUMP SUPPLY. THE REACTOR WAS OPERATING AT 90% POWER. THE INVESTIGATION WILL CONTINUE WHEN THE PLANT IS SHUTDOWN AND ACCESS TO THE PRE-AMPLIFIER CAN BE GAINED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PMR) + INSTRUMENT, AMPLIFIER + INSTRUMENT, WIDE RANGE + INSTRUMENT, NUCLEAR + REACTOR SAFETY SYSTEM + FAILURE, INSTRUMENT + ELECTRONIC FUNCTION UNITS + INSTRUMENT, STARTUP RANGE

104325
 UNPLANNED RELEASE OF RADIOACTIVE MATERIAL OCCURS AT CALVERT CLIFFS 1
 BALTIMORE GAS & ELECTRIC COMPANY, MD.

3 PAGES, LETTER WITH ADM 75-42 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, JULY 15, 1975, DOCKET 50-317, TYPE--PMR, MFG--COMB., AE--BECHTEL

CAUSE - CHARGING PUMP PACKING LEAK. WHILE OPERATING AT 90% POWER, A HIGH ALARM WAS RECEIVED FROM THE FUEL HANDLING AREA MONITORS. THE 12 WORKERS EXITING UNIT 1 SIDE OF THE AUXILIARY BUILDING WERE FOUND TO BE SLIGHTLY CONTAMINATED. ALL WERE DECONTAMINATED. TWO CHARGING PUMPS WERE LEAKING EXCESSIVELY AND RADIOACTIVE GASES WERE BEING RELEASED FROM THE LEAKAGE. THE PUMPS WERE ISOLATED AND REPAIRED. THEY WERE RETURNED TO SERVICE WITHIN 12 HOURS. ABOUT 100 CI OF XE-133 AND 3 CI OF KI-135 WERE RELEASED DURING THIS INCIDENT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PMR) + RADIOACTIVE RELEASE + PUMPS + SEAL + LEAK + FRESHWATER + REACTOR COOLANT + CONTAMINATION + FAILURE, EQUIPMENT

104820
 CONTAINMENT RADIATION MONITOR FAILS AT CALVERT CLIFFS 1
 BALTIMORE GAS & ELECTRIC COMPANY

3 PGS, LTR WITH ADM 75-43 TO NRC OFFICE OF I & E, REGION 1, JULY 16, 1975, DOCKET 50-317, TYPE--PMR, MFG--COMB., AE--BECHTEL

CAUSE - DEFECTIVE GEIGER-MUELLER TUBE. ON JULY 7, 1 OF THE 4 CONTAINMENT RADIATION MONITORS WAS FUNCTIONING ERRATICALLY WITH READINGS HIGH ENOUGH TO PRODUCE ALARMS. THE GEIGER-MUELLER TUBE USED AS A DETECTOR WAS DEFECTIVE. IT WAS REPLACED DURING THE OUTAGE OF JULY 11.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PMR) + RADIATION MONITORS + CONTAINMENT + FAILURE, INSTRUMENT

105733
 RADIOACTIVITY IN WASTE GAS PROCESSING AREA EXCEEDS LIMIT AT CALVERT CLIFFS 1
 BALTIMORE GAS & ELECTRIC COMPANY

2 PGS, LTR TO NRC OFFICE OF I & E, REGION 1, JULY 23, 1975, DOCKET 50-317, TYPE--PMR, MFG--COMB., AE--BECHTEL

CAUSE - SEVERAL SMALL LEAKS. ON JUNE 17, A PERSONNEL MONITORING FRISKER, LOCATED ADJACENT TO THE WASTE GAS PROCESSING AREA, WAS FOUND TO BE ALARMING. XE-133 CONCENTRATION WAS ABOUT 1500 TIMES THE LIMIT. IODINE AND PARTICULATE ISOTOPES DID NOT EXCEED LIMITS. HIGH AIRBORNE RADIOACTIVITY WAS CONFINED TO THIS AREA. SEVERAL SMALL LEAKS, MOSTLY IN VALVE PACKING AND TUBING CONNECTIONS, WERE DETECTED AND REPAIRED OVER A 7 DAY PERIOD. AIRBORNE RADIOACTIVITY LEVELS DECREASED TO NORMAL. WHOLE BODY EXPOSURES OF MAINTENANCE WORKERS WERE WELL BELOW LIMITS.

105733 PLUTINIUM
 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) + RADIUMINE RELEASE + NEON + WASTE TREATMENT, G. S. + COMPARTMENT + PLEAK + VALVES +
 TUBING

100819
 UNPLANNED RELEASE OF RADIOACTIVE GAS AT CALVERT CLIFFS 1
 BALTIMORE GAS & ELECTRIC COMPANY
 3 PGS, LHM #/AIR 75-74 TO NRC OFFICE OF I & E REGION 1, JULY 28, 1975, DOCKET 50-317, TYPE--PWR, NRG--COMB.,
 AE--BECHTEL

CAUSE - VALVE LEFT OPEN AND PUMP DIAPHRAGM FAILURE. WHILE THE REACTOR WAS OPERATING AT 998
 POWER, A HIGH ALARM WAS RECEIVED ON THE U-I WATER AREA VENTILATION RADIOGAS MONITOR. GAS WAS
 LEAKING FROM A WASTE GAS COMPRESSOR. THE DIAPHRAGM WAS REPLACED AND THE COMPRESSOR RETURNED TO
 SERVICE. ALSO, A VOLUME CONTROL TANK VAPOR SPACE SAMPLE VALVE IN THE PRIMARY SAMPLE HOOD WAS
 INADEQUATELY NOT COMPLETELY CLOSED FOLLOWING SAMPLING. THE OPEN VALVE ALLOWED RADIOGAS TO LEAK
 THROUGH A SECTION OF SURGICAL TUBING WHICH HAD BEEN REPEATEDLY PERFORATED BY A GAS SAMPLING
 STRINGS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) + RADIUMINE RELEASE + FAILURE, EQUIPMENT + FAILURE, OPERATOR ERROR + SAMPLING + WASTE
 HANDLING

104975
 UNPLANNED RELEASE OF REACTOR COOLANT WASTE MONITOR TANK AT CALVERT CLIFFS 1
 BALTIMORE GAS & ELECTRIC COMPANY
 3 PGS, LHM #/AIR 75-65 TO NRC OFFICE OF I & E REGION 1, JULY 31, 1975, DOCKET 50-317, TYPE--PWR, NRG--COMB.,
 AE--BECHTEL

CAUSE - IMPROPER VALVE LINE UP. DISCHARGE FROM REACTOR COOLANT WASTE MONITOR TANK 12 WAS
 TERMINATED WHEN THE EFFLUENT MONITOR READINGS WERE 700 TO 800 CPM. INSTEAD OF THE EXPECTED 230
 CPM. THE TANK WAS RESAMPLED. WHEN ANALYSIS CONFIRMED ACTIVITIES BELOW LIMITS, THE RELEASE WAS
 RESTARTED. LATER, THE OPERATOR NOTED A DECREASE IN TANK 11 BUT NOT TANK 12. THE RELEASE WAS
 TERMINATED AFTER RELEASING 11400 GALLONS. ANALYSIS OF TANK 11 SHOWED THAT 12.2 MILLICURIES HAD
 BEEN RELEASED EXCLUDING TRITIUM AND NUBLE GAS. THE OPERATOR MISREAD THE VALVE NUMBERS AND
 ALLOWED THE WASTE TANK.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) + RADIOACTIVITY RELEASE + WASTE DISPOSAL + WASTE DISPOSAL, LIQUID + FAILURE, OPERATOR
 ERROR + STORAGE CONTAINER + PROCEDURES AND MANUALS

105040
 INITIATING SIGNAL FOR LOCK SEQUENCER AND SHUTDOWN SEQUENCER FAILS AT CALVERT CLIFFS 1
 BALTIMORE GAS & ELECTRIC CO., MARYLAND
 3 PGS, LETTER WITH AD REPORT 75/46 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, AUG. 5, 1975, DOCKET
 50-317, TYPE--PWR, NRG--COMB., AE--BECHTEL

CAUSE - FABRICATION ERROR IN BREAKER. WHILE TESTING DIESEL GENERATOR 21 PRIOR TO PLACING IT IN
 SERVICE ON 4 KV BUS 14, THE SHUTDOWN SEQUENCER ALARM DID NOT INITIATE. WHEN MAINTENANCE CHECKED
 THE ALARM 4 DAYS LATER, THEY FOUND THAT THE PIVOT ARM FOR THE AUXILIARY SWITCH LINKAGE OF 4 KV
 BUS BREAKER 1403, WHICH SUPPLIES THE BREAKER CLOSED SIGNAL TO THE SEQUENCERS, WAS BROKEN, THUS
 PRECLUDING INITIATION OF THE SEQUENCERS IF NEEDED. A PIN IN A PIVOT ARM OF THE LINKAGE TO THE
 AUXILIARY SWITCH MECHANISM WAS PULLED FROM ITS BACKING PLATE PREVENTING ACTUATION OF THE
 AUXILIARY SWITCH. THE PIN SPUT WELD APPARENTLY FAILED. THE BREAKER WAS REPAIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) + BREAKER + EMERGENCY POWER, ELECTRIC + TEST, SYSTEM OPERABILITY + GENERATOR, DIESEL
 + FAILURE, FABRICATION ERROR + INSTRUMENT, SWITCH + INSTRUMENT, PROTECTIVE

105290
 CONDENSER DISCHARGE TEMPERATURE EXCEEDS LIMIT AT CALVERT CLIFFS 1
 BALTIMORE GAS & ELECTRIC COMPANY
 2 PGS, LHM TO NRC OFFICE OF I & E REGION 1, AUG. 7, 1975, DOCKET 50-317, TYPE--PWR, NRG--COMB., AE--BECHTEL

CAUSE - REACTOR POWER NOT REDUCED ENOUGH. REACTOR POWER WAS REDUCED TO 928 AND CIRCULATING WATER
 PUMP WAS SHUT DOWN TO ALLOW CLEANING OF ITS CONDENSER WATER BOX. LATER, THE HOURLY FLOW-WEIGHTED
 DISCHARGE TEMPERATURE INCREASED TO 90.2 F FOR 1 HOUR EXCEEDING THE 90 F LIMIT. THE POWER WAS NOT
 REDUCED ENOUGH TO COMPENSATE FOR THE LOSS OF FLOW WHEN THE PUMP WAS SHUT DOWN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

105290 *CONTINUED*
 CALVERT CLIFFS 1 (PWR) * TEMPERATURE * CONDENSER COOLING SYSTEM * DISCHARGE * EFFLUENT * MAINTENANCE AND
 REPAIR * FAILURE, ADMINISTRATIVE CONTROL * REACTOR POWER

105513
 UNPLANNED RELEASE OF RADIOACTIVE MATERIAL AT CALVERT CLIFFS 1
 BALTIMORE GAS & ELECTRIC COMPANY
 3 PGS. LTR W/AD 75-47 TO NRC OFFICE OF I & E, REGION 1, AUG. 12, 1975, DOCKET 50-317, TYPE--PWR, NRG--COMB.,
 AE--BECHTEL

CAUSE - LEAK IN CHARGING PUMP PACKING. WHILE THE REACTOR WAS OPERATING AT 98% POWER, A HIGH
 ALARM WAS RECEIVED ON THE U-1 WASTE AREA VENTILATION RADIOGAS MONITOR. GASEOUS RADIOACTIVITY
 WAS BEING RELEASED VIA LEAKAGE OF REACTOR COOLANT PAST THE CHEVRON PLUNGER PACKING OF CHARGING
 PUMP 13. THE CHARGING PUMP WAS REMOVED FROM SERVICE AND REPAIRED PRIOR TO BEING RETURNED TO
 SERVICE. ABOUT 4 CI OF Xe-133 AND 0.5 CI OF Xe-135 WERE RELEASED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) * AIRBORNE RELEASE * LEAK * PUMPS * FEEDWATER * SEAL * REACTOR COOLANT * FAILURE,
 EQUIPMENT

105512
 CONDENSER TEMPERATURE RISE EXCESSIVE AT CALVERT CLIFFS 1
 BALTIMORE GAS & ELECTRIC COMPANY
 3 PGS. LTR TO NRC OFFICE OF I & E, REGION 1, AUG. 14, 1975, DOCKET 50-317, TYPE--PWR, NRG--COMB., AE--BECHTEL

CAUSE - FISH IMPINGEMENT ON INTAKE SCREENS. WHILE OPERATING AT 98% POWER, A LARGE INFLUX OF FISH
 ON THE INTAKE SCREENS CAUSED A LOSS OF SUCTION TO SALT WATER PUMP NO. 11. A SHARP RISE IN THE
 MAIN CONDENSER TEMPERATURE RISE WAS NOTICED AND POWER DECREASE WAS STARTED IMMEDIATELY. SUCTION
 TO SALT WATER PUMP NO. 12 WAS LOST 30 MINUTES LATER. THE PLANT WAS MANUALLY TRIPPED FROM 50%
 POWER DUE TO A HIGH GENERATOR STATOR COOLANT TEMPERATURE RELATED TO LOSS OF SALT WATER FLOW. THE
 FLUX-WEIGHTED RISE WAS 11.5 F WHICH EXCEEDS THE LIMIT BY 1.5 F. A SUDDEN INFLUX OF A LARGE
 QUANTITY OF MEENADEN BLOCKED THE INTAKE SCREENS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) * CONDENSER COOLING SYSTEM * INTAKE * FILTER, SCREEN * ANIMAL, FISH * REACTOR
 SHUTDOWN * THERMAL TRANSIENT

106370
 RELEASE OF NOBLE GASES EXCEEDS LIMITS AT CALVERT CLIFFS 1
 BALTIMORE GAS & ELECTRIC CO., MARYLAND
 3 PGS. LTR W/AD 75-48 TO NRC OFFICE OF I & E, REGION 1, AUG. 20, 1975, DOCKET 50-317, TYPE--PWR, NRG--COMB.,
 AE--BECHTEL

CAUSE - DELIBERATE VENTING. CONTAINMENT STRUCTURE PRESSURE GRADUALLY INCREASED TO 0.9 PSIG OVER
 SEVERAL HOURS WHILE THE REACTOR WAS IN COLD SHUTDOWN. THE CONTAINMENT WAS VENTED TO ATMOSPHERE
 BY OPENING THE PURGE EXHAUST ISOLATION VALVES FOR 4 MINUTES. DURING THE FIRST MINUTE THE RELEASE
 RATE, BASED ON PRESSURE DROP MEASUREMENTS, EXCEEDED TECH SPEC LIMITS BY 48. DURING FUTURE
 VENTINGS, A PURGE VALVE WILL BE THROTTLED TO ENSURE COMPLIANCE WITH TECH SPECS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) * RELEASE RATE * AIRBORNE RELEASE * CONTAINMENT PURGE * NOBLE GAS * XENON * KRYPTON *
 FAILURE, OPERATION ERROR

106369
 REACTOR COOLANT PUMP UPPER SEAL FAILS AT CALVERT CLIFFS 1
 BALTIMORE GAS & ELECTRIC CO., MARYLAND
 3 PGS. LTR W/AD 75-49 TO NRC OFFICE OF I & E, REGION 1, AUG. 22, 1975, DOCKET 50-317, TYPE--PWR, NRG--COMB.,
 AE--BECHTEL

CAUSE - UPPER AND MIDDLE SEALS FAIL. WHILE PERFORMING A DAILY LEAKAGE CALCULATION WITH THE
 REACTOR AT 97% POWER, IT WAS NOTED THAT GROSS REACTOR COOLANT SYSTEM LEAKAGE HAD INCREASED TO
 2.7 GPM. INSPECTION AND SEAL PRESSURE INDICATIONS INDICATED A FAILURE OF REACTOR COOLANT PUMP
 VAPOR SEAL. THE UPPER AND MIDDLE SEALS HAD FAILED. THE PLANT WAS SHUT DOWN AND THE SEAL
 ASSEMBLY REPLACED AND THE PUMP RETURNED TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) * SEAL * PUMPS * MAIN COOLING SYSTEM * LEAK * FAILURE, COMPONENT * REACTOR SHUTDOWN

106368

100300 *CONTINUEUP

AVERAGE EFFLUENT TEMPERATURE EXCEEDS LIMITS AT CALVERT CLIFFS 1

BALTIMORE GAS & ELECTRIC CO., MARYLAND

2 PGS. LTR W/RE 75-04 TO NRC OFFICE OF I & E, REGION I, SEPT. 4, 1975, DOCKET 50-317, TYPE--PWR, WFG--COMB., AE--BECHTEL

CAUSE - INCREASE IN INLET TEMPERATURE. REACTOR POWER WAS REDUCED TO 47% TO CLEAN CONDENSER INLET WATER BOXES. EACH OF THE 6 CIRCULATING WATER PUMPS WAS STOPPED ONE AT A TIME WHILE ITS BOX WAS CLEANED. THE 3 PM COMPUTED FLOW-WEIGHTED HOURLY AVERAGE CIRCULATING WATER DISCHARGE TEMPERATURE WAS 90.4 F. THIS EXCEEDS THE LIMIT BY 0.4 F. BETWEEN 2 PM AND 3 PM, THE INLET WATER TEMPERATURE UNEXPECTEDLY INCREASED FROM 79.9 TO 80.4 F WITH A RESULTING INCREASE IN DISCHARGE TEMPERATURE. REACTOR POWER WAS REDUCED TO LOWER THE DISCHARGE TEMPERATURE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) * EFFLUENT * CONDENSER COOLING SYSTEM * DISCHARGE * MAINTENANCE AND REPAIR * TEMPERATURE

100307

AVERAGE DISCHARGE TEMPERATURE EXCEEDS LIMIT AT CALVERT CLIFFS 1

BALTIMORE GAS & ELECTRIC CO., MARYLAND

2 PGS. LTR W/RE 75-05 TO NRC OFFICE OF I & E, REGION I, SEPT. 5, 1975, DOCKET 50-317, TYPE--PWR, WFG--COMB., AE--BECHTEL

CAUSE - INCREASE IN INLET TEMPERATURE. ON THE EVENING OF AUG. 30 WHILE OPERATING AT FULL POWER, THE FLOW-WEIGHTED HOURLY AVERAGE TEMPERATURE OF THE CONDENSER COOLING WATER DISCHARGE WAS CALCULATED TO BE 90.1 F. EXCEEDING THE LIMIT BY 0.1 F. PERSONNEL HAD BEGUN A POWER REDUCTION BASED ON OBSERVATION OF INCREASING INLET TEMPERATURE. THE OPERATOR FAILED TO DECREASE POWER ENOUGH TO COMPENSATE FOR THE INCREASED INLET TEMPERATURE. THE INCREASE IN DAY TEMPERATURE IS A NORMAL SOLAR EFFECT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) * TEMPERATURE * EFFLUENT * CONDENSER COOLING SYSTEM * DISCHARGE * FAILURE, OPERATOR ERROR

100402

UNPLANNED RELEASE OF RADIOACTIVE MATERIAL OCCURS AT CALVERT CLIFFS 1

BALTIMORE GAS & ELECTRIC CO., MARYLAND

3 PGS. LTR W/AD 50-317/75/50 TO NRC OFFICE OF I & E, REGION I, SEPT. 9, 1975, DOCKET 50-317, TYPE--PWR, WFG--COMB., AE--BECHTEL

CAUSE - DEGASSING OF LIQUID WASTE. WHEN AN OPERATOR STARTED DRAINING THE WASTE GAS SURGE TANK TO THE LIQUID WASTE SYSTEM VIA A FLOOR DRAIN, ABOUT 1 CI OF XE-133 AND XE-135 AND 9 MICROCURIES OF I-131 WERE RELEASED TO THE AUXILIARY BUILDING AND THE PLANT VENTILATION SYSTEM. WHEN THE RADIATION ALARMS SOUNDED, THE OPERATOR TERMINATED THE RELEASE. SEVEN INDIVIDUALS SLIGHTLY CONTAMINATED DURING THE INCIDENT WERE REACILY AND COMPLETELY DECONTAMINATED. INSTRUCTIONS WILL BE MODIFIED TO DRAIN THE WASTE GAS SURGE TANK DIRECTLY TO THE WASTE PROCESSING SYSTEM DEGASSIFIER RATHER THAN THE FLOOR DRAIN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) * PAIRBORNE RELEASE * WASTE HANDLING * CONTAMINATION * FAILURE, ADMINISTRATIVE CONTROL * PROCEDURES AND MANUALS * OPERATOR ACTION * WASTE TREATMENT

105020

FINAL REPORT ON EROSION DAMAGE TO SALT WATER PIPING AT CALVERT CLIFFS 1

BALTIMORE GAS & ELECTRIC CO., MARYLAND

2 PGS. LTR W/RPT TO NRC OFFICE OF I & E, SEPT. 12, 1975, DOCKET 50-317, TYPE--PWR, WFG--COMB., AE--BECHTEL

CAUSE - SEVERE CAVITATION. DURING PREOPERATIONAL TESTS, A BUTTERFLY VALVE IN THE DISCHARGE PIPING FROM A SALT WATER COOLING SYSTEM HEAT EXCHANGER WAS USED TO THROTTLE FLOW. SINCE NORMAL FLOW IS SMALL COMPARED TO EMERGENCY FLOW, THE VALVE WAS NEARLY CLOSED. SEVERE CAVITATION DAMAGED THE CEMENT LINING AND ERODED THE PIPE WALL. THE VALVE HAS BEEN RELOCATED FROM UPSTREAM TO DOWNSTREAM OF AN ELBOW. ALSO, THE AMOUNT OF THROTTLING WILL BE LIMITED TO REDUCE CAVITATION. DRILLED VALVE DISCS ARE ON ORDER. THESE DISCS WILL RELOCATE THE TURBULENCE TOWARD THE CENTER OF THE PIPE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) * PIPES AND PIPE FITTINGS * AUXILIARY COOLING * EROSION * HYDRAULIC EFFECT * DAMAGE * FAILURE, PIPE * FAILURE, DESIGN ERROR * MODIFICATION * FLOW DISTRIBUTION

104067

FINAL REPORT ON LOSS OF TOLERANCE REACTOR INTERNALS AT CALVERT CLIFFS 2

BALTIMORE GAS & ELECTRIC CO., MARYLAND

104667 CONTINUED
 2 PGS. LTR W/AD 50-317/75/51 TO NRC OFFICE OF I & E, SEPT. 15, 1975. DOCKET 50-317, TYPE--PHR, RFG--COMB., AE--DECHTEL

CAUSE - FABRICATION DEFICIENCIES. FIELD MEASUREMENTS INDICATED THAT REACTOR INTERVALS, SPECIFICALLY THE CORE SUPPORT BARRREL, MAY BE OUT OF TOLERANCE IN 5 AREAS. THE VENDOR REVIEWED THE DATA AND TOOK ADDITIONAL MEASUREMENTS TO INSURE THAT CRITICAL DIMENSIONS WERE SATISFACTORY. WITH THE EXCEPTION OF THE MISLOCATION OF THE GUIDE PINS IN THE BOTTOM FLANGE WITH THE HOLES IN THE LOWER SUPPORT STRUCTURE, ALL DATA REVIEWED WAS ACCEPTABLE. THE PINS WERE REMOVED AND THE LOWER SUPPORT STRUCTURE REALIGNED IN THE FIELD. THE ALIGNMENT WAS FOUND ACCEPTABLE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 2 (PHR) + CONSTRUCTION + CORE COMPONENTS + SUPPORT STRUCTURE + FAILURE, FABRICATION ERROR + COMPLETION + INSTALLATION

104634
 THERMAL POWER CALCULATOR FAILS AT CALVERT CLIFFS 1
 BALTIMORE GAS & ELECTRIC CO., MARYLAND
 3 PGS. LTR W/AD 50-317/75/51 TO NRC OFFICE OF I & E, REGION 1, SEPT. 16, 1975. DOCKET 50-317, TYPE--PHR, RFG--COMB., AE--DECHTEL

CAUSE - DIRTY CONTACTS AND DEFECTIVE MODULE. WHILE THE REACTOR WAS AT 1308 POWER, AN INVESTIGATION INTO INTERMITTENT TRIPS OF RPS CHANNEL A THERMAL MARGIN/LOW PRESSURE TRIP CIRCUIT FOUND THE FOLLOWING: (1) DIRTY RESISTOR TERMINAL CONTACTS GAVE INCORRECT COLD LEG TEMPERATURE INPUT TO THE THERMAL POWER CALCULATOR AND (2) THE MULTIPLIER MODULE IN THE THERMAL POWER CALCULATOR WAS DEFECTIVE. IT WAS REPLACED. A CONDITION CAUSING A 14 VDC DIFFERENTIAL BETWEEN THE THERMAL POWER CALCULATOR COMMON AND GROUND GENERATED NOISE WITHIN THE CALCULATOR. ALL COMMON CONNECTIONS WERE CLEANED AND RESOLDERED. THE VOLTAGE DIFFERENCE WAS NO LONGER PRESENT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PHR) + INSTRUMENTS, MISC. + REACTOR SAFETY SYSTEM + NOISE + INSTRUMENT, ABNORMAL INDICATION + FAILURE, COMPONENT + ELECTRONIC FUNCTION UNITS + FAILURE, MAINTENANCE ERROR

104415
 UNPLANNED RELEASE OF RADIOACTIVE MATERIAL OCCURS AT CALVERT CLIFFS 1
 BALTIMORE GAS & ELECTRIC CO., MARYLAND
 3 PGS. LTR W/AD 50-317/75/52 TO NRC OFFICE OF I & E, REGION 1, SEPT. 22, 1975. DOCKET 50-317, TYPE--PHR, RFG--COMB., AE--DECHTEL

CAUSE - CHARGING PUMP PACKING LEAK. WHILE THE REACTOR WAS AT 898 POWER, INVESTIGATION OF A RADIATION MONITOR ALARM FOUND REACTOR COOLANT LEAKING FROM THE PACKING OF CHARGING PUMP 13. THE PUMP WAS ISOLATED AND WILL BE REPAKED BEFORE BEING RETURNED TO SERVICE. ABOUT 5 CI OF XE-133, 1 CI OF XE-135, AND 0.1 CI OF KR-85M WERE RELEASED. NO PERSONNEL WERE CONTAMINATED OR EXPOSED TO AN EXCESSIVE AMOUNT OF RADIATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PHR) + AIRBORNE RELEASE + LEAK + SEAL + PUMPS + FEEDWATER + REACTOR COOLANT + FAILURE, EQUIPMENT

107436
 WIDE RANGE NUCLEAR INSTRUMENTATION FAILS AT CALVERT CLIFFS 1
 BALTIMORE GAS & ELECTRIC CO., BALTIMORE, MARYLAND
 3 PGS. LTR W/AD 50-317/75/53 TO NRC OFFICE OF I & E, REGION 1, OCT. 3, 1975. DOCKET 50-317, TYPE--PHR, RFG--COMB., AE--DECHTEL

CAUSE - NOT IDENTIFIED. WHILE THE PLANT WAS IN HOT SHUTDOWN, CHANNEL A WIDE RANGE NUCLEAR INSTRUMENTATION WAS INDICATING ABOUT 101-4TH & POWER. THE CAUSE WAS ISOLATED TO PRE-AMPLIFIER OR DETECTOR/PRE-AMPLIFIER INTERCONNECTING CABLEING. NO MALFUNCTION WAS IDENTIFIED. WHEN THE CABLES WERE RECONNECTED, THE MALFUNCTION WAS NO LONGER PRESENT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PHR) + INSTRUMENT, WIDE RANGE + CABLES AND CONNECTORS + FAILURE, INSTRUMENT

107435
 COLD LEG TEMPERATURE INPUT TO RPS FAILS AT CALVERT CLIFFS 1
 BALTIMORE GAS & ELECTRIC CO., BALTIMORE, MARYLAND
 3 PGS. LTR W/AD 50-317/75/54 TO NRC OFFICE OF I & E, REGION 1, OCT. 7, 1975. DOCKET 50-317, TYPE--PHR, RFG--COMB., AE--DECHTEL

CAUSE - BROKEN COMPENSATION LEAD. WHILE THE PLANT WAS IN HOT SHUTDOWN, THE OPERATOR NOTICED THAT THE COLD LEG TEMPERATURE INDICATION WAS LOW FOR CHANNEL B. THE ASSOCIATED TRIPS WERE BYPASSED. THE TEMPERATURE COMPENSATION LEAD TERMINAL LUG BOLT ON THE HTD HEAD WAS BROKEN OFF FLUSH WITH

107435 CONTINUED

THE HEAD SO THAT THE LEAD COULD NOT BE RECONNECTED. THE RTO WILL BE REPLACED WHENEVER THE REACTOR IS SHUT DOWN AND ACCESS GAINED TO THE SENSOR. THE CHANNEL WILL REMAIN OUT OF SERVICE UNTIL THEN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) + SENSORS, TEMPERATURE + INSTRUMENT, SWITCH + CABLES AND CONNECTORS + FAILURE, INSTRUMENT + REACTOR SAFETY SYSTEM

107776

UNPLANNED RELEASE OF RADIOACTIVE MATERIAL AT CALVERT CLIFFS 1

BALTIMORE GAS & ELECTRIC CO., BALTIMORE, MARYLAND

3 PGS. LTR W/AD 50-317/75/55 TO NRC OFFICE OF I & E, REGION I, DEC. 10, 1975, DOCKET 50-317, TYPE--PWR, NRC--COMB., AE--DECTEL

CAUSE - CRACKED WELD ON INSTRUMENT LINE. WHILE THE REACTOR WAS IN HOT STANDBY, RADIATION ALARMS WERE RECEIVED. A CRACKED WELD WAS FOUND ON THE CHARGING FLUX INSTRUMENT LINE. THE SOCKET WELD WAS AT THE INSTRUMENT LINE UNION TO THE CHARGING HEADER BUSS. THE HEADER WAS ISOLATED AND THE WELD REPAIRED. ABOUT 1.2 CI OF Xe-133 WERE RELEASED. THE FAILED WELD WILL BE EXAMINED METALLURGICALLY TO IDENTIFY FAILURE MODE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) + AIRBORNE RELEASE + FAILURE, PIPE + SENSORS, FLUX + FEEDWATER + PNEUMOS

108828

LINEAR POWER NUCLEAR INSTRUMENTATION FAILS AT CALVERT CLIFFS 1

BALTIMORE GAS & ELECTRIC CO., BALTIMORE, MD

3 PGS. LTR W/AD 50-317/75/56 TO NRC OFFICE OF I & E, REGION I, NOV. 11, 1975, DOCKET 50-317, TYPE--PWR, NRC--COMB., AE--DECTEL

CAUSE - POWER SUPPLY FAILURE. WHILE OPERATING AT 100% POWER, A ROUTINE CHECK OF THE APS REVEALED AN ILLUMINATED HIGH VOLTAGE ALARM ON CHANNEL C LINEAR POWER NUCLEAR INSTRUMENTATION. THE 15 VOLT POWER SUPPLY HAD FAILED. THE DEFECTIVE UNIT WAS REPLACED. A MORE RELIABLE POWER SUPPLY HAS BEEN ORDERED FOR REPLACEMENT OF EXISTING POWER SUPPLIES. SEVEN PREVIOUS FAILURES HAVE OCCURRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) + ELECTRIC POWER + INSTRUMENT, POWER RANGE + INSTRUMENT, LINEAR + FAILURE, INSTRUMENT + FAILURE, DESIGN ERROR

108874

UNPLANNED RELEASE OF RADIOACTIVE MATERIAL AT CALVERT CLIFFS 1

BALTIMORE GAS & ELECTRIC CO., BALTIMORE, MD

3 PGS. LTR W/AD 50-317/75/57 TO NRC OFFICE OF I & E, REGION I, DEC. 12, 1975, DOCKET 50-317, TYPE--PWR, NRC--COMB., AE--DECTEL

CAUSE - SAMPLE LINE INADVERTENTLY CUT. DURING AN INVESTIGATION OF A HIGH ALARM ON WASTE AREA U-2 VENTILATION RADIOGAS MONITOR WHILE THE UNIT WAS AT 100% POWER, GASEOUS RADIOACTIVITY WAS FOUND BEING RELEASED FROM A PLANT GAS ANALYZER RETURN LINE TO THE WASTE GAS SURGE TANK. THE LINE HAD BEEN INADVERTENTLY CUT DURING CONSTRUCTION WORK IN THE BUILDING. THE LINE WAS ISOLATED AND REPAIRED. NO PERSONNEL CONTAMINATION WAS FOUND. ABOUT 7 CI OF Xe-133 WERE RELEASED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CALVERT CLIFFS 1 (PWR) + XENON + PIPES AND PIPE FITTINGS + SAMPLING + AIRBORNE RELEASE + FAILURE, INSTALLATION ERROR

109270

AUXILIARY FEEDWATER PUMP SUPPLY VALVE FOUND CLOSED AT CALVERT CLIFFS 1

BALTIMORE GAS & ELECTRIC CO., BALTIMORE, MD

3 PGS. LTR W/AD 50-317/75/58 TO NRC OFFICE OF I & E, REGION I, DEC. 16, 1975, DOCKET 50-317, TYPE--PWR, NRC--COMB., AE--DECTEL

CAUSE - OPERATOR ERROR. WHILE OPERATING AT 100% POWER, AN OPERATOR DISCOVERED THAT CONDENSATE STORAGE TANK 12 SUPPLY VALVE TO THE AUXILIARY FEEDWATER PUMPS WAS CLOSED. THE PUMPS DID NOT HAVE A SUPPLY OF WATER. THE SUPPLY VALVE WAS OPENED IMMEDIATELY. IT IS BELIEVED THAT THE VALVE WAS MISPOSITIONED DURING THE LAST PLANT STARTUP. AT THAT TIME, THE OPERATOR WAS TOLD TO SHIFT THE SUPPLY FROM TANK 11 TO TANK 12. SINCE THE VALVES WERE LOCKED AT THAT TIME AND HAVE NOT BEEN REPOSITIONED SINCE THEN, IT IS CONCLUDED THAT THE OPERATOR ERRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

10473 ACQUITTANCE
CALVERT CLIFFS 1 (PWR) • VALVES • OPERATIONS • AUXILIARY • PUMPS • STORAGE CONTAINER • FAILURE, OPERATOR
CHARGE

10403C
UNUSUALLY LARGE NUMBER OF FISH COLLECTED AT CALVERT CLIFFS 1
BALTIMORE WAS A ELECTRIC CO., BALTIMORE, MD
2 PGS, LTR W/MT TO NRC OFFICE OF I & E, REGION 1, DEC. 30, 1975, DOCKET 50-317, TYPE--PWR, WFG--COMB., AE--
SECURE

CAUSE - SUMMER DROP IN DAY TEMPERATURE. FOR 2 DAYS IN DECEMBER 1975, UNUSUALLY LARGE NUMBERS OF
FISH WERE COLLECTED DURING ROUTINE ENVIRONMENTAL SAMPLING PROGRAMS. THE FISH WERE MAINLY SPOT,
CALAHERS, AND PERCHES. ALL WERE FROM THE FIRST YEAR CLASS. THESE FISH ARE NOT USUALLY IN THIS
AREA THIS TIME OF THE YEAR. THE DAY TEMPERATURE AT THE INTAKE STRUCTURE DROPPED FROM 0.4 C TO
-0.5 C IN 33 HOURS. STUDIES INDICATE THAT THIS RAPID DROP DID NOT ALLOW SUFFICIENT TIME FOR MANY
SPECIES TO ACCLIMATE TO THE COLDER TEMPERATURE. THE TEMPERATURE CHANGE WAS NOT RELATED TO PLANT
OPERATIONS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00)

CALVERT CLIFFS 1 (PWR) • MORTALITY • WEATHER, SEVERE • THERMAL TRANSIENT • MONITORING PROGRAM, ENVIRONMENTAL
• FILTER, SCREEN • CONDENSER COOLING SYSTEM • FAILURE, INHERENT • ANIMAL, FISH

10374
INTERIM REPORT ON PRESSURE VESSEL DAMAGE AT CATAMBA 1
JUNE POWER COMPANY
16 PAGES, LETTER WITH PHOTOGRAPHS TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, REGION 2, FEBRUARY 6, 1975,
DOCKETS 50-413/414, TYPE--PWR, WFG--WEST., AE--DUNE

CAUSE - HANDLING ERROR. DURING THE RIGGING OF THE REACTOR PRESSURE VESSEL FOR OFF-LOADING AT THE
STORAGE SITE, A CABLE SUFFERER WAS PULLED OFF THE LIFTING GIRDER PRIOR TO LIFTING AND STRUCK 2
NOZZLES. MULTIPLE MAKING A POSITIVE DUGGING DEVICE HAD BEEN ENGAGED IN JULY 2 OR 3 THREADS. THE
BOLTS PULLED LOOSE FROM THE WEIGHT OF THE CABLE AS THE CABLE WAS BEING LOADED UNDER THE VESSEL.
BOTH NOZZLES WERE DAMAGED IN THE WELD PREPARATION AREA. THE LOWER NOZZLE WAS ONLY SLIGHTLY
DAMAGED. THE DAMAGED AREA WAS 1.5 X 1.5 INCHES BY 1/4 INCH DEEP ON THE EDGE OF THE UPPER
NOZZLES. NECESSARY REPAIRS WILL BE MADE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00)

FAILURE, OPERATOR ERROR • PRESSURE VESSELS • TRANSPORTATION AND HANDLING • FASTENER • NOZZLE • DAMAGE •
CONSTRUCTION • CATAMBA 1 (PWR) • ON SITE

10102
REACTOR BUILDING EXCAVATION PLANS AT CORANOME 1 AND 2
TEXAS UTILITIES GENERATING CO., DALLAS, TX
2 PGS, LTR W/MT TO NRC OFFICE OF I & E, REGION IV, DEC. 12, 1975, DOCKET 50-445, TYPE--PWR, WFG--WEST., AE--
GIBBS & HILL

CAUSE - BLASTING. AS PREVIOUSLY REPORTED, HORIZONTAL FRACTURES WERE DISCOVERED WHEN EXCAVATION OF
UNITS 1 AND 2 REACTOR CAVITIES WERE COMPLETED. AREAS CONTAINING THE MOST DAMAGE WERE REMOVED BY
SINKING A NARROW TRENCH ABOUT 30 INCHES DEEP AND REMOVING THE ROCK WITH A BACKHOE. THE REMOVED
ROCK WAS REPLACED WITH DENTAL CONCRETE. VERTICAL FRACTURES WERE ALSO FOUND AS A RESULT OF
BLASTING. GROUT WILL BE PLACED IN THESE 1/8 INCH FRACTURES AFTER PLACEMENT OF THE CONTAINMENT
FOUNDATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00)

CORANOME 1 (PWR) • CORANOME 2 (PWR) • CONSTRUCTION • FOUNDATION ENGINEERING • WFLM • SOIL PROPERTY • GEOLOGY
• RJA MECHANICS • CONTAINMENT CONSTRUCTION

101134
REACTOR COOLANT SYSTEM PACKING GLAND LEAK AT CONNECTICUT YANKEE
CONNECTICUT YANKEE POWER COMPANY
2 PAGES, ABNORMAL OCCURRENCE REPORT 75/1, APRIL 1, 1975, DOCKET 50-213, TYPE--PWR, WFG--WEST., AE--STINE &
WEBSTER

CAUSE - PACKING FAILURE. VALVES IN THE REACTOR COOLANT SYSTEM, 2 INCHES OR LARGER, HAVE A DUAL
VALVE STEM PACKING ARRANGEMENT WITH A VALVE STEM LEAK OFF SYSTEM CONNECTED TO THE VALVE BETWEEN
THE 2 SETS OF PACKING TO DIRECT LEAKAGE TO A DRAIN COLLECTION TANK. THE INNER PACKING ON THE
LEAKDOWN ISOLATION VALVE FAILED PRESSURIZING THE DRAIN COLLECTION SYSTEM. ITS RELIEF VALVE OPENED
INCREASING LEAKAGE TO THE CONTAINMENT IN EXCESS OF LIMITS. THE REACTOR WAS SHUT DOWN. BOTH SETS
OF VALVE STEM PACKING WERE REPLACED WITH NEW PACKING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00)

101154 ACQUISITION
FAILURE, EQUIPMENT + CONTAINMENT ISOLATION + CONNECTICUT YANKEE (PWR) + REACTOR COOLANT + SEAL + COOLANT
PURIFICATION SYSTEM + LEAK + REACTOR SHUTDOWN + VALVES

100040
NRC REQUESTS ANALYSIS OF SECONDARY SYSTEM FLUID FLOW INSTABILITY AT CONNECTICUT YANKEE
U.S. NUCLEAR REGULATORY COMMISSION
5 PAGES, LETTER TO CONN. YANKEE ATOMIC POWER CO., MAY 13, 1975, DOCKET 50-213, TYPE--PWR, NRC--WEST., AE--
STONE & WEBSTER

CAUSE - POSSIBLE DESIGN DEFICIENCY. THE POTENTIAL FOR OCCURRENCE AND THE POTENTIAL CONSEQUENCES
OF SECONDARY SYSTEM FLUID FLOW INSTABILITY IN PWR'S NEEDS TO BE ADEQUATELY ANALYZED. DAMAGE WAS
OCCURRED TO FEEDWATER PIPING AT OPERATING PLANTS AS A CONSEQUENCE OF UNCOVERING THE FEEDWATER
SPARGER ON THE FEEDWATER INLET NOZZLES IN THE STEAM GENERATOR. AN INSTABILITY IN PRESSURE WAVE
THAT IS PROPAGATED THROUGH THE PIPING CAN RESULT IN FAILURE OF THE PIPING AND/OR ITS SUPPORTS.
NRC REQUESTS AN ANALYSIS TO DETERMINE THE POTENTIAL FOR OCCURRENCE AND POTENTIAL CONSEQUENCES OF
SUCH AN EVENT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

CONNECTICUT YANKEE (PWR) + BACKFIT + HYDRAULIC EFFECT + PIPES AND PIPE FITTINGS + SHOCK WAVE + SUPPORT
STRUCTURE + FEEDWATER + OPERATING EXPERIENCE + FAILURE, DESIGN ERROR + STRUCTURAL ANALYSIS, DYNAMIC

103051
SHUTTER LONG HOLDOWN BOLTS PULLED ON STEAM GENERATORS AT CONNECTICUT YANKEE
CONNECTICUT YANKEE ATOMIC POWER CO.
1 PAGE, ADM 50-213/75-2, MAY 27, 1975, DOCKET 50-213, TYPE--PWR, NRC--WEST., AE--STONE & WEBSTER

CAUSE - INSTALLATION DEFICIENCY. WHILE PREPARING TO INSTALL A NEW STEAM GENERATOR SUPPORT AND
SEISMIC RESTRAINT SYSTEM DURING THE REFUELING SHUTDOWN, 3 OF THE ORIGINAL SYSTEM LONG BOLTS WERE
FOUND BROKEN. NO ALARM HAD BEEN RECEIVED ON THE LONG BOLT MONITORING SYSTEM. TWO BOLTS HAD NOT
MOVED ENOUGH TO ACTIVATE THE LIMIT SWITCHES. THE OTHER BOLT HAD BEEN WIERED TO THE SHORT BOLT
ALARM BECAUSE OF AN IDENTIFICATION ERROR ON THE MICROSWITCHES. A SHORT BOLT ALARM HAD BEEN
RECEIVED. THE NEW SUPPORT SYSTEM WILL BE COMPLETED DURING THIS OUTAGE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

CONNECTICUT YANKEE (PWR) + FASTENER + FAILURE, INSTALLATION ERROR + FAILURE, DESIGN ERROR + ANN. CIATORS +
REFUELING + STEAM GENERATOR

104202
SEISMIC RESTRAINTS NOT INSTALLED AS DESIGNED AT CONNECTICUT YANKEE
CONN. YANKEE ATOMIC POWER COMPANY
3 PAGES, LETTER TO NRC DIVISION OF INSPECTION & ENFORCEMENT, REGION 1, JUNE 30, 1975, DOCKET 50-213, TYPE--
PWR, NRC--WEST., AE--STONE & WEBSTER

CAUSE - INSTALLATION ERROR. DURING THE JUNE 1975 REFUELING OUTAGE, THE PRESSURIZER SEISMIC
RESTRAINTS WERE EXAMINED AS REQUESTED BY RD BULLETIN 74-3. EXAMINATION REVEALED THAT ONLY 1 OF
THE 4 TOP GUIDES WAS INSTALLED PROPERLY. THE OTHERS DID NOT LINE UP PROPERLY WITH THE EMBEDDED
PLATE SO THAT ONLY 6 OF THE 8 BOLTS AND 1 OF 2 DOWEL PINS WERE INSTALLED. ON THE BOTTOM RING
GIRDER, 16 OF THE 24 BOLTS WERE NEVER TIGHTENED ENOUGH TO COMPRESS THE LOCK WASHERS. ANALYSIS
SHOWED THAT SEISMIC RESTRAINT CAPACITY WOULD BE ADEQUATE BY ADDING THE MISSING DOWELS AND
TIGHTENING THE LOWER SUPPORT BOLTING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

CONNECTICUT YANKEE (PWR) + BACKFIT + SEISMIC DESIGN + SUPPORT STRUCTURE + SHOCK ABSORBER + PRESSURIZER +
FAILURE, INSTALLATION ERROR + FASTENER + REFUELING + SURVEILLANCE PROGRAM + MAIN COOLING SYSTEM

104049
FEEDWATER HANGER PIPE ATTACHMENTS DISCOVERED BROKEN AT CONNECTICUT YANKEE
CONNECTICUT YANKEE ATOMIC POWER CO.
1 PAGE, LETTER TO NRC DIVISION OF INSPECTION & ENFORCEMENT, REGION 1, JULY 2, 1975, DOCKET 50-213, TYPE--PWR,
NRC--WEST., AE--STONE & WEBSTER

CAUSE - UNKNOWN. DURING THE JUNE 1975 REFUELING OUTAGE, FEEDWATER HANGER PIPE ATTACHMENTS WERE
DISCOVERED BROKEN ON STEAM GENERATOR PIPING INSIDE CONTAINMENT. ONE WAS IN SG NO. 3 AND 2 WERE
ON NO. 4. ANALYSIS DID NOT INDICATE ANY OVERSTRESSING OF THE PIPING HAD OCCURRED DURING PAST
OPERATION. THE DAMAGED ATTACHMENTS WERE REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

CONNECTICUT YANKEE (PWR) + SUPPORT STRUCTURE + PIPES AND PIPE FITTINGS + STEAM GENERATOR + REFUELING +
SURVEILLANCE PROGRAM + FAILURE, EQUIPMENT

100348
DISSOLVED OXYGEN ACROSS PLANT COOLING WATER EXCEEDS LIMITS AT CONNECTICUT YANKEE
CONN. YANKEE ATOMIC POWER CO., CONN.
2 PGS. AUG 30-213/75-3, SEPT. 5, 1975. DOCKET 50-213, TYPE--PMR, MFG--WEST., AE--STONE & WEBSTER

CAUSE - UNKNOWN. A GREATER THAN 2 DELTA DISSOLVED OXYGEN ALARM WAS RECEIVED ACROSS THE PLANT'S COOLING WATER FOR A 3 HOUR PERIOD. THE CAUSE WAS NOT IMMEDIATELY APPARENT. GRAB SAMPLES IDENTIFIED THAT THE CONTINUOUS MONITORS WERE NOT FUNCTIONING PROPERLY. OREDDING IN THE CANAL UPSTREAM OF THE MONITOR MAY HAVE LOOSENED REDUCING MATERIAL THAT SCAVANGED OXYGEN FROM THE CANAL WATER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONNECTICUT YANKEE (PMR) + COMPOSITION + EFFLUENT + CONDENSER COOLING SYSTEM + OXYGEN + MONITORING PROGRAM, ENVIRONMENTAL

100349
SERVICE WATER TO CONTAINMENT FAN COOLERS INTERRUPTED AT CONNECTICUT YANKEE
CONNECTICUT YANKEE ATOMIC POWER CO.
2 PGS. AUG 30-213/75-3 TO U.S. NRC, NOV. 25, 1975. DOCKET 50-213, TYPE--PMR, MFG--WEST., AE--STONE & WEBSTER

CAUSE - OPERATOR ERROR. AN OPERATOR FOUND SERVICE WATER FILTER A TO BE NOT OPERATING PROPERLY. ANOTHER OPERATOR WAS TOLD TO PLACE FILTER B IN SERVICE. HE OBSERVED THAT FILTER B WAS TURNING AND ASSUMED IT HAD BEEN OPERATING IN PARALLEL WITH FILTER A. HE ISOLATED FILTER A ONLY. THIS INTERRUPTED SERVICE WATER FLOW TO ALL 4 CONTAINMENT RECIRCULATION FAN COOLERS. CONTAINMENT TEMPERATURE ROSE 13 F IN 45 MINUTES BEFORE THE ERROR WAS FOUND AND CORRECTED. FILTER B HAD BEEN ON BACKWASH. THE DISCHARGE VALVE WAS FOUND CLOSED. THE PROPER VALVE LINEUP WAS MADE. NO DAMAGE OCCURRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONNECTICUT YANKEE (PMR) + VALVES + CONTAINMENT AIR COOLING + AUXILIARY COOLING + WATER + FAILURE, OPERATOR ERROR

099115
DIESEL FUEL OIL NOT SAMPLED ON SCHEDULE AT COOK 1
INDIANA & MICHIGAN POWER COMPANY, MICHIGAN
2 PAGES, LETTER WITH AD REPORT 74/UT, TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, JANUARY 10, 1975, DOCKET 50-315, TYPE--PMR, MFG--WEST., AE--UTILITY

CAUSE - COMPUTER PROGRAM ERROR. TECH SPECS REQUIRE SAMPLING OF THE DIESEL FUEL OIL STORAGE TANKS EACH 30 DAYS. THE PERIOD BETWEEN THE FIRST AND SECOND SAMPLES WAS 41 DAYS. THE COMPUTER WHICH PRINTS OUT SAMPLING REQUIRED EACH DAY WAS INCORRECTLY PROGRAMMED. THE PROGRAM WAS CORRECTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COMPUTER PROGRAM + SAMPLING + REACTOR STARTUP EXPERIENCE + FAILURE, ADMINISTRATIVE CONTROL + TEST INTERVAL + COOK 1 (PMR) + FUEL, FOSSIL + GENERATOR, DIESEL

099196
PH OF TURBINE ROOM SUMP DISCHARGE EXCEEDS LIMITS AT COOK 1
INDIANA & MICHIGAN POWER COMPANY, MICHIGAN
1 PAGE, LETTER TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, JANUARY 10, 1975, DOCKET 50-315, TYPE--PMR, MFG--WEST., AE--UTILITY

CAUSE - REGENERATION DIFFICULTIES. A WEEKLY COMPOSITE SAMPLE OF THE TURBINE ROOM SUMP DISCHARGE WAS ANALYZED AS HAVING A PH OF 9.55. TECH SPECS REQUIRE THE PH TO BE 9.0 TO 9.0. DURING THIS WEEK, A LARGE AMOUNT OF MAKE-UP WATER WAS REQUIRED TO COMPENSATE FOR STEAM LOSS FROM PLANT HEAT-UP TEMPERATURE CONTROL. PROBLEMS OCCURRED WITH THE REGENERATION SEQUENCE WHICH RESULTED IN THE DISCHARGE DIFFICULTY. SOME DIFFICULTIES WITH THE REGENERATION CYCLE HAVE BEEN IDENTIFIED AND ADJUSTMENTS ARE BEING MADE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

EFFLUENT + FAILURE, EQUIPMENT + WASTE DISPOSAL + CHEMICAL ANALYSIS + REACTOR STARTUP EXPERIENCE + FAILURE, DESIGN ERROR + COOK 1 (PMR)

099114
TURBINE ROOM SUMP DISCHARGE OUT OF LIMITS AT COOK 1
INDIANA & MICHIGAN POWER COMPANY, MICHIGAN
1 PAGE, LETTER TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, JANUARY 13, 1975, DOCKET 50-315, TYPE--PMR, MFG--WEST., AE--UTILITY

CAUSE - REGENERATION PROBLEMS. RESULTS FROM A WEEKLY COMPOSITE SAMPLE OF THE TURBINE ROOM SUMP

099114 CONTINUED

DISCHARGE INDICATED A PH OF 3.75. TECH SPEC PH RANGE IS 5.5 TO 9.0. DURING THE WEEK, A LARGE AMOUNT OF MAKE-UP WATER WAS REQUIRED TO COMPENSATE FOR STEAM LOSS DUE TO PLANT HEAT-UP TEMPERATURE CONTROL THROUGH ATMOSPHERIC JUMP VALVES. ALSO, THERE WERE PROBLEMS WITH REGENERATION SEQUENCE ON THE DEMINERALIZED WATER MAKE-UP SYSTEM. TO PREVENT RECURRENCE SAMPLING WILL BE INCREASED AND CHEMICALS ADDED AS NEEDED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20543, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

EFFLUENT • WASTE DISPOSAL • WASTE DISPOSAL, LIQUID • BUILDING • REACTOR STARTUP EXPERIENCE • TURBINE • COOL 1 (PH) • COMPOSITION

099382

PH OF TURBINE ROOM JUMP DISCHARGE EXCEEDS LIMIT AT COOL 1

INDIANA & MICHIGAN POWER COMPANY, MICHIGAN

1 PAGE, LETTER TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 3 (DEC), JANUARY 17, 1975, DOCKET 50-315, TYPE-- PH, NRC--WEST, AE--UTILITY

CAUSE - DEMINERALIZER REGENERATION PROBLEMS. ANALYSIS OF A WEEKLY COMPOSITE SAMPLE OF THE TURBINE ROOM JUMP DISCHARGE INDICATED A PH OF 9.55. TECH SPEC LIMITS ARE A PH OF 5.5 TO 9.0. FAILURE RESULTED FROM PROBLEMS WITH THE REGENERATION SEQUENCE ON THE DEMINERALIZER WATER MAKE-UP SYSTEM. SAMPLING SCHEDULES HAVE BEEN INCREASED. MEANS OF ADDING NEUTRALIZATION CHEMICALS TO THE JUMP PRIOR TO DISCHARGE HAVE BEEN INSTALLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20543, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

EFFLUENT • WASTE HANDLING • REACTOR STARTUP EXPERIENCE • FAILURE, DESIGN ERROR • COOLANT PURIFICATION SYSTEM • TURBINE • COOL 1 (PH) • COMPOSITION

099608

A REJECTED TRIP DEVICE INSTALLED IN CIRCUIT BREAKER AT COOL 1

INDIANA & MICHIGAN POWER CO., MICHIGAN

3 PAGES, LETTER WITH AO REPORT 75/1 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, FEBRUARY 13, 1975, DOCKET 50-315, TYPE--PH, NRC--WEST, AE--UTILITY

CAUSE - INSTALLATION ERROR. WHILE PREPARING FOR INITIAL CRITICALITY, A SOLID STATE TRIP DEVICE FOR A 4000L SS14 ITC CIRCUIT BREAKER WAS FOUND WITH A TRIP SETTING OF 14 SECONDS INSTEAD OF THE SPECIFIED 14 SECONDS. IT HAD BEEN REJECTED DURING RECEIPT INSPECTION FOR INCORRECT TRIP SET POINT AND WAS INSTALLED WITHOUT BEING PROPERLY CLEARED. APPROVAL WAS OBTAINED TO USE THE DEVICE UNTIL ONE HAVING THE PROPER SETTING COULD BE OBTAINED. THE ERROR WAS DISCOVERED DURING AN INTERNAL PLANT AUDIT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20543, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INSTRUMENT, PROTECTIVE • REACTOR STARTUP EXPERIENCE • REVIEW • FAILURE, INSTALLATION ERROR • COOL 1 (PH) • SET POINT • BREAKER

099609

WIND SPEED INDICATOR CLAMP LOOSE AT COOL 1

INDIANA & MICHIGAN POWER CO., MICHIGAN

2 PAGES, LETTER WITH AO REPORT 75/2 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, FEBRUARY 13, 1975, DOCKET 50-315, TYPE--PH, NRC--WEST, AE--UTILITY

CAUSE - VIBRATION. A SIGNIFICANT DISCREPANCY WAS NOTED BETWEEN WIND SPEED INDICATION SYSTEMS. THE WIND SPEED TRANSDUCER AT THE 50 FOOT LEVEL ON THE MICROHIVE TOWER WAS FOUND LOOSE ON THE ROOM. THE CLAMPING Allen SCREW ON THE CONNECTOR COLLAR SHOOK LOOSE. THE CLAMPING ASSEMBLY WAS REPLACED. THE COLLAR WILL BE FITTED WITH A LOCKING WIRE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20543, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT • INSTRUMENT, METEOROLOGICAL • FASTENER • REACTOR STARTUP EXPERIENCE • WIND STATISTICS • VIBRATION • COOL 1 (PH)

100090

RELEASES FROM WASTE HOLDUP TANK OUT OF LIMITS AT COOL 1

INDIANA & MICHIGAN POWER COMPANY, N.Y.

5 PAGES, LETTER WITH ATTACHMENT TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, FEBRUARY 21, 1975, DOCKET 50-315, TYPE--PH, NRC--WEST, AE--UTILITY

CAUSE - PROCEDURAL DEFICIENCY IS. THE SOUTH WASTE EVAPORATOR CONDENSATE TANK WAS RELEASED TO THE DISCHARGE CANAL WITHOUT HAVING BEEN ANALYZED. THE NORTH TANK HAD BEEN SAMPLED AND WAS THE ONE TO BE DISCHARGED. PROCEDURES ARE NOT SPECIFIC IN IDENTIFYING THE PROPER TANK. WHILE INVESTIGATING THIS EVENT, IT WAS DISCOVERED THAT THE BORON CONCENTRATION IN SEVERAL PAST RELEASES SLIGHTLY EXCEEDED TECH SPEC LIMITS. ALSO, LAKE SAMPLES HAD NOT ALWAYS BEEN TAKEN 24 HOURS AFTER EACH RELEASE. PROCEDURES ARE BEING MODIFIED TO PREVENT RECURRENCE OF THESE EVENTS.

100000 CONTINUED
 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

EFFLUENT + PROCEDURES AND MANUALS + WASTE DISPOSAL + SAMPLING + WASTE DISPOSAL - LIQUID + REACTOR STARTUP EXPERIENCE + STORAGE CONTAINER + FAILURE, ADMINISTRATIVE CONTROL + COOK 1 (PWR) + LEAK

100028
 RELEASE OF UNSAMPLED WASTE EVAPORATOR CONDENSATE TANK AT COOK 1
 INDIANA & MICHIGAN POWER COMPANY, MICH.
 1 PAGE. LETTER TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, REGION 3, MARCH 7, 1975. DOCKET 50-315, TYPE--PWR, NRC--WEST., AE--UTILITY

CAUSE - VALVE NOT CLOSED COMPLETELY. THE SOUTH WASTE EVAPORATOR CONDENSATE TANK WAS SAMPLED AND THE RELEASE WAS STOPPED. DURING THE RELEASE, THE OPERATOR NOTICED THAT THE LEVEL IN THE NORTH TANK HAD INCREASED. THE RELEASE WAS TERMINATED. VALVE LINEUP WAS CHECKED AS BEING SATISFACTORY. ONLY THE OUTLET VALVE FOR THE NORTH TANK TURNED SLIGHTLY TOWARD THE SHOT DIRECTION. THE STRIKE ADJUSTING AND JAM OUT FOR THIS DIAPHRAGM VALVE WAS LOOSE PERMITTING THE STRIKE TO CHANGE. THE VALVE WAS ADJUSTED AND THE RELEASE CONTINUED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

WASTE DISPOSAL + WASTE DISPOSAL, LIQUID + RADIOACTIVITY RELEASE + FAILURE, MAINTENANCE ERROR + LEAK + COOK 1 (PWR) + VALVES

100083
 REQUIRED SURVEILLANCE TESTS NOT PERFORMED AT COOK 1
 INDIANA & MICHIGAN POWER CO., MICH.
 2 PAGES. LETTER WITH AD REPORT 75/3 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, MARCH 10, 1975. DOCKET 50-315, TYPE--PWR, NRC--WEST., AE--UTILITY

CAUSE - OPERATOR ERROR. A REACTOR TRIP OCCURRED DURING POWER ASCENSION TESTING. THE CAUSE WAS DETERMINED AND CORRECTED. A REACTOR STARTUP WAS CONDUCTED. TESTING OF SOME REACTOR TRIP SYSTEM PROTECTIVE INSTRUMENTATION HAD NOT BEEN PERFORMED WITHIN 7 DAYS OF STARTUP DUE TO OPERATOR FAILURE TO VERIFY TEST TIMES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATOR ERROR + REACTOR SAFETY SYSTEM + REACTOR STARTUP EXPERIENCE + TEST INTERVAL + COOK 1 (PWR) + INSTRUMENTS, MISC.

100084
 METEOROLOGICAL INSTRUMENTS INOPERABLE AT COOK 1
 INDIANA & MICHIGAN POWER CO., MICH.
 2 PAGES. LETTER WITH AD REPORT 75/4 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, MARCH 10, 1975. DOCKET 50-315, TYPE--PWR, NRC--WEST., AE--UTILITY

CAUSE - SEVERE WEATHER. WHILE OPERATING AT LESS THAN 100 POWER, THE WIND SPEED AND DIRECTION INSTRUMENTS WERE FOUND INOPERABLE. THE AEROVANES WERE ICED UP. SUB-ZERO TEMPERATURES AND STEAM FROM PLANT VENTING CAUSED ICE TO FORM ON THE MOVING PARTS. THE AEROVANES WERE CLEANED AND RETURNED TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INSTRUMENT, METEOROLOGICAL + FAILURE, INSTRUMENT + REACTOR STARTUP EXPERIENCE + WEATHER, SEVERE + COOK 1 (PWR)

100087
 EXHAUST AIR FILTER TRAIN NOT TESTED AT COOK 1
 INDIANA & MICHIGAN POWER CO., MICH.
 2 PAGES. LETTER WITH AD REPORT 75/7 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, MARCH 10, 1975. DOCKET 50-315, TYPE--PWR, NRC--WEST., AE--UTILITY

CAUSE - DEFECTIVE SURVEILLANCE SCHEDULE. A ESP VENTILATION SYSTEM EXHAUST AIR FILTER TRAIN WAS NOT TESTED LONGER PER 30 DAYS. A DEFECTIVE SURVEILLANCE SCHEDULE WAS THE CAUSE. THE TEST HAD BEEN LISTED FOR THE WRONG OPERATIONAL MODES. THE MASTER SCHEDULE HAS BEEN REVISED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PROCEDURES AND MANUALS + TESTING + VENTILATION SYSTEM + REACTOR STARTUP EXPERIENCE + FAILURE, ADMINISTRATIVE CONTROL + TEST INTERVAL + COOK 1 (PWR) + FILTERS

100088
 DIESEL GENERATOR NOT TESTED WHEN REQUIRED AT COOK 1

100004 (CONTINUED)

INDIANA & MICHIGAN POWER CO., MICH.

2 PAGES, LETTER WITH AD REPORT 75/6 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, MARCH 10, 1975. DOCKET 50-315, TYPE--PWR, RFG--WEST., AE--UTILITY

CAUSE - OPERATOR OVERSIGHT. WHEN A DIESEL GENERATOR WAS REMOVED FROM SERVICE, THE SECOND DIESEL GENERATOR WAS NOT TESTED UNTIL 14 HOURS AND 22 MINUTES LATER. TESTING SHOULD HAVE BEEN PERFORMED IMMEDIATELY AND THEN ONCE PER EIGHT HOURS THEREAFTER. THE OPERATOR FAILED TO DO THE TESTING WHEN HE TAGGED A DIESEL FOR MAINTENANCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATOR ERROR + MAINTENANCE AND REPAIR + TESTING + REACTOR STARTUP EXPERIENCE + TEST INTERVAL + COOK 1 (PWR) + ENGINES, INTERNAL COMBUSTION + GENERATOR, DIESEL

100005

LOSS OF POWER AT COOK 1

INDIANA & MICHIGAN POWER CO., MICH.

2 PAGES, LETTER WITH AD REPORT 75/5 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, MARCH 10, 1975. DOCKET 50-315, TYPE--PWR, RFG--WEST., AE--UTILITY

CAUSE - GROUND FAULT DETECTION CIRCUITRY. THE PLANT EXPERIENCED BLACKOUT CONDITIONS WHEN THE SUPPLY BREAKERS TO RESERVE TRANSFORMERS OPENED. BOTH DIESEL-GENERATORS STARTED AND ACCEPTED THEIR ASSIGNED LOADS. THE CONDITION WAS CAUSED BY GROUND FAULT DETECTION CIRCUITRY. A POOR SPlice WAS FOUND IN ONE CABLE. THE SPlice WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ACCIDENT, LOSS OF POWER + ELECTRIC POWER + REACTOR STARTUP EXPERIENCE + FAILURE, INSTALLATION ERROR + COOK 1 (PWR) + CABLES AND CONNECTORS

100911

UNSAMPLED RELEASE OCCURS FROM GAS DECAY TANK AT COOK 1

INDIANA & MICHIGAN POWER CO., MICH.

1 PAGE, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, MARCH 14, 1975. DOCKET 50-315, TYPE--PWR, RFG--WEST., AE--UTILITY

CAUSE - DESIGN ERROR. AN UNSAMPLED RELEASE OF 100 PSI FROM A GAS DECAY TANK RESULTED FROM FAILURE OF A BLOWDOWN TUBE IN A VALVE CONTROLLER. THE VALVE FAILED OPEN. WHEN THE SOUTH WASTE GAS COMPRESSOR WAS SHUT DOWN BEFORE THE FAILURE, ANOTHER VALVE OPENED TO PREVENT STARTING THE COMPRESSOR UNDER SHUTOFF HEAD CONDITIONS. THE LEAK FLOW PATH WAS FROM THE RECYCLE HEADER THROUGH THIS VALVE, THROUGH THE MOISTURE SEPARATOR, THROUGH THE FAILED OPEN VALVE TO THE CLEAN WASTE HOLDUP TANK AND THEN THE AUXILIARY BUILDING VENT SYSTEM TO ATMOSPHERE. ANALYSIS OF THE REMAINING GAS IN THE TANK INDICATED VERY LOW ACTIVITY. A DESIGN CHANGE IS BEING CONSIDERED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

AIRBORNE RELEASE + FAILURE, EQUIPMENT + WASTE HANDLING + WASTE STORAGE + REACTOR STARTUP EXPERIENCE + FAILURE, DESIGN ERROR + COOK 1 (PWR)

102121

WIND DIRECTION INSTRUMENT IN ERROR AT COOK 1

INDIANA & MICHIGAN POWER COMPANY, MICH.

2 PAGES, LETTER WITH AD REPORT 75/10 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, APRIL 10, 1975. DOCKET 50-315, TYPE--PWR, RFG--WEST., AE--UTILITY

CAUSE - LEADS REVERSED. DURING TESTING WITH THE REACTOR AT 5% POWER, THE 150-FT AND THE 50-FT WIND DIRECTION DIFFERED BY 180 DEGREES. THE POWER SUPPLY LEADS FOR THE 150-FT INSTRUMENT WERE FOUND TO BE REVERSED. THE PROBLEM WAS CORRECTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INSTRUMENT, METEOROLOGICAL + REACTOR STARTUP EXPERIENCE + TEST, SYSTEM OPERABILITY + FAILURE, MAINTENANCE ERROR + WIND STATISTICS + COOK 1 (PWR) + CABLES AND CONNECTORS

102122

BORATION ATTEMPT FAILS AT COOK 1

INDIANA & MICHIGAN POWER COMPANY, MICH.

2 PAGES, LETTER WITH AD REPORT 75/11 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, APRIL 10, 1975. DOCKET 50-315, TYPE--PWR, RFG--WEST., AE--UTILITY

CAUSE - VALVE CALLED. WHILE OPERATING AT 44% POWER, AN ATTEMPTED BORATION FAILED WHEN THE BORIC ACID TO BLENDER CONTROL VALVE FAILED TO OPEN. THE VALVE INTERNALS (TRIM ASSEMBLY) WERE CALLED DUE TO CLOSE TOLERANCES. THE INTERNALS WERE REPLACED WITH SPARES. NO FLOW WAS INDICATED WHEN EMERGENCY BORATION WAS ATTEMPTED. BORON WAS ADDED FROM RUST.

102122 - PLOTTING UP
 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

REACTION CONTROL + REACTOR STARTUP EXPERIENCE + FAILURE, FABRICATION ERROR + CHEMICAL SHIM + COOK 1 (PHM) +
 VALVES

102125
 RHM EQUALIZING LINE WELD CRACK AT COOK 1
 INDIANA & MICHIGAN POWER COMPANY, MICH.
 2 PAGES, LETTER WITH AD REPORT 75/14 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, APRIL 10, 1975.
 JACKET 50-315, TYPE--PHM, RFG--WEST., AE--UTILITY

CAUSE - VIBRATION. WITH THE PLANT IN COLD SHUTDOWN USING THE RHM SYSTEM TO REMOVE DECAY HEAT, A
 CRACK WAS DISCOVERED IN A WELD ON THE EQUALIZING LINE AROUND A VALVE REQUIRING ISOLATION OF THE
 EAST RHM TRAIN. SUBSEQUENTLY, 2 ADDITIONAL WELD CRACKS WERE FOUND IN THE SAME LINE. ALL CRACKED
 WELDS WERE REMOVED AND REWELDED. FAILURES WERE ATTRIBUTED TO EXCESSIVE VIBRATION WHEN THE RHM
 SYSTEM IS IN SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

WELDS + REACTOR STARTUP EXPERIENCE + FAILURE, DESIGN ERROR + VIBRATION + SHUTDOWN COOLING SYSTEM + LEAK + COOK
 1 (PHM) + PIPES AND PIPE FITTINGS

102119
 RADIATION MONITOR NOT TESTED ON SCHEDULE AT COOK 1
 INDIANA & MICHIGAN POWER COMPANY, MICH.
 2 PAGES, LETTER WITH AD REPORT 75/8 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, APRIL 10, 1975.
 JACKET 50-315, TYPE--PHM, RFG--WEST., AE--UTILITY

CAUSE - CONTAMINATED PIG. MONTHLY TESTING OF A RADIATION MONITOR FOR THE WASTE LIQUID OFF GAS WAS
 NOT PERFORMED ON MARCH 1. THE PIG FOR THE DETECTOR WAS CONTAMINATED TO A LEVEL WHICH MADE
 TESTING IMPOSSIBLE. DECONTAMINATION EFFORTS FAILED TO REDUCE THE COUNT RATE SUFFICIENTLY. THE
 TEST WAS RUN SATISFACTORILY ON MARCH 24.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

WASTE TREATMENT + CONTAMINATION + REACTOR STARTUP EXPERIENCE + FAILURE, MAINTENANCE ERROR + TEST INTERVAL +
 COOK 1 (PHM) + RADIATION MONITORS

102120
 WIND SPEED AND DIRECTION INSTRUMENT MALFUNCTIONS AT COOK 1
 INDIANA & MICHIGAN POWER COMPANY, MICH.
 2 PAGES, LETTER WITH AD REPORT 75/9 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, APRIL 10, 1975.
 JACKET 50-315, TYPE--PHM, RFG--WEST., AE--UTILITY

CAUSE - DEFECTIVE TRANSLATOR. WHILE OPERATING AT 58 POWER, A ROUTINE CALIBRATION CHECK FOUND THE
 WIND SPEED AND DIRECTION INSTRUMENTATION AT THE 50-FT LEVEL MALFUNCTIONING. THE CAUSE WAS A BAD
 TRANSLATOR. THE TRANSLATOR WAS REPAIRED AND THE INSTRUMENT RETURNED TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

FAILURE, COMPONENT + INSTRUMENT, METEOROLOGICAL + REACTOR STARTUP EXPERIENCE + TEST, SYSTEM OPERABILITY + WIND
 STATISTICS + COOK 1 (PHM) + INSTRUMENTS, MISC.

102123
 SUCTION HEADER TO CHARGING PUMPS ISOLATED AT COOK 1
 INDIANA & MICHIGAN POWER COMPANY, MICH.
 2 PAGES, LETTER WITH AD REPORT 75/12 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, APRIL 10, 1975.
 JACKET 50-315, TYPE--PHM, RFG--WEST., AE--UTILITY

CAUSE - MAINTENANCE ACTIVITY. THE SUCTION HEADER TO THE CHARGING PUMPS WAS ISOLATED AND DRAINED
 FOR ABOUT 59 HOURS TO PERMIT PERFORMANCE OF VARIOUS MAINTENANCE ITEMS. TECH SPECS REQUIRE A
 MINIMUM OF ONE CHARGING PUMP. ISOLATION WAS REQUIRED TO REPLACE A NONISOLATABLE VENT VALVE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

MAINTENANCE AND REPAIR + REACTOR STARTUP EXPERIENCE + FAILURE, ADMINISTRATIVE CONTROL + COOK 1 (PHM) + INTAKE
 + FEEDWATER + PUMPS

102124
 ATTEMPTED EMERGENCY DEGRATION FAILS AT COOK 1
 INDIANA & MICHIGAN POWER COMPANY, MICH.

102126 CONTINUUM
2 PAGES, LETTER WITH AD REPORT 75-13 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, APRIL 13, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - SOLIDS PLUGGING LINE. WHILE OPERATING AT 600 POWER, A BURATION WAS ATTEMPTED AND FAILED. BURATION WAS THEN ATTEMPTED AND FAILED DUE TO SOLIDIFICATION IN THE LINE. HEAT WAS APPLIED AND THE SOLIDAGE REMOVED. SOLIDIFICATION OCCURRED AT THE PLUG INSTANT FLANGES. THE FLANGES WERE INSULATED BUT NOT HEAT TRACED. WORK IS IN PROGRESS TO HEAT TRACE THE FLANGES. BURATION WAS ACCOMPLISHED FROM THE RUST.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

REACTION STARTUP EXPERIENCE + FAILURE, DESIGN ERROR + CHEMICAL SHIM + FLANGE + FLOW BLOCKAGE + COOL 1 (PWR) + TEMPERATURE + HEATERS

102109
CONTAINMENT ISOLATION MEMBRANE BARRIER DEFICIENCY AT COOL 1
AMERICAN ELECTRIC POWER SERVICE CORP., N.Y.
4 PAGES, LETTER TO NRC DIRECTORATE OF LICENSING, APRIL 16, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - DESIGN ERROR. IT WAS RECENTLY DISCOVERED THAT THE CONTAINMENT ISOLATION MEMBRANE BARRIER FOR THE NON-ESSENTIAL SERVICE WATER SYSTEM WAS NOT BEEN QUALIFIED AS SEISMIC CLASS 1 AS SPECIFIED IN THE PSAR. INCOMING AND OUTGOING LINES TO THE VENTILATION SYSTEM HAVE CLASS C ISOLATION VALVES OUTSIDE CONTAINMENT. ANOTHER ISOLATION VALVE WILL BE ADDED IN EACH LINE TO UPGRADE TO CLASS A. THE SYSTEM PIPING AND WELDS DO NOT HAVE THE ADDITIONAL QUALITY CONTROL ASSOCIATED WITH CLASS 1 EQUIPMENT. UPGRADING THE VALVES WILL PROVIDE THE NECESSARY PROTECTION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTAINMENT INTEGRITY + CONTAINMENT AIR COOLING + MODIFICATION + FAILURE, INSTALLATION ERROR + AUXILIARY COOLING + COOL 1 (PWR) + SEISMIC DESIGN + PIPES AND PIPE FITTINGS

102104
ADDITIONAL INFORMATION ON ELECTRICAL BLACKOUT AT COOL 1
INDIANA & MICHIGAN POWER COMPANY, MICH.
4 PAGES, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, APRIL 19, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - DEFECTIVE UNDERGROUND SPLICE. DURING PREPARATION FOR A TURBINE START, 2 OIL COOLED BREAKERS OPENED CAUSING AN ELECTRICAL BLACKOUT. EMERGENCY DIESEL GENERATORS STARTED AND ASSUMED THEIR LOAD. EMERGENCY OFF-SITE POWER WAS AVAILABLE. THE PARTIAL LOSS OF OFF-SITE POWER RESULTED FROM A DEFECTIVE SPLICE IN AN UNDERGROUND CABLE BETWEEN ONE BREAKER AND A TRANSFORMER. THE CAUSE WAS POOR WORKMANSHIP. THE DEFECTIVE SPLICE WAS REPAIRED. THE OTHER 15 SPLICES WERE FOUND TO BE SATISFACTORY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ACCIDENT, LOSS OF POWER + ELECTRIC POWER + ELECTRIC POWER, NORMAL + REACTOR STARTUP EXPERIENCE + FAILURE, INSTALLATION ERROR + COOL 1 (PWR) + OFF SITE + CABLES AND CONNECTORS

103097
SET POINT DRIFT IN TIME-DELAY RELAY AT COOL 1
INDIANA & MICHIGAN POWER COMPANY, MICH.
2 PAGES, LETTER WITH AD 75-15 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, MAY 9, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - UNKNOWN. DURING TESTING OF THE CONTAINMENT AIR RECIRCULATION SYSTEM WHILE OPERATING AT 750 POWER, COOL FAN 2 TIME DELAY WAS FOUND TO BE 8 MIN. 45 SEC, WHICH IS LESS THAN THE 9 SEC LIMIT. NO CAUSE FOR THE SHIFT COULD BE DETERMINED. THE AGASTAT TIMER WAS RESET TO 10 MIN. 20 SEC.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOL 1 (PWR) + INSTRUMENT, SWITCH + INSTRUMENT CALIBRATION + INSTRUMENTS, MISC. + TEST, SYSTEM OPERABILITY + FAILURE, INSTRUMENT + SET POINT + DRIFT + CONTAINMENT AIR COOLING

103098
SEISMIC STARTER FAILS IN THE RUN MODE AT COOL 1
INDIANA & MICHIGAN POWER COMPANY, MICH.
2 PAGES, LETTER WITH AD 75-16 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, MAY 9, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - SEVERE ELECTRICAL STORM. WHILE THE REACTOR WAS OPERATING AT 800 POWER, SEISMIC STARTER 2 FAILED IN THE START MODE CAUSING THE SEISMIC RECORDERS TO RUN CONSTANTLY FOR SEVERAL HOURS.

103040 PCUNTINGPOD

SINCE THE RECORDING CASSETTES ONLY RUN 30 MINUTES, THE SYSTEM WAS INOPERABLE FOR 12 HOURS UNTIL THE STARTER UNIT COULD BE REPLACED FROM SPARES. FAILURE WAS ASSUMED TO BE DAMAGE FROM A SEVERE ELECTRICAL STORM WHICH WAS IN THE AREA AT THAT TIME.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PWR) + INSTRUMENT, EARTHQUAKE + FAILURE, COMPONENT + WEATHER, SEVERE + FAILURE, INSTRUMENT

103550

WIND SPEED INDICATOR BROKEN AT COOK 1

INDIANA & MICHIGAN POWER COMPANY, MICH.

2 PAGES, LETTER WITH AD 75-18 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, MAY 30, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - FLYING DEBRIS. WHILE THE REACTOR WAS AT SIX POWER, THE WIND SPEED INDICATION AT THE 150 FT LEVEL ON THE MICROWAVE TOWER FAILED. THE LAST RECORDED WIND SPEED WAS 76 MPH. ONE OF THE PLASTIC ANEMOMETER CUPS HAD BROKEN OFF PROBABLY FROM BEING STRUCK BY FLYING DEBRIS OR DEFECTIVE MATERIAL. A NEW CUP ASSEMBLY WAS INSTALLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PWR) + INSTRUMENT, METEOROLOGICAL + DESTRUCTIVE WIND + WEATHER, SEVERE + FAILURE, INSTRUMENT + REACTOR STARTUP EXPERIENCE

103949

TEMPORARY CHANGE SHEET FOR TEST NOT APPROVED ON TIME AT COOK 1

INDIANA & MICHIGAN POWER COMPANY, MICH.

2 PAGES, LETTER WITH AD 75-17 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, MAY 30, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - SHEET MISLaid. DURING PERFORMANCE OF A CALIBRATION PROCEDURE, A TEMPORARY CHANGE SHEET WAS INITIATED. THE SHEET WAS MISLaid IN THE C & I FOREMAN'S DESK AND WAS NOT APPROVED WITHIN THE REQUIRED 7 DAY PERIOD. IT WAS APPROVED 5 MONTHS LATER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PWR) + PROCEDURES AND MANUALS + INSTRUMENT CALIBRATION + TESTING + FAILURE, ADMINISTRATIVE CONTROL + REACTOR STARTUP EXPERIENCE

103985

REQUIRED SURVEILLANCE TESTS NOT PERFORMED ON SCHEDULE AT COOK 1

INDIANA & MICHIGAN POWER CO., BRIDGEMAN

2 PAGES, LETTER WITH AD REPORT 75-22 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, JUNE 6, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - OPERATOR OVERSIGHT. WHEN THE UNIT ENTERED MODE 5, TWO SURVEILLANCE TESTS WERE NOT CONDUCTED IN THE REQUIRED TIME FRAME. WHEN THE ERROR WAS DISCOVERED 4 DAYS LATER, THE TESTS WERE PERFORMED SATISFACTORILY. WHEN THE MODE OF OPERATION WAS CHANGED, THE OPERATOR FAILED TO DETERMINE THE NEW SURVEILLANCE REQUIREMENTS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PWR) + TEST INTERVAL + TESTING + FAILURE, OPERATOR ERROR + REACTOR STARTUP EXPERIENCE + TEST, SYSTEM OPERABILITY

104027

CHLORINE ANALYSIS NOT PERFORMED DURING CHLORINATION AT COOK 1

INDIANA & MICHIGAN POWER COMPANY, MICH.

1 PAGE, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, JUNE 17, 1975, DOCKET 50-391, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - AUTOMATIC TIMER TIMING ERROR. NO RESIDUAL CHLORINE ANALYSIS WAS PERFORMED DURING A CHLORINATION. ELECTRIC POWER HAD BEEN TURNED OFF TO THE CHLORINE BUILDING FOR ABOUT 1 HOUR. THIS CAUSED THE AUTOMATIC TIMER FOR OPERATION OF THE CHLORINATORS TO BE 1 HR LATE. THE SAMPLE WAS TAKEN BEFORE ACTUAL CHLORINATION. THE BUILDING IS SUPPLIED BY CONSTRUCTION ELECTRIC POWER. CONTROL OF THE POWER SUPPLY WILL BE ESTABLISHED TO PREVENT RECURRANCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PWR) + SAMPLING + DEF LUENT + CHLORINE + TEST INTERVAL + ELECTRIC POWER + FAILURE, INSTALLATION ERROR

103000

ESSENTIAL SERVICE WATER VALVE FAILS TO CLOSE AT COOK 1

INDIANA & MICHIGAN POWER COMPANY, MICH.

1 PAGES, LETTER WITH AOR 75-19-20 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, JUNE 20, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - SHAFT SEIZED TO BUSHING. DURING SURVEILLANCE IN THE WEST ESSENTIAL SERVICE WATER TRAIN WHILE THE REACTOR WAS AT 80% POWER, 2 VALVES FAILED TO CLOSE ON SIGNAL FROM THE CONTROL ROOM. BOTH ARE NORMALLY OPEN. THE SHAFT ON ONE VALVE WAS FOUND SEIZED TO ITS BUSHINGS. AFTER CLEANING THE SHAFT AND BUSHINGS, THE VALVE OPERATED SATISFACTORILY. AN OFFSET PACKING FOLLOWER FLANGE CAUSED BINDING IN THE SHAFT OF THE OTHER. FLANGE BOLTS WERE LOOSENEED, REALIGNED AND RETIGHTENED. THEN THE VALVE OPERATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PWR) + VALVES + AUXILIARY COOLING SYSTEM + TEST, SYSTEM OPERABILITY + FAILURE, MAINTENANCE ERROR + DESIGN + FAILURE, EQUIPMENT

103075

BORATION PATH HEAT TRACING CIRCUIT INOPERATIVE AT COOK 1

INDIANA & MICHIGAN POWER COMPANY, MICH.

2 PAGES, LETTER WITH AOR 75-25 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, JUNE 30, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - FAULTY THERMOSTAT. WHILE THE REACTOR WAS AT 81% POWER, THE EMERGENCY BORATION PATH HEAT TRACING CIRCUIT WAS FOUND TO BE AT 103 F. THE THERMOSTAT WAS FAULTY. IT WAS REPLACED IMMEDIATELY AND THE SYSTEM RETURNED TO NORMAL. FLOW CAPABILITY WAS VERIFIED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PWR) + OPERATORS + CONTROL + INSTRUMENTS, MISC. + ELECTRIC POWER + FAILURE, INSTRUMENT + SHUTDOWN SYSTEM, SECONDARY

103076

CRACK FOUND IN EQUALIZING LINE VALVE WELD AT COOK 1

INDIANA & MICHIGAN POWER COMPANY, MICH.

2 PAGES, LETTER WITH AOR 75-29 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, JUNE 30, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - FATIGUE FROM PIPE VIBRATION. WHILE RUNNING THE EAST RESIDUAL HEAT REMOVAL PUMP FOR A PIPING VIBRATION CHECK, A LEAK WAS DISCOVERED AT AN EQUALIZING LINE VALVE. THE LEAK WAS CAUSED BY A CRACKED WELD ATTRIBUTED TO WELD FATIGUE DUE TO PIPE VIBRATION. A REDESIGN AND MODIFICATION OF EQUALIZING LINES IS CURRENTLY UNDERWAY. THE REACTOR WAS AT 80% POWER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PWR) + WELDS + VALVES + BYPASS + LEAK + FAILURE, FATIGUE + FAILURE, PIPE + VIBRATION + FLOW + FAILURE, DESIGN ERROR + PIPES AND PIPE FITTINGS + SHUTDOWN COOLING SYSTEM

103078

EMERGENCY BORATION VALVE FAILS TO OPEN COMPLETELY AT COOK 1

INDIANA & MICHIGAN POWER COMPANY, MICH.

2 PAGES, LETTER WITH AOR 75-21 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, JUNE 30, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - UNKNOWN. DURING TESTING ON REMOTELY OPERATED VALVES WHILE THE REACTOR WAS AT 80% POWER, THE EMERGENCY BORATION VALVE WOULD NOT OPEN FULLY. IT WOULD ONLY GO 3/4 OPEN BY REMOTE OR MANUAL OPERATION. THE PROBLEM WILL BE INVESTIGATED AT THE NEXT SCHEDULED OUTAGE. TESTS VERIFIED THAT THE 70 GPM MINIMUM FLOW REQUIREMENT WERE EXCEEDED IN THE 3/4 OPEN POSITION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PWR) + VALVES + SHUTDOWN SYSTEM, SECONDARY + TEST, SYSTEM OPERABILITY + FAILURE, EQUIPMENT

104400

CONTAINMENT SPRAY PUMPS LOCKED OUT OF SERVICE AT COOK 1

INDIANA & MICHIGAN POWER COMPANY, BRIDGMAN, MICH.

3 PAGES, LETTER WITH AOR 75-35 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, JULY 16, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - FALSE HI-PRESSURE ALARM. DURING A UNIT COOLDOWN, A CONTAINMENT PRESSURE HI-HI ALARM WAS RECEIVED. ALL CONTAINMENT PRESSURE INDICATORS AND RECORDERS SHOWED NORMAL PRESSURE. CONTAINMENT SPRAY PUMPS WERE LOCKED OUT FOR 4 HOURS WHILE TROUBLESHOOTING TO PREVENT INADVERTENT ACTUATION. A BAD ISOLATOR CARD WAS FOUND IN SOLID STATE PROTECTION TRAIN B LOGIC BAY. THE CARD WAS REPLACED

104400 PCONTINUED
AND THE SYSTEM RETURNED TO NORMAL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CDOR 1 (PWR) + SENSORS, PRESSURE + CONTAINMENT + PCONTAINMENT PRAY + FAILURE, INSTRUMENT + SOLID STATE DEVICE + REACTOR STARTUP EXPERIENCE + ELECTRONIC FUNCTION UNIT.

104403
SURVEILLANCE TESTING NOT PERFORMED AS REQUIRED AT CDOR 1
INDIANA & MICHIGAN POWER COMPANY, BRIDGEMAN, MICH.
2 PAGES, LETTER WITH AOR 75-31 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, JULY 14, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - DEFECTIVE SURVEILLANCE SCHEDULE. A REVIEW OF TECH SPECS INDICATED THAT SURVEILLANCE TESTS WERE NOT BEING PERFORMED ONCE PER 3 MONTHS ON A STAGGERED TEST BASIS AS REQUIRED BUT RATHER ON BOTH UNITS AT THE SAME TIME. THE CAUSE WAS A DEFECTIVE SURVEILLANCE SCHEDULE. THE SCHEDULE HAS BEEN REVISED TO REFLECT THE REQUIREMENTS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CDOR 1 (PWR) + TEST INTERVAL + TESTING + FAILURE, ADMINISTRATIVE CONTROL + REACTOR STARTUP EXPERIENCE + REVIEW

104404
CONTAINMENT DOOR GASKET LEAKAGE NOT REPORTED AT CDOR 1
INDIANA & MICHIGAN POWER COMPANY, BRIDGEMAN, MICH.
2 PAGES, LETTER WITH AOR 75-30 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, JULY 14, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - REQUIREMENTS OVERLOOKED. A REVIEW OF JOB ORDERS BY THE NRC RESIDENT INSPECTOR INDICATED THAT A JOB ORDER WAS WRITTEN WHEN CONTAINMENT PERSONNEL DOOR GASKET LEAKAGE WAS FOUND TO BE EXCESSIVE BUT NO REPORT WAS SUBMITTED. THE LEAKAGE WAS CORRECTED BY READJUSTMENT OF THE DOOR A.J. TIGHTENING THE STRUTBOLTS. REPORTING REQUIREMENTS WERE OVERLOOKED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CDOR 1 (PWR) + DATA PROCESSING + LEAK RATE + CONTAINMENT AIR LOCK + FAILURE, ADMINISTRATIVE CONTROL + REVIEW + AGENCY, NRC + REACTOR STARTUP EXPERIENCE + TEST, SYSTEM OPERABILITY + TEST, LEAK RATE

104401
DIESEL GENERATOR INVERTER FAILS AT CDOR 1
INDIANA & MICHIGAN POWER COMPANY, BRIDGEMAN, MICH.
2 PAGES, LETTER WITH AOR 75-26 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, JULY 14, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - EXCESSIVE AMBIENT TEMPERATURE. WHILE THE REACTOR WAS AT 80% POWER, NO AC OR DC POWER INDICATION WAS FOUND AT DIESEL GENERATOR INVERTER AB. THE TECHNICIAN FOUND THE DC INPUT FUSE BLOWN, COMMUTATING SCR SHORTED, AND 2 CLAMPING DIODES DEFECTIVE. THE INVERTER WAS LIGHTLY LOADED. THE CAUSE WAS DETERMINED TO BE EXCESSIVE AMBIENT TEMPERATURE DURING A BATTERY EQUALIZING CHANGE. A DESIGN STUDY IS IN PROGRESS TO IMPROVE LOCAL VENTILATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CDOR 1 (PWR) + REACTOR STARTUP EXPERIENCE + FAILURE, DESIGN ERROR + HIGH TEMPERATURE + VENTILATION SYSTEM + COMPARTMENT + GENERATORS + EMERGENCY POWER, ELECTRIC

104402
CRITICAL INSTRUMENTATION BUS LOST AT CDOR 1
INDIANA & MICHIGAN POWER COMPANY, BRIDGEMAN, MICH.
2 PAGES, LETTER WITH AOR 75-29 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, JULY 14, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - HIGH AMBIENT TEMPERATURE. WHILE THE REACTOR WAS IN SHUTDOWN MODE, CRITICAL INSTRUMENTATION BUS GRID 4 WAS LOST. GRID 4 WAS TRANSFERRED TO STAND-BY POWER. THE AC OUTPUT FUSE M11 BLOWN. THE FUSE WAS REPLACED AND THE UNIT RETURNED TO SERVICE. THE CAUSE WAS DETERMINED TO BE EXCESSIVE AMBIENT TEMPERATURE DURING A HIGH LOAD ON THE INVERTER. A DESIGN CHANGE IS IN PROGRESS TO IMPROVE LOCAL VENTILATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CDOR 1 (PWR) + ELECTRIC POWER + INSTRUMENTS, MISC. + INSTRUMENT, PROTECTIVE + FAILURE, DESIGN ERROR + COMPARTMENT + VENTILATION SYSTEM + REACTOR STARTUP EXPERIENCE + HIGH TEMPERATURE

104306

AXIAL FLUX DIFFERENCE LIMITS EXCEEDED AT COOK 1
INDIANA & MICHIGAN POWER COMPANY, MICH.
4 PAGES, LETTER WITH AD REPORT 75-32 (SUPPLEMENT) TO NRC DIR. OF REGULATORY OPERATIONS, REGION 3, JULY 16, 1975.
DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - METERS NOT YET CALIBRATED. WITH IN-CORE-EX-CORE DETECTOR CALIBRATION PREOPERATIONAL TEST IN PROGRESS, SEVERAL FLUX MAPS WERE TAKEN AS PART OF THE PROCEDURE. DATA ANALYSIS REVEALED THAT AXIAL FLUX DIFFERENCE LIMITS WERE EXCEEDED BY A SMALL AMOUNT (FROM 3 TO 4%) DURING THE 17 HOUR TEST PERIOD. LIMITS WERE EXCEEDED BECAUSE THE READINGS BEING GIVEN BY THE AXIAL FLUX DIFFERENCE METERS WERE NOT YET CORRELATED WITH THE TRUE VALUE OF THE IN-CORE AXIAL FLUX DIFFERENCE. THE TEST WAS TO ESTABLISH THIS CORRELATION. THE METERS HAVE NOW BEEN CALIBRATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PWR) * FLUX DISTRIBUTION * TEST, SYSTEM OPERABILITY * INSTRUMENT CALIBRATION * INSTRUMENT, IN CORE * INSTRUMENT, POWER RANGE * REACTOR STARTUP EXPERIENCE

104863

POWER RANGE CHANNEL FAILS AT COOK 1
INDIANA & MICHIGAN POWER COMPANY
2 PAGES, LETTER WITH AD REPORT 75-33 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, JULY 22, 1975.
DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - SHORTED SIGNAL CABLE. WHILE THE REACTOR WAS OPERATING AT 60% POWER, AN ENGINEER WAS TAKING READINGS ON A POWER RANGE CHANNEL WHEN IT FAILED GIVING A NEGATIVE RATE TRIP SIGNAL AND OVERPOWER DELTA T SIGNAL. THE DRAWER INTERCONNECTION SIGNAL CABLE HAD SHORTED. THE CABLE WAS REPAIRED AND THE CHANNEL RETURNED TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PWR) * INSTRUMENT, POWER RANGE * FAILURE, COMPONENT * CABLES AND CONNECTORS * FAILURE, INSTRUMENT * REACTOR SAFETY SYSTEM

104861

GAS MONITOR FAILS TO RUN CONTINUOUSLY AT COOK 1
INDIANA & MICHIGAN POWER COMPANY
2 PAGES, LETTER WITH AD REPORT 75-39 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, JULY 22, 1975.
DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - LOW FLOW TRIP RELAY FAULTY. A REVIEW OF JOB ORDERS BY A NRC INSPECTOR FOUND THAT A JOB ORDER WAS WRITTEN WHEN THE CONTAINMENT AIR PARTICULATE AND RADIO GAS MONITOR WOULD NOT RUN CONTINUOUSLY BUT NO REPORT WAS SUBMITTED. THE MONITOR FAILED BECAUSE OF A FAULTY LOW FLOW TRIP RELAY. THE RELAY WAS REPLACED AND THE UNIT RETURNED TO SERVICE. GRAB SAMPLES WERE TAKEN EVERY 8 HOURS. SUPERVISORS WERE REMINDED TO CRITICALLY REVIEW ALL JOB ORDERS SUBMITTED AND TO INITIAL REPORTS IF REQUIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PWR) * RADIATION MONITORS * CONTAINMENT * FAILURE, EQUIPMENT * RELAYS * FAILURE, ADMINISTRATIVE CONTROL

104862

ICE CONDENSER DOORS PARTIALLY OPENED AT COOK 1
INDIANA & MICHIGAN POWER COMPANY
2 PAGES, LETTER WITH AD REPORT 75-37 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, JULY 22, 1975.
DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - DEFECTIVE TEST PROCEDURES. DURING A TEST OF THE HYDROGEN SKIMMER RECIRCULATION FAN WITH THE REACTOR AT 60% POWER, BACKDRAFT DAMPERS WERE OPENED ABOUT 15 SECONDS AFTER THE FAN BREAKER WAS OPENED. THE RESULTANT AIR MOVEMENT DURING FAN COASTDOWN CAUSED 45 ICE CONDENSER DOORS TO PARTIALLY OPEN. THE MAXIMUM ICE BED TEMPERATURE RISE RECORDED WAS 2 F. TEST PROCEDURES WERE DEFICIENT. THEY HAVE BEEN REVISED TO PROVIDE A 30 MINUTE FAN COASTDOWN PERIOD PRIOR TO OPENING BACKDRAFT DAMPERS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PWR) * CONTAINMENT, ICE CONDENSER * TEST, SYSTEM OPERABILITY * HYDROGEN * CONTROL * CONTAINMENT INTEGRITY * PROCEDURES AND MANUALS * THERMAL TRANSIENT * BLOWERS * FAILURE, ADMINISTRATIVE CONTROL

104696

CONTAINMENT PRESSURE RELIEF FAN ISOLATION VALVE CLOSING TIME SLOW AT COOK 1
INDIANA & MICHIGAN POWER COMPANY, BRIGHTON, MICH.
3 PGS, LTR W/AD 75-20 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, JULY 20, 1975, DOCKET 50-315, TYPE--

104946 PLUTONIUM
-PWR, MFG--WEST., AE--UTILITY

CAUSE - DESIGN DEFICIENCY. DURING CONTAINMENT ISOLATION VALVE TESTING WITH THE REACTOR AT 50% POWER, THE CONTAINMENT PRESSURE RELIEF SYSTEM FAN ISOLATION VALVE CLOSING TIME EXCEEDED THE 10 SECOND LIMIT. THE ORIGINAL DESIGN VENTED THE VALVE DIAPHRAGM BACK THROUGH THE INSTRUMENT AIR HOUSING GREATLY SLOWING ISOLATION TIME. THE VENT VALVE HAS CHANGED SO THAT VENT FLOW IS NO LONGER THROUGH THE HOUSING. ISOLATION TIME IS NOW 2.6 SECONDS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOL 1 (PWR) + RESPONSE TIME + VALVES + CONTAINMENT ISOLATION + PRESSURE RELIEF + CONTAINMENT + TEST, SYSTEM OPERABILITY + FAILURE, DESIGN ERROR + PNEUMATIC SYSTEM + MODIFICATION

104947

STEAM GENERATOR BLOWDOWN ISOLATION VALVE CLOSING TIMES SLOW AT COOL 1
INDIANA & MICHIGAN POWER COMPANY, MICHIGAN

2 PGS. LTR #/ADR 75-30 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, JULY 20, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - DESIGN DEFICIENCY. DURING CONTAINMENT ISOLATION VALVE TESTING WITH THE REACTOR AT 50% POWER, ISOLATION TIMES FOR 2 STEAM GENERATOR ISOLATION VALVES EXCEEDED THE LIMIT. QUARTER INCH TUBING HAD BEEN USED FOR THE VENT WHICH RESTRICTED THE FLOW THUS SLOWING ISOLATION TIME. WHEN THE TUBING WAS REMOVED, ISOLATION TIMES DECREASED TO LESS THAN 4 SECONDS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOL 1 (PWR) + RESPONSE TIME + VALVES + CONTAINMENT ISOLATION + STEAM GENERATOR + BLOWDOWN + COOLANT PURIFICATION SYSTEM + FAILURE, DESIGN ERROR

104948

BORIC ACID TRANSFER PUMP FLOW RATE LESS THAN SPECS AT COOL 1
INDIANA & MICHIGAN POWER COMPANY, MICHIGAN

3 PGS. LTR WITH AD REPORT 75-30 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, AUG. 1, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - BORIC ACID CRYSTALS IN VALVES. DURING TESTING OF BORIC ACID TRANSFER PUMP 2 WITH THE REACTOR AT 80% POWER, THE FLOW RATE WAS FOUND TO BE 17.3 GPM. THE LIMIT IS 20 GPM. THE POSTULATED CAUSE WAS CRYSTALLIZATION OF BORIC ACID IN VALVE BOOTIES AND FITTINGS OF THE RECIRCULATION PATH. AFTER AN INCRUDINATE AMOUNT OF FLOW SURGING AND VALVE CYCLING, FLOW INCREASED TO 20 GPM.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOL 1 (PWR) + FLOW + RATE + CHEMICAL SHIM + POISON, SOLUBLE + PUMPS + TEST, SYSTEM OPERABILITY + FLOW BLOCKAGE

104949

REACTOR COOLANT PUMP SEAL BYPASS LINE LEAKS AT COOL 1
INDIANA & MICHIGAN POWER CO., MICHIGAN

3 PGS. LTR WITH AD REPORT 75-27 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, AUG. 6, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - IMPROPER WELD FIT UP. DURING A HOT SHUTDOWN TO INVESTIGATE TURBINE CONDENSER PROBLEMS, BURON BUILDUP WAS NOTED AROUND REACTOR COOLANT PUMP 2. THE WELD ON THE PUMP SEAL BYPASS LINE WAS LEAKING. THE 1 INCH SOCKET WELD WAS COMPLETELY GROUND OUT AND REWELDED WITH PROPER FIT UP. ORIGINALLY, THE PIPE WAS BUTTERED IN THE SOCKET.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOL 1 (PWR) + PIPES AND PIPE FITTINGS + WELDS + LEAK + FAILURE, PIPE + FAILURE, INSTALLATION ERROR + PUMPS + SEAL + REACTOR COOLANT + MAIN COOLING SYSTEM

104950

BORIC ACID TRANSFER PUMP FAILS AT COOL 1
INDIANA & MICHIGAN POWER CO., MICHIGAN

2 PGS. LTR WITH AD REPORT 75-40 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, AUG. 6, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - MECHANICAL SEAL FAILURE. WITH THE PLANT IN HOT SHUTDOWN PREPARING TO GO INTO HOT STANDBY, THE MECHANICAL SEAL ON BORIC ACID TRANSFER PUMP 1 FAILED PREVENTING THE PUMP FROM MEETING ITS DESIGNED FLOW REQUIREMENTS. NO CHANGE IN MODES WAS MADE UNTIL A NEW PUMP WAS INSTALLED AND TESTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

104956 CONTINUED
CHARGE \$2.00

COOL 1 (PWR) + PUMPS + PULSION, SOLUBLE + CHEMICAL SWIN + FAILURE, EQUIPMENT + SEAL + LEAK

105046
FAILED PRESSURIZER LEVEL CHANNEL NOT PLACED IN TRIPPED POSITION AT COOL 1
INDIANA & MICHIGAN POWER CO., MICH.
2 PGS., LETTER WITH AD REPORT 75-44 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, AUG. 12, 1975.
DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - OPERATOR ERROR. WHILE THE REACTOR WAS AT 40% POWER, A PRESSURIZER LEVEL CHANNEL FAILED TO LOW LEVEL SET POINT OF 58. THE HIGH LEVEL TRIP WAS NOT PLACED IN THE TRIP POSITION AS REQUIRED FOR 4 DAYS. WHEN THE CHANNEL FAILED LOW, OPERATORS FAILED TO ASSOCIATE THE HIGH LEVEL TRIP WITH IT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOL 1 (PWR) + INSTRUMENT, SWITCH + SENSORS, LEVEL + FAILURE, OPERATOR ERROR + REACTOR SAFETY SYSTEM

105047
PRESSURIZER PRESSURE CHANNELS MALFUNCTION AT COOL 1
INDIANA & MICHIGAN POWER CO., MICH.
3 PGS., LETTER WITH AD REPORT 75-43 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, AUG. 12, 1975.
DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - INSTALLATION ERROR. WHILE THE REACTOR WAS OPERATING AT 81% POWER, 2 PRESSURIZER PRESSURE CHANNELS WERE OBSERVED TO BE SLOWLY DECREASING. A PRESSURIZER LEVEL CHANNEL HAD BEEN ISOLATED EARLIER. DUE TO AN INSTALLATION ERROR, ISOLATION OF THE LEVEL TRANSMITTER ALSO ISOLATED THE PRESSURE TRANSMITTERS THROUGH A COMMON ROOT VALVE. WHEN THE VALVE WAS OPENED, PRESSURE ON BOTH CHANNELS RETURNED TO NORMAL. LATER, THE INSTRUMENT PIPING WAS SWITCHED TO CONFORM WITH AS BUILT DRAWINGS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOL 1 (PWR) + SENSORS, PRESSURE + PRESSURIZER + FAILURE, INSTALLATION ERROR + REACTOR SAFETY SYSTEM

104976
CONDENSATE STORAGE TANK LEVEL LESS THAN LIMIT AT COOL 1
INDIANA & MICHIGAN POWER COMPANY, BRIGHTON, MICH.
4 PGS., LTR W/ADJ 75-34 TO NRC OFFICE OF I & E, REGION 3, AUG. 13, 1975. DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - CONDENSER TUBE FAILURE. UNIT 1 WAS REMOVED FROM SERVICE DUE TO CONDENSER TUBE LEAKAGE. HIGH CONDUCTIVITY EXISTED IN THE STEAM GENERATORS. BLOWDOWN WAS MAINTAINED AT MAXIMUM TO MINIMIZE CONDUCTIVITY RESULTING IN THE LEVEL IN THE CONDENSATE STORAGE TANK DECREASING TO 127700 GALLONS. THIS IS BELOW THE TECH SPEC LIMIT. BLOWDOWN WAS DECREASED WHILE ADJUSTING MAKEUP PLANT CAPACITY. THE DECISION TO MAINTAIN MAXIMUM BLOWDOWN CAUSED THE LOW LEVEL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOL 1 (PWR) + SYSTEM CAPACITY + FEEDWATER + STORAGE CONTAINER + FAILURE, ADMINISTRATIVE CONTROL + COOLANT QUALITY + STEAM GENERATOR

105289
CHLORINE RESIDUAL IN EFFLUENT EXCEEDS LIMIT AT COOL 1
INDIANA & MICHIGAN POWER COMPANY, BRIGHTON, MICH.
2 PGS., LTR TO NRC OFFICE OF I & E, REGION 3, AUG. 13, 1975. DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - UNKNOWN. ROUTINE MONITORING OF THE CIRCULATING WATER SYSTEM DURING A CHLORINATION PROGRAM INDICATED THAT TOTAL CHLORINE RESIDUALS WERE IN EXCESS OF THE 0.1 PPM LIMIT FOR 10 MINUTES. THE CONCENTRATION PEAKED AT 0.25 PPM. NO PROBLEMS WERE FOUND EXCEPT THE CHLORINATOR ADDITIVE RATE CONTROLLER RACK AND PINION MAY HAVE BEEN STICKING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOL 1 (PWR) + CONCENTRATION + CHLORINE + EFFLUENT + CONDENSER COOLING SYSTEM

105517
CONTAINMENT AIR PARTICULATE DETECTOR PUMP FAILS AT COOL 1
INDIANA & MICHIGAN POWER COMPANY, BRIGHTON, MICH.
2 PGS., LTR W/ADJ 75-50 TO NRC OFFICE OF I & E, REGION 3, AUG. 27, 1975. DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

105517 CONTINUED

CAUSE - VIBRATION. WHILE THE REACTOR WAS OPERATING AT 60% POWER, THE CONTAINMENT AIR PARTICULATE DETECTOR AIR PUMP TRIP/PROG ENG FAILED TO RUN CONTINUOUSLY AFTER RESTARTING. GRAB SAMPLES WERE TAKEN EVERY 8 HOURS. THE RELAY FAILED DUE TO EXCESSIVE AIR PUMP VIBRATION. THE RIGID PIPING BETWEEN THE PUMP AND HIGH FLOW RELAY WAS REPLACED WITH FLEXIBLE TUBING TO RESOLVE THE PROBLEM.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOR 1 (PWR) + PUMPS + RADIATION MONITORS + MAINTEN. AIR + VIBRATION + RELAYS + FAILURE, DESIGN ERROR + MAINTENING SYSTEM, RADIATION

105518

CONTAINMENT PRESSURE CHANNELS NOT TESTED PROPERLY AT COOR 1

INDIANA & MICHIGAN POWER COMPANY, BRIGHTON, MICH.

2 PGS, LTR W/ADR 75-48 TO NRC OFFICE OF I & E, REGION 3, AUG. 27, 1975, DOCKET 50-315, TYPE--PWR, NRC--WEST., AE--UTILITY

CAUSE - DEFECTIVE PROCEDURES. A REVIEW OF CONTAINMENT PRESSURE CHANNEL TESTS INDICATED THAT THE TESTS DID NOT FULLY SATISFY TECH SPECS AS WRITTEN. PROCEDURES WERE DEFICIENT. WITH THE DISTABLE TRIP SWITCH IN THE TEST POSITION AS SPECIFIED, THE SIGNAL TO THE SOLID STATE PROTECTION SYSTEM IS INHIBITED. PROCEDURES HAVE BEEN CHANGED TEMPORARILY UNTIL THE NEXT SCHEDULED REVIEW DATE FOR PROCEDURES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOR 1 (PWR) + PROCEDURES AND MANUALS + TESTING + ELECTRONIC FUNCTION UNITS + CONTAINMENT + FAILURE, ADMINISTRATIVE CONTROL + MODIFICATION + INSTRUMENT, SWITCH + PRESSURE, INTERNAL

105519

SET POINT DRIFT IN FLOW SENSOR AT COOR 1

INDIANA & MICHIGAN POWER COMPANY, BRIGHTON, MICH.

2 PGS, LTR W/ADR 75-49 TO NRC OFFICE OF I & E, REGION 3, AUG. 27, 1975, DOCKET 50-315, TYPE--PWR, NRC--WEST., AE--UTILITY

CAUSE - INSTRUMENT DRIFT. DURING REACTOR COOLANT FLOW TESTING WITH THE UNIT AT 60% POWER, A DISTABLE TRIP POINT WAS 0.3655 VDC WHICH IS BELOW THE 0.3600 VDC LIMIT. THE APPARENT CAUSE WAS INSTRUMENT DRIFT. THE DISTABLE WAS RECALIBRATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOR 1 (PWR) + INSTRUMENT, SWITCH + INSTRUMENT CALIBRATION + SENSORS, FLOW + TEST, SYSTEM OPERABILITY + FAILURE, INSTRUMENT + SET POINT + DRIFT + REACTOR SAFETY SYSTEM + ELECTRONIC FUNCTION UNITS

105519

PROCEDURE USED PRIOR TO BEING APPROVED AT COOR 1

INDIANA & MICHIGAN POWER COMPANY, BRIGHTON, MICH.

2 PGS, LTR W/ADR 75-48 TO NRC OFFICE OF I & E, REGION 3, AUG. 27, 1975, DOCKET 50-315, TYPE--PWR, NRC--WEST., AE--UTILITY

CAUSE - PERSONNEL ERROR. THE REACTOR COOLANT SYSTEM WAS FILLED AND VENTED USING A REVISED PROCEDURE THAT HAD NOT BEEN APPROVED BY THE PLANT NUCLEAR SAFETY AND REVIEW COMMITTEE. THE PERSON RESPONSIBLE FOR PRESENTING IT TO THE COMMITTEE MISPLACED THE NOTICE OF CHANGE AND REALIZED THAT HE HAD IT 10 DAYS LATER AT WHICH TIME IT WAS PRESENTED AND APPROVED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOR 1 (PWR) + REVIEW + PROCEDURES AND MANUALS + MODIFICATION + FAILURE, ADMINISTRATIVE CONTROL

105722

SEISMIC TRIGGER NOT TESTED AS REQUIRED AT COOR 1

INDIANA & MICHIGAN POWER COMPANY, BRIGHTON, MICH.

2 PGS, LTR W/ADR 75-47 TO NRC OFFICE OF I & E, REGION 3, AUG. 29, 1975, DOCKET 50-315, TYPE--PWR, NRC--WEST., AE--UTILITY

CAUSE - NOT ACCESSIBLE DURING OPERATION. AN INTERNAL AUDIT DISCLOSED THAT THE SEISMIC TRIGGER ON THE REACTOR PIT FLOOR HAD NOT BEEN TESTED AS REQUIRED. THE LOCATION OF THE COMPONENTS PREVENTS TESTING DURING PLANT OPERATION. A TECH SPEC CHANGE WILL BE REQUIRED TO CHANGE THE FREQUENCY OF TESTING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOR 1 (PWR) + TEST INTERVAL + INSTRUMENT, EARTHQUAKE + TESTING + FAILURE, ADMINISTRATIVE CONTROL + INSTRUMENT CALIBRATION

106366

TESTING OF REACTOR TRIP BREAKERS NOT PERFORMED ON TIME AT COOK 1

INDIANA & MICHIGAN POWER CO., MICH.

2 PGS. LTR W/AD 50-315/75-52 TO NRC OFFICE OF I & E, REGION III, SEPT. 13, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - NOT ON TEST SCHEDULE. INTERNAL AUDITING REVEALED THAT MONTHLY CHANNEL FUNCTIONAL TESTS OF REACTOR TRIP BREAKERS WERE NOT PERFORMED FOR APRIL, MAY, AND JULY 1975. THIS MONTHLY TEST WAS NOT INCLUDED ON THE TEST SCHEDULE. THE SCHEDULE HAS BEEN REVISED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PWR) • TESTING • BREAKER • REACTOR SAFETY SYSTEM • FAILURE, ADMINISTRATIVE CONTROL • REVIEW • TEST INTERVAL

106371

RHR PUMP VALVE FAILS TO CLOSE AT COOK 1

INDIANA & MICHIGAN POWER CO., MICH.

2 PGS. LTR W/AD 75-55 TO NRC OFFICE OF I & E, REGION III, SEPT. 12, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - IMPROPER TORQUE SWITCH SETTING. DURING TESTING WITH THE REACTOR AT 818 POWER, WEST REGIONAL HEAT REMOVAL PUMPS VALVE WAS OPENED BUT COULD NOT BE CLOSED REMOTELY. IT WAS MANUALLY CLOSED USING THE HANDWHEEL. THE LIMITORQUE SWITCH WAS AT ITS MINIMUM POSSIBLE SETTING. THE SWITCH WAS RESET FROM 2.0 TO 2.75 AND THE VALVE CYCLED SUCCESSFULLY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

VALVES • SHUTDOWN COOLING SYSTEM • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT • INSTRUMENT, SWITCH • SET POINT • FAILURE, MAINTENANCE ERROR • COOK 1 (PWR)

106373

CONTAINMENT AIR PARTICULATE MONITOR PUMP FAILS AT COOK 1

INDIANA & MICHIGAN POWER CO., MICH.

2 PGS. LTR W/AD 75-56 TO NRC OFFICE OF I & E, REGION III, SEPT. 12, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - BEARING FAILURE. WHILE THE REACTOR WAS OPERATING AT 838 POWER, THE CONTAINMENT AIR PARTICULATE MONITOR PUMP SEIZED. SEIZURE WAS DUE TO FAILURE OF BEARINGS. A PUMP WITH BEARINGS OF IMPROVED DESIGN IS ON ORDER. A NEW ONE FROM SPARES WAS INSTALLED UNTIL THE IMPROVED MODEL IS RECEIVED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PWR) • MONITOR, AIR • CONTAINMENT • PUMPS • BEARING • FAILURE, EQUIPMENT • FAILURE, DESIGN ERROR • MONITORING SYSTEM, RADIATION

106372

SEISMIC MONITORING SYSTEM MALFUNCTION AT COOK 1

INDIANA & MICHIGAN POWER CO., MICH.

2 PGS. LTR W/AD 75-56 TO NRC OFFICE OF I & E, REGION III, SEPT. 12, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - SEVERE AMPLIFIER BALANCE SHIFT. DURING TESTING OF THE SEISMIC MONITORING SYSTEM WITH THE REACTOR SHUTDOWN, CHANNEL 1 ON THE REACTOR PIT FLOOR WAS FOUND INCAPABLE OF PRODUCING AN ACCEPTABLE TEST-CALIBRATED PATTERN. THE CAUSE WAS A SEVERE AMPLIFIER BALANCE SHIFT. THE AMPLIFIER BOARD WAS REPLACED WITH A SPARE AND THE UNIT RETESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PWR) • INSTRUMENT, EARTHQUAKE • INSTRUMENT, AMPLIFIER • INSTRUMENT CALIBRATION • ELECTRONIC FUNCTION UNITS • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT • MONITOR

106408

UNIT 2 AUXILIARY FEEDWATER PUMP NOT TESTED AS REQUIRED AT COOK 1

INDIANA & MICHIGAN POWER CO., MICH.

2 PGS. LTR W/AD 75-60 TO NRC OFFICE OF I & E, REGION III, SEPT. 22, 1975, DOCKET 50-315, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - MISUNDERSTANDING OF REQUIREMENTS. DURING REVIEW OF TEST PROCEDURES WHILE OPERATING AT 818 POWER, IT WAS DISCOVERED THAT UNIT 2 MOTOR DRIVEN AUXILIARY FEEDWATER PUMP WAS NOT BEING TESTED FOR PROOF OF EMERGENCY SUCTION FROM THE ESSENTIAL SERVICE WATER SYSTEM. THE EMERGENCY SUCTION VALVE WAS IMMEDIATELY CYCLED. PREVIOUS TO THIS REVIEW, THIS VALVE WAS CONSIDERED A UNIT 2 VALVE NOT REQUIRING TESTING UNTIL UNIT 2 STARTUP. PROCEDURES HAVE BEEN MODIFIED.

100000 CONTINUED
 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

COOL 1 (PWR) + TEST INTERVAL + TESTING + VALUES + PUMPS + FREEWATER + FAILURE, ADMINISTRATIVE CONTROL +
 PROCEDURES AND MANUALS + SHARED COMPONENTS + EMERGENCY COOLING + REVIEW

100000
 BORIC ACID TRANSFER PUMP REMOVED FROM SERVICE AT COOL 1
 INDIANA & MICHIGAN POWER CO., MICH.
 2 PGS, LTR W/NO 75-59 TO NRC OFFICE OF I & E, REGION III, SEPT. 22, 1975, DOCKET 50-315, TYPE--PWR, NRC--
 WEST., AE--UTILITY

CAUSE - SEAL FAILURE. WITH THE PLANT OPERATING AT 80% POWER, THE BORIC ACID TRANSFER PUMP WAS
 REMOVED FROM SERVICE DUE TO EXCESSIVE LEAKAGE. THE JUMP CHANE MECHANICAL SEAL HAD FAILED. A
 NEW SEAL WAS INSTALLED. THIS HAS BEEN A RECURRING PROBLEM. A REVISION TO THESE SEALS IS BEING
 FINALIZED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

COOL 1 (PWR) + SEAL + PUMPS + CHEMICAL SHIM + FAILURE, DESIGN ERROR

100007
 RECIRCULATING FLOW IN BORON INJECTION TANK REDUCED AT COOL 1
 INDIANA & MICHIGAN POWER CO., MICH.
 2 PGS, LTR W/NO 75-59 TO NRC OFFICE OF I & E, REGION III, SEPT. 22, 1975, DOCKET 50-315, TYPE--PWR, NRC--
 WEST., AE--UTILITY

CAUSE - BORON CRYSTALLIZATION. WHILE OPERATING AT 80% POWER, RECIRCULATION FLOW IN THE BORON
 INJECTION TANK DECREASED RESULTING IN THE LEVEL IN THE BIT DROPPING TO 85%. REDUCED FLOW WAS
 CAUSED BY BORON CRYSTALLIZATION ON VALVE INTERNALS. MANUAL OPERATION OF THE VALVES REMOVED THE
 CRYSTALS AND RESTORED FLOW. CRYSTALLIZATION WAS DUE TO FAILURE OF HEAT TAPE TO MAINTAIN PROPER
 TEMPERATURE. MODIFICATIONS ARE IN PROGRESS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

COOL 1 (PWR) + STORAGE CONTAINER + SAFETY INJECTION + SYSTEM CAPACITY + PLOW BLOCKAGE + BORON + FAILURE,
 DESIGN ERROR + TEMPERATURE + HEATERS

100009
 WIND SPEED INDICATOR FAILS AT COOL 1
 INDIANA & MICHIGAN POWER CO., MICH.
 2 PGS, LTR W/NO 75-63 TO NRC OFFICE OF I & E, REGION III, SEPT. 22, 1975, DOCKET 50-315, TYPE--PWR, NRC--
 WEST., AE--UTILITY

CAUSE - CUP ASSEMBLY BLOWN OFF. WHILE OPERATING AT 80% POWER, THE WIND SPEED INDICATION FROM THE
 150 FT LEVEL AT THE MICROWAVE TOWER FAILED. THE ANEMOMETER CUP ASSEMBLY HAD BEEN BLOWN OFF
 DURING A LOCAL WIND STORM. A NEW TYPE ASSEMBLY WAS INSTALLED AND THE SYSTEM RETURNED TO
 OPERATION WITHIN 48 HOURS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

COOL 1 (PWR) + INSTRUMENT, METEOROLOGICAL + FAILURE, INSTRUMENT + DESTRUCTIVE WIND + FAILURE, DESIGN ERROR

100014
 SAFETY INJECTION OCCURS AT COOL 1
 INDIANA & MICHIGAN POWER CO., MICH.
 3 PGS, LTR W/NO 75-02 TO NRC OFFICE OF I & E, REGION III, SEPT. 23, 1975, DOCKET 50-315, TYPE--PWR, NRC--
 WEST., AE--UTILITY

CAUSE - OPERATOR ERROR. WHILE THE REACTOR WAS IN HOT STANDBY WITH THE REACTOR COOLANT SYSTEM
 BEING HEATED UP, AN ANNUNCIATOR ALARM WAS RECEIVED INDICATING FAILURE OF INVERTOR CRIO-IV FOR
 VITAL BUS CHANNEL IV. THE OPERATOR MISTAKENLY READ IT AS CRIO II AND DIRECTED THAT ALTERNATE AC
 POWER SUPPLY TO CRIO II BE PLACED IN SERVICE. THE TRANSFER CAUSED A MOMENTARY LOSS OF POWER
 MAKING 2 VITAL BUSES DEENERGIZED. THIS CAUSED A REACTOR TRIP AND SAFETY INJECTION. SAFETY
 INJECTION WAS TERMINATED AFTER 150 GALLONS HAD BEEN INJECTED. NO DAMAGE OCCURRED. ROMAN
 NUMERALS WILL BE CHANGED TO ARABIC NUMERALS. THIS OCCURRED ON JUNE 26, 1975.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

COOL 1 (PWR) + SAFETY INJECTION + FAILURE, OPERATOR ERROR + SCRAM, REAL + ANNUNCIATORS

100003

106603 CONTINUED

TEST LINES ON SERVICE WATER PIPING FAIL TO MEET CODE AT COOK 1
AMERICAN ELECTRIC POWER SERVICE CORP., ALY.

2 PGS. LTR W/AD 50-315/75-01 TO NRC OFFICE OF I & E, REGION III, SEPT. 29, 1975, DOCKET 50-315, TYPE--PNR, NRC--WEST., AE--UTILITY

CAUSE - FAILURE TO FOLLOW REQUIREMENTS. LEAKAGE TEST LINES WERE ADDED TO THE NON-ESSENTIAL SERVICE WATER PIPING. A REVIEW OF DOCUMENTATION REVEALED THAT 10 WELDED BRANCH CONNECTIONS FOR 1/2 INCH TEST LINES HAD NOT BEEN MADE WITH FULL PENETRATION WELDS AS REQUIRED. ALL 10 WILL BE REPLACED WITH PROPERLY PREPARED HALF-COUPPLINGS USING FULL PENETRATION WELDS. THE 1/2 INCH VALVES WERE INSTALLED TO QUALITY LEVEL D RATHER THAN THE REQUIRED QUALITY LEVEL B. NINE HAVE BEEN UPGRADED TO LEVEL B. THE OTHERS WILL BE REPLACED. VALVES OF BOTH QUALITY LEVELS WERE STORED IN THE SAME BIN. SEPARATE STORAGE BINS WILL BE USED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PNR) • GELIDS • VALVES • COJRS AND STANDARDS • FAILURE, ADMINISTRATIVE CONTROL • MODIFICATION • AUXILIARY COOLING • PIPES AND PIPE FITTINGS • FAILURE, INSTALLATION ERROR • QUALITY ASSURANCE

106605

FLOW BLOCKAGE PROBLEMS OCCUR IN THE BORIC ACID SYSTEM AT COOK 1
INDIANA & MICHIGAN POWER CO., BRIGHTON, MICH.

2 PGS. LTR W/AD 75-01 TO NRC OFFICE OF I & E, REGION III, SEPT. 29, 1975, DOCKET 50-315, TYPE--PNR, NRC--WEST., AE--UTILITY

CAUSE - BORON CRYSTALLIZATION. TECH SPEC REQUIRES A FLOW PATH FROM THE BORIC ACID TANKS VIA THE BORIC ACID TRANSFER PUMPS AND 1 CHARGING PUMP TO THE REACTOR COOLANT SYSTEM. THIS PATH HAS MADE IMPOSSIBLE 4 TIMES FOR WORK IN THE BORON INJECTION TANK RECIRCULATION LINE WHEN THE BORIC ACID TRANSFER PUMP HAD TO BE ISOLATED. THE REACTOR WAS AT 918 PPMR EACH TIME. FLOW BLOCKAGE RESULTS FROM THE ACCUMULATION OF BORON CRYSTALS. CONSIDERABLE EFFORT HAS BEEN MADE TO DETERMINE AREAS OF HEAT LOSS. HEAT TRACING IN SOME LINES HAS BEEN REPLACED AND ADDITIONAL HEAT TRACING INSTALLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PNR) • FLOW BLOCKAGE • PIPES AND PIPE FITTINGS • CHEMICAL SHIM • POISON, SOLUBLE • SAFETY INJECTION • HEATERS • BORON • CONSTRUCTION

107001

BORIC ACID PUMP TAKEN OUT OF SERVICE AT COOK 1

INDIANA & MICHIGAN POWER CO., BRIGHTON, MICH.

2 PGS. LTR W/AD 50-315/75-07 TO NRC OFFICE OF I & E, REGION III, OCT. 10, 1975, DOCKET 50-315, TYPE--PNR, NRC--WEST., AE--UTILITY

CAUSE - MECHANICAL SEAL FAILURE. WHILE OPERATING AT 818 PPMR, BORIC ACID PUMP 2 WAS TAKEN OUT OF SERVICE DUE TO EXCESSIVE MECHANICAL SEAL LEAKAGE. A NEW JOURNAL CRANE SEAL WAS INSTALLED AND THE PUMP RETURNED TO SERVICE WITHIN THE REQUIRED 72 HOUR PERIOD. PLANS HAVE BEEN FINALIZED FOR A REVISION TO THESE SEALS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PNR) • SEAL • PUMPS • CHEMICAL SHIM • POISON, SOLUBLE • FAILURE, DESIGN ERROR

107779

HYDROGEN MONITORING SYSTEM NOT CALIBRATED ON SCHEDULE AT COOK 1

INDIANA & MICHIGAN POWER CO., BRIGHTON, MICH.

3 PGS. LTR W/AD 50-315/75-70 TO NRC OFFICE OF I & E, REGION III, OCT. 29, 1975, DOCKET 50-315, TYPE--PNR, NRC--WEST., AE--UTILITY

CAUSE - OVERSIGHT. INTERNAL AUDITING REVEALED THAT THE CONTAINMENT HYDROGEN MONITORING SYSTEM CALIBRATION WAS NOT PERFORMED APRIL 26, 1975 AS REQUIRED DUE TO MANPOWER SHORTAGE. IT WAS NOT RESCHEDULED DUE TO OVERSIGHT. SCHEDULES HAVE BEEN REVISED TO PREVENT RECURRENCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PNR) • TEST INTERVAL • INSTRUMENT CALIBRATION • HYDROGEN • MONITOR • FAILURE, ADMINISTRATIVE CONTROL • CONTAINMENT

107780

MRV VALVE FAILS TO CLOSE AT COOK 1

INDIANA & MICHIGAN POWER CO., BRIGHTON, MICH.

2 PGS. LTR W/AD 50-315/75-08 TO NRC OFFICE OF I & E, REGION III, OCT. 31, 1975, DOCKET 50-315, TYPE--PNR, NRC--WEST., AE--UTILITY

CAUSE - FACTORY SET POINT TOO LOW. DURING TESTING WITH THE REACTOR AT 818 PPMR, THE MOTOR

107766 ALUMINUM

OPERATION MAINTENANCE CLOSE THE EAST RAMP PUMP-TU-LOOPS 1 AND 4 COLD LEGS VALVE. THE VALVE WAS 1 OF 4 VALVE OPERATORS. EXPERIENCE SHOWS FACTORY SETTINGS OF THE TORQUE SWITCHES ARE TOO LOW FOR THIS APPLICATION. SETTING ON ALL 4 SWITCHES WAS INCREASED FROM 2.0 TO 3.5 TO ASSURE POSITIVE OPERATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CUOM 1 (PWR) • VALVES • VALVE OPERATORS • SHUTDOWN COOLING SYSTEM • TEST, SYSTEM OPERABILITY • FAILURE, FABRICATION ERROR • RESET POINT • INSTRUMENT, SWITCH

109273

BORIC ACID TRANSFER PUMP REMOVED FROM SERVICE AT CUOM 1

INDIANA & MICHIGAN POWER CO., BRIDGEMAN, MI

4 PGS, LTR N/AO 50-315/75-72 TO NRC OFFICE OF I & E, REGION III, NOV. 5, 1975, DOCKET 50-315, TYPE--PWR, NRC--WEST, AE--UTILITY

CAUSE - CASING SEEPAGE. WHILE THE REACTOR WAS AT B18 POWER, BORIC ACID TRANSFER PUMP WAS TAKEN OUT OF SERVICE TO CORRECT CASING SEEPAGE. THE LEAK WAS BETWEEN THE STUFFING BOX COVER AND THE CASING. THERE PROBABLY WAS DAMAGE TO THE GASKET SEALING SURFACE IN THE PUMP CASING. THE CASING WAS REPAIRED AND LEAKAGE WAS CORRECTED. THE PUMP WAS REPAIRED WITHIN THE TIME LIMIT AND PUT IN SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CUOM 1 (PWR) • PUMPS • PLEAK • CHEMICAL SHIM • POISON, SOLUBLE • FAILURE, EQUIPMENT

109272

BORIC ACID TRANSFER PUMP REMOVED FROM SERVICE AT CUOM 1

INDIANA & MICHIGAN POWER CO., BRIDGEMAN, MI

2 PGS, LTR N/AO 50-315/75-71 TO NRC OFFICE OF I & E, REGION III, NOV. 5, 1975, DOCKET 50-315, TYPE--PWR, NRC--WEST, AE--UTILITY

CAUSE - PUMP SHAFT SEAL LEAKAGE. WITH THE REACTOR OPERATING AT B18 POWER, BORIC ACID TRANSFER PUMP NO. 1 WAS TAKEN OUT OF SERVICE TO CORRECT PUMP SHAFT SEAL LEAKAGE. THE JOHN CRANE MECHANICAL SEAL FAILED. FOR EXPEDIENCY, THE CASING AND ACTOR WITH A NEW SHAFT SEAL WERE INSTALLED. THE PUMP WAS REPAIRED WITHIN THE TIME AND PUT IN SERVICE. THIS IS A RECURRING PROBLEM. PLANS FOR A REDESIGNED SEALING SYSTEM HAVE BEEN FINALIZED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CUOM 1 (PWR) • PUMPS • SEAL • PLEAK • POISON, SOLUBLE • CHEMICAL SHIM • FAILURE, EQUIPMENT • FAILURE, DESIGN ERROR

108074

OPENING TORQUE OF ICE CONDENSER DOORS EXCEEDS LIMIT AT CUOM 1

INDIANA & MICHIGAN POWER CO., BRIDGEMAN, MICHIGAN

3 PGS, LTR N/AO 50-315/75-69 PLUS SUPPLEMENTAL RPT TO NRC OFFICE OF I & E, REGION III, NOV. 17, 1975, DOCKET 50-315, TYPE--PWR, NRC--WEST, AE--UTILITY

CAUSE - ICE BUILDUP AT SEAL. WHILE THE UNIT WAS SHUT DOWN, THE OPENING TORQUE FOR 10 OF THE 40 ICE CONDENSER DOORS WAS FOUND TO EXCEED THE 675 INCH POUND LIMIT. ICE HAD BUILT UP AT THE BOTTOM SEAL-DOOR INTERFACE OF THE LOWER INLET DOORS. CONDENSATION WAS OCCURRING OUTSIDE THE DOOR AT THE BOTTOM DOOR FRAME SURFACE IN 20 OF THE 24 DAYS FROM HUMIDITY IN THE WARM ATMOSPHERE. THE FLOOR COOLING SYSTEM WAS ADJUSTED TO RAISE FLOOR TEMPERATURE TO 15 F. INSULATION THAT HAD BECOME WATER SOAKED WAS REPLACED. INSULATION WAS PLACED ON THE LOWER INLET DOOR METAL FRAME STRIP TO RETARD CONDENSATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CUOM 1 (PWR) • COMPONENTS • CONTAINMENT, ICE CONDENSER • TEST, SYSTEM OPERABILITY • CONDENSATION • FAILURE, DESIGN ERROR • INSULATION • HUMIDITY, RELATIVE • SEAL • FAILURE, COMMON MODE

108529

WIND SPEED AND DIRECTION RECORDER FOUND INOPERABLE AT CUOM 1

INDIANA & MICHIGAN POWER CO., BRIDGEMAN, MICH.

2 PGS, LTR N/AO 50-315/75-73 TO NRC OFFICE OF I & E, REGION III, DEC. 3, 1975, DOCKET 50-315, TYPE--PWR, NRC--WEST, AE--UTILITY

CAUSE - STRUCK BY BIRD. WHILE THE REACTOR WAS SHUT DOWN, THE WIND SPEED AND DIRECTION RECORDER FOR THE 150 FOOT LOCATION BECAME INOPERABLE. APPARENTLY, A BIRD STRUCK THE ASSEMBLY AS EVIDENCED BY THE PRESENCE OF BLOOD AND FEATHERS ON THE TOWER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

100229 *CONTINUED*

COOK 1 (PWR) * INSTRUMENT, METEOROLOGICAL * ANIMAL, BIRD * FAILURE, INSTRUMENT * WIND STATISTICS

100029

CLOSING TIME OF STEAM GENERATOR VALVE EXCEEDS LEVEL AT COOK 1

INDIANA & MICHIGAN POWER CO., BRIDGMAN, MI

3 PGS. LTR W/AD 50-315/75-74 TO NRC OFFICE OF I & E, REGION III, DEC. 10, 1975, DOCKET 50-315, TYPE--PWR, NEG--WEST., AE--UTILITY

CAUSE - SPRING TENSION SET IMPROPERLY. DURING A TEST WITH THE REACTOR AT 58 POWER, LOOP 2 STEAM GENERATOR STOP VALVE FAILED TO CLOSE WITHIN THE REQUIRED 5 SECONDS. ACTUAL CLOSURE TIMES WERE 9.0 AND 9.2 SECONDS IN 2 TESTS. THE HYDRAULIC SYSTEM COMPRESSION SPRING TENSION SETTING, WHICH IS CONTROLLED BY ADJUSTING THE THROTTLING BYPASS VALVE, WAS SLIGHTLY OUT OF ADJUSTMENT. THE BYPASS VALVE WAS ADJUSTED TO REDUCE CLOSING TIME TO 2.0 SECONDS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PWR) * RESPONSE TIME * VALVES * STEAM GENERATOR * CONTAINMENT ISOLATION * TEST, SYSTEM OPERABILITY * FAILURE, MAINTENANCE ERROR * SET POINT

100271

SEISMIC MONITORING SYSTEM FOUND UNSATISFACTORY AT COOK 1

INDIANA & MICHIGAN POWER CO., BRIDGMAN, MI

3 PGS. LTR W/AD 50-315/75-75 TO NRC OFFICE OF I & E, REGION III, DEC. 17, 1975, DOCKET 50-315, TYPE--PWR, NEG--WEST., AE--UTILITY

CAUSE - TEMPERATURE AND FLUX EFFECTS. WHILE OPERATING AT 80% POWER, SURVEILLANCE TESTING OF THE SEISMIC MONITORING SYSTEM FOUND THE REACTOR PIT FLOOR CHANNEL UNSATISFACTORY. THE AMPLIFIER BALANCE SHIFTED IN 2 OF THE 3 CHANNELS. SHIFT WAS APPARENTLY DUE TO EXCESSIVE TEMPERATURES AND NEUTRON FLUX LEVELS AT POWER. BOARDS OF IMPROVED DESIGN AND WIDER TEMPERATURE AND FLUX TOLERANCES ARE BEING ASSEMBLED BY KINEMATICS AND SHOULD ARRIVE ON SITE BY JAN. 1, 1976.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PWR) * INSTRUMENT, EARTHQUAKE * TEST, SYSTEM OPERABILITY * TEMPERATURE * RADIATION DAMAGE * FAILURE, DESIGN ERROR * DRIFT

100619

SAFETY INJECTION ACTUATION OCCURS AT COOK 1

INDIANA & MICHIGAN POWER CO., BRIDGMAN, MI

3 PGS. LTR W/SPECIAL RPT SI-03 TO NRC OFFICE OF I & E, REGION III, DEC. 31, 1975, DOCKET 50-315, TYPE--PWR, NEG--WEST., AE--UTILITY

CAUSE - UNKNOWN. WHILE OPERATING AT 81% POWER WITH SYSTEM CONTROLS IN AUTOMATIC AND FUNCTIONING PROPERLY, ALL REACTOR PROTECTION SYSTEM STATUS LIGHTS FLASHED ON AND OFF SEVERAL TIMES. ON THE SECOND OR THIRD CYCLE REACTOR/TURBINE TRIP AND SAFETY INJECTION WITH STEAM LINE ISOLATION WAS VERIFIED. AFTER ASSURING THAT ALL CRITICAL PARAMETERS WERE NORMAL, SAFETY INJECTION WAS TERMINATED AFTER 900 GALLONS WERE INJECTED IN 3 MINUTES. THOROUGH CHECKING OF POWER SUPPLIES AND TESTING OF THE APS DID NOT REVEAL ANY ABNORMALITIES. NO EVIDENCE OF DAMAGE WAS FOUND. THIS IS THE 3RD INADVERTENT ACTUATION OF THE SAFETY INJECTION SYSTEM.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COOK 1 (PWR) * SAFETY INJECTION * SCRAM, SPURIOUS * ACCIDENT, LOSS OF POWER * THERMAL TRANSIENT

099010

FAILURES IN REACTOR PROTECTION TEST PANEL CIRCUITS AT COOK 1 AND 2

INDIANA AND MICHIGAN ELECTRIC COMPANY

6 PAGES, LETTER WITH RD INQUIRY REPORTS 74/01Q, 74/02Q TO DIRECTORATE OF REGULATORY OPERATIONS, JANUARY 14, 1975, DOCKET 50-315/316, TYPE--PWR, NEG--WEST., AE--UTILITY

CAUSE - INADEQUATE COMPONENTS. (1) A LAMP PROTECTION DIODE SHORTED AND DESTROYED CONTROL WIRE INSULATION DURING 2 DIFFERENT TESTS. THE DIODES WERE INADEQUATE FOR INTENDED SERVICE. ABOUT 140 DIODES/UNIT WERE REPLACED WITH VARISTORS. DAMAGED WIRING WAS REPLACED. (2) A GENERIC PROBLEM WAS DISCOVERED ON THE TEST PANEL ASSOCIATED WITH REACTOR CONTROL AND PROTECTIVE SYSTEM RACKS AND CABINETS. CERTAIN TYPES OF SHORT CIRCUITS COULD REMAIN UNDETECTED THAT COULD PREVENT A VALID UNSTABLE TRIP SIGNAL. THE TEST SWITCHES (ABOUT 144/UNIT) WERE REMOVED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT * CONTROL SYSTEM * TESTING * INSTRUMENT, SWITCH * MODIFICATION * FAILURE, DESIGN ERROR * COOK 1 (PWR) * COOK 2 (PWR) * CONSTRUCTION * FAILURE, COMMON MODE * ELECTRONIC FUNCTION UNITS

102541
WELD DEFICIENCIES DURING CONSTRUCTION CORRECTED AT COKR 1 AND 2
AMERICAN ELECTRIC POWER SERVICE CORPORATION, N.Y.
4 PAGES, LETTERS TO AEC DIRECTORATE OF REGULATORY OPERATIONS, DECEMBER 30, 1974 AND JANUARY 21, 1975. DOCKETS
50-302/210. TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - USE OF INCORRECT PROCEDURES. A DEFICIENCY INVOLVING USE OF AN INCORRECT WELDING PROCEDURE FOR WELDING THE LOW ALLOY STEAM GENERATOR NOZZLES TO CARBON STEEL PIPING WAS REPORTED EARLIER. FURTHER INVESTIGATION FOUND 12 P-5 AND P-6 GROUP ALLOY VALVES 2 INCHES AND SMALLER WHICH WERE SOCKET WELDED TO CARBON STEEL PIPE IMPROPERLY. TO CORRECT THIS, THEY HAVE BEEN HEAT TREATED AND RT/PT INSPECTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

COKR 1 (PWR) + COKR 2 (PWR) + CONSTRUCTION + WELDS + HEAT TREATMENT + FAILURE, ADMINISTRATIVE CONTROL + PROCEDURES AND MANUALS + PIPES AND PIPE FITTINGS + VALVES

102227
FUEL ASSEMBLY DROPPED AT CRYSTAL RIVER 3
FLUORIDA POWER CORP.
3 PGS. LTR N/1-75-1 TO NRC OFFICE OF I & E, NOV. 23, 1975. DOCKET 50-302, TYPE--PWR, MFG--EM, AE--GILBERT ASSOC.

CAUSE - CABLE PULLED OUT OF SWAGE FITTING. FUEL ASSEMBLY 3433 FELL ABOUT 5 FEET DURING TRANSFER FROM ITS SHIPPING CONTAINER TO THE INSPECTION STATION. THE WIRE CABLE FOR THE FUEL HANDLING TOOL PULLED OUT OF ITS SWAGE FITTING. THE CABLE WAS CERTIFIED TO SUPPORT 2400 LBS. THE ASSEMBLY WEIGHED 1550 LBS. THE CAUSE OF FAILURE IS STILL UNDER STUDY. SOME FUEL PINS WERE BOWED OUT SOME RUPTURED. SOME SPACER GRIDS WERE BOWED. THE LOWER END FITTING WAS BENT. SOME WELDS OF THE FUEL HANDLING TOOL WERE CRACKED. NO RADIOACTIVITY RELEASE OCCURRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CRYSTAL RIVER 3 (PWR) + CONSTRUCTION + FUEL HANDLING MACHINE + CABLES AND CONNECTORS + DAMAGE + FUEL HANDLING + FAILURE, EQUIPMENT + FUEL ELEMENTS

101700
MPS PUMP MOTORS FAIL TO MEET SPECIFICATIONS AT JAVIS-BESSE
TOLEDO EUSON COMPANY, OHIO
2 PAGES, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, FEBRUARY 20, 1975. DOCKET 50-346, TYPE--PWR, MFG--B&B, AE--BECHTEL

CAUSE - DESIGN DEFICIENCY. TWO 600 HP, 4000 VOLT HIGH PRESSURE INJECTION PUMP MOTORS WERE REPORTED BY WESTINGHOUSE TO BE IN NONCONFORMANCE WITH THE SPECS. REQUIRING ACCELERATION TO NORMAL OPERATING SPEED WITHIN 6 SECONDS AT 720 VOLTAGE. THE MOTORS WERE RETURNED TO THE VENDOR FOR MODIFICATIONS. STARTING TORQUE WAS INCREASED BY INCREASING ROTOR RESISTANCE. AN INTEGRAL AXIAL BLUNDER WAS ADDED TO OVERCOME THE ADDITIONAL HEATING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

DESIGN CRITERIA + SAFETY INJECTION + MODIFICATION + FAILURE, DESIGN ERROR + CONSTRUCTION + MOTORS

102230
480-V AIR CIRCUIT BREAKER DEFICIENCIES AT DAVIS-BESSE I
TOLEDO EUSON COMPANY, OHIO
2 PAGES, LETTER TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, MARCH 14, 1975. DOCKET 50-346, TYPE--PWR, MFG--B&B, AE--BECHTEL

CAUSE - TEST DEFICIENCY. DURING ON-SITE TESTING OF GE 480 VOLT AIR CIRCUIT BREAKERS, SEVERAL APPARENT DEFICIENCIES WERE NOTED. THE MAGNETIC TRIP SOLENOIDS FAILED TO TRIP WHEN ENERGIZED BY A TRIP SIGNAL FROM THE TEST SET. THIS WAS DUE TO LOW ENERGY OUTPUT OF THE TEST SET COUPLED WITH A SLIGHT BINDING. THE SOLENOIDS WERE REPLACED. THE LONG TIME DELAY CONCERN IN FOUR OF THE LOGIC UNITS WAS ATTRIBUTABLE TO THE ACCURACY OF THE POWER SENSOR TEST SET USED IN THE FIELD. AS A RESULT, FACTORY TESTING AND SETTINGS HAVE BEEN MODIFIED. MINOR OPERATIONAL PROBLEMS CONSISTED OF A FAULTY WIRE, AN OVERSIZED TOP STUD, AND TWO POOR SOLDERING CONNECTIONS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, EQUIPMENT + TESTING + TEST, PREOPERATIONAL + TEST, SYSTEM OPERABILITY + FAILURE, ADMINISTRATIVE CONTROL + DAVIS-BESSE I (PWR) + CONSTRUCTION + BREAKER

102442
REACTION COOLANT PUMP SUCTION WELD DEFECTS AT DAVIS-BESSE I
TOLEDO EUSON COMPANY, OHIO
1 PAGES, LETTER WITH ATTACHMENT TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, APRIL 7, 1975. DOCKET 50-346,

102242 CONTINUED
 TYPE--PWR, MFG--B&W, AE--B&WTEL

CAUSE - WELDING TECHNIQUE. RADIOGRAPHIC EXAMINATION OF FOUR COMPLETED REACTOR COOLANT PIPE-TU-PUMP FIELD WELDS REVEALED DISCONTINUITY INDICATIONS. THESE FISSURES COULD HAVE BEEN CAUSED BY CONTAMINATION FROM AIRBORNE PARTICLES AND/OR DIFFERENTIAL THERMAL CONTRACTION STRESSES BETWEEN THE STAINLESS STEEL CASING AND THE INCONEL WELD METAL. IN COMBINATION WITH WELD JOINT ORIENTATION. THE WELDS WERE GROUND OUT. THE STAINLESS STEEL CASTING WAS BUTTERED WITH STAINLESS STEEL WELD METAL AND THEN WITH A LAYER OF INCONEL. WELDS OF ACCEPTABLE QUALITY, WITH NO INDICATIONS, WERE THEN MADE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

WELDS + MODIFICATION + FAILURE, DESIGN ERROR + DAVIS-BESSE 1 (PWR) + MAIN COOLING SYSTEM + CONSTRUCTION + PUMPS + PIPES AND PIPE FITTINGS

104700
 NOTICE OF VIOLATION ON QUALITY ASSURANCE PROGRAM AT DAVIS-BESSE 1
 NUCLEAR REGULATORY COMMISSION, WASHINGTON
 5 PGS. LTR W/ENCL TO TOLEDO EDISON COMPANY, AUG. 1, 1975, DOCKET 50-346, TYPE--PWR MFG--B&W, AE--B&WTEL

CAUSE - INSUFFICIENT MANAGEMENT. DURING AN INSPECTION, QUALITY ASSURANCE/QUALITY CONTROL PROBLEMS WERE IDENTIFIED IN CONNECTION WITH SAFETY-RELATED ELECTRICAL WORK. OF PARTICULAR CONCERN IS THAT THE ITEMS OF NONCOMPLIANCE, WHEN VIEWED COLLECTIVELY, INDICATE A BREAKDOWN IN MANAGEMENT AND PROCEDURAL CONTROLS WITH RESPECT TO MAINTENANCE OF AN EFFECTIVE QUALITY ASSURANCE PROGRAM. THIS NOTICE OF VIOLATION APPEARS TO BE ADEQUATE TO ACHIEVE CORRECTIVE ACTION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

DAVIS-BESSE 1 (PWR) + QUALITY ASSURANCE + CONSTRUCTION + INSTALLATION + CABLES AND CONNECTORS + ENGINEERED SAFETY FEATURE + FAILURE, ADMINISTRATIVE CONTROL + LEGALISTICS

108826
 CRACKS FOUND IN SWITCHGEAR THERMOPLASTIC INSULATION JACKET AT DIABLO CANYON 2
 PACIFIC GAS & ELECTRIC CO., SAN FRANCISCO, CA
 2 PGS. RPT TO NRC OFFICE 1 & E, MARCH 26, 1975, DOCKET 50-323, TYPE--PWR, MFG--WEST., AE--UTILITY

CAUSE - FABRICATION ERRORS. ON JUNE 14, 1974 DURING INSTALLATION OF 12 KV AND 4.16 KV SYSTEMS SWITCHGEAR, WHILE MAKING UP BUS SECTIONS THAT WERE SHIPPED DISASSEMBLED, CRACKING OF THE THERMOPLASTIC INSULATION JACKET MATERIAL WAS DISCOVERED AT THE JNDS OF THE INSULATION. CRACKING WAS CAUSED BY HIGH STRESS AT THE ENDS DURING MANUFACTURE. REPAIR CONSISTED OF WRAPPING EACH PLASTIC-JACKETED JOINT FOR 5 INCHES IN EACH DIRECTION WITH 1-202 EPOXY/RESIN TAPE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

DIABLO CANYON 2 (PWR) + CONSTRUCTION + INSULATION + BREAKER + CABLES AND CONNECTORS + CRACK + FAILURE, FABRICATION ERROR + PLASTICS

099374
 FINAL REPORT ON STEAM GENERATOR NOZZLE INDICATIONS AT DIABLO CANYON 1 AND 2
 PACIFIC GAS AND ELECTRIC COMPANY, CALIFORNIA
 2 PAGES, LETTER TO DIRECTORATE OF REGULATORY OPERATIONS (REG), JANUARY 15, 1975, DOCKET 50-275/323, TYPE--PWR, MFG--WEST., AE--PG&E

CAUSE - CORROSIVE ENVIRONMENT. DISCOVERY OF INTERCONNECTED CIRCUMFERENTIAL SURFACE INDICATIONS IN THE FIRST WELD PASS ON A UNIT 1 STEAM GENERATOR PRIMARY NOZZLE SAFE END WAS REPORTED ON MARCH 29, 1974. NO SIMILAR INDICATIONS WERE FOUND IN NOZZLES OF THE REACTOR VESSEL, PRESSURIZER, OR OTHER STEAM GENERATORS IN EITHER UNIT. INDICATIONS WERE REMOVED BY GRINDING. MAXIMUM DEPTH WAS .097 INCH. STRESS RISERS WERE ELIMINATED BY BLENDING. INDICATIONS WERE INTERGRANULARLY ATTACKED BY A CORROSIVE MARINE ATMOSPHERE DURING ON-SITE STORAGE. A PLASTIC PROTECTIVE COVER WAS NOT USED. IT HAS NOW BEEN APPLIED TO ALL NOZZLES DURING STOPAGE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

WELDS + FLAW + CORROSION + FAILURE, FABRICATION ERROR + NOZZLE + DIABLO CANYON 1 (PWR) + STEAM GENERATOR + CHLORIDE + DIABLO CANYON 2 (PWR) + CONSTRUCTION + SURFACE TREATMENT

100345
 DEFICIENCIES FOUND IN 600 VOLT LOAD CENTER BREAKERS AT FARLEY 1 AND 2
 ALABAMA POWER COMPANY
 4 PAGES, LETTER WITH REPORT TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, FEBRUARY 24, 1975, DOCKET 50-348/364, TYPE--PWR, MFG--WEST., AE--SOUTHERN SERVICES

CAUSE - DESIGN AND INSTALLATION ERRORS. DURING ACCEPTANCE TESTS ON THE 210 600-VOLT LOAD CENTER BREAKERS (WESTINGHOUSE TYPE DS-206), THREE PROBLEMS WERE FOUND. (1) CONTROL WIRING INSULATION

100345 CONTINUED

OVERLOADING RESULTED FROM THE SCREWS WHICH ATTACH THE FRONT COVER BEING TOO LONG. THE SCREWS HELDED THE WIRING AGAINST THE CUII DAMAGING THE INSULATION AND RESULTING IN A GROUND. (2) BREAKER CURRENT SENSORS APPEAR TO HAVE A BROKEN CONNECTION INSIDE THE MOLDING IN 29 OF THE 630 SENSORS. (3) TRIP ACTUATORS FAILED TO TRIP AS A RESULT OF CORROSION ON THE PLUNGER SHAFT. CORROSION WAS CAUSED BY INADEQUATE CLEANING OF FLUX FROM THE PLUNGER ASSEMBLY AFTER BRAZING THE DISK ON.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ELECTRIC POWER + FASTENER + CORROSION + TEST, PREOPERATIONAL + FAILURE, DESIGN ERROR + FAILURE, INSTALLATION ERROR + CONSTRUCTION + FARLEY 1 (PWR) + CABLES AND CONNECTIONS + FARLEY 2 (PWR) + BREAKER

100500

CONTROL FUSES IN MOTOR CONTROL CENTERS FAIL AT FARLEY 1 AND 2

ALABAMA POWER COMPANY, BIRMINGHAM

2 PGS, LETTER WITH REPORT TO NRC DIRECTORATE OF REGULATORY OPERATIONS, JULY 31, 1975, DOCKET 50-348/364, TYPE--PWR, MFG--WEST., AE--SOUTHERN SERVICE

CAUSE - CORROSION. DURING PRELIMINARY TESTING OF ETE MOTOR CONTROL CENTERS, 17 OUT OF 39 SIZE 3 STARTERS WERE FOUND WITH OPEN 3-AMP FUSES. THESE ARE SHUNNUT AMP-TRAP 16Y3, TYPE 2 FUSES SUPPLIED WITH THE MOTOR CONTROL CENTER. CORROSION WAS FOUND ON THE ENDS WHERE THE LEAD WAS SOLDERED TO THE CAP ON THE OUTSIDE. ON THE INSIDE, THE FUSES WERE BROKEN FROM CORROSION AT THE SOLDER JOINT. A SOLDERING MATERIAL WAS SPECIFIED WHICH CAUSED CORROSION IN THE PRESENCE OF MOISTURE. ALL DEFECTIVE FUSES WILL BE REPLACED WITH ONE HAVING A DIFFERENT SOLDERING MATERIAL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FARLEY 1 (PWR) + FARLEY 2 (PWR) + CONSTRUCTION + INSTRUMENT, PROTECTIVE + CORROSION + FAILURE, DESIGN ERROR + FAILURE, COMMON MODE + MATERIAL + CONTROL SYSTEM + MOTORS + TEST, SYSTEM OPERABILITY + ENGINEERED SAFETY FEATURE

100438

PROBLEMS FOUND WITH MEA RELAYS IN D/G SWITCHING SYSTEM AT FARLEY 1 AND 2

ALABAMA POWER CO., ALA.

2 PGS, LTR W/RTPT TO NRC OFFICE OF I & E, SEPT. 4, 1975, DOCKET 50-348/364, TYPE--PWR, MFG--WEST., AE--SOUTHERN SERVICE

CAUSE - DESIGN DEFICIENCY. THE PROBLEMS WERE FOUND WITH THE GE MEA RELAYS THAT ARE A PART OF THE DIESEL GENERATOR SWITCHING SYSTEM AND THE MOTOR RELAY PANELS IN THE MAIN CONTROL ROOM. (1) THE TERMINAL STRAP MOVES FREELY AROUND THE OCTAGONAL SHAFT ON WHICH IT IS MOUNTED. THE MOVEMENT RESULTS IN DAMAGE TO THE FLEXIBLE SHUNT. SEVERAL BROKEN AND DAMAGED SHUNTS WERE DISCOVERED. THE TERMINAL APPARENTLY WAS NOT SHAPED CORRECTLY. (2) USE OF LONG BARREL TERMINAL LUGS COULD RESULT IN SHIDING THE TERMINAL AND MAY INTERFERE WITH THE SWITCH COVER. ALL DEFECTIVE MEA RELAYS WILL BE REPLACED WITH NEW ONES WHICH MEET THE ORIGINAL REQUIREMENTS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FARLEY 1 (PWR) + FARLEY 2 (PWR) + CONSTRUCTION + RELAYS + GENERATOR, DIESEL + FAILURE, DESIGN ERROR + CABLES AND CONNECTIONS

100275

CURRENT TRANSFORMER DEFICIENCIES FOUND AT FARLEY 1 AND 2

ALABAMA POWER CO., BIRMINGHAM, ALA.

3 PGS, LTR W/RTPT TO NRC OFFICE OF I & E, NOV. 3, 1975, DOCKET 50-348/364, TYPE--PWR, MFG--WEST., AE--SOUTHERN SERVICE

CAUSE - SPECIFICATIONS NOT MET. THE RESISTANCE OF 290 OF THE 303 4000/5A CURRENT TRANSFORMERS WAS FOUND TO EXCEED THE ACCEPTABLE RESISTANCE OF 1.0 OHMS. RESISTANCES RANGED FROM 2.46 TO 2.96 OHMS. THESE TRANSFORMERS WERE WOUND WITH SMALLER WIRE THAN REQUIRED BY THE MANUFACTURER'S SPECS. A SIMILAR PROBLEM WAS FOUND WITH THE 4000/5A CURRENT TRANSFORMERS. THE VOLTAGE SATURATION FOR BOTH OF THESE WAS LOWER THAN THAT SPECIFIED BECAUSE THEY WERE SUPPLIED WITH REDUCED IRON CONTENT. ALL WILL BE REPLACED WITH NEW ONES WHICH MEET THE ORIGINAL REQUIREMENTS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FARLEY 1 (PWR) + FARLEY 2 (PWR) + CONSTRUCTION + EMERGENCY POWER, ELECTRIC + FAILURE, FABRICATION ERROR + FAILURE, COMMON MODE + QUALITY ASSURANCE + TRANSFORMERS

100513

DIFFERENTIAL RELAY DEFICIENCY FOUND AT FARLEY 1 AND 2

ALABAMA POWER CO., BIRMINGHAM, ALA.

1 PGS, LTR W/RTPT TO NRC OFFICE OF I & E, NOV. 11, 1975, DOCKETS 50-348/364, TYPE--PWR, MFG--WEST., AE--SOUTHERN SERVICE

008513 CONTINUED

CAUSE - SENSITIVE TO RADIO FREQUENCY. DURING INITIAL ENERGIZATION OF A 600 V LOAD CENTER, A FALSE OPERATION OF THE TRANSFORMER OF TYPE 12 STD 1985A DIFFERENTIAL RELAY WAS OBSERVED. THE RELAY IS RADIO FREQUENTLY SENSITIVE AND TRIPS WITH AN ACTIVATED TRANSCIEVER LOCATED 5 FEET AWAY. THIS RELAY IS A SOLID STATE DEVICE WITH CERTAIN PARTS MOUNTED ON A PRINTED CIRCUIT BOARD WHICH APPARENTLY PICK UP A SIGNAL FROM A RECEIVER AND FEED IT INTO THE RELAY AMPLIFIER CAUSING A FALSE OPERATION. INVESTIGATION IS UNDERWAY TO DETERMINE CORRECTIVE ACTION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAHLEY 1 (PNR) + FAHLEY 2 (PNR) + CONSTRUCTION + RELAYS + ELECTRIC POWER + FAILURE - DESIGN ERROR + RADIOSENSITIVITY + SOLID STATE DEVICE

099020

LOCKOUT RELAY FAILS TO TRIP AT FT. CALHOUN

OMAHA PUBLIC POWER DISTRICT, NEBRASKA

3 PAGES, LETTER WITH AD REPORT 76/18 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 4 (AEC), JANUARY 2, 1975. DOCKET 50-285, TYPE--PNR, MFG--COMB., AE--GIBBS & HILL

CAUSE - MECHANICAL BINDING. DURING TESTING OF THE ENGINEERING SAFEGUARDS WITH THE REACTOR AT 75% POWER, A LOCKOUT RELAY FAILED TO TRIP. CONTACT 11-11C WAS MECHANICALLY BOUND OPEN BY THE INSULATION ON THE WIRE LUG OF STATIONARY CONTACT 11C. THIS PROHIBITED MOVABLE CONTACT 11 TO MAKE CONTACT WITH 11C. AFTER THE WIRE LUG INSULATION WAS ADJUSTED, PROPER CONTACT WAS MADE. THIS IS THE THIRD FAILURE OF THIS TYPE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TEST, SYSTEM OPERABILITY + FAILURE, MAINTENANCE ERROR + FT. CALHOUN (PNR) + ENGINEERED SAFETY FEATURE + INSULATION + CABLES AND CONNECTORS + RELAYS

099035

STEAM GENERATOR BLOWDOWN ACTIVITY RECORDER FAILS AT FT. CALHOUN

OMAHA PUBLIC POWER DISTRICT, NEBRASKA

3 PAGES, LETTER WITH AD REPORT 76/17 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 4 (AEC), JANUARY 3, 1975. DOCKET 50-285, TYPE--PNR, MFG--COMB., AE--GIBBS & HILL

CAUSE - BLOWN FUSE. DURING 75% POWER OPERATION WITH CONTINUOUS BLOWDOWN IN PROGRESS ON BOTH STEAM GENERATORS, THE PROCESS RADIATION MONITOR RECORDER WAS FOUND INOPERABLE. IT WAS LAST CHECKED 3 HOURS EARLIER. A 1 1/4 AMP FUSE HAD BLOWN IN THE POWER SUPPLY. THE FUSE WAS REPLACED. A REDUNDANT RECORDER WILL BE INSTALLED AND ALSO AN ALARM IN CASE OF POWER FAILURE TO THE RECORDER IN OPERATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

EFFLUENT + INSTRUMENT, PROTECTIVE + FAILURE, INSTRUMENT + MODIFICATION + CULMANT PURIFICATION SYSTEM + FT. CALHOUN (PNR) + STEAM GENERATOR + RADIATION MONITORS + RECORDERS

009372

PERSONNEL AIR LOCK INNER AND OUTER DOOR SEALS LEAK AT FT. CALHOUN

OMAHA PUBLIC POWER DISTRICT, NEBRASKA

4 PAGES, LETTER WITH AD REPORT 75/2 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 4, JANUARY 13, 1975. DOCKET 50-285, TYPE--PNR, MFG--COMB., AE--GIBBS & HILL

CAUSE - SEALS MISALIGNED. DURING STARTUP LEAK TESTING OF THE PERSONNEL AIR LOCK SEALS, THE LEAK RATE EXCEEDED THE LIMIT FOR BOTH THE INNER DOOR (24 CC/MIN) AND THE OUTER DOOR (20.5 CC/MIN). INNER AND OUTER DOOR RUBBER SEALS BECAME MISALIGNED CAUSING EXCESSIVE LEAKAGE. SEALS WERE ADJUSTED. LEAK RATES WERE THEN WITHIN LIMITS. THIS IS THE FIRST INSTANCE WHERE THE LEAKAGE ON BOTH DOORS EXCEEDED THE 10 CC/MIN LIMIT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTAINMENT AIR LOCK + TEST, SYSTEM OPERABILITY + FAILURE, MAINTENANCE ERROR + SEAL + FT. CALHOUN (PNR) + LEAK

099664

LOCKOUT RELAY FAILS TO TRIP AT FT. CALHOUN

OMAHA PUBLIC POWER DISTRICT, NEBRASKA

4 PAGES, LETTER WITH AD REPORT 75/3 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 4, JANUARY 29, 1975. DOCKET 50-285, TYPE--PNR, MFG--COMB., AE--GIBBS & HILL

CAUSE - MECHANICAL BINDING BY WIRE LUG. DURING TESTING WITH THE REACTOR AT 75% POWER, A LOCKOUT RELAY FAILED TO TRIP. A SET OF CONTACTS ON ANOTHER RELAY WERE MECHANICALLY BOUND OPEN BY THE INSULATION ON THE WIRE LUG OF THE STATIONARY CONTACT. THE LUG WAS ADJUSTED TO REMOVE THE BINDING. THIS IS THE FOURTH FAILURE OF THIS TYPE. A PERMANENT CHANGE WILL BE MADE DURING THE NEXT REFUELING OUTAGE TO PREVENT RECURRENCE.

101446 CONTINUED
 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

REACTOR SAFETY SYSTEM + TEST, SYSTEM OPERABILITY + FT. CALHOUN (PHR) + FAILURE, INSTALLATION ERROR +
 INSULATION + CABLES AND CONNECTORS + RELAYS

101447
 LIQUID EFFLUENT CONTROL MONITOR FAILS TO CLOSE VALVE AT FT. CALHOUN
 UMANA PUBLIC POWER DISTRICT, NEBRASKA
 4 PAGES, LETTER WITH AD REPORT 7574 TO U.S. NRC, REGION 4, MARCH 14, 1975, DCKET 50-285, TYPE--PHR, RFG--
 COMB., AE--GIBBS & HILL

CAUSE - SHORTED RESET SWITCH. DURING A WASTE LIQUID RELEASE WITH THE REACTOR SHUTDOWN FOR
 REFUELING, THE OPERATOR NOTICED THAT THE READING ON THE LIQUID EFFLUENT CONTROL MONITOR WAS ABOVE
 THE ALARM AND CLOSURE SETPOINT AND THE RELEASE CONTINUED. THE INVESTIGATION FOUND THAT THE HIGH
 READING WAS DUE TO CONTAMINATION OF THE DETECTOR WELL. IT WAS DECONTAMINATED, THE MONITOR FAILED
 TO PERFORM ITS CONTROL FUNCTION DUE TO A SHORTED RESET SWITCH WHICH MAINTAINED A CONTINUOUS RESET
 CONDITION. IT IS THOUGHT THAT THE RESET SWITCH FAILED AFTER THE TEST THAT WAS MADE JUST BEFORE
 THE RELEASE WAS STARTED. HAD THE READING BEEN CORRECT, NO LIMITS WOULD HAVE BEEN EXCEEDED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

FAILURE, COMPONENT + WASTE DISPOSAL + WASTE HANDLING + INSTRUMENT, SWITCH + REFUELING + FT. CALHOUN (PHR) +
 NAVIGATION MONITORS

101457
 HIGH PRESSURE SAFETY INJECTION VALVE FAILS TO OPEN AT FT. CALHOUN
 UMANA PUBLIC POWER DISTRICT, NEBRASKA
 3 PAGES, LETTER WITH AD REPORT 7578 TO U.S. NRC, REGION 4, MARCH 17, 1975, DCKET 50-285, TYPE--PHR, RFG--
 COMB., AE--GIBBS & HILL

CAUSE - BREAKER/STARTER IMPROPERLY ASSEMBLED. DURING A REFUELING OUTAGE, A HIGH PRESSURE SAFETY
 INJECTION VALVE FAILED TO OPEN IN SIGNAL FROM THE CONTROL ROOM. THE REVERSING INTERLOCK AT THE
 COMBINATION STARTER/BREAKER WAS NOT MAKING PROPER CONTACT. A NORMALLY OPEN CONTACT HAD BEEN
 INSTALLED INSTEAD OF A NORMALLY CLOSED CONTACT DURING REASSEMBLY FOLLOWING RECENT PREVENTATIVE
 MAINTENANCE. ALL PROCEDURES WERE CORRECT EXCEPT THAT NO FUNCTIONAL TEST WAS PERFORMED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

SAFETY INJECTION + REFUELING + FAILURE, MAINTENANCE ERROR + FT. CALHOUN (PHR) + EMERGENCY COOLING SYSTEM +
 BREAKER + VALVES

101458
 DIESEL BREAKER FAILS TO CLOSE DURING LOSS OF OFF SITE POWER AT FT. CALHOUN
 UMANA PUBLIC POWER DISTRICT, NEBRASKA
 3 PAGES, LETTER WITH AD REPORT 7577 TO U.S. NRC, REGION 4, MARCH 17, 1975, DCKET 50-285, TYPE--PHR, RFG--
 COMB., AE--GIBBS & HILL

CAUSE - OPERATOR ERROR. DURING A REFUELING SHUTDOWN, MAIN TRANSFORMER T1 TRIPPED ON AN INDICATED
 INTERNAL FAULT. BOTH DIESEL GENERATORS AUTO STARTED AND CAME TO RATED SPEED AND VOLTAGE. ONE
 DIESEL BREAKER AUTO CLOSED BUT THE OTHER BREAKER DID NOT. THE OPERATOR MANUALLY CLOSED IT. THE
 BREAKER FAILED TO CLOSE AUTOMATICALLY BECAUSE A LOW PRESSURE SAFETY INJECTION PUMP WAS IN
 SERVICE. THE OPERATOR SHOULD HAVE TRIPPED THE PUMP BREAKER, THEN THE AUTO CLOSE CIRCUIT WOULD
 HAVE WORKED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

EMERGENCY POWER, ELECTRIC + FAILURE, OPERATOR ERROR + ACCIDENT, LOSS OF POWER + REFUELING + FT. CALHOUN (PHR)
 + OFF SITE + BREAKER

101459
 STACK PARTICULATE RADIATION MONITOR FAILS AT FT. CALHOUN
 UMANA PUBLIC POWER DISTRICT, NEBRASKA
 3 PAGES, LETTER WITH AD REPORT 7576 TO U.S. NRC, REGION 4, MARCH 17, 1975, DCKET 50-285, TYPE--PHR, RFG--
 COMB., AE--GIBBS & HILL

CAUSE - FAILURE OF GREASE AND TRANSISTORS. DURING TESTING WHILE REFUELING WAS IN PROGRESS, THE
 STACK PARTICULATE RADIATION MONITOR WAS FOUND TO BE READING ABOUT 3% OF THE REQUIRED COUNTS. THE
 COUPLING GREASE BETWEEN THE PHOTO-MULTIPLIER TUBE AND THE BETA SENSITIVE PLASTIC CRYSTAL HAD
 MELTED AWAY. NEW COUPLING GREASE WAS APPLIED. THEN, SEVERAL TRANSISTORS IN THE PRE-AMPLIFIER
 CIRCUIT FAILED. THEY WERE REPLACED. THE DETECTOR CALIBRATED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

101459 CONTINUOUS
FAILURE, COMPONENT + STACK + INSTRUMENT CALIBRATION + REFUELING + TEST, SYSTEM OPERABILITY + FT. CALHOUN (PWR)
+ LUBRICATION + ELECTRONIC FUNCTION UNITS + RADIATION MONITORS

101460
SETPOINT DRIFT IN LEVEL INDICATORS AT FT. CALHOUN
OMAHA PUBLIC POWER DISTRICT, NEBRASKA
3 PAGES, LETTER WITH AD REPORT 75/5 TO U.S. NRC, REGION 4, MARCH 21, 1975, DOCKET 50-285, TYPE--PWR, NRG--
COMB., AE--GIBBS & HILL

CAUSE - MISAPPLICATION OF SWITCH. DURING A REVIEW OF STEAM TANK LEVEL CHANNEL CALIBRATION WHILE THE UNIT WAS SHUTDOWN FOR REFUELING, IT WAS DISCOVERED THAT THE AS FOUND PRESSURE SWITCH SETTINGS FOR THE RECIRCULATION ACTUATION SIGNAL HAD DRIFTED UPWARD ABOVE THE 14 TO 16 INCHES OF WATER LIMIT RANGE. THE SETPOINTS DRIFTED WITHIN THE ALLOWABLE MANUFACTURER'S SPECIFICATION OF PLUS OR MINUS 4.98 INCHES OF WATER. SETPOINTS WERE 1 TO 3 INCHES HIGH. CALIBRATION PROCEDURES PERMITTED SETTINGS SLIGHTLY ABOVE THE TECH SPEC LIMITS. A SET POINT CHANGE WAS ISSUED IMMEDIATELY. A DESIGN CHANGE REQUEST WAS ISSUED FOR SWITCHES WITH A LARGER RANGE OF PRESSURE SETTING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INSTRUMENT CALIBRATION + FAILURE, INSTRUMENT + INSTRUMENT, SWITCH + REFUELING + TEST, SYSTEM OPERABILITY + FAILURE, DESIGN ERROR + FT. CALHOUN (PWR) + SET POINT + EMERGENCY COOLING SYSTEM + DRIFT + SENSORS, LEVEL

102137
CHARCOAL FILTER EFFICIENCY BELOW LIMIT AT FT. CALHOUN
OMAHA PUBLIC POWER DISTRICT, NEB.
3 PAGES, LETTER WITH AD REPORT 75A-1 TO U.S. NRC, REGION 4, MARCH 25, 1975, DOCKET 50-285, TYPE--PWR, NRG--
COMB., AE--GIBBS & HILL

CAUSE - UNKNOWN. TESTS ON 2 CONTAINMENT CHARCOAL CELLS SHOWED REMOVAL EFFICIENCIES FOR ELEMENTAL IODINE OF 98.32% AND 98.62% WHICH ARE BELOW THE 99.5% LIMIT. EFFICIENCIES FOR METHYL IODIDE EXCEED LIMITS FOR BOTH. THE LIMIT FOR ELEMENTAL IODINE IS BELIEVED TO BE UNREASONABLY HIGH. A TECH SPEC REVISION WAS INITIATED TO LOWER THE LIMIT TO 95%. ONE-FOURTH OF THE CHARCOAL WAS REPLACED ACCORDING TO PLANS. THE REACTOR WAS SHUT DOWN FOR REFUELING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FILTER EFFICIENCY + IODINE + CHARCOAL + CONTAINMENT FILTERING SYSTEM + REFUELING + TEST, SYSTEM OPERABILITY + FAILURE, ADMINISTRATIVE CONTROL + FT. CALHOUN (PWR)

102135
DETERIORATION OF SECONDARY INSULATION ON 4 KV BUS DUCT AT FT. CALHOUN
OMAHA PUBLIC POWER DISTRICT, NEB.
3 PAGES, LETTER WITH AD REPORT 75/2 TO U.S. NRC, REGION 4, MARCH 31, 1975, DOCKET 50-285, TYPE--PWR, NRG--
COMB., AE--GIBBS & HILL

CAUSE - EXCESSIVE EXPANSION. DURING MAINTENANCE ON THE 4 KV INDOOR METAL CLAD SWITCHGEAR, PIECES OF RED THERMO-PLASTIC INSULATING MATERIAL WERE FOUND SEPARATED FROM THE 4 KV NON-SEGREGATED INDOOR BUS DUCT. THE 0.1 INCH THICK INSULATING MATERIAL APPEARS TO HAVE FAILED AS A RESULT OF EXPANSION TO A POINT WHERE CRACKING WAS INEVITABLE. THE CAUSE OF EXPANSION IS UNKNOWN. SEVERELY DAMAGED INSULATION WAS REMOVED AND THE BUS COVERED WITH 2 LAYERS OF TAPE APPROVED BY C.E. FOR LESSER DAMAGE, TAPE WAS APPLIED OVER THE INSULATION. ABOUT 20% OF THE INDOOR 3000 A AND 2000 A BUS DUCT REQUIRED REPAIR. THE UNIT WAS BEING REFUELED AT THIS TIME.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MAINTENANCE AND REPAIR + ELECTRIC POWER + REFUELING + FAILURE, DESIGN ERROR + FT. CALHOUN (PWR) + INSULATION + CABLES AND CONNECTORS

102138
RAW WATER BACKUP VALVES FAIL TO OPERATE AT FT. CALHOUN
OMAHA PUBLIC POWER DISTRICT, NEBRASKA
3 PAGES, LETTER WITH AD REPORT 75/9 TO U.S. NRC, REGION 4, APRIL 4, 1975, DOCKET 50-285, TYPE--PWR, NRG--
COMB., AE--GIBBS & HILL

CAUSE - SOLENOID FAILURE AND DIRT. DURING TESTING WITH THE REACTOR SHUTDOWN FOR REFUELING, 2 RAW WATER BACKUP VALVES FAILED TO OPERATE. THE SUPPLY VALVE HAD DIRT IN THE POSITIONER ON THE VALVE. AFTER THE PNEUMATIC RELAY ORIFICES ON THE POSITIONER WERE CLEANED, THE VALVE OPERATED SATISFACTORILY. A SOLENOID ON A RETURN VALVE HAD FAILED. THE SOLENOID WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

WATER + CHAD + REFUELING + TEST, SYSTEM OPERABILITY + FAILURE, MAINTENANCE ERROR + FT. CALHOUN (PWR) + COOLING + PNEUMATIC SYSTEM + SOLENOID + VALVE OPERATORS + VALVES

102474
 TWO COMPONENT COOLING WATER VALVES FAIL TO REMAIN OPEN AT FT. CALHOUN
 IOWA PUBLIC POWER DISTRICT, NEBRASKA
 4 PAGES, LETTER WITH AWR 75-11 TO U.S. NRC, REGION 6, APRIL 9, 1975, DOCKET 50-285, TYPE--PWR, HFG--COMB., AE--
 WOODS & MILL

CAUSE - SET POINT UNSET IN SWITCH. DURING TESTING WITH THE REACTOR SHUTDOWN FOR REFUELING, THE
 INLET AND OUTLET VALVES TO A CONTAINMENT COOLING AND FILTERING UNIT OPENED ON SIGNAL THEN
 RECLOSED AFTER A 15-SEC DELAY. THE SET POINT ON THE FLOW CONTROLLER WAS MIS-SET HIGH SO THAT
 NORMAL FLOW WOULD NOT ACTUATE THE CONTROLLER. THIS PREVENTED REOPENING THE VALVES AFTER THEY
 WERE AUTOMATICALLY CLOSED AFTER A 15-SEC. TIME DELAY. AFTER THE FLOW SWITCH WAS RESET, THE
 VALVES WERE TESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

FT. CALHOUN (PWR) + VALVES + CONTAINMENT AIR COOLING + CONTAINMENT FILTERING SYSTEM + TEST, SYSTEM
 OPERABILITY + FAILURE, MAINTENANCE ERROR + SET POINT + REFUELING + INSTRUMENT, SWITCH + SENSORS, FLOW

102475
 DIESEL GENERATOR BACKUP UNDERVOLTAGE START MALFUNCTION AT FT. CALHOUN
 IOWA PUBLIC POWER DISTRICT, NEBRASKA
 3 PAGES, LETTER WITH OIR 75A-27 TO U.S. NRC, REGION 6, APRIL 13, 1975, DOCKET 50-285, TYPE--PWR, HFG--COMB.,
 AE--WOODS & MILL

CAUSE - UNKNOWN. THE BACKUP RELAY LOGIC CHAIN WHICH INITIATES FULL SPEED START TO DIESEL
 GENERATOR 2 DID NOT START THE DG IMMEDIATELY BUT DELAYED 1.75 SEC FROM THE INITIAL LOSS OF BUS
 VOLTAGE DURING TESTING. THE PRIMARY RELAYS FUNCTIONED PROPERLY. THE BACKUP RELAY CHAIN RESET
 PROPERLY WHEN BUS VOLTAGE WAS RESTORED. DURING RE-TESTING, THE BACKUP RELAYS OPERATED PROPERLY.
 NO CAUSE FOR THIS ONE TIME SLUG ACTUATION WAS FOUND.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

FT. CALHOUN (PWR) + RELAYS + RESPONSE TIME + CONTROL SYSTEM + GENERATOR, DIESEL + ENGINES, INTERNAL
 COMMUNICATION + TEST, SYSTEM OPERABILITY + FAILURE, INSTRUMENT + REFUELING

102482
 SHUTDOWN COOLING VALVE INTERLOCK DESIGN DEFICIENCY AT FT. CALHOUN
 IOWA PUBLIC POWER DISTRICT, NEBRASKA
 3 PAGES, LETTER WITH OIR 75-3 TO U.S. NRC, REGION 6, APRIL 15, 1975, DOCKET 50-285, TYPE--PWR, HFG--COMB., AE--
 WOODS & MILL

CAUSE - DESIGN ERROR. THE PSAM DESCRIBES A PRIMARY AND SECONDARY INHIBIT TO PREVENT OPENING A
 SHUTDOWN COOLING VALVE WHEN RCS PRESSURE IS ABOVE 250 PSIG. THE PRIMARY INHIBIT IS AS DESCRIBED.
 THE SECONDARY INHIBIT IS A TURBU SWITCH WHICH CANNOT SENSE PRESSURE BUT ONLY MECHANICAL FORCE.
 DURING THE PRESENT REFUELING OUTAGE, A SECONDARY PRESSURE SENSING INTERLOCK WILL BE INSTALLED.
 THE APPARENT CAUSE WAS DESIGN OVERSIGHT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

INSTRUMENT, INTERLOCK + SHUTDOWN COOLING SYSTEM + MAIN COOLING SYSTEM + FAILURE, DESIGN ERROR + MODIFICATION
 + ALARMING SYSTEM + FT. CALHOUN (PWR)

102900
 SEWAGE TREATMENT PLANT EFFLUENT DID EXCEEDS LIMIT AT FT. CALHOUN
 IOWA PUBLIC POWER DISTRICT, NEB.
 3 PAGES, LETTER WITH OIR 75-6 TO U.S. NRC, REGION 6, APRIL 23, 1975, DOCKET 50-285, TYPE--PWR, HFG--COMB., AE--
 WOODS & MILL

CAUSE - LIMIT EXCEEDS AVAILABLE TECHNOLOGY. THE TERTIARY SEWAGE TREATMENT PLANT WAS INSTALLED IN
 THE SPRING OF 1970. FOR THE FIRST YEAR, THE ANNUAL AVERAGE BIOLOGICAL OXYGEN DEMAND IN THE
 EFFLUENT WAS 18.1 PPM. THE TECH SPEC LIMIT IS 5 PPM. STATE AND FEDERAL LIMIT FOR MUNICIPAL AND
 DOMESTIC WASTE IS NORMALLY 30 PPM BOD. CONTRIBUTING CAUSES WERE AS FOLLOWS: ENGINEERING DESIGN
 AND TECHNOLOGY AVAILABLE WHEN THE PLANT WAS CONSTRUCTED COULD NOT GUARANTEE LESS THAN 5 PPM.
 CONTINUAL DISCHARGE WAS ATTAINABLE. THE PLANT LOAD HAS BEEN HIGHER THAN EXPECTED. HIGHER THAN
 EXPECTED MAINTENANCE HAS BEEN EXPERIENCED WITH THE EQUIPMENT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

FT. CALHOUN (PWR) + EFFLUENT + WASTE, SEWAGE + FAILURE, DESIGN ERROR + PERFORMANCE LIMIT + WATER QUALITY

102473
 HYDRAULIC SMUCK SUPPRESSOR INSPECTION AT FT. CALHOUN
 IOWA PUBLIC POWER DISTRICT, NEBRASKA
 20 PAGES, LETTER WITH ATTACHMENTS TO NRC DIRECTORATE OF LICENSING, APRIL 24, 1975, DOCKET 50-285, TYPE--PWR.

102473 CONTINUED
 HFG--COMB., AE--GIBBS & HILL

DURING THE INITIAL REFUELING OUTAGE, AN INSPECTION WAS MADE OF ALL SAFETY-RELATED HYDRAULIC SHOCK SUPPRESSORS. ALL SUPPRESSORS WITHIN CONTAINMENT, OUT OUTSIDE THE BIOLOGICAL SHIELD, WERE REBUILT WITH ETHYLENE PROPYLENE SEAL MATERIAL. NO DEFECTIVE SUPPRESSORS WERE FOUND. A FEW LEAKS AT TUBING FITTINGS WERE CORRECTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM CHARGE \$2.00)

FT. CALHOUN (PHN) * BACKFIT * OSKCA ABSORBER * SUPPORT STRUCTURE * PIPES AND PIPE FITTINGS * SURVEILLANCE PROGRAM * SEAL * MATERIAL * REFUELING

103443
 AXIAL POWER DISTRIBUTION CHANNEL TRIP LIMITS OUT OF SPECS AT FT. CALHOUN
 OMAHA PUBLIC POWER DISTRICT, NEBRASKA
 4 PAGES, LETTER WITH AD REPORT 75-12 TO NRC, REGION IV, MAY 29, 1975, DOCKET 50-285, TYPE--PHN, HFG--COMB., AE--GIBBS & HILL

CAUSE - ADDER-SUBTRACTOR OSCILLATING. WHILE THE REACTOR WAS OPERATING AT 60% POWER, THE AXIAL SHAPE INDEX UPPER AND LOWER TRIP LIMITS WERE FOUND OUT OF SPECIFICATIONS. FAILURE RESULTED FROM OSCILLATIONS OF 2 WELL AND HOWELL ADDER-SUBTRACTOR MODULES MODEL 19-71A. THE MODULES WERE REPLACED. THE OPERATOR FAILED TO RECOGNIZE THE OUT-OF-LIMIT CONDITION WHEN THE READ-OUTS WERE TAKEN. THE CHANNEL WAS TAKEN OUT OF SERVICE, NOT TRIPPED, FOR MAINTENANCE. A SHIFT SUPERVISOR HAD BYPASSED ANOTHER CHANNEL BECAUSE OF NOISE WITHOUT NOTIFYING HIS SUPERVISOR. THIS LEFT ONLY 2 OPERATING CHANNELS. PROCEDURES WERE MODIFIED TO PREVENT RECURRENCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM CHARGE \$2.00)

FT. CALHOUN (PHN) * INSTRUMENTS, MISC. * POWER DISTRIBUTION * SET POINT * TEST, SYSTEM OPERABILITY * FAILURE, INSTRUMENT * FAILURE, ADMINISTRATIVE CONTROL * COMMUNICATION

103444
 UNWIVED SIGNAL SEQUENCES FAILS TO ACTUATE ON TIME AT FT. CALHOUN
 OMAHA PUBLIC POWER DISTRICT, NEBRASKA
 3 PAGES, LETTER WITH AD REPORT 75-13 TO NRC, REGION IV, JUNE 5, 1975, DOCKET 50-285, TYPE--PHN, HFG--COMB., AE--GIBBS & HILL

CAUSE - BINDING OF OPERATING MECHANISM. DURING A TEST WITH THE REACTOR AT 70% POWER, 2 SEQUENCE TIMER RELAYS FAILED TO TIME OUT AT THEIR SET TIME. THE CAUSE WAS A BINDING OPERATING MECHANISM. THE PROBABLE CAUSE OF SLOW TIME OUT WAS IMPROPER LUBRICATION OF THE RELAYS. RELAY SIGNAL NO. HA-4100-L-UN TIMING RELAYS. THE RELAYS WERE LUBRICATED ACCORDING TO THE VENDOR'S RECOMMENDATION. THIS WILL BE ADDED TO THE PREVENTATIVE MAINTENANCE PROGRAM.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM CHARGE \$2.00)

FT. CALHOUN (PHN) * INSTRUMENT, SWITCH * INSTRUMENT CALIBRATION * INSTRUMENTS, MISC. * TEST, SYSTEM OPERABILITY * SET POINT * DRIFT * LUBRICATION * FAILURE, MAINTENANCE ERROR * FAILURE, INSTRUMENT

103427
 STACK PARTICULATE MONITOR FAILS AT FT. CALHOUN
 OMAHA PUBLIC POWER DISTRICT, NEB.
 3 PAGES, LETTER WITH AD 75-14 TO U.S. NRC, REGION IV, JUNE 13, 1975, DOCKET 50-285, TYPE--PHN, HFG--COMB., AE--GIBBS & HILL

CAUSE - LOG-RATEMETER CIRCUIT CARD. DURING A CALIBRATION CHECK WITH THE REACTOR AT 72% POWER, A STACK PARTICULATE MONITOR SHOWED A COUNT RATE OF 11,000 CPM FOR THE STANDARD GEOMETRY INSTEAD OF THE REQUIRED 20809 CPM. THE LOG-RATEMETER CIRCUIT CARD HAD FAILED. A SLIGHT MELTING OF THE COUPLING GREASE CHANGED THE COUNT RATE SLIGHTLY. THE COUPLING GREASE WAS INSTALLED. A NEW LOG-RATEMETER BOARD WAS INSTALLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM CHARGE \$2.00)

FT. CALHOUN (PHN) * MONITOR, STACK * STACK * INSTRUMENT CALIBRATION * TEST, SYSTEM OPERABILITY * FAILURE, INSTRUMENT * FAILURE, COMPONENT * ELECTRONIC FUNCTION UNITS * RADIATION MONITORS

103445
 RECENTLY INSTALLED INCUR DETECTORS CONTINUE TO FAIL AT FT. CALHOUN
 OMAHA PUBLIC POWER DISTRICT, NEB.
 3 PAGES, LETTER WITH UER 75-5 TO U.S. NRC, REGION IV, JUNE 18, 1975, DOCKET 50-285, TYPE--PHN, HFG--COMB., AE--GIBBS & HILL

CAUSE - UNKNOWN. DURING THE 1975 REFUELING OUTAGE, 14 OF THE 28 SELF-POWERED INCUR DETECTOR STRINGS WERE REPLACED BECAUSE 1 OR 2 OF THE 4 RHODIUM DETECTORS IN EACH STRING OR ITS SYMMETRIC STRING HAD FAILED. SINCE READING 100% POWER ON MAY 1, THE NEWLY INSTALLED RHODIUM DETECTORS

103845 (CONTINUED)

HAVE FAILED AT A RATE OF ABOUT 2 PER DAY. CURRENTLY, 50 OF THE 50 REPLACED RHODIUM DETECTORS HAVE FAILED. THE CAUSE HAS NOT BEEN DETERMINED. NORMAL PLANT OPERATIONS CONTINUE WITHIN TECHNICAL LIMITATIONS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FT. CALHOUN (PWR) + INSTRUMENT, IN CLAR + INSTRUMENT, POWER RANGE + FAILURE, INSTRUMENT + FAILURE, COMMON MODE + SELF MONITORED FLUX DETECTION

103904

UNMODDED RADIAL PEAKING FACTOR EXCEEDS LIMIT AT FT. CALHOUN

OMAHA PUBLIC POWER DISTRICT, NEB.

3 PAGES, LETTER WITH ACR 75-6 TO U.S. NRC, REGION 4, JUNE 23, 1975, Docket 50-285, TYPE--PWR, NRC--COMB., AE--GIBBS & HILL

CAUSE - UNCERTAINTY NOT INCLUDED. DURING INITIAL POWER ASCENSIONS FOLLOWING THE 1975 REFUELING OUTAGE, MEASUREMENTS OF THE POWER DISTRIBUTION MADE DURING SEVERAL DAYS AND THE SUBSEQUENT CALCULATION OF THE UNMODDED RADIAL PEAKING FACTOR CONFIRMED THAT THE FACTOR WAS 1.40 WHICH IS ABOVE THE DESIGN VALUE OF 1.40. THE MEASURED VALUE, INCLUDING NO UNCERTAINTY, EXCEEDED THE LIMIT, INCLUDING NO UNCERTAINTY. WHEN THE UNCERTAINTIES WERE INCLUDED THE MEASURED VALUE WAS 1.40 AND THE DESIGN VALUE WAS 1.41. A POTENTIAL UNSAFE CONDITION DID NOT EXIST.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FT. CALHOUN (PWR) + POWER DISTRIBUTION + COMPARISON, THEORY AND EXPERIENCE + FLUX DISTRIBUTION + DESIGN CRITERIA

104204

SET POINT DRIFT IN AXIAL POWER DISTRIBUTION CHANNEL AT FT. CALHOUN

OMAHA PUBLIC POWER DISTRICT, NEB.

3 PAGES, LETTER WITH ACR 75-15 TO U.S. NRC, REGION 4, JUNE 30, 1975, Docket 50-285, TYPE--PWR, NRC--COMB., AE--GIBBS & HILL

CAUSE - ADDER-SUBTRACTOR MODULE DEFICIENCY. DURING TESTING WITH THE REACTOR AT 74.98 POWER, AXIAL POWER DISTRIBUTION CHANNEL A UPPER TRIP SET POINT WAS FOUND TO BE 1.43 BUT SHOULD HAVE BEEN 0.33. ACTIVATION OF CERTAIN SWITCHES DURING TESTING INDUCED A SIGNAL TRANSFER INTO THE CALCULATOR BY CHANGING THE POWER INPUT. THIS TRANSFER APPEARS TO HAVE SENT THE BELL AND HOWELL 19-301A ADDER-SUBTRACTOR MODULE INTO OSCILLATION PRODUCING THE OUT-OF-SPEC CONDITION. AN IMPROVED MODULE LESS PRONE TO GO INTO OSCILLATION WAS INSTALLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FT. CALHOUN (PWR) + INSTRUMENT, SWITCH + INSTRUMENT CALIBRATION + INSTRUMENT, POWER RANGE + FAILURE, COMPONENT + ELECTRONIC FUNCTION UNITS + POWER DISTRIBUTION + INSTRUMENTS, MISC. + SET POINT + DRIFT

104493

DERIVED SIGNAL SEQUENCES FAIL TO ACTUATE ON TIME AT FT. CALHOUN

OMAHA PUBLIC POWER DISTRICT, NEB.

3 PAGES, LETTER WITH ACR 75-16 TO U.S. NRC, REGION 4, JULY 8, 1975, Docket 50-285, TYPE--PWR, NRC--COMB., AE--GIBBS & HILL

CAUSE - LACK OF LUBRICATION. DURING A TEST WITH THE REACTOR AT 74.58 POWER, 3 SEQUENCER TIMER RELAYS FAILED TO TIME OUT AT THEIR SET TIMES. THE CAUSE WAS A BONDING OPERATING MECHANISM. THE MANUFACTURER RECOMMENDED THAT THE 3 RELAYS BE LUBRICATED AND THAT ALL RELAYS BE EXERCISED MORE FREQUENTLY. THE TIMERS WILL BE TESTED EACH WORKING DAY FOR A PERIOD OF 30 DAYS TO ALLOW THE LUBRICANT TO PROPERLY PENETRATE THE MECHANISMS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FT. CALHOUN (PWR) + RELAYS + INSTRUMENT CALIBRATION + TEST, SYSTEM OPERABILITY + FAILURE, MAINTENANCE ERROR + LUBRICATION

104804

SET POINT DRIFT IN THERMAL MARGIN/LOW PRESSURE SWITCH AT FT. CALHOUN

OMAHA PUBLIC POWER DISTRICT, NEBRASKA

3 PAGES, LETTER WITH ACR 75/17 TO NRC, REGION 4, JULY 10, 1975, Docket 50-285, TYPE--PWR, NRC--COMB., AE--GIBBS & HILL

CAUSE - MULTIPLIER MODULE FAILURE. DURING TESTING WITH THE REACTOR AT 74.58 POWER, 1 OF THE 4 THERMAL MARGIN/LOW PRESSURE CHANNELS WAS OBSERVED TO BE READING 75 PSI LOWER THAN THE OTHER CHANNELS. THIS IS 10 PSI BELOW THE LIMIT. THE CAUSE WAS FAILURE OF A BELL AND HOWELL 19-309 MULTIPLIER MODULE. THE FAILED MODULE WAS REPLACED AND THE CHANNEL RETURNED TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

106630 CONTINUED
CHARGE \$2.00

FT. CALHOUN (PWR) + INSTRUMENT, SWITCH + INSTRUMENT CALIBRATION + TEST, SYSTEM OPERABILITY + FAILURE, INSTRUMENT + SET POINT + DRIFT + SENSORS, PRESSURE + REACTION SAFETY SYSTEM + ELECTRONIC FUNCTION UNITS

106634
ADDITIONAL INFORMATION ON SEQUENCER TIMER RELAYS AT FT. CALHOUN
OMAHA PUBLIC POWER DISTRICT, NEB.
4 PGS., LTR W/SUPPL. (AU 75-164) TO AU 75-16 TO U.S. NRC, REGION IV, SEPT. 9, 1975, DOCKET 50-285, TYPE--PWR, HFG--COMB., AE--GIBBS & HILL

CAUSE - MAINTENANCE DEFICIENCY. DURING TESTING WITH THE UNIT AT THE POWER, DERIVED SIGNAL SEQUENCERS FAILED TO ACTUATE AT SET TIME AS REPORTED EARLIER. FOLLOWING MANUFACTURERS RECOMMENDATIONS, THE SEQUENCER TIMER RELAYS WERE TESTED EACH WORKING DAY FOR A TOTAL OF 30 DAYS. DURING THIS PERIOD ONLY 5 FAILURES OCCURRED. EACH RELAY WAS REMOVED, CLEANED, AND LUBRICATED AND RETURNED TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FT. CALHOUN (PWR) + RELAYS + TESTING + MAINTENANCE AND REPAIR + FAILURE, MAINTENANCE ERROR + LUBRICATION

107434
DERIVED SIGNAL SEQUENCER FAILS TO ACTUATE ON SET TIME AT FT. CALHOUN
OMAHA PUBLIC POWER DISTRICT, OMAHA, NEB.
3 PGS., LTR W/SUPPL. RPT. 50-285/75-168 TO U.S. NRC, REGION IV, OCT. 3, 1975, DOCKET 50-285, TYPE--PWR, HFG--COMB., AE--GIBBS & HILL

CAUSE - NOT STATED. DURING TESTING, A SEQUENCER TIMER RELAY FOR SI-3A FAILED TO TIME OUT AT ITS SET TIME. SINCE THIS WAS THE ONLY FAILURE EXPERIENCED AFTER THESE TIMER RELAYS HAD BEEN CLEANED AND LUBRICATED AT THE MANUFACTURER'S RECOMMENDATION, THE TIMER WAS REPLACED. THE REPLACEMENT WAS CLEANED, LUBRICATED, AND TESTED. ITS TIMER DIAL HAD TO BE ADJUSTED TO 3.0 SECONDS TO GIVE AN ADJUSTMENT OF A TIMER DIAL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FT. CALHOUN (PWR) + RELAYS + TEST, SYSTEM OPERABILITY + SAFETY INJECTION + CONTROL SYSTEM

107503
REACTOR COOLANT PUMP SEALS FAIL AT FT. CALHOUN
OMAHA PUBLIC POWER DISTRICT, OMAHA, NEB.
4 PGS., LTR W/AU 50-285/75-18 TO U.S. NRC, REGION IV, OCT. 10, 1975, DOCKET 50-285, TYPE--PWR, HFG--COMB., AE--GIBBS & HILL

CAUSE - INADEQUATE PROCEDURES. STARTUP ACTIVITIES WERE UNDERWAY FROM HOT SHUTDOWN WHEN THE OPERATORS NOTICED AN INCREASE IN CONTAINMENT SUMP LEVELS. THE UPPER VAPOR SEAL REGION OF 2 REACTOR SEAL PUMPS WAS LEAKING. THIS COULD NOT BE ATTRIBUTED TO ANY SPECIFIC CAUSE. THE UNIT WAS BROUGHT TO COLD SHUTDOWN. THE VAPOR SEALS WERE REPLACED. WHEN THE UNIT WAS REPRESSURIZED, THE SEAL PRESSURE BREAKDOWN PRESSURE WAS INCORRECT. UPON REMOVAL OF THE SEAL CARTRIDGE, 5 OF THE 8 LOWER BREAKDOWN DEVICE LAMP SCREWS WERE FOUND TO HAVE BACKED OUT AND DAMAGED THE SEAL COOLANT RECIRCULATION IMPELLER AND BUTTOM SUPPORT. ALL PARTS WERE RECOVERED. DAMAGED PARTS WERE REPLACED AND THE SEAL REASSEMBLED. TWO OTHER SEALS ALSO REQUIRED REPLACEMENT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FT. CALHOUN (PWR) + SEAL + PUMPS + MAIN COOLING SYSTEM + LEAK + FAILURE, ADMINISTRATIVE CONTROL + PROCEDURES AND MANUALS

107517
DIESEL GENERATOR FAILS TO START IN LESS THAN 10 SECONDS AT FT. CALHOUN
OMAHA PUBLIC POWER DISTRICT, OMAHA, NEB.
4 PGS., LTR W/AU 50-285/75-19 TO U.S. NRC, REGION IV, OCT. 10, 1975, DOCKET 50-285, TYPE--PWR, HFG--COMB., AE--GIBBS & HILL

CAUSE - PRESSURE REGULATOR FAILURE. DURING A TEST WITH THE UNIT IN COLD SHUTDOWN, DIESEL GENERATOR DI FAILED TO START IN LESS THAN 10 SECONDS. THE PRIMARY STARTING AIR MOTOR FAILED TO START THE DIESEL. THE SECONDARY AIR STARTING SYSTEM SUCCESSFULLY STARTED IT. THE SYSTEM WAS AT FULL LOAD IN 2.5 SECONDS. THE PRESSURE REGULATOR FAILED TO ALLOW SUFFICIENT IR TO THE START MOTOR. THE REGULATOR WAS REBUILT, THE AIR STRAINER CLEANED, AND THE AIR START MOTORS LUBRICATED. THEN THE DIESEL STARTED IN 0.9 SECONDS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FT. CALHOUN (PWR) + RESPONSE TIME + GENERATOR, DIESEL + ENGINES, INTERNAL COMBUSTION + PNEUMATIC SYSTEM + VALVES + FLOW BLOCKAGE + FAILURE, EQUIPMENT + CRUD + TEST, SYSTEM OPERABILITY

107722

DIESEL GENERATOR FAILS TO START IN LESS THAN 10 SECONDS AT FT. CALHOUN
 OMAHA PUBLIC POWER DISTRICT, OMAHA, NEB.
 3 PGS, LTR W/AD 50-285/75-60 TO U.S. NRC, REGION IV, OCT. 15, 1975, DOCKET 50-285, TYPE--PWR, NRG--COMB., AE--
 GIBBS & HILL

CAUSE - DEFECTIVE AIR START MOTORS. DURING TESTING WITH THE REACTOR AT 1200 MW, DIESEL GENERATOR
 DID NOT START IN LESS THAN 10 SECONDS. AIR START MOTORS WERE LUBRICATED. ONE OF THE
 PRIMARY MOTORS WAS REPLACED. THE DIESEL THEN STARTED WITHIN THE 10 SEC LIMIT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

FT. CALHOUN (PWR) + GENERATOR, DIESEL + ENGINES, INTERNAL COMBUSTION + TEST, SYSTEM OPERABILITY + PNEUMATIC
 SYSTEM + MOTORS + FAILURE, MAINTENANCE ERROR + LUBRICATION

109207

SEQUENCED SIGNAL SEQUENCE FAILS TO ACTUATE IN SET TIME AT FT. CALHOUN
 OMAHA PUBLIC POWER DISTRICT, OMAHA, NEB.
 3 PGS, LTR W/AD 50-285/75-100 TO U.S. NRC, REGION IV, OCT. 29, 1975, DOCKET 50-285, TYPE--PWR, NRG--COMB., AE--
 GIBBS & HILL

CAUSE - BINDING OPERATING MECHANISM. DURING A TEST WITH THE REACTOR AT 898 POWER, SEQUENCER S1-2
 TIMED RELAY FOR AC-10A FAILED TO TIME OUT AT ITS SET TIME. BINDING OF THE OPERATING MECHANISM
 RETARDED THE TIME RELAY AFTER IT HAD RECEIVED ITS UNLATCHING SIGNAL CAUSING THE RELAY TO TIME
 OUT AT 7.4 SECONDS RATHER THAN ITS SET TIME OF 4.0 SEC. SINCE THIS RELAY FAILED FOLLOWING
 CLEANING AND LUBRICATION, IT WAS CLASSIFIED AS DEFECTIVE AND REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

FT. CALHOUN (PWR) + RELAYS + ENGINEERED SAFETY FEATURE + TEST, SYSTEM OPERABILITY + FAILURE, INSTRUMENT +
 CONTROL SYSTEM + UNLATCH + SET POINT

108523

STEAM GENERATOR BLOWDOWN ACTIVITY NOT RECORDED CONTINUOUSLY AT FT. CALHOUN
 OMAHA PUBLIC POWER DISTRICT, OMAHA, NEB.
 4 PGS, LTR W/AD 50-285/75-41 TO U.S. NRC, REGION IV, NOV. 4, 1975, DOCKET 50-285, TYPE--PWR, NRG--COMB., AE--
 GIBBS & HILL

CAUSE - BLOWN FUSE. WITH THE REACTOR AT 898 POWER AND CONTINUOUS BLOWDOWN IN PROGRESS ON BOTH
 STEAM GENERATORS, THE PROCESS RADIATION MONITOR RECORDER WAS OBSERVED NOT TO BE PRINTING.
 BLOWDOWN WAS TERMINATED. THE FUSE TO THE CHART DRIVE MOTOR HAD BLOWN. THE FUSE RATING IS VERY
 CLOSE TO THE NORMAL LOAD AMPERAGE. ANY ADDITIONAL LOAD WILL CAUSE THE FUSE TO BLOW. THE FUSE
 WAS REPLACED AND BLOWDOWN CONTINUED. THE RADIATION MONITORS WERE AVAILABLE AND WOULD HAVE
 TERMINATED BLOWDOWN IF ACTIVITY HAD INCREASED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

FT. CALHOUN (PWR) + RECORDERS + RADIATION MONITORS + STEAM GENERATOR + BLOWDOWN + FAILURE, INSTRUMENT +
 INSTRUMENT, PROTECTIVE

108547

SEAL MATERIAL WITHIN GRINNELL HYDRAULIC SHOCK SUPPRESSOR FAILS AT FT. CALHOUN
 OMAHA PUBLIC POWER DISTRICT, OMAHA, NEB.
 4 PGS, LTR W/AD 50-285/75-7 TO U.S. NRC, REGION IV, NOV. 11, 1975, DOCKET 50-285, TYPE--PWR, NRG--COMB., AE--
 GIBBS & HILL

CAUSE - MATERIAL COMPATIBILITY AND HEAT. DURING A SHUTDOWN, A GRINNELL SHOCK SUPPRESSOR WAS
 REMOVED AND DISASSEMBLED TO INVESTIGATE A LEAK. TWO SPECIAL O-RING SEALS LOCATED ON THE PISTON
 SHAFT OUTSIDE DIAPHRAGM WERE FOUND TO BE BRITTLE. BRITTLENESS WAS FOUND ON SEALS IN 2 OTHER
 UNITS. THE PROBLEM SELMS TO BE COMPATIBILITY OF THE SEAL MATERIALS WITH THE HYDRAULIC FLUID AND
 THE HEAT. THE MATERIAL IS CALLED POLYTHANE. NEW SEAL KITS ARE ON ORDER FOR ALL 24 GRINNELL
 UNITS. THEY WILL BE INSTALLED WHEN FEASIBLE AFTER THEY ARE RECEIVED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

FT. CALHOUN (PWR) + SEAL + LEAK + FAILURE, DESIGN ERROR + FAILURE, COMMON MODE + SURVEILLANCE PROGRAM +
 SHOCK ABSORBER

108877

TWO GAS DECAY TANKS RELEASED PRIOR TO 30 DAY HOLDUP TIME AT FT. CALHOUN
 OMAHA PUBLIC POWER DISTRICT, OMAHA, NEB.
 9 PGS, LTR W/AD 50-285/75-22 TO U.S. NRC, REGION IV, NOV. 28, 1975, DOCKET 50-285, TYPE--PWR, NRG--COMB., AE--
 GIBBS & HILL

100877 *CONTINUED*

CAUSE - LIQUID WASTE EVAPORATOR FAILURE. CONTROLLED RELEASE OF WASTE GAS DECAY TANKS C AND D PRIOR TO 30 DAY HILOUP WAS NECESSARY DUE TO THE LIQUID WASTE EVAPORATOR BEING INOPERABLE. BOTH RELEASES WERE WELL WITHIN THE LIMIT FOR SLAP. EMERGENCY REPAIRS WERE CONDUCTED ON THE EVAPORATOR. THE TOTAL AMOUNT OF ACTIVITY RELEASED WAS 0.7234 CI.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM CHARGE \$2.00)

FT. CALHOUN (PWR) * AIRBORNE RELEASE * STORAGE CONTAINER * PRETENTION * FAILURE, EQUIPMENT * WASTE TREATMENT * EVAPORATION

109582

MPSI VALVE FAILS TO OPEN ON SIGNAL AT FT. CALHOUN
OMAHA PUBLIC POWER DISTRICT, OMAHA, NE

6 PGS, LTR W/AD 50-285/75-23 TO U.S. NRC, REGION IV, DEC. 9, 1975, DOCKET 50-285, TYPE--PWR, NRG--COMB., AE--GIBBS & HILL

CAUSE - MOTOR STARTER BINDING. IN PREPARATION FOR MAINTENANCE ON SAFETY INJECTION SYSTEM, 1 OF THE 8 MPSI VALVES FAILED TO OPEN ON SIGNAL. A GE TYPE 7700, SIZE 1 COMBINATION BREAKER/REVERSING SWITCHER FAILED TO OPERATE DUE TO A BINDING CONTACT. THE CONTACT WAS LUBRICATED, ADJUSTED AND SATISFACTORILY TESTED. THE REACTOR WAS OPERATING AT 90% POWER AT THE TIME.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM CHARGE \$2.00)

FT. CALHOUN (PWR) * VALVES * BREAKER * VALVE OPERATORS * FAILURE, EQUIPMENT * FAILURE, INHERENT * MPSI

109581

UNPLANNED RELEASE OF RADIOACTIVE GAS AT FT. CALHOUN

OMAHA PUBLIC POWER DISTRICT, OMAHA, NE

6 PGS, LTR W/AD 50-285/75-24 TO U.S. NRC, REGION IV, DEC. 15, 1975, DOCKET 50-285, TYPE--PWR, NRG--COMB., AE--GIBBS & HILL

CAUSE - INADVERTENT OPENING OF RELIEF VALVE. WHILE VENTING THE VOLUME CONTROL TANK TO WASTE GAS DECAY TANK USING THE WASTE GAS COMPRESSORS, HIGH STACK ACTIVITY WAS INDICATED. VENTING WAS TERMINATED IMMEDIATELY. THE DRESSER RELIEF VALVE, MODEL 1970 C, ON THE WASTE GAS DECAY TANK HAD INADVERTENTLY OPENED. IT WAS GAGGED AND WILL BE REPAIRED AT THE EARLIEST OPPORTUNITY. THE RELEASE LASTED 3 TO 6 MINUTES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM CHARGE \$2.00)

FT. CALHOUN (PWR) * AIRBORNE RELEASE * VALVES * PRESSURE RELIEF * WASTE HANDLING * WASTE STORAGE * STORAGE CONTAINER * FAILURE, EQUIPMENT

109580

RADIOACTIVE WASTE GAS VENTED WITHOUT AUTOMATIC ISOLATION DEVICE AT FT. CALHOUN

OMAHA PUBLIC POWER DISTRICT, OMAHA, NE

6 PGS, LTR W/AD 50-285/75-25 TO U.S. NRC, REGION IV, DEC. 26, 1975, DOCKET 50-285, TYPE--PWR, NRG--COMB., AE--GIBBS & HILL

CAUSE - PROCEDURAL DEFICIENCY. DURING A REVIEW, IT WAS DISCOVERED THAT THE REACTOR COOLANT SYSTEM FILL AND VENT PROCEDURE ALLOWED FOR VENTING THE RCS TO THE ENVIRONMENT WITHOUT AN AUTOMATIC ISOLATION DEVICE. RELEASES WERE CONTINUOUSLY MONITORED. FURTHER INVESTIGATION FOUND THAT CONTAINMENT PRESSURE REDUCTION USING THE HYDROGEN PURGE FANS DID NOT INCLUDE AN AUTOMATIC ISOLATION DEVICE. THE APPROVED PROCEDURES WERE IN ERROR. RCS PROCEDURES WILL BE MODIFIED. NO CONTAINMENT PRESSURE REDUCTIONS WILL BE MADE USING THE FANS UNTIL THE RELEASE PATH IS MODIFIED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM CHARGE \$2.00)

FT. CALHOUN (PWR) * CONTROL SYSTEM * CONTAINMENT ISOLATION * WASTE DISPOSAL * WASTE DISPOSAL, GAS * AIRBORNE RELEASE * FAILURE, ADMINISTRATIVE CONTROL * PROCEDURES AND MANUALS * ENGINEERED SAFETY FEATURE

09279

TURBINE DRIVEN AUXILIARY FEEDWATER PUMP TRIP AT GINNA

ROCHESTER GAS AND ELECTRIC CORPORATION, NEW YORK

3 PAGES, LETTER WITH AD REPORT 75/1 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, JANUARY 17, 1975, DOCKET 50-244, TYPE--PWR, NRG--HEAT, AE--GILBERT ASSOC.

CAUSE - MAINTENANCE ERROR. DURING TESTING OF THE TURBINE DRIVEN AUXILIARY FEEDWATER PUMP WITH THE REACTOR AT 92% POWER, THE TURBINE GOVERNOR VALVE AND ASSOCIATED TRIP AND THROTTLE VALVES TRIPPED CLOSED. TRIPPING RESULTED FROM A DEGRADED LUBE OIL SUPPLY PRESSURE DUE TO DRIFT OF THE LUBE OIL SUPPLY REGULATOR. PROCEDURES DID NOT REQUIRE CHECKING THE REGULATOR. THE REGULATOR AND THE PRESSURE WERE CHECKED AND SET PROPERLY. PROCEDURES WERE MODIFIED. THE PUMP THEN STARTED PROPERLY.

100279 (CONTINUED)
 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

FAILURE, COMPONENT + CONTROL + TEST, SYSTEM OPERABILITY + FAILURE, MAINTENANCE ERROR + LUBRICATION + TURBINE +
 GINNA (PWR) + FEEDWATER + PUMPS + VALVES

100281
 SAFETY INJECTION PUMP FAILS TO START AT GINNA
 ROCHESTER GAS AND ELECTRIC CORPORATION, N.Y.
 4 PAGES, LETTER WITH AD REPORT 75/2 AND 75/3 TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, REGION 1, FEBRUARY
 14, 1975, DCKET 50-244, TYPE--PWR, NRC--WEST., AE--GILBERT ASSOC.

CAUSE - UNKNOWN DEFICIENCIES. DURING TESTING WHILE OPERATING AT 100% POWER, SAFETY INJECTION
 PUMP IC FAILED TO START MANUALLY ON THE FIRST TRY ON TWO CONSECUTIVE DAYS. ITS BREAK WAS
 EXAMINED. A SPRING IN 1 OF THE 24 SECONDARY CONTACTS WAS FOUND TO BE WEAR. IT WAS REPLACED.
 ALSO, A WIRE WAS FOUND TO BE LOOSE AT ITS TERMINAL. IT WAS SECURED. ALL OTHER WIRES WERE FOUND
 TO BE SECURED. NO OTHER FAILURES HAVE OCCURRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

FAILURE, COMPONENT + SAFETY INJECTION + TEST, SYSTEM OPERABILITY + FAILURE, INSTALLATION ERROR + GINNA (PWR) +
 CABLES AND CONNECTORS + BREAKER + PUMPS

100280
 SOLENOID TEST VALVES FAIL TO OPERATE A RSTV AT GINNA
 ROCHESTER GAS AND ELECTRIC CORPORATION, N.Y.
 3 PAGES, LETTER WITH AD REPORT 75/04 TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, REGION 1, FEBRUARY 21, 1975.
 DCKET 50-244, TYPE--PWR, NRC--WEST., AE--GILBERT ASSOC.

CAUSE - FLAT SPOT ON LATCHING PIN. DURING MAIN STEAM ISOLATION VALVE SOLENOID TRIP TESTING WHILE
 OPERATING AT 100% POWER, 1 OF THE 2 SERIES AIR SUPPLY SOLENOIDS DID NOT TRIP TO THE CLOSED
 POSITION ALTHOUGH THE COIL ARMATURE DID PICK UP. REPEAT TESTING RESULTED IN FAILURE OF THE SAME
 VALVE AND ALSO 1 OF THE AIR EXHAUST VALVES. FAILURE WAS IN THEIR MECHANICAL OPERATION. IT IS
 BELIEVED THAT A FLAT SPOT OR BURR MAY HAVE DEVELOPED ON THE LATCHING PIN OF THE TRIP MECHANISM.
 ROTATION FROM ITS FIXED POSITION PRODUCED SUCCESSFUL RETESTING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

FAILURE, COMPONENT + CONTAINMENT ISOLATION + STEAM + TEST, SYSTEM OPERABILITY + MAIN COOLING SYSTEM +
 PNEUMATIC SYSTEM + GINNA (PWR) + SOLENOID + VALVES

100276
 SAFETY INJECTION PUMP FAILS TO START MANUALLY AT GINNA
 ROCHESTER GAS AND ELECTRIC CORP., N.Y.
 4 PAGES, LETTER WITH AD REPORT 75/5 TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, REGION 1, FEBRUARY 26, 1975.
 DCKET 50-244, TYPE--PWR, NRC--WEST., AE--GILBERT ASSOC.

CAUSE - BREAKER MALFUNCTION. BUS 16 POWER SUPPLY CIRCUIT BREAKER TO SAFETY INJECTION PUMP IC,
 ALTERNATE TO A SIMILAR BREAKER AT BUS 14, FAILED TO CLOSE DURING A MANUAL TEST START. THE
 LOCKOUT SOLENOID PLUNGER UNIT WAS OBSERVED TO START BUT IN A SLUGGISH MANNER, NOT COMPLETING ITS
 STROKE. THE CAUSE OF THE ERRATIC BEHAVIOR HAS NOT BEEN DETERMINED. DURING THE UPCOMING
 REFUELING OUTAGE, A MORE DETAILED INSPECTION WILL BE MADE WHEN BUS 16 CAN BE DEENERGIZED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

FAILURE, COMPONENT + SAFETY INJECTION + TEST, SYSTEM OPERABILITY + CHEMICAL SHIM + GINNA (PWR) + BREAKER +
 PUMPS

100286
 TWO CONTROL RODS DROPPED AT GINNA
 ROCHESTER GAS & ELECTRIC CORP., N.Y.
 2 PAGES, LETTER WITH AD REPORT 75/02 TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, REGION 1, MARCH 17, 1975.
 DCKET 50-244, TYPE--PWR, NRC--WEST., AE--GILBERT ASSOC.

CAUSE - CONSTRUCTION ERROR. DURING CORE BORING OF THE FLOOR ABOVE THE CONTROL ROD CABINETS, A
 TURBINE RUNBACK TO 70% OCCURRED. TWO CONTROL RODS WERE OBSERVED AT THE BOTTOM OF THE CORE. WITH
 THE UNIT AT HOT SHUTDOWN, THEY WERE EXERCISED TO VERIFY OPERABILITY. A WATER HOSE FOR THE BORING
 MACHINE BROKE AT A COUPLING. WATER DRAINED THROUGH 2 NEW HOLES TO THE TOP OF THE CONTROL ROD
 CABINETS GRABBERING OUT CONTROL POWER FOR THE STATIONARY GRIPPERS FOR THESE CONTROL RODS, ALLOWING
 THEM TO DROP. OPENINGS HAVE BEEN COVERED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

CONTROL SYSTEM + MAINTENANCE AND REPAIR + FAILURE, MAINTENANCE ERROR + ELECTRICAL CONDUCTION + GINNA (PWR) +

100898 *CONTINUED*
 REACTOR SHUTDOWN + CONTROL RODS

100924
 UNPLANNED INSERTION OF REACTIVITY EXCEEDS LIMIT DURING SHUTDOWN AT GINNA
 ROCHESTER GAS & ELECTRIC CORPORATION, N.Y.
 3 PAGES, LETTER WITH AU REPORT 75/06 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, MARCH 25, 1975,
 DOCKET 50-244, TYPE--PHR, MFG--WEST., AE--GILBERT ASSOC.

CAUSE - PROCEDURAL ERROR. DURING STEPS TO PROVIDE ADDITIONAL PURIFICATION OF REACTOR COOLANT WITH
 THE REACTOR IN COLD SHUTDOWN, BORON CONCENTRATION WAS REDUCED INADVERTENTLY FROM 2368 PPM TO 1975
 PPM, AN INSERTION OF MORE THAN 0.5% REACTIVITY. BORON CONCENTRATION WAS RESTORED TO ABOVE 2000
 PPM IN PREPARATION FOR REFUELING. IN 1972 CATION RESINS WERE PLACED IN 1 OF 2 DEORATING
 DEMINERALIZERS. THE PROCEDURE TO VALVE IN THIS CONVERTED DEMINERALIZER WAS IN ERROR. A
 DEORATING DEMINERALIZER WAS VALVED IN INSTEAD. PROCEDURES HAVE BEEN REVISED. VALVES WILL BE
 MARKED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

PROCEDURES AND MANUALS + REACTIVITY EFFECT + REFUELING + CHEMICAL SHIM + FAILURE, ADMINISTRATIVE CONTROL +
 MAIN COOLING SYSTEM + GINNA (PHR) + CONCENTRATION + DEMINERALIZERS

101700
 ABNORMAL DEGRADATION OF STEAM GENERATOR TUBES AT GINNA
 ROCHESTER GAS & ELECTRIC CORP., N.Y.
 3 PAGES, LETTER WITH AU REPORT 75/07 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, APRIL 7, 1975, DOCKET 50-244,
 TYPE--PHR, MFG--WEST., AE--GILBERT ASSOC.

CAUSE - LOCAL CORROSION. DURING EDDY CURRENT INSPECTION OF STEAM GENERATOR TUBES, RESULTS SHOWED
 10 ASG HOT LEG TUBES AND 12 BGS HOT LEG TUBES WITH WALL THINNING OF 50% OR GREATER. THINNING IN
 THE ASG WAS REPORTED ON FEB. 19, 1974. THE TUBES ARE TO BE PLUGGED. LOCAL CORROSION OF TUBE OD
 SURFACE IS BELIEVED TO HAVE BEEN CAUSED BY PHOSPHATE RESIDUE NOT REMOVED ON CHANGE TO ALL
 VOLATILE TREATMENT CHEMICAL CONTROL. SHELL SIDE OF THE TUBE SHEETS WILL BE CLEANED USING A HIGH
 PRESSURE WATER LANCE TO REMOVE ANY REMAINING SLODGE CONTAINING PHOSPHATES OR CAUSTICS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

CORROSION + INCONEL + FAILURE, TUBING + STEAM GENERATOR + SURVEILLANCE PROGRAM + TUBING + GINNA (PHR)

101732
 DEGRADATION OF CHARCOAL FILTER IODINE REMOVAL EFFICIENCY AT GINNA
 ROCHESTER GAS & ELECTRIC CORP., N.Y.
 2 PAGES, LETTER WITH AU REPORT 75/08 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, APRIL 17, 1975,
 DOCKET 50-244, TYPE--PHR, MFG--WEST., AE--GILBERT ASSOC.

CAUSE - AGING OF THE CHARCOAL. DURING THE REFUELING SHUTDOWN, SAMPLES FROM THE POST ACCIDENT
 FILTER CHARCOAL SHOWED MOLECULAR IODINE REMOVAL EFFICIENCIES OF 99.4% AND 99.9% AND METHYL
 IODINE REMOVAL EFFICIENCIES OF 95.9% AND 96.7%. MOLECULAR IODINE REMOVAL SPEC. IS 99.9%. THE
 FILTER WHICH FAILED TO MEET LIMITS WILL BE CHARGED WITH CHARCOAL MEETING THE SPEC. THE REDUCED
 MOLECULAR IODINE REMOVAL EFFICIENCY MAY BE DUE TO AGING OF THE CHARCOAL. THE FILTERS WERE
 INSTALLED IN 1969.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

FILTER EFFICIENCY + IODINE + CHARCOAL + CONTAINMENT FILTERING SYSTEM + REFUELING + TEST, SYSTEM OPERABILITY +
 GINNA (PHR) + EFFECT, AGE + FILTERS

102290
 CHARCOAL FILTER IODINE REMOVAL EFFICIENCY DEGRADED AT GINNA
 ROCHESTER GAS & ELECTRIC CORP., N.Y.
 1 PAGE, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, APRIL 17, 1975, DOCKET 50-244, TYPE--PHR,
 MFG--WEST., AE--GILBERT ASSOC.

CAUSE - AGING OF CHARCOAL. DURING THE REFUELING SHUTDOWN, THE POST-ACCIDENT FILTERS, CHARCOAL
 SAMPLES SHOWED FILTER 'A' MOLECULAR IODINE REMOVAL EFFICIENCY OF 99.4% WHICH IS BELOW THE 99.9%
 LIMIT. METHYL IODIDE REMOVAL EFFICIENCIES WERE 95.9% AND 96.7% FOR THE TWO FILTERS. REDUCED
 MOLECULAR IODINE REMOVAL EFFICIENCY MAY BE DUE TO AGING OF THE CHARCOAL. FILTERS WERE
 INSTALLED IN 1969. FILTER A WILL BE CHARGED WITH CHARCOAL MEETING THE LIMIT. A TECH SPEC
 CHANGE IS BEING CONSIDERED TO USE 90.0% METHYL IODIDE REMOVAL EFFICIENCY AS THE LIMIT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

GINNA (PHR) + FILTER EFFICIENCY + CHARCOAL ADSORBER + EFFECT, AGE + STANDBY GAS TREATMENT + TEST, FILTER +
 TEST, SYSTEM OPERABILITY + REFUELING + IODINE

102555
PINHOLE LEAK FOUND ON CONTROL ROD DRIVE ROD TRAVEL HOUSING AT GINNA
ROCHESTER GAS & ELECTRIC CORPORATION, N.Y.
2 PAGES. LETTER WITH ACR 75-09 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, APRIL 22, 1975, DOCKET 50-244. TYPE--PMR, MFG--WEST., AE--GILBERT ASSOC.

CAUSE - INSTALLATION ERROR. VISUAL INSPECTION OF CAPS ON CONTROL ROD DRIVE ROD TRAVEL HOUSINGS REVEALED A PUMERY DEPOSIT ON A CAP. A PINHOLE LEAK HAD DEVELOPED IN THE CANNOPY SECTION OF THE CAP ABOVE THE SEAL WELD OF THE CAP TO THE HOUSING. THE CAP WAS REPLACED. APPARENTLY, THE CAP HAD NOT BEEN TORQUED DOWN SUFFICIENTLY PERMITTING HUMID WATER TO LEAK THROUGH THE SEAL AND THREADS AND ULTIMATELY THROUGH A MACHINING DEFECT AT THE THINNED WALL SECTION OF THE CAP.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM CHARGE \$2.00

GINNA (PMR) + PIPES AND PIPE FITTINGS + LEAK + CONTROL ROD DRIVE MECHANISM + FAILURE, INSTALLATION ERROR + FLAW + REACTOR COOLANT + FAILURE, PIPE

102795
SMALL LEAK FOUND IN LETDOWN DRAIN LINE WELD AT GINNA
ROCHESTER GAS & ELECTRIC CORP., N.Y.
2 PAGES. LETTER WITH DE 75-02 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, MAY 8, 1975, DOCKET 50-244. TYPE--PMR, MFG--WEST., AE--GILBERT ASSOC.

CAUSE - INCOMPLETE FUSION IN WELD. DURING ROUTINE OPERATIONS, A SMALL LEAK WAS FOUND ON A LETDOWN LINE DRAIN LINE REGULATOR WELD. THE LEAK WAS REPAIRED. THE WELD, PERFORMED DURING CONSTRUCTION IN A RELATIVELY INACCESSIBLE LOCATION, WAS APPLIED SUCH THAT A WELD ARC START WAS ON TOP OF A STOP LEAVING AN AREA OF INCOMPLETE FUSION. THIS WEAK POINT ULTIMATELY LEAD TO THE DEVELOPMENT OF THE LEAK.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM CHARGE \$2.00

GINNA (PMR) + WELDS + PIPES AND PIPE FITTINGS + COOLANT PURIFICATION SYSTEM + LEAK + FAILURE, PIPE + FAILURE, INSTALLATION ERROR + FLAW

109653
INDIVIDUALS OVEREXPOSED AND AIR MASK TRAINING NOT DOCUMENTED AT GINNA
ROCHESTER GAS & ELECTRIC CORP., ROCHESTER, N.Y.
2 PAGES. LETTER WITH REPORT TO NRC OFFICE OF IS, MAY 19, 1975, DOCKET 50-244. TYPE--PMR, MFG--WEST., AE--GILBERT ASSOCIATES

CAUSE - ADMINISTRATIVE DEFICIENCY. WHILE PLUGGING TUBES IN STEAM GENERATOR A, SIX INDIVIDUALS ENTERED THE TENT AROUND THE SG MANWAY USING MASKS WITH A PROTECTION FACTOR OF 100, INTO AN ATMOSPHERE WHICH WAS 770 TIMES MPC. ALL WERE GIVEN WHOLE BODY COUNTS AND ONE SHOWED AN UPTAKE ABOVE LIMITS. THE DOSE TO THE LUNG FROM CO AND AR IS 9.6 REM FOR THE FIRST YEAR. ALL HAD RECEIVED TRAINING EXCEPT ONE. THREE OTHERS USED THE PROPER MASKS BUT WITHOUT DOCUMENTED MASK USE TRAINING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM CHARGE \$2.00

GINNA (PMR) + PERSONNEL EXPOSURE, RADIATION + MAINTENANCE AND REPAIR + STEAM GENERATOR + FILTER, GAS MASK + PERSONNEL PROTECTIVE DEVICE + TRAINING + INHALATION + FAILURE, ADMINISTRATIVE CONTROL

104052
SAFETY INJECTION PUMP DISCHARGE VALVES FOUND CLOSED AT GINNA
ROCHESTER GAS & ELECTRIC CORP., N.Y.
2 PAGES. LETTER WITH ACR 75-10 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, JUNE 25, 1975, DOCKET 50-244. TYPE--PMR, MFG--WEST., AE--GILBERT ASSOC.

CAUSE - OPERATOR ERROR. DURING TESTING OF SI PUMP C WITH THE REACTOR AT 90% POWER, BOTH DISCHARGE VALVES WERE FOUND CLOSED. THE VALVES WERE PLACED IN THE OPEN POSITION. INCORRECT VALVE POSITION WAS DUE TO OPERATOR ERROR DURING SI PUMP MONTHLY TESTING. NO INADEQUACIES WERE NOTED IN THE PROCEDURES. THE OPERATOR INVOLVED WAS REPRIMAND FOR HIS ERROR.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM CHARGE \$2.00

GINNA (PMR) + VALVES + SAFETY INJECTION + TEST, SYSTEM OPERABILITY + FAILURE, OPERATOR ERROR

103607
SAFETY INJECTION DISCHARGE VALVES FOUND CLOSED AT GINNA
ROCHESTER GAS & ELECTRIC CORP., N.Y.
3 PAGES. LETTER WITH ACR 75-10 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, JUNE 25, 1975, DOCKET 50-244. TYPE--PMR, MFG--WEST., AE--GILBERT ASSOC.

CAUSE - OPERATOR ERROR. DURING TESTING WHILE THE REACTOR WAS AT 90% POWER, THE 2 DISCHARGE

103687 CONTINUED

VALVES FOR SI PUMP C WERE FOUND CLOSED. THE VALVES WERE PLACED IN THE OPEN POSITION. THE INCORRECT POSITION OF THE VALVES WAS DUE TO OPERATOR ERROR DURING SAFETY INJECTION PUMP TESTING. THE OPERATION INVOLVED WAS REPHRASED FOR HIS ERROR. NO INADEQUACIES WERE NOTED IN THE PROCEDURE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM CHARGE \$2.00

GINNA (PWR) + 0 VALVES + 0 SAFETY INJECTION + FAILURE, OPERATOR ERROR + PROCEDURES AND MANUALS + TEST, SYSTEM OPERABILITY

103688

SAMPLING SCHEDULE FOR REACTOR COOLANT FOUND DEFICIENT AT GINNA
ROCHESTER GAS & ELECTRIC CORP., N.Y.

2 PAGES, LETTER WITH AOR 75-18, TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, JUNE 30, 1975, DOCKET 50-244, TYPE--PWR, MFG--WEST., AE--GILBERT ASSOC.

CAUSE - OPERATOR ERROR. DURING NORMAL POWER ESCALATION AFTER SHUTDOWN, REACTOR COOLANT SYSTEMS GROSS ACTIVITY INCREASED TO 10.4% OF THE LIMIT. FREQUENCY OF GROSS ACTIVITY ANALYSIS WAS NOT IMMEDIATELY INCREASED TO DAILY UNTIL A STEADY ACTIVITY LEVEL WAS ESTABLISHED. FAILURE WAS DUE TO THE OBSERVATION THAT STEADY STATE HAD BEEN REACHED BASED ON DEGASSED ACTIVITY ANALYSIS. GROSS ACTIVITY HAS BEEN 15 TO 20% OF THE LIMIT FOR THE PAST 3 YEARS DUE TO TRAMP URANIUM AND IS PROPORTIONAL TO POWER LEVEL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM CHARGE \$2.00

GINNA (PWR) + CHEMICAL ANALYSIS + 0 FISSION PRODUCT ACTIVITY, GROSS + REACTOR COOLANT + FAILURE, OPERATOR ERROR + 0 TEST INTERVAL

104209

SPURIOUS CLOSING OF MAIN STEAM ISOLATION VALVE AT GINNA
ROCHESTER GAS & ELECTRIC CORP., N.Y.

2 PAGES, LETTER WITH AOR 75-03 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, JULY 15, 1975, DOCKET 50-244, TYPE--PWR, MFG--WEST., AE--GILBERT ASSOC.

CAUSE - SLIGHT ROTATION OF DISK. WHILE THE REACTOR WAS OPERATING AT 88% POWER, THE MSIV'S CLOSED WITHOUT OPERATION OF THE AIR SOLENOID VALVES WHICH NORMALLY CAUSE OPERATION. THE REACTOR WAS TAKEN TO COLD SHUTDOWN. SPURIOUS CLOSURES ARE BELIEVED TO HAVE BEEN CAUSED BY SUFFICIENT ROTATION OF VALVE DISK TO ALLOW THE FLOWING STEAM TO ACT ON THE LEADING EDGE TO FORCE THE VALVE TO CLOSE. THE RUBBER PISTON SEAT IN THE ACTUATOR WAS REMOVED TO INCREASE PISTON STROKE AND 1 INCH OF METAL WAS REMOVED FROM THE VALVE DISK STOP TO PERMIT POSITIONING THE LEADING EDGE OF THE DISK OUT OF STEAM FLOW.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM CHARGE \$2.00

GINNA (PWR) + 0 VALVES + VALVE, CHECK + 0 CONTAINMENT ISOLATION + 0 MAIN COOLING SYSTEM + FAILURE, DESIGN ERROR + STEAM + MODIFICATION + SCRAM, SPURIOUS + REACTOR SHUTDOWN

104954

UNDERVOLTAGE RELAY MALFUNCTIONS AT GINNA
ROCHESTER GAS & ELECTRIC CORP., NEW YORK

2 PAGES, LETTER WITH AOR REPORT 75-12 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, AUG. 5, 1975, DOCKET 50-244, TYPE--PWR, MFG--WEST., AE--GILBERT ASSOC.

CAUSE - DEPOSIT ON PLUNGER. DURING TESTING OF THE UNDERVOLTAGE RELAYS WITH THE REACTOR AT FULL POWER, ONE DEVICE FAILED TO DROP TO THE DE-ENERGIZED POSITION AFTER AN UNDERVOLTAGE SIGNAL WAS STIMULATED. A BUILDUP OF BUSHING DEPOSITS ON THE PLUNGER SHAFT CAUSED THE MALFUNCTION. ALL 4 WESTINGHOUSE TYPE SV 75-150V AC UNDERVOLTAGE RELAYS WERE FIELD STRIPPED TO CLEAN PLUNGERS. THEY WERE RETESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM CHARGE \$2.00

GINNA (PWR) + 0 RELAYS + 0 CHAD + TEST, SYSTEM OPERABILITY + INSTRUMENT, PROTECTIVE + FAILURE, DESIGN ERROR

105549

SET POINT DRIFT IN TEMPERATURE DIFFERENTIAL DISTABLE AT GINNA
ROCHESTER GAS & ELECTRIC CORP.

2 PGS, LTR W/AOR 75-04 TO NRC OFFICE OF I & E, REGION 1, AUG. 21, 1975, DOCKET 50-244, TYPE--PWR, MFG--WEST., AE--GILBERT ASSOC.

CAUSE - ZENER DIODE FAILURE. DURING TESTING WITH THE REACTOR AT 100% POWER, THE OVERPOWER DELTA T TRIP BISTABLE SET POINT WAS FOUND TO BE OFF IN THE NONCONSERVATIVE DIRECTION BY 1.70 F. THE UNIT WAS REPLACED WITH A BENCH TESTED SPARE UNIT. A FOXBORO 43 V D.C. ZENER DIODE HAD FAILED IN THE POWER SUPPLY CIRCUIT.

105294 REPTINGED
 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

GINNA (PWR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SENSORS, TEMPERATURE • TEST, SYSTEM OPERABILITY •
 • SET POINT • DRIFT • REACTOR SAFETY SYSTEM • FAILURE, COMPONENT • ELECTRONIC FUNCTION UNITS

105298
 SET POINT DRIFT IN TEMPERATURE DISTABLE AT GINNA
 ROCHESTER GAS & ELECTRIC CORP.
 2 PGS, LTR #/AUG 75-04 TO NRC OFFICE OF I & E, REGION 1, AUG. 21, 1975, DOCKET 50-244, TYPE--PWR, WFG--WEST.,
 AE--GILBERT ASSOC.

CAUSE - ZENER DIODE FAILURE. DURING TESTING WITH THE REACTOR AT FULL POWER, AN OVERPOWER
 TEMPERATURE DIFFERENTIAL DISTABLE SET POINT WAS FOUND TO BE OFF IN THE NONCONSERVATIVE DIRECTION
 BY 1.70 F. A FUZEURG 43 VDC ZENER DIODE IN THE REGULATED POWER SUPPLY HAD FAILED. THE DEFECTIVE
 DISTABLE WAS REPLACED WITH A BENCH TESTED SPARE UNIT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

GINNA (PWR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SENSORS, TEMPERATURE • FAILURE, INSTRUMENT •
 TEST, SYSTEM OPERABILITY • SET POINT • DRIFT • REACTOR SAFETY SYSTEM • ELECTRONIC FUNCTION UNITS

105297
 REFUELING WATER INACVERTENTLY TRANSFERRED TO CONTAINMENT BASEMENT AT GINNA
 ROCHESTER GAS & ELECTRIC CORP.
 3 PGS, LTR #/AUG 75-13 TO NRC OFFICE OF I & E, REGION 1, AUG. 22, 1975, DOCKET 50-244, TYPE--PWR, WFG--WEST.,
 AE--GILBERT ASSOC.

CAUSE - OPERATOR ERROR. DURING TESTING OF SAFEGUARD VALVES WITH THE REACTOR AT FULL POWER, THE
 OPERATOR CLOSED A VALVE, ERRONEOUSLY REOPENED IT, AND INITIALED THE PROCEDURE STEP AS CLOSED.
 HE NOTED IT WAS TIME FOR HOURLY READING AND TURNED THE DATA TAKING OVER TO ANOTHER OPERATOR.
 WHEN HE RETURNED TO THE TEST, HE OPENED THE NEXT VALVE, WITH BOTH VALVES OPEN, 12000 GALLONS
 OF WATER WERE TRANSFERRED FROM THE REFUELING WATER STORAGE TANK TO CONTAINMENT SUMP B IN THE 3
 MINUTES BEFORE THE ERROR WAS IDENTIFIED. NO DAMAGE OCCURRED. THE OPERATOR WAS REPRIMAND. THE
 PERSONNEL INVOLVED IN TESTING WILL BE RELIEVED OF NORMAL DUTIES AND ROUTINE OPERATIONS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

GINNA (PWR) • CONTAINMENT INTEGRITY • FAILURE, OPERATOR ERROR • TEST, SYSTEM OPERABILITY • VALVES • REACTOR
 COOLANT • PROCEDURES AND MANUALS

105248
 NOTICE OF PROPOSED CIVIL MONETARY PENALTIES AT GINNA
 NUCLEAR REGULATORY COMMISSION, WASHINGTON
 9 PGS, LTR #/AUG 75-05 TO ROCHESTER GAS & ELECTRIC CORP., AUG. 23, 1975, DOCKET 50-244, TYPE--PWR, WFG--WEST.,
 AE--GILBERT ASSOC.

CAUSE - IMPROPER RADIATION SAFETY. BASED ON RESULTS OF INSPECTIONS, CERTAIN ACTIVITIES WERE NOT
 CONDUCTED IN FULL COMPLIANCE WITH NRC REQUIREMENTS. FAILURE TO IMPLEMENT ADEQUATE MANAGEMENT
 CONTROL OF RADIATION SAFETY WAS OF PARTICULAR CONCERN. CONTRACTOR EMPLOYEES WERE PERMITTED TO
 ENTER AN ATMOSPHERE CONTAINING CONCENTRATIONS OF RADIOACTIVE MATERIALS WHICH WERE 770 TIMES MPC
 WITHOUT PROPER PROTECTIVE EQUIPMENT. OTHER OVEREXPOSURES HAD ALSO OCCURRED. NRC PROPOSES TO
 IMPOSE CIVIL PENALTIES OF \$10,000.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

GINNA (PWR) • LEGALISTICS • ECONOMICS • FAILURE, ADMINISTRATIVE CONTROL • RADIATION SAFETY AND CONTROL •
 PERSONNEL EXPOSURE, RADIATION • COMPLIANCE

106344
 BUS BREAKER FROM EMERGENCY GENERATOR FAILS TO CLOSE AT GINNA
 ROCHESTER GAS AND ELECTRIC CORP., N.Y.
 2 PGS, LTR #/AUG 75-05 TO NRC OFFICE OF I & E, REGION 1, SEPT. 15, 1975, DOCKET 50-244, TYPE--PWR, WFG--WEST.,
 AE--GILBERT ASSOC.

CAUSE - UNKNOWN. DURING A TEST OF EMERGENCY DIESEL GENERATOR 1 B, BUS 16 BREAKER FROM THE
 EMERGENCY GENERATOR FAILED ON 3 ATTEMPTS TO CLOSE MANUALLY. NO LOOSE CONNECTIONS OR DIRTY
 CONTACTS WERE FOUND IN THE BREAKER OR SWITCHES THAT COULD BE ATTRIBUTED TO THIS EVENT.
 AFTERWARDS, THE BREAKER WAS SUCCESSFULLY OPERATED 8 TIMES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

GINNA (PWR) • BREAKER • GENERATOR, DIESEL • EMERGENCY POWER, ELECTRIC • TEST, SYSTEM OPERABILITY

100614

CONTROL ROD DEVIATION MONITOR ALARM POINT CHANGED AT GINNA
ROCHESTER GAS & ELECTRIC CORP., N.Y.

3 PGS. LTR W/RE 75-07 TO NRC OFFICE OF I & E, REGION 1, SEPT. 29, 1975, DCKET 50-244, TYPE--PWR, NRG--WEST.. AE--GILBERT ASSOC.

CAUSE - UNKNOWN PERSONNEL. DURING A ROUTINE SCAN OF THE CONTROL BOARD WITH THE REACTOR AT FULL POWER, THE OPERATOR NOTED A DISCREPANCY BETWEEN ROD POSITION INDICATORS AND DATA COUNTERS. ALTHOUGH THE DEVIATION WAS LESS THAN THE NORMAL ALARM POINT FOR THE ROD DEVIATION MONITOR, HE INVESTIGATED AND FOUND THE ALARM POINT WAS SET AT THE NORMAL + OR - 7.5 INCHES. THE SET POINT HAD BEEN CHANGED TO + OR - 20 INCHES. THE TIME AND THE INDIVIDUAL INVOLVED COULD NOT BE DETERMINED. THE EVENT WAS CAUSED BY LACK OF ADMINISTRATIVE AND PROCEDURAL COVERAGE IN THE PLANT COMPUTER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

GINNA (PWR) * COMMUNICATIONS * RESET POINT * CONTROL RODS * COMPUTER CONTROL * FAILURE, ADMINISTRATIVE CONTROL * PROCEDURES AND MANUALS * MONITOR

100618

TRANSFER OF STEAM GENERATOR LEVEL CONTROL VIOLATES STANDARDS AT GINNA
ROCHESTER GAS & ELECTRIC CORP., N.Y.

3 PGS. LTR W/RE 75-06 TO NRC OFFICE OF I & E, REGION 1, SEPT. 29, 1975, DCKET 50-244, TYPE--PWR, NRG--WEST.. AE--GILBERT ASSOC.

CAUSE - ADMINISTRATIVE ERROR. AS A STEP TO ELIMINATE EXHAUSTIVE STEAM GENERATOR LEVEL INDICATION AND CONTROL SIGNAL TO THE FEEDWATER CONTROL, THE LEVEL SIGNAL INPUT WAS TRANSFERRED FROM LT-661 TO LT-662 WHILE OPERATING AT FULL POWER. THIS CONSTITUTED NON-COMPLIANCE WITH IEEE STANDARD 279-1971. AS A RESULT OF THE CIRCUITRY CHANGE, LT-662 WAS MADE PART OF THE LEVEL CONTROL SYSTEM. THE LO-LO WATER LEVEL PROTECTION SYSTEM, AND THE LO 3/2 FEEDWATER REACTOR TRIP LOGIC. WHEN THE ERROR WAS FOUND, LEVEL CONTROL WAS RETURNED TO THE ORIGINAL STATUS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

GINNA (PWR) * CONTROL SYSTEM * FEEDWATER * FAILURE, ADMINISTRATIVE CONTROL * CODES AND STANDARDS * SENSORS, LEVEL * STEAM GENERATOR

100620

CONTROL ROD FAILS TO MOVE AT GINNA
ROCHESTER GAS & ELECTRIC CORP., N.Y.

3 PGS. LTR W/RE 75-08 TO NRC OFFICE OF I & E, REGION 1, OCT. 1, 1975, DCKET 50-244, TYPE--PWR, NRG--WEST.. AE--GILBERT ASSOC.

CAUSE - OPEN CIRCUIT IN COIL. DURING ROD CONTROL SYSTEM TESTS WITH THE REACTOR AT 100% POWER, RPI INDICATED THAT ROD G-5 IN BANK B WAS NOT MOVING WITH THE BANK. THE LIFT COIL HAD AN OPEN CIRCUIT IN THE CABLE OR COIL PREVENTING NORMAL DRIVING. NORMAL ROD DROP WAS NOT IMPEDED UPON TRIP SIGNAL. THE ROD WILL BE REPAIRED AT THE EARLIEST CONVENIENT OUTAGE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

GINNA (PWR) * CONTROL ROD DRIVE MECHANISMS * FAILURE, COMPONENT * TEST, SYSTEM OPERABILITY

107765

IODINE ACTIVITY IN REACTOR COOLANT EXCEEDS LIMIT AT GINNA
ROCHESTER GAS & ELECTRIC CORP., ROCHESTER, N.Y.

2 PGS. LTR W/RE 75-09 TO NRC OFFICE OF I & E, REGION 1, NOV. 4, 1975, DCKET 50-244, TYPE--PWR, NRG--WEST.. AE--GILBERT ASSOC.

CAUSE - TEMPERATURE AND PRESSURE CYCLE. DURING A STARTUP WITH THE REACTOR COOLANT TEMPERATURE OVER 500 F, 1-131 EQUIVALENT ACTIVITY WAS REPORTED TO BE 5.43 MICRO CI/GM WHICH EXCEEDS THE LIMIT. A PARTIAL COLDOWN AND SUBSEQUENT HEATUP AND THE ACCOMPANYING DEPRESSURIZING AND PRESSURIZING OF THE FUEL RESULTED IN THE INCREASE. PURIFICATION FLOW WAS INCREASED TO THE MAXIMUM. 1-131 ACTIVITY RETURNED TO LESS THAN 3 MICRO CI/GM IN ABOUT 9 HOURS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

GINNA (PWR) * CONCENTRATION * IODINE * REACTOR COOLANT * MAIN COOLING SYSTEM * REACTOR STARTUP * THERMAL TRANSIENT * PRESSURE TRANSIENT * FISSION PRODUCT, IODINE

100510

DC WATTMETER INDICATES NO RESPONSE TO GOVERNOR CONTROL SWITCH AT GINNA
ROCHESTER GAS & ELECTRIC CORP., ROCHESTER, N.Y.

3 PGS. LTR W/RE 75-10 TO NRC OFFICE OF I & E, REGION 1, DEC. 2, 1975, DCKET 50-244, TYPE--PWR, NRG--WEST.. AE--GILBERT ASSOC.

106514 CONTINUED

CAUSE - UNKNOWN. DURING TESTING OF THE EMERGENCY GENERATOR IN, IMMEDIATELY FOLLOWING CLOSE AND TRIP OF A SERVICE WATER PUMP BREAKER, THE GENERATOR WATTMETER INDICATED NO RESPONSE TO OPERATION OF THE GENERATOR CONTROL SWITCH. DURING OPERATION OF THE PHASE CURRENT SELECTOR SWITCH, THE METER INDICATION CHANGED TO ABOUT FULL LOAD AND RESPONDED TO GOVERNOR CONTROL OPERATION. THE CAUSE HAS NOT BEEN DETERMINED. TESTING CONTINUES. THE REACTOR WAS AT 1038 POWER DURING THIS EVENT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

GENA (PHN) + INSTRUMENTS, MISC. + GENERATOR, DIESEL + ENGINES, INTERNAL COMBUSTION + TEST, SYSTEM OPERABILITY + EMERGENCY POWER, ELECTRIC

108802

PINHOLE LEAK FOUND IN CHARGING PUMP DISCHARGE DRAIN LINE AT WINNA

ROCHESTER GAS & ELECTRIC CORP., ROCHESTER, NY

2 PGS. LTR W/AS 75-11 TO NRC OFFICE OF I & E, REGION 1, DEC. 15, 1975, DOCKET 50-244, TYPE--PHN, NRC--WEST., AE--GILBERT ASSOC.

CAUSE - SMALL VOID IN WELD. DURING AN INSPECTION WHILE OPERATING AT 1008 POWER, A PINHOLE LEAK WAS NOTED IN A 3/4 INCH SULKET WELD OF CHARGING PUMP B DISCHARGE DRAIN LINE. THE PUMP WAS ISOLATED. A SMALL VOID FUMED DURING TIG WELDING RESULTING IN THE LEAK. THE WELD WAS REPAIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

GENA (PHN) + PIPES AND PIPE FITTINGS + FEEDWATER + PLEBA + FAILURE, INSTALLATION ERROR + WELDS

108895

UNPLANNED RELEASE OF RADIOACTIVE MATERIAL AT INDIAN POINT 1

CONSOLIDATED EDISON CO. OF N.Y., INC.

2 PAGES. LTR WITH ASR 5-1-1 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, JUNE 26, 1975, DOCKET 50-3, TYPE--PHN, NRC--BEN, AE--GILBERT, ED.

CAUSE - HOLE DRILLED IN INSTRUMENT LINE. DURING COLD SHUTDOWN CONDITIONS, A CONTRACTOR DRILLING A HOLE IN A CONCRETE FLOOR PUNCTURED AN INSTRUMENT PRESSURE SENSING LINE FOR A CLEAN WATER STORAGE TANK RELEASING 1.5 CI OF KR-85 TO THE ATMOSPHERE. THE TUBING WAS PUNCTURED DUE TO UNUSUAL TUBING RUN CONFIGURATION WITHIN THE CONCRETE FLOOR. TUBING DOES NOT SHOW ON DRAWINGS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INDIAN POINT 1 (PHN) + PIPING + SENSORS, PRESSURE + WASTE STORAGE + MODIFICATION + FAILURE, INSTALLATION ERROR + ATMOSPHERE RELEASE

107904

NUCLEAR INSTRUMENTATION CHANNEL FAILS AT INDIAN POINT 1

CONSOLIDATED EDISON CO. OF NEW YORK, NEW YORK, N.Y.

2 PGS. LTR W/AS 75-12 (A) TO NRC OFFICE OF I & E, REGION 1, NOV. 7, 1975, DOCKET 50-3, TYPE--PHN, NRC--BEN, AE--CON ED

CAUSE - TIMER CIRCUITRY FAULT. DURING A COLD SHUTDOWN WITH THE PRIMARY C/JOLANT BORATED TO REFUELING CONCENTRATION, CHANNEL 2 OF THE NUCLEAR INSTRUMENTATION SYSTEM FAILED WHILE CHANNEL 1 WAS OUT OF SERVICE FOR REPAIRS. A FAULT IN THE CIRCUITRY ASSOCIATED WITH A TIMER THAT REMOVES THE AC POWER FROM ALL 4 CHANNELS AT PREDETERMINED POWER LEVEL WAS THE CAUSE. DURING THIS SHUTDOWN, THE TIMER HAS BEEN BYPASSED TO PREVENT RECURRENCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INDIAN POINT 1 (PHN) + INSTRUMENT, STARTUP RANGE + REACTOR SAFETY SYSTEM + FAILURE, COMPONENT + ELECTRIC POWER

100369

TWO FAN COOLER-CHARCOAL FILTER UNITS NOT OPERABLE AT INDIAN POINT 2

CONSOLIDATED EDISON COMPANY OF NEW YORK, INC.

1 PAGE. LTR TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, JANUARY 7, 1975, DOCKET 50-267, TYPE--PHN, NRC--WEST., AE--UNITED ENGR

CAUSE - DIRTY DEMISTERS. DURING A REVIEW OF TEST DATA, IT WAS FOUND THAT THE REACTOR HAD BEEN OPERATED FOR A DAY WITH 2 OF THE 5 FAN COOLER-CHARCOAL FILTER UNITS INOPERABLE. THEY WERE INOPERABLE BECAUSE THE DIFFERENTIAL PRESSURE ACROSS THE DEMISTER AND HEPA FILTER EXCEEDED THE 5 INCHES OF WATER LIMIT. PRESSURES WERE 7.72 AND 5.6 INCHES. AFTER CLEANING THE DEMISTERS, THE UNITS WERE RETURNED TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTAINMENT AIR COOLING + CONTAINMENT FILTERING SYSTEM + PRESSURE DROP + FAILURE, ADMINISTRATIVE CONTROL +

100569 *CONTINUED*
INDIAN POINT 2 (IPWR) * REACTOR STARTUP * FILTERS

100514
SETPOINT DRIFT IN DISTABLE UNIT AT INDIAN POINT 2
CONSOLIDATED EDISON COMPANY OF NEW YORK, INC.
1 PAGE, LETTER TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, REGION 1, MARCH 10, 1975, DOCKET 50-247, TYPE--
PWR, NRG--WEST., AE--UNITD ENGR

CAUSE - UNKNOWN. DURING A TEST OF THE LOW REACTOR COOLANT FLOW REACTOR TRIP LOGIC, 1 OF 3
DISTABLES TRIPPED AT 674, WHICH IS LESS THAN THE 908 LIMIT. THE CAUSE IS BEING INVESTIGATED.
THE REACTOR WAS IN COLD SHUTDOWN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

REACTOR SAFETY SYSTEM * FAILURE, INSTRUMENT * INSTRUMENT, SWITCH * TEST, SYSTEM OPERABILITY * INDIAN POINT 2
(IPWR) * SET POINT * DRIFT * ELECTRONIC FUNCTION UNITS * SENSORS, FLOW

100575
SETPOINT DRIFT IN FLOW SENSOR AT INDIAN POINT 2
CONSOLIDATED EDISON CO. OF N.Y.
1 PAGE, LETTER TO U.S. NRC, REGION 1, MARCH 10, 1975, DOCKET 50-247, TYPE--PWR, NRG--WEST., AE--UNITD ENGR

CAUSE - INSTRUMENT DRIFT. DURING TESTING OF THE LOW REACTOR COOLANT FLOW REACTOR TRIP LOGIC WITH
THE UNIT IN COLD SHUTDOWN, 1 OF THE 3 DISTABLE UNITS WAS FOUND WITH A SETTING OF 678 WHICH IS
BELOW THE 908 LIMIT. THE CAUSE IS UNKNOWN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

REACTOR SAFETY SYSTEM * INSTRUMENT CALIBRATION * FAILURE, INSTRUMENT * INSTRUMENT, SWITCH * TEST, SYSTEM
OPERABILITY * INDIAN POINT 2 (IPWR) * MAIN CHARGING SYSTEM * SET POINT * DRIFT * ELECTRONIC FUNCTION UNITS *
SENSORS, FLOW

100576
CHARGING LINE VALVE LEAKS TO CONTAINMENT AT INDIAN POINT 2
CONSOLIDATED EDISON CO. OF N.Y.
1 PAGE, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, MARCH 11, 1975, DOCKET 50-247, TYPE--PWR,
NRG--WEST., AE--UNITD ENGR

CAUSE - DEFECT IN VALVE BODY. DURING AN INSPECTION WITH THE REACTOR SHUTDOWN, NUCRON CRYSTALS WERE
FOUND ON AND BELOW A CHARGING LINE VALVE. THE LEAK WAS DUE TO AN APPARENT DEFECT IN THE AREA OF
THE STUD HOLES THAT PERMITTED CHARGING FLUID TO THE REACTOR COOLANT SYSTEM TO SEEP INTO 1 IN MORE
STUD HOLES AND THEN INTO THE CONTAINMENT ATMOSPHERE. ALL SIMILAR VALVES WILL BE INSPECTED FOR
LEAKAGE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

FAILURE, EQUIPMENT * REACTOR COOLANT * FLOW * INDIAN POINT 2 (IPWR) * LEAK * FREEMATER * VALVES

100923
SETPOINT DRIFT IN REACTOR COOLANT FLOW DISTABLE AT INDIAN POINT 2
CONSOLIDATED EDISON COMPANY OF N.Y., INC.
3 PAGES, LETTER WITH AG REPORT 5/2/2 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, MARCH 17, 1975, DOCKET 50-
247, TYPE--PWR, NRG--WEST., AE--UNITD ENGR

CAUSE - POWER SUPPLY BOARD MALFUNCTION. DURING A REACTOR COOLANT FLOW ANALOG CHANNEL TEST WITH
THE UNIT IN COLD SHUTDOWN, THE LOW FLOW SETTING FOR A DISTABLE WAS 678 WHICH IS BELOW THE 908
LIMIT. THE POWER SUPPLY BOARD IN THE DISTABLE HAD MALFUNCTIONED. THE REFERENCE POWER SUPPLY WAS
OPERATING AT 4.7 VOLTS INSTEAD OF THE SPECIFIED 5.2 V DC. THE POWER SUPPLY PANEL WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

FAILURE, COMPONENT * REACTOR SAFETY SYSTEM * INSTRUMENT CALIBRATION * FAILURE, INSTRUMENT * INSTRUMENT, SWITCH
* INDIAN POINT 2 (IPWR) * SET POINT * DRIFT * ELECTRONIC FUNCTION UNITS * SENSORS, FLOW

100922
CHARGING LINE VALVE LEAKS THROUGH FLAW AT INDIAN POINT 2
CONSOLIDATED EDISON COMPANY OF N.Y., INC.
3 PAGES, LETTER WITH AG REPORT 5/4/3 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, MARCH 19, 1975, DOCKET 50-
247, TYPE--PWR, NRG--WEST., AE--UNITD ENGR

CAUSE - UNKNOWN. DURING AN INVESTIGATION OF THE SOURCE OF BORON CRYSTALS ON AND BELOW A VALVE
DURING A SHUTDOWN, IT WAS DETERMINED THAT THE VALVE HAD BEEN LEAKING SLIGHTLY DUE TO AN APPARENT

102504

DEFECT IN THE OPEN OF A STEAM VALVE. THIS IS AN AIR OPERATED CONTROL VALVE IN A COOLING LINE. COOLING WATER STEPS OUT A STEAM VALVE AND THEN DROPS TO THE CONTAINMENT ATMOSPHERE. THE CAUSE OF THE DEFECT HAS NOT YET BEEN DETERMINED. THE VALVE WAS REPLACED. A DEFECT WAS REPORTED ON THE DEFECT LOG OF THE REPLACEMENT VALVE BEFORE IT WAS INSTALLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, EQUIPMENT - INDIAN POINT 2 (PWR) - LEAK - PREVENTION - VALVES

102504

COMPONENT COOLING SYSTEM VALVE FAILS TO OPEN AT INDIAN POINT 2
CONSULTANT ENGINEER COMPANY OF NEW YORK, INC.
1 PAGE, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, MARCH 26, 1975, DOCKET 50-247, TYPE--PWR, NRC--NRC, NRC--UNIT 2 PWR

CAUSE - UNKNOWN. DURING A PLANNED OUTAGE, A VALVE IN THE COMPONENT COOLING SYSTEM ON THE TUBES OF A REACTOR HEAT EXCHANGER FAILED TO OPEN ON SIGNAL. IT HAD BEEN OPERATED SEVERAL TIMES BEFORE THE OUTAGE. THE VALVE WAS NOT OVERTHROTTLED. THE INVESTIGATION OF THE CAUSE IS CONTINUING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INDIAN POINT 2 (PWR) - VALVES - COMPONENT COOLING SYSTEM - VALVE OPERATIONS - FAILURE, EQUIPMENT - SHUTDOWN COOLING SYSTEM

102507

COMPONENT COOLING SYSTEM VALVE FAILS TO OPEN AT INDIAN POINT 2
CONSULTANT ENGINEER COMPANY OF NEW YORK, INC.
1 PAGE, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, MARCH 26, 1975, DOCKET 50-247, TYPE--PWR, NRC--NRC, NRC--UNIT 2 PWR

CAUSE - WIND UP VALVE STEM. DURING A PLANNED OUTAGE, A VALVE IN THE COMPONENT COOLING SYSTEM ON THE TUBES OF A REACTOR HEAT EXCHANGER FAILED TO OPEN AFTER HAVING BEEN USED SEVERAL TIMES. A WIND UP VALVE IN THE COMPONENT COOLING SYSTEM WAS PARTIALLY STRIPPED. DIRT, DUST, AND PIECES OF STEEL WERE FOUND BETWEEN THE VALVE AND THE VALVE STEM LEAD SCREW. THE FOREIGN MATERIAL ON THE VALVE STEM CAUSED THE VALVE TO BE HEAVILY LOADED BY BOTH THE OPEN AND CLOSED DIRECTION RESULTING IN EXCESSIVE WEAR. THE WIND UP VALVE WAS REPLACED AND THE VALVE STEM CLEANED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, EQUIPMENT - LEAK - FAILURE, MAINTENANCE ERROR - INDIAN POINT 2 (PWR) - AUXILIARY COOLING - SHUTDOWN COOLING SYSTEM - VALVE OPERATIONS - VALVES

102509

CONTROL ROOM VENTILATION DAMPERS CLOSED AT INDIAN POINT 2
CONSULTANT ENGINEER COMPANY OF NEW YORK, INC.
1 PAGE, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, MARCH 26, 1975, DOCKET 50-247, TYPE--PWR, NRC--NRC, NRC--UNIT 2 PWR

CAUSE - INSTALLATION ERROR. DURING TESTING OF THE CONTROL ROOM VENTILATION SYSTEM IN AUG. 1974, IT WAS FOUND THAT THE WINDUP AIR DAMPERS IN THIS SYSTEM WERE WIRED SO THAT THEY WOULD OPEN AUTOMATICALLY ON A HIGH RADIOACTIVITY SIGNAL. ACCORDING TO THE PLAN, THE DAMPERS SHOULD CLOSE ON HIGH RADIOACTIVITY. INVESTIGATION SHOWED THIS TO BE AN INSTALLATION ERROR. THE CONTROLS WERE REWIRED PROPERLY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTROL SYSTEM - VENTILATION SYSTEM - TEST, SYSTEM OPERABILITY - INDIAN POINT 2 (PWR) - FAILURE, INSTALLATION ERROR - CONTROL PANEL/ROOM

102553

REFUELING WATER STORAGE TANK VOLUME LESS THAN LIMITS AT INDIAN POINT 2
CONSULTANT ENGINEER COMPANY OF NEW YORK, INC.
1 PAGE, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, MARCH 26, 1975, DOCKET 50-247, TYPE--PWR, NRC--NRC, NRC--UNIT 2 PWR

CAUSE - ADDITIONS TO SI ACCUMULATORS. WHEN ROUTINE SAMPLING INDICATED THAT THE BORON CONCENTRATION IN THE SAFETY INJECTION SYSTEM ACCUMULATORS WAS AT THE 2000 PPM LIMIT, A BLEED AND FILL OPERATION WAS STARTED TO INCREASE THE CONCENTRATION. SAMPLING THEN INDICATED 1910 PPM. A REACTOR SHUTDOWN WAS STARTED UNTIL THE CONCENTRATION WAS BROUGHT ABOVE THE 2000 PPM LIMIT. AFTER THIS, THE REFUELING WATER STORAGE TANK WAS REFILLED. DURING FILLING, IT WAS DETERMINED THAT THE VOLUME HAD DRIPPED BELOW THE 390,000 GALLON LIMIT BY 2200 GALLONS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

102993 - MULTIPLE
INDIAN POINT 2 (PUMP) • PUMP • CONDENSATION • PUMPED CAPACITY • STORAGE CONTAINER • PUMPED CAPACITY • PUMPED CAPACITY • PUMPED CAPACITY • PUMPED CAPACITY • PUMPED CAPACITY • PUMPED CAPACITY

103100
PNEUMATIC PRESSURE DISTANCE PAIRS AT INDIAN POINT 2
CONSOLIDATED EDISON COMPANY OF N.Y., INC.
1 PAGES, LETTER WITH ACR 5-7-71 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, JUNE 20, 1975, DCACT 50-267, TYPE--PUB, NRC--BEST, AC--UNIT ENCL

CAUSE - OPEN CAPACITY. DURING A PRESSURIZED PUMPING TEST WHILE OPERATING AT 100% POWER, A DISTANCE PAIR WAS FOUND TO HAVE FAILED AND THE SYSTEM WAS SHUT DOWN. THE CAUSE WAS AN OPEN CAPACITY. THE EXISTING PUMP SUPPLY DRAIN WHICH CONTAINED THE OPEN CAPACITY WAS REPLACED WITH A SPARE. THE DISTANCE PAIR WAS THEN SET AND TESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INDIAN POINT 2 (PUMP) • PNEUMATIC FUNCTION TESTS • PNEUMATIC PRESSURE • TEST, SYSTEM OPERABILITY • FAILURE, COMPONENT • PNEUMATIC • INSTRUMENT, SWITCH • REACTION SAFETY SYSTEM

103004
CONDENSATE STORAGE TANK LEVEL LOW AT INDIAN POINT 2
CONSOLIDATED EDISON COMPANY OF N.Y., INC.
1 PAGES, LETTER WITH ACR 75-9 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, JUNE 20, 1975, DCACT 50-267, TYPE--PUB, NRC--BEST, AC--UNIT ENCL

CAUSE - MAKEUP WATER OUT OF SPEC. WHILE THE REACTOR WAS OPERATING AT 100% POWER, LEVEL IN THE CONDENSATE STORAGE TANK DROPPED BELOW THE LIMIT OF 800,000 GALS TO 800,000. THE OUTPUT OF THE TANK EVAPORATOR, WHICH NORMALLY SUPPLIES MAKEUP, WAS REDUCED DUE TO OUT OF SPEC WATER. LEVEL WAS RETURNED TO ABOVE THE LIMIT WITHIN 60 MIN. SUFFICIENT MAKEUP WAS AVAILABLE AT A UNIT 1 TO REQUIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INDIAN POINT 2 (PUMP) • SYSTEM CAPACITY • STORAGE CONTAINER • PNEUMATIC • FAILURE, OPERATION ERROR • COMPONENT FAILURE • RECOMBINATION • EVAPORATION

103033
SIGNAL UNIT IN OVERPOWER DELTA T SUMMING AMPLIFIER AT INDIAN POINT 2
CONSOLIDATED EDISON COMPANY OF N.Y., INC.
1 PAGES, LETTER WITH ACR 75-9 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, JUNE 20, 1975, DCACT 50-267, TYPE--PUB, NRC--BEST, AC--UNIT ENCL

CAUSE - DEFECTIVE POTENTIOMETERS. DURING TESTING OF THE OVERPOWER DELTA T TEMPERATURE FROM 500 POINTS WITH THE REACTOR AT 100% POWER, LOOP 20 WAS FOUND TO BE JITTERING. A PLANTER WARNING AMPLIFIER HAS THREE 500 OHM POTENTIOMETERS WITH 500 OHM IN THE SUMMING UNIT. THE POTIS WERE REPLACED, THE UNIT RESET, AND RETURNED TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INDIAN POINT 2 (PUMP) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SENSOR, TEMPERATURE • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT • SET POINT • POINT • FAILURE, COMPONENT • REACTION SAFETY SYSTEM

103002
PUMP SEAL HEAT EXCHANGER LEAKS AT INDIAN POINT 2
CONSOLIDATED EDISON COMPANY OF N.Y., INC.
2 PAGES, LETTER WITH ACR 75-9 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, JUNE 20, 1975, DCACT 50-267, TYPE--PUB, NRC--BEST, AC--UNIT ENCL

CAUSE - PIPE JOINT LEAK. DURING OPERATION AT 100% POWER, AN INDOLENE-BAND MODEL 8423 A PUMP DEVELOPED A SLIGHT LEAK AT A SCREWED FITTING ON THE PUMP SEAL HEAT EXCHANGER. THE LEAK STOPPED AFTER THE FITTINGS WERE DISASSEMBLED AND REASSEMBLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INDIAN POINT 2 (PUMP) • PIPES AND PIPE FITTINGS • LEAK • AUTOMATIC COOLING SYSTEM • SEAL • FAILURE, INSTALLATION ERROR • HEAT EXCHANGERS

104000
CONTAINMENT SPRAY LOGIC NOT COMPLETELY TESTED AT INDIAN POINT 2
CONSOLIDATED EDISON COMPANY OF N.Y., INC.
2 PAGES, LETTER WITH ACR 75-9 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, JULY 30, 1975, DCACT 50-267, TYPE--PUB, NRC--BEST, AC--UNIT ENCL

 

105040 CONTINUED
MAINTENANCE AND REPAIR

105041
REACTOR PROTECTION LOGIC CHANNEL NOT TESTED IN SCHEDULE AT INDIAN POINT 2
CONSOLIDATED EUSON CO. OF NEW YORK, INC., N.Y.
2 PGS. LTR WFO 75-2-10101 TO NRC OFFICE OF I & E, REGION 1, SEPT. 30, 1975, DISCT 50-247, TYPE--PMR, WFO--
WEST., AC--UNIT 2 ENCL

CAUSE - EQUIPMENT ISOLATED FOR MAINTENANCE. DURING CIRCUIT PROTECTION CONNECTION FOR A SCHEDULED
JULAGE, PERIODIC SURVEILLANCE TEST OF THE REACTOR PROTECTION LOGIC WAS NOT PERFORMED AT THE
REQUIRED TIME FREQUENCY. THE CONTINGENT SPARE PUMPS WHICH ARE REQUIRED TO BE OPERABLE FOR THIS
TEST, WERE ISOLATED FOR PROTECTION OF MAINTENANCE WORKERS DURING THE JULAGE. A TECH SPEC CHANGE
WAS SUBMITTED TO AVOID THIS TYPE OF CONFLICT. THE TEST WAS COMPLETED PRIOR TO STARTUP.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

INDIAN POINT 2 (PMR) - TEST INTERVAL - PROTECTIVE SYSTEM - REACTOR SAFETY SYSTEM - FAILURE, ADMINISTRATIVE
CONTROL - MAINTENANCE AND REPAIR

093100
HEAT TRACING CIRCUIT FOUND TO BE OPEN AT INDIAN POINT 2
CONSOLIDATED EUSON CO. OF NEW YORK, INC., N.Y.
3 PGS. LTR WFO 75-2-10101 TO NRC OFFICE OF I & E, REGION 1, SEPT. 19, 1975, DISCT 50-247, TYPE--PMR, WFO--
WEST., AC--UNIT 2 ENCL

CAUSE - CONNECTION OF WIRE. DURING TESTS IN THE ELECTRICAL HEAT TRACING WITH THE REACTOR AT HOT
PUMPS, A CIRCUIT FOR SULFURIC ACID TRANSFER PUMP (1) WAS FOUND TO BE OPEN. SULFURIC ACID LEAKED FROM A
PLUGGED WASHER ON THE SECTION OF THE PUMP CAUSING THE WIRE IN THE HEAT TRACING CIRCUIT TO CORRODE
IN THE. THE WASHER WAS REPLACED AND THE WIRE REPAIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

INDIAN POINT 2 (PMR) - OVERHEAD - ELECTRICAL WIRE - PIPES AND PIPE FITTINGS - FAILURE, COMPONENT - REPAIRS AND
CORRECTIONS - OCCASION - TEST, SYSTEM OPERABILITY

100050
INCONSISTENCY IN TEST PROCEDURES FOR THE TWO UNITS FOUND AT INDIAN POINT 2
CONSOLIDATED EUSON CO. OF NEW YORK, INC., N.Y.
2 PGS. LTR WFO 75-2-10101 TO NRC OFFICE OF I & E, REGION 1, SEPT. 26, 1975, DISCT 50-247, TYPE--PMR, WFO--
WEST., AC--UNIT 2 ENCL

CAUSE - LOGIC DIAGRAM NOT UPDATED. DURING A REVIEW OF SURVEILLANCE TEST PROCEDURES FOR UNIT 2, A
DISCREPANCY BETWEEN IT AND THE COMPARABLE UNIT 1 PROCEDURE WAS IDENTIFIED. FOR UNIT 2,
SEPARATE RELAYS WERE USED FOR 0.9 MV BUS UNDERVOLTAGE PROTECTION. UNIT 1 REQUIRED TESTING A
MULTI-PURPOSE RELAY UNIT. INVESTIGATION SHOWED THE SAME SEPARATE RELAYS EXISTED FOR UNIT 2 BUT
HAD NOT BEEN TESTED AS REQUIRED. UNIT 2 PROCEDURES WERE WRITTEN USING LOGIC DIAGRAMS. A CHANGE
WAS MADE TO THE CIRCUIT. WIRING DIAGRAMS WERE REVISED BUT LOGIC DIAGRAMS WERE NOT. PROCEDURES
HAVE BEEN CORRECTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

INDIAN POINT 2 (PMR) - TEST INTERVAL - TESTING - OVERLAYS - INSTRUMENT, PROTECTIVE - ELECTRIC POWER - FAILURE,
ADMINISTRATIVE CONTROL - PROCEDURES AND METHODS

100040
TWO CHARGING PUMPS BECAME INOPERABLE AT INDIAN POINT 2
CONSOLIDATED EUSON CO. OF NEW YORK, INC., N.Y.
2 PGS. LTR WFO 75-2-10101 TO NRC OFFICE OF I & E, REGION 1, SEPT. 26, 1975, DISCT 50-247, TYPE--PMR, WFO--
WEST., AC--UNIT 2 ENCL

CAUSE - PLUNGER SEAL LEAKAGE. DURING 1200 POWER OPERATION, 2 OF THE 3 CHARGING PUMPS BECAME
INOPERABLE DUE TO EXCESSIVE PLUNGER SEAL LEAKAGE. THE AFFECTED PLUNGERS OF BOTH PUMPS WERE
REPLACED. ONE WAS RETURNED TO SERVICE WITHIN THE REQUIRED 24 HOUR PERIOD. POSSIBLE DESIGN
MODIFICATIONS ARE BEING INVESTIGATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

INDIAN POINT 2 (PMR) - PUMPS - LEAK - FAILURE, EQUIPMENT - FAILURE, DESIGN ERROR - FAILURE, SIMULTANEOUS -
SEAL - PRESSURIZER

100047
TWO CHARGING PUMPS BECAME INOPERABLE AT INDIAN POINT 2

100007 PLANTAGEUR
CONSOLIDATED EDISON CO. OF NEW YORK, INC., N.Y.
2 PGS. LTR W/BU 75-2-201 TO NRC OFFICE OF I & E, REGION 1, SEPT. 20, 1975, DOCKET 50-247, TYPE--PWR, NRC--
BEST.. AE--UNITED ENGR

CAUSE - EXCESSIVE SEAL LEAKAGE. WHILE OPERATING AT 72% POWER, 2 OF THE 3 CHARGING PUMPS BECAME INOPERABLE DUE TO EXCESSIVE PLUNGER SEAL LEAKAGE. AFFECTED PLUNGERS OF BOTH PUMPS WERE REPAIRED OR REPLACED. POSSIBLE DESIGN MODIFICATIONS ARE BEING INVESTIGATED. THE CHARGING PUMPS WERE OPERABLE WITHIN 24 HOURS, AS REQUIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INDIAN POINT 2 (PWR) * PUMPS * PLUNGERS * SEAL * LEAK * FAILURE, EQUIPMENT * FAILURE, DESIGN ERROR * FAILURE, SIMILARITIES

100532
Boric Acid Transfer Pump Fails at Indian Point 2
CONSOLIDATED EDISON CO. OF NEW YORK, INC., N.Y.
2 PGS. LTR W/BU 75-2-201 TO NRC OFFICE OF I & E, REGION 1, OCT. 3, 1975, DOCKET 50-247, TYPE--PWR, NRC--
BEST.. AE--UNITED ENGR

CAUSE - LEAKING PUMP SEAL. WHILE OPERATING AT 70% POWER, BORIC ACID TRANSFER PUMP 21 WAS REMOVED FROM SERVICE TO REPAIR A LEAKING PUMP SEAL. THE JOHN CRANE, TYPE 1, BELLOWS SHAFT SEAL LONG PSP 10063-21 WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INDIAN POINT 2 (PWR) * SEAL * LEAK * PUMPS * CHEMICAL SPIN * FAILURE, EQUIPMENT

100902
Fan Cooler Unit Breaker Found Sticking at Indian Point 2
CONSOLIDATED EDISON CO. OF NEW YORK, INC., N.Y.
2 PGS. LTR W/BU 75-2-201 TO NRC OFFICE OF I & E, REGION 1, OCT. 10, 1975, DOCKET 50-247, TYPE--PWR, NRC--
BEST.. AE--UNITED ENGR

CAUSE - FAILED CLOSING COIL. WHILE OPERATING AT 60% POWER, A SMOKE DETECTOR INITIATED AN ALARM IN CCM. SMOKE WAS OBSERVED COMING FROM A FAN COOLER UNIT BREAKER COMPARTMENT. THE FAN WAS SHUT DOWN. THE CLOSING COIL WAS FAILED. IT WAS REPLACED. NO CAUSE FOR FAILURE WAS FOUND.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INDIAN POINT 2 (PWR) * PUMPS * PLUNGERS * CONTAINMENT AIR COOLING * FAILURE, COMPONENT * SMOKE

107704
Pressure Drop Across Fan Cooler Filters Exceed Limit at Indian Point 2
CONSOLIDATED EDISON CO. OF NEW YORK, INC., N.Y.
2 PGS. LTR W/BU 75-2-201 TO NRC OFFICE OF I & E, REGION 1, NOV. 6, 1975, DOCKET 50-247, TYPE--PWR, NRC--
BEST.. AE--UNITED ENGR

CAUSE - JEST ACCUMULATION. DURING TESTING WHILE THE REACTOR WAS SHUT DOWN, PRESSURE DROP ACROSS THE DEMISTERS AND PAPA FILTER FOR EACH OF 2 FAN COOLER UNITS EXCEEDED THE 5 INCHES OF WATER LIMIT. AS FAN COOLER PRESSURE DROPS WERE 9.2 INCHES AND 9.7 INCHES. THIS RESULTED FROM JEST ACCUMULATION IN THE DEMISTERS. THE DEMISTERS WERE WASHED. PRESSURE DROPS WERE REDUCED TO BELOW LIMITS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INDIAN POINT 2 (PWR) * PRESSURE DROP * FILTERS * FILTER, HIGH EFFICIENCY * CONTAINMENT AIR COOLING * TEST, SYSTEM OPERABILITY * TEST, FILTER * CRUD

107901
Boric Acid Transfer Pump Removed from Service at Indian Point 2
CONSOLIDATED EDISON CO. OF NEW YORK, INC., N.Y.
2 PGS. LTR W/BU 75-2-201 TO NRC OFFICE OF I & E, REGION 1, NOV. 12, 1975, DOCKET 50-247, TYPE--PWR, NRC--
BEST.. AE--UNITED ENGR

CAUSE - LEAKING PUMP SEAL. WHILE THE REACTOR WAS OPERATING AT 100% POWER, BORIC ACID TRANSFER PUMP 22 WAS REMOVED FROM SERVICE TO REPAIR A LEAKING PUMP SEAL. THE JOHN CRANE, TYPE 1, BELLOWS SHAFT SEAL WAS REPLACED. THE PUMP WAS RETURNED TO SERVICE WITHIN 24 HOURS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INDIAN POINT 2 (PWR) * SEAL * PUMPS * POISON, SOLUBLE * CHEMICAL SPIN * FAILURE, EQUIPMENT

100990

Two charging pumps become inoperable at Indian Point 2
 Consolidated Edison Co. of New York, New York, N.Y.
 2 Pgs. Ltr WAB-75-2-25 to NRC Office of I & E, Region 1, DEC. 5, 1975, JACKET 50-247, TYPE--PUR, NRC--
 WEST., AE--UNIT 2 ENCL

CAUSE - GASKET AND SEAL LEAKAGE. DURING NORMAL OPERATION AT STE POWER, 2 QUENTRON TYPE 30-300 VARIABLE SPEED POSITIVE DISPLACEMENT 30 GPM CHARGING PUMPS BECAME INOPERABLE DUE TO A LEAKING HEAD GASKET ON PUMP 23 AND EXCESSIVE PLUNGER SEAL LEAKAGE ON PUMP 22. THE HEAD GASKET AND THE PLUNGER WERE REPLACED. BOTH PUMPS WERE OPERABLE WITHIN 24 HOURS. POSSIBLE DESIGN MODIFICATIONS ARE BEING INVESTIGATED.

AVAILABILITY - NRC PUBLIC DOCUMENT NUM. 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INDIAN POINT 2 (PWR) • SEAL • PUMPS • FREQUATOR • MAIN COOLING SYSTEM • LEAK • FAILURE, EQUIPMENT

100991

URIC CONCENTRATION IN STORAGE TANKS BELOW LIMIT AT INDIAN POINT 2
 Consolidated Edison Co. of New York, NY
 3 Pgs. Ltr WAB-75-2-201 to NRC Office of I & E, Region 1, DEC. 12, 1975, JACKET 50-247, TYPE--PUR, NRC--
 WEST., AE--UNIT 2 ENCL

CAUSE - OPERATOR ERROR. WHILE OPERATING AT ONE POWER, URIC ACID PROCESSED IN THE EVAPORATOR WAS TRANSFERRED TO THE URIC ACID STORAGE TANK. SAMPLES TAKEN AFTER THE TRANSFER INDICATED THAT THE CONCENTRATION IN BOTH TANKS WAS 11.28, WHICH IS LESS THAN THE 11.58 LIMIT. A CORRELATED SHUTDOWN WAS INITIATED UNTIL A NEW BATCH WAS PREPARED TO INCREASE THE CONCENTRATION ABOVE THE LIMIT. THE CAUSE WAS EITHER INACCURACIES IN SAMPLING BEFORE THE TRANSFER OR USE OF EXCESSIVE WATER IN FLUSHING THE LINE FOLLOWING THE TRANSFER. THE TANKS WILL BE SEPARATED DURING BATCHING TO PREVENT AFFECTING BOTH TANKS.

AVAILABILITY - NRC PUBLIC DOCUMENT NUM. 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INDIAN POINT 2 (PWR) • CONCENTRATION • CHEMICAL UNIT • POISON, SOURCE • STORAGE CONTAINER • FAILURE, OPERATION ERROR

100990

CHARGING PUMP BECOMES INOPERABLE AT INDIAN POINT 2
 Consolidated Edison Co. of New York, New York, NY
 2 Pgs. Ltr WAB-75-2-210 to NRC Office of I & E, Region 1, DEC. 11, 1975, JACKET 50-247, TYPE--PUR, NRC--
 WEST., AE--UNIT 2 ENCL

CAUSE - CYLINDER HEAD GASKET LEAK. WHILE THE UNIT WAS OPERATING AT ONE POWER WITH CHARGING PUMP 23 INOPERABLE, A LEAK DEVELOPED AT HIGH PRESSURE HEAD CYLINDER 2 GASKET OF PUMP 21. THE QUENTRON TYPE 60-300 VARIABLE SPEED POSITIVE DISPLACEMENT 30 GPM PUMP HEAD GASKET WAS REPLACED AND THE PUMP RETURNED TO SERVICE WITHIN THE 24 HOUR TIME LIMIT. A DESIGN MODIFICATION IS BEING INVESTIGATED.

AVAILABILITY - NRC PUBLIC DOCUMENT NUM. 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INDIAN POINT 2 (PWR) • SEAL • PUMPS • FREQUATOR • MAIN COOLING SYSTEM • LEAK • FAILURE, EQUIPMENT

102582

FUEL TRANSFER APPARATUS AND HANDLING TOOL DAMAGED AT INDIAN POINT 3
 Consolidated Edison Co. of New York, Inc.
 1 PAGE, LETTER TO NRC DIR. OF REGULATORY OPERATIONS, REGION 1, APRIL 28, 1975, JACKET 50-206, TYPE--PUR, NRC--
 WEST., AE--UNIT 2 ENCL

CAUSE - LAMP MALFUNCTION. DURING PRE-OPERATIONAL TESTING OF THE FUEL HANDLING EQUIPMENT, THE CRANE USED TO REMOVE AND RELOCATE FUEL ELEMENTS SUSSTAINED MECHANISM MALFUNCTIONS WHICH LED TO DAMAGE TO THE FUEL-HANDLING EQUIPMENT. THE CAUSE OF THE INCIDENT IS BEING INVESTIGATED. DAMAGE WAS ONLY REPAIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT NUM. 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INDIAN POINT 3 (PWR) • CONSTRUCTION • FUEL HANDLING MACHINE • CRANE • FAILURE, EQUIPMENT • TEST, PREOPERATIONAL • TEST, SYSTEM OPERABILITY • DAMAGE

103044

ONE PENETRANT INDICATIONS IN STEAM GENERATOR CLADDING AT INDIAN POINT 3
 Consolidated Edison Company of N.Y., Inc.
 1 PAGE, LETTER TO NRC DIR. OF REGULATORY OPERATIONS, REGION 1, MAY 5, 1975, JACKET 50-206, TYPE--PUR, NRC--
 WEST., AE--UNIT 2 ENCL

CAUSE - WELD DEFECTS. DURING WARE CLEANING OF STEAM GENERATOR 36 WATER BOXES, A DISCOLORATION WAS

144400 02 25112100

As shown in the drawings, the pressure tests resulted in negative indications between weld
corrosion areas. No detectable indications were also found in steam generation 32. These indications
are being analyzed and removed. Necessary repairs will be made.

Approved For Release by NSA on 08-25-2013 pursuant to E.O. 13526

1. INITIAL PLANT DESIGN • CONSTRUCTION • OPERATION • PLANT • STEAM GENERATION • FAILURE • CLADDING • FAILURE.
FACILITIES DATA

1-4524

ALL ADVERTISING PRICES ARE IN U.S. DOLLARS. ADVERTISING PRICES ARE IN U.S. DOLLARS.

U.S. DEPARTMENT OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D. C. 20535

7-255, 11th, WPAFB IL HMC OFFICE CO B & C, NEWTON, N. CAR. 21, 1975. DUCKER 5G-286. TYPE--PUB. #G--4431. AC-
15114-134

LAUNCH - IMMEDIATELY INSTALLED CHECK VALVES. WHEN AN ATTEMPT WAS MADE TO START DIESEL GENERATOR 32 FOR A TEST, THE SPINNING OF THE PUMPS WOULD STOP. THE TEST WAS IMMEDIATELY TERMINATED. CHECK VALVES HAD BEEN INSTALLED UNDER THE MANUFACTURER'S INSTRUCTIONS TO PREVENT OIL FROM LEAKING BACK INTO THE TURBOMACHINE WHEN THE PULSING PUMP IS RUNNING. THE CHECK VALVES HAD BEEN IMPROPERLY INSTALLED IN THE OIL DRAIN LINE RATHER THAN THE SUPPLY LINE. A SECOND REPRESENTATIVE FROM THE OWNER HAS MADE THE VALVE INSTALLED PROPERLY. NO DAMAGE OCCURRED. THE TEST WAS THEN SUCCESSFUL.

AVAILABILITY - THE PUBLIC ACCOUNT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
FEE \$1.00

IGNITION POINT • IGNITION • COMBUSTION • OPERATOR, DIESEL • LOGGING, INTERNAL COMBUSTION • FAILURE, ADMINISTRATION • AIR • VALVE, CYCLE • INSTALLATION • HYDRAULIC SYSTEM • RES. SYSTEM, OPERABILITY

שלום

STEAD GENERATION REQUIRES SAMPLE VALVE FAILS TO CLOSE AT REMOVAL

ALUMINUM PUBLIC SERVICE CORPORATION

3 PAGE, LETTER WITH AN REPORT 75/2 TO DIRECTORATE OF LICENSING (AECL), JANUARY 21, 1975, DOCKET 57-305, TYPE--
PUB, WSG--WST, AT--PILGRIM SPR.

CAUSE - STEERING VALVE WAS STICKING, DURING TESTING OF THE RADIATION MONITORING SYSTEM WITH THE RESULT OF F.B. NUMBER. THE ISOLATE STEAM GENERATOR IN MONITORING SAMPLE VALVE FAILED TO CLOSE. THE STEERING VALVE WHICH VENTS THE AIR FROM THE SAMPLE VALVE WAS STICKING. WHEN THE SOLENOID WAS TAPPED WITH A SCREWDRIVER, IT OPERATED PROPERLY. NO CAUSE F.B. STICKING WAS FOUND.

AVAILABILITY - NRC PUBLIC JUDGMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545. 100 CENTS/PAGE -- MINIMUM
FEE \$5.00

FAILURE COMPONENTS • SAMPLING • TEST SYSTEM OPERABILITY • COOLANT PURIFICATION SYSTEM • STEAM GENERATOR •
MANAGEMENT (PWR) • SUB-COOLING • VALVES

091221

Inspection of all lines in California, line with piping at resource

DISCIPLIN PUBLIC SERVICE CORPORATION

* PHOTOS. LETTER WITH AD REPORT 75/3 TO NAC DIRECTORATE OF LICENSING, JANUARY 27, 1975. OJCRET 50-305. TYPE--
PUB. OFFICIALS OF PLANNED SERV.

LAUSE - VIBRATION. WHILE OPERATING AT 750 POUNDS A CRACK DEVELOPED IN THE 3/4 INCH PIPE TO WEST VALVE ADJACENT TO THE CONNECTION TO THE 2 INCH CHARGING LINE. THE CRACK WAS 1/4 INCH LONG AT THE EXTERIOR SURFACE. THE LEAK WAS VERY SMALL. THIS PIPE HAD DEVELOPED A LEAK BEFORE. AT THAT TIME, THE STUB LENGTH WAS REDUCED FROM 12 TO 3 INCHES SINCE FATIGUE WAS ASSIGNED TO BE THE CAUSE OF FAILURE. THE PIPE STUB WAS REDUCED TO THE MINIMUM LENGTH WHICH WOULD ALLOW PROPER WELDING, ABOUT 3/4 INCH. PIPE WALL THICKNESS WAS INCREASED BY WELDING. A PULSATION DAMPERER BEHIND THE POSITIVE DISPLACEMENT PUMP IS BEING STUDIED.

AVAILABILITY - THE PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, PIPE • WELDS • FAILURE, FATIGUE • FAILURE, DESIGN ERROR • VIBRATION • LEAK • KENAUKEE (PWA) • FREQUATOR • PIPES AND PIPE FITTINGS

491018

AUGILARY PROJECTION PUMP FALLS TO START AT KEMUNGER

DISCERNING PUBLIC SERVICE CORPORATION

2 PAGES, LETTER WITH NO REPORT 7576 TO DIRECTORATE OF LICENSING, FEBRUARY 3, 1975, DOCKET 90-305, TYPE--PWR.
WFO--ALB. AL--PIONEER SERV.

CASE - BREAKER OUT OF ADJUSTMENT. AUXILIARY FEEDWATER PUMP IS FAILED TO START FOLLOWING A REACTOR TRIP. THE REACTOR PUMPS STARTED. THE 4160 V BREAKER OPERATING HANDLE DID NOT CONTACT THE CLOSE PERMISSIVE SWITCH. EITHER THE HANDLE WAS BUMPED FOLLOWING THE OPERATIONAL START SPIN BREAKER INSTALLATION OR IT WAS VIBRATED OUT OF ITS POSITION. THE HANDLE WAS POSITIONED PROPERLY. THIS HAZARD HAD BEEN INSTALLED RECENTLY AND TESTED AT THAT TIME.

093019 CONTINUED
 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 134 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, EQUIPMENT + FAILURE, MAINTENANCE ERROR + REMANUEE (PWR) + BREAKER + FEEDWATER + PUMPS

100619
 AUXILIARY FEEDWATER PUMP FAILS TO START AT REMANUEE
 WISCONSIN PUBLIC SERVICE CORP.
 3 PAGES. LETTER WITH NO REPORT 7/5/75 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, MARCH 7, 1975. JACKET 50-325. TYPE--PWR, REG--WEST., AC--PIONEER SERV.

CAUSE - DESIGN DEFICIENCY. AUXILIARY FEEDWATER PUMP LA FAILED TO START ON A LOW-LO SO LEVEL SIGNAL FOLLOWING A MANUAL TRIP. A SPARE 6102V BREAKER HAD BEEN INSTALLED EARLIER. THE OPERATOR POSITION METER IN THE BREAKER GUIDE ARM WAS NOT DEEP ENOUGH TO ALLOW THE INTERLOCK SWITCH TO ACTUATE PROPERLY WITH THE SPARE BREAKER IN THE OPERATING POSITION. SIGNAL DIFFERENCES BETWEEN THE NORMAL AND SPARE BREAKERS PREVENTED PROPER OPERATION. THE NOTCH DEPTH WAS INCREASED ABOUT 1/16 INCH TO PERMIT PROPER OPERATION. THIS MODIFICATION WAS APPROVED BY THE VENDOR.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 130 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, EQUIPMENT + MODIFICATION + FAILURE, DESIGN ERROR + REMANUEE (PWR) + BREAKER + FEEDWATER + PUMPS

100807
 UNAUTHORIZED RELEASE OF NON-RADIOLOGICAL WASTE AT REMANUEE
 WISCONSIN PUBLIC SERVICE CORP.
 2 PAGES. LETTER TO NRC DIRECTORATE OF LICENSING, MARCH 16, 1975. JACKET 50-325. TYPE--PWR, REG--WEST., AC--PIONEER SERV.

CAUSE - TANK OVERFILLING. DURING REGENERATION OF A DEMINERALIZER, THE WASTE NEUTRALIZING TANK OVERFLOWS TO A FILLER CHAIN WHICH DRAINS TO THE COOLING WATER DISCHARGE LINE. THE TANK WAS SAMPLED, FOUND TO BE WITHIN DISCHARGE LIMITS, AND THEN DISCHARGED NORMALLY. THE OPERATOR FAILED TO DETERMINE THAT ADEQUATE STORAGE VOLUME WAS AVAILABLE PRIOR TO INITIATION OF DEMINERALIZER REGENERATION AND TO ADEQUATELY POSITION TANK LEVEL DURING THE REGENERATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 130 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATOR ERROR + WASTE DISPOSAL + WASTE HANDLING + WASTE DISPOSAL, LIQUID + RADIOACTIVITY RELEASE + REMANUEE (PWR)

102114
 CONDENSER TEMPERATURE NOT RECORDED ON TIME DURING LOAD CHANGE AT REMANUEE
 WISCONSIN PUBLIC SERVICE CORP.
 2 PAGES. LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, APRIL 10, 1975. JACKET 50-325. TYPE--PWR, REG--WEST., AC--PIONEER SERV.

CAUSE - OPERATOR OVERSIGHT. WHILE REDUCING THE LOAD FROM 39% POWER TO TAKE THE UNIT OFF THE LINE FOR MAINTENANCE, THE TRENDS TYPEWRITER WAS RECORDING CONDENSER INTAKE AND DISCHARGE TEMPERATURES TO BE RECORDED EVERY 15 MINUTES DURING A POWER DECREASE OF 25% OR GREATER. THE OPERATOR FAILED TO RESET THE TRENDS TYPEWRITER. THE PROCEDURE REQUIRING THIS WAS NOT REFERENCED. EVALUATION OF THE READINGS TAKEN INDICATE THAT THE ALLOWABLE 0.5 FPM CHANGE DURING A POWER DECREASE WAS NOT EXCEEDED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 130 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATOR ERROR + PROCEDURES AND MANUALS + TEST INTERVAL + REMANUEE (PWR) + DATA COLLECTION + THERMAL TRANSIENT + TEMPERATURE + CONDENSER COOLING SYSTEM

102009
 SAFETY INJECTION SYSTEM RELAY FAILS TO LATCH AT REMANUEE
 WISCONSIN PUBLIC SERVICE CORP.
 1 PAGE. LETTER TO NRC DIRECTORATE OF LICENSING, APRIL 23, 1975. JACKET 50-325. TYPE--PWR, REG--WEST., AC--PIONEER SERV.

CAUSE - OUT OF ADJUSTMENT. DURING A TEST, A SAFETY INJECTION SYSTEM DID NOT LATCH IN THE ENERGIZED POSITION. IF AN ACTUAL ACTUATION SIGNAL HAD OCCURRED, THE RELAY WOULD HAVE REMAINED ENERGIZED AS LONG AS THE SIGNAL EXISTED. THE MECHANICAL LATCH WAS ADJUSTED AND TESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM CHARGE \$2.00

REMANUEE (PWR) + DELAYS + SAFETY INJECTION + TEST, SYSTEM OPERABILITY + FAILURE, COMPONENT + FAILURE, MAINTENANCE ERROR

10090
SAFETY INJECTION VALVE TRIP ON OVERCURRENT AT REMANUEE
DISCOUNT PUBLIC SERVICE CORP.
2 PAGES, LETTER WITH REG 75-10 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, MAY 20, 1975, DOCKET 50-305, TYPE--PWR, NPS--
BEST, AT-PLENER SERVICE

CAUSE - UNKNOWN. WHEN A VALVE WAS CLOSED FOLLOWING COMPLETION OF SAFETY INJECTION SYSTEM TESTING,
THE MOTOR SUPPLY CABLED TRIPPED ON OVERCURRENT AFTER IT WAS PROVIDED TO THE FULLY CLOSED
POSITION. THE INVESTIGATION OF THE CAUSE HAS NOT BEEN COMPLETED.

AVAILABILITY - NRC PUBLIC DOCUMENT NUMBER 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

REMANUEE (PWR) • VALVES • SAFETY INJECTION • TEST, SYSTEM VERIFIABILITY • FAILURE, COMPONENT • BREAKER • VALVE
OPERATIONS

10091
WASTE NEUTRALIZING TANK DISCHARGE ON LOW AT REMANUEE
DISCOUNT PUBLIC SERVICE CORP.
2 PAGES, LETTER WITH REG 75-10 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, MAY 20, 1975, DOCKET 50-305, TYPE--PWR, NPS--
BEST, AT-PLENER SERVICE

CAUSE - ACID TANK OVERFILLED. A DISCHARGE IN THE WASTE NEUTRALIZING TANK WAS INITIATED FOLLOWING
OPERATIONS THAT TECH SPECS WERE SATISFIED. THE SULFURIC ACID JOY TANK WAS BEING FILLED AT THE
SAME TIME. THE ACID TANK OVERFILLED INTO THE WASTE NEUTRALIZING TANK DUE TO CORROSION OF THE
LEVEL MONITORING SYSTEM WHICH SHOULD HAVE TRIPPED THE ACID TRANSFER PUMP. THE MINIMUM PH IN THE
EFFLUENT WAS 1.00. THE DISCHARGE OF THE OVERFLOW LINE FOR THE ACID JOY TANK WILL CHANGE FROM THE
WASTE NEUTRALIZING TANK TO THE ACID STORAGE TANK TO PREVENT REOCCURENCE.

AVAILABILITY - NRC PUBLIC DOCUMENT NUMBER 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

REMANUEE (PWR) • EFFLUENT • WASTE DISPOSAL • WASTE DISPOSAL, LIQUID • FAILURE, COMPONENT • INSTRUMENT, SWITCH
• ACID • SULFURIC ACID • FAILURE, DESIGN ERROR • DESIGN, LEVEL

10092
SAFETY INJECTION VALVE FAILS TO OPEN AT REMANUEE
DISCOUNT PUBLIC SERVICE CORP.
2 PAGES, LETTER WITH REG 75-10 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, MAY 20, 1975, DOCKET 50-305, TYPE--
PWR, NPS--BEST, AT-PLENER SERVICE

CAUSE - THERMAL OVERLOADS TRIPPING. DURING AN INVESTIGATION OF THE FAILURE OF A PARALLEL VALVE,
VALVE JAMMER FAILED TO OPEN FROM A PARALLEL CONTROL SWITCH SIGNAL. THE DRIVE CURRENT AND THERMAL
SHUT OFF SETTINGS WERE CHECKED AND FOUND TO BE NORMAL. THE DRIVE MOTOR THERMAL OVERLOADS HAD
TRIPPED. THE INVESTIGATION IS CONTINUING.

AVAILABILITY - NRC PUBLIC DOCUMENT NUMBER 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

REMANUEE (PWR) • VALVES • SAFETY INJECTION • TEST, SYSTEM VERIFIABILITY • FAILURE, COMPONENT • INSTRUMENT,
PROTECTIVE • VALVE OPERATIONS

10093
COIL IN AUXILIARY FEEDWATER PUMP CONTROL CIRCUIT FAILS AT REMANUEE
DISCOUNT PUBLIC SERVICE CORPORATION
2 PAGES, LETTER WITH REG 75-10 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, MAY 23, 1975, DOCKET 50-305, TYPE--
PWR, NPS--BEST, AT-PLENER SERVICE

CAUSE - INCORRECT VOLTAGE RATING. A BURNED OUT COIL WAS DISCOVERED ON AUXILIARY FEEDWATER PUMP 10
CONTROL CIRCUIT. THE COIL WAS BEING CHECKED FOR CORRECT COIL STYLE AT THE REQUEST OF THE
MANUFACTURER. THE COIL VOLTAGE RATING WAS INCORRECT FOR THE RELAY. A COIL WITH THE CORRECT
RATING WAS INSTALLED. ALL SIMILAR RELAYS ARE BEING VERIFIED TO BE OF PROPER RATING. THE REACTOR
WAS SHUT DOWN AT THE TIME.

AVAILABILITY - NRC PUBLIC DOCUMENT NUMBER 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

REMANUEE (PWR) • CONTROL SYSTEM • FEEDWATER • FAILURE, COMPONENT • FAILURE, FABRICATION ERROR • RELAYS •
PUMP

10094
SAFETY INJECTION VALVE TRIPS ON OVERCURRENT AT REMANUEE
DISCOUNT PUBLIC SERVICE CORP.
2 PAGES, LETTER WITH REG 75-10 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, MAY 23, 1975, DOCKET 50-305, TYPE--
PWR, NPS--BEST, AT-PLENER SERVICE

CAUSE - UNKNOWN. WHILE THE REACTOR WAS OPERATING AT 900 PWR, A SAFETY INJECTION VALVE TRIPPED
ON CLOSING FOLLOWING COMPLETION OF A TEST. PRIOR TO TRIPPING, THE VALVE COMPLETED ITS SAFETY

103111 *CONTINUED*

RELATED OPERATION. MONITORING EQUIPMENT INSTALLED PRIOR TO THE TEST VERIFIED THAT THE CAUSE WAS NOT ELECTRICAL. THE BELLVILLE SPRING ASSEMBLY IS SUSPECTED AS THE CAUSE SINCE THE MOHM SHAFT HAS LIMITED MOVEMENT DURING VALVE TIGHTENING. THERE HAVE BEEN 3 OTHER SIMILAR OCCURRENCES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

KEWAUNEE (PWR) * VALVES * SAFETY INJECTION * TEST, SYSTEM OPERABILITY * FAILURE, EQUIPMENT * VALVE OPERATORS

103663

CONTAINMENT SUMP ISOLATION VALVES NOT TESTED AT KEWAUNEE
WISCONSIN PUBLIC SERVICE CORP.

1 PAGE, LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JUNE 13, 1975, DOCKET 50-305, TYPE--PWR, WFG--WEST, AE--PIONEER SERVICE

CAUSE - PROCEDURAL DEFICIENCY. IT WAS DISCOVERED THAT 4 CONTAINMENT SUMP ISOLATION VALVES WERE NOT INCLUDED IN THE SCHEDULED SURVEILLANCE TEST PROGRAM AND THEREBY NOT BEING TESTED IN ACCORDANCE WITH TECH SPECS. TEMPORARY TEST PROCEDURES WERE WRITTEN AND VALVE OPERABILITY VERIFIED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

KEWAUNEE (PWR) * TESTING * VALVES * CONTAINMENT SUMP * FAILURE, ADMINISTRATIVE CONTROL * PROCEDURES AND MANUALS

103695

AIR-OPERATED ISOLATION VALVES FAIL TO CLOSE AT KEWAUNEE
WISCONSIN PUBLIC SERVICE CORP.

3 PAGES, LETTER WITH AOR 75-11 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JUNE 25, 1975, DOCKET 50-305, TYPE--PWR, WFG--WEST, AE--PIONEER SERVICE

CAUSE - BORIC ACID CRYSTAL BUILDUP. A REVIEW OF THE SHIFT SUPERVISOR'S LOG REVEALED THAT DURING TESTING OF ASCO SOLENOID VALVES 5 DAYS EARLIER, 2 1-INCH AIR-OPERATED ISOLATION VALVES FAILED TO CLOSE COMPLETELY. BOTH WERE ON SAMPLE LINES, ONE FOR PRESSURIZER LIQUID AND THE OTHER FOR COOLANT HOT LEG. A BUILDUP OF BORIC ACID CRYSTALS HAD FORMED ON THE VALVE STEM EXTERNAL TO THE VALVE BODY FROM GRAVURAL LEAKS THROUGH THE LAMINATED PACKING DURING PROLONGED DISUSE. THE VALVE STEMS WERE CLEANED AND POLISHED. THE VALVES WERE THEN TESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

KEWAUNEE (PWR) * VALVES * CONTAINMENT ISOLATION * SAMPLING * TEST, SYSTEM OPERABILITY * SEAL * LEAK * CRUD * FAILURE, EQUIPMENT * FAILURE, MAINTENANCE ERROR

104072

CALIBRATION SHIFT OF BORIC ACID TANK LEVEL INSTRUMENTS AT KEWAUNEE
WISCONSIN PUBLIC SERVICE CORP.

3 PAGES, LETTER WITH AOR 75-12 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JULY 7, 1975, DOCKET 50-305, TYPE--PWR, WFG--WEST, AE--PIONEER SERVICE

CAUSE - TEMPERATURE EFFECT. WHILE OPERATING AT 90% POWER, BORIC ACID TANK 1A WAS DRAINED COMPLETELY TO REPAIR A LEAK ON A VALVE THAT IS UNISOLABLE FROM THE TANK. THE TANK LOW LEVEL ALARM DID NOT ACTUATE AND ALL 4 LEVEL INSTRUMENTS INDICATED A LEVEL GREATER THAN 48. THE INSTRUMENTS ARE NORMALLY CALIBRATED WITH COLD FLUID. WHEN PLACED IN SERVICE WITH 145-165 F FLUID, A CALIBRATION SHIFT OCCURS. PRESENT PLANS ARE TO EITHER MODIFY THE EXISTING INSTRUMENTS OR PURCHASE NEW ONES PROPERLY CALIBRATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

KEWAUNEE (PWR) * INSTRUMENT CALIBRATION * SENSORS, LEVEL * EFFECT * TEMPERATURE * FAILURE, DESIGN ERROR * CHEMICAL SHIM * POISON, SOLUBLE * STORAGE CONTAINER

104071

STEAM GENERATOR BLOWDOWN LINE ISOLATION VALVE FAILED TO CLOSE AT KEWAUNEE
WISCONSIN PUBLIC SERVICE CORP.

2 PAGES, LETTER WITH AOR 75-13 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JULY 7, 1975, DOCKET 50-305, TYPE--PWR, WFG--WEST, AE--PIONEER SERVICE

CAUSE - IMPROPER TORQUE SWITCH SETTING. WITH THE REACTOR AT 92% POWER, A STEAM GENERATOR BLOWDOWN LINE CONTAINMENT ISOLATION VALVE FAILED TO CLOSE ON SIGNAL. THE REDUNDANT VALVE CLOSED SATISFACTORILY. THE MOTOR OPERATOR TORQUE SWITCH SETTING WAS IMPROPER. IT WAS RESET TO THE PROPER VALUE. THE VALVE OPERATED PROPERLY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

100071 *CONTINUOUS*
 VALVES • CONTAINMENT ISOLATION • STEAM GENERATOR • COOLANT PURIFICATION SYSTEM • INSTRUMENT, SWITCH • SET
 POINT • FAILURE, MAINTENANCE ERROR • REPAIRS (PMI) • FAILURE, INSTRUMENT

100072
 CONTAINMENT COOLING SERVICE WATER VALVE FAILS TO OPEN AT KEWAUNEE
 WISCONSIN PUBLIC SERVICE CORP., GREEN BAY
 3 PGS, LTR W/AD 75-10-14 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, AUG. 20, 1975, DOCKET 50-305, TYPE--
 PWR, NRG--WEST., AE--PIONEER SERVICE

CAUSE - TORQUE SWITCH SET IMPROPERLY. WHILE THE REACTOR WAS OPERATING AT 99% POWER, CONTAINMENT
 FAN COIL UNIT IN OUTLET SERVICE WATER VALVE FAILED TO OPEN ON SIGNAL. THE MOTOR OPERATOR THERMAL
 OVERHEAT DEVICES WERE TRIPPED DUE TO IMPROPER TORQUE SWITCH SETTING EXISTING DURING THE PREVIOUS
 VALVE CLOSE. THE TORQUE SWITCH SETTING WAS REDUCED AND THE VALVE TESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

KEWAUNEE (PMI) • VALVES • CONTAINMENT AIR COOLING • AUXILIARY COOLING • FAILURE, MAINTENANCE ERROR •
 INSTRUMENT, SWITCH • SET POINT • VALVE OPERATORS

100379
 COMPONENTS OF TWO SAFEGUARD TRAINS OUT OF SERVICE CONCURRENTLY AT KEWAUNEE
 WISCONSIN PUBLIC SERVICE CORP., WIS.
 2 PGS, LTR W/AD 75-15 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, SEPT. 5, 1975, DOCKET 50-305, TYPE--PWR,
 NRG--WEST., AE--PIONEER SERV.

CAUSE - PERSONNEL ERROR. A MANAGEMENT REVIEW OF THE SHIFT SUPERVISOR'S LOG REVEALED THAT DIESEL
 GENERATOR IN WAS TAKEN OUT OF SERVICE CONCURRENTLY WITH THE OUTAGE OF SAFEGUARDS TRAIN A SPECIAL
 VENTILATION ZONE FAN. SPECIAL VENTILATION ZONE FAN IN SAFEGUARDS TRAIN B WAS THEN TESTED.
 OPERATING PERSONNEL HAD FAILED TO RECOGNIZE THAT A SAFEGUARDS TRAIN A COMPONENT WAS OUT OF
 SERVICE PRIOR TO PLACING THE SAFEGUARDS TRAIN B EMERGENCY POWER SUPPLY OUT OF SERVICE. THE
 REACTOR WAS AT 99% POWER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

KEWAUNEE (PMI) • REDUNDANCE • MAINTENANCE AND REPAIR • FAILURE, ADMINISTRATIVE CONTROL • GENERATOR, DIESEL •
 EMERGENCY POWER, ELECTRIC • VENTILATION SYSTEM • DEVICES • COMPONENTS • REVIEW

100376
 CONTAINMENT FAN SERVICE WATER VALVES FAIL TO OPEN AT KEWAUNEE
 WISCONSIN PUBLIC SERVICE CORP., WIS.
 2 PGS, LTR W/AD 75-10 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, SEPT. 12, 1975, DOCKET 50-305, TYPE--PWR,
 NRG--WEST., AE--PIONEER SERV.

CAUSE - GREASE IN TORQUE SWITCH. WHILE OPERATING AT 61% POWER, TWO CONTAINMENT FAN COIL OUTLET
 SERVICE WATER VALVES FAILED TO OPEN ON SIGNAL. BOTH CIRCUIT BREAKERS WERE RESET. GREASE WAS
 FOUND IN THE BELLEVILLE SPRING WHICH PREVENTED PROPER SPRING COMPRESSION AND SUBSEQUENT TORQUE
 SWITCH OPERATION. BOTH VALVES WERE TESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

KEWAUNEE (PMI) • VALVES • CONTAINMENT AIR COOLING • VALVE OPERATORS • LUBRICATION • FAILURE, MAINTENANCE
 ERROR • INSTRUMENT, SWITCH • FAILURE, EQUIPMENT

100117
 BOTH SHIELD BUILDING AIR LOCK DOORS FOUND OPEN AT KEWAUNEE
 WISCONSIN PUBLIC SERVICE CORP., WIS.
 2 PGS, LTR W/AD 75-17 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, SEPT. 19, 1975, DOCKET 50-305, TYPE--PWR,
 NRG--WEST., AE--PIONEER SERV.

CAUSE - OPERATOR ERROR. DURING A SCHEDULED MAINTENANCE OUTAGE WITH THE UNIT IN HOT SHUTDOWN, THE
 SHIFT SUPERVISOR DISCOVERED BOTH DOORS OF THE SHIELD BUILDING AIR LOCK WERE OPEN. THE EVENT WAS
 THE RESULT OF PERSONNEL ERROR.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

KEWAUNEE (PMI) • CONTAINMENT INTEGRITY • CONTAINMENT AIR LOCK • FAILURE, OPERATOR ERROR • MAINTENANCE AND
 REPAIR

100012
 TESTING OF LIQUID LEVEL INSTRUMENTS NOT PERFORMED AT KEWAUNEE
 WISCONSIN PUBLIC SERVICE CORP., WIS.
 1 PG, RPT TO NRC OFFICE OF J & P, REGION III, OCT. 3, 1975, DOCKET 50-305, TYPE--PWR, NRG--WEST., AE--PIONEER

100014 Kewaunee
SERV.

CAUSE - REMANANT UNIT OUT OF SERVICE. AN INCIDENT REPORT WAS ISSUED AS A RESULT OF A MANAGEMENT AUDIT OF TESTS NOTING THAT REQUIRED TESTING OF THE INSERVICE BORIC ACID TANK LEVEL INSTRUMENTS WAS NOT PERFORMED DURING AUGUST. TESTS PERFORMED THE DAY AFTER THE ERROR WAS NOTED VERIFIED THAT SET POINTS WERE WITHIN LIMITS. PROCEDURES CALL FOR PLACING THE OPPOSITE TANK "IN SERVICE DURING THE TEST. THE OPPOSITE TANK WAS EMPTY DUE TO MAINTENANCE SO THAT THE TEST COULD NOT BE PERFORMED. AN EXCEPTION REPORT WAS MADE OUT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

KEWAUNEE (PHR) • TEST INTERVAL • TESTING • INSTRUMENT, SWITCH • SENSORS, LEVEL • STORAGE CONTAINER • FAILURE, ADMINISTRATIVE CONTROL • CHEMICAL SHEN

107506
TWO AUXILIARY FEEDWATER PUMPS FAIL TO START AT KEWAUNEE
WISCONSIN PUBLIC SERVICE CORP., GREEN BAY, WIS.
2 PGS, LTR W/AD 75-18 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, OCT. 23, 1975, DOCKET 50-305, TYPE--PHR,
NRC--WEST., AE--PIONEER SERV.

CAUSE - DEFECTIVE CONTROL SWITCHES. TWO AUXILIARY FEEDWATER PUMPS FAILED TO START FOLLOWING A UNIT TRIP FROM 99% POWER. THE TRIP WAS DUE TO A FLUTTER OF THE RELAY. THE THIRD AUXILIARY FEEDWATER PUMP STARTED AND FULFILLED REQUIREMENTS. THE CAUSE WAS DEFECTIVE WESTINGHOUSE W-2 CONTROL SWITCHES. BOTH SWITCHES, WHEN EASED INTO THE AUTO POSITION, FAILED TO CLOSE THE AUTO CONTACTS ASSOCIATED WITH PUMP START. A RAPID JERK ACTION RESULTS IN PROPER CLOSURE. THE SWITCHES WERE REPLACED AND INSTRUCTIONS AS TO PROPER SWITCH OPERATION WAS PROVIDED TO OPERATORS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

KEWAUNEE (PHR) • PUMPS • FEEDWATER • FAILURE, EQUIPMENT • INSTRUMENT, SWITCH • FAILURE, DESIGN ERROR • FAILURE, SIMULTANEOUS

107507
SHIELD BUILDING VENTILATION SYSTEM LOCKED OUT AT KEWAUNEE
WISCONSIN PUBLIC SERVICE CORP., GREEN BAY, WIS.
2 PGS, LTR W/AD 75-19 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, OCT. 29, 1975, DOCKET 50-305, TYPE--PHR,
NRC--WEST., AE--PIONEER SERV.

CAUSE - INADEQUATE PROCEDURE. DURING THE INITIAL PERFORMANCE OF PREVENTATIVE MAINTENANCE PROCEDURES TO VERIFY OPERATION OF THE DELUGE SYSTEM ON SHIELD BUILDING VENTILATION SYSTEM WITH THE REACTOR AT 99%, A HEAT GUN WAS USED TO ELEVATE THE TEMPERATURE ON THE HEAT DETECTOR. ACTIVATION OF THE HEAT DETECTOR LOCKED OUT TRAIN A SHIELD BUILDING EXHAUST AND RECIRCULATION FANS DISABLING THAT TRAIN. THIS VIOLATED TECH SPECS SINCE TRAIN B HAD NOT BEEN TESTED. THE PROCEDURE WAS INADEQUATE IN THAT IT DID NOT EVALUATE THE CONSEQUENCES OF ACTIVATING THE HEAT SENSOR.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

KEWAUNEE (PHR) • VENTILATION SYSTEM • POLYMERS • TEST, SYSTEM OPERABILITY • FAILURE, ADMINISTRATIVE CONTROL • PROCEDURES AND MANUALS

100070
DIESEL GENERATOR FAILS TO START AT KEWAUNEE
WISCONSIN PUBLIC SERVICE CORP., GREEN BAY, WIS.
2 PGS, LTR W/AD 75-21 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, NOV. 14, 1975, DOCKET 50-305, TYPE--PHR,
NRC--WEST., AE--PIONEER SERV.

CAUSE - IMPROPER OPERATION OF CONTROL SWITCH. DURING A TRIP TEST OF THE TURBINE WITH 1 DIESEL ALIGNED FOR AUTO START, THE DIESEL FAILED TO START. WITH THE START PERMISSIVE PRESENT, THE DIESEL CONTROL SWITCH WAS MOVED RESULTING IN AN IMMEDIATE START. THE WESTINGHOUSE W-2 CONTROL SWITCH WAS APPARENTLY EASED INTO AUTO POSITION RESULTING IN A FAILURE TO CLOSE THE AUTO CONTACTS. OPERATORS WERE ISSUED A DIRECTIVE ON PROPER OPERATING TECHNIQUES FOR W-2 SWITCHES. THE REACTOR WAS AT 88 POWER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

KEWAUNEE (PHR) • GENERATOR, DIESEL • ENGINE, INTERNAL COMBUSTION • TEST, SYSTEM OPERABILITY • FAILURE, OPERATOR ERROR • INSTRUMENT, SWITCH • OPERATION

100070
AUXILIARY FEEDWATER PUMP FLOWS RESTRICTED AT KEWAUNEE
WISCONSIN PUBLIC SERVICE CORP., GREEN BAY, WIS.
3 PGS, LTR W/AD 75-20 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, NOV. 14, 1975, DOCKET 50-305, TYPE--PHR,
NRC--WEST., AE--PIONEER SERV.

10076 MONTICELLO

CAUSE - SUCTION STRAINERS PLUGGED. DURING UNIT STARTUP OPERATIONS, REDUCED AUXILIARY FEEDWATER FLOW WAS NOTED WITH PUMPS 1A AND 1B IN OPERATION. PUMP 1C WAS STARTED. ITS FLOW WAS ALSO REDUCED. THE MAIN FEEDWATER PUMPS WERE THEN USED. THE DEMINERALIZER MEXED BED UNITS HAD LOST ABOUT 1 CU FT OF RESIN TO THE CONDENSATE STORAGE TANKS WHICH IS THE NORMAL SUPPLY OF AUXILIARY FEEDWATER. THE RESIN GRAUS PLUGGED THE FINE MESH STRAINERS IN THE SUCTION OF ALL THE AUXILIARY FEEDWATER PUMPS. THE FINE MESH SCREENS AND THE CONDENSATE STORAGE TANKS WERE CLEANED. THE SCREENS WILL BE REMOVED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

REMARKS (PHN) + FLOW + FEEDWATER + AUXILIARY + PUMPS + FLOW METERAGE + FILTERS + CRUD + RESIN + FAILURE, COMMON MODE + FAILURE, EQUIPMENT + FAILURE, DESIGN ERROR

10086

SAFEGUARD BUS BREAKER TRIPS CAUSING A UNIT TRIP AT KENNAWEE

DISCLOSURE PUBLIC SERVICE COMP., GREEN BAY, WI

3 PAGES, LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, DEC. 12, 1975, DOCKET 50-305, TYPE--PHN, MFG--WEST., AE--PILNER SERV.

CAUSE - UNKNOWN. WHILE OPERATING AT 94% POWER, THE BREAKER SUPPLYING POWER TO A NON-INTERRUPTIBLE INSTRUMENT BUS OPENED. THE SCOTS TURBINE OVERSPEED PROTECTION AND RUN, FEEDWATER PUMP LUBRICATING OIL PUMP WERE SUPPLIED THROUGH THIS BREAKER. LOSS OF POWER RESULTED IN A UNIT TRIP AND LOSS OF ONE AUX. FEEDWATER PUMP. THE CAUSE OF THE BREAKER OPENING HAS NOT BEEN DETERMINED. THE BREAKER WAS CLOSED MANUALLY AND ALL EQUIPMENT OPERATED CORRECTLY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

REMARKS (PHN) + BREAKER + ELECTRIC POWER + ELECTRIC POWER, UNINTERRUPTED + SCRAM, REAL + FAILURE, EQUIPMENT + INSTRUMENT, PROTECTIVE + REACTOR SHUTDOWN + TURBINE

10086

NOTICE OF PROPOSED IMPOSITION OF CIVIL PENALTIES AT MAINE YANKEE

AEC, WASHINGTON, D.C.

4 PAGES, LETTER TO MAINE YANKEE ATOMIC POWER COMPANY, JANUARY 10, 1975, DOCKET 50-309, TYPE--PHN, MFG--COMB., AE--STONE & WEBSTER

CAUSE - SECURITY VIOLATIONS. DURING AN INSPECTION, CERTAIN ACTIVITIES WERE FOUND THAT APPEARED TO BE IN VIOLATION OF AEC REQUIREMENTS. THESE RESULTED FROM FAILURES TO IMPLEMENT AND/OR COMPLY WITH THE SECURITY PLAN. AEC PROPOSES TO IMPOSE CIVIL PENALTIES OF \$7,250.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ECONOMICS + FAILURE, ADMINISTRATIVE CONTROL + MAINE YANKEE (PHN) + LEGALISTICS + SECURITY

10088

PIN-HOLE LEAK IN CHARGING PUMP RECIRCULATION LINE AT MAINE YANKEE

MAINE YANKEE ATOMIC POWER COMPANY

1 PAGE, LETTER TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, FEBRUARY 3, 1975, DOCKET 50-309, TYPE--PHN, MFG--COMB., AE--STONE & WEBSTER

CAUSE - EROSION. DURING NORMAL OPERATION, A PIN-HOLE LEAK DEVELOPED IN THE MINIMUM FLOW RECIRCULATION LINE ON THE RUNNING CHARGING PUMP. THE SPARE PUMP WAS PLACED IN SERVICE. THE DAMAGED COMPONENTS WERE REPLACED IN KIND. THE CAUSE WAS EXCESSIVE EROSION OF THE MINIMUM FLOW RECIRCULATION ORIFICE AND ASSOCIATED DOWNSTREAM PIPING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, PIPE + FAILURE, DESIGN ERROR + EROSION + FLOW + LEAK + MAINE YANKEE (PHN) + BYPASS + FEEDWATER + PIPES AND PIPE FITTINGS

10089

PIN-HOLE LEAK IN CHARGING PUMP LINE AT MAINE YANKEE

MAINE YANKEE ATOMIC POWER CO.

1 PAGE, LETTER TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, FEBRUARY 3, 1975, DOCKET 50-309, TYPE--PHN, MFG--COMB., AE--STONE & WEBSTER

CAUSE - EXCESSIVE EROSION. DURING NORMAL OPERATION, A PIN-HOLE LEAK DEVELOPED IN THE MINIMUM FLOW RECIRCULATION LINE ON THE RUNNING CHARGING PUMP. A SPARE PUMP WAS PLACED IN SERVICE. THE AFFECTED COMPONENTS WERE REPLACED IN KIND. THE LEAK RESULTED FROM EXCESSIVE EROSION DOWNSTREAM OF THE MINIMUM FLOW RECIRCULATION ORIFICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

100062 CONTINUED

FAILURE, PIPE • FAILURE, DESIGN ERROR • EROSION • FLU • LEAK • MAINE YANKEE (PWR) • FEEDWATER • PIPE, AND PIPE FITTINGS

000673

PIN HOLE LEAK IN MINIMUM FLOW LINE OF A CHARGING PUMP AT MAINE YANKEE
MAINE YANKEE ATOMIC POWER COMPANY

1 PAGE, LETTER TO NRC DIRECTORATE OF LICENSING, FEBRUARY 7, 1975, Docket 50-309, TYPE--PWR, NRC--COMB., AE--STONE & WEBSTER

CAUSE - EROSION. DURING NORMAL OPERATION, A PIN-HOLE LEAK DEVELOPED IN THE MINIMUM FLOW RECIRCULATION LINE ON THE OPERATING CHARGING PUMP. A SPARE PUMP WAS PLACED IN SERVICE AND THE AFFECTED PUMP VALVED OUT. THE LEAK RESULTED FROM EXCESSIVE EROSION OF THE MINIMUM FLOW RECIRCULATION ORIFICE AND THE ASSOCIATED DOWNSTREAM PIPING. THE PIPING AND ORIFICE WERE REPLACED IN KIND.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, PIPE • FAILURE, DESIGN ERROR • EROSION • FLU • LEAK • MAINE YANKEE (PWR) • FEEDWATER • PIPES AND PIPE FITTINGS

100088

TWO SURVEILLANCE CHECKS NOT PERFORMED AT MAINE YANKEE
MAINE YANKEE ATOMIC POWER COMPANY

1 PAGE, LETTER TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, FEBRUARY 10, 1975, Docket 50-309, TYPE--PWR, NRC--COMB., AE--STONE & WEBSTER

CAUSE - PROCEDURAL DEFICIENCY. TWO SURVEILLANCE CHECKS, REQUIRED TO BE PERFORMED WHENEVER THE PLANT IS IN COLD SHUTDOWN, WERE NOT PERFORMED DURING A SHUTDOWN. THESE TESTS WERE ON CONTAINMENT ISOLATION TRIP VALVES AND CONTAINMENT HIGH PRESSURE SWITCHES. PROCEDURES FAILED TO NOTIFY MANAGEMENT THAT THESE CHECKS WERE DUE. PROCEDURES ARE BEING REVISED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTAINMENT ISOLATION • PROCEDURES AND MANUALS • TESTING • CONTAINMENT INTEGRITY • FAILURE, ADMINISTRATIVE CONTROL • MAINE YANKEE (PWR) • REACTOR SHUTDOWN

100913

REACTOR POWER LEVEL TRIP DISTABLE FAILS TO TRIP AT MAINE YANKEE
MAINE YANKEE ATOMIC POWER CO.

2 PAGES, LETTER WITH AD REPORT 75/3 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, MARCH 13, 1975, Docket 50-309, TYPE--PWR, NRC--COMB., AE--STONE & WEBSTER

CAUSE - FAILED RECTIFIER. DURING TESTING, 1 OF THE 4 REACTOR POWER LEVEL TRIP DISTABLES WOULD NOT TRIP ON INCREASING POWER LEVEL. THE GULF ELECTRONICS DISTABLE TRIP UNIT, MODEL NO. ELD 240-0030-1F FAILED BECAUSE OF A FAILED RECTIFIER WITHIN THE UNIT. THE DEFECTIVE UNIT WAS REPLACED IN KIND.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT • INSTRUMENT CALIBRATION • FAILURE, INSTRUMENT • INSTRUMENT, SYSTEM • TEST, SYSTEM OPERABILITY • INSTRUMENT, POWER RANGE • MAINE YANKEE (PWR) • ELECTRONIC FUNCTION UNITS

100914

SERVICE WATER SYSTEM VALVE FOUND CLOSED AT MAINE YANKEE
MAINE YANKEE ATOMIC POWER CO.

2 PAGES, LETTER WITH AD REPORT 75/4 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, MARCH 10, 1975, Docket 50-309, TYPE--PWR, NRC--COMB., AE--STONE & WEBSTER

CAUSE - PROCEDURAL DEFICIENCY. DURING NORMAL OPERATION A SERVICE WATER SYSTEM VALVE, WHICH SHOULD HAVE BEEN LOCKED OPEN TO PROTECT THE REDUNDANCY OF THE SERVICE WATER SYSTEM, WAS FOUND CLOSED. THE VALVE DID NOT APPEAR ON THE APPROPRIATE LOCKED VALVE LIST. THE VALVE WAS LOCKED OPEN AND ADDED TO THE APPROPRIATE LOCKED VALVE LIST.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PROCEDURES AND MANUALS • FAILURE, ADMINISTRATIVE CONTROL • AUXILIARY COOLING • MAINE YANKEE (PWR) • VALVES

100924

ORDER IMPOSING CIVIL PENALTIES OF \$4000 AT MAINE YANKEE
NUCLEAR REGULATORY COMMISSION, WASHINGTON, D.C.

4 PAGES, LETTER TO MAINE YANKEE ATOMIC POWER COMPANY, MARCH 20, 1975, Docket 50-309, TYPE--PWR, NRC--COMB., AE--STONE & WEBSTER

133936 CONTINUOUS

CAUSE - SECURITY VIOLATIONS. CIVIL PENALTIES OF \$4000 WERE IMPOSED FOR 5 ITEMS OF NONCOMPLIANCE CONCERNING VIOLATIONS OF THE REQUIREMENTS OF THE SECURITY PLAN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ELEMENTS - COMPLIANCE - FAILURE, ADMINISTRATIVE CONTROL - MAINE YANKEE (PM) - LEGALISTICS - AGENCY, NRC - SECURITY

133946

CHECK VALVE ON AIR PARTICULATE DETECTOR FAILS AT MAINE YANKEE

MAINE YANKEE ATOMIC POWER COMPANY

3 PAGES. LETTER WITH ACR 75-6 TO NRC DIRECTOR OF REGULATORY OPERATIONS, REGION 1, APRIL 18, 1975, DOCKET 50-309, TYPE--PM, MW--CUMD, AE--STONE & WEBSTER

CAUSE - HIGH PIN FAILURE. A CHECK VALVE ON THE SUCTION SIDE OF THE CONTAINMENT AIR PARTICULATE DETECTOR PUMP BROKE DURING NORMAL OPERATION, RESTRICTING FLOW THROUGH THE SYSTEM. THE JENNINS BRUSHERS, FIG. 40, TAC-A, 1-INCH CHECK VALVE FAILED AT THE VALVE DISC HINGE PIN. THE VALVE WAS REPAIRED. DURING THIS INCIDENT 3027 CU FT OF AIR ESCAPED FROM THE CONTAINMENT THROUGH WEAR SEALS AND GASKETS BEHIND THE APD. A TOTAL OF 0.332 CI OF ACTIVITY WAS RELEASED. PROCEDURES HAVE BEEN REVISITED REGARDING ISOLATION OF THE APD ANYTIME ITS ASSOCIATED PUMP IS NOT RUNNING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MAINE YANKEE (PM) - VALVE, CHECK - CONTAINMENT - AIR - AIRBORNE RELEASE - FAILURE, EQUIPMENT - SEAL - RADIATION SUITORS - PUMPS

133948

PMSI PUMP SUCTION VALVE FAILS TO OPEN AT MAINE YANKEE

MAINE YANKEE ATOMIC POWER CO.

3 PAGES. LETTER WITH ACR 75-7 TO NRC DIR. OF REGULATORY OPERATIONS, REGION 1, APRIL 29, 1975, DOCKET 50-309, TYPE--PM, MW--CUMD, AE--STONE & WEBSTER

CAUSE - UNKNOWN. DURING TESTING WITH THE REACTOR AT 87% POWER, A PMSI PUMP SUCTION SUPPLY VALVE FAILED TO OPEN. THE VALVE WAS WACKED OFF ITS CLOSED SEAT MANUALLY AND THEN CYCLED 5 TIMES USING THE MOTOR OPERATION WITHOUT REOCCURENCE. NO CAUSE WAS FOUND.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

VALUES - SAFETY INJECTION - TEST, SYSTEM OPERABILITY - FAILURE, EQUIPMENT - MAINE YANKEE (PM)

133950

RUST OUTLET VALVE FAILS TO CLOSE AT MAINE YANKEE

MAINE YANKEE ATOMIC POWER COMPANY

3 PAGES. LETTER WITH ACR 75-8 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, MAY 29, 1975, DOCKET 50-309, TYPE--PM, MW--CUMD, AE--STONE & WEBSTER

CAUSE - VALVE MOTOR FAILURE. DURING TESTING WITH THE PLANT IN A REFUELING CONDITION, RUST OUTLET VALVE FAILED TO CLOSE ON SIGNAL. IT STARTED TO MOVE WHEN THE POWER SUPPLY BREAKER TRIPPED. THE VALVE MOTOR HAD RUNNER LUB. IT WAS SENT OFF SITE TO BE REWOUND. NO DEFICIENCIES WERE FOUND IN THE VALVE OR CIRCUIT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MAINE YANKEE (PM) - VALVES - REACTOR COOLANT - STORAGE CONTAINER - TEST, SYSTEM OPERABILITY - FAILURE, EQUIPMENT - VALVE OPERATORS - REFUELING

133957

SAFETY INJECTION TANK ISOLATION VALVES CLOSED AT MAINE YANKEE

MAINE YANKEE ATOMIC POWER CO.

2 PAGES. LETTER TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, JUNE 25, 1975, DOCKET 50-309, TYPE--PM, MW--CUMD, AE--STONE & WEBSTER

CAUSE - OPERATOR ERROR. THE 3 SAFETY INJECTION TANK MOTOR OPERATED ISOLATION VALVES WERE NOT OPENED DURING A PLANT STARTUP UNTIL THE REACTOR COOLANT SYSTEM TEMPERATURE AND PRESSURE HAD REACHED 370 & 720 PSIG. THE OPERATOR WHO COMPLETED THE ECCS VALVE CHECKLIST NOTED THE VALVE HANDWHEELS AND INSTANTLY ASSUMED THE VALVES WERE LOCKED OPEN WHEN THEY WERE LOCKED CLOSED. THE CONTROL ROOM OPERATOR NOTICED IMPROPER VALVE POSITION INDICATION. THE VALVES WERE OPENED IMMEDIATELY AND THE ENTIRE ECCS VALVE CHECKLIST RE-COMPLETED. NO OTHER ERRORS WERE FOUND.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MAINE YANKEE (PM) - VALVES - SAFETY INJECTION - STORAGE CONTAINER - CONTAINMENT ISOLATION - FAILURE,

100007 PLANTINGUP
OPERATION END - REACTION STARTUP

100000
MPSI SYSTEM FLUID DISTRIBUTION FAILS TO MEET SPECS AT MAINE YANKEE
MAINE YANKEE ATOMIC POWER CO.
2 PAGES, LETTER WITH AOR 75-11 TO NRC LIA. RE REGULATORY OPERATIONS, REGION 1, JUNE 27, 1975, DOCKET 50-309, TYPE--
PWR, MFG--COMB.. AE--STONE & WEBSTER

CAUSE - VALVE STOPS MISADJUSTED. FLUID TESTS CONDUCTED ON MPSI TRAIN A AT 1230 PSIG DISCHARGE HEAD
SHOWED THAT TOTAL FLOW EXCEEDED THE LIMIT BUT THE DISTRIBUTION BETWEEN LINES WAS LOW FOR ONE
PAIR. THE FLUID DISTRIBUTION VALVES WERE ADJUSTED. A RETEST SHOWED AN ACCEPTABLE FLUID
DISTRIBUTION. APPARENTLY THE VALVE MECHANICAL STOPS WERE NOT ADJUSTED PROPERLY FOLLOWING ROUTINE
MAINTENANCE. THE PUMP STOP POSITIONS WERE RECORDED AND WILL BE CHECKED EVERY 3 MONTHS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

MAINE YANKEE (PWR) + FLUID DISTRIBUTION + SAFETY INJECTION + TEST, SYSTEM OPERABILITY + FAILURE, MAINTENANCE
ERROR + VALVES + SET POINT

100312
LPSI HEADER STOP VALVE FAILS AT MAINE YANKEE
MAINE YANKEE ATOMIC POWER COMPANY
3 PAGES, LETTER WITH AOR 75-11 TO NRC LIA. RE REGULATORY OPERATIONS, REGION 1, JULY 7, 1975, DOCKET 50-309,
TYPE--PWR, MFG--COMB.. AE--STONE & WEBSTER

CAUSE - CONTROL POWER TRANSFORMER FAILS. WHILE OPERATING AT 300 PPM, THE OPERATOR NOTED A LOSS
OF VALVE POSITION INDICATION ON A LPSI HEADER STOP VALVE. THE VALVE'S CONTROL POWER TRANSFORMER
HAD FAILED. THE VALVE WAS MANUALLY OPENED AND LOCKED IN POSITION WHILE THE DEFECTIVE TRANSFORMER
WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

MAINE YANKEE (PWR) + VALVES + LPSI + ELECTRIC POWER + FAILURE, EQUIPMENT + TRANSFORMER.

100377
CIRCULATING WATER DISCHARGE TEMPERATURE EXCEEDS LIMITS AT MAINE YANKEE
MAINE YANKEE ATOMIC POWER CO., MAINE
2 PGS, LTR WITH AOR 75-12 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, AUG. 22, 1975, DOCKET 50-309,
TYPE--PWR, MFG--COMB.. AE--STONE & WEBSTER

CAUSE - NOT STATED. THE CIRCULATING WATER TEMPERATURE, MEASURED AT A POINT ROUGHLY EQUIVALENT TO
THE PUMP DISCHARGE HEAD, EXCEEDED THE 99 F LIMIT FOR MORE THAN 2 HOURS 13 TIMES DURING AUG.
1975. THE DISCHARGE IS RUN THROUGH AN UNDERWATER, MULTI-PORT, DIFFUSER INTO BUCKLE RIVER RATHER
THAN THE WEIR FOR WHICH THE TECH SPEC CHANGE HAS BEEN PREPARED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

MAINE YANKEE (PWR) + TEMPERATURE + EFFLUENT + CONDENSER COOLING SYSTEM + RIVER + DISCHARGE

100376
APS MONTHLY TESTING NOT PERFORMED IN PROPER TIME INTERVAL AT MAINE YANKEE
MAINE YANKEE ATOMIC POWER CO., MAINE
2 PGS, LTR WITH AOR 75-12 TO NRC OFFICE OF I & E, REGION 1, AUG. 27, 1975, DOCKET 50-309, TYPE--PWR, MFG--COMB.. AE--
STONE & WEBSTER

CAUSE - PERSONNEL OVERSIGHT. A TIME INTERVAL OF FROM 39 TO 40 DAYS ELAPSED BETWEEN PERFORMANCES
OF INDIVIDUAL PLATFORMS OF REACTOR PROTECTIVE SYSTEM MONTHLY TESTS. TECH SPECS LIMIT IS 33 DAYS
PLUS OR MINUS 25%. FAILURE WAS DUE PRIMARILY TO OVERSIGHT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

MAINE YANKEE (PWR) + TEST INTERVAL + TESTING + REACTOR SAFETY SYSTEM + FAILURE, ADMINISTRATIVE CONTR.

100002
SCRAMMED VALVE FAILS AT MAINE YANKEE
MAINE YANKEE ATOMIC POWER CO., WISCONSIN
3 PGS, LTR WITH AOR 75-12 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, NOV. 19, 1975, DOCKET 50-309,
TYPE--PWR, MFG--COMB.. AE--STONE & WEBSTER

CAUSE - COMPONENT FAILURE. DURING A MAINTENANCE SHUTDOWN, A GROUND ON A DC DISTRIBUTION BUS LED TO
THE DISCOVERY THAT A CONTROL SYSTEM SCRAMMED VALVE FOR A TEMPERATURE CONTROL VALVE HAD FAILED.
THE CONTROL VALVE SECURES SECONDARY COMPONENT COOLING FLOW THROUGH THE NON-ESSENTIAL HYDROGEN

100832 REJUSTICE

CONCRETE ON CONTAINMENT SPRAY ACTUATION. AFFECTED PARTS ON ASCO MODEL 833001 SOLENOID VALVE WERE REPLACED IN FIELD.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

VALVES • OPERATIONS • CONTROL SYSTEM • AUXILIARY COOLING SYSTEM • FAILURE, COMPONENT • MAINE YANKEE (PHR)

100831

CONTAINMENT ISOLATION TRIP VALVE FAILS TO CLOSE AT MAINE YANKEE

MAINE YANKEE ATOMIC POWER CO., WISCASSETT, ME

3 PGS. LTR W/ADJ 75-14 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION I, DEC. 3, 1975, DOCKET 50-309, TYPE--PHR, NRC--CONR., AE--STONE & WEBSTER

CAUSE - UNKNOWN. DURING TESTING OF THE CONTAINMENT ISOLATION TRIP VALVES WHILE OPERATING AT 628 POWER, THE CONTAINMENT NITROGEN SUPPLY HEADER VALVE FAILED TO ACTUATE. ON THE THIRD ATTEMPT, THE VALVE FUNCTIONED NORMALLY. NO DISCREPANCIES WERE NOTED IN THE ELECTRO-PNEUMATIC CONTROL SYSTEM FOR THE VALVE. THIS VALVE WILL BE TESTED DAILY FOR 2 WEEKS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MAINE YANKEE (PHR) • VALVES • CONTAINMENT ISOLATION • CONTAINMENT PURGE • NITROGEN • TEST, SYSTEM OPERABILITY • FAILURE, EQUIPMENT

109270

LEAK FOUND IN RC LETDOWN LINE WELD AT MAINE YANKEE

MAINE YANKEE ATOMIC POWER CO., WISCASSETT, ME

3 PGS. LTR W/ADJ 75-14 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION I, DEC. 15, 1975, DOCKET 50-309, TYPE--PHR, NRC--CONR., AE--STONE & WEBSTER

CAUSE - WELD POROSITY. WHILE OPERATING AT 1306 POWER, A SMALL LEAK WAS FOUND THROUGH A DEFECTIVE SOCKET WELD ON A 3/4 INCH PRESSURE TAP ON THE REACTOR COOLANT LETDOWN LINE NEAR THE OUTLET OF THE HEAT EXCHANGER. THE LINE WAS ISOLATED AND THE WELD REPAIRED. A LEAK CHECK REVEALED A SECOND WELD DEFECT. IT WAS ALSO REPAIRED. FAILURE WAS APPARENTLY CAUSED BY WELD POROSITY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MAINE YANKEE (PHR) • WELDS • PIPES AND PIPE FITTINGS • COOLANT PURIFICATION SYSTEM • FAILURE, PIPE • LEAK • FAILURE, INSTALLATION ERROR

100512

LAMINATION FOUND IN PIPING MATERIAL AT REQUIRE 1 AND 2

DUKE POWER CO., CHARLOTTE, N.C.

2 PGS. LTR W/CONSTRUCTION DEFICIENCY RPT C0369-370775-2 TO NRC OFFICE OF I & E, NOV. 19, 1975, DOCKETS 50-369/370, TYPE--PHR, NRC--NEST., AE--DUKE

CAUSE - UNKNOWN. IN ONE LOT OF 2-INCH SCH 40 EFW STAINLESS STEEL PIPE CONFORMING TO SA-312 TYPE 304, A LAMINATION WAS NOTED IN THE PIPE DURING FIELD WELDING. THIS LAMINATION EXTENDS AROUND THE WALL GIVING THE APPEARANCE OF 2 CONCENTRIC PIPES. ALL PIPING MATERIAL FOR THIS HEAT WHICH HAS BEEN INSTALLED IN SAFETY RELATED SYSTEMS HAS BEEN IDENTIFIED. A UT PROCEDURE IS BEING DEVELOPED TO DETECT SIMILAR DEFICIENCIES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

REQUIRE 1 (PHR) • REQUIRE 2 (PHR) • CONSTRUCTION • PIPES AND PIPE FITTINGS • PLAN • FAILURE, FABRICATION ERROR • ENGINEERED SAFETY FEATURE

059670

REACTION CONTAINMENT BUILDING REINFORCING BAR SPACING AT MIDLAND 1 AND 2

CONSUMERS POWER COMPANY, MICHIGAN

7 PGS. LTR TO REC DIRECTORATE OF REGULATORY OPERATIONS, JANUARY 3, 1975, DOCKETS 50-329/330, TYPE--PHR, NRC--BPA, AE--BECHTEL

CAUSE - INSTALLATION ERROR. PRIOR TO PLACEMENT OF CONCRETE IN A SECTION OF THE REACTOR BUILDING CONTAINMENT BUILDING WALL, CONSUMER POWER FIELD OR ENGINEERS SURVEYED THE AREA. SPACING OF VERTICAL REBARS VARIED FROM 4.5 TO 15 INCHES. DESIGN SPACING WAS 6.7 TO 9.3 INCHES. THE FIELD INSPECTION PLAN WAS SIGNED OFF BY BECHTEL JC ENGINEER. A STOP WORK ORDER WAS ISSUED. REBAR SPACING WAS READJUSTED AT THE TOP. AT THE BOTTOM IT WAS ALREADY ENCLOSED IN CONCRETE. STRESS ANALYSIS INDICATES THAT STRENGTH DEPENDS MORE ON THE TOTAL AREA OF STEEL RATHER THAN THE SPACING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

STEEL • CONTAINMENT INTEGRITY • CONTAINMENT STRUCTURE • FAILURE, INSTALLATION ERROR • QUALITY ASSURANCE • MIDLAND 1 (PHR) • MIDLAND 2 (PHR) • CONSTRUCTION • CONCRETE, REINFORCED

101540

FINAL REPORT ON REINFORCING BAR SPACING DEFICIENCY AT MIDLAND 2

CONSUMERS POWER COMPANY, MICHIGAN

3 PAGES, LETTER TO NRC DIVISION OF REACTOR LICENSING, JANUARY 24, 1979, Docket 50-330, TYPE--PWR, NRC--NOL, AC--DECHTEL

CAUSE - INSTALLATION ERROR. AS REPORTED EARLIER, DEFICIENCIES WERE FOUND IN REBAR SPACING IN THE REACTOR CONTAINMENT BUILDING WALL. THE FOLLOWING STEPS WERE TAKEN TO PREVENT RECURRENCE. (1) SPACING-OF-REINFORCEMENT SPECIFICATIONS WERE CHANGED BY DEFINING EXCEPTIONS MORE SPECIFICALLY. (2) WRITTEN INSTRUCTIONS TO FIELD ENGINEERS HAVE BEEN PREPARED WHICH COVERS THESE REQUIREMENTS. (3) FIELD ENGINEERS AND QUALITY CONTROL ENGINEERS HAVE RECEIVED ADDITIONAL TRAINING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MEASUREMENT + PROCEDURES AND MANUALS + STEEL + CONTAINMENT STRUCTURE + MODIFICATION + FAILURE, INSTALLATION ERROR + QUALITY ASSURANCE + MIDLAND 2 (PWR) + CONSTRUCTION + CONCRETE, REINFORCED

090940

REBAR INSTALLATION AND INSPECTION ERRORS AT MIDLAND 2

AEC, WEN ELLYN, ILL.

4 PAGES, LETTER TO REGULATORY OPERATIONS, HEADQUARTERS, TRANSMITTING NO INQUIRY REPORT, JANUARY 13, 1979, Docket 50-330, TYPE--PWR, NRC--NOL, AC--DECHTEL

CAUSE - CONTRACTOR ERRORS. DURING A ROUTINE JO JOINT BY THE UTILITY, IT WAS FOUND THAT FOR ONE LEFT THE REBAR SPACING WAS OUT OF LIMITS. A TRANSITION FROM 12 INCH TO 8 INCH SPACING OCCURS WITHIN THE LEFT. MINIMUM SPACING OBSERVED WAS 4 INCHES AGAINST A 6 2/3 INCH LIMIT. MAXIMUM WAS 15 INCHES AGAINST A 12 1/3 INCH LIMIT. THE CONTRACTOR QC INSPECTOR TREATED THEM AS ACCEPTABLE. A STOP WORK ORDER WAS ISSUED UNTIL THE INTEGRITY OF THIS SECTION WAS VERIFIED. PRELIMINARY DATA INDICATE THAT THE AVERAGE CROSS SECTIONAL AREA OF REBAR PER SEGMENT OF WALL IS 2.79 SQ IN/FT COMPARED TO THE SPECIFIED 2.34 SQ IN/FT AND INTEGRITY WAS NOT ADVERSELY AFFECTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

STEEL + CONTAINMENT STRUCTURE + FAILURE, INSTALLATION ERROR + QUALITY ASSURANCE + MIDLAND 2 (PWR) + CONSTRUCTION + CONCRETE, REINFORCED

090630

RELAYS IN SAFEGUARDS STATUS PANEL FAIL AT HILLSTONE 2

NORTHEAST NUCLEAR ENERGY COMPANY, CONNECTICUT

3 PAGES, LETTER WITH DEFICIENCY REPORT NO. 14 TO DIRECTORATE OF REGULATORY OPERATIONS AEC, JANUARY 8, 1979, Docket 50-330, TYPE--PWR, NRC--CMB, AC--DECHTEL

CAUSE - DESIGN ERROR. DURING STARTUP TESTING OF THE SAFEGUARDS EQUIPMENT STATUS PANEL, RELAYS USED TO CHECK FOR PRESENCE OF AC OR DC CONTROL POWER HAVE FAILED IN DC CIRCUITS WHICH OPERATE SOLENOID VALVES. FAILURES RESULTED FROM DIODE BREAKDOWN RESULTING FROM VOLTAGE SURGES DURING THE ENERGIZATION OF A VALVE OPERATION. ALL DC CIRCUITS ARE NOW DESIGNED TO USE RELAYS WITHOUT A DIODE BRIDGE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + CONTROL SYSTEM + TEST, PREOPERATIONAL + FAILURE, DESIGN ERROR + ENGINEERED SAFETY FEATURE + HILLSTONE POINT 2 (PWR) + CONSTRUCTION + TRANSIENT + RELAYS

101950

HIGH PRESSURE SAFETY INJECTION PUMPS DO NOT ROTATE FREELY AT HILLSTONE 2

NORTHEAST UTILITIES COMPANY, CONN.

3 PAGES, LETTER WITH REPORT TO NRC DIRECTORATE OF REGULATORY OPERATIONS, MARCH 10, 1979, Docket 50-330, TYPE--PWR, NRC--CMB, AC--DECHTEL

CAUSE - STATIC LOUAS ON SUCTION. DURING AN ALIGNMENT CHECK, 2 OF THE 3 HIGH PRESSURE SAFETY INJECTION PUMPS DID NOT ROTATE FREELY. THEY HAD BEEN OPERATED PREVIOUSLY. INSTALLATION OF PERMANENT PIPE HANGERS IS IN PROGRESS. IT IS THOUGHT THAT THIS CAUSED HIGH STATIC LOADINGS ON THE Suction CONNECTIONS. SLIGHT DISPLACEMENT OF THE CASING CAN CAUSE THE CLAMP CLEARANCE RING FITS TO CONTACT THE SHAFT. THE RUNNING FITS WILL BE INCREASED BY ABOUT 5 MILLS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

STRESS + SAFETY INJECTION + FAILURE, INSTALLATION ERROR + HILLSTONE POINT 2 (PWR) + INSTALLATION + CONSTRUCTION + PUMPS

102100

DIESEL GENERATOR FIELD CIRCUIT DEFICIENCY AT HILLSTONE 2

NORTHEAST NUCLEAR ENERGY CO.

2 PAGES, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, APRIL 1, 1979, Docket 50-330, TYPE--PWR, NRC--

102140 PLANTINGUP
CUMM. AC--BECHTEL

CAUSE - WIRING ERROR. DURING A 24 HOUR FULL LOAD TEST OF DIESEL GENERATOR A, A BUNDLE OF WIRES IN THE LOCAL CONTROL AND ANNUNCIATOR PANEL BURNED. THROUGH A WIRING ERROR, THE 60 AMP GENERATOR FIELD CURRENT WAS CONDUCTED THROUGH A NO. 14 WIRE USED FOR METERING. DAMAGE WAS CONFINED TO THE WIRING HARNESS WHICH CONTAINED THE OVERLOADED WIRE. DIESEL GENERATOR B, WHICH HAD COMPLETED ITS 24 HOUR TEST, WAS WIRING SIMILARLY AND SHOWED SIGNS OF WIRING DEGRADATION DUE TO THE SAME ERROR. ALL OVERHEATED AND DAMAGED WIRING WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TEST, SYSTEM OPERABILITY + FAILURE, INSTALLATION ERROR + HILLSTONE POINT 2 (PHM) + CONSTRUCTION + CABLES AND CONNECTIONS + ENGINE, INTERNAL COMBUSTION + GENERATOR, DIESEL

101701
RADIOACTIVE LIQUIDS DISCHARGED FROM SUMP AT HILLSTONE 2
NORTHEAST NUCLEAR ENERGY COMPANY, CORP.
7 PAGES. LETTER WITH REPORT 75/6 TO NRC DIVISION OF REACTOR LICENSING, APRIL 8, 1975, DOCKET 50-245, TYPE--DNR, 406--6000, AC--E04500

CAUSE - MISUNDERSTANDING. RADIOACTIVE LIQUIDS WERE DISCHARGED TWICE IN ONE DAY FROM AN UNIDENTIFIED SUMP IN THE FIRST CONDENSER PIT SUMP OF UNIT 2. TOTAL ACTIVITY WAS 40 MICRO-CURIES. ACTING SHIFT SUPERVISORS WERE ASSIGNED AT THIS TIME. PREVIOUS SAMPLES FROM THE SUMPS SHOWED NO ACTIVITY. WORK WAS ANTICIPATED. THEREFORE, PROVISION HAD NOT BEEN MADE. BOTH BATCHES WERE SAMPLED PRIOR TO DISCHARGE. THE ACTIVITY WAS A RESULT OF CONTAMINATION OF THE HOUSE HEATING STRAP PIPING (REPORTED EARLIER). PROCEDURES HAVE BEEN MODIFIED TO PREVENT RECCURENCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

REACTOR, DNR + REACTOR STARTUP EXPERIENCE + RADIOACTIVITY RELEASE + FAILURE, ADMINISTRATIVE CONTROL + HILLSTONE POINT 2 (PHM) + HILLSTONE POINT 1 (DNR)

100609
NOTICE OF PROPOSED IMPOSITION OF CIVIL PENALTIES AT HILLSTONE
U.S. NUCLEAR REGULATORY COMMISSION
4 PAGES. LETTER WITH ATTACHMENT TO NORTHEAST NUCLEAR ENERGY COMPANY, APRIL 13, 1975, DOCKET 50-245, TYPE--PMP, 406--6000, AC--E04500

CAUSE - ADMINISTRATIVE ERROR. DURING AN INSPECTION, IT WAS FOUND THAT CERTAIN ACTIVITIES APPEARED TO BE IN NONCOMPLIANCE WITH NRC REQUIREMENTS. THE ITEMS ARE THE RESULT OF FAILURE TO IMPLEMENT ANNUAL FOLLOW THE SITE SECURITY PLAN. PROPER CONTROL WAS NOT ESTABLISHED BETWEEN THE OPERATING AREA OF UNIT 1 AND THE CONSTRUCTION AREA OF UNIT 2. THE EFFECTIVENESS OF THE MANAGEMENT CONTROL SYSTEM IS OF CONCERN IN THAT IT DID NOT PREVENT THE INCIDENTS. NRC PROPOSES TO IMPOSE CIVIL PENALTIES OF \$11500.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

HILLSTONE POINT 1 (DNR) + REACTOR, DNR + COMPLIANCE + SECURITY + LEGALISTICS + ECONOMICS + FAILURE, ADMINISTRATIVE CONTROL + HILLSTONE POINT 2 (PHM)

100891
RELAYS SAFEGUARDS EQUIPMENT PANEL FAIL AT HILLSTONE 2
NORTHEAST NUCLEAR ENERGY COMPANY, CORP.
2 PAGES. LETTER WITH DEFICIENCY REPORT 14 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, APRIL 16, 1975, DOCKET 50-330, TYPE--PMP, 406--6000, AC--BECHTEL

CAUSE - DESIGN DEFICIENCY. DURING STARTUP TESTING OF THE SAFEGUARDS EQUIPMENT STATUS PANEL, RELAYS USED TO CHECK FOR THE PRESENCE OF AC OR DC CONTROL POWER HAVE FAILED IN DC CIRCUITS WHICH OPERATE SHUTDOWN VALVES. DIODES IN THE BRIDGE RECTIFIER CIRCUIT OF THE COIL FAILED BLOWING CONTROL POWER FUSES. SURGE SUPPRESSION DIODES HAVE BEEN CONNECTED ACROSS ALL DC MONITOR RELAYS TO PROTECT THEM FROM INDUCTIVE KICKBACK.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

HILLSTONE POINT 2 (PHM) + CONSTRUCTION + RELAYS + CONTROL SYSTEM + ENGINEERED SAFETY FEATURE + TEST, SYSTEM OPERABILITY + TEST, PREOPERATIONAL + FAILURE, COMPONENT + SOLID STATE DEVICE + FAILURE, DESIGN ERROR

100890
FINAL REPORT ON POTENTIAL DAMAGE TO CONTAINMENT TENDONS AT HILLSTONE 2
NORTHEAST NUCLEAR ENERGY COMPANY, CORP.
9 PAGES. LETTER WITH DEFICIENCY REPORT 17 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, APRIL 16, 1975, DOCKET 50-330, TYPE--PMP, 406--6000, AC--BECHTEL

CAUSE - CONSTRUCTION ERROR. IN FEBRUARY IT WAS DISCOVERED THAT A CORE DRILL USED TO INSTALL PIPE

102890 CONTINUED

SUPPORTS ON THE EXTERIOR SURFACE OF THE CONTAINMENT STRUCTURE HAD HIT AND POTENTIALLY DAMAGED AN EMBEDDED POST TENSIONING TENDON. CORE DRILLING MAY HAVE ALSO DAMAGED EMBEDDED REINFORCING STEEL AT OTHER LOCATIONS. CORE DRILLING IN THE CONTAINMENT EXTERIOR WALL HAS BEEN DISCONTINUED. THE HOLE INTO THE TENDON WAS PLUGGED AND THE LOST GREASE REPLACED. ANALYSIS INDICATES THAT STRESSES IN THE LINER PLATE, CONCRETE, AND REINFORCING STEEL ARE WITHIN THE DESIGN LIMITS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

HILLSTONE POINT 2 (PHN) • CONSTRUCTION • CABLES AND CONNECTORS • CONCRETE, PRESTRESSED • CONTAINMENT STRUCTURE • FAILURE, INSTALLATION ERROR • DAMAGE

103049

BRACKETS INSTALLED ON CONTAINMENT LINER AT HILLSTONE 2
NORTHEAST NUCLEAR ENERGY COMPANY, CORP.

2 PAGES, LETTER WITH ATTACH. TO NRC OFFICE OF INSPECTION & ENFORCEMENT, MAY 5, 1975, Docket 50-330, TYPE--PHN, NRC--CUMB., AE--DECHTEL

CAUSE - INSTALLATION ERROR. BRACKETS, INTENDED TO BE USED TO HANG PERSONNEL STRETCHERS, WERE INSTALLED ON THE CONTAINMENT LINER PLATE WITH CARTRIDGE-DRIVEN STUDS AFTER COMPLETION OF THE INTEGRATED LEAK RATE TEST. THE STUDS PENETRATED TO A DEPTH OF 5/8 INCH FROM THE SURFACE. A SMALL PLATE WILL BE WELDED OVER EACH HOLE. LEAK RATE TESTS WILL BE MADE BY PRESSURIZING A BOX SURROUNDING THE REPAIR AREA TO 54 PSIG.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

HILLSTONE POINT 2 (PHN) • CONSTRUCTION • CONTAINMENT LINER • DAMAGE • CONTAINMENT INTEGRITY • FAILURE, INSTALLATION ERROR

103073

AUXILIARY CONTACTS OF MOTOR CONTROL CENTERS STICK AT HILLSTONE 2
NORTHEAST NUCLEAR ENERGY COMPANY, CORP.

2 PAGES, LETTER WITH DEFICIENCY REPORT NO. 19 TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, JUNE 12, 1975, Docket 50-330, TYPE--PHN, NRC--CUMB., AE--DECHTEL

CAUSE - DESIGN DEFICIENCY. AUXILIARY CONTACTS (MODEL CR 2354) OF 480 V MOTOR CONTROL CENTERS HAVE STUCK IN THE OPEN POSITION AFTER THE MAIN CONTACTOR HAS DE-ENERGIZED. THE SQUARE CORNER OF THE MOVABLE CONTACT PLUNGER HAS FOUND STUCK ON THE EDGE OF THE FIXED CONTACT BLOCK. THIS OCCURS ONLY WHEN ADDITIONAL ADDER CONTACT BLOCKS ARE INSTALLED. NEW ADDER CONTACTS ON SITE HAVE A REVELLED CORNER ON THE PLUNGER. STICKING CONTACTS WERE REPLACED WITH NEW PARTS FROM SPARES WITH BEVELLED CORNERS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

HILLSTONE POINT 2 (PHN) • CONSTRUCTION • INSTRUMENT, SWITCH • RELAYS • ELECTRIC POWER • CONTROL • ENGINEERED SAFETY FEATURE • MODIFICATION • FAILURE, DESIGN ERROR

104930

ADDITIONAL INFORMATION ON OL HEAT EXCHANGER INLET NOZZLE FAILURE AT HILLSTONE 2
NORTHEAST NUCLEAR ENERGY CO., HARTFORD, CONN.

4 PAGES, LETTER WITH REPORT TO NRC OFFICE OF INSPECTION & ENFORCEMENT, JULY 31, 1975, Docket 50-330, TYPE--PHN, NRC--CUMB., AE--DECHTEL

CAUSE - HYDRAULIC TRANSIENT. THE SERVICE WATER INLET NOZZLE TO THE AIR COOLER HEAT EXCHANGER FOR DIESEL GENERATOR A FAILED. DURING START UP AND SHUT DOWN OF THE DIESEL GENERATOR FOLLOWING THE LOSS OF NORMAL POWER TEST, A HYDRAULIC TRANSIENT OCCURRED DUE TO THE OUTLET CONTROL VALVE CONTROL SCHEME ON THE SERVICE WATER LINE TO THE HEAT EXCHANGER. THE HYDRAULIC TRANSIENT PROPAGATED TO THE INLET SIDE CAUSING THRUST FORCES WELL IN EXCESS OF THE ALLOWABLE STRESS OF THE CAST IRON NOZZLE. THE CONTROL SYSTEM AND THE SERVICE WATER PIPING WERE MODIFIED TO REDUCE THE HYDRAULIC TRANSIENT AND ITS EFFECTS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

HILLSTONE POINT 2 (PHN) • CONSTRUCTION • HEAT EXCHANGERS • NOZZLE • GENERATOR, DIESEL • HYDRAULIC EFFECT • AUXILIARY CIRCUIT • FAILURE, DESIGN ERROR • TEST, SYSTEM OPERABILITY • TEST, PREOPERATIONAL

105500

REFUELING POOL WATER LEVEL LOW DURING CORE ALTERATIONS AT HILLSTONE 2

NORTHEAST NUCLEAR ENERGY COMPANY, HARTFORD

2 PGS, LTR D/WR 75-32 TO NRC OFFICE OF I & E, REGION 1, AUG. 20, 1975, Docket 50-330, TYPE--PHN, NRC--CUMB., AE--DECHTEL

CAUSE - OPERATOR ERROR. DURING INITIAL FUELING OPERATIONS, THE REFUEL POOL WATER LEVEL WAS MAINTAINED BELOW THE TRANSFER TUBE PRIOR TO CLOSING THE TRANSFER TUBE ISOLATION VALVE. CORE ALTERATIONS (ERTING UP THE UPPER GUIDE STRUCTURE) WERE CONDUCTED CONTRARY TO TECH SPECS. CORE

100350 - CONTINUED

ALERTATIONS WERE SUSPENDED AND THE ISOLATION VALVE CLOSED. THE OPERATOR FAILED TO FOLLOW PROCEDURES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MILLSTONE POINT 2 (PM2) - FUEL HANDLING - STORAGE CONTAINER - FUEL STORAGE - CONTAINMENT ISOLATION - VALVES - REACTOR STARTUP EXPERIENCE - FAILURE, OPERATOR ERROR - PROCEDURES AND MANUALS

100355

DIESEL GENERATOR SERVICE WATER HEAT EXCHANGER LEAKS AT MILLSTONE 2

NORTHEAST NUCLEAR ENERGY CORP. CORN.

2 PGS. LTR W/AT 75-05 TO NRC OFFICE OF I & E, REGION I, SEPT. 5, 1975, DCKET 50-336, TYPE--PM2, HSG--COMB., AT--BECFILE

CAUSE - ZINC PLUG CORRUDED. DURING TESTING, A ZINC PLUG ON DIESEL GENERATOR B SERVICE WATER HEAT EXCHANGER STARTED LEAKING AND WAS REPLACED RESULTING IN THE DIESEL BEING INOPERABLE FOR 20 MINUTES. THE ZINC CORRUDED DUE TO NORMAL USAGE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MILLSTONE POINT 2 (PM2) - REACTOR STARTUP EXPERIENCE - GENERATION, DIESEL - ENGINES, INTERNAL COMBUSTION - TEST, SYSTEM OPERABILITY - PIPES AND PIPE FITTINGS - CORROSION - HEAT EXCHANGERS - AUXILIARY COOLING - LEAK

100356

SERVICE WATER HEADER DEVELOPS A PIN HOLE LEAK AT MILLSTONE 2

NORTHEAST NUCLEAR ENERGY CORP. CORN.

2 PGS. LTR W/AT 75-05 TO NRC OFFICE OF I & E, REGION I, SEPT. 5, 1975, DCKET 50-336, TYPE--PM2, HSG--COMB., AT--BECFILE

CAUSE - CORROSION. DURING NET FUNCTIONAL TESTING, SERVICE WATER HEADER A WAS DECLARED INOPERABLE TO REPAIR A PIN HOLE LEAK. THE LEAK DEVELOPED THROUGH CORROSION OF THE 6 INCH PIPE OFF THE HEADER. A PLATE WAS WELDED OVER THE AREA AND THE HEADER RETURNED TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MILLSTONE POINT 2 (PM2) - REACTOR STARTUP EXPERIENCE - PIPES AND PIPE FITTINGS - AUXILIARY COOLING - CORROSION - LEAK - FAILURE, PIPE

100358

CABLE SHIELDING INSTALLED ON WIDE RANGE NUCLEAR INSTRUMENTATION AT MILLSTONE 2

NORTHEAST NUCLEAR ENERGY CORP. CORN.

2 PGS. LTR W/AT 75-07 TO NRC OFFICE OF I & E, REGION I, SEPT. 5, 1975, DCKET 50-336, TYPE--PM2, HSG--COMB., AT--BECFILE

CAUSE - HIGH NOISE LEVEL. DURING NET FUNCTIONAL TESTING, EACH OF THE 4 WIDE RANGE NUCLEAR INSTRUMENT CHANNELS WAS REMOVED FROM SERVICE ONE AT A TIME TO INSTALL ADDITIONAL CABLE SHIELDING. HIGH NOISE LEVEL UNDER CERTAIN CONDITIONS REQUIRED THE ADDITIONAL SHIELDING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MILLSTONE POINT 2 (PM2) - REACTOR STARTUP EXPERIENCE - NOISE - CABLES AND CONNECTORS - SHIELDING - INSTRUMENT, NUCLEAR - FAILURE, DESIGN ERROR - MODIFICATION

100357

NO CHARGING PUMP FLOW NOTED AT MILLSTONE 2

NORTHEAST NUCLEAR ENERGY CORP. CORN.

2 PGS. LTR W/AT 75-01 TO NRC OFFICE OF I & E, REGION I, SEPT. 5, 1975, DCKET 50-336, TYPE--PM2, HSG--COMB., AT--BECFILE

CAUSE - FLOW INSTRUMENT DE-ENERGIZED. DURING TESTING, NO CHARGING PUMP FLOW WAS NOTED. THE OPERATOR ASSUMED A FLOW MILEAGE. HOWEVER, THE FLOW INSTRUMENT WAS DE-ENERGIZED TO ACCOMPLISH MAINTENANCE. CONTROL BOARD MODIFICATIONS AND THE OPERATOR WAS UNAWARE OF INTERFACE PROBLEMS. ON COMPLETION OF MODIFICATION, THE FLOW INSTRUMENT WAS RE-ENERGIZED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MILLSTONE POINT 2 (PM2) - REACTOR STARTUP EXPERIENCE - PRESSURE, FLOW - OPERATOR - FAILURE, OPERATOR ERROR - ELECTRIC PUMP

100359

TESTING OF CONTAINMENT ISOLATION VALVES NOT PERFORMED WHEN REQUIRED AT MILLSTONE 2

106323 PLANTINURD
NORTHEAST NUCLEAR ENERGY CO., CONN.
2 PGS. LTR W/AD 50-330/75-04 TO NRC OFFICE OF I & E, REGION I, SEPT. 5, 1975. DOCKET 50-330, TYPE--PWR, NRC--COMB.,
AC--BCHTEL

CAUSE - DEFICIENT TEST SCHEDULE. DURING POST-LORE NOT FUNCTIONAL TESTING, SURVEILLANCE TESTING WAS NOT PERFORMED ON CONTAINMENT ISOLATION VALVE AS REQUIRED PRIOR TO ENTERING MODE 4. COMPUTER SURVEILLANCE SCHEDULE WAS NOT DETAILED ENOUGH TO COVER ALL TESTS. THE SCHEDULE FORMAT WAS MODIFIED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 104 CENTS/PAGE -- MINIMUM CHARGE \$2.00

HILLSTONE POINT 2 (PWR) • REACTOR STARTUP EXPERIENCE • TEST INTERVAL • TESTING • FAILURE, ADMINISTRATIVE CONTROL • COMPUTER CONTROL • PROCEDURES AND MANUALS • VALVES • CONTAINMENT ISOLATION

106445
VARIABLE OVERPOWER TRIP SET POINT SHIFT WITH POWER AT HILLSTONE 2
NORTHEAST NUCLEAR ENERGY CO., CONN.
2 PGS. LTR W/AD 50-330/75-03 TO NRC OFFICE OF I & E, REGION I, SEPT. 11, 1975. DOCKET 50-330, TYPE--PWR, NRC--COMB., AC--BCHTEL

CAUSE - UNKNOWN. DURING NOT FUNCTIONAL TESTING PRIOR TO INITIAL CRITICALITY, THE RPS VARIABLE OVERPOWER TRIP SET POINT WAS FOUND TO RAMP UP AS POWER WAS RAMPED UP WITH THE TEST CIRCUIT ON ALL 4 CHANNELS. THE CAUSE IS A DESIGN DEFICIENCY RESULTING IN NOISE IN THE VARIABLE HIGH POWER TRIP CIRCUIT RESETTING THE PEAK DETECTOR. THE INVESTIGATION IS CONTINUING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 104 CENTS/PAGE -- MINIMUM CHARGE \$2.00

HILLSTONE POINT 2 (PWR) • REACTOR STARTUP EXPERIENCE • INSTRUMENTS, MISC. • INSTRUMENT, PROTECTIVE • REACTOR SAFETY SYSTEM • TEST, SYSTEM OPERABILITY • FAILURE, DESIGN ERROR • MISUSE • RESET POINT • INSTRUMENT, POWER RANGE

106599
PRESSURIZER PRESSURE SWITCHES SET NON-CONSERVATIVELY AT HILLSTONE 2
NORTHEAST NUCLEAR ENERGY CO., CONN.
3 PGS. LTR W/AD 50-330/75-08 TO NRC OFFICE OF I & E, REGION I, SEPT. 18, 1975. DOCKET 50-330, TYPE--PWR, NRC--COMB., AC--BCHTEL

CAUSE - CALIBRATION PROCEDURAL DEFICIENCY. DURING TESTING PRIOR TO INITIAL CRITICALITY, PRESSURIZER PRESSURE WAS INCREASED TO TEST THE SRAS UNBLOCK SET POINT OF 1750 PSIA. PRESSURE REACHED 1754 PSIA WITHOUT RESULT. THE MODULES WERE RECALIBRATED. THE PROCEDURE USED DID NOT PROVIDE FOR CONSERVATION IN THE CALIBRATION. PROCEDURES WERE REVISED. THE SRAS AND MSI BLOCK MODULE SET POINTS WERE ALSO REVISED AND RECALIBRATED IN THE CONSERVATIVE DIRECTION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM CHARGE \$2.00

HILLSTONE POINT 2 (PWR) • REACTOR STARTUP EXPERIENCE • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SENSORS, PRESSURE • TEST, SYSTEM OPERABILITY • RESET POINT • FAILURE, INSTRUMENT • PRESSURIZER • FAILURE, ADMINISTRATIVE CONTROL • PROCEDURES AND MANUALS

106114
MECHANICAL SHOCKER FAILS AT HILLSTONE 2
NORTHEAST NUCLEAR ENERGY CO., CONN.
2 PGS. LTR W/AD 50-330/75-11 TO NRC OFFICE OF I & E, REGION I, SEPT. 23, 1975. DOCKET 50-330, TYPE--PWR, NRC--COMB., AC--BCHTEL

CAUSE - INSTALLED WITHOUT REMOVING SET SCREW. DURING A PLANT HEATUP TO 260 F., A MECHANICAL SHOCKER ON A PRESSURIZER SAFETY LINE LOCKED UP RESULTING IN BENDING THE SHAFT OF A SECOND MECHANICAL SHOCKER ON THE SAME LINE. BOTH SEISMIC UNITS WERE REPLACED. PIPING WAS NOT OVERSTRESSED. VENOR ANALYSIS OF THE LOCKED-UP UNIT REVEALED THAT IT HAD BEEN INSTALLED WITH THE PRESET SCREW STILL IN PLACE. LOADING FROM HEATUP CAUSED THE SET SCREW TO SHEAR, INDUCING SUFFICIENT FORCE TO CAUSE THE SHOCKER TO LOCK-UP.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM CHARGE \$2.00

HILLSTONE POINT 2 (PWR) • REACTOR STARTUP EXPERIENCE • SHOCK ABSORBER • SUPPORT STRUCTURE • PIPES AND PIPE FITTINGS • FAILURE, EQUIPMENT • FAILURE, INSTALLATION ERROR

104811
BOTH CONTAINMENT AIR LOCK DOORS OPENED MOMENTARILY AT HILLSTONE 2
NORTHEAST NUCLEAR ENERGY CO., CONN.
2 PGS. LTR W/AD 50-330/75-14 TO NRC OFFICE OF I & E, REGION I, SEPT. 24, 1975. DOCKET 50-330, TYPE--PWR, NRC--COMB., AC--BCHTEL

CAUSE - ENTRY TO REPAIR INNER DOOR SEAL. DURING TESTING OF CONTAINMENT AIR LOCK SEAL LEAKAGE, THE

100011 PLANTINGEJO

INNER GASKET FAILED. IT WAS NECESSARY TO TEMPORARILY OPEN THE OUTER DOOR TO ALLOW ENTRY TO REPLACE THE INNER GASKET. THIS VIOLATED TECH SPECS. THE INNER GASKET WAS REPLACED. A TECH SPEC CHANGE WAS SUBMITTED TO PERMIT TEMPORARY ENTRY FOR REPAIRS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

HILLSTONE POINT 2 (PHM) - REACTOR STARTUP EXPERIENCE - CONTAINMENT INTEGRITY - FAILURE, ADMINISTRATIVE CONTROL - CONTAINMENT AIR LOCK - MAINTENANCE AND REPAIR - SEAL - LEAK - TEST, LEAK RATE - TEST, SYSTEM OPERABILITY

100040

WELD - INSTRUMENT LINE LEAKS AT HILLSTONE 2

NORTHEAST NUCLEAR ENERGY CO., CORP.

3 PGS. LTR W/AD 75-336/75-10 TO NRC OFFICE OF I & E, REGION I, SEPT. 25, 1975, DOCKET 50-336, TYPE--PHM, NRC--COMB., AE--BECHTEL

CAUSE - WELD POROSITY. DURING TESTING PRIOR TO INITIAL CRITICALITY, A LEAK 10.1 TO 0.5 GPM WAS DISCOVERED IN THE DIFFERENTIAL PRESSURE INSTRUMENT ROOT TAP UPSTREAM OF THE ISOLATION VALVE LOCATED ON REACTOR COOLANT PUMP P60A DISCHARGE PIPING. THE PLANT WAS AT 2250 PSIA AND 532F. IT WAS BROUGHT TO COOL SHUTDOWN. THE 1-INCH ELBOW SCKET WELD INDICATED WELD POROSITY. IT WAS GROUND OUT AND REWELDED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

HILLSTONE POINT 2 (PHM) - REACTOR STARTUP EXPERIENCE - MAIN COOLING SYSTEM - SENSORS, PRESSURE - PIPES AND PIPE FITTINGS - LEAK - FAILURE, PIPE - FAILURE, INSTALLATION ERROR - FLAW - WELDS

100037

INADEQUATE ACTUATION OF ALL ESAS SIGNALS AT HILLSTONE 2

NORTHEAST NUCLEAR ENERGY CO., CORP.

3 PGS. LTR W/AD 75-17 TO NRC OFFICE OF I & E, REGION I, SEPT. 25, 1975, DOCKET 50-336, TYPE--PHM, NRC--COMB., AE--BECHTEL

CAUSE - PERSONNEL ERROR. DURING MAINTENANCE OF THE ESAS WITH ONE CHANNEL DEENERGIZED, A SECOND CHANNEL WAS INADVERTENTLY REENERGIZED BY REMOVAL OF A LOGIC POWER SUPPLY FUSE THOUGHT TO BE BLANK. THIS GENERATED ALL ESAS ACTUATION SIGNALS. THE FOLLOWING PROBLEMS RESULTED. DIESEL GENERATOR B CIRCUIT BREAKER DID NOT CLOSE ONTO EMERGENCY BUS 240 DUE TO A BLOWN UNDERSIZED FUSE IN THE 24V POWER SUPPLY. SERVICE WATER PUMP B FAILED TO START FROM A WIRING ERROR MADE DURING A CONTROL SCHEME MODIFICATION. CONTAINMENT AIR RECIRCULATION FANS A AND C DID NOT START IN SLOW SPEED DUE TO A LOOSE ACTUATION DELAY. ALL THESE ERRORS WERE CORRECTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D.C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

HILLSTONE POINT 2 (PHM) - REACTOR STARTUP EXPERIENCE - EMERGENCY POWER, ELECTRIC - PUMPS - AUXILIARY COOLING - DEUMERS - CONTAINMENT AIR COOLING - FAILURE, EQUIPMENT - FAILURE, INSTALLATION ERROR - FAILURE, OPERATOR ERROR - BREAKER

100030

AIR OPERATED VALVE ACCUMULATOR NOT SEISMICALLY QUALIFIED AT HILLSTONE 2

NORTHEAST NUCLEAR ENERGY CO., CORP.

3 PGS. LTR W/AD 75-10 TO NRC OFFICE OF I & E, REGION I, SEPT. 30, 1975, DOCKET 50-336, TYPE--PHM, NRC--COMB., AE--BECHTEL

CAUSE - INADEQUATE DESIGN CONTROL. DURING A REVIEW BY THE AE, IT WAS DETERMINED THAT THE MOUNTING AND DISCHARGE TUBING OF SEVERAL AIR OPERATED VALVE ACCUMULATORS WERE NOT SEISMICALLY QUALIFIED. THE CAUSE WAS INADEQUATE DESIGN CONTROL. ALL ACCUMULATOR MOUNTINGS AND DISCHARGE TUBING SUPPORTS HAVE BEEN UPGRADED TO SEISMIC QUALIFICATIONS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

HILLSTONE POINT 2 (PHM) - REACTOR STARTUP EXPERIENCE - SEISMIC DESIGN - SUPPORT STRUCTURE - ACCUMULATORS - VALVES - REVIEW - FAILURE, DESIGN ERROR - MODIFICATION

100044

FILTERS TESTED USING HIGH FLOW RATES AT HILLSTONE 2

NORTHEAST NUCLEAR ENERGY CO., CORP.

3 PGS. LTR W/AD 75-13 TO NRC OFFICE OF I & E, REGION I, OCT. 1, 1975, DOCKET 50-336, TYPE--PHM, NRC--COMB., AE--BECHTEL

CAUSE - FAILURE TO RECOGNIZE A MODIFICATION. STARTUP TESTS FOR THE ENCLOSURE BUILDING FILTRATION SYSTEM AND THE CONTAINMENT ROOM VENTILATION SYSTEM WERE USED TO FULFILL FILTER SURVEILLANCE REQUIREMENTS. DURING DATA REVIEW, IT WAS DETERMINED THAT TESTS WERE MADE AT FLOW RATES ABOVE THOSE SPECIFIED. HIGHER FLOWS RESULTED FROM RECENTLY IMPLEMENTED DESIGN CHANGES. FLOWS WERE DECREASED TO WITHIN SPECIFICATIONS. TECH SPEC CHANGE FOR THE HIGHER FLOW RATES HAVE NOW BEEN

106644 *CONTINUED*
APPROVED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MILLSTONE POINT 2 (PWR) * REACTOR STARTUP EXPERIENCE * *PLUM * ORATE * *TESTING * FILTERS * VENTILATION SYSTEM * TEST, SYSTEM OPERABILITY * FAILURE, ADMINISTRATIVE CONTROL

106641
DISSOLVED OXYGEN IN REACTOR COOLANT EXCEEDS LIMIT AT MILLSTONE 2
NORTHEAST NUCLEAR ENERGY CO., CORP.
2 PGS. LTR W/AD 75-09 TO NRC OFFICE OF I & E, REGION 1, OCT. 1, 1975, DCKET 50-336, TYPE--PWR, NRC--COMB., AE--BECHTEL

CAUSE - MISINTERPRETATION OF DATA. DURING HOT FUNCTIONAL TESTING, REACTOR COOLANT TEMPERATURE WAS INCREASED TO 260 F WITH DISSOLVED OXYGEN AT 0.266 PPM. RCS WAS COOLED BELOW THE 250 F LIMIT, HYDRAZINE ADDED, AND O₂ REDUCED BELOW 0.1 PPM. THE CAUSE WAS MISINTERPRETATION OF INFORMATION PROVIDED BY CHEMISTRY OPERATIONS. PROCEDURES WERE MODIFIED TO REQUIRE LOGGING OF INFORMATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MILLSTONE POINT 2 (PWR) * REACTOR STARTUP EXPERIENCE * *COOLANT QUALITY * MAIN COOLING SYSTEM * CONCENTRATION * FAILURE, OPERATOR ERROR * OXYGEN * COMMUNICATION

106642
SERVICE WATER PIPING NOT SEISMICALLY QUALIFIED AT MILLSTONE 2
NORTHEAST NUCLEAR ENERGY CO., CORP.
2 PGS. LTR W/AD 75-10 TO NRC OFFICE OF I & E, REGION 1, OCT. 1, 1975, DCKET 50-336, TYPE--PWR, NRC--COMB., AE--BECHTEL

CAUSE - INADEQUATE DESIGN REVIEW. PRIOR TO INITIAL CRITICALITY, IT WAS DISCOVERED THAT THE SERVICE WATER PIPING TO THE SERVICE WATER BOOSTER PUMP WAS NOT SEISMICALLY QUALIFIED. THE NON-QUALIFIED PIPING WAS ISOLATED BY 2 SEISMICALLY QUALIFIED ISOLATION VALVES. THE SYSTEM WILL BE UPGRADED UNPIPED FROM A NON-SEISMIC SOURCE. THERE WAS INADEQUATE DESIGN REVIEW BY THE AE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MILLSTONE POINT 2 (PWR) * REACTOR STARTUP EXPERIENCE * *SEISMIC DESIGN * *PIPES AND PIPE FITTINGS * AUXILIARY COOLING * FAILURE, DESIGN ERROR * REVIEW

106643
AUXILIARY FEEDWATER PUMP GOVERNOR FAILS TO RESPOND AT MILLSTONE 2
NORTHEAST NUCLEAR ENERGY CO., CORP.
2 PGS. LTR W/AD 75-12 TO NRC OFFICE OF I & E, REGION 1, OCT. 1, 1975, DCKET 50-336, TYPE--PWR, NRC--COMB., AE--BECHTEL

CAUSE - WORN MOTOR CLUTCH. DURING THE INITIAL SURVEILLANCE TEST, THE TURBINE DRIVEN AUXILIARY FEEDWATER PUMP GOVERNOR WOULD NOT RESPOND TO SPEED CHANGE SIGNALS. THE WORMWHEEL MODEL PG SPEED CHANGER MOTOR CLUTCH WAS EXCESSIVELY WORN. IT WAS READJUSTED FOR AN INTERIM REPAIR. PARTS ARE ON ORDER FOR REPLACEMENT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MILLSTONE POINT 2 (PWR) * REACTOR STARTUP EXPERIENCE * *CONTROL * *PUMPS * FEEDWATER * COOLING SYSTEM, SECONDARY * TEST, SYSTEM OPERABILITY * FAILURE, COMPONENT * TURBINE

106646
BOTH CONTAINMENT SPRAY HEADERS FOUND INOPERABLE AT MILLSTONE 2
NORTHEAST NUCLEAR ENERGY CO., HARTFORD, CONN.
3 PGS. LTR W/AD 50-336/75-19 TO NRC OFFICE OF I & E, REGION 1, OCT. 7, 1975, DCKET 50-336, TYPE--PWR, NRC--COMB., AE--BECHTEL

CAUSE - PROCEDURAL DEFICIENCY. DURING A CONTAINMENT INSPECTION, 2 CONTAINMENT SPRAY MANUAL ISOLATION VALVES WERE FOUND TO BE CLOSED, MAKING BOTH CONTAINMENT SPRAY HEADERS INOPERABLE. THE VALVES WERE SHUT TO ALLOW RECIRCULATION OF THE RWST. NO WRITTEN PROCEDURE WAS AVAILABLE. DURING VALVE LINEUP PRIOR TO SYSTEM HEATUP, THE VALVES WERE INSPECTED BUT INCORRECTLY DETERMINED TO BE OPEN BY VALVE STEM POSITION. A COMPLETE CS SYSTEM LINEUP WAS PERFORMED. A PROCEDURE WILL BE PREPARED FOR RWST RECIRCULATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MILLSTONE POINT 2 (PWR) * *VALVES * CONTAINMENT ISOLATION * CONTAINMENT SPRAY * *FAILURE, SIMULTANEOUS * FAILURE, ADMINISTRATIVE CONTROL * PROCEDURES AND MANUALS * REWINDANCE * REACTOR STARTUP EXPERIENCE

106576

NINJA SOCKET WELD FLOW LEAKS FOUND IN INSTRUMENT LINES AT HILLSTONE 2
NORTHEAST NUCLEAR ENERGY CO., HARTFORD, CONN.

3 PGS. LTR W/AT 75-336/75-21 TO NRC OFFICE OF I & E, REGION 1, OCT. 14, 1975, DCKET 50-336, TYPE--
PWR, NRC--CUMB., AE--BECHTEL

CAUSE - VIBRATION INDUCED FATIGUE. DURING HOT FUNCTIONAL TESTING, NINJA SOCKET WELD FLOW LEAKS WERE DISCOVERED IN 2 1/2-IN. OP INSTRUMENT ROUT TIPS ON THE REACTOR COOLANT PIPING. EXAMINATION SHOWED THIS WAS FATIGUE FAILURE WITH RELATIVELY LOW LEVELS OF ALTERNATING STRESS. THE REP NUMEROUS FREQUENTLY CORRESPONDED CLOSELY WITH THE ASSEMBLY NATURAL FREQUENCY. THE SECOND ISOLATION VALVE WAS REMOVED FROM THE PIPING ASSEMBLY RESULTING IN A SIGNIFICANT INCREASE IN THE ASSEMBLY RESONANT FREQUENCY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM CHARGE \$2.00)

REACTOR STARTUP EXPERIENCE + PIPES AND PIPE FITTINGS + PNEUMS + PLEAK + FAILURE, PIPE + INSTRUMENTS, MISC. + FAILURE, FATIGUE + VIBRATION + FAILURE, DESIGN ERROR + MODIFICATION + HILLSTONE POINT 2 (PWR)

107422

UPDATE REPORT ON OVERPOWER TRIP SET POINT RAMPING UP AT HILLSTONE 2
NORTHEAST NUCLEAR ENERGY CO., HARTFORD, CONN.

3 PGS. LTR W/AT 50-336/75-03 TO NRC OFFICE OF I & E, REGION 1, OCT. 16, 1975, DCKET 50-336, TYPE--PWR, NRC--
CUMB., AE--BECHTEL

CAUSE - INSTRUMENT NOISE. DURING TESTING PRIOR TO INITIAL CRITICALITY, THE RPS VARIABLE OVERPOWER TRIP SET POINT WAS FOUND TO RAMP UP AS POWER WAS RAMPED UP, AS REPORTED EARLIER. THE CAUSE WAS TRACED TO ELECTRONIC NOISE RESETTING THE VARIABLE OVERPOWER TRIP PEAK DETECTOR. THE NOISE SOURCE WAS CONTACT JACING NOISE FROM THE RPS RELAYS, THE REACTOR TRIP SWITCH GEAR RELAYS, AND THE RELAYS WHICH ILLUMINATE THE VARIABLE HIGH POWER TRIP RESET LIGHTS. THE NOISE WAS SUFFICIENT TO CAUSE RESETTING. A DISCRIMINATOR NETWORK WAS INSTALLED ON THE PEAK DETECTOR RESET LINE TO UNSENSITIVE THE PEAK DETECTOR RESET CIRCUIT SO THAT IT CANNOT BE RESET BY NOISE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM CHARGE \$2.00)

REACTOR STARTUP EXPERIENCE + REACTOR SAFETY SYSTEM + RELAYS + FAILURE, DESIGN ERROR + MODIFICATION + ELECTRONIC FUNCTION UNITS + HILLSTONE POINT 2 (PWR) + NOISE + INSTRUMENT, POWER RANGE

108096

NE CHANNEL TESTS NOT PERFORMED WHEN RCS TEMPERATURE DECREASED AT HILLSTONE 2
NORTHEAST NUCLEAR ENERGY CO., HARTFORD, CONN.

3 PGS. LTR W/AT 50-336/75-22 TO NRC OFFICE OF I & E, REGION 1, NOV. 17, 1975, DCKET 50-336, TYPE--PWR, NRC--
CUMB., AE--BECHTEL

CAUSE - OPER. ATTN. OVERSIGHT. DURING FLOW POWER PHYSICS TESTING, THE REACTOR COOLANT SYSTEM TEMPERATURE WAS DECREASED BELOW 915 F TO 911 F WITHOUT PERFORMING NE CHANNEL FUNCTIONAL TESTS. THE REQUIREMENT WAS OVERLOOKED BY OPERATING AND TEST PERSONNEL. WHEN THE ERROR WAS NOTED, TEMPERATURE WAS INCREASED ABOVE 915 F. TEST PROCEDURES HAVE BEEN MODIFIED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM CHARGE \$2.00)

HILLSTONE POINT 2 (PWR) + REACTOR STARTUP EXPERIENCE + TESTING + INSTRUMENT, NUCLEAR + FAILURE, OPERATOR ERROR + TEST, SYSTEM OPERABILITY + REACTOR STARTUP TESTING

108290

CONCENTRATION OF MANGANESE INCREASES IN LOBSTERS AT HILLSTONE 2
NORTHEAST NUCLEAR ENERGY CO., HARTFORD, CONN.

2 PGS. LTR W/NON-ROUTINE ENVIRONMENTAL RPT. WEN-50-336/75-01 TO NRC OFFICE OF I & E, REGION 1, NOV. 17, 1975, DCKET 50-336, TYPE--PWR, NRC--CUMB., AE--BECHTEL

CAUSE - OPERATION OF UNIT 1. LOBSTER SAMPLES COLLECTED IN NANTIC BAY EXHIBITED A CONCENTRATION OF MANGANESE-54 WHICH IS 10 TIMES GREATER THAN THOSE FROM THE CONTROL STATION. UNIT 1 OPERATED AT CLOSE TO 100% POWER IN THE EARLY PART OF THE QUARTER. UNIT 2 RELEASED NO RADIOACTIVE LIQUIDS. USE CONSEQUENCE TO THE PUBLIC IS OF NO SIGNIFICANCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM CHARGE \$2.00)

CONCENTRATION + MANGANESE + ANIMAL, INVERTEBRATE + FOOD CHAIN + WASTE DISPOSAL + BAY + HILLSTONE POINT 2 (PWR) + SURVEILLANCE PROGRAM

108819

CONDENSATE STORAGE TANK LEVEL DECREASED BELOW LIMIT AT HILLSTONE 2
NORTHEAST NUCLEAR ENERGY CO., HARTFORD, CT

2 PGS. LTR W/AT 50-336/75-25 TO NRC OFFICE OF I & E, REGION 1, DEC. 11, 1975, DCKET 50-336, TYPE--PWR, NRC--
CUMB., AE--BECHTEL

100019 CONTINUED

CAUSE - STARTUP TESTING. DURING POWER ASCENSION TESTING FOLLOWING A REACTOR AND FEED PUMP TRIP, CONDENSATE STORAGE TANK LEVEL DECREASED BELOW THE TECH SPEC LIMIT OF 150,000 GALLONS TO 140,000 GALLONS. FOLLOWING THE FEED PUMP TRIP, IT WAS NECESSARY TO RESTORE AND MAINTAIN STEAM GENERATOR LEVELS WITH 4 MOTOR DRIVEN AUX. FEED PUMPS, LOWERING THE CONDENSATE STORAGE TANK LEVEL. USING ALL TEMPORARY AND PERMANENT MAKEUP SYSTEMS, THE TANK LEVEL WAS RESTORED WITHIN 30 MINUTES. ADDITIONAL TEMPORARY MAKEUP CAPACITY DURING TESTING WILL PREVENT RECCURRENCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MILLSTONE POINT 2 (PHN) + REACTOR STARTUP EXPERIENCE + SYSTEM CAPACITY + STORAGE CONTAINER + TEST, SYSTEM OPERABILITY + CONDENSATION

100018

SET POINT DRIFT IN FLOW DISTABLE AT MILLSTONE 2

NORTHEAST NUCLEAR ENERGY CO., HARTFORD, CT

2 PGS. LTR W/NO 50-336/75-26 TO NRC OFFICE OF I & E, REGION I, DEC. 11, 1975, DUCRET 50-336, TYPE--PHN, MFG--CUMM., AE--BECHTEL

CAUSE - INSTRUMENT DRIFT. DURING APS TESTING WITH THE REACTOR AT ZERO POWER, 1 OF THE 4 LOW FLOW DISTABLE SET POINTS WAS FOUND TO TRIP AT A CALCULATED REACTOR COOLANT FLOW RATE OF 93.2PPH, WHICH IS BELOW THE 95P LIMIT. THE CAUSE WAS ATTRIBUTED TO INSTRUMENT DRIFT. THE GULF ATOMIC MODEL EL 0210 DISTABLE, PART NUMBER ELG 240-0000-F, WAS SATISFACTORILY RECALIBRATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MILLSTONE POINT 2 (PHN) + REACTOR STARTUP EXPERIENCE + INSTRUMENT CALIBRATION + SENSORS, FLOW + ELECTRONIC FUNCTION UNITS + SET POINT + DRIFT + TEST, SYSTEM OPERABILITY + FAILURE, INSTRUMENT + REACTOR SAFETY SYSTEM + INSTRUMENT, SWITCH

100017

DIESEL GENERATOR FAILS TO START AT MILLSTONE 2

NORTHEAST NUCLEAR ENERGY CO., HARTFORD, CT

3 PGS. LTR W/NO 50-336/75-23 TO NRC OFFICE OF I & E, REGION I, DEC. 11, 1975, DUCRET 50-336, TYPE--PHN, MFG--CUMM., AE--BECHTEL

CAUSE - UNKNOWN. DURING POWER ASCENSION TESTING WITH THE REACTOR AT 128 POWER, DIESEL GENERATOR #20 FAILED TO START FOLLOWING A REACTOR/TURBINE TRIP. THE FAILURE COULD NOT BE DUPLICATED IN RETESTS. IT HAS STARTED NORMALLY ON WEEKLY TESTS SINCE THEN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MILLSTONE POINT 2 (PHN) + REACTOR STARTUP EXPERIENCE + GENERATOR, DIESEL + ENGINE, INTERNAL COMBUSTION + TEST, SYSTEM OPERABILITY + FAILURE, EQUIPMENT

100020

SET POINT DRIFT IN CONTAINMENT PRESSURE TRANSMITTER AT MILLSTONE 2

NORTHEAST NUCLEAR ENERGY CO., HARTFORD, CT

2 PGS. LTR W/NO 50-336/75-26 TO NRC OFFICE OF I & E, REGION I, DEC. 11, 1975, DUCRET 50-336, TYPE--PHN, MFG--CUMM., AE--BECHTEL

CAUSE - INSTRUMENT DRIFT. DURING TESTING WITH THE REACTOR AT 208 PDPH, 1 OF THE 4 CONTAINMENT PRESSURE TRANSMITTER TRIP SET POINTS WAS DETERMINED TO BE 5.3 PSIG VS THE 4.75 PSIG LIMIT. THE APPARENT CAUSE WAS INSTRUMENT DRIFT. THE FOXBORO TRANSMITTER, MODEL EL100, PART #0. 4114, WAS SATISFACTORILY RECALIBRATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MILLSTONE POINT 2 (PHN) + REACTOR STARTUP EXPERIENCE + INSTRUMENT, SWITCH + INSTRUMENT CALIBRATION + TEST, SYSTEM OPERABILITY + SET POINT + DRIFT + REACTOR SAFETY SYSTEM + FAILURE, INSTRUMENT + CONTAINMENT + ELECTRONIC FUNCTION UNITS + SENSORS, PRESSURE

109254

TRAC TIME DELAY SETTING FOUND TO BE INCORRECT AT MILLSTONE 2

NORTHEAST NUCLEAR ENERGY CO., HARTFORD, CT

3 PGS. LTR W/NO 50-336/75-27 TO NRC OFFICE OF I & E, REGION I, DEC. 15, 1975, DUCRET 50-336, TYPE--PHN, MFG--CUMM., AE--BECHTEL

CAUSE - INCORRECT CALIBRATION PROCEDURE. DURING A REVIEW OF SURVEILLANCE TESTING, THE TIME DELAY SETTING FOR THE TURBINE RUNBACK ACTUATION CIRCUIT WAS FOUND TO BE INCORRECTLY SET AT 4 SECONDS INSTEAD OF THE TECH SPEC LIMIT OF 2 SECONDS. THE TIME WAS INCORRECTLY SPECIFIED IN THE CALIBRATION PROCEDURE. EACH CHANNEL TIME DELAY WAS RESET CORRECTLY AND THE PROCEDURE WAS REVISED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM

100224 CONTINUOUS
CHANGE 02-001

HILLSTONE POINT 2 (PHN) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • PRELAYS • RESET POINT • PROCEDURES AND
MANUALS • FAILURE, ADMINISTRATIVE CONTROL • REVIEW • REACTOR STARTUP EXPERIENCE

100820

WATER FLOW IN OFF-GAS PIPE AT HILLSTONE 2
NORTHEAST NUCLEAR ENERGY CO., HARTFORD, CT

3 PGS. LTR W/NU 50-336/75-33 TO NRC OFFICE OF I & E, REGION I, DEC. 19, 1975, Docket 50-336, TYPE--PHN, NRC--
COMB., AR--BECHTEL

CAUSE - DESIGN DEFICIENCY. DURING POWER ASCENSION TESTING, WATER WAS FOUND IN THE OFF-GAS PIPE.
A DESIGN DEFICIENCY WAS IDENTIFIED. A PIPE RIFTURE IN THE OFF-GAS PIPEWAY SUMP COULD ALLOW WATER
TO BACK UP THROUGH THE OFF-GAS PIPEWAY DRAIN LINE, FILLING THE OFF-GAS LINE AND RENDERING THE
ENCLOSURE BUILDING FILTRATION SYSTEM INOPERABLE. TEMPORARY CORRECTION WAS INSTALLATION OF A PLUG
AND DRAIN VALVE IN THE OFF-GAS PIPE DRAIN LINE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHANGE 02-001

HILLSTONE POINT 2 (PHN) • REACTOR STARTUP EXPERIENCE • OFFLOAD • PIPES AND PIPE FITTINGS • OFF GAS • FILTERS
• DAMAGE • FAILURE, DESIGN ERROR

100847

DIESEL FUEL OIL SAMPLE LOST AT HILLSTONE 2
NORTHEAST NUCLEAR ENERGY CO., HARTFORD, CT

2 PGS. LTR W/NU 50-336/75-28 TO NRC OFFICE OF I & E, REGION I, DEC. 23, 1975, Docket 50-336, TYPE--PHN, NRC--
COMB., AR--BECHTEL

CAUSE - UNKNOWN. DURING TESTING, A ROUTINE DIESEL 130 FUEL OIL SUPPLY TANK SAMPLE WAS TAKEN AS
REQUIRED. DURING A LATER REVIEW, IT WAS FOUND THAT RESULTS FROM THE SAMPLE HAD NOT BEEN RECEIVED
FROM THE OUTSIDE VENDOR. THE SAMPLE HAD BEEN LOST. THE CAUSE IS UNKNOWN. ATTEMPTS TO TRACE THE
SAMPLE WERE UNSUCCESSFUL. A SUBSEQUENT SAMPLE HAD ACCEPTABLE RESULTS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHANGE 02-001

HILLSTONE POINT 2 (PHN) • REACTOR STARTUP EXPERIENCE • SAMPLING • FUEL, FOSSIL • GENERATOR, DIESEL •
TRANSPORTATION AND HANDLING • CHEMICAL ANALYSIS

100851

SET POINT UNIT IN STEAM GENERATOR PRESSURE CHANNELS AT HILLSTONE 2
NORTHEAST NUCLEAR ENERGY CO., HARTFORD, CT

3 PGS. LTR W/NU 50-336/75-32 TO NRC OFFICE OF I & E, REGION I, DEC. 23, 1975, Docket 50-336, TYPE--PHN, NRC--
COMB., AR--BECHTEL

CAUSE - FAULTY I/I CONVERTERS. DURING POWER ASCENSION TESTING, CHANNELS B AND C OF STEAM
GENERATOR 1 WERE FOUND TO TRIP AT 410 AND 300 PSIA, RESPECTIVELY, INSTEAD OF THE 500 PSIA LIMIT.
THE I/I CONVERTER, WHICH ISOLATES THE ESAS AND RPS COMMON SIGNAL LOOPS WAS REPLACED IN EACH
CHANNEL. TWO OTHER FAILURES OF THE ROCHESTER INSTRUMENT MODEL SC-302 I/I CONVERTERS OCCURRED. A
DECISION WAS MADE TO REPLACE THEM WITH BELL AND HOWELL I/I CONVERTERS, MODEL 10-119.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHANGE 02-001

HILLSTONE POINT 2 (PHN) • REACTOR STARTUP EXPERIENCE • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SENSORS,
PRESSURE • FAILURE, COMPONENT • ELECTRONIC FUNCTION UNITS • RESET POINT • DRIFT • FAILURE, COMMON MODE •
FAILURE, DESIGN ERROR • TEST, SYSTEM OPERABILITY • MODIFICATION

100848

CONTAINMENT PURGE SUPPLY VALVE FAILS TO CLOSE AT HILLSTONE 2
NORTHEAST NUCLEAR ENERGY CO., HARTFORD, CT

2 PGS. LTR W/NU 50-336/75-30 TO NRC OFFICE OF I & E, REGION I, DEC. 23, 1975, Docket 50-336, TYPE--PHN, NRC--
COMB., AR--BECHTEL

CAUSE - DIRT IN SOLENOID VALVE. WHILE SECURING CONTAINMENT PURGE, THE INBOARD CONTAINMENT PURGE
SUPPLY VALVE FAILED TO CLOSE. IT WAS MANUALLY CLOSED. THE SPRING AREA OF THE AIR SUPPLY VALVE
SOLENOID CONTAINED DIRT AND RUST SCALE. THE SOLENOID WAS REPLACED AND THE VALVE RESTORED TO
SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHANGE 02-001

HILLSTONE POINT 2 (PHN) • REACTOR STARTUP EXPERIENCE • VALVES • CONTAINMENT PURGE • FAILURE, EQUIPMENT •
VERUO • SOLENOID

100049

EXCESS DRIFT IN PRESSURIZER PRESSURE CHANNEL AT HILLSTONE 2

NORTHEAST NUCLEAR ENERGY CO., MANTHOUS, CT

3 PGS. LTR W/ENCL. NPT 50-330/75-34 TO NRC OFFICE OF I & E, REGION 1, DEC. 23, 1975, DOCKET 50-330, TYPE--PWR, NRC--COMB., AE--DECEMBER

CAUSE - OPERATIONAL AMPLIFIER FAILURE. DURING TESTING WHILE THE REACTOR WAS AT SUB POWER, CHANNEL 3 PRESSURIZER PRESSURE WAS FOUND TO HAVE EXCESSIVE DRIFT. CHANNEL 4 ALSO HAD DRIFTED BUT WAS STILL OPERABLE. THE OPERATIONAL AMPLIFIERS FOR BOTH CHANNELS WERE REPLACED. THE AMPLIFIERS HAD FAILED BY SATURATING (OUTPUT VOLTAGE BECAME INDEPENDENT OF INPUT). ON THE FOLLOWING DAY, CHANNEL 4 WAS FOUND TO HAVE DRIFTED HIGH AGAIN, OUT OF SPECIFICATION. THE AMPLIFIER WAS AGAIN REPLACED. THESE ARE THE FIRST CASES OF OPERATIONAL AMPLIFIER FAILURES IN 10 MONTHS OF SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 1.8 CENTS/PAGE -- MINIMUM CHARGE \$2.00

HILLSTONE POINT 2 (PWR) • REACTOR STARTUP EXPERIENCE • REACTOR SHUTDOWN • INSTRUMENT CALIBRATION • SENSORS, PRESSURE • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT • ELECTRONIC FUNCTION UNITS • POINT

109253

CONCENTRATION OF RADIOISOTOPES IN MUSSELS EXCEED LIMIT AT HILLSTONE 2

NORTHEAST NUCLEAR ENERGY CO., MANTHOUS, CT

2 PGS. LTR W/ENCL. NPT 50-330/75-33 TO NRC OFFICE OF I & E, REGION 1, DEC. 26, 1975, DOCKET 50-330, TYPE--PWR, NRC--COMB., AE--DECEMBER

CAUSE - WASTE DISPOSAL FROM UNIT 1. MUSSELS COLLECTED AT HILLSTONE POINT COVE EMITTED CONCENTRATIONS OF ⁶⁰Co AND ⁶⁰Cs WHICH WERE 10 TIMES GREATER THAN AT THE CONTROL STATION. UNIT 2 WAS IN STARTUP WITH NO RADIOACTIVE LIQUID EFFLUENTS. UNIT 1 HAD BEEN OPERATED AT NEARLY 100% POWER. THERE APPEARS TO BE A DECREASING TREND IN THE CONCENTRATION OF WASTE ISOTOPES WITH THE PEAK HAVING OCCURRED IN EARLY OR MID-1975. WISE CONSEQUENCES TO THE PUBLIC FROM THESE CONCENTRATIONS ARE OF NO SIGNIFICANCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 1.04 CENTS/PAGE -- MINIMUM CHARGE \$2.00

HILLSTONE POINT 2 (PWR) • CONCENTRATION • ECOSYSTEM, AQUATIC • ANIMAL, INVERTEBRATE • WASTE DISPOSAL • EFFLUENT • RADIOISOTOPE • MONITORING PROGRAM, ENVIRONMENTAL

100455

ELECTRICAL TERMINATION DEFICIENTLY FOUND AT NORTH ANNA 1 AND 2

VIRGINIA ELECTRIC AND POWER COMPANY

3 PGS. LETTER TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, FEBRUARY 22, 1976, DOCKETS 50-330/339, TYPE--PWR, NRC--WEST., AE--STONE C WEBSTER

CAUSE - DEFECTIVE MATERIAL. DURING VERIFICATION CHECKING OF THE M AND J THREE-PHASE SWITCH GEAR PRIOR TO ENERGIZING FOR INITIAL OPERATION, AN OILY FILM WAS OBSERVED ON SOME OF THE CABLE TERMINATIONS. THE OIL WAS SECRETING FROM BETWEEN THE TERMINATION TAPE LAYERS. A CHECK REVEALED OIL ON 553 TERMINATIONS. ALL POWER CABLE TERMINATING WORK WAS STOPPED. TESTS INDICATE THE OIL CAME FROM JUMP-RAM-VILLE TYPE NSG RED OUNSEAL ON DISHOP ELECTRIC FILLER TAPE NO. 125. THESE MATERIALS WERE REMOVED FROM THE APPROVED LIST. ALL POWER CABLES ARE BEING REWOUND USING APPROVED MATERIAL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 1.08 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ELECTRIC POWER • MATERIAL • MODIFICATION • FAILURE, DESIGN ERROR • LUBRICATION • NORTH ANNA 1 (PWR) • INSULATION • NORTH ANNA 2 (PWR) • CONSTRUCTION • CABLES AND CONNECTORS

100000

DEFICIENCY FOUND IN SEPARATION OF SAFETY RELATED CABLES AT NORTH ANNA 1 AND 2

VIRGINIA ELECTRIC & POWER CO., VIRGINIA

2 PGS. LTR W/ENCL. TO NRC OFFICE OF I & E, AUG. 22, 1975, DOCKET 50-330/339, TYPE--PWR, NRC--WEST., AE--STONE C WEBSTER

CAUSE - UNDEFINED SEPARATION CRITERIA. AS A RESULT OF THE DISCOVERY OF A DEFICIENCY IN SEPARATION OF SAFETY RELATED INSTRUMENT AND CONTROL CABLES IN THE CONTROL ROOM, A CONTROL GROUP HAS ESTABLISHED TO DEFINE THE SCOPE OF THE PROBLEM, DEVELOP ADDITIONAL CRITERIA, AND INITIATE DESIGN EFFORT FOR REMEDY. AREAS SUCH AS PROPER SLEEVE SEPARATION, WHICH WAS HERETOFORE UNDEFINED, AND CABLE FREE AIR SEPARATION WERE BETTER DEFINED. THIS GROUP WILL REVIEW ALL EXISTING CABLE INSTALLATION AND MONITOR FUTURE INSTALLATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 1.08 CENTS/PAGE -- MINIMUM CHARGE \$2.00

NORTH ANNA 1 (PWR) • NORTH ANNA 2 (PWR) • CONSTRUCTION • DETAILS AND CONNECTIONS • ENGINEERED SAFETY FEATURE • INDEPENDENCE • REDUNDANCE • NRC DESIGN CRITERIA • FAILURE, DESIGN ERROR • CONTROL PANEL/ROOM

10060 PLANTING
VIRGINIA ELECTRIC & POWER COMPANY, RICHMOND, VIRGINIA
2 PAGES, LETTER WITH REPORT TO NRC OFFICE OF I & E, DEC. 31, 1975, DOCKET 50-404/405, TYPE--PM, NRC--RM, AE--STONE C WEBSTER

CAUSE - DESIGN DEFICIENCY. WHILE REVIEWING THE QUALITY ASSURANCE CATEGORY DESIGNATION FOR DESIGN CONDITIONS, A CATEGORY DISCREPANCY BETWEEN THE STRUCTURAL STEEL SPECIFICATION AND THE PSAM WAS NOTED. SAFETY RELATED EQUIPMENT, MATERIALS, AND COMPONENTS ARE SPECIFIED AS CATEGORY I. THE PSAM PURCHASE SPECIFICATION FOR GENERAL STRUCTURAL STEEL SPECIFIES CATEGORY II AND III LEVEL. A PORTION, 1000 LBS OR 14% OF THE TOTAL WEIGHT, SHOULD MEET CATEGORY I LEVEL. NONE OF THIS STEEL WAS EVER DELIVERED TO THE SITE. PURCHASE SPECIFICATIONS FOR STRUCTURAL STEEL FOR SAFETY RELATED STRUCTURES WILL BE MODIFIED TO MEET CATEGORY I LEVEL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

NORTH ANNA 3 (PM) + NORTH ANNA 4 (PM) + CONSTRUCTION + QUALITY ASSURANCE + STEEL + STRUCTURE + DESIGN
FAILURE, DESIGN ERROR

100200
LETDOWN CLOSURE PADS TO BE DEFICIENT AT NORTH ANNA 3
VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA.
2 PAGES, LETTER WITH REPORT TO NRC OFFICE OF I & E, NOV. 7, 1975, DOCKET 50-404, TYPE--PM, NRC--RM, AE--STONE C WEBSTER

CAUSE - ERROR IN ORIGINAL STRESS ANALYSIS. THE ORIGINAL SPECIFICATIONS FOR THE COILER, WHICH WAS A NEW DESIGN, WERE BASED ON THE ASSUMPTION THAT 1 OF THE 2 JOINTS WOULD BE ON STANDBY AND ONE IN SERVICE. THE STANDBY JOINT WOULD BE USED DURING PERIODS OF MAXIMUM LETDOWN. THE KEY ERROR IN THE ORIGINAL STRESS CALCULATIONS WAS THE INTERPRETATION OF ALLOWABLE STRESS LIMIT FOR COMBINED TENSILE AND MECHANICAL STRESS. THE ALLOWABLE STRESS VALUE WAS TAKEN AT THE AVERAGE TEMPERATURE FOR THE INTERNAL BRIDGEHEAD INSTEAD OF AT THE HIGHEST TEMPERATURE. THE NEW DESIGN TO CORRECT THIS ERROR WILL INCORPORATE AN INCOMPLETE TUBE SHEET IN PLACE OF THE PRESENT STAINLESS STEEL UNIT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

NORTH ANNA 3 (PM) + CONSTRUCTION + HEAT EXCHANGERS + PLANTANT PURIFICATION SYSTEM + STRESS ANALYSIS + FAILURE, DESIGN ERROR + MODIFICATION + MATERIAL

100911
CORRECTIONS OF NEUTRON SHIELD TANK DEFECTS AT NORTH ANNA 3
VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA.
2 PAGES, LETTER WITH REPORT TO NRC OFFICE OF I & E, NOV. 24, 1975, DOCKET 50-404, TYPE--PM, NRC--RM, AE--STONE C WEBSTER

CAUSE - FABRICATION DEFECTS. AS REPORTED EARLIER, UNACCEPTABLE INDICATIONS WERE OBSERVED IN THE WELOS IN THE UPPER SECTION OF THE NEUTRON SHIELD TANK. THE INDICATIONS ADJACENT TO THE PADS WERE CAUSED BY SHARP WELDED CONTIGUOUS TO THE PADS WHICH PROVIDED FAILURE OF THE WELDED MATERIAL WITHIN POST WELD HEAT TREATMENT. INDICATIONS AT THE EDGE OF WELD JOINTS IN THE INTERNAL BRIDGEHEADS AND SHROUD PLATES RESULTED FROM EXCESSIVE WELD UNDERCUT WHICH EXISTED PRIOR TO PWHT. ALL UNACCEPTABLE INDICATIONS HAVE BEEN REMOVED. A REPAIR PROGRAM IS UNDERWAY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

NORTH ANNA 3 (PM) + CONSTRUCTION + WELDS + SUPPORT STRUCTURE + PRESSURE VESSELS + PLANT + HEAT TREATMENT + STRESS + FAILURE, DESIGN ERROR

100631
PELUS ON PLANT CRANE ASSEMBLY FOUND DEFICIENT AT NORTH ANNA 3
VIRGINIA ELECTRIC & POWER COMPANY, RICHMOND, VA.
2 PAGES, LETTER WITH REPORT TO NRC OFFICE OF I & E, DEC. 17, 1975, DOCKET 50-404, TYPE--PM, NRC--RM, AE--STONE C WEBSTER

CAUSE - POOR WELDING. ABOUT 40% OF THE WELDS CONTAINED IN THE TRUCKY CARS OF THE CONTAINMENT PLANT CRANE ASSEMBLY ARE DEFICIENT. DEFICIENCIES INCLUDE (1) FILLET WELDS WITH INSUFFICIENT LEG, (2) BUTT AND FILLET WELDS OF INSUFFICIENT THROAT, (3) UNDERCUTTING OF WELDS IN EXCESS OF SPECIFIED LIMITS, (4) PRESENCE OF UNFILLED CRATERS, AND (5) SMALL AMOUNTS OF REJECTABLE POROSITY. WELDS ON OTHER COMPONENTS ARE OF A MUCH HIGHER QUALITY. THE VENDOR WILL MAKE REPAIRS USING APPROVED PROCEDURES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

NORTH ANNA 3 (PM) + CONSTRUCTION + CRANES + PLANT + CRANE + CONTAINMENT + FAILURE, FABRICATION ERROR

000716
IMPROPER STEAM VALVE LINEUP PREVENTING MAINTENANCE AT HIGGINS I
DUKE POWER COMPANY
3 PAGES, LETTER TO DIRECTORATE OF REGULATORY OPERATIONS REGION 3 (REC), JANUARY 3, 1975, DOCKET 50-267, TYPE--PM, NRC--RM, AE--DUKE

099716 - PURIFICATION

CAUSE - INCOMPLETE VALVE VERIFICATION. DURING THE REFUELING OUTAGE, URCLY HEAT COOLER IS AND ASSOCIATED LOW PRESSURE INJECTION PIPING WERE BEING REFILLED FOLLOWING MAINTENANCE. ALL RED TAGS ASSOCIATED WITH THE MAINTENANCE HAD BEEN PROPERLY REMOVED. HOWEVER, A HIGH POINT VALVE HAD BEEN LEFT OPEN SINCE THE SYSTEM HAD BEEN DRAINING. WATER SPRAYED INTO THE EAST PENETRATION ROOM UNTIL THE VALVE WAS CLOSED. A COMPLETE VALVE VERIFICATION WAS NOT DONE PRIOR TO RETURNING THE SYSTEM TO SERVICE. PROCEDURES WILL BE MODIFIED TO PROVIDE LATER CONTROL DURING MAINTENANCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MAINTENANCE AND REPAIR • CONTAMINATION • REFUELING • FAILURE, ADMINISTRATIVE CONTROL • OCONEE 1 (PWR) • VALUES • LPL

099777

REACTION BUILDING COOLING UNIT LOGIC ERROR AT OCONEE 1

Duke Power Company, North Carolina

3 PAGES, LETTER WITH RE REPORT 75/1 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 2 (R2), JANUARY 20, 1975, DOCKET 50-269, TYPE--PWR, NRC--BOM, AE--DURE

CAUSE - INTERFACE ERROR. DURING REFUELING TESTING OF THE REACTION BUILDING COOLING UNIT, THE 2 OPERATING PANS SHIFTED FROM HIGH SPEED TO LOW SPEED WHEN AN ES CHANNEL TRIPPED AS DESIGNED. HOWEVER, THE TOLLE FAN SENSED THE LOSS OF HIGH SPEED AND STARTED RUNNING AT HIGH SPEED. IT SHOULD NOT HAVE STARTED. THE APPARENT CAUSE IS THE INTERFACE BETWEEN THE NORMAL AND ENGINEERED SAFEGUARDS LOGIC. UNTIL THE LOGIC IS MODIFIED, THE CONTROLLER FOR THE TOLLE FAN WILL BE KEPT IN THE OFF POSITION TO PREVENT STARTING ON AN ES SIGNAL. HOWEVER, THIS PREVENTS AN AUTOMATIC START IF AN OPERATING FAN FAILS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTROL SYSTEM • VENTILATION SYSTEM • BUILDING • MODIFICATION • REFUELING • TEST, SYSTEM OPERABILITY • FAILURE, DESIGN ERROR • OCONEE 1 (PWR) • OTHERS

099768

REACTION COOLANT PRESSURE BUFFER AMPLIFIER FAILS AT OCONEE 1

Duke Power Company, North Carolina

3 PAGES, LETTER WITH RE REPORT 75/1 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 2, JANUARY 21, 1975, DOCKET 50-269, TYPE--PWR, NRC--BOM, AE--DURE

CAUSE - COMPONENT FAILURE. DURING REFUELING OUTAGE TESTING, IT WAS NOTED THAT THE OUTPUT OF THE REACTOR COOLANT PRESSURE BUFFER AMPLIFIER WOULD NOT RESPOND PROPERLY TO ITS INPUT. IT RESPONDED PROPERLY TO INPUTS WHICH CORRESPOND TO PRESSURES UP TO 2005 PSIG BUT WOULD NOT RESPOND TO INPUTS SIMULATING GREATER PRESSURE. THE CAUSE WAS FOUND TO BE A FAULTY OPERATIONAL AMPLIFIER IN THE CIRCUIT. THIS IS REGARDED AS A RANDOM FAILURE. THE AMPLIFIER WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT • INSTRUMENT, AMPLIFIER • REFUELING • TEST, SYSTEM OPERABILITY • MAIN COOLING SYSTEM • OCONEE 1 (PWR) • SENSORS, PRESSURE • ELECTRONIC FUNCTION UNITS

099704

RADIATION EXPOSURES IN EXCESS OF ADMINISTRATIVE LIMITS AT OCONEE 1

Duke Power Company, N.C.

3 PAGES, LETTER WITH RE REPORT 75/1 TO NRC, REGION 2, FEBRUARY 13, 1975, DOCKET 50-269, TYPE--PWR, NRC--BOM, AE--DURE

CAUSE - MISUNDERSTANDING OF LIMITS. ON JAN. 3, 1975, 4 HEALTH PHYSICS TECHNICIANS RECEIVED RADIATION DOSES IN EXCESS OF THE ADMINISTRATIVELY IMPOSED 100 MREM PER WEEK LIMIT. DURING THE REFUELING SHUTDOWN, THE STATION MANAGER GRANTED PERMISSION FOR THESE 4 TO RECEIVE 1000 MREM FOR THAT QUARTER. THE HEALTH PHYSICS SUPERVISOR FAILED TO REALIZE THAT THIS WAS AN EXCEPTION AND, THEREFORE, PERMITTED EXPOSURES HIGHER THAN THE 100 MREM/WEED LIMIT. ACTION IS BEING TAKEN TO REDUCE EXPOSURES FOR CERTAIN JOBS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MAINTENANCE AND REPAIR • PERSONNEL EXPOSURE, RADIATION • FAILURE, ADMINISTRATIVE CONTROL • OCONEE 1 (PWR)

099703

HOT ZERO POWER EJECTED ROD WORTH NOT CALCULATED AT OCONEE 1

Duke Power Company, N.C.

3 PAGES, LETTER WITH RE REPORT 75/2 TO NRC, REGION 2, FEBRUARY 14, 1975, DOCKET 50-269, TYPE--PWR, NRC--BOM, AE--DURE

CAUSE - OVERSIGHT. DUKE POWER WAS INFORMED BY BOW THAT THE HOT ZERO POWER EJECTED ROD WORTHS WERE NOT CALCULATED FOR CORE CONDITIONS AFTER THE FIRST CONTROL ROD GROUP INTERCHANGE. FAILURE WAS DUE TO OMISSION. A PROGRAM FOR THIS CALCULATION HAS BEEN IMPLEMENTED. IN ORDER TO VERIFY THE

100730 CONTINUED

PRELIMINARY CAUSE: A TEST PROGRAM IS BEING DEVELOPED. ALSO, POWER WAS NOT KEPT IN CONTROL AND INSTRUMENTS TO ASSURE FUEL TEMPERATURES WERE NOT BEING USED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE - MINIMUM CHARGE \$2.00

CONTROL AND INSTRUMENTATION + CONTROL ROOM DESIGN + FAILURE, ADMINISTRATION DESIGN + QUALITY CONTROL + DESIGN + MAINTENANCE ERROR + JOURNAL 1 (PWR)

100900

PERSONNEL WATCH INTERLUCKS FAIL AT JOURNAL 1

JUNE POWER COMPANY, N.C.

2 PAGES, LETTER TO U.S. NRC, REGION 2, MARCH 17, 1975, DUCRET 50-269, TYPE--PWR, NRC--BOW, AR--DURE

CAUSE - OUT OF ADJUSTMENT. WHILE THE UNIT WAS IN SHUT-DOWN, ENTRY TO THE REACTOR BUILDING WAS ATTEMPTED THROUGH THE EMERGENCY MATCH. THE OPERATION TURNED THE EMERGENCY MATCH ON IN THE WRONG DIRECTION AND OPENED THE EMERGENCY MATCH. IN ATTEMPTING TO CLOSE THE EMERGENCY MATCH, THE EMERGENCY MATCH MECHANISM BECAME OUT OF ADJUSTMENT WHICH RESULTED IN THE EMERGENCY MATCH REMAINING OPEN. THE EMERGENCY MATCH WAS OPEN. ATTEMPTS TO CLOSE EITHER EMERGENCY MATCH WERE UNSUCCESSFUL. THE EMERGENCY MATCH WAS ADJUSTED AND THE EMERGENCY MATCH RETURNED TO SERVICE. CONTAINMENT INTEGRITY WAS NOT COMPROMISED AT THIS TIME.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE - MINIMUM CHARGE \$2.00

FAILURE, OPERATION ERROR + CONTAINMENT AIR LOCK + CONTAINMENT INTEGRITY + INSTRUMENT, INTERLUCK + FAILURE, MAINTENANCE ERROR + JOURNAL 1 (PWR)

101100

PERSONNEL WATCH INTERLUCKS FAIL AT JOURNAL 1

JUNE POWER COMPANY, N.C.

2 PAGES, LETTER TO U.S. NRC, REGION 2, MARCH 21, 1975, DUCRET 50-269, TYPE--PWR, NRC--BOW, AR--DURE

CAUSE - EXCESSIVE WEAR. ON 3 OCCASIONS, THE PERSONNEL WATCH INTERLUCK MECHANISM BECAME OUT OF ADJUSTMENT RESULTING IN THE INTERLUCKS BEING UNSUCCESSFUL. CONTAINMENT INTEGRITY WAS NOT LOST AT ANY TIME BUT BOTH LOCKS COULD HAVE BEEN KEPT SIMULTANEOUSLY. THE APPARENT CAUSE WAS EXCESSIVE WEAR OF THE WEAR TEETH AND THE PAIR MAKING THE LOCK LENGTH ADJUSTMENT EXTREMELY SENSITIVE. THE INTERLUCKS WERE ADJUSTED EACH TIME. A FURTHER REPAIR/REPLACEMENT WILL BE IF MODIFICATIONS ARE NECESSARY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE - MINIMUM CHARGE \$2.00

CONTAINMENT AIR LOCK + CONTAINMENT INTEGRITY + INSTRUMENT, INTERLUCK + FAILURE, MAINTENANCE ERROR + JOURNAL 1 (PWR)

101600

SETPOINT DRIFT IN PRESSURE TRANSDUCER AT JOURNAL 1

JUNE POWER COMPANY, N.C.

3 PAGES, LETTER WITH AD REPORT 75/4 TO U.S. NRC, REGION 2, APRIL 2, 1975, DUCRET 50-269, TYPE--PWR, NRC--BOW, AR--DURE

CAUSE - CHANGING AMBIENT TEMPERATURE. DURING TESTING OF THE REACTOR COOLANT PRESSURE TRANSDUCERS WHILE THE REACTOR WAS AT 754 PWR, ONE WAS FOUND TO BE OUT OF CALIBRATION BY -2.7%. THE FULL SCALE ERROR WAS -21.0 PSI. THE LIMIT IS 20. THE APPARENT CAUSE WAS EXCESSIVE DRIFT ASSOCIATED WITH CHANGING AMBIENT TEMPERATURE. THE TRANSDUCER WAS RECALIBRATED. PROCUREMENT OF NEW TRANSDUCERS OF A DIFFERENT TYPE IS IN PROGRESS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE - MINIMUM CHARGE \$2.00

REACTOR SAFETY SYSTEM + INSTRUMENT CALIBRATION + FAILURE, INSTRUMENT + INSTRUMENT, SWITCH + TEST, SYSTEM OPERABILITY + FAILURE, DESIGN ERROR + SET POINT + JOURNAL 1 (PWR) + THERMAL TRANSIENT + DRIFT + SENSORS, PRESSURE

101725

DEFECTS FOUND IN A FUEL ROD OF A SPENT FUEL ASSEMBLY AT JOURNAL 1

JUNE POWER COMPANY, N.C.

4 PAGES, LETTER WITH AD REPORT 75/3 TO U.S. NRC, REGION 2, APRIL 13, 1975, DUCRET 50-269, TYPE--PWR, NRC--BOW, AR--DURE

CAUSE - UNKNOWN. DURING THE POST-IRRADIATION EXAMINATION OF SPENT FUEL ASSEMBLIES 11-CYCLE (BURNED), A PERIPHERAL ROD WAS FOUND WITH 2 DEFECTS LOCATED BETWEEN THE FOURTH AND FIFTH INTERMEDIATE SPACER GRIDS. A 1/2 INCH DIAMETER HOLE IN THE CLADDING WAS OBSERVED AND ALSO A SMALL CRACK. THE FUEL ROD DID NOT SHOW ANY GROSS OUTWARD BOW. NO CAUSE HAS BEEN DETERMINED. ANALYSIS OF THE REACTOR COOLANT INDICATE THAT NO FUEL WAS LOST.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE - MINIMUM CHARGE \$2.00

10175 - CONTINUOUS
 1. ADVISE - PUMP RELIABILITY - FLOW - FAILURE - LEAKING - CONTAMINATION - FUEL OIL - MISCUE 1 (PWR)

101947

1. IN PRESSURE SERVICE WITH PUMP OPERATING WITH SECTION VALVE CLOSED AT MISCUE 1
 JUNE POWER COMPANY, N.C.
 3 PAGES, LETTER WITH NO REPORT 75-6 TO U.S. NRC, REGION 2, MAY 7, 1975, DOCKET 50-269, TYPE--PWR, WFG--BEN, AE--DUNE

CAUSE - CHECK LIST NOT COMPLETED. LOW PRESSURE SERVICE WATER PUMP 6 WAS REMOVED FROM SERVICE FOR PUMP MAINTENANCE. THE CHECKLIST LISTED THE PUMP SECTION VALVE BROKEN AS BEING OPEN BUT NOT THE VALVE BEING CLOSED. WHEN THE PUMP WAS RETURNED TO SERVICE, THE BREAKER WAS CLOSED BUT THE VALVE WAS NOT OPENED. PUMP AMPERAGE WAS NOT MONITORED WHEN THE PUMP WAS STARTED BECAUSE THE MAINTENANCE MENHAD NOT HAVE ADJUSTED IT. THE PUMP WAS OPERATED SEVERAL HOURS BEFORE THE ERROR WAS DISCOVERED. THE PUMP WAS OPENED AND RETURNED TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MISCUE 1 (PWR) - PUMPS - AUXILIARY CIRCUL - VALVES - RELIABLE, MAINTENANCE ERROR - PRACTICES AND PROCEDURES - MAINTENANCE AND REPAIR

102028

RECORD 1 TRIP DURING EMERGENCY START TEST AT MISCUE 1
 JUNE POWER COMPANY, N.C.
 3 PAGES, LETTER WITH NO REPORT 75-6 TO U.S. NRC, REGION 2, MAY 16, 1975, DOCKET 50-269, TYPE--PWR, WFG--BEN, AE--DUNE

CAUSE - INSUFFICIENT CONTROL IN EMERGENCY START TEST. DURING A REHEAT SYSTEM EMERGENCY START TEST PERFORMED FROM THE REHEAT CONTROL ROOM, REHEAT 2 STARTED BUT TRIPPED 4 SECONDS LATER DUE TO A LOW FUEL OIL LEVEL SIGNAL. WHEN THE UNIT IS OPERATED IN THE UNLOADED CONDITION, THE LOW FUEL OIL LEVEL WAS NOT SUFFICIENT TO CONTROL THE UNIT SPEED. SPEED OSCILLATED BETWEEN 90 AND 100 RPM. THIS RESULTED IN SHUTTING OFF THE OIL WHICH CAUSED A LOW LEVEL INDICATION. THE OIL LEVEL PUMP WAS LUNDED 1/4 IN. AND THE UNIT TESTED SUCCESSFULLY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MISCUE 1 (PWR) - EMERGENCY PUMP, ELECTRICAL - TEST, SYSTEM OPERABILITY - RELIABLE, INSTRUMENT - SENSORS, LEVEL - LOGIC/ALARM - CONTROL

102143

PROCESS RADIATION MONITOR FAILS DURING A RELEASE AT MISCUE 1
 JUNE POWER COMPANY, N.C.
 2 PAGES, LETTER WITH NO REPORT 75-6 TO U.S. NRC, REGION 2, MAY 20, 1975, DOCKET 50-269, TYPE--PWR, WFG--BEN, AE--DUNE

CAUSE - GASKET LEAK. DURING A RADIATION LIQUID WASTE RELEASE FROM A CONDENSATE MONITOR TANK, A PROCESS RADIATION MONITOR BECAME INOPERABLE. THE RELEASE WAS TERMINATED. WATER WAS LEAKED FROM A GASKET BETWEEN THE SAMPLE AND DETECTOR WELL INTO THE DETECTOR JUNCTION BOX CAUSING THE COMPUTER TO INDICATE ERROR. THE JUNCTION BOX WAS REPAIRED. A NEW GASKET WAS INSTALLED BETWEEN THE DETECTOR WELL AND SAMPLER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MISCUE 1 (PWR) - RADIATION MONITORS - SEAL - LEAK - FAILURE, COMPONENT - WASTE DISPOSAL

102985

MURON CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT MISCUE 1
 JUNE POWER COMPANY, CHARLOTTE
 1 PG. LTR TO NRC, REGION 2, JUNE 6, 1975, DOCKET 50-269, TYPE--PWR, WFG--BEN, AE--DUNE

CAUSE - IMPROPER CALCULATIONS. A RELEASE RATE FOR WASTES WAS CALCULATED BASED UPON THE ACTIVITY OF THE SAMPLE TO BE 50 GPM. HAD THE RELEASE BEEN CALCULATED UPON MURON CONCENTRATION, THE RATE WOULD HAVE BEEN 24 GPM. THE PUMP RELEASE RATE RESULTED IN A RELEASE CONCENTRATION AT THE MISCUE RIVER OF 0.32 PPM MURON EXCEEDING THE 0.2 PPM LIMIT. TO PREVENT RECURRENCE, A RELEASE RATE WILL BE CALCULATED FOR EACH PARAMETER FOR WHICH ANALYSIS WAS PERFORMED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MISCUE 1 (PWR) - MURON - CONCENTRATION - EFFLUENT - WASTE DISPOSAL, LIQUID - WASTE DISPOSAL - FAILURE, OPERATION ERROR - MATHEMATICAL TREATMENT - RIVER

103457

SET POINT TRIP IN PRESSURE SWITCHES AT MISCUE 1, 2, AND 3
 JUNE POWER CO., CHARLOTTE, N.C.
 3 PAGES, LETTER WITH NO REPORT 75-6 TO NRC, REGION 2, JUNE 12, 1975, DOCKET 50-269, TYPE--PWR, WFG--BEN, AE--DUNE

103007 ALJ211000

CAUSE - INSTRUMENT ERROR. DURING AN AUDIT, IT WAS DETERMINED THAT 5 MPS REACTION PURIFICATION UNIT PRESSURE DROP SWITCH SET POINTS HAD EXCEEDED THE 0.2 PSI LIMIT BY 0.2 TO 0.10 PSI. SWITCHES IN EACH OF THE 3 UNITS WERE INSULATED. MPS SET POINTS WERE REDUCED 2 YEARS LATER TO MATCH THE LIMIT. THESE SWITCHES WERE INCIDENTALLY JUSTIFIED IN THIS RECALIBRATION. THE SWITCHES WERE RESET TO 0.2 PSI. PROBLEMS WERE REPORTED TO INCLUDE THIS CHANGE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONNE 1 (PWR) • UCONNE 2 (PWR) • UCONNE 3 (PWR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SETPOINTS, PRESSURE • TEST, SYSTEM OPERABILITY • SET POINT • ERROR • DESIGN • REACTOR SAFETY SYSTEM • FAILURE, ADMINISTRATIVE CONTROL • PROCEDURES AND MANUALS

103009

REACTOR COOLANT SYSTEM OPENED ON AN INCORRECT UNIT AT UCONNE 1
DUKE POWER COMPANY, N.C.

3 PAGES. LETTER WITH ADJN 75-9 TO NRC, REGION 2, JUNE 12, 1975, DCKET 50-209, TYPE--PWR, NRC--DCN, RE--NONE

CAUSE - OPERATOR ERROR. DURING REPLACEMENT OF THE UNIT 2 PURIFICATION DEMINERALIZER DESIGN, THE DRAIN VALVE FOR UNIT 1 PURIFICATION DEMINERALIZER WAS INCORRECTLY OPENED INSTEAD OF THE DRAIN VALVE FOR UNIT 2 PURIFICATION DEMINERALIZER. THE CONTROL OPERATOR IMMEDIATELY NOTED A DECREASE IN UNIT 1 LITHIUM STORAGE TANK LEVEL. THE ERROR WAS LOCATED AND CORRECTED. THESE VALVES WERE LABELED WITH A TAPWAL WHICH HAD DIFFICULTY BEING READ. THIS WAS A CONTRIBUTING CAUSE. NEW VALVE MARKERS WERE MADE. OPERATOR INSTRUCTED TO PROPERLY IDENTIFY VALVES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONNE 1 (PWR) • PWR • COOLANT PURIFICATION SYSTEM • DEMINERALIZERS • FAILURE, OPERATOR ERROR • IDENTIFICATION

104000

REACTOR COOLANT SYSTEM LEAKAGE WITH AT UCONNE 1
DUKE POWER COMPANY, N.C.

3 PAGES. LETTER WITH ADJN 75-9 TO U.S. NRC, REGION 2, JULY 9, 1975, DCKET 50-209, TYPE--PWR, NRC--DCN, RE--NONE

CAUSE - INTERLOCK FAILURE. WHILE THE UNIT WAS OPERATING AT FULL POWER, THE OPERATOR IDENTIFIED A DECREASING LEVEL IN THE LITHIUM STORAGE TANK INDICATING A LEAKAGE OF ABOUT 40 GPM OUTSIDE THE REACTOR BUILDING. A REACTOR SHUTDOWN WAS INITIATED. A POSITION SWITCH ON THE OUTLET VALVE TO UNIT 2 FROM THE SPARE PURIFICATION DEMINERALIZER FAILED INDICATING AN OPEN VALVE. THIS WAS INTERLOCKED TO CAUSE THE INLET FROM UNIT 1 TO THE SPARE PURIFICATION DEMINERALIZER. THE RESULTING BACKLOG CAUSED PRESSURE INCREASES AND RELIEF VALVE ACTUATIONS. A BYPASS AROUND THE DEMINERALIZER WAS OPENED AND THE RELIEF VALVE CLOSED STOPPING THE LEAKAGE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONNE 1 (PWR) • PWR • VALVES • PRESSURE RELIEF • COOLANT PURIFICATION SYSTEM • FAILURE, INSTRUMENT • INSTRUMENT, INTERLOCK • REACTOR SHUTDOWN • REACTOR COOLANT

104200

REQUIRED EMERGENCY POWER SOURCE NOT PROVIDED AT UCONNE 1

DUKE POWER COMPANY, N.C.

3 PAGES. LETTER WITH ADJN 75-9 TO U.S. NRC, REGION 2, JULY 10, 1975, DCKET 50-209, TYPE--PWR, NRC--DCN, RE--NONE

CAUSE - DISPATCHER'S ERROR. WITH UNITS 1 AND 3 AT FULL POWER AND UNIT 2 SHUTDOWN, REACTOR WINDUP STATION 2 WAS DECLARED INOPERABLE AND WAS NOT REPAIRED WITHIN THE REQUIRED 2-HR PERIOD. A LEE COMBUSTION TURBINE WAS PLACED IN SERVICE ON A NON-ISOLATED 100 KV TRANSMISSION LINE INSTEAD OF AN ISOLATED LINE BECAUSE OF TRANSFORMERS IN THE AREA. IT TRIPPED IN 20 MINUTES. REACTOR 2 SHUTDOWN WAS IMPROPERLY ADJUSTED. IT WAS READJUSTED. THE DISPATCHER WAS REMINDER OF THE UNIQUE REQUIREMENTS OF A REACTOR STATION WITH REGARD TO EMERGENCY POWER SOURCES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONNE 1 (PWR) • FAILURE, OPERATOR ERROR • FAILURE, EQUIPMENT • WEATHER, SEVERE • EMERGENCY POWER, ELECTRIC

104207

EFFLUENT DISCHARGE ISOLATION VALVE FAILS TO CLOSE AT UCONNE 1

DUKE POWER COMPANY, N.C.

3 PAGES. LETTER WITH ADJN 75-9 TO U.S. NRC, REGION 2, JULY 10, 1975, DCKET 50-209, TYPE--PWR, NRC--DCN, RE--NONE

CAUSE - DESIGN ERROR. WHILE TESTING THE LIQUID EFFLUENT MONITORS DURING A LIQUID WASTE RELEASE, 1 OF THE 2 EFFLUENT DISCHARGE ISOLATION VALVES FAILED TO CLOSE WHEN AN ALARM WAS RECEIVED DURING

100007 - CONTINUATION

The pressure vessel. The release was terminated. The differential pressure seen by the valve within a normal release is 50 psi. When the low-pressure station pumps are used the differential is 100 psi. This lifts the valve off its seat and allows 320 ft/min. A modification has been completed to deactivate the pumps in the event of an effluent alert alarm.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 1 (PWR) - PHYSICS - CONTAINMENT ISOLATION - WASTE TREATMENT - TEST, SYSTEM OPERABILITY - FAILURE, DESIGN ERROR - PRESSURE LOSS

100090

ON 10 PPM WAS NOTED EXCESS LEAK AT OCONEE 1, 2, AND 3
DUNE POWER COMPANY, CHARLOTTE NC

2 PGS, LTR W/AMR 75-11 TO NRC, REGION 2, AUG. 15, 1975, DCKET 50-209, TYPE--PWR, NRC--DEN, AE--DUNE

CAUSE - LEAKING PIPE. A ROUTINE SAMPLE OF THE WANO DRAINS INDICATED A PH OF 9.0. THE UPPER LIMIT IS 0.5. THE CAUSE WAS A LEAK IN THE DISCHARGE PIPE FROM THE WASTE TREATMENT PUMP SUMP PUMP. THIS CAUSE CAUSED WATER TO LEAK INTO A DRAINAGE DITCH. VALVES IN THIS LINE HAD BEEN CLOSED FOR AN APPARENT REASON. THIS GREATLY INCREASED THE LEAKAGE. THE PIPE WAS REPLACED. THE VALVES HAVE BEEN TIGHTENED TO PREVENT UNAUTHORIZED OPERATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 1 (PWR) - OCONEE 2 (PWR) - OCONEE 3 (PWR) - WATER QUALITY - EFFLUENT - DRAINAGE

100091

MODIFICATION COMPLETED WITHOUT PWR AUTHORIZATION AT OCONEE 1

DUNE POWER COMPANY, CHARLOTTE NC

2 PGS, LTR W/AMR 75-11 TO NRC, REGION 2, AUG. 15, 1975, DCKET 50-209, TYPE--PWR, NRC--DEN, AE--DUNE

CAUSE - MISUNDERSTANDING OF REQUIREMENTS. ON AUG. 22, 1975, A REQUEST FOR MODIFICATION TO THE WANO TREATMENT GENERATORS AND RECIRC WANO GENERATORS WAS INITIATED BY DUNE PERSONNEL EXTERNAL TO THE STATION ORGANIZATION. THE COMPLETE MODIFICATION PACKAGE WAS FORWARDED FOR APPROPRIATE STATION REVIEW, COMMITTEE REVIEW AND APPROVAL. THE MODIFICATION WAS COMPLETED PRIOR TO RECEIVING APPROVAL. THE APPARENT CAUSE WAS A MISUNDERSTANDING OF THE APPROVALS REQUIRED BY THE PROSECUTOR. THE INCIDENT WAS DISCOVERED DURING A REVIEW OF RECORDS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 1 (PWR) - MISUNDERSTANDING - FAILURE, ADMINISTRATIVE CONTROL - COMMUNICATION - PLANT PROTECTIVE SYSTEM - DELAYS

100092

DEFECTIVE FUEL ROD DISCOVERED AT OCONEE 1

DUNE POWER COMPANY, CHARLOTTE NC

2 PGS, LTR W/AMR 75-11 TO NRC, REGION 2, AUG. 20, 1975, DCKET 50-209, TYPE--PWR, NRC--DEN, AE--DUNE

CAUSE - UNKNOWN. DURING POST-IRRADIATION EXAMINATION OF ONCE-BURNED FUEL ASSEMBLIES, 2 DEFECTIVE FUEL RODS WERE FOUND. ONE OF WHICH WAS REPORTED EARLIER. THE SECOND ONE IS ALSO A PERIPHERAL ROD. THE DEFECT, A 1/4 INCH DEBRISER HOLE IN THE CLADDING, IS LOCATED BETWEEN THE SECOND AND THIRD INTERMEDIATE SPACER SHIMS FROM THE TOP. FUEL WAS PRESENT AT THE HOLE. NO ABNORMAL CORROSION WAS IDENTIFIED THAT COULD HAVE AFFECTED THE INTEGRITY OF THE FUEL ROD. ONLY 2 OF THE 400 PERIPHERAL FUEL RODS SEEMED TO BE DEFECTIVE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 1 (PWR) - FAILURE, CLADDING - FUEL ELEMENTS - CLADDING - EXAMINATION

100170

BALANCE EMERGENCY POWER SOURCE REMOVED FROM SERVICE IMPROPERLY AT OCONEE 1

DUNE POWER COMPANY, CHARLOTTE NC

2 PGS, LTR W/AMR 75-11 TO NRC, REGION 2, AUG. 29, 1975, DCKET 50-209, TYPE--PWR, NRC--DEN, AE--DUNE

CAUSE - MAINTENANCE ERROR. WITH ALL 3 REACTORS OPERATING, KEONEE HYDRO STATION 1 BATTERY WAS REMOVED FROM SERVICE FOR CHARGING. LATER, BATTERY 2 WAS PLACED IN EMERGENCY LOCKOUT FOR MAINTENANCE WHICH DISABLED ITS EMERGENCY START ENGINEERED SAFEGUARDS SIGNAL. THE SHIFT SUPERVISOR IMMEDIATELY ORDERED THE BATTERY CHARGE TO BE TERMINATED AND THE BATTERY PLACED IN SERVICE. THE MAINTENANCE PERSONNEL DID NOT OBTAIN PERMISSION PRIOR TO REMOVING A KEONEE UNIT FROM SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 1 (PWR) - EMERGENCY POWER, ELECTRIC - MAINTENANCE AND REPAIR - REDUNDANCE - FAILURE, MAINTENANCE ERROR

105537

MEASURED LEVEL OF AIRBORNE RADIOACTIVITY EXCEEDS CONTROL LEVEL AT OCONEE 1, 2, AND 3
 JUNE POWER CO., CHARLOTTE
 1 PGS. LTR W/AD-209/75-12 TO U.S. NRC, REGION II, SEPT. 2, 1975, Docket 50-269/270/281, TYPE--PWR, HPG--BLM, AE--DUKE

CAUSE - BACKGROUND FLUCTUATIONS. RESULTS OF THE AIR PARTICULATE SAMPLE FROM LOCATION 9, TAKEN DURING JUNE, INDICATED A SIGNIFICANT VALUE WHICH WAS GREATER THAN 4 TIMES THE CONTROL VALUE. BASED ON THE LAST 6 MONTHS DATA, THE JUNE CONTROL VALUE WAS LOWER AND THE SAMPLE VALUE ABOUT THE SAME. BACKGROUND FLUCTUATIONS ARE THOUGHT TO BE THE CAUSE OF THIS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 1 (PWR) + OCONEE 2 (PWR) + OCONEE 3 (PWR) + EFFLUENT + CONCENTRATION + STRONTIUM + MONITORING SYSTEM, RADIATION + AIRBORNE RELEASE

A-7444

DIAMETER WATER STORAGE TANK LEVEL LOW AT OCONEE 1
 JUNE POWER CO., CHARLOTTE, N.C.
 2 PGS. LTR W/AD-209/75-12 TO U.S. NRC, REGION II, OCT. 21, 1975, Docket 50-269, TYPE--PWR, HPG--BLM, AE--DUKE

CAUSE - USE OF OUT-OF-DATE PROCEDURES. WHILE RECIRCULATING THE DIAMETER WATER STORAGE TANK FOR PURIFICATION WITH THE HEATER AT 100% POWER, A LOW TANK LEVEL ALARM WAS RECEIVED. THE Suction LOSS CONTROL VALVE BETWEEN THE TANK AND THE SPENT FUEL POND WAS OPEN. THUS, THE TANK WAS BEING DRAINED INTO THE SPENT FUEL POND. THE VALVE WAS CLOSED AND THE LEVEL RESTORED. AN OUT-OF-DATE PROCEDURE WAS USED EARLIER WHILE PLACING THE SPENT FUEL POND IN RECIRCULATION. THE OPERATOR INVOLVED WAS COUNSELLED TO USE PROPER PROCEDURES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 1 (PWR) + STORAGE CONTAINER + CHEMICAL SHIM + SYSTEM CAPACITY + FAILURE, OPERATOR ERROR + PROCEDURES AND MANUALS

107227

INADEQUATE CONTROL OF ISOLATED 100 KV TRANSMISSION LINE AT OCONEE 1
 JUNE POWER CO., CHARLOTTE, N.C.
 3 PGS. LTR W/AD-209/75-12 TO U.S. NRC, REGION II, OCT. 24, 1975, Docket 50-269, TYPE--PWR, HPG--BLM, AE--DUKE

CAUSE - DESIGN DEFICIENCY. IT WAS DETERMINED THAT OCONEE DOES NOT HAVE CONTROLS TO ASSURE THAT THE 100 KV TRANSMISSION LINE FROM LEE STATION REMAINS ISOLATED WHEN USED AS BACKUP EMERGENCY POWER. THE LINE PROVIDES A BACKUP SOURCE TO ONE CUSTOMER IF ITS NORMAL POWER IS DEENERGIZED. THE DESIGN OF THE CUSTOMER TIE DID NOT CONSIDER THE NEED TO ISOLATE THIS LINE. MODIFICATIONS TO ENABLE OCONEE TO REMOVALY REMOVE LOADS FROM THE LINE IS IN PROGRESS. IN THE INTERIM, THE TIE TO THE LINE HAS BEEN MANUALLY DISABLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 1 (PWR) + POWER TRANSMISSION + EMERGENCY POWER, ELECTRIC + INDEPENDENCE + FAILURE, DESIGN ERROR + CONTROL

108284

OCONEE HYDRO UNIT 2 FAILS TO AUTOSTART AT OCONEE 1
 JUNE POWER CO., CHARLOTTE, N.C.
 3 PGS. LTR W/AD-209/75-13 TO U.S. NRC, REGION II, NOV. 21, 1975, Docket 50-269, TYPE--PWR, HPG--BLM, AE--DUKE

CAUSE - BINDING IN BREAKER LINKAGE. WHILE ALL 3 UNITS WERE OPERATING, AN ATTEMPT TO START OCONEE HYDRO UNIT 2 FROM THE OCONEE CONTROL ROOM FAILED. MECHANICAL BINDING IN THE GENERATOR SUPPLY BREAKER LINKAGE FROM THE CLOSING COIL TO THE AUXILIARY CONTACTS PREVENTED THE BREAKER FROM CLOSING. THE BREAKER WAS CLEANED AND REPAIRED AND RETURNED TO SERVICE IN 7.5 HOURS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 1 (PWR) + EMERGENCY POWER, ELECTRIC + BREAKER + TEST, SYSTEM OPERABILITY + FAILURE, MAINTENANCE ERROR

109298

BORON CONCENTRATION IN ROUSE RIVER EXCEEDS LIMIT AT OCONEE 1, 2, AND 3
 JUNE POWER CO., CHARLOTTE, NC
 2 PGS. LTR W/AD-209/75-12 TO U.S. NRC, REGION II, NOV. 20, 1975, Docket 50-269/270/281, TYPE--PWR, HPG--BLM, AE--DUKE

CAUSE - MISCALCULATION OF RELEASE RATE. THE UNIT 3 SPENT FUEL POND WAS DRAINED TO THE UPPER SETTLING BASIN IN PREPARATION FOR INSTALLATION OF NEW SPENT FUEL RACKS. IN CALCULATING THE RELEASE RATE FROM THE UPPER BASIN TO THE LOWER POND, A RELEASE RATE OF 50 GPM WAS ASSUMED FROM THE LOWER POND. HOWEVER, THE ACTUAL RELEASE RATE WAS 350 GPM RESULTING IN A BORON CONCENTRATION OF 1.03 PPM IN THE ROUSE RIVER. THE LIMIT IS 0.2 PPM. THE ERROR WAS DISCOVERED AND CORRECTED AFTER 48 HOURS. DURING THIS 48 HOURS, THE HYDRO PLANT OPERATED FOR 15.8 HOURS WHICH REDUCED

100700 MONITORING
CALCULATION TO DETERMINE PPM DURING THIS PERIOD.

AVAILABILITY - ONE PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

LEADER 1 (PUM) + LEADER 2 (PUM) + LEADER 3 (PUM) + CONCENTRATION + PUMPHOUSE + EFFLUENT + WASTE DISPOSAL + RIVER
+ FAILURE, ADMINISTRATIVE CONTROL + RELEASE RATE

100705
RELEASE RATE OF TRITIUM EXCEEDS LIMIT AT OCONEE 1
JUNE PUMPHOUSE, CHARLOTTE, NC.
2 PGS. LTR 0000-200/75-14 TO U.S. NRC, REGION II, DEC. 22, 1975, SUBJECT 50-209, TYPE--PWR, HFC--DCN, AE--ORNL

CAUSE - PERSONNEL ERROR. THE CONTENTS OF CONDENSATE TEST TANK B WERE RELEASED AT A FLOW RATE OF
40 GPM FOR 30 MINUTES. THIS RATE EXCEEDED THE MAXIMUM RECOMMENDED RATE OF 30 GPM AS DETERMINED
BY STATION HEALTH PHYSICS. UPON RECEIPT OF THE RECOMMENDATION, THE OPERATOR MISREAD THE VALUE AS
30 GPM INSTEAD OF 30 GPM.

AVAILABILITY - ONE PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

LEADER 1 (PUM) + RELEASE RATE + POSITION + WASTE DISPOSAL + FAILURE, OPERATION ERROR + PROCEDURES AND MANUALS

100710
API SYSTEM VALVES PLUNGED MANUALLY INOPERABLE AT OCONEE 1
JUNE PUMPHOUSE, CHARLOTTE, NC.
2 PGS. LTR 0000-200/75-9 TO U.S. NRC, REGION II, DEC. 10, 1975, SUBJECT 50-209, TYPE--PWR, HFC--DCN, AE--ORNL

CAUSE - IMPROPER PLUNGING SWITCH SETTING. DURING A TEST WITH THE REACTOR AT 100% POWER, 2 LOW
PRESSURE INJECTION MANUVAL ISOLATION VALVES COULD NOT BE OPERATED MANUALLY. THEY WERE CYCLED
ELECTRICALLY. THE TUNING SWITCH ON THE VALVE MOTOR CONTROLLERS HAD BEEN IMPROPERLY SET CAUSING
THE VALVE TO STAY TOO SECURELY. THE SETTING WAS PROPERLY ADJUSTED AND THE VALVES WERE
SUCCESSFULLY TESTED.

AVAILABILITY - ONE PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

LEADER 1 (PUM) + VALVES + CONTAINMENT ISOLATION + SAFETY INJECTION + TEST, SYSTEM OPERABILITY + FAILURE,
MAINTENANCE ERROR + INSTRUMENT, SENSOR + SET POINT

100717
ADDITIONAL INFORMATION ON RADIOACTIVITY IN AQUATIC VEGETATION AT OCONEE 1, 2, AND 3
JUNE PUMPHOUSE, CHARLOTTE, NC.
2 PGS. LTR 0000-200/75-14 TO U.S. NRC, REGION II, DEC. 22, 1975, SUBJECTS 50-209/270/287, TYPE--PWR, HFC--DCN, AE--ORNL

CAUSE - RIVER FLOW CONDITIONS. AS REPORTED PREVIOUSLY, A MEASURED LEVEL OF RADIOACTIVITY FROM AN
AQUATIC VEGETATION SAMPLER EXCEEDED THE CRITICAL LEVEL BY GREATER THAN 10 TIMES. THE BUILDUP IS
EXPECTED IN THE FRESHWATER AREA. DESCRIBES THE METHOD OF CALCULATING THE BUILDUP AND COMPARES
WITH SAMPLE RESULTS. THE SAMPLE AREA IS AFFECTED BY WINDY PLANT OPERATION. CONCENTRATIONS ARE
GIVEN HIGH AND LOW FLOW CONDITIONS THEN IN THE WATTS RIVER STREAM.

AVAILABILITY - ONE PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

LEADER 1 (PUM) + LEADER 2 (PUM) + LEADER 3 (PUM) + CONCENTRATION + VEGETATION, AQUATIC + SAMPLING + WASTE
DISPOSAL + RIVER + EFFLUENT + MATHEMATICAL TREATMENT + COMPARISON, THEORY AND EXPERIENCE

100720
TRITIUM CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT OCONEE 1, 2, AND 3
JUNE PUMPHOUSE, CHARLOTTE, NC.
2 PGS. LTR 0000-200/75-14 TO U.S. NRC, REGION II, DEC. 23, 1975, SUBJECTS 50-209/270/287, TYPE--PWR, HFC--DCN, AE--ORNL

CAUSE - SAMPLING METHOD. THE TRITIUM CONCENTRATION IN A COMPOSITE WATER SAMPLE COLLECTED OVER A
QUARTER EXCEEDED THAT AT THE CONTROL STATION BY GREATER THAN 10 TIMES. THE SAMPLE WAS
REPRESENTATIVE ONLY OF THE CONCENTRATION WHEN THE 3 GALS SAMPLES WERE COLLECTED. A CONTINUOUS
COMPOSITE SAMPLER HAS BEEN INSTALLED BUT IT DOES COMPENSATE FOR FLOW PAST THE SAMPLER. ACTUAL
AVERAGE CONCENTRATION IS LESS THAN EITHER SAMPLE INDICATES.

AVAILABILITY - ONE PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

LEADER 1 (PUM) + LEADER 2 (PUM) + LEADER 3 (PUM) + CONCENTRATION + TRITIUM + EFFLUENT + RIVER + SAMPLING +
WASTE DISPOSAL

000729
SET POINT DRIFT IN PRESSURE TRANSMITTER AT OCONEE 2

098729 CONTINUED

DUKE POWER COMPANY
3 PAGES, LETTER TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 2 (AEC), JANUARY 3, 1975, DOCKET 50-270, TYPE--
PUR, RFG--BOM, AE--DUKE

CAUSE - INSTRUMENT DRIFT. DURING CALIBRATION OF THE REACTOR COOLANT PRESSURE TRANSMITTERS WITH THE UNIT AT COLD SHUTDOWN, CHANNEL A WAS FOUND TO BE OUT OF CALIBRATION BY +2.05%. FULL SCALE ERROR MEASURED AS A RESULT OF THIS DRIFT WAS +22.0 PSI. THE OTHER 3 TRANSMITTERS WERE WITHIN THE 2% LIMIT. THE MOTOROLA TYPE 56PM TRANSMITTER WAS RECALIBRATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

REACTOR SAFETY SYSTEM + INSTRUMENT CALIBRATION + FAILURE, INSTRUMENT + INSTRUMENT, SWITCH + TEST, SYSTEM OPERABILITY + SET POINT + DRIFT + GEORGE 2 (PWR) + SENSORS, PRESSURE

099021

SETPOINT DRIFT IN PRESSURE TRANSMITTER AT GEORGE 2
DUKE POWER COMPANY, CHARLOTTE, N.C.
3 PAGES, LETTER WITH AD REPORT 74/11 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 2 (AEC), JANUARY 9, 1975, DOCKET 50-270, TYPE--PUR, RFG--BOM, AE--DUKE

CAUSE - INSTRUMENT DRIFT. DURING CALIBRATION OF THE REACTOR COOLANT PRESSURE TRANSMITTERS DURING POWER OPERATION, CHANNEL A TRANSMITTER WAS FOUND TO BE -2.4% OUT OF CALIBRATION. FULL SCALE ERROR WAS -19.2 PSI. THE OTHER 3 TRANSMITTERS WERE WITHIN THE REQUIRED 2% ACCURACY. THE MOTOROLA TYPE 56 PM TRANSMITTER WAS RECALIBRATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INSTRUMENT CALIBRATION + FAILURE, INSTRUMENT + INSTRUMENT, SWITCH + TEST, SYSTEM OPERABILITY + MAIN COOLING SYSTEM + SET POINT + DRIFT + GEORGE 2 (PWR) + SENSORS, PRESSURE

099031

INCORRECT WASTE GAS RELEASE RATE AT GEORGE 2
DUKE POWER COMPANY, CHARLOTTE, N.C.
3 PAGES, LETTER WITH AD REPORT 74/8 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 2 (AEC), JANUARY 9, 1975, DOCKET 50-270, TYPE--PUR, RFG--BOM, AE--DUKE

CAUSE - CALCULATIONAL ERROR. WHILE OPERATING AT 100% POWER, A SAMPLE FROM WASTE GAS TANK B WAS ANALYZED. A RELEASE RATE OF 40 CFM WAS CALCULATED. DURING THE RELEASE, A RADIATION ALARM WAS RECEIVED AND THE RELEASE TERMINATED. WHEN ENTERING INFORMATION TO A COMPUTER TO CALCULATE RELEASE RATE, A SAMPLE VOLUME OF 3300 ML WAS INCORRECTLY ENTERED INSTEAD OF THE ACTUAL 100 ML VALUE. THE LARGER VOLUME IS USED IN SEVERAL PROCEDURES. THE RECALCULATED RELEASE RATE WAS 8.6 CFM. THE ALLOWABLE LIMIT WAS NOT EXCEEDED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

EFFLUENT + FAILURE, OPERATION ERROR + RELEASE RATE + WASTE DISPOSAL + WASTE DISPOSAL, GAS + MATHEMATICAL TREATMENT + GEORGE 2 (PWR)

099032

LETOFFIN FILTER GASKET FAILURE AT GEORGE 2
DUKE POWER COMPANY, CHARLOTTE, N.C.
4 PAGES, LETTER WITH AD REPORT 74/10 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 2 (AEC), JANUARY 10, 1975, DOCKET 50-270, TYPE--PUR, RFG--BOM, AE--DUKE

CAUSE - UNKNOWN. DURING POWER OPERATION, THE OPERATOR SHIFTED LETOFFIN FILTERS BY REMOTELY OPENING THE INLET VALVE TO FILTER B AND CLOSING INLET VALVE TO FILTER A. LATER, WATER WAS SEEN LEAKING INTO THE FILTER ROOM. BOTH FILTERS WERE ISOLATED BUT THE LEAK CONTINUED. THE LETOFFIN LINE WAS ISOLATED AND A SHUTDOWN STARTED. THE GASKET IN A FAILED AT THE TIME FILTER B WAS PLACED IN SERVICE. NO REASON FOR THE FAILURE WAS FOUND. THE GASKET WAS REPLACED. THE LEAK HAD CONTINUED AFTER FILTER A WAS ISOLATED BECAUSE 2 VALVES USED IN THE PREFILTERING MUDS HAD BEEN LEFT OPEN MAINTAINING PRESSURE ON THE FILTER. THE VALVES WERE CLOSED AND THE SHUTDOWN TERMINATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATION ERROR + SEAL + COOLANT PURIFICATION SYSTEM + LEAK + REACTOR SHUTDOWN + GEORGE 2 (PWR) + FILTERS

099036

POWER LEVEL EXCEEDS LIMIT DURING TRANSIENT REACTOR AT GEORGE 2
DUKE POWER COMPANY, CHARLOTTE, N.C.
3 PAGES, LETTER WITH AD REPORT 75/1 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 2 (AEC), JANUARY 17, 1975, DOCKET 50-270, TYPE--PUR, RFG--BOM, AE--DUKE

CAUSE - FAULTY CONTROL SWITCH. THE REACTOR WAS OPERATING AT 80% POWER WHILE WAITING FOR REACTOR TO

093220 CONTINUED

APPROACH EQUIBLIATION. THE MOTOR OPERATED VALVE ON A MAIN STEAM LINE TO HEATERS OPENED DUE TO A CONTROL SWITCH MALFUNCTION. THE SUDDEN INCREASE OF STEAM FLOW RESULTED IN THE REACTOR POWER INCREASING TO 64%. THIS EXCEEDED THE 62.5% POWER LIMIT DURING TRANSIENT XENON CONDITIONS. REACTOR POWER WAS DECREASED, THE VALVE CLOSED, AND THE CONTROL SWITCH REPLACED.

2 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

REACTOR TRANSIENT + STEAM + CONTROL + FAILURE, INSTRUMENT + INSTRUMENT, SWITCH + OCONEE 2 (PWR) + VALVES

093222

PROPER OVERLAP BETWEEN CONTROL ROD GROUPS NOT MAINTAINED AT OCONEE 2

Duke Power Company, North Carolina

3 PAGES, LETTER WITH AD REPORT 75/2 TO U.S. NRC, REGION 2, JANUARY 30, 1975, DOCKET 50-270, TYPE--PWR, NRC--BON, AE--DUKE

CAUSE - OPERATOR OVERSIGHT. WITH THE UNIT AT 99% POWER, THE OPERATOR OBSERVED THAT CONTROL ROD GROUP 6 WAS 99% WITHDRAWN AND GROUP 7 WAS ONLY 15% WITHDRAWN. ONLY A 16% OVERLAP EXISTED BETWEEN THESE 2 GROUPS. THIS IS OUTSIDE THE 20 TO 30% LIMIT. DURING WITHDRAWAL, THE CONTROL ROD DRIVE SEQUENCER AUTOMATICALLY ENSURES THE PROPER OVERLAP. AFTER THE WITHDRAWAL, THE INTEGRATED CONTROL SYSTEM TAKES POSITION, AS NECESSARY, TO CONTROL ACTIVITY. OVER A PERIOD OF TIME, THE 2 GROUPS BECAME SEPARATED. AN ALARM IS PROVIDED FOR THE HIGH SIDE BUT NOT THE LOW SIDE. THE OPERATOR FAILED TO RECOGNIZE THE CONDITION. A LOW ALARM WILL BE DEVELOPED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTROL ROD INTERACTION + CONTROL ROD PROGRAM + CONTROL ROD NORTH + FAILURE, OPERATOR ERROR + REACTOR CONTROL + OCONEE 2 (PWR)

093342

PERSONNEL MATCH INTERLOCKS INOPERABLE AT OCONEE 2

Duke Power Company, North Carolina

1 PAGE, LETTER TO NRC, REGION 2, JANUARY 31, 1975, DOCKET 50-270, TYPE--PWR, NRC--BON, AE--DUKE

CAUSE - MECHANISM OUT OF ADJUSTMENT. DURING A MAINTENANCE OUTAGE, THE INTERLOCK MECHANISM ON THE PERSONNEL MATCH WAS FOUND TO HAVE FAILED. BOTH DOORS COULD BE OPENED SIMULTANEOUSLY. AN OPERATOR WAS DISPATCHED TO THE MATCH TO PREVENT THE OPENING OF BOTH DOORS. THE INTERLOCK MECHANISM MAY BECOME OUT OF ADJUSTMENT DUE TO FREQUENT USAGE DURING THE MAINTENANCE OUTAGE. IT WAS ADJUSTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MAINTENANCE AND REPAIR + CONTAINMENT AIR LOCK + CONTAINMENT INTEGRITY + INSTRUMENT, INTERLOCK + FAILURE, MAINTENANCE ERROR + OCONEE 2 (PWR)

093421

CORE FLOOD DISCHARGE VALVES NOT TAGGED OPEN AT OCONEE 2

Duke Power Company, North Carolina

3 PAGES, LETTER WITH AD REPORT 75/3 TO U.S. NRC, REGION 2, FEBRUARY 4, 1975, DOCKET 50-270, TYPE--PWR, NRC--BON, AE--DUKE

CAUSE - OPERATOR ERROR. DURING A STARTUP, THE CONTROL OPERATOR INSTRUCTED THE UTILITY OPERATOR TO LOCK OPEN AND TAG THE CORE FLOOD TANK DISCHARGE VALVE. THE CONTROL OPERATOR SIGNED THIS STEP AND THEN INCREASED SYSTEM PRESSURE. LATER, THE VALVES WERE FOUND OPEN BUT NOT TAGGED. THE UTILITY OPERATOR WAS NOT FAMILIAR WITH THIS PROCEDURE AND FAILED TO UNDERSTAND THE REQUEST. PROCEDURES WERE MODIFIED TO REQUIRE RECORDING THE NUMBER OF THE TAG USED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATOR ERROR + PROCEDURES AND MANUALS + CORE REFLOODING SYSTEM + IDENTIFICATION + OCONEE 2 (PWR) + VALVES

099702

REACTOR BUILDING SPRAY TRAIN NOT PROVIDED WHEN REQUIRED AT OCONEE 2

Duke Power Company, N.C.

2 PAGES, LETTER WITH AD REPORT 75/4 TO NRC, REGION 2, FEBRUARY 13, 1975, DOCKET 50-270, TYPE--PWR, NRC--BON, AE--DUKE

CAUSE - UNKNOWN. DURING A UNIT STARTUP, THE REACTOR COOLANT SYSTEM WAS ELEVATED SLIGHTLY ABOVE 250 PSIG AND 350 PSIG WITHOUT AN OPERABLE REACTOR BUILDING SPRAY TRAIN. A TRAIN WAS LINED UP IMMEDIATELY. AN INVESTIGATION OF THE EVENT IS IN PROGRESS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

100702 (CONTINUED)
CONTAINMENT SPRAY • EMERGENCY COOLING SYSTEM • OCUR# 2 (PH#) • REACTOR STARTUP

100893
ADDITIONAL INFORMATION ON STARTUP WITHOUT BUILDING SPRAY AT OCUR# 2
DUKE POWER COMPANY, N.C.
3 PAGES, LETTER WITH NO REPORT 75/48 TO U.S. NRC, REGION 2, FEBRUARY 21, 1975, DCKET 50-270, TYPE--PH#, NRC--
BOM, AE--DUKE

CAUSE - OPERATION ERROR. DURING A UNIT STARTUP, THE REACTOR COOLANT SYSTEM WAS ELEVATED ABOUT 250
F AND 350 PSI WITHOUT AN OPERABLE REACTOR BUILDING SPRAY TRAIN. THERE ARE 2 APPARENT CAUSES.
THE UTILITY OPERATOR THAT PERFORMED THE PROCEDURE FOR RAS SYSTEM DID NOT UNDERSTAND THAT HE WAS
TO PLACE THE SYSTEM IN THE AS STANDBY MODE. ALSO, THE UTILITY OPERATOR THAT CHECKED THE WHITE
TAG LU, DID NOT COMPLETE HIS REVER. THE CONTROL OPERATOR ASSUMED THAT HE HAD. IN BOTH CASES,
THE LACK OF COMPLETE COMMUNICATIONS WAS THE CAUSE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

CONTAINMENT SPRAY • FAILURE, OPERATION ERROR • PROCEDURES AND MANUALS • OCUR# 2 (PH#) • REACTOR STARTUP

100909
THE EMERGENCY CONDENSEN COOLING WATER VALVES FAIL TO OPEN AT OCUR# 2
DUKE POWER CO., N.C.
3 PAGES, LETTER WITH NO REPORT 75/2 TO U.S. NRC, REGION 2, MARCH 12, 1975, DCKET 50-270, TYPE--PH#, NRC--BOM,
AE--DUKE

CAUSE - RELAY FAILURE. WITH THE UNIT IN COLD SHUTDOWN, THE SINGLE OPERATING CONDENSER
CIRCULATING WATER PUMP TRIPPED. ALL 6 CONDENSER OUTLET VALVES CLOSED PROPERLY; HOWEVER, THE 2
VALVES WHICH ALLOW THE CCH DISCHARGE TO THE REINER TAILRACE TO PROVIDE A GRAVITY FLOW Siphon
FAILED TO OPER. ANOTHER CCH PUMP WAS STARTED. THE FIRST PUMP TRIPPED WHEN A SHORT CIRCUIT
OCCURRED IN THE CIRCUIT OF AN INDICATING BULB AS THE BULB WAS BEING REPLACED. CONTACTS IN A
RELAY ASSOCIATED WITH THE CONTROL CIRCUIT FOR THE VALVES WERE MISWIRING. AFTER THE RELAY WAS
REPLACED, THE VALVES OPERATED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

MAINTENANCE AND REPAIR • FAILURE, INSTRUMENT • EMERGENCY COOLING • CONDENSER COOLING SYSTEM • OCUR# 2 (PH#) •
VALVES • RELAYS

101109
BOIATED WATER STORAGE TANK LEVEL INDICATION FAILS AT OCUR# 2 AND 3
DUKE POWER COMPANY, N.C.
3 PAGES, LETTER WITH NO REPORT 75/5 TO U.S. NRC, REGION 2, MARCH 17, 1975, DCKET 50-270/207, TYPE--BOM, AE--
DUKE

CAUSE - MOISTURE FROZEN IN LINES. THE LEVEL INSTRUMENTATION FOR THE BOIATED WATER STORAGE TANKS
BECAME INOPERABLE UNCE AT EACH UNIT. THE APPARENT CAUSE OF THESE OCCURRENCES WAS THE EXTREMELY
COLD AMBIENT TEMPERATURE CAUSING MOISTURE ENTRAINED IN AN INSTRUMENT AIR LINE TO FREEZE IN THE
SUPPLY REGULATOR VALVES FOR THE BOI LEVEL INSTRUMENTS. THE STATION AIR DRYERS LOCATED ON THE
OUTLET OF THE AIR COMPRESSORS WERE INOPERABLE AT THE TIME. THE VALVES WERE THAWED. INSTRUMENT
AIR LINES ARE BEING HEAT TRACED. THE 4 STATION AIR DRYERS HAVE BEEN REBUILT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

STORAGE CONTAINER • FAILURE, DESIGN ERROR • CHEMICAL SHIM • WEATHER, SEVERE • OCUR# 3 (PH#) • OCUR# 2 (PH#)
• HEATERS • SENSORS, LEVEL • SH DRYERS

100909
BOIATED WATER STORAGE TANK LEVEL INDICATION FAILS AT OCUR# 2 AND 3
DUKE POWER COMPANY, N.C.
3 PAGES, LETTER WITH NO REPORT 75/5 TO U.S. NRC, REGION 2, MARCH 17, 1975, DCKETS 50-247/270, TYPE--PH#, NRC--
BOM, AE--DUKE

CAUSE - ICE IN INSTRUMENT LINES. ON 2 SEPARATE DAYS, OPERATORS NOTED THAT THE LEVEL
INSTRUMENTATION FOR THE BOIATED WATER STORAGE TANKS BECAME INOPERABLE. THE INDICATION DECREASED
IN BOTH CASES. THE CAUSE WAS EXTREMELY COLD AMBIENT TEMPERATURE CAUSING MOISTURE ENTRAINED IN AN
INSTRUMENT AIR LINE TO FREEZE IN THE SUPPLY REGULATOR FOR THE LEVEL INSTRUMENTS. A CONTRIBUTING
CAUSE WAS THE INOPERABILITY OF THE STATION AIR DRYERS LOCATED ON THE OUTLET OF THE AIR
COMPRESSORS. THE VALVES WERE THAWED. INSTRUMENT AIR LINES ARE BEING HEAT TRACED. AIR DRYERS
ARE BEING REBUILT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

WATER • MODIFICATION • STORAGE CONTAINER • FAILURE, DESIGN ERROR • CHEMICAL SHIM • TUBING • WEATHER, SEVERE •
OCUR# 3 (PH#) • OCUR# 2 (PH#) • SENSORS, LEVEL • AIR DRYERS

101157
 MANUAL FEATURE OF LEAKY HEAT REMOVAL SYSTEM VALVES FAIL AT OCEANEE 2 AND 3
 DURE POWER COMPANY, N.C.
 2 PAGES, LETTER TO U.S. NRC, REGION 2, MARCH 25, 1975, DOCKET 50-270/207, TYPE--PWR, NRC--B+N, AE--DURE

CAUSE - INSTALLATION ERRORS. THE LEAKY HEAT REMOVAL SYSTEM POWER OPERATED VALVE MANUAL TEST WAS PERFORMED FOR THE FIRST TIME. FIVE VALVES COULD NOT BE MANUALLY OPERATED AS REQUIRED. HANDWHEELS WERE MISSING ON TWO. ONE STARTED ELECTRICALLY WHEN THE MANUAL CLUTCH WAS ENGAGED. THE HANDWHEEL SYSTEM WAS BENT PREVENTING ROTATION ON ANOTHER. THE SPEED HANDLE ON THE FIFTH HAD INTERFERENCE WITH TWO ADJACENT PIPES; THE CLUTCH WOULD NOT ENGAGE FOR MANUAL OPERATION. ALL VALVES WERE REPAIRED. THERE WAS NO INDICATION THAT THESE VALVES HAD EVER BEEN MANUALLY OPERATED SINCE INITIAL CONSTRUCTION. THEY HAD BEEN SUCCESSFULLY OPERATED ELECTRICALLY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, EQUIPMENT + TEST, SYSTEM OPERABILITY + FAILURE, INSTALLATION ERROR + SHUTDOWN COOLING SYSTEM + OCEANEE 2 (PWR) + OCEANEE 2 (PWR) + VALVES + LPCI

101156
 REACTOR BUILDING SPRAY VALVE FAILS TO OPEN AT OCEANEE 2
 DURE POWER COMPANY, N.C.
 2 PAGES, LETTER TO U.S. NRC, REGION 2, MARCH 26, 1975, DOCKET 50-270, TYPE--PWR, NRC--B+N, AE--DECHTEL

CAUSE - UNKNOWN. DURING A REACTOR BUILDING SPRAY SYSTEM TEST WITH ONE UNIT OPERATING AT 100% POWER, A REACTOR ISOLATION VALVE FAILED TO OPEN ON SIGNAL. THE VALVE WAS JAMMED ON ITS SEAT. AFTER IT WAS OPENED MANUALLY, IT WAS CYCLED ELECTRICALLY SEVERAL TIMES. NO CAUSE COULD BE FOUND FOR THE JAMMING. THE REQUIREMENT TO ELECTRICALLY OPERATE THE VALVE FOLLOWING MANUAL OPERATION WAS RE-EMPHASIZED TO THE OPERATORS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTAINMENT SPRAY + FAILURE, EQUIPMENT + CONTAINMENT ISOLATION + TEST, SYSTEM OPERABILITY + OCEANEE 2 (PWR) + VALVE

101158
 SETPOINT DRIFT IN PRESSURE TRANSMITTER AT OCEANEE 2
 DURE POWER COMPANY, N.C.
 2 PAGES, LETTER TO U.S. NRC, REGION 2, MARCH 27, 1975, DOCKET 50-270, TYPE--PWR, NRC--B+N, AE--DURE

CAUSE - CHANGING AMBIENT TEMPERATURE. DURING TESTING WHILE THE REACTOR WAS AT 100% POWER, A REACTOR COOLANT PRESSURE TRANSMITTER WAS FOUND TO BE OUT OF CALIBRATION BY -3.48. THE FULL SCALE ERROR WAS -27.2 PSI. THE LIMIT IS 26. THE APPARENT CAUSE IS EXCESSIVE DRIFT ASSOCIATED WITH CHANGING AMBIENT TEMPERATURE ON THIS ROTORDA, TYPE 56 PM, PRESSURE TRANSMITTER. IT WAS RECALIBRATED. PROCUREMENT OF NEW TYPE TRANSMITTERS IS IN PROGRESS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

REACTOR SAFETY SYSTEM + INSTRUMENT CALIBRATION + FAILURE, INSTRUMENT + INSTRUMENT, SWITCH + MODIFICATION + TEST, SYSTEM OPERABILITY + FAILURE, DESIGN ERROR + SET POINT + DRIFT + OCEANEE 2 (PWR) + SENSORS, PRESSURE

101775
 SETPOINT DRIFT IN PRESSURE TRANSMITTER AT OCEANEE 2
 DURE POWER COMPANY, N.C.
 3 PAGES, LETTER WITH AD REPORT 75/7 TO U.S. NRC, REGION 2, MARCH 27, 1975, DOCKET 50-270, TYPE--PWR, NRC--B+N, AE--DURE

CAUSE - CHANGE IN AMBIENT TEMPERATURE. DURING CALIBRATION OF THE REACTOR COOLANT PRESSURE TRANSMITTERS WITH THE REACTOR AT 100% POWER, ONE WAS FOUND TO BE OUT OF CALIBRATION BY -3.48. THE FULL SCALE ERROR WAS -2.72 PSI. THE APPARENT CAUSE IS EXCESSIVE DRIFT ASSOCIATED WITH CHANGING AMBIENT TEMPERATURE. THE TRANSMITTER WAS CALIBRATED WHEN THE UNIT WAS IN A COLD SHUTDOWN CONDITION. THE UNIT WAS RECALIBRATED. PROCUREMENT OF REPLACEMENT TRANSMITTERS HAS STARTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THERMAL MECHANICAL EFFECT + INSTRUMENT CALIBRATION + FAILURE, INSTRUMENT + INSTRUMENT, SWITCH + TEST, SYSTEM OPERABILITY + SET POINT + TEMPERATURE + DRIFT + OCEANEE 2 (PWR) + SENSORS, PRESSURE

101720
 POWER LEVEL RAISED ABOVE CUTOFF PRIOR TO XENON EQUILIBRIUM AT OCEANEE 2
 DURE POWER COMPANY, N.C.
 3 PAGES, LETTER WITH AD REPORT 75/8 TO U.S. NRC, REGION 2, APRIL 8, 1975, DOCKET 50-270, TYPE--PWR, NRC--B+N, AE--DURE

101726 CONTINUED

CAUSE - MISUNDERSTANDING. A CALCULATION WAS MADE TO DETERMINE THE TIME THAT NERON REACTIVITY WOULD BE HIGH ENOUGH FOR THE VALUE OF STEADY STATE POWER. RESULTS OF THE CALCULATION WERE INCORRECTLY INTERPRETED IN THAT THEY REFERENCE ONE RATHER THAN 1338 POWER AS REQUIRED. THEREFORE, THE EXTRAPOLATED TIME WAS TOO SHORT. A SECOND CAUSE WAS THE MISREADING OF THE VALUE OF NERON REACTIVITY BY THE CONTROL ROOM OPERATORS. THE REACTOR POWER WAS ABOVE THE 92.50 CUTOFF POWER FOR ABOUT 9 HOURS BEFORE NERON CONDITIONS MET THE REQUIREMENTS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

NERON + REACTOR POWER + FAILURE, ADMINISTRATIVE CONTROL + MATHEMATICAL TREATMENT + OCONEE 2 (PWR)

102316

SMALL OIL FIRE UNDERNEATH PUMP MOTOR STAND AT OCONEE 2

DURE POWER COMPANY, N.C.

1 PAGE, LETTER TO U.S. NRC, REGION 2, APRIL 11, 1975, DOCKET 50-270, TYPE--PWR, NRC--DEN, AE--DURE

CAUSE - AIR LEAKAGE INTO OIL. A SMALL FIRE OCCURRED UNDERNEATH A REACTOR COOLANT PUMP MOTOR STAND. THE UNIT WAS AT HOT SHUTDOWN. AN IMMEDIATE COOL-DOWN WAS BEGUN. NO EQUIPMENT DAMAGE OCCURRED. THE THRUST RUNNER AIR SEAL IN THE MOTOR HAD ALLOWED AIR INTO THE OIL CAUSING OIL TO OVERFLOW THE OIL POT VENT. THE LEAKING OIL SATURATED BORON CRYSTALS IN THE AREA WHICH WERE IN CONTACT WITH THE HOT PIPING. MODIFICATIONS WERE MADE TO CORRECT THIS OIL LEAKAGE PROBLEM. THE LEAKING INSTRUMENT CONNECTION (THE SOURCE OF THE BORON CRYSTALS) WAS SEALED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 2 (PWR) + OIL + LUBRICATION + SUPPORT STRUCTURE + PUMPS + MAIN COOLING SYSTEM + FAILURE, DESIGN ERROR + LEAK

100327

SMALL OIL FIRE UNDER COOLANT PUMP MOTOR STAND AT OCONEE 2

DURE POWER CO., N.C.

5 PGS, LTR ATTACHMENTS TO NRC, APRIL 11, 1975, DOCKET 50-270, TYPE--PWR, NRC--DEN, AE--DURE

CAUSE - AIR IN OIL SYSTEM. ON JAN. 31, 1975, A SMALL OIL FIRE (SPILLING BORON CRYSTALS) OCCURRED UNDERNEATH REACTOR COOLANT PUMP 202 MOTOR STAND WHILE THE UNIT WAS AT HOT SHUTDOWN. AN IMMEDIATE COOL-DOWN WAS BEGUN. NO EQUIPMENT DAMAGE OCCURRED. THE THRUST RUNNER AIR SEAL IN THE MOTOR HAD ALLOWED AIR TO ENTER THE OIL CAUSING SOME OIL TO ESCAPE OUT OF THE UPPER OIL POT OVERFLOW AND VENT. THE OIL SATURATED BORON CRYSTALS THAT WERE IN CONTACT WITH HOT REACTOR COOLANT SYSTEM PIPING. MODIFICATIONS HAVE BEEN PERFORMED TO CORRECT THE OIL LEAKAGE PROBLEM.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 2 (PWR) + OIL + LUBRICATION + LEAK + MAIN COOLING SYSTEM + PUMPS + SEAL

102317

BREATHING AIR ISOLATION VALVES FOUND OPEN AT OCONEE 2

DURE POWER COMPANY, N.C.

1 PAGE, LETTER TO U.S. NRC, REGION 2, APRIL 16, 1975, DOCKET 50-270, TYPE--PWR, NRC--DEN, AE--DURE

CAUSE - PROCEDURAL DEFICIENCIES. TWO BREATHING AIR ISOLATION VALVES IN THE REACTOR BUILDING WERE DISCOVERED OPEN, RATHER THAN SHUT, AND WITHOUT THE REQUIRED WHITE TAGS. THE UNIT WAS IN COLD SHUTDOWN AND CONTAINMENT WAS NOT REQUIRED. A SEARCH OF THE RECORDS SHOWED ONE VALVE HAD BEEN CLOSED AND TAGGED ON JAN. 23. NO RECORD OF TAG REMOVAL WAS FOUND. THE OTHER VALVE HAD BEEN OMITTED FROM THE CHECK LIST OF VALVES. BOTH VALVES WERE CLOSED AND TAGGED. PROCEDURES WERE MODIFIED TO REQUIRE CHECKING THESE VALVES PRIOR TO A STARTUP.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 2 (PWR) + VALVES + CONTAINMENT ISOLATION + PNEUMATIC SYSTEM + FAILURE, ADMINISTRATIVE CONTROL + PROCEDURES AND MANUALS + CONTAINMENT INTEGRITY

102546

QUENCH TANK LEVEL TOO LOW AT OCONEE 2

DURE POWER COMPANY, N.C.

2 PGS, LETTER WITH UER 75-4 TO U.S. NRC, REGION 2, APRIL 30, 1975, DOCKET 50-270, TYPE--PWR, NRC--DEN, AE--DURE

CAUSE - MISIDENTIFICATION OF AN ALARM. A QUENCH TANK LOW LEVEL ALARM WAS RECEIVED AND ACKNOWLEDGED. HOWEVER IT WAS INCORRECTLY IDENTIFIED AND NO ACTION TAKEN UNTIL THE LOW LEVEL WAS OBSERVED BY AN OPERATOR. LEVEL WAS RESTORED TO NORMAL 45 MINUTES AFTER THE ALARM. IMMEDIATELY PRIOR TO THIS INCIDENT, THE ALARM NEXT TO THE QUENCH TANK LOW LEVEL ALARM HAD BEEN INTERMITTENTLY ALARMING. THE OPERATOR HEARD THE AUDIO PORTION, LOOKED UP, AND MISTAKENLY THOUGHT THIS WAS THE INTERMITTENT ALARM AGAIN. OPERATORS TOLD TO TREAT EACH ALARM AS A NEW AND DIFFERENT ALARM.

102500 PLUTONIUM
 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 (CHARGE \$2.00)

UCINET 2 (PWR) • OXYGEN CAPACITY • ANNUNCIATORS • FAILURE, OPERATOR ERROR • IDENTIFICATION • OPERATIVE ACTION
 • STORAGE CONTAINERS

103000
 URINE PWR MISSING FROM LPEI VALVE AT UCINET 2
 JUNE PUMP COMPANY, N.C.
 3 PAGES, LETTER WITH NRC 75-10 TO U.S. NRC, REGION 2, MAY 9, 1975, DOCKET 50-270, TYPE--PWR, NRC--GEN, AE--SURE

CAUSE - DESIGN DEFICIENCY. DURING A MODIFICATION OF MEMORIAL GUIDE PINS IN THE OUTLET VALVES FROM LOW PRESSURE INJECTION COLUMNS, THE GUIDE PIN ON THE BASE OF A VALVE WAS MISSING. THE 316 STAINLESS STEEL PIN IS 3/4 BY 4 INCHES. THE APPARENT CAUSE IS CAVITATION DAMAGE WHEN OPERATING IN THE HEAT EXCHANGER. A SEARCH FOR THE MISSING PART WILL BE MADE BY RADIOGRAPHING ALL LOW POINTS IN THE PIPING. REPLACEMENT VALVES ARE BEING OBTAINED TO PREVENT REOCCURRENCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 (CHARGE \$2.00)

UCINET 2 (PWR) • PVALVES • LPEI • SHUTDOWN COOLING SYSTEM • FAILURE, COMPONENT • FAILURE, DESIGN ERROR • HYDRAULIC EFFECT • PLANS

103004
 REACTOR BUILDING NORMAL SUMP ISOLATION VALVE FAILS TO CLOSE AT UCINET 2
 JUNE PUMP COMPANY, N.C.
 2 PAGES, LETTER WITH NRC 75-5 TO U.S. NRC, REGION 2, MAY 12, 1975, DOCKET 50-270, TYPE--PWR, NRC--GEN, AE--SURE

CAUSE - ELECTRIC INTERLOCK MALFUNCTION. WHILE THE REACTOR WAS AT ONE POWER, THE REACTOR BUILDING NORMAL SUMP CONTAINMENT ISOLATION VALVE WAS OPEN AND WOULD NOT CLOSE DUE TO AN ELECTRICAL INTERLOCK PROBLEM. THE VALVE WAS NORMALLY CLOSED. A SPRING ON THE OPEN SIDE OF THE ELECTRICAL INTERLOCK CONTACT IN THE AUTOM CONTROL CENTER FOR THE VALVE WAS WEAR CAUSING A NORMALLY CLOSED CONTACT TO REMAIN OPEN. THE MOTOR CONTROL CENTER WAS REPAIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 (CHARGE \$2.00)

UCINET 2 (PWR) • PVALVES • CONTAINMENT ISOLATION • CONTAINMENT SUMP • FAILURE, INSTRUMENT • INSTRUMENT, INTERLOCK • VALVE OPERATORS

103001
 EMERGENCY FEEDWATER VALVE FAILS TO OPEN AT UCINET 2
 JUNE PUMP COMPANY, N.C.
 3 PAGES, LETTER WITH NRC 75-6 TO U.S. NRC, REGION 2, MAY 13, 1975, DOCKET 50-270, TYPE--PWR, NRC--GEN, AE--SURE

CAUSE - VALVE JAMMED ON SEAT. DURING THE TRANSIENT THAT FOLLOWED A FULL LOAD TURBINE TRIP TEST, BOTH MAIN FEEDWATER PUMPS TRIPPED. THE EMERGENCY FEEDWATER PUMP WAS AUTOMATICALLY ACTIVATED. THE VALVE TO STEAM GENERATOR A DID NOT OPEN. A MAIN FEEDWATER PUMP WAS RESET AND LINED UP TO BOTH STEAM GENERATORS. THE MOTOR OPERATOR FOR THE VALVE THAT FAILED HAD TRIPPED ON OVERLOAD. THE APPARENT CAUSE WAS THE VALVE BEING JAMMED ON ITS SEAT. AFTER THE VALVE WAS PARTIALLY OPENED MANUALLY, IT WAS REMOTELY CYCLED SEVERAL TIMES WITHOUT FAILURE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 (CHARGE \$2.00)

UCINET 2 (PWR) • PVALVES • FEEDWATER • TEST, SYSTEM OPERABILITY • FAILURE, EQUIPMENT

103054
 CORE FLOOD TANK OVERPRESSURIZED AT UCINET 2
 JUNE PUMP COMPANY, N.C.
 1 PAGE, LETTER TO U.S. NRC, REGION 2, MAY 16, 1975, DOCKET 50-270, TYPE--PWR, NRC--GEN, AE--SURE

CAUSE - VALVE MALFUNCTION. WITH THE UNIT OPERATING AT 75% POWER, NITROGEN WAS ADDED TO CORE FLOOD TANK 20. THIS IS A ROUTINE OPERATION. WHEN THE DESIRED PRESSURE WAS REACHED, THE VALVE WAS CLOSED BUT TANK PRESSURE CONTINUED TO INCREASE. THE PRESSURE INCREASE WAS TERMINATED BY JAMMING THE VALVE SHUT. MAXIMUM INDICATED PRESSURE WAS 633.2 PSIG WHICH EXCEEDS THE UPPER LIMIT OF 625 PSIG. PRESSURE WAS REDUCED TO WITHIN LIMITS IN 3 MINUTES. THE APPARENT CAUSE WAS A FAULTY YONE RUF THAT CAUSED VALVE OPERATION TO BE UNUSUALLY DIFFICULT. THE VALVE WAS REPAIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 (CHARGE \$2.00)

UCINET 2 (PWR) • OVERPRESSURE, INTERNAL • STORAGE CONTAINER • FAILURE, EQUIPMENT • VALVES • CORE REFLOODING SYSTEM

100005

PRIMARY REACTOR COOLANT FLOW EXCEEDS DESIGN VALUE AT UCONEE 2

DUKE POWER COMPANY, N.C.

3 PAGES. LETTER WITH REF 75-7 TO U.S. NRC, REGION 2, MAY 23, 1975, DOCKET 50-270, TYPE--PWR, HFC--BEN, AE--DUKE

CAUSE - NOT STATED. THE PRIMARY REACTOR COOLANT FLOW WAS MEASURED BY THE PRECISION HEAT BALANCE METHOD. INCONSISTENCIES WERE FOUND IN THE RTD READINGS IN THAT ONE COLD LEG NARROW RANGE RTD WAS READING 3°F HIGHER THAN THE OTHER THREE. THE RTD'S WERE NORMALIZED AT ISOTHERMAL CONDITIONS. A FLOW VALUE OF 111.94 OF DESIGN FLOW WAS THEN ESTABLISHED. SINCE THIS IS NEAR THE PWR ASSEMBLY LIFT FLOW, THE POSITION OF SEVERAL ASSEMBLIES WAS DETERMINED AT FULL FLOW AND AT REDUCED FLOW. NO MOVEMENT WAS DETECTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONEE 2 (PWR) • OPLIN • ORATE • MAIN COOLING SYSTEM • HYDRAULIC EFFECT • TESTING • MEASUREMENT • FUEL ELEMENTS

101111

CONDENSER CIRCULATING WATER VALVES FAIL TO OPEN AT UCONEE 2

DUKE POWER COMPANY, N.C.

3 PAGES. LETTER WITH REF 75-4 TO U.S. NRC, REGION 2, MAY 30, 1975, DOCKET 50-280, TYPE--PWR, HFC--BEN, AE--DUKE

CAUSE - PROCEDURAL DEFICIENCY. DURING A CONDENSER CIRCULATING WATER SYSTEM GRAVITY AND RECIRCULATION FLOW TEST WITH THE REACTOR IN COLD SHUTDOWN, 3 OF THE 6 CONDENSER DISCHARGE VALVES DID NOT CLOSE. THE EMERGENCY DISCHARGE VALVES DID NOT OPEN AS THEY ARE INTERLOCKED TO THE DISCHARGE VALVES. THE CONTROL SWITCHES FOR THE VALVES THAT MALFUNCTIONED WERE IN THE OPEN POSITION INSTEAD OF THE REMOTE POSITION. THIS PREVENTED THEIR PROPER OPERATION. THE SWITCH POSITION IS NOT ASSUMED IN OPERATING PROCEDURES. PROCEDURES HAVE BEEN CHANGED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONEE 2 (PWR) • VALVES • CONDENSER COOLING SYSTEM • EMERGENCY COOLING • TEST, SYSTEM OPERABILITY • FAILURE, ADMINISTRATIVE CONTROL • PROCEDURES AND MANUALS

103402

ES VALVE THERMAL OVERLOADS SIZED INCORRECTLY AT UCONEE 2

DUKE POWER CO., CHARLOTTE, N.C.

2 PAGES. LETTER TO NRC, REGION 2, JUNE 3, 1975, DOCKET 50-270, TYPE--PWR, HFC--BEN, AE--DUKE

CAUSE - INSTALLATION ERROR. AS A RESULT OF THE DISCOVERY OF AN INCORRECT THERMAL OVERLOAD COIL IN AN ENGINEERED SAFEGUARDS VALVE, ALL ES VALVE MOTOR CONTROL CENTERS WERE CHECKED FOR PROPER SIZING AND LOCATION ON THE PROPER PHASES. DISCREPANCIES FOUND WERE OVERLOAD COILS RATED AT TWICE THE CURRENT CARRYING CAPACITY OF THE CABLE. OVERLOAD COILS WILL BE REPLACED WITH THOSE COMPATIBLE WITH THE DESCRIPTION IN THE FSM.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONEE 2 (PWR) • INSTRUMENT, PROTECTIVE • ELECTRIC POWER • ENGINEERED SAFETY FEATURE • FAILURE, INSTALLATION ERROR • REVIEW

105071

4160 VOLT MAIN FEEDER BUSES FAIL TO TRANSFER AT UCONEE 2

DUKE POWER COMPANY, N.C.

4 PAGES. LETTER WITH REF 75-12 TO U.S. NRC, REGION 2, JULY 14, 1975, DOCKET 50-270, TYPE--PWR, HFC--BEN, AE--DUKE

CAUSE - CONTROL RELAY FAILURE. DURING TESTING OF THE 4160 V EMERGENCY POWER SWITCHING LOGIC WITH THE REACTOR IN COLD SHUTDOWN, 1 OF 2 STANDBY BREAKERS FAILED TO CLOSE IN. ITS CONTROL RELAY HAD FAILED. THE RELAY CONTACTS WERE CLEANED AND DUST PARTICLES WERE REMOVED FROM THE INDUCTION DISC. PROPER OPERATION WAS VERIFIED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONEE 2 (PWR) • ELECTRIC POWER • BREAKER • TEST, SYSTEM OPERABILITY • FAILURE, MAINTENANCE ERROR • EMERGENCY POWER, ELECTRIC • RELAYS

104724

4160 VOLT MAIN FEEDER BUS BREAKER FAILS TO CLOSE AT UCONEE 2

DUKE POWER COMPANY, CHARLOTTE

4 PGS. LTR WITH REF 75-12 TO NRC, REGION 2, JULY 14, 1975, DOCKET 50-270, TYPE--PWR, HFC--BEN, AE--DUKE

CAUSE - DIRTY CONTROL RELAY. THE 4160 VOLT EMERGENCY POWER SWITCHING LOGIC TEST WAS PERFORMED TO VERIFY THAT THE 4160 VOLT MAIN FEEDER BUSES WILL TRANSFER FROM THE STARTUP TRANSFORMER TO THE STANDBY BUSES SHOULD THE STARTUP TRANSFORMER BE DEENERGIZED. DURING TESTING WITH THE REACTOR IN

104734 COUNTING UP

CRU SHUTDOWN. 1 OF THE 2 REDUNDANT STANDBY BUS BREAKERS FAILED TO CLOSE IN. A CONTROL RELAY FAILED. THE CONTACTS ON THE RELAY WERE CLEANED AND DUST PARTICLES REMOVED FROM THE INDUCTION DISC. THE BREAKER THEN OPERATED PROPERLY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 130 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCURR 2 (PWR) • ELECTRICAL POWER • EMERGENCY POWER, ELECTRICAL • TEST, SYSTEM OPERABILITY • FAILURE, MAINTENANCE (ARM • DELAY • CRU • BREAKER)

104901

EMERGENCY CONDENSER DISCHARGE VALVE FAILS TO OPEN AT UCURR 2

DUKE POWER COMPANY, N.C.

2 PAGES, LETTER WITH REF 75-10 TO U.S. NRC, REGION 2, JULY 18, 1975, DOCKET 50-270, TYPE--PWR, NRC--BLW, AE--DUKE

CAUSE - MOISTURE IN LIMIT SWITCH BOX. DURING THE PERIODIC 4160 V EMERGENCY POWER SWITCH LOGIC TEST WITH THE UNIT IN COLD SHUTDOWN, A LOSS OF POWER TO THE UNIT OCCURS WHILE SWITCHING FROM THE STANDBY TRANSFORMER TO THE STANDBY BUSES. DURING THIS LOSS, A CONDENSER COOLING WATER EMERGENCY DISCHARGE VALVE FAILED TO OPEN. THE APPARENT CAUSE WAS MOISTURE IN THE LIMIT SWITCH JUNCTION BOX CAUSING THE CONTROL POWER FUSES TO BLOW. ACTION WILL BE TAKEN TO PREVENT MOISTURE BUILDUP.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCURR 2 (PWR) • VALVES • EMERGENCY COOLING • CONDENSER COOLING SYSTEM • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT • INSTRUMENT, PROTECTIVE • WATER

104904

REACTION BUILDING EMERGENCY MATCH LEAK RATE EXCESSIVE AT UCURR 2

DUKE POWER COMPANY, CHARLOTTE

2 PAGES, LETTER WITH REF 75-3 TO U.S. NRC, REGION 2, AUG. 1, 1975, DOCKET 50-270, TYPE--PWR, NRC--BLW, AE--DUKE

CAUSE - CRACKED PIPE FITTING. DURING THE EMERGENCY MATCH LEAK RATE TEST WITH THE REACTOR AT FULL POWER, LEAKAGE EXCEEDED THE LIMIT. A CRACKED UNION FITTING WAS FOUND ON AN EQUALIZING LINE INSIDE THE EMERGENCY MATCH. IT COULD NOT BE DETERMINED WHEN IT CRACKED. THE FITTING WAS REPLACED AND THE TEST MADE SUCCESSFULLY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCURR 2 (PWR) • LEAK RATE • CONTAINMENT AIR LOCK • TEST, SYSTEM OPERABILITY • TEST, LEAK RATE • FAILURE, PIPE • PIPES AND PIPE FITTINGS • CONTAINMENT INTEGRITY

104945

GASEOUS ACTIVITY RELEASED TO AUXILIARY BUILDING AT UCURR 2

DUKE POWER CO., CHARLOTTE, N.C.

3 PAGES, LETTER WITH NO REPORT 75-14 TO NRC, REGION 2, AUG. 8, 1975, DOCKET 50-270, TYPE--PWR, NRC--BLW, AE--DUKE

CAUSE - FAILURE OF PUMP SEAL AND LEVEL INSTRUMENT. THE CONTROL ROOM OPERATOR RECEIVED INDICATIONS OF INCREASED GASEOUS ACTIVITY IN THE AUXILIARY BUILDING. INVESTIGATION REVEALED THE QUENCH TANK LEVEL INSTRUMENT HAD FAILED HIGH, RESULTING IN THE VENTING OF STEAM FROM THE DRY QUENCH TANK TO THE COMPONENT DRAIN PUMP VENT. THIS DRAINED TO THE HIGH ACTIVITY WASTE TANK, WHERE GASEOUS ACTIVITY LEAKED AROUND THE MAIN PUMP SEAL. OVER A 3-DAY PERIOD 104.3 C3 WERE RELEASED. PUMP SEALS WERE REPLACED AND THE QUENCH TANK FILLED TO ITS NORMAL LEVEL. CORRECTIVE ACTION WAS TAKEN ON THE LEVEL INSTRUMENT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCURR 2 (PWR) • RADIOACTIVE RELEASE • FAILURE, EQUIPMENT • SEAL • PUMPS • LEAK • SENSORS, LEVEL

104944

SIMULTANEOUS OUTAGE OF TWO STRINGS OF BATTERIES AT UCURR 2

DUKE POWER CO., CHARLOTTE, N.C.

3 PAGES, LETTER WITH NO REPORT 75-13 TO NRC, REGION 2, AUG. 11, 1975, DOCKET 50-370, TYPE--PWR, NRC--BLW, AE--DUKE

CAUSE - OPERATOR ERROR. DURING PLANNING FOR THE STARTUP OF UNIT 1 WITH UNITS 2 AND 3 AT FULL POWER, IT WAS DISCOVERED THAT ONE STRING OF KEOWEE BATTERIES AND ONE STRING OF SWITCHING STATION BATTERIES WERE BEING CHARGED SIMULTANEOUSLY. ALTHOUGH THE CONTROL OPERATOR WAS NOTIFIED THAT THESE BATTERIES WERE TO BE TAKEN OUT OF SERVICE, HE FAILED TO RECOGNIZE THAT THIS VIOLATED LIMITING CONDITIONS. POWER REDUCTION OF BOTH UNITS WAS IMMEDIATELY INITIATED. THE BATTERIES WERE RETURNED TO SERVICE 9 MINUTES AFTER THE ERROR WAS DISCOVERED AND POWER REDUCTION CEASED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 130 CENTS/PAGE -- MINIMUM CHARGE \$2.00

109944 CONTINUED

OCONEE 2 (PWR) • BATTERIES & CHARGERS • EMERGENCY POWER, ELECTRIC • FAILURE, OPERATOR ERROR

109945

AMPLIFIER IN PWR POWER IMBALANCE CIRCUIT FAILS AT OCONEE 2

DUKE POWER COMPANY, CHARLOTTE

2 PAGES, LETTER WITH AL MEMPHI 75-15 TO NRC, REGION 2, AUG. 19, 1975, DCKET 50-270, TYPE--PWR, WSG--BEN, AE--DUKE

CAUSE - UNKNOWN. DURING TESTING OF REACTOR PROTECTIVE SYSTEM CHANNEL D, A FAULTY AMPLIFIER IN THE POWER IMBALANCE CIRCUIT OF THE POWER-IMBALANCE-FLUX TRIP FUNCTION RESULTED IN A TRIP SET POINT LESS THAN THE LIMIT. THE FAULTY AMPLIFIER WILL BE REPLACED WHEN A REPLACEMENT IS AVAILABLE. UNTIL THAT TIME, THE CHANNEL WILL REMAIN IN MANUAL BYPASS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 2 (PWR) • INSTRUMENT, AMPLIFIER • REACTOR SAFETY SYSTEM • INSTRUMENT, SWITCH • FAILURE, INSTRUMENT • TEST, SYSTEM OPERABILITY

109172

AMPLIFIER IN PWR POWER IMBALANCE CIRCUIT FAILS AT OCONEE 2

DUKE POWER COMPANY, CHARLOTTE

2 PGS, LTR W/ENR 75-15 TO NRC, REGION 2, AUG. 19, 1975, DCKET 50-270, TYPE--PWR, WSG--BEN, AE--DUKE

CAUSE - FAULTY AMPLIFIER. DURING A TEST OF REACTOR PROTECTIVE SYSTEM CHANNEL D, A FAULTY AMPLIFIER IN THE POWER IMBALANCE CIRCUIT OF THE POWER-IMBALANCE-FLUX-TRIP FUNCTION RESULTED IN A TRIP SET POINT LESS CONSERVATIVE THAN THE TECH SPECS. THE CHANNEL WAS PLACED IN MANUAL AND LEFT THAT WAY UNTIL A REPLACEMENT AMPLIFIER BECAME AVAILABLE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 2 (PWR) • INSTRUMENT, AMPLIFIER • FAILURE, INSTRUMENT • TEST, SYSTEM OPERABILITY • REACTOR SAFETY SYSTEM • FLUX • REACTOR POWER • SET POINT • INSTRUMENT, SWITCH • TRIP

109200

OPERABLE BUILDING SPRAY TRAIN NOT PROVIDED AS REQUIRED AT OCONEE 2

DUKE POWER COMPANY, CHARLOTTE

3 PGS, LTR W/ENR 75-10 TO NRC, REGION 2, AUG. 22, 1975, DCKET 50-270, TYPE--PWR, WSG--BEN, AE--DUKE

CAUSE - OPERATOR ERROR. WHILE CONDUCTING A UNIT STARTUP, THE REACTOR COOLANT SYSTEM WAS ELEVATED ABOVE 250 P AND 350 PSIG WITHOUT AN OPERABLE REACTOR BUILDING SPRAY TRAIN. THE PUMP SECTION VALVE HAD BEEN CLOSED AS REQUIRED BY THE SHUTDOWN PROCEDURES. DURING STARTUP, THE OPERATOR CHECKED THE OUT-OF-MANUAL LIST INSTEAD OF THE VALVE TO SIGN THE CHECKLIST THAT THE SPRAY SYSTEM WAS OPERABLE. THE STARTUP WAS HALTED UNTIL THE SPRAY SYSTEM COULD BE LINED UP.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 2 (PWR) • REACTOR BUILDING SPRAY • FAILURE, OPERATOR ERROR • PROCEDURES AND MANUALS • REACTOR STARTUP

109170

HIGH ENERGY LINE BREAK DRAIN INADVERTENTLY REMOVED AT OCONEE 2

DUKE POWER COMPANY, CHARLOTTE

2 PGS, LTR W/ENR 75-11 TO NRC, REGION 2, A. 27, 1975, DCKET 50-270, TYPE--PWR, WSG--BEN, AE--DUKE

CAUSE - MAINTENANCE ERROR. A MODIFICATION TO UNIT 1 WAS PERFORMED TO REPLACE THE TEMPORARY HIGH ENERGY LINE BREAK DRAINS WITH A PERMANENT INSTALLATION. PERSONNEL UNFAMILIAR WITH THE AUXILIARY BUILDING LAYOUT REMOVED THE DOOR TO UNIT 2 RATHER THAN UNIT 1 CABLE ROOM WHILE UNIT 2 WAS AT POWER OPERATION. THE ERROR WAS DISCOVERED AND THE DOOR REPLACED WITHIN 3 HOURS. PROCEDURES LISTED THE DOORS TO BE REPLACED BUT DID NOT SPECIFY WHICH DOORS WERE APPLICABLE TO EACH UNIT. PROCEDURES WERE MODIFIED TO SHOW THOSE DOORS WHICH ARE TO BE REPLACED DURING THE TIME EACH UNIT IS SHUT DOWN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 2 (PWR) • MISSILE GENERATION AND PROTECTION • HYDRAULIC EFFECT • OSHIELDING • MODIFICATION • FAILURE, ADMINISTRATIVE CONTROL

109100

LINE TRAIN OF REACTOR BUILDING SPRAY INADVERTENTLY TAKEN OUT OF SERVICE AT OCONEE 2

DUKE POWER COMPANY, CHARLOTTE

2 PAGES, LTR W/ENR 75-13 TO NRC, REGION 2, AUG. 27, 1975, DCKET 50-270, TYPE--PWR, WSG--BEN, AE--DUKE

CAUSE - INADEQUATE SUPERVISION OF TRAINEE. DURING TESTING OF UNIT 1 REACTOR BUILDING SPRAY

105190 PLANTING

SYSTEM. A TRAINER INADVERTENTLY OPENED A UNIT 2 BREAKER INSTEAD OF THE REQUESTED UNIT 1 BREAKER. THIS DISABLED THE SPRAY SYSTEM WITH UNIT 2 AT FULL POWER. THE ERROR WAS CORRECTED WITHIN 20 SECONDS. THIS EVENT WAS OPERATOR ERROR IN THAT THE TRAINER WAS NOT ADEQUATELY SUPERVISED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONNE 2 (PWR) • PLANTING SPRAY • FAILURE, OPERATOR ERROR • OMBREAKER • TRAINING

105179

URGENCY TIME LEVEL INSTRUMENT FAILS AT UCONNE 2

NUREG PWR COMPANY, CHARLOTTE

2 PGS. LTR NRC 75-12 TO NRC, REGION 2, AUG. 27, 1975, DOCKET 50-270, TYPE--PWR, NRC--BEN, AE--DUKE

CAUSE - IMPULSE LINE WATER LEG DRAINED, WITH THE UNIT OPERATING AT 100% POWER, THE COMPONENT DRAIN PUMP FAILED WHILE PUMPING DOWN THE JUECH TANK. FAILURE WAS DUE TO PUMPING WITH A LOW JUECH TANK LEVEL. THE INSTRUMENTATION DID NOT INDICATE LESS THAN 90 INCHES. THE UPPER IMPULSE LINE WATER LEG WAS PARTIALLY DRAINED CAUSING A HIGH INDICATED LEVEL. NO LEAK WAS FOUND. THE LINE WAS REFILLED AND THE TRANSMITTER CALIBRATION CHECKED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONNE 2 (PWR) • PERSONNEL, LEVEL • PUMPING • WATER • STORAGE CONTAINER • INSTRUMENT, ABNORMAL INDICATION • INSTRUMENT CALIBRATION

100320

REQUIRED OVERLAP BETWEEN CONTROL ROD GROUPS LOST AT UCONNE 2

NUREG PWR CO., N.C.

2 PGS. LTR NRC 75-12 TO NRC, SEPT. 8, 1975, DOCKET 50-270, TYPE--PWR, NRC--BEN, AE--DUKE

CAUSE - ONE GROUP DROPPED INTO CORE, WHILE THE UNIT WAS OPERATING AT 95% POWER WITH CONTROL ROD GROUP 7 AT 100% WITHDRAWAL, GROUP 6 RODS DROPPED INTO THE CORE. THE INTEGRATED CONTROL SYSTEM IMMEDIATELY WITHDREW GROUP 6 TO 100% WITHDRAWAL TO MAINTAIN POWER LEVEL. THESE ACTIONS RESULTED IN THE LOSS OF THE REQUIRED 25% OVERLAP BETWEEN OPERATING CONTROL ROD GROUPS. THE OPERATOR IMMEDIATELY PLACED THE CONTROL ROD DRIVE SYSTEM IN MANUAL AND RESEQUENCED GROUPS 6 AND 7 TO ESTABLISH THE REQUIRED OVERLAP. REWIREMENTS WERE NOT YET FIN 5 MINUTES. NO PROBLEMS WERE IDENTIFIED THAT COULD HAVE CAUSED THE DROP.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONNE 2 (PWR) • CONTROL ROD INTERACTION • CONTROL ROD PROGRAM • REACTOR STABILITY • REACTOR CONTROL • CONTROL SYSTEM • CONTROL ROD DRIVE MECHANISMS

100030

ACTIVITY IN THE COMPONENT COOLING SYSTEM INCREASES AT UCONNE 2

NUREG PWR COMPANY, N.C.

2 PGS. LTR TO NRC DIRECTOR, SEPT. 8, 1975, DOCKET 50-270, TYPE--PWR, NRC--BEN, AE--DUKE

CAUSE - LEAK IN LETDOWN COOLER. A REVIEW OF THE RADIATION MONITOR TREND RECORDER REVEALED A CLEARLY DEFINED STEP IN THE COMPONENT COOLING SYSTEM COUNT RATE ABOUT 20 MINUTES AFTER A REACTOR TRIP FROM 99% POWER. THE INCREASED ACTIVITY RESULTED FROM A LEAK IN LETDOWN COOLER A. THE COOLER WAS REMOVED FROM SERVICE AND ISOLATED. REPAIRS ARE IN PROGRESS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONNE 2 (PWR) • COOLANT PURIFICATION SYSTEM • AUXILIARY COOLING SYSTEM • LEAK • REACTOR COOLANT • HEAT EXCHANGERS

100006

PENETRATION ROOM VALVES LEAK IN EXCESS OF LIMIT AT UCONNE 2

NUREG PWR CO., N.C.

2 PGS. LTR NRC 75-12 TO U.S. NRC, REGION 11, OCT. 7, 1975, DOCKET 50-270, TYPE--PWR, NRC--BEN, AE--DUKE

CAUSE - DIRTY SEATING SURFACES. DURING LOCAL LEAK TESTS ON THE REACTOR BUILDING PURGE SYSTEM WITH THE UNIT IN COLD SHUTDOWN, AN INTAKE VALVE AND A DISCHARGE VALVE WERE FOUND TO HAVE EXCESSIVE LEAKAGE. THE INTAKE VALVE WAS NOT CLOSING COMPLETELY. IT WAS READJUSTED. SEATING SURFACES ON THE DISCHARGE VALVE WERE DRY AND DIRTY. THEY WERE CLEANED AND LUBRICATED. DURING RETESTING, THE GASKET ON THE OTHER DISCHARGE VALVE WAS FOUND TO NEED REPLACING. IT WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONNE 2 (PWR) • LEAK RATE • VALVES • CONTAINMENT PURGE • FAILURE, MAINTENANCE ERROR • CAUD • LUBRICATION

107221

UNPLANNED RELEASE OF RADIOACTIVE LIQUID AT OCONEE 2

DUKE POWER CO., CHARLOTTE, N.C.

3 PGS. LTR W/UE-270/75-15 TO U.S. NRC, REGION II, OCT. 17, 1975, DOCKET 50-270, TYPE--PMR, NRC--BEN, AE--DUKE

CAUSE - INADEQUATELY INSTALLED PIPE. ROUTINE CHEMISTRY TESTS PERFORMED ON UNITS 1 AND 2 TURNING BUILDING SUMP REVEALED A MEASURABLE AMOUNT OF RADIOACTIVITY. A PIPE CONNECTING UNIT 2 COMPONENT MAIN PUMP DISCHARGE HEADER TO THE TURBINE BUILDING TRENCH WHICH LEADS TO THE SUMP WAS FOUND. THE LINE WAS INADEQUATELY INSTALLED. IT SHOULD DISCHARGE TO THE COMPENSATE STORAGE TANK. THE ISOLATION VALVE IN THE LINE WAS LEAKING. A BLIND FLANGE WAS INSTALLED IN THE LINE UNTIL THE LEAK COULD BE REMOVED. CALCULATED RELEASE WAS WELL BELOW THE LIMIT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 2 (PMR) • FAILURE, INSTALLATION ERROR • PIPES AND PIPE FITTINGS • WASTE HANDLING • RADIOACTIVITY RELEASE

107222

TEMPERATURE DETECTOR IN MPS CHANNEL A FAILS AT OCONEE 2

DUKE POWER CO., CHARLOTTE, N.C.

2 PGS. LTR W/UE-270/75-20 TO U.S. NRC, REGION II, OCT. 23, 1975, DOCKET 50-270, TYPE--PMR, NRC--BEN, AE--DUKE

CAUSE - UNKNOWN. ERATIC TEMPERATURE INDICATIONS WERE OBSERVED ON ONE LEG OF THE REACTOR CIRCUIT SYSTEM. INDICATIONS VARIED BETWEEN 507 F AND 592 F. THE RTD IN THE INSTRUMENT STRING WAS THE CAUSE. THIS CHANNEL WAS PLACED IN MANUAL BYPASS. THE EXACT CAUSE CANNOT BE DETERMINED UNTIL THE RTD CAN BE REMOVED. A SPARE RTD WILL BE USED IN THE CHANNEL. THE FAILED RTD IS A ROSEMOUNT TYPE 177 GV S/N 2314.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 2 (PMR) • PERSONS, TEMPERATURE • INSTRUMENT, ABNORMAL INDICATION • REACTOR SAFETY SYSTEM • FAILURE, INSTRUMENT

107223

INCORRECT LETDOWN FILTER VENT REMOVED AT OCONEE 2

DUKE POWER CO., CHARLOTTE, N.C.

2 PGS. LTR W/UE-270/75-15 TO U.S. NRC, REGION II, OCT. 24, 1975, DOCKET 50-270, TYPE--PMR, NRC--BEN, AE--DUKE

CAUSE - MAINTENANCE ERROR. WHILE PERFORMING ROUTINE MAINTENANCE ON LETDOWN FILTER 2A WITH THE UNIT IN COLD SHUTDOWN, THE QUICK DISCONNECT VENT FITTING FROM LETDOWN FILTER 2A WAS INADVERTENTLY REMOVED. REACTOR COOLANT WAS RELEASED TO THE LETDOWN FILTER ROOM UNTIL THE CONTROL ROOM OPERATOR ISOLATED THE VENT. THE VENT WAS REPLACED. LABEL 2A HAD BEEN REMOVED FROM THE WALL. LABEL 2A WAS POSSIBLY OBLSCURED FROM VIEW. LARGE LETTERS WILL BE PAINTED ON THE WALLS BESIDE THE FILTERS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 2 (PMR) • PIPES AND PIPE FITTINGS • COOLANT PURIFICATION SYSTEM • FILTERS • FAILURE, MAINTENANCE ERROR • IDENTIFICATION • RADIOACTIVITY RELEASE • REACTOR COOLANT • MAINTENANCE AND REPAIR

107527

INSTRUMENT AIR LINES TO HIGH PRESSURE INJECTION VALVES ISOLATED AT OCONEE 2

DUKE POWER CO., CHARLOTTE, N.C.

2 PGS. LTR W/UE-270/75-16 TO U.S. NRC, REGION II, OCT. 31, 1975, DOCKET 50-270, TYPE--PMR, NRC--BEN, AE--DUKE

CAUSE - PERSONNEL ERROR. NUCLEAR CHEMISTRY PERSONNEL WERE ATTEMPTING TO ISOLATE THE FILTERED WATER SUPPLY FOR FAUCET REPAIRS. THEY INADVERTENTLY CLOSED THE AIR SUPPLY ISOLATION VALVES INSTEAD OF THE WATER VALVES. THIS CAUSED A VALVE TO CLOSE PREVENTING REACTOR COOLANT LETDOWN FLOW AND ANOTHER VALVE TO OPEN ALLOWING EXCESS REACTOR COOLANT MAKEUP. THE RESULTING INCREASE IN PRESSURIZER LEVEL WAS NOTICED IMMEDIATELY AND THE AIR SUPPLY VALVES REOPENED. VALVES WILL BE IDENTIFIED. VALVE OPERATION WILL BE ASSIGNED TO LOGICIZANT PERSONNEL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 2 (PMR) • PNEUMATIC SYSTEM • VALVES • CONTAINMENT ISOLATION • FAILURE, OPERATOR ERROR • MAINTENANCE AND REPAIR

107528

LETDOWN FLOW INADVERTENTLY ISOLATED AT OCONEE 2

DUKE POWER CO., CHARLOTTE, N.C.

3 PGS. LTR W/UE-270/75-17 TO U.S. NRC, REGION II, NOV. 3, 1975, DOCKET 50-270, TYPE--PMR, NRC--BEN, AE--DUKE

CAUSE - IMPROPER COMMUNICATION. A 3-WAY VALVE DIVERTING LETDOWN FLOW TO EITHER THE LETDOWN STORAGE TANK OR THE REACTOR COOLANT BLEED MAKEUP TANKS WAS CYCLED SEVERAL TIMES TO CHECK IT. THE

107520 MONTMONT

LIFT SWITCH WAS FOUND TO REQUIRE ADJUSTMENT. THE CONTROL ROOM OPERATOR CLOSED THE ISOLATION VALVE TO THE DIESEL MOUNT TANKS. DURING THE ADJUSTMENT, THE 3-WAY SWITCH WAS POSITIONED TO THE WROD MOUNT TANK CAUSING A RELIEF VALVES TO OPEN MOMENTARILY. THE 3-WAY VALVE WAS PLACED IN NORMAL POSITION AND LEAKAGE FLOW REINITIATED. THERE WAS A MISUNDERSTANDING BETWEEN MAINTENANCE AND OPERATIONS ON WHAT WAS REQUIRED FOR THE SWITCH ADJUSTMENT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ISSUE 2 (PWR) • MOUNTAIN ISOLATION • MAIN COOLING SYSTEM • MAINTENANCE AND REPAIR • COMMUNICATION • FAILURE, OPERATION ERROR

100205

REACTOR BUILDING ELECTRICAL PENETRATION FAILS AT ISSUE 2

Duke Power Co., Charlotte, N.C.

3 PGS. LTR W/UE-210/75-10 TO U.S. NRC, REGION II, NOV. 19, 1975, DOCKET 50-270, TYPE--PWR, NRC--BEN, AE--DURE

CAUSE - CRACKED BUSHING. DURING A ROUTINE MONTHLY CHECK OF SFG GAS PRESSURE WHILE THE REACTOR WAS AT 75% POWER, THE REACTOR BUILDING ELECTRICAL PENETRATION FOR REACTOR COOLANT PUMP MOTOR 202 WAS FOUND TO BE LEAKING. A REACTOR SHUTDOWN WAS INITIATED. A CRACKED BUSHING IN THE PENETRATION ON THE PENETRATION FLUP SIDE HAD ALLOWED THE SFG GAS TO ESCAPE. THE CRACKED BUSHING WAS REPLACED WITH THE PENETRATION IN PLACE AND TESTED FOR LEAKAGE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ISSUE 2 (PWR) • MOUNTAIN PENETRATION, ELECTRICAL • LEAK • TEST, SYSTEM OPERABILITY • FAILURE, EQUIPMENT • SEAL • MOUNTAIN INTEGRITY • REACTOR SHUTDOWN

100225

ES VALVE FAILS TO CLOSE DURING COOLANT SYSTEM FILL AT ISSUE 2

Duke Power Co., Charlotte, N.C.

3 PGS. LTR W/UE-270/75-19 TO U.S. NRC, REGION II, DEC. 8, 1975, DOCKET 50-270, TYPE--PWR, NRC--BEN, AE--DURE

CAUSE - MOTOR MOUNT BOLTS LOOSE. DURING FILLING OF THE REACTOR COOLANT SYSTEM FOLLOWING A SHUTDOWN FOR REACTOR COOLANT PUMP SEAL REPAIR, AN ATTEMPT WAS MADE TO CYCLE A VALVE IN THE LINE BETWEEN THE DONATEE WATER STORAGE TANK AND THE LOW PRESSURE INJECTION PUMPS. THE VALVE OPENED BUT FAILED TO CLOSE. OTHER VALVES WERE IMMEDIATELY CLOSED TO STOP FLOW FROM DONATEE TO THE COOLANT SYSTEM. THE VALVE MOTOR FAILED DUE TO BINDING BETWEEN THE VALVE STEM AND MOTOR OPERATOR. THE 4 BOLTS SECURING THE MOTOR OPERATOR TO THE VALVE BODY WERE LOOSE. THE MOTOR WAS REPLACED. THE BOLTS WERE TIGHTENED AND BLOCK WEDGED TO PREVENT LOOSENING. BOLTS WERE LOOSE ON 2 OTHER SIMILAR VALVES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ISSUE 2 (PWR) • VALVES • LPLI • FAILURE, DESIGN ERROR • VALVE OPERATORS • FASTENER • FAILURE, COMMON MODE • TEST, SYSTEM OPERABILITY • MISPLICATION • FAILURE, EQUIPMENT

100220

QUENCH TANK INADVERTENTLY PUMPED BELOW OPERATING LIMIT AT ISSUE 2

Duke Power Co., Charlotte, N.C.

3 PGS. LTR W/UE-270/75-20 TO U.S. NRC, REGION II, DEC. 9, 1975, DOCKET 50-270, TYPE--PWR, NRC--BEN, AE--DURE

CAUSE - OPERATOR ERROR. IN RESPONSE TO A QUENCH TANK HIGH PRESSURE ALARM WITH THE REACTOR AT 100% POWER, THE OPERATOR STARTED DECREASING WATER LEVEL BY PUMPING. ABOUT 3 MINUTES LATER, A QUENCH TANK LOW LEVEL ALARM WAS RECEIVED BUT WAS MISINTERPRETED AS A HIGH PRESSURE ALARM BY A SECOND OPERATOR SO PUMPING CONTINUED FOR 30 MINUTES. LEVEL DECREASED TO 50 INCHES BEFORE THE ERROR WAS NOTICED. ALARM LEVEL IS 85 INCHES. PUMPING WAS STOPPED IMMEDIATELY AND LEVEL RESTORED TO NORMAL. PERSONNEL TOLD TO CONSIDER EACH ALARM AS A NEW AND DIFFERENT ALARM.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ISSUE 2 (PWR) • SYSTEM CAPACITY • STORAGE CONTAINER • ENGINEERED SAFETY FEATURE • FAILURE, OPERATION ERROR • ANNUNCIATIONS

100200

ADDITIONAL INFORMATION ON RADIOACTIVE RELEASE THROUGH SUMP AT ISSUE 2

Duke Power Co., Charlotte, N.C.

2 PGS. LTR W/ SUPPLEMENTAL INFORMATION TO 50-270/75-15 TO U.S. NRC, REGION II, DEC. 29, 1975, DOCKET 50-269, TYPE--PWR, NRC--BEN, AE--DURE

CAUSE - PROCEDURAL DEFICIENCY. AS REPORTED ON OCT. 17, 1975, AN UNPLANNED RELEASE OF RADIOACTIVE LIQUID OCCURRED THROUGH THE TURBINE BUILDING SUMP. THE LINE WHICH ALLOWED THE DISCHARGE WAS ORIGINALLY INTENDED TO CONNECT THE SECONDARY SIDE OF THE STEAM GENERATOR TO THE CONDENSATE STORAGE TANK VIA THE COMPONENT DRAIN PUMP, ALLOWING QUICK DRAINAGE DURING INITIAL TESTING. THE

100230 CONTINUED

LINE HAD BEEN CUT FOR A SYSTEM FLUSH. THIS WAS NOT PROBABLY IDENTIFIED. THIS RESULTED FROM A PROCEDURAL INADEQUACY IN THE PROPERATIONAL TEST PROCEDURE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCNEE 2 (PWR) • RADIOACTIVITY RELEASE • FAILURE, ADMINISTRATIVE CONTROL • PROCEDURES AND MANUALS • TESTING • TEST, PREOPERATIONAL • GIVEN • FAILURE, PIPE

003540

INADEQUATE ISOLATION OF REACTOR LOWVOLTAGE FEEDER AT UCNEE 3

DUNE POWER COMPANY, NORTH CAROLINA

3 PAGES, LETTER WITH NO REPORT 75/5 TO NRC, REGION 2, JANUARY 31, 1975, DOCKET 50-287, TYPE--PWR, NRC--BOW, AE--DUNE

CAUSE - LEAK IN AIR SUPPLY LINE TO BREAKER. TWO POWER CIRCUIT BREAKERS TRIPPED AND ISOLATED THE OVERHEAD TRANSMISSION LINE FROM REACTOR TO THE 230 KV SWITCHYARD. THE AIR SUPPLY LINE TO AN AIR CIRCUIT BREAKER CAME LOOSE RESULTING IN THE OPERATION OF THE PILOT WIRE MONITORING RELAY WHICH TRIPPED THE 2 BREAKERS. THE AIR SUPPLY LINE WAS NOT ACCURATELY SUPPORTED AT A COUPLING. VIBRATION CAUSED THE LINE TO WALK LOOSE FROM THE COUPLING. THE AIR LINE WAS RECONNECTED. ADDITIONAL SUPPORTS WILL BE ADDED. THE PILOT WIRE MONITORING SYSTEM TRIP FUNCTION WILL BE DELETED WITH THE ALARM FUNCTION RETAINED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT • ELECTRIC POWER • MODIFICATION • FAILURE, DESIGN ERROR • OFF SITE • PNEUMATIC SYSTEM • BREAKER • UCNEE 3 (PWR)

000705

REACTOR COOLANT TEMPERATURE INDICATION LOW AT UCNEE 3

DUNE POWER COMPANY, N.C.

3 PAGES, LETTER WITH NO REPORT 75/1 TO NRC, REGION 2, FEBRUARY 10, 1975, DOCKET 50-287, TYPE--PWR, NRC--BOW, AE--DUNE

CAUSE - LOW RESISTANCE TO GROUND FROM LEAK. A REACTOR PROTECTIVE SYSTEM CHANNEL REACTOR COOLANT TEMPERATURE WAS OBSERVED TO BE INDICATING 5 P LOW. THE RESISTANCE TEMPERATURE DETECTOR CABLE FROM THE REACTOR BUILDING TO THE RPS CABINET HAD A LOW RESISTANCE TO GROUND. CONDENSATION OF STEAM FROM A LEAKING PERMEATION VALVE IN THE PENETRATION ADJY HAD HIT THE CABLE CAUSING THE LOW RESISTANCE TO GROUND. A SECOND CHANNEL WAS ALSO AFFECTED. THE REACTOR WAS SHUT DOWN AND THE CABLES WERE UNLID. RESISTANCE TO GROUND RETURNED TO NORMAL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

REACTOR SAFETY SYSTEM • CONDENSATION • FAILURE, INSTRUMENT • MAIN CYCLING SYSTEM • ELECTRICAL CONDUCTION • REACTOR SHUTDOWN • CABLES AND CONNECTORS • UCNEE 3 (PWR) • SENSORS, TEMPERATURE

100092

LPCI VALVE CONTROL POWER FUSE FAILS AT UCNEE 3

DUNE POWER COMPANY, N.C.

2 PAGES, LETTER WITH NO REPORT 75/7 TO U.S. NRC, REGION 2, FEBRUARY 19, 1975, DOCKET 50-287, TYPE--PWR, NRC--BOW, AE--DUNE

CAUSE - UNKNOWN. WHILE A SCHEDULED SHUTDOWN WAS IN PROGRESS, ATTEMPTS TO REMOTELY OPEN A VALVE TO ESTABLISH HEAT FLOW WITH THE LOW PRESSURE INJECTION SYSTEM WERE UNSUCCESSFUL. A FUSE IN THE CONTROL POWER TRANSFORMER HAD FAILED. THE FUSE WAS REPLACED AND THE VALVE OPERATED PROPERLY. NO CAUSE WAS FOUND FOR THE ULCAH FUSE. IT IS ASSUMED THAT THE FUSE FAILED FROM A VOLTAGE SURGE ON A DEFECTIVE FUSE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INSTRUMENT, PROTECTIVE • ELECTRIC POWER • FAILURE, INSTRUMENT • UCNEE 3 (PWR) • VALVES • LPCI • TRANSFORMERS

100300

VALVE CONTROL POWER FUSE FAILS AT UCNEE 3

DUNE POWER COMPANY, N.C.

2 PAGES, LETTER WITH NO REPORT 75/2, FEBRUARY 19, 1975, DOCKET 50-287, TYPE--PWR, NRC--BOW, AE--DUNE

CAUSE - UNKNOWN. WHILE THE REACTOR WAS BEING SHUT DOWN, ATTEMPTS TO REMOTELY OPEN A VALVE TO ESTABLISH HEAT FLOW WITH THE LPS WERE UNSUCCESSFUL. A FUSE IN THE CONTROL POWER TRANSFORMER HAD FAILED. THE FUSE WAS REPLACED AND PROPER VALVE OPERATION WAS VERIFIED. NO CAUSE COULD BE FOUND. IT WAS CONCLUDED THAT FAILURE RESULTED FROM EITHER A VOLTAGE SURGE ON A DEFECTIVE FUSE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

100300 CONTINUOUS
INSTRUMENT, PROTECTIVE + ELECTRIC POWER + FAILURE, INSTRUMENT + SHUTDOWN COOLING SYSTEM + DECREE 3 (PMR) +
VALUES

100301
PROPER OVERLAP BETWEEN CONTROL ROD GROUPS NOT PREVENTED AT DECREE 3
JUNE POWER COMPANY, N.C.
3 PAGES, LETTER WITH NO REPORT 75/3 TO U.S. NRC, REGION 2, FEBRUARY 26, 1975, DOCKET 50-277, TYPE--PMR, NRC--B+W,
AE--DURE

CAUSE - OPERATOR ERROR. THE INTEGRATED CONTROL SYSTEM INITIATED A RUMBLE FROM 50 TO 55E POWER. SIX MINUTES LATER IT WAS NOTED THAT CONTROL ROD GROUPS 6 AND 7 HAD AN OVERLAP OF 10E WHICH IS BEYOND THE 2 TO 3E LIMIT. THE POSITION INDICATION SWITCH FOR A ROD HAD FAILED PRIOR TO THIS CAUSING THE GROUP AVERAGE POSITIONS TO INDICATE LOWER THAN ACTUAL POSITION. COMING RECOVERY FROM THE RUMBLE, THE OPERATOR FAILED TO MONITOR INDIVIDUAL ROD POSITION TO MAINTAIN A PROPER OVERLAP. THE RODS WERE READJUSTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM
(CHANGE 02.00)

CONTROL ROD INTERACTION + CONTROL ROD PROGRAM + FAILURE, OPERATOR ERROR + REACTIVITY EFFECT + DECREE 3 (PMR)

100304
ENGINEERED SAFEGUARDS LOGIC BUFFER FAILS AT DECREE 3
JUNE POWER COMPANY, N.C.
3 PAGES, LETTER WITH NO REPORT 75/6 TO U.S. NRC, REGION 2, MARCH 12, 1975, DOCKET 50-287, TYPE--PMR, NRC--B+W,
AE--DURE

CAUSE - INTERMITTENT REACTIVITY CONTROL FAILURE. DURING TESTING OF ENGINEERED SAFEGUARDS ANALOG CHANNEL 1 WHILE OPERATING THE REACTOR AT 75% POWER, ONLY 1 OF THE 2 DIGITAL CHANNELS TRIPPED. WITH TRIPPER JUMPING REACTIVITY. THE APPARENT CAUSE WAS INTERMITTENT FAILURE OF ONE SET OF CONTACTS OF A RELAY UNIT DELAY ON THE OUTPUT OF THE ANALOG CHANNEL 1 LOGIC BUFFER. THE LOGIC BUFFER WAS REPLACED EVEN THOUGH THE FAILURE COULD NOT BE REPRODUCED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
(CHANGE 02.00)

CONTROL SYSTEM + FAILURE, INSTRUMENT + TEST, SYSTEM OPERABILITY + ENGINEERED SAFETY FEATURE + DECREE 3 (PMR) +
LIMITED ACCESS/INTERLUPTERS + DELAYS

100310
"EMERGENCY MANUAL" START PUSHBUTTONS IMPERFECT AT DECREE 3
JUNE POWER COMPANY, N.C.
1 PAGE, LETTER TO U.S. NRC, REGION 2, MARCH 25, 1975, DOCKET 50-287, TYPE--PMR, NRC--B+W, AE--DURE

CAUSE - DESIGN ERROR. A TEST ENGINEER NOTICED THAT THE ELECTRICAL DRAWINGS DID NOT SHOW THE WIRING FOR THE REACTOR EMERGENCY START PUSHBUTTONS TO BE COMPLETE IN THE CONTROL ROOM. THE PUSHBUTTONS WERE WIRED TO A READY TERMINAL BOARD BUT NOT FROM THE TERMINAL BOARD TO THE REACTOR EMERGENCY START PANELS. THE AUTOMATIC ACTUATION WAS NOT AFFECTED. THIS WAS A DESIGN ERROR IN WIRING THE CIRCUIT BETWEEN THE TERMINAL BOARD AND THE START PANEL. QUALITY ASSURANCE COMPARED INSTALLATION TO THE DESIGN DRAWING AND THEREFORE DID NOT CATCH THE ERROR. A MODIFICATION HAS BEEN COMPLETED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
(CHANGE 02.00)

CONTROL SYSTEM + EMERGENCY POWER, ELECTRIC + MODIFICATION + FAILURE, DESIGN ERROR + REVIEW + CABLES AND
CONNECTIONS + DECREE 3 (PMR)

100314
REACTOR UNDERGROUND FEEDER INADVERTENTLY ISOLATED AT DECREE 3
JUNE POWER COMPANY, N.C.
2 PAGES, LETTER WITH NO REPORT 75/6 TO U.S. NRC, REGION 2, APRIL 11, 1975, DOCKET 50-287, TYPE--PMR, NRC--B+W,
AE--DURE

CAUSE - PROCEDURAL DEFICIENCY. DURING A REACTOR EMERGENCY START TEST FROM UNIT 3 CONTROL ROOM WHILE THE REACTOR WAS AT POWER, THE UNDERGROUND FEEDER FROM REACTOR TO UNIT 3 WAS INADVERTENTLY ISOLATED WHILE PREPARING TO TEST THE SECOND REACTOR UNIT. THE PROCEDURE DID NOT CAUTION THAT A REACTOR UNIT ISOLATES FEEDBACK IN THE OPENING OF THE ASSOCIATED BREAKER IN THE UNDERGROUND FEEDER. THE FEEDER WAS ISOLATED FOR 5 MINUTES. THE PROCEDURE WAS MODIFIED TO ASSURE THAT 1 OF THE 2 OPERATORS TO THE FEEDER IS CLOSED AT ALL TIMES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
(CHANGE 02.00)

EMERGENCY POWER, ELECTRIC + PROCEDURES AND MANUALS + ELECTRIC POWER + TEST, SYSTEM OPERABILITY + FAILURE,
ADMINISTRATIVE CONTROL + BREAKER + DECREE 3 (PMR)

103812

PERSONNEL MATCH INTERLOCKS FAIL AT OCONEE 3
DUKE POWER COMPANY, N.C.

3 PAGES, LETTER WITH OR 75-3 TO U.S. NRC, REGION 2, MAY 23, 1975, DOCKET 50-287, TYPE--PWR, MFG--BEM, AE--DUKE

CAUSE - EXCESSIVE WEAR WEAR. DURING A MAINTENANCE OUTAGE, THE OPERATOR RECEIVED AN INDICATION THAT BOTH HANDS TO THE PERSONNEL MATCH WERE OPEN SIMULTANEOUSLY. THE MATCH INTERLOCK MECHANISM HAD BECOME OUT OF ADJUSTMENT AND WAS IMPERABLE. THERE WAS EXCESSIVE WEAR OF THE RATCHET GEAR TEETH IN THE INTERLOCK MECHANISM. A NEW RATCHET GEAR AND ANOTHER INTERMEDIATE GEAR HAVE BEEN REPLACED. A SPRING ASSIST HAS BEEN ADDED TO GIVE MORE POSITIVE DISPLACEMENT OF THE INTERLOCK CABLE. RECOMMENDED SPARE PARTS ARE NOW ON SITE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 3 (PWR) + CONTAINMENT INTEGRITY + INSTRUMENT, INTERLOCK + CONTAINMENT AIR LOCK + FAILURE, DESIGN ERROR + MODIFICATION

103440

SOURCE RANGE NUCLEAR INSTRUMENTATION IMPERABLE AT OCONEE 3
DUKE POWER CO., CHARLOTTE, N.C.

3 PAGES, LETTER WITH NO REPORT 75-6 TO NRC, REGION 2, JUNE 3, 1975, DOCKET 50-287, TYPE--PWR, MFG--BEM, AE--DUKE

CAUSE - POWER SUPPLY SWITCH OFF. DURING A LOSS OF ELECTRICAL LOAD TEST, A REACTOR TRIP OCCURRED. THE SOURCE RANGE NUCLEAR INSTRUMENTATION CHANNELS DID NOT COME ON SCALE. CHANNEL NI-1 WAS IMPERABLE DUE TO FAILURE OF THE PRE-AMPLIFIER. CHANNEL NI-2 HAD A DE-ENERGIZED HIGH VOLTAGE POWER SUPPLY. DURING THE REPAIR OF NI-1, THE POWER SUPPLY SWITCH FOR NI-2 HAD BEEN TURNED ON AND OFF SEVERAL TIMES. IT HAD BEEN LEFT OFF. IT WAS IMMEDIATELY TURNED ON. REPAIR OF NI-1 WAS COMPLETED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 3 (PWR) + INSTRUMENT, STARTUP RANGE + FAILURE, MAINTENANCE ERROR + INSTRUMENT, SWITCH + ELECTRIC POWER

103445

EMERGENCY FEEDWATER PUMP IMPERABLE AT OCONEE 3

DUKE POWER CO., CHARLOTTE, N.C.

2 PAGES, LETTER TO NRC, REGION 2, JUNE 11, 1975, DOCKET 50-287, TYPE--PWR, MFG--BEM, AE--DUKE

CAUSE - PACKING GLAND TOO TIGHT. DURING TESTING WITH THE REACTOR AT FULL POWER, THE EMERGENCY FEEDWATER PUMP WAS DETERMINED TO BE IMPERABLE. A LEAKING PACKING GLAND HAD BEEN REPAIRED 11 DAYS EARLIER. THE PACKING WAS APPARENTLY SET TOO TIGHT AND THE PUMP RETURNED TO SERVICE WITHOUT VERIFYING OPERABILITY. PERSONNEL WERE REMINDED OF THE IMPORTANCE OF VERIFYING OPERABILITY PRIOR TO RETURNING EQUIPMENT TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 3 (PWR) + PUMPS + FEEDWATER + TEST, SYSTEM OPERABILITY + FAILURE, MAINTENANCE ERROR + FAILURE, EQUIPMENT + SEAL + TESTING

103892

REACTOR COOLANT SYSTEM COOLDOWN RATE EXCESSIVE AT OCONEE 3

DUKE POWER COMPANY, N.C.

2 PAGES, LETTER WITH AOR 75-7 TO U.S. NRC, REGION 2, JUNE 27, 1975, DOCKET 50-287, TYPE--PWR, MFG--BEM, AE--DUKE

CAUSE - OPERATOR ERROR. DURING A ROUTINE SHUTDOWN FOR MAINTENANCE, A MINOR SYSTEM TRANSIENT OCCURRED WHICH RESULTED IN OPENING A POWER-ACTUATED PRESSURIZER RELIEF VALVE WITH REACTOR POWER AT 15%. THE VALVE REMAINED OPEN AND THE RC SYSTEM DEPRESSURIZATION CONTINUED UNTIL THE ISOLATION VALVE WAS CLOSED. THE SHUTDOWN CONTINUED WITH A COOLDOWN RATE OF 100 F/HR. HOWEVER, WHEN THE INITIAL DROP IN TEMPERATURE FROM DEPRESSURIZATION WAS INCLUDED THE RATE EXCEEDED THE 100 F/HR LIMIT BY 1 F/HR. BORIC ACID CRYSTAL BUILDUP ON THE CONNECTING PIN OF THE LEVER ARM OF THE PILOT VALVE CAUSED THE VALVE TO REMAIN OPEN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 3 (PWR) + COOLING + RATE + RAIN COOLING SYSTEM + FAILURE, OPERATOR ERROR + SHUTDOWN + VALVES + PRESSURE RELIEF + PRESSURE TRANSIENT

103893

STEAM GENERATOR SAMPLE LINE VALVE FAILS TO CLOSE AT OCONEE 3

DUKE POWER COMPANY, N.C.

2 PAGES, LETTER WITH UER 75-7 TO U.S. NRC, REGION 2, JULY 1, 1975, DOCKET 50-287, TYPE--PWR, MFG--BEM, AE--DUKE

103893 PLANTINURUP

CAUSE - NEAR SPRING IN OPERATION. DURING TESTING WITH THE UNIT AT FULL POWER, A STEAM GENERATOR SAMPLE LINE ISOLATION VALVE FAILED TO CLOSE ON COMMAND. THIS VALVE IS NORMALLY CLOSED AND IS OPENED ONLY FOR SAMPLING. THE APPARENT CAUSE WAS A NEAR SPRING IN THE VALVE OPERATOR. IT WOULD CLOSE WITH NO PRESSURE IN THE SAMPLE LINE BUT NOT WITH PRESSURE. A NEAR SPRING HAS BEEN ORDERED. UNTIL THE VALVE OPERATOR CAN BE REPAIRED, THE VALVE HAS BEEN LOCKED CLOSED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONEE 3 (PWR) • VALVES • CONTAINMENT ISOLATION • SAMPLING • STEAM GENERATOR • TEST, SYSTEM OPERABILITY • FAILURE, EQUIPMENT • VALVE OPERATORS

103891

SET POINT UPRIFT IN PRESSURE SWITCH AT UCONEE 3

DURE POWER COMPANY, N.C.

2 PAGES, LETTER WITH ACR 75-8 TO U.S. NRC, REGION 2, JULY 3, 1975, DOCKET 50-287, TYPE--PWR, NRC--BEN, AE--DURE

CAUSE - INSTRUMENT DRIFT. DURING CALIBRATION WITH THE UNIT IN COLD SHUTDOWN, 1 OF THE 3 REACTOR BUILDUP EQUIPPED SAFEGUARDS PRESSURE TRANSMITTERS TRIPPED AT 4.615 PSIG WHICH EXCEEDS THE 4.0 PSIG UPPER LIMIT. THE APPARENT CAUSE WAS INSTRUMENT UPRIFT. THE TRANSMITTER WAS RECALIBRATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONEE 3 (PWR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SENSORS, PRESSURE • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT • SET POINT • UPRIFT • EMERGENCY COOLING SYSTEM • BUILDING

104307

PERSONNEL MATCH INTERLOCKS FAIL AT UCONEE 3

DURE POWER COMPANY, N.C.

2 PAGES, LETTER WITH ACR 75-8 TO U.S. NRC, REGION 2, JULY 14, 1975, DOCKET 50-287, TYPE--PWR, NRC--BEN, AE--DURE

CAUSE - PINCHED CABLE. DURING A MAINTENANCE OUTAGE, IT WAS DETERMINED THAT THE INTERLOCK MECHANISM ON THE PERSONNEL MATCH HAD FAILED. ADMINISTRATIVE CONTROLS WERE TAKEN TO ASSURE THAT BOTH DURENS WERE NOT OPENED SIMULTANEOUSLY EVEN THOUGH CONTAINMENT INTEGRITY WAS NOT REQUIRED. FAILURE WAS CAUSED FROM A PINCHED CABLE WHICH RESTRICTED MOVEMENT OF THE PAILS. THE INTERLOCKS WERE ADJUSTED AND THE MATCH RETURNED TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONEE 3 (PWR) • INSTRUMENT, INTERLOCK • CONTAINMENT AIR LOCK • CONTAINMENT INTEGRITY • FAILURE, MAINTENANCE • BUILDING

104302

POWER LEVEL CUTOFF EXCEEDED DURING TRANSIENT XENON CONDITIONS AT UCONEE 3

DURE POWER COMPANY, CHARLOTTE

3 PAGES, LETTER WITH ACR 75-9 TO U.S. NRC, REGION 2, JULY 25, 1975, DOCKET 50-287, TYPE--PWR, NRC--BEN, AE--DURE

CAUSE - TURBINE BYPASS VALVE OPENED. THE UNIT WAS OPERATING AT 80% POWER WHILE WAITING FOR XENON TO APPROACH EQUILIBRIUM. THE ANNUNCIATOR SOUNDED INDICATING THAT POWER HAD INCREASED TO 84% EXCEEDING THE 82.5% POWER LEVEL CUTOFF. LOOP B TURBINE BYPASS VALVES HAD OPENED. THE OPERATOR REDUCED POWER AND CLOSED THE BYPASS VALVES. THE VALVES OPENED BECAUSE OF A FAILED MODULE WITHIN THE VALVE CONTROLS. THE FAILED MODULE WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONEE 3 (PWR) • TRANSIENT • REACTOR POWER • XENON • FAILURE, EQUIPMENT • VALVES • TURBINE • CONTROL SYSTEM • ELECTRONIC FUNCTION UNITS

104301

BORATED WATER STORAGE TANK LEVEL LOW AT UCONEE 3

DURE POWER COMPANY, CHARLOTTE

2 PAGES, LETTER WITH ACR 75-10 TO U.S. NRC, REGION 2, JULY 25, 1975, DOCKET 50-287, TYPE--PWR, NRC--BEN, AE--DURE

CAUSE - INSTRUMENT CALIBRATION ERROR. DURING A SURVEILLANCE TEST WITH THE REACTOR AT FULL POWER, BOTH LEVEL TRANSMITTERS FOR THE BORATED WATER STORAGE TANK WERE FOUND TO BE OUT OF CALIBRATION BY GREATER THAN THE CALIBRATION TOLERANCE. WHEN THEY WERE PROPERLY CALIBRATED, ONE CHANNEL INDICATED THAT THE LEVEL WAS BELOW THE 46 FT LIMIT BY 0.5 FT. THE TANK LEVEL WAS INCREASED. SINCE BOTH TRANSMITTERS WERE OUT OF CALIBRATION BY ABOUT 1% SAME MAGNITUDE, IT IS POSTULATED THAT THE INITIAL CALIBRATION WAS PERFORMED INCORRECTLY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

104301 *CONTINUE*

UCONEE 3 (PWR) + SYSTEM CAPABILITY + STORAGE CONTAINER + CHEMICAL SPIN + POISON, SOLUBLE + FAILURE, INSTRUMENT + INSTRUMENT CALIBRATION + SENSORS, LEVEL + FAILURE, MAINTENANCE ERROR

104941

ADDITIONAL INFORMATION ON EXCESSIVE COOLDOWN RATE AT UCONEE 3
DUKE POWER CO., CHARLOTTE, N.C.

3 PAGES, LETTER TO NRC, REGION 2, AUG. 8, 1975, DOCKET 50-207, TYPE--PWR, NRC--BEN, AE--DUKE

CAUSE - RELIEF VALVE MALFUNCTION. REACTOR POWER WAS BEING REDUCED FROM 100% TO 15% BY THE INTEGRATED CONTROL SYSTEM FOR A MAINTENANCE SHUTDOWN. WHEN 15% WAS REACHED, UNIT LOAD DEMAND WAS 65 MW AND POWER GENERATION WAS 115 MW. THIS DIFFERENCE EXISTED BECAUSE THE REACTOR WAS OPERATING AT ITS LOWER LIMIT OF 15% AND COULD NOT FOLLOW LOAD DEMAND. A TRANSIENT OCCURRED THAT TRIPPED THE REACTOR. DURING THE TRANSIENT, A RELIEF VALVE OPENED AND FAILED TO CLOSE. THIS TRANSIENT WAS TERMINATED BY CLOSING THE ISOLATION VALVE. COOLDOWN RATE WAS 101 F/MH DURING THE FIRST HOUR. THE RELIEF VALVE FAILED BECAUSE OF HEAT EXPANSION, BORIC ACID CRYSTAL BUILDUP ON THE VALVE LEVER, AND BENDING OF THE SOLENOID SPRING BRACKET.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONEE 3 (PWR) + PRELIMINARY TRANSIENT + THERMAL TRANSIENT + VALVES + PRESSURE RELIEF + COOLING SYSTEM, SECONDARY + STEAM + FAILURE, MAINTENANCE ERROR + SHUTDOWN + SCRAM, AER + REACTOR CONTROL

105174

CONTROL ROD DRIVE BREAKER FAILS TO TRIP AT UCONEE 3
DUKE POWER COMPANY, CHARLOTTE

3 PGS, LTR NUMBER 75-11 TO NRC, REGION 2, AUG. 21, 1975, DOCKET 50-207, TYPE--PWR, NRC--BEN, AE--DUKE

CAUSE - MAL-ADJUSTMENT OF BREAKER. DURING TESTING OF REACTOR PROTECTIVE SYSTEM CHANNEL A WITH THE UNIT AT FULL POWER, A CONTROL ROD DRIVE BREAKER FAILED TO TRIP. SUBSEQUENT ATTEMPTS WERE SUCCESSFUL. THE BREAKER WAS CLEANED, LUBRICATED, ADJUSTED, AND PERFORM TESTED 50 TIMES. IT APPARENTLY WAS NOT PROPERLY ADJUSTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONEE 3 (PWR) + BREAKER + CONTROL ROD DRIVE MECHANISMS + TEST, SYSTEM OPERABILITY + FAILURE, MAINTENANCE ERROR

105274

PERSONNEL MATCH INTERLOCKS FAIL AT UCONEE 3
DUKE POWER COMPANY, CHARLOTTE, N.C.

3 PGS, LTR NUMBER 75-9 TO NRC, REGION 2, AUG. 25, 1975, DOCKET 50-207, TYPE--PWR, NRC--BEN, AE--DUKE

CAUSE - INSUFFICIENT SPRING TENSION. PERSONNEL ENTERING THE REACTOR BUILDING WHILE THE UNIT WAS AT FULL POWER CHECKED THE PERSONNEL MATCH INTERLOCKS AND FOUND THE INNER DOOR INTERLOCK WAS NOT FUNCTIONING PROPERLY. ADMINISTRATIVE CONTROLS WERE TAKEN TO ASSURE THAT BOTH DOORS WERE NOT OPENED SIMULTANEOUSLY. THE SPRING TENSION IN THE INTERLOCK CABLE WAS NOT SUFFICIENT TO OPERATE THE "NO" MECHANISM. THE SPRING TENSION WAS ADJUSTED AND THE INTERLOCKS TESTED 10 TIMES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONEE 3 (PWR) + INSTRUMENT, INTERLOCK + CONTAINMENT AIR LOCK + FAILURE, MAINTENANCE ERROR + CONTAINMENT INTEGRITY

107097

LOW FLOW RESTRICTED BY VALVE FAILURE AT UCONEE 3
DUKE POWER CO., CHARLOTTE, N.C.

2 PGS, LTR NUMBER 207/75-11 TO U.S. NRC, REGION II, NOV. 10, 1975, DOCKET 50-207, TYPE--PWR, NRC--BEN, AE--DUKE

CAUSE - IMPROPER INSTALLATION OF COUPLING PIN. DURING AN OUTAGE WITH THE UNIT IN COLD SHUTDOWN, DIFFICULTY WAS ENCOUNTERED IN MAINTAINING LOW PRESSURE SERVICE WATER FLOW TO DECAY HEAT COOLER 3B ABOVE 1000 GPM. DECAY HEAT COOLER 3A WAS PLACED IN SERVICE. THE OUTLET VALVE FROM THE COOLER HAD FAILED IN THE PARTIALLY CLOSED POSITION RESTRICTING FLOW. THE TAPERED PIN WHICH COUPLES THE VALVE OPERATOR SLEEVE TO THE VALVE SHAFT APPARENTLY WAS INSTALLED FROM THE BOTTOM RATHER THAN FROM THE TOP OF THE SLEEVE. IT VIBRATED LOOSE AND FELL OUT ALLOWING THE THROTTLE VALVE TO CLOSE. THE PIN WAS PROPERLY INSTALLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

UCONEE 3 (PWR) + FLOW + SHUTDOWN COOLING SYSTEM + AUXILIARY COOLING + VALVES + FAILURE, INSTALLATION ERROR + HEAT EXCHANGERS

107096

107896 CONTINUED
CONTAINMENT ISOLATION VALVE FOUND TO BE INOPERABLE AT OCONEE 3
DUKE POWER CO., CHARLOTTE, N.C.
2 PGS. LTR N/AU-20775-12 TO U.S. NRC. REGION II, NOV. 11, 1975, DOCKET 50-207, TYPE--PWR, NRC--BEN, AE--DUKE

CAUSE - BREAKER LEFT OPEN. DURING A TEST WITH THE UNIT AT 100% POWER, THE REACTOR BUILDING AIR SAMPLING LINE INLET VALVE FAILED TO CLOSE. THE VALVE'S ELECTRICAL BREAKER HAD BEEN LEFT OPEN. NO REASON WAS FOUND FOR THE BREAKER BEING OPEN. THE APPARENT CAUSE WAS PERSONNEL ERROR. THE BREAKER WAS CLOSED IMMEDIATELY AND THE VALVE TESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 3 (PWR) • VALVES • CONTAINMENT ISOLATION • SAMPLING • FAILURE, OPERATOR ERROR • TEST, SYSTEM OPERABILITY • BREAKER

107907
WELD ON SAMPLE LINE FROM THE LPI SYSTEM FAILS AT OCONEE 3
DUKE POWER CO., CHARLOTTE, N.C.
3 PGS. LTR N/AU-20775-10 TO U.S. NRC. REGION II, NOV. 13, 1975, DOCKET 50-207, TYPE--PWR, NRC--BEN, AE--DUKE

CAUSE - CAVITATION OCCURRING AT HIGH FLOW RATE. WHILE THE UNIT WAS AT COLD SHUTDOWN AND LOW PRESSURE INJECTION TRAIN 3 A IN THE DECAY HEAT REMOVAL MODE, A 1-INCH SAMPLE LINE FROM THE COOLER DISCHARGE SEPARATED FROM THE DISCHARGE LINE. CAVITATION WAS OCCURRING AT HIGH FLOW RATES IN THE BUTTERFLY CONTROL VALVE LOCATED IN THE COOLER DISCHARGE LINE. THIS CAUSED EXCESSIVE VIBRATION RESULTING IN A WELD FAILURE. THE TRAIN WAS ISOLATED AND THE WELD REPAIRED. A GLOBE VALVE WILL BE OBTAINED FOR THIS LOCATION. CAVITATION HAD OCCURRED AT LOW FLOW ON THE OTHER 2 UNITS BUT THIS IS THE FIRST HIGH FLOW CAVITATION EXPERIENCED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 3 (PWR) • PIPES AND PIPE FITTINGS • SAMPLING • SHUTDOWN COOLING SYSTEM • FAILURE, PIPE • VIBRATION • FAILURE, DESIGN ERROR • HYDRAULIC EFFECT • WELDS

108423
PERSONNEL MATCH INNER DOOR SEAL FAILS AT OCONEE 3
DUKE POWER CO., CHARLOTTE, N.C.
2 PGS LTR N/AU-20775-12 TO U.S. NRC. REGION II, DEC. 8, 1975, DOCKET 50-207, TYPE--PWR, NRC--BEN, AE--DUKE

CAUSE - TEST PRESSURE UNSEATED DOOR. DURING A LEAK RATE TEST ON THE PERSONNEL MATCH WHILE OPERATING AT 95% POWER, IT WAS NOTICED THAT THE INNER DOOR GASKET HAD FAILED WHEN THE TEST PRESSURE REACHED 50 PSIG. THE TEST WAS DISCONTINUED AND THE OUTER DOOR LOCKED CLOSED. A TECH SPEC CHANGE HAS BEEN APPROVED ALLOWING ACCESS THROUGH THE OUTER DOOR FOR REPAIR OF THE INNER DOOR. THE GASKET HAS THEN REPLACED. TEST PRESSURE TENDS TO UNSEAT THE INNER DOOR RESULTING IN GASKET FAILURE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 3 (PWR) • LEAK RATE • SEAL • CONTAINMENT AIR LOCK • TEST, SYSTEM OPERABILITY • TEST, LEAK RATE • CONTAINMENT INTEGRITY

109579
LPCI SAMPLE LINE WELD FOUND DEFECTIVE AT OCONEE 3
DUKE POWER CO., CHARLOTTE, NC
1 PG. LTR N/AU-20775-10 TO U.S. NRC. REGION II, DEC. 17, 1975, DOCKET 50-207, TYPE--PWR, NRC--BEN, AE--DUKE

CAUSE - VIBRATION. A WELD FAILURE ON A SAMPLE LINE FROM LOW PRESSURE INJECTION SYSTEM COOLER 3A WAS REPORTED EARLIER. AS PART OF THE CORRECTIVE ACTION, WELDS ON EACH UNIT WERE DYE PENETRANT TESTED TO DETERMINE DEleterious EFFECTS DUE TO VIBRATION IN THE LPI TRAINS. ONLY ONE WELD ON A 3/4 INCH SAMPLE LINE WAS FOUND UNACCEPTABLE. THIS WELD HAD FAILED PREVIOUSLY. THE WELD AND ITS ADJACENT LINE AND VALVE, INTO WHICH THE CRACK EXTENDED, WERE REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

OCONEE 3 (PWR) • WELDS • PIPES AND PIPE FITTINGS • LPCI • FAILURE, PIPE • FAILURE, DESIGN ERROR • VIBRATION • CRACK

093507
LEAK RATE ON PURGE AIR SUPPLY VALVE EXCEEDS LIMIT AT PALISADES
CONSUMERS POWER COMPANY, RICHMOND
3 PAGES, LETTER WITH NO REPORT 75/1 TO NRC DIVISION OF REACTOR LICENSING, JANUARY 31, 1975, DOCKET 50-255,
TYPE--PWR, NRC--LUM, AE--DELMTEL

CAUSE - INSUFFICIENT LUBRICATION. DURING LOCAL LEAK RATE TESTING WITH THE UNIT IN COLD SHUTDOWN, THE LEAK RATE AROUND THE PACKING OF THE CONTROL VALVE ON THE PURGE AIR SUPPLY EXCEEDED LIMITS.

C93507 CONTINUED

THE MEASURED RATE WAS 3 PSI/MIN. THE OPERATOR NOTED THIS ON THE BOTTOM OF THE TEST SHEET. REPAIRED THE VALVE, AND RERAN THE TEST ENTERING THE NEW VALV IN THE TEST RESULTS. THE LEAK RESULTED FROM IMPROPER LUBRICATION OF THE PACKING AGGRAVATED BY UNUSUAL SERVICE CONDITIONS. THE PACKING WAS PROPERLY LUBRICATED. OPERATORS WANTED TO IDENTIFY LEAK RATE DATA AS BEFORE OR AFTER MAINTENANCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATION ERROR • TEST, LEAK RATE • CONTROL • TEST, SYSTEM OPERABILITY • FAILURE, MAINTENANCE ERROR • SEAL • PALISADES (PM) • LUBRICATION • LEAK • VALVES

C93609

FISSION CHAMBER DELAY DURING SHIPMENT AT PALISADES

CONSUMERS POWER COMPANY, MICHIGAN

2 PAGES, LETTER TO DIRECTORATE OF REGULATORY OPERATIONS NRC, REGION 3, FEBRUARY 3, 1975, DOCKET 50-255, TYPE-- PM, NRC--COND., AE--DECHTEL

CAUSE - UNKNOWN. AN OUT-OF-CORE FISSION CHAMBER CONTAINING ABOUT 1.7 GM OF ENRICHED URANIUM HAD BEEN REPORTED AS LOST IN TRANSIT BUT HAS BEEN DELIVERED. EVERY AIR FREIGHT RECEIVED THE FISSION CHAMBER ON DEC. 4 IN CLEVELAND, OHIO. IT WAS SHIPPED TO CHICAGO DEC. 11, DELIVERED TO ASSOCIATED TRUCK LINE CHICAGO TERMINAL ON DEC. 31, AND ARRIVED AT BENTON HARBOR TERMINAL ON JAN. 9.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CHAMBER, FISSION • INSTRUMENT, NUCLEAR • TRANSPORTATION AND HANDLING • PALISADES (PM) • SPECIAL NUCLEAR MATERIAL

C93502

UNCONTROLLED RELEASE OF LOW LEVEL RADIOACTIVE LIQUID AT PALISADES

CONSUMERS POWER COMPANY, MICHIGAN

2 PAGES, LETTER WITH AD REPORT 3/75 TO NRC DIVISION OF REACTOR LICENSING, FEBRUARY 4, 1975, DOCKET 50-255, TYPE--PM, NRC--COND., AE--DECHTEL

CAUSE - TUBE LEAK. WHILE THE PLANT WAS IN COLD SHUTDOWN, A TUBE IN THE COMPONENT COOLING WATER HEAT EXCHANGER FAILED. THE TUBE WAS PLUGGED AND THE HEAT EXCHANGER RETURNED TO SERVICE. TOTAL ACTIVITY RELEASED WAS .003 MILLCURIE OF CO-60 AND 0.975 MILLCURIE OF TRITIUM.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RADIOACTIVITY RELEASE • PALISADES (PM) • FAILURE, TUBING • LEAK • AUXILIARY COOLING SYSTEM • HEAT EXCHANGERS

C93503

UNCONTROLLED RELEASE OF RADIOACTIVE GAS AT PALISADES

CONSUMERS POWER COMPANY, MICHIGAN

2 PAGES, LETTER WITH AD REPORT 2/75 TO NRC DIVISION OF REACTOR LICENSING, FEBRUARY 4, 1975, DOCKET 50-255, TYPE--PM, NRC--COND., AE--DECHTEL

CAUSE - LOSS OF LOOP SEAL. WITH THE PLANT IN COLD SHUTDOWN, AN OPERATOR STARTED VENTING THE VOLUME CONTROL TANK TO THE WASTE GAS SURGE TANK. ANOTHER OPERATOR OBSERVED A SEVERE VACUUM UPSET FOR THE EVAPORATOR. VENTING WAS STOPPED. BACK PRESSURE FROM VENTING BLEW THE LOOP SEAL ON THE EVAPORATOR VACUUM PUMP - AIR WATER SEPARATOR. TOTAL ACTIVITY RELEASED WAS 1.06 X 10⁻⁶THI MILLCURIE. PROCEDURES WILL BE CHANGED TO VALVE THE EVAPORATOR DISCHARGE LINE TO THE WASTE GAS COLLECTION HEADER PRIOR TO VENTING THE VCT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

AIRBORNE RELEASE • PROCEDURES AND MANUALS • WASTE HANDLING • WATER • SEAL • FAILURE, ADMINISTRATIVE CONTROL • PALISADES (PM)

106579

SEISMIC RESTRAINTS FAIL TO COMPLY WITH DESIGN CRITERIA AT PALISADES

CONSUMERS POWER COMPANY, MICH.

3 PAGES, LETTER WITH AD REPORT 4/75 TO NRC DIVISION OF REACTOR LICENSING, MARCH 17, 1975, DOCKET 50-255, TYPE--PM, NRC--COND., AE--DECHTEL

CAUSE - INSTALLATION ERROR. A REVIEW OF THE SEISMIC RESTRAINTS HAS DETERMINED THAT NOT ALL THE RESTRAINTS ON THE ENGINEERED SAFEGUARDS SYSTEMS AND CONNECTIONS TO THE PRIMARY COOLANT LOOPS WERE IN CONFORMANCE. ABOUT 135 NEW AND MODIFIED RESTRAINTS WILL BE INSTALLED PRIOR TO FULL POWER OPERATION. THE CAUSE OF THE DEFICIENCY IS BEING STUDIED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

101379 - CONTINUOUS

MODIFICATION • SMALL ASSEMBLY • REVIEW • PALISADES (PHM) • SUPPORT STRUCTURE • FAILURE, INSTALLATION ERROR • ENGINEERED SAFETY FEATURE • SEISMIC DESIGN • REACTOR SHUTDOWN • PIPES AND PIPE FITTINGS

101352

ADDITIONAL INFORMATION ON SEISMIC RESTRAINTS ON PIPING AT PALISADES

CONSUMERS POWER COMPANY, MICHIGAN

2 PAGES, LETTER WITH NO REPORT 6/75 TO NRC DIVISION OF REACTOR LICENSING, MARCH 27, 1975, DOCKET 50-255, TYPE--
PHM, NRC--CUMD, AE--DECHTEL

CAUSE - DESIGN DEFICIENCY. AS REPORTED EARLIER, DEFICIENCIES WERE FOUND IN SEISMIC RESTRAINTS ON PIPING SYSTEM. THE REVIEW IS NOW COMPLETE. IT WAS DETERMINED THAT 132 NEW RESTRAINTS, 14 RESTRAINT REPLACEMENTS, AND 16 RESTRAINT MODIFICATIONS WERE REQUIRED OR ADDED FOR ADDITIONAL COMPENSATION. OF THE 132 TOTAL, 66 WERE ON LINES 2-3 INCHES AND LARGER. INSTALLATION WILL BE COMPLETED PRIOR TO RESTARTING THE REACTOR.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MODIFICATION • SMALL ASSEMBLY • FAILURE, DESIGN ERROR • REVIEW • PALISADES (PHM) • SUPPORT STRUCTURE • SEISMIC DESIGN • PIPES AND PIPE FITTINGS

101405

THREE PROCEDURAL DEFICIENCIES FOUND AT PALISADES

CONSUMERS POWER COMPANY, MICHIGAN

2 PAGES, LETTER WITH NO REPORT 1/75 TO NRC DIVISION OF REACTOR LICENSING, MARCH 31, 1975, DOCKET 50-255, TYPE--
PHM, NRC--CUMD, AE--DECHTEL

CAUSE - IMMEDIATE CORRECTIVE PROCEDURES. DURING MODIFICATIONS TO SYSTEMS ASSOCIATED WITH POSTULATED HIGH-ENERGY LINE BREAKS OUTSIDE CONTAINMENT, 3 PROCEDURAL DEFICIENCIES INVOLVING REVIEW OF DESIGN CHANGES AND DOCUMENTATION WERE DETECTED. THESE ITEMS WERE INDICATIVE OF A PROGRAM DEFICIENCY RATHER THAN A SPECIFIC EQUIPMENT DEFICIENCY. THE PLANT WAS IN THE SHUTDOWN CONDITION. THE CAUSE WAS PRIMARILY DUE TO INADEQUATE DESIGN CHANGE CONTROL PROCEDURES DURING CONSTRUCTION ACTIVITY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PROCEDURES AND MANUALS • MODIFICATION • REVIEW • FAILURE, ADMINISTRATIVE CONTROL • PALISADES (PHM) • QUALITY ASSURANCE • CONSTRUCTION

101756

CONTROL ROD FAILS TO DROP PROPERLY AT PALISADES

CONSUMERS POWER COMPANY, MICHIGAN

2 PAGES, LETTER WITH NO REPORT 7/72 TO NRC DIVISION OF REACTOR LICENSING, APRIL 10, 1975, DOCKET 50-255, TYPE--
PHM, NRC--CUMD, AE--DECHTEL

CAUSE - UNKNOWN. A CONTROL ROD FAILED TO DROP PROPERLY DURING ROD DROP TIMING TESTS WITH THE REACTOR IN HOT SHUTDOWN. SUCCESSIVE TESTING SHOWED MUCH OPERATION COUPLED WITH SLOW OR INCOMPLETE ROD DROPS. THE CAUSE HAS NOT BEEN DETERMINED. THIS ROD WILL NOT BE EXERCISED OR TESTED UNTIL THE CAUSE OF THE MALFUNCTION HAS BEEN DETERMINED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, EQUIPMENT • TEST, CONTROL ROD DRIVE • TEST, SYSTEM OPERABILITY • FAILURE, SCRAM MECHANISM • PALISADES (PHM) • CONTROL RODS • CONTROL ROD DRIVE MECHANISMS

101736

SMALL QUANTITY OF UNSAMPLED LIQUID WASTE RELEASED AT PALISADES

CONSUMERS POWER COMPANY, MICHIGAN

3 PAGES, LETTER WITH NO REPORT 7/75 TO NRC DIVISION OF REACTOR LICENSING, APRIL 11, 1975, DOCKET 50-255, TYPE--
PHM, NRC--CUMD, AE--DECHTEL

CAUSE - SAMPLING ERROR. SHORTLY AFTER AN OPERATOR STARTED THE RELEASE OF THE SOUTH FILTERED WASTE MONITOR TANK, HE NOTICED A 6% DIFFERENCE BETWEEN THE ACTUAL TANK LEVEL AND THE LEVEL INDICATED ON THE GAGE. HE STOPPED THE RELEASE. TWO SEPARATE ANALYSIS WERE INADVERTENTLY RUN FOR THE CONTENTS OF THE TANK. ONE ANALYSIS WAS USED PROPERLY. THE SECOND WAS USED FOR THIS UNSAMPLED BATCH. A NEW SAMPLE WAS TAKEN AND ANALYZED PRIOR TO RELEASING THE REMAINING CONTENTS OF THE TANK. NO RELEASE LIMITS WERE VIOLATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATOR ERROR • WASTE DISPOSAL • WASTE HANDLING • SAMPLING • WASTE DISPOSAL, LIQUID • RADIOACTIVITY RELEASE • PALISADES (PHM)

101730

108740 UNCLASSIFIED

HEATED WATER RELEASE RATE EXCEEDS LIMITS AT PALISADES

CONSUMERS POWER COMPANY, MICHIGAN

2 PAGES, LETTER WITH NO REPORT 75/6 TO NRC DIVISION OF REACTOR LICENSING, APRIL 14, 1975, DOCKET 50-255, TYPE--
PWR, NRC-COMB., AC-DECHTEL

CAUSE - PROCEDURE PROBLEMS. FOR A PERIOD OF ABOUT 33 HOURS, THE PLANT WAS DISCHARGING HEAT AT A RATE OF 1.4 BILLION BTU/H FROM THE BASIN OUTFALL WITH THE REACTOR AT 250 POWER. THE UPPER LIMIT IS 0.5 BILLION BTU/H. THE APPARENT CAUSE APPEARS TO BE ASSOCIATED WITH PLANT PROCEDURE PROBLEMS AND THE BEGINNING OPERATION OF THE NEWLY INSTALLED CLOSED CYCLE COOLING SYSTEM. DILUTION WATER WAS BEING OPERATED THROUGH HALF OF THE MAIN CONDENSER WHICH HAD NOT BEEN PLACED IN SERVICE. THIS METHOD OF COOLING WAS TERMINATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

PROCEDURES AND MANUALS • RELEASE RATE • FAILURE, ADMINISTRATIVE CONTROL • PALISADES (PWR) • WASTE HEAT
MANAGEMENT • CONDENSER COOLING SYSTEM

108737

RELEASE RATE AND TEMPERATURE OF HEATED WATER EXCEEDS LIMITS AT PALISADES

CONSUMERS POWER COMPANY, MICHIGAN

2 PAGES, LETTER WITH NO REPORT 75/7 TO NRC DIVISION OF REACTOR LICENSING, APRIL 16, 1975, DOCKET 50-255, TYPE--
PWR, NRC-COMB., AC-DECHTEL

CAUSE - PROCEDURE PROBLEMS. FOR 3.5 HOURS, THE PLANT WAS DISCHARGING HEAT AT A RATE OF 1.42 BILLION BTU/H AND AT A TEMPERATURE 30 F ABOVE THE LAKE INLET TEMPERATURE. THIS RESULTED FROM ACTION TAKEN TO REDUCE HOT WELL TEMPERATURE TO AVOID THERMAL SHOCKING OF THE CONDENSER TUBES. THE CAUSE APPEARS TO BE ASSOCIATED WITH PLANT PROCEDURE PROBLEMS AND THE BEGINNING OPERATION OF THE NEWLY INSTALLED CLOSED CYCLE COOLING SYSTEM.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

PROCEDURES AND MANUALS • RELEASE RATE • FAILURE, ADMINISTRATIVE CONTROL • PALISADES (PWR) • TEMPERATURE •
WASTE HEAT MANAGEMENT • CONDENSER COOLING SYSTEM

102266

STEAM GENERATOR LEAK AT PALISADES

CONSUMERS POWER COMPANY, MICH.

1 PAGE, LETTER TO NRC DIVISION OF REACTOR LICENSING, APRIL 10, 1975, DOCKET 50-255, TYPE--PWR, NRC-COMB., AC-
DECHTEL

CAUSE - SMALL PRIMARY-TO-SECONDARY LEAK. SINCE ACHIEVING A SIGNIFICANT POWER LEVEL, A LEAKAGE OF 17 GAL/DAY HAS BEEN OBSERVED IN STEAM GENERATOR B. THE RATE REMAINS CONSTANT. THIS IS ABOUT 4% OF THE 0.3 GPM LIMIT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

PALISADES (PWR) • FAILURE, TUBING • STEAM GENERATOR • TUBING • LEAK

102300

IN-CORE READING ON PRIMARY DATA LOGGER FAILS TO UPDATE AT PALISADES

CONSUMERS POWER COMPANY, MICH.

3 PAGES, LETTER WITH AOR 10/75 TO NRC DIVISION OF REACTOR LICENSING, APRIL 23, 1975, DOCKET 50-255, TYPE--PWR,
NRC-COMB., AC-DECHTEL

CAUSE - SOFTWARE DEFICIENCY. WHILE PREPARING AN INCA RUN, IT WAS NOTED THAT THE IN-CORE READINGS HAD NOT UPDATED FOR 4 DAYS. THE PRIMARY DATA LOGGER WAS PUT IN STOP, RESET, AND STARTED. IN-CORES UPDATED PROPERLY THEN. THERE WAS A DEFICIENCY IN THE COMPUTER PROGRAM. IT WAS FOUND AND CORRECTED. THE SEQUENCE ERROR BUZZER TO PRIMARY DATA LOGGER ALARM LIGHT WILL BE WIRED IN AND USED WHENEVER THE PLANT IS AT OR ABOVE 50% POWER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

PALISADES (PWR) • DATA PROCESSING • INSTRUMENT, IN CORE • FAILURE, ADMINISTRATIVE CONTROL • COMPUTER PROGRAM
• MODIFICATION

102316

SET POINT DRIFT IN CONTAINMENT PRESSURE SWITCHES AT PALISADES

CONSUMERS POWER COMPANY, MICH.

3 PAGES, LETTER WITH AOR 75/9 TO NRC DIVISION OF REACTOR LICENSING, APRIL 20, 1975, DOCKET 50-255, TYPE--PWR,
NRC-COMB., AC-DECHTEL

CAUSE - USE OF INCORRECT PROCEDURES. DURING CALIBRATION WHILE THE REACTOR WAS SHUTDOWN FOR REFUELING, 3 OF THE 4 CONTAINMENT HIGH PRESSURE SWITCHES EXCEEDED THE 9 PSIG LIMIT BY 0.2 TO 2.3 PSI. THE SWITCH SETTINGS WERE IMMEDIATELY CORRECTED. WHEN THESE SWITCHES WERE REPLACED DURING

102314 CONTINUED

JULY 1974. AN INCORRECT MAINTENANCE PROCEDURE WAS USED FOR CALIBRATION. THIS WAS THE RESULT OF A HUMAN ERROR. THE INSTRUMENT ERROR HAS BEEN REVISED. ALSO, THIS OCCURRENCE WAS NOT REPORTED ON TIME BECAUSE IT WAS NOT RECOGNIZED AS A REPORTABLE INCIDENT DUE TO THE PRESS OF OTHER ACTIVITIES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PALISADES (PWR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SENSORS, PRESSURE • TEST, SYSTEM OPERABILITY • FAILURE, ADMINISTRATIVE CONTROL • PROCEDURES AND MANUALS • CONTAINMENT • REFUELING • SET POINT

103471

SET POINT DRIFT IN LINEAR POWER CHANNEL AT PALISADES

CONSUMERS POWER CO., JACKSON, MICHIGAN

2 PAGES, LETTER WITH AD REPORT 11-75 TO NRC DIRECTORATE OF LICENSING, JUNE 9, 1975, DCKET 50-255, TYPE--PWR, NRC--COMB., AE--BECHTEL

CAUSE - POWER SUPPLY FAILURE. DURING A TEST WITH THE REACTOR AT 800 POWER, A LINEAR POWER CHANNEL WAS FOUND TO TRIP AT 100.00, WHICH EXCEEDS THE LIMIT BY 0.38. THE INTERNAL +15 V POWER SUPPLY WAS DEFECTIVE. IT WAS REPLACED AND THE SET POINTS ADJUSTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PALISADES (PWR) • INSTRUMENT, POWER RANGE • INSTRUMENT, LINEAR • INSTRUMENT CALIBRATION • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT • ELECTRIC POWER • SET POINT • DRIFT • REACTOR SAFETY SYSTEM

103464

REQUIRED MEASUREMENTS DURING UNPLANNED NOT MADE AT PALISADES

CONSUMERS POWER CO., JACKSON, MICHIGAN

3 PAGES, LETTER WITH AD REPORT 12-75 TO NRC DIRECTORATE OF LICENSING, JUNE 13, 1975, DCKET 50-255, TYPE--PWR, NRC--COMB., AE--BECHTEL

CAUSE - ADMINISTRATIVE OVERSIGHT. A REVIEW OF THE CHLORINATION TREATMENT OF THE CLOSED CYCLE CONDENSER COOLING SYSTEM SHOWED THAT CERTAIN REQUIRED MEASUREMENTS AND OBSERVATIONS HAD NOT BEEN MADE CONSISTENT AND, IN A FEW CASES, NOT AT ALL. RECENTLY, IT HAS BEEN DETERMINED THAT SOME COOLING TOWER WATER IS GOING FROM THE PUMP BASIN INTO THE MAKEUP BASIN AND THEN BEING DISCHARGED OVER THE WEIR INTO THE LAKE. THIS PATH HAD NOT BEEN RECOGNIZED PRIOR TO BEGINNING OPERATION OF THE NEWLY INSTALLED CLOSED CYCLE COOLING SYSTEM. PROCEDURES WILL BE MODIFIED TO PREVENT RECURRENCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PALISADES (PWR) • TEST INTERVAL • CHLORINE • EFFLUENT • CONDENSER COOLING SYSTEM • FAILURE, ADMINISTRATIVE CONTROL • PROCEDURES AND MANUALS • MODIFICATION

103703

RELEASE RATE OF HEATED WATER EXCEEDS LIMITS AT PALISADES

CONSUMERS POWER COMPANY, NICH.

2 PAGES, LETTER WITH AD 75-13 TO NRC DIV. OF REACTOR LICENSING, JUNE 30, 1975, DCKET 50-255, TYPE--PWR, NRC--COMB., AE--BECHTEL

CAUSE - LOWERING COOLING TOWER BASIN LEVEL. FOR ABOUT 16 HOURS, THE TEMPERATURE IN THE PLANT HEATING BASIN INCREASED TO BETWEEN 76 F AND 80 F WHICH EXCEEDS THE 5 F INCREASE LIMIT. INLET WATER TEMPERATURE WAS 65-66 F DURING THIS PERIOD. THE LOWER BASIN LEVEL FOR THE COOLING TOWERS WAS BEING CHANGED DURING THIS PERIOD. THERE PRESENTLY ARE NO EXISTING PROCEDURES WHICH DEFINE THE PROPER METHOD FOR RAISING AND LOWERING TOWER BASIN LEVELS. THE REACTOR WAS OPERATING AT 800 POWER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PALISADES (PWR) • RELEASE RATE • WASTE HEAT • EFFLUENT • COOLING TOWER • CONDENSER COOLING SYSTEM • FAILURE, ADMINISTRATIVE CONTROL

104044

BUS 10 FAILS TO TRANSFER FROM STATION POWER TO START-UP POWER AT PALISADES

CONSUMERS POWER COMPANY, NICH.

3 PAGES, LETTER WITH AD 75-14 TO NRC DIVISION OF REACTOR LICENSING, JULY 8, 1975, DCKET 50-255, TYPE--PWR, NRC--COMB., AE--BECHTEL

CAUSE - INTERLOCK OUT OF ADJUSTMENT. FOLLOWING A REACTOR TRIP, AN ANNUNCIATED ALARM INDICATED BUS 10 WAS NOT ENERGIZED. THE 2400 V START-UP TRANSFORMER WAS AVAILABLE AND DIESEL GENERATOR 1-2 WAS RUNNING. THE OPERATOR MANUALLY CLOSED THE START-UP POWER INCOMING BREAKER WITHIN 30 SECONDS. A DIESEL GENERATOR BREAKER INTERLOCK CONTACT WAS OUT OF ADJUSTMENT. A SURVEY WAS CONDUCTED TO DETERMINE THAT ALL AUXILIARY SWITCH CHANGING ARMS WERE PROPERLY ENGAGED ON ALL ENGINEERED SAFEGUARDS BREAKERS. AUXILIARY SWITCH MOUNTING BRACKETS WERE SHIPPED AS REQUIRED TO ACHIEVE PROPER ENGAGEMENT.

104044 *CONTINUED*
 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

PALISADES (PWR) * ELECTRICAL POWER * ENGINEERED SAFETY FEATURE * FAILURE, EQUIPMENT * OPERATOR * FAILURE,
 MAINTENANCE ERROR * INSTRUMENT, INTERLOCK

104220
 9-INCH DEVIATION ON A CONTROL ROD AT PALISADES
 CONSUMERS POWER COMPANY, RICH.
 2 PGS., LETTER WITH REF 75-4 TO NRC DIVISION OF REACTOR LICENSING, JULY 8, 1975, DOCKET 50-255, TYPE--PWR,
 NRC-COMB., AC--BECHTEL

CAUSE - SHORTEN CAPACITOR MOTOR. WHILE OPERATING AT 20% POWER WITH CONTROL RODS OPERATING IN THE
 AUTOMATIC MODE, A CONTROL ROD WAS FOUND TO BE LOWER THAN THE REST OF THE ROD IN THAT GROUP.
 ATTEMPTS AT RAISING IT RESULTED IN ITS SLIPPING TO A LOWER 9-INCH DEVIATION NOTCH. THE APPARENT
 CAUSE OF FAILURE TO WITHDRAW RESULTED FROM A SHORTED PHASE SHIFTING CAPACITOR IN THE MOTOR DRIVE
 CIRCUIT. THE CAPACITOR WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

PALISADES (PWR) * CONTROL ROD DRIVE MECHANISMS * FAILURE, COMPONENT * INSTRUMENTS, MISC. * REACTOR CONTROL

104725
 LPSI PUMP FOUND NOT ALIGNED FOR NORMAL SERVICE AT PALISADES
 CONSUMERS POWER COMPANY, JACKSON, RICH.
 2 PGS., LTR W/AMR 75-15 TO NRC DIV. OF REACTOR LICENSING, JULY 21, 1975, DOCKET 50-255, TYPE--PWR, NRC--
 COMB., AC--BECHTEL

CAUSE - OPERATOR ERROR. WHILE ATTEMPTING TO OPERATE A LOW PRESSURE SAFETY INJECTION PUMP FOR
 TESTING WITH THE REACTOR AT 80% POWER, THE OPERATOR NOTICED NO RECIRCULATION FLOW AND NO
 DISCHARGE PRESSURE. TWO VALVES WERE FOUND IN THE IMPROPER POSITION SO THAT THERE WAS NO SUCTION
 TO THE PUMP. THE STARTUP MASTER CHECK SHEET INDICATED THAT THE APPROPRIATE CHECKLIST HAD BEEN
 COMPLETED. HOWEVER, THE CHECKLIST WAS NOT FOUND. THE SHIFT SUPERVISOR TOOK THE OPERATOR'S WORD
 THAT IT HAD BEEN COMPLETED AND SIGNED OFF THE CHECK SHEET. THE PROBLEM IS ADDED IN INSUFFICIENT
 DISCIPLINE WITHIN THE OPERATING GROUP.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

PALISADES (PWR) * PUMPS * SAFETY INJECTION * FAILURE, OPERATOR ERROR * PROCEDURES AND MANUALS * TEST, SYSTEM
 OPERABILITY

104604
 CONTROL ROD FOUND INOPERABLE AT PALISADES
 CONSUMERS POWER COMPANY, RICH.
 2 PGS., LETTER WITH REF 75-5 TO NRC DIV. OF REACTOR LICENSING, JULY 23, 1975, DOCKET 50-255, TYPE--PWR, NRC--
 COMB., AC--BECHTEL

CAUSE - UNKNOWN. WHILE OPERATING AT 80% POWER, CONTROL ROD EXERCISING REVEALED THAT A CONTROL ROD
 WOULD NOT INSERT. THE INVESTIGATION TO DATE HAS NOT FOUND THE CAUSE. IT IS CONTINUING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

PALISADES (PWR) * CONTROL ROD DRIVE MECHANISMS * TEST, SYSTEM OPERABILITY * FAILURE, EQUIPMENT * REACTOR
 CONTROL

104033
 RADWASTE BATCH DISCHARGE RATE EXCEEDED AT PALISADES
 CONSUMERS POWER COMPANY, JACKSON, RICH.
 2 PGS., LTR W/AMR 75-16 TO NRC DIVISION OF REACTOR LICENSING, AUG. 4, 1975, DOCKET 50-255, TYPE--PWR, NRC--
 COMB., AC--BECHTEL

CAUSE - FLOW CONTROLLER REFERENCE LEG LOST. RADWASTE BATCH WAS AUTHORIZED FOR DISCHARGE AT LESS
 THAN 70 GPM. CALCULATED RATE WAS 84.7 GPM. THE OPERATOR SET THE FLOW CONTROLLER AT 40 GPM FOR
 THE 5000 GALLON RELEASE. AFTER 45 MINUTES, HE CHECKED AND NOTED THE TANK LOST SUCTION WHILE HE
 WAS CHECKING. THE RELEASE WAS AT 1.19 MPC. NO DETECTABLE ACTIVITY WAS FOUND AT THE RELEASE
 POINTS. THE CAUSE WAS LOSS OF THE FLOW CONTROLLER REFERENCE LEG. THIS IS A GENERIC PROBLEM
 BECAUSE THE SYSTEM PRESSURE IS SLIGHTLY NEGATIVE DUE TO A LARGE DROP.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

PALISADES (PWR) * RELEASE RATE * WASTE DISPOSAL, LIQUID * WASTE DISPOSAL * FAILURE, INSTRUMENT * SENSORS,
 FLOW * CONTROL * FAILURE, DESIGN ERROR

100900
 FOG CONTROL RODS FAIL AT PALISADES
 CONSUMERS POWER CO., JACKSON, MICH.
 3 PAGES, LETTER WITH NO REPORTS 75-7 AND -8 TO NRC DIVISION OF REACTOR LICENSING, AUG. 7, 1975, DOCKET 50-255, TYPE--PWR, NRC--COMB.. AE--BECHTEL

CAUSE - BRAKE PROBLEMS. CONTROL ROD EXERCISING REVEALED THAT ONE CROM WOULD NOT RESPOND TO EITHER AN INSERT OR A WITHDRAWAL SIGNAL. DURING A DECREASE IN POWER, ANOTHER CROM WOULD NOT INSERT. IT WOULD WITHDRAW. BOTH RODS COULD BE TRIPPED. DURING INSPECTION, PARTICLES FROM THE BRAKE LININGS WERE FOUND TO BE BETWEEN THE BRAKE COIL AND THE STATIONARY SHAFT. AFTER THE BRAKE COMPONENTS WERE CLEANED AND REASSEMBLED, THE CROM OPERATED SATISFACTORILY. ALL BRAKE ASSEMBLIES WILL BE INSPECTED DURING THE NEXT OPPORTUNITY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PALISADES (PWR) + CONTROL ROD DRIVE MECHANISMS + FAILURE, EQUIPMENT + CROM + TEST, SYSTEM OPERABILITY + REACTOR CONTROL + FAILURE, MAINTENANCE ERROR

100991
 UNPLANNED GASEOUS WASTE RELEASE AT PALISADES
 CONSUMERS POWER COMPANY, JACKSON, MICH.
 2 PGS, LTR W/AM 75-17 TO NRC DIV. OF REACTOR LICENSING, AUG. 12, 1975, DOCKET 50-255, TYPE--PWR, NRC--COMB.. AE--BECHTEL

CAUSE - UNKNOWN. ON 3 OCCASIONS THE PRESSURE IN THE WASTE GAS DECAY TANK HAS DECREASED OVER A PERIOD OF TIME BY 2 TO 5 PSI. NO WASTE GAS SYSTEM OPERATIONS WERE BEING CONDUCTED WHICH COULD BE ASSOCIATED WITH THE LOSS IN PRESSURE. A SMALL VALVE LEAK IS CONSIDERED TO BE THE MOST PROBABLE CAUSE. SPECIAL MONITORING OF THIS TANK WILL BE PROVIDED DURING ITS NEXT USED PERIOD.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PALISADES (PWR) + AIRBORNE RELEASE + WASTE STORAGE + STORAGE CONTAINER + WASTE TREATMENT, GAS + LEAK

105051
 DIESEL GENERATOR CYLINDER AND EXHAUST TEMPERATURES HIGH AT PALISADES
 CONSUMERS POWER CO., JACKSON, MICH.
 2 PAGES, LETTER WITH NO REPORT 75-9 TO NRC DIVISION OF REACTOR LICENSING, AUG. 14, 1975, DOCKET 50-255, TYPE--PWR, NRC--COMB.. AE--BECHTEL

CAUSE - EXHAUST MANIFOLD BELLONS FAILURE. DURING TESTING OF A DIESEL GENERATOR WITH THE REACTOR AT ONE POWER, CYLINDER TEMPERATURES REACHED 1100 F AFTER 20 MINUTES OF OPERATION AT FULL LOAD. TYPICAL TEMPERATURES ARE 950 TO 1000 F. INSPECTION FOUND THAT A BELLONS SUPPORT BRACKET HAD FAILED RESULTING IN AN EXHAUST MANIFOLD FAILURE. THIS DECREASED EXHAUST FLOW TO THE TURBOSUPERCHARGER AND INCREASED CYLINDER TEMPERATURES 100 F. THE BELLONS SUPPORT BRACKET WAS REPAIRED AND A NEW EXHAUST MANIFOLD BELLONS INSTALLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PALISADES (PWR) + TEMPERATURE + GENERATOR, DIESEL + ENGINES, INTERNAL COMBUSTION + TEST, SYSTEM OPERABILITY + FAILURE, EQUIPMENT + SUPPORT STRUCTURE + EMERGENCY POWER, ELECTRIC

105182
 HIGH PRESSURE SAFETY INJECTION VALVE FAILS TO OPEN AT PALISADES
 CONSUMERS POWER COMPANY, JACKSON, MICH.
 2 PGS, LTR W/AM 75-8 TO NRC DIV. OF REACTOR LICENSING, AUG. 22, 1975, DOCKET 50-255, TYPE--PWR, NRC--COMB.. AE--BECHTEL

CAUSE - SWITCH FAILURE. WITH THE PLANT AT ONE POWER THE SAFETY INJECTION SYSTEM WITH STANDBY-POWER TEST WAS CONDUCTED SATISFACTORILY. THEN, THE WITHOUT-STANDBY-POWER TEST WAS CONDUCTED. DURING THIS, A HIGH-PRESSURE VALVE DID NOT OPEN. THE CLOSED CONTACTS OF THE SWITCH WERE FOUND TO BE STUCK SHUT. THE SWITCH WAS REPAIRED AND RETURNED TO SERVICE. A REPLACEMENT SWITCH HAS BEEN ORDERED AND WILL BE INSTALLED AS SOON AS PRACTICAL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PALISADES (PWR) + VALVES + SAFETY INJECTION + TEST, SYSTEM OPERABILITY + FAILURE, EQUIPMENT + INSTRUMENT, SWITCH

105541
 CONTROL ROD DROPPED INTO THE CORE AT PALISADES
 CONSUMERS POWER COMPANY, JACKSON, MICH.
 3 PGS, LTR W/AM 75-18 TO NRC DIV. OF REACTOR LICENSING, AUG. 28, 1975, DOCKET 50-255, TYPE--PWR, NRC--COMB.. AE--BECHTEL

105541 *CONTINUED*

CAUSE - SHORTED CLUTCH COIL. WHILE THE UNIT WAS OPERATING AT 60% POWER, CONTROL ROD NO. 19 DROPPED INTO THE CORE. AN ATTEMPT TO RETRIEVE THE ROD FAILED. THE PLANT WAS SHUT DOWN DUE TO ADDITIONAL PROBLEMS ASSOCIATED WITH ANOTHER CDM. THE CLUTCH WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PALISADES (PWR) * CONTROL ROD DRIVE MECHANISMS * FAILURE, EQUIPMENT * FAILURE, COMPONENT * REACTOR CONTROL * REACTOR SHUTDOWN

106337

CONTROL ROD DROPPED INTO THE CORE AT PALISADES

CONSUMERS POWER CO., NICH.

3 PGS. LTR W/AD 75-19 TO NRC DIVISION OF REACTOR LICENSING, SEPT. 9, 1975. DOCKET 50-255, TYPE--PWR, NRC--COMB.. AE--BECHTEL

CAUSE - SHORTED CLUTCH COIL. WHILE OPERATING AT 60% POWER, CONTROL ROD NO. 11 DROPPED INTO THE CORE. POWER WAS REDUCED TO 60%. THE APPARENT CAUSE WAS A SHORTED CLUTCH COIL. THE CLUTCH WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PALISADES (PWR) * FAILURE, COMPONENT * ACCIDENT, CONTROL ROD DROPPEN * CONTROL RODS * CONTROL ROD DRIVE MECHANISMS

106336

CONTROL ROD DROPPED INTO THE CORE AT PALISADES

CONSUMERS POWER CO., NICH.

3 PGS. LTR WITH ADR 75-20 TO NRC DIVISION OF REACTOR LICENSING, SEPT. 15, 1975. DOCKET 50-255, TYPE--PWR, NRC--COMB.. AE--BECHTEL

CAUSE - SHORTED CLUTCH COIL. WHILE OPERATING AT 60% POWER, CONTROL ROD NO. 19 DROPPED INTO THE CORE. REACTOR POWER WAS REDUCED TO 60%. THE APPARENT CAUSE WAS A SHORTED CLUTCH COIL. THE CLUTCH WAS REPAIRED. A GENERIC PROBLEM MAY EXIST WITH THE CDM CLUTCHES. THIS IS THE THIRD RECENT FAILURE. PRELIMINARY INFORMATION INDICATES THAT A HIGH CLUTCH COIL TEMPERATURE MAY BE ASSOCIATED WITH THESE FAILURES. COIL VOLTAGE HAS BEEN LOWERED TO REDUCE POWER DISSIPATION WITHIN THE CLUTCH COILS BY 25%.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PALISADES (PWR) * CONTROL ROD DRIVE MECHANISMS * ACCIDENT, CONTROL ROD DROPPEN * FAILURE, COMPONENT * CONTROL RODS

106448

HIGH-PRESSURE SAFETY INJECTION VALVE FAILS TO OPEN AT PALISADES

CONSUMERS POWER CO., NICH.

3 PGS. LTR W/AD 21-75 TO NRC DIVISION OF REACTOR LICENSING, SEPT. 22, 1975. DOCKET 50-255, TYPE--PWR, NRC--COMB.. AE--BECHTEL

CAUSE - VALVE STEM-TO-DISC SEPARATION. WHILE OPERATING AT 40% POWER, HIGH-PRESSURE SAFETY INJECTION PUMP A WAS BEING USED TO REFILL THE SAFETY INJECTION BOTTLE AFTER SAMPLING. A VALVE, ALTHOUGH INDICATING OPEN, WOULD NOT PASS BORATED WATER. THE APPARENT CAUSE WAS A VALVE STEM TO VALVE DISC SEPARATION. THE REDUNDANT SYSTEM WAS PLACED IN SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PALISADES (PWR) * VALVES * SAFETY INJECTION * FAILURE, EQUIPMENT

106449

BORON CONCENTRATION IN SAFETY INJECTION TANKS LESS THAN LIMIT AT PALISADES

CONSUMERS POWER CO., NICH.

3 PGS. LTR W/AD 22-75 TO NRC DIVISION OF REACTOR LICENSING, SEPT. 27, 1975. DOCKET 50-255, TYPE--PWR, NRC--COMB.. AE--BECHTEL

CAUSE - POOR MIXING OF THE SIW TANK. ANALYSIS OF THE SAFETY INJECTION TANK WHILE OPERATING AT 40% POWER SHOWED A LOW BORON CONCENTRATION (169 PPM). THE LOW CONCENTRATION IS BELIEVED TO BE DUE TO THE TANKS BEING TOPPED OFF FROM THE SIW TANK WITHOUT PROPER MIXING OF THE SIW TANK. THE BORON CONCENTRATION IN THE SIW TANK WAS INCREASED TO 1763 PPM. THE SAFETY INJECTION TANKS WERE DRAINED ONE AT A TIME AND REFILLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PALISADES (PWR) * CONCENTRATION * STORAGE CONTAINER * CHEMICAL SWM * SAFETY INJECTION * FAILURE, OPERATION ERROR * BORON

100450
RELEASE RATES OF LIQUID WASTEWATER EXCEED LIMITS AT PALISADES
CONSUMERS POWER CO., JACKSON, MICH.
5 PGS, LTR W/AD-23-75 TO NRC DIVISION OF REACTOR LICENSING, SEPT. 22, 1975, DOCKET 50-255, TYPE--PWR, NRC--
COMB., AE--BECHTEL

CAUSE - INJUNCT CALCULATIONS. A REVIEW OF THE LIQUID WASTEWATER RELEASE FOR THE PAST 2 WEEKS
SHOWED THAT 10 RELEASE RATES WERE INCORRECTLY CALCULATED. TWO EXCEEDED LIMITS, ONE BY 34% AND
THE OTHER BY 62%. A NEW TECHNICIAN WAS CALCULATING THE RATES. HE FAILED TO CONVERT RELEASE
RATE FROM LITERS/MIN TO GAL/MIN. THE SUPERVISOR WHO REVIEWED AND AUTHORIZED THE RELEASES FAILED
TO CATCH THE ERROR.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

PALISADES (PWR) • RELEASE RATE • WASTE DISPOSAL, LIQUID • WASTE DISPOSAL • MATHEMATICAL TREATMENT • FAILURE,
ADMINISTRATIVE CONTROL

100471
FINAL REPORT ON CONTROL ROD FAILURE AT PALISADES
CONSUMERS POWER CO., JACKSON, MICH.
1 PG, LTR TO NRC DIRECTOR OF NUCLEAR REACTOR REGULATION, OCT. 9, 1975, DOCKET 50-255, TYPE--PWR, NRC--COMB.,
AE--BECHTEL

CAUSE - LOOSE SET SCREW. FAILURE OF CONTROL ROD 27 TO INSERT WAS REPORTED ON JULY 23, 1975. SINCE
THEN THE BRAKE WAS DISASSEMBLED. THE ROTATING ELEMENT OF THE BRAKE ASSEMBLY WAS LOOSE. ONE OF
THE SET SCREWS HAD BACKED OUT CAUSING THE ELEMENT TO LOOSEN AND CHANGE THE AIR GAP BETWEEN THE
STATORARY DISK AND THE ROTATING DISK. ALL 45 CROM BRAKE ASSEMBLIES WILL BE INSPECTED DURING THE
NEXT EXTENDED PLANT OUTAGE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

PALISADES (PWR) • CONTROL ROD DRIVE MECHANISMS • FASTENER • FAILURE, MAINTENANCE ERROR

107225
PRELIMINARY INFORMATION OF AXIAL GROWTH OF PUISON RODS AT PALISADES
CONSUMERS POWER CO., JACKSON, MICH.
2 PGS, LTR W/AD-75-10 TO NRC DIRECTOR OF NUCLEAR REACTOR REGULATION, OCT. 14, 1975, DOCKET 50-255, TYPE--PWR,
NRC--COMB., AE--BECHTEL

CAUSE - RADIATION-INDUCED GROWTH. PRELIMINARY INFORMATION FROM THE FUEL SUPPLIES INDICATES THAT
THE AXIAL GROWTH OF PUISON RODS IN THE A & B TYPE FUEL MAY HAVE REACHED THE ALLOWED LIMIT. THE
MOST PROBABLE CAUSE IS RELATED TO RADIATION-INDUCED GROWTH. INTERIM MEASURES TAKEN INCLUDE
LIMITING POWER LEVEL TO 80% AND MONITORING THE PRIMARY COOLANT GROSS GAMMA RADIOACTIVITY.
CONTINUED GROWTH WOULD RESULT IN BORING. THIS COULD AFFECT HEAT TRANSFER IN ADJACENT FUEL RODS.
ONLY 1 OF 20 PUISON RODS HAVE OBSERVABLE GROWTH.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

PALISADES (PWR) • PUISON, BURNABLE • FUEL ELEMENTS • DEFORMATION • RADIATION EFFECT • SURVEILLANCE PROGRAM •
FUEL INTEGRITY • POWER DERATING

107511
TEMPERATURE OF BLOWDOWN FROM CLOSED-CYCLE COOLING EXCEEDS LIMIT AT PALISADES
CONSUMERS POWER CO., JACKSON, MICH.
3 PGS, LTR W/AD-75-24 TO NRC DIRECTOR OF NUCLEAR REACTOR REGULATION, OCT. 24, 1975, DOCKET 50-255, TYPE--PWR,
NRC--COMB., AE--BECHTEL

CAUSE - DILUTION PUMPS SHUT OFF. DURING INSTALLATION OF NEW THERMAL DISCHARGE MONITORING
EQUIPMENT, THE DILUTION PUMPS WERE SHUT OFF TO REDUCE TURBULENCE IN THE DISCHARGE MIXING BASIN
WHILE DIVERS INSTALLED TEMPERATURE SENSING PROBES. THE PLANT WAS AT 80% POWER. HEATED WATER
FLOWED INTO THE MIXING BASIN FROM THE MAKEUP BASIN AND FROM THE CLOSED-CYCLE COOLING SYSTEM
BLOWDOWN. TEMPERATURE RISE IN THE MIXING BASIN WAS GREATER THAN EXPECTED. IT PEAKED AT 14 F FOR
90 MINUTES. SINCE SOME DISCHARGE CAME FROM THE CLOSED-CYCLE SYSTEM, TEMPERATURE LIMITS WERE
EXCEEDED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

PALISADES (PWR) • TEMPERATURE • EFFLUENT • MAINTENANCE AND REPAIR • RIVER • HEAT SINK • THERMAL POLLUTION •
CONDENSER COOLING SYSTEM

107762
ERROR FOUND IN COMPUTER PROGRAM USED FOR ALARM LIMITS AT PALISADES
CONSUMERS POWER CO., JACKSON, MICH.
3 PGS, LTR W/AD-75-25 TO NRC DIRECTOR OF NUCLEAR REACTOR REGULATION, NOV. 5, 1975, DOCKET 50-255, TYPE--PWR,

107762 CONTINUED
MFG-COMB., AE-BECHTEL

CAUSE - IMPROPER BURNUP CURVES. INTERIM SPECIAL TECH SPECS REQUIRES THAT EN-CORE ALARMS BE SET TO LIMIT SPEND TO LOCAL POWER LIMITS USED IN RCCS ANALYSIS. WHILE CHECKING DATA, IT WAS NOTICED THAT THE BURNUP CORRECTION CURVE FOR THE FLUX-TO-POWER FACTORS FOR A PARTICULAR FUEL TYPE HAD A SHAPE CONTRARY TO THE EXPECTED. INVESTIGATION FOUND THAT BURNUP CORRECTION FACTOR CURVES FOR 2 SETS OF 2 FUEL TYPES EACH HAD BEEN INADVERTENTLY INTERCHANGED. THE ERROR OCCURRED JUNE 19, 1975. ERRORS WERE IN THE CONSERVATIVE DIRECTION. THE MAXIMUM ERROR DURING THIS TIME WAS 6.5% IN THE CONSERVATIVE DIRECTION. PROPER CURVES WERE PUT IN THE COMPUTER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PALISADES (PWR) • PSAT POINT • FLUX DISTRIBUTION • COMPUTER PROGRAM • MATHEMATICAL TREATMENT • FUEL BURNUP • FAILURE, ADMINISTRATIVE CONTROL • PARAMETERIZATION

107812
LEAK RATE OF CONTAINMENT PURGE VALVES EXCESSIVE AT PALISADES
CONSUMERS POWER CO., JACKSON, MISS.

3 PGS, LTR W/ATTACH TO NRC DIRECTOR OF NUCLEAR REACTOR REGULATION, NOV. 21, 1975, DCKET 50-255, TYPE--PWR, MFG-COMB., AE-BECHTEL

CAUSE - IMPROPER ALIGNMENT ON SEAT. DURING TESTING OF THE PURGE AIR EXHAUST VALVES, THE MINIMUM TEST PRESSURE (55 PSIG) COULD NOT BE MAINTAINED USING THE NORMAL METHOD. PRESSURE DROPPED RAPIDLY TO 46 PSIG WHERE IT STABILIZED AND INDICATED VERY LITTLE ADDITIONAL LEAKAGE. NO LEAKAGE WAS IDENTIFIED ON THE 2 DOWNSTREAM VALVES. APPARENTLY, THE UPSTREAM VALVE IS NOT GETTING ALIGNED PROPERLY ON THE SEAT AND WHEN PRESSURE EXCEEDS 46 PSIG, THE INFLATABLE SEAT BECOMES DEFORMED. ALL 3 VALVES HAVE BEEN TIGHTENED. REPAIRS WILL BE MADE DURING THE NEXT SCHEDULED SHUTDOWN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PALISADES (PWR) • LEAK RATE • VALVES • CONTAINMENT PURGE • TEST, SYSTEM OPERABILITY • TEST, LEAK RATE • CONTAINMENT INTEGRITY • FAILURE, MAINTENANCE ERROR

108200
THERMAL DISCHARGE EXCEEDS LIMIT AT PALISADES
CONSUMERS POWER CO., JACKSON, MISS.

3 PGS, LTR W/ATTACH TO NRC OFFICE OF I & E, REGION III, NOV. 21, 1975, DCKET 50-255, TYPE--PWR, MFG-COMB., AE-BECHTEL

CAUSE - NOT STATED. THE TEMPERATURE DIFFERENTIAL BETWEEN THE INTAKE AND DISCHARGE EXCEEDED 5 F FOR ABOUT 1 HOUR. THE MAXIMUM DIFFERENTIAL WAS 6.3 F. ANALYSIS SHOWED THAT AFTER SUBTRACTING THE EFFECT OF THE SERVICE WATER THAT THE ACTUAL DISCHARGE TEMPERATURE WAS LESS THAN 5 F LIMIT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PALISADES (PWR) • TEMPERATURE GRADIENT • CONDENSED COILING SYSTEM • EFFLUENT

109100
LPSI PUMP SEAL LEAKS AT PALISADES
CONSUMERS POWER CO., JACKSON, MISS.
2 PGS, LTR W/ATTACH TO NRC OFFICE OF I & E, REGION III, DEC. 22, 1975, DCKET 50-255, TYPE--PWR, MFG-COMB., AE-BECHTEL

CAUSE - IMPROPER O-RING CLEARANCE. DURING A TEST WITH THE REACTOR AT 70% POWER, LPSI PUMP SEAL LEAKAGE WAS OBSERVED. THE PUMP WAS REMOVED FROM SERVICE. SEAL LEAKAGE APPEARS TO BE CAUSED BY IMPROPER O-RING CLEARANCE. THE SEAL WAS REPLACED WITH A SIMILAR ONE. THE STAFF WILL INVESTIGATE IMPROVED SEAL DESIGN AND METHODS FOR REDUCING REPAIR TIME.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PALISADES (PWR) • SEAL • PUMPS • SAFETY INJECTION • PLEAK • TEST, SYSTEM OPERABILITY • FAILURE, EQUIPMENT • FAILURE, DESIGN ERROR

109107
PRIMARY COOLANT SYSTEM LEAKAGE EXCEEDS LIMIT AT PALISADES
CONSUMERS POWER CO., JACKSON, MISS.
2 PGS, LTR W/ATTACH TO NRC OFFICE OF I & E, REGION III, DEC. 22, 1975, DCKET 50-255, TYPE--PWR, MFG-COMB., AE-BECHTEL

CAUSE - VALVE LEAKAGE. WHILE OPERATING AT 70% POWER, PRIMARY COOLANT SYSTEM LEAKAGE WAS OBSERVED TO BE SLIGHTLY GREATER THAN 1 GPM (UNIDENTIFIED) FOR 2 HOURS. LEAKAGE WAS SUBSEQUENTLY IDENTIFIED AS A SAMPLE ISOLATION VALVE. THE VALVE HAS BEEN TEMPORARILY CAPPED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

100107 PLANTINTEL
CHARGE 02-001

FAILURE (PHR) • LEAK • MAIN COOLING SYSTEM • VALVES • SAMPLING • CONTAINMENT ISOLATION • FAILURE, EQUIPMENT

090617
CONTAINMENT PURGE VALVE CLOSING TIMES EXCEED LIMIT AT POINT BEACH 1
WISCONSIN ELECTRIC POWER COMPANY
2 PAGES, LETTER TO DIRECTORATE OF LICENSING, FEBRUARY 4, 1975, DOCKET 50-266, TYPE--PHR, MFG--WEST., AE--BECHTEL

CAUSE - STICKING PNEUMATIC RELAYS. DURING A SHUTDOWN, A TEST OF THE CONTAINMENT PURGE INLET AND EXHAUST VALVES CLOSING TIMES FOUND 2 VALVES HAD CLOSING TIMES THAT EXCEEDED THE 3 SECOND LIMIT. THE CAUSE WAS STICKING PNEUMATIC RELAYS IN THE VALVE AIR OPERATORS. AFTER THE RELAYS WERE CLEANED AND LUBRICATED, THE VALVES WERE RETESTED WITH SATISFACTORY CLOSING TIMES. DURING NORMAL OPERATION, THESE VALVES ARE CLOSED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE 02-001

CONTAINMENT ISOLATION • CONTAINMENT AIR COOLING • RESPONSE TIME • TEST, SYSTEM OPERABILITY • FAILURE, MAINTENANCE ERROR • POINT BEACH 1 (PHR) • VALVES

100076
REDUNDANT TRIP MECHANISM ON MSIV OPERATOR FAILS TO UNLATCH AT POINT BEACH 1
WISCONSIN ELECTRIC POWER COMPANY
3 PAGES, LETTER TO NRC DIRECTORATE OF LICENSING, FEBRUARY 10, 1975, DOCKET 50-266, TYPE--PHR, MFG--WEST., AE--BECHTEL

CAUSE - EXCESS FRICTION. DURING TESTING OF THE MAIN STEAM ISOLATION AND CHECK VALVES, THE MECHANICAL LATCHING MECHANISM ON A REDUNDANT SOLENOID TRIP VENT VALVE FAILED TO UNLATCH WHEN THE SOLENOID WAS DEENERGIZED. THE LATCHING MECHANISM WAS RESTRAINED BY FRICTION. FOLLOWING A PRIOR FAILURE OF THIS TYPE, A ROLLER HAD BEEN INSTALLED TO REDUCE FRICTION. IN UNIT 1 MECHANISMS, THE THREADS HAD NOT BEEN REMOVED FROM THE CENTER PIN OF THE ROLLER AS CALLED FOR. WHEN THE THREADS WERE REMOVED, THE ROLLER TURNED FREELY AND THE MECHANISM TRIPPED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE 02-001

FAILURE, COMPONENT • CONTAINMENT ISOLATION • STEAM • TEST, SYSTEM OPERABILITY • FAILURE, MAINTENANCE ERROR • POINT BEACH 1 (PHR) • MAIN COOLING SYSTEM • VALVE, CHECK

100257
STEAM GENERATOR TUBE FAILS AT POINT BEACH 1
U.S. ATOMIC ENERGY COMMISSION, WASHINGTON
2 PAGES, OFFICE OF INSPECTION AND ENFORCEMENT INCIDENT NOTIFICATION NO. 144, FEBRUARY 28, 1975, DOCKET 50-266, TYPE--PHR, MFG--WEST., AE--BECHTEL

CAUSE - UNKNOWN. A STEAM GENERATOR TUBE(S) FAILURE OCCURRED IN STEAM GENERATOR B. THE FAILURE WAS PROGRESSIVE OVER A 40-MIN INTERVAL. THE FIRST INDICATION WAS A SPIKE ON THE AIR EJECTOR MONITOR AND THEN IN THE SHUTDOWN MONITOR. THE REACTOR WAS SHUTDOWN FOR REPAIR. LEVEL CONTROL WAS MAINTAINED BY THE NORMAL CHARGING SYSTEM. PRELIMINARY DATA INDICATE THAT GASEOUS AND LIQUID RELEASES DID NOT EXCEED LIMITS. ALL CONTAMINATED WATER IS BEING CONTAINED UNTIL IT IS PROCESSED BY THE WASTEWATER EVAPORATOR.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE 02-001

POINT BEACH 1 (PHR) • FAILURE, TUBING • STEAM GENERATOR • TUBING • REACTOR SHUTDOWN

100507
STEAM GENERATOR TUBE FAILS AT POINT BEACH 1
WISCONSIN ELECTRIC POWER CO.
20 PAGES, LETTER WITH ATTACHMENTS TO NRC DIRECTORATE OF LICENSING, MARCH 8, 1975, DOCKET 50-266, TYPE--PHR, MFG--WEST., AE--BECHTEL

CAUSE - UNKNOWN. A STEAM GENERATOR B TUBE FAILURE WENT FROM AN INITIAL POINT LEAK TO A MAXIMUM OF 125 GPM IN ABOUT 30 MINUTES. AUTOMATIC AND MANUAL CHARGING PUMP ACTION MAINTAINED THE REACTOR PRESSURE AND NORMAL MAIN COOLANT INVENTORY. AUTOMATIC SAFETY INJECTION WAS NOT INITIATED SINCE NORMAL CONDITIONS WERE MAINTAINED. SOME RADIOACTIVITY, MAINLY XENON, TRANSFERRED INTO THE SECONDARY PLANT. THE PRIMARY SYSTEM WAS BROUGHT TO COLD SHUTDOWN CONDITION IN 4 HOURS. ALL EQUIPMENT PERFORMED WITHOUT MALFUNCTIONING. THERE WERE NO OPERATOR ERRORS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE 02-001

INCIDENT • RADIOACTIVITY RELEASE • POINT BEACH 1 (PHR) • FAILURE, TUBING • STEAM GENERATOR • TUBING • LEAK •

100587 CONTINUOUS
OPERATION ACTION + REACTOR SHUTDOWN

101167
LOW LEVEL RADIOACTIVE LIQUID RELEASE AT POINT BEACH 1
WISCONSIN ELECTRIC POWER COMPANY
3 PAGES, LETTER TO THE OFFICE OF NUCLEAR REACTOR REGULATION, MARCH 10, 1975, DOCKET 50-266, TYPE--PWR, NRC--
WEST., AE--BECHTEL

CAUSE - MAIN FEED PUMP SEAL LEAK. WITH THE UNIT IN COLD SHUTDOWN FOLLOWING A STEAM GENERATOR TUBE FAILURE, A SUPERVISOR OBSERVED A SMALL FLOW OF WATER INTO THE TURBINE HALL FLOOR DRAIN. THE STEAM GENERATOR MAIN FEED PUMP SEALS WERE LEAKING AT A RATE OF 0.3 GPM. LEAKAGE WAS STOPPED WHEN THE MAIN FEED REGULATING VALVE BYPASS VALVE AND MAIN FEED PUMP CASING WARM-UP LINES WERE ISOLATED. NO RELEASE LIMITS WERE VIOLATED. A MINOR BACKLEAKAGE HAD DEVELOPED THROUGH THE 16-INCH MAIN FEED CHECK VALVES WHEN THE PRESSURE DROPPED TO ATMOSPHERIC. NO LEAKAGE OCCURS AT OPERATING PRESSURE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MAINTENANCE AND REPAIR + BUILDING + RADIOACTIVITY RELEASE + SEAL + POINT BEACH 1 (PWR) + STEAM GENERATOR + LEAK + FEEDWATER + PUMPS

101774
MAIN STEAM LINE FLOW CHANNEL FAILS AT POINT BEACH 1
WISCONSIN ELECTRIC POWER COMPANY
2 PAGES, LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, APRIL 15, 1975, DOCKET 50-266, TYPE--PWR, NRC--
WEST., AE--BECHTEL

CAUSE - FAULTY DIFFERENTIAL PRESSURE CELL. WHEN NEARING THE COMPLETION OF A SLOW POWER ESCALATION FOLLOWING AN OUTAGE, AN OPERATOR NOTED A DISCREPANCY BETWEEN 2 CHANNELS OF STEAM FLOW INDICATION ON A LINE. THE CAUSE WAS A FAULTY DIFFERENTIAL PRESSURE CELL IN ONE FLOW TRANSMITTER. A SPARE TRANSMITTER WAS INSTALLED IN PLACE OF THE FAULTY UNIT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + REACTOR SAFETY SYSTEM + STEAM + FAILURE, INSTRUMENT + INSTRUMENT, SWITCH + POINT BEACH 1 (PWR) + SENSORS, FLOW

101909
CONTRACTOR EMPLOYEE RECEIVES OVEREXPOSURE AT POINT BEACH 1
WISCONSIN ELECTRIC POWER CO., MILWAUKEE, WISCONSIN
2 PGS, RPT TO U.S. NRC, APRIL 10, 1975, DOCKET 50-266, TYPE--PWR, NRC--WEST., AE--BECHTEL

CAUSE - DISCREPANCIES IN MONITORING DEVICES. TLD RESULTS FOR A CONTRACTOR EMPLOYEE INDICATED A QUARTERLY EXPOSURE OF 3.1 REM. SELF-READING POCKET DOSIMETRY READING TOTALLED 2.46 REM, WHICH IS WELL WITHIN THE ALLOWED 15% MARGIN IN READINGS. THE REASON FOR THE DISCREPANCIES IN MONITORING DEVICES REMAINS UNANSWERED. THE EMPLOYEE IS THE SENIOR CONTRACTOR SUPERVISOR WHO IS IN CHARGE OF THE STEAM GENERATOR WORK.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

POINT BEACH 1 (PWR) + MAINTENANCE AND REPAIR + STEAM GENERATOR + DOSE MEASUREMENT, EXTERNAL + DOSIMETRY + PERSONNEL EXPOSURE, RADIATION

102319
LOW LEVEL RADIOACTIVE LIQUID RELEASE AT POINT BEACH 1
WISCONSIN ELECTRIC POWER CO.
1 PAGE, LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, APRIL 29, 1975, DOCKET 50-266, TYPE--PWR, NRC--
WEST., AE--BECHTEL

CAUSE - BACK LEAKAGE FROM STEAM GENERATOR. WITH THE UNIT AT FULL POWER, AN OPERATOR OBSERVED LEAKAGE FROM THE STEAM-DRIVEN AUXILIARY FEED PUMP SHAFT GLANDS. THE LEAKAGE WAS CAUSED BY BACK LEAKAGE FROM STEAM GENERATOR B THROUGH THE CHECK VALVES TO THE PUMP. SOME OF THIS LEAKAGE RAN OVER INTO THE NEARBY SUB-SOIL DRAIN SYSTEM WHICH IS UNMONITORED. BECAUSE OF THE PREVIOUS STEAM GENERATOR TUBE FAILURE INCIDENT, THE SECONDARY SYSTEM FLUIDS WERE SLIGHTLY RADIOACTIVE. ONLY ABOUT 8 GALLONS LEAKED INTO THIS SYSTEM. THE LEAK WAS STOPPED BY CLOSING THE PUMP DISCHARGE VALVE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

POINT BEACH 1 (PWR) + RADIOACTIVITY RELEASE + LEAK + SEAL + PUMPS + FEEDWATER + WATER

103403

103403 *CONTINUED*
 BORIC ACID HEAT TRACING CHANNEL INOPERABLE AT POINT BEACH 1
 WISCONSIN ELECTRIC POWER CO., MILWAUKEE
 2 PAGES, LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JUNE 9, 1975, DOCKET 50-266, TYPE--PWR, NRC--
 WEST.. AE--BECHTEL

CAUSE - LOOSE CONNECTION ON FUSE HOLDER. DURING A REVIEW OF BORIC ACID HEAT TRACING TEST DATA, THE SUPERINTENDENT NOTED THAT RESULTS INDICATED THAT A CHANNEL WAS NOT FUNCTIONAL. A REACTOR SHUTDOWN WAS STARTED. THE CAUSE WAS A LOOSE CONNECTION ON A FUSE HOLDER. THE CHANNEL WAS REPAIRED AND THE SHUTDOWN TERMINATED 26 MINUTES LATER. OPERATING PERSONNEL WHO PERFORMED THE TEST AND ITS INITIAL REVIEW FAILED TO RECOGNIZE THIS AS A REPORTABLE INCIDENT. TEST PROCEDURES WERE MODIFIED TO SPECIFY REQUIRED CHANNELS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

POINT BEACH 1 (PWR) * HEATERS * POISON, SOLUBLE * CHEMICAL SHIM * SAFETY INJECTION * PIPES AND PIPE FITTINGS
 * TEST, SYSTEM OPERABILITY * REVIEW * FAILURE, MAINTENANCE ERROR * CABLES AND CONNECTORS * REACTOR SHUTDOWN

103905
 ADDITIONAL INFORMATION ON STEAM GENERATOR TUBE FAILURE AT POINT BEACH 1
 WISCONSIN ELECTRIC POWER COMPANY
 30 PAGES, LETTER WITH ATTACHMENT TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JUNE 26, 1975, DOCKET 50-266,
 TYPE--PWR, NRC--WEST.. AE--BECHTEL

CAUSE - CORROSION. ESSENTIALLY ALL THE TUBES IN BOTH STEAM GENERATORS WERE INSPECTED EXCEPT THE PREVIOUSLY PLUGGED OR THOSE INACCESSIBLE. ALL TUBES WITH DEFECT INDICATIONS GREATER THAN 300 WERE PLUGGED. THERE WERE 90 IN A AND 90 IN B STEAM GENERATOR. ONE TUBE HAD FAILED. SLUDGE FROM THE PHOSPHATE TREATMENT THAT HAD BEEN USED WAS REMOVED, 1200 POUNDS OF WET SLUDGE FROM A AND 1000 POUNDS FROM B. THE RECALCULATED TOTAL AIRBORNE RELEASE FOR THIS INCIDENT IS 602 CI OR 2265 CI RE-133 EQUIVALENT. SLUDGE REMAINING IN THE SECONDARY SIDE WILL BE REMOVED BY LANCING DURING REFUELING SHUTDOWNS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

POINT BEACH 1 (PWR) * TUBING * STEAM GENERATOR * MAINTENANCE AND REPAIR * TEST, NONDESTRUCTIVE * FAILURE,
 TUBING * CRUD * CORROSION * AIRBORNE RELEASE

103906
 PURGE SUPPLY ISOLATION VALVE LEAKS AT POINT BEACH 1
 WISCONSIN ELECTRIC POWER COMPANY
 1 PAGE, LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JULY 1, 1975, DOCKET 50-266, TYPE--PWR, NRC--
 WEST.. AE--BECHTEL

CAUSE - DIRT ON MATING SURFACES. AN INTEGRATED VALVE LEAK RATE TEST PERFORMED AFTER A CONTAINMENT PURGE FOUND THE OUTBOARD PURGE SUPPLY ISOLATION VALVE TO BE LEAKING. THE VALVE WAS CLEANED, LUBRICATED, AND RETESTED SATISFACTORILY. THE CAUSE OF THE SLIGHT LEAK-THROUGH WAS DIRT ON THE VALVE MATING SURFACES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

POINT BEACH 1 (PWR) * VALVES * LEAK RATE * CONTAINMENT ISOLATION * CONTAINMENT PURGE * CRUD * FAILURE,
 EQUIPMENT * TEST, SYSTEM OPERABILITY * TEST, LEAK RATE

105203
 OUTBOARD CONTAINMENT PURGE SUPPLY VALVE LEAKS AT POINT BEACH 1
 WISCONSIN ELECTRIC POWER COMPANY, MILWAUKEE
 2 PGS, LTR TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, AUG. 10, 1975, DOCKET 50-266, TYPE--PWR, NRC--WEST..
 AE--BECHTEL

CAUSE - DIRT ON SEAT. FOLLOWING A CONTAINMENT PURGE OPERATION, AN INTEGRATED VALVE LEAK RATE TEST SHOWED THAT THE OUTBOARD PURGE SUPPLY VALVE LEAKED. THE VALVE WAS CLEANED AND LUBRICATED AND RETESTED SATISFACTORILY. THE POTENTIAL FOR DUST ACCUMULATION DURING PURGING IS RECOGNIZED; THEREFORE, THE VALVES ARE TESTED AFTER EACH PURGING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

POINT BEACH 1 (PWR) * LEAK RATE * VALVES * CONTAINMENT PURGE * TEST, SYSTEM OPERABILITY * TEST, LEAK RATE *
 CRUD * FAILURE, EQUIPMENT

105530
 PRESSURIZER PRESSURE CHANNEL DISTABLE FAILS TO TRIP AT POINT BEACH 1
 WISCONSIN ELECTRIC POWER COMPANY, MILWAUKEE
 2 PGS, LTR TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, AUG. 20, 1975, DOCKET 50-266, TYPE--PWR, NRC--WEST..
 AE--BECHTEL

105538 "CONTINUED"

CAUSE - SILICONE CONTROL SWITCH FAILURE. DURING TESTING, THE BISTABLE OF A HIGH PRESSURIZER PRESSURE CHANNEL FAILED TO TRIP. THE FORBODER MODEL 63U-AC-OMBA BISTABLE WAS REPLACED IN KIND. A FAILED SILICONE CONTROL SWITCH WAS FOUND IN THE FAULTY BISTABLE CIRCUITRY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

POINT BEACH 1 (PBR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • PERSONNEL, PRESSURE • TEST, SYSTEM OPERABILITY • ELECTRONIC FUNCTION UNITS • FAILURE, COMPONENT • FAILURE, INSTRUMENT

106331

REDUNDANCY ON NUCLEAR POWER RANGE CHANNEL LOST TEMPORARILY AT POINT BEACH 1

WISCONSIN ELECTRIC POWER CO., MILWAUKEE, WI

2 PGS, AWR 50-266/75-13 TO NRC DIRECTOR OF OFFICE OF NUCLEAR REACTOR REGULATION, SEPT. 15, 1975, DOCKET 50-266, TYPE--PWR, MFG--WEST., AE--DECHTEL

CAUSE - POWER SUPPLY MALFUNCTION. WITH THE UNIT AT 100% POWER DURING A TRANSFER OF THE NUCLEAR POWER RANGE CHANNEL 43 POWER SUPPLY FROM INVERTER 10Y01 TO INVERTER 10Y02, THE HIGH-FREQUENCY POWER SUPPLY FAILED TO RESTART, THEREBY MAKING THE CHANNEL INOPERATIVE. CHANNEL 43 OPERATION WAS RE-ESTABLISHED FROM INVERTER 10Y02 BY REMOVING AND REINSERTING THE POWER SUPPLY FUSES. RESTART WAS EFFECTED BY OPENING AND THEN RE-ESTABLISHING THE 60 HZ SUPPLY TO THE HIGH-FREQUENCY OSCILLATOR.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

POINT BEACH 1 (PBR) • INSTRUMENT, POWER RANGE • ELECTRIC POWER • FAILURE, INSTRUMENT • REACTOR CONTROL • REDUNDANCE • ELECTRONIC FUNCTION UNITS

106440

PRESSURE SWITCH CALIBRATED INCORRECTLY AT POINT BEACH 1

WISCONSIN ELECTRIC POWER CO., WIS.

2 PGS, LTR W/AV 50-266/75-14 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, SEPT. 17, 1975, DOCKET 50-266, TYPE--PWR, MFG--WEST., AE--DECHTEL

CAUSE - PERSONNEL ERROR. DURING TESTING, A TECHNICIAN INCORRECTLY RECALIBRATED A CONTAINMENT PRESSURE CHANNEL SET POINT BASED ON MISTAKEN TEST RESULTS. HE CORRECTLY LOGGED THE APPARENT DISCREPANCY AND CORRECTIVE ACTION TAKEN. THE NEXT MORNING HE REQUESTED VERIFICATION OF THE SET POINT. TESTS SHOWED THE SET POINT TO BE 0.295 PSI ABOVE THE 6 PSI LIMIT. IT WAS RECALIBRATED. THE TECHNICIAN MISDID THE CHANNEL RESET POINT FOR THE SET POINT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

POINT BEACH 1 (PBR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • PERSONNEL, PRESSURE • TEST, SYSTEM OPERABILITY • SET POINT • FAILURE, OPERATOR ERROR • FAILURE, INSTRUMENT • EMERGENCY COOLING SYSTEM

106797

SAFETY INJECTION SYSTEM VALVE FAILS TO CLOSE AT POINT BEACH 1

WISCONSIN ELECTRIC POWER CO., MILWAUKEE, WI

2 PGS, AWR 50-266/76-16 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, DEC. 12, 1975, DOCKET 50-266, TYPE--PWR, MFG--WEST., AE--DECHTEL

CAUSE - UNKNOWN. DURING EVENTS FOLLOWING A UNIT TRIP, AN UNNECESSARY SAFETY INJECTION SIGNAL WAS INITIATED WITH EXPECTED AUTOMATIC EQUIPMENT ACTION. A GAINWELL-SAUNDERS 1-INCH, A32R DIAPHRAGM VALVE SERVING AS THE OUTBOARD CONTAINMENT ISOLATION VALVE ON THE REACTOR COOLANT DRAIN TANK VENT LINE WAS THOUGHT TO HAVE FAILED TO CLOSE. AN INVESTIGATION INDICATED THAT THE LIMIT SWITCH WAS NOT SET PROPERLY. IT WAS READJUSTED. DURING ANOTHER TEST, IT FAILED AGAIN. RETESTING SHOWED IT TO OPERATE PROPERLY. THE REACTOR WAS IN A REFUELING SHUTDOWN AT THE TIME.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

VALVES • SAFETY INJECTION • FAILURE, EQUIPMENT • TEST, SYSTEM OPERABILITY • REFUELING • CONTAINMENT ISOLATION • POINT BEACH 1 (PBR)

109105

REDUNDANT CONTAINMENT VALVE FAILS TO CLOSE AT POINT BEACH 1

WISCONSIN ELECTRIC POWER CO., MILWAUKEE, WI

2 PGS, AWR 50-266/75-17 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, DEC. 19, 1975, DOCKET 50-266, TYPE--PWR, MFG--WEST., AE--DECHTEL

CAUSE - SOLENOID MALFUNCTION. DURING A REFUELING OUTAGE TEST, A REDUNDANT ISOLATION VALVE ON THE RETURN LINE FROM A RADIATION MONITOR TO THE CONTAINMENT FAILED TO CLOSE ON SIGNAL. WHEN AN OPERATOR TAPPED THE SOLENOID VALVE ON THE INSTRUMENT AIR VENT LINE FROM THE VALVE OPERATOR, THE VALVE CLOSED. THE VALVE WAS CYCLED SEVERAL TIMES WITH NO FURTHER ASSISTANCE. NO PROBLEM WAS FOUND WITH THE SOLENOID. THE ENERGIZING COIL WAS CHANGED AS A PRECAUTIONARY MEASURE.

109105 PLANTINURUP
 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

POINT BEACH 1 (PBR) • VALVES • CONTAINMENT ISOLATION • TEST, SYSTEM OPERABILITY • SOLENOID • RADIATION
 MONITORS • REFUELING

109106
 FAILED FUEL RODS FOUND IN AN ASSEMBLY AT POINT BEACH 1
 WISCONSIN ELECTRIC POWER CO., MILWAUKEE, WI
 9 PAGES, RELEASE EVENT RPT 50-206/75-10 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, DEC. 30, 1975, DOCKET 50-
 206, TYPE--PWR, NRC--WEST., AE--ORCTEL

CAUSE - WATER IMPINGEMENT THROUGH BAFFLE PLATE. DURING REFUELING, SOMETHING WAS OBSERVED TO BE
 FALLING FROM THE SIDE OF A FUEL ASSEMBLY. EXAMINATION FOUND 3 DAMAGED FUEL RODS. PARTS OF 2
 RODS WERE MISSING. A HIGHLY PROBABLE INITIATING FACTOR WAS WATER IMPINGEMENT THROUGH THE BAFFLE
 PLATE WHILE THE ASSEMBLY WAS IN ITS ORIGINAL POSITION. FUEL RODS CONTAINING HOLES IN THE CLAD
 BECAME WATERLOGGED DURING SHUTDOWN AND BURST DUE TO STEAM PRESSURE AND/OR LACK OF SUFFICIENT TIME
 FOR THE ZIRCALOY TO PRACTICALLY DEFORM DURING POWER ESCALATION. LOOSE FUEL PELLETS HAVE BEEN
 REMOVED. THE RATE OF POWER ESCALATION HAS BEEN REDUCED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

POINT BEACH 1 (PBR) • FUEL ROD • FAILURE, FUEL ELEMENT • FAILURE, FUEL ELEMENT WATERLOGGING • FAILURE,
 CLADDING • HYDRAULIC EFFECT • JET • REFUELING

090722
 STEAM GENERATOR AUXILIARY FEED VALVE FAILS TO OPEN AT POINT BEACH 2
 WISCONSIN ELECTRIC POWER COMPANY
 3 PAGES, LETTER TO DIRECTORATE OF LICENSING (AEC), JANUARY 2, 1975, DOCKET 50-301, TYPE--PWR, NRC--WEST., AE--
 ORCTEL

CAUSE - EXCESS CLOSING TORQUE. FOLLOWING THE INITIAL POST-REFUELING STARTUP, THE AUXILIARY FEED
 DISCHARGE VALVE COULD NOT BE OPENED ELECTRICALLY. THE MOTOR THERMAL SWITCH WAS TRIPPED. THE
 TORQUE SWITCH WAS SET AT A SLIGHTLY HIGHER TORQUE THAN DESIRED. EXPERIENCE HAS SHOWN THAT A
 MOTOR AMPERAGE OF 1.5 TO 2.0 TIMES NORMAL OPERATING AMPERAGE FOR THE MOTOR AT THE TIME THE TORQUE
 SWITCH IS ACTUATED ACHIEVES A SATISFACTORY CLOSING. NO CAUSE FOR THE SLIGHT SHIFT HAS BEEN
 FOUND. THE SWITCH WAS RESET.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

FAILURE, COMPONENT • INSTRUMENT, SWITCH • STEAM GENERATOR • SET POINT • POINT BEACH 2 (PBR) • FEEDWATER •
 VALVE OPERATORS • VALVES

099017
 STEAM GENERATOR LEVEL INSTRUMENT MALFUNCTION AT POINT BEACH 2
 WISCONSIN ELECTRIC POWER COMPANY
 1 PAGE, LETTER TO DIRECTORATE OF LICENSING (AEC), JANUARY 3, 1975, DOCKET 50-301, TYPE--PWR, NRC--WEST., AE--
 ORCTEL

CAUSE - OBSTRUCTION IN SENSING LINE. AT 1:00 A.M., THE OPERATOR NOTED THAT 1 OF THE 3 FEEDWATER
 LEVEL INDICATORS WAS RISING. MANUAL CONTROL OF THE FEED REGULATING VALVE WAS IMMEDIATELY
 INITIATED. AFTER BLOWING DOWN THE SENSING LINES CONNECTING THE STEAM GENERATOR TO THE LEVEL
 TRANSMITTER, THE CHANNEL INDICATION RETURNED TO NORMAL AND THE INSTRUMENT WAS RETURNED TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

REACTION SAFETY SYSTEM • FAILURE, INSTRUMENT • CRUD • INSTRUMENT, SWITCH • STEAM GENERATOR • TUBING • POINT
 BEACH 2 (PBR) • SENSORS, LEVEL

099365
 CONTAINMENT PURGE AND EXHAUST VALVE CLOSING TIME EXCEEDS LIMIT AT POINT BEACH 2
 WISCONSIN ELECTRIC POWER COMPANY
 2 PAGES, LETTER TO DIRECTORATE OF LICENSING (AEC), JANUARY 8, 1975, DOCKET 50-301, TYPE--PWR, NRC--WEST., AE--
 ORCTEL

CAUSE - LACK OF LUBRICATION. DURING REFUELING OUTAGE TESTING OF THE CONTAINMENT PURGE AND
 EXHAUST VALVES, CLOSING TIMES EXCEEDED THE 3 SECOND LIMIT FOR ALL 4 VALVES. TIMES RANGED FROM 7
 TO 57 SECONDS. THE VALVES WERE CLEANED AND LUBRICATED. RETEST SHOWED CLOSING TIMES TO BE LESS
 THAN 3 SECONDS. DURING NORMAL OPERATION, THESE VALVES ARE CLOSED TO ESTABLISH CONTAINMENT
 INTEGRITY AND ARE NOT NORMALLY REOPENED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

CONTAINMENT • CONTAINMENT AIR COOLING • RESPONSE TIME • REFUELING • TEST, SYSTEM OPERABILITY • FAILURE,

099365 PLUMBERED
MAINTENANCE ERROR • LUBRICATION • POINT BEACH 2 (PWR) • VALVES

099400
ISOLATION VALVES TESTED FOR LEAKAGE AT POINT BEACH 2
WISCONSIN ELECTRIC POWER COMPANY
4 PAGES, LETTER TO NRC DIRECTORATE OF LICENSING (AE), JANUARY 13, 1975, DOCKET 50-301, TYPE--PWR, NRC--WEST., AE--
BECHTEL

CAUSE - NOT STATED. DURING THE FIRST REFUELING UNITAGE, ALL CONTAINMENT ISOLATION VALVES WERE TESTED AND NECESSARY REPAIRS WERE MADE. THROUGH LEAKAGE IN EXCESS OF 2330 CC/MIN AT 60 PSIG (AIR) WAS FOUND IN 7 VALVES. ALL CHECK VALVES. TEST PRESSURE WAS ADDED SLOWLY. CHECK VALVES SEAT BETTER WITH SLOWER PRESSURE INCREASES. THREE WERE CLEANED AND LAPPEED, 2 WERE REPLACED, AND 2 MAC J-WINGS INSTALLED. THE OVERALL TYPE A TEST INDICATED A TOTAL LEAK RATE OF 0.7% OF THE ALLOWABLE RATE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20543, 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

CONTAINMENT ISOLATION • TEST, LEAK RATE • CONTAINMENT INTEGRITY • REFUELING • TEST, SYSTEM OPERABILITY •
VALVE, CHECK • POINT BEACH 2 (PWR)

099715
LOW LEVEL RADIOACTIVE RELEASE WITHOUT IN-LINE MONITOR AT POINT BEACH 2
WISCONSIN ELECTRIC POWER COMPANY
3 PAGES, LETTER TO NRC DIRECTORATE OF LICENSING, FEBRUARY 7, 1975, DOCKET 50-301, TYPE--PWR, NRC--WEST., AE--
BECHTEL

CAUSE - ADMINISTRATIVE ERROR. DURING A STARTUP OF THE 35-PPH BLOWDOWN EVAPORATOR, A SAMPLE OF THE STEAM GENERATOR BLOWDOWN TANK DISCHARGE WATER WAS TAKEN. A LATER ANALYSIS INDICATED TRACES OF RADIOACTIVITY IN THE WATER. INVESTIGATION INDICATED THAT A CONTAMINATED SAMPLE BOTTLE MAY HAVE BEEN USED. ANOTHER STARTUP PRODUCED A SAMPLE WHICH INDICATED RADIOACTIVITY. THIS IS BELIEVED TO BE CARRYOVER FROM VENTING PRIOR TO STARTUP. IN THE FUTURE, IF THE SAMPLE SHOWS RADIOACTIVITY, THE LIQUID WILL BE RECYCLED PRIOR TO RELEASE. CALCULATED RELEASES WERE LESS THAN .001% OF THE TECH SPEC LIMIT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20543, 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

FAILURE, OPERATION ERROR • WASTE DISPOSAL • WASTE HANDLING • SAMPLING • WASTE DISPOSAL, LIQUID • RADIOACTIVITY
RELEASE • FAILURE, ADMINISTRATIVE CONTROL • POINT BEACH 2 (PWR)

100410
PURGE SUPPLY VALVE LEAKS AT POINT BEACH 2
WISCONSIN ELECTRIC POWER CO.
1 PAGE, LETTER TO NRC DIRECTORATE OF LICENSING, MARCH 5, 1975, DOCKET 50-301, TYPE--PWR, NRC--WEST., AE--
BECHTEL

CAUSE - DIRT. PRIOR TO REACTOR COOLANT SYSTEM HEATUP AND FOLLOWING A CONTAINMENT PURGE OPERATION, TESTS SHOWED THAT OUTWARD PURGE SUPPLY VALVE, A CONTAINMENT ISOLATION VALVE, LEAKED. AFTER BEING CLEANED AND LUBRICATED, THE VALVE TESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20543, 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

CONTAINMENT ISOLATION • TEST, LEAK RATE • VENTILATION SYSTEM • CRUD • TEST, SYSTEM OPERABILITY • FAILURE,
MAINTENANCE ERROR • LUBRICATION • LEAK • POINT BEACH 2 (PWR) • VALVES

102520
RESISTANCE TEMPERATURE DETECTOR FAILS AT POINT BEACH 2
WISCONSIN ELECTRIC POWER COMPANY
2 PAGES, LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, APRIL 30, 1975, DOCKET 50-301, TYPE--PWR, NRC--
WEST., AE--BECHTEL

CAUSE - COMPONENT FAILURE. THE DIFFERENTIAL TEMPERATURE METER FOR A CHANNEL WAS READING ABOUT 3 F LOWER THAN THOSE FOR THE OTHER 3 CHANNELS. THE HOT LEG TEMPERATURE WAS READING 3.2 F LOW. THE PROBLEM WAS FOUND TO BE A FAILED RESISTANCE TEMPERATURE DETECTOR. THE INSTALLED SPARE WAS WIRED INTO THE CIRCUIT AND THE CHANNEL RETURNED TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20543, 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

POINT BEACH 2 (PWR) • SENSORS, TEMPERATURE • REACTOR SAFETY SYSTEM • FAILURE, INSTRUMENT

103105
MAIN STEAM STOP VALVE FAILS TO CLOSE WITH ZERO FLOW AT POINT BEACH 2
WISCONSIN ELECTRIC POWER CO.

103105 CONTINUUM
3 PGS. LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, MAY 19, 1975, Docket 50-301, TYPE--PWR, HFC--
WEST.. AE--RECEIVED

CAUSE - FLAT PACKING. WITH THE UNIT AT HOT SHUTDOWN, ZERO POWER CONDITIONS, THE MAIN STEAM STOP VALVES WERE TRIPPED SHUT FROM THE CONTROL ROOM. ONE VALVE WENT ONLY ABOUT 90% CLOSED. THE SUPERVISOR LOOSENED THE VALVE PACKING, APPLIED LUBRICATION TO THE VALVE OPERATOR LINKAGE, AND CLOSED THE VALVE SEVERAL TIMES. THESE VALVES HAVE FAILED TO CLOSE COMPLETELY SEVERAL TIMES AT ZERO FLOW. IF THEY ARE REQUIRED TO OPERATE, THERE WILL BE STEAM FLOW WHICH WILL SNEAK THEM SHUT. LOOSENING THE PACKING COMPROMISES LEAK TIGHTNESS. THEREFORE, TESTING WILL BE DONE WITH SOME STEAM FLOW IN THE FUTURE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

POINT BEACH 2 (PWR) + VALVES + CONTAINMENT ISOLATION + MAIN COOLING SYSTEM + STEAM + SEAL + LUBRICATION + FAILURE, MAINTENANCE ERROR + LUBRICATION + TESTING + PROCEDURES AND MANUALS

103604
REDUNDANT TRIP MECHANISM ON MAIN STEAM STOP VALVE FAILS AT POINT BEACH 2
WISCONSIN ELECTRIC POWER COMPANY
1 PAGE, LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JUNE 13, 1975, Docket 50-301, TYPE--PWR, HFC--
WEST.. AE--RECEIVED

CAUSE - LINKAGE OUT OF ADJUSTMENT. DURING A MAIN STEAM ISOLATION AND CHECK VALVE TEST, THE MECHANICAL LATCHING MECHANISM ON THE REDUNDANT SOLENOID TRIP VENT VALVE ON STOP VALVE A FAILED TO UNLATCH WHEN THE SOLENOID WAS ENERGIZED. THE CAUSE WAS A SLIGHT MALADJUSTMENT OF THE SOLENOID LINKAGE. NO SPECIFIC REASON FOR THE CHANGE IN ADJUSTMENT WAS FOUND. CREEPING OF THE LINKAGE IS A POSSIBILITY. AFTER THE LINKAGE WAS ADJUSTED, THE TEST WAS SUCCESSFUL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

POINT BEACH 2 (PWR) + VALVES + CONTAINMENT ISOLATION + MAIN COOLING SYSTEM + STEAM + FAILURE, COMPONENT + SOLENOID + TEST, SYSTEM OPERABILITY

106113
REDUNDANT TRIP MECHANISM ON MAIN STEAM STOP VALVE FAILS AT POINT BEACH 2
WISCONSIN ELECTRIC POWER CO., WISC.
2 PGS. AUG 30-30/75-7 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, SEPT. 10, 1975, Docket 50-301, TYPE--PWR, HFC--
WEST.. AE--RECEIVED

CAUSE - UNKNOWN. DURING TESTING, THE MECHANICAL LATCHING MECHANISM ON THE REDUNDANT SOLENOID TRIP VENT VALVE ON A MAIN STEAM STOP VALVE FAILED TO UNLATCH WHEN THE SOLENOID WAS ENERGIZED. IT TRIPPED SUCCESSFULLY ON 11 SUCCESSIVE TESTS. NO CAUSE WAS FOUND FOR THE MALFUNCTION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

POINT BEACH 2 (PWR) + VALVES + COOLING SYSTEM, SECONDARY + CONTAINMENT ISOLATION + TEST, SYSTEM OPERABILITY + STEAM + FAILURE, EQUIPMENT

106613
STEAM GENERATOR TUBE LEAK AT POINT BEACH 2
WISCONSIN ELECTRIC POWER CO., WISC.
8 PGS. LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, SEPT. 26, 1975, Docket 50-301, TYPE--PWR, HFC--
WEST.. AE--RECEIVED

CAUSE - MANUFACTURING DEFECT OR DAMAGE. AN UPWARD TREND IN AN AIR EJECTOR RADIATION MONITOR AND BLOWDOWN MONITOR INDICATED A PRIMARY-SECONDARY STEAM GENERATOR LEAK. WHEN THE SLIGHT UPWARD TREND CONTINUED, THE REACTOR WAS SHUT DOWN. A RELATIVELY CLEAN CUT, ROUGHLY CIRCULAR HOLE WAS FOUND IN ONE TUBE. IT APPEARS TO BE A MANUFACTURING DEFECT OR THE RESULT OF DAMAGE FOLLOWING MANUFACTURE. OUR CURRENT TESTING FOUND ONLY 2 OTHER TUBES TO HAVE SIGNIFICANT DEFECTS. THE DEFECTIVE TUBES WERE PLUGGED. THE ALL VOLATILE WATER CHEMISTRY TREATMENT APPEARS AT THIS STAGE TO HAVE INHIBITED THE TUBE MASTAGE PROBLEM IN THE HOT LEGS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

POINT BEACH 2 (PWR) + STEAM GENERATOR + LEAK + TUBING + FAILURE, TUBING + FAILURE, FABRICATION ERROR + DAMAGE + WATER TREATMENT + EFFECT

107705
REFUELING WATER STORAGE TANK LEVEL BELOW LIMIT AT POINT BEACH 2
WISCONSIN ELECTRIC POWER CO., WILMUNKEE, WISC.
2 PGS. AUG 30-30/75-8 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, OCT. 30, 1975, Docket 50-301, TYPE--PWR, HFC--
WEST.. AE--RECEIVED

CAUSE - INCORRECT VALVE LINE-UP. THE OPERATOR NOTED THAT THE REFUELING WATER STORAGE TANK LEVEL

107705 PLANTINAGEUP

WAS 90%. 1 IS BELOW THE LIMIT. THE TANK WAS THOUGHT TO BE IN THE RECIRCULATING MODE USING THE REFUELING WATER CIRCULATING PUMP. IT WAS FOUND THAT THE PUMP DISCHARGE LINE WAS INCORRECTLY LINED UP TO THE UNIT 1 RUST ISOLATING IN THE TRANSFER FROM UNIT 2 RUST TO UNIT 1 RUST. A RETRANSFER TO UNIT 2 RUST WAS STARTED IMMEDIATELY. LEVEL WAS RESTORED IN 1 HOUR. THE IMPROPER VALVE LINE-UP WAS DUE TO A MISMATCH IN COMMUNICATION BETWEEN THE AUXILIARY OPERATOR AND HIS TRAINEE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

POINT BEACH 2 (PWR) • SYSTEM CAPACITY • STORAGE CONTAINER • REFUELING • WATER • CHEMICAL SHIM • POISON, SOLUBLE • FAILURE, OPERATOR ERROR • COMMUNICATION

092249

POSSIBLE GENERAL PROBLEMS WITH SAMPLE LINES WITHIN PENETRATIONS AT POINT BEACH 1 AND 2

WISCONSIN ELECTRIC POWER COMPANY

4 PGS., LETTER TO NRC DIRECTORATE OF LICENSING, JANUARY 22, 1975, DOCKETS 50-266/301, TYPE--PWR, WFG--WEST., AE--DEINTEL

CAUSE - THERMAL EXPANSION. FAILURE OF A SAMPLE LINE WITHIN UNIT 2 CONTAINMENT PENETRATION ASSEMBLY WAS REPORTED EARLIER. EXAMINATION OF THE LINE INDICATED IT FAILED FROM FATIGUE. WITH THE 4 FOOT LONG 3/4 INCH LINE SECURED AT EITHER END OF THE PENETRATION, BENDING OCCURS DUE TO THERMAL EXPANSION. IF THE SAMPLE VALVE IS OPENED QUICKLY, THERE IS A RAPID TEMPERATURE RISE TO 530 F AND POSSIBLY HYDRAULIC SHOCK. LINE FAILURE CAN OVERPRESSURIZE THE PENETRATION. A DESIGN MODIFICATION WILL BE INSTALLED IN 2 PENETRATIONS IN EACH UNIT DURING THE NEXT REFUELING OUTAGE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THERMAL MECHANICAL EFFECT • SAMPLING • FAILURE, FATIGUE • FAILURE, DESIGN ERROR • POINT BEACH 1 (PWR) • CONTAINMENT PENETRATION, PIPE • POINT BEACH 2 (PWR) • FAILURE, COMMON MODE • PIPES AND PIPE FITTINGS • PENETRATIONS, PRIMARY CONTAINMENT

093246

STATION BATTERY TESTING NOT PERFORMED ON TIME AT POINT BEACH 1 AND 2

WISCONSIN ELECTRIC POWER COMPANY

1 PAGE, LETTER TO NRC DIRECTORATE OF LICENSING, JANUARY 24, 1975, DOCKETS 50-266/301, TYPE--PWR, WFG--WEST., AE--DEINTEL

CAUSE - NEW SUPERVISOR. DURING A REVIEW OF PAST RECORDS, IT WAS DISCOVERED THAT THE TIME INTERVAL BETWEEN STATION BATTERY TESTS WAS 62 DAYS FOR ONE TIME IN 1973. THE MAXIMUM ALLOWABLE PERIOD IS 39 DAYS. THE SCHEDULING DIFFICULTY INVOLVED A NEW SUPERVISOR. THE PRESENT SYSTEM OF CALLING OUT THIS TEST IS BASICALLY SOUND.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

REVIEW • FAILURE, ADMINISTRATIVE CONTROL • POINT BEACH 1 (PWR) • TEST INTERVAL • POINT BEACH 2 (PWR) • BATTERIES & CHARGERS

102506

DIESEL RELAY FAILS TO RESPOND WITHIN TIME LIMIT AT POINT BEACH 1 AND 2

WISCONSIN ELECTRIC POWER CO.

2 PGS., LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, APRIL 28, 1975, DOCKETS 50-266/331, TYPE--PWR, WFG--WEST., AE--DEINTEL

CAUSE - UNKNOWN. DURING THE ANNUAL EMERGENCY DIESEL INSPECTION, A START-FAILURE DELAY RELAY FAILED TO OPERATE WITHIN THE 4 SECOND MAXIMUM TIME LIMIT. IT REQUIRED 1 MIN. 39 SECONDS. THE RELAY OPERATED SATISFACTORILY UPON IMMEDIATE RETEST. THIS IS NOT CONSIDERED AN ABNORMAL OCCURRENCE SINCE FAILURE OF THE RELAY WHEN NEEDED PRESUMES A DOUBLE FAILURE. THIS RELAY'S FUNCTION IS TO TIME OUT AFTER 4 SECONDS AND, IF THE PRIMARY STARTING CIRCUIT HAS FAILED TO BRING THE DIESEL SPEED TO OVER 100 RPM, SHUT DOWN THE PRIMARY CIRCUIT AND SHIFT TO THE SECONDARY STARTING CIRCUIT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

POINT BEACH 1 (PWR) • POINT BEACH 2 (PWR) • RESPONSE TIME • RELAYS • CONTROL SYSTEM • GENERATOR, DIESEL • ENGINES, INTERNAL COMBUSTION • TEST, SYSTEM OPERABILITY

104034

UNSCHEDULED RELEASE OF GASEOUS RADIOACTIVITY AT POINT BEACH 1 AND 2

WISCONSIN ELECTRIC POWER COMPANY, MILWAUKEE

3 PGS., LTR TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JULY 30, 1975, DOCKET 50-266/301, TYPE--PWR, WFG--WEST., AE--DEINTEL

CAUSE - MAINTENANCE ERROR. MAINTENANCE PERSONNEL, IN PREPARATION FOR WASTE GAS VENT HEADFR

104034 PLANTINGUP

MAINTENANCE PERSONNEL BEGAN SAMPLING FOR HYDROGEN AND RADIOACTIVE GAS IN 3 LOCATIONS. HOWEVER, 2 OF THE PLANTS WERE NOT WITHIN THE BOUNDARY ESTABLISHED BY THE RED-TAG PERMIT. IN A 120 MINUTE PERIOD, 76.5 LB WERE RELEASED, PRIMARILY AE-133 AND AE-131 M. MAINTENANCE PERSONNEL FAILED TO NOTICE THAT ONE VALVE THAT WAS OPENED WAS A BOUNDARY VALVE BUT THE RED TAG WAS ON THE OTHER SIDE OF THE SHIELD WALL. A CONTRIBUTING FACTOR WAS LACK OF COMMUNICATION BETWEEN OPERATIONS AND MAINTENANCE SUPERVISORS CONCERNED WITH THE WORK PERMIT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

POINT BEACH 1 (PWR) + POINT BEACH 2 (PWR) + OAKRIDGE RELEASE + WASTE TREATMENT + MAINTENANCE AND REPAIR + FAILURE, MAINTENANCE ERROR + COMMUNICATION

104210

UNANNOUNCED MONITORED GASEOUS DISCHARGE OCCURS AT POINT BEACH 1 AND 2

WISCONSIN ELECTRIC POWER CO., MILWAUKEE, WIS.

2 PGS. LHM W/ILLUSTR. EVENT APTS 50-266/75-25 & 50-331/75-9 TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, NOV. 17, 1975. Docket 50-266/301, TYPE--PWR, HFG--WEST, AE--DECTEL

CAUSE - VALVE LEAKAGE. A SCHEDULED RELEASE FROM GAS DELAY TANK 2 WAS MADE THROUGH THE NEW CATALYTIC SYSTEM. ANALYSIS OF A DISCHARGE SAMPLE FOUND SHORT-LIVED ISOTOPES THAT WERE NOT PRESENT IN THE TANK. INVESTIGATION SHOWED THAT THE VALVE LINE-UP WAS CORRECT. THE IN-LEAKAGE FROM THE RADWASTE SYSTEM PROCESS STREAM WAS LEAKAGE THROUGH ONE OF THE CROSS-CONNECT VALVES. THE DISCHARGE WAS TERMINATED. IT WAS REMEDIATED UTILIZING THE PATH EMPLOYED PRIOR TO INSTALLATION OF THE NEW RADWASTE SYSTEM. THE TOTAL UNPLANNED RELEASE WAS 0.034 CI.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

POINT BEACH 1 (PWR) + OAKRIDGE RELEASE + PLEAK + VALVES + WASTE TREATMENT, EQUIPMENT + WASTE TREATMENT + WASTE DISPOSAL + FAILURE, EQUIPMENT

104085

MAIN STEAM POWER OPERATED RELIEF VALVE MALFUNCTION AT PRAIRIE ISLAND 1

NORTHERN STATES POWER COMPANY, MINN.

1 PAGE. LETTER TO NRC DIVISION OF REACTOR LICENSING, FEBRUARY 24, 1975. DOCKET 50-282, TYPE--PWR, HFG--WEST, AE--PIONEER SERV.

CAUSE - UNKNOWN. WHILE THE UNIT WAS AT HOT SHUTDOWN, A MAIN STEAM POWER OPERATED RELIEF VALVE FAILED TO OPEN. AFTER IT WAS ISOLATED, IT OPENED ON DEMAND. STEAM WAS THEN ADMITTED TO SLIGHTLY OPEN THE VALVE BY CRACKING OPEN THE ISOLATION VALVE. AFTER THIS WAS DONE, THE VALVE WAS USED SATISFACTORILY. IT IS BELIEVED THAT FOREIGN MATERIAL CAUSED THE INITIAL STICKING. IT WAS BLOWN CLEAN BY STEAM FLOW.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, EQUIPMENT + STEAM + CRUI + PRESSURE RELIEF + MAIN COOLING SYSTEM + PRAIRIE ISLAND 1 (PWR) + VALVES

104080

CONTROL ROD EXERCISE UNIT AT PRAIRIE ISLAND 1

NORTHERN STATES POWER CO., MINN.

1 PAGE. LETTER TO NRC DIVISION OF REACTOR LICENSING, MARCH 11, 1975. DOCKET 50-282, TYPE--PWR, HFG--WEST, AE--PIONEER SERV.

CAUSE - PERSONNEL OVERSIGHT. DURING POWER OPERATION, A BI-WEEKLY CONTROL ROD EXERCISE TEST WAS UNITED BECAUSE OF OVERSIGHT. PERSONNEL WERE REMINDED TO KEEP TESTS ON SCHEDULE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATION ERROR + TESTING + TEST, CONTROL ROD DRIVE + TEST INTERVAL + PRAIRIE ISLAND 1 (PWR) + CONTROL RODS

101456

TURBINE DRIVEN AUXILIARY FEEDWATER PUMP MALFUNCTIONS AT PRAIRIE ISLAND 1

NORTHERN STATES POWER COMPANY

1 PAGE. LETTER TO NRC DIVISION OF REACTOR LICENSING, APRIL 4, 1975. DOCKET 50-282, TYPE--PWR, HFG--WEST, AE--PIONEER SERV.

CAUSE - DIRTY GOVERNOR CONTROL VALVE LINKAGE. FOLLOWING A UNIT TRIP, A TURBINE DRIVEN AUXILIARY FEEDWATER PUMP FAILED TO REACH ACCEPTABLE DISCHARGE PRESSURE. THE GOVERNOR CONTROL VALVE LINKAGE WAS FOUND TO BE STICKY. THE LINKAGE WAS CLEANED AND FREED IMMEDIATELY. GOVERNOR CONTROL VALVES WILL BE ADDED TO THE PREVENTIVE MAINTENANCE PROGRAM.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

101420 CONTINUOUS
FAILURE, COMPONENT + CONTROL + CHAIN + FAILURE, MAINTENANCE ERROR + PRAIRIE ISLAND 1 (PWI) + FRESHWATER + PUMPS

101420
VENT RADIATION MONITORING SYSTEM INOPERABLE AT PRAIRIE ISLAND 1
NORTHERN STATES POWER COMPANY, MINN.
1 PAGE, LETTER TO NRC DIVISION OF REACTOR LICENSING, APRIL 16, 1975, DCKET 50-282, TYPE--PWR, MFG--WEST., AE--
PIONEER SERV.

CAUSE - FAULTY TRANSFORMER. DURING POWER OPERATION, A CHANNEL OF THE AUXILIARY BUILDING VENT
RADIATION MONITORING SYSTEM WAS FOUND INOPERABLE. THE SAMPLE PUMP MOTOR OVERLOAD RELAY WAS
FOUND TRIPPED. LOW FLOW ALARM WAS NOT RECEIVED DUE TO AN UNDERATED POWER SUPPLY TRANSFORMER.
THE TRANSFORMER WAS SMALLER THAN CALLED FOR IN THE ORIGINAL SPECIFICATIONS. LARGER
TRANSFORMERS WILL BE INSTALLED IN BOTH RADIATION MONITOR CABINETS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

VENTILATION SYSTEM + BUILDING + MONITORING SYSTEM, RADIATION + FAILURE, INSTALLATION ERROR + PRAIRIE ISLAND 1
(PWI) + RADIATION MONITORS + TRANSDUCERS

101440
SAFETY INJECTION INITIATION DURING SHUTDOWN AT PRAIRIE ISLAND 1
NORTHERN STATES POWER CO., MINNESOTA
2 PAGES, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, MAY 15, 1975, DCKETS 50-282/306, TYPE--
PWR, MFG--WEST., AE--PIONEER SERVICE

CAUSE - IMPROPER RELAY COIL. WHILE UNIT 1 WAS IN COLD SHUTDOWN, SAFETY INJECTION WAS ACTIVATED BY
LOW STEAM LINE PRESSURE. THE SI BLOCK RELAY HAD FAILED ALLOWING THE LOGIC TO MAKE UP. THE RELAY
HAD OPERATED CAUSING DISCOLORATION AND CRACKING OF THE COIL. THE WRONG STYLE COIL HAD BEEN
INSTALLED. THE FAILED RELAY WAS A REPLACEMENT FROM SPARE STOCK FOR THE ORIGINAL RELAY. THE
SPARE PARTS MANUAL SPECIFIED THE WRONG COIL. INVESTIGATION FOUND 8 IMPROPER COILS. THE CORRECT
COILS HAVE BEEN INSTALLED. THE MANUAL WAS REVISED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

PRAIRIE ISLAND 1 (PWI) + PRAIRIE ISLAND 2 (PWI) + RELAYS + SAFETY INJECTION + ENGINEERED SAFETY FEATURE +
FAILURE, DESIGN ERROR + PROCEDURES AND MANUALS + FAILURE, COMPONENT

102990
LOCAL LEAK RATE TESTS FAIL TO MEET LIMIT AT PRAIRIE ISLAND 1
NORTHERN STATES POWER COMPANY, MINN.
1 PAGE, LETTER TO NRC DIV. OF REACTOR LICENSING, MAY 16, 1975, DCKET 50-282, TYPE--PWR, MFG--WEST., AE--
PIONEER SERVICE

CAUSE - VALVE STOPS OUT OF ADJUSTMENT. DURING CONTAINMENT LOCAL LEAK TESTING CONDUCTED DURING THE
STEAM GENERATOR INSPECTION OUTAGE, THE AS FOUND LEAKAGE THROUGH 4 PENETRATIONS EXCEEDED LIMITS.
THE APPARENT CAUSE IN 3 INSTANCES WAS MALADJUSTMENT OF VALVE MECHANICAL STOPS AND A LOOSE PLUG
IN THE FOURTH CASE. THESE WERE ALL CORRECTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

PRAIRIE ISLAND 1 (PWI) + LEAK RATE + PENETRATIONS, PRIMARY CONTAINMENT + TEST, SYSTEM OPERABILITY + TEST,
LEAK RATE + FAILURE, MAINTENANCE ERROR

102909
SURVEILLANCE TEST PERFORMED LATE AT PRAIRIE ISLAND 1
NORTHERN STATES POWER COMPANY, MINN.
1 PAGE, LETTER TO NRC DIV. OF REACTOR LICENSING, MAY 19, 1975, DCKET 50-282, TYPE--PWR, MFG--WEST., AE--
PIONEER SERVICE

CAUSE - PERSONNEL ERROR. REVIEW OF THE SURVEILLANCE PROGRAM REVEALED THAT THE MONTHLY EMERGENCY
PLAN RADIATION INSTRUMENTS TEST WAS NOT PERFORMED WITHIN THE ACCEPTABLE TOLERANCE BAND. IT WAS
PERFORMED 1 1/2 DAYS LATE. THE CAUSE WAS PERSONNEL ERROR. THE IMPORTANCE OF ADHERING TO THE
SURVEILLANCE SCHEDULE WILL BE REEMPHASIZED. THE REACTOR WAS AT 100% POWER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

PRAIRIE ISLAND 1 (PWI) + TEST INTERVAL + INSTRUMENTS, MISC. + INSTRUMENT CALIBRATION + FAILURE,
ADMINISTRATIVE CONTROL

103115
LAPSE IN SECONDARY CONTAINMENT INTEGRITY AT PRAIRIE ISLAND 1
NORTHERN STATES POWER COMPANY, MINN.

103115 PLANTMANUP
1 PAGE, LETTER TO NRC DIV. OF REACTOR LICENSING, MAY 21, 1975, DOCKET 50-282, TYPE--PWR, NRC--WEST., AE--
PIONEER SERVICE

CAUSE - PROCEDURAL DEFICIENCY. DURING A UNIT HEATUP, AN OPERATOR DISCOVERED BOTH DOUBLE DOORS OF THE SHIELD BUILDING OPEN AT THE SAME TIME. THE DOORS WERE IMMEDIATELY CLOSED. THE DOORS DID NOT APPEAR ON THE PRE-HEATUP CHECKLIST. THEY WILL BE ADDED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RAIRIE ISLAND 1 (PWR) • CONTAINMENT INTEGRITY • PREACTOR STARTUP • FAILURE, ADMINISTRATIVE CONTROL • PROCEDURES AND MANUALS

103116
MAIN STEAM POWER OPERATED RELIEF VALVE FAILS TO OPEN AT PRAIRIE ISLAND 1
NORTHERN STATES POWER COMPANY, MINN.
1 PAGE, LETTER TO NRC DIV. OF REACTOR LICENSING, MAY 22, 1975, DOCKET 50-282, TYPE--PWR, NRC--WEST., AE--
PIONEER SERV.

CAUSE - VALVE OPERATOR AIR LEAKAGE. DURING HOT STANDBY OPERATION, A MAIN STEAM POWER OPERATED RELIEF VALVE FAILED TO OPEN ON DEMAND. THE CAUSE WAS AIR LEAKAGE AROUND THE VALVE OPERATOR. THE VALVE WAS REPAIRED AND RETURNED TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RAIRIE ISLAND 1 (PWR) • VALVES • OPRESSURE RELIEF • STEAM • MAIN COOLING SYSTEM • VALVE OPERATORS • LEAK • PNEUMATIC SYSTEM • FAILURE, EQUIPMENT

103045
VENTILATION EXHAUST FAN TRIPS ON OVERLOAD AT PRAIRIE ISLAND 1
NORTHERN STATES POWER COMPANY, MINN.
1 PAGE, LETTER TO NRC DIVISION OF REACTOR LICENSING, JUNE 10, 1975, DOCKET 50-282, TYPE--PWR, NRC--WEST., AE--
PIONEER SERVICE

CAUSE - INCORRECT SIZED OVERLOAD RELAYS. DURING A TEST WITH THE REACTOR AT 100% POWER, AN AUXILIARY BUILDING SPECIAL VENTILATION EXHAUST FAN TRIPPED ON OVERLOAD SHORTLY AFTER STARTING. THE THERMAL OVERLOAD PROTECTION RELAYS FOR THE FAN MOTOR APPEAR TO BE INCORRECTLY SIZED AND HAVE BEEN RESET TO 315%. RELAYS FOR BOTH FANS WILL BE REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RAIRIE ISLAND 1 (PWR) • PUMPS • VENTILATION SYSTEM • BUILDING • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT • INSTRUMENT, PROTECTIVE • RELAYS • FAILURE, INSTALLATION ERROR

103043
AUXILIARY BUILDING VENTILATION EXHAUST FAN FAILS AT PRAIRIE ISLAND 1
NORTHERN STATES POWER COMPANY, MINN.
1 PAGE, LETTER TO NRC DIVISION OF REACTOR LICENSING, JULY 3, 1975, DOCKET 50-282, TYPE--PWR, NRC--WEST., AE--
PIONEER SERVICE

CAUSE - UNDERSIZED THERMAL OVERLOAD. DURING A TEST WITH THE REACTOR AT FULL POWER, AUXILIARY BUILDING SPECIAL VENTILATION EXHAUST FAN 121 TRIPPED SHORTLY AFTER STARTING. THERMAL OVERLOAD PROTECTION RELAYS HAVE BEEN REPLACED. AN INCORRECT SIZE OF THERMAL OVERLOAD PROTECTION RELAYS HAD BEEN USED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RAIRIE ISLAND 1 (PWR) • PUMPS • VENTILATION SYSTEM • FAILURE, DESIGN ERROR • INSTRUMENT, PROTECTIVE • MODIFICATION • TEST, SYSTEM OPERABILITY

103002
UNPLANNED RELEASE OF LIQUID WASTE AT PRAIRIE ISLAND 1
NORTHERN STATES POWER COMPANY, MINN.
1 PAGE, LETTER TO NRC DIVISION OF REACTOR LICENSING, JULY 3, 1975, DOCKET 50-282, TYPE--PWR, NRC--WEST., AE--
PIONEER SERVICE

CAUSE - PROCEDURAL DEFICIENCY. DURING THE PLANNED RELEASE OF ADT MONITOR TANK 121 WITH ADT MONITOR TANK 122 ON RECYLE, 90% OF THE CONTENTS OF TANK 122 WERE INADVERTENTLY RELEASED AFTER PASSING THROUGH THE DEMINERALIZER TRAIN AND ENTERING TANK 121 THROUGH THE TANK INLET VALVE. PROCEDURAL DEFICIENCY ALLOWED THE INLET VALVE TO TANK 121 TO BE OPEN DURING THE RELEASE. PROCEDURES WILL BE REVISED. THERE WAS 0.77 G OF H-3 RELEASED. THE REACTOR WAS OPERATING AT FULL POWER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

103902 *CONTINUED*
 PRAIRIE ISLAND 1 (PHR) • MAINTENANCE RELEASE • WASTE DISPOSAL • WASTE DISPOSAL, LEAK • FAILURE,
 ADMINISTRATIVE CONTROL • PROCEDURES AND MANUALS • LITIGATION

104004
 LEAK FOUND IN RHM SYSTEM AT PRAIRIE ISLAND 1
 NORTHERN STATES POWER COMPANY, MINN.
 1 PG. LETTER TO NRC DIVISION OF REACTOR LICENSING, JULY 7, 1975, DOCKET 50-202, TYPE--PHR, NRC--WEST., AE--
 PIONEER SERVICE

CAUSE - UNKNOWN. DURING A HOT SHUTDOWN, LEAKAGE WAS NOTED IN A 3/4 IN. RHM SYSTEM LINE WHERE A
 CHECK VALVE IS MOUNTED. THE TRAIN WAS ISOLATED AND THE LEAK REPAIRED. THE CRACKED PORTION WAS
 REPLACED AND A PIPE HANGER ADDED. THE CAUSE OF THE BREAK IS UNKNOWN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

PRAIRIE ISLAND 1 (PHR) • PIPES AND PIPE FITTINGS • LEAK • SHUTDOWN COOLING SYSTEM • FAILURE, PIPE •
 MODIFICATION • SUPPORT STRUCTURE

104005
 REACTOR COOLANT PUMP SEAL INJECTION LINE LEAKS AT PRAIRIE ISLAND 1
 NORTHERN STATES POWER COMPANY, MINN.
 1 PG. LETTER TO NRC DIVISION OF REACTOR LICENSING, JULY 7, 1975, DOCKET 50-202, TYPE--PHR, NRC--WEST., AE--
 PIONEER SERVICE

CAUSE - UNKNOWN. DURING FULL POWER OPERATION, LEAKAGE WAS NOTICED FROM REACTOR COOLANT PUMP 12
 SEAL INJECTION LINE. A CRACKED PORTION WAS REPLACED USING HEAVIER PIPE AND A PIPE HANGER WAS
 ADDED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

PRAIRIE ISLAND 1 (PHR) • PIPES AND PIPE FITTINGS • LEAK • FAILURE, PIPE • PUMPS • SEAL • MODIFICATION •
 SUPPORT STRUCTURE

105275
 REACTOR COOLANT PUMP SEAL INJECTION LEAK FOUND AT PRAIRIE ISLAND 1
 NORTHERN STATES POWER COMPANY, MINN.
 1 PG. LTR TO NRC DIV. OF REACTOR LICENSING, AUG. 19, 1975, DOCKET 50-202, TYPE--PHR, NRC--WEST., AE--PIONEER
 SERVICE

CAUSE - UNKNOWN. DURING A HOT SHUTDOWN, LEAKAGE WAS DISCOVERED FROM A REACTOR COOLANT PUMP SEAL
 INJECTION THROUGH A CRACKED WELD. LEAKAGE WAS ABOUT 0.005 GPM. THE WELD WAS REPAIRED.
 METALLURGICAL EXAMINATION IS PLANNED TO DETERMINE THE CAUSE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

PRAIRIE ISLAND 1 (PHR) • PUMPS • LEAK • SEAL • PUMPS • PIPES AND PIPE FITTINGS

105529
 CONTAINMENT PENETRATION FLANGE NOT INSTALLED AT PRAIRIE ISLAND 1
 NORTHERN STATES POWER COMPANY, MINN.
 1 PG. LTR TO NRC DIV. OF REACTOR LICENSING, AUG. 28, 1975, DOCKET 50-202, TYPE--PHR, NRC--WEST., AE--PIONEER
 SERVICE

CAUSE - COMMUNICATION BREAKDOWN. DURING A STARTUP, THE REACTOR WAS RETURNED TO POWER WITH THE
 EXTERIOR BLIND FLANGE NOT INSTALLED ON THE CONTAINMENT DEMINERALIZED WATER PENETRATION. UPON
 DISCOVERY, THE FLANGE WAS IMMEDIATELY INSTALLED. THE INNER FLANGE WAS IN PLACE. THE CAUSE WAS A
 COMMUNICATION BREAKDOWN BETWEEN THE LEAK TEST MAN AND WORKMAN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

PRAIRIE ISLAND 1 (PHR) • FLANGE • CONTAINMENT INTEGRITY • PENETRATIONS, PRIMARY CONTAINMENT • CONTAINMENT
 PENETRATION, PIPE • FAILURE, MAINTENANCE ERROR • COMMUNICATION

105716
 AIRLOCK INNER DOOR AND EQUALIZING VALVE OPENED SIMULTANEOUSLY AT PRAIRIE ISLAND 1
 NORTHERN STATES POWER COMPANY, MINN.
 1 PG. LTR TO NRC DIV. OF REACTOR LICENSING, SEPT. 4, 1975, DOCKET 50-202, TYPE--PHR, NRC--WEST., AE--PIONEER
 SERVICE

CAUSE - LATCH MALFUNCTION. WHILE THE UNIT WAS OPERATING AT 248 POWER, THE CONTAINMENT MAINTENANCE
 AIRLOCK EQUALIZING VALVE WAS OPENED TO THE SHIELD BUILDING FOR 5 MINUTES WHILE THE INNER DOOR WAS
 OPEN. THIS VIOLATED CONTAINMENT INTEGRITY. THE LATCHING MECHANISM FAILED TO CATCH AND CLOSE THE

105716 ALCOHOLIC

INNER LOCK BUT ALLOWED THE INTERLOCK SWITCH TO MAKE UP THUS ALLOWING THE EQUALIZING VALVE TO BE OPENED. THE LATCHING MECHANISM WILL BE ADJUSTED. A MODIFICATION IS UNDER CONSIDERATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PRairie Island 1 (PHN) + CONTAINMENT INTEGRITY + CONTAINMENT AIR LOCK + VALVES + FAILURE, MAINTENANCE ERROR + INSTRUMENT, INTERLOCK

106313

UNPLANNED RELEASE OF RADIOACTIVE LIQUID OCCURS AT PRAIRIE ISLAND 1

NORTHERN STATES POWER CO., MINN.

3 PGS. LTR W/ SUPPL. TO HQ 75-31 TO NRC DIVISION OF REACTOR LICENSING, SEPT. 5, 1975. DOCKET 50-202, TYPE--PHN, NPG--WEST., AE--PIONEER SERVICE

CAUSE - WASTE EVAPORATOR TUBE LEAKAGE. AN UNCONTROLLED AND UNPLANNED RELEASE OF RADIOACTIVE LIQUID OCCURRED WHILE CHEMICALLY CLEANING THE 5 GPM WASTE EVAPORATOR DUE TO RADIOACTIVE WASTE LEAKING THROUGH THE STEAM BUNDLE TUBES INTO THE HEATING SYSTEM CONDENSATE RETURN HEADER. THE MAXIMUM POSSIBLE RELEASE WAS CALCULATED TO BE 0.30 CI. THE PROBABLE RELEASE WAS 0.130 CI. TWENTY-THREE TUBES WERE FOUND TO BE LEAKING AND WERE PLUGGED. LEAKAGE IN 4 WAS FROM OVERROLLING WHEN THE BUNDLE WAS RETURNED APRIL 27, 1975. CORROSION WAS THE CAUSE FOR THE OTHER LEAKS. A NEW TUBE BUNDLE OF INCONEL WILL BE INSTALLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PRairie Island 1 (PHN) + RADIOACTIVITY RELEASE + LEAK + WASTE TREATMENT EQUIPMENT + FAILURE, TUBING + CORROSION + FAILURE, DESIGN ERROR + MODIFICATION + HEAT EXCHANGERS

105719

INTERMEDIATE RANGE NUCLEAR INSTRUMENTATION TRIP SET POINTS DRIFT AT PRAIRIE ISLAND 1

NORTHERN STATES POWER COMPANY, MINN.

1 PG. LTR TO NRC DIV. OF REACTOR LICENSING, SEPT. 5, 1975. DOCKET 50-202, TYPE--PHN, NPG--WEST., AE--PIONEER SERVICE

CAUSE - UNKNOWN. DURING A START-UP, HIGH INTERMEDIATE RANGE HIGH FLUX REACTOR TRIP SET POINTS WERE OBSERVED TO TRIP AT ABOUT 300 POWER VERSUS TECH SPEC LIMIT OF 250. THE CAUSE IS UNKNOWN. SET POINTS WERE READJUSTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PRairie Island 1 (PHN) + INSTRUMENT, SWITCH + INSTRUMENT CALIBRATION + INSTRUMENT, INTERMEDIATE RANGE + FAILURE, INSTRUMENT + SET POINT + DRIFT

105718

POWER RANGE NUCLEAR INSTRUMENTATION CHANNEL FAILS AT PRAIRIE ISLAND 1

NORTHERN STATES POWER COMPANY, MINN.

1 PG. LTR TO NRC DIV. OF REACTOR LICENSING, SEPT. 5, 1975. DOCKET 50-202, TYPE--PHN, NPG--WEST., AE--PIONEER SERVICE

CAUSE - POWER SUPPLY FAILED. DURING FULL POWER OPERATION, NUCLEAR INSTRUMENTATION POWER RANGE CHANNEL IN-01 FAILED. THE LOW VOLTAGE POWER SUPPLY FAILED. THE ENTIRE POWER SUPPLY WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PRairie Island 1 (PHN) + INSTRUMENT, POWER RANGE + ELECTRIC POWER + FAILURE, INSTRUMENT + REACTOR SAFETY SYSTEM

105717

AUXILIARY FEEDWATER PUMP PLACED IN MANUAL CONTROL AT PRAIRIE ISLAND 1

NORTHERN STATES POWER COMPANY, MINN.

1 PG. LTR TO NRC DIV. OF REACTOR LICENSING, SEPT. 5, 1975. DOCKET 50-202, TYPE--PHN, NPG--WEST., AE--PIONEER SERV.

CAUSE - DEFECTIVE PROCEDURES. DURING OPERATION AT FULL POWER, THE CONTROL SWITCH FOR THE MOTOR-DRIVEN AUXILIARY FEEDWATER PUMP WAS PLACED FROM AUTO TO MANUAL DURING A TEST WHILE THE OPPOSITE TRAIL DIESEL GENERATOR WAS OUT OF SERVICE FOR MAINTENANCE. THE CONTROL ROOM OPERATOR WAS AWARE THAT MANUAL ACTION WAS REQUIRED IF THE PUMP WERE NEEDED. THE PROCEDURES WERE DEFECTIVE THAT REQUIRED THIS. THEY WILL BE REVISED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PRairie Island 1 (PHN) + CONTROL + PUMPS + FEEDWATER + FAILURE, ADMINISTRATIVE CONTROL + PROCEDURES AND MANUALS + TEST, SYSTEM OPERABILITY

102606

AIRLOCK INNER DOOR AND EQUALIZING VALVE OPEN SIMULTANEOUSLY AT PRAIRIE ISLAND 1
NORTHERN STATES POWER CO., MINN.
2 PGS. LTR W/RT TO NRC DIVISION OF REACTOR LICENSING, SEPT. 26, 1975, DOCKET 50-282, TYPE--PWR, NRG--WEST., AE--PIONEER SERVICE

CAUSE - DEFECTIVE LATCHING MECHANISM. THE CONTAINMENT MAINTENANCE AIRLOCK EQUALIZING VALVE WAS OPENED TO THE SHIELD BUILDING FOR ABOUT 30 SECONDS AT THE SAME TIME THAT THE INNER DOOR WAS OPEN PROVIDING A PATH FROM CONTAINMENT TO THE BUILDING WHILE THE REACTOR WAS AT FULL POWER. THE LATCHING MECHANISM WAS IMPROPERLY ADJUSTED. CORRECTIVE ACTION INITIATED FOLLOWING A SIMILAR EVENT ON AUG. 21 HAD NOT BEEN COMPLETED AT THE TIME OF THIS EVENT. THE LATCHING MECHANISM HAS NOW BEEN ADJUSTED. A DOOR SEAL LEAKAGE TEST WILL BE ADDED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PRAIRIE ISLAND 1 (PWR) + CONTAINMENT INTEGRITY + FAILURE, MAINTENANCE ERROR + INSTRUMENT, INTERLOCK + CONTAINMENT AIR LOCK

100526

CONTAINMENT FAN COIL DAMPER FAILS AT PRAIRIE ISLAND 1
NORTHERN STATES POWER CO., MINN.
2 PGS. LTR W/RT TO NRC DIV. OF REACTOR LICENSING, SEPT. 29, 1975, DOCKET 50-282, TYPE--PWR, NRG--WEST., AE--PIONEER SERVICE

CAUSE - BROKEN YOKER DRIVE. DURING TESTING WITH THE REACTOR AT FULL POWER, A CONTAINMENT FAN COIL DAMPER IMPROPER POSITION WAS INDICATED. THE CONTAINMENT FAN COIL DOME DISCHARGE DAMPER WAS IN THE MID-POSITION AND COULD NOT BE OPERATED REMOTELY. ONE ACTUATOR WAS FOUND WITH A BROKEN YOKER DRIVE. THE OTHER WAS BINDING APPARENTLY FROM LACK OF LUBRICATION. THE BROKEN YOKER DRIVE WAS REPLACED AND THE OTHER WAS LUBRICATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PRAIRIE ISLAND 1 (PWR) + CONTAINMENT AIR COOLING + ACTUATOR + BLOWERS + FAILURE, EQUIPMENT + FAILURE, MAINTENANCE ERROR + LUBRICATION + TEST, SYSTEM OPERABILITY

100996

DIESEL GENERATOR BEARING F. 5 AT PRAIRIE ISLAND 1
NORTHERN STATES POWER CO., MINNEAPOLIS, MINN.
2 PGS. LTR W/RT TO NRC DIVISION OF REACTOR LICENSING, OCT. 13, 1975, DOCKET 50-282, TYPE--PWR, NRG--WEST., AE--PIONEER SERVICE

CAUSE - UNKNOWN. DURING A TEST WITH THE REACTOR AT 100% POWER, DIESEL GENERATOR DR WAS TRIPPED MANUALLY DUE TO FAILURE OF THE GENERATOR BEARING. AFTER BEARING REPLACEMENT, THE DIESEL GENERATOR WAS RETURNED TO SERVICE. THE CAUSE OF FAILURE HAS NOT YET BEEN DETERMINED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PRAIRIE ISLAND 1 (PWR) + BEARING + GENERATOR, DIESEL + ENGINES, INTERNAL COMBUSTION + TEST, SYSTEM OPERABILITY + FAILURE, COMPONENT

107609

LEAK PROTECTION FOR RHR PITS INADEQUATE AT PRAIRIE ISLAND 1
NORTHERN STATES POWER CO., MINNEAPOLIS, MINN.
4 PGS. LTR W/RT 75-1 TO NRC DIVISION OF REACTOR LICENSING, OCT. 20, 1975, DOCKET 50-282, TYPE--PWR, NRG--WEST., AE--PIONEER SERVICE

CAUSE - INITIAL DESIGN DEFICIENCY. DURING AN INVESTIGATION, IT WAS FOUND THAT THE RESIDUAL HEAT REMOVAL PITS WERE NOT ADEQUATELY SEALED AGAINST CROSS LEAKAGE AND INLEAKAGE. THE DESIGN WAS DEFICIENT. MODIFICATIONS WILL BE MADE TO PROTECT THE PITS. ELECTRICAL JUNCTION BOXES WILL BE SEALED TO PREVENT SHORTING OUT DUE TO HIGH WATER LEVEL. SHIELDS WILL BE INSTALLED OVER ALL PENETRATIONS INTERCONNECTING THE 2 PITS TO PREVENT LOSS OF BOTH TRAINS DUE TO A LARGE LEAK IN ONE PIT. THE VENTILATION DUCT FROM THE CONTAINMENT SPRAY PUMP ROOM TO THE RHR PIT WILL BE RAISED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PRAIRIE ISLAND 1 (PWR) + COMPARTMENT + PUMPS + SHUTDOWN COOLING SYSTEM + FLOOD + FAILURE, DESIGN ERROR + INDEPENDENCE + MODIFICATION + REDUNDANCE + REVIEW

107513

STEAM GENERATOR BLINDING VALVE FAILS TO CLOSE AT PRAIRIE ISLAND 1
NORTHERN STATES POWER CO., MINNEAPOLIS, MINN.
2 PGS. LTR W/RT 75-40 TO NRC DIVISION OF REACTOR LICENSING, OCT. 23, 1975, DOCKET 50-282, TYPE--PWR, NRG--WEST., AE--PIONEER SERVICE

107513 CONTINUOUS

CAUSE - DEFECTIVE TORQUE SWITCH. WITH THE REACTOR IN SHUTDOWN, STEAM GENERATOR 11 BLOWDOWN ISOLATION VALVE WOULD NOT CLOSE REMOTELY ON DEMAND. THE TORQUE SWITCH IN THE VALVE OPERATOR WAS DEFECTIVE. AFTER THE SWITCH WAS REPLACED, THE VALVE TESTED SUCCESSFULLY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RAIRIE ISLAND 1 (PWR) • VALVES • CONTAINMENT ISOLATION • STEAM GENERATOR • BLOWDOWN • COOLANT PURIFICATION SYSTEM • FAILURE, EQUIPMENT • INSTRUMENT, SWITCH • VALVE OPERATORS

108527

SET POINT UNIT IN TEMPERATURE DIFFERENTIAL SWITCH AT PRAIRIE ISLAND 1

NORTHERN STATES POWER CO., MINNEAPOLIS, MINN.

2 PGS. LTR W/AD 75-62 TO NRC DIVISION OF REACTOR LICENSING, DEC. 4, 1975, DOCKET 50-306, TYPE--PWR, NRC--WEST., AE--PIONEER SERV.

CAUSE - INSTRUMENT DRIFT. DURING TESTING WITH THE UNIT OPERATING AT 103% POWER, AN OVERPOWER DIFFERENTIAL TEMPERATURE SET POINT WAS FOUND SLIGHTLY OUTSIDE THE LIMIT. THE CAUSE WAS INSTRUMENT DRIFT. THE CHANNEL WAS RECALIBRATED. ALSO, AN IMPULSE LOG UNIT RESPONDED IMPROPERLY. IT WAS REPAIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RAIRIE ISLAND 1 (PWR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SENSORS, TEMPERATURE • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT • SET POINT • DRIFT • REACTOR SAFETY SYSTEM • INSTRUMENT, LOGARITHMIC

108541

STEAM EXCLUSION DAMPER FOUND INOPERABLE AT PRAIRIE ISLAND 1

NORTHERN STATES POWER CO., MINNEAPOLIS, MINN.

2 PGS. LTR W/AD 75-63 TO NRC DIVISION OF REACTOR LICENSING, DEC. 5, 1975, DOCKET 50-306, TYPE--PWR, NRC--WEST., AE--PIONEER SERV.

CAUSE - IMPROPER TRAVEL ADJUSTMENT. DURING A STEAM EXCLUSION DAMPER INSPECTION TEST WITH THE UNIT AT FULL POWER, 2 BLADES OF A 5-BLADE DAMPER IN THE SUPPLY DUCT TO THE BATTERY ROOMS WERE FOUND INOPERABLE. THEY WERE DISENGAGED FROM THE ACTUATING ARM. THE CAUSE WAS IMPROPER TRAVEL ADJUSTMENT. THE DAMPER WAS REPAIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RAIRIE ISLAND 1 (PWR) • VENTILATION SYSTEM • TEST, SYSTEM OPERABILITY • FAILURE, COMPONENT • COMPARTMENT • BATTERIES & CHARGERS • FAILURE, MAINTENANCE ERROR

109289

FLUX DIFFERENCE ALARM OUT OF SERVICE AT PRAIRIE ISLAND 1

NORTHERN STATES POWER CO., MINNEAPOLIS, MN

2 PGS. LTR W/AD 75-64 TO NRC DIVISION OF REACTOR LICENSING, DEC. 19, 1975, DOCKET 50-282, TYPE--PWR, NRC--WEST., AE--PIONEER SERVICE

CAUSE - DEFECTIVE PROCEDURE. AFTER REPLACEMENT OF HIS POWER RANGE DETECTOR RM, RECALIBRATION OF THE CHANNEL TOOK PLACE DURING POWER OPERATION OVER THE NEXT 3 DAYS. DURING CALIBRATION, INPUT FROM THE CHANNEL TO THE FLUX DIFFERENCE ALARM WAS UNRELIABLE AND THE ALARM CONSIDERED TO BE OUT OF SERVICE. HALF HOUR LOGGING OF FLUX DIFFERENCE WAS NOT DONE BECAUSE IT WAS NOT REQUIRED BY OPERATING PROCEDURE. PROCEDURE WILL BE REVISED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RAIRIE ISLAND 1 (PWR) • ANNUNCIATORS • FLUX DISTRIBUTION • FLUX TILT • FAILURE, ADMINISTRATIVE CONTROL • PROCEDURES AND MANUALS • INSTRUMENT CALIBRATION • INSTRUMENT, POWER RANGE

109288

LOGGING TOWER BLOWDOWN RATE SLIGHTLY EXCEEDS LIMIT AT PRAIRIE ISLAND 1 AND 2

NORTHERN STATES POWER CO., MINNEAPOLIS, MN

1 PG. LTR W/ENV, EVENT RPT 75-12 TO NRC OFFICE OF I & E, REGION III, DEC. 31, 1975, DOCKETS 50-282/306, TYPE--PWR, NRC--WEST., AE--PIONEER SERVICE

CAUSE - MAINTENANCE ACTIVITIES. ON TWO DAYS, THE BLOWDOWN FLOW AVERAGED 155 AND 152 CFS WHICH SLIGHTLY EXCEEDS THE 150 CFS LIMIT. THIS BECAME NECESSARY TO MAINTAIN TEMPERATURE LIMITATIONS BECAUSE COOLING TOWERS WERE SEQUENTIALLY REMOVED FROM SERVICE FOR MAINTENANCE AND REPAIR.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RAIRIE ISLAND 1 (PWR) • PRAIRIE ISLAND 2 (PWR) • RATE • BLOWDOWN • COOLING TOWER • MAINTENANCE AND REPAIR • EFFLUENT

099111

LAPSE IN CONTAINMENT INTEGRITY AT PRAIRIE ISLAND 2
NORTHERN STATES POWER COMPANY, MINN.
1 PAGE, LETTER TO DIRECTORATE OF LICENSING (AEC), JANUARY 13, 1975, DOCKET 50-306, TYPE--PWR, MFC--WEST., AE--
PIONEER SERV.

CAUSE - CRUD IN CHECK VALVE. AFTER INCREASING THE PRESSURE IN THE REACTOR COOLANT ACCUMULATORS, THE NITROGEN SUPPLY ISOLATION CHECK VALVE COULD NOT BE FULLY CLOSED FROM THE CONTROL ROOM. POUNDANT VALVES WERE CLOSED. A FOREIGN PIECE OF METAL PREVENTED COMPLETE CLOSURE. IT WAS REMOVED AND THE VALVE TESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTAINMENT ISOLATION + CONTAINMENT INTEGRITY + CRUD + PRAIRIE ISLAND 2 (PWR) + VALVE, CHECK + ACCUMULATORS

100425

LETOURNEAU HEAT EXCHANGER TUBE FAILURE AT PRAIRIE ISLAND 2
NORTHERN STATES POWER COMPANY, MINN.
1 PAGE, LETTER TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, FEBRUARY 21, 1975, DOCKET 50-306, TYPE--
PWR, MFC--WEST., AE--PIONEER SERV.

CAUSE - DESIGN ERROR. WHILE THE REACTOR WAS IN HOT SHUTDOWN, IT WAS NOTED THAT AN UNUSUAL AMOUNT OF PRIMARY SYSTEM MAKEUP WAS BEING REQUIRED AND THE COMPONENT COOLING SURGE TANK LEVEL WAS INCREASING. THE LETOURNEAU HEAT EXCHANGER WAS ISOLATED. A TUBE IN THE OUTLET PASS WAS FOUND SNAPPED OFF AT THE TOP BAFFLE PLATE. THE FAILED TUBE WAS PLUGGED AT BOTH ENDS. STAINLESS STEEL BANDS WERE INSTALLED AROUND THE TUBE BUNDLE AT THE DIRECTION OF THE VENDOR TO PREVENT RECURRENCE. THERE WAS NO CONTAMINATION SINCE THE FUEL HAD NOT BEEN IRRADIATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MODIFICATION + REACTOR STARTUP EXPERIENCE + FAILURE, DESIGN ERROR + COOLANT PURIFICATION SYSTEM + MAIN COOLING SYSTEM + FAILURE, TUBING + TUBING + PRAIRIE ISLAND 2 (PWR) + HEAT EXCHANGERS

100426

REACTOR COOLANT PUMP SEAL WATER RETURN LINE LEAKS AT PRAIRIE ISLAND 2
NORTHERN STATES POWER COMPANY, MINN.
1 PAGE, LETTER TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, FEBRUARY 24, 1975, DOCKET 50-306, TYPE--
PWR, MFC--WEST., AE--PIONEER SERV.

CAUSE - UNKNOWN. WHILE THE UNIT WAS IN HOT SHUTDOWN, A LEAK WAS FOUND IN THE REACTOR COOLANT PUMP SEAL WATER RETURN LINE BETWEEN THE FILTER AND HEAT EXCHANGER. THE LEAK WAS WHERE THE PIPE WAS WELDED TO ITS ANCHOR PLATE. THE LEAKING SECTION WAS REMOVED AND A TEMPORARY HOSE WAS RUN. A NEW SECTION WAS INSTALLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, PIPE + REACTOR STARTUP EXPERIENCE + SEAL + LEAK + COOLING + PRAIRIE ISLAND 2 (PWR) + PIPES AND PIPE FITTINGS

100427

PRESSURIZER LIQUID SAMPLE LINE LEAKS AT PRAIRIE ISLAND 2
NORTHERN STATES POWER COMPANY, MINN.
1 PAGE, LETTER TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, MARCH 4, 1975, DOCKET 50-306, TYPE--PWR,
MFC--WEST., AE--PIONEER SERV.

CAUSE - CONSTRUCTION ERROR. LEAKAGE WAS OBSERVED FROM THE PRESSURIZER LIQUID SAMPLE LINE IN THE AUXILIARY BUILDING. THE LINE WAS ISOLATED AT THE TIME. NO CONTAMINATION RESULTED SINCE THE FUEL HAD NOT BEEN IRRADIATED. AN EMP SIZED WELDING CABLE HAD BEEN DRAPED OVER THE PRESSURIZER LIQUID SAMPLE LINE BEFORE THE PRIMARY PLANT WAS HOT. AFTER HEATUP WHEN SAMPLES WERE DRAWN THROUGH THE LINE, THE INSULATION ON THE CABLE MELTED. THE CABLE SHORTED TO THE SAMPLE LINE MELTING THE TUBING. THE TUBING WAS REPLACED. THE PLANT WAS INSPECTED FOR OTHER CABLES ACROSS HOT LINES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, PIPE + SAMPLING + REACTOR STARTUP EXPERIENCE + ELECTRIC ARC + FAILURE, INSTALLATION ERROR + LEAK + PRAIRIE ISLAND 2 (PWR) + PIPES AND PIPE FITTINGS

102100

SETPPOINT DRIFT IN LEVEL AND FLOW SWITCHES AT PRAIRIE ISLAND 2
NORTHERN STATES POWER COMPANY, MINN.
1 PAGE, LETTER TO NRC DIVISION OF REACTOR LICENSING, APRIL 9, 1975, DOCKET 50-306, TYPE--PWR, MFC--WEST., AE--
PIONEER SERV.

CAUSE - INSTRUMENT DRIFT. DURING POWER OPERATION, TESTING FOUND A LOW REACTOR COOLANT FLOW SWITCH

102166 CONTINUOUS

WITH A SETPOINT OF 49.58 (LIMIT OF 934) AND A PRESSURIZED LOW LEVEL SAFETY INJECTION SETPOINT OF 48 (LIMIT OF 58). BOTH INSTRUMENTS WERE IMMEDIATELY RECALIBRATED. THE APPARENT CAUSE OF BOTH WAS INSTRUMENT DRIFT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

REACTOR SAFETY SYSTEM + SAFETY INJECTION + INSTRUMENT CALIBRATION + FAILURE, INSTRUMENT + INSTRUMENT, SWITCH + TEST, SYSTEM OPERABILITY + SET POINT + PRAIRIE ISLAND 2 (PIM) + DRIFT + SENSORS, FLOW + SENSORS, LEVEL

102165

ACS LEAKAGE EVALUATION NOT PERFORMED ONE DAY AT PRAIRIE ISLAND 2
NORTHMAN STATES PUMER COMPANY, MINN.

1 PAGE, LETTER TO NRC DIVISION OF REACTOR LICENSING, APRIL 10, 1975, DOCKET 50-306, TYPE--PUR, NRC--WEST., AE--PUMER SERV.

CAUSE - OPERATION ERROR. A REVIEW OF THE SURVEILLANCE PROGRAM INDICATED THAT THE DAILY REACTOR COOLANT SYSTEM LEAKAGE EVALUATION WAS NOT PERFORMED ONE DAY. SATISFACTORY LEAKAGE RATES WERE INDICATED BEFORE AND AFTER THIS DAY. INTERVIEWS WITH PERSONNEL INDICATED THAT THE TEST WAS BEGUN BUT NOT COMPLETED. PERSONNEL WERE WARNED OF THE IMPORTANCE OF PERFORMING SURVEILLANCE ON SCHEDULE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATION ERROR + TESTING + CONTAINMENT LEAKAGE CONTROL + MAIN COOLING SYSTEM + TEST INTERVAL + LEAK RATE + PRAIRIE ISLAND 2 (PIM)

103000

FINAL REPORT ON THERMAL BARRIER HEAT EXCHANGER LEAKAGE AT PRAIRIE ISLAND 2
NORTHMAN STATES PUMER COMPANY, MINN.

2 PAGES, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, MAY 6, 1975, DOCKET 50-306, TYPE--PUR, NRC--WEST., AE--PUMER SERVICE

CAUSE - IMPROPER WELD. THE REACTOR COOLANT PUMP HEAT EXCHANGER, INTEGRAL WITH THE THERMAL BARRIER, LEAKED DURING HYDROSTATIC TESTING. THE LEAK OCCURRED AT AN IMPROPERLY CONSTRUCTED WELD JOINING THE SPACER, HEADER, AND OUTER COIL SHELL. MISMATCH AT THE WELD JOINT CAUSED THE OUTER COIL SHELL TO OVERLAP THE ROOT PASS OF THE SPACER-HEADER WELD. THE 3000 PSI HYDROSTATIC TEST WAS IN AN OPPOSITE DIRECTION FROM WHICH THE THERMAL BARRIER HEAT EXCHANGER WAS DESIGNED. A MINIMUM ROOT GAP WAS SPECIFIED TO PREVENT RECURRENCE. TEST PRESSURE WILL BE LIMITED TO 1.5 TIMES THE COOLING WATER SYSTEM DESIGN OF 15 PSI.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PRAIRIE ISLAND 2 (PIM) + HEAT EXCHANGERS + WELDS + PUMPS + MAIN COOLING SYSTEM + LEAK + FAILURE, FABRICATION ERROR + TEST, PUMP

102924

CONTAINMENT VACUUM BREAKER INOPERABLE AT PRAIRIE ISLAND 2
NORTHMAN STATES PUMER COMPANY, MINN.

1 PAGE, LETTER TO NRC DIVISION OF REACTOR LICENSING, MAY 9, 1975, DOCKET 50-306, TYPE--PUR, NRC--WEST., AE--PUMER SERV.

CAUSE - SENSING LINE CAPPED. DURING A TEST, A CONTAINMENT VACUUM BREAKER ISOLATION VALVE FAILED TO CLOSE ON DEMAND. THE DIFFERENTIAL PRESSURE SWITCH ERRONEOUSLY SENSED CONTAINMENT VACUUM AND HELD THE ISOLATION VALVE OPEN. A CAP WAS INADVERTENTLY LEFT ON THE SENSING LINE, APPARENTLY FROM THE CONSTRUCTION ERA. WHEN THE CAP WAS REMOVED, THE VALVE WAS TESTED SATISFACTORILY. ALL SIMILAR LINES WILL BE INSPECTED FOR CAPS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PRAIRIE ISLAND 2 (PIM) + CONTAINMENT VACUUM BREAKER + FAILURE, INSTALLATION ERROR + OBSTRUCTION + CONTROL SYSTEM + TEST, SYSTEM OPERABILITY + REACTOR STARTUP EXPERIENCE

103070

SET POINT DRIFT IN UNDERFREQUENCY RELAY AT PRAIRIE ISLAND 2
NORTHMAN STATES PUMER COMPANY, MINN.

1 PAGE, LETTER TO NRC DIVISION OF REACTOR LICENSING, JUNE 20, 1975, DOCKET 50-306, TYPE--PUR, NRC--WEST., AE--PUMER SERV.

CAUSE - INSTRUMENT DRIFT. DURING SURVEILLANCE TESTING WITH THE UNIT AT COLD SHUTDOWN, A RCP BUS UNDERFREQUENCY RELAY WAS FOUND TO TRIP AT 50.19 HZ. THIS IS BELOW THE 50.2 HZ LIMIT. THE RELAY WAS IMMEDIATELY RECALIBRATED. THE APPARENT CAUSE WAS DRIFT IN THE WASHINGTON TYPE RF RELAY, STYLE 6750207A09.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM

103670 CONTINUED
CHARGE \$2.00

PRAIRIE ISLAND 2 (PWR) • DELAYS • INSTRUMENT CALIBRATION • INSTRUMENT, PROTECTIVE • TEST, SYSTEM OPERABILITY
• FAILURE, INSTRUMENT • RESET POINT • RESET • REACTOR SAFETY SYSTEM • INSTRUMENT, SWITCH

104073
OVER-TEMPERATURE DELTA T TRIP SETTING IMPROPER AT PRAIRIE ISLAND 2
NORTHERN STATES POWER COMPANY, MINN.
1 PG., LTR TO NRC DIVISION OF REACTOR LICENSING, JULY 11, 1975, DOCKET 50-306, TYPE--PWR, NRC--WEST., AE--PIONEER SERVICE

CAUSE - PERSONNEL ERROR. DURING SURVEILLANCE TEST AT HOT SHUTDOWN, AN OVER-TEMPERATURE DELTA T REACTOR TRIP SET POINT WAS FOUND 5.98 POWER HIGH. THE CAUSE WAS PERSONNEL ERROR IN RECENT CALIBRATION. THE CHANNEL WAS RECALIBRATED. THE EMPLOYEE WAS REPRIMANDED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PRAIRIE ISLAND 2 (PWR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SENSORS, TEMPERATURE • TEST, SYSTEM OPERABILITY • FAILURE, MAINTENANCE ERROR • RESET POINT • REACTOR SAFETY SYSTEM

104090
SHIELD BUILDING VENTILATION SYSTEM TRIP IMPROPER AT PRAIRIE ISLAND 2
NORTHERN STATES POWER COMPANY, MINN.
1 PG., LTR TO NRC DIV. OF REACTOR LICENSING, JULY 20, 1975, DOCKET 50-306, TYPE--PWR, NRC--WEST., AE--PIONEER SERVICE

CAUSE - PROCEDURAL DEFICIENCY. DURING A TEST OF THE SHIELD BUILDING VENTILATION SYSTEM ON JULY 3 WITH THE REACTOR AT 100% POWER, A MONITOR LIGHT INDICATING PROPER OPERATION OF AN INLET HEATER DID NOT LIGHT. WHEN INVESTIGATING ON JULY 13, THE HEATER THERMOSTAT SET POINT HAD DRIFTED DOWNWARD TO 135 F. THE THERMOSTAT WAS RECALIBRATED. THE PROCEDURE FAILED TO FLAG MONITOR LIGHT OPERATION AS BEING REQUIRED FOR TRIP OPERABILITY. PROCEDURES WILL BE REVISED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PRAIRIE ISLAND 2 (PWR) • VENTILATION SYSTEM • PRETENS • PROCEDURES AND MANUALS • FAILURE, ADMINISTRATIVE CONTROL • TEST, SYSTEM OPERABILITY • SHIELDING • BUILDING

105730
SET POINT DRIFT IN PRESSURE SWITCH AT PRAIRIE ISLAND 2
NORTHERN STATES POWER COMPANY, MINN.
1 PG., LTR TO NRC DIV. OF REACTOR LICENSING, SEPT. 5, 1975, DOCKET 50-306, TYPE--PWR, NRC--WEST., AE--PIONEER SERVICE

CAUSE - INSTRUMENT DRIFT. DURING A TEST WITH THE UNIT AT 100% POWER, THE SET POINT OF LOOP 9 MAIN STEAM LINE LOW PRESSURE SAFETY INJECTION WAS FOUND TO BE 497 PSIG VERSUS THE LIMIT OF 500 PSIG. THE APPARENT CAUSE WAS INSTRUMENT DRIFT. THE INSTRUMENT WAS RECALIBRATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PRAIRIE ISLAND 2 (PWR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SENSORS, PRESSURE • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT • RESET POINT • DRIFT • SAFETY INJECTION

105492
STEAM GENERATOR BLOWDOWN VALVE FAILS TO CLOSE AT PRAIRIE ISLAND 2
NORTHERN STATES POWER CO., MINN.
2 PGS., LTR W/RT TO NRC DIVISION OF REACTOR LICENSING, SEPT. 23, 1975, DOCKET 50-306, TYPE--PWR, NRC--WEST., AE--PIONEER SERV.

CAUSE - LOOSE FUSE CLIP. DURING A SHUTDOWN, A STEAM GENERATOR BLOWDOWN ISOLATION VALVE COULD NOT BE CLOSED REMOTELY. A LOOSE FUSE CLIP ON THE BREAKER CAUSED LOSS OF BREAKER INDICATING LIGHTS AND LOSS OF ABILITY TO REMOTELY OPERATE THE VALVE. THE FUSE CLIP WAS REPAIRED AND THE VALVE CYCLED SEVERAL TIMES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PRAIRIE ISLAND 2 (PWR) • VALVES • STEAM GENERATOR • COOLANT PURIFICATION SYSTEM • FAILURE, COMPONENT • CONTAINMENT ISOLATION • INSTRUMENT, PROTECTIVE • BREAKER

104556
AUXILIARY FEEDWATER PUMP LUBE OIL PRESSURE SWITCH FAILS AT PRAIRIE ISLAND 2
NORTHERN STATES POWER CO., MINN.
2 PGS., LTR W/RT TO NRC DIVISION OF REACTOR LICENSING, SEPT. 23, 1975, DOCKET 50-306, TYPE--PWR, NRC--

104520 *CONTINUUM
WEST.. AE--PIONEER SERV.

CAUSE - DEFECTIVE SWITCH. DURING TESTING WITH THE REACTOR AT 63% POWER, THE AUXILIARY LUBE OIL PUMP FOR AUXILIARY FEEDWATER PUMP 22 STARTED AND TRIPPED SHORTLY BEFORE THE APP STARTED. THE CAUSE WAS A DEFECTIVE PRESSURE SWITCH WHICH FAILED IN THE HIGH POSITION. THE SWITCH WAS REPLACED AND THE PUMP TESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RAIRIE ISLAND 2 (PWR) * INSTRUMENT, SWITCH * *SENSORS, PRESSURE * TEST, SYSTEM OPERABILITY * LUBRICATION * PUMPS * FEEDWATER * FAILURE, INSTRUMENT

105142
CONTAINMENT VACUUM BREAKER FOUND UNSERVICEABLE AT PRAIRIE ISLAND
NORTHMAN STATES POWER CO., MINN.
2 PGS. LTR W/AD 75-41 TO NRC DIVISION OF REACTOR LICENSING, SEPT. 26 1975, DOCKET 50-306, TYPE--PWR, NRC--WEST.. AE--PIONEER SERV.

CAUSE - LEAKOFF VALVE DIAPHRAGM FAILURE. DURING A TEST WITH THE UNIT OPERATING AT FULL POWER, CONTAINMENT VACUUM BREAKER ISOLATION VALVE 22 FAILED TO CLOSE ON DEMAND. THE DIAPHRAGM IN THE ALUMINUM AIR LEAKOFF VALVE HAD FAILED. THE DIAPHRAGM WAS REPLACED AND THE ISOLATION VALVE TESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RAIRIE ISLAND 2 (PWR) * CONTAINMENT VACUUM BREAKER * TEST, SYSTEM OPERABILITY * FAILURE, COMPONENT

107916
BLOCK AND HOLD CARDS NOT INSTALLED AT PRAIRIE ISLAND 2
NORTHMAN STATES POWER CO., MINNEAPOLIS, MINN.
2 PGS. LTR W/AD 75-41 TO NRC DIVISION OF REACTOR LICENSING, NOV. 5, 1975, DOCKET 50-306, TYPE--PWR, NRC--WEST.. AE--PIONEER SERV.

CAUSE - OPERATION ERROR. DURING FULLPOWER OPERATION, THE BLOCK AND PERMANENT HOLD CARDS FOR THE BORE ACID SUPPLY TO S1 PUMP SUCTION VALVE WERE NOT INSTALLED. DURING HEATUP 6 DAYS EARLIER, AN OPERATOR WAS INSTRUCTED TO INSTALL THEM ON THE VALVE HANDWHEEL. THE OPERATOR INITIALED THE APPROPRIATE STEP IN THE PROCEDURE BUT FAILED TO COMPLETE IT. REEMPHASIZED THAT STEPS ARE TO BE SIGNED OFF ONLY AFTER COMPLETION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RAIRIE ISLAND 2 (PWR) * ADMINISTRATIVE CONTROL * VALVES * SAFETY INJECTION * POISON, SOLUBLE * IDENTIFICATION * FAILURE, OPERATOR ERROR * PROCEDURES AND MANUALS

108033
DRIFT IN INTERMEDIATE RANGE HIGH FLUX REACTOR TRIP SET POINT AT PRAIRIE ISLAND 2
NORTHMAN STATES POWER CO., MINNEAPOLIS, MINN.
2 PGS. LTR W/AD 75-224 TO NRC DIVISION OF REACTOR LICENSING, DEC. 15, 1975, DOCKET 50-306, TYPE--PWR, NRC--WEST.. AE--PIONEER SERV.

CAUSE - FUEL BURNUP EFFECT. DURING A STARTUP, BOTH INTERMEDIATE RANGE HIGH FLUX REACTOR TRIP SET POINTS WERE OBSERVED TO TRIP AT 30% POWER VERSUS TECH SPEC LIMIT OF 25%. AS POWER DISTRIBUTION CHANGES OVER CORE LIFE, DETECTOR CURRENTS CHANGE SIGNIFICANTLY FROM VALUES MEASURED DURING INITIAL STARTUP. SET POINTS WERE READJUSTED. DETECTOR CURRENT VERSUS POWER DATA WILL BE TAKEN ON FUTURE STARTUPS AND USED TO ADJUST SETTING AS NECESSARY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RAIRIE ISLAND 2 (PWR) * INSTRUMENT, SWITCH * INSTRUMENT CALIBRATION * INSTRUMENT, INTERMEDIATE RANGE * REACTOR STARTUP * FAILURE, INSTRUMENT * RESET POINT * DRIFT * FUEL BURNUP * POWER DISTRIBUTION * FAILURE, ADMINISTRATIVE CONTROL * FAILURE, COMMON MODE

108034
LEAK OCCURS IN ANN SYSTEM PIPING AT PRAIRIE ISLAND 2
NORTHMAN STATES POWER CO., MINNEAPOLIS, MINN.
2 PGS. LTR W/AD 75-224 TO NRC DIVISION OF REACTOR LICENSING, DEC. 15, 1975, DOCKET 50-306, TYPE--PWR, NRC--WEST.. AE--PIONEER SERV.

CAUSE - IMPROPER SUPPORT OF LINE. DURING A HOT SHUTDOWN, LEAKAGE WAS NOTED IN A 3/4 INCH LINE OF THE ANN SYSTEM WHERE A RELIEF VALVE IS MOUNTED. FAILURE WAS DUE TO IMPROPER SUPPORT OF THE LINE FROM A DYNAMIC STANDPOINT. THE CRACKED PORTION WAS REPLACED AND A PIPE HANGER WAS ADDED AS RECOMMENDED BY THE AE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

100834 CONTINUOUS
CHARGE \$2.00

RAIRIE ISLAND 2 (PWR) • PIPES AND PIPE FITTINGS • SHUTDOWN COOLING SYSTEM • LEAK • FAILURE, PIPE • FAILURE, DESIGN ERROR • SUPPORT STRUCTURE • STRESS

100835
CONTAINMENT FAN COIL DAMPER IMPROPERLY POSITIONED AT PRAIRIE ISLAND 2
NORTHERN STATES POWER CO., MINNEAPOLIS, MINN.
2 PGS. LTR #140 75-300 TO NRC DIVISION OF REACTOR LICENSING, DEC. 15, 1975, DOCKET 50-300, TYPE--PWR, NRC--
WEST., AE--PIONEER SERV.

CAUSE - INSUFFICIENT LUBRICATION. DURING A TEST WITH THE REACTOR AT 100% POWER, IMPROPER POSITION OF A CONTAINMENT FAN COIL DAMPER WAS INDICATED. THE DOME DISCHARGE DAMPER WAS IN THE MIS-POSITION AND COULD NOT BE OPERATED REMOTELY. ACTUATOR B WAS BINDING DUE TO INSUFFICIENT LUBRICATION. ACTUATOR A (WITH A BROKEN YOKE DRIVE) WAS BELIEVED TO HAVE FAILED FOLLOWING MANUAL OPENING OF THE DAMPER BLADES WHICH CAUSES FORCES ON THE YOKE IN EXCESS OF DESIGN VALUES. AIR LINE LUBRICATORS WILL BE INSTALLED ON ALL DAMPER ACTUATORS DURING THE NEXT REFUELING OUTAGE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM CHARGE \$2.00)

RAIRIE ISLAND 2 (PWR) • COMPONENTS • VENTILATION SYSTEM • CONTAINMENT • FAILURE, DESIGN ERROR • LUBRICATION • TEST, SYSTEM OPERABILITY

100841
AVERAGE BLUENOVA FLOW EXCEEDS LIMIT AT PRAIRIE ISLAND 1 AND 2
NORTHERN STATES POWER CO., MINN.
2 PAGES. LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 3, MARCH 13, 1975, DOCKETS 50-202/300, TYPE--
PWR, NRC--WEST., AE--PIONEER SERV.

CAUSE - COOLING TOWER REPAIR. A BLADE TORE LOOSE FROM THE FAN ON A COOLING TOWER CELL PULLING THE FAN STRUCTURE FROM ITS MOUNTING AND CAUSING SUBSTANTIAL DAMAGE TO THE TOWER SUPPORT STRUCTURE. AS A RESULT OF THIS, THE VENDOR HAS RECOMMENDED DESIGN MODIFICATIONS AFFECTING ALL 4 TOWERS. THIS CONSISTS OF STRUCTURAL SUPPORT IMPROVEMENTS AND REPAIRS TO SOME DRIVE TRAINS ON THE CELL FANS. DURING THE MODIFICATIONS, BLUENOVA FLOW WILL BE INCREASED ABOVE THE 150 CFS LIMIT. NO ADVERSE ENVIRONMENTAL EFFECTS ARE EXPECTED. MODIFICATIONS ARE EXPECTED TO BE COMPLETED IN 10 WEEKS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM CHARGE \$2.00)

MODIFICATION • FAILURE, DESIGN ERROR • SUPPORT STRUCTURE • FLOW • PRAIRIE ISLAND 1 (PWR) • RATE • COOLING TOWER • PRAIRIE ISLAND 2 (PWR)

103114
FISH TRAPPED IN THE INTAKE STRUCTURE AT PRAIRIE ISLAND 1 AND 2
NORTHERN STATES POWER COMPANY, MINN.
2 PAGES. LETTER TO NRC INSPECTION & ENFORCEMENT, REGION 3, MAY 20, 1975, DOCKETS 50-202/300, TYPE--PWR, NRC--
WEST., AE--PIONEER SERVICE

CAUSE - RIVER AT FLOOD STAGE. FOR 2 SUCCESSIVE 7-DAY PERIODS, A TOTAL OF 3519 FISH (PREDOMINANTLY BLACK BULLHEADS) WERE TRAPPED, BUT MORE THAN 500 WERE RETURNED ALIVE TO THE RIVER. THE LIMIT IS 700 PER WEEK. THE PRIMARY CAUSE WAS THAT THE RIVER WAS AT FLOOD STAGE. THIS PREVENTED NORMAL OPERATION OF THE CIRCULATING WATER SYSTEM AND RESULTED IN THE COOLING TOWERS BEING OPERATED IN A PARTIALLY CLOSED, PARTIALLY HELPED, CYCLE MODE. THIS CAUSED INCREASED FLOW THROUGH THE INTAKE STRUCTURE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM CHARGE \$2.00)

PRAIRIE ISLAND 1 (PWR) • PRAIRIE ISLAND 2 (PWR) • MORTALITY • INTAKE • CONDENSER COOLING SYSTEM • WEATHER, SEVERE • ANIMAL, FISH

105528
FISH IMPINGED ON INTAKE SCREENS AT PRAIRIE ISLAND 1 AND 2
NORTHERN STATES POWER COMPANY
2 PGS. LTR TO NRC OFFICE OF I & E, REGION 3, AUG. 20, 1975, DOCKETS 50-202/300, TYPE--PWR, NRC--WEST., AE--
PIONEER SERVICE

CAUSE - INCREASED INTAKE FLOW. DURING TWO 7-DAY PERIODS IMPINGEMENT LOSSES OF FISH ON THE INTAKE SCREENS EXCEEDED LIMITS. DURING THIS PERIOD THE INTAKE FLOW WAS HIGHER THAN NORMAL DUE TO REPAIR WORK ON THE COOLING TOWERS AND HIGHER RIVER WATER TEMPERATURE. THE SEASONAL PATTERNS ALSO EFFECT IMPINGEMENTS. INTERIM REPAIR WORK HAS BEEN COMPLETED ON THE COOLING TOWERS AND ALL 4 ARE AVAILABLE FOR SERVICE NOW.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 (100 CENTS/PAGE -- MINIMUM CHARGE \$2.00)

105520 CONTINUATION
PRAIRIE ISLAND 1 (PWR) • PRAIRIE ISLAND 2 (PWR) • ANIMAL, FISH • MORTALITY • INTAKE • CONDENSER COOLING
SYSTEM • STRUCTURE • MAINTENANCE AND REPAIR

105527
COOLING TOWER BLOWDOWN FLOW EXCEEDS LIMITS AT PRAIRIE ISLAND 1 AND 2
NORTHERN STATES POWER COMPANY, MINN.
2 PGS. LTR TO NRC OFFICE OF I & E, REGION III, AUG. 27, 1975, DOCKETS 50-202/306, TYPE--PWR, NRG--WEST., AE--
PIONEER SERVICE

CAUSE - RIVER LEVEL HIGH. BLOWDOWN FLOW IS CONTROLLED BY ADJUSTING THE HEAD OF WATER MAINTAINED
IN THE GATE STRUCTURE LOCATED AT THE UPSTREAM EDGE OF THE DISCHARGE CANAL. FROM APRIL 24 TO MAY
11, THE RIVER LEVEL WAS OVER THE GATE SO THAT BLOWDOWN FLOW WAS UNCONTROLLED. ONLY UNIT 2 WAS
OPERATING AT THIS TIME. SINCE THE RIVER FLOW WAS HIGH DURING THE FLOOD STAGE PERIOD, THERE WAS
LITTLE THERMAL EFFECT FROM THE INCREASED DISCHARGE FLOW. THE RIVER IS EXPECTED TO REACH THIS
LEVEL ONCE IN 4-5 YEARS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

PRAIRIE ISLAND 1 (PWR) • PRAIRIE ISLAND 2 (PWR) • FLOW • DISCHARGE • CONDENSER COOLING SYSTEM • RIVER •
WEATHER, SEVERE • COOLING TOWER

106300
COOLING TOWER REMOVED FROM SERVICE AT PRAIRIE ISLAND 1 AND 2
NORTHERN STATES POWER CO., MINN.
2 PGS. LTR LTR 75-73 TO NRC DIRECTOR OF OFFICE OF I & E, REGION III, SEPT. 10, 1975, DOCKETS 50-202/306, TYPE--
PWR, NRG--WEST., AE--PIONEER SERVICE

CAUSE - CRACK IN DISCHARGE PIPE. ON AUG. 30, 1 OF THE 4 COOLING TOWERS HAD TO BE REMOVED FROM
SERVICE BECAUSE OF A LEAK IN THE UNDERGROUND 64 INCH DISCHARGE PIPE ON ONE OF THE TOWER PUMPS.
THE BREAK APPEARS TO BE 50-75 FEET FROM THE PUMP HOUSE STRUCTURE. BLOWDOWN FLOW HAS BEEN
INCREASED TO 500-700 CFS DEPENDING ON WEATHER CONDITIONS AND RIVER TEMPERATURE. REPAIRS WILL
REQUIRE SEVERAL WEEKS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

PRAIRIE ISLAND 1 (PWR) • PRAIRIE ISLAND 2 (PWR) • TYPES AND PIPE FITTINGS • COOLING TOWER • PUMPS • FAILURE,
PIPE • LEAK • BLOWDOWN • FLOW

106312
FISH IMPINGEMENT LOSSES EXCEED LIMIT AT PRAIRIE ISLAND 1 AND 2
NORTHERN STATES POWER CO., MINN.
2 PGS. LTR LTR 75-4, 75-63 TO NRC OFFICE OF I & E, REGION III, SEPT. 11, 1975, DOCKET ' -202/306, TYPE--
PWR, NRG--WEST., AE--PIONEER SERVICE

CAUSE - HIGH WATER INTAKE RATE. FOR THE 7 DAY PERIOD ENDING AUG. 14 AND 20 THE FISH IMPINGED BY
THE INTAKE STRUCTURE EXCEEDED ETS LIMITS. BLOWDOWN FLOW HAS BEEN AT A HIGHER LEVEL FOR SEVERAL
MONTHS BECAUSE OF LIMITED COOLING TOWER AVAILABILITY. THIS REQUIRES A GREATER APPROPRIATION FLOW
AND THUS INCREASES IMPINGEMENT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

PRAIRIE ISLAND 1 (PWR) • PRAIRIE ISLAND 2 (PWR) • ANIMAL, FISH • MORTALITY • FILTER, SCREEN • CONDENSER
COOLING SYSTEM • INTAKE • MAINTENANCE AND REPAIR • COOLING TOWER

107000
FISH IMPINGEMENT ON INTAKE STRUCTURE EXCEEDS LIMIT AT PRAIRIE ISLAND 1 AND 2
NORTHERN STATES POWER CO., MINNEAPOLIS, MINN.
3 PGS. ENVIRONMENTAL EVENT RPTS 75-08 & 75-09 TO NRC OFFICE OF I & E, REGION III, OCT. 31, 1975, DOCKETS 50-
202/306, TYPE--PWR, NRG--WEST., AE--PIONEER SERVICE

CAUSE - NATURAL PHENOMENA. FOR 4 SUCCESSIVE 7-DAY PERIODS, THE NUMBER OF CATFISH IMPINGED BY THE
INTAKE STRUCTURE EXCEEDED THE 175 LIMIT. NUMBERS RANGED FROM 227 TO 1050 PER 7-DAY PERIOD.
MUCH FISH IMPINGEMENT FOR ONE PERIOD EXCEEDED THE 700 LIMIT BY 193 FISH. IT APPEARS THAT THE
LOSSES ARE NOT ATTRIBUTABLE TO PLANT OPERATIONAL VARIABLES, BUT RATHER TO NATURAL PHYSICAL AND
BIOLOGICAL PHENOMENA INFLUENCING FISH PASSAGE AND PRESENCE IN THE INTAKE CANAL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

PRAIRIE ISLAND 1 (PWR) • PRAIRIE ISLAND 2 (PWR) • ANIMAL, FISH • MORTALITY • FILTER, SCREEN • INTAKE •
STRUCTURE • CONDENSER COOLING SYSTEM

104000

100060 *CONTINUED*

MALODEN AND PARTICULATE RELEASES EXCEED TWICE DESIGN OBJECTIVE AT PRAIRIE ISLAND 1 AND 2
NORTHERN STATES POWER CO., MINNEAPOLIS, MINN.
4 PGS. LTR W/RE 75-02 * SUPPLEMENTAL RPT TO NRC DIVISION OF REACTOR LICENSING, NOV. 14, 1975, DOCKETS 50-202/306. TYPE--PWR, NRG--WEST.. AE--PIONEER SERVICE

CAUSE - CONSERVATIVE LIMITS. THE RELEASE RATE OF MALODENS AND PARTICULATES WITH HALF LIVES LONGER THAN 8 DAYS, WHEN AVERAGED OVER A 3-MONTH PERIOD (5-11 TO 8-10-75) AND WHEN EXTRAPOLATED AT THE SAME RELEASE RATE FOR A YEAR, WAS MORE THAN TWICE THE DESIGN OBJECTIVE. TOTAL LONG LIFE RELEASE DURING THE 13 WEEK PERIOD WAS 0.0107 CI. NO CORRECTIVE ACTION IS NECESSARY. A REEVALUATION OF RELEASE LIMITS HAS BEEN REQUESTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PRAIRIE ISLAND 1 (PWR) * PRAIRIE ISLAND 2 (PWR) * RELEASE RATE * AIRBORNE RELEASE * IODINE * PARTICLE, RADIOACTIVE

100791

COOLING TOWER BLOWDOWN RATE EXCEEDS LIMIT AT PRAIRIE ISLAND 1 AND 2
NORTHERN STATES POWER CO., MINNEAPOLIS, MINN.
1 PG. LTR RPT 75-11 TO NRC OFFICE OF I & E, REGION III, NOV. 20, 1975, DOCKETS 50-202/306. TYPE--PWR, NRG--WEST.. AE--PIONEER SERVICE

CAUSE - MAINTENANCE ACTIVITIES. IN ANTICIPATION OF COLD WEATHER OPERATION OF THE COOLING TOWERS, A PROGRAM OF PREVENTATIVE MAINTENANCE WAS INITIATED. TOWERS WERE REMOVED FROM SERVICE ONE AT A TIME SO THAT AT LEAST 3 WERE AVAILABLE FOR HEAT REMOVAL. TO MEET COOLING WATER INLET TEMPERATURE LIMITATIONS DURING THIS PERIOD, IT BECAME NECESSARY TO INCREASE BLOWDOWN FLOW BEYOND 150 CFS ON 4 DAYS. THE LARGEST FLOW WAS 240 CFS. FLOW WAS FREQUENTLY REGULATED DURING THE DAY TO MINIMIZE THE HOURS THAT IT EXCEEDED 150 CFS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PRAIRIE ISLAND 1 (PWR) * PRAIRIE ISLAND 2 (PWR) * FLOW * RATE * BLOWDOWN * COOLING TOWER * MAINTENANCE AND REPAIR

099112

DIESEL GENERATOR FAILS TO START AT RANCHO SECO
SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIFORNIA
3 PAGES. LETTER WITH AD REPORT 75/13 TO DIRECTORATE OF LICENSING (AEC), JANUARY 2, 1975, DOCKET 50-312, TYPE--PWR, NRG--BWR, AE--DECHTEL

CAUSE - ZENER DIODES FAIL. DURING A TEST, A DIESEL GENERATOR FAILED TO START. THE DYNALCO RELAY TACHOMETER HAD MALFUNCTIONED IN A MANNER THAT BLOCKED THE ENERGIZING OF THE DIESEL AIR START SOLENOIDS. THREE ZENER DIODES IN THE SPEED SWITCH HAD OVERHEATED AND FAILED. THE DEFECTIVE TACHOMETER WAS REPLACED. TESTS ARE UNDERWAY TO DETERMINE THE CAUSE OF THE ZENER DIODE OVERHEATING. THIS IS THE THIRD FAILURE OF THE TACHOMETER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT * REACTOR STARTUP EXPERIENCE * TEST, SYSTEM OPERABILITY * RANCHO SECO (PWR) * ENGINES, INTERNAL COMBUSTION * GENERATOR, DIESEL * ELECTRONIC FUNCTION UNITS

100078

CONTAINMENT ISOLATION VALVE FAILS TO OPERATE AT RANCHO SECO
SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.
3 PAGES. LETTER WITH AD REPORT 75/1 TO AEC DIRECTORATE OF LICENSING, FEBRUARY 13, 1975, DOCKET 50-312, TYPE--PWR, NRG--BWR, AE--DECHTEL

CAUSE - WATER IN AIR LINES. DURING ISOLATION VALVE TESTING, THE NORMALLY OPEN REACTOR BUILDING EQUALIZATION VALVE FAILED TO CLOSE. THE AIR LINE TO THE VALVE HAD FILLED WITH WATER. AFTER THE LINE WAS DRAINED AND BLOWN DRY, THE VALVE WAS STROKED 6 TIMES SUCCESSFULLY. IMPROVEMENTS WERE MADE TO THE INSTRUMENT AIR DRYING SYSTEM.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTAINMENT * CONTAINMENT ISOLATION * MODIFICATION * TEST, SYSTEM OPERABILITY * FAILURE, MAINTENANCE ERROR * RANCHO SECO (PWR) * PNEUMATIC SYSTEM * VALVES * INSTRUMENTS, MISC. * AIR DRIERS

100079

FLOW INSTRUMENTATION NOT OPERATING AT RANCHO SECO
SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.
3 PAGES. LETTER WITH AD REPORT 75/2 TO NRC DIRECTORATE OF LICENSING, FEBRUARY 18, 1975, DOCKET 50-312, TYPE--PWR, NRG--BWR, AE--DECHTEL

CAUSE - ROOT VALVE CLOSED. BORATED WATER WAS BEING RECIRCULATED TO THE BORATED WATER STORAGE

100879 CONTINUEUP

TIME FOR MIXING AFTER ADDING MAKEUP WATER. THE SOLUTION WAS CIRCULATED BY THE DECAY HEAT SYSTEM. DURING CIRCULATION, THE OPERATOR NOTED THAT THE FLOW INSTRUMENTATION IN THE CROSS-TIE BETWEEN THE 2 LPI LOOPS WAS NOT OPERATING. THE ROOT VALVES TO THE TRANSMITTER WERE VALVED OUT OF SERVICE. THIS WAS NOTED ON THE VALVE INSPECTION. THE SUPERVISOR SIGNED OFF THE VALVE INSPECTION PROCEDURE AND TOOK NO FURTHER ACTION. THE PROCEDURE REQUIRED THE VALVE TO BE OPEN. OPERATORS WARRIED OF THE IMPORTANCE OF PROPER LINEUP.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, ADMINISTRATIVE CONTROL + RANCHO SECO (PWR) + VALVES + SENSORS, FLOW

100896

SETPOINT DRIFT IN REACTOR COOLANT PRESSURE CHANNEL AT RANCHO SECO

SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.

2 PAGES, LETTER WITH AD REPORT 75/3 TO NRC DIVISION OF REACTOR LICENSING, MARCH 11, 1975, DOCKET 50-312, TYPE-- PWR, NRC--B+W, AE--BECHTEL

CAUSE - ZERO REFERENCE DRIFT. DURING STEADY STATE OPERATION AT 92% POWER, THE TURBINE-GENERATOR TRIPPED WHEN AN OVERSPEED TRIP RELAY FALSELY BECAME DE-ENERGIZED. THE REACTOR COOLANT PRESSURE INCREASED TO 2355 PSIG TRIPPING 3 OF THE 4 REACTOR PROTECTION HIGH PRESSURE CHANNELS. IN THE FOURTH CHANNEL, THE ZERO REFERENCE HAD DRIFTED RESULTING IN AN INCREASE IN THE PRESSURE/RESPONSE CURVE THROUGHOUT THE ENTIRE BAND. THE ACTUAL SETPOINT WAS WELL ABOVE THE SPECIFIED LIMIT. CAUSE FOR THE ZERO DRIFT HAS NOT BEEN DETERMINED. THE TRANSMIT WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, INSTRUMENT + INSTRUMENT, SWITCH + PRESSURE RELIEF + MAIN COOLING SYSTEM + RANCHO SECO (PWR) + SET POINT + DRIFT + SENSORS, PRESSURE

101446

RADIOACTIVITY DETECTED IN COMPONENT COOLING SYSTEM AT RANCHO SECO

SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.

2 PAGES, LETTER WITH AD REPORT 75/5 TO NRC DIVISION OF REACTOR LICENSING, MARCH 28, 1975, DOCKET 50-312, TYPE-- PWR, NRC--B+W, AE--BECHTEL

CAUSE - UNKNOWN. SAMPLES TAKEN FROM THE COMPONENT COOLING SYSTEM ON JAN. 13 INDICATED THE PRESENCE OF TRITIUM BUT NO TRACE OF GROSS BETA, FISSION GAS, OR ACTIVATION PRODUCTS. THE FEB. 17 SAMPLES DETECTED FISSION GASES AND ACTIVATION PRODUCTS INDICATING A POSSIBLE BREACH OF A BOUNDARY CONTAINING REACTOR COOLANT. THE CALCULATED LEAK RATE IS 2 TO 4 GAL/DAY. AN INTENSIVE INVESTIGATION IS CONTINUING TO DETERMINE THE ORIGIN OF THE RADIOACTIVITY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, EQUIPMENT + REACTOR COOLANT + CHEMICAL ANALYSIS + REACTOR STARTUP EXPERIENCE + RADIOISOTOPE + LEAK + RANCHO SECO (PWR) + AUXILIARY COOLING SYSTEM

101454

AUXILIARY FEEDWATER BYPASS VALVE FAILS TO OPEN AT RANCHO SECO

SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.

2 PAGES, LETTER WITH AD REPORT 75/6 TO NRC DIVISION OF REACTOR LICENSING, MARCH 31, 1975, DOCKET 50-312, TYPE-- PWR, NRC--B+W, AE--BECHTEL

CAUSE - STEM BOUND BY PACKING. DURING A TEST WITH THE REACTOR AT 92% POWER, THE EMERGENCY FEEDWATER BYPASS VALVE WOULD NOT OPEN AUTOMATICALLY FROM A CONTROL ROOM SIGNAL. AFTER THE VALVE WAS MANUALLY SEARDED ONCE, THE AUTOMATIC CONTROLS SUCCESSFULLY OPENED THE VALVE SEVERAL TIMES. THE PACKING HAD BOUND TO THE VALVE STEM. FREQUENT EXERCISING WILL WEAR IN THE PACKING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, EQUIPMENT + REACTOR STARTUP EXPERIENCE + TEST, SYSTEM OPERABILITY + SEAL + RANCHO SECO (PWR) + BYPASS + FEEDWATER + VALVES

102165

SET POINT DRIFT IN PRESSURE TRANSMITTERS AT RANCHO SECO

SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.

3 PAGES, LETTER WITH AD REPORT 75/4 TO NRC DIVISION OF REACTOR LICENSING, APRIL 4, 1975, DOCKET 50-312, TYPE-- PWR, NRC--B+W, AE--BECHTEL

CAUSE - INSTRUMENT DRIFT. DURING A CALIBRATION, 3 OF THE 4 APS PRESSURE TRANSMITTERS WERE FOUND TO HAVE DRIFTED MORE THAN THE EXPECTED 4 PSI. ONE WAS 8 PSI LOW, ONE 12 PSI HIGH, AND THE OTHER SLIGHTLY ABOVE THE 4 PSI TOLERANCE. THE UNITS WERE RECALIBRATED TO 1904 PSIG FOR LOW PRESSURE TRIP AND 2351 PSIG FOR HIGH PRESSURE TRIP. THEY WILL BE CHECKED EVERY 2 WEEKS TO DETERMINE TRENDS.

102165 PLCONTINUED
 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

REACTOR SAFETY SYSTEM • INSUFFICIENT CALIBRATION • FAILURE, INSTRUMENT • INSTRUMENT, SWITCH • TEST, SYSTEM
 OPERABILITY • RANCHO SECO (PWR) • SET POINT • DRIFT • SENSORS, PRESSURE

102114
 CHLORINE IN EFFLUENT EXCEEDS LIMIT AT RANCHO SECO
 SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.
 2 PAGES, LETTER TO NRC DIVISION OF REACTOR LICENSING, APRIL 8, 1975, DOCKET 50-312, TYPE--PWR, NRC--B&N, AE--DECHTEL

CAUSE - OPERATING CONDITIONS. DURING NORMAL OPERATION, THE CHLORINE INJECTED INTO THE CIRCULATING
 WATER SYSTEM FOR ALGAE CONTROL IS REMOVED WHEN SPRAYED THROUGH THE COOLING TOWERS. ON MARCH 22
 THE REACTOR WAS SHUT DOWN BUT THE CIRCULATING WATER SYSTEM CONTINUED IN OPERATION. THE NEXT DAY
 IT WAS SHUT DOWN JUST AFTER A CHLORINE INJECTION. THIS RESULTED IN A TEMPORARY OVERFLOW
 CONDITION FROM THE TOWER SPRAYS. EFFLUENT SAMPLES HAD A MAXIMUM OF 1.5 PPM CHLORINE. THE 1 PPM
 LIMIT WAS EXCEEDED FOR 2 HOURS. THE CIRCULATING WATER SYSTEM WILL BE SAMPLED PRIOR TO SECURING
 ALL PUMPS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

EFFLUENT • PROCEDURES AND MANUALS • CHLORINE • FAILURE, ADMINISTRATIVE CONTROL • RANCHO SECO (PWR) • CONDENSER
 COOLING SYSTEM

102486
 BORIC ACID CONCENTRATION IN STORAGE TANK EXCEEDS LIMIT AT RANCHO SECO
 SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.
 3 PAGES, LETTER WITH AM 75-7 TO NRC DIVISION OF REACTOR LICENSING, APRIL 16, 1975, DOCKET 50-312, TYPE--PWR,
 NRC--B&N, AE--DECHTEL

CAUSE - OPERATOR ERROR. PERSONNEL WERE CONCENTRATING REACTOR COOLANT TO RECOVER THE BORIC ACID.
 THE CONCENTRATE FROM THE BORIC ACID EVAPORATOR IS STORED IN THE CONCENTRATED BORIC ACID STORAGE
 TANK. AFTER THE CONCENTRATE WAS TRANSFERRED, THE STORAGE TANK BORON CONCENTRATION WAS FOUND TO
 BE 8010 PPM, WHICH EXCEEDS THE 8500 PPM LIMIT. DEMINERALIZED WATER WAS ADDED TO REDUCE
 CONCENTRATION BELOW LIMITS. THE OPERATORS HAD FAILED TO SAMPLE AND CALCULATE THE CONCENTRATION
 BEFORE THE TRANSFER. OPERATORS WILL BE RETRAINED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

RANCHO SECO (PWR) • BORON • CONCENTRATION • STORAGE CONTAINER • FAILURE, OPERATOR ERROR • SAMPLING •
 MATHEMATICAL TREATMENT

102117
 CHLORINE IN EFFLUENT EXCEEDS LIMITS AT RANCHO SECO
 SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.
 4 PAGES, LETTER TO NRC DIVISION OF REACTOR LICENSING, APRIL 18, 1975, DOCKET 50-312, TYPE--PWR, NRC--B&N, AE--
 DECHTEL

CAUSE - OPERATOR ERROR. ON APRIL 7, THE REACTOR WAS SHUT DOWN AND THE AUTOMATIC CHLORINE
 INJECTION INTO THE CIRCULATING WATER SYSTEM WAS TERMINATED. CHLORINE WAS ADDED MANUALLY. LATER
 THE CHLORINE INCREASED TO 1.95 PPM IN THE SYSTEM. THE NEXT DAY WHEN THE DILUTION FLOW WAS
 SECURED, THE EFFLUENT EXCEEDED THE CHLORINE LIMIT UNTIL THE FLOW WAS REESTABLISHED. THE CHLORINE
 INJECTION SYSTEM HAD BEEN TURNED TO AUTOMATIC FOR THE MANUAL INJECTION. THIS ADDED EXCESSIVE
 QUANTITIES CAUSING THE HIGH CONCENTRATION IN THE SYSTEM. PROCEDURES WERE CHANGED TO PREVENT USE
 OF THE AUTOMATIC INJECTION DURING A SHUTDOWN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

EFFLUENT • FAILURE, OPERATOR ERROR • PROCEDURES AND MANUALS • CHLORINE • RANCHO SECO (PWR) • LAKE • CONDENSER
 COOLING SYSTEM

102487
 HIGH CHLORINE IN PLANT EFFLUENT AT RANCHO SECO
 SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.
 1 PAGE, LETTER TO NRC DIVISION OF REACTOR LICENSING, APRIL 24, 1975, DOCKET 50-312, TYPE--PWR, NRC--B&N, AE--
 DECHTEL

CAUSE - PROCEDURAL DEFICIENCY. DURING ROUTINE EFFLUENT WATER SAMPLE COLLECTIONS, THE TECHNICIAN
 DETECTED THE SMELL OF CHLORINE IN THE EFFLUENT WATER. THE SAMPLE ANALYSIS INDICATED 1.8 PPM
 WHICH IS ABOVE THE 0.2 PPM LIMIT. A TANK TRUCK HAD MADE A DELIVERY OF HYPOCHLORITE. AFTER
 FILLING THE LAST TANK, THE DRIVER DRAINED THE HOSE, CONTAINING ABOUT 4 GALLONS, TO THE STORM
 SEWER. A MEMORANDUM WILL BE ISSUED TO RECEIVING PERSONNEL TO HAVE THE TRUCKER EMPTY THE FILL
 MOUNT BACK INTO THE NUCLEAR SERVICE RAW WATER SPRAY POND. NO HYPOCHLORITE IS TO BE PUT INTO THE
 STORM DRAIN SYSTEM.

102407 *CONTINUED*
 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

RANCHO SECO (PWR) * CHLORIDE * CONCENTRATION * EFFLUENT * TRANSPORTATION AND HANDLING

103046
 NON-CONSERVATIVE SET POINTS IN PART OF THE TRIP ENVELOPE AT RANCHO SECO
 SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIFORNIA
 4 PAGES. LETTER WITH AQ 75-8 TO NRC DIV. OF REACTOR LICENSING, MAY 7, 1975, DOCKET 50-312, TYPE--PWR, HFG--
 BEN, AE--DECHTEL

CAUSE - ERROR IN READING A LIMIT POINT. AN ERROR WAS DISCOVERED IN THE POSITIVE IMBALANCE PORTION
 OF THE TRIP ENVELOPE FOR FLUX/IMBALANCE/FLOW, RESULTING IN NON-CONSERVATIVE SET POINTS.
 CONSERVATIVE INTERIM SET POINTS WERE THEN INSERTED IN THE APS PENDING FORMAL RECEIPT OF FINAL SET
 POINTS. THIS ERROR RESULTED FROM ONE POINT OF THE OFFSET-VERSUS-POWER LIMITS BEING MISREAD
 DURING CONVERSION OF THE CORE-AXIAL-OFFSET TO CORE-AXIAL-IMBALANCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

RANCHO SECO (PWR) * SET POINT * REACTOR SAFETY SYSTEM * FAILURE, ADMINISTRATIVE CONTROL * MATHEMATICAL
 TREATMENT

103046
 CONCENTRATED BORIC ACID STORAGE TANK VOLUME BELOW LIMITS AT RANCHO SECO
 SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.
 3 PAGES. LETTER WITH AQ 75-9 TO NRC DIVISION OF REACTOR LICENSING, MAY 13, 1975, DOCKET 50-312, TYPE--PWR,
 HFG--BEN, AE--DECHTEL

CAUSE - OPERATOR ERROR. DURING A CHEMICAL CLEANUP OF THE ONCE THROUGH STEAM GENERATORS, EXCESS
 ADDITION CAUSED A REACTOR TRIP ON HIGH PRESSURE. BORATED WATER WAS ADDED TO THE REACTOR COOLANT
 SYSTEM FROM THE CONCENTRATED BORIC ACID STORAGE TANK. THE REACTOR WAS RETURNED TO CRITICAL
 WITHOUT REFILLING THE TANK, THUS VIOLATING THE MINIMUM VOLUME LIMIT. THE VOLUME WAS RESTORED
 WITHIN AN HOUR AFTER DISCOVERY OF THE ERROR. PROCEDURES WILL BE REVISED TO INCREASE THE VOLUME
 MAINTAINED IN THE TANK.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

RANCHO SECO (PWR) * SYSTEM CAPACITY * STORAGE CONTAINER * POISON, SOLUBLE * CHEMICAL SHIM * FAILURE,
 OPERATOR ERROR * BORON

103130
 CHLORINE CONCENTRATION IN EFFLUENT EXCEEDS LIMITS AT RANCHO SECO
 SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIFORNIA
 2 PAGES. LETTER TO NRC DIV. OF REACTOR LICENSING, MAY 16, 1975, DOCKET 50-312, TYPE--PWR, HFG--BEN, AE--DECHTEL

CAUSE - CHANGE IN PROCESS. SINCE OPERATION WAS RESUMED AT 92% POWER, THE ALGAE GROWTH IN THE
 CIRCULATING WATER SYSTEM HAS STEADILY INCREASED. A NEW PROGRAM WAS INITIATED TO INVESTIGATE
 BETTER CHLORINE INJECTION SEQUENCES. THREE DAYS LATER AN EFFLUENT SAMPLE SHOWED AN INCREASE TO
 0.3 PPM CHLORINE. THE DILUTION WATER WAS INCREASED AND THE CONCENTRATION WAS REDUCED TO 0.14 PPM
 0.5 HR LATER. CHLORINE INJECTION RATES WERE REDUCED TO PREVENT RECURRENCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

RANCHO SECO (PWR) * CHLORINE * CONCENTRATION * EFFLUENT * CONDENSER COOLING SYSTEM * MODIFICATION * PLANT,
 ALGAE/FUNGUS * CONTROL * WATER QUALITY

103407
 DAILY CHECKS OF VOLTAGE ACROSS ZENER DIODES NOT MADE AT RANCHO SECO
 SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIFORNIA
 2 PAGES. LETTER WITH AQ REPORT 74-13 TO NRC DIVISION OF REACTOR LICENSING, JUNE 3, 1975, DOCKET 50-312, TYPE--
 PWR, HFG--BEN, AE--DECHTEL

CAUSE - PERSONNEL ERROR. A DAILY CHECK OF THE VOLTAGE ACROSS 3 ZENER DIODES WAS TO BE MADE UNTIL
 SUFFICIENT EVIDENCE WAS ACCUMULATED TO ASSURE RELIABLE OPERATION. DURING AN INTERNAL AUDIT, NO
 DATA WAS FOUND FOR 2 DAYS AND FOR ONLY 6 DAYS DURING A 4 WEEK PERIOD. THE TECHNICIAN WAS ON
 VACATION DURING THE 2 DAY PERIOD. LATER, HE BELIEVED HE HAD ACCUMULATED SUFFICIENT INFORMATION
 SO HE STOPPED TAKING DATA. DATA ACCUMULATION WAS REINSTATED UNTIL AN ENGINEER ACCUMULATION WAS
 REINSTATED UNTIL AN ENGINEER TERMINATED THE PROGRAM

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

RANCHO SECO (PWR) * DATA COLLECTION * ACCUMULATION * FAILURE, MAINTENANCE ERROR * SOLID STATE DEVICE *
 INSTRUMENTS, MISC.

103651

ADDITIONAL INFORMATION ON DECAY HEAT FLOW METER AT RANCHO SECO
SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.

2 PAGES, LETTER WITH AD REPORT 75-2 TO NRC DIVISION OF REACTOR LICENSING, JUNE 6, 1975, DOCKET 50-312, TYPE--PWR, NRC--BGE, AE--BECHTEL

CAUSE - WRONG SCALE IN INDICATOR. AS REPORTED EARLIER, THE DECAY HEAT REMOVAL CROSS-TIE FLOW METER WAS TO BE RECALIBRATED. TEST REVIEW SHOWED THAT FLOW WAS STILL UNACCEPTABLE. A THIRD TEST WAS ALSO NOT ACCEPTABLE. IT WAS THEN FOUND THAT THE SCALE ON THE FLOW INDICATOR INSTALLED IN THE CONTROL ROOM TO MONITOR THIS FLOW WAS RECEIVED WITH THE WRONG SCALE FROM THE MANUFACTURER. WHEN THE CORRECT SCALE WAS INSTALLED AND THE TEST RUN UNDER THE ORIGINAL CONDITIONS, THE INDICATED FLOW PASSED THE FLOW REQUIREMENTS OF 1500 GPM.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RANCHO SECO (PWR) • PWR • PRIMARY COOLING SYSTEM • FAILURE, FABRICATION ERROR • SENSORS, FLOW • INSTRUMENT CALIBRATION • TEST, SYSTEM OPERABILITY

103662

INITIUM FOUND IN COMPONENT COOLING SYSTEM AT RANCHO SECO
SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.

1 PAGE, LETTER TO NRC DIVISION OF REACTOR LICENSING, JUNE 9, 1975, DOCKET 50-312, TYPE--PWR, NRC--BGE, AE--BECHTEL

CAUSE - LEAK IN AC PUMP SEAL WATER COOLER. A NORMALLY NON-RADIOACTIVE CLOSED COOLING SYSTEM WAS FOUND TO CONTAIN INITIUM ON JAN. 13, 1975. AN INTENSIVE INVESTIGATION WAS INITIATED. A LEAK WAS DETECTED IN THE REACTOR COOLANT PUMP A SEAL WATER COOLER. THE SMOKE-TO-COIL WELD HAD DEVELOPED A CRACK IN THE COOLING COIL. SINCE REACTOR COOLANT PRESSURE IS HIGHER THAN CCM PRESSURE, A COIL-TO-SMOKE LEAK OCCURRED. SINCE REPLACEMENT, THE ACTIVITY IN THE CCM SYSTEM HAS BEEN STEADILY DECREASING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RANCHO SECO (PWR) • AUXILIARY COOLING SYSTEM • HEAT EXCHANGERS • LEAK • REACTOR COOLANT • WELDS • CRACK • FAILURE, EQUIPMENT

103661

AUXILIARY FEEDWATER PUMP STOPS AT RANCHO SECO
SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.

3 PAGES, LETTER WITH AD REPORT 75-10 TO NRC DIVISION OF REACTOR LICENSING, JUNE 10, 1975, DOCKET 50-312, TYPE--PWR, NRC--BGE, AE--BECHTEL

CAUSE - TRIPPED ON OVERCURRENT. DURING A TEST WITH THE REACTOR AT 92% POWER, 1 OF THE 2 AUXILIARY FEEDWATER PUMPS STOPPED. A SECOND TRY WAS ALSO UNSUCCESSFUL. THE PUMP MOTOR TRIPPED ON OVERCURRENT. THE LOCK OUT ON THE RELAY ELEMENT PLUNGER WAS LOOSE. IT WAS TIGHTENED. ALSO THE FINE DELAY OVERCURRENT TRIP SET POINT HAD DRIFTED FROM 23 AMPS TO 21 AMPS ON ALL 3 PHASES. THE SET POINTS WERE READJUSTED. THE PUMP THEN OPERATED SUCCESSFULLY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RANCHO SECO (PWR) • PUMPS • FEEDWATER • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT • INSTRUMENT, PROTECTIVE • SET POINT • DRIFT

104962

REQUIRED ISOTOPIC ANALYSIS NOT PERFORMED AT RANCHO SECO
SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIFORNIA

2 PAGES, LETTER WITH AD REPORT 75-11 TO NRC DIVISION OF REACTOR LICENSING, JUNE 23, 1975, DOCKET 50-312, TYPE--PWR, NRC--BGE, AE--BECHTEL

CAUSE - PROCEDURAL DEFICIENCY. THE ISOTOPIC ANALYSIS OF WASTE GAS DECAY TANK D WAS NOT PERFORMED FOR THE FIRST QUARTER OF 1975, AS REQUIRED. THIS EVENT WAS CAUSED BY LACK OF A PROCEDURE DEFINING THE SURVEILLANCE SCHEDULE CORRECTLY. A PROCEDURE WILL BE WRITTEN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RANCHO SECO (PWR) • CHEMICAL ANALYSIS • ELEMENTS AND ISOTOPES • WASTE STORAGE • STORAGE CONTAINER • WASTE TREATMENT, GAS • FAILURE, ADMINISTRATIVE CONTROL • PROCEDURES AND MANUALS

104295

WASTE WATER EFFLUENT PH EXCEEDS LIMIT AT RANCHO SECO
SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.

1 PAGE, LETTER WITH AD REPORT 75-7 TO NRC DIV. OF REACTOR LICENSING, JULY 14, 1975, DOCKET 50-312, TYPE--PWR, NRC--BGE, AE--BECHTEL

104295 - CONTINUED

CAUSE - IMPROPER SET POINT. WITH THE REACTOR IN COLD SHUTDOWN FOR TURBINE REPAIRS, A SAMPLE OF WASTE WATER EFFLUENT INDICATED A PH OF 9.15. THE LIMIT ALLOWS A PH OF 8.5 OR EQUAL TO THAT OF THE DILUTION WATER. THE UPPER LIMIT ON THE PH METER HAD BEEN SET AT 9.2 ON A PREVIOUS OCCASION WHEN THE DILUTION WATER PH WAS 9.2. THE UPPER LIMIT WAS RESET TO 8.5. PRIOR TO RESETTING THE LIMIT, A TEMPORARY CHANGE MUST BE APPROVED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RANCHO SECO (PHR) + WATER QUALITY + EFFLUENT + WASTE DISPOSAL + FAILURE, ADMINISTRATIVE CONTROL + SET POINT + INSTRUMENTS, MISC.

104313

QUANTITY OF DISSOLVED SOLIDS DISCHARGED EXCEEDS LIMIT AT RANCHO SECO

SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.

2 PAGES, LETTER WITH LTR 75-5 TO NRC DIV. OF REACTOR LICENSING, JULY 14, 1975, DOCKET 50-312, TYPE--PHR, MFG--BEN, AE--BECHTEL

CAUSE - HIGH COOLING TOWER BLOWDOWN. CALCULATIONS OF DAILY DISSOLVED SOLIDS RELEASED INDICATED 30400 POUNDS DISCHARGED ONE DAY, EXCEEDING THE 34000 POUND LIMIT. HIGH COOLING TOWER BLOWDOWN CONDUCTIVITY AND LARGE RETENTION BASIN RELEASES OCCURRED ON THE SAME DAY. A PROCEDURE HAD BEEN INSTITUTED TO HAVE A CALCULATION PERFORMED FOR THE EXPECTED DAILY RELEASE ON THE DAYS WHEN THERE IS TO BE A RETENTION BASIN RELEASE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RANCHO SECO (PHR) + WATER QUALITY + EFFLUENT + WASTE DISPOSAL + FAILURE, ADMINISTRATIVE CONTROL + RELEASE RATE + PROCEDURES AND MANUALS

104296

CONDUCTIVITY OF EFFLUENT WASTE WATER EXCEEDS LIMIT AT RANCHO SECO

SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.

2 PAGES, LETTER WITH LTR 75-6 TO NRC DIV. OF REACTOR LICENSING, JULY 15, 1975, DOCKET 50-312, TYPE--PHR, MFG--BEN, AE--BECHTEL

CAUSE - SENSING SYSTEM OVERREACTED. BRIEF SPIKES ON THE CONDUCTIVITY METER INDICATING TOTAL DISSOLVED SOLIDS ABOVE THE 850 MG/L LIMITS ON 4 DAYS. ON ANOTHER DAY A READING OF 1630 MG/L WAS INDICATED FOR 15 MINUTES. THE CONDUCTIVITY METER OVERREACTS WHEN THE RETENTION BASIN IS RELEASED. WHEN CONDUCTIVITY STARTS INCREASING, A SPIKE OCCURS. THE SYSTEM WILL BE DESENSITIZED TO ALLEVIATE THE PROBLEM. NO EXPLANATION WAS FOUND FOR THE EXTENDED HIGH LEVEL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RANCHO SECO (PHR) + EFFLUENT + WASTE DISPOSAL + WATER QUALITY + INSTRUMENTS, MISC. + FAILURE, INSTRUMENT

105472

DISSOLVED SOLIDS IN EFFLUENT EXCEEDS LIMIT AT RANCHO SECO

SACRAMENTO MUNICIPAL UTILITY DISTRICT

1 PAGE, LETTER TO NRC DIRECTOR OF REGULATORY OPERATIONS, REGION 5, AUG. 12, 1975, DOCKET 50-312, TYPE--PHR, MFG--BEN, AE--BECHTEL

CAUSE - PROCEDURES NOT IN EFFECT. WITH THE PLANT OPERATING AT 92.5% POWER, THE CALCULATED DISCHARGE OF DISSOLVED SOLIDS WAS INDICATED TO BE GREATER THAN THE 34,000 LB/DAY LIMIT ON 3 DAYS IN EARLY JUNE. A SIMILAR EVENT WAS REPORTED EARLIER. A PROCEDURE WAS INSTITUTED THEN TO PREVENT REOCCURRENCE, BUT THE REVIEW OF IT HAD NOT BEEN COMPLETED. THESE RELEASES DID NOT USE THE NEW PROCEDURE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

EFFLUENT + WASTE DISPOSAL + FAILURE, ADMINISTRATIVE CONTROL + PROCEDURES AND MANUALS + WASTE DISPOSAL, LIQUID + CONDENSER COOLING SYSTEM + RANCHO SECO (PHR)

105731

DISCHARGE OF DISSOLVED SOLIDS EXCEEDS LIMITS AT RANCHO SECO

SACRAMENTO MUNICIPAL UTILITY DISTRICT

2 PGS, LTR W/ LTR 75-8 TO NRC DIR. OF REGULATORY OPERATIONS, REGION 5, AUG. 12, 1975, DOCKET 50-312, TYPE--PHR, MFG--BEN, AE--BECHTEL

CAUSE - PREVENTIVE PROCEDURES NOT IN EFFECT. ON 3 DAYS IN JUNE, THE DISCHARGE OF DISSOLVED SOLIDS EXCEEDED THE TECH SPEC LIMIT OF 34000 LBS/DAY. THE PLANT WAS OPERATING AT 92.5% POWER. PREVENTIVE PROCEDURES WRITTEN AFTER A SIMILAR OCCURRENCE WERE NOT INSTITUTED UNTIL EARLY JULY DUE TO A ONE MONTH TIME LAG IN REVIEWING DATA CHARTS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

105731 CONTINUED
RANCHO SECO (PHR) + SULLO + CONCENTRATION + EFFLUENT + CONDENSER COOLING SYSTEM

100021
DIESEL GENERATOR VENT FAN FAILS TO START AT RANCHO SECO
SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.
2 PGS. LTR W/AD-75-15 TO NRC DIRECTOR OF REGULATORY OPERATIONS, REGION V, SEPT. 26, 1975, DOCKET 50-312, TYPE--
PHR, HFG--BCH, AE--BECHTEL

CAUSE - DEFECTIVE RELAY. DURING A TEST OF SAFETY FEATURES ACTUATION OF DIESEL GENERATOR B WHILE THE REACTOR WAS IN COLD SHUTDOWN, A BREAKER FAILED TO CYCLE, PREVENTING OPERATION OF THE DIESEL VENT FAN. AN INTERNAL SPACER WAS MISSING FROM A RELAY, ALLOWING MOVEMENT WHICH DESTROYED THE CONTACTS, PREVENTING THE BREAKER FROM OPERATING. THE RELAY WAS REPLACED. TESTS VERIFIED OPERABILITY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RANCHO SECO (PHR) + BREAKER + TEST, SYSTEM OPERABILITY + GENERATOR, DIESEL + FAILURE, COMPONENT + RELAYS + FAILURE, FABRICATION ERROR + BLOWERS

100022
DECAY HEAT REMOVAL SYSTEM VALVE FAILS TO OPEN AT RANCHO SECO
SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.
2 PGS. LTR W/AD-75-16 TO NRC DIRECTOR OF REGULATORY OPERATIONS, REGION V, SEPT. 26, 1975, DOCKET 50-312, TYPE--
PHR, HFG--BCH, AE--BECHTEL

CAUSE - SHAFT KEY SHEARED. WITH THE REACTOR IN COLD SHUTDOWN, AN ATTEMPT TO PLACE DECAY HEAT REMOVAL SYSTEM B IN SERVICE FAILED WHEN THE COOLER OUTLET VALVE FAILED TO OPEN. A KEY ON THE SHAFT HAD SHEARED DISCONNECTING THE MOTOR SHAFT FROM THE VALVE STEM. THE KEY WAS REPLACED. TESTING VERIFIED VALVE OPERABILITY. THE VENDOR STATED THAT THIS TYPE OF FAILURE IS VERY RARE AND THAT KEY SIZE WAS CORRECT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RANCHO SECO (PHR) + VALVES + SHUTDOWN COOLING SYSTEM + FAILURE, COMPONENT

100023
REACTOR BUILDING PURGE OUTLET VALVE LEAKAGE EXCESSIVE AT RANCHO SECO
SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.
3 PGS. LTR W/AD-75-12 TO NRC DIRECTOR OF REGULATORY OPERATIONS, REGION V, SEPT. 26, 1975, DOCKET 50-312, TYPE--
PHR, HFG--BCH, AE--BECHTEL

CAUSE - VALVE SEATS IMPROPERLY ADJUSTED. WHILE PERFORMING LOCAL LEAK RATE TESTS ON THE REACTOR BUILDING PURGE OUTLET VALVE PENETRATION WITH THE REACTOR IN COLD SHUTDOWN, EXCESSIVE LEAKAGE WAS FOUND THROUGH THE INNER VALVE. THE VALVE SEATS ON THE 60 INCH ALLIS CHAMBERS BUTTERFLY VALVE, MODEL 60 NR, WERE ADJUSTED TO REDUCE LEAKAGE TO ESSENTIALLY ZERO. THE OUTER VALVE HAD AN ACCEPTABLE LEAK RATE. ATTEMPTS TO REDUCE LEAKAGE BY ADJUSTMENT OF THE SEATS WERE NOT SUCCESSFUL. SEATS WILL BE REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RANCHO SECO (PHR) + LEAK RATE + VALVES + TEST, LEAK RATE + TEST, SYSTEM OPERABILITY + FAILURE, MAINTENANCE ERROR + FAILURE, EQUIPMENT + CONTAINMENT INTEGRITY + CONTAINMENT PURGE

100964
BOTH HYDROGEN PURGE BLOWERS FOUND INOPERABLE AT RANCHO SECO
SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.
3 PGS. LTR W/AD-75-15 TO NRC DIRECTOR OF REGULATORY OPERATIONS, REGION V, OCT. 1, 1975, DOCKET 50-312, TYPE--
PHR, HFG--BCH, AE--BECHTEL

CAUSE - WATER IN SUCTION LINES. DURING REFUELING SURVEILLANCE TESTS ON THE HYDROGEN PURGE BLOWERS, BOTH BLOWERS FAILED TO OPERATE. WATER WHICH HAD CONDENSED IN HYDROGEN PURGE LINES COLLECTED IN THE BLOWERS CAUSING FAILURE. THE SYSTEM WILL BE ISOLATED WHEN NOT IN USE. DRAINAGE VALVES WILL BE ADDED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RANCHO SECO (PHR) + BLOWERS + HYDROGEN + CONTROL + CONTAINMENT PURGE + TEST, SYSTEM OPERABILITY + FAILURE, SIMULTANEOUS + REFUELING + CONDENSATION

107413
FOLLOW-UP REPORT ON CONDUCTIVITY PETER SPIKES AT RANCHO SECO
SACRAMENTO MUNICIPAL UTILITY DISTRICT, CALIF.

107613 CONTINUED
2 PGS. LTR W/AV 75-6 TO NRC DIRECTOR OF REGULATORY OPERATIONS, REGION 5, OCT. 6, 1975, DOCKET 50-312, TYPE--
PWR, NRG--BEN, AE--BECHTEL

CAUSE - DESIGN DEFICIENCY. IN RESPONSE TO SPIKES WHICH APPEARED ON CONDUCTIVITY METER MEASURING WASTE WATER EFFLUENT, DESENSITIZING THE SYSTEM WAS RECOMMENDED. THIS WAS FOUND TO BE IMPRACTICAL. THE SYSTEM IS PRESENTLY BEING REDESIGNED. TWO NEW CONDUCTIVITY METERS WILL BE INCLUDED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RANCHO SECO (PWR) + MONITOR + EFFLUENT + FAILURE, DESIGN ERROR + MODIFICATION + MEASUREMENT, NOISE

108222
FOUR REACTOR BUILDING SPRAY SYSTEM NOZZLES BLOCKED AT RANCHO SECO
SACRAMENTO MUNICIPAL UTILITY DISTRICT, SACRAMENTO, CALIF.
3 PGS. LTR W/AV 75-16 TO NRC DIRECTOR OF REGULATORY OPERATIONS, REGION V, NOV. 19, 1975, DOCKET 50-312, TYPE--
PWR, NRG--BEN, AE--BECHTEL

CAUSE - TAPE NOT REMOVED AFTER PAINTING. INVESTIGATION REVEALED THAT 4 REACTOR BUILDING SPRAY SYSTEM NOZZLES HAD BEEN COVERED WITH TAPE OVER THEIR OPENINGS AND 12 OTHERS HAD TAPE WHICH DID NOT ALLOW THE SPRAY OPENINGS. THERE ARE 199 NOZZLES IN THE SYSTEM. THE TAPE WAS PLACED OVER THE NOZZLES DURING PAINTING IN THE REACTOR BUILDING AND WAS NOT REMOVED BY THE OUTSIDE CONTRACTOR WHEN WORK WAS COMPLETED. THE TAPE WILL BE REMOVED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RANCHO SECO (PWR) + NOZZLE + CONTAINMENT SPRAY + FLOW BLOCKAGE + FAILURE, INSTALLATION ERROR

108875
PRELIMINARY REPORT ON TURBINE FAILURE AT RANCHO SECO
SACRAMENTO MUNICIPAL UTILITY DISTRICT, SACRAMENTO, CA
3 PGS. LTR W/AV 75-17 TO NRC DIRECTOR OF NUCLEAR REACTOR REGULATION, DEC. 3, 1975, DOCKET 50-312, TYPE--PWR, NRG--
BEN, AE--BECHTEL

CAUSE - STRESS CORROSION. ON JUNE 29 WITH THE UNIT OPERATING AT STEADY LOAD OF 92% A NO. 6 TURBINE BEARING VIBRATION ALARM SOUNDED. A FEW HOURS LATER, THE UNIT WAS SHUT DOWN BECAUSE THE VIBRATION WAS INCREASING. INSPECTION OF LOW PRESSURE TURBINE 2 FOUND THAT 18 BLADES HAD BEEN THROWN FROM STAGE H3 AND 14 STEPPLES WERE BROKEN OFF THE ROTATING DISC. ALSO, 22 STATIONARY BLADES WERE MISSING. SEVERAL HUNDRED STEPPLES CONTAINED CRACKS. PRELIMINARY CONCLUSION IS THAT THE FAILURE WAS CAUSED BY STRESS CORROSION WITH SODIUM HYDROXIDE BEING THE CORRODENT. TWO NEW LOW PRESSURE TURBINE AUTOMS HAVE BEEN INSTALLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RANCHO SECO (PWR) + TURBINE + STRESS CORROSION + FAILURE, EQUIPMENT + TURBINE BLADE, VIBRATION + CRACK + DAMAGE + REACTOR SHUTDOWN

109277
HYDRAULIC SNUBBER INSPECTION FOUND DEFICIENT AT RANCHO SECO
SACRAMENTO MUNICIPAL UTILITY DISTRICT, SACRAMENTO, CA
3 PGS. LTR W/AV 75-17 TO NRC DIRECTOR OF REGULATORY OPERATIONS, REGION V, DEC. 12, 1975, DOCKET 50-312, TYPE--
PWR, NRG--BEN, AE--BECHTEL

CAUSE - PERSONNEL ERRORS. REVIEW OF SURVEILLANCE REPORTS ON SAFETY SYSTEM HYDRAULIC SHAY SUPPRESSORS REVEALED THAT PREVIOUS INSPECTIONS WERE NOT PERFORMED ACCORDING TO PROCEDURE. PERSONNEL PERFORMING SURVEILLANCE DID NOT REPORT INACCESSIBILITY OF SNUBBERS OR INABILITY TO LOCATE SNUBBERS BUT LISTED THEM AS ACCEPTABLE. AUDITS WILL BE PERFORMED TO INSURE THAT ALL PROCEDURES ARE BEING FOLLOWED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RANCHO SECO (PWR) + SURVEILLANCE PROGRAM + SHOCK ABSORBER + SUPPORT STRUCTURE + PIPES AND PIPE FITTINGS + FAILURE, MAINTENANCE ERROR + REVIEW + PROCEDURES AND MANUALS

098711
FAILURE TO CONDUCT INCUR DETECTOR TRAVERSES ON SCHEDULE AT ROBINSON
CALIFORNIA POWER & LIGHT COMPANY
5 PAGES, LETTER TO DIRECTORATE OF REGULATORY OPERATIONS (AEC), JANUARY 3, 1975, DOCKET 50-261, TYPE--PWR, NRG--
WEST., AE--EDASCO

CAUSE - OPERATOR OVERSIGHT. AN APODS SCAN SEQUENCE WAS INITIATED BY CONTROL ROD MOTION. THE NEXT PROGRAMMED SCAN WAS NOT COMPLETED DUE TO JAMMING OF INCUR DETECTOR C. THE OPERATOR DID NOT NOTICE THAT THE SCAN SEQUENCE WAS INTERRUPTED DUE TO HIS PREOCCUPATION WITH THE RUNBACK OPERATIONAL MANEUVER. WHEN HE DID NOTICE IT, THE DETECTOR WAS CLEARED AND THE SCAN SEQUENCES

090711 UNCONTINUED

WERE REQUIRED. HOWEVER, HE DID NOT INITIATE A MANUAL SCAN WHICH IS REQUIRED TO RESTART THE SEQUENCE. THE DETECTION JAMMED AS A RESULT OF A PARTIAL FAILURE OF THE MECHANICAL WRAP OF THE DETECTION DRIVE CABLE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATION ERROR • INSTRUMENT, IN CORE • POWER DISTRIBUTION • ROBINSON 2 (PWR) • TEST INTERVAL

09242

REACTOR TRIP DUE TO LOSS OF INSTRUMENT BUSES AT ROBINSON 2

CAROLINA POWER & LIGHT COMPANY

9 PAGES, LETTER WITH REPORT TO AEC, REGION 2, JANUARY 19, 1975, DOCKET 50-261, TYPE--PWR, NRC--WEST., AE--EDASCO

CAUSE - BREAKER MALFUNCTION. WHILE OPERATING THE REACTOR AT 100% POWER, THE OPERATOR STARTED THE SECOND AUXILIARY BUILDING VENTILATION EXHAUST FAN FOR AN AIR FLOW READING. A REACTOR TRIP, SAFETY INJECTION, AND LOSS OF REC-6 AND 2 INSTRUMENT BUSES OCCURRED. THE DISCHARGE DAMPER ON THE FAN WAS LEAKING. BACK PRESSURE FROM THE OPERATING FAN CAUSED THE FAN TO RUN BACKWARD. WHEN IT WAS STARTED, A LARGE STARTING CURRENT RESULTED. FOR REASONS UNKNOWN, THIS CAUSED TRIPPING OF THE REC-6 SUPPLY BREAKER INSTEAD OF THE FAN BREAKER. THE DISCHARGE DAMPER WAS ADJUSTED AND BOTH BREAKERS EXAMINED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ACCIDENT, LOSS OF POWER • SCRAM, REACTOR • VENTILATION SYSTEM • SAFETY INJECTION • FAILURE, SEQUENTIAL • ROBINSON 2 (PWR) • CONTROL PANEL/ROOM • BREAKER • BLOWERS

093250

BORIC ACID TRANSFER PUMP FAILS AT ROBINSON 2

CAROLINA POWER & LIGHT COMPANY

3 PAGES, LETTER WITH REPORT 75/1 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 2, JANUARY 27, 1975, DOCKET 50-261, TYPE--PWR, NRC--WEST., AE--EDASCO

CAUSE - BROKEN SHAFT. THE PLANT WAS OPERATING AT 100% POWER WITH BORIC ACID TRANSFER PUMP A LINED UP TO RECIRCULATE THE BORON INJECTION TANK AND PUMP B LINED UP TO THE BORIC ACID BLENDER. PUMP A WAS FOUND TO BE TRIPPED. THE SHAFT HAD FAILED IN THE VICINITY OF THE IMPELLER KEYWAY. THE STATOR WINDING WAS SCORED. THIS IS BELIEVED TO HAVE RESULTED AFTER THE SHAFT FAILURE. THE PUMP WAS REPLACED WITH A SPARE PUMP. THESE ARE GARDNER CHENIERE MODEL G.E. 20R.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT • FAILURE, EQUIPMENT • POISON, SOLUBLE • CHEMICAL SHIP • ROBINSON 2 (PWR) • PUMPS

093570

PRESSURIZER LEVEL CHANNEL FAILS TO GENERATE TRIP SIGNAL AT ROBINSON 2

CAROLINA POWER & LIGHT COMPANY

3 PAGES, LETTER WITH REPORT 75/2 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 2, JANUARY 30, 1975, DOCKET 50-261, TYPE--PWR, NRC--WEST., AE--EDASCO

CAUSE - DEFECTIVE COMPARTOR. DURING TESTING WITH THE REACTOR AT 100% POWER, PRESSURIZER LEVEL CHANNEL 2 FAILED TO GENERATE A REACTOR TRIP SIGNAL OR A SAFETY INJECTION SIGNAL. CHECKS SHOWED THE COMPARTOR HAD MALFUNCTIONED. THE FILTER CAPACITOR HAD FAILED CAUSING THE +15 DC POWER SUPPLY TO INCREASED NOISE LEVEL. THE COMPARTOR WOULD OPERATE DURING BENCH TESTS BUT, WHEN THE LOOP NOISE WAS ADDED, IT WOULD NOT FUNCTION. A NEW COMPARTOR WAS INSTALLED. THE CAPACITOR WAS REPLACED IN THE DEFECTIVE UNIT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT • REACTOR SAFETY SYSTEM • PRESSURIZER • TEST, SYSTEM OPERABILITY • ROBINSON 2 (PWR) • ELECTRONIC FUNCTION UNITS • SENSORS, LEVEL

093608

COMPONENT COOLING PUMP FAILS TO START AT ROBINSON 2

CAROLINA POWER & LIGHT COMPANY

4 PAGES, LETTER WITH REPORT 75/3 TO DIRECTORATE OF REGULATORY OPERATIONS NRC, REGION 2, FEBRUARY 6, 1975, DOCKET 50-261, TYPE--PWR, NRC--WEST., AE--EDASCO

CAUSE - UNKNOWN. DURING THE USUAL ROUTINE OF SHAPPING AUXILIARY COMPONENT LOADS WHILE OPERATING AT 100% POWER, COMPONENT COOLING WATER PUMP INDICATOR LIGHT DID NOT INDICATE THE PUMP HAD STARTED. ABOUT 30 SECONDS LATER AN ALARM INDICATED AN OVERLOAD TRIP. THE MECHANICAL SEAL HAD FAILED. IT WAS REPLACED. HOWEVER THIS DID NOT CAUSE THE OVERLOAD. THE INDICATOR LIGHT WAS DEFECTIVE AND WAS REPLACED. IT IS THOUGHT THAT THE PUMP DISCHARGE CHECK VALVE WAS LEAKING CAUSING THE PUMP TO ROTATE BACKWARD. THE HIGH CURRENT REQUIRED TO REVERSE THE ROTATION CAUSED THE BREAKER TO TRIP.

003406 RELATINUED
 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

ROBINSON 2 (PWR) • AUXILIARY COOLING • AUXILIARY COOLING SYSTEM • PUMPS

102506
 BORIC ACID TRANSFER PUMP FAILS AT ROBINSON 2
 CAROLINA POWER & LIGHT COMPANY
 5 PAGES, LETTER WITH AD REPORT 75/5 TO U.S. NRC, REGION 2, MARCH 7, 1975, DOCKET 50-261, TYPE--PWR, NRC--
 WEST., AE--EASLO

CAUSE - UNKNOWN. DURING ROUTINE USE OF BORIC ACID TRANSFER PUMP B, THE PUMP STOPPED DUE TO
 ACTIVATION OF THE STRAP-ON THERMAL OUTPUT SWITCH. NO DEFECTIVE PARTS OR ABNORMAL CONDITIONS WERE
 FOUND DURING DISASSEMBLY AND INSPECTION. THE NEXT DAY THE PUMP MOTOR AGAIN OVERHEATED. NO CAUSE
 COULD BE FOUND. THE PUMP WAS REPLACED WITH A SPARE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

FAILURE, EQUIPMENT • SHUTDOWN SYSTEM, SECONDARY • CHEMICAL SHIM • ROBINSON 2 (PWR) • PUMPS

101403
 COMBATANT PERSONNEL RELIEVES UNDERPRESSURE AT ROBINSON 2
 CAROLINA POWER & LIGHT COMPANY
 6 PAGES, LETTER WITH AD REPORT 75/6 TO U.S. NRC, REGION 2, MARCH 27, 1975, DOCKET 50-261, TYPE--PWR, NRC--
 WEST., AE--EASLO

CAUSE - STAY TIME IN HIGH FIELD TOO LONG. TRANSFER OF SPENT RESIN FROM THE SPENT RESIN STORAGE
 TANK TO A SPENT RESIN TRANSPORT VEHICLE HAD JUST BEEN COMPLETED. ONE OF THE CONTRACTOR
 PERSONNEL ENTERED A LOCAL TO REMAIN FIELD TO DISCONNECT THE TRANSFER HOSE. A RADIATION CONTROL
 TECHNICIAN COVERED THE WORK. THE TASK REQUIRED ABOUT 2 MINUTES. HOWEVER, A CHECK OF THE
 NUMBERS DOCKET CHARGE INDICATED HE HAD RECEIVED MORE THAN 300 MREM LIMIT FOR A VISITOR. HE
 WAS IMMEDIATELY REMOVED FROM THE AREA. THE FEASIBILITY OF USING ADDITIONAL SHIELDING IS BEING
 STUDIED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

MAINTENANCE AND REPAIR • WASTE HANDLING • PERSONNEL EXPOSURE, RADIATION • RESIN • ROBINSON 2 (PWR)

101701
 DIESEL GENERATOR TRIPS ON LOW LUBE OIL PRESSURE AT ROBINSON 2
 CAROLINA POWER & LIGHT COMPANY
 3 PAGES, LETTER WITH AD REPORT 75/7 TO U.S. NRC, REGION 2, APRIL 17, 1975, DOCKET 50-261, TYPE--PWR, NRC--
 WEST., AE--EASLO

CAUSE - DIRTY FILTERS. DURING TESTING OF THE EMERGENCY DIESELS WITH THE REACTOR AT 100% POWER, 1
 OF THE 2 STARTED BUT TRIPPED ON LOW LUBE OIL PRESSURE. THE LOW PRESSURE WAS CAUSED BY LUBE OIL
 FILTER HIGH DIFFERENTIAL PRESSURE (80 PSI) RESULTING FROM DIRTY FILTERS. AFTER THE FILTERS WERE
 REPLACED, THE PRESSURE DIFFERENTIAL WAS 3 PSI. PROCEDURES WERE MODIFIED TO REQUIRE DIFFERENTIAL
 PRESSURE CHECKS OF THE FILTERS EACH TIME THE DIESEL IS TESTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

EMERGENCY POWER, ELECTRIC • COLD • TEST, SYSTEM OPERABILITY • FAILURE, MAINTENANCE ERROR • ROBINSON 2 (PWR) •
 LUBRICATION • ENGINES, INTERNAL COMBUSTION • GENERATOR, DIESEL • FILTERS

102004
 MAIN COOLANT PUMP SEAL FAILS AT ROBINSON 2
 NUCLEAR REGULATORY COMMISSION
 2 PAGES, NOTIFICATION OF AN INCIDENT OR OCCURRENCE NO. 149, MAY 6, 1975, DOCKET 50-261, TYPE--PWR, NRC--WEST.,
 AE--EASLO

CAUSE - UNKNOWN. THE UNIT WAS OPERATING AT 100% POWER WHEN LEAKAGE FROM THE FIRST STAGE PUMP SEAL
 RESULTED IN AN ALARM. THE POWER LEVEL WAS REDUCED QUICKLY AND THE PUMP SHUT DOWN. ABOUT 200,000
 GALLONS OF PRIMARY COOLANT WATER WAS DISCHARGED INTO THE CONTAINMENT STRUCTURE. PRESSURIZER
 LEVEL WAS MAINTAINED BY USE OF THE 3 CHARGING PUMPS AND INTERMITTENT MANUAL ACTIVATION OF THE
 SAFETY INJECTION SYSTEM. MAXIMUM LEAKAGE RATE WAS ESTIMATED TO BE 500 GPM WHICH EXCEEDS THE
 NORMAL CAPACITY OF THE CHARGING SYSTEM. FOLLOWING THE REACTOR TRIP WHEN THE PUMP WAS RESTARTED
 TO EQUALIZE TEMPERATURE, THE SECOND STAGE SEAL ALSO FAILED. CAUSE IS UNKNOWN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

ROBINSON 2 (PWR) • SEAL • PUMPS • MAIN COOLING SYSTEM • LEAK • CONTAINMENT • REACTOR SHUTDOWN • LEAK RATE •
 FAILURE, EQUIPMENT

103077

REACTOR COOLANT PUMP SEAL SYSTEM FAILS AT ROBINSON 2

CAROLINA POWER & LIGHT COMPANY

3 PAGES, LETTER WITH AD 75-9 TO NRC DIV. OF REGULATORY OPERATIONS, REGION 2, MAY 12, 1975, DCKET 50-261, TYPE--PHN, HFG--WEST., AE--EASCO

CAUSE - NOT STATED. THE PLANT HAD JUST REACHED FULL POWER EARLY IN THE MORNING FOLLOWING A MAINTENANCE OUTAGE. THAT EVENING REACTOR COOLANT PUMP C SEAL LEAKOFF OSCILLATED FULL RANGE SEVERAL TIMES AND STABILIZED AT A FLOW ABOVE 6 GPM. A LOAD REDUCTION OF 100% WAS STARTED TO SAVE THE PUMP. A REACTOR TRIP OCCURRED. THE PUMP WAS LATER RESTARTED TO AID IN COOLDOWN. BOTH OTHER SEALS FAILED AT THIS TIME. FAILURE CAUSED OVERHEATING OF THE PUMP SHAFT AND SEAL HOUSING. THESE WILL BE REPAIRED. PROPER OPERATION OF SAFEGUARDS EQUIPMENT AND ACTIONS TAKEN BY THE OPERATORS PREVENTED MORE EXTENSIVE DAMAGE AFTER THE SEAL FAILURE. ALL SYSTEMS FUNCTIONED AS DESIGNED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D.C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ROBINSON 2 (PHN) + INCIDENT + SEAL + PUMPS + MAIN COOLING SYSTEM + LEAK + REACTOR COOLANT + FAILURE, COMPONENT + OPERATION ACTION + REACTOR SHUTDOWN + SAFETY INJECTION + PRESSURE TRANSIENT

103199

Boric Acid Transfer Pump Fails at Robinson 2

CAROLINA POWER & LIGHT CO.

3 PAGES, LETTER WITH AD 75-13 TO U.S. NRC, REGION 2, JUNE 2, 1975, DCKET 50-261, TYPE--PHN, HFG--WEST., AE--EASCO

CAUSE - BREAKER TRIP. WITH THE REACTOR IN COLD SHUTDOWN, BORIC ACID TRANSFER PUMP B FAILED WHILE LINED UP TO RECIRCULATE BORIC ACID TANK B. THE SHAFT BROKE AT THE KEYWAY CAUSING THE BREAKER TO TRIP. THE PUMP WAS REBUILT FROM SPARE PARTS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ROBINSON 2 (PHN) + PUMPS + CHEMICAL SHUT + POISON, SOLUBLE + FAILURE, COMPONENT + FAILURE, DESIGN ERROR

103404

REACTOR COOLANT SYSTEM OXYGEN CONCENTRATION EXCEEDS LIMITS AT ROBINSON 2

CAROLINA POWER & LIGHT CO., RALEIGH, N.C.

2 PAGES, LETTER WITH AD REPORT 75-11 TO NRC, REGION 2, JUNE 6, 1975, DCKET 50-261, TYPE--PHN, HFG--WEST., AE--EASCO

CAUSE - PERSONNEL ERROR. A DAILY CHECK OF THE VOLTAGE ACROSS 3 ZENER DIODES WAS TO BE MADE UNTIL SUFFICIENT EVIDENCE WAS ACCUMULATED TO ASSURE RELIABLE OPERATION. DURING AN INTERNAL AUDIT, NO DATA WAS FOUND FOR 2 DAYS AND FOR ONLY 6 DAYS DURING A 4 WEEK PERIOD. THE TECHNICIAN WAS ON VACATION DURING THE 2 DAY PERIOD. LATER, HE BELIEVED HE HAD ACCUMULATED SUFFICIENT INFORMATION SO HE STOPPED TAKING DATA. DATA ACCUMULATION WAS REINSTITUTED UNTIL AN ENGINEER TERMINATED THE PROGRAM.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ROBINSON 2 (PHN) + OXYGEN + CONCENTRATION + MAIN COOLING SYSTEM + REACTOR COOLANT + REACTOR SHUTDOWN

103403

REVISED REPORT ON REACTOR COOLANT PUMP SEAL SYSTEM FAILURE AT ROBINSON 2

CAROLINA POWER & LIGHT CO., RALEIGH, N.C.

10 PAGES, LETTER WITH AD REPORT 75-4 TO NRC, REGION 2, JUNE 12, 1975, DCKET 50-261, TYPE--PHN, HFG--WEST., AE--EASCO

CAUSE - UNKNOWN. WHILE OPERATING AT FULL POWER, SEAL B LEAK OFF FLOW FROM REACTOR COOLANT PUMP C INCREASED TO A FLOW GREATER THAN 6 GPM. THE SEALS IN THIS PUMP HAD BEEN REPLACED ONE WEEK EARLIER. THE REACTOR WAS SHUTDOWN. SEAL WATER FLOW COULD NOT BE MAINTAINED IN EITHER OF THE OTHER 2 PUMPS TO THEY WERE SHUTDOWN. WHEN PUMP C WAS RESTARTED TO EQUALIZE TEMPERATURE AND BORON CONCENTRATION, THE OTHER 2 SEALS FAILED. NO CAUSE WAS FOUND FOR SEAL FAILURE. HAD THE LEAK OFF ISOLATION VALVE TO PUMP C BEEN SHUT IMMEDIATELY UPON INDICATION OF DAMAGE, SEAL WATER FLOW TO THE OTHER PUMPS COULD HAVE BEEN MAINTAINED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ROBINSON 2 (PHN) + SEAL + PUMPS + MAIN COOLING SYSTEM + FAILURE, EQUIPMENT + LEAK + REACTOR SHUTDOWN + INCIDENT + RADIOACTIVITY RELEASE

104213

Boric Acid Transfer Pump Fails at Robinson 2

CAROLINA POWER & LIGHT COMPANY, RALEIGH

3 PAGES, LETTER WITH AD 75-12 TO U.S. NRC, REGION 2, JULY 10, 1975, DCKET 50-261, TYPE--PHN, HFG--WEST., AE--

104213 PLUMBERSHIP
CAMEL

CAUSE - OTHER SHUT. WHILE THE REACTION WAS OPERATING AT 100% POWER, ACID ACID TRANSFER PUMP A FAILED WHILE RECALIBRATING ACID TANK A WITH THE SHUT INJECTION TANK. THE PUMP SHUT WAS SHUTTER AT THE REACTOR. THIS TYPE OF FAILURE HAS OCCURRED SEVERAL TIMES. A NEW PUMP IS IN ORDER. THE DEFECTIVE PUMP WAS REBUILT AND RETURNED TO SERVICE IN LESS THAN 24 HOURS.

AVAILABILITY - THE PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 130 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ROBINSON 2 (PUMP + PUMPS) + PLUMBERSHIP SHUT + POSITION, VALVE + FAILURE, OF SHUT DOWN + FAILURE, EQUIPMENT + OTHER

104090
JUNCTION PUMP UP LAMP AT ROBINSON 2
CAMEL PUMP & LIGHT LAMP, BELL

5 PAGES, LETTER WITH AOM 75-11 TO U.S. NRC, REGION 2, JULY 10, 1975, Docket 50-201, TYPE--PWR, NRC--WEST, AT--EASCO

CAUSE - REPAIR REPAIRING TANK. DURING A UNIT SHUT TO REPAIR A REACTION COOLANT PUMP, A LARGE WORK FORCE WAS USED BECAUSE OF THE HIGH RADIATION LEVELS INCURRED. IN ACCORDANCE WITH RADIATION RULES, THE WORK FOR THE INDIVIDUAL WAS ASSIGNED TO ANOTHER INDIVIDUAL OF SIMILAR RANK. THE WORKING INDIVIDUALS NUMBER WAS NOT CHECKED. AS A RESULT, THE INDIVIDUAL RECEIVED A QUANTITATIVE WORK BODY EXPOSURE OF 3000 MREM WHICH EXCEEDS THE 2000 MREM/QUARTER LIMIT. THE NUMBER WAS OBTAINED FROM RADIATION MONITOR. THE PROGRAM WAS ADVISED BY REPAIRING CROSS CHECKING OF RECORDS AND REPAIRS.

AVAILABILITY - THE PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 130 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ROBINSON 2 (PUMP) + MAINTENANCE AND REPAIR + RADIATION EXPOSURE, RECORD KEEPING + FAILURE, ADMINISTRATIVE CONTROL + PERSONNEL EXPOSURE, RADIATION

104214
BOM VALVE FAILS TO OPEN AT ROBINSON 2
CAMEL PUMP & LIGHT LAMP, BELL
5 PAGES, LETTER WITH AOM 75-11 (REVISION) TO U.S. NRC, REGION 2, JULY 11, 1975, Docket 50-201, TYPE--PWR, NRC--WEST, AT--EASCO

CAUSE - TORQUE SWITCH UP UP ADJUSTMENT. DURING A UNIT SHUT WHILE ALIGNING THE BOM SYSTEM FOR NORMAL POWER OPERATION, A VALVE FAILED TO OPEN ON SIGNAL. A REACTION LOCKDOWN WAS COMMENCED. THE OPERATOR TORQUE SWITCH WAS UP ADJUSTMENT CAUSING THE VALVE TO BE JAMMED ON THE SEAT. THE VALVE WAS MANUALLY OPENED AND THE TORQUE SWITCH ADJUSTED. IT WAS TESTED SATISFACTORILY. THE SHUT WAS RECOMMENDED.

AVAILABILITY - THE PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 130 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ROBINSON 2 (PUMP) + VALVES + SHUTDOWN COOLING SYSTEM + FAILURE, EQUIPMENT + FAILURE, MAINTENANCE (PART) + INSTRUMENT, SWITCH + SET POINT + VALVE OPERATORS

104037
AUXILIARY FEEDWATER PUMP DISCHARGE VALVE FAILS TO OPEN AT ROBINSON 2
CAMEL PUMP & LIGHT LAMP, BELL
5 PAGES, LETTER WITH AOM 75-10 TO U.S. NRC, REGION 2, JULY 25, 1975, Docket 50-201, TYPE--PWR, NRC--WEST, AT--EASCO

CAUSE - TORQUE SWITCH MALFUNCTION. DURING A TEST WITH THE REACTION AT 100% POWER, THE DISCHARGE VALVE UP THE STEAM DRIVEN FEEDWATER PUMP FAILED TO OPEN. THE VALVE WAS FOUND IN ITS SEAT AND THE LIMITING OPERATOR RELEASED UNIT ON THERMAL OVERLOADS WITH THE TORQUE SWITCH CLOSED. INTERNAL INSPECTION REVEALED THAT THE BELLEVILLE SPRING WAS FILLED WITH GREASE AND THE SHOT IN WHICH IT RIDES WAS MARKED BY A SMALL BURN. BOTH OF THESE COULD CHANGE THE SPRING STIFFNESS. THE BURN WAS REMOVED AND THE GREASE CLEANED FROM THE SPRING PACK.

AVAILABILITY - THE PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 130 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ROBINSON 2 (PUMP) + VALVES + OPERATOR + TEST, SYSTEM OPERABILITY + VALVE OPERATORS + INSTRUMENT, SWITCH + COMMUNICATION + PLAN

104205
AUXILIARY FEEDWATER PUMP DISCHARGE VALVE FAILS TO OPEN AT ROBINSON 2
CAMEL PUMP & LIGHT LAMP, BELL
5 PAGES, LETTER WITH AOM 75-10 TO U.S. NRC, REGION 2, JULY 25, 1975, Docket 50-201, TYPE--PWR, NRC--WEST, AT--EASCO

CAUSE - FAULTY TORQUE SWITCH. DURING A TEST WHILE OPERATING AT FULL POWER, A STEAM DRIVEN AUXILIARY FEEDWATER PUMP DISCHARGE VALVE FAILED TO OPEN. THE THERMAL OVERLOAD WAS TRIPPED AND THE VALVE WAS ON ITS SEAT. THE THERMAL OVERLOAD WAS RESET AND THE TORQUE SWITCH RESET. INSPECTION OF THE SWITCH REVEALED THAT THE BELLEVILLE SPRING WAS FILLED WITH GREASE AND THE SHOT

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED DATE 07-19-2008 BY 60322 UCBAW/BJS

1. Method

U.S. DEPARTMENT OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D. C. 20535

Approved: _____
Special Agent in Charge

1. 1970-1971, 1972-1973, 1974-1975, 1976-1977, 1978-1979, 1980-1981, 1982-1983, 1984-1985, 1986-1987, 1988-1989, 1990-1991, 1992-1993, 1994-1995, 1996-1997, 1998-1999, 2000-2001, 2002-2003, 2004-2005, 2006-2007, 2008-2009, 2010-2011, 2012-2013, 2014-2015, 2016-2017, 2018-2019, 2020-2021, 2022-2023, 2024-2025, 2026-2027, 2028-2029, 2030-2031, 2032-2033, 2034-2035, 2036-2037, 2038-2039, 2040-2041, 2042-2043, 2044-2045, 2046-2047, 2048-2049, 2050-2051, 2052-2053, 2054-2055, 2056-2057, 2058-2059, 2060-2061, 2062-2063, 2064-2065, 2066-2067, 2068-2069, 2070-2071, 2072-2073, 2074-2075, 2076-2077, 2078-2079, 2080-2081, 2082-2083, 2084-2085, 2086-2087, 2088-2089, 2090-2091, 2092-2093, 2094-2095, 2096-2097, 2098-2099, 2100-2101, 2102-2103, 2104-2105, 2106-2107, 2108-2109, 2110-2111, 2112-2113, 2114-2115, 2116-2117, 2118-2119, 2120-2121, 2122-2123, 2124-2125, 2126-2127, 2128-2129, 2130-2131, 2132-2133, 2134-2135, 2136-2137, 2138-2139, 2140-2141, 2142-2143, 2144-2145, 2146-2147, 2148-2149, 2150-2151, 2152-2153, 2154-2155, 2156-2157, 2158-2159, 2160-2161, 2162-2163, 2164-2165, 2166-2167, 2168-2169, 2170-2171, 2172-2173, 2174-2175, 2176-2177, 2178-2179, 2180-2181, 2182-2183, 2184-2185, 2186-2187, 2188-2189, 2190-2191, 2192-2193, 2194-2195, 2196-2197, 2198-2199, 2200-2201, 2202-2203, 2204-2205, 2206-2207, 2208-2209, 2210-2211, 2212-2213, 2214-2215, 2216-2217, 2218-2219, 2220-2221, 2222-2223, 2224-2225, 2226-2227, 2228-2229, 2230-2231, 2232-2233, 2234-2235, 2236-2237, 2238-2239, 2240-2241, 2242-2243, 2244-2245, 2246-2247, 2248-2249, 2250-2251, 2252-2253, 2254-2255, 2256-2257, 2258-2259, 2260-2261, 2262-2263, 2264-2265, 2266-2267, 2268-2269, 2270-2271, 2272-2273, 2274-2275, 2276-2277, 2278-2279, 2280-2281, 2282-2283, 2284-2285, 2286-2287, 2288-2289, 2290-2291, 2292-2293, 2294-2295, 2296-2297, 2298-2299, 2300-2301, 2302-2303, 2304-2305, 2306-2307, 2308-2309, 2310-2311, 2312-2313, 2314-2315, 2316-2317, 2318-2319, 2320-2321, 2322-2323, 2324-2325, 2326-2327, 2328-2329, 2330-2331, 2332-2333, 2334-2335, 2336-2337, 2338-2339, 2340-2341, 2342-2343, 2344-2345, 2346-2347, 2348-2349, 2350-2351, 2352-2353, 2354-2355, 2356-2357, 2358-2359, 2360-2361, 2362-2363, 2364-2365, 2366-2367, 2368-2369, 2370-2371, 2372-2373, 2374-2375, 2376-2377, 2378-2379, 2380-2381, 2382-2383, 2384-2385, 2386-2387, 2388-2389, 2390-2391, 2392-2393, 2394-2395, 2396-2397, 2398-2399, 2400-2401, 2402-2403, 2404-2405, 2406-2407, 2408-2409, 2410-2411, 2412-2413, 2414-2415, 2416-2417, 2418-2419, 2420-2421, 2422-2423, 2424-2425, 2426-2427, 2428-2429, 2430-2431, 2432-2433, 2434-2435, 2436-2437, 2438-2439, 2440-2441, 2442-2443, 2444-2445, 2446-2447, 2448-2449, 2450-2451, 2452-2453, 2454-2455, 2456-2457, 2458-2459, 2460-2461, 2462-2463, 2464-2465, 2466-2467, 2468-2469, 2470-2471, 2472-2473, 2474-2475, 2476-2477, 2478-2479, 2480-2481, 2482-2483, 2484-2485, 2486-2487, 2488-2489, 2490-2491, 2492-2493, 2494-2495, 2496-2497, 2498-2499, 2500-2501, 2502-2503, 2504-2505, 2506-2507, 2508-2509, 2510-2511, 2512-2513, 2514-2515, 2516-2517, 2518-2519, 2520-2521, 2522-2523, 2524-2525, 2526-2527, 2528-2529, 2530-2531, 2532-2533, 2534-2535, 2536-2537, 2538-2539, 2540-2541, 2542-2543, 2544-2545, 2546-2547, 2548-2549, 2550-2551, 2552-2553, 2554-2555, 2556-2557, 2558-2559, 2560-2561, 2562-2563, 2564-2565, 2566-2567, 2568-2569, 2570-2571, 2572-2573, 2574-2575, 2576-2577, 2578-2579, 2580-2581, 2582-2583, 2584-2585, 2586-2587, 2588-2589, 2590-2591, 2592-2593, 2594-2595, 2596-2597, 2598-2599, 2600-2601, 2602-2603, 2604-2605, 2606-2607, 2608-2609, 2610-2611, 2612-2613, 2614-2615, 2616-2617, 2618-2619, 2620-2621, 2622-2623, 2624-2625, 2626-2627, 2628-2629, 2630-2631, 2632-2633, 2634-2635, 2636-2637, 2638-2639, 2640-2641, 2642-2643, 2644-2645, 2646-2647, 2648-2649, 2650-2651, 2652-2653, 2654-2655, 2656-2657, 2658-2659, 2660-2661, 2662-2663, 2664-2665, 2666-2667, 2668-2669, 2670-2671, 2672-2673, 2674-2675, 2676-2677, 2678-2679, 2680-2681, 2682-2683, 2684-2685, 2686-2687, 2688-2689, 2690-2691, 2692-2693, 2694-2695, 2696-2697, 2698-2699, 2700-2701, 2702-2703, 2704-2705, 2706-2707, 2708-2709, 2710-2711, 2712-2713,

[illegible]

44-38861-117 - Not Public Document under E.O. 13526, 6/8/2013. 10/10/2013 10:10:10 AM -- 10/10/2013 10:10:10 AM

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED
DATE 08-10-2010 BY 60322 UCBAW

~~SECRET~~

ATTENTION: This report contains information concerning the internal security of the United States. It is to be controlled, stored, handled, transmitted, and disposed of in accordance with the provisions of Executive Order 11652, dated August 17, 1956, and the provisions of the Federal Bureau of Investigation Manual, Section 1-2.2, dated May 2, 1962.

LONG ISLAND POWER & LIGHT CO., INC.

* Pub. Lia. #249 12-13 to U.S. Sen. William H. J. 1. 1975, 20041 12/201, 1979-000, 002--0051, 04--00000

[illegible]

ADDITIONAL - THE PUBLIC DOCUMENTS ACT, 1977 - please, authorities, J. G. 201-136 (8/1/78) -- my name
Lundin B. J.

[illegible]

101900

100 MARINE SOUTH PACIFIC COMPANY, INCORPORATED IN NEW JERSEY

LEADING FROM 6:10 AM TO 6:30 PM, D.C.

• 761. 118 4000 50-201/75-10 10 1000 01001-00010 20 400000000 000000000 000000 11. 1000. 11. 1000. 000001 20-
201. 1000-0000. 0000-0000. 0000-0000

[illegible]

AVAILABILITY - THE PUBLIC DOCUMENT REPORT, 1977 IN STATUS, WASHINGTON, D. C. 20540 100 (1977)0000 -- 000000
(1977) 0000

~~ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED EXCEPT WHERE SHOWN OTHERWISE~~

10/2/2004

Consistent indicator violated at minimum 1

CAROLINA POWER & LIGHT CO., 401160, N.C.

• Pub. in WASH POST 10-20/75-1/ 16 p.1. WDC, 44610th St, Room 12, 1975. WDC, 10-20, 1975--000, 00--00, 00--00, 00--00

Copy - mechanical and electronic files. Also the plan is to furnish all the necessary data
concerning the physical and the chemical data, the physical and the chemical data, the physical and the chemical data.
The data is to be furnished in the form of a report, and the data is to be furnished in the form of a report.

100700

CAUSE - THE JUMP JUMPER WAS NOT OPEN. THE OUTER JUMPER ENCLOSURES COULD NOT BE SECURED. ATTEMPTS TO OPEN THE OUTER JUMPER RESULTED IN IT JAMMING 2 TIMES OPEN. THE JUMPER JUMPER OPERATIONAL MECHANISM WAS NOT BEHIND THE OUTER JUMPER. THE OUTER JUMPER WAS OPENED FROM WITHIN THE JUMPER. A JUMPER BEHIND THE OUTER JUMPER WAS NOT FOUND. REPAIRS WERE MADE. CONTINUITY WAS VERIFIED FOR 10 MINUTES.

AVAILABILITY - THE PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$1.00

ADDITION 2 (PART) - PLACEMENT INSTABILITY - FAILURE, EQUIPMENT - CONTINUITY AND LCA - INSTRUMENT, INTERNAL - APPROPRIATE ACTION

100700

ADDITION 2 (PART) - PLACEMENT INSTABILITY - FAILURE, EQUIPMENT - CONTINUITY AND LCA - INSTRUMENT, INTERNAL - APPROPRIATE ACTION

ADDITION 2 (PART) - PLACEMENT INSTABILITY - FAILURE, EQUIPMENT - CONTINUITY AND LCA - INSTRUMENT, INTERNAL - APPROPRIATE ACTION

ADDITION 2 (PART) - PLACEMENT INSTABILITY - FAILURE, EQUIPMENT - CONTINUITY AND LCA - INSTRUMENT, INTERNAL - APPROPRIATE ACTION

CAUSE - EXHAUSTED SAFETY CONTACTS. DURING A TEST TO VERIFY SAFETY INJECTION EQUIPMENT SEQUENCING WITH THE PLANT OPERATING FOR DEFECTIVE. AUXILIARY FEEDWATER PUMP A FAILED TO START. THREE SETS OF CONTACTS IN THE LOCAL/MANUAL SWITCH AT THE LOCAL CONTROL STATION WERE FOUND TO BE JAMMED. THE CONTACTS WERE CLEANED AND THE PUMP OPERATED SATISFACTORILY. THE EXCESSIVE JAMMING OF CONTACTS IS BELIEVED TO BE A RESULT OF HIGH HUMIDITY IN THE ROOM.

AVAILABILITY - THE PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$1.00

ADDITION 2 (PART) - PLACEMENT INSTABILITY - FAILURE, EQUIPMENT - CONTINUITY AND LCA - INSTRUMENT, INTERNAL - APPROPRIATE ACTION

100700

ADDITION 2 (PART) - PLACEMENT INSTABILITY - FAILURE, EQUIPMENT - CONTINUITY AND LCA - INSTRUMENT, INTERNAL - APPROPRIATE ACTION

ADDITION 2 (PART) - PLACEMENT INSTABILITY - FAILURE, EQUIPMENT - CONTINUITY AND LCA - INSTRUMENT, INTERNAL - APPROPRIATE ACTION

ADDITION 2 (PART) - PLACEMENT INSTABILITY - FAILURE, EQUIPMENT - CONTINUITY AND LCA - INSTRUMENT, INTERNAL - APPROPRIATE ACTION

CAUSE - LACK OF COMMUNICATION. A SAMPLE OF SAFETY INJECTION ACCUMULATOR B INDICATED A SHORT CIRCULATION OF 1015 PPM WHICH IS BELOW THE LIMIT. THE CONTROL ROOM WAS NOTIFIED. THE SHORT CIRCULATION WAS NOT IN THE PLANT AREA AND THE MESSAGE WAS NOT RELAYED TO MEN. THE CONTROL OPERATION DID NOT ALLOW THE SHORT CIRCULATION AND FOR NO ACTION. A SHORT JUMP SAMPLE TAKEN 4 HOURS LATER INDICATED 1017 PPM. THIS TIME THE JUMPER RECEIVED THE NOTICE AND CALLED THE SUPERVISOR. THE JUMPER WAS PARTLY OPENED AND REFILLED FROM THE DEFECTIVE WATER STORAGE TANK. CONCENTRATION WAS THEN 1001 PPM. THE MESSAGE WAS AT THE PLANT FOR PHYSICAL TESTING FOLLOWING REPAIRING.

AVAILABILITY - THE PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$1.00

ADDITION 2 (PART) - PLACEMENT INSTABILITY - FAILURE, EQUIPMENT - CONTINUITY AND LCA - INSTRUMENT, INTERNAL - APPROPRIATE ACTION

100700

ADDITION 2 (PART) - PLACEMENT INSTABILITY - FAILURE, EQUIPMENT - CONTINUITY AND LCA - INSTRUMENT, INTERNAL - APPROPRIATE ACTION

ADDITION 2 (PART) - PLACEMENT INSTABILITY - FAILURE, EQUIPMENT - CONTINUITY AND LCA - INSTRUMENT, INTERNAL - APPROPRIATE ACTION

ADDITION 2 (PART) - PLACEMENT INSTABILITY - FAILURE, EQUIPMENT - CONTINUITY AND LCA - INSTRUMENT, INTERNAL - APPROPRIATE ACTION

CAUSE - GROUND FAULT. WHILE THE UNIT WAS AT 20 PPM DURING STARTUP TESTS FOLLOWING REPAIRING. ONE CHANNEL OF LIMITATION PROTECTION CHANNEL WAS FOUND IMPROPERLY DURING TESTING. PERSONNEL FAILED TO RECOGNIZE THIS AS A WARNING CONDITION AND DID NOT INITIATE A COLD STARTUP. THE JUMPER WAS ON THE COMPUTER AND ALARM. IT WAS REPLACED AND THE CHANNEL RETURNED TO SERVICE WITHIN 10 MINUTES.

AVAILABILITY - THE PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$1.00

ADDITION 2 (PART) - PLACEMENT INSTABILITY - FAILURE, EQUIPMENT - CONTINUITY AND LCA - INSTRUMENT, INTERNAL - APPROPRIATE ACTION

100700

ADDITION 2 (PART) - PLACEMENT INSTABILITY - FAILURE, EQUIPMENT - CONTINUITY AND LCA - INSTRUMENT, INTERNAL - APPROPRIATE ACTION

ADDITION 2 (PART) - PLACEMENT INSTABILITY - FAILURE, EQUIPMENT - CONTINUITY AND LCA - INSTRUMENT, INTERNAL - APPROPRIATE ACTION

ADDITION 2 (PART) - PLACEMENT INSTABILITY - FAILURE, EQUIPMENT - CONTINUITY AND LCA - INSTRUMENT, INTERNAL - APPROPRIATE ACTION

CAUSE - MANUFACTURING PROCESS. AS A RESULT OF FINDING A LINEAR INDICATION IN A COMPONENT COOLING JUMP PIPE, ALL PIPING IN THE JUMP MATERIAL, DIAPHRAGM, AND SCHEMEL WAS INSPECTED. ONLY THE OTHER JUMP PIPE WAS FOUND TO HAVE A LINEAR INDICATION. THESE INDICATIONS EXTENDED INTO THE PIPE WALL FROM 0.000 TO 0.010 INCH. METALLURGICAL INSPECTION REVEALED THAT THE DEFECTS WERE

10000 PLANTING

EXHAUST MANIFOLD SURFACE LAPS EXTENDING INTO THE PIPING IN A SPIRAL PATTERN. THE DEFECTS WERE LIMITED TO ONE HEAD. THEY RESULTED FROM THE MANUFACTURING PROCESS. BOTH SPARE PIECES WERE REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SALFN 1 (PWR) + CONSTRUCTION + PIPES AND PIPE FITTINGS + STEEL + FAILURE, FABRICATION ERROR + FAILURE, PIPE + OPER. + TEST, NONSTRUCTIVE + AUXILIARY COOLING SYSTEM

10005

CRANE MANUFACTURING CRANE AUXILIARY PUMPS DEFECTIVE AT SALFN 1 AND 2

PUBLIC SERVICE ELECTRIC AND GAS COMPANY, N.J.

3 PAGES, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, JANUARY 20, 1975, Docket 50-272/311, TYPE--PWR, REG--WEST, AG--PUBLIC SERVICE OF NJ

CAUSE - CASTING DEFECTS. ANNUAL CRANE INSPECTION REVEALED SEVERAL LINEAR INDICATIONS IN THE AUXILIARY PUMPS OF BOTH CRANES. RADIOGRAPHS SHOWED THAT SEVERAL OF THE INDICATIONS WERE OF SUCH MAGNITUDE TO BE EVALUATED AS LAUSE FOR REJECTION OF THE AUXILIARY PUMPS. THESE PUMPS HAD BEEN ULTRASONIC TESTED BY CRANE INSPECTION SERVICE. INAPPROPRIATE STANDARDS OF ACCEPTANCE WERE USED AND NO DEFECTS WERE REPORTED IN THE MATERIAL. REPLACEMENT PUMPS WILL BE OBTAINED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + PLAN + FAILURE, FABRICATION ERROR + TEST, NONSTRUCTIVE + QUALITY ASSURANCE + SALFN 1 (PWR) + SALFN 2 (PWR) + CONSTRUCTION + CRANE

10016

DIESEL GENERATOR EXHAUST VALVE MODIFICATION AT SALFN 1 AND 2

PUBLIC SERVICE ELECTRIC & GAS COMPANY, N.J.

2 PAGES, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, MARCH 17, 1975, Docket 50-272/311, TYPE--PWR, REG--WEST, AG--PUBLIC SERV.

CAUSE - FABRICATION DEFICIENCY. OPERATING EXPERIENCE ON CANADIAN LOCOMOTIVES SHOWED FAILURES OCCURRING ON THE EXHAUST VALVES MANUFACTURED BY EATON CORP. THAT WERE USED IN ALCO DIESELS. THE MILLING PROCESS USED TO STRAIGHTEN THE VALVES INTRODUCED INTERNAL STRESSES IN EXCESS OF 5000 PSI TENILE AT THE FRACURE LOCATION. STRAIGHTENING BY BENDING ELIMINATED THE STRESSES. ALL EXHAUST VALVE IN THE SALFN DIESELS WILL BE REMOVED BY ALCO AND REPLACED WITH VALVES MANUFACTURED WITH THE NEWLY ADOPTED PROCESS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

STRESS + MODIFICATION + FAILURE, FABRICATION ERROR + SALFN 1 (PWR) + OPERATING EXPERIENCE + SALFN 2 (PWR) + FAILURE, COMPONENT + VALVES + ENGINES, INTERNAL COMBUSTION + GENERATION, DIESEL

10052

DIESEL GENERATOR HEAT EXCHANGER WATER BOX HEADS LEAK AT SALFN 1 AND 2

PUBLIC SERVICE ELECTRIC & GAS COMPANY, N.J.

2 PAGES, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, MAY 30, 1975, Docket 50-272/311, TYPE--PWR, REG--WEST, AG--PUBLIC SERVICE

CAUSE - CASTING DEFECTS. DURING HYDROSTATIC TESTING OF UNIT 1 SERVICE WATER SYSTEM, WATER WAS OBSERVED TO BE LEAKING FROM 3 OF THE 4 EMERGENCY DIESEL GENERATOR HEAT EXCHANGER WATER BOX HEADS. ZONES OF SCATTERED SPRINKLING AND WAS MORE POSITIVE WITH DEFECTS AS LARGE AS 3/16 IN. IN DIAMETER WERE FOUND. A DEFECTIVE HEAD WAS FOUND ON UNIT 2. THE 4 DEFECTIVE HEADS WERE RETURNED TO THE VENDOR FOR REPLACEMENT. THREE ACCEPTABLE HEADS FROM UNIT 2 WERE INSTALLED IN UNIT 1.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SALFN 1 (PWR) + SALFN 2 (PWR) + CONSTRUCTION + HEAT EXCHANGERS + GENERATION, DIESEL + ENGINES, INTERNAL COMBUSTION + FAILURE, COMPONENT + PLAN + FAILURE, FABRICATION ERROR + TEST, SYSTEM OPERABILITY + TEST, PUMP

10056

DIESEL GENERATOR TRIPS AT SAN CAJON 2

SOUTHERN CALIFORNIA Edison COMPANY

1 PAGE, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, JANUARY 22, 1975, Docket 50-206, TYPE--PWR, REG--WEST, AG--NRC/ETEL

CAUSE - PULLEY FAILURE. DURING TESTING OF THE DIESEL GENERATORS, ONE WAS AIR STARTED BUT TRIPPED ON OVERCAMP. THE PULLEY USED TO DRIVE THE DIESEL'S AUXILIARY GENERATOR WAS SEPARATED FROM ITS DRIVE SHAFT. THIS CAUSED FAILURE OF THE START SIGNAL TO DIESEL'S STARTING CIRCUITRY. THE AIR STARTING MOTOR CONTINUED TO OPERATE UNTIL IT FIRED OUT. THE PULLEY WAS REMOVED TO ITS SHAFT. THE PULLEY ON THE OTHER UNIT WAS FOUND TO BE SATISFACTORY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM

093960 PLCONTINUED
CHANGE 02.003

FAILURE, COMPONENT • RELIES • SAN ONOFRE I (PWR) • TEST, SYSTEM OPERABILITY • ENGINES, INTERNAL COMBUSTION • GENERATION, DIESEL

100976
DIESEL GENERATOR FAILS TO OPERATE FOR ONE HOUR AT SAN ONOFRE I
SOUTHERN CALIFORNIA Edison CO.
1 PAGE, LETTER TO NRC DIVISION OF REACTOR LICENSING, MARCH 22, 1975, Docket 50-206, TYPE--PWR, NRC--WEST., AE--
ORCHTEL

CAUSE - FUEL TRANSFER PUMP DEFICIENCY. DURING THE SEMI-ANNUAL 1-HOUR FULL LOAD TEST OF THE DIESEL GENERATORS, ONE GENERATOR TRIPPED AFTER 45 MINUTES OF OPERATION. AN INVESTIGATION REVEALED THAT THE FUEL TRANSFER PUMP DID NOT HAVE SUFFICIENT CAPACITY. PRIOR TESTING HAD LOWERED THE FUEL LEVEL AND ACTIVATED THE CUMMINS CUMMINS ALARM SO THAT THE LOW OIL FUEL LEVEL WAS NOT ALARMED IN THE CONTROL ROOM. A PUMP OF LARGER CAPACITY WAS INSTALLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHANGE 02.003

SAN ONOFRE I (PWR) • MAINTENANCE • TEST, SYSTEM OPERABILITY • FAILURE, INSTALLATION ERROR • SYSTEM CAPACITY • FUEL, FUZZIL • PUMPS • ENGINES, INTERNAL COMBUSTION • GENERATION, DIESEL

100981
SAFETY INJECTION SYSTEM DESIGN DEFICIENCY FOUND AT SAN ONOFRE I
SOUTHERN CALIFORNIA Edison COMPANY
5 PAGES, LETTER TO NRC DIVISION OF REACTOR LICENSING, MARCH 31, 1975, Docket 50-206, TYPE--PWR, NRC--WEST., AE--
ORCHTEL

CAUSE - DESIGN ERROR. DURING AN EXTENSIVE DESIGN REVIEW OF THE EXISTING SAFETY INJECTION SYSTEM, IT WAS FOUND THAT FAILURE OF 1 OF THE 2 PREHEATER PUMP DISCHARGE VALVES TO CLOSE MAY RESULT IN A FLOOD OF THE SI WATER INTENDED FOR THE REACTOR VESSEL BEING DIVERTED TO THE STEAM GENERATORS. THIS WOULD ACCUM WITHIN STEAM GENERATOR PRESSURE IS LESS THAN REACTOR COOLANT PRESSURE. ADMINISTRATIVE CONTROLS WERE APPLIED FOR IMMEDIATE USE UNTIL ADDITIONAL CORRECTION CAN BE MADE DURING THE UPCOMING REFUELING OUTAGE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHANGE 02.003

SAFETY INJECTION • SAN ONOFRE I (PWR) • MODIFICATION • FAILURE, DESIGN ERROR • REVIEW • SYSTEM CAPABILITY

100985
AIR AND WATERING WATER SAMPLES NOT TAKEN AT SAN ONOFRE
SOUTHERN CALIFORNIA Edison COMPANY, ROSEMOUNT
1 PAGE, LETTER TO NRC DIVISION OF REACTOR LICENSING, JUNE 7, 1975, Docket 50-206, TYPE--PWR, NRC--WEST., AE--
ORCHTEL

CAUSE - EQUIPMENT FAILURES. A REVIEW OF THE SAMPLE COLLECTION RECORD DISCLOSED THAT 3 DRINKING WATER AND 6 AIR SAMPLES HAD NOT BEEN TAKEN DURING THE SECOND QUARTER OF 1975. EQUIPMENT FAILURES ACCOUNTED FOR THE LOSS OF AIR SAMPLES. A WATER SAMPLE WAS MISSED BECAUSE THE WELL WAS PERMANENTLY CAPPED. A SECOND SAMPLE WAS MISSED BECAUSE OF A CHANGE IN PERSONNEL AT THAT LOCATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHANGE 02.003

SAN ONOFRE I (PWR) • TEST INTERVAL • OSAMPLING • ENVIRONMENT • AIR • WATER, DRINKING • FAILURE, EQUIPMENT

100991
CHLORINE MONITORING OF THE DISCHARGE AT SAN ONOFRE
SOUTHERN CALIFORNIA Edison COMPANY, ROSEMOUNT
1 PAGE, LETTER TO NRC DIVISION OF REACTOR LICENSING, JULY 30, 1975, Docket 50-206, TYPE--PWR, NRC--WEST., AE--
ORCHTEL

CAUSE - NOT STATED. THE BASIS FOR TECH SPEC LIMITS INDICATES THAT LESS THAN 0.1 PPM RESIDUAL CHLORINE WILL EXIST IN THE DISCHARGE IF THE LIMIT OF 1.0 PPM IS REACHED AT THE CONDENSER OUTLET. A TEST SHOWED A CONCENTRATION OF 0.00 PPM RESIDUAL CHLORINE AT THE EDGE OF THE DISCHARGE WHEN THE CONDENSER OUTLET REACHED 0.3 PPM. A TECH SPEC CHANGE WILL BE SUBMITTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHANGE 02.003

SAN ONOFRE I (PWR) • CHLORINATION • CHLORINE • DRIVER • TESTING • CONDENSER COOLING SYSTEM • MONITORING PROGRAM, ENVIRONMENTAL

100993
CHLORINE DEMAND NOT MEASURED AT SAN ONOFRE I

100551 PLANTINUED
SOUTHERN CALIFORNIA Edison COMPANY, ROSEMEAD
1 PG, LTR TO WAC OFFICE OF NUCLEAR REGULATION, AUG. 25, 1975, Docket 50-206, TYPE--PWR, NRC--BEST., AE--DECETEL

CAUSE - NOT REASONABLY POSSIBLE. A SPECIAL STUDY PROGRAM WAS ESTABLISHED TO MONITOR CHLORINE CONCENTRATIONS AND CHLORINE DEMAND AROUND THE COOLING WATER DISCHARGE AND AT A CONTROL POINT. TO DATE ONLY CHLORINE CONCENTRATION HAS BEEN MEASURED. IT IS NOT REASONABLY POSSIBLE TO MEASURE CHLORINE DEMAND IN THE LOW SHORE ENVIRONMENT. THE DATA WOULD BE SUSPECT AND ITS USEFULNESS QUESTIONED. A TECH SPEC CHANGE WILL BE PREPARED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SAN GROUP 1 (PWR) • CHEMICAL ANALYSIS • CHLORINE • EFFLUENT • FAILURE, ADMINISTRATIVE CONTROL • R AND D PROGRAM • OPERATING • TEST INTERVAL • CLEAN AND SEA

100550
OFFSHORE TEMPERATURE SENSOR FAILS AT SAN GROUP 1
SOUTHERN CALIF. Edison Co., CALIF.
1 PG, LTR TO WAC OFFICE OF DIVISION OF NUCLEAR REGULATION, SEPT. 3, 1975, Docket 50-206, TYPE--PWR, NRC--BEST., AE--DECETEL

CAUSE - UNKNOWN. DURING A VERIFICATION CHECK, 1 OF THE 6 OFFSHORE TEMPERATURE SENSORS WAS FOUND TO BE INOPERATIVE. IT WAS REPLACED IMMEDIATELY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SAN GROUP 1 (PWR) • PRESSORS, TEMPERATURE • MONITORING PROGRAM, ENVIRONMENTAL • FAILURE, INSTANTANT • TEST, SYSTEM OPERABILITY • CLEAN AND SEA

100549
DIESEL GENERATOR NO 2 TRIPS FROM HIGH COOLING WATER TEMPERATURE AT SAN GROUP 1
SOUTHERN CALIFORNIA Edison Co., CALIF.
3 PGS, RPT TO WAC OFFICE OF NUCLEAR REGULATION, SEPT. 12, 1975, Docket 50-206, TYPE--PWR, NRC--BEST., AE--DECETEL

CAUSE - LEAK IN COOLANT SYSTEM. DURING A SEMI-ANNUAL RATED LOAD TEST, DIESEL GENERATOR NO 2 TRIPPED BECAUSE OF HIGH COOLING WATER TEMPERATURE AFTER 20 MINUTES OF OPERATION. THE SEALING SURFACE OF THE CAP CRUISER ON THE COOLANT SYSTEM ALLOWED LEAKAGE. SUFFICIENT PRESSURE AND COOLANT CONTACTS WERE NOT MAINTAINED IN THE COOLING SYSTEM. THE LEAKAGE WAS PIPED TO A DRAIN AND WAS NOT VISIBLE TO OPERATING PERSONNEL. THE DRAIN LINE WAS MODIFIED TO FACILITATE IDENTIFICATION OF LEAKAGE. THE CAP SEALING SURFACE WAS REPAIRED. THE DIESEL GENERATOR WAS OPERATED AT RATED LOAD FOR 1 HOUR.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SAN GROUP 1 (PWR) • GENERATOR, DIESEL • ENGINE, INTERNAL COMBUSTION • TEST, SYSTEM OPERABILITY • FAILURE, EQUIPMENT • CLEANING • CLEAN • PIPES AND PIPE FITTINGS

100548
DIESEL GENERATOR NO 1 TRIPS FROM HIGH COOLING WATER TEMPERATURE AT SAN GROUP 1
SOUTHERN CALIFORNIA Edison Co., CALIF.
3 PGS, RPT TO WAC OFFICE OF NUCLEAR REGULATION, SEPT. 12, 1975, Docket 50-206, TYPE--PWR, NRC--BEST., AE--DECETEL

CAUSE - HEAT EXCHANGER AIR PATH BLOCKED. DURING A SEMI-ANNUAL RATED LOAD TEST, DIESEL GENERATOR NO 1 TRIPPED BECAUSE OF HIGH COOLING WATER TEMPERATURE AFTER 35 MINUTES OF OPERATION. DURING AN EXAMINATION OF THE WATER-TO-AIR RADIATOR TYPE HEAT EXCHANGER, AIR PASSAGES WERE FOUND TO BE BLOCKED WITH JUMBORED PARTICLES OF THE RADIATOR COOLING FINS. THE RADIATOR WAS RECENTLY CLEANED DURING THE FOURTH DEWELLING OUTAGE. THE RADIATOR WAS CLEANED AND THE DIESEL GENERATOR OPERATED AT RATED LOAD FOR ONE HOUR. RADIATORS WILL BE INSPECTED MORE FREQUENTLY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SAN GROUP 1 (PWR) • GENERATOR, DIESEL • ENGINE, INTERNAL COMBUSTION • TEST, SYSTEM OPERABILITY • FAILURE, EQUIPMENT • HEAT EXCHANGERS • CRUD • AIR COOLED • FLOW BLOCKAGE

100547
PARTICULATE FILTERS NOT COLLECTED DURING TWO WEEKS AT SAN GROUP 1
SOUTHERN CALIFORNIA Edison Co., ROSEMEAD, CALIF.
1 PG, LTR WAC TO WAC DIVISION OF NUCLEAR REGULATION, NOV. 25, 1975, Docket 50-206, TYPE--PWR, NRC--BEST., AE--DECETEL

CAUSE - RESPONSIBLE PERSONNEL DUTY. A REPORT OF AIRBORNE SAMPLE DATA RECEIVED IN NOVEMBER SHOWED THAT SAMPLES COLLECTED FROM SAN GROUP ON SEPT. 22 AND SEPT. 27 DID NOT INCLUDE THE PARTICULATE FILTERS. THE PLANT STATION PERSONNEL, WHO WERE RESPONSIBLE FOR SAMPLE COLLECTION,

100550 CONTINUING

WERE ONLY WITH 2 MAJOR FEAS AND UNLOCKED THE SAMPLES. REACTOR PERSONNEL WILL BE DIRECTLY RESPONSIBLE FOR THE SAMPLES IN THE FUTURE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SAN ONOFRE 1 (PWR) • SAMPLES • PERMITTING, AIR • OFFICERS • MONITORING PROGRAM, ENVIRONMENTAL • FAILURE, OPERATION ERROR • OFF SITE

100600

OFFSHORE TEMPERATURE SENSOR FAILS AT SAN ONOFRE 1
SOUTHERN CALIFORNIA Edison CO., ROSAMEND, CA

1 PG. LETTER TO NRC OFFICE OF INSPECTION AND ENFORCEMENT TRANSMITTING REPORT, DEC. 12, 1975, DOCKET 50-200, TYPE--PWR, NRC--WEST., AC--DECEMBER

CAUSE - NOT STATED. DURING A SCHEDULED OPERATION VERIFICATION CHECK, IT WAS DISCOVERED THAT 1 OF THE 6 TEMPERATURE SENSORS HAD MALFUNCTIONED FOR THE PREVIOUS 2 WEEKS. THIS OFFSHORE SENSOR WAS LOCATED NEAR THE BOTTOM LOCATION. IT WAS REPLACED IMMEDIATELY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON D.C. 20545 10 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SAN ONOFRE 1 (PWR) • SENSORS, TEMPERATURE • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT • OCEAN AND SEA

100777

FINAL REPORT ON EFFECT OF CHANGE IN MODULUS USED FOR SEISMIC DESIGN AT SEQUOYAN 1 AND 2
TVA, CHATTANOOGA, TENN.

2A PAGES, LETTER TO NRC OFFICE OF INSPECTION AND ENFORCEMENT TRANSMITTING REPORT, FEBRUARY 3, 1979, DOCKETS 50-327320, TYPE--PWR, NRC--WEST., AC--TVA

CAUSE - DESIGN ERROR. THIS FINAL REPORT CONTAINS TVA'S INVESTIGATION AND ANALYSIS OF THE EFFECT ON STRUCTURES, SYSTEMS, AND COMPONENTS OF THE CHANGE IN THE MODULUS OF ELASTICITY OF CONCRETE FROM THAT SPECIFIED IN THE ORIGINAL DESIGN CRITERIA. THE RESULT OF THIS EVALUATION PROGRAM IS THAT ALL STRUCTURES, ATTACHED EQUIPMENT, AND PIPING SYSTEM REMAIN ADEQUATE AS ORIGINALLY DESIGNED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONCRETE • CONFINEMENT DESIGN • DESIGN CRITERIA • ELASTICITY • MODIFICATION • FAILURE, DESIGN ERROR • PROPERTY, PHYSICAL • REVIEW • SEQUOYAN 1 (PWR) • SEQUOYAN 2 (PWR) • SEISMIC DESIGN • CONSTRUCTION

102015

INTERIM REPORT ON STEAM GENERATOR AND CONDENSER PUMP ANCHOR BOLTS AT SEQUOYAN 1 AND 2
TENNESSEE VALLEY AUTHORITY

1 PAGE, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, MARCH 31, 1979, DOCKET 50-327320, TYPE--PWR, NRC--WEST., AC--TVA

CAUSE - DESIGN DEFICIENCY. A TEST SPECIMEN WAS FABRICATED USING THE SAME WELDING PROCEDURES AND TECHNIQUES AS FOR THE ORIGINAL ANCHOR BOLT ASSEMBLIES. TEST ASSEMBLIES WERE LEFT IN THE RESTRAINED CONDITIONS FOR 1 WEEK. EXTENSIVE CRACKING WAS OBSERVED IN THE HEAT-AFFECTED ZONE OF THE AISI 4340 BOLT MATERIAL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SEQUOYAN 1 (PWR) • SEQUOYAN 2 (PWR) • CONSTRUCTION • FASTENER • WELDS • STEAM GENERATOR • PUMPS • RAIN COOLING SYSTEM • FAILURE, DESIGN ERROR • CRACK • HEAT TREATMENT

103000

WELDING DOCUMENTATION DEFICIENCY IN CLASS A, B, C, AND D PIPING AT SEQUOYAN 1 AND 2
TENNESSEE VALLEY AUTHORITY, CHATTANOOGA

APPROXIMATELY 125 PAGES, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT TRANSMITTING REPORT, MAY 9, 1979, DOCKETS 50-327320, TYPE--PWR, NRC--WEST., AC--TVA

DURING A NRC-LIE INSPECTION, DEFICIENCIES WERE DETECTED IN THE WELDING DOCUMENTATION OF TVA CLASS A, B, C, AND D PIPING SYSTEMS. TVA STOPPED ALL WELDING UNTIL A REVIEW COULD BE MADE OF THE WELDS AND DOCUMENTATION. DEFICIENCIES WERE CAUSED BY (1) LACK OF TRAINED AND EXPERIENCED EMPLOYEES, (2) CHANGING REQUIREMENTS OF DOCUMENTATION, (3) INCOMPLETE PROCEDURES, AND (4) INADEQUATE INSTRUCTIONS. PROCEDURES CONTROLLING WELDING ACTIVITIES WERE REVISED. ALL PERSONNEL WERE GIVEN TRAINING. DEFICIENCIES WERE EVALUATED AND CORRECTIVE ACTION INITIATED BEFORE WELDING WAS RESUMED. ALL ACCESSIBLE WELDS WERE VISUALLY INSPECTED AND ALL INDICATIONS COMPARED TO AUDIT FINDING SHEET.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SEQUOYAN 1 (PWR) • SEQUOYAN 2 (PWR) • CONSTRUCTION • QUALITY ASSURANCE • WELDING • WELDS • PIPES AND PIPE FITTINGS • FAILURE, ADMINISTRATIVE CONTROL • PROCEDURES AND MANUALS • TRAINING • RECORDS

100409

SETTLEMENT OF EAST STEAM VALVE ROOMS AT SEQUOYAH 1 & 2

TENNESSEE VALLEY AUTHORITY, CHATTANOOGA

5 PGS., LTR W/RT TO NRC OFFICE OF INSPECTION & ENFORCEMENT, JULY 2, 1975, DUCKETS 50-327/320, TYPE--PWR, MFG--WEST., AE--TVA

CAUSE - STA. 0. TWO IDENTICAL VALVE ROOM STRUCTURES WERE BUILT TO HOUSE AND PROTECT THE MAIN STEAM AND REHEATER ISOLATION VALVES AND THE MAIN STEAM SAFETY VALVES FROM THE EFFECTS OF TORNADO, EARTHQUAKE, AND OTHER EVENTS. PRIOR TO INSTALLATION OF ANY EQUIPMENT, SETTLEMENT MEASURED AT THE CURRENTS RANGE FROM 0.28 TO 0.37 FT. CALCULATED PERMITTED DIFFERENTIAL SETTLEMENT OF THE PIPING IS 0.50 INCH. TO MEET THIS REQUIREMENT, REINFORCED CONCRETE CAISSONS WILL BE INSTALLED AT INTERVALS AROUND EACH BUILDING PERIMETER. THE CAISSONS WILL EXTEND 4 TO 10 FT INTO BEDROCK AND WILL BE TIED STRUCTURALLY INTO THE BUILDING SPREAD FOOTING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SEQUOYAH 1 (PWR) + SEQUOYAH 2 (PWR) + CONSTRUCTION + INTERACTION, SOIL AND STRUCTURE + FOUNDATION ENGINEERING + DEFORMATION + MULTIPLICATION + STRUCTURE + CONCRETE, REINFORCED + VALVES + MISSILE VENTILATION AND PROTECTION

100408

THIRD INTERIM REPORT OF ANCHOR BOLT DEFICIENCY AT SEQUOYAH 1 AND 2

TENNESSEE VALLEY AUTHORITY, CHATTANOOGA

1 PG., WPT TO NRC OFFICE OF I & E, JULY 25, 1975, DCKET 50-327/320, TYPE--PWR, MFG--WEST., AE--TVA

CAUSE - INSTALLATION DEFICIENCY. TESTS HAVE BEEN MADE ON 3 OF THE 4 TENSION TEST ASSEMBLY BOLTS. TWO FAILED AT 104,000 AND 275,000 LBS RESPECTIVELY. THE THIRD STRIPPED THE HOLDING THREADS OFF THE BOLT AT 430,000 LBS. TO DATE 16 OF THE 274 ANCHOR BOLTS HAVE BEEN ULTRASONICALLY TESTED. ALL EXHIBIT SOME DEGREE OF UNDERHEAD CRACKING. A PROOF-LOAD TEST MAY BE USED TO CORRELATE THE ULTRASONIC TESTING RESULTS WITH BOLT/HELD STRENGTH.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SEQUOYAH 1 (PWR) + SEQUOYAH 2 (PWR) + CONSTRUCTION + OVERLAP + FASTENER + STEAM GENERATION + PUMPS + MAIN CIRCULATING SYSTEM + FAILURE, INSTALLATION ERROR + PLAN + TESTING

100402

REFUELING WATER STORAGE TANK AND FOUNDATION DEFICIENCY AT SEQUOYAH 1 AND 2

TENNESSEE VALLEY AUTHORITY, CHATTANOOGA

3 PGS., LTR W/RT TO NRC OFFICE OF I & E, SEPT. 22, 1975, DUCKETS 50-327/320, TYPE--PWR, MFG--WEST., AE--TVA

CAUSE - DESIGN DEFICIENCY. DURING AN INVESTIGATION TO INCREASE THE REFUELING WATER STORAGE TANK CAPACITY, A STRUCTURAL EVALUATION INDICATED THAT THE ORIGINAL TANK AND FOUNDATION WOULD NOT SATISFY THE CRITERIA. THE MAGNITUDE OF SEISMIC LOADING WAS UNDERESTIMATED. ALSO, THE TANK BUTTIN IN THE SUCTION PIPE ATTACHMENT AREA WAS NOT ADEQUATELY DESIGNED TO SUPPORT THE HYDROSTATIC PRESSURE. A MODIFIED TANK DESIGN WAS PREPARED WHICH INCREASES CAPACITY FROM 550,000 TO 575,000 GALLONS. MODIFICATIONS WERE MADE IN ADDITION TO THE INCREASED HEIGHT SO THAT THE TANK AND FOUNDATION MET REQUIREMENTS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SEQUOYAH 1 (PWR) + SEQUOYAH 2 (PWR) + CONSTRUCTION + STORAGE CONTAINER + REFUELING + WATER + SEISMIC DESIGN + STRESS + FAILURE, DESIGN ERROR

100403

INTERIM REPORT ON SETTLEMENT OF STEAM VALVE ROOMS AT SEQUOYAH 1 AND 2

TENNESSEE VALLEY AUTHORITY, CHATTANOOGA

9 PGS., LTR W/RT TO NRC OFFICE OF I & E, OCT. 1, 1975, DCKET 50-327/320, TYPE--PWR, MFG--WEST., AE--TVA

CAUSE - UNKNOWN. A FOUNDATION INVESTIGATION PROGRAM HAS BEEN DEVELOPED. THE FIRST PHASE OF THE PROGRAM CONSISTS OF CORE DRILLING TO UNDERLYING ROCK STRATA. FIVE CORES WILL BE TAKEN AT EACH CAISSON LOCATION. THE SECOND PHASE CONSISTS OF OBTAINING UNDISTURBED SOIL SAMPLES AROUND THE PERIMETER OF EACH STRUCTURE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SEQUOYAH 1 (PWR) + SEQUOYAH 2 (PWR) + CONSTRUCTION + DISPLACEMENT + BUILDING + FOUNDATION ENGINEERING + INTERACTION, SOIL AND STRUCTURE + SOIL PROPERTY, IN SITU

107903

CABLE TRAY HULL-HULL CLIPS INADEQUATE FOR HORIZONTAL LOAD AT SEQUOYAH 1 & 2

TENNESSEE VALLEY AUTHORITY, CHATTANOOGA

7 PGS., LTR W/RT TO NRC OFFICE OF I & E, NOV. 3, 1975, DUCKETS 50-327/320, TYPE--PWR, MFG--WEST., AE--TVA

CAUSE - DESIGN DEFICIENCY. A TEST EVALUATION OF CATEGORY 1 CABLE TRAY SUPPORT SYSTEMS AS DESIGNED

107903 RECONTINUING

ADVISED THAT THE MAXIMUM CLIPS USED TO ATTACH THE CABLE TRAYS TO THE SUPPORT BRACKET WOULD NOT WITHSTAND THE HORIZONTAL SEISMIC DESIGN LOADS. THREE GENERAL TYPES OF LOAD TRANSFER CONNECTIONS HAVE BEEN TESTED AND WERE APPROVED FOR SPECIFIC SITUATIONS. THE IMPROVED CONNECTIONS ARE BEING INSTALLED. THIS IS THE FINAL REPORT ON THIS DEFICIENCY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SEQUENT 1 (PWR) + SEQUENT 2 (PWR) + CONSTRUCTION + SUPPORT STRUCTURE + CABLES AND CONNECTORS + SEISMIC DESIGN + FAILURE, DESIGN ERROR + TESTING + MODIFICATION

107902

FINAL REPORT ON SG AND RC PUMP ANCHOR BOLT DEFICIENCY AT SEQUENT 1 AND 2
RENUCLEAR VALLEY AUTHORITY, CHATTANOOGA, TN

1 PAGES. LETTER WITH REPORT TO NRC OFFICE OF E & C, DEC. 5, 1975, DOCKET 50-277320, TYPE--PWR, NRC--WEST., AC--TVA

CAUSE - USE OF INCORRECT PROCEDURES. AN INCORRECT WELDING PROCEDURE WAS USED TO WELD THE STEAM GENERATOR AND REACTOR COOLANT PUMP ANCHOR BOLTS TO THE EMBEDDED PLATES ANCHORED IN THE CONCRETE SLAB. THIS RESULTED IN UNDERWELD CRACKING IN THE BOLT BASE METAL HEAT-AFFECTED ZONE. THE ANCHOR BOLT EFFECTIVE CROSS-SECTIONAL AREA AND ITS STRENGTH WERE THEREFORE REDUCED. WELDS WERE MADE IN 1971. ALL ANCHOR BOLTS FOR BOTH THE REACTOR COOLANT PUMPS AND STEAM GENERATORS WILL BE APPROVED AND REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SEQUENT 1 (PWR) + SEQUENT 2 (PWR) + CONSTRUCTION + FASTENER + WELDS + STEAM GENERATOR + PUMPS + DATA LOGGING SYSTEM + FAILURE, INSTALLATION ERROR + PROCEDURES AND MANUALS + PLAN + SUPPORT STRUCTURE

107901

REPELLING CANAL WALL CRACK INTERIM REPORT AT ST. LUCIE 1

FLORIDA POWER & LIGHT COMPANY

7 PAGES. LETTER WITH REPORT TO NRC DIRECTOR OF REGULATORY OPERATIONS, JANUARY 24, 1975, DOCKET 50-335, TYPE--PWR, NRC--CUMB., AC--EASCO

CAUSE - UNKNOWN. A MAINLINE CRACK WAS FOUND AT THE EAST WALL OF THE REINFORCED CONCRETE REPELLING CANAL. THE CRACK WAS NEAR AN EMBEDDED STEEL PLATE BEING USED TO SUPPORT ONE END OF A PLATFORM. THE CAUSE OF THE CRACK IS UNKNOWN. IT IS BEING INVESTIGATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONCRETE + REPELLING + CANAL + CONSTRUCTION + CONCRETE, REINFORCED + ST. LUCIE 1 (PWR) + CRACK

079071

MAINLINE CRACK FOUND IN REPELLING CANAL WALL AT ST. LUCIE 1

FLORIDA POWER & LIGHT COMPANY

6 PAGES. LETTER WITH REPORT TO NRC DIRECTOR OF REGULATORY OPERATIONS, JANUARY 24, 1975, DOCKET 50-335, TYPE--PWR, NRC--CUMB., AC--EASCO

CAUSE - UNKNOWN. A CONSTRUCTION WORKER NOTICED WHAT APPEARED TO BE A MAINLINE CRACK AT THE EAST WALL OF THE REINFORCED CONCRETE REPELLING CANAL. THE CRACK WAS NEAR AN EMBEDDED STEEL PLATE USED TO SUPPORT ONE END OF A PLATFORM. THE CAUSE IS UNKNOWN AND IS UNDER INVESTIGATION. CORRECTIVE ACTION PROPOSED IS EITHER TO DETACH THE PLATFORM AND SUPPORT THAT END ON A STEEL COLUMN OR TO MERELY REPAIR THE CONCRETE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONCRETE + PLAN + REPELLING + CANAL + CONSTRUCTION + CONCRETE, REINFORCED + ST. LUCIE 1 (PWR)

100304

REACTOR VESSEL SURFACE CONTAMINATION AT ST. LUCIE 1

FLORIDA POWER & LIGHT COMPANY

3 PAGES. LETTER TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, JANUARY 30, 1975, DOCKET 50-335, TYPE--PWR, NRC--CUMB., AC--EASCO

CAUSE - UNKNOWN. DURING INSPECTION OF THE REACTOR VESSEL FOR CLEANLINESS PRIOR TO A TRIAL INSERTION OF THE REACTOR INTERNALS, SEVERAL DISCOLORED AREAS WERE FOUND ON THE VESSEL CLAD BETWEEN A HOT LEG NOZZLE AND A COLD LEG NOZZLE. TESTS INDICATED THAT THE AREAS HAD A HIGH FREE IONIC CONTENT AND THAT SOME FORM OF CLAD CONTAMINATION HAD TAKEN PLACE. THE AREAS WERE POLISHED AND RINSED SEVERAL TIMES UNTIL NO FURTHER FREE IONIC CONTAMINATION WAS INDICATED. THIS HAD NO EFFECT ON CLAD INTEGRITY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CLADDING + PRESSURE VESSELS + INOA + CONTAMINATION + FAILURE, FABRICATION ERROR + CONSTRUCTION + ST. LUCIE 1

100352 CONTINUED
(PWR)

100250
CRANE COUNTERWEIGHT CRASHES ON REACTOR AUXILIARY BUILDING AT ST. LUCIE I
FLORIDA POWER & LIGHT COMPANY
10 PAGES. LETTER WITH REPORT TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, FEBRUARY 21, 1975. DOCKET 50-335.
TYPE--PWR, NRC--CUMD.. AE--EDASLO

CAUSE - UNKNOWN. A 5100 LB CONCRETE CRANE COUNTERWEIGHT DROPPED ABOUT 80 FEET TO THE CONCRETE ROOF DECK OF THE REACTOR AUXILIARY BUILDING CONTROL ROOM. THE CRANE WAS BEING DISASSEMBLED AT THE TIME. AS THE COUNTERWEIGHT WAS BEING LOWERED, THE AUXILIARY WINCH MALFUNCTIONED ALLOWING THE LOAD TO FALL FREELY. THE CAUSE HAS NOT BEEN DETERMINED. SOME CRACKING AND SPALLING OF THE CONCRETE ROOF DECK OCCURRED IN THE IMMEDIATE VICINITY OF THE IMPACT AREA AND THE UNDERSIDE AROUND EMBLEMENTS, AND ALONG THE CONCRETE BLOCK WALL SEPARATING THE CONTROL ROOM FROM THE CLASSROOM.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545. 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONCRETE + FAILURE, EQUIPMENT + IMPACT SHOCK + BUILDING + DAMAGE + CONTROL PANEL/ROOM + CONSTRUCTION + ST. LUCIE I (PWR) + CRANE + STRUCTURE

100900
FINAL REPORT ON INTAKE COOLING WATER SYSTEM MISALIGNMENT AT ST. LUCIE I
FLORIDA POWER & LIGHT CO.
11 PAGES. LETTER WITH REPORT TO NRC OFFICE OF INSPECTION & ENFORCEMENT, FEBRUARY 27, 1975. DOCKET 50-335. TYPE--PWR, NRC--CUMD.. AE--EDASCO

CAUSE - DESIGN ANOMALY. DURING THE INITIAL PREOPERATIONAL TESTING OF THE INTAKE COOLING WATER SYSTEM, IT WAS DISCOVERED THAT THE A HEADER WAS FILLING THE B COMPONENT COOLING HEAT EXCHANGER. REVIEW OF THE DRAWINGS INDICATED THAT THE MISALIGNMENT WAS DUE TO A DESIGN ANOMALY THAT OCCURRED DURING A YARD PIPING REDSIGN EFFORT. PIPING CHANGES WILL BE MADE TO CORRECT THIS PRIOR TO FUEL LOADING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545. 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MODIFICATION + TEST, PREOPERATIONAL + TEST, SYSTEM OPERABILITY + FAILURE, DESIGN ERROR + AUXILIARY COOLING + CONSTRUCTION + ST. LUCIE I (PWR) + PIPES AND PIPE FITTINGS

101352
LPST PUMP CASING LEAK FOUND DURING CONSTRUCTION. FINAL REPORT, AT ST. LUCIE I
FLORIDA POWER & LIGHT COMPANY
7 PAGES. LETTER WITH REPORT TO NRC OFFICE OF INSPECTION & ENFORCEMENT, MARCH 10, 1975. DOCKET 50-335. TYPE--PWR, NRC--CUMD.. AE--EDASCO

CAUSE - REMOVAL OF A SAMPLE. A LEAK WAS DISCOVERED IN THE CASING OF A LOW PRESSURE SAFETY INJECTION PUMP DURING SYSTEM FLUSHING BY STARTUP PERSONNEL. THE LEAK WAS THE RESULT OF OBTAINING A METAL SAMPLE FROM THE PUMP DRAIN BOSS SUBSEQUENT TO THE SHIP HYDRO TEST. THE PUMP CASING WAS REPAIRED BY THE VENDOR.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545. 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

METAL + SAFETY INJECTION + SAMPLING + FAILURE, FABRICATION ERROR + LEAK + CONSTRUCTION + ST. LUCIE I (PWR) + PUMPS

102000
SQUARE D CONTROL RELAYS FAIL AT ST. LUCIE I
FLORIDA POWER & LIGHT CO.
7 PAGES. LETTER WITH REPORT TO NRC OFFICE OF INSPECTION & ENFORCEMENT, APRIL 25, 1975. DOCKET 50-335. TYPE--PWR, NRC--CUMD.. AE--EDASCO

CAUSE - UNKNOWN. SIX SQUARE D TYPE G-O CLASS 8501 CONTROL RELAYS REQUIRED REPAIR WORK AND 4 SQUARE D RELAYS FAILED TO ACTUATE DURING THE FUNCTIONAL AND PREOPERATIONAL TESTING OF DIESEL GENERATOR 1A. THERE ARE 21 RELAYS IN EACH DIESEL GENERATOR CONTROL CABINET. DEFECTS NOTED WERE SLIPPAGE OF THE SPRING ON THE MOVABLE CONTACT AND CRACKING OF THE MOLDED PLASTIC. THE CAUSE IS PRESENTLY UNKNOWN. CORRECTIVE ACTION WILL BE DETERMINED WHEN THE CAUSE IS KNOWN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545. 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ST. LUCIE I (PWR) + CONSTRUCTION + RELAYS + CONTROL SYSTEM + GENERATOR, DIESEL + ENGINES, INTERNAL COMBUSTION + TEST, SYSTEM OPERABILITY + FAILURE, COMPONENT

104900
FINAL REPORT ON AC-100 WELDING INCIDENT AT ST. LUCIE I

104963 *CONTINUED*
 FLORIDA POWER & LIGHT CO., MIAMI
 5 PAGES, LETTER WITH REPORT TO NRC OFFICE OF INSPECTION & ENFORCEMENT, JULY 23, 1975, DOCKET 50-335, TYPE--
 PWR, NRC--CUMB., AE--EBASCO

CAUSE - VIOLATION OF QC PROCEDURES. LINE RC-100 IS A CATEGORY 1 LINE UTILIZED FOR SENSING PRESSURE IN THE REACTOR COOLANT PUMP UPPER SEAL CAVITY. TEMPORARY FLANGES, WHICH HAD BEEN INSTALLED, WERE REMOVED AND PERMANENT FLANGES INSTALLED. NO PROVISIONS WERE MADE FOR QC PERSONNEL TO OBSERVE THE REMOVAL OF THE TEMPORARY FLANGES AND THE INSTALLATION OF THE PERMANENT ONES. WHEN THE ERROR WAS DISCOVERED, THE PERMANENT FLANGES WERE CUT OUT AND REWELDED USING PROPER PROCEDURES AND INSPECTION. QC PROCEDURES WERE MODIFIED TO PREVENT REOCCURRENCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ST. LUCIE 1 (PWR) * CONSTRUCTION * QUALITY ASSURANCE * WELDS * PIPES AND PIPE FITTINGS * TEST, NONDESTRUCTIVE * FAILURE, INSTALLATION ERROR * PROCEDURES AND MANUALS

104961
 FINAL REPORT ON RELAY FAILURES AT ST. LUCIE
 FLORIDA POWER & LIGHT COMPANY
 6 PGS, LTR W/REPORT TO NRC OFFICE OF INSPECTION & ENFORCEMENT, JULY 20, 1975, DOCKET 50-335, TYPE--PWR, NRC--
 CUMB., AE--EBASCO

CAUSE - MISAPPLICATION. SIX SQUARE D CONTROL RELAYS (TYPE G3, CLASS 0901) REQUIRED REPAIRS AND 4 FAILED TO OPERATE DURING PREOPERATIONAL TESTING OF A DIESEL GENERATOR. THERE ARE 21 SUCH RELAYS IN EACH CONTROL CABINET. THREE FAILURE MODES WERE DETECTED. (1) BREAKING OF SIDE PLATES OF CONTACT BLOCKS. (2) CONTACT MISALIGNMENT. (3) MAINLINE CRACKS IN THE INTERIOR OF THE CONTACT BLOCKS. NEW CONTACT BLOCKS WERE INSTALLED ON ALL RELAYS. NEW CONTACT RETAINING SCREWS WITHOUT A CAPTIVE PRESSURE PLATE WERE USED. FAILURE RESULTED BECAUSE THE PRESSURE PLATE WAS ROTATED DURING INSTALLATION OF THE WIRING TERMINALS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ST. LUCIE 1 (PWR) * CONSTRUCTION * RELAYS * CONTROL SYSTEM * GENERATION, DIESEL * FAILURE, INSTALLATION ERROR * INSTALLATION * DAMAGE * CABLES AND CONNECTORS * MODIFICATION * TEST, SYSTEM OPERABILITY * TEST, PREOPERATIONAL

104964
 STEAM GENERATOR PRIMARY HEAD CLAD PENETRATED AT ST. LUCIE 1
 FLORIDA POWER & LIGHT CO., MIAMI
 2 PAGES, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, AUG. 5, 1975, DOCKET 50-335, TYPE--PWR, NRC--CUMB.,
 AE--EBASCO

CAUSE - EXCESSIVE GRINDING AT WELD. DURING THE FINAL CLEANING OF STEAM GENERATOR 1B1 PRIMARY HEAD ON THE COLD SIDE, 2 AREAS OF CORROSION WERE DETECTED. ONE WAS 2 X 1/8 INCH AND THE OTHER 3/32 X 3/4 INCH AT THE SEAM WELD WHICH ATTACHES THE STAY CYLINDER TO THE PRIMARY HEAD. CORROSION RESULTED FROM PENETRATION OF THE CLADDING CAUSED BY EXCESSIVE GRINDING AT THE HEAD WELD. THIS IS A DIFFICULT AREA TO GRIND. REPAIRS WERE MADE IN ACCORDANCE WITH ASME CODE CASE 1401-1.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ST. LUCIE 1 (PWR) * CONSTRUCTION * STEAM GENERATOR * CLADDING * FAILURE, CLADDING * WELDS * FAILURE, FABRICATION ERROR * CORROSION

105015
 REACTOR COOLANT SYSTEM OVERPRESSURIZED AT ST. LUCIE 1
 FLORIDA POWER & LIGHT CO., FLA.
 9 PGS, LTR W/REPORT TO NRC OFFICE OF I & E, REGION II, SEPT. 9, 1975, DOCKET 50-335, TYPE--PWR, NRC--CUMB., AE--
 EBASCO

CAUSE - LETDOWN VALVE FAILED CLOSED. DURING NOT FUNCTIONAL TESTING, THE LETDOWN ISOLATION VALVE FAILED CLOSED. THE RESULTANT TRANSIENT CAUSED THE REACTOR COOLANT SYSTEM TO EXCEED THE PRESSURE/TEMPERATURE LIMITATIONS. TEMPERATURE WAS 105 F WHEN PRESSURE REACHED 600 PSIA OR 80 PSI ABOVE THE LIMIT. VALVE FAILURE OCCURRED DUE TO A BROKEN LUG CONNECTION ON A SEATING RELAY. A SECOND BROKEN LUG WAS FOUND ON THE FACTORY-WIRED RELAY PANEL. THE LEADS WERE RELUGGED AND TIGHTENED. IT IS PROBABLE THAT DURING THE START-UP CHECK OUTS, THAT THIS LUG WAS FLEXED EACH TIME THE WIRE IDENTIFICATION NUMBER WAS READ AND THE LUG FINALLY BROKE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ST. LUCIE 1 (PWR) * CONSTRUCTION * OVERPRESSURE TRANSIENT * MAIN COOLING SYSTEM * FAILURE, EQUIPMENT * VALVES * CABLES AND CONNECTORS * FAILURE, INSTALLATION ERROR

104955
 FINAL REPORT ON INTAKE COOLING WATER FLANGE FAILURE AT ST. LUCIE 1

106055 *CONTINUED*

FLORIDA POWER & LIGHT CO., FLORIDA

7 PGS. LTR W/HPT TO NRC OFFICE OF I & E, OCT. 6, 1975, DOCKET 50-335, TYPE--PHR, NRC--COMB., AE--EDASCO

CAUSE - INCORRECT MATERIAL. A 3-INCH TEE IN THE SEISMIC CLASS 1 PORTION OF INTAKE COOLING WATER SYSTEM WAS FOUND TO BE CRACKED. INSPECTION OF THE TEE REVEALED THAT IT WAS MADE OF CAST IRON. CAST CARBON STEEL WAS SPECIFIED. FURTHER INSPECTION FOUND A TOTAL OF 16 3-INCH TEES AND ELBOWS TO BE OF THE WRONG MATERIAL. THE PROPER FITTINGS HAD BEEN CORRECTLY DRAWN FROM STOCK AND STORED AT THE INSTALLATION POINT. FITTINGS FOR NEW SAFETY CLASS LINES WERE STORED NEARBY. THE JOE GROUPS BECAME FIXED DURING INSTALLATION. FITTINGS OF THE PROPER MATERIAL ARE ON ORDER AND WILL BE INSTALLED PRIOR TO FUEL LOADING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ST. LUCIE 1 (PHR) * CONSTRUCTION * PIPES AND PIPE FITTINGS * AUXILIARY COOLING * FAILURE, INSTALLATION ERROR * MATERIAL * QUALITY ASSURANCE

107520

FINAL REPORT ON CRANE COUNTERWEIGHT CRASH AT ST. LUCIE 1
FLORIDA POWER & LIGHT CO., FLA.

53 PGS. LTR W/HPT TO NRC OFFICE OF I & E, OCT. 14, 1975, DOCKET 50-335, TYPE--PHR, NRC--COMB., AE--EDASCO

CAUSE - CRANE DEFICIENCY. ON JAN. 14, 1975, A 5100 LB CRANE COUNTERWEIGHT DROPPED 40 FEET TO THE CONCRETE ROOF DECK OF THE REACTOR AUXILIARY BUILDING CONTROL ROOM. THIS CAUSED CONSIDERABLE DAMAGE TO THE COUNTERWEIGHT, CRACKED THE CONCRETE ROOF DECK, SPALLED CONCRETE IN THE IMMEDIATE VICINITY OF THE IMPACT AREA AND ON THE UNDERSIDE OF THE ROOF DECK. SONISCOPE SURVEY REVEALED A DAMAGED AREA ABOUT 14 X 12 FEET. A SERIES OF EPOXY INTRUSION GROUTING OPERATIONS RE-ESTABLISHED THE BUILDING TO THE ORIGINAL DESIGN CRITERIA. FAILURE OF THE AUXILIARY DRAIN TO CONTROL THE LOWERING OF THE COUNTERWEIGHT WAS DISengagement OF THE DRAIN FROM THE DRIVE PINION DUE TO ABSENCE OF A SAFETY LOCK.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ST. LUCIE 1 (PHR) * CONSTRUCTION * CRANE * BUILDING * STRUCTURE * CONTROL PANEL/ROOM * DAMAGE * MAINTENANCE AND REPAIR * FAILURE, DESIGN ERROR * MISSILE GENERATION AND PROTECTION

106276

DIESEL GENERATOR LOAD SEQUENCING IMPROPER AT ST. LUCIE 1
FLORIDA POWER & LIGHT CO., MIAMI, FLA.

7 PGS. LTR W/HPT TO NRC OFFICE OF I & E, NOV. 6, 1975, DOCKET 50-335, TYPE--PHR, NRC--COMB., AE--EDASCO

CAUSE - DESIGN DEFICIENCY. DURING PREOPERATIONAL TESTING, DIESEL GENERATOR 1A FAILED TO LOAD IN THE DESIGNED SEQUENCE. THE NEXT DAY, IMPROPER LOAD SEQUENCING WAS OBSERVED DURING SIMILAR TESTING OF DIESEL GENERATOR 1B. A DESIGN DEFICIENCY RESULTED IN A RELAY RACE IN THE LOAD SHEDDING RELAY AND THE SEQUENCE START RELAY. A TIME DELAY RELAY WAS ADDED WHICH MAINTAINS THE LOAD SHEDDING RELAY ENERGIZED UNTIL THE DG BREAKER CLOSING IS COMPLETED AND THE BUS UNDERVOLTAGE RELAY IS ACTUATED. TESTING SHOWED THE LOADING SEQUENCE THEN OPERATED PROPERLY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ST. LUCIE 1 (PHR) * CONSTRUCTION * CONTROL SYSTEM * GENERATOR, DIESEL * ENGINES, INTERNAL COMBUSTION * TEST, SYSTEM OPERABILITY * TEST, PREOPERATIONAL * FAILURE, DESIGN ERROR * EMERGENCY POWER, ELECTRIC

107985

SAFETY INJECTION SYSTEM SOCKET WELDS LEAK AT ST. LUCIE 1
FLORIDA POWER & LIGHT CO., MIAMI, FLA.

7 PGS. LTR W/HPT TO NRC OFFICE OF I & E, NOV. 13, 1975, DOCKET 50-335, TYPE--PHR, NRC--COMB., AE--EDASCO

CAUSE - UNKNOWN. DURING HOT OPERATIONAL TESTING PRIOR TO CORE LOADING, LEAKS WERE FOUND IN 2 1/2-INCH WELDS. ONE WAS A SOCKET WELD BETWEEN THE LINE AND THE VENT VALVE FOR THE 12-INCH CONNECTOR BETWEEN THE SAFETY INJECTION TANK 1A2 AND THE REACTOR COOLANT LOOP. THE OTHER WAS THE SOCKET WELD BETWEEN THE DRAIN LINE AND THE SOCKET ON THE 12-INCH LINE FROM SAFETY INJECTION TANK 1A1 TO THE REACTOR COOLANT LOOP. TEMPORARY REPAIRS WERE MADE. THE CAUSE IS UNKNOWN AT THIS TIME. PERMANENT REPAIRS WERE MADE AFTER THE HOT OPERATIONAL TESTS. RADIOGRAPHS INDICATE THE POSSIBILITY OF INCOMPLETE RETRACTION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ST. LUCIE 1 (PHR) * CONSTRUCTION * WELDS * PIPES AND PIPE FITTINGS * SAFETY INJECTION * TEST, SYSTEM OPERABILITY * TEST, PREOPERATIONAL * LEAK

108023

4-KV BUS LOAD SHEDDING DEFICIENCY AT ST. LUCIE 1
FLORIDA POWER & LIGHT CO., MIAMI, FL

1 PG. LTR W/HPT TO NRC OFFICE OF I & E, NOV. 23, 1975, DOCKET 50-335, TYPE--PHR, NRC--COMB., AE--EDASCO

100023 *CONTINUED*

CAUSE - DESIGN DEFICIENCY. ECCS PRE-OPERATIONAL TESTING REQUIRED INTENTIONAL DISRUPTION OF NORMAL SITE POWER TO SIMULATE LOSS OF OFF-SITE POWER. WHEN NORMAL POWER WAS DISRUPTED, THE AB BUS FAILED TO LOAD SHED. THE AB BUS LOAD SHEDDING PERMISSIVE RELAY, WHICH IS ENERGIZE-TO-ACTUATE, SUFFERED LOSS OF POWER WHEN NORMAL POWER WAS TERMINATED BECAUSE IT WAS POWERED FROM THE SA POWER DISTRIBUTION PANEL. FAILURE BLOCKED OPERATION OF THE ACTUAL LOAD SHED RELAYS. CORRECTIVE ACTION IS UNDER INVESTIGATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ST. LUCIE 1 (PWR) * CONSTRUCTION * INSTRUMENT, PROTECTIVE * INSTRUMENT, INTERLOCK * RELAYS * TEST, SYSTEM OPERABILITY * TEST, PREOPERATIONAL * ACCIDENT, LOSS OF POWER * OFF SITE * FAILURE, DESIGN ERROR * EMERGENCY COOLING SYSTEM * GENERATOR, DIESEL

100022

CHARGING PUMP FAILS TO START AT ST. LUCIE 1

FLORIDA POWER & LIGHT CO., MIAMI, FL

2 PGS. LTR WRPT TO NRC OFFICE OF I & E, DEC. 1, 1975, DOCKET 50-335, TYPE--PWR, NRC--COMB., AE--EBASCO

CAUSE - TIME SEQUENCE DEFICIENCY. DURING PREOPERATIONAL TESTING OF THE ECCS, CHARGING PUMP IC FAILED TO RESTART DURING A SIMULATED LOSS OF OFF-SITE POWER. FAILURE IS ATTRIBUTED TO THE TIME SEQUENCE OF EVENTS WHICH ENABLED THE DIESEL GENERATOR BREAKER TO CLOSE BEFORE THE 480V SWITCH GEAR BREAKER ASSOCIATED WITH THE CHARGING PUMP COULD REWIND ITS CLOSING SPRINGS. THE TIME DIFFERENCE ALLOWED THE PUMP ANTI-PUMP RELAY TO ENERGIZE. CORRECTIVE ACTION IS UNDER INVESTIGATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ST. LUCIE 1 (PWR) * CONSTRUCTION * PUMPS * FEEDWATER * MAIN COOLING SYSTEM * TEST, SYSTEM OPERABILITY * TEST, PREOPERATIONAL * INSTRUMENT, PROTECTIVE * ACCIDENT, LOSS OF POWER * OFF SITE * FAILURE, DESIGN ERROR

100021

FINAL REPORT ON LACK OF HOT IN THE CONTAINMENT PENETRATIONS AT ST. LUCIE 1

FLORIDA POWER & LIGHT CO., MIAMI, FL

4 PGS. LTR WRPT TO NRC OFFICE OF I & E, DEC. 4, 1975, DOCKET 50-335, TYPE--PWR, NRC--COMB., AE--EBASCO

CAUSE - PROCEDURAL DEFICIENCY. DURING A QUALITY CONTROL REVIEW, IT WAS FOUND THAT 2 PRIMARY CONTAINMENT PENETRATION WELDS HAD NOT BEEN RADIOGRAPHED. THE ORIGINAL PROCEDURE ON QUALITY CLASS B LINES DID NOT REQUIRE RT. IT IS REQUIRED BY ANSI CODE B31.7. THE WELDS HAVE BEEN RADIOGRAPHED. OTHER LINES IN THE SAME CATEGORY ARE BEING AUDITED. PROCEDURE WAS AMENDED TO INCLUDE RT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ST. LUCIE 1 (PWR) * CONSTRUCTION * TEST, NONDESTRUCTIVE * WELDS * PIPES AND PIPE FITTINGS * QUALITY ASSURANCE * REVIEW * FAILURE, ADMINISTRATIVE CONTROL * PROCEDURES AND MANUALS * RADIOGRAPHY * PENETRATIONS, PRIMARY CONTAINMENT

100054

FINAL REPORT ON LEAKING SOCKET WELDS AT ST. LUCIE 1

FLORIDA POWER & LIGHT CO., MIAMI, FL

12 PGS. LTR WRPT TO NRC OFFICE OF I & E, DEC. 23, 1975, DOCKET 50-335, TYPE--PWR, NRC--COMB., AE--EBASCO

CAUSE - VIBRATION. DURING HOT OPERATIONS TESTING, SOCKET TYPE WELD FAILURES WERE FOUND IN A VENT LINE AND A DRAIN LINE. A PROGRAM WAS INITIATED TO ACCESS THE VIBRATION STRAIN IN ALL VENT AND DRAIN CONNECTIONS IN 4 SYSTEMS. THESE CONNECTIONS ARE OF 3/4, 1, AND 2-INCH DIAMETER PIPING. FOR THOSE CASES SUBJECT TO RESONANT CONDITIONS OF VIBRATION DURING NORMAL OPERATION, RESTRAINTS WILL BE PROVIDED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ST. LUCIE 1 (PWR) * CONSTRUCTION * WELDS * PIPES AND PIPE FITTINGS * LEAK * FAILURE, PIPE * VIBRATION * FAILURE, DESIGN ERROR * MODIFICATION * SUPPORT STRUCTURE * TEST, SYSTEM OPERABILITY * TEST, PREOPERATIONAL

100053

FINAL REPORT ON 4 KV BUS LOAD SHEDDING INCIDENT AT ST. LUCIE 1

FLORIDA POWER & LIGHT CO., MIAMI, FL

4 PGS. LTR WRPT TO NRC OFFICE OF I & E, DEC. 23, 1975, DOCKET 50-335, TYPE--PWR, NRC--COMB., AE--EBASCO

CAUSE - DESIGN DEFICIENCY. DURING ECCS PREOPERATIONAL TESTING, LOAD SHEDDING FOR THE 4160 V IAB SWITCH GEAR DID NOT OCCUR AS ANTICIPATED DURING SIMULATED LOSS OF OFF-SITE POWER DUE TO SIMULTANEOUS LOSS OF POWER FROM THE A BUS/AB BUS INTERLOCK CIRCUITRY. POWER TO THE A BUS/AB BUS INTERLOCK CIRCUITRY IS NOW SUPPLIED THROUGH INVERTERS FROM THE UNINTERRUPTABLE DC STATION BATTERIES. PREVIOUSLY POWER WAS SUPPLIED FROM THE SA/50 POWER DISTRIBUTION PANELS.

100053 *CONTINUED*
 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D.C. 20545 10 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

ST. LUCIE 1 (PWR) * CONSTRUCTION * ELECTRIC POWER * CONTROL SYSTEM * TEST, SYSTEM OPERABILITY * TEST,
 PREOPERATIONAL * FAILURE, DESIGN ERROR * ELECTRIC POWER, UNINTERRUPTED * MODIFICATION * ACCIDENT, LOSS OF
 POWER

093256
 UNPLANNED RELEASE OF LOW LEVEL RADIOACTIVE WATER TO RIVER AT SURRY 1
 VIRGINIA ELECTRIC AND POWER COMPANY
 6 PAGES, LETTER WITH AD REPORT 51/74/16 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 2, JANUARY 23,
 1975, DOCKET 50-200, TYPE-PWR, NRC--WEST., AE--STONE & WEBSTER

CAUSE - HEAT EXCHANGER TUBE LEAK. WITH BOTH UNITS AT COLD SHUTDOWN, A RADIATION MONITOR ALARM WAS
 RECEIVED FROM THE SERVICE WATER LEAVING THE COMPONENT COOLING HEAT EXCHANGERS. LEAKS TOTALING
 0.515 GPM WERE FOUND IN 2 TUBES OF A HEAT EXCHANGER. THE TUBES WERE REMOVED FOR EXAMINATION.
 THE STRIP CHART FOR THE MONITOR HAD AN UPWARD TREND FOR 11.25 MINUS PRIOR TO ISOLATING THE HEAT
 EXCHANGER. NO RELEASE LIMITS WERE EXCEEDED. THE RELEASE WAS CALCULATED TO BE 349 GALLONS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

RIVER * STRESS * REFUELING * RADIOACTIVITY RELEASE * FAILURE, TUBING * SURRY 1 (PWR) * LEAK * AUXILIARY
 COOLING SYSTEM * HEAT EXCHANGERS

093618
 SERVICE WATER RADIATION MONITOR FAILS AT SURRY 1
 VIRGINIA ELECTRIC AND POWER COMPANY
 5 PAGES, LETTER WITH EVENT REPORT 74/03 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 2, JANUARY 30, 1975,
 DOCKET 50-200, TYPE-PWR, NRC--WEST., AE--STONE & WEBSTER

CAUSE - SAMPLE PUMP FAILURE. A SMALL AMOUNT OF LOW LEVEL RADIOACTIVITY WAS RELEASED TO THE JAMES
 RIVER VIA THE COMPONENT COOLING SERVICE WATER AS REPORTED EARLIER. THE RADIATION MONITOR ON THE
 SERVICE WATER LINE OF THE HEAT EXCHANGER DID NOT ALARM DURING THIS PERIOD. FLOW THROUGH THE
 MONITOR WAS LESS THAN REQUIRED FOR PROPER OPERATION. THE SAMPLE PUMP HAD FAILED DUE TO BEARING
 FAILURE FROM LACK OF WATER LUBRICATION. THE SYSTEM DESIGN WOULD NOT ALLOW A PRIME TO BE
 MAINTAINED. THE PUMP WAS REPAIRED. SAMPLE SYSTEM PIPING WAS MODIFIED TO ASSURE PRIME.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

SAMPLING * MODIFICATION * FAILURE, DESIGN ERROR * AUXILIARY COOLING * SURRY 1 (PWR) * FLJW * AUXILIARY COOLING
 SYSTEM * PUMPS * RADIATION MONITORS

100266
 STEAM GENERATOR BLOWDOWN ACTIVITY NOT MONITORED AT SURRY 1
 VIRGINIA ELECTRIC AND POWER COMPANY
 2 PAGES, LETTER WITH AD REPORT 75/01 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 11, FEBRUARY 21,
 1975, DOCKET 50-200, TYPE-PWR, NRC--WEST., AE--STONE & WEBSTER

CAUSE - OPERATOR ERROR. ALL 3 STEAM GENERATOR BLOWDOWN COOLERS WERE ISOLATED RESULTING IN
 BLOWDOWN ACTIVITY NOT BEING MONITORED BY THE MONITORING SYSTEM FOR 9 HOURS. ONE COOLER WAS THEN
 RETURNED TO SERVICE AND ALL SAMPLES WERE DIRECTED THROUGH IT. FAILURE WAS DUE TO OPERATOR ERROR.
 INVOLVED PERSONNEL WERE INSTRUCTED IN PROPER OPERATING CONDITIONS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D.C. 20545 10 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

FAILURE, OPERATOR ERROR * SAMPLING * COOLANT PURIFICATION SYSTEM * MONITORING SYSTEM, RADIATION * STEAM
 GENERATOR * SURRY 1 (PWR) * RADIATION MONITORS

100263
 PRIMARY SYSTEM BORON CONCENTRATION DILUTED AT SURRY 1
 VIRGINIA ELECTRIC AND POWER COMPANY
 1 PAGES, LETTER WITH AD REPORT 75/01 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 2, FEBRUARY 24, 1975,
 DOCKET 50-200, TYPE-PWR, NRC--WEST., AE--STONE & WEBSTER

CAUSE - LOSS OF POWER TO INSTRUMENT BUS. UNIT 1 WAS IN A COLD SHUTDOWN CONDITION FOR A REFUELING
 OUTAGE. PREPARATIONS WERE BEING MADE TO START UP BUT CONTAINMENT INTEGRITY HAD NOT BEEN
 ESTABLISHED. BORON CONCENTRATION IN THE PRIMARY COOLANT WAS FOUND TO HAVE DECREASED TO 1842 PPM.
 PRIMARY GRADE WATER FLOW CONTROLLER WAS FOUND IN MANUAL MODE WITH ITS VALVE IN FULL OPEN
 POSITION. THE CONTROLLER WAS RETURNED TO AUTOMATIC MODE. A TEMPORARY LOSS OF POWER TO VITAL BUS
 3 CAUSED THE CONTROLLER SWITCH TO SWITCH FROM AUTOMATIC TO MANUAL. THE NORMALLY CLOSED VALVE
 HAPPENED TO BE FULL OPEN AT THE TIME AND REMAINED SO. THE INDICATING LIGHT FOR THIS CONDITION
 HAD BURNED OUT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

100203 CONTINUED

CAUSE - FAILURE, OPERATOR ERROR - ELECTRIC POWER - REACTOR COOLANT - INSTRUMENT, CONTROL - REFUELING - CHEMICAL SHUT - MAIN COOLING SYSTEM - SUMMARY 1 (PWR) - CONCENTRATION

100073

DEBRIS IN REACTOR VESSEL AT SUMMARY 1
VIRGINIA ELECTRIC AND POWER COMPANY

4 PAGES, LETTER WITH SPECIAL REPORT 50-51-75-01 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 2, FEBRUARY 24, 1975, Docket 50-200, TYPE-PWR, NRC-WEST, AC-STONE & WEBSTER

CAUSE - PARTIAL COLLAPSE OF WALL. THE REACTOR HEAD HAD BEEN REMOVED FOR REFUELING AND THE UPPER INTERNALS AND ALL FUEL HAD BEEN REMOVED FROM THE VESSEL. ABOUT 45 CONCRETE BLOCKS FELL FROM THE TOP TWO RINGS OF A CONCRETE BLOCK WALL ON THE NORTH SIDE OF THE PRESSURIZER CUBICLE DURING REMOVAL OF THE CUBICLE COVER. ONE BLOCK FELL INTO REACTOR CAUSTY 3 FEET FROM THE REACTOR VESSEL. OTHER DEBRIS 12 INCHES IN DIAMETER AND SMALLER WAS DEPOSITED WITHIN THE REACTOR VESSEL AND ON THE UPPER INTERNALS. ALL PARTICLES WERE REMOVED BY BLINDING AN EJECTOR. NEITHER THE VESSEL NOR THE ASSOCIATED SYSTEMS WERE DAMAGED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20543, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT - PRESSURE VESSELS - BUILDING - CAND - REFUELING - FAILURE, MAINTENANCE ERROR - CORE COMPONENTS - SUMMARY 1 (PWR)

100205

PROCESS VENTS GASEOUS WASTE RELEASE AT SUMMARY 1
VIRGINIA ELECTRIC AND POWER COMPANY

6 PAGES, LETTER WITH REPORT 75/03 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 2, FEBRUARY 24, 1975, Docket 50-200, TYPE-PWR, NRC-WEST, AC-STONE & WEBSTER

CAUSE - MALFUNCTION OF PRESSURE CONTROLLER. WHILE THE UNIT WAS AT COLD SHUTDOWN, PARTICULATE MONITOR ALARMS SOUNDED. THE INVESTIGATION REVEALED THAT THE RELIEF VALVE IN THE LINE TO THE WINDROCK RECOMBINER HAD LIFTED. THE RELEASE WAS TERMINATED BY CLOSING THE MANUAL ISOLATION VALVE. THE PRESSURE REGULATING VALVE IN THIS LINE HAD FAILED. THE UNIT HAD BEEN SHUTDOWN FOR 3 MONTHS. DIRT AND CORROSION PRODUCTS PROBABLY ACCUMULATED IN THE REGULATOR. WHEN THE VALVE WAS TAPPED WITH A HAMMER IT STARTED CONTROLLING. PRESSURE WAS REGULATED TO THE REQUIRED 1 PSIG. THE REASON FOR THE PARTICULATE MONITOR ALARMING RATHER THAN THE GAS MONITOR IS UNDER INVESTIGATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20543, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

AIRBORNE RELEASE - FAILURE, EQUIPMENT - WASTE HANDLING - WASTE TREATMENT - CONTROL - CAND - REFUELING - OFF GAS - PRESSURE, INTERNAL - SUMMARY 1 (PWR) - VALVES

100206

CONTAINMENT INSTRUMENT AIR SYSTEM NOT PROPERLY ISOLATED AT SUMMARY 1
VIRGINIA ELECTRIC AND POWER COMPANY

5 PAGES, LETTER WITH REPORT 75/02 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 2, FEBRUARY 24, 1975, Docket 50-200, TYPE-PWR, NRC-WEST, AC-STONE & WEBSTER

CAUSE - OPERATOR ERROR. AS PART OF THE PREPARATION FOR STARTUP FOLLOWING A REFUELING OUTAGE, A VALVE POSITION VERIFICATION WAS PERFORMED. DURING WARM UP, THE OPERATOR NOTED THAT THE CONTAINMENT INSTRUMENT AIR PRESSURE WAS THE SAME AS STATION INSTRUMENT AIR INSTEAD OF 10 PSIG LOWER, WHICH IS NORMAL. THE CONTAINMENT ISOLATION VALVES WERE OPEN. SINCE THESE VALVE NUMBERS STARTED WITH 2, THE OPERATOR ASSUMED THE VALVES WERE FOR UNIT 2 AND DID NOT CLOSE THEM AS INSTRUCTED. THE VALVE WERE CLOSED. OPERATOR INSTRUCTED TO FOLLOW PROCEDURES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20543, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATOR ERROR - CONTAINMENT ISOLATION - PROCEDURES AND MANUALS - CONTAINMENT INTEGRITY - SUMMARY 1 (PWR) - PNEUMATIC SYSTEM - INSTRUMENTS, ETC.

100030

SETPOINT DRIFT IN PRESSURIZER PRESSURE COMPARISON AT SUMMARY 1
VIRGINIA ELECTRIC AND POWER COMPANY

2 PAGES, LETTER WITH REPORT 51-75-05 TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, REGION 2, FEBRUARY 27, 1975, Docket 50-200, TYPE-PWR, NRC-WEST, AC-STONE & WEBSTER

CAUSE - COMPONENT FAILURE. DURING CALIBRATION TESTS, THE PRESSURIZER PRESSURE COMPARISON WAS FOUND TO HAVE A TRIP SETPOINT OF 1010 PSIG INSTEAD OF 1075 PSIG LIMIT. THE MAGN COMPUTER SYSTEMS MODEL 110 SIGNAL COMPARISON WAS REPLACED. THE CAUSE OF DRIFT WAS A COMPONENT FAILURE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20543, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT - INSTRUMENT CALIBRATION - FAILURE, INSTRUMENT - INSTRUMENT, SWITCH - PRESSURIZER - TEST, SYSTEM OPERABILITY - SUMMARY 1 (PWR) - SET POINT - DRIFT - SIGNALS, PRESSURE

101719

RADIATION MONITOR SAMPLE PUMP FAILS AT SURRY 1

VIRGINIA ELECTRIC & POWER COMPANY

2 PAGES, LETTER WITH NO REPORT 75/01 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, MARCH 25, 1975, DOCKET 50-200.

TYPE--PWR, NRG--WEST., AE--STONE & WEBSTER

CAUSE - EROSION DUE TO CAVITATION. DURING ROUTINE FLUX VERIFICATION, THE SH PUMP SUPPLYING THE RADIATION MONITOR WITH SAMPLE FROM THE SH SIDE OF THE CLM'S WAS FOUND TO HAVE FAILED. THE INSERIAL HAND PUMP MODEL A (CENTRIFUGAL PUMP) FAILED DUE TO EROSION CAUSED BY CAVITATION DURING NORMAL OPERATION. THE NPSH WAS NOT PRESENT. A ONCE-PER-SHIFT SAMPLING HAS BEEN INITIATED UNTIL A DESIGN MODIFICATION IS INSTALLED. A POSITIVE DISPLACEMENT PUMP PER COOLER WILL BE USED IN LIEU OF THE PRESENT CENTRIFUGAL PUMP FOR ALL 4 COOLERS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

HYDRAULIC EFFECT + SAMPLING + MODIFICATION + FAILURE, DESIGN ERROR + EROSION + ABNORMAL COOLING + SURRY 1 (PWR) + PUMPS + RADIATION MONITORS

101720

UNPLANNED RELEASE OF LOW LEVEL RADIOACTIVE WATER AT SURRY 1

VIRGINIA ELECTRIC & POWER COMPANY

2 PAGES, LETTER WITH NO REPORT 75/07 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, MARCH 26, 1975, DOCKET 50-200.

TYPE--PWR, NRG--WEST., AE--STONE & WEBSTER

CAUSE - OPERATOR OVERSIGHT. AN UNCONTROLLED AND UNPLANNED RELEASE OF LOW LEVEL RADIOACTIVE WATER WAS MADE TO THE DISCHARGE CANAL WHEN A PRIMARY GRADE WATER TANK OVERFLOWED FOR 2 HOURS. THE CAUSE WAS OVERSIGHT OF SHIFT PERSONNEL BECAUSE OF OTHER PRESSING EVENTS. THE OVERFLOW WAS STOPPED BY ISOLATING THE FILL. TOTAL ACTIVITY RELEASED WAS 0.106 CI. OPERATORS WERE RE-INSTRUCTED ON MAINTAINING PROPER CONTROL DURING FILLING OF TANKS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATOR ERROR + WATER + REACTOR COOLANT + STORAGE CONTAINER + RADIOACTIVITY RELEASE + CANAL + SURRY 1 (PWR)

101729

NUCLEAR AXIAL OFFSET OUT OF TARGET BAND AT SURRY 1

VIRGINIA ELECTRIC & POWER COMPANY

3 PAGES, LETTER WITH NO REPORT 75/08 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, APRIL 11, 1975, DOCKET 50-200.

TYPE--PWR, NRG--WEST., AE--STONE & WEBSTER

CAUSE - PROCEDURAL DEFICIENCY. THE NUCLEAR AXIAL OFFSET WAS OUT OF THE TARGET BAND (50) FOR 1.5 HR. DURING A STARTUP WHILE POWER WAS BELOW 50%. THE OPERATOR RESTORED THE OFFSET TO WITHIN THE BAND PRIOR TO EXCEEDING 50% AND BELIEVED THE DELTA FLUX ALARM WHICH OCCURRED AT 50% TO BE IN ERROR. THE REQUIRED 2 SURVEILLANCE WAS NOT PERFORMED FOR A 3 HOUR PERIOD. PROCEDURE SPECIFYING THE ANNUNCIATOR RESPONSE WAS INADEQUATE. IT HAS BEEN REVISED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FLUX DISTRIBUTION + PROCEDURES AND MANUALS + TESTING + FLUX TILT + FAILURE, ADMINISTRATIVE CONTROL + SURRY 1 (PWR) + OPERATOR ACTION + REACTOR STARTUP

101730

PROCESS VENT GASEOUS RADIATION MONITOR LEFT IN CALIBRATE AT SURRY 1

VIRGINIA ELECTRIC & POWER COMPANY

3 PAGES, LETTER WITH NO REPORT 75/09 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, APRIL 10, 1975.

DOCKET 50-200, TYPE--PWR, NRG--WEST., AE--STONE & WEBSTER

CAUSE - OPERATOR ERROR. THE PROCESS VENT GASEOUS WASTE MONITOR MODE SWITCH WAS PLACED IN THE CALIBRATE POSITION TO DEMONSTRATE TO A TRAINEE WHICH VALVES ACTUATE ON A HIGH ALARM. IT WAS INADVERTENTLY LEFT IN THIS POSITION. DURING A RADIATION MONITOR CHECK 24 HOURS LATER THE MISTAKE WAS FOUND AND CORRECTED BUT NOT REPORTED FOR ANOTHER 20 HOURS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATOR ERROR + VENTILATION SYSTEM + SURRY 1 (PWR) + OPERATOR ACTION + RADIATION MONITORS

102270

RADIATION MONITOR LEFT IN CALIBRATE POSITION AT SURRY 1

VIRGINIA ELECTRIC & POWER CO.

3 PAGES, LETTER WITH NO REPORT 75/09 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, APRIL 10, 1975, DOCKET 50-200.

TYPE--PWR, NRG--WEST., AE--STONE & WEBSTER

CAUSE - OPERATOR OVERSIGHT. THE PROCESS VENT GASEOUS WASTE MONITOR MODE SWITCH WAS PLACED IN THE

102270 *CONTINUED*

CAUTIONATE POSITION TO DEMONSTRATE TO A TRAINEE WHICH AUTOMATIC VALVES IN THE PROCESS VENT SYSTEM ACTIVATE WHEN AN ALARM INITIATES. IT WAS INADVERTENTLY LEFT IN CAUTIONATE. DURING A CHECK 20 HOURS LATER, THE ERROR WAS FOUND AND CORRECTED. THE ONE RESPONSIBLE FOR THIS WAS INSTRUCTED ON THE SERIOUSNESS OF THE SITUATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATOR ERROR • CONTAINMENT ISOLATION • VENTILATION SYSTEM • CONTROL • INSTRUMENT, SWITCH • SURRY 1 (PWR) • RADIATION MONITORS

102470

AUTOMATIC ISOLATION VALVE FAILS TO CLOSE AT SURRY 1

VIRGINIA ELECTRIC AND POWER CO.

3 PAGES, LETTER WITH ADM 75-10 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, APRIL 22, 1975, DOCKET 90-200, TYPE--PWR, RFG--WEST., AE--STONE & WEBSTER

CAUSE - DRTY RELAY. AN ALARM ON THE PROCESS VENT SYSTEM PARTICULATE RADIATION MONITOR WAS MANUALLY INITIATED TO DEMONSTRATE THE OPERATION OF VARIOUS TRIP VALVES IN THE SYSTEM TO A TRAINEE. THE AUTOMATIC ISOLATION VALVE FOR UNIT 2 CONTAINMENT VACUUM PUMP DISCHARGE DID NOT SHUT AS REQUIRED. A RELAY IN THE CONTROL CIRCUIT FOR THE VALVE WAS STUCK IN THE OPERATOR POSITION. THE RELAY WAS EXCESSIVELY DIRTY WHICH PREVENTED PROPER OPERATION. THE RELAY WAS CLEANED AND TESTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 1 (PWR) • VALVES • CONTAINMENT ISOLATION • FAILURE, COMPONENT • PRELIMS • FAILURE, MAINTENANCE ERROR • CRUD

102279

UNPLANNED RELEASE OF RADIOACTIVE WATER AT SURRY 1

VIRGINIA ELECTRIC & POWER CO.

2 PAGES, LETTER WITH ADM 75/07 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, APRIL 22, 1975, DOCKET 90-200, TYPE--PWR, RFG--WEST., AE--STONE & WEBSTER

CAUSE - OPERATOR. ABOUT 5400 GALLONS OF WATER OVERFLOWED THE PG WATER TANK INTO THE DISCHARGE CANAL OVER A 1 HR. 40 MIN PERIOD. SHIFT PERSONNEL DID NOT TERMINATE FILLING THE TANK AT THE TIME OF THE TANK HIGH LEVEL ALARM. ABOUT .100 CI OF TRITIUM WERE RELEASED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATOR ERROR • REACTOR CIRCUIT • STORAGE CONTAINER • RADIOACTIVITY RELEASE • SURRY 1 (PWR)

102274

CHARGING PUMP RECIR LINE DEVELOPS PINHOLE LEAK AT SURRY 1

VIRGINIA ELECTRIC & POWER CO.

2 PAGES, LETTER WITH ADM 75/11 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, APRIL 20, 1975, DOCKET 90-200, TYPE--PWR, RFG--WEST., AE--STONE & WEBSTER

CAUSE - NOT STATED. DURING NORMAL OPERATION, A PINHOLE LEAK DEVELOPED IN THE RECIRCULATION LINE ON A CHARGING PUMP RESULTING IN AN UNPLANNED RELEASE OF RADIOACTIVE MATERIAL FROM THE SITE. THE LEAK WAS THROUGH A WELD ON A 2 INCH STAINLESS STEEL PIPE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, PIPE • WELDS • RADIOACTIVITY RELEASE • SURRY 1 (PWR) • LEAK • FEEDWATER • PIPES AND PIPE FITTINGS

102495

EMERGENCY DIESEL GENERATOR FAILS AT SURRY 1

VIRGINIA ELECTRIC AND POWER COMPANY

3 PAGES, LETTER WITH ADM 75-12 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, MAY 9, 1975, DOCKET 90-200, TYPE--PWR, RFG--WEST., AE--STONE & WEBSTER

CAUSE - TURBO-BLOWER FAILURE. WITH THE UNIT OPERATING AT 100% POWER, EMERGENCY DIESEL GENERATOR 3 FAILED WHILE RUNNING AND FEEDING BUS 2J. SEVERAL ATTEMPTS TO RESTART THE ENGINE FAILED. FAILURE LED TO THE REACTOR TRIPPING. THE PLANETARY AND SPLINE SHAFT GEARS OF THE MECHANICAL DRIVE OF THE TURBO-BLOWER WERE PARTIALLY STRIPPED OF TEETH. THE DRIVE IS DESIGNED TO OPERATE ONLY LONG ENOUGH FOR THE ENGINE SPEED AND EXHAUST TEMPERATURE TO CAP THE TURBINE DRIVE TO OVERRUN THE MECHANICAL DRIVE AND DISENGAGE THE CLUTCH. THE ENGINE SPEED AND LOADING WERE NOT SUFFICIENT FOR THIS. SPEED AND LOADING WILL BE INCREASED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 1 (PWR) • GENERATOR, DIESEL • ENGINES, INTERNAL COMBUSTION • FAILURE, COMPONENT • SCRAM, REEL •

102995 PLANTWIDE
HEALTH SITUATION + EMERGENCY POWER, ELECTRIC

102119
CHEMICAL ADDITION TANK DISCHARGE VALVE FAILS TO OPEN AT SURRY 1
VIRGINIA ELECTRIC & POWER CO.
5 PAGES, LETTER WITH AUG 25-13 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, MAY 10, 1975, DOCKET 50-200. TYPE--PWR, NRC--WEST., AE--STONE & WEBSTER

CAUSE - UNKNOWN. THE CHEMICAL ADDITION TANK DISCHARGE VALVE ON THE RUST FAILED TO OPEN DURING A TEST. THE ALJCO 6-IN. 150 LB. STAINLESS STEEL GATE VALVE WITH LEVERHOLME OPERATOR WAS MANUALLY OPENED AND THEREAFTER CYCLED ELECTRICALLY. NO ABNORMAL CONDITION WAS FOUND. APPARENTLY, SMALL DEBRIS IN THE VALVE SEAM AREA CAUSED THE INITIAL PROBLEM. THE REACTOR WAS OPERATING AT FULL POWER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 1 (PWR) + VALVES + POSITIVE + REACTOR COOLANT + STORAGE CONTAINER + TEST, SYSTEM OPERABILITY + FAILURE, EQUIPMENT + CAND + CHEMICAL SPIN

104062
PINHOLE LEAK DEVELOPS IN CHARGING PUMP RECIRCULATION LINE AT SURRY 1
VIRGINIA ELECTRIC & POWER COMPANY
5 PAGES, LETTER WITH AUG 25-11 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, JULY 11, 1975, DOCKET 50-200. TYPE--PWR, NRC--WEST., AE--STONE & WEBSTER

CAUSE - UNKNOWN. WHILE THE UNIT WAS OPERATING AT FULL POWER, THE VENTILATION VENT SAMPLE ALARMED INDICATING HIGH AIRBORNE PARTICULATE ACTIVITY. A PINHOLE LEAK WAS DISCOVERED ON THE CHARGING PUMP RECIRCULATION LINE. THE CHARGING PUMP WAS ISOLATED AND DRAINED. ABOUT 25 GALLONS OF REACTOR COOLANT LEAKED OUT RELEASING 897 MICROCURIES OF ACTIVITY. TWO SMALL LEAKS HAVE PREVIOUSLY OCCURRED THAT APPEAR TO BE RELATED TO HYDRAULIC EROSION AND/OR CAVITATION IN THE RECIRCULATION LINE. THE NUCLEAR STEAM SUPPLIER HAS NOT PROVIDED A FIRM RECOMMENDATION FOR A SOLUTION TO THE PROBLEM.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 1 (PWR) + PIPES AND PIPE FITTINGS + LEAK + OPEEWATER + FAILURE, PIPE + EROSION + AIRBORNE RELEASE + REACTOR COOLANT + HYDRAULIC EFFECT

104303
VENTILATION VENT ACTIVITY HIGH AT SURRY 1
VIRGINIA ELECTRIC & POWER COMPANY, RICHMOND
5 PAGES, LETTER WITH REPORT TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, JULY 25, 1975. DOCKET 50-200. TYPE--PWR, NRC--WEST., AE--STONE & WEBSTER

CAUSE - CONTAINMENT PURGING. ROUTINE SAMPLING OF THE VENTILATION VENT ACTIVITY REVEALED AN 1-131 ACTIVITY OF 4.08 UP THE LIMIT. PURGING OPERATIONS AND MAINTENANCE ACTIVITIES ASSOCIATED WITH THE SHUTDOWN ARE BELIEVED TO BE THE CAUSE. THIS, ALONG WITH LIQUID WASTE PROCESSING RAISED THE LEVEL ABOVE THE 4.1 LIMIT. CONTAINMENT PURGE EXHAUST WAS DIVERTED THROUGH THE CHARCOAL FILTER SYSTEM. 1-131 ACTIVITY IN THE NEXT DAY'S SAMPLE WAS 2.96.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 1 (PWR) + RELEASE RATE + IODINE + FISSION PRODUCT, IODINE + CONTAINMENT PURGE + VENTILATION SYSTEM + WASTE TREATMENT

105277
BORON CONCENTRATION IN SI ACCUMULATOR BELOW LIMITS AT SURRY 1
VIRGINIA ELECTRIC & POWER COMPANY, RICHMOND
5 PAGES, LETTER WITH AUG 25-10 TO NRC OFFICE OF I & E, REGION 2, AUG. 12, 1975, DOCKET 50-200. TYPE--PWR, NRC--WEST., AE--STONE & WEBSTER

CAUSE - INLEAKAGE THROUGH CHECK VALVES. DURING STARTUP OPERATIONS, SAMPLING OF THE SAFETY INJECTION ACCUMULATORS REVEALED THAT THE BORON CONCENTRATION IN ONE WAS 1050 PPM WHICH IS LESS THAN THE 1050 PPM LIMIT. THE ACCUMULATOR WAS DILUTED DURING UNIT WARM-UP BY INLEAKAGE THROUGH THE PRIMARY SYSTEM. THE REACTOR WAS MADE SUBCRITICAL UNTIL THE CONCENTRATION WAS INCREASED ABOVE THE LIMIT. PRESSURE INCREASED SUFFICIENTLY TO SEAT THE CHECK VALVES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 1 (PWR) + BORON + CONCENTRATION + ACCUMULATORS + REACTOR SHUTDOWN + FAILURE, EQUIPMENT + LEAK + VALVE, CHECK

10496

BORON CONCENTRATION IN ACCUMULATOR LESS THAN LIMIT AT SURRY 1

VIRGINIA ELECTRIC AND POWER CO., RICHMOND

3 PGS. LETTER WITH AN REPORT 31-75 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, AUG. 12, 1975, DOCKET 50-200, TYPE--PWR, HFC--WEST., AE--STONE & WEBSTER

CAUSE - CHECK VALVE LEAKAGE. DURING STARTUP, SAMPLING OF THE SAFETY INJECTION ACCUMULATORS REVEALED THAT THE BORON CONCENTRATION IN ACCUMULATOR 1C WAS 1050 PPM WHICH IS LESS THAN THE 1950 PPM LIMIT. THE REACTOR WAS MADE SUBCRITICAL UNTIL THE BORON CONCENTRATION WAS INCREASED TO ABOVE THE LIMIT. INLEAKAGE OCCURRED THROUGH THE LOOP CHECK VALVES WHEN THE ACCUMULATOR DISCHARGE VALVE WAS OPENED AT A PRIMARY SYSTEM PRESSURE OF 950 PSI. PRESSURE WAS INCREASED TO SEAT THE CHECK VALVES AND STOP THE INLEAKAGE. THE ACCUMULATOR HAD BEEN DRAINED TO THE PROPER LEVEL WITHOUT SAMPLING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 1 (PWR) • BORON • POISON, SOLUBLE • CHEMICAL SWIM • ACCUMULATORS • FAILURE, EQUIPMENT • VALVE, CHECK • LEAK • FAILURE, OPERATOR ERROR • SAMPLING • CONCENTRATION

104982

UNPLANNED RELEASE OF AIRBORNE RADIOACTIVITY AT SURRY 1

VIRGINIA ELECTRIC AND POWER COMPANY, RICHMOND

3 PGS. LTR W/DR 75-15 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, AUG. 10, 1975, DOCKET 50-200, TYPE--PWR, HFC--WEST., AE--STONE & WEBSTER

CAUSE - LOOSE FITTING. DURING FULL POWER OPERATION, A LEAKING FITTING ON OVERHEAD GAS COMPRESSOR 8 RESULTED IN THE UNPLANNED RELEASE OF 20.5 CI OF RADIOACTIVE MATERIAL FROM THE SITE. THE LEAKING FITTING WAS REPAIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 1 (PWR) • AIRBORNE RELEASE • LEAK • PIPES AND PIPE FITTINGS • WASTE TREATMENT • WASTE TREATMENT, GAS • WASTE HANDLING

100310

SET POINT DRIFT IN TEMPERATURE CHANNEL AT SURRY 1

VIRGINIA ELECTRIC & POWER CO., VIRGINIA

3 PGS. LTR W/DR 75-10 TO NRC OFFICE OF I & E, REGION 11, SEPT. 5, 1975, DOCKET 50-200, TYPE--PWR, HFC--WEST., AE--STONE & WEBSTER

CAUSE - REACTOR COOLANT LEAK. DURING OPERATION AT 90% POWER, CHANNEL 11 DELTA T/T AVG PROTECTION DRIFTED IN THE NONCONSERVATIVE DIRECTION CAUSED BY AN INCORRECT RESISTANCE OF THE HOT LEG RESISTANCE TEMPERATURE DETECTOR. THE INSTALLED SPARE WAS PLACED INTO SERVICE. THE CHANNEL DRIFTED AGAIN FOR THE SAME REASON. INVESTIGATION REVEALED THAT THE RTD WAS BEING SPRAYED WITH STEAM AND WATER FROM A PACKING LEAK ON A VALVE CAUSING INCORRECT OHMIC CHARACTERISTICS. THE PACKING WAS REPLACED AND THE RTD OHMIC CHARACTERISTICS RETURNED TO NORMAL AFTER THE RTD DRIED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 1 (PWR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • DRIFT • SET POINT • FAILURE, EQUIPMENT • VALUES • LEAK • SENSORS, TEMPERATURE • REACTOR SAFETY SYSTEM

100715

SET POINT DRIFT IN TEMPERATURE SENSOR AT SURRY 1

VIRGINIA ELECTRIC & POWER COMPANY, RICHMOND

3 PGS. LTR W/DR 75-16 TO NRC OFFICE OF I & E, REGION 2, SEPT. 5, 1975, DOCKET 50-200, TYPE--PWR, HFC--WEST., AE--STONE & WEBSTER

CAUSE - LEAK SPRAYING ON SENSOR. DURING NORMAL OPERATION AT 90% POWER, IT WAS NOTED THAT CHANNEL 11 DELTA T/T AVG PROTECTION HAD DRIFTED IN THE NON-CONSERVATIVE DIRECTION. AN INCORRECT RESISTANCE OF THE HOT LEG RESISTANCE TEMPERATURE DETECTOR CAUSED THE DRIFT. THE SPARE DETECTOR WAS PLACED IN SERVICE. THE NEXT DAY THE SAME CONDITIONS WERE FOUND. THEN, A REACTOR COOLANT LEAK OF ABOUT 2.5 GPM FROM THE PACKING OF A VALVE WAS FOUND TO BE SPRAYING ON THE DETECTORS. THIS CAUSED THE INCORRECT RESISTANCE. THE REACTOR WAS SHUT DOWN AND THE LEAK REPAIRED. WHEN THE DETECTORS DRIED, THEIR RESISTANCE RETURNED TO NORMAL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 1 (PWR) • INSTRUMENT, SWITCH • SENSORS, TEMPERATURE • REACTOR SAFETY SYSTEM • REACTOR SHUTDOWN • SET POINT • DRIFT • LEAK • MAIN COOLING SYSTEM

100315

VENTILATION VENT GASEOUS RELEASE EXCEEDS LIMIT AT SURRY 1

VIRGINIA ELECTRIC & POWER CO., VIRGINIA

100315 CONTINUED

2 PGS. LTR W/NO 51-75-06 TO NRC OFFICE OF I & E, REGION II, SEPT. 15, 1975, DOCKET 50-200, TYPE--PWR, RFG--
WEST., AE--STONE & WEBSTER

CAUSE - CONTAINMENT PURGING AND FITTING LEAK. THE RELEASE OF GASEOUS WASTES EXCEEDED 48 OF THE TECH SPEC LIMIT ON 2 OCCASIONS. ON JULY 30, SAMPLING OF THE VENTILATION VENT GASEOUS ACTIVITY REVEALED AN I-131 ACTIVITY OF 0.048 OF THE TECH SPEC LIMIT. THIS WAS ATTRIBUTED TO UNIT 1 CONTAINMENT PURGING OPERATIONS. FOLLOWING TERMINATION OF PURGING, ACTIVITY DROPPED TO 5.78 OF THE LIMIT. THE ACTIVITY ROSE AGAIN TO 0.238 OF LIMIT. THIS HAS BEEN ATTRIBUTED TO A LEAKING FITTING ON THE SULTON UNLOADER TO JERHEAD WAS COMPRESSOR 0. FOLLOWING ISOLATION OF THE COMPRESSOR, I-131 ACTIVITY DECLINED RAPIDLY, DROPPING BELOW THE 48 LEVEL TO 2 TO 38 ON AUG. 5.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 1 (PWR) • RELEASE RATE • PURGING • VENTILATION SYSTEM • CONTAINMENT • CONTAINMENT PURGE • LEAK • PIPES AND PIPE FITTINGS • AIRBORNE RELEASE • FAILURE, PIPE • WASTE TREATMENT, GAS

100400

HEAT TRACING CIRCUIT FAILS AT SURRY 1
VIRGINIA ELECTRIC & POWER CO., VIRGINIA

3 PGS. LTR W/NO 51-75-17 TO NRC OFFICE OF I & E, REGION II, SEPT. 25, 1975, DOCKET 50-200, TYPE--PWR, RFG--
WEST., AE--STONE & WEBSTER

CAUSE - TRANSFORMER SHORTED BY WATER LEAK. DURING FULL POWER OPERATION, A CHANNEL OF THE REACTOR HEAT TRACING HAD FAILED. THE BREAKER FOR HEAT TRACING PANEL 1 HAD TRIPPED ON OVERLOAD DUE TO ITS POWER TRANSFORMER BEING SHORT CIRCUITED BY A SERVICE WATER LEAK. THE LEAK WAS FROM A FAILED TEMPORARY PIPING WHICH WAS ASSOCIATED WITH AN EARLIER SERVICE WATER PIPING LEAK. THE LEAK WAS SECURED AND THE TRANSFORMER WAS REPAIRED. THE HEAT TRACING CIRCUIT WAS RETURNED TO SERVICE IN ABOUT 8 HOURS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 1 (PWR) • THERMS • PIPES AND PIPE FITTINGS • LEAK • FAILURE, EQUIPMENT • TRANSFORMERS

100402

TEMPERATURE DIFFERENTIAL INSTRUMENTATION DRIFTS LOW AT SURRY 1

VIRGINIA ELECTRIC & POWER CO., VIRGINIA

2 PGS. LTR W/NO 51-75-18 TO NRC OFFICE OF I & E, REGION II, OCT. 3, 1975, DOCKET 50-200, TYPE--PWR, RFG--
WEST., AE--STONE & WEBSTER

CAUSE - HIGH MOISTURE IN ATMOSPHERE. WHILE THE REACTOR WAS OPERATING AT 99.58 POWER, LOOP A DELTA T INSTRUMENTATION DRIFTED LOW TO A SETTING LESS CONSERVATIVE THAN THE TECH SPEC LIMIT. A MUSEMONT ENCL. CO., MODEL 176 HP RTD (RTD) HAD DRIFTED LOW DUE TO HIGH MOISTURE IN THE CONTAINMENT ATMOSPHERE WHICH CAUSED INSULATION RESISTANCE TO GROUND TO DECREASE. THE RTD WILL BE REPAIRED OR REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 1 (PWR) • INSTRUMENT, SWITCH • SENSORS, TEMPERATURE • FAILURE, INSTRUMENT • HUMIDITY, RELATIVE • REACTOR SAFETY SYSTEM • DRIFT • INSULATION • INSTRUMENTS, MISC.

100403

TEMPERATURE DIFFERENTIAL INSTRUMENT DRIFTS LOW AT SURRY 1

VIRGINIA ELECTRIC & POWER CO., VIRGINIA

3 PGS. LTR W/NO 51-75-19 TO NRC OFFICE OF I & E, REGION II, OCT. 3, 1975, DOCKET 50-200, TYPE--PWR, RFG--
WEST., AE--STONE & WEBSTER

CAUSE - HIGH MOISTURE AROUND DETECTOR. WHILE THE UNIT WAS OPERATING AT 1338 POWER, DELTA T INSTRUMENTATION B DRIFTED LOW. CHANNEL A HAD BEEN TRIPPED PRIOR TO THIS. A UNIT SHUTDOWN WAS INITIATED. THE SPARE RTD WAS PLACED IN SERVICE AND THE SHUTDOWN TERMINATED. HIGH CONTAINMENT ATMOSPHERE MOISTURE CAUSED THE INSULATION RESISTANCE TO DECREASE. THE NEXT DAY THE SAME INCIDENT RE-OCCURRED ON THE SPARE RTD. UNIT SHUTDOWN WAS IMMEDIATELY INITIATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 1 (PWR) • SENSORS, TEMPERATURE • HUMIDITY, RELATIVE • FAILURE, INSTRUMENT • REACTOR SHUTDOWN • REACTOR SAFETY SYSTEM • THERMOCOUPLE

100403

SAFETY INJECTION RELAY IN ENERGIZED POSITION AT SURRY 1

VIRGINIA ELECTRIC & POWER CO., VIRGINIA

2 PGS. LTR W/NO 51-75-20 TO NRC OFFICE OF I & E, REGION II, OCT. 10, 1975, DOCKET 50-200, TYPE--PWR, RFG--
WEST., AE--STONE & WEBSTER

CAUSE - INSUFFICIENT SPRING TENSION. DURING SAFETY INJECTION FUNCTIONAL TESTS WITH THE REACTOR

100053 CONTINUING

SHUTDOWN FOR REFUELING. A RELAY FAILED IN THE ENERGIZED POSITION. AS A RESULT, THE CONTROL ROOM EMERGENCY PAN DID NOT TRIP AND ITS DAMPER DID NOT CLOSE. THE AMBATURE SPRING TENSION WAS INSUFFICIENT TO RETURN THE RELAY TO THE DE-ENERGIZED POSITION. SPRING TENSION WAS INCREASED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SUMMARY (PWR) - DELAYS - FAILURE, COMPONENT - TEST, SYSTEM OPERABILITY - SAFETY INJECTION - REFUELING

100062

SET POINT DRIFT IN MAIN STEAM SAFETY VALVES AT SHUTTY 1

VIRGINIA ELECTRIC & POWER CO., VIRGINIA

2 PGS. LTR W/AD-51-75-22 TO NRC OFFICE OF I & E, REGION II, OCT. 19, 1975, DOCKET 50-200, TYPE--PWR, NRC--WEST.. AT--STONE & WEBSTER

CAUSE - MANUAL DRIFT. DURING A REFUELING SHUTDOWN TEST OF MAIN STEAM SAFETY VALVE SET POINTS, 4 VALVES WERE NOT WITHIN PLUS OR MINUS 10 OF THE REQUIRED VALUE. THE APPARENT CAUSE WAS MANUAL SET POINT DRIFT. THEY WERE ADJUSTED AND RETESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SUMMARY (PWR) - VALVES - OPRESSURE RELIEF - CIRCUIT SYSTEM, SECONDARY - TEST, SYSTEM OPERABILITY - SET POINT - DRIFT - FAILURE, EQUIPMENT - REFUELING

100011

SAFETY INJECTION MASTER RELAY FAILS TO LATCH AT SHUTTY 1

VIRGINIA ELECTRIC & POWER CO., VIRGINIA

2 PGS. LTR W/AD-51-75-28 TO NRC OFFICE OF I & E, REGION II, OCT. 13, 1975, DOCKET 50-200, TYPE--PWR, NRC--WEST.. AT--STONE & WEBSTER

CAUSE - LAMP UP ADJUSTMENT. DURING THE REFUELING SHUTDOWN, A SAFETY INJECTION MASTER RELAY FAILED TO LATCH WHEN TESTING THE DRIFT. THE LATCH ADJUSTMENT SCREW WAS ADJUSTED IN ACCORDANCE WITH THE MANUFACTURER'S INSTRUCTION MANUAL. THE RELAY PERFORMED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SUMMARY (PWR) - DELAYS - SAFETY INJECTION - TEST, SYSTEM OPERABILITY - FAILURE, MAINTENANCE ERROR - FAILURE, INSTRUMENT - REFUELING

107431

SET POINT DRIFT IN PRESSURE TRANSDUCERS AT SHUTTY 1

VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA.

1 PGS. LTR W/AD-51-75-24 TO NRC OFFICE OF I & E, REGION II, OCT. 24, 1975, DOCKET 50-200, TYPE--PWR, NRC--WEST.. AT--STONE & WEBSTER

CAUSE - OVERRANGING ZERO SPRING. DURING CALIBRATION OF THE PRESSURIZER PRESSURE INSTRUMENTATION AT THE REFUELING OUTAGE, 3 CHANNELS WERE FOUND TO BE CONSERVATIVE BY 41.4 PSI, 57.0 PSI, AND 44.4 PSI FOR THE HIGH PRESSURE TRIP AND NONCONSERVATIVE BY 11.4 PSI, 27.3 PSI, AND 14.4 PSI FOR THE LOW PRESSURE TRIP. DURING PRIOR CALIBRATIONS THE ZERO SPRING HAD TO BE USED FOR ADJUSTMENTS GREATER THAN THE 0.50 RECOMMENDED BY THE MANUFACTURER. OVERADJUSTMENT OF THE ZERO SPRING COULD RESULT IN A WEARER TENDENCY TOWARD BOTH ZERO AND SPIN SHIFT. DRIFT HAS BEEN ATTRIBUTED TO OVERWINDING OF THE ZERO SPRING. PROCEDURES HAVE BEEN REVISED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SUMMARY (PWR) - INSTRUMENT, SWITCH - INSTRUMENT CALIBRATION - SENSORS, PRESSURE - TEST, SYSTEM OPERABILITY - SET POINT - DRIFT - FAILURE, CEMACH CODE - FAILURE, MAINTENANCE ERROR - REACTOR SAFETY SYSTEM - REFUELING - FAILURE, INSTRUMENT

107520

CONTAINMENT LEAK RATE EXCEEDS LIMIT AT SHUTTY 1

VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA.

1 PGS. LTR W/AD-51-75-24 TO NRC OFFICE OF I & E, REGION II, OCT. 30, 1975, DOCKET 50-200, TYPE--PWR, NRC--WEST.. AT--STONE & WEBSTER

CAUSE - DEFECTIVE STEAM GENERATOR TUBES. DURING THE REFUELING OUTAGE, PERFORMANCE OF THE TYPE A CONTAINMENT LEAK RATE TEST REVEALED THE MEASURED RATE TO BE 0.000181724 M3. THE LIMIT IS 0.18724 M3. THE PROBABLE SOURCE OF LEAKAGE WAS THROUGH 2 DEFECTIVE STEAM GENERATOR A TUBES. THE TUBES WILL BE PLUGGED. THE RECIRCULATION SPRAY SYSTEM ISOLATION VALVES ALSO LEAKED. THEY WILL BE REPAIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SUMMARY (PWR) - LEAK RATE - CONTAINMENT - TEST, LEAK RATE - TEST, SYSTEM OPERABILITY - REFUELING - STEAM

107526 PLUMING: JO
GENERATOR + FAILURE, TUBING + CONTAINMENT ISOLATION + VALVES

107096
VENTILATION VENT GASEOUS RELEASE EXCEEDS 48 OF LIMIT AT SURRY 1
VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA.
3 PGS. LTR WSA-SI-75-05 TO NRC OFFICE OF I & E, REGION II, NOV. 4, 1975, DOCKET 50-280, TYPE--PWR, NRC--
WEST., AE--STONE & WEBSTER

CAUSE - OPERATING CIRCUMSTANCES. THE VENTILATION VENT IODINE-131 ACTIVITY EXCEEDED 48 OF THE TECH
SPEC LIMIT FROM SEPT. 29 TO OCT. 23 DUE TO CONTAINMENT PURGING OPERATIONS, FILTER PROBLEMS, AND
LEAKAGE AND SUBSEQUENT TREATMENT OF RADIOACTIVE WATER WHICH HAD ACCUMULATED IN THE CONTAINMENT
BASEMENT. I-131 ACTIVITY FROM THE VENT SHOULD DECREASE BELOW 48 OF THE LIMIT IN THE NEAR FUTURE
AS REPLACEMENT OF FILTER CHARCOAL AND PROCESSING OF CONTAMINATED LIQUIDS IS COMPLETED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

SURRY 1 (PWR) + PLUMING RELEASE + VENTILATION SYSTEM + CHEMICAL ADSORBER + WASTE TREATMENT + FAILURE,
DESIGN ERROR + MISOPERATION + IODINE

100242
STEAM GENERATOR TUBE PULL APART AT SURRY 1
VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA.
3 PGS. LTR WSA-SI-75-06 TO NRC OFFICE OF I & E, REGION II, NOV. 26, 1975, DOCKET 50-280, TYPE--PWR, NRC--
WEST., AE--STONE & WEBSTER

CAUSE - MALFUNCTION OF CUTTER. TO ASSIST IN ANALYZING GENERIC STEAM TUBE CONCERNS, A TUBE WAS TO
BE CUT AND REMOVED FROM STEAM GENERATOR A. THE TUBE WAS PULLED APART IN THE REMOVAL OPERATION AS
A RESULT OF AN UNDETECTED MALFUNCTION OF THE INTERNAL TUBE CUTTER WHICH FAILED IN A MANNER WHICH
GAVE THE OPERATOR A FALSE INDICATION OF HAVING CUT COMPLETELY THROUGH THE TUBE WALL. THE
INADEQUATE PULLING DID NOT AFFECT THE STRUCTURAL INTEGRITY OF THE STEAM GENERATOR. THE
SURROUNDING TUBES WERE PLUGGED AS AN ADDED PRECAUTION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

SURRY 1 (PWR) + TUBING + STEAM GENERATOR + FAILURE, EQUIPMENT + SURVEILLANCE PROGRAM + FAILURE, MAINTENANCE
ERROR

100255
CONTROL ROD DRIVE SHAFT INADVERTENTLY BENT AT SURRY 1
VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA.
3 PGS. LTR WSA-SI-75-07 TO NRC OFFICE OF I & E, REGION II, NOV. 23, 1975, DOCKET 50-280, TYPE--PWR, NRC--
WEST., AE--STONE & WEBSTER

CAUSE - CRANE DRIVEN INTO UPPER INTERNALS. WHILE THE UNIT WAS IN THE REFUELING CONDITION
FOLLOWING FUEL MOVEMENT AND REPLACEMENT OF THE UPPER INTERNALS PACKAGE, THE MANIPULATOR CRANE
GUIDE RAIL WAS INADVERTENTLY DRIVEN INTO THE UPPER INTERNALS PACKAGE CARRYING THE SHAFT DRIVE AT
GUIDE LOCATION P-8. THE DRIVE SHAFT WAS NOT LATCHED TO ITS CONTROL ROD AT THE TIME. DETAILED
INVESTIGATION INDICATED THAT THE GUIDE TUBE ASSEMBLY AND RCCA ARE ACCEPTABLE FOR REUSE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

SURRY 1 (PWR) + CONTROL ROD DRIVE MECHANISMS + DAMAGE + CRANE + FAILURE, MAINTENANCE ERROR + REFUELING

100540
AUXILIARY FEEDWATER PUMP DISCHARGE VALVE FAILS TO OPEN AT SURRY 1
VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA.
3 PGS. LTR WSA-SI-75-26 TO NRC OFFICE OF I & E, REGION II, DEC. 11, 1975, DOCKET 50-280, TYPE--PWR, NRC--
WEST., AE--STONE & WEBSTER

CAUSE - SWITCH OUT OF ADJUSTMENT. WITH THE UNIT SHUT DOWN, AN AUXILIARY FEEDWATER PUMP DISCHARGE
VALVE FAILED TO AUTOMATICALLY OPEN WHEN BOTH MAIN FEED PUMPS WERE LOCKED OUT. A SWITCH IN THE
CONTROL CIRCUIT FAILED TO CLOSE. A SMALL ADJUSTMENT OF THE SWITCH'S LEVER ARM CORRECTED THE
PROBLEM.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

SURRY 1 (PWR) + VALVES + FEEDWATER + AUXILIARY + FAILURE, EQUIPMENT + FAILURE, MAINTENANCE ERROR +
INSTRUMENT, SWITCH

100549
PRIMARY GRADE WATER TANK OVERFILLED AT SURRY 1
VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA.

100544 *CONTINUUM

3 PGS. LTR WAO-51-75-25 TO NRC OFFICE OF I & E, REGION II, DEC. 11, 1975, DOCKET 50-200, TYPE--PWR, NRC--WEST., AE--STONE & WEBSTER

CAUSE - OPERATOR ERROR. DURING THE EARLY STAGES OF POST REFUELING START-UP, AN OPERATOR ON NUTTING CRUISE OBSERVED THAT THE PRIMARY GRADE WATER TANK, WHICH WAS BEING FILLED, WAS OVERFLOWING. THE FILL SOURCE WAS IMMEDIATELY ISOLATED. ABOUT 1000 GALLONS OF LOW LEVEL RADIOACTIVE PRIMARY GRADE WATER ENTERED THE YARD STORM DRAINS. ABOUT 0.021 CI OF ACTIVITY WAS RELEASED. FILLING OF SPECIFIED TANKS WILL CEASE UPON A HIGH LEVEL ALARM TO PREVENT REOCCURRENCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SUMRY 1 (PWR) * RADIOACTIVITY RELEASE * REACTOR COOLANT * STORAGE CONTAINER * FAILURE, OPERATOR ERROR

100670

INFORMATION CONCERNING DENTING OF STEAM GENERATOR TUBES AT SUMRY 1
VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA

9 PGS. LTR WAO-51-75-26 TO NRC OFFICE OF I & E, REGION II, DEC. 11, 1975, DOCKETS 50-200/201, TYPE--PWR, NRC--WEST., AE--STONE & WEBSTER

CAUSE - UNKNOWN. DURING THE CURRENT REFUELING OUTAGE, INSPECTIONS WERE CONDUCTED ON STEAM GENERATOR TUBES TO ACQUIRE ADDITIONAL INFORMATION CONCERNING DENTING. TWO TECHNICAL BULLETINS REPORT ON THE GENERAL PROBLEM OF DENTING. THE CAUSE HAS NOT BEEN DETERMINED. DENTING OCCURS IN TUBES IN THE REGION OF SUPPORT PLATES. THERE APPEARS TO BE NO LOSS IN INTEGRITY. TUBE WALLS ARE DEFORMED INWARD UP TO 7 MILS ON ONE RADIIUS. DENTING IS RATHER UNIFORM. NO GROSS WORKING OF THE TUBE SURFACE IS EVIDENT. NO EVIDENCE OF INTERGRANULAR STRESS CORROSION PRODUCT BUILDUP IN THE TUBE/TUBE SUPPORT ANNULUS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SUMRY 1 (PWR) * FAILURE, TUBING * STEAM GENERATOR * DEFORMATION * FAILURE, CORROSION * TUBING * METALLURGY * WATER TREATMENT * COOLANT QUALITY

109291

PRIMARY GRADE WATER TANK OVERFLOWS TO YARD AREA AT SUMRY 1

VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA

3 PGS. LTR WAO-51-75-27 TO NRC OFFICE OF I & E, REGION II, DEC. 10, 1975, DOCKET 50-200, TYPE--PWR, NRC--WEST., AE--STONE & WEBSTER

CAUSE - OPERATOR ERROR. WHILE THE REACTOR WAS IN HOT SHUTDOWN, PRIMARY GRADE WATER TANK 10 HAD BEEN FILLED AND WAS BEING LINED UP TO RECIRCULATE THE WATER. THE OPERATOR OPENED THE PUMP DISCHARGE TO TANK 1A AND WATER WAS INADVERTENTLY PUMPED FROM TANK 10 TO 1A CAUSING TANK 1A TO OVERFLOW. ABOUT 425 GALLONS OF PG WATER SPILLED TO THE YARD AREA AND PROBABLY THE STORM DRAINS. TOTAL ACTIVITY RELEASE WAS .02% CI.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SUMRY 1 (PWR) * RADIOACTIVITY RELEASE * REACTOR COOLANT * FAILURE, OPERATOR ERROR * STORAGE CONTAINER * SYSTEM CAPACITY

100800

AUXILIARY FEEDWATER PUMP DISCHARGE VALVE FAILS TO OPEN AT SUMRY 1

VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA

3 PGS. LTR WAO-51-75-28 TO NRC OFFICE OF I & E, REGION II, DEC. 31, 1975, DOCKET 50-200, TYPE--PWR, NRC--WEST., AE--STONE & WEBSTER

CAUSE - TIMING RELAY FAILURE. WITH THE UNIT IN SHUTDOWN, AN AUXILIARY FEEDWATER PUMP DISCHARGE VALVE FAILED TO AUTOMATICALLY OPEN WHEN A LOW-LOW LEVEL WAS EXPERIENCED DURING DRAINING OF STEAM GENERATOR B. THE TIMING RELAY PLUNGER FAILED TO ACTIVATE A MICROSWITCH NECESSARY FOR VALVE OPENING. THE TIMING RELAY/MICROSWITCH ASSEMBLY WAS REPLACED AND THE VALVE TESTED SATISFACTORILY. THE VALVE IS NORMALLY OPEN DURING POWER OPERATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SUMRY 1 (PWR) * VALVES * FEEDWATER * AUXILIARY * FAILURE, INSTRUMENT * RELAYS * FAILURE, EQUIPMENT * CONTAINMENT SYSTEM * COOLING SYSTEM, SECONDARY

100879

NORMAL CHARGING LINE STOP VALVE FAILS TO CLOSE AT SUMRY 1

VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA

3 PGS. LTR WAO-51-75-29 TO NRC OFFICE OF I & E, REGION II, DEC. 31, 1975, DOCKET 50-200, TYPE--PWR, NRC--WEST., AE--STONE & WEBSTER

CAUSE - LIMIT SWITCH GEAR FAILS. WHILE THE UNIT WAS IN COLD SHUTDOWN, 1 OF THE 2 NORMAL CHARGING LINE STOP VALVES FAILED TO FULLY CLOSE ON SIGNAL FROM THE CONTROL ROOM. THE PINION GEAR ON THE

100876 OCONTINUED

LIMIT SWITCH WOUND UP CAUSING THE THERMAL OVERLOAD TO OPEN. GEAR FAILURE WAS DUE TO MECHANICAL WEAR. THE LIMIT SWITCH ASSEMBLY WAS REPLACED AND THE VALVE PERFORMED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SUNNY 1 (PWR) • VALVES • VALVE OPERATORS • FEEDWATER • MAIN COOLING SYSTEM • FAILURE, COMPONENT

100444

AUXILIARY FEEDWATER PUMP DISCHARGE VALVE FAILS TO OPEN AT SUNNY 1

VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA

5 PAGES, LETTER WITH AD REPORT 52/75-20 TO NRC OFFICE OF 1 & C, REGION II, DEC. 31, 1975, Docket 50-200, TYPE--PWR, MFG--WEST., AE--STONE & WEBSTER

CAUSE - TIMING RELAY FAILURE. WITH THE UNIT SHUT DOWN, AN AUXILIARY FEEDWATER PUMP DISCHARGE VALVE FAILED TO AUTOMATICALLY OPEN WHEN A LOW-LOW LEVEL OCCURRED DURING DRAINING OF STEAM GENERATOR D. THE PLUNGER IN A CONTROL CIRCUIT TIMING RELAY FAILED TO ACTIVATE A MICROSWITCH NECESSARY FOR VALVE OPENING OPERATION. THE RELAY/MICROSWITCH ASSEMBLY WAS REPLACED AND THE VALVE TESTED SATISFACTORILY. THIS VALVE IS NORMALLY OPEN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SUNNY 1 (PWR) • VALVES • FEEDWATER • AUXILIARY • PUMPS • RELAYS • FAILURE, EQUIPMENT • FAILURE, INHERENT

053259

STEAM GENERATOR LEVEL INDICATION MALFUNCTION AT SUNNY 2

VIRGINIA ELECTRIC AND POWER COMPANY

5 PAGES, LETTER WITH AD REPORT 52/75/02 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 2, JANUARY 24, 1975, Docket 50-201, TYPE--PWR, MFG--WEST., AE--STONE & WEBSTER

CAUSE - VALVE STEAM LEAK. ON 2 OCCASIONS WHILE THE REACTOR WAS OPERATING AT POWER, A STEAM GENERATOR LEVEL TRANSMITTER DRIFTED BEYOND LIMITS. IN BOTH CASES A STEAM LEAK WAS FOUND AT THE CONDENSATE POT ISOLATION VALVE, ONCE BETWEEN THE BONNET AND VALVE BODY AND ONCE IN THE PACKING. AFTER THE LEAKS WERE REPAIRED THE INDICATIONS RETURNED TO NORMAL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

STEAM • INSTRUMENT, SWITCH • STEAM GENERATOR • LEAK • SUNNY 2 (PWR) • VALVES • SENSING, LEVEL

053255

SERVICE WATER VALVE PIT FLOODED AT SUNNY 2

VIRGINIA ELECTRIC AND POWER COMPANY

5 PAGES, LETTER WITH AD REPORT 52/75/01 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 2, JANUARY 24, 1975, Docket 50-201, TYPE--PWR, MFG--WEST., AE--STONE & WEBSTER

CAUSE - OPERATOR ERROR. WHILE OPERATING AT 30% POWER, IT WAS FOUND THAT HIGH WATER LEVEL EXISTED IN THE SUMP AREA OF THE HIGH PRESSURE HEATER DRAIN PUMPS AND THE RECIRCULATION SPRAY SERVICE WATER VALVE PIT. AN UNDESIRABLE SHUTDOWN WAS STARTED UNTIL THE WATER LEVEL WAS LOWER AND THE VALVES OPENED. THE TURBINE BUILDING SUMP HAD BEEN SHUT OFF TO MEASURE FLOW TO THE SUMP. THE WORKER WAS CALLED AWAY FOR AN EMERGENCY. THIS SUMP FILLED AND OVERFLOWED THROUGH OVERFLOW PIPES TO THE OTHER TWO SUMPS. PROCEDURES WILL BE CHANGED TO PREVENT THE MAN FROM LEAVING THE TEST.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TESTING • FAILURE, ADMINISTRATIVE CONTROL • FLOOD • OPERATOR ACTION • SUNNY 2 (PWR) • REACTOR SHUTDOWN • PUMPS • VALVES

059893

CONTAINMENT AND RECIRCULATION SPRAY CHECK VALVE FAILURES AT SUNNY 2

VIRGINIA ELECTRIC AND POWER COMPANY

7 PAGES, LETTER WITH AD REPORT 74/10 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 2, FEB. 14, 1975, Docket 50-201, TYPE--PWR, MFG--WEST., AE--STONE & WEBSTER

CAUSE - EXCESSIVE TORQUE. WHILE THE UNIT WAS AT COLD SHUTDOWN, A CRACK WAS NOTED IN A KEYWAY OF THE ROCKSHAFT OF A CONTAINMENT SPRAY CHECK VALVE. FOLLOWING REPLACEMENT OF THE ROCKSHAFT, A CRACK WAS FOUND IN THE VALVE BODY. WELD REPAIR RESULTED IN A LARGER CRACK. THE VALVE WAS REPLACED. THE CRACK RESULTED FROM A SAND INCLUSION WHICH WAS ACCEPTABLE AT THE TIME OF FABRICATION. SEVERAL OTHER CRACKS WERE FOUND IN ROCKSHAFT KEYWAYS. THE ROCKSHAFTS WERE REPLACED. CRACKS WERE THE RESULT OF HIGH IMPACT LOADING OF THE VALVE DISCS RESULTING FROM EXCESS TORQUE. THE CLOSING TORQUE HAS BEEN ADJUSTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT • CONTAINMENT SPRAY • STRESS • IMPACT SHOCK • FAILURE, INSTALLATION ERROR • VALVE, CHECK •

099693 -CONTINUOUS
SURRY 2 (PWR) + FAILURE, LUNAR MODE

100262
ORIFT IN STEAM GENERATOR LEVEL INDICATOR AT SURRY 2
VIRGINIA ELECTRIC AND POWER COMPANY
2 PAGES, LETTER WITH AD REPORT 75/03 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 2, FEBRUARY 21, 1975, DOKRET 50-201, TYPE--PWR, NRC--WEST., AE--STONE & WEBSTER

CAUSE - DIRT IN SENSING LINE. DURING NORMAL OPERATION A STEAM GENERATOR NARROW RANGE LEVEL CHANNEL INDICATION WAS FOUND TO HAVE DRIFTED TO 65% WHEN THE ACTUAL LEVEL WAS 44%. THE CHANNEL WAS PLACED IN THE TRIP MODE AND THE SENSING LINES WERE BLOWN DOWN REMOVING A BLACK SLUDGE DEPOSIT. THE CHANNEL THEN OPERATED SATISFACTORILY. THIS WAS A ITT-BARTON MODEL 300 LEVEL TRANSMITTER. SIMILAR PROBLEMS ARE NOT UNCOMMON FOLLOWING A LONG SHUTDOWN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, (30 CENTS/PAGE -- MINIMUM CHARGE \$2.00)

REACTOR SAFETY SYSTEM + FAILURE, INSTRUMENT + CRUD + FAILURE, MAINTENANCE ERROR + STEAM GENERATOR + TUBING + SURRY 2 (PWR) + ORIFT + SENSORS, LEVEL

100072
SET POINT ORIFT IN LEVEL INDICATOR AT SURRY 2
VIRGINIA ELECTRIC AND POWER COMPANY
2 PAGES, LETTER WITH AD REPORT 51-75-04 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, FEBRUARY 21, 1975, DOKRET 50-201, TYPE--PWR, NRC--WEST., AE--STONE & WEBSTER

CAUSE - CRUD IN SENSING LINES. DURING NORMAL OPERATION, A STEAM GENERATOR NARROW RANGE LEVEL INDICATOR WAS FOUND TO HAVE DRIFTED TO 65% WHEN THE ACTUAL LEVEL WAS 44%. THE CHANNEL WAS PLACED IN THE TRIP MODE AND THE SENSING LINES WERE BLOWN DOWN, REMOVING A BLACK SLUDGE DEPOSIT. THE CHANNEL OPERATED SATISFACTORILY. PROBLEMS SIMILAR IN NATURE ARE NOT UNCOMMON FOLLOWING A LONG SHUTDOWN. THIS IS AN ITT-BARTON, MODEL 300, LEVEL TRANSMITTER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

REACTOR SAFETY SYSTEM + INSTRUMENT CALIBRATION + CRUD + INSTRUMENT, SWITCH + STEAM GENERATOR + TUBING + SET POINT + SURRY 2 (PWR) + ORIFT + SENSORS, LEVEL

100434
SETPOINT ORIFT IN STEAM GENERATOR LEVEL INDICATOR AT SURRY 2
VIRGINIA ELECTRIC AND POWER COMPANY
2 PAGES, LETTER WITH AD REPORT 52-75-04 TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, REGION 2, FEBRUARY 27, 1975, DOKRET 201, TYPE--PWR, NRC--WEST., AE--STONE & WEBSTER

CAUSE - LEAKING VALVE. DURING NORMAL OPERATION, 1 OF THE 3 NARROW RANGE LEVEL INDICATORS FOR A STEAM GENERATOR DRIFTED HIGH. IT WAS PLACED IN THE TRIP MODE. A LEAKING CONDENSATE POT INSULATION VALVE PREVENTED THE PCT FROM MAINTAINING A PROPER WATER LEVEL. THIS CAUSED THE INDICATION TO DRIFT. AFTER THE VALVE WAS REPAIRED, THE INDICATOR OPERATED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + INSTRUMENT CALIBRATION + TEST, SYSTEM OPERABILITY + INSTRUMENT, ABNORMAL INDICATION + STEAM GENERATOR + LEAK + SURRY 2 (PWR) + ORIFT + SENSORS, LEVEL

100354
QUADRANT TILT EXCEEDS LIMIT AT SURRY 2
VIRGINIA ELECTRIC AND POWER COMPANY
2 PAGES, LETTER WITH AD REPORT 75/05 TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, REGION 2, FEBRUARY 27, 1975, DOKRET 50-201, TYPE--PWR, NRC--WEST., AE--STONE & WEBSTER

CAUSE - FLUX DEVIATION ALARM FAILURE. DURING 100% POWER OPERATION, A QUADRANT TILT OF UP TO A MAXIMUM OF 2.5% EXISTED FOR GREATER THAN 2 HOURS WITHOUT POWER REDUCTION. A CARU FAILURE CAUSED THE FLUX DEVIATION ALARM TO FAIL TO ALERT THE OPERATOR TO THE FLUX TILT. THE TILT WAS CAUSED BY A DROPPED ROD WHICH HAD BEEN EXPERIENCED EARLIER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATOR ERROR + POWER DISTRIBUTION + FAILURE, INSTRUMENT + FLUX TILT + SURRY 2 (PWR) + CONTROL RODS + ANNUNCIATIONS

102550
CONTAINMENT VACUUM SYSTEM CAPACITY BELOW LIMITS AT SURRY 2
VIRGINIA ELECTRIC & POWER CO.
9 PAGES, LETTER WITH USRE 74-01 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, APRIL 10, 1975, DOKRET 50-

102558 (CONTINUED)
201. TYPE--PMA, MFG--WEST., AE--STONE & WEBSTER

CAUSE - PUMP CAPACITY LOW. WHILE UNIT 2 WAS OPERATING AT 90% POWER, AN ALARM INDICATING LOW DISCHARGE FLOW IN THE CONTAINMENT VACUUM SYSTEM WAS RECEIVED. BOTH VACUUM PUMPS WERE NOT PUMPING AIR PROPERLY. PUMPS, FLOW ELEMENTS, AND THE PIPING SYSTEM WERE CAREFULLY CHECKED AND MINOR CONNECTIONS MADE WITHOUT INCREASING FLOW. TESTS SHOWED THE CAPACITY OF THE INSTALLED VACUUM PUMPS WAS LESS THAN SPEC. NEW VACUUM PUMPS OF AN IMPROVED DESIGN HAVE BEEN ORDERED TO REPLACE THE PRESENT ONES. THE NEW PUMPS WILL BE INSTALLED AT THE NEXT CONVENIENT SHUTDOWN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 2 (PWR) • SYSTEM CAPACITY • PUMPS • FLOW • PRESSURE, SUBATMOSPHERIC • FAILURE, DESIGN ERROR • CONTAINMENT

101731
CONTAINMENT VACUUM SYSTEM EFFICIENCY AT SURRY 2
VIRGINIA ELECTRIC & POWER COMPANY
9 PAGES, LETTER WITH NURE REPORT 74/01 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, APRIL 10, 1975.
DOCKET 50-201, TYPE--PMA, MFG--WEST., AE--STONE & WEBSTER

CAUSE - PUMPS TOO SMALL. WHILE OPERATING AT 90% POWER WITH A CONTAINMENT AIR PARTIAL PRESSURE OF 9.6 PSIA, A LOW DISCHARGE FLOW IN THE CONTAINMENT VACUUM SYSTEM ALARM WAS RECEIVED. THE INVESTIGATION FOUND THAT THE CONTAINMENT VACUUM PUMPS, THOUGH CAPABLE OF REDUCING THE INLEAKAGE, FAILED TO MEET THE CAPACITY REQUIREMENTS. PUMPS HAVING A LARGER CAPACITY ARE ON ORDER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MODIFICATION • FAILURE, INSTALLATION ERROR • CONTAINMENT LEAKAGE CONTROL • PRESSURE, SUBATMOSPHERIC • SYSTEM CAPACITY • SURRY 2 (PWR) • PUMPS

101780
CORE RADIAL DISTRIBUTION FILTS IN EXCESS OF LIMIT AT SURRY 2
VIRGINIA ELECTRIC & POWER COMPANY
2 PAGES, LETTER WITH AD REPORT 75/05 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, APRIL 14, 1975.
DOCKET 50-201, MFG--WEST., AE--STONE & WEBSTER

CAUSE - EXCORE DETECTOR FAILURE. DURING 100% POWER OPERATION, A CHECK OF THE OUTPUTS OF THE EXCORE DETECTORS REVEALED THAT A RADIAL FILT IF 2-58 EXISTED. THIS FILT WAS GENERATED EARLIER BY A DROPPED CONTROL ROD AND A PROLONGED RECOVERY WHICH BUILT IN A RADIAL XENON DISTRIBUTION. A CENTRAL ALUM ALARM DID NOT SOUND BECAUSE OF A DEFECTIVE CIRCUIT CARD IN THE EXCORE DETECTORS. THE CARD WAS REPLACED. OPERATORS WANTED TO MONITOR EXCORE DETECTORS SUBSEQUENT TO A DROPPED ROD.

AVAILABILITY - ERMA PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D.C. 20545 100 CENTS/PAGE--MINIMUM CHARGE \$2.00

FAILURE, COMPONENT • FLUX DISTRIBUTION • FAILURE, OPERATOR ERROR • INSTRUMENT, NUCLEAR • FAILURE, INSTRUMENT • FLUX FILT • SURRY 2 (PWR) • ANNUNCIATORS

102273
TEMPERATURE GRADIENT ACROSS CONDENSER EXCEEDS LIMIT AT SURRY 2
VIRGINIA ELECTRIC & POWER CO.
2 PAGES, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, APRIL 18, 1975, DOCKET 50-201, TYPE--PMA, MFG--WEST., AE--STONE & WEBSTER

CAUSE - UNUSUAL WEATHER CONDITIONS. WHILE OPERATING AT 80% POWER, THE DIFFERENTIAL TEMPERATURE ACROSS THE MAIN CONDENSER EXCEEDED THE 23 F LIMIT FOR 15 TO 20 MINUTES. WATERBOX A WAS OUT OF SERVICE FOR MAINTENANCE ON THE HIGH LEVEL INTAKE TRAVELING WATER SCREEN. DURING THIS TIME, SCREEN D SNEAKED A PIN IN THE DRIVE UNIT AND STOPPED. FLOW HAD TO BE STOPPED TO START THE SCREEN AFTER PIN REPLACEMENT. THE HIGH TEMPERATURE GRADIENT OCCURRED AT THIS TIME. HIGH MINUS AND VERY LOW TIMES CAUSED VERY LOW LEVELS AT THE INTAKE. MUD AND DEBRIS WERE SO HEAVY THE LOW LEVEL SCREENS WERE INEFFECTIVE. DEBRIS ACCUMULATED IN THE MAIN CONDENSER WATER BOX AT THIS TIME ALSO.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, EQUIPMENT • TEMPERATURE GRADIENT • CRUD • FILTER, SCREEN • CONDENSER • WEATHER, SEVERE • SURRY 2 (PWR) • CONDENSER COOLING SYSTEM

102530
CIRCULATING WATER SYSTEM MAIN CONDENSER "HIVE" FAILS TO CLOSE AT SURRY 2
VIRGINIA ELECTRIC & POWER COMPANY
2 PAGES, LETTER WITH AOR 75-07 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, MAY 2, 1975, DOCKET 50-201, TYPE--PMA, MFG--WEST., AE--STONE & WEBSTER

CAUSE - LOOSE MOUNTING SCREW. DURING TESTING WHILE PREPARING FOR REFUELING, A CIRCULATING WATER

102500 *CONTINUED*

SYSTEM RAIN CONDENSER VALVE FAILED TO CLOSE ON SIGNAL FROM THE CONTROL ROOM. ONE OF 2 MOUNTING SCREWS OF THE TONNE SWITCH WAS NOT FULLY SEATED. THIS PREVENTED THE MOTOR CURRENTS FROM CLOSING. THE SCREW AND LUBR WASHER WERE SEATED FULLY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.000

SURRY 2 (PWR) • VALVES • FAILURE, INSTALLATION ERROR • VALVE OPERATOR'S • FASTENER • TEST, SYSTEM OPERABILITY • REFUELING • CONDENSER COOLING SYSTEM

102531

ACCUMULATOR DISCHARGE VALVE FAILS TO OPEN AT SURRY 2
VIRGINIA ELECTRIC & POWER CO.

2 PAGES, LETTER WITH AD REPORT 75-00 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, MAY 2, 1975. DOCKET 50-201, TYPE--PWR, NRG--WEST., AE--STONE & WEBSTER

CAUSE - DISCONNECTED LEAD. DURING TESTING, AN ACCUMULATOR DISCHARGE VALVE DID NOT RECEIVE A SIGNAL TO OPEN UPON A SAFETY INJECTION INITIATION. A DISCONNECTED LEAD WAS FOUND IN THE MOTOR CONTROL CENTER. THE VALVE COULD BE OPERATED FROM THE CONTROL ROOM. INVESTIGATION FAILED TO REVEAL THE TIME OR THE REASON THAT THE LEAD WAS LIFTED. THE VALVE IS OPEN DURING NORMAL OPERATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.000

SURRY 2 (PWR) • VALVES • ACCUMULATORS • TEST, SYSTEM OPERABILITY • FAILURE, MAINTENANCE ERROR • CABLES AND CONNECTORS

102507

CONSEQUENCE LIMITING SAFEGUARD TRAIN FAILS TO OPERATE AT SURRY 2
VIRGINIA ELECTRIC & POWER CO.

2 PAGES, LETTER WITH AD REPORT 75-00 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, MAY 2, 1975. DOCKET 50-201, TYPE--PWR, NRG--WEST., AE--STONE & WEBSTER

CAUSE - RELAY FAILURE. DURING TESTING, CONSEQUENCE LIMITING SAFEGUARD HIGH-MGY TRAIN B WOULD NOT INITIATE WHEN THE 3/4 MATRIX OF CHANNELS 1, 2, AND 3 WERE TRIPPED. IT DID INITIATE USING CHANNELS 1, 2, AND 4. A NORMALLY DE-ENERGIZED RELAY WAS FOUND TO HAVE AN OPEN CIRCUITED COIL. THE DEFECTIVE RELAY WAS REPLACED. THE CAUSE OF COIL FAILURE COULD NOT BE DETERMINED. IT SHOWED SIGNS OF OVERHEATING.

AVAILABILITY - MICROSURANCE, INC., P.O. BOX 3522 OAK RIDGE, TENN. 37830

SURRY 2 (PWR) • CONTROL SYSTEM • ENGINEERED SAFETY FEATURE • FAILURE, COMPONENT • PRELAYS • TEST, SYSTEM OPERABILITY

103116

FUEL ASSEMBLY DAMAGED DURING UNLOADING AT SURRY 2
VIRGINIA ELECTRIC & POWER COMPANY

7 PAGES, LETTER WITH SPECIAL REPORT 75-02 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, JUNE 3, 1975. DOCKET 50-201, TYPE--PWR, NRG--WEST., AE--STONE & WEBSTER

CAUSE - FUEL HANDLING CRANE MALFUNCTION. WHEN FUEL ASSEMBLY L-16 WAS BEING REMOVED FROM THE CORE, 2 ADJACENT LATCHING FINGERS ON THE FUEL HANDLING CRANE FAILED TO ENGAGE THE TOP NOZZLE. THIS ALLOWED THE ASSEMBLY TO PIVOT CAUSING BINDING IN THE CRANE MAST. WHEN THE CRANE OPERATOR NOTED THE INCREASED LOAD, HE LOWERED THE ASSEMBLY. THE BOTTOM OF WHICH HAD DRIFTED OVER ASSEMBLY N-20. THE BOTTOM NOZZLE ASSEMBLY OF L-16 DAMAGED 2 HOLD-DOWN SPRINGS ON N-20. ANALYSIS INDICATED THAT THE 2 UNDAUNTED SPRINGS ARE ADEQUATE TO PREVENT LIFT-OFF OF THE FUEL ASSEMBLY DURING NORMAL POWER OPERATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.000

SURRY 2 (PWR) • DAMAGE • FUEL HANDLING • REFUELING • FAILURE, OPERATOR ERROR • FUEL HANDLING MACHINE • FUEL ELEMENTS

103117

CLADDING PERFORATION DETECTED ON FUEL ASSEMBLY AT SURRY 2
VIRGINIA ELECTRIC & POWER COMPANY

4 PAGES, LETTER WITH SPECIAL REPORT 75-01 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, JUNE 3, 1975. DOCKET 50-201, TYPE--PWR, NRG--WEST., AE--STONE & WEBSTER

CAUSE - HYDRIDING. VISUAL INSPECTION OF FUEL ASSEMBLIES DURING THE FIRST REFUELING REVEALED GAS BUBBLES COMING FROM ONE OF THE LOWER FUEL RODS IN ONE ASSEMBLY. CLADDING WAS PERFORATED WITH A 0.1 IN. DIA. HOLE IN A DEFECTIVE AREA 0.25 IN. IN DIA. CAUSED BY LOCAL HYDRIDING. OPERATING EXPERIENCE IN OTHER REACTORS REVEAL NO EVIDENCE OF PROPAGATION OF SIMILAR FAILURES. THEREFORE, THE FUEL ASSEMBLY CAN BE SAFELY OPERATED TO ITS DESIGN BURNUP.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM

103117 CONTINUED
CHANGE 82-001

SUMRY 2 (PWR) • PLANNING • POWER HDU • FAILURE, CLADDING • FUEL INTEGRITY • REMOTE MANIPULATING AND VIEWING • ONYDRIE • REFUELLING • FAILURE, FADICATION ERROR • POWER ELEMENTS

103070
EMERGENCY CONDENSATE STORAGE TANK LEVEL LOW AT SUMRY 2
VIRGINIA ELECTRIC & POWER CO.
2 PAGES. LETTER WITH ADM 75-10 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, JUNE 20, 1975. DCKET 50-201. TYPE--PWR, RW--WEST., AE--STONE & WEBSTER

CAUSE - PHASED DEFICIENCY. DURING A REACTOR HEATUP, IT WAS FOUND THAT THE ABOVE MENTIONED EMERGENCY CONDENSATE STORAGE TANK CONTAINED LESS THAN THE REQUIRED 60,000 GALLONS. THIS WAS CAUSED BY INCONSISTENCIES IN OPERATING PROCEDURES. THE TANK WAS FILLED TO A LEVEL GREATER THAN 60,000 GALLONS. THE DEFICIENCY LASTED ABOUT 9 HOURS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHANGE 82-001

SUMRY 2 (PWR) • SYSTEM CAPACITY • STORAGE CONTAINER • FAILURE, ADMINISTRATIVE CONTROL • PROCEDURES AND MANUALS • EMERGENCY CLADDING SYSTEM • CONDENSATION

103044
ABOVE MENTIONED EMERGENCY CONDENSATE TANK LEVEL LOW AT SUMRY 2
VIRGINIA ELECTRIC AND POWER COMPANY
2 PAGES. LETTER WITH ADM 75-10 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, JUNE 20, 1975. DCKET 50-201. TYPE--PWR, RW--WEST., AE--STONE & WEBSTER

CAUSE - INCONSISTENCIES IN PROCEDURES. DURING A REACTOR HEATUP, IT WAS FOUND THAT THE ABOVE MENTIONED EMERGENCY CONDENSATE STORAGE TANK CONTAINED LESS THAN THE REQUIRED 60,000 GAL OF WATER. THE LEVEL WAS BROUGHT TO GREATER THAN 60,000 GAL WITHIN 9 HOURS. INCONSISTENCIES IN OPERATING PROCEDURES WAS THE CAUSE. STEPS ARE BEING TAKEN TO CORRECT THE PROCEDURES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHANGE 82-001

SUMRY 2 (PWR) • SYSTEM CAPACITY • REACTOR COOLANT • STORAGE CONTAINER • FAILURE, ADMINISTRATIVE CONTROL • PROCEDURES AND MANUALS

103901
SERVICE WATER PUMP SEAL LEAK DAMAGES VALVE OPERATION AT SUMRY 2
VIRGINIA ELECTRIC & POWER CO.
2 PAGES. LETTER WITH ADM 75-10 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, JULY 1, 1975. DCKET 50-201. TYPE--PWR, RW--WEST., AE--STONE & WEBSTER

CAUSE - DESIGN ERROR. DURING FULL POWER OPERATION, A SERVICE WATER PUMP DEVELOPED A SEAL LEAK. WATER FILLED THE VALVE PIT CONTAINING AN ISOLATION VALVE. WATER CAUSED AN ELECTRIC SHORT IN THE MOTOR OPERATION. THE PUMP LEAK AND MOTOR OPERATION WERE REPAIRED. FLOW PLATING ABOVE THE PIT WILL BE SEALED TO PREVENT REOCCURENCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHANGE 82-001

SUMRY 2 (PWR) • SEAL • PUMPS • AUXILIARY CABLEING • LEAK • FAILURE, EQUIPMENT • VALVE OPERATIONS • CONTAINMENT ISOLATION • FAILURE, DESIGN ERROR • FLOOD • COMPARTMENT

104000
UNDERVOLTAGE CONTROL CIRCUIT FOUND DE-ENERGIZED AT SUMRY 2
VIRGINIA ELECTRIC & POWER COMPANY
1 PAGE. LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 2, JULY 9, 1975. DCKET 50-201. TYPE--PWR, RW--WEST., AE--STONE & WEBSTER

CAUSE - BLOWN FUSES. DURING FULL POWER OPERATION, IT WAS FOUND THAT 2 OF THE 3 UNDERVOLTAGE CONTROL CIRCUITS FOR THE 4 KV SYSTEM WERE DE-ENERGIZED DUE TO A BLOWN FUSE IN EACH CIRCUIT. THE FUSES WERE REPLACED IMMEDIATELY. THE APPARENT CAUSE IS FUSE DEGRADATION DUE TO AGE. THE FAILED FUSES HAVE BEEN SENT FOR EVALUATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHANGE 82-001

SUMRY 2 (PWR) • INSTRUMENT, PROTECTIVE • DETECTING POWER • ENGINEERED SAFETY FEATURE • FAILURE, INSTRUMENT • EFFECT, AGE

104219
MAIN STEAM TRIP VALVE CLOSURES SPURIOUSLY AT SUMRY 2
VIRGINIA ELECTRIC & POWER COMPANY, RICHMOND

107276 PLANTINGOP

CYCLING OF SOME VALVES SUPPLIED BY THIS MEMBER LIMITED THE AIR PRESSURE ALONGING THESE 3 VALVES TO ZERO. THEY WERE OUT OF SERVICE FOR 24 MINUTES

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SUMMARY (P) = VALVES + POLYMER RECIRCULATION + STORAGE CONTAINER + SHUTDOWN SYSTEM, SECONDARY + FAILURE, EQUIPMENT + PNEUMATIC SYSTEM + FLUX DECREASE

107280

BORIC ACID TANK LEVEL DECREASED BELOW LIMIT AT SURRY 2

VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA.

2 PGS. LHM WPAU-52-75-10 TO NRC OFFICE OF I & E, REGION 2, SEPT. 4, 1975, DCKET 50-281, TYPE--PWR, NRC--WEST, AE--STONE & WEBSTER

CAUSE - IMPROPER PIPING MATERIAL. WHILE OPERATING AT 100% POWER, A LOW LEVEL ALARM WAS RECEIVED ON BORIC ACID TANK C. THE LEVEL WAS OBSERVED TO BE STEADILY DECREASING. AN IMMEDIATE SHUTDOWN OF 150 MW/HR WAS INITIATED. THE MELT FLANGE TO A FLUX TRANSMITTER WAS LEAKING. BORIC ACID TRANSFER PUMP D WAS SECURED TO STOP THE LEAK. A DRAIN FLANGE WAS INSTALLED UPSTREAM OF THE TRANSMITTER AND THE PUMP RETURNED TO SERVICE. THE TANK LEVELS WERE RESTORED AND REACTOR POWER WAS INCREASED 150 MW/HR. THE FAILED FLANGES AND PIPE OF THE SPILL PIECE WERE CARBON STEEL RATHER THAN 304 STAINLESS STEEL AS SPECIFIED. PROPER REPLACEMENT PARTS WILL BE INSTALLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SUMMARY (P) = FLANGE + PIPES AND PIPE FITTINGS + MECHANICAL SHIM + FAILURE, INSTALLATION ERROR + MATERIAL + CORROSION + LEAK + STORAGE CONTAINER

107282

RTD FAILED LOW AT SURRY 2

VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA.

2 PGS. LHM WPAU-52-75-17 TO NRC OFFICE OF I & E, REGION II, OCT. 17, 1975, DCKET 50-281, TYPE--PWR, NRC--WEST, AE--STONE & WEBSTER

CAUSE - SATURATED WITH WATER. DURING OPERATION AT 100% POWER, LOOP C HOT LEG RTD FAILED LOW CAUSING THE PROTECTION DELTA T AND T ADV SIGNALS TO FAIL LOW. THE CHANNEL WAS PLACED IN THE TRIP MODE. THE LOGIC CHARACTERISTICS OF BOTH THE CONNECTED TRD AND THE INSTALLED SPARE WERE INADEQUATE. WHEN THE UNIT WAS BROUGHT INTO COLD SHUTDOWN 7 DAYS LATER, IT WAS FOUND THAT STEAM/WATER LEAK HAD SATURATED THE INSTRUMENTS. BOTH ROSEMONT, MODEL 170KF, RTDS WERE REPLACED AND PLACED INTO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SUMMARY (P) = INSTRUMENT, SWITCH + SENSORS, TEMPERATURE + LEAK + STEAM + FAILURE, INSTRUMENT + REACTOR SAFETY SYSTEM

107283

ERRATIC ROD POSITION INDICATIONS FOR 24 RODS AT SURRY 2

VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA.

2 PGS. LHM WPAU-52-75-18 TO NRC OFFICE OF I & E, REGION II, OCT. 24, 1975, DCKET 50-281, TYPE--PWR, NRC--WEST, AE--STONE & WEBSTER

CAUSE - VALVE LEAK WETS RPI CABLEING. WHILE OPERATING AT 100% POWER, A STEAM GENERATOR LEVEL TRANSMITTER ISOLATION VALVE BODY-TO-BONNET LEAK WETTED DOWN RPI CABLEING CAUSING GROUNDING AND ERRATIC INDICATION FOR 24 DIFFERENT RODS. A TURBINE RUNBACK ALARM WAS INITIATED VIA THE RPI AND A RUNBACK DID NOT OCCUR. THE UNIT WAS SHUT DOWN. THE VALVE WAS REPLACED WITH A SEAL WELDED VALVE, AND RPI'S RESTORED TO SERVICE. THE TURBINE RUNBACK DID NOT OCCUR BECAUSE LEADS WERE LIFTED OUT TO PAST RPI AND EMC PROBLEMS. LEADS WERE RECONNECTED. ALL SG LEVEL ISOLATION VALVES IN BOTH UNITS WILL BE REPLACED WITH SEAL WELDED VALVES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SUMMARY (P) = SENSORS, LEVEL + INSTRUMENT, ABNORMAL INDICATION + CABLES AND CONNECTORS + LEAK + WATER + RUNBACK SHUTDOWN + VALVES + FAILURE, INSTRUMENT + FAILURE, SIMULTANEOUS

107295

BORIC ACID TRANSFER PUMP MOTOR FAILS AT SURRY 2

VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA.

2 PGS. LHM WPAU-52-75-19 TO NRC OFFICE OF I & E, REGION II, OCT. 30, 1975, DCKET 50-281, TYPE--PWR, NRC--WEST, AE--STONE & WEBSTER

CAUSE - BORIC ACID IN STATOR. DURING 100% POWER OPERATION, BORIC ACID TRANSFER PUMP D MOTOR FAILED RESULTING IN LOSS OF RECIRCULATION OF BORON INJECTION TANK 2. PUMP D WAS PLACED IN SERVICE WITHIN 15 MINUTES. BORIC ACID WAS FOUND IN THE DEFECTIVE MOTOR STATOR WINDINGS ALTHOUGH THE PRESENT MOTORS ARE THE GRIP PROOF TYPE. EXISTING MOTORS WILL BE REPLACED WITH TOTALLY

107605 RECONTINUED

ENCLOSED FOR COOLEN TYPE MOTORS AS THE NEW TYPE MOTORS BECOME AVAILABLE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 2 (PHR) • PNEUMS • PUMPS • PERSONS • SUBMERSE • CHEMICAL SHIP • FAILURE, EQUIPMENT • FAILURE, DESIGN ERROR • ACCIDENTATION

090731

INTAKE CANAL LEVEL MAGNETIC AMPLIFIERS FAIL AT SURRY 1 AND 2
 VIRGINIA ELECTRIC AND POWER COMPANY

6 PAGES, LETTER TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 2 (REC), JANUARY 3, 1975, DOCKETS 50-200/201, TYPE--PHR, NRC--WEST., AC--STONE & WEBSTER

CAUSE - NORMAL AGING. DURING TESTING WHILE BOTH UNITS WERE AT COLO SHUTDOWN, THE MAGNETIC AMPLIFIER FOR UNIT 1 LOW LEVEL ALARM WAS OUT OF CALIBRATION AND BOTH UNIT 1 AND 2 TURBINE TRIP AMPLIFIERS WOULD NOT TRIP. THE CAUSE WAS NORMAL AGING OF ELECTRONIC COMPONENTS. THE UNIT 1 AMPLIFIERS WERE LAST CALIBRATED ON JULY 29, 1971 AND UNIT 2 ON JAN. 20, 1972. ALL 3 WERE RECALIBRATED. ANNUAL TESTS WILL BE MADE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INSTRUMENT CALIBRATION • FAILURE, INSTRUMENT • INSTRUMENT, SWITCH • TEST, SYSTEM OPERABILITY • CANAL • SURRY 1 (PHR) • SET POINT • SURRY 2 (PHR) • EFFECT, AGE • DRIFT • CONDENSER COOLING SYSTEM • SENSORS, LEVEL

093604

NOTICE OF PROPOSED IMPOSITION OF CIVIL PENALTIES AT SURRY 1 AND 2
 AEC, WASHINGTON, D.C.

6 PAGES, LETTER TO VIRGINIA ELECTRIC AND POWER COMPANY, JANUARY 10, 1975, DOCKETS 50-200/201, TYPE--PHR, NRC--WEST., AC--STONE & WEBSTER

CAUSE - SECURITY VIOLATIONS. DURING AN INSPECTION, CERTAIN ACTIVITIES WERE FOUND THAT APPEARED TO BE IN VIOLATION OF AEC REQUIREMENTS. THESE RESULTED FROM FAILURES TO IMPLEMENT AND/OR COMPLY WITH THE SECURITY PLAN. AEC PROPOSES TO IMPOSE CIVIL PENALTIES UP TO \$12,000.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ECONOMICS • FAILURE, ADMINISTRATIVE CONTROL • SURRY 1 (PHR) • SURRY 2 (PHR) • LEGALISTICS • SECURITY

093261

STEAM GENERATOR TUBE DETEIORATION AT SURRY 1 AND 2
 VIRGINIA ELECTRIC AND POWER COMPANY

6 PAGES, LETTER WITH AD REPORT S174/15 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 2, JANUARY 23, 1975, DOCKET 50-200, TYPE--PHR, NRC--WEST., AC--STONE & WEBSTER

CAUSE - TYPE OF CHEMISTRY CONTROL USED. EDDY CURRENT INSPECTIONS HAVE BEEN COMPLETED ON ALL 3 STEAM GENERATORS. TO DATE FOR BOTH UNITS WALL THICKNESS DATA HAS BEEN TAKEN ON THE HOT LEG SIDE OF 10001 TUBES AND THE COLD LEG SIDE OF 1000 TUBES. WALL THICKNESS DETEIORATION OF 508 OR MORE WAS FOUND IN 50 TUBES IN UNIT 2 AND 137 TUBES IN UNIT 1. THESE 195 TUBES HAVE BEEN PLUGGED. DETEIORATION CAN BE ATTRIBUTED TO TUBE SHEET SLUDGE DEPOSITS AND DELETERIOUS EFFECTS OF SODIUM-PHOSPHATE CHEMISTRY CONTROL. AN ALL VOLATILE TREATMENT WAS INITIATED ON UNIT 2 DURING STARTUP ON JANUARY 3, 1975 AND WILL BE INITIATED ON UNIT 1 FOLLOWING THE PRESENT REFUELING OUTAGE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MAINTENANCE AND REPAIR • COOLANT CHEMISTRY • REFUELING • TEST, NONDESTRUCTIVE • FAILURE, DESIGN ERROR • SURFACE FILM DEPOSIT • FAILURE, TUBING • STEAM GENERATOR • SURRY 1 (PHR) • TUBING • SURRY 2 (PHR)

100905

ORDER IMPOSING CIVIL PENALTIES OF \$10,000 AT SURRY 1 AND 2
 NUCLEAR REGULATORY COMMISSION, WASHINGTON, D.C.

7 PAGES, LETTER TO VIRGINIA ELECTRIC & POWER COMPANY, MARCH 19, 1975, DOCKETS 50-200/201, TYPE--PHR, NRC--WEST., AC--STONE & WEBSTER

CAUSE - SECURITY VIOLATIONS. CIVIL PENALTIES OF \$10,000 WERE IMPOSED FOR 3 ITEMS OF NONCOMPLIANCE CONCERNING VIOLATIONS OF THE REQUIREMENTS OF THE SECURITY PLAN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ECONOMICS • COMPLIANCE • FAILURE, ADMINISTRATIVE CONTROL • SURRY 1 (PHR) • SURRY 2 (PHR) • LEGALISTICS • AGENCY, NRC • SECURITY

100920

VENTILATION VENT VALVES WILL BE SHUT AT SURRY 1 AND 2
 VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA.
 2 PGS. LTR TO NRC OFFICE OF I & E, REGION 2, NOV. 20, 1975, DICKETS 50-434/435, TYPE--PWR, NRC--BOL, AE--STONE & WEBSTER

CAUSE - CONTINUOUS WASTE PROCESSING. JUNIOR APRIL AND MAY, NORMAL WASTE-ROUTING OPERATIONS CONTINUED WITHOUT INCIDENT TO THE QUANTITY OF LIQUID WASTE GENERATED BY THE WASTE. THIS REQUIRED CONTINUOUS OPERATION OF LIQUID WASTE FACILITIES AT FULL CAPACITY INCREASING THE I-131 ACTIVITY WITHIN THE AUXILIARY BUILDING. VENTILATION VENT I-131 ACTIVITY WAS INCREASED AS OF THE BEGINNING OF THE MONTH OF JULY. IT IS ESTIMATED THAT OPERATION OF LIQUID WASTE FACILITIES AT FULL CAPACITY WILL CONTINUE THROUGHOUT THE QUARTER. THE QUARTERLY LIMIT OF 100 MFC SPEC LIMIT WILL NOT BE EXCEEDED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 1 (PWR) + SURRY 2 (PWR) + AIRBORNE RELEASE + EFFLUENT + WASTE TREATMENT + WASTE TREATMENT, LIQUID + WASTE DISPOSAL

100700

DISCHARGE CONTROL STRUCTURE TEMPERATURE INCREASED TO 400°F AT SURRY 1 AND 2
 VIRGINIA ELECTRIC & POWER COMPANY, RICHMOND, VA.
 1 PG. LTR TO NRC OFF. OF REACTOR REGULATION, JULY 23, 1975, DICKETS 50-434/201, TYPE--PWR, NRC--BOL, AE--STONE & WEBSTER

CAUSE - FLOW INCREASED FOR FLOW, WHILE ESCALATING PUMP ON UNIT 2 FOLLOWING A START-UP. 2 CIRCULATING WATER PUMPS WERE STARTED AND THE CONDENSER INLET VALVES POSITIONED TO MAINTAIN INTRA CANAL LEVEL. THE INCREASED FLOW CAUSED THE TEMPERATURE AT THE DISCHARGE CONTROL STRUCTURE TO INCREASE TO 375°F IN 15 MINUTES EXCEEDING THE 3°F/M LIMIT. PROCEDURES WERE REVISED TO LIMIT STARTING OF THE CIRCULATING WATER PUMPS TO ONE AT A TIME.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 1 (PWR) + SURRY 2 (PWR) + INTERNAL TRANSIENT + CONDENSER COOLING SYSTEM + DISCHARGE + EFFLUENT + FAILURE, OPERATOR ERROR

100505

EXCLUSION AREA BOUNDARY DOES NOT EXCEED PSA VALUES AT SURRY 1 AND 2
 VIRGINIA ELECTRIC & POWER COMPANY, RICHMOND, VA.
 1 PG. LTR TO NRC OFFICE OF I & E, REGION 2, NOV. 20, 1975, DICKETS 50-434/435, TYPE--PWR, NRC--BOL, AE--STONE & WEBSTER

CAUSE - REVISED METEOROLOGICAL DATA. METEOROLOGICAL DATA GATHERING HAS BEEN COMPLETED AT THE SITE. PRELIMINARY RESULTS INDICATE THAT THE EXCLUSION AREA BOUNDARY DOES NOT EXCEED THE DESIGN BASIS ACCIDENT MAY BE INCREASED BY ABOUT 10% AS A RESULT OF THE NEW VALUES OBTAINED FROM THE REVISED DATA AND PRESENT CALCULATIONAL TECHNIQUES. THE INCREASED DOSE IS STILL WITHIN LIMITS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 3 (PWR) + SURRY 4 (PWR) + CONSTRUCTION + POPULATION EXPOSURE + ACCIDENT, DESIGN BASIS + WIND STATISTICS + MATHEMATICAL TREATMENT + METEOROLOGY + ATMOSPHERIC DIFFUSION

107420

PERMANENT DOWATERING SYSTEM REQUIRED AT SURRY 3 AND 4
 VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA.
 2 PGS. LTR TO NRC OFFICE OF I & E, REGION 2, NOV. 25, 1975, DICKETS 50-434/435, TYPE--PWR, NRC--BOL, AE--STONE & WEBSTER

CAUSE - ADEQUATE STABILITY MARGINS. A PERMANENT DOWATERING SYSTEM TO LOWER THE WATER TABLE IN THE AREA OF THE ENGINEERED SAFETY FEATURES BUILDINGS AND CONTAINMENT STRUCTURES IS REQUIRED TO PROVIDE ADEQUATE STABILITY MARGINS AGAINST SLIDING OF THESE STRUCTURES DURING A SEISMIC EVENT. UNDERWATER LEVEL WILL BE LOWERED FROM ELEVATION + 15 TO - 10 IN THE VICINITY OF THESE STRUCTURES EXTENDING TO A RADIUS OF ABOUT 1000 FEET. PRELIMINARY ANALYSIS INDICATE THAT ABOUT 100 GPM OF GROUNDWATER WILL BE REMOVED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SURRY 3 (PWR) + SURRY 4 (PWR) + CONSTRUCTION + INTERACTION, SOIL AND STRUCTURE + GROUNDWATER + HYDROLOGY + STABILITY + BUILDING + FOUNDATION ENGINEERING + FAILURE, DESIGN ERROR + SEISMIC DESIGN

100510

DEFICIENCY FOUND IN PRELIMINARY APPLIED RESPONSE SPECTRA FOR SURRY 3 AND 4
 VIRGINIA ELECTRIC & POWER CO., RICHMOND, VA.
 3 PGS. LTR W/RT TO NRC OFFICE OF I & E, NOV. 10, 1975, DICKETS 50-434/435, TYPE--PWR, NRC--BOL, AE--STONE & WEBSTER

140510 PLANTINER UP
080178

CAUSE - DESIGN DEFICIENCY. THE AMPLIFIED RESPONSE SPECTRA (ARSS) USED IN THE PLAN FOR THE REACTOR CONTAINMENT DOWNSHED INCLUDE THE EFFECTS OF CONTINGUOUS CAMPING IN THE STRUCTURE FOR THE MAINSHED SEISMIC LOADS. ARSS HAVE BEEN RECALCULATED INCORPORATING THIS EFFECT. NO FURTHER CHANGES ARE EXPECTED AT THIS TIME. THE PRELIMINARY ARSS CURVES FOR DESIGN OF EQUIPMENT IN THE CONTAINMENT SHEDS, FUEL, AND AUXILIARY BUILDINGS USE THE MEDIAN VALUE OF SHED RESPONSE FOR THE SILL, AND THE ASSUMED 0.31 - 338 VARIATIONS. CORRECTED ARSS CURVES ARE BEING SUBMITTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SUBJECT: (PWR) + SUMMIT + (PWR) + CONSTRUCTION + SEISMIC DESIGN + STRUCTURE + EQUIPMENT + STRUCTURAL ANALYSIS, DYNAMICS + FAILURE, DESIGN ERROR + RESPONSE SPECTRUM + STRESS ANALYSIS

000700
FIRE ON THE EASTERN SHORELINE OF THE GREAT WETLANDS AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY
3 PAGES, LETTER TO DIRECTORATE OF LICENSING (NRC), JANUARY 2, 1975, DOCKET 50-289, TYPE--PWR, NRC--BOW, AE--GILBERT ASSOC.

CAUSE - OIL LEAK. DURING TESTING OF THE EMERGENCY DIESEL GENERATION WHILE THE REACTOR WAS AT 25% PWR, A SMALL FIRE OCCURRED IN THE LOGGING ROOM. THE DIESEL ENGINE COMBUSTION ROOMS ADJACENT TO THE TUNNELBOUNCE COMBUSTION GAS INLET. THE FIRE RESULTED FROM A SMALL AMOUNT OF OIL LEAKAGE FROM AN ENGINE INSPECTION COVER PLATE JOINT WHICH IGNITED FUEL OIL. THE FIRE WAS EXTINGUISHED. NO DAMAGE OCCURRED. THE OILS WERE LUBRICANT. TEMPORARY OIL DEFLECTORS WERE FORMICATED AND INSTALLED TO KEEP OIL OFF THE THROUGH TRAFFIC.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FIRE + AMPLIFICATION + TEST, SYSTEM OPERABILITY + FAILURE, DESIGN ERROR + LUBRICATION + THREE MILE ISLAND 1 (PWR) + ENGINES, INTERNAL COMBUSTION + GENERATION, DIESEL

000710
CONTAINMENT INTEGRITY VIOLATED IN ACCESS MATCH AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY
3 PAGES, LETTER TO DIRECTORATE OF LICENSING (NRC), JANUARY 6, 1975, DOCKET 50-289, TYPE--PWR, NRC--BOW, AE--GILBERT ASSOC.

CAUSE - IMPROPER SWITCH LOCATION. WHILE THE REACTOR WAS OPERATING AT 99.4% POWER, A WORKER LEAVING THE REACTOR BUILDING THROUGH THE PERSONNEL ACCESS MATCH SLAMMED THE OUTER DOOR WHICH RESULTED IN THE DOOR BEING A INCHES ALAD AND ALSO IN IMPROPER OPERATION OF THE LIMIT SWITCH FOR THE ALARM AND INTERLOCK. WHEN THE NEXT MAN OPENED THE SHOWER DOOR, CONTAINMENT WAS VIOLATED. WORKERS HAVE BEEN WARNED TO SHUT DOORS PROPERLY AND TO OBSERVE THAT THEY ARE SHUT. THE LIMIT SWITCH MAY BE RELOCATED TO GIVE A BETTER INDICATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATION ERROR + CONTAINMENT AIR LEAK + CONTAINMENT INTEGRITY + FAILURE, DESIGN ERROR + THREE MILE ISLAND 1 (PWR)

000801
DECAY HEAT PUMP Suction VALVE FAILS TO CLOSE AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, PENNSYLVANIA
3 PAGES, LETTER TO DIRECTORATE OF LICENSING (NRC), JANUARY 10, 1975, DOCKET 50-289, TYPE--PWR, NRC--BOW, AE--GILBERT ASSOC.

CAUSE - BROKEN RELAY CONTACT. WHILE PERFORMING A PRETEST VALVE LINE UP WITH THE REACTOR AT 100% POWER, A DECAY HEAT PUMP Suction VALVE FROM THE BORATED WATER STORAGE TANK FAILED TO CLOSE. THE CIRCUIT BREAKER TO THE METER OPERATOR HAD TRIPPED ON OVERCURRENT. THE OVERCURRENT RESULTED FROM A BROKEN CHATTERING AUXILIARY CONTACT IN THE OPENING MOTOR-STARTER. THE BROKEN CONTACT WAS REPLACED. THE VALVE STEM WAS LUBRICATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + TEST, SYSTEM OPERABILITY + SHUTDOWN COOLING SYSTEM + THREE MILE ISLAND 1 (PWR) + VALVES + RELAYS

000800
MPC1 PUMP FAILS TO START AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, PENNSYLVANIA
3 PAGES, LETTER TO DIRECTORATE OF LICENSING (NRC), JANUARY 13, 1975, DOCKET 50-289, TYPE--PWR, NRC--BOW, AE--GILBERT ASSOC.

000000

CAUSE - LOOSE TERMINATION IN BREAKER. DURING TESTING WITH THE REACTOR AT 1000 POWER, A HIGH PRESSURE INJECTION PUMP FAILED TO START BECAUSE ITS CIRCUIT BREAKER FAILED TO CLOSE. INSPECTION REVEALED A LOOSE TERMINATION IN THE BREAKER RELEASE MECHANISM. CORRECTION WILL BE MADE BY JUNE 1975. THE CAUSE IS INSUFFICIENT LOCK MECHANISM ON THE TERMINATION. THE BREAKER WAS REPLACED. ALL SIMILAR TO BE CHECKED FOR LOOSE TERMINATIONS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENTS + FAILURE, FERRULES/LEAKS + TEST, SYSTEM OPERABILITY + THREE MILE ISLAND 1 (PWR) + CABLES AND CONNECTIONS + BREAKER + PUMPS + NPCL

000000

INTERNAL HANDLING PICTURE SPHERICAL NUT LOOSE AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, PENNSYLVANIA
1 PAGE, LETTER TO DIRECTORATE OF LICENSING (AEC), JANUARY 13, 1975, DOCKET 50-209, TYPE--PWR, NRC--BOM, AS--GILBERT ASSOC.

CAUSE - LOOSE TERMINATION IN BREAKER. DURING A TEST WITH THE REACTOR AT 1000 POWER, A REACTOR SHUTDOWN BREAKER CIRCUIT NUTTER BREAKER FAILED TO START BECAUSE THE CIRCUIT BREAKER FAILED TO CLOSE. THE BREAKER WAS REPLACED. INSPECTION REVEALED FAILURE DUE TO A LOOSE TERMINATION IN THE BREAKER RELEASE MECHANISM. CORRECTION WILL BE MADE BY JUNE 1975. THE CAUSE IS INSUFFICIENT LOCK MECHANISM ON THE TERMINATION. THE BREAKER WAS REPLACED. ALL SIMILAR TO BE CHECKED FOR LOOSE CONNECTIONS. THEY ARE NOT SHOWN IN THE CIRCUIT BREAKER TO BE P 200, STATE 20000001.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENTS + FAILURE, FERRULES/LEAKS + TEST, SYSTEM OPERABILITY + EMERGENCY COOLING + THREE MILE ISLAND 1 (PWR) + AUXILIARY COOLING SYSTEM + CABLES AND CONNECTIONS + BREAKER + PUMPS

000201

DESIGN DEFICIENCY IN CONTROL AND DRIVE BREAKER CIRCUITS AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, PENNSYLVANIA
1 PAGE, LETTER TO DIRECTORATE OF LICENSING (AEC), JANUARY 13, 1975, DOCKET 50-209, TYPE--PWR, NRC--BOM, AS--GILBERT ASSOC.

CAUSE - DESIGN ERROR. A REEVALUATION OF THE DESIGN QUALIFICATION OF THE CONTROL AND DRIVE BREAKER CIRCUIT REVEALED THAT THE ATTACHMENT OF THE CIRCUIT TO THE PLENUM MAY BE INADEQUATE TO WITHSTAND THE SAFE SHUTDOWN EARTHQUAKE ACCELERATION LEVELS. ADDITIONAL WELDS AND/OR STEEL ANGLES WILL BE ADDED WITH APPROVAL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

DESIGN CRITERIA + MODIFICATION + FAILURE, DESIGN ERROR + CONTROL PANEL/ROOM + THREE MILE ISLAND 1 (PWR) + SEISMIC DESIGN + CONCRETE AND DRIVE MECHANISMS

000371

PIPE SUPPORT PLUMB BREAKER AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, PENNSYLVANIA
1 PAGE, LETTER TO DIRECTORATE OF LICENSING (AEC), JANUARY 17, 1975, DOCKET 50-209, TYPE--PWR, NRC--BOM, AS--GILBERT ASSOC.

CAUSE - DESIGN ERROR. DURING A ROUTINE INSPECTION, IT WAS NOTED THAT A CONCRETE FOOTING FOR A RIGID PIPE SUPPORT FOR THE OUTLET VALVE OF DECAT HEAT REMOVAL COOLER WAS CRACKED. LARGE PIECE, COULD BE EASILY REMOVED. TWO OF THE 6 FOOTINGS HAD FAILED. THE DESIGN WAS SUCH THAT THE LOAD WAS NOT PROPERLY DISTRIBUTED. ALSO, IT APPEARS THAT IT WAS NOT INSTALLED PROPERLY, AND THE JOINTS MAY HAVE BEEN TIGHTENED BEFORE THE GRANTING HAD CURED PROPERLY. ALL 6 FOOTINGS WILL BE REPLACED USING A MODIFIED DESIGN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONCRETE + MODIFICATION + FAILURE, DESIGN ERROR + SUPPORT STRUCTURE + SHUTDOWN COOLING SYSTEM + THREE MILE ISLAND 1 (PWR)

000400

INTERNAL HANDLING PICTURE SPHERICAL NUT LOOSE AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, PENNSYLVANIA
2 PAGES, LETTER TO AEC DIRECTORATE OF LICENSING, JANUARY 30, 1975, DOCKET 50-209, TYPE--PWR, NRC--BOM, AS--GILBERT ASSOC.

CAUSE - DESIGN DEFICIENCY. DURING PREPARATION FOR PLENUM ASSEMBLY REMOVAL FROM THE REACTOR VESSEL, IT WAS NOTICED THAT THE SPHERICAL NUT WAS NOT SECURED TO THE THREADED ROD AND COULD

000000

CLIMATE UNIFORMITY. THE SET SCREWS ON THE 3 ASSEMBLIES WERE EITHER MISSING, LOOSE, OR OF THE WRONG LENGTH. THE CAUSE WAS A DESIGN DEFICIENCY. A NUT WAS ADDED TO THE THREADED ROD TO ENSURE CAPTURE BY THE SET SCREW. THE SET SCREW WAS STUCK IN PLACE. A SIMILAR MODIFICATION WILL BE MADE AT UNIT 2.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TRANSPORTATION AND HANDLING • MAINTENANCE • FAILURE, DESIGN ERROR • EQUIPMENT DESIGN • EQUIPMENT • CORE COMPONENTS • THREE MILE ISLAND 1 (PWR) • THREE MILE ISLAND 2 (PWR)

000070

CHLORINE IN RIVER WATER DISCHARGE EXCEEDS LIMITS AT THREE MILE ISLAND 1

METROPOLITAN EDISON COMPANY, PENNSYLVANIA

4 PAGES, LETTER TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, REGION 1, JANUARY 31, 1975, DCKET 50-289, TYPE--PWR, NRC--BOM, AE--GILBERT ASSOC.

CAUSE - PROCEDURAL DEFICIENCY. DURING A PERIODIC EVALUATION CONDUCTED TO CHLORINATE THE SYSTEM, CAUSED BY THE MECHANICAL UNIT CORRECTION TOWERS. THE PLANT AREA DISCHARGE SAMPLES INDICATED THAT THE CHLORINE RESIDUAL WAS 0.20 PPM, WHICH EXCEEDS THE 0.2 PPM LIMIT. THERE ARE NO PROCEDURAL GUIDELINES TO ADD OR DETERMINE HOW THE CHLORINE FEED RATE SHOULD BE VARIED AS A FUNCTION OF EXISTING CONDITIONS. CHLORINATION RATE WAS REDUCED FROM 450 LBS/DAY TO 300 LBS/DAY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

EFFLUENT • RIVER • CHLORINE • FAILURE, ADMINISTRATIVE CONTROL • THREE MILE ISLAND 1 (PWR) • CONCENTRATION • CONDENSER COOLING SYSTEM

000090

EXCESSIVE CHLORINE CONCENTRATION IN DISCHARGE AT THREE MILE ISLAND 1

METROPOLITAN EDISON COMPANY, PENNSYLVANIA

4 PAGES, LETTER TO NRC OFFICE OF INSPECTION AND ENFORCEMENT, REGION 1, NRC, JANUARY 31, 1975, DCKET 50-289, TYPE--PWR, NRC--BOM, AE--GILBERT ASSOC.

CAUSE - LOSS OF LOUP WATER SEAL. WITH THE UNIT IN HOT SHUTDOWN, A PRESSURIZER SPRAY VALVE WAS BACKSEATED FOR LINTORONE OPERATOR REPLACEMENT. THE PRESSURIZER BLOCK VALVE WAS, THEREFORE, CLOSED. WHEN THE BLOCK VALVE WAS CLOSED, VALVE STEM LEAK OFF TO THE VENT HEADER INCREASED TO 10 GPM. THIS OVERPRESSURIZED THE VENT HEADER NITROGEN COVER GAS WHICH BLANKETS SEVERAL TANKS IN THE WASTE DISPOSAL SYSTEM. THE HIGH PRESSURE CAUSED THE LOSS OF THE RECLAIMED BORIC ACID TANK OVERFLOW LINE WATER SEAL RELEASING RADIOACTIVE COVER GAS TO THE VENTILATION SYSTEM UNTIL THE SEAL WAS RESTORED. ABOUT 60 CI OF MOSTLY RE-133 WERE RELEASED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

EFFLUENT • RIVER • CHLORINE • FAILURE, ADMINISTRATIVE CONTROL • THREE MILE ISLAND 1 (PWR) • CONCENTRATION • CONDENSER COOLING SYSTEM • DISCHARGE

000098

UNPLANNED RADIOACTIVE GAS RELEASE AT THREE MILE ISLAND 1

METROPOLITAN EDISON COMPANY, PENNSYLVANIA

4 PAGES, LETTER TO DIRECTORATE OF LICENSING, FEBRUARY 2, 1975, DCKET 50-289, TYPE--PWR, NRC--BOM, AE--GILBERT ASSOC.

CAUSE - LOSS OF LOUP WATER SEAL. WITH THE UNIT IN HOT SHUTDOWN, A PRESSURIZER SPRAY VALVE WAS BACKSEATED FOR LINTORONE OPERATOR REPLACEMENT. THE PRESSURIZER BLOCK VALVE WAS, THEREFORE, CLOSED. WHEN THE BLOCK VALVE WAS CLOSED, VALVE STEM LEAK OFF TO THE VENT HEADER INCREASED TO 10 GPM. THIS OVERPRESSURIZED THE VENT HEADER NITROGEN COVER GAS WHICH BLANKETS SEVERAL TANKS IN THE WASTE DISPOSAL SYSTEM. THE HIGH PRESSURE CAUSED THE LOSS OF THE RECLAIMED BORIC ACID TANK OVERFLOW LINE WATER SEAL RELEASING RADIOACTIVE COVER GAS TO THE VENTILATION SYSTEM UNTIL THE SEAL WAS RESTORED. ABOUT 60 CI OF MOSTLY RE-133 WERE RELEASED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

AIRBORNE RELEASE • MAINTENANCE AND REPAIR • WASTE HANDLING • STORAGE CONTAINER • FAILURE, DESIGN ERROR • SEAL • THREE MILE ISLAND 1 (PWR) • PRESSURE TRANSIENT

000097

HYDRAULIC SHOCK SUPPRESSOR FAILS AT THREE MILE ISLAND 1

METROPOLITAN EDISON COMPANY, PENNSYLVANIA

2 PAGES, LETTER TO NRC DIRECTORATE OF LICENSING, FEBRUARY 2, 1975, DCKET 50-289, TYPE--PWR, NRC--BOM, AE--GILBERT ASSOC.

CAUSE - LOOSE END CAPS. DURING AN INSPECTION OF ALL HYDRAULIC SHOCK SUPPRESSORS INSIDE THE REACTOR BUILDING'S SECONDARY SHIELD, A SHOCKER WAS FOUND TO BE INOPERABLE DUE TO A LOSS OF FLUID. THE RESERVOIR END CAPS WERE LOOSE. SOME EVIDENCE OF LEAKAGE AT THE CYLINDER END CAPS WAS FOUND.

100407 CONTINUED

NO SEAL DEFORMATION WAS OBSERVED. THE DEFECTIVE UNIT WAS REPLACED WITH A REBUILD ONE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SUCKA ASSEMBLY • FAILURE, MAINTENANCE ERROR • SUPPLANT STRUCTURE • SURVEILLANCE PROGRAM • LEAK • THREE MILE ISLAND 1 (PHN) • BACKUP • PIPES AND PIPE FITTINGS

100408

CONTROL ROD NOT DECEASED INDEPENDENTLY WHEN MISALIGNED AT THREE MILE ISLAND 1 METROPOLITAN EDISON COMPANY, PA.

5 PAGES, LETTER TO NRC DIVISION OF REACTOR LICENSING, FEBRUARY 21, 1975, DOCKET 50-289, TYPE--PHN, NRC--BOM, AE--GILBERT ASSOC.

CAUSE - OPERATOR ERROR. DURING THE PERIOD 1-31 TO 2-9-75, THE ABSOLUTE POSITION INDICATOR FOR A CONTROL ROD INDICATED IT WAS 7 TO 100 LUMER IN THE CLUE THAN THE GROUP AVERAGE POSITION. THE RELATIVE POSITION INDICATOR INDICATED THE ROD WAS WITHIN 9 INCHES OF THE AVERAGE. THERE HAS BEEN A HISTORY OF DIFFICULTIES WITH THE ABSOLUTE POSITION INDICATORS SO IT WAS BYPASSED. LATER, THE ROD WAS WITHDRAWN TO CHECK THE ABSOLUTE POSITION INDICATOR. IT WAS READING PROPERLY. THE REACTOR HAD BEEN OPERATED WITH THIS ROD MISALIGNED FOR 10 DAYS. OPERATORS SHOULD HAVE CHECKED THE INDICATION MORE THOROUGHLY WHEN THE ERROR WAS FIRST FOUND.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTROL ROD INTERACTION • FAILURE, OPERATOR ERROR • REACTIVITY EFFECT • POWER DISTRIBUTION • INSTRUMENT, POSITION • THREE MILE ISLAND 1 (PHN) • CONTROL RODS

100409

UNDERSIZED WIRING FOUND IN MOTOR CONTROL CENTER AT THREE MILE ISLAND 1

METROPOLITAN EDISON COMPANY, PA.

1 PAGE, LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, FEBRUARY 24, 1975, DOCKET 50-289, TYPE--PHN, NRC--BOM, AE--GILBERT ASSOC.

CAUSE - DESIGN ERROR. WHILE INVESTIGATING THE CAUSE OF A TRIP OF THE 00-50 FEEDER BREAKER TO THE 10 ES MOTOR CONTROL CENTER, IT WAS DISCOVERED THAT UNDERSIZE WIRE EXISTED IN A UNIT OF THE CENTER. A PORTION OF THE WIRING BURNED OFF AT THE LUGS WHERE THE WIRING CONNECTS TO THE BUS STABS AND A RESULTING ARC TO GROUND CAUSED THE BREAKER TO TRIP. THE FAILED WIRING WAS REPLACED WITH LARGER SIZE WIRE. AN INSPECTION PROGRAM IS BEING PREPARED TO CHECK WIRE SIZES IN ALL MOTOR CONTROL CENTERS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, DESIGN ERROR • ENGINEERED SAFETY FEATURE • THREE MILE ISLAND 1 (PHN) • CABLES AND CONNECTORS • BREAKER

100410

INADVERTENT RELEASE OF AIRBORNE RADIOACTIVITY AT THREE MILE ISLAND 1

METROPOLITAN EDISON COMPANY, PA.

4 PAGES, LETTER WITH REPORT TO NRC DIVISION OF REACTOR LICENSING, MARCH 7, 1975, DOCKET 50-289, TYPE--PHN, NRC--BOM, AE--GILBERT ASSOC.

CAUSE - LOSS OF VENTILATION AIR FLOW. AN INADVERTENT RELEASE OF RADIOACTIVE MATERIAL OCCURRED OVER A 2.5 MIN PERIOD. THE AUXILIARY BUILDING VENTILATION WAS LOST DUE TO ACTIVATION OF THE AIR INTAKE TUNNEL DELUGE FIRE PROTECTION SYSTEM BY A FAULTY TEMPERATURE SENSOR IN THE TUNNEL. RADIOACTIVE GAS, WHICH ACCUMULATED IN THE AUXILIARY BUILDING WHILE THE VENTILATION SYSTEM WAS OFF, WAS SWEEPED OUT TO THE ATMOSPHERE WHEN THE SYSTEM WAS RETURNED TO SERVICE. ABOUT 5.37 C' (1988 AE-133) WAS RELEASED. THE SOURCE OF THE RELEASE IS BEING INVESTIGATED. NO RELEASE LIMITS WERE EXCEEDED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

AIRBORNE RELEASE • FAILURE, EQUIPMENT • VENTILATION SYSTEM • FAILURE, INSTRUMENT • THREE MILE ISLAND 1 (PHN) • SENSORS, TEMPERATURE

100411

REACTOR BUILDING EMERGENCY COOLER INLET VALVE FAILS AT THREE MILE ISLAND 1

METROPOLITAN EDISON CO., PA.

3 PAGES, LETTER TO NRC DIVISION OF REACTOR LICENSING, MARCH 21, 1975, DOCKET 50-289, TYPE--PHN, NRC--BOM, AE--GILBERT ASSOC.

CAUSE - LOOSE LOCK NUT. DURING TESTING WITH THE UNIT AT 90.9% POWER, A REACTOR BUILDING EMERGENCY COOLER INLET VALVE FAILED CLOSED, WHICH IS NOT THE OPEN POSITION. A LOCK NUT WITHIN THE VALVE OPERATOR HAD BEEN IMPROPERLY STAKED, HAD WORKED LOOSE, AND PERMITTED DISENGAGEMENT OF THE STEM NUT FROM THE VALVE STEM. THE VALVE WAS DISCONNECTED FROM THE OPERATOR. THE STAKE MARK WAS ON THE LOCK NUT BODY, NOT IN THE THREAD AREA AS IS NORMAL. THE OPERATOR WAS RECONNECTED AND THE LOCK NUT STAKED IN PLACE. LIMIT SWITCHES WERE CHECKED; SIMILAR VALVES WILL BE CHECKED FOR PROPER

100915 "CONTINUED"
STAKING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTAINMENT + BUILDING + TEST, SYSTEM OPERABILITY + FAILURE, INSTALLATION ERROR + AUXILIARY COOLING + THREE MILE ISLAND 1 (PWR) + VALVE OPERATORS + VALVES

101455
GAINBEL HYDRAULIC SHOCK SUPPRESSOR INOPERATIVE AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, PA.
3 PAGES, LETTER TO NRC DIVISION OF REACTOR LICENSING, APRIL 2, 1975, DOCKET 50-289, TYPE--PWR, NRG--B+W, AE--GILBERT ASSOC.

CAUSE - DESIGN AND INSTALLATION ERRORS. DURING REGTIME INSPECTION OF HYDRAULIC SHOCK SUPPRESSORS, ONE WAS FOUND INOPERATIVE IN THAT THE PISTON WAS UNABLE TO MOVE WITHIN THE CYLINDER. DURING INSTALLATION, THE PISTON ROD HAD BEEN PAINTED IN VIOLATION OF INSTRUCTIONS. THE PAINT CHIPPED OFF AS THE ROD MOVED THROUGH ITS BUSHING. THE CHIPS AND ROUGHENED PAINT LOCKED THE PISTON TO THE BUSHING. DURING THE SEAL REPLACEMENT PROGRAM THAT IS IN PROGRESS, 8 UNITS WERE FOUND THAT HAD PISTON VELOCITIES IN EXCESS OF THE 8 INCHES/MIN LIMIT. THIS RESULTED FROM A DESIGN DEFICIENCY IN THE SHOCKER VALVE. ALL NINE UNITS WERE REPLACED WITH REBUILT UNITS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

RESPONSE TIME + SHOCK ABSORBER + SURFACE, PAINTED + FAILURE, DESIGN ERROR + SUPPORT STRUCTURE + FAILURE, INSTALLATION ERROR + SURVEILLANCE PROGRAM + THREE MILE ISLAND 1 (PWR) + PIPES AND PIPE FITTINGS

101462
CONNECTION AND WIRING PROBLEMS FOUND ON CONTROL CENTERS AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., PA.
6 PAGES, LETTER TO NRC DIRECTORATE OF REACTOR LICENSING, APRIL 2, 1975, DOCKET 50-289, TYPE--PWR, NRG--B+W, AE--GILBERT ASSOC.

CAUSE - POOR WORKMANSHIP. DURING AN INSPECTION OF ENGINEERED SAFEGUARDS ELECTRIC CIRCUITS, SEVERAL PROBLEMS WERE FOUND WITH CONNECTORS AND WIRING IN MOTOR CONTROL CENTER UNITS. THE PROBLEM IS POOR WORKMANSHIP DURING MANUFACTURE AND/OR INSTALLATION. THE THREE PRIMARY AREAS ARE (1) USE OF WIRE SMALLER THAN REQUIRED IN THE SPECIFICATIONS, (2) POORLY CRIMPED LUGS, AND (3) LOOSELY-BOULDED ELECTRICAL CONNECTIONS. CORRECTIONS ARE BEING MADE AS RAPIDLY AS POSSIBLE WITHOUT SHUTTING THE REACTOR DOWN. SOME CORRECTIONS ARE AWAITING RECEIPT OF MATERIAL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTROL SYSTEM + FAILURE, FABRICATION ERROR + FAILURE, INSTALLATION ERROR + ENGINEERED SAFETY FEATURE + THREE MILE ISLAND 1 (PWR) + CABLES AND CONNECTORS

102139
HYDRAULIC SHOCK SUPPRESSORS INOPERABLE AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, PA.
3 PAGES, LETTER TO NRC DIRECTORATE OF REACTOR LICENSING, APRIL 15, 1975, DOCKET 50-289, TYPE--PWR, NRG--B+W, AE--GILBERT ASSOC.

CAUSE - DESIGN ERROR AND MATERIAL DEFECT. DURING AN INSPECTION OF THE HYDRAULIC SHOCK SUPPRESSOR WITH THE UNIT IN HOT SHUTDOWN, 3 SHOCKERS WERE FOUND WITH LOW FLUID AND 3 WITH THE DEFECTIVE VALVES MODEL B4-1226 (DESCRIBED EARLIER). THE LOSS OF FLUID IS BELIEVED TO BE DUE TO MATERIAL FAILURE ALTHOUGH NO SPECIFIC DEFECTS WERE FOUND. THE VALVE PROBLEM IS A DESIGN DEFICIENCY. FIVE UNITS WERE REPLACED REBUILT UNITS AND ONE WAS REPAIRED AND REFILLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SHOCK ABSORBER + FAILURE, DESIGN ERROR + SEAL + SUPPORT STRUCTURE + SURVEILLANCE PROGRAM + THREE MILE ISLAND 1 (PWR) + VALVES + PIPES AND PIPE FITTINGS

102970
MEASURED LEVEL OF RADIATION IN EFFLUENT EXCEEDS CONTROL AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, PA.
4 PAGES, LETTER WITH ENVIRON. REPORT 75-01 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, APRIL 18, 1975, DOCKET 50-289, TYPE--PWR, NRG--B+W, AE--GILBERT ASSOC.

CAUSE - SAMPLES ABNORMAL. A MONTHLY COMPOSITE OF WEEKLY GRAB SAMPLES OF SURFACE RIVER WATER COLLECTED DOWNSTREAM UP THE STATION HAD A TOTAL TRITIUM ACTIVITY ABOUT 4 TIMES THE CONTROL STATION VALUE. IT IS BELIEVED THAT THE GRAB SAMPLES WERE TAKEN DURING PERIODS OF CONDENSATE STORAGE TANK DISCHARGE, A PERIOD OF HIGHER-THAN-NORMAL TRITIUM LEVEL. THE RELEASE WAS LESS THAN 0.001 MPC.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM

102670 PLUTINIUM
CHARGE 82-000

THREE MILE ISLAND 1 (PWR) • RADIOACTIVITY RELEASE • PLUTINIUM • EFFLUENT • RIVER • SAMPLING • WASTE DISPOSAL •
REACTOR SYSTEM, REACTOR

102669
EXCESSIVE TOTAL CHLORINE CONCENTRATION IN PLANT DISCHARGE AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, PA.
4 PAGES, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, APRIL 18, 1975, DOCKET 50-289, TYPE--PWR,
NRC--BEM, AE--GILBERT ASSOC.

CAUSE - LACK OF GUIDELINES. DURING A PERIODIC EVOLUTION CONDUCTED TO CHLORINATE SYSTEMS COOLING
BY THE MECHANICAL DRAFT COOLING TOWER, THE STATION RIVER DISCHARGE SAMPLE TAKEN 30 MINUTES AFTER
COMMENCEMENT OF THE EVOLUTION INDICATED A TOTAL CHLORINE RESIDUAL OF 0.23 PPM. AFTER 50 MINUTES,
IT WAS 0.16 PPM. THE APPARENT CAUSE IS THAT THERE ARE NO GUIDELINES TO AID IN DETERMINING HOW
THE CHLORINE FEED RATE SHOULD BE VARIED AS A FUNCTION OF EXISTING CONDITIONS. THE UNIT WAS A
HOT STANDBY AT THE TIME. THE CHLORINATION RATE AT THE SCREEN HOUSE WAS REDUCED FROM 300 TO 200
LBS/DAY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE 82-000

THREE MILE ISLAND 1 (PWR) • CHLORINE • CONCENTRATION • EFFLUENT • RIVER • FAILURE, ADMINISTRATIVE CONTROL •
COOLING TOWER

102660
COMPOSITE RIVER WATER SAMPLE INDICATED RESULTS EXCEED LIMIT AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, PA.
4 PAGES, LETTER WITH REPORT 75/01 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, APRIL 18, 1975, DOCKET
50-289, TYPE--PWR, NRC--BEM, AE--GILBERT ASSOC.

CAUSE - NONREPRESENTATIVE SAMPLE. A MONTHLY COMPOSITE OF WEEKLY GRAB SAMPLES OF SURFACE RIVER
WATER COLLECTED 1/2 MILE DOWNSTREAM FROM THE DISCHARGE HAD A TRITIUM LEVEL 4 TIMES GREATER THAN
THE CONTROL STATION VALUE. THE NEXT SAMPLE SHOWED THAT THE LEVEL WAS NORMAL. IT IS BELIEVED
THAT THE SAMPLES IN THE COMPOSITE WERE TAKEN DURING PERIODS OF CONDENSATE STORAGE TANK DISCHARGE
AND WERE HIGHER THAN NORMAL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE 82-000

RIVER • TRITIUM • SAMPLING • RADIOACTIVITY RELEASE • FAILURE, ADMINISTRATIVE CONTROL • THREE MILE ISLAND 1
(PWR)

102671
REACTOR CRITICALITY REACHED AT 505 F AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, PA.
3 PAGES, LETTER TO NRC DIR. OF LICENSING, APRIL 21, 1975, DOCKET 50-289, TYPE--PWR, NRC--BEM, AE--GILBERT
ASSOC.

CAUSE - PROCEDURAL EFFICIENCY. DURING A PLANT HEATUP, PRIOR TO COMMENCING A ROUTINE REACTOR
STARTUP, THE REACTOR WENT CRITICAL AT 505 F. TECH SPECS REQUIRE A 525 F MINIMUM TEMPERATURE FOR
CRITICALITY. IT HAD BEEN CALCULATED THAT 21,000 GALLONS OF DEMINERALIZED WATER NEEDED TO BE
ADDED TO ACHIEVE CRITICALITY AT 532 F. DUE TO PROCEDURAL INADEQUACIES, THE WATER WAS ADDED AT
505 F. INSTEAD OF 532 F. ALSO THE FUEL REACTIVITY VERSUS EPD CURVE HAD NOT BEEN UPDATED. THIS
ADDED A SECOND COMPONENT OF EXCESS POSITIVE REACTIVITY. GROUP 4 CONTROL RODS WERE INSERTED FROM
1008 WITHDRAWN TO 088 WITHDRAWN TO SHUT DOWN THE REACTOR.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE 82-000

THREE MILE ISLAND 1 (PWR) • REACTIVITY, EXCESS • ACCIDENT, CRITICALITY • FAILURE, ADMINISTRATIVE CONTROL •
PROCEDURES AND MANUALS • REACTOR STARTUP

102668
TOTAL CHLORINE CONCENTRATION IN RIVER EXCEEDS LIMIT AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, PA.
4 PAGES, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, APRIL 24, 1975, DOCKET 50-289, TYPE--PWR,
NRC--BEM, AE--GILBERT ASSOC.

CAUSE - CRACKED HYPOCHLORITE CARBOY. A CRACKED AND LEAKING HYPOCHLORITE CARBOY WAS IN THE
PRETREATMENT BUILDING. ABOUT 12 GALLONS OF SOLUTION (108 PREP AVAILABLE CHLORINE) WERE SPILLED.
DISCHARGE FROM THE SUMP WAS STOPPED UNTIL IT WAS TREATED. CALCULATIONS INDICATE THAT THE
CONCENTRATION IN THE PLANT DISCHARGE NEVER EXCEEDED 0.2 PPM. THE INITIAL CAUSE OF THE INCIDENT
WAS THE CRACKED CARBOY. THE PRIMARY CAUSE WAS DESIGN IN THAT A SEPARATE STORAGE AREA WITH
SEPARATE UNITS IS NEEDED FOR LIQUID CHEMICALS. THIS WILL BE PROVIDED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE 82-000

102468 *CONTINUED*
THREE MILE ISLAND 1 (PHR) * * * CHLORINE * CONCENTRATION * EFFLUENT * RIVER * FAILURE, EQUIPMENT * STORAGE
CONTAINER * FAILURE, DESIGN ERROR * ORDNANCE * BUILDING

102467
FOLLOW-UP REPORT ON RADIOACTIVE GAS BUILDUP IN AUXILIARY BUILDING AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, PA.
1 PAGE, LETTER TO NRC DIV. OF REACTOR LICENSING, APRIL 20, 1975, DOCKET 50-289, TYPE--PHR, MFG--PEP, AE--
GILBERT ASSOC.

CAUSE - MINOR LEAKS. INVESTIGATIONS WITH THE VENTILATION SECURED HAVE IDENTIFIED 6 SOURCES OF
LEAKAGE. THREE ARE OPEN-ENDED FUNNELS DESIGNED TO COLLECT VALVE STEM LEAKOFF. LEAK RATES
INVOLVED ARE CALCULATED TO BE .002 TO .003 GPM. LEAKS WILL BE STOPPED. THE FOURTH AREA IS
WITHIN THE NAYS GAS ANALYZER ROOM. SAMPLING IS CONTINUING IN ORDER TO LOCATE THE SPECIFIC VALVE
OR FITTING CAUSING LEAKAGE.

AVAILABILITY - MICROSURANCE, INC., P.O. BOX 3522 OAK RIDGE, TENN. 37830

THREE MILE ISLAND 1 (PHR) * * * AIRBORNE RELEASE * DU LING * LEAK * N. VES * * * TEST, LEAK LOCATION

102540
REACTOR BUILDING EMERGENCY COOLING RIVER WATER PUMP FAILS TO START AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, PA.
3 PAGES, LETTER TO NRC DIVISION OF REACTOR LICENSING, MAY 1, 1975, DOCKET 50-289, TYPE--PHR, MFG--BEM, AE--
GILBERT ASSOC.

CAUSE - INTERMITTENT CONTACT ON SWITCH. DURING A TEST WHILE OPERATING THE REACTOR AT 98% POWER, A
REACTOR BUILDING EMERGENCY COOLING RIVER WATER PUMP FAILED TO START ON SIGNAL. THE PUMP WAS
SUCCESSFULLY STARTED MANUALLY FROM THE CONTROL ROOM. AN INTERMITTENT CONTACT ON THE CONTROL ROOM
SWITCH CAUSED THE FAILURE OF THE PUMP TO START. THE SWITCH WAS REPLACED. THE CAUSE OF THE
INTERMITTENT CONTACT WILL BE DETERMINED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

THREE MILE ISLAND 1 (PHR) * * * PUMPS * EMERGENCY COOLING * CONTAINMENT * TEST, SYSTEM OPERABILITY * * FAILURE,
COMPONENT * INSTRUMENT, SWITCH

102533
GAP FOUND AT SLIDE BEARING PLATE FOR MAIN STEAM LINE AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, PA.
2 PAGES, LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, MAY 2, 1975, DOCKET 50-289, TYPE--PHR, MFG--BEM,
AE--GILBERT ASSOC.

CAUSE - DESIGN DEFICIENCY. DURING A PERIOD OF EXTENDED POWER OPERATION, A GAP OF ABOUT 0.013 INCH
WAS FOUND AT THE SLIDE BEARING PLATES ON A HEATED POST IN THE MAIN STEAM SUPPORT SYSTEM. THE
CALCULATED MAXIMUM ALLOWABLE GAP IS 0.02749 INCH. WEEKLY INSPECTIONS WILL BE MADE TO SEE THAT
THE GAP DOES NOT EXCEED LIMITS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

THREE MILE ISLAND 1 (PHR) * * * SUPPLANT STRUCTURE * * PIPES AND PIPE FITTINGS * FAILURE, DESIGN ERROR

102527
CONTROL ROD DRIVE BREAKER FAILS TO TRIP AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, PA.
3 PAGES, LETTER TO NRC DIVISION OF REACTOR LICENSING, MAY 3, 1975, DOCKET 50-289, TYPE--PHR, MFG--BEM, AE--
GILBERT ASSOC.

CAUSE - LINKAGE OUT OF ADJUSTMENT. WHILE THE UNIT WAS OPERATING AT 98% POWER, VOLTAGE WAS LOST TO
CHANNEL D OF THE APS. CONTROL ROD DRIVE BREAKERS TRIPPED WHEN THE UNDERVOLTAGE RELAYS DE-
ENERGIZED. WHEN AN OPERATOR ATTEMPTED TO RECLOSE THE BREAKERS, ONE DID CLOSE WITH THE
UNDERVOLTAGE COIL DE-ENERGIZED. PROCEDURAL INADEQUACIES LED TO AN OUT OF ADJUSTMENT CONDITION OF
A MECHANICAL LINKAGE WITHIN THE BREAKER. THE ADJUSTMENT WAS CORRECTED. OTHER CRD TRIP BREAKERS
WERE TESTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

THREE MILE ISLAND 1 (PHR) * * * BREAKER * FAILURE, ADMINISTRATIVE CONTROL * PROCEDURES AND MANUALS * * CONTROL ROD
DRIVE MECHANISMS

103469
RADIUM CONCENTRATION IN RIVER WATER EXCEEDS LIMITS AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., READING, PA.
2 PAGES, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, JUNE 5, 1975, DOCKET 50-289, TYPE--PHR,

103664 CONTINUED
MFG--BEN, AE--GILBERT ASSOC.

CAUSE - HEAVY WATER TREATMENT. MONTHLY COMPOSITES OF WEEKLY GRAB SAMPLES OF RIVER WATER COLLECTED AT 2 STATIONS DOWNSTREAM FROM THE DISCHARGE SHOWED TRITIUM CONCENTRATIONS MORE THAN 10 TIMES THE CONTROL STATION VALUE. GAMMA SPECTROSCOPY INDICATED ALL OTHER ISOTOPES WERE LESS THAN MINIMUM DETECTABLE LEVELS. PROCESSING OF LIQUID RADIOACTIVE WASTE WATER WAS UNUSUALLY HEAVY DURING APRIL DUE TO BACKUP FROM PREVIOUS MONTHS WHEN EVAPORATORS HAD REDUCED AVAILABILITY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • TRITIUM • CONCENTRATION • EFFLUENT • RIVER • WASTE TREATMENT • WASTE TREATMENT, LIQUID • MONITORING PROGRAM, ENVIRONMENTAL

103673
TRITIUM CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., READING, PA.
3 PAGES, LETTER WITH REPORT TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION I, JUNE 5, 1975, DOCKET 50-289, TYPE--PWR, MFG--BEN, AE--GILBERT ASSOC.

CAUSE - WASTE PROCESSING. TWO MONTHLY COMPOSITES OF WEEKLY GRAB SAMPLES OF RIVER WATER SHOWED TRITIUM CONCENTRATIONS GREATER THAN 10 TIMES THE CONTROL STATION VALUE. ALL OTHER ISOTOPES WERE LESS THAN DETECTABLE LEVELS. PROCESSING OF LIQUID RADIOACTIVE WASTE WATER BY EVAPORATORS WAS UNUSUALLY HEAVY DURING APRIL DUE TO PREVIOUS REDUCED AVAILABILITY OF THE EVAPORATORS. THE LEVEL WAS LESS THAN 1/200 TH OF THE MAXIMUM PERMISSIBLE CONCENTRATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • TRITIUM • CONCENTRATION • EFFLUENT • WASTE DISPOSAL, LIQUID • WASTE DISPOSAL • RIVER • MONITORING PROGRAM, ENVIRONMENTAL

103672
DECAY HEAT RIVER WATER PUMP SHAFT FAILS AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., READING, PA.
4 PAGES, LETTER TO NRC DIVISION OF REACTOR LICENSING, JUNE 6, 1975, DOCKET 50-289, TYPE--PWR, MFG--BEN, AE--GILBERT ASSOC.

CAUSE - ROTATING BEARING FATIGUE. DURING TESTS IN A ROUTINE STARTUP, THE MOTOR SHAFT OF DECAY HEAT RIVER WATER PUMP B SHEARED ABOVE THE COUPLING. THE REACTOR WAS PLACED IN COLD SHUTDOWN 2 DAYS LATER. CONTRIBUTING FACTORS WERE (1) EXCESSIVE CLEARANCE IN THE UPPER BEARING FROM SHAFT VIBRATION AND ECCENTRICITY, (2) POSSIBLE MISALIGNMENT BETWEEN MOTOR AND SHAFT, AND (3) HYDRAULIC FORCES DUE TO PUMP STARTUP. THE MOTOR ENDBELL WAS CRACKED. THE SHAFT AND ENDBELL WERE REPLACED. ANTI-THRUST RESTRAINTS WILL BE INSTALLED ON ALL 12 RIVER WATER PUMPS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • PUMPS • FAILURE, COMPONENT • FAILURE, FATIGUE • FAILURE, DESIGN ERROR • FAILURE, INSTALLATION ERROR • SHUTDOWN COOLING SYSTEM • TEST, SYSTEM OPERABILITY • REACTOR SHUTDOWN

103680
SET POINT DRIFT IN REACTOR COOLANT PRESSURE CHANNEL AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, PA.
3 PAGES, LETTER TO NRC DIVISION OF REACTOR LICENSING, JUNE 13, 1975, DOCKET 50-289, TYPE--PWR, MFG--BEN, AE--GILBERT ASSOC.

CAUSE - INSTRUMENT DRIFT. DURING REACTOR COOLANT PRESSURE TRANSMITTER CALIBRATION WHILE THE REACTOR WAS IN COLD SHUTDOWN, ONE CHANNEL TRIPPED AT 2877 PSIG WHICH EXCEEDS THE 2855 PSIG LIMIT. THE CAUSE WAS MINOR CALIBRATION DRIFT. THE CHANNEL WAS RECALIBRATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SENSORS, PRESSURE • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT • SET POINT • DRIFT • MAIN COOLING SYSTEM • REACTOR SAFETY SYSTEM

103629
SET POINT DRIFT IN REACTOR COOLANT PRESSURE SWITCHES AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, PA.
3 PAGES, LETTER TO NRC DIVISION OF REACTOR LICENSING, JUNE 16, 1975, DOCKET 50-289, TYPE--PWR, MFG--BEN, AE--GILBERT ASSOC.

CAUSE - CONVERTERS OUT OF CALIBRATION. DURING TESTING WITH THE REACTOR IN COLD SHUTDOWN, 3 VARIABLE LOW REACTOR COOLANT SYSTEM PRESSURE TRIP SET POINTS WERE LESS THAN THE 183.5 PSIG LIMIT BY 2.0 TO 4.1 PSI. THE CAUSE IS NOT KNOWN FOR SURE. THE TEMPERATURE-TO-PRESSURE SIGNAL CONVERTERS MAY HAVE BEEN OUT OF CALIBRATION OR A VOLTMETER USED IN CHECKS COULD HAVE BEEN OUT OF CALIBRATION. THE SWITCHES WERE RESET USING A CALIBRATED VOLTMETER.

103029 CONTINUUM
 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND I (PWR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SENSORS, PRESSURE • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT • SET POINT • DRIFT • REACTOR SAFETY SYSTEM • MAIN COOLING SYSTEM • FAILURE, MAINTENANCE ERROR

103090
 REACTOR BUILDING PURGE ISOLATION VALVE LEAKS EXCESSIVELY AT THREE MILE ISLAND I
 METROPOLITAN EDISON COMPANY, PA.
 3 PAGES. LETTER TO NRC DIRECTORATE OF LICENSING, JUNE 25, 1975, DOCKET 50-289, TYPE--PWR, NRC--BEM, AE--GILBERT ASSOC.

CAUSE - UNKNOWN. DURING THE YEARLY LEAK RATE TEST OF THE REACTOR BUILDING PURGE ISOLATION VALVES WHILE THE REACTOR WAS AT 89.58 POWER, A VALVE WAS FOUND TO LEAK EXCESSIVELY. THERE WAS ABOUT 1/16 INCH GAP BETWEEN SEATING SURFACES IN THE CLOSED POSITION. THE OPERATING MECHANISM WAS ADJUSTED AND THE VALVE RETESTED SATISFACTORILY. THE APPARENT CAUSE IS NOT KNOWN. THE ADJUSTMENT PROCEEDURE MAY BE INADEQUATE TO ASSURE LONG TERM ADJUSTMENT OR THE DESIGN MAY NOT PERMIT PROPER ADJUSTMENT FOR LONG TERM SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND I (PWR) • LEAK RATE • VALVES • CONTAINMENT ISOLATION • CONTAINMENT PURGE • TEST, SYSTEM OPERABILITY • TEST, LEAK RATE • CONTAINMENT INTEGRITY

103089
 VENDOR PERFORMED WORK NOT CONTROLLED PROPERLY AT THREE MILE ISLAND I
 METROPOLITAN EDISON COMPANY, PA.
 3 PAGES. LETTER TO NRC DIRECTORATE OF REACTOR LICENSING, JUNE 27, 1975, DOCKET 50-289, TYPE--PWR, NRC--BEM, AE--GILBERT ASSOC.

CAUSE - PROCEDURAL DEFICIENCY. WHEN THE MOTOR FOR A DECAY HEAT RIVER WATER PUMP WAS RECEIVED FROM THE VENDOR FOLLOWING REPAIR OF A FAILED SHAFT, ADEQUATE DOCUMENTATION WAS NOT AVAILABLE. THE MOTOR HAD NOT BEEN REPAIRED IN ACCORDANCE WITH ORIGINAL DESIGN SPECS. FOR HIGH PRIORITY VENDOR WORK, ADMINISTRATIVE/PROCEDURAL CONTROLS ARE NOT ADEQUATE TO ENSURE APPROPRIATE UAC REQUIREMENTS PRIOR TO START OF WORK. THE MOTOR WAS UPGRADED TO EXCEED REQUIREMENT. MEASURES WILL BE TAKEN TO PREVENT RECURRENCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND I (PWR) • QUALITY ASSURANCE • MAINTENANCE AND REPAIR • MOTORS • SHUTDOWN COOLING SYSTEM • FAILURE, ADMINISTRATIVE CONTROL • PROCEDURES AND MANUALS

103087
 SET POINT DRIFT IN PRESSURE TRANSMITTER AT THREE MILE ISLAND I
 METROPOLITAN EDISON COMPANY, PA.
 3 PAGES. LETTER TO NRC DIRECTORATE OF REACTOR LICENSING, JUNE 27, 1975, DOCKET 50-289, TYPE--PWR, NRC--BEM, AE--GILBERT ASSOC.

CAUSE - MINOR INSTRUMENT DRIFT. DURING TESTING TO DETERMINE INSTRUMENT DRIFT WITH THE REACTOR AT 99% POWER, 1 OF THE 4 VARIABLE LOW REACTOR COOLANT SYSTEM PRESSURE TRIP SET POINTS WAS MEASURED TO BE 1031.2 PSIG WHICH IS BELOW THE 1031.5 PSIG LIMIT. THE CHANNEL WAS RECALIBRATED. THE TEMPERATURE-TO-PRESSURE SIGNAL CONVERTER WAS OUT OF CALIBRATION DUE TO MINOR INSTRUMENT DRIFT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND I (PWR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SENSORS, PRESSURE • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT • SET POINT • DRIFT • REACTOR SAFETY SYSTEM

103086
 REACTOR POWER INCREASED ABOVE POWER LEVEL CUT OFF TOO SOON AT THREE MILE ISLAND I
 METROPOLITAN EDISON COMPANY, PA.
 3 PAGES. LETTER TO NRC DIVISION OF REACTOR LICENSING, JULY 2, 1975, DOCKET 50-289, TYPE--PWR, NRC--BEM, AE--GILBERT ASSOC.

CAUSE - PROCEDURAL DEFICIENCY. WHILE RETURNING TO FULL POWER OPERATION AFTER A FORCED POWER REDUCTION, REACTOR POWER WAS INCREASED ABOVE THE CUTOFF (82.5%) BEFORE REACTOR REACTIVITY WAS ASYMPTOTICALLY APPROACHING STABILITY. REACTOR REACTIVITY WAS WITHIN 1% OF THE EQUILIBRIUM VALUE. THERE WAS A LACK OF PROCEDURAL GUIDANCE FOR DETERMINING WHEN REACTOR REACTIVITY IS ASYMPTOTICALLY APPROACHING STABILITY FOR THE TYPE OF POWER MANEUVERING IN PROGRESS AT THE TIME OF THE OCCURRENCE. CURVES OF REACTOR REACTIVITY VS TIME AND POWER LEVEL FOR SEVERAL POWER TRANSIENTS WILL BE SHOWN TO THE OPERATORS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 N STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

10000 CONTINUED

THREE MILE ISLAND 1 (PHR) • PHENIX • REACTIVITY EFFECT • REACTOR POWER • REACTOR STARTUP • FAILURE, ADMINISTRATIVE CONTROL • PROCEDURES AND MANUALS • REACTOR STABILITY

10100

SET POINT DRIFT IN TEMPERATURE DISTABLE AT THREE MILE ISLAND 1

METROPOLITAN EDISON COMPANY, PA.

3 PAGES, LETTER TO NRC DIVISION OF REACTOR LICENSING, JULY 3, 1975, DOCKET 50-289, TYPE--PHR, NRC--BEM, AE--WILBERT ASSOC.

CAUSE - DEFECTIVE SOLDER JOINT. DURING TESTING WITH THE REACTOR AT 99% POWER, 1 OF THE 4 REACTOR COOLANT TEMPERATURE TRIP DISTABLES FAILED TO TRIP. FAILURE WAS TRACED TO A DEFECTIVE PRINTED CIRCUIT BOARD SOLDER JOINT IN THE SIGNAL CONVERTER. THE DEFECTIVE TRIP CIRCUIT WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PHR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SENSORS, TEMPERATURE • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT • SET POINT • DRIFT • REACTOR SAFETY SYSTEM • FAILURE, FABRICATION ERROR • ELECTRONIC FUNCTION UNITS

10200

UNPLANNED RELEASE OF RADIOACTIVE GAS OCCURS AT THREE MILE ISLAND 1

METROPOLITAN EDISON COMPANY, PA.

3 PAGES, LETTER WITH REPORT TO NRC DIVISION OF REACTOR LICENSING, JULY 3, 1975, DOCKET 50-289, TYPE--PHR, NRC--BEM, AE--WILBERT ASSOC.

CAUSE - LEAK IN WASTE EVAPORATOR. DURING A 13 HOUR PERIOD, INADVERTANT SPORADIC RELEASES OF RADIOACTIVE MATERIAL OCCURRED WHILE ADDING WATER TO THE MAKEUP TANK AND THE REACTOR COOLANT BLEED TANKS. TOTAL RELEASE TIME WAS 7.1 HOURS RELEASING 3.97 CI OF MAINLY Xe-133. THE APPARENT CAUSE WAS LEAKS IN THE MISCELLANEOUS WASTE EVAPORATOR OR ITS ASSOCIATED PIPING. WHEN THE EVAPORATORS WERE ISOLATED FROM THE VENT HEADER SYSTEM, NO FURTHER RELEASES OCCURRED DURING SIMILAR MAKEUP OPERATIONS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PHR) • AIRBORNE RELEASE • WASTE TREATMENT, EQUIPMENT • EVAPORATION • PHENIX • FAILURE, EQUIPMENT

10400

SUSPENDED SOLIDS IN EFFLUENT EXCEEDS LIMIT AT THREE MILE ISLAND 1

METROPOLITAN EDISON COMPANY, PA.

3 PAGES, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, JULY 10, 1975, DOCKET 50-289, TYPE--PHR, NRC--BEM, AE--WILBERT ASSOC.

CAUSE - HIGH CONCENTRATION IN INFLUENT. IT WAS DISCOVERED ON JULY 3 THAT DURING THE RELEASE OF THE WASTE NEUTRALIZING TANK ON JUNE 6 THAT THE CONCENTRATION OF SUSPENDED SOLIDS IN THE PLANT RIVER WATER DISCHARGE EXCEEDED THE 500 PPM LIMIT BY 24 PPM. AT THAT TIME THE RIVER WATER INFLUENT INDICATED 659 PPM. SINCE THE CONCENTRATION IN THE INFLUENT EXCEEDED THE CONCENTRATION IN THE EFFLUENT, THERE WAS NO APPROPRIATE IMMEDIATE CORRECTIVE ACTION THAT COULD BE TAKEN. HEAVY RAINS HAD OCCURRED THE DAY BEFORE THE RELEASE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

WATER QUALITY • EFFLUENT • WASTE DISPOSAL • WEATHER, SEVERE • THREE MILE ISLAND 1 (PHR) • RIVER

10430

SOLDER WELD JOINTS LEAK IN VENT LINE OF MAKE-UP PUMPS AT THREE MILE ISLAND 1

METROPOLITAN EDISON COMPANY, PA.

3 PAGES, LETTER TO NRC DIV. OF REACTOR LICENSING, JULY 21, 1975, DOCKET 50-289, TYPE--PHR, NRC--BEM, AE--WILBERT ASSOC.

CAUSE - IMPROPER INSTALLATION. DURING A ROUTINE INSPECTION WITH THE REACTOR AT 100% POWER, 2 LEAKS WERE DISCOVERED IN SOLDER WELD JOINTS OF THE MAKE-UP PUMP SUCTION VENT LINE. ONE WAS A CRACK IN THE WELD JOINT ADJACENT TO THE 6-INCH SUCTION LINE. THE OTHER WAS A PINHOLE CRACK IN THE WELD JOINT OF AN ELBOW FITTING. PROCEDURES SPECIFY 80 INCH MINIMUM DISTANCE BETWEEN A MOVING ANCHOR AND THE FIRST PIPE RESTRAINT. FOR THE VENT LINE ONLY 23 INCHES EXISTED. CYCLIC STRESSES CAUSED FATIGUE FAILURE OF THE WELD JOINTS. THE LEAKS WERE ISOLATED. RESTRAINTS WERE MODIFIED TO CONFORM TO SPECS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PHR) • PIPES AND PIPE FITTINGS • FAILURE, FATIGUE • FAILURE, PIPE • FEEDWATER • FAILURE, INSTALLATION ERROR • SUPPORT STRUCTURE • LEAK • PHENIX

104450
NUCLEAR SERVICES RIVER WATER PUMP VALVE FAILS TO CLOSE AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, READING, PA.
3 PGS, LTR TO NRC DIVISION OF REACTOR LICENSING, JULY 25, 1975, DOCKET 50-209, TYPE--PWR, NRC--BGM, AE--
GILBERT ASSOC.

CAUSE - MOTOR FAILURE. WHILE REMOVING A NUCLEAR SERVICES RIVER WATER PUMP FROM SERVICE, ITS
DISCHARGE VALVE FAILED TO CLOSE ON SIGNAL FROM THE CONTROL ROOM. THE VALVE WAS MANUALLY CLOSED.
THE VALVE MOTOR APPEARS TO HAVE EXPERIENCED AN OPEN PHASE ON ONE WINDING RESULTING IN SEVERE
HEATING. THE OVERLOAD PROTECTION DEVICES WERE OVERSIZED AND FAILED TO PROTECT ON OVERLOAD. THE
OVERLOAD TRIPPED AT 50 SECONDS WHILE THE ACCEPTABLE RANGE IS 17 TO 30 SE. THE MOTOR WAS
REPLACED AND THE OVERLOAD RESET. THE CAUSE OF THE OPEN PHASE HAS NOT BEEN DETERMINED. THE
REACTOR WAS AT FULL POWER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • VALVES • AUXILIARY COOLING • VALVE OPERATORS • FAILURE, EQUIPMENT

104459
FREQUENCY RELAY FOR DIESEL GENERATOR FAILS AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., READING, PA.
3 PAGES, LETTER TO NRC DIVISION OF REACTOR LICENSING, JULY 31, 1975, DOCKET 50-209, TYPE--PWR, NRC--BGM, AE--
GILBERT ASSOC.

CAUSE - UNKNOWN. DURING A TEST ON DIESEL GENERATOR A WITH THE REACTOR AT 99% POWER, 1 OF THE 3
FREQUENCY RELAYS WAS NOTED NOT TO HAVE PICKED UP. THE RELAY WAS REPLACED. THE DEFECTIVE RELAY
WAS THEN TESTED AND FOUND TO PICK UP AT 59.2 HZ. NO DEFINITE CAUSE OF FAILURE WAS FOUND. THE
RELAY WAS RESET TO PICK UP AT 59 HZ, CLEANED, AND CONNECTIONS TIGHTENED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • RELAY • INSTRUMENT, PROTECTIVE • GENERATOR, DIESEL • FAILURE, INSTRUMENT •
TEST, SYSTEM OPERABILITY • EMERGENCY POWER, ELECTRIC

104460
SET POINT DRIFT IN PRESSURE TRANSMITTERS AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., READING, PA.
3 PAGES, LETTER TO NRC DIVISION OF REACTOR LICENSING, AUG. 1, 1975, DOCKET 50-209, TYPE--PWR, NRC--BGM, AE--
GILBERT ASSOC.

CAUSE - INSTRUMENT DRIFT. DURING TESTING OF THE HIGH REACTOR COOLANT PRESSURE TRIP SET POINTS
WITH THE REACTOR AT FULL POWER, 2 HIGH PRESSURE AND 1 SHUTDOWN BYPASS CHANNEL TRIPPED ABOVE THEIR
LIMIT OF 2 TO 3 PSI. THEY WERE IMMEDIATELY RECALIBRATED. THE CAUSE WAS MINOR CALIBRATION DRIFTS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SENSORS, PRESSURE • TEST, SYSTEM
OPERABILITY • FAILURE, INSTRUMENT • SET POINT • DRIFT • REACTOR SAFETY SYSTEM

104470
DISSOLVED SOLIDS CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, READING, PA.
3 PGS, LTR TO NRC OFFICE OF I & E, REGION 1, AUGUST 9, 1975, DOCKET 50-209, TYPE--PWR, NRC--BGM, AE--GILBERT
ASSOC.

CAUSE - PROCEDURAL DEFICIENCY. A PREOPERATIONAL CLEANING AND FLUSHING SETTLING BASIN WAS BEING
NEUTRALIZED AND DISCHARGED TO THE RIVER. THE DAILY SAMPLE FOR A DAY INDICATED THE DISSOLVED
SOLIDS CONCENTRATION TO BE 821 PPM, EXCEEDING THE 700 PPM LIMIT. THIS RESULT WAS NOT NOTICED
UNTIL THE DISCHARGE WAS STARTED THE NEXT DAY. THE DISCHARGE WAS TERMINATED. RELEASE RATE WILL
BE REDUCED FROM 750 TO 550 GPP. PROCEDURES WERE MODIFIED TO REQUIRE SAMPLING AND ANALYSIS
(SEE 1) THE DAY TO PREVENT RECURRENCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • CONCENTRATION • EFFLUENT • FAILURE, ADMINISTRATIVE CONTROL • PROCEDURES AND
MANUALS

104479
SAMPLE NOT TAKEN DURING WASTE TANK RELEASE AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, READING, PA.
3 PGS, LTR TO NRC OFFICE OF I & E, REGION 1, AUG. 9, 1975, DOCKET 50-209, TYPE--PWR, NRC--BGM, AE--GILBERT
ASSOC.

CAUSE - PROCEDURAL DEFICIENCY. DISCHARGE OF THE WASTE NEUTRALIZING TANK WAS INITIATED AND THE

100575 RELATIVES

CHEMISTRY DEPARTMENT ACTIVITIES TO DRAW A SAMPLE. DUE TO THE END OF SHIFT WORK LOAD, THE TANK WAS PASSED ON TO THE ON-COMING SHIFT BUT INSTRUCTIONS WERE NOT PROPERLY TRANSMITTED. THE SAMPLE WAS NOT TAKEN. PROCEDURES DO NOT REQUIRE VERIFICATION THAT THE SAMPLE WAS TAKEN. THEY WILL BE REVISITED. TRAILING ON THE IMPORTANCE OF RELIABLE TURNOVER OF INFORMATION DURING SHIFT RELIEF WILL BE GIVEN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • SAMPLING • WASTE DISPOSAL, LIQUID • PROCEDURES AND MANUALS • FAILURE, ADMINISTRATIVE CONTROL • COMMUNICATION

105273

RADIOACTIVITY IN EFFLUENT EXCEEDS CONTROL VALUE AT THREE MILE ISLAND 1

METROPOLITAN EDISON COMPANY, READING, PA.

3 PGS, LTR W/AD TS-02 TO NRC OFFICE OF I & E, REGION I, AUG. 10, 1975, DOCKET 50-289, TYPE--PWR, NRC--BEM, AE--GILBERT ASSOC.

CAUSE - SAMPLES NOT REPRESENTATIVE. A MONTHLY COMPOSITE OF WEEKLY GRAB SAMPLES OF SURFACE RIVER WATER COLLECTED 1.5 MILES DOWNSTREAM OF THE DISCHARGE HAD A TOTAL TRITIUM ACTIVITY THAT WAS MORE THAN 4 TIMES THE CONTROL STATION VALUE. IT IS BELIEVED THAT SAMPLES WERE TAKEN DURING PERIODS OF EVAPORATOR CONDENSATE TANK DISCHARGE AND, THEREFORE, DURING PERIODS OF HIGHER-THAN-NORMAL TRITIUM LEVEL. THE LEVEL WAS LESS THAN 1/1000 OF THE NRC LIMIT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • OPERATION • CONCENTRATION • EFFLUENT • WASTE DISPOSAL • RIVER • SAMPLING • WASTE DISPOSAL, LIQUID • CONDENSER COOLING SYSTEM

105526

EXCESSIVE COOLING OF THE COOLING TOWER DISCHARGE AT THREE MILE ISLAND 1

METROPOLITAN EDISON COMPANY, READING, PA.

3 PGS, LTR TO NRC OFFICE OF I & E, REGION I, AUG. 22, 1975, DOCKET 50-289, TYPE--PWR, NRC--SLV, AE--GILBERT ASSOC.

CAUSE - PRIMAORDIAL DEFICIENCY. WITH THE REACTOR OPERATING AT FULL POWER, WATER WITH A TEMPERATURE 5.5 F BELOW AMBIENT RIVER TEMPERATURE (90 F) WAS DISCHARGED FROM THE MECHANICAL DRAFT COOLING TOWER. THE OPERATOR HAD SWITCHED FROM FAN A TO FAN C WHICH HAS A SLIGHTLY GREATER COOLING CAPACITY. COOLING OCCURRED MORE RAPIDLY THAN EXPECTED. WITHIN 30 MINUTES THE ERROR WAS RECOGNIZED AND CORRECTED. PROCEDURES DID NOT PROVIDE ENOUGH GUIDANCE ON SWITCHING COOLING TOWER FANS. THE OPERATOR FAILED TO PROPERLY MONITOR EFFLUENT TEMPERATURE AFTER FAN SWITCHING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • TEMPERATURE • EFFLUENT • CONDENSER COOLING SYSTEM • COOLING TOWER, MECHANICAL • COOLING TOWER • FAILURE, ADMINISTRATIVE CONTROL • FAILURE, OPERATOR ERROR • PROCEDURES AND MANUALS

106310

UNPLANNED RELEASE OF RADIOACTIVE MATERIAL AT THREE MILE ISLAND 1

METROPOLITAN EDISON CO., PA.

4 PGS, LTR W/AD TS-04 TO NRC DIV. OF OFFICE OF I & E, AUG. 28, 1975, DOCKET 50-289, TYPE--PWR, NRC--BEM, AE--GILBERT ASSOC.

CAUSE - LOSS OF TANK LOOP SEAL. AN INADVERTANT RELEASE OF RADIOACTIVE MATERIAL OCCURRED DUE TO LOSS OF THE RECLAIMED BORIC ACID TANK B LOOP SEAL. THE MATERIAL WAS RELEASED TO THE RECLAIMED BORIC ACID TANK/CONCENTRATED WASTE STORAGE TANK ROOM AND DISCHARGED THROUGH THE VENTILATION SYSTEM. A LEAK DEVELOPED AT A UNION FITTING IN PIPING ASSOCIATED WITH THE LOOP SEAL SIGHT GLASS. THIS CAUSED LOSS OF THE LOOP SEAL. THE TOTAL RELEASE WAS 0.51 CI OF PREDOMINATELY RE-139. THE SEAL WAS RE-ESTABLISHED TERMINATING THE RELEASE. THE LEAKING FITTING WAS REPAIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • AIRBORNE RELEASE • XENON • SEAL • STORAGE CONTAINER • LEAK • PIPES AND PIPE FITTINGS • WASTE TREATMENT • WASTE TREATMENT, EQUIPMENT

106311

SOCKET WELD IN MAKE-UP PUMP SUCTION VENT LINE LEAKS AT THREE MILE ISLAND 1

METROPOLITAN EDISON CO., PA.

3 PGS, AD 50-289/75-27 TO NRC DIVISION OF REACTOR LICENSING, AUG. 29, 1975, DOCKET 50-289, TYPE--PWR, NRC--BEM, AE--GILBERT ASSOC.

CAUSE - VIBRATION INDUCED FATIGUE. DURING A ROUTINE INSPECTION WHILE OPERATING AT 100% POWER, A SMALL CRACK AND LEAK WERE DISCOVERED IN MAKE-UP PUMP A SUCTION VENT LINE SOCKET WELD ADJACENT TO THE 6-INCH DIAMETER PUMP SUCTION LINE. CONTINUED VIBRATION OF THE MAKE-UP PUMP SUCTION LINE CREATED A FATIGUE CRACK IN THE VENT LINE AT THE EDGE OF THE REPAIR MADE TO CORRECT A PREVIOUS

100322 - CONTINUED

LEAK. THE 3 RIGID PIPE GUIDES FOR THE SUCTION LINE DO NOT PROVIDE ADEQUATE DAMPENING. THE WELD CRACK WAS REPAIRED. THE 3 RIGID PIPE GUIDES WILL BE REBUILT TO RESTRICT VIBRATIONAL AMPLITUDE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • PWR • PIPES AND PIPE FITTINGS • FEEDWATER • FAILURE, PIPE • FAILURE, FATIGUE • FAILURE, DESIGN ERROR • VIBRATION • LEAK • CRACK • SUPPORT STRUCTURE

105720

PRESSURE SWITCH IN VALVE CONTROL CIRCUIT FAILS AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, READING, PA.

3 PGS. LTR TO NRC DIV. OF REACTOR LICENSING, SEPT. 2, 1975, DOCKET 50-289, TYPE--PWR, NRG--BEB, AE--GILBERT ASSOC.

CAUSE - HIGH AMBIENT TEMPERATURE. DURING TESTING OF THE TURBINE DRIVE EMERGENCY FEED PUMP, STEAM GENERATOR B STEAM SUPPLY VALVE WOULD NOT REMAIN OPEN WHEN THE OPEN PUSHBUTTON WAS RELEASED. THE RECLOSURE RESULTED FROM FAILURE OF A PRESSURE SWITCH IN THE VALVE CONTROL CIRCUIT. THE SWITCH WAS EXPOSED TO A HIGH AMBIENT TEMPERATURE RESULTING IN MATERIAL DEGRADATION AND A STEAM LEAKAGE INTO THE ELECTRICAL PORTION OF THE SWITCH. THE MET. CORRUDED PRESSURE SWITCH CAUSED A GROUND ENERGIZING A RELAY WHICH CLOSED THE VALVE. THE PRESSURE SWITCH WAS REPLACED. A DIFFERENT TYPE SWITCH IS BEING CONSIDERED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INSTRUMENT, SWITCH • SENSORS, PRESSURE • FAILURE, DESIGN ERROR • ENVIRONMENT • TEMPERATURE • TEST, SYSTEM OPERABILITY • PUMPS • FEEDWATER • THREE MILE ISLAND 1 (PWR)

105722

COOLING TOWER DISCHARGE COOLED EXCESSIVELY AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, READING, PA.

3 PGS. LTR TO NRC OFFICE OF L & E, SEPT. 3, 1975, DOCKET 50-289, TYPE--PWR, NRG--BEB, AE--GILBERT ASSOC.

CAUSE - SUDDEN COLD FRONT MOVED THROUGH. WHILE OPERATING AT 100% POWER, WATER WITH A TEMPERATURE OF 3-4 F BELOW THE AMBIENT RIVER TEMPERATURE (89 F) WAS DISCHARGED FROM THE MECHANICAL DRAFT COOLING TOWER. THIS OCCURRED WHEN A COLD FRONT MOVED THROUGH THE AREA CAUSING A RAPID CHANGE IN THE TOWER OPERATING CONDITIONS. AMBIENT AIR TEMPERATURE DROPPED FROM 88 F TO 76 F IN 30 MINUTES. ALLOWABLE TEMPERATURE DIFFERENTIAL WAS ESTABLISHED WITHIN 15 MINUTES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • TEMPERATURE GRADIENT • CONDENSER COOLING SYSTEM • DISCHARGE • COOLING TOWER, MECHANICAL • COOLING TOWER • WEATHER, SEVERE • RIVER • THERMAL TRANSIENT

100308

CURE FLOOD TANK SAMPLE LINE FAILS TO CLOSE AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., PA.

4 PGS. LTR NRC 50-429/75-30 TO DIR. OF DIVISION OF REACTOR LICENSING, SEPT. 5, 1975, DOCKET 50-289, TYPE--PWR, NRG--BEB, AE--GILBERT ASSOC.

CAUSE - TORQUE SWITCH MALFUNCTION. DURING SURVEILLANCE TESTING WITH THE REACTOR AT 90% POWER, CURE FLOOD TANK B SAMPLE LINE ISOLATION VALVE FAILED TO CLOSE. IMMEDIATELY PRIOR TO THIS FAILURE, IT OPERATED SATISFACTORILY TWICE. INITIAL INVESTIGATION INDICATED THAT THE VALVE PACKING WAS BINDING AGAINST THE VALVE STEM CAUSING THE CLOSING TORQUE SWITCH TO OPERATE PREMATURELY. LATER, IT WAS FOUND THAT THE TORQUE SWITCH MAY HAVE BEEN PHYSICALLY HELD OPEN INTERMITTENTLY BY SPLICE INSULATING CAPS ASSOCIATED WITH WIRING LOCATED NEXT TO THE SWITCH. THE SWITCH SETTING WAS INCREASED, WIRES RELOCATED, AND THE PACKING REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • VALVES • CURE REFLOODING SYSTEM • CONTAINMENT ISOLATION • SAMPLING • FAILURE, MAINTENANCE ERROR • SEAL • CABLES AND CONNECTORS • INSTRUMENT, SWITCH • TEST, SYSTEM OPERABILITY

105721

REACTOR BUILDING PURGE SUPPLY VALVE FAILS TO FULLY CLOSE AT THREE MILE ISLAND 1
METROPOLITAN EDISON COMPANY, READING, PA.

3 PGS. LTR TO NRC DIV. OF REACTOR LICENSING, SEPT. 5, 1975, DOCKET 50-289, TYPE--PWR, NRG--BEB, AE--GILBERT ASSOC.

CAUSE - LACK OF LUBRICATION. WHILE PLACING VARIOUS COMPONENTS IN THE REQUIRED PRETEST POSITION WITH THE REACTOR AT 90% POWER, A REACTOR BUILDING PURGE SUPPLY VALVE INDICATED THAT THE VALVE WAS NOT FULLY CLOSED. THE OPERATOR ATTEMPTED TO OPEN THE VALVE BUT IT DID NOT FULLY OPEN. IT THEN CLOSED COMPLETELY ON SIGNAL. THE OPERATING CYLINDERS ON THE ROBOTARM ACTUATOR WERE FOUND TO HAVE CORROSION ON THE INTERNAL SURFACES. THERE MAY BE NO PERIODIC LUBRICATION OF THE CYLINDERS AND THE VALVE AIR SUPPLY IS NOT SUPPLIED WITH AN OILER. THE CYLINDERS WERE BINDING DUE TO CORROSION

105721 CONTINUED
AND INADEQUATE LUBRICATION. THE ADJUSTING ACTUATOR WAS LUBRICATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PHN) • VALVES • PLANT/INSTRUMENT PURGE • TEST, SYSTEM OPERABILITY • FAILURE, MAINTENANCE ERROR • VALVE OPERATORS • LUBRICATION • LUBRICATION

106330
INCORRECT ULTRAVIOLET DETECTOR INSTALLED AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., PA.
3 PGS. LTR W/REPORT TO NRC DIR. OF OFFICE OF I & E, REGION 1, SEPT. 10, 1975, DOCKET 50-289, TYPE--PHN, MFG--
GEN. AR--GILBERT ASSOC.

CAUSE - BREAKDOWN IN QA PROGRAM. RECENTLY IT WAS DISCOVERED THAT THE ULTRAVIOLET DETECTORS USED IN THE AIR INTAKE TUNNEL FIRE PROTECTION SYSTEM ARE OF A DIFFERENT TYPE THAN ORIGINALLY SPECIFIED BY THE VENDOR DRAWINGS. THE INSTALLED DETECTOR HAS A LONGER REACTION TIME, SMALLER CONE OF VISION, AND A SMALL SPECTRAL RANGE. HOWEVER, THE INSTALLED DETECTORS MEET DESIGN CRITERIA AND ARE SATISFACTORY IN ALL RESPECTS. THE CAUSE WAS A BREAKDOWN IN THE QUALITY ASSURANCE PROGRAM THAT EXISTED DURING INSTALLATION. TECH SPECS AND THE PSAR WILL BE AMENDED TO COMPLY WITH THE INSTALLED UNITS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PHN) • ULTRAVIOLET • MONITOR • FIRE PROTECTION • INSTRUMENT, SURVEILLANCE • FAILURE, INSTALLATION ERROR • QUALITY ASSURANCE • SYSTEM CAPABILITY • MODIFICATION

106335
AVAILABILITY OF EMERGENCY SHUTDOWN COOLING WATER LIMITED AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., PA.
3 PGS. LTR W/REPORT TO NRC DIR. OF OFFICE OF I & E, REGION 1, SEPT. 11, 1975, DOCKET 50-289, TYPE--PHN, MFG--
GEN. AR--GILBERT ASSOC.

CAUSE - EXCESS SEDIMENT IN INTAKE CHANNEL. THE RESULTS OF THE ANNUAL HYDROGRAPHIC SURVEY SHOWED THAT AN EXCESSIVE AMOUNT OF SEDIMENT HAD ACCUMULATED IN THE INTAKE CHANNEL SINCE IT WAS LAST DREDGED. ANALYSIS INDICATED THAT NOT ENOUGH COOLING WATER WOULD BE AVAILABLE FOR SAFE SHUTDOWN DURING A LULL IF THE RIVER FLOW DECREASED BELOW 7000 CFS AND A MAJOR PORTION OF THE YONK HAVEN DAM FAILED. EFFORTS ARE UNDERWAY TO OBTAIN AN EMERGENCY PERMIT FROM THE ARMY CORPS OF ENGINEERS AND TO MOBILIZE NECESSARY EQUIPMENT FOR DREDGING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PHN) • SYSTEM CAPABILITY • CANAL • INTAKE • EMERGENCY COOLING SYSTEM • PERIOD • FLOW OBSTRUCTION

106337
UNPLANNED RELEASE OF RADIOACTIVE MATERIAL OCCURS AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., PA.
3 PGS. LTR W/REPORT TO NRC DIR. OF OFFICE OF I & E, SEPT. 15, 1975, DOCKET 50-289, TYPE--PHN, MFG--GEN. AR--GILBERT ASSOC.

CAUSE - OPERATOR ERROR. DURING A 2.5-HR PERIOD, AN INADVERTANT RELEASE OF RADIOACTIVE MATERIAL OCCURRED DUE TO A DRAIN POT DRAIN VALVE ASSOCIATED WITH THE WASTE GAS SYSTEM DELAY TANK BEING LEFT IN THE OPEN POSITION FOLLOWING A R. THE DRAINING OF THE DRAIN POT. THIS WAS A PERSONNEL ERROR. TOTAL RELEASE WAS 5.75 CI OF PREVIOUSLY RE-133. PROCEDURAL CHANGES HAVE BEEN IMPLEMENTED TO MAINTAIN HIGHER LEVELS IN DRAIN POT SIGHT GLASSING TO ALLOW POSITIVE INDICATION OF OPEN DRAIN VALVES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PHN) • RADIOACTIVE RELEASE • PERSON • FAILURE, OPERATOR ERROR • VALVES • WASTE TREATMENT, EQUIPMENT • WASTE TREATMENT

106338
DE-ICE MAKE-UP VALVE FAILS TO CLOSE AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., PA.
3 PGS. LTR W/REPORT TO NRC DIVISION OF REACTOR LICENSING, SEPT. 26, 1975, DOCKET 50-289, TYPE--PHN, MFG--
GEN. AR--GILBERT ASSOC.

CAUSE - HIGH RESISTANCE CONTACT. AFTER TERMINATING MAKE-UP FLOW TO THE NUCLEAR SERVICES COOLING-WATER CIRCULATING WATER SYSTEM, A DE-ICE MAKE-UP VALVE FAILED IN THE OPEN POSITION. IT WAS CLOSED USING ITS HANDWHEEL. A HIGH RESISTANCE CONTACT WAS FOUND IN THE CLOSING CONTROL CIRCUIT. THE CONTACT WAS CLEANED AND CHECKED FOR PROPER OPERATION. THE VALVE WAS TESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM

102604 PLUTINUM
CHARGE \$2.00

THREE MILE ISLAND 1 (PHW) • VALVES • AUXILIARY COOLING • FAILURE, INSTRUMENT • INSTRUMENT, INTERLOCK • CONTROL SYSTEM • FAILURE, MAINTENANCE ERROR • RELAYS

104517
CORE FLOW TANK LEVEL FOUND TO BE LESS THAN LIMITS AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., PA.
3 PGS., AU 50-289/75-31 TO NRC DIVISION OF REACTOR LICENSING, SEPT. 26, 1975, JACKET 50-289, TYPE--PHW, HFG--
BGM, AE--GILBERT ASSOC.

CAUSE - INSTRUMENT LINE BLOCKED WITH THE REACTOR AT 100% POWER. CORE FLOW TANK LEVEL TRANSMITTER CALIBRATION WAS CONDUCTED DUE TO DIFFERENCES IN INDICATION BETWEEN REDUNDANT CHANNELS. THE LOWER READING CHANNEL WAS CHECKED FIRST SINCE THE OTHER HAD REMAINED CONSTANT. IT WAS FOUND TO REQUIRE ONLY MINOR ADJUSTMENT. THE TANK LEVEL WAS ACTUALLY 12.2 FEET WHICH IS BELOW THE 12.55 FOOT LIMIT. DURING CALIBRATION OF THE OTHER CHANNEL THE LOW SIDE SENSING LINE HAD A PARTIAL BLOCKAGE. AFTER IT WAS BLOWN DOWN, BOTH CHANNELS INDICATED THE SAME. AN EARLIER CHECK-OUT OF CHANNELS WITH PROBLEMS WILL BE INITIATED. TANK LEVEL WAS INCREASED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

THREE MILE ISLAND 1 (PHW) • SYSTEM CAPACITY • CORE REFLUDDING SYSTEM • STORAGE CONTAINER • FAILURE, INSTRUMENT • INSTRUMENT CALIBRATION • FLOW BLOCKAGE • TUBING • SENSORS, LEVEL • TEST, SYSTEM OPERABILITY

102605
TWO MANUAL ISOLATION VALVES IN AIR LINE FOUND CLOSED AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., PA.
3 PGS., AU 50-289/75-32 TO NRC DIVISION OF REACTOR LICENSING, SEPT. 26, 1975, JACKET 50-289, TYPE--PHW, HFG--
BGM, AE--GILBERT ASSOC.

CAUSE - PERSONNEL ERROR. WHILE PERFORMING A REACTOR BUILDING PERSONNEL ACCESS HATCH DOOR SEAL LEAK TEST WITH THE REACTOR AT FULL POWER, THE OPERATOR FOUND 2 NORMALLY OPEN VALVES IN THE CLOSED POSITION DURING THE AIR SUPPLY VALVE LINEUP CHECK. THE VALVES WERE IMMEDIATELY OPENED. PROCEDURES WERE APPARENTLY NOT FOLLOWED SINCE THESE VALVES ARE REQUIRED TO BE RE-CLOSED AFTER ANY TEST WHICH WOULD REQUIRE THEIR CLOSURE. LOCKING DEVICES WILL BE INSTALLED ON THESE VALVES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

THREE MILE ISLAND 1 (PHW) • VALVES • PNEUMATIC SYSTEM • FAILURE, OPERATOR ERROR • TEST, SYSTEM OPERABILITY • TESTING • PROCEDURES AND MANUALS

106969
DEFICIENCIES FOUND IN RIP MAP OF DIKES AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., HEADING, PA.
2 PGS., LTR TO NRC DIVISION OF REACTOR LICENSING, SEPT. 29, 1975, JACKET 50-289, TYPE--PHW, HFG--BGM, AE--
GILBERT ASSOC.

CAUSE - INSTALLATION DEFICIENCIES. RESULTS OF ANALYSES PERFORMED ON THE RIP MAP OF DIKES IDENTIFIED SEVERAL DEFICIENCIES. (1) IN SEVERAL AREAS, THE RIP MAP IS THINNER OR SMALLER THAN ORIGINALLY SPECIFIED. ADDITIONAL RIP MAP WILL BE ADDED. (2) A TOE CAN NOT BE VERIFIED IN A 225-FT LONG AREA DUE TO A THICK CLYPERING OF SPOIL MATERIAL. ADDITIONAL TESTS WILL BE MADE AND A TOE WILL BE INSTALLED IF IT IS NOT PRESENT. (3) INSUFFICIENT FILTER BLANKET EXISTS ON AN AREA. ADDITIONAL MATERIAL WILL BE ADDED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

THREE MILE ISLAND 1 (PHW) • FAILURE, INSTALLATION ERROR • EROSION • DRIVER • FLOW • DAMAGE

106617
MAIN STEAM VALVES NOT SEISMIC QUALIFIED AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., PA.
3 PGS., LTR W/PT TO NRC DIVISION OF REACTOR LICENSING, SEPT. 30, 1975, JACKET 50-289, TYPE--PHW, HFG--BGM, AE--
GILBERT ASSOC.

CAUSE - INADEQUATE INTERFACE CONTROL. IT WAS DISCOVERED THAT 2 MAIN STEAM VALVES AND 2 EMERGENCY FLEUWATER VALVES WERE NEVER ANALYZED TO SEISMIC CLASS 1 REQUIREMENTS. WHEN THESE VALVES WERE ORIGINALLY PURCHASED, THE PORTION OF THE MAIN STEAM SYSTEM IN WHICH THESE VALVES WERE LOCATED WERE NOT REQUIRED TO BE SEISMICALLY QUALIFIED. DURING LICENSING, THE SYSTEMS WERE UPGRADED. HOWEVER, THE REQUIREMENT TO UPGRADE THESE 4 VALVES WAS OVERLOOKED. THERE WAS INADEQUATE INTERFACE CONTROL BETWEEN MET-ED, GILBERT ASSOC., AND BGM IN THE AREA OF BALANCE OF PLANT DESIGN. SEISMIC CALCULATIONS CONFIRM THAT THESE 4 VALVES ARE CAPABLE OF WITHSTANDING SEISMIC CLASS 1 LOADING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

100017 CONTINUED

THREE MILE ISLAND 1 (PHN) • DESIGN • VALVES • PRESSURE • CONTAINMENT ISOLATION • COOLING SYSTEM • SECONDARY • FAILURE • ADMINISTRATIVE CONTROL • DESIGN CRITERIA • MODIFICATION

100007

UNPLANNED RELEASE OF RADIOACTIVE MATERIAL AT THREE MILE ISLAND 1

METROPOLITAN EDISON CO., READING, PA.

J PGD, LTR W/RT TO NRC DIRECTOR OF NUCLEAR REACTOR REGULATION, JCT. 7, 1975, DCKET 50-289, TYPE--PHR, MFG--GEN, AE--GILBERT ASSOC.

CAUSE - LIFTING OF RELIEF VALVE. WITH THE REACTOR SUBMITTAL AND COOLING DOWN VIA THE DECAY HEAT REMOVAL OPERATING MODE, AN INADVERTENT RELEASE OF GASEOUS RADIOACTIVE MATERIAL OCCURRED DUE TO THE LIFTING OF A RELIEF VALVE THAT ASSURED BY LEAKAGE OF PRIMARY COOLANT. DEPRESSING OF THE COOLANT RELEASED 0.792 LB. OF PREDOMINANTLY ^{135}Xe TO THE EXHAUST SYSTEM. THE APPARENT CAUSE WAS LEAKAGE PAST A CHECK VALVE CAUSING THE RELIEF VALVE TO LIFT AT ITS DESIGNED RELIEF POINT. THE DECAY HEAT REMOVAL SYSTEM WAS SECURED AND THE RELEASE TERMINATED. THE DEFECTIVE CHECK VALVE WAS REPAIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PHN) • RADIOACTIVE RELEASE • AERIAL • PRESSURE RELIEF • VALVES • OVERVIEW, CHECK • CLEAR • FAILURE, EQUIPMENT • SHUTDOWN COOLING SYSTEM

100900

HYDRAULIC SHOCK SUPPRESSOR FOUND TO BE DISCONNECTED AT THREE MILE ISLAND 1

METROPOLITAN EDISON CO., READING, PA.

J PGD, AU 50-289/75-34 TO NRC DIRECTOR OF REACTOR REGULATION, JCT. 8, 1975, DCKET 50-289, TYPE--PHR, MFG--GEN, AE--GILBERT ASSOC.

CAUSE - INSTALLATION ERROR. DURING AN INSPECTION OF HYDRAULIC SHOCK SUPPRESSORS INSIDE THE SECONDARY SHIELD OF THE REACTOR BUILDING WHILE THE REACTOR WAS IN COLD SHUTDOWN, 1 OF THE 14 SHOCKERS ON THE PRESSURIZER AUXILIARY SPRAY LINE WAS FOUND TO BE DISCONNECTED. THE U.IT WAS IMMEDIATELY REBUILT AND RE-INSTALLED. IT HAD BEEN REMOVED FOR REPAIR IN MAY AND APPARENTLY WAS NOT PROPERLY CORRECTED DURING RE-INSTALLATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PHN) • OSCILLATION • SUPPORT STRUCTURE • PIPES AND PIPE FITTINGS • SURVEILLANCE PROGRAM • FAILURE, INSTALLATION ERROR • MAINTENANCE AND REPAIR

107607

COALIT CONCENTRATION IN SAMPLER EXCEEDS CONTROL LEVEL AT THREE MILE ISLAND 1

METROPOLITAN EDISON CO., READING, PA.

J PGD, EN 75-02 TO NRC OFFICE OF I & E REG. I, JCT. 17, 1975, DCKET 50-289, TYPE--PHR, MFG--GEN, AE--GILBERT ASSOC.

CAUSE - LOW RIVER FLOW. THE CONCENTRATION OF CO-60 IN THE SEMI-ANNUAL RIVER BOTTOM SEDIMENT SAMPLES EXCEEDED 10 TIMES THE CONTROL STATION VALUE. THE CONTROL VALUE WAS LESS THAN 0.20 PLU/GRAM. SAMPLE VALUES WERE 0.97 AND 3.34 PLU/GRAM RESPECTIVELY. DURING JULY SAMPLING THERE WAS UNUSUALLY LOW RIVER FLOW RATES CAUSING SEDIMENTATION RATES TO INCREASE SIGNIFICANTLY DURING WASTE DISCHARGES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PHN) • POLLUTANT • SEDIMENT • RIVER • MONITORING PROGRAM, ENVIRONMENTAL • WASTE DISPOSAL, LIQUID • WASTE DISPOSAL

107600

BORIC ACID MIX TANK OUTLET LINE BLOCKED AT THREE MILE ISLAND 1

METROPOLITAN EDISON CO., READING, PA.

J PGD, AU 50-289/75-35 TO NRC DIRECTOR OF REACTOR REGULATION, JCT. 20, 1975, DCKET 50-289, TYPE--PHR, MFG--GEN, AE--GILBERT ASSOC.

CAUSE - MIXER FAILURE. DURING AN ATTEMPT TO TRANSFER BORIC ACID FROM THE BORIC ACID MIX TANK TO RECLAIMED BORIC ACID STORAGE TANK A, WHILE OPERATING AT 1038 PMW, THE MIX TANK OUTLET LINE WAS FOUND TO BE BLOCKED. THE TANK MIXER PROPELLER WAS DISCONNECTED FROM THE MOTOR SHAFT. THE LINE WAS IMMEDIATELY CLEARED OF THE BLOCKAGE. DURING A PREVIOUS ADDITION, BORIC ACID CRYSTALS DID NOT MIX PROPERLY DUE TO MIXER FAILURE. PROCEDURES DID NOT INSURE PROPER MIXING PRIOR TO ADDING BORIC ACID CRYSTALS. THE CRYSTALS SETTLED TO THE BOTTOM AND BLOCKED THE PIPE. THE MIXER WILL BE MODIFIED AND PROCEDURES REVISED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PHN) • STORAGE CONTAINER • CHEMICAL SHIP • PIPES AND PIPE FITTINGS • FLOW BLOCKAGE • FAILURE, EQUIPMENT • PLUM, MIXING

107525
TRITIUM LEVEL IN EFFLUENT EXCEEDS CONTROL VALUE AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., READING, PA.
3 PGS. RM 75-03 TO NRC OFFICE OF I & E, REGION 1, OCT. 26, 1975, DOCKET 50-289, TYPE--PWR, MFG--BGM, AE--
GILBERT ASSOC.

CAUSE - LOW RIVER FLOW. MONTHLY COMPOSITES OF WEEKLY GRAB SAMPLES COLLECTED DOWNSTREAM FROM THE
DISCHARGE SHOWED TRITIUM CONCENTRATIONS OF 2900 PC/L AND 2720 PC/L AS COMPARED WITH THE CONTROL
STATION VALUE OF 250 PC/L. LOW RIVER FLOW RATES ARE BELIEVED TO HAVE REDUCED NORMAL MIXING OF
EFFLUENTS. THESE CONCENTRATIONS DID NOT EXCEED LIMITS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • CONCENTRATION • TRITIUM • EFFLUENT • RIVER • MONITORING PROGRAM, ENVIRONMENTAL •
FLOW

107693
OPERATOR FAILS TO CARRY MONITOR INTO HIGH RADIATION AREA AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., READING, PA.
1 PGS. AU 50-289/75-36 TO NRC DIVISION OF REACTOR LICENSING, OCT. 29, 1975, DOCKET 50-289, TYPE--PWR, MFG--BGM,
AE--GILBERT ASSOC.

CAUSE - PROCEDURES NOT FOLLOWED. AN AUXILIARY OPERATOR WAS ORDERED TO ISOLATE, VENT, AND DRAIN
THE MAKEUP AND PURIFICATION SYSTEM'S PREFILTER FOR FILTER REPLACEMENT. A RADIATION WORK PERMIT
HAD BEEN ISSUED. HE FAILED TO PROPERLY CHECK OUT THE PERMIT AND ENTERED THE AREA WITHOUT AN
INDICATING METER. HIS TLD READING WAS 1260 PLUS OR MINUS 126 MREM WHEN HE COMPLETED THE JOB. HE
HAD FAILED TO FOLLOW PROPER PROCEDURES FOR THE JOB. PROCEDURES HAVE BEEN MODIFIED FOR ENTRY INTO
AREAS GREATER THAN 1000 MR/HR. EQUIPMENT MODIFICATIONS ARE BEING STUDIED TO REDUCE PERSONNEL
EXPOSURE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • PERSONNEL EXPOSURE, RADIATION • MAINTENANCE AND REPAIR • FAILURE, OPERATOR ERROR •
PROCEDURES AND MANUALS • FILTERS • COOLANT PURIFICATION SYSTEM

107692
SOURCE OF CONCENTRATED BORIC ACID SOLUTION NOT OPERABLE AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., READING, PA.
2 PGS. AU 50-289/75-37 TO NRC DIRECTOR OF NUCLEAR REACTOR REGULATION, OCT. 31, 1975, DOCKET 50-289, TYPE--PWR,
MFG--BGM, AE--GILBERT ASSOC.

CAUSE - PLUGGED FILTER. WHILE FILLING A RECLAIMED BORIC ACID STORAGE TANK FROM THE BORIC ACID MIX
TANK WITH THE REACTOR AT 21% POWER, FLOW RATE WAS OBSERVED TO BE DECREASING. THE STRAINER ON THE
MIX TANK OUTLET WAS PARTIALLY OBSTRUCTED BY FINES. THE OBSTRUCTED STRAINER WAS REMOVED AND
REPLACED WITH A NEW STRAINER. A NORMAL SHUTDOWN WAS INITIATED DURING THE 17 MINUTES REQUIRED.
THEN THE PLANT WAS RETURNED TO 81% POWER. ONLY ONE STRAINER WITH NO BYPASS WAS PROVIDED.
PROCEDURES DID NOT PROVIDE FOR PERIODIC REPLACEMENT OF THE STRAINER. A DUAL STRAINER ARRANGEMENT
WILL BE INSTALLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • OPERATOR, SOLUBLE • CHEMICAL SHIM • SYSTEM CAPABILITY • FAILURE, DESIGN ERROR •
FILTERS • REQUINANCE • MODIFICATION

107691
CONTROL ROD PROGRAM VERIFICATION INADEQUATELY IMPLEMENTED AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., READING, PA.
3 PGS. AU 50-289/75-38 TO NRC DIRECTOR OF NUCLEAR REACTOR REGULATION OCT. 31, 1975, DOCKET 50-289, TYPE--PWR,
MFG--BGM, AE--GILBERT ASSOC.

CAUSE - MISINTERPRETATION OF PROCEDURES. DURING A PLANT OPERATION REVIEW COMMITTEE REVIEW OF THE
CONTROL ROD PROGRAM VERIFICATION, IT WAS FOUND THAT EACH ROD IN A GROUP HAD NOT BEEN MOVED
SEPARATELY AS REQUIRED. THE GROUP HAD BEEN MOVED. PERSONNEL INVOLVED IN THE TEST HAD
MISINTERPRETED THE PROCEDURE. PROCEDURES WILL BE REVISED TO CLEARLY STATE INDIVIDUAL ROD
MOVEMENT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • TESTING • CONTROL ROD DRIVE MECHANISMS • PLANTING AIDS • FAILURE, OPERATOR ERROR •
PROCEDURES AND MANUALS

108236
CONCENTRATION OF TRITIUM IN RIVER WATER EXCEEDS LIMIT AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., READING, PA.

100236 POLLUTING
3 PGS. LTR W/EN 75-09 TO NRC OFFICE OF I & E, REGION I, NOV. 20, 1975, DCKET 50-289, TYPE--PWR, WFG--DEN, AE--GILBERT ASSOC.

CAUSE - WASTE DISPOSAL. ANALYSIS OF THE SEPTEMBER MONTHLY COMPOSITE OF WEEKLY GRAB SAMPLES OF SURFACE RIVER WATER COLLECTED 0.5 MILE DOWNSTREAM OF THE PLANT DISCHARGE INDICATED THAT THE IODINE CONCENTRATION WAS GREATER THAN 4 TIMES THE CONTROL STATION VALUE. IT IS BELIEVED THAT GRAB SAMPLES WERE TAKEN DURING PERIODS OF EVAPORATOR CONDENSATE TANK DISCHARGE AND, ACCORDINGLY, DURING PERIODS OF HIGHER-THAN-NORMAL RIVER WATER IODINE LEVEL.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • CONCENTRATION • EFFLUENT • IODINE • WASTE DISPOSAL • RIVER • SURFACE WATER • RADIOACTIVITY RELEASE

100239
TEMPERATURE DIFFERENTIAL ACROSS THE PLANT EXCEEDS LIMIT AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., READING, PA.
3 PGS. LTR W/EN 75-09 TO NRC OFFICE OF I & E, REGION I, NOV. 20, 1975, DCKET 50-289, TYPE--PWR, WFG--DEN, AE--GILBERT ASSOC.

CAUSE - NOT CLOSELY MONITORED. DURING COOLDOWN OF THE REACTOR COOLANT SYSTEM, THE DECAY HEAT REMOVAL SYSTEM WAS PLACED INTO OPERATION. THE ADDITIONAL HEAT LOAD CAUSED THE EFFLUENT TEMPERATURE TO RISE FROM 52 F TO 57 F IN 3.5 HOUR. THE OPERATOR THEN STARTED AN EXTRA MECHANICAL GRAFT COOLING TOWER FAN. THE EFFLUENT TEMPERATURE CHANGE OVER A ONE HOUR PERIOD WAS 3 F/HOUR WHICH EXCEEDS THE ETS LIMIT 0.2 F/HOUR. THE OPERATOR FAILED TO CLOSELY MONITOR THE TEMPERATURE CHANGE WHEN PLACING THE PLANT IN DECAY HEAT MODE OF OPERATION. ADEQUATE GUIDANCE MAY NOT BE PROPERLY INTEGRATED INTO THE PROCEDURE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • TEMPERATURE GRADIENT • THERMAL TRANSIENT • EFFLUENT • SHUTDOWN COOLING SYSTEM • RIVER • FAILURE • OPERATOR ERROR

100237
CONCENTRATIONS IN MONTHLY EFFLUENT SAMPLE EXCEED LIMIT AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., READING, PA.
4 PGS. LTR W/EN 75-09 TO NRC OFFICE OF I & E, REGION I, NOV. 21, 1975, DCKET 50-289, TYPE--PWR, WFG--DEN, AE--GILBERT ASSOC.

CAUSE - LOW RIVER WATER FLOW. ANALYSIS OF THE AUGUST MONTHLY COMPOSITE OF WEEKLY GRAB SAMPLES OF SURFACE RIVER WATER COLLECTED 0.5 MILE DOWNSTREAM OF THE PLANT DISCHARGE INDICATED THAT CO-60 AND I-131 CONCENTRATIONS WERE GREATER THAN 4 TIMES THE MINIMUM DETECTABLE LEVEL. IT IS BELIEVED THAT THE GRAB SAMPLES WERE TAKEN DURING PERIODS OF ABNORMALLY LOW RIVER WATER FLOW. THE HEALTH AND SAFETY OF THE PUBLIC WAS NOT THREATENED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • RADIOACTIVITY RELEASE • CONCENTRATION • EFFLUENT • WASTE DISPOSAL • RIVER • IODINE • COBALT • SURFACE WATER

100240
UNPLANNED RELEASE OF RADIOACTIVE MATERIAL AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., READING, PA.
3 PGS. LTR W/EN 75-09 TO NRC DIRECTOR OF NUCLEAR REACTOR REGULATION, NOV. 21, 1975, DCKET 50-289, TYPE--PWR, WFG--DEN, AE--GILBERT ASSOC.

CAUSE - LACK OF PROCEDURAL GUIDANCE. WHILE DRAINING THE REACTOR COOLANT SYSTEM FROM THE PRESSURIZER SURGE LINE TO REACTOR COOLANT BLEED TANK C, PRESSURE IN THE TANK INCREASED AND PARTIALLY EVACUATED THE SEAL RELEASING RADIOACTIVE GAS TO ATMOSPHERE THROUGH THE VENTILATION SYSTEM. PRESSURE INCREASED BECAUSE THE 260 F COOLANT BEING BLED INTO THE TANK FLASHED INTO STEAM. PROCEDURES DID NOT COVER DRAINING ABOVE 150 F. THEY WILL BE MODIFIED TO PERMIT DRAINING ONLY WHEN TEMPERATURES ARE LESS THAN 150 F. THE TOTAL RELEASE WAS CALCULATED TO BE 6.00 CI, PRIMARILY Xe-135.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • PATRONS RELEASE • XENON • MAIN COOLING SYSTEM • FAILURE, ADMINISTRATIVE CONTROL • PROCEDURES AND MANUALS

100254
CONTROL ROOMS INOPERABLE AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., READING, PA.
3 PGS. AU 50-289/75-39 TO NRC DIRECTOR OF NUCLEAR REACTOR REGULATION, NOV. 21, 1975, DCKET 50-289, TYPE--PWR, WFG--DEN, AE--GILBERT ASSOC.

100254 CONTINUED

CAUSE - FAILED STATOR WINDING. DURING 100% POWER OPERATION, CONTROL ROD 4 IN GROUP 7 DROPPED INTO THE CORE FROM ITS WITHDRAWN POSITION. DURING THE RESULTING HAMBACK, GROUP 7 ROD 5 BECAME MISALIGNED BY MORE THAN THE ALLOWABLE 1/8 INCHES AND WAS THUS DECLARED INOPERABLE. THE REACTOR WAS SHUT DOWN AND WAS OFF LINE 1 HOUR 20 MINUTES AFTER ROD 4 DROPPED. THE DROPPED ROD RESULTED FROM A FAILED STATOR WINDING. THE UPPER O-RING, THAT SEALS THE STATOR ASSEMBLY TO THE DRIVE MOTOR TUBE WAS MISSING. THIS MAY HAVE ALLOWED MOISTURE TO ENTER THE STATOR CAVITY RESULTING IN I.E. FAILURE. THE FAILED WINDING WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) + CONTINUAL ROD DRIVE MECHANISMS + MOTORS + REACTOR SHUTDOWN + FAILURE, MAINTENANCE + SEAL

100201

VOLTAGE RELAY CONTACTS OF DIESEL GENERATOR STICK AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., READING, PA.

3 PGS. LTR W/NOIRUPT TO NRC DIRECTOR OF NUCLEAR REACTOR REGULATION, NOV. 21, 1975, DOCKET 50-289, TYPE--PWR, NRC--BEN, AE--GILBERT ASSOC.

CAUSE - PITTING JUNE 14 PREVENT OPERATION. WHILE OPERATING AT 100% POWER, THE 3 UP-TO-VOLTAGE RELAYS ON DIESEL GENERATOR 1A WERE FOUND TO HAVE STUCK CONTACTS. THIS COULD HAVE CAUSED PREMATURE CLOSURE OF THE BREAKER. THE VOLTAGE RELAY CONTACT PITS SLIGHTLY DUE TO FREQUENT OPERATION. THE STUCK RELAYS WERE MANUALLY RESET IMMEDIATELY. A DESIGN CHANGE WILL BE SUBMITTED TO PERMANENTLY SOLVE THIS PROBLEM. RELAYS WILL BE CHECKED AFTER EACH OPERATION UNTIL CHANGE IS MADE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) + RELAYS + GENERATOR, DIESEL + ENGINES, INTERNAL COMBUSTION + FAILURE, DESIGN ERROR + ELECTRIC ARC + FAILURE, CORPUS MODE + EMERGENCY POWER, ELECTRIC + MAINTENANCE AND REPAIR

100201

UNPLANNED RELEASE OF RADIOACTIVE GAS AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., READING, PA.

3 PGS. LTR W/NOIRUPT TO NRC DIVISION OF REACTOR LICENSING, NOV. 24, 1975, DOCKET 50-289, TYPE--PWR, NRC--BEN, AE--GILBERT ASSOC.

CAUSE - FAILURE TO FOLLOW PROCEDURES. WHEN A SMALL INCREASE IN THE RADIATION LEVEL ON THE REACTOR BUILDING PURGE RADIATION MONITOR WAS OBSERVED, A THOROUGH CHECK OF THE REACTOR BUILDING FOUND THAT THE CENTER CONTROL ROD DRIVE MECHANISM WAS VENTED TO THE BUILDING PERMITTING RADIOACTIVE GAS TO EVOLVE FROM THE REACTOR COOLANT SYSTEM TO THE REACTOR BUILDING. THE OPERATOR INVOLVED IN THE VENTING OPERATION IMPLIED THAT VENTING TO THE BUILDING WOULD ACCOMPLISH THE SAME OBJECTIVES AS VENTING TO THE REACTOR COOLANT DRAIN TANK AS SPECIFIED BY PROCEDURES. THE REACTOR WAS IN COLD SHUTDOWN AT THE TIME. ABOUT 3.90 CI, PRIMARILY Xe-133, WERE RELEASED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) + RADIOACTIVE RELEASE + XENON + MAIN COOLING SYSTEM + FAILURE, OPERATOR ERROR + PROCEDURES AND MANUALS

100235

BOLTS USED PRIOR TO CHECKING QC DOCUMENTATION AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., READING, PA.

1 PG. LTR W/NOIRUPT TO NRC DIRECTOR OF NUCLEAR REACTOR REGULATION, NOV. 26, 1975, DOCKET 50-289, TYPE--PWR, NRC--BEN, AE--GILBERT ASSOC.

CAUSE - BREAKDOWN IN ADMINISTRATIVE CONTROL. DURING THE OCTOBER OUTAGE WHILE BALANCING THE REACTOR COOLANT PUMPS, LONGER PUMP/MOTOR COUPLING BOLTS WERE INSTALLED IN ORDER TO ADD ADDITIONAL BALANCING WEIGHTS. THE PUMPS WERE DECLARED OPERABLE BEFORE IT HAD BEEN DETERMINED IF THE VENDOR QC DOCUMENTATION WAS ADEQUATE. THIS CONSTITUTES AN ADMINISTRATIVE CONTROL BREAKDOWN BUT NOT A VIOLATION OF TECH SPECS. THE DOCUMENTATION WAS ADEQUATE. PREVENTATIVE MEASURES WILL BE TAKEN TO PREVENT RECURRENCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) + QUALITY ASSURANCE + FASTENER + PUMPS + MAIN COOLING SYSTEM + FAILURE, ADMINISTRATIVE CONTROL

100239

TWO UNPLANNED RELEASES OF RADIOACTIVE MATERIAL AT THREE MILE ISLAND 1
METROPOLITAN EDISON CO., READING, PA.

3 PGS. LTR W/NOIRUPT TO NRC DIRECTOR OF NUCLEAR REACTOR REGULATION, NOV. 26, 1975, DOCKET 50-289, TYPE--PWR, NRC--BEN, AE--GILBERT ASSOC.

109234 - CONTINUED

CAUSE - PROCEDURE INADEQUATE. WHILE PERFORMING THE DRAIN THROUGH STEAM GENERATOR NET AND DRY LAYOUT PROCEDURE, 2 HEATER COOLANT DRAIN TANK VALVES WERE OPEN TO VENT TO THE SECONDARY SIDE OF THE STEAM GENERATORS. AT THE TIME, THE STEAM GENERATORS WERE IN A VACUUM CONDITION. RADIOACTIVE GAS WAS RELEASED VIA THE MAIN CONDENSER VACUUM PUMP. PROCEDURES DID NOT SPECIFY NO VENTING UNDER VACUUM CONDITIONS. A SECOND RELEASE OCCURRED DURING PLANT HEATUP WHEN RADIOACTIVE GAS CAME OUT OF THE SOLUTION AND WAS RELEASED THROUGH THE VACUUM PUMP VENT WHEN THE STEAM GENERATOR WAS HEATED TO F. TOTAL RELEASE WAS 2.70 CI. (1978 X-133).

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 139 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) + PARACHUTE RELEASE + XENON + STEAM GENERATOR + FAILURE, ADMINISTRATIVE CONTROL + PROCEDURES AND MANUALS

109240

UNPLANNED RELEASE OF RADIOACTIVE MATERIAL OCCURS AT THREE MILE ISLAND 1

METROPOLITAN EDISON CO., READING, PA.

3 PGS. LTR W/ADJ 50-289/75-10 TO NRC DIRECTOR OF NUCLEAR REACTOR REGULATION, DEC. 5, 1975, DOCKET 50-289, TYPE--PWR, MFG--BGM, AE--GILBERT ASSOC.

CAUSE - PERSONNEL ERROR. DURING A 41 MINUTE PERIOD, 830 GALLONS OF REACTOR COOLANT OVERFLOUED REACTOR COOLANT BLEED TANK B INTO THE AUXILIARY BUILDING SUMP. THE OPERATOR CONFUSED THE LEVEL INDICATION OF TANK B, WHICH WAS FULL, AND TANK C, WHICH WAS NEARLY EMPTY. WHEN PERSONNEL NOTED AN INCREASE IN THE AUXILIARY BUILDING SUMP LEVEL, LETDOWN TO TANK B WAS TERMINATED STOPPING THE RELEASE. TOTAL RELEASE THROUGH THE AUXILIARY BUILDING VENTILATION SYSTEM WAS 0.110 CI OF PREDOMINANTLY XE-133. NO RELEASE LIMITS WERE EXCEEDED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 138 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) + PARACHUTE RELEASE + REACTOR COOLANT + FAILURE, OPERATOR ERROR + COOLANT PURIFICATION SYSTEM + STORAGE CONTAINER + SYSTEM CAPACITY + XENON

109284

UNPLANNED RELEASE OF GASEOUS RADIOACTIVITY AT THREE MILE ISLAND 1

METROPOLITAN EDISON CO., READING, PA.

3 PGS. LTR W/ADJ 50-289/75-10 TO NRC DIRECTOR OF NUCLEAR REACTOR REGULATION, DEC. 16, 1975, DOCKET 50-289, TYPE--PWR, MFG--BGM, AE--GILBERT ASSOC.

CAUSE - UNKNOWN. DURING A 2 HOUR PERIOD, AN INADVERTANT RELEASE OF RADIOACTIVE MATERIAL OCCURRED WHILE WATER WAS BEING ADDED TO THE REACTOR COOLANT SYSTEM MAKEUP TANK FROM BLEED TANK A. THIS ADDITION CAUSED THE RELEASE THROUGH EITHER THE MAKEUP TANK MANWAY GASKET OR FROM A VALVE ISOLATING THE MAKEUP TANK FROM THE VENT HEADER. NO APPARENT CAUSE HAS BEEN DEFINITELY IDENTIFIED. SAMPLING IS CONTINUING TO IDENTIFY ANY LEAKS. THE TOTAL RELEASE WAS 0.262 CI OF PREDOMINANTLY XE-133.

AVAILABILITY - CAUSE - UNKNOWN. DURING A 2 HOUR PERIOD, AN INADVERTANT RELEASE OF RADIOACTIVE MATERIAL OCCURRED WHILE WATER

THREE MILE ISLAND 1 (PWR) + XENON + LEAK + PARACHUTE RELEASE

109876

STEAM GENERATOR SAMPLE LINE VALVE FOUND INOPERABLE AT THREE MILE ISLAND 1

METROPOLITAN EDISON CO., READING, PA.

4 PGS. LTR W/ADJ 50-289/75-42 TO NRC DIRECTOR OF NUCLEAR REACTOR REGULATION, DEC. 19, 1975, DOCKET 50-289, TYPE--PWR, MFG--BGM, AE--GILBERT ASSOC.

CAUSE - MANUAL OPERATOR IMPROPERLY POSITIONED. WHILE TESTING THE ISOLATION SYSTEM LOGIC WITH THE REACTOR AT 100% POWER, THE OUTSIDE CONTAINMENT ISOLATION VALVE FOR THE STEAM GENERATOR SAMPLE LINE FAILED TO CLOSE. AN OPERATOR INADVERTENTLY LEFT THE VALVE MANUAL OPERATOR IN THE OPEN POSITION RATHER THAN THE NEUTRAL POSITION, THUS PREVENTING THE VALVE FROM AUTOMATICALLY CLOSING. THIS ALSO CAUSED TEMPORARY JAMMING OF THE VALVE. THE OPERATOR WAS PLACED IN THE NEUTRAL POSITION AND THE VALVE CYCLED SEVERAL TIMES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 138 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) + VALVES + CONTAINMENT ISOLATION + TEST, SYSTEM OPERABILITY + STEAM GENERATOR + SAMPLING + FAILURE, OPERATOR ERROR + VALVE OPERATORS

109235

SET POINT DRIFT IN PRESSURE SWITCH AT THREE MILE ISLAND 1

METROPOLITAN EDISON CO., READING, PA.

3 PGS. LTR W/ADJ 50-289/75-43 TO NRC DIRECTOR OF NUCLEAR REACTOR REGULATION, DEC. 26, 1975, DOCKET 50-289, TYPE--PWR, MFG--BGM, AE--GILBERT ASSOC.

CAUSE - INSTRUMENT DRIFT. WHILE CONDUCTING REFUELING REACTOR BUILDING 30 PSIG CHANNEL TESTS, 1 OF THE 6 PRESSURE SWITCHES WAS FOUND TO BE OUT OF LIMITS. THE SQUARE O CU PRESSURE SWITCH, TYPE

104205 CONTINUED

9013-AMG. FORM A WAS Miscalibrated. THE LAST CALIBRATION WAS ON JAN. 15, 1974. THE CAUSE WAS SLIGHT INSTRUMENT DRIFT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 1 (PWR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SENSORS, PRESSURE • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT • RESET POINT • PURGE • REFUELING • PLANT PROTECTIVE SYSTEM • CONTAINMENT

093400

CONTROL ROD DRIVE SYSTEM AC BREAKER CABINETS DEFICIENCY AT THREE MILE ISLAND 2
METROPOLITAN EDISON COMPANY, PENNSYLVANIA

2 PAGES, LETTER TO DIRECTORATE OF REGULATORY OPERATIONS, AEC, JANUARY 15, 1975, DOCKET 50-320, TYPE--PWR, MFG--BOM, AE--BURNS & ROE

CAUSE - DESIGN ERROR. A REVIEW BY THE VENDOR INDICATED THAT THE DESIGN OF THE STRUCTURAL ATTACHMENT OF THE CONTROL ROD DRIVE AC BREAKER CABINETS TO THE FLOOR IS INADEQUATE TO WITHSTAND THE SAFE SHUTDOWN EARTHQUAKE ACCELERATION LEVELS. MODIFICATIONS TO INCREASE THE ATTACHMENT STRENGTH WILL BE ACCOMPLISHED BEFORE THE CABINETS ARE INSTALLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTROL ROD SCRAM MECHANISM • FAILURE, DESIGN ERROR • CONTROL PANEL/ROOM • THREE MILE ISLAND 2 (PWR) • BACKFIT • SEISMIC DESIGN • CONSTRUCTION

100420

LOW CONCRETE CYLINDER TEST STRENGTHS (SUPPLEMENT) AT THREE MILE ISLAND 2
METROPOLITAN EDISON COMPANY, PA.

3 PAGES, LETTER TO AEC DIRECTORATE OF REGULATORY OPERATIONS, JANUARY 31, 1975, DOCKET 50-320, TYPE--PWR, MFG--BOM, AE--BURNS & ROE

CAUSE - CYLINDERS MISHANDLED. REPORT DATED OCT. 20, 1974, ERRONEOUSLY REPORTED THAT 4 OF 6 SETS OF TEST CYLINDERS WERE BELOW 20 DAY STANDARD STRENGTH. IN FACT, 4 OF 43 SETS WERE BELOW STANDARD. THE 90-DAY TEST RESULTS SHOWED THAT 4 OF THE 6 WERE SATISFACTORY. THE REMAINING 2 DID NOT REACH THE 5000 PSI REQUIREMENTS. IN BOTH CASES ANOTHER SET OF CYLINDERS FROM THE SAME THUNDERBOLT EXCEEDED THE LIMIT. SWISS HAMMER TESTS PERFORMED ON THIS CONCRETE IN SITU INDICATE COMPRESSIVE STRENGTHS IN THE 5000 PSI RANGE. IT IS BELIEVED THAT THE TEST CYLINDERS HAD BEEN MISHANDLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONCRETE • TESTING • SAMPLING • PROPERTY, PHYSICAL • FAILURE, INSTALLATION ERROR • THREE MILE ISLAND 2 (PWR) • CONSTRUCTION

102614

REACTOR BUILDING SPRAY PUMP MOTOR MODIFICATIONS AT THREE MILE ISLAND 2
METROPOLITAN EDISON COMPANY, PA.

8 PAGES, LETTER WITH ATTACHMENT TO NRC OFFICE OF INSPECTION & ENFORCEMENT, APRIL 21, 1975, DOCKET 50-320, TYPE--PWR, MFG--BOM, AE--BURNS & ROE

CAUSE - DESIGN DEFICIENCY. REACTOR BUILDING SPRAY PUMP MOTORS WOULD NOT ACCELERATE UNDER A LOW VOLTAGE CONDITION (ABOUT 70%). THE MOTORS WERE RETURNED TO THE VENDOR. THEY WERE REPAIRED WITH LARGER END RINGS AND THE USE OF A DIFFERENT ALLOY FOR THE END RINGS. DYNAMOMETER TESTS DEMONSTRATED THAT THE REPAIRED MOTOR WOULD ACCELERATE TO FULL SPEED IN LESS THAN 6 SECONDS AT REDUCED VOLTAGE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 2 (PWR) • CONSTRUCTION • PROVISIONS • CONTAINMENT SPRAY • MODIFICATION • FAILURE, DESIGN ERROR

103005

ADDITIONAL INFORMATION ON DEFECTIVE CRANE VALVES AT THREE MILE ISLAND 2
METROPOLITAN EDISON COMPANY, PA.

2 PAGES, LETTER TO NRC OFFICE OF INSPECTION & ENFORCEMENT, MAY 9, 1975, DOCKET 50-320, TYPE--PWR, MFG--BOM, AE--BURNS & ROE

CAUSE - BLOW HOLES. WHILE INSTALLING SMALL BORE (2 INCHES AND SMALLER) CAST STAINLESS STEEL SOCKET WELD END GLOBE AND CHECK VALVES SUPPLIED BY CRANE CO., BLOW HOLES WERE FOUND IN 2 VALVES AS REPORTED EARLIER. ACCEPTABILITY OF VALVES IS BASED ON A VISUAL INSPECTION PRIOR TO INSTALLATION AND HYDROSTATIC TEST SUBSEQUENT TO INSTALLATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 2 (PWR) • CONSTRUCTION • VALVES • VALVE, CHECK • FLAW • TEST, NONDESTRUCTIVE • FAILURE,

106005 (CONTINUED)
FABRICATION ERROR

106076
LINEAR AXIAL INDICATION FOUND IN RC PUMP NUTS AND STUDS AT THREE MILE ISLAND 2
METROPOLITAN EDISON COMPANY, READING, PA.
2 PGS. LHM W/ATTN TO NRC OFFICE OF I & E, JULY 24, 1975, DOCKET 50-320, TYPE--PHR, MFG--BEM, AE--BURNS & ROE

CAUSE - NON-METALLIC INCLUSIONS. DURING BASELINE IN-SERVICE INSPECTION OF THE REACTOR COOLANT PUMP STUDS AND NUTS, 14 NUTS AND 29 STUDS SHOWED LINEAR AXIAL INDICATIONS GREATER THAN 1 INCH IN LENGTH. THE INDICATIONS ARE TYPICAL OF NON-METALLIC INCLUSIONS AND, THEREFORE, MAY NOT BE REJECTABLE. ENGINEERING JUSTIFICATION FOR USE OR REJECTION WILL BE MADE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 2 (PHR) • CONSTRUCTION • FASTENER • PUMPS • MAIN COOLING SYSTEM • PLAN • TEST, MAINTENANCE • INSERVICE INSPECTION

106087
REACTOR BUILDING CABLE TRAY PAINTING FOUND DEFICIENT AT THREE MILE ISLAND 2
METROPOLITAN EDISON CO., PA.
2 PGS. LHM W/ATTN TO NRC OFFICE OF I & E, AUG. 26, 1975, DOCKET 50-320, TYPE--PHR, MFG--BEM, AE--BURNS & ROE

CAUSE - IMPROPER SURFACE PREPARATION. A VISUAL EXAMINATION OF SOME REACTOR BUILDING CABLE TRAYS FOUND 75% OF THE TRAYS EXHIBITED MECHANICAL DAMAGE AND POOR PAINT ADHESION. THE VENDOR HAD CHEMICALLY PREPARED THE SURFACE FOR PAINTING INSTEAD OF GRIT BLASTING THE SURFACE TO WHITE METAL, AS REQUIRED BY THE PAINT VENDOR'S BULLETIN. ABOUT 1200 LINEAR FEET OF TRAY HAD BEEN INSTALLED. THE TRAY WAS REMOVED AND REQUOTED TO COMPLY WITH REQUIREMENTS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 2 (PHR) • CONSTRUCTION • SURFACE, PAINTED • SUPPORT STRUCTURE • CABLES AND CONNECTORS • FAILURE, FABRICATION ERROR • PLAN • SURFACE TREATMENT

106085
INTERIOR CONCRETE BLOCK WALLS NOT SEISMICALLY QUALIFIED AT THREE MILE ISLAND 2
METROPOLITAN EDISON CO., PA.
2 PGS. LHM W/ATTN TO NRC OFFICE OF I & E, AUG. 28, 1975, DOCKET 50-320, TYPE--PHR, MFG--BEM, AE--BURNS & ROE

CAUSE - DESIGN DEFICIENCY. DURING A ROUTINE INSPECTION OF THE CONTROL BUILDING, A VERTICAL MECHANICAL AND ELECTRIC CHASE CONTAINING ELECTRICAL SAFETY RELATED CIRCUITS WAS BOUNDED BY MULLION BLOCK WALLS THAT COULD NOT BE SEISMICALLY QUALIFIED. THESE CONCRETE BLOCK WALLS HAVE BEEN REMOVED AND ARE BEING REPLACED WITH STRUCTURAL STEEL AND A U-DECK TYPE OF PANELING.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 2 (PHR) • CONSTRUCTION • SEPARATOR • STRUCTURE • SEISMIC DESIGN • FAILURE, DESIGN ERROR • CONTROL • PIPING • CABLES AND CONNECTORS

106089
VOID FILLING IN FUEL HANDLING BUILDING WALL AT THREE MILE ISLAND 2
METROPOLITAN EDISON CO., READING, PA.
2 PGS. LHM W/ATTN TO NRC OFFICE OF I & E, NOV. 14, 1975, DOCKET 50-320, TYPE--PHR, MFG--BEM, AE--BURNS & ROE

CAUSE - CONSTRUCTION ERROR. WHILE PREPARING THE SOUTH EXTERIOR WALL OF THE FUEL HANDLING BUILDING FOR CONCRETE PLACEMENT OF THE FUEL TRANSFER TUBE SHIELD WALLS, A VOID WAS FOUND ABOVE THE TUBE. IT WAS ABOUT 3 INCHES HIGH BY 6 FEET WIDE AND VARIES FROM 3 TO 5 FEET DEEP. THIS LOCATION HAD INITIALLY BEEN A BLOCKOUT FOR THE TUBE INSTALLATION. WHEN CONCRETE WAS SUBSEQUENTLY PLACED IN THE BLOCKOUT, THE INNER TOP SECTION FAILED TO FILL COMPLETELY, LEAVING THE VOID. THE VOID WILL BE REPAIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 2 (PHR) • PLAN • CONCRETE • VOID • BUILDING • FUEL HANDLING • FAILURE, INSTALLATION ERROR • CONSTRUCTION

106269
CABLE ROUTING AND PULLING DEFICIENCY AT THREE MILE ISLAND 2
METROPOLITAN EDISON CO., READING, PA.
2 PGS. LHM W/ATTN TO NRC OFFICE OF I & E, DEC. 19, 1975, DOCKET 50-320, TYPE--PHR, MFG--BEM, AE--BURNS & ROE

CAUSE - LACK OF COMMUNICATION. A DEVIATION REPORT WAS ISSUED DUE TO THE FACT THAT A CONDUIT WAS NOT ROUTED THROUGH A PULL BOX AS INDICATED ON THE DRAWING AND PULL SLIP. CONSTRUCTION HAD

109209 PLONTINUED

ELECTED TO INSTALL THE CONDUIT THROUGH AN UNNUMBERED PULL SLEEVE. A RELEASE FOR PULLING WAS APPROVED BY GA BUT THE A/E WOULD NOT SIGN IT. THE CABLE PULLING SUPERVISOR WAS NOT INFORMED AND SCHEDULED THE PULL AN URGENT. JC INSPECTORS WERE NOT NOTIFIED AND DID NOT MONITOR THE PULL. CONSTRUCTION WORKERS WERE INSTRUCTED TO REMOVE ALL HOLD TAGS AND NOT ASSUME A RELEASE HAS BEEN PROCESSED. BETTER COMMUNICATION METHODS BETWEEN CONSTRUCTION AND JC PERSONNEL HAVE BEEN DEVELOPED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

THREE MILE ISLAND 2 (PWR) • CONSTRUCTION • CABLES AND CONNECTORS • QUALITY ASSURANCE • FAILURE, INSTALLATION ERROR • COMMUNICATION

106366

REACTOR COOLANT SYSTEM UNPRESSURIZED UNINTENTIONALLY AT TROJAN

PORTLAND GENERAL ELECTRIC CO., OREGON

8 PGS. LTR W/MT TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION V, AUG. 21, 1975, DOCKET 50-344, TYPE--PWR, NRC--WEST., AE--BECHTEL

CAUSE - UNAUTHORIZED CLOSURE OF A VALVE. FOLLOWING HYDROSTATIC TESTING OF THE REACTOR COOLANT SYSTEM AT 3107 PSIG, SYSTEM PRESSURE WAS REDUCED TO 400 PSIG. THE RHR SYSTEM WAS LINED UP WITH THE REACTOR COOLANT SYSTEM. WHILE REMOVING JUMPERS AND RESETTING RELIEF VALVE SETTINGS FOLLOWING THE TEST, THE RHR SYSTEM LOOP SUCTION VALVE WAS CLOSED BY AN UNAUTHORIZED PERSON RESULTING IN PRESSURIZING THE REACTOR COOLANT SYSTEM TO ABOUT 3300 PSIG. THE ENTIRE PRESSURE TRANSIENT LASTED ABOUT 10 TO 12 MINUTES WITH PEAK PRESSURE LASTING LESS THAN ONE MINUTE. NO DAMAGE WAS FOUND. ACCESS TO CONTROL AREAS WAS BEEN RESTRICTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TROJAN (PWR) • CONSTRUCTION • PRESSURE TRANSIENT • MAIN COOLING SYSTEM • FAILURE, OPERATOR ERROR

109632

CONTAINMENT INTEGRITY VIOLATED AT TROJAN

PORTLAND GENERAL ELECTRIC CO., PORTLAND, OR.

4 PAGES, LETTER WITH AU 75-03 TO U.S. NRC, REGION V, DEC. 26, 1975, DOCKET 50-344, TYPE--PWR, NRC--WEST., AE--BECHTEL

CAUSE - PERSONNEL ERROR. DURING RCS PUMP FLOW TESTING WITH THE REACTOR SHUT DOWN, CONTAINMENT INTEGRITY WAS VIOLATED FOR UP TO 5 MINUTES OF EACH HOUR. A TEST LINE TO THE INNER DOOR SEAL WAS PASSED THROUGH AN UNSEALED PENETRATION PARALLELING THE OUTER DOOR WHICH WAS INTERLOCKED CLOSED WHEN THE INNER DOOR WAS OPEN. CONTAINMENT WAS VIOLATED EACH TIME THE INNER DOOR WAS OPENED. THE PENETRATION WAS SEALED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TROJAN (PWR) • REACTOR STARTUP EXPERIENCE • CONTAINMENT INTEGRITY • CONTAINMENT AIR LOCK • FAILURE, OPERATOR ERROR • TESTING

099021

FEEDWATER TEMPERATURE RECORDER CALIBRATION INCORRECT AT TURKEY POINT 3

FLORIDA POWER & LIGHT COMPANY

3 PAGES, LETTER TO DIRECTORATE OF LICENSING (MCC), JANUARY 6, 1975, DOCKET 50-250, TYPE--PWR, NRC--WEST., AE--BECHTEL

CAUSE - PROCEDURAL ERROR. UNIT 3 WAS IN MIT SHUTDOWN. COMPARISON OF RESULTS OF UNIT 4 SECONDARY SYSTEM CALORIMETRICS CALCULATED BY PERSONNEL WITH RESULTS FROM THE NEW DIGITAL DATA PROCESSING SYSTEM REVEALED A 10 F DIFFERENCE IN FEEDWATER TEMPERATURE. THE RECORDER WAS LOWER BY 10 F. INVESTIGATION SHOWED THAT THE CALIBRATION PROCEDURES DID NOT INCLUDE THE RESISTANCE OF THE CONDUCTOR THAT IS BETWEEN THE RTD AND THE RECORDER. PROCEDURES WERE MODIFIED AND THE RECORDERS IN BOTH UNITS RECALIBRATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PROCEDURES AND MANUALS • INSTRUMENT CALIBRATION • FAILURE, ADMINISTRATIVE CONTROL • TURKEY POINT 3 (PWR) • FEEDWATER • SENSORS, TEMPERATURE • RECORDERS

100581

REACTOR OPERATION WITH AXIAL FLUX DIFFERENCE OUTSIDE TARGET BAND AT TURKEY POINT 3

FLORIDA POWER & LIGHT CO.

3 PAGES, LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, MARCH 12, 1975, DOCKET 50-250, TYPE--PWR, NRC--WEST., AE--BECHTEL

CAUSE - OPERATOR MISUNDERSTANDING. THE REACTOR TRIPPED AFTER A PERIOD OF 100% POWER OPERATION. THE UNIT WAS RETURNED TO SERVICE 3.5 HOURS LATER WITH THE LOAD BEING INCREASED TO 87% POWER OVER A 7 HOUR PERIOD. WHEN IT WAS FOUND THAT THE REACTOR HAD BEEN OPERATED OUTSIDE THE INDICATED

100501 CONTINUOUS

ANAL FLUX DIFFERENCE TARGET BAND FOR MORE THAN 1 HOUR IN THE PRECEDING 24 HOUR PERIOD. REACTOR POWER WAS REDUCED TO 448 UNTIL THE ACCUMULATED OPERATING TIME OUTSIDE LIMITS WAS REDUCED. THE CAUSE WAS ATTRIBUTED TO THE OPERATORS NOT FULLY UNDERSTANDING THE TECH SPEC REQUIREMENTS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATION ERROR + POWER DISTRIBUTION + FLUX FILE + TURKEY POINT 3 (PWR) + REACTOR STARTUP

102510

APPARENT DISCREPANCY IN CENTRAL HD NORTH AT TURKEY POINT 3

FLORIDA POWER & LIGHT CO.

3 PAGES, LETTER WITH ATTACHMENT TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, APRIL 14, 1975, DOCKET 50-250, TYPE--PWR, NRC--BEST, AE--BECHTEL

CAUSE - CALCULATIONAL ERROR. DURING PHYSICS TESTING FOLLOWING CYCLE 2 REFUELING, A COMPARISON OF MEASURED CENTRAL HD NORTH TO PREDICTED NORTH, FURNISHED BY VENDOR, INDICATED THAT THE MEASURED VALUES WERE 1% LOWER THAN PREDICTED VALUES. THE FUEL VENDOR RECALCULATED HIS PREDICTION AND THE RESULTS ARE CONSISTENT WITH THE UTILITY PREDICTED VALUES. ADEQUATE SHUTDOWN MARGIN EXISTS THROUGHOUT THE CYCLE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 3 (PWR) + CENTRAL HD NORTH + MATHEMATICAL TREATMENT + COMPARISON, THEORY AND EXPERIENCE + COMPARISON + SHUTDOWN MARGIN + REFUELING

102311

SPECIAL MAINTENANCE ON CONTAINMENT TENDON GREASE CAPS AT TURKEY POINT 3

FLORIDA POWER & LIGHT CO.

3 PAGES, LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, APRIL 21, 1975, DOCKET 50-250, TYPE--PWR, NRC--BEST, AE--BECHTEL

CAUSE - GREASE LEAKS. DURING CONTAINMENT TENDON SURVEILLANCE, GREASE LEAKAGE WAS FOUND FROM 110 UP 832 TENDON LOCATIONS. LEAKAGE WAS AT THE GASKETED JOINTS BETWEEN THE GREASE CAP AND THE BEARING PLATE, BOLT FITTINGS, PIPE PLUGS, AND DEFECTIVE SEAL WELDS. ALL TENDON CASING THAT HAD EXPERIENCED LEAKAGE WERE REPAIRED AND REFILLED WITH GREASE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 3 (PWR) + PLEAS + STEEL + CONCRETE, PRESTRESSED + CABLES AND CONNECTORS + SURVEILLANCE PROGRAM + INSERVICE INSPECTION + CONTAINMENT STRUCTURE + CONTAINMENT INTEGRITY + LUBRICATION

102312

STEAM GENERATOR LO-LO LEVEL COMPARATOR FAILS AT TURKEY POINT 3

FLORIDA POWER & LIGHT CO.

2 PAGES, LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, APRIL 23, 1975, DOCKET 50-250, TYPE--PWR, NRC--BEST, AE--BECHTEL

CAUSE - CAPACITOR FAILURE. DURING TESTING, A LOW-LOW LEVEL COMPARATOR FOR A STEAM GENERATOR DID NOT TRIP AT THE EXPECTED 15% LEVEL. A CAPACITOR IN THE -15 VDC INSTRUMENT POWER SUPPLY HAD FAILED ALLOWING AN AC SIGNAL TO BE SUPERIMPOSED ON THE INTERNAL DC SIGNAL IN THE COMPARATOR. THE FAULTY COMPARATOR WAS REPLACED WITH A CALIBRATED SPARE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 3 (PWR) + SENSORS, LEVEL + INSTRUMENT, SWITCH + INSTRUMENT CALIBRATION + TEST, SYSTEM OPERABILITY + FAILURE, INSTRUMENT + ELECTRONIC FUNCTION UNITS + FAILURE, COMPONENT + STEAM GENERATOR

103103

BATTERY CHARGER TRANSFORMER FAILS AT TURKEY POINT 3

FLORIDA POWER & LIGHT CO.

1 PAGE, LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, MAY 27, 1975, DOCKET 50-250, TYPE--PWR, NRC--BEST, AE--BECHTEL

CAUSE - MAINTENANCE ERROR. WHILE OPERATING THE REACTOR AT FULL LOAD WITH BATTERY CHARGER 3A IN SERVICE AT 50 TO 55% OUTPUT, SMOKE WAS OBSERVED COMING FROM THE CHARGER. A TRANSFORMER WAS OVERHEATING. THE FAILED TRANSFORMER HAD THE ORIGINAL INSULATION WHICH WAS NOT SATISFACTORY. ALL TRANSFORMERS HAVING THE ORIGINAL INSULATION WERE THOUGHT TO HAVE BEEN CHANGED OUT IN 1973 FOLLOWING A SIMILAR INCIDENT. THE TRANSFORMER WAS REPLACED WITH ONE HAVING CLASS F INSULATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

BATTERIES & CHARGERS + EMERGENCY POWER, ELECTRIC + FAILURE, COMPONENT + FAILURE, MAINTENANCE ERROR + INSULATION + TURKEY POINT 3 (PWR) + TRANSFORMERS

103206
INTAKE COOLING WATER PUMP BREAKER MALFUNCTIONS AT TURKEY POINT 3
FLORIDA POWER & LIGHT COMPANY
1 PAGE. LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JUNE 6, 1975, DOCKET 50-250, TYPE--PWR, WFG--
WEST., AE--BECHTEL

CAUSE - UNKNOWN. DURING A NORMAL SHIFTING OF OPERATING INTAKE COOLING WATER PUMPS, PUMP 3A FAILED TO START. ITS BREAKER FAILED TO REMAIN CLOSED. THE CAUSE HAS NOT YET BEEN DETERMINED. THE BREAKER WAS RACKED OUT AND INSPECTED. NO DAMAGED PARTS WERE FOUND. IT WAS RETURNED TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 3 (PWR) • PUMPS • CONDENSED COOLING SYSTEM • FAILURE, EQUIPMENT • BREAKER

104003
EMERGENCY DIESEL GENERATOR BREAKER FAILS TO CLOSE AT TURKEY POINT 3
FLORIDA POWER & LIGHT CO.
2 PAGES. LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JULY 11, 1975, DOCKET 50-250, TYPE--PWR, WFG--
WEST., AE--BECHTEL

CAUSE - LOOSE FUSE HOLDER. WITH BOTH UNITS OPERATING NEAR FULL POWER, A LOAD TEST WAS INITIATED FOR DIESEL GENERATOR 3. THE DIESEL GENERATOR STARTED AND CAME UP TO RATED SPEED AND VOLTAGE. WHEN AN ATTEMPT WAS MADE TO CLOSE THE BREAKER, IT FAILED TO CLOSE BECAUSE OF A LOOSE FUSE HOLDER IN THE 125 VDC CIRCUIT SUPPLY LESTING CONTROL POWER. ONE SET OF FUSE HOLDER MALE-FEMALE STABS WAS MISALIGNED AND DID NOT MAKE GOOD ELECTRICAL CONTACT. MISALIGNMENT PROBABLY WAS CAUSED BY RUMOR HANDLING DURING REMOVAL AND REINSTALLATION. THE STABS WERE REALIGNED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 3 (PWR) • BREAKER • EMERGENCY POWER, ELECTRIC • GENERATOR, DIESEL • TEST, SYSTEM OPERABILITY • FAILURE, MAINTENANCE ERROR • INSTRUMENT, PROTECTIVE • DAMAGE

104024
INTAKE COOLING WATER PUMP BREAKER TRIPS AT TURKEY POINT 3
FLORIDA POWER & LIGHT COMPANY, MIAMI
1 PG. LTR TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, AUG. 1, 1975, DOCKET 50-250, TYPE--PWR, WFG--WEST., AE--
BECHTEL

CAUSE - WEAR TRIP LATCH WEAR SPRING. DURING ROUTINE ROTATION OF OPERATING EQUIPMENT WITH THE UNIT AT 12 POWER, THE BREAKER FOR INTAKE COOLING WATER PUMP 3A CLOSED AND THEN TRIPPED OPEN. THE TRIP LATCH RETURN SPRING WAS FOUND TO BE WEAR. IT APPARENTLY HAD NOT RETURNED THE TRIP LATCH TO THE PROPER POSITION THEREBY PERMITTING THE BREAKER TO TRIP AFTER INITIAL CLOSURE. THE 6E TYPE AN-4, 10-350-LB BREAKER WAS REPLACED WITH A SPARE. THE DEFECTIVE SPRING WAS REPLACED AND THE BREAKER TESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 3 (PWR) • BREAKER • AUXILIARY COOLING • FAILURE, COMPONENT • FAILURE, EQUIPMENT

104992
LATERAL RESTRAINTS FOR SPENT FUEL RACKS BROKEN AT TURKEY POINT 3
FLORIDA POWER & LIGHT COMPANY, MIAMI
2 PGS. LTR TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, AUG. 5, 1975, DOCKET 50-250, TYPE--PWR, WFG--WEST., AE--
BECHTEL

CAUSE - DESIGN ERROR. IN EARLY MARCH, SEVERAL STAINLESS STEEL SEISMIC RESTRAINT SPRINGS INSTALLED ON UNIT 4 SPENT FUEL RACKS WERE FOUND BROKEN. ALL HAVE BEEN REPLACED. INSPECTION OF 70 SPRINGS ON UNIT 3 FOUND 10 CRACKED AND 7 POSSIBLY CRACKED. ALL UNIT 3 SPRINGS WILL BE REPLACED ALSO.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 3 (PWR) • SHOCK ABSORBER • SUPPORT STRUCTURE • FUEL STORAGE • FAILURE, DESIGN ERROR • SURVEILLANCE PROGRAM

105542
CONTAINMENT RING GIRDER REPAIR AT TURKEY POINT 3
FLORIDA POWER & LIGHT COMPANY, MIAMI
16 PGS. LTR W/ATTACH. TO NRC DIV. OF REACTOR LICENSING, AUG. 27, 1975, DOCKET 50-250, TYPE--PWR, WFG--WEST., AE--
BECHTEL

CAUSE - CONSTRUCTION ERROR. DURING THE THIRD YEAR CONTAINMENT PERIOD SURVEILLANCE, SOME CONCRETE SPALLING WAS FOUND TO HAVE OCCURRED AT THE HORIZONTAL CONSTRUCTION JOINT AT THE RING GIRDER. SPALLING WAS CONFINED TO THE LOWER EXPOSED SURFACES ADJACENT TO THE JOINT, RESULTING IN SOME

105542 *CONTINUED*

SUPERFICIAL CRACKS. NO REINFORCING STEEL WAS EXPOSED. THE STRUCTURAL INTEGRITY WAS NOT EFFECTED. THE CRACKS WERE FILLED WITH MORTAR BY GROUT-PACK METHOD. SPALLING APPEARS TO BE THE RESULT OF INCOMPLETE REMOVAL OF SAND USED IN THE SAND-BLASTING OPERATION IN PREPARATION OF THE JOINT PRIOR TO PLACEMENT OF CONCRETE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 3 (PWR) * PWR * CONCRETE * CONCRETE, PRESTRESSED * CONTAINMENT STRUCTURE * SURVEILLANCE PROGRAM * FAILURE, INSTALLATION ERROR * MAINTENANCE AND REPAIR * CONTAINMENT INTEGRITY * CONTAINMENT

106040

HIGH PRESSURE COMPARTMENT FAILS TO TRIP AT TURKEY POINT 3

FLORIDA POWER & LIGHT CO., MIAMI, FLA.

2 PGS. AD 250-75-7 TO NRC OFFICE OF I & E, REGION II, OCT. 3, 1975, DOCKET 50-250, TYPE--PWR, NRC--WEST., AE--DECHTEL

CAUSE - TWO FAILED CAPACITORS. DURING A TEST WITH THE REACTOR AT 90% POWER, A HIGH PRESSURIZER PRESSURE COMPARTMENT DID NOT TRIP AT THE REQUIRED SET POINT. TESTS REVEALED 2 FAILED CAPACITORS IN THE DC POWER SUPPLY. THE COMPARTMENT WAS REPLACED WITH A SPARE UNIT. THIS WAS A MAJOR/COMPUTER SYSTEM, MODEL AG-411082-001 COMPARTMENT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 3 (PWR) * INSTRUMENTS, MISC. * SENSORS, PRESSURE * INSTRUMENT CALIBRATION * TEST, SYSTEM OPERABILITY * FAILURE, INSTRUMENT * ELECTRONIC FUNCTION UNITS * FAILURE, COMPONENT * REACTOR SAFETY SYSTEM

107763

MAIN STEAM ISOLATION VALVE FAILS TO CLOSE AT TURKEY POINT 3

FLORIDA POWER & LIGHT CO., MIAMI, FLA.

3 PGS. AD 250-75-8 TO NRC OFFICE OF I & E, REGION II, NOV. 5, 1975, DOCKET 50-250, TYPE--PWR, NRC--WEST., AE--DECHTEL

CAUSE - UNKNOWN. WITH THE REACTOR CRITICAL BELOW THE POWER RANGE THE CONTROL ROOM SWITCH WHICH OPERATES MAIN STEAM ISOLATION VALVE C WAS PLACED IN CLOSE POSITION, BUT THE VALVE FAILED TO CLOSE. ATTEMPTS TO CLOSE THE VALVE BY VENTING THE AIR SYSTEM FAILED. ABOUT 1 1/2 HOURS LATER, THE VALVE CLOSED. NO INDICATIONS OF BINDING IN THE STEM PACKING OR THE PNEUMATIC CYLINDER INTERNALS WERE FOUND. THE VALVE HAS BEEN SATISFACTORILY CYCLED 9 TIMES SINCE THE OCCURRENCE. THE INVESTIGATION IS CONTINUING DURING THE REFUELING OUTAGE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 3 (PWR) * VALVES * CONTAINMENT ISOLATION * COOLING SYSTEM, SECONDARY * STEAM * FAILURE, EQUIPMENT

108471

SET POINT DRIFT IN CONTAINMENT PRESSURE SWITCH AT TURKEY POINT 3

FLORIDA POWER & LIGHT CO., MIAMI, FLA.

2 PGS. AD 250-75-9 TO NRC OFFICE OF I & E, REGION II, NOV. 26, 1975, DOCKET 50-250, TYPE--PWR, NRC--WEST., AE--DECHTEL

CAUSE - UNKNOWN. DURING A REFUELING OUTAGE TEST, 1 OF THE 3 HIGH-HIGH CONTAINMENT PRESSURE SWITCHES WAS FOUND TO HAVE A SET POINT OF 35 PSIG WHICH EXCEEDS THE 30 PSIG LIMIT. THE CAUSE OF THE SET POINT DRIFT IS UNKNOWN. THE STATIC O-RING, TYPE 6N-4A3-AAA PRESSURE SWITCH WAS RECALIBRATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 3 (PWR) * INSTRUMENT, SWITCH * INSTRUMENT CALIBRATION * SENSORS, PRESSURE * TEST, SYSTEM OPERABILITY * FAILURE, INSTRUMENT * SET POINT * DRIFT * CONTAINMENT * PLANT PROTECTIVE SYSTEM * REFUELING

108230

MAIN STEAM LINE SPRING SUPPORT DISTORTED AT TURKEY POINT 3

FLORIDA POWER & LIGHT CO., MIAMI, FLA.

2 PGS. UNUSUAL EVENT 250-75-3 TO NRC OFFICE OF I & E, REGION II, DEC. 5, 1975, DOCKET 50-250, TYPE--PWR, NRC--WEST., AE--DECHTEL

CAUSE - UNKNOWN. WHILE THE UNIT WAS IN REFUELING SHUTDOWN CONDITION, THE SPRING HANGER ON MAIN STEAM LINE 3A INSIDE CONTAINMENT WAS FOUND TO BE DISTORTED. THE EXACT CAUSE IS UNKNOWN. HOWEVER, A RECENT SPURIOUS CLOSURE OF THE MSIV AT FULL POWER MAY HAVE GENERATED ENOUGH TRANSIENT LOAD TO DISTORT IT. THE HANGER HAD BEEN DESIGNED TO WITHSTAND HYDROSTATIC TEST AND DEAD LOADS. A NEW HANGER IS BEING DESIGNED TO WITHSTAND SPURIOUS CLOSURE LOAD AS WELL. PARTS HAVE BEEN RECEIVED AND WORK WILL BEGIN UPON FINAL APPROVAL OF THE DESIGN. HANGERS ON OTHER MAIN STEAM LINES ARE BEING EVALUATED.

100230 CONTINUED

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 3 (PHR) + SUPPORT STRUCTURE + PIPES AND PIPE FITTINGS + MAIN COOLING SYSTEM + STEAM + FAILURE, DESIGN ERROR + MODIFICATION + DAMAGE + REPAIRING

099026

FEEDWATER TEMPERATURE RECORDER CALIBRATION INCOMPLETE AT TURKEY POINT 4
FLORIDA POWER & LIGHT COMPANY

3 PAGES, LETTER TO DIRECTORATE OF LICENSING (AEC), JANUARY 6, 1975, DOCKET 50-251, TYPE--PHR, WFG--WEST., AE--BCHTEL

CAUSE - PROCEDURAL ERROR. UNIT 4 WAS AT 99.98 POWER. COMPARISON OF RESULTS OF UNIT 4 SECONDARY SYSTEM CALORIMETRICS CALCULATED BY PERSONNEL WITH RESULTS FROM THE NEW DIGITAL DATA PROCESSING SYSTEM REVEALED A 10 F DIFFERENCE IN FEEDWATER TEMPERATURE. THE RECORDER WAS LOWER BY 10 F. INVESTIGATION SHOWED THAT THE CALIBRATION PROCEDURE DID NOT INCLUDE THE RESISTANCE OF THE CONDUCTION THAT IS BETWEEN THE RTD AND THE RECORDER. PROCEDURES WERE MODIFIED AND THE RECORDERS IN BOTH UNITS RECALIBRATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

PROCEDURES AND MANUALS + INSTRUMENT CALIBRATION + FAILURE, ADMINISTRATIVE CONTROL + TURKEY POINT 4 (PHR) + FEEDWATER + SENSORS, TEMPERATURE + RECORDERS

099025

PRESSURIZER LEAD/LAG CONTROLLER FAILS AT TURKEY POINT 4
FLORIDA POWER & LIGHT COMPANY

3 PAGES, LETTER TO DIRECTORATE OF LICENSING (AEC), JANUARY 13, 1975, DOCKET 50-251, TYPE--PHR, WFG--WEST., AE--BCHTEL

CAUSE - ZERO SHIFT. DURING TESTING OF THE PRESSURIZER PRESSURE AND LEVEL PROTECTION SYSTEM WITH THE REACTOR AT 99.88 POWER, IT WAS NOTED THAT THE LOW PRESSURE LEAD/LAG CONTROLLER WAS HIGHER THAN THE SIGNAL FROM THE PRESSURE TRANSMITTER SIMULATOR. UNDER TEST CONDITIONS, THE OUTPUT SHOULD EQUAL THE SIGNAL. THE CAUSE WAS A ZERO-SHIFT IN THE CONTROLLER. THE CONTROLLER WAS ADJUSTED TO CORRECT FOR ZERO-SHIFT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INSTRUMENT CALIBRATION + FAILURE, INSTRUMENT + INSTRUMENT, SWITCH + PRESSURIZER + TEST, SYSTEM OPERABILITY + SET POINT + TURKEY POINT 4 (PHR) + SHIFT + SENSORS, PRESSURE + INSTRUMENTS, MISC.

100039

ADDITIONAL INFORMATION ON LEAK IN VENT LINE ASSEMBLY AT TURKEY POINT 4
FLORIDA POWER & LIGHT COMPANY

3 PAGES, LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JANUARY 20, 1975, DOCKET 50-251, TYPE--PHR, WFG--WEST., AE--BCHTEL

CAUSE - INSTALLATION ERROR. A LEAK IN A 3/4 INCH VENT LINE ASSEMBLY UPSTREAM OF THE SAFETY INJECTION SYSTEM 10 INCH CHECK VALVE WAS REPORTED EARLIER. THE INVESTIGATION INDICATED A DEFECT WAS AT THE WELD ROOT RESULTING FROM LACK OF PENETRATION. THE FIT-UP BETWEEN THE PIPE AND COUPLING WAS POOR. CYCLIC LOADING WAS ENCOUNTERED IN SERVICE. FATIGUE CRACK PROPAGATION HAD OCCURRED. THE SOURCE OF THE CYCLIC LOADING IS BEING INVESTIGATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SAFETY INJECTION + FAILURE, FATIGUE + EXAMINATION + FAILURE, INSTALLATION ERROR + LEAK + TURKEY POINT 4 (PHR) + PIPES AND PIPE FITTINGS

099365

LOW BORON CONCENTRATION IN INJECTION TANK AND STORAGE TANK AT TURKEY POINT 4

FLORIDA POWER & LIGHT COMPANY

1 PAGE, LETTER TO OFFICE OF NUCLEAR REACTOR REGULATION, JANUARY 30, 1975, DOCKET 50-251, TYPE--PHR, WFG--WEST., AE--BCHTEL

CAUSE - DILUTION DURING FLUSHING. WHILE OPERATING AT 100% POWER, SAMPLES FROM BORIC ACID STORAGE TANK C INDICATED A CONCENTRATION OF 18900 PPM WHICH IS BELOW THE 20000 PPM LIMIT. STORAGE TANK B WAS THEN PLACED IN SERVICE. THEN, SAMPLES FROM THE BORON INJECTION TANK INDICATED ONLY 17000 PPM BORON. IMMEDIATELY LOAD REDUCTION WAS STARTED UNTIL THE CONCENTRATION COULD BE INCREASED. DEMINERALIZED WATER USED TO FLUSH TEMPORARY HOSES RESULTED IN THE DILUTION. OPERATORS CAUTIONED TO TAKE GREATER CARE IN TRANSFERRING BORIC ACID.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, OPERATOR ERROR + POISON, SOLUBLE + STORAGE CONTAINER + SHUTDOWN SYSTEM, SECONDARY + CHEMICAL SHIM +

103585 CONTINGED
TURKEY POINT 4 (PWR) + REACTOR SHUTDOWN + CONCENTRATION

103582
LOW STEAM LINE PRESSURE COMPARTOR FAILS AT TURKEY POINT 4
FLORIDA POWER & LIGHT CO.
2 PAGES. LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, MARCH 16, 1975, DCKET 50-251, TYPE--PWR, NRC--
WEST., AE--DECEMTEL

CAUSE - FAILED CAPACITOR. DURING TESTING WITH THE REACTOR AT LOW POWER, A LOW STEAM LINE PRESSURE COMPARTOR FAILED TO TRIP AT THE EXPECTED TRIP SETPOINT. A CAPACITOR IN THE -15V DC INSTRUMENT POWER SUPPLY HAD FAILED. THIS ALLOWED AN AC SIGNAL TO BE SUPERIMPOSED ON THE INTERNAL DC SIGNAL IN THE COMPARTOR. THE FAULTY COMPARTOR WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + INSTRUMENT CALIBRATION + FAILURE, INSTRUMENT + TEST, SYSTEM OPERABILITY + TURKEY POINT 4 (PWR) + SENSORS, PRESSURE + ELECTRONIC FUNCTION UNITS

103697
LATERAL RESTRAINTS FOR SPENT FUEL RODS BROKEN AT TURKEY POINT 4
FLORIDA POWER & LIGHT CO.
4 PAGES. LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, MARCH 21, 1975, DCKET 50-251, TYPE--PWR, NRC--
WEST., AE--DECEMTEL

CAUSE - UNKNOWN. THE SPENT FUEL POOL WAS DRAINED AND BEING CLEANED IN PREPARATION FOR THE FIRST REFUELING. ONE OF THE 110 STAINLESS STEEL SEISMIC RESTRAINT SPRINGS WAS FOUND BROKEN INTO TWO PIECES AND LYING ON THE POOL FLOOR. EXAMINATION FOUND 5 MORE WERE SIMILARLY BROKEN BUT WERE HELD IN PLACE BY THE NUTS USED TO FASTEN THE SPRING TO THE STUD USED FOR PRELOADING THE SPRING. THE CAUSE OF FAILURE HAS NOT BEEN DETERMINED. THE FAILED SPRINGS WERE REPLACED IN KIND.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, EQUIPMENT + FUEL STORAGE + SHOCK ABSORBER + SUPPORT STRUCTURE + TURKEY POINT 4 (PWR) + SEISMIC DESIGN

102309
UNPLANNED RELEASE OF RADIOACTIVE WATER AT TURKEY POINT 4
FLORIDA POWER & LIGHT CO.
3 PAGES. LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, APRIL 22, 1975, DCKET 50-251, TYPE--PWR, NRC--
WEST., AE--DECEMTEL

CAUSE - PROCEDURAL DEFICIENCY. DURING A REFUELING SHUTDOWN, THE SPENT FUEL PIT COOLING PUMP BEARINGS FAILED. THE PUMP WAS REMOVED FOR SERVICE. AN EMERGENCY SFP PUMP WAS INSTALLED. SIX HOURS LATER, IT WAS DISCOVERED THAT THE PUMP DISCHARGE HOSE CONNECTION HAD SEPARATED FROM THE PIPING. WATER FLOW WAS STOPPED. ABOUT 7400 GALLONS OF WATER WERE SPILLED OF WHICH 2900 GALLONS WERE ABSORBED BY THE GROUND. PROCEDURES DID NOT SPECIFY THE TYPE OF PUMP AND CONNECTIONS TO USE IN THIS CASE. A LARGE PUMP WAS INSTALLED USING PIPE CONNECTIONS. PROCEDURES WERE MODIFIED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 4 (PWR) + RADIOACTIVITY RELEASE + WATER + STORAGE CONTAINER + FUEL STORAGE + FAILURE, ADMINISTRATIVE CONTROL + PIPES AND PIPE FITTINGS + COOLING + PROCEDURES AND MANUALS + FAILURE, PIPE + REFUELING

102552
ADDITIONAL INFORMATION ON BROKEN SPENT FUEL ROD RESTRAINTS AT TURKEY POINT 4
FLORIDA POWER & LIGHT CO.
3 PAGES. LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, MAY 1, 1975, DCKET 50-251, TYPE--PWR, NRC--
WEST., AE--DECEMTEL

CAUSE - STRESS CORROSION. BROKEN SPENT FUEL ROD LATERAL RESTRAINTS (LEAF SPRINGS) WERE REPORTED EARLIER. AN ADDITIONAL 7 SPRINGS WERE FOUND TO BE BROKEN. METALLURGICAL EXAMINATION FOUND THAT THE SPRINGS FAILED IN A STRESS CORROSION MODE. ANALYSIS REVEALED A HIGH INCLUSION CONTENT BUT THE INCLUSION WAS INSUFFICIENT TO HAVE CAUSED FAILURE. ALL RESTRAINTS WERE REPLACED WITH ONES OF THE ORIGINAL DESIGN. REPLACEMENT SPRINGS WERE FABRICATED UTILIZING SPECIAL QUALITY CONTROL MEASURES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 4 (PWR) + SHOCK ABSORBER + SUPPORT STRUCTURE + FUEL STORAGE + STORAGE CONTAINER + STRESS CORROSION + METALLURGY + FABRICATION + MODIFICATION

102551

102551 PLUTINIUM
CONTAINMENT INTEGRITY BREACHED DURING REFUELING OPERATIONS AT TURKEY POINT 4
FLORIDA POWER & LIGHT CO.
3 PAGES, LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, MAY 1, 1975, DOCKET 50-251, TYPE--PWR, NRC--
WEST.. AE--DECTEL

CAUSE - PROCEDURAL DEFICIENCY. DURING THE REFUELING OUTAGE, A SAFETY VALVE SEATING SURFACE WAS BEING LAPPED. AT THE SAME TIME, PERSONNEL INSIDE CONTAINMENT REMOVED A STEAM GENERATOR SECONDARY SIDE HANDWAY. WHEN THE LAPPING BLOCK WAS REMOVED FROM THE SAFETY VALVE SEAL (OUTSIDE CONTAINMENT), A MIXTURE OF AIR AND WATER ESCAPED FROM THE SAFETY VALVE. FUEL HANDLING OPERATIONS WERE SUSPENDED UNTIL SECONDARY CONTAINMENT WAS REESTABLISHED. PROCEDURES INVOLVED IN THESE OPERATIONS DID NOT REQUIRE CONTAINMENT INTEGRITY. THEY WILL BE REVISED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 4 (PWR) • PLUTINIUM INTEGRITY • MAINTENANCE AND REPAIR • REFUELING • FAILURE, ADMINISTRATIVE CONTROL • PROCEDURES AND MANUALS

102898
FUEL ASSEMBLY DAMAGED DURING REFUELING OPERATIONS AT TURKEY POINT 4
FLORIDA POWER & LIGHT CO.
4 PAGES, LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, MAY 6, 1975, DOCKET 50-251, TYPE--PWR, NRC--
WEST.. AE--DECTEL

CAUSE - PROCEDURAL DEFICIENCY. AS A FUEL ASSEMBLY WAS BEING LOWERED INTO THE REACTOR CORE, AN OBSERVER NOTICED AN ANOMALOUS CONDITION ON A FACE OF THE ASSEMBLY. AN INSPECTION SHOWED THAT THE FIRST GRID ABOVE THE BOTTOM NOZZLE WAS DAMAGED AND 2 FUEL RODS WERE DISTORTED. CLADDING INTEGRITY HAD NOT BEEN BREACHED. DAMAGE RESULTED FROM PROCEDURAL DEFICIENCIES. THE PROCEDURE DID NOT SPECIFY THAT THE FUEL ASSEMBLY MUST BE LIFTED TO THE FULL UP POSITION BY THE SPENT FUEL PIT CRANE BEFORE THE SFP BRIDGE IS MOVED AWAY FROM THE BACK POSITION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 4 (PWR) • FUEL ELEMENTS • DAMAGE • FUEL HANDLING • FAILURE, ADMINISTRATIVE CONTROL • PROCEDURES AND MANUALS • REFUELING • TRANSPORTATION AND HANDLING • FUEL INTEGRITY

103207
DIESEL GENERATOR BREAKER AND BUS STRIPPING RELAY MALFUNCTION AT TURKEY POINT 4
FLORIDA POWER & LIGHT CO.
2 PAGES, LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JUNE 4, 1975, DOCKET 50-251, TYPE--PWR, NRC--
WEST.. AE--DECTEL

CAUSE - MECHANICAL BINDING. WITH BOTH UNITS SHUT DOWN, BOTH 4160 VOLT BUSES FOR UNIT 4 WERE MANUALLY DEENERGIZED. DG 3 STARTED, CAME TO SPEED, BUT THEN SHUT DOWN AUTOMATICALLY. DG 4A BREAKER WAS FOUND TO BE BINDING MECHANICALLY IN THE LATCHING MECHANISM WHICH PREVENTED IT FROM CLOSING. THIS LED TO THE DG SHUTDOWN. THE BREAKER WAS REPLACED. DG 4 STARTED AND CAME UP TO SPEED BUT BREAKER 4B DID NOT CLOSE BECAUSE THE BUS HAD NOT COMPLETELY STRIPPED OF LOAD. THIS RELAY FAILED TO CAUSE 3 BREAKERS TO OPEN. NO CAUSE FOR THE MALFUNCTION WAS FOUND. THE STRIPPING RELAY WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 4 (PWR) • BREAKER • TEST, SYSTEM OPERABILITY • ACCIDENT, LOSS OF POWER • JFF SITE • REFUELING • ELECTRICAL POWER • EMERGENCY POWER, ELECTRIC • FAILURE, EQUIPMENT • RELAYS

103635
AIRLOCK EQUALIZING VALVE FOUND OPEN AT TURKEY POINT 4
FLORIDA POWER & LIGHT COMPANY
3 PAGES, LETTER TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, JUNE 20, 1975, DOCKET 50-251, TYPE--PWR, NRC--
WEST.. AE--DECTEL

CAUSE - DISCONNECTED MECHANICAL LINKAGE. DURING HEATUP FOLLOWING A REFUELING OUTAGE, A GC INSPECTOR DISCOVERED A DISCONNECTED MECHANICAL LINKAGE ON THE EQUALIZING VALVE FOR THE OUTER DOOR OF THE PERSONNEL ACCESS AIRLOCK. THE VALVE WAS OPEN THEREBY ESTABLISHING A FLOW PATH FROM CONTAINMENT TO ATMOSPHERE WHENEVER THE INNER DOOR WAS OPEN. THE VALVE AND LINKAGE ARE HIDDEN FROM VIEW BEHIND A COVER PLATE. THE PROBLEM WAS NOT FOUND DURING THE PRESTART CHECK. NO REASON WAS FOUND FOR THE LINKAGE TO BE DISCONNECTED. IT WAS RECONNECTED. CHECKLISTS WERE REVISED TO INCLUDE VERIFYING THAT THE VALVE IS CLOSED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 4 (PWR) • PLUTINIUM INTEGRITY • VALVES • CONTAINMENT AIR LOCK • PROCEDURES AND MANUALS • REACTOR STARTUP • FAILURE, ADMINISTRATIVE CONTROL

104051

107421 CONTINUED

ECCS ANALYSIS REVISED AT TURKEY POINT 4
FLORIDA POWER & LIGHT COMPANY
3 PAGES. LETTER WITH WER 75-11 TO NRC DIVISION OF REACTOR LICENSING, JULY 8, 1975. DOCKET 50-251, TYPE--PWR, NRC--WEST., AE--BCHTEL

CAUSE - CALCULATIONAL ERROR. AN AUDIT BY WESTINGHOUSE OF THE CALCULATIONS OF THE ECCS ANALYSIS FOR THE LARGE BREAK SPECTRUM HAS SHOWN THAT THE VALUE FOR PEAK CLAD TEMPERATURE IS IN ERROR. IN THE ANALYSIS, FUEL DESIGN DATA FOR UNIT 3 WAS USED WHICH WAS NOT APPLICABLE FOR CYCLE 2 OF UNIT 4. A RECALCULATION WITH THE CORRECT INPUT INCREASED PEAK CLAD TEMPERATURE TO 2233 F WHEN OPERATING AT 2300 MWt WHICH EXCEEDS THE 2200 F LIMIT. LICENSED POWER IS 2200 MWt. FOR THIS POWER, PEAK CLAD TEMPERATURE IS 2150 F, WELL BELOW THE 2200 F LIMIT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 4 (PWR) • TEMPERATURE • FUEL ELEMENTS • CLADDING • ACCIDENT, LOSS OF COOLANT • FAILURE, ADMINISTRATIVE CONTROL • ACCIDENT ANALYSIS • MATHEMATICAL TREATMENT

107430

SUPPLEMENTARY REPORT ON BUS STRIPPING RELAY MALFUNCTION AT TURKEY POINT 1
FLORIDA POWER & LIGHT CO., FLA.
2 PAGES. AD 251-75-8 TO NRC OFFICE OF I & E, REGION II, OCT. 13, 1975. DOCKET 50-251, TYPE--PWR, NRC--WEST., AE--BCHTEL

CAUSE - INTERMITTENT OPEN CIRCUIT. DURING A TEST ON MAY 25, A BUS STRIPPING RELAY FAILED TO COMPLETELY STRIP THE LOAD FROM ONE BUS AS REPORTED EARLIER. INVESTIGATION BY THE VENDOR REVEALED AN INTERMITTENT OPEN CIRCUIT IN THE RELAY COIL CAUSED BY ELECTROLYTIC CORROSION. FOR RELAYS WITH MILK-WHITE NYLON COIL SPOOLS, A HEAT STABILIZING COMPONENT OF THE NYLON CONTAINS HALOGEN IONS WHICH CAN BE RELEASED OVER A PERIOD OF TIME. THE IONS COMBINE WITH MOISTURE TO FORM ACID WHICH CORRODES THE COIL WIRE. ALL OF THIS TYPE NYLON SPOOL WILL BE REPLACED IN BOTH UNITS WITH LEXAN SPOOLS BEFORE THE END OF THE NEXT REFUELING OUTAGES. THESE WERE GE TYPES MFA, MHA, AND MHA RELAYS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 4 (PWR) • RELAYS • CORROSION • FAILURE, DESIGN ERROR • TEST, SYSTEM OPERABILITY • MATERIAL • MODIFICATION • FAILURE, COMMON MODE

107530

UNPLANNED RELEASE OF RADIOACTIVE LIQUID AT TURKEY POINT 4
FLORIDA POWER & LIGHT CO., FLA.
2 PAGES. AD 251-75-10 TO NRC OFFICE OF I & E, REGION II, OCT. 31, 1975. DOCKET 50-251, TYPE--PWR, NRC--WEST., AE--BCHTEL

CAUSE - PERSONNEL ERROR. THE WASTE MUDPUP TANK, WHICH IS SHARED BY BOTH UNITS, WAS CLEANED TO REMOVE SLUDGE DEPOSITS. THE RESULTING SLUDGE-WATER MIXTURE WAS TEMPORARILY STORED IN 55-GALLON DRUMS. AFTER A SETTLING PERIOD, WATER WAS PUMPED FROM 20 DRUMS TO THE FLOOR DRAIN. HOWEVER, PERSONNEL ERROR RESULTED IN PUMPING INTO THE WRONG FLOOR DRAIN RELEASING 800 GALLONS TO AN UNDERGROUND AREA OUTSIDE THE RADIATION CONTROLLED BOUNDARY. ANALYTICAL RESULTS INDICATE THAT ABOUT 2.1 Ci OF PRIMARILY CO-60 AND CS-137 WERE RELEASED. FLOOR DRAIN WILL BE LABELED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 4 (PWR) • RADIOACTIVITY RELEASE • WASTE HANDLING • FAILURE, OPERATOR ERROR

108247

BORON CONCENTRATION IN BORIC ACID STORAGE TANK HIGH AT TURKEY POINT 4
FLORIDA POWER & LIGHT CO., MIAMI, FLA.
3 PAGES. AD 251-75-11 TO NRC OFFICE OF I & E, REGION II, NOV. 21, 1975. DOCKET 50-251, TYPE--PWR, NRC--WEST., AE--BCHTEL

CAUSE - CONCENTRATED SOLUTION ADDED. WHILE OPERATING AT 99% POWER, THE BORON CONCENTRATION IN BORIC ACID STORAGE TANK C, WHICH WAS IN SERVICE, WAS VERIFIED TO BE 22600 PPM WHICH IS ABOVE THE 22500 PPM UPPER LIMIT. A CONCENTRATED SOLUTION HAD BEEN ADDED TO INCREASE THE VOLUME WELL ABOVE THE REQUIRED MINIMUM. TANK B COULD NOT BE PLACED IN SERVICE BECAUSE OF MAINTENANCE ACTIVITIES. PRIMARY WASTE WATER WAS ADDED TO THE TANK AND THE CONTENTS OF THE TANK RECIRCULATED TO DILUTE THE BORON CONCENTRATION. CONCENTRATION WAS WITHIN SPECIFICATIONS WITHIN 12.5 HOURS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 4 (PWR) • CONCENTRATION • BORON • STORAGE CONTAINER • POISON, SOLUBLE • CHEMICAL SHIM • FAILURE, OPERATION ERROR

108799

SPENT FUEL PIT LEAKS AT TURKEY POINT 4

108799 CONTINUED

FLORIDA POWER & LIGHT CO., MIAMI, FL

2 PGS, LR 251-75-3 TO NRC OFFICE OF I & E, REGION II, DEC. 5, 1975, DOCKET 50-251, TYPE--PWR, NRC--WEST., AE--BECHTEL

CAUSE - LINER LEAK. THE SPENT FUEL PIT CONCRETE WALL WAS FOUND TO BE LEAKING. THE LEAK IS ABOVE THE CONCRETE SHIELDING AROUND THE FUEL TRANSFER TUBE. THE RATE IS ABOUT 2 GALLONS PER HOUR. WATER IS LEAKING THROUGH THE LINER AND THEN THE WALL. A SPECIAL DRAIN TROUGH WAS INSTALLED TO DIVERT LEAKAGE TO THE WASTE HOLDUP TANK. AN ESTIMATED 240 GEL. WAS LEAKED INTO THE GROUND BEFORE INSTALLATION OF THE TROUGH. THE LINER CANNOT BE REPAIRED AT THIS TIME BECAUSE OF SPENT FUEL STORAGE REQUIREMENTS. IF MODIFICATIONS ARE MADE TO THE STORAGE SYSTEM, LINER REPAIR WILL BE CONSIDERED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 4 (PWR) • LEAK • STEEL LINER • STORAGE CONTAINER • FUEL STORAGE • RADIOACTIVITY RELEASE • FAILURE, EQUIPMENT • WATER

108844

BORON CONCENTRATION IN BORON INJECTION TANK LOW AT TURKEY POINT 4

FLORIDA POWER & LIGHT CO., MIAMI, FL

3 PGS, LR 251-75-12 TO NRC OFFICE OF I & E, REGION II, DEC. 22, 1975, DOCKET 50-251, TYPE--PWR, NRC--WEST., AE--BECHTEL

CAUSE - VALVE LEAKAGE. WHILE OPERATING AT 1308 POWER, THE BORON CONCENTRATION IN THE BORON INJECTION TANK WAS FOUND TO BE 15,000 PPM WHICH IS BELOW THE 20,000 PPM LIMIT. APPARENTLY, UNIT 3 BIT WAS DILUTED WITH WATER DURING ACCUMULATOR ZACLEAKAGE TESTS. THIS RESULTED IN DILUTION OF BORON ACID STORAGE TANK 8 AND THEN UNIT 4 BIT. ONE VALVE BETWEEN THE ACCUMULATOR AND THE BIT WAS LEAKING AND THE OTHER WAS FOUND TO BE OPEN ABOUT ONE TURN. A LOAD REDUCTION WAS INITIATED UNTIL THE CONCENTRATION WAS INCREASED ABOVE 20,000 PPM IN THE BIT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 4 (PWR) • CONCENTRATION • POISON, SOLUBLE • STORAGE CONTAINER • SAFETY INJECTION • VALVES • LEAK • FAILURE, EQUIPMENT • FAILURE, MAINTENANCE ERROR

105943

SPENT FUEL PIT COOLING PUMPS FAIL AT TURKEY POINT 3 AND 4

FLORIDA POWER & LIGHT COMPANY, MIAMI

2 PGS, LTR TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, AUG. 18, 1975, DOCKETS 50-250/251, TYPE--PWR, NRC--WEST., AE--BECHTEL

CAUSE - CAVITATION. DURING THE PAST 4 MONTHS, UNIT 3 SPENT FUEL PIT COOLING PUMP HAS MALFUNCTIONED TWICE AND UNIT 4 PUMP MALFUNCTIONED THREE TIMES. FAILURES OCCURRED TO RADIAL AND THRUST BEARINGS AND THE PUMP SHAFT. THE EXACT CAUSE IS UNKNOWN. IT IS SUSPECTED THAT EXCESSIVE INTERNAL STRESSES HAVE BEEN CREATED BY PUMP CAVITATION. THE POSITION OF THE SYSTEM DISCHARGE VALVE HAS BEEN ADMINISTRATIVELY REDUCED FROM 50% TO 25% OPEN. REDUNDANT PUMPS ARE BEING INSTALLED IN EACH COOLING SYSTEM.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TURKEY POINT 3 (PWR) • TURKEY POINT 4 (PWR) • PUMPS • COOLING • STORAGE CONTAINER • FUEL STORAGE • FAILURE, DESIGN ERROR • HYDRAULIC EFFECT • INTAKE • BEARING

099379

CONCRETE FORM FALLS ON ROOF SLAB OF CONTROL BUILDING AT WATTS BAR 1 AND 2

TVA, CHATTANOOGA, TENN.

5 PAGES, LETTER WITH FINAL INCIDENT REPORT TO DIRECTORATE OF REGULATORY OPERATIONS (AEC), JANUARY 15, 1975, DOCKET 50-390/391, TYPE--PWR, NRC--WEST., AE--TVA

CAUSE - DEFECTIVE WELD SPLICE. A SECTION OF THE CONTROL BUILDING ROOF FELL DURING CONCRETE PLACEMENT. ABOUT 112 CU YD OF AN ESTIMATED 320 CU YD HAD BEEN PLACED. THE CAUSE WAS FAILURE OF THE BAR JOISTS USED FOR SUPPORT OF THE CONCRETE ROOF FORMS. A BUTT WELD SPLICE IN A BOTTOM CHORD ANGLE OF 1 OF THE 40 BAR JOISTS FAILED. INSPECTION SHOWED ONLY MINOR STRUCTURAL DAMAGE TO THE BUILDING. IT WILL BE REPAIRED. BETTER CONTROL OF FORMS WILL BE REQUIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONCRETE • STRESS • WELDS • BUILDING • FAILURE, DESIGN ERROR • SUPPORT STRUCTURE • INSTALLATION • CONSTRUCTION • WATTS BAR 1 (PWR) • WATTS BAR 2 (PWR)

104211

FAILURE TO MEET RADIATION EXPOSURE RECORD REQUIREMENTS AT YANKEE ROSE

YANKEE ATOMIC ELECTRIC COMPANY, MASS.

2 PAGES, LETTER TO NRC DIRECTORATE OF REGULATORY OPERATIONS, JAN. 9, 1975, DOCKET 50-29, TYPE--PWR, NRC--

103411 ACQUINCECO
WEST., AE--STONE C WEBSTER

CAUSE - ADMINISTRATIVE ERROR. A MAINTENANCE WORKER INCURRED A WHOLE BODY EXTERNAL EXPOSURE IN EXCESS OF 1.25 REM FROM THE THIRD QUARTER OF 1974 BEFORE THE PREVIOUS RADIATION EXPOSURE HISTORY WAS DOCUMENTED ON AEC FORM NO. THE EXPOSURE CONTROL PROGRAM HAD BEEN SUCCESSFULLY CONDUCTED FOR OVER 6 YEARS. THE IMPORTANCE OF COMPLETE RECORD KEEPING HAS BEEN REITERATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

YANKEE NUCLE (PWR) • COMPLIANCE • PERSONNEL EXPOSURE, RADIATION • RADIATION EXPOSURE, RECORD KEEPING • FAILURE, ADMINISTRATIVE CONTROL

103468

SIX WORKERS EXPOSED TO AIRBORNE RADIOACTIVE MATERIAL AT YANKEE-ROWE
YANKEE ATOMIC ELECTRIC COMPANY, MASS.
10 PAGES, LETTER WITH AN REPORT 75/2 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, JANUARY 20, 1975. JACKET 50-29, TYPE--PWR, REG--WEST., AE--STONE C WEBSTER

CAUSE - MISUNDERSTANDING OF PROCEDURES. SIX WORKERS WERE EXPOSED TO AIRBORNE RADIOACTIVE MATERIAL IN EXCESS OF LIMITS DURING INSPECTION AND REPAIR OF STEAM GENERATOR RIBBING. CALCULATED EXPOSURES RANGED FROM 1.7 TO 10.0 TIME LIMITS WITH NO CREDIT FOR THE RESPIRATORY PROTECTION DEVICES THAT WERE WORN. RESULTS OF MEASUREMENTS INDICATED THAT THE PROTECTION FACTORS RANGED FROM 5.5 TO 22 FOR THE FACE MASKS USED. THESE OVEREXPOSURES RESULTED FROM A MISINTERPRETATION OF PREVIOUS WORK PRACTICES. FULL ENVIRONMENTAL ISOLATION SHOULD HAVE BEEN USED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

AIRBORNE RELEASE • INHALATION • MAINTENANCE AND REPAIR • YANKEE NUCLE (PWR) • PERSONNEL EXPOSURE, RADIATION • FAILURE, MAINTENANCE ERROR • STEAM GENERATION • COMMUNICATION

103507

MONTHLY CHECK OF SI INITIATION SWITCHES NOT PERFORMED AT YANKEE ROWE
YANKEE ATOMIC ELECTRIC COMPANY, MASS.
5 PAGES, LETTER WITH AN REPORT 75/2 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, MARCH 5, 1975. JACKET 50-29, TYPE--PWR, REG--WEST., AE--STONE C WEBSTER

CAUSE - MISUNDERSTANDING. MONTHLY CHECK OF 2 SI INITIATION AND PRESSURE SWITCHES WAS MISSED FOR A MONTH. TECH SPECS HAD BEEN REVISED TO REQUIRE THIS CHECK. PERSONNEL ASSUMED THE TESTS WERE NOT REQUIRED UNTIL APPROVED PROCEDURES WERE ISSUED. THEY WERE INSTRUCTED THAT TECH SPECS APPLY WHEN ISSUED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

TESTING • YANKEE NUCLE (PWR) • FAILURE, ADMINISTRATIVE CONTROL • TEST INTERVAL • COMMUNICATION • SENSORS, PRESSURE

103580

CHARGING LINE FLOW TRANSMITTER LINE LEAKS AT YANKEE ROWE
YANKEE ATOMIC ELECTRIC COMPANY, MASS.
2 PAGES, LETTER WITH AN REPORT 75/1 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, MARCH 5, 1975. JACKET 50-29, TYPE--PWR, REG--WEST., AE--STONE C WEBSTER

CAUSE - WELD DEFECT. A MINOR LEAK DEVELOPED ON THE LOW PRESSURE INLET NIPPLE OF THE CHARGING LINE FLOW TRANSMITTER. THE WELD ON THE INLET NIPPLE TO A BARON MODEL 244 D/P TRANSMITTER FAILED. IT WAS REPAIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, PIPE • WELDS • YANKEE NUCLE (PWR) • LEAK • FRESHWATER • SENSORS, PRESSURE • PIPES AND PIPE FITTINGS

103586

FLOW INDICATOR SENSING LINE LEAKS AT YANKEE ROWE
YANKEE ATOMIC ELECTRIC COMPANY, MASS.
2 PAGES, LETTER WITH AN REPORT 75/3 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 1, MARCH 5, 1975. JACKET 50-29, TYPE--PWR, REG--WEST., AE--STONE C WEBSTER

CAUSE - WELD DEFECT. A MINOR LEAK WAS FOUND ON THE SHUTDOWN COOLING SYSTEM FLOW INDICATOR SENSING LINE. A WELD ON A SOCKET FITTING HAD FAILED. THE WELD WAS REPAIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, PIPE • WELDS • YANKEE NUCLE (PWR) • SHUTDOWN COOLING SYSTEM • LEAK • PIPES AND PIPE FITTINGS • SENSORS, FLOW

100891
SHUTDOWN COOLING FLOW INDICATOR SENSING LINE LEAK AT YANKEE ROWE
YANKEE ATOMIC ELECTRIC CO., MASS.
2 PAGES, LETTER WITH ACR REPORT 75/4 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, MARCH 21, 1975, DOCKET 50-29, TYPE--PWR, MFG--WEST., AE--STONE & WEBSTER

CAUSE - WELD FAILURE. DURING INSPECTION OF WORK IN THE VICINITY OF THE SHUTDOWN COOLING FLOW INDICATOR, A SUPERVISOR OBSERVED A BUILDUP OF BURON CRYSTALS ON AN ELMO LEADING TO THE INDICATOR. A SMALL LEAK WAS FOUND AT THE WELD ON THE SENSING LINE ELBO. THE INSTRUMENT PIPING WILL BE REPLACED. THE SHUTDOWN COOLING SYSTEM IS ISOLATED AND DEPRESSURIZED DURING NORMAL PLANT OPERATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, PIPE • WELDS • YANKEE ROWE (PWR) • SHUTDOWN COOLING SYSTEM • LEAK • PIPES AND PIPE FITTINGS

102298
EMERGENCY DIESEL GENERATOR DC CONTROL CIRCUIT FAILS AT YANKEE ROWE
YANKEE ATOMIC ELECTRIC COMPANY, MASS.
3 PAGES, LETTER WITH ACR 75/5 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, APRIL 23, 1975, DOCKET 50-29, TYPE--PWR, MFG--WEST., AE--STONE & WEBSTER

CAUSE - SHORT CIRCUIT WITHIN THE PILOT LIGHT. THE OPERATOR OBSERVED THAT THE NO. 3 DIESEL GENERATOR DC CONTROL CIRCUIT PILOT LIGHT LOCATED OUTSIDE THE DIESEL CUBICAL WAS OUT. IT WAS FUSED TO ITS SOCKET. AN ATTEMPT TO START THE DIESEL FAILED. A SHORT CIRCUIT WITHIN THE PILOT LIGHT BLEN THE FUSE IN THE DC CONTROL CIRCUIT. THE DEFECTIVE LIGHT AND HOLDER WERE REPLACED AND NEW FUSES INSTALLED. THE DIESEL OPERATED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

YANKEE ROWE (PWR) • GENERATOR, DIESEL • ENGINES, INTERNAL COMBUSTION • INSTRUMENT, PROTECTIVE • CONTROL SYSTEM • FAILURE, INSTRUMENT • EMERGENCY POWER, ELECTRIC

102544
DIESEL GENERATOR DC CONTROL CIRCUIT FAILS AT YANKEE ROWE
YANKEE ATOMIC ELECTRIC COMPANY, MASS.
3 PAGES, LETTER WITH ACR 75-5 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION 1, APRIL 23, 1975, DOCKET 50-29, TYPE--PWR, MFG--WEST., AE--STONE & WEBSTER

CAUSE - SHORT CIRCUIT IN PILOT LIGHT. WHILE THE UNIT WAS OPERATING AT 185 MWE, THE OPERATOR OBSERVED THAT DIESEL GENERATOR 3 DC CONTROL CIRCUIT PILOT LIGHT WAS OUT. THE BULB WAS FUSED TO ITS SOCKET. THE DIESEL FAILED TO START. THE APPARENT CAUSE WAS A SHORT CIRCUIT WITHIN THE PILOT LIGHT RESULTING IN A BLOWN FUSE IN THE DC CONTROL CIRCUIT. THE DEFECTIVE PILOT LIGHT AND HOLDER WERE REPLACED AND NEW FUSES INSTALLED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

YANKEE ROWE (PWR) • GENERATOR, DIESEL • ENGINES, INTERNAL COMBUSTION • CONTROL SYSTEM • FAILURE, COMPONENT • INSTRUMENT, PROTECTIVE • EMERGENCY POWER, ELECTRIC • INSTRUMENT, ABNORMAL INDICATION

104078
NRC REQUESTS REVIEW OF MSIV'S AT YANKEE ROWE
U.S. NUCLEAR REGULATORY COMMISSION
4 PAGES, LETTER TO YANKEE ATOMIC ELECTRIC CO., MAY 23, 1975, DOCKET 50-29, TYPE--PWR, MFG--WEST., AE--STONE & WEBSTER

AS A RESULT OF A STUDY OF THE ABILITY OF SWING-CHECK TYPE MSIV'S TO WITHSTAND THE DYNAMIC FORCES ASSOCIATED WITH RAPID CLOSURE, IT WAS DETERMINED THAT IN SOME CASES THERE MAY BE A NEED TO UPGRADE BOTH THE MATERIALS AND THE DESIGN OF THE LARGER VALVES. A Y-PATTERN GLOBE DESIGN MSIV HAS ALSO EXPERIENCED FAILURE DURING ROUTINE PLANT STARTUP. NRC REQUESTS ASSURANCE FROM LICENSEES THAT APPROPRIATE REMEDIAL MEASURES HAVE BEEN OR WILL BE TAKEN FOR THESE TYPES OF VALVES. THIS APPLIES TO ALL PWR STATIONS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

YANKEE ROWE (PWR) • BACKFIT • VALVES • VALVE, CHECK • CONTAINMENT ISOLATION • MAIN COOLING SYSTEM • STEAM • FAILURE, DESIGN ERROR • MODIFICATION • OPERATING EXPERIENCE • AGENCY, NRC

094241
SET POINT DRIFT IN PRESSURE SWITCH AT YANKEE ROWE
YANKEE ATOMIC ELECTRIC COMPANY
2 PAGES, LETTER TO DIRECTOR, U.S. NUCLEAR REGULATORY COMMISSION, REGION 1 (AEC), JULY 5, 1974, DOCKET 50-29, TYPE--PWR, MFG--WEST., AE--STONE & WEBSTER

094241 *CONTINUED*

CAUSE - INSTRUMENT DRIFT. DURING TESTING WHILE THE REACTOR WAS SHUTDOWN FOR REFUELING, THE LOW PRESSURE SWAMP SET POINT FOR THE PRESSURIZER PRESSURE CHANNEL WAS FOUND TO BE 20 PSI BELOW THE 1000 PSIG LIMIT. IT HAD BEEN SET TOO CLOSE TO THE LIMIT TO ALLOW FOR INSTRUMENT DRIFT. THE SET POINT WAS READJUSTED TO 1030 PSIG.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

YANKEE NUH (PWR) + INSTRUMENT CALIBRATION + INSTRUMENT, SWITCH + PRESSURIZER + TEST, SYSTEM OPERABILITY + FAILURE, ADMINISTRATIVE CONTROL + SET POINT + DRIFT + CIRCUIT CLOSERS/INTERRUPTERS + SENSORS, PRESSURE

104810

VAPOR CONTAINER DRAIN LINE VALVE FAILS TO CLOSE AT YANKEE NUH

YANKEE ATOMIC ELECTRIC COMPANY, NUH, MASS.

2 PGS, LTR W/ADR 75-6 TO NRC OFFICE OF I & E, REGION I, AUG. 4, 1975, DOCKET 50-29, TYPE--PWR, MFG--WEST., AE--STONE & WEBSTER

CAUSE - CORROSION ON LINNAGE. DURING PREPARATION FOR A LEAK TEST WITH THE REACTOR AT FULL POWER, A VAPOR CONTAINER DRAIN LINE TRIP VALVE FAILED TO GO FULLY CLOSED. FAILURE OF THE FISHER GOVERNOR CO. TYPE 647L VALVE WAS DUE TO CORROSION BUILDUP BETWEEN THE VALVE DISC LINNAGE AND THE PIN HINDING THE LINNAGE TO THE VALVE BODY. THE VALVE WAS REPAIRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

YANKEE NUH (PWR) + VALVES + CONTAINMENT ISOLATION + TEST, SYSTEM OPERABILITY + FAILURE, EQUIPMENT + CORROSION + FAILURE, MAINTENANCE ERROR

104995

WELD IN CHARGING PUMP RELIEF VALVE NOZZLE CRACKS AT YANKEE NUH

YANKEE ATOMIC ELECTRIC COMPANY, NUH, MASS.

2 PGS, LTR W/ADR 75-37 TO NRC OFFICE OF INSPECTION & ENFORCEMENT, REGION I, AUG. 15, 1975, DOCKET 50-29, TYPE--PWR, MFG--WEST., AE--STONE & WEBSTER

CAUSE - VIBRATION. WHILE THE REACTOR WAS OPERATING AT 90% POWER, THE AUXILIARY OPERATOR NOTED A SLIGHT WEEP IN CHARGING PUMP 3 RELIEF VALVE NOZZLE JUST ABOVE THE FLANGE CONNECTION TO THE DISCHARGE PIPING. CHARGING WAS TRANSFERRED TO PUMP 1. THE FLANGED RELIEF VALVE WAS REPLACED. THE NOZZLE TO FLANGE WELD CRACK WAS ATTRIBUTED TO VIBRATION CAUSED BY THE POSITIVE DISPLACEMENT CHARGING PUMPS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

YANKEE NUH (PWR) + VALVES + WELDS + PRESSURE RELIEF + FEEDWATER + LEAK + VIBRATION + FAILURE, PIPE + FAILURE, DESIGN ERROR

105552

VAPOR CONTAINER LEAKAGE EXCEEDS LIMITS AT YANKEE NUH

YANKEE ATOMIC ELECTRIC COMPANY, NUH, MASS.

2 PGS, LTR W/ADR 75-38 TO NRC OFFICE OF I & E, REGION I, AUG. 22, 1975, DOCKET 50-29, TYPE--PWR, MFG--WEST., AE--STONE & WEBSTER

CAUSE - IMPROPERLY INSTALLED BLIND FLANGE. DURING OPERATION AT 90% POWER, CONTAINMENT LEAKAGE MONITORING DATA INDICATED VAPOR CONTAINER LEAKAGE IN EXCESS OF CALCULATED ALLOWABLE LIMITS. AN UNDESIRABLE SHUTDOWN TO COLD CONDITION WAS COMMENCED. THE SOURCE OF LEAKAGE WAS TRACED TO AN IMPROPERLY INSTALLED BLIND FLANGE ON THE VAPOR CONTAINMENT LOW PRESSURE VENT HEADER IN THE UPPER PIPE CHASE. THE LEAK WAS ISOLATED. TOTAL ACTIVITY RELEASED WAS 18.045 MICROCURIRES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

YANKEE NUH (PWR) + LEAK RATE + CONTAINMENT + CONTAINMENT INTEGRITY + CONTAINMENT LEAK MONITOR + FAILURE, MAINTENANCE ERROR + FLANGE + LEAK + AIRBORNE RELEASE + REACTOR SHUTDOWN

106300

DIESEL GENERATION CONTROL CIRCUIT FAILS AT YANKEE NUH

YANKEE ATOMIC ELECTRIC CO., MASS.

3 PGS, LETTER TO NRC DIRECTOR OF OFFICE OF INSPECTION AND ENFORCEMENT, REGION I, SEPT. 16, 1975, DOCKET 50-29, TYPE--PWR, MFG--WEST., AE--STONE & WEBSTER

CAUSE - SUPERVISORY LAMP FUSED TO SOCKET. DURING NORMAL COASTDOWN OPERATION, AN OPERATOR NOTED THAT DIESEL GENERATOR 1 CONTROL CIRCUIT SUPERVISORY LAMP WAS OUT. A CIRCUIT FUSE WAS BLOWN. THE LOCAL SUPERVISORY LAMP HAD FUSED INTO THE LAMP SOCKET DUE TO OVERHEATING. BECAUSE OF THE REPETITIVENESS OF THIS INCIDENT, LOCAL SUPERVISORY LAMPS AND SOCKETS MAY BE REPLACED WITH ONES OF A DIFFERENT DESIGN AND/OR VOLTAGE RATING. THE REACTOR WAS OPERATING AT 89% POWER AT THIS TIME.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

100300 *CONTINUED*
 YANKEE ROWE (PHR) * GENERATION, DIESEL * ENGINES, INTERNAL COMBUSTION * CONTROL SYSTEM * FAILURE, DESIGN
 ERROR * TEST, SYSTEM OPERABILITY * INDICATORS

100046
 VAPOR CONTAINER TRIP VALVE SOLENOIDS FAIL TO OPERATE AT YANKEE ROWE
 YANKEE ATOMIC ELECTRIC CO., ROWE, MASS.
 3 PGS, LTR W/REPORTABLE OCCURRENCE 50-29/75-11 TO NRC OFFICE OF I & E, REGION I, NOV. 21, 1975, DOCKET 50-29,
 TYPE--PHR, MFG--WEST., AE--STONE & WEBSTER

CAUSE - MEAN UN LATCHING MECHANISM. DURING A REFUELING TEST, 2 ASCO MODEL WPR 8310 F SOLENOID
 OPERATED VALVES FAILED TO OPERATE ON SIGNAL. THE LATCHING MECHANISM HAD WORK PROBABLY DUE TO
 VIBRATION. THESE VALVES DUMP AIR TO CAUSE A TRIP OF VARIOUS CONTAINMENT ISOLATION TRIP VALVES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

YANKEE ROWE (PHR) * VALVES * SOLENOID * CONTAINMENT ISOLATION * TEST, SYSTEM OPERABILITY * CONTAINMENT *
 FAILURE, EQUIPMENT * VIBRATION * REFUELING

100045
 STEAM GENERATOR TUBE DEGRADATION FOUND AT YANKEE ROWE
 YANKEE ATOMIC ELECTRIC CO., ROWE, MASS.
 3 PGS, LTR W/REPORTABLE OCCURRENCE 50-29/75-10 TO NRC OFFICE OF I & E, REGION I, NOV. 21, 1975, DOCKET 50-29,
 TYPE--PHR, MFG--WEST., AE--STONE & WEBSTER

CAUSE - USE OF PHOSPHATE CHEMISTRY CONTROL. DURING REFUELING OPERATIONS, A SCHEDULED EDGY CURRENT
 EXAMINATION OF TUBES IN STEAM GENERATORS 1 AND 4 FOUND INDICATIONS IN EXCESS OF LIMITS.
 DEGRADATION WAS NOTED IN AREAS BETWEEN THE TUBE SHEET AND 4 INCHES ABOVE THE TUBE SHEET OVER 15
 YEARS OF PLANT OPERATION. THE USE OF PHOSPHATE CHEMISTRY CONTROL IS SUSPECTED AS THE CAUSE. IN
 EACH STEAM GENERATOR, 5 TUBES SHOWED GREATER THAN 50% DEGRADATION. THEY WERE EXPLOSIVELY
 PLUGGED, AND 3 OTHER HAVING INDICATIONS GREATER THAN 40% WERE ALSO PLUGGED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

YANKEE ROWE (PHR) * TUBING * STEAM GENERATOR * FAILURE, TUBING * TEST, SYSTEM OPERABILITY * TEST,
 NONDESTRUCTIVE * REFUELING * WATER TREATMENT * PHOSPHATE

100506
 VAPOR CONTAINER ELECTRICAL PENETRATION WAS EXCESSIVE LEAKAGE AT YANKEE ROWE
 YANKEE ATOMIC ELECTRIC CO., ROWE, MASS.
 2 PGS, LTR W/AD RD 50-29/75-14 TO NRC OFFICE OF I & E, REGION I, DEC. 8, 1975, DOCKET 50-29, TYPE--PHR, MFG--
 WEST., AE--STONE & WEBSTER

CAUSE - CRACKED GLAND SEAL NUT. DURING AN ELECTRICAL PENETRATION TEST WITH THE UNIT SHUT DOWN FOR
 REFUELING, EXCESSIVE OUTWARD LEAKAGE WAS DETECTED FROM PENETRATION 14 IN BULB 10 OF THE VAPOR
 CONTAINER. A GENERAL CABLE CORP. GLAND SEAL NUT FOR THE MINERAL INSULATED CABLE WAS FOUND TO
 BE CRACKED. IT WAS REPLACED AND RETESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

YANKEE ROWE (PHR) * LEAK RATE * CONTAINMENT PENETRATION, ELECTRICAL * TEST, SYSTEM OPERABILITY * TEST, LEAK
 RATE * REFUELING * FAILURE, COMPONENT * SEAL

100529
 HYDRAULIC SHOCK SUPPRESSORS FAIL TO MEET CRITERIA AT YANKEE ROWE
 YANKEE ATOMIC ELECTRIC CO., ROWE, MASS.
 2 PGS, LTR W/AD RD 50-29/75-15 TO NRC OFFICE OF I & E, REGION I, DEC. 8, 1975, DOCKET 50-29, TYPE--PHR, MFG--
 WEST., AE--STONE & WEBSTER

CAUSE - NOT STATED. DURING TESTING OF THE HYDRAULIC SHOCK SUPPRESSORS BY THE MANUFACTURER FOR
 PROPER STROKE, LOCK-UP, AND BLEED, EIGHT 11.5 INCH BORE, 5 INCH STROKE, GRINNELL, FIG 2001 UNITS
 FAILED TO MEET THE ACCEPTANCE CRITERIA. ALL WERE REPLACED WITH SIMILAR SUPPRESSORS THAT HAD
 BEEN SUCCESSFULLY TESTED. THE REACTOR WAS IN A REFUELING OUTAGE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

YANKEE ROWE (PHR) * SHOCK ABSORBER * SUPPORT STRUCTURE * PIPES AND PIPE FITTINGS * TEST, SYSTEM OPERABILITY *
 REFUELING

100846
 SET POINT DRIFT IN LEVEL SCRAM INSTRUMENT AT YANKEE ROWE
 YANKEE ATOMIC ELECTRIC CO., ROWE, MA
 2 PGS, LTR W/AD 50-29/75-12 TO NRC OFFICE OF I & E, REGION I, DEC. 12, 1975, DOCKET 50-29, TYPE--PHR, MFG--

108844 WESTINGHOUSE
WEST., AE--STONE & WEBSTER

CAUSE - INSTRUMENT DRIFT. DURING A REFUELING CALIBRATION OF THE PRESSURIZER WIDE RANGE LEVEL INSTRUMENT, THE BISTABLE SET POINT WAS FOUND TO BE 203 INCHES. THE LIMIT IS 200 INCHES. THIS WAS ATTRIBUTED TO INSTRUMENT DRIFT. THE WESTINGHOUSE 9270633, S4. 1, STANDARD BISTABLE ASSEMBLY WAS RECALIBRATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

YANKEE NUCLE (PWR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SENSORS, LEVEL • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT • SET POINT • DRIFT • REACTOR SAFETY SYSTEM • PRESSURIZER • REFUELING

108843
VAPOR CONTAINER TRIP VALVE LEAKS EXCESSIVELY AT YANKEE NUCLE
YANKEE ATOMIC ELECTRIC CO., ROCHE, MA
2 PGS, LTR W/NO 50-29775-10 TO NRC OFFICE OF I & E, REGION 1, DEC. 12, 1975, DOCKET 50-29, TYPE--PWR, MFG--
WEST., AE--STONE & WEBSTER

CAUSE - SEATING SURFACE DEGRADATION. DURING REFUELING TYPE C CONTAINMENT ISOLATION VALVE TESTING, EXCESSIVE LEAKAGE WAS DETECTED FROM THE VAPOR CONTAINER HEATING SYSTEM RETURN HEATER ISOLATION TRIP VALVE. THE 4 INCH, ASA 150 PASON METAL VALVE SEATING SURFACE HAD DEGRADED. THE VALVE WAS REPAIRSHEATHED AND RETESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

YANKEE NUCLE (PWR) • VALVES • CONTAINMENT ISOLATION • TEST, SYSTEM OPERABILITY • FAILURE, EQUIPMENT • LEAK RATE • CONTAINMENT • HEATERS • REFUELING • TEST, LEAK RATE

109198
SAFETY INJECTION ACCUMULATOR SOLENOID RELIEF VALVE FAILS AT YANKEE NUCLE
YANKEE ATOMIC ELECTRIC CO., ROCHE, MA
2 PGS, LTR W/NO 50-29775-13 TO NRC OFFICE OF I & E, REGION 1, DEC. 19, 1975, DOCKET 50-29, TYPE--PWR, MFG--
WEST., AE--STONE & WEBSTER

CAUSE - OPEN HOLDING COIL. DURING REFUELING OPERATION, A TEST ON THE SAFETY INJECTION ACCUMULATOR LEVEL SWITCHES REVEALED THAT AN ACCUMULATOR PILOT OPERATED RELIEF SOLENOID VALVE FAILED TO OPEN WHEN REQUIRED. THE AUTOMATIC VALVE CO 1/4 INCH, 500 PSID, 3000 PSI MI 31000 SOLENOID OPERATED VALVE HAD AN OPEN HOLDING COIL. THE FAILED SOLENOID WAS REPLACED IN KIND AND TESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

YANKEE NUCLE (PWR) • VALVES • SOLENOID • SAFETY INJECTION • TEST, SYSTEM OPERABILITY • FAILURE, COMPONENT • REFUELING • ACCUMULATORS

C59102
CRACKED MOTOR HOUSING FOUND ON ISOLATION VALVE AT ZION 1
COMMONWEALTH EDISON, ILLINOIS
3 PAGES, LETTER WITH NO REPORT 75/1 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, JANUARY 9, 1975, DOCKET 50-295, TYPE--PWR, MFG--WEST., AE--SGT & LUNDY

CAUSE - UNKNOWN. DURING MAINTENANCE WORK IN THE AREA, A CRACK WAS FOUND IN THE STATOR SECTION OF THE MOTOR HOUSING FOR A FEEDWATER ISOLATION VALVE. THE CRACK WAS 6 INCHES LONG ON THE CIRCUMFERENCE OF THE HOUSING. THE CAUSE IS UNKNOWN. THE HOUSING WAS BANDAGED TO PREVENT FURTHER PROPAGATION OF THE CRACK. IT WILL BE REPLACED DURING THE SCHEDULED OUTAGE IN FEBRUARY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT • CONTAINMENT ISOLATION • FLAN • ZION 1 (PWR) • FEEDWATER • VALVE OPERATORS • MOTORS

C93208
DIESEL GENERATOR FAILS TO DEVELOP VOLTAGE AT ZION 1
COMMONWEALTH EDISON COMPANY, ILLINOIS
3 PAGES, LETTER TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, JANUARY 28, 1975, DOCKET 50-295, TYPE--
PWR, MFG--WEST., AE--SGT & LUNDY

CAUSE - SHORT IN EXCITATION CURRENT LEADS. DURING TESTING WITH THE REACTOR AT 70% POWER, DIESEL GENERATOR 1B STARTED AND OBTAINED SPEED BUT FAILED TO DEVELOP VOLTAGE. A GROUND SHORT HAD OCCURRED IN THE LEADS CARRYING EXCITATION CURRENT FROM THE BRUSHLESS EXCITER TO THE GENERATOR FIELD. SHORTING RESULTED FROM CHAFING OF THE INSULATION ON THE LEADS WHERE THEY PENETRATE THE MOTOR INDOOR. LEADS MADE A 90 DEGREE BEND AND ENTERED THE SQUARE EDGE PENETRATION. THE ROTOR PENETRATION WAS REMOVED BY GRINDING. DAMAGED CABLES WERE REPLACED. BRAIDED FIBERGLASS SHEATHING WAS ADDED IN THE FAILURE AREA. THE OTHER DIESELS WILL ALSO BE MODIFIED.

C93506 CONTAINMENT
 AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MODIFICATION + TEST, SYSTEM OPERABILITY + FAILURE, DESIGN ERROR + DAMAGE + ZION 1 (PWR) + INSULATION + FAILURE, COMMON MODE + ENGINES, INTERNAL COMBUSTION + GENERATOR, DIESEL

C93601
 UNPLANNED RELEASE OF GAS FROM THE CONTAINMENT AT ZION 1
 COMMONWEALTH EDISON COMPANY, ILLINOIS
 3 PAGES, LETTER WITH AQ REPORT 74/51 TO AEC, REGION 3, JANUARY 30, 1975, DOCKET 50-295, TYPE--PWR, MFG--WEST., AE--SGT & LUNDY

CAUSE - EXHAUST FAN DAMPER LEAKAGE. WHILE PERFORMING THE VALVE LINEUP FOR THE HYDROGEN RECOMBINED PREOPERATIONAL TEST WITH THE REACTOR AT 85% POWER, THE CONTAINMENT PURGE EXHAUST VALVES WERE OPENED. CONTAINMENT PRESSURE DROPPED FROM 0 TO 0 INCHES OF WATER. THE VALVES WERE CLOSED. THE OUTLET DAMPERS ON THE PURGE EXHAUST FAN WERE NOT LEAK TIGHT. CONTAINMENT AIR ESCAPED THROUGH THE DAMPERS TO THE VENT STACK. RELEASE RATES WERE NOT ENTERED. THIS LEAKAGE HAD NOT BEEN ANTICIPATED IN THE PROCEDURES. TEST PROCEDURES WILL BE MODIFIED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

AIRBORNE RELEASE + CONTAINMENT + PROCEDURES AND MANUALS + VENTILATION SYSTEM + TEST, SYSTEM OPERABILITY + FAILURE, ADMINISTRATIVE CONTROL + LEAK + ZION 1 (PWR) + BLUENERS

C99677
 HEATING WATER ISOLATION VALVE FAILS TO CLOSE AT ZION 1
 COMMONWEALTH EDISON, ILLINOIS
 3 PAGES, LETTER WITH AQ REPORT 75/3 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, FEBRUARY 12, 1975, DOCKET 50-295, TYPE--PWR, MFG--WEST., AE--SGT & LUNDY

CAUSE - SOLENOID VALVE STICKING. DURING TESTING WITH THE REACTOR IN HOT SHUTDOWN, A HEATING WATER ISOLATION VALVE FAILED TO CLOSE. THE SOLENOID VALVE SUPPLYING CONTROL AIR HUNG UP. THE FAILURE MECHANISM IS UNKNOWN AT THIS TIME. THE SOLENOID VALVE WILL BE ANALYZED. IT WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTAINMENT + FAILURE, EQUIPMENT + CONTAINMENT ISOLATION + TEST, SYSTEM OPERABILITY + ZION 1 (PWR) + SOLENOID + VALVES + HEATERS

C99676
 STEAM GENERATOR BLOWDOWN SAMPLE VALVE FAILS TO CLOSE AT ZION 1
 COMMONWEALTH EDISON COMPANY, ILLINOIS
 3 PAGES, LETTER WITH AQ REPORT 75/3 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, FEBRUARY 12, 1975, DOCKET 50-295, TYPE--PWR, MFG--WEST., AE--SGT & LUNDY

CAUSE - SOLENOID VALVE STICKING. DURING TESTING WITH THE REACTOR IN HOT SHUTDOWN, A STEAM GENERATOR BLOWDOWN SAMPLE VALVE FAILED TO CLOSE. THE SOLENOID VALVE SUPPLYING CONTROL AIR TO THE ISOLATION VALVE HUNG UP. THE FAILURE MECHANISM IS UNKNOWN AT THIS TIME. THE SOLENOID VALVE WILL BE ANALYZED. IT WAS REPLACED. A TRENDDING PROGRAM HAS BEEN ISSUED FOR SOLENOID VALVE FAILURES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, EQUIPMENT + SAMPLING + TEST, SYSTEM OPERABILITY + COOLANT PURIFICATION SYSTEM + STEAM GENERATOR + ZION 1 (PWR) + SOLENOID + VALVES

C99716
 CONTAINMENT ISOLATION VALVE FAILS TO CLOSE AT ZION 1
 COMMONWEALTH EDISON COMPANY, ILLINOIS
 3 PAGES, LETTER WITH AQ REPORT 75/3 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, FEBRUARY 16, 1975, DOCKET 50-295, TYPE--PWR, MFG--WEST., AE--SGT & LUNDY

CAUSE - STICKING SOLENOID VALVE. WHILE THE UNIT WAS IN HOT SHUTDOWN, 1 OF THE 2 CONTAINMENT ISOLATION VALVES FOR SERVICE AIR FAILED TO CLOSE WHEN THE SOLENOID WAS DE-ENERGIZED. THE SOLENOID VALVE SUPPLYING CONTROL AIR TO THE ISOLATION VALVE HUNG UP. THE FAILURE MECHANISM IS UNKNOWN AT THIS TIME. TWO PREVIOUS FAILURES ARE BEING ANALYZED. THE ISOLATION VALVE IS CLOSED AND WILL BE REPLACED WHEN A NEW SOLENOID VALVE IS AVAILABLE. THE SOLENOID IS MANUFACTURED BY ASCO, CATALOG NUMBER M0X8320A26, 110 VAC.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, EQUIPMENT + CONTAINMENT ISOLATION + ZION 1 (PWR) + PNEUMATIC SYSTEM + SOLENOID + VALVES

100498
 SET POINT DRIFT IN STEAM GENERATOR LEVEL COMPARISON AT ZION 1
 COMMONWEALTH EDISON COMPANY, ILLINOIS
 1 PAGE, LETTER TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, FEBRUARY 22, 1975, DCKET 50-295, TYPE--
 PWR, MFG--WEST., AE--SGT & LUNDY

CAUSE - UNKNOWN. DURING TESTING WHILE THE REACTOR WAS OPERATING AT 84% POWER, A LU-LO STEAM
 GENERATOR LEVEL COMPARISON WAS FOUND TO TRIP 2.025% LOWER THAN THE SET POINT. OVERALL CHANNEL
 ACCURACY REQUIRED IS 1.5%. NO CAUSE FOR THE DRIFT WAS FOUND. THE MAGAN MODEL 113 SIGNAL
 COMPARISON WAS RECALIBRATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545, 108 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

INSTRUMENT CALIBRATION + FAILURE, INSTRUMENT + INSTRUMENT, SWITCH + TEST, SYSTEM OPERABILITY + STEAM GENERATOR
 + ZION 1 (PWR) + SET POINT + DRIFT + SENSORS, LEVEL

100492
 RADIATION MONITOR TAKEN OUT OF SERVICE WITHOUT CAUSE AT ZION 1
 COMMONWEALTH EDISON COMPANY, ILLINOIS
 1 PAGE, LETTER TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, MARCH 5, 1975, DCKET 50-295, TYPE--PWR,
 MFG--WEST., AE--SGT & LUNDY

CAUSE - OPERATOR ERROR. WHILE THE REACTOR WAS AT 63% POWER, A RADIATION MONITOR WAS ORDERED TO BE
 TAKEN OUT OF SERVICE FOR REPAIR. DUE TO OPERATOR ERROR 2 RADIATION MONITORS WERE TAKEN OUT OF
 SERVICE INSTEAD OF ONE. A PORTABLE MONITORING DEVICE WAS SET UP FOR THE DEFECTIVE UNIT. THE
 OPERABLE UNIT WAS PLACED BACK IN SERVICE WHEN THE REPAIR WAS DISCLOSED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545, 109 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

FAILURE, OPERATOR ERROR + VENTILATION SYSTEM + MONITORING SYSTEM, RADIATION + ZION 1 (PWR) + RADIATION MONITORS

100375
 YEARLY USE OF BOMIC ACID EXCEEDS LIMIT AT ZION 1
 COMMONWEALTH EDISON COMPANY, ILLINOIS
 2 PAGES, LETTER WITH AD REPORT 75/77 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, MARCH 6, 1975,
 DCKET 50-295, TYPE--PWR, MFG--WEST., AE--SGT & LUNDY

CAUSE - HIGH LEAKAGE RATE. THE ANNUAL USAGE OF BOMIC ACID FOR 1974 EXCEEDED THE TECH SPEC LIMIT.
 HIGH SOLIDATED WATER STREAMS ARE LEAKING INTO THE RAHWASTE SYSTEM. THE BOMIC ACID IS SHIPPED OFF
 SITE AS RADIOACTIVE WASTE. THE LEAK RATES FROM VALVES AND OTHER EQUIPMENT ARE HIGHER THAN
 ANTICIPATED. EQUIPMENT URBANS ARE BEING MODIFIED TO RETURN PART OF THIS LEAKAGE TO THE BOMIN
 RECYCLE SYSTEM. THE QUANTITY GIVEN IN THE TECH SPECS WAS INTENDED AS AN ESTIMATE BUT IS
 INTERPRETED AS A LIMIT.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545, 108 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

PURSON, SOLUBLE + WASTE TREATMENT + WASTE DISPOSAL, SOLID + FAILURE, DESIGN ERROR + LEAK + ZION 1 (PWR)

101421
 ZION STATION DIESEL GENERATOR PERFORMANCE
 COMMONWEALTH EDISON CO., ILLINOIS
 24 PAGES, LETTER WITH ATTACHMENTS TO NRC DIRECTORATE OF LICENSING, MARCH 7, 1975, DCKETS 50-295/304, TYPE--
 PWR, MFG--WEST., AE--SGT & LUNDY

REPORTS ON THE DIESEL GENERATOR CORRECTIVE ACTIONS AND REVISED TESTING PROGRAM. ONE ATTACHMENT
 LISTS ABNORMAL OCCURRENCES THROUGH JANUARY 1975 AND THE CORRECTIVE ACTION DIRECTLY RESULTING FROM
 THE FAILURES. ANOTHER ATTACHMENT IS THE PROCEDURE FOR THE TESTING PROGRAM AND REFLECTS THE
 STATIONS EXPERIENCE IN OPERATING, TROUBLESHOOTING, AND MAINTAINING THE FIVE (4000 KW) STANDBY
 DIESEL GENERATORS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545, 108 CENTS/PAGE -- MINIMUM
 CHARGE \$2.00

EMERGENCY POWER, ELECTRIC + PROCEDURES AND MANUALS + TESTING + RELIABILITY, SYSTEM + OPERATING EXPERIENCE +
 ZION 1 (PWR) + ZION 2 (PWR) + GENERATOR, DIESEL

102141
 CONTAINMENT PURGE VALVE LEAKAGE HIGH AT ZION 1
 COMMONWEALTH EDISON COMPANY, ILLINOIS
 3 PAGES, LETTER WITH AD REPORT 75/10 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, APRIL 2, 1975,
 DCKET 50-295, TYPE--PWR, MFG--WEST., AE--SGT & LUNDY

CAUSE - GASKET NOT SEALING. DURING TESTING ON THE CONTAINMENT PURGE EXHAUST ISOLATION VALVES, AN
 INNER VALVE WAS FOUND TO BE LEAKING. A SECTION OF THE RUBBER GASKET ON THE SEATING SURFACE WAS
 NOT TIGHTLY SEALING THE VALVE WHEN CLOSED. THE GASKET WAS ADJUSTED TO MINIMIZE LEAKAGE. THE

102141 CONTINUOUS
UNIT WAS IN COLO SHUTDOWN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTAINMENT + CONTAINMENT ISOLATION + VENTILATION SYSTEM + TEST, SYSTEM OPERABILITY + FAILURE, MAINTENANCE ERROR + SEAL + LEAK RATE + ZION 1 (PWR) + VALVES

102539
SURVEILLANCE OPTION COULD REDUCE SAFETY MARGIN AT ZION 1 AND 2
COMMONWEALTH EDISON COMPANY, ILLINOIS
2 PAGES, LETTER WITH AOR 75-12 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, APRIL 15, 1975, DOCKET 50-295/304.
TYPE--PWR, MFG--WEST., AE--SGT C LUNDY

CAUSE - DESIGN DEFICIENCY. A LETTER FROM WESTINGHOUSE STATED THAT A REVIEW OF THE SURVEILLANCE OPTION WHICH SUBSTITUTES ADDITIONAL AXIAL POWER DISTRIBUTION MEASUREMENT IN LIEU OF POWER REDUCTIONS REQUIRED BY CONSTANT AXIAL OFFSET CONTROL PROCEDURES LED TO THE CONCLUSION THAT THIS IS INCONSISTENT WITH THE DAB ANALYSIS BASIS. SINCE THIS OPTION MAY RESULT IN A REDUCTION IN THE SAFETY MARGIN SHOWN IN THE FSAR, A STANDING ORDER WAS ISSUED TO EXCLUDE ITS USE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 1 (PWR) + ZION 2 (PWR) + TESTING + POWER DISTRIBUTION + SAFETY MARGIN + FAILURE, DESIGN ERROR + MODIFICATION + REACTOR PHYSICS + HOT CHANNEL + REVIEW

103044
PRESSURE TRANSIENT IN MAIN COOLING SYSTEM AT ZION 1
COMMONWEALTH EDISON COMPANY, ILL.
3 PAGES, LETTER WITH AOR 75-12 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, JUNE 13, 1975, DOCKET 50-295.
TYPE--PWR, MFG--WEST., AE--SGT C LUNDY

CAUSE - FAILURE TO FOLLOW PROCEDURES. DURING A COLO SHUTDOWN UPON ISOLATING THE RHR SYSTEM FOR REPAIR, THE CENTRIFUGAL CHARGING PUMP WAS OVERLOADED AND NOT IMMEDIATELY SHUT OFF. THIS CAUSED THE ACS PRESSURE TO INCREASE FROM 100 TO 1100 PSIG WITHIN 10 MIN. THE CHARGING PUMP WAS SHUT OFF AND THE SYSTEM PRESSURE REDUCED TO 150 PSIG WITHIN 5 MINUTES. NO DAMAGE OCCURRED. OPERATOR ERROR WAS THE CAUSE. THE IMPORTANCE OF FOLLOWING PROCEDURES WAS STRESSED TO THOSE INVOLVED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 1 (PWR) + OPRESSURE TRANSIENT + MAIN COOLING SYSTEM + FAILURE, OPERATOR ERROR + MAINTENANCE AND REPAIR + PROCEDURES AND MANUALS

103075
REACTOR COOLANT RELEASE TO CONTAINMENT AT ZION 1
COMMONWEALTH EDISON COMPANY, ILL.
6 PAGES, LETTER WITH AOR 75-13,14,15 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, JUNE 16, 1975, DOCKET 50-295, TYPE--PWR, MFG--WEST., AE--SGT C LUNDY

CAUSE - DRAIN VALVE LEFT OPEN. WITH THE REACTOR AT HOT SHUTDOWN, REACTOR COOLANT LOOP D DRAIN VALVE WAS OPENED TO ESTABLISH EXCESS LETDOWN TO DEPRESSURIZE THE LETDOWN LINE BY AN ATTEMPT TO SET A WEeping RELIEF VALVE. THIS RESULTED IN RELEASING 5000 GAL OF COOLANT TO THE CONTAINMENT AND 143 CI OF AE TO THE ATMOSPHERE. THE CAUSE HAS BEEN TRACED TO A VALVE THAT HAD BEEN LEFT OPEN AFTER DRAINING THE REACTOR COOLANT LOOPS FOR PUMP MAINTENANCE. THE VALVE SHOULD HAVE BEEN ADDED TO THE VALVE LINEUP LIST WHEN OPENED OUT WAS NOT. WHEN THE LOOP WAS REFILLED THIS VALVE WAS NOT CLOSED. PROCEDURES WILL BE CHANGED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 1 (PWR) + RADIOACTIVITY RELEASE + MAIN COOLING SYSTEM + SHUTDOWN + REACTOR COOLANT + AIRBORNE RELEASE + FAILURE, ADMINISTRATIVE CONTROL + PROCEDURES AND MANUALS + FAILURE, MAINTENANCE ERROR

103095
SET POINT DRIFT IN FEEDFLOW TRANSMITTER AT ZION 1
COMMONWEALTH EDISON COMPANY, ZION, ILL.
2 PAGES, LETTER WITH AOR 75-16 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, JUNE 30, 1975, DOCKET 50-295, TYPE--PWR, MFG--WEST., AE--SGT C LUNDY

CAUSE - UNKNOWN. DURING TROUBLESHOOTING WITH THE REACTOR SHUT DOWN, A FEEDFLOW TRANSMITTER WAS FOUND OUT OF CALIBRATION BY +2.125% WHICH IS NON-CONSERVATIVE. THIS IS A REPEITIVE OCCURRENCE AND IS BEING INVESTIGATED. THE TRANSMITTER WAS RECALIBRATED AND RETURNED TO SERVICE. THIS IS A FISCHER PORTER MODEL NO. 130295005 S/N 7305550620 TRANSMITTER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

100895 CONTINUED

ZION 1 (PWR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SEISMIC, FLOW • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT • SET POINT • SHIFT • REACTOR SAFETY SYSTEM • FEEDWATER • ELECTRONIC FUNCTION UNITS

100903

COMPARATOR FOUND INOPERATIVE AT ZION 1

COMMONWEALTH EDISON COMPANY, ZION, ILL.

2 PGS. LTR W/AGR 75-17 TO NRC DIR. OF REGULATORY OPERATIONS, JULY 23, 1975, DOCKET 50-295, TYPE--PWR.
 RFO--WEST., AE--SGT & LUNDY

CAUSE - UNKNOWN. DURING A TEST WITH THE REACTOR AT 40% POWER, 1 OF THE 4 COMPARATORS WAS FOUND INOPERATIVE AND WOULD NOT TRIP. THE MODULE WAS REPLACED WITH A SPARE. THE CAUSE OF FAILURE HAS NOT BEEN DETERMINED. THE NUCLEAR MODEL NO. 411-302-002, S/N GJ 328, UNIT WILL BE REPAIRED WHEN TIME PERMITS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 1 (PWR) • INSTRUMENTS, MISC. • REACTOR SAFETY SYSTEM • TEST, SYSTEM OPERABILITY • FAILURE, INSTRUMENT

100926

INADVERTENT RELEASE OF RADIOACTIVE MATERIAL AT ZION 1

COMMONWEALTH EDISON COMPANY, ZION, ILL.

3 PGS. LTR W/AGR 75-18 TO NRC DIR. OF REGULATORY OPERATIONS, REGION 3, JULY 29, 1975, DOCKET 50-295, TYPE--PWR.
 RFO--WEST., AE--SGT & LUNDY

CAUSE - HOLD-UP TANK SEAM SPLIT. WHILE INCREASING POWER TO 95%, THE AUXILIARY BUILDING VENT STACK RADIATION MONITOR ALARMED HIGH. UNIT 1 HOLD-UP TANK HAD A SPLIT 5 AM. THE TANK WAS ISOLATED WITH THE NITROGEN HEATER IN SERVICE. THIS SEAM WAS DAMAGED WHEN A NEGATIVE PRESSURE CONDITION EXISTED DUE TO INSTRUMENTS OUT OF CALIBRATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 1 (PWR) • STORAGE CONTAINER • REACTOR COOLANT • PRESSURE, SUBATMOSPHERIC • PRESSURE, INTERNAL • FAILURE, MAINTENANCE ERROR • INSTRUMENT CALIBRATION • PATRUUNE RELEASE • FAILURE, EQUIPMENT

100727

MOLE WAS RELEASE RATE EXCEEDED LIPIT AT ZION 1

COMMONWEALTH EDISON COMPANY, ZION, ILL.

3 PGS. LTR W/AGR 75-20 TO NRC DIR. OF REGULATORY OPERATIONS, REGION 3, AUG. 29, 1975, DOCKET 50-295, TYPE--PWR.
 RFO--WEST., AE--SGT & LUNDY

CAUSE - FAILURE TO FOLLOW PROCEDURES. WHEN THE CWS MIXED BED DEMINERALIZER WAS VENTED TO THE AUXILIARY BUILDING EQUIPMENT DRAIN TANK, RADIOACTIVE GAS IN EXCESS OF 60000 UCI/SEC WAS RELEASED TO THE AUX. BUILDING VENT SYSTEM. PROCEDURES REQUIRE THE USE OF PRIMARY MAKEUP WATER FOR VENTING. THE SHIFT ENGINEER USED REACTOR COOLANT SYSTEM WATER. GAS WAS RELEASED THROUGH A LOOSE TANK MANWAY. A TOTAL OF 63.7 CI WAS RELEASED BEFORE VENTING WAS TERMINATED OF WHICH 1 CI WAS LONG LIVED NUCLEAR GASES. THE ENGINEER WAS INSTRUCTED TO USE PRIMARY WATER FOR VENTING. THE MANWAY WAS TIGHTENED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 1 (PWR) • PATRUUNE RELEASE • FAILURE, OPERATION ERROR • PROCEDURES AND MANUALS • COOLANT PURIFICATION SYSTEM

100728

CONTAINMENT SPRAY DIESEL FAILS TO START AT ZION 1

COMMONWEALTH EDISON COMPANY, ZION, ILL.

3 PGS. LTR W/AGR 75-21 TO NRC DIR. OF REGULATORY OPERATIONS, REGION 3, SEPT. 4, 1975, DOCKET 50-295, TYPE--PWR.
 RFO--WEST., AE--SGT & LUNDY

CAUSE - STARTING BATTERIES FAILED. DURING A TEST WITH THE UNIT OPERATING AT 95% POWER, THE CONTAINMENT SPRAY DIESEL FAILED TO START. THE DIESEL STARTING BATTERIES HAD FAILED BECAUSE VOLTAGE TO THE BATTERY CHARGER WAS TOO LOW TO MAINTAIN THE BATTERY. INPUT VOLTAGE TO THE CHARGER FLUCTUATES AS IT COMES FROM AN UNREGULATED POWER SUPPLY. THE OUTPUT VOLTAGE VARIES WITH INPUT VOLTAGE. THE BATTERY CHARGER TAPS WERE RAISED TO ALLOW FOR THIS OSCILLATION. THE BATTERIES WERE REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 1 (PWR) • REFINERS, INTERNAL COMBUSTION • CONTAINMENT SPRAY • TEST, SYSTEM OPERABILITY • FAILURE, DESIGN ERROR • BATTERIES & CHARGERS • ELECTRIC POWER

100906

100344 - CONTINUOUS
FOLLOW-UP REPORT ON COMPARTMENT FAILURE AT ZION 1
COMMONWEALTH EDISON, ILL.
3 PGS. LTR W/AT 50-295/75-24 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION III, SEPT. 4, 1975. DOCKET 50-295. TYPE--
PWR. NRC--WEST., AE--SGT C LUNDY

CAUSE - BAD SEMI-CONDUCTOR. DURING TESTING WITH THE REACTOR AT 40% POWER, 1 OF THE 4 COMPARTMENTS
WAS FOUND INOPERATIVE AND WOULD NOT TRIP AS REPORTED EARLIER. THE CAUSE WAS A BAD SEMI-CONDUCTOR
ON SUB 1. SUB 1 PROVIDES AN INVERTED SIGNAL TO A RELAXATION OSCILLATOR WHICH TRIGGERS THE
OUTPUT TRIP ON SUB 9. WITH SUB 1 HELD IN THE OPEN STATE THE TRIAC WOULD NEVER GET A TRIP
SIGNAL. THE TRANSISTOR WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

ZION 1 (PWR) + ELECTRONIC FUNCTION UNITS + TEST, SYSTEM OPERABILITY + FAILURE, COMPONENT + SOLID STATE DEVICE

102599
FOLLOW-UP REPORT ON MODIFICATIONS TO OFF GAS HOLD-UP TANKS AT ZION 1 AND 2
COMMONWEALTH EDISON, ILL.
9 PGS. LTR W/AT 50-295/75-24 AND 50-295/75-18 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION III, SEPT.
22, 1975. DOCKET 50-295/304. TYPE--PWR. NRC--WEST., AE--SGT C LUNDY

CAUSE - DESIGN DEFICIENCIES. ACCIDENTAL DEPRESSURIZATION OF THE HOLD-UP TANKS OCCURRED TWICE.
STEPS TAKEN TO PREVENT RECURRENCE ARE (1) OPERATING PRESSURE RANGE OF THE WASTE GAS SYSTEM WAS
RAISED BY 2 PSI. (2) WASTE GAS COMPRESSORS WILL AUTO-TRIP ON LOW VENT HEADR PRESSURE. (3)
ADDITIONAL ALARMS AND PRESSURE GAUGES WERE INSTALLED. (4) #2 SUPPLY PRESSURE CONTROL VALVE TO
THE HOLD-UP TANKS WAS RELOCATED NEARER THE TANKS. (5) GAS ISOLATION VALVES TO THE 3 HOLD-UP
TANKS HAVE BEEN LOCKED OPEN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

ZION 2 (PWR) + ZION 1 (PWR) + STORAGE CONTAINER + WASTE TREATMENT, GAS + WASTE TREATMENT, EQUIPMENT +
MODIFICATION + FAILURE, OPERATOR ERROR + WASTE STORAGE

102600
CONTAINMENT SPRAY RECIRCULATION VALVE FOUND OPEN AT ZION 1
COMMONWEALTH EDISON, ILL.
3 PGS. LTR W/AT 50-295/75-23 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION III, SEPT. 22, 1975. DOCKET
50-295. TYPE--PWR. NRC--WEST., AE--SGT C LUNDY

CAUSE - OPERATOR ERROR. DURING RECIRCULATION OF WAST WATER WITH CONTAINMENT SPRAY PUMP 1A FOR
SAMPLING, PUMP 1C RECIRCULATION VALVE WAS DISCOVERED TO BE OPEN. THE 1C CONTAINMENT SPRAY SYSTEM
WOULD DELIVER ONLY 1/3 CAPACITY WITH THE VALVE OPEN. UPON COMPLETION OF TESTING ON AUG. 26, THE
OPERATOR FAILED TO CLOSE THE VALVE. HE HAD SOME DOUBTS ABOUT THE PROPER VALVE POSITION BUT
FAILED TO ASK HIS SUPERVISOR. THE VALVE WAS CLOSED. THE UNIT WAS OPERATING AT 85% POWER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

ZION 1 (PWR) + VALVES + CONTAINMENT SPRAY + FAILURE, OPERATOR ERROR + SYSTEM CAPABILITY + PROCEDURES AND
MANUALS

107518
SET POINT UNIT IN FLOW TRANSMITTERS AT ZION 1
COMMONWEALTH EDISON, ZION, ILL.
3 PGS. LTR W/AT 50-295/75-24 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION III, OCT. 10, 1975. DOCKET 50-
295. TYPE--PWR. NRC--WEST., AE--SGT C LUNDY

CAUSE - ZERO POINT SHIFT. WHILE OPERATING AT 87% POWER, REACTOR COOLANT FLOW INDICATION WAS 38
HIGH ON 2 OF THE 3 CHANNELS. THE FISHER & PORTER CO, MODEL 1002490PMAJ30-NS FLOW TRANSMITTERS
HAD ZERO POINT SHIFT. THEY WERE RE-ZEROED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM
CHARGE \$2.00

ZION 1 (PWR) + INSTRUMENT, SWITCH + SENSORS, FLOW + FAILURE, INSTRUMENT + REACTOR SAFETY SYSTEM + MAIN
COOLING SYSTEM + SET POINT + POINT

107600
THERMAL PLUME SIZE EXCEEDS LIMIT AT ZION 1 AND 2
COMMONWEALTH EDISON CO., ZION, ILL.
4 PGS. LTR W/ENV. RPT TO NRC OFFICE OF NUCLEAR REACTOR REGULATIONS, OCT. 31, 1975. DOCKETS 50-295/304. TYPE--
PWR. NRC--WEST., AE--SGT C LUNDY

CAUSE - UNFORESEEN INTERACTIONS. REPORTS RECEIVED FROM CONSULTANTS RETAINED TO STUDY THE SIZE OF
THE THERMAL PLUME UNDER VARIOUS CONDITIONS INDICATE THAT TECH SPECS ARE BEING VIOLATED. THE
UTILITY HAS REQUESTED ADOPTION OF ALTERNATIVE EFFLUENT LIMITATIONS. THE CAUSE OF THIS VIOLATION

107600 UNCLASSIFIED

IS UNDESIRABLE INTERACTION OF THE DISCHARGE PLUMES BETWEEN UNITS WITH CERTAIN COMBINATIONS OF WIND, CURRENT DIRECTIONS, AND SPEEDS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

21001 (PHR) + 21002 (PHR) + PLUME BEHAVIOR + WASTE HEAT MANAGEMENT + LAKE + CONDENSED COOLING SYSTEM + DISCHARGE + EFFLUENT + THERMAL POLLUTION + TEMPERATURE GRADIENT

108200

SET POINT UNIT IN DIFFERENTIAL TEMPERATURE SWITCH AT ZION 1

COMMONWEALTH EDISON CO., ZION, ILL.

3 PGS, LTR W/ENCL. RPT. TO NRC OFFICE OF NUCLEAR REACTOR REGULATION, NOV. 13, 1975, DOCKET 50-295, TYPE--PHR, MFG--WEST., AE--SGT & LUNDY

CAUSE - LOOSE FRICTION CLUTCH. WHILE THE REACTOR WAS OPERATING AT 838 POWER, THERE WAS A LOSS OF VACUUM WHICH CAUSED THE CIRCULATING WATER DIFFERENTIAL TEMPERATURE TO INCREASE TO NEAR THE 20 F. LIMIT. A TEST WAS MADE TO SEE IF THE INSTRUMENT WOULD ALARM. THE SET POINT HAD DRIFTED TO 50 F. THE MECHANIC FOUND A LOOSE FRICTION CLUTCH IN THE ALARM DISC WHICH HAD CAUSED THE DRIFT. THE CLUTCH WAS TIGHTENED AND THE SET POINT ADJUSTED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

21001 (PHR) + INSTRUMENT, SWITCH + INSTRUMENT CALIBRATION + SENSORS, TEMPERATURE + TEST, SYSTEM OPERABILITY + FAILURE, INSTRUMENT + SET POINT + DRIFT + CONDENSED COOLING SYSTEM + FAILURE, MAINTENANCE ERROR + ANNUNCIATORS

108200

NOTICE OF VIOLATION CONCERNING CONFORMANCE TO PROCEDURES AT ZION 1

U.S. NUCLEAR REGULATORY COMMISSION, WASH., D.C.

6 PGS, LTR W/ATTACH. TO COMMONWEALTH EDISON CO., NOV. 24, 1975, DOCKET 50-295, TYPE--PHR, MFG--WEST., AE--SGT & LUNDY

CAUSE - LACK OF DISCIPLINED PROCEDURAL CONTROL. DURING INSPECTIONS, CERTAIN ACTIVITIES APPEARED TO BE IN NONCOMPLIANCE WITH NRC REQUIREMENTS. A MAJOR CONCERN WAS IDENTIFIED IN CONNECTION WITH CONFORMANCE TO PROCEDURES. TWO REPORTABLE OCCURRENCES ON JUNE 3 AND 6, 1975 ARE SPECIFIC EXAMPLES THAT APPEAR TO HAVE RESULTED FROM A LACK OF DISCIPLINED PROCEDURAL CONTROL AND COMMUNICATION ON THE PART OF OPERATING PERSONNEL, AND SITE AND COMPANY MANAGEMENT. THESE REPRESENT THE FIFTH AND SIXTH OF A SERIES OF SIMILAR EVENTS. NRC REQUESTS DISCUSSION OF ACTIONS TAKEN OR PLANNED TO IMPROVE THE EFFECTIVENESS OF MANAGEMENT CONTROL SYSTEM.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

21001 (PHR) + COMPLIANCE + FAILURE, ADMINISTRATIVE CONTROL + LEGALISTICS + COMMUNICATION + PROCEDURES AND MANUALS + AGENCY, NRC

109207

SAFETY INJECTION OCCURS AT ZION 1

COMMONWEALTH EDISON CO., ZION, IL

2 PGS, LTR W/ATTACH. TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION III, DEC. 12, 1975, DOCKET 50-295, TYPE--PHR, MFG--WEST., AE--SGT & LUNDY

CAUSE - PRESSURE TRANSMITTER BUMPED. ON SEPT. 10, 1975, UNIT 1 WAS OPERATING AT 2760 MWt WHEN A REACTOR TRIP AND SAFETY INJECTION OCCURRED DUE TO LOOP A HIGH STEAMLINE DELTA PRESSURE. AT THE TIME, ONE CHANNEL OF THE LOGIC WAS IN THE TRIP CONDITION FOR SURVEILLANCE. IT IS SUSPECTED THAT CONTRACTORS WORKING NEAR THE MAIN STEAMLINE PRESSURE TRANSMITTERS PHYSICALLY BUMPED ANOTHER TRANSMITTER. TESTS HAVE SHOWN THAT A BUMP CAN CAUSE A SPIKE OF GREATER THAN 100 PSI. THE 2 OUT OF 3 LOGICS WERE SATISFIED. WHEN ASSURED OF STABLE PLANT PARAMETERS, THE OPERATOR TERMINATED THE INJECTION AFTER 10 MINUTES. NO DAMAGE OCCURRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

21001 (PHR) + SAFETY INJECTION + FAILURE, MAINTENANCE ERROR + SCRAM, REACTOR + REACTOR SHUTDOWN + INSTRUMENT, ANNUNCIATION + MAINTENANCE AND REPAIR

109201

CONTAINMENT GRAB SAMPLES NOT TAKEN AT ZION 1

COMMONWEALTH EDISON CO., ZION, IL

3 PGS, LTR W/RO 50-295/75-26 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION III, DEC. 30, 1975, DOCKET 50-295, TYPE--PHR, MFG--WEST., AE--SGT & LUNDY

CAUSE - SUPERVISOR ERROR. MANUAL GRAB SAMPLES WERE NOT DRAWN EACH SHIFT AS REQUIRED DURING A PERIOD WHEN 2 RADIATION MONITORS WERE INOPERABLE. ONE PARTICULATE AND 5 GAS SAMPLES WERE MISSED. THE RADIATION PROTECTION DEPARTMENT WAS NOTIFIED TO OBTAIN GRAB SAMPLES BUT THE FOREMAN FORGOT TO WRITE THE REQUIREMENT ON THE SURVEILLANCE SHEETS. PROCEDURES HAVE BEEN REVISED TO HELP

109281 CONTINUING
PREVENT RECURRENCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZIGN 1 (PHR) + SAMPLE BUG + PLUMBING + ADJUSTING SYSTEM, RADIATION + FAILURE, ADMINISTRATIVE CONTROL

059165

FEEDWATER ISOLATION VALVE FAILS TO CLOSE AT ZIGN 2

COMMONWEALTH EDISON, ILLINOIS

3 PAGES, LETTER WITH AD REPORT 74/55 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 3 (AEC), JANUARY 6, 1975, DOCKET 50-304, TYPE--PHR, RFG--WEST., AE--SGT & LUNDY

CAUSE - MOTOR FELL OFF. AS THE UNIT WAS BEING COOLED TO THE COLD SHUTDOWN CONDITION, THE OPERATOR ATTEMPTED TO CAUSE A FEEDWATER ISOLATION VALVE. THE VALVE FAILED TO OPEN. THE MOTOR HAD FALLEN OFF OF THE LIMITSWITCH OPERATOR. THE VALVE WAS MANUALLY CLOSED. THE CAPSCREWS HOLDING THE MOTOR HOUSING TO THE OPERATOR WERE TOO SHORT AND ONLY ENGAGED A COUPLE OF THREADS. THE THREADS STRIPPED OUT. THE CAP SCREWS WERE REPLACED WITH THREADED RODS AND NUTS AS THERE WERE INSUFFICIENT THREADS LEFT. THE SHORT CAP SCREWS ON SIMILAR OPERATIONS WERE REPLACED WITH LONGER ONES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

CONTAINMENT ISOLATION + FASTENER + AGGREGATION + FAILURE, FABRICATION ERROR + ZIGN 2 (PHR) + FEEDWATER + VALVE OPERATIONS + MOTORS + VALVES

099110

CHARGING PUMP PRESSURE INDICATING PIPE CRACKS AT ZIGN 2

COMMONWEALTH EDISON, ILLINOIS

3 PAGES, LETTER WITH AD REPORT 74/56 TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 3 (AEC), JANUARY 9, 1975, DOCKET 50-304, TYPE--PHR, RFG--WEST., AE--SGT & LUNDY

CAUSE - UNKNOWN. WHILE THE REACTOR WAS AT HOT SHUTDOWN, WATER WAS DISCOVERED TO BE SPRAYING FROM A CRACK IN 3/4 INCH PRESSURE INDICATING PIPING ON THE CHARGING PUMP SUCTION. THE LEAK WAS ABOUT 1 GPM. THE PUMP WAS STOPPED. THE PIPING WAS REPLACED. THE CRACK DEVELOPED IMMEDIATELY ADJACENT TO A SOCKET WELD WHICH HAD BEEN REPAIRED ONE MONTH EARLIER. FAILURE APPEARS TO BE RELATED TO THE REPAIR AND AGGRAVATED BY THE HIGH VIBRATION OF THE POSITIVE DISPLACEMENT PUMP. PERMANENT CORRECTIVE ACTION WILL BE BASED ON DATA FROM EXAMINATION OF THE FAILED SECTION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

MAINTENANCE AND REPAIR + FAILURE, PIPE + WELDS + REACTOR COOLANT + VIBRATION + LEAK + ZIGN 2 (PHR) + FEEDWATER + PIPES AND PIPE FITTINGS

099385

UNOVERTANT INJECTION OF THE BORON INJECTION TANK AT ZIGN 2

COMMONWEALTH EDISON COMPANY, ILLINOIS

1 PAGE, LETTER TO DIRECTORATE OF REGULATORY OPERATIONS, REGION 3 (AEC), JANUARY 17, 1975, DOCKET 50-304, TYPE--PHR, RFG--WEST., AE--SGT & LUNDY

CAUSE - OPERATOR ERROR. ON OCT. 22, 1974 A REACTOR TRIP AND AUTOMATIC SAFETY INJECTION ACTUATION OCCURRED AS REPORTED EARLIER. AFTER THE FAILURES THAT CAUSED THESE EVENTS WERE CORRECTED, TESTS WERE MADE TO VERIFY PROPER OPERATION OF THE AFFECTED COMPONENTS. DURING PART OF THE TESTING, A VALVE OPENED BUT FAILED TO CLOSE ON SIGNAL. THE OPERATOR DID NOT NOTICE IT. DURING LATER TESTING, THIS OPEN VALVE ALLOWED AN INJECTION OF THE BORON INJECTION TANK TO THE REACTOR COOLANT SYSTEM. THE INJECTION WENT UNNOTICED FOR 4 MINUTES. ABOUT 1175 GALLONS OF BORATED WATER WERE INJECTED. NO DAMAGE OCCURRED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, (OPERATOR ERROR + POISON, SOLUBLE + TESTING + TEST, SYSTEM OPERABILITY + SHUTDOWN SYSTEM, SECONDARY + CHEMICAL SHIM + ZIGN 2 (PHR)

099208

DIESEL GENERATOR FAILS TO START AT ZIGN 2

COMMONWEALTH EDISON COMPANY, ILLINOIS

5 PAGES, LETTER WITH AD REPORT 75/1,2,3,4 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, JANUARY 23, 1975, DOCKET 50-304, TYPE--PHR, RFG--WEST., AE--SGT & LUNDY

CAUSE - VIBRATION SWITCH MALFUNCTION. FOUR DIESEL GENERATOR FAILURES ARE REPORTED. DIESEL GENERATOR 2B TRIPPED DURING TESTING 3 TIMES. IT IS THOUGHT THAT THE VIBRATION SWITCH WAS DEFECTIVE. IT WAS REPLACED. THE NEW SWITCH CAUSED THE THIRD TRIP. THE VIBRATION WAS MEASURED AND FOUND TO BE ACCEPTABLE. THE SWITCH IS NOW JUMPERED. DIESEL GENERATOR 0 ALSO FAILED TO START DURING A TEST. NO CAUSE WAS FOUND. A BROKEN AIR LINE WAS FOUND AND REPAIRED. THERE IS NO FIRST OUT ANNUNCIATION ON THE TRIP CIRCUITS.

053253 PLANTING
 AVAILABILITY - MRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + EMERGENCY POWER, ELECTRIC + INSTRUMENT, SWITCH + TEST, SYSTEM OPERABILITY + VIBRATION + ZION 2 (PWR) + ENGINE, INTERNAL COMBUSTION + GENERATION, DIESEL

053254
 STEAM PRESSURE TRANSMITTER DRIFT AT ZION 2
 COMMONWEALTH EDISON COMPANY, ILLINOIS
 1 PAGE, LETTER TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, JANUARY 24, 1975, DOCKET 50-306, TYPE--PWR, PFG--WEST., AE--SGT E LUNDY

CAUSE - ZERO DRIFT. WHILE OPERATING AT 54% POWER, A STEAM PRESSURE TRANSMITTER WAS FOUND TO BE OUT OF TOLERANCE. THE TRANSMITTER HAD A ZERO DRIFT OF 3.78 WHICH CAUSED THE PRESSURE INDICATOR TO READ HIGH. THE FISCHER PORTER MODEL 2496 TRANSMITTER WAS RECALIBRATED.

AVAILABILITY - MRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

STEAM + SAFETY INJECTION + FAILURE, MAINTENANCE ERROR + ZION 2 (PWR) + DRIFT + SENSORS, PRESSURE + ELECTRONIC FUNCTION UNITS

053255
 CHARGING MEASUR ISOLATION VALVE FAILS TO CLOSE AT ZION 2
 COMMONWEALTH EDISON COMPANY, ILLINOIS
 1 PAGE, LETTER TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, JANUARY 27, 1975, DOCKET 50-306, TYPE--PWR, PFG--WEST., AE--SGT E LUNDY

CAUSE - PACKING OUT OF ADJUSTMENT. DURING TESTING WITH THE PLANT IN HOT STANDBY, A CHARGING MEASUR ISOLATION VALVE FAILED TO CLOSE FULLY WHEN THE ACTUATION SIGNAL WAS APPLIED. VALVE PACKING WAS OUT OF ADJUSTMENT. IT APPARENTLY BECAME DISLOOSED DURING PREVIOUS OPERATION. THE PACKING WAS ADJUSTED. THE TORQUE SWITCH SETTING TO CLOSE WAS INCREASED FROM 1.0 TO 1.5. PERIODIC ADJUSTMENT OF TORQUE SETTINGS IS TO BE EXPECTED OVER THE LIFE OF THE PLANT.

AVAILABILITY - MRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ISOLATION + TEST, SYSTEM OPERABILITY + FAILURE, MAINTENANCE ERROR + SEAL + ZION 2 (PWR) + FEEDWATER + VALVES

053606
 SET POINT DRIFT IN LEVEL SENSOR AT ZION 2
 COMMONWEALTH EDISON COMPANY, ILLINOIS
 2 PAGES, LETTER WITH AD REPORT 75/5 TO DIRECTORATE OF REGULATORY OPERATIONS AEC, REGION 3, JANUARY 30, 1975, DOCKET 50-306, TYPE--PWR, PFG--WEST., AE--SGT E LUNDY

CAUSE - UNKNOWN. WHILE OPERATING AT 83% POWER, A STEAM GENERATOR LEVEL TRANSMITTER WAS FOUND TO BE 02.48 OUT OF TOLERANCE DURING CHANNEL CALIBRATION. THE ALLOWABLE TOLERANCE IS 2%. THE CAUSE IS UNKNOWN AT THIS TIME. THE TRANSMITTER WAS RECALIBRATED. IT IS A FISCHER PORTER D/P TRANSMITTER MODEL 1302445KRB000-NS.

AVAILABILITY - MRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, INSTRUMENT + INSTRUMENT, LIQUID LEVEL + INSTRUMENT, SWITCH + TEST, SYSTEM OPERABILITY + STEAM GENERATOR + SET POINT + ZION 2 (PWR) + DRIFT + SENSORS, LEVEL

053675
 BORIC ACID CONCENTRATION LOW IN BORIC ACID TANK AT ZION 2
 COMMONWEALTH EDISON COMPANY, ILLINOIS
 3 PAGES, LETTER WITH AD REPORT 75/6 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, FEBRUARY 5, 1975, DOCKET 50-306, TYPE--PWR, PFG--WEST., AE--SGT E LUNDY

CAUSE - VALVE LEAKAGE. THE BORON INJECTION TANK WAS ON CONTINUOUS RECIRCULATION WITH THE BORIC ACID TANK. SAMPLES INDICATED THAT THE BORIC ACID CONCENTRATION IN THE BAT WAS 11.28 WHICH IS BELOW THE 11.58 LIMIT. A MONTHLY TEST WAS PERFORMED 2 DAYS EARLIER WHICH INVOLVED STRONGING THE BIT INLET VALVES. APPARENTLY, ONE VALVE FAILED TO SEAT TIGHTLY AFTER THE TEST, ALLOWING WATER OF LOW BORIC ACID CONCENTRATION TO LEAK INTO THE BIT AND THEN INTO THE BAT THROUGH RECIRCULATION. THE CONCENTRATION WAS INCREASED ABOUT 11.58 BY THE ADDITION OF A HIGHLY CONCENTRATED BATCH OF ACID.

AVAILABILITY - MRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545, 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

BORON + SAFETY INJECTION + STORAGE CONTAINER + CHEMICAL SHIP + ZION 2 (PWR) + CONCENTRATION

009710
ZERO UNIT IN FEEDWATER FLOW INSTRUMENT AT ZION 2
COMMONWEALTH EDISON COMPANY, ILLINOIS
3 PAGES. LETTER WITH AD REPORT 75/77 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, FEBRUARY 7, 1975.
DOCKET 50-304, TYPE--PWR, NRC--WEST., AE--SGT E LUNDY

CAUSE - UNKNOWN. DURING TESTING WHILE THE REACTOR WAS AT 83% POWER, THE ZERO SETTING OF A FEEDWATER FLOW MULTIPLIER/DIVIDER WAS FOUND TO HAVE DRIFTED 0.4% HIGH IN THE NON-CONSERVATIVE DIRECTION. THE CAUSE OF THE DRIFT WAS NOT BEEN DETERMINED YET. THE MODULE WAS REMOVED AND REPLACED WITH A SPARE. IT IS A HAWAY MULTIPLIER/DIVIDER MODEL NO. 127-112.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545. 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

REACTOR SAFETY SYSTEM + INSTRUMENT CALIBRATION + FAILURE, INSTRUMENT + INSTRUMENT, SWITCH + TEST, SYSTEM OPERABILITY + SET POINT + ZION 2 (PWR) + GRIFF + FEEDWATER + SENSORS, FLOW

009894
DELTA TEMPERATURE SUMMATOR FAILS AT ZION 2
COMMONWEALTH EDISON CO., ILLINOIS
1 PAGE. LETTER TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, FEBRUARY 7, 1975. DOCKET 50-304, TYPE--PWR, NRC--WEST., AE--SGT E LUNDY

CAUSE - TRANSISTOR FAILURE. WHILE THE REACTOR WAS OPERATING AT 83% POWER, LOOP A DELTA TEMPERATURE INDICATION FAILED TO 0%. THE DISTANCES IN THIS LOOP WERE PUT INTO THE TRIP MODE UNTIL THE MODULE COULD BE REPLACED WITH A SPARE. A 2N41 TRANSISTOR HAD FAILED IN THE SUMMATOR CAUSING THE OUTPUT TO FAIL TO ZERO. THE FAILED MODULE WILL BE REPAIRED WHEN THE INVOLVED TRANSISTOR IS RECEIVED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545. 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + REACTOR SAFETY SYSTEM + SOLID STATE DEVICE + INSTRUMENT, SWITCH + ZION 2 (PWR) + SENSORS, TEMPERATURE

100453
SAFETY INJECTION OCCURS AT ZION 2
COMMONWEALTH EDISON COMPANY, ILLINOIS
1 PAGE. LETTER TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, MARCH 7, 1975. DOCKET 50-304, TYPE--PWR, NRC--WEST., AE--SGT E LUNDY

CAUSE - BROKEN CONNECTION ON RELAY. THE LEVEL CONTROL VALVE FOR A STEAM GENERATOR CLOSED DURING SAFEGUARDS TESTING. THE REACTOR TRIPPED FROM STEAM FLOW/FEED FLOW MISMATCH WITH LOW LEVEL. THE VALVE CLOSED AS A RESULT OF A BACKEN CRIMP CONNECTION ON A RELAY. THE PRESSURE OSCILLATIONS THAT OCCURRED IN THE STEAM GENERATOR AS THE FEED RING WAS BEING COVERED ACTUATED SAFETY INJECTION. THE SAFETY INJECTION WAS TERMINATED WITHIN 30 SECONDS WHEN ANALYZED AS INADVERTANT. DURING NORMAL TRIPS, THE FEED RINGS ARE NOT UNCOVERED. VIBRATION CAUSED THE BROKEN CONNECTION TO SEPARATE FROM THE RELAY. AVAL: POR

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D.C. 20545. 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

SCRAM, REAL + SAFETY INJECTION + FAILURE, INSTRUMENT + VIBRATION + STEAM GENERATOR + PRESSURE TRANSIENT + ZION 2 (PWR) + CABLES AND CONNECTORS + RELAYS

100890
TWO CONTAINMENT ISOLATION VALVES FAIL TO CLOSE AT ZION 2
COMMONWEALTH EDISON CO., ILL.
2 PAGES. LETTER WITH AD REPORT 75/11 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, MARCH 10, 1975.
DOCKET 50-304, TYPE--PWR, NRC--WEST., AE--SGT E LUNDY

CAUSE - MAKE-UP OF SOLENOID VALVES. WITH THE UNIT OPERATING AT 84% POWER, LOOP SAMPLE AND PRESSURIZER LIQUID SAMPLE ISOLATION VALVES FAILED TO CLOSE DURING TESTING. THE SOLENOID VALVES, SUPPLYING CONTROL AIR TO THE ISOLATION VALVES MAKE-UP. THE FAILURE MECHANISM IS NOT KNOWN AT THIS TIME. THESE ARE THE FIRST FAILURES FOR THIS MODEL SOLENOID. THE ISOLATION VALVES AND THE MANUAL ISOLATION VALVES CLOSED. THE SOLENOIDS WILL BE REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545. 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + CONTAINMENT ISOLATION + SAMPLING + TEST, SYSTEM OPERABILITY + PNEUMATIC SYSTEM + ZION 2 (PWR) + SOLENOID + VALVE OPERATORS + VALVES

100888
CONTAINMENT ISOLATION VALVE FAILS TO CLOSE AT ZION 2
COMMONWEALTH EDISON CO., ILL.
2 PAGES. LETTER WITH AD REPORT 75/10 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, MARCH 10, 1975.
DOCKET 50-304, TYPE--PWR, NRC--WEST., AE--SGT E LUNDY

100900 *CONTINUED*

CAUSE - HAND-UP OF SOLLENOID VALVE. DURING TESTING WITH THE REACTOR AT 80% POWER, AN INLET ISOLATION VALVE FOR 2 CONTAINMENT RADIATION MONITORS FAILED TO CLOSE. THE SOLENOID VALVE SUPPLYING CONTROL AIR TO THE ISOLATION VALVE HUNG UP. FAILURE MECHANISM IS NOT KNOWN AT THIS TIME. THERE HAVE BEEN 4 SIMILAR FAILURES. EXCESS GREASE FROM AN UNKNOWN SOURCE WAS FOUND ON THE VALVE. THE SOLENOID VALVE WAS CLEANED. IT WILL BE REPLACED WHEN A NEW VALVE IS AVAILABLE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT + CONTAINMENT ISOLATION + TEST, SYSTEM OPERABILITY + PNEUMATIC SYSTEM + ZION 2 (PHR) + SOLENOID + VALVE OPERATORS + VALVES + RADIATION MONITORS

100928

INTERMEDIATE RANGE HIGH FLUX TRIP SETPOINT REPORTED HIGH AT ZION 2

COMMONWEALTH Edison COMPANY, ILLINOIS

2 PAGES, LETTER WITH AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, MARCH 19, 1975, DCKET 50-304, TYPE--PHR, MFG--WEST., AE--SGT & LUNDY

CAUSE - INDICATED READING HIGH. DURING A UNIT STARTUP, IT WAS NOTED THAT A HIGH FLUX TRIP DISTANCE ON A POWER RANGE CHANNEL TRIPPED AT 338, WHICH IS 8% OUT OF TOLERANCE. BECAUSE THE POWER RANGE CHANNELS INDICATE HIGHER POWER THAN ACTUAL POWER AT LEVELS LOWER THAN THE CALIBRATION POINT, ADDITIONAL CALIBRATION POINTS WERE TAKEN. THESE DATA INDICATE THAT THE SETPOINT WAS LESS THAN 2% ACTUAL POWER. NO LIMITS WERE VIOLATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INSTRUMENT CALIBRATION + INSTRUMENT, SWITCH + INSTRUMENT, POWER RANGE + SET POINT + ZION 2 (PHR) + ELECTRONIC FUNCTION UNITS

100927

SETPOINT UNIT IN STEAM GENERATOR LEVEL COMPARATOR AT ZION 2

COMMONWEALTH Edison COMPANY, ILLINOIS

2 PAGES, LETTER WITH AEC REPORT 75/12 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, MARCH 20, 1975, DCKET 50-304, TYPE--PHR, MFG--WEST., AE--SGT & LUNDY

CAUSE - UNKNOWN. DURING TESTING WITH THE REACTOR AT 850 MWE, 1 OF THE 3 LO LO LEVEL COMPARATORS FOR A STEAM GENERATOR TRIPPED 1.75% LOW, WHICH IS 0.25% OUT OF TOLERANCE. THE MODULE WAS REPLACED WITH A SPARE. THE FAILED UNIT WILL BE EXAMINED FOR THE CAUSE OF FAILURE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INSTRUMENT CALIBRATION + FAILURE, INSTRUMENT + INSTRUMENT, SWITCH + TEST, SYSTEM OPERABILITY + STEAM GENERATOR + SET POINT + ZION 2 (PHR) + DRIFT + SENSORS, LEVEL

101002

SETPOINT DRIFT IN STEAM GENERATOR LEVEL COMPARATOR AT ZION 2

COMMONWEALTH Edison COMPANY, ILLINOIS

2 PAGES, LETTER WITH AEC REPORT 75/12 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, MARCH 20, 1975, DCKET 50-304, TYPE--PHR, MFG--WEST., AE--SGT & LUNDY

CAUSE - UNKNOWN. WHILE THE REACTOR WAS OPERATING AT 850 MWE, A STEAM GENERATOR LO-LO LEVEL COMPARATOR WAS FOUND TO TRIP 1.75% LOW DURING SURVEILLANCE. THIS IS 0.25% OUT OF TOLERANCE. THE MODULE WAS REPLACED WITH A SPARE. THE DEFECTIVE UNIT WILL BE REPAIRED. THE CAUSE OF FAILURE IS UNKNOWN AT THIS TIME.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

INSTRUMENT CALIBRATION + FAILURE, INSTRUMENT + INSTRUMENT, SWITCH + TEST, SYSTEM OPERABILITY + STEAM GENERATOR + SET POINT + ZION 2 (PHR) + DRIFT + SENSORS, LEVEL

100920

STEAM GENERATOR ATMOSPHERIC RELIEF VALVE INOPERABLE AT ZION 2

COMMONWEALTH Edison COMPANY, ILLINOIS

3 PAGES, LETTER WITH AEC REPORT 75/12 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, MARCH 21, 1975, DCKET 50-304, TYPE--PHR, MFG--WEST., AE--SGT & LUNDY

CAUSE - LACK OF COMMUNICATION. DURING A STAFF SURVEILLANCE, THE MANUAL ISOLATION VALVE FOR STEAM GENERATOR A ATMOSPHERIC RELIEF VALVE WAS FOUND CLOSED. THE VALVE WAS IMMEDIATELY OPENED BUT HAD TO BE CLOSED DUE TO A STEAM LEAK THROUGH THE RELIEF VALVE. THE REACTOR WAS BROUGHT TO HOT SHUTDOWN. THE ATMOSPHERIC RELIEF VALVE WAS REPAIRED AND TESTED SUCCESSFULLY. FOLLOWING PRIOR MAINTENANCE ON THE VALVE, THE ISOLATION VALVE WAS LEFT CLOSED FROM LACK OF COMMUNICATION BETWEEN AN OPERATOR AND THE SUPERVISOR. THE VALVE WAS TESTED AT THAT TIME WITH THE ISOLATION VALVE CLOSED PREVENTING DETECTION OF THE LEAK.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM

100920 *CONTINUED*
CHARGE \$2.00

MAINTENANCE AND REPAIR * PRESSURE RELIEF * FAILURE, ADMINISTRATIVE CONTROL * MAIN COOLING SYSTEM * STEAM GENERATOR * ZION 2 (PWR) * REACTOR SHUTDOWN * COMMUNICATION * VALVES

101041
OVERTEMPERATURE DELTA T CHANNEL FAILS AT ZION 2
COMMONWEALTH EDISON COMPANY, ILLINOIS
1 PAGE, LETTER TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, MARCH 26, 1975, JACKET 50-304, TYPE--
PWR, NRG--WEST., AE--SGT & LUNDY

CAUSE - CAPACITOR FAILURE. WHILE THE REACTOR WAS OPERATING AT 84% POWER, AN OVERTEMPERATURE DELTA TEMPERATURE CHANNEL FAILED HIGH MAKING THIS CHANNEL NON-CONSERVATIVE. CAPACITOR C4 IN THE SIGNAL SUMMATOR HAD FAILED. THE CAPACITOR WAS REPLACED AND THE MODULE RETURNED TO SERVICE. CAPACITOR C4 HAS BEEN IDENTIFIED AS A RECURRING COMPONENT FAILURE BY STATION TRENDS PROGRAM. CORRECTION OF THE PROBLEM IS UNDER STUDY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 139 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT * REACTOR SAFETY SYSTEM * FAILURE, INSTRUMENT * INSTRUMENT, SWITCH * FAILURE, DESIGN ERROR * ZION 2 (PWR) * SENSORS, TEMPERATURE

102127
OVERTEMPERATURE DELTA T SUMMATOR FAILS AT ZION 2
COMMONWEALTH EDISON COMPANY, ILLINOIS
2 PAGES, LETTER WITH AD REPORT 75/15 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, APRIL 3, 1975, JACKET 50-304, TYPE--PWR, NRG--WEST., AE--SGT & LUNDY

CAUSE - CAPACITOR FAILURE. WHILE OPERATING AT 67% PWR, THE OPERATOR FOUND THAT L3OP 3 OVERTEMPERATURE DELTA T INDICATOR HAD FAILED HIGH. THE L3OP HAD A FAILED SUMMATOR. A CAPACITOR IN THE SUMMATOR CIRCUITRY HAD FAILED. THE CAPACITOR WAS REPLACED. THIS PROBLEM COMPONENT IS UNDER INVESTIGATION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 136 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT * FAILURE, INSTRUMENT * FAILURE, DESIGN ERROR * ZION 2 (PWR) * SENSORS, TEMPERATURE * ELECTRONIC FUNCTION UNITS

102126
DISTABLE FAILS TO TRIP AT ZION 2
COMMONWEALTH EDISON COMPANY, ILLINOIS
2 PAGES, LETTER WITH AD REPORT 75/16 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, APRIL 8, 1975, JACKET 50-304, TYPE--PWR, NRG--WEST., AE--SGT & LUNDY

CAUSE - CAPACITOR FAILURE. WHILE DECREASING UNIT LOAD, THE OPERATOR NOTED THAT A DISTABLE DID NOT TRIP ON LU-TAVG NUR ON LC-LU TAVG. THE CAUSE OF THE COMPARATOR FAILURE WAS A BAD CAPACITOR IN THE POWER SUPPLY. THE CAPACITOR WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 128 CENTS/PAGE -- MINIMUM CHARGE \$2.00

FAILURE, COMPONENT * ZION 2 (PWR) * SENSORS, TEMPERATURE * ELECTRONIC FUNCTION UNITS

102171
Boric Acid Concentration Low in Boric Acid Tank at Zion 2
COMMONWEALTH EDISON COMPANY, ILLINOIS
3 PAGES, LETTER WITH AD REPORT 75/17 TO AEC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, APRIL 11, 1975, JACKET 50-304, TYPE--PWR, NRG--WEST., AE--SGT & LUNDY

CAUSE - OPERATOR ERROR. WHILE OPERATING THE REACTOR AT 84% POWER, THE DAILY SAMPLE OF THE BORIC ACID TANK INDICATED A BORIC ACID CONCENTRATION OF 11.48 WHICH IS BELOW THE 11.52 LIMIT. A 15% BATCH OF BORIC ACID WAS ADDED IMMEDIATELY TO RESTORE THE CONCENTRATION TO 11.52. ADDITIONAL BATCHES WERE ADDED UNTIL THE CONCENTRATION EXCEEDED 12%. NO CAUSE FOR DILUTION WAS FOUND. THE OPERATORS HAD FAILED TO INCREASE CONCENTRATION WHEN THE PRIOR DAY'S SAMPLE WAS 11.68. OPERATORS WERE INSTRUCTED TO MAINTAIN THE CONCENTRATION ABOVE 12%.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 108 CENTS/PAGE -- MINIMUM CHARGE \$2.00

BUREN * FAILURE, OPERATOR ERROR * SHUTDOWN SYSTEM, SECONDARY * CHEMICAL SHIM * ZION 2 (PWR) * CONCENTRATION

102530
ADDITIONAL INFORMATION ON CHARGING PUMP PIPE FAILURE AT ZION 2
COMMONWEALTH EDISON COMPANY, ILLINOIS

102538 PLANTINGEN
1 PAGE, LETTER TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, APRIL 17, 1975, DOCKET 50-304, TYPE--
PHN, MFG--WEST., AE--SGT & LUNDY

CAUSE - FATIGUE. A CRACK IN A 3/4 INCH PIPE IMMEDIATELY ADJACENT TO A SCKET WELD WAS FOUND IN THE POSITIVE DISPLACEMENT CHARGING PUMP LOCATION PRESSURE INDICATOR PIPING AS REPORTED EARLIER. METALLURGICAL INVESTIGATION SHOWED THAT THE LINE HAD CRACKED DUE TO FATIGUE. THERE IS A GREAT STRESS CONCENTRATION AT THE WELD-JOINT DUE TO THE CHANGE IN WALL THICKNESS. MEASUREMENTS INDICATE THAT THE LINE IS NOT RECEIVING STRONG VIBRATIONS.

AVAILABILITY - MICRODURANCE, INC., P.O. BOX 3522 OAK RIDGE, TENN. 37830

ZION 2 (PHN) - PIPES AND PIPE FITTINGS - FAILURE, PIPE - FAILURE, FATIGUE - METALLURGY - FEEDWATER - CRACK - WELDS - STRESS

102537
CONTAINMENT PURGE FAILS TO TRIP AT ZION 2
COMMONWEALTH EDISON COMPANY, ILLINOIS
3 PAGES, LETTER WITH ACR 75-18 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, APRIL 17, 1975, DOCKET 50-304, TYPE--PHN, MFG--WEST., AE--SGT & LUNDY

CAUSE - DIRTY CONTACTS. WITH THE REACTOR AT COLD SHUTDOWN, THE CONTAINMENT PURGE ISOLATION VALVES FAILED TO CLOSE AND THE PURGE FANS DID NOT TRIP ON A HIGH RADIATION SIGNAL ON THE IODINE MONITOR. DIRTY CONTACTS IN THE CONTROL CIRCUITRY OF THE RADIATION MONITOR WERE THE PROBLEM. THE LIGHT BULB WAS REPLACED AND THE DIRTY CONTACTS CLEANED. THE MONITOR WAS TESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PHN) - CONTAINMENT PURGE - CONTAINMENT ISOLATION - FAILURE, COMPONENT - RADIATION MONITORS - FAILURE, MAINTENANCE ERROR

102677
CONTAINMENT PURGE FAILS TO TRIP AT ZION 2
COMMONWEALTH EDISON COMPANY, ILLINOIS
3 PAGES, LETTER WITH ACR 75-18 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, APRIL 17, 1975, DOCKET 50-304, TYPE--PHN, MFG--WEST., AE--SGT & LUNDY

CAUSE - DIRTY CONTACTS. WHILE THE UNIT WAS AT COLD SHUTDOWN, THE PURGE ISOLATION VALVES FAILED TO CLOSE AND THE PURGE FANS DID NOT TRIP WHEN A HIGH RADIATION SIGNAL WAS RECEIVED ON THE IODINE MONITOR. THE OPERATOR CLOSED THE VALVES IMMEDIATELY. DIRTY CONTACTS IN THE CONTROL CIRCUITRY OF THE RADIATION MONITOR ELIMINATED ITS FUNCTION TO CLOSE THE VALVES. THE CONTACTS WERE CLEANED AND THE MONITOR TESTED SATISFACTORILY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PHN) - VALVES - BLOWERS - FAILURE, INSTRUMENT - CONTAINMENT INTEGRITY - CPUD - RADIATION MONITORS - CONTAINMENT PURGE

102536
CHARGING PUMP PIPING WELD LEAKS AT ZION 2
COMMONWEALTH EDISON COMPANY, ILLINOIS
3 PAGES, LETTER WITH ACR 75-19 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, APRIL 28, 1975, DOCKET 50-304, TYPE--PHN, MFG--WEST., AE--SGT & LUNDY

CAUSE - FATIGUE. DURING NORMAL OPERATION, A WELD LEAK WAS DISCOVERED ON A POSITIVE DISPLACEMENT CHARGING PUMP DISCHARGE 3/4 INCH LOAN PRESSURE INDICATOR LINE AT THE POINT OF ATTACHMENT TO THE 3 INCH PIPING. THE LEAK WAS LESS THAN 0.5 GPM. FAILURE APPEARS TO BE FROM FATIGUE DUE TO PIPING VIBRATION. VIBRATION IS CAUSED BY PRESSURE PULSATIONS ORIGINATING IN THE POSITIVE DISPLACEMENT PUMP. A PRESSURE PULSATION DAMPER, NO FILTER IS BEING CONSIDERED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PHN) - PIPES AND PIPE FITTINGS - WELDS - FAILURE, PIPE - FAILURE, FATIGUE - VIBRATION - FEEDWATER - LEAK - FAILURE, DESIGN ERROR

103000
ZERO SHIFT IN SQUARE-ROOT EXTRACTOR AT ZION 2
COMMONWEALTH EDISON COMPANY
2 PAGES, LETTER WITH ACR 75-20 TO NRC DIR. OF REGULATORY OPERATIONS, REGION 3, MAY 2, 1975, DOCKET 50-304, TYPE--PHN, MFG--WEST., AE--SGT & LUNDY

CAUSE - INSTRUMENT DRIFT. DURING TESTING WITH THE REACTOR AT 95% POWER, A SQUARE-ROOT EXTRACTOR WAS FOUND OFF AT ZERO BY A POSITIVE 6.5%. THE APPARENT CAUSE WAS INSTRUMENT DRIFT. THE INSTRUMENT WAS RECALIBRATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM

103000 MCINTOSH
CHARGE \$2.00

ZION 2 (PWR) + INSTRUMENTS, MISC. + INSTRUMENT CALIBRATION + INSTRUMENT SWITCH + TEST, SYSTEM OPERABILITY + FAILURE, INSTRUMENT + SET POINT + CRIFT

103063
CONTAINMENT PURGE ISOLATION VALVE LEAK RATES EXCESSIVE AT ZION 2
COMMONWEALTH EDISON CO., ILLINOIS
3 PAGES, LETTER WITH AD 75-22 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, MAY 12, 1975, DOCKET 50-306, TYPE--
PWR, MFG--WEST., AE--SUT & LUNDY

CAUSE - GASKET ADJUSTED IMPROPERLY. INVESTIGATION OF A PENETRATION PRESSURIZATION AIR LEAK FOUND THAT 2 CONTAINMENT PURGE EXHAUST ISOLATION VALVES WERE LEAKING. ESTIMATED LEAKAGE WAS 1990 SCFH. A SHUTDOWN FROM 408 POWER WAS STARTED. THE RUBBER GASKETS ON THE VALVE SEATING SURFACE WAS NOT TIGHTLY SEALING WHEN THE VALVE CLOSED. THE GASKETS WERE ADJUSTED TO MINIMIZE LEAKAGE. LEAK REDUCTION WAS STOPPED AT 408 POWER WHEN THE LEAK RATE WAS 2,399 SCFH. THESE ARE 42 INCH BUTTERFLY VALVES, MC AT PRATT CL., FUEL RIB P2 OFFSET DISC.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) + LEAK RATE + VALVES + CONTAINMENT ISOLATION + CONTAINMENT PURGE + TEST, SYSTEM OPERABILITY + TEST, LEAK RATE + FAILURE, MAINTENANCE ERROR + REACTOR SHUTDOWN

103123
DIESEL GENERATOR FAILS TO START AT ZION 2
COMMONWEALTH EDISON CO., ILLINOIS
5 PAGES, LETTER WITH AD 75-23 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, MAY 16, 1975, DOCKET 50-306, TYPE--PWR, MFG--WEST., AE--SUT & LUNDY

CAUSE - CONTROL AIR LEAKS. A DIESEL GENERATOR FAILED TO START DURING A TEST TO ALLOW WORK ON A CURE SPRAY PUMP PIPING. IT STARTED ON A RETEST BUT FAILED AGAIN ON ANOTHER TRY. IT WAS THEN RESTARTED AND KEPT LOADED UNTIL THE PUMP WORK WAS FINISHED. TWO SMALL CONTROL AIR LEAKS WERE FOUND ONE OF WHICH REDUCED FUEL SUPPLY. BOTH WERE REPAIRED. THE CURE SPRAY PUMPS HAD BEEN TAKEN OUT OF SERVICE FOR REPAIR WITHOUT VERIFYING OPERABILITY OF THE DG'S. THE ON COMING SHIFT DISCOVERED THE LEAKS AND COMPLETED THE TESTS BEFORE ALLOWING WORK TO PROCEED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) + GENERATOR, DIESEL + ENGINES, INTERNAL COMBUSTION + TEST, SYSTEM OPERABILITY + FAILURE, COMPONENT + LEAK + PNEUMATIC SYSTEM

103444
FLOW TRANSMITTER FAILS AT ZION 2
COMMONWEALTH EDISON COMPANY, ILLINOIS
3 PAGES, LETTER WITH AD REPORT 75-24 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, JUNE 3, 1975, DOCKET 50-306, TYPE--PWR, MFG--WEST., AE--SUT & LUNDY

CAUSE - OSCILLATOR FAILURE. AS LEAD WAS BEING LOWERED TO 358 POWER, A FLOW TRANSMITTER FAILED HIGH. THE OSCILLATOR WAS DEFECTIVE. THE OSCILLATOR WAS REPLACED AND THE FLOW TRANSMITTER CALIBRATED AND RETURNED TO SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) + INSTRUMENT, SWITCH + SENSORS, FLOW + FAILURE, COMPONENT + REACTOR SAFETY SYSTEM + FEEDWATER

103493
INADVERTANT SAFETY INJECTION OCCURS AT ZION 2
COMMONWEALTH EDISON COMPANY, ILLINOIS
2 PAGES, LETTER TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, JUNE 12, 1975, DOCKET 50-306, TYPE--
PWR, MFG--WEST., AE--SUT & LUNDY

CAUSE - OPERATOR ERROR. WHILE OPERATING AT 2678 MWt, A REACTOR TRIP OCCURRED DUE TO LOW LEVEL IN A STEAM GENERATOR COINCIDENT WITH STEAM FLOW/FEED FLOW MISMATCH. SAFETY INJECTION OCCURRED. IT WAS TERMINATED 90 SECONDS LATER. A MAINTENANCE TECHNICIAN MISTAKENLY INSTRUCTED THE OPERATOR TO SELECT LOOP 522 FOR STEAM GENERATOR LEVEL CONTROL RATHER THAN LOOP 523 PRIOR TO CALIBRATION TESTS. TESTING THEN CAUSED THE FEEDWATER REGULATING VALVE TO CLOSE AND ALSO SUPPLIED A HIGH STEAM FLOW SIGNAL. OPERATORS WERE WARNED TO BE CERTAIN OF CALIBRATION INSTRUCTIONS.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 H STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) + SAFETY INJECTION + FAILURE, MAINTENANCE ERROR + INSTRUMENT CALIBRATION + PROCEDURES AND MANUALS + SCRAM, REAL + REACTOR SHUTDOWN

103710
DIESEL GENERATOR FAILS TO START AT ZION 2
COMMONWEALTH EDISON COMPANY, ZION, ILL.
3 PAGES, LETTER WITH ACR 75-25 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, JUNE 23, 1975, DOCKET 50-304, TYPE--PMR, NRC--WEST., AE--SGT & LUNDY

CAUSE - FUEL OIL PRIMING PUMP FAILS. DURING A TEST WITH THE REACTOR AT COLD SHUTDOWN, A DIESEL GENERATOR FAILED TO START. THE AIR MOTOR DRIVING THE FUEL OIL PRIMING PUMP WAS FOUND INOPERABLE. THERE WAS WEAR ON THE BALL BEARINGS OF THE GAST 79G. CORP. MODEL 644-MHV-11A AIR DRIVEN MOTOR. THE AIR MOTOR WAS REPLACED WITH A SPARE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PMR) * GENERATION, DIESEL * ENGINES, INTERNAL COMBUSTION * TEST, SYSTEM OPERABILITY * FAILURE, EQUIPMENT * SEATING * FAILURE, COMPLAINT

103896
JONON CONCENTRATION IN BOMIC ACID TANK LOW AT ZION 2
COMMONWEALTH EDISON COMPANY, ZION, ILL.
3 PAGES, LETTER WITH ACR 75-29 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, JUNE 25, 1975, DOCKET 50-304, TYPE--PMR, NRC--WEST., AE--SGT & LUNDY

CAUSE - DILUTION. ANALYSIS OF A SAMPLE FROM A BOMIC ACID TANK INDICATED A CONCENTRATION OF 11.68 BOMIC ACID WHICH IS LESS THAN THE 11.58 LOWER LIMIT. PRIMARY WATER HAD BEEN ADDED TO THE TANK. THIS OCCURRED ON OCT. 9, 1974.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PMR) * BURLA * POISON, SOLUBLE * SAFETY INJECTION * STORAGE CONTAINER * CONCENTRATION

103897
CONTAINMENT PENETRATION BELLWIS LEAKING AT ZION 2
COMMONWEALTH EDISON COMPANY, ZION, ILL.
3 PAGES, LETTER WITH ACR 75-26 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, JUNE 25, 1975, DOCKET 50-304, TYPE--PMR, NRC--WEST., AE--SGT & LUNDY

CAUSE - UNKNOWN. WHILE INVESTIGATING A PENETRATION AIR LEAK, THE BELLWIS ON A CONTAINMENT PENETRATION WAS FOUND TO BE LEAKING IN EXCESS OF THE LIMIT. THE STEAM GENERATOR SAMPLE LINE FOR 2 STEAM GENERATORS PASSED THROUGH THIS PENETRATION. WHILE THE UNIT REMAINED IN COLD SHUTDOWN, THE SAMPLE LINE WAS REROUTED. THE OLD LINE WAS PLANKED OFF AND THE PENETRATION WAS CAPPED. THE BELLWIS IS BEING ANALYZED FOR FAILURE MODE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PMR) * LEAK RATE * CONTAINMENT PENETRATION, PIPE * SEAL * TEST, SYSTEM OPERABILITY * FAILURE, EQUIPMENT * MODIFICATION

103898
SHIFT FOUND IN TEMPERATURE SUPPLIER AT ZION 2
COMMONWEALTH EDISON COMPANY, ZION, ILL.
1 PAGE, LETTER WITH ACR 75-28 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, JUNE 27, 1975, DOCKET 50-304, TYPE--PMR, NRC--WEST., AE--SGT & LUNDY

CAUSE - FAILED CAPACITOR. DURING SURVEILLANCE WHILE THE UNIT WAS AT COLD SHUTDOWN, A T-AVG SUPPLIER WAS FOUND OUT OF TOLERANCE BY -7.58. A FAILED CAPACITOR, MILLROY 10 UF, 6 VDC, DATE CODE 6931A WAS FOUND. IT WAS REPLACED AND THE UNIT CALIBRATED AND RETURNED TO SERVICE. THIS CAPACITOR HAS BEEN A PROBLEM COMPONENT AND IS BEING REPLACED IN ACCORDANCE WITH A REPLACEMENT PROGRAM.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PMR) * INSTRUMENTS, MISC. * SENSORS, TEMPERATURE * FAILURE, COMPONENT * ELECTRONIC FUNCTION UNITS * TEST, SYSTEM OPERABILITY * FAILURE, DESIGN ERROR

103899
AIR-OPERATED CONTAINMENT ISOLATION VALVES FAILS TO CLOSE AT ZION 2
COMMONWEALTH EDISON COMPANY, ZION, ILL.
3 PAGES, LETTER WITH ACR 75-28 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, JUNE 30, 1975, DOCKET 50-304, TYPE--PMR, NRC--WEST., AE--SGT & LUNDY

CAUSE - DEFECTIVE SOLENOID VALVES. WHILE THE UNIT WAS IN COLD SHUTDOWN, THE AIR-OPERATED CONTAINMENT ISOLATION VALVES WERE STRICKED FROM THE CONTROL ROOM DURING SPECIAL TESTING. FOUR VALVES FAILED TO CLOSE. THE ASCC, 3 WAY, NO. M080329420 SOLENOID VALVES FAILED TO VENT THE AIR FROM THE VALVE DIAPHRAGM WHEN DE-ENERGIZED. THE CAUSE IS UNKNOWN. ERRATIC OPERATION OF THE

103898 *CONTINUED*

SOLENOIDS MAY BE CAUSED BY SMALL AMOUNTS OF A SILICONE TYPE GREASE IN THE SOLENOID COIL ASSEMBLY. THE SOURCE OF THE SILICA AND THE EXTENT OF THE PROBLEM IS BEING INVESTIGATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) * VALVES * CONTAINMENT ISOLATION * TEST, SYSTEM OPERABILITY * FAILURE, EQUIPMENT * SOLENOID * FAILURE, COMMON MODE

104609

HOLD-UP TANK BUCKLED AT ZION 2

COMMONWEALTH EDISON COMPANY, ZION, ILL.

3 PGS. LTR W/NOIR 75-29, TL NRC DIR, OF REGULATORY OPERATIONS, REGION 3, JULY 23, 1975, DCKET 50-304, TYPE--PWR, NRC--WEST.. AE--SGT & LUNDY

CAUSE - NEGATIVE PRESSURE. WHILE THE REACTOR WAS OPERATING AT 618 POWER, A SECTION OF HOLD-UP TANK (A) WAS FOUND TO BE BUCKLED WITH A HOLE IN THE BUCKLED SECTION. ABOUT 2500 GAL OF WATER HAD LEAKED ON THE FLOOR OF THE TANK CUBICLE IN THE AUXILIARY BUILDING. THE TANK WAS ISOLATED AND UNMAINED. THE BACKUP NITROGEN SUPPLY TO THE TANK HAD BEEN ISOLATED DUE TO PROBLEM WITH THE REGULATING VALVES. THE WASTE GAS COMPRESSOR HAD BEEN LEFT ON PAST THE LOW PRESSURE LIMIT WHEN IT SHOULD HAVE BEEN MANUALLY STOPPED. WHILE THE TANK WAS FEEDING THE NITRIC ACID EVAPORATORS, A NEGATIVE PRESSURE DEVELOPED AS VOLUME DECREASED BUCKLING THE TANK.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) * STORAGE CONTAINER * REACTOR COOLANT * LEAK * FAILURE, OPERATOR ERROR * FAILURE, EQUIPMENT * PRESSURE, SUBATMOSPHERIC

104818

MAIN STEAM ISOLATION VALVE IMPROPER AT ZION 2

COMMONWEALTH EDISON COMPANY, ZION, ILL.

3 PGS. LTR W/NOIR 75-30 TO NRC DIR, OF REG. OPER., REGION 3, AUG. 1, 1975, DCKET 50-304, TYPE--PWR, NRC--WEST.. AE--SGT & LUNDY

CAUSE - LOSS OF HYDRAULIC FLUID THROUGH GAUGE. WHILE OPERATING AT 858 POWER, MSIV 2A HYDRAULIC OPERATOR UNIT (OIL RESERVOIR OIL LEVEL WAS FOUND TO BE LOW WITH TIL ON THE FLOOR. TESTS THE NEXT DAY SHOWED THE MSIV TO BE IMPROPER. THE REACTOR WAS SHUT DOWN. THE CHICAGO FLUID PUMER CO., HYDRAULIC OPERATOR UNIT, MODEL SL-CRC-002, FAILED DUE TO LOSS OF HYDRAULIC FLUID THROUGH A LEAKY PRESSURE GAUGE. THE UNION TUBE OF THE PRESSURE GAUGE HAD RUPTURED. THE HYDRAULIC UNIT WAS REPAIRED BY REPLACING THE PUMP, PUMP RELIEF VALVE, 4-WAY SOLENOID VALVE, AND THE PRESSURE GAUGE. THE CONTROL TRANSDUCER WAS REPLACED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) * VALVES * CONTAINMENT ISOLATION * STEAM * HYDRAULIC SYSTEM * FAILURE, COMPONENT * SENSORS, PRESSURE * LEAK * REACTOR SHUTDOWN * COOLING SYSTEM, SECONDARY

105525

DIESEL GENERATOR FAILS TO START AT ZION 2

COMMONWEALTH EDISON COMPANY

4 PGS. LTR W/NOIR 75-19 TO NRC DIR, OF REGULATORY OPERATIONS, REGION 3, AUG. 21, 1975, DCKET 50-295, TYPE--PWR, NRC--WEST.. AE--SGT & LUNDY

CAUSE - WATER IN CHAMBER. DURING A LOAD TEST WITH THE REACTOR AT 45% POWER, DIESEL GENERATOR (A) FAILED TO START. A SIGNIFICANT AMOUNT OF WATER (100) WAS EVIDENT IN THE ENGINE LUBE OIL. OIL FILTERS WERE WATER SOAKED. THIS CAUSED LOW OIL PRESSURE WHICH PREVENTED THE DIESEL FROM STARTING. WATER HAD LEAKED FROM CYLINDER OR LINER BELLWIS. TO PREVENT RECURRENCE, CYLINDER HEAD BOLTS AND CYLINDER LINER BELLWIS BOLTS WILL BE RETORQUED AFTER A 3 HOUR RUNNING PERIOD WHENEVER GASKETS ARE REPLACED. THE OIL SYSTEM WAS CLEANED AND REFILLED. A SIGNIFICANT CARBON BUILDUP WAS FOUND ON THE TURBOCHARGER TURBINE CASING. THE TURBOCHARGER WAS REPLACED WITH A SPARE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) * GENERATOR, DIESEL * ENGINES, INTERNAL COMBUSTION * TEST, SYSTEM OPERABILITY * FAILURE, MAINTENANCE ERROR * LUBRICATION * WATER * LEAK * SEAL

105523

PRESSURE INDICATOR READING SHIFTS AT ZION 2

COMMONWEALTH EDISON COMPANY, ZION

2 PGS. LTR W/NOIR 75-32 TO NRC DIR, OF REGULATORY OPERATIONS, REGION 3, AUG. 28, 1975, DCKET 50-306, TYPE--PWR, NRC--WEST.. AE--SGT & LUNDY

CAUSE - UNKNOWN. WHILE THE REACTOR WAS OPERATING AT 858 POWER, A PRESSURE INDICATOR INCREASED FROM 2230 PSIG TO 2265 PSIG OR +4.48 OF SPAN. THE OTHER 3 CHANNELS REMAINED CONSTANT. THE INSTANCES WERE PLACED IN THE TRIP MODE. THE CHANNEL RETURNED TO NORMAL 25 MINUTES LATER. NO

105523 PLANTINUED

CAUSE WAS PLUGGED. A BRUSH RECORDER WAS PLACED ON THE LOOP FOR 24 HOURS WITH NO RECURRENCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) • SENSORS, PRESSURE • INSTRUMENT, ABNORMAL INDICATION • MAIN LOCKING SYSTEM • REACTOR SAFETY SYSTEM

106059

ISOLATION VALVE FAILS TO CLOSE COMPLETELY AT ZION 2

COMMONWEALTH EDISON, ILL.

3 PGS. LTR W/AL 50-304/75-34 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION III, SEPT. 26, 1975, DOCKET 50-304, TYPE--PWR, RFG--WEST., AE--SGT E LUNDY

CAUSE - VALVE STEM TO PLUG WELD BROKEN. DURING A MANUAL ACTUATION TEST OF PHASE A ISOLATION WITH THE REACTOR IN SHUTDOWN MODE, A VALVE FAILED TO CLOSE COMPLETELY. A BROKEN SCKET WELD BETWEEN THE VALVE STEM AND PLUG CAUSED THE 2 PIECES TO SEPARATE AND JAM THE VALVE. THE STEM AND PLUG WERE REMOVED ACCORDING TO APPROVED PROCEDURE. THIS WAS A 3/8 INCH MASONELLAN CO. 1500 PSI PRESSURE CLASS VALVE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) • VALVES • CONTAINMENT ISOLATION • TEST, SYSTEM OPERABILITY • FAILURE, FABRICATION ERROR • NRC LOS

106013

SET POINT SHIFT IN LEVEL INDICATORS AT ZION 2

COMMONWEALTH EDISON, ILL.

3 PGS. LTR W/AL 75-30 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION III, SEPT. 26, 1975, DOCKET 50-304, TYPE--PWR, RFG--WEST., AE--SGT E LUNDY

CAUSE - INSTRUMENT SHIFT. WHILE THE UNIT WAS IN COLD SHUTDOWN, LOOP 460 AND 461 WERE INVESTIGATED DUE TO 2 LEVEL INDICATORS READING - 118 AND 6.08 LOW RESPECTIVELY. THE CAUSE WAS INSTRUMENT SHIFT. THE HARTON MODEL 386-351 TRANSMITTERS WERE RECALIBRATED AND RETURNED TO NORMAL SERVICE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) • INSTRUMENT, SWITCH • INSTRUMENT CALIBRATION • SENSORS, LEVEL • FAILURE, INSTRUMENT • SET POINT • PURIFI • REACTOR SAFETY SYSTEM

106060

CONTAINMENT PURGE VALVES HAVE EXCESSIVE LEAKAGE AT ZION 2

COMMONWEALTH EDISON, ILL.

3 PGS. LTR W/AL 50-304/75-33 TO NRC DIRECTOR OF REGULATORY OPERATIONS, REGION III, SEPT. 26, 1975, DOCKET 50-304, TYPE--PWR, RFG--WEST., AE--SGT E LUNDY

CAUSE - WASKETS OUT OF ADJUSTMENT. DURING LEAK RATE TESTS WITH THE REACTOR SHUTDOWN, THE CONTAINMENT PURGE SUPPLY AND EXHAUST VALVES WERE UNABLE TO HOLD PRESSURE. THE SEATING WASKETS WERE ADJUSTED AND LUBRICATED. THE NUMBER WASKETS WHICH THE VALVES SEAT AGAINST, DRY OUT WITH TIME AND ARE PUSHED OUT OF ADJUSTMENT EACH TIME THE VALVES ARE CYCLED. A SILICON GREASE FILM IS EXPECTED TO ALLOW THE VALVE SURFACE TO SLIDE EVENLY OVER THE SEATING WASKET. THESE ARE 42 INCH HENRY PRATT CO., MODEL 184B PS OFFSET DISC. BUTTERFLY VALVES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) • VALVES • CONTAINMENT PURGE • LEAK RATE • TEST, LEAK RATE • TEST, SYSTEM OPERABILITY • LUBRICATION • FAILURE, EQUIPMENT • FAILURE, MAINTENANCE ERROR

106098

REACTOR COOLANT SYSTEM OVERPRESSURIZED AT ZION 2

COMMONWEALTH EDISON, ILL.

3 PGS. LTR W/AL 50-304/75-35 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION III, SEPT. 26, 1975, DOCKET 50-304, TYPE--PWR, RFG--WEST., AE--SGT E LUNDY

CAUSE - PROCEDURAL DEFICIENCY AND OPERATOR ERROR. DURING A PWR INTERLOCK TEST AT COLD SHUTDOWN CONDITIONS, A VALVE WAS CLOSED AT A SIMULATED RCS PRESSURE OF 400 PSIG ISOLATING THE LETDOWN PATH WHILE A CHARGE PUMP WAS OPERATING. RCS PRESSURE INCREASED FROM 72 TO 1300 PSIG IN 15 MINUTES WITH RCS TEMPERATURE OF 80 F. THE PUMP WAS SECURED AND EXCESS LETDOWN ESTABLISHED. PRESSURE RETURNED TO THE INITIAL VALUE IN 23 MINUTES. ANALYSIS INDICATED NO DAMAGE OCCURRED. PROCEDURES LACKED SUFFICIENT WARNING OF THE POTENTIAL OF THIS TRANSIENT. THE OPERATORS RESPONSE COULD HAVE BEEN MORE TIMELY TO REDUCE THE PEAK PRESSURE. PROCEDURE HAS BEEN REWRITTEN.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) • OVERPRESSURE TRANSIENT • MAIN COOLING SYSTEM • TEST, SYSTEM OPERABILITY • FAILURE, ADMINISTRATIVE

100058 CONTINUOUS
CONTINUOUS PROCEDURES AND MANUALS • OPERATOR ACTION • FAILURE, OPERATOR ERROR

100965
CHARGING PUMP VALVES NOT TESTED ON TIME AT ZION 2
COMMONWEALTH EDISON CO., ILL.
3 PGS. LTR W/AD 50-334/75-37 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION III, OCT. 3, 1975, DOCKET 50-304. TYPE--PMR, NRC--WEST., AE--SUT & LUNDY

CAUSE - SHIFT ENGINEER OVERSIGHT. CENTRIFUGAL CHARGING PUMP MOTOR OPERATOR VALVES WERE TESTED 20 HOURS BEFORE THE ALLOWABLE TIME INTERVAL LIT. DUE DATE NOTIFICATION FORMS STIPULATING THE LATEST ACCEPTABLE DATE WERE POSTED IN THE SHIFT ENGINEER'S OFFICE BUT WERE OVERLOOKED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PMR) • PRETEST INTERVAL • TESTING • PVALVES • FEEDWATER • FAILURE, OPERATOR ERROR

107414
AUXILIARY FEEDWATER STOP VALVE FAILS TO OPEN AT ZION 2
COMMONWEALTH EDISON, ZION, ILL.
3 PGS. LTR W/AD 50-334/75-38 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION III, OCT. 10, 1975, DOCKET 50-304. TYPE--PMR, NRC--WEST., AE--SUT & LUNDY

CAUSE - RELAY CONTACTS FAIL TO CLOSE. WHILE COOLING DUMP, STEAM GENERATOR 2C RESERVE AUXILIARY FEEDWATER STOP VALVE FAILED TO OPEN FROM THE CONTROL ROOM SWITCH. IT WAS OPENED MANUALLY. THE 8 CONTACTS THAT HAVE TO CLOSE TO ENERGIZE THE OPENING CIRCUIT WERE NOT MAKING UP. THE CONTACTS WERE CLEANED, FILED, AND ADJUSTED FOR FREE MOTION.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PMR) • PVALVES • FEEDWATER • FAILURE, INSTRUMENT • PRELAYS • FAILURE, MAINTENANCE ERROR • VALVE OPERATIONS

107094
CONTAINMENT COOLER VALVE FAILS TO OPEN AT ZION 2
COMMONWEALTH EDISON, ZION, ILL.
3 PGS. LTR W/AD 50-334/75-39 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION III, OCT. 31, 1975, DOCKET 50-304. TYPE--PMR, NRC--WEST., AE--SUT & LUNDY

CAUSE - TORQUE SWITCH SET TOO LOW. DURING A TEST WITH THE REACTOR AT 82% POWER, A VALVE IN THE CONTAINMENT COOLING SYSTEM FAILED TO OPEN. THE TORQUE SWITCH SETTING WAS TOO LOW CAUSING THE VALVE TO TORQUE OUT DUE TO PUMP DISCHARGE PRESSURE ON THE VALVE. THE SMO-00 LIMITED TORQUE OPERATOR TORQUE SWITCH SETTING WAS INCREASED FROM 1.0 TO 1.75. MAXIMUM ALLOWABLE SETTING IS 2.0. A SIMILAR VALVE FAILED A DAY EARLIER FOR THE SAME REASON.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PMR) • PVALVES • CONTAINMENT AIR COOLING • TEST, SYSTEM OPERABILITY • INSTRUMENT, SWITCH • SET POINT • FAILURE, FABRICATION ERROR • VALVE OPERATIONS

107092
CONTAINMENT SPRAY VALVE NOT PROPERLY ALIGNED AT ZION 2
COMMONWEALTH EDISON, ZION, ILL.
3 PGS. LTR W/AD 50-334/75-40 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION III, OCT. 31, 1975, DOCKET 50-304. TYPE--PMR, NRC--WEST., AE--SUT & LUNDY

CAUSE - PHILLUMES NOT REALIGNED. FOLLOWING A TEST ON CONTAINMENT SPRAY SYSTEM 2B, A VALVE WAS NOT REALIGNED PROPERLY. THE MISALIGNMENT WAS FOUND WHEN A VALVE ON CS SYSTEM 2A FAILED. PHILLUMES FOR REALIGNMENT WAS SIGNED AS BEING COMPLETE. THIS ERROR NEGATED 2 OF THE 3 SPRAY AUGMENTATIVE SYSTEMS FOR 6 HOURS. THIS WAS AN OPERATOR OVERSIGHT. THE VALVE WAS OPENED IMMEDIATELY. THE REACTOR WAS AT 82% POWER.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PMR) • PVALVES • CONTAINMENT SPRAY • FAILURE, OPERATOR ERROR • PROCEDURES AND MANUALS • TEST, SYSTEM OPERABILITY

107093
CONTAINMENT COOLING SYSTEM VALVE FAILS TO OPEN AT ZION 2
COMMONWEALTH EDISON, ZION, ILL.
3 PGS. LTR W/AD 50-334/75-41 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION III, OCT. 31, 1975, DOCKET 50-304. TYPE--PMR, NRC--WEST., AE--SUT & LUNDY

107893 CONTINUUM

CAUSE - TORQUE SWITCH SET TOO LOW. DURING TESTING WITH THE REACTOR AT 83% POWER, A VALVE IN THE CONTAINMENT COOLING SYSTEM FAILED TO OPEN AGAINST PUMP PRESSURE. THE TORQUE SWITCH SETTING WAS TOO LOW CAUSING THE VALVE TO TORQUE OUT. THE SWITCH SETTING FOR THE SMO-30 LIMITING OPERATION WAS INCREASED FROM 1.3 TO 1.75. MAXIMUM ALLOWABLE SETTING IS 2.0.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) + VALVES + CONTAINMENT AIR COOLING + TEST, SYSTEM OPERABILITY + INSTRUMENT, SWITCH + SET POINT + FAILURE, FABRICATION ERROR + VALVE OPERATORS

108543

SAFETY INJECTION OCCURS AT ZION 2

COMMONWEALTH EDISON CO., ZION, ILL.

2 PGS. LTR W/AL 50-304/75-42 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION III, NOV. 20, 1975, DOCKET 50-304, TYPE--PWR, MFG--WEST., AE--SGT & LUNDY

CAUSE - ISOLATION VALVE FAILURE. THE UNIT WAS OPERATING AT 2730 MW WHEN A REACTOR TRIP OCCURRED DUE TO LOOP D LOW FLOW. DISAS. ON LOOP D HOT LEG ISOLATION VALVE HAD DROPPED. WHILE THE UNIT WAS IN HOT SHUTDOWN, THE DISAS. WHICH HAD BEEN WEDGED HALF CLOSED, DROPPED COMPLETELY WHEN THE PUMP WAS STOPPED. WITH NO FLOW, LOOP D COOLED. WHEN THE PRESSURE DIFFERENTIAL BETWEEN THIS LOOP AND THE OTHERS REACHED 100 PSI, SAFETY INJECTION WAS INITIATED. ASSURED OF NO STEAM LINE ACCIDENT, THE OPERATION TERMINATED INJECTION IN 3 MINUTES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) + SAFETY INJECTION + FAILURE, EQUIPMENT + VALVES + CONTAINMENT ISOLATION + COOLING SYSTEM, SECONDARY + REACTOR SHUTDOWN + SCRAM, REAR

108542

CONTAINMENT PURGE ISOLATION VALVE FAILS TO CLOSE AT ZION 2

COMMONWEALTH EDISON CO., ZION, ILL.

3 PGS. LTR W/AL 50-304/75-42 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION III, DEC. 4, 1975, DOCKET 50-304, TYPE--PWR, MFG--WEST., AE--SGT & LUNDY

CAUSE - DEFECTIVE SOLENOID. WHILE TESTING WITH THE REACTOR AT 82% POWER, THE CONTAINMENT PURGE ISOLATION VALVE FAILED TO CLOSE. THE SOLENOID IN THE SUPPLY AIR LINE VALVE WAS LOOSE PREVENTING AIR FROM BLEEDING FROM THE VALVE OPERATOR. AFTER THE SOLENOID WAS TIGHTENED DOWN, THE VALVE OPERATED PROPERLY.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) + VALVES + CONTAINMENT ISOLATION + CONTAINMENT PURGE + SOLENOID + PNEUMATIC SYSTEM + FAILURE, MAINTENANCE ERROR + TEST, SYSTEM OPERABILITY

108528

SET POINT DRIFT IN PRESSURIZER LEVEL TRANSMITTERS AT ZION 2

COMMONWEALTH EDISON CO., ZION, ILL.

2 PGS. LTR W/AL 50-304/75-43 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION III, DEC. 4, 1975, DOCKET 50-304, TYPE--PWR, MFG--WEST., AE--SGT & LUNDY

CAUSE - ZERO SHIFT. DURING A TEST WITH THE REACTOR AT 85% POWER, 2 PRESSURIZER LEVEL TRANSMITTERS WERE FOUND TO BE LOW BY 3.9% AND 7.6% RESPECTIVELY. THE CAUSE WAS ZERO SHIFT. THE BARTON MODEL 300-351 TRANSMITTERS WERE RECALIBRATED.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) + INSTRUMENT, SWITCH + INSTRUMENT CALIBRATION + SENSORS, LEVEL + TEST, SYSTEM OPERABILITY + FAILURE, INSTRUMENT + SET POINT + DRIFT + PRESSURIZER + REACTOR SAFETY SYSTEM

108539

MAIN STEAM ATMOSPHERIC RELIEF VALVE LIFTS AT ZION 2

COMMONWEALTH EDISON CO., ZION, ILL.

2 PGS. LTR W/AL 50-304/75-45 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION III, DEC. 5, 1975, DOCKET 50-304, TYPE--PWR, MFG--WEST., AE--SGT & LUNDY

CAUSE - SET POINT DRIFT IN E/P CONVERTER. WHILE OPERATING AT 44% POWER, LOOP 2 ATMOSPHERIC RELIEF VALVE WAS FOUND TO BE LIFTING AT REGULAR INTERVALS. THE E/P CONVERTER WAS CALIBRATED. THE VALVE WAS FOUND TO BE LIFTING IN A HIGH PNEUMATIC OUTPUT BEING SENT TO THE VALVE POSITIONER. THE AIR LINES FROM THE POSITIONER WERE CLEANED AND THE E/P CONVERTER AND POSITIONER WERE BOTH CALIBRATED. THE VALVE WAS RETURNED TO SERVICE WITHIN 2 HOURS 15 MINUTES.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

100039 *CONTINUUM
 ZION 2 (PWR) * VALVES * PRESSURE RELIEF * COOLING SYSTEM, SECONDARY * FAILURE, INSTRUMENT * PNEUMATIC SYSTEM
 * SEE POINT * DRIFT

100037
 DIESEL GENERATOR DEVELOPS SEVERE LUBE OIL LEAK AT ZION 2
 COMMONWEALTH EDISON CO., ZION, IL
 3 PGS, LTR W/NO 50-304/75-46 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION III, DEC. 13, 1975, DOCKET 50-304, TYPE-PWR, NRG-MEST., AE-SGT & LUNDY

CAUSE - FILTER GASKET FAILURE. WHILE DIESEL GENERATOR 2A WAS BEING LOAD TESTED WITH THE REACTOR OPERATING AT 60% POWER, A SEVERE LEAK DEVELOPED AT THE MAIN LUBE OIL FILTER. THE OPERATOR TRIPPED THE ENGINE. A GASKET ON THE MAIN LUBE FILTER HAD FAILED. THE LUBE OIL PUMP RELIEF VALVE (NOMINALLY SET AT 75 PSIG) HAD STUCK CLOSED ALLOWING THE OIL PRESSURE TO EXCEED 110 PSIG. BLOWING THE GASKET. SOME HOUGH SPOTS WERE FOUND ON THE RELIEF VALVE INTERNAL SLIDING SURFACE. THE SURFACE WAS HONED SMOOTH. THE VALVE THEN MAINTAINED THE OIL PRESSURE AT 75 PSIG.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) * GENERATOR, DIESEL * ENGINES, INTERNAL COMBUSTION * TEST, SYSTEM OPERABILITY * LUBRICATION * LEAK * VALVES * PRESSURE RELIEF * SEAL * PRESSURE, INTERNAL

109280
 CONTAINMENT GRAB SAMPLES NOT TAKEN AT ZION 2
 COMMONWEALTH EDISON CO., ZION, IL
 3 PGS, LTR W/NO 50-304/75-47 TO NRC DIRECTORATE OF REGULATORY OPS S, REGION III, DEC. 30, 1975, DOCKET 50-304, TYPE-PWR, NRG-MEST., AE-SGT & LUNDY

CAUSE - LACK OF COMMUNICATION. MANUAL GRAB SAMPLES WERE NOT TAKEN AS REQUIRED WHILE THE CONTAINMENT PARTICULATE RADIATION MONITOR WAS INOPERABLE. THE RADIATION MONITOR HAD BEEN OUT OF SERVICE AND THE RADIATION PROTECTION DEPARTMENT UNDERSTOOD THAT IT HAD BEEN PLACED BACK IN SERVICE. HOWEVER, THE MONITOR WAS HAVING INTERMITTENT FAILURE OF ITS POWER SUPPLY. COMMUNICATIONS BETWEEN THE SHIFT PERSONNEL AND RADIATION PROTECTION WAS NOT CLEAR. PROCEDURES WERE MODIFIED TO PREVENT RECURRENCE.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) * SAMPLING * CONTAINMENT * MONITORING SYSTEM, RADIATION * COMMUNICATION * FAILURE, ADMINISTRATIVE CONTROL

109279
 LOW STEAMLINE PRESSURE DISTABLE MALFUNCTION AT ZION 2
 COMMONWEALTH EDISON COMPANY, ILLINOIS
 3 PGS, LTR W/NO 50-304/75-48 TO NRC DIRECTORATE OF REGULATORY OPERATIONS, REGION 3, DEC. 30, 1975, DOCKET 50-304, TYPE-PWR, NRG-MEST., AE-SGT & LUNDY

CAUSE - SWITCH POSITIONED IMPROPERLY. DURING A HEATUP, A LOW STEAMLINE PRESSURE STATUS LIGHT WAS NOT LIT WHILE PRESSURE WAS BELOW 600 PSIG. THE LEAD/LAG MODULE MODE SELECTOR SWITCH WAS FOUND IN THE IN-BETWEEN POSITION CAUSING AN IMPROPER OUTPUT TO THE COMPARATOR. THE SWITCH PROBABLY WAS ACCIDENTALLY MOVED IN THE IN-BETWEEN POSITION AFTER THE LAST TEST.

AVAILABILITY - NRC PUBLIC DOCUMENT ROOM, 1717 M STREET, WASHINGTON, D. C. 20545 100 CENTS/PAGE -- MINIMUM CHARGE \$2.00

ZION 2 (PWR) * INSTRUMENT, SWITCH * SENSORS, PRESSURE * ELECTRONIC FUNCTION UNITS * FAILURE, MAINTENANCE ERROR * TESTING * FAILURE, INSTRUMENT * PLANT PROTECTIVE SYSTEM

REYNOLDS INDEX

A COLLECTION OF REYNOLDS IS USED TO DENOTE THE MAIN SAFETY RELATED POINTS COVERED IN EACH ARTICLE. THE FOLLOWING INDEX IS AN ALPHABETICAL LISTING OF THE REYNOLDS GIVING REFERENCES TO EACH ARTICLE WHICH WAS KEYED TO IT.

ACCIDENT ANALYSIS				ARKANSAS NUCLEAR 2 (PWR)			
104031 P227				102240 P 13	104077 P 14	104087 P 14	104089 P 14
ACCIDENT, CONTROL ROD DRIPIN				ATMOSPHERIC DIFFUSION			
100330 P132	100337 P132			105505 P193			
ACCIDENT, CONTROL ROD EJECTION				AUXILIARY			
099703 P101				107898 P169	104078 P 82	104078 P188	104080 P189
ACCIDENT, CRITICALITY				104270 P 30	104444 P193		
102475 P236				AUXILIARY COOLING			
ACCIDENT, DESIGN CASES				093577 P 2	093638 P164	093618 P180	100872 P 20
100505 P490	100635 P 94			100908 P176	100914 P 84	100915 P202	101149 P182
ACCIDENT, LOSS OF COOLANT				101437 P 71	102169 P 38	102567 P103	102634 P212
094301 P 10	104051 P227			102531 P194	104296 P 6	104698 P209	104829 P223
ACCIDENT, LOSS OF POWER				104938 P 90	105020 P 28	105572 P 81	106354 P 91
093292 P160	100611 P 36	101458 P 55	102164 P 38	106355 P 71	106633 P 47	106637 P 93	106642 P 94
100207 P227	100617 P179	103823 P178	108853 P179	106655 P177	107097 P174	107074 P 99	108249 P 33
104615 P 90				AUXILIARY COOLING SYSTEM			
ACCUMULATION				093256 P160	093532 P128	093608 P164	093618 P180
103457 P100				099044 P200	101444 P177	102554 P 71	103126 P 23
ACCUMULATIONS				103652 P160	103685 P 40	104304 P169	105836 P117
094411 P150	102531 P193	104942 P185	105277 P184	107938 P168	108832 P 86		
106636 P 53	109198 P234			BACKFIT			
ACID				093497 P201	093630 P219	099201 P230	102473 P 57
102535 P 79				104048 P 32	104078 P231	104232 P 32	
ACTUATOR				BATTERIES CHARGERS			
106526 P160				093248 P162	103133 P272	104964 P115	105728 P239
ADJUSTIVE				108541 P149			
ADJUTANT	100684 P 5	105521 P 8		DAY			
ADJUTANT				108290 P 95			
ADJUTANT				HEATING			
104636 P 13				103688 P 40	103713 P248	104246 P 6	105543 P229
ADMINISTRATIVE CONTROL				106373 P 66	106996 P148		
107916 P153				BEAVER VALLEY 1 (PWR)			
AGENCY, ARC				104076 P 14	109606 P 15		
100504 P 24	100905 P197	104076 P231	104404 P 41	BELLEFOUNT 1 (PWR)			
100074 P 99	105208 P240			109612 P 15			
AIR				BELLEFOUNT 2 (PWR)			
102408 P 85	104065 P171			109612 P 15			
AIR COLLU				ALUMINUM			
106454 P172				103675 P247	103872 P122	104697 P 43	104941 P124
AIR DRIERS				106309 P156	107513 P148	108573 P 61	108791 P156
100078 P152	103589 P110	101169 P110		109288 P149			
AIRBORNE RELEASE				BLOWERS			
093533 P120	093548 P201	093631 P235	100265 P181	093242 P164	093550 P 17	093601 P235	099377 P101
100394 P202	100368 P230	100911 P 30	102467 P205	101453 P 20	102170 P 21	102477 P246	103645 P165
102408 P 35	103675 P237	103655 P 69	103888 P208	103903 P145	104862 P 42	106379 P 81	106576 P148
103530 P198	103905 P137	104062 P184	104305 P 25	106631 P162	106637 P 93	106964 P162	106992 P 75
104415 P 24	104814 P 20	104824 P238	104834 P142	107793 P 92			
104602 P 28	104945 P110	104982 P185	104991 P131	BURN			
105513 P 27	105537 P106	105552 P232	105727 P238	093675 P242	103263 P190	102171 P245	102446 P154
105733 P 25	106307 P212	106310 P210	106315 P185	102553 P 71	103006 P154	103896 P248	104213 P156
106370 P 27	106967 P214	107696 P188	107778 P 30	104942 P185	104930 P195	104945 P103	105277 P184
100000 P155	100210 P143	108435 P217	108240 P216	106449 P137	106605 P 48	106637 P 47	108247 P223
108241 P217	104546 P211	108874 P 30	108877 P 61	109248 P106			
109264 P218	109540 P 62	109581 P 62		BREAKER			
ANIMAL, BIRD				093242 P164	093540 P120	093550 P 17	093616 P 77
100529 P 49				099039 P200	099100 P199	099688 P 34	100041 P 83
ANIMAL, FISH				100083 P202	100276 P 63	100345 P 92	100415 P 78
093495 P 2	093573 P 1	093574 P 1	093575 P 1	101453 P 20	101457 P 55	101458 P 55	102134 P121
093714 P 2	100272 P 2	100273 P 3	100416 P 3	102239 P 51	102490 P 79	102527 P205	103200 P223
100807 P 3	103114 P154	105512 P 27	105528 P154	103237 P227	104044 P129	104063 P223	104734 P114
106312 P155	107694 P155	109600 P 31		104829 P221	105044 P 26	105071 P114	105174 P124
ANIMAL, INVERTEBRATE				105180 P116	105492 P157	106344 P 67	106386 P 46
100270 P 95	104253 P 90			106611 P162	106637 P 93	106982 P 75	107896 P124
ANNUALATIONS				108234 P126	108826 P 52	108836 P 83	109582 P 52
100354 P191	101780 P192	102546 P112	103051 P 37	BATTLE FRACTURE			
100604 P 47	106615 P 68	107742 P133	108224 P114	103127 P 23			
108266 P240	109289 P149			BUILDING			
ARKANSAS NUCLEAR 1 (PWR)				099114 P 33	099377 P101	099379 P229	100073 P191
093495 P 2	093573 P 1	093574 P 1	093575 P 1	100258 P176	100915 P202	101147 P136	102136 P144
093576 P 1	093577 P 2	094113 P 1	094396 P 2	102467 P205	102468 P204	103645 P145	103891 P123
093714 P 2	100272 P 2	100273 P 3	100416 P 3	104060 P152	104365 P220	104963 P174	107420 P198
100602 P 3	107611 P 3	103123 P 4	103129 P 3	107524 P178	108539 P220		
103486 P 4	103654 P 4	103658 P 5	103659 P 5	ATPASS			
103660 P 5	103689 P 5	103876 P 5	104041 P 6	103096 P 13	100431 P 43	101444 P157	103127 P 23
104005 P 6	104194 P 6	104296 P 6	104821 P 6	103874 P 40			
104077 P 6	105157 P 4	105286 P 7	105287 P 7	CABLES AND CONNECTORS			
105288 P 7	105518 P 7	105519 P 7	105520 P 8	093180 P 74	093551 P 17	097020 P 54	099079 P203
105521 P 8	106374 P 6	106375 P 8	106611 P 9	099100 P199	099664 P 54	099705 P120	100041 P 53
106657 P 9	106973 P 9	107411 P 10	107412 P 10	100083 P202	100345 P 92	100433 P243	100435 P 98
107781 P 10	107782 P 10	107946 P 11	107914 P 11	103085 P 36	103919 P 15	101170 P121	101447 P223
107915 P 10	108075 P 11	108077 P 11	108202 P 11	107121 P 36	102135 P 56	102148 P 88	102160 P 22
108233 P 12	108234 P 12	108540 P 12	108540 P 12	102164 P 38	102311 P222	102531 P193	102890 P 89
100030 P 12	109274 P 13	109275 P 13	109276 P 13				

BLANK PAGE

COOLING TOWER
 103801 P154 102449 P204 103733 P129 105524 P210
 105527 P155 105722 P211 106309 P155 106312 P155
 106791 P156 109288 P149
 COOLING TOWER, MECHANICAL
 105524 P210 105722 P211
 CUMULATIVE COMPONENTS
 093496 P200 100073 P161 104667 P 28
 CUMULATIVE REFLUDDING SYSTEM
 093421 P109 103054 P113 104517 P213 106336 P211
 CORROSION
 093160 P 74 099374 P 52 100345 P 52 101700 P 64
 103335 P137 104810 P232 104964 P177 105050 P 53
 105530 P196 105721 P211 106313 P167 106354 P 91
 106355 P 91 107430 P226 107894 P169 108016 P 99
 CRACK
 103355 P175 102536 P245 102615 P173 103662 P160
 105520 P 6 106311 P210 106657 P 9 107915 P 10
 108434 P 12 108649 P 14 108826 P 52 108875 P165
 109579 P125
 CRANE
 106258 P176 102355 P170 102532 P 76 107523 P178
 108255 P188 109631 P100
 CNUD
 099017 P139 099111 P150 100072 P191 100373 P161
 100805 P143 100262 P191 100265 P181 100418 P140
 101437 P 71 101456 P143 101711 P165 102138 P 56
 102273 P192 102477 P246 102478 P183 103119 P164
 103899 P 60 103905 P187 103906 P137 104719 P194
 104734 P114 104954 P 66 104960 P171 105163 P 73
 105283 P137 106305 P244 106454 P172 106466 P117
 107517 P 60 107764 P 75 108078 P 52 108848 P 97
 CRYSTAL RIVER 3 (PMR)
 108227 P 51
 DAMAGE
 093508 P234 100258 P176 100274 P 31 102532 P 76
 104890 P 89 102896 P227 103049 P 90 103118 P193
 104125 P 23 104069 P243 104349 P 24 104681 P177
 105020 P 24 105520 P 8 106613 P141 106969 P213
 107520 P178 108227 P 51 108230 P224 108255 P188
 108850 P 47 108875 P163
 DATA COLLECTION
 102114 P 78 103487 P159
 DATA PROCESSING
 102338 P128 104404 P 41
 DAVIS-BESSE 1 (PMR)
 102238 P 51 102242 P 51 104706 P 52
 DEFORMATION
 104405 P174 107225 P133 108878 P189
 DEMINERALIZERS
 100924 P 64 103459 P104
 DESIGN CRITERIA
 099201 P200 100277 P173 101708 P 51 103904 P 59
 106617 P213 107430 P 99
 DESTRUCTIVE WIND
 103550 P 39 106609 P 47
 DIABLO CANYON 1 (PMR)
 099374 P 52
 DIABLO CANYON 2 (PMR)
 099374 P 52 108026 P 52
 DISCHARGE
 093599 P201 103654 P 5 103658 P 5 103659 P 5
 103660 P 4 103876 P 5 104736 P198 105157 P 9
 105290 P 26 105527 P155 105722 P211 106367 P 28
 106368 P 27 106377 P 86 107698 P239
 DISPLACEMENT
 106903 P174
 DOSE MEASUREMENT, EXTERNAL
 107969 P136
 DUSTMETRY
 107969 P136
 DRAINAGE
 102468 P204 103338 P105
 DRIFT
 093260 P262 093604 P242 094741 P231 093729 P137
 094731 P197 099021 P104 099025 P225 099710 P245
 100072 P191 100098 P236 100262 P191 100414 P 70
 100434 P191 100436 P181 100575 P 70 100896 P157
 100923 P 73 100927 P244 101082 P244 101168 P111
 101445 P102 101460 P 56 101775 P111 102165 P157
 102166 P150 103000 P246 103057 P 38 103444 P 58
 103457 P103 103471 P129 103629 P206 103630 P206
 103633 P 72 103661 P160 103676 P151 103886 P208
 103887 P207 103891 P123 103895 P237 104234 P 59
 104857 P195 104858 P 59 104860 P209 105172 P116
 105298 P 67 105516 P 45 105549 P 56 105715 P185
 105719 P167 105730 P152 106316 P185 106652 P186
 106664 P167 106813 P253 107431 P187 107516 P239
 108271 P224 108286 P240 108526 P252 108527 P149
 108818 P 96 108870 P 96 108883 P153 108889 P252
 108894 P233 108899 P 98 108851 P 97 109271 P 50
 109285 P214 109287 P 61
 EARTHQUAKE
 106635 P 99
 ECONOMICS
 093664 P197 093665 P 53 109284 P 54 109413 P197
 106009 P 89 105548 P 67
 ECOSYSTEM, AQUATIC
 109253 P 58 109297 P107
 EFFECT
 104072 P 60 106613 P161
 EFFECT, AGE
 094731 P197 101732 P 64 102793 P 54 104258 P196
 EFFECT, PH
 105521 P 8
 EFFLUENT
 093599 P201 099031 P106 099355 P 54 099356 P 53
 099196 P 33 099342 P 34 099357 P 54 100347 P 34
 102116 P158 102117 P158 102668 P 54 102669 P206
 102470 P203 102487 P158 102665 P 53 102666 P 53
 102982 P 57 103128 P 4 103129 P 5 103130 P159
 103336 P105 103449 P235 103568 P125 103673 P236
 103686 P 5 103687 P 4 103687 P 39 103689 P 5
 103659 P 5 103660 P 4 103731 P129 103875 P 51
 104041 P 6 104194 P 6 104211 P224 104274 P161
 104295 P160 104313 P161 104736 P198 104821 P 6
 104977 P 6 104978 P239 104985 P103 105157 P 7
 105272 P161 105273 P210 105276 P 7 105287 P 7
 105288 P 7 105289 P 64 105290 P 65 105315 P 7
 105519 P 7 105526 P210 105547 P106 105551 P171
 105731 P161 106348 P 33 106347 P 28 106358 P 27
 106375 P 8 106377 P 46 106617 P 9 107411 P 10
 107412 P 10 107413 P162 107511 P133 107525 P215
 107688 P239 107731 P 13 107914 P 11 108075 P 11
 108077 P 11 108202 P 11 108209 P216 108233 P 12
 108236 P215 108237 P216 108246 P124 108543 P 17
 108830 P 12 109253 P 49 109274 P 13 109275 P 13
 109296 P149 109296 P107 109297 P107 109298 P105
 ELASTICITY
 102777 P171
 ELECTRIC ARC
 093550 P 17 100427 P150 108761 P217
 ELECTRIC POWER
 093540 P123 100392 P123 100243 P140 100345 P 77
 100390 P123 100430 P 19 100435 P 48 100835 P 36
 102134 P121 102135 P 56 102164 P 53 103137 P 22
 103207 P227 103493 P122 103493 P122 103493 P122
 103657 P 39 10373 P 90 103875 P 63 104044 P129
 104068 P194 104312 P 36 104402 P 41 104736 P198
 105071 P114 105716 P147 105726 P239 106311 P193
 106352 P 91 106458 P 74 106621 P168 107934 P 63
 108513 P 53 108824 P 30 109496 P 63 109653 P177
 109276 P 18
 ELECTRIC POWER, NOMINAL
 102164 P 36
 ELECTRIC POWER, UNINTERRUPTED
 108836 P 83 108853 P179
 ELECTRICAL CONDUCTION
 093551 P 17 099705 P120 100898 P 63
 ELECTRONIC FUNCTION UNITS
 093239 P 15 093246 P131 093257 P 15 093258 P242
 093552 P 17 093573 P164 093625 P 17 099318 P 53
 099112 P156 099645 P 18 100414 P 70 100575 P 70
 100582 P226 100913 P 84 100923 P 73 100928 P244
 101459 P 55 102126 P245 102127 P245 102312 P227
 103149 P 72 103627 P 56 103691 P 24 103895 P108
 103894 P246 103895 P237 104234 P 59 104382 P123
 104398 P 25 104399 P 24 104400 P 40 104735 P195
 104857 P195 104858 P 59 105298 P 67 105516 P 45
 105516 P 45 105538 P137 105549 P 66 106331 P138
 106372 P 40 106374 P238 106534 P 29 106658 P224
 107422 P 95 108818 P 96 108820 P 96 108849 P 98
 108851 P 97 109279 P253
 ELEMENTS AND ISOTOPES
 104962 P160
 EMERGENCY COOLING
 099099 P203 103550 P110 107540 P205 108111 P114
 104061 P115 106376 P 4
 EMERGENCY COOLING SYSTEM
 099381 P 16 099732 P109 101457 P 55 101458 P 54
 103693 P194 103891 P123 106335 P212 106463 P133
 108823 P178
 EMERGENCY POWER, ELECTRIC
 093258 P241 101173 P121 101421 P234 101453 P 45
 101781 P165 102134 P121 102298 P231 102544 P231
 104955 P183 104955 P103 105123 P222 105237 P227
 104963 P223 104963 P104 104971 P 41 104971 P114
 104959 P209 104964 P115 105145 P 26 105351 P131
 105071 P114 105173 P105 105344 P 67 106377 P 41
 106837 P 93 107227 P106 107421 P217 108275 P 53
 108276 P178 108284 P196 108519 P 68
 ENGINEERED SAFETY FEATURE

103117 P103
 MYMUGEN
 100000 P 42 100900 P102 107770 P 40
 MYMUGEN
 107420 P 33
 IDENTIFICATION
 093621 P139 100075 P 14 103500 P110 103459 P100
 107220 P110 107910 P153 109012 P 15
 IMPACT SMOKE
 099655 P190 100250 P176
 L-IDENT
 100507 P135 101071 P100 103403 P100
 L-CUREL
 101700 P 60
 IMPERMEANCE
 100400 P 90 107227 P100 107609 P160
 INDICAN POINT 1 (PMB)
 103655 P 60 107900 P 60
 INDICAN POINT 2 (PMB)
 093100 P 70 100300 P 60 100014 P 70 103575 P 70
 103570 P 70 103922 P 70 100923 P 70 101407 P 71
 101733 P 71 102553 P 71 103149 P 72 103632 P 72
 103633 P 72 103034 P 72 104993 P 72 105163 P 73
 103604 P 73 100500 P 73 105040 P 73 105061 P 74
 100440 P 74 100447 P 74 100450 P 74 100532 P 75
 100902 P 75 107764 P 75 107901 P 75 100556 P 76
 100001 P 76 101190 P 76
 INDICAN POINT 3 (PMB)
 102552 P 76 102554 P 71 103044 P 76 100524 P 77
 INDICATORS
 100300 P202
 INSTALLATION
 103300 P230 100653 P 65
 INSERVICE INSPECTION
 102311 P222 100974 P220
 INSTALLATION
 099379 P229 101553 P 80 103700 P 24 100007 P 20
 100001 P177 100700 P 52 100524 P 77
 INSTRUMENTS CALIBRATION
 090261 P231 090729 P107 090731 P197 099021 P100
 099025 P225 099020 P225 099027 P221 099710 P263
 100072 P191 100090 P230 100034 P191 103630 P101
 103575 P 70 100502 P200 100913 P 80 103923 P 70
 100927 P244 100920 P244 101002 P244 101160 P111
 101445 P102 101450 P 50 101460 P 50 101775 P111
 102105 P157 102100 P150 102312 P222 102314 P120
 102400 P144 103000 P240 103007 P 30 103444 P 50
 103453 P247 103457 P103 103471 P129 103549 P 30
 103627 P 50 103629 P200 103630 P200 103633 P 72
 103651 P400 103670 P151 103684 P200 103807 P207
 103891 P123 103899 P237 104072 P 80 104073 P122
 104200 P 50 104293 P 50 104300 P 42 104301 P123
 104517 P213 104524 P230 104530 P 50 104530 P200
 105179 P117 105290 P 67 105510 P 55 105530 P137
 105549 P 80 105719 P147 105730 P157 105732 P 45
 106310 P105 106372 P 40 106400 P130 106599 P 92
 106600 P 24 106613 P250 107431 P107 107775 P 40
 106271 P224 106280 P240 106526 P252 108527 P109
 108010 P 90 108020 P 90 108033 P153 108044 P233
 108049 P 90 108051 P 97 109254 P 90 109205 P210
 109209 P149
 INSTRUMENT, ABNORMAL INDICATION
 100430 P191 100909 P 15 102504 P231 105179 P117
 10543 P249 100534 P 25 107220 P110 107433 P190
 109247 P240
 INSTRUMENT, AMPLIFIER
 093200 P101 103691 P 24 104390 P 25 105045 P110
 105172 P110 106372 P 40
 INSTRUMENT, CONTROL
 100203 P100
 INSTRUMENT, EARTHQUAKE
 103090 P 30 105732 P 45 106372 P 40 109271 P 50
 INSTRUMENT, IN CONE
 090711 P103 102300 P100 103005 P 50 104300 P 42
 INSTRUMENT, INTERLOCK
 093504 P109 100900 P100 101150 P102 102402 P 57
 102600 P212 102600 P100 103059 P113 103112 P122
 104044 P129 104060 P100 104067 P123 105274 P124
 105710 P100 107909 P100 108023 P170
 INSTRUMENT, INTERMEDIATE RANGE
 105713 P147 108023 P150
 INSTRUMENT, LINEAR
 100910 P 20 103471 P129 106020 P 30
 INSTRUMENT, LIQUID LEVEL
 093004 P202
 INSTRUMENT, LOGARITHMIC
 103001 P 24 100927 P140
 INSTRUMENT, METEOROLOGICAL
 090009 P 34 100004 P 35 102120 P 37 102121 P 30
 103550 P 39 100009 P 47 100529 P 49
 INSTRUMENT, NUCLEAR

093630 P126 100900 P 15 100900 P 20 101740 P192
 103390 P 25 100350 P 91 100360 P 95
 INSTRUMENT, POSITION
 103004 P202
 INSTRUMENT, POWER RANGE
 093230 P 15 100913 P 04 100920 P200 103133 P 73
 103139 P 25 103671 P129 103691 P 26 103695 P 50
 106270 P 59 106700 P 42 106803 P 62 107110 P167
 100331 P130 100445 P 92 107422 P 95 108020 P 30
 109259 P109
 INSTRUMENT, PROTECTIVE
 099035 P 50 050000 P 34 103097 P120 103350 P120
 102107 P 21 102100 P 21 102700 P231 102730 P 70
 103500 P231 103692 P110 103695 P147 103691 P160
 103670 P151 103903 P145 104001 P115 104003 P273
 104000 P190 104002 P 41 104050 P209 104994 P 60
 105040 P 20 105040 P 53 105002 P152 106445 P 92
 106450 P 70 106421 P100 106423 P 61 106422 P179
 106425 P170 106450 P 83 106803 P109
 INSTRUMENT, STATUS RANGE
 093020 P 10 103690 P122 104390 P 25 107950 P 60
 INSTRUMENT, SURVEILLANCE
 103330 P212
 INSTRUMENT, SWITCH
 093250 P241 093250 P190 093004 P242 096201 P231
 090720 P139 090729 P107 090731 P197 090017 P139
 090010 P 50 090021 P100 090025 P225 090370 P100
 090072 P 19 090094 P243 090710 P263 100072 P191
 100090 P230 103614 P 70 100430 P101 100575 P 70
 103890 P157 100913 P 04 100923 P 70 100927 P244
 100920 P244 101001 P245 101002 P244 101150 P 23
 101160 P111 101445 P102 101447 P 55 101460 P 50
 101774 P130 101775 P111 102105 P157 102100 P150
 102270 P102 102312 P222 102314 P120 102312 P222
 102535 P 70 102540 P205 103000 P240 103007 P 30
 103149 P 72 103444 P 50 103457 P103 103471 P122
 103490 P247 103629 P200 103630 P200 103633 P 72
 103670 P151 103673 P 90 103684 P200 103807 P207
 103891 P123 103895 P237 104071 P 80 104073 P122
 104204 P 50 104210 P107 104210 P107 104210 P107
 104735 P195 104037 P107 104037 P107 104037 P107
 104003 P 72 104003 P110 104003 P110 104003 P110
 105040 P 20 105172 P110 105172 P110 105172 P110
 105515 P 45 105510 P 45 105522 P 81 105520 P137
 105549 P 60 105715 P105 105719 P147 105720 P110
 105730 P152 106300 P211 106310 P105 106310 P105
 106370 P 81 106400 P130 106400 P130 106400 P130
 106412 P 81 106413 P250 107431 P107 107431 P107
 107435 P 20 107500 P 82 107513 P140 107510 P139
 107700 P 40 107893 P251 107894 P251 107894 P251
 107900 P100 108070 P 82 108071 P224 108070 P100
 108526 P252 108527 P109 108540 P100 108540 P100
 108010 P 90 108020 P 90 108033 P153 108044 P233
 108049 P 90 108051 P 97 108055 P109 108055 P109
 INSTRUMENT, WIDE RANGE
 100430 P 11 103132 P 22 103134 P 22 104390 P 25
 107430 P 29
 INSTRUMENTS, MISC.
 099025 P225 100070 P154 100704 P101 100093 P 35
 102120 P 37 102909 P140 103000 P240 103097 P 30
 103133 P 23 103443 P 50 103444 P 50 103444 P150
 103875 P 40 103894 P240 104204 P 50 104220 P133
 104294 P101 104295 P100 104402 P 41 104403 P234
 106445 P 92 106534 P 29 106600 P224 106602 P100
 106657 P 9 106970 P 95 108519 P 60
 INSULATION
 093500 P230 093551 P 17 099070 P 50 099004 P 54
 100435 P 90 102135 P 56 103103 P222 106052 P100
 108074 P 40 108070 P 52
 INTAKE
 093495 P 2 093573 P 1 093574 P 1 093575 P 1
 099714 P 2 100272 P 2 100273 P 3 100010 P 3
 100802 P 3 102123 P 37 103114 P154 105512 P 27
 105520 P154 105543 P229 106305 P212 106312 P155
 107094 P155
 INTERACTION, SOIL AND STRUCTURE
 104409 P170 106903 P174 107420 P190 108079 P 60
 IODINE
 101732 P 04 102137 P 56 102290 P 04 103930 P100
 104303 P100 106315 P105 107600 P105 107765 P 60
 108040 P155 108237 P210
 IRON
 100352 P175
 JET
 109104 P179
 KENAMURE (PMB)
 093253 P 77 093610 P 77 099043 P 77 100010 P 70
 100007 P 70 102114 P 70 102400 P 70 102400 P 70
 102534 P 70 102535 P 70 103001 P 70 103131 P 70
 103003 P 80 103099 P 80 104071 P 80 104077 P 80

THE INDEX IS ONE IN WHICH THE REPORT TITLES ARE PRESENTED ALPHABETICALLY AND WORDS WHICH APPEAR IN THE TITLE, THE INDEX WORDS ARE ARRANGED ALPHABETICALLY IN A COLUMN IN THE ENTRY IN THE PAGE WITH THE TITLE PRESENTED ABOVE THEM. 0 INDICATES BEGINNING OF TITLE, 1 INDICATES END OF TITLE.

[illegible]

[illegible]

PHRAIDE ISLAND 10	0	ANALOG LINE	BUILDING VENTILATION EXHAUST FAN FAILS AT	100903	P 005
MULLSTONE 20	0	ANALOG LINE	CONTRACTS OF MOTOR CONTROL CENTERS STICK AT	100673	P 000
SECO	0	ANALOG LINE	REC'D VALVE FAILS TO OPEN AT POINT DESIGN 20	000722	P100
	0	ANALOG LINE	FEEDWATER BYPASS VALVE FAILS TO OPEN AT RANCHO	100454	P137
SUMMIT 10	0	ANALOG LINE	FEEDWATER PUMP DISCHARGE CIRCUMT FAILS AT ALHAMBRA	100001	P 79
SUMMIT 10	0	ANALOG LINE	FEEDWATER PUMP DISCHARGE VALVE FAILS TO OPEN AT	100000	P100
SUMMIT 10	0	ANALOG LINE	FEEDWATER PUMP DISCHARGE VALVE FAILS TO OPEN AT	100944	P100
HOBBS ISLAND 20	0	ANALOG LINE	FEEDWATER PUMP DISCHARGE VALVE FAILS TO OPEN AT	100540	P100
WYOMING 20	0	ANALOG LINE	FEEDWATER PUMP DISCHARGE VALVE FAILS TO OPEN AT	100705	P107
	0	ANALOG LINE	FEEDWATER PUMP DISCHARGE VALVE FAILS TO OPEN AT	100837	P107
	0	ANALOG LINE	FEEDWATER PUMP FAILS TO START AT HOBBS	000616	P 77
	0	ANALOG LINE	FEEDWATER PUMP FAILS TO START AT ALHAMBRA	000749	P 70
	0	ANALOG LINE	FEEDWATER PUMP FAILS TO START AT WYOMING 20	100700	P100
MULLSTONE 20	0	ANALOG LINE	FEEDWATER PUMP RESISTED AT HOBBS	100070	P 62
PHRAIDE ISLAND 20	0	ANALOG LINE	FEEDWATER PUMP W/LOWDOWN FAILS TO RESUME AT	000000	P 90
	0	ANALOG LINE	FEEDWATER PUMP LOW D.P. POS-SURE SWITCH FAILS AT	100550	P152
	0	ANALOG LINE	FEEDWATER PUMP JUNCTIONS AT PHRAIDE ISLAND 10	100150	P103
	0	ANALOG LINE	FEEDWATER PUMP NOT TESTED AS REQUIRED AT COB 10	100400	P 66
PHRAIDE ISLAND 10	0	ANALOG LINE	FEEDWATER PUMP PLACED IN MANUAL CONTROL AT	100517	P107
CALVERT CLIFFS 10	0	ANALOG LINE	FEEDWATER PUMP STOPS AT RANCHO SECO	100641	P100
	0	ANALOG LINE	FEEDWATER PUMP SUPPLY VALVE FOUND CLOSED AT	100770	P 60
	0	ANALOG LINE	FEEDWATER PUMP TRIPS AT GENCO	000270	P 62
	0	ANALOG LINE	FEEDWATER PUMP'S FAIL TO START AT HOBBS	100500	P 62
OPEN AT CALVERT CLIFFS 10	0	ANALOG LINE	FEEDWATER STOP VALVE FAILS TO OPEN AT ZION 20	100616	P251
	0	ANALOG LINE	HIGH PRESSURE SAFETY INJECTION VALVE FAILS TO	100150	P 60
	0	ANALOG LINE	MONITOR MONS DEF-CTIVE AT SALEM 1 AND 20	100055	P100
AT THREE MILE ISLAND 10	0	ANALOG LINE	EMERGENCY STOP/SHUT DOWN COOLING WATER LIMITED	000000	P212
AND 20	0	ANALOG LINE	FLOW MONITOR FLOW EXCEEDS LIMIT AT PHRAIDE ISLAND 10	000001	P150
CLIFFS 10	0	ANALOG LINE	TEMPERATURE EXCEEDS LIMIT AT CALVERT	100367	P 20
CLIFFS 10	0	ANALOG LINE	TEMPERATURE EXCEEDS LIMITS AT CALVERT	100360	P 27
0	0	ANALOG LINE	PLUM DIFFERENCE LIMITS EXCEEDED AT COB 10	000304	P 52
CLIFFS 10	0	ANALOG LINE	PLUM DIFFERENCE LIMITS EXCEEDED AT TUNNEY POINT 1	100001	P211
	0	ANALOG LINE	PLUM UPSET CALCULATOR OVERSAY FAIL AT CALVERT	100000	P100
	0	ANALOG LINE	GROWTH OF POISON RODS AT PHRAIDE	000725	P103
MILE ISLAND 20	0	ANALOG LINE	INDICATION FOUND IN RC PUMP MTS AND STOPS AT THREE	100070	P220
	0	ANALOG LINE	OFFSET OUT OF TARGET AND AT SUMMIT 10	100770	P102
AT FT. CALHOUN	0	ANALOG LINE	POWER DISTRIBUTION CHANNEL AT FT. CALHOUN	100404	P 90
	0	ANALOG LINE	POWER DISTRIBUTION CHANNEL TRIP LIMITS OUT OF SPECS	100403	P 90

[illegible]

[illegible]

BATTERED EMERGENCY 0 VIBRATION ATTEMPT FAILS AT COOK 10 102122 P 30
 0 VIBRATION FAILS AT COOK 10 102124 P 37
 RANCHO SECOP 0 VIBRATION PAIN HEAT TRACING CHANNEL INOPERABLE AT COOK 10 102075 P 40
 0 EMERGENCY 0 VIBRATION VALVE FAILS TO OPEN COMPLETELY AT COOK 10 102075 P 40
 0 BOREAC ACID CONCENTRATION IN STORAGE TANK EXCEEDS LIMIT AT 102000 P150
 0 BOREAC ACID CONCENTRATION LOW IN BOREAC ACID TANK AT ZION 20 102171 P245
 0 BOREAC ACID CONCENTRATION LOW IN BOREAC ACID TANK AT ZION 20 094075 P262
 0 BOREAC ACID EXCEEDS LIMIT AT ZION 10 100375 P296
 0 BOREAC ACID HEAT TRACING CHANNEL INOPERABLE AT POINT BEACH 1 102403 P136
 0 BOREAC ACID MIX TANK UNLIFT LINE BLOCKED AT THREE MILE 102000 P214
 0 BOREAC ACID PUMP TAKEN OUT OF SERVICE AT COOK 10 102000 P 40
 0 BOREAC ACID SOLUTION NOT OPERABLE AT THREE MILE ISLAND 10 102002 P215
 0 BOREAC ACID STORAGE TANK HIGH AT TURKEY POINT 40 102007 P220
 0 BOREAC ACID STORAGE TANK VOLUME BELOW LIMITS AT RANCHO SECOP 102000 P197
 0 BOREAC ACID STORAGE AT COOK 10 102005 P 40
 0 BOREAC ACID TANK AT ZION 20 094075 P262
 0 BOREAC ACID TANK AT ZION 20 102171 P245
 0 BOREAC ACID TANK LEVEL DECREASED BELOW LIMIT AT SURREY 20 102030 P 46
 0 BOREAC ACID TANK LEVEL INSTRUMENTS AT REMBURSE 102072 P 00
 0 BOREAC ACID TANK LOW AT ZION 20 102006 P240
 0 BOREAC ACID TRANSFER PUMP FAILS AT COOK 10 104056 P 03
 0 BOREAC ACID TRANSFER PUMP FAILS AT INDIAN POINT 20 100332 P 73
 0 BOREAC ACID TRANSFER PUMP FAILS AT HODGSON 20 102000 P106
 0 BOREAC ACID TRANSFER PUMP FAILS AT HODGSON 20 092350 P106
 0 BOREAC ACID TRANSFER PUMP FAILS AT HODGSON 20 102000 P106
 0 BOREAC ACID TRANSFER PUMP FAILS AT HODGSON 20 102000 P106
 0 BOREAC ACID TRANSFER PUMP FLOW RATE LESS THAN SPEC'S AT COOK 102005 P 03
 0 BOREAC ACID TRANSFER PUMP MOTOR FAILS AT SURREY 20 102005 P106
 0 BOREAC ACID TRANSFER PUMP REMOVED FROM SERVICE AT COOK 10 102072 P 40
 0 BOREAC ACID TRANSFER PUMP REMOVED FROM SERVICE AT COOK 10 102072 P 40
 0 BOREAC ACID TRANSFER PUMP REMOVED FROM SERVICE AT COOK 10 102072 P 40
 0 BOREAC ACID TRANSFER PUMP REMOVED FROM SERVICE AT INDIAN 102001 P 75
 0 BOREAC CONCENTRATION DILUTED AT SURREY 10 102003 P100
 0 BOREAC CONCENTRATION IN ACCUMULATION LESS THAN LIMIT AT 102002 P105
 0 BOREAC CONCENTRATION IN BOREAC ACID STORAGE TANK HIGH AT 102007 P220
 0 BOREAC CONCENTRATION IN BOREAC ACID TANK LOW AT ZION 20 102006 P240
 0 BOREAC CONCENTRATION IN BOREAC INJECTION TANK LOW AT SURREY 20 102000 P105
 0 BOREAC CONCENTRATION IN BOREAC INJECTION TANK LOW AT TURKEY 102000 P220
 0 BOREAC CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT OCTOBER 10 102005 P103
 0 BOREAC CONCENTRATION IN INJECTION TANK AND STORAGE TANK AT 092005 P225
 0 BOREAC CONCENTRATION IN KEMMER NEVER EXCEEDS LIMIT AT 102000 P106
 0 BOREAC CONCENTRATION IN SAFETY INJECTION ACCUMULATION LOW AT 102000 P106
 0 BOREAC CONCENTRATION IN SAFETY INJECTION TANKS LESS THAN 102000 P132
 0 BOREAC CONCENTRATION IN SI ACCUMULATION BELOW LIMITS AT 102077 P106
 0 BOREAC CONCENTRATION IN STORAGE TANKS BELOW LIMIT AT INDIAN 102001 P 76
 0 BOREAC INJECTION TANK AT ZION 20 092005 P201
 0 BOREAC INJECTION TANK LOW AT SURREY 20 102000 P105
 0 BOREAC INJECTION TANK LOW AT TURKEY POINT 40 102000 P220
 0 BOREAC INJECTION TANK RECOMBINATION VALUES FOUND CLOSED AT 102076 P105
 0 BOREAC INJECTION TANK REDUCED AT COOK 10 102007 P 07
 0 BOREAC CONTAINMENT AIR LOCK DOORS OPENED MOMENTARILY AT 102001 P 02
 0 BOREAC CONTAINMENT SPRAY HEADS FOUND INOPERABLE AT 102006 P 96
 0 BOREAC HYDROGEN PURGE BLOWERS FOUND INOPERABLE AT RANCHO SECOP 102006 P102
 0 BOREAC SHIELD BUILDING AIR LOCK DOORS FOUND OPEN AT REMBURSE 102007 P 01
 0 BOREAC ROSES MAY EXCEED PSN VALUES AT SURREY 3 AND 40 102005 P100
 0 BOREAC HEADS LEAK AT SILEN 1 AND 20 102005 P170
 0 BRACKETS INSTALLED IN CONTAINMENT LINER AT HILLSTONE 20 102000 P 00
 0 BREACHED DURING REPAIRING OPERATIONS AT TURKEY POINT 40 102001 P226
 0 BREACH BEAM INADVERTENTLY REMOVED AT OCTOBER 20 102070 P116
 0 BREACHER AND BUS STOPPING RELAY MALFUNCTION AT TURKEY 102070 P227
 0 BREACHER AT COOK 10 092000 P 36
 0 BREACHER CABINETS AT THREE MILE ISLAND 10 092001 P200
 0 BREACHER CABINETS DEFICIENCY AT THREE MILE ISLAND 20 092000 P209
 0 BREACHER DEFICIENCIES AT DAVIS 0556 10 102070 P 51
 0 BREACHER FAILS TO CLOSE AT OCTOBER 20 102070 P116
 0 BREACHER FAILS TO CLOSE AT TURKEY POINT 30 102003 P223
 0 BREACHER FAILS TO CLOSE DURING LOSS OF IND SITE POWER AT 102000 P 50
 0 BREACHER FAILS TO TRIP AT OCTOBER 30 102074 P126
 0 BREACHER FAILS TO TRIP AT THREE MILE ISLAND 10 102072 P209
 0 BREACHER FOUND INOPERABLE AT PHAROS ISLAND 20 102002 P109
 0 BREACHER FOUND STOPPING AT INDIAN POINT 20 102002 P 75
 0 BREACHER FROM EMERGENCY GENERATOR FAILS TO CLOSE AT GEMMA 102000 P 07
 0 BREACHER INOPERABLE AT PHAROS ISLAND 20 102070 P191
 0 BREACHER MALFUNCTIONS AT TURKEY POINT 30 102000 P223
 0 BREACHER TRIPS AT REMBURSE 102000 P 70
 0 BREACHER TRIPS AT TURKEY POINT 30 102070 P223
 0 BREACHER TRIPS CAUSING A UNIT TRIP AT REMBURSE 102000 P 03
 0 BREACHERS AT FAIRLEY 1 AND 20 102005 P 52
 0 BREACHERS NOT PERFORMED ON TIME AT COOK 10 102000 P 00
 0 BREATHING AIR ISOLATION VALVES FOUND OPEN AT OCTOBER 20 102077 P117
 0 BREATHING AT CONNECTICUT VARNER 102000 P 30
 0 BREATHING AT COOK 10 102000 P 30
 0 BREATHING AT THREE MILE ISLAND 10 092001 P200
 0 BREATHING AT TURKEY POINT 30 102002 P223
 0 BREATHING AT TURKEY POINT 40 102002 P223
 0 BREATHING LONG HOLDDOWN BOLTS FOUND ON STEAM GENERATORS AT 102001 P 30
 0 BREATHING SPENT PULP RACK RESTRAINTS AT TURKEY POINT 40 102072 P220
 0 BSBW REPORTED AT ALLEPLATE 1 AND 20 102012 P 15
 ADDITIONAL INFORMATION ON
 ALTERATION OF RECORDS BY

[illegible]

[illegible]

DESCRIPTION	STATUS	CLIFFS	CLIFFS	CLIFFS
ONLINE RANGE NUCLEAR INSTRUMENTATION FAILS AT CALVERT	CLIFFS 10	103134	P 22	
ONLINE RANGE NUCLEAR INSTRUMENTATION FAILS AT CALVERT	CLIFFS 10	100913	P 20	
STAGNANT BEHAVIOR OF HOT LEG TEMPERATURE INPUT AT CALVERT	CLIFFS 10	093549	P 16	
OVERDRIVE MASTER STOP VALVE FAILS AT CALVERT	CLIFFS 10	123125	P 23	
EMERGENCY DIESEL GENERATOR SPILL CHURNING FAILS AT CALVERT	CLIFFS 10	123167	P 21	
OUTLET NOZZLE ON HEAT EXCHANGERS OVERSTRESS AT CALVERT	CLIFFS 10	099101	P 16	
ONLINE RANGE NUCLEAR INSTRUMENTATION FAILS AT CALVERT	CLIFFS 10	100630	P 16	
SAFETY INJECTION ACTIVATION SYSTEM MODULAR FAILS AT CALVERT	CLIFFS 10	093257	P 19	
SAFETY INJECTION ACTIVATION SYSTEM INITIATED AT CALVERT	CLIFFS 10	103427	P 23	
STEAM GENERATOR BLOWDOWN VALVE OPEN TOO LONG AT CALVERT	CLIFFS 10	100096	P 19	
STANDING BLOWBACK CIRCUITS INCAPACITATED AT CALVERT	CLIFFS 10	102106	P 21	
WEST PROCEDURAL REQUIREMENT VIOLATES TECH SPECS AT CALVERT	CLIFFS 10	120403	P 22	
DECONTAMINANT CIRCULATION FAILS TO START IN SLOUGH PUMP AT CALVERT	CLIFFS 10	123430	P 22	
ONLINE RANGE NUCLEAR INSTRUMENTATION FAILS AT CALVERT	CLIFFS 10	123132	P 22	
ONPS HOT LEG TEMPERATURE INPUT FAILS AT CALVERT	CLIFFS 10	099066	P 18	
DECONTAMINANT TEMPERATURE GRADIENT EXCEEDS LIMIT AT CALVERT	CLIFFS 10	123211	P 22	
ONLINE RANGE NUCLEAR INSTRUMENTATION FAILS AT CALVERT	CLIFFS 10	120390	P 23	
SAFETY INJECTION VALVE FAILS TO OPEN AT CALVERT	CLIFFS 10	102140	P 22	
DECONTAMINANT RADIATION MONITOR FAILS AT CALVERT	CLIFFS 10	090197	P 17	
DECONTAMINANT RADIATION MONITOR FAILS AT CALVERT	CLIFFS 10	093475	P 17	
DECONTAMINANT CIRCULATION FAILS TO START AT CALVERT	CLIFFS 10	093550	P 17	
COLD LEG TEMPERATURE INPUT TO HPS FAILS AT CALVERT	CLIFFS 10	107435	P 21	
ABNORMALLY LARGE NUMBER OF FISH COLLECTED AT CALVERT	CLIFFS 10	100008	P 29	
RELEASE OF MOBILE GASES EXCEEDS LIMITS AT CALVERT	CLIFFS 10	100370	P 27	
IRREGULAR COOLANT PUMP UPPER SEAL FAILS AT CALVERT	CLIFFS 10	103649	P 27	
PUMP, UNPLANNED RELEASE OF RADIOACTIVE MATERIAL AT CALVERT	CLIFFS 10	120513	P 22	
PUMP, UNPLANNED RELEASE OF RADIOACTIVE MATERIAL AT CALVERT	CLIFFS 10	123430	P 22	
DISCHARGE EFFLUENT TEMPERATURE EXCEEDS LIMITS AT CALVERT	CLIFFS 10	100360	P 27	
DECONTAMINANT TEMPERATURE EXCEEDS LIMIT AT CALVERT	CLIFFS 10	103290	P 26	
ONLINE RANGE NUCLEAR INSTRUMENTATION FAILS AT CALVERT	CLIFFS 10	100429	P 30	
DISCHARGE TEMPERATURE EXCEEDS LIMIT AT CALVERT	CLIFFS 10	100367	P 28	
DECONTAMINANT RADIATION MONITOR FAILS AT CALVERT	CLIFFS 10	100420	P 28	
INTERNAL PUMP CALCULATION FAILS AT CALVERT	CLIFFS 10	120534	P 29	
UNPLANNED RELEASE OF RADIOACTIVE MATERIAL AT CALVERT	CLIFFS 10	107778	P 30	
UNPLANNED RELEASE OF RADIOACTIVE GAS AT CALVERT	CLIFFS 10	120419	P 27	
DECONTAMINANT TEMPERATURE RISE EXCESSIVE AT CALVERT	CLIFFS 10	105512	P 26	
ONLINE RANGE NUCLEAR INSTRUMENTATION FAILS AT CALVERT	CLIFFS 10	107436	P 29	
UNPLANNED RELEASE OF RADIOACTIVE MATERIAL OCCURS AT CALVERT	CLIFFS 10	100445	P 29	
UNPLANNED RELEASE OF RADIOACTIVE MATERIAL OCCURS AT CALVERT	CLIFFS 10	100402	P 28	
UNPLANNED RELEASE OF RADIOACTIVE MATERIAL OCCURS AT CALVERT	CLIFFS 10	103305	P 28	
NUCLEAR INSTRUMENTATION WITH RANGE CHANNEL FAILS AT CALVERT	CLIFFS 10	099101	P 16	
STEAM GENERATOR ISOLATION SIGNAL SENSOR FAILS AT CALVERT	CLIFFS 10	099065	P 18	
COLD LEG TEMPERATURE INPUT TO CALCULATOR FAILS AT CALVERT	CLIFFS 10	093551	P 17	
RATES OUTSIDE CONTAINMENT HIGHER THAN EXPECTED AT CALVERT	CLIFFS 10	093624	P 18	
REPORT ON CRACKS IN DAMAGE TO SALT WATER PIPING AT CALVERT	CLIFFS 10	105020	P 20	
AMPLIFIER IN NUCLEAR INSTRUMENTATION FAILS AT CALVERT	CLIFFS 10	093230	P 15	
INJECTION ACTIVATION SYSTEM LOGIC MODULE FAILS AT CALVERT	CLIFFS 10	093552	P 17	
INJECTION ACTIVATION SYSTEM LOGIC MODULE FAILS AT CALVERT	CLIFFS 10	093625	P 17	
TEMPERATURE TO THERMAL POWER CALCULATOR FAILS AT CALVERT	CLIFFS 10	123133	P 23	
WATER SYSTEM PIPING CLASSIFICATION IN ERROR AT CALVERT	CLIFFS 10	100072	P 20	
PERFORATED PUMP SUPPLY VALVE FOUND CLOSED AT CALVERT	CLIFFS 10	120270	P 30	
RELEASE OF REACTION COOLANT WASTE MONITOR TANK AT CALVERT	CLIFFS 10	104475	P 26	
RELEASE OF MISCELLANEOUS WASTE RECEIVER TANK AT CALVERT	CLIFFS 10	102159	P 21	
STEAM STOP VALVE IN ISOLATION NOT INSTALLED AT CALVERT	CLIFFS 10	123706	P 24	
ISOLATION VALVE FOUND INSTALLED IMPROPERLY AT CALVERT	CLIFFS 10	103190	P 24	
PRESSURE SAFETY INJECTION VALVE FAILS TO OPEN AT CALVERT	CLIFFS 10	103190	P 24	
IN WASTE GAS PROCESSING AREA EXCEEDS LIMIT AT CALVERT	CLIFFS 10	105733	P 25	
PUMP UPPER SEAL PRESSURE SENSING LINE LEAKS AT CALVERT	CLIFFS 10	121651	P 20	
FOR LOGIC SEQUENCER AND SHUTDOWN SEQUENCER FAILS AT CALVERT	CLIFFS 10	103040	P 26	
INPUT TO THERMAL POWER CALCULATOR FAILS AT CALVERT	CLIFFS 10	103139	P 23	
INPUT TO REACTION PROTECTIVE SYSTEM FAILS AT CALVERT	CLIFFS 10	100390	P 26	
REPORT ON OUT OF TOLERANCE REACTOR INTERNALS AT CALVERT	CLIFFS 20	1		

[illegible]

	SAFETY	CONTACTS IN MAJOR CONTROL CENTERS STICK AT HILLSTONE 20	103673 P 90
	BYAPOR	CONTAINER MAIN LINE VALVE FAILS TO CLOSE AT YAMMER ROME	104817 P 232
YAMMER ROME	BYAPOR	CONTAINER ELECTRICAL PENETRATION HAS EXCESSIVE LEAKAGE AT	100560 P 233
	BYAPOR	CONTAINER LEAKAGE EXCEEDS LIMITS AT YAMMER ROME	105552 P 232
	BYAPOR	CONTAINER TRIP VALVE LEAKS EXCESSIVELY AT YAMMER ROME	100063 P 236
	BYAPOR	CONTAINER TRIP VALVE SOLENOIDS FAIL TO OPERATE AT YAMMER	100004 P 233
20	BYAPOR	CONTAINER AIR LOCK DOORS OPENED TEMPORARILY AT HILLSTONE	104111 P 92
	BYAPOR	CONTAINER AIR PARTICULATE DETECTION PUMP FAILS AT COOK 10	105117 P 96
	BYAPOR	CONTAINER AIR PARTICULATE MONITOR PUMP FAILS AT COOK 10	106373 P 96
	BYAPOR	CONTAINER AND RECIRCULATION SPRAY CHECK VALVE FAILURES	099603 P 100
AT SURRY 20		CONTAINMENT AT INDIAN POINT 20	100576 P 70
		CONTAINMENT AT ZION 10	103675 P 237
		CONTAINMENT AT ZION 10	093601 P 235
		CONTAINMENT BASEMENT AT GENNAO	105297 P 67
20 20		CONTAINMENT BUILDING REINFORCING BAR SPACING AT MIDLAND 1	099670 P 87
		CONTAINMENT COOLER FAILS TO START AT CALVERT CLIFFS 10	093550 P 17
CLIFFS 10		CONTAINMENT COOLER FAILS TO START IN SLOW SPEED AT CALVERT	101653 P 26
		CONTAINMENT COOLER VALVE FAILS TO OPEN AT ZION 20	107094 P 251
		CONTAINMENT COOLING FAN FAILS AT CALVERT CLIFFS 10	102170 P 21
REDAUNDED		CONTAINMENT COOLING SERVICE WATER VALVE FAILS TO OPEN AT	105522 P 81
		CONTAINMENT COOLING SYSTEM VALVE FAILS TO OPEN AT ZION 20	107093 P 251
10	ONCACTA	CONTAINMENT DOME PROTECTIVE COATING FAILS AT BRAVER VALLEY	106006 P 15
		CONTAINMENT DOME GASKET LEAKAGE NOT REPAIRED AT COOK 10	104404 P 61
		CONTAINMENT FAN COIL DAMPER FAILS AT PRAIRIE ISLAND 10	100526 P 108
PRAIRIE ISLAND 20		CONTAINMENT FAN COIL DAMPER IMPROPERLY POSITIONED AT	100835 P 136
		CONTAINMENT FAN COILERS INTERRUPTED AT CONNECTICUT YAMMER	100240 P 33
REDAUNDED		CONTAINMENT FAN SERVICE WATER VALVES FAIL TO OPEN AT	106170 P 81
		CONTAINMENT FAN SERVICE WATER VALVES FAIL TO OPEN AT	106170 P 81
		CONTAINMENT GRAB SAMPLES NOT TAKEN AT ZION 10	109201 P 260
		CONTAINMENT GRAB SAMPLES NOT TAKEN AT ZION 20	109203 P 253
		CONTAINMENT HIGHER THAN EXPECTED AT CALVERT CLIFFS 10	093626 P 18
SURRY 10		CONTAINMENT INSTRUMENT AIR SYSTEM NOT PROPERLY INSTALLED AT	102664 P 181
		CONTAINMENT INTEGRITY AT PRAIRIE ISLAND 10	103115 P 146
		CONTAINMENT INTEGRITY AT PRAIRIE ISLAND 20	099111 P 150
AT TURNER POINT 40		CONTAINMENT INTEGRITY BREACHED DURING REFUELING OPERATIONS	102591 P 226
		CONTAINMENT INTEGRITY VIOLATED AT ROBINSON 20	107909 P 168
		CONTAINMENT INTEGRITY VIOLATED AT TRIJANO	106332 P 221
		CONTAINMENT INTEGRITY VIOLATED IN ACCESS HATCH AT THREE	098713 P 199
WILL ISLAND 10		CONTAINMENT ISOLATION MEMBRANE BARRIER DEFICIENCY AT COOK 1	102169 P 30
YAMMER		CONTAINMENT ISOLATION TRIP VALVE FAILS TO CLOSE AT YAMMER	100631 P 67
		CONTAINMENT ISOLATION VALVE FAILS TO CLOSE AT ZION 10	099716 P 235
		CONTAINMENT ISOLATION VALVE FAILS TO CLOSE AT ZION 20	103088 P 263
		CONTAINMENT ISOLATION VALVE FAILS TO OPERATE AT RANCHO SECO	100370 P 156
CALVERT CLIFFS 10		CONTAINMENT ISOLATION VALVE FOUND INSTALLED IMPROPERLY AT	103126 P 23
CLUMBER 20		CONTAINMENT ISOLATION VALVE FOUND TO BE IMPERABLE AT	107096 P 126
	BYAPOR	CONTAINMENT ISOLATION VALVES FAIL TO CLOSE AT ZION 20	100090 P 263
	BYAPOR	CONTAINMENT ISOLATION VALVES FAIL TO CLOSE AT ZION 20	103090 P 260
AT HILLSTONE 20		CONTAINMENT ISOLATION VALVES NOT PERFORMED WHEN REQUIRED	106353 P 91
		CONTAINMENT LEAK RATE EXCEEDS LIMIT AT SURRY 10	107526 P 107
		CONTAINMENT LINES AT HILLSTONE 20	103349 P 90
		CONTAINMENT PENETRATION BELLONS LEAKING AT ZION 20	103097 P 260
ISLAND 10		CONTAINMENT PENETRATION FLANGE NOT INSTALLED AT PRAIRIE	105529 P 166
		CONTAINMENT PENETRATIONS AT ST. LUCIE 10	100021 P 179
		CONTAINMENT PRESSURE CHANNELS NOT TESTED PROPERLY AT COOK 1	105515 P 65
		CONTAINMENT PRESSURE INPUT TO REACTOR PROTECTIVE SYSTEM	104399 P 24
FAILS AT CALVERT CLIFFS 10		CONTAINMENT PRESSURE PROTECTION CHANNEL FOUND IMPERABLE	100085 P 169
AT ROBINSON 20		CONTAINMENT PRESSURE RELIEF FAN ISOLATION VALVE CLOSING	106096 P 62
TIME SLOW AT COOK 10		CONTAINMENT PRESSURE SWITCH AT TURNER POINT 30	104271 P 224
		CONTAINMENT PRESSURE SWITCHES AT PALISADES	102316 P 120
		CONTAINMENT PRESSURE TRANSMITTER AT HILLSTONE 20	100820 P 96
		CONTAINMENT PURGE AND EXHAUST VALVE CLOSING TIME EXCEEDS	099365 P 139
		CONTAINMENT PURGE FAILS TO TRIP AT ZION 20	102677 P 266
		CONTAINMENT PURGE FAILS TO TRIP AT ZION 20	102557 P 266
		CONTAINMENT PURGE ISOLATION VALVE FAILS TO CLOSE AT ZION 20	100542 P 252
ZION 20		CONTAINMENT PURGE ISOLATION VALVE LEAK RATES EXCESSIVE AT	103363 P 267
20		CONTAINMENT PURGE SUPPLY VALVE FAILS TO CLOSE AT HILLSTONE	100048 P 97
		CONTAINMENT PURGE SUPPLY VALVE LEAKS AT POINT BEACH 10	105283 P 137
POINT BEACH 10		CONTAINMENT PURGE VALVE CLOSING TIMES EXCEED LIMIT AT	093617 P 135
		CONTAINMENT PURGE VALVE LEAKAGE HIGH AT ZION 10	102141 P 236
		CONTAINMENT PURGE VALVES EXCESSIVE AT PALISADES	100212 P 136
		CONTAINMENT PURGE VALVES HAVE EXCESSIVE LEAKAGE AT ZION 20	106660 P 250
		CONTAINMENT RADIATION AREA MONITOR FAILS AT CALVERT CLIFFS	093676 P 16
		CONTAINMENT RADIATION MONITOR FAILS AT CALVERT CLIFFS 10	093475 P 25
		CONTAINMENT RADIATION MONITOR FAILS AT CALVERT CLIFFS 10	104020 P 17
		CONTAINMENT RADIATION MONITOR FAILS AT CALVERT CLIFFS 10	099107 P 15
		CONTAINMENT RING GIRDER REPAIR AT TURNER POINT 30	105542 P 223
		CONTAINMENT SPRAY UTESIL FAILS TO START AT ZION 10	105728 P 230
		CONTAINMENT SPRAY HEADERS FOUND IMPERABLE AT HILLSTONE 20	106056 P 99
POINT 20		CONTAINMENT SPRAY LOGIC NOT COMPLETELY TESTED AT INDIAN	104993 P 72
POINT 20		CONTAINMENT SPRAY PUMP NOT TESTED ON SCHEDULE AT INDIAN	105040 P 73
		CONTAINMENT SPRAY PUMPS LOCKED OUT OF SERVICE AT COOK 10	104400 P 60
		CONTAINMENT SPRAY RECIRCULATION VALVE FOUND OPEN AT ZION 10	102600 P 239
		CONTAINMENT SPRAY VALVE NOT PROPERLY ALIGNED AT ZION 20	107092 P 251
CLIFFS 10		CONTAINMENT SUMP DRAIN VALVE FAILS TO CLOSE AT CALVERT	099672 P 19
		CONTAINMENT SUMP ISOLATION VALVES NOT TESTED AT REDAUNDED	103663 P 80
		CONTAINMENT TENDONS AT HILLSTONE 20	102090 P 89
		CONTAINMENT TENDON GRASP CAPS AT TURNER POINT 30	102311 P 222
ISLAND 20		CONTAINMENT VACUUM BREAKER FOUND IMPERABLE AT PRAIRIE	105162 P 153
		CONTAINMENT VACUUM BREAKER IMPERABLE AT PRAIRIE ISLAND 20	102529 P 51

BOILER ACID TRANSFER PUMP FLOW RATE LESS THAN SPEC AT	COOL 10	124965 P 43
EMERGENCY ISOLATION VALVE FAILS TO OPEN COMPLETELY AT	COOL 10	103873 P 40
BULKHEAD ANALYSIS NOT PERFORMED DURING DEMERITATION AT	COOL 10	103857 P 39
TEMPERATURE CHANGE SHEET FOR TEST NOT APPROVED ON TIME AT	COOL 10	103549 P 39
BRISQ MONITORING SYSTEM MALFUNCTION AT	COOL 10	106372 P 46
ISOLATION PLEGE TO CHARGING PUMPS ISOLATED AT	COOL 10	102123 P 37
BRISQ FLOWER NOT TESTED AS REQUIRED AT	COOL 10	105732 P 45
BIOL CONDENSER COOLERS PARTIALLY OPENED AT	COOL 10	100602 P 42
BIOL POINT DRIFT IN TIME-DRIFT RELAY AT	COOL 10	103097 P 38
BONITCAL INSTRUMENTATION BUS LIST AT	COOL 10	104432 P 41
BUS MONITOR FAILS TO ACT CONTINUOUSLY AT	COOL 10	104801 P 42
BONITCAL PATH HEAT TRAILING CIRCUIT INOPERATIVE AT	COOL 10	103875 P 40
BONITCAL REDUCED IN EFFLUENT EXCEEDS LIMIT AT	COOL 10	105289 P 44
BUNIT 2 AVAILABLE PRECOOLER PUMP NOT TESTED AS REQUIRED AT	COOL 10	106608 P 46
BONITCAL STORAGE TANK LEVEL LESS THAN LIMIT AT	COOL 10	104976 P 44
BONITCAL INFORMATION ON ELECTRICAL SHUTDOWN AT	COOL 10	102164 P 38
BONITCAL TRIP BREAKERS NOT PERFORMED ON TIME AT	COOL 10	106386 P 44
BONITCAL PUMP IN EQUILIBRIUM LINE VALVE WELD AT	COOL 10	103874 P 40
BONITCAL EQUILIBRIUM LINE VALVE WELD AT	COOL 10	102125 P 37
BONITCAL TESTING NOT PERFORMED AS REQUIRED AT	COOL 10	104403 P 41
BONITCAL ACID TRANSFER PUMP REMOVED FROM SERVICE AT	COOL 10	106606 P 47
BONITCAL RANGE CHANNEL FAILS AT	COOL 10	104883 P 42
BONITCAL SERVICE WATER VALVE FAILS TO CLOSE AT	COOL 10	103888 P 40
BONITCAL SPEED INDICATOR SHOWN AT	COOL 10	103550 P 39
BONITCAL POINT DRIFT IN FLOW SENSOR AT	COOL 10	105516 P 45
BONITCAL GENERATOR INVERTER FAILS AT	COOL 10	104401 P 41
BONITCAL STARTER FAILS IN THE RUN MODE AT	COOL 10	103098 P 38
BONITCAL PUMP IN SHOWN INJECTION TANK REDUCED AT	COOL 10	106677 P 47
BONITCAL AIR FAN/CLIMATE DETECTION PUMP FAILS AT	COOL 10	105517 P 44
BONITCAL EMERGENCY ISOLATION FAILS AT	COOL 10	102124 P 37
BONITCAL COOLANT PUMP SEAL BYPASS LINE LEAKS AT	COOL 10	104957 P 43
BONITCAL SPRAY PUMPS LOCKED OUT OF SERVICE AT	COOL 10	104420 P 40
BONITCAL SPEED INDICATOR FAILS AT	COOL 10	106609 P 47
BONITCAL MONITOR NOT TESTED ON SCHEDULE AT	COOL 10	102119 P 37
BONITCAL PRESSURE CHANNELS MALFUNCTION AT	COOL 10	105047 P 44
BONITCAL PRESSURE CHANNELS NOT TESTED PROPERLY AT	COOL 10	105515 P 45
BONITCAL INJECTION OCCURS AT	COOL 10	106604 P 47
BONITCAL ISOLATION MEMBRANE BARRIER DEFICIENCY AT	COOL 10	102169 P 38
BA REJECTED TRIP SERVICE INSTALLED IN CIRCUIT BREAKER AT	COOL 10	099688 P 34
BONITCAL LOSS OF POWER AT	COOL 10	100885 P 36
BONITCAL SURVEILLANCE TESTS NOT PERFORMED AT	COOL 10	100883 P 35
BONITCAL RELEASE OCCURS FROM WAS DELAY TANK AT	COOL 10	100911 P 36
BONITCAL FUEL OIL NOT SAMPLED ON SCHEDULE AT	COOL 10	099115 P 33
BONITCAL ROOM SUMP DISCHARGE OUT OF LIMITS AT	COOL 10	099114 P 33
BONITCAL GENERATOR NOT TESTED WHEN REQUIRED AT	COOL 10	100886 P 35
BONITCAL UNDESIRABLE WASTE EVAPORATION CONDENSATE TANK AT	COOL 10	106628 P 47
BONITCAL DIRECTION INSTRUMENT IN ERROR AT	COOL 10	102121 P 36
BONITCAL INSTRUMENTS INOPERABLE AT	COOL 10	103884 P 35
BONITCAL TURBINE ROOM SUMP DISCHARGE EXCEEDS LIMIT AT	COOL 10	099382 P 34
BONITCAL AIR FILTER TRAIL NOT TESTED AT	COOL 10	100887 P 35
BONITCAL ISOLATION ATTEMPT FAILS AT	COOL 10	102122 P 36
BONITCAL TURBINE ROOM SUMP DISCHARGE EXCEEDS LIMITS AT	COOL 10	099196 P 33
BONITCAL PUMP WASTE HOLDUP TANK OUT OF LIMITS AT	COOL 10	100890 P 34
BONITCAL SPEED INDICATOR CLAMP LOOSE AT	COOL 10	099689 P 34
BONITCAL ISOLATION VALVE CAUSING TANKS SHUT AT	COOL 10	104497 P 43
BONITCAL LEVEL CHANNEL NOT PLACED IN TRIPPED POSITION AT	COOL 10	105046 P 44
BONITCAL RELEASE PUMP ISOLATION VALVE CAUSING TANKS SHUT AT	COOL 10	104498 P 42
BONITCAL LINES ON SERVICE WATER PIPING FAIL TO MEET CODE AT	COOL 10	104403 P 41
BONITCAL ACTIVITY IN REACTOR	COOLANT EXCEEDS LIMIT AT GINNA	107765 P 48
BONITCAL OXYGEN IN REACTOR	COOLANT EXCEEDS LIMIT AT WILLSTONE 20	104461 P 44
BONITCAL UNIT IN REACTOR	COOLANT FLOW MISTAKE AT INDIAN POINT 20	100923 P 70
BONITCAL REACTOR	COOLANT FLOW EXCEEDS DESIGN VALUE AT OCONEE 20	103095 P 114
BONITCAL SCHEDULE FOR REACTOR	COOLANT FLOW DEFICIENT AT GINNA	103606 P 60
BONITCAL REACTOR	COOLANT PRESSURE BUFFER AMPLIFIER FAILS AT OCONEE 10	093246 P 101
BONITCAL DRIFT IN REACTOR	COOLANT PRESSURE CHANNEL AT RANCHO SECOP	100896 P 157
BONITCAL DRIFT IN REACTOR	COOLANT PRESSURE CHANNEL AT THREE MILE ISLAND 10	103630 P 206
BONITCAL DRIFT IN REACTOR	COOLANT PRESSURE SWITCHES AT THREE MILE ISLAND 10	103629 P 206
BONITCAL REACTOR IN STEAM GENERATOR AND	COOLANT PUMP ANCHOR BOLTS AT SEQUOIA 1 AND 20	102615 P 173
BONITCAL USE FIRE TUBES UNDER	COOLANT PUMP WITOUT STAND AT OCONEE 20	106327 P 112
BONITCAL REACTOR	COOLANT PUMP SEAL BYPASS LINE LEAKS AT COOL 10	104957 P 43
BONITCAL REACTOR	COOLANT PUMP SEAL FAILS AT ROBINSON 20	102889 P 185
BONITCAL REACTOR	COOLANT PUMP SEAL INJECTION LEAK FOUND AT PRAIRIE ISLAND 10	105275 P 146
BONITCAL REACTOR	COOLANT PUMP SEAL INJECTION LINE LEAKS AT PRAIRIE ISLAND 10	104085 P 146
BONITCAL REACTOR	COOLANT PUMP SEAL SYSTEM FAILS AT ROBINSON 20	103077 P 160
BONITCAL REACTOR	COOLANT PUMP SEAL SYSTEM FAILURE AT ROBINSON 20	103463 P 160
BONITCAL REACTOR	COOLANT PUMP SEAL VENT VALVE AT ARKANSAS NUCLEAR 10	099113 P 33
BONITCAL REACTOR	COOLANT PUMP SEAL WATER RETURN LINE LEAKS AT PRAIRIE	100426 P 150
BONITCAL REACTOR	COOLANT PUMP SEAL FAIL AT FT. CALHOUN	107503 P 60
BONITCAL REACTOR	COOLANT PUMP SUCTUM WELD DEFECTS AT DAVIS-BESSE 10	102242 P 51
BONITCAL REACTOR	COOLANT PUMP UPPER SEAL FAIL AT CALVERT CLIFFS 10	106369 P 27
BONITCAL REACTOR	COOLANT PUMP UPPER SEAL PRESSURE SENSING LINE LEAKS AT	031451 P 20
BONITCAL REACTOR	COOLANT RELEASED TO CONTAINMENT AT ZION 10	103675 P 237
BONITCAL REACTOR	COOLANT SYSTEM COOLDOWN RATE EXCESSIVE AT OCONEE 30	103892 P 122
BONITCAL REACTOR	COOLANT SYSTEM FILL AT OCONEE 20	108225 P 119
BONITCAL REACTOR	COOLANT SYSTEM LEAKAGE EXCEEDS LIMIT AT PALISADPS	109187 P 134
BONITCAL REACTOR	COOLANT SYSTEM LEAKAGE HIGH AT OCONEE 10	104060 P 104
BONITCAL REACTOR	COOLANT SYSTEM OVERPRESSURIZED AT ST. LUCIE 10	105915 P 177
BONITCAL REACTOR	COOLANT SYSTEM OVERPRESSURIZED AT ZION 20	106658 P 250

[illegible]

FOR SURRY 3 AND 40
NORTH ANNA 1 AND 20
MILE ISLAND 10
AND 20

	PLATFORM COOLERS FOUND TO BE DEFICIENT AT NORTH ANNA 30	100200 P100
	HYDRAULIC SHAMBER INSPECTION FOUND DEFICIENT AT RANCHO SEC20	100277 P103
	REACTOR BUILDING CABLE TRAY PAINTING FOUND DEFICIENT AT THREE MILE ISLAND 20	100307 P220
	STEAM GENERATOR TUBE DEGRADATION FOUND AT YANKEE ROWE0	100308 P233
AT GINNA0	DEGRADATION OF CHARCOAL FILTER 100% REMOVAL EFFICIENCY DEGRADED AT GINNA0	101732 P 66
	DIESEL GENERATOR BACKUP UNDERVOLTAGE START MALFUNCTION AT DELAY DURING SHIPMENT AT PALISADES0	101700 P 66
FT. CALHOUN0	MISSION CHARTER	102203 P 66
	DETERMINED FILTER LOGGING REMOVAL EFFICIENCY	102475 P 57
	DETERMINED POINT DRIFT IN TIME	103409 P126
	DETERMINED STRIKE TIME	103507 P 30
	DETERMINED OVERTEMPERATURE	103524 P 90
	DETERMINED OVERTEMPERATURE	103601 P245
	DETERMINED POINT DRIFT IN OVERPOWER	103633 P 72
	DETERMINED OVER-TEMPERATURE	103673 P152
	DETERMINED NOT MEASURED AT SAN ONOFRE 10	099096 P243
	DETERMINED FOR COOLERS EXCEEDS LIMIT AT INDIAN POINT 20	105551 P171
	DETERMINED OF STEAM GENERATOR TUBES AT SURRY 10	105163 P 73
	DEPTH MAY HAVE BEEN BELOW LIMIT AT ARRANAS NUCLEAR 10	100670 P109
FT. CALHOUN0	DETERMINED SIGNAL SEQUENCER FAILS TO ACTUATE ON SET TIME AT	106376 P 8
FT. CALHOUN0	DETERMINED SIGNAL SEQUENCER FAILS TO ACTUATE ON SET TIME AT	107207 P 61
CALHOUN0	DETERMINED SIGNAL SEQUENCER FAILS TO ACTUATE ON SET TIME AT	107334 P 60
CALHOUN0	DETERMINED SIGNAL SEQUENCER FAILS TO ACTUATE ON SET TIME AT	107344 P 50
	DETERMINED AT SURRY 1 AND 20	104203 P 59
	DETERMINED CRITERIA AT PALISADES0	100277 P173
	DETERMINED DEFICIENCY AT FT. CALHOUN0	100579 P126
	DETERMINED DEFICIENCY FOUND AT SAN ONOFRE 10	102402 P 57
THREE MILE ISLAND 10	DETERMINED DEFICIENCY IN CONTROL ROOM DRIVE BREAKER CABINETS AT	099201 P200
	DETERMINED DEFICIENCY IN CONTROL ROOM DRIVE BREAKER CABINETS AT	100060 P155
	DETERMINED DEFICIENCY IN CONTROL ROOM DRIVE BREAKER CABINETS AT	103095 P114
	DESIGNED AT CONNECTICUT YANKEE0	104202 P 32
	DETECTED IN COMPONENT COOLING SYSTEM AT RANCHO SEC00	101446 P157
	DETECTED IN FUEL ASSEMBLY AT SURRY 20	103117 P193
	DETECTED FAILS AT MAINE YANKEE0	102400 P 85
	DETECTED FAILS AT POINT BEACH 20	102520 P140
	DETECTED IN RPS CHANNEL A FAILS AT OCONEE 20	107220 P110
	DETECTED INSTALLED AT THREE MILE ISLAND 10	106306 P222
	DETECTED PUMP FAILS AT COOK 10	105517 P 66
	DETECTED TRAVELER ON SCHEDULE AT ROBINSON 20	090711 P163
	DETECTORS CONTINUE TO FAIL AT FT. CALHOUN0	103005 P 50
FT. CALHOUN0	DETERIORATION AT SURRY 1 AND 20	093261 P107
	DETERIORATION OF SECONDARY INSULATION ON 4 KV BUS DUCT AT	102135 P 56
	DEVELOP VOLTAGE AT ZION 10	093500 P274
	DEVELOPS A PIN HOLE LEAK AT HILLSTONE 20	106354 P 91
	DEVELOPS IN CHARGING PUMP RECIRCULATION LINE AT SURRY 10	104062 P104
	DEVELOPS PINHOLE LEAK AT SURRY 10	102276 P103
	DEVELOPS SEVERE LUBE OIL LEAK AT ZION 20	100037 P253
	DEVIATION MONITOR ALARM POINT CHANGED AT GINNA0	106619 P 60
	DEVIATION ON A CONTROL ROD AT PALISADES0	106220 P130
	DEVICE AT FT. CALHOUN0	109580 P 67
	DEVICE INSTALLED IN CIRCUIT BREAKER AT COOK 10	099600 P 74
	DEWATERING SYSTEM REQUIRED AT SURRY 3 AND 40	107620 P140
	DIAGNOSTIC EXCHANGER INLET NOZZLE FAILURE AT HILLSTONE 20	104930 P 90
SWITCH AT GINNA0	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	100519 P 60
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	099374 P 52
POWER AT FT. CALHOUN0	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	100026 P 52
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	101450 P 55
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	105720 P230
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	090115 P 33
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	100047 P 97
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	090700 P190
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	100990 P140
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	103207 P227
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	104063 P223
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	106700 P232
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	105051 P131
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	102290 P231
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	102544 P231
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	100037 P253
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	100524 P 77
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	102271 P170
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	102995 P103
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	104059 P209
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	093500 P234
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	100574 P171
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	100070 P 82
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	100017 P 90
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	099111 P150
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	09325 P261
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	103123 P267
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	105525 P249
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	103710 P240
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	107772 P 61
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	107517 P 60
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	102140 P 80
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	103053 P170
	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	104401 P 61
FT. CALHOUN0	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	
FT. CALHOUN0	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	
SALEM 1 AND 20	DIAGNOSTIC INDICATES NO RESPONSE TO GOVERNOR CONTROL	

1964-65 000000 3-

100275	P180
991000	P210
100270	P62
121050	P43
105163	P73
107760	P75
107520	P170
101730	P128
100227	P51
100090	P61
100030	P132
125500	P131
100037	P132
100050	P176
102135	P56
100000	P106
103700	P20
103103	P103
103657	P103
123000	P120
102901	P59
131552	P189
100275	P176
105500	P6
102110	P78
101050	P55
127551	P220
102090	P227
091000	P120
100020	P60
123000	P120
100150	P120
100052	P123
100050	P172
103110	P193
100070	P200
123000	P200

IDENTIFY	DESCRIPTION	STATUS	LOCATION
1	SETTLEMENT OF	EXCEEDS	VALVE ROOMS AT SEVENTH 1 & 2
2	EXCESS ANALYSIS PERFORMED AT TURKEY POINT	EXCEEDS	ANALYSIS PERFORMED AT TURKEY POINT
3	EFFECT OF CHANGE IN MODULUS USED FOR SEISMIC DESIGN	EXCEEDS	EFFECT OF CHANGE IN MODULUS USED FOR SEISMIC DESIGN
4	EFFICIENCY AT GERMANY	EXCEEDS	EFFICIENCY AT GERMANY
5	EFFICIENCY BELOW LIMIT AT FT. CALHOUN	EXCEEDS	EFFICIENCY BELOW LIMIT AT FT. CALHOUN
6	EFFICIENCY DEGRADED AT GERMANY	EXCEEDS	EFFICIENCY DEGRADED AT GERMANY
7	EXCESS CALIBRE IN PLANT	EXCEEDS	EXCESS CALIBRE IN PLANT
8	EXCESSIVE THROUGH PLANT	EXCEEDS	EXCESSIVE THROUGH PLANT
9	EXCESSIVE	EXCEEDS	EXCESSIVE
10	EXCESSIVE	EXCEEDS	EXCESSIVE
11	EXCESSIVE	EXCEEDS	EXCESSIVE
12	EXCESSIVE	EXCEEDS	EXCESSIVE
13	EXCESSIVE	EXCEEDS	EXCESSIVE
14	EXCESSIVE	EXCEEDS	EXCESSIVE
15	EXCESSIVE	EXCEEDS	EXCESSIVE
16	EXCESSIVE	EXCEEDS	EXCESSIVE
17	EXCESSIVE	EXCEEDS	EXCESSIVE
18	EXCESSIVE	EXCEEDS	EXCESSIVE
19	EXCESSIVE	EXCEEDS	EXCESSIVE
20	EXCESSIVE	EXCEEDS	EXCESSIVE
21	EXCESSIVE	EXCEEDS	EXCESSIVE
22	EXCESSIVE	EXCEEDS	EXCESSIVE
23	EXCESSIVE	EXCEEDS	EXCESSIVE
24	EXCESSIVE	EXCEEDS	EXCESSIVE
25	EXCESSIVE	EXCEEDS	EXCESSIVE
26	EXCESSIVE	EXCEEDS	EXCESSIVE
27	EXCESSIVE	EXCEEDS	EXCESSIVE
28	EXCESSIVE	EXCEEDS	EXCESSIVE
29	EXCESSIVE	EXCEEDS	EXCESSIVE
30	EXCESSIVE	EXCEEDS	EXCESSIVE
31	EXCESSIVE	EXCEEDS	EXCESSIVE
32	EXCESSIVE	EXCEEDS	EXCESSIVE
33	EXCESSIVE	EXCEEDS	EXCESSIVE
34	EXCESSIVE	EXCEEDS	EXCESSIVE
35	EXCESSIVE	EXCEEDS	EXCESSIVE
36	EXCESSIVE	EXCEEDS	EXCESSIVE
37	EXCESSIVE	EXCEEDS	EXCESSIVE
38	EXCESSIVE	EXCEEDS	EXCESSIVE
39	EXCESSIVE	EXCEEDS	EXCESSIVE
40	EXCESSIVE	EXCEEDS	EXCESSIVE
41	EXCESSIVE	EXCEEDS	EXCESSIVE
42	EXCESSIVE	EXCEEDS	EXCESSIVE
43	EXCESSIVE	EXCEEDS	EXCESSIVE
44	EXCESSIVE	EXCEEDS	EXCESSIVE
45	EXCESSIVE	EXCEEDS	EXCESSIVE
46	EXCESSIVE	EXCEEDS	EXCESSIVE
47	EXCESSIVE	EXCEEDS	EXCESSIVE
48	EXCESSIVE	EXCEEDS	EXCESSIVE
49	EXCESSIVE	EXCEEDS	EXCESSIVE
50	EXCESSIVE	EXCEEDS	EXCESSIVE
51	EXCESSIVE	EXCEEDS	EXCESSIVE
52	EXCESSIVE	EXCEEDS	EXCESSIVE
53	EXCESSIVE	EXCEEDS	EXCESSIVE
54	EXCESSIVE	EXCEEDS	EXCESSIVE
55	EXCESSIVE	EXCEEDS	EXCESSIVE
56	EXCESSIVE	EXCEEDS	EXCESSIVE
57	EXCESSIVE	EXCEEDS	EXCESSIVE
58	EXCESSIVE	EXCEEDS	EXCESSIVE
59	EXCESSIVE	EXCEEDS	EXCESSIVE
60	EXCESSIVE	EXCEEDS	EXCESSIVE
61	EXCESSIVE	EXCEEDS	EXCESSIVE
62	EXCESSIVE	EXCEEDS	EXCESSIVE
63	EXCESSIVE	EXCEEDS	EXCESSIVE
64	EXCESSIVE	EXCEEDS	EXCESSIVE
65	EXCESSIVE	EXCEEDS	EXCESSIVE
66	EXCESSIVE	EXCEEDS	EXCESSIVE
67	EXCESSIVE	EXCEEDS	EXCESSIVE
68	EXCESSIVE	EXCEEDS	EXCESSIVE
69	EXCESSIVE	EXCEEDS	EXCESSIVE
70	EXCESSIVE	EXCEEDS	EXCESSIVE
71	EXCESSIVE	EXCEEDS	EXCESSIVE
72	EXCESSIVE	EXCEEDS	EXCESSIVE
73	EXCESSIVE	EXCEEDS	EXCESSIVE
74	EXCESSIVE	EXCEEDS	EXCESSIVE
75	EXCESSIVE	EXCEEDS	EXCESSIVE
76	EXCESSIVE	EXCEEDS	EXCESSIVE
77	EXCESSIVE	EXCEEDS	EXCESSIVE
78	EXCESSIVE	EXCEEDS	EXCESSIVE
79	EXCESSIVE	EXCEEDS	EXCESSIVE
80	EXCESSIVE	EXCEEDS	EXCESSIVE
81	EXCESSIVE	EXCEEDS	EXCESSIVE
82	EXCESSIVE	EXCEEDS	EXCESSIVE
83	EXCESSIVE	EXCEEDS	EXCESSIVE
84	EXCESSIVE	EXCEEDS	EXCESSIVE
85	EXCESSIVE	EXCEEDS	EXCESSIVE
86	EXCESSIVE	EXCEEDS	EXCESSIVE
87	EXCESSIVE	EXCEEDS	EXCESSIVE
88	EXCESSIVE	EXCEEDS	EXCESSIVE
89	EXCESSIVE	EXCEEDS	EXCESSIVE
90	EXCESSIVE	EXCEEDS	EXCESSIVE
91	EXCESSIVE	EXCEEDS	EXCESSIVE
92	EXCESSIVE	EXCEEDS	EXCESSIVE
93	EXCESSIVE	EXCEEDS	EXCESSIVE
94	EXCESSIVE	EXCEEDS	EXCESSIVE

104609 P174
104651 P227
104777 P173
131752 P
102137 P 50
102790 P 64
102447 P150
102908 P 55
100875 P 11
101447 P 55
132437 P104
100877 P 13
132974 P 13
132975 P 13
103659 P 5
105288 P 7
104452 P 10
107914 P 10
104111 P 10
135262 P 10
106792 P 11
102470 P201
105213 P201
107525 P215
100810 P 12
105267 P 12
105519 P 12
107781 P 10
135518 P 8
106375 P 8
104977 P 8
103658 P 5
104194 P 6
103466 P 6
104661 P 6
105789 P 6
104985 P104
132976 P104
102118 P104
103821 P150
104973 P204
104978 P204
132671 P204
103876 P 5
133129 P 5
103128 P 5

[illegible]

0SAFETY INJECTION VALVE	FAILS TO OPEN AT CALVERT CLIFFS 10	102163 P 22
0HIGH PRESSURE SAFETY INJECTION VALVE	FAILS TO OPEN AT FT. CALHOUN	121607 P 55
0COMPONENT COOLING SYSTEM VALVE	FAILS TO OPEN AT INDIAN POINT 20	101607 P 71
0COMPONENT COOLING SYSTEM VALVE	FAILS TO OPEN AT INDIAN POINT 20	102356 P 71
0CONTAINMENT COOLING SERVICE WATER VALVE	FAILS TO OPEN AT REMAINEE	102522 P 81
0SAFETY INJECTION VALVE	FAILS TO OPEN AT REMAINEE	102536 P 79
0PUMP PUMP SECTION VALVE	FAILS TO OPEN AT MAINE YANKEE	100048 P 85
0REACTOR CONDENSER DISCHARGE VALVE	FAILS TO OPEN AT OCOEE 20	100048 P 115
0REACTOR BUILDING SPRAY VALVE	FAILS TO OPEN AT OCOEE 20	101156 P 111
0EMERGENCY PREHEATER VALVE	FAILS TO OPEN AT OCOEE 20	101301 P 113
0HIGH PRESSURE SAFETY INJECTION VALVE	FAILS TO OPEN AT PALISADES	101182 P 131
0HIGH PRESSURE SAFETY INJECTION VALVE	FAILS TO OPEN AT PALISADES	100448 P 132
0STEAM GENERATOR AUXILIARY PUMP VALVE	FAILS TO OPEN AT POINT BEACH 20	100722 P 139
0MAIN STEAM PUMP OPERATOR RELIEF VALVE	FAILS TO OPEN AT PRAIRIE ISLAND 10	101416 P 165
0SAFETY PREHEATER BYPASS VALVE	FAILS TO OPEN AT RANCHO SECOP	101454 P 157
0DIESEL HEAT REMOVAL SYSTEM VALVE	FAILS TO OPEN AT RANCHO SECOP	100432 P 162
0DIESEL VALVE	FAILS TO OPEN AT ROBINSON 20	100414 P 167
0AUXILIARY FEEDWATER PUMP DISCHARGE VALVE	FAILS TO OPEN AT ROBINSON 20	100405 P 167
0AUXILIARY FEEDWATER PUMP DISCHARGE VALVE	FAILS TO OPEN AT OCOEE 20	100437 P 167
0AUXILIARY FEEDWATER PUMP DISCHARGE VALVE	FAILS TO OPEN AT SURREY 10	100444 P 190
0AUXILIARY FEEDWATER PUMP DISCHARGE VALVE	FAILS TO OPEN AT SURREY 10	100548 P 188
0AUXILIARY FEEDWATER PUMP DISCHARGE VALVE	FAILS TO OPEN AT SURREY 10	103116 P 184
0AUXILIARY FEEDWATER PUMP DISCHARGE VALVE	FAILS TO OPEN AT SURREY 10	100000 P 189
0ACCUMULATOR DISCHARGE VALVE	FAILS TO OPEN AT SURREY 20	102531 P 193
0CONTAINMENT COOLING SYSTEM VALVE	FAILS TO OPEN AT ZION 20	107095 P 251
0CONTAINMENT COOLER VALVE	FAILS TO OPEN AT ZION 20	107095 P 251
0AUXILIARY FEEDWATER STOP VALVE	FAILS TO OPEN AT ZION 20	107095 P 251
0EMERGENCY ISOLATION VALVE	FAILS TO OPEN COMPLETELY AT COON 10	103078 P 40
0SAFETY VALVE	FAILS TO OPEN ON SIGNAL AT FT. CALHOUN	100502 P 62
0CONTAINMENT ISOLATION VALVE	FAILS TO OPERATE AT RANCHO SECOP	100070 P 156
0CONSEQUENCE LIMITING SAFEGUARD TRIP	FAILS TO OPERATE AT SURREY 20	102562 P 193
0DIESEL GENERATOR	FAILS TO OPERATE FOR ONE HOUR AT SURE UNFIRE 10	100574 P 171
0AUXILIARY FEEDWATER PUMP GOVERNOR	FAILS TO RESPOND AT HILLSTONE 20	100603 P 96
0DIESEL RELAY	FAILS TO RESPOND WITHIN TIME LIMIT AT POINT BEACH 1 AND 20	102566 P 162
0BUS MONITOR	FAILS TO RUN CONTINUOUSLY AT COON 10	100401 P 62
0CONTAINMENT COOLER	FAILS TO START AT CALVERT CLIFFS 10	100550 P 17
0SAFETY INJECTION PUMP	FAILS TO START AT GINNA	100041 P 63
0AUXILIARY FEEDWATER PUMP	FAILS TO START AT REMAINEE	100016 P 77
0AUXILIARY FEEDWATER PUMP	FAILS TO START AT REMAINEE	100410 P 78
0DIESEL GENERATOR	FAILS TO START AT REMAINEE	100076 P 82
0DIESEL GENERATOR	FAILS TO START AT HILLSTONE 20	100017 P 96
0DIESEL GENERATOR	FAILS TO START AT RANCHO SECOP	100112 P 156
0DIESEL GENERATOR VENT FAN	FAILS TO START AT RANCHO SECOP	100631 P 162
0AUXILIARY FEEDWATER PUMP	FAILS TO START AT ROBINSON 20	107098 P 167
0COMPONENT COOLING PUMP	FAILS TO START AT ROBINSON 20	093608 P 166
0RECHARGING PUMP	FAILS TO START AT ST. LUCIE 10	100022 P 179
0REACTOR BUILDING EMERGENCY COOLING RIVER WATER PUMP	FAILS TO START AT THREE HILL ISLAND 10	102563 P 205
0EMERGENCY COOLING RIVER WATER PUMP	FAILS TO START AT THREE HILL ISLAND 10	090099 P 200
0BPCI PUMP	FAILS TO START AT THREE HILL ISLAND 10	090103 P 199
0CONTAINMENT SPRAY DIESEL	FAILS TO START AT ZION 10	105720 P 230
0DIESEL GENERATOR	FAILS TO START AT ZION 20	093258 P 241
0DIESEL GENERATOR	FAILS TO START AT ZION 20	093110 P 248
0DIESEL GENERATOR	FAILS TO START AT ZION 20	105525 P 249
0DIESEL GENERATOR	FAILS TO START AT ZION 20	103123 P 247
0DIESEL GENERATOR	FAILS TO START IN LESS THAN 10 SECONDS AT FT. CALHOUN	107517 P 60
0DIESEL GENERATOR	FAILS TO START IN LESS THAN 10 SECONDS AT FT. CALHOUN	107772 P 61
0CONTAINMENT COOLER	FAILS TO START IN SLOW SPEED AT CALVERT CLIFFS 10	101653 P 20
0SAFETY INJECTION PUMP	FAILS TO START MANUALLY AT GINNA	102276 P 63
0BUS 10	FAILS TO TRANSFER FROM STATION POWER TO START-UP POWER AT	100444 P 129
0LOCKOUT RELAY	FAILS TO TRIP AT FT. CALHOUN	090664 P 54
0LOCKOUT RELAY	FAILS TO TRIP AT FT. CALHOUN	090020 P 54
0REACTOR POWER LEVEL TRIP DISTABLE	FAILS TO TRIP AT MAINE YANKEE	100913 P 84
0CONTROL ROD DRIVE BREAKER	FAILS TO TRIP AT OCOEE 30	105176 P 124
0PRESSURIZER PRESSURE CHANNEL DISTABLE	FAILS TO TRIP AT POINT BEACH 10	105538 P 137
0CONTROL ROD DRIVE BREAKER	FAILS TO TRIP AT THREE HILL ISLAND 10	102527 P 205
0PRESSURIZER PRESSURE COMPARTOR	FAILS TO TRIP AT TURKEY POINT 30	100648 P 124
0CONTAINMENT PURGE	FAILS TO TRIP AT ZION 20	102537 P 246
0CONTAINMENT PURGE	FAILS TO TRIP AT ZION 20	102677 P 246
0DISTABLE	FAILS TO TRIP AT ZION 20	102126 P 245
0REBOUNDANT TRIP MECHANISM ON HSB OPERATOR	FAILS TO UNLATCH AT POINT BEACH 10	100074 P 135
0BIN-CORE READING ON PRIMARY DATA LOGGER	FAILS TO UPDATE AT PALISADES	102308 P 120
0ADDITIONAL INFORMATION ON DC HEAT EXCHANGER INLET NOZZLE	FAILURE AT HILLSTONE 20	100430 P 90
0MPSN FLOW RESTRICTED BY VALVE	FAILURE AT OCOEE 30	107097 P 124
0FINAL REPORT ON CONTROL ROD	FAILURE AT PALISADES	100971 P 133
0ADDITIONAL INFORMATION ON STEAM GENERATOR TUBE	FAILURE AT POINT BEACH 10	103005 P 137
0LEAKDOWN HEAT EXCHANGER TUBE	FAILURE AT PRAIRIE ISLAND 20	100425 P 150
0PRELIMINARY REPORT ON TUBING	FAILURE AT RANCHO SECOP	100875 P 163
0REVISED REPORT ON REACTOR COOLANT PUMP SEAL SYSTEM	FAILURE AT ROBINSON 20	103663 P 166
0FINAL REPORT ON INTAKE COOLING WATER FLANGE	FAILURE AT ST. LUCIE 10	100655 P 177
0FALL-UP REPORT ON COMPARTOR	FAILURE AT ZION 10	106380 P 238
0ADDITIONAL INFORMATION ON CHARGING PUMP PIPE	FAILURE AT ZION 20	102538 P 245
AT ROBINSON 20	FAILURE TO CONDUCT INCREASE DETECTOR TRAVERSES ON SCHEDULE	090731 P 163
YANKEE POWER	FAILURE TO MEET RADIATION EXPOSURE RECORD REQUIREMENTS AT	100211 P 279
0ADDITIONAL INFORMATION ON SERVICE WATER VALVE	FAILURES AT BRANFAS NUCLEAR 10	100206 P 1
0FINAL REPORT ON RELAY	FAILURES AT ST. LUCIE	100461 P 177
0CONTAINMENT AND RECIRCULATION SPRAY CHECK VALVE	FAILURES AT SURREY 20	090493 P 190
1 AND 20	FAILURES IN REACTOR PROTECTION TEST PANEL CIRCUITS AT COON	090010 P 50
0CONTAINMENT	FAN COIL DAMPER FAILS AT PRAIRIE ISLAND 10	100526 P 160

	CONTAINMENT	00000000	1515
	OPRESSURE DROP ACROSS	00000000	1516
POINT 20	0000	00000000	1517
	00000000	00000000	1518
	00000000	00000000	1519
	00000000	00000000	1520
	00000000	00000000	1521
	00000000	00000000	1522
	00000000	00000000	1523
	00000000	00000000	1524
	00000000	00000000	1525
	00000000	00000000	1526
	00000000	00000000	1527
	00000000	00000000	1528
	00000000	00000000	1529
	00000000	00000000	1530
	00000000	00000000	1531
	00000000	00000000	1532
	00000000	00000000	1533
	00000000	00000000	1534
	00000000	00000000	1535
	00000000	00000000	1536
	00000000	00000000	1537
	00000000	00000000	1538
	00000000	00000000	1539
	00000000	00000000	1540
	00000000	00000000	1541
	00000000	00000000	1542
	00000000	00000000	1543
	00000000	00000000	1544
	00000000	00000000	1545
	00000000	00000000	1546
	00000000	00000000	1547
	00000000	00000000	1548
	00000000	00000000	1549
	00000000	00000000	1550
	00000000	00000000	1551
	00000000	00000000	1552
	00000000	00000000	1553
	00000000	00000000	1554
	00000000	00000000	1555
	00000000	00000000	1556
	00000000	00000000	1557
	00000000	00000000	1558
	00000000	00000000	1559
	00000000	00000000	1560
	00000000	00000000	1561
	00000000	00000000	1562
	00000000	00000000	1563
	00000000	00000000	1564
	00000000	00000000	1565
	00000000	00000000	1566
	00000000	00000000	1567
	00000000	00000000	1568
	00000000	00000000	1569
	00000000	00000000	1570
	00000000	00000000	1571
	00000000	00000000	1572
	00000000	00000000	1573
	00000000	00000000	1574
	00000000	00000000	1575
	00000000	00000000	1576
	00000000	00000000	1577
	00000000	00000000	1578
	00000000	00000000	1579
	00000000	00000000	1580
	00000000	00000000	1581
	00000000	00000000	1582
	00000000	00000000	1583
	00000000	00000000	1584
	00000000	00000000	1585
	00000000	00000000	1586
	00000000	00000000	1587
	00000000	00000000	1588
	00000000	00000000	1589
	00000000	00000000	1590
	00000000	00000000	1591
	00000000	00000000	1592
	00000000	00000000	1593
	00000000	00000000	1594
	00000000	00000000	1595
	00000000	00000000	1596
	00000000	00000000	1597
	00000000	00000000	1598
	00000000	00000000	1599
	00000000	00000000	1600
	00000000	00000000	1601
	00000000	00000000	1602
	00000000	00000000	1603
	00000000	00000000	1604
	00000000	00000000	1605

[illegible]

PALISADES	DIESEL	GENERATOR CONTROL CIRCUIT FAILS AT YAMKEE ROME	100380 P232
	DIESEL	GENERATOR CYLINDER AND EXHAUST TEMPERATURES HIGH AT	100351 P131
	DIESEL	GENERATOR DC CONTROL CIRCUIT FAILS AT YAMKEE ROME	100294 P231
	EMERGENCY DIESEL	GENERATOR DC CONTROL CIRCUIT FAILS AT YAMKEE ROME	100296 P231
	DIESEL	GENERATOR DEVELOPS SEVERE LUBE OIL LEAK AT ZION 20	100037 P233
	BOIL SPRAYS FROM DIESEL	GENERATOR EXHAUST MANIFOLD AT INDIAN POINT 30	100524 P 77
	DIESEL	GENERATOR EXHAUST VALVE MODIFICATION AT SALEM 1 AND 20	100271 P170
	EMERGENCY DIESEL	GENERATOR FAILS AT SURRY 10	100295 P103
	OPERATION RELAY FOR DIESEL	GENERATOR FAILS AT THREE MILE ISLAND 10	100039 P209
	BOUS BREAKER FROM EMERGENCY	GENERATOR FAILS TO CLOSE AT GINNA	100304 P 67
	DIESEL	GENERATOR FAILS TO DEVELOP VOLTAGE AT ZION 10	001500 P234
	DIESEL	GENERATOR FAILS TO OPERATE FOR ONE HOUR AT SAN ONOFRE 10	100576 P171
	DIESEL	GENERATOR FAILS TO START AT ARKANSAS	100076 P 82
	DIESEL	GENERATOR FAILS TO START AT HILLSTONE 20	100017 P 90
	DIESEL	GENERATOR FAILS TO START AT RANCHO SECOP	001112 P156
	DIESEL	GENERATOR FAILS TO START AT ZION 20	003256 P261
	DIESEL	GENERATOR FAILS TO START AT ZION 20	103710 P260
	DIESEL	GENERATOR FAILS TO START AT ZION 20	005525 P260
	DIESEL	GENERATOR FAILS TO START AT ZION 20	103123 P267
	DIESEL	GENERATOR FAILS TO START IN LESS THAN 10 SECONDS AT PT.	107772 P 61
	DIESEL	GENERATOR FAILS TO START IN LESS THAN 10 SECONDS AT PT.	107517 P 60
	DIESEL	GENERATOR FIELD CIRCUIT DEFICIENCY AT HILLSTONE 20	102140 P 80
	DIESEL	GENERATOR HEAT EXCHANGER WATER BOX HEADS LEAK AT SALEM 1	100053 P170
	DIESEL	GENERATOR INVERTER FAILS AT COOK 10	104401 P 61
	DES STEAM	GENERATOR ISOLATION SIGNAL SENSOR FAILS AT CALVERT CLIFFS 1	001605 P 10
	DES STEAM	GENERATOR LEAK AT PALISADES	102260 P129
	DES POINT DRIFT IN STEAM	GENERATOR LEVEL COMPARATOR AT ZION 10	100000 P230
	DES POINT DRIFT IN STEAM	GENERATOR LEVEL COMPARATOR AT ZION 20	100027 P266
	DES POINT DRIFT IN STEAM	GENERATOR LEVEL COMPARATOR AT ZION 20	101002 P266
	DES POINT DRIFT IN STEAM	GENERATOR LEVEL CONTROL VIOLATES STANDARDS AT GINNA	100610 P 60
	DES POINT DRIFT IN STEAM	GENERATOR LEVEL INDICATOR MALFUNCTION AT SURRY 20	003250 P100
	DES POINT DRIFT IN STEAM	GENERATOR LEVEL INDICATOR AT SURRY 20	100262 P101
	DES POINT DRIFT IN STEAM	GENERATOR LEVEL INDICATOR AT SURRY 20	100430 P101
	DES POINT DRIFT IN STEAM	GENERATOR LEVEL INSTRUMENT MALFUNCTION AT POINT BEACH 20	001017 P130
	DES POINT DRIFT IN STEAM	GENERATOR LOW-LOW LEVEL COMPARATOR FAILS AT TURKEY POINT 30	102312 P222
	DES POINT DRIFT IN STEAM	GENERATOR LOAD SEQUENCING IMPROPER AT ST. LUCIE 10	100270 P170
	DES POINT DRIFT IN STEAM	GENERATOR NO 1 TRIPS FROM HIGH COOLING WATER TEMPERATURE	100454 P172
	DES POINT DRIFT IN STEAM	GENERATOR NO 2 TRIPS FROM HIGH COOLING WATER TEMPERATURE	100455 P172
	DES POINT DRIFT IN STEAM	GENERATOR NOT TESTED WHEN REQUIRED AT COOK 10	100006 P 35
	DES POINT DRIFT IN STEAM	GENERATOR NOZZLE INDICATIONS AT DIABLO CANYON 1 AND 20	001376 P 52
	DES POINT DRIFT IN STEAM	GENERATOR OIL COOLER OUTLET PLANGE LEAKS AT ARKANSAS	100520 P 12
	DES POINT DRIFT IN STEAM	GENERATOR PERFORMANCE	101621 P230
	DES POINT DRIFT IN STEAM	GENERATOR PRESSURE CHANNELS AT HILLSTONE 20	100051 P 97
	DES POINT DRIFT IN STEAM	GENERATOR PRIMARY HEAD GASKET PENETRATED AT ST. LUCIE 10	100006 P177
	DES POINT DRIFT IN STEAM	GENERATOR SAMPLE LINE VALVE FAILS TO CLOSE AT COOK 30	103093 P122
	DES POINT DRIFT IN STEAM	GENERATOR SAMPLE LINE VALVE FOUND IMPROPER AT THREE MILE	100676 P210
	DES POINT DRIFT IN STEAM	GENERATOR SERVICE WATER HEAT EXCHANGER LEAKS AT HILLSTONE 2	100355 P 91
	DES POINT DRIFT IN STEAM	GENERATOR SPEED CONTROL FAILS AT CALVERT CLIFFS 10	102167 P 21
	DES POINT DRIFT IN STEAM	GENERATOR STICK AT THREE MILE ISLAND 10	100261 P217
	DES POINT DRIFT IN STEAM	GENERATOR TRIPS AT SAN ONOFRE 10	001500 P170
	DES POINT DRIFT IN STEAM	GENERATOR TRIPS ON LOW LUBE OIL PRESSURE AT ROBINSON 20	101781 P105
	DES POINT DRIFT IN STEAM	GENERATOR TUBE DEGRADATION FOUND AT YAMKEE ROME	100005 P233
	DES POINT DRIFT IN STEAM	GENERATOR TUBE DEGRADATION AT SURRY 1 AND 20	003261 P197
	DES POINT DRIFT IN STEAM	GENERATOR TUBE FAILS AT POINT BEACH 10	100507 P135
	DES POINT DRIFT IN STEAM	GENERATOR TUBE FAILS AT POINT BEACH 10	100257 P135
	DES POINT DRIFT IN STEAM	GENERATOR TUBE FAILURE AT POINT BEACH 10	100905 P137
	DES POINT DRIFT IN STEAM	GENERATOR TUBE LEAK AT POINT BEACH 20	100613 P101
	DES POINT DRIFT IN STEAM	GENERATOR TUBE PULL APART AT SURRY 10	100262 P100
	DES POINT DRIFT IN STEAM	GENERATOR TUBES AT GINNA	101700 P 64
	DES POINT DRIFT IN STEAM	GENERATOR TUBES AT SURRY 10	100070 P109
	DES POINT DRIFT IN STEAM	GENERATOR VALVE EXCEEDS LIMIT AT COOK 10	100820 P 50
	DES POINT DRIFT IN STEAM	GENERATOR VENT FAN FAILS TO START AT RANCHO SECOP	100631 P162
	DES POINT DRIFT IN STEAM	GENERATORS AT CONNECTICUT YAMKEE	103051 P 32
	DES POINT DRIFT IN STEAM	GENERIC PROBLEMS WITH SAMPLE LINES WITHIN PENETRATIONS AT	003240 P162
	DES POINT DRIFT IN STEAM	GINNA	100620 P 60
	DES POINT DRIFT IN STEAM	GINNA	100040 P 63
	DES POINT DRIFT IN STEAM	GINNA	103060 P 60
	DES POINT DRIFT IN STEAM	GINNA	103540 P 67
	DES POINT DRIFT IN STEAM	GINNA	100610 P 60
	DES POINT DRIFT IN STEAM	GINNA	100090 P 63
	DES POINT DRIFT IN STEAM	GINNA	101700 P 64
	DES POINT DRIFT IN STEAM	GINNA	102795 P 65
	DES POINT DRIFT IN STEAM	GINNA	102290 P 67
	DES POINT DRIFT IN STEAM	GINNA	100200 P 60
	DES POINT DRIFT IN STEAM	GINNA	103087 P 65
	DES POINT DRIFT IN STEAM	GINNA	100954 P 66
	DES POINT DRIFT IN STEAM	GINNA	003270 P 62
	DES POINT DRIFT IN STEAM	GINNA	102555 P 65
	DES POINT DRIFT IN STEAM	GINNA	100041 P 63
	DES POINT DRIFT IN STEAM	GINNA	100590 P 66
	DES POINT DRIFT IN STEAM	GINNA	100276 P 63
	DES POINT DRIFT IN STEAM	GINNA	107765 P 68
	DES POINT DRIFT IN STEAM	GINNA	100052 P 65
	DES POINT DRIFT IN STEAM	GINNA	100344 P 67
	DES POINT DRIFT IN STEAM	GINNA	0 100002 P 69
	DES POINT DRIFT IN STEAM	GINNA	0 101732 P 64
	DES POINT DRIFT IN STEAM	GINNA	0 100610 P 60

WILLSTONE 20
ISOLATED AT WILDER 20

10

20

[illegible]

REACTION BUILDING EMERGENCY

209371 P230
209103 P230
209590 P201
10.471 P208
121.139 P233
2091.47 P208
1325.4 P212
1231.47 P208
1236.42 P208
1232.17 P205
124079 P207
124087 P207
124095 P207
124103 P207
124111 P207
124119 P207
124127 P207
124135 P207
124143 P207
124151 P207
124159 P207
124167 P207
124175 P207
124183 P207
124191 P207
124199 P207
124207 P207
124215 P207
124223 P207
124231 P207
124239 P207
124247 P207
124255 P207
124263 P207
124271 P207
124279 P207
124287 P207
124295 P207
124303 P207
124311 P207
124319 P207
124327 P207
124335 P207
124343 P207
124351 P207
124359 P207
124367 P207
124375 P207
124383 P207
124391 P207
124399 P207
124407 P207
124415 P207
124423 P207
124431 P207
124439 P207
124447 P207
124455 P207
124463 P207
124471 P207
124479 P207
124487 P207
124495 P207
124503 P207
124511 P207
124519 P207
124527 P207
124535 P207
124543 P207
124551 P207
124559 P207
124567 P207
124575 P207
124583 P207
124591 P207
124599 P207
124607 P207
124615 P207
124623 P207
124631 P207
124639 P207
124647 P207
124655 P207
124663 P207
124671 P207
124679 P207
124687 P207
124695 P207
124703 P207
124711 P207
124719 P207
124727 P207
124735 P207
124743 P207
124751 P207
124759 P207
124767 P207
124775 P207
124783 P207
124791 P207
124799 P207
124807 P207
124815 P207
124823 P207
124831 P207
124839 P207
124847 P207
124855 P207
124863 P207
124871 P207
124879 P207
124887 P207
124895 P207
124903 P207
124911 P207
124919 P207
124927 P207
124935 P207
124943 P207
124951 P207
124959 P207
124967 P207
124975 P207
124983 P207
124991 P207
124999 P207
125007 P207
125015 P207
125023 P207
125031 P207
125039 P207
125047 P207
125055 P207
125063 P207
125071 P207
125079 P207
125087 P207
125095 P207
125103 P207
125111 P207
125119 P207
125127 P207
125135 P207
125143 P207
125151 P207
125159 P207
125167 P207
125175 P207
125183 P207
125191 P207
125199 P207
125207 P207
125215 P207
125223 P207
125231 P207
125239 P207
125247 P207
125255 P207
125263 P207
125271 P207
125279 P207
125287 P207
125295 P207
125303 P207
125311 P207
125319 P207
125327 P207
125335 P207
125343 P207
125351 P207
125359 P207
125367 P207
125375 P207
125383 P207
125391 P207
125399 P207
125407 P207
125415 P207
125423 P207
125431 P207
125439 P207
125447 P207
125455 P207
125463 P207
125471 P207
125479 P207
125487 P207
125495 P207
125503 P207
125511 P207
125519 P207
125527 P207
125535 P207
125543 P207
125551 P207
125559 P207
125567 P207
125575 P207
125583 P207
125591 P207
125599 P207
125607 P207
125615 P207
125623 P207
125631 P207
125639 P207
125647 P207
125655 P207
125663 P207
125671 P207
125679 P207
125687 P207
125695 P207
125703 P207
125711 P207
125719 P207
125727 P207
125735 P207
125743 P207
125751 P207
125759 P207
125767 P207
125775 P207
125783 P207
125791 P207
125799 P207
125807 P207
125815 P207
125823 P207
125831 P207
125839 P207
125847 P207
125855 P207
125863 P207
125871 P207
125879 P207
125887 P207
125895 P207
125903 P207
125911 P207
125919 P207
125927 P207
125935 P207
125943 P207
125951 P207
125959 P207
125967 P207
125975 P207
125983 P207
125991 P207
125999 P207
126007 P207
126015 P207
126023 P207
126031 P207
126039 P207
126047 P207
126055 P207
126063 P207
126071 P207
126079 P207
126087 P207
126095 P207
126103 P207
126111 P207
126119 P207
126127 P207
126135 P207
126143 P207
126151 P207
126159 P207
126167 P207
126175 P207
126183 P207
126191 P207
126199 P207
126207 P207
126215 P207
126223 P207
126231 P207
126239 P207
126247 P207
126255 P207
126263 P207
126271 P207
126279 P207
126287 P207
126295 P207
126303 P207
126311 P207
126319 P207
126327 P207
126335 P207
126343 P207
126351 P207
126359 P207
126367 P207
126375 P207
126383 P207
126391 P207
126399 P207
126407 P207
126415 P207
126423 P207
126431 P207
126439 P207
126447 P207
126455 P207
126463 P207
126471 P207
126479 P207
126487 P207
126495 P207
126503 P207
126511 P207
126519 P207
126527 P207
126535 P207
126543 P207
126551 P207
126559 P207
126567 P207
126575 P207
126583 P207
126591 P207
126599 P207
126607 P207
126615 P207
126623 P207
126631 P207
126639 P207
126647 P207
126655 P207
126663 P207
126671 P207
126679 P207
126687 P207
126695 P207
126703 P207
126711 P207
126719 P20

OUTER POINT UNIT IN UNEXPECTEDLY RELAY AT PRAIRIE	ISLAND 20	103670 P151
ONCE LEAKAGE EVALUATION NOT PERFORMED ONE DAY AT PRAIRIE	ISLAND 20	102115 P151
BLASPHE IN CONTAINMENT INTEGRITY AT PRAIRIE	ISLAND 20	099111 P150
CONTAINMENT VACUUM BREAKER INOPERABLE AT PRAIRIE	ISLAND 20	102529 P151
OUTER POINT UNIT IN LEVER AND FLOW SWITCHES AT PRAIRIE	ISLAND 20	102106 P150
OPPRESSOR LUGS AND SAMPLE LINE LEAKS AT PRAIRIE	ISLAND 20	100427 P150
UNDER-TEMPERATURE JETTER FIFTH SETTING EMPLOYED AT PRAIRIE	ISLAND 20	104373 P152
BLEEDING HEAT EXCHANGER TUBE FAILURE AT PRAIRIE	ISLAND 20	100425 P150
BREAR VACUUM IN KNO SYSTEM PIPING AT PRAIRIE	ISLAND 20	100434 P153
BREAR AND MOLD LUGS NOT INSTALLED AT PRAIRIE	ISLAND 20	107016 P153
CONTAINMENT VACUUM BREAKER PUMP INOPERABLE AT PRAIRIE	ISLAND 20	105162 P153
CONCRETE CYLINDER TEST STRENGTHS (SUPPLEMENT) AT THREE MILE	ISLAND 20	100420 P219
REPORT ON THERMAL BARRIER HEAT EXCHANGER LEAKAGE AT PRAIRIE	ISLAND 20	071056 P151
BUILDING VENTILATION SYSTEM TRAIL INOPERABLE AT PRAIRIE	ISLAND 20	071056 P152
CONCRETE PUMP SEAL WATER RETURN LINE LEAKS AT PRAIRIE	ISLAND 20	100426 P150
GROUNDING SPRAY PUMP MOTOR MANIPULATIONS AT THREE MILE	ISLAND 20	102614 P219
WELDING CABLE THAT PRINTING PUMP DEFICIENT AT THREE MILE	ISLAND 20	100387 P220
PREWATER PUMP LUBE OIL PRESSURE SWITCH FAILS AT PRAIRIE	ISLAND 20	104558 P152
IMPROVEMENT ON DEFECTIVE CRANE VALVES AT THREE MILE	ISLAND 20	103005 P219
FAN COIL DAMPER IMPROPERLY POSITIONED AT PRAIRIE	ISLAND 20	100035 P154
JOBBER SYSTEM AC BREAKER CABINETS DEFICIENCY AT THREE MILE	ISLAND 20	093600 P219
INSULATION FOUND IN AC PUMP HUTS AND STUDS AT THREE MILE	ISLAND 20	104976 P220
BLUCK FALLS NOT SEISMICALLY QUALIFIED AT THREE MILE	ISLAND 20	104365 P220
RANGE HIGH FLUX REACTION TRIP SET POINT AT PRAIRIE	ISLAND 20	100033 P153
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATED AT COOK 10	107123 P 37
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATED AT COOK 20	107520 P118
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATED AT COOK 20	107527 P118
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATED AT COOK 20	102134 P121
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATED AT COOK 20	100264 P101
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATED AT COOK 20	107227 P106
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATED AT COOK 20	109580 P 62
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION DEVICE AT FT. CALHOUN	102149 P 30
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION MEMBRANE BARRIER DEFICIENCY AT COOK 10	093540 P120
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION OF KROONE OVERHEAD FEEDER AT COOK 30	099485 P 18
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION SIGNAL SENSOR FAILS AT CALVERT CLIFFS 10	100031 P 07
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION TRIP VALVE FAILS TO CLOSE AT RAINE YANKEE	104209 P 66
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE AT GENNA	099102 P234
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE AT ZION 10	104697 P 42
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE CLOSING TIME SLOW AT COOK 10	104697 P 43
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE CLOSING TIME SLOW AT COOK 10	104071 P 80
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE FAILED TO CLOSE AT REMANUEP	104087 P104
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE FAILS TO CLOSE AT COOK 10	103059 P113
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE FAILS TO CLOSE AT COOK 20	102670 P109
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE FAILS TO CLOSE AT SURREY 10	107763 P224
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE FAILS TO CLOSE AT THREE POINT 30	099677 P235
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE FAILS TO CLOSE AT ZION 10	099716 P235
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE FAILS TO CLOSE AT ZION 10	093254 P242
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE FAILS TO CLOSE AT ZION 20	100088 P243
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE FAILS TO CLOSE AT ZION 20	099109 P241
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE FAILS TO CLOSE AT ZION 20	100542 P252
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE FAILS TO CLOSE COMPLETELY AT ZION 20	104659 P250
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE FAILS TO OPERATE AT RANCHO SEC00	100078 P156
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE FOUND INSTALLED IMPROPERLY AT CALVERT	103126 P 23
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE FOUND TO BE INOPERABLE AT COOK 30	103096 P124
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE INOPERABLE AT ZION 20	104018 P249
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE LEAK RATES EXCESSIVE AT ZION 20	103063 P247
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE LEAKS AT POINT BEACH 10	103006 P131
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVE LEAKS EXCESSIVELY AT THREE MILE ISLAND 10	103090 P207
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVES CLOSED AT RAINE YANKEE	104081 P 05
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVES FAIL TO CLOSE AT REMANUEP	103099 P 80
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVES FAIL TO CLOSE AT ZION 20	100490 P243
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVES FAILS TO CLOSE AT ZION 20	103090 P248
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVES FOUND OPEN AT COOK 20	102317 P112
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVES IN AIR LINE FOUND CLOSED AT THREE MILE	102605 P213
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVES NOT PERFORMED WHEN REQUIRED AT HILLSTONE 2	100353 P 91
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVES NOT TESTED AT REMANUEP	103043 P 80
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOLATION VALVES TESTED FOR LEAKAGE AT POINT BEACH 20	099108 P140
ISOLATION PUMP TO CRYSTALLINE PUMPS	ISOTOPIC ANALYSIS NOT PERFORMED AT RANCHO SEC00	104962 P140
CRACKS FOUND IN SWITCHGEAR THERMOPLASTIC INSULATION	JACKET AT DIABLO CANYON 20	100026 P 52
ISLAND 10	JOINTS LEAK IN VENT LINE OF MAKE-UP PUMPS AT THREE MILE	104308 P208
ISLAND 10	ISLAND 10	100204 P106
ISLAND 10	ISLAND 10	101170 P121
ISLAND 10	ISLAND 10	093540 P120
ISLAND 10	ISLAND 10	100290 P106
ISLAND 10	ISLAND 10	102134 P121
ISLAND 10	ISLAND 10	103058 P103
ISLAND 10	ISLAND 10	107506 P 02
ISLAND 10	ISLAND 10	106117 P 01
ISLAND 10	ISLAND 10	106012 P 01
ISLAND 10	ISLAND 10	105522 P 01

CONTAINMENT FAN SERVICE WATER VALVES FAIL TO OPEN AT 106370 P 01
 20-LEAD BUILDING VENTILATION SYSTEM LOCKED "2" AT 107783 P 02
 AUXILIARY FEEDWATER PUMP FLOWS RESTRICTED AT 108076 P 02
 UNSAFEGUARD BUS BREAKER TRIPS CAUSING A UNIT TRIP AT 108036 P 03
 DECONTAMINATION SHIFT OF BORIC ACID TANK LEVEL INSTRUMENTS AT 106072 P 00
 DIESEL GENERATOR FAILS TO START AT 108076 P 02
 AUXILIARY FEEDWATER PUMP FAILS TO START AT 100619 P 78
 SAFETY INJECTION VALVE MOTOR BREAKER TRIPS AT 102490 P 79
 SAFETY INJECTION SYSTEM RELAY FAILS TO LATCH AT 122409 P 78
 CONTAINMENT SHUT DOWN ISOLATION VALVES NOT TESTED AT 103603 P 00
 WASTE NEUTRALIZING TANK DISCHARGE PH LOW AT 102555 P 79
 THROUGH WALL LEAK IN CHARGING LINE VENT PIPING AT 093253 P 77
 DATA-OPERATED ISOLATION VALVES FAIL TO CLOSE AT 103099 P 00
 SAFETY INJECTION VALVE TRIPS ON OVERCURRENT AT 103131 P 79
 DIESEL IN AUXILIARY FEEDWATER PUMP CONTROL CIRCUIT FAIL, AT 133001 P 75
 SAFETY INJECTION VALVE FAILS TO OPEN AT 102534 P 79
 UNAUTHORIZED RELEASE OF NON-RADIOLOGICAL WASTE AT 100067 P 78
 AUXILIARY FEEDWATER PUMP FAILS TO START AT 093616 P 77
 STEAM GENERATOR BLOWDOWN SAMPLE VALVE FAILS TO CLOSE AT 093503 P 77
 GENERATOR BLOWDOWN LINE ISOLATION VALVE FAILED TO CLOSE AT 124371 P 00
 OF TWO SAFEGUARD TRAINS OUT OF SERVICE CONCURRENTLY AT 136379 P 01
 TEMPERATURE NOT RECORDED ON TIME DURING LOAD CHANGE AT 102114 P 78
 BMSH 1000273 P 3
 DECONTAMINATION OF SECONDARY INSULATION ON 4 1000272 P 2
 OF 1002135 P 56
 OF 100623 P 70
 OF 100953 P 179
 OF 10227 P 106
 OF 100021 P 179
 OF 100512 P 07
 OF 090111 P 150
 OF 103115 P 164
 OF 100600 P 31
 OF 122609 P 78
 OF 100611 P 107
 OF 102009 P 164
 OF 124992 P 223
 OF 102097 P 226
 OF 090925 P 25
 OF 100234 P 12
 OF 101154 P 31
 OF 090372 P 54
 OF 100354 P 91
 OF 102200 P 120
 OF 100613 P 141
 OF 103753 P 170
 OF 107905 P 178
 OF 102274 P 103
 OF 120091 P 231
 OF 100837 P 253
 OF 103901 P 196
 OF 100082 P 104
 OF 105275 P 144
 OF 101552 P 176
 OF 107906 P 11
 OF 105500 P 73
 OF 100002 P 69
 OF 102795 P 65
 OF 100270 P 07
 OF 100404 P 146
 OF 102555 P 25
 OF 093253 P 77
 OF 100092 P 03
 OF 100431 P 03
 OF 100666 P 117
 OF 090673 P 06
 OF 100973 P 9
 OF 090113 P 1
 OF 100039 P 225
 OF 100300 P 208
 OF 100834 P 153
 OF 107409 P 140
 OF 105726 P 107
 OF 100384 P 119
 OF 100212 P 154
 OF 093507 P 129
 OF 102900 P 144
 OF 103063 P 247
 OF 090100 P 166
 OF 103056 P 151
 OF 100560 P 233
 OF 100660 P 250
 OF 102115 P 151
 OF 100107 P 134

BYAPUR CONTAINER	LEAKAGE EXCEEDS LIMITS AT "ANACE ROOM"	105552 P232
REACTOR PURGING OUTLET VALVE	LEAKAGE EXCESSIVE AT HANGAR SECOND	106612 P162
REACTOR COOLANT SYSTEM	LEAKAGE HIGH AT OCOREE 10	106600 P106
REACTOR PURGE VALVE	LEAKAGE HIGH AT ZION 10	106161 P236
REACTOR PURGE VALVE	LEAKAGE NOT REPORTED AT COOK 10	106634 P 41
REACTOR PURGE VALVE	LEAKAGE AT ZION 20	106957 P260
REACTOR PURGE VALVE	LEAKING SOCKET HELDS AT ST. LUCIE 10	106956 P179
REACTOR PURGE VALVE	LEAKS AT ARKANSAS NUCLEAR 10	106900 P 5
REACTOR PURGE VALVE	LEAKS AT ARKANSAS NUCLEAR 10	093576 P 1
REACTOR PURGE VALVE	LEAKS AT ARKANSAS NUCLEAR 10	106920 P 12
REACTOR PURGE VALVE	LEAKS AT ARKANSAS NUCLEAR 10	107915 P 10
REACTOR PURGE VALVE	LEAKS AT CALVERT CLIFFS 10	101451 P 20
REACTOR PURGE VALVE	LEAKS AT COOK 10	104957 P 43
REACTOR PURGE VALVE	LEAKS AT INDIAN POINT 20	104632 P 72
REACTOR PURGE VALVE	LEAKS AT HILLSTONE 20	104355 P 91
REACTOR PURGE VALVE	LEAKS AT HILLSTONE 20	104436 P 93
REACTOR PURGE VALVE	LEAKS AT HILLSTONE 20	104100 P134
REACTOR PURGE VALVE	LEAKS AT POINT BEACH 10	105203 P137
REACTOR PURGE VALVE	LEAKS AT POINT BEACH 10	103906 P137
REACTOR PURGE VALVE	LEAKS AT POINT BEACH 20	106610 P160
REACTOR PURGE VALVE	LEAKS AT PRAIRIE ISLAND 10	104005 P166
REACTOR PURGE VALVE	LEAKS AT PRAIRIE ISLAND 20	104627 P150
REACTOR PURGE VALVE	LEAKS AT PRAIRIE ISLAND 20	104976 P150
REACTOR PURGE VALVE	LEAKS AT THREE MILE ISLAND 10	106311 P210
REACTOR PURGE VALVE	LEAKS AT TURKEY POINT 40	106790 P220
REACTOR PURGE VALVE	LEAKS AT YANKEE ROVER	106966 P210
REACTOR PURGE VALVE	LEAKS AT YANKEE ROVER	106100 P230
REACTOR PURGE VALVE	LEAKS AT ZION 20	102536 P266
REACTOR PURGE VALVE	LEAKS EXCESSIVELY AT THREE MILE ISLAND 10	104940 P267
REACTOR PURGE VALVE	LEAKS EXCESSIVELY AT YANKEE ROVER	106433 P234
REACTOR PURGE VALVE	LEAKS FOUND IN INSTRUMENT LINES AT HILLSTONE 20	106976 P 95
REACTOR PURGE VALVE	LEAKS THROUGH PLUG AT INDIAN POINT 20	106922 P 70
REACTOR PURGE VALVE	LEAKS TO CONTAINMENT AT INDIAN POINT 20	107570 P 70
REACTOR PURGE VALVE	LEFT IN CALIBRATE POSITION AT SURRY 10	101730 P162
REACTOR PURGE VALVE	LEFT IN CALIBRATE POSITION AT SURRY 10	102270 P162
REACTOR PURGE VALVE	LEG TEMPERATURE INPUT AT CALVERT CLIFFS 10	093549 P 16
REACTOR PURGE VALVE	LEG TEMPERATURE INPUT FAILS AT CALVERT CLIFFS 10	093606 P 17
REACTOR PURGE VALVE	LEG TEMPERATURE INPUT TO CALCULATOR FAILS AT CALVERT	093551 P 17
REACTOR PURGE VALVE	LEG TEMPERATURE INPUT TO RPS FAILS AT CALVERT CLIFFS 10	107635 P 29
REACTOR PURGE VALVE	LEG TEMPERATURE INPUT TO THERMAL POWER CALCULATOR FAILS AT	103180 P 23
REACTOR PURGE VALVE	LEG TEMPERATURE TO THERMAL POWER CALCULATOR FAILS AT	103133 P 23
REACTOR PURGE VALVE	LESS THAN LIMIT AT COOK 10	104976 P 44
REACTOR PURGE VALVE	LESS THAN LIMIT AT PALLASADES	106449 P132
REACTOR PURGE VALVE	LESS THAN LIMIT AT SURRY 10	104962 P105
REACTOR PURGE VALVE	LESS THAN LIMITS AT INDIAN POINT 20	102553 P 71
REACTOR PURGE VALVE	LESS THAN LIMITS AT THREE MILE ISLAND 10	104517 P213
REACTOR PURGE VALVE	LESS THAN SPECS AT COOK 10	104965 P 43
REACTOR PURGE VALVE	LESS THAN 10 SECONDS AT FT. CALHOUN	107517 P 60
REACTOR PURGE VALVE	LESS THAN 10 SECONDS AT FT. CALHOUN	107772 P 61
REACTOR PURGE VALVE	LETOBORN COTTERS FOUND TO BE DEFICIENT AT NORTH ANNA 10	106800 P100
REACTOR PURGE VALVE	LETOBORN DRAIN LINE HELD AT GINNA	102795 P 65
REACTOR PURGE VALVE	LETOBORN FILTER GASKET FAILS AT OCOREE 20	093532 P108
REACTOR PURGE VALVE	LETOBORN FILTER VENT REMOVED AT OCOREE 20	107220 P110
REACTOR PURGE VALVE	LETOBORN FLOW INADVERTENTLY ISOLATED AT OCOREE 20	107520 P110
REACTOR PURGE VALVE	LETOBORN HEAT EXCHANGER TUBE FAILURE AT PRAIRIE ISLAND 20	106425 P150
REACTOR PURGE VALVE	LETOBORN LINE HELD AT RAINE YANKEE	106270 P 87
REACTOR PURGE VALVE	LEVEL AND FLOW SWITCHES AT PRAIRIE ISLAND 20	102166 P150
REACTOR PURGE VALVE	LEVEL AT OCOREE 1, 2, AND 30	105537 P106
REACTOR PURGE VALVE	LEVEL AT THREE MILE ISLAND 10	107607 P214
REACTOR PURGE VALVE	LEVEL BELOW LIMIT AT POINT BEACH 20	107705 P161
REACTOR PURGE VALVE	LEVEL CHANNEL FAILS TO GENERATE TRIP SIGNAL AT ROBINSON 20	093570 P166
REACTOR PURGE VALVE	LEVEL CHANNEL NOT PLACED IN TRIPPED POSITION AT COOK 10	105046 P 44
REACTOR PURGE VALVE	LEVEL COMPARTMENT AT ZION 10	100900 P236
REACTOR PURGE VALVE	LEVEL COMPARTMENT AT ZION 20	101002 P244
REACTOR PURGE VALVE	LEVEL COMPARTMENT AT ZION 20	100927 P244
REACTOR PURGE VALVE	LEVEL COMPARTMENT FAILS AT TURKEY POINT 30	102312 P222
REACTOR PURGE VALVE	LEVEL CONTROL VIOLATES STANDARDS AT GINNA	106610 P 60
REACTOR PURGE VALVE	LEVEL CUT OFF TOO SOON AT THREE MILE ISLAND 10	104006 P207
REACTOR PURGE VALVE	LEVEL CUTOFF EXCEEDED DURING TRANSIENT TENSION CONDITIONS AT	104302 P123
REACTOR PURGE VALVE	LEVEL DECREASED BELOW LIMIT AT HILLSTONE 20	106810 P 95
REACTOR PURGE VALVE	LEVEL DECREASED BELOW LIMIT AT SURRY 20	105530 P106
REACTOR PURGE VALVE	LEVEL EXCEEDS LIMIT DURING TRANSIENT TENSION AT OCOREE 20	093526 P108
REACTOR PURGE VALVE	LEVEL FOUND TO BE LESS THAN LIMITS AT THREE MILE ISLAND 10	104517 P213
REACTOR PURGE VALVE	LEVEL IN EFFLUENT EXCEEDS CONTROL VALUE AT THREE MILE	107525 P215
REACTOR PURGE VALVE	LEVEL INDICATION FAILS AT OCOREE 2 AND 30	105040 P110
REACTOR PURGE VALVE	LEVEL INDICATION FAILS AT OCOREE 2 AND 30	101169 P110
REACTOR PURGE VALVE	LEVEL INDICATION MALFUNCTION AT SURRY 20	093250 P100
REACTOR PURGE VALVE	LEVEL INDICATOR AT SURRY 20	104340 P101
REACTOR PURGE VALVE	LEVEL INDICATOR AT SURRY 20	100072 P101
REACTOR PURGE VALVE	LEVEL INDICATOR AT SURRY 20	100262 P101
REACTOR PURGE VALVE	LEVEL INDICATORS AT FT. CALHOUN	101660 P 56
REACTOR PURGE VALVE	LEVEL INDICATORS AT ZION 20	106813 P250
REACTOR PURGE VALVE	LEVEL INSTRUMENT FAILS AT OCOREE 20	105170 P117
REACTOR PURGE VALVE	LEVEL INSTRUMENT MALFUNCTION AT POINT BEACH 20	093017 P109
REACTOR PURGE VALVE	LEVEL INSTRUMENTS AT KEWAUNEE	104072 P 60
REACTOR PURGE VALVE	LEVEL INSTRUMENTS NOT PERFORMED AT KEWAUNEE	106812 P 81
REACTOR PURGE VALVE	LEVEL LESS THAN LIMIT AT COOK 10	104976 P 44
REACTOR PURGE VALVE	LEVEL LOW AT INDIAN POINT 20	104634 P 72
CLIFFS 10	ORCS COLD	
CALVERT CLIFFS 10	ORCS COLD	
CALVERT CLIFFS 10	ORCS COLD	
CONDENSATE STORAGE TANK LEVEL	LESS THAN LIMIT AT COOK 10	
CONDENSATE STORAGE TANK LEVEL	LESS THAN LIMIT AT PALLASADES	
CONDENSATE STORAGE TANK LEVEL	LESS THAN LIMIT AT SURRY 10	
CONDENSATE STORAGE TANK LEVEL	LESS THAN LIMITS AT INDIAN POINT 20	
CONDENSATE STORAGE TANK LEVEL	LESS THAN LIMITS AT THREE MILE ISLAND 10	
CONDENSATE STORAGE TANK LEVEL	LESS THAN SPECS AT COOK 10	
CONDENSATE STORAGE TANK LEVEL	LESS THAN 10 SECONDS AT FT. CALHOUN	
CONDENSATE STORAGE TANK LEVEL	LESS THAN 10 SECONDS AT FT. CALHOUN	
CONDENSATE STORAGE TANK LEVEL	LETOBORN COTTERS FOUND TO BE DEFICIENT AT NORTH ANNA 10	
CONDENSATE STORAGE TANK LEVEL	LETOBORN DRAIN LINE HELD AT GINNA	
CONDENSATE STORAGE TANK LEVEL	LETOBORN FILTER GASKET FAILS AT OCOREE 20	
CONDENSATE STORAGE TANK LEVEL	LETOBORN FILTER VENT REMOVED AT OCOREE 20	
CONDENSATE STORAGE TANK LEVEL	LETOBORN FLOW INADVERTENTLY ISOLATED AT OCOREE 20	
CONDENSATE STORAGE TANK LEVEL	LETOBORN HEAT EXCHANGER TUBE FAILURE AT PRAIRIE ISLAND 20	
CONDENSATE STORAGE TANK LEVEL	LETOBORN LINE HELD AT RAINE YANKEE	
CONDENSATE STORAGE TANK LEVEL	LEVEL AND FLOW SWITCHES AT PRAIRIE ISLAND 20	
CONDENSATE STORAGE TANK LEVEL	LEVEL AT OCOREE 1, 2, AND 30	
CONDENSATE STORAGE TANK LEVEL	LEVEL AT THREE MILE ISLAND 10	
CONDENSATE STORAGE TANK LEVEL	LEVEL BELOW LIMIT AT POINT BEACH 20	
CONDENSATE STORAGE TANK LEVEL	LEVEL CHANNEL FAILS TO GENERATE TRIP SIGNAL AT ROBINSON 20	
CONDENSATE STORAGE TANK LEVEL	LEVEL CHANNEL NOT PLACED IN TRIPPED POSITION AT COOK 10	
CONDENSATE STORAGE TANK LEVEL	LEVEL COMPARTMENT AT ZION 10	
CONDENSATE STORAGE TANK LEVEL	LEVEL COMPARTMENT AT ZION 20	
CONDENSATE STORAGE TANK LEVEL	LEVEL COMPARTMENT AT ZION 20	
CONDENSATE STORAGE TANK LEVEL	LEVEL COMPARTMENT FAILS AT TURKEY POINT 30	
CONDENSATE STORAGE TANK LEVEL	LEVEL CONTROL VIOLATES STANDARDS AT GINNA	
CONDENSATE STORAGE TANK LEVEL	LEVEL CUT OFF TOO SOON AT THREE MILE ISLAND 10	
CONDENSATE STORAGE TANK LEVEL	LEVEL CUTOFF EXCEEDED DURING TRANSIENT TENSION CONDITIONS AT	
CONDENSATE STORAGE TANK LEVEL	LEVEL DECREASED BELOW LIMIT AT HILLSTONE 20	
CONDENSATE STORAGE TANK LEVEL	LEVEL DECREASED BELOW LIMIT AT SURRY 20	
CONDENSATE STORAGE TANK LEVEL	LEVEL EXCEEDS LIMIT DURING TRANSIENT TENSION AT OCOREE 20	
CONDENSATE STORAGE TANK LEVEL	LEVEL FOUND TO BE LESS THAN LIMITS AT THREE MILE ISLAND 10	
CONDENSATE STORAGE TANK LEVEL	LEVEL IN EFFLUENT EXCEEDS CONTROL VALUE AT THREE MILE	
CONDENSATE STORAGE TANK LEVEL	LEVEL INDICATION FAILS AT OCOREE 2 AND 30	
CONDENSATE STORAGE TANK LEVEL	LEVEL INDICATION FAILS AT OCOREE 2 AND 30	
CONDENSATE STORAGE TANK LEVEL	LEVEL INDICATION MALFUNCTION AT SURRY 20	
CONDENSATE STORAGE TANK LEVEL	LEVEL INDICATOR AT SURRY 20	
CONDENSATE STORAGE TANK LEVEL	LEVEL INDICATOR AT SURRY 20	
CONDENSATE STORAGE TANK LEVEL	LEVEL INDICATOR AT SURRY 20	
CONDENSATE STORAGE TANK LEVEL	LEVEL INDICATORS AT FT. CALHOUN	
CONDENSATE STORAGE TANK LEVEL	LEVEL INDICATORS AT ZION 20	
CONDENSATE STORAGE TANK LEVEL	LEVEL INSTRUMENT FAILS AT OCOREE 20	
CONDENSATE STORAGE TANK LEVEL	LEVEL INSTRUMENT MALFUNCTION AT POINT BEACH 20	
CONDENSATE STORAGE TANK LEVEL	LEVEL INSTRUMENTS AT KEWAUNEE	
CONDENSATE STORAGE TANK LEVEL	LEVEL INSTRUMENTS NOT PERFORMED AT KEWAUNEE	
CONDENSATE STORAGE TANK LEVEL	LEVEL LESS THAN LIMIT AT COOK 10	
CONDENSATE STORAGE TANK LEVEL	LEVEL LOW AT INDIAN POINT 20	

OBORATED WATER STORAGE TANK	LEVEL LOW AT OCONEE 10	137222 P106
OBORATED WATER STORAGE TANK	LEVEL LOW AT OCONEE 30	104301 P123
BABOYU GAGUVO EMERGENCY CONDENSATE TANK	LEVEL LOW AT SURRY 20	103644 P106
EMERGENCY CONDENSATE STORAGE TANK	LEVEL LOW AT SURRY 20	103690 P106
DEFUELING POOL WATER	LEVEL LOW DURING CORE ALTERATIONS AT HILLSTONE 20	105506 P 90
VENTURE CANAL	LEVEL MAGNETIC AMPLIFIERS FAIL AT SURRY 1 AND 20	090731 P107
MEASURED	LEVEL OF AIRBORNE RADIOACTIVITY EXCEEDS CONTROL LEVEL AT	105537 P106
MEASURED	LEVEL OF RADIATION IN EFFLUENT EXCEEDS CONTROL AT THREE	102670 P203
UNCONTROLLED RELEASE OF LOW	LEVEL RADIOACTIVE LIQUID AT PALISADES0	093502 P126
	LEVEL RADIOACTIVE LIQUID RELEASE AT POINT BEACH 10	02319 P136
	LEVEL RADIOACTIVE LIQUID RELEASE AT POINT BEACH 10	101147 P136
	LEVEL RADIOACTIVE RELEASE WITHOUT IN-LINE MONITOR AT POINT	099715 P160
UNPLANNED RELEASE OF LOW	LEVEL RADIOACTIVE WATER AT SURRY 10	101720 P102
UNPLANNED RELEASE OF LOW	LEVEL RADIOACTIVE WATER TO RIVER AT SURRY 10	093256 P100
	LEVEL RAISED ABOVE CUTOFF PRIOR TO XENON EQUILIBRIUM AT	101726 P111
	LEVEL SERAN INSTRUMENT AT YANKEE 30M0	070044 P233
	LEVEL SENSOR AT ZION 20	093604 P262
	LEVEL TOO LOW AT OCONEE 20	102946 P112
	LEVEL TRANSMITTERS AT ZION 20	100526 P252
	LEVEL TRIP DISTANCE FAILS TO TRIP AT MAINE YANKEE0	100913 P 04
MAIN STEAM ATMOSPHERIC RELIEF VALVE	LEVELS AT ZION 20	100913 P252
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT ARKANSAS NUCLEAR 10	100530 P 12
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT ARKANSAS NUCLEAR 10	100771 P 13
DECHLORIDE INCREASE ACROSS PLANT EXCEEDS	LIMIT AT ARKANSAS NUCLEAR 10	100611 P 9
DECHLORIDE CONCENTRATIONS IN EFFLUENT EXCEED	LIMIT AT ARKANSAS NUCLEAR 10	100774 P 13
DECHLORIDE CONCENTRATIONS IN EFFLUENT EXCEED	LIMIT AT ARKANSAS NUCLEAR 10	100777 P 13
DECHLORIDE CONCENTRATIONS IN EFFLUENT EXCEED	LIMIT AT ARKANSAS NUCLEAR 10	100775 P 11
DECHLORIDE CONCENTRATIONS IN EFFLUENT EXCEED	LIMIT AT ARKANSAS NUCLEAR 10	100071 P 11
DECHLORIDE CONCENTRATION EXCEEDS	LIMIT AT ARKANSAS NUCLEAR 10	100272 P 2
DECHLORIDE CONCENTRATION EXCEEDS	LIMIT AT ARKANSAS NUCLEAR 10	100273 P 3
DECHLORIDE CONCENTRATION EXCEEDS	LIMIT AT ARKANSAS NUCLEAR 10	100374 P 8
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT ARKANSAS NUCLEAR 10	100510 P 7
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT ARKANSAS NUCLEAR 10	100375 P 8
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT ARKANSAS NUCLEAR 10	100341 P 6
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT ARKANSAS NUCLEAR 10	100306 P 4
DECHLORIDE CONCENTRATION OF AMMONIA IN EFFLUENT EXCEEDS	LIMIT AT ARKANSAS NUCLEAR 10	100287 P 7
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT ARKANSAS NUCLEAR 10	100519 P 7
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT ARKANSAS NUCLEAR 10	100477 P 6
DECHLORIDE INCREASE ACROSS PLANT EXCEEDS	LIMIT AT ARKANSAS NUCLEAR 10	100517 P 9
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT ARKANSAS NUCLEAR 10	100306 P 5
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT ARKANSAS NUCLEAR 10	100394 P 6
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT CALVERT CLIFFS 10	100733 P 25
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT CALVERT CLIFFS 10	100767 P 20
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT CALVERT CLIFFS 10	100761 P 22
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT CALVERT CLIFFS 10	100790 P 26
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT COOK 10	100776 P 44
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT COOK 10	100774 P 49
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT COOK 10	100789 P 44
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT COOK 10	100829 P 50
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT COOK 10	099302 P 34
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT FT. CALHOUN0	100774 P 49
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT FT. CALHOUN0	100760 P 57
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT FT. CALHOUN0	100777 P 56
DECHLORIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT GUNBAR	100776 P 60
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT INDIAN POINT 20	100801 P 76
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT INDIAN POINT 20	100766 P 75
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT INDIAN POINT 20	100763 P 73
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT HILLSTONE 20	100819 P 95
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT HILLSTONE 20	100841 P 94
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT HILLSTONE 20	100253 P 90
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT OCONEE 10	100555 P107
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT OCONEE 10	100495 P103
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT OCONEE 1, 2, AND 30	100290 P107
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT OCONEE 1, 2, AND 30	100330 P105
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT OCONEE 1, 2, AND 30	100290 P106
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT OCONEE 20	100224 P119
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT OCONEE 20	100406 P117
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT PALISADES0	100246 P134
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT PALISADES0	100187 P134
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT PALISADES0	100511 P133
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT PALISADES0	090507 P125
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT PALISADES0	100449 P132
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT POINT BEACH 1 AND 20	100566 P142
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT POINT BEACH 10	093517 P135
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT POINT BEACH 20	099365 P139
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT POINT BEACH 20	100775 P161
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT PRAIRIE ISLAND 1 AND 20	100210 P149
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT PRAIRIE ISLAND 1 AND 20	100481 P154
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT PRAIRIE ISLAND 1 AND 20	100791 P156
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT PRAIRIE ISLAND 1 AND 20	100694 P155
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT PRAIRIE ISLAND 1 AND 20	100312 P155
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT PRAIRIE ISLAND 10	100990 P144
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT RANCHO SEC00	100216 P150
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT RANCHO SEC00	100294 P161
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT RANCHO SEC00	100406 P158
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT RANCHO SEC00	100313 P161
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT RANCHO SEC00	100272 P161
DECHLORIDE CONCENTRATION IN STORAGE TANKS BELOW	LIMIT AT RANCHO SEC00	100295 P160

REACTION COOLANT SYSTEM JARVIS CONCENTRATION EXCEEDS	LIMIT AT ROBINSON 20	104960 P168
BOILUM CONCENTRATION IN ACCUMULATOR LESS THAN	LIMIT AT SURRY 10	104962 P185
VENTILATION VENT GAS RELEASE EXCEEDS OR OF	LIMIT AT SURRY 10	104966 P188
VENTILATION VENT GASEOUS RELEASE EXCEEDS	LIMIT AT SURRY 10	104315 P185
BOUNTAINMENT LEAK RATE EXCEEDS	LIMIT AT SURRY 10	107526 P187
BOUADRANT TILT EXCEEDS	LIMIT AT SURRY 20	108554 P191
BOOHIC ACID TANK LEVEL DECREASED BELOW	LIMIT AT SURRY 20	105530 P196
BOTEMPERATURE GRADIENT ACROSS CONDENSER EXCEEDS	LIMIT AT SURRY 20	102273 P192
BOURE RADIAL DISTRIBUTION TILTS IN EXCESS OF	LIMIT AT SURRY 20	101780 P192
BOITAL CHLORINE CONCENTRATION IN RIVER EXCEEDS	LIMIT AT THREE MILE ISLAND 10	102668 P206
BOPOSITE RIVER WATER SAMPLE INDICATED RESULTS EXCEEDS	LIMIT AT THREE MILE ISLAND 10	102140 P204
BOTEMPERATURE DIFFERENCE ACROSS THE PLANT EXCEEDS	LIMIT AT THREE MILE ISLAND 10	108209 P216
BOCONCENTRATION IN PRIMARY EFFLUENT SAMPLE EXCEEDS	LIMIT AT THREE MILE ISLAND 10	100277 P216
BOCONCENTRATION OF TRITIUM IN RIVER WATER EXCEEDS	LIMIT AT THREE MILE ISLAND 10	102234 P215
BOSSPENDED SOLIDS IN EFFLUENT EXCEEDS	LIMIT AT THREE MILE ISLAND 10	104251 P200
BOTRITIUM CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT THREE MILE ISLAND 10	103673 P206
BOISSOLVED SOLIDS CONCENTRATION IN EFFLUENT EXCEEDS	LIMIT AT THREE MILE ISLAND 10	104678 P209
BOETHERMAL PLUME SIZE EXCEEDS	LIMIT AT ZION 1 AND 20	107680 P239
BOHOLE GAS RELEASE RATE EXCEEDS	LIMIT AT ZION 10	105727 P230
BOYEARLY USE OF BOHIC ACID EXCEEDS	LIMIT AT ZION 10	100375 P234
BOUNPLANNED INSERTION OF ACTIVITY EXCEEDS	LIMIT DURING SHUTDOWN AT GINNA	100924 P 64
BOPOWER LEVEL EXCEEDS	LIMIT DURING TRANSIENT XENON AT OCONEE 20	099326 P100
BOCHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED	LIMIT TWICE AT ARKANSAS NUCLEAR 10	103459 P 5
BOAVAILABILITY OF EMERGENCY SHUTDOWN COOLING WATER	LIMITED AT THREE MILE ISLAND 10	106305 P212
BOCONSEQUENCE	LIMITING SAFEGUARD TRAIN FAILS TO OPERATE AT SURRY 20	102562 P193
BOALUMIDE CONCENTRATION IN EFFLUENT EXCEEDS	LIMITS AT ARKANSAS NUCLEAR 10	103076 P 5
BOHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED	LIMITS AT ARKANSAS NUCLEAR 10	105288 P 7
BOCHLORINE CONCENTRATION IN EFFLUENT EXCEEDS	LIMITS AT ARKANSAS NUCLEAR 10	103652 P 4
BOCHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED	LIMITS AT ARKANSAS NUCLEAR 10	105286 P 7
BOCHEMICAL CONCENTRATION IN EFFLUENT EXCEEDS	LIMITS AT ARKANSAS NUCLEAR 10	103128 P 6
BOHEMICAL CONCENTRATION IN EFFLUENT EXCEEDS	LIMITS AT ARKANSAS NUCLEAR 10	103129 P 3
BOHEMICAL CONCENTRATION IN EXCESS OF	LIMITS AT ARKANSAS NUCLEAR 10	104021 P 6
BOCHEMICAL CONCENTRATIONS EXCEED	LIMITS AT ARKANSAS NUCLEAR 10	100560 P 12
BOCHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED	LIMITS AT ARKANSAS NUCLEAR 10	108233 P 12
BOHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED	LIMITS AT ARKANSAS NUCLEAR 10	107914 P 11
BOHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED	LIMITS AT ARKANSAS NUCLEAR 10	107412 P 10
BOHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED	LIMITS AT ARKANSAS NUCLEAR 10	107411 P 10
BOHEMICAL CONCENTRATIONS IN EFFLUENT EXCEED	LIMITS AT ARKANSAS NUCLEAR 10	108202 P 11
BORELEASE OF NOBLE GASES EXCEEDS	LIMITS AT CALVERT CLIFFS 10	106370 P 27
BOAVERAGE EFFLUENT TEMPERATURE EXCEEDS	LIMITS AT CALVERT CLIFFS 10	102360 P 27
BOISSOLVED OXYGEN ACROSS PLANT COOLING WATER EXCEEDS	LIMITS AT CONNECTICUT YANKEE	106340 P 23
BOPM OF TURBINE ROOM SUMP DISCHARGE EXCEEDS	LIMITS AT COOK 10	099196 P 33
BOBURNING ROOM SUMP DISCHARGE OUT OF	LIMITS AT COOK 10	099114 P 33
BORELEASES FROM WASTE HOLDUP TANK OUT OF	LIMITS AT COOK 10	100090 P 34
BOREFUELING WATER STORAGE TANK VOLUME LESS THAN	LIMITS AT INDIAN POINT 20	102553 P 71
BOCIRCULATING WATER DISCHARGE TEMPERATURE EXCEEDS	LIMITS AT MAINE YANKEE	106377 P 86
BOADIATION EXPOSURES IN EXCESS OF ADMINISTRATIVE	LIMITS AT OCONEE 10	099704 P101
BOERRUM FOUND IN COMPUTER PROGRAM USED FOR ALARM	LIMITS AT PALISADES	107762 P133
BORELEASE RATE OF HEATED WATER EXCEEDS	LIMITS AT PALISADES	102703 P129
BOHEATLY WATER RELEASE RATE EXCEEDS	LIMITS AT PALISADES	101730 P127
BORELEASE RATE AND TEMPERATURE OF HEATED WATER EXCEEDS	LIMITS AT PALISADES	101737 P126
BORELEASE RATES OF LIQUID WASTEWATER EXCEED	LIMITS AT PALISADES	106450 P133
BOHEATING TOWER BLOWDOWN FLOW EXCEEDS	LIMITS AT PRAIRIE ISLAND 1 AND 20	105527 P155
BODISCHARGE OF DISSOLVED SOLIDS EXCEEDS	LIMITS AT RANCHO SECOP	105731 P161
BOCHLORINE CONCENTRATION IN EFFLUENT EXCEEDS	LIMITS AT RANCHO SECOP	103130 P149
BOCONCENTRATED BOHIC ACID STORAGE TANK VOLUME BELOW	LIMITS AT RANCHO SECOP	103306 P159
BOCHLORINE IN EFFLUENT EXCEEDS	LIMITS AT RANCHO SECOP	102117 P158
BOREACTION COOLANT SYSTEM OXYGEN CONCENTRATION EXCEEDS	LIMITS AT ROBINSON 20	103484 P164
BOBOILUM CONCENTRATION IN SI ACCUMULATOR BELOW	LIMITS AT SURRY 10	105277 P184
BOCONTAINMENT VACUUM SYSTEM CAPACITY BELOW	LIMITS AT SURRY 20	102558 P191
BOBOLE FLOOD TANK LEVEL FOUND TO BE LESS THAN	LIMITS AT THREE MILE ISLAND 10	104517 P213
BOBTRITIUM CONCENTRATION IN RIVER WATER EXCEEDS	LIMITS AT THREE MILE ISLAND 10	103449 P205
BOCHLORINE IN RIVER WATER DISCHARGE EXCEEDS	LIMITS AT THREE MILE ISLAND 10	099678 P201
BOVAPOR CONTAINER LEAKAGE EXCEEDS	LIMITS AT YANKEE ROME	105552 P232
BOAXIAL FLUX DIFFERENCE	LIMITS EXCEEDED AT COOK 10	104306 P 42
BOAXIAL POWER DISTRIBUTION CHANNEL TRIP	LIMITS OUT OF SPECS AT FT. CALHOUN	103443 P 58
BOHEMICAL CONCENTRATION IN EFFLUENT EXCEEDS	LIMITS TWICE AT ARKANSAS NUCLEAR 10	103660 P 6
BOADDITIONAL INFORMATION ON LEAK IN VENT	LIMIT ASSEMBLY AT TURKEY POINT 60	108039 P225
BOLEAK FOUND IN VENT	LIMIT AT ARKANSAS NUCLEAR 10	107900 P 11
BOPINHOLE LEAK FOUND IN CHARGING PUMP DISCHARGE DRAIN	LIMIT AT GINNA	108062 P 69
BOPIN-HOLE LEAK IN CHARGING PUMP RECIRCULATION	LIMIT AT MAINE YANKEE	104431 P 83
BOPIN-HOLE LEAK IN CHARGING PUMP	LIMIT AT MAINE YANKEE	100892 P 83
BOINADEQUATE CONTROL OF ISOLATED 100 KV TRANSMISSION	LIMIT AT OCONEE 10	107221 P186
BOPINHOLE LEAK DEVELOPS IN CHARGING PUMP RECIRCULATION	LIMIT AT SURRY 10	104062 P184
BOGAP FOUND AT SILEW BEARING PLATE FOR MAIN STEAM	LIMIT AT THREE MILE ISLAND 10	102533 P205
BOBOHIC ACID MIX TANK OUTLET	LIMIT BLOCKED AT THREE MILE ISLAND 10	107408 P214
BOHEAT ENERGY	LIMIT BREAK DOWN INADVERTENTLY REMOVED AT OCONEE 20	105178 P116
BOASAFETY INJECTION SYSTEM VENT	LIMIT CRACKS AT BEAVER VALLEY 10	104076 P 14
BOCHARGING PUMP RECIR	LIMIT DEVELOPS PINHOLE LEAK AT SURRY 10	102274 P183
BOBOLE FLOOD TANK SAMPLE	LIMIT FAILS TO CLOSE AT THREE MILE ISLAND 10	106308 P211
BOBRAIN STEAM	LIMIT FLOW CHANNEL FAILS AT POINT BEACH 10	101774 P134
BOCHARGING	LIMIT FLOW TRANSMITTER LINE LEAKS AT YANKEE ROME	100366 P230
BOBHO MANUAL ISOLATION VALVES IN AIR	LIMIT FOUND CLOSED AT THREE MILE ISLAND 10	102605 P213
BOHEAT IN PRESSURE SENSING	LIMIT FROM RC PUMP SEAL CAVITY LEAKS AT ARKANSAS NUCLEAR 10	104009 P 5
BOHEAT ON SAMPLE	LIMIT FROM THE LPI SYS. M FAILS AT OCONEE 30	107907 P125
BOBLOWDOWN CLOSING FLOW INDICATION SENSING	LIMIT ISOLATION VALVE FAILED TO CLOSE AT YANKEE ROME	104071 P 80
BOPRIMARY MAKEUP PUMP ORATE	LIMIT LEAKS AT YANKEE ROME	106891 P231
	LIMIT LEAKS AT ARKANSAS NUCLEAR 10	093576 P 1

[illegible]

[illegible]

BUCKET LEAK RATE TESTS FAIL TO	MEET LIMIT AT PRINCE ISLAND 10	102990	P146
SMALLER TO	MEET RADIATION EXPOSURE RECORD REQUIREMENTS AT TONGUE AHEAD	104211	P229
SMALL PUMP METERS FAIL TO	MEET SPECIFICATIONS AT JAMES-BESSE	101700	P 51
SMALL SYSTEM FLOW DISTRIBUTION FAILS TO	MEET SPECS AT MAIN TANKS	104000	P 00
CONTAINMENT ISOLATION	MEMBRANE BARRIER DEFICIENCY AT CSD 10	102109	P 30
	METEOROLOGICAL INSTRUMENTS INOPERABLE AT CSD 10	100000	P 35
ADDITIONAL INFORMATION ON LEAK RATE FROM	METER AT RANGU SEC20	103051	P160
OPERATION CONTAINMENT BUILDING RELOCATING VAN SPACING AT	METER SPIRES AT RANGU SEC20	107613	P167
DRUM INSTALLATION AND INSPECTION ERRORS AT	NEEDLE 1 AND 20	000673	P 07
SMALL REPORT ON RELOCATING VAN SPACING DEFICIENCY AT	NEEDLE 20	000940	P 00
HYDRAULIC SMALL SUPPRESSOR FAILS AT THREE	NEEDLE ISLAND 10	101540	P 00
BUMPLAND RELEASE OF RADIOACTIVE MATERIAL AT THREE	NEEDLE ISLAND 10	003007	P200
BRISTLE CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT THREE	NEEDLE ISLAND 10	003500	P100
SMALL SUPPLY FOUND IN TANK AT THREE	NEEDLE ISLAND 10	103073	P200
SMALL PUMP FAILS TO START AT THREE	NEEDLE ISLAND 10	000971	P200
CONTINUAL RUN DRIVE BREAKER FAILS TO TRIP AT THREE	NEEDLE ISLAND 10	000930	P100
HYDRAULIC SMALL SUPPRESSOR INOPERABLE AT THREE	NEEDLE ISLAND 10	102527	P205
DEFECTIVE HANDBOOK FEATURE SPHERICAL NUT LOOSE AT THREE	NEEDLE ISLAND 10	102130	P205
DECAY HEAT PUMP SUCTION VALVE FAILS TO CLOSE AT THREE	NEEDLE ISLAND 10	003000	P200
DEFLECTIVE CHLORINE CONCENTRATION IN DISCHARGE AT THREE	NEEDLE ISLAND 10	000901	P100
DEFLECTIVE RELEASE OF AROMATIC RADIOACTIVITY AT THREE	NEEDLE ISLAND 10	000900	P201
DEFLECTIVE HYDRAULIC SMALL SUPPRESSOR INOPERABLE AT THREE	NEEDLE ISLAND 10	100544	P232
DECAY HEAT RIVER WATER PUMP SHUT FAILS AT THREE	NEEDLE ISLAND 10	101555	P200
DEFLECTIVE WIRING FOUND IN MOTOR CONTROL CENTER AT THREE	NEEDLE ISLAND 10	103072	P200
CONTAINMENT INTEGRITY VIOLATED IN ACCESS MARCH AT THREE	NEEDLE ISLAND 10	103003	P202
DEFLECTIVE CRITICALLY REACHED AT 505 F AT THREE	NEEDLE ISLAND 10	100713	P100
DEFLECTIVE LUNING RIVER WATER PUMP FAILS TO START AT THREE	NEEDLE ISLAND 10	102571	P200
DEFLECTIVE IN RIVER WATER U. CHANGE EXCEEDS LIMITS AT THREE	NEEDLE ISLAND 10	000000	P200
SMALL FLOOD TANK SAMP. LINE FAILS TO CLOSE AT THREE	NEEDLE ISLAND 10	000070	P200
BUMPLAND RELEASE OF RADIOACTIVE MATERIAL AT THREE	NEEDLE ISLAND 10	100300	P211
BUMPLAND RELEASE OF RADIOACTIVE GAS OCCURS AT THREE	NEEDLE ISLAND 10	100310	P210
SET POINT DRIFT IN PRESSURE TRANSDUCER AT THREE	NEEDLE ISLAND 10	103000	P200
DEFLECTIVE SUIES IN EFFLUENT EXCEEDS LIMIT AT THREE	NEEDLE ISLAND 10	103007	P207
DEFLECTIVE SWITCH IN VALVE CONTROL CIRCUIT FAILS AT THREE	NEEDLE ISLAND 10	104701	P200
DEFLECTIVE TOWER DISCHARGE COOLED EXCESSIVELY AT THREE	NEEDLE ISLAND 10	105720	P211
SET POINT DRIFT IN TEMPERATURE DISTABLE AT THREE	NEEDLE ISLAND 10	105722	P211
DEFLECTIVE MAKE UP VALVE FAILS TO CLOSE AT THREE	NEEDLE ISLAND 10	103000	P200
DEFLECTIVE ULTRAVIOLET DETECTOR INSTALLED AT THREE	NEEDLE ISLAND 10	102000	P212
BUMPLAND RELEASE OF RADIOACTIVE MATERIAL AT THREE	NEEDLE ISLAND 10	100500	P212
MAIN STEAM VALVES NOT SEISMIC QUALIFIED AT THREE	NEEDLE ISLAND 10	100067	P214
SET POINT DRIFT IN PRESSURE TRANSDUCERS AT THREE	NEEDLE ISLAND 10	100017	P213
DEFLECTIVE ACID MIX TANK OUTLET LINE BLOCKED AT THREE	NEEDLE ISLAND 10	100000	P230
OVERHAUL PERFORMED WHEN NOT CONTROLLED ADEQUATELY AT THREE	NEEDLE ISLAND 10	107000	P214
DEFLECTIVE IN EFFLUENT EXCEEDS CONTROL VALUE AT THREE	NEEDLE ISLAND 10	103000	P207
DEFLECTIVE COOLING OF THE COOLING TOWER DISCHARGE AT THREE	NEEDLE ISLAND 10	105273	P210
FREQUENCY RELAY FOR DIESEL GENERATOR FAILS AT THREE	NEEDLE ISLAND 10	105526	P210
BUMPLAND RELEASE OF RADIOACTIVE MATERIAL OCCURS AT THREE	NEEDLE ISLAND 10	100050	P209
DEFLECTIVE RELEASE OF RADIOACTIVE MATERIAL IN RAMP OF DIES AT THREE	NEEDLE ISLAND 10	100050	P212
DEFLECTIVE NOT TAKEN DURING WASTE TANK RELEASE AT THREE	NEEDLE ISLAND 10	100050	P210
BUMPLAND RELEASE OF RADIOACTIVE MATERIAL OCCURS AT THREE	NEEDLE ISLAND 10	100050	P210
BUMPLAND RELEASE OF GASEOUS RADIOACTIVITY AT THREE	NEEDLE ISLAND 10	100200	P210
BUMPLAND RELEASE OF RADIOACTIVE MATERIAL AT THREE	NEEDLE ISLAND 10	100200	P210
DEFLECTIVE RELEASES OF RADIOACTIVE MATERIAL AT THREE	NEEDLE ISLAND 10	100230	P217
DEFLECTIVE LEVEL IN EFFLUENT EXCEEDS CONTROL VALUE AT THREE	NEEDLE ISLAND 10	107525	P215
SET POINT DRIFT IN PRESSURE SWITCH AT THREE	NEEDLE ISLAND 10	100205	P210
DEFLECTIVE ADJUS INOPERABLE AT THREE	NEEDLE ISLAND 10	100250	P210
OVERVOLTAGE RELAY CONTACTS OF DIESEL GENERATOR STICK AT THREE	NEEDLE ISLAND 10	100261	P217
ADJUS USED PRIOR TO CHECKING DOCUMENTATION AT THREE	NEEDLE ISLAND 10	100235	P217
BUMPLAND RELEASE OF RADIOACTIVE GAS AT THREE	NEEDLE ISLAND 10	100261	P217
STEAM GENERATOR SAMPLE LINE VALVE FOUND INOPERABLE AT THREE	NEEDLE ISLAND 10	0 100070	P210
CURVE FLOOD TANK LEVEL FOUND TO BE LESS THAN LIMITS AT THREE	NEEDLE ISLAND 10	0 100517	P213
FOUND AT SLIDE BEARING PLATE FOR MAIN STEAM LINE AT THREE	NEEDLE ISLAND 10	0000	P200
POINT DRIFT IN REACTOR COOLANT PRESSURE SWITCHES AT THREE	NEEDLE ISLAND 10	0000	P200
HANDBOOK ISOLATION VALVES IN AIR LINE FOUND CLOSED AT THREE	NEEDLE ISLAND 10	0000	P213
ON THE EXHAUST MANIFOLD OF THE DIESEL GENERATOR AT THREE	NEEDLE ISLAND 10	0000	P200
DEFLECTIVE CONCENTRATION IN RIVER EXCEEDS LIMIT AT THREE	NEEDLE ISLAND 10	0000	P200
DEFLECTIVE IN SAMPLE EXCEEDS CONTROL LEVEL AT THREE	NEEDLE ISLAND 10	0000	P210
DEFICIENCY IN CONTROL AND DRIVE BREAKER CABINETS AT THREE	NEEDLE ISLAND 10	0000	P210
WELD IN MAKE-UP PUMP SUCTION VENT LINE LEAKS AT THREE	NEEDLE ISLAND 10	0000	P210
WELD JOINTS LEAK IN VENT LINE OF MAKE-UP PUMPS AT THREE	NEEDLE ISLAND 10	0000	P210
DEFLECTIVE CONCENTRATION OF ACID SOLUTION NOT OPERABLE AT THREE	NEEDLE ISLAND 10	0000	P215
AND PROGRAM VERIFICATION INADEQUATELY IMPLEMENTED AT THREE	NEEDLE ISLAND 10	0000	P215
AND NOT WELL MAINTAINED WHEN MISALIGNED AT THREE	NEEDLE ISLAND 10	0000	P202
SERVICES RIVER WATER PUMP VALVE FAILS TO CLOSE AT THREE	NEEDLE ISLAND 10	0000	P200
BUILDING PURGE ISOLATION VALVE LEAKS EXCESSIVELY AT THREE	NEEDLE ISLAND 10	0000	P207
BUILDING PURGE SUPPLY VALVE FAILS TO FULLY CLOSE AT THREE	NEEDLE ISLAND 10	0000	P211
PURGE INCREASED ABOVE POWER LEVEL CUT OFF TOC SCUM AT THREE	NEEDLE ISLAND 10	0000	P207
BUILDING EMERGENCY COOLER SHUT VALVE FAILS AT THREE	NEEDLE ISLAND 10	0000	P202
CONCENTRATION IN RIVER WATER EXCEEDS LIMITS AT THREE	NEEDLE ISLAND 10	0000	P205
LEVEL OF RADIATION IN EFFLUENT EXCEEDS CONTROL AT THREE	NEEDLE ISLAND 10	0000	P203
FAILS TO CARRY WASTEWATER INTO HIGH RADIATION AREA AT THREE	NEEDLE ISLAND 10	0000	P215
RIVER WATER SAMPLE INDICATED RESULTS EXCEED LIMIT AT THREE	NEEDLE ISLAND 10	0000	P200
AND WIRING PROBLEMS FOUND IN CONTROL CENTERS AT THREE	NEEDLE ISLAND 10	0000	P203
SIMILAR CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT THREE	NEEDLE ISLAND 10	0000	P200
FATAL CHLORINE CONCENTRATION IN PLANT DISCHARGE AT THREE	NEEDLE ISLAND 10	0000	P200
SMALL SUPPRESSOR FOUND TO BE DISCONNECTED AT THREE	NEEDLE ISLAND 10	0000	P200
	HYDRAULIC	100000	P214

DIFFERENTIAL ACROSS THE PLANT EXCEEDS LIMIT AT THREE	MILE ISLAND 10	TEMPERATURE	136220	P216
OF EMERGENCY SHUTDOWN CALLING WATER LIMIT AT THREE	MILE ISLAND 10	AVAILABILITY	106305	P212
IN TIGHTENED EFFLUENT SAMPLE LIMIT AT THREE	MILE ISLAND 10	CONCENTRATION	130230	P215
ON RADIOACTIVE GAS BUILDUP IN QUALITY BUILDING AT THREE	MILE ISLAND 10	CONCENTRATION	130237	P216
EMERGENCY COOLING RIVER WATER PUMP FAILS TO START AT THREE	MILE ISLAND 10	OFF-LOAD-UP REPORT	132607	P225
ADDITIONAL INFORMATION ON DEVIATION CRANE VALVES AT THREE	MILE ISLAND 20	REACTOR BUILDING	132607	P225
REACTOR BUILDING SPRAY PUMP MOTOR INSPECTIONS AT THREE	MILE ISLAND 20		132616	P219
SMOKE FOUND IN FUEL HANDLING BUILDING WALL AT THREE	MILE ISLAND 20		132639	P220
ON CONCRETE CYLINDER TEST STARTING (SUPPLEMENT) AT THREE	MILE ISLAND 20		132640	P219
CRANE ADJUSTING AND PULLING DEFICIENCY AT THREE	MILE ISLAND 20		132640	P220
ALARM INDICATION FOUND IN AC PUMP MOTORS AND STOPS AT THREE	MILE ISLAND 20	LINEAR	132640	P220
NO DRIVE SYSTEM AC DRUMS CABINETS DEFICIENCY AT THREE	MILE ISLAND 20	CONTROL	132640	P219
OVERLOADING CABLE THAT PAINTING FOUND DEFICIENCY AT THREE	MILE ISLAND 20	REACTOR	132640	P220
CONCRETE BLOCK WALLS NOT SEISMICALLY QUALIFIED AT THREE	MILE ISLAND 20	INTERIOR	132640	P220
OFFICIAL REPORT ON POTENTIAL DAMAGE TO CONFINEMENT TENDONS AT	MILLSTONE 20		102790	P 89
SERVICE WATER HEADERS DEVELOPS A PPM MILE LEAK AT	MILLSTONE 20		106156	P 91
DIESEL GENERATOR FLOW CIRCUIT DEFICIENCY AT	MILLSTONE 20		102160	P 90
DISPERSED PUMP WATER LEVEL LOW DURING CORE ALTERATIONS AT	MILLSTONE 20		135506	P 90
ADDITIONAL CONTACTS OF MOTOR CONTROL CENTERS STICK AT	MILLSTONE 20		103673	P 90
RELAYS SAFETY/STATUS EQUIPMENT PANEL FAIL AT	MILLSTONE 20		102891	P 89
ADDITIONAL RELAYS DISCHARGE PUMP STOP AT	MILLSTONE 20		101701	P 89
RELAYS IN SAFETY/STATUS EQUIPMENT PANEL FAIL AT	MILLSTONE 20		103606	P 90
DIESEL GENERATOR SERVICE WATER HEAT EXCHANGER LEAKS AT	MILLSTONE 20		106355	P 91
RELAYS INSTALLED ON CONFINEMENT LINE AT	MILLSTONE 20		103049	P 90
CONCENTRATION OF MONITORING INCREASES IN LOUVERS AT	MILLSTONE 20		102893	P 91
OPERATIONAL PRESSURE SWITCHES SET NON-CONSERVATIVELY AT	MILLSTONE 20		106199	P 92
UPDATE REPORT ON OVERPOWER TRIP SET POINT HANGING UP AT	MILLSTONE 20		107622	P 95
DIESEL GENERATOR FAILS TO START AT	MILLSTONE 20		139017	P 96
RELAYS TESTED USING HIGH FLOW RATES AT	MILLSTONE 20		106644	P 93
CONCENTRATION OF MONITORING IN MONITORS EXCEEDS LIMIT AT	MILLSTONE 20		109253	P 98
AVAILABLE OVERPOWER TRIP SET POINT SHIFT WITH POWER AT	MILLSTONE 20		106645	P 92
SET POINT SHIFT IN STEAM GENERATOR PRESSURE CHANNELS AT	MILLSTONE 20		108051	P 97
SET POINT SHIFT IN CONFINEMENT PRESSURE TRANSMITTER AT	MILLSTONE 20		108023	P 96
ADDITIONAL FREQUENCY PUMP GOVERNOR FAILS TO RESPOND AT	MILLSTONE 20		106643	P 96
DISPERSED ACTUATION OF ALL REAS SIGNALS AT	MILLSTONE 20		106637	P 93
OVERSIZED GATE IN REACTOR COOLANT EXCEEDS LIMIT AT	MILLSTONE 20		106641	P 96
DIESEL FUEL OIL SAMPLE LOST AT	MILLSTONE 20		108867	P 97
OTRAC TIME DELAY SETTING PUMP TO BE EXCEEDED AT	MILLSTONE 20		139254	P 96
SERVICE WATER PIPING NOT SEISMICALLY QUALIFIED AT	MILLSTONE 20		106642	P 96
OVERNIGHT HOLD ELONG LEAKS FOUND IN INSTRUMENT LINES AT	MILLSTONE 20		106076	P 91
AND LONGING PUMP FLOW METER AT	MILLSTONE 20		106352	P 91
DISCHARGE PUMP FAULTS AT	MILLSTONE 20		106116	P 92
SET POINT SHIFT IN FLOW DISTABLE AT	MILLSTONE 20		108010	P 96
OVERSIZED ORBIT IN PRESSURIZER PRESSURE CHANNEL AT	MILLSTONE 20		108049	P 98
CONFINEMENT PUMP SUPPLY VALVE FAILS TO CLOSE AT	MILLSTONE 20		108040	P 97
QUARTER PUMP IN OFF-GAS PIPE AT	MILLSTONE 20		108050	P 97
BOOTH CONTAINMENT SPRAY HEADERS FOUND INOPERABLE AT	MILLSTONE 20		106956	P 96
COMPENSATE STORAGE TANK LEVEL DECREASED BELOW LIMIT AT	MILLSTONE 20		108019	P 95
BOOTH CONTAINMENT AIR LOCK DOORS OPENED AUTOMATICALLY AT	MILLSTONE 20		106111	P 92
BUILD ON INSTRUMENT LINE LEAKS AT	MILLSTONE 20		106636	P 93
AIR OPERATED VALVE ACCUMULATOR NOT SEISMICALLY QUALIFIED AT	MILLSTONE 20		106636	P 93
PRESSURE SAFETY INJECTION PUMPS DO NOT ROTATE FREELY AT	MILLSTONE 20		101553	P 88
INFORMATION ON DC HEAT EXCHANGER INLET NOZZLE FAILURE AT	MILLSTONE 20	SMITH	104938	P 90
TESTS NOT PERFORMED WHEN RCS TEMPERATURE DECREASED AT	MILLSTONE 20	ADDITIONAL	128086	P 95
CONTAINMENT ISOLATION VALVES NOT PERFORMED WHEN REQUIRED AT	MILLSTONE 20	OUT CHANNEL	106353	P 91
INSTALLED ON HIGH RANGE NUCLEAR INSTRUMENTATION AT	MILLSTONE 20	TESTING OF	106356	P 91
NOTICE OF PROPOSED IMPOSITION OF CIVIL PENALTIES AT	MILLSTONE 20	CABLE SHIELDING	106009	P 91
OPEN HOLE LEAK IN	MILLSTONE 20		106075	P 90
MILLSTONE 20			106076	P 95
CONFINEMENT AND NOT DECLARED INOPERABLE WHEN			130084	P202
OFFICIAL REPORT ON INTAKE COOLING WATER SYSTEM			100900	P176
UNPLANNED RELEASE OF			102159	P 21
DEUTERIDE PIV			103600	P163
DEUTERIDE ACID			137600	P214
DEUTERIDE STARTER FAILS IN THE RUN			103090	P 30
DIESEL GENERATOR EXHAUST VALVE			132271	P170
OCONEE 10			104986	P105
REACTOR BUILDING SPRAY PUMP MOTOR			102614	P219
OFF-LOAD-UP REPORT ON			102599	P239
SAFETY INJECTION ACTUATION SYSTEM LOGIC			103552	P 17
SAFETY INJECTION ACTUATION SYSTEM			103257	P 16
SAFETY INJECTION ACTUATION SYSTEM LOGIC			103625	P 17
OFFICIAL REPORT ON EFFECT OF CHANGE IN			100277	P173
ORTH ANNA 1 AND 20			130633	P 99
BOOTH CONTAINMENT AIR LOCK DOORS OPENED			104111	P 92
NOTICE OF PROPOSED CIVIL			105546	P 61
CONTROL AND DEVIATION			106419	P 68
LOW LEVEL RADIOACTIVE RELEASE WITHOUT IN-LINE			099715	P160
CONTAINMENT RADIATION			099197	P 15
CONTAINMENT RADIATION AREA			093476	P 16
CONTAINMENT RADIATION			093475	P 17
CONTAINMENT RADIATION			104023	P 25
STACK PARTICULATE			103627	P 58
STACK PARTICULATE RADIATION			101459	P 55
SERVICE WATER RADIATION			093618	P180
PROCESS RADIATION			103163	P103
LIQUID EFFLUENT CONTROL			131647	P 55

	OFFICIAL REPORT ON LACK OF	NOT ON TWO CONTAINMENT PENETRATIONS AT ST. LUCIE ISLAND	100821 P179
	DIRECTOR'S OFFICE	NORMALIZING TANK DISCHARGE ON LOW AT KENAUWEE*	102333 P 70
	DECREASED AT HILLSTONE 20	NEUTRON SHIELD TANK DEFECTS AT NORTH ANNA 30	100531 P100
	ARKANSAS NUCLEAR 10	NO CHANNEL TESTS NOT PERFORMED WHEN RCS TEMPERATURE	100006 P 95
		NITRATE CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT	100477 P 6
		NO CHARGING PUMP FLOW NOTED AT HILLSTONE 20	126352 P 91
	BUG METER INDICATES	NO RESPONSE TO GOVERNOR CONTROL SWITCH AT GINMA*	100519 P 60
JANUARY 10	DIESEL GENERATOR	NO 1 TRIPS FROM HIGH COOLING WATER TEMPERATURE AT SAN	100654 P172
JANUARY 10	DIESEL GENERATOR	NO 2 TRIPS FROM HIGH COOLING WATER TEMPERATURE AT SAN	100655 P172
		NUCLEON GAS RELEASE RATE EXCEEDS LIMIT AT IZOM 10	100572 P236
	RELEASE OF	NURSE CASES EXCEEDS LIMITS AT CALVERT CLIFFS 10	100615 P 27
AT RANCHU SECOP		NON-CONSERVATIVE SET POINTS IN PART OF THE TRIP ENVELOPE	100366 P199
	OPPRESSURIZER PRESSURE SWITCHES SEE	NON-CONSERVATIVELY AT HILLSTONE 20	100599 P 92
	UNAUTHORIZED RELEASE OF	NON-RADIOLOGICAL WASTE AT KENAUWEE*	100067 P 70
		NORMAL CHARGING LINE STOP VALVE FAILS TO CLOSE AT SURRY 10	100079 P109
	PUMP FOUND NOT ALIGNED FOR	NORMAL SERVICE AT PALISADES*	100725 P130
	REACTOR BUILDING	NORMAL SUMP ISOLATION VALVE FAILS TO CLOSE AT OCEOKEE 20	100399 P113
DEFICIENTLY FOUND IN SEPARATION OF SAFETY RELATED CABLES AT		NORTH ANNA 1 AND 20	100600 P 90
MOISTURE AND CHEMICAL CONTAMINATE THE RV HEAD ASSEMBLY AT		NORTH ANNA 1 AND 20	100633 P 90
ELECTRICAL TERMINATION DEFICIENCY FOUND AT		NORTH ANNA 1 AND 20	100635 P 90
INSTALLING OF STAINLESS STEEL PIPE ASSEMBLIES AT		NORTH ANNA 1 AND 20	100016 P 90
IF VIOLATION IN REPAIRING AND EVALUATING A DEFICIENCY AT		NORTH ANNA 1 AND 20	100079 P 90
SEISMIC DEFICIENCIES IN CERTAIN STRUCTURES AT		NORTH ANNA 3RD AND 40	100079 P 90
STEEL PURCHASED WITH INCORRECT OR REQUIREMENTS AT		NORTH ANNA 30	100430 P 99
OLEUM COLUMNS FOUND TO BE DEFICIENT AT		NORTH ANNA 30	100440 P100
DECOMPOSITIONS OF NEUTRON SHIELD TANK DEFECTS AT		NORTH ANNA 30	100511 P100
WELDS ON POLAR PLANE ASSEMBLY FOUND DEFICIENT AT		NORTH ANNA 30	100631 P100
	PUMP FOUND	NOT ALIGNED FOR NORMAL SERVICE AT PALISADES*	100725 P130
TEMPORARY CHANGE SHEET FOR TEST		NOT APPROVED IN TIME AT COOK 10	100549 P 39
SMALL ZERO POWER EJECTED ROD NORTH		NOT CALCULATED AT OCEOKEE 10	099703 P101
HYDROGEN MONITORING SYSTEM		NOT CALCULATED ON SCHEDULE AT COOK 10	100779 P 46
OPARTICULATE FILTERS		NOT COLLECTED DURING TWO WEEKS AT SAN ONOFRE 10	100550 P172
CONTAINMENT SPRAY LOGIC		NOT COMPLETELY TESTED AT INDIAN POINT 20	100493 P 72
OVERFLOW PERFORMED WORK		NOT CONTROLLED ADEQUATELY AT THREE HILE ISLAND 10	100309 P207
OVERFLOW ROD		NOT DECIDED INDEPENDENTLY WHEN MISALIGNED AT THREE HILE	100615 P 27
INDIVIDUALS OVERLOADED AND AIR FASH TABLING		NOT DOCUMENTED AT GINMA*	100655 P 65
MOTION BUILDING SPRAY SYSTEM MAY		NOT DRAM DOWN UNIFORMITY AT ARKANSAS NUCLEAR 10	100369 P 9
SEISMIC RESTRAINTS		NOT INSTALLED AS DESIGNED AT CONNECTICUT TANNERY*	100420 P 32
ATMOSPHERIC STEAM DUMP VALVE ENCLOSURE		NOT INSTALLED AT CALVERT CLIFFS 10	100370 P 26
CONTAINMENT PENETRATION FLANGE		NOT INSTALLED AT PRAIRIE ISLAND 10	100529 P146
BLOCK AND HOLD CARDS		NOT INSTALLED AT PRAIRIE ISLAND 20	100716 P153
OVERHEAT MEASUREMENTS DURING COLD STARTUP		NOT MADE AT PALISADES*	100366 P129
BODY CELLS OF VOLTAGE ACROSS ZENER DIODES		NOT MADE AT RANCHU SECOP	100467 P190
BRASSER OVERLAP BETWEEN CONTROL AND GROUPS		NOT MAINTAINED AT OCEOKEE 20	099622 P109
CHEMICAL DEMAND		NOT MEASURED AT SAN ONOFRE 10	100551 P171
STEAM GENERATOR ON DOWN ACTIVITY		NOT MONITORED AT SURRY 10	100076 P100
STOW PAN COLLIER-CARBONAL FILTER UNITS		NOT OPERABLE AT INDIAN POINT 20	100590 P 60
SOURCE OF CONCENTRATED BICACID SOLUTION		NOT OPERABLE AT THREE HILE ISLAND 10	100702 P215
FLOW INSTRUMENTATION		NOT OPERATING AT RANCHU SECOP	100079 P136
OSERVEILLANCE TESTING		NOT PERFORMED AS REQUIRED AT COOK 10	100463 P 41
REQUIRED SURVEILLANCE TESTS		NOT PERFORMED AT COOK 10	100063 P 35
TESTING OF LIQUID LEVEL INSTRUMENTS		NOT PERFORMED AT KENAUWEE*	100012 P 91

OTHER SURVEILLANCE CHECKS NOT PERFORMED AT MAIN YANKEE 133344 P 84
 REQUIRED ISOTOPIC ANALYSES NOT PERFORMED AT RANCHO SEC 10 104492 P 82
 MONTHLY CHECK UP 51 INITIATION SWITCHES NOT PERFORMED AT YANKEE HONOL 133347 P 83
 DECONTAMINATION ANALYSES NOT PERFORMED DURING COMMISSIONING AT COOK 10 133657 P 80
 BPS MONTHLY TESTING NOT PERFORMED IN PROPER TIME INTERVAL AT YANKEE YANKEE 136376 P 86
 REQUIRED SURVEILLANCE TESTS NOT PERFORMED ON SCHEDULE AT COOK 10 136465 P 89
 TESTING OF REACTOR TRIP BREAKERS NOT PERFORMED ON TIME AT COOK 10 136785 P 66
 BATTERY BATTERY TESTING NOT PERFORMED ON TIME AT PINE BEACH 1 AND 20 203248 P 67
 OCS LEAKAGE EVALUATION NOT PERFORMED JUNE MAY AT PRAIRIE ISLAND 20 132115 P 51
 ONE CHANNEL TESTS NOT PERFORMED WHEN RCS TEMPERATURE DECREASED AT HILLSTONE 2 130706 P 95
 TESTING OF CONTAINMENT ISOLATION VALVES NOT PERFORMED WHEN REQUIRED AT HILLSTONE 20 136353 P 91
 FAILED PRESSURIZER LEVEL CHANNEL NOT PLACED IN TRIPPED POSITION AT COOK 10 135346 P 66
 CONTAINMENT SPRAY VALVE NOT PROPERLY ALIGNED AT COOK 10 137092 P 251
 CONTAINMENT INSTRUMENT AIR SYSTEM NOT PROPERLY ISOLATED AT SURRY 10 132866 P 181
 REMEDIABLE BUILDING SPRAY TRASH NOT PROVIDED AS REQUIRED AT COOK 20 105283 P 116
 REMEDIABLE EMERGENCY POWER SOURCE NOT PROVIDED AT COOK 10 136226 P 136
 PROPER OVERLAP BETWEEN CATHODIC ROD GROUPS NOT PROVIDED AT COOK 10 133391 P 121
 REACTOR BUILDING SPRAY TRASH NOT PROVIDED WHEN REQUIRED AT COOK 20 209702 P 109
 STRAIN GENERATION OR VIBRATION ACTIVITY NOT REQUESTED CONTINUOUSLY AT FT. CALHOUN 132921 P 61
 REACTOR BUILDING PUBLIC SERVICE CONDENSER TEMPERATURE NOT REQUESTED ON TIME DURING LOAD CHANGE AT 132116 P 70
 CONTAINMENT DOOR CASSET LEAKAGE NOT REPORTED AT COOK 10 104406 P 61
 HIGH PRESSURE SAFETY INJECTION PUMPS DO NOT OPERATE FREELY AT HILLSTONE 20 131553 P 80
 DIESEL PUMP JEL NOT SAMPLED ON SCHEDULE AT COOK 10 209115 P 33
 MAIN STEAM VALVES NOT SEISMICALLY QUALIFIED AT THREE MILE ISLAND 10 136617 P 213
 SERVICE WATER PIPING NOT SEISMICALLY QUALIFIED AT HILLSTONE 20 136642 P 96
 AIR OPERATED VALVE ACCUMULATOR NOT SEISMICALLY QUALIFIED AT HILLSTONE 20 136636 P 93
 INTERIOR CONCRETE BLOCK WALLS NOT SEISMICALLY QUALIFIED AT THREE MILE ISLAND 20 136365 P 220
 OCEAN FLOOD DISCHARGE VALVES NOT TAGGED WHEN AT COOK 20 203621 P 109
 OCEAN AND DRINKING WATER SAMPLES NOT TAKEN AT SAN ONOFRE 134045 P 118
 CONTAMINANT GRAB SAMPLES NOT TAKEN AT COOK 10 139281 P 260
 CONTAMINANT GRAB SAMPLES NOT TAKEN AT COOK 20 109280 P 253
 SAMPLE NOT TAKEN DURING WASTE TANK RELEASE AT THREE MILE ISLAND 10 136679 P 209
 DIESEL FREGGER NOT TESTED AS REQUIRED AT COOK 10 135732 P 65
 UNIT 2 AUXILIARY FEEDWATER PUMP NOT TESTED AS REQUIRED AT COOK 10 136636 P 66
 REACTOR AIR FILTER TRASH NOT TESTED AT COOK 10 133087 P 35
 CONTAMINANT SUMP ISOLATION VALVES NOT TESTED AT YANKEE HONOL 133663 P 60
 RADIATION MONITOR NOT TESTED ON SCHEDULE AT COOK 10 102119 P 37
 REACTOR PROTECTION LOGIC CHANNEL NOT TESTED ON SCHEDULE AT INDIAN POINT 20 135041 P 76
 CONTAMINANT SPRAY PUMP NOT TESTED ON SCHEDULE AT INDIAN POINT 20 136043 P 73
 DECONTAMINANT PUMP VALVES NOT TESTED ON TIME AT COOK 20 136045 P 251
 CONTAMINANT PRESSURE CHANNELS NOT TESTED PROPERLY AT COOK 10 135515 P 65
 DIESEL GENERATOR NOT TESTED WHEN REQUIRED AT COOK 10 132006 P 35
 DIESEL MATERIAL NOT VERIFIED AT CALVERT CLIFFS 1 AND 20 132073 P 19
 AND CHARGING PUMP FLOW NOT VERIFIED AT HILLSTONE 10 136352 P 91
 NOTICE OF PROPOSED CIVIL PENALTIES AT INDIAN 135548 P 67
 NOTICE OF PROPOSED IMPOSITION OF CIVIL PENALTIES AT 104309 P 89
 NOTICE OF PROPOSED IMPOSITION OF CIVIL PENALTIES AT YANKEE 203665 P 83
 NOTICE OF PROPOSED IMPOSITION OF CIVIL PENALTIES AT SURRY 203666 P 87
 NOTICE OF VIOLATION CONCERNING COMPLIANCE TO PROCEEDINGS 136238 P 260
 NOTICE OF VIOLATION IN REPORTING AND EVALUATING A 136079 P 99
 NOTICE OF VIOLATION ON QUALITY ASSURANCE PROGRAM AT DAVIS- 136720 P 52
 DIESEL CRACKS AT YANKEE HONOL 104995 P 232
 DIESEL FAILURE AT HILLSTONE 20 136988 P 90
 DIESEL INDICATIONS AT YANKEE HONOL 1 AND 20 099376 P 52
 DIESEL BLOCKED AT RANCHO SEC 20 136222 P 163
 DIESEL ON HEAT EXCHANGERS OVERSTRESSED AT CALVERT CLIFFS 1 205791 P 116
 DIESEL REQUESTS ANALYSIS OF SECONDARY SYSTEM FLUID FLOW 136249 P 32
 DIESEL REVIEW OF HSI'S AT YANKEE HONOL 104370 P 231
 DIESEL AXIAL OFFSET OUT OF TOLERANCE BAND AT SURRY 10 131729 P 102
 DIESEL INSTRUMENT FAILS AT CALVERT CLIFFS 10 103132 P 22
 DIESEL INSTRUMENT FAILS AT CALVERT CLIFFS 10 104398 P 25
 DIESEL INSTRUMENT FAILS AT CALVERT CLIFFS 10 104134 P 22
 DIESEL INSTRUMENTATION AT HILLSTONE 20 136356 P 91
 DIESEL INSTRUMENTATION CHANNEL FAILS AT INDIAN POINT 10 137304 P 60
 DIESEL INSTRUMENTATION CHANNEL FAILS AT PRAIRIE ISLAND 10 105710 P 167
 DIESEL INSTRUMENTATION FAILS AT CALVERT CLIFFS 10 133913 P 20
 DIESEL INSTRUMENTATION FAILS AT CALVERT CLIFFS 10 137636 P 29
 DIESEL INSTRUMENTATION FAILS AT CALVERT CLIFFS 10 133691 P 26
 DIESEL INSTRUMENTATION FAILS AT CALVERT CLIFFS 10 104633 P 19
 DIESEL INSTRUMENTATION FAILS AT CALVERT CLIFFS 10 203239 P 35
 DIESEL INSTRUMENTATION FAILS AT CALVERT CLIFFS 10 100020 P 15
 DIESEL INSTRUMENTATION IMPROVABLE AT COOK 10 133693 P 122
 DIESEL INSTRUMENTATION TRIP SET POINTS DRIFT AT PRAIRIE 135719 P 167
 DIESEL INSTRUMENTATION HIGH RANGE CHANNEL FAILS AT 203624 P 18
 DIESEL POWER RANGE CHANNEL LOST TEMPORARILY AT PINE 136331 P 130
 DIESEL SERVICES RIVER WATER PUMP VALVE FAIL TO CLOSE AT 136600 P 209
 DIESEL 10 105940 P 12
 DIESEL 10 104915 P 10
 DIESEL 10 137004 P 11
 DIESEL 10 130375 P 11
 DIESEL 10 135157 P 9
 DIESEL 10 136194 P 6
 DIESEL 10 132011 P 1
 DIESEL 10 136511 P 6
 DIESEL 10 136821 P 6
 DIESEL 10 136552 P 6
 DIESEL 10 203574 P 1
 DIESEL 10 203574 P 1

FISH IMPIGEMENT ON INTAKE SCREENS	AT ARKANSAS	MUSCLE EAR 10		093573	P 1	
OBSERVE WATER VALVES FAIL TO OPEN	AT ARKANSAS	MUSCLE EAR 10		093577	P 2	
PRIMARY MAKEUP PUMP MAIN LINE LEAKS	AT ARKANSAS	MUSCLE EAR 10		093576	P 1	
FISH IMPIGMENT ON INTAKE SCREENS	AT ARKANSAS	MUSCLE EAR 10		094714	P 2	
FISH IMPIGMENT ON INTAKE SCREEN	AT ARKANSAS	MUSCLE EAR 10		093695	P 2	
FISH KILL ON INTAKE SCREENS EXCEEDS LIMIT	AT ARKANSAS	MUSCLE EAR 10		100273	P 3	
FISH KILL ON INTAKE SCREENS EXCEEDS LIMIT	AT ARKANSAS	MUSCLE EAR 10		100272	P 2	
FISH IMPIGEMENT ON INTAKE SCREENS	AT ARKANSAS	MUSCLE EAR 10		120616	P 3	
FISH IMPIGEMENT ON INTAKE SCREENS	AT ARKANSAS	MUSCLE EAR 10		100882	P 3	
AMMONIA CONCENTRATION IN EFFLUENT EXCEEDS LIMIT	AT ARKANSAS	MUSCLE EAR 10		0106375	P 0	
ADDITIONAL DATA ON FAILED INSTANTANEOUS TIME MEAS	AT ARKANSAS	MUSCLE EAR 10		0106657	P 0	
AMMONIA CONCENTRATION IN EFFLUENT EXCEEDS LIMIT	AT ARKANSAS	MUSCLE EAR 10		0106568	P 0	
UREA CONCENTRATION USE COMMON FLOTATION PLANTS	AT ARKANSAS	MUSCLE EAR 10		0106520	P 12	
SERIAL CONCENTRATION IN EFFLUENT EXCEEDS LIMIT	AT ARKANSAS	MUSCLE EAR 10		010977	P 0	
LEAK IN REACTION CHAMBER PUMP SEAL VENT VALVE	AT ARKANSAS	MUSCLE EAR 10		SP INHOLE	099113	P 1
CONCENTRATION IN EFFLUENT EXCEEDS LIMIT TWICE	AT ARKANSAS	MUSCLE EAR 10		CHEMICAL	133660	P 4
CONCENTRATIONS IN EFFLUENT EXCEED LIMITS	AT ARKANSAS	MUSCLE EAR 10		CHEMICAL	101611	P 10
CONCENTRATIONS IN EFFLUENT EXCEED LIMIT TWICE	AT ARKANSAS	MUSCLE EAR 10		CHEMICAL	133659	P 5
CONCENTRATION IN EFFLUENT EXCEEDS LIMIT	AT ARKANSAS	MUSCLE EAR 10		CHEMICAL	109519	P 7
CONCENTRATION IN EFFLUENT EXCEEDS LIMITS	AT ARKANSAS	MUSCLE EAR 10		CHEMICAL	101329	P 3
CONCENTRATIONS IN EFFLUENT EXCEED LIMITS	AT ARKANSAS	MUSCLE EAR 10		CHEMICAL	105208	P 7
CONCENTRATIONS IN EFFLUENT EXCEEDS LIMITS	AT ARKANSAS	MUSCLE EAR 10		CHEMICAL	101320	P 4
CONCENTRATIONS IN EFFLUENT EXCEEDS LIMITS	AT ARKANSAS	MUSCLE EAR 10		CHEMICAL	121612	P 10
CONCENTRATION IN EFFLUENT EXCEEDS LIMIT	AT ARKANSAS	MUSCLE EAR 10		CHEMICAL	127701	P 10
CONCENTRATION IN EFFLUENT EXCEEDS LIMIT	AT ARKANSAS	MUSCLE EAR 10		CHEMICAL	109518	P 7
CONCENTRATIONS IN EFFLUENT EXCEEDS LIMITS	AT ARKANSAS	MUSCLE EAR 10		CHEMICAL	135206	P 7
CONCENTRATIONS IN EFFLUENT EXCEED LIMITS	AT ARKANSAS	MUSCLE EAR 10		CHEMICAL	108233	P 12
CONCENTRATIONS IN EFFLUENT EXCEEDS LIMIT	AT ARKANSAS	MUSCLE EAR 10		CHEMICAL	139276	P 13
CONCENTRATIONS IN EFFLUENT EXCEEDS LIMITS	AT ARKANSAS	MUSCLE EAR 10		CHEMICAL	130202	P 11
CONCENTRATIONS IN EFFLUENT EXCEED LIMITS	AT ARKANSAS	MUSCLE EAR 10		CHEMICAL	130716	P 10
CONCENTRATIONS IN EFFLUENT EXCEEDS LIMIT	AT ARKANSAS	MUSCLE EAR 10		CHEMICAL	130077	P 11
CONCENTRATIONS IN EFFLUENT EXCEEDS LIMIT	AT ARKANSAS	MUSCLE EAR 10		CHEMICAL	130275	P 13
CONCENTRATION IN EFFLUENT EXCEEDS LIMIT	AT ARKANSAS	MUSCLE EAR 10		CHLORIDE	100830	P 12
CONCENTRATION IN EFFLUENT EXCEEDS LIMIT	AT ARKANSAS	MUSCLE EAR 10		CHLORIDE	104041	P 6
CONCENTRATION IN EFFLUENT EXCEEDS LIMITS	AT ARKANSAS	MUSCLE EAR 10		CHLORIDE	103076	P 5
POND WATER UPTAKE MAY HAVE BEEN BELOW LIMIT	AT ARKANSAS	MUSCLE EAR 10		EMERGENCY	106374	P 0
INFURMATION ON REACTOR BUILDING SPRAY PIPING	AT ARKANSAS	MUSCLE EAR 10		BAJOIT TYPICAL	099396	P 2
INFURMATION ON LEAK IN H/S URGIN PIPING	AT ARKANSAS	MUSCLE EAR 10		BAJOIT TYPICAL	126973	P 9
INFURMATION ON REACTOR BUILDING SPRAY PIPING	AT ARKANSAS	MUSCLE EAR 10		BAJOIT TYPICAL	137702	P 10
INFURMATION ON SERVICE WATER VALVE FAILURES	AT ARKANSAS	MUSCLE EAR 10		BAJOIT TYPICAL	124296	P 6
INFURMATION ON PRIMARY MAKEUP PUMP LEAK	AT ARKANSAS	MUSCLE EAR 10		BAJOIT TYPICAL	108234	P 12
IN REACTOR BUILDING SPRAY SYSTEM PIPE CRACKS	AT ARKANSAS	MUSCLE EAR 10		OFFICIAL REPORT	109520	P 7
IF AMMONIA IN EFFLUENT EXCEEDS LIMIT	AT ARKANSAS	MUSCLE EAR 10		RECONCENTRATION	105287	P 7
IN REACTOR BUILDING SPRAY SYSTEM ANALYSIS	AT ARKANSAS	MUSCLE EAR 10		OFFICIAL REPORT	109521	P 8
SPRAY SYSTEM MAY NOT OPERATE UNIFORMITY	AT ARKANSAS	MUSCLE EAR 10		REACTOR BUILDING	103689	P 5
GREATLY DECREASING CUMULATIVE RISK NUMBER LIST	AT ARKANSAS	MUSCLE EAR 10		ONCE INTO WHEEL	100276	P 13
TESTING LIVE POND PUMP SEAL LEAKY	AT ARKANSAS	MUSCLE EAR 10		BUILD IN PROGRESS	103690	P 9
INCREASE IN EFFLUENT EXCEEDS LIMIT	AT ARKANSAS	MUSCLE EAR 10		CHEMICAL CONCENTRATION	133666	P 4
OSPREY FUEL PUMP WALL DEFICIENCY	AT ARKANSAS	MUSCLE EAR 20			102240	P 13
UNITARY DELAYS FAIL TO UPDATE	AT ARKANSAS	MUSCLE EAR 20			134667	P 14
SIGNAL REPORT ON SPENT FUEL PWR WALL DEFICIENCY	AT ARKANSAS	MUSCLE EAR 20			104607	P 14
MAIN STEAM PIPE RESTRAINT EJECTION DEFICIENCY	AT ARKANSAS	MUSCLE EAR 20			100609	P 14
UNUSUALLY LARGE				PSOUTH	100600	P 31
NUMBER OF FISH COLLECTED AT CALVERT CLIFFS 10					109680	P 10
RIFT LOGGE AT THREE MILE ISLAND 10					093696	P200
RUITS AND STUOS AT THREE MILE ISLAND 20					106974	P220

SMALL GUN AND PARTICULATE RELEASES DURING THREE DESIGN	OBJECTIVE AT PRAIRIE ISLAND 1 AND 20	100000 P155
SMALL OIL/GAS PROBLEMS	ACCURATE IN THE OIL/GAS ACID SYSTEM AT COOK 10	100005 P 40
UNSCHEMED RELEASES DURING OIL/GAS DISCHARGE	OCCURS AT POINT BEACH 1 AND 20	100210 P143
UNPLANNED RELEASE OF RADIOACTIVE MATERIAL	OCCURS AT CALVERT CLIFFS 10	100402 P 20
UNPLANNED RELEASE OF RADIOACTIVE MATERIAL	OCCURS AT CALVERT CLIFFS 10	100405 P 25
UNPLANNED RELEASE OF RADIOACTIVE MATERIAL	OCCURS AT CALVERT CLIFFS 10	100415 P 29
SAFETY INJECTION ACTIVATION	OCCURS AT COOK 10	100419 P 50
SAFETY INJECTION	OCCURS AT COOK 10	100404 P 67
UNPLANNED RELEASE OF RADIOACTIVE LIQUID	OCCURS AT PRAIRIE ISLAND 10	100313 P167
UNPLANNED RELEASE OF RADIOACTIVE MATERIAL	OCCURS AT THREE MILE ISLAND 10	100546 P210
UNPLANNED RELEASE OF RADIOACTIVE GAS	OCCURS AT THREE MILE ISLAND 10	100308 P200
UNPLANNED RELEASE OF RADIOACTIVE MATERIAL	OCCURS AT THREE MILE ISLAND 10	100307 P212
SAFETY INJECTION	OCCURS AT ZEPH 10	100247 P240
SAFETY INJECTION	OCCURS AT ZEPH 20	100413 P243
SAFETY INJECTION	OCCURS AT ZEPH 20	100443 P252
DISBURSEMENT SAFETY INJECTION	OCCURS AT ZEPH 20	100453 P257
UNSAMPLED RELEASE	OCCURS FROM GAS DECAY TANK AT COOK 10	100911 P 36
OLEUM	IN THE SYSTEM PIPING AT PRAIRIE ISLAND 20	100004 P153
SMALL JIL PUMP	UNDER CORRELANT PUMP MOTOR STAND AT JCOMER 20	100527 P112
RADIATION EXPOSURES IN PROCESS OF ADMINISTRATIVE LIMITS AT	OCCUR	090704 P101
DISPERSED GASES IN PRESSURE TRANSMITTER AT	OCCUR	101465 P102
ORIENTATION CONTROL PRESSURE BUFFER AMPLIFIER FAILS AT	OCCUR	093204 P101
INJECTS PUMP IN A PUMP HOLD UP A SPENT PUMP ASSEMBLY AT	OCCUR	101725 P102
DISCHARGER SYSTEM VALVE LINEUP FAILING MAINTENANCE AT	OCCUR	090716 P100
OPERATIONAL MATCH INTERLOCKS FAIL AT	OCCUR	101150 P102
ORCA 1.4 BUILDING COOLING UNIT LOGIC ERROR AT	OCCUR	090377 P101
ORCA 2.0 BUILDING ELECTED AND NORTH NOT CALCULATED AT	OCCUR	090723 P101
ORCA 2.0 BUILDING ELECTED AND NORTH NOT CALCULATED AT	OCCUR	100548 P102
ORCA 2.0 BUILDING ELECTED AND NORTH NOT CALCULATED AT	OCCUR	100796 P102

INADEQUATE CONTROL OF ISOLATED 100 KV TRANSMISSION LINE AT	OCEANEE 10	137227 P100
EFFLUENT DISCHARGE ISOLATION VALVE FAILS TO CLOSE AT	OCEANEE 10	104237 P136
RELEASE RATE OF TRITIUM EXCEEDS LIMIT AT	OCEANEE 10	135555 P137
DEFECTIVE PWR ROD DISCOVERED AT	OCEANEE 10	135281 P145
MODIFICATION COMPLETED WITHOUT PRIOR AUTHORIZATION AT	OCEANEE 10	104986 P105
OCEANEE 1 TRIPS DURING EMERGENCY START TEST AT	OCEANEE 10	103098 P103
BOILERED WATER STORAGE TANK LEVEL LOW AT	OCEANEE 10	137222 P106
BOORON CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT	OCEANEE 10	104985 P103
BOONAIN VALVE OPENED ON AN INCORRECT UNIT AT	OCEANEE 10	133459 P104
REACTION COOLANT SYSTEM LEAKAGE HIGH AT	OCEANEE 10	104263 P104
OCEANEE WOOD JOINT 2 FAILS TO AUTOSTART AT	OCEANEE 10	134284 P136
REQUIRED EMERGENCY PWR SOURCE NOT PROVIDED AT	OCEANEE 10	104236 P104
PROCESS RADIATION MONITOR FAILS DURING A RELEASE AT	OCEANEE 10	103143 P103
EMERGENCY POWER SOURCE REMOVED FROM SERVICE IMPROPERLY AT	OCEANEE 10	105173 P105
SERVICE WATER PUMP OPERATED WITH SUCTION VALVE CLOSED AT	OCEANEE 10	102547 P103
TRITIUM CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT	OCEANEE 1, 2, AND 30	109296 P107
BOORON CONCENTRATION IN REOUE RIVER EXCEEDS LIMIT AT	OCEANEE 1, 2, AND 30	109296 P106
WPM OF YARD DRAIN WATER EXCEEDS LIMIT AT	OCEANEE 1, 2, AND 30	133330 P105
RESET POINT DRIFT IN PRESSURE TRANSMITTER AT	OCEANEE 1, 2, AND 30	134657 P103
LEVEL OF AIRBORNE RADIOACTIVITY EXCEEDS CONTROL LEVEL AT	OCEANEE 1, 2, AND 30	105537 P106
INFORMATION ON RADIOACTIVITY IN AQUATIC VEGETATION AT	OCEANEE 1, 2, AND 30	109297 P107
BOILERED WATER STORAGE TANK LEVEL INDICATION FAILS AT	OCEANEE 2 AND 30	109589 P110
BOILERED WATER STORAGE TANK LEVEL INDICATION FAILS AT	OCEANEE 2 AND 30	101169 P110
MANUAL FEATURE OF DECAT HEAT REMOVAL SYSTEM VALVES FAIL AT	OCEANEE 2 AND 30	101157 P111
SMALL OIL FIRE OCCURS UNDER COOLANT PUMP MOTOR STAND AT	OCEANEE 20	106327 P112
GUIDE PIN MISSING FROM LPCI VALVE AT	OCEANEE 20	103060 P113
RESETPOINT DRIFT IN PRESSURE TRANSMITTER AT	OCEANEE 20	131160 P111
BLEEDDOWN FILTER GASKET FAILS AT	OCEANEE 20	099032 P108
REACTOR BUILDING SPRAY TRAIN NOT PROVIDED WHEN REQUIRED AT	OCEANEE 20	099102 P109
DISCONNECT WASTE GAS RELEASE RATE AT	OCEANEE 20	099031 P108
BOORE FLOOD DISCHARGE VALVES NOT TAGGED OPEN AT	OCEANEE 20	091021 P109
RESETPOINT DRIFT IN PRESSURE TRANSMITTER AT	OCEANEE 20	101775 P111
POWER LEVEL EXCEEDS LIMIT DURING TRANSIENT REMON AT	OCEANEE 20	099326 P108
SMALL OIL FIRE UNDERNEATH PUMP MOTOR STAND AT	OCEANEE 20	102316 P112
RESET POINT DRIFT IN PRESSURE TRANSMITTER AT	OCEANEE 20	098729 P107
RESETPOINT DRIFT IN PRESSURE TRANSMITTER AT	OCEANEE 20	099021 P100
REACTOR BUILDING SPRAY VALVE FAILS TO OPEN AT	OCEANEE 20	121156 P111
PERSONNEL WATCH INTERLOCKS INOPERABLE AT	OCEANEE 20	093542 P109
BOUNCH TANK LEVEL TOO LOW AT	OCEANEE 20	102546 P112
BREATHING AIR ISOLATION VALVES FOUND OPEN AT	OCEANEE 20	102317 P112
EMERGENCY FEEDWATER VALVE FAILS TO OPEN AT	OCEANEE 20	133361 P113
ACTIVITY IN THE COMPONENT COOLING SYSTEM INCREASES AT	OCEANEE 20	135036 P117
AMPLIFIER IN RPS POWER IMBALANCE CIRCUIT FAILS AT	OCEANEE 20	105045 P116
2400 VOLT MAIN FEEDER BUS BREAKER FAILS TO CLOSE AT	OCEANEE 20	106734 P114
INSTANTANEOUS OUTAGE OF TWO STRINGS OF BATTERIES AT	OCEANEE 20	104946 P115
BOUNCH TANK INADEQUATELY PUMPED BELOW OPERATING LIMIT AT	OCEANEE 20	108424 P119
OPERABLE BUILDING SPRAY TRAIN NOT PROVIDED AS REQUIRED AT	OCEANEE 20	105160 P116
BOUNCH TANK LEVEL INSTRUMENT FAILS AT	OCEANEE 20	105177 P117
PRIMARY REACTOR COOLANT FLOW EXCEEDS DESIGN VALUE AT	OCEANEE 20	103095 P103
UNPLANNED RELEASE OF RADIOACTIVE LIQUID AT	OCEANEE 20	107221 P110
REACTOR BUILDING EMERGENCY MATCH LEAK RATE EXCESSIVE AT	OCEANEE 20	104384 P115
EMERGENCY CONDENSER DISCHARGE VALVE FAILS TO OPEN AT	OCEANEE 20	104081 P115
DES VALVE MANUAL OVERLOADS SIZED INCORRECTLY AT	OCEANEE 20	133492 P114
HIGH ENERGY LEAK HEAT SOUR INADVERTENTLY REMOVED AT	OCEANEE 20	105178 P116
AMPLIFIER IN RPS POWER IMBALANCE CIRCUIT FAILS AT	OCEANEE 20	105172 P116
2400 VOLT MAIN FEEDER BUSES FAIL TO TRANSFER AT	OCEANEE 20	105071 P114
REQUIRED OVERLAP BETWEEN CONTROL ROD GROUPS LOST AT	OCEANEE 20	106320 P117
CONDENSER CIRCULATING WATER VALVES FAIL TO OPEN AT	OCEANEE 20	103111 P114
DISCONNECT BLEEDDOWN FILTER VENT REMOVED AT	OCEANEE 20	107220 P110
BOGASOUS ACTIVITY RELEASED TO AUXILIARY BUILDING AT	OCEANEE 20	104945 P115
DES VALVE FAILS TO CLOSE DURING COOLANT SYSTEM FILL AT	OCEANEE 20	106225 P119
REACTOR BUILDING ELECTRICAL PENETRATION FAILS AT	OCEANEE 20	108485 P119
BLEEDDOWN FLOW INADVERTENTLY ISOLATED AT	OCEANEE 20	101526 P118
TEMPERATURE DETECTION IN RPS CHANNEL A FAILS AT	OCEANEE 20	107220 P118
PENETRATION ROOM VALVES LEAK IN EXCESS OF LIMIT AT	OCEANEE 20	104446 P117
BOORE FLOOD TANK OVERPRESSURIZED AT	OCEANEE 20	103094 P113
ADDITIONAL INFORMATION ON STARTUP WITHOUT BUILDING SPRAY AT	OCEANEE 20	130093 P110
PROPER OVERLAP BETWEEN CONTROL ROD GROUPS NOT MAINTAINED AT	OCEANEE 20	093622 P109
EMERGENCY CONDENSER COOLING WATER VALVES FAIL TO OPEN AT	OCEANEE 20	105049 P110
LEVEL RAISED ABOVE CUTOFF PRIOR TO REMON EQUILIBRIUM AT	OCEANEE 20	101726 P111
BUILDING NORMAL SHUT ISOLATION VALVE FAILS TO CLOSE AT	OCEANEE 20	133259 P113
INFORMATION ON RADIOACTIVE RELEASE THROUGH SHUT AT	OCEANEE 20	109100 P119
ATR LINES TO HIGH PRESSURE INJECTION VALVES ISOLATED AT	OCEANEE 20	107527 P110
BUILDING SPRAY INADVERTENTLY TAKEN OUT OF SERVICE AT	OCEANEE 20	105183 P116
PROPER OVERLAP BETWEEN CONTROL ROD GROUPS NOT PROVIDED AT	OCEANEE 30	130091 P121
PERSONNEL WATCH INTERLOCKS FAIL AT	OCEANEE 30	104707 P123
STEAM GENERATOR SAMPLE LINE VALVE FAILS TO CLOSE AT	OCEANEE 30	103893 P122
PERSONNEL WATCH INTERLOCKS FAIL AT	OCEANEE 30	103112 P122
EMERGENCY FEEDWATER PUMP INOPERABLE AT	OCEANEE 30	103445 P122
VALVE CONTROL POWER FUSE FAILS AT	OCEANEE 30	100380 P120
CONTROL ROD DRIVE BREAKER FAILS TO TRIP AT	OCEANEE 30	105174 P124
ENGINEERED SAFEGUARDS LOGIC BUFFER FAILS AT	OCEANEE 30	100094 P121
RESET POINT DRIFT IN PRESSURE SWITCH AT	OCEANEE 30	103091 P123
REACTOR COOLANT TEMPERATURE INDICATION LOW AT	OCEANEE 30	099705 P120
BOUNCE RANGE NUCLEAR INSTRUMENTATION INOPERABLE AT	OCEANEE 30	103493 P122
PERSONNEL WATCH INTERLOCKS FAIL AT	OCEANEE 30	105274 P124
REACTOR COOLANT SYSTEM COOLDOWN RATE EXCESSIVE AT	OCEANEE 30	103892 P122
ADDITIONAL INFORMATION ON EXCESSIVE COOLDOWN RATE AT	OCEANEE 30	104941 P124

BOUNDED WATER STORAGE TANK LEVEL LOW AT	OCURRER 30	104581 P 123
BOUNCE MANUAL EMERGENCY START PUSHBUTTONS INOPERABLE AT	OCURRER 30	101173 P 121
BOUNCE UNDERGROUND FEEDER INADVERTENTLY ISOLATED AT	OCURRER 30	102134 P 121
BOUNCE PLUM RESTRICTED BY VALVE FAILURE AT	OCURRER 30	107897 P 124
BOUNCEMENT ISOLATION OF RESUME OVERHEAD FEEDER AT	OCURRER 30	093540 P 120
BOUNCE VALVE CONTACT POWER FUSE FAILS AT	OCURRER 30	100892 P 120
BOUNCEMENT MATCH INNER UNDER SEAL FAILS AT	OCURRER 30	100223 P 125
BOUNCE ON SAMPLE LINE FROM THE LPI SYSTEM FAILS AT	OCURRER 30	107007 P 125
BOUNCE SAMPLE LINE WELD FOUND DEFECTIVE AT	OCURRER 30	100579 P 125
BOUNCEMENT ISOLATION VALVE FOUND TO BE INOPERABLE AT	OCURRER 30	107896 P 124
BOUNCE CUTOFF EXCEEDED DURING TRANSIENT AERON CONDITIONS AT	OCURRER 30	104382 P 123
BOUNCE-UP REPORT ON MODIFICATIONS TO	OFF GAS HOLD-UP TANKS AT ZION 1 AND 20	102990 P 230
BOUNCE BREAKER FAILS TO CLOSE DURING LOSS OF	OFF SITE POWER AT FT. CALHOUN	101458 P 55
BOUNCE POWER INCREASED ABOVE PUMP LEVEL CUT	OFF TOC SOON AT THREE MILE ISLAND 10	104086 P 207
BOUNCE PUMP IN	OFF-GAS PIPE AT HILLSTONE 20	100850 P 97
BOUNCE PLUM	OFFSET CALCULATOR DRAINER FAILS AT CALVERT CLIFFS 10	100909 P 15
BOUNCE AXIAL	OFFSET OUT OF TARGET BAND AT SURRY 10	101729 P 102
	OFFSHORE TEMPERATURE SENSOR FAILS AT SAN ONOFRE 10	100350 P 172
	OFFSHORE TEMPERATURE SENSOR FAILS AT SAN ONOFRE 10	100804 P 173
BOUNCE GENERATOR	OIL COOLER JETLET FLANGE LEAKS AT ARKANSAS NUCLEAR 10	100528 P 12
BOUNCE	OIL FIRE OCCURS UNDER COOLANT PUMP MOTOR STAND AT OCURRER 20	100327 P 112
BOUNCE	OIL FIRE UNDERNEATH PUMP MOTOR STAND AT OCURRER 20	102316 P 112
BOUNCE GENERATOR DEVELOPS SEVERE LEAK	OIL LEAK AT ZION 20	100837 P 253
BOUNCE FUEL	OIL NOT SAMPLED ON SCHEDULE AT COOK 10	099115 P 33
BOUNCE GENERATOR TRIPS ON LOW LUBE	OIL PRESSURE AT ROBINSON 20	101781 P 105
BOUNCE FEEDWATER PUMP LUBE	OIL PRESSURE SWITCH FAILS AT PRAIRIE ISLAND 20	104559 P 152
BOUNCE FUEL	OIL SAMPLE LOST AT HILLSTONE 20	100807 P 97
	OIL SPRAYS FROM DIESEL GENERATOR EXHAUST MANIFOLD AT	100524 P 77
	ONCE AT PRAIRIE ISLAND 10	102990 P 230
	ONE DAY AT PRAIRIE ISLAND 20	102115 P 151
	ONE HOUR AT SAN ONOFRE 10	100574 P 171
	ONE INOPERABLE CONTROL ROD AT ROBINSON 20	100621 P 160
	ONE TRAIN OF REACTOR BUILDING SPRAY INADVERTENTLY TAKEN	105100 P 116
OUT OF SERVICE AT OCURRER 20	OCURRER 10	105551 P 171
	OCURRER 10	102574 P 171
	OCURRER 10	101411 P 171
	OCURRER 10	093540 P 170
	OCURRER 20	100804 P 173
	OCURRER 10	100558 P 172
	OCURRER 10	100350 P 172
	OCURRER 10	100455 P 172
	OCURRER 10	104071 P 171
	OCURRER 10	104065 P 171
	OPEN AT ARKANSAS NUCLEAR 10	093577 P 2
	OPEN AT CALVERT CLIFFS 10	101159 P 20
	OPEN AT CALVERT CLIFFS 10	102160 P 22
	OPEN AT FT. CALHOUN	101457 P 55
	OPEN AT FT. CALHOUN	102474 P 57
	OPEN AT INDIAN POINT 20	093100 P 74
	OPEN AT INDIAN POINT 20	102554 P 71
	OPEN AT INDIAN POINT 20	101407 P 71
	OPEN AT KEMAUNEE	105522 P 81
	OPEN AT KEMAUNEE	102534 P 79
	OPEN AT KEMAUNEE	100378 P 81
	OPEN AT KEMAUNEE	100117 P 81
	OPEN AT KEMAUNEE	103008 P 85
	OPEN AT MAINE VANKEE	093621 P 109
	OPEN AT OCURRER 20	102317 P 112
	OPEN AT OCURRER 20	101156 P 111
	OPEN AT OCURRER 20	103061 P 113
	OPEN AT OCURRER 20	100549 P 110
	OPEN AT OCURRER 20	104061 P 115
	OPEN AT OCURRER 20	103111 P 114
	OPEN AT PALISADES	100448 P 132
	OPEN AT PALISADES	105182 P 131
	OPEN AT POINT BEACH 20	090722 P 139
	OPEN AT PRAIRIE ISLAND 10	103116 P 145
	OPEN AT RANCHO SECO	101454 P 157
	OPEN AT RANCHO SECO	100632 P 162
	OPEN AT ROBINSON 20	104305 P 167
	OPEN AT ROBINSON 20	104037 P 167
	OPEN AT ROBINSON 20	104216 P 167
	OPEN AT SURRY 10	103119 P 184
	OPEN AT SURRY 10	100548 P 188
	OPEN AT SURRY 10	100800 P 189
	OPEN AT SURRY 10	100444 P 190
	OPEN AT SURRY 20	102531 P 193
	OPEN AT TURKEY POINT 40	103635 P 227
	OPEN AT ZION 10	102600 P 239
	OPEN AT ZION 20	107896 P 251
	OPEN AT ZION 20	107416 P 251
	OPEN AT ZION 20	107893 P 251
	OPEN COMPLETELY AT COOK 10	103073 P 40
	OPEN ON SIGNAL AT FT. CALHOUN	104582 P 62
	OPEN SIMULTANEOUSLY AT PRAIRIE ISLAND 10	102606 P 140
	OPEN TOO LONG AT CALVERT CLIFFS 10	100096 P 19
	OPENED AT COOK 10	104062 P 42

[illegible]

[illegible]

1201154	P 31
1206307	P 270
1208212	P 134
1209168	P 131
1209541	P 131
1209501	P 131
1209991	P 131
1207275	P 130
1205979	P 126
1217358	P 127
1209187	P 134
1216635	P 127
1206607	P 133
1215882	P 131
1223161	P 128
1200874	P 130
1213073	P 131
1201736	P 127
1209663	P 131
1208313	P 130
1203703	P 129
1209502	P 126
1202744	P 130
1209507	P 125
1203609	P 126
1206648	P 132
1207762	P 131
1205051	P 131
1222268	P 129
1201734	P 132
1206337	P 127
1203666	P 129
1202308	P 128
1211552	P 127
1207225	P 131
1206134	P 132
1213671	P 130
1205223	P 130
1206044	P 129
1205404	P 132
1201737	P 128
1207511	P 133
1209018	P 50
1222891	P 59
1209326	P 59
1203066	P 180
1204862	P 47
1207888	P 82
1205517	P 62
1205559	P 66
1206272	P 58
1206373	P 58
1201659	P 55
1206383	P 55
1208705	P 43
1203924	P 59
1205548	P 67
1208253	P 63
1204000	P 67
1203664	P 107
1203935	P 107
1200904	P 86
1213244	P 74
1204964	P 177
1203897	P 248
1208285	P 119
1205529	P 133
1206560	P 133
1206646	P 137
1203249	P 162
1218021	P 170
1203117	P 126
1214221	P 206
1204605	P 31
1213083	P 55
1204012	P 81
1213088	P 81
1204982	P 106
1203367	P 230
1203367	P 230
1203376	P 66
1202989	P 144
1203405	P 39
1203386	P 39
1203268	P 151
1202115	P 151
1200806	P 95
1206353	P 95

ISLAND 10	OVERDOOR	PERFORMED	MURA NOT CONTROLLED ADEQUATELY AT THREE MILE	133889 P237
CONNECTICUT		0	PERMANENT UNWATERING SYSTEM REQUIRED AT SURRY 3 AND 40	137523 P138
		0	PERSONNEL AIR LOCK INNER AND OUTER DOOR SEALS LEAK AT FT.	090372 P 56
		0	PERSONNEL MATCH INNER LOCK S.M. FAILS AT JCOMF 30	134223 P125
		0	PERSONNEL MATCH INTERLOCKS FAIL AT JCOMF 10	131150 P132
		0	PERSONNEL MATCH INTERLOCKS FAIL AT JCOMF 30	133112 P122
		0	PERSONNEL MATCH INTERLOCKS FAIL AT JCOMF 30	134307 P123
		0	PERSONNEL MATCH INTERLOCKS FAIL AT JCOMF 30	135274 P126
		0	PERSONNEL MATCH INTERLOCKS INOPERABLE AT JCOMF 20	093567 P109
	CONTRACTOR		PERSONNEL RECEIVES OVEREXPOSURE AT ROBINSON 20	101403 P165
	WASTE WATER EFFLUENT		PH EXCEEDS LIMIT AT RANCHO SEC20	104295 P160
	WASTE NEUTRALIZING TAIL DISCHARGE		PH LOW AT REMANUEP	132535 P 79
		0	PH IF TURBINE ROOM SUMP DISCHARGE EXCEEDS LIMIT AT CCM 10	090382 P 34
		0	PH IF TURBINE ROOM SUMP DISCHARGE EXCEEDS LIMITS AT CCM 10	090196 P 33
		0	PH OF YARU DRAIN WATER EXCEEDS LIMIT AT JCOMF 10, 20, AND 30	133330 P105
	OVERVIEW WATER MEASUREMENT DEVELOPS A		PIR HOLE LEAK AT HILLSTONE 20	136374 P 91
MAINE YANKEE		0	PIR HOLE LEAK IN MINIMUM FLOW LINE OF A CHARGING PUMP AT	090673 P 86
	GUIDE		PIR MISSING FROM LPCI VALVE AT JCOMF 20	133367 P113
		0	PIR-HOLE LEAK IN CHARGING PUMP LINE AT MAINE YANKEE	130892 P 81
YANKEE		0	PIR-HOLE LEAK IN CHARGING PUMP RECIRCULATION LINE AT MAINE	130631 P 83
	CHARGING PUMP RECIRC LINE DEVELOPS		PIR-HOLE LEAK AT SURRY 10	132274 P103
AT SURRY 10		0	PIR-HOLE LEAK DEVELOPS IN CHARGING PUMP RECIRCULATION LINE	134367 P104
AT JCOMF		0	PIR-HOLE LEAK FOUND IN CHARGING PUMP DISCHARGE DRAIN LINE	130932 P 49
		0	PIR-HOLE LEAK FOUND ON CRO AND TRAVEL HOUSING AT GEMAN	132955 P 65
ARKANSAS NUCLEAR 10		0	PIR-HOLE LEAK IN REACTOR COOLANT PUMP SEAL VENT VALVE AT	090113 P 1
	HOUSING OF STAINLESS STEEL		PIPE ASSEMBLIES AT NORTH ANNA 1 AND 20	130816 P 99
	WATER FOUND IN OFF-GAS		PIPE AT HILLSTONE 20	130750 P 97
	BLINER INDICATIONS FOUND IN CARBON STEEL		PIPE AT SALEM 10	104984 P169
	OFF-GAS MANAGER		PIPE ATTACHMENTS DISCOVERED BROKEN AT CONNECTICUT YANKEE	104093 P 32
	OFFICIAL REPORT ON REACTOR BUILDING SPRAY SYSTEM		PIPE CRACKS AT ARKANSAS NUCLEAR 10	135523 P 8
	CHARGING PUMP PRESSURE INDICATING		PIPE CRACKS AT ZION 20	090112 P261
	ADDITIONAL INFORMATION ON CHARGING PUMP		PIPE FAILURE AT ZION 20	132938 P265
	BOOTH WITH STEAM		PIPE RESTRAINT BRACKET DEFICIENCY AT ARKANSAS NUCLEAR 20	100809 P 16
		0	PIPE SUPPORT FOUND BROKEN AT THREE MILE ISLAND 10	090371 P230
	ADDITIONAL INFORMATION ON REACTOR BUILDING SPRAY		PIPING AT ARKANSAS NUCLEAR 10	137782 P 10
	ADDITIONAL INFORMATION ON REACTOR BUILDING SPRAY		PIPING AT ARKANSAS NUCLEAR 10	090396 P 2
	ADDITIONAL INFORMATION ON LEAK IN ACS DRAIN		PIPING AT ARKANSAS NUCLEAR 10	130673 P 9
	OFFICIAL REPORT ON ENDSUM DAMAGE TO SALT WATER		PIPING AT CALVERT CLIFFS 10	130523 P 20
	STENOGRAPH HALL LEAK IN LINING LINE - VENT		PIPING AT REMANUEP	093253 P 77
	ADDITIONAL INFORMATION OF SEISMIC RESTRAINTS ON		PIPING AT PALLASDEP	131152 P127
	BLEAK OCCURS IN THE SYSTEM		PIPING AT PRAIRIE ISLAND 20	130834 P153
	BUILDING DOCUMENTATION DEFICIENCY ON CLASS A, B, C, AND D		PIPING AT SEQUOYAH 1 AND 20	130300 P173
	OVERVIEW WATER SYSTEM		PIPING CLASSIFICATION IN BRACH AT CALVERT CLIFFS 10	130872 P 20
	BEST LINES ON SERVICE WATER		PIPING FAIL TO MEET CODE AT CCM	100603 P 67
	REACTOR BUILDING SPRAY PUMP		PIPING LEAKS AT ARKANSAS NUCLEAR 10	137915 P 10
	DEMINATION FOUND IN		PIPING MATERIAL AT MCQUIRE 1 AND 20	130512 P 87
	OVERVIEW WATER		PIPING NOT SEISMICALLY QUALIFIED AT HILLSTONE 20	130642 P 96
	CHARGING PUMP		PIPING WELD LEAKS AT ZION 20	132936 P266
	OSPERT FUEL		PIR COOLING PUMPS FAIL AT TURKEY POINT 2 AND 40	135563 P229
	OVERVIEW WATER VALVE		PIR FLOODED AT SURRY 20	093255 P190
	OSPERT FUEL		PIR LEAKS AT TURKEY POINT 40	100799 P228
	BLEAK PROTECTION FOR RMR		PITS INADEQUATE AT PRAIRIE ISLAND 10	107409 P148
	AUXILIARY FEEDWATER PUMP		PLACED IN MANUAL CONTROL AT PRAIRIE ISLAND 10	135717 P167
	FAILED PRESSURIZER LEVEL CHANNEL NOT		PLACED IN TRIPPED POSITION AT CCM 10	135244 P 44
	TURBIDITY IN		PLANT CIRCULATING WATER INCREASES AT ARKANSAS NUCLEAR 10	132611 P 3
	DISSOLVED OXYGEN ACROSS		PLANT COOLING WATER EXCEEDS LIMITS AT CONNECTICUT YANKEE	130340 P 33
	PERCESSIVE TOTAL CHLORINE CONCENTRATION IN		PLANT DISCHARGE AT THREE MILE ISLAND 10	132669 P204
	DRINK CHLORINE IN		PLANT EFFLUENT AT RANCHO SEC00	102487 P158
	DRINKAGE TREATMENT		PLANT EFFLUENT DO EXCEEDS LIMIT AT FT. CALHOUN	102980 P 57
	TURBIDITY INCREASE ACROSS		PLANT EXCEEDS LIMIT AT ARKANSAS NUCLEAR 10	130611 P 9
	CHLORIDE INCREASE ACROSS		PLANT EXCEEDS LIMIT AT ARKANSAS NUCLEAR 10	105157 P 9
	TEMPERATURE DIFFERENTIAL ACROSS THE		PLANT EXCEEDS LIMIT AT THREE MILE ISLAND 10	100239 P216
	OGAP FOUND AT SLIDE BEARING		PLATE FOR PLIN STEEL LINE AT THREE MILE ISLAND 10	132533 P205
	OTHERMAL		PLUME SIZE EXCEEDS LIMIT AT ZION 1 AND 20	107688 P230
	SHIFT IN INTERMEDIATE RANGE HIGH FLUX REACTOR TRIP SET		POINT AT PRAIRIE ISLAND 20	130833 P153
	UNSCHEMULED RELEASE OF GASEOUS RADIOACTIVITY AT		POINT BEACH 1 AND 20	104834 P162
	UNSCHEMULED MONITORED GASEOUS DISCHARGE OCCURS AT		POINT BEACH 1 AND 20	108210 P163
	STATION BATTERY TESTING NOT PERFORMED ON TIME AT		POINT BEACH 1 AND 20	093248 P162
	DIESEL RELAY FAILS TO RESPOND WITHIN TIME LIMIT AT		POINT BEACH 1 AND 20	102566 P162
	GENERIC PROBLEMS WITH JAMPER LINES WITHIN PENETRATING AT		POINT BEACH 1 AND 20	093249 P162
	SAFETY INJECTION SYSTEM VALVE FAILS TO CLOSE AT		POINT BEACH 10	130879 P138
	OPRESSURIZER PRESSURE CHANNEL DISTABLE FAILS TO TRIP AT		POINT BEACH 10	135538 P137
	REDUNDANT CONTAINMENT VALVE FAILS TO CLOSE AT		POINT BEACH 10	109185 P138
	OPRESSURE SWITCH CALIBRATED INCORRECTLY AT		POINT BEACH 10	100660 P138
	CONTRACTOR EMPLOYEE RECEIVES OVEREXPOSURE AT		POINT BEACH 10	137987 P136
	FAILED FUEL RODS FOUND IN AN ASSEMBLY AT		POINT BEACH 10	130184 P139
	BLON LEVEL RADIOACTIVE LIQUID RELEASE AT		POINT BEACH 10	102319 P136
	DRAIN STEAM LINE FLOW CHANNEL FAILS AT		POINT BEACH 10	101774 P136
	OUTBOARD CONTAINMENT PURGE SUPPLY VALVE LEAKS AT		POINT BEACH 10	105283 P137
	OPURGE SUPPLY ISOLATION VALVE LEAKS AT		POINT BEACH 10	103906 P137
	ADDITIONAL INFORMATION ON STEAM GENERATOR TUBE FAILURE AT		POINT BEACH 10	105905 P137
	BOHRIC ACID HEAT TRACING CHANNEL INOPERABLE AT		POINT BEACH 10	103483 P136
	CONTAINMENT PURGE VALVE CLOSING TIMES EXCEED LIMIT AT		POINT BEACH 10	093517 P135
	STEAM GENERATOR TUBE FAILS AT		POINT BEACH 10	130257 P135
	STEAM GENERATOR TUBE FAILS AT		POINT BEACH 10	130547 P135
	BLON LEVEL RADIOACTIVE LIQUID RELEASED AT		POINT BEACH 10	121147 P136
	TRIP MECHANISM ON MSIV OPERATOR FAILS TO UNLATCH AT		POINT BEACH 10	100074 P135
	ON NUCLEAR POWER RANGE CHANNEL LOST TEMPORARILY AT		POINT BEACH 10	106331 P138

DEFUELING WATER STORAGE TANK LEVEL BELOW LIMIT AT	POINT BEACH 20	107785 P161
DISCREPANCY VALVES TESTED FOR LEAKAGE AT	POINT BEACH 20	099108 P140
STEAM GENERATOR AUXILIARY FUEL VALVE FAILS TO OPEN AT	POINT BEACH 20	099722 P139
DRUM SUPPLY VALVE LEAKS AT	POINT BEACH 20	100618 P143
DRUM DISTANCE TEMPERATURE DETECTOR FAILS AT	POINT BEACH 20	102528 P141
DRUM STEAM STOP VALVE FAILS TO CLOSE WITH ZERO FLOW AT	POINT BEACH 20	103105 P141
DRUM JUMP TRIP MECHANISM ON MAIN STEAM STOP VALVE FAILS AT	POINT BEACH 20	106113 P141
DRUM GENERATOR LEVEL INSTRUMENT MALFUNCTION AT	POINT BEACH 20	099017 P139
DRUM GENERATOR TUBE LEAK AT	POINT BEACH 20	106613 P161
DRUM JUMP TRIP MECHANISM ON MAIN STEAM STOP VALVE FAILS AT	POINT BEACH 20	106664 P161
DRUM LEVEL RADIOACTIVE RELEASE WITHOUT IN-LINE MONITOR AT	POINT BEACH 20	099715 P160
PURGE AND EXHAUST VALVE CLOSING TIME EXCEEDS LIMIT AT	POINT BEACH 20	099365 P139
GENERAL HIGH DEVIATION MONITOR ALARM	POINT BEACH 20	100019 P 00
CALMAYO	POINT DRIFT IN ATOM POWER DISTRIBUTION CHANNEL AT FT.	106204 P 99
30	POINT DRIFT IN CONTAINMENT PRESSURE SWITCH AT TURKEY POINT	106271 P226
HILLSTONE 20	POINT DRIFT IN CONTAINMENT PRESSURE SWITCHES AT PALISADES	102314 P120
	POINT DRIFT IN CONTAINMENT PRESSURE TRANSMITTER AT	100020 P 90
	POINT DRIFT IN DIFFERENTIAL TEMPERATURE SWITCH AT ZION 10	106206 P240
	POINT DRIFT IN FLOW TRANSMITTER AT ZION 10	103095 P237
	POINT DRIFT IN FLOW DISTANCE AT HILLSTONE 20	100018 P 96
	POINT DRIFT IN FLOW SENSOR AT COOK 10	105516 P 45
	POINT DRIFT IN FLOW TRANSMITTERS AT ZION 10	107518 P239
	POINT DRIFT IN LEVEL INDICATOR AT SURRY 20	100072 P191
	POINT DRIFT IN LEVEL INDICATORS AT ZION 20	100013 P230
	POINT DRIFT IN LEVEL SCRAM INSTRUMENT AT YANKEE RIVER	100044 P233
	POINT DRIFT IN LEVEL SENSOR AT ZION 20	099604 P242
	POINT DRIFT IN LEVEL SENSOR AT PALISADES	103671 P129
	POINT DRIFT IN MAIN STEAM SAFETY VALVES AT SURRY 10	106662 P187
	POINT DRIFT IN OVERPOWER DELTA T SUMMING AMPLIFIER AT	103633 P 72
	POINT DRIFT IN PRESSURE SWITCH AT OCONEE 30	100001 P123
	POINT DRIFT IN PRESSURE SWITCH AT PHAEDRIS ISLAND 20	105730 P152
	POINT DRIFT IN PRESSURE SWITCH AT THREE MILE ISLAND 10	102955 P210
	POINT DRIFT IN PRESSURE SWITCH AT YANKEE RIVER	099621 P231
	POINT DRIFT IN PRESSURE SWITCHES AT OCONEE 1, 2, AND 30	103457 P103
	POINT DRIFT IN PRESSURE TRANSMITTER AT OCONEE 20	099729 P127
	POINT DRIFT IN PRESSURE TRANSMITTER AT THREE MILE ISLAND 10	103007 P207
	POINT DRIFT IN PRESSURE TRANSMITTERS AT AARMO SECOP	102105 P157
	POINT DRIFT IN PRESSURE TRANSMITTERS AT SURRY 10	107631 P187
	POINT DRIFT IN PRESSURE TRANSMITTERS AT THREE MILE ISLAND 1	100000 P209
	POINT DRIFT IN PRESSURIZER LEVEL TRANSMITTERS AT ZION 20	102526 P252
	POINT DRIFT IN REACTOR COOLANT PRESSURE CHANNEL AT THREE	103630 P206
	POINT DRIFT IN REACTOR COOLANT PRESSURE SWITCHES AT THREE	103629 P206
	POINT DRIFT IN STEAM GENERATOR LEVEL COMPARE AT ZION 10	100098 P236
	POINT DRIFT IN STEAM GENERATOR PRESSURE CHANNELS AT	100051 P 97
	POINT DRIFT IN TEMPERATURE DISTANCE AT GINNAO	105298 P 87
	POINT DRIFT IN TEMPERATURE DISTANCE AT THREE MILE ISLAND 10	103006 P100
	POINT DRIFT IN TEMPERATURE CHANNEL AT SURRY 10	106318 P105
	POINT DRIFT IN TEMPERATURE DIFFERENTIAL DISTANCE AT GINNAO	105549 P 04
	POINT DRIFT IN TEMPERATURE DIFFERENTIAL SWITCH AT PHAEDRIS	100527 P149
	POINT DRIFT IN TEMPERATURE SENSOR AT SURRY 10	105715 P105
	POINT DRIFT IN TEMPERATURE SWITCH AT SURRY 20	105857 P195
	POINT DRIFT IN THERMAL MARGIN/LON PRESSURE SWITCH AT FT.	100458 P 50
	POINT DRIFT IN TIME-DELAY RELAY AT COOK 10	103097 P 30
	POINT DRIFT IN UNDERFREQUENCY RELAY AT PHAEDRIS ISLAND 20	103670 P151
	POINT RAMPING UP AT HILLSTONE 20	107622 P 95
	POINT SHIFT WITH POWER AT HILLSTONE 20	106445 P 92
	POINT 10	107695 P 69
	POINT 10	107906 P 69
	POINT 10	107630 P228
	POINT 20	100923 P 70
	POINT 20	103634 P 72
	POINT 20	103147 P 72
	POINT 20	100975 P 70
	POINT 20	100922 P 70
	POINT 20	102554 P 71
	POINT 20	100014 P 70
	POINT 20	101733 P 71
	POINT 20	101007 P 71
	POINT 20	100576 P 70
	POINT 20	105164 P 73
	POINT 20	105332 P 75
	POINT 20	103632 P 72
	POINT 20	100993 P 72
	POINT 20	100556 P 76
	POINT 20	100801 P 76
	POINT 20	099180 P 74
	POINT 20	106647 P 74
	POINT 20	106982 P 75
	POINT 20	109190 P 76
	POINT 20	105860 P 73
	POINT 20	107901 P 75
	POINT 20	105546 P 73
	POINT 20	106666 P 74
	POINT 20	100749 P 69
	POINT 20	105861 P 74
	POINT 20	107744 P 75
	POINT 20	105163 P 73
	POINT 20	102553 P 71

CONTAINMENT

SUPPLEMENTARY

REACTOR

PRESSURE

PRESSURE

[illegible]

[illegible]

[illegible]

0	UNPLANNED RELEASE OF	0 REACTOR COOLANT SYSTEM HYDROGEN CONCENTRATION EXCEEDS LIMIT	100040 P160
0	0	0 REACTOR COOLANT SYSTEM HYDROGEN CONCENTRATION EXCEEDS LIMITS	100040 P160
0	0	0 REACTOR COOLANT SYSTEM PACKING SLAND LEAK AT CONNECTION	101150 P 31
0	0	0 REACTOR COOLANT TEMPERATURE INDICATION LOW AT COOLIDGE 30	000705 P120
0	0	0 REACTOR COOLANT WASTE RETURN TANK AT CALVERT CLIFFS 10	100075 P 26
0	0	0 REACTOR CRITICALITY REACHED AT 50% AT THREE MILE ISLAND 1	100271 P204
0	0	0 REACTOR OPERATIONS AT CALVERT CLIFFS 20	100607 P 20
0	0	0 REACTOR OPERATIONS WITH AIRMAL PLAN DIFFERENCE OUTSIDE	100501 P221
0	0	0 REACTOR POWER INCREASED ABOVE POWER LEVEL SET OFF TWO MINS	100400 P207
0	0	0 REACTOR POWER LEVEL TO UP DISTANCE FAILS TO TRIP AT MIDGE	100400 P130
0	0	0 REACTOR PROTECTION LOGIC CHANNELS NOT TESTED ON SCHEDULE AT	100040 P 74
0	0	0 REACTOR PROTECTIVE TEST PANEL CIRCUITS AT COOL 1 AND 20	000010 P 30
0	0	0 REACTOR PROTECTIVE SYSTEM PANELS AT CALVERT CLIFFS 10	100390 P 24
0	0	0 REACTOR TRIP OPERATIONS NOT PERFORMED ON TIME AT COOL 10	000204 P 40
0	0	0 REACTOR TRIP DUE TO LOSS OF INSTRUMENT BUSES AT ROBINSON 2	000242 P100
0	0	0 REACTOR TRIP SET POINT AT PRAIRIE ISLAND 20	100033 P153
0	0	0 REACTOR VESSEL AT SURRY 10	100373 P101
0	0	0 REACTOR VESSEL SURFACE CONTAMINATION AT ST. LUCIE 10	100052 P175
0	0	0 READING ON PRIMARY DATA LOGGER FAILS TO UPDATE AT PALISADES	102300 P120
0	0	0 READING SHIFTS AT ZION 20	000523 P200
0	0	0 REBAR INSTALLATION AND INSPECTION ERRORS AT MIDLAND 20	000040 P 00
0	0	0 RECOVER TANK AT CALVERT CLIFFS 20	100210 P 21
0	0	0 RECEIVES OVEREXPOSURE AT POINT BEACH 10	100400 P130
0	0	0 RECEIVES OVEREXPOSURE AT PALISADES	100400 P130
0	0	0 RECENTLY INSTALLED INCOME DETECTORS CONTINUE TO FAIL AT	100005 P 50
0	0	0 REED LINE DEVELOPS PIVOTAL LEAK AT SURRY 10	100270 P103
0	0	0 REECONCILING FLOW IN BURN INJECTION TANK REDUCED AT COOL	100607 P 67
0	0	0 REECONCILING LINE AT HAINE YANKEE	100431 P 03
0	0	0 REECONCILING LINE AT SURRY 10	100402 P104
0	0	0 REECONCILING SPRAY CHECK VALVE FAILURES AT SURRY 20	000403 P100
0	0	0 REECONCILING VALVE FOUND OPEN AT ZION 10	100200 P130
0	0	0 REECONCILING VALVES FOUND CLOSED AT SURRY 20	100270 P105
0	0	0 RECORD REQUIREMENTS AT YANKEE RIVER	100211 P220
0	0	0 RECORDED CONTINUOUSLY AT FT. CALHOUN	100023 P 61
0	0	0 RECORDED ON TIME DURING LOAD CHANGE AT KENNAWHEE/NECONSIN	100214 P 70
0	0	0 RECORDED CALIBRATION INCORRECT AT TURKEY POINT 30	000027 P221
0	0	0 RECORDED CALIBRATION INCORRECT AT TURKEY POINT 40	000020 P225
0	0	0 RECORDED FAILS AT FT. CALHOUN	000020 P 04
0	0	0 RECORDED FORMAL INSPECTION AT COOL 10	100020 P 50
0	0	0 RECORDS BY 05H DEPARTED AT BELLEFOUNT 1 AND 20	100042 P 15
0	0	0 REDUCE SAFETY MARGIN AT ZION 1 AND 20	100259 P237
0	0	0 REDUCED AT COOL 10	100607 P 67
0	0	0 REDUNDANCY ON NUCLEAR POWER RANGE CHANNEL LOST TEMPORARILY	100331 P130
0	0	0 REDUNDANT CONTAINMENT VALVE FAILS TO CLOSE AT POINT BEACH 1	120105 P122
0	0	0 REDUNDANT TRIP MECHANISM ON 10% STEAM STOP VALVE FAILS AT	100540 P101
0	0	0 REDUNDANT TRIP MECHANISM ON MAIN STEAM STOP VALVE FAILS AT	100113 P101
0	0	0 REDUNDANT TRIP MECHANISM ON MSV OPERATOR FAILS TO UNLATCH	000070 P135
0	0	0 REPAIRING CANAL WALL AT ST. LUCIE 10	000471 P175
0	0	0 REPAIRING CANAL WALL CRACK INTERIM REPORT AT ST. LUCIE 10	100353 P175
0	0	0 REPAIRING OPERATIONS AT TURKEY POINT 40	100251 P226
0	0	0 REPAIRING OPERATIONS AT TURKEY POINT 40	100290 P227
0	0	0 REPAIRING POOL WATER LEVEL LOW DURING CORE ALTERATIONS AT	100500 P 00
0	0	0 REPAIRING WATER INADEQUATELY REFERRED TO CONTAINMENT	100527 P 17
0	0	0 REPAIRING WATER STORAGE TANK AND FOUNDATION DEFICIENCY AT	100232 P171
0	0	0 REPAIRING WATER STORAGE TANK LEVEL BELOW LIMIT AT POINT	100705 P101
0	0	0 REPAIRING WATER STORAGE TANK VOLUME LESS THAN LIMITS AT	100253 P 71
0	0	0 REPAIRING BAR SPACING AT MIDLAND 1 AND 20	000670 P 07
0	0	0 REPAIRING BAR SPACING DEFICIENCY AT MIDLAND 20	100540 P 08
0	0	0 REJECTED TRIP DEVICE INSTALLED IN CIRCUIT BREAKER AT COOL 1	000600 P 30
0	0	0 RELATED CABLES AT NORTH ANNA 1 AND 20	100600 P 00
0	0	0 RELAY AT COOL 10	100307 P 30
0	0	0 RELAY AT PRAIRIE ISLAND 20	100370 P151
0	0	0 RELAY CONTACTS OF DIESEL GENERATOR STICK AT THREE MILE	100261 P217
0	0	0 RELAY DEFICIENCY FOUND AT PEARLY 1 AND 20	100013 P 53
0	0	0 RELAY FAILS IN ENERGIZED POSITION AT SURRY 10	100453 P100
0	0	0 RELAY FAILS TO LATCH AT KENNAWHEE	100409 P 70
0	0	0 RELAY FAILS TO LATCH AT PEARLY	100409 P107
0	0	0 RELAY FAILS TO RESPOND WITHIN TIME LIMIT AT POINT BEACH 1	100506 P102
0	0	0 RELAY FAILS TO TRIP AT FT. CALHOUN	000020 P 54
0	0	0 RELAY FAILS TO TRIP AT FT. CALHOUN	000044 P 54
0	0	0 RELAY FAILURES AT ST. LUCIE	100601 P177
0	0	0 RELAY FOR DIESEL GENERATOR FAILS AT THREE MILE ISLAND 10	100450 P200
0	0	0 RELAY MALFUNCTION AT TURKEY POINT 10	100330 P220
0	0	0 RELAY MALFUNCTION AT TURKEY POINT 40	100207 P227
0	0	0 RELAY MALFUNCTIONS AT GINNA	100454 P 06
0	0	0 RELAYS AT FT	

[illegible]

[illegible]

[illegible]

MAIN STEAM LINE SPRING	SPURGE	SUPPLY VALVE LEAKS AT POINT EACH 20	173616 P160
PIPE	PIPE	SUPPORT FOUND BROKEN AT THREE MILE ISLAND 10	174732 P224
DEAD MATERIAL WITHIN GRINDERS HYDRAULIC SHOCK	SHOCK	SUPPRESSOR FAILS AT PT. CALHOUN	175547 P 61
HYDRAULIC SHOCK	SHOCK	SUPPRESSOR FAILS AT THREE MILE ISLAND 10	175647 P231
HYDRAULIC SHOCK	SHOCK	SUPPRESSOR FOUND TO BE DISCONNECTED AT THREE MILE ISLAND 10	176763 P216
HYDRAULIC SHOCK	SHOCK	SUPPRESSOR INSPECTED AT THREE MILE ISLAND 10	176855 P203
HYDRAULIC SHOCK	SHOCK	SUPPRESSOR INSPECTION AT PT. CALHOUN	176873 P 57
HYDRAULIC SHOCK	SHOCK	SUPPRESSORS FAIL TO MEET CRITERIA AT VAMBER 3350	176879 P233
HYDRAULIC SHOCK	SHOCK	SUPPRESSORS INSPECTABLE AT THREE MILE ISLAND 10	177139 P233
REACTION VESSEL	REACTOR	SURFACE CONTAMINATION AT ST. LUCIE 10	177352 P175
VENTILATION VENT GASEOUS RELEASE HIGH AT	VENT	SURVEY 1 AND 20	177903 P190
NOTICE OF PROPOSED IMPOSITION OF CIVIL PENALTIES AT	NOTICE	SURVEY 1 AND 20	177964 P197
VENTILATION CANAL LEVEL MAGNETIC AMPLIFIERS FAIL AT	VENT	SURVEY 1 AND 20	178731 P197
OSTEAM GENERATOR TUBE EFFICIENCY AT	OSTEAM	SURVEY 1 AND 20	179261 P197
POWER IMPOSING CIVIL PENALTIES OF \$10,000 AT	POWER	SURVEY 1 AND 20	179705 P197
CONTROL STRUCTURE TEMPERATURE DECREASED TOO RAPIDLY AT	CONTROL	SURVEY 1 AND 20	180736 P196
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS TO OPEN AT	EMERGENCY	SURVEY 10	180803 P189
ORIGINAL CHARGING LINE STOP VALVE FAILS TO CLOSE AT	ORIGINAL	SURVEY 10	180879 P189
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS TO OPEN AT	EMERGENCY	SURVEY 10	180964 P193
BORON CONCENTRATION IN ACCUMULATOR LESS THAN LIMIT AT	BORON	SURVEY 10	180962 P185
TEMPERATURE DIFFERENTIAL INSTRUMENT DRIFTS LOW AT	TEMPERATURE	SURVEY 10	180633 P186
BORON CONCENTRATION IN SE ACCUMULATOR BELLO LIMITS AT	BORON	SURVEY 10	182277 P186
CONTACT ROD DRIVE SHORT INADEQUATELY SENT AT	CONTACT	SURVEY 10	182255 P188
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	180273 P191
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	181149 P182
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	182436 P181
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	182762 P188
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	183618 P183
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	184667 P187
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	182276 P182
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	184544 P188
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	187526 P187
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	187431 P187
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	187119 P184
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	186652 P186
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	187265 P181
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	188549 P198
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	182678 P183
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	181729 P182
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	183263 P180
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	186316 P185
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	187596 P188
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	186361 P184
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	188978 P189
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	185715 P185
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	182264 P181
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	185653 P186
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	186315 P185
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	184683 P186
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	182995 P185
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	181724 P182
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	189291 P189
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	182274 P183
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	183266 P180
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	186811 P187
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	182279 P193
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	184982 P185
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	181733 P182
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	184462 P184
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	187375 P180
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	180272 P191
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	186219 P196
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	182562 P191
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	180436 P191
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	185532 P196
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	183693 P194
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	181780 P192
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	183118 P193
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	180262 P191
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	182555 P191
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	187355 P190
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	187632 P196
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	184857 P195
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	182531 P193
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	186735 P195
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	187901 P194
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	183117 P193
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	187695 P196
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	180394 P191
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	182466 P196
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	187633 P196
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	185276 P195
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	184980 P195
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	189754 P190
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	182273 P192
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	184764 P194
EMERGENCY FREIGHTER PUMP DISCHARGE VALVE FAILS AT	EMERGENCY	SURVEY 10	181731 P197

DISCHARGE

SPURGE
DISCHARGE

CONTAINMENT AND HEAT EXCHANGE SPRAY CHECK VALVE FAILURES AT
WATER SYSTEM MAIN CONDENSER VALVE FAILS TO CLOSE AT
OFFSHORE WEATHERING SYSTEM REQUIRED AT
DECONTAMINATION AREA DRYDOWN VALVES MAY FAIL PSAM VALVES AT
PUMP IN PRELIMINARY AMPLIFIED RESPONSE SPECTRA P-4

200 20
0 SURVEILLANCE CHECKS NOT PERFORMED AT MAIN YANKEE
0 SURVEILLANCE ACTION COULD REDUCE SAFETY MARGIN AT ZION 1
0 SURVEILLANCE TEST PERFORMED LATE AT PRAIRIE ISLAND 10
0 SURVEILLANCE TESTING NOT PERFORMED AS REQUIRED AT COON 10
0 SURVEILLANCE TESTS NOT PERFORMED AT COON 10
0 SURVEILLANCE TESTS NOT PERFORMED ON SCHEDULE AT COON 10
0 SUSPENDED SILENOS IN EFFLUENT EXCEEDS LIMIT AT THREE MILE
SWITCH AT ST. CALMEAD
SWITCH AT GINNEP
SWITCH AT OCONEE 30
SWITCH AT PRAIRIE ISLAND 10
SWITCH AT PRAIRIE ISLAND 20
SWITCH AT SURREY 20
SWITCH AT THREE MILE ISLAND 10
SWITCH AT TURNER POINT 30
SWITCH AT YANKEE NGEP
SWITCH AT ZION 10
SWITCH CALIBRATED INCORRECTLY AT POINT BEACH 10
SWITCH FAILS AT PRAIRIE ISLAND 20
SWITCH IN W/ CONTROL CIRCUIT FAILS AT THREE MILE ISLAND
SWITCHES AT 1, 2, AND 30
SWITCHES AT 150
SWITCHES AT 1 ISLAND 20
SWITCHES AT 1 MILE ISLAND 10
SWITCHES NOT PERFORMED AT YANKEE NGEP
SWITCHES SET W/IN-CONSERVATIVE AT WILLSTONE 20
SWITCHING SYSTEM AT PRAIRIE 1 AND 20
SYSTEM AC OPERATOR CABINETS DEFICIENCY AT THREE MILE ISLAND
SYSTEM ANALYSIS AT ARKANSAS NUCLEAR 10
SYSTEM AT COON 10
SYSTEM AT PRAIRIE 1 AND 20
SYSTEM AT PRAIRIE ISLAND 10
SYSTEM AT RANCHO SECOP
SYSTEM AT RANCHO SECOP
SYSTEM AT ZION 10
SYSTEM BOMM CONCENTRATION DILUTED AT SURREY 10
SYSTEM CAPACITY BELOW LIMITS AT SURREY 20
SYSTEM COOLDOWN RATE EXCESSIVE AT OCONEE 30
SYSTEM DEFICIENCY AT SURREY 20
SYSTEM DESIGN DEFICIENCY FOUND AT SAN ONOFRE 10
SYSTEM FAILS AT CALVERT CLIFFS 10
SYSTEM FAILS AT OCONEE 30
SYSTEM FAILS AT ROBINSON 20
SYSTEM FAILURE AT ROBINSON 20
SYSTEM FULL AT OCONEE 20
SYSTEM FLOW DISTRIBUTION FAILS TO MEET SPECS AT MAINE
SYSTEM FLUID FLOW INSTABILITY AT CONNECTICUT YANKEE
SYSTEM FOUND UNSATISFACTORY AT COON 10
SYSTEM INCREASES AT OCONEE 40
SYSTEM INSUPERABLE AT PRAIRIE ISLAND 10
SYSTEM LEAKAGE EXCEEDS LIMIT AT PALESAUES
SYSTEM LEAKAGE HIGH AT OCONEE 30
SYSTEM LOCKED OUT AT YANKEE
SYSTEM LOGIC MODULE FAILS AT CALVERT CLIFFS 10
SYSTEM LOGIC MODULE FAILS AT CALVERT CLIFFS 10
SYSTEM MAIN CONDENSER VALVE FAILS TO CLOSE AT SURREY 20
SYSTEM MALFUNCTION AT COON 10
SYSTEM MAY NOT DRAW DOWN UNIFORMLY AT ARKANSAS NUCLEAR 10
SYSTEM MISALIGNMENT AT ST. LUCIE 10
SYSTEM MODULE FAILS AT CALVERT CLIFFS 10
SYSTEM NOT CALIBRATED ON SCHEDULE AT COON 10
SYSTEM NOT PROPERLY ISOLATED AT SURREY 10
SYSTEM NOZZLES BLOCKED AT RANCHO SECOP
SYSTEM OVERPRESSURIZED AT ST. LUCIE 10
SYSTEM OVERPRESSURIZED AT ZION 20
SYSTEM OVERPRESSURIZED UNINTENTIONALLY AT TROJAN
SYSTEM OXYGEN CONCENTRATION EXCEEDS LIMIT AT ROBINSON 20
SYSTEM OXYGEN CONCENTRATION EXCEEDS LIMITS AT ROBINSON 20
SYSTEM PACKING LEAK LEAK AT CONNECTICUT YANKEE
SYSTEM PIPE CRACKS AT ARKANSAS NUCLEAR 10
SYSTEM PIPING AT PRAIRIE ISLAND 20
SYSTEM PIPING CLASSIFICATION IN ERROR AT CALVERT CLIFFS 10
SYSTEM RELAY FAILS TO LATCH AT YANKEE
SYSTEM REQUIRED AT SURREY 1 AND 60
SYSTEM SOCKET WELD LEAK AT ST. LUCIE 10
SYSTEM TANK INSUPERABLE AT PRAIRIE ISLAND 20
SYSTEM VALVE FAILS TO CLOSE AT POINT BEACH 10
SYSTEM VALVE FAILS TO OPEN AT INDIAN BEACH 20
SYSTEM VALVE FAILS TO OPEN AT INDIAN POINT 20
SYSTEM VALVE FAILS TO OPEN AT RANCHO SECOP
SYSTEM VALVE FAILS TO OPEN AT ZION 20
SYSTEM VALVE FOUND CLOSED AT MAINE YANKEE

0 000093 P100
102530 P102
107420 P106
109505 P108
100510 P100
100008 P 04
102539 P237
102909 P144
104403 P 41
103003 P 35
103005 P 30
104201 P200
104050 P 59
100519 P 60
103001 P123
100527 P149
100730 P152
104057 P105
100205 P210
100271 P226
004201 P230
100286 P240
100400 P130
104550 P152
100570 P211
103057 P103
102314 P120
102100 P150
103029 P206
100967 P230
100599 P 52
100026 P 02
100430 P 53
003600 P19
105521 0
100405 P 60
100430 P 53
104004 P106
101044 P157
103002 P160
103040 P237
100267 P100
102550 P191
103092 P122
101731 P192
101411 P171
104999 P 24
107007 P125
102377 P106
103003 P106
100255 P119
100000 00
100240 P117
102136 P104
100107 P134
100260 P104
107703 P 02
093552 P 17
093025 P 17
102533 P192
100372 P 46
103009 P 55
100900 P176
103257 P 16
107779 P 60
100204 P101
100222 P103
100515 P157
100403 P250
100906 P221
100440 P100
103004 P106
101154 P 31
105520 P 0
100034 P153
100072 P 20
102009 P 20
107420 P100
107005 P170
100490 P152
100707 P130
101407 P 71
102554 P 71
100432 P162
107093 P251
100916 P 04

02404944 SYSTEM VALVE LINEUP FOLLOWING MAINTENANCE AT TOWER 10 009716 P103
 MANUAL FEEDBACK OF HEAT REJECTION SYSTEM VALVES FAIL AT TOWER 2 AND 30 121157 P111
 02405000 SYSTEM VALVES PUMP MANUALLY INOPERABLE AT TOWER 10 100750 P107
 02405000 SYSTEM VENT LINE CRACKS AT DRAIN VALVE 10 126375 P 14

02405000 BORE FLOOD DISCHARGE VALVES NOT 003621 P109
 02405000 BORE AND DRINKING WATER SAMPLES NOT 126365 P171
 02405000 BORE AND DRINKING WATER SAMPLES NOT 100201 P260
 02405000 BORE AND DRINKING WATER SAMPLES NOT 100200 P253
 02405000 BORE AND DRINKING WATER SAMPLES NOT 100479 P209
 02405000 BORE ACID PUMP 107001 P 40
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 105103 P116
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100632 P236
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100602 P176
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 003565 P225
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 122159 P 21
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100475 P 26
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100478 P 35
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100911 P 36
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 003565 P225
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 000675 P262
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 122171 P265
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 000915 P261
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100480 P269
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100511 P103
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100535 P 79
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100510 P106
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100506 P150
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100527 P220
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100507 P 85
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100505 P161
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100509 P 55
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100513 P196
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100517 P213
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100503 P110
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100509 P113
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100519 P117
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100517 P 83
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100515 P 43
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100513 P 12
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100522 P136
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100501 P123
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100503 P196
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100506 P196
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100506 P112
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100503 P195
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100506 P223
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100506 P260
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100503 P 34
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100503 P160
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100503 P189
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100503 P113
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100526 P195
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100607 P 47
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100479 P229
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100309 P211
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100306 P159
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100553 P 71
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100559 P239
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100001 P 76
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100449 P137
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100077 P 61
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100729 P102
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100501 P221
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100524 P119
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100503 P 26
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100505 P172
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100505 P172
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100508 P 67
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100506 P208
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100516 P105
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100506 P 95
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100506 P190
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100503 P157
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100528 P143
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100528 P110
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100520 P216
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100509 P 86
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100503 P100
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100503 P195
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100503 P106
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100527 P169
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100520 P 26
 02405000 BORE TRAIN UP REACTOR BUILDING SPRAY INADEQUATELY 100503 P 28

[illegible]

DELAY HEAT PUMP SUCTION VALVE FAILS TO CLOSE AT	THREE MILE ISLAND 10	099121 P199
INTERNAL HANDLING FIXTURE SPHERICAL NOT LOOSE AT	THREE MILE ISLAND 10	093496 P205
UNPLANNED RELEASE OF RADIOACTIVE GAS AT	THREE MILE ISLAND 10	108761 P217
ESCAPE OF CONCENTRATED AMEL ACT. SOLUTION NOT OPERABLE AT	THREE MILE ISLAND 10	107692 P219
SAMPLE NOT TAKEN DURING WASTE TANK RELEASE AT	THREE MILE ISLAND 10	104979 P209
CONCENTRATIONS IN EFFLUENT SAMPLE EXCEED LIMIT AT	THREE MILE ISLAND 10	103237 P214
UNPLANNED RELEASE OF RADIOACTIVE MATERIAL AT	THREE MILE ISLAND 10	106967 P214
CONTAINER ROOS IMPERMEABLE AT	THREE MILE ISLAND 10	108254 P216
OPPRESSURE SWITCH IN VALVE CONTROL CIRCUIT FAILS AT	THREE MILE ISLAND 10	105720 P211
VOLTAGE RELAY CONTACTS OF DIESEL GENERATOR STICK AT	THREE MILE ISLAND 10	108261 P217
HYDRAULIC SHOCK SUPPRESSOR FOUND TO BE DISCONNECTED AT	THREE MILE ISLAND 10	106969 P216
QUALITY USED PRIOR TO CHECKING OF DOCUMENTATION AT	THREE MILE ISLAND 10	108235 P217
TEMPERATURE DIFFERENTIAL ACROSS THE PLANT EXCEEDS LIMIT AT	THREE MILE ISLAND 10	108209 P216
MANUAL ISOLATION VALVES IN AIR LINE FOUND CLOSED AT	THREE MILE ISLAND 10	102605 P213
DEFICIENCIES FOUND IN RIP MAP OF DIKES AT	THREE MILE ISLAND 10	106969 P213
CONCENTRATION OF TRITIUM IN RIVER WATER EXCEEDS LIMIT AT	THREE MILE ISLAND 10	108236 P215
BOE-ICE MAKE UP VALVE FAILS TO CLOSE AT	THREE MILE ISLAND 10	102604 P212
BOE-ICE FLOOD TANK SAMPLE LINE FAILS TO CLOSE AT	THREE MILE ISLAND 10	106308 P211
BOE-ICE FLOOD TANK LEVEL FOUND TO BE LESS THAN LIMITS AT	THREE MILE ISLAND 10	104517 P223
UNPLANNED RELEASES OF RADIOACTIVE MATERIAL AT	THREE MILE ISLAND 10	108239 P217
UNPLANNED RELEASE OF RADIOACTIVE MATERIAL OCCURS AT	THREE MILE ISLAND 10	106107 P212
UNPLANNED RELEASE OF RADIOACTIVE MATERIAL AT	THREE MILE ISLAND 10	108240 P216
BOE-ICE MAKE UP TANK WELLET LINE BLOCKED AT	THREE MILE ISLAND 10	107608 P214
BOE-ICE MAKE UP VALVE NOT SCIENTIFICALLY QUALIFIED AT	THREE MILE ISLAND 10	106617 P213
BOE-ICE CONCENTRATION IN SAMPLE EXCEEDS CONTROL LEVEL AT	THREE MILE ISLAND 10	107607 P214
PERCESSION COOLING OF THE COOLING TOWER DISCHARGE AT	THREE MILE ISLAND 10	105526 P210
RADIOACTIVITY IN EFFLUENT EXCEEDS CONTROL VALUE AT	THREE MILE ISLAND 10	105473 P210
UNPLANNED RELEASE OF RADIOACTIVE MATERIAL OCCURS AT	THREE MILE ISLAND 10	105566 P210
COOLING TOWER DISCHARGE COOLED EXCESSIVELY AT	THREE MILE ISLAND 10	105722 P211
BUCKET WELD IN MAKE-UP PUMP SUCTION VENT LINE LEAKS AT	THREE MILE ISLAND 10	106311 P210
UNPLANNED RELEASE OF RADIOACTIVE MATERIAL AT	THREE MILE ISLAND 10	106312 P210
TRITIUM LEVEL IN EFFLUENT EXCEEDS CONTROL VALUE AT	THREE MILE ISLAND 10	107525 P215
INCORRECT ULTRAVIOLET DETECTION INSTALLED AT	THREE MILE ISLAND 10	106306 P212
STEAM GENERATOR SAMPLE LINE VALVE FOUND IMPERMEABLE AT	THREE MILE ISLAND 10	106976 P214
RESET POINT DRIFT IN PRESSURE SWITCH AT	THREE MILE ISLAND 10	109285 P218
UNPLANNED RELEASE OF GASEOUS RADIOACTIVITY AT	THREE MILE ISLAND 10	109284 P218
BOE-ICE HYDRAULIC SHOCK SUPPRESSOR IMPERMEABLE AT	THREE MILE ISLAND 10	101655 P203
HYDRAULIC SHOCK SUPPRESSOR FAILS AT	THREE MILE ISLAND 10	093497 P201
DELAY HEAT RIVER WATER PUMP SHUT FAILS AT	THREE MILE ISLAND 10	103672 P206
SUSPENDED SOLIDS IN EFFLUENT EXCEEDS LIMIT AT	THREE MILE ISLAND 10	106201 P208
UNPLANNED WIRING FOUND IN REACTOR CONTROL CENTER AT	THREE MILE ISLAND 10	103093 P207
RESET POINT DRIFT IN REACTOR COOLANT PRESSURE SWITCHES AT	THREE MILE ISLAND 10	103679 P206
UNPLANNED RADIOACTIVE GAS RELEASE AT	THREE MILE ISLAND 10	093508 P201
RESET POINT DRIFT IN TEMPERATURE DISCHARGE AT	THREE MILE ISLAND 10	103886 P208
RESET POINT DRIFT IN PRESSURE TRANSMITTER AT	THREE MILE ISLAND 10	103887 P207
UNCLEAN SERVICES RIVER WATER PUMP VALVE FAILS TO CLOSE AT	THREE MILE ISLAND 10	106694 P209
BOE-ICE FLOOD TANK HEATING PLATE FOR MAIN STEAM LINE AT	THREE MILE ISLAND 10	102533 P205
UNPLANNED RELEASE OF AIRBORNE RADIOACTIVITY AT	THREE MILE ISLAND 10	100364 P232
CONCENTRATION IN RIVER WATER DISCHARGE EXCEEDS LIMITS AT	THREE MILE ISLAND 10	099573 P231
CONTROL AND DRIVE BREAKER FAILS TO TRIP AT	THREE MILE ISLAND 10	102577 P235
UNPLANNED RELEASE OF RADIOACTIVE GAS OCCURS AT	THREE MILE ISLAND 10	103888 P209
BUCKET WELD JOINTS LEAK IN VENT LINE OF MAKE-UP PUMPS AT	THREE MILE ISLAND 10	106308 P210
OVERLOAD PERFORMED WORK NOT CONTROLLED ADEQUATELY AT	THREE MILE ISLAND 10	103889 P207
FREQUENCY RELAY FOR DIESEL GENERATOR FAILS AT	THREE MILE ISLAND 10	104859 P209
CONTAINER ROOS NOT DECLARED IMPERMEABLE WHEN MISALIGNED AT	THREE MILE ISLAND 10	103084 P232
RESET POINT DRIFT IN REACTOR COOLANT PRESSURE CHANNEL AT	THREE MILE ISLAND 10	103630 P206
REACTION BUILDUP EMERGENCY COOLER INLET VALVE FAILS AT	THREE MILE ISLAND 10	103915 P202
TRITIUM CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT	THREE MILE ISLAND 10	103473 P206
TRITIUM CONCENTRATION IN RIVER WATER EXCEEDS LIMITS AT	THREE MILE ISLAND 10	103469 P205
TRITIUM CONCENTRATION IN RIVER WATER EXCEEDS LIMITS AT	THREE MILE ISLAND 10	102671 P204
UNPLANNED RELEASE OF RADIOACTIVE GAS OCCURS AT	THREE MILE ISLAND 10	101662 P203
UNPLANNED RELEASE OF RADIOACTIVE GAS OCCURS AT	THREE MILE ISLAND 10	106860 P209
RESET POINT DRIFT IN PRESSURE TRANSMITTERS AT	THREE MILE ISLAND 10	102670 P203
UNPLANNED RELEASE OF RADIOACTIVE GAS OCCURS AT	THREE MILE ISLAND 10	093509 P201
PERCESSION COOLING CONCENTRATION IN DISCHARGE AT	THREE MILE ISLAND 10	102139 P203
HYDRAULIC SHOCK SUPPRESSOR IMPERMEABLE AT	THREE MILE ISLAND 10	102608 P204
TRITIUM CONCENTRATION IN RIVER WATER EXCEEDS LIMIT AT	THREE MILE ISLAND 10	103890 P207
REACTOR BUILDUP PURGE ISOLATION VALVE LEAKS EXCESSIVELY AT	THREE MILE ISLAND 10	0105721 P211
REACTOR BUILDUP PURGE SUPPLY VALVE FAILS TO FULLY CLOSE AT	THREE MILE ISLAND 10	0107693 P215
OPERATION FAILS TO CARRY MONITOR INTO HIGH RADIATION AREA AT	THREE MILE ISLAND 10	0104970 P239
DISSOLVED SOLIDS CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT	THREE MILE ISLAND 10	0106325 P212
AVAILABILITY OF EMERGENCY SHUTDOWN COOLING WATER LIMITED AT	THREE MILE ISLAND 10	0107591 P215
NUD PROGRAM VERIFICATION INADEQUATELY IMPLEMENTED AT	THREE MILE ISLAND 10	010686 P209
POWER INCREASE ABOVE POWER LEVEL CUT OFF FOR 100 SOPS AT	THREE MILE ISLAND 10	010686 P209
RIVER WATER SAMPLE INDICATED RESULTS EXCEED LIMIT AT	THREE MILE ISLAND 10	0102143 P204
TOTAL CHLORINE CONCENTRATION IN PLANT DISCHARGE AT	THREE MILE ISLAND 10	0102469 P234
REPORT ON RADIOACTIVE GAS BUILDUP IN AUXILIARY BUILDING AT	THREE MILE ISLAND 10	0102469 P234
EMERGENCY COOLING RIVER WATER PUMP FAILS TO START AT	THREE MILE ISLAND 10	0102469 P234
ALTERNATE AXIAL INDICATION FOUND IN AC PUMP RUTS AND STUDS AT	THREE MILE ISLAND 10	0104974 P220
BOE-ICE ROUTINE AND PULLING DEFICIENCY AT	THREE MILE ISLAND 10	0102649 P220
BOE-ICE FOUND IN PULP HANDLING BUILDING WALL AT	THREE MILE ISLAND 10	0105119 P220
REACTOR BUILDING CABLE TRAY PAINTING FOUND DEFICIENT AT	THREE MILE ISLAND 10	0106187 P220
INTERIOR CONCRETE BLOCK WALLS NOT SEISMICALLY QUALIFIED AT	THREE MILE ISLAND 10	0106187 P220
FLOW CONCRETE CYLINDER TEST STRENGTHS (SUPPLEMENT) AT	THREE MILE ISLAND 10	0100420 P219
REACTOR BUILDING SPRAY PUMP MOTOR MODIFICATIONS AT	THREE MILE ISLAND 10	0107614 P219
ADDITIONAL INFORMATION ON DEFECTIVE CRANE VALVES AT	THREE MILE ISLAND 10	0103005 P219
CONTROL AND DRIVE SYSTEM AC BREAKER CABINETS DEFICIENCY AT	THREE MILE ISLAND 10	093600 P219
RECHARGING LINE VALVE LEAKS	THREE MILE ISLAND 10	0104005 P127
PROCEDURAL DEFICIENCIES FOUND AT PALISADES	THREE MILE ISLAND 10	0103922 P 73
THROUGH PLUG AT INDIAN POINT 20		

ADDITIONAL INFORMATION ON INACTIVE RELEASE THROUGH SUMP AT OCONEE 20 109200 P119
 THROUGH WELL LEAK IN CHARGING LINE VENT PIPING AT KEMAUKEE 093257 P 77
 TILT EXCEEDS LIMIT AT SURRY 20 100354 P101
 TILTS IN EXCESS OF LIMIT AT SURRY 20 131700 P102
 TIME AT COOK 10 106386 P 46
 TIME AT COOK 10 103540 P 39
 TIME AT FT. CALHOUN 109207 P 41
 TIME AT FT. CALHOUN 106293 P 59
 TIME AT FT. CALHOUN 108077 P 61
 TIME AT FT. CALHOUN 137636 P 60
 TIME AT FT. CALHOUN 133444 P 58
 TIME AT POINT BEACH 1 AND 20 093208 P142
 TIME AT ZION 20 106965 P251
 TIME DELAY SETTING FOUND TO BE INCORRECT AT HILLSTONE 20 109254 P 96
 TIME DURING LOAD CHANGE AT KEMAUKEE/SCONKIN PUBLIC 102114 P 78
 TIME EXCEEDS LIMIT AT POINT BEACH 20 099365 P139
 TIME INTERVAL AT WAINE YAMKEE 106376 P 06
 TIME LIMIT AT POINT BEACH 1 AND 20 102566 P142
 TIME OF STEAM GENERATOR VALVE EXCEEDS LIMIT AT COOK 10 100020 P 50
 TIME SLUG AT COOK 10 104695 P 42
 TIME-DELAY RELAY AT COOK 10 103097 P 38
 TIMES RELAYS AT FT. CALHOUN 106634 P 60
 TIMES EXCEED LIMIT AT POINT BEACH 10 093617 P135
 TIMES SLUG AT COOK 10 106697 P 43
 TOLERANCE REACTOR INTERVALS AT CALVERT CLIFFS 20 106667 P 28
 TOO LOW AT CALVERT CLIFFS 10 100096 P 29
 TOO LOW AT OCONEE 20 102546 P112
 TOO RAPIDLY AT SURRY 1 AND 20 104736 P198
 TOO SLUG AT THREE MILE ISLAND 10 104086 P207
 TUBE DAMAGED AT INDIAN POINT 30 102532 P 76
 TUBE OF ICE CONDENSER DOWNS EXCEEDS LIMIT AT COOK 10 108074 P 49
 TOTAL CHLORINE CONCENTRATION IN PLANT DISCHARGE AT THREE 102449 P204
 TOTAL CHLORINE CONCENTRATION IN RIVER EXCEEDS LIMIT AT 102648 P204
 TOWER BLOWDOWN FLOW EXCEEDS LIMITS AT PRAIRIE ISLAND 1 AND 2 105527 P195
 TOWER BLOWDOWN RATE EXCEEDS LIMIT AT PRAIRIE ISLAND 1 AND 2 106791 P154
 TOWER BLOWDOWN RATE SLIGHTLY EXCEEDS LIMIT AT PRAIRIE 109288 P149
 TOWER DISCHARGE AT THREE MILE ISLAND 10 105526 P210
 TOWER DISCHARGE COOLED EXCESSIVELY AT THREE MILE ISLAND 10 105722 P211
 TOWER REMOVED FROM SERVICE AT PRAIRIE ISLAND 1 AND 20 106309 P155
 TRAC TIME DELAY SETTING FOUND TO BE INCORRECT AT HILLSTONE 109254 P 96
 TRACING CHANNEL INOPERABLE AT POINT BEACH 10 103403 P136
 TRACING CIRCUIT FAILS AT SURRY 10 106880 P106
 TRACING CIRCUIT FOUND TO BE OPEN AT INDIAN POINT 20 093180 P 74
 TRACING CIRCUIT INOPERATIVE AT COOK 10 103875 P 48
 TRAM FAILS TO OPERATE AT SURRY 20 102542 P193
 TRAM INOPERABLE AT PRAIRIE ISLAND 20 106692 P152
 TRAM NOT PROVIDED AS REQUIRED AT OCONEE 20 105280 P116
 TRAM NOT PROVIDED WHEN REQUIRED AT OCONEE 20 099702 P109
 TRAM NOT TESTED AT COOK 10 100887 P 35
 TRAM OF REACTOR BUILDING SPRAY INADVERTENTLY TAKEN OUT OF 105180 P116
 TRAMING NOT DOCUMENTED AT GINNA 109053 P 65
 TRAMS OUT OF SERVICE CONCURRENTLY AT KEMAUKEE 106379 P 81
 TRANSFER APPARATUS AND HANDLING TOOL DAMAGED AT INDIAN 102532 P 76
 TRANSFER AT OCONEE 20 105071 P114
 TRANSFER FROM STATION POWER TO START-UP POWER AT PALISADES 104044 P129
 TRANSFER OF STEAM GENERATOR LEVEL CONTROL VIOLATES 106618 P 48
 TRANSFER PUMP FAILS AT COOK 10 104956 P 43
 TRANSFER PUMP FAILS AT INDIAN POINT 20 100532 P 75
 TRANSFER PUMP FAILS AT ROBINSON 20 100580 P105
 TRANSFER PUMP FAILS AT ROBINSON 20 106213 P106
 TRANSFER PUMP FAILS AT ROBINSON 20 103199 P106
 TRANSFER PUMP FAILS AT ROBINSON 20 093250 P104
 TRANSFER PUMP FLOW RATE LESS THAN SPECS AT COOK 10 106945 P 43
 TRANSFER PUMP MOTOR FAILS AT SURRY 20 107695 P196
 TRANSFER PUMP REMOVED FROM SERVICE AT COOK 10 109273 P 49
 TRANSFER PUMP REMOVED FROM SERVICE AT COOK 10 109272 P 49
 TRANSFER PUMP REMOVED FROM SERVICE AT COOK 10 106606 P 47
 TRANSFER PUMP REMOVED FROM SERVICE AT INDIAN POINT 20 107981 P 75
 TRANSFERRED TO CONTAINMENT BASIN AT GINNA 105297 P 67
 TRANSFER DEFICIENCIES FOUND AT FARLEY 1 AND 20 106275 P 53
 TRANSFORMER FAILS AT TURKEY POINT 30 103103 P222
 TRANSIENT IN MAIN COOLING SYSTEM AT ZION 10 103646 P237
 TRANSIENT XENON AT OCONEE 20 099326 P105
 TRANSIENT XENON CONDITIONS AT OCONEE 30 104382 P123
 TRANSMISSION LINE AT OCONEE 10 107227 P106
 TRANSMITTER AT HILLSTONE 20 108820 P 96
 TRANSMITTER AT OCONEE 10 101445 P102
 TRANSMITTER AT OCONEE 20 101775 P111
 TRANSMITTER AT OCONEE 20 101168 P111
 TRANSMITTER AT OCONEE 20 099021 P108
 TRANSMITTER AT OCONEE 20 099729 P107
 TRANSMITTER AT THREE MILE ISLAND 10 108067 P207
 TRANSMITTER AT ZION 10 103895 P237
 TRANSMITTER DRIFT AT ZION 20 093260 P262
 TRANSMITTER FAILS AT ZION 20 103444 P267
 TRANSMITTER LINE LEAKS AT YAMKEE ROWE 100366 P230
 TRANSMITTERS AT RANCHO SEC70 102165 P157
 TRANSMITTERS AT SURRY 10 107431 P187

ORBIT POINT DRIFT IN PRESSURE TRANSMITTERS AT THREE MILE ISLAND 10 105400 P209
 ORBIT POINT DRIFT IN FLOW TRANSMITTERS AT ZION 10 107510 P239
 ORBIT POINT DRIFT IN PRESSURIZER LEVEL TRANSMITTERS AT ZION 20 106520 P252
 OFISH TRAPPED IN THE INTAKE STRUCTURE AT PRAIRIE ISLAND 1 AND 20 131110 P156
 OPENURE LEAK FLOW ON CRU 400 TRAPPER HOUSING AT GINNAF 107255 P165
 FAILURE TO CONDUCT INLEAK DETECTOR TRAVERSES ON SCHEDULE AT ROBINSON 20 107411 P163
 ORACLE TRAY HOLD-DOWN CLIPS INADEQUATE FOR HORIZONTAL LOAD AT 107003 P174
 ORCAUTION BUILDING, CABLE TRAY PAINTING FOUND DEFICIENT AT THREE MILE ISLAND 20 106107 P223
 ORSEALING TREATMENT PLANT EFFLUENT BOD EXCEEDS LIMIT AT FT. CALHOUN 107900 P157
 ORSEALING TRIGGER NOT TESTED AS REQUIRED AT CTOR 10 105732 P145
 ORSHOUT RELAY FAILS TO TRIP AT FT. CALHOUN 099273 P156
 ORSHOUT RELAY FAILS TO TRIP AT FT. CALHOUN 099600 P156
 ORSHOUT BUS BREAKER TRIPS CAUSING A UNIT TRIP AT MAINE YANKEE 107436 P183
 ORSHOUT POWER LEVEL TRIP DISTABLE FAILS TO TRIP AT MAINE YANKEE 107913 P186
 ORSHOUT AND DRIVE BREAKER FAILS TO TRIP AT OCONEE 30 105174 P124
 ORSHOUT PRESSURE CHANNEL DISTABLE FAILS TO TRIP AT POINT BEACH 10 105510 P137
 ORSHOUT AND DRIVE BREAKER FAILS TO TRIP AT THREE MILE ISLAND 10 102527 P205
 ORSHOUT PRESSURE COMPARTMENT FAILS TO TRIP AT TURKEY POINT 30 105454 P224
 ORSHOUT PURGE FAILS TO TRIP AT ZION 20 102477 P240
 ORSHOUT PURGE FAILS TO TRIP AT ZION 20 102126 P245
 ORSHOUT POWER LEVEL TRIP DISTABLE FAILS TO TRIP AT MAINE YANKEE 107913 P186
 ORSHOUT NOT PERFORMED ON TIME AT CTOR 10 106100 P146
 ORSHOUT DEVICE INSTALLED IN CORRUPT BREAKER AT CTOR 10 099809 P136
 ORSHOUT DUE TO LOSS OF INSTRUMENT BUSES AT ROBINSON 20 093262 P169
 ORSHOUT TRIP UNUSUAL AT ROBINSON 20 102406 P159
 ORSHOUT LOST OUT OF SPEC AT FT. CALHOUN 101641 P158
 ORSHOUT MECHANISM ON MAIN STEAM STOP VALVE FAILS AT POINT BEACH 10 103666 P161
 ORSHOUT MECHANISM ON MAIN STEAM STOP VALVE FAILS AT POINT BEACH 10 106117 P161
 ORSHOUT MECHANISM ON MAIN STEAM STOP VALVE FAILS AT POINT BEACH 10 107376 P135
 ORSHOUT SET POINT AT PRAIRIE ISLAND 20 105253 P153
 ORSHOUT SET POINT RAMPING 30 AT HILLSTONE 20 107622 P195
 ORSHOUT SET POINT SHIFT WITH POWER AT HILLSTONE 20 106445 P192
 ORSHOUT SET POINTS DRIFT AT PRAIRIE ISLAND 10 105729 P167
 ORSHOUT SETPOINT REPORTED HIGH AT ZION 20 102020 P254
 ORSHOUT SETTINGS IMPROPER AT PRAIRIE ISLAND 20 106173 P152
 ORSHOUT SIGNAL AT ROBINSON 20 093573 P164
 ORSHOUT VALVE CLOSURE SPONTANEOUSLY AT SUNNY 20 106219 P194
 ORSHOUT VALVE FAILS TO CLOSE AT MAINE YANKEE 106931 P187
 ORSHOUT VALVE LEAKS EXCESSIVELY AT MAINE YANKEE 106863 P234
 ORSHOUT VALVE SOLENOIDS FAIL TO OPERATE AT MAINE YANKEE 106306 P233
 ORSHOUT POSITION AT CTOR 10 105200 P140
 ORSHOUT TRIPS AT GINNAF 093274 P157
 ORSHOUT TRIPS AT MAINE YANKEE 102492 P170
 ORSHOUT TRIPS AT SAN ONOFRE 10 093549 P170
 ORSHOUT TRIPS AT TURKEY POINT 30 104479 P223
 ORSHOUT CAUSING A UNIT TRIP AT MAINE YANKEE 104436 P193
 ORSHOUT TRIPS DURING EMERGENCY START TEST AT OCONEE 10 103350 P103
 ORSHOUT TRIPS FROM HIGH COOLING WATER TEMP. TURE AT SAN ONOFRE 10 106455 P172
 ORSHOUT TRIPS FROM HIGH COOLING WATER TEMP. TURE AT SAN ONOFRE 10 105454 P172
 ORSHOUT TRIPS ON LOW LUBE OIL PRESSURE AT ROBINSON 20 101781 P165
 ORSHOUT TRIPS ON OVERCURRENT AT MAINE YANKEE 101311 P170
 ORSHOUT TRIPS ON OVERLOAD AT PRAIRIE ISLAND 10 103645 P165
 ORSHOUT CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT OCONEE 107946 P157
 ORSHOUT CONCENTRATION IN EFFLUENT EXCEEDS LIMIT AT THREE MILE ISLAND 10 103473 P206
 ORSHOUT CONCENTRATION IN RIVER WATER EXCEEDS LIMITS AT 103449 P205
 ORSHOUT EXCEEDS LIMIT AT OCONEE 10 105955 P157
 ORSHOUT FOUND IN COMPONENT COOLING SYSTEM AT RANCHO SECOR 103602 P163
 ORSHOUT IN RIVER WATER EXCEEDS LIMIT AT THREE MILE ISLAND 10 103236 P215
 ORSHOUT LEVEL IN EFFLUENT EXCEEDS CONTROL VALUE AT THREE MILE ISLAND 10 107525 P215
 ORSHOUT TROUBLE 106150 P221
 ORSHOUT TUBE DEGRADATION FOUND AT YANKEE RIVER 107632 P221
 ORSHOUT TUBE DETERIORATION AT SUNNY 1 AND 20 107385 P233
 ORSHOUT TUBE FAILS AT POINT BEACH 10 093261 P197
 ORSHOUT TUBE FAILS AT POINT BEACH 10 107257 P135
 ORSHOUT TUBE FAILURE AT POINT BEACH 10 107507 P135
 ORSHOUT TUBE LEAK AT PRAIRIE ISLAND 20 103925 P137
 ORSHOUT TUBE LEAK AT POINT BEACH 20 103425 P150
 ORSHOUT TUBE PULL APART AT SUNNY 10 106513 P161
 ORSHOUT TUBES AT GINNAF 106252 P188
 ORSHOUT TUBES AT SUNNY 10 101700 P154
 ORSHOUT TURBIDITY IN PLANT CIRCULATING WATER INCREASES AT ARKANSAS 105470 P189
 ORSHOUT TURBIDITY INCREASE ACROSS PLANT EXCEEDS LIMIT AT ARKANSAS 107201 P13
 ORSHOUT TURBINE DRIVER AUXILIARY PERFORATOR PUMP TRIPS AT GINNAF 106411 P17
 ORSHOUT TURBINE DRIVER AUXILIARY PERFORATOR PUMP TRIPS AT GINNAF 106411 P17
 ORSHOUT TURBINE DRIVER AUXILIARY PERFORATOR PUMP TRIPS AT GINNAF 106411 P17
 ORSHOUT TURBINE FAILURE AT RANCHO SECOR 103805 P163
 ORSHOUT TURBINE RAMP SURP DISCHARGE EXCEEDS LIMIT AT CTOR 10 099382 P134
 ORSHOUT TURBINE RAMP SURP DISCHARGE EXCEEDS LIMITS AT CTOR 10 099105 P133
 ORSHOUT TURBINE RAMP SURP DISCHARGE OUT OF LIMITS AT CTOR 10 099116 P133
 ORSHOUT TURBINE RAMP SURP DISCHARGE OUT OF LIMITS AT CTOR 10 102160 P21
 ORSHOUT TURBINE POINT 10 107410 P220
 ORSHOUT TURBINE POINT 3 AND 40 105543 P220
 ORSHOUT TURBINE POINT 10 104303 P223
 ORSHOUT TURBINE POINT 10 103105 P222
 ORSHOUT TURBINE POINT 10 102312 P222
 ORSHOUT TURBINE POINT 10 105719 P224
 ORSHOUT TURBINE POINT 10 103700 P223

35746 P 153
37257 P 21
380419 P 26
39701 P 62
44241 P 217
53804 P 238
57221 P 110
57533 P 220
58373 P 67
59553 P 27
613474 P 32
67770 P 30
68095 P 60
68513 P 210
68840 P 216
68867 P 216
69615 P 29
69802 P 20
69135 P 25
69940 P 210
69937 P 212
69279 P 103
69309 P 226
69975 P 26
69739 P 217
69904 P 50
61736 P 127
69911 P 36
69920 P 35
69927 P 50
699271 P 50
69213 P 163
69834 P 162
69933 P 31
67622 P 95
69244 P 129
69311 P 210
69308 P 200
69304 P 238
67413 P 162
69259 P 239
62667 P 205
69921 P 8
69689 P 269
69259 P 239
69604 P 112
69330 P 128
67622 P 95
69309 P 27
61451 P 20
69375 P 236
67762 P 133
69277 P 175
695514 P 65
69235 P 217
69644 P 93

35162 P 153
37229 P 151
37555 P 191
41731 P 192
44076 P 14
49600 P 15
53395 P 114
55273 P 210
57525 P 275
59505 P 198
60636 P 93
69113 P 1
61467 P 55
69229 P 66
69300 P 113
69102 P 236
67547 P 103
69219 P 194
69365 P 139
69496 P 62
69367 P 135
69497 P 63
69720 P 211
69097 P 120
69390 P 120
69706 P 24
69829 P 50
69567 P 125
694071 P 89

[illegible]

LEAKAGE AT YAMNIE HOLEP	0	VENTILATION CONTAINER DRAIN LINE VALVE FAILS TO CLOSE AT YAMNIE	130410	P132
	0	VENTILATION ELECTRICAL PENETRATION HAS RECESSIVE	130400	P130
	0	VENTILATION CONTAINER LEAKAGE EXCEEDS LIMITS AT YAMNIE HOLEP	130552	P132
YAMNIE HOLEP	0	VENTILATION TRIP VALVE LEANS EXCESSIVELY AT YAMNIE HOLEP	130600	P130
WILLSTONE 20	0	VENTILATION TRIP VALVE SCHEMatics FAIL TO OPERATE AT	130600	P130
ADDITIONAL INFORMATION ON RADIOACTIVITY IN AQUATIC	0	VARIABLE OVERPOWER TRIP SET POINT SHIFT WITH POWER AS	130600	P 02
MILE ISLAND 10	0	VEGETATION AT OCCURE 1, 2, AND 30	130700	P107
	0	VENTILATION PERFORMED WORK NOT CONTAINED ADEQUATELY AT THREE	130800	P108
	0	VENTILATION ACTIVITY HIGH AT SURRY 10	130900	P109
	0	VENTILATION FAN FAILS TO START AT RANCHO SEC10	130900	P109
	0	VENTILATION GASOLINE RADIATION MONITOR LEFT IN CALIBRATE AT SURRY 1	131732	P107
	0	VENTILATION GASOLINE RELEASE EXCEEDS LIMITS AT SURRY 10	130615	P105
	0	VENTILATION GASOLINE RELEASE EXCEEDS 48 OF LIMIT AT SURRY 10	130600	P106
	0	VENTILATION GASOLINE RELEASE HIGH AT SURRY 1 AND 20	130900	P109
ADDITIONAL INFORMATION ON LEAK IN	0	VENT LINE ASSEMBLY AT TURNKEY POINT 40	130300	P225
0 SAFETY INJECTION SYSTEM	0	VENT LINE CRACKS AT BEAVER VALVE 10	130300	P 10
0 SOCKET WELD IN MAKE-UP PUMP SEAL	0	VENT LINE LEAKS AT THREE MILE ISLAND 10	130310	P113
0 SOCKET WELD JOINTS LEAK IN	0	VENT LINE OF MAKE-UP PUMPS AT THREE MILE ISLAND 10	130300	P108
0 THROUGH WALL LEAK IN CHARGING LINE	0	VENT PIPING AT REMANDED	093250	P11
ISLAND 10	0	VENTILATION MONITORING SYSTEM INOPERABLE AT PRAIRIE	132130	P110
	0	VENTILATION REMOVED AT OCCURE 20	107230	P110
	0	VENTILATION VALVE AT ARRANOS NUCLEAR 10	100710	P110
0 INHIBIT LEAK IN REACTION COOLANT PUMP SEAL	0	VENTILATION WITHOUT AUTOMATIC ISOLATION DEVICE AT FT. CALHOUN	100900	P 07
0 RADIOACTIVE WASTE GAS	0	VENTILATION EXHAUST FAN FAILS AT PRAIRIE ISLAND 10	130900	P109
0 AUXILIARY BUILDING	0	VENTILATION EXHAUST FAN TRIPS ON OVERLOAD AT PRAIRIE	130600	P106
ISLAND 10	0	VENTILATION ROOM DAMPER ERROR AT INDIAN POINT 20	101700	P 10
	0	VENTILATION SYSTEM LOCKED OUT AT REMANDED	107700	P 07
	0	VENTILATION SYSTEM INRAIN INOPERABLE AT PRAIRIE ISLAND 20	130600	P132
	0	VENTILATION VENT ACTIVITY HIGH AT SURRY 10	130100	P104
	0	VENTILATION VENT GASOLINE RELEASE EXCEEDS LIMIT AT SURRY 10	130315	P107
SURRY 10	0	VENTILATION VENT GASOLINE RELEASE EXCEEDS 48 OF LIMIT AT	107600	P106

ALL INFORMATION CONTAINED
HEREIN IS UNCLASSIFIED

UNCLASSIFIED
DATE 08-16-2017 BY 60322 UCBAW

1042410 0222
000000 0100

THE UNIVERSITY OF CHICAGO

0. 000000 000000 000000 000000 000000 000000 000000 000000 000000 000000
 000000 000000 000000 000000 000000 000000 000000 000000 000000 000000
 000000 000000 000000 000000 000000 000000 000000 000000 000000 000000
 000000 000000 000000 000000 000000 000000 000000 000000 000000 000000

105713	P 23
070325	P100
100322	P123
100320	P111

[illegible][illegible][illegible][illegible][illegible][illegible]

[illegible][illegible]

NUCLEAR SAFETY

A BIMONTHLY REVIEW JOURNAL PREPARED BY NSIC

Nuclear Safety covers significant developments in the field of nuclear safety.

The scope is limited to topics relevant to the analysis and control of hazards associated with nuclear reactors, operations involving fissionable materials, and the products of nuclear fission.

Primary emphasis is on safety in reactor design, construction, and operation; however, safety considerations in reactor fuel fabrication, spent-fuel processing, nuclear waste disposal, handling of radioisotopes, and related operations are also treated.

Qualified authors are invited to submit interpretive articles, which will be reviewed for technical accuracy and pertinency. Authors will be advised as soon as possible of acceptance or suggested changes. Send inquiries or 3 copies of manuscripts (with the draftsman's original line drawing plus 2 copies, and with continuous-tone glossy prints of photographs plus 2 copies) to Wm. B. Cottrell, Oak Ridge National Laboratory, P.O. Box Y, Oak Ridge, Tennessee 37830.

Nuclear Safety is prepared by the Nuclear Safety Information Center at Oak Ridge National Laboratory for the U.S. Nuclear Regulatory Commission. For subscriptions, address Superintendent of Documents, U.S. Government Printing Office, Washington, D.C. 20402. The subscription rate is \$16.70 per year. Below is an order blank for your convenience.

U.S. GOVERNMENT PRINTING OFFICE
DIVISION OF PUBLIC DOCUMENTS
WASHINGTON, D.C. 20402

OFFICIAL BUSINESS
RETURN AFTER 5 DAYS

POSTAGE AND FEES PAID
U.S. GOVERNMENT PRINTING OFFICE

Name _____
Street _____
City _____ State _____ ZIP _____

To Ensure Prompt, Accurate Shipment, Please Print or Type Address on Mailing Label Above

MAIL ORDER FORM TO:

Superintendent of Documents, U.S. Government Printing Office, Washington, D.C., 20402

Enclosed find \$ _____ (check, money order, or Superintendent of Documents coupons).

Please send me _____ subscriptions to *Nuclear Safety* at
\$16.70 per subscription. (Single issues are sold at \$2.80 per issue.)

Please charge this order _____ Name _____
to my Deposit Account _____ Street _____
No. _____ City _____ State _____ ZIP _____

FOR USE OF SUPT. DOCS.

Enclosed _____
To be mailed _____
later _____
Subscription _____
Refund _____
Coupon refund _____
Postage _____

POSTAGE AND REMITTANCE: Postpaid within the United States, Canada, Mexico, and all Central and South American countries except Argentina, Brazil, Guyana, French Guiana, Surinam, and British Honduras. For these and all other countries, add \$4.20 for each annual subscription; for a single issue, add one-fourth of the single-issue price. Payment should be by check, money order, or document coupons, and **MUST** accompany order. Remittances from foreign countries should be made by international money order or draft on an American bank payable to the Superintendent of Documents or by UNESCO book coupons.

AVAILABILITY OF NSIC DOCUMENTS (Continued)

<u>ORNL/ NSIC</u>	<u>Title</u>	<u>Price</u>
111	Reactor Protection Systems: Philosophies and Instrumentation, Reviews from <i>Nuclear Safety</i> , by E. W. Hagen, July 1973	\$15.00
112	Compilation of Nuclear Standards, 9th Edition, 1972, Part I: United States Activities, by J. P. Blakely, Oct. 1973	\$12.00
113	A Selected Bibliography on Emergency Core Cooling Systems (ECCS) for Light-Water-Cooled Power Reactors (LWRs), by Wm. B. Cottrell, Jan. 1974	\$12.00
114	Annotated Bibliography of Safety-Related Occurrences in Nuclear Power Plants as Reported in 1973, by R. L. Scott and R. B. Callaheer, Nov. 1974	\$15.00
115	Index to <i>Nuclear Safety</i> , A Technical Progress Review by Chronology, Permuted Title, and Author, Vol. 11, No. 1 through Vol. 14, No. 6, by Wm. B. Cottrell and Ann Klein, June 1974	\$ 8.00
116	Index to <i>Nuclear Safety</i> , A Technical Progress Review by Chronology, Permuted Title, and Author, Vol. 11, No. 1 through Vol. 15, No. 6, by Wm. B. Cottrell and Ann Klein, Apr. 1975	\$ 8.00
117	Protection of Nuclear Power Plants Against External Disasters, by Wm. B. Cottrell, Apr. 1975	\$15.00
119	A Selected Bibliography on Pressure Vessels for Light-Water-Cooled Power Reactors (LWRs), by Fred A. Heddleson, Jan. 1975	\$15.00
120	Annotated Bibliography of Hydrogen Considerations in Light-Water-Power Reactors, by G. W. Keilholtz, Feb. 1976	\$15.00
121	Reactor Operating Experiences, 1972-1974, U.S. Nuclear Regulatory Commission, Dec. 1975	\$15.00
122	Annotated Bibliography of Safety-Related Occurrences in Nuclear Power Plants as Reported in 1974, by R. L. Scott and R. B. Callaheer, May 1975	\$15.00
123	Nuclear Power: Accident Probability, Risks, and Benefits: A Bibliography, by NSIC Staff, Feb. 1976	\$12.00
124	Index to <i>Nuclear Safety</i> , A Technical Progress Review by Chronology, Permuted Title, and Author, Vol. 11, No. 1 Through Vol. 16, No. 6, by Wm. B. Cottrell and Ann Klein, April 1976	\$ 8.00
<u>ORNL/ NUREG/ NSIC</u>		
118	Siting of Nuclear Facilities, Selections from <i>Nuclear Safety</i> , by J. R. Buchanan	\$15.00
125	Annotated Bibliography of LMFBR Safety Literature, Vol. 1, by J. R. Buchanan and G. W. Keilholtz	\$15.00
126	Annotated Bibliography of Safety-Related Occurrences in Boiling-Water Nuclear Power Plants as Reported in 1975, by R. L. Scott and R. B. Callaheer	\$15.00
127	Annotated Bibliography of Safety-Related Occurrences in Pressurized Water Nuclear Power Plants as Reported in 1975, by R. L. Scott and R. B. Callaheer	\$15.00