012302

1 OF 1

PREACTION SYSTEMS

SYSTEM DESCRIPTION

General Design

Preaction fire alarm systems at ATP include sprinkler heads with fusible

**Idaho
National
Engineering
Laboratory**

*Managed
by the U.S.
Department
of Energy*

EGG-SSRE-9625
August 1991

Received by ASTI
APR 27 1992

INFORMAL REPORT

**FIREWATER SYSTEM INADVERTENT
ACTUATION FREQUENCY**

J. A. Schroeder
S. A. Eide

*Work performed under
DOE Contract
No. DE-AC07-76ID01570*

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

This document contains new concepts or the author(s) interpretation of new calculations and/or measurements; accordingly, EG&G Idaho, Inc. is required by the United States Government to include the following disclaimer:

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product or process disclosed, or represents that its use would not infringe privately owned rights. References herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

EGG-SSRE--9625

DE92 012362

FIREWATER SYSTEM INADVERTENT ACTUATION FREQUENCY

John A. Schroeder

Steven A. Eide

August 1991

Idaho National Engineering Laboratory
EG&G Idaho, Inc.
Idaho Falls, Idaho 83415

Prepared for the
U.S. Department of Energy
Idaho Operations Office
Under DOE Contract No. DE-AC07-76ID01570

MASTER

ok
DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

EXECUTIVE SUMMARY

The purpose of this analysis was to determine both generic and plant-specific firewater inadvertent actuation frequencies for wetpipe and preaction firewater systems at the Advanced Test Reactor (ATR). Firewater systems of both kinds are installed throughout the ATR facility. When installed for the protection of reactor equipment, firewater systems may also adversely affect the equipment they are meant to protect. This occurs when inadvertent actuation of a firewater system causes wetting and subsequent damage to equipment.

Wetpipe system inadvertent actuation can occur as a result of any single failure in the system pressure boundary. A number of data sources were reviewed to determine the most likely causes of system failure. The relevant failure modes for wetpipe systems were found to consist of piping leaks or ruptures and sprinkler head failures. Either of these failures may result directly from operator action, or may result from corrosion of piping, pre-existing manufacturing defects, or other random failures. All data sources reviewed were found to be compilations of failure events, and all lacked adequate population data. That is, they provided numbers of failures of a particular type, but not feet of installed piping, number of installed sprinkler heads, number of service years, or the time to failure for a particular failure event. This analysis used the available data, to the extent possible, to determine inadvertent actuation frequencies for three representative wetpipe systems at ATR. The systems cover areas M-2, M-3, and F-7A, B, C, and D. The resulting frequencies are shown by area in Table ES-1.

Preaction systems require two separate failures to cause an inadvertent actuation. The data sources used in the analysis of wetpipe systems were also used to identify the significant failure modes for preaction systems. Fault tree analysis was then used to determine the combinations of system failures that can lead to a spray event. The resulting cutsets were quantified using generic, commercial, and U. S. Department of Energy (DOE) data as applicable, and then requantified using available ATR-specific data. ATR has seven preaction systems. These systems are different mainly in the number of installed sprinkler heads and

feet of installed piping. The calculation was, therefore, performed for an average system, and can easily be adjusted to show the expected inadvertent actuation frequency in any specific area. The results indicate that the dominant cause of inadvertent actuation is human error during repair activities. The results are shown in Table ES-1.

Table ES-1. Summary of ATR wetpipe and preaction system inadvertent actuation frequencies

System	Inadvertent Actuation Mean Frequency	
	Generic	ATR
Wetpipe		
M-2	5.0E-3/yr	3.8E-3/yr
M-3	5.0E-3/yr	1.9E-3/yr
F7-A, B, C, and D	5.0E-3/yr	9.3E-4/yr
Preaction		
Experience	2.0E-4/yr ^a	- ^b
Fault tree model	4.3E-5/yr	2.0E-5/yr

- a. Based on no failures
b. ATR experience limited

CONTENTS

EXECUTIVE SUMMARY	iii
INTRODUCTION	1
WETPIPE SYSTEMS	2
System Description	2
Instrumentation and Control	2
Operator Actions	2
Test and Maintenance	3
Operational Experience	3
Quantification	5
Results	6
PREACTION SYSTEMS	7
System Description	7
General Design	7
Instrumentation and Control	7
Operator Actions	7
Test And Maintenance	8
Operational Experience	8
Fault Tree Development	9
Assumptions	10
Fault Tree Logic	10
System Cut Sets	11
Basic Event Quantification	12
Results	20
REFERENCES	30

FIGURES

Figure 1.	Master logic diagram.	26
Figure 2.	Pressure boundary initiators.	27
Figure 3.	Flood valve initiators.	28
Figure 4.	Operator error initiators.	29

TABLES

Table 1.	ATR preaction firewater system data	22
Table 2.	Preaction firewater system basic event data	23
Table 3.	Inadvertent release frequency (generic) by cut set	24
Table 4.	Preaction system inadvertent actuation frequency per year . .	25

FIREWATER SYSTEM INADVERTENT ACTUATION FREQUENCY

INTRODUCTION

The purpose of this calculation was to determine both generic and plant-specific frequencies of inadvertent firewater release from firewater systems at the Advanced Test Reactor (ATR). Two different types of systems were considered; wetpipe sprinkler systems, and preaction systems. Both types of systems are used throughout ATR.

Wetpipe systems are single failure systems. Commercial plant, U. S. Department of Energy (DOE), and ATR experiences were reviewed to determine the significant failure modes that must be quantified. The ATR inadvertent actuation frequency was then quantified using generic and DOE data for the failure modes. The resulting frequency is ATR specific in that it depends on the relative scale of the ATR systems as compared to commercial plant systems and the average DOE system.

Precision systems require multiple failures before an inadvertent release can occur. Fault tree methods were used to identify the failure modes for a typical ATR precision firewater system. Cutsets were generated for event sequences leading to inadvertent firewater release. The cutsets were then quantified with DOE, generic, or ATR-specific data as applicable.

WETPIPE SYSTEMS

SYSTEM DESCRIPTION

General Design

Wetpipe systems are continuously flooded and pressurized with firewater. Sprinkler heads with fusible link actuation release water in the event of fire. The fusible links are normally designed for water release at 165°F. At ATR the sprinkler headers are supplied from seven main distribution systems. Each system contains a pressure isolation valve and a 6-in. alarm check valve that indicates water flow in the system.

Instrumentation and Control

The only instrumentation associated with the system is the alarm circuitry associated with the water flow check valves and pressure isolation valves. The water flow check valves are equipped with position switches that provide for annunciation when the valves open. The pressure isolation valves are also equipped with tamper switches that indicate valve position. Both detection circuits cause annunciation at the Central Facilities Area (CFA) fire department and at the shift manager's office.

Operator Actions

The INEL fire department and ATR operations personnel respond to water flow alarms. Detection of water flow may not prevent equipment damage. The amount of wetting that can occur prior to system isolation may be sufficient to cause system damage.

Test and Maintenance

No test or maintenance work is performed while the reactor is critical. Repairs are made as needed, and within 24 h of discovery that the system is impaired.

Operational Experience

Reference 1 provides a list of firewater system inadvertent actuation events that occurred in the commercial nuclear power industry during the 1980s. Most of the events were caused by faults in deluge systems. However, some were either clearly in wetpipe systems, or most likely in wetpipe systems. In the 878.5 reactor years of operation covered in Reference 1, the following types of inadvertent actuations occurred:

- Steam actuation of sprinkler head
- Personnel caused impact
- Piping failures from corrosion and vibration
- Freezing of piping
- Testing resulting in piping or valve failure
- Unknown cause.

Because of incomplete event descriptions, 12 to 25 events could be included in the wetpipe inadvertent actuation category. With 878.5 reactor years of operation, a commercial plant wetpipe failure frequency of $1.4\text{E-}2$ to $2.9\text{E-}2/\text{yr}$ per plant is indicated, using a Bayesian update of a noninformative prior. The equation for this update is the following²:

$$F = (2n + 1)/(2T)$$

where

F = mean frequency for inadvertent actuation per plant

n = number of events

T = number of reactor years of experience.

The referenced report indicates 6.9 wetpipe fire protection systems per plant, resulting in a inadvertent actuation frequency of $2.1\text{E-}3$ to $4.2\text{E-}3/\text{yr}$ per system.

DOE experience is reported in Reference 3. The 278 inadvertent actuations of wetpipe systems were classified into the following types of categories:

- Freezing (54%)
- Overheating causing sprinkler head actuation (21%)
- Mechanical (impact) failure (12%)
- Leakages (6%)
- Faulty equipment (4%)
- Corrosion (2%)
- Unknown (1%).

Based on 30,000 system years of operation, the resulting mean frequency for inadvertent operation is $9.3\text{E-}3/\text{yr}$ per system.

In order to obtain a single generic estimate for inadvertent actuation of wetpipe systems, the commercial nuclear power plant and DOE estimates were combined using a geometric average. The geometric average is

$$\{[(2.1\text{E-}3)(4.2\text{E-}3)]^{0.5}(9.3\text{E-}3)\}^{0.5} = 5.3\text{E-}3/\text{yr per system.}$$

This value was rounded off to $5.0\text{E-}3/\text{yr}$ per system. An error factor of 10 is assumed to apply.

ATR experience includes a number of firewater system supply failures, but only two wetpipe system actuations. Both of these events were caused by fusible link failure caused by high ambient temperature. In one case the high

temperature was the result of a steam leak; in the other, a room cooler failed, allowing high temperature in the room. Neither of these events are thought to be relevant to the systems being modeled. There are no steam lines in the rooms considered, and cooler failures could not result in room ceiling temperatures approaching 165°F.

QUANTIFICATION

As discussed above, a generic inadvertent actuation frequency of $5.0E-3/\text{yr}$ per system for wetpipe systems was obtained from commercial nuclear power plant and DOE facility experience. However, ATR-specific numbers are desired to support the internal flooding analysis. In the following calculations, mean values from References 3 and 4 were used for sprinkler head and pipe leakage failure rates. The pipe leakage failure rate has an error factor of 10. No distribution information is provided with the sprinkler head failure data, so an error factor of 10 was assumed.

Area M-2. Area M-2 is protected by wetpipe systems with an estimated 200 ft of piping of less than 3 in. in diameter. An estimated leakage frequency can be calculated from the per foot piping failure frequency⁴, and from the head failure frequency³, assuming 50 heads in the system. The system leakage frequency is then

$$\begin{aligned} & (3.0E-9/\text{h}/\text{ft})(200\text{ft})(6132\text{h}/\text{yr}) \\ & + (3.0E-10/\text{h}/\text{head})(50\text{head})(6132\text{h}/\text{yr}) = 3.8E-3/\text{yr}. \end{aligned}$$

In this calculation, it was assumed that ATR is at power 70% of the time. Therefore, 6132 h was used as the hours at power each year.

Area M-3. Area M-3 is protected by a small wetpipe system. The system is estimated to include about 100 ft of piping of less than 3-in. diameter, and 10 sprinkler heads. As with area M-2, the piping failure frequency can be calculated from the piping leakage and head failure frequencies as

$$(3.0E-9/h/ft)(100ft)(6132h/yr) \\ + (3.0E-10/h/head)(10head)(6132h/yr) = 1.9E-3/yr.$$

Areas F-7A, B, C, and D. Sprinkler systems are located in the southeast end of the first basement. These systems are each estimated to include about 50 ft of pipe and 5 sprinkler heads. As in the preceding two areas, the inadvertent actuation frequency for each area can be calculated from piping leakage and head failure data as

$$(3.0E-9/h/ft)(50ft)(6132hr/yr) \\ + (3.0E-10/h/head)(5head)(6132h/yr) = 9.3E-4/yr.$$

RESULTS

The above calculations result in inadvertent actuation frequencies of $3.8E-3/yr$ (area M-2), $1.9E-3/yr$ (area M-3), and $9.3E-4/yr$ (areas F-7A, B, C, and D). The generic piping leakage failure rate used in this calculation has an error factor of 10. The head failure data does not include an error factor so a value of 10 was assumed. A simple uncertainty calculation indicates an overall error factor of 10 is appropriate. These results agree reasonably well with the commercial and DOE experience if it can be assumed that the inadvertent actuation frequency is proportional to system size. (The ATR systems are generally considered to be smaller than those typical for DOE systems.)

PREACTION SYSTEMS

SYSTEM DESCRIPTION

General Design

Preaction firewater systems at ATR include sprinkler heads with fusible link actuation. The sprinkler heads and piping are kept dry by a solenoid-operated flood valve. Supervisory air fills the piping between the sprinkler heads and flood valve. A control system is provided that processes smoke or heat detector signals, provides alarm functions, and opens the flood valve when required. Flooding the spray header will not result in water discharge unless one of the sprinkler head fusible links melts or the piping fails.

Instrumentation and Control

The actuation system includes either smoke or thermal detectors that provide solenoid valve trip signals. There is also a manual trip that allows operators to flood the system at will. Supervisory circuits are provided that indicate low air pressure in the spray header or water flow past the flood valve. The system provides alarm functions at the shift supervisor's office, and at the CFA fire station. The flood valve will open on loss of power, or on smoke or heat detection. The valve is protected against inadvertent actuation on loss of power by a backup battery. It will not open on low pressure in the supervisory air.

Operator Actions

Both plant operations and the Idaho National Engineering Laboratory (INEL) fire department respond to alarms. In the event that no fire is present (spurious alarm), the cause of the alarm is investigated. If there is a system failure present (or suspected), fire engineering personnel will be notified. If the spray header is flooded, it will generally remain so until

repair is scheduled. Repairs, should they be required, will normally be made within 16 h. The system must be repaired within 24 h.

Test And Maintenance

Testing of the system is required on a periodic basis. Every 6 mo the detectors and control circuits are tested. At least yearly the flood valve is trip tested, actually flooding the dry portion of the system. No tests are performed while the reactor is critical.

Operational Experience

The commercial reactor experience presented in Reference 1 appears to indicate no inadvertent actuations of preaction systems. Given 878.5 reactor years of operation and 3.1 preaction systems per reactor, a Bayesian update of a noninformative prior results in a mean frequency of $1.8\text{E-}4/\text{yr}$ per system. This value was rounded off to $2.0\text{E-}4/\text{yr}$ per system. The DOE experience discussed in Reference 3 does not distinguish preaction systems.

Operational experience with preaction systems at the ATR is similar to that for commercial systems. As shown in Table 1, ATR has 7 preaction systems that have been in operation for a total of 44 system-years. In approximately 44 system-years of operation there has been no record of an inadvertent release of water from a preaction system, although there have been a number of precursor events, such as flooding of the spray header. The cause of header flooding has been leakage past the flood valve, or possibly, spurious detector signals.

A review of the plant deficiency log sheets (DLSs) from 1982 through 1989 turned up several events affecting ATR preaction firewater systems. In, May of 1983 leakage past the flood valve for the Loop Data Acquisition System (LDAS) room preaction system caused pressurization of the spray header. Upon investigation three problems were found. The manual trip valve was found to leak, a pressure gauge was found to be broken, and the pressure switch that sends a signal to the CFA fire department failed to respond to system

pressurization. The fire department bled the pressure off the header. If the system was repaired at this point, it was not clear from the DLS. Four days later the water flow alarm was received four times. At this point the system was isolated and a system impaired tag was hung.

In another incident (August 1983), the water pressure gauge on the computer room preaction system was found out of calibration. It read 100 psi when the system was depressurized.

Another incident occurred in August of 1983. This was a trip of the reactor control room preaction system flood valve. The DLS said this was the second time this had happened, although no record was found of the first incident. The fire department responded to the trip. Investigation of the cause was not conclusive. Fire engineering later cleaned the valve, finding some scale build-up on the seat. A detector check was also performed. The system was returned to service, with no clear cause having been identified.

In May of 1984, another LDAS water flow alarm was received. The problem appeared to be another leak past the flood valve.

The DLS system was first implemented in 1982, so events occurring prior to 1982 would be recorded only if significant enough to be considered an unusual occurrence. A review of the Unusual Occurrence Reports turned up no additional events relevant to preaction systems.

FAULT TREE DEVELOPMENT

The calculation of initiating event frequencies from fault trees requires a specialized approach to fault tree development.⁵ The approach requires that basic events in the tree are categorized as either initiating events or enabling events. Initiating events are those that, given the prior existence of system faults (or enabling events), cause the undesired result. Enabling faults or events may occur in the system without causing the undesired result to occur. As a practical matter, the only difference between

an initiating event and an enabling event is the sequence in which the events occur (initiating events occur last).

Three types of event sequences were considered to be applicable. In the first sequence, it was assumed that faults in the flood valve or its controls allow flooding of the spray header. Then faults in the spray header pressure boundary cause water release. In the second type of sequence, faults in the spray header provide a flow path so that a fault in the flood valve or its controls will initiate water release. The third type of sequence involves operator errors during repair activities. Figure 1 provides a master logic diagram showing the breakdown of the inadvertent water release event by its contributors.

Assumptions

Development and quantification of the inadvertent actuation fault trees was based on the following assumptions:

- No test or maintenance work is performed on the preaction firewater systems while the reactor is critical.
- System faults that are detected and alarmed will be repaired within 24 h.
- Faults not alarmed will be detected in 6 mo.
- Operator errors will not affect both the pressure boundary and flood valve at the same time.

Fault Tree Logic

The fault trees for pressure boundary initiators and flood valve related initiators are shown in Figures 2 and 3. In Figure 2, failure of the pressure boundary acts as the initiator, while events resulting in flooding of the spray header are enabling. Flooding of the spray header can only occur as a result of solenoid isolation valve failure. Internal leakage is included, as are control system failures. The control system failures are not developed, but would result in events leading to a spurious actuation signal. This would

include environmental factors affecting the heat or smoke detectors. Smoke (e.g., from welding in the area) and dust are responsible for some commercial plant actuations. Quantification of the enabling events must account for detection (by supervisory alarms or functional checks) and repair of system faults as shown in the logic.

Failure of the system pressure boundary requires either failure of the spray nozzles or fusible links, or leakage of the associated piping. The only ATR-specific experience is due to failure of the fusible links because of steam leaks, and these would not be applicable in the areas of interest because there are no steam lines. Improper installation and failure of the links or nozzles to operate as designed are also considered.

Figure 3 shows the model when the flood valve faults act to initiate the release.

Figure 4 shows the model for operator-error-induced failures. In this model, the frequency with which repairs are required depends only on the rate of occurrence of system faults. Once a repair is required, there is then some probability that operator error will cause a release.

System Cut Sets

Qualitative evaluation of the system represented in Figures 1, 2, 3, and 4 produces the cutsets shown below:

```
FWS-PIP-IE-RUPT * FWS-XHE-VF-REPAR +  
FWS-XHE-IE-PBI * FWS-XHE-VF-REPAR +  
FWS-SPR-IE-MT1HD * FWS-XHE-VF-REPAR +  
FWS-PIP-IE-RUPT * FWS-SOV-VF-S24HE +  
FWS-PIP-RP-P24HE * FWS-SOV-IE-SOLEN +  
FWS-PIP-IE-RUPT * FWS-ICC-VF-I24HE +  
FWS-ICC-IE-FAULT * FWS-PIP-RP-P24HE +  
FWS-PIP-IE-RUPT * FWS-ICC-VF-A6ME * FWS-SOV-VF-S6ME +  
FWS-ICC-VF-SUPER * FWS-PIP-RP-P6ME * FWS-SOV-IE-SOLEN +  
FWS-PIP-RP-P24HE * FWS-XHE-IE-FVI +  
FWS-XHE-IE-PBI * FWS-SOV-VF-S24HE +  
FWS-PIP-IE-RUPT * FWS-ICC-VF-A6ME * FWS-ICC-VF-I6ME +  
FWS-ICC-IE-FAULT * FWS-ICC-VF-SUPER * FWS-PIP-RP-P6ME +
```

FWS-XHE-IE-PBI * FWS-ICC-VF-I24HE +
 FWS-ICC-VF-SUPER * FWS-PIP-RP-P6ME * FWS-XHE-IE-FVI +
 FWS-XHE-IE-PBI * FWS-ICC-VF-A6ME * FWS-SOV-VF-S6ME +
 FWS-SPR-IE-MT1HD * FWS-SOV-VF-S24HE +
 FWS-SOV-IE-SOLEN * FWS-SPR-FO-H24HE +
 FWS-XHE-IE-PBI * FWS-ICC-VF-A6ME * FWS-ICC-VF-I6ME +
 FWS-SPR-IE-MT1HD * FWS-ICC-VF-I24HE +
 FWS-ICC-IE-FAULT * FWS-SPR-FO-H24HE +
 FWS-ICC-VF-SUPER * FWS-SOV-IE-SOLEN * FWS-SPR-FO-H6ME +
 FWS-SPR-IE-MT1HD * FWS-ICC-VF-A6ME * FWS-SOV-VF-S6ME +
 FWS-SPR-FO-H24HE * FWS-XHE-IE-FVI +
 FWS-ICC-IE-FAULT * FWS-ICC-VF-SUPER * FWS-SPR-FO-H6ME +
 FWS-SPR-IE-MT1HD * FWS-ICC-VF-A6ME * FWS-ICC-VF-I6ME +
 FWS-ICC-VF-SUPER * FWS-SPR-FO-H6ME * FWS-XHE-IE-FVI.

These cutsets are the combinations of initiating events and enabling events required to produce a spray event. Quantification is discussed in the following section.

Basic Event Quantification

Quantification of the system cutsets requires careful consideration of whether each basic event is an initiator or enabling event. Each cutset from the previous discussion must have only one initiating event. The remaining events must be enabling events.

In Figure 2, all failures leading to flooding of the dry piping are considered enabling events, and all failures leading to pressure boundary failure are considered initiating events. This implies a failure scenario in which something happens to cause flooding of the dry piping, but a spray event will not occur until something happens to breach the spray header pressure boundary. Flooding would be detected and repaired within 24 h, unless there is an accompanying failure of the alarm function; then detection would not occur until the 6-mo detector and logic check.

In Figure 3, the event sequence is reversed so that failure of the pressure boundary will provide the enabling events that will allow an inadvertent spray event if the flood valve should fail (the initiating event). Since breaches in the boundary will cause depressurization and will be

detected by the supervisory circuits, the same sort of time to repair considerations are made as in Figure 2.

Quantification of each basic event is discussed below. For all calculations, a lognormal distribution is assumed. The quantification code requires the mean and the error factor (EF). The error factor is the 95th percentile value (from the failure rate distribution) divided by the 50th percentile (or median).

FWS-ICC-IE-FAULT. Control system faults cause the solenoid valve to open. This event is quantified as spurious actuation of the solenoid valve. The generic mean failure rate is $5.0\text{E-}7/\text{h}$, with an EF of 10.⁶ This value can be updated to include the ATR operating experience of no such events in 44 system years of operation. Results from a Bayesian update with the prior frequency given above indicate a mean frequency of $2.3\text{E-}7/\text{h}$, with an EF of 10.

FWS-ICC-VF-A6ME. Flooding of the spray header goes undetected. This includes instrumentation and control (ICC) faults that prevent detection of water flow. The generic mean failure rate for an alarm that fails to operate is $1.0\text{E-}6/\text{h}$ with an EF of 10.⁶ The probability of flooding without detection (until the 6-mo logic check) is calculated using the failure rate and the mean time to detect as

$$\begin{aligned} & (0.5)(\text{failure rate})(\text{detection interval}) \\ & = (0.5)(1.0\text{E-}6/\text{h})(4380\text{h}) = 2.2\text{E-}3. \end{aligned}$$

When the mean failure rate is adjusted (using a Bayesian update) for the ATR experience of no such events in 44 system years, the new value is $3.0\text{E-}7/\text{h}$ with an EF of 10. With the new failure rate, the basic event probability becomes

$$(0.5)(3.0\text{E-}7/\text{h})(4380\text{h}) = 6.6\text{E-}4.$$

FWS-ICC-VF-I24HE. Control system faults open the solenoid valve. This event is the same as FWS-ICC-IE-FAULT except that it is an enabling event

considered in the context of normal detection and repair within 24 h. The basic event probability is

$$(5.0\text{E-}7/\text{h})(24\text{h}) = 1.2\text{E-}5.$$

When the mean failure rate is adjusted (using Bayesian update) for the ATR experience of no such events in 44 system years, the new value is $2.3\text{E-}7$ with an EF of 10. With the new failure rate, the basic event probability becomes

$$(2.3\text{E-}7/\text{h})(24\text{h}) = 5.5\text{E-}6.$$

FWS-ICC-VF-I6ME. Control system faults open the solenoid valve. This event is similar to FWS-ICC-IE-FAULT above, except that detection and repair is based on a 6-mo detection. The basic event probability is

$$(0.5)(5.0\text{E-}7/\text{h})(4380\text{h}) = 1.1\text{E-}3.$$

Using a Bayesian update to account for the ATR experience of no such events in 44 system years gives

$$(0.5)(2.3\text{E-}7/\text{h})(4380\text{h}) = 5.0\text{E-}4.$$

The error factor is 10.

FWS-ICC-VF-SUPER. Supervisory circuits fail to detect or alarm a low pressure condition resulting from a spray header failure. This event is quantified as an alarm failure that is assumed to be detected during the 6-mo logic check. The mean failure rate is $1.0\text{E-}6/\text{h}$ with an EF of 10.⁶ The basic event probability is

$$(0.5)(1.0\text{E-}6/\text{h})(4380\text{h}) = 2.2\text{E-}3.$$

When the mean failure rate is adjusted (using a Bayesian update) for the ATR experience of no such events in 44 system years, the new value is $3.0\text{E-}7$ with an EF of 10. With the new failure rate, the basic event probability becomes

$$(0.5)(3.0E-7/h)(4380h) = 6.6E-4.$$

FWS-PIP-IE-RUPT. Spray header ruptures. Leakage or rupture of piping or fittings in the dry portion of the preaction system pressure boundary occurs as a result of improper installation, corrosion, or use of faulty materials during construction. Assuming 200 ft of piping, the leakage frequency is

$$(3.0E-9/h/ft)(200ft) = 6.0E-7/h.$$

An error factor of 10 is assumed. No such events have been recorded for preaction systems at ATR. Using a Bayesian update to adjust this number for the ATR experience of no events in 44 system years of operation results in the a mean frequency of $2.5E-7/h$ with an EF of 10.

FWS-PIP-RP-P24HE. Spray header ruptures. When spray header rupture is considered as an enabling event, repair must be accounted for. Should the dry pipe system leak, it would normally be detected by the supervisory circuit and alarmed. The assumed response and repair time of 24 h results in an unavailability of

$$(6.0E-7/h)(24h) = 1.4E-5.$$

Using a Bayesian update to adjust this number for the ATR experience of no events in 44 system years of operation results in the an unavailability of

$$(2.5E-7/h)(24h) = 6.0E-6.$$

The EF for the above unavailability is 10.

FWS-PIP-RP-P6ME. Spray header ruptures. This event is similar to the above, but a 6-mo detection period is assumed. The unavailability resulting from the DOE data is

$$(0.5)(6.0E-7/h)(4380h) = 1.3E-3.$$

Adjusting the mean failure rate for the ATR experience gives

$$(0.5)(2.5E-7/h)(4380h) = 5.5E-4$$

with an EF of 10.

FWS-SOV-IE-SOLEN. Solenoid valve (or flood valve) leaks or ruptures internally. This event is mechanical failure of the solenoid valve (or flood valve) used to flood the dry portion of the system. Several events involving either the flood valve or solenoid valve have occurred at ATR. The events that did occur involved leakage of the flood valves in the LDAS and reactor control room preaction systems. The generic mean failure rate is $1.0E-6/h$ with an EF of 10.⁶ If the ATR experience of 3 events (ATR DLS 84-316, 83-516, 83-364) in 44 system years is used to update the above number, then the mean failure frequency becomes $5.8E-6/h$ with an EF of 3.

FWS-SOV-VF-S24HE. Solenoid valve leaks or ruptures. This event is similar to FWS-SOV-IE-SOLEN, but is considered as an enabling event with detection and repair in 24 hours. The event probability is

$$(1.0E-6/h)(24h) = 2.4E-5$$

with an EF of 10. Using ATR data to update the mean failure rate in the above calculation results in an event unavailability of

$$(5.8E-6/h)(24h) = 1.4E-4.$$

The resultant EF is 3.

FWS-SOV-VF-S6ME. Solenoid valve leaks or ruptures. This event is similar to FWS-SOV-IE-SOLEN, but is considered as an enabling event with detection and repair in 6 mo. The generic event unavailability is

$$(0.5)(1.0E-6/h)(4380h) = 2.2E-3.$$

The ATR specific unavailability is

$$(0.5)(5.8E-6/h)(4380h) = 1.3E-2.$$

FWS-SPR-IE-MT1HD. One or more sprinkler heads fail. This failure could involve either the sprinkler nozzle or the fusible link that prevents water release before the local temperature reaches 165°F. Using DOE data³ for the mean sprinkler head failure rate (rounded off to 3.0E-10/yr), and the average number of sprinkler heads per system (see Table 1) results in a per system sprinkler head failure frequency of

$$(3.0E-10/h/head)(24head) = 7.2E-9/h.$$

No EF information is provided with the DOE data, so a value of 10 was assumed. There have been two such events at ATR. However, both have involved failure of the fusible link because of environmental conditions not expected in ATR rooms with preaction systems. Updating with the ATR experience of no such events having occurred in 44 system years does not affect the results. Note that the ATR experience is not included in the DOE experience because the DOE data was collected between 1952 and 1980, and the ATR events occurred in the middle 1980s.

FWS-SPR-F0-H24HE. One or more sprinkler heads fail. This event is similar to FWS-SPR-IE-MT1HD, but is considered as an enabling event with detection and repair in 24 h. Sprinkler head failure will depressurize the dry pipe portion of the system, resulting in a supervisory alarm at the control panels. The assumption that any such failures would be discovered and repaired within 24 h results in an unavailability of

$$(7.2E-9/h)(24h) = 1.7E-7.$$

The ATR specific value is the same, with an EF of 10.

FWS-SPR-FO-H6ME. One or more sprinkler heads fail. This event is similar to FWS-SPR-FO-H24HE, but is considered as an enabling event with detection and repair in 6 mo. The unavailability is

$$(0.5)(7.2E-9/h)(4380h) = 1.6E-5.$$

The ATR specific value is the same, with an EF of 10.

FWS-XHE-IE-FVI. This event involves opening of the flood valve as a result of human error. This event is limited to actions that cause flooding of the spray header. It includes events such as bumping or accidentally actuating switches or even tampering or sabotage. It does not include errors during repair operations or errors affecting the pressure boundary. These are treated separately (see FWS-XHE-VF-REPAR and FWS-XHE-IE-PBI). Review of the data provided for deluge valves in Reference 1 shows 14 events in 878.5 reactor years of operation, where operators were clearly the cause of flood valve trips. Reference 1 indicates 7.0 water-based systems per reactor, resulting in 6149.5 system years. Therefore a generic value for this event can be calculated as

$$[(2)(14) + 1]/[(2)(6149.5)] = 1.4E-3/yr.$$

Converting to an hourly frequency, the value is $1.6E-7/h$. No EF is listed with the available data, so a value of 10 was assumed. Updating for the ATR experience of no events in 44 years gives a value of $1.2E-7/h$ with an EF of 10.

FWS-XHE-IE-PBI. This event also involves failures caused by human error. This event is limited to events affecting the spray header pressure boundary. It includes bumping of spray nozzles or piping, or even tampering or sabotage. This error does not affect the flood valve, and **does not** include errors occurring during repair activities. These are treated separately (see FWS-XHE-IE-FVI and FWS-XHE-VF-REPAR).

The data in Reference 1 did not include any partial failures of preaction systems (spray header pressure boundary). However for wetpipe systems, human error events (impacts) resulted in 3 leakages. Because the wetpipe system is similar to the spray header portion of a preaction system, these data are considered applicable. Reference 1 indicates 6.9 wetpipe systems per plant and 878.5 plant years of experience, resulting in 6062 systems years of operation. Therefore, a generic value for this event is

$$[(2)(3) + 1]/[(2)(6062)] = 5.8E-4/\text{yr per system.}$$

Converting to an hourly frequency results in $6.6E-8/\text{h}$ per system. An error factor of 10 was assumed. Updating for the ATR experience of no events in 44 system years, the result is $5.7E-8/\text{h}$ per system, with an EF of 10.

FWS-XHE-VF-REPAR. This event results when a craftsman repairing the system makes a mistake that results in the release of a water spray. Given an event requiring a repair activity (any of the initiators modeled in this analysis), one barrier against water release has already failed, and a mistake during the repair activity can fail the final barrier. Quantification is based on the following rules for determining human error probability (HEP) screening values⁷:

- If the repair activity is knowledge-based, (i.e., no procedures are used), then the HEP ranges from 0.5 to 0.005, and has a recommended value of 0.1.
- If the repair activity is rule-based, (i.e., procedures are used, but the activity occurs infrequently, and no specialized training is provided), then the HEP ranges from 0.05 to 0.0005, and has a recommended value of 0.01.
- If the repair activity is skill-based, (i.e., procedures are used, the activity occurs frequently, and specific training is provided), then the HEP ranges from 0.005 to 0.00005, and has a recommended value of 0.001.

FWS repair activities are considered rule-based, giving a HEP of $1.0E-2$. An EF of 10 was assumed for this event. In some respects the above screening values do not provide a very satisfying basis for quantification of this

event. This is because not all repairs are equally likely to produce a significant release. It seems obvious that if the spray header is intact, repairs involving the flood or solenoid valves would not be very likely to cause a significant flood event. However, if the spray header has been breached, repairs might be very likely to result in a damaging release, since all that is required is to mistakenly open the solenoid valve. Proper quantification of these repair sequences would require a detailed human reliability analysis, which is beyond the scope of this analysis.

RESULTS

Most of the basic events in the preaction system actuation fault tree have both a generic and ATR specific quantification. Basic event unavailabilities are summarized in Table 2. The cutsets were quantified using both basic event quantifications. The quantification included both a point estimate, and uncertainty analysis that propagated basic event distributions through the cutset equation to determine the uncertainty in the resulting frequency.

The hourly frequency (mincut upper bound) resulting from the generic quantification is shown in Table 3. The yearly frequency for inadvertent release is $(7.1E-9/h)(6132h/yr) = 4.3E-5/yr$ per system. The mean frequency and uncertainty parameters are shown in Table 4. The primary contributors all include human errors during repair activities. In these scenarios something has happened to fail one of the two primary barriers to inadvertent water release. The spray header either has been flooded (as in cut sets 1 and 2) or has been breached (as in cut set 3). These conditions are detected and alarmed, so repair is performed within 24 h. Inadvertent spray occurs when the crafts personnel involved in the repair activity make a mistake that fails the final barrier.

The above frequency of $4.3E-5/yr$ per system is based on repair HEP screening values that may not accurately reflect the specific procedures in use at ATR. Given the importance of the repair HEP in this analysis, a

worthwhile refinement to this calculation would be to pursue a detailed human reliability analysis for the sequences identified in Table 3.

The cutsets in Table 3 have also been quantified with specific ATR data obtained by Bayesian update of the data for the generic case. The results are shown in Table 4. The ATR-specific result, $2.0\text{E-}5/\text{yr}$ per system, is lower than the generic result (fault tree), $4.3\text{E-}5/\text{yr}$ per system, because most of the ATR experience has been favorable (no failures).

Table 1. ATR preaction firewater system data

<u>System</u>	<u>Service date</u>	<u>Number of valves</u>	<u>Number of sprinkler heads</u>
LDAS	1979	1 (2in.)	6
1C-W	1982	1 (2in.)	8
PPS & SATS	1979	1 (2in.)	10
RCR	1979	1 (2in.)	9
RDAS	1989	1 (2in.)	24
PPMR	1989	1 (4in.)	46
SGR	1989	1 (4in.)	67

Table 2. Preaction firewater system basic event data

Basic Event	Generic		ATR Data		Description
	Mean	EF	Mean	EF	
FWS-ICC-IE-FAULT	5.0E-07	10	2.3E-07	10	Control system faults open flood valve
FWS-ICC-VF-A6ME	2.2E-03	10	6.6E-04	10	Flooding of dry pipe is undetected - alarm function fails
FWS-ICC-VF-I24HE	1.2E-05	10	5.5E-06	10	Control system faults open flood valve - normal detection
FWS-ICC-VF-I6ME	1.1E-03	10	5.0E-04	10	Control system opens flood valve - 6-mo detection
FWS-ICC-VF-SUPER	2.2E-03	10	6.6E-04	10	Supervisory circuit fails to detect pressure loss
FWS-PIP-IE-RUPT	6.0E-07	10	2.5E-07	10	Dry pipe ruptures - initiating event
FWS-PIP-RP-P24HE	1.4E-05	10	6.0E-06	10	Dry pipe ruptures - enabling event with 24-h discovery
FWS-PIP-RP-P6ME	1.3E-03	10	5.5E-04	10	Dry pipe ruptures - enabling event with 6-mo discovery
FWS-SOV-IE-SOLEN	1.0E-06	10	5.8E-06	3	Solenoid valve internal leakage - initiating event
FWS-SOV-VF-S24HE	2.4E-05	10	1.4E-04	3	SOV internal leakage - enabling event w/24-h discovery
FWS-SOV-VF-S6ME	2.2E-03	10	1.3E-02	3	SOV internal leakage - enabling event w/6-mo discovery
FWS-SPR-IE-MT1HD	7.2E-09	10	7.2E-09	10	One or more sprinkler heads fail - initiating event
FWS-SPR-FO-H24HE	1.7E-07	10	1.7E-07	10	One or more sprinkler heads fail - enabling event w/24 h
FWS-SPR-FO-H6ME	1.6E-05	10	1.6E-05	10	One or more sprinkler heads fail - enabling event w/6 mo
FWS-XHE-IE-FVI	1.6E-07	10	1.2E-07	10	Operator error causes flooding of spray header
FWS-XHE-IE-PBI	6.6E-08	10	5.7E-08	10	Operator error breaches spray header pressure boundary
FWS-XHE-VF-REPAR	1.0E-02	10	1.0E-02	10	Operator error causes spray during repair activity

Table 3. Inadvertent release frequency (generic) by cut set

Cut No.	% Total	% Cut Set	Freq. per hour	Cut Sets
1	88.3	88.3	6.0E-009	FWS-PIP-IE-RUPT, FWS-XHE-VF-REPAR
2	98.0	9.7	6.6E-010	FWS-XHE-IE-PBI, FWS-XHE-VF-REPAR
3	99.1	1.0	7.2E-011	FWS-SPR-IE-MT1HD, FWS-XHE-VF-REPAR
4	99.3	.2	1.4E-011	FWS-PIP-IE-RUPT, FWS-SOV-VF-S24HE
5	99.5	.2	1.4E-011	FWS-PIP-RP-P24HE, FWS-SOV-IE-SOLEN
6	99.6	.1	7.2E-012	FWS-PIP-IE-RUPT, FWS-ICC-VF-I24HE
7	99.7	.1	7.0E-012	FWS-ICC-IE-FAULT, FWS-PIP-RP-P24HE
8	99.8	.0	2.9E-012	FWS-PIP-IE-RUPT, FWS-ICC-VF-A6ME, FWS-SOV-VF-S6ME
9	99.8	.0	2.8E-012	FWS-ICC-VF-SUPER, FWS-PIP-RP-P6ME, FWS-SOV-IE-SOLEN
10	99.9	.0	2.2E-012	FWS-PIP-RP-P24HE, FWS-XHE-IE-FVI
11	99.9	.0	1.5E-012	FWS-XHE-IE-PBI, FWS-SOV-VF-S24HE
12	99.9	.0	1.4E-012	FWS-PIP-IE-RUPT, FWS-ICC-VF-A6ME, FWS-ICC-VF-I6ME
13	99.9	.0	1.4E-012	FWS-ICC-IE-FAULT, FWS-ICC-VF-SUPER, FWS-PIP-RP-P6ME
14	99.9	.0	7.9E-013	FWS-XHE-IE-PBI, FWS-ICC-VF-I24HE
15	99.9	.0	4.5E-013	FWS-ICC-VF-SUPER, FWS-PIP-RP-P6ME, FWS-XHE-IE-FVI
16	99.9	.0	3.1E-013	FWS-XHE-IE-PBI, FWS-ICC-VF-A6ME, FWS-SOV-VF-S6ME
17	99.9	.0	1.7E-013	FWS-SPR-IE-MT1HD, FWS-SOV-VF-S24HE
18	99.9	.0	1.7E-013	FWS-SOV-IE-SOLEN, FWS-SPR-FO-H24HE
19	100.0	.0	1.6E-013	FWS-XHE-IE-PBI, FWS-ICC-VF-A6ME, FWS-ICC-VF-I6ME
20	100.0	.0	8.6E-014	FWS-SPR-IE-MT1HD, FWS-ICC-VF-I24HE
21	100.0	.0	8.5E-014	FWS-ICC-IE-FAULT, FWS-SPR-FO-H24HE
22	100.0	.0	3.5E-014	FWS-ICC-VF-SUPER, FWS-SOV-IE-SOLEN, FWS-SPR-FO-H6ME
23	100.0	.0	3.4E-014	FWS-SPR-IE-MT1HD, FWS-ICC-VF-A6ME, FWS-SOV-VF-S6ME
24	100.0	.0	2.7E-014	FWS-SPR-FO-H24HE, FWS-XHE-IE-FVI
25	100.0	.0	1.7E-014	FWS-ICC-IE-FAULT, FWS-ICC-VF-SUPER, FWS-SPR-FO-H6ME
26	100.0	.0	1.7E-014	FWS-SPR-IE-MT1HD, FWS-ICC-VF-A6ME, FWS-ICC-VF-I6ME
27	100.0	.0	5.6E-015	FWS-ICC-VF-SUPER, FWS-SPR-FO-H6ME, FWS-XHE-IE-FVI

Mincut

Upper Bound

6.8E-9 per hour (4.2E-5 per ATR reactor year)

Table 4. Preaction system inadvertent actuation frequency per year

<u>Case</u>	<u>Mean</u>	<u>EF</u>	<u>5th</u>	<u>Median</u>	<u>95th</u>
Generic data (Ref. 1)	2.0E-4	10	7.5E-6	7.5E-5	7.5E-4
Fault tree (generic data)	4.3E-5	22	5.8E-7	7.4E-6	1.6E-4
Fault tree (ATR-specific data)	2.0E-5	17	4.2E-7	4.4E-6	7.4E-5

Figure 1. Master logic diagram.

Figure 2. Pressure boundary initiators.

Figure 3. Flood valve initiators.

Figure 4. Operator error initiators.

REFERENCES

1. J. A. Lambright et. al., Evaluation of Generic Issue 57, Effects of Fire Protection System Actuation on Safety-Related Equipment, NUREG/CR-5580 (draft), January 1991.
2. PRA Procedures Guide, NUREG/CR-2300, January 1983.
3. Automatic Sprinkler System Performance and Reliability In United States Department of Energy Facilities 1952-1980, DOE/EP-0052, June 1982, pp. 59 and 75.
4. S. A. Eide et al., Component Leakage and Rupture Frequency Estimates, EG&G Idaho, Inc., EGG-SSRE-9639, August 1991.
5. C. Dunglinson and H. Lambert, "Interval Reliability for Initiating and Enabling Events," IEEE Transactions on Reliability, Vol. R-32, No. 2, June 1983.
6. S. A. Eide et.al., Generic Component Failure Data Base for Light Water and Sodium Reactor PRAs, EGG-SSRE-8875, February 1990.
7. Systematic Human Action Reliability Procedure (SHARP), EPRI NP-3583, Interim Report, June 1984.

END

DATE
FILMED
6/12/92