9/4/85

Operated by
Westinghouse
Hanford Company
for the USDOE

A subsidiary of
Westinghouse Electric
Corporation

NE Standards Transmittal

1-21561

A subsidiary of
Westinghouse Electric
Corporation

P. O. Box 1970
Richland, WA 99352

Hanford Engineering Development Laboratory

MASTER

NE-F--11-2T-Rev.3/85

DISTRIBUTION	DATE May 20, 1985		DE93 011213	
	RETURN COMMENTS TO	TYPE SUBMISSION	TYPE ACTION	
	J.J. McCown Westinghouse Hanford Co. P.O. Box 1970 Richland, WA 99352	☐ 1. PRELIMINARY ☐ 2. DRAFT ☒ 3. TENTATIVE ☐ 4. FINAL ☒ 5. REVISION	☐ A. APPROVAL ☐ B. INFORMATION ☐ C. COMMENTS ☒ D. TRIAL USE ☐ E.	
	NOT LATER THAN			
List 01 05	NUMBER	DESCRIPTION		ACTION
	NE F 11-2T	Analytical Chemistry Methods for Boron Carbide Absorber Material. March 1985		D

REVISIONS OF THIS DOCUMENT IS UNLIMITED *RB*

SIGNATURE

John D. ...

FOREWORD

This standard supersedes the July 1977 issue RDT F 11-2T and incorporates changes that were approved for publication in this revision. These changes are identified by the following marginal notations:

C	Change approved 3-27-85
D	Deletion approved 3-27-85
N	Addition approved 3-27-85

Editorial changes that were made during preparation of this revision are not identified.

The methods in this revision are presented in one of the following three categories:

1. Referenced to appropriate ASTM standard(s),
2. Referenced to appropriate ASTM standard(s) with additional requirements, or
3. Kept intact as existing in the July 1977 issue.

Methods 7 and 14 are Category 1. Methods 4, 5, 6, 8, 9, 10, 11, and 12 are in Category 2 with reference to NE F 2-8T for calibration frequency and standard. Methods 13, 15, 16, and 17 are unchanged from the July 1977 issue since ASTM C791-80 does not contain methods for these analysis.

March 1985

i

i

ANALYTICAL CHEMISTRY METHODS FOR BORON CARBIDE ABSORBER MATERIAL

TABLE OF CONTENTS

	<u>Page</u>
1. SCOPE	1
2. APPLICABLE DOCUMENTS	1
3. GENERAL REQUIREMENTS	1
4. TOTAL CARBON	3
5. TOTAL BORON	3
6. BORON ISOTOPIC COMPOSITION	3
7. SOLUBLE CARBON	3
8. SOLUBLE BORON	3
9. FLUORIDE	3
10. CHLORIDE	3
11. GENERAL METALLIC IMPURITIES BY A PHOTOGRAPHIC METHOD	4
12. GENERAL METALLIC IMPURITIES BY A DIRECT READER METHOD	4
13. GAS CONTENT	5
14. WATER	14
15. NITROGEN BY SPECTROPHOTOMETRY	15
16. NITROGEN BY GAS CHROMATOGRAPHY	23
17. OXYGEN	30

| D

March 1985

1

34

ANALYTICAL CHEMISTRY METHODS FOR BORON CARBIDE ABSORBER MATERIAL

1. SCOPE

This standard provides analytical chemistry methods for the analysis of boron carbide powder and pellets.

2. APPLICABLE DOCUMENTS

The following documents are a part of this standard to the extent specified herein. The issue of a document in effect on the date of the invitation to bid, including any amendments or other published changes also in effect, shall apply unless otherwise specified. Where this standard appears to conflict with the requirements of a reference document, such conflict shall be brought to the attention of the purchaser for resolution.

2.1 NE Standard.

NE F 2-8T Qualification and Control of Analytical Chemistry Laboratories for Control Rod Absorber Material Analysis

2.2 American Society for Testing and Materials (ASTM) Publications.

ASTM C 791 Chemical, Mass Spectrometric, and Spectrochemical Analysis of Nuclear-Grade Boron Carbide. | C

2.3 The Matheson Co. Publication.

Matheson Gas Data Book, 4th Edition.

3. GENERAL REQUIREMENTS

3.1 Analytical Methods. The analytical methods contained in this standard or referenced in ASTM C 791 describe acceptable equipment and procedures for use by trained analysts. Other methods approved by the purchaser may be used. Identification of brand names and model numbers are for information; equivalent equipment may be used instead. Special safety hazard precautions are noted where appropriate. The analytical methods contained herein are presented in the following typical form. The methods referenced in ASTM C 791 follow this same general format. | C

3.1.1 Application. The material to be analyzed and its form are given. Recommended sample size, range of the method, or limits of the analysis are noted.

3.1.2 Summary. A brief summary of the method is presented.

3.1.3 Interferences. Impurities or materials that can contribute to incorrect results are noted. Methods for avoiding the interferences may be given.

3.1.4 Apparatus. Specific apparatus and equipment needed for the method are listed. Equipment normally found in a chemical laboratory is usually not listed.

3.1.5 Reagents and Standards. Specific reagents and standards are given. Unless otherwise specified, analytical grade reagents shall be used. Special storage or handling requirements are noted.

3.1.6 Calibration. Requirements for the calibration of the method are given.

3.1.7 Analysis. Steps for performing the analysis are given. Precautions, recommendations and references are noted.

3.1.8 Calculations. A procedure is given, including appropriate equations, to calculate the result.

3.1.9 Precision. The relative standard deviation* or the standard deviation attainable by the method is stated. The proficiency of the analyst and the condition and adequacy of the equipment will determine the degree of precision obtained within a particular laboratory.

3.2 Laboratory Qualification. Analytical laboratories performing analyses in accordance with this standard shall conform to the requirements of NE F 2-8.

3.3 Tolerances. Unless otherwise specified, all values for measurements stated in the methods (volume, weight, time, temperature, etc.) are nominal values. The actual measurements used, however, shall be within $\pm 5\%$ of the stated value. For example, "add 20 mL" means that a volume between 19 and 21 mL shall be added. Required tolerances are specified in one of the two following ways:

1. Tolerance limits are given with the value. For example, 15 ± 0.1 mL, $1 \text{ h} \pm 10$ min, or "take a 50 mg sample weighed to the nearest 0.1 mg."
2. When one or more significant figures are given to the right of the decimal point, the tolerance limit is ± 5 in the next digit located beyond the last one stated. For example, 5.0 mL means 5.0 ± 0.05 mL.

*The standard deviation (s) expressed as a percentage of the average ($\bar{x}$) of the quantity measured; or expressed as an equation, relative standard deviation = $(s/\bar{x})(100)$.

4. TOTAL CARBON

The method given in ASTM C 791, "Total Carbon by Combustion and Gravimetry," is suitable for this analysis. When using this method, follow NE F 2-8 for calibration frequency and standard and for the procedure to calculate and use calibration data. |C

5. TOTAL BORON

The method given in ASTM C 791, "Total Boron by Titrimetry," is suitable for this analysis. When using this method, follow NE F 2-8 for calibration frequency and standard and for the procedure to calculate and use calibration data. |C

6. BORON ISOTOPIC COMPOSITION

The method given in ASTM C 791, "Isotopic Composition by Mass Spectrometry," is suitable for this analysis. When using this method, follow NE F 2-8 for calibration frequency and standard and for the procedure to calculate and use calibration data. |C

7. SOLUBLE CARBON

The method given in ASTM C 791, "Soluble Carbon by a Manometric Measurement," is suitable for this analysis. |C

8. SOLUBLE BORON

The method given in ASTM C 791, "Soluble Boron by Titrimetry," is suitable for this analysis. When using this method, follow NE F 2-8 for calibration frequency and standard and for the procedure to calculate and use calibration data. |C

9. FLUORIDE

The methods given in ASTM C 791, "Chloride and Fluoride Separation by Pyrohydrolysis" and "Fluoride by Ion-Selective Electrode," are suitable for this analysis. When using these methods, follow NE F 2-8 for calibration frequency and standard and for the procedure to calculate and use calibration data. |C

10. CHLORIDE

The methods given in ASTM C 791, "Chloride and Fluoride Separation by Pyrohydrolysis" and "Chloride by Constant-Current Coulometry," are suitable for this analysis. When using these methods, follow NE F 2-8 for calibration frequency and standard and for the procedure to calculate and use calibration data. |C

11. GENERAL METALLIC IMPURITIES BY A PHOTOGRAPHIC METHOD

The method given in ASTM C 791, "Impurities by Spectrochemical Analysis," is suitable for this analysis. When using this method, follow NE F 2-8 for calibration frequency and standard and for the procedure to calculate and use calibration data.

C

12. GENERAL METALLIC IMPURITIES BY A DIRECT READER METHOD

The method given in ASTM C 791, "Metallic Impurities by a Direct Reader Spectrometric Method," is suitable for this analysis. When using this method, follow NE F 2-8 for calibration frequency and standard and for the procedure to calculate and use calibration data.

C

13. GAS CONTENT

13.1 Application. This method is applicable to the determination of the gas content of samples of boron carbide pellets. Depending upon the blank, the lower limit ranges between 0.01 and 0.03 mL/g standard temperature and pressure (STP) with a 1 g sample. The upper limit is dependent upon the capacity of the gas measuring section.

13.2 Summary. The sample is heated by induction in a tungsten crucible at 1000°C. The evolved gas is pumped into the gas measuring section where the pressure and temperature are measured at a known volume. From these data, the millilitres per gram of gas at STP is calculated. The apparatus is designed so that a sample of the gas can be taken for an analysis of composition.¹

13.3 Interferences. With the exception of water, which may partially react with the tungsten crucible to produce hydrogen, interferences are not expected. The gases normally released obey the ideal gas laws sufficiently to permit simple ratio conversion of pressure and temperature to standard conditions.

13.4 Apparatus.

1. Induction generator.²

CAUTION: Care shall be taken to avoid contact with high frequency induction leads to prevent burns and electrical shocks.

2. Outgassing section, Fig. 1 and 2.

CAUTION: Care shall be taken while operating stopcocks and handling the apparatus when the system is under high vacuum.

- a. Furnace tube, fused-silica, water cooled.
- b. Pellet loading arm.
- c. Mercury diffusion pump.³

¹M. C. Burt, "Apparatus for Measuring Gas Release of Ceramic Nuclear Fuel Materials at High Temperatures," Anal. Chem., 41, 459, March (1969). Section 13.

²The Lepel, 2.5-kW, generator has been found satisfactory for this method.

³The NRC, G-2-M, mercury diffusion pump has been found satisfactory for the vacuum outgassing section.

Fig. 1. Outgassing Section.

- AA. MAGNET (LOCATED IN ARM "D", FIG. 1)
- BB. RING MAGNET (AROUND "AA"-OUTSIDE ARM "D")
- CC. GOLD CHAIN
- DD. TANTALUM CHAIN
- EE. TUNGSTEN CRUCIBLE
- FF. NICKEL CYLINDER
- GG. TANTALUM BAIL
- HH. HOOK AND PULLEY (SEE "F", FIG. 1)

Fig. 2. Crucible Raising and Lowering Device.

- d. Crucible raising and lowering device. See Fig. 2.
- e. Thermocouple gauge.
- f. Tungsten crucible with tantalum bail.
- g. Copper induction coil, 5 mm tubing covered with glass tape.

3. Gas measuring section, Fig. 3.

The volume between the mercury diffusion pump "L" and valves "U" and "V" is calibrated and equals V_1 in the calculation.

CAUTION: Care shall be taken while operating stopcocks and handling the apparatus when the system is under high vacuum. Mercury vapor is hazardous to health and any mercury spilled from the apparatus shall be cleaned up immediately.

lc

- a. Vacuum pumps, mechanical.
- b. Mercury diffusion pump, capable of pumping with a forepressure up to 5 torr (670 Pa).¹
- c. Stopcocks and valves located as shown in Fig. 3.

The arrangement of stopcocks "G", "H", and "J" permits the vacuum outgassing sections to be vented and pumped down independent of the gas measuring section.

- d. McLeod gauge.²
- e. Toepler pump.

A Toepler pump is included so that gas samples can be taken for analysis by mass spectrometry if desired.

- f. Thermocouple gauge.
- g. Calibrated expansion bulb.
- h. Oil diffusion pump.

¹The NRC, G-3-M, mercury diffusion pump has been found satisfactory for this purpose.

²The CVC, 3-range, type GM 100A, McLeod gauge has been found satisfactory.

Fig. 3. Gas Measuring Section.

i. Cold trap.

A cold trap is placed between the oil diffusion pump and the system to prevent backstreaming of oil vapor.

j. Residual gas analyzer (RGA). Optional.

13.5 Reagents and Standards.

1. Liquid nitrogen.

2. Magnesium perchlorate, anhydrous, for the water trap.

13.6 Calibration. No calibration standards are available to calibrate the method. Two techniques can be used to calibrate the gas measuring part of the apparatus. One is to measure the volume of each component and then add the volumes to get total volume. The second and more accurate technique is to introduce known volumes of gas into the system and measure these in the same manner as samples.

13.7 Analysis.

1. Evacuate the gas measuring section (Fig. 3) including the expansion bulb "O", Toepler pump "P", and sampling bulb "Q" by turning on the mechanical pump "R", opening valve "U", and opening the appropriate stopcocks to "O", "P", and "Q". Stopcock "G" is closed.

Once evacuated the gas measuring section is normally kept under vacuum through continuous operation of the mechanical pumps.

Steps 1 through 13 provide for loading samples into the apparatus and for establishing a blank (Step 13) before samples are analyzed.

2. Turn on diffusion pumps "L" and "S" when the pressure has decreased to less than 500 millitorr (67 Pa).
3. Fill cold trap "T" with liquid nitrogen.
4. Weigh samples to the nearest 1 mg.
5. Open stopcock "H" (Fig. 3).

The outgassing section (Fig. 1) must be at atmospheric pressure.

6. Load pellet samples into arm "B" (Fig. 1) and seal the end cap on "B" with black wax.*
7. Allow the black wax to cool and close stopcock "H".
8. Evacuate the outgassing section through stopcock "J" with mechanical pump "I" (Fig. 3).
9. Turn on diffusion pump "C" (Fig. 1) when the pressure is less than 500 millitorr (67 Pa).
10. Close stopcock "J" and the stopcocks to the expansion bulb "O", Toepler pump "P", and sampling bulb "Q"; open stopcock "G" (Fig. 3).

The outgassing section is now opened to the gas measuring section.

11. Position the crucible in furnace tube "A" (Fig. 1) within the area enclosed by the induction coil.
12. Turn the induction generator on when the pressure in the system is less than 1 millitorr (0.13 Pa).
13. Heat the crucible to 1000°C and continue heating until an outgassing leak rate of ≤ 1 millitorr (0.13 Pa)/min is reached with valve "U" closed.

This outgassing leak rate is the blank. A blank of ≤ 1 millitorr (0.13 Pa)/min is essential for samples having gas contents of ≤ 0.05 mL/g. Higher blanks are satisfactory for samples with higher gas contents. The acceptability of a blank is a matter of judgement.

The system is now ready for the sample analysis.

14. Open valve "U".
15. Turn off the induction generator and allow the crucible to cool for at least 5 min.
16. Raise the crucible to the funnel mouth at the top of the furnace tube (Fig. 1).
17. Push a sample from arm "B" into the crucible.

*Hard wax sealing compound, high vacuum, Apiezon W or equivalent.

Samples are pushed along arm "B" by an aluminum nail with an iron head, which is manipulated from the outside with a magnet.

18. Move the crucible into the area enclosed by the induction coil and close valve "U".
19. Turn on the induction generator and heat the crucible to 1000°C.
20. Take pressure readings on the McLeod gauge "N" every 5 min until the readings are constant or the rate of increase equals the blank rate.
21. Record the pressure (P_T) and turn off the generator.
The time required to obtain P_T is usually less than 30 min.
22. Record the temperature (T_S) from a thermometer placed adjacent to the gas measuring section.
23. Optional. Determine composition of the gas with a residual gas analyzer or sample the gas for mass spectrometric analysis.

If the RGA is to be used, open valves "V" and "X" and make the analysis. If a gas sample is to be taken instead, use the Toepler pump "P" and sampling bulb "Q". See Fig. 3.

24. Open valve "U" to evacuate the system.
25. Dump the spent sample to the bottom of "A" after the crucible has cooled for at least 5 min.

To dump the sample, the crucible is inverted as follows: hold the cylinder "FF" (Fig. 2), which hangs below the crucible, stationary against the wall of the bottom section of the furnace tube "A" and lower the crucible past the cylinder. The cylinder is held against the interior wall with a magnet held against the outside wall.

26. Repeat Steps 16 through 25 for subsequent pellet samples.

13.8 Calculations. Calculate the gas content using Equation 1.

$$\text{mL/g (STP)} = \frac{P_1 V_1 T_2}{T_1 P_2 W} \quad (1)$$

where

$P_1 = P_T - P_B$
 P_T = pressure from sample (Step 21 of 13.7)
 P_B = pressure of blank (Step 13 of 13.7)
 V_1 = system volume (see 13.4, Item 3)
 $T_1 = T_S (^{\circ}\text{C}) + 273$ (Step 22 of 13.7)
 $P_2 = 760$ torr
 $T_2 = 273$ K
 W = sample weight, grams.

13.9 Precision. The estimated relative standard deviation of the method is 5%.

nuclear

F 11-2T

14

14. WATER

The method given in ASTM C 791, "Water by Constant-Voltage Coulometry" is suitable for this analysis.

|C

15. NITROGEN BY SPECTROPHOTOMETRY

15.1 Application. This method is applicable to the determination of nitrogen in samples of boron carbide powder and pellets. From 25 to 1500 μg of nitrogen can be determined in a 0.1 g sample.

15.2 Summary. The sample is mixed with lithium hydroxide and fused to decompose the boron carbide. The nitride nitrogen is converted to ammonia, which is trapped in a hydrochloric acid solution. The ammonium ion is measured spectrophotometrically using the colored complex produced by Nessler reagent.

15.3 Interferences. Interference from material normally found in nuclear-grade boron carbide is not expected. Ammonia from extraneous sources will give a high bias.

15.4 Apparatus.

1. Analytical balance capable of weighing to 0.1 mg.
2. Combustion tube with combustion tube cap and delivery tube (see Fig. 4.)
3. Crucible, nickel. (See Fig. 5.)
4. Diamond (Plattner) mortar.
5. Flowmeter, Manostat No. 1044B or equivalent.
6. Induction furnace, Leco No. 523-100 or equivalent.
7. Porous lids, Leco No. 528-42 or equivalent.
8. Sieve, 100 mesh (U.S. Standard Sieve Series), 3 in. (76 mm) diameter, brass or stainless steel.
9. Spectrophotometer, UV to visible range, using 10 mm matched cells.
10. Tin capsules, Leco No. 501-059 or equivalent.
11. Variable transformer, Leco No. 521-084 or equivalent, used with the induction furnace.
12. V-Blender, 15 mL volume.

Fig. 4. Nitrogen Apparatus.

Fig. 5. Nickel Crucible.

15.1 Reagents and Standards.

1. Argon, prepurified grade or equivalent.*
2. Deionized water, ammonia-free.
3. Hydrochloric acid, 12M (37%).
4. Lithium hydroxide, anhydrous.

Lithium hydroxide is dried at 120°C and stored in a desiccator.

5. Nessler reagent.

Dissolve 100 g of mercuric iodide and 70 g of potassium iodide in a small quantity of ammonia-free water. Add this solution slowly, with stirring, to a cool solution of 160 g of sodium hydroxide in 150 ml of ammonia-free water. Dilute to 1 litre with ammonia-free water and store in a dark glass bottle.

6. Calibration standard, boron nitride powder.

The boron nitride may be blended with boron carbide powder having a low residual nitrogen content.

15.6 Calibration. Using at least five calibration points ranging up to 1500 µg of nitrogen, calibrate the method as follows:

1. Analyze weighed portions of the calibration standard and a reagent blank by following 15.7. Subtract the absorbance reading of the reagent blank from the absorbance reading of each standard.

A secondary calibration of the spectrophotometer can be made using a standard solution of an ammonium salt.

2. Prepare a calibration curve by plotting absorbance versus micrograms of nitrogen. The curve will range up to 150 µg of nitrogen.
3. A new calibration curve is not required each time nitrogen analyses are made, although at least one point on the calibration curve is checked during each 8-h shift in which analyses are made. When checking a point, the method is in calibration

*See Section 2.3.

if the result obtained falls within $\pm 10\%$ of the curve. A new calibration curve is made when the checks made on the curve begin to show a drift away from the curve, the results of two consecutive analyses of standards are outside of the $\pm 10\%$ limit, or a new batch of Nessler reagent is used.

15.7 Analysis. The laboratory atmosphere must be free of ammonia and other nitrogen-containing fumes to avoid nitrogen contamination of glassware, reagents, and samples. A reagent blank is determined at least once in each 8-h shift in which analyses are made.

1. Determine a reagent blank by starting at Step 2 but omitting Step 5 (an empty tin capsule is added at Step 6).

If the absorbance of the reagent blank is greater than 0.08, repeat the blank determination until a reproducible absorbance at or below 0.08 is obtained. If a satisfactory blank is not obtained, a probable cause is contamination. Replace reagents or eliminate the source of extraneous nitrogen, as necessary, to reduce the blank to an acceptable level.

2. Turn on the power to the induction furnace and allow 15 min for warm-up.
3. Clamp the combustion tube cap and delivery tube in place and adjust the argon flow rate to 0.4 L/min.

The combustion tube, cap, and delivery tube must be clean.

4. Add 5 g of lithium hydroxide to the crucible.
5. Add about 0.1 g of powdered sample to a tared tin capsule and weigh capsule and sample to the nearest 0.1 mg.

Prepare the powdered sample as follows:

- a. Place the sample into a clean diamond (Plattner) mortar.

The pestle face and mortar cavity should be machined occasionally to remove pits.

- b. Crush the sample with a few, light hammer blows.

Do not crush and grind the boron carbide extensively because significant iron contamination can occur.

- c. Transfer the crushed sample to the sieve and shake until the finer material has passed through the sieve and been collected.

- d. Return the coarse material from the sieve to the mortar and repeat Steps a and b until the whole sample has passed through the sieve.
 - e. Remove iron particles by passing a magnet over the sieved powder.
 - f. Mix the sieve sample thoroughly.
6. Add the capsule containing sample to the crucible containing the lithium hydroxide.
 7. Remove the cap from the combustion tube; place the crucible on the furnace pedestal in the induction furnace; place the porous cover on the crucible.
 8. Clamp the cap and delivery tube back in place and let the argon sweep through the apparatus for at least 5 min.

The ball and socket joints should be greased with silicone lubricant.

9. Add 30 mL of ammonia-free water and 2 drops of 12M hydrochloric acid to a 50 mL cylinder.

The cylinder must be positioned in the apparatus such that the delivery tube is immersed below the surface of the acid solution.

10. Turn the grid tap setting to medium; turn on the high voltage.
11. Increase the plate current in sequential steps to increase the furnace temperature as shown in Table 1.

Table 1. Plate Current Settings

Variable Transformer Setting	Plate Current, mA	Minutes
Med. 40	160	2
Med. 96	230	2
High 96	250	10

The actual temperature obtained at 250 mA should be measured and if the temperature is not about 750°C, the upper current setting should be adjusted to obtain approximately 750°C. The decomposition temperature should be between 700 and 750°C.

The heating sequence depends upon sample characteristics including particle size and solubility in lithium hydroxide. Some samples froth and blow out of the crucible. For these samples, loss can be eliminated by heating for longer periods at lower temperatures.

12. Turn off the furnace.
13. Remove the cap from the combustion tube and the cover from the crucible.
14. Remove the crucible and pour the molten lithium hydroxide into a metal waste can; thoroughly clean and dry the crucible.
15. Rinse the inside and outside of the delivery tube into the 50 mL cylinder with ammonia-free water.
16. Transfer the solution to a 50 mL volumetric flask; rinse the cylinder several times with ammonia-free water, adding the rinses to the volumetric flask.
17. Dilute the solution to volume with ammonia-free water and mix thoroughly.
18. Transfer 5.0 mL of the solution to a second 50 mL volumetric flask.
19. Add 1.0 mL of the Nessler reagent to the flask.
20. Dilute the solution to volume with ammonia-free water and mix thoroughly.
21. Let stand for 10 min and measure the absorbance of the solution at 410 nm in a 10 mm cell using distilled water as the reference solution.

If the sample absorbance indicates an amount of nitrogen less than 25 μg or greater than 150 μg in the 5 mL aliquot from Step 18, repeat Steps 18, 19, 20, and 21, using an appropriate volume of sample solution at Step 18.

15.8 Calculations. Calculate the micrograms of nitrogen per gram of sample as follows:

1. Subtract the absorbance reading of the reagent blank from the absorbance reading of each sample.
2. Obtain the micrograms of nitrogen for each sample from the calibration curve.

3. Calculate the concentration of nitrogen in the sample using Equation 2.

$$\text{Nitrogen} = \frac{S}{W} \quad (2)$$

where

Nitrogen = micrograms of nitrogen per gram of sample
s = micrograms of nitrogen from sample measurement
W = sample weight, grams.

15.9 Precision. The pooled relative standard deviation obtained by four laboratories for a single boron carbide powder batch was 6% at a nitride nitrogen level of 0.3% (by weight).

16. NITROGEN BY GAS CHROMATOGRAPHY

16.1 Application. This method is applicable to the determination of nitrogen in samples of boron carbide powder and pellets. From 5 to 2500 μg of nitrogen can be determined in a 0.1 g sample.

16.2 Summary. Powdered or small pieces of boron carbide are fused with nickel at about 2600°C in a graphite crucible. The nitrogen is released in its elemental form and it is measured by gas chromatography, which is based upon the differences in thermal conductivity of gases.

16.3 Interferences. Nitrogen from the atmosphere will enter the nitrogen analyzer if the sample is improperly loaded and this will cause a high result. Ammonia, nitrates, and other nitrogen-containing compounds from extraneous sources will cause high results.

16.4 Apparatus.

1. Analytical balance capable of weighing to 0.1 mg.
2. Nickel basket, LECO No. 763-065 or equivalent.
3. Nitrogen analyzer.*
4. Tin capsule, LECO No. 501-059 or equivalent.

16.5 Reagents and Standards.

1. Anhydrone, LECO No. 501-171 or equivalent.
2. Ascarite, 20 to 30 mesh, LECO No. 183-001 or equivalent.
3. Ascarite, 8-20 mesh, LECO No. 501-166 or equivalent.
4. Helium, ultra high purity, 99.995%.
5. Molecular sieve, 5A, 20 to 30 mesh.
6. Phosphorus pentoxide, LECO No. 765-278 or equivalent.
7. Rare earth oxide, LECO No. 501-170 or equivalent.
8. Sulfur absorber, LECO No. 763-770 or equivalent.
9. Calibration standards.

*The LECO U014 sp Nitrogen Determinator, Model No. 875-034, has been found satisfactory.

Standards are prepared by mixing weighed amounts of boron nitride with boron carbide powder having less than 0.05% nitrogen. In addition, the following steel standards are used for instrument calibration and test: NBS SRM 346 and 133a and LECO No. 501-551, No. 501-552, and No. 501-553.

16.6 Calibration.*

1. Prepare the instrument for analysis. The analyzer must conform to the following:
 - a. Be sure that the water supply to the coolant circulator has not been shut off or disconnected; then turn on the coolant circulator power switch.
 - b. "DVM ON" switches must be on.
 - c. "AUX TURN ON" indicator must be on.
 - d. The "FUNCTION SWITCH" switch must be in the "OPERATE" position.
 - e. The two circuit breakers must be on.
 - f. The "STD-BY" indicator must be green.
 - g. The "HELIUM BLANKET" indicator must be off.
 - h. The coolant circulator power switch must be on.
 - i. The furnace must be empty and closed.
 - j. The "OVEN INDICATOR" must be cycling on and off and the oven temperature must be approximately 45°C.
 - k. The helium regulator must be set for 40 psig (275 kPa).
 1. Both the "MEASURE FLOW" and the "REFERENCE FLOW" rotometers must indicate the approximate flows.
 2. Turn the "FUNCTION SELECT" switch to the "DVM ZERO" and adjust the digital voltmeter (DVM) zeros if necessary.

*This method is based upon the LECO U014 sp Nitrogen Determinator Model No. 875-934. If another analyzer is used, follow the manufacturer's recommended procedure.

3. Depress the "STD-BY" switch. Turn the "FUNCTION SELECT" switch to the "OPERATE" position for approximately 30 s. Then turn the "FUNCTION SELECT" switch to the "INTEG CHECK" position and note the time; at the end of 1 min note the reading.

The DVM reading must not change more than ± 0.001 during this period. If it does, refer to the electronic checkout in the instruction manual.

4. Depress the "STD-BY" switch. Turn the "FUNCTION SELECT" switch to the operate position.

The "STD-BY" indicator should turn green.

5. Open the furnace.

The "PURGE" indicator will turn white and the "STD-BY" indicator will go off.

Inspect the interior of the upper electrode cavity with a mirror and flashlight to make sure that no deposits of graphite or other material are present. Also inspect the lower electrode. The bottom interior of the lower cup must be free from all metal or graphite particles. A small jet of air is ideal for cleaning the bottom interior of the lower electrode. Use the proper brush and precautions should be taken to prevent scratching of the electrodes or the O-rings.

Do not insert your fingers or any metallic object near the safety thermostat mounted on the outside of the upper electrode. When power is applied, there is 115 V on these connections.

6. Place a LECO crucible on the lower electrode assembly using tweezers.

To avoid contamination, do not touch the crucibles with your fingers.

7. Close the furnace.

The "PURGE" indicator will turn green.

The furnace must be kept closed at all times except when cleaning the interior of the furnace or loading the crucible. The furnace must be cleaned before each analysis.

8. Depress the "OUT-GAS" switch.

The "OUT-GAS" indicator will be white during the outgas period and the "PURGE" indicator will be off.

The crucible current value is indicated on the "FURNACE POWER" meter and during outgas, the value should be between 850 and 950 A. If not, refer to the procedure described in the installation section of the instruction manual.

9. Compensate for a normal nitrogen blank as follows:

- a. Repeat Steps 4 through 8.
- b. The "OUT-GAS" indicator must be green.

Do not put a sample into the crucible at this time.

- d. Depress the "ANALYZE" switch.

The "ANALYZE" indicator will turn white and the "OUT-GAS" indicator will go off.

When the "ANALYZE" indicator goes off, the "NITROGEN" indicator will turn green. The "BLANK" control must be adjusted before the "NITROGEN" indicator turns green.

- e. Adjust the "NITROGEN BLANK" control while the "NITROGEN" indicator is white to maintain all zeros on the "NITROGEN" DVM.
- f. Repeat this procedure with a minimum of three crucibles to establish the proper "NITROGEN BLANK" setting.

10. Calibrate the "SLOPE" adjustment as follows:

- a. Repeat Steps 4 through 6.
- b. Place a steel calibration standard of a weight between 0.300 and 0.699 g into the loading head.

Be sure to handle the sample only with tweezers.

The sample form must be such that it can be contained in a cylinder 6 mm in diameter and 8 mm high.

- c. Turn the "SAMPLE WEIGHT COMPENSATOR" switches to the value of the weighed sample.
- d. Close the furnace.
- e. Depress the "OUT-GAS" switch.

- f. Push the "SAMPLE DROP" button after the "OUT-GAS" indicator turns green.

This lets the standard fall into the crucible.

- g. Depress the "ANALYZE" switch.

The "OUT-GAS" indicator will go off and the "ANALYZE" indicator will turn white.

The crucible current value should be slightly lower than during outgas (approximately 30 A lower). If the current is considerably lower, the sample may not have fallen into the crucible - check the loading head cavity.

- h. Note the reading when the "NITROGEN" indicator turns green, but do not adjust the slope control.
- i. Repeat this procedure for a minimum of three standards to determine the average reading.
- j. If the average reading is within the tolerance stated for the sample, no adjustment is needed. If the average reading is above or below the tolerance for the nitrogen standard value, adjust the slope control to bring the average value within the tolerance.

The slope adjustment can be made only when the "NITROGEN" indicator is white.

Never attempt to open or close the furnace during "OUT-GAS" or "ANALYZE" (indicators white) because the furnace electrodes of the a-c switch will be severely damaged.

11. Prepare a calibration curve by repeating Step 10, except use the boron carbide calibration standards instead of a steel standard at Step 10b. The boron carbide is placed into a tin capsule; the ends are pinched closed and the capsule is placed into a nickel basket, which is then placed into the loading head.

- a. Analyze at least five portions of the standards to provide calibration points ranging between 10 and 1000 μg of nitrogen.

The amounts of standard taken should be between 0.06 and 0.15 g.

- b. Determine a tin capsule and nickel basket blank using one empty capsule and basket at Step 10b; make at least three determinations and calculate an average blank.

- c. Subtract the average blank from each standard readout and prepare a calibration curve by plotting the net readouts versus micrograms of nitrogen using linear graph paper.

A new calibration curve is not required each time nitrogen analyses are made, although at least one point on the curve must be checked during each 8-h shift in which analyses are made. The method is in calibration if the result falls within +5% of the curve. A new curve is required if two consecutive results fall outside +5%.

16.7 Analysis.

1. Repeat Steps 4 through 6 of 16.6.
2. Place a sample weighing between 0.06 and 0.15 g into the loading head.

The sample form must be such that it can be contained in a cylinder 6 mm in diameter and 8 mm high.

Weigh powdered samples in tin capsules; pinch the ends in and place in a nickel basket. Weighed pieces are placed directly into a nickel basket.

Contamination of samples with nitrogen from air can be eliminated by weighing in an argon atmosphere.

For samples containing less than 0.5% nitrogen, the 0 to 1000 μg range should be used; for more than 0.5%, the 0 to 10,000 $\mu\text{g/g}$ range should be used.

3. Turn the "SAMPLE WEIGHT COMPENSATOR" switch to 0.5.
4. Close the furnace.
5. Depress the "OUT-GAS" switch.
6. Push the "SAMPLE DROP" button after the "OUT-GAS" switch turns green.

This lets the sample fall into the crucible.

7. Depress the "ANALYZE" switch.

The "OUT-GAS" indicator will go off and the "ANALYZE" indicator will turn white.

The fusion current should be at least 850 A, which requires the highest transformer top setting possible without causing crucible breakdown.

If current drops to zero during analysis, discard the result and repeat the analysis.

As soon as the "NITROGEN" indicator turns green, the impulse furnace may be opened and the used crucible removed. The furnace can be cleaned and next sample introduced into the loading head.

When the "NITROGEN" indicator turns green, the micrograms of nitrogen will be displayed on the DVM.

16.8 Calculations. Calculate the concentration of nitrogen in the sample using Equation 3.

$$\text{Nitrogen} = \frac{(A-B)}{2W} \quad (3)$$

where

Nitrogen = nitrogen content in micrograms per gram

A = micrograms of nitrogen determined from the DVM readout and the calibration curve

B = average tin capsule blank, micrograms of nitrogen

W = sample weight, grams.

16.9 Precision. At the 0.7% level of nitrogen, a relative standard deviation of 1.7% was obtained from 9 replicate measurements.

17. OXYGEN

17.1 Application. This method is applicable to the determination of oxygen in samples of boron carbide powder and pellets. Between 30 and 100 μg oxygen are required per measurement.

17.2 Summary. Powdered boron carbide is fused with iron chips at 2600°C in a graphite crucible. Oxygen is evolved as carbon monoxide, which is converted to carbon dioxide when passed over heated rare earth oxide. The carbon dioxide is measured by thermal conductivity gas chromatography. A water analysis is required to correct the oxygen results for any water sorbed by the powdered material.

17.3 Interferences. Boron carbide (especially in powdered form) readily sorbs water, which contributes to the oxygen concentration. By analyzing samples for water, a correction for the water contribution can be made to minimize this bias. Sorbed gases such as carbon dioxide, carbon monoxide, oxygen, and sulfur dioxide also contribute to the total oxygen content; however, the extent of their contribution is unknown. Since all analyses are performed on powdered materials, which may readily sorb these gases, a high bias may result. To eliminate the possibility of this bias, analyses should be performed in an inert atmosphere enclosure, if possible.

17.4 Apparatus.

1. Crucibles, graphite, LECO No. 760-414 or equivalent.
2. Oxygen analyzer.¹

17.5 Reagents and Standards.

1. Anhydron, LECO No. 501-171 or equivalent.
2. Ascarite, LECO No. 501-166 or equivalent.
3. Copper shot, 6 to 8 mesh, LECO No. 501-641 or equivalent.
4. Iron chips, LECO No. 501-077 or equivalent.
5. Nitrogen, prepurified grade or equivalent.²
6. Rare earth oxide, LECO No. 501-170 or equivalent.

¹The LECO RO-16 Oxygen Determinator, Model 738-400, has been found satisfactory.

²See Section 2.3.

7. Calibration standards.

The following standards are used for a primary and a secondary calibration:

- a. Steel pins with certified oxygen contents, LECO No. 501-644, 645, and 646 or equivalent.
- b. Carbon dioxide, Coleman grade or equivalent.*

8. Control standards.

The following materials are used for control purposes:

- a. Boric acid, NBS SRM 951 or boron trioxide, ultra high purity (>99.99%).
- b. Boron carbide, -100 mesh containing >0.05% oxygen.

17.6 Calibration.

1. Primary and secondary calibrations are made during each 8-hour shift in which oxygen analyses are made as follows:

- a. Primary calibration. Analyze each of the calibration standards using the manufacturer's recommended procedure.

All standards must give values within their stated ranges before proceeding to Step b.

- b. Secondary calibration. Crosscheck primary calibration by using the built-in, calibrated, carbon dioxide, gas-dosing system following manufacturer's instructions.

The values obtained for the carbon dioxide injections should fall within the recommended levels before proceeding with the analysis of control standards and samples.

2. A control procedure is used during each 8-h shift in which oxygen analyses are made. The procedure is as follows:

- a. Determine the average total oxygen content of the boron carbide reagent by analyzing three portions of the reagent by following Steps 2 through 8 of 17.7.

The results should agree within 0.02% absolute.

*See Section 2.3.

Because the water content of the boron carbide reagent can vary, the total water content must be determined whenever oxygen analyses are made on the reagent.

- b. Weigh 500 to 1000 μg of boric acid or boron trioxide to +10 μg and add it to 0.1 g of the boron carbide reagent; analyze by following Steps 3 through 8 of 17.7 and calculate the percent recovery using 17.8.2.

Proceed with the analyses of samples only after recoveries between 90 and 110% have been demonstrated for three consecutive samples.

17.7 Analysis.

1. Determine a system blank by following Steps 3 through 10, omitting the sample in Step 4.

Blanks shall be determined initially until a reproducibility of +3 μg of oxygen is obtained. Repeat the blank measurement after every five samples.

Powdered samples are loaded by opening the furnace to add the material to the crucible; therefore, higher and more variable blanks are expected than those observed when analyzing steel standards which are dropped into an outgassed crucible in a closed furnace.

2. Weigh from 0.1 to 0.15 g of sample in the powdered form to the nearest 0.1 mg.

For pellet samples, crush to a powder as follows:

- a. Place the sample into a clean diamond (Plattner) mortar.

The pestle face and mortar cavity should be machined occasionally to remove pits.

- b. Crush the sample with a few, light hammer blows.

Do not crush and grind the boron carbide extensively because significant iron contamination can occur.

- c. Transfer the crushed sample to the sieve and shake until the finer material has passed through the sieve and been collected.

- d. Return the coarse material from the sieve to the mortar and repeat Steps a and b until the whole sample has passed through the sieve.

- e. Remove iron particles by passing a magnet over the sieved powder.
- f. Mix the sieve sample thoroughly.

A V-blender can be used for mixing. Tests have indicated that V-blending is necessary to obtain a homogeneous sample for the nitrogen and oxygen methods.

Experience has shown that the oxygen in boron carbide pellets is seldom distributed homogeneously. Since entire pellets cannot be analyzed, samples are crushed and sieved to obtain a more uniform material with respect to oxygen. Mixing should be done in a V-blender.

- 3. Add 2 g of iron chips to a graphite crucible; load and outgas by following the instruction manual.
- 4. Remove the outgassed crucible and quantitatively transfer the sample from Step 2 to the crucible.

Handle the crucible only with clean forceps.

- 5. Position the crucible in the furnace and close.
- 6. Depress the reset switch.

This allows the sample to be purged with nitrogen to remove any oxygen introduced while loading the sample.

- 7. Complete the analysis by depressing the "analyze" switch.

Once the analyze switch is depressed, the entire operation is automatic.

- 8. Record the micrograms of oxygen from the digital voltmeter (DVM) readout.
- 9. Immediately make a moisture analysis on the sample material using Method 14 and record the micrograms of water per gram of sample.

17.8 Calculations. Calculate the percent of oxygen in the samples and the percent recovery from control standards using 17.8.1 and 17.8.2.

17.8.1 Samples. Calculate the oxygen content of samples using Equations 4 and 5.

$$T.O. = \frac{(A-B)(10^{-4})}{S_o} \quad (4)$$

$$N.O. = T.O. - (H) (8/9) (S_o) (10^{-4}) \quad (5)$$

where

T.O. = total oxygen, weight percent

A = total micrograms of oxygen displayed on DVM (Step 8, 17.7)

B = average system blank in micrograms of oxygen (Step 1, 17.7)

S_o = sample weight, grams

N.O. = net oxygen, weight percent (total oxygen minus oxygen contributed from the water present in the sample).

H = micrograms of water per gram sample (Step 9, 17.7).

17.8.2 Control Standards. Calculate the percent recovery using Equation 6.

$$R = \frac{(A-B) - \left[\frac{(B_{A.R.}) (S_R)}{O_c} \right]}{O_c} \times 100 \quad (6)$$

where

R = percent recovery

A = total micrograms of oxygen displayed on DVM (Step 8 of 17.7)

B = average system blank in micrograms of oxygen (Step 1 of 17.7)

B_{A.R.} = average boron carbide reagent blank in total micrograms of oxygen per gram of reagent

S_R = grams of boron carbide reagent used

O_c = micrograms of oxygen from boric acid or boron trioxide added to boron carbide reagent.

17.9 Precision. The relative standard deviation for samples ranging from 0.1 to 0.7% oxygen is about 11%.

D

END

DATE
FILMED

5/04/93