DECLASSIFIED

GENERAL ELECTRIC

HANFORD ATOMIC PRODUCTS OPERATION - RICHMOND, WASHINGTON

HW--58153

DE92 018859

☒

RESTRICTED DATA

THIS DOCUMENT CONTAINS RESTRICTED DATA AS DEFINED IN THE ATOMIC ENERGY ACT OF 1954. ITS TRANSMITTAL OR THE DISCLOSURE OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED.

TITLE

THROUGH REACTOR DECONTAMINATION
A TECHNICAL STATUS REPORT

☐

OTHER OFFICIAL CLASSIFIED INFORMATION

THIS MATERIAL CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECS. 793 AND 794, THE TRANSMISSION OR REVELATION OF WHICH IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.

AUTHOR

N. R. Miller
R. B. Hall

ORIGINAL FILE
RECEIVED

RETURN TO

TECHNICAL INFORMATION FILES

THIS DOCUMENT MUST NOT BE LEFT UNATTENDED OR WHERE AN UNAUTHORIZED PERSON MAY HAVE ACCESS TO IT. WHEN NOT IN USE, IT MUST BE STORED IN AN APPROVED LOCKED REPOSITORY OR AN APPROVED GUARDED AREA. WHILE IT IS YOUR POSSESSION AND UNTIL YOU HAVE OBTAINED A SIGNED RECEIPT FROM CLASSIFIED FILES, IT IS YOUR RESPONSIBILITY TO KEEP IT AND ITS CONTENTS WITHIN THE LIMITS OF THIS PROJECT AND FROM ANY UNAUTHORIZED PERSON. ITS TRANSMISSION AND STORAGE AT YOUR PLACE OF RESIDENCE IS PROHIBITED. IT IS NOT TO BE DUPLICATED. IF ADDITIONAL COPIES ARE REQUIRED, OBTAIN THEM FROM THE RELATED ISSUING FILE. ALL PERSONS READING THIS DOCUMENT ARE REQUESTED TO SIGN IN THE SPACE PROVIDED BELOW.

ROUTE TO:	PAYROLL NO.	LOCATION	FILES ROUTE DATE	SIGNATURE AND DATE
<i>C. J. Miller</i>	<i>1445</i>	<i>1704 H</i>	<i>11-25-58</i>	<i>PD Jones 2/4/57</i>
<i>D. S. K. ...</i>				
<i>H. S. K. ...</i>	<i>1001</i>	<i>1703 H</i>	<i>2-16-59</i>	<i>M. H. ...</i>

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

DECLASSIFIED

DISTRIBUTION

1. JA Ayres-JF Hokenson
2. JT Baker
3. RS Bell
4. RV Bowersock
5. JH Brown
6. RG Clough
7. RL Dickeman
8. EF Fairweather
9. EJ Fillip
10. OH Greager
11. C Groot-B Griggs
12. CN Gross
13. RE Hall
14. WM Hartly
15. RR Henderson
16. ET Hubbard
17. HF Jensen
18. PC Jerman
19. RT Jessen ←
20. DS Lewis
21. CO Lewis
22. WK MacCreedy
23. AR Maguire
24. JS McMahon
25. JHM Miller
26. NR Miller
27. JF Music
28. RW Reid
29. HQ Spencer
30. P Thompson
31. RE Trumble
32. FW Woodfield
33. 300 Files
34. Record Center
- 35-39. Extra

Classification Cancelled (Change to

DeclassifiedBy Authority per doc May 1973See Encl. 6/1/92
PM Encl 6-1-92

part 1 of 1, SERIES MA

This document consists of
10 pages. No. 11 of
39 copies. Series A.

This document classified by

Due to film deterioration,
 portions of this document
 may be illegible.

48
1
3

FWL-6-1-1972
 Classified person is prohibited.

November 12, 1958

THROUGH-REACTOR DECONTAMINATION
A TECHNICAL STATUS REPORT

DECLASSIFIED

DECLASSIFIED

HW-58153
Page 2

INTRODUCTION

Attention has focused on the feasibility of conducting through-reactor, internal decontaminations in order to reduce rear face radiation levels and alleviate personnel exposure problems.

The purpose of this report is to review the technical aspects of "through-reactor" decontaminations and to present an interim recommendation regarding the use of this method.

SUMMARY AND CONCLUSIONS

From the data obtained to date, it is concluded that a through-reactor decontamination with Turco 4306-B will cause a significant added corrosion of fuel jackets and process tubes. Each decontamination may result in an added 2 mils of corrosion on the central zone tubes and at least a temporary increase in jacket corrosion rates to values between 1.5 and 2.5 times their previous values.

The reduction in rear face radiation levels would be about the same as obtained with rear face only decontamination but the reduction would likely persist longer.

The conclusions are not regarded as final, but rather reflect the status of investigations to date.

RECOMMENDATIONS

In view of the significant deleterious effects and unknowns involved, full scale through-reactor decontamination with Turco 4306-B might be very costly. It is therefore recommended that consideration of such tests be deferred until additional data has been obtained and evaluated.

Rear-face only decontaminations are considered acceptable if special end-caps are employed to direct the decontaminant directly into the storage basins without spraying it against the reactor rear-face piping. Also, decontamination of process tubes just prior to their removal is considered acceptable if the tubes are not leakers.

While the above recommendations are not final, no bases for making changes are expected before April, 1959.

DISCUSSION

1. Background

An immediate method of obtaining relief from the personnel radiation exposure problem is to reduce reactor rear face radiation levels by some type of a chemical decontamination. Two methods of performing this decontamination have

REDACTED

been studied. 1) Decontaminate the internal surfaces of rear face piping by introducing the decontaminant through the relief riser through the rear crossheader and out the rear nozzle, and 2) Feed the decontaminant from a high tank to the front face coolant distribution system, through the reactor and out the regular effluent system. Turco 4306-B, a proprietary material, would be used in either scheme of decontamination inasmuch as it has received extensive development.

The advantages of the through-reactor method:

- 1) Reduced reactor outage time requirement.
- 2) Reduced personnel exposure requirements for the treatment.
- 3) A possible longer lasting reduction of radiation levels.
- 4) Better containment of the spent decontaminant - radioactive materials mixture.

The disadvantages of the through-reactor method include:

- 1) Probability of increased corrosion of fuel element jackets.
- 2) Probability of increased corrosion of process tubes.
- 3) Increased possibility of introduction of decontaminant into the graphite stack via tube leaks.
- 4) Possibility of damage to the critical front face reactor piping.

During the past several months, a considerable amount of information has been obtained on the technical aspects of the preceding list of advantages and disadvantages. This technical information is discussed below.

2. Effects of the Turco Flush on Aluminum Corrosion

Aluminum exposed under isothermal conditions to water, corrodes in the manner shown in Figure I.

Figure 1

GENERAL ALUMINUM CORROSION BEHAVIOR UNDER ISOTHERMAL CONDITIONS

DECLASSIFIED

DECLASSIFIED

HW-50153

Page 4

The instantaneous corrosion rate is the slope of the curve at any point. As can be seen, the corrosion rate decreases regularly until some time (represented by point [A,B] on the graph) and then becomes constant.

The reduction of the rate is caused by the growth of the corrosion-product oxide film which forms a diffusion barrier. At point "B", the oxide layer reaches a maximum thickness and the rate becomes constant.

When a corroded aluminum surface is flushed with Turco 4306-B, some or all of the oxide layer can be expected to be removed or damaged, and a higher rate can be anticipated to return for a period. The net extra corrosion caused by the flush will be equal to the corrosion occurring during the flush plus an amount roughly indicated by point "C" on the graph, a point established by an extrapolation of the linear portion of the curve to zero time. The net increase in corrosion following the flush will depend on water quality and temperature, being in general higher for a more corrosive water and higher water temperature.

The corrosion of process tubes is roughly equivalent to the idealized isothermal case (Figure 1), and an effort has been made to determine the magnitude of the added corrosion of process tubes attributable to a Turco 4306-B decontamination.

Data on process tubes have been obtained by D. E. Sturge of the Component Testing Operation which are pertinent to the problem. Sturge has obtained measurements on three tubes from H Reactor. The rear portions of these tubes were contacted with Turco 4306-B on 8/2/57 when the rear face of the reactor was decontaminated.

In all three cases both the top and the bottom portions of the tubes near the rear Van Stone Flange were thinner than portions of the tube about 8 inches upstream of the rear flange. The difference in wall thicknesses varied from 1.0 to 3.4 mils with the average of the six comparisons being 1.8 mils.

In addition, Sturge has also obtained data from three other tubes for control. One of the tubes was from DR, one from D, and one from C Reactor. Neither the D nor C Reactor tubes were contacted with Turco. The DR tube had been contacted with Turco less than one operating month before the measurement was taken. Little extra corrosion would be expected in this period.

No variation was found in the thickness of bottom portions of any of the latter three tubes. A variation was found in the thickness of the top portions of process tubes obtained from C and DR Reactors with the tube from C Reactor being 9.7 mils thinner near the Van Stone Flange than 8 inches upstream of the flange. Sturge is of the opinion that the sections taken from the tops of the tubes may have been obtained in an area where the tube wall was reduced by the reaming operation preparatory to forming the flange. More data from H and other reactors will be obtained to clarify the situation.

With some reservations, the data are interpreted as indicating that the contact with the Turco flush resulted in an added 1-2 mils of corrosion at the rear of the tubes. Process tube corrosion rates are significantly higher near the rear

SECRET

of the metal charge because of the temperature variation around the annulus due to annulus eccentricity. Therefore, if the extra corrosion is in the order of 1-2 mils at the rear of the tube, the effect may be greater near the end of the metal charge where the higher rates are found. For the time being, it will be assumed that approximately 1200 central zone tubes (in the 6 older reactors) would experience an added attack of about 2 mils. This is equivalent to the loss of about 80 tubes per decontamination. This "loss" will not be realized immediately but will be spread out over a central zone retubing cycle of about four years duration.

The situation in regard to fuel jackets is somewhat more complicated than for process tubing. The complications arise from two sources: 1) An oxide film is pre-formed on the jackets by the 300 Area autoclaves and the corrosion loss corresponding to point "C" of Figure 1 is relatively small, perhaps a fraction of a mil. The cause of the initial loss being small seems to be: 1) A diffusion barrier is present at the onset and initial rates are minimized, and 2) As the film increases in thickness, the extra protection afforded by the thicker film is offset by higher diffusion rates, resulting from an elevation of temperatures in the oxide layer which prevents a decrease in rates. When a corroded fuel element is decontaminated with Turco, the oxide layer can be at least partially removed and/or damaged - that is, the film may not be completely removed but may be attacked in such a way as to destroy its roles as a diffusion barrier. With almost complete removal, corrosion rates would be accelerated until the oxide film is re-established. If the oxide layer is damaged, i.e., no longer protective, it serves only to elevate temperatures where the rate controlling process occurs and rates will be accelerated.

Some data on fuel elements contacted with Turco 4306-B have been obtained. Griggs reports that 4 oz/gal of Turco 4306-B at 50°C does not attack the "non-corroded", autoclaved, element during a five minute exposure, and it is presumed that at least at 50°C, the Turco has no effect on the autoclaved oxide film. However, after exposure to process water the oxide is apparently modified. Lane exposed autoclaved dummy fuel elements to process water at 120°C for two weeks and then flushed the dummy elements with a 2.5% solution of Turco 4306 at 80°C for ten minutes, and found attack had taken place. Hokenson found a similar effect at 50°C.

Thus, it can be seen that corroded elements flushed with Turco 4306-B may exhibit an accelerated corrosion attack. Some data have been obtained which indicates that such an acceleration does occur. Lane re-exposed the flushed elements to process water at 120°C for an added 76 days. During this 76 day period, the incremental weight loss was triple what one would expect from elements exposed only to the 120°C process water. The actual "extra" corrosion was only about 0.2 mils, a negligible amount; but, the test indicated that the protective oxide was removed or damaged by the solution.

An in-reactor test was then conducted to determine quantitatively the effects of a flush on fuel elements exposed to process conditions. Because of the damage

DECLASSIFIED

DECLASSIFIED

HW-58153
Page 6

Lane noted at 80°C, the in reactor test was conducted at 50°C. Further, two passivating treatments were tested in the hope that any damage to the oxide could be quickly healed. Details of the test are shown below:

TABLE I
CONDITIONS OF TEST TO EVALUATE EFFECTS OF
TURCO 4306-B ON FUEL JACKET CORROSION

<u>Number of Tubes</u>	<u>Flushed with Turco 4306-B</u>	<u>Remarks</u>
2	No	These charges utilized as controls.
2	Yes	No post-treatment applied.
2	Yes	Flush with Turco 4306-B followed with a flush of 50 ppm dichromate.
2	Yes	Flush with Turco 4306-B followed with a flush with Turcoat 4504, a proprietary "passivating" material.

The charges were made up of preweighed alternate X-8001 and 1245 clad elements.

The charges were first exposed under standard processing conditions for 26 operating days -- during which time a fuel failure occurred in one charge. Next six charges were flushed for 20 minutes with the Turco solution as shown in Table I. The elements were then exposed for an added 20 operating days at which time a second fuel failure occurred and all charges were discharged. The data on the X-8001 clad elements are shown in Figure 2.

The abscissa is the overall corrosion rate which one would predict for elements as determined from a correlation derived from data from about 50 charges of weighed metal. The ordinate is the overall rate actually observed. By overall rate is meant the gross penetration divided by time.

From Figure 2 it can be seen that the control elements corroded slightly more and the treated pieces significantly more than one would predict from the correlation. The probability that chance was responsible for the higher rates exhibited by any of the five treated charges is less than 0.01.

Based on the data from the control charges, it appears that the treatment increased the overall rate by between 25 to 80%. Actually the difference between the controls and test samples must have occurred during the post-flush period, and it can be inferred that overall rates during this last period were increased between 50 to 160%.

It is further observed that the post-flush treatment with dichromate and turcoat had no beneficial effects.

DECLASSIFIED

FIGURE 2
CORROSION OF X-8001 CIAD ELEMENTS

DECLASSIFIED

From the introductory remarks on fuel jacket corrosion, it may be inferred that treated elements would eventually exhibit instantaneous corrosion rates no different than normal, i.e., rates would eventually decrease to those occurring before the treatment. It is not possible to determine from the test whether the instantaneous rates of the treated elements had returned to normal by the end of the test. In other words, it is possible that all of the extra 1-1/2 mils of corrosion occurred during the first week after the flush. In such a case, the damage would not be serious. However, until the point is established, it should be assumed that an acceleration of rates of X-8001 cladding does continue for a significant amount of time.

Inspection of the data indicates that the 1245 clad elements contacted with the solution corroded at a higher rate than did the control elements. The severe TOA temperatures caused accelerated corrosion in both cases, and prevent quantitative determination of the effects of the flushing solution.

3. Radiological Implications

One of the main reasons for interest in through-reactor decontaminations is the expectation that the benefit received from reduced radiation levels may be longer lasting. Information on rear face only and through-reactor decontamination is presented below.

a. Rear Face Piping Only

Three tests have been conducted to date; all headers at 105-H in November, 1957; all headers at 105-DR in July, 1958; and 5 headers at 105-KW in July, 1958.

The background dose rate in the discharge area was reduced by about 50% at 105-H and by about 60% at 105-DR. The benefit lasted only about 30 days at 105-H because external contamination became severe. However, at 105-DR the dose rate increased to about 50 percent of original in 90 days and it is now estimated that it may be nine months before the background dose rate reaches the previous level. No record was kept of the radiation exposure used at 105-H, but 105-DR reported 1500 mr of personnel exposure was required to accomplish the decontamination. They also reported a savings of about 3300 mr during the tube replacement outage that followed the decontamination.

Waste disposal problems are not severe for rear face decontamination. Both the concentrations and total amounts of radioisotopes removed are small. Concentrations are about the same as or less than those encountered in reactor effluent water and the total amount removed, about 10 curies, is far less than the amount released in normal reactor effluent water over the same period of time. Chemical toxicity in downstream drinking water supplies has been studied and found to be no problem to date. Continuing study will be required because this is controlled by river flow rates and flow patterns. Waste disposal problems are not expected to be limiting.

The decontamination of the 5 headers at 105-KW achieved about 50 percent reduction in dose rates which persisted for only one month. Since these headers represent only a part of the radiation source, dose rate measurements to determine the benefit during later outages may not be too indicative. A waste disposal problem was encountered which is peculiar to the 100-K Reactors. The waste cannot be released to the river because the drains which carry the spent cleaner are piped to the 107 trench. Therefore, at the 100-K reactors, the waste must be neutralized to avoid decontamination of the trench.

b. Through-Reactor Decontamination

Single tube decontamination tests have been conducted. Radiation exposure required to decontaminate a complete reactor should be very slight. The maximum reduction in discharge area dose rate accomplished to date was about 50%. The persistence of the benefit was only about 30 days, but the tubes cleaned represented so small a part of the radiation source that the measurements have not been considered reliable. It is expected that the benefits of this type of decontamination would last somewhat longer than decontamination of the rear face only, but further study will be required to establish this point.

Severe waste disposal problems are expected to result from through-reactor decontamination because large amounts of chemicals would be used and large amounts of contamination would be removed. The large amounts of contamination involved would require cribbing the waste. It is expected that certain radioisotopes would be present in amounts equivalent to 100 days of a normal reactor's output and that the average might equal 10 days of a normal reactor's output. Studies have indicated that this waste can be safely released to a crib after it has been neutralized. The problem of chemical toxicity is not well resolved, but is not expected to be limiting.

FUTURE PROGRAM

In view of the initial unfavorable results obtained from preliminary tests, additional testing is in order to characterize better the undesired effects.

More data on the effects of Turco 4306-B on process tubes will be obtained from measurements on tubes removed from H and other reactors. It is believed that such measurements will, in large part, supply the needed information on tubes.

In addition to work on process tubes, added work on fuel cladding is planned. Hokenson is conducting a laboratory test to gather more data on the effects of a Turco-4306 at 50°C; this will be followed by another test at 30°C. In-reactor tests are also tentatively planned which are designed to determine the time required for corrosion rates to return to normal after a flush.

DECLASSIFIED

UNCLASSIFIED

HW-58153

Page 10

A major increase in knowledge of the corrosion aspects of through-reactor decontamination can be expected by April, 1959. Until then, the present interim conclusions on effects can be expected to remain essentially unchanged.

N. R. Miller
Reactor Engineering
Research & Engineering Operation
IRRADIATION PROCESSING DEPARTMENT

R. B. Hall
Radiological Science
Research & Engineering Operation
IRRADIATION PROCESSING DEPARTMENT

Approved:

R. E. Trumble, Supervisor
Reactor Engineering Operation

NRM-RBH/cn

END

**DATE
FILMED**

9 / 9 / 92