NRTSC
Nuclear Reactor Technology and
Scientific Computations

WSRC-RP-92-1099

Key Words: PRA
Septifoil
Probability
Design Basis

Retention: Lifetime

**UNSEATED SEPTIFOIL NON-DETECTION PROBABILITY
TASK: PRA**

by
S. V. Topp

Authors Signature

Issued: September, 1992

MASTER

Westinghouse Savannah River Company
Savannah River Site
Aiken, SC 29808

PREPARED FOR THE U. S. DEPARTMENT OF ENERGY UNDER CONTRACT NO. DE-AC09-88SR18035

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

Document: WSRC-RP-92-1099
Date: September 18, 1992
Title: UNSEATED SEPTIFOIL NON-DETECTION PROBABILITY
Task: PRA

Approvals:

9/22/92

D. S. Gramer, Technical Reviewer Date

9-27-92

K. R. O'Kula, Responsible Manager Date

10/2/92

M. J. Hitchler, Level 3 Manager Date

WESTINGHOUSE SAVANNAH RIVER TECHNOLOGY CENTER
NUCLEAR REACTOR TECHNOLOGY AND SCIENTIFIC COMPUTATIONS

WSRC-RP-92-1099
September 18, 1992

INTRODUCTION

The frequency that the Savannah River K-Reactor would proceed beyond hydraulic startup with a septifoil not properly seated is estimated in this report. It summarizes previous work on this subject (Reference 1), incorporates concerns about the utility of individual septifoil pressure measurements, and discusses two proposed techniques that could lower the non-detection probability to the point that this issue could be beyond Design Basis consideration.

SUMMARY

Reference 1 gives the frequency as being the product of the following factors:

Probability of non-detection with TV camera of $1.2\text{E-}04$, times
Probability of non-detection by pressure of $1.0\text{E-}01$, times
Frequency of actually having a misseat= $2.0\text{E-}01/\text{rx-yr}$, equals
 $2.4\text{E-}06/\text{rx-yr}$.

References 2 and 3 indicate the present pressure measurements involve so much uncertainty that credit for the factor of ten should be discontinued, leaving the probability at $2.4\text{E-}05$ for the present Q septifoils.

Appendix 1 of this document shows that if a new septifoil featuring a high-seat ring were installed, then an additional probability of non-detection of $4.9\text{E-}05$ would multiply the above factors, yielding $1.2\text{E-}09/\text{rx-yr}$ for the frequency of proceeding beyond hydraulic startup with a septifoil not seated.

Appendix 2 of this document shows that if a new helium sample pipe inspection technique were implemented, then an additional probability of non-detection of $1.4\text{E-}02$ would multiply the above factors, yielding $3.4\text{E-}07/\text{rx-yr}$ for the frequency.

CONCLUSIONS

Either of the two options discussed in the appendices could reduce the frequency to below the level of $1\text{E-}06/\text{rx-yr}$ considered an appropriate threshold for Design Basis events (Reference 4), even if no credit is given for the individual septifoil pressure tests. These tests should, however, be continued for septifoil system checking for other reasons related to acceptable septifoil configuration.

A new septifoil featuring the high-seat ring has the disadvantage that, if a misseated septifoil were not detected by the other checks and hydraulic startup occurred, then a tank-top leak may result. Such a leak is in itself an undesirable event. This consideration leads to the recommendation that the helium sample pipe inspection technique be implemented instead.

REFERENCES

- (1) S. V. Topp, "Probability of Reactor Operation with a Septifoil Not Seated", WSRC-RP-91-949, September, 1991
- (2) D. A. Coutts, "Uncertainty Analysis of the Unseated Septifoil Evaluation Methods", WSRC-TR-92-130, March, 1992
- (3) S. V. Topp, "Review of Septifoil Pressure Measurement Study", SRL-PRA-92-0079, March, 1992
- (4) ANSI/ANS-51.1-1983, Section 3.2.3

APPENDIX 1

UNSEATED SEPTIFOIL NON-DETECTION PROBABILITY TYPE S DESIGN WITH HIGH SEAT RING

INTRODUCTION

A new septifoil has been designed and is under test which is more likely to be properly seated than the present Q septifoil, and, if it is not seated, then detection should be more likely. The PRA group has been asked to estimate the conditional probability of non-detection, if an S septifoil is not seated (memorandum to D. A. Sharp from G. W. Richardson, NES-ETH-920097, March 9, 1992)

This memorandum presents the calculation of non-detection probability. This probability would multiply the other probabilities used to estimate the total frequency of reactor operation with a septifoil not seated (WSRC-RP-91-949, S. V. Topp September, 1991). The resulting frequency will be low enough to remove the unseated septifoil scenario from Design Basis consideration, even without credit for individual pressure testing.

Even if the Type S septifoil is installed, all the other lines of defense against an unseated septifoil should continue to be used. There may be a tendency to discontinue some of the checking, because from an analytic standpoint all the checks would not be needed to satisfy design basis requirements. However, if an unseated septifoil is not found with the other checks, then it may result in a tank-top leak before it is found because of the Type S design. Such a leak is in itself an undesirable event, and its avoidance is worth continuing the other checks.

ANALYSIS

The attached fault tree is the model for detecting a Type S septifoil that is not seated, which means it will be about an inch high on the tank top and it will leak at the top during

hydraulic startup. The human error probabilities are scoping values suggested by Alan D. Swain in an abbreviated THERP technique (NUREG/CR-4772, page 3-4 February, 1987). If the new septifoil is implemented and a new procedure written for checking, then a more detailed THERP analysis can be made. The more detailed analysis would be expected to yield a lower non-detection probability, since the scoping values are stated by Swain to be conservative.

Each top event in the tree is discussed below:

SEPTIFOIL SEATED HIGH--This probability is taken to be 1.0, since the result of this analysis is to be used as a conditional probability.

TANKTOP CHECK PROCEDURE FOLLOWED--This is the probability that the operating crew will skip the tanktop check as it relates to septifoils (.03).

SUPERVISOR CORRECTS FAILURE TO FOLLOW--This is the probability that supervision will fail to notice and correct the fact that the tanktop check is skipped. The high failure probability arises from the assumption that there is a moderately high degree of dependence between the operators and their supervision (.1).

OPERATOR SPOTS THE HIGH SEPTIFOIL--This is the probability that the inspection crew will not spot the high septifoil, given that they are following the procedure (.03).

HIGH SEPTIFOIL NOTICED AT LATCHUP--This is the probability that a (different) crew will not spot the high septifoil when the forest is lowered and assemblies are latched, or fail to latch (C&D crew) (.03).

VISUALLY OBSERVE THE TANKTOP LEAK--This is the probability that people fail to see the leak from a high septifoil by looking at the tank top through the observation windows. This is taken to be a high value, since there is very little experience with success versus demands for visually finding such leaks (.5).

BEETLE ALARM CATCHES LEAK--This is a combination of instrumentation failure and human error in interpreting and acting upon the beetle leak detectors, and is conservatively estimated (.1).

The final non-detection probability is the sum of the sequence probabilities for the "ND" damage class, and equals $4.9E-05$.

before hydraulic startup							after hydraulic startup		SEQ.PROB.	CLASS
septifoil seated high	tanktop check procedure followed	supervisor corrects failure to follow t	operator spots the high septifoil	high septifoil notice at latchup	visually observe tanktop leak	beetle alarm catches leak				
TANKTOP	FOLW PROC	SUPV CTCH	SEE HI	LATC CT	VIS OBS	BEETLE				
1.00E+00	3.00E-02	1.00E-01	3.00E-02	3.00E-02	5.00E-01	1.00E-01	9.41E-01	D		
							2.82E-02	D		
							4.37E-04	D		
							3.93E-04	D		
							4.37E-05	ND		
							2.62E-02	D		
	3.00E-02	1.00E-01	3.00E-02	3.00E-02	5.00E-01	1.00E-01	7.86E-04	D		
							1.21E-05	D		
							1.09E-05	D		
							1.21E-06	ND		
							2.91E-03	D		
							4.50E-05	D		
	3.00E-02	1.00E-01	3.00E-02	3.00E-02	5.00E-01	1.00E-01	4.05E-05	D		
							4.50E-06	ND		

tanktop non-detection prob if

tanktop non-detection prob if misseat ring used

A:SEATCK1.TRE 4-15-92

APPENDIX 2

UNSEATED SEPTIFOIL NON-DETECTION PROBABILITY FOR HELIUM SAMPLE PIPE INSPECTION TECHNIQUE

INTRODUCTION

The PRA group has been asked to estimate the conditional probability of non-detection if an S septifoil is not seated (memorandum to D. A. Sharp from G. W. Richardson, NES-ETH-920097, March 9, 1992). The new S septifoil has been designed so that it is more likely to be properly seated than the present Q septifoil.

One of the proposed tests for correct seating is a new helium sample pipe inspection technique. This method involves attaching a balloon to a sample pipe whose lower end is inserted below the holes near the top of the septifoil. Helium is then injected at the pressure tap of the septifoil, and if the septifoil is properly seated the empty balloon will fill.

This memorandum presents the calculation of non-detection probability. This probability would multiply the other probabilities used to estimate the total frequency of reactor operation with a septifoil not seated (WSRC-RP-91-949, S. V. Topp September, 1991). The resulting frequency will be low enough to remove the unseated septifoil scenario from design basis consideration, even if no credit is given for individual pressure testing.

The helium sample pipe inspection technique has a major advantage over the backup given by the high seat ring analyzed previously (SRL-PRA-92-0108, S. V. Topp, April 1992). One reason the high seat ring is an effective check is that, if other tank-top inspections fail, the result will be a tank-top leak of process water upon hydraulic startup, which will be noticed. However, such a leak is in itself an undesirable incident. The high seat ring could be eliminated if the helium balloon technique is used, and the resulting non-detection probability would still place this scenario beyond design basis.

ANALYSIS

The attached event tree is the model for detecting a Type S septifoil that is not seated with the helium sample pipe inspection technique. The human error probabilities are scoping values suggested by Alan D. Swain in an abbreviated THERP technique (NUREG/CR-4772, February, 1987). If the new septifoil is implemented and a new procedure written for checking, then a more detailed analysis would be expected to yield a lower non-detection probability, since the scoping values are stated by Swain to be conservative.

Each top event in the tree is discussed below:

UNSEATED SEPTIFOIL--This probability is taken to be 1.0, since the result of this analysis is to be used as a conditional probability.

HELIUM CHECK PROCEDURE FOLLOWED--This is the probability that the operating crew will skip the helium sample pipe inspection technique after changes that could unseat a septifoil (.03).

SUPERVISOR CORRECTS FAILURE TO FOLLOW--This is the probability that supervision will fail to notice and correct the fact that the helium technique is skipped. The high failure probability arises from the assumption that there is a moderately high degree of dependence between the operators and their supervision (.1).

SAMPLE PIPE NOT BELOW HOLES--If the sample pipe is not inserted far enough to be below the holes in the top of the septifoil, it is conservatively assumed that, if the septifoil is unseated, the helium gas will travel up the outside, then some will enter the holes and rise to enter the end of the pipe and fill the balloon (.001). This highlights the fact that it will be important to have a physical design that forces the end of the pipe to be low enough.

BALLOON NOT DEFLATED--If all gas is not forced from the balloon before testing a particular septifoil, the system will appear to have passed the helium test (.01). This highlights the importance of having a procedure that double-checks that the balloon is deflated each test, or even having more than one inflation attempt for each septifoil, with the balloon deflated between tests.

The final non-detection probability is the sum of the sequence probabilities for the "ND" damage class, and equals $1.4E-02$.

before hydraulic startup					SEQ.PROB.	CLASS
unseated septifoil	helium check procedure followed	supervisor corrects failure to follow	sample pipe below holes	balloon deflated		
TANKTOP	FOLW PROC	SUPV CTCH	HI PIPE	BALLOON		
1.00E+00					9.59E-01	D
				1.00E-02	9.69E-03	ND
			1.00E-03		9.70E-04	ND
					2.67E-02	D
				1.00E-02	2.70E-04	ND
	3.00E-02		1.00E-03		2.70E-05	ND
		1.00E-01			3.00E-03	ND

seat check with helium sample pipe

A:SAMPLHE.TRE 8-24-92

END

DATE
FILMED

7/12/93