Association for Information and Image Management
 1100 Wayne Avenue, Suite 1100
 Silver Spring, Maryland 20910
 301/587-8202

Centimeter

Inches

MANUFACTURED TO AIM STANDARDS
 BY APPLIED IMAGE, INC.

1 of 2

RECEIVED

JUN 21 1993

RLH-27-91
From R. L. Hastings
Phone 6-3846/MS 5230
Date November 21, 1991
Subject Summary of Meeting on Disposal of LET&D HEPA Filters

To R. R. Bone B. H. O'Brien R. E. Schindler
K. N. Brewer C. W. Olsen K. L. Shifty
E. P. Mondok B. T. Richards M. C. Swenson

cc: J. G. Burton S. M. Halupa W. B. Palmer
R. H. Davis J. P. Law B. R. Wheeler
L. F. Ermold V. C. Maio A. M. Umek

A meeting was held on 11-20-91 in the CPP-663 Conference Room to discuss the issues involved in the disposal of LET&D HEPA filters. The issues considered were:

1. Methods to sample the filters to characterize the filters.
2. The disposal location once the filters have been characterized.

A decision was made to take a 100 gm. sample of the filter media only using EPA protocol. The hazardous constituents will be in greatest concentrations on the filter media. The housing may have an unknown but smaller amount of the same materials. Therefore, if the media is hazardous, the housing will also be treated as hazardous. If the media is not hazardous, the housing can not be hazardous.

At present, the EPA does not have RCRA rules governing listed wastes in off-gases but is discussing the possibility of issuing rules for this situation. When EPA promulgates these rules, LET&D HEPA filter disposal will be reexamined.

Another situation considered was if the filters are found to be radioactive at levels beneath the limit declaring the filters radioactive. If the filters are at or slightly above radioactive limits, the possibility exists that frequent change-outs or a water flush of the filters could

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

Westinghouse Idaho Nuclear Company, Inc.

Box 4000 — Idaho Falls, Idaho 83403

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

Idaho National Engineering Laboratory

KNB-08-91

From : K. N. Brewer
Phone : 6-3018/MS 5218
Date : September 9, 1991
Subject: Mercury Amalgamation

To : T. H. Waite

cc: S. S. Bodner
C. M. Frazee
P. T. Grahovac
M. R. Greene
M. B. Heiser
G. F. Kessinger
V. C. Maio *VCM*
E. P. Mondok
B. H. O'Brien *BHO*
K. L. Shifty
D. D. Siemer
K. N. Brewer-2

A recent Value Engineering Seminar was held to develop a process(s) that would allow for the disposal of used HEPA filters generated at the ICPP. During this seminar, much time was spent discussing possible treatments for mercury because mercury concentrations on the filters are currently preventing their treatment and disposal. The mercury concentration was not brought below the EPA's TCLP limit of 0.2 mg/L on a consistent basis during initial testing of the current filter leach treatment process. One of the mercury treatment methods discussed during the VE Seminar was amalgamation.

As requested, a technical justification for not doing amalgamation as a mercury treatment during the processing of used HEPA filters has been prepared and is attached. Amalgamation is the preferred treatment for mercury by the EPA; however, this treatment has been found chemically incompatible with the waste streams at the ICPP.

If you have any questions regarding this information, please contact me at 6-3018.

K. N. Brewer, Sr. Scientist
HLW Process Development

Attachment

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
WASHINGTON, D.C. 20460

M. Kelly

OFFICE OF
SOLID WASTE AND EMERGENCY RESPONSE

OCT 26 1990

J. C. Kent, Staff Engineer
RCRA Compliance and Regulations
Westinghouse Idaho Nuclear
Company, Inc.
Box 4000
Idaho Falls, Idaho 83403

Re: Freedom of Information Act Request
HQ-RIN-6824-90

Dear Mr. Kent:

This is in response to your October 3, 1990, Freedom of Information Act Request concerning EPA correspondence. As requested, I have enclosed a copy of the November 2, 1988, EPA letter from Robert W. Dellinger to Donald E. Stone.

Thank you for your interest in solid and hazardous waste.

Sincerely yours,

Barbara Roth

Barbara Roth, Acting Chief
Information Services Section
Communication Services Branch
Communication, Analysis and Budget
Division
Office of Solid Waste

cc: FOI Office (2)

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
WASHINGTON, D.C. 20460

1/16/89

NOV 2 1988

OFFICE OF
SOLID WASTE AND EMERGENCY RESPONSE

Mr. Donald E. Stone
Manager, Environmental Compliance
GSX Chemical Services, Inc.
P. O. Box 210799
Columbia, SC 29221

Dear Mr. Stone:

This letter is in response to our telephone conversation of October 19, 1988 and your follow-up letter dated October 20, 1988, both dealing with waste listings for commercial chemical products.

When defining a material as a hazardous waste under RCRA Subtitle C, the material must first be defined as a solid waste in accordance with 40 CFR Section 261.3(a). A discarded material that is recycled by being reclaimed may be defined as a solid waste, depending on the type of secondary material (see Table 1, Section 261.2(c)(3)). Since you did not specify in the examples in your letter the disposition of the mercury and mercury-containing material, I am assuming that it is going for reclamation.

In your first example, the mercury is contaminated before being placed in the product (thermometer). If the contaminated mercury is shipped off-site for disposal, it would be a solid and hazardous waste identified as an off-specification commercial chemical product (listed waste U151) in 40 CFR Section 261.33. If, however, the mercury was sent for reclamation, it would not be defined as a solid waste (see 40 CFR Section 261.2(c)(3)(Table 1)). Therefore, the mercury would not be identified as listed waste U151 and a manifest would not be required in this case because Subtitle C of RCRA is not applicable to materials that are not defined as a solid waste (see 40 CFR Section 261.2).

In your second example, the broken thermometer has been used and meets the definition of a spent material in 40 CFR Section 261.1(c)(1). Spent material sent for reclamation is defined as a solid waste in 40 CFR Section 261.2(c)(3)(Table 1). The broken thermometer (mercury and glassware) could then

be further defined as a hazardous waste if it exhibits a characteristic of a hazardous waste (i.e., EP toxic, in which case it is hazardous waste D009). This determination is made either through the generator's knowledge of the characteristics of the waste or by subjecting the waste to the EP toxicity leaching procedure (refer to 40 CFR Section 262.11(c)).

Finally, in your third example, if the mercury-containing batteries and switches can be defined as spent materials as specified in 40 CFR Section 261.1(c)(1), the waste identification process used in example two above would apply.

As is always the case, a RCRA authorized State might have more stringent requirements so you should contact the appropriate state agency to determine what their regulations require.

If you have any additional questions, please contact Steve Cochran at (202) 475-8551.

Sincerely,

A handwritten signature in black ink, appearing to read 'R. Dellinger', with a long horizontal flourish extending to the left.

Robert W. Dellinger
Chief, Waste
Characterization Branch

W/ 11-1
GSX Chemical Services, Inc.
P O Box 210799
121 Executive Center Drive
Congaree Building, Suite 100
Columbia, SC 29221
(803) 798-2993

October 20, 1988

Mr. Robert Dellinger
US Environmental Protection Agency
401 M Street, SW
Washington, DC 20460
05-332

Dear Mr. Dellinger:

This is to confirm our October 19, 1988 telephone conversation concerning the waste listing of used commercial chemical products. Specifically, "U" listed wastes are those wastes generated by the manufacturer of that chemical or a manufacturer of a product which contains that chemical. As an example, a thermometer manufacturer who contaminates this mercury prior to putting it in his product would manifest that contaminated mercury as U151.

On the other hand, a person who uses a thermometer, breaks it, and collects the mercury and glassware would manifest his waste as D009 since it is spent EP toxic material. This same determination could be made from similar products such as mercury-containing batteries and switches.

If the Agency should disagree with the above determination please let me know as soon as possible at (803) 798-2993.

Sincerely yours,

Donald E. Stone
Manager, Environmental Compliance

DES/jh

cc: E. Lin Longshore	.. Bill Hallam
Bob Caldwell	Dave Sprinkle
Roger Davis	Jackie Noles
Mona Bartoletti	Dan Allen

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

WCB ncf

APR 12 1989

APR 14 1989

Mr. Robert W. Oleszko
Vice President, HazMat Environmental Group, Inc.
P. O. Box 676
Buffalo, New York 14217

Dear Mr. Oleszko:

This letter is in response to your letter of January 6, 1989, in which you request an official interpretation of the regulatory status of ignitron tubes containing mercury, when sent for reclamation.

I understand that your inquiry is a follow-up to a previous official interpretation made by the Environmental Protection Agency (EPA) to Mr. Philip E. Gerwert, Manager, Industrial Waste and Toxic Substances, General Motors Corporation, concerning Resource Recovery and Conservation Act (RCRA) regulations as they relate to various aspects of recycling mercury (copy attached). Our interpretation regarding the regulatory status of ignitron tubes has not changed.

As was indicated in the letter to Mr. Gerwert, when a material (e.g., an ignitron tube) is being sent for reclamation, it is necessary to determine what type of secondary material it is in order to define the material as a solid waste under Subtitle C of RCRA. In the above referenced letter, the Agency determined that ignitron tubes sent off site for mercury reclamation are classified as spent material and therefore meet the definition of a solid waste as defined in 40 CFR Section 261.2(c)(3), Table 1. If the mercury is removed from the ignitron tubes on site (e.g., material reclaimed from solid waste) and only the mercury from the tubes is sent off site for direct beneficial use or further refining, the mercury is a product, not a solid waste (see 40 CFR Section 261.3(c)(2) and 50 FR 634, January 4, 1985).

As I understand your letter, you disagree with this interpretation. It is your position that the ignitron tubes do not meet the definition of a spent material under 40 CFR Section 261.1(c)(1). You believe the ignitron tubes should be defined as a commercial chemical product and therefore, would not be a solid waste when sent off site for reclamation under 40 CFR Section 261.2(c)(3), Table 1. Your rationale is that

neither the tube, or any component of the tube, has been contaminated. Therefore, the ignitron tube cannot be defined as a spent material.

In deciding the status of material being sent for reclamation, you have to look at what is actually physically being sent off site. In this case, it is the entire ignitron tube that is being sent off site. The purity of the mercury within the tube is not a consideration when determining whether the ignitron tube itself meets the definition of a spent material.

You further argue that even though the ignitron tube is burned out and can no longer serve its intended use, the tube's failure is not due to contamination of the mercury or any other part of the tube. Again, the condition of the mercury or the mercury itself has nothing to do with determining whether the ignitron tube is a solid waste by being a spent material. If the ignitron tube is considered a solid waste under 40 CFR Section 261.2(c), the unit would likely be a hazardous waste because the mercury component may exhibit the hazardous waste characteristic of EP toxicity.

In summary, the ignitron tube is the material that becomes spent and thus, would be considered a spent material. The presence of mercury in the ignitron tube is not a consideration when defining the tube as a solid waste. There is nothing in the RCRA regulations that would support defining an ignitron tube as a commercial chemical product. The non-functional ignitron tubes from the welding equipment meet the definition of spent material and are solid waste under Subtitle C of RCRA when sent for reclamation (mercury recovery). The tubes could be further defined as a hazardous waste if they exhibit a characteristic of hazardous waste (e.g., EP toxicity--D009).

If you have any additional questions, please feel free to call me at (202) 475-9715.

Sincerely

Stephen L. Cochran
Environmental Protection Specialist
Waste Characterization Branch

Attachment

File

September 4, 1991

Distribution

SUCCESS OF "PRINTSOLVE" AS A DEGLAZING SOLVENT SUBSTITUTE - SMS-60-91

Printsolve, an ink remover/deglazing solvent substitute, manufactured by GAF Chemical, has replaced 1,1,1-Trichloroethane in deglazing press rollers and pads at the Argonne National Lab-West Print Shop. It is used at full strength and according to the manufacturer, may be recycled. The product is considered to be non-hazardous by the manufacturer and by various Industrial Hygienists at the Idaho National Engineering Laboratory. It has a flash point of 191° F and a pH of 9.2. The product can be adjusted to a neutral pH by adding acetic acid (vinegar) before disposal.

For more specifics on how this product is being utilized at ANL-W, please contact Rod Harris at 208-533-7130.

If you would like an MSDS or technical information, you can request it from me at 208-526-4491 or Ed Lamm of GAF Chemical at 201-628-3345.

Stella M. Steele
Pollution Prevention Unit

jms

Idaho National Engineering Laboratory

August 21, 1991

Distribution

ALTERNATIVE SOLVENT LIST - SMS-52-91

Enclosed is the first draft of the EG&G Idaho Pollution Prevention Unit's solvent substitution list. This list will enable you, as a hazardous-solvent user, to examine possible solvent alternatives to fit your application needs. This list will be updated periodically as we are informed of new products or more information for the products now listed becomes available. We currently have MSDSs and technical information available for the products on this list.

We would be happy to assist you in obtaining any additional information you may require. Please feel free to contact me at (208) 525-5643.

Sincerely,

S. M. Steele
Associate Scientist
EG&G Idaho, Inc.

SS

Enclosure:
As Stated

DRAFT

ATTENTION--ATTENTION--ATTENTION--ATTENTION--ATTENTION--ATTENTION--ATTENTION

Please be advised that this document contains a legal disclaimer that must be read before any further investigation. Due to data link-up difficulties, separate documents must be used in order to provide you with all of the needed information. Some information is still lacking in this report which leaves blank areas. It is a working draft that is updated periodically. This draft is not in the final form. Directions on the use of this draft are provided below.

1. The documents have been separated into the following subjects: Main company and solvent information (including company contact information, available solvents, flashpoint, references, and who performed tests on the product), metals passed in corrosion tests, application, soils cleaned, and hazardous chemicals.
2. Take notice of all fields. These are your way of keeping track of the product of your choice.
3. Company numbers have been assigned to each company for ease of tracking.
4. Start at the field of your choice (applications, soils cleaned, metals passed, etc.) and then narrow your subjects from there.
5. If there are any questions on how to use this document, or if you would like to have further local information on a product, please contact Stella Steele at (208) 525-5643 or Nolan Stucki at (208) 526-8096.

DRAFT

DISCLAIMER

The following document is an informal, predecisional draft created for the internal use of participating contractors of the Idaho National Engineering Laboratory and beyond. It is intended for use as an informative document only. This document was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor EG&G Idaho Incorporated, nor any of their employees, makes any warranty, expressed or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed. Reference herein to any specified commercial products, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or EG&G Idaho Incorporated. The information herein shall not be used for advertising or product endorsement purposes. All further inquiries or requests for information should be obtained from the manufacturer of the product, and cleared through an Industrial Hygienist and/or Safety before use.

DRAFT

IV. WESTINGHOUSE IDAHO NUCLEAR COMPANY (WINCO)

1. EPA Letter - 90 Day Accumulation Area Start Date
2. EPA Memorandum - "Compliance With Satellite Accumulation Requirements"
3. Checklist - Satellite Accumulation Area Inspection Form
4. Letter - "Usage of "Sure Shot" Containers in Place of Aerosol Cans"
5. Letter - "Notice of Upcoming Recyclable Battery Shipments"
6. Fact Sheet - "Disposition of Batteries"
7. Letter - HEPA Filter Leach Sampling and Permit Impacts"
8. Draft - "Functional and Operational Requirements for the Spent Filter Handling System"
9. Letter - "Summary of Meeting on Disposal of LET&D HEPA Filters"

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
WASHINGTON, D.C. 20460

RECEIVED

AUG 09 1989

ENVIRONMENTAL
SUPPORT BRANCH

APR 21 1989

OFFICE OF
SOLID WASTE AND EMERGENCY RESPONSE

Mr. Stephen J. Axtall
Smith & Schnacke
2000 Courthouse Plaza NE
Post Office Box 1817
Dayton, Ohio 45401-1817

Dear Mr. Axtall:

This letter is in response to your letter of February 23, 1989, requesting clarification of the generator accumulation time requirements of 40 CFR 262.34. You ask when the accumulation time begins for an unknown waste that, upon analysis, is found to meet the definition of hazardous waste. Initially, the container was improperly labelled or not labelled at all. A sample of the contents was sent off site for analysis, and was found to be hazardous.

In your letter you relate that Chris Bryant of the RCRA Hotline indicated that the accumulation time for an unknown waste begins when the analytical results indicating that the waste is hazardous are received. Unfortunately, this information was incorrect. The correct reading of Section 262.34 in this instance follows.

Section 262.34(a) provides a limited exemption from the requirement that those who store hazardous waste must obtain permits. To obtain the exemption, a generator must comply with all the requirements of Section 262.34. If the date on which the accumulation began was not marked on the drum (Section 262.34(a)(2)) or the drum was not marked "Hazardous Waste" (Section 262.34(a)(3)), then the generator has not met the pre-conditions for the exemption from permitting requirements and is an operator of a storage facility subject to the requirements of 40 CFR Parts 264 and 265 and the permit requirements of 40 CFR Part 270.

Where a generator does meet the conditions of Section 262.34, the accumulation time begins when a waste is generated or when it is first taken from a "satellite" accumulation area operated pursuant to 40 CFR 262.34(c). Waste is generated either when it is produced or when it is first caused to be subject to regulation (40 CFR 260.10), not when a generator first analyzes the waste. If the waste in the drum was a listed or characteristic hazardous waste when it was produced, then the one-time 90-day accumulation time could begin only at the time the waste was produced or removed from the satellite accumulation area.

- 2 -

If the waste was not subject to regulation when it was first stored, s.g., the material had not yet been listed as a regulated hazardous waste, then the 90-day period would have begun when the waste became subject to regulation--upon the effective date of the new listing. A generator's failure to properly analyze, label, and accumulate waste does not exempt the waste from regulation.

If we can be of any further assistance, please contact Emily Roth at (202) 382-4777.

Sincerely,

Sylvia K. Lawrence, Director
Office of Solid Waste

MEMORANDUM

MAR 26 1990

SUBJECT: Compliance With Satellite Accumulation Requirements
FROM: Dave Tetta, Chief RCRA Compliance, EPA Region 10 *261*
TO: Addressees

EPA Region 10 seeks to develop consistency within the Region on the interpretation of satellite accumulation requirements (262.34(c)). This memo is intended to assist both EPA and State inspectors in interpreting satellite accumulation regulations.

Many situations will arise during generator inspections concerning satellite accumulation. This memo does not intend to clarify all situations, but is hoped some key points brought out can assist in making the inspections of generator facilities in the Region consistent. It is the responsibility of each inspector to determine whether the satellite accumulation exemption applies in a specific situation.

Situations considered not to be satellite accumulation:

- A. Waste accumulation container is located outside of the room where the waste is generated.
- B. To access container one or more doorway(s) must be passed through.
- C. Accumulation container is serving as a central point for waste coming from more than one process or waste stream.

Other helpful points on satellite accumulation:

- A. The satellite container does not have to be 55 gallons in size. The container may be any size (from 1 quart up to 55 gallons) as long as it is compatible with the waste type stored in it.
- B. There may be one satellite container per waste stream. Accumulation is allowed of up to 55 gallons per process.
- C. Satellite container(s) needs to be within sight/control of the process or operator, or locked. The container does need to be securely closed. The container must also be labeled or marked as containing waste, (this does not mean it needs a hazardous waste label).

For more background information refer to the preambles of the January 3, 1983, and December 20, 1984 Federal Registers.

REMEMBER THE EXEMPTIONS FROM BEING CLASSIFIED AS A LESS THAN 90 DAY AREA ARE LIMITED.

SAA

CONTAINERS

1. Number of containers in SAA. _____

2. Does the total capacity of the containers exceed 55 gallons? CFR 262.34 (c) (1) YES _____ NO _____
If yes, explain.

3. Are all containers labeled "Hazardous Waste" or "Acutely Hazardous Waste"? YES _____ NO _____
If no, explain. CFR 262.34 (a) (3); (c) (i) (ii)

4. If "Acutely Hazardous Waste" present, does container capacity for this type of waste exceed 1 quart? YES _____ NO _____
If yes, explain. CFR 261.33 (e), 262.34 (c) (1)

5. Is there nonhazardous waste in the SAA? YES _____ NO _____
If yes, explain.

6. Is Satellite Accumulation Area near point of hazardous waste generation? YES _____ NO _____
If no, explain. CFR 262.34 (c) (1)

7. Is the Satellite Accumulation Area near a drain? YES _____ NO _____
If yes, how close?

Where does the drain go?

8. Additional information.
Is there a sign identifying the area as a Satellite Accumulation Area with appropriate instructions? YES _____ NO _____
If no, explain.

9. Are "No Smoking" signs posted in SAA? YES _____ NO _____
If no, explain. CFR 264.17 (a); 265.17 (a)
10. Is there a log book present in the Satellite Accumulation Area or in office which is accessible to all employees using the SAA? YES _____ NO _____
If no, explain.
11. Do the quantities recorded in the log book correspond to quantities in the Satellite Accumulation Area? YES _____ NO _____
If no, explain.
12. Are weekly inspection for leaking containers performed? Is the date, time and signature of person who performed inspection recorded in the log book? YES _____ NO _____
If no, explain. CFR 265.174; 264.174
13. Are incompatible waste segregated and labeled as to type? A list of waste which are compatible can be found in SOP 04.1.35. YES _____ NO _____
If no, explain. CFR 264.177 (b) (c); 265.177 (b)
14. Are the waste containers compatible with waste stored in them, i.e., waste will not corrode or generate heat. YES _____ NO _____
If no, explain. CFR 265.172; 264.172
15. Is a source of ignition near the SAA? YES _____ NO _____
If yes, explain. CFR 264.17 (a); 265.17 (a)
16. Are containers holding ignitable or reactive waste 15 m (50 ft) from facility property line? YES _____ NO _____
If no, explain. CFR 265.176; 264.176
17. Is the container holding hazardous waste opened, handled or stored in a manner which will prevent rupture or leaking of container? YES _____ NO _____
If no, explain. CFR 265.173 (b); 264.173 (b)

18. Is the container closed? YES _____ NO _____
If no, explain. CFR 265.173
264.173
19. Are containers in good condition? YES _____ NO _____
If no, explain. CFR 265.171; 264.171
20. Are the containers leaking? YES _____ NO _____
If yes, explain. CFR 265.171; 264.171
21. Is there a containment structure under the waste containers? YES _____ NO _____
If no, explain. CFR 264.175 (a) (b) (c) (d)
22. Is containment free of cracks or gaps? YES _____ NO _____
If no, explain. CFR 264.175 (b) (1)
23. Does the containment structure leak? YES _____ NO _____
If yes, explain.
24. Is there liquid in the containment structure? YES _____ NO _____
If yes, explain. CFR 264.175 (b) (5)
25. Can the containment hold 10% of the volume of all containers or the volume of the largest container (liquids only)? YES _____ NO _____
If no, explain. CFR 264.175 (b) (3)
26. Can the containment system be drained i.e., sloped, operated to drain? YES _____ NO _____
If no, explain. CFR 264.175 (b) (2)
27. Are the containers in the containment above any accumulated liquids? YES _____ NO _____
If no, explain. CFR 264.175 (b) (2)
28. Can the current containment system prevent run off from entering containment

- area? YES _____ NO _____
If no, explain. CFR 264.175 (b) (4)
29. Is an overburden barrel located nearby? YES _____ NO _____
If no, explain. CFR 264.171; 265.171
30. Is the overburden barrel in the SAA? YES _____ NO _____
If yes, explain.
31. Is the SPCC nearby and accessible to all employees? YES _____ NO _____
If no, explain. CFR 264.51, 264.52
265.51, 265.52
32. Is spill response material available? YES _____ NO _____
If no, explain. CFR 264.32 (c); 265.32 (c)
33. Is fire fighting equipment near the SAA? YES _____ NO _____
If no, explain. CFR 264.32 (c); 265.32 (c)
34. Is there clear passage to the emergency equipment? YES _____ NO _____
If no, explain. CFR 264.34, .35; 265.34, .35
35. Is there a communication device nearby i.e., walkie talkie, phone? YES _____ NO _____
If no, explain. CFR 264.32 (a) (b); 265.32 (a) (b)
36. Are there an emergency phone numbers posted? YES _____ NO _____
If no, explain. CFR 264.32 (b); 265.32 (b)
37. Does the communication device work? YES _____ NO _____
If no, explain. CFR 264.33; 265.33
38. Is there clear passage to the communication device? YES _____ NO _____
If no, explain. CFR 264.34

Idaho National Engineering Laboratory

AMD-02-92

From : A.M. Dismuke
Phone : 6-5942/MS-5117
Date : January 14, 1992
Subject: Response to "Disposition of Contaminated Dirt-High Level
Waste Tank Farm Replacement (HLWTFR) Project"

To : C.M. Cole, MS-2304
Ref: (1) C.M. Cole, CMC-09-91, "Disposition of Contaminated
Dirt -High Level Waste TANK Farm Replacement (HLWTFR)
Project"

In response to the above referenced memo, I contacted the Environmental Restoration and RCRA Compliance groups to determine if there were any RCRA or CERCLA concerns with your anticipated plans for backfilling. At this time, there are no additional requirements nor Environmental Compliance concerns therefor your plans are acceptable.

If you have additional concerns you may contact me at the above number.

A handwritten signature in cursive script, appearing to read "Angela M. Dismuke".

Angela M Dismuke, Senior Engineer
Environmental Assurance

Westinghouse Idaho Nuclear Company, Inc.

Box 4000 — Idaho Falls, Idaho 83403

Idaho National Engineering Laboratory

CMC-09-91

From : C. M. Cole
Phone : 5-5463/MS-2304
Date : December 10, 1991
Subject : Disposition of Contaminated Dirt - High Level Waste Tank Farm
Replacement (HLWTFR) Project

To : G. C. McCoy, MS-5209
A. M. Dismuke, MS-5711

cc: M. J. Beer, MS-2304 H. A. Jaafar, MS-2304
G. E. Bingham, MS-5306 H. L. Lord, MS-2034
A. R. Eberle, MS-2304 P. B. Summers, MS-2304
A. C. Hohbach, MS-2304 Project File - HLWTFR
J. C. Hughes, MS-2304 C. M. Cole - 2

Ref: (1) J. D. Edelmayer, JDE-035-90, to S. M. Halupa,
"Disposition of Radioactively Contaminated Soil," dated
July 12, 1990
(2) E. R. Spruill, ERS-114-90, to OHP Supervisors,
"Disposal of Contaminated Dirt," dated July 23, 1990

HLWTFR Project intends to backfill excavations within the existing tank farm with contaminated dirt meeting the requirements in Reference 2 above. Dirt will be characterized prior to excavation and used for backfill only in excavation from which it was removed. Please provide requirements for handling material during excavation, stockpiling, and backfill operations including monitoring, protection or confinement, and restrictions due to weather.

If you have any questions, please contact C. M. Cole at 525-5463 or H. L. Lord at 525-5467.

C. M. Cole

C. Mike Cole, Project Engineer
HLWTFR Project

/gh

Attachments

Westinghouse Idaho Nuclear Company, Inc.

Reference 2
Attachment to CMC-C9-91

ERS-114-90
From : E. R. Spruill
Phone : 6-3140/MS 5205
Date : July 23, 1990
Subject: Disposition of Contaminated Dirt

To : OHP Supervisors

The effective area must have been characterized prior to digging, to determine if it is to be classified as mixed or not.

If dirt is not mixed and is greater than 3 mrem/hr. beta-gamma at contact or has any detectable alpha, contact the managers of OHP and Shipping and Material Management for disposition. Dirt below these levels can be placed in the hole as fill with a minimum of 5 inches of clean fill on top. As a general rule, do not put dirt back if contaminated dirt removed is of a higher level than what is left in the hole, contact managers for directions.

If dirt is classified as mixed, store dirt at the site with the above approvals for dirt to be replaced in the hole with a minimum of 6" clean fill on top.

In both cases, any excess contaminated dirt will be placed in the appropriate container for disposal.

E. R. Spruiell, Manager
Operational Health Physics

GWC/33

63545

Westinghouse Idaho Nuclear Company, Inc.

Idaho National Engineering Laboratory

JDE-035-90

Reference 1
Attachment to CMC-09-91

From : J. D. Edelmayer
Phone : 6-3516/CPP-666/MS-5114
Date : July 12, 1990
Subject: Disposition of Radioactively Contaminated Soil

To : S. M. Halupa, Vice President and Manager
Engineering and Plant Projects Department

L. F. Ermold
F. E. Hicks, MK/F
A. J. Matule
P. I. Nelson

G. K. Oswald
W. L. Random
K. E. Ryan
E. R. Spruill

I recently had a discussion with Mr. Jerry Lyle of DOE-ID concerning the large volume of soil being disposed of at the Radioactive Waste Management Complex (RWMC). The concern is that during excavation projects at WINCO, the soil is normally placed into hot waste boxes and shipped to the RWMC. Then, to replace the void, clean soil is added to the contaminated soil that is still in the hole. This practice is adding to the total volume of contaminated soil at the INEL.

Mr. Lyle is in agreement that the contaminated soil should be placed back into the excavation area upon completion of the project. When contaminated soil is found, it must be well documented by the HP Technician and the Projects representative assigned to the project. The documentation should indicate the contamination levels found and the total area affected (if known).

Contaminated soil should only be placed in waste boxes if only a small amount (i.e. 1 or 2 boxes) is found.

If you have any questions, please call me at extension 6-3516.

J. D. Edelmayer, Manager
Shipping and Material Management

TELECOMMUNICATION

001337

Person(s) called: S. Green, M. M. Gutman (Westinghouse Corp.)

Person(s) calling: S. C. Cooper, T. F. Pointer, T. L. Winder
(WINCO)

Date of call: May 29, 1985 Time of Call: 10:00 a.m.

Subject: PCB Contaminated Soil at the ICPP

cc: C. J. Flynn
K. R. Krivanek
J. J. Volpe
R. K. Wrigley

It was agreed that the following course of action be taken with respect to the PCB contaminated soil in the transformer substation area (UREP II) at the ICPP.

1. Remove the top 1-2 ft. of soil in areas to be excavated for the new transformer pad and appurtenances, since this soil contains PCB contamination and some low-level radioactive material (up to 200 cpm), it will be stored temporarily in wooden radioactive waste containers lined with 8-mil plastic to prevent leakage. These boxes will be stored on site until disposal or treatment site has been located. At this time, it will be removed and sent to this facility for final disposition.
2. Use the remainder of the soil as backfill within the confines of the ICPP fenced area. Only soil that is nonradioactive (i.e., shows no detectable radioactivity levels above background) and virtually free of PCBs (i.e., contains less than 1.5 ppm PCB) will be used as backfill.
3. Monitor the excavation process, particularly in the area of the spill, and take samples at approximately 6 in. and 1 ft. Any soil excavated that appears oily will be sampled. All the soil from the spill area and from any other areas exhibiting oiliness will be temporarily stockpiled separately while chemical analyses are being run for PCBs. If the analyses show the soil to be contaminated (i.e., have a greater concentration of PCBs than 1.5 ppm), that soil will be stored in the radioactive waste boxes with the top 1-2 ft. of PCB contaminated soil.

Any questions may be addressed to T. F. Pointer.

July 15, 1991

Distribution

USAGE OF "SURE SHOT" CONTAINERS IN PLACE OF AEROSOL CANS - SMS-39-91

In some instances commercial aerosol products contain chlorofluorocarbons (CFCs). The usage of CFCs is slowly being phased-out at the INEL, as per the DOE Waste Minimization Program Plan, May 1990. Some of these commercial products that are available in aerosol form are also available in liquid form. These liquid forms usually do not contain CFCs or freons. Product manufacturers should be able to supply you with the information on the availability of their products in liquid form.

If the ease of an aerosol is deemed necessary, a device called "Sure Shot" can be used with the liquid form of the product, producing an aerosol-like spray after being pressurized with air. Safety could become an issue, depending upon which product is being used in the "Sure Shot". Any product being considered for use in this application should first be reviewed and approved by the appropriate industrial hygienist or safety engineer.

If you would like more information on the "Sure Shot" devices or you have any questions or concerns, I may be contacted at 208-525-5643.

Stella M. Steele
INEL Solvent Substitution Program

November 5, 1991

Distribution

NOTICE OF UPCOMING RECYCLABLE BATTERY SHIPMENTS - JDB-276-91

Plans are being made to ship recyclable batteries off-site prior to the Christmas holidays. If you or someone you know has batteries for recycle please contact Leroy Ewing (6-8294, Fax 6-8007, MS 8102) with the types of batteries, amount (in pounds) of each type, type of container (if any) the batteries are stored in, location of the batteries and an appropriate charge number.

Transportation needs to be scheduled by the first of December, so the above information will need to be gathered and the required paperwork completed before the batteries can be shipped.

Thank you in advance for your cooperation.

T. J. Thilman for

J. D. Bradford, Manager
Waste Reduction Operations Complex

LEE:jc

cc: P. North, EG&G Idaho, MS 3601
J. C. Okeson, EG&G Idaho, MS 3601
J. O. Zane, EG&G Idaho, MS 3600

P.O. Box 1625 Idaho Falls, ID 83415

EG&G
Environmental Coordinator Fact Sheet
Prepared by EG&G Environmental Programs

DISPOSITION OF BATTERIES

A variety of constituents are found in batteries rendering the spent batteries as possibly hazardous wastes, recyclable, or simply as solid waste (non-RCRA regulated), depending upon the battery type.

This guidance sheet has been prepared to assist generators with the packaging and transportation of batteries for storage, recycling, and/or disposal. It is intended to be used in conjunction with Fact Sheet No. 10, Battery Recycling/Disposal Requirements. The information contained in both of these fact sheets is subject to change based on the outcome of the battery recycling/disposal contract process. Expected changes may be in the types of shipping containers the recycler/disposal facility will accept.

The EG&G Idaho Hazardous Waste Handling Operation (HWHO) has set up cargo containers to store spent recyclable and non-RCRA regulated batteries that cannot be stored at facilities. The preference is that generators store the batteries at their facilities until ready to ship. However, space has been made available for interim storage by HWHO for those generators who genuinely do not have storage space.

General Requirements

1. Generators with a "Limited Quantity" (49 CFR 173.244) of batteries will be responsible for delivering the batteries to the Battery Storage Container. For the purpose of this acceptance criteria "limited quantity" is defined as five (5) pounds or less.
2. If one generator or several generators together have more than the "Limited Quantity" amount, a truck will be dispatched and the batteries will be collected at a designated central location.
3. Generators must obtain the services of a qualified shipper. If one is not available to your group call Traffic for assistance. The EG&G Traffic number is 526-0216.
4. Shipments to the Storage Container must be made on Monday afternoons as early as possible, unless other arrangements are made with HWHO.
5. Scheduling for the shipments should be arranged a week in advance to ensure availability of manpower and equipment.
6. Battery terminals must be insulated by covering them with electrical tape or equivalent material before storage and/or shipping.
7. Generators must complete a comprehensive (i.e., 100%) radiological survey of batteries and containers prior to transporting.

8. In addition to restrictions imposed by the EG&G, Idaho, Radiological Controls Manual, and due to the lack of designated and nationally accepted "de minimis" and "Below Regulatory Concern" values for radioactive materials, no batteries with detectable contamination will be allowed in unrestricted, off-site shipments.

Specific Battery Type Requirements

Spent Lithium batteries are RCRA hazardous wastes and cannot be recycled. These batteries must be shipped through the Hazardous Waste Storage Facility (HWSF), also known as the "bunker".

Alkaline and Carbon-Zinc batteries are not presently considered RCRA hazardous waste, but are considered "industrial waste". They are being disposed of at an off-site permitted hazardous waste landfill and do require manifesting for shipping purposes. Requirements:

1. Complete IDF 5480.3A Form with the DOT description "CORROSIVE SOLID, N.O.S., CORROSIVE MATERIAL, UN1759 (SPENT ALKALINE BATTERIES)". If the quantity of batteries meets the limited quantity definition the following must be added to the form: "LTD QTY" or "LIMITED QUANTITY."
2. Complete Battery Storage and Battery Certification Forms.
3. a). For "Limited Quantities", batteries can be packed in plastic or paper containers (not to exceed 5 pounds capacity), which are then packed in fiberboard outside packaging not exceeding 25 pounds net weight each (e.g., plastic or paper sack within a cardboard box).
b). For larger quantities, a metal drum is required with an inner polyethylene liner or, at minimum, a strong inner plastic bag to contain any battery leakage.
4. The container must be marked with the DOT description on container top and side. It shall also be marked on the top and sides "SPENT ALKALINE BATTERIES FOR DISPOSAL".
5. If the shipping container is a metal drum, it must also have corrosive labels on the drum top and side.

Lead acid/Gel cell batteries can be stored together, but segregated from all other battery types. Requirements:

1. Ship the lead acid batteries and gel cell batteries on a completed IDF 5480.3A with the DOT description "BATTERY, WET, FILLED WITH ACID, CORROSIVE MATERIAL, UN2794". (Lead acid batteries for recycle are exempt from the uniform hazardous waste manifest requirements under RCRA.)
2. Complete Battery Storage and Battery Certification Forms.

3. Specification packaging for electric storage batteries containing electrolyte or corrosive battery fluid is not required when:
 - a) No other hazardous materials are transported in the same vehicle,
 - b) The batteries are loaded or braced so as to prevent damage and short circuits in transit,
 - c) Any other material loaded in the same vehicle is secured to prevent contact with or damage to the batteries, and
 - d) The transport vehicle is carrying no material shipped by any person other than the shipper of the batteries.
4. Lead acid and gel cell batteries should be banded or shrink-wrapped to a pallet (leaving battery tops unwrapped for ventilation purposes), in pallet sized tote containers, or packaged in drums with a polyethylene liner.
5. If a container is used it must be marked with the DOT description and have corrosive labels placed on the top and side. The container must also be marked on the top and side "LEAD ACID/GEL CELL BATTERIES FOR RECYCLE".

Nickel-Cadmium (Ni-Cad), Mercury, and Silver "button" batteries, must be segregated by battery type. Requirements:

1. Complete IDF 5480.3A form with DOT description "CORROSIVE SOLID, N.O.S., CORROSIVE MATERIAL, UN1759, (***** BATTERIES WITH ALKALINE ELECTROLYTE)". Enter "NICKEL-CADMIUM", "MERCURY", OR "SILVER" as appropriate for "*****". If the quantity of batteries meets the limited quantity definition the following must be added to the form: "LTD QTY" or "LIMITED QUANTITY."
2. Complete Battery Storage and Battery Certification Forms.
3.
 - a). For "Limited Quantities", batteries can be packed in plastic or paper containers (not to exceed 5 pounds capacity), which are then packed in fiberboard outside packaging not exceeding 25 pounds net weight each (e.g., plastic or paper sack within a cardboard box).
 - b). For larger quantities, a metal drum is required with an inner polyethylene liner or, at minimum, a strong inner plastic bag to contain any battery leakage.
4. The container must be marked with the DOT description on the top and side. The container shall also be marked on the top and side with the type of batteries for recycle, (e.g. "MERCURY BATTERIES FOR RECYCLE").
5. If the shipping container is a metal drum, it must also have corrosive labels on the top and side.

SAB-5-92
From : S. A. Birrer
Phone : 6-3427/MS 3202
Date : February 18, 1992
Subject: HEPA Filter Leach Sampling and Permit Impacts

To G. W. Hogg, Manager
Process Development

cc w/o Federal Register:

R. D. Bradley	J. C. Kent	N. C. Olson
K. N. Brewer	C. K. Kimball	W. B. Palmer
J. G. Burton	K. Kristofferson	W. L. Random
G. B. Frandsen	V. C. Maio	K. L. Shifty
G. R. Franz	R. F. Mozes	G. G. Simpson
M. R. Green	P. I. Nelson	A. M. Umek
S. M. Halupa	B. H. O'Brien	B. R. Wheeler
K. L. Jones		

Ref: (1) G. W. Hogg, Hogg-74-91, to L. F. Ermold, "HEPA Filter Leach Process Implementation at NWCF", dated December 31, 1991.

This letter is in response to the commitment dates in the referenced letter, dated December 31, 1991. Currently there is a proposed regulation in the January 9, 1992 Federal Register on contaminated debris that Environmental Compliance submitted comments on. Our comments focused on several key areas including how we propose the rulemaking to address the issue of filter media sampling and filter treatment, i.e., acid washing. It appears that the rule making has the potential to improve our ability to leach filters for subsequent disposal as non-hazardous waste. (If the EPA modifies the proposed rule as we have suggested).

I have attached a copy of our comment paper along with a copy of the proposed rule making published in the Federal Register.

If the rule is modified in the important but not drastic ways we have suggested, filter leach could operate with very little or no sampling of the filter media or housing and everything remaining after the leaching process could be disposed of to RWMC. The listed waste codes would be deemed removed if the acid bath complies with the regulations.

Westinghouse Idaho Nuclear Company, Inc.

G. W. Hogg
Page 2
SAB-5-92
February 18, 1992

The final rule is required to be issued prior to May 8, 1992. Any regulatory analysis based on current regulations would be worthless for assessing design or operating requirements because the system is not to operate prior to May. For these reasons we wish to adjust our commitment by agreeing to provide you a regulatory analysis of the final rule within two weeks of its issuance. If you have any comments or questions please call me at 6-3427.

S. A. Birrer, Manager
RCRA Compliance

KLS/jll

Attachment

RFM-23-91

From : R. F. Mozes
Phone : 6-1640/MS-5227
Date : August 15, 1991
Subject: Spent Filter Handling Requirements

To : G. R. Franz/3202

cc:	R. J. Bone/3202	J. C. Kent/5117
	J. G. Burton/5230	P. I. Nelson/5227
	P. T. Grahovac/5301	W. L. Random/5227
	J. D. Harris/3202	K. L. Shifty/5117
	M. B. Heiser/5230	T. H. Waite/5227
		Project File

A value engineering study was held on August 5-7, 1991, to discuss the handling of the spent HEPA filters at the ICPP. Several questions concerning the environmental requirements for sampling and disposal were raised and discussed at the meeting. An interpretation on the following questions is requested:

1. What are the sampling requirements for the spent HEPA Filters?
Specifically:
 - a) Is pre-treatment sampling required?
 - b) Is sampling of every filter required, and if a representative sample is adequate, what is a representative sample?
 - c) Are alternatives to the specified TCLP possible, such as considering the entire filter in the leaching vessel as a sample (without the capability of tumbling for 24 hours)?
2. What are the Land Disposal Restrictions (LDR) requirements for the spent filters with respect to treatment, handling, and storage?
3. Is permitting in place and current for the spent filter leach system, and are there any known future permits that would affect filter leach operations?
4. Should leaching of the spent filters be included in the NWCF Part B permit?

G. R. Franz
Page 2
RFM-23-91
August 15, 1991

5. Since elemental mercury may be present in the tank farm does this require that the filters must be considered as having elemental mercury?

The answer to these questions will impact future operation of the filter leach system and the alternatives to the filter leaching system.

Your reply to these questions is requested in thirty (30) days. Please contact T. H. Waite at extension 6-3699 if there are any questions.

R. F. Mozes, Manager
Waste Processing Projects

THW
THW/skm

MS 8527

WBP-88-91
From : W. B. Palmer
Phone : 6-3385/MS-5230/CPP-663
Date : October 18, 1991
Subject: HEPA Filter Leach

To : G. R. Franz, Manager
Environmental Permitting and Regulations

cc: J. G. Burton M. B. Heiser
 L. F. Ermold T. H. Waite
 M. R. Greene P. T. Grahovac

We are currently trying to make decisions on the future of the current HEPA Filter Leach Facility vs the new line item project. We need a ruling on the use of the filter housing weight to meet the disposal requirements for hazardous waste. Please provide this decision by October 31, 1991, so we may meet schedule commitments.

W. B. Palmer

W. B. Palmer, Manager
Waste Processing

/idh

FUNCTIONAL AND OPERATIONAL REQUIREMENTS
FOR THE
SPENT FILTER HANDLING SYSTEM

DRAFT

By

T.H.Waite

September, 1991

Engineering and Plant Projects

For The

U. S. Department of Energy

Idaho Operations Office

Idaho Falls, Idaho

FUNCTIONAL AND OPERATIONAL REQUIREMENTS
FOR THE
SPENT FILTER HANDLING SYSTEM

Prepared By:

Engineering and Plant Projects

Date

Approvals:

Engineering and Plant Projects

Date

Production Department

Date

Nuclear & Industrial Safety Department

Date

Quality Assurance Department

Date

Technical Department

Date

Environmental Compliance

Date

Material Processing Division, DOE-ID

Date

1.0 DESCRIPTION

The purpose of this project is to select, design, and install a Spent Filter Handling System at the Idaho Chemical Processing Plant (ICPP). Currently the used High Efficiency Particulate Air (HEPA) filters are being stored pending a means of disposing of them. The filters must be handled remotely due to the high radiation fields and high levels of contamination. Depending on the source of the filters, they may also contain heavy metals and/or transuranics.

The initial step of this project will consist of a feasibility study to evaluate and recommend one of the preferred alternatives for handling the used HEPA filters. After selection of the process, a filter handling system will be designed and installed at the ICPP to perform this work. The two preferred options for filter handling include filter dissolution or compaction of the filters into storage containers. The feasibility study will include recommendation of a location for the new spent filter handling system and the need for the demolition or removal of any existing equipment, if necessary.

2.0 JUSTIFICATION

2.1 Basis of Need

Used HEPA filters are currently being removed from the filter banks and stored at the cells where they are being generated. It is not possible to dispose of the filters due to the high radiation fields which, combined with the presence of heavy metals and transuranics, classifies them as high-level mixed wastes. There is no place in the country that can receive and store them at this time. There is ~~also no place at the ICPP~~ ^{currently stored at ICPP} where they can be stored in their present configuration pending resolution to this problem. There are over 100 filters at both of the New Waste Calcining Facility (NWCF) and the Fuel Dissolution Process (FDP) facilities. The storage space at these buildings is extremely limited, and additional filters are being generated in the course of plant operations. A means of either disposing of the spent filters or reducing the volume of the filters is necessary to safely continue the ICPP facility operations.

*Must also decide if
final disposal because
NDR exemption up to
May 1992*

Preliminary studies have indicated that the used filters can either be dissolved and treated as high level wastes at the ICPP or compacted in order to reduce their storage volume. The feasibility study will evaluate and recommend a preferred means of handling the filters.

References:

ADS ID-1032-C1, "Filter Leach System Upgrade"

DRAFT

3.0 REQUIREMENTS

3.1 Unique Requirements:

3.1.1 If filter dissolution is selected, the process must be capable of processing the filter with no residues remaining after the system process. It is not necessary that the filter housing be dissolved, and it may be decontaminated and disposed of separately ~~from the filter~~ ^{from filter} housing.

3.1.2 All filter handling operations must be performed remotely due to the high radiation fields. Minimal handling operations are preferred due to the difficulty of remote handling.

3.1.3 If filter compaction is selected, the end product must provide maximum volume reduction. The compaction method must minimize the spread of filter media during the compaction process.

3.1.4 If filter or filter housing and media compaction are selected, the final product shall be capable of being handled and transported to other locations. Although the criteria for filter disposal is not available or known at this time, the final form should be adaptable and capable of being stored or shipped in a variety of containers.

3.1.5 Any sampling requirements required must be performed remotely.

3.1.6 There are currently over 100 filters at both of the NWCF and FDP facilities. The new process should be capable of handling the backlog of filters as well as those currently being generated at the NWCF, FDP, and the other facilities at the ICPP.

3.1.7 The equipment shall be designed to minimize maintenance requirements since it will be located in a contaminated zone.

3.1.8 The preferred location for any filter compaction process is the Filter Handling Cell at the Decontamination Facility, since it is an existing cell designed for remote work.

3.1.9 The new system shall be capable of receiving used filters of varying sizes from several facilities at the ICPP.

3.1.10 The spent filter handling equipment shall be capable of withstanding a corrosive environment if it is installed in the Filter Handling Cell.

3.1.11 The system shall be designed to minimize interference with the Decon Cell operations.

3.1.12 The new system shall minimize the generation of liquid wastes due to the limited waste tank holding capacity.

3.1.13 The new system shall be capable of handling silica gel beads that will be in the filters received from FDP.

*disposal or re-use
of these beads need
to be identified*

3.2 Standard Requirements

3.2.1 General Performance Requirements

3.2.1.1 The system shall be capable of processing the backlog of used HEPA filters as well as the ones that are being generated in the course of ICPP operations.

3.2.1.2 The system shall be designed for ease and simplicity of operation and to be safe and reliable.

DRAFT

3.2.1.4 The need for a new facility shall take into consideration the fact that it may take up to ten years to design and construct a new building.

The new system shall be capable of receiving and processing a variety of filter types and sizes from various facilities at the ICPP. The existing facilities at the Filter Handling Cell shall be utilized to the greatest extent feasible. The existing utility services at the filter handling cell may be used as necessary.

The disposal criteria for high-level mixed hazardous waste has not been prepared. Consequently, the final disposal form of the spent filters after handling shall taken into consideration the need for further handling and packaging requirements.

The filter handling cell is subject to acid vapors, and any equipment in the cell shall be capable of withstanding these conditions.

All work is to be performed remotely due to the high radiation fields. This work shall include the receiving, handling, and final transport of the spent filters.

3.2.8 Access and Administrative Requirements:

3.2.8.2 A Construction Safe Work Permit will be required per WSOP WE-2 for all construction activities. The Construction Safe Work Permit also assures that the areas are monitored by Health Physics (HP's), tie-ins have been properly identified, and outages have been obtained. WINCO procedures WP-3 "Facility Outages and Excavation" and WP-10, "Isolation and Tag/Lockout of ICPP Systems and Equipment" will be followed.

3.2.8.3 No special provisions will be required for the handicapped.

3.2.9 Safety Requirements

3.2.9.1 This project has been designated as Safety Class I. Special consideration will be given to the need to perform work in the contaminated filter handling cell. During operations special non-standard health physics procedures may be required.

3.2.10 Energy Conservation Requirements

3.2.10.1 Energy conservation conditions shall meet the current design requirements for energy conservation.

3.2.11 Quality Requirements

3.2.11.1 The quality assurance provisions shall be determined based on the quality level designations assigned to the different systems or components of the project. The project shall be Quality Level II as determined using QMP 3-3 and WSOP WE-1. The Quality Program Plan (QPP) invokes the applicable requirements of DOE-ID Orders 5700.6C and 4700.1, ANSI/ASME NQA-1, and the WINCO Quality Assurance Manual. Requirements invoked by the QPP shall be implemented by all organizations, when stated, during conceptual, title design, construction, testing, and turnover phases of the project. The Architect Engineer, Construction Manager, and Title III organizations must have an approved QPP. The quality level and QPP's indicate the level of control, detail, and verification needed for designated project activities. The project quality assurance requirements impose management controls on the activities consistent with their importance.

3.2.12 Long-Lead Equipment

3.2.12.1 No long-lead items have been identified at this time. If any long-lead items are identified, they will be procured as GFE as appropriate.

3.2.13 General Utility Requirements

3.2.13.1 The existing utility services may be used unless heavy demands are placed on them. The utility requirements will be evaluated and considered during the conceptual design.

3.2.14 Maintenance Requirements

3.2.14.1 Standard equipment shall be used to the extent feasible. Any equipment placed in contaminated areas such as the Filter Handling Cell shall be designed to minimize maintenance.

4.0 POTENTIAL SOLUTIONS

At the present time there are no means of handling spent HEPA filters at the ICPP. This project will provide a means of either disposing of the

filters dissolution or reducing their volume so that they can be safely stored pending the availability of a permanent storage location. The Filter Leach System has not proven workable for use on the large number of filters that have to be processed.

5.0 SCHEDULE AND COSTS

5.1 Proposed Schedule This is a line item project, with the feasibility study scheduled to begin in October, 1991. After selection of a filter handling process in March, 1992, conceptual design will begin in April, 1992.

	<u>Start</u>	<u>Complete</u>
Feasibility Study	10/91	3/92
Conceptual Design	4/92	12/92
Title Design	1/93	12/93
Procurement/Construction	1/94	6/95
Startup	7/95	6/96

5.2 Cost Estimate

It is not possible to make a cost estimate for this project at the present time, since the system process has not yet been selected.

DRAFT

DRAFT

Solvent Substitution Database Report
Printed On Aug 12, 1991
Predecisional Draft

<u>Company #</u> 1	<u>Company Name</u> 3 D Inc.	<u>Address</u> 2053 Plaza Dr. Benton Harbor, MI. 49022	<u>Phone #</u> 800-272-5326
	<u>Product Name</u> Siege Low Foam-7100 Series 747 1100 Series Aircraft Clnr. 3 D Supreme XP Series 8000	<u>Flashpoint</u> none none none	<u>Tested Performed By:</u> Chemical Sciences EG&G Idaho Chemical Sciences EG&G Idaho Manufacturer
	<u>References</u> General Motors Corp. Ford Motor Co. Whirlpool Aviation Rocketdyne / Div. of Rockwell International, Reynolds Metals		
<u>Company #</u> 2	<u>Company Name</u> Arco Chemical Co.	<u>Address</u> 3801 West Chester Pike, Newtown Sq. Pennsylvania, 19073-2387	<u>Phone #</u> 215-359-2000
	<u>Product Name</u> Arcosolv IPH Arconate 1000 N-Methyl Pyrrolidone	<u>Flashpoint</u> >200 >226 199 cc	<u>Tested Performed By:</u> Manufacturer Manufacturer Manufacturer
	<u>References</u>		
<u>Company #</u> 3	<u>Company Name</u> Better Engineering Mfg.	<u>Address</u> 7101 Belair Rd. Baltimore, MD. 21206	<u>Phone #</u> 800-229-3380
	<u>Product Name</u> Natural Orange	<u>Flashpoint</u> none	<u>Tested Performed By:</u> Manufacturer
	<u>References</u> Baltimore City Vehicle Mtnce, Md. I-Care St. Petersburg FL.		
<u>Company #</u> 4	<u>Company Name</u> Build-All Corp.	<u>Address</u> N59 W14508 Babolink Ave. Monomonee Falls, WI. 53051	<u>Phone #</u> 414-252-3230
	<u>Product Name</u> BAC #100 BAC #137	<u>Flashpoint</u> none none	<u>Tested Performed By:</u>
	<u>References</u>		
<u>Company #</u> 5	<u>Company Name</u> Bio-Tek Inc.	<u>Address</u> P.O. Box 20094. San Diego, CA. 92120	<u>Phone #</u> 619-286-1786
	<u>Product Name</u> 140 Saf-Solv	<u>Flashpoint</u> >220tcc	<u>Tested Performed By:</u> Chemical Sciences EG&G Idaho
	<u>References</u>		

Solvent Substitution Database Report
 Printed On Aug 12, 1991
 Predecisional Draft

<u>Company #</u> 6	<u>Company Name</u> Brulin Corp.	<u>Address</u> P.O. Box 271 Indianapolis, IN. 46205	<u>Phone #</u> 206-536-6612
	<u>Product Name</u> Formula 815 GD Nature Sol 100 Brulin Solv 140	<u>Flashpoint</u> none 156coc 140	<u>Tested Performed By:</u> Chemical Sciences EG&G Idaho Manufacturer Manufacturer
		<u>References</u> Calvin Fong, Northrop Corp 213-332-6661 Boeing Co. Seattle Wa. General Dynamics, Northrop Boeing Co. Seattle Wa. General Dynamics, Northrop	
<u>Company #</u> 7	<u>Company Name</u> BASF Corp.	<u>Address</u> 100 Cherry Nut Rd. Parsippany NJ. 07054	<u>Phone #</u> 409-238-6386
	<u>Product Name</u> EP-323	<u>Flashpoint</u> 235tcc	<u>Tested Performed By:</u>
		<u>References</u> Industrial Solvents, Houston TX.	
<u>Company #</u> 8	<u>Company Name</u> Bioversal USA Inc.	<u>Address</u> 1703 Victoria Dr. #303 Mt. Prospect IL. 60056	<u>Phone #</u> 414-357-4671
	<u>Product Name</u> Bio-Pent E Bioversal GP Concentrate	<u>Flashpoint</u> >142cc 212cc	<u>Tested Performed By:</u>
		<u>References</u>	
<u>Company #</u> 9	<u>Company Name</u> Baker Performance Chemical Inc	<u>Address</u> 3920 Essex Lane, P.O. Box 27714 Houston, TX. 77227-7714	<u>Phone #</u> 713-599-7460
	<u>Product Name</u> Calla 436 LF Calla 301 A Lemon	<u>Flashpoint</u> >200tcc >200tcc	<u>Tested Performed By:</u>
		<u>References</u>	
<u>Company #</u> 10	<u>Company Name</u> Cabot Chemical Corp.	<u>Address</u> 570 W. Lambert Rd. #M Brea Ca. 92622	<u>Phone #</u> 800-345-8224
	<u>Product Name</u> Formula D-166	<u>Flashpoint</u> none	<u>Tested Performed By:</u> Manufacturer
		<u>References</u> U.S. Post Office, Brea CA. Douglas Aircraft, Fullerton CA.	

Solvent Substitution Database Report
 Printed On Aug 12, 1991
 Predecisional Draft

<u>Company #</u> 11	<u>Company Name</u> Chemical Products Ind. Inc.	<u>Address</u> 7649 Southwest 34th Oklahoma City, Ok. 73179	<u>Phone #</u> 405-745-2205
	<u>Product Name</u> Terazyme	<u>Flashpoint</u> none	<u>Tested Performed By:</u> Chemical Sciences, EG&G Idaho
		<u>References</u> Valeo, Ft. Worth TX.	
<u>Company #</u> 13	<u>Company Name</u> Cooke Industries	<u>Address</u> P.O. Box 4420 Kaheohe, Hawaii 96744	<u>Phone #</u> 800-446-6167
	<u>Product Name</u> Tuff Job Degreaser	<u>Flashpoint</u> 176	<u>Tested Performed By:</u> Manufacturer
		<u>References</u> Scofield AFB, Honolulu HI. Diamondhead Base, Honolulu HI.	
<u>Company #</u> 14	<u>Company Name</u> Detrex Chemical Ind. Inc. ICSD	<u>Address</u> 26000 Capitol Ave. Redford, MI. 48239	<u>Phone #</u> 313-937-1900
	<u>Product Name</u> EC-375D EC-376R AC	<u>Flashpoint</u> none none none	<u>Tested Performed By:</u> Manufacturer Manufacturer Manufacturer
		<u>References</u>	
<u>Company #</u> 15	<u>Company Name</u> Dupont	<u>Address</u> Chestnut Run Plaza, P.O. Box 80711 Wilmington DE 19880-0711	<u>Phone #</u> 302-999-3634
	<u>Product Name</u> Axarel 38 Axarel 52	<u>Flashpoint</u> >150tcc 210pmcc	<u>Tested Performed By:</u> Manufacturer Manufacturer
		<u>References</u> Trimble Navigation, CA. 3-Com, CA. Sun Micro, CA. Trimble Navigation, CA. 3-Com, CA. Sun Micro, CA.	
<u>Company #</u> 16	<u>Company Name</u> Dober Chemical Corp.	<u>Address</u> 14461 S. Waverly, Midlothian IL. 60445	<u>Phone #</u> 800-323-4983
	<u>Product Name</u> 8918 8711 B	<u>Flashpoint</u> >200tcc none	<u>Tested Performed By:</u>
		<u>References</u>	

Solvent Substitution Database Report
 Printed On Aug 12, 1991
 Predecisional Draft

<u>Company #</u>	<u>Company Name</u>	<u>Address</u>	<u>Phone #</u>
17	Etus Inc.	1511 Knstner Place, Port of Sanford, Sanford, FL. 32771	407-321-7910

<u>Product Name</u>	<u>Flashpoint</u>	<u>Tested Performed By:</u>	<u>References</u>
Thio Red 2	none		
Buff Clean	none		
RBD-Mil	none		
RB Degreaser	none		

<u>Company #</u>	<u>Company Name</u>	<u>Address</u>	<u>Phone #</u>
18	Enthone-OHI Inc.	2779 El Presidio St. Long Beach, CA. 90810	213-537-0288

<u>Product Name</u>	<u>Flashpoint</u>	<u>Tested Performed By:</u>	<u>References</u>
Resolve 152	>200cc	Manufacturer	
Udylite Resolve 130	none	Manufacturer	
Udylite Resolve 81	none	Manufacturer	

<u>Company #</u>	<u>Company Name</u>	<u>Address</u>	<u>Phone #</u>
19	Enviro-solv	P.O. Box 783 Graylake 60030-0078	708-233-5914

<u>Product Name</u>	<u>Flashpoint</u>	<u>Tested Performed By:</u>	<u>References</u>
II-1 Degreaser	150tcc	Manufacturer	

<u>Company #</u>	<u>Company Name</u>	<u>Address</u>	<u>Phone #</u>
20	Exxon Chemical Co.	P.O. Box 3272 Houston, TX. 77001	203-655-5200

<u>Product Name</u>	<u>Flashpoint</u>	<u>Tested Performed By:</u>	<u>References</u>
Actrel 4493L	200cc	Manufacturer	
Actrel 3393L	200pmcc	Manufacturer	
Actrel 3360L	142cc	Manufacturer	
Actrel 1960	141cc	Manufacturer	
Actrel 1971	174cc	Manufacturer	
Actrel 1160	143	Manufacturer	
Actrel 1911L	235	Manufacturer	
Exxate 1300 Solvent	261	Manufacturer	
Exxate 1000 Solvent	212tcc	Chemical Sciences EG&G Idaho	EG&G Mound, Bob Salermo (513) 865-3205

5
5

Solvent Substitution Database Report
 Printed On Aug 12, 1991
 Predecisional Draft

Citriterge 8910		200	Chemical Sciences EG&G Idaho	
<u>Company #</u>	<u>Company Name</u>	<u>Address</u>	<u>Phone #</u>	
26	Hurri Kleen Corp.	6000 Southern Industrial Dr. Birmingham, Alabama 35235	205-655-8808	
	<u>Product Name</u>	<u>Flashpoint</u>	<u>Tested Performed By:</u>	<u>References</u>
	Hurri-Safe Special fmln dgrsr	none	Manufacturer	
	Hurri-Safe Hot Immersion Dgrsr	none	Manufacturer	
International Products Corp				
<u>Company #</u>	<u>Company Name</u>	<u>Address</u>	<u>Phone #</u>	
27	International Products Corp	P.O. Box 70 Burlington, NJ. 08016	609-386-8776	
	<u>Product Name</u>	<u>Flashpoint</u>	<u>Tested Performed By:</u>	<u>References</u>
	Micro	none	Chemical Sciences EG&G Idaho	Dupage Dicastng, Niles IL. Dow Corning Auburn Mich.
Jet-Lube				
<u>Company #</u>	<u>Company Name</u>	<u>Address</u>	<u>Phone #</u>	
28	Jet-Lube	4849 Homestead Rd. P.O. Box 21258, Houston, TX. 77226	713-674-7617	
	<u>Product Name</u>	<u>Flashpoint</u>	<u>Tested Performed By:</u>	<u>References</u>
	Removit HD	none	Manufacturer	
Johnson Vnx / Gem State Paper				
<u>Company #</u>	<u>Company Name</u>	<u>Address</u>	<u>Phone #</u>	
29	Johnson Vnx / Gem State Paper	1525 Howe St. Racine WI. 53403	208-232-6966	
	<u>Product Name</u>	<u>Flashpoint</u>	<u>Tested Performed By:</u>	<u>References</u>
	Big Bare Water Based Cleaner	none	Manufacturer	Gem State Paper & Supply, Pocatello, ID.
Lonco				
<u>Company #</u>	<u>Company Name</u>	<u>Address</u>	<u>Phone #</u>	
30	Lonco	240 Foster Ave. Bensenville, IL. 60106	312-766-5902	
	<u>Product Name</u>	<u>Flashpoint</u>	<u>Tested Performed By:</u>	<u>References</u>
	Loncoterge 590X2-2	180sc		
LPS Laboratory				
<u>Company #</u>	<u>Company Name</u>	<u>Address</u>	<u>Phone #</u>	
31	LPS Laboratory	4647 Hugh Howell Rd. Tucker GA. 30085-5052	800-241-8334	
	<u>Product Name</u>	<u>Flashpoint</u>	<u>Tested Performed By:</u>	<u>References</u>
	LPS Precision Clean	none	Chemical Sciences EG&G Idaho	McDonnell Douglas, Boeing Co.

Solvent Substitution Database Report
 Printed On Aug 12, 1991
 Predecisional Draft

<u>Company #</u> 32	<u>Company Name</u> Magie Brothers Oil Co.	<u>Address</u> 9101 Fullerton Ave. Franklin Park, IL 60131-1089	<u>Phone #</u> 708-455-4500
	<u>Product Name</u> Magiesol 52	<u>Flashpoint</u> 265	<u>References</u>
		<u>Tested Performed By:</u>	
<u>Company #</u> 33	<u>Company Name</u> Modern Chemical (Carroll Co.)	<u>Address</u> 129 Hellenbrand Ave. P.O. Box 21 Batesville Indiana 47006	<u>Phone #</u> 812-934-4463
	<u>Product Name</u> Blue Gold Industrial Cleaner	<u>Flashpoint</u> none	<u>References</u> Siemens Energy, Cincinnati OH.
		<u>Tested Performed By:</u> Scientific Material Intern.	
<u>Company #</u> 34	<u>Company Name</u> Man.Gill Chemical	<u>Address</u> 23000 St. Clair Ave. Cleveland, OH 44117	<u>Phone #</u> 800-627-6422
	<u>Product Name</u> Gillite 5110B	<u>Flashpoint</u> none	<u>References</u> Trane Air Conditioning
	Gillite 905-XX	none	Trane Air Conditioning
	Gillite 150-X	>200tcc	Trane Air Conditioning
	Gillite 0650	none	Trane Air Conditioning
	Magnuspray 205	none	Trane Air Conditioning
<u>Company #</u> 35	<u>Company Name</u> McGean-Rohco Inc.	<u>Address</u> 9520 E. Cee Bee Dr. Downey, CA. 90241	<u>Phone #</u> 213-203-4311
	<u>Product Name</u> CEE-BEE Cleaner A-7X7NC	<u>Flashpoint</u> none	<u>References</u>
		<u>Tested Performed By:</u> Manufacturer	
<u>Company #</u> 36	<u>Company Name</u> Mirachem	<u>Address</u> 2107. E. 5th St. Tempe, AZ. 85281-3034	<u>Phone #</u> 602-966-3030
	<u>Product Name</u> Mirachem 100 Cleaner-Degreaser	<u>Flashpoint</u> none	<u>References</u>
		<u>Tested Performed By:</u>	

Solvent Substitution Database Report
 Printed On Aug 12, 1991
 Predecisional Draft

<u>Company #</u> 37	<u>Company Name</u> Oakite Products Inc.	<u>Address</u> S. Valley Rd. Berkeley Heights, NJ 07922	<u>Phone #</u> 908-464-6900
	<u>Product Name</u> Oakite Super Turbo-Det	<u>Flashpoint</u> none	<u>Tested Performed By:</u> Manufacturer
		<u>References</u>	
<u>Company #</u> 38	<u>Company Name</u> Orange-Sol Inc.	<u>Address</u> P.O. Box 306 Chandler Az. 85244	<u>Phone #</u> 800-877-2436
	<u>Product Name</u> Clean Away De-Solv-It ADL-1	<u>Flashpoint</u> none 205 212coc	<u>Tested Performed By:</u> Manufacturer Manufacturer Chemical Sciences E&G Idaho
		<u>References</u>	EG&G Darwin Dinsdale, (208) 526-0114
<u>Company #</u> 39	<u>Company Name</u> Petroferm Inc.	<u>Address</u> 5400 First Coast Hwy. Fernandima Beach, FL. 32034	<u>Phone #</u> 904-261-8286
	<u>Product Name</u> Bioact 240 Bioact VS-5 PFC 215-17 PFC 215-9	<u>Flashpoint</u> 241pmcc 220pmcc 241pmcc 255pmcc	<u>Tested Performed By:</u> Manufacturer Manufacturer Manufacturer Manufacturer
		<u>References</u>	AT&T, Kansas City MO. Motorola, Boynton Beach FL, Chicago IL AT&T, Kansas City MO. Motorola, Boynton Beach FL, Chicago IL AT&T, Kansas City MO. Motorola, Boynton Beach FL, Chicago IL AT&T, Kansas City MO. Motorola, Boynton Beach FL, Chicago IL
<u>Company #</u> 40	<u>Company Name</u> Planisol Inc.	<u>Address</u> 452 Hudson Terr. P.O. Box 1302 Englewood Cliffs, NJ. 07632	<u>Phone #</u> 800-877-2436
	<u>Product Name</u> Planisol W	<u>Flashpoint</u> none	<u>Tested Performed By:</u> Manufacturer
		<u>References</u>	
<u>Company #</u> 41	<u>Company Name</u> PPG Ind. Inc. Chemical Group	<u>Address</u> 3938 Porett Dr. Gurnee, IL. 60031	<u>Phone #</u> 800-323-0856
	<u>Product Name</u> Mazawet 77 Macol 48 Minzon 245-103	<u>Flashpoint</u> 300pmcc 240pmcc >200pmc	<u>Tested Performed By:</u> Manufacturer Manufacturer Manufacturer
		<u>References</u>	

Solvent Substitution Database Report
 Printed On Aug 12, 1991
 Predecisional Draft

<u>Company #</u> 42	<u>Company Name</u> Royal Lubricants Co. Inc.	<u>Address</u> East Hanover, NJ. 07936	<u>Phone #</u> 201-887-7410
	<u>Product Name</u> Royco 64D	<u>Flashpoint</u> none	<u>References</u>
	Royco 782	425	
<u>Company #</u> 43	<u>Company Name</u> Rochester Midland	<u>Address</u> 321 Commercial Ave. Kalisndes Park, NJ. 07650	<u>Phone #</u> 800-688-1117
	<u>Product Name</u> LA 180	<u>Flashpoint</u> none	<u>References</u>
	Neugenitc 4176	235coc	
	Neugenitc 4177	none	
<u>Company #</u> 44	<u>Company Name</u> Sentinel Chemical Co. Inc.	<u>Address</u> 7714 Becch St. N.E. Minneapolis, MN. 55432	<u>Phone #</u> 612-571-0630
	<u>Product Name</u> Sentinel 7200	<u>Flashpoint</u> >200pnc	<u>References</u> Reis Environmental, Denver CO. Ramsco, Chicago IL, Houston TX
<u>Company #</u> 45	<u>Company Name</u> Safety Kleen Corp	<u>Address</u> 777 Big Timber Rd. Elgin, IL. 60123	<u>Phone #</u> 312-697-8460
	<u>Product Name</u> REF 32705 Immersion Cleaner	<u>Flashpoint</u> >200tcc	<u>References</u>
<u>Company #</u> 46	<u>Company Name</u> Spartan Chemical Co. Inc.	<u>Address</u> 110 N. Westwood Ave. Toledo, OH 43607	<u>Phone #</u> 419-531-5551
	<u>Product Name</u> IC-115	<u>Flashpoint</u> none	<u>References</u> USDA Classified A-1
	SNB-130	none	USDA Classified A-1

Solvent Substitution Database Report
 Printed On Aug 12, 1991
 Predecisional Draft

<u>Company #</u> 47	<u>Company Name</u> Salesco Marketing	<u>Address</u> 5711 W. Washington Phoenix, AZ. 85043	<u>Phone #</u> 602-278-2717
	<u>Product Name</u> SC-1000 Cleaner	<u>Flashpoint</u> none	<u>References</u>
		<u>Tested Performed By:</u> Manufacturer	
<u>Company #</u> 48	<u>Company Name</u> Stutton Corp.	<u>Address</u> P.O. Box 7913 Metairie, LA 70010	<u>Phone #</u> 504-889-1323
	<u>Product Name</u> EP90 Multiuse Solvent Topsall #30	<u>Flashpoint</u> 205coc none	<u>References</u> General Electric, Exxon Valdez Oil Spill General Electric, Exxon Valdez Oil Spill
<u>Company #</u> 49	<u>Company Name</u> SWI International Inc.	<u>Address</u> 487 Division St. Boonton, N.J. 07005	<u>Phone #</u> 201-334-2525
	<u>Product Name</u> Super Wash	<u>Flashpoint</u> none	<u>References</u> Bell, A&T, Dupont
<u>Company #</u> 50	<u>Company Name</u> Sentry Chemical Co.	<u>Address</u> 1481 Rock Mtn. Blvd. Stone Mountain, GA. 30086	<u>Phone #</u> 404-934-4242
	<u>Product Name</u> Electron Dielectric Solvent Heavyweight Non-Butyl Degreaser Rip-Tide Biodegradable Solvent	<u>Flashpoint</u> 205 none none	<u>References</u>
		<u>Tested Performed By:</u> Manufacturer Manufacturer Manufacturer	
<u>Company #</u> 51	<u>Company Name</u> Titan Chemical (Labs) Inc.	<u>Address</u> 1240 Mtn. View, Alviso Rd. Sunnyvale, CA. 94089	<u>Phone #</u> 408-734-2200
	<u>Product Name</u> Titan Green, All Purpose Clnr	<u>Flashpoint</u> none	<u>References</u>
		<u>Tested Performed By:</u> Manufacturer	
<u>Company #</u> 52	<u>Company Name</u> Tower Chemical Corp.	<u>Address</u> P.O. Box 3070 Palmer, PA. 18047-2703	<u>Phone #</u> 215-253-6206
	<u>Product Name</u> Eco-Clean Degreaser	<u>Flashpoint</u> >200tcc	<u>References</u>
		<u>Tested Performed By:</u> Manufacturer	

Solvent Substitution Database Report
 Printed On Aug 12, 1991
 Predecisional Draft

<u>Company #</u> 53	Compliance Degreaser 270 Cleaner Concentrate	>200tcc none	Chemical Sciences EG&G Idaho Manufacturer	Dana Corp, Lancaster PA. Olevetti Products, Singapore
	<u>Company Name</u> Turco Products Inc.	<u>Address</u> 7300 Bolsa Ave. West Minster CA. 92684-3600	<u>Phone #</u> 714-890-3600	
	<u>Product Name</u> Turco 677B Turco 594B-R	<u>Flashpoint</u> none none	<u>Tested Performed By:</u> Manufacturer Manufacturer	
<u>Company #</u> 54	<u>Company Name</u> Trigon Corp	<u>Address</u> P.O. Box 7183 Reno, Nevada 89510	<u>Phone #</u> 702-359-8494	<u>References</u>
	<u>Product Name</u> Green Beret	<u>Flashpoint</u> none	<u>Tested Performed By:</u> Manufacturer	
	<u>Company Name</u> U.S. Polychemicals Corp.	<u>Address</u> Rt. 45 P.O. Box 268 Spring Valley, NY 10977	<u>Phone #</u> 800-431-2072	
<u>Company #</u> 55	<u>Product Name</u> Lots of Instant Suds	<u>Flashpoint</u> 200	<u>Tested Performed By:</u> Manufacturer	<u>References</u>
	<u>Company Name</u> Universal of St. Louis Inc.	<u>Address</u> 12716 Penridge St. Louis, MO. 63044	<u>Phone #</u> 314-739-6503	
	<u>Product Name</u> U-951	<u>Flashpoint</u> none	<u>Tested Performed By:</u> Manufacturer	
<u>Company #</u> 56	<u>Company Name</u> Vista Chemical Co.	<u>Address</u> P.O. Box 727 Old Spanish Trail Rd. Westlake, LA 70669	<u>Phone #</u> 318-494-5140	<u>References</u> Tennessee Valley Authority
	<u>Product Name</u> LPA-210 Solvent	<u>Flashpoint</u> 215pmcc	<u>Tested Performed By:</u> Chemical Sciences EG&G Idaho	
	<u>Company Name</u> Witco Corp.Kendall/Amalie Div.	<u>Address</u> 77n. Kendall Ave. Bradford, PA 16701	<u>Phone #</u> 212-605-3000	
<u>Company #</u> 57	<u>Product Name</u> Witsol 45	<u>Flashpoint</u> >200	<u>Tested Performed By:</u> Manufacturer	<u>References</u>

Solvent Substitution Database Report
 Printed On Aug 12, 1991
 Predecisional Draft

<u>Company #</u> 64	<u>Company Name</u> VARIOUS PRODUCTS	<u>Address</u> VARIOUS	<u>Phone #</u> VARIOUS
	<u>Solvent Name</u> D'Limonene 96% Pure	<u>Flashpoint</u> <u>Tested Performed By:</u>	<u>References</u> Frank Adams, USAF Little Rock, AFB AR. 501-988-3009
<u>Company #</u> 65	<u>Company Name</u> OCS Manufacturing Inc.	<u>Address</u> P.O. Box 370, San Gabriel, Ca. 91778-0370	<u>Phone #</u> 818-458-2471
	<u>Solvent Name</u> Electronics Cleaner #H2002E Aeronautics Cleaner #HK288HI Ultrasonic Cleaner #H2002U Immersion Cleaner #H2002	<u>Flashpoint</u> none none none none <u>Tested Performed By:</u> Manufacturer Manufacturer Manufacturer Manufacturer	<u>References</u>
<u>Company #</u> 66	<u>Company Name</u> Inland Technology Inc.	<u>Address</u> 2612 Pacific Highway East, Suite C, Tacoma, WA 98424	<u>Phone #</u> 206-922-8932
	<u>Solvent Name</u> Citra Safe Breakthrough Citrex Partsmaster Safety Prep X-Caliber Z-Strip	<u>Flashpoint</u> 150 142 150 141 none 155 150 <u>Tested Performed By:</u> Manufacturer Manufacturer Manufacturer Manufacturer Manufacturer Manufacturer Manufacturer	<u>References</u>
<u>Company #</u> 4	<u>Company Name</u> Build-All Corp.	<u>Address</u> N59 W14508 Bobolink Ave. Monomonee Falls, WI. 53051	<u>Phone #</u> 414-252-3230
	<u>Solvent Name</u> BAC 120	<u>Flashpoint</u> none <u>Tested Performed By:</u>	<u>References</u>
<u>Company #</u> 5	<u>Company Name</u> Bio-Tek Inc.	<u>Address</u> P.O. Box 20094. San Diego, CA. 92120	<u>Phone #</u> 619-286-1786
	<u>Solvent Name</u> 134 Ili-Solv	<u>Flashpoint</u> 215fcc <u>Tested Performed By:</u>	<u>References</u>

Solvent Substitution Database Report
 Printed On Aug 12, 1991
 Predecisional Draft

<u>Company #</u>	<u>Company Name</u>	<u>Address</u>	<u>Phone #</u>
6	Brulin Corp.	P.O. Box 271 Indianapolis, IN. 46205	206-536-6612

<u>Solvent Name</u>	<u>Flashpoint</u>	<u>Tested Performed By:</u>	<u>References</u>
Degreaser 191	>200pmc		

<u>Company #</u>	<u>Company Name</u>	<u>Address</u>	<u>Phone #</u>
67	Envirosolv Inc.	1840 Southside Blvd. Jacksonville, FL, 32216	904-724-1990

<u>Solvent Name</u>	<u>Flashpoint</u>	<u>Tested Performed By:</u>	<u>References</u>
Re-entry KNI	140tcc		
Re-entry RFS	150tcc		
Re-entry ES	145tcc		

<u>Company #</u>	<u>Company Name</u>	<u>Address</u>	<u>Phone #</u>
18	Enthone-OHI Inc.	2779 El Presidio St. Long Beach, CA. 90810	213-537-0288

<u>Solvent Name</u>	<u>Flashpoint</u>	<u>Tested Performed By:</u>	<u>References</u>
Udylite Resolve 29	none		

<u>Company #</u>	<u>Company Name</u>	<u>Address</u>	<u>Phone #</u>
54	Trigon Corp	P.O. Box 7183 Reno, Nevada 89510	702-359-8494

<u>Solvent Name</u>	<u>Flashpoint</u>	<u>Tested Performed By:</u>	<u>References</u>
Citri-X	142coc		
Cleaner Concentrate H.D.	none		

Records printed: 148

Solvent Substitution Database

Printed: 08/19/91 13:18

Predecisional Draft

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Solvent Applications</u>
1	3 D Inc.	Siege Low Foam-7100 Series	High Pressure Spray Spray Cabinet
		747 1100 Series Aircraft Clnr.	Pressure Washer Foamer
		3 D Supreme XP Series 8000	General Agitation
2	Arco Chemical Co.	Arcosolv TPM Arconate 1000 N-Methyl Pyrrolidone	
3	Better Engineering Mfg.	Natural Orange	
4	Build-All Corp.	BAC #100 BAC #137	
5	Bio-Tek Inc.	140 Saf-Solv	
6	Brulin Corp.	Formula 815 GD Nature Sol 100	Pressure Spray Diptank Brush On
		Brulin Solv 140	Spray Wipe
7	BASF Corp.	EP-323	
8	Bioversal USA Inc.	Bio-Pent E Bioversal GP Concentrate	High Pressure Spray Presoak Heated Spray Spray Washed
9	Baker Performance Chemical Inc	Calla 436 LF Calla 301 A Lemon	Mop On Brush On Ultrasonic
10	Cabot Chemical Corp.	Formula D-166	Spray On Soak Swab Stream
11	Chemical Products Ind. Inc.	Terazyme	Agitation

DRAFT

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Solvent Applications</u>
			Ultrasonics Spray Booth
13	Cooke Industries	Tuff Job Degreaser	
14	Detrex Chemical Ind. Inc. ICSD	EC-375D	Immersion
		EC-376R	Spray Washer
		AC	
15	Dupont	Axarel 38	Immersion Direct Spray Spray Undr Immersion Ultrasonics
		Axarel 52	Submerged Liquid Jet Mechanical Agitation Ultrasonic Heated Application
16	Dober Chemical Corp.	8918 8711 B	
17	Etus Inc.	Thio Red 2 Buff Clean RBD-Mil RB Degreaser	
18	Enthone-OMI Inc.	Resolve 152 Udylite Resolve 130	Soak Agitation Ultrasonics Heated Cleaning Spray Wash
		Udylite Resolve 81	Soak Agitation Ultrasonics Heated Cleaning
19	Enviro-solv	H-T Degreaser	Agitation Brush On
20	Exxon Chemical Co.	Actrel 4493L Actrel 3393L Actrel 3360L Actrel 1960 Actrel 1971 Actrel 1160 Actrel 1911L Exxate 1300 Solvent Exxate 1000 Solvent	

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Solvent Applications</u>
21	Fine Organics Corp.	Envirosolv 20743 Envirosolv CRX Envirosolv 2148	
22	Fremont Industries	Fremont 3100 Fremont 776 Fremont 761	Recirculating Spray Mechanical Agitation Spray On Power Wash Turbulation Ultrasonics Turbulation Power Wash Spray Cleaner
23	General Chemical Corp.	Red-Strip 7881	Hot Immersion
24	GAF Corp.	Ship Shape Resin Cleaner M-Pyrol Partsprep Degreaser Preprite Coatings Remover Printsolve Ink Remover	Immersion Spray Brush On Spray On
25	Harry Miller Corp.	Purgitol SR Immunol S-6-H Citriterge 8910	Immersion Parts Washer Soak Tank Heated Applications Immersion Steam Injection Steam Jennie
26	Hurri Kleen Corp.	Hurri-Safe Special fmla dgrsr Hurri-Safe Hot Immersion Dgrsr	
27	International Products Corp	Micro	Ultrasonic Wipe On Soak Heated Applications
28	Jet-Lube	Removit HD	Spray Brush On Wipe On Diptank Steam Cleaner

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Solvent Applications</u>
29	Johnson Wax / Gem State Paper	Big Bare Water Based Cleaner	Pressure Washer Hot Tank Spray Soak Mop On Steam Clean
30	Lonco	Loncoterge 590X2-2	Modified Dishwasher Spray Soak Tank
31	LPS Laboratory	LPS Precision Clean	
32	Magie Brothers Oil Co.	Magiesol 52	
33	Modern Chemical (Carroll Co.)	Blue Gold Industrial Cleaner	
34	Man.Gill Chemical	Gillite 51108	Immersion
		Gillite 905-XX	Immersion Hot Tank
		Gillite 150-X	Immersion
		Gillite 0650	Heated Applications
		Magnuspray 205	
35	McGean-Rohco Inc.	CEE-BEE Cleaner A-7X7NC	Heated Immersion
36	Mirachem	Mirachem 100 Cleaner-Degreaser	
37	Oakite Products Inc.	Oakite Super Turbo-Det	
38	Orange-Sol Inc.	Clean Away De-Solv-It ADL-1	
39	Petroferm Inc.	Bioact 240	Dip Tank Agitated Dip Tank Spray On Brush On
		Bioact VS-5	Spray On Brush On Immersion
		PFC 215-17 PFC 215-9	
40	Planisol Inc.	Planisol M	
41	PPG Ind. Inc. Chemical Group	Mazawet 77 Macol 48	

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Solvent Applications</u>
42	Royal Lubricants Co. Inc.	Mazon 245-103	
		Royco 64D	
		Royco 782	
43	Rochester Midland	LA 180	
		Neugenic 4176	Spray On
		Neugenic 4177	Wipe On
			Pressure Wash
			Steam Cleaner
			Spray On
			Wipe On
			Hot Tank
			Cold Tank
44	Sentinel Chemical Co. Inc.	Sentinel 7200	
			Mop On
			Soak
45	Safety Kleen Corp	REF 32705 Immersion Cleaner	
46	Spartan Chemical Co. Inc.	IC-115	
			Pressure Wash
			Steam Cleaner
			Brush On
			Mop On
			Auto Scrub
		SNB-130	
47	Salesco Marketing	SC-1000 Cleaner	
			Soak Tank
			Pressure Washer
			Steam Cleaner
			Spray On
			Dip Tank
			Brush On
48	Stutton Corp.	EP90 Multiuse Solvent	
		Topsall #30	
			Spray On
			Mop On
			Mechanical Agitation
			Dip Tank
49	SWI International Inc.	Super Wash	
50	Sentry Chemical Co.	Electron Dielectric Solvent	
		Heavyweight Non-Butyl Degreasr	
		Rip-Tide Biodegradable Solvent	
			Power Washer
			Tank Cleaning
			Mechanical Agitation
51	Titan Chemical (Labs) Inc.	Titan Green, All Purpose Clnr	

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Solvent Applications</u>
52	Tower Chemical Corp.	Eco-Clean Degreaser Compliance Degreaser 270 Cleaner Concentrate	
53	Turco Products Inc.	Turco 6778 Turco 5948-R	Heated Application Air Agitation Mechanical Agitation Ultrasonics Turbulation Spray On Mop On Mechanical Agitation
54	Trigon Corp	Green Beret	Steam Cleaning Pressure Washer Parts Washer
55	U.S. Polychemicals Corp.	Lots of Instant Suds	
56	Universal of St. Louis Inc.	U-951	
57	Vista Chemical Co.	LPA-210 Solvent	
58	Witco Corp.Kendall/Amalie Div.	Witsol 45 PD-23 PD-25	
59	W.R. Grace	Daraclean 90i-220 Daraclean 282 Daraclean 283	Heated Application Soak Agitation Spray On Ultrasonic Soak Agitation Spray On Heated Application Soak Agitation Heated Application Spray On
60	Western Water Management Inc.	Concentrated Awesome	Spray On Mop On
61	World Enzymes Inc.	Enzyme Cleaner Degreaser Enzyme Cleaner Degreaser #109 Enzyme Cleaner Degreaser #105	
62	Todco Industries Inc.	Todco 1060	

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Solvent Applications</u>
		Todco 1000	
63	Golden Technologies Co.	Bio-T-Max	
64	VARIOUS PRODUCTS	D'Limonene 96% Pure	
65	OCS Manufacturing Inc.	Electronics Cleaner #H2002E Aeronautics Cleaner #HK288H1 Ultrasonic Cleaner #H2002U Immersion Cleaner #H2002	
66	Inland Technology Inc.	Citra Safe Breakthrough Citrex Partsmaster Safety Prep X-Caliber Z-Strip	
4	Build-All Corp.	BAC 120	
5	Bio-Tek Inc.	134 Hi-Solv	Partswash Clnr Tank Brush On Spray On
6	Brulin Corp.	Degreaser 191	
67	Envirosolv Inc.	Re-entry KNI Re-entry RFS Re-entry ES	Agitation Agitation Agitation Ultrasonic
18	Enthone-OMI Inc.	Udylite Resolve 29	Soak Agitation Ultrasonic Heated Application
54	Trigon Corp	Citri-X Cleaner Concentrate H.D.	Steam Cleaning Pressure Washer Parts Washer

Records printed: 255

Solvent Substitution Database Report
Predecisional Draft
Printed: 08/19/91

Company # Company Name
1 3 D Inc.

Product Name

Siege Low Foam-7100 Series

Soils Removed

Carbon
Grease
Oil
Wax
Ram 225
WD-40
Sani-tuff Hand Cream
Trim sol
Adhesives
Hydraulic Fluid
Machine Coolants
Fuel Oil
Cutting Oils

DRAFT

747 1100 Series Aircraft Clnr.

Carbon
Grease
Oil
Wax
Trim sol
Sani-tuff Hand Cream
Lanolin
Epon 828
Hydraulic Fluid
WD-40
Dioctylphthalate
MOS

3 D Supreme XP Series 8000

Vaseline
Grease
Oil
Hydraulic Fluid
Kester Flux
Sani-tuff Hand Cream
Epon 828

2 Arco Chemical Co.

Arcosolv TPM

Epon 828
WD-40
Dioctylphthalate
Trim sol
Sani-tuff Hand Cream
Ram 225
Hydraulic Fluid
Kester Flux

Arconate 1000

Epon 828
Dioctylphthalate
Trim sol

N-Methyl Pyrrolidone

Paint
Varnish
Ink
Mold
Resin

3 Better Engineering Mfg.

Natural Orange

Oil
Grease
Tar
Wax

7 BASF Corp.

EP-323

8 Bioversal USA Inc.

Bio-Pent E
Bioversal GP Concentrate

Oil Slick Treatment
Resin
Oil
Fats
Albumen
Diesel Oil

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Soils Removed</u>
9	Baker Performance Chemical Inc	Calla 436 LF Calla 301 A Lemon	Phenol Hydraulic Fluid Dirt Carbon Grease Oil
10	Cabot Chemical Corp.	Formula D-166	Proteins Petroleum Based Products Lubricants Oil Grease
11	Chemical Products Ind. Inc.	Terazyme	Hydraulic Fluid WD-40 MOS Grease Sani-tuff Hand Cream Kester Flux Dioctyllphthalate Epon 828 Trim sol
13	Cooke Industries	Tuff Job Degreaser	Grease Oil Wax Carbon WD-40
14	Detrex Chemical Ind. Inc. ICSD	EC-375D EC-376R AC	Oil Smut Working Fluids Oil Smut Working Fluids Oil Smut Working Fluids
15	Dupont	Axarel 38 Axarel 52	Rosin Flux Cutting Oils Grease Oil Wax Sani-tuff Hand Cream Trim sol Vaseline Kester Flux Dioctyllphthalate Buffing Compound Lapping Compound
16	Dober Chemical Corp.	8918 8711 B	
17	Etus Inc.	Thio Red 2 Buff Clean RBD-Mil	Dioctyllphthalate Epon 828 Sani-tuff Hand Cream Versamid 140 WD-40

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Soils Removed</u>
		Actrel 1971	Grime Machine Oils Resin Carbonized Oil Plating Wax Hydraulic Fluid
		Actrel 1160	Hydraulic Fluid Plating Wax Carbonized Oil Resin Machine Oils Grime
		Actrel 1911L	Grime Machine Oils Resin Carbonized Oil Plating Wax Hydraulic Fluid
		Exxate 1300 Solvent	Wax Grease Drawing oils Machine Oils
		Exxate 1000 Solvent	WD-40 Epon 828 Vaseline Trim sol Sani-tuff Hand Cream Diocetylphthalate Ram 225 Krylon Acrylic 150 Hydraulic Fluid Versamid 140 Kester Flux Rosin
21	Fine Organics Corp.	Envirosolv 20743 Envirosolv CRX Envirosolv 2148	
22	Fremont Industries	Fremont 3100	Preservative Oils Forming Fluids
		Fremont 776	Trim sol Dirt
		Fremont 761	Shop Oils Stamp Oils Rust Preventatives Petroleum Based Products Cutting Oils Quenching Oil Drawing Compound
23	General Chemical Corp.	Red-Strip 7881	Paint
24	GAF Corp.	Ship Shape Resin Cleaner	Vaseline WD-40 Hydraulic Fluid Sani-tuff Hand Cream Kester Flux Diocetylphthalate Trim sol Krylon Acrylic 150 Versamid 140 Epon 828
		M-Pyrol	WD-40 Diocetylphthalate

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Soils Removed</u>
			Epon 828 Kester Flux 197 RMA Sani-tuff Hand Cream Hydraulic Fluid Lanolin Versamid 140 MS 143
		Partsprep Degreaser	Carbon Grease Buffing Compound Lubricants Epoxy Resin Machine Oils
		Preprite Coatings Remover Printsolve Ink Remover	
25	Harry Miller Corp.	Purgitol SR	Drawing oils Lubricants Trim sol
		Immunol S-6-H	Mill Oils Drawing Compound Rust Preventatives Vaseline Hydraulic Fluid Sani-tuff Hand Cream Diocetylphthalate Epon 828 Trim sol Smut
		Citriterge 8910	Grease Oil Dirt Smut Carbon Tar Asphalt Gumsoils
26	Hurri Kleen Corp.	Hurri-Safe Special fmla dgrsr	Oil Grease Carbon Petroleum Based Products Paint Flux
		Hurri-Safe Hot Immersion Dgrsr	Wax Flux Paint Petroleum Based Products Carbon Grease Oil
27	International Products Corp	Micro	Oil Grease Silicon Ink Dye Carbon Resin Flux Wax Hydraulic Fluid Diocetylphthalate Trim sol WD-40 MS 143 Sani-tuff Hand Cream

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Soils Removed</u>
28	Jet-Lupe	Removit HD	Oil Grease Grime Dirt
29	Johnson Wax / Gem State Paper	Big Bare Water Based Cleaner	Oil Grease Dirt Lanolin Vaseline Sani-tuff Hand Cream Dioctyllphthalate Epon 828 Trim sol Kester Flux Soot Grime
30	Lonco	Loncoterge 590X2-2	Resin Flu.
31	LPS Laboratory	LPS Precision Clean	Oil Grease Dirt Inorganic Materials Kester Flux Sani-tuff Hand Cream MOS Dioctyllphthalate Trim sol WD-40
32	Magie Brothers Oil Co.	Magiesol 52	Kester Flux Trim sol Dioctyllphthalate
33	Modern Chemical (Carroll Co.)	Blue Gold Industrial Cleaner	Oil Drawing Compound Grease Dirt Trim sol Sani-tuff Hand Cream Epon 828
34	Man.Gill Chemical	Gillite 51108	Mill Oils Machine Oils Drawing Compound Preservative Oils
		Gillite 905-XX	Grease Carbon Oil Paint
		Gillite 150-X	Grease Oil Buffing Compound Dioctyllphthalate Trim sol Wax Hydraulic Fluid Sani-tuff Hand Cream WD-40
		Gillite 0.50	Oil Grease Carbon Dirt

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Soils Removed</u>
		Magnuspray 205	Wax Grease Oil Kester Flux Trim sol Sani-tuff Hand Cream
35	McGean-Rohco Inc.	CEE-BEE Cleaner A-7X7NC	Grease Oil Petroleum Based Products
36	Mirachem	Mirachem 100 Cleaner-Degreaser	
37	Oakite Products Inc.	Oakite Super Turbo-Det	Carbon Grease Oil Grime Gumsoils Wax
38	Orange-Sol Inc.	Clean Away	Proteins Residues
		De-Solv-It	Carbon Grease Oil Flux Paint Hydraulic Fluid Diocetylphthalate Ran 225 Lanolin Trim sol WD-40 Sani-tuff Hand Cream Kester Flux Vaseline
		ADL-1	Oil Ink Epon 828 Hydraulic Fluid Diocetylphthalate
39	Petroferm Inc.	Bioact 240	Grease Lubricants Buffing Compound Body Oils Resin Trim sol Hydraulic Fluid Kester Flux Epon 828 Vaseline WD-40 MOS Stamp Oils Cutting Oils Drawing oils
		Bioact VS-5	Oil Grease Dirt Stamp Oils Drawing oils Cutting Oils
		PFC 215-17	Grease Oil Carbon

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Soils Removed</u>
		PFC 215-9	Oil Grease Carbon
40	Planisol Inc.	Planisol M	
41	PPG Ind. Inc. Chemical Group	Mazawet 77	Dirt Tar Grease Oil Dioctyllphthalate Trim sol WD-40 Sani-tuff Hand Cream Hydraulic Fluid
		Macol 48	Dirt Tar Grease Oil Trim sol
42	Royal Lubricants Co. Inc.	Mazon 245-103	
		Royco 64D	
		Royco 782	
43	Rochester Midland	LA 180	Carbon Grease Oil Trim sol Dioctyllphthalate Sani-tuff Hand Cream Lanolin Vaseline Kester Flux
		Neugenic 4176	Carbon Grease Oil Trim sol Dioctyllphthalate Vaseline WD-40 Sani-tuff Hand Cream
		Neugenic 4177	Carbon Grease Oil Vaseline Trim sol Dioctyllphthalate Sani-tuff Hand Cream
44	Sentinel Chemical Co. Inc.	Sentinel 7200	Mastic Hydraulic Fluid Kester Flux Dioctyllphthalate Vaseline Trim sol Adhesives
45	Safety Kleen Corp	REF 32705 Immersion Cleaner	
46	Spartan Chemical Co. Inc.	IC-115	Grease Carbon Oil Petroleum Based Products Cutting Oils Lube Oil
		SNB-130	Oil

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Soils Removed</u>
			Grease Carbon Petroleum Based Products Sani-tuff Hand Cream Trim sol WD-40 MS 143
47	Salesco Marketing	SC-1000 Cleaner	Animal Fat Oil Grease Dirt WD-40 Sani-tuff Hand Cream
48	Stutton Corp.	EP90 Multiuse Solvent	Adhesives Oil Grease Dirt
		Topsall #30	Oil Smut Wax Grease Mold Petroleum Based Products
49	SWI International Inc.	Super Wash	Wax Oil Grease Carbon
50	Sentry Chemical Co.	Electron Dielectric Solvent	Kester Flux Dioctylphthalate Residues Trim sol Ran 225 Hydraulic Fluid Lanolin Sani-tuff Hand Cream
		Heavyweight Non-Butyl Degreaser	Grease Dirt
		Rip-Tide Biodegradable Solvent	Grease Carbon Coal Dust Fuel Oil
51	Titan Chemical (Labs) Inc.	Titan Green, All Purpose Clnr	Oil Cutting Oils Carbon Dirt Residues WD-40 Trim sol
52	Tower Chemical Corp.	Eco-Clean Degreaser	Grease Oil Carbon Dirt Vaseline WD-40
		Compliance Degreaser	Grease Oil Carbon Dirt
		270 Cleaner Concentrate	Flux

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Soils Removed</u>
			Grease Oil Carbon
53	Turco Products Inc.	Turco 6778	Shop Oils Marking Inks Cutting Oils Forming Oils Lubricants Trim sol Dioctyllphthalate
		Turco 5948-R	Jet Oils Synthetic Oil Films Grease Carbon Exhaust Residues Sani-tuff Hand Cream Dioctyllphthalate Trim sol Hydraulic Fluid
54	Trigon Corp	Green Beret	Grease Carbon Petroleum Based Products Oil Wax
55	U.S. Polychemicals Corp.	Lots of Instant Suds	Ink Grease Oil Carbon
56	Universal of St. Louis Inc.	U-951	Grease Dirt Oil Wax Ink Soap Scum Soot Hydraulic Fluid Sani-tuff Hand Cream Trim sol
57	Vista Chemical Co.	LPA-210 Solvent	Vaseline WD-40 Lanolin Sani-tuff Hand Cream Dioctyllphthalate Kester Flux Trim sol Hydraulic Fluid Ram 225
58	Witco Corp.Kendall/Amalie Div.	Witsol 45	Oil Grease Dirt Grime Hydraulic Fluid Dioctyllphthalate Trim sol WD-40 Kester Flux Vaseline Lanolin Ram 225
		PD-23	Oil Grease Dirt

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Soils Removed</u>
		PD-25	Grime
59	W.R. Grace		Oil Grease Dirt Grime
		Daraclean 90i-220 Daraclean 282	
			Oil Grease Dirt Carbon
		Daraclean 283	
			Oil Grease Dirt Carbon
60	Western Water Management Inc.	Concentrated Awesome	
			Grease Dirt Oil
61	World Enzymes Inc.	Enzyme Cleaner Degreaser Enzyme Cleaner Degreaser #109 Enzyme Cleaner Degreaser #105	
67	Envirosolv Inc.	Re-entry KNI	Oil Grease Working Fluids
		Re-entry RFS	Adhesives
		Re-entry ES	Working Fluids Grease Oil
18	Enthone-OMI Inc.	Udylite Resolve 29	
			Fabricating Oils Heavy Viscous Oils Fingerprints
54	Trigon Corp	Citri-X	
			Grease Tar
		Cleaner Concentrate H.D.	
			Grime Grease Oil Carbon Soap Scum

Records printed: 664

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Hazardous Chemicals</u>
51	Titan Chemical (Labs) Inc.	Titan Green, All Purpose Clnr	Ethylene Glycol Butyl Ether EDTA
52	Tower Chemical Corp.	Eco-Clean Degreaser	Terpene Blend
		Compliance Degreaser	Dipropylene Glycol Methyl Ether
		270 Cleaner Concentrate	NONE
53	Turco Products Inc.	Turco 6778	Tetrapotassium Pyrophosphate Modified Polyethoxylated Alcohol Modified Linear Aliphatic Polyether Potassium Silicate
		Turco 5948-R	2-Butoxyethanol Ethanolamine
54	Trigon Corp	Green Beret	NONE
55	U.S. Polychemicals Corp.	Lots of Instant Suds	NONE
56	Universal of St. Louis Inc.	U-951	Xanthan Gum Sodium Tripolyphosphate Sodium Metasilicate Diethylene Glycol Butyl Ether Propylene Glycol Amphoteric Surfactant Non-ionic Surfactant
57	Vista Chemical Co.	LPA-210 Solvent	NONE
58	Witco Corp.Kendall/Amalie Div.	Witsol 45	NONE
		PD-23	NONE
		PD-25	NONE
59	W.R. Grace	Daraclean 90i-220	NONE
		Daraclean 282	NONE
		Daraclean 283	Sodium Hydroxide
60	Western Water Management Inc.	Concentrated Awesome	NONE
61	World Enzymes Inc.	Enzyme Cleaner Degreaser	NONE
		Enzyme Cleaner Degreaser #109	NONE
		Enzyme Cleaner Degreaser #105	NONE
62	Todco Industries Inc.	Todco 1060	
		Todco 1000	
63	Golden Technologies Co.	Bio-T-Max	
64	VARIOUS PRODUCTS	D'Limonene 96% Pure	
65	OCS Manufacturing Inc.	Electronics Cleaner #H2002E Aeronautics Cleaner #HK288H1 Ultrasonic Cleaner #H2002U Immersion Cleaner #H2002	
66	Inland Technology Inc.	Citra Safe	

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Hazardous Chemicals</u>
		Breakthrough Citrex Partsmaster Safety Prep X-Caliber Z-Strip	
4	Build-All Corp.	BAC 120	Caustic Soda Tetrasodium Pyrophosphate
5	Bio-Tek Inc.	134 Hi-Solv	Hydrocarbon Solvents
6	Brulin Corp.	Degreaser 191	Dipropylene Glycol Methyl Ether Ethyl 3-ethoxypropionate
67	Envirosolv Inc.	Re-entry KNI	NONE NONE NONE
		Re-entry RFS Re-entry ES	
18	Enthone-OMI Inc.	Udylite Resolve 29	Potassium Hydroxide
54	Trigon Corp	Citri-X Cleaner Concentrate H.D.	D'Limonene 2-Butoxyethanol Sodium Metasilicate

Records printed: 212

Solvent Substitution Database
Predecisional Draft
Printed On: 08/19/91

DRAFT

Company # Company Name
1 3 D Inc.

Product Name

Siege Low Foam-7100 Series
747 1100 Series Aircraft Clnr.

Metals Passed In Corrosion Tests

ANODIZED AL
CADMIUM PLTD ST
MAGNESIUM
AL 2024
AL 7075

3 D Supreme XP Series 8000

STEEL
CHROME
BRONZE
CADMIUM
IRON
COPPER
NICKEL
BRASS
STAINLESS ST
LEAD
ALUMINUM

2 Arco Chemical Co.

Arcosolv TPM
Arconate 1000
N-Methyl Pyrrolidone

STEEL
ALUMINUM
CARBON STEEL
ALLOY STEEL
NICKEL

3 Better Engineering Mfg.

Natural Orange

4 Build-All Corp.

BAC #100
BAC #137

5 Bio-Tek Inc.

140 Saf-Solv

6 Brulin Corp.

Formula 815 GD

CDA 443
AL 7075
TITANIUM
SS 310S
SS 304L
SS 410
SS 17-4-PH

7 BASF Corp.

Nature Sol 100
Brulin Solv 140

EP-323

CARBON STEEL

8 Bioversal USA Inc.

Bio-Pent E
Bioversal GP Concentrate

ALL METALS

9 Baker Performance Chemical Inc

Calla 436 LF
Calla 301 A Lemon

ALL METALS

10 Cabot Chemical Corp.

Formula D-166

ALL METALS

11 Chemical Products Ind. Inc.

Terazyme

MAGNESIUM
AL 2024
AL 7075
TITANIUM
SS 310S
SS 304L
SS 410
SS 17-4-PH

13 Cooke Industries

Tuff Job Degreaser

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Metals Passed in Corrosion Tests</u>
14	Detrex Chemical Ind. Inc. ICSD	EC-375D EC-376R AC	ALL FERROUS AL 2024 AL 7075 AL 1100 AL 5456 AL 6061 STEEL ALL FERROUS ALUMINUM AL 2024 AL 7075 AL 7075 AL 5456 AL 6061
15	Dupont	Axarel 38 Axarel 52	ALL FERROUS
16	Dober Chemical Corp.	8918 8711 B	
17	Etus Inc.	Thio Red 2 Buff Clean RBD-Mil RB Degreaser	MAGNESIUM AL 2024 AL 7075 TITANIUM SS 310S SS 304L SS 410 SS 17-4-PH
18	Enthone-OMI Inc.	Resolve 152 Udylite Resolve 130 Udylite Resolve 81	ALL FERROUS STAINLESS ST COPPER STEEL AL 2024 AL 7075 AL 1100 AL 5456 AL 6061 BRASS STEEL STAINLESS ST COPPER ALL FERROUS ALLOY STEEL COPPER NICKEL MAGNESIUM
19	Enviro-solv	H-T Degreaser	ALL METALS
20	Exxon Chemical Co.	Actrel 4493L Actrel 3393L Actrel 3360L Actrel 1960 Actrel 1971 Actrel 1160	ALL METALS ALL METALS ALL METALS ALL METALS ALL METALS ALL METALS ALL METALS

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Metals Passed In Corrosion Tests</u>
		Actrel 1911L	ALL METALS
		Exxate 1300 Solvent	ALL METALS
		Exxate 1000 Solvent	SS 310S SS 304L SS 410 SS 17-4-PH AL 2024 AL 7075 MAGNESIUM CBN STL C1020 TITANIUM
21	Fine Organics Corp.	Envirosolv 20743 Envirosolv CRX Envirosolv 2148	
22	Fremont Industries	Fremont 3100 Fremont 776	ALL METALS ALL NON-FERROUS STEEL STAINLESS ST IRON COPPER BRASS MAGNESIUM
23	General Chemical Corp.	Fremont 761 Red-Strip 7881	ALUMINUM
24	GAF Corp.	Ship Shape Resin Cleaner M-Pyrol	MAGNESIUM AL 2024 AL 7075 TITANIUM SS 310S SS 304L SS 410 SS 310S SS 304L SS 410 SS 17-4-PH AL 2024 AL 7075 MAGNESIUM CBN STL C1020 TITANIUM
		Partsprep Degreaser	TITANIUM RMI WASPALLOY ALLOY
		Preprite Coatings Remover Printsolve Ink Remover	
25	Harry Miller Corp.	Purgitol SR Immunol S-6-H Citriterge 8910	ALL METALS ALL FERROUS ALL NON-FERROUS AL 2024 AL 7075 TITANIUM SS 310S SS 304L SS 410 SS 17-4-PH MAGNESIUM
26	Hurri Kleen Corp.	Hurri-Safe Special fmla dgrsr Hurri-Safe Hot Immersion Dgrsr	

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Metals Passed In Corrosion Tests</u>
27	International Products Corp	Micro	STEEL BRASS STAINLESS ST IRON COPPER
28	Jet-Lube	Removit HD	AL 2024 AL 7075 AL 1100 AL 5456 AL 6061 ALA 356 ALLOY 52 ANODIZED AL BRASS CBN STL C4340 CBN STL C1020 INCONEL 750 INCONEL 625 KOVAR MONEL NICKEL SS 310S SS 304L SS 410 SS 17-4-PH TITANIUM RMI WASPALLOY ALLOY CHROME STEEL MAGNESIUM BRONZE IRON COPPER LEAD ALLOY STEEL ALL FERROUS TITANIUM NICKEL 200 MK 500 CARBON STEEL ALUMINUM STAINLESS ST
29	Johnson Wax / Gem State Paper	Big Bare Water Based Cleaner	CHROME BRONZE ZINC BRASS COPPER STAINLESS ST BRASS TIN CADMIUM LEAD ALUMINUM
30	Lonco	Loncoterge 590X2-2	
31	LPS Laboratory	LPS Precision Clean	STAINLESS ST STEEL ALUMINUM MAGNESIUM
32	Magie Brothers Oil Co.	Magiesol 52	
33	Modern Chemical (Carroll Co.)	Blue Gold Industrial Cleaner	ALL FERROUS ALL NON-FERROUS
34	Man.Gill Chemical	Gillite 51108	ALL FERROUS

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Metals Passed In Corrosion Tests</u>
		Gillite 905-XX	ALL METALS
		Gillite 150-X	
		Gillite 0650	
		Magnuspray 205	ALL METALS
			ALL FERROUS
			ALL NON-FERROUS
35	McGean-Rohco Inc.	CEE-BEE Cleaner A-7X7NC	STEEL
			ALUMINUM
			TITANIUM
			MAGNESIUM
			COPPER
36	Mirachem	Mirachem 100 Cleaner-Degreaser	
37	Oakite Products Inc.	Oakite Super Turbo-Det	
38	Orang-Sol Inc.	Clean Away	
		De-Solv-It	AL 2024
			AL 7075
			TITANIUM
			SS 310S
			SS 304L
			SS 410
			SS 17-4-PH
			MAGNESIUM
39	Petroferm Inc.	ADL-1	
		Bioact 240	
		Bioact VS-5	
		PFC 215-17	
		PFC 215-9	
40	Planisol Inc.	Planisol M	
41	PPG Ind. Inc. Chemical Group	Mazawet 77	
		Macol 48	
		Mazon 245-103	
42	Royal Lubricants Co. Inc.	Royco 640	
		Royco 782	
43	Rochester Midland	LA 180	CADMIUM PLTD ST
			BRASS
			TITANIUM
			CBN STL C4340
			CBN STL C1020
			INCONEL 750
			INCONEL 625
			KOVAR
			MONEL
			NICKEL
			SS 310S
			SS 304L
			SS 410
			SS 17-4-PH
			TITANIUM RMI
			WASPALOY ALLOY
			CHROME
			STEEL
			MAGNESIUM
			TIN
			ZINC
			BRONZE
			IRON
			COPPER
			LEAD
			ALLOY STEEL
			CADMIUM
			STAINLESS ST
			CARBON STEEL
			MK 500

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Metals Passed In Corrosion Tests</u>
		Neugenic 4176	NICKEL 200
		Neugenic 4177	ALL METALS
			ALL METALS
44	Sentinel Chemical Co. Inc.	Sentinel 7200	
45	Safety Kleen Corp	REF 32705 Immersion Cleaner	
46	Spartan Chemical Co. Inc.	IC-115	
			CADMIUM PLTD ST
			BRASS
			CDA 443
			CBN STL C4340
			CBN STL C1020
			INCONEL 750
			INCONEL 625
			KOVAR
			MONEL
			NICKEL
			SS 310S
			SS 304L
			SS 410
			SS 17-4-PH
			TITANIUM RMI
			WASPALLOY ALLOY
			CHROME
			STEEL
			MAGNESIUM
			TIN
			ZINC
			ALL METALS
			BRONZE
			IRON
			COPPER
			LEAD
			ALLOY STEEL
			CADMIUM
			STAINLESS ST
			CARBON STEEL
			MK 500
			NICKEL 200
			TITANIUM
		SNB-130	
			CADMIUM PLTD ST
			BRASS
			CDA 443
			CBN STL C4340
			CBN STL C1020
			INCONEL 750
			INCONEL 625
			KOVAR
			MONEL
			NICKEL
			SS 310S
			SS 304L
			SS 410
			SS 17-4-PH
			TITANIUM RMI
			WASPALLOY ALLOY
			CHROME
			STEEL
			MAGNESIUM
			TIN
			ZINC
			ALL METALS
			BRONZE
			IRON
			COPPER
			LEAD
			ALLOY STEEL
			CADMIUM
			STAINLESS ST
			CARBON STEEL
			MK 500
			NICKEL 200

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Metals Passed In Corrosion Tests</u>
47	Salesco Marketing	SC-1000 Cleaner	TITANIUM
48	Stutton Corp.	EP90 Multiuse Solvent	ALL METALS
		Topsall #30	ALL METALS
49	SWI International Inc.	Super Wash	CADMIUM PLTD ST BRASS CDA 443 CBN STL C4340 CBN STL C1020 INCONEL 750 INCONEL 625 KOVAR MONEL NICKEL SS 310S SS 304L SS 410 SS 17-4-PH TITANIUM RMI WASPALLOY ALLOY CHROME STEEL MAGNESIUM TIN ZINC ALL METALS BRONZE IRON COPPER LEAD ALLOY STEEL CADMIUM STAINLESS ST CARBON STEEL MK 500 NICKEL 200 TITANIUM
50	Sentry Chemical Co.	Electron Dielectric Solvent Heavyweight Non-Butyl Degreaser	ALL METALS
51	Titan Chemical (Labs) Inc.	Rip-Tide Biodegradable Solvent Titan Green, All Purpose Clnr	ALL METALS
52	Tower Chemical Corp.	Eco-Clean Degreaser Compliance Degreaser	ALL FERROUS ALL NON-FERROUS ALL METALS
53	Turco Products Inc.	270 Cleaner Concentrate Turco 6778	ALL FERROUS ALL NON-FERROUS ALUMINUM STEEL COPPER TITANIUM STAINLESS ST MAGNESIUM
54	Trigon Corp	Turco 5948-R Green Beret	ALL METALS
55	U.S. Polychemicals Corp.	Lots of Instant Suds	ALL METALS

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Metals Passed in Corrosion Tests</u>
56	Universal of St. Louis Inc.	U-951	ALL METALS
57	Vista Chemical Co.	LPA-210 Solvent	MAGNESIUM AL 2024 AL 7075 TITANIUM SS 310S SS 304L SS 410 SS 17-4-PH
58	Witco Corp.Kendall/Amalie Div.	Witsol 45 PD-23 PD-25	ALL METALS ALL METALS ALL METALS
59	W.R. Grace	Daraclean 90i-220 Daraclean 282 Daraclean 283	ALL FERROUS ALL NON-FERROUS ALL FERROUS ALL NON-FERROUS ALL FERROUS ALL NON-FERROUS
60	Western Water Management Inc.	Concentrated Awesome	ALUMINUM NICKEL STEEL COPPER STAINLESS ST CHROME
61	World Enzymes Inc.	Enzyme Cleaner Degreaser Enzyme Cleaner Degreaser #109 Enzyme Cleaner Degreaser #105	
62	Todco Industries Inc.	Todco 1060 Todco 1000	
63	Golden Technologies Co.	Bio-T-Max	
64	VARIOUS PRODUCTS	D'Limonene 96% Pure	
65	OCS Manufacturing Inc.	Electronics Cleaner #H2002E Aeronautics Cleaner #HK288H1 Ultrasonic Cleaner #H2002U Immersion Cleaner #H2002	
66	Inland Technology Inc.	Citra Safe Breakthrough Citrex Partsmaster Safety Prep X-Caliber Z-Strip	
4	Build-All Corp.	BAC 120	
5	Bio-Tek Inc.	134 Hi-Solv	
6	Brulin Corp.	Degreaser 191	
67	Envirosolv Inc.	Re-entry KNI Re-entry RFS Re-entry ES	
18	Enthone-OMI Inc.	Udylite Resolve 29	STEEL STAINLESS ST TITANIUM

<u>Company #</u>	<u>Company Name</u>	<u>Product Name</u>	<u>Metals Passed in Corrosion Tests</u>
54	Trigon Corp	Citri-X Cleaner Concentrate H.D.	COBALT ALLOY BLACK IRON GALVANIZED ALL METALS

Records printed: 472

All GE fluorescent lamp ballasts manufactured prior to May 1977 contain a small metal capacitor which in turn contains approximately 10 grams of PCB. Ballasts manufactured after January 1, 1979 contain capacitors without PCB. Ballasts in the interim time period may contain either type. Those ballasts manufactured during the interim period which do not contain PCB may be identified by a catalog number which has a "W" suffix on the label.

Even if the ballast overheats and leaks a black, tar-like material, the PCB-containing capacitor will not normally leak. In the event of a fire, however, PCB's may be released if the ballast and the capacitor ruptures.

Capacitors containing less than 3 pounds PCB are exempted by the EPA and may be disposed of at a sanitary landfill. Since the capacitors contained in our ballasts are well below this limit, they may be sent to such landfills.

I have included a copy of our date-coding system along with drawings of where the date codes are located so that the date of manufacture of your ballasts may be determined.

Should you have any further questions, please feel free to call me at (216) 266-3349.

A. M. Zielinski
Lighting Environmental Operation

Attachments

In response to your request, I am enclosing information on our standard fluorescent lamp and its contents.

The glass tube used in a standard fluorescent lamp is manufactured from soda-lime glass and is essentially similar to that used throughout the glass industry for bottles and other common consumer items. The end-caps on the lamp are generally aluminum while the wires in the lamps (called electrodes) are made of tungsten. None of these materials would present a potential hazard in the event of breakage of the lamp, aside from the obvious ones.

The white coating (normally called a phosphor) on the inside of a standard cool white fluorescent lamp is generally a calcium chloro-fluoro-phosphate, with small amounts (<1-2% each of the phosphor weight) of cadmium, antimony, barium and manganese also present but tightly bound in the phosphor matrix. The percentage of these minor components may change slightly depending on the color of the lamp (cool white, warm white, etc.). Normally a 1 1/2 inch fluorescent lamp has approximately 1.5 grams of the phosphor per foot of lamp. A standard four-foot lamp has about 6 grams of the phosphor coating its inside length.

Except for small changes, it is essentially the same phosphor that has been in use in our lamps for nearly forty years. No significant adverse effects, either by ingestion, inhalation, skin contact, or eye implant, were found in a five-year animal study of the original phosphor by the Industrial Hygiene Foundation of the Mellon Institute. Also, to our knowledge there have been no significant adverse effects on humans by any of these routes during the many years of its manufacture or use. The phosphor is somewhat similar to the inert mineral apatites (calcium phosphate-fluorides) which occur in nature.

Cadmium, antimony, barium, and manganese are listed as hazardous materials by OSHA and workplace exposure limits have been established for them. In addition, although the evidence is limited and conflicting, cadmium and certain cadmium compounds have been listed by the International Agency for Research on Cancer as possible human carcinogens.

Mercury is present in small amounts in all fluorescent lamps. A standard four-foot lamp contains approximately 50 milligrams or less, while an eight-foot lamp may contain 75 - 100 milligrams. The air concentration caused as a result of breaking one or a small number of fluorescent lamps should result in no significant exposure to the individual. However, when breaking a large number of lamps for disposal, appropriate monitoring and controls should be implemented to control airborne levels or surface contamination. We recommend that the work be done in a well-ventilated area, and local exhaust ventilation or personal protective equipment may be needed.

Should you have any further questions, please feel free to contact me at (216) 266-3349.

A. M. Zielinski

This letter is in response to your request for additional information on our Lucalox lamps. These lamps are a high pressure sodium lamp. Although the lamp does contain a small amount of mercury, present as an amalgam with the sodium, there is very little ultraviolet light emitted by the lamp as compared to the mercury or metal halide lamp types. UV is a concern with both the mercury and the metal halide lamps since they can produce considerable amounts of UV if the outer jacket of these lamps is broken and the lamp continues to operate. This is not the case with a Lucalox lamp.

Other than the normal concerns for electrical safety, there are no safety issues involved in the use of Lucalox lamps during use. As for disposal, no special precautions are necessary since the amalgam is contained in the inner arc tube and, unlike low pressure sodium lamps, will not react with water. I have enclosed a copy of a letter concerning the disposal of Lucalox lamps.

I hope this will answer any concerns that you might have regarding these lamps. Should you have any further questions, please call me at (216) 266-3349.

A. M. Zielinski
Lighting Environmental Operation
TECHNOLOGY INTEGRATION OPERATON

GENERAL ELECTRIC

LIGHTING BUSINESS GROUP
GENERAL ELECTRIC COMPANY • NELA PARK • CLEVELAND, OHIO 44112 • (216) 866-

This letter is in response to your request for additional information on our metal halide lamps. These lamps consist of an inner quartz arc tube enclosed in an outer envelope of heat-resistant glass. Depending on the lamp type, the envelope is either clear or coated with one of two different materials. The "MVR" and "MVT" lamps are coated with a phosphor material while the "MXR" lamps are coated with a diffusing material.

The phosphor used on outer envelope of the coated lamps consists of yttrium vanadate phosphate. This material, like most vanadium compounds, is relatively insoluble, and appears to have a much lower toxicity than vanadium pentoxide but may elicit some similar symptoms at high exposure levels. Excessive inhalation exposure to vanadium pentoxide may result in irritation of the nasal passages and respiratory tract, cough, difficulty in breathing, and bronchitis. The yttrium vanadium phosphate from the breakage of one or a small number of lamps should not, however, result in a significant exposure.

The material used as a diffuser the "MXR" lamps is a specially prepared kaolin clay which contains no crystalline silica or asbestos as impurities. These types of clays are generally considered to be toxicologically relatively inert.

The quartz arc tube contains a small amount of mercury, ranging from 20 milligrams in a 75 watt up to 250 mg. in a 1000 watt lamp. The arc tube contains a small amount of the inert gas argon used as a fill gas. It also contains trace amounts of other materials, but there would be no significant exposure from lamp breakage. The air concentration of mercury resulting from the breakage of one or a small number of lamps should result in no significant exposure to the individual. However, when breaking a large number of lamps for disposal, appropriate monitoring and controls should be implemented to control airborne levels or surface contamination. We recommend that such work be done in a well ventilated area, and local exhaust ventilation or personal protective equipment may be needed.

Also contained in the arc tube are small amounts of sodium and scandium iodide, and in some cases thorium iodide. None of these materials are expected to be a hazard in the small quantities present in the arc tube. The coating on the ends of the arc tube is aluminum oxide, a material generally considered to have a low order of toxicity.

The quartz arc tube, when operating, generates a considerable amount of ultraviolet radiation. The UV is filtered to acceptable levels by the glass outer envelope during normal use. However if the outer envelope is broken, this filtering is lost. Thus those lamps having ordering codes beginning with the letters "MVR" or "MXR" have the following warning notice required under Federal Regulation 21 CFR 1040.30:

WARNING: This lamp can cause serious skin burn and eye inflammation from shortwave ultraviolet radiation if outer envelope of the lamp is broken or punctured, and the arc tube continues to operate. Do not use where people will remain for more than a few minutes unless adequate shielding or other safety precautions are used. General Electric Company has commercially available SAF-T-GARD mercury and Multi-Vapor lamps that will automatically extinguish when the outer envelope is broken.

The self-extinguishing lamps referred to above have order codes beginning with the letters "MVT". If the outer glass envelope of a SAF-T-GARD lamp is broken, although the arc tube will have self-extinguished, its support structure will still be electrically connected and could present an electrical shock hazard. Therefore, regardless of the type, if the outer envelope of the lamp has been broken, the lamps should be replaced after turning the power off.

I hope this will answer any concerns that you may have regarding these lamps. Should you have any further questions, please call me at (216)-266-3349. 2430 AMZ:nld

AMZ:nld
Lighting Environmental Operation

AMZ:nld

This letter is in response to your request for additional information on our mercury vapor lamps. These lamps consist of an inner quartz arc tube enclosed in an outer envelope of heat-resistant glass. Depending on the lamp type, the envelope is either clear or coated with one of two different phosphor materials.

The phosphor used on outer envelope of "DX" type lamps consists of yttrium vanadate phosphate. This material, like most vanadium compounds, is relatively insoluble, and appears to have a much lower toxicity than vanadium pentoxide but may elicit some similar symptoms at higher exposure levels. Excessive inhalation exposure to vanadium pentoxide may result in irritation of the nasal passages and respiratory tract, cough, difficulty in breathing, and bronchitis. The yttrium vanadium phosphate from the breakage of one or a small number of lamps should not, however, result in a significant exposure.

The phosphor used on the outer envelope of the "VDX" lamps is the same as that in the "DX" lamps but with the addition of a small amount of magnesium germanate phosphor, a toxicologically relatively inert material.

The quartz arc tube contains a small amount of mercury, ranging from 20 milligrams in a 75 watt up to 250 mg in a 1000 watt lamp. The arc tube contains a small amount of the inert gas argon used as a fill gas. It also contains trace amounts of other materials, but there would be insignificant exposure from lamp breakage. The air concentration of mercury resulting from the breakage of one or a small number of lamps should result in no significant exposure to the individual. However, when breaking a large number of lamps for disposal, appropriate monitoring and controls should be implemented to control airborne levels or surface contamination. We recommend that such work be done in a well ventilated area, and local exhaust ventilation or personal protective equipment may be needed.

The quartz arc tube, when operating, generates a considerable amount of ultraviolet radiation. The UV is filtered to acceptable levels by the glass outer envelope during normal use. However if the outer envelope is broken this filtering is lost. Thus those lamps having ordering codes beginning with the letters "HR" have the following warning notice required under Federal Regulation 21 CFR 1040.30:

WARNING: This lamp can cause serious skin burn and eye inflammation from shortwave ultraviolet radiation if outer envelope of the lamp is broken or punctured, and the arc tube continues to operate. Do not use where people will remain for more than a few minutes unless adequate shielding or other safety precautions are used. General Electric Company has commercially available SAF-T-GARD mercury and Multi-Vapor lamps that will automatically extinguish when the outer envelope is broken.

The self-extinguishing lamps referred to above have order codes beginning with the letters "HT". If the outer glass envelope of a SAF-T-GARD lamp is broken, although the arc tube will have self-extinguished, its support structure will still be electrically connected and could present an electrical shock hazard. Therefore, regardless of the type, if the outer envelope of the lamp has been broken, the lamps should be replaced after turning the power off.

I hope this will answer any concerns that you may have regarding these

lamps. Should you have any further questions, please call me at (216)
266-3349.

A. M. Zielinski
Lighting Environmental Operation

HANDLING BURNED-OUT FLUORESCENT LAMPS

As in the case of any product containing glass and chemicals, reasonable care should be observed when burned out fluorescent lamps are handled and discarded.

Fluorescent lamps are basically low pressure discharge lamps. The electric arc is conducted through an atmosphere of inert gas (usually argon, neon or krypton) and mercury vapor. The light is generated by the thin coating of phosphor on the inside surface of the tube. Since 1949, the basic phosphor used by the General Electric Company in the manufacture of fluorescent lamps has been a relatively inert phosphate. Incidental exposure to that compound due to a broken lamp has been found to be not harmful.

Fluorescent lamps are filled to a very low pressure (almost a vacuum), and implosions may occur when lamps are broken. If lamps are to be broken or crushed prior to disposal, certain precautions should be taken. Proper equipment should be worn to protect the eyes and skin from flying glass fragments. Unbroken lamps should not be thrown into fires or domestic-type incinerators.

Where large quantities of fluorescent lamps are to be broken, either regularly or intermittently, precautionary measures are recommended to control personnel exposure to dispersed dust or mercury vapor. Break lamps outdoors or in a well-ventilated indoor area. The use of a waste container, especially a closed one, and local exhaust ventilation will reduce the dispersed dust and mercury vapor. As in the case of any fine dust, excessive exposure to the phosphor dust should be avoided. In most cases it is not to be expected that the small amount of mercury contained in each lamp will cause any significant amount of airborne mercury. However, where large quantities of lamps are being broken in a confined or poorly ventilated area, mercury vapor concentrations should periodically be measured to determine compliance with established standards. If the level exceeds such standards, corrective steps such as increased ventilation or use of suitable respirators should be taken.

The status of lamps under local and state regulations that follow the federal scheme should be the same. However, some jurisdictions control waste based on the absolute percentage by weight of the regulated material. For example, in California waste containing more than 20 milligrams mercury per kilogram of waste is considered hazardous. A typical four foot fluorescent lamp contains 50 milligrams and weighs about 270 grams. Following is a table of similar data for typical mercury, metal halide and high pressure sodium lamps. The weights listed should not be considered as the exact weight for any one lamp, but as representative of the approximate weight of that lamp type.

<u>Lamp Type</u>	<u>mg Mercury</u>	<u>Lamp weight</u>
HR175DX39	30	150 g
HR400A23	82	260
MVR175/U	26	150
MVR400/C/U	62	270
MVR/HOR	62	270
LU400	23	160

These amounts should be compared to local standards where they are in effect. Lamp disposal in these locations should follow applicable regulations.

Association for Information and Image Management
1100 Wayne Avenue, Suite 1100
Silver Spring, Maryland 20910
301/587-8202

Centimeter

Inches

MANUFACTURED TO AIM STANDARDS
BY APPLIED IMAGE, INC.

2 of 2

ENVIRONMENTAL TESTING & CONSULTING INC.

2924 WALNUT GROVE RD. • MEMPHIS, TENN. 38111 • PHONE (901) 327-2750

December 12, 1988

Mr. Jeff A. Bergersen
Westinghouse Electric Corporation
P.O. Box 2068
Idaho Falls, Idaho 83401

REF: ANALYTICAL TESTING - EP TOXICITY LEACHATE
SAMPLE(S) DATE: 11/11/88
SAMPLE #: 890065 (HAZARDOUS WASTE CHARACTERIZATION)
SAMPLE I.D.: CRUSHED GLASS FROM MERCURY VAPOR LIGHT

Dear Mr. Bergersen:

The above referenced sample has been analyzed per your instructions. The tests were performed in our laboratory (#00210) in accordance with the Federal Register Vol. 45, No. 98, Part 261 "Identification & Listing of Hazardous Waste," Subpart C., 261.24. The results are shown below.

<u>Tests</u>	<u>Results</u> <u>(mg/l)</u>	<u>*MDL</u>	<u>Date</u>	<u>By</u>
Arsenic	0.018	0.002	12/1	JF
Barium	3.94	0.03	11/29	JF
Cadmium	<0.002	0.002	11/29	JF
Chromium	<0.02	0.02	11/29	JF
Lead	<0.02	0.05	11/29	JF
Mercury	<0.001	0.001	12/1	JF
Silver	<0.01	0.01	11/29	JF
Selenium	<0.002	0.002	12/1	JF

* Method Detection Limit

If you have any questions please call me.

Very truly yours,

Michael J. Cimbalo
President

MJC/mg

Westinghouse
Electric Corporation

CHAIN OF CUSTODY RECORD

DATE 11-15-88 PAGE 1 OF 1

NAME Westinghouse Elec. Corp. NRF
ADDRESS P.O. Box 2068
Idaho Falls, Idaho 83401
ATTENTION J.A. Bergersen
PROJECT NAME Haz. Waste Characterization
SOUPO NO 73-H-30050
SAMPLE (SIGNATURE) Jeff Bergersen (PRINTED NAME)

DATE 11/11/88 TIME 1330 LOCATION ECF
SAMPLE NO 840065

TESTING PARAMETERS

NO OF CONTAINERS

1

OBSERVATIONS, COMMENTS,
SPECIAL INSTRUCTIONS

Analyze crushed
contents (glass) for
E.P. Tox. metals

Sample is a high
pressure sodium lamp

SHIPMENT METHOD

SPECIAL SHIPMENT, HANDLING OR STORAGE REQUIREMENTS

TOTAL NUMBER OF CONTAINERS: 1

INSTRUCTIONS:

1. Shaded areas for lab use only.
2. Complete in ballpoint pen. Draw one line through errors and initial.
3. Be specific in test requests.
4. Check off tests to be performed for each sample.
5. Retain final copy after signing.
6. Provide name and telephone of your contact person.

NAME J.A. Bergersen

TELEPHONE (208) 526-5392

DATE

11/15/88

TIME

1131

DATE

11/18

TIME

1015AM

RECEIVED BY

G.W. Tox

(SIGNATURE)

G.W. Tox

(PRINTED NAME)

Westinghouse NRF

(COMPANY)

DATE

11/15/88

TIME

1131

DATE

11/18

TIME

1015AM

RELINQUISHED BY

J. A. Bergersen

(SIGNATURE)

J.A. Bergersen

(PRINTED NAME)

COMPANY

Westinghouse NRF

(COMPANY)

SIGNATURE

J.A. Bergersen

(PRINTED NAME)

COMPANY

Westinghouse NRF

(COMPANY)

From : ECF Facility Engineering

Date : December 29, 1988

Subject: Mercury Vapor Light Analytical Testing (*Sylvania*)

To : D. D. Streett, Manager
ECF Operations (ECF2)

cc:	R. L. Chase (ECF2)	H. J. Maestas (ECF2)
	N. L. Davis (ECF2)	B. J. Paul (ECF2)
	E. G. Dees (ECF2)	D. B. Shaw (ECF2)
	C. L. Hansen (ECF2)	S. J. Smith (ECF2)
	R. L. Harker (ECF2)	M. J. Wise (ECF2)
	E. W. Hook (ECF2)	

A hot cell 1,000 watt mercury vapor light has been analyzed by Environmental Testing and Consulting, Inc., for Extraction Procedure (EP) Toxicity Leachate. The tests were performed in laboratory (#00210) in accordance with the Federal Register, Volume 45, No. 98, Part 261, "Identification and Listing of Hazardous Waste," Subpart C, 261.24. The results show that mercury vapor light bulbs are not hazardous waste and can be disposed of as radioactive waste in Compactor Bail Containers (CBCs) via the 55-ton scrap cask.

Sam Orme 12/29/88
S. P. Orme, Environmental Controls Facilitator
ECF Facility Engineering

SPOrme/dkp
WP/406

APPROVED BY:

B. J. Angwin, Supervisor
Facility Engineering

PRE-08-91

From : P.R. Cunningham
Phone : 6-5940/ ms 5117
Date : August 26, 1991
Subject: CRUSHING FLUORESCENT LIGHT TUBES

AUG 27 1991

RECEIVED

AUG 29 1991

Ans'd.....

To : K.L. Miller

cc: K.M. Coburn
J.D. Edelmeyer
M.A. Georgeson
P.T. Grahovac

G.K. Oswald
R.E. Remsburg
L.R. Stuart
A.M. Umek

Confusion has arisen as to the appropriate action for disposal of fluorescent mercury light tubes here at the ICPP. The problem is that these tubes fail TCLP for mercury because they contain greater than the 0.2 mg/l concentration allowed by the EPA, and are therefore considered hazardous. While a TCLP done on the same material after crushing was found to be less than the 0.2 mg/l limit for mercury and thus non hazardous.

To facilitate disposal and end the current confusion, it has been determined, with concurrence from WINCO attorney, Paul Grahovac, that crushing fluorescent light tubes is an acceptable practice under RCRA for the following reason: a generator is allowed to treat waste, without a permit, provided it is treated at the point of accumulation in the container in which the waste will be shipped (51 FR 10146, March 26, 1986, page 10168).

Please be advised that crushing the light tubes must be done in a DOT approved container which our Shipping and Materials Management section can supply for your needs. The mercury contaminated filter used during the crushing must be removed prior to shipment and tested in accordance with the TCLP to determine whether it is hazardous. If the TCLP results are above the acceptable limits, the filter must be disposed of in accordance with the applicable hazardous waste regulations.

Please contact me at 6-5940 if you have any further questions or need assistance regarding this matter.

P. R. Cunningham
Environmental Assurance

FINAL report for HG LEACH
(EPA copy)

TEST

** EPA Log **

Report for :GOETTSCHE
Address :MS-5211

Log Number : 91-11199
Phone number : 6-3039

Date received :11/19/91
Time received :11:48

Date completed: 01/16/92
Time completed: 12:35

GWA charged :12220-200-001

Reviewed by W.A. RYDER

MSR mR/hr :0

Signature W.A. Ryder

Hazard Index :0

Lab QC/QA reviewed by

Quality Level :IV

Signature Chris Pindler

COMMENTS: (sorted by Analysis)

A TINY AMOUNT OF WEIGHED MERCURY WAS SUBJECTED TO A TCLP
LEACH WITH EXTRACTION FLUID #1 TO SEE IF ELEMENTAL HG WILL
DISSOLVE IN THE FLUID.

Analysis	Sample	Method	Analyst	Result(s) for log 11199
CHROMIUM	#1	2249	MPR	.0308 mg/l
CHROMIUM	#2	2249	MPR	Not Detected:DL= .00630 mg/l
MERCURY	#1	2809	MPR	.00062 mg/l
MERCURY	#2	2809	MPR	Not Detected:DL= .00050 mg/l
TCLP	#1	8998	JHG	Completed. 7.9 mg/ 2 L
TCLP	#2	8998	JHG	Completed. 2.8 mg/ 2 L.

FLAMMABILITY OF HEXONE IN WATER

The flammability of hexone in water solutions was determined at different concentrations using the Pensky-Martens closed cup flashpoint tester. The flashpoints of the samples were determined using ASTM method D93-85. The samples are heated at a slow constant rate with continual stirring. A small flame is directed into the cup at regular intervals with a simultaneous interruption of stirring. The flashpoint is the lowest temperature at which the application of the flame causes the vapor above the sample to ignite.

Solution of different hexone concentrations were prepared by dissolving a small amount of hexone in water. The concentrations of the hexone was verified by analyzing the solutions using Analytical Chemistry method 1-061, March 1987, Gas Chromatographic Determination of Hexone.

The results are tabulated below.

Hexone Concentration

Observed Flashpoint *

0.7	wt %	90 = Fahrenheit
0.360 +- .025	wt %	110 = F.
0.291 +- .022	wt %	117 = F.
0.214 +- .018	wt %	130 = F.
0.195 +- .017	wt %	134 = F.
0.184 +- .017	wt %	137 = F.
0.176 +- .016	wt %	None Observed
0.153 +- .015	wt %	None Observed
0.144 +- .015	wt %	None Observed

* The flashpoints have not be corrected to that which would be observed at a barometric pressure of 760 mm of Hg. Values corrected to that atmospheric pressure would be about 7 degrees higher.

The solutions continued to be tested at temperatures higher than the flashpoint. When the temperatures rose above 140 degrees Fahrenheit, no flashpoints were observed for solutions at any concentration. The small flame was extinguished when it was applied to the vapors within the cup. However, the vapors coming out of the cup would burn as long as the flame was applied to them. Even the vapors coming off the solutions for which no flashpoint was observed would burn.

ge 1

FINAL report for ACETONE

Report for : GOETTSCHE
Address : CPP-602
MS 5211
Date received : 06/07/89
Time received : 16:00
GWA charged : 12220-200-550
MSA mR/hr : 0

Log number : 060712
Phone number : 6-3039
Date completed: 06/12/90
Time completed: 15:34
Reviewed by : R.L. DEMMER

Signature:

AZARD INDEX: 0

Quality Level: None

COMMENTS: (sorted by Analyses)

CONCENTRATIONS ARE V/V.
E

<u>ANALYSIS</u>	<u>SAMPLE</u>	<u>METHOD</u>	<u>ANALYST</u>	<u>RESULTS for 060712</u>
FLASHPOINT	1 %	8985	JHG	NO FLASHPOINT OBSERVED.
FLASHPOINT	1.3 %	8985	JHG	NO FLASHPOINT OBSERVED.
FLASHPOINT	1.4 %	8985	JHG	NO FLASHPOINT OBSERVED.
FLASHPOINT	1.5 %	8985	JHG	55.7 DEG. CENTIGRADE
FLASHPOINT	2 %	8985	JHG	50.7 DEG. CENTIGRADE
FLASHPOINT	3 %	8985	JHG	40.2 DEG. CENTIGRADE

Date: January 8, 1992

To: K. Shifty
MS-5117

cc: R. L. Hand; MS-5211
D. R. Trammell MS-5211
J. H. Nicklas MS-5117

Subject: Benzene and Toluene Analysis Results in Hydrocarbon Diluent.

The analysis of benzene and toluene impurities in hydrocarbon diluent, log 92-01088 is complete. Hydrocarbon diluent raw material was sampled for material specification analysis under log 91-102424. This material was analyzed using the methods of standard additions by ultraviolet absorption spectroscopy. The results of the UV analysis averaged 0.258 volume percent aromatics for five composite samples consisting of 4 drum samples per composite. Ultraviolet absorption spectroscopy is a non-specific type of analysis that is sensitive to primarily aromatic ring compounds and conjugated double bonded organics. In some cases double and triple bonded organics will absorb in the ultraviolet spectrum when certain substituted species are attached to the molecule. However, aliphatic alkanes such as hydrocarbon diluent, Amsco, and n-dodecane are not UV absorbing therefore they can be monitored for general aromatic impurities down to 0.05 % level (500 mg/L) by ultraviolet absorption.

One of the composite samples derived from barrel samples 5 through 8 was then subjected to capillary column gas chromatographic analysis using the photoionization detector and flame ionization detector connected in series. The system was calibrated at 58 ug/mL for both benzene and toluene in methanol solvent. The hydrocarbon diluent was then injected into the GC and no peaks at the calibrated benzene and toluene retention times were noted. A portion of the hydrocarbon diluent was then spiked at 58 ug/mL for benzene and toluene and chromatographed. Benzene and toluene peaks were detected at the calibrated retention times. Based on the methanolic calibration standards, the calculated recovery of benzene was 103 % and toluene was 108 %, indicating insignificant matrix interferences. The reported results are less than 25 mg/L benzene and toluene.

The conclusion reached from these tests indicate that the results from the aromatic analysis by UV absorption spectroscopy is neither due to benzene nor toluene. The UV absorbing compound(s)

are unknown and one can only speculate since UV absorption is so generic in selectivity and the list of organic compounds which absorb in the UV is potentially huge.

Sincerely,

C. G. Christensen 4/8/92

C. G. Christensen
Senior Scientist I
Analytical Chemistry Section

FINAL report for AROMATICS
(Lab copy)

Report for :K SHIFTY
Address :MS-5117

Log Number : 92-01088
Phone number : 6-6937

Date received :01/08/92
Time received :08:30

Date completed: 01/08/92
Time completed: 09:27

GWA charged :12810-200-001

Reviewed by D.R. TRAMMELL

MSR mR/hr :COLD

Signature *D.R. Trammell*

Hazard Index :<1E+05

Quality Level :IV

COMMENTS: (sorted by Analysis)

BENZENE AND TOLUENE IMPURITIES IN HYDROCARBON DILUENT (10242
COMPOSITES FROM 4 BARRELS OF HYDROCARBON DILUENT WERE ANALYZ
NO DETECTABLE BENZENE NOR TOLUENE WAS FOUND. UV ANALYSIS OF
THESE SAMPLES AVERAGED 0.26 VOL % AROMATICS.

Analysis	Sample	Method	Analyst	Result(s) for log 01088
BENZENE	COMP5-8	8000	CGC	NONE DETECT; < 25 MG/L
BENZENE SP	COMP5-8	8003	CGC	103 % AT 58 MG/L SPIKE
TOLUENE	COMP5-8	8001	CGC	NONE DETECT; < 25 MG/L
TOLUENE SP	COMP5-8	8004	CGC	103 % AT 58 MG/L SPIKE

NOTEGRAM

RECEIVED

MAR 13 1991

Ans'd.....

DATE: March 12, 1991

TO: D. A. Pavlica (MS 5211)

RECEIVED

CC: D. E. Davis (MS 5117)
L. C. Lewis (MS 5211)
W. A. Ryder (MS 5211)
✓L. R. Stuart (MS 5117)

MAR 14 1991

Ans'd.....

FROM: K. R. Krivanek (MS 5117)

It has recently become apparent that the service waste composite sample must be analyzed using both the TCLP methods and drinking water standard methods. Please provide both these analytical results for the trace elements beginning with the March composite (March 20, 1991). If you have any questions, feel free to contact me at 6-3949.

Kenneth R. Krivanek

Notegram
J. H. Nicklas
6-3650/CPP-1645/MS 5117
February 13, 1992
TCLP Versus Total Analysis

To: C. V. Park

There have been some discussions regarding the analytical results from a totals analysis compared to a toxicity characteristic leaching procedure (TCLP) analysis. The questions were specifically related to the sampling which occurred for the initial characterization of the percolation ponds for RCRA closure activities.

The main questions regarding the analytical results is the interpretation of the data. The statement has been made that if a total analysis result is less than 20 times the TCLP regulatory level, then a TCLP analysis result would be less than the regulatory level.

The TCLP is a sample preparation procedure for samples. Samples with less than 0.5% solids are filtered, and only the liquid is analyzed. Samples with greater than 0.5% solids are filtered, the solids are leached and the leachate from the solids is recombined with the liquid and analyzed. Samples which are solids, such as soil samples from the percolation pond, would be leached. Steps 2.2 and 7.2.11 from the TCLP procedure (40 CFR 261, Appendix II) calls for the volume of extraction fluid used to be twenty times the weight of the sample. TCLP procedural steps 2.3 and 7.2.14 call for the analysis of the extract/leachate (liquid phase). Since the volume of leachate used is twenty times that of the solid, a minimum of a twenty fold reduction in the concentration occurs. A greater reduction in the concentration may occur due to the leachability of the contaminant.

The maximum concentration regulatory level for chromium (40 CFR 261.24) is 5.0 mg/L. Twenty times the regulatory level is 100 mg/L. The total analysis results obtained from the sampling of percolation pond #2 ranged from 8.8 to 22.2 mg/Kg. Since the maximum concentration obtained from the totals analysis (22.2 mg/Kg) is less than twenty times the regulatory level (100 mg/L), the sample is not considered to have the waste number D007 for chromium.

John H. Nicklas

07/10/91

ETS ICLP DATABASE

Page No. 1

CFA BIG SHOP COVERALLS

WASTE DESCRIPTION COMMENTS RANDOM SAMPLE OF COVERALLS (SOILED) FROM CFA BIG SHOP

COVERALLS SOILED FROM NORMAL OPERATIONS IN THE CFA BIG SHOP. WANTED TO DEMONSTRATE THAT LAUNDERING OF THE COVERALLS IS NOT TREATING A HAZARDOUS WASTE.

D004	ND	D014	D024	D034
D005	0.691	D015	D025	ND
D006	0.120	D016	D026	D036
D007	ND	D017	D027	D037
D008	ND	D018	ND	D038
D009	ND	D019	ND	D039
D010	ND	D020	D030	ND
D011	ND	D021	D031	D041
D012	ND	D022	D032	D042
D013	D023	D033	D043	ND

CFA BIG SHOP RAGS

WASTE DESCRIPTION COMMENTS RANDOM SAMPLE OF RAGS (SOILED) FROM CFA BIG SHOP

RAGS SOILED FROM NORMAL OPERATIONS IN THE CFA BIG SHOP. WANTED TO DEMONSTRATE THAT LAUNDERING THE RAGS IS NOT TREATING A HAZARDOUS WASTE.

D004	0.104	D014	D024	D034
D005	0.603	D015	D025	ND
D006	0.594	D016	D026	D036
D007	0.017	D017	D027	D037
D008	ND	D018	ND	D038
D009	ND	D019	ND	D039
D010	ND	D020	D030	ND
D011	0.009	D021	D031	D041
D012	ND	D022	D032	D042
D013	D023	D033	D043	ND

CFA BS LARGE PARTS WASHER

WASTE DESCRIPTION COMMENTS SOLIDS FROM THE LARGE PARTS WASHER IN THE CFA BIG SHOP

SOLIDS FROM THE BOTTOM OF THE LARGE PARTS WASHER IN THE CFA BIG SHOP TAKEN TO DETERMINE IF THEY EXHIBIT THE TOXICITY CHARACTERISTIC UNDER RCRA.

D004	ND	D014	D024	D034
D005	1.34	D015	D025	ND
D006	0.014	D016	D026	D036
D007	0.076	D017	D027	D037
D008	ND	D018	ND	D038
D009	ND	D019	ND	D039
D010	ND	D020	D030	ND
D011	ND	D021	D031	D041
D012	ND	D022	D032	D042
D013	D023	D033	D043	ND

07/10/91

ETS ICPL DATABASE

Page No. 2

WASTE	CFA BS SMALL PARTS WASHER	
DESCRIPT	SOLIDS FROM THE SMALL PARTS WASHER IN THE CFA BIG SHOP	
COMMENTS	SOLIDS TAKEN FROM THE BOTTOM OF THE SMALL PARTS WASHER IN THE CFA BIG SHOP TO SEE IF THEY EXHIBIT THE CHARACTERISTIC OF TOXICITY UNDER RCRA.	
D004	ND	D014 D024 D034
D005	0.391	D015 D025 ND
D006	0.575	D016 D026
D007	0.021	D017 D027
D008	ND	D018 ND D028 ND
D009	ND	D019 ND D029 ND
D010	ND	D020 D030 ND
D011	ND	D021 ND D031 ND
D012	ND	D022 ND D032 ND
D013		D023 D033 ND

WASTE	CFA BS LARGE PARTS WASHER	
DESCRIPT	LIQUID FROM LARGE PARTS WASHER AT CFA BIG SHOP	
COMMENTS	LIQUID TAKEN FROM THE LARGE PARTS WASHER IN THE CFA BIG SHOP TO DETERMINE WHETHER THE LIQUID EXHIBITS THE CHARACTERISTIC OF TOXICITY UNDER RCRA.	
D004	0.54	D014 D024 D034
D005	0.76	D015 D025 ND
D006	0.03	D016 D026
D007	0.59	D017 D027
D008	ND	D018 ND D028 ND
D009	ND	D019 ND D029 ND
D010	ND	D020 D030 ND
D011	ND	D021 ND D031 ND
D012	ND	D022 ND D032 ND
D013		D023 D033 ND

WASTE	DIESEL CONTAMINATED SOIL	
DESCRIPT	SOIL COLLECTED FROM SITE OF DIESEL SPILL - SPILL SITE NOT SPECIFIED	
COMMENTS	EIGHT GALLON DRUM CONTAINING DIESEL CONTAMINATED SOIL STORED AT WERF TAA.	
D004	ND	D014 D024 D034
D005	0.7	D015 D025 0.01
D006	0.01	D016 D026
D007	0.06	D017 D027
D008	ND	D018 ND D028 ND
D009	ND	D019 ND D029 ND
D010	ND	D020 D030 ND
D011	ND	D021 ND D031 ND
D012	ND	D022 ND D032 ND
D013		D023 D033 ND

07/10/91

EIS TCLP DATABASE

Page No. 3

WASTE	DIESEL CONTAMINATED KITTY LITT									
DESCRIPT	KITTY LITTER USED TO ABSORB DIESEL									
COMMENTS	CHAIN OF CUSTODY FORM IDENTIFIES SAMPLE LOCATION WITH CFA 688 BOILER									
D004	ND	D014		D024	ND	D034	ND			
D005	0.5	D015		D025	ND	D035	ND			
D006	0.03	D016		D026	ND	D036	ND			
D007	0.02	D017		D027	ND	D037	ND			
D008	0.82	D018	ND	D028	ND	D038	ND			
D009	ND	D019	ND	D029	ND	D039	ND			
D010	ND	D020		D030	ND	D040	ND			
D011	ND	D021	ND	D031		D041	ND			
D012		D022	ND	D032	ND	D042	ND			
D013		D023	ND	D033	ND	D043	ND			

WASTE	OILY RAGS									
DESCRIPT	OILY RAGS FROM WIPING/CLEANING									
COMMENTS	CHAIN OF CUSTODY FORM INDICATES RAGS COME FROM CFA-688 BOILER AREA									
D004	ND	D014		D024	ND	D034	ND			
D005	0.2	D015		D025	ND	D035	ND			
D006	0.03	D016		D026	ND	D036	ND			
D007	0.04	D017		D027	ND	D037	ND			
D008	ND	D018	ND	D028	ND	D038	ND			
D009	ND	D019	ND	D029	ND	D039	ND			
D010	ND	D020		D030	ND	D040	ND			
D011	ND	D021	ND	D031		D041	ND			
D012		D022	ND	D032	ND	D042	ND			
D013		D023	ND	D033	ND	D043	ND			

WASTE	GASOLINE CONTAMINATED SOIL									
DESCRIPT	GASOLINE CONTAMINATED SOIL COLLECTED DURING THE CLEANUP OF A GASOLINE SPILL NEAR CFA LANDFILL. SOIL STORED IN 4-55 GALLON DRUMS IN CFA-689 TAA.									
COMMENTS	ESTIMATED 6 TO 7 GALLONS OF GASOLINE RELEASED FROM RUPTURED FUEL TANK ON VEHICLE. MEK LEVEL BELOW IS NOT OF CONCERN BECAUSE MEK WAS ALSO DETECTED IN THE BLANK									
D004	ND	D014		D024	ND	D034	ND			
D005	1.1	D015		D025	ND	D035	0.10			
D006	0.03	D016		D026	ND	D036	ND			
D007	0.03	D017		D027	ND	D037	ND			
D008	ND	D018	0.015	D028	ND	D038	ND			
D009	ND	D019	ND	D029	ND	D039	ND			
D010	ND	D020		D030	ND	D040	ND			
D011	ND	D021	ND	D031		D041	ND			
D012		D022	ND	D032	ND	D042	ND			
D013		D023	ND	D033	ND	D043	ND			

07/10/91

EIS TCLP DATABASE

Page No. 4

DIESEL CONTAMINATED KITTY LITT

WASTE DESCRIPTION COMMENTS
KITTY LITTER USED AS ABSORBENT FOR DIESEL CLEANUP. STORED IN CFA-6891AA.
SOURCE AND CONDITIONS OF DIESEL SPILL NOT SPECIFIED.

D004	0.975	D014	D024	D034
D005	0.514	D015	D025	D035
D006	ND	D016	D026	D036
D007	ND	D017	D027	D037
D008	ND	D018	0.091	D038
D009	ND	D019	ND	D039
D010	ND	D020	D030	D040
D011	0.012	D021	D031	D041
D012	ND	D022	D032	D042
D013	ND	D023	D033	D043

MOTOR OIL (NEW/UNUSED)

WASTE DESCRIPTION COMMENTS
SAMPLE PULLED FROM UNUSED CONTAINER OF MOTOR OIL IN CFA BIG SHOP. * BY ND INDICATES DETECTION LEVEL ABOVE REGULATORY LEVEL.
DUE TO MATRIX EFFECTS IN THE SAMPLE, ANALYTICAL DILUTION WAS REQUIRED. AS A RESULT, THE DETECTION LIMITS FOR MOST OF THE VOLATILE AND ALL THE SEMIVOLATILES
EXCEED THE TCLP LEVEL. DETECTION LEVELS FOR D021 AND D035 WERE 1/2 THE REGULATORY LEVEL

D004	ND	D014	D024	D034
D005	ND	D015	D025	D035
D006	ND	D016	D026	ND*
D007	ND	D017	D027	ND*
D008	ND	D018	ND*	D038
D009	ND	D019	ND*	D039
D010	ND	D020	D030	ND*
D011	ND	D021	D031	ND*
D012	ND	D022	D032	ND*
D013	ND	D023	D033	ND*

CFA BUS WASH SUMP SLUDGE

WASTE DESCRIPTION COMMENTS
SLUDGE COLLECTED FROM CFA BUS WASH SUMP. SAMPLE CONSISTS OF THE SOLID PORTION OF THE TWO PHASE MATERIAL IN THE SUMP.

D004	ND	D014	D024	D034
D005	0.7	D015	D025	D035
D006	ND	D016	D026	D036
D007	0.06	D017	D027	D037
D008	0.2	D018	ND	D038
D009	ND	D019	ND	D039
D010	ND	D020	D030	D040
D011	ND	D021	D031	D041
D012	ND	D022	D032	D042
D013	ND	D023	D033	D043

07/10/91

ETS TCLP DATABASE

Page No. 5

CFA BUS WASH SUMP LIQUID

LIQUID COLLECTED FROM CFA BUS WASH SUMP. SAMPLE CONSISTS OF THE LIQUID PHASE OF A TWO PHASE (SOLID AND LIQUID) MATERIAL IN THE SUMP.

COMMENTS

D004	ND	D014	D024	ND	D034	ND
D005	0.36	D015	D025	ND	D035	ND
D006	0.06	D016	D026	ND	D036	ND
D007	0.02	D017	D027	ND	D037	ND
D008	0.59	D018	D028	ND	D038	ND
D009	ND	D019	D029	ND	D039	ND
D010	ND	D020	D030	ND	D040	ND
D011	ND	D021	D031	ND	D041	ND
D012	ND	D022	D032	ND	D042	ND
D013	ND	D023	D033	ND	D043	ND

OILY RAGS

OILY RAGS COLLECTED FROM THE CFA-665 BOILER ROOM

OILY RAGS GENERATED IN THE CFA-665 BOILER ROOM AND TESTED TO DETERMINE IF THE RAGS MIGHT CONTAIN REGULATED AMOUNTS OF RCRA HAZARDOUS SUBSTANCES.

D004	ND	D014	D024	ND	D034	ND
D005	1.4	D015	D025	ND	D035	ND
D006	ND	D016	D026	ND	D036	ND
D007	0.05	D017	D027	ND	D037	ND
D008	ND	D018	D028	ND	D038	ND
D009	ND	D019	D029	ND	D039	ND
D010	ND	D020	D030	ND	D040	ND
D011	ND	D021	D031	ND	D041	ND
D012	ND	D022	D032	ND	D042	ND
D013	ND	D023	D033	ND	D043	ND

USED OIL

COMPOSITE SAMPLE OF USED OIL STORED IN SEVERAL DRUMS AT CFA-665. THE SAMPLING NOTES INDICATED THERE MAY BE SOME GREASE IN THE OIL ALSO.

THE ANALYSIS FOR METALS IS A TOTALS ANALYSIS RATHER THAN TCLP.

D004	ND	D014	D024	ND	D034	ND
D005	6.0	D015	D025	ND	D035	ND
D006	0.7	D016	D026	ND	D036	ND
D007	ND	D017	D027	ND	D037	ND
D008	10.8	D018	D028	ND	D038	ND
D009	ND	D019	D029	ND	D039	ND
D010	ND	D020	D030	ND	D040	ND
D011	ND	D021	D031	ND	D041	ND
D012	ND	D022	D032	ND	D042	ND
D013	ND	D023	D033	ND	D043	ND

07/10/91

ETS ICLP DATABASE

Page No. 6

WASTE DIESEL FUEL CONTAMINATED SOIL
 DESCRIPT SOIL CONTAMINATED FROM DIESEL FUEL SPILL WAS COLLECTED FROM THE MOST SATURATED SPOT IN THE ROADWAY WITHIN 4 HOURS OF THE SPILL. THE AMBIENT TEMPERATURE WAS 1 AND 50 DEGREES F.

COMMENTS THIS SAMPLE WAS ANALYZED FOR VOLATILES ONLY. THE HOLDING TIME WAS EXCEEDED BY ONE DAY FOR VOLATILES. THE MATERIAL CLEANED UP IN THE SPILL WAS SAMPLED AGAIN AFTER IT WAS CONTAINERIZED. THE RESULTS ARE INCLUDED BELOW.

D004	D014	D024	D034
D005	D015	D025	0.003
D006	D016	D026	D036
D007	D017	D027	D037
D008	D018	0.026	ND
D009	D019	ND	ND
D010	D020	D030	ND
D011	D021	ND	D041
D012	D022	ND	D042
D013	D023	D033	D043

WASTE DIESEL CONTAMINATED SOIL
 DESCRIPT SOIL COLLECTED DURING CLEANUP OF DIESEL SPILL WHICH OCCURRED ON 10-30-90. THIS SAMPLE WAS COLLECTED FROM THE SOIL CONTAINED IN BARRELS AFTER THE CLEANUP.
 COMMENTS SAMPLE ANALYZED FOR VOLATILES AND METALS.

D004	ND	D014	D024	D034
D005	0.9	D015	D025	D035
D006	ND	D016	D026	D036
D007	0.04	D017	D027	D037
D008	0.3	D018	ND	D038
D009	ND	D019	ND	D039
D010	ND	D020	D030	D040
D011	ND	D021	D031	D041
D012	ND	D022	D032	D042
D013	D023	D033	D043	ND

WASTE SOIL W/ HYDRAULIC OIL CONTAM.
 DESCRIPT SOIL COLLECTED IN CLEANUP OF HYDRAULIC OIL SPILL.

D004	ND	D014	D024	D034
D005	0.73	D015	D025	D035
D006	ND	D016	D026	D036
D007	0.03	D017	D027	D037
D008	0.79	D018	ND	D038
D009	ND	D019	ND	D039
D010	ND	D020	D030	D040
D011	ND	D021	D031	D041
D012	ND	D022	D032	D042
D013	D023	D033	D043	ND

07/10/91

ETS TCLP DATABASE

Page No. 7

WASTE SILVER IODIDE RESPIR. CANISTER

CONTENTS OF A SILVER IODIDE RESPIRATOR CANISTER WERE REMOVED AND TESTED FOR TCLP METALS. THE CANISTER IS FROM A HSA CARTRIDGE - LARGE CANISTER.

WASTE DESCRIPT	COMMENTS		
D004	ND	D014	D024
D005	ND	D015	D025
D006	ND	D016	D026
D007	0.03	D017	D027
D008	ND	D018	D028
D009	ND	D019	D029
D010	ND	D020	D030
D011	0.02	D021	D031
D012		D022	D032
D013		D023	D033
			D034
			D035
			D036
			D037
			D038
			D039
			D040
			D041
			D042
			D043

WASTE WASHDOWN FROM INDOOR GUNRANGE

SAMPLE OF LIQUID EFFLUENT COLLECTED FROM A SAMPLING TAP LOCATED IN THE INDOOR GUN RANGE WHILE THE FLOOR WAS BEING WASHED DOWN.

SAMPLED THE WASHDOWN WATER FOR LEAD WHICH MAY HAVE BEEN PRESENT AFTER SHOOTING IN THE RANGE.

WASTE DESCRIPT	COMMENTS		
D004		D014	D024
D005		D015	D025
D006		D016	D026
D007		D017	D027
D008	0.003	D018	D028
D009		D019	D029
D010		D020	D030
D011		D021	D031
D012		D022	D032
D013		D023	D033
			D034
			D035
			D036
			D037
			D038
			D039
			D040
			D041
			D042
			D043

WASTE MERCURY VAPOR BULB

SPENT MERCURY VAPOR BULB

* INDICATES BELOW PQL FOR ANALYTICAL METHOD BUT LAB ESTIMATED VALUE ANYWAY.

WASTE DESCRIPT	COMMENTS		
D004	*0.23	D014	D024
D005	*0.2	D015	D025
D006	ND	D016	D026
D007	ND	D017	D027
D008	3.92	D018	D028
D009	0.32	D019	D029
D010	ND	D020	D030
D011	ND	D021	D031
D012		D022	D032
D013		D023	D033
			D034
			D035
			D036
			D037
			D038
			D039
			D040
			D041
			D042
			D043

07/10/91

ETS TCLP DATABASE

Page No. 8

WASTE SEWAGE SLUDGE

DESCRIPT SEWAGE SLUDGE AWAITING DISPOSAL AT CFA. SAMPLE COLLECTED IS A COMPOSITE OF 29 BOXES OF SLUDGE.

COMMENTS D022 AND D039 ARE ESTIMATED VALUES BUT ARE BELOW PQL'S OF THE METHOD

D004	ND	D014	D024	D034	ND
D005	0.23	D015	D025	D035	ND
D006	NE	D016	D026	D036	ND
D007	ND	D017	D027	D037	ND
D008	ND	D018	D028	D038	ND
D009	ND	D019	D029	D039	0.001
D010	ND	D020	D030	D040	ND
D011	ND	D021	D031	D041	ND
D012		D022	D032	D042	ND
D013		D023	D033	D043	ND

WASTE WELDING PENETRANT - TURCO DY-CHIE

DESCRIPT WELDING PENETRANT APPLIED FROM AEROSOL CAN. USED IN TRA 635. THE PENETRANT IS TURCO DY-CHIEK.

COMMENTS DUE TO MATRIX EFFECTS, THE SAMPLE HAD TO BE DILUTED AND THE DETECTION LEVEL FOR ALL THE VOLATILE AND SEMIVOLATILE COMPONENTS IS ABOVE THE REGULATORY LEVEL.

D004	ND	D014	D024	D034	ND
D005	ND	D015	D025	D035	ND
D006	ND	D016	D026	D036	ND
D007	ND	D017	D027	D037	ND
D008	ND	D018	D028	D038	ND
D009	ND	D019	D029	D039	ND
D010	ND	D020	D030	D040	ND
D011	ND	D021	D031	D041	ND
D012	ND	D022	D032	D042	ND
D013		D023	D033	D043	ND

WASTE RAGS CONTAMINATED W/WELD PENET

DESCRIPT RAGS USED TO WIPE PENETRANT OFF WELDS AT TRA-635. THE PENETRANT IS TURCO DY-CHIEK PENETRANT.

D004	ND	D014	D024	D034	ND
D005	ND	D015	D025	D035	ND
D006	ND	D016	D026	D036	ND
D007	ND	D017	D027	D037	ND
D008	ND	D018	D028	D038	ND
D009	ND	D019	D029	D039	ND
D010	ND	D020	D030	D040	ND
D011	ND	D021	D031	D041	ND
D012		D022	D032	D042	ND
D013		D023	D033	D043	ND

07/10/91

EIS ICIP DATABASE

Page No. 9

WASTE PAINT CHIPS

DESCRIPT PAINT CHIPS SCRAPED FROM FLOOR OF BIG SHOP

COMMENTS SAMPLE ANALYZED FOR ICIP METALS

D004	ND	D014	D024	D034
D005	1.0	D015	D025	D035
D006	0.18	D016	D026	D036
D007	4.1	D017	D027	D037
D008	3.2	D018	D028	D038
D009	ND	D019	D029	D039
D010	ND	D020	D030	D040
D011	ND	D021	D031	D041
D012		D022	D032	D042
D013		D023	D033	D043

WASTE WASTE PAINT

DESCRIPT WASTE PAINT CONTAINED IN 55 GALLON BARREL AT CFA BIG SHOP.

COMMENTS LAB STATED THEY COULD NOT QUANTIFY METALS IN THE SAMPLE MATRIX USING METHOD 1311 (ICLP) EXTRACTION SO THEY RAN A TOTAL DIGESTION. DUE TO MATRIX PROBLEMS, THE SAMPLE HAD TO BE DILUTED AND THE DETECTION LEVELS FOR SEHIV'S AND VOL'S EXCEED ICLP.

D004	ND	D014	D024	ND	D034	ND
D005	670	D015	D025	ND	D035	ND
D006	9.4	D016	D026	ND	D036	ND
D007	310	D017	D027	ND	D037	ND
D008	870	D018	D028	ND	D038	ND
D009	ND	D019	D029	11	D039	ND
D010	1.5	D020	D030	ND	D040	ND
D011	ND	D021	D031	ND	D041	ND
D012		D022	D032	ND	D042	ND
D013		D023	D033	ND	D043	ND

WASTE PAINT CHIPS

DESCRIPT PAINT CHIPS FROM FOUR MTR CATCH TANKS LOCATED AT TRA

COMMENTS SAMPLE OF PAINT CHIPS ANALYZED FOR LEAD.

D004		D014	D024	D034
D005		D015	D025	D035
D006		D016	D026	D036
D007		D017	D027	D037
D008	80	D018	D028	D038
D009		D019	D029	D039
D010		D020	D030	D040
D011		D021	D031	D041
D012		D022	D032	D042
D013		D023	D033	D043

07/10/91

ETS TCLP DATABASE

Page No. 10

WASTE USED HYDRAULIC OIL

DESCRIPT HYDRAULIC OIL FROM SPILL SOURCE WAS SAMPLED.

COMMENTS DRILL RIG BLEW A HYDRAULIC HOSE AND RELEASED FLUID TO THE GROUND. A SAMPLE OF HYDRAULIC OIL WAS ANALYZED TO DETERMINE IF A HAZARDOUS WASTE WAS RELEASED.

D004	ND	D014	D024	D034
D005	ND	D015	D025	D035
D006	ND	D016	D026	D036
D007	ND	D017	D027	D037
D008	ND	D018	D028	D038
D009	ND	D019	D029	D039
D010	ND	D020	D030	D040
D011	ND	D021	D031	D041
D012		D022	D032	D042
D013		D023	D033	D043

WASTE OLD GASOLINE

DESCRIPT RESIDUAL GASOLINE FROM SEVERAL OLD DRUMS WAS CONSOLIDATED INTO ONE DRUM AND SAMPLED. THE DRUMS WERE LOCATED AT IET TAN.

COMMENTS CONTENTS FROM OLD PETROLEUM CONTAINING DRUMS WERE CONSOLIDATED INTO TWO DRUMS AND SAMPLED. THE AGE OF THE GASOLINE IS UNKNOWN AT THIS TIME. THE DETECTION LEVEL FOR THE VOL'S AND SEMI-VOL'S IS ABOVE THE REGULATORY LEVELS.

D004	ND	D014	D024	D034	ND
D005	ND	D015	D025	D035	ND
D006	ND	D016	D026	D036	ND
D007	ND	D017	D027	D037	ND
D008	8.	D018	D028	D038	
D009	ND	D019	D029	D039	ND
D010	ND	D020	D030	D040	
D011	ND	D021	D031	D041	ND
D012		D022	D032	D042	ND
D013		D023	D033	D043	ND

WASTE OILY SLUDGE

DESCRIPT OILY SLUDGE RESULTING FROM THE CLEANUP OF STATIONARY EQUIPMENT SUCH AS COMPRESSORS, ETC.

COMMENTS CONTENTS FROM A NUMBER OF DRUMS CONTAINING OILY SLUDGE WERE CONSOLIDATED INTO ONE DRUM AND SAMPLED. THE MINIMUM DETECTION LEVELS FOR VOLATILE AND SEMI-VOL. ORGANICS ARE GREATER THAN THE REGULATORY LEVELS.

D004	ND	D014	D024	D034	ND
D005	ND	D015	D025	D035	ND
D006	ND	D016	D026	D036	ND
D007	ND	D017	D027	D037	ND
D008	12	D018	D028	D038	
D009	ND	D019	D029	D039	ND
D010	ND	D020	D030	D040	
D011	ND	D021	D031	D041	ND
D012		D022	D032	D042	ND
D013		D023	D033	D043	ND

MACHINE OIL - REGAL 68

WASTE MACHINE OIL (REGAL 68) WHICH IS USED IN BORING OPERATIONS AT TAN 667.

DESCRIPT OIL WAS COLLECTED FROM MACHINING OPERATIONS TO AID IN DETERMINING HOW TO DISPOSE OF RAGS CONTAMINATED WITH MACHINE OIL. THE OIL WAS ANALYZED FOR TOTAL METALS.

COMMENTS	
D004	0.1 D014 D024 D034
D005	ND D015 D025 D035
D006	ND D016 D026 D036
D007	ND D017 D027 D037
D008	8. D018 D028 D038
D009	ND D019 D029 D039
D010	ND D020 D030 D040
D011	ND D021 D031 D041
D012	ND D022 D032 D042
D013	D023 D033 D043

MACHINE OIL - REGAL 68

WASTE MACHINE OIL (REGAL 68) WHICH IS USED IN LATHE OPERATIONS AT TAN 667.

DESCRIPT OIL WAS COLLECTED FROM MACHINING OPERATIONS TO AID IN DETERMINING HOW TO DISPOSE OF RAGS CONTAMINATED WITH MACHINE OIL. A OIL WAS ANALYZED FOR TOTAL METALS.

COMMENTS	
D004	0.1 D014 D024 D034
D005	ND D015 D025 D035
D006	ND D016 D026 D036
D007	ND D017 D027 D037
D008	ND D018 D028 D038
D009	ND D019 D029 D039
D010	0.2 D020 D030 D040
D011	ND D021 D031 D041
D012	ND D022 D032 D042
D013	D023 D033 D043

WOOD FROM COOLING TOWER

WASTE WOOD COLLECTED FROM A COOLING TOWER CELL AT TRA.

DESCRIPT A SAMPLE OF THE TRA COOLING TOWER WOOD IS TO BE ANALYZED FOR TCLP CHROMIUM TO DETERMINE IF PREVIOUS USE OF CHROMATE CONTAINING WATER TREATMENT CHEMICALS LEFT

COMMENTS TCLP LEVELS OF CHROMIUM IN THE WOOD.

D004	D014 D024 D034
D005	D015 D025 D035
D006	D016 D026 D036
D007	1.62 D017 D027 D037
D008	D018 D028 D038
D009	D019 D029 D039
D010	D020 D030 D040
D011	D021 D031 D041
D012	D022 D032 D042
D013	D023 D033 D043

07/10/91

EIS ICIP DATABASE

Page No. 12

WASTE	DESCRIPTION	COMMENTS
	LIGHT BALLAST	
	LIGHT BALLAST WITHOUT THE WET CAPACITOR.	
	THIS ANALYSIS WAS PROVIDED BY ADVANCE TRANSFORMER COMPANY, WHO MANUFACTURES LIGHT BALLASTS. THE BALLAST WAS ANALYZED WITHOUT THE WET CAPACITOR.	
D004	ND	D014 ND D024 ND D034 ND
D005		D015 ND D025 ND D035 ND
D006	0.07	D016 ND D026 ND D036 ND
D007	0.40	D017 ND D027 ND D037 ND
D008	ND	D018 ND D028 ND D038 0.09
D009		D019 ND D029 ND D039 ND
D010	0.73	D020 ND D030 ND D040 ND
D011	ND	D021 ND D031 ND D041 ND
D012		D022 ND D032 ND D042 ND
D013		D023 ND D033 ND D043 ND

WASTE	DESCRIPTION	COMMENTS
	#5 FUEL OIL	
	A SAMPLE OF #5 FUEL OIL WAS ANALYZED.	
	THE DETECTION LEVELS FOR METALS, VOLATILE AND SEMI-VOLATILE ORGANICS ARE WELL BELOW THE REGULATORY LEVELS.	
D004	ND	D014 ND D024 0.086 D034 ND
D005	ND	D015 ND D025 0.086 D035 ND
D006	ND	D016 ND D026 ND D036 ND
D007	ND	D017 ND D027 ND D037 ND
D008	ND	D018 0.050 D028 ND D038 ND
D009	ND	D019 ND D029 ND D039 ND
D010	ND	D020 ND D030 ND D040 ND
D011	ND	D021 ND D031 ND D041 ND
D012	ND	D022 ND D032 ND D042 ND
D013	ND	D023 0.057 D033 ND D043 ND

WASTE	DESCRIPTION	COMMENTS
	PAINTS AND PAINT-RELATED WASTES	
	MIXTURE OF PAINT AND PAINT RELATED WASTES FROM TRA 653 PAINTSHOP.	
	THE HOLDING TIME WAS EXCEEDED FOR THE ZINC EXTRACTION PROCEDURE FOR VOLATILES. THE DETECTION LEVEL EXCEEDS THE REGULATORY LEVEL FOR SEMI-VOLS AND VOLATILES EXCEPT FOR D021,D026,D035,D037,D041.	
D004	ND	D014 ND D024 ND D034 ND
D005	0.216	D015 ND D025 390 D035 ND
D006	ND	D016 ND D026 17300 D036 ND
D007	0.074	D017 ND D027 ND D037 ND
D008	0.960	D018 ND D028 ND D038 ND
D009	ND	D019 ND D029 ND D039 50
D010	ND	D020 ND D030 ND D040 ND
D011	ND	D021 ND D031 ND D041 ND
D012	ND	D022 ND D032 ND D042 ND
D013	ND	D023 ND D033 ND D043 10est

07/10/91

WASTE	CADMIUM	
DESCRIPT	SAMPLE OF CADMIUM SHEETING.	
COMMENTS	A PIECE OF SHEET CADMIUM FROM TRA WAS CUT INTO SAMPLE SIZE PIECES AND SUBMITTED TO TWO LABS FOR ANALYSIS. ONE LAB SHOWED 960 mg/l, THE OTHER OBTAINED 1900 mg	
D004	960	D034
D005	D014	D024
D006	D015	D025
D007	D016	D026
D008	D017	D027
D009	D018	D028
D010	D019	D029
D011	D020	D030
D012	D021	D031
D013	D022	D032
	D023	D033

WASTE	OIL/SOLVENT	
DESCRIPT	ORGANIC OIL/SOLVENT STORED AT WERF TAA.	
COMMENTS	DETECTION LEVEL FOR SELENIUM EXCEEDS THE REGULATORY LEVEL.	
D004	ND	D024
D005	0.8	D025
D006	ND	D026
D007	ND	D027
D008	4.1	D028
D009	ND	D029
D010	ND	D030
D011	ND	D031
D012	D022	D032
D013	D023	D033
		D034
		D035
		D036
		D037
		D038
		D039
		D040
		D041
		D042
		D043

WASTE	MINERAL SPIRITS (PARTS CLEAN)	
DESCRIPT	SAFETY KLEEN 105 PARTS CLEANING SOLVENT AT CFA-621.	
COMMENTS	THE DETECTION LEVELS FOR ALL THE TCLP VOLATILES WITH THE EXCEPTION OF D021, D022, AND D035 EXCEED THE REGULATORY LEVELS SET BY RCRA. ALL THE SEMI-VOLATILE DETECTION LEVELS EXCEED THE REGULATORY LEVELS.	
D004	ND	D024
D005	ND	D025
D006	ND	D026
D007	0.07	D027
D008	1.8	D028
D009	0.002	D029
D010	ND	D030
D011	ND	D031
D012	ND	D032
D013	ND	D033
		D034
		D035
		D036
		D037
		D038
		D039
		D040
		D041
		D042
		D043

07/10/91

ETS ICIP DATABASE

Page No. 14

WASTE RAGS FROM PARTS CLEANING
 RAGS ASSOCIATED WITH PARTS CLEANING AT CFA-621. THE CLEANING SOLVENT USED ON THE PARTS IS SAFETY KLEEN 105.
 COMMENTS SAMPLE WAS TAKEN OF RAGS ASSOCIATED WITH THE PARTS CLEANING. VOLATILES WERE NOT ANALYZED FOR ON THIS RAG SAMPLING.

D004	ND	D014	D024	D034	ND
D005	0.38	D015	D025	D035	
D006	ND	D016	D026	D036	ND
D007	ND	D017	D027	D037	ND
D008	ND	D018	D028	D038	
D009	ND	D019	D029	D039	
D010	ND	D020	D030	D040	
D011	ND	D021	D031	D041	ND
D012		D022	D032	D042	ND
D013		D023	D033	D043	

WASTE HYDRAULIC OIL CONTAIN. SOIL
 SOIL RESULTING FROM CLEANUP OF HYDRAULIC OIL SPILL.
 COMMENTS SOIL CLEANED UP AFTER HYDRAULIC OIL SPILL WAS SAMPLED.

D004	ND	D014	D024	D034	
D005	0.73	D015	D025	D035	ND
D006	ND	D016	D026	D036	
D007	0.03	D017	D027	D037	
D008	0.79	D018	D028	D038	
D009	ND	D019	D029	D039	ND
D010	ND	D020	D030	D040	ND
D011	ND	D021	D031	D041	
D012	ND	D022	D032	D042	
D013		D023	D033	D043	ND

WASTE HYDRAULIC OIL

HYDRAULIC OIL FROM A CRANE LOCATED AT TAN WAS SAMPLED.

AFTER A HYDRAULIC HOSE ON A CRANE AT TAN FAILED, THE HYDRAULIC OIL WAS SAMPLED FOR METALS TO AID IN DISPOSING OF THE CONTAMINATED SOIL. THE OIL WAS ALSO TESTED FOR PCB'S. THE PCB'S WERE BELOW THE DETECTION LEVEL OF 4 mg/Kg.

D004	ND	D014	D024	D034	
D005	0.01	D015	D025	D035	
D006	ND	D016	D026	D036	
D007	ND	D017	D027	D037	
D008	ND	D018	D028	D038	
D009	ND	D019	D029	D039	
D010	ND	D020	D030	D040	
D011	ND	D021	D031	D041	
D012		D022	D032	D042	
D013		D023	D033	D043	

WASTE	HYDRAULIC OIL CONTAM. SOIL	
DESCRIPT	SOIL RESULTING FROM CLEANUP OF HYDRAULIC OIL SPILL.	
COMMENTS	E.P. TOXICITY WAS RUN ON THE SOIL WHICH WAS CONTAMINATED WITH HYDRAULIC OIL FROM A COMPRESSOR DURING DRILLING OPERATIONS NEAR THE BOREHOLE TAN 10A. PCB'S ALSO ANALYZED FOR AND NOT DETECTED IN THE SOIL SAMPLES.	
D004	ND	D034
D005	1.09	D035
D006	0.004	D036
D007	ND	D037
D008	ND	D038
D009	ND	D039
D010	ND	D040
D011	ND	D041
D012	ND	D042
D013	ND	D043

WASTE	HYDRAULIC OIL	
DESCRIPT	HYDRAULIC OIL USED IN DRILL RIG AT CFA LANDFILL II.	
COMMENTS	SAMPLE OF HYDRAULIC OIL WAS TAKEN FROM A DRILL RIG LOCATED NEAR CFA LANDFILL II. THIS ANALYSIS WAS PERFORMED TO ASSIST IN EVALUATING HOW TO DISPOSE OF SOIL CONTAMINATED WITH HYDRAULIC OIL FROM THE DRILL RIG.	
D004	ND	D034
D005	0.19	D035
D006	1.64	D036
D007	ND	D037
D008	ND	D038
D009	ND	D039
D010	ND	D040
D011	ND	D041
D012	ND	D042
D013	ND	D043

WASTE	CUTTING OIL (WATER SOLUBLE)	
DESCRIPT	WATER SOLUBLE CUTTING OIL USED AT TAN 653.	
COMMENTS	DUE TO SAMPLE MATRIX, THE SAMPLE REQUIRED AN ANALYTICAL DILUTION. AS A RESULT, THE DETECTION LIMITS FOR D030, D032, AND D043 EXCEED THE ICPL REGULATORY LEVEL.	
D004	ND	D034
D005	1.5	D035
D006	ND	D036
D007	ND	D037
D008	1.4	D038
D009	ND	D039
D010	ND	D040
D011	ND	D041
D012	ND	D042
D013	ND	D043

WASTE	DESCRIPTION	COMMENTS
D004	FILTER ON FLUOR. TUBE CRUSHER	
D005	USED CHARCOAL FILTER FROM A FLUORESCENT LIGHT TUBE CRUSHER.	
D006	A USED CHARCOAL FILTER FROM A FLUORESCENT TUBE CRUSHER AT TRA WAS ANALYZED FOR TCLP MERCURY. THE DETECTION LEVEL FOR THE ANALYSIS WAS 0.001 mg/l.	
D007		
D008		
D009		
D010		
D011		
D012		
D013		

WASTE	DESCRIPTION	COMMENTS
D004	SANDBLAST GRIT	
D005	SANDBLAST GRIT FROM CFA-623.	
D006	SANDBLAST GRIT WHICH HAD BEEN SWEPT FROM THE FLOOR AND STORED IN A DRUM AT CFA-623 WAS ANALYZED. THE SANDBLASTING HAD BEEN PERFORMED PRIMARILY ON BUS WHEELS.	
D007		
D008		
D009		
D010		
D011		
D012		
D013		

WASTE	DESCRIPTION	COMMENTS
D004	PAINT BOOTH FILTERS	
D005	FILTERS FROM PAINT BOOTH AT CFA-623.	
D006	FILTERS FROM CFA-623 PAINT SHOP PAINT BOOTH WERE ANALYZED FOR TCLP METALS. THE FILTERS HAD BEEN IN SERVICE FOR APPROXIMATELY 9 MONTHS AND PAINTS USED IN THE BO	
D007	INCLUDE NUMEROUS COLORS OF ENAMELS AND EPOXIES.	
D008		
D009		
D010		
D011		
D012		
D013		

I. INTRODUCTION

A recent Value Engineering Seminar was held to develop strategies for the disposal of used process HEPA filters. These filters are used to remove particulates from an off-gas air stream and become heavily contaminated with radioactive particulates. HEPA filters used to filter NWCF and FDP dissolver off-gases may also contain significant amounts of cadmium and/or mercury. A nitric acid leach process was developed to remove the radioactive and chemically toxic constituents from the filter so that they would meet land fill disposal requirements. The leaching process was performed on a small number of filters and has been proven to reduce the concentration of radioactive elements to below allowable low-level waste limits and cadmium to below the EPA's TCLP limit for land fill disposal. However, 50% of the filters still exceeded the EPA's TCLP limit for mercury of 0.2 parts per million after leaching.

During the Value Engineering Seminar, much time was spent on debating ways of treating mercury. The debate focused on amalgamation, the EPA's preferred treatment for mercury. In order to amalgamate mercury that has been deposited on HEPA filters, it would first have to be removed from the media. This could be done by either a dissolution (the most effective process) or volatilization process. Once in the liquid or gas phase, the mercury could then be amalgamated provided that other conditions were compatible with the amalgamation process.

All metals, except for a few transition elements, will dissolve in mercury to form alloys called amalgams (Ref. 1). Mercury does not have to start out in its elemental state to form an amalgam because it is easily reduced by most metals to its elemental form (an equivalent amount of the other metal is oxidized). Amalgamation is a highly efficient way of removing mercury from a dilute waste water stream and constitutes a suitable treatment for such

streams because the amalgam formed is a stable alloy that is essentially non-toxic (Ref. 2). Chemically stated, the amalgam is formed by the following reaction,

where M is the amalgamating metal. The mercury and metal atoms in the $Hg(M)_x$ alloy are neutral species (not ions) and the molar ratio of the metal atom to the mercury atom depends on the specific metal.

II. DISCUSSION

At the ICPP, mercury (in the form of mercuric nitrate) is used to catalyze nitric acid dissolutions of aluminum fuel. Without the mercury, aluminum dissolves very slowly in nitric acid because it is passivated by an oxide layer. Mercury ion acts as a catalyst because it is reduced and surface-amalgamates the aluminum and prevents passivation. Since aluminum is soluble in mercury, a short-lived amalgam is formed (Ref. 3). The resulting amalgam is quickly dissolved in the nitric acid and the nitrate salts of both elements are formed. The mercuric ion continuously recycles through the catalytic amalgamation/dissolution cycle until either all the acid and/or aluminum is consumed. The chemical reactions for this process are:

Since mercury amalgams are soluble in nitric acid, it is highly unlikely that they would exist in most of the waste streams at the ICPP. Reaction 3 from above would occur with any of the preferred metals listed by EPA for amalgamation (silver, zinc, and aluminum). Amalgamation might work if the waste stream was neutralized prior to forming the amalgam. If mercury were to be removed by amalgamation, the waste streams would first have to be

Attachment
T. H. Waite
Page 3
KNB-08-91
September 9, 1991

3396 → 7

neutralized to a pH of 6 or 7 prior to being treated. Neutralizing waste presents four problems: 1) hydroxide salts are incompatible with the waste processing techniques (calcination), 2) neutralization causes the precipitation of most of the radionuclides, 3) the resulting amalgam waste form will be heavily contaminated with radioactivity, and 4) neutralization will increase both the volume and solids content of the radioactive waste stream which violates waste minimization/reduction guidelines.

*increasing volume
neutralization
gas or liquid*

Elemental mercury is also soluble in nitric acid (Eq. 4) so it doesn't normally exist in the liquid ICPP waste streams.

A fraction of the mercury is deposited on the HEPA filters when the waste is calcined. Some of the reactions that mercury might undergo in the 500°C calciner include:

where: $X = Cl, Br, I$

The elemental mercury and halide salts are volatile. Most of the volatile mercury will be scrubbed out by the nitric acid scrub solution. Mercury from the scrub solution will contaminate the HEPA filter because the scrub is actually aspirated onto the media due to the large air velocity in the off-gas system. But some mercury will escape the scrub and proceed on towards the HEPA filters. A portion of the elemental mercury that gets by the off-gas scrub system is most likely to be converted to particulate mercuric oxide or

scrub system is most likely to be converted to particulate mercuric oxide or mercuric nitrate by NO_x in the hot air stream before it gets to the filters.

A very small fraction of the mercury is retained in the calcine. During the calcination process, a fine dust is generated. This fine calcine dust is blown into the off-gas system where most of it is recovered in the nitric acid off-gas scrubbing solution. However, some of these fine particulates survive the scrubbing system and are deposited on the HEPA filters. It is estimated that a total of about 300 grams of fines are trapped in each HEPA filter by the time that it is ready to be replaced.

Therefore, mercury can be deposited on the HEPA filter as mercuric oxide or mercuric nitrate by three mechanisms: 1) aspiration of the scrub solution, 2) conversion from a volatile species by either the acidic scrub solution or the oxidizing air stream and 3) to a lesser extent, direct deposition on the media with calcine fines.

Mercury is currently being removed from the HEPA filter by leaching it with 4-6 molar nitric acid at 60°C . This process dissolves the mercury from the media and brings it back into a solution that is somewhat similar in concentration to that of the original waste except that the leachate contains a higher concentration of both cadmium and mercury.

An alternative way to remove mercury from the filters would be to directly volatilize it from the filters by heating them. This reaction has been shown in Equation 7.

Mercuric oxide decomposes at temperatures greater than 400°C (Ref. 4). To volatilize the mercury from the HEPA filter at a reasonable rate, the media would have to be heated to at least 500°C . Temperatures in this range would decompose both the organic binder in the media and the silicone adhesive that

is used to bind the media to the filter housing. This might create a fire hazard for process(s) based on direct volatilization (Ref. 5).

Since mercury is the most troublesome element with regards to the disposal of used HEPA filters, reducing the amount volatilized in the calciner would alleviate future problems. Herbst (Ref. 6) reports that mercury is repeatedly recycled between the nitric acid off-gas scrub solution and the calciner bed. Acid scrub recycle typically accounts for more than 90% of the mercury being introduced into the calciner under steady state operating conditions (Ref. 6). Therefore, if mercury were removed from the scrub before it was recycled back in the calciner, the steady state mercury concentration in the calciner would be reduced by a factor of 10 and so would the amount of mercury volatilized into the off-gas system.

Duane Siemer has recently described an electrochemical process for recovering mercury from the calciner scrub solution (Ref. 7). If implemented, this system could: 1) reduce the amount of mercury being volatilized into the off-gas system which would, in turn, alleviate future problems with used HEPA filters, and 2) provide a means for recycling mercury for beneficial use in the plant. This and other environmentally sound practices should be evaluated.

III. CONCLUSIONS

Mercury generally exists at the ICPP in strongly oxidizing acidic waste streams. If this mercury were to be removed by amalgamation, the waste streams would first have to be neutralized to a pH of 6 or 7 prior to being treated. Neutralizing ICPP high-level waste presents four problems: 1) hydroxide salts are incompatible with calcination, 2) radionuclide precipitations (Ref. 8), 3) heavily radioactive amalgam, and 4) violation of waste minimization/reduction guidelines.

Attachment
T. H. Waite
Page 6
KNB-08-91
September 9, 1991

If the mercury were removed from the media by direct volatilization, as opposed to dissolution, the gas might be compatible with an amalgamation process. However, volatilization is incompatible with other components of the HEPA filter and might cause a fire hazard.

Providing that the mercury from the scrub solution is removed, the best treatment for mercury would be to leach it from the media and re-introduce it back into the calciner.

IV. REFERENCES

1. H. H. Sisler, et al., General Chemistry: A Systematic Approach, page 782, Second Edition, The MacMillan Company, New York, New York, 1959.
2. J. C. Bailer, Jr., et al., Chemistry, page 730, Academic Press, Inc., 111 5th Ave., New York, New York, 1978.
3. G. K. Cederberg, et al., ICPP Safety Document, WIN-107, page 2, Section 5.1, "Aluminum Dissolution", July, 1985.
4. Handbook of Chemistry and Physics, page B-120, 62nd Edition, CRC Press 1981-82.
5. K. N. Brewer, Lab Notebook LN-362, page 63, January 1, 1990.
6. A. K. Herbst, "Mercury Concentration in the Effluent Streams of the Idaho Chemical Processing Plant", ACI-378, May 1979.
7. D.D.Siemer, letter DDS-23-91 to A.P. Hoskins, "Explanation of and Cure for the Mercury Waste Problem at the ICPP", dated July 29, 1991 (additional information on this process is found in a patent discloser entitled "Electrochemical Hg Removal from ICPP Waste").
8. Cotton and Wilkinson, Advanced Inorganic Chemistry, page 965, Fifth Edition, John Wiley and Sons, New York, 1988.

**DATE
FILMED**

8/12/93

END