A Waterjet Mining Machine for Use in Room and Pillar Mining Operations

**in fulfillment of
Contract DOE DE FG01 87CE 15307**

**for the
U.S. Department of Energy
1000 Independence Avenue, S.W.
Washington, D.C. 20585**

**by
Dr. David A. Summers
University of Missouri-Rolla
High Pressure Waterjet Laboratory
Rolla, MO. 65401**

June, 1990

MASTER

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

TABLE OF CONTENTS

CHAPTER I. BACKGROUND.....	1
Introduction.....	1
Historical Background	1
Proposed RAPIERS Method of Operation.....	4
Jet Cutting Parameters	7
CHAPTER II. EQUIPMENT CONSTRUCTION.....	14
Introduction.....	14
Gathering Arm Loader Apron.....	15
Shield Support	20
Computer Operated Slot Cutting Arm	24
Controls	27
Hydraulic Circuitry and System Hardware	34
CHAPTER III. EQUIPMENT CONSTRUCTION	37
Introduction.....	37
Prototype Evaluation	38
Future Plans	39
Acknowledgements	40
REFERENCES	42

Abstract

A new mining machine is constructed for use in room and pillar mining operations. This machine uses the action of computer controlled, centrally located high pressure cutting lances to cut deep slots in a coal face. These slots stress relieve the coal ahead of the machine and outline blocks of coal. The movement forward of the machine then wedges up the lower block of coal.

This wedging action is assisted by the gathering arms of the loader section of the machine, and by underlying oscillating waterjets which create a slot ahead of the loading wedge as it advances. Finally the top section of coal is brought down by the sequential advance of wedge faced roof support members, again assisted by the waterjet action from the central cutting arms.

The machine is designed to overcome major disadvantages of existing room and pillar mining machines in regard to a reduction in respirable dust, the creation of an immediate roof support, and an increase in product size, with concomitant reduction in cleaning costs.

CHAPTER I. BACKGROUND

Introduction

In 1987 the University of Missouri Rolla undertook the design and construction of a room and pillar coal mining machine. This final report documents the original concept which was proposed and the modifications made as the design evolved during the construction of the first prototype. The report concludes with discussion of the projected future plans to develop this equipment.

Historical Background

Coal has been a major fuel source for the United States for the whole of the 20th Century. Current declining production of domestic oil suggests that it will retain this role well into the 21st Century. Production of coal is largely from underground operations in the Eastern and Western United States. The majority of the coal excavated from underground workings is extracted by continuous mining machines (Figure 1).

Fig. 1 of
SME 1992
Paper
on Optical
Disk
"Reports/
General-
1991"

Figure 1. Continuous Mining Machine.

Figure 1. Continuous Mining Machine

These miners are fitted with a large rotating drum into which high strength steel picks are arranged in one of a variety of patterns. As the drum rotates against the coal face, these picks penetrate into the coal, grinding it from the solid. Under the drum

the continuous miner has a wedge shaped apron upon which two gathering arms are mounted. These arms push the fallen coal towards the center of the machine where a conveyor is located. As the coal passes onto the conveyor it is carried through the machine to a boom projecting out of the back of the continuous miner. The most common method of moving the coal from this point is to use shuttle cars. These are small, generally electric powered trucks which collect the coal from the back of the continuous miner and carry it to the face end of a continuous belt conveyor. This conveyor is then used to carry the coal away from the working panel on its way out of the mine.

Although productivity from a continuous miner can be quite high on an instantaneous basis, overall production rates on a daily basis can be disappointingly low. This is because of two major requirements which must be implemented during the cycle. As the mining machine grinds the coal from the surface, the cutting action of the individual picks generate considerable volumes of very fine coal dust. This dust easily becomes airborne and provides a respirable dust hazard for the continuous miner operator and any other workers in the vicinity. To overcome this environmental problem it is necessary to keep a clean air supply feed close to the working face. This is often done by moving a length of ventilation line towards the face after every 10 feet of machine advance. This will obviously slow the production rate of the machine since it is generally not operating when this is done.

The second problem creates a significantly greater cutback in production. The roof over most coal seams is made up of rock which can be quite weak and may itself comprise a number of very thin layers of material. In order to hold the roof in place and prevent its collapse on the mining crew, artificial supports must be used. Over the years, the most popular of these has become what is known as a roof bolting system. In essence, this requires that holes be drilled into the roof typically upward over a distance of approximately 7 feet. The holes are spaced on 4 to 5 foot intervals apart both across and along the tunnel. Once each hole has been drilled, a metal rod, known as a roof bolt, is installed in the hole. These are attached to the rock in one of several ways, each of which serves to hold the rock layers together and to prevent their collapsing into the working space.

The machine which drills the holes and places the bolts in them is itself quite large. Thus, in order to bolt the area of roof which has been exposed by the operation of the continuous miner, that machine must first be withdrawn out of the tunnel. In a normal mining plan a machine will work in several different tunnels in sequence to give time

for the roof bolters to support the roof. At the same time, this pattern of extraction is planned so that the continuous miner will drive a series of normally perpendicular tunnels. As these intersect they will outline, between them, a series of coal pillars which will be left standing in the seam to provide stronger support for the more permanent stability of the excavation.

This need to provide an immediate support of the roof, before the continuous miner operator is required to work under it, limits the advance of the machine to a distance of perhaps only 20 feet in any one tunnel at one time. The resulting intermittent cutting action of the machine significantly reduces the overall daily production which can be obtained from the working section.

One additional problem of increasingly significant economic importance has developed with the use of the continuous miner. The grinding action of the drum and picks against the coal face produces very small coal. As an approximate rule more than 80% of the coal produced will be less than 1 inch in size. The cost for cleaning this material to remove dirt and other impurities can be as high as \$6.50/ton. Cleaning these impurities from the coal is becoming mandatory before it can be sold to many current buyers, particularly for power generation.

One can therefore summarize some of the working disadvantages of the common continuous miner as being:

- that it produces large quantities of respirable dust,
- that mining must be stopped to provide support of the roof,
- that too much small coal is produced which is expensive to clean.

As a result, it is appropriate to look at a different excavation philosophy which might overcome these disadvantages.

The University of Missouri-Rolla has worked with the Jet Propulsion Laboratory of Pasadena, CA to develop a mining machine which would overcome some of these disadvantages (Reference 1). The design which has been developed was based upon the successful testing of a longwall mining machine which used high pressure waterjets as a cutting tool to replace the impact of the hard metal picks. Trials of the longwall unit had shown that the waterjets mine coal without generating respirable dust and in significant quantities and that the coal produced by the combined waterjets and mechanical system was significantly larger in size (Reference 2). Because large coal

After considerable evaluation the design of a continuous miner version of the hydrominer, as this earlier machine was known, has been developed. This design sought to include the advantages of the longwall machine adapted to the type of room and pillar mining most common in the United States. In order to provide a simple reference to the machine during the course of this report, an acronym has been developed for the machine. This is **RAPIERS** (standing for **Room And Pillar In-seam Excavator and Roof Supporter).**

The machine which has been developed has been designed to produce more coal with less energy and with less environmental and safety problems than existing equipment. To trace the development of the machine, the original method of excavation proposed will be initially described. Following this the modifications required as the machine was constructed will be reviewed.

A schematic diagram of a B Jet Cutting machine. The diagram shows a cross-section of the machine with various components labeled. On the right, a thick black line represents the cutting jet, labeled "B Jet Cutting". The jet is directed towards a workpiece. The workpiece is shown with a circular hole. The machine structure includes a base, a vertical support, and a horizontal arm. The jet is shown cutting through the workpiece, with a small gap between the jet and the workpiece.

Page 4

Once the initial central cut has been taken, two vertical relieving cuts are made at the edges of the tunnel. This isolates the block of coal which is to be mined. The bottom wedge at the front of RAPIERS is then moved forward. As it moves forward into the coal, an oscillating waterjet nozzle traverses underneath the leading edge cutting a slot ahead of the blade. Two jets issue from this nozzle, and can cut a slot up to three feet deep ahead of the wedge, two inches high. The interaction of the wedge and the waterjet together enhance the performance of both since the uplifting force generated by the wedge is concentrated at the back of the slot which the waterjet is cutting. This opens any cracks which might be present and puts the coal in tension making it easier for the waterjet to cut the coal.

As the wedge moves forward it will break the overlying coal upwards, fragmenting it into pieces, and at the same time moving it back up the wedge. In order to help this movement and to load the coal mined from the face, the machine uses the same principle as is currently used in the conventional continuous coal mining machines, namely two rotating gathering arms, located one on either side of the top of the wedge. These arms rotate and move the coal from in front of the machine towards the center of the apron, where a small transfer conveyor is located. This conveyor carries the coal up the apron and back through the machine to a protruding boom where the coal can be loaded onto a shuttle car. By using an already existing gathering arm it is possible to eliminate the requirement for developing a new method of loading the coal from the coal face. Further, the wedge shape of the existing continuous miner aprons can be used to help break the coal from the solid.

Once the bottom wedge has been pushed forward into the coal to its full extent, a block of coal cut to the width of the tunnel, measuring half the seam in height and some 2-3 feet deep will have been extracted. At this time, a second wedge and oscillating waterjet will be activated at the top of the seam. This will similarly push forward, breaking down the top half of the coal and causing it to fall onto the apron which is located underneath it. The gathering arms will then move this upper half of the coal back to the transfer conveyor. After all the coal has been mined in the block ahead of the machine, then the main body of the machine will be moved forward ready to restart the process. (This sequence of events is illustrated in Figure 3).

Figure 3. Schematic representation of operation of RAPIERS.

In order to provide a strong base against which the wedges can be thrust forward, it is necessary to create a strong, yet moveable support. This is achieved by extending two pistons, from cylinders located on either side of the apron. These pistons brace between the roof and floor of the mine, through steel plates. Similar devices are commonly used in mining to provide temporary roof support along the mining face in the method known as longwall mining, and are referred to as chocks or shields.

The large force required to hold the roof up also provides a considerable frictional force, which is sufficient to hold the main body of the machine in place, while the wedges are advancing forward. Once the machine has extracted both the upper and lower sections of the coal seam, then the piston on one of the shields is lowered, and it is advanced, by reversing the push ram used earlier to advance the lower wedge and loading apron. After this shield is fully forward, then it will be raised into position, so as to provide a brace for the apron, while the second shield is lowered and advanced. When the complete machine has been moved forward then roof bolts will be installed by a machine operating behind the coal excavator. These hold the tunnel open during the remainder of the mining process.

The relatively small size of the machine, and the immediate support that is provided to the machine operator by the hydraulic cylinders make it easier to use a roofbolter behind the machine. At the same time the machine operator is always working under a supported roof, as provided by the hydraulic cylinders on the machine.

Jet Cutting Parameters

Coal is a rare rock in that it contains a large number of flaws which normally lie in perpendicular planes. The horizontal planes are usually referred to as the bedding planes of the seam, while the vertical planes are known as the cleat of the coal. These weakness planes provide an ideal avenue for waterjets to exploit the coal and excavate it.

The simple way to describe the cutting of coal by a high pressure waterjet is to examine the sequence of events as a jet impacts the surface. In the initial instants of impact the first water to arrive on the surface will penetrate into the surface cracks, filling them with fluid. The next segment of the water jet to arrive will then pressurize these fluid wedges in the coal, causing them to extend the cracks to the point that they coalesce, removing material from the solid. For the greatest effect this requires that there

is a pressure differential between adjacent cracks, so that the block of coal which is surrounded by fluid has a relative force on it, making it move out of the solid.

The method of coal removal requires that the most effective use be made of the flaws already in the coal. This is the same principal of material removal which is effective in cutting many rocks. Early experiments in the waterjet removal of rock were directed at finding the best way of using the jet horsepower to remove the greatest volume of rock, as fast as possible.

Jet horsepower is derived from two main sources, the volume flow of the water, and the pressure at which it is driven. Experiments have shown that the greater the pressure that the water is driven at, so the deeper the slot that is cut. However, the most effective use of a waterjet in cutting coal for this application is not restricted to the depth of the slot achieved. Nor is higher pressure alone a necessarily advantageous option.

As waterjet pressures increase, so the size of the equipment required to generate and deliver the water must increase. This is needed to safely contain the pressure and it makes the resulting machine heavier, more cumbersome, and more expensive. Greater demands on better water quality become necessary, and, for equivalent horsepower, the volume of water available is reduced. This has several disadvantages. These come about because, as the water pressure increases, so the velocity of the water coming from the nozzle also goes up. This means that, with the reduced volume of water travelling faster, the cross-sectional area of the jet must be reduced even further.

The faster the jet travels as it moves through the air from the nozzle to the coal face, then the greater the difference in speed between it and the air. This increases the rate at which the outer edges of the jet are disrupted. If at the same time the jet diameter is smaller, then the amount of jet available becomes less. The result is that the distance over which the jet is able to cut into the coal becomes shorter.

The second problem relates to the width of the slot which the jet will cut. The narrower the jet is, then the smaller the width of cut that will be made. As a simple approximation the jet will cut a slot about twice the width of the impacting jet. While this is not a great problem in surface cutting or in applications where the jets cut materials in factories, it is very significant in underground applications. This is because all rock underground is under pressure. Most of this pressure comes from the weight of the rock lying on top of the tunnel. Pressure can also be present as a result of nearly

other tunnels, and geological movements which might have occurred since the rock was deposited. These pressures can be quite high, and result in the rock becoming compressed by the load. When a waterjet or other mining machine now cuts this rock the first result is that the load on that coal is removed. This is a useful ability of the RAPIERS since it makes the coal easier to break out and load if it is under no pressure from the surrounding rock. However, when the slot is made, the removal of pressure from the coal above and below the slot allows them to expand. If the slot cut by the waterjet is very narrow, then the expansion may be sufficient that the slot is completely closed. In which case pressure will again build up in the coal and it will become as hard to break out and load as before.

The third problem is along the same lines as the first two, and relates to the mechanism of coal removal. The jet penetrates by getting into the flaws in the coal surface. The higher the pressure and the smaller the diameter of the jet, then the smaller the number of flaws that will be found under the jet impact area at one time. Thus the cutting operation will be less efficient.

These considerations had been evaluated in the development of the original longwall waterjet mining machine (the HYDROMINER). Experiments with the development of that machine showed that while cutting depth was increased, as jet pressure was increased (Figure 4) the specific energy of cutting did not improve. This is the amount of energy required to remove a unit volume of coal from the surface.

Figure 4. Relationship between volume and energy of removal and jet pressure (after Reference 3).

If however, additional horsepower was given to the water by increasing the flow volume, or the jet diameter, then (Figure 5), not only did the depth of the slot cut increase, but the volume of material increased faster, so that the specific energy of cutting dropped significantly.

Figure 5. Relationship between volume and energy of removal and jet diameter (after Reference 3).

Those experiments concluded, and subsequent machine testing verified, that the most effective cutting conditions occurred where the jets were at higher volume but lower pressure. Within that constraint there are additional bounds. The coal found underground is often surrounded by softer shales. These often provided the soil of the primeval forest from which the coal was formed. Subsequent pressure has turned this material into a shale. It is, however, very sensitive to the presence of a lot of water. A mining machine therefore cannot use vast quantities of water without the floor being destroyed, making mining more difficult, and reducing the stability of the excavation.

In order to reach a compromise on the quantities of water to be used, the Hydrominer standardized on the approximately 50 gpm of water used on most conventional mining machines as a means of suppressing the respirable dust generated by the typical conventional continuous miner. However, the Hydrominer was used in a longwall mining operation. In such an operation almost immediately after the coal is taken out the roof is allowed to collapse into the empty space. In conventional room and pillar mining, where RAPIERS will be used, this is not so. The tunnels made by the machine will continue to be used to carry coal away as the tunnel grows longer. Men, materials and machines may use any one tunnel for several weeks, and thus floor and stability con-

cerns are much more important. For this reason it is prudent to consider using a smaller volume flow than that used with the Hydrominer.

The machine design for the Hydrominer used four sets of dual-orifice nozzles at one time to cut out the coal ahead of the machine. That machine continuously moved. The RAPIERS instead is a machine with sequential operation. Instead of four nozzles therefore, the machine can be operated satisfactorily with only two in operation at one time. This reduces the water quantity required to approximately 22 gpm. When this is integrated with the performance data evaluated from Hydrominer, a jet pressure of 10,000 psi has been found to be satisfactory at this flow rate.

The choice of 10,000 psi is dictated by considerations which go beyond just the ability to cut the coal. As mentioned in the earlier discussion on the need and costs of cleaning coal, there is a considerable amount of dirt and other impurities in natural coal. This often takes the form of layers of other rock in the coal seam layer. These are usually harder than the coal, and the jets must be able to cut through them if the machine is to be a success. Tests in a surface mine of the Hydrominer prototype indicated that a 10,000 psi jet system would be able to do this at an effective rate for most of the rocks found in the coal.

A dual orifice design (Figure 6) was chosen in order to ensure that the slots cut would be wide enough to totally relieve the surrounding pressure and to leave a large enough gap for the cutting heads to enter the slot. This is important since the performance requirements for RAPIERS need a deep slot, projected as being about 18 inches deep.

Figure 6. Dual Orifice design (after Reference 4).

A single waterjet will not be able to cut this deep on a single pass, but the depth can be achieved using multiple passes of a dual orifice combination. The design chosen takes advantage of the structure of the coal. Because of the many bedding and cleat planes in coal it has relatively little strength in tension. Thus two jets, inclined slightly outwards, and traversed vertically, cut not only the coal immediately under the jets, but also will penetrate along the weakness planes in the intervening material and break it from the solid. On the next pass of the nozzle the jets will now not encounter coal

until they reach the back of the previous slot, as shown in Figure 7, and the process is repeated.

Figure 7. Jet passage through a slot cut by a dual orifice, showing the lack of wall contact.

This has the additional advantage over a single nozzle design that the jet effectiveness is not reduced by contact with the sides of the previously cut slot, until the jet hits the back of the previous cut. In this way it became relatively simple to cut a slot roughly two inches wide over the required depth of cut ahead of the machine. The result enables the cutting nozzle to establish a deep slot ahead of the machine, and in this way to break the cantilever carrying the surrounding ground stress. This moves the stress away from the coal to be excavated, making it easier to cut and to break out from the solid. Further, by minimizing the number of cuts which need to be made in the face, the majority of the coal will be removed in large blocks of coal with relatively little force being required.

The cutting action of these jets is sufficiently powerful that the slot can easily be established, however, the amount of force required on the machine to hold the cutting nozzles is still quite small. In contrast to the thousands of pounds required to hold a continuous miner head in position, not only to counter the thrust required but also to support its weight. The cutting forces from a dual orifice nozzle flowing 10 gpm at 10,000 psi can be approximated by the equation:

$$\text{Force} = 0.052 \cdot \text{Flow (gpm)} \sqrt{\text{Pressure (psi)}}$$

This gives a force of approximately 52 lb. The nozzle assembly on the lance weighs less than 10 lb. In consequence a much smaller, and thus lighter, more maneuverable and less expensive system can be developed.

With these parameters as the preliminary basis for the design of the machine, and working with equipment donated by two manufacturers of mining machines, it was now possible to design and assemble a first prototype of the equipment.

CHAPTER II. EQUIPMENT CONSTRUCTION

Introduction

The University of Missouri-Rolla was fortunate, at the beginning of this contract, to be receive donations of two used pieces of equipment from their manufacturers which could then be used as the basic components for RAPIERS. The first of these was the gathering arm loader from a Joy Continuous Miner. This comprised the front apron together with the gathering arms and the drive and channel for a central 30" wide scraper conveyor used to carry the coal away from the cutting drum (Figure 8).

Figure 8. The Gathering Arm and Apron of a continuous Miner

The second component which was donated was a longwall hydraulic roof support or shield (Figure 9). This comprised two large hydraulic cylinders connected together and fitted with a hydraulic pushing ram. The hydraulic cylinders push between floor and roof plates to support the overlying roof, while underneath it. At the same time large steel plates mounted at the back of the frame prevented rock from entering behind the machine.

The initial design for the RAPIERS system had conceived that two roof supports would be used, one on each side of the gathering arms. However, the machine is designed to cut only to the width of the loading apron—which, in this case, restricted the operational width to 110 inches. The use of a shield on each side of the conveyor would place the outer half of each shield out considerably beyond this width. A decision was therefore made to modify the equipment design. Fortunately, the shield obtained was largely symmetric. Thus, it would be possible to cut a single shield in half and mount one half on either side of the loading conveyor. This would allow the machine to fit within the required width.

Figure 9. Original Shield Support System

In the description of the assembly of the unit which follows, particular problems encountered in each stage of the operation will be described, together with their solution. Although this solution is simply described, it should be recognized that these were often the result of false starts and other proposed solutions which were found to be less effective in the final analysis.

Gathering Arm Loader Apron

The method of collecting coal produced by a conventional continuous miner is relatively simple and with little modification can be adopted for the RAPIERS System. In essence the mechanism, commonly known as a gathering arm loader, is made up of a loading ramp or apron, which is simply a sloped metal surface. On this surface, two hinged arms are constrained to sweep out a path which pushed the coal intercepted towards the center of the ramp. As the coal enters and moves up this central section of the ramp it falls onto a contained scraper conveyor section. The conveyor carries the coal out of the working area.

The gathering arm apron thus already has the wedge shape required for RAPIERS in order to break out the lower section of the coal seam after the initial slotting of the face has occurred. The loading wedge will be thrust forward during this part of the mining cycle so that its leading edge enters the slot cut in the bottom of the coal seam (Figure 3). The wedge will be pushed forward with sufficient force that the leading edge will elevate and break the overlying segment of coal into fragments which the gathering arms can then load out. During the development of the earlier Hydrominer, discussions were carried out with coal plow manufacturers in Germany (Reference 5).

A major aspect of those discussions was to determine, based on their extensive experience, the angle of the wedge which would give best loading conditions. The information obtained at that time, suggested that, at the speeds to be used with RAPIERS, the wedge angle required to break and elevate the coal was not a critical value. In other words provided that extreme values were not selected, variations in the angle between 30 and 60 degrees would have little effect on machine performance. This was an important preliminary finding and was an encouraging development. Because of the lack of importance of this angle, it could be increased at little cost. This would allow the existing apron to be simply modified to accept the waterjet cutting equipment required to cut the underlying slot of the coal seam.

Rather than modify the internal construction of the gathering arms, a separate wedge shaped framework 3" high on its leading edge, 10" high at its backward edge, and 4' 5" deep was constructed (Figure 10). This ran the full width of the loading apron. Once the cutting arm mechanism had been assembled and mounted in this frame, the loading apron could then be mounted on top and would thus provide the top housing for the slotting arm drive. The whole piece was bolted to the bottom of the gathering arm apron, so that it could be easily disassembled easily when necessary for repair.

Figure 10. Separate wedge shaped framework constructed to hold the lower cutting arm mechanism.

A hydraulic drive was chosen to move the cutting arm over the required slot width. This has the inherent advantage of being a relatively safe system for use in the possible dangerous environments at the working face of the coal mine. The bi-directional hydraulic motor drove a screw thread, in turn moving a platform to which the jet

cutting lances were mounted (Figure 11). Guidance for the nozzles is provided by a steel guide pipe.

Figure 11. Schematic Representation of lower arm drive mechanism

The maximum traverse speed of the nozzles was set at 8 inches/second. This provided a sweep speed of 7 seconds a pass, or a ~~maximum oscillation speed of 8.5~~ passes a minute. At a slot cutting speed of ~~more than 2 inches/pass, as determined by field~~ experience during the first trials of the Hydrominer, this would give an advance speed of 17 inches/minute. For an 18 inch step for each advance, this would give a time of roughly one minute for the lower wedge to advance. For a 36 inch "bite" the advance time would be some 2 minutes. It should be noted that this does not consider the beneficial action of having the wedge head applying tensile pressure to the root of the slot being extended by waterjet action. In trials of the Hydrominer the slot at the bottom of the coal could be kept effectively open ahead of the machine while it was advancing at 10 ft/minute. A similar machine in Germany achieved an advance rate of 60 ft/minute (Reference 6). The potential performance of this machine is thus already practically demonstrated to be significantly above that which is being predicted in this report.

It was decided to use two lances mounted on either side of the machine centerline to cut the underlying coal slot. This decision was based on the amount of time that

would be required to cut the slot in contrast with the desire for a machine which would be at least as competitive in production rate as existing equipment.

After considerable debate, it was decided to use dual orifice nozzles which would not rotate to produce the waterjets coming from the waterjet lances. These were chosen over self rotating nozzle assemblies because of the smaller space which they would require allowing them to fit close to the leading edge of the cutting slot. The nozzle design also gained from the previous work with Hydrominer. That experience had shown that the egress slot allowing the jets to flow out of the apron onto the coal also provided access for coal particles. By reducing the slot width to about 1/4 inch, and putting the two diverging jets adjacent rather than vertically above one another so that they could use the narrow slot this was avoided.

The method of drive for these lances is different from that which was used in the Hydrominer. In that earlier machine, the lances were oscillated over an arc by a hydraulic motor through a camshaft design. However, the arms had only to swing over a range of approximately 2 feet. Thus, the standoff distance of the arm from the coal did not increase significantly from the center to the extremities of the stroke. In the case of the RAPIERS machine each lance must sweep out a length of approximately 55". Were this to be done by oscillation, the standoff distance of the nozzles from the coal face at the extremities of the sweep, relative to that in the center, would have a significant effect on jet cutting performance. For this reason the slightly more complicated screw feed mechanism was adopted because it would provide a linear drive moving the nozzle pair along the inner face of the apron.

In order to simplify operation, electric limit switches at the ends of the lance path were used to reverse the motion (Figure 12). These switches feed into a directional flow control valve within the servo controlled hydraulic drive to the slotting motor.

Figure 12. Location of electrical limit switch on lower arm traverse.

The high pressure lances were built from sections of high pressure stainless steel tubing and were manifolded together at the back of the traverse platform to simplify the supply of high pressure water to the system through a single line from the high pressure pump (Figure 13).

Figure 13. Feed lines to the two lower cutting nozzles

When the apron had been acquired, no thought had been given to the power and prime mover that would be required for the operation of the gathering arms. In the machine for which this component was designed, this power comes through a drive linkage from the main machine motors. In this instance, all those motors which lie in the center of the continuous miner were not available. To replace them and to provide power for the gathering arms, a 15 hp electric motor and a replacement gearbox were mounted on a bearing plate and oriented to drive the transmission rods operating the gathering arms (Figures 14 & 15).

Figure 14. Electric Motor with Belt Drive to Gearbox

It was found necessary to completely rebuild this assembly in order to make it work effectively in this new configuration. The gearing was chosen to rotate the gathering arms at a speed of 12 rpm. The operation of this system required a considerable effort in cleaning and replacing worn and failed components in order to bring the equipment into working order.

Figure 15. Replacement gearbox and Drive to Gathering Arms

Shield Support

The roof support obtained had been initially constructed as a single unit. However, in its assembly almost all the components were duplicated on each side of the central axis of the support. The major exception to this was the main bearing plate which would be pressed up against the roof of the mine in order to hold it in place. This component was therefore removed from the frame and the remaining components separated into two halves. The roof beam was then cut in half using a low pressure (5,000 psi) high volume flow rate (22 gpm) abrasive laden waterjet using garnet as the abrasive (Figure 16). The system gave an acceptable cut through the steel with the exception of 4 rib locations which were subsequently cut with a flame torch. This was only done because of some difficulty in orienting the cutting nozzle to access the remaining metal.

Figure 16. Edge Cut along the Shield Roof with a DIAjet System.

Each roof section was then remounted on the appropriate chock half which was in turn placed on either side of the gathering apron (Figures 17 & 18). In order to connect the chock to the apron, a double acting hydraulic cylinder was attached to the base plate of each chock half (Figure 19). The piston ram from the cylinder was connected through a hinge point mounted on the back of the apron. In this way, either the apron could be pushed forward under the thrust from both rams on the roof supports or alternately, one of the supports could be lowered from the roof and pulled forward to the apron position in sequence.

Figure 17. Side View of the RAPIERS machine

Figure 18. Front View of the RAPIERS machine.

Figure 19. Hydraulic Ram for Apron and Shield Movement

Hydraulic controls to operate the 4 cylinders (the two pushing cylinders and the two roof support cylinders) were through servo control valves mounted on the machine (Figures 20 & 21) and were themselves controlled by the software in the MACSYM computer (Appendix I).

Figure 20 Initial Assembly of the bank of Servo Control Valves used to control RAPIERS

Figure 21. Schematic of the Hydraulic Control Circuitry

Computer Operated Slot Cutting Arm

The first cut in the coal face is made to provide stress relief to the coal ahead of the machine (Figure 3). At the same time, the slot must be wide enough to allow the coal which will then be wedged out a free space into which to move during the fragmentation process. For these purposes, the original machine was conceived so that a water-jet would move to cut a slot approximately 18" deep ahead of the machine in the form of an "H" (Figure 22). Such a shape would provide a central horizontal cut which would give a free surface for the lower wedge which it defined to move into. The two vertical cuts would be at the edge of the opening and would free the coal in the RAPIERS path from the surrounding solid making it easier to extract.

Figure 22. Original Pattern of Slots to be cut in the Coal Face.

The original conception of the cutting arm to cut this first slot was that a single lance could be used (Figure 23). A practical evaluation of the limited time available to make the cut and the logistics of the cutting process suggested that a two-lance system would be more effective.

Figure 23. Design Concept proposed by JPL Report

A rigid and stable mounting location was required as a base plate for the slotting arm drive unit. Examination of the possible mounting surfaces in the assembled unit indicated only a limited set of options. The most practical point was just outside the frame of the scraper conveyor where this crossed the upper surface of the gathering arm.(Figure 24). This location had many benefits and would allow the cutting arms to be retracted out of the way during the removal of the coal. The problem with this location was that it made it very difficult to reach the outer edges of the coal seam and even more difficult to direct the lance to cut a slot along this perimeter. For this reason, the pattern of relief slots to be cut was changed.

Figure 24. Location of the Central Cutting Arm Assembly

Instead of cutting the slot horizontally and then along the edges of the proposed tunnel, the design was modified to cut the vertical slot in the center of the machine ahead of the face. This would still provide the stress relief and access for unloading and fragmenting the main coal mass ahead of the machine. It would also provide a more rapid method of cutting the slot. The experiments which had previously been carried out with Hydrominer indicated that providing the slot was wide enough and of sufficient depth this would be sufficient to allow the coal to be removed from the solid by the wedging action of the apron as it moved forward.

Controls

The robotic cutting arm had, by now, been designed to make all the cuts in the coal face except the bottom slot.

a) Structural considerations

The dimensions of the coal face which this prototype machine would excavate were considered to be an average of 5.5 feet in height and 9 feet 2 inches in width. In reality the height of the coal is likely to vary as the machine advances, and the flexibility of the design will allow for some considerable variation in this height. The nozzle head should be able to reach any point along the face. One option to get this purpose is to adopt the scheme proposed by Jet Propulsion Laboratory of California Institute of Technology in the report on the design of hydro-mechanical system for underground coal mining. In that report the robotic cutting arm was rail-mounted and able to move horizontally. The rail was supported hydraulically by cylinders placed at each end, and was designed to move up and down and skew at an angle as shown in Figure 23.

While this idea was a good starting point it required that both the supporting structure and the driving system would be quite complicated. When this complexity was considered in light of the harsh conditions which exist in the vicinity of the underground working face, it was decided it would create too many problems. Instead it was decided to modify the design following the principles of simplicity and rigidity.

Figure 25. Detail of the cutting arm showing the horizontal pivoting ram

Figures 24, 25 and 26 show the position and arrangement decided for the robotic cutting arm. Because the working range over which each jet can act is limited by the dimensions of the arm, two arms were chosen for use. These were mounted on either side of the conveyor channel and each arm was arranged so that it could cut slots in the facing half of the coal seam (5.5 feet in height and 4.5 feet in width).

Figure 26 Front View of the Assembled RAPIERS

A schematic diagram of the cutting arm is shown in Figure 27. The movements required of the arm could be achieved with just three degrees of freedom. Rotation joint 1 will allow the nozzle to move in the vertical direction, while rotation joint 2 lets the cutting head travel across the face in the horizontal direction. Both joints are to be driven by hydraulic cylinders. The third freedom is a linear motion and is used to compensate for changes in the distance between the nozzle and the coal face and to advance the nozzle into the face as the slot is deepened. This is intended to keep the stand-off distance as a constant. This feed mechanism is provided by a pair of gears and a rack and pinion and is driven by a hydraulic motor.

A considerable period of discussion arose over the choice of the cutting arm motions. It was necessary to evaluate the benefits and disadvantages of this three freedom arm in comparison with the more generally accepted robotic arms which have a greater number of degrees of freedom. The advantage of an arm with a greater number of degrees of freedom, such as for example an arm with 5 degrees of freedom, is that the attack angle of the nozzle to the coal face can be kept at 90 degrees or, if needed, can also be adjusted. However the structure required to allow this freedom, and the controls which it would require to sense the position and to ensure the correct motions,

Figure 27. Overall System Co-ordinates for Operation of the Cutting Arm

would be complicated and the cutting lance would have to be lighter for the additional equipment to be able to move it effectively. This would make the equipment more fragile.

In contrast, the three motion arm is simple to operate. Because of its simplicity greater weight can be given to the arm, which will thus become more rigid. The major disadvantage of this system is that the attack angle cannot be adjusted. As the nozzle moves to the edge of the working range, the angle between the waterjet and the face will reduce to about 70 degrees. In this application this reduction can be accepted, because the purpose of the cuts is to isolate the coal block and relieve the surrounding stress. This will still be possible with the smaller angle.

b) Kinematic solution

Figures 27 and 28 show the basic coordinates of the robotic arm, in which the X-Y plane is set parallel to the working face, and the positive Z direction is set perpendicular to and away from the face. Point O is the intersection point of the axes of the two planes of rotation set by the joints. θ_1 and θ_2 are the parameters for the first and second rotation joints, and d_3 is the parameter for third linear translation. Based on conventional robotic theory, the following equations can therefore be established:

$$A1 = \begin{vmatrix} 1 & 0 & 0 & 0 \\ 0 & \cos \theta_1 & -\sin \theta_1 & 0 \\ 0 & \sin \theta_1 & \cos \theta_1 & 0 \\ 0 & 0 & 0 & 1 \end{vmatrix}$$

$$A2 = \begin{vmatrix} \cos \theta_2 & 0 & \sin \theta_2 & 0 \\ 0 & 1 & 0 & 0 \\ -\sin \theta_2 & 0 & \cos \theta_2 & 0 \\ 0 & 0 & 0 & 1 \end{vmatrix}$$

$$A3 = \begin{vmatrix} 1 & 0 & 0 & a_3 \\ 0 & 1 & 0 & b_3 \\ 0 & 0 & 1 & d_3 \\ 0 & 0 & 0 & 1 \end{vmatrix}$$

The total transformation T should be

$$T = A1 \diamond A2 \diamond A3 = \begin{vmatrix} C2 & 0 & S2 & a3C2+d3S2 \\ S1S2 & C1 & -S1C2 & b3C1+a3S1S2-d3S1C2 \\ -C1S2 & S1 & C1C2 & b3S1-a3C1S2+d3C1C2 \\ 0 & 0 & 0 & 1 \end{vmatrix}$$

where S1, S2 means $\sin \theta_1$, $\sin \theta_2$, C1, C2 means $\cos \theta_1$, $\cos \theta_2$.

Figure 28. Base coordinate System for the Robotic Arm in which the X-Y plane is parallel to the work face, and the positive Z direction is away from the face.

Suppose that the end-effector, i.e., the cutting head, is located at X,Y,Z, then the equations become

$$X = a_3 \cdot \cos \theta_2 + d_3 \cdot \sin \theta_2$$

$$Y = b_3 \cdot \cos \theta_1 + a_3 \cdot \sin \theta_1 \cdot \sin \theta_2 - d_3 \cdot \sin \theta_1 \cdot \cos \theta_2$$

$$Z = b_3 \cdot \sin \theta_1 - a_3 \cdot \cos \theta_1 \cdot \sin \theta_2 + d_3 \cdot \cos \theta_1 \cdot \cos \theta_2$$

Solving the above equations, gives the results

$$d_3 = \sqrt{X^2 + Y^2 + Z^2 - a_3^2 - b_3^2}$$

$$\theta_1 = \tan^{-1} \frac{-b_3}{\sqrt{Y^2 + Z^2 - b_3^2}} - \tan^{-1} \frac{Y}{Z}$$

$$\theta_2 = \tan^{-1} \frac{-X}{\sqrt{a_3^2 + d_3^2 - X^2}} - \tan^{-1} \frac{a_3}{d_3}$$

Once the kinetic solutions have been obtained, the position of the cutting head (X, Y, Z), can be controlled by controlling the values of the parameters θ_1 , θ_2 and d_3 .

In order to control the traverse speed of the cutting head in the X, Y, or Z directions the Jacobian matrix. i.e., the relationship between the velocities of the nozzle and the three joint coordinates, θ_1 , θ_2 , and d_3 , should be established. Then, once the required traverse speed is known, the joint speeds, w_1 and w_2 for the rotational joints 1 and 2, and the linear velocity v_3 for the translation joint 3 can be calculated as the cutting head moves through the different locations of the cutting path. Here, the derivation and the calculation of the Jacobian matrix are neglected. The location and speed control will be further explained later.

Control Scheme for Each Joint

Figure 29. Representation of the Closed Loop Control System

Figure 30. MOOG Model 22-131A and Model 32-187 Servo Valves

Hydraulic Circuitry and System Hardware

A closed-loop control scheme was designed for use in the system, and is shown in Figure 29. The computer used in the system is a MACSYM-150, which was specially chosen its capabilities in dealing with analog input and output. The computer is connected to a MACSYM-200, expansion box, which holds one analog input board and one output board. Three hydraulic servo-valves are connected to the output board, and are used to direct and to control the flowrate of the hydraulic fluid to the various system controls. It is by controlling the opening and position of the spools in the servo-valves, that the direction of motion and the speed of the two cylinders and the one hydraulic motor can be controlled. Two rotational encoders are attached to the axes of the first and second rotary joints.

A third encoder is installed along the axis of the hydraulic motor. These encoders are connected to the input board of the MACSYM-200, and are used to feed back to the computer the actual position of the cutting head. When these signals are integrated with that of the system clock within the computer, the real-time velocities of the head in the three directions can also be derived, and compared, inside the computer, with that required. As a result any necessary positional and velocity changes required can be mandated from within the program.

The servo-valves used in this control system were produced by the MOOG Company. Two Model 22-131A valves were used to control the cylinder positions. These cylinders each had a rated flowrate of 30 cubic inch per second. A model 32-187 valve was chosen to control the flow of fluid to the hydraulic motor and had a smaller rate of flow, of 2 cubic inch per second. Both valve types had close to equivalent characteristics, as shown in Figure 30. Theoretically the control flow is proportional to the input electric current. Because the control electric current is very small (rated currents are 15 ma and 3.6 ma respectively), no amplifier was needed in the control circuit and the controlling coils could be directly hooked up to the computer analog outputs.

The encoders used were all of the potential type, based on the same principle as a linear potential meter as shown in Figure 31. The output voltage indicates the position of the moving shaft of the encoder, which is fixed to the joint shaft of the cutting arm. The advantage of this type of encoder is that the output voltage correlates closely with the actual position of the arm, and no initialization is required before the unit can start to operate, as would be required with the photo type of encoder. This simplified the programming and operation of the unit considerably.

Figure 31. Load Flow - Control Current Characteristics

a) Programming

The MACSYM-BASIC language was used to write the operating computer program which is given in Appendix 1. The general idea used for controlling the movement of the cutting arm was as follows.

First, the program tests the analog input and output of the controlling system, and obtains the basic information on the condition of the cutting arm. Then the computer will request that the operator enter the required coordinates of the cutting path (X_0 , Y_0 , X_1 , Y_1) over the coal face, and the required traverse speed.

The program will then compute the kinematic solution for the movement of the robotic arm. As a part of this process the program calculates the joint parameters, θ_1 , θ_2 , d_3 , and the joint velocities, w_1 , w_2 , and v_3 at different points all along the cutting path. The basis for the selection was designated to be at equal time intervals over the course of the path designated. The program will then establish a table, exemplified by that shown in table 1. This table will list all the required parameters tied to their value at specific times along the path which the arm must sweep out. Based on the velocities given in the table, the computer will output a controlling voltage to the individual servo-valves. This voltage will be adjusted to the computed motion and will thus change as a function of the time during the arm motion. At the same time, the cur-

rent actual locations and velocities of the cutting head will be measured from the readings of the encoders. These will be converted by the program into the actual position and velocities. Then the program computes the individual errors between the actual values and those which the programmed motion requires. These errors are used to compute correcting values which are then output as compensating signals, which are proportional to the position error and velocity error. The computer will then integrate these signals to generate a new value for the controlling output voltage for each of the servo-valves. The program will continue to monitor and control the motion over the course of the movement.. Because of the close monitoring of the movement and the velocity, any errors in motion which occur can be detected while they are still small. In this way, the nozzle will closely follow the required cutting path and moves at the specified speed.

CHAPTER III. EQUIPMENT CONSTRUCTION

Introduction

The purpose of the award for the development of a room and pillar waterjet mining machine under this program was to move the technology toward commercial development. Investigations at UMR into the application of high pressure waterjets have been going on for almost 23 years. A number of developments have shown considerable commercial promise, but it has been difficult to find a reliable path to move novel ideas forward into the market place.

At the beginning of this project considerable hope was placed in the development of the Mining Excavation Research Institute (MERI). This program was funded by ASME during its formative period, and a considerable effort was directed toward this avenue to the ultimate user. Unfortunately, new ideas take some time to develop and although the MERI program is not dead, its development has been much slower and there has been much less industrial support than had been hoped when the program was started. This avenue, therefore, towards the future development of the machine has not been as successful to this point in time as had been hoped. The development of a research arm to the American Mining Congress and the Research Council for the Society of Mining Engineers had both been outgrowths of the MERI activity. These two organizations will hopefully allow a better method of communicating with potential licensees as they become better established.

It, thus, becomes necessary to find a way to reach and convince possible licensees of the potential of RAPIERS. Experience with earlier machines has shown that the simple presentation of papers at symposia and meetings of learned societies is not enough. A graphic visual presentation has been found to be much more powerful in demonstrating the capabilities of waterjets and short video presentations have become widely accepted as a means of demonstrating the capabilities of waterjet cutting systems.

The original proposal therefore called for a video tape to be made of the mining machine operation. The level of funding currently available when taken with the high costs of travelling and installing the mining machine underground, prohibited the actual demonstration of the machine in a field environment. The length of time to obtain certification and the cost that this would incur also mandated against this option.

The decision was therefore made to manufacture the machine at UMR and to demonstrate the operation of its separate components both by using field footage shot of the longwall waterjet mining machine in use, and also by demonstrating the jet cutting ability against an artificial coal seam.

An artificial coal seam was therefore constructed in which particles of coal approximately 1/4" in size were bound into a coarse abrasive cement paste. It was necessary to use a minimum amount of water in the mixture to minimize segregation and also to control the cement strength. The resulting material was relatively friable in much the same way as was found in a conventional coal seam.

In order to give some indication as to the performance of the machine in an underground situation, two short cartoon segments were prepared using the Videoworks II Program on an Apple Macintosh II computer. The first of these segments used a simple black and white model to demonstrate the cyclic operation of a normal continuous miner panel. The second, which was colorized, demonstrated the basic operational parameters of RAPIERS. These two segments were integrated with linking videotape to form a short documentary. The script is presented in Appendix II.

Prototype Evaluation

There is not a great deal of complexity to the prototype RAPIERS which has been developed. Experience has shown that the simpler the mining machine is built then the more likely it is to succeed. Several questions have to be answered, however, with the cutting trials in the artificial coal.

The initial questions was the best novel considerations to use for the cutting arms and the best way to cut the coal ahead of the mining machine. The lower cutting arm placed inside the wedge section of the loading apron performed adequately without additional modification. The use of a dual orifice nozzle issuing through a narrow channel was demonstrated to be successful in the earlier longwall machine and proved again to be successful with this device.

The operation of the sample slotting arms could use as a dual orifice fixed nozzles or self-rotating nozzle assemblies. The self-rotating nozzle designs have become increasingly available and reliable over the last three years. These devices sensibly comprise a dual nozzle assembly with the jets inclined not only radially but also tangentially to the axis of the feed pipe. Thus, as the jet is used from the nozzles the reaction force is sufficient to cause the nozzle assembly to rotate about the feed line. This concept is of considerable benefit in that it allows the nozzle to be rotated with-

out any additional external drive mechanism which would be complicated and which would make the assembly much heavier. Three different assemblies have been obtained at UMR. One from the Hammelmann Corporation, one from NLB, and one from the Stone Age Company of Durango, Colorado. Evaluation of the performance of the different systems indicated that although the Stone Age System was the lightest of the three, the Hammelmann device gave the best performance, and this unit was then used during tests of the cutting head.

The development of the prototype machine used a computer controlled system to operate and control the operations of the machine. Although the trend in machine operation is in this direction, this addition to the machine may well have been an overcomplicated addition at this stage in the program. The basic mechanical components of the unit are very simple. The addition of computer monitoring equipment and the integration of servo valves and feed back control made the unit much more sensitive and more complicated to operate.

This complexity was compounded by two factors. In order to reduce the cost of construction a bank of used servo control valves was obtained for use with the equipment. It transpired that several of these valves were faulty and the diagnosis and ultimate replacement of these units after a relatively lengthy and expensive attempt at repair, cost a lot of valuable time. Further, once the machine was operated the feedback controls for the motion of the arm did not initially give a smooth and stable path for the arm at the required speed and in the required direction. Again, a considerable amount of time was spent in debugging this problem. Since a partial objective of the program was to demonstrate the simplicity of the equipment the problems generated by the attempt to use computer control were perhaps unnecessary at this stage of the program.

Future Plans

The presence of the RAPIERS prototype at UMR has drawn considerable and increasing interest from the visiting executives at mining companies. Interest has been expressed by two of these companies by having the machine operated in one of their mines. It is believed that this will be a significant step forward but it will require some additional funding to become practical. The present intention is to seek that funding through the Bureau of Mines Generic Center Program in 1991.

A problem with the introduction of waterjet equipment has lain in its cost and its relatively unproven capabilities for the mining industry. This situation is changing as

the capabilities of high pressure waterjets and abrasive waterjet systems become more apparent. Significant progress in the technology has been made.

The relative cost and size of RAPIERS makes it unlikely that this will be the first waterjet equipment that a company will install in a mine. Two other developments which are now moving forward will likely proceed it. The first of these is a waterjet drilling device, and the second is the small fine coal planing machine being developed under separate DOE funding.

The reason that these other two machines will likely enter the market first, is that they are smaller, cheaper, and are much more capable of being operated in a stand-alone mode than RAPIERS. Although much more independent of other equipment than a longwall unit, a room and pillar mining machine still must be integrated into existing mining operations. This requires a relatively expensive commitment on the part of mine owners. While that commitment appears to be on the horizon, it will be easier to introduce the independent equipment first.

RAPIERS has been found in many ways to be a simpler machine than was anticipated when it was originally conceived. As interest continues to build in new mining equipment, and the needs for inexpensive clean coal become more demanding, the role that this new machine will have to play is likely to be significant. We are committed to move the development of this machine forward in the next few years as the opportunity increasingly arises to introduce its benefits to industry.

Acknowledgements

This program was funded under the Energy Related Inventions Program with Mr. Jack Aellen as Project Officer. His considerable patience and helpful advice as we struggled with many of the problems in the development of this machine is sincerely appreciated.

The concept for RAPIERS was developed in cooperation with the Jet Propulsion Laboratory, Pasadena, CA. with Mr. Jay Estus as co-inventor of the machine. The help that was provided by that organization and the forbearance which they displayed as we struggled to bring the machine to completion is also appreciated.

A considerable part of the final machine design was built by Mr. James Blaine and the electronic circuitry by Mr. John Tyler of the Rock Mechanics & Explosives Research Center Staff. The reporting and financial monitoring of the contract was under the direction of Mrs. Jo Blaine, this support is also very gratefully acknowledged.

Finally the video script was prepared with considerable advice from Dr Sam Geonetta, now at the University of Cincinnati. His advice and the assistance of the Center for Media Studies at UMR in assembling the tape, and that of Mr Fossey who shot is is willingly acknowledged.

References

1. Lavin M.L. et al, "Design and Evaluation of a Continuous , In-Place, Hydromechanical System for Underground Coal Mining" Final Report on Contract JO134054 for the US Bureau of Mines, Jet Propulsion Laboratory, JPL Publication 84-64. July 1984.
2. Summers D. A., Barker C.R. and Mazurkiewicz M. "Experimentation in Hydraulic Coal Mining", 1977 AIME Ann Mtg, Atlanta, GA, Mar 18, 1977.
3. Summers D.A. And Peters, J.L. "Preliminary Experimentation in Coal Cutting in the Pressure Range 500 to 2,000 Atmospheres", 2nd Int Symp Jet Cutting Tech, Cambridge, UK, April 1974, paper H-2.
4. Selberg B.P. and Barker C.R. "Dual-Orifice Waterjet Predictions and Experiments", pp 493-510, in Erosion: Prevention and Useful Applications, ASTM STP 664, October 1977.
5. Summers D.A. et al "Excavation of Coal Using a High Pressure Water Jet System", Final Report on Contract HO232064 to US Bureau of Mines, November 1974.
6. Henkel E. "Gewinnungs- und Strebfordertechnik", 25th Year Review, Gluckauf, 1983, pp30-34.

B: B-o-h. D: Sep:

```

10 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
20 @                PROGRAM FOR CONTROLLING HYDRO-MINER                @
30 @                WRITTEN BY                                          @
40 @                YAO, JIANCHI                                         @
50 @                ROCK MECHANICS AND EXPLOSIVE RESEARCH CENTER         @
60 @                UNIVERSITY OF MISSOURI-ROLLA                         @
70 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
80 @
90 @
100 @ THIS PROGRAM IS USED TO CONTROL THE HYDRO-MINER. IT CONSISTS OF TWO PA
RTS ONE CONTROLS ROBOTIC CUTTING ARMS. THE OTHER CONTROLS THE BOTTOM WATERJET A
ND THE MOVING OF MACHINE.
110 GOSUB 500 @ CHECK COMMUNICATION CHANNELS & ANALOG I/O
120 GOSUB 300 @ MAIN MENU
122 END
125 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
125 @ SUBROUTINE FOR ROBOTIC ARM CONTROL
130 GOSUB 700 @ GET THE BASIC DATA FOR COAL FACE AND ROBOTIC ARMS
140 GOSUB 1000 @ GET THE REQUIRED PATH PARAMETRERS FOR THE CUTTING
150 GOSUB 1400 @ PLOT THE REQUIRED PATH ON THE SCREEN
160 GOSUB 1600 @ CALCULATE THE LOCATION PARAMETERS FOR THE PATH
170 @ GOSUB 2500 @ PRINT THE PARAMETER TABLE
180 GOSUB 2800 @ FIND PRESENT POSITION PARAMETERS OF LEFT HEAD
190 GOSUB 2900 @ FIND PRESENT POSITION PARAMETERS OF RIGHT HEAD
200 GOSUB 3000 @ PREPARE SCREEN SHOW FOR MOVING TO HOME POSITIONS
210 GOSUB 3100 @ CALCULATE LEFT CUTTING HEAD POSITION AND SHOW ON SCREEN
220 GOSUB 3200 @ CALCULATE RIGHT CUTTING HEAD POSITION AND SHOW ON SCREEN
230 GOSUB 3300 @ STOP THE CUTTING HEADS WHERE THEY ARE
240 GOSUB 3500 @ MOVE THE CUTTING HEADS TO HOME POSITIONS
250 GOSUB 3700 @ TEST THE SERVO-CONTROLLED HYDRAULIC SYSTEM
260 GOSUB 4100 @ START TO CUT
270 GOSUB 4400 @ CHOOSING TABLE
290 RETURN
290 @
300 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
310 @ SUBROUTINE FOR MIAN MENU
320 PAGE 0 CLS DISPLAY 0
330 ! ! !
340 ! TAB(10) "PRESS 'R' TO CONTROL ROBOTIC ARMS"
350 ! TAB(10) "PRESS 'M' TO CONTROL MACHINE MOVING"
360 ! TAB(10) "PRESS 'Q' TO QUIT"
370 INPUT X$
380 IF X$="M" THEN GOSUB 10000 GOTO 320
390 IF X$="R" THEN GOSUB 125 GOTO 320
400 IF X$="Q" THEN RETURN
410 GOTO 370
420 @
500 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
510 @ SUBROUTINE FOR CHECKING COMM. CHANNEL AND ANALOG I/O
520 PAGE 0 CLS DISPLAY 0
530 ON ERROR ERRNUM', 580
540 A'=1 XRESET NOMODE ! " CHECKING SERIAL I/O & ANALOG I/O." !
550 AOT(1,0)=0 AOT(2,0)=0 B=AIN(0,12,0,0) A=DIN(3,12,13) DOT(3,0,10)=0
560 ! " XRESET SUCCESSFUL, MACSYM IS READY FOR ANALOG I/O." ! " PRESS ANY
KEY TO CONTINUE." INPUT X$
570 OFF ERROR RETURN
580 IF ERRNUM'=23 THEN ! " COMM. CHANNEL TIMEOUT, CHECK CABLE BETWEEN MACSYM
150 AND MACSYM 200." ! " IF CABLE IS DISCONNECTED, RECONNECT IT AND RESTART P

```

```
PROGRAM." OFF ERROR RESET SUB END  
590 A'=A'+1 IF A'=3 THEN 1 GOTO 610  
600 XRESET WAIT 5 GOTO 550  
610 ! " ATTEMPTS TO INIT. ANALOG I/O AND DIGITAL I/O ARE UNSUCCESSFUL."  
620 ! " CHECK ALL CARDS IN MACSYM 200 FOR PROPER POSITIONING AND PLACEMENT:"  
630 ! TAB(10) "ANALOG INPUT ---> SLOT 0"  
640 ! TAB(10) "ANALOG OUTPUT 1 ---> SLOT 1"  
650 ! TAB(10) "ANALOG OUTPUT 2 ---> SLOT 2"  
660 ! TAB(10) "DIGITAL OUTPUT ---> SLOT 3"  
670 OFF ERROR RESET SUB END  
680 @  
700 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@  
710 @ SUBROUTINE FOR GETTING BASIC DATA FOR THE CUTTING SYSTEM  
720 H=5.5 W=9 @ DIMENSIONS OF THE COAL FACE  
730 LA3=1/12 LB3=11.65/12 @ OFFSETS OF LEFT ARM  
740 RA3=-1.34/12 RB3=12.3/12 @ OFFSETS OF RIGHT ARM  
750 @ THE LOCATION OF THE BASE COORDINATES OF THE CUTTING HEADS  
760 LXX=26/12 RXR=82/12 LYX=29.5/12 LZL=46/12 RYY=29.5/12 RZZ=46/12  
770 C=PI/180 HC=C/2  
780 LTHETA10=153.13+C LC1=-32.45*C @ CONSTANTS FOR LEFT ENCODER 1  
790 LTHETA20=-205.90*C LC2=+31.06*C @ LEFT ENCODER 2  
800 LD30=-6.870+.1 LC3=0.503 @ LEFT ENCODER 3  
810 RTHETA10=-186.825+C RC1=30.0984*C @ RIGHT ENCODER 1  
820 RTHETA20=-184.808+C RC2=31.5258*C @ RIGHT ENCODER 2  
830 RD30=-6.4274+.1 RC3=0.5038 @ RIGHT ENCODER 3  
840 OUT1=0 OUT2=1 OUT3=2 @ OUT PORTS FOR LEFT ARM  
850 OUT4=0 OUT5=1 OUT6=2 @ OUT PORTS FOR RIGHT ARM  
860 LSLOT=1 RSLOT=2 @ SLOTS FOR OUTPUT  
870 IN1=12 IN2=13 IN3=14 @ IN PORTS FOR LEFT ARM  
880 IN4=24 IN5=25 IN6=26 @ IN PORTS FOR RIGHT ARM  
890 LSS1=0 LSS2=0 LSS3=0 @ INITIALIZING DATA  
900 RSS1=0 RSS2=0 RSS3=0 @ INITIALIZING DATA  
910 LSET11=0.2 LSET21=0.2 LSET31=0.2  
920 RSET11=0.2 RSET21=0.2 RSET31=0.2  
930 AOT(LSLOT,OUT1)=LSS1 AOT(LSLOT,OUT2)=LSS2 AOT(LSLOT,OUT3)=LSS3  
940 AOT(RSLOT,OUT4)=RSS1 AOT(RSLOT,OUT5)=RSS2 AOT(RSLOT,OUT6)=RSS3  
950 W1=S/C W2=S*C V3=2/12 CC=0.1/C  
955 ON ERROR 183, 9000, ERLINE  
960 RETURN  
970 @  
1000 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@  
1010 @ SUBROUTINE FOR GETTING THE REQUIRED CUTTING PATH PARAMETERS  
1020 NL=3 NR=3 RESTORE @ NUMBER OF PATHS  
1030 DIM LX1(NL), LY1(NL), LX2(NL), LY2(NL)  
1040 DIM RX1(NR), RY1(NR), RX2(NR), RY2(NR)  
1050 FOR I=1 TO 10 READ Z$ NEXT  
1060 FOR I=1 TO NL  
1070 READ LX1(I), LY1(I), LX2(I), LY2(I) @ LEFT START & END POINTS  
1080 NEXT I  
1090 FOR I=1 TO NR  
1100 READ RX1(I), RY1(I), RX2(I), RY2(I) @ RIGHT START & END POINTS  
1110 NEXT I  
1120 @ DATA IN LINE 13000  
1130 @  
1140 V=1 @ TRAVERSE SPEED (INCH/SEC)  
1150 RETURN  
1160 @  
1400 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@  
1410 @ SUBROUTINE FOR PLOTTING THE CUTTING PATH ON THE SCREEN  
1420 PAGE 4 CLS
```

```

1430 WINDOW -0.5, 9.5,-0.5, 7
1440 LTYPE 2      DISPLAY 4       CLS 4       FONT 0
1450 MOVE 0,0     PLOT 9,0        PLOT 9,5.5   PLOT 0,5.5   PLOT 0,0
1460 MOVE 4.5,0   PLOT 4.5,5.5
1470 LTYPE 0 WAIT .1
1480 FOR I=1 TO NL
1490 MOVE LX(I), LY(I) PLOT LX2(I), LY2(I) WAIT .1
1500 NEXT I
1510 FOR I=1 TO NR
1520 MOVE RX(I), RY(I) PLOT RX2(I), RY2(I) WAIT .1
1530 NEXT I
1540 HPRINT 1,6.2, "THE VELOCITY IS "
1550 VS=STR$(V)    HPRINT 4.3,6.2, V$    HPRINT 5.5,6.2,"INCH/SEC."
1560 HPRINT 1,5.9, "PRESS 'Y' TO CONTINUE, OR 'N' TO CHANGE PATH PARAMETERS"
1570 INPUT X$ IF X$="Y" THEN RETURN
1580 IF X$="N" THEN RESET SUB END
1590 GOTO 1570
1595 @
1600 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
1610 @ SUBROUTINE FOR CALCULATING THE CUTTING PATH PARAMETERS
1620 N=101 M=100 @ DIVIDE THE WHOLE PATH INTO 100 SECTIONS
1630 DIM LX(NL,N),LY(NL,N),LT(NL,N),LTHETA1(NL,N),LTHETA2(NL,N),LD3(NL,N),LW1(
NL,N),LW2(NL,N),LV3(NL,N)
1640 DIM RX(NR,N),RY(NR,N),RT(NR,N),RTHETA1(NR,N),RTHETA2(NR,N),RD3(NR,N),RW1(
NR,N),RW2(NR,N),RV3(NR,N)
1650 DIM LL(NL),LTT(NL),RL(NR),RTT(NR),LOT(NL),ROT(NR)
1660 @ CALCULATE THE LENGTH OF PATH & TIME NEEDED FOR TRAVELLING
1670 FOR I=1 TO NL
1680 LL(I)=SQR((LX2(I)-LX1(I))*(LX2(I)-LX1(I))+(LY2(I)-LY1(I))*(LY2(I)-LY1(I)))
) @ LENGTH OF LEFT PATHS
1690 LTT(I)=LL(I)*12/V LOT(I)=LTT(I)/M @ TOTAL TIME AND TIME STEP
1700 NEXT I
1710 FOR I=1 TO NR
1720 RL(I)=SQR((RX2(I)-RX1(I))*(RX2(I)-RX1(I))+(RY2(I)-RY1(I))*(RY2(I)-RY1(I)))
) @ LENGTH OF RIGHT PATHS
1730 RTT(I)=RL(I)*12/V ROT(I)=RTT(I)/M @ TOTAL TIME AND TIME STEP
1740 NEXT I
1745 A3=LA3 B3=LB3
1750 FOR I=1 TO NL @ LEFT SIDE
1760 DX=(LX2(I)-LX1(I))/M
1770 DY=(LY2(I)-LY1(I))/M
1780 DT=LTT(I)/M
1790 LX(I,1)=LX1(I) LY(I,1)=LY1(I) LT(I,1)=0
1800 FOR J=1 TO M
1810 LX(I,J+1)=LX(I,J)+DX
1820 LY(I,J+1)=LY(I,J)+DY
1830 LT(I,J+1)=LT(I,J)+DT
1840 NEXT J
1850 @ CLACULATE THE PARAMETERS
1860 FOR J=1 TO N
1870 X=LX(I,J)-LXX
1880 Y=LY(I,J)-LYY
1890 Z=-LZZ
1900 GOSUB 2400 @ GET LOCATION PARAMETERS
2000 LTHETA1(I,J)=THETA11
2010 LTHETA2(I,J)=THETA22
2020 LD3(I,J)=O33
2030 NEXT J
2040 FOR J=1 TO M
2050 LW1(I,J)=(LTHETA1(I,J+1)-LTHETA1(I,J))/DT

```



```

2060 LW2(I,J)=(LTHETA2(I,J+1)-LTHETA2(I,J))/DT
2070 LV3(I,J)=(LD3(I,J+1)-LD3(I,J))/DT
2080 NEXT J
2085 NEXT I
2090 A3=RA3 B3=RB3
2100 FOR I=1 TO NR @ RIGHT SIDE
2110 DX=(RX2(I)-RX1(I))/M
2120 DY=(RY2(I)-RY1(I))/M
2130 DT=RTT(I)/M
2140 RX(I,1)=RX1(I) RY(I,1)=RY1(I) RT(I,1)=0
2150 FOR J=1 TO M
2160 RX(I,J+1)=RX(I,J)+DX
2170 RY(I,J+1)=RY(I,J)+DY
2180 RT(I,J+1)=RT(I,J)+DT
2190 NEXT J
2200 @ CLACULATE THE PARAMETERS
2210 FOR J=1 TO N
2220 X=RX(I,J)-RXX
2230 Y=RY(I,J)-RYY
2240 Z=-RZZ
2250 GOSUB 2400 @ GET THE LOCATION PARAMETERS
2260 RTHETA1(I,J)=THETA11
2270 RTHETA2(I,J)=THETA22
2280 RD3(I,J)=D33
2290 NEXT J
2300 FOR J=1 TO M
2310 RW1(I,J)=(RTHETA1(I,J+1)-RTHETA1(I,J))/DT
2320 RW2(I,J)=(RTHETA2(I,J+1)-RTHETA2(I,J))/DT
2330 RV3(I,J)=(RD3(I,J+1)-RD3(I,J))/DT
2340 NEXT J
2345 NEXT I
2350 RETURN
2360 @
2400 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
2410 @ SUBROUTINE FOR PARAMETER CALCULATION
2420 D33=-SQR(X*X+Y*Y+Z*Z-A3*A3-B3*B3)
2430 U=SQR(Y*Y+Z*Z-B3*B3)
2440 THETA11=-ATN(B3/U)-ATN(Y/Z)
2450 UU=SQR(A3*A3+D33*D33-X*X)
2460 THETA22=-ATN(X/UU)-ATN(A3/D33)
2470 RETURN
2480 @
2500 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
2510 @ SUBROUTINE FOR PRINTING THE PARAMETER TABLE
2520 PAGE 0 CLS DISPLAY 0
2525 OPENW : 3 "STTO" @ "STTO" FOR SCREEN PRINTING
2526 @ OPENW : 3 "SQTO:3" @ "SQTO:3" FOR PRINTER PRINTING
2530 FOR I=1 TO NL @ PRINT LEFT SIDE
2540 ! :3 " TABLE FOR FOR LEFT PATH * "; I !:3 !
2550 !:3 "


---


2560 !:3 " T X Y THETA1 THETA2 D3 W1 W2 V
3"
2570 !:3 "


---


2580 FOR J=1 TO N
2590 PRINT USING:3 "-###.### " LT(I,J),LX(I,J),LY(I,J),LTHETA1(I,J)/C,LTHETA2(I,J)/C,LD3(I,J),LW1(I,J)/C,LW2(I,J)/C,LV3(I,J)
2600 IF J=20 OR J=40 OR J=60 OR J=80 OR J=101 THEN INPUT AS
2610 NEXT J

```

```

2620 NEXT I
2630 FOR I=1 TO NR @ PRINT RIGHT SIDE
2640 !:3 " TABLE FOR FOR RIGHT PATH # "; I !
2650 !:3 "

```

```

2660 !:3 " T X Y THETA1 THETA2 D3 W1 W2
V3*
2670 !:3 "

```

```

2680 FOR J=1 TO N
2690 PRINT USING:3 "-##.### " RT(I,J),RX(I,J),RY(I,J),RTHETA1(I,J)/C,RTHETA2(I,J)/C,
RD3(I,J),RW1(I,J)/C,RW2(I,J)/C,RV3(I,J)
2700 IF J=20 OR J=40 OR J=60 OR J=80 OR J=101 THEN INPUT AS
2710 NEXT J
2720 NEXT I
2725 CLOSE :3
2730 RETURN
2740 @
2800 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
2810 @ SUBROUTINE FOR FINDING PRESENT POSITION OF LEFT HEAD
2820 P1=AIN(0,IN1,0,0) P2=AIN(0,IN2,0,0) P3=AIN(0,IN3,0,0)
2830 LTHETA1=LTHETA10+P1*LC1 @ CALCULATE LEFT THETA1
2840 LTHETA2=LTHETA20+P2*LC2 @ CALCULATE LEFT THETA2
2850 LD3=LD30+P3*LC3 @ CALCULATE LEFT D3
2860 RETURN
2870 @
2900 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
2910 @ SUBROUTINE FOR FINDING PRESENT POSITION OF RIGHT HEAD
2920 P4=AIN(0,IN4,0,0) P5=AIN(0,IN5,0,0) P6=AIN(0,IN6,0,0)
2930 RTHETA1=RTHETA10+P4*RC1 @ CALCULATE RIGHT THETA1
2940 RTHETA2=RTHETA20+P5*RC2 @ CALCULATE RIGHT THETA2
2950 RD3=RD30+P6*RC3 @ CALCULATE RIGHT D3
2960 RETURN
2970 @
3000 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
3010 @ SUBROUTINE FOR PREPARING SCREEN FOR STOPPING CUTTING HEADS
3020 @ PAGE 4 DISPLAY 4
3030 COLOR 0 BOX 0.5,5.5,9,1.5,1 COLOR 7
3040 HPRINT 1,6.5, "THE POSITION OF HEADS ARE SHOWN BELOW."
3050 HPRINT 1,6.2, "THE CUTTING HEADS ARE STOPPING WHERE THEY ARE."
3060 HPRINT 1,5.9, "PRESS ANY KEY TO CONTINUE."
3070 RETURN
3080 @
3100 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
3110 @ SUBROUTINE FOR CALCULATING LEFT HEAD POSITION AND SHOWING ON SCREEN
3120 LSIN1=SIN(LTHETA1) LCOS1=COS(LTHETA1)
3130 LSIN2=SIN(LTHETA2) LCOS2=COS(LTHETA2)
3140 LX=LA3*LCOS2+LD3*LSIN2+LXX
3150 LY=LB3*LCOS1+LA3*LSIN1*LSIN2-LD3*LSIN1*LCOS2+LYY
3160 @ Z=B3*SIN1-A3*COS1*SIN2+D3*COS1*COS2 DZ=(Z+ZZ)*12
3170 CIRCLE LX,LY,.03 @ HPRINT 7.2,5.5,STR$(DZ)
3180 RETURN
3190 @
3200 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
3210 @ SUBROUTINE FOR CALCULATING RIGHT HEAD POSITION AND SHOWING ON SCREEN
3220 RSIN1=SIN(RTHETA1) RCOS1=COS(RTHETA1)
3230 RSIN2=SIN(RTHETA2) RCOS2=COS(RTHETA2)
3240 RX=RA3*RCOS2+RD3*RSIN2+RXX
3250 RY=RB3*RCOS1+RA3*RSIN1*RSIN2-RD3*RSIN1*RCOS2+RYY
3260 @ Z=B3*SIN1-A3*COS1*SIN2+D3*COS1*COS2 DZ=(Z+ZZ)*12

```

```

3270 CIRCLE RX,R,Y,.03      @ HPRINT 7.2,S.6,STR$:"DZ")
3280 RETURN
3290 @
3300 #####
3310 @ SUBROUTINE FOR STOPPING CUTTING HEADS WHERE THEY ARE
3320 TASK 3, 6900, 50   TASK 4, 6800, 50
3330 TASK 5, 8900, 50   TASK 6, 8800, 50
3340 GOSUB 5000          @ STOP LEFT ARM
3350 GOSUB 7000          @ STOP RIGHT ARM
3360 LALPHA1=LTHETA1    LALPHA2=LTHETA2    LTRAN3=LD3
3370 RALPHA1=RTHETA1    RALPHA2=RTHETA2    RTRAN3=RD3
3380 TASK 1, 5200   TASK 2, 7200   @ MOVE TO ALPHA1, ALPHA2, TRAN3 POSITIONS
3390 LS=0   RS=0
3400 ACT 1   ACT 2
3410 IF LS=1 AND RS=1 THEN INPUT X$: RETURN
3420 WAIT .2   GOTO 3410
3430 @
3500 #####
3510 @ SUBROUTINE FOR MOVING CUTTING HEADS TO HOME POSITIONS
3520 COLOR 0 BOX 0.5,5.6,9,1.5,1 COLOR 7
3530 HPRINT 1,5.9, "THE CUTTING HEADS ARE MOVING TO HOME POSITIONS."
3540 KILL 1   KILL 2
3550 LALPHA1=0   LALPHA2=0   LTRAN3=-50/12
3560 RALPHA1=0   RALPHA2=0   RTRAN3=-50/12
3570 TASK 1, 5200   TASK 2, 7200
3580 LS=0   RS=0
3590 ACT 1   ACT 2
3600 GOSUB 6700   GOSUB 8700
3610 IF LS=1 AND RS=1 THEN RETURN
3620 WAIT .5   GOTO 3600
3630 @
3700 #####
3710 @ SUBROUTINE FOR TESTING THE HYDRAULIC SYSTEM
3720 COLOR 0 BOX 0.5,5.6,9,1.5,1 COLOR 7
3730 HPRINT 1,6.5, "PRESS 'LU' 'LD' 'RU' 'RD' TO MOVE UP OR DOWN."
3740 HPRINT 1,6.2, "PRESS 'LL' 'LR' 'RL' 'RR' TO MOVE LEFT OR RIGHT."
3750 HPRINT 1,5.9, "PRESS 'LF' 'LB' 'RF' 'RB' TO MOVE FORWARD OR BACKWARD."
3760 HPRINT 1,5.6, "PRESS 'X' TO EXIT TESTING."
3770 INPUT X$
3780 IF X$="LU" THEN LALPHA1=LALPHA1+2*C   GOTO 3920
3790 IF X$="LD" THEN LALPHA1=LALPHA1-2*C   GOTO 3920
3800 IF X$="LL" THEN LALPHA2=LALPHA2+2*C   GOTO 3920
3810 IF X$="LR" THEN LALPHA2=LALPHA2-2*C   GOTO 3920
3820 IF X$="LB" THEN LTRAN3=LTRAN3+.03   GOTO 3920
3830 IF X$="LF" THEN LTRAN3=LTRAN3-.03   GOTO 3920
3840 IF X$="RU" THEN RALPHA1=RALPHA1+2*C   GOTO 3970
3850 IF X$="RD" THEN RALPHA1=RALPHA1-2*C   GOTO 3970
3860 IF X$="RL" THEN RALPHA2=RALPHA2+2*C   GOTO 3970
3870 IF X$="RR" THEN RALPHA2=RALPHA2-2*C   GOTO 3970
3880 IF X$="RB" THEN RTRAN3=RTRAN3+.03   GOTO 3970
3890 IF X$="RF" THEN RTRAN3=RTRAN3-.03   GOTO 3970
3900 IF X$="X" THEN RETURN
3910 GOTO 3770
3920 KILL 1   LS=0   TASK 1, 5200   ACT 1              @ LEFT SIDE
3930 GOSUB 6700                                @ SHOW NEW POSITION
3940 @ SEE IF TARGET REACHED
3950 IF LS=1 THEN GOTO 3770
3960 WAIT 0.5   GOTO 3930
3970 KILL 2   RS=0   TASK 2, 7200   ACT 2              @ RIGHT SIDE
3980 GOSUB 8700                                @ SHOW NEW POSITION

```

[illegible]

```

5230 L10=LTHETA10+P1*LC1   L20=LTHETA20+P2*LC2   L30=LD30+P3*LC3   LT0=LT
5240 IF ABS(L10-LALPHA1)>HC THEN LSET1=LSS1      GOTO 5270
5250 IF L10>LALPHA1 THEN LSET1=LSS1-LSET11     GOTO 5270
5260 IF L10<LALPHA1 THEN LSET1=LSS1+LSET11
5270 IF ABS(L20-LALPHA2)>HC THEN LSET2=LSS2      GOTO 5300
5280 IF L20>LALPHA2 THEN LSET2=LSS2-LSET21     GOTO 5300
5290 IF L20<LALPHA2 THEN LSET2=LSS2+LSET21
5300 IF ABS(L30-LTRAN3)<.02 THEN LSET3=LSS3      GOTO 5330
5310 IF L30>LTRAN3 THEN LSET3=LSS3-LSET31     GOTO 5330
5320 IF L30<LTRAN3 THEN LSET3=LSS3+LSET31
5330 WAIT .1
5340 ACT 3   WAIT 0.016667       @ GET POSITION PARAMETERS
5350 L11=LTHETA10+P1*LC1   L21=LTHETA20+P2*LC2   L31=LD30+P3*LC3   LT1=LT
5360 LDF1=LALPHA1-L11   LDF2=LALPHA2-L21   LDF3=LTRAN3-L31
5370 IF ABS(LDF1)>HC AND ABS(LDF2)>HC AND ABS(LDF3)>.02 THEN 5560
5380 IF ABS(LDF1)>10*C THEN LW1=W1*SGN(LDF1)    GOTO 5400           @ MAXIMUM SPEED
5390 IF ABS(LDF1)<=10*C THEN LW1=CC+W1*LDF1          @ SPEED REDUCED
5400 IF ABS(LDF2)>10*C THEN LW2=W2*SGN(LDF2)    GOTO 5420
5410 IF ABS(LDF2)<=10*C THEN LW2=CC+W2*LDF2
5420 IF ABS(LDF3)>.0.333 THEN LV3=V3*SGN(LDF3)   GOTO 5440
5430 IF ABS(LDF3)<=.0.333 THEN LV3=3*V3*LDF3
5440 IF ABS(LDF1)>HC THEN 5470
5450 LDW1=(L11-L10)/(LT1-LT0)-LW1
5460 LSET1=LSET1-LDW1/C*.1
5470 IF ABS(LDF2)>HC THEN 5500
5480 LDW2=(L21-L20)/(LT1-LT0)-LW2
5490 LSET2=LSET2-LDW2/C*.1
5500 IF ABS(LDF3)<.02 THEN 5530
5510 LDV3=(L31-L30)/(LT1-LT0)-LV3
5520 LSET3=LSET3-LDV3
5530 ACT 4   WAIT 0.016667
5540 LT0=LT1   L10=L11   L20=L21   L30=L31
5550 GOTO 5330
5560 @ TARGET HAS BEEN REACHED
5570 GOSUB 5000
5580 LS=1
5590 GOTO 5220
5595 @
5600 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
5610 @ TASK 7 FOR LEFT ARM MOVING AND CUTTING
5620 FOR I=1 TO NL                @ NL PATHES
5630 @@@ MOVING THE ARM TO THE STARTING POINT @@@
5640 LTRAN3=-46/12   LS=0                                @ RETREAT ARM
5650 KILL 1
5655 IF TSTATE(1)>-1 THEN 5650
5656 TASK 1,5200   ACT 1
5660 IF LS=0 THEN WAIT 0.5   GOto 5660
5670 LALPHA1=LTHETA1(I,1)   LALPHA2=LTHETA2(I,1)   LS=0         @ MOVE
5680 KILL 1
5685 IF TSTATE(1)>-1 THEN 5680
5686 TASK 1,5200   ACT 1
5690 IF LS=0 THEN WAIT 0.5   GOTO 5690
5700 LTRAN3=LD3(I,1)   LS=0                                    @ EXTEND ARM
5710 KILL 1
5715 IF TSTATE(1)>-1 THEN 5710
5716 TASK 1,5200   ACT 1
5720 IF LS=0 THEN WAIT 0.5   GOTO 5720
5730 @@@ START TO CUT @@@
5740 FOR LOI=1 TO 4            @ CUTTING COAL BACK AND FORTH 4 TIMES
5750 GOSUB 6300               @ CUTTING THE COAL

```

```

5760 IF LDI=4 THEN 5770
5762 GOSUB 6000 @ CHANGE PARAMETERS FOR DEEP CUTTING
5764 LALPHA1=LTHETA1(I,1) LALPHA2=LTHETA2(I,1) LTRAN3=LD3(I,1) LS=0
5765 KILL 1
5766 IF TSTATE(1)>-1 THEN 5765
5767 TASK 1,5200 ACT 1
5768 IF LS=0 THEN WAIT 0.5 GOTO 5768
5770 NEXT LDI
5780 NEXT I
5790 @ CUTTING IS FINISHED, RETURN TO HOME POSITION
5800 LALPHA1=L11 LALPHA2=L21 LTRAN3=-46/12 LS=0 KILL 1
5810 TASK 1, 5200 ACT 1 @ RETREAT
5820 IF LS=0 THEN WAIT 0.5 GOTO 5820
5830 LALPHA1=0 LALPHA2=0 LS=0 KILL 1 @ MOVE TO HOME POSITION
5840 TASK 1, 5200 ACT 1 @ MOVE
5850 IF LS=0 THEN WAIT 0.5 GOTO 5850
5860 @ COLOR 0 BOX 0.5, 5.6, 9, 0.6, 1 COLOR 7
5870 HPRINT 1, 5.6, "LEFT SIDE CUTTING IS FINISHED."
5880 LSF=1
5890 WAIT 0.5 GOTO 5890
5900 @
5900 @
6010 @ SUBROUTINE FOR CHANGING THE LEFT ARM PARAMETERS FOR DEEP CUTTING
6015 ON ERROR 101, 6270, ERRLINE
6020 NN=N+1 HN=M/2 DOC=.3
6030 FOR LI=1 TO HN
6040 LTEM=LTHETA1(I,LI)
6050 LTHETA1(I,LI)=LTHETA1(I,NN-LI)
6060 LTHETA1(I,NN-LI)=LTEM
6070 LTEM=LTHETA2(I,LI)
6080 LTHETA2(I,LI)=LTHETA2(I,NN-LI)
6090 LTHETA2(I,NN-LI)=LTEM
6100 LTEM=LD3(I,LI)
6110 LD3(I,LI)=LD3(I,NN-LI)-DOC
6120 LD3(I,NN-LI)=LTEM-DOC
6130 LTEM=LW1(I,LI)
6140 LW1(I,LI)=-LW1(I,N-LI)
6150 LW1(I,N-LI)=-LTEM
6160 LTEM=LW2(I,LI)
6170 LW2(I,LI)=-LW2(I,N-LI)
6180 LW2(I,N-LI)=-LTEM
6190 LTEM=LV3(I,LI)
6200 LV3(I,LI)=-LV3(I,N-LI)
6210 LV3(I,N-LI)=-LTEM
6220 NEXT LI
6225 LD3(I,HN+1)=LD3(I,HN+1)-DOC
6230 FOR LI=1 TO N
6240 IF LD3(I,LI)<-5.4 THEN LD3(I,LI)=-5.4 LV3(I,LI)=0
6250 NEXT LI
6260 RETURN
6270 @ ERROR TRAP
6271 IF ERRLINE=6040 THEN 6040
6272 IF ERRLINE=6050 THEN 6050
6273 IF ERRLINE=6060 THEN 6060
6274 IF ERRLINE=6070 THEN 6070
6275 IF ERRLINE=6080 THEN 6080
6276 IF ERRLINE=6090 THEN 6090
6277 IF ERRLINE=6100 THEN 6100
6278 IF ERRLINE=6110 THEN 6110
6279 IF ERRLINE=6120 THEN 6120

```

```
6290 IF ERRLINE=6130 THEN 6130
6281 IF ERRLINE=6140 THEN 6140
6282 IF ERRLINE=6150 THEN 6150
6293 IF ERRLINE=6160 THEN 6160
6284 IF ERRLINE=6170 THEN 6170
6285 IF ERRLINE=6180 THEN 6180
6286 IF ERRLINE=6190 THEN 6190
6287 IF ERRLINE=6200 THEN 6200
6288 IF ERRLINE=6210 THEN 6210
6290 ! "ERROR HAPPENED IN LINE ";ERRLINE RESET SUB END
6295 @
6300 #####
6310 @ SUBROUTINE FOR KEEPING NOZZLE ALONG THE TRACK OF CUTTING PATH
6315 ON ERROR ERNUM', 6460
6320 KILL 1
6330 IF ABS(LW1(I,1))<0.001 THEN LSET1=LSS1 GOTO 6360
6340 IF LW1(I,1)>0 THEN LSET1=LSS1-LSET11 GOTO 6360
6350 LSET1=LSS1+LSET11
6360 IF ABS(LW2(I,1))<0.001 THEN LSET2=LSS2 GOTO 6390
6370 IF LW2(I,1)>0 THEN LSET2=LSS2-LSET21 GOTO 6390
6380 LSET2=LSS2+LSET21
6390 IF ABS(LV3(I,1))<0.001 THEN LSET3=LSS3 GOTO 6420
6400 IF LV3(I,1)>0 THEN LSET3=LSS3-LSET31 GOTO 6420
6410 LSET3=LSS3+LSET31
6420 LST=TIMER
6430 ACT 4 WAIT 0.116667 @ OUTPUT SIGNALS .
6440 ACT 3 WAIT 0.016667 @ GET POSITION PARAMETERS
6450 L10=LTHETA10+P1*L01 L20=LTHETA20+P2*L02 L30=L030+P3*L03 LT0=LT
6460 WAIT .1
6470 ACT 3 WAIT 0.016667 @ GET POSITION PARAMETERS
6480 L11=LTHETA10+P1*L01 L21=LTHETA20+P2*L02 L31=L030+P3*L03 LT1=LT
6490 IF ABS(L11-LTHETA1(I,N))>HC AND ABS(L21-LTHETA2(I,N))>HC AND ABS(L31-LD3(
I,N))>0.02 THEN 6660
6500 LK=INT((LT1-LST)/LDT(I)+1.5)
6510 IF LK>100 THEN 6660
6520 LDR1=L11-LTHETA1(I,LK) LDR2=L21-LTHETA2(I,LK) LDR3=L31-LD3(I,LK)
6530 LDT=LT1-LT0
6540 LDW1=(L11-L10)/LDT-LW1(I,LK) LDW2=(L21-L20)/LDT-LW2(I,LK)
LDV3=(L31-L30)/LDT-LV3(I,LK)
6550 IF ABS(LDR1)>HC AND ABS(LDW1)<0.001 THEN 6570
6560 LSET1=LSET1-LDR1/C*.02-LDW1/C*.02
6570 IF ABS(LDR2)>HC AND ABS(LDW2)<0.001 THEN 6590
6580 LSET2=LSET2-LDR2/C*.02-LDW2/C*.02
6590 IF ABS(LDR3)<.015 AND ABS(LDV3)<0.005 THEN 6610
6600 LSET3=LSET3-LDR3+.5-LDV3+.5
6610 ACT 4 WAIT 0.016667
6620 L10=L11 L20=L21 L30=L31 LT0=LT1
6630 WAIT .05
6640 GOTO 6470
6650 @ TARGET REACHED, KEEP IT IN POSITION
6660 LALPHA1=LTHETA1(I,N) LALPHA2=LTHETA2(I,N) LTRAN3=LD3(I,N)
6670 TASK 1, 5200 ACT 1
6680 RETURN
6690 @
6700 #####
6710 @ SUBROUTINE FOR SHOWING THE LEFT ARM
6720 COLOR 0 GOSUB 3100 WAIT 0.016667 @ ERASE
6730 GOSUB 2830 COLOR 7 GOSUB 3100 @ SHOW
6740 RETURN
6750 @
```

```
6800 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@  
6810 @ TASK 4 FOR OUTPUTING LEFT CONTROLLING SIGNALS  
6820 AOT(LSLOT,OUT1)=LSET1 AOT(LSLOT,OUT2)=LSET2 AOT(LSLOT,OUT3)=LSET3  
6830 SUSP SELF  
6840 GOTO 6820  
6850 @  
6900 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@  
6910 @ TASK 3 FOR GETTING POSITION PARAMETERS FOR LEFT ARM  
6920 LT=TIMER  
6930 P1=AIN(0,IN1,0,0) P2=AIN(0,IN2,0,0) P3=AIN(0,IN3,0,0)  
6940 SUSP SELF  
6950 GOTO 6920  
6960 @  
7000 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@  
7010 @ SUBROUTINE FOR STOPPING RIGHT CUTTING HEAD WHERE IT IS  
7020 ACT 5 WAIT 0.016667 @ GET POSITION PARAMETERS  
7030 R10=RTHETA10+P4*RC1 R20=RTHETA20+P5*RC2 R30=RD30+P6*RC3  
7040 WAIT .10  
7050 ACT 5 WAIT 0.016667  
7060 R11=RTHETA10+P4*RC1 R21=RTHETA20+P5*RC2 R31=RD30+P6*RC3  
7070 IF R10=R11 AND R20=R21 AND R30=R31 THEN RETURN  
7080 IF R11>R10 THEN RSS1=RSS1-.05 AOT(RSLT,OUT4)=RSS1 GOTO 7100  
7090 IF R11<R10 THEN RSS1=RSS1+.05 AOT(RSLT,OUT4)=RSS1  
7100 IF R21>R20 THEN RSS2=RSS2-.05 AOT(RSLT,OUT5)=RSS2 GOTO 7120  
7110 IF R21<R20 THEN RSS2=RSS2+.05 AOT(RSLT,OUT5)=RSS2  
7120 IF R31>R30 THEN RSS3=RSS3-.05 AOT(RSLT,OUT6)=RSS3 GOTO 7140  
7130 IF R31<R30 THEN RSS3=RSS3+.05 AOT(RSLT,OUT6)=RSS3  
7140 R10=R11 R20=R21 R30=R31 GOTO 7040  
7150 @  
7200 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@  
7210 @ TASK 2 FOR MOVINNNG RIGHT ARM TO RALPHA1, RALPHA2, RTRAN3 POSITION  
7215 ON ERROR 183, 7220  
7220 ACT 5 WAIT 0.016667 @ GET POSITION PARAMETERS  
7230 R10=RTHETA10+P4*RC1 R20=RTHETA20+P5*RC2 R30=RD30+P6*RC3 RT0=RT  
7240 IF ABS(R10-RALPHA1)<HC THEN RSET1=RSS1 GOTO 7270  
7250 IF R10>RALPHA1 THEN RSET1=RSS1-RSET11 GOTO 7270  
7260 IF R10<RALPHA1 THEN RSET1=RSS1+RSET11  
7270 IF ABS(R20-RALPHA2)<HC THEN RSET2=RSS2 GOTO 7300  
7280 IF R20>RALPHA2 THEN RSET2=RSS2-RSET21 GOTO 7300  
7290 IF R20<RALPHA2 THEN RSET2=RSS2+RSET21  
7300 IF ABS(R30-RTRAN3)<.02 THEN RSET3=RSS3 GOTO 7330  
7310 IF R30>RTRAN3 THEN RSET3=RSS3-RSET31 GOTO 7330  
7320 IF R30<RTRAN3 THEN RSET3=RSS3+RSET31  
7330 WAIT .1  
7340 ACT 5 WAIT 0.016667 @ GET POSITION PARAMETERS  
7350 R11=RTHETA10+P4*RC1 R21=RTHETA20+P5*RC2 R31=RD30+P6*RC3 RT1=RT  
7360 RDF1=RALPHA1-R11 RDF2=RALPHA2-R21 RDF3=RTRAN3-R31  
7370 IF ABS(RDF1)>HC AND ABS(RDF2)>HC AND ABS(RDF3)>.02 THEN 7560  
7380 IF ABS(RDF1)>10*C THEN RW1=W1*S6N(RDF1) GOTO 7400  
7390 IF ABS(RDF1)<-10*C THEN RW1=-CC*W1*RDF1  
7400 IF ABS(RDF2)>10*C THEN RW2=W2*S6N(RDF2) GOTO 7420  
7410 IF ABS(RDF2)<-10*C THEN RW2=-CC*W2*RDF2  
7420 IF ABS(RDF3)>.333 THEN RV3=V3*S6N(RDF3) GOTO 7440  
7430 IF ABS(RDF3)<-0.333 THEN RV3=-3.0*V3*RDF3  
7440 IF ABS(RDF1)<HC THEN 7470  
7450 ROW1=(R11-R10)/(RT1-RT0)-RW1  
7460 RSET1=RSET1-ROW1/C*.1  
7470 IF ABS(RDF2)<HC THEN 7500  
7480 ROW2=(R21-R20)/(RT1-RT0)-RW2  
7490 RSET2=RSET2-ROW2/C*.1
```



```

7500 IF ABS(RDF3) .GT .02 THEN 7530
7510 RDV3=(R31-R30)/(RT1-RT0)-RV3
7520 RSET3=RSET3-RDV3
7530 ACT 6 WAIT 0.016667
7540 RT0=RT1 RI0=RI1 R20=R21 R30=R31
7550 GOTO 7330
7560 @ TARGET HAS BEEN REACHED
7570 GOSUB 7000
7580 RS=1
7590 GOTO 7220
7595 @
7600 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
7610 @ TASK 8 FOR RIGHT ARM MOVING AND CUTTING
7620 FOR J=1 TO NR @ NR PATHS
7630 @@@ MOVING THE ARM TO THE STARTING POINT @@@
7640 RTRAN3=-46/12 RS=0 @ RETREAT ARM
7650 KILL 2
7655 IF TSTATE(2)>-1 THEN 7650
7656 TASK 2,7200 ACT 2
7660 IF RS=0 THEN WAIT 0.5 GOTO 7660
7670 RALPHA1=RTHETA1(J,1) RALPHA2=RTHETA2(J,1) RS=0 @ MOVE
7680 KILL 2
7685 IF TSTATE(2)>-1 THEN 7680
7686 TASK 2,7200 ACT 2
7690 IF RS=0 THEN WAIT 0.5 GOTO 7690
7700 RTRAN3=RD3(J,1) RS=0 @ EXTEND ARM
7710 KILL 2
7715 IF TSTATE(2)>-1 THEN 7710
7716 TASK 2,7200 ACT 2
7720 IF RS=0 THEN WAIT 0.5 GOTO 7720
7730 @@@ START TO CUT @@@
7740 FOR RDI=1 TO 4 @ CUTTING THE COAL BACK AND FORTH 4 TIMES
7750 GOSUB 8300 @ CUTTING THE COAL
7760 IF RDI=4 THEN 7770
7762 GOSUB 8000 @ CHANGE PARAMETERS FOR DEEP CUTTING
7764 RALPHA1=RTHETA1(J,1) RALPHA2=RTHETA2(J,1) RTRAN3=RD3(J,1) RS=0
7765 KILL 2
7766 IF TSTATE(2)>-1 THEN 7765
7767 TASK 2,7200 ACT 2
7768 IF RS=0 THEN WAIT 0.5 GOTO 7768
7770 NEXT RDI
7780 NEXT J
7790 @ CUTTING IS FINISHED, RETURN TO HOME POSITION
7800 RALPHA1=R11 RALPHA2=R21 RTRAN3=-46/12 RS=0 KILL 2
7810 TASK 2, 7200 ACT 2 @ RETREAT
7820 IF RS=0 THEN WAIT 0.5 GOTO 7820
7830 RALPHA1=0 RALPHA2=0 RS=0 KILL 2 @ MOVE TO HOME POSITION
7840 TASK 2, 7200 ACT 2 @ MOVE
7850 IF RS=0 THEN WAIT 0.5 GOTO 7850
7860 @ COLOR 0 BOX 0.5, 6.2, 9, 0.6, 1 COLOR 7
7870 HPRINT 1, 5.9, "RIGHT SIDE CUTTING IS FINISHED."
7880 RSF=1
7890 WAIT 0.5 GOTO 7890
7895 @
8000 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
8010 @ SUBROUTINE FOR CHANGING THE RIGHT ARM PARAMETERS FOR DEEP CUTTING
8015 ON ERROR 101, 8270, ERRLINE
8020 NN=N+1 HN=M/2 DOC=.3
8030 FOR RI=1 TO HN
8040 RTEM=RTHETA1(J,RI)
```

```
8050 RTHETA1(J,RI)=RTHETA1(J,NN-RI)
8060 RTHETA1(J,NN-RI)=RTEM
8070 RTEM=RTHETA2(J,RI)
8080 RTHETA2(J,RI)=RTHETA2(J,NN-RI)
8090 RTHETA2(J,NN-RI)=RTEM
8100 RTEM=RD3(J,RI)
8110 RD3(J,RI)=RD3(J,NN-RI)-DOC
8120 RD3(J,NN-RI)=RTEM-DCC
8130 RTEM=RW1(J,RI)
8140 RW1(J,RI)=-RW1(J,N-RI)
8150 RW1(J,N-RI)=-RTEM
8160 RTEM=RW2(J,RI)
8170 RW2(J,RI)=-RW2(J,N-RI)
8180 RW2(J,N-RI)=-RTEM
8190 RTEM=RV3(J,RI)
8200 RV3(J,RI)=-RV3(J,N-RI)
8210 RV3(J,N-RI)=-RTEM
8220 NEXT RI
8225 RD3(J,HN+1)=RD3(J,HN+1)-DCC
8230 FOR RI=1 TO N
8240 IF RD3(J,RI)<-5.76 THEN RD3(J,RI)=-5.76   RV3(J,RI)=0
8250 NEXT RI
8260 RETURN
8270 @ ERROR TRAP
8271 IF ERRLINE=8040 THEN GOTO 8040
8272 IF ERRLINE=8050 THEN GOTO 8050
8273 IF ERRLINE=8060 THEN GOTO 8060
8274 IF ERRLINE=8070 THEN GOTO 8070
8275 IF ERRLINE=8080 THEN GOTO 8080
8276 IF ERRLINE=8090 THEN GOTO 8090
8277 IF ERRLINE=8100 THEN GOTO 8100
8278 IF ERRLINE=8110 THEN GOTO 8110
8279 IF ERRLINE=8120 THEN GOTO 8120
8280 IF ERRLINE=8130 THEN GOTO 8130
8281 IF ERRLINE=8140 THEN GOTO 8140
8282 IF ERRLINE=8150 THEN GOTO 8150
8283 IF ERRLINE=8160 THEN GOTO 8160
8284 IF ERRLINE=8170 THEN GOTO 8170
8285 IF ERRLINE=8180 THEN GOTO 8180
8286 IF ERRLINE=8190 THEN GOTO 8190
8287 IF ERRLINE=8200 THEN GOTO 8200
8288 IF ERRLINE=8210 THEN GOTO 8210
8290 ! "ERROR HAPPENED IN LINE ":ERRLINE RESET SUB END
8295 @
8300 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
8310 @ SUBROUTINE FOR KEEPING NOZZLE ALONG THE TRACK OF CUTTING PATH
8315 ON ERROR ERNUM', 8460
8320 KILL 2
8330 IF ABS(RW1(J,1))<0.001 THEN RSET1=RSS1 GOTO 8360
8340 IF RW1(J,1)<0 THEN RSET1=RSS1-RSET1! GOTO 8360
8350 RSET1=RSS1+RSET1!
8360 IF ABS(RW2(J,1))<0.001 THEN RSET2=RSS2 GOTO 8390
8370 IF RW2(J,1)<0 THEN RSET2=RSS2-RSET2! GOTO 8390
8380 RSET2=RSS2+RSET2!
8390 IF ABS(RV3(J,1))<0.001 THEN RSET3=RSS3 GOTO 8420
8400 IF RV3(J,1)<0 THEN RSET3=RSS3-RSET3! GOTO 8420
8410 RSET3=RSS3+RSET3!
8420 RST=TIMER
8430 ACT 6 WAIT 0.116667 @ OUTPUT SIGNALS
8440 ACT 5 WAIT 0.016667 @ GET POSITION PARAMETERS
```

```

8450 R10=RTHETA10+P4*RC1 R20=RTHETA20+P5*RC2 R30=RD30+P6*RC3 RT0=RT
8460 WAIT .1
8470 ACT 5 WAIT 0.016667 @ GET POSITION PARAMETERS
8480 R11=RTHETA10+P4*RC1 R21=RTHETA20+P5*RC2 R31=RD30+P6*RC3 RT1=RT
8490 IF ABS(R11-RTHETA1(J,N))<HC AND ABS(R21-RTHETA2(J,N))<HC AND ABS(R31-RD3
J,N))<0.02 THEN 8660
8500 RK=INT((RT1-RST)/RDT(J))+1.5
8510 IF RK>100 THEN 8660
8520 RDR1=R11-RTHETA1(J,RK) RDR2=R21-RTHETA2(J,RK) RDR3=R31-RD3(J,RK)
8530 RDT=RT1-RT0
8540 RDW1=(R11-R10)/RDT-RW1(J,RK) RDW2=(R21-R20)/RDT-RW2(J,RK)
RDV3=(R31-R30)/RDT-RV3(J,RK)
8550 IF ABS(RDR1)<HC AND ABS(RDW1)<0.001 THEN 8570
8560 RSET1=RSET1-RDR1/C*.02-RDW1/C*.02
8570 IF ABS(RDR2)<HC AND ABS(RDW2)<0.001 THEN 8590
8580 RSET2=RSET2-RDR2/C*.02-RDW2/C*.02
8590 IF ABS(RDR3)<.015 AND ABS(RDV3)<0.005 THEN 8610
8600 RSET3=RSET3-RDR3*.5-RDV3*.5
8610 ACT 6 WAIT 0.016667
8620 R10=R11 R20=R21 R30=R31 RT0=RT1
8630 WAIT .05
8640 GOTO 8470
8650 @ TARGET REACHED, KEEP IT IN POSITION
8660 RALPHA1=RTHETA1(J,N) RALPHA2=RTHETA2(J,N) RTRAN3=RD3(J,N)
8670 TASK 2, 7200 ACT 2
8680 RETURN
8690 @
8700 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
8710 @ SUBROUTINE FOR SHOWING THE RIGHT ARM
8720 COLOR 0 GOSUB 3200 WAIT 0.016667 @ ERASE
8730 GOSUB 2930 COLOR 7 GOSUB 3200 @ SHOW
8740 RETURN
8750 @
8800 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
8810 @ TASK 6 FOR OUTPUTING RIGHT CONTROLLING SIGNALS
8820 AOT(RSL0T,OUT4)=RSET1 AOT(RSL0T,OUT5)=RSET2 AOT(RSL0T,OUT6)=RSET3
8830 SUSP SELF
8840 GOTO 8820
8850 @
8900 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
8910 @ TASK 5 FOR GETTING POSITION PARAMETERS FOR RIGHT ARM
8920 RT=TIMER P4=AIN(0,IN4,0,0) P5=AIN(0,IN5,0,0) P6=AIN(0,IN6,0,0)
8930 SUSP SELF
8940 GOTO 8920
8950 @
9000 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
9010 @ ERROR TRAP
9020 IF ERLINE<2860 AND ERLINE>2810 THEN 2830
9030 IF ERLINE<2960 AND ERLINE>2910 THEN 2930
9040 IF ERLINE<3170 AND ERLINE>3110 THEN 3120
9050 IF ERLINE<3270 AND ERLINE>3210 THEN 3220
9060 ! "ERROR HAPPENED IN LINE ": ERLINE RESET SUB END
9070 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
10000 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
10010 @ SUBROUTINE FOR CONTROLLING THE ACTIONS OF CYLINDERS AND BOTTOM JETS IN
THE HIGH PRESSURE WATERJET MINER
10020 GOSUB 10100 @ GET BASIC DATA FOR SCREEN CONTROL AND OUTPUT PORTS
10030 GOSUB 10400 @ SET UP MENU FOR ACTIONS
10040 RETURN
10050 @

```

```

10100 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
10110 @ SUBROUTINE FOR ENTERING BASIC DATA
10120 DSLOT=3 @ DIGITAL I/O SLOT
10130 LU=1 LF=2 BL=3 RF=4 RU=5 @ CHANNELS FOR CYLINDERS
10140 LD=6 LB=7 BR=4 RB=9 RD=10
10150 @ SCREEN CONTROL CONSTANTS
10160 ESC=27 EQ=61
10170 NORMAL=183 REVERSE=180 BLINK=181
10180 BEEP=7 CR=13 LINE_DEL=166
10190 INV_CUR=185 VIS_CUR=186
10200 LEFT=8 RIGHT=12 UP=11 DOWN=10 SPACE=32
10210 STOP_ALL=83
10220 DOT(3,14,15)=0
10230 RETURN
10240 @
10400 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
10410 @ SUBROUTINE FOR SETTING UP MENU AND TAKING ACTIONS
10420 DIM ACTION(10)
10430 DATA "LEFT UP","LEFT FORWARD","BOTTOM LEFT","RIGHT FORWARD","RIGHT UP"
10440 DATA "LEFT DOWN","LEFT BACK","BOTTOM RIGHT","RIGHT BACK","RIGHT DOWN"
10450 SKIP=16 LAST=10 CHOICE=1 RR=44 COL=34
10460 FOR I=1 TO LAST ACTION(I)=0 NEXT I
10470 SET_NUM'=0
10480 CLS 0
10490 PNT NORMAL, INV_CUR
10500 ! ! ! " <UP>, <DOWN>, <LEFT>, <RIGHT> --- SELECT A CHOICE
10510 ! " <RETURN> --- ACTIVATE THE CHOICE
10520 ! " <S> --- STOP ALL ACTIONS
10530 ! " <ESC> --- RETURN TO MAIN MENU
10540 ! ! " A BLINKING ITEM MEANS IT IS IN ACTION."
10550 ! " TO ACTIVATE A BLINKING ITEM WILL STOP ITS ACTION."
10560 RESTORE
10570 FOR I=1 TO LAST
10580 READ S$
10590 COLUMN=(I-1)*SKIP+COL ROW=RR
10600 IF I>S THEN ROW=RR+2 COLUMN=COLUMN-S*SKIP
10610 IF I=CHOICE AND ACTION(I)=1 THEN PNT ESC,EQ,ROW,COLUMN,REVERSE,BLINK ! S$
GOTO 10650
10620 IF I=CHOICE THEN PNT ESC,EQ,ROW,COLUMN,REVERSE ! S$ GOTO 10650
10630 IF ACTION(I)=1 THEN PNT ESC,EQ,ROW,COLUMN,BLINK ! S$ GOTO 10650
10640 PNT ESC,EQ,ROW,COLUMN ! S$
10650 PNT NORMAL
10660 NEXT I
10670 INP SELECT'
10680 IF SELECT'=CR GOTO 10810
10690 IF SELECT'=STOP_ALL THEN 10940
10700 IF SELECT'=ESC THEN 10990
10710 IF SELECT'=UP AND CHOICE<6 THEN PNT BEEP GOTO 10670
10720 IF SELECT'=UP THEN CHOICE=CHOICE-5 GOTO 10790
10730 IF SELECT'=DOWN AND CHOICE>5 THEN PNT BEEP GOTO 10670
10740 IF SELECT'=DOWN THEN CHOICE=CHOICE+5 GOTO 10790
10750 IF SELECT'=LEFT AND (CHOICE=1 OR CHOICE=6) THEN PNT BEEP GOTO 10670
10760 IF SELECT'=LEFT THEN CHOICE=CHOICE-1 GOTO 10790
10770 IF SELECT'=RIGHT AND (CHOICE=5 OR CHOICE=10) THEN PNT BEEP GOTO 10670
10780 IF SELECT'=RIGHT THEN CHOICE=CHOICE+1 GOTO 10790
10790 IF DIN(3,12,13)=0 GOTO 10560
10800 GOTO 10670
10810 @ MAKE AN ACTION
10820 J=CHOICE IF (J=3) OR (J=8) GOTO 12000
10830 IF ACTION(J)=1 THEN GOSUB 11700 ACTION(J)=0 GOTO 10900

```

```

10840 IF J=5 GOTO 10870
10850 IF ACTION(J+5)=0 THEN GOSUB 11700 ACTION(J)=1 GOTO 10900
10860 J=J+5 GOSUB 11700 ACTION(J)=0 J=J-5 GOSUB 11700 ACTION(J)=1 GOTO 10
900
10870 IF ACTION(J-5)=0 THEN GOSUB 11700 ACTION(J)=1 GOTO 10900
10880 J=J-5 GOSUB 11700 ACTION(J)=0 J=J+5 GOSUB 11700 ACTION(J)=1
10890 @
10900 DOT(3,0,10)=SET_NUM'
10910 IF DIN(3,12,13)=0 GOTO 10560
10920 GOTO 10670
10930 @
10940 @ STOP ALL ACTIONS
10950 KILL ALL SET_NUM'=0
10960 FOR I=1 TO LAST ACTION(I)=0 NEXT I
10970 GOTO 10900
10980 @
10990 @ RETURN TO MAIN MENU
11000 KILL ALL SET_NUM'=0
11010 FOR I=1 TO LAST ACTION(I)=0 NEXT I
11020 @
11030 DOT(3,0,10)=SET_NUM'
11040 PNT NORMAL, VIS_CUR CLS
11050 RETURN
11060 @
11070 PNT VIS_CUR,NORMAL
11700 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
11710 @ SUBROUTINE FOR REVERSING DIGIT J FOR THE SET_NUM
11720 MASK='2^J
11730 SET_NUM'=SET_NUM' XOR MASK'
11740 RETURN
11750 @
12000 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
12010 @ ROUTINE FOR DEALING WITH THE BOTTOM MOVING PIECE
12020 IF DIN(3,12,13)<>0 GOTO 12120
12030 IF TSTATE(10)=-1 THEN GOTO 12070
12040 KILL 10
12050 IF ACTION(3)=1 THEN J=3 GOSUB 11700 ACTION(J)=0 GOTO 10900
12060 IF ACTION(8)=1 THEN J=8 GOSUB 11700 ACTION(J)=0 GOTO 10900
12070 GOSUB 11700 ACTION(J)=1 DOT(3,0,10)=SET_NUM'
12080 TASK 10,12200 ACT 10
12090 WAIT 0.016667
12100 GOTO 10560
12120 IF TATATE(10)<>-1 THEN GOTO 12040
12130 TASK 10,12200 ACT 10 WAIT .016667
12140 GOTO 10670
12200 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
12210 @ TASK 10 FOR MONITORING LIMIT SWITCHES
12220 AA'=DIN(3,12,13) IF AA'=0 THEN 12220
12230 PRIORITY 10
12240 IF AA'=1 THEN ACTION(3)=1 ACTION(8)=0 SET_NUM'=SET_NUM' OR 8 SET_NUM
'=SET_NUM' AND -257 GOTO 12260
12250 IF AA'=2 THEN ACTION(3)=0 ACTION(8)=1 SET_NUM'=SET_NUM' AND -9 SET_NUM'
=SET_NUM' OR 256
12260 DOT(3,0,10)=SET_NUM'
12270 GOSUB 12300 @ PRINT MENU
12280 WAIT 0.5 PRIORITY 1 GOTO 12210
12290 @
12300 @@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@
12310 @ SUBROUTINE FOR PRINTING MENU
12320 RESTORE

```

```

12350 FOR II=1 TO LAST
12340 READ SS$
12350 COLUMN1=(II-1)*SKIP+COL ROW1=RR
12360 IF II>5 THEN ROW1=RR+2 COLUMN1=COLUMN1-5*SKIP
12370 IF II=CHOICE AND ACTION(II)=1 THEN PNT ESC,EQ,ROW1,COLUMN1,REVERSE,BLINK
! SS$ GOTO 12410
12380 IF II=CHOICE THEN PNT ESC,EQ,ROW1,COLUMN1,REVERSE ! SS$ GOTO 12410
12390 IF ACTION(II)=1 THEN PNT ESC,EQ,ROW1,COLUMN1,BLINK ! SS$ GOTO 12410
12400 PNT ESC,EQ,ROW1,COLUMN1 ! SS$
12410 PNT NORMAL
12420 NEXT II
12430 RETURN
12440 @
13000 DATA 0, 3, 4.5, 3, 0, 5.5, 4.5, 5.5, 0, 0, 0, 5.5
13010 DATA 4.5, 3, 9, 3, 4.5, 5.5, 9, 5.5, 9, 0, 9, 5.5

```

Ready

END

**DATE
FILMED**

12 / 15 / 92