JUN 16 1995 58 ENGINEERING DATA TRANSMITTAL

Page 1 of 1
1. EDT 608947

2. To: (Receiving Organization) Solid Waste Management	3. From: (Originating Organization) Solid Waste Management	4. Related EDT No.: N/A
5. Proj./Prog./Dept./Div.: Low Level Burial Grounds	6. Cog. Engr.: L.J. Gaschott	7. Purchase Order No.: N/A
8. Originator Remarks: Attached is the Preliminary Fire Hazards Analysis developed to address transuranic drums in the burial grounds. The FHA which is being developed to encompass the entire Low Level Burial Grounds will rely heavily on the information in this report.		9. Equip./Component No.: N/A
		10. System/Bldg./Facility: LLBG
11. Receiver Remarks:		12. Major Assm. Dwg. No.: N/A
		13. Permit/Permit Application No.: N/A
		14. Required Response Date: 5/26/95

15. DATA TRANSMITTED					(F)	(G)	(H)	(I)
(A) Item No.	(B) Document/Drawing No.	(C) Sheet No.	(D) Rev. No.	(E) Title or Description of Data Transmitted	Approval Designator	Reason for Transmittal	Originator Disposition	Receiver Disposition
1	WHC-SD-WM-FHA-009		0	Preliminary Fire Hazard Analysis for the PUTDR and TRU Trenches in the Solid Waste Burial Ground	SQ	4/1		

16. KEY			
Approval Designator (F)	Reason for Transmittal (G)		Disposition (H) & (I)
E, S, Q, D or N/A (see WHC-CM-3-5, Sec.12.7)	1. Approval 2. Release 3. Information	4. Review 5. Post-Review 6. Dist. (Receipt Acknow. Required)	1. Approved 2. Approved w/comment 3. Disapproved w/comment 4. Reviewed no/comment 5. Reviewed w/comment 6. Receipt acknowledged

17. SIGNATURE/DISTRIBUTION (See Approval Designator for required signatures)										(G)	(H)
Reason	Disp.	(J) Name	(K) Signature	(L) Date	(M) MSIN	(J) Name	(K) Signature	(L) Date	(M) MSIN	Reason	Disp.
1	2	Cog.Eng. L.J. Gaschott	<i>L.J. Gaschott</i>	4/15/95	T4-03	Central Files		12-04		3	
1	2	Cog. Mgr. D.B. Powell	<i>D.B. Powell</i>	4/15/95	T4-03	O.S.T.I. (2)		A3-36		3	
1	1	QA D.L. Vance	<i>D.L. Vance</i>	6/16/95	T4-06						
1	2	Safety D.J. Hart	<i>D.J. Hart</i>	6/16/95	S2-42						
1	2	Fire Protection J.R. Keene	<i>J.R. Keene</i>	6/16/95	S2-42						
3		System Engr. R.R. Ames			N3-13						

18. L.J. Gaschott <i>L.J. Gaschott</i> Signature of EDT Originator	5/8/95 Date	19. _____ Authorized Representative for Receiving Organization	20. D.B. Powell <i>D.B. Powell</i> Cognizant Manager	4/15/95 Date	21. DOE APPROVAL (if required) Ctrl. No. ☐ Approved ☐ Approved w/comments ☐ Disapproved w/comments
---	----------------	--	---	-----------------	---

DISCLAIMER

Portions of this document may be illegible in electronic image products. Images are produced from the best available original document.

RELEASE AUTHORIZATION

Document Number: WHC-SD-WM-FHA-009, REV 0

Document Title: Preliminary Fire Hazard Analysis for the PUTDR and TRU Trenches in the Solid Waste Burial Ground

Release Date: 6/16/95

**This document was reviewed following the
procedures described in WHC-CM-3-4 and is:**

APPROVED FOR PUBLIC RELEASE

WHC Information Release Administration Specialist:

Kara M. Broz

June 16, 1995

TRADEMARK DISCLAIMER. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors.

This report has been reproduced from the best available copy. Available in paper copy and microfiche. Printed in the United States of America. Available to the U.S. Department of Energy and its contractors from:

U.S. Department of Energy
Office of Scientific and Technical Information (OSTI)
P.O. Box 62
Oak Ridge, TN 37831
Telephone: (615) 576-8401

Available to the public from:

U.S. Department of Commerce
National Technical Information Service (NTIS)
5285 Port Royal Road
Springfield, VA 22161
Telephone: (703) 487-4650

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

SUPPORTING DOCUMENT

1. Total Pages 83

2. Title

Preliminary Fire Hazard Analysis for the PUTDR and TRU Trenches in the Solid Waste Burial Ground

3. Number

WHC-SD-WM-FHA-009

4. Rev No.

0

5. Key Words

Low Level Burial Ground, LLBG, PUTDR, TRU Trenches, Fire Hazards Analysis, FHA, DOE 5480.7A

6. Author

Name: L.J. Gaschott

L.J. Gaschott
Signature

Organization/Charge Code 87250/76039

7. Abstract

This document represents the Preliminary Fire Hazards Analysis for the Pilot Unvented TRU Drum Retrieval effort and for the Transuranic drum trenches in the low level burial grounds. The FHA was developed in accordance with DOE Order 5480.7A to address major hazards inherent in the facility.

8. RELEASE STAMP

OFFICIAL RELEASE 58
BY WHC
DATE JUN 16 1995
Sta # 3

Preliminary Fire Hazard Analysis
for the PUTDR and TRU Trenches
in the Solid Waste Burial Ground

WHC-SD-WM-FHA-009 Rev. 0

Prepared for

Westinghouse Hanford Company
P.O. Box 1970
Richland, Washington, 99352

Prepared by

Hughes Associates, Inc.
6770 Oak Hall Lane, Suite 125
Columbia, Maryland 21045
(301) 596-2190
FAX (301) 596-2295

November 23, 1994

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

35 **MASTER**

Table of Contents

	Page
1.0 INTRODUCTION	1
2.0 SUMMARY AND CONCLUSIONS	1
3.0 DESCRIPTION OF CONSTRUCTION	3
4.0 FIRE PROTECTION FEATURES	3
5.0 DESCRIPTION OF FIRE HAZARDS	5
5.1 General	5
5.1.1 Failure of Drums Exposed to a Diesel Fuel Fire – Worst Case Drum Exposure	6
5.1.1.1 Test Conditions	7
5.1.2 Hypothesized Pool Fire Exposure	9
5.1.3 Burning of Plywood Layer(s)	13
5.1.4 Drum Array Pile Dynamics	14
5.1.4.1 Backfilled Drum Array	17
5.1.5 Drum Burning	17
5.1.6 Drum to Drum Fire Propagation	18
5.1.6.1 Drum to Drum Propagation via Radiation	18
5.1.6.2 Drum to Drum Propagation via Expulsion of Burning Contents	34
5.1.6.3 Summary of Drum to Drum Fire Propagation Analyses	36
5.1.7 Hazardous Materials Contribution	36
5.2 Scenario Hazard Assessments	39
5.2.1 Scenario 1: 50 gallon spill of diesel at the edge of the drum array	39
5.2.2 Scenario 2: 50 gallon spill of diesel in a 8 ft by 8 ft void in the drum array	44
5.2.3 Scenario 3: Burning tumbleweed along edge of the drum array	47
6.0 PROTECTION OF ESSENTIAL SAFETY CLASS SYSTEMS	48
7.0 LIFE SAFETY CONSIDERATIONS	48
8.0 CRITICAL PROCESS EQUIPMENT	48
9.0 HIGH VALUE PROPERTY	48

Table of Contents (Continued)

	Page
10.0 DAMAGE POTENTIAL	48
10.1 Maximum Credible Fire Loss (MCFL)	49
10.2 Fire Department Intervention Effectiveness	49
11.0 FIRE DEPARTMENT/BRIGADE RESPONSE	52
12.0 RECOVERY POTENTIAL	52
13.0 POTENTIAL FOR A TOXICOLOGICAL, BIOLOGICAL, AND/OR RADIOLOGICAL INCIDENT DUE TO A FIRE	52
14.0 EMERGENCY PLANNING	53
15.0 SECURITY AND SAFEGUARDS CONSIDERATIONS RELATED TO FIRE PROTECTION	53
16.0 NATURAL HAZARDS IMPACT ON FIRE SAFETY	53
17.0 EXPOSURE FIRE POTENTIAL	54
18.0 RECOMMENDATIONS	54
19.0 REFERENCES	55
Appendix A – Review of Fire Test Literature on Solid Waste Drum Storage	59
Appendix B – Drum Array Stability Models	63

List of Figures

	Page
Figure 1 Backfilled Drum Array	4
Figure 2 ANSI MH2-1991 DOT 17C Drum Dimensions	10
Figure 3 Drum and Void Plan Areas	12
Figure 4 Plan View of Drum Array Heat Transfer	20
Figure 5 Plan View of a Drum Defining the Hote Wall Section	22
Figure 6 Definition of Geometry for the Plate to Cylinder Configuration Factor	25
Figure 7 Plan View for One Drum Burning Analysis	27
Figure 8 Definition of Geometry for Parallel Plate Configuration Factors ...	28
Figure 9 Definition of Geometry for Adjacent Plate Configuration Factors ..	28
Figure 10 Plan View of Three Burning Drums Exposing One Adjacent Drum	30
Figure 11 Drum Array Void Plan	45

List of Tables

	Page
Table 1 Large Scale Pool Fire Maximum Average Heat Flux Measurements	8
Table 2 Number of Simultaneous Drum Lid Failures Needed to Topple an Eight Drum per Tier Array for a Range of Average Lid Release Pressures	17
Table 3 Fire Suppression Timetable for Scenario 1	50
Table 4 Fire Suppression Timetable for Scenario 2	51

Solid Waste Burial Ground Fire Hazard Analysis

1.0 INTRODUCTION

A fire hazard analysis (FHA) was performed for the Solid Waste Burial Ground (SWBG) PUTDR and TRU Trenches at the Department of Energy (DOE) Hanford site. The analysis was conducted in accordance with DOE Order 5480.7A, Fire Protection (DOE Order 5480.7A (2/17/93)) and addresses each of the fifteen principle elements outlined in paragraph 9.a.(3) of the Order. The "Guidance on Performance of Fire Hazard Analyses" (DOE EH-31.3 (1991)) was also used to guide the conduct of the analysis.

This FHA was completed in draft form prior to the initiation of a testing and modeling task by HAI with regards to fire propagation in solid waste drums. The final version of this FHA was completed while the testing and model development task was still underway and this FHA does not make use of specific work from that task. This FHA should be reviewed upon completion of that task to evaluate the potential impact of insights and results from that task on this FHA.

2.0 SUMMARY AND CONCLUSIONS

The analysis included three fire scenarios identified in the SWBG that were considered plausible candidates for Design Based Fire (DBF). The three scenarios were as follows:

- (1) Diesel fuel (50 gal) was spilled at the edge of a drum array as a result of an accident involving drum handling equipment. The pool ignites, exposing the drum array;

- (2) During drum removal as part of the Pilot Unvented TRU Drum Retrieval Effort, a void in the drum array measuring 8 ft by 8 ft was created in the array which was originally soil covered. Diesel fuel (50 gal) was spilled in the void, exposing the drum array;
- (3) Tumbleweeds accumulates along the edge of the drum array within the trench. The tumbleweed is ignited and fire propagates along the drum array edge, exposing the drum array.

The mechanisms for involvement of drum combustible contents are violent lid loss due to fire induced overpressurization of the drum and damage to the drum/lid due to mechanical forces associated with falling drums. While some additional release may occur due to the loss of lid seal integrity without lid loss, these contributions are shown to be minor compared to burning of drum contents from drums which experience lid loss. While the analysis showed that the drum arrays are quite stable and can resist toppling due to drum lid releases, the plywood used between tiers of the array is critical to this stability. Stability is ultimately lost due to burning of the plywood during pool fire exposure. The plywood alone is insufficient as a fuel to cause drum lid failures. The analysis provided burning rate and fire duration information based on the burning of combustibles in the drums. For the packing densities generally found in these drums, the heat release rates are modest (75 kW/drum), but the duration is quite long (3 hours).

Scenario 2 was found through analysis to represent the worst case scenario, resulting in the burning of the contents of up to 56 drums. The burning of the drums was estimated to continue for up to 3 hours with a heat release rate of about 4.2 MW without any intervention. The dispersion of radioactive material in the fire plume was calculated and contamination estimates were made. Recommendations to limit drum involvement include the investigation of the use of nylon bungs to serve as pressure relief devices to prevent violent lid loss.

3.0 DESCRIPTION OF CONSTRUCTION

The Solid Waste Burial Ground (SWBG) is an array of trenches designed for the storage of radioactively contaminated solid waste. A large percentage of the containers are 55 gallon drums. The base of each TRU trench is paved with asphalt which forms the foundation for the drum array. The drums are stacked 12 wide, 4 high, and 12 deep. A small gap of 1-2 feet is allowed between 12 x 4 x 12 drum arrays. From a practical viewpoint, the storage may be viewed as 12 wide by 4 high with a depth equal to the length of the trench. The drums are arranged in a tight regular array with only incidental spacing between drums. The layers of the array are separated by 0.75-inch plywood sheeting to form a stable base for the next layer. These characteristics are uniform over the burial site for uncovered TRU drums.

Other additional storage configurational elements vary from location to location within the burial ground site. Historically, the drum arrays have been covered with soil (see Figure 1). In the soil covered configuration, 0.25 inch plywood is used between tiers and the top of the 4 layer array is covered with 0.75-inch plywood. This is then covered with vinyl sheeting. A 2-inch diameter PVC vent pipe is inserted into the array at about 6 drum intervals along the length of the trench. The array is then covered with soil. More recently, the practice has been to not cover the drum arrays with soil. As such, there are areas of storage which include the 0.75-inch plywood and vinyl sheeting but without soil as well as areas where the 4 layer drum array is not covered at all.

4.0 FIRE PROTECTION FEATURES

There are no fixed fire protection systems for the SWBG. A trained, fully staffed fire department is maintained at the Hanford site which is staffed on a 24 hour, seven day per week basis. The response time of the fire department to the SWBG is estimated to be 5 minutes. Hydrants are available on the perimeter of the SWBG site for use in firefighting.

Figure 1. Backfilled Drum Array

5.0 DESCRIPTION OF FIRE HAZARDS

5.1 General

Three fire initiation scenarios have been identified for the SWBG drum arrays. These scenarios are as follows:

- (1) Fifty gallons of diesel fuel is spilled at the edge of the drum array. Fuel can burn adjacent to the drum array or within the drum array. The fuel spill results from an accident involving heavy equipment being used to place or remove drums from the array.
- (2) During the removal of drums from the array, drums may be removed to form an 8 ft by 8 ft void in the drum stack. Fifty gallons of diesel fuel is spilled within this void and may flow within the drum array.
- (3) Tumbleweeds can accumulate along the edges of the drum array. Due to a wildland fire, these tumbleweeds are ignited and fire spreads along the drum array edge, exposing the edge drums to an external heat source.

Before analyzing these scenarios specifically, it is necessary to develop the concepts/tools that will be used in the analysis.

The major hazard of a fire involving the drum array is the release of radioactive material from the drums. As such, failure of the drums is a critical element of any fire scenario in the SWBG. Appendix A summarizes the available test data for fires exposing 55 gallon drums with either no contents or filled with solid waste. The exposing fires are all pool fires in these experiments. Appendix A also includes an investigation of the effects of hydrogen explosions within 55 gallon drums. All the available data indicate that drums fail by lid loss due to an overpressure of 8 to 20 psi. Further, the DOT requirements for 17-C drums requires the drum to contain a 20 psi overpressure (ANSI (1991)). These

independent sources of data, indicating a release pressure of 20 psig or less, give great credibility to this as a conservative release pressure for purposes of predicting the force of drum failure on array stability. Drums fully exposed to a pool fire environment have been found to fail by lid loss in 3-7 minutes of exposure with only about 15 percent of drum lids failing violently (i.e. with displacement of the lid from the drum). The 3-7 minute exposure time includes drums loaded with combustibles as well as empty drums. Empty drums tend to fail more rapidly than filled drums. Noncombustibles were not included in any of the drum contents.

There are several phenomena which may occur when drums are exposed to fire. The most dramatic is violent lid failure which results in total lid removal and allows burning of the contents. In this report this is called lid loss failure. Loss of containment can also occur without the loss of the lid. The lid seal can be destroyed by the fire, creating an escape path for gases in the drum. This will be referred to as lid seal failure. Air will not be able to enter the drum with damaged seals at the rates required to support flaming combustion. However, pyrolysis gases generated within the drum can escape.

5.1.1 Failure of Drums Exposed to a Diesel Fuel Fire – Worst Case Drum Exposure

The worst case drum response to an exposure fire is that reported in the second test of Series B of the Sandia tests (Sandia (1979)). In this test, the lid of an unloaded, unlined, sealed drum was blown off after 3 minutes of fire exposure when the internal pressure of the drum was 20 psig (138 kPa). It was found in the research work reviewed in Appendix A that combustible drum contents tended to slow the drum lid failure. As such, the three minute exposure criterion is conservative for loaded drums. It should be noted that this worst case drum was also not in a drum array so that heat transfer to the drum was greater than expected in a tight pack drum array.

5.1.1.1 Test Conditions

The test conditions involved two such drums in a shallow burn pan containing 5 gallons (0.0189 m³) of diesel fuel. The exact size of the pan is not reported, but the fire is reported to have consumed the fuel in 6.5 minutes. Since diesel fuel is available in several grades and the data needed to appraise the potential burning rate are not specifically reported in available standard references, the values reported by Babrauskas (1988) in the SFPE Handbook for kerosene were used as the closest approximation available. At a specific gravity of approximately 0.82, 5 gallons of diesel fuel (i.e., kerosene) weigh approximately 34.2 lb (15.5 kg). The estimated burning rate is based on the pool fire burning rate equation presented by Babrauskas (1988). That equation is as follows:

$$\dot{m}'' = \dot{m}_x'' (1 - e^{-k\beta D}) \quad (1)$$

where $\dot{m}''$ = mass burning rate per unit area,
 $\dot{m}_x''$ = maximum burning rate per unit area (for large diameter pools) {0.039 kg/m²-s for kerosene},
 $k\beta$ = product of the extinction-absorption coefficient of the flame and the mean-beam-length corrector {3.5 m⁻¹ for kerosene (Babrauskas (1988))}, and
 D = pool diameter.

Assuming that the fire burned at near full intensity for 6 minutes (360 s), the burning rate would be 43 g/s (i.e., 15.5 kg/360 s). Assuming a burning rate of 0.039 kg/m²-s, the burning surface is approximately 1.1 m². Converting this area to an equivalent circular pool produces a pool diameter of 1.2 m. Using Equation (1), above, the calculated burning rate per unit area is 0.0384 kg/m²-s. Based on the closeness of this result to the maximum burning rate, the maximum burning rate of 0.039 kg/m²-s is used.

The Sandia report indicates that wind conditions blew the flame towards the drum that failed. In a quiescent condition, the flame from such a fire would be about 10 ft (3 m) high. For purposes of this analysis, it is assumed that the wind conditions assured that all

exposed surfaces (i.e., the vertical sides and the top) were subjected to direct flame impingement. Table 1 is a compilation of data from large scale pool fire tests where the incident flux emitted by a flame have been measured.

Table 1. Large Scale Pool Fire Maximum Average Heat Flux Measurements

Large Calorimeters	kW/m ²
Gregory, Mata, Keltner (1987)	120
Wachtell and Langhaar (1966)	85
Anderson et al. (1974)	100
National Academy of Science (1973) (average of data in the literature pre-1970)	110
Moodie (1987)	100
McLain (1988)	85*
Taylor et al. (1975)	75*
Small Calorimeters	kW/m ²
Russell and Cansfield (1973)	170
Gregory, Keltner and Mata (1987)	160

* Object size comparable to pool fire.

The heat fluxes in these tests ranged between 75 and 120 kW/m² for large calorimeters. The tests by Taylor et al. (1975) and McLain (1988) involved situations where the object size was approximately comparable to the pool fire size. These tests, which produced the lowest heat flux to the target, are the tests that most nearly simulate the conditions in the Sandia tests. For this analysis, a conservative assumption of an average heat flux of 60 kW/m² is assumed (i.e., indicating a lower energy input needed to cause the drum to fail.)

The average heat flux of 60 kW/m² chosen is less than the average fluxes determined from McLain (1988) and Taylor's (1975) data. This is a reflection of the fact that the heat

fluxes were deduced by HAI from the test data in these references. In particular, the time rate of change of the liquid temperature in the container was used to deduce the heat fluxes. Since the experiments were not specifically designed to determine the flux and certain assumptions needed to be made in making these estimates, it is prudent to use a conservative value which is less than the two experimental determinations.

The drum dimensions were assumed to be those reported in ANSI Standard MH2-1991 (ANSI (1991)). Figure 2 is a diagram abstracted from that standard showing drum dimensions. Each drum is approximately 34.75 inches (0.88 m) high with a diameter of 22.5 inches (0.57 m). This produces an exposed area of 20 ft² (1.8 m²) receiving an energy input of 60 kJ/s-m² for 180 s to produce failure. The calculated energy input for failure using these conservative assumptions is 19.4 MJ. Most of the drums exposed to pool fire conditions in the Sandia tests failed after 6 to 7 minutes of exposure and required approximately 40-45 MJ of incident energy to produce failure. Violent lid failures in the LLNL tests occurred in 3-4.5 minutes. As such, the range in estimated energy exposure is 20-45 MJ for drums exposed to a pool fire around their full perimeter.

5.1.2 Hypothesized Pool Fire Exposure

a. Potential Energy. Based on the density of kerosene as reported by Babrauskas (i.e., 820 kg/m³) fifty gallons of diesel fuel weigh approximately 342 lb (155 kg). At an estimated heat of combustion of 40 kJ/g the total potential heat output is 6,200 MJ. Ignoring any heat losses, this would be sufficient to provide 19.4 MJ to approximately 300 drums. The use of the minimum energy required and ignoring heat losses makes this a very conservative estimate. This estimate could only be achieved by placing the drums and fuel in an adiabatic bomb. Clearly heat losses and many other factors make this estimate an unachievable worst case. More realistic estimates follow.

ANSI MH2-1991

3.4.7 Tolerances

Diameter over rolling hoops.....	23-13/32 in (595 mm) minimum
	23-15/32 in (596 mm) maximum
Overall height.....	34-3/4 in $\pm$ 1/8 in (883 mm $\pm$ 3.18 mm)
All other height dimensions	$\pm$ 1/8 in ($\pm$ 3.18 mm)
Center-to-center fitting	17-1/2 in $\pm$ 1/4 in (444 mm $\pm$ 6.35 mm)
Convexity of each head	9/16 in $\pm$ 3/16 in (14.3 mm $\pm$ 4.76 mm)
All other dimensions	$\pm$ 1/16 in ($\pm$ 1.59 mm)

NOTES:

- (1) All metric units are rounded, where required, in accordance with the procedure given in 2.2.1.2.
- (2) This dimension is applicable to both the top and bottom heads.

Figure 2. ANSI MH2-1991 DOT 17C Drum Dimensions

AND 03-111-11A-009 Rev. 0

b. Heat Transfer Assessment. The hard surface under the drum stacks is not perfectly flat. It is assumed, however, that any diesel fuel that would flow under drums would not burn in that position but would eventually flow to an uncovered portion of the hard surface and feed the fire. Based on the rolling hoop diameter of 0.595 m, it is assumed that each drum stack occupies an area 0.61 m by 0.61 m (0.37 m^2) to account for minimal drum to drum spacing of about 1 cm. Given a drum area of 0.27 m^2 , the area available for fire within the pile is 0.1 m^2 per drum. The assumed geometry is shown in Figure 3.

The diameter of a pool fire of the same area would be 0.35 m. Applying Equation (1) produces an expected burning rate of $0.028 \text{ kg/m}^2\text{-s}$. Based on the expected heat of combustion of 40 kJ/g and an area of 0.1 m^2 per drum, the expected resultant rate of heat release per drum enclosed space is 112 kW.

The maximum average convective heat flux to the drums due to flame contact is about 10 kW/m^2 , or 18 kW over the 1.8 m^2 area of the drum. The maximum radiative flux can be estimated by the total radiative output of the flame. The radiative fraction for hydrocarbon fuels is approximately 0.35 (McCaffrey (1981)) so that the maximum radiative heat flow to the drum is 39 kW. In order to transfer 19.4 MJ to the drum to cause lid failure would require a burning time of 340 s or 5.6 minutes. This same analysis can be applied to the LLNL test configuration, where the drums are not as tightly packed, but appear to have about a 4-inch drum to drum clearance. This increased spacing enlarges the pool area to about 2.5 ft^2 per drum and produces a heat release per drum of greater than 250 kW. Using this heat release requires 3 minutes to allow 19.4 MJ to be transferred to the drum. This illustrates the importance of the tight drum spacing in determining failure time.

Using this more realistic heat transfer based analysis shows that 0.95 kg of fuel must be burned per drum in the tight-packed array configuration to cause lid failure. Given the 155 kg of fuel available, this yields a maximum drum lid loss of 163 drum lids.

Figure 3. Drum and Void Plan Areas

c. Worst Case Exposing Pool Fire within the Array. The worst case fire pool that spreads so that the burning duration is just sufficient to heat the drums to cause lid failure and possible loss. Section (a) above limits this area to 300 drums, and the more detailed analysis of Section (b) indicates that about 163 bottom tier drums lids could fail. Both these assessments are conservative in that they ignore the limitations on air supply to the interior of the drum array. Both assume that the fire duration at a given location is just sufficient to cause lid loss and no longer, and both assume that the pool fire is fully within the drum array where more efficient heating of drums is possible. As such, 163 drums heated to potential lid loss by the pool fire represents a conservatively high estimate of potential drum involvement in fire for pool fire exposure of drums in the array.

5.1.3 Burning of Plywood Layer(s)

a. Burn Through. The report of the ASTM round robin tests of the cone calorimeter (ASTM (1990)) indicates the average rate of heat release from pine as 106 kW/m^2 when tested in the horizontal position with an incident flux of 25 kW/m^2 and similar average heat release rates of 153 kW/m^2 when exposed to an incident flux of 50 kW/m^2 . Recent tests by HAI showed rates of heat release of 116 and 130 kW/m^2 for samples of pine tested in the cone calorimeter in the horizontal position when exposed to incident fluxes of 25 and 50 kW/m^2 , respectively. In these tests, the effective heat of combustion for pine was reported as 10 to 12 kJ/g. For this analysis, the heat release rate for plywood is assumed as 120 kW/m^2 , and the assumed effective heat of combustion is 15 kJ/g. This produces a mass loss rate of approximately $8 \text{ g/m}^2\text{-s}$. Given an estimate density of 500 kg/m^2 for a typical plywood (Gross (1985)), the fire should burn through the 0.25-inch (6 mm) plywood in about 5 or 6 min. This indicates an average penetration rate of about 1/20 inch (1.2 mm/min). This is approximately twice as fast as the 1/40 inch (0.6 mm/min), traditionally attributed to wood and so reported by T.T. Lie (1972). Butler (as reported in Drysdale (1985)) also measured penetration rates of up to 1/20 inch/min at flux levels characteristic of fire exposures. The calculated 1/20 inch/min (1.2 mm/min) value is used in this analysis as the more conservative approach. The differences in using 1/20 inch/min rather than 1/40

inch/min is significant. Using the 1/20 inch/min value yields burning through times of 5 and 15 minutes for 1/4 inch and 3/4 inch thick plywood, respectively.

The above analysis also ignores the effect of moisture on the behavior of the plywood. Atreya and Abu-Zaid (1991) have documented the effect of moisture on ignition times. At 35 kW/m^2 , the highest flux they tested, the ignition time changed from 25 s for dry wood to 100 s for 27 percent moisture content. Lie (1972) indicates that penetration rates in wood are reduced by 20 percent for changes in moisture from 5 percent (about normal dry wood) to 20 percent moisture.

With a 5-6 minute burn through time, it is clear that a reduced pool fire area with the drum array of greater duration would cause fewer drums to fail for the same amount of fuel. This is most clear when one considers that in order to cause failure of second tier drum after plywood burn through, the already failed drums in the first tier would continue to be heated and thus essentially wasting energy in terms of causing drum failures. Thus, the largest number of potential lid failures for in-pile pool exposures is obtained if the failures are all on the lowest tier.

b. Impact of Plywood. Only that portion not covered by drums will burn while the array is in place. The area of exposed plywood is 0.1 m^2 (1.1 ft^2)/drum. With a burning rate of 120 kW/m^2 over 0.1 m^2 for a burning time of 15 min. (3/4 inch thick plywood), this produces a total energy release of 10.8 MJ, considerably less than the 19.4 MJ estimated to have been required to cause failure of the worst performing drum in the Sandia test series, and ignores the considerable heat losses. On this basis, it is concluded that plywood burning would not be sufficient to cause drum failure.

5.1.4 Drum Array Pile Dynamics

While tests have shown that drums fail by violent lid loss failure, there are no data which demonstrate that such behavior of drums in a multi-tiered array can cause opening of the drum whose lid failed or to cause other drums to be dislodged from the drum array.

The only multi-tiered drum tests conducted did not have sealed lids (Brown (1979)) so that pressure buildup within the lowest tier drums did not reach 20 psig before venting. Nonetheless, the drum array remained in place, and no drum contents burned in these tests. Further, even in hydrogen explosion tests conducted with a second drum atop the ignited drum, the lid of the ignited drum failed but was not dislodged from the drum (Beers (1983)). As such, all available evidence points toward the conclusion that the drum lids which fail while a loaded drum is above it in the array do not become dislodged and the array is not toppled.

Unfortunately, the experimental evidence is not alone compelling because of the lack of lid seals in the multi-tier testing. Models developed in Appendix B can be used to analytically assess the stability of small drum arrays subjected to drum lid failures. The models formulate the problem as a rotational stability analysis. The lid failure imparts angular momentum to the drums above the failed lid, and the analysis assesses the stability of the drum array through a simple dynamics simulation. Venting of the drum pressure as the lid rotates is included in the model.

A model was initially formulated for a single stack of drums. Later, the model was generalized to small drum arrays. This model was envisioned for use for up to eight drum stacks which can be accommodated on a 4 ft by 8 ft sheet of plywood. Both models are considered to be quite conservative in that the interlocking aspects of the plywood which impart significant stability are not fully included in the model. The models are not intended to represent the interlocking drum array, but rather to model a simpler array which is less stable than the actual arrays. This conservatism is expected to be significant as can be seen in the discussion of the model in Appendix B.

Results using the single stack indicated that a four tier array with a drum mass of 80 kg the stack was not stable. For this stack, the drum lid release pressure needed to be reduced to 3 psig to prevent loss of stability. This result indicates the importance of the plywood in allowing the stacks to act as a unit rather than each stack reacting individually.

The low stability of the drum array in the absence of plywood was well recognized in the design of the array.

Calculations with a four tier, eight drums per tier array indicated that the array was quite stable for single drum lid failures. In fact, three simultaneous lid releases out of the eight base drums were required to cause the array to topple with a 20 psi lid release pressure. It is important to note that the time scale for the stack dynamic response is measured in fractions of a second so that simultaneous lid failure would essentially require the lids to fail over a period of 100 ms to approach simultaneous behavior. Given that the observed range of failure times in the tests summarized in Appendix A is 3-7 minutes and only 15 percent of the drum lids fail violently, three simultaneous failures is not a credible event. From this, we must find that the drum array is stable for bottom tier lid failures.

Additional calculations were performed for 2, 3, and 4 tier stacks with release pressures of 10, 15, and 20 psig. The results are shown in Table 2. As one would expect, as the stack height decreases, the number of simultaneous lid failures required to topple the stack also decreases. Also as the release pressure decreases, the number of simultaneous lid failures increases. The trend with pressure in the four tier case is not as regular as one might expect due to the discrete number of drums. The 15 psig, three drum lid release just barely caused toppling. The 10 psig result of seven drums includes drum lids in the drum row nearest the point of rotation which are less effective in their contribution to the angular momentum due to their reduced moment arm about the point of rotation.

Given that the average lid release pressure in the LLNL (1993) tests was about 10 psig and only 15 percent of the drums failed violently as required to contribute to array destabilization, Table 2 illustrates that destabilization of even a two tier array is not expected. Even for the two tier case, 2-3 lids (25-37 percent of drums in the tier) must fail simultaneously to topple the array. Given these results for a simplified array less stable than those found in the SWBG, it must be concluded that the drum arrays are stable against drum lid failures.

Table 2. Number of Simultaneous Drum Lid Failures Needed to Topple an Eight Drum per Tier Array for a Range of Average Lid Release Pressures.*

Stack Height	10 psig	15 psig	20 psig
Four Tier**	7	3	3
Three Tier	4	3	2
Two Tier	3	2	2

- * These are the minimum number of simultaneous lid failures with failures in the most destabilizing drum lid locations, i.e., the row away from the point of rotation.
- ** Lid failures are in the lowest tier, so a two tier scenario represents lid failures in the third tier of a four tier array, and a four tier scenario represent lid failure in the first tier of a four tier array.

5.1.4.1 Backfilled Drum Array

We have established that the plywood could not propagate the failure of drum lids through the array. This assessment does not depend on any assumptions about the availability of air. Further, we have shown that the drum array is stable to lower tier drum lid failures. The backfill of the drum arrays adds to the fire safety in three important ways. First, the backfilled area cannot be the area of fire origin due to the insulating/isolating property of the fill. Second, the backfill seriously limits air availability in the array to support combustion. Finally, the backfill adds additional stability to the drum array subjected to a drum lid failure. Given the inherent safety of the drum arrays as already discussed and these additional safeguards, it is not possible to cause fire involvement of drum contents in portions of any trench which is backfilled.

5.1.5 Drum Burning

Based on the detailed drum contents survey of Joyce (1993), the average combustible load in a drum is 26 kg. In estimating a heat release rate for the drum, we will consider the drum contents as analogous to trash bags. The burning rates of trash bags is reviewed by

Babrauskas (1988). The heat release rate is determined by the size of the source in terms of its diameter and the packing density of the material. Of course, the drum diameter is 0.6 m and based on the 26 kg load has a packing density of 92 kg/m^3 . For these characteristics, the heat release rate as correlated by Babrauskas (1988) is about 75 kW. Using an average heat of combustion of 30 kJ/g for mixed cellulosic and plastics (15 kJ/g for cellulose and 40 kJ/g for common plastics (Tewarson (1988)) gives a burning rate of 2.35 g/s and a burning time of 3 hours.

If the SWBG drums are assumed to be represented by 95th percentile drum as documented by Joyce (1993), the burning rates would be reduced and the duration would be extended. The 95th percentile drum in the Joyce (1993) report included 42 kg of combustibles. This increases the combustible density to 150 kg/m^3 . This is outside the range correlated in Babrauskas (1988). If we made the reasonable assumption that the heat release is reduced to 50 kW, the burning duration would increase to 7 hours.

The burning times calculated in this section are for individual drums. It is expected to apply to arrays of multiple drums whose lids have been removed.

5.1.6 Drum to Drum Fire Propagation

Fire propagation through a drum array away from the initiating source requires that the contents of the drums to burn. This, in turn, requires that drums fail by lid loss. We have seen in the analysis of these phenomena that lid loss can only occur on the top tier of the array or by drum stack toppling after the plywood is burned through.

The drums which topple, open, and burn are thrown away from the remainder of the array during toppling. As such, there is a natural separation of the burning drums from the remaining array which reduces the ability of the burning contents to damage the array drums. The lowest tier of the toppled row is expected to remain in place or fall by simple rotation. In either case, drum contents will not be in direct contact with the second row of drums. Those first row drums most likely to lose their contents due to falling will also tend

to be thrown the farthest from the array. Given this separation and the low burning rate of drum contents, it is not expected that the fire exposure to the second row drums and plywood would be sufficient to cause lid loss and plywood burn through. The plywood burn through is particularly critical and the separation of the contents fire and the edge on configuration factor between the contents fire and the plywood is not favorable for plywood heating.

The top tier drums can fail by lid loss and burn. There are two potential mechanisms for fire propagation resulting from lid loss. First, the contents of the drum may remain in the drum and burn in place. This leads to radiative heating of the adjacent drums, which may cause lid loss and involvement of these adjacent drum contents. Second, the contents of the drum may leave the drum during lid loss. The burning contents will then land on drums not yet burning and may cause these drums to experience lid loss. These mechanisms will be evaluated in the following subsections.

5.1.6.1 Drum to Drum Propagation via Radiation

A heat transfer analysis is considered for a single tier array of 55-gallon storage drums in order to determine the extent of fire propagation given an initiating event. A 3 x 3 drum configuration, as shown in Figure 4, is taken as representative for the array. As an initiating event, a pool fire exposes the perimeter of the first row of drums providing a constant incident heat flux to the drum walls. As the pool fire heats the first row of drums on one side, the opposite wall radiates to the second row of drums. Likewise, the second row drum walls radiate to the third row. The failure mode criteria for the drums is determined from experimental test data. Because the objective of this analysis is to determine the extent of fire propagation and not the rate of spread, only the steady state heat transfer equations are applied. For this analysis, the fire propagation through the drum array is broken into two separate problems:

Figure 4. Plan View of Drum Array Heat Transfer

- (1) The three drums originally exposed to the pool fire(row 1) are burning and radiate to adjacent drums in the next row (row 2)(the analysis focuses on only one of these drums but represents the behavior of any second row drum); and
- (2) A single drum burning in row 2 radiates to single adjacent drum in row 3. Adjacent drums are conservatively regarded as adiabatic.

5.1.6.1.1 *Shape Factor Analysis*

Although convection plays a major role in the heat transfer for a single drum, the sole mode of energy exchange between drums is heat radiation. This section deals with shape factors required for the radiation analysis. The thermal radiation to a drum is dependant upon the radiosity of the adjacent drums and the shape (configuration, view) factor between the drums. The radiosity is a function of the drum wall temperature and may be determined from the heat transfer energy equations. The shape factor, however, is solely a function of the geometry and location of the drum or drum components with respect to one another. The shape factor is effectively the fraction of energy leaving one surface which reaches a second surface. Several different shape factors are used in this analysis. The calculation and use of the various shape factors required are discussed below.

Inside the Drum

Figure 5 shows a cross sectional view of a single drum where a section of the wall, bounded by the angle θ , is at a higher temperature than the rest of the drum wall. This represents a drum being heated over a portion of its perimeter. For purposes of simplicity and conservativeness, it is assumed that the top and bottom of the drum are adiabatic, and the drum is taken as a cylinder of infinite height (which leads to simple and conservative two dimensional shape factors). For all of the following shape factor notations (F_{a-b}), the first subscript indicates the surface which energy is leaving, and the second subscript is the surface which the energy is incident upon. For this configuration, there are four different shape factors: (1) the hot wall radiates to itself, (2) the hot wall radiates to the cold wall,

Figure 5. Plan View of a Drum Defining the Hot Wall Section [1]

(3) the cold wall radiates to itself and, (4) the cold wall radiates to the hot wall. The segment, x , in Figure 5, joins the points where the hot and cold wall meet. Using standard configuration analysis techniques,

$$\begin{aligned}
 F_{x-1} &= 1 \\
 F_{1-x} A_1 &= F_{x-1} A_x \\
 F_{1-x} &= (A_x/A_1) \\
 F_{1-1} &= 1 - F_{1-x} \\
 F_{1-1} &= 1 - (A_x/A_1) \\
 F_{1-2} &= 1 - F_{1-1} \\
 F_{1-2} &= (A_x/A_1)
 \end{aligned}$$

Likewise for the cold wall,

$$\begin{aligned}
 F_{2-2} &= 1 - (A_x/A_2) \\
 F_{2-1} &= (A_x/A_2)
 \end{aligned}$$

Since $A_1 = \theta r h$
 $A_2 = (2\pi - \theta) r h$
 and $A_x = 2 r h \sin(\theta/2)$

where r is the drum radius and h is the drum height,

$$\begin{aligned}
 F_{1-1} &= 1 - (2/\theta) \sin(\theta/2) & F_{2-2} &= 1 - [2/(2\pi - \theta)] \sin(\theta/2) \\
 F_{1-2} &= (2/\theta) \sin(\theta/2) & F_{2-1} &= [2/(2\pi - \theta)] \sin(\theta/2)
 \end{aligned}$$

For this analysis, $\theta = \pi$; therefore,

$$\begin{aligned}
 F_{1-1} &= F_{2-2} = 0.36 \\
 F_{1-2} &= F_{2-1} = 0.64
 \end{aligned}$$

3 Drums - 1 Drum

The first part of the fire propagation problem involves three drums burning radiating to a single drum in the opposite row. Since the wall temperature of each of the three drums is the same, they are treated as a single body. Rather than calculating complicated shape factor correlations for the curved surfaces of the three drums, they are treated as a single wall of infinite height extending two drum diameters between the two rows (Figure 6). This length was chosen because it bounds the area which radiates to the exposed drum. The exposed drum is approximated as a cylinder of infinite height such that the exposing wall is tangent to it at the wall's midpoint. Assuming the geometries to have infinite heights is a conservative approximation because it does not allow energy to escape the system through the top and bottom of the drum array. The shape factor for the exposing wall to the single drum is given as (Sparrow and Cess (1978)):

$$F_{A1-A2} = [\tan^{-1}(z/x) - \tan^{-1}(y/x)] / (z-y)$$

where $x = c/d$,

$y = a/d$,

and $z = b/d$ as shown in Figure 6.

For this analysis, $a = 0$, $b = 0.58$ m, $c = 0.29$ m, and $d = 0.29$ m; therefore,

$$F_{A1-A2} = 0.55$$

The calculation of this shape factor assumes that there is no obstructions between the wall and the exposed drum. For the actual configuration, the drums next to the exposed drum block some of the incident heat flux and prevent irradiation on the back side. Therefore, this value for the shape factor is somewhat conservative.

Figure 6. Definition of Geometry for the Plate to Cylinder Configuration Factor

1 Drum to 1 Drum

Since only one drum is burning in this problem, it is not appropriate to treat the entire row as a single body because each of the drum walls is at a different temperature. Therefore, it is necessary to more accurately define the geometries between the adjacent drums. As shown in Figure 7, a rectangle is drawn such that it encloses the space between the drums. The configuration factors for the drum walls are approximated as the configuration factors for the rectangle sides since any radiation incident upon a drum wall will also be incident upon the rectangle wall. For this geometry, the rectangle has equal length sides and a finite height equal to the height of the drum. Two shape factors result: (1) opposite sides and, (2) adjacent sides.

The shape factor for drum walls opposite one another is determined from a graph of shape factors for two parallel plates as shown in Figure 8 (Sparrow and Cess (1978)) where, a is the length of the rectangle side, b is the height of the drum, and c is the distance between sides. For $a = 0.41$ m, $b = 0.88$ m, and $c = 0.41$ m,

$$F_{op1-op2} = 0.29$$

Likewise, the shape factor for adjacent sides is determined from a graph of shape factors for two adjacent plates as shown in Figure 9 (Sparrow and Cess (1978)) where a and c are the lengths of the rectangle side, θ is the angle between the plates, and b is the height of the drum. For $\theta = 90^\circ$,

$$F_{ad1-ad2} = 0.25$$

The shape factors defined in this section are referred to in several of the heat transfer energy equations. The geometries were chosen to closely represent the actual configurations of the drum array while at the same time certain assumptions were made to maintain a conservative approach to the problem.

Figure 7. Plan View for One Drum Burning Analysis

Figure 8. Definition of Geometry for Parallel Plate Configuration Factors

Figure 9. Definition of Geometry for Adjacent Plate Configuration Factors

5.1.6.1.2 *Drum Heat Transfer*

Three Burning Drums Exposing One Drum

Figure 10 shows the layout for three drums burning in a row radiating to a single drum in the next row. Area 1 (A_1) is taken as the radiating body such that the temperature (T_s) is that of the burning drum walls (see Shape Factor Analysis). Areas 2 and 3 (A_2 and A_3) are the hot and cold wall surface areas of the exposed drum respectively. Since the drum is very thin (~ 1 mm), the surface area of the inside and outside of the drum is approximately equal. Also, the top and bottom of the drums are conservatively assumed to be adiabatic. The heat transfer energy equations are applied to the exposed drum where A_2 equals A_3 . The incident radiant heat flux to the exposed drum is given in terms of the radiosity of wall A_1 , the shape factor between the drums, and the area of the exposed wall (A_1):

$$\dot{Q}_{inc, A_1-A_2}'' = \left(\frac{A_1}{A_2} \right) F_{A_1-A_2} \sigma T_s^4 \quad (2)$$

where A_1 = area of exposing wall ($4 \pi r h$),
 A_2 = exposed drum wall area ($\pi r h$),
 $F_{A_1-A_2}$ = configuration factor (0.55),
 σ = Stefan Boltzmann constant ($5.669 \text{ E-}11$)
 T_s = burning drum wall temperature,
 r = drum radius,
 h = drum height.

The steady state steel temperature of the burning drums is determined from the energy equation applied for a constant flame heat flux impinging the inside wall of the drum.

$$\dot{Q}_{f1}'' - h_c (T_s - T_\infty) - \sigma (2 T_s^4 - T_\infty^4) = 0 \quad (3)$$

Figure 10. Plan View of Three Burning Drums Exposing One Adjacent Drum

The flux from the drum contents to the drum wall has not been reported in the open literature. As such, we are forced to use analogies to determine a suitable bounding flux. Two sources of data are available for this assessment, burning wall heat transfer measurements and flame heat flux measurements between parallel walls. The wall fire heat fluxes to the burning surface were measured by Quintiere and Harkleroad (1985) and Hasemi (1984) who found heat fluxes to the burning surface of 20-30 kW/m². An opposing wall would be expected to experience similar fluxes via flame contact as well as some radiation from the burning surface which would be expected to be about 15 kW/m² (consistent with a black fuel surface at 450°C). The sum of these two fluxes is about 40 kW/m². Fires burning between closely spaced parallel plates has recently been studied by Foley and Drysdale (1994). They measured fluxes to the wall. The average flame flux determined from their measurements is 37 kW/m². Thus, the two method of estimation are remarkably consistent though originating from different sources.

These fluxes represent bounding heat fluxes because they assume that a gap always exists between the fuel and the drum wall to allow a flame over the interior of the drum wall. In fact, with 26 kg of combustibles and similar amounts of noncombustibles, this is not generally expected. Similarly, it assumes that all the air gap is used to support flame. This is also not possible since at least half of gap areas need to be used to supply air to allow burning in the fuel/drum wall gap at all. As such, assuming an average flux of half the above noted levels is still a bounding analysis. Thus, an average flux of 20 kW/m² will be used in this analysis. (Ongoing testing indicates that 20 kW/m² is the highest average flux observed).

The heat transfer coefficient h_c in Equation 2 was determined from a natural convection correlation for a cylinder (Holman (1990)) and is taken as 8 W/m²-K. Taking $T_{\infty} = 300$ K (27°C) and applying Eqs. (1) and (2), the steady state burning drum wall temperature is 630 K (357°C) and the resulting incident heat flux to the target drum is 6.5 kW/m². In order to determine the pressure rise in the exposed drum, the steady energy equations are applied:

$$\dot{Q}_{inc, A_1-A_2}'' + \sigma (F_{1-1} T_1^4 + F_{2-1} T_2^4 + T_\infty^4 - 2T_2^4) - h_c (T_1 - T_a) - h_c (T_1 - T_\infty) = 0 \quad (4)$$

$$\sigma (F_{1-2} T_1^4 + F_{2-2} T_2^4 + T_\infty^4 - 2T_2^4) + h_c (T_a - T_2) - h_c (T_2 - T_\infty) = 0 \quad (5)$$

$$h_c (T_1 - T_a) - h_c (T_a - T_2) = 0 \quad (6)$$

$$p = p_o \left(\frac{T_a}{T_o} \right) \quad (7)$$

Eq. (3) is for the hot wall exposed to the incident radiant flux, Eq. (4) is for the cold wall, and Eq. (5) is for the air inside the drum. Eq. (6) is the absolute pressure in the exposed drum assuming the air acts as an ideal gas, where p_o and T_o is the ambient pressure and temperature respectively. Solving the above equations for an incident radiant heat flux of 6.5 kW/m^2 yields a maximum pressure rise of approximately 7 psig in the exposed drum. The exposed area of the target drum is heated to 230°C and the air in the drum is heated to 180°C . These temperatures are well below temperatures at which pyrolysis gas generation needs to be considered.

One Burning Drum Exposing One Drum

Figure 7 shows the layout for one drum burning in a row radiating to a single drum in the next row. Since the drums in this problem have different temperatures and because the rectangle used to define the shape factors between drums forms an enclosure, the energy equations for the two rows are coupled to include the radiant heat exchange between burning and non-burning drums. The drums adjacent to the center drums are assumed to be adiabatic to maximize radiative feedback to the exposed drum. Since all of the exposed surfaces have equal area, the heat transfer energy equations for the system are given as follows:

$$\dot{Q}_{f1}'' + \sigma (F_{ad1-ad2} T_1^4 + F_{op1-op2} T_3^4 + F_{ad1-ad2} T_4^4 - 2T_s^4) - h_c (T_s - T_\infty) = 0 \quad (8)$$

$$\sigma (F_{ad1-ad2} T_s^4 + F_{ad1-ad2} T_3^4 + F_{op1-op2} T_4^4 + F_{2-1} T_2^4 + F_{1-1} T_1^4 - 2T_1^4) - h_c (T_1 - T_\infty) - h_c (T_1 - T_a) = 0 \quad (9)$$

$$\sigma (F_{1-2} T_1^4 + F_{2-2} T_2^4 + T_\infty^4 - 2T_2^4) + h_c (T_a - T_2) - h_c (T_2 - T_\infty) = 0 \quad (10)$$

$$h_c (T_1 - T_a) - h_c (T_a - T_2) = 0 \quad (11)$$

$$\sigma (F_{op1-op2} T_s^4 + F_{ad1-ad2} T_1^4 + F_{ad1-ad2} T_4^4 - T_3^4) - h_c (T_3 - T_\infty) = 0 \quad (12)$$

$$\sigma (F_{ad1-ad2} T_s^4 + F_{op1-op2} T_1^4 + F_{ad1-ad2} T_3^4 - T_4^4) - h_c (T_4 - T_\infty) = 0 \quad (13)$$

Eq. (7) is for the burning drum, Eqs. (8), (9), and (10) are for the exposed drum, and Eqs. (11) and (12) are for the adjacent adiabatic drums. Again, the flame heat flux in Eq. (7) is taken as 20 kW/m². In this problem, unlike the Three Drum to One Drum configuration, the incident heat flux to the exposed drum is the sum of the irradiances from each of the drums in the array. Solving the above equations yields a maximum pressure rise of approximately 5.4 psig. The exposed target drum temperature is 180°C and the air temperature in the drum is 140°C. Here again, these temperatures will not lead to pyrolysis gas generation.

5.1.6.1.3 Assessment of Drum to Drum Fire Propagation via Radiation

The above analyses indicate that three burning drums can cause target drum pressures up to 7 psig and a single burning drum can generate pressures up to 5.4 psig. In

both cases pyrolysis of drum contents is not expected due to the low temperatures involved. The evidence we have for drum lid loss from the Sandia and LLNL testing is that only 0.15 of the drums fail by lid loss and the minimum pressure observed with lid loss was 8.5 psig. This means that the relevant scenario for assessing fire propagation is the one drum to one drum scenario and the critical pressure endpoint for lid loss is 8.5 psig. The bounding analysis performed here indicates that this endpoint is not reached so that fire propagation from drum to drum via radiation is not expected.

5.1.6.2 Drum to Drum Propagation via Expulsion of Burning Contents

Only the top tier of the array can experience actual lid loss due to overpressure since the plywood burn through requires more thermal exposure than overpressure failure of the drum. In the available testing only 15 percent ($p=0.15$) of the drum lids were actually removed from the drum due to lid venting (3 of 22 Hasegawa et al. (1993), 3 of 17 in Hunter (1979)). The variance in the fraction of drums failing by lid loss is given by $p(1-p)/n$ (Bowker and Leiberman (1972)). Defining the uncertainty in p as two standard deviations, 2σ , we have $p=0.15\pm0.11$. Thus, only up to 26 percent of the drum lids are expected to be lost.

In the LLNL testing with 10 kg of waste in the drums, when a lid was lost, the contents were expelled from the drum. It is unclear if this can occur with higher more realistic drum loadings, but in the absence of any data for more heavily loaded drums we will assume that the contents may be expelled from a drum when lid loss occurs. The contents may be expected to be distributed both next to the array as well as on top of the array. If we assume that the distribution of expelled contents is symmetric about the source drum, then half the expelled combustible contents will fall on the array of uninvolved drums and the remainder will fall to the ground next to the array in the general area of the exposing pool fire or on already burning drums.

If the contents burn on top of the drum array, it is highly unlikely that drum lid losses will result. The contents will burn from the top down with the unburnt contents insulating

the drum lid. When the contents are substantially burned, heat will begin to be transferred to the drum. Since the drum lid seal is heated directly and the drum lid area is small relative to the drum area, the seals are likely to fail and provide venting and overall heating of the drum will be minor. However, if the contents contain polyethylene (PE) which melts and flows, this fuel may flow both onto the drum lid and onto the plywood at the base of the drum. This molten PE is effectively a pool fire exposure to the drum of the sort discussed in Section 5.1.2b. The assumption that all plastic is PE and hence is capable of melt and flow behavior is a conservative assumption. In addition, the assumption that other noncombustible or cellulosic materials will not prevent the assumed flow of PE is also very conservative.

Based on the heating calculations performed in that section a pool fire with $0.028 \text{ kg/m}^2\text{s}$ over a void area of 0.1 m^2 for 340 s ($0.028 \times 0.1 \times 340 = 0.95 \text{ kg PE/drum}$) will be sufficient to cause drum lid failure. Considering the relative areas of the drum (0.27 m^2) and the void between drums (0.1 m^2), this leads to a requirement of 3.5 kg of PE per drum ($0.95 \text{ kg PE/drum} \times (0.27 \text{ m}^2 + 0.1 \text{ m}^2)/0.1 \text{ m}^2 = 3.5 \text{ kg PE per drum}$). Since an average drum contains about 13 kg of PE, there is sufficient PE to cause failure of 3.25 drums ($13 \text{ kg per source drum}/3.5 \text{ kg per target drum} = 3.25 \text{ target drums exposed per source drum}$) if the contents are optimally distributed on neighboring drums. Since only about half of the contents will fall on uninvolved drums and less than 0.26 of failed drums yield violent lid loss, each drum failure leads to about 0.42 drum lid losses ($0.5 \times 3.25 \times 0.26$). If each lid loss failure leads to less than one additional lid loss, then the process is not expected to continue indefinitely. If the probability of burning contents leading to lid loss in a neighboring drum is less than one, indefinite propagation of the drum fire is not possible. For a probability less than one the expected number of involved drums per initially lost lid, n_{loss} , can be determined by evaluating the infinite series:

$$n_{\text{loss}} = 1 + \text{sum from } n = 1 \text{ to infinity } p^n = 1/(1-p)$$

where p is the probability of one lid loss leading to an additional lid loss. In this case $p = 0.42$, so that $n_{\text{loss}} = 1.7$. Each top tier drum which burns due to initiating source heating

is expected to lead to a total of 1.7 drum lid losses (including itself). This extent of drum to drum propagation is quite modest.

This evaluation assumes that if plywood sheets are placed on top of the array are thrown clear of the affected area to allow penetration of PE melt into the top tier of the array. The evaluation also assumes an optimal distribution of PE from the overpressured drum such that the amount of PE which falls on a drum is just sufficient to cause lid failure. This assumes that other nonplastic contents do not interfere with this worst case distribution of PE. Obviously, if less optimal assumptions are used, the number of violent lid losses would decrease proportionately.

5.1.6.3 Summary of Drum to Drum Fire Propagation Analyses

The foregoing sections have demonstrated that drum to drum fire propagation remote from the influence of the initiating source is not possible. These analyses have considered each of the identifiable mechanisms for propagation and have shown that propagation is not expected. Of course, no testing of fire propagation in drum arrays has been reported in the literature so validation of these results is not possible at this time. However, the analyses do seem to be conservative bounding analyses which based on currently available information are credible.

5.1.7 Hazardous Materials Contribution

The hazardous materials which may be found in the SWBG are documented in WHC-SD-W306-TI-001 Rev 1. Approximately 15 percent of drums are thought to contain 2.2 kg toluene and 200 g xylene. Approximately 1 percent of drums are thought to have larger amounts of hazardous materials. From a fire and explosion standpoint, the most notable extreme is 104 kg of toluene in a maximum drum. Interviews with past PFP personnel have indicated that up to 1200 one-pound propane bottles may be contained in the existing drum inventory. In light of this possibility, it may be prudent to assume that about 1 percent of drums contain a one pound propane tank.

The most important role of these hazardous materials in an incident is their contribution to drum overpressure and ultimate lid loss. Toluene boils at 110°C and xylene boils at 106°C. The 1 atmosphere (14.7 psi) vapor pressure at these very attainable temperatures is sufficient to cause lid loss when coupled with the modest pressure increases due to drum to drum radiative heat transfer (5-7 psig) (see Section 5.1.6). Similarly, the venting of a propane tank into the drum is sure to cause violent failure as the liquified gas vaporizes in the drum. It is unclear what pressures and temperatures are required for this type of failure, but given the normal tank pressure of about 110 psig and the potential for tank degradation, violent tank failure cannot be excluded. The real question is how many of the propane tanks are vented empty tanks and how many are sealed and partially filled. There is no way to estimate this critical fraction.

The heat content of the hazardous materials is not of any great significance. Even heating due to fireballs resulting from violent venting of a propane tank is not expected to be a significant contributor to fire development due to the moderate heat fluxes involved and the very limited duration.

The key effect of the volatile liquid hazardous material is its ability to reduce the required heat input to cause overpressures and lid loss. We know that temperatures in the drum required to generate overpressures on the order of 10 psig, the low end of the pressures observed at lid failure, is about 220°C from the ideal gas law. If volatile liquids can cause the generation of gases at half this temperature, it is clear that the heat input to a drum with volatile liquids absorbed on the contents would be much easier to overpressure than normal combustibles. This assumes that the volatile liquids are not significantly insulated by drum contents.

Applying this rationale to the either of the above drum to drum propagation models developed in Section 5.1.6 yields thermal conditions which would be expected to generate overpressures sufficient to cause lid loss. This approach does not include seal failure and venting, as well as internal heat transfer considerations(i.e. insulation of the volatile liquids by contents). As such, we can only say that we have not been able to exclude the possibility

of lid loss via heating from adjacent drums or expelled contents when free volatile liquids are present in the drum.

For the radiation model, the steady state drum contents temperature is above the boiling points of toluene and xylene. The quantities of these materials present are more than enough to cause the required overpressures. Since 16 per cent of the drums have these hazardous materials, we expect a burning drum to be next to one other hazmat drum. The only thing which can stop propagation would be if a break in adjacent hazmat drums occurs in the array. While this may occur for individual drums, we have no basis for assuming that such breaks will occur since there is no data available on the distribution of hazardous materials drums in the array. It is entirely possible that hazardous materials drums are present in groups rather than randomly.

Considering the second mechanism involving the loss and burning of contents which cause failure of adjacent drums, we find the same result. With the reduced heat input requirements, the number of drums which can be heated to failure by a single drum's contents is increased. If this number is increased by a factor of 2.5, indefinite propagation is expected. While it is difficult to assess this factor, a value of 2 or more is certainly plausible, given the reduction in temperature required for failure pressure from about 200°C to 100°C. Given the reduced heat input expected, it must be concluded that propagation cannot be excluded.

These results indicate that propagation of the fire from drum to drum on the top tier of the uncovered drum arrays may indeed be possible in the presence of about 16 percent hazmat drums. While this cannot be assured by the present estimates, neither can propagation be ruled out. It seems prudent under these circumstances to assume that propagation occurs between hazmat drums. This applies only to the top tier of uncovered drum arrays. With 16 percent hazmat drums and a probability of lid loss of 25 percent, about 4 percent of the top tier drums of an open array will burn and the remainder of the 16 percent hazmat drums will experience lid seal failure without lid loss. This leads to a total of 4 drums consumed (26 kg burned) and 12 drums with seal only failure (1 kg loss)

per 100 drums on the top tier. This yields 116 kg of contents lost per 100 top tier drum. This should be added to the local effects of the initiating source, if hazmat are present in the expected fraction of the drums.

The largest uncovered trench array is 1.5 modules or a 12 X 18 array of drums, so that 216 top tier drums are present. As such hazardous materials effects can contribute up to 8 drum lid failures and 26 drum seal failures.

5.2 Scenario Hazard Assessments

5.2.1 Scenario 1: 50 gallon spill of diesel at the edge of the drum array

For this scenario, the fuel is assumed to spill near the drum array, but the array is assumed to not be physically disrupted by the spill event or other outside event. Based on the analysis of Section 5.1, up to 165 drums could be exposed and fail by lid overpressure release due to the diesel fuel spill. However, based on the stability of the drum array, this would not lead to displacement of the drum lids and involvement of the drum contents. As such, the extensive penetration of the drum array by the fuel spill does not represent a worst case scenario.

With the spill adjacent to the array, it is possible to expose drums on all tiers to heat from the fire. Based on the drum array stability analysis, only the drums on the top tier at the edge row are at risk of fire involvement. The involvement of the top tier of drums requires a flame height which is at least to the top of the array. The worst case configuration is a line type pool fire whose flame height is to the top of the array and lasts the 3 minutes conservatively estimated to cause lid failure. This represents a fuel spill which flows along the trench at the edge of the drum array.

Several investigations of line fires indicate that the flame height can be correlated as

$$L_f = A \dot{Q}^{2/3} \quad (14)$$

where A is 0.029, 0.034, and 0.056 $\text{m}/(\text{kW}/\text{m})^{2/3}$ as determined by Achmad (1979), Delichatsios (1984), and Hasemi (1984), respectively. For this application, the taller Hasemi correlation is the most conservative and will be used here, since there is no identifiable rationale for the different constants. The use of the lower values of A would linearly reduce the length of the worst case line fire and would linearly decrease the number of drums affected. Based on a drum array height of 3.5 m, the Hasemi correlation yields 500 kW/m heat release. Using a 3 minute burn duration required to cause drum failure and the 6,200 MJ energy content of 50 gal of diesel fuel yields a 69 m long line fire exposing 112 drum stacks. The array is stable for this exposure, and the top tier drum is the only drum expected to experience actual lid loss.

In the available testing only 15 percent ($p=0.15$) of the drum lids were actually removed from the drum due to lid venting (3 of 22 Hasegawa et al. (1993), 3 of 17 in Hunter (1979)). The variance in the fraction of drums failing by lid loss is given by $p(1-p)/n$ (Bowker and Leiberman (1972)). Defining the uncertainty in p as two standard deviations, 2σ , we have $p=0.15\pm0.11$. Using $p+2\sigma = 0.26$ as the fraction of drums which fail with lid loss, the contents of approximately 29 drums of the 112 top tier drums vented would be expected to experience lid loss and burn. Lower tier exposed drums will experience lid seal failure only due to the stability of the array.

This represents a very conservative analysis of this exposure. The fuel is assumed to spill in the least advantageous way (fuel spills and flows along the edge of the edge of the array without flowing into the array or away from the array to the worst case fuel depth and length) and is assumed to not be at all absorbed by the sandy soil at the edge of the drum array. The most conservative flame height correlation is used, and the flame exposure time used is the minimum observed for failure for flame exposure on all sides when in this scenario only a single side exposure is possible. The analysis also assumes at least an average heat flux of $60 \text{ kW}/\text{m}^2$ (see Section 5.1.1.1) whereas the typical flux at the flame tip is about $20 \text{ kW}/\text{m}^2$.

Based on the drum burning behavior developed in Section 5.1.5, the drums are expected to burn for 3 hours at a combined heat release rate of 2.2 MW (29 drums X 75 kW/drum). The pool fire exposes 448 drums (112 X 4). Of these only 29 drums experience lid loss and the remaining 419 are expected to experience lid seal failure. The total mass loss for this scenario is 754 kg burned (26 kg/drum X 29 drums) and 419 kg lost via seal failures.

An alternate scenario for this situation is to have a spill width sufficient to yield an optically thick flame which could burn out the stabilizing plywood around the edge row drums. An optically thick flame would require a spill width of about 1 m for diesel fuel. This is based on the observation that the width of a trench fire required to be optically thick is about the same as the diameter of a pool to assure an optically thick flame (Mudan and Croce (1988)). For hydrocarbon pools, a diameter of one meter is needed for optically thick flames (Babrauskas (1988)).

Based on a spill width of 1 m and a burning rate per unit area of 1.6 MW/m^2 (see Section 5.1.1), we have a burning rate per unit length of 1600 kW/m. While this is a single sided flame exposure, the heat fluxes associated with this size pool fire can be as high as 120 kW/m² as shown in Table 1 and lid failure is assumed to occur. With a plywood burn through time of about 15 minutes (3/4 inch thick plywood), this yields a spill length of 4.3 m or 7 drums. One would expect the drums to vent prior to plywood burn out. As such, at the time of the plywood burn out there would be no violent venting of drums.

The only experiments which have been conducted with four tier arrays of drums is the INEL tests documented by Brown (1979). In these tests a two by two by four tier tall array of drums was exposed to a pool fire next to plywood storage boxes. The plywood between several of the tiers was burned out, but the array remained in place through the whole test. Despite this evidence, the drums directly exposed to flames will be assumed to fall or otherwise lose their lids. It is assumed that all the 28 exposed drums experience lid seal failure (not necessarily violent failure) and the lid is removed during toppling. Thus, we have a total of 28 drums which topple and contribute fuel.

The drums which topple, open, and burn are thrown away from the remainder of the array during toppling. As such there is a natural separation of the burning drums from the remaining array which reduces the ability of the burning contents to damage the array drums. The lowest tier of the toppled row is expected to remain in place or fall by simple rotation. In either case, drum contents will not be in direct contact with the second row of drums. Those first row drums most likely to lose their contents due to falling will also tend to be thrown farthest from the array. Given this separation, the low burning rate of drum contents, and the analysis of Section 5.1.6, it is not expected that the fire exposure to the second row drums and plywood would be sufficient to cause lid loss and plywood burn through. The plywood burn through is particularly critical and the separation of the contents fire and the edge on configuration factor between the contents fire and the plywood is not favorable for plywood heating.

Only the top tier of the array can experience actual lid loss due to overpressure since the plywood burn through requires more thermal exposure than overpressure failure of the drum. As discussed earlier in this section, only up to 26 percent of the drum lids are expected to be lost. In the LLNL testing with 10 kg of waste in the drums, when a lid was lost, the contents were expelled from the drum. It is unclear if this can occur with higher more realistic drum loadings, but in the absence of any data for more heavily loaded drums we will assume that the contents may be expelled from a drum when lid loss occurs. This means in this scenario that 2 top tier drums (7×0.26) are expected to expel their contents prior to toppling the first row drums. As such, the contents may be expected to be distributed both next to the array as well as on top of the array. If we assume that the distribution of expelled contents is symmetric about the source drum, then half the expelled combustible contents ($0.5 \times 26 \text{ kg/drum} \times 2 \text{ drums} = 26 \text{ kg}$) will fall on the array and the remainder will fall to the ground next to the array in the general area of the exposing pool fire.

If the contents burn on top of the drum array, it is highly unlikely that drum lid losses will result. The contents will burn from the top down with the unburnt contents insulating the drum lid. When the contents are substantially burned, heat will begin to be transferred

to the drum. Since the drum lid seal is heated directly and the drum lid area is small relative to the drum area, the seals are likely to fail and provide venting and overall heating of the drum will be minor. However, if the contents contain polyethylene (PE) which melts and flows, this fuel will flow both onto the drum lid and onto the plywood at the base of the drum. This molten PE is effectively a pool fire exposure to the drum of the sort discussed in Section 5.1.2b.

As developed in Section 5.1.2b n_{loss} , the number of drums lost per exposed drum is 1.7. With 7 top row drums exposed to the pool fire, the expected number of initial drum lid losses is 2 drums. Each of these drums are expected to lead to a total of 1.7 drum lid losses (including itself). Thus, we expect a total of 4 drum lid losses (2×1.7 rounded up) in the top tier under the conservative assumptions of this evaluation. This evaluation assumes that if plywood sheets are placed on top of the array are thrown clear of the affected area to allow penetration of PE melt into the top tier of the array. The evaluation also assumes an optimal distribution of PE from the overpressured drum such that the amount of PE which falls on a drum is just sufficient to cause lid failure. Obviously, if less optimal assumptions are used, the number of violent lid losses would decrease proportionately.

In addition to the drums which experience lid loss and complete contents burning, some drums will experience lid seal loss without lid loss. These drums cannot burn because of the inability to transport air into the drum at a rate sufficient to sustain combustion. Based on the results of the LLNL testing, such drums exposed to a pool fire were found to experience about 1 kg of mass loss which contributes to the radiological source term. For purposes of this analysis we will assume that any drum exposed to the fire will sustain sufficient seal damage to allow behavior similar to the LLNL testing. Drums so exposed include the second row in the lowest three tiers and the adjacent drums at the end of the first row ($3 \times 7 + 2 \times 3 = 60$). On the top tier the drums with seal failure include those exposed to expelled contents fires. Since 3 drums fail exposing 4 drums each, there are up to 12 drums exposed to contents fires. This extends beyond the second row on this tier.

The total drums which experience lid seal failure without lid loss is estimated to be 72 drums, adding an additional 72 kg total to the material consumed in the fire.

The drum burning rate estimate made in Section 5.1.5 does not include the possibility that the drum contents might be distributed by drum toppling. Ignoring this behavior, the Section 5.1.5 results yield a total heat release rate of 2.4 MW for 3 hours (28 toppled drums plus 4 top tier drums @ 75 kW each). The total material consumed in the fire is 32 drums @ 26 kg/drum (832 kg) plus 72 drums @ 1 kg (72 kg) for a total mass of combustibles consumed of 904 kg. Dispersal of the drum contents prior to burning could increase the burning rate while reducing the duration, though the product of heat release rate and duration must be a constant.

This alternate scenario results in somewhat more material lost via drum contents burning (832 kg vs 754 kg), but less mass lost via seal failures (72 kg vs 419 kg) relative to the first scenario developed. The total mass lost is greatest in the first scenario developed, 1173 kg. This first scenario will be taken as the worst case.

These determinations do not include the hazardous materials contributions as described in Section 5.1.7. Adding the 8 drum lid losses and 26 drum seal losses from hazardous materials effects, we find that the total drum lid losses is 37 (962 kg) and the total drum seal failures is 445 (445 kg). The drum burning heat release rate is 2.8 MW for 3 hours.

5.2.2 Scenario 2: 50 gallon spill of diesel in a 8 ft by 8 ft void in the drum array

This scenario includes burning diesel fuel in the void created by drum removal. This scenario only applies to backfilled trenches, since the removal of drums is caused by the pilot retrieval project which applies only to backfilled trenches. The void geometry is shown in Figure 11.

Drums stacks stabilized by plywood and backfill

Drum stacks not stabilized by plywood and backfill

Figure 11. Drum Array Void Plan

The burning rate of diesel in the void can be determined using the methods used in Section 5.1.1. This results in 1.6 MW/m^2 and a heat release rate of 9.2 MW . For 155 kg of fuel (50 gallons), this gives a burning duration of 11 minutes . Using the Heskestad flame height correlation (Heskestad (1983))

$$L_f = 0.23 \dot{Q}^{2/5} - 1.02 D \quad [m, kW] \quad (15)$$

and using the edge length of the pool as D yields a flame height of 6.5 m or about twice the drum array height. This flame height and burning duration will certainly be sufficient to cause lid failure in all drums directly adjacent to the void. While this is a single sided flame exposure, the heat fluxes associated with this size pool fire can be as high as 120 kW/m^2 as shown in Table 1.

Based on the assessments of Section 5.1, only the adjacent drums on the upper level will actually have their lids removed to allow fire involvement of the drum contents. However, additional drums could become involved if they fall from the drum array. As we have seen in Section 5.1.4, the stability of the array with the plywood in place is excellent. As such, the plywood must be burned in order to destabilize the drums. As discussed in Section 5.1.3, the $1/4 \text{ inch}$ thick plywood could burn through in about five minutes of fire exposure.

Assuming that the plywood surrounding the edge drum can be exposed by the pool fire, the edge drums would be destabilized in about 5 minutes . This is quite conservative in that the pool fire as specified does not directly impinge on the plywood. Assuming that the drums topple at this time, there may be sufficient exposure time to the second row of drums to just cause the $1/4 \text{ inch}$ plywood to burn out prior to pool fire burnout. This is quite conservative in that the $8 \times 8 \text{ ft}$ void pool fire is heating the second drum row without direct flame contact and the burning rate of the pool is reduced by the toppled first row drums. However, one would expect the drums to vent prior to plywood burn out. As such, at the time of the plywood burn out there would be no violent venting of drums and the backfilled

soil above the stacks would stabilize the pile. As such, the second row of drums would vent, but would not be expected to lose lids and allow the contents to burn. The only experiments which have been conducted with four tier arrays of drums is the INEL tests documented by Brown (1979). In these tests a two by two by four tier tall array of drums was exposed to a pool fire next to plywood storage boxes. The plywood between several of the tiers was burned out, but the array remained in place through the whole test.

This scenario would result in 14 first row stacks to topple. While the base tier is not expected to topple, these drums are expected to experience lid loss and burn. With four tiers of exposed drums we expect 56 drums whose lid seals fail and topple. It must be assumed that all of these drums experience sufficient forces to dislodge their lids and contribute to the fire. Based on the analysis of Section 5.1.5 on drum burning, the drum fire heat release rate will be 4.2 MW for 3 hours. The 18 stacks of drums in the second row from the void will experience lid seal failure, but will not burn actively since the lids are not displaced. Thus, the total combustibles expected to be consumed is 56 drums @ 26 kg/drum (1456 kg) plus 72 drums @ 1 kg/drum (72 kg) for a total of 1528 kg.

5.2.3 Scenario 3: Burning tumbleweeds along edge of the drum array

The collection of tumbleweeds along the edge of the drum arrays is a known phenomena. In the event of ignition of the tumbleweeds by a wildland fire or other cause the full length of a drum array could be exposed to a tumbleweed fire. The intensity of such fires is well known and results from the dry thin fuel elements. The thin fuel yields high heat release rates but also results in relatively short fire duration. Gross (1962) and Thomas (1974) have studied the burning of wood sticks. Their results indicate that an active burning duration of 3 minutes requires a stick thickness of approximately 1.2 cm. Since the typical stick thickness of tumbleweed is less than 1.2 cm and the density of tumbleweed is less than wood, the duration of burning is not sufficient to cause failure of exposed drums.

6.0 PROTECTION OF ESSENTIAL SAFETY CLASS SYSTEMS

The SWBG has no safety class systems.

7.0 LIFE SAFETY CONSIDERATIONS

The SWBG is an outdoor facility which is not normally occupied. As such, the normal concerns regarding life safety are not applicable. Life safety concerns are applicable to personnel involved in drum handling operations involving diesel fueled heavy equipment. Fires involving diesel fuel are expected to present serious thermal hazards to personnel in and near the pool fire. The arrangement of the trenches would allow free escape from such a pool fire incident.

8.0 CRITICAL PROCESS EQUIPMENT

There is no critical process equipment associated with the SWBG.

9.0 HIGH VALUE PROPERTY

There is no high value property associated with the SWBG. Costs associated with a fire incident are dominated by repackaging and remediation costs.

10.0 DAMAGE POTENTIAL

The fire damage potential was assessed for three scenarios. Scenario 2 involved the burning of the drum contents of 56 drums over a period of 3 hours. Scenario 1 involved 37

drums burning over the same 3 hour period. Scenario 3 did not result in any drum contents burning. The following analysis focuses on Scenario 2. Since there are no automatic fire systems in place, the MCFL and MPFL are formally the same. Following the discussion of the MPFL, an assessment of the fire department effect on the loss is included.

10.1 Maximum Possible Fire Loss (MPFL)

As developed in Section 5.2.2, Scenario 2 results in a 4.2 MW fire which lasts 3 hours. Without fire department intervention, this release of heat and mass will occur. Additional drums are not expected to be involved. The total combustibles expected to be consumed is 56 drums @ 26 kg/drum (1456 kg) (active burning) plus 72 drums @ 1 kg/drum (72 kg) (pyrolysis from seal failures) for a total of 1528 kg.

The heat release rate of diesel pool fire in the void is 9.2 MW. For 155 kg of fuel (50 gallons), this gives a burning duration of 11 minutes. This is sufficiently short with respect to the drum burning that the buoyancy of the initial pool fire will have little effect on the plume dispersion of radioactive materials released during drum burning.

10.2 Fire Department Intervention Effectiveness

Scenario 1 is initiated while drum handling operations are in progress at the SWBG so that detection of the fire will be by onsite operating personnel at the onset of the incident and will report the fire by radio. The fire department will be notified and would be expected to be on the scene in 6 minutes from pool fire initiation. At this point in time, the fire will have propagated over the full length of the spill. This is based on 69 m pool length with central ignition and a flame spread rate of 10 cm/s typical of combustible liquids ($34.5 \text{ m} / 0.1 \text{ m/s} = 345 \text{ s} = 5.75 \text{ min}$). With half the length of the pool having been burning for 3 minutes or more prior to arrival, half the ultimate lid losses would be expected to have already occurred. Setup for attacking the fire would require approximately two minutes. Based on the three minute exposure assumed to cause lid loss, it is not expected that the fire department could prevent many lid losses at the time they are operational.

It will be necessary for the fire department to move into the trench edge to extinguish the drum contents fire. This will be a slow process. The burning drums are on the top tier and contents will have been partially expelled onto the ground and onto the array. Until the drums have been individually removed, residual fires in some or all drums are to be expected.

Table 3 shows an estimate of the burning rate as a percent of the free burn estimate as a function of time during the extinguishment process. Time zero is the time at which the edge drums topple. Based on the timetable, 3.5 percent of the combustible drum contents are consumed. With 28 drums involved, the 100 percent of freeburn corresponds to 2.2 MW and a mass loss rate of 70 g/s. The 3.5 percent of total combustible consumed corresponds to less than 26 kg of combustibles.

Table 3. Fire Suppression Timetable for Scenario 1

Time After Ignition (min.)	Percent of Free Burning Rate	Fire Department Actions
6	100	FD arrives on scene(6 min. after ignition) (drums ignite uniformly over the period 3-9 minutes after pool ignition with an average of 6 minutes)
8	100	Water/foam application begins
9	20	Knockdown complete
24	1	Suppression of active flames in individual drums complete
240	0	Drum removal and extinction of residual flame/smoldering complete

Scenario 2 is initiated while drum handling operations are in progress at the SWBG so that detection of the fire will be by onsite operating personnel at the onset of the incident and will report the fire by radio. The fire department will be notified and would be expected to be on the scene in 6 minutes from pool fire initiation. At this point in time, the first row would be expected to be toppling due to the burnout of the plywood stabilizing sheets (14 x 4 drums). Setup for attacking the fire would require approximately two minutes, and knockdown of the pool fire would occur within an additional minute. At this

point in time, up to 56 drums will have toppled into the pool so that actual extinction of the pool fire will be difficult due to the severe obstructions.

Once a secure foam blanket has been established on the pool, it will be necessary for the fire department to move into the void area filled partially with toppled drums to extinguish the drum contents fire. This will be a slow process. After the drums have been extinguished as best one can in the toppled array, the drums will need to be systematically removed. Until the drums have been individually removed, residual fires in some or all drums are to be expected.

Table 4 shows an estimate of the burning rate as a percent of the free burn estimate as a function of time during the extinguishment process. Time zero is the time at which the edge drums topple. Based on the timetable, less than 3 percent of the combustible drum contents are consumed. With 56 drums involved, the 100 percent of freeburn corresponds to 4.2 MW and a mass loss rate of 140 g/s. The 3 percent of total combustible consumed corresponds to less than 44 kg of combustibles.

Table 4. Fire Suppression Timetable for Scenario 2

Time After Drums Topple (min.)	Percent of Free Burning Rate	Fire Department Actions
0	100	FD arrives on scene(6 min. after ignition)
2	100	Foam application begins
3	20	Knockdown complete
18	1	Suppression of active flames in individual drums complete
240	0	Drums removal and extinction of residual flame/smoldering complete

11.0 FIRE DEPARTMENT/BRIGADE RESPONSE

A trained, fully staffed fire department is maintained at the Hanford site which is staffed on a 24 hour, seven day per week basis. The response time of the fire department to the SWBG is estimated to be 5 minutes with an additional 1 minute notification time for the scenarios discussed in Section 10. Hydrants are available on the perimeter of the SWBG site for use in firefighting. The actions expected in a major incident are included in Section 10.1.

12.0 RECOVERY POTENTIAL

Since the SWBG is a storage site, the resumption of operations is not a major issue. Storage of additional drums within the fire affected trench will not immediately be possible, but other trenches will not be affected by the fire directly. Contamination of other trenches can, however, occur due to dispersion of radioactive material. Beyond the initial fire department actions, recovery activities required include securing the remaining drum contents, repackaging these contents, decontamination of the surrounding soil and drums, inspection of nearby drums, collection of fire department water runoff within the trench as possible, and reassembly of the drum arrays. These tasks will require a major effort extending over a period of many months.

13.0 POTENTIAL FOR A TOXICOLOGICAL, BIOLOGICAL, AND/OR RADIOLOGICAL INCIDENT DUE TO A FIRE

The dose assessment, deposition calculations, etc. will be done by WHC and transmitted to HAI for incorporation into the FHA.

14.0 EMERGENCY PLANNING

The SWBG Emergency Plan provides a system of planned responses to minimize risks to personnel, equipment, and the environment in the event of an emergency. The SWBG Building Emergency Director(BED) is at all times either on the facility premises or on call with the responsibility for coordinating all emergency response measures. The SWBG BED is thoroughly familiar with all operations and activities at the SWBG facility, the location and properties of all wastes handled, the location of all records within the facility, and the facility layout. He has authority to commit the resources needed to carry out the Emergency Plan.

15.0 SECURITY AND SAFEGUARDS CONSIDERATIONS RELATED TO FIRE PROTECTION

The SWBG is located within a secure/protected area. There are no security/safeguards in place which impact the likelihood or severity of a fire incident. Fire department access is not affected adversely by an security systems or procedures.

16.0 NATURAL HAZARDS IMPACT ON FIRE SAFETY

The impact of wildland fires on fire safety are directly addressed in Scenario 3 (Section 5.2.3). While the tumbleweed fire exposure will cause damage to the adjacent drums, burning of the drum contents is not expected.

Floods would have no effect of SWBG fire safety, and tornadoes are not expected to have any fire safety impact since drum handling operations would not be allowed under such conditions and without fuel associated with these operations, there are not credible scenarios.

Earthquakes could cause toppling of the uncovered drum arrays. If a fire and an earthquake did occur at the same time, it is reasonable to assume that the drums breached by earthquake induced toppling would be burned and would be in addition to any fire induced breaching and burning. However, there is insufficient information available to assess the effects of earthquakes on the drum array and the interaction of these effects with fire scenarios. Further examination of this issue should be pursued.

17.0 EXPOSURE FIRE POTENTIAL

Fire propagation from one trench to an adjacent trench cannot be supported based on the very limited heat release rates, the substantial separation distance, and the geometry of the trenches (i.e., the separation of trenches by earth mounds).

18.0 RECOMMENDATIONS

The use of pressure relief devices on drum lids could eliminate violent lid losses and hence involvement of drum contents. The LLNL (Hasegawa et al. (1993)) test series showed that filters on TRU drums prevented the buildup pressure beyond 2-3 psi and thereby prevented violent lid failure. The Sandia tests (Hunter (1979)) showed that a 1/8-in. diameter vent was inadequate to prevent violent lid loss. Experiments with flammable liquid drums have shown that the use of nylon bungs are effective in preventing BLEVE's of these drums (Tavares and Delichatsios (1981)). While testing of these bungs with solid waste drums should be performed prior to any decision to use nylon bungs, this method of pressure relief is promising in that it is passive, reliable, and only operates in fire conditions due to heating.

19.0 REFERENCES

- Achmad, T. and G.M. Faeth (1979), "Turbulent Fire Walls," *Seventeenth Symposium (International) on Combustion*, The Combustion Institute, p. 1149.
- Anderson, C. et al. (1974), "Effects of a Fire Environment on a Rail Tank Car Filled with LPG," Report No. FRA-OR&D 75-31, U.S. Department of Transportation, Federal Railroad Administration
- ANSI (1991), "ANSI MH2-1991, American National Standard for Materials Handling (Containers) – Steel Drums and Pails," American National Standards Institute, New York, NY.
- ASTM (1990), "Report to ASTM on cone calorimeter inter-laboratory trials prepared by Task Group E 5.21 T.G. 6a, Jan. 3, 1990", American Society for Testing and Materials, Philadelphia, PA.
- Atreya, A., Abu-Zaid, M., (1991), "Effect of Environmental Variables on Piloted Ignition", *Third International Symposium on Fire Safety Science*, Elsevier Science Publishing, NY, NY.
- Babrauskas, V., (1988) "Burning Rates", Section 2/Chapter 1, *The SFPE Handbook of Fire Protection Engineering*, P. DiNenno, Editor-in-Chief, National Fire Protection Association, Quincy, MA.
- Bowker, A., Lieberman, G., (1972), *Engineering Statistics*, Prentice-Hall, Inc., Englewood Cliff NJ, pp 126-129.
- Beers, R. (1983), "Gas Generation Studies: Year-end Report, FY 1983," EG&G Idaho, Inc., RHB-387-83, 1983.
- Brown, R. (1979), "DOT 7A FRP Box Fire Test at the INEL," EG&G Idaho, Inc., TREE-1367, 1979.
- Cleary, T.G, and Quintiere, J.G. (1991) "A Framework for Utilizing Fire Property Tests," NISTIR 4619, National Institute of Standards and Technology, Gaithersburg, MD
- Delichatsios, M.A. (1984), "Flame Heights in Turbulent Wall Fires with Significant Flame Radiation," *Combustion Science and Technology*, Vol. 39, 1984, pp. 195-214.
- DOE EH-31.3 (1991), "Guidance on Performance of Fire Hazards Analyses," Department of Energy Memorandum, November 7, 1991.
- DOE Order 5480.7A (1993), "Fire Protection," U.S. Department of Energy, Washington, DC, February 17, 1993.
- Drysdale, D. (1985), *An Introduction to Fire Dynamics*, Wiley and Sons, Chichester, England.

- Foley, M. and D. Drysdale (1994), "Heat Transfer from Flames between Vertical Parallel Walls," University of Edinburgh, Scotland.
- Gregory, J.J., N.R. Keltner, and R. Mata, Jr. (1987), "Thermal Measurements in Large Pool Fires," SAND-87-0094C, Sandia National Laboratories, Albuquerque, NM
- Gregory, J.J., R. Mata, Jr., and N.R. Keltner (1985), "Thermal Measurements in a Series of Large Pool Fires," SAND-85-0196 TTC-0659-UC-71, Sandia National Laboratories, Albuquerque, NM
- Gross, D. (1962), "Experiments on the Burning of Cross Piles of Wood," *Journal of Research of the National Bureau of Standards—C. Engineering and Instrumentation*, Vol. 66C, No. 2, April-June 1962.
- Gross, D., (1985) "Data Sources for Parameters Used in Predictive Modeling of Fire Growth and Smoke Spread", NBSIR 85-3223, National Institute of Standards and Technology, Gaithersburg, MD
- Hasegawa, H.K., Staggs, K.J., and Doughty, S.M. (1993), "Fire Testing of 55 Gallon Metal Waste Drums for Dry Waste Storage," Lawrence Livermore National Laboratory, UCRL-CR-115037, 1993.
- Hasemi, Y. (1984), "Experimental Wall Flame Heat Transfer Correlations for the Analysis of Upward Wall Flame Spread," *Fire Science and Technology*, 4 (2), December 30, 1984.
- Heskestad, G. (1983), "Luminous Flame Height of Turbulent Diffusion Flames," *Fire Safety Journal*, 5, p. 103.
- Holman, J.P (Ed.) (1990), *Heat Transfer*, Seventh Edition, McGraw-Hill, Inc., NY.
- Hunter, T. (1979), "Summary of Research and Development Activities in Support of Waste Acceptance Criteria for WIPP," Sandia Laboratories, Albuquerque, NM, SAND79-1305, 1979.
- Joyce, J.P. (1993), "SWBG FHA Combustible Loadings for TRU 55-gallon Drums," Westinghouse Hanford Company Internal Memo JPJ-29540-93-001, October 13, 1993.
- Lie, T.T., (1972), *Fire and Buildings*, Applied Science Pub. Hse., London.
- McCaffrey, B. (1981), "Some Measurements of Radiative Power Output of Diffusion Flames," Western States Section of the Combustion Institute, WSS/CI 81-15.
- McLain, W.H. (1988), "Investigation of the Fire Safety Characteristics of Portable Tanks — Polyethylene Tanks Containing Flammable Liquids," Report No. CG-M-1-88, U.S. Coast Guard, Washington, DC

- Moodie, K. et al. (1987), "Total Pool Fire Engulfment Trials on a 5-tonne LPG Tank," HSE Internal Report No. IR/L/FR/87/27
- Mudan, K.S., and P.A. Croce (1988), "Fire Hazard Calculations for Large Open Hydrocarbon Fires," Section 2/Chapter 4, *The SFPE Handbook of Fire Protection Engineering*, P. DiNenno, Editor-in-Chief, National Fire Protection Association, Quincy, MA.
- National Academy of Science Committee on Hazardous Materials, Division of Chemistry and Chemical Technology, National Research Council (ed.) (1973), *Pressure-Relieving Systems for Marine Cargo Bulk Liquid Containers*, National Academy of Sciences, Washington, DC
- Quintiere, J.G. and M. Harkleroad (1985), "Wall Flames and Implications for Upward Flame Spread," AIAA-85-0456, *ALAA 23rd Aerospace Sciences Meeting*, Reno, NV, January 14-17, 1985.
- Quintiere, J.G. (1988), "Surface Flame Spread," Section 1/Chapter 24, *The SFPE Handbook of Fire Protection Engineering*, P. DiNenno, Editor-in-Chief, National Fire Protection Association, Quincy, MA.
- Russell, L.H., and J.A. Canfield (1973), "Experimental Measurement of Heat Transfer to a Cylinder Immersed in a Large Aviation Fuel Fire," *Journal of Heat Transfer*.
- Sandia (1979), Anno., "Summary of Research and Development Activities in Support of Waste Acceptance Criteria for WIPP," SAND79-1305, Sandia Laboratories, Albuquerque, NM.
- Sparrow, E. and Cess, R. (1978), *Radiation Heat Transfer*, Augmented Ed. (1978) Appendix A, configuration no. 6, Hemisphere Publishing Company, Washington.
- Tavares, R., and M.A. Delichatsios (1981), "Pressure Relief in Flammable-liquid Drums by Pressure-activated and Plastic Bungs," FMRC J.I. 0F0R4.RA 070(A), Factory Mutual Research Corporation, Norwood, MA, March 1981.
- Taylor, A.J. et al. (1975), "Engulfment Fire Tests on Road Tanker Sections," Rarde Technical Report 7/75, Controller HMSO, London.
- Tewarson, A. (1988), "Generation of Heat and Chemical Compounds in Fires," Section 1/Chapter 13, *The SFPE Handbook of Fire Protection Engineering*, P. DiNenno, Editor-in-Chief, National Fire Protection Association, Quincy, MA.
- Thomas, P.H. (1974), "The Effect of Crib Porosity in Recent CIB Experiments," Fire Research Note No. 999, Fire Research Station, Borehamwood, UK, February 1974.

Wachtell, G.P., and J.W. Langhaar (1966), "Fire Test and Thermal Behavior of 150-Ton Lead-Shielded Cask," DP 1070, Engineering and equipment, TID-4500, E.I. DuPont De Nemours and Co.

Appendix A

Review of Fire Test Literature on Solid Waste Drum Storage

Summary

A limited number of tests have been conducted on the response of 17C drums to pool fire exposures and internal explosions (A1-A4). The general results of this testing indicate that drums exposed to pool fires may vent at the lid seal, in some cases throwing the lid some distance and scattering some of the contents. In other cases, the failure of the drum seal results in gas or flame jetting only. Testing involving multi-tiered arrays of drums indicates that, while lower tier drums may vent violently, the pile of drums is not disrupted and the contents of the array remain in the drums. The 0.25-in. plywood between tiers acts as a thermal/flame barrier until it burns through. Internal hydrogen explosion tests show that drum failure is by drum lid seal failure just as in the pool fire tests. Internal explosions can lead to loss of the lid and some of the contents. The pool fire tests and the explosion tests indicate that drum lid seal failures occur over a range of pressure of 1 to 20 psi.

While failure of the drum via drum seam failure is possible, none have been observed in testing. As such, drum failures seem to occur by lid loss via drum overpressure. In many cases lid seals can fail without lid loss. While materials can be lost via pyrolysis without lid loss, active burning of contents requires lid loss.

Pool Fire Exposure Tests

SANL(A1): Tests of 17C solid waste drums exposed to pool fires were conducted by Sandia Laboratories (A1) in support of waste acceptance criteria and hazard analysis for the WIPP site. Two types of tests were conducted. The first test type twelve drums were placed in a 10-ft diameter salt-filled pan, and 50 gallons of diesel fuel was added and ignited. Some of the drums were filled with simulated combustible wastes. Some had plastic liners while others did not. Some of the drums had 1/8-inch vent holes, and others were sealed.

Of the twelve drums tested, one vented unlined drum failed by violently blowing the lid and some contents out of the drum. Two other lined drums vented by flaring, and one lined drum ruptured at the base of the drum late in the test. Eight other drums did not vent or fail. Wind effects may have affected the uniformity of the pool fire exposure. Venting of the drums with 1/8-inch hole did not affect drum behavior.

In a second type of pool fire test, one plastic lined and one unlined drums were exposed to pool fires (no salt bed) with durations of 6.5-8 minutes. In one test, the drums were filled with combustibles while in the other test the drums were empty. The unlined drums failed via lid loss with the unfilled drum failing in 3 minutes (internal pressure of 20 psig) and the filled drum failing in 5 minutes (internal pressure of 14 psig). The plastic lined drums did not fail during the tests.

Of the 16 drums tested, three violently blew their lids. All the drums which failed by lid loss were unlined drums. Of the 5 unlined drums tested, three failed by lid loss. The most rapid lid loss was 3 minutes for the unfilled drum. The other two lid failures were filled drums and occurred in 5-7 minutes. This indicates that the contents of the drums is acting as a heat sink, slowing the venting process. Further, the plastic drum lining appeared to prevent lid loss failures. Drum venting failures for lined drums were all flare/jet failures and did not result in lid loss. The largest jet flame was 4 feet long.

INEL(A2): Two tests were performed with DOT 17C drums and DOT 7A boxes. The first test included five 17C drums in a 6 feet square salt filled pan with 15 gallons of diesel fuel. The drums were plastic lined and the lids were not sealed. All five drum lids popped in the first 3-5 minutes of the intense exposure.

In the second test, 16 drums were stacked in four tiers with 3/8-inch plywood between the tiers. The stacking arrangement is that of interest for the SWBG. Again, the drums were not sealed in this test, and plastic drum liners were used. In this test, no salt was present in the burn pan. Venting of the drums began at 3 minutes into the exposure, and

the pan fire burned for 15 minutes. While the drums vented, the four tier stack was not disrupted. Some lids were dislodged during venting so that flame jet issued from the lid.

In these tests, plastic lined drums did vent, but the drums were not sealed. Based on the SANL tests and other tests on 17C drums, it is not clear if these drums would have vented if sealed. While the unsealed drums in the 4 tier array did vent and did not affect the stability of the array, it is not clear if sealing the drums would have resulted in sufficient venting force to topple the array. The 3/8 inch thick plywood between the first and second tier of drums was entirely destroyed except where protected by the drums, and the plywood between the second and third tiers was severely damaged as judged from a report photo. There was no evidence of serious damage to the plywood between tiers three and four.

LLNL(A4): Five pool fire experiments were conducted using a total of 14 single solid waste drums and four salvage drum assemblies. The pool fires were 6 feet in diameter with the drums occupying less than half that area. As such, the flames were more severe than would be expected in a tight drum array. The fuel used for the tests was isopropanol, a luminous but low soot fuel, chosen to facilitate visual observation throughout the test duration.

Of the 14 single drums tested, three failed by complete lid loss. Times to lid loss ranged from 180 to 270 s. Peak pressure at lid loss was 8.6 to 13.2 psi. Lid seal failures in the remaining 11 drums occurred less violently with a maximum pressure in the range 1 to 14 psi and times to lid seal failure in the range 180 to 345 s.

For this test series, the worst case drum was a violent lid loss at 180 s with a release pressure of 13 psi. The drums which lost their lids, the contents were substantially consumed (8-9 kg of 10 kg were consumed) while other drums lost less than 1.2 kg of their 10 kg load.

Hydrogen Explosion Tests (INEL) (A3): Based on the possible presence of hydrogen in solid waste storage drums, tests were conducted with 14 and 30 percent hydrogen concentrations in 17C drums lined with 90-mil plastic. On ignition, only the 30 percent

hydrogen (stoichiometric) drums failed by loss of the lid. Typically the lid was thrown 100 feet, and drum contents were partially lost. The fraction of material lost from the drum ranged from 0-41 percent. In one test, two drums were filled with stoichiometric hydrogen/air mixtures with one drum stacked on the other. Ignition of the lower drum resulted in autoignition of the upper drum. The lid of the lower drum was not blown off. Pretest pressure testing of the drums yielded venting at about 10 psi.

References

- A1. Hunter, T., "Summary of Research and Development Activities in Support of Waste Acceptance Criteria for WIPP," Sandia Laboratories, Albuquerque, NM, SAND79-1305, 1979.
- A2. Brown, R., "DOT 7A FRP Box Fire Test at the INEL," EG&G Idaho, Inc., TREE-1367, 1979.
- A3. Beers, R., "Gas Generation Studies: Year-end Report, FY 1983," EG&G Idaho, Inc., RHB-387-83, 1983.
- A4. Hasegawa, H.K., Staggs, K.J., Doughty, S.M., "Fire Testing of 55 Gallon Metal Waste Drums for Dry Waste Storage," Lawrence Livermore National Laboratory, UCRL-CR-115037, 1993.

Appendix B

Drum Array Stability Models

Single Stack Pile Stability Model

Loss of pile stability due to lid release from the relief of internal pressure buildup can be modeled using simple conservation of angular momentum principles. We conservatively assume that the lid loaded by drums above rotates about one lid edge in response to the lid release. This rotational response maximizes the contribution of the pressure release to pile instability. The equation of motion of the loaded lid is

$$M = I \dot{\omega} \quad (1)$$

$$M = (P_1 - P_{amb}) A_1 R - L_1 R_1' g \quad (2)$$

where M = moment about the lid edge,
 P_1 = drum pressure,
 A_1 = drum lid area,
 R_1 = drum radius,
 L_1 = lid load (other drums above),
 H_{CG} = height of the center of gravity of the lid load,
 R_1' = distance from edge to CG of loaded drum,
 I = moment of inertia, and
 $\dot{\omega}$ = rate of change of angular velocity.

The first term is the moment applied by the drum overpressure, and the second term is the gravitational restoring moment of the lid load. R_1' varies as the drum stack rotates as indicated in Figure B1. From basic geometry, we find

Figure B1. Model Geometry Nomenclature

$$\frac{R_1}{R_1' + R_1''} = \cos \theta \quad (3)$$

Combining these yields

$$\begin{aligned} R_1'' &= (R_1 \tan \theta + H_{CG}) \sin \theta \\ R_1' &= \frac{R_1}{\cos \theta} - (R_1 \tan \theta + H_{CG}) \sin \theta \end{aligned} \quad (4)$$

The movement of inertia about the edge of rotation is (B1)

$$I = C \frac{5}{4} \pi R^4 = L_1 \frac{5}{4} R_1^2 \quad (5)$$

where C = the load per unit area of drum lid.

The average TRU drum is 80 kg so the load, L_1 , for a base drum in a 4 drum stack is 3 x 80 or 240 kg. The maximum pressure is the initial failure pressure of 34 psia (2.35×10^5 N/m²) and $R_1 = 0.285$ m. This yields an initial angular acceleration of 425 rad/s².

Of course, in practice the pressure quickly decreases due to venting. The venting rate is given by the compressible venting equation (B2)

$$\dot{m}_{vent,1} = \min \left\{ \begin{aligned} &CA_1 \sqrt{\rho_1 P_1} \left[\gamma \left(\frac{2}{\gamma + 1} \right)^{\frac{\gamma + 1}{\gamma - 1}} \right]^{1/2} \\ &CA_1 \sqrt{\rho_1 P_1} \left\{ \frac{\gamma}{\gamma - 1} \left(\frac{P_{amb}}{P_1} \right)^{2/\gamma} \left[1 - \left(\frac{P_{amb}}{P_1} \right)^{\frac{\gamma - 1}{\gamma}} \right] \right\}^{1/2} \end{aligned} \right\} \quad (6)$$

where the first expression is for choked (sonic) flow. In this problem, the initial pressure in the drum will lead to choked flow, but later the flow will cease to be choked. The vent area changes with time and is yet to be determined.

We will consider that heating rates and volatilization rates which yield the initial 20 psig are slow relative to the venting and can be ignored during venting. The drum will be taken to be substantially empty ($V = 0.2 \text{ m}^3$).

Conservation of mass for the drum yields

$$\frac{dm_d}{dt} = -\dot{m}_{vent} \quad (7)$$

Since venting is rapid, we will take the process to be adiabatic (B3).

$$m_d(t) = m_d(0) \left(\frac{P_1(t)}{P_1(0)} \right)^{1/\gamma} \quad (8)$$

Taking derivatives of both sides of Equation 8 with respect to time yields

$$\frac{dm_d}{dt} = \frac{m_d(0)}{P_1(0)^{1/\gamma}} \frac{d}{dt} (P_1^{1/\gamma}) = \frac{m_d(0)}{P_1(0)^{1/\gamma}} \frac{1}{\gamma} P_1^{\frac{1}{\gamma}-1} \frac{dP}{dt} \quad (9)$$

Equating to Equation 9 and solving for dp/dt yields

$$\frac{dP_1}{dt} = -\dot{m}_{vent} \frac{\gamma P_1(0)^{1/\gamma}}{m_d(0)} P_1^{\frac{\gamma-1}{\gamma}} \quad (10)$$

$m_d(0) = V_{\text{drum}} \rho_0$, the initial contents of the drum.

Equation 10 needs to be integrated along with the following equations to deduce the rotational dynamics of the loaded lid. It should be noted that if in the course of the drum release, R_1' becomes negative the drum stack will fall, whereas if it remains positive the lid will fall back onto the drum.

$$\begin{aligned}
 w &= \int_0^t \dot{w} dt & \dot{w}(0) &= \text{known} \\
 \theta &= \int_0^t w dt & w(0) &= \theta(0) = 0
 \end{aligned}
 \tag{11}$$

It remains to determine the vent area as a function of the lid opening angle, θ .

The vent/leak area, A_v , is dependent on the lid angle, θ , and can be determined by integration around drum perimeter (see Figure B1)

$$A_v = 2 \int_0^\pi h R d\phi \tag{12}$$

where h = the height of the lid above the drum,
 R = the radius of the drum, and
 ϕ = the angle in the drum top plane about the drum centerline.

h is given by the distance from the rotational edge, X , and the rotation angle, θ , as

$$h = X \tan \theta \tag{13}$$

X can be related to the angle ϕ by geometry

$$\begin{aligned}
 \frac{R - X}{R} &= \cos \phi \\
 \text{or } X &= R (1 - \cos \phi)
 \end{aligned}
 \tag{14}$$

Substituting into the A_v equation yields

$$\begin{aligned}
 A_v &= 2 \int_0^\pi R (1 - \cos \phi) \tan \theta R d\phi \\
 A_v &= 2 R^2 \tan \theta \int_0^\pi (1 - \cos \phi) d\phi = 2 \pi R^2 \tan \theta
 \end{aligned}
 \tag{15}$$

The equations to be solved simultaneously are Equations 10 and 11 with Equations 1, 2, 4, 5, 6, and 15 as subsidiary equations. These calculations were implemented in MathCad.

Multiple Stack Pile Stability Model

The multiple stack model as developed in this section is intended to partially account for the effect of the plywood in stabilizing the drum array. While in practice the plywood is used to integrate the array through staggered orientation in the array, this model deals only with the only a multiple drum stack where all of the interacting drums are piled on the same sheets of plywood (see Figure B2). As such, the calculation is conservative in that it ignores array interconnections which exist in the arrays. Rotation is assumed to be about the minor axis of the 4 x 8 ft sheet.

The model follows the basic approach of the single stack model with the addition of several generalizations of that model. As such, this section will include only additions and modifications to the single stack model.

The most important difference between the single and multiple stack model is the addition of a second stack/center of gravity. Figure B2 illustrates the situation. Within this context up to eight drums/tier on a single sheet of plywood can be treated. An important assumption in this model is that the plywood sheet is assumed to remain plane and the multiple drum lids rotate about the same axis. This is again a conservative assumption in that the right drum lid which rotates 2θ for a rotation of θ of the other drum could lift rather than rotate and as such would vent more rapidly.

The moment equation for the situation pictured in Figure B2 is includes a pressure and gravity term for each of the drum rows. The moment is given by

$$M = nP_1 (P_1 - P_{amb}) A_1 R_1 - n_1 L_1 R_1' g + nP_2 (P_2 - P_{amb}) A_2 R_2 - n_2 L_2 R_2' g \quad (16)$$

Figure B2. Multiple Drum Model Geometry

The index np_1 is the number of drums in this row that release simultaneously, and n_1 is the total number of drums in that row. Similarly, np_2 is the number of drums in row two that release simultaneously, and n_2 is the total number of drums in row two. n_1 and n_2 can be as high as four (one full plywood sheet), and np_1 and np_2 may take on any value up to n_1 and n_2 . R_2 can be taken to be equal to $3R_1$, ignoring the small gap between drums. Using this yields the following expression for R_2'

$$R_2' = \frac{3R_1}{\cos \theta} - (3R_1 \tan \theta + H_{CG2}) \sin \theta \quad (17)$$

The venting equation for the second drum row is the same as for the single drum case except that the rotation angle is 2θ as shown in Figure B2.

$$A_{v2} = 2\pi R_2 \tan(2\theta) \quad (18)$$

Finally, the moment of inertia for the drums about the axis of rotation is given by

$$I = n_1 \frac{5}{4} L_1 R^2 + n_2 \frac{37}{4} L_2 R^2 \quad (19)$$

The second term dominates due to the $3R$ lever arm.

This results in four simultaneous equations to be solved; two pressure equations, the angular velocity equation, and the angle equation. These have been solved using MathCad. The attached MathCad model implements the multiple drum stack model.

Calculate the rotation of a loaded drum lid subject to a drum overpressure failure.

```

L := 240.          lid load on each stack, kg
n := 4.            number of drums in initial row
np := 0.           number of pressure release drums in init row
Ll := 240.         restraining load on each second row stack, kg
nl := 4.           number of drums in second row
npl := 2.          number of pressure release drums in 2nd row
HCG := 1.33        height of center of gravity of lid load, m
HCGl := 1.33       ht of center of gravity of second lid, m
R := 0.285         drum radius, m
                    5
P0 := 2.35 · 10    initial drum release pressure, N/m2

VD := 0.2          drum volume, m3
dt := 0.001        time step, s
T := 0.8           run time, s
CD := 0.6          discharge coefficient
                    5
Pamb := 1 · 10     ambient pressure, N/m2
Tamb := 293.       ambient temperature, K
k := 1.4           ratio of specific heats
g := 9.8           acceleration due to gravity, m/s2
TH0 := 0.          initial lid angle, rad
w0 := 0.           initial lid angular velocity, rad/s
DN := 20           size of output table

i := 0 ..  $\frac{T}{dt}$ 

ti := i · dt

I := n · L2 · 1.25 · R2 + nl · 9.25 · Ll2 · R2  moment of inertia loaded lids, kgm2

Alid := 3.14159 · R2  lid area, m2

T0 :=  $\frac{P0}{Pamb}$  · Tamb  initial drum gas temperature, K
T0 = 688.55

RH00 := P0 · 10-5 ·  $\frac{353}{T0}$   initial drum gas density, kg/m3
RH00 = 1.205

```

$$AO := \frac{P0}{353 \cdot \frac{1}{k} \cdot \frac{1}{Tamb}} \cdot k$$

constant in pressure equation

$$AO = 39871.998$$

$$P := 2 \cdot 10^5 \quad TH := 0.1$$

$$MOM(P, P1, TH) := np \cdot (P - Pamb) \cdot (Alid \cdot R) - n \cdot L \cdot g \cdot \left[\frac{R}{\cos(TH)} - (R \cdot \tan(TH) + HCG) \cdot \sin(TH) \right] \dots$$

$$+ np1 \cdot (P1 - Pamb) \cdot Alid \cdot 3 \cdot R - n1 \cdot L1 \cdot g \cdot \left[\frac{R \cdot 3}{\cos(TH)} - (R \cdot 3 \cdot \tan(TH) + HCG1) \cdot \sin(TH) \right]$$

$$A := MOM(P, P, TH)$$

$$A = 35461.856$$

$$MVENT(P, TH) := CD \cdot R^2 \cdot 6.28 \cdot \tan(TH) \cdot \sqrt{\frac{1}{k} \cdot \frac{-1}{k}} \cdot \sqrt{RHO0 \cdot P} \cdot P0 \cdot \min \left[\sqrt{k \cdot \frac{2}{1+k}} \cdot \frac{1+k}{k-1}, \sqrt{\frac{2}{k} \cdot \frac{k-1}{k}} \cdot \left[\frac{k}{k-1} \cdot \frac{Pamb}{P} \cdot \left(1 - \frac{Pamb}{P} \right) \right] \right]$$

$$A := MVENT(P, TH)$$

$$A = 6.878$$

$$\begin{bmatrix} TH \\ 0 \\ w \\ 0 \\ P \\ 0 \\ P1 \\ 0 \end{bmatrix} := \begin{bmatrix} 0 \\ 0 \\ P0 \\ P0 \end{bmatrix}$$

WFOC SD WFF TNA 005 REV. 0

$$j := 0, \text{floor} \left[\frac{N}{DN} \right] \dots \min \left[\frac{N}{dt} \right]$$

t_j
0
0.033
0.066
0.099
0.132
0.165
0.198
0.231
0.264
0.297
0.33
0.363
0.396
0.429
0.462
0.495
0.528
0.561
0.594
0.627
0.66

TH	j
	0
	0.03
	0.089
	0.14
	0.181
	0.213
	0.239
	0.258
	0.272
	0.281
	0.285
	0.284
	0.28
	0.27
	0.255
	0.235
	0.209
	0.175
	0.133
	0.081
	0.017

w	j
	0
	1.703
	1.692
	1.373
	1.102
	0.871
	0.671
	0.496
	0.338
	0.193
	0.054
	-0.082
	-0.221
	-0.368
	-0.527
	-0.706
	-0.91
	-1.145
	-1.421
	-1.747
	-2.132

[illegible][illegible]

References

- B1. Housner, G.W. and D.E. Hudson, *Applied Mechanics Dynamics*, Second Edition, Van Nostrand Company, Inc., NY, 1959.
- B2. Emmons, H.W., "Vent Flows," Section 1/Chapter 8, *The SFPE Handbook of Fire Protection Engineering*, P. DiNenno, Editor-in-Chief, Society of Fire Protection Engineers, Boston, MA, 1988.
- B3. Wark, K. Jr., *Thermodynamics*, 5th Edition, McGraw-Hill Book Company, NY, 1988.

REVIEW COMMENT RECORD (RCR)

1. Date 24 May 1995	2. Review No. WAES-95-151
3. Project No. WHC-SD-WM-FHA-009	4. Page 1 of 4

5. Document Number(s)/Title(s) PRELIMINARY FIRE HAZARDS ANALYSIS FOR THE PUTDR AND TRU WASTE BURIAL GROUND	6. Program/Project/ Building Number WHC-SD-WM-FHA- 009	7. Reviewer J R KEENE	8. Organization/Group WAES FIRE PROTECTION	9. Location/Phone MO-286/373-9018
---	---	--------------------------	---	--------------------------------------

17. Comment Submittal Approval: <i>[Signature]</i> 4/15/95 Organization Manager (Optional)	10. Agreement with indicated comment disposition(s) 16 June 95 Date <i>[Signature]</i> Reviewer/Point of Contact <i>[Signature]</i> Author/Originator	11. CLOSED 16 June 95 Date <i>[Signature]</i> Reviewer/Point of Contact <i>[Signature]</i> Author/Originator
--	---	--

12. Item	13. Comment(s)/Discrepancy(s) (Provide technical justification for the comment and detailed recommendation of the action required to correct/resolve the discrepancy/problem indicated.)	14. Hold Point	15. Disposition (Provide justification if NOT accepted.)	16. Status
i			The RCR comment responses reflect the position that the preliminary FHA cannot be revised. Consequently, any comments that are strictly editorial in nature cannot be addressed in this report. Comments that are of a technical nature will be addressed in the final FHA for burial grounds.	
1	Section 3.0, second paragraph, General Comment: Why are some trenches not covered with dirt? Covering the trench and contents with dirt appears the best method of mitigating potential fires.		Accept in Principle - This comment will be addressed in the operations section of the burial grounds final FHA.	
2	Section 5.1, last paragraph on page 5, first sentence: Though the radiological concern is the major hazard analyzed by a SAR. This statement or conclusion is not accurate from a fire protection point of view as many fires result in an IDLH situation and most radiological releases can not result in such a situation. The first sentence should be deleted.		Accept in Principle - The Preliminary FHA cannot be revised. The final FHA for burial grounds will consider the comment and evaluate the reviewers concern.	

REVIEW COMMENT RECORD (RCR)

1. Date

24 May 1995

2. Review No.

WAES-95-151

3. Project No.

WHC-SD-WM-FHA-009

4. Page

2 of 4

12. Item	13. Comment(s)/Discrepancy(s) (Provide technical justification for the comment and detailed recommendation of the action required to correct/resolve the discrepancy/problem indicated.)	14. Hold Point	15. Disposition (Provide justification if NOT accepted.)	16. Status
3	Section 5.1, General Comment: This section should outline those features of the PUTDR/TRU trenches which constitute fire hazards. As written, this section restates the possible fire scenarios. These scenarios may not be appropriate for this section. The actual and/or expected hazards should be dealt with in some detail.		Accept in Principle - This comment will be addressed in the fire hazards section of the burial grounds final FHA.	
4	Section 5.1, page 6, first paragraph, last sentence: This sentence indicates no noncombustible materials are included in any of the drums. Upon what basis is this statement made?		Accept in Principle - This comment will be addressed in the operations section of the burial grounds final FHA.	
5	Section 5.1.1, first paragraph, last two sentences: It appears contradictory to state (earlier in this document) "an unloaded drum blew its lid off in three minutes" and later state combustible drum contents tend to slow drum lid failure, finally concluding "three minute exposure criteria conservative for loaded drums." Please explain and provide supporting data.		Accept in Principle - This comment will be addressed in the fire hazards section of the burial grounds final FHA.	
6	Section 5.1.1.1, first paragraph, third sentence: Uncertainty as to grade of fuel oil used in the test, would it be more applicable to <i>assume</i> data based upon fuel grade diesel?		Accept in Principle - This comment addresses assumptions and limitations resulting from the limited fire test data base available on diesel fuels. The fire hazards section of the burial grounds FHA will consider the comment with respect to the fire hazards that are identified.	
7	Section 5.1.1.1, General Comment: It appears we are making a number of assumptions. Within this section assumptions are made for the grade of fuel, the pan size, and the burn time. We should work to nail down some of these details a little more accurately or base our work on more well documented test data.		Accept in Principle - The Preliminary FHA cannot be revised. The final FHA for burial grounds will consider the comment and evaluate the reviewers concern.	

REVIEW COMMENT RECORD (RCR)

1. Date

24 May 1995

2. Review No.

WAES-95-151

3. Project No.

WHC-SD-WM-FHA-009

4. Page

3 of 4

12. Item	13. Comment(s)/Discrepancy(s) (Provide technical justification for the comment and detailed recommendation of the action required to correct/resolve the discrepancy/problem indicated.)	14. Hold Point	15. Disposition (Provide justification if NOT accepted.)	16. Status
8	Section 5.1.1.1, page 8, first paragraph following Table 1, last sentence: The conclusion 60 kW/m ² is conservative does not appear supported by the data referenced. This conclusion appears to be 20% less than the lowest data point cited.		Accept in Principle - The Preliminary FHA cannot be revised. The final FHA for burial grounds will consider the comment and evaluate the reviewers concern.	
9	Section 5.1.1.1, page 9, top of page, last sentence in the paragraph: Is there experimental data which may provide more appropriate and useful data? The data used appears to require an excessive number of assumptions.		Accept in Principle - The Preliminary FHA cannot be revised. The final FHA for burial grounds will consider the comment and evaluate the reviewers concern.	
10	Section 5.1.1.1, Page 9, second paragraph, first sentence: This sentence <i>assumes</i> drum dimensions to be those reported in ANSI Standard MH2-1991. Is this standard consistent with those which the are specified for the drums used at Solid Waste?		Accept in Principle - This comment will be addressed in the operations section of the burial grounds final FHA.	
11	Section 5.1.4.1: Would not the backfill also protect trench contents from exposure fires?		Accept in Principle - This comment will be addressed in the operations section of the burial grounds final FHA.	
12	Section 5.1.5, first paragraph, second sentence: Please provide explanation as to why the drum contents are considered analogous to trash bags.		Accept in Principle - The Preliminary FHA cannot be revised. The final FHA for burial grounds will consider the comment and evaluate the reviewers concern.	
13	Section 5.1.5, page 18, second paragraph, last sentence: Why is it a "reasonable assumption" that we reduce the heat release to 50kW and increase the burning duration to 7 hours?		Accept in Principle - The Preliminary FHA cannot be revised. The final FHA for burial grounds will consider the comment and evaluate the reviewers concern.	
14	Section 5.1.7, page 37, first paragraph: Flash points for the liquids noted should be included.		Accept in Principle - This comment will be considered during the completion of the final FHA for burial grounds.	

REVIEW COMMENT RECORD (RCR)

1. Date

24 May 1995

2. Review No.

WAES-95-151

3. Project No.

WHC-SD-WM-FHA-009

4. Page

4 of 4

12. Item	13. Comment(s)/Discrepancy(s) (Provide technical justification for the comment and detailed recommendation of the action required to correct/resolve the discrepancy/problem indicated.)	14. Hold Point	15. Disposition (Provide justification if NOT accepted.)	16. Status
15	Section 5.1.7, page 37, first paragraph, last sentence: This sentence questions the number of propane tanks possible in the trenches. No reasonable effort is made to address this question.		Accept in Principle - This comment will be considered during the completion of the final FHA for burial grounds.	
16	Section 5.1.7, page 37, second paragraph: This paragraph appears to state the heat content of flammable/combustible liquids, combustible metals, reactive metals, and flammable gases are similar to other materials. This office finds this conclusion difficult to handle. Please explain.		Accept in Principle - The Preliminary FHA cannot be revised. The final FHA for burial grounds will consider the comment and evaluate the reviewers concern.	
17	Same section and paragraph: While the heating due to a fireball are passed off as not significant, are the blast effects of such an event analyzed?		Accept in Principle - The Preliminary FHA cannot be revised. The final FHA for burial grounds will consider the comment and evaluate the reviewers concern.	
18	Section 5.1.7, Page 37, third paragraph: There appears to be a tacit assumption there will be no standing liquids in any of the subject drums. Please verify and support this conclusion.		Accept in Principle - This comment will be addressed in the operations section of the burial grounds final FHA.	
19	Section 7.0, second sentence: This sentence indicates "normal concerns regarding life safety are not applicable." That may be true in the sense we are not dealing with a building. However, the design and arrangement of some of the trenches appears to provide potential for life safety related hazards including; one excessively long route of egress, no means for notification of emergency, close working proximity to hazardous materials. Please re-address this issue.		Accept in Principle - This comment will be addressed in the burial grounds final FHA.	
20				