UNCLASSIFIED

Photostat Price \$ 10.80

Microfilm Price \$ 3.90

Available from the
Office of Technical Services
Department of Commerce
Washington 25, D. C.

ANL-5465(Del.)

ARGONNE NATIONAL LABORATORY
P. O. Box 299
Lemont, Illinois

DELETED VERSION

Classification change to Unclassified
Authorized by H.F. Connell 2-12-57
Change by H. Kinon Date 6-18-72

QUARTERLY REPORT
APRIL, MAY, AND JUNE 1955

DELETED VERSION

METALLURGY DIVISION

Frank G. Foote, Director
James F. Schumar, Associate Director

LEGAL NOTICE

This report was prepared as an account of Government sponsored work. Neither the United States, nor the Commission, nor any person acting on behalf of the Commission:

A. Makes any warranty or representation, express or implied, with respect to the accuracy, completeness, or usefulness of the information contained in this report, or that the use of any information, apparatus, method, or process disclosed in this report may not infringe privately owned rights; or

B. Assumes any liabilities with respect to the use of, or for damages resulting from the use of any information, apparatus, method, or process disclosed in this report.

As used in the above, "person acting on behalf of the Commission" includes any employee or contractor of the Commission to the extent that such employee or contractor prepares, handles or distributes, or provides access to, any information pursuant to his employment or contract with the Commission.

November, 1955

Operated by The University of Chicago
under

Contract W-31-109-eng-38

UNCLASSIFIED

264 001

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency Thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

DISCLAIMER

Portions of this document may be illegible in electronic image products. Images are produced from the best available original document.

3

TABLE OF CONTENTS

	<u>Page</u>
ABSTRACT	7
I. ADVANCED WATER REACTOR PROGRAM ■	
1. Fabrication of Zircaloy-Clad Uranium Alloy Fuel Plates	15
a. Effect of Orientation of Zircaloy-II on Roll-Bonded Plate End Closures	15
b. Cladding Billets with Introduced Assembly and Rolling Variables	19
c. Fabrication and Evaluation of Uranium- 5 w/o Zirconium Alloy Clad Plates	22
d. Evaluation of Clad Uranium-5 w/o Zirconium- 1.5 w/o Niobium Alloy Plates Scaled to EBWR-Size Fuel Elements	25
2. Fabrication of Zircaloy-Clad EBWR Subassembly . . .	26
II. FAST POWER BREEDER REACTOR PROGRAM ■	
1. Plutonium-Aluminum Fuel Slugs for EBR-I.	27
2. Resistance of Uranium-Plutonium Alloys to Attack by Sodium	27
III. ADVANCED ENGINEERING AND DEVELOPMENT: METALLURGY ■	
1. Melting and Casting of Uranium and High Uranium Alloys	28
a. Graphite Crucibles and Washes.	29
b. Graphite Molds, Mold Washes, and Mold Insulation	30
c. Ingot Quality	31
2. Welding Borax Fuel Subassemblies	32
3. Thoria-Urania Ceramic Fuel Bodies	32
4. Properties of Urania-Thoria Bodies	32
5. Rare Earth Ceramic Bodies	33
6. Vanadium Base Alloys.	33

TABLE OF CONTENTS

	<u>Page</u>
IV. PRODUCTION, TREATMENT AND PROPERTIES OF METALS	
1. Preparation of Alpha-Uranium Single Crystals	36
a. Effects of Carbon Segregation.	36
b. Effects of Rolling Schedules	36
2. Recrystallization Textures of Deformed Alpha- Uranium Single Crystals	39
3. Identification of Inclusions in Uranium	41
4. Uranium-Carbon Phase Diagram Liquidus	44
5. Uranium-Zirconium Alloys	45
a. Equilibrium Phases Below 600° C.	45
b. Structure of the Epsilon Phase	48
6. Uranium-Zirconium-Niobium Alloys	49
a. Phase Diagram	49
b. Heat Treatment and Properties.	49
7. Properties of Uranium-Plutonium-Fissium Alloys.	52
V. AQUEOUS CORROSION	
1. High Temperature Aqueous Corrosion of Aluminum	55
a. 2S Aluminum-Nickel Alloys	55
b. Effect of Iron and Silicon Additions to Aluminum- Nickel Alloys.	59
c. Effects of Other Alloying Constituents	61
d. Solution Additives.	61
2. Mechanism of Zirconium Corrosion.	61
3. Corrosion-Resistant Uranium Alloys	62
a. Uranium-5 w/o Zirconium-1.5 w/o Niobium Alloys	62
b. U-5 w/o Zr-1.5 w/o Nb Alloy Clad with Zircaloy-II	64
c. Epsilonized Uranium-Silicon Alloys.	64
d. Postirradiation Corrosion Tests	67

5
TABLE OF CONTENTS

	<u>Page</u>
VI. EFFECTS OF IRRADIATION ON MATERIALS. ■ [REDACTED]	
1. Effects of Irradiation on Uranium Powder Compacts. . .	68
2. Effects of Irradiation on Corrosion-Resistant Uranium Alloys	70
a. U-5 w/o Zr-1.5 w/o Nb Alloy	70
b. U-3.8 w/o Si Alloy	71
c. U-3.0 w/o Nb-0.48 w/o Sn Alloy.	71

DECLASSIFIED

264 004

7

QUARTERLY REPORT
APRIL, MAY, AND JUNE 1955
METALLURGY DIVISION

ABSTRACT

Advanced Water-Cooled Reactor [REDACTED]

A total of 38 cladding billets of the U-5 w/o Zr-1.5 w/o Nb EBWR core alloy were roll-bonded with Zircaloy-II by the modified picture frame technique to study the effects of Zircaloy deformational anisotropy upon bond quality, the limitations of the cladding billet assembly procedure, and optimum rolling practices. Nineteen of these were scaled to full-size EBWR fuel plates for experimental reactor subassemblies. Radiographs of these plates indicated a uniform core distribution. Close control of total reductions and final mill settings improved the core length uniformity over previously rolled plates. Ultrasonic through-transmission tests indicated complete bonding at all clad-to-core and clad-to-clad interfaces in 18 out of 19 plates tested; the latter had a 1/4" x 1" unbonded area between the cover plate and side strip at one end due to contamination of the mating surfaces.

Studies on the deformational anisotropy of rolled Zircaloy-II led to a better understanding of the roll-bonding process, particularly as it relates to the bond between the Zircaloy side strip and the end plug; in previous practice this was the most difficult bond to achieve. Hot-rolling, pressing, and forging studies indicated that Zircaloy exhibits deformational anisotropy in different directions in a manner related to its prior hot-working history. By selecting the proper orientation of the end plug which will result in a maximum side spread, excellent end plug to side strip bonds were obtained which showed no defects or inclusions. In plates for which the end plug orientation was not properly selected the bonds contained numerous segmented or continuous defects.

Roll-bonded plates from cladding billets which were assembled with thoroughly cleaned components, purged during welding, and containing no intentionally introduced defects, showed excellent bonding throughout between the core and cladding as well as at the Zircaloy interfaces. Several billets with an intentionally introduced light fluoride deposit on the side strips also showed no bond defects. Billets which contained intentional weld defects between the cover plates and the end plug, however, contained semicontinuous inclusions in the vicinity of the defect; similarly, welding defects in the steel jackets generally resulted in inferior Zircaloy-to-Zircaloy bonds. The results point up the significance of the weld integrity in attaining good bonding.

204-005

Continued static corrosion tests on previously rolled plates showed no evidence of failure after 1018 hours in 290°C water. One plate with a 1/16" diameter hole drilled through the cladding into the core was corrosion tested for 59 hours in 290°C water. Localized corrosion occurred over an area approximately 7/16" in diameter, with the formation of loose black oxide and rupture of the cladding in the shape of a 1/2" diameter disc over the corroded area. Except for a small bump on the surface opposite the corroded area no blistering or separation at the clad-to-core bond was noted. The alloy core material in this plate was not heat treated for corrosion resistance.

One full-size, Zircaloy-II-clad EBWR fuel assembly has been fabricated by heliarc spot welding. Welds produced were of sufficient strength to withstand service conditions. Corrosion tests, however, indicated that the shielding provided by the welding grade argon supplied to the welding pistol is not sufficient; additional shielding of the work during welding will be required.

Seven cladding billets were prepared with U-5 w/o Zr alloy cores to determine whether improvement could be made in cladding this alloy in the event of its possible use as a substitute for the ternary alloy in EBWR fuel plates. The billets were scaled to full EBWR size plates and were roll-clad with Zircaloy-II using the same techniques as for the ternary alloy cores. The uniformity of the plate size, surface finish, and end effects were greatly affected by cladding temperature variations. The surfaces of plates rolled at 850°C with 0.020" nominal cladding were quite rough, with regular depressions of 0.010" to 0.020" at 1/4" intervals throughout the plate surface. Increasing the cladding thickness to 0.025" improved the surfaces, but slight depressions were still evident. The surface irregularities are due to differences in the hot-working properties of the core and cladding. Roll cladding at 800°C and 900°C intensified the surface irregularities: at 800°C the core did not deform as readily as the clad, and the reverse occurred at 900°C. In plates rolled below 900°C the end effects were bad at the core-to-clad transition; this was improved somewhat by increasing the length of the preshaped end tapers. Complete bonding was obtained at all clad-to-core interfaces and between the various cladding components in six out of seven plates. The diffusion bonds were uniform throughout each plate but varied with rolling temperature.

Fast Power Breeder Reactor

The necessary equipment and materials have been shipped to Rocky Flats to help them fabricate, test, and ship the plutonium-aluminum fuel slugs for EBR-I. Procedures and specifications have been worked out and mutually agreed upon.

Uranium-plutonium alloy castings containing 10, 15, and 20 w/o plutonium showed no attack after exposure of 165 hours in clean sodium at 450°C.

CONFIDENTIAL

62-006

Advanced Engineering and Development: Metallurgy

Grade C Bureau of Mines sponge zirconium worked satisfactorily as an alloying addition in making small melts (25 kg) of U-5 w/o Zr-1.5 w/o Nb alloys. It evolved considerable gas and/or vapor, stirring up the melt, and aiding in the solution of the alloying additions. Grade A sponge was less satisfactory. For larger melts (80 to 100 kg) Grade C sponge gave rise to considerable frothing, causing overflow. A reactor grade sponge from the Carborundum Company gave almost no melt action at all. Using a mixture of 25% Grade C sponge and 75% Carborundum reactor grade sponge yielded satisfactory agitation conditions.

The most satisfactory graphite crucible coating for melting the ternary alloys was found to be the following: one thin coat of brushed-on magnesium-zirconate, air-dried for several hours; then one coat of brushed on magnesium zirconate allowed to air-dry overnight; then one heavy coat of thoria applied by spraying. The wash is good for just one melt and affords a ceramic lining for as high as 1600°C, with no attack on the crucible. Slight attack was noted, however, when melting uranium-zirconium alloys of higher zirconium concentrations (7 to 10 w/o Zr).

Magnesium zirconate was adopted as a mold wash for the ternary alloy castings. A single thin coat adheres satisfactorily for one heat. The advantage of the magnesium zirconate over the slaked lime used previously is that the coated mold may be stored for several days before use without detrimental effects.

To make castings from which a number of EBWR cores could be obtained, molds were designed with cavities 1-1/8" x 10-3/4" in cross section by 32" deep. The cavities were designed so that the end tapers were cast to shape. Some of these cast slabs were of sufficient length to yield seven EBWR cores. These multiple EBWR core castings, weighing 80 to 110 kg each, contained concave shrinking defects 0.020" - 0.050" deep which did not clean up in the grinding operation, since only 0.030" per face was allowed for clean-up in the mold design. This difficulty was overcome by increasing the pouring hole to 5/8" diameter and by insulating the side faces of the mold to provide a suitable temperature gradient. It is felt that long, thin slab castings of satisfactory quality can be produced which will yield at least seven EBWR cores.

A spot-welded fuel subassembly for the Borax-III has been designed and tested. A full reactor loading based on this design has been made by ANL Central Shops.

Ceramic cylinders, 1/4" in diameter by 1/2" in length, consisting of 90 w/o ThO₂ and 10 w/o highly enriched U₃O₈, were compounded and fired at 1830°C. Their average density was 10.06 g/cc, with an apparent porosity

of 1.3%. The pellets were canned in aluminum-1 w/o nickel alloy tubes and submitted for irradiation tests in CP-5 and MTR. Some of the canned assemblies were bonded with metallic purified lead; others were unbonded.

A group of ceramic specimens containing from 10 to 90 w/o U_3O_8 in increments of 10 percent in ThO_2 were pressed and fired at $1830^\circ C$ in air. Bodies with more than 60 w/o U_3O_8 were cracked. The densities decreased with increasing U_3O_8 content, varying from 10.0 g/cc for the 10 w/o U_3O_8 composition to 8.8 g/cc for the 90 w/o U_3O_8 composition.

Sintering of Sm_2O_3 - Gd_2O_3 powder mixtures containing 26 w/o Gd_2O_3 at $1200^\circ C$ failed to increase the bulk density of the powder mixtures above 1.07 g/cc; pressing, firing at $1200^\circ C$, and crushing to <100 mesh raised the density to 2.21 g/cc. Additions of 0.5 w/o of B_2O_3 followed by pressing, firing, and recrushing to <50 mesh raised the density of the powder mixtures to 4.40 g/cc.

A study has been initiated to study the feasibility of using vanadium-base alloys as fuel element cladding material in the temperature range $650^\circ - 800^\circ C$. Preliminary screening tests on thermal conductivity and corrosion in sodium at $800^\circ C$ indicate that vanadium-base alloys with 20 w/o titanium or 3 w/o silicon may be competitive with pure zirconium. These alloys will be tested for their high temperature strength at $650^\circ - 800^\circ C$.

Production, Treatment, and Properties of Metals

It was postulated in the last quarterly report (ANL-5439) that the adverse peripheral coarsening encountered in attempts to prepare alpha-uranium single crystals about 1 cm in diameter might be due to concentration of residual impurities at the center of the larger castings, or to nonuniform deformation in the step reduction process. Ingots with and without carbon concentration variations from center to surface and with no detectable segregation of other impurities all showed the tendency for the coarsening to start at the outer regions of the cross section. The anomalous behavior, therefore, cannot be attributed to impurity segregation. Studies on the step reduction variables indicated that the degree of banding and the variations in the penultimate grain size were greater the fewer the number of reduction steps. However, even in fabrication schedules with an increased number of reduction steps, when the first two or three reductions were of the order of 10 - 15%, the matrix grain size increased with distance from the surface, thus confining the initiation of coarsening to the peripheral regions. Experiments are presently being directed toward increasing the degrees of reduction in the first few passes. Preliminary results indicate this modification in the reduction schedule may be effective in producing a uniform and small matrix grain size.

Orientation studies of recrystallized grains in one more deformed alpha-uranium single crystal have confirmed the previously reported observations that the orientations are related to the original orientation of the crystal and/or its twins by a rotation of about 32° about an axis corresponding to approximately a $\langle 212 \rangle$ direction.

Inclusions found in liquated uranium ingots have been removed from polished surface by a sonic microchisel technique and collected on the tip of a 0.005" diameter quartz fiber for X-ray diffraction studies. Ingots liquated in graphite crucibles, and therefore of high carbon content, contained microscopic dendritic inclusions in the center and angularly shaped inclusions at the top. Both types yielded UC diffraction patterns only, with a unit cell size (a_0) corresponding to that reported in the literature. Two types of inclusions were removed from an ingot which was nitrated at $1440^\circ - 1475^\circ\text{C}$ and contained high nitrogen and carbon contents. One type etched gray and yielded a face-centered cubic pattern with $a_0 = 4.92 \text{ \AA}$; the size of the unit cell would indicate this inclusion to be a solid solution of UC and UN. A second type of inclusion, etching dark, yielded a UO_2 pattern only. The X-ray results were consistent on several samples, and it is believed that a positive identification of the carbide, carbide-nitride, and dioxide inclusions in uranium metal has been made in correlation with their metallographic and microstructural characteristics.

Studies to determine the liquidus curve of uranium-carbon alloy of low carbon concentrations by saturation experiments have led to abnormally high saturation concentrations, as compared with values previously obtained in liquation experiments. The reasons for the discrepancy are as yet not evident.

X-ray diffraction patterns of powder specimens of 59 w/o and 46 w/o Zr-U alloys, taken "at temperature" after various treatments, indicated that the equilibrium phases at 600°C are alpha uranium and alpha zirconium. Room temperature retained gamma filings may be made to transform through the following sequence:

Back-reflection Laue photograms from a single crystal of the epsilon phase obtained at 45° rotations about an axis parallel to one of its major axes yield fourfold symmetry at the 0° , 90° , 180° , and 270° positions, and two-fold symmetry at the 45° , 135° , 225° , and 315° positions. Upon positioning the crystal such that the (111) plane was perpendicular to the X-ray beam, threefold symmetry was obtained. Rotation and equi-inclination Weissenberg photographs for seven layer lines were indexed

according to a body-centered cubic unit cell with an a_0 approximately 10.69 Å. This value is slightly less than three times the a_0 of the parent gamma phase.

A partial binary phase diagram has been constructed for uranium-niobium alloys up to 5 w/o niobium. The beta-to-alpha peritectoid horizontal was located at 667°C. Metallographic observations also indicated a eutectoid reaction between 660°C and 640°C at higher niobium concentrations. The gamma-phase bounding surface has been determined for the ternary system U-Zr-Nb up to 8 w/o zirconium and 5 w/o niobium.

Scanning the (111) reflection from a number of specimens of a U-5 w/o Zr-1.5 w/o Nb alloy which were gamma quenched and aged at various temperatures in the alpha-phase region indicated considerable line shifting as a function of aging temperature and time. The results correlate qualitatively with previous observations of increasing hardness and the loss of corrosion resistance on aging.

Additions of 5 w/o molybdenum to as cast U-21 w/o Pu alloys appear to refine the grain size and to increase the hardness only slightly. The machinability is improved over the binary alloy. As cast, the alloy is predominantly body-centered cubic, indicating the stabilization of the isotropic cubic phase. It is hoped that this will lead to improved irradiation stability.

Aqueous Corrosion

Aluminum base alloys containing 0.5 - 2.0 w/o nickel corroded faster in dynamic loops (15 - 20 fps) than in static tests. For example, the corrosion rate of an aluminum-1 w/o nickel alloy in distilled water at 315°C in dynamic tests was of the order of 10-mil penetration per year as contrasted with 3 mils per year in stagnant tests. The corrosion rate of these alloys at 290°C was not affected by lowering the pH to 4.6. No unusual corrosion effects were noted when the alloys were coupled galvanically to stainless steel, or in assemblies containing crevices. Heliarc and spot welding had no deleterious effects on the corrosion resistance.

Experiments tentatively indicate that for good corrosion resistance at 350°C, Al-Ni-Fe alloys require at least 0.8 w/o total nickel and iron, with a probable minimum nickel content of about 0.4 to 0.5 w/o. In the presence of silicon, the amount of total nickel and iron is greater.

Aluminum binary alloys containing 2 w/o of lead, tin, bismuth, cadmium, cobalt, iron, copper, or platinum were air-cast and corrosion tested at 315°C. Only the last four gave fair results; the others disintegrated. Cobalt and copper alloys were superior to platinum or iron alloys but all were inferior to a vacuum-cast 1 w/o nickel alloy.

13

The corrosion rate of 2S aluminum in 275°C water containing 5 ppm nickel as NiSO_4 additive (pH 3.5) was only 0.41 mil per year. After a 70-day test the samples were in excellent condition, with no discernible deposits on either the samples or the autoclaves.

Electrical conductivities of anodic films on zirconium were found to be reproducible provided the metal is homogeneous. The temperature of conduction increased with film thickness from about 350°C for the thinnest films to about 550°C for the thickest. The thicknesses of anodic films on Grades I and III zirconium and on Zircaloy-I increased linearly with anodizing voltage up to 500 volts. In the case of Zircaloy-II, however, linear growth was observed only up to 300 volts, indicating significantly different anodizing parameters.

Hydrogen analyses of corroded samples of an U-5 w/o Zr-1.5 w/o Nb alloy indicated a constant rate of hydrogen buildup in the metal even though the corrosion rate may vary. The hydrogen content increased with corrosion test time. Bond layers formed on cladding this alloy with Zircaloy-II were found to be less corrosion resistant than the alloy itself. Aging for improving the corrosion resistance of the core alloy was detrimental to the corrosion resistance of the bonds.

Several series of supposedly identical samples of an epsilonized uranium-silicon alloy yielded erratic corrosion results in 290°C water tests. No correlation was noted between the corrosion behavior and carbon content, silicon content, or the epsilonizing heat treatments. Weight changes varied from +3.1 to -5.5 mcd after 69 hours in 290°C water.

An epsilonized 3.89 w/o Si alloy sample irradiated in the MTR to a 0.71% burnup showed a corrosion rate of only 0.1 mcd in 260°C water in a one-day test. The same sample had a corrosion rate of 15.7 mcd at 290°C prior to irradiation.

A pin sample of a U-5 w/o Zr-1.5 w/o Nb alloy clad with Zircaloy-II and open at both ends, which had been irradiated in CP-5 to 0.1 a/o burnup, showed no apparent changes on a 24-hour test in boiling distilled water.

Effects of Irradiation on Materials

Hot-pressed uranium powder compacts of full and partial density, the latter with approximately 12.5% porosity, were irradiated in Kittel capsules in the MTR to burnups of 0.28 a/o. The specimens were cylindrical and some contained a 1/16" diameter axial core hole. The full density specimens shortened at an increasing rate with burnup. The partial density specimens, on the other hand, increased in length at a uniform rate.

264 011

DECLASSIFIED

14

A group of Zircaloy-II-clad, roll-bonded U-5 w/o Zr-1.5 w/o Nb plate specimens were irradiated in NaK-filled capsules in the MTR to 0.094 a/o burnup. Unrestrained specimens of this alloy with similar heat treatments were found to elongate at a rate of about 290 micro-inches/inch/ppm burnup; the clad specimens elongated at considerably lower rates. The cladding evidently restrained the growth tendency to a large degree.

Several cast specimens of a U-3.8 w/o Si alloy, 10% enriched, showed remarkable dimensional stability to burnups up to 0.94% of the uranium atoms, except for one specimen whose computed central metal temperature reached 1150°C; the latter showed a radical increase in diameter. Based on prior observations of other specimens, the large increase in diameter at high temperatures is probably an internal void resulting from fission gas accumulation.

Cast specimens of an U-3.0 w/o Nb-0.48 w/o Sn alloy, 10% enriched, showed only moderate stability on irradiations up to 0.58% of the uranium atoms.

264-12

037029.030

I. ADVANCED WATER REACTOR PROGRAM ▲

1. Fabrication of Zircaloy-Clad Uranium Alloy Fuel Plates (C. H. Bean, J. R. Lindgren, R. E. Macherey)

The reference uranium core alloy for the EBWR, containing 5 w/o zirconium and 1.5 w/o niobium, has been integrally clad with Zircaloy-II. Satisfactory methods for the preparation of cladding components, assembly of cladding billets, and for roll-bonding flat plate-type fuel elements have been reported in the previous Quarterly Report (ANL-5439). Additional development work during the past quarter has resulted in further improvements in plate quality and in a better understanding of the variables which control the roll bonding of plates scaled to the size of EBWR fuel elements. A sufficient number of EBWR-size clad plates have been prepared to make several full-size subassemblies.

A total of 45 cladding billets, 26 of which were scaled to full-size EBWR fuel plates, were fabricated to study the effects of Zircaloy-II prerolling deformational anisotropy upon roll bonds, the limitations of the cladding billet assembly procedure, optimum rolling practices, and to provide clad plates for corrosion testing and for experimental reactor subassemblies. Seven of these billets were prepared with U-5 w/o Zr alloy cores to determine whether improvements could be made in cladding this alloy in the event of its possible use as a substitute for the ternary alloy.

a. Effect of Orientation of Zircaloy-II on Roll-Bonded Plate End Closures

A study has been made of the deformational anisotropy of Zircaloy-II as hot-rolled and as forged and of the effects of directional properties upon roll bonding. Particularly important was the side bonding between the Zircaloy side strip and the end plug, because this was the most difficult bond to produce in the roll cladding of fuel plates. The studies below indicate that a sound Zircaloy side strip to end plug bond can be produced by properly orienting the end plug relative to its prior hot-working directions.

Eighteen 1.100" cubes were machined for anisotropy tests from Zircaloy-II plate hot-rolled from forged ingot 5Y345. The Zircaloy was forged from an 11-1/2" diameter ingot to a 3" x 8" slab at 950°C and then hot rolled 50% reduction in thickness at 850°C. The three cube axes were marked on the faces of the cubes as follows: X was designated as the rolling direction, Z the axis at right angles to the rolling direction in the rolling plane, and Y the axis perpendicular to the rolling plane. Hardness

3

tests at room temperature revealed that indentations made perpendicular to the rolling plane (Y axis) were approximately 40 Vickers hardness points above the hardnesses observed when indentations were made in either of the other two directions.

Three of the cubes were hot rolled at 850°C to 80% reduction in thickness with different orientations as follows: the first cube was rolled with the X axis in the direction of rolling and the Z axis perpendicular to the rolling plane; the second cube was rolled with the Y axis in the rolling direction and the X axis perpendicular to the rolling plane; the third was rolled with the Z axis in the rolling direction and the Y axis perpendicular to the rolling plane. The second and third cubes spread approximately 40% more in width than the first, as shown in Figure 1. These results show that Zircaloy-II "remembers" its previous hot-working history to a considerable degree, as has been previously reported.¹

Twelve cubes were hot pressed between stainless steel platens at 850°C to half their original thicknesses in the following directions: four were compressed along the X axis, four along the Y axis, and four along the Z axis. In every case the spreads in the X and Z directions were approximately 70% greater than in the Y direction, bearing out the fact that directionality is as significant in hot pressing as it is in hot rolling. The extent of spread in each direction is illustrated in Figure 2. Three cubes were beta annealed in a vacuum furnace at 1000°C for one hour and were hot pressed as above. The spread was approximately the same in each of the cube directions indicating that nearly all of the anisotropy was removed by this heat treatment.

Six additional cubes were prepared from the forged slab to study the deformational characteristics in relation to the forging direction. The X axis was designated as the forging direction, Z the axis at right angles to the forging direction in the forging plane, and Y the axis perpendicular to the forging plane. Three of the cubes were hot pressed at 850°C to 80% reduction in thickness, each with a different forging axis in the pressing direction. The results on the forged material corresponded to those for cubes prepared from the hot rolled slab: the resistance to deformation along the Y axis was significantly greater than along the X and Z axes.

It was reasonable, therefore, to assume that the indicated anisotropy in hot-rolled Zircaloy-II could be advantageous in enhancing bonding between the end plug and side strip in the roll cladding of fuel plates, if the orientation of the end plugs were properly selected with reference to the prior hot rolling or forging directions. In order to

¹F. Forscher, "Effect of Cold Work on the Mechanical Properties of Zircaloy-II," WAPD-111 (December 18, 1954)

Figure 1. Zircaloy-II Cubes Machined from Hot-Rolled Slab and Rolled 80% Reduction in Thickness at 850°C.

Each cube was rolled with the prior hot-rolling axes in different directions. The prior hot-rolling direction was designated as the X axis, the direction perpendicular to the rolling plane as the Y axis, and the direction at right angles to the rolling direction in the rolling plane as the Z axis.

Cube rolled with the X axis in the rolling direction and the Z axis perpendicular to the rolling plane. Very little spread has occurred along the Y axis.

Cube rolled with the Y axis in the direction of rolling and the X axis perpendicular to the rolling plane. Width spread along the Z axis approximately 40% greater than along the Y axis in Figure 1-a.

Cube rolled with the Z axis in the rolling direction and the Y axis perpendicular to the rolling plane. Width spread along the X axis approximately 40% greater than along the Y axis in Figure 1-a.

Figure 2. Zircaloy-II Cubes Machined from Hot-Rolled Slab and Hot Pressed at 850°C to Half Their Original Thicknesses.

Each cube was pressed along different hot-rolling axes. The hot-rolling direction was designated as the X axis, the direction perpendicular to the rolling plane as the Y axis, and the direction at right angles to the rolling direction in the rolling plane as the Z axis.

2-a.

Macro 17614

1-X

Cube pressed along the X axis. Spread along the Z axis approximately 70% greater than along the Y axis.

2-b.

Macro 17615

1-X

Cube pressed along the Y axis. Spread along the X and Z axes approximately equal.

2-c.

Macro 17616

1-X

Cube pressed along the Z axis. Spread along the X axis approximately 70% greater than along the Y axis.

19

facilitate side bonding in rolling, the orientation of the end plug which will result in the maximum side spread should be selected. This orientation of the end plug must be such that the rolling direction of the cladding billet, which is the direction along which the length of the end plug is measured, will be along the Y axis. The choice of X or Z axes for the thickness or width of the end plug is not important since the spread in these directions is approximately the same. Figure 3 illustrates the desired orientation of the end plug.

Three cladding billets, No. 168, 169, and 170, were prepared with end plugs having different orientations as follows: in billet 168, the end plugs were oriented with the Y axis of the hot-rolled slab in the billet rolling direction, as in Figure 3; for billets 169 and 170, the end plug orientations in the billet rolling direction were from the X and Z axes, respectively. Figure 4 shows three photomicrographs of the bonds between the Zircaloy-II end plug and Zircaloy-II side strip from each of the above billets rolled 80% reduction in thickness at 850°C. With the proper orientation of the end plugs, as in billet 168, no defects or inclusions were present in the bond. For the billets with end plugs machined with their axes other than shown in Figure 3, numerous segmented or continuous defects could be noted in the bond.

End plugs in two additional cladding billets, No. 171 and 172, were beta annealed one hour at 1000°C. There was little or no improvement in the end plug to side strip bonds of these plates compared with plates 169 and 170. Except for the end plug variations, all five plates were fabricated in the same manner. It is evident, therefore, from these results that the orientation of the end plug with respect to the prior hot working directions of the material is critical in achieving sound metallurgical bonds in the fabrication of roll clad fuel plates.

b. Cladding Billets with Introduced Assembly and Rolling Variables

Two groups of billets, a total of 14, were prepared to assay the effects of weld penetration, contamination during billet assembly, and variations in rolling schedules. The billets were approximately 1-3/8" x 2-5/8" x 6-3/4", including 1/8" thick cover plates and 1/4" thick side strips. The ternary alloy cores were cast and machined to size with a 90° included angle tapered ends. The cladding components were all cleaned. The billets were assembled with a 0.020" per inch expansion allowance for the core and purged during welding according to previously established practice.

Billets 147 to 152 inclusive, and 160 and 161, were welded with maximum weld penetration at 240 amp, using a 1/8" diameter tungsten electrode. Four of these billets, 147, 148, 160, and 161, had no intentional defects; billets 149 and 150 had a light, white fluoride deposit on the side strips at the strip to cover plate interface; billets 151 and 152 had a 1/2" long unwelded gap between the cover plate and end plug at one end. Welded

DECLASSIFIED

264 017

264 018

20

Figure 3. Desired Orientations of Cladding Billet End Plugs to Obtain Maximum Side Spread in Producing a Side Strip to End Plug Roll Bond.

21

Figure 4. Zircaloy-II End Plug to Zircaloy-II Side Strip Bonds from Billets Prepared with End Plugs Having Different Orientations of the Prior Hot-Rolled Slab in the Rolling Direction of the Cladding Billet.

4-a. Bond from Plate 168.

Micro 17811

150-X

The axis perpendicular to the prior hot-rolling plane was oriented parallel to the rolling direction of the cladding billet. No evidence of inclusions in the bond.

4-b. Bond from Plate 169.

Micro 17812

150-X

Bond Line

The axis parallel to the prior hot-rolling direction was oriented parallel to the rolling direction of the cladding billet. A large number of inclusions or discontinuities may be noted along the bond line.

4-c. Bond from Plate 170.

Micro 17813

150-X

Bond Line

The axis at right angles to the rolling direction in the rolling plane was oriented parallel to the rolling direction of the cladding billet. A large number of inclusions or discontinuities may be noted along the bond line.

264 019

DECLASSIFIED

billets were assembled in regular steel jackets for roll cladding. Billets 160 and 161 were welded in jackets which were not completely sealed, having 1/2" long gaps in the weld along one side. All billets were roll bonded 80% reduction in thickness at 850°C and were reheated after every pass, with the exception of billets 149 and 150 which were reheated after every two passes.

Rolled plates from billets 160 and 161 are being corrosion tested in 290°C water to determine the possible extent of surface contamination while heating and rolling in a defectively welded steel jacket. Plates from all other rolled billets were sectioned for metallographic examination of roll bonds. The alloy cores in these plates were found to be integrally bonded to the cladding with no apparent defects. All cover plate to side plate bonds were sound, free from inclusions, and with no defects in plates 149 and 150 as a result of the fluoride contamination. Semicontinuous inclusions were noted in the cover plate to end plug bonds at the ends of plates 151 and 152, which had not been sealed by welding; inclusions were quite obvious in the end plug to side strip bonds in these two plates. The Zircaloy-II bonds on billets which were not completely welded were generally inferior to the bonds in properly welded billets. The quality of plates rolled two passes per reheat was equal to plates reheated after every pass, indicating that heat loss between passes during rolling was not detrimental to bonding. All bonds in plates 147 and 148 were satisfactory.

Billets 162 and 167 inclusive were welded with a minimum weld penetration at 120 amp, using a 1/16" diameter tungsten electrode. To check possible weld failures on subsequent heating and rolling, billets 162 and 163 were rolled 80% reduction in thickness at 850°C, billets 164 and 165 were heated 1-1/2 hours at 850°C and examined without rolling, and billets 166 and 167 were rolled only 13.5% reduction in thickness at 850°C. There was no evidence of weld failure in any of these billets as a result of heating or rolling. Clad-to-core and clad-to-clad bonds on plates from billets 162 and 163 were all satisfactory. Partial bonding was noted on billets 166 and 167. The core and cladding components of billets 164 and 165 were all clean, bright, and free from contamination after heating to the roll bonding temperatures (see Figure 5). Varying the weld penetration on cladding billet assemblies did not appear to have any effect on bond quality; the integrity of the weld, however, did have a significant effect on it.

c. Fabrication and Evaluation of Uranium-5 w/o Zirconium Alloy Clad Plates

In an effort to improve the uniformity and quality of Zircaloy-II clad U-5 w/o Zr alloy plates, a total of seven additional billets were prepared, using 0.125" thick cover plates and a 90° instead of 100° included angle tapered core ends (Nos. 153 - 159, inclusive). Billets were scaled

Figure 5. Cladding Components of Billet 165 After Heating 1-1/2 Hours at 850°C.

Macro 17567

1/2-X

264 021

DECLASSIFIED

for full-size EBWR type plates. Cladding components were prepared and billets assembled using procedures developed for cladding the EBWR ternary U-Zr-Nb reference alloy. The billets, except 157, were roll clad 80% reduction in thickness at 850°C; billet 157 was rolled to only 31% reduction in thickness at the same temperature.

Evaluation of the previously rolled plates 135 - 139 and the present plates 153 - 159 inclusive has been completed. The evaluation was based on physical and mechanical testing, metallographic examination, and limited corrosion testing. Uniformity of plate size, surface finish, cladding, and end effects were greatly affected by cladding temperature variations. The surfaces of plates rolled at 850°C with 0.020" nominal cladding were quite rough, with regular depressions of 0.010" to 0.020" at 1/4" intervals throughout the plate surface. Increasing the cladding thickness to 0.025" improved the surfaces of plates rolled at 850°C, although some slight depressions were still evident. Surface irregularities were due to differences in the hot-working properties of the core and cladding. Roll-cladding temperatures of 800° and 900°C intensified the surface irregularities: at 800°C the core did not deform as readily as the clad, and the reverse was true at 900°C. End effects were bad at the core-to-clad transition at ends of plates rolled below 900°C. This end effect was improved by increasing the length of preshaped end tapers in the cores of billets 153 - 159 inclusive.

Representative tensile strength tests revealed clad-to-core bond strengths between 56,000 and 60,000 psi on all plates hot-rolled 80% reduction in thickness at rolling temperatures between 800° and 900°C. Mechanical bend tests on hot-rolled clad plate specimens at room temperature indicated appreciable ductility of the core alloy as well as at the clad-to-core interface.

Complete bonding was obtained at all clad-to-core interfaces and between the various cladding components on all plates except 157. Diffusion bands observed on metallographic examination of clad-to-core interfaces were uniform throughout each plate but varied with rolling temperature. The widths of the diffusion bands varied from 2.4×10^{-4} inch for plates rolled at 800°C to 9.0×10^{-4} inch for plates rolled at 900°C.

Test strips cut from the solid Zircaloy-II rolled end closures at plate ends were corrosion tested in 400°C steam for 359 hours. Specimens were uniformly coated with a black, adherent oxide scale with no evidence of white corrosion product on either the Zircaloy-II surfaces or at any of the cladding interfaces. Three rolled plates, 153, 154, and 158, were machined to 3-3/4" wide x 53" long to be corrosion tested in 290°C water.

25

d. Evaluation of Clad Uranium-5 w/o Zirconium-1.5 w/o Niobium Alloy Plates Scaled to EBWR Size Fuel Elements

Nineteen plates were roll clad from billets 140 - 146 and 175 - 186, inclusive. Although most of these plates were prepared for experimental EBWR fuel subassemblies, sufficient data were obtained from physical and mechanical testing, metallographic examination, non-destructive testing, and corrosion tests to further evaluate the cladding process. Measurements of hot-rolled plate length, width, thickness, and roll camber will be used to establish practical tolerances for clad plates rolled on a semiproduction basis. Although roll camber can be held to less than $1/16$ " on all plates, close control of cladding billet dimensions should make it possible to reduce the roll camber to less than $1/32$ ". All plates were radiographed before and after final machining to locate the alloy core relative to plate ends and sides. Uniform core distribution was noted on all plates. Close control of total reductions and final mill settings on the above rolled plates improved the core length uniformity over previously rolled plates. Of these plates, 60% had cores $50" \pm 1/4$ " long, as compared with 20% for previously rolled plates, and 90% had cores $50" \pm 1/2$ " long compared with 80% in the past.

Metallographic examination of two sectioned plates showed no discontinuities in clad-to-core bonds. All clad-to-clad bonds were satisfactory except for segmented inclusions in the side plate to end plug bonds at the end closures. Sections cut from the solid Zircaloy-II ends showed similar inclusions in this bond on all but seven of the 19 plates.

Ultrasonic through-transmission tests on finished plates indicated complete bonding at all clad-to-core interfaces and at clad-to-clad interfaces of all plates except No. 180, which had a $1/4" \times 1"$ unbonded area between the cover plate and side strip at one end of the plate. Lack of bond in this location was due to contamination of the mating surfaces.

Continued static corrosion tests on previously rolled plates 114, 116, 123, and 127 have shown no evidence of failure after 1,018 hours in water at 290°C . Plates 129, 133 and 134 were also in good condition with a uniform, black oxide scale after 694 hours in water at 290°C . Clad plate 134 was corrosion tested for an additional 59 hours with a $1/16$ " diameter hole drilled through the cladding into the core near one end of the plate. Localized corrosion occurred over an area approximately $7/16$ " in diameter, with the formation of loose, black oxide and rupture of the clad in the shape of a $1/2$ " diameter disc over the corroded area. Except for a small bump on the surface opposite the corroded area, no blistering or separation at the clad-to-core bond was noted. The alloy core material in these plates was not heat treated for water corrosion resistance. Sections cut from the solid Zircaloy-II ends of plates 140 - 146 were uniformly coated with a black, adherent oxide film after testing for 359 hours in 400°C steam.

264 023

DECLASSIFIED

2. Fabrication of Zircaloy-Clad EBWR Subassembly (C. C. Stone,
F. D. McCuaig, R. A. Noland)

Several small sections and one full-size Zircaloy-II clad EBWR fuel subassembly have been fabricated by heliarc spot welding. No additional shielding was used other than that supplied by the welding grade argon supplied to the spot welding pistol. Welds produced were considered to be of sufficient strength to withstand service conditions. Corrosion tests of dummy welded sections indicated that additional shielding of the work during welding is necessary.

II. FAST POWER BREEDER REACTOR PROGRAM

1. Plutonium-Aluminum Fuel Slugs for EBR-I (L. R. Kelman)

Rocky Flats expects to have the fuel slugs for the EBR-I completed late in the month of July. Some equipment and materials have been sent to Rocky Flats to help them fabricate, test, and ship the fuel elements. Procedures and specifications have been mutually agreed upon. ANL personnel helped set up the "motor arc" welding equipment at Rocky Flats.

2. Resistance of Uranium-Plutonium Alloys to Attack by Sodium (L. R. Kelman, E. W. Hoyt)

Uranium-plutonium alloy castings containing 10, 15, and 20 w/o Pu were exposed to clean sodium at 450°C for 165 hours in a stainless steel container. There was little, if any, discernible change that could be attributed to attack by sodium; there was localized spalling of the 10 and 15 w/o Pu specimens, but most of the material that flaked off was recovered as discrete particles. The spalling can be attributed to the tendency for the development of internal microcracks which is characteristic of these alloys.

29

of Mines and a reactor grade sponge from Carborundum were used. In two melts the Grade C sponge gave rise to considerable frothing and the melts started to overflow the crucible; it was necessary to close the vacuum valve and bleed in argon to suppress it. After the zirconium had been dissolved the valve was opened and the furnace operated with mechanical pumps only. The frothing appears at only a certain stage during solution and eventually dies away; it was partially overcome by more rapid heating through the solution range up to 1500°C.

The sponge from Carborundum gave almost no melt action; there was bubbling in only a few small localized spots. A heavy skull was left in the crucible in both melts which employed only this type of sponge. Analysis is not yet available to ascertain whether ingots were homogeneous or segregated. Two melts of 110 kg each were made using a mixture of 25% Bureau of Mines Grade C sponge and 75% Carborundum reactor grade sponge. This mixture gave considerable agitation to the melt, but the melt never frothed up in the crucible nor boiled violently. The analysis is not yet available on these heats, but since very little skull was left in the crucible it is expected that the alloys will be satisfactory.

The Bureau of Mines Grade C sponge contains up to a few thousand ppm of magnesium, which is at least several times the content of the Carborundum sponge. Moderate evolution of the magnesium during melting is an aid in the solution of the alloying additions.

a. Graphite Crucibles and Washes

No ceramic crucibles were used in the foundry during this quarter; only graphite crucibles with protective washes were employed. The most satisfactory graphite crucible coating for preventing pickup of carbon in melting uranium-zirconium-niobium alloys was found to be the following: one thin coat of brushed-on magnesium zirconate, air-dried for several hours; then one thin coat of brushed-on magnesium zirconate allowed to air-dry overnight or longer; then one heavy coat of thoria applied by spraying. The crucible should air-dry for several hours before charging in the furnace; it can be allowed to air-dry for as long as a week without adverse effects. The same procedure was also used for protecting graphite stopper rods. The above-mentioned wash has been used in 50 melts during the last four months and has been adopted as a standard protective wash for graphite crucibles when melting U-5 w/o Zr-1.5 w/o Nb alloys. The wash is good for just one melt, but it affords a complete ceramic lining for the graphite crucible for temperatures as high as 1600°C. When the wash has been applied properly, there is no attack on the graphite even during frothing or violent boiling of the melt, when the zirconium sponge is going into solution. After melting, the skull cleans out very easily by just inverting the crucible. The wash near the top of the crucible that has not been touched by molten metal can be easily removed by hand wire brushing.

264 027

DECLASSIFIED

30

In melting uranium alloys containing 7.5 w/o and 10 w/o zirconium, there was a slight attack on the crucible wall in three out of four virgin melts which caused a pickup of carbon of from 50 to 200 ppm. It is felt that this wash can be applied in thicker coats that will also withstand the attack of the higher zirconium alloys.

The magnesium zirconate is of low boron content and is supplied by Titanium Alloy Manufacturing Division of National Lead. The thoria for spraying has been prepared at Argonne by the Ceramics Group and consists mainly of broken thoria crucibles ball milled to -200 mesh. The thoria appears to sinter to the magnesium zirconate during the heating up period and prior to the melting of the metal.

The combination wash of magnesium zirconate and thoria was used satisfactorily on the following sizes of graphite crucibles:

<u>I.D.</u> <u>(inches)</u>	<u>O.D.</u> <u>(inches)</u>	<u>Height</u> <u>(inches)</u>
3-1/4	4	6
7	8	10
9-1/2	12	12
10-1/2	13-1/2	16

b. Graphite Molds, Mold Washes, and Mold Insulation

Only heated graphite molds were used during this quarter. They were all of a split design and were held together by caps at the top and bottom. The graphite crucible rested on top of the mold and heated the mold by conduction. The top cap was as large in diameter as the crucible, so that considerable heat would be induced in it when the mold extended several inches up into the coil. This heat at the top of the mold helped maintain a good temperature gradient in the mold and served to bake out thoroughly the mold wash.

Magnesium zirconate was adopted as the standard mold wash during this quarter. Only one thin coat is brushed on, and it adheres satisfactorily for one heat. The big advantage of the magnesium zirconate wash over the slaked lime wash that was used previously is that a mold coated with magnesium zirconate may be allowed to stand for several days before using without detrimental effects; the lime-washed mold had to be used within a few hours after coating. Also, the magnesium zirconate wash stands up better than lime wash under impact of molten metal, especially when the metal drop is more than 12" or 15".

Design work on molds was concentrated on making core stock for the EBWR that would require only a small amount of machining prior to cladding with Zircaloy and rolling into finished fuel elements. The

31

molds for single cores have cavities $1\text{-}1/8" \times 3\text{-}5/16" \times 15"$ deep. The single core castings were cast endwise and required the milling of tapers on each end after they were cut to length.

To make castings from which a number of EBWR cores could be obtained, molds were designed in which the length of the EBWR core lay transverse, so that the end tapers could be cast to shape. The cavities in these molds were each $1\text{-}1/8" \times 10\text{-}3/4"$ in cross section $\times 32"$ deep. Some of the cast slabs were of sufficient length to yield seven EBWR cores by hacksawing them transversely. The cores from these slab castings needed the removal by machining of only $0.030" - 0.050"$ per face to give a finished core ready for cladding.

In casting the U-5 w/o Zr-1.5 w/o Nb alloy in hot graphite molds it has been found necessary to insulate the mold to conserve heat, while maintaining a good temperature gradient throughout the mold. It was difficult to obtain sound castings when making the long thin slab without insulating each of the two large flat sides of the mold with zirconia brick.

c. Ingot Quality

The internal and surface quality was excellent in nearly all of the 39 single core castings made, which included the virgin melts and re-melts of alloys containing 5 w/o Zr + 1.5 w/o Nb, 5 w/o Zr, 7.5 w/o Zr, and 10 w/o Zr. In a few of these castings some small subsurface blowholes were encountered near the bottom of the ingots. This defect was eliminated by insulating the molds with 8" diameter zirconia tubes. It was also found necessary to keep the molds about 2" up into the coil so that heat could be induced in the top retainer ring.

Considerable experimentation was required to obtain satisfactory surface and internal quality throughout the multiple EBWR core castings that weighed 80 - 110 kg. The first few ingots were cast with no mold insulation and were poured through $3/8"$ or $1/2"$ diameter pouring holes. These ingots developed several concave shrink spots, 1" to $1\text{-}1/2"$ in diameter, at random locations on the sides of the top half of the ingot. These side shrink spots were $0.020"$ to $0.050"$ deep and did not clean up in the grinding operation, since only $0.030"$ per face was allowed for clean-up in the mold design.

It was reasoned that these side shrink spots must be due to an insufficient temperature gradient within the mold from bottom to top. The ingot must have solidified through the entire cross section near the top and left pockets of molten metal below, which later showed the side shrink defect. Also, these ingots showed little blowholes in the pointed ends in the bottom third of the ingot.

264 029

DECLASSIFIED

The above defects were overcome by increasing the pouring hole to 5/8" in diameter and placing 2-1/2" thick bricks on the wide faces of the mold. The resultant ingots have satisfactory external quality throughout the entire length as far as can be determined by visual examination. At the present time, it is felt that long thin slab castings of satisfactory quality which will yield at least seven EBWR cores can be produced. Nearly all of these melts have been virgin melts, and it is expected that the sum of the carbon and nitrogen contents will be under 200 ppm. Experience with the 15 - 20 kg melts in making the single core castings showed that in virgin melts of the U-5 w/o Zr-1.5 w/o Nb alloy, the sum of the nitrogen and carbon contents was between 80 and 200 ppm, and that remelting brought the figure down to 30 to 50 ppm.

2. Welding Borax Fuel Subassemblies (D. E. Walker, G. B. O'Keeffe, R. A. Noland)

Development work on a spot-welded fuel subassembly for use in the Borax-III experimental power reactor has been completed during the quarter. Results obtained from simple physical tests on sample subassemblies led to the selection of a design for use in the reactor.

ANL Central Shops has made a full reactor loading in accordance with this design.

3. Thoria-Urania Ceramic Fuel Bodies (J. H. Handwerk, R. A. Bach)

Additional ceramic cylinders, composed of 90 w/o ThO₂ and 10 w/o highly enriched U₃O₈ and measuring approximately 1/4" in diameter by 1/2" in length, were fabricated. The pellets were fired at 1830°C. The average density was found to be 10.06 g/cc, and the average apparent porosity was 1.3%.

Thirteen aluminum-1 w/o nickel alloy tubes with four ceramic pellets in each were submitted for irradiation tests in CP-5. These tubes were filled with purified, degassed lead as bonding material.

Eight aluminum-1 w/o nickel alloy tubes with two ceramic pellets in each tube were submitted to J. H. Kittel for irradiation tests in the MTR. Four of these tubes were filled with lead as bonding material; the remaining four contained no bonding material.

4. Properties of Urania-Thoria Bodies (J. H. Handwerk, R. A. Bach)

A series of bodies containing from 10 w/o U₃O₈ to 90 w/o U₃O₈ in increments of 10% in ThO₂ were compounded. These mixtures were isostatically pressed using a pressure of 50,000 psi, and the specimens were fired at 1830°C in air. The bodies containing less than 60 w/o U₃O₈ appeared to be good, while the mixtures containing more than 60 w/o U₃O₈ were cracked.

33

The densities appeared to decrease as the U_3O_8 content increased, varying from 10.0 g/cc for the body containing 10 w/o U_3O_8 to 8.8 g/cc for the body containing 90 w/o U_3O_8 . The apparent porosities of the bodies appeared to decrease with a decrease in the U_3O_8 content, ranging from 5.6% for the body containing 90 w/o U_3O_8 to 1.3% for the body containing 10 w/o U_3O_8 .

5. Rare Earth Ceramic Bodies (J. H. Handwerk, R. A. Bach)

Work was started to produce a dense Sm_2O_3 - Gd_2O_3 powder mixture suitable for filling control rods. The as-received mixture of Sm_2O_3 - Gd_2O_3 contained approximately 26 w/o Gd_2O_3 and was found to have a bulk density of 1.07 g/cc. Sintering tests on the loose powder at temperatures up to 1200°C failed to increase the density appreciably. The powder was isostatically pressed into pellets with a pressure of 50,000 psi. The pressed specimens were then fired at 1200°C and crushed to pass a 100-mesh screen. The bulk density of this powder was found to be 2.21 g/cc. In attempts to further raise the density, the Sm_2O_3 - Gd_2O_3 was mixed with 0.5 w/o B_2O_3 , and the mixture was isostatically pressed using 50,000 psi pressure. The pressed specimens were fired at 1200°C and then crushed to pass a 50 mesh screen. The bulk density of this material was found to be 4.40 g/cc.

6. Vanadium-Base Alloys (K. F. Smith, L. T. Lloyd)

A program to study vanadium alloys has been initiated for determining the feasibility of their application as fuel element cladding material in the temperature range 650° to 800°C. Previous work on zirconium and titanium base alloys and tantalum as possible materials for this temperature range are reported in ANL-5339 and ANL-5439.

Vanadium is a promising material from the standpoint of thermal conductivity. It is suspected, however, that, unlike tantalum, high temperature strength is lacking in the unalloyed state. It would be useful to know if the high temperature strength of vanadium could be developed by some alloying addition without unduly affecting the thermal conductivity.

Preliminary screening of some selected vanadium alloys prepared by Armour Research Foundation shows the values of thermal conductivity, as reported by the ANL Chemistry Division, given in Table I; 800°C sodium corrosion results, as reported by the ANL Reactor Engineering Division, are given in Table II. From these tests it would appear that alloys up to 20% titanium or 3% silicon may be competitive with pure zirconium.

It is now planned to examine the strength of these, and perhaps some additional compositions, in the range 650° to 800°C.

264 031

DECLASSIFIED

34
TABLE I

Thermal Conductivity of Vanadium and Some of Its Alloys Near 70°C

Sample No.	Composition (w/o)	Thermal Conductivity (K) in $\text{cal} \cdot \text{sec}^{-1} \text{cm}^{-1} \text{°C}^{-1}$					
		K	°C	K	°C	K	°C
1	Unalloyed V	0.086 ₄	93.7	0.083 ₉	63.4	0.084 ₄	70.0
2	V-5% Ti	0.072 ₁	89.0	0.068 ₉	61.2	0.069 ₉	
3	V-10% Ti	0.061 ₀	89.7	0.057 ₀	61.6	0.058 ₂	
4	V-20% Ti	0.051 ₃	94.4	0.046 ₁	64.4	0.047 ₁	
5	V-10% Ti-5% Al	0.032 ₉	92.9	0.030 ₇	63.3	0.031 ₂	
6	V-40% Ti-5% Al	0.026 ₀	97.5	0.023 ₈	66.0	0.024 ₀	
7	V-1% Si	0.065 ₆	96.8	0.063 ₅	65.6	0.063 ₈	
8*	V-3% Si-2.5% Zr	0.052 ₃	94.7	0.049 ₄	63.8	0.050 ₀	

*Flaw in side of specimen.

TABLE II

Sodium Corrosion of Vanadium and Some of Its Alloys
Near 800°C for 760 Hours

Composition (w/o)	Weight Change (mg)	Corrosion Rate (mg/cm ² /mo)	Other Observations
Unalloyed V	- 3.0	- 1.3	Dull gray tarnish
Unalloyed V	+ 0.7	+ 0.34	Dull gray tarnish
V-5% Ti	- 2.1	- 0.92	Dull gray tarnish
V-5% Ti	- 1.7	- 0.72	Dull gray tarnish
V-10% Ti	- 0.7	- 0.31	Dull gray tarnish
V-10% Ti	- 0.8	- 0.35	Dull gray tarnish
V-20% Ti	+ 0.5	+ 0.23	Dull gray tarnish
V-20% Ti	+ 0.5	+ 0.21	Dull gray tarnish
V-10% Ti-5% Al	- 5.6	- 2.4	Black film covering lustrous black tarnish (loose nonadherent film)
V-10% Ti-5% Al	- 3.6	- 1.5	Black film covering lustrous black tarnish (loose nonadherent film)
V-40% Ti-5% Al	- 0.4	- 0.17	Finely mottled brown and gray tarnish
V-40% Ti-5% Al	- 0.1	- 0.04	Finely mottled brown and gray tarnish
V-1% Si	+ 0.1	+ 0.04	Dull dark gray tarnish
V-1% Si	- 0.2	- 0.08	Dull dark gray tarnish
V-3% Si-2.5% Zr	- 5.1	- 2.2	Dull gray tarnish
V-3% Si-2.5% Zr	- 6.8	- 3.0	Dull gray tarnish
Nickel A	- 6.6	- 2.6	Satin silver tarnish
Nickel A	- 6.6	- 2.7	Satin silver tarnish
Nickel A	- 5.2	- 2.1	Satin silver tarnish
Nickel A	- 5.1	- 2.1	Satin silver tarnish
304 SS	None	None	Mottled silver and black tarnish
304 SS	- 0.5	- 0.21	Mottled silver and black tarnish
304 SS	+ 0.2	+ 0.09	Mottled silver and black tarnish
304 SS	- 0.4	- 0.16	Mottled silver and black tarnish

264 033

36

IV. PRODUCTION, TREATMENT AND PROPERTIES OF METALS

1. Preparation of Alpha-Uranium Single Crystals (E. S. Fisher, L. T. Lloyd)

Studies have continued on the effects of impurity segregation and various fabrication schedules upon adverse coarsening wherein coarsening starts near the outside of the cross section rather than at the center, as desired (see ANL-5439). The results have contributed much information with regard to the conditions which affect coarse grain growth in alpha uranium. The most recent studies indicate that adjustment of the fabrication schedule may supply a solution to the problem.

a. Effects of Carbon Segregation

The distribution of impurities in ingots cast in water-cooled copper molds has been studied by chemical analysis. Two ingots cast into a 2" diameter mold and one ingot cast into a 1-1/8" diameter mold were rolled to 0.9" diameter; samples for spectrochemical, carbon, and nitrogen analyses were machined concentrically from two different cross sections of each rod. No significant segregation of the detected impurities other than carbon was observed in the rods from the 2" diameter ingots; the carbon content of the centers of these rods was approximately twice that at the surface. On the other hand, the rod from the 1-1/8" diameter ingot showed a remarkably uniform distribution of all detected impurities.

Comparison of the grain coarsening results in specimens from the above three ingots and an additional 1-1/8" diameter ingot showed no significant differences. Rods which were rolled after siliconizing and gamma-phase heat treatment by a 5-step reduction schedule with small initial reductions all showed the tendency for coarsening to start at the outer regions of the cross section. It appears, therefore, that the anomalous coarsening behavior cannot be attributed to carbon segregation in the indicated concentration ranges.

b. Effects of Rolling Schedules

The concentration of second phase particles and the matrix grain size are probably the most important factors which determine the time before coarsening starts and the rate of growth of the coarse grains. From the analytical data described above and the results observed in the variations of rolling schedule, differences in matrix grain size appear to be the more important.

The effects of such factors as reduction per step, number of steps, passes per reduction, anneals between reductions, rolling versus

REF ID: A66666

204 034

37

swaging, starting and finishing diameter were studied in 13 different rolling schedules. In all cases the reductions were carried out at 300°C. In most cases the rods were rolled from a starting diameter of 0.83" to a finishing diameter of 0.400".

Metallographic studies indicate that the variations in incubation periods for coarsening produced by the different schedules are the result of differences in matrix grain size produced by recrystallization after the final reduction. As was expected from earlier studies (ANL-5160), the degree of banding or grouping of grain sizes in longitudinal bands was greater the fewer the number of reduction steps; for example, a rod reduced in two steps (57% reduction, annealed 1 hour at 600°C, followed by 45% reduction) contained a large number of narrow bands as observed after a 5-hour anneal at 650°C. Coarse grains were found to have grown along some of the bands, which were of the smallest grain size, as shown in Figure 6; with longer annealing times, the number and length of coarse grains increased, but even after 40 hours, bands of larger matrix grains remained which were not absorbed by the coarsening. In such heavily banded specimens, there was a large variation in grain size between the bands throughout the specimen cross sections, and initial coarsening was not confined to the peripheral areas. However, since there were more fine grain bands in the periphery, there were more coarse grains in these areas.

By increasing the number of steps between the same initial and final diameters, the degree of banding was decreased so that there were fewer abrupt changes in grain size across a section. Schedules which consisted of 10 to 15% reductions in the first two or three steps, followed by steps of increasing reductions up to 40%, generally resulted in larger matrix grain sizes with increasing distance from the rod surfaces. The start of coarsening was correspondingly confined to the peripheral regions as shown in Figure 7; the initial coarse grains grew to relatively large widths in contrast to those in the heavily banded structures. The larger center matrix grain size, however, not only caused an adverse distribution of the initial coarse grains, but also a gradual decrease in the rate of growth of the peripheral coarse grains. By increasing the time and temperature of anneals between reduction steps, the over-all matrix grain size, after the same final reductions, was greater, as were the incubation periods for coarsening; the distribution of initial coarsening was not changed.

The effect of increasing the initial reduction steps in a 5-step schedule is under study. The first results indicate that this type of schedule may be effective in producing a smaller matrix grain size in the center. A specimen of one rod which was rolled by a schedule using 24% and 30% reductions for the first two steps contained small coarse grains at the center after 5 and 7 hours at 650°C, and no indication of coarsening at the periphery.

264 035

DECLASSIFIED

38

Figure 6. Preferential Growth of Coarse Grains Within Bands of Smallest Primary Grain Size.

Micro 17580 Longitudinal Section 50-X

Figure 7. Preferential Growth of Coarse Grains at Periphery of Rod Specimens After 5-Step Rolling Schedule with Initially Small Steps.

Macro 17430 Longitudinal Section 7-X

39

At the present time there is no indication that the number of passes per reduction or the method of reduction (rolling or swaging) have significant effects on the resulting recrystallized grain size. Experiments in which rods of the same starting diameter were rolled to different finishing diameters indicate no effect of the finished size. A comparison of rods of the same finished diameter which were rolled from different starting diameters, however, indicates that the tendency to produce smaller surface grain size increases with the starting diameter. This would indicate that the initial deformation steps are critical in the reduction of larger diameters.

2. Recrystallization Textures of Deformed Alpha-Uranium Single Crystals (L. T. Lloyd, M. D. Odie)

The recrystallization texture has been determined for crystal J, which was deformed approximately 9% at room temperature by compression in a direction 73° from the $[100]$, 23.5° from the $[010]$, and 73° from the $[001]$. The observed operative deformation mechanisms in this crystal were twinning on $\{172\}$ and $\{130\}$ planes and slip on the (010) plane. Partial recrystallization and the formation of grains, which were of sufficient size to be irradiated by a fine X-ray beam for individual orientation determinations, was brought about by an anneal for one hour at 650°C . Individual Laue patterns were obtained from five recrystallized grains in the partially annealed state. One pattern was taken from the unrecrystallized, deformed material to determine the initial orientation of the crystal.

The data from the stereographic solutions of the Laue photograms were analyzed in a manner as reported in ANL-5382 and -5423. Figure 8 illustrates the groupings of the principal poles of the recrystallized grains with respect to the original orientation in (001) standard projection, together with the stereographic solution of the axis about which rotation occurred on recrystallization. The "centers of gravity" may be brought into coincidence with the principal poles of the original orientation by a rotation of 32.5° about an axis corresponding to a $\langle 212 \rangle$ direction. These values are in fair agreement with those reported previously for crystals A, E, P, and S (ANL-5382, -5423). From this analysis, one recrystallized grain may be said to have nucleated from the original orientation, two grains from $\{172\}$ twins, and two grains from $\{130\}$ twins.

A rather interesting feature with regard to the absorption of twinned material by the parent orientation and vice versa was observed metallographically in crystal J. In the deformed condition sharply defined and parallel-sided $\{172\}$ type twins were present on both metallographic faces. As a result of the annealing heat treatment, portions of these in the unrecrystallized areas were either absorbed by the parent orientation or grew to absorb the parent orientation. Figure 9 shows a twin which has undergone both of these phenomena. The tip of the twin near the upper left-hand corner has been absorbed by the parent orientation; the area in the lower left-hand

DECLASSIFIED

264 037

40

Figure 8. Grouping of Principal Poles for Recrystallized Grains in Crystal J with Respect to the Original Orientation.

The "centers of gravity" of each group are indicated as X. Principal poles of unreformed crystal may be rotated into the "center of gravity" position by a rotation of 32.5° about an axis approximately $\langle 212 \rangle$.

Macro 17757

Figure 9. $\{172\}$ Type Twin in Crystal J, Parts of Which Have Grown to Absorb Parent Material and Other Parts are Being Absorbed by Parent Material.

Micro 17748 Polarized Light 250-X

41

corner is a portion of a recrystallized grain. At the lower right-hand corner the same twin has thickened by growing into the parent and has finally merged with the adjacent twin. The shape of the interfaces between the growing material and the material which is being absorbed indicates that the direction of growth is toward its center of curvature; this is consistent with observations of grain growth in other metals. The fact that the same twin grows into other material as well as being absorbed may be due to inhomogeneities of strain throughout its length and in the surrounding material.

3. Identification of Inclusions in Uranium (M. H. Mueller, B. Blumenthal)

X-ray diffraction patterns were made of inclusions found in liquated uranium. The inclusions were removed from the polished surfaces of specimens by the sonic microchisel described by Kehl, Steinmetz, and McGonnagle.² Diffraction specimens of sufficient size were obtained by combining the material removed from the central portion of several inclusions and mounting on the tip of a 0.005" diameter quartz fiber coated with Vistanex. Diffraction patterns were obtained using approximately a 50-hour exposure with Cu K α radiation and a camera with a diameter of 114.6 mm.

Inclusions from three different ingots were studied. Ingots K5 and K6 were reactor grade slug rejects liquated in graphite crucibles in a vacuum resistance furnace; K5 was liquated for 2-1/2 hours at 1190°C and furnace cooled, and K6 was cycled in the temperature range 1050° - 1200°C, held for 3 hours at 1220°C, and then furnace cooled. Both ingots contained many inclusions in the interior and a heavy layer of inclusion particles at the top surface. Since both oxygen and nitrogen are readily removed from uranium by liquation, it was concluded at the time of the liquation experiments that the inclusions should be almost pure UC.³ The third ingot studied, melt B-92, was reactor grade uranium which had been nitrided by the addition of uranium nitride to the molten metal at 1440° to 1475°C. The resultant ingot had high nitrogen and carbon contents.

Micrographs of the regions from which the samples for X-ray diffraction analysis were taken are shown in Figures 10, 11, and 12. The X-ray results are summarized in Table III. The a_0 's were calculated from the first five lines in the forward reflecting region, since all the lines in the back-reflection region were either absent or were very diffuse. It is to be expected,

²G. Kehl, A. Steinmetz, and W. J. McGonnagle, "An Ultrasonic 'Jack Hammer' for Removal of Inclusions." To be published.

³B. Blumenthal, "Refining of Uranium by Melting and Liquation." ANL-5349.

264 039
DECLASSIFIED

42

Figure 10. Dendritic Inclusions in Top Layer of Reactor Grade Uranium Liquefied in Graphite Crucible.

Micro 6343 Ingot K-6-B' 100-X

Figure 11. Angular Inclusions in Interior of Reactor Grade Uranium Liquefied in Graphite Crucible.

Micro 6345 Ingot K-5-B 100-X

Figure 12. Gray and Occasional Dark Inclusions in Top Layer of Nitrided Reactor Grade Uranium.

Micro 7855 Ingot B-92-TL 100-X

43

TABLE III

Correlation of X-ray, Microscopic, and Chemical Analysis Results Obtained
from Some Inclusions Found in Uranium

X-ray Sample No.	X-ray Film No.	Specimen No.	Micro No.	Metallurgical Description of Inclusions	Chemical Analysis (ppm)		Phases	Approximate a_0 (Å)
					C	N		
28	4669	K6-B	6343	Dendritic carbides in top layer of ingot.	1750	<10	UC	4.978
32	4671	K6-B	6343		1750	<10	s. UC v.w. UO ₂	4.962
26	4668	K5-B	6345	Angular carbides in interior of ingot.	550	<10	UC	4.976
31	4670	K5-B	6345		550	<10	UC	4.985
27	4665	B-92-T	7855	Gray, irregularly-shaped nitride-carbides	>700	>700	s. U(C,N) v.w. UO ₂	4.927
30	4667	B-92-T	7855	" "	>700	>700	s. U(C,N) v.w. UO ₂	4.920
33	4695	B-92-T	7855	" "	>700	>700	U(C,N) v.v.w. UO ₂	4.916
34	4696	B-92-T	7855	" "	>700	>700	U(C,N) v.v.w. UO ₂	4.909
35	4697	B-92-T	7855	" "	>700	>700	U(C,N) v.v.w. UO ₂	4.919
29	4666	B-92-T	7855	Occasional dark oxides	>700	>700	s. UO ₂	5.474

s. = strong

v.w. = very weak

v.v.w. = very, very weak

therefore, that the a_0 as calculated may be slightly high. The results indicate the following:

1. The dendritic inclusions found in specimen K6-B' (Figure 10) consist mostly of the compound UC. This is substantiated by the fact that the carbon content in this sample is high and the a_0 is only slightly higher than the a_0 of 4.961 Å reported by Rundle, et al.⁴ for the compound UC. The very weak pattern of UO_2 which was observed in X-ray sample No. 32 may be due to an oxidation of the inclusions during removal. A slight oxidation still may occur even in a purified argon atmosphere, since the specimen becomes quite hot at the point where the inclusion is being knocked out.

2. The small angular inclusions found in specimen K5-B (Figure 11) consist of UC, which is consistent with the chemistry of the sample and the a_0 of the face-centered cubic pattern. Thus, equivalent X-ray diffraction patterns were obtained from two differently shaped inclusions.

3. A face-centered cubic diffraction pattern with an a_0 of 4.92 Å was obtained from the large quantity of light gray inclusions found in B-92-T (Figure 12). The size of this cubic cell would indicate that this phase is a solid solution phase of UC and UN, since UC has a reported a_0 of 4.961 Å and UN an a_0 of 4.890 Å.⁵ Both of these compounds have been reported⁵ to be mutually soluble in each other. The small amount of UO_2 which was observed together with the U(C,N) phase is probably again due to a slight oxidation as explained above. It was noted that the amount of UO_2 was less in X-ray samples No. 34, 35, and 36 which can be explained by the greater care taken to insure an oxygen-free atmosphere during the removal of these inclusions.

4. The large dark inclusions found in specimen B-92-T are UO_2 .

4. Uranium-Carbon Phase Diagram Liquidus (B. Blumenthal)

An attempt was made to determine the liquidus curve of uranium-carbon alloys of low carbon concentrations by saturation experiments. High purity uranium was kept molten in a high purity graphite crucible for predetermined periods of time and then rapidly solidified. After cutting off the top, each ingot was machined on a lathe in steps of 1/8" in depth; the first two cuts were 1/16" deep each. The turnings of each step were analyzed for carbon; the values reported in Table IV represent averages of two to four analyses.

⁴R. E. Rundle, N. C. Baenziger, A. S. Wilson and R. A. McDonald, "The Structures of the Carbides, Nitrides and Oxides of Uranium," J. Am. Chem. Soc. 70, 99 (1948).

⁵R. E. Rundle, N. C. Baenziger, A. S. Wilson, and R. A. McDonald, op. cit.

45
TABLE IV

Saturation Experiments of High Purity Uranium in Graphite Crucibles

No.	Temp. (°C)	Time (hrs)	Average Carbon Content (ppm) in Layer #(a)									Saturation(b) Concentration
			1a	1b	2	3	4	5	6	7	8	
B-612	1200	1	848		625	610	625	605	616	633	650	618
B-613	1200	2	1133	751	721	725	729	706	731	723	740	728
B-614	1200	4	1031	694	695	708	712	729	739	740	755	721
B-615	1250	1	1253	881	869	863	841	857	853	838	998	853
B-622	1300	1	1823	1063	1045	1055	1035	1010	1050	1014	1000	1035
B-623	1350	1	1659	1383	1296	1260	1269	1205	1166	1132	952	1275

(a) For layer location in ingot see Figure 13.

(b) Average values of layers 2 - 7 inclusive, except for specimen B-623 where only layers 2 - 4 were considered.

In general, each ingot has a skin of high carbon concentration (Figure 13). The carbon content rapidly decreases toward the interior; material at approximately $1/8$ " depth from the surface appears to be in equilibrium with the remainder of the melt. The last $1/8$ ", representing material at the core of the ingot, deviated from the average concentration in several experiments. The first and last $1/8$ " sections were, therefore, disregarded in computing the average saturation concentration of each ingot. At 1200°C , equilibrium was apparently reached after 2 hours; at 1250° and 1300°C , 1 hour sufficed to attain equilibrium. At 1350°C , a one-hour saturation experiment was not completely satisfactory; for the time being the carbon content of layers 2 through 4 are thought to represent the equilibrium concentration.

Figure 14 shows a plot of the temperature versus the saturation concentration. This liquidus curve, as plotted occurs at considerably higher carbon concentrations than the one previously obtained from liquation experiments on impure material. The reasons for the discrepancy are as yet not evident.

5. Uranium-Zirconium Alloys (M. H. Mueller)

a. Equilibrium Phases below 600°C

In a further attempt to determine the equilibrium phases present below 600°C in the uranium-zirconium alloy system, additional X-ray

264 043

DECLASSIFIED

46

Figure 13. Distribution of Carbon Content in Saturation Experiments.

Macro 17794

Figure 14. Saturation Curve of High Purity Uranium Melted in Graphite.

Macro 17793

47

diffraction patterns have been obtained at elevated temperatures. The results for a 59 w/o Zr-U alloy are summarized in Table V. The filings were obtained from gamma-quenched solid specimens. The indicated heat treatments were carried out on the same filings without cooling down until the final room temperature pattern, which indicated the presence of α Zr + ϵ + very slight α -U lines. At that time the filings were pounded slightly, resealed under vacuum, and heated for 16 hours at 600°C. A room temperature pattern of this material showed the presence of α U + α Zr only. The cold working apparently completely decomposed the ϵ phase.

Filings taken from a quenched solid sample of a 46 w/o Zr-U alloy, which consisted of the γ phase heated for 16 hours at 600°C, showed the presence of α U + α Zr only at room temperature. This sample, when put in the high temperature X-ray camera at approximately 800°C, showed the presence of γ + α Zr.

From the above observations, coupled with previously reported data, it appears that it is possible to transform a sample of filings through the following sequence:

TABLE V

X-Ray Diffraction Results Obtained from 59 w/o Zr-U Alloy
Filings Heated to the Following Temperatures

Temperature at Which Diffraction Pattern Was Obtained (°C)	Holding Time at Temperature (hr)	Phases
Room Temperature	--	γ
↓ 600	8	$\alpha \text{ U} + \alpha \text{ Zr} + \epsilon$
↓ 600	16	$\alpha \text{ U} + \alpha \text{ Zr} + \epsilon$
↓ 800	8	$\gamma + \alpha \text{ Zr}$
↓ 700	16	$\gamma + \alpha \text{ Zr}$
↓ 600	8	$\alpha \text{ Zr} + \epsilon$
↓ 600	16	$\alpha \text{ Zr} + \epsilon + \text{very slight } \alpha \text{ U}$
↓ Room Temperature	--	$\alpha \text{ Zr} + \epsilon + \text{very slight } \alpha \text{ U}$

264 045
DECLASSIFIED

48

b. Structure of the Epsilon Phase

The epsilon phase, which has been observed in the uranium-zirconium alloys with high zirconium contents, approximately 60 - 80 a/o Zr, appears to be a cubic phase with an a_0 of approximately 10.69 Å. The a_0 varies somewhat according to the ratio of uranium to zirconium content.

A single crystal of this phase was positioned so that one of its major axes was parallel to the main axis of a goniometer. A number of Laue back-reflection photograms were then obtained at each 45° rotation about this axis in order to check for symmetry. Fourfold symmetry was observed at the 0°, 90°, 180° and 270° positions and twofold symmetry was noted at the 45°, 135°, 225°, and 315° positions. This same symmetry was observed with several different crystals. The Laue patterns also showed fourfold symmetry after moving the crystal 90° to the above described rotation axis. Upon positioning the crystal such that the (111) plane was perpendicular to the X-ray beam, the Laue photograph showed threefold symmetry.

Rotation and equi-inclination Weissenberg photographs for seven layer lines from these crystals were indexed according to a body-centered cubic unit cell with an a_0 of approximately 10.69 Å. Powder photographs of the same composition could also be indexed according to this cubic cell, except for a few of the high angle lines which appeared to be displaced in a regular way that indicated an increase in the a_0 of approximately 1 part in 500.

The a_0 of the epsilon phase, as shown in Table VI, is slightly less than three times the a_0 of the parent gamma phase from which the epsilon was formed. The gamma phase, which is body-centered cubic, is a high temperature solid solution phase between gamma uranium and alpha zirconium.

TABLE VI

Lattice Parameters of the Gamma and Epsilon Phases
of the Same Composition Uranium-Zirconium Alloy

Phase	a_0 (Å)
γ	3.575
(3 times γ)	(10.725)
ϵ	10.688

49

A transformation has also been made from a single crystal of gamma to a single crystal of epsilon in which the (100) cube face of the small gamma cubic cell became the (100) cube face of the epsilon phase.

6. Uranium-Zirconium-Niobium Alloys

a. Phase Diagram (A. E. Dwight, L. T. Lloyd, R. S. Lindberg)

A partial binary equilibrium phase diagram (Figure 15), which essentially confirms the earlier diagram reported by Sawyer in ANL-4027, has been constructed for uranium alloys containing up to 5 w/o niobium. The line which separates the gamma region from the gamma plus beta region is based upon metallographic examination of specimens transformed by the interrupted quench method. The 667°C horizontal line is based upon thermal arrest points as well as metallographic evidence. The beta to alpha transformation is believed to be of a peritectoid type, in that metallographic observation of a 0.49 w/o Nb alloy quenched from a temperature below 667°C indicated the presence of less second phase material than the one quenched from a temperature just above 667°C. Metallographic observations indicate a eutectoid reaction between 660° and 640°C; the exact temperature of this reaction has not been determined.

The lower bounding surface of the single phase gamma region has been determined for uranium alloys containing up to 8 w/o Zr and 5 w/o Nb. The isothermal lines which locate this surface are shown in Figure 16. These were determined by metallographic examination of specimens which contained from 1 to 5 w/o Nb and from 0 to 8 w/o Zr, and which had been isothermally transformed at various temperatures by the interrupted quench method. The intersections of the isothermal lines with the uranium-niobium binary diagram were taken from that reported above; the intersections with the uranium-zirconium diagram were taken from the work of Summers-Smith,⁶ modified in the range of 1 to 3 w/o Zr to conform to the data of Chiswick and Zegler reported in ANL-5439.

b. Heat Treatment and Properties (M. H. Mueller, A. E. Dwight, S. Greenberg)

An X-ray diffraction study was made of a number of heat-treated specimens of U-5 w/o Zr-1.5 w/o Nb ternary alloys which have been previously shown to undergo aging with respect to hardening and corrosion following gamma quenching. The X-ray diffractometer charts obtained from these samples indicated that there was a change in the lattice parameters of the alpha uranium as a function of the time and temperature of the aging treatment. Most of the diffraction peaks were quite broad, especially those

⁶"The Constitution of Uranium-Zirconium Alloys," J. Inst. of Metals, 83, 277 (1954-55).

264 047

DECLASSIFIED

50

Figure 15. Uranium-Niobium Equilibrium Diagram up to 5 w/o Niobium.

Macro 17791

Figure 16. Lower Bounding Surface of the Single Phase Gamma Region in the Uranium-Zirconium-Niobium Ternary Diagram as Shown by Isothermal Lines.

Macro 17790

264 048

0371229.0330

51

obtained from the as-quenched specimens, causing considerable overlap of some of the peaks and resulting in very broad and diffuse peaks in the region of medium to high 2θ values. However, the peaks became progressively sharper as aging progressed. Since the line position shifting was considerable, it was possible to observe the effect of aging time and temperature on the (111) reflection. Due to the fact that the (111) is affected by all three lattice parameters of alpha uranium, it is not possible to determine which of the parameters were expanded in the as-quenched or low temperature aged samples.

Special precautions were taken to insure that the specimen surface of each sample was accurately located in the exact same position of the diffractometer. The (111) peak was then step scanned in order to locate the position of maximum intensity. This peak appears at a 2θ of approximately 39.50° in normal unalloyed uranium. The 2θ angles along with the corresponding corrosion and hardness values obtained on a number of specimens which were quenched from the gamma and then aged for various times and temperatures are shown in Table VII.

TABLE VII

Correlation of Corrosion Resistance, Position of 2θ Angle for (111) and Hardness Data for Various Samples as a Function of Aging

Sample Number	Aging		Corrosion Resistance ^(a)	2θ Angle for (111)	Vickers Hardness (30-kg load)
	Temperature ($^\circ\text{C}$)	Time			
1	As Quenched		Good	39.1	450
2	425	10 min	Good	39.3	551
3	425	20 min	Good	39.3	564
5	425	40 min	Bad	39.35	547
7	425	2 hr	Bad	39.4	604
8	425	4 hr	Bad	39.5	600
	375	72 hr	Borderline	39.15	
	440	5 min	Good	39.35	
	475	3 min	Bad	39.4	

(a) "Good" implies no failure by cracking or spalling in two-week test in degassed, distilled water at 290°C . "Bad" implies failure in less than two weeks.

DECLASSIFIED

264 049

The hardness is believed to be increased by aging as the result of a precipitation of a submicroscopic second phase from a metastable solid solution. The response obtained in the corrosion tests can also be explained on the basis of this same type of precipitation and a relief of stress, as indicated by a sharpening of the diffraction peak. On this alloy, corrosion resistance is improved over the "as quenched" condition by aging at a sufficiently low temperature for short times. Upon further aging at this temperature, the corrosion resistance is destroyed before the precipitated phase has agglomerated to a size visible microscopically, but precipitation may be continuing on a submicroscopic scale. In fact, none of the samples aged at 425°C shown in Table VII was overaged to the point of showing the presence of a second phase microscopically, nor did they show a definite softening as a result of overaging. At present there seems to be some question as to the correlation between hardness and corrosion resistance in these alloys.

Additional diffraction and hardness data were obtained from a set of alloy specimens which were annealed for various times at 400°C, as shown in Figure 17. Like the previous data, a shift in the (111) position was observed with increased time, which also resulted in increased hardness. It is evident, based on the hardness data only, that overaging did not take place in these specimens.

7. Properties of Uranium-Plutonium-Fissium Alloys (L. R. Kelman, J. E. Baumrucker)

A study has been initiated of uranium-plutonium-fissium alloys to determine the influence of fission products on metallurgical properties of recycled fuel for PBR. Los Alamos has shown that additions of 1 to 2 w/o Zr to U-10 w/o Pu and U-15 w/o Pu alloys tend to stabilize the zeta phase and markedly lower machinability of normally cooled alloys. The eutectoid reaction occurring normally at 650°C is inhibited, resulting in increased hardness, brittleness, and microcracks. Also, Los Alamos has some tentative information to the effect that additions of molybdenum to uranium-plutonium alloys tend to stabilize the gamma uranium phase and to suppress the formation of the brittle zeta phase. These results suggest that additions of small amounts of fission products such as molybdenum, niobium, and zirconium may tend to embrittle uranium-plutonium alloys but that larger quantities may result in relatively ductile alloys. It is hoped that the addition of larger amounts of these elements will also result in alloys stable to irradiation damage by virtue of the stabilization of an isotropic cubic phase. With this in mind, we have started our fissium alloy program by studying a U-20 w/o Pu-5 w/o Mo alloy. It is our intention to add other fission elements to a base alloy which has already been proven to have satisfactory metallurgical properties and to be stable to irradiation damage.

53

Figure 17. 2θ Angles for the (111) Reflection and Hardnesses as Functions of Aging Time for U-5 w/o Zr-1.5 w/o Nb Alloy Tempered at 400°C After Quenching from 800°C.

Macro 17924

264 051

DECLASSIFIED

54

Preliminary results on a cast U-21 w/o Pu-5 w/o Mo alloy indicate that it is fine grained with a hardness only slightly higher than that of the binary U-20 w/o Pu alloy. As cast, it has a predominantly BCC structure. Its machinability is improved somewhat over that of the binary alloy. Irradiation studies on uranium alloys containing 15 and 20 w/o Pu resulted in extreme surface roughening normally associated with a coarse grain structure; accordingly, the refinement of the grain size by a 5 w/o Mo addition is encouraging.

55

V. AQUEOUS CORROSION ▲

1. High Temperature Aqueous Corrosion of Aluminum (W. E. Ruther, C. A. Youngdahl, G. Dragel)

a. 2S Aluminum-Nickel Alloys

Corrosion rate determinations have been centered about aluminum alloys containing 0.5 to 2 w/o nickel in 2S aluminum. Corrosion tests are now in progress in small autoclaves and in solution replenishing loops (all static tests). The results are summarized in Table VIII.

TABLE VIII

Corrosion Rates of Aluminum-Nickel Alloys

Alloy	Test Condition	Rate of Metal Loss After Initial Period	Estimated Intercept (mg/cm ²)
0.5 w/o Ni in 2S (A108, A124)	Distilled water; replenishing loop; 290°C	3.4 mdd* (71 days)**	0.8
0.5 w/o Ni in 2S (A124)	pH 4.6 (H ₂ SO ₄); replenishing loop; 290°C	3.4 mdd (43 days)	0.6
0.5 w/o Ni in 2S (A124)	Distilled water; replenishing loop; 250°C	2.4 mdd (41 days)	0.6
0.5 w/o to 2 w/o Ni in 2S Al	Distilled water; small autoclaves; 315°C	6 mdd (38 days)	2.3
0.5 w/o to 2 w/o Ni in 2S Al	Distilled water; small autoclaves; 350°C	18 mdd (22 days)	2.3

*mdd = milligrams per square decimeter per day.

**number of days the test has run.

The corrosion rate at 290°C was not affected by lowering the pH to 4.6. This was unexpected since reducing the pH by this amount for 2S unalloyed aluminum markedly reduced the corrosion rate at 200°C. The samples were typically covered with a smooth, dark gray corrosion coating. In the 350°C testing, the initial coating flaked off, leaving a transparent film which then grew into the type of coating described above.

56

In testing performed by the Reactor Engineering Division in dynamic loops (15 - 20 fps) the rates were higher than those reported in Table VIII. For example, the corrosion rate of a 2S aluminum-1 w/o nickel alloy in distilled water at 315°C (20 fps) is perhaps 20 mdd (10 mils per year) as compared with about 6 mdd measured in the stagnant tests.

Heat Treatment. A few simple tests were made to determine the sensitivity of the 2S Al-1 w/o Ni alloy to heat treatment. The results are presented in Table IX.

TABLE IX

Effect of Heat Treatment of 2S Al-1 w/o Ni Alloy on Corrosion

Heat Treatment	Metal Lost After 13 Days at 315°C in Distilled Water (mg/cm ²)
Annealed 2 hours at 343°C	3.1 3.3
Held 30 minutes at 510°C and water quenched	2.9 2.9
Held 30 minutes at 510°C, water quenched, and aged 10 hours at 174°C	2.9 2.8

The data indicate that the annealed condition is the poorest corrosion-wise, but only by a small amount. This finding is concordant with results previously obtained with worked vacuum cast 2S aluminum.

Couple Tests. A test was performed to evaluate the sort of damage which might result when 2S Al-1 w/o Ni is galvanically coupled to Type 347 stainless steel. Four Type 347 stainless steel bolts and washers were tightened in holes drilled in a 1/8" sheet of the alloy. The bolts were removed after various corrosion periods in distilled water at 315°C; the longest time was 25 days. No large effects were noted. A small trough was formed (0.08 mm deep by about the same width) in the aluminum alloy at the circumference of the stainless steel washer. There was no pitting under the washer or in the bolt hole.

Crevise Corrosion. A simple crevice corrosion experiment was performed. One-eighth inch thick plates were set in close fitting slots milled in two plates of a 2S Al-1 w/o Ni alloy. The units were bound together

CONFIDENTIAL

264 054

57
with alloy wire or with stainless bolts, as shown in Figure 18. After 5.7 days in distilled water at 315°C the units were disassembled. Oxide formation caused sticking, but no serious trouble was encountered in separating the units. The samples were examined and reassembled for a further corrosion test to a total of 21 days.

The unit held together with wire gave no indication of crevice effects. The bolted unit produced a series of shallow pits which did not grow noticeably after the 5.7-day examination. The pits were located where the bottom of the milled slots and the sharp corners of the pieces in the slot were forced together by the bolt tension. The bolts were pulled up enough to slightly bend the slotted member. Since the pitting occurred on this specimen only, the extra bolt tension may be assumed to be the cause.

Welding. To determine the weldability of these alloys and the effects of corrosion on the welds, 1/8" thick specimens of the 2S Al-1 w/o Ni alloy were heliarc butt welded using filler rods of the same composition. The results of tensile tests on standard tensile specimens are shown in Table X.

TABLE X

Tensile Tests* of Welded 2S Al-1 w/o Ni Alloy

Before Corrosion (psi)	After 11.7 Days in Water at 360°C (psi)
17,700	16,600
18,200	17,000

*In each case break occurred at least 1/2" from weld line.

X-ray and metallographic examination of the welds showed them to be sound, with a smooth transition in microstructure through the welded area. The welder compared the ease of welding favorably with 2S aluminum.

Some of the same material was rolled to 0.063" and spot welded. Two spots were tensile tested in the annealed condition and two after a six-day corrosion test at 350°C. No difference in strength and no unusual corrosion effects were noted.

DECLASSIFIED

264 055

58

Figure 18. View of Crevice Corrosion Assembly After 21 Days in Water at 315°C.

Macro 17336

3/4-X

264 056

0371228.030

59

Melting and Casting Technique. As reported last quarter (ANL-5439), the very poor corrosion performance of one casting of a 2S Al-1.5 w/o Ni alloy made by the Sonken Galamba Company was attributed to porosity, since the chemical analysis showed no significant difference between this casting and other good castings. To test this hypothesis, a remelt of this alloy was made using chlorine sparging and chill casting. A great improvement in corrosion resistance was obtained, as is shown in Figure 19. The time of test was 15 days at 315°C in distilled water. The splotchy appearance of the remelt is due to some of the coating flaking off (unusual corrosion behavior). Note the absence of blisters.

The side view of the original casting shows the corrosion blister produced. This cavity was empty when opened, providing another bit of proof for the hydrogen blister theory. The casting technique for our experimental alloys has been improved so that no porosity is now noted on X-ray radiographs of typical castings.

b. Effect of Iron and Silicon Additions to Aluminum-Nickel Alloys

As described in the last quarterly report (ANL-5439), a series of alloys were made with iron and silicon additions to a master alloy of high purity Al-0.6 w/o Ni. The results indicated that for corrosion resistance at 350°C, a small amount of iron (0.2 w/o) was necessary, and that silicon additions of 0.1 w/o to 2 w/o, in the absence of iron, resulted in disintegration on corrosion testing.

Combined additions of iron and silicon to the same aluminum-nickel master alloy (composition: Al-0.6 w/o Ni-0.3 w/o Fe-0.3 w/o Si) produced an alloy which corroded considerably faster than the Al-0.6 w/o Ni-0.2 w/o Fe alloy, but it did not disintegrate in a 6.3-day test at 350°C. Combined additions of 1.1 w/o Fe + 0.33 w/o Si to the same master alloy produced an alloy that was comparable in corrosion resistance with the aluminum-nickel-iron ternary alloys when tested for 7.7 days at 350°C.

To see if larger amounts of nickel alone could accommodate the presence of silicon, an Al-4 w/o Ni-1 w/o Si alloy was tested. This alloy was corrosion resistant at 350°C when tested for one day. In a series of alloys containing 0.5 w/o nickel, with 0.1 w/o, 0.2 w/o, and 0.3 w/o iron additions, only the 0.3 w/o iron alloy was good at 350°C.

The tentative conclusions drawn from this preliminary investigation are:

1. For good corrosion resistance at 350°C, the aluminum-nickel-iron alloy appears to require at least 0.8 w/o total nickel and iron, with a probable minimum nickel content of about 0.4 - 0.5 w/o.

DECLASSIFIED

264 057

60

Figure 19. Effect of Casting Quality on Corrosion Behavior of 2S Al-1.5 w/o Ni Alloy After 15 Days at 315°C in Distilled Water.

19-a.

Macro 17407

Macro 17408

19-b.

Macro 17407

Macro 17408

All magnifications 2-X

Original Sonken Galamba
Casting Rolled to 1/8".

Remelted and Rolled to 1/8".

61

2. In the presence of silicon, the amount of total nickel and iron required to prevent disintegration is greater. Alloys containing silicon appear to have slightly improved adherence between the corrosion coating and the metal. Whether this aids in resistance to flowing water is not known at this time.
3. A smooth adherent corrosion coating is produced by a fine and uniform dispersion of the second phase in the alloy. Surface roughness on corrosion occurs when the second phase has agglomerated into larger particles.

c. Effects of Other Alloying Constituents

Alloys with nominally 2 w/o of the following alloying element additions to high purity aluminum were air-cast: lead, tin, bismuth, cadmium, cobalt, iron, copper and platinum. Only the last four gave fair results on corrosion testing at 315°C; the others disintegrated. Cobalt and copper alloys were superior to the platinum and iron alloys, but all were inferior to a vacuum cast 1 w/o Ni alloy. In view of the effect of small amounts of iron on aluminum-nickel alloy corrosion, it is planned to attempt a preliminary investigation of combined additions of copper-nickel-iron to high purity aluminum to see if further improved corrosion resistance may be obtained.

d. Solution Additives

The test of a solution additive of 5 ppm nickel as NiSO_4 at pH 3.5 has been concluded after about 70 days at 275°C. The corrosion rate of the 2S aluminum in replenishing autoclaves was 0.83 mdd. The samples were in excellent condition with very thin films; no discernible deposit was formed on either the samples or the autoclave.

2. Mechanism of Zirconium Corrosion (R. D. Misch, F. H. Gunzel)

The following three aspects of the electrical properties of oxide films on zirconium have been studied: (1) the reproducibility of successive measurements; (2) the temperature of conduction of anodic films as a function of increasing anodizing voltage; and (3) the change in film thickness with anodizing voltage as determined by electrical capacity.

Anodic films show very reproducible conductivities when the metal is homogeneous. The technique is to measure the current flowing when 10 mv is maintained between a probe resting on the oxide and the sample as a function of temperature in a vacuum. In the case of cast zirconium, the variations in temperature of conduction may arise from heterogeneity or from differences in area of contact as a result of the topography of the surface. On a single specimen, the temperature at which 0.5 microampere flowed was $353^\circ \pm 12^\circ\text{C}$ for a 100-V anodic film.

264 059

DECLASSIFIED

62

In subsequent work, emphasis has been placed on the temperature range in which the current is $0.5 \mu\text{a}$. The temperature of conduction increases with film thickness from about 350°C for the thinnest films to about 550°C for the thickest. The highest temperatures of conduction are observed when white oxide appears on the surface.

Capacity data indicate that the thickness of the anodic film increases linearly for Grades I and III zirconium and for Zircaloy-I up to the maximum voltage investigated - 500 V. In the case of Zircaloy-II, the linear growth is observed only up to about 300 V. Above this point the film apparently breaks down as it thickens and the capacity does not decrease. Other observations also indicate that the anodizing parameters of Zircaloy-II differ significantly from those of Grades I and III zirconium, and of Zircaloy-I. This unusual behavior is not apparent from the curve of temperature of conduction versus anodizing voltage.

3. Corrosion Resistant Uranium Alloys (S. Greenberg)

a. Uranium-5 w/o Zirconium-1.5 w/o Niobium Alloys

Analyses of corroded samples have continued. Table XI indicates the steady build-up of hydrogen as corrosion proceeds; it also indicates that after a short initial period, the fraction of hydrogen produced during corrosion which penetrates the alloy remains constant. This fact is of importance in considering the over-all rate of hydrogen build-up in the metal, as shown in Table XII. The product of the average hydrogen production rate and the percentage of hydrogen that enters the metal is a measure of the rate of hydrogen build-up in the metal. The average corrosion rate and behavior of the samples varied widely, yet the over-all rate of hydrogen build-up rate was fairly constant.

TABLE XI

Hydrogen Build-up as Function of Corrosion Time
(Alloy H-416. Cast, gamma quenched, aged 2 hours at 400°C)

Time (hr)	Wt. Loss (mg)	H ₂ in Corroded Sample (ppm)	% of Total H ₂ Produced That is Found in Sample
113	234	4.0	1.14
274	692	6.5	0.71
401	848	7.6	0.69
Chip out of sample			
642	1127	13.9	0.71
Sample cracked into 3 pieces			

63

TABLE XII
Hydrogen Diffusion

Sample and Heat Treatment	Test Time (days)	Average Corrosion Rate (mcd)	Average H ₂ Produced Per Day ^(a) (ppm)	% of H ₂ Produced That Entered Metal	Rate of Hydrogen Build-up in Metal ^(b) (ppm/day)	Condition After Test
<u>H-416C</u> . Cast, gamma quenched from vacuum, aged 400°C, 2 hours	26.7	8.6	68.1	0.7	0.48	Cracked
<u>L-170B</u> . Cast, gamma quenched from salt	18.9	9.4	73.3	0.6	0.44	No Cracks
<u>H-419B</u> . Rolled, gamma quenched from vacuum, aged 400°C, 2 hours	48.9	6.7	47.6	0.96	0.46	Cracked
<u>L-170B</u> . Cast, gamma quenched from vacuum	47.9	6.5	49.5	0.97	0.48	No Cracks

(a) Based on final weight of sample and reaction $U + 2 H_2O \rightarrow UO_2 + 2 H_2$

(b) Product of columns 3 and 4

264 061

64

It is believed that, in order to rigorously correlate hydrogen content with cracking, the concentration very close to cracks is the significant quantity to be evaluated; techniques to accomplish this are being developed. Evidence for this belief is the fact that the salt-treated sample referred to in Table XII contained about 35 ppm hydrogen after heat treatment, which was undoubtedly uniformly distributed. No cracking was evident after an additional build-up of 8 ppm produced by corrosion. Also, in the previous quarterly report (ANL-5439), reference was made to a sample which was cut in two after corrosion: one piece had a subsurface crack and had the higher hydrogen content.

b. U-5 w/o Zr-1.5 w/o Nb Alloy Clad with Zircaloy-II

Studies to determine the effects of several variables on the corrosion resistance of the bonds are as yet inconclusive, but the following generalizations may tentatively be made:

1. The bond layer is not as corrosion resistant as the meat: sections of clad plate with meat and bond exposed on four sides have never lasted as long as one month in 290°C water without failure of at least part of the bond.
2. 315°C is a much more severe condition than 290°C as regards the comparison between the bond area and the meat material.
3. Aging for improved corrosion resistance of the meat appears to be detrimental to the corrosion resistance of the bond.
4. Cold rolling as a final step before heat treatment appears to improve the corrosion resistance of the bond.

c. Epsilonized Uranium-Silicon Alloys

Work has continued on castings received from Nuclear Metals, Inc. Two groups of samples have been tested:

Group 1. The results of 65 - 69 hour tests at 290°C are summarized in Table XIII. It is difficult to speculate seriously as to the effects of silicon and carbon contents and time of heat treatment when there are such differences in corrosion behavior between supposedly identical samples tested under as nearly identical conditions as it is possible to maintain. However, there is some indication that longer heat treating times are necessary for epsilonization of lower silicon alloys. It would be pertinent to determine the degree of epsilonization of the three castings. Carbon content, including the ratio to silicon, may also be of importance.

65

TABLE XIII

Corrosion of Epsilonized Uranium-Silicon Alloy in
Distilled Water at 290°C

Sample	Si (w/o)	C (ppm)	Crucible	Time at 800°C (days)	Corrosion Test Time (hours)	Wt. Change Rate (mcd)	Appearance After Test
UA-30-1	3.7	700	Graphite	2.67	69	- 0.38	Discontinuous dull film over lustrous black metal. Swelling at cracks in cylindrical surface.
UA-30-2	3.7	750	Graphite	2.67	69	+ 2.0	Less rough than above sample. Slight swelling at many cracks on cylindrical surface.
UA-56-1	3.9	630	BeO	4.33	69	+ 3.1	Dull luster. Pitted.
UA-56-2	3.9	630	BeO	4.33	69	- 1.3	More lustrous than above. Small crack at one end. Swelling at crack.
UA-72-1	3.7	330	BeO	4.33	65	+ 2.3	Lustrous. Pitted.
UA-72-2	3.7	330	BeO	4.33	65	- 5.5	Discontinuous brown film over lustrous black metal. Pitted.

66

Group 2. The results of tests at 290°C for 74 hours are summarized in Table XIV. All samples were melted in zirconia-washed graphite crucibles and epsilonized at 800°C for seven days. No simple relationship between corrosion behavior and silicon or carbon content is evident. It is possible that inhomogeneity of the material may result in poor sampling.

Additional samples of UA-106 and UA-109 were tested at 315°C for 92 hours. UA-106 swelled and broke in half; UA-109 had a weight loss of 20 mcd. Half the sample was very rough and was swelling; the other half was smooth.

TABLE XIV

Corrosion of Epsilonized Uranium-Silicon Alloys
74-Hour Tests in Distilled Water at 290°C

Sample	Si (w/o)	C (ppm)	Rate of Wt. Loss (mcd)	Appearance After Test
UA-98-1 } UA-98-2 }	3.8 ₄	900	3.71 3.91	Faintly lustrous black film. Loose powder. Same as above except one end chipping and cracking.
UA-103-1	3.8 ₄	465	0.87	Lustrous black film with some gray areas. Very little loose powder.
UA-106-1 } UA-106-2 }	3.7 ₆	786	0.34 1.1	Same as above. Same as above.
UA-109-1	3.8 ₀	930	0.88	Same as above.
UA-125-1 } UA-125-2 }	3.8 ₄	795	6.6 6.5	Dull black coating. Some loose powder. One silver colored spot. Dull black coating. Some loose powder.

264 064

03712291030

67

d. Post Irradiation Corrosion Tests

An epsilonized 3.89 w/o silicon alloy, irradiated in an aluminum block in CP-5 to an estimated burnup of 0.1 a/o, was tested in boiling distilled water. Its weight change was +0.61 mcd after 22 hours. There was no visible oxide in the water.

A similar sample, irradiated in a Kittel capsule in the MTR to an estimated burnup of 0.71 a/o, has been tested for one day in degassed, distilled water at 260°C. Surface temperature during irradiation was 360°C, and the central metal temperature was estimated to be at 860°C. After the indicated corrosion test there was no apparent change in the sample. Corrosion rate was 0.1 mcd. The same sample had a rate of 15.7 mcd at 290°C prior to irradiation.

A pin sample of U-5 w/o Zr-1.5 w/o Nb alloy clad with Zircaloy-II and open at both ends was tested in boiling distilled water after an estimated 0.1 a/o burnup in an aluminum block in CP-5. The specimen as received contained several holes in the clad and the core appeared to be approximately half gone. No weights were taken. There was no apparent change in the sample and no visible oxide in the water, as a result of a 24-hour test in boiling distilled water.

68

VI. EFFECTS OF IRRADIATION ON MATERIALS

1. Effects of Irradiation on Uranium Powder Compacts (J. H. Kittel)

Three types of hot-pressed unalloyed uranium powder compacts prepared by Sylvania are being irradiated in NaK-filled capsules in the MTR. They are: (1) solid, full density material; (2) full density material with a 1/16" diameter axial core hole; and (3) partial density material with approximately 12.5% porosity. The specimens are 3/8" in diameter and 1" long.

Some of the above specimens have been removed from the MTR and examined for changes resulting from irradiation. Burnups ranged up to 0.28 a/o (2400 MWD/T), as determined from attached cobalt monitors. The irradiation conditions and the changes observed are summarized in Table XV.

It can be noted from the data in the table and in Figure 20 that the full density specimens are shortening under irradiation and the rate of shortening increases with increasing burnup. On the other hand, the partial density specimens increased in length at a uniform rate. One of the specimens exhibited surface cracking which resulted in the loss of part of the specimen.

TABLE XV

Effects of Irradiation on Uranium Powder Compacts

Specimen Type	Co ⁶⁰ Indicated Burnup (a/o)	Calculated Temp. (°C)		Growth Rate (microinches/inch/ppm burnup)
		Surface	Center	
Solid	0.046	105	160	- 0.11
Solid	0.28	380	660	- 24
Cored	0.14	235	395	- 19
Cored	0.28	380	660	- 31
12.4% Porosity	0.080	155(a)	245(a)	42
12.5% Porosity	0.24	335(a)	575(a)	43

(a) Temperatures of porous specimens were calculated as though specimens were solid.

264 060

03 10 1960

69

Figure 20. Effect of Increasing Burnup on the Rate of Shrinkage of Hot Pressed Uranium Powder Specimens.

264 067

DECLASSIFIED

70

2. Effects of Irradiation on Corrosion-Resistant Uranium Alloys (J. H. Kittel)

a. U-5 w/o Zr-1.5 w/o Nb Alloy

A group of twelve plate-type specimens has been examined for changes resulting from burnups up to 0.094 atom per cent (800 MWD/T), as indicated by attached cobalt monitors. The plates were approximately 1" x 0.8" x 0.2" and were irradiated in the MTR in NaK-filled capsules. Each plate had from two to six sides roll bonded to Zircaloy-II cladding which ranged in thickness from 0.010" to 0.040". The conditions under which the specimens were irradiated and the changes observed are summarized in Table XVI.

Unrestrained swaged specimens of this alloy with similar heat treatments had been found to elongate at growth rates of approximately 290 microinches/inch/ppm burnup; the present clad specimens were found to elongate at considerably lower rates. Cladding appears to restrain the irradiation growth tendency of the alloy to a large degree. The elongation that was observed on the plates clad on two sides occurred at the center of the core where the influence of the cladding was least, so that full size plates with edge strips and end closures would probably show even lower growth rates. The above specimens have been submitted to the Corrosion Group for post-irradiation corrosion testing.

TABLE XVI

Irradiation Growth of U-5 w/o Zr-1.5 w/o Nb Wrought and
Heat Treated Plates Clad with Zircaloy-II

Heat Treatment	Number of Sides Clad	Growth Rates, G_i^* (microin/in/ppm burnup)
15 minutes at 850°C, water quench, reheat 45 minutes at 425°C	4	18 - 44
Same	6	1 - 18
3 minutes at 725°C, 1 hour at 650°C, air-cool; followed by 3 minutes at 725°C, water quench, 2 hours at 400°C	2	9 - 28
3 minutes at 850°C, 1 hour at 650°C, air-cool; followed by 3 minutes at 850°C, water quench, 2 hours at 400°C	2	5 - 33

*Irradiation temperatures estimated not to have exceeded 300°C.

7/
b. U-3.8 w/o Si Alloy

Three cast specimens of this alloy, 10% enriched, were irradiated in NaK capsules to burnups up to 0.94% of the uranium atoms (8000 MWD/T). Burnups were computed from readings on attached cobalt monitors and corrected for flux depression resulting from the enriched material.

The conditions under which the specimens were irradiated and the changes observed are summarized in Table XVII. This material is highly stable dimensionally under irradiation unless irradiated near the melting point of the alloy. Based on observations of other specimens, the radical increase in diameter of the specimen exposed at the high temperature is probably due to an internal void resulting from fission gas accumulation.

TABLE XVII

Irradiation Growth of Cast and Homogenized*
U-3.8 w/o Si Specimens

Computed Irradiation Temperature (°C)		Growth Rate, G_i (microin/in/ppm burnup)	% Change in Diameter
Surface	Center		
160	350	- 3.2	2.3
360	860	- 2.0	2.4
480	1150	3.4	33.0

*2 hours at 825°C, air-cooled.

The specimens have been submitted to the Corrosion Group for determination of post-irradiation corrosion rates.

c. U-3.0 w/o Nb-0.48 w/o Sn Alloy

Six cast specimens of this alloy, 10% enriched, were irradiated in NaK capsules to burnups up to 0.58% of the uranium atoms (4900 MWD/T). Burnups were determined from attached cobalt monitors, due consideration being given to the flux depression created by the enrichment of the material.

264 069

DECLASSIFIED

72

The conditions under which the specimens were irradiated and the changes observed are shown in Table XVIII. This material is only moderately stable dimensionally, although it maintained good surface smoothness. The six specimens have been submitted to the Corrosion Group for post-irradiation corrosion testing.

TABLE XVIII

Irradiation Growth of Cast and Heat Treated*
U-3.0 w/o Nb-0.48 w/o Sn Alloy Specimens

Indicated U Burnup (a/o)	Computed Irradiation Temperature (°C)		Irradiation Growth Rate, G_i (microin/in/ppm burnup)
	Surface	Center	
0.19	180	230	38
0.30	220	330	29
0.38	250	340	28
0.58	310	410	15

*4 minutes at 800°C, water quench, 6 hours at 350°C.

264 070

0371228.030