Report No. BMI-1350
UC-25 Metallurgy and Ceramics
(TID-4500, 15th Ed.)

Contract No. W-7405-eng-92

AN EVALUATION OF THE PROPERTIES
AND BEHAVIOR OF ZIRCONIUM-URANIUM ALLOYS

Edited by

Arthur A. Bauer

September 28, 1959

BATTELLE MEMORIAL INSTITUTE
505 King Avenue
Columbus 1, Ohio

This document is
PUBLICLY RELEASABLE
Barry Steel
Authorizing Official
Date: 11-9-66

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency Thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

DISCLAIMER

Portions of this document may be illegible in electronic image products. Images are produced from the best available original document.

TABLE OF CONTENTS

	<u>Page</u>
ABSTRACT	1
INTRODUCTION	2
THE ZIRCONIUM-URANIUM CONSTITUTIONAL DIAGRAM	3
Areas of Disagreement	3
The Ternary Zirconium-Uranium-Oxygen and -Nitrogen Systems	5
The Influence of Oxygen and Nitrogen on Binary-Alloy Constitution	5
Epsilon-Phase Crystal Structure.	9
Discussion	13
References	13
KINETICS OF TRANSFORMATION OF ZIRCONIUM-URANIUM ALLOYS	15
Modes of Transformation	15
Gamma Transformation in the 50 w/o (28 a/o) Uranium Alloy	16
Gamma Transformation in 20 to 75 w/o (9 to 54 a/o) Uranium Alloys	29
Gamma Transformation in 0 to 20 w/o (9 a/o) Uranium Alloys	37
Discussion	39
References	41
THE EFFECTS OF HEAT TREATMENT ON THE MICROSTRUCTURE OF ZIRCONIUM-URANIUM ALLOYS	43
Alloys Containing 1 to 20 w/o (0.4 to 9 a/o) Uranium	44
Alloys Containing 20 to 75 w/o (9 to 54 a/o) Uranium	46
Alloys Containing 75 to 95 w/o (54 to 88 a/o) Uranium	51
References	54
STRENGTH CHARACTERISTICS OF ZIRCONIUM-URANIUM ALLOYS	55
The Effects of Composition on Mechanical Properties in the Annealed Condition.	56
The Effects of Gamma-Phase Decomposition on Mechanical Strength	66
Discussion	76
References	77
PHYSICAL PROPERTIES OF ZIRCONIUM-URANIUM ALLOYS	78
Density	78
Resistivity	78
Thermal Conductivity	78
Thermal Expansion	82
Diffusion Coefficients	84
References	87

TABLE OF CONTENTS
(Continued)

	<u>Page</u>
FABRICATING CHARACTERISTICS OF ZIRCONIUM ALLOYS CONTAINING UP TO 50 w/o (28 a/o) URANIUM	89
Alloys Containing up to 20 w/o (9 a/o) Uranium	89
Alloys Containing 20 to 50 w/o (9 to 28 a/o) Uranium	90
Discussion	91
References	92
THE CORROSION BEHAVIOR OF ZIRCONIUM-URANIUM ALLOYS	93
Corrosion Behavior of Uranium	93
Corrosion Behavior of Zirconium	93
Corrosion of Binary Alloys in 100 C (212 F) Water	94
Corrosion of Binary Alloys in High-Temperature Water	95
Corrosion Behavior of Zirconium-Uranium Ternary Alloys	103
Corrosion Behavior of Zirconium-Uranium Quaternary Alloys	106
Discussion	106
References	107
IRRADIATION PERFORMANCE OF ZIRCONIUM-URANIUM ALLOYS	112
Alloys Containing Up to 22 w/o (10 a/o) Uranium	113
Alloys Containing 40 to 60 w/o (20 to 36 a/o) Uranium	115
Discussion	115
References	116

AN EVALUATION OF THE PROPERTIES AND BEHAVIOR OF ZIRCONIUM-URANIUM ALLOYS

Arthur A. Bauer

Data from a survey of the literature and other available information on zirconium-uranium alloys have been reviewed for the purpose of obtaining a coherent picture of current knowledge about the properties and behavior of zirconium-uranium alloys. The results of the survey were used to revise and extend the presentation of material gathered earlier in a similar study and reported in BMI-1030 in August, 1955.

The constitution of zirconium-uranium alloys is discussed and a constitutional diagram for the system is presented. The effects of oxygen and nitrogen, which are present in these alloys as contaminants, on alloy constitution are shown in the form of ternary diagrams and in terms of their quantitative effects on the phases present. The transformation kinetics and the nature of the transformation of the high-temperature body-centered-cubic gamma phase to the phases stable at room temperature are described. Two regions are discussed: in the 20 to 70 w/o uranium composition range, gamma, which is retained on quenching, transforms isothermally to the intermediate epsilon-phase structure by a diffusion-controlled nucleation-and-growth process; in alloys containing less than 20 w/o uranium, gamma transforms martensitically to a strained alpha-zirconium structure on quenching, with the diffusion-controlled transformation of gamma to either epsilon or alpha proceeding above the M_s temperature.

Typical zirconium-uranium alloy microstructures produced by working and by various heat treatments are shown, and a correlation of the structure with the manner in which it was produced and the resultant mechanical properties is attempted. Hardness, tensile, and creep data for zirconium-uranium alloys are tabulated and evaluated in terms of alloy constitution and transformation-kinetics behavior. Physical-property data for zirconium-uranium alloys are presented in tabular and graphical form. The best fabrication techniques for forging, hot and cold rolling, extruding, and swaging are detailed.

The corrosion resistance of zirconium-uranium alloys in water at various temperatures and corrosion behavior as affected by alloy constitution are discussed. The effect of ternary additions on corrosion resistance is discussed, and pertinent data are tabulated.

The influence of zirconium-uranium alloy constitution and properties on neutron-irradiation behavior is discussed, and the general effects of irradiation upon these alloys are summarized.

INTRODUCTION

Zirconium, because of its low thermal-neutron cross section and its excellent resistance to corrosion by high-temperature water, has seen wide application in nuclear reactors. These favorable properties have also led to the development of zirconium- or Zircaloy-clad zirconium-uranium fuel elements for reactor use.

In 1955, to obtain a coherent picture of zirconium-uranium properties and behavior, a review of literature pertinent to these alloys was undertaken. These data were evaluated and the results presented in a previous publication, BMI-1030, "An Evaluation of Data on Zirconium-Uranium Alloys". On the basis of the analysis contained in BMI-1030, a program of research was begun at Battelle which was intended to refine our knowledge of zirconium-uranium alloys. The results of this research, along with data generated at other laboratories during this period, have provided a better understanding of the behavior of zirconium-uranium alloys, and have been utilized in preparing the revision of BMI-1030 presented in this report.

A standard system of phase designations has been adopted in order to prevent confusion in presenting data. Alpha uranium, alpha zirconium, and beta uranium are referred to as such, while the solid solution of body-centered-cubic gamma uranium and beta zirconium is referred to as gamma. The intermediate phase occurring near 50 w/o uranium is designated as epsilon.

To help the reader locate the information of his particular interest, the data have been presented by category in separate sections of the report. Each section includes a list of the original sources for the information given.

THE ZIRCONIUM-URANIUM CONSTITUTIONAL DIAGRAM

Arthur A. Bauer

The constitution of zirconium-uranium alloys has been the subject of study by a number of investigators.⁽¹⁻⁹⁾ Agreement has been reached on the general form of the system although there are specific areas where disagreement still exists. At the present time, the diagram shown in Figure 1 is believed to present the best interpretation for the constitution of zirconium-uranium alloys prepared by arc melting from crystal-bar zirconium and biscuit uranium.

At elevated temperatures the body-centered-cubic forms of beta zirconium and gamma uranium are isomorphous. The body-centered solid solution is stabilized in intermediate alloys to a temperature of about 595 C (1105 F), where it decomposes to form alpha zirconium and epsilon. This intermediate epsilon phase is stable up to about 610 C (1130 F) at which temperature it forms peritectoidally from alpha uranium and the body-centered-cubic gamma solid solution.

At the high-uranium end of the system [approximately 93 w/o (84 a/o) uranium] the body-centered-cubic phase decomposes at about 685 C (1265 F) in a monotectoid reaction.

Solubilities of zirconium in alpha and beta uranium and of uranium in alpha zirconium are limited. Uranium solubility in alpha zirconium is less than 1 w/o (0.3 a/o).

Areas of Disagreement

As noted above, while there is agreement on the general form of the diagram, including such features as the gamma solid-solution immiscibility gap and the existence and stability of the intermediate epsilon phase, there are specific areas of the diagram concerning which disagreement exists.

Earlier, the intermediate epsilon phase had been the subject of considerable discussion; while there was general agreement that the phase did form it was thought the phase might be metastable. Recent studies⁽⁷⁻¹⁰⁾ have established the stability of the epsilon phase beyond question. However, fairly wide variations in the solubility range of the epsilon phase have been reported⁽⁷⁻¹¹⁾, with a maximum range at 500 C (930 F) of about 41 to 62 w/o (21 to about 34 a/o) being given⁽¹¹⁾. There is agreement that the range of solubility increases slightly as the eutectoid temperature is approached. A portion of the discrepancies in reported solubility limits can be attributed to differences in impurity levels, notably oxygen and nitrogen contents. Also, the rejection of alpha zirconium and alpha uranium occurs quite slowly from the epsilon phase which initially, during the transformation of quenched alloys, can contain considerable amounts of uranium and zirconium in supersaturated solution. The rate of rejection can significantly affect the apparent solubility limits for a given time of heat treatment.

FIGURE 1. ZIRCONIUM-URANIUM CONSTITUTIONAL DIAGRAM

The principal area of disagreement in the system occurs in the high-uranium portion of the diagram. The features shown in Figure 1 are based upon quantitative analysis of metallographic structures obtained by annealing in the beta-plus-gamma, alpha-plus-beta, alpha-plus-gamma₁, and alpha-plus-gamma₂ phase regions.⁽¹²⁾ In addition, high-temperature X-ray data⁽¹³⁾ for a 95 w/o (88 a/o) uranium alloy, initially heated to gamma solid-solution temperatures, indicated only the alpha-plus-gamma₂ region below the gamma monotectoid temperature on subsequent step cooling. However, dilatometric and high-temperature X-ray data have also been reported⁽⁴⁾ which indicate that a beta-plus-gamma₂ field exists in the temperature range below the monotectoid temperature and down to 662 C (1225 F), there being no alpha-plus-gamma field. This area of the system requires additional study and consideration but its discussion is not within the scope of the present report, which is concentrated on alloys of intermediate and high-zirconium compositions.

The Ternary Zirconium-Uranium-Oxygen and -Nitrogen Systems

Oxygen and nitrogen additions to zirconium-uranium alloys have a pronounced effect on constitution. Ternary zirconium-uranium-oxygen phase relationships are shown in Figures 2, 3, and 4. Phase relationships in the zirconium-uranium-nitrogen system are similar.

The phase relationships shown are based upon studies of the phase relationships occurring between zirconium and UO₂⁽¹⁴⁾, studies of the effect of oxygen and nitrogen on the constitution of alloys of epsilon-phase composition⁽⁷⁾, and quantitative studies of the effect of oxygen and nitrogen on the gamma uranium-alpha zirconium phase region⁽¹⁵⁾. Solubility of oxygen in epsilon is reported to be less than 500 ppm. Solubility of oxygen in the gamma phase at 660 C (1220 F) is given as 556 ppm, while nitrogen solubility is given as 425 ppm, with this maximum solubility occurring at about 65 w/o (41.5 a/o) uranium. The oxygen and nitrogen contents of the alpha-zirconium phase existing in equilibrium with the gamma phase containing these maximum oxygen and nitrogen levels are reported as 25,020 and 19,125 ppm, respectively.

The general phase relationships shown in Figures 2 through 4 may also be predicted from thermodynamic considerations. Both oxygen and nitrogen markedly increase the stability of alpha zirconium. Alpha uranium is little affected by these additions, and, if the same is assumed for the epsilon phase and the gamma solid-solution phase, then free-energy considerations lead to the ternary sections shown.

The Influence of Oxygen and Nitrogen on Binary-Alloy Constitution

The constitutional diagram presented in Figure 1 is, as noted, presented for alloys prepared from crystal-bar zirconium and biscuit uranium by arc melting. On the order of 200 to 300 ppm oxygen and 50 to 60 ppm nitrogen is normally contained in alloys of intermediate composition where the most obvious effects of these contaminants

FIGURE 2. PROPOSED ZIRCONIUM-URANIUM-OXYGEN TERNARY SECTION AT 540 C (1000 F)

FIGURE 3. PROPOSED ZIRCONIUM-URANIUM-OXYGEN TERNARY SECTION AT 660 C (1220 F)

FIGURE 4. PROPOSED ZIRCONIUM-URANIUM-OXYGEN TERNARY SECTION AT 1095 C (2000 F)

on constitution are observed. It is felt that this diagram presents a reasonable working diagram for most applications since, at the present time, oxygen and nitrogen levels on this order are about the minimum that can be expected.

However, in the absence of oxygen and nitrogen some refinement of the diagram shown in Figure 1 is required. Based on quantitative studies of the effect of oxygen and nitrogen on the alpha zirconium-plus-gamma phase region⁽¹⁵⁾ and from consideration of the effects of oxygen and nitrogen on the epsilon phase region, the partial zirconium-uranium diagram as drawn for alloys containing neither nitrogen nor oxygen shown in Figure 5 has been proposed. The principal features of this diagram are the increased width of the gamma and epsilon regions as compared with those shown in Figure 1.

The volume percentage of alpha zirconium formed at 660 C (1220 F) in zirconium-uranium alloys exhibiting the alpha zirconium-plus-gamma phase as a function of oxygen and uranium content is shown in Figure 6. The pronounced effect of oxygen on constitution is apparent from the curves presented. A binary zirconium-35 w/o (17 a/o) uranium alloy is single-phase gamma. However, 1000 and 10,000 ppm oxygen produce microstructures in which the volume of alpha increases from zero to 17 and 55 per cent, respectively. Nitrogen will produce a similar and, in fact, a more pronounced effect at similar levels of contamination since it exhibits lower solubility in the gamma phase and presumably in the epsilon phase than does oxygen. However, since high nitrogen contents are not encountered in zirconium to the same extent as high oxygen contents, the nitrogen is less of a problem.

Epsilon-Phase Crystal Structure⁽¹⁶⁾

The structure of the intermediate epsilon phase has been determined to be primitive hexagonal with an a_0 of 5.03 Å and c_0 of 3.08 Å and with a c/a ratio of 0.61.⁽¹⁷⁻¹⁹⁾ The structure is based on the analysis of transformed single crystals of the body-centered-cubic high-temperature gamma phase. The transformation produces twinned crystals where the c -axis of the hexagonal cell is oriented along the eight possible (111) directions of the parent cubic cell, resulting in apparent cubic symmetry.

The structure is partially ordered with zirconium atoms located at the 0,0,0 position and with zirconium and uranium atoms located randomly at $1/3, 2/3, 1/2$, and $2/3, 1/3, 1/2$ positions. The random distribution of uranium and zirconium atoms allows a considerable range in composition. Intensity data indicate a space group of $P\bar{6}/mmm$, the structure being a partially disordered C 32-type AlB_2 structure. It does not appear that the degree of ordering is great.

A possible change in the nature or degree of ordering of the epsilon phase below 300 C (570 F) is indicated by a variety of data. Thermal-expansion data obtained in a high-temperature X-ray camera show a change in the rate of expansions at about 300 C with an increased rate above this temperature.⁽⁷⁾ Dilatometric data confirm this change in rate.⁽¹⁰⁾ Electrical-resistance curves versus temperature also show evidence of a change in the nature of the epsilon phase near 300 C as presented in Figure 7.⁽²⁰⁾ Specimens of the 50 w/o (28 a/o) uranium alloy quenched from 500 C (930 F) exhibit a break in the curve during reheating which is not reproduced on

FIGURE 5. CONSTITUTION OF OXYGEN- AND NITROGEN-FREE ZIRCONIUM-RICH ZIRCONIUM-URANIUM ALLOYS

FIGURE 6. VOLUME PERCENTAGE OF ALPHA PHASE AS A FUNCTION OF OXYGEN AND URANIUM CONTENT IN ZIRCONIUM-URANIUM ALLOYS AT 660 C (1220 F)

FIGURE 7. ELECTRICAL-RESISTANCE CHANGE WITH TEMPERATURE OF ZIRCONIUM-50 w/o (28 a/o) URANIUM SPECIMENS INITIALLY QUENCHED FROM 500 C (930 F)

subsequent slow cooling from either the gamma or epsilon region or during additional slow heating and slow cooling cycles. The indication is that the structure produced by quenching from 500 C is different than that produced by slow cooling. In addition to these observations, X-ray diffraction patterns obtained below 300 C show an increased broadening of reflections. While the nature of the change in structure below 300 C is unknown, the data referred to above do not suggest a change in crystal symmetry. It is more probable that a change in positioning of atoms on the crystal lattice or a change in the degree of order occurs as the temperature is lowered.

Discussion

The constitution of zirconium-uranium alloys has been studied by a number of investigators. While areas of disagreement concerning all of the details of the constitutional diagram still remain, agreement has been reached on its essential form. The diagram shown is based upon the study of alloys prepared by arc melting crystal-bar zirconium and biscuit uranium.

Both oxygen and nitrogen have a pronounced effect on alloy constitution. The most pronounced effect on constitution is noted in alloys of intermediate zirconium-uranium composition. Less than 500 ppm of oxygen is soluble in the epsilon phase and solubility in the gamma phase at 660 C (1220 F) is only slightly greater. Consequently, very little oxygen can be tolerated before a change in constitution is produced. Nitrogen exhibits a similar effect. As a result, control and knowledge of alloy oxygen and nitrogen content is important if the prediction of zirconium-uranium alloy constitution is to be attempted.

References

- (1) Peterson, D., and Wilhelm, H. A., "Phase Studies of Uranium-Zirconium Alloys", ISC-139 (December, 1950).
- (2) Kauffmann, A. R., Arnold, S. V., Titorchok, W. H., Russell, R. B., and Paynton, W. C., "Status of Zirconium-Uranium Phase Diagram", MIT-1078 (April, 1952)
- (3) Saller, H. A., Rough, F. A., and Bauer, A. A., "The Uranium-Zirconium Constitutional Diagram", BMI-824 (April, 1953).
- (4) Summers-Smith, D., "Constitution of Uranium-Zirconium Alloy System", J. Inst. Metals, 83 (February, 1955).
- (5) Buzzard, R. W., Liss, R. B., and Fickle, D. P., "The Uranium-Zirconium Binary System", J. Reactor Sci. Technol., 2 (2), TID-2002 (August, 1952).
- (6) McGeary, R. K., "Dilatometric Investigation of Zirconium, Zirconium-Uranium, Zirconium-Oxygen, and Zirconium-Nitrogen Alloys", WAPD-36 (July, 1951).

- (7) Rough, F. A., Austin, A. E., Bauer, A. A., and Doig, J. R., "The Stability and Existence Range of the Zirconium-Uranium Epsilon Phase", BMI-1092 (May 28, 1956).
- (8) Holden, A. N., and Seymour, W. E., "The Uranium-Zirconium System", Trans. AIME, 209, 515 (1957).
- (9) Duffey, J. F., and Bruch, C. A., "The Delta Phase Field of the Uranium Zirconium Equilibrium Diagram", Trans. AIME, 212 (1958).
- (10) Kearns, J., unpublished information (1956).
- (11) Knapton, A. G., United Kingdom, unpublished information (1957).
- (12) Saller, H. A., Rough, F. A., and Bauer, A. A., unpublished information (1954).
- (13) Bauer, A. A., and Austin, A. E., unpublished information (1956).
- (14) Saller, H. A., Rough, F. A., Bauer, A. A., and Fackelmann, J. M., "Phase Relationships of the Uranium-Zirconium-Oxygen System Involving Zirconium and Uranium Dioxide", BMI-1023 (July 28, 1953).
- (15) Bauer, A. A., Beatty, G. H., and Rough, F. A., "The Constitution of Zirconium-Uranium Alloys Containing Oxygen or Nitrogen", Trans. AIME, 212, 801 (1958).
- (16) Austin, A. E., private communication (1958).
- (17) Silcock, J. M., Trans. AIME, 209, 521 (1957).
- (18) Boyko, E. R., "The Structure of the Phase in the Uranium-Zirconium System", Acta Cryst., 10, 712 (1957).
- (19) Mueller, M. H., Knott, H. W., and Heaton, L., "The Hexagonal Phase Found in Certain Zirconium and Titanium Alloys", presented at the 15th Pittsburgh Diffraction Conference (November, 1957).
- (20) Bauer, A. A., unpublished information (1957).

KINETICS OF TRANSFORMATION OF ZIRCONIUM-URANIUM ALLOYS

Arthur A. Bauer

The transformation kinetics of zirconium-uranium alloys have been studied fairly intensively in recent years,⁽¹⁻³⁾ and the transformation behavior has been fairly well defined. Consequently, early studies which provided an indication of alloy-transformation behavior but which were not definitive are not presented here since they have already been reviewed elsewhere.⁽⁴⁾

Modes of Transformation

In alloys containing about 20 to 75 w/o (9 to 54 a/o) uranium, gamma can be retained on quenching.⁽²⁾ Isothermal transformation of the gamma phase to epsilon, a partially ordered phase, occurs by a diffusion-controlled process throughout this range. The initial product of gamma transformation during isothermal transformation in alloys outside the equilibrium epsilon composition range is a supersaturated form of epsilon. Prolonged annealing results in subsequent precipitation of either alpha uranium or alpha zirconium, depending upon composition, and the formation of equilibrium epsilon.

The gamma-to-epsilon transformation is least rapid in alloys of the epsilon-phase composition. The ability to retain gamma becomes more difficult as departures from this composition are made. The gamma phase is only incompletely retained in a water-quenched 22 w/o (10 a/o) uranium alloy, while more complete transformation to epsilon is observed in a water-quenched 20 w/o (9 a/o) uranium alloy.

In alloys containing less than 20 w/o (9 a/o) uranium a martensitic alpha-zirconium phase is formed on quenching from the gamma region.⁽³⁾ The temperature for the start of martensite formation increases with zirconium content.

Above this M_s temperature, the nature of the transformation is susceptible to a variety of interpretations. However, it seems reasonable to assume that the diffusion-controlled transformation of gamma to epsilon, such as occurs in higher uranium alloys, is also operative in the high-zirconium alloys. Such a conclusion is consistent with the available data. Thus, the transformation above the M_s temperature can be described in terms of the diffusion-controlled growth of activated epsilon nuclei, while the transformation to martensite can be described in terms of the strain-activated growth of zirconium nuclei. Both processes result in the formation of supersaturated phases.

An additional transformation is reported in alloys of 8.85 and 11.1 w/o (3.6 and 4.6 a/o) uranium.⁽³⁾ This is the transformation of gamma to a bainitic type of alpha zirconium. The transformation occurs at a temperature just above the M_s in these alloys, indicating the diffusion-controlled growth of alpha-zirconium nuclei in preference to either of the two previous processes.

Upon the basis of this discussion, three areas for consideration are defined: the gamma-to-epsilon transformation in alloys, typified by the 50 w/o (28 a/o) uranium alloy, in which the transformation to epsilon is uncomplicated by precipitation of a second phase; the gamma-to-epsilon transformation in alloys containing 20 to 75 w/o (9 to 54 a/o) uranium and in which the isothermal formation of epsilon is followed by the precipitation of either alpha zirconium or alpha uranium; and the transformation of gamma in alloys containing less than 20 w/o (9 a/o) uranium, in which martensitic alpha zirconium forms on quenching.

Gamma Transformation in the 50 w/o (28 a/o) Uranium Alloy

The gamma-to-epsilon transformation in the 50 w/o (28 a/o) uranium alloy has been studied in detail by hardness, dilatometric, dynamic-modulus, and resistivity measurements as well as by X-ray diffraction and metallographic techniques. The characteristics of the transformation as revealed by these studies are presented below.

Dilatometric and Dynamic-Modulus Measurements

The results of a dilatometric study to determine the kinetics of epsilon formation during isothermal transformation are shown in Figure 8 in the form of a TTT diagram for the 50 w/o (28 a/o) uranium alloy prepared from sponge zirconium.⁽¹⁾ The transformation from gamma to epsilon is accompanied by a volume increase of roughly 1/2 per cent. As a result of the oxygen in the alloy, small amounts of alpha zirconium were stabilized along with the gamma phase and small amounts of alpha uranium precipitated during the isothermal transformation at low temperatures. However, the presence of these phases had no appreciable effect on the transformation to epsilon since the results with sponge-zirconium alloys correlate well with results for iodide-zirconium-base material.

One of the features to be noted concerning this diagram is that two quenching techniques were employed in obtaining the data. Data for isothermal transformation at temperatures at and above the C-curve nose were obtained by interrupted quenching (direct quenching to the temperature of transformation), while data at and below the C-curve nose were obtained by quenching and reheating. Transformation rates above and below the C-curve nose vary significantly with quenching technique; specimens transformed by gamma quenching and then reheating to temperatures above the C-curve nose transform more rapidly than specimens transformed by interrupted quenching to these same temperatures, while at temperatures below the C-curve nose the reverse is observed. Hardness data also reflect the effect of quenching technique on transformation rates.

Dynamic-modulus measurements have been employed to describe the transformation rate of gamma to epsilon on quenching and then reheating. Data for the 50 w/o (28 a/o) uranium alloy prepared from iodide zirconium are shown in Figure 9⁽²⁾. The curves are found to follow the empirical error-function equation on page 19.

FIGURE 8. TIME-TEMPERATURE-TRANSFORMATION DIAGRAM FOR SPONGE-BASE ZIRCONIUM-50 w/o (28 a/o) URANIUM ALLOY(1)

FIGURE 9. PER CENT OF GAMMA TRANSFORMED TO EPSILON AS DETERMINED FROM DYNAMIC MODULUS MEASUREMENTS

$$N = 1/2 \left[1 - \operatorname{erf} 0.118 \left(\frac{31,800}{RT} - \ln \frac{t}{\tau} \right) \right],$$

where

N = per cent transformation

R = universal gas constant

T = temperature, K

$\tau = \exp(-23.64)$, sec

t = time, sec.

It is evident from these data that a single mechanism is operative over the temperature range investigated. The indicated activation energy for the process, 31,800 cal per mole, agrees well with the reported activation energy for diffusion in the gamma phase at this composition⁽⁵⁾, suggesting that the process is diffusion controlled.

Microstructural Changes

The microstructural changes accompanying the transformation of gamma to epsilon have been described as being of two types.⁽¹⁾

The first type is obtained primarily during transformation by interrupted quenching at temperatures above the C-curve nose, although transformation structures characteristic of this type are also obtained on furnace cooling. The microstructural changes involve the activation and growth of discrete epsilon particles, with growth initiating primarily at the gamma grain boundaries but also within the gamma grains. The final microstructure consists of numerous small grains which have a subgrain or domain appearance. These microstructural changes are illustrated⁽¹⁾ in Figures 10a and 10b for a 50 w/o (28 a/o) uranium alloy prepared from sponge zirconium. The structure becomes increasingly fine with decreasing temperature.

Transformation at temperatures at and below the C-curve nose as accomplished by interrupted quenching or by the transformation of quenched-and-reheated samples is characterized by a transformed structure which consists of numerous and minute epsilon particles or domains within the gamma grains; the structure is often unresolvable. With continued annealing the epsilon domains grow until the final structure is similar to that obtained as a direct product of transformation by the previous process. The cellular appearance of the epsilon microstructure is suggestive of domain structure rather than a normal grain structure. Structural changes of this type are shown in Figures 10c and 10d.⁽¹⁾

While the microstructural characteristics of transformation of gamma to epsilon change with the specific transformation temperatures and type of transformation heat treatment, there is no reason to believe that a change in the basic mechanism of transformation is occurring. Rather, a sharp increase in the rate of nucleation or in the

a. 1/2 Min at 580 C

Structure indicates 50 to 70 per cent transformation. Epsilon can be seen in gamma matrix.

b. 2 Min at 580 C

100 per cent transformation indicated in alloy. Domains of epsilon can be seen.

c. 1/2 Min at 560 C

Structure shows 75 to 100 per cent transformation. Fine dispersion of epsilon particles can be seen.

d. 2 Hr at 560 C

100 per cent transformation and domains of epsilon produced by coalescence are illustrated in this structure.

FIGURE 10. STRUCTURES PRODUCED DURING TRANSFORMATION BY INTERRUPTED QUENCHING OF SPONGE-BASE ZIRCONIUM-50 w/o (28 a/o) URANIUM SPECIMENS(1)

number of epsilon sites activated for growth, when temperatures at and below the C-curve nose are reached, is believed to be responsible for the change in transformation behavior. Thus, transformation by interrupted quenching at temperatures above the C-curve nose is accomplished by the activation and growth of a limited number of nuclei. However, at temperatures near the C-curve nose and below, the transformation is accomplished by the growth of a greatly increased number of nuclei with the result that the transformed structure consists of minute epsilon particles or domains. These coalesce slowly with continued time at temperature, the rate of growth and size being temperature dependent.

Hardness Characteristics

The transformation of retained gamma to epsilon is accompanied by an increase in hardness.^(1,2) An increase in hardness is to be expected as a result of the structural change from body-centered-cubic to hexagonal symmetry with the consequent reduction in the number of operative slip systems in the lattice.

During transformation by interrupted quenching at a temperature of 580 C (1075 F) only the hardness increase attributable to the change in crystal structure accompanying transformation is apparent.⁽¹⁾ However, transformation at lower temperatures results in an intermediate peak in hardness. The hardness curves are similar to those exhibited by age-hardening alloys and are shown in Figure 11.⁽¹⁾ It will be noted that the peak hardness increases rapidly with decreasing temperature of transformation. This increase in peak hardness can be related to the changes in microstructure observed as the temperature of transformation is lowered. Thus, only at 580 C (1075 F) does the transformation of gamma result in a relatively coarse-grained epsilon phase (Figure 10b). At lower temperatures the epsilon resulting from transformation consists of minute epsilon particles, their size decreasing and the resultant peak hardness increasing as temperature is lowered. It appears probable that the intermediate hardness peak is primarily a product of the fine epsilon particle size, and that softening accompanies the coalescence of the epsilon particles. While lattice strain resulting from the volume contraction may play a small part in the aging behavior observed, the principal role must be attributed to particle size. No evidence of diffuseness in X-ray patterns which is attributable to strain has been reported.

A marked effect of the technique of transformation heat treatment on the rate of hardness change has also been observed.⁽²⁾ Specimens transformed by gamma quenching and then reheating to temperatures above the C-curve nose transform more rapidly than specimens transformed by interrupted quenching to these same temperatures, while at temperatures below the C-curve nose the reverse effect is observed. Hardness curves illustrating the effect of quenching technique on subsequent hardness changes are shown in Figure 12. Specimens quenched and then transformed by reheating to 200 and 400 C (390 and 750 F) transform more slowly, as indicated by the rate of hardness increase and by the time at which maximum hardness is reached, than do specimens transformed by interrupted quenching. At 500 C (930 F), however, the quenched-and-reheated specimens reach maximum hardness faster than do specimens transformed by interrupted quenching.

FIGURE 11. HARDNESS BEHAVIOR FOR 50 w/o (27.7 a/o) URANIUM ALLOY QUENCHED FROM 700 C (1290 F) DIRECTLY TO INDICATED TEMPERATURES⁽¹⁾

O-25398

FIGURE 12. HARDNESS CHANGES ACCOMPANYING TRANSFORMATION OF ZIRCONIUM-50 w/o (28 a/o) URANIUM ALLOY AT 200, 400, AND 500 C (390, 750, AND 930 F)⁽²⁾

This behavior is not completely understood but coincides with the dilatometric observations made concerning the dependence of transformation rate on heat-treatment technique. Apparently at some temperature between 400 and 500 C (750 and 930 F) the rate at which nuclei are activated for subsequent growth is a maximum. During transformation by interrupted quenching, passage through this region is slow, compared with that for specimens water quenched to room temperature. Consequently, the greater number of nuclei activated during this passage results in a more rapid transformation than is obtained for specimens initially quenched to room temperature. However, for specimens transformed at 500 C (750 F) and above it is the passage through this same region on reheating after quenching which accelerates the transformation.

X-Ray Diffraction Characteristics

The transformation from gamma to epsilon results in the formation of a partially ordered structure with hexagonal symmetry. The diffraction lines common to both the gamma and epsilon phase remain essentially constant in intensity although they show a slight shift in position due to the transformation. The additional lines associated with the hexagonal symmetry of the partially ordered epsilon phase appear early in the transformation, these reflections increasing in intensity as transformation proceeds. However, their intensity is dependent upon the degree of order exhibited by the epsilon structure. As such, the hexagonal lines can be considered as superlattice lines resulting from ordering of the gamma phase.

The exact sequence of structural changes during transformation is unknown. Thus, the transformation could involve ordering of the cubic gamma phase followed by a cooperative shift of atoms in the (111) direction to yield hexagonal symmetry, the shift occurring to accommodate lattice strains resulting from ordering. It is also possible that the cubic-to-hexagonal structural change precedes the ordering reaction or even that the ordering reaction is a continuous process. However, whichever occurs, it seems clear that it is the diffusion of atoms to preferred lattice positions which is rate controlling. Since only short diffusion distances are involved, the transformation proceeds fairly rapidly.

Change in line width and corresponding particle size as a function of time and temperature of transformation is shown in Figure 13 for a 50 w/o (28 a/o) alloy prepared from sponge zirconium.⁽¹⁾ The changes shown are for the hexagonal (111) reflection. One of the features of this plot is the continued decrease in line width after the completion of transformation as indicated by other measurements. It is believed that this continued growth represents coalescence of epsilon particles or domains, the coalescence also being reflected in the hardness decreases shown.

The characterization of the epsilon particles as domains arises from the observation that the gamma lines exhibit essentially no change in breadth⁽²⁾, only the hexagonal lines assignable to the ordering process show evidence of particle growth. Thus domain growth or growth of ordered particles rather than the growth of particles of a discrete new phase occurs.

FIGURE 13. WIDTH OF SUPERLATTICE LINE FOR REHEATED SAMPLES OF 50 w/o (28 a/o) URANIUM ALLOY⁽¹⁾

Additional evidence of the domain character of epsilon particles in the 50 w/o (28 a/o) uranium alloy is reported. Examination of a single grain within a sample of the alloy revealed that the epsilon domains exhibited the identical cubic orientation of the gamma grain in which they formed.⁽⁶⁾

The nucleation and diffusion-controlled nature of the gamma-to-epsilon transformation is illustrated by intensity and line-breadth measurements obtained at 200 and 300 C (390 and 570 F) for quenched-and-reheated specimens.⁽²⁾ At both temperatures nucleation was found to occur quite rapidly as evidenced by the appearance within 5 sec of a diffuse tail to the (220) gamma reflection which was identifiable with increased time as the (301) hexagonal reflection. Changes in breadth and intensity of the (301) reflection indicated increased growth of the epsilon-phase particles with time. After 500 sec at 200 C (390 F) it was estimated that the epsilon particles had grown to 30 Å and after 10,000 sec to about 100 Å. At 300 C (570 F), less than 30 sec was required for the epsilon particle size to exceed 100 Å.

Electrical Characteristics

The gamma-to-epsilon transformation is accompanied by a sharp increase in electrical resistivity, as shown in Figure 14 where the resistivities of the retained-gamma and epsilon phases are plotted versus temperature. The increase in resistance of the retained-gamma phase above 75 C (170 F) is a result of the initiation of transformation. As a result of heating to 150 C (300 F), the electrical resistivity as measured after subsequently cooling to 50 C (120 F) was found to have increased by 5 per cent.⁽²⁾

Hall-coefficient measurements are also reported⁽²⁾; these are given in Table 1 and Figure 15. These measurements serve to provide some additional insight into the nature of the gamma-to-epsilon transformation. The sharp increase in resistivity is not consistent with the description of the transformation as an ordering reaction since ordering is normally accompanied by a decrease in resistivity, at least when no structural change is involved, as a result of increased mobility of current carriers in the periodic field of an ordered crystal lattice. Similarly, a negative temperature coefficient of resistivity is not normally exhibited by a stable phase. Decreasing temperature and attendant decreased lattice vibration result in increased current-carrier mobility which should lead to decreased electrical resistance.

TABLE 1. HALL-COEFFICIENT AND ELECTRICAL-RESISTIVITY VALUES FOR ZIRCONIUM-50 w/o (28 a/o) URANIUM ALLOY

Heat Treatment	Hall Coefficient, R_H , cm ³ per coulomb	Resistivity, μohm-cm
1/2 hr at 700 C and W.Q.	5.5×10^{-5}	141
1/2 hr at 700 C and W.Q. plus 6 hr at 100 C	6.5×10^{-5}	144

FIGURE 14. RESISTIVITY OF RETAINED GAMMA AND EPSILON AS A FUNCTION OF TEMPERATURE⁽²⁾

FIGURE 15. VARIATION IN HALL COEFFICIENT AND RESISTIVITY AS A FUNCTION OF TEMPERATURE IN THE ZIRCONIUM-50 w/o (28 a/o) URANIUM EPSILON-PHASE ALLOY(2)

The Hall coefficients are interpreted as providing a measure of current-carrier concentration, the coefficient being inversely proportional to this concentration. The conclusion drawn from these measurements is that the current-carrier concentration is decreasing at a higher rate than the resistivity is increasing as a result of both the transformation and the decreasing temperature of the epsilon phase. Consequently, increased current-carrier mobility as a result of the gamma-to-epsilon transformation and also increased mobility with decreasing temperature of the epsilon phase are indicated.

Gamma Transformation in 20 to 75 w/o (9 to 54 a/o) Uranium Alloys

The gamma-to-epsilon transformation in alloys outside the range in which equilibrium epsilon forms has been studied by hardness, metallographic, and X-ray diffraction methods.⁽²⁾ The data indicate a similarity in the nature of the transformation throughout this range, although an increase in the rate of transformation as departures from the epsilon-phase composition are made is indicated, particularly with increasing zirconium content.

X-Ray Diffraction Characteristics

Transformation of gamma to the equilibrium phases present at lower temperatures is preceded by the formation of an epsilon structure which is supersaturated in either zirconium or uranium, depending on composition.⁽²⁾ With continued annealing, alpha uranium or alpha zirconium precipitates from the nonequilibrium epsilon phase. The gradual shift of lattice spacings for the hexagonal (301) and (111), and cubic (220) reflections, respectively, as equilibrium epsilon forms are shown in Figure 16. Only the (220) reflection (1.26-A spacing) is common to both the retained-gamma and epsilon phases.

Retention of gamma is incomplete on water quenching the 22 w/o (10 a/o) uranium alloy, as evidenced by very weak and diffuse epsilon reflections. Hardness variations with composition of gamma-quenched zirconium-uranium alloys also reflect increased instability of the gamma phase, as well as supersaturation hardening, as departures from the epsilon composition are made. The higher hardness of water-quenched alloys on either side of the epsilon phase is shown in Figure 17.

Gamma-quenched 22 and 70 w/o (10 and 47 a/o) uranium specimens also were found to exhibit evidence of strain in the cubic (110) reflection. This was apparently associated with nucleation of the alpha phases and preceded actual precipitation, which occurred between 10 and 100 sec at 575 C (1070 F).

FIGURE 16. SHIFT OF EPSILON-PHASE INTERPLANAR SPACINGS DURING ISOTHERMAL TRANSFORMATION AT 575 C (1070 F)⁽²⁾

FIGURE 17. HARDNESS OF WATER-QUENCHED ZIRCONIUM-URANIUM ALLOYS(2)

Hardness Characteristics

Hardness changes during gamma transformation illustrate the similarity in the nature of transformation through the 22 to 70 w/o (10 to 47 a/o) uranium-alloy range while also serving to emphasize some of the differences. As with the 50 w/o (28 a/o) uranium alloy, hardness curves obtained are dependent upon the heat-treating techniques.⁽²⁾

Interrupted quenching results in similar hardening curves for alloys containing 40 to 60 w/o (20 to 36.5 a/o) uranium, although there is some variation in the reference gamma-quenched hardness. However, the 22, 30, and 70 w/o (10, 14, and 47 a/o) uranium alloys exhibit notably different hardness curves. Hardness changes accompanying transformation of the 22 and 70 w/o (10 and 47 a/o) alloys are shown in Figure 18. The 30 w/o (14 a/o) uranium alloy exhibits behavior similar to that of the 22 w/o (10 a/o) alloy.

The 70 w/o (47 a/o) uranium alloy experiences two aging peaks. The first aging peak, which is similar to that observed for the 50 w/o (28 a/o) uranium alloy, results from the gamma-to-epsilon transformation. The second peak is occasioned by precipitation of alpha uranium from the supersaturated epsilon phase produced initially.

The 22 w/o (10 a/o) uranium alloy, on the other hand, shows maximum hardness on quenching as a result of the initiation of the gamma-to-epsilon transformation. Subsequent precipitation of alpha zirconium may account for minor hardness increases noted but it is not associated with any marked aging peak such as is observed for the 70 w/o (47 a/o) alloy.

Hardness changes accompanying transformation of specimens reheated after gamma quenching are shown in Figure 19. The 30 w/o (14 a/o) uranium alloy when heat treated in this manner exhibited the same type of hardness changes as the 40 w/o (20 a/o) alloy, which are similar to those for alloys containing 45, 50, 55, and 60 w/o (24, 28, 32, and 36.5 a/o) uranium.

The 22 w/o (10 a/o) alloy when transformed at 450 C (840 F) exhibited a slight aging peak, indicating that maximum hardness had not been obtained on quenching, although at the higher temperatures only overaging is observed. This illustrates the similarity in behavior of the 22 w/o (10 a/o) alloy to that of the higher uranium alloys, the principal difference being in the rate at which transformation occurs; normally only overaging is observed. The hardness plateau shown on aging of this alloy is believed to be caused by lattice strain associated with preprecipitation of the alpha-zirconium phase.

The 70 w/o (47 a/o) uranium alloy behaves in a similar manner to that shown for the 40 w/o (20 a/o) uranium alloy, with the exception of the second aging peak which is associated with the precipitation of alpha uranium. The aging peak occurs earlier at 500 C (930 F) during the interrupted-quenching transformation treatment (Figure 18) than during transformation of quenched-and-reheated specimens (Figure 19). Metallographic examination substantiated the fact that alpha rejection occurs more slowly in specimens subjected to the latter treatment. Apparently nucleation of the alpha phase is initiated during the initial quench through the alpha uranium-plus-gamma region. The quenching rate during interrupted quenching is lower than for a direct water quench; consequently, alpha uranium precipitates more rapidly in the specimens transformed

FIGURE 18. HARDNESS CHANGES IN ZIRCONIUM-22 AND -70 w/o (10 AND 47 a/o) URANIUM ALLOYS(2) ACCOMPANYING TRANSFORMATION AT 500 C (930 F) BY INTERRUPTED QUENCHING

FIGURE 19. HARDNESS CHANGES ACCOMPANYING TRANSFORMATION OF WATER-QUENCHED ZIRCONIUM-22, -40, AND -70 (10, 20, AND 47 a/o) URANIUM ALLOYS⁽¹⁾

by interrupted-quenching techniques. The same dependence on method of transformation heat treatment for the rejection of alpha zirconium in high-zirconium alloys is observed.

Microstructural Characteristics

In the range from 22 to 70 w/o (10 to 47 a/o) uranium all alloys exhibit large-grained gamma structures when water quenched.⁽²⁾ The transformed epsilon structure produced by heat treatment at 500 C (930 F) or above consists of epsilon domains within the prior gamma grains. The domain character of the epsilon particles is illustrated by the photomicrographs in Figure 20. The epsilon phase polarizes markedly in the 22 w/o (10 a/o) uranium alloy, with whole blocks of domains within a single gamma grain exhibiting the same orientation and response to polarized light. When gamma quenched, no evidence of polarization was observed in the 22 w/o (10 a/o) alloy despite the detection of partial epsilon formation by X-ray diffraction examination.⁽²⁾

Evidence of domain growth is shown in the structures appearing in Figures 20a and 20b. Between 10 and 1000 sec at 500 C (930 F) an increase in diameter of approximately three times occurred.

The microstructure of the 22 w/o (10 a/o) alloy is similar to that exhibited by the 50 w/o (28 a/o) uranium alloy. However, growth of the epsilon particles is much more rapid in the 22 w/o (10 a/o) alloy.

The structural changes accompanying transformation of the 70 w/o (47 a/o) alloy are similar to those exhibited by the 22 and 50 w/o (10 and 28 a/o) alloys. Figure 20c shows epsilon domains, outlined by precipitated uranium, within prior gamma grains of the 70 w/o (47 a/o) uranium alloy. As with the 50 w/o (28 a/o) alloy, domain growth occurs more slowly than in the 22 w/o (10 a/o) uranium alloy.

Precipitation of the respective alpha phases from supersaturated epsilon occurs fairly slowly, the time required for observable precipitation to occur increasing with decreasing temperature and with decreasing supersaturation of the epsilon phase. Alpha-uranium precipitation from epsilon supersaturated in uranium appears to occur more rapidly than does zirconium precipitation for an alloy of equivalent supersaturation.

In quenched and reheated alloys no evidence of precipitation of the alpha phases was observed in specimens held for periods of up to 100,000 sec at 450 C (840 F). In the 70 w/o (47 a/o) uranium alloy alpha uranium precipitated after 10,000 sec at 500 C (930 F) while 100,000 sec was required before alpha zirconium was observed in 22 and 30 w/o (10 and 14 a/o) alloys. At 550 C (1020 F), these times reduced to 1,000 and 10,000 sec for the 70 w/o (47 a/o) and 22 and 30 w/o (10 and 14 a/o) alloys, respectively. For the 40 and 60 w/o (20 and 36.5 a/o) uranium alloys, 100,000 sec at 600 C is required before noticeable amounts of the alpha phases appear.

1000X Polarized Light RM4129

1000X Bright Field RM4130

a. Zirconium-22 w/o (10 a/o) Uranium Held 1/2 Hr at 900 C,
10 Sec at 500 C, and Water Quenched

1000X Polarized Light RM4131

1000X Bright Field RM4133

b. Zirconium-22 w/o (10 a/o) Uranium Held 1/2 Hr at 900 C,
1000 Sec at 500 C, and Water Quenched

1000X Bright Field RM5761

c. Zirconium-70 w/o (47 a/o) Uranium Held 1 Hr at 800 C,
1000 Sec at 500 C, and Water Quenched

FIGURE 20. MICROSTRUCTURES OF ZIRCONIUM-URANIUM ALLOYS TRANSFORMED BY INTERRUPTED QUENCHING

Gamma Transformation in 0 to 20 w/o
(9 a/o) Uranium Alloys

Alloys containing less than 20 w/o (9 a/o) uranium exhibit two types of structures not observed in higher uranium alloys: the martensitic strained alpha-zirconium structure and a bainitic-type of alpha structure. The martensitic alpha structure is obtained by gamma quenching alloys containing less than 20 w/o (9 a/o) uranium while the bainitic structure is reported to form isothermally in alloys containing 8.85 and 11.1 w/o (3.6 and 4.6 a/o) uranium.⁽⁴⁾

In addition to formation of martensitic and bainitic alpha, epsilon and supersaturated epsilon also form in these alloys. Based on studies of alloys containing 20 w/o (9 a/o) uranium or less, it was not possible to clearly determine the exact mechanism of epsilon formation. It was concluded that equilibrium epsilon formed isothermally but that supersaturated epsilon either nucleated very rapidly under isothermal conditions or else nucleated athermally.⁽⁴⁾

However, considering the system as a whole, the conclusion is reached that supersaturated epsilon forms isothermally in these alloys as it does in the higher uranium alloys, although the transformation is very rapid. No conflict with available experimental data results from this conclusion.

Figure 21 contains schematic time-temperature-transformation diagrams which illustrate the nature of the transformations in alloys containing 20 w/o (9 a/o) uranium and less. The detailed sequence of the transformations is unknown and is therefore not shown.

The gamma-to-epsilon transformation in all of these alloys can be expressed in terms of a C-curve as with the 50 w/o (28 a/o) alloy. However, the times involved for the transformation are much shorter, with the result that in the 20 and 22 w/o (9 and 10 a/o) uranium alloy partial transformation of gamma to supersaturated epsilon occurs on quenching. The same is true of the 14.3 w/o (6 a/o) uranium alloy although the remaining gamma, which does not transform to epsilon, transforms to martensitic alpha zirconium during the quench to room temperature.

The temperature for the start of martensitic transformation, the M_s temperature, decreases from 430 C (810 F) for an 8.85 w/o (3.6 a/o) uranium alloy to 370 C (700 F) for a 11.1 w/o (4.6 a/o) uranium alloy and to 325 C (620 F) for a 14.3 w/o (6 a/o) alloy.⁽⁴⁾ The nose of the curve for the precipitation of alpha zirconium from gamma decreases from about 700 C (1290 F) at 8.85 w/o (3.6 a/o) uranium to 620 C (1150 F) at 20.7 w/o (9 a/o) uranium. Times for the initiation of alpha precipitation at the nose of the curve increased from 10 to about 60 sec, respectively, at these compositions. The formation of bainitic alpha was observed in 8.85 and 11.1 w/o (3.6 and 4.6 a/o) uranium alloys at temperatures below 550 C (1020 F), the C-curve nose for the start of this transformation being indicated as occurring at about 500 and 430 C (1020 and 810 F), respectively. The transformation is initiated in about 20 sec at these temperatures.

FIGURE 21. SCHEMATIC T-T-T DIAGRAMS ILLUSTRATING TRANSFORMATIONS IN ZIRCONIUM ALLOYS CONTAINING 20 w/o (9 a/o) OR LESS URANIUM

Figure 22 illustrates the martensitic and bainitic microstructures obtained in high-uranium alloys. Figure 22a shows martensitic needles in a 11.1 w/o (4.6 a/o) uranium alloy. Figure 22b illustrates the bainitic alpha phase, which is lenticular in form, and which contains an angular precipitate of epsilon within the alpha lenses.

While the martensitic alpha formed on gamma quenching zirconium-uranium alloys is a supersaturated form of alpha zirconium which is strained, as indicated by the diffuseness and line broadening of X-ray diffraction patterns, the alpha does not exhibit a high hardness. This lack of hardening is attributed to a lack of coherency between the martensitic alpha and parent gamma phase.

The nature of the transformation products obtained in zirconium alloys containing less than 20 w/o (9 a/o) uranium can be extremely variable. Alpha zirconium, which is acicular in nature, is nucleated and grows rapidly in the alpha-plus-gamma phase region. If quenching conditions are not ideal, resultant gamma, enriched in uranium, will be responsible for the formation of epsilon in conjunction with acicular alpha zirconium in place of martensitic alpha zirconium. Similarly, different oxygen contents can be responsible for producing different results in the same alloy subjected to the same treatment. The effect of oxygen is to extend the alpha zirconium-plus-gamma region both with respect to composition and temperature. Consequently, the uranium content of the gamma phase may vary widely in the presence of oxygen-stabilized alpha zirconium. The effect of prior existing alpha zirconium is to increase the rate of additional acicular-alpha precipitation on cooling and to prevent the formation of martensitic alpha zirconium.⁽⁷⁾

Discussion

The gamma phase can be completely or partially retained by water quenching in alloys containing about 20 to 75 w/o (9 to 54 a/o) uranium. The retained-gamma phase transforms isothermally to epsilon, the intermediate phase in the zirconium-uranium system. In alloys outside the equilibrium epsilon composition range the epsilon formed is initially supersaturated. Alpha uranium or alpha zirconium, depending on composition, precipitates from the supersaturated epsilon phase. Both the gamma-to-epsilon transformation and the alpha-phase precipitation are diffusion-controlled processes.

The time for the start of gamma transformation decreases as departures from the epsilon composition are made. The time-temperature-transformation relationships for the gamma-to-epsilon transformation in the 50 w/o (28 a/o) uranium alloy can be presented in the form of a C-curve, as determined by dilatometric measurements, and in the form of an empirical equation, as derived from dynamic-modulus measurements.

Except for transformation at temperatures just below the gamma-epsilon equilibrium temperatures, i.e., 580 C (1075 F) and above, where the number of nuclei which are activated for growth is small, the gamma-to-epsilon transformation is accompanied by a marked hardness increase and an aging peak. The hardness increase is associated with the beginning of transformation, and peak hardness with essentially complete transformation. The hardness increase is attributed to the small size of epsilon particles or domains. Overaging is attributed to coalescence of the epsilon domains.

500X

N27140

a. 11.1 w/o (4.6 a/o) Uranium Alloy Water Quenched From 1000 C

Martensitic alpha needles are visible.

1000X

N31201

b. 8.85 w/o (3.6 a/o) Uranium Alloy Transformed 62,000 Min at 450 C

Bainitic alpha (lenticular phase) plus epsilon (angular precipitate) can be seen.

FIGURE 22. MICROSTRUCTURES OF TRANSFORMED ALLOYS CONTAINING LESS THAN 20 w/o (9 a/o) URANIUM

The gamma-to-epsilon transformation can be interpreted as being an ordering transformation. X-ray diffraction observations are consistent with this interpretation and the kinetics of the transformation are apparently controlled by the rate at which atoms assume preferred positions to achieve a partially ordered lattice. The nucleation and diffusion-controlled growth nature of the transformation is also illustrated by X-ray diffraction observations.

The transformation is accompanied by a sharp increase in resistivity of the 50 w/o (28 a/o) uranium alloy. Based on measurements of Hall coefficients, a decrease in the number of available current carriers is responsible for the increased resistivity.

Hardness changes during transformation of alloys containing 22 to 70 w/o (10 to 47 a/o) uranium are similar. However, due to partial decomposition of gamma in the 22 w/o (10 a/o) uranium alloy on quenching, peak or close to peak hardness is observed in quenched specimens. The 70 w/o (47 a/o) uranium alloy exhibits two hardness peaks during aging; the first is associated with gamma-to-epsilon transformation and the second with precipitation of alpha uranium. No aging peak associated with alpha-zirconium precipitation is observed in high-zirconium alloys.

The rejection of alpha uranium and alpha zirconium from the supersaturated epsilon phase is accompanied by a gradual shift in lattice spacing of the epsilon phase in the 22 and 70 w/o (10 and 47 a/o) uranium alloys, as the lattice spacings of these alloys approach those of the 50 w/o (28 a/o) uranium alloy.

In alloys containing less than 20 w/o (9 a/o) uranium, gamma transforms martensitically on quenching to yield a strained alpha-zirconium lattice. At temperatures above the M_s temperature, the isothermal transformation of gamma to epsilon proceeds as in higher uranium alloys; the transformation proceeds extremely rapidly, however, and some epsilon (supersaturated) is usually found in conjunction with martensitic alpha in quenched alloys. An additional diffusion-controlled transformation of gamma to a bainitic form of alpha zirconium has been observed in alloys of 8.85 and 11.1 w/o (3.6 and 4.6 a/o) uranium.

References

- (1) Kearns, J. J., "The Transformation Kinetics of Uranium-Zirconium Alloys Containing 50 and 60 w/o Uranium", WAPD-T-417 (November 21, 1956). Submitted for publication to AIME.
- (2) Bauer, A. A., "The Gamma-to-Epsilon Transformation in Zirconium 20 to 70 w/o Uranium Alloys", Submitted for publication to AIME (1959).
- (3) Douglass, D. L., Marsh, L. L., Jr., and Manning, G. K., "Transformation Kinetics of Zirconium-Uranium Alloys", Trans. ASM, 50, 305 (1958).
- (4) Rough, F. A., "An Evaluation of Data on Zirconium-Uranium Alloys", BMI-1030 (August 15, 1955).

- (5) Adda, V., and Philibert, J., "Study of Uranium-Zirconium Gamma-Phase Diffusion", Compt. Rend., 242, 3081 (1956).
- (6) Holden, A. N., and Seymour, W. E., "Intermediate Phase in the Uranium-Zirconium System", Trans. AIME, 206, 1312 (1956).
- (7) Douglass, D. L., and Marsh, L. L., BMI, private communication (1958).

to
be

THE EFFECTS OF HEAT TREATMENT ON THE MICROSTRUCTURE OF ZIRCONIUM-URANIUM ALLOYS

Walston Chubb

The zirconium-uranium system is characterized by complete solubility of these elements in one another in a body-centered-cubic solid solution at temperatures above 865 C (1590 F). Below 865 C the mutual solubility of zirconium and uranium decreases until at about 600 C (1110 F) zirconium and uranium are virtually insoluble in one another. Any residual terminal solubility of these elements in one another below 600 C is so small as to be unimportant. Such a change in solubility can be expected to result in a host of microstructural and heat-treatment effects. The change in solubility is accompanied by the formation of an intermediate phase, epsilon, which has many metallic properties, and by the transformation of a body-centered structure into hexagonal alpha zirconium and orthorhombic alpha uranium. The formation of the epsilon phase has evoked considerable interest, partly because of its metallic properties and partly because it forms below 600 C at a convenient rate of speed. This phase forms with an accompanying hardening reaction which is suggestive of coherent nucleation, but the resultant structure is equiaxed so that oriented crystal growth need not be postulated. On the other hand, alpha zirconium and alpha uranium both form from gamma solid solution by mechanisms involving crystallographic relations between the high-temperature phase and the low-temperature phases. These crystallographic orientation relationships between the phases result in acicular microstructures, which are called martensitic, acicular, Widmanstätten, or rhomboidal according to the heat treatment.

The gamma phase can be retained as a metastable phase by quenching zirconium-uranium alloys containing between 20 and 75 w/o (9 to 54 a/o) uranium.⁽¹⁻⁵⁾ When retained gamma is aged, it undergoes an extremely severe hardening and embrittling reaction just prior to the precipitation of the low-temperature epsilon phase. Alloys near 20 w/o (9 a/o) or near 75 w/o (54 a/o) uranium are invariably brittle in the quenched condition because of changes in the gamma solid solution during quenching. The quenched structure is body-centered cubic, however. Soft gamma solid solution is readily obtained by quenching zirconium-uranium alloys containing between 40 and 65 w/o (20 and 41 a/o) uranium.

The gamma phase cannot be retained as a metastable phase by quenching zirconium-uranium alloys containing 0 to 20 w/o (0 to 9 a/o) or 75 to 100 w/o (54 to 100 a/o) uranium.^(2,4-7) Alloys in these composition ranges transform at the highest quenching rates by a martensitic mode, and the transformation to martensite is usually complete at room temperature. Exceptions to this rule occur if an isothermal product is formed by slack quenching or if the composition approaches 20 or 75 w/o (9 to 54 a/o) uranium.

The intermediate epsilon phase exists below 600 C (1110 F) at equilibrium within the limits of about 45 to 55 w/o (24 to 32 a/o) uranium.^(2, 3, 4, 5, 8, 9) Under nonequilibrium conditions, this phase is readily observed below 600 C and above the martensite-formation temperatures in alloys ranging from 10 w/o (4 a/o) uranium to at

least 75 w/o (54 a/o) uranium. It appears that within the above composition and temperature limits a nonequilibrium epsilon phase forms by a nucleation-and-growth process from gamma solid solution. It requires times of the order of 1 to 10 sec to complete the transformation of gamma into nonequilibrium epsilon at about 500 C (930 F). It must be possible to describe the formation of this phase by ordinary C-curves, and attempts to do this are described in the section of this report on kinetics. Additional time at 500 C causes alpha zirconium or alpha uranium to precipitate from nonequilibrium epsilon and with the passage of time the epsilon phase approaches its equilibrium composition limits.

Alloys Containing 1 to 20 w/o (0.4 to 9 a/o) Uranium

Figure 23 shows a typical zirconium martensite as found in a water-quenched sample of zirconium-10 w/o (4 a/o) uranium alloy. Typically this structure occurs only in the zirconium alloys that have received the most drastic quench. If the history of the sample is not known, martensite is very difficult to distinguish from acicular alpha zirconium. Martensite is usually found in large feathery masses which often extend across the entire width of a beta grain, whereas acicular alpha tends to appear as very fine needles.

Figure 24 shows a zirconium-15 w/o (6.3 a/o) uranium alloy that has been isothermally transformed below 600 C (1110 F) but above 300 C (570 F), the approximate temperature for martensite formation in this alloy. The photomicrograph shows that gamma has decomposed into nonequilibrium epsilon and that acicular alpha zirconium has begun to precipitate.

Figure 25 shows a more completely transformed zirconium-15 w/o (6.3 a/o) uranium alloy. This photomicrograph shows additional acicular alpha zirconium plus some residual nonequilibrium epsilon.

Figure 26 shows a typical acicular alpha-zirconium structure as found in air-cooled zirconium-10 w/o (4 a/o) uranium alloy. This structure consists of needles of alpha zirconium in a matrix of fine particles of epsilon. Presumably this epsilon is near its equilibrium composition of 50 w/o (28 a/o) uranium. At 250 diameters it is not possible to say that a particular area is epsilon, but the dark-etching behavior of the sample indicates its presence as finely divided particles or a fine network.

Figure 27 is the most common and one of the more desirable structures found in zirconium-uranium alloys containing less than 20 w/o (9 a/o) or even 40 w/o (20 a/o) uranium. When gamma phase is cooled slowly through the alpha zirconium-plus-gamma region, acicular alpha zirconium forms at a few centers and grows into rhomboidal particles as shown in Figure 27. When the residual gamma solid solution reaches the eutectoid at 600 C (1110 F), it transforms to equilibrium epsilon with very little precipitation of alpha zirconium. The resultant mixture of soft, ductile alpha zirconium and soft, slightly ductile epsilon usually represents the state of maximum ductility and minimum hardness for alloys in this composition range. Slow cooling from 700 to 600 C (1290 to 1110 F) is particularly important for maximum ductility in these alloys.

500X

N31469

FIGURE 23. TYPICAL MARTENSITIC STRUCTURE OBTAINED IN IODIDE ZIRCONIUM-10 w/o (4 a/o) URANIUM BY WATER QUENCHING FROM 900 C (1650 F)

Hardness: 250 DPH.

1000X

N31209

FIGURE 24. ISOTHERMALLY TRANSFORMED IODIDE ZIRCONIUM-15 w/o (6.3 a/o) URANIUM EXHIBITING NONEQUILIBRIUM EPSILON AND ACICULAR ALPHA ZIRCONIUM

Alpha formation is evident, particularly at the old grain boundaries. Heat treatment involved 1 hr at 900 C (1650 F) followed by 5 hr at 450 C (840 F) and water quenching. Hardness: 326 DPH.

1000X

N31210

FIGURE 25. IODIDE ZIRCONIUM-15 w/o (6.3 a/o) URANIUM EXHIBITING EXTENSIVE TRANSFORMATION AFTER 24-HR ISOTHERMAL HEAT TREATMENT

Structure shows nonequilibrium epsilon and acicular alpha zirconium within old gamma grain boundaries. Alloy was heated 1 hr at 900 C (1650 F) and isothermally transformed 24 hr at 450 C (840 F) and water quenched. Hardness: 313 DPH.

250X

N31472

FIGURE 26. TYPICAL ACICULAR ALPHA-ZIRCONIUM STRUCTURE IN IODIDE ZIRCONIUM-10 w/o (4 a/o) URANIUM ALLOY AIR COOLED FROM 900 C (1650 F)

Alpha zirconium dominates this structure in the form of acicular alpha. Epsilon is apparent only as a darkening of the structure. Hardness: 220 DPH.

Figure 28 shows a typical structure of a zirconium-19 w/o (8.3 a/o) uranium alloy as cold rolled and annealed at temperatures below 600 C (1110 F). Recrystallization occurs below 600 C, but grain growth is slow so that cold- or warm-rolled and recrystallized structures tend to be fine grained and show preferred orientation. For almost all applications it is desirable to remove such preferred orientations by heating for a short time in the gamma solid-solution range.

Alloys Containing 20 to 75 w/o (9 to 54 a/o) Uranium

Alloys containing more than 20 w/o (9 a/o) and less than 75 w/o (54 a/o) uranium are unique among zirconium-uranium alloys in that they do not transform to martensite when quenched to room temperature at the most rapid rates available. The structure of water-quenched alloys in this composition range is that of the gamma solid solution. Figure 29 is a photomicrograph of this structure in a sample of zirconium-60 w/o (36.5 a/o) uranium alloy. This structure is rather difficult to prepare metallographically because of its softness (220 DPH) and its tendency to smear. However, as indicated earlier, this structure is not necessarily soft. As a result of aging during or after quenching the hardness of retained-gamma solid solution may rise as high as 450 DPH, or even higher in uranium-rich alloys.

In the composition range 20 to 75 w/o (9 to 54 a/o) uranium, the first constituent to precipitate from the gamma solid solution at temperatures below 600 C (1110 F) is nonequilibrium epsilon. Figure 30 shows photomicrographs obtained at intervals along an end-quenched bar of zirconium-20 w/o (9 a/o) uranium alloy. These photomicrographs suggest that the nonequilibrium epsilon phase forms by a process of nucleation and growth, and they show that the formation of nonequilibrium epsilon is practically complete before any acicular alpha zirconium begins to precipitate under these conditions.

The nucleation of alpha zirconium in alloys containing 20 to 50 w/o (9 to 28 a/o) uranium results in acicular structures similar to those found in alloys containing 1 to 20 w/o (0.4 to 9 a/o) uranium. Figure 31 shows the process of precipitation of alpha zirconium and nonequilibrium epsilon in isothermally transformed samples of zirconium-20 w/o (9 a/o) uranium alloy. A similarity between Figure 31b and Figure 24 is apparent.

When a zirconium-22 w/o (10 a/o) uranium alloy is brought to equilibrium at about 600 C (1110 F), the resultant structure will contain about 50 per cent alpha zirconium. Manipulations with this ratio of phases in the product are particularly instructive, and some of the possibilities for phase redistribution are shown in Figure 32. The structure shown in Figure 32a is directly comparable with that shown in Figure 27 and is quite common and easy to produce. In this photomicrograph, epsilon forms a matrix for rhomboidal alpha zirconium, but it would be difficult to say which phase more completely surrounds the other. Figure 32b shows what happens when the alloy is held in the high alpha zirconium-plus-gamma region for 5 hr and furnace cooled. The large

FIGURE 27. WIDMANSTÄTTEN STRUCTURE IN IODIDE ZIRCONIUM-19 w/o (8.3 a/o) URANIUM PRODUCED BY FURNACE COOLING FROM 800 C (1560 F)

Rhomboidal particles of alpha zirconium are surrounded by epsilon.
Hardness: 210 DPH.

FIGURE 28. TYPICAL STRUCTURE OF ALPHA ZIRCONIUM AND EPSILON IN IODIDE ZIRCONIUM-19 w/o (8.3 a/o) URANIUM ALLOY COLD ROLLED AND ANNEALED FOR 20 HR AT 570 C (1060 F)

Hardness: 250 DPH.

FIGURE 29. RETAINED METASTABLE GAMMA SOLID SOLUTION IN IODIDE ZIRCONIUM-60 w/o (36.5 a/o) URANIUM ALLOY WATER QUENCHED FROM 900 C (1650 F)

This structure is obtained in alloys containing between 20 and 75 w/o (9 and 54 a/o) uranium when rapidly quenched to room temperature. Hardness: 220 DPH.

500X

N31474

a. Structure Found 0.020 In. From the End

Particles of nonequilibrium epsilon are evident in the gamma solid solution. Hardness: 410 DPH.

500X

N31475

b. Structure Found 0.050 In. From the End

The microstructure shows particles of nonequilibrium epsilon in a gamma solid solution. Hardness: 350 DPH.

500X

N31478

c. Structure Found 1.0 In. From the End

A few particles of acicular alpha zirconium can be seen in the nonequilibrium epsilon. Hardness: 290 DPH.

FIGURE 30. PHOTOMICROGRAPHS OBTAINED AT INTERVALS ALONG AN END-QUENCHED BAR OF ZIRCONIUM-20 w/o (9 a/o) URANIUM ALLOY

Formation of epsilon by nucleation-and-growth process can be seen in the photomicrographs. Bar was quenched from 900 C (1650 F).

1000X

N30779

a. Nonequilibrium Epsilon Plus Acicular Alpha Zirconium

Sample was heated 1 hr at 900 C (1650 F) and isothermally transformed for 5 min at 500 C (930 F) and water quenched. Hardness: 265 DPH.

1000X

N30212

b. Nonequilibrium Epsilon Plus Increased Acicular Alpha Zirconium

The time at 500 C was extended to 140 min. Hardness: 264 DPH.

FIGURE 31. PROCESS OF PRECIPITATION OF ALPHA ZIRCONIUM AND NONEQUILIBRIUM EPSILON IN ISOTHERMALLY TRANSFORMED SAMPLES OF ZIRCONIUM-20 w/o (9 a/o) URANIUM ALLOY

500X

N18199

- a. Structure of Rhomboidal Alpha Zirconium in Epsilon Produced by Furnace Cooling From 900 C (1650 F)

Hardness: 230 DPH.

250X

N17478

- b. Globular and Rhomboidal Alpha Zirconium in Epsilon Matrix Formed by Homogenizing 36 Hr at 850 C (1545 F), Water Quenching, Reheating for 5 Hr at 760 C (1400 F), and Furnace Cooling

Hardness: 230 DPH.

500X

RM4405

- c. Grain-Boundary Network of Alpha Zirconium Surrounding Retained Gamma in Sample Annealed 1/2 Hr at 775 C (1430 F), Air Cooled, Reheated for 1/2 Hr at 750 C (1380 F), and Cooled at 25 C per Hr to 650 C (1200 F) and Water Quenched

Hardness: 314 DPH.

FIGURE 32. MICROSTRUCTURES PRODUCED BY VARIOUS HEAT TREATMENTS OF THE ZIRCONIUM-22 w/o (10 a/o) URANIUM ALLOY

patches of alpha zirconium agglomerated at this temperature [760 C (1400 F)] and the smaller particles formed during furnace cooling. Figure 32c shows what happens when a fine grained gamma structure is cooled so as to produce a small amount of alpha precipitation as in Figure 31. If the sample is then reheated into the alpha zirconium-plus-gamma region and furnace cooled, the acicular alpha zirconium will agglomerate and form into a grain-boundary network as shown in Figure 32c.

As the composition changes from 20 to 50 w/o (9 to 28 a/o) uranium the precipitation of alpha zirconium becomes progressively more sluggish and the amount formed becomes progressively less. At 30 w/o (14 a/o) uranium, ample quantities of alpha zirconium can be precipitated by simple furnace cooling from the gamma solid-solution region, but at 40 w/o (20 a/o) uranium only traces of alpha zirconium are observed in furnace-cooled samples. At 45 w/o (24 a/o) uranium it requires an isothermal anneal of several weeks at 575 C (1070 F) to form any alpha zirconium.

Figure 33a shows a typical structure of epsilon, Zr_2U , as repeatedly cold worked and annealed below 600 C (1110 F).

Alpha uranium tends to precipitate much more readily from nonequilibrium epsilon on the high-uranium side of this phase. Figure 33b shows the appearance of alpha uranium in a zirconium-60 w/o (36.5 a/o) uranium alloy as air cooled from 900 C. The matrix phase in this photomicrograph is epsilon, the black spots are holes from which alpha uranium has been removed by the etchant. Figure 33c shows the acicular habit form of alpha uranium as it appears in a sample of zirconium-70 w/o (47 a/o) uranium alloy furnace cooled from the gamma region. This structure has its counterpart in the zirconium-rich structures shown in Figures 32a and 32b. This region from 57 to 75 w/o (34 to 54 a/o) uranium is troublesome in the zirconium-uranium system because of the tendency of easily oxidized alpha uranium to form in the microstructures. Further stabilization of the gamma solid solution by the addition of other alloying elements appears to be a possible solution to this problem.

Alloys Containing 75 to 95 w/o (54 to 88 a/o) Uranium

Figure 34 shows a typical uranium martensite as found in a sample of zirconium-95 w/o (88 a/o) uranium alloy water quenched from the gamma solid-solution region. The appearance of the uranium martensite is unique in the zirconium-uranium system and there should be no difficulty in distinguishing it from acicular alpha uranium or from the zirconium martensite shown in Figure 23. Because of their supersaturated condition, uranium martensites tend to be more corrosion resistant than alpha uranium, and they are, therefore, of practical interest, whereas the zirconium martensites appear to be quite useless.

Figure 35 shows a typical acicular alpha structure as found in a furnace-cooled sample of zirconium-95 w/o (88 a/o) uranium alloy. Metallurgists familiar with the structure of pure alpha uranium as formed from gamma uranium will recognize a distinct similarity between the structure of Figure 35 and that of pure uranium. This structure has its counterpart in zirconium-rich alloys in the Widmanstätten structure shown in Figure 27.

500X

N16912

- a. Epsilon Structure in Iodide Zirconium-49 w/o (27 a/o) Uranium Alloy Repeatedly Cold Worked and Annealed Below 600 C (1110 F)

Alloy was homogenized 5 hr at 1070 C (1960 F), water quenched, and cold swaged and annealed twice at 550 C (1020 F), and, finally, cold swaged and annealed for 7 days at 575 C (1070 F). Hardness: 260 DPH.

500X

N31486

- b. Alpha Uranium in Epsilon Matrix of Iodide Zirconium-60 w/o (36.5 a/o) Uranium Alloy Air Cooled From 900 C (1650 F)

Hardness: 370 DPH.

500X

RM4644

- c. Acicular Alpha Uranium Plus Epsilon in Iodide Zirconium-70 w/o (47 a/o) Uranium Alloy Heated for 12 Hr at 650 C (1200 F) and Cooled at 25 C per Hr

The zirconium-rich counterpart of this structure can be seen in Figures 32a and 32b. Hardness: 300 DPH.

FIGURE 33. TYPICAL STRUCTURES OF HIGH-URANIUM ALLOYS IN THE ZIRCONIUM-URANIUM SYSTEM

Alpha uranium replaces alpha zirconium as the dominant precipitate.

250X

N95545

FIGURE 34. URANIUM MARTENSITE STRUCTURE IN IODIDE ZIRCONIUM-95 w/o (88 a/o) URANIUM ALLOY HEATED 1 HR AT 900 C (1650 F) AND WATER QUENCHED

The singular appearance of this phase distinguishes it from the zirconium martensite shown in Figure 23. Hardness: 530 DPH.

250X

N93813

FIGURE 35. ACICULAR ALPHA URANIUM STRUCTURE IN IODIDE ZIRCONIUM-95 w/o (88 a/o) URANIUM ALLOY HEATED 1 HR AT 900 C (1650 F) AND FURNACE COOLED

This structure resembles that of pure uranium. The zirconium-rich counterpart is shown in Figure 27. Hardness: 330 DPH.

550X

N97370

FIGURE 36. TWO IMMISCIBLE GAMMA SOLID SOLUTIONS IN IODIDE ZIRCONIUM-85 w/o (69 a/o) URANIUM ALLOY HEATED 20 HR AT 710 C (1310 F) AND WATER QUENCHED

Presumably, one of the solid solutions is present as uranium martensite and the other is present as retained metastable gamma solid solution.

Alloys in the range from 75 to 95 w/o (54 to 88 a/o) uranium are subject to far more microstructural manipulation by heat treatment than other alloys in the zirconium-uranium system because of the nature of the phase fields in this composition range. Such heat treatments result in mixtures of the basic structures that have already been described. For example, an alloy of zirconium and 85 w/o (69 a/o) uranium might be equilibrated at about 700 C (1290 F) and water quenched so that one portion transforms to uranium martensite and the other is retained as metastable gamma. Such a structure is shown in Figure 36. Similarly, a zirconium-95 w/o (88 a/o) uranium alloy might be annealed at 650 C (1200 F) to produce a network of gamma around particles of alpha uranium. On air cooling, this gamma phase containing perhaps 60 w/o (36.5 a/o) uranium, could be expected to harden as a result of partial transformation and act as a barrier to deformation of the alpha uranium in irradiation. An alloy having this type of treatment has been used in the Experimental Boiling Water Reactor.

References

- (1) Dwight, A. E., and Mueller, M. H., "Constitution of the Uranium-Rich Uranium-Niobium and Uranium-Niobium-Zirconium Systems", ANL-5581 (October, 1957).
- (2) Chubb, W., and Rough, F. A., "Mechanical Properties and Heat-Treatment Response of Zirconium-Uranium Alloys", Trans. ASM, 51, 697 (1959).
- (3) Kearns, J. J., "Transformation Kinetics of Uranium-Zirconium Alloys Containing 50 and 60 Per Cent Uranium", WAPD-T-417 (November, 1956).
- (4) Saller, H. A., Rough, F. A., and Chubb, W., "The Heat-Treatment Response of Some Zirconium-Uranium Alloys", BMI-1096 (June, 1956).
- (5) Chubb, W., Muehlenkamp, G. T., and Manning, G. K., "The Properties and Heat Treatment of Zirconium-Uranium Alloys", BMI-973 (January, 1955).
- (6) Saller, H. A., Rough, F. A., and Bauer, A. A., "Heat Treatment and Properties of Uranium-5 Per Cent Zirconium Alloy", BMI-915 (May, 1954).
- (7) Douglass, D. L., Marsh, L. L., and Manning, G. K., "Transformation Kinetics of Zirconium-Uranium Alloys", Trans. ASM, 50, 305 (1958).
- (8) Holden, A. N., and Seymour, W. E., "Intermediate Phase in the Uranium-Zirconium System", Trans. AIME, 206, 1312 (October, 1956).
- (9) Silcock, J. M., Discussion of Uranium-Zirconium System, Trans. AIME, 209, 521 (April, 1957).

STRENGTH CHARACTERISTICS OF ZIRCONIUM- URANIUM ALLOYS

Lyle L. Marsh, Jr.

The mechanical strength of zirconium-base alloys, like the properties of other metal-base alloys, depends not only on composition, but also on the microstructure; that is, the type, amount, and distribution of phases. Impurity and alloy elements in zirconium affect the transformation of gamma (body-centered cubic) to alpha (hexagonal close packed) and, therefore, affect not only the phases present at room temperature, but also the size and shape of the microconstituents. Thus, impurity elements such as carbon, nitrogen, and oxygen may exert a tremendous influence on the mechanical properties of zirconium.

Crystal-bar zirconium, when processed to minimize contamination, will be soft and ductile and will have a room-temperature tensile strength in the range 28,000 to 38,000 psi with an elongation of about 40 per cent. A crystal-bar zirconium-0.1 w/o oxygen alloy will have a tensile strength of approximately 52,000 psi at room temperature. The first sponge zirconium made had a high oxygen content, and possessed a tensile strength of 70,000 to 90,000 psi at room temperature, with an elongation of only about 5 per cent. Sponge zirconium produced more recently has a lower oxygen content. It has a tensile strength of only about 52,000 psi, but an elongation of 25 to 30 per cent. The latter values are comparable to those obtained from a zirconium-0.1 w/o oxygen alloy made from crystal-bar zirconium. It is apparent from the above data that improved process control for sponge zirconium has resulted in roughly a 50 per cent decrease in strength with a severalfold increase in tensile ductility. Although the impurity content of zirconium alloys is very important, it has not been reported by many investigators. There has, however, been a gradual evolution toward higher purity. Because of these factors, it is frequently difficult to rationalize the results of early work with those of more recent studies.

Zirconium-uranium alloys have long been regarded as promising for reactor fuel, and much development work has been done. However, a detailed and systematic study of the binary system to evaluate the compositional dependence of heat-treatment characteristics and the effects on mechanical properties of corrosion and fabrication as directly related to heat treatment has not been undertaken. Recently, several studies have been made to bridge this gap in the knowledge of zirconium-uranium alloys.^(1,2,3) Since many of the early mechanical-property data reported in the literature were determined on material of variable fabrication history and, nominally, in the alpha-annealed condition, it was not until these more recent studies of alloys richer in uranium were undertaken that the peculiarities of gamma-phase decompositions were observed.

On the basis of the reported data, the mechanical properties of zirconium-uranium alloys have been divided into two groups for analysis: (1) data on alloys in the alpha-treated condition, and (2) data concerned primarily with gamma-phase decomposition products. Before reviewing these data, a brief examination of the mechanical properties of the microconstituents is desirable.

The solid solubility of uranium in alpha zirconium is less than 1.0 w/o (0.4 a/o) uranium.⁽⁴⁾ As a consequence, appreciable solid-solution strengthening of alpha is not to be expected, and the bulk of any strengthening will be dependent on the size and distribution of the gamma-phase decomposition products, particularly of the epsilon phase. Experimental evidence obtained on alloys in the composition range where the volume per cent of the epsilon phase is large indicates that this phase is comparatively hard^(2,3) and of limited ductility. Therefore, the mechanical properties of zirconium-rich uranium alloys may be expected to be intermediate between the properties of alpha zirconium and epsilon.

The Effects of Composition on Mechanical Properties in the Annealed Condition

A fairly good picture of the properties of annealed zirconium-uranium alloys can be gained from hot-hardness data. Data for alloys across the system have been plotted on the constitutional diagram and are shown in Figure 37.⁽³⁾

The early tensile data for various alloy compositions and temperatures are summarized in Figure 38 and Table 2. There is considerable scatter, but a trend of increasing strength with greater uranium content is shown. Much of the scatter can be attributed to variations in hot-rolling and annealing temperatures, as well as to variations in melting stock and melting practice. Contamination by carbon, nitrogen, or oxygen, in general, results in higher tensile strength and reduced tensile ductility for annealed alloys and contributes to the scatter also.

Figure 39 and Table 3 contain more recent tensile data obtained for alloys prepared by induction and by arc melting.⁽²⁾ The alloys were forged and rolled at temperatures, depending on composition, between 700 and 925 C (1300 and 1700 F) and were vacuum annealed 24 hr at 575 C (1065 F). Induction melting consistently resulted in lower tensile ductility, primarily because of carbon pickup from graphite crucibles. The tensile ductility at room temperature decreases continuously with increasing uranium and exhibits semibrittle behavior in the composition range 40 to 70 w/o (21 to 47 a/o) uranium, presumably due to the epsilon phase. The effect of epsilon-phase formation on the dynamic modulus at various temperatures is shown in Figures 40 and 41. The dynamic modulus of the induction-melted alloys (Figure 40) is consistently greater than for the arc-melted alloys (Figure 41), again indicating the effect of contamination. It is possible that the role of contamination, aside from alloy strengthening, may be to alter the distribution and size of the microconstituents present after hot rolling followed by 24 hr at 575 C (1065 F).

The creep properties of dilute zirconium-uranium alloys have received limited attention. Creep data have been reported for a 3.66 w/o (1.44 a/o) uranium alloy at 260 C (500 F).⁽⁹⁾ These data are tabulated below.

Stress, psi	Time, hr	Total Deformation, per cent	Secondary Creep Rate, per cent per hr
20,000	2000	0.39	7×10^{-6}
22,000	2000	0.96	10×10^{-6}
23,000	600	1.45	Nil
27,000	600	2.60	Nil
30,000	700	5.25	Nil

FIGURE 37. HARDNESS-TEMPERATURE RELATIONSHIPS IN THE ZIRCONIUM-URANIUM SYSTEM

Hardness in DPH, kg per mm².

TABLE 2. RESULTS OF EARLY STUDIES OF TENSILE PROPERTIES OF ZIRCONIUM URANIUM ALLOYS

Uranium Content (Balance Zirconium)		Fabrication History	Reference	Test Temperature		0.2 Per Cent Offset Yield	Tensile	Elongation,	Reduction of
w/o	a/o			C	F	Strength, psi	Strength, psi	per cent	Area, per cent
Iodide zirconium		Hot rolled at 790 C (1450 F), cold rolled, annealed 1 hr at 700 C (1300 F), (Grade 1 double-arc-melted zirconium)	(5)	Room temperature		16,400	35,500	36	43
2	0.8	Arc-melted Grade 3 crystal bar, hot rolled	(6)	260	500	8,400	16,000	49	70
				315	600	7,800	15,600	52	78
				150	300	36,600	56,500	26	58
				315	600	20,400	33,000	27	70
3.3	1.3	Rolled at 900 C (1650 F), an- nealed 1 hr at 900 C (1650 F)	(7)	350	660	17,300	39,800	--	--
3.5	1.4	Grade 1 crystal bar, double-arc melted, rolled at 790 C (1450 F), cold rolled, and annealed 1 hr at 700 C (1300 F)	(5)	Room temperature		38,600	60,800	12	19
				260	500	17,600	30,600	44	67
				315	600	17,200	27,900	38	66
3.66	1.44	Rolled at 675 C (1250 F), annealed 1 hr at 590 C (1100 F)	(8, 9)	Room temperature		34,000	54,200	35	--
				200	400	23,200	38,800	33	--
				260	500	20,100	32,200	36	--
				480	900	16,400	26,200	41	--
4	1.6	Arc melted, hot rolled	(6)	150	300	50,000	63,500	26	46
				315	600	33,400	42,500	28	52
6	2.4	Arc melted	(2)	155	310	51,200	61,300	25	44
				260	500	36,000	46,000	27	46
9.7	4.0	Arc melted	(10)	Room temperature		103,000-117,000	121,000	18	37
				150	300	85,000-90,000	91,000	25-34	46-50
							96,000		
				260	500	58,500	74,700	24	48
				315	600	57,500	61,000- 70,000	22-43	38-57

TABLE 2. (Continued)

Uranium Content (Balance Zirconium)		Fabrication History	Reference	Test Temperature		0.2 Per Cent Offset Yield Strength, psi	Tensile Strength, psi	Elongation, per cent	Reduction of Area, per cent
w/o	a/o			C	F				
12.9	5.4	Rolled at 900 C (1650 F), an- nealed 1 hr at 900 C (1650 F); Bur. Mines Zr	(2, 7)	Room temperature		81,300-	106,000-	25	45/85
						92,500	103,700		
				100	212	66,800	88,200	26	
				100	212	87,500	107,000	--	
								--	--

A-15791

FIGURE 39. TENSILE BEHAVIOR OF ZIRCONIUM-URANIUM ALLOYS PREPARED BY INDUCTION AND ARC MELTING

TABLE 3. TENSILE PROPERTIES OF ZIRCONIUM-URANIUM ALLOYS ANNEALED 24 HR AT 575 C (1065 F)

Analyzed Composition			Room-Temperature Property					Properties at 370 C (700 F)			
Zirconium, w/o	Uranium w/o	a/o	0.2 Per Cent Offset Yield Strength, psi	Tensile Strength, psi	Elongation in 2 In., per cent	Reduction in Area, per cent	Hardness (DPHN)	0.2 Per Cent Offset Yield Strength, psi	Tensile Strength, psi	Elongation in 2 In., per cent	Reduction in Area, per cent
<u>Induction-Melted Fernald Uranium</u>											
100.0	0	0	26,700	53,800	34.0	27.0	138	10,500	22,400	30.0	55.0
90.0	10.0	4	58,800	84,300	16.0	27.0	197	43,800	61,000	5.6	29.0
80.8	19.2	8	85,500	103,900	10.0	8.0	252	69,300	80,100	5.7	9.0
71.7	28.3	13	87,700	110,000	4.0	4.0	298	73,900	93,600	8.0	8.0
59.5	40.5	21	80,700	116,500	3.6	6.2	302	60,100	94,100	3.5	1.1
50.1	49.9	28	79,700	109,000	2.6	3.6	264	67,600	86,800	6.0	9.7
39.7	--	--	118,700	157,300	1.5	1.6	384	113,300	125,700	0.5	1.8
39.9	--	--	(a)	--	--	--	370	114,000	145,000	2.0	--
21.9	--	--	140,000	179,000	4.0	5.8	291	116,700	137,200	4.3	9.3
10.9	--	--	110,600	163,200	5.0	6.0	363	75,800	100,800	6.0	17.0
5.8	--	--	97,200	166,200	5.0	6.0	347	63,700	84,600	9.0	35.0
0	--	--	65,900	117,300	3.5	4.9	265	27,100	34,550	16.0	37.0
<u>Arc-Melted Derby Uranium</u>											
100.0	0	--	18,000	36,700	43.0	56.0	113	8,500	17,300	42.0	--
89.4	10.6	4	60,500	70,200	6.0(b)	19.0(b)	246	53,200	64,200	7.0(b)	11.0(b)
80.0	20.0	9	86,800	101,800	24.0	41.0	235	72,000	77,900	5.0	22.0
70.4	29.6	14	71,300	115,000	14.0	16.0	243	64,800	86,400	20.0	27.0
60.6	39.4	20	80,800	131,800	9.0	14.0	295	63,800	97,800	22.0	20.0
50.5	49.5	27	84,300	118,000	4.5	8.0	272	68,100	96,100	22.0	28.0
41.7	58.3	35	95,000	103,300	1.0	--	279	97,000	115,300	8.0	13.0
31.4	--	--	132,700	161,600	2.0	4.0	350	112,000	145,200	7.0	7.0
20.5	--	--	(a)	--	--	--	411	124,000	135,200	8.0	18.0
11.5	--	--	145,000	199,000	9.0	--	359	100,800	122,800	8.0	29.0
5.5	--	--	88,000	162,000	6.0	7.5	307	50,500	77,000	10.0	25.0
2.4	--	--	47,300	133,000	18.0	21.0	283	35,100	48,400	17.0	49.0
0	--	--	48,400	123,000	11.0	--	263	21,300	31,400	27.0	57.0

(a) Specimens contained rolling defects.

(b) Specimens broke in what appeared to be rolling defects.

FIGURE 40. VARIATION OF DYNAMIC MODULUS OF ELASTICITY AT VARIOUS TEMPERATURES WITH URANIUM CONTENT IN INDUCTION-MELTED ZIRCONIUM-URANIUM ALLOYS

A-8092

FIGURE 41. VARIATION OF DYNAMIC MODULUS OF ELASTICITY AT VARIOUS TEMPERATURES WITH URANIUM CONTENT IN ARC-MELTED ZIRCONIUM-URANIUM ALLOYS

This alloy was prepared by double arc melting and was forged and rolled to sheet at 675 C (1250 F). The alloy was anneal straightened at 760 C (1400 F), cold rolled (25 per cent reduction), and annealed 1 hr at 590 C (1100 F). These data reveal an interesting characteristic in that the strain obtained on loading is apparently sufficient to work harden the alloy such that negligible secondary creep results at stresses between 23,000 and 30,000 psi. These results are contrary to normal high-temperature creep behavior and would not be expected at temperatures above the recrystallization temperature (about 400 C for this alloy).

Creep data have also been obtained on 22 and 41 w/o (10 and 21 a/o) uranium alloys.⁽¹⁾ These alloys were prepared from Foote Grade 1 low-hafnium iodide zirconium and biscuit uranium. The 22 w/o (10 a/o) uranium alloy was arc melted by the consumable-electrode process, while the 41 w/o (21 a/o) uranium alloy was prepared by arc melting in a water-cooled copper crucible. The creep data are summarized in the following tabulation.

Fabrication History	Test		Stress for 1 Per Cent			Minimum
	Temperature		Deformation, psi			Creep Rate ^(a) ,
	C	F	In 100 Hr	In 1,000 Hr	In 10,000 Hr	10 ⁻⁶ in./in./hr
<u>22 w/o (10 a/o) Uranium Alloy^(b)</u>						
Hot rolled at	400	750	38,000	30,000	18,000	0.8
675 C (1245 F),	450	840	19,000	15,000	8,400	3
annealed at	500	930	11,000	8,400	5,500	100
800 C (1470 F),						
and furnace						
cooled						
<u>41 w/o (21 a/o) Uranium Alloy</u>						
Hot rolled at	450	840	--	20,000	10,500	0.8
900 C (1650 F),						
water quenched,						
reheated to						
575 C (1070 F)						
for 24 hr, and						
furnace cooled						

(a) Minimum creep rate at a stress of 10,000 psi.

(b) Data obtained from graph in Reference (1).

The time to rupture of a 20 w/o (9 a/o) uranium specimen at 540 C (1000 F) in sodium for various stresses has been determined.⁽¹¹⁾ This alloy was double arc melted and rolled to sheet at 700 C (1300 F). Tests were run on the hot-rolled sheet. The data are given in the following tabulation:

Stress, psi	Time to Rupture ^(a) , hr
30,000	0.28
5,000	12
5,000	19
4,000	33
3,500	1000

(a) Data taken from graph of Reference⁽¹¹⁾.

The data for the creep behavior of the 20 and 22 w/o (9 and 10 a/o) uranium alloys are at first glance inconsistent, in that extrapolation of the data for the 22 w/o (10 a/o) alloy to 540 C (1000 F) indicates that the stress for 1 per cent total deformation in 100 hr should, if applied to the 20 w/o (9 a/o) uranium alloy, result in rupture in less than 10 hr. While extrapolations should be viewed with caution, the range of extrapolation is only 40 C (70 F) and the alloy is already in the temperature range of rapid creep. The discrepancy might arise from the different thermal histories of the alloys or from a weakening influence of liquid sodium.

Creep data in the gamma phase at 815 C (1500 F) and 980 C (1800 F) have been reported for 27.4 and 52.9 w/o (12.6 and 30.1 a/o) uranium alloys.⁽¹²⁾ These alloys were double arc melted and forged and rolled at 790 C (1450 F). These data, along with data at 980 C (1800 F) for an induction-melted alloy containing 36.3 w/o (17.9 a/o) uranium, are given in the following tabulation:

Uranium Content (Balance Zirconium)		Stress, psi	Time for	Minimum	Test Time,	Elongation,
w/o	a/o		1 Per Cent	Creep Rate,		
			Deformation,	per cent		
		hr	per hr	hr	per cent	
<u>Tested at 815 C (1500 F)</u>						
27.4	12.6	500	40	0.021	162.7	12.3
52.9	30.1	500	56	0.013	169	15.1
<u>Tested at 980 C (1800 F)</u>						
27.7	12.8	500	0.57	1.7	7.5	36.2
36.3(a)	17.9	500	0.5	2.0	21	65.3
52.9	30.1	500	0.16	5.5	1.8	37

(a) Induction melted, cast in copper crucible, rolled at 815 C (1500 F).

These data demonstrate the weakness of the gamma phase at these temperatures, but indicate that some solid-solution strengthening by uranium still occurs.

The Effects of Gamma-Phase Decomposition on Mechanical Strength

Most of the information available on the relation between composition, heat treatment, and some strength parameter, such as tensile strength or hardness has been of rather recent origin.^(1,13-15)

Zirconium-uranium alloys containing up to approximately 20 w/o (9 a/o) uranium transform on very rapid cooling from the gamma phase by a mechanism very similar to the martensite reaction in iron-carbon and in many titanium-base alloys. At lower cooling rates, Widmanstätten alpha is rejected from gamma at temperatures between the alpha plus epsilon/alpha plus gamma transus and the alpha plus gamma/gamma transus. For temperatures below the reaction isotherm (595 ± 5 C) gamma decomposes to alpha and epsilon. The epsilon thus formed may be supersaturated with zirconium, depending on the cooling rate and transformation temperature. For uranium

concentrations in excess of approximately 20 w/o (9 a/o) uranium and up to at least 45 w/o (24 a/o) uranium, the high-temperature gamma solid solution transforms on cooling to a supersaturated epsilon. The process of decomposition of gamma solid solution is accompanied by considerable hardening and a corresponding decrease in ductility.

Typical mechanical properties of an alloy with 10 w/o (4 a/o) uranium, as affected by heat treatment, are summarized in Table 4. Based on the phase diagram, the microstructure of the 10 w/o (4 a/o) uranium alloy at 700 C (1300 F) consists of alpha plus uranium-enriched gamma. Hot working at this temperature will probably result in fine-grained alpha with regions of uranium-enriched gamma dispersed through the structure. If a sufficiently rapid cooling is used from the two-phase field, the enriched gamma phase undergoes a hardening reaction, and limited ductility would be expected, as in Treatment 1 in Table 4. Reheating to 700 C (1300 F) and soaking for 4 hr (Treatment 2) probably resulted in alpha-phase grain growth and, possibly, some coalescence of the gamma phase, thereby yielding somewhat greater ductility. The low ductility due to Treatment 3 is the result of a martensitic microstructure obtained on quenching from 900 C (1650 F). The increased ductility obtained by Treatment 4 may be associated with growth of the alpha phase at temperature and decomposition of the uranium-enriched gamma phase to form a Widmanstätten structure of alpha and epsilon.

As indicated earlier the heat treatment response of alloys with uranium concentrations in the range of 15 to 20 w/o (6 to 9 a/o) is strongly dependent on the quenching temperature and cooling rate.⁽¹⁾ Very rapid cooling from the gamma phase results in gamma decomposition by a martensitic-type transformation. This is accompanied by an increase in hardness and a decrease in ductility. A lower cooling rate, but faster than air cooling, will suppress the martensitic transformation and gamma will transform to a supersaturated epsilon exhibiting a large increase in hardness and virtually no tensile ductility. For example, water quenching a 19 w/o (8 a/o) uranium alloy from 900 C (1650 F) results in a martensitic microstructure with a hardness of approximately 250 DPH.⁽¹⁾ The tensile ductility corresponding to this hardness is approximately 7 per cent elongation. A slack quench from 950 C (1740 F) for a 20 w/o (9 a/o) uranium alloy produced an equiaxed structure of supersaturated epsilon within the former gamma grains. The corresponding tensile elongation is approximately 2 per cent.

Data for a 22 w/o (10 a/o) uranium alloy⁽¹⁾ indicate that the martensitic reaction was suppressed and the gamma phase was partially retained by water quenching. The hardness of the partially retained beta was about 425 to 450 DPH. This hardness is not a characteristic of retained gamma, but is the result of initiation of decomposition during quenching. This interpretation is supported by X-ray studies⁽¹⁾ of the decomposition products obtained by quenching a Jominy bar of the 22 w/o (10 a/o) alloy from 900 C (1650 F). No evidence was found of alpha zirconium even 1 in. from the quenched end, but retained gamma and the epsilon phase were identified. Additional discussion of the hardening reaction is given in the section on "Kinetics of Transformation of Zirconium-Uranium Alloys".

Regardless of the hardening mechanism, its effect on the mechanical properties is, in many respects, pronounced. Mechanical properties of the 22 w/o (10 a/o) uranium alloy as determined in separate studies, are summarized in Tables 5, 6, and 7 for various heat-treated conditions. One of the more important features shown by these data is the effect of hot-rolling temperature on the tensile ductility and, to a lesser degree, on

TABLE 4. MECHANICAL PROPERTIES OF ZIRCONIUM-10 w/o URANIUM ALLOY(a)

Heat Treatment	Room-Temperature Tensile Properties						Hardness	
	0.2 Per Cent Offset Yield Strength, psi	Ultimate Strength, psi	Elongation to Maximum Load, per cent	Total Elongation in 1 In., per cent	Reduction of Area, per cent		DPH	R _A
1	77,800	109,200	4	8	13		221	59
2	54,500	79,900	13	17	20		203	56
3	88,100	105,600	4	8	10		242	60
4	40,800	71,800	19	32	32		180	51

Treatment 1: Hot rolled at 700 C (1300 F) and air cooled.

Treatment 2: Hot rolled at 700 C (1300 F) and air cooled; reheated to 700 C (1300 F) for 4 hr and furnace cooled.

Treatment 3: Hot rolled at 700 C (1300 F) and air cooled; reheated to 900 C (1650 F) for 1 hr and water quenched.

Treatment 4: Hot rolled at 700 C (1300 F) and air cooled; reheated to 800 C (1470 F) for 1 hr and furnace cooled.

(a) From Reference 1.

the tensile strength. Hot rolling at 675 C (1250 F) in the alpha-plus-gamma field (Table 5) resulted in a lower tensile strength and increased tensile ductility compared with rolling at 540 C (1000 F) (Table 6). These differences in properties may result from the distribution of the epsilon phase in the matrix, or to residual cold work. Another difference may be observed in the properties of the alloy in the gamma-treated and furnace-cooled conditions. The specimen furnace cooled after 36 hr at 840 C (1550 F), Treatment 2 in Table 6, exhibited no ductility, while a 1-hr treatment at 800 C (1470 F), Treatment 5 in Table 5, resulted in excellent ductility. The specimen treated 36 hr at 840 C (1550 F) may have been cooled more rapidly from the beta, and may also have picked up oxygen and nitrogen during the long heat treatment. Air cooling seems to embrittle the alloy, as shown by Treatment 4 in Table 5. The data contained in Table 7 reinforce the conclusions drawn from Tables 5 and 6 in that slow cooling or isothermal transformation is needed to impart even limited ductility to these alloys. Table 7 also indicates that increasing the oxygen content by preparing alloys from sponge zirconium greatly reduces ductility, although this point is not firmly established.

The 41 w/o (21 a/o) uranium alloy exhibits gamma-decomposition behavior similar to the 22 w/o (10 a/o) alloy, except that the reaction is slower. The gamma phase can be fully retained in the 41 w/o (21 a/o) alloy and is soft (260 DPH) and ductile. Jominy end-quench tests, Figure 42, produced a hardness maximum away from the quenched end of the specimen, indicating that the hardening reactions require time, or some slight amount of diffusion. X-ray studies also revealed that the Jominy bar contained only retained gamma at the end of the bar. Unfortunately, these data do not reveal the basic nature of the hardening reaction.

The mechanical properties of the 41 w/o (21 a/o) uranium alloy after various heat treatments are given in Table 8. In general, the tensile strength has not been significantly affected by the increase in composition from 22 w/o to 41 w/o (10 to 21 a/o) uranium nor by the heat treatments indicated.

Further increases in uranium concentration to 50, 55, and 60 w/o (28, 32, and 36.5 a/o) as shown in Table 9 do not alter the tensile behavior appreciably. This composition range extends to the uranium-rich side of the epsilon-phase region. The gamma phase of the 60 w/o uranium alloy transforms to an epsilon phase supersaturated with uranium. The hardening process due to the transformation of gamma is similar to that observed in the higher zirconium alloys. The retained-gamma phase is seen to be quite ductile as noted with alloys quenched directly from 950 C (1742 F).

In transformed alloys the tensile ductility has been generally decreased as compared with that of the 22 w/o (10 a/o) alloy. Isothermal transformation at 425 C (797 F) for periods up to 5 hr after solution treating at 950 C (1742 F) does not result in improved mechanical behavior. Longer times or transformation at higher temperatures, which will result in epsilon-particle growth, are required for increased ductility.

It has been reported⁽¹⁶⁾ that serrated stress-strain curves were obtained for sponge-zirconium-base alloys containing 40, 50, 55, 60, and 70 w/o (20, 28, 32, 36.5,

TABLE 5. MECHANICAL PROPERTIES OF ZIRCONIUM-22 w/o URANIUM ALLOY^(a)

Heat Treatment	Test Temperature	0.2 Per Cent Offset Yield Strength, psi	Ultimate Strength, psi	Elongation to Maximum Load, per cent	Total Elongation in 1 In., per cent	Reduction of Area, per cent	Hardness	
							DPH	R _A
1	Room	102,800	120,200	5	16	23	240	61
2	Room	94,000	101,900	12	17	25	238	61
3	Room	(b)	83,400	(b)	0	0	387	72
4	Room	81,400	106,600	2	3	2	274	65
5	Room	59,700	103,500	21	23	24	245	60
5	400 C, 750 F	43,700	67,300	14	24	37	--	--
5	450 C, 840 F	41,000	59,200	10	29	34	--	--
5	500 C, 930 F	36,900	48,000	3	48	69	--	--

Treatment 1: Hot rolled at 675 C (1250 F) and furnace cooled.

Treatment 2: Hot rolled at 675 C (1250 F) and furnace cooled; reheated to 575 C (1065 F) for 24 hr and furnace cooled.

Treatment 3: Hot rolled at 675 C (1250 F); heated to 800 C (1470 F) for 1 hr and water quenched.

Treatment 4: Hot rolled at 675 C (1250 F); heated to 800 C (1470 F) for 1 hr and air cooled in a Vycor capsule.

Treatment 5: Hot rolled at 675 C (1250 F); heated to 800 C (1470 F) for 1 hr and furnace cooled at a rate of 100 C (180 F) per hr.

(a) From Reference 1.

(b) Specimens failed in reduced section in brittle manner.

TABLE 6. TENSILE PROPERTIES OF HEAT-TREATED ZIRCONIUM-22 w/o URANIUM ALLOY(a)

Heat Treatment	Test Temperature	0.2 Per Cent Offset Yield Strength, psi	Ultimate Strength, psi	Uniform Elongation, per cent	Total Elongation in 1 In., per cent	Reduction of Area, per cent
1	Room	112,000	129,200	1.9	2	2
2	Room	(b)	57,700	0.5	0	0
3	Room	48,300	87,900	13	16	17
4	Room	(b)	60,800	0.4	0	0
5	Room	(b)	55,400	0.4	0	0
6	Room	64,000	97,200	7.4	8	9
1	500 C, 930 F	12,000	25,600	8.4	75	92
2	500 C, 930 F	41,800	55,200	5.1	14	13
3	500 C, 930 F	29,200	44,200	6.2	34	32
4	500 C, 930 F	38,400	54,500	3.7	12	18
5	500 C, 930 F	34,200	47,500	4.9	25	38
6	500 C, 930 F	35,100	48,000	5.7	18	22

Heat treatment 1: As rolled at 540 C (1000 F).

Heat treatment 2: 36 hr at 840 C (1550 F), furnace cooled.

Heat treatment 3: 36 hr at 840 C (1550 F), cooled 1/2 F/min from 840 C (1550 F) to 650 C (1200 F), furnace cooled.

Heat treatment 4: 36 hr at 840 C (1550 F), furnace cooled; reannealed 1 hr 840 C (1550 F), quenched to 550 C (1020 F), held 1/2 hr, reheated to 700 C (1300 F), held 10 hr, water quenched, annealed 1 hr 550 C (1020 F), water quenched.

Heat treatment 5: 36 hr at 840 C (1550 F), water quenched; annealed 1/2 hr at 550 C (1020 F), water quenched; annealed 10 hr at 760 C (1400 F), furnace cooled.

Heat treatment 6: 36 hr at 840 C (1550 F), water quenched; annealed 22 days at 550 C (1020 F), furnace cooled.

(a) From Reference 13.

(b) Brittle fracture.

TABLE 7. MECHANICAL PROPERTIES OF ZIRCONIUM-20 TO 22 w/o URANIUM ALLOYS AT 25 C

Uranium Content (Balance Zirconium)		Heat Treatment	0.2 Per Cent Offset Yield Strength, psi	Tensile Strength, psi	Total Elongation, per cent	Reduction in Area, per cent
w/o	a/o					
20(a)	9	1	--	89,800	2.3	1.4
		2	66,500	99,550	7.5	8.7
		3	--	82,100	Brittle	
22(a)	10	1	Brittle			
		4	84,800	112,000	5.0	5.0
		3	--	75,700	0.6	--
		5	60,000	98,000	5	10.2
22(b)	10	4	109,000	128,000	3.5	5.5
		3	90,500	121,000	1.5	1.8
		5	65,200	102,500	7.8	7.0

Treatment 1: Held 1 hr at 950 C (1740 F) and water quenched.

Treatment 2: Held 1 hr at 950 C (1740 F), isothermally transformed 100 min at 550 C (1020 F), and water quenched.

Treatment 3: Held 1 hr at 950 C (1740 F) and air cooled.

Treatment 4: Held 1 hr at 950 C (1740 F), isothermally transformed at 550 C (1020 F) for 200 min, and water quenched.

Treatment 5: Held 1 hr at 950 C (1740 F) and furnace cooled.

(a) Alloy prepared from crystal-bar zirconium.

(b) Alloy prepared from sponge zirconium.

FIGURE 42. JOMINY END-QUENCH TESTS ON ZIRCONIUM-41 w/o (21 a/o) URANIUM ALLOY

TABLE 8. MECHANICAL PROPERTIES OF ZIRCONIUM-41 w/o URANIUM ALLOY^(a)

Heat Treatment	Room-Temperature Tensile Properties						Hardness	
	0.2 Per Cent Offset Yield Strength, psi	Ultimate Strength, psi	Elongation to Maximum Load, per cent	Total Elongation in 1 In., per cent	Reduction of Area, per cent			
							DPH	R _A
1	--	92,000	--	0	0		227	61
2	111,600	144,400	3	4	1		325	65
3	83,600	133,000	4	5	5		317	65
4	80,200	126,200	3	4	4		287	64
5	53,600	73,400	1	2	5		243	60

Treatment 1: Hot rolled at 760 C (1400 F) and furnace cooled; reheated to 700 C (1300 F) for 4 hr and water quenched.

Treatment 2: Hot rolled at 760 C (1400 F) and furnace cooled; reheated to 700 C (1300 F) for 4 hr and air cooled in a Vycor capsule.

Treatment 3: Hot rolled at 760 C (1400 F) and furnace cooled.

Treatment 4: Hot rolled at 760 C (1400 F) and furnace cooled; reheated to 575 C (1070 F) for 24 hr and furnace cooled.

Treatment 5: Hot rolled at 900 C (1650 F) and water quenched from 900 C; reheated to 575 (1070 F) for 24 hr and furnace cooled.

(a) From Reference 1.

TABLE 9. MECHANICAL PROPERTIES OF ZIRCONIUM-50, -55, AND -60
w/o URANIUM ALLOYS AT 25 C

Uranium Content (Balance Zirconium)		Heat Treatment	0.2 Per Cent Offset Yield Strength, psi	Tensile Strength, psi	Elongation, per cent	Reduction in Area, per cent
w/o	a/o					
50(a)	28	1	82,700	94,400	7	24.7
		2	84,000	114,500	2	3
		3	97,500	131,200	-	1.6
50(b)	28	1	94,500	104,300	4.4	12.5
50(c)	28	1	101,000	110,500	3	3.3
55(a)	32	1	73,000	85,000	7.5	19.5
		4	100,000	117,500	1.4	5.1
		5	98,700	112,000	-----Brittle -----	
60(a)	36.5	1	78,000	89,000	5.5	20.2
		4	108,400	129,000	2.5	2.3
		5	107,600	123,700	1.4	-

Treatment 1: Held 1 hr at 950 C (1740 F) and water quenched.

Treatment 2: Held 1 hr at 950 C (1740 F), isothermally transformed
2 hr at 425 C (800 F), and water quenched.

Treatment 3: Held 1 hr at 950 C (1740) and isothermally transformed
2 hr at 250 C (480 F).

Treatment 4: Held 1 hr at 950 C (1740 F), isothermally transformed
5 hr at 425 C (800 F), and water quenched.

Treatment 5: Held 1 hr at 950 C (1740 F), isothermally transformed
5 hr at 425 C (800 F), and air cooled.

(a) Alloy prepared with crystal-bar zirconium.

(b) Alloy prepared with sponge zirconium.

(c) Alloy prepared with high-oxygen sponge zirconium.

and 47 a/o) uranium. The results showed that:

- (1) Epsilonized alloys produced serrations in all the alloys mentioned except 70 w/o (47 a/o) uranium.
- (2) Gamma-quenched alloys exhibited serrated behavior for all compositions (serrations always appear at test temperatures where the gamma-transformation reaction occurs rapidly).
- (3) The serrations appeared at lower temperatures for gamma-quenched alloys than for epsilonized alloys.
- (4) Aging caused the serrations to become smaller, more numerous, while the tensile strength was lowered.
- (5) Serrations increased in size as the strain rate was decreased.

The observed behavior was interpreted as being caused by strain-induced transformation of supersaturated epsilon by precipitation of platelets of alpha zirconium or alpha uranium depending on the uranium and oxygen composition.

Discussion

The foregoing description of data on the effects of uranium composition on the mechanical properties of zirconium-uranium alloys indicates that the system has been reasonably well studied in a general manner. Annealed alloys exhibit mechanical properties intermediate between those of the alpha-zirconium and epsilon phases. The data also indicate that induction melting results in lower tensile ductility as compared with arc melting. Presumably, this reduced ductility results from carbon contamination.

In the composition range up to 19 w/o (8 a/o) uranium, alloys cooled from the gamma phase transform to yield microstructures varying from a coarse Widmanstätten structure on slow cooling to a fine, acicular, martensitic structure on water quenching. As would be expected, the mechanical strength is sensitive to the size of the alpha-phase particles and the uranium content of the alpha phase. Furnace cooling 10 w/o (4 a/o) uranium alloys from the gamma phase (Table 4) yields a microstructure of Widmanstätten alpha with epsilon particles distributed along the alpha interface. Increasing the uranium content to 15 or 20 w/o (6 or 9 a/o) uranium requires faster cooling to obtain a martensitic microstructure. A slack quench of these alloys yields a duplex structure of acicular alpha and an equiaxed epsilon phase supersaturated with zirconium. The appearance of this supersaturated epsilon phase coincides with the onset of very limited tensile ductility. In addition, the embrittlement introduced by this phase is remarkably persistent as can be observed in Table 6. Apparently, a gamma anneal is required to restore full ductility, while prolonged alpha annealing is only partially effective. However, a quench from the gamma phase to alpha temperatures of approximately 500 C (930 F) results in the decomposition of gamma to alpha plus epsilon and results in partial ductility.

Increasing the uranium content to compositions close to the epsilon-phase concentration range and beyond results in the retention of the gamma phase on quenching; maximum ductility is obtained in this condition. Similar ductility is observed upon

furnace cooling these alloys. Maximum hardness and minimum ductility are obtained on air cooling or when heat treatment produces either a partially transformed structure or one in which the epsilon particles have not had sufficient time to coalesce.

References

- (1) Chubb, W. , Muehlenkamp, G. T. , and Manning, G. K. , "Properties and Heat Treatment of Zirconium-Uranium Alloys", BMI-973 (January, 1955).
- (2) Muehlenkamp, G. T. , Chubb, W. , and Schwope, A. D. , "Mechanical Properties of Alloys of the Uranium-Zirconium System", BMI-879 (October, 1953).
- (3) Chubb, W. , Muehlenkamp, G. T. , and Schwope, A. D. , "A Hot Hardness Survey of the Zirconium-Uranium System", BMI-833 (May, 1953).
- (4) Saller, H. A. , and Rough, F. A. , "Compilation of U. S. and U. K. Uranium and Thorium Constitutional Diagram, BMI-1000 (June, 1955).
- (5) Schwope, A. D. , Muehlenkamp, G. T. , and Chubb, W. , "Mechanical Properties of Zirconium and Zirconium-Uranium Alloys Containing Tin", BMI-770 (September, 1952).
- (6) "Monthly Technical Progress Report", WAPD-MR-14 (February, 1951).
- (7) Layman, D. L. , and Naymark, S. , unpublished information, Argonne National Laboratories (May, 1951).
- (8) Udy, M. C. , and Boulger, F. M. , "The Properties of Zirconium Alloys", Part IV, BMI-T-50 (June, 1951).
- (9) Schwope, A. D. , Muehlenkamp, G. T. , "Tensile-Creep Properties at 500 F of Zirconium and 3.66 Per Cent Uranium Alloy of Zirconium", BMI-779 (November, 1952).
- (10) "Monthly Technical Progress Report", WAPD-MR-13 (January, 1951).
- (11) Unpublished information, Knolls Atomic Power Laboratory (July, 1954).
- (12) Saller, H. A. , Stacy, J. T. , Eddy, H. S. , and Klebanow, H. L. , "Creep Strength of Uranium Alloys at 1500 and 1800 F", BMI-834 (May, 1953).
- (13) Lillie, D. W. , "Uranium Newsletter No. 8", WASH-155 (August, 1954).
- (14) Epremian, E. , "Uranium Alloy Newsletter No. 11", WASH-198 (May, 1955).
- (15) Lillie, D. W. , "Uranium Alloy Newsletter No. 4", WASH-125 (August, 1953).
- (16) Epremian, E. , "Uranium Alloy Newsletter", WASH-700 (November, 1956).

PHYSICAL PROPERTIES OF ZIRCONIUM- URANIUM ALLOYS

Walston Chubb

Those physical properties of zirconium-uranium alloys which are available and which may be useful in the design of experiments, or for engineering applications, are included in this section. These properties include density, resistivity, thermal conductivity, thermal-expansion coefficients, and diffusion coefficients.

Various other properties which are known for uranium and for zirconium, but not for their alloys, have been omitted.

Density

The density of zirconium-uranium alloys is shown in Figure 43.⁽¹⁻⁵⁾ Data for iodide and sponge zirconium-base alloys, regardless of heat treatment or history, fall approximately on the curve. Calculations show that the curve drawn corresponds closely with the law of mixtures.

Resistivity

The resistivity of zirconium-uranium alloys prepared by a variety of techniques is shown in Figure 44.^(3,6-11) The peak in resistivity corresponds with the epsilon phase. It can be seen by comparison of the curves for room temperature and 200 C (390 F) that the resistivity of alpha zirconium and of alpha uranium increases with temperature, while that of epsilon decreases with increasing temperature.

Thermal Conductivity

The thermal conductivity of alloys across the system zirconium-uranium have been determined. Part of the available data are shown in Figure 45.^(2,6,9,12,13) Data for intermediate temperatures were available, but were not included.

Based on electrical-conductivity and thermal-conductivity data for a series of specimens across the system, but for temperatures only up to 200 C (390 F), an attempt was made to develop a relationship between the two properties. It was found that the Lorenz ratios calculated for the Wiedemann-Franz relation varied greatly with composition, and inadequate information was available to establish a relation for the system as a whole.⁽¹⁴⁾ An empirical relation has been established which applies to zirconium alloys containing up to 14 w/o uranium.⁽¹⁵⁾ Although it has not been done, a similar relation could be established for the uranium-rich alloys.

FIGURE 43. DENSITY OF ZIRCONIUM-URANIUM ALLOYS

FIGURE 44. RESISTIVITY OF ZIRCONIUM-URANIUM ALLOYS.

A-15187

FIGURE 45. THERMAL CONDUCTIVITY OF ZIRCONIUM-URANIUM ALLOYS

Thermal Expansion

The linear-thermal-expansion coefficients of uranium, and of zirconium to some extent, are affected by preferred orientations developed by fabrication procedures. Therefore, when comparing data it is important to know the fabrication and heat-treatment history of the specimens. Since expansion coefficients of zirconium-uranium alloys increase rapidly with temperature, the temperature range over which the data are applicable must be stated also.

Thermal-expansion coefficients of zirconium, uranium, and representative alloys are given in the following tabulation:

Uranium Content (Balance Zirconium)		Temperature Range, C	Mean Thermal- Expansion Coefficient, $\mu\text{in.}/\text{in.}/\text{C}$	Reference	Sample History
w/o	a/o				
100 Zr	100 Zr	20-200	5.7	(1)	Cold worked and alpha annealed
100 Zr	100 Zr	25	5.9	(16)	Ditto
20	9	20-300	7.0	(17)	Furnace cooled from 1000 C
20	9	20-550	7.2	(17)	Ditto
22	10	20-300	7.0	(9)	Furnace cooled from 900 C
22	10	20-550	7.7	(9)	Ditto
41	21	20-300	9.4	(9)	Furnace cooled from 815 C
41	21	20-550	10.2	(9)	Ditto
50	28	20-300	8.6	(17)	Furnace cooled from 1000 C
50	28	20-550	9.6	(17)	Ditto
50	28	650-1000	14.1	(17)	Ditto
60	36.5	20-300	9.5	(17)	Ditto
60	36.5	20-550	10.4	(17)	Ditto
80	60	20-300	12.1	(17)	Ditto
80	60	20-550	13.2	(17)	Ditto
100	100	-170-25	13	(18)	Cast and beta annealed
100	100	25-125	14.5	(19)	Calculated from X-ray data

More complete representation of the thermal-expansion behavior of a metal or alloy can be achieved by use of actual dilation curves. Representative heating curves for a variety of zirconium-uranium alloys are shown in Figure 46. These curves were obtained on arc-melted sponge-zirconium-base alloys which were randomized by heating to 900 or 1000 C (1650 to 1830 F) and furnace cooled. For sponge-zirconium-base alloys, 1000 C (1830 F), is probably somewhat low for complete randomization since

a. Zirconium-20 w/o (9 a/o) Uranium

b. Zirconium-22 w/o (10 a/o) Uranium

c. Zirconium-50 w/o (28 a/o) Uranium

d. Zirconium-80 w/o (60 a/o) Uranium

FIGURE 46. DILUTION CURVES FOR FOUR ZIRCONIUM-URANIUM ALLOYS

oxygen-rich alpha-zirconium particles may remain undissolved for short times at this temperature.

As indicated by the first two dilation curves, a variety of dilation effects can be observed on heating and cooling alloys containing about 15 to 30 w/o (6 to 14 a/o) uranium through the transformation range. Zirconium contracts on transforming from alpha zirconium to the body-centered-cubic solid solution while epsilon expands when it transforms. Alloys near 20 w/o uranium may contain nearly equal proportions of alpha zirconium and epsilon, and the dilation curve obtained on these alloys through the temperature range 600 to 800 C (1110 to 1470 F) will be dependent upon the orientation of the phases relative to each other and relative to the measuring apparatus. Dimensional growth caused by ratcheting has been observed in alloys containing about 20 w/o (9 a/o) uranium which have not been randomized after fabrication. The dilation curve for the zirconium-22 w/o (10 a/o) uranium alloy shows a net contraction as the result of both expansion and contraction in the temperature range from 600 to 800 C (1110 to 1470 F). This effect might have been caused by the presence of considerable alpha zirconium in the microstructure prior to testing. The dilation curve for the zirconium-20 w/o (9 a/o) uranium alloy shows a net expansion on heating from 600 to 700 C (1110 to 1290 F). This effect might have been caused by the presence of only a small amount of alpha zirconium in the microstructure prior to testing.

Diffusion Coefficients

A number of investigations of the rate of interdiffusion of zirconium and uranium have been made. These investigations included measurements of the rate of interdiffusion of sponge zirconium + 14 w/o (6 a/o) uranium alloy and sponge zirconium⁽²⁰⁾, of the rate of interface movement in diffusion between pure zirconium and pure uranium⁽²¹⁾, of the rate of interdiffusion of couples made from an iodide zirconium-41 w/o (21 a/o) uranium alloy and pure iodide zirconium⁽²²⁾ or Zircaloy-2⁽²³⁾, and of the rate of interdiffusion at very high temperatures between pure uranium and sponge zirconium⁽²⁴⁾ or iodide zirconium⁽²⁵⁾.

Representative results of some of these investigations are shown in Figure 47. Considering the differences in experimental techniques and in methods of calculating diffusion coefficients from analytical data, the results shown in Figure 47 show remarkably good agreement. These data suggest that at a given temperature the rate of interdiffusion of uranium and zirconium in the gamma phase is several times faster than the rate of diffusion of uranium in the alpha-zirconium phase. Interdiffusion of uranium and zirconium in the gamma solid solution has been found to be concentration dependent, with a minimum in diffusion rates near 47 w/o (25 a/o) uranium. This finding and the existence of an eutectoid at 44 w/o (23 a/o) uranium in this system are probably related. Figure 48 is a representation of the data for diffusion of uranium and zirconium at temperatures between 950 and 1075 C (1740 and 1970 F). Based on the data in Figures 47 and 48, the activation energy for diffusion of uranium in alpha zirconium in the temperature range from 594 to 865 C (1100 to 1590 F) is about 32,000 cal per mole; the activation energy for interdiffusion of uranium and zirconium in the temperature range from 950 to 1075 C (1740 to 1970 F) is dependent upon composition and varies from about 26,000 cal per mole at 86 w/o (70 a/o) uranium to 47,000 cal per mole at 12 w/o (5 a/o) uranium.

FIGURE 47. DIFFUSION OF URANIUM IN ALPHA AND BETA ZIRCONIUM

FIGURE 48. EFFECT OF COMPOSITION UPON THE RATE OF INTERDIFFUSION OF ZIRCONIUM AND URANIUM AT 950 TO 1075 C

References

- (1) Adenstedt, H. K. , "Physical Properties of Zirconium", Trans. ASM, 44 (1952).
- (2) Smith, K. F. , "Physical Properties of Zirconium and Zirconium-Uranium Alloys", ANL-4464 (April, 1951).
- (3) Kalish, H. S. , and Hausner, H. H. , "The Structures and Properties of Zirconium-Uranium Alloys", TID-5084 (June, 1952).
- (4) "Metallurgy Section Progress Report", KAPL-1149 (May, 1954).
- (5) Saller, H. A. , and Rough, F. A. , "Microstructure and Properties of Uranium Alloys", BMI-878 (October, 1953).
- (6) Nelson, H. R. , and Dayton, R. W. , "Progress Report for January, 1954", BMI-902 (February, 1954).
- (7) Udy, M. C. , and Boulger, F. M. , "The Properties of Zirconium Alloys, Part IV", BMI-T-50 (June, 1951).
- (8) Cook, L. A. , Castleman, L. S. , and Johnson, W. E. , "The Electrical Resistivity of Zirconium", WAPD-25 (December, 1950).
- (9) Deem, H. W. , BMI, Private Communication.
- (10) Balz, G. , "Electrical Behavior and Allotropy of Uranium", Metallforschung, 2 (May, 1947).
- (11) Ebert, H. , and Schulze, A. , "Electrical and Thermal Properties of Uranium", Metallforschung, 2 (February, 1947).
- (12) Droher, J. J. , "Thermal Conductivity of Uranium", TID-5185, Proceedings of the Metallurgy Information Meeting held at Argonne National Laboratory, April 19-21, 1954 (December, 1954).
- (13) McCreight, L. R. , "Thermal Conductivity Data of Some Nuclear Fuels", KAPL-822 (October, 1952).
- (14) Baroody, E. , BMI, Unpublished Information (1954).
- (15) Bing, G. , Fink, F. W. , and Thompson, H. G. , "The Thermal and Electrical Conductivities of Zirconium and Its Alloys", BMI-65 (April, 1951).
- (16) Russell, R. B. , "Coefficients of Thermal Expansion for Zirconium", Trans. AIME, 200 (September, 1954).

- (17) Kearns, J. J. , Private Communication (1957).
- (18) Schuch, A. F. , and Lacquer, H. L. , "Low Temperature Thermal Expansion of Uranium", Physical Review, 86 (June, 1952).
- (19) The Reactor Handbook, Vol 3, Section I, "General Properties of Materials", HELD-3647 (1955).
- (20) Schwope, A. D. , and Jackson, L. R. , "Diffusion Studies of the Zirconium-Uranium System", BMI-T-24 (April, 1950).
- (21) Mash, D. R. , and Disselhorst, B. F. , "Uranium-Zirconium Diffusion Studies", LRL-143 (June, 1954).
- (22) Dayton, R. W. , and Tipton, C. R. , Jr. , "Progress Report for July, 1954", BMI-937 (August, 1954).
- (23) Dayton, R. W. , and Tipton, C. R. , Jr. , "Progress Report for June, 1954", BMI-925 (July, 1954).
- (24) Adda, Y. , Philibert, J. , and Faraggi, H. , "Investigation of the Intermetallic Diffusion Phenomenon in the System Uranium Zirconium", Revue de Metallurgie, 54, 597 (August, 1957).
- (25) Kearns, J. J. , "Diffusion Measurements in the Uranium-Zirconium System", WASH-702 (May, 1957).

FABRICATING CHARACTERISTICS OF ZIRCONIUM ALLOYS
CONTAINING UP TO 50 w/o (28 a/o) URANIUM

S. J. Paprocki

Zirconium and uranium form a complete series of solid solutions at elevated temperatures. The alloys are readily fabricable at elevated temperatures as would be expected. However, the working of these alloys is complicated by the epsilon phase which exists at temperatures below about 600 C (1110 F), and has a composition of about 50 w/o (28 a/o) uranium. The epsilon phase is metallic in nature, but forms by a process which causes hardening during the transformation from gamma to epsilon. As a result, the alloys are very sensitive to heat treatment, especially in the composition range from 15 to 85 w/o (6.3 to 69 a/o) uranium.

For purposes of discussion, the alloys have been divided into two groups:

(1) alloys containing up to 20 w/o (9 a/o) uranium, and (2) alloys containing 20 to 50 w/o (9 to 28 a/o) uranium. This division is based largely on differences in heat-treating characteristics of the two groups, but, as will be seen, some of the fabricating characteristics of the two groups are also different. Alloys containing much more than 50 w/o uranium are not discussed, because such alloys have not been investigated extensively, except for alloys containing only a little zirconium.

Alloys Containing Up to 20 w/o (9 a/o) Uranium

Zirconium is a ductile metal that can be fabricated hot or cold with little concern about heat treatment. As uranium is added, up to 20 w/o (9 a/o) uranium, the alloys become progressively less ductile, and use of the proper heat treatment is essential for any cold-fabrication operations.

When gamma-treated and quenched, alloys containing up to 20 w/o uranium form martensitic structures. This martensite is relatively soft and, in the 10 w/o (4 a/o) uranium alloy, can be cold worked small amounts. Perhaps the best simple heat treatment for the production of a structure with cold ductility in this range is a slow furnace cool from 815 C (1500 F) or above. ⁽¹⁾ In this condition, the 10 w/o uranium alloy can be cold worked over 50 per cent by rolling.

Most heat treatments of the 19 w/o (8 a/o) uranium alloy result in some ductility, but the best results are obtained by heat treating in the gamma phase and furnace cooling or isothermally transforming in the alpha-plus-gamma phase field at 675 C (1250 F), followed by additional transforming just below the gamma-to-epsilon transformation. ^(2,3)

When 10 to 19 w/o (4 to 8 a/o) uranium alloys are cooled at some intermediate rate between quenching and furnace cooling, such as air cooling, acicular alpha

structures are formed. Available information suggests that these structures are less ductile than the structures produced by the treatments described above. They can be cold worked and recrystallized at temperatures in the epsilon region, or about 540 C (1000 F). However, this treatment is generally inferior to the gamma treatment. At about 19 w/o uranium, difficulty is encountered in cold working, regardless of heat treatment, because of increased hardness and lower ductility.

The 10 to 19 w/o uranium alloys can be hot fabricated most readily in the alpha-plus-gamma region, at about 675 C (1250 F). Successful hot fabrication of the 19 w/o alloy has been achieved over a range of temperatures from 540 to 730 C (1000 to 1350 F). This range includes both the alpha-plus-epsilon and alpha-plus-gamma regions. The 10 w/o uranium alloy has also been fabricated at 815 C (1500 F) with no difficulty, but the 19 w/o alloy is sensitive to surface chilling, which sometimes causes cracking during fabrication in the gamma. This sensitivity to surface chilling may be the result of the formation of a martensite structure on the surface. The behavior may be further complicated by surface age hardening similar to the 22 w/o (10 a/o) uranium alloy. This effect will be discussed below.

Important factors in the hot fabrication of the 19 w/o alloy are the size of the piece and the fabrication method. Since ingots of less than 10 lb were used in the work described above, surface chilling occurred. With larger ingots, or jacketed assemblies used in cladding and extrusion operations, surface temperatures will not drop so drastically, and the problem of surface chilling will be largely avoided.

Alloys Containing 20 to 50 w/o (9 to 28 a/o) Uranium

While alloys across the zirconium-uranium system have been forged and hot rolled, detailed fabrication studies have not been made beyond about 50 w/o (28 a/o) uranium, except for uranium-rich alloys. The following discussion, therefore, will be largely confined to alloys containing 22, 30, 40, 41, and 50 w/o (10, 14, 20, 21, and 28 a/o) uranium.

Alloys of 22 to 80 w/o (10 to 60 a/o) uranium will retain gamma when quenched rapidly from the beta region. When fully retained, beta is a soft, ductile phase. In the 22 w/o uranium alloy, however, initiation of decomposition occurs during quenching, and the alloy is very hard and brittle. The best heat treatment preparatory to cold working this alloy was found to be a slow furnace cool (50 to 100 C [100 to 200 F] per hr) from about 800 C (1475 F). The alloy can be recrystallized by annealing at about 540 C (1000 F), but furnace cooling from 800 C (1475 F) is more effective.^(4,5) An isothermal treatment used for the 19 w/o (8 a/o) alloy was unsatisfactory for the 22 w/o (10 a/o) alloy and produced brittle structures.^(3,4) A slightly different treatment consisting of annealing at 800 C (1475 F) and isothermally transforming at 620 C (1150 F) gives fair results in less time, but is inferior to the furnace-cooling treatment. In a 30 w/o (14 a/o) uranium alloy the best cold fabricability was obtained by treating 1 hr at 650 C (1200 F) and furnace cooling. This treatment was more satisfactory than furnace cooling from the gamma, but the reason is not apparent.

In alloys of 40 to 60 w/o (20 to 36 a/o) uranium, gamma can be fully retained, but only in thin sections. As a result, gamma-quenched 40 w/o (20 a/o) uranium alloy

specimens can be cold worked up to 50 per cent, but this applies only to specimens up to about 3/16 in. in thickness or diameter. (2,6) Thin sections of 50 w/o (28 a/o) uranium alloy have been treated in a similar fashion, but no data are available on the thickness of sections that can be effectively quenched.

Perhaps the most experience in fabrication has been obtained with the 22 w/o (10 a/o) uranium alloy. It has been extruded successfully in the gamma range. In this work, it was necessary to heat treat at 900 C (1650 F), or hot work, before extrusion in order to get smooth surfaces. The purpose of heat treating, or hot working, was to homogenize the cast structure. A steel can, instead of copper, also aided in the production of smooth, extruded surfaces. Friction during extrusion was minimized by the use of a stainless steel nose. Using these techniques, billets were extruded with a reduction ratio of 30 to 1. (7) This alloy has also been successfully hammer forged at temperatures of 750 to 815 C (1375 to 1500 F) (7), but when hot rolled in the gamma it is very sensitive to surface chilling, which causes cracking. This is probably the result of the start of decomposition of the gamma phase, which can produce a very hard, brittle structure in this alloy. However, there is no proof that the cracking is caused by this effect. The best hot-rolling temperature for the 22 w/o (10 a/o) uranium alloy is in the alpha-plus-gamma region at about 675 C (1250 F), where surface chilling is not a problem. The 30 w/o (14 a/o) alloy has been fabricated in a similar fashion. (8)

As the alloy content increases from 22 w/o to 50 w/o (10 to 28 a/o) uranium, the temperature at which gamma is stable is progressively lower. This seems to correlate with the observation that the 40 and 50 w/o (20 and 28 a/o) uranium alloys are insensitive to the effects of surface chilling.

The 40 and 50 w/o alloys have been hot fabricated by a variety of techniques. The 40 w/o (20 a/o) alloy has been hot rolled in the gamma range, 815 to 870 C (1500 to 1600 F) (6,9,10), and has also been extruded satisfactorily in the gamma range with a reduction ratio of 15 to 1 (10). The 50 w/o (28 a/o) alloy has been fabricated at 675 C (1250 F), and has been coextruded with a Zircaloy-2 cladding to give reductions of 40 to 50 per cent at 700 to 925 C (1300 to 1700 F).

Discussion

The data presented indicate that all of the alloys discussed can be fabricated by a variety of techniques. The best conditions of fabrication are determined not only by the constitutional diagram and heat-treating characteristics, but also by the type of fabrication, such as extrusion, forging, and rolling, and by the size and geometry of the piece to be fabricated.

The hot-hardness data presented in the section "Strength Characteristics of Zirconium-Uranium Alloys" can be a useful aid in understanding and selecting fabrication procedures. However, these data should be used in conjunction with available data on the heat treatment and transformation of these alloys. Similarly, in roll-cladding studies, roll-pressure data may be particularly useful in determining

temperatures where the fabrication characteristics of the core and cladding materials are compatible, but the temperature selected must be one where good bonding will occur.

Many of the fabrication studies discussed have been directed toward the production of pin-type fuel elements. For most of the alloys, extrusion is the most desirable process for making pins. Generally, there is less danger of failure during extrusion due to improper heat treatment, or to chilling, as compared with a process involving rolling, swaging, and drawing.

References

1. Dayton, R. W., and Tipton, C. R., Jr., "Progress Report for May, 1954", BMI-920 (June, 1954).
2. Chubb, W., Muehlenkamp, G. T., and Manning, G. K., "The Properties and Heat Treatment of Zirconium-Uranium Alloys", BMI-973 (January, 1955).
3. Nelson, H. R., and Dayton, R. W., "Progress Report for February, 1954", BMI-905 (March, 1954).
4. "Metallurgy Section Progress Report", KAPL-1149 (May, 1954).
5. Dayton, R. W., and Tipton, C. R., Jr., "Progress Report for July, 1954", BMI-937 (August, 1954).
6. Burke, J. E., and White, D. W., "Report of the Metallurgy Section", KAPL-1039 (November, 1953).
7. Van Tassel, K. R., White, D. W., Holden, A. N., and Cashin, W. M., "Report of the Metallurgy Section", KAPL-1196 (August, 1954).
8. Dayton, R. W., and Tipton, C. R., Jr., "Progress Report for December, 1954", BMI-972 (January, 1955).
9. Nelson, H. R., and Dayton, R. W., "Progress Report for January, 1954", BMI-902 (February, 1954).
10. Van Tassel, K. R., White, D. W., Holden, A. N., and Cashin, W. M., "Report of the Metallurgy Section", KAPL-1093 (February, 1954).

THE CORROSION BEHAVIOR OF ZIRCONIUM-URANIUM ALLOYS

Warren E. Berry

This section is devoted to a review and evaluation of the corrosion data in the literature. Particular emphasis has been placed on the corrosion behavior of zirconium-7 through 95 w/o (2.7 through 88 a/o) uranium alloys in high-temperature water up to 360 C (680 F). Where possible, data from several sources have been compared and the effects of composition, heat treatment, and microstructure on corrosion resistance have been interpreted.

Corrosion Behavior of Uranium

Unalloyed uranium has poor corrosion resistance and tarnishes readily in humid air at room temperature. It corrodes rapidly in water at 100 C (212 F) to form a loosely adherent nonprotective coating of uranium dioxide.^(1, 2) Corrosion rates have been reported ranging from -2.5 to -4.9 mg/(cm²)(hr)*, depending upon the metal purity and heat treatment. Gamma quenching appears to improve corrosion resistance of impure uranium somewhat, with rates of -3.3 mg/(cm²)(hr), reported, as compared with -4.9 mg/(cm²)(hr) for alpha-annealed material.⁽³⁾

The corrosion resistance of unalloyed uranium is sensitive to dissolved gases in the test water.⁽²⁾ Dissolved hydrogen increases corrosion rates at test temperatures up to 70 C (160 F). Protective oxide films are formed in aerated water and initial corrosion rates are low. However, at temperatures above 70 C (160 F), or after extended exposures, corrosion rates approach those obtained in hydrogen-saturated water.

The rate of reaction of uranium with water is extremely rapid at temperatures above 100 C (212 F). A corrosion rate of -6260 mg/(cm²)(hr) has been reported for exposure in water at 308 C (587 F).^(4, 5)

Corrosion Behavior of Zirconium

The corrosion behavior of zirconium and several of its alloys in water at temperatures up to 360 C (680 F) has been well established and is summarized in several publications.^(6, 7) Good-quality zirconium corrodes in 315 C (600 F) water at a rate in the neighborhood of 10⁻⁵ mg/(cm²)(hr) to form an adherent protective film of ZrO₂.⁽⁸⁾ It has been found that after the film reached a certain thickness it breaks up and is no longer protective.^(6, 7) The resulting sharp increase in corrosion rate has been known as "breakaway". For crystal-bar zirconium, this occurs in excess of a 1-year exposure in 315 C (600 F) water.

Minor compositional variables greatly influence the corrosion behavior of zirconium. Early failure occurs when the following composition limits are exceeded: 50 ppm

*Minus signs are employed here to indicate weight losses.

nitrogen, 400 ppm carbon, or 1000 ppm aluminum or titanium. (6, 7) The impurities in crystal-bar and sponge zirconium are below the above-mentioned amounts. On the other hand, it is believed that zirconium corrodes fairly rapidly unless small amounts (approximately 500 ppm) of iron and/or nickel are present. In addition to approximately 500 ppm iron, sponge zirconium contains approximately 1000 ppm oxygen, an amount which does not affect its corrosion resistance appreciably.

The effect of heat treatment on the corrosion behavior of zirconium has not been established. There are indications that arc-melted sponge exhibits impaired resistance when quenched from temperatures above the alpha-beta zirconium transformation. (7)

The principal corrosion-resistant alloy of zirconium is Zircaloy-2, which contains 1.5 w/o tin, 0.12 w/o iron, 0.10 w/o chromium, and 0.05 w/o nickel.

Corrosion of Binary Alloys in 100 C (212 F) Water

Most investigations of high-uranium low-zirconium alloys have been directed toward applications in low-temperature water-cooled reactors. Numerous sites have studied the 100 C (212 F) water corrosion behavior of zirconium-uranium alloys. (1, 2, 9-19)

It has been shown that, under certain conditions, alloys containing up to 95 w/o (88 a/o) uranium form a tarnish film and exhibit little or no weight change when exposed to 100 C (212 F) water. (1, 2, 11, 12) Such alloys must be rapidly quenched from above 700 C and the test water must contain sufficient oxygen to maintain a protective oxide film. Of the alpha-annealed alloys (heat treated just below the alpha-to-beta uranium transformation temperature), only those containing less than 80 w/o (60 a/o) uranium are resistant in boiling water. (11, 16) These data are summarized in Table 10.

TABLE 10. SURVEY OF CORROSION DATA ON ZIRCONIUM-URANIUM ALLOYS TESTED IN 100 C (212 F) WATER

Heat Treatment	Uranium, w/o, in Alloys That Exhibited Protective Tarnish Films for Time Indicated		
	Less Than	Less Than	
	24 Hr	1 Week	10 Months
1 hr 600 C (1110 F) and furnace cooled	91-100	82-89	0-80
1 hr 800 C (1470 F) and water quenched	96-100	--	0-94
1 hr 800 C (1470 F) and water quenched, and 1 hr 600 C (1110 F) and furnace cooled	96-100	89-94	0-82
1 hr 700 C (1300 F) and water quenched	96-100	--	0-94

Corrosion rates of alloys prepared at several sites are compared in Figure 49. (11, 14, 16) The variance in results can be accounted for in part by the difference in heat treatment employed by the several laboratories. Another variable is the control of dissolved gases in the test water since it already has been noted that dissolved oxygen can influence corrosion behavior of some of these alloys.

The best corrosion resistance for the very high uranium-binary alloys is obtained by a gamma-quenching heat treatment. Alloys containing more than 80 w/o (60 a/o) uranium transform by a martensitic-type reaction when quenched from the gamma-phase field. X-ray diffraction studies of water- and oil-quenched 94 to 96 w/o (86 to 90 a/o) uranium alloys have shown no lines that cannot be assigned to alpha uranium. (20) Subsequent annealing yields a fine precipitate, presumably epsilon, indicating a super-saturated alpha uranium.

The poor corrosion resistance of alpha-annealed high-uranium alloys can be attributed to the presence of alpha uranium. In alloys containing less than 80 w/o (60 a/o) uranium, apparently there is sufficient epsilon to form a continuous protective corrosion film, or the alpha uranium is dispersed in and surrounded by the epsilon phase so that it is no longer a major factor in the corrosion process.

Corrosion of Binary Alloys in High-Temperature Water

A considerable amount of corrosion data has been reported for binary zirconium-uranium alloys exposed in high-temperature water. Several investigations have covered the entire range of alloy compositions (21-27), while others have been concerned with one or two alloys (5, 16, 28-37). In general, only alloys containing less than 60 w/o (36 a/o) uranium survive prolonged exposure in 360 C (680 F) water. (21, 25, 27, 34) Alloys of higher uranium content are completely oxidized within several days of exposure. Zirconium-70 w/o (47 a/o) uranium alloys are fairly resistant to 260 C (500 F) water (21, 25, 27), while 90 w/o (77 a/o) alloys are fairly resistant to 178 C (352 F) water (28).

Corrosion rates obtained from several sources for zirconium-uranium alloys in 315 C (600 F) and 360 C (680 F) water are compared in Figures 50 and 51. (14, 21, 25, 26, 30-33) The general trend is for corrosion rates to increase as uranium content increases. However, at a given composition level, corrosion rates may vary considerably. These variations can be explained on the basis of differences in amount and distribution of alloy phases as affected by oxygen content and prior heat treatment.

Corrosion of Equilibrium Alloys

It has been shown that the amount and distribution of phases in equilibrium zirconium-uranium alloys influence corrosion behavior. (25) Alloys of more than 60 w/o (36 a/o) uranium contain sufficient alpha uranium to cause rapid failure in high-temperature water.

FIGURE 49. CORROSION RATES OF ZIRCONIUM-URANIUM ALLOYS IN 100 C (212 F) WATER

FIGURE 50. CORROSION RATES OF ZIRCONIUM-URANIUM ALLOYS
IN 315 C (600 F) WATER

FIGURE 51. CORROSION RATES OF ZIRCONIUM-URANIUM ALLOYS
IN 360 C (680 F) WATER

Alloys containing 30 to 55 w/o (14 to 32 a/o) uranium are predominantly epsilon and epsilon is usually the matrix phase. Since alpha zirconium is much more resistant than epsilon, it should be encircled and dislodged during corrosion of such alloys. It has been demonstrated that corrosion rates of alloys in this range fall within limits calculated from corrosion rates of epsilon of 45 and 55 w/o (24 to 32 a/o) uranium composition, as shown in Figure 52.⁽²⁵⁾ The failure of the crystal-bar zirconium-30 and -40 w/o (14 and 20 a/o) uranium alloys in this series to fall within these limits is explained by the presence of alpha zirconium at grain boundaries acting as a barrier. On the other hand, the abnormally high rate of the sponge zirconium-15 w/o (6.3 a/o) uranium alloy fell near the calculated limits. Examination of the microstructure of the alloy revealed that the epsilon phase was continuous and completely surrounded the alpha zirconium.

Alpha zirconium occupies the larger volume in alloys containing less than 30 w/o (14 a/o) uranium and influences corrosion behavior. Although alpha zirconium is usually the matrix phase, attack is not stifled after surface-exposed epsilon is corroded away. Apparently, the uranium oxide in the corrosion product prevents the zirconium oxide from forming a protective film.

Effect of Oxygen

Oxygen influences corrosion behavior of equilibrium zirconium-uranium alloys through its effect on the stability of the epsilon phase. It has been shown that the epsilon phase exists over the composition range of about 45 to 53 w/o (24 to 30 a/o) uranium and that, as the oxygen content of a zirconium-rich alloy increases, the epsilon composition is pushed toward the higher uranium content.⁽³⁸⁾ Above certain oxygen levels, epsilon no longer exists and only the terminal phases of alpha uranium and alpha zirconium are present.⁽³⁹⁾

Since epsilon is the predominant phase over the middle portion of the alloy system, it follows that oxygen should influence corrosion behavior. It has been shown that, in the range of 30 to 70 w/o (14 to 47 a/o) uranium, increasing oxygen content results in increased corrosion rates at a given alloy composition.⁽²⁵⁾ These results are summarized in Table 11, and are depicted graphically in Figure 53. There is little or no effect on corrosion behavior of up to 0.3 w/o oxygen in alloys containing less than 22 w/o (10 a/o) uranium.

Effect of Cooling Rate From Above Transformation Temperature

The effect of cooling rate from above the transformation temperature on the corrosion behavior of binary zirconium-uranium alloys is quite pronounced. Alloys containing about 0 to 20 or 75 to 100 w/o (0 to 9 or 54 to 100 a/o) uranium undergo a martensitic-type transformation when rapidly quenched from the gamma phase. These alloys are more corrosion resistant than similar alloys which are alpha annealed. In general, gamma-quenched zirconium-7 to 20 w/o (2.7 to 9 a/o) uranium alloys exposed in high-temperature water exhibit thin dark films and small weight gains in much the same fashion as unalloyed zirconium.^(21, 30, 35, 36) After continued exposure in 360 C

FIGURE 52. CORROSION RESULTS OBTAINED WITH ZIRCONIUM-URANIUM ALLOYS IN 680 F HIGH-PURITY WATER(25)

Dashed lines define limits of corrosion rates which would be obtained if epsilon were the matrix phase.

TABLE 11. CORROSION RESULTS OBTAINED FOR EQUILIBRIUM ZIRCONIUM-URANIUM ALLOYS EXPOSED IN HIGH-TEMPERATURE HIGH-PURITY WATER⁽²⁵⁾

Nominal Uranium Content (Balance Zirconium)			Weight-Loss Rate, mg/(cm ²)(hr), in Water at Temperature Indicated				
w/o	a/o	Zirconium Melting Stock	500 F ^(a)	550 F ^(b)	600 F ^(c)	640 F ^(b)	680 F ^(c)
7	2.7	Crystal bar	0.00027	0.0020	0.0056	0.013	0.024
		Sponge	0.00050	0.0024	0.0073	0.010	0.017
		Sponge-0.3 w/o oxygen	0.00024	0.0040	0.0052	0.0091	0.017
10	4	Crystal bar	0.00026	0.0028	0.0073	0.016	0.029
		Sponge	No alloy				
		Sponge-0.3 w/o oxygen	0.00070	0.0059	0.010	0.015	0.026
15	6.3	Crystal bar	0.00098	0.0039	0.010	0.018	0.037
		Sponge	0.0031	0.025	0.059	0.097	0.15
		Sponge-0.3 w/o oxygen	0.0014	0.0067	0.016	0.023	0.043
22	10	Crystal bar	0.0015	0.0064	0.019	0.033	0.052
		Sponge	0.0049	0.010	0.032	0.052	0.082
		Sponge-0.3 w/o oxygen	0.0029	0.013	0.043	0.057	0.12
30	14	Crystal bar	0.0016	0.0089	0.019	0.034	0.068
		Sponge	0.0049	0.017	0.054	0.075	0.15
		Sponge-0.3 w/o oxygen	0.0051	0.027	0.063	0.11	0.21
40	20	Crystal bar	0.0028	0.013	0.031	0.053	0.095
		Sponge	0.0050	0.020	0.052	0.092	0.17
		Sponge-0.3 w/o oxygen	0.0050	0.027	0.063	0.12	0.21
45	24	Crystal bar	0.0029	0.018	0.040	0.072	0.12
		Sponge	0.0043	0.020	0.051	0.084	0.16
		Sponge-3.0 w/o oxygen	0.0044	0.021	0.055	0.091	0.16
50	28	Crystal bar	0.0036	0.025	0.057	0.094	0.16
		Sponge	0.0057	0.032	0.071	0.12	0.20
		Sponge-3.0 w/o oxygen	0.0075	0.029	0.083	0.13	0.23
55	32	Crystal bar	0.0069	0.032	0.068	0.10	0.17
		Sponge	0.0064	0.034	0.075	0.12	0.20
		Sponge-3.0 w/o oxygen	0.0091	0.042	0.093	0.15	0.30
60	36	Crystal bar	0.0065	0.031	0.069	0.12	0.27
		Sponge	0.0082	0.039	0.082	0.15	0.31
		Sponge-3.0 w/o oxygen	0.017	0.069	0.20	0.34	0.77
70	47	Crystal bar	0.35	(d)	(d)	(d)	(d)
		Sponge	0.85	(d)	(d)	(d)	(d)
		Sponge-3.0 w/o oxygen	1.23	(d)	(d)	(d)	(d)

(a) Based on exposure times to 7000 hr.

(b) Based on exposure times to 2350 hr.

(c) Based on exposure times to 3700 hr.

(d) Completely oxidized after 168-hr exposure.

FIGURE 53. TEMPERATURE DEPENDENCY OF THE CORROSION RATE OF ZIRCONIUM-50 w/o URANIUM ALLOYS IN HIGH-TEMPERATURE WATER⁽²⁵⁾

(680 F) water, the adherent films became yellow in color. (30, 35, 36) Equilibrium alloys in the same composition range corrode to form nonprotective yellow films which eventually break up and allow the alloy to lose weight at a linear rate. (21, 25, 26, 30, 35, 36)

Alloys containing 80 to 100 w/o (60 to 100 a/o) uranium are not so resistant as those described above. However, the same effect of improved corrosion resistance as a result of gamma quenching has been reported. Gamma-quenched 90 w/o (77 a/o) alloys corrode at a moderate rate of $-0.027 \text{ mg}/(\text{cm}^2)(\text{hr})$ in 178 C (352 F) water, while attack is excessive on alpha-annealed 80 w/o (60 a/o) alloys under the same conditions. (28) However, gamma-quenched 95 w/o (88 a/o) alloys sometimes fail by cracking in water at temperatures as low as 100 C (212 F). (11)

The gamma phase can be retained in 20 to about 75 w/o (9 to 54 a/o) uranium alloys by rapid quenching. This treatment generally does not result in lower corrosion rates. (31, 32) However, during quenching or at test temperatures, gamma begins to transform to the equilibrium epsilon (or epsilon plus alpha) with an accompanying hardness increase. (40) Gamma-quenched samples in this composition range often fail prematurely by cracking. (21, 23, 31, 32) There is no evidence of hydride needles in the microstructures of cracked samples as in uranium-12 w/o molybdenum alloys. (26, 40) Cracking has been attributed to a combination of corrosion and stresses from the hardening reaction mentioned above. (42) This phenomenon has resulted in the rejection of some as-fabricated alloys in this composition range because of high hardness and subsequent cracking during corrosion testing.

Corrosion Behavior of Zirconium-Uranium Ternary Alloys

A large number of ternary systems have been studied in attempts to develop corrosion-resistant zirconium-uranium alloys. The major part of the work has been devoted to alloys containing more than 70 w/o or less than 10 w/o uranium. Objectives with the high-uranium alloys were to prevent rapid oxidation, while those with the low-uranium alloys were to produce a "stainless" alloy comparable in corrosion resistance to unalloyed zirconium. Recently, some studies have been made on ternaries of intermediate uranium content.

Zirconium-Uranium-Niobium Alloys

The addition of up to 10 w/o niobium to alloys containing 80 to 98 w/o uranium has been found to markedly increase their corrosion resistance in water at temperatures up to 360 C (680 F) if the alloys are rapidly quenched from around 800 C (1470 F). (2, 15, 21, 43-52) Particularly promising are a zirconium-88 w/o uranium-10 w/o niobium alloy which exhibits low corrosion rates in 360 C (680 F) water (33, 51) and a zirconium-94 w/o uranium-1 w/o niobium alloy which is fairly resistant in 260 C (500 F) water. (49) The corrosion resistance of 60 w/o uranium alloys is improved by niobium additions in the range of 3 to 5 w/o. (53) Niobium additions of less than 3 w/o do not improve corrosion resistance of this alloy. (53)

It should be pointed out that gamma-quenched binary uranium-3 to 10 w/o niobium alloys are fairly resistant to high-temperature water. They corrode at low rates, with 10 w/o alloys surviving 5 to 8 weeks of exposure in 360 C (680 F) water before transformation to alpha uranium and/or internal hydriding result in rapid oxidation.^(33, 54) Three to 6 w/o alloys last 2 to 3 weeks in 315 C (600 F) water and for longer periods in 260 C (500 F) and 300 C (570 F) water.⁽⁵⁵⁾

Zirconium-Uranium-Molybdenum Alloys

The effect of molybdenum additions on the high-temperature-water corrosion resistance of zirconium-uranium alloys has been investigated in the range of 1 to 10 w/o molybdenum and 50 to 98 w/o uranium.

In general, molybdenum additions do not improve the corrosion resistance of 50 through 90 w/o uranium alloys.^(21, 31, 56) Short-time tests indicate that additions of 2 to 7 w/o molybdenum to 91 w/o uranium alloys result in some improvement in corrosion resistance.⁽¹⁷⁾ Three and 5 w/o molybdenum additions to 60 w/o uranium alloys also improve corrosion resistance.⁽⁵³⁾ Binary uranium-molybdenum alloys themselves are fairly corrosion resistant. Corrosion rates of -0.1 to -0.2 mg/(cm²)(hr) are reported for uranium-12 w/o molybdenum alloys exposed to 343 C (650 F) water.⁽⁴¹⁾ These alloys survive 4 to 6 weeks of exposure under these conditions before they disintegrate from uranium hydride formation at grain boundaries.

Zirconium-Uranium-Tin Alloys

Additions of up to 2 w/o tin do not improve the corrosion resistance of 50, 60, or 80 w/o uranium alloys in high-temperature water.^(21, 31, 32)

It has been reported that additions of up to 5 w/o tin to 1.5 to 15 w/o uranium alloys improve corrosion resistance somewhat.^(1, 29, 57) The tin may overcome the adverse effects of contaminants in alpha zirconium, the major phase in these alloys.

Zirconium-Uranium-Tantalum Alloys

Tantalum additions of approximately 5 w/o improve the corrosion resistance of 50, 60, and 70 w/o uranium alloys in high-temperature water.^(21, 31) The role of tantalum in improving corrosion resistance is not yet fully known.

Other Ternary Alloys

A limited amount of work has been reported for other ternary alloys. The alloy compositions and the sources of information are presented in Table 12. Of these alloys only the zirconium-78 w/o uranium-2 w/o ruthenium was more corrosion resistant than the corresponding binary zirconium-uranium alloy.

TABLE 12. COMPOSITIONS OF TERNARY ALLOYS THAT HAVE BEEN INVESTIGATED FOR CORROSION BEHAVIOR AND FOUND INFERIOR TO THE CORRESPONDING ZIRCONIUM-URANIUM BINARY

Alloy Composition, w/o			
Zirconium	Uranium	Other	Reference
20	Balance	1-30 thorium	(21)
30	Balance	1-10 thorium	(21)
20	Balance	1 and 2 titanium	(21)
30	Balance	1.3 and 1.5 titanium	(21)
Balance	70	4.18-5.32 titanium	(56)
35 and 38	Balance	4.6 and 4.8 titanium	(31)
45-49.5	Balance	1-10.3 titanium	(31)
30	Balance	0.32 and 1.6 chromium	(21)
38	Balance	5.0 chromium	(31)
45-49.5	Balance	0.69-9.73 chromium	(31)
30	Balance	0.35 and 1.72 iron	(21)
40 and 50	Balance	0.05 and 0.2 iron	(32)
39.5	Balance	1.05 iron	(31)
49	Balance	0.48-2.04 iron	(31)
30	Balance	0.36 and 1.8 cobalt	(21)
30	Balance	0.36 and 1.8 nickel	(21)
40 and 50	Balance	0.08 and 0.19 nickel	(32)
39.5	Balance	0.98 nickel	(31)
49-49.75	Balance	0.53-1.94 nickel	(31)
30	Balance	0.75 and 3.74 antimony	(21)
30	Balance	0.86 cerium	(21)
30	Balance	1.12 and 5.66 tungsten	(21)
39	Balance	1.57 tungsten	(31)
48-49.5	Balance	0.4-2.64 tungsten	(31)
30	Balance	1.26 and 2.52 lead	(21)
30	Balance	1.27 and 6.4 bismuth	(21)
Balance	70	1.48 and 1.63 silicon	(56)
38	Balance	4.9 vanadium	(31)
45-49.5	Balance	0.98-9.8 vanadium	(31)
39	Balance	1.72 aluminum	(31)
48-49.5	Balance	0.96-4.0 aluminum	(31)
39.5	Balance	1.02 platinum	(31)
49-49.75	Balance	0.5-1.93 platinum	(31)
20	Balance	2.0 ruthenium(a)	(53)

(a) This alloy was superior to the zirconium-80 w/o uranium alloy.

Corrosion Behavior of Zirconium-Uranium Quaternary Alloys

Very little information has been reported on the corrosive behavior of quaternary zirconium-uranium alloys. There are indications that additions of 3 to 5 w/o niobium together with 3 w/o molybdenum improve the corrosion resistance of zirconium-80 and -90 w/o uranium alloys.⁽⁵³⁾

Discussion

Binary Alloys

The corrosion behavior of binary zirconium-uranium alloys in high-temperature water is influenced by the amount and distribution of phases in the alloys which in turn are affected by the oxygen content of the alloys and the prior heat treatment.

In general, corrosion rates of equilibrium alloys increase as uranium-alloy content increases. Alloys containing more than 60 w/o (36 a/o) uranium apparently have sufficient alpha uranium in their microstructure to cause rapid oxidation in water at temperatures above 260 C (500 F). In the range of 30 to 55 w/o (14 to 32 a/o) uranium, epsilon occupies the larger volume, is usually the matrix phase, and determines the corrosion resistance of the alloys. During corrosion, alpha zirconium, being more corrosion resistant, apparently is encircled in these alloys and the penetration rate of epsilon and the alloy's specific gravity determine weight-loss rates. In alloys containing less than 30 w/o (14 a/o) uranium, alpha zirconium occupies the larger volume, is usually the matrix phase, and influences corrosion behavior. However, attack is not completely stifled in these alloys when surface-exposed epsilon is corroded away and the water comes in contact with the alpha zirconium. Apparently, uranium oxide is incorporated in the zirconium corrosion film and prevents the latter from forming a protective film. It is conceivable that, through proper heat treatment, corrosion resistance could be improved in 30 to 45 w/o (14 to 24 a/o) uranium alloys by dispersing alpha zirconium as the matrix phase surrounding epsilon. Similarly, epsilon might be made to completely surround alpha uranium in alloys containing more than 60 w/o (36 a/o) uranium. However, efforts to accomplish the above results have met with little success.

The oxygen content in the alloys of intermediate uranium content influences corrosion resistance through its effect on the stability of the epsilon phase. As the oxygen content of an alloy increases, the epsilon composition is first pushed to the higher uranium limit and eventually begins to decompose to alpha uranium and alpha zirconium. Both of these phenomena decrease corrosion resistance. A certain amount of oxygen is difficult to avoid, since present-day sponge zirconium contains approximately 1000 ppm of oxygen.

The cooling rate from above the transformation temperature also influences corrosion behavior of zirconium-uranium alloys. The corrosion resistance of alloys containing 0 to 20 and 80 to 100 w/o (0 to 9 and 60 to 100 a/o) uranium is improved by rapid quenching from the gamma-phase field. However, the high-uranium alloys may fail by cracking. Gamma-quenched samples in the range of 20 to 80 w/o (9 to 60 a/o) uranium

also may fail prematurely by cracking during exposure in high-temperature water. Cracking in the latter is attributed to an increase in hardness resulting from the onset of transformation from the high-temperature phase to the equilibrium phases. This may occur during quenching or at the corrosion-test temperature. During fabrication, precautions should be taken to cool these alloys slowly to below the transformation temperature. This avoids retention of gamma and subsequent problems of high hardness and corrosion cracking.

Ternary Alloys

From a practical viewpoint, ternary additions to zirconium-uranium alloys to improve high-temperature-water corrosion resistance have not been particularly successful. In the quest for a "stainless" alloy in the low uranium range, tin additions improve corrosion resistance somewhat. In the high uranium range, molybdenum, niobium, ruthenium, and tantalum offer promise. However, in most of the latter alloys, the ternary addition is either higher than the zirconium content, or neutron capture by the ternary addition is so great that there is no economy in such an alloy. The zirconium-94 w/o uranium-1 w/o niobium alloy most nearly approaches the ideal concept of a minor ternary addition improving the corrosion behavior of a high uranium-zirconium alloy. However, its water-corrosion resistance is poor at temperatures above 260 C (500 F).

A possible approach to improving the corrosion resistance of high uranium-zirconium alloys is to tie up the free alpha uranium in equilibrium alloys in the form of a compound or intermediate phase. To date, preliminary efforts along these lines have not proved successful.^(53, 56) However, more work is needed in this area to establish definitely whether this type of alloy can be made corrosion resistant.

References

- (1) Waber, James T., "A Review of the Corrosion of Uranium and Its Alloys", LA-1524 (November 7, 1952).
- (2) McWhirter, J. W., and Draley, J. E., "Aqueous Corrosion of Uranium and Alloys: Survey of Project Literature", ANL-4862 (May 14, 1952).
- (3) Draley, J. E., and McWhirter, J. W., "Effects of Metal Purity and Heat Treatment on the Corrosion of Uranium in Boiling Water", ANL-5029 (April 14, 1953).
- (4) Grieser, D. R., and Simons, E. M., "Apparatus for Visual Study of Corrosion by Hot Water", BMI-998 (May 4, 1955).
- (5) Grieser, D. R., and Simons, E. M., "Aqueous Corrosion of Uranium Fuel-Element Cores Containing 0 to 20 w/o Zirconium", BMI-1156 (January 7, 1957).
- (6) Lustman, B., and Kerze, F., Metallurgy of Zirconium, Vol. 4, Div. VII, NNES, McGraw-Hill Book Company, New York (1955).

- (7) Thomas, D. E., "Aqueous Corrosion of Zirconium and Its Alloys at Elevated Temperatures", P/537, Vol IX, Peaceful Uses of Atomic Energy: Proceedings of the International Conference in Geneva (August, 1955).
- (8) Goldman, K. M., "Minutes of Meeting on the Corrosion of Zirconium Alloys", WAPD-MM-127 (July 18, 1952).
- (9) Lillie, D. W., "Uranium Alloy Newsletter No. 4", WASH-125.
- (10) Burke, J. E., and White, D. W., "Report of the Metallurgy Section", KAPL-1039 (November, 1953).
- (11) Pray, H. A., and Berry, W. E., "Corrosion of Uranium-Zirconium Alloys in Water at Temperatures up to 100 C", BMI-893 (December 16, 1953).
- (12) Draley, J. E., McWhirter, J. W., Field, F., and Guon, J., "The Corrosion of Low Zirconium-Uranium Alloys in Boiling Water", ANL-5030 (April 14, 1953).
- (13) Lillie, D. W., "Uranium Alloy Newsletter No. 3", WASH-124 (May 27, 1953).
- (14) Lillie, D. W., "Uranium Alloy Newsletter No. 1", WASH-120 (January 29, 1953).
- (15) "Reactor Engineering Division Quarterly Report for December 1, 1953, through March 4, 1954", ANL-5260 (April 15, 1954).
- (16) Chiotti, P., and Carlson, O. N., unpublished information, Iowa State College (February 15, 1954).
- (17) Lillie, D. W., "Uranium Alloy Newsletter No. 2", WASH-123.
- (18) Saller, H. A., Pray, H. A., Dickerson, R. F., Berry, W. E., and Foster, E. L., Jr., "Corrosion Evaluation of Binary Uranium Alloys in Water at 100 C", BMI-971 (December 27, 1954).
- (19) Ruther, W. E., and Seefeldt, W. B., "Aqueous Corrosion of Uranium and Uranium-6 w/o Zirconium Alloy", ANL-5672 (January 9, 1957).
- (20) Foote, F. G., and Schumar, J. F., "The Metallurgy Division Quarterly Report for July, August, and September, 1952", ANL-4923 (September 30, 1952).
- (21) Pray, H. A., and Berry, W. E., "Corrosion of Uranium Alloys in High-Temperature Water", BMI-874 (October 5, 1953).
- (22) Thomas, D. E., "Corrosion of Zirconium-Uranium Alloys", WAPD-MDM-24 (December 29, 1954).
- (23) Bostrom, W. A., Burkart, M. W., Halteman, E. K., Leggett, R. D., McGeary, R. K., and Padden, T. R., "Development and Properties of Uranium-Base Alloys Corrosion Resistant in High-Temperature Water, Part I - Alloys Without Protective Cladding", WAPD-127 (April 25, 1955).

- (24) Unpublished information, Bettis Atomic Power Division (November 20, 1955).
- (25) Berry, W. E., and Peoples, R. S., "The Corrosion Behavior of Zirconium-Uranium Alloys in High-Temperature Water", *Corrosion*, 14 (9), 414t-418t (September, 1958).
- (26) Kass, S., and Goldman, K. M., "Corrosion Behavior of Uranium-Zirconium Alloys in High Temperature Water and Steam", WAPD-T-416 (April, 1958).
- (27) Bauer, A. A., Kass, S., and Goldman, K. M., "Physical Metallurgy and Properties of Zirconium-Uranium Alloys", Second International Conference on the Peacetime Uses of Atomic Energy, held at Geneva Switzerland September 1-13, 1958.
- (28) Chiotti, P., and Carlson, O. N., unpublished information, Iowa State College (May 24, 1954).
- (29) Kass, S., "The Corrosion Properties of Zirconium-Base Fuel Alloys", WAPD-136 (November 2, 1955).
- (30) Merten, V., and Belouin, D. C., "Corrosion Behavior of Zirconium-Base Uranium Alloys", KAPL-1570 (June 15, 1956).
- (31) Reynolds, J. E., Berry, W. E., Ogden, H. R., Peoples, R. S., and Jaffee, R. I., "The Effects of Ternary Alloy Additions on the Corrosion Resistance of Epsilon Phase Uranium-Zirconium Alloys", BMI-1087 (April 27, 1956).
- (32) Berry, W. E., Reynolds, J. E., Ogden, H. R., Peoples, R. S., and Jaffee, R. I., "Effects of Impurities on the Corrosion Behavior of Zirconium-Uranium Alloys", BMI-1130 (September 13, 1956).
- (33) Unpublished information, Bettis Atomic Power Division (May, 1956).
- (34) Dayton, R. W., and Tipton, C. R., Jr., "Progress Relating to Civilian Applications During January, 1957", BMI-1161 (February 1, 1957).
- (35) Unpublished information, Knolls Atomic Power Laboratory (November 14, 1957).
- (36) Belouin, D. C., "The Corrosion Behavior of Some Zirconium 8 w/o Uranium Alloys in 680 F Water", KAPL-M-DCB-1 (December 5, 1956).
- (37) Salmons, B. H., unpublished information, United Kingdom (January, 1957).
- (38) Rough, F. A., Austin, A. E., Bauer, A., and Doig, J. R., "The Stability and Existence of the Zirconium-Epsilon Phase", BMI-1092 (May 28, 1956).

- (39) Saller, H. A., Rough, F. A., and Bauer, A. A., "The Effect of Oxygen on Zirconium-Uranium Epsilon-Phase Alloys", Paper No. 57-NESC-20, The Second Nuclear Engineering and Science Conference, Philadelphia, (March 11-14, 1957).
- (40) Saller, H. A., Rough, F. A., and Chubb, W., "An Experimental Survey of the Heat Treatment Response of Some Zirconium-Uranium Alloys", BMI-1096 (June 14, 1956).
- (41) Lustman, B., "Résumé of Uranium Alloy Data - VIII", WAPD-PMM-15 (February 25, 1954).
- (42) Dayton, R. W., and Tipton, C. R., Jr., "Progress Relating to Civilian Applications During April, 1956", BMI-1088 (May 1, 1956).
- (43) "Progress (A-1) Report for Month of June, 1945", MIT, CT-3194 (July 10, 1945).
- (44) Foote, F., "Summary Report for Month of June, 1945 - Metallurgy Division", University of Chicago, CT-3071 (July 9, 1945).
- (45) Foote, F., "Summary Report for Month of May, 1945 - Metallurgy Division", University of Chicago, CT-3011 (June 5, 1945).
- (46) Greninger, A. B., "Report for Month of April, 1945 - Metallurgy Division", University of Chicago, CT-2925 (May 8, 1945).
- (47) Greninger, A. B., "Report for Month of March, 1945 - Metallurgy Division", University of Chicago, CT-2794 (April 12, 1945).
- (48) Dwight, A. E., and Roebuck, A. H., "Preliminary Report on Corrosion of Uranium-Base Alloys Continuing Niobium and Zirconium", ANL-5376 (December 19, 1954).
- (49) Draley, J. E., Greenberg, S., and Ruther, W. D., "The High-Temperature Aqueous Corrosion of Uranium Alloys Containing Minor Amounts of Niobium and Zirconium", ANL-5530 (April, 1957).
- (50) McGeary, R. K., and Justusson, W. M., "Corrosion-Resistant Uranium Alloys", WAPD-MM-227 (June, 1953).
- (51) Unpublished information, Bettis Atomic Power Division (November, 1956).
- (52) Dayton, R. W., and Tipton, C. R., Jr., "Progress Relating to Civilian Applications During October, 1957", BMI-1232 (November 1, 1957).
- (53) Storhok, V. W., Bauer, A. A., and Dickerson, R. F., "Survey of Ternary and Quarternary Metastable Gamma-Phase Uranium Alloys", BMI-1278 (July 15, 1958).

- (54) Hodge, E. S., Berry, W. E., Beatty, G. H., Paprocki, S. J., and Peoples, R. S., "Effect of Impurities on the Corrosion Behavior of Uranium-10 w/o Niobium Alloys in 680 F Water", BMI-1159 (January 24, 1957).
- (55) Draley, J. E., "Status of Development of Corrosion-Resistant Uranium Alloys", ANL-EF-409b (November 12, 1953).
- (56) Dayton, R. W., and Tipton, C. R., Jr., "Progress Relating to Civilian Applications During February, 1957", BMI-1173 (March 1, 1957).
- (57) Dwight, D. E., and Roebuck, A. H., "Preliminary Report on the Corrosion of Low-Uranium Zirconium-Base Alloys", ANL-5196 (October, 1953).

IRRADIATION PERFORMANCE OF ZIRCONIUM-URANIUM ALLOYS

Arthur A. Bauer

Zirconium-uranium alloys when irradiated are subject to damage by fission fragments and fast neutrons. The resultant atom displacements can cause marked changes in physical and mechanical properties. However, the most important effect which accompanies the irradiation of any fuel is a change in volume. This change in volume can be divided into two parts: (1) growth resulting from the production of two atoms for each uranium atom fissioned; and (2) swelling, the change in volume which results from the accumulation of fission gases.

Growth due to the fission of uranium atoms would be expected to produce a volume expansion of from 2 to 2.5 per cent per a/o burnup with the less dense high-zirconium alloys exhibiting the lesser volume change. This estimate is made for fission-product atoms which are dispersed in the lattice of the fuel-alloy matrix.

While the above volume change can be reasonably expected for low-temperature irradiations, as the temperature of irradiation increases the concept of fission-product atoms dispersed in the alloy matrix no longer holds. The majority of these atoms exhibit low solubility in zirconium or uranium and therefore tend to precipitate. Such precipitation occurs as the temperature of irradiation is increased and the mobility of the fission-product atoms is increased. The precipitation of solid fission-product atoms is not expected to have any significant effect on volume change accompanying irradiation. However, the gaseous fission-product atoms when precipitated exert molecular gas pressures which result in swelling. The amount of swelling will be determined by the restraint offered by the fuel-alloy matrix.

Thus, the mechanical strength of zirconium-uranium alloys has a major influence on irradiation performance. While increased strength properties can be achieved by heat treatment, such properties are transient in nature, and, in general, equilibrium properties will be obtained as a result of annealing during irradiation at elevated temperatures. As a consequence, the irradiation behavior of zirconium-uranium alloys appears to be generally insensitive to heat treatment except in alloys containing 80 w/o (60 a/o) or more uranium. Since alpha uranium is the primary phase in these high-uranium alloys, irradiation behavior is highly dependent on grain size, orientation, amount, and distribution of this highly anisotropic phase.

The irradiation behavior of zirconium-uranium alloys can be discussed in two parts, the behavior of alloys containing up to 22 w/o (10 a/o) uranium and the behavior of alloys containing 40 to 60 w/o (20 to 36 a/o) uranium. Except for a few scattered bits of information, reliable data are available only for these ranges, with the major amount of information available for alloys containing less than 22 w/o uranium. At the high-uranium portion of the system, data are available for alloys containing 80 w/o uranium and more. However, the discussion of these uranium-rich alloys is not within the scope of this report.

A knowledge of irradiation-temperature data is of prime importance in the evaluation of irradiation behavior; fission-gas-atom diffusion and mechanical strength

are highly temperature dependent. While irradiation temperatures are reported for most irradiation tests, the values quoted are the maximum temperatures for the start of irradiation. A rapid decrease in this temperature occurs as the irradiation proceeds due to uranium burnup. This effect is most pronounced for samples encapsulated in NaK where temperature decreases of as much as 333 C (600 F) from an initial 485 C (900 F) are achieved in high-zirconium alloys irradiated to high burnups. For irradiation conducted in pressurized-water loops, the temperature decreases are generally less than 100 C (150 F) for the same alloys.^(1,2) Thus, evaluation of alloy behavior must be based not on an absolute temperature but on an approximate temperature which is subject to variations.

Alloys Containing Up to 22 w/o (10 a/o) Uranium

The irradiation performance of zirconium-rich zirconium-uranium alloys has been the subject of several recent reviews.^(1,2,3) The performance capabilities of alloys containing 22 w/o (10 a/o) uranium or less appear to be fairly well defined. Up to about 425 C (800 F), the volume change per a/o burnup is 7 per cent or less.⁽²⁾ The average change is about 3 per cent⁽¹⁾, which is approximately the value predicted for the case of dispersed fission-product atoms. Above this temperature, at approximately 480 C (900 F), a rapid increase in volume with increasing temperature is indicated. A plot of irradiation data showing volume changes per a/o burnup as a function of irradiation temperature for alloys containing up to 22 w/o uranium appears in Figure 54.

Dependence on burnup level of the temperature at which the inflection in the volume-change curve is observed is also suggested⁽¹⁾, although the data are fairly well scattered and are insufficient to permit a firm conclusion. Volume change at various burnup levels is shown plotted versus temperature in Figure 55. The plot indicates that the inflection temperature for increased swelling decreases as the burnup increases.

In addition to the diffusion of fission gases, an additional mechanism for the accumulation of fission-gas atoms is indicated for zirconium-uranium alloys. This is the accumulation which accompanies thermal cycling in the alpha zirconium-plus-gamma phase region. Examination of the zirconium-uranium phase diagram reveals that the equilibrium amounts of the phases vary with temperature. The amounts at different temperatures can be predicted by the lever law. The interface motion accompanying thermal cycling provides a mechanism for sweeping the fuel matrix of fission gases and for the accumulation of the gases at the interface boundary.

The effects of variations in microstructure on the irradiation stability of the 22 w/o uranium alloy have been investigated.⁽⁴⁾ No significant changes in irradiation behavior could be attributed to variations in distribution of the phases present.

In another study⁽⁵⁾ of the effect of heat treatment on the irradiation performance of a 25 w/o (11 a/o) uranium alloy, it was found that a sample slow cooled to yield an equilibrium structure exhibited much greater surface stability than specimens which were gamma quenched. Presumably distortion accompanied the transformation of the nonequilibrium structures in the quenched specimens.

FIGURE 54. THE EFFECT OF TEMPERATURE ON PER CENT VOLUME CHANGE PER a/o BURNUP FOR ZIRCONIUM ALLOYS CONTAINING UP TO 22 w/o (10 a/o) URANIUM

FIGURE 55. VOLUME INCREASE VERSUS IRRADIATION TEMPERATURE FOR ZIRCONIUM ALLOYS CONTAINING UP TO 22 w/o (10 a/o) URANIUM AT VARIOUS BURNUP LEVELS

Alloys Containing 40 to 60 w/o (20 to 36 a/o) Uranium

The irradiation performance of alloys in this range, which are essentially epsilon phase, is not as well documented as that of the higher zirconium alloys. Burn-ups and irradiation temperatures have generally been low.

The general behavior, for example, volume change per a/o burnup, for these epsilon phase alloys appears to be similar to that exhibited by the higher zirconium alloys.⁽³⁾

There is no significant difference in the behavior of specimens heat treated either to retain the gamma phase or to produce the partially ordered epsilon phase when irradiations are conducted at elevated temperatures.⁽⁶⁾ This might be expected, since transformation of retained gamma occurs rapidly, with the result that it is impossible to irradiate the gamma-phase structure at elevated temperatures in the epsilon-phase region. At low temperatures, near room temperature, where the transformation is sufficiently sluggish, it is quite probable that gamma-phase reversion of the epsilon phase takes place on irradiation. Low-temperature irradiation results suggest that a disordering of the epsilon phase to produce gamma can occur.⁽⁷⁾

Other studies also show little effect of heat treatment on dimensional stability of 50 and 60 w/o (27 and 36 a/o) uranium-alloy samples.^(8,9) However, technique of melting appears to have a pronounced effect on stability. Induction-melted material was found⁽⁶⁾ to exhibit much greater stability than arc-melted material. The greater stability may be related to the higher carbon content of the induction-melted material which is responsible for increased strength.

Discussion

Data concerning the irradiation behavior of zirconium-uranium alloys are confined principally to alloys containing 22 w/o (10 a/o) or less uranium. While limited data are available for alloys in the 40 to 60 w/o (20 to 36 a/o) uranium range, no data at high burnup levels (near 1 a/o or greater) have been obtained. In general it appears that for low-temperature irradiations, alloys containing up to 60 w/o uranium exhibit similar behavior. One might expect improved behavior for epsilon-phase alloys (40 to 60 w/o uranium) at elevated temperatures since alloys near the middle of the system exhibit greater strength due to solid-solution strengthening. However, experimental data are insufficient to confirm this prediction.

The irradiation performance of zirconium-uranium alloys is generally insensitive to heat treatment. Microstructural variations appear to have little effect on dimensional stability. Heat treatments which produce nonequilibrium structures are detrimental to stability since warpage and distortion accompany the transformation of nonequilibrium structures during irradiation.

Volume changes average about 3 per cent per a/o burnup for zirconium alloys containing up to 22 w/o uranium when the irradiations are conducted at temperatures below 425 to 480 C (800 to 900 F). Above this temperature range the volume change for equivalent burnups becomes increasingly severe. This swelling is a result of increasing fission-gas diffusion rate and decreasing mechanical strength of the zirconium-uranium alloy with increasing temperature.

References

- (1) Lacy, C. E., and Leary, E. A., "Irradiation Performance of Highly-Enriched Fuel", KAPL-1952 (June 20, 1958).
- (2) Thomas, D. E., unpublished information, Bettis Atomic Power Division (September 22, 1958).
- (3) Wilson, W. H., and Ziebold, T. O., "Performance of Fuel Elements at Elevated Temperatures", WASH-741 (September 4, 1957).
- (4) Dayton, R. W., and Tipton, C. R., Jr., "Progress Relating to Civilian Application During March, 1957", BMI-1176 (April 1, 1957).
- (5) Unpublished information, Bettis Atomic Power Division (September 20, 1955).
- (6) Bruch, C. A., and Cashin, W. M., "Metallurgy Report of the Technical Department - March, April, and May, 1956", KAPL-1564.
- (7) "Metallurgy Report of the Technical Department - June, July, August, 1956", KAPL-1604.
- (8) Unpublished information, Bettis Atomic Power Division (November 20, 1955).
- (9) Unpublished information, Bettis Atomic Power Division (January 20, 1955).