UNCLASSIFIED

RECEIVED BY DTIC AUG 29 1968

BNWL-853

14 Copies

~~CONFIDENTIAL~~

MASTER

**QUARTERLY PROGRESS REPORT
FUELED GRAPHITE STUDIES
APRIL, MAY, JUNE, 1968**

AUGUST 1968

**AEC RESEARCH &
DEVELOPMENT REPORT**

Classification cancelled (reclassified to)

by authority of

by Alfred Conell TIC, date AUG 28 1973

Exempt from CCRP Re-review Requirements
(per 7/22/82 Duff/Caudle memorandum)

UNCLASSIFIED

68-9575

~~CONFIDENTIAL~~

BATTELLE
BATTELLE MEMORIAL INSTITUTE

NORTHWEST
PACIFIC NORTHWEST LABORATORY

BATTELLE BOULEVARD, P. O. BOX 999, RICHLAND, WASHINGTON 99352

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

BNWL-853

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency Thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

DISCLAIMER

Portions of this document may be illegible in electronic image products. Images are produced from the best available original document.

~~CONFIDENTIAL~~

INFORMATION CONCERNING USE OF THIS REPORT

PATENT STATUS

This document copy, since it is transmitted in advance of patent clearance, is made available in confidence solely for use in performance of work under contracts with the U. S. Atomic Energy Commission. This document is not to be published nor its contents otherwise disseminated or used for purposes other than specified above before patent approval for such release or use has been secured, upon request, from the Chief, Chicago Patent Group, U. S. Atomic Energy Commission, 9800 So. Cass Ave., Argonne, Illinois.

PRELIMINARY REPORT

This report contains information of a preliminary nature prepared in the course of work under Atomic Energy Commission Contract AT(45-1)-1830. This information is subject to correction or modification upon the collection and evaluation of additional data.

LEGAL NOTICE

This report was prepared as an account of Government sponsored work. Neither the United States, nor the Commission, nor any person acting on behalf of the Commission:

A. Makes any warranty or representation, expressed or implied, with respect to the accuracy, completeness, or usefulness of the information contained in this report, or that the use of any information, apparatus, method, or process disclosed in this report may not infringe privately owned rights; or

B. Assumes any liabilities with respect to the use of, or for damages resulting from the use of any information, apparatus, method, or process disclosed in this report.

As used in the above, "person acting on behalf of the Commission" includes any employee or contractor of the Commission, or employee of such contractor, to the extent that such employee or contractor of the Commission, or employee of such contractor prepares, disseminates, or provides access to, any information pursuant to his employment or contract with the Commission, or his employment with such contractor.

PACIFIC NORTHWEST LABORATORY

RICHLAND, WASHINGTON

operated by

BATTELLE MEMORIAL INSTITUTE

for the

UNITED STATES ATOMIC ENERGY COMMISSION UNDER CONTRACT AT(45-1)-1830

PRINTED BY/FOR THE U.S. ATOMIC ENERGY COMMISSION

54-1950-016 (4-68)
AEC-RL RICHLAND, WASH.

~~CONFIDENTIAL~~

UNCLASSIFIED

BNWL-853

C-91, Nuclear Reactors
for Rocket Propulsion
(M-3679, 56th Ed.)

QUARTERLY PROGRESS REPORT
FUELED GRAPHITE STUDIES
APRIL, MAY, JUNE, 1968

By

Ceramics Department

August 1968

United
he accu-
t the use
infringe
from the
any em-
tent that
repairs,
contract

NOTICE

This report was prepared as an account of work sponsored by the United States Government. Neither the United States nor the United States Atomic Energy Commission, nor any of their employees, nor any of their contractors, subcontractors, or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness or usefulness of any information, apparatus, product or process disclosed, or represents that its use would not infringe privately owned rights.

This report
States, nor th
A. Make
racy, complete
of any infor
privately own
B. Assu
use of any in
As used
ployee or co
such employ
disseminates
with the Commission, or this employment with the Commission.

RESTRICTED DATA

This document contains Restricted Data as defined in the Atomic Energy Act of 1954. Its transmittal or the disclosure of its contents in any manner to an unauthorized person is prohibited.

BATTELLE MEMORIAL INSTITUTE
PACIFIC NORTHWEST LABORATORY
RICHLAND, WASHINGTON

UNCLASSIFIED

GROUP 1

Excluded from automatic Downgrading
and Declassification

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

To Government Agencies and Contractors + CAP

~~UNCLASSIFIED~~

Printed in the USA. Charge \$0.75.
Available from the
U.S. Atomic Energy Commission
Division of Technical Information Extension
P.O. Box 62, Oak Ridge, Tennessee
Please direct to the same address inquiries covering
procurement of other classified AEC reports.

UNCLASSIFIED

UNCLASSIFIED

BNWL-853

CONTENTS

INTRODUCTION	1
MICROSCOPY	2
Optical Microscopy	2
Electron Microscopy	4
RADIOGRAPHY	6
Experiment 50	6
WANL Samples	19
COATING STUDIES	24
SCANNING ELECTRON MICROSCOPY	28
REFERENCES	29
DISTRIBUTION	31

LIST OF FIGURES

1 Comparison of Experiment 50 Elements Given the Longest Over- and Underpressure Tests	3
2 Bead Coating Structure Change Induced by Uranium Migration; Station 50, Element 210-46216	5
3 Uranium-Induced Graphitization of the Matrix; Station 50, Element 210-46216	7
4 Macroradiograph (8X) from Station 19, Element 3110-AA-20	10
5 Macroradiograph (8X) from Station 40, Element 3110-AA-20	11
6 Macroradiograph (8X) from Station 13, Element 3023-AA-284	12
7 Macroradiograph (8X) from Station 20, Element 3023-AA-254	13
8 Macroradiograph (8X) from Station 40, Element 3023-AA-254	14

UNCLASSIFIED

UNCLASSIFIED

iv
BNWL-853

9	Macroradiograph (8X) from Station 40, Element 02-2051-90184	16
10	Macroradiograph (8X) from Station 13, Element 02-2051-90183	17
11	Macroradiograph (8X) from Station 17, Element 210-46219	18
12	Macroradiograph (8X) from Station 19, Element 431-1042309	21
13	Macroradiograph (8X) from Station 19, Element AL-20-81352	22
14	Macroradiograph (100X) of Resinate-Impregnated Element Stained by Tetrabromoethane	23
15	Same Field as Figure 14 After Tetrabromoethane Was Removed by Baking to Show Only the NbC	23
16	Macroradiograph (8X) from Station 19, Element 431-1042296, Stained by Tetrabromoethane from Bores	25
17	Macroradiograph (8X) at Station 19, Element 432-3079889, Showing the Distribution of -325 Mesh NbC Particles Added to Graphite Mix	26

~~CONFIDENTIAL~~

QUARTERLY PROGRESS REPORT
FUELED GRAPHITE STUDIES
APRIL, MAY, JUNE, 1968

INTRODUCTION

A study of the effect of porosity in ROVER fuel and its relationship to hydrogen corrosion is under investigation at Los Alamos Scientific Laboratory (LASL). This study, Experiment 50, involves both fueled and unfueled elements with differences in permeability created through the additions of wood flour. The corrosion during hot-gas tests is compared in the cases where the helium-blanket gas is at a pressure both above and below the hydrogen gas pressure in the fuel bores. Metallographic and radiographic examination of samples from these tests is being performed at Battelle-Northwest. Results on both hot-gas tested and untested elements with and without wood-flour additions were discussed in the previous Quarterly Progress Report⁽¹⁾ and observations on additional tested elements are continued in this report.

Examination was initiated on a series of elements prepared with NbC inclusions in the matrix by Westinghouse Astronuclear Laboratory (WANL) for Phase IIFb of the fuel-development program. Untested elements are discussed here; however, our examinations will eventually include tested elements. Variables in this series of elements include a standard element without NbC additions, NbC introduced into high- and low-permeability elements by impregnation with niobium resinate before final graphitization, and an addition of 2.5 vol% of -325 mesh NbC particles in a mix.

~~CONFIDENTIAL~~

MICROSCOPY

E. M. Woodruff

OPTICAL MICROSCOPY

Elements representing the longest hot-gas tests given each of the four basic element variations in Experiment 50 were examined optically. A brief description of the elements and test conditions is given in Table I.

TABLE I. Hot Gas Test Conditions of Elements Examined

<u>Element Type</u>	<u>Element Number</u>	<u>Test Condition</u>	<u>Test Time, min</u>	<u>Weight Loss, gm</u>
Regular unloaded	3023-AA-284	Overpressure	60	-7.3
Regular unloaded	3023-AA-254	Underpressure	57 1/2	-16.1
Unloaded with 2% wood flour	3110-AA-17	Overpressure	60	-8.0
Unloaded with 2% wood flour	3110-AA-20	Underpressure	54 1/3	-15.7
Regular loaded	210-46218	Overpressure	60	-7.5
Regular loaded	210-46219	Underpressure	44 1/2	-11.9
Loaded with 2% wood flour	02-2051-90184	Overpressure	60	-7.7
Loaded with 2% wood flour	02-2051-90183	Underpressure	30	-6.8

Large differences in corrosion patterns which can be related to underpressure or overpressure test conditions are not obvious in optical micrographs. There are, however, subtle and fairly consistent differences at the corrosion peak near Station 15 (Figure 1) which can be described as a tendency for pitting near coating cracks in overpressure tests; while in underpressure tests, corrosion is evenly distributed to greater depths. Since pits are easily detected, the impression of more severe corrosion for overpressure tests is given, while actual weight

OVERPRESSURE

Unfueled
Regular-Mix

Unfueled +
2% Wood Flour

Fueled
Regular-Mix

(e) Station 16, Element 210-46218,
Tested 60 min.

Fueled +
2% Wood Flour

(g) Station 12, Element 02-2051-90184,
Tested 60 min.

UNDERPRESSURE

(b) Station 20, Element 3023-AA-254,
Tested 57 1/2 min.

(d) Station 12, Element 3110-AA-20,
Tested 54 1/3 min.

(f) Station 17, Element 210-46219,
Tested 44 1/2 min.

(h) Station 13, Element 02-2051-90183,
Tested 30 min.

FIGURE 1. Comparison of Experiment 50 Elements Given the Longest Over- and Underpressure Tests. Sections of Channel One at the Peak of Corrosion near the Inlet (G) End of Elements (200X).

~~CONFIDENTIAL~~

BNWL-853

losses are about half of those for underpressure tests of equivalent duration. It can be concluded that for low-numbered stations with underpressure conditions (i.e., furnace helium-blanket pressure below hydrogen pressure in bores) corrosion proceeds uniformly throughout accessible pores in the matrix. These observations suggest that cursory inspection of corrosion immediately under bore coats by longitudinally slicing elements and stripping away the coating can be misleading, particularly for low-numbered stations in overpressure-tested elements.

The addition of wood flour in fueled elements (Figures 1g and 1h) improved coating adherence and prevented the large gap observed in regular-mix fueled elements (Figures 1e and 1f). Micrographs at Station 40 in these elements do not reveal significant differences attributable to either pressure conditions or wood-flour additions. At this station, an overpressure condition exists in all elements and higher coating temperatures apparently prevent root development in pores made available by the wood-flour additions.

ELECTRON MICROSCOPY

Gross fuel-migration patterns near the H-end of tested elements have been located and characterized using microradiography.⁽³⁾ Replica electron microscopy has been used to examine changes occurring in these regions in greater detail. Station 50 of an Experiment 50 element (210-46216) was selected for study on the basis of radiographic and optical evidence of gross fuel migration and considerable change in the appearance of the matrix. The element was prepared using a regular mix and had been overpressure tested for 30 min.

Figure 2 illustrates migration through a fuel-bead shell with partial conversion of the as-deposited pyrolytic structure into concentric graphite lamellae similar to those found

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

FIGURE 2. Bead Coating Structure Change Induced by Uranium Migration; Station 50, Element 210-46216. Markers indicate 10 μ (3825X).

- A - As-deposited PyC structure
- B - Region graphitized in the presence of uranium
- C - Matrix graphite

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

BNWL-853

adjacent to fuel in as-manufactured beads. The band of unaltered PyC on the left side of the area shown has a structure very similar to the unaffected outer region (lower right). Isolation of the inner zone from structural change during migration could be associated with the delaminations following its inner and outer surfaces.

The matrix surrounding beads is converted to a granular graphite structure. Transition from the normal filler-binder structure to the precipitated graphite form occurs over a distance of less than 5 μ in Figure 3. Realignment continues after this initial transition and forms relatively large, randomly oriented graphite grains shown on the left in Figure 3. Large property changes must accompany this complete transformation of structure. One can speculate that in graphite regions strength would decrease, thermal conductivity would increase, and resistance to corrosion might also increase.

RADIOGRAPHY

L. R. Bunnell

EXPERIMENT 50

The past two quarterly reports^(1,2) have contained results of radiographic observations on the first shipment of Experiment 50 elements, which included untested standards and one hot-gas-tested element. The other hot-gas-tested elements of Experiment 50 are now under examination; the elements tested for the longest time (1 hr, nominal) have been the subject of recent examinations. The experimental method was the same as outlined previously,⁽¹⁾ with samples taken at Stations 1 and 40, and at intermediate stations representing peaks in the MULE weight-loss profiles.

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~ 10 μ

FIGURE 3. *Uranium-Induced Graphitization of the Matrix. Migration from Left to Right Resulted in Total Recrystallization of Filler Particles and Binder. Unaltered Matrix Is Shown on the Right. Station 50, Element 210-46216 (4500X).*

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

The observations from 10X macroradiographs of the elements, impregnated by bore hole access, are summarized in Tables II and III. The observations in Table II (unfueled elements) reveal that the principal effects of underpressure testing of unfueled elements are penetrations at low-numbered stations (10-20 region), and an annular ring attack at higher-numbered stations. The penetrations are to be expected, especially in the case of wood-flour-containing elements. The annular ring corrosion is not so easily understood because the pressure difference between over- and underpressure testing is not great at Station 40. Additional recent work on the underpressure tested, unfueled, regular-mix element, 3023-AA-254, showed that, at Station 30, where the helium pressure is about equal to the bore pressure, the annular ring attack does not occur. At Station 45, it occurred to greater severity than at Station 40. More micro-radiography will be done to help clarify this point.

It appears that the single thermal cycle of hot-gas testing allowed stain access in the case of the regular-mix, unfueled element, since this element type was shown to be tight along its entire length prior to testing. Even though a built-in system of pores existed, it had not been accessible from bores.

The observations in Table III (fueled elements) reveal, first, that the overpressure-underpressure test effects are not so noticeable on fueled elements as on unfueled. Some penetrations were visible in the Station 10-20 range of underpressure tested elements, but none of the annular ring Station 40 attack was visible. As in the case of unfueled elements, an increase in bore-accessible porosity was also noticed.

Although not included in Table III, it was observed that fuel migration occurred at higher-numbered stations in these elements than in the single tested element examined previously.

~~CONFIDENTIAL~~

TABLE II. Observations on Unfueled Elements

Element	Station 1	Intermediate Station	Station 40
3110-AA-17 (Unfueled, wood flour, overpressure tested 60 min) 8.0 g weight loss	Weight loss 0.04 g/in. No change over untested element; no staining from bores.	(St. 12) Weight loss 0.15 g/in. Weight loss occurs with no obvious change in original pore networks.	Weight loss 0.25 g/in. Weight loss occurs with no change in original pore networks.
3110-AA-20 (Unfueled, wood flour, underpressure tested 54 1/3 min) 15.7 g weight loss	Weight loss 0 g/in. No change over untested element; no staining from bores.	(St. 12) Weight loss 0.13 g/in. Some "penetrations,"* not much evidence of corrosion. (St. 19) Weight loss 0.28 g/in. Weight loss occurs as result of penetrations. (Figure 4)	Weight loss 0.25 g/in. Attack in annular rings, especially center and inner-six bores. No penetrations seem active (Figure 5)
3023-AA-284 (Unfueled, regular-mix, overpressure tested 60 min) 7.3 g weight loss	Weight loss 0 g/in. No change over untested element; no staining from bores.	(St. 13) Weight loss 0.09 g/in. Bore coating allowed access to built-in network. (Figure 6) Untested counterpart tight at Station 15.	Weight loss 0.2 g/in. Same as Station 13. Untested element tight at Station 40.
3023-AA-254 (Unfueled, regular-mix, underpressure tested 57 1/2 min) 16.1 g weight loss	Weight loss 0 g/in. No change from untested element; no staining from bores.	(St. 20) Weight loss 0.27 g/in. A decreased extent of pore networks (compare Figures 6 and 7) but penetrations (arrow) responsible for weight loss. (Figure 7)	Weight loss 0.2 g/in. Corrosion in annular rings around inner bore holes. (Figure 8)

* A penetration is the access of the impregnated stain from bore holes to external surfaces.

~~CONFIDENTIAL~~

10

BNWL-853

FIGURE 4. Macroradiograph (8X) from Station 19, Element 3110-AA-20. Note Diffuse Black Areas on Outer Surfaces, Which Indicate "Penetration" and Gross Weight Loss.

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

FIGURE 5. Macroradiograph (8X) from Station 40, Element 3110-AA-20. Note Corroded Zones (Gray Annular Rings) Around Inner-Six and Center Bore Holes.

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

12
BNWL-853

FIGURE 6. Macroradiograph (8X) from Station 13, Element 3023-AA-284. Pore Network Is Approximately Normal, but Has Been Made Accessible by Hot-Gas Testing.

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

13
BNWL-853

FIGURE 7. Macroradiograph (8X) from Station 20, Element 3023-AA-254. Arrow Indicates Penetration Resulting from Underpressure Testing.

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

14
BNWL-853

FIGURE 8. Macroradiograph (8X) from Station 40, Element 3023-AA-254. Compare with Figure 5; the Same Pattern of Station 40 Corrosion Exists.

~~CONFIDENTIAL~~

TABLE III. Observations on Fueled Elements

Element	Station 1	Intermediate Station	Station 40
02-2051-90184 (Fueled, wood flour, overpressure tested 60 min) 7.7 g weight loss	No change over untested element; no staining from bores.	(St. 12) Weight loss 0.14 g/in. Normal pore network, untested element had no bore access.	Weight loss 0.19 g/in. No obvious difference from untested, except near one flat (arrow) where massive corrosion occurred. (Figure 9) One corner corroded severely.
02-2051-90183 (Fueled, wood flour, underpressure tested 30 min) 6.8 g weight loss	No change over untested element; no staining from bores.	(St. 13) Weight loss 0.1 g/in. Porosity made accessible as in overpressure test above. Outer- 12 holes seem involved in increased corrosion. (Figure 10) (St. 20) Weight loss 0.08 g/in. Same appearance as Figure 10, outer-12 bore hole corrosion to a lesser extent.	Weight loss 0.07 g/in. Same as Figure 9 above, but pore networks less enlarged. No annular ring attack as in unfueled counterpart.
210-46218 (Fueled, regular-mix, overpressure tested 60 min) 7.5 g weight loss	No change over untested element; no staining from bores.	(St. 16) Weight loss 0.11 g/in. As-manufactured porosity seems enlarged.	Weight loss 0.23 g/in. As-manufactured porosity seems enlarged.
210-46219 (Fueled, regular-mix, underpressure tested 44 1/2 min) 11.9 g weight loss	No change over untested element; no staining from bores.	(St. 17) Weight loss 0.08 g/in. Evidence of penetrations at corners. (Figure 11) Most of weight loss at corners. (St. 25) Weight loss 0.07 g/in. Same porosity as before testing.	Weight loss 0.14 g/in. Same as overpressure tested Station 40.

CONFIDENTIAL

BNWL-853

~~CONFIDENTIAL~~

16
BNWL-853

FIGURE 9. Macroradiograph (8X) from Station 40, Element 02-2051-90184. Note Extreme, Localized Corrosion (arrow) and Missing Segments of Bore Coating.

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

FIGURE 10. Macroradiograph (8X) from Station 13, Element 02-2051-90183. Notice Heavy Staining Around Outer-Twelve Bore Holes.

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

FIGURE 11. Macroradiograph (8X) from Station 17, Element 210-46219. Note Fairly Extensive Corrosion at Corners.

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

It was previously stated⁽²⁾ that massive fuel migration originated at about Station 47 1/2 in a regular-mix element tested 30 min. In element 210-46218, which was tested for 1 hr, examination at Stations 47 1/2, 48, and 48 1/2 showed no mass migration, but only the transport of fuel to the bore coating region. Los Alamos furnace 5 was used for the 30 min test, while all the other elements in Experiment 50 were tested in furnace 3. A complete set of elements tested in furnace 3 are included in the set at Battelle-Northwest. Examinations in progress include all the remaining hot-gas-tested members of Experiment 50.

WANL SAMPLES

Samples from four WANL elements have recently been examined by microradiography. Their processing history is briefly described in Table IV. These elements were furnished as untested standards; their tested counterparts will be furnished later.

In elements 431-1042309 and AL-20-81352, containing the Nb resinate, microradiography shows the distribution of the resinate very well. Figure 12 shows this distribution at Station 19 in element 431-1042309, the low-permeability element. It is seen that impregnation is mostly among the inner-six and outer-twelve bore holes, with little impregnation around the center hole or between the outer-twelve bores and flats. The high permeability of element AL-20-81352, on the other hand, is reflected in its resinate impregnation pattern. Figure 13, from Station 19 of this element, shows that impregnation occurred in the entire cross section of the element, except around the center bore hole. At the low magnification shown, the resinate seems to be a continuous pore liner, but examination at higher magnification revealed the NbC to be present as small particles along the inner surface of pores.

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~TABLE IV. *Brief Element Characterization*

<u>Element No.</u>	<u>Matrix</u>	<u>Impregnant</u>	<u>Test Condition</u>
431-1042309	Graphite (low permeability, 15 cm ³ air/min)	Nb resinate (triple impregnate and rebake)	NbC + X-coated Untested
AL-20-81352	Graphite (high permeability, 412 cm ³ air/min)	Nb resinate (triple impregnate and rebake)	NbC + X-coated Untested
431-1042296	Graphite (low permeability, 52 cm ³ air/min)	None	NbC + X-coated Untested
432-3079889	Graphite + 2.5 vol% NbC (low permeability, 65 cm ³ air/min)	None	NbC + X-coated Untested

The elements shown here were impregnated with a tetrabromoethane-resin staining mixture, prior to radiography. In addition, the stain has been baked out in an attempt to disclose bore-accessible porosity by comparison of the radiographs. The extra absorber introduced by the resinate, however, makes the discrimination between stain and NbC difficult at moderate magnification. Comparison at 100X revealed the position of the stain. Figures 14 and 15 are 100X microradiographs from Station 47 of element AL-20-81352. Figure 14 shows the sample with stain impregnated from the bores; Figure 15 shows the same sample after bake-out. Close comparison of areas such as "o" reveals that the stain is within pores containing resinate-deposited NbC. Figure 15 also reveals that the impregnated NbC is not present as a continuous pore liner, but exists in the form of very small (<5 μ) particles on the inner surface of pores.

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

FIGURE 12. *Macroradiograph (8X) from Station 19, Element 431-1042309, Showing Resinate-Derived NbC Distribution in Initially Low-Permeability Element.*

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

22

BNWL-853

FIGURE 13. *Macroradiograph (8X) from Station 19, Element AL-20-81352, Showing Distribution of Resinate-Derived NbC in Initially High-Permeability Element.*

~~CONFIDENTIAL~~

FIGURE 14. *Macroradiograph (100X) of Resinate-Impregnated Element Stained by Tetrabromoethane.*

FIGURE 15. *Same Field as Figure 14, After Tetrabromoethane Was Removed by Baking to Show Only the NbC. Note the Granular Nature of the Resinate-Derived NbC.*

~~CONFIDENTIAL~~

Figure 16 shows the regular (no resinate impregnation) graphite element (431-1042296) at Station 19. Comparison of Figures 12 and 16 shows a rough one-to-one correspondence of dark networks, except in Figure 16 the networks are due not to NbC, but to stain penetration of the normal porosity network through cracks in the bore coating.

Figure 17 shows a Station 19 cross section of the element containing NbC as an addition to the extrusion batch. The uniform distribution is evident, as the only regions not containing the -325 mesh particles are graphite flour particles, which are visible in Figure 14 as the small white "islands" among the dark granular NbC particles. Although this element was also impregnated with stain from the bores, none of it is visible because of the extraneous NbC particles. This element looks very much like other NbC-loaded elements observed and reported in the past.⁽³⁾

The tested counterparts of the above elements arrived during the past quarter; results of their microradiographic examination, along with the microautoradiographic examination of the entire set of samples, will be included in the next quarterly progress report.

COATING STUDIES

C. E. McNeilly

The first experiments designed for studying the effect of deposition rate on coating behavior by dropping fuel elements out of the coater during operation has been completed. These experiments were conducted at 1600 °C and the significant data are summarized in Table V.

The causes for the discrepancies in the element weight gains are unknown, but the most likely reason is that we still do not have a reliable system for monitoring the delivery rate

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

25
BNWL-853

FIGURE 16. Macroradiograph (8X) from Station 19, Element 431-1042296, Stained by Tetrabromoethane from Bores. The Pore Pattern Is Similar to the NbC Distribution Pattern in Figure 12.

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

FIGURE 17. *Macroradiograph (8X) at Station 19, Element 432-3079889, Showing the Distribution of -325 Mesh NbC Particles Added to Graphite Mix*

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

of the NbCl_5 . The assumption that the salt delivery rate is directly proportional to the helium flow through the saturator may well be in error. The fact that runs 12a - 2, 15a - 3, and 16a - 2 all gained less weight than expected would indicate this may be the case. The very low value for 13a - 1 is presently unexplainable. The coatings still do not run the full length of the bore holes but the coating thickness profiles seem quite consistent from one element to the next. The coatings (at Station 6) from runs 12 and 13 have been examined by microscopy and radiography and examination of runs 15 and 16 is in progress.

TABLE V. *Experimental Coating Conditions*

<u>Gas Composition</u>	<u>Run No.</u>	<u>Time in Coater</u>	<u>Weight Gain</u>
NbCl_5 - 0.006 moles/min 3% of total flow	12a - 3	10 min	0.8 g
	12a - 1	20 min	1.6 g
H_2/NbCl_5 - 2.2	12a - 2	30 min	1.9 g
HCl/NbCl_5 - 1.0	13a - 3	60 min	8.0 g
He - remainder	13a - 1	120 min	2.0 g
	13a - 2	240 min	25.0 g
NbCl_5 - 0.001 moles/min 1% of total flow	15a - 1	1 hr	0.8 g
	15a - 2	2 hr	1.3 g
H_2/NbCl_5 - 2.0	15a - 3	4 hr	1.1 g
HCl/NbCl_5 - 1.0	16a - 1	8 hr	4.3 g
He - remainder	16a - 3	16 hr	13.2 g
	16a - 2	30 hr	16.3 g

Radiographic and microscopic examination of these samples are underway.

While awaiting these results, we are starting the experiments on developing root structure by vacuum impregnating the graphite with NbCl_5 . In the first experiment, the fuel element

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

was held at 600 °C in a vacuum of 20 μ . After opening the coater to the NbCl₅ saturator, which was at a temperature of 220 °C, an equilibrium pressure of about 15 to 20 in. of mercury resulted. Enough helium was passed into the saturator and into the coating jig to bring the pressure up to one atmosphere. After shutting off the saturator, the furnace temperature was raised to 1600 °C for one-half hour to react the NbCl₅ and graphite.

No significant weight increase resulted, so it may be the NbCl₅ evaporated before it reacted. The next experiment will involve keeping an NbCl₅ flow through the furnace during the heating cycle.

SCANNING ELECTRON MICROSCOPY

J. L. Daniel

The scanning electron microscope was received and installed. This instrument includes the following features:

- (a) Provisions included or available for images resulting from secondary, backscattered, transmitted and absorbed electrons, cathodoluminescence, and e.m.f. differences;
- (b) Magnification range 100X to 100,000X with primary beam voltage of 5 to 50 kV;
- (c) Image resolution of 250 Å or better;
- (d) Universal goniometer specimen stage;
- (e) Provisions for image recording by standard camera and Polaroid high-speed photography; video tape recording attachment available;
- (f) Physical design adaptable to use of specially designed attachments for dynamic in-microscope experiments, and for examination of plutonium-bearing materials.

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

During initial testing and evaluation, the main problems to be overcome have been the instrument's sensitivity to low-frequency floor vibrations, and some electronic instability. The electronic problem was corrected simply by properly adjusting the variable control points within the high-voltage feedback circuit. Mechanical stability has been improved by use of temporary air-cushion mounting; complete stabilization is expected to be achieved by a suitably designed instrument suspension and remote relocation of adjacent mechanical pumps, or a substitution by liquid nitrogen sorption pumps, if necessary.

Initial examination of NbC specimens showed excellent performance by the microscope with no charge buildup or other disturbance introduced by the specimen material. Depth of focus allows examination into cavities, pores, and re-entrant spaces not observable by other microscopic techniques on as-fabricated or fractured specimens. Stereo-micrograph pairs, prepared using the goniometer stage, have demonstrated the utility of that technique for correct interpretation of microstructure in depth; a measuring stereoscope to be obtained later will allow quantitative determinations of vertical distances represented in the micrographs.

REFERENCES

1. Quarterly Progress Report, Fueled Graphite Studies, January, February, March, 1968, BNWL-798. Pacific Northwest Laboratory, Richland, Washington, June 1968. (Confidential)
2. Quarterly Progress Report, Fueled Graphite Studies, October, November, December, 1967, BNWL-731. Pacific Northwest Laboratory, Richland, Washington, May 1968. (Confidential)

~~CONFIDENTIAL~~

~~CONFIDENTIAL~~

3. Quarterly Progress Report, Fueled Graphite Studies, April, May, June, 1967, BNWL-509. Pacific Northwest Laboratory, Richland, Washington, September 1967. (Confidential)

~~CONFIDENTIAL~~

UNCLASSIFIED

BNWL-853

DISTRIBUTIONNo. of
Copies

2	AEC Albuquerque Operations Office
2	AEC Albuquerque Operations Office Space Nuclear Propulsion Office Albuquerque Extension J. F. Cully H. Hessing
1	AEC Chicago Patent Group
2	AEC Chicago Patent Group G. H. Lee R. K. Sharp, Richland
1	AEC Library, Washington
1	AEC Library, Washington J. M. Morrissey
1	AEC Nevada Operations Office
1	AEC Patent Office
2	AEC Richland Operations Office C. L. Robinson Technical Information Library
2	Aerojet-General Corporation (NASA)
2	Aerojet General Corporation, Sacramento (AEC)
1	Aerospace Corporation, Los Angeles (AF)
1	Air Force Headquarters
1	Air Force Strategic Air Command
1	Argonne National Laboratory (AEC)
1	Army Redstone Arsenal
2	Army White Sands Missile Range
1	Aro, Inc. (AF)
1	AEC-NASA Space Nuclear Propulsion Office, Nevada
1	Atlantic Richfield Hanford Company
1	Atomics International (AEC)
1	Battelle Memorial Institute (AEC)
6	Battelle-Northwest (AEC)
1	Bellcom, Incorporated (NASA)
1	Brookhaven National Laboratory (AEC)
1	Central Intelligence Agency
1	DOD-DASA-Sandia

UNCLASSIFIED

UNCLASSIFIED

BNWL-853

No. of
Copies

1	DOD-OSD-Director of Defense Research and Engineering
2	Douglas Aircraft Corporation, MSSD (AF)
2	Douglas United Nuclear
1	duPont Company, Aiken (AEC)
1	EG&G, Inc., Goleta (AEC)
1	EG&G, Inc., Las Vegas (AEC)
1	General Dynamics/Fort Worth (AF)
1	General Electric Company, Cincinnati (AEC)
1	General Electric Company (FPD) (NASA)
1	Gulf General Atomic Incorporated (AEC)
1	Institute for Defense Analyses (ARPA)
1	Jet Propulsion Laboratory (NASA)
1	Johns Hopkins University (Navy)
2	Lawrence Radiation Laboratory, Livermore (AEC)
1	Lockheed-Georgia Company (NASA)
2	Los Alamos Scientific Laboratory (AEC)
2	Los Alamos Scientific Laboratory
	R. D. Baker
	D. P. MacMillan
1	NASA Goddard Space Flight Center
1	NASA Langley Research Center
6	NASA Lewis Research Center
6	NASA Lewis Research Center
	N. R. Thielke
1	NASA Manned Spacecraft Center
4	NASA Marshall Space Flight Center
3	NASA Scientific and Technical Information Facility
4	National Reactor Testing Station (Inc) (AEC)
1	Navy Air Systems Command
1	Navy Missile Center
1	Navy Office of the Chief of Naval Operations
2	Navy Ordnance Systems Command
1	Navy Radiological Defense Laboratory
1	Navy Ship Systems Command Headquarters
5	Oak Ridge National Laboratory (AEC)
1	Pratt and Whitney Aircraft Division (NASA)
1	Public Health Service (HEW)
1	Rand Corporation (AF)
1	Rocketdyne (AEC)
1	Rocketdyne (NASA)
3	Sandia Corporation, Albuquerque (AEC)
1	TRW Systems (AEC)
1	Union Carbide Corporation (AEC)

UNCLASSIFIED

UNCLASSIFIED

BNWL-853

No. of
Copies

1 Union Carbide Corporation (Paducah Plant) (AEC)
1 Westinghouse Electric Corporation, Wal (AEC)
10 AEC Division of Technical Information Extension

4 AEC Division of Technical Information Extension
for Transmittal to:

Space Nuclear Propulsion Office
2100 Brookpark
Cleveland, Ohio 44135
L. Corrington

Union Carbide Corporation (ORNL) (OR)
J. M. Napier

Westinghouse Electric Corporation (NASA)
M. B. Blinn
H. Holmgren

17 Battelle-Northwest
L. R. Bunnell
T. D. Chikalla
J. L. Daniel
D. R. de Halas
K. Drumheller
C. E. McNeilly
R. E. Nightingale
J. C. Spanner
G. L. Tingey
E. M. Woodruff
Technical Information Files (5)
Technical Publications (2)

UNCLASSIFIED