LEGAL NOTICE

This report was prepared as an account of Government sponsored work. Neither the United States, nor the Commission, nor any person acting on behalf of the Commission:

A. Makes any warranty or representation, expressed or implied, with respect to the accuracy, completeness, or usefulness of the information contained in this report, or that the use of the information, apparatus, method, or process disclosed in this report may not infringe privately owned rights; or

B. Assumes any liabilities with respect to the use of, or for damages resulting from the use of any information, apparatus, method, or process disclosed in this report.

As used in the above, "person acting on behalf of the Commission" includes any employee or contractor of the Commission, or employee of such contractor, to the extent that such employee or contractor of the Commission, or employee of such contractor prepares, disseminates, or provides access to, any information pursuant to his employment or contract with the Commission, or his employment with such contractor.

Progress in Sintering*

D. R. Wilder

Institute for Atomic Research and Department of Ceramic Engineering
Iowa State University, Ames, Iowa

ABSTRACT

Sintering is broadly defined as all aspects of the adhesion, densification, shrinkage, and consolidation which accompanies the reduction in surface energy of a powder compact which occurs upon application of heat and/or pressure. The process of sintering is then further divided into the initiation, material transport, and grain growth-recrystallization stages. A general review is made of each of these stages, noting typical work which has contributed to progress in each area involved.

Introduction

The purpose of this paper is to review the progress of sintering, with attention to some of the work which marks such progress. It is not an attempt to review the subject exhaustively, but rather to outline the avenues along which the present concept of sintering has traveled during its evolution. Most of the paper is of a review nature for this

* Contribution No. 1115. Work was performed in the Ames Laboratory of the U. S. Atomic Energy Commission. The review presented as the keynote address for the Electrothermics and Metallurgy Program: Sintering of Refractory Metals and Materials, at the Detroit Meeting of the Electrochemical Society, 1961.

Facsimile Price \$ 2.60
Microfilm Price \$ 1.10
Available from the
Office of Technical Services
Department of Commerce
Washington 25, D. C.

This paper was submitted for publication in the open literature at least 6 months prior to the issuance date of this Microcard. Since the U.S.A.E.C. has no evidence that it has been published, the paper is being distributed in Microcard form as a preprint.

IS-460
MASTER

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency Thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

DISCLAIMER

Portions of this document may be illegible in electronic image products. Images are produced from the best available original document.

reason. The papers, comments, and results cited are taken as representative, and are not to be considered all-inclusive of work which might be cited. Exhaustive bibliographies of the subject are readily available (1, 2, 3).

In as general a discussion as this, it is extremely important to make a clear definition of terminology. We wish to make sintering as broad and all-inclusive a process as possible and so will define sintering as any adherence, coherence, or other attachment by which a loose or consolidated mass of particles change on heating to a denser mass. In a general sense, the particles involved should be of identical chemical and structural composition, but may or may not be homogeneous within a given particle. For example, oxide layers on metal particles exist and still the process of consolidation would be defined as sintering. Under such a broad definition of sintering, all phases of the process must be included, from the very first initial activity at low temperatures to grain growth effects at the highest temperatures.

This review is divided into three parts for the sake of clarity. Sintering is actually a continuous process, and these three parts of the process are continuous with one another, but as each becomes the major concern, we tend to isolate it and study it as a separate part. First the initiation of sintering will be considered, next the densification phase, and last the phenomena of recrystallization and grain growth.

Initiation of Sintering

Some of the first work recorded concerning sintering and the recognition of such is attributed to Wollaston, who sintered platinum

sponge and caused a densification to occur in 1725 (4). The sintering of ceramics goes back to a much earlier date, and the origin of this is lost in early history. Even if one excludes the ceramics which are two phased, i. e. vitrified in contrast to sintered, the early glass makers knew how to sinter glass powders into decorative objects.

Much of the very early pioneer work was concerned with the initiation of sintering and the opinion was widely held that a characteristic temperature could be determined for large groups of materials which would relate to the melting temperature. It was found that large groups of materials could be characterized in such a manner, the ionics initiating sintering at the lowest temperature, the silicates next, and the covalents at the highest relative to their respective melting points.

This relative temperature of initiation has been widely described as the ratio of the temperature at which initiation of sintering was observed to the melting temperature, and most frequently termed the Tammann temperature. Typical of studies to determine this ratio, which was thought to be a constant for any group of materials having similar bond characteristics, is that of Tammann and Mansuri (5). A paddle wheel was driven by a friction clutched shaft and the temperature at which a powder in which the paddle was moving arrested the paddle motion sufficiently to cause the clutch to disengage was observed. This experiment was repeated many times with various mechanical arrangements and different materials. The results were not as satisfactory as anticipated, all metals showing an initiation between 120°

and 140°C and the oxides studied exhibited very wide scatter of the ratio of temperature of sintering initiation to melting point.

Interest in sintering became active in the later stages of sintering at about this time and little attention was given to initiation until recently. Activated particles, essentially aggregates and agglomerates of very fine crystallites, have become available and interest in the sintering activity of these particles has rekindled interest in initiation phenomena. The term activation can have two or more meanings. In catalysis the term applies to fine crystallites and the extreme reactivity and sinterability that occurs due to their high surface/volume ratio. However, it is also possible to induce considerable strain energy into metallic powders during the compaction process. This induced strain can also result in a highly "activated" condition with great potential energy at the interfaces which can be released by heating and subsequent sintering initiation.

An example of the first of these activated state processes was studied by Hyde and Duckworth, in an investigation of the sintering of an oxide calcine product derived from basic magnesium carbonate (6). The maximum density achieved by subsequent sintering was shown to be highly dependent upon the calcination temperature as noted in Fig. 1 (6). This is perhaps involved with the initiation of sintering.

Another example of a similar study has been reported by Livey and co-workers (7) with magnesium hydroxide and barium oxide (8). The magnesium hydroxide was calcined under both air and vacuum and measurements were made of the subsequent sintering rate, heat of solution, particle size, and

particle surface. Curves very similar to the curves of Hyde and Duckworth were obtained as shown in Fig. 2 (7).

They found strong indications of water molecules on the surface of the calcined powders, and a sensitivity to the presence or absence of air during the calcination cycle. If the calcination was made in air, the surface areas resulting were less than if the calcination had been made in vacuum. The temperature of calcination was also influential, with heat of solution decreasing with increasing calcination temperature, corresponding to an increasing crystallite size. Growth of crystallites was likewise greater in air than under vacuum. Livey et al. also found good agreement of their sintering rates with the equations predicted by the Mackenzie-Shuttleworth relation (9), which will be taken up later in this discussion.

A basic study of crystallite size has been made by Rosauer and Handy (10) on magnesium carbonate. A refined x-ray technique for evaluation of line broadening was used to establish crystallite size and growth kinetics. Crystallite growth was found to be very slow at calcination temperatures below about 600°C. Above this temperature, growth becomes quite rapid, changing in the particular carbonate studied from 0.0152 μ to 1.13 μ by 1600°C. Good correlation is obtained with surface measurements (BET) as shown in Table I (10). This abrupt change in growth rate also agrees well with the work of Livey, et al. (9). Rosauer found maximum sintering could be expected when the coincidence of a clean, dehydrated surface, and a minimum crystallite size occurred.

Some further work on this subject was done by Wilder (11) on fused aluminum oxide. The surface structures and the ions absorbed thereon were evaluated by infrared absorption and the slaking and sintering characteristics of the compacts measured after heat treatment. An abrupt change in strength and slaking characteristics occurs between 500° and 600°C. Above this temperature strength increases rapidly and the ability of the compact to slake in water disappears. The conclusions from this investigation were that newly heated, fused aluminum oxide becomes actively engaged in sintering only after the surface adsorbed water is lost, i. e. both water and OH molecules are driven from the surface. It was further found that if the high temperature was not extended and/or maintained sufficiently for sintering to commence, the adsorption of OH and water molecules on the surface was reversible. After sintering has begun, slaking cannot occur nor will the reversal of the adsorption be possible.

In summary, the availability of and interest in activated powders have created new interest in the initiation of sintering. In metallic materials the strain energy induced at the particle interfaces by cold compaction probably dominates the initiation. In oxides and similar non-ductile materials, the nature of the surfaces is less well understood. Clean surfaces, or newly exposed, are essential, but the exact kinetics of initiation are not well understood.

Material Transport Phase

It is widely accepted and understood that any consolidation and shrinkage must be brought about by material transport. The idealized model

of this transport is the well known configuration of two spheres, the lens shaped area between these spheres being filled by transport of material from the spheres to the lens shaped volume between. Obviously such a transport will reduce the free surface, and thus can be attributed to a reduction in free energy. The question arises next, by what mechanism is this transport achieved, and equally important, how can it be controlled?

It is likewise generally accepted that four modes of material transport are feasible. Evaporation and condensation or transport by the vapor phase, surface diffusion or motion of ions on the surface of the particles, volume diffusion or ion motion through the particles, and macroflow, either viscous or plastic, of large groups of ions. Understanding and progress in this area are largely attributable to the efforts of Kuczynski (12, 13) and others who have been attracted to his model and excellent method. It consists essentially of following the bonding of a sphere to a plate or to another sphere by measuring the radius of the interspherical volume formed during isothermal treatment. The relations then derived are summarized in Table II and have been expanded to many other problems with a variety of materials with good success (14). The work of Shaler and Wulff (15) should also be noted and also the comments of Cabrera (16) on the experiments of Kuczynski should be considered. The important point is that these experiments were performed and they lend a great deal of support to a volume diffusion mechanism being

the dominant mode of material transport in the materials studied and under the size, atmosphere, and other conditions imposed as part of the experiments. However, it is easy to assume volume diffusion is the only mechanism by which sintering occurs. Looking at the entire spectrum of materials, viscous flow is generally accepted as the dominant mechanism in glasses, and Clark and White (17) have presented excellent evidence of plastic flow in ionic crystals.

The contribution of Herring (18) to this question of mode of material transport has had a large effect. From basic fundamentals, he predicted the scale relations which would be expected between particle size and shrinkage. As shown in Table III, these relations are simple for monodisperse fractions and amenable to experimental verification. These parameters have been applied to aluminum oxide, as shown in Fig. 3 (19). The straight line shown is very near the slope predicted by Herring's scalar laws for plastic flow with the fractions studied. The particular progress achieved here is the realization and graphic illustration that more than one mode of material transport may occur in any given material, and that any one might be dominant, depending on the ambient conditions of such transport.

The Clark-White model (17) is pioneer work based on an equation derived to fit the entire sintering curve over the open pore region. A number of parameters are included which may be changed depending on the mechanism which is found to be dominant. The fundamental assumption is that the material transport is by plastic flow. Similar work has been reported by Mackenzie and Shuttleworth (9) for the later closed pore stage. Both of these equations have been criticized for

the large number of terms incorporated as correcting terms, but they are the only efforts exhibiting any success to describe large portions of the sintering curves with a single equation.

Kingery and Berg (20) assumed a volume diffusion as a dominant mechanism and using the Kuczynski model, found the fractional shrinkage to be proportional to the $2/5$ power of time. Experimental data have been presented to prove the accuracy of their derivation over certain ranges of particle size and material. It, however, has been found to be applicable only when the pores are connected by grain boundaries, i. e., only in the early stages of the process.

An analysis of the Kuczynski and other spherical models has been made by Coble (21) with special attention to the mechanism by which vacancies are eliminated. Of the four possible schemes of vacancy elimination shown in Fig. 4, only I and II, with the grain boundary acting as a sink, should be expected to contribute to shrinkage for spherical models. Based on this analysis, and after some excellent experimental measurements, Coble concludes bulk diffusion is the dominant mechanism of material transport in the sintering of aluminum oxide and ferric oxide while shrinkage is active.

Other work of great significance concerning the volume diffusion model is the classic experiment of Alexander and Balluffi (22) with fine copper wire wound on a mandrel. Polished sections made after sintering showed the shrinkage of the pores continued as long as such pores were connected by grain boundaries. As soon as the

pores became isolated, they ceased to shrink. The explanation of this, that the grain boundaries act as vacancy sinks, is usually attributed to the suggestions of Nabarro (23) and Herring (24).

To accentuate the influence of a single contributing factor to sintering, it is fortunate that quite a lot of work has been done by necessity on hot-pressing of refractory oxides. Here the pressure variable is magnified to the point of being the dominant factor.

The work of Murray, Livey, and Williams (25) contributes a great deal to this question. In their consideration of a wide variety of metals, ceramics, and intermetallics, they found the rate of densification to be increased in all cases by application of pressure while at the maximum temperature, and that an end-point bulk density could be observed for each temperature and pressure. It should also be noted that there is a limiting pressure, however; i. e., when the pressure exceeds the fracture stress, densification will not occur. Thus, as expected, hot-pressing produces greater relative densification in ductile metals than in brittle ceramics or intermetallics.

A further question is raised by Murray, et al., concerning extremely fine powders. They suggest such powders may sinter well under the application of external (hot-press) loading due to the nearly viscous behavior of the very fine particles, i. e. $<0.1 \mu$. It is known that extremely high temperature calcination can destroy this ability, and that it can be restored by allowing the powder to age for several months or years. They suggest that the high calci-

nation creates grain growth of the fine crystallites, and that aging creates a layer of hydroxide which decomposes on heating and forms a pseudo-viscous fine particle material which can contribute to the powders ability to densify under hot-pressing conditions.

Returning to the question of plastic flow, one asks what the elastic or flow properties are at the temperatures in question. Scott, Hall, and Williams (26) investigated this problem, correlating the variation in flow properties in uranium oxide with the variation in stoichiometry. It has been well established that excess oxygen beyond that required for stoichiometric UO_2 is advantageous to sintering and hot-pressing. Figure 5 the results of Scott, et al., show this variation in flow properties with varying oxygen content. The flow at the extreme is similar to creep as it occurs in ductile metals. The importance of this work is the qualitative correlation of deviation from stoichiometry, sintering, and flow properties at elevated temperatures.

The conclusions that may be drawn from this discussion of material transport still leave the fundamental questions only partially answered. Factors which have contributed to the answers include the good model systems, which have permitted the collection of quantitative data. Also the recognition of scalar relations to incorporate particle size effects into the understanding must be considered. An especially useful concept is the understanding that more than one mechanism may be operative in any given material. So while some materials are well understood, and the dominant material transport mode has been established, such clarity does not prevail for all materials.

Grain Growth and Recrystallization

The somewhat similar nature of grain growth and recrystallization has been a point of much confusion between metallurgists and ceramists. The terminology of powder metallurgy has not been as widely adapted by ceramists as it deserves.

By definition, primary recrystallization will be considered the nucleation and growth of a new generation of strain free (or nearly so) grains from a matrix which has been plastically deformed. Obviously, if no deformation can occur, as is the condition approached in many ceramics, such a driving force will not exist and primary recrystallization will not occur. Exceptions to this in ionics are magnesium oxide and the halides, where plastic deformation has been observed. Furthermore, if the powder compact has been heated above the yield temperature, the strain will be relieved, and no driving force will exist.

Grain growth is construed to mean the growth of the average particle size in a compact at the expense of some of the particles. It is fairly common in both ceramics and metals, the driving force being simply the reduction in surface energy as the surface/volume ratio decreases.

Secondary recrystallization is often termed discontinuous grain growth. A few large grains grow at the expense of large numbers of the smaller grains making up the matrix. As we shall see, this mechanism is fairly common in ceramic materials.

All three of the above effects contribute to changes in the microstructure, and have been observed and discussed extensively (27, 28). We will discuss each briefly.

Primary recrystallization has long been thought to be a highly influential factor in sintering. The recent improvement in the understanding of material transport has somewhat diminished this impression. It obviously has its greatest influence with highly deformed metals and probably has its least influence with brittle ceramics.

Grain growth will commence after any primary recrystallization has been completed, and such grain boundary migration can proceed quite rapidly in a strain-free matrix, provided the material transport mechanism has reduced the pore volume sufficiently, i. e. below about 15% porosity or above a relative density of 0.8. An example of this limiting value is shown in Fig. 6. Note the very rapid change in the ratio of final grain size to initial particle size as the porosity diminishes. It has been further noted by Burke (29) that even melting and resolidifying a metal will not cause the boundary migration (grain growth) to cease.

The contributions of Vogel (30), Bragg (31), Burke (32) and others concerning the curvature of the grain boundaries were major contributions. Essentially, it is now understood that the rate of movement of the grain boundary is roughly inversely proportional to the radius of curvature of the grain interface and that roughly grains having more than six sides in a two-dimensional system will grow at the expense of grains having less than six sides. The direction of growth (grain boundary migration) is shown in Fig. 7. While this concept is not absolute, being based on an idealized system, its accuracy is very well supported by photomicrographs of actual systems. The driving force is universally accepted to be reduction in surface energy.

Why doesn't grain growth continue until the ultimate, a single crystal, results Grain boundaries cannot migrate past large inclusions, impurities, or other major defects in the lattice. This can be considered in a gross manner, that the boundary cannot change its energy sufficiently to move past the disturbed zone, or more accurately, the surface dislocations by which the grain boundary moves are blocked by the inclusion or disturbed zone. Excellent evidence of each blocking has been given by Burke (32).

Secondary recrystallization, or discontinuous grain growth, is somewhat different. Both primary recrystallization and normal grain growth concern situations where the grain sizes are, and remain, approximately equal. But it has long been known, that while normal grain growth can be stopped by inclusions of a calculable size (33) the incorporation of grains much larger than this size will result in discontinuous grain growth. This puzzle existed for some time in an unsolved condition, since it made possible a larger final grain size from roughly smaller material than from larger material. It can be explained by considering the grain size distribution in the two sizes. In a very small sized initial powder, the ratio of largest grains to smallest grains may be quite large. But in a coarser initial powder, the grain size distribution may not be nearly as great. Therefore the initially smaller material will be much more likely to exhibit extensive secondary recrystallization than the larger initial material. Secondary recrystallization thus can be considered similar to grain growth, if the appropriate geometric considerations are applied to the factors which limit the growth.

An interesting secondary characteristic of discontinuous grain growth concerns the decreasing rate of migration as the grains become larger. At the slow rates involved, there is sufficient time for pores to migrate to the grain boundaries by diffusional processes. The "sweeping" effect of a grain boundary, as noted by Burke (32) is shown in Fig. 8 and has been further noted by Coble (21).

An exact understanding of grain boundary effects will come through expansion of our knowledge of their motion. Work with dislocation concentrations at grain boundaries and bicrystal interfaces is underway and will aid greatly in understanding the motion of these boundaries.

Summary

Comparing the progress which has been made in understanding the three stages of sintering, we must conclude that relatively little is known about the initiation stage. The kinetics of the initiation need attention and the early stages of sintering, where shrinkage has just started, needs further study.

The material transport stages are better understood. The mechanisms are more widely accepted. The factors which influence these mechanisms are not as well recognized and understood, but this stage is still probably the best known of the three.

Grain growth and recrystallization rates lend themselves to easier measurement than the above problems and so the rates have been well established. The mechanisms here are not as well understood.

REFERENCES

1. H. B. Michaelson, The Theories of the Sintering Process. A Guide to the Literature. Sylvania Electric Products, Inc., Atomic Energy Commission Report SEP-80 (1951).
2. C. G. Goetzel, "Treatise on Powder Metallurgy," Vol. II, Chap. 35, Interscience Publishers, Inc., New York (1950).
3. D. R. Wilder, Sintering Mechanism as Applied to Refractory Oxides. Ames Laboratory, Atomic Energy Commission Report ISC-288 (1952), Supplement I (1956), Supplement II (1960).
4. C. S. Smith, "History of Powder Metallurgy," Powder Metallurgy, Am. Soc. Metals, Cleveland (1942).
5. G. Tammaun and Q. A. Mansuri, Z. anorg. u. allgem. Chem., 126, 119 (1923).
6. C. Hyde and W. H. Duckworth, Investigation of Sinterable Powders and Ceramics Made from Them, Wright Air Development Division Tech. Report 61-262, U. S. Air Force, Wright-Patterson Air Force Base, Ohio (1961).
7. D. T. Livey, B. M. Wanklyn, M. Hewitt, and P. Murray, Trans. Brit. Ceram. Soc., 56, 217 (1957).
8. D. T. Livey and D. Murry, Nature, 182, 1362 (1958).
9. J. K. MacKenzie and R. Shuttleworth, Proc. Phys. Soc., No. 12, 62, 833 (1949).
10. E. A. Rosauer and R. L. Handy, Iowa Acad. of Science, 68, 357 (1961).
11. D. R. Wilder, unpublished work.
12. G. C. Kuczynski, J. Metals, 1 (2), Trans. 169 (1949).

13. G. C. Kuczynski, J. Appl. Phys., 21, 632 (1950).
14. G. C. Kuczynski and I. Zaplatynskyj, J. Am. Ceram. Soc., 39, 349 (1956).
15. A. J. Shaler and J. Wulff, Phys. Rev., 73, 926 (1948).
16. N. Cabrera, Trans. Am. Inst. Mining Met. Engrs., 188, 667 (1950).
17. P. W. Clark and J. White, Trans. Brit. Ceram. Soc., 49, 305 (1950).
18. C. Herring, J. Applied Phys., 21, 301 (1950).
19. D. R. Wilder and E. J. Fitzsimmons, J. Am. Ceram. Soc., 38, 66 (1955).
20. W. D. Kingery and M. Berg, J. Applied Phys., 26, 1205 (1955).
21. R. L. Coble, J. Am. Ceram. Soc., 41, 55 (1958).
22. B. H. Alexander and R. W. Balluffi, J. Metals, 2, 1219 (1950).
23. F. R. N. Nabarro, Deformation of Crystals by Motion of Single Ions, Rept. Conf. Strength of Solids (Univ. Bristol) (1948).
24. C. Herring, J. Appl. Phys., 21, 437 (1950).
25. P. Murray, D. T. Livey, and J. Williams, "Hot Pressing of Ceramics," in Ceramic Fabrication Processes, ed. by W. D. Kingery, Technology Press of Massachusetts Institute of Technology and John Wiley and Sons, New York (1959).
26. R. Scott, A. Hall, and J. Williams, J. Nucl. Matr., 1, 39 (1959).
27. J. E. Burke, "Grain Growth in Ceramics," in Kinetics of High Temperature Processes, ed. by W. D. Kingery, Technology Press of Massachusetts Institute of Technology and John Wiley and Sons, Inc., New York (1959).
28. J. E. Burke, J. Am. Ceram. Soc., 40, 80 (1957).
29. J. E. Burke, "The Migration of Grain Boundaries," in Atomic Movements, Am. Soc. Metals, Cleveland (1951).

30. R. Vogel, Zeit. für anorg. u. allgem. Chem., 126, 1 (1923).
31. W. L. Bragg, Proc. Phys. Soc., London, 52, 105 (1940).
32. J. E. Burke, "Recrystallization and Sintering in Ceramics," in Ceramic Fabrication Processes, John Wiley and Sons, Inc., New York (1958).
33. C. Zener, noted by C. S. Smith, Trans. Am. Inst. Mining Met. Engrs., 175, 15 (1948).

Table I. Sizes of MgO crystallites and aggregates (10)

Temp. , °C	Crystallites (μ)	Aggregates (μ)
400	0.00369	3.73
600	0.0153	4.16
800	0.0721	4.34
1000	0.143	4.90
1600	1.130	5.35

Table II. Correlation of neck radius, sintering mechanism and time at temperature (12)

Viscous flow	$x^2 \sim t$
Evaporation-condensation	$x^3 \sim t$
Volume diffusion	$x^5 \sim t$
Surface diffusion	$x^7 \sim t$

Table III. Correlation of particle size ratios, sintering mechanism, and shrinkage (18)

$$\Delta t_2 = \lambda^n \Delta t_1$$

$$r_2 = \lambda r_1$$

Where Δt_2 , Δt_1 are the time intervals required to produce identical change in compacts of particles of size r_2 and r_1 respectively.

Viscous flow	$n = 1$
Evaporation-condensation	$n = 2$
Volume diffusion	$n = 3$
Surface diffusion	$n = 4$

FIGURE CAPTIONS

- Fig. 1. Sintered density of magnesia prepared from different calcines (6).
- Fig. 2. Sintered density of magnesia prepared from different calcines (7).
- Fig. 3. Application of Herring scalar laws to shrinkage data for aluminum oxide (19).
- Fig. 4. Vacancy sources, sinks, and paths for sintering between pairs of particles (21).
- Fig. 5. Creep curves for uranium oxides at 1200 g load (26).
- Fig. 6. Grain growth vs relative density for aluminum oxide (19).
- Fig. 7. Schematic of polycrystalline specimen showing direction of grain boundary motion (32).
- Fig. 8. Sweeping of pores by grain boundary motion (32).

Fig. 1. Sintered density of magnesia prepared from different calcines (6).

Fig. 2. Sintered density of magnesia prepared from different calcines (7).

Fig. 3. Application of Herring scalar laws to shrinkage data for aluminum oxide (19).

Fig. 4. Vacancy sources, sinks, and paths for sintering between pairs of particles (21).

Fig. 5. Creep curves for uranium oxides at 1200 g load (26).

Fig. 6. Grain growth vs relative density for aluminum oxide (19).

Fig. 7. Schematic of polycrystalline specimen showing direction of grain boundary motion (32).

Fig. 8. Sweeping of pores by grain boundary motion (32).