304
RECEIVED BY TIC FEB 16 1972

MASTER

GEAP-12246
AEC RESEARCH AND
DEVELOPMENT REPORT
OCTOBER 1971

FISSION GAS RE-SOLUTION RATES

Quarterly Report No. 5
July 1 to September 30, 1971

M. O. MARLOWE

U. S. ATOMIC ENERGY COMMISSION
CONTRACT AT(04-3)-189
PROJECT AGREEMENT 56

NUCLEAR TECHNOLOGY & APPLICATIONS OPERATION • GENERAL ELECTRIC COMPANY
VALLECITOS NUCLEAR CENTER, PLEASANTON, CALIFORNIA 94566

GENERAL ELECTRIC

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency Thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

DISCLAIMER

Portions of this document may be illegible in electronic image products. Images are produced from the best available original document.

FISSION GAS RE-SOLUTION RATES

Quarterly Report No. 5 — July 1 to September 30, 1971

M. O. Marlowe

Approved:

**A. I. Kaznoff, Manager
Metallurgy and Ceramics Laboratory
Nucleonics Laboratories**

**Prepared for the
United States Atomic Energy Commission
Division of Reactor Development and Technology
Contract No. AT(04-3)-189, Project Agreement PA-56**

NOTICE

This report was prepared as an account of work sponsored by the United States Government. Neither the United States nor the United States Atomic Energy Commission, nor any of their employees, nor any of their contractors, subcontractors, or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness or usefulness of any information, apparatus, product or process disclosed, or represents that its use would not infringe privately owned rights.

**NUCLEAR TECHNOLOGY & APPLICATIONS OPERATION • GENERAL ELECTRIC COMPANY
VALLECITOS NUCLEAR CENTER, PLEASANTON, CALIFORNIA 94566**

3550-NT&AO-33
95-DAC/mea-12/71

GENERAL ELECTRIC

LEGAL NOTICE

This report was prepared as an account of work sponsored by the United States Government. Neither the United States nor the United States Atomic Energy Commission, nor any of their employees, nor any of their contractors, subcontractors, or their employees, make any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness or usefulness of any information, apparatus, product or process disclosed, or represents that its use would not infringe privately owned rights.

CONTENTS

	<u>Page</u>
ABSTRACT	1
INTRODUCTION	1
CHARACTERIZATION OF AS-IRRADIATED UO ₂ SAMPLES	1
FISSION GAS BUBBLE DEVELOPED BY IN-SITU ANNEALING OF IRRADIATED UO ₂ IN THE ELECTRON BEAM MICROSCOPE	2
FISSION GAS BUBBLES DEVELOPED IN IRRADIATED UO ₂ BY POST-IRRADIATION ANNEALING	2
REFERENCES	26

FISSION GAS RE-SOLUTION RATES

Quarterly Report No. 5 – July 1 to September 30, 1971

M. O. Marlowe

ABSTRACT

This fifth quarterly report describes progress in an experimental program to determine the re-resolution rates of fission gases in oxide nuclear fuels under irradiation. As-irradiated specimens at burnups of approximately 0.1, 1.2 and 3.2×10^{20} fissions/cm³ were examined by transmission electron microscopy. Considerable radiation damage and some dislocations that were not present in the as-fabricated samples were observed. No fission gas bubbles were detected. Annealing of the irradiated specimens in the electron microscope at high beam currents produced fission gas bubbles. Specimens annealed at 1300°C for 16 hours exhibited detectable bubbles only on grain boundaries and at dislocations. A specimen which was heated to 1575°C after irradiation showed an essentially uniform concentration of bubbles with a log-normal size distribution; the geometric mean diameter was 72 Å and the geometric standard deviation was 1.42.

INTRODUCTION

This is the fifth quarterly progress report on the status of the experimental program and studies being conducted to determine the re-resolution rates of fission gases in oxide nuclear fuels. Characterization of as-irradiated UO₂ specimens ($T_{\text{irradiation}} < 550^\circ\text{C}$) and comparison with the unirradiated material by transmission electron microscopy was completed. Progress toward characterization of post-irradiation annealed specimens and delineation of an annealing process for development of a desirable fission gas bubble concentration and size distribution for further experimentation is presented.

CHARACTERIZATION OF AS-IRRADIATED UO₂ SAMPLES

Three as-irradiated UO₂ specimens of natural, 10% and 25% U-235 enrichment were prepared for transmission electron microscopy by the techniques previously developed.¹ The calculated maximum temperature of the specimens during irradiation did not exceed 550°C.² The sample designations and burnups as previously reported are noted below (Table 1).

TABLE 1. Description of Specimens for As-Irradiated Characterization

Specimen Number	U-235 Enrichment (%)	Burnup (f/cc $\times 10^{-20}$)
N-5	Natural	0.091
10-5	10	1.266
25-5	25	3.208

For interpretation of those results, it is necessary to first consider the transmission electron microscopy of unirradiated specimens of the same material, prepared by the same techniques. Those specimens were prepared previously.¹ Examples of the electron micrographs obtained of the unirradiated material are shown in Figures 1 to 3. The specimen preparation technique which incorporates final thinning by an ion-milling process, produces considerable black-spot radiation damage, as is apparent in all three of the micrographs. The ion-milling technique also produces surface irregularities in the foil; that feature can be distinguished and therefore accounted for in interpretation of the micrographs by use of stereo pairs. (See Figure 3.) The unirradiated specimens showed a dearth of dislocations and no precipitates that might be interpreted as fission gas bubbles. Because of this latter observation, the specimens produced by the thinning technique were judged to be acceptable, although they leave much to be desired because of the black-spot damage and surface roughness.

By comparison with the unirradiated samples, the as-irradiated material showed essentially the same microstructure as determined by transmission electron microscopy. The only distinguishing feature was an increased dislocation density. Examples of the electron micrographs of the three as-irradiated samples are shown in Figures 4 through 10. Black-spot damage is prevalent in the as-irradiated specimens, but is not distinguishable from that produced in the unirradiated specimens produced by the specimen preparation process. There was no evidence of any precipitates, including fission gas bubbles.

FISSION GAS BUBBLE DEVELOPED BY IN-SITU ANNEALING OF IRRADIATED UO_2 IN THE ELECTRON MICROSCOPE

After thorough examination in the as-irradiated condition, a small area of specimen 25-5 was annealed in-situ in the electron microscope at high electron beam intensity. The heating process produced a clearing of the observed structure as a result of annealing of the black-spot damage. Fission gas bubbles were also observed throughout the annealed area (Figures 11 to 13) with some evidence of enhanced bubble density on grain boundaries and larger bubbles with correspondingly larger denuded zones near dislocations. The fission gas bubbles were in the size range 35-220 Å diameter. The estimated bubble density (assuming that the specimen thickness is 1000 Å) was in the range 10^{16} – $10^{17}/\text{cm}^3$. Associated with essentially all of the fission gas bubbles is a black-spot which is probably solid fission product precipitates.³ Other black spots, also probably solid fission product precipitates, were observed which were not associated with bubbles (Figure 13).

FISSION GAS BUBBLES DEVELOPED IN IRRADIATED UO_2 BY POST-IRRADIATION ANNEALING

Three specimens that were annealed after irradiation were examined by transmission electron microscopy. Those specimens and the annealing treatment are summarized in Table 2.

TABLE 2. Description of Irradiated and Annealed UO_2 Specimens

Specimen Number	U-235 Enrichment (%)	Burnup (f/cc X 10^{-20})	Annealing Temperature (°C)	Annealing Time (hours)
10-1	10	0.678	1300	16
10-11	10	0.678	1300	16
10-12	10	0.913	1575	0

The annealing conditions were chosen on the basis of the observations of Cornell.⁴ He observed average gas bubble diameters of approximately 56 Å after annealing specimens with gas contents similar to the specimens used here for 16 hours at 1300°C. One hour at 1600°C produced bubbles approximately 96 Å in diameter; after only 5 minutes at 1600°C he observed the bubble diameter to already be ~ 88 Å.

The specimens annealed at 1300°C for 16 hours showed measurable fission gas bubbles mainly on dislocations or on grain boundaries. A few bubbles were observed in the bulk material but they were largely unresolved. Examples of the electron micrographs obtained on those specimens are shown in Figure 14 and 15. Since those electron micrographs were taken, a mechanical problem with the electron microscope specimen stage which allowed excessive vibration of the specimen and attendant poor resolution was noted and corrected. Those specimens will be re-examined in an attempt to better characterize the bubble distributions. The initial indications are, however, that 1300°C is not a sufficiently high temperature to develop bubbles large enough for thorough characterization as required for the remaining experimental tasks of the study.

As previously noted in reference 1, specimen 10-12 was heated to 1575°C, at which point electrical difficulties terminated the run and the specimen was allowed to cool. Electron micrographs of that specimen show a well developed bubble distribution (Figures 16 to 19). Bubbles on dislocations and grain boundaries are considerable larger than the matrix bubbles, and many of the larger bubbles appear to be faceted.

Photographic enlargements corresponding to a magnification of approximately 300,000X were used to characterize the size distribution of the matrix fission gas bubbles. Bubbles on dislocations or grain boundaries were ignored in the size distribution analysis. The size distribution was obtained using a Zeiss particle size analyzer; a total of 1565 bubbles were measured. The bubble diameter was taken as the mid-diameter of the dark ring defining the bubbles.⁵ A histogram of the bubble size measurements is shown in Figure 20. A cumulative percent finer size distribution was calculated from the results and is listed in Table 3. The bubble size distribution (Table 3) was plotted on both standard normal and log-normal probability paper. The standard normal plot showed considerable curvature, indicating that the bubble diameters are not normally distributed. However, the log-normal plot of the bubble size distribution (Figure 21) is essentially linear, indicating a normal distribution of the logarithm of the bubble diameters. The "best fit" (by eye) line drawn through the data in Figure 21 gives a geometric mean diameter of 72 Å and a geometric standard deviation of 1.42. Those two values are sufficient to completely characterize the bubble size distribution. Re-examination of the data of Cornell⁴ showed that the bubble size distribution he obtained after 1300°C annealing could also be well described as a log-normal distribution. Successive annealing coarsened the bubble sizes and produced a decrease in the geometric standard deviation as noted by Markworth and Baroody,⁶ but the log-normal character of the bubble size distribution was maintained. Cornell's results, after annealing at 1300°C for 0.5, 4, and 16 hours are shown in Figure 22.

The estimated bubble density was $1.1 \times 10^{16}/\text{cm}^3$ in specimen 10-12, but that estimate was only based on an assumed specimen thickness of 1000 Å. Attempts to date to determine the specimen thickness have not been successful.

TABLE 3. Cumulative Bubble Size Distribution for Sample 10-12
After Heating to 1575°C

<u>% Finer</u>	<u>Diameter (Å)</u>
100	271
99.93	259
99.93	246
99.87	234
99.87	222
99.87	210
99.74	197
99.68	185
99.29	173
99.16	161
99.04	148
97.76	136
96.23	124
92.26	111
83.32	99
68.88	87
45.23	75
26.38	62
11.56	50
2.61	38
0.38	26

FIGURE 1. ELECTRON MICROGRAPH OF UNIRRADIATED UO_2

FIGURE 2. ELECTRON MICROGRAPH OF UNIRRADIATED UO_2

FIGURE 3. ELECTRON MICROGRAPH OF UNIRRADIATED UO_2 (Note Surface Irregularities)

FIGURE 4. ELECTRON MICROGRAPH OF SAMPLE N-5, AS-IRRADIATED

FIGURE 5. ELECTRON MICROGRAPH OF SAMPLE N-5, AS-IRRADIATED

FIGURE 6. ELECTRON MICROGRAPH OF SAMPLE N-5, AS-IRRADIATED

FIGURE 7. ELECTRON MICROGRAPH OF SAMPLE 10-5, AS-IRRADIATED

FIGURE 8. ELECTRON MICROGRAPH OF SAMPLE 10-5, AS-IRRADIATED

FIGURE 9. ELECTRON MICROGRAPH OF SAMPLE 25-5, AS-IRRADIATED

FIGURE 10. ELECTRON MICROGRAPH OF SAMPLE 25-5, AS-IRRADIATED

FIGURE 11. ELECTRON MICROGRAPH OF IN-SITU ELECTRON BEAM ANNEALED, IRRADIATED UO_2 (Sample 25-5)

FIGURE 12. ELECTRON MICROGRAPH OF IN-SITU ELECTRON BEAM ANNEALED, IRRADIATED UO₂ (Sample 25-5)

FIGURE 13. ELECTRON MICROGRAPH OF IN-SITU ELECTRON BEAM ANNEALED, IRRADIATED UO_2 (Sample 25-5)

FIGURE 14. ELECTRON MICROGRAPH OF SPECIMEN 10-11 AFTER ANNEALING AT 1300°C FOR 16 HOURS

FIGURE 15. ELECTRON MICROGRAPH OF SPECIMEN 10-11 AFTER ANNEALING AT 1300°C FOR 16 HOURS

FIGURE 16. ELECTRON MICROGRAPH OF SPECIMEN 10-12, HEATED TO 1575°C AFTER IRRADIATION

FIGURE 17. ELECTRON MICROGRAPH OF SPECIMEN 10-12, HEATED TO 1575°C AFTER IRRADIATION

FIGURE 18. ELECTRON MICROGRAPH OF SPECIMEN 10-12, HEATED TO 1575°C AFTER IRRADIATION

FIGURE 19. ELECTRON MICROGRAPH OF SPECIMEN 10-12, HEATED TO 1575°C AFTER IRRADIATION
(The large faceted bubbles in the lower portion of the micrograph lie on a grain boundary)

FIGURE 20. HISTOGRAM OF BUBBLE SIZE DISTRIBUTION ON SPECIMEN HEATED TO 1575°C AFTER IRRADIATION

FIGURE 21. LOG-NORMAL PROBABILITY PLOT OF BUBBLE SIZE DISTRIBUTION
ON SPECIMEN HEATED TO 1575°C AFTER IRRADIATION

FIGURE 22. DISTRIBUTION OF BUBBLE SIZES OBTAINED BY CORNELL⁴ ON ANNEALING AT 1300°C FOR INDICATED TIME

REFERENCES

1. M. O. Marlowe, *Fission Gas Re-Solution Rates, Quarterly Report No. 4, April 1 to June 30, 1971*, GEAP-12217, 1971.
2. M. O. Marlowe, *Fission Gas Re-Solution Rates, Quarterly Report No. 1, July 1 to September 30, 1970*, GEAP-12147, 1970.
3. A. D. Whapham, "Electron Microscope Observation of the Fission Gas Bubble Distribution in UO_2 ," *Nuclear Applications* 2 123-130, 1966.
4. R. M. Cornell, "The Growth of Fission Gas Bubbles in Irradiated Uranium Dioxide," *Phil. Mag.*, 19, 539-554, 1969.
5. M. E. Gulden, "Migration of Gas Bubbles in Irradiated Uranium Dioxide," *J. Nucl. Materials* 23, 30-36, 1967.
6. A. J. Markworth and E. M. Baroody, "Size Distribution Effects in the Precipitation of Inert Gas Bubbles in Solids," *Metal Science Journal* 5, 55-57, 1971.

PREVIOUS REPORTS IN THIS SERIES

1. GEAP-12147, *Fission Gas Re-Solution Rates, Quarterly Report No. 1, July, 1 to September 30, 1970*, September 1970.
2. GEAP-12148, *Fission Gas Re-Solution Rates: Limitations of Fission Gas Bubble Growth by the Re-Solution Process*, November 1970.
3. GEAP-12189, *Fission Gas Re-Solution Rates, Quarterly Report No. 2, October 1 to December 31, 1970*, January 1971.
4. GEAP-12189, *Fission Gas Re-Solution Rates, Quarterly Report No. 3, January 1 to March 31, 1971*, April 1971.
5. GEAP-12217, *Fission Gas Re-Solution Rates, Quarterly Report No. 4, April 1 to June 30, 1971*, July 1971.

DISTRIBUTION

	<u>Copies</u>		<u>Copies</u>
Assistant Director, Engineering Standards U.S. Atomic Energy Commission Division of Reactor Development and Technology, Headquarters Washington, D.C. 20545	1	Chief, Reactor Vessels Branch U.S. Atomic Energy Commission Division of Reactor Development and Technology, Headquarters Washington, D.C. 20545	1
Assistant Director, Nuclear Safety U.S. Atomic Energy Commission Division of Reactor Development and Technology, Headquarters Washington, D.C. 20545	1	Assistant Director for Pacific Northwest Programs, RDT U.S. Atomic Energy Commission P.O. Box 550 Richland, Washington 99352	1
Assistant Director, Plant Engineering U.S. Atomic Energy Commission Division of Reactor Development and Technology, Headquarters Washington, D.C. 20545	1	RDT Site Office U.S. Atomic Energy Commission Argonne National Laboratory Building 2 Argonne, Illinois 60439	1
Assistant Director, Program Analysis U.S. Atomic Energy Commission Division of Reactor Development and Technology, Headquarters Washington, D.C. 20545	1	RDT Site Office U.S. Atomic Energy Commission Argonne National Laboratory P.O. Box 2108 Idaho Falls, Idaho 83401	1
Assistant Director, Project Management U.S. Atomic Energy Commission Division of Reactor Development and Technology, Headquarters Washington, D.C. 20545	2	RDT Site Office U.S. Atomic Energy Commission Atomic Power Development Associates 1911 First Street Detroit, Michigan 48226	1
Assistant Director, Reactor Engineering U.S. Atomic Energy Commission Division of Reactor Development and Technology, Headquarters Washington, D.C. 20545	2	RDT Site Office U.S. Atomic Energy Commission Atomics International P.O. Box 1446 Canoga Park, California 91304	1
Assistant Director, Reactor Technology U.S. Atomic Energy Commission Division of Reactor Development and Technology, Headquarters Washington, D.C. 20545	1	RDT Site Office U.S. Atomic Energy Commission General Electric Company 310 DeGuigne Drive Sunnyvale, California 94086	1
Chief, Fuels and Materials Branch U.S. Atomic Energy Commission Division of Reactor Development and Technology, Headquarters Washington, D.C. 20545	3	RDT Site Office U.S. Atomic Energy Commission Gulf General Atomic P.O. Box 2325 San Diego, California 92112	1
Chief, Fuel Engineering Branch U.S. Atomic Energy Commission Division of Reactor Development and Technology, Headquarters Washington, D.C. 20545	1	RDT Site Office U.S. Atomic Energy Commission Oak Ridge National Laboratory P.O. Box X Oak Ridge, Tennessee 37830	1

RDT Site Office	1	Director, Metallurgy and Materials	1
Pacific Northwest Laboratory		Science Division	
U.S. Atomic Energy Commission		Brookhaven National Laboratory	
P.O. Box 550		Upton, New York 11973	
Richland, Washington 99352			
Division of Naval Reactors	1	Director, Metals and Ceramics Division	2
Chief, Nuclear Materials Branch		Oak Ridge National Laboratory	
U.S. Atomic Energy Commission		P.O. Box X	
Washington, D.C. 20545		Oak Ridge, Tennessee 37830	
Division of Technical Information Extension	3*	Division Chief, M & S Division	1
U.S. Atomic Energy Commission		NASA — Lewis Research Center	
P.O. Box 62		2100 Brook Park Road	
Oak Ridge, Tennessee 37831		Cleveland, Ohio 44135	
Manager	2	Director	1
U.S. Atomic Energy Commission		Atomics International	
New York Operations Office		Liquid Metal Engineering Center	
376 Hudson Street		P.O. Box 309	
New York, New York 10014		Canoga Park, California 91305	
Director	2	Division Leader, Inorganic Materials	1
LMFBR Program Office		Chemistry Department	
Argonne National Laboratory		Lawrence Radiation Laboratory	
9700 South Cass Avenue		P.O. Box 808	
Argonne, Illinois 60439		Livermore, California 94551	
Director, Metallurgy Division	2	Manager—Advanced Development Activity	1
Argonne National Laboratory		General Electric Company	
9700 South Cass Avenue		Knolls Atomic Power Laboratory	
Argonne, Illinois 60439		P.O. Box 1072	
		Schenectady, New York 12301	
Manager, FFTF Project	2	General Manager	1
Pacific Northwest Laboratory		Westinghouse Electric Corporation	
P.O. Box 999		Bettis Atomic Power Laboratory	
Richland, Washington 99352		P.O. Box 79	
		West Mifflin, Pennsylvania 15122	
FTTF Fuels Department	2	Director, LMFBR Technology Program	1
Pacific Northwest Laboratory		Atomics International	
P.O. Box 999		P.O. Box 309	
Richland, Washington 99352		Canoga Park, California 91304	
Manager, Chemistry and Metallurgy Div.	1	Associate Manager, Materials Engineering Dept.	1
Pacific Northwest Laboratory		Battelle Memorial Institute	
P.O. Box 999		Columbus Laboratories	
Richland, Washington 99352		505 King Avenue	
		Columbus, Ohio 43201	
Division Leader, Chemistry and	1	Director, Nuclear Development Center	1
Metallurgy Division (CMB)		The Babcock and Wilcox Company	
Los Alamos Scientific Laboratory		Atomic Energy Division	
P.O. Box 1663		Lynchburg, Virginia 24501	
Los Alamos, New Mexico 87544			

*Submitted with transmittal form AEC-426

Manager, Nuclear Laboratories Combustion Engineering Inc. Nuclear Division Prospect Hill Road Windsor, Connecticut 06095	1	Head, Fuels and Materials Atomic Power Development Associates 1911 First Street Detroit, Michigan 48226
Laboratory Assistant Director Gulf General Atomic P.O. Box 608 San Diego, California 92112	1	K-2 Group Leader Reactor Division Los Alamos Scientific Laboratory P.O. Box 1663 Los Alamos, New Mexico 87544
Manager, Plutonium Chemistry and Ceramics Fuel Development Nuclear Materials and Equipment Corp. Plutonium Laboratory Leechburg, Pennsylvania 15656	1	Irradiations Manager EBR-II Project Argonne National Laboratory P.O. Box 1096 Idaho Falls, Idaho 83401
Manager, Sodium Reactor Technology General Electric Company Breeder Reactor Development Operation 310 DeGuigne Drive Sunnyvale, California 94086	2	Westinghouse Electric Corporation Technical Director Advanced Reactors Division P.O. Box 158 Madison, Pennsylvania 15663
Project Engineer, Demonstration Plant Development General Electric Company Breeder Reactor Development Operation 310 DeGuigne Drive Sunnyvale, California 94086	1