11-20-66

MASTER

NOT APPROVED FOR PUBLIC RELEASE. AVAILABLE
TO THE AEC AND ITS SUCCESSORS ONLY

RELEASED FOR ANNOUNCEMENT
IN NUCLEAR SCIENCE ABSTRACTS

Westinghouse Atomic Power Division

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency Thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

DISCLAIMER

Portions of this document may be illegible in electronic image products. Images are produced from the best available original document.

EURAC-1721
WCAP-3680-1

EURAC-
WCAP-3680-1
CFSTI PRICE

H.C. \$ 3.00; MN .65

CONTROL OF XENON INSTABILITIES

IN LARGE PWR'S

TECHNICAL PROGRESS REPORT

FOR THE PERIOD ENDING

SEPTEMBER 30, 1966

RELEASED FOR ANNOUNCEMENT

IN NUCLEAR SCIENCE ABSTRACTS

THIS REPORT WAS RECEIVED UNDER THE
PROVISIONS OF THE *U.S. Atomic Energy Act*

ARRANGEMENT AND IS SUBJECT TO THE
TERMS THEREOF.

M. J. O'Boyle
Project Engineer

~~NOT APPROVED FOR PUBLIC RELEASE - AVAILABLE
TO THE AEC AND ITS CONTRACTORS ONLY~~

Prepared for the New York Operations Office
U. S. Atomic Energy Commission
Under AEC Contract AT(30-1)-3680

October 1966

WESTINGHOUSE ELECTRIC CORPORATION
Atomic Power Divisions
Box 355
Pittsburgh, Pennsylvania 15230

LEGAL NOTICE

This report was prepared as an account of Government sponsored work. Neither the United States, nor the Commission, nor any person acting on behalf of the Commission:

A. Makes any warranty or representation, expressed or implied, with respect to the accuracy, completeness, or usefulness of the information contained in this report, or that the use of any information, apparatus, method, or process disclosed in this report may not infringe privately owned rights; or

B. Assumes any liabilities with respect to the use of, or for damages resulting from the use of any information, apparatus, method, or process disclosed in this report.

As used in the above, "person acting on behalf of the Commission" includes any employee or contractor of the Commission, or employee of such contractor, to the extent that such employee or contractor of the Commission, or employee of such contractor prepares, disseminates, or provides access to, any information pursuant to his employment or contract with the Commission, or his employment with such contractor.

EXTERNAL DISTRIBUTION

USAEC, Brussels Office, APO 667 New York, New York 09667 Attention: Senior AEC Representative.	21
USAEC, New York Operations Office, 376 Hudson Street, New York, N.Y. 10014 Attention: Leo Graup.	1
USAEC, New York Operations Office, 376 Hudson Street, New York, N.Y. 10014 Attention: Reports Library.	1
USAEC, Brookhaven Area Office, New York Patents Group, Upton, New York 11973 Attention: Chief, Harmon S. Potter.	1
USAEC, Office of Foreign Activities, GM Washington, D. C. 20545	1
USAEC, Assistant General Counsel for Patents Washington, D. C. 20545 Attention: Dr. William Holton	1
USAEC, Division of Technical Information Ext. P. O. Box 62 Oak Ridge, Tennessee 37830.	1
USAEC, Division of Reactor Development and Technology, Washington, D. C. 20545	2
<hr/>	
TOTAL	29

PRELIMINARY REPORT - U. S. EURATOM EXCHANGE

To expedite dissemination of technical information to those persons requiring it, this report has been issued without the administrative review necessary to protect the interests of the U. S. Government, the European Atomic Energy Community (Euratom) and Westinghouse Electric Corporation. The recipient of this report agrees that it is passed on to him in confidence, that he will maintain that confidence and make no disclosures or publication of the contents, that would be detrimental to the interests of the U. S. Government, the European Atomic Energy Community (Euratom) and Westinghouse.

INTERNAL DISTRIBUTION

R. J. Allio	W. Lester
H. C. Amtsberg/G. L. Duke	T. R. Mager
H. N. Andrews	S. M. Marshall (15)
B. Axelson	R. G. McGrath
R. F. Barry	D. L. Miller
S. Bartnoff	G. H. Minton
E. S. Beckjord	T. J. Mitlo
A. A. Bishop	N. R. Nelson
J. O. Cermak	M. J. O'Boyle
L. Chajson	W. L. Orr
C. C. Christensen	E. Paxson
A. Christie	C. G. Poncelet
I. H. Coen	D. J. Povejsil
P. Cohen	V. Rajagopal
R. J. Creagan	J. C. Rengel
W. F. Davis	C. Roderick
P. G. DeHuff	H. L. Russo
W. J. Dollard	D. G. Sammarone
W. F. Eanes	R. E. Schreiber
G. H. Farbman	A. A. Simmons
H. M. Ferrari	D. C. Spencer
W. D. Fletcher	R. W. Steer
R. J. French	T. Stern
J. M. Gallagher	L. E. Strawbridge
N. E. Gordon/D. T. Galm	G. R. Taylor
H. W. Graves	D. Thorn
P. B. Haga	L. S. Tong
W. S. Hazelton	H. J. von Hollen
R. G. Hobson	H. E. Walchli
D. Hunter	R. A. Wiesemann
H. W. Keller	R. L. Witzke
J. C. R. Kelly	P. M. Wood
A. S. Kitzes	J. H. Wright
F. L. Kuno	W. E. Wright
F. L. Langford	J. M. Yadon/D. C. Beatty
W. B. Lee	TIC (3)

Total 92

TABLE OF CONTENTS

	<u>Page No.</u>
LIST OF FIGURES	v
PROGRAM DESCRIPTION	1
PROGRESS SUMMARY.	2
DETAILED PROGRESS REPORTS	3
EUXE-100 PROGRAM MANAGEMENT.	4
EUXE-200 EFFECT OF CORE PARAMETERS ON SPATIAL OSCILLATIONS . . .	5
EUXE-300 REMEDIAL CONTROL PROCEDURES	14
EUXE-400 THREE-DIMENSIONAL ANALYSIS.	15

LIST OF FIGURES

<u>Figure No.</u>	<u>Title</u>	<u>Page No.</u>
200.1	Full Core Calculation Asymmetric Perturbation, 75% Growth per Cycle, No Doppler	8
200.2	No Doppler, Full Core Calculation Asymmetric Perturbation	9
200.3	No Doppler, Diagonal Symmetry Calculation Perturbation on Diagonal Axis, 69% Growth per Cycle	10
200.4	Half Core Calculation Perturbation on y-axis, No Doppler, 51% Growth per Cycle.	11
200.5	Diagonal Symmetry Calculation Perturbation on Diagonal Axis Doppler Included, 24% Growth per Cycle. .	13

PROGRAM DESCRIPTION

This program investigates the characteristics and control of spatial instabilities in large pressurized-water reactors (large PWR's), with particular emphasis on azimuthal xenon instabilities (x-y plane). The program consists of the following technical tasks:

Task EUXE-200 - Effect of Core Parameters on Spatial Oscillations

Analyze the effect of variations in core design and operating parameters on the propensity for spatial oscillations, such as those resulting from xenon redistribution. Parameters to be analyzed include, but are not limited to, core dimensions, power coefficient, moderator coefficient, and power distributions.

Task EUXE-300 - Remedial Control Procedures

Perform two-dimensional analysis of control methods and detector locations which will prevent divergent oscillations. Develop criteria for the application of these remedial measures to large pressurized-water reactors.

Task EUXE-400 - Three-Dimensional Analysis

Perform either direct or synthesized three-dimensional analysis of a large PWR core with conditions conducive to oscillations. If a three-dimensional oscillation develops after perturbations have been introduced, selected remedial methods (as developed under Task EUXE-300) will be applied and evaluated. The unique characteristics of three-dimensional oscillations (if observed) will be identified and the criteria for the application of remedial measures will be developed.

PROGRESS SUMMARY

This is the first technical progress report for the joint US-Euratom program titled "Control of Xenon Instabilities in Large PWR's". Major progress is summarized below for the period ending September 30, 1966:

Studies performed to date have demonstrated that the selected calculational procedures are acceptable for the initial phases of the program.

An x-y calculation without Doppler damping was performed for a large PWR core to establish the characteristics of a free-running, divergent oscillation. This calculation was carried through several cycles of the xenon oscillation so that the rate of divergence could be determined. The x-y case seems to be less stable than expected.

Comparisons of predicted xenon stability in the x-y plane were then made for full-core calculations, full-core calculations with 45° symmetry, and half-core symmetric calculations. From these comparisons it appears possible to perform some of the analyses with symmetric calculations which reduce computer running time. For corrective control action, however, full-core calculations will probably be required.

A calculation that included a pointwise Doppler coefficient was also performed to observe its stabilizing effect. However, this calculation required an excessive amount of computer time, and alternate calculational approaches are being considered.

DETAILED PROGRESS REPORTS

EUXE-100

PROGRAM MANAGEMENT

M. J. O'Boyle, Project Engineer

Development Projects
PWR Plant Division

Program management is not discussed in this technical progress report, since separate reports emphasizing the administrative aspects of the program are published monthly for limited distribution. In future quarterlies, however, this section will list issued technical reports.

EFFECT OF CORE PARAMETERS ON SPATIAL OSCILLATIONS

R. J. French, Manager

Nuclear Engineering
PWR Plant Division

G. H. Minton, Manager

Reactor Physics and
Mathematics Section

J. W. Miller

C. G. Poncelet

A. Summary

Preliminary calculations of azimuthal oscillations (x-y plane) in a large, 11-foot diameter, pressurized-water reactor (PWR) with the diffusion-depletion program TURBO* (pronounced TURBO-star)/1 indicate the following:

1. TURBO* is capable of exhibiting the instability associated with xenon redistribution.
2. With the perturbation located about two-thirds of the way from core-center along a radius, the power density tends to oscillate in space along a diameter; there is no apparent tendency for the power to precess about the center of the core.
3. The stability characteristics of the core are rather insensitive to the azimuthal location of the perturbation. Thus, it appears that parametric studies can be performed with core geometries which exhibit symmetry, with the corresponding reduction in machine time.

1. Hendley, S. M. and R. A. Mangan, "TURBO* - A Two-Dimensional Few-Group Depletion Code for the IBM-7090", WCAP-6059 (1964)

4. The local Doppler effect acts as a stabilizing agent in reducing the amplitude and rate of divergence of the oscillations. However, the effect of the Doppler feedback appears to be much smaller in the x-y plane than in the axial direction.
5. An excessive amount of machine time is required to perform a calculation which includes the Doppler feedback, with the present Doppler treatment in TURBO*.

B. Evaluation of TURBO* for Analyses of Xenon-Induced Oscillations

Several x-y calculations of xenon oscillations in a large pressurized-water reactor were performed with the TURBO* diffusion-depletion computer program. The equivalent core diameter was 11 feet (3.4 m). The core materials (fuel cells, water holes, etc.) were homogenized; however, each fuel assembly was represented explicitly. In the full-core description 1,296 mesh points were used. This corresponds to a mesh width of about 10.8 cm. A tight convergence criterion (0.01) was used to insure the convergence of the computed power distribution. A three-enrichment loading was selected, with an average enrichment of 2.5%. The resulting radial power density is dished toward the center of the core, with a ratio of power density in the central assembly to average power density of 0.77. The ratio of peak assembly power to average power was 1.29. Both the relatively low average enrichment, and the dished power distribution tend to decrease the inherent stability of the core.

The following procedure was used in the calculations. The core was burned for 100 hours to establish equilibrium xenon conditions. A single control rod was inserted for 1 hour and then withdrawn. Following this perturbation, time steps of 4 hours were run to examine stability.

Three x-y calculations were performed which did not include the Doppler feedback. These were a full-core calculation with an asymmetrical perturbation in the peak-power assembly; a full-core calculation using the 45-degree symmetry option with the perturbation on the diagonal axis; and a half-core calculation with the perturbation on the y-axis.

Figures 200.1 and 200.2 show the ratio of assembly average power to core average power at four locations (0° , 90° , 180° , and 270°) in the full-core calculation with an asymmetrical perturbation. In these figures, the assembly where the control rod was inserted is marked by an X, and its angular position is arbitrarily labeled 0 degrees. Figure 200.1 shows that the power continues to rise in the 180° assembly for 9 hours after the perturbation, and then begins a divergent oscillation with a damping factor of 1.75 for the first cycle. The calculated period is approximately 43 hours; however, the calculations tend to overestimate the period because of the finite time-step length used.^{/1} Figure 200.2 indicates that the power density in the 90° and 270° assemblies is in phase, and that the oscillation is about the 90° - 270° diameter. That is, there is no tendency for the peak to precess about the core-center.

Figures 200.3 and 200.4 show the power transients for a calculation using the 45-degree symmetry option, and for a half-core calculation, respectively, with the perturbation on the axis of symmetry. The damping factors (first cycle) are 1.69 and 1.51, respectively. A comparison of Figures 200.3 and 200.4 with Figures 200.1 and 200.2 show that the spatial transients and general stability characteristics are quite similar for the three cases studied. That is, the azimuthal location of the perturbation has negligible effects on the transient response of the core. Since symmetric calculations afford a significant reduction in

¹ L. E. Strawbridge, L. E. C. Allard, and C. P. Bhalla, "Xenon-Induced Core Instabilities", WCAP-3269-48 (1965).

Figure 200.1

Figure 200.2

Figure 200.3

Figure 200.4

machine time (a factor of two when doing half-core versus full-core calculations), this suggests that parametric stability analyses can be performed with half-core symmetry at a saving in cost. However, it should be noted that when remedial control action is studied, the full-core calculations may be required to allow for a rotation of the flux peak resulting from the corrective action.

C. Calculations with the Doppler Feedback

The calculation for the core having diagonal symmetry (Figure 200.3) was repeated with the local Doppler feedback effect taken into account. The results are shown on Figure 200.5 which should be compared with Figure 200.3. The core still exhibits a divergent oscillation, although the damping effect of the Doppler feedback is quite apparent. The damping factor is 1.24 (first cycle), compared to 1.69 in the case with no-Doppler feedback. Note, however, that the stabilizing effect of the Doppler feedback appears to be smaller in the x-y plane than was reported in the axial dimension.^{/1} An interesting aspect of Figure 200.5 is that the power in the 180° assembly did not increase immediately after the perturbation (as it did in the calculation without Doppler feedback). With Doppler feedback, the peak decreased following the perturbation, and the original peak was not exceeded until 16-hours later. This can be quite important from the standpoint of control strategy.

The calculation with the Doppler feedback required an excessive running time; the average time per time step was increased by a factor of 7 when the Doppler feedback was included, against the no-feedback case. This large increase in machine time can be traced to the actual procedure used in TURBO* to include Doppler feedback, and does not reflect an increase in outer iterations.

-
1. Strawbridge, L. E., E. C. Allard, and C. P. Bhalla, "Xenon-Induced Core Instabilities", WCAP-3269-48 (1965).

Figure 200.5

EUXE-300

REMEDIAL CONTROL PROCEDURES

This sub-task was inactive during this report period.

EUXE-400

THREE-DIMENSIONAL ANALYSIS

This sub-task was inactive during this report period.