ORNL
OAK RIDGE NATIONAL LABORATORY
operated by
UNION CARBIDE CORPORATION
for the
U.S. ATOMIC ENERGY COMMISSION

ORNL - TM - 168 *9-4*

COPY NO. - *7/*

DATE - March 8, 1962

SWAPS - AN EXPERIMENTAL PROGRAM FOR NUMERICAL SOLUTION OF THE TRANSPORT
EQUATION WITH ANISOTROPIC SCATTERING IN ONE-DIMENSIONAL SLAB GEOMETRY

Melvin L. Tobias and Tom B. Fowler

ABSTRACT

The program described in this report is part of an attempt to solve the neutron transport equation in as general a manner as present day machine capacity will permit. The simple iterative technique employed is equivalent to the EQUIPOISE method modified by a form of block relaxation. The block relaxation method is extremely simple and should be generally applicable not only to transport equation programs but also to heat conduction problems and neutron diffusion programs in more than one dimension. In terms of mesh sweeps, the procedure is extremely rapid by comparison with a similar program. Two energy groups, 16 angular directions, and 400 mesh points, are provided. Anisotropic scattering is permitted, and an arbitrary one-dimensional distribution of material properties can be used. Checks of the results of the program against published analytical results for both isotropic and anisotropic scattering have been in excellent agreement.

NOTICE

This document contains information of a preliminary nature and was prepared primarily for internal use at the Oak Ridge National Laboratory. It is subject to revision or correction and therefore does not represent a final report. The information is not to be abstracted, reprinted or otherwise given public dissemination without the approval of the ORNL patent branch, Legal and Information Control Department.

LEGAL NOTICE

This report was prepared as an account of Government sponsored work. Neither the United States, nor the Commission, nor any person acting on behalf of the Commission:

- A. Makes any warranty or representation, expressed or implied, with respect to the accuracy, completeness, or usefulness of the information contained in this report, or that the use of any information, apparatus, method, or process disclosed in this report may not infringe privately owned rights; or
- B. Assumes any liabilities with respect to the use of, or for damages resulting from the use of any information, apparatus, method, or process disclosed in this report.

As used in the above, "person acting on behalf of the Commission" includes any employee or contractor of the Commission, or employee of such contractor, to the extent that such employee or contractor of the Commission, or employee of such contractor prepares, disseminates, or provides access to, any information pursuant to his employment or contract with the Commission, or his employment with such contractor.

SWAPS - AN EXPERIMENTAL PROGRAM FOR NUMERICAL SOLUTION OF
THE TRANSPORT EQUATION WITH ANISOTROPIC SCATTERING IN
ONE-DIMENSIONAL SLAB GEOMETRY

I. Introduction

The EQUIPOISE method¹ has been successfully applied to the problem of solving the neutron transport equation in slab geometry including the effects of anisotropic scattering in the laboratory system. The present program permits the use of an arbitrary distribution of 20 materials in up to 100 regions over 400 mesh points. Two energy groups are considered and as many as 16 angular directions may be used. Two types of anisotropic collision are treated, one of which is scattering from group to group (both ways) while the other is scattering within a group. Permitted boundary conditions at either or both faces are zero return current, zero net current, and arbitrary incoming current.

Succeeding sections of this report will describe the equations upon which the program is based, the iterative method (including the new block relaxation technique), a comparison of program results with published analytical results, and instructions for program input.

It must be pointed out that SWAPS is at the present time an experimental code and does not have built into it all the refinements of a finished program. It is nevertheless easy to use and the answers are clearly identified. The program requires between 0.009 and 0.016 sec per point per angular direction per iteration for anisotropic scattering problems and about 0.002 sec per point per angle per iteration for isotropic scattering problems. Instructions for input preparation and a sample problem are given in the Appendix.

II. Difference Equation Form of the Boltzmann
Equation for Slab Geometry

The basic technique used to treat the Boltzmann equation numerically is very similar to the methods used in the SNG and DSN codes of Carlson.² The difference equations will be derived directly rather than by differencing the integro-differential form of the Boltzmann

equation. This procedure is used to make certain that the resulting difference equations are an approximation to the physical process. (All symbols are defined in a table of notation at the end of Sec. VII.)

In one-dimensional slab geometry it is necessary to consider variation of angular flux in only one of the three coordinates and only one angular direction. For, if a slab is infinite and uniform in the y and z coordinates, the angular flux is constant for a given x and in a cone having a given generating angle α with the x axis. (See Fig. 1)

ORNL-LR-Dwg. 67168
Unclassified

Fig. 1. Angular Flux in Slab Geometry

The total of 4π steradians of solid angle in which neutrons can move is divided into n equal parts each of size $2\pi\Delta(\cos\alpha)$, where $-1 \leq \cos\alpha \leq 1$. For the purposes of calculation, the physical picture of neutrons moving in all possible directions is replaced by a model in which the neutrons are permitted to move making one of n possible angles with the x axis. The directions are chosen by taking them at the

midpoints of the cosine increments. For instance, if two directions are used, then neutrons are supposed to travel to the right in Fig. 2 at an angle of 45° with the positive x direction or to the left at an angle of 135° with the positive x direction. If 16 directions are used, one group of neutrons is said to travel with a cosine of $-13/16$, etc.

ORNL-LR-Dwg. 67169
Unclassified

Fig. 2. Volume Element for Neutron Balance

The complete sequence would be $-15/16, -13/16, -11/16, -9/16, -7/16, \dots$ adding increments of $1/8$ until $+15/16$ is reached. An even number of angular increments is used, half on one side of a material interface and half on the other so that possible ambiguities connected with neutrons moving parallel to an interface are avoided. The interval along the x axis is divided into k parts, not necessarily equal. It is assumed that the average angular flux in a particular direction in one of these parts may be estimated by the arithmetic mean of the values for the angular flux at the ends. Alternatively, one may say that the neutrons traveling in a given range of solid angle behave on the average

like that differential fraction of them which have a direction in the center of that range. It is intuitively obvious that the accuracy of the procedure will increase as the number of both angular and space increments used increases.

The iteration equations used in the SWAPS program are based upon neutron balances taken over volume elements which are directed along the n directions and whose length is bounded by the increments along the x axis. Two energy groups are used in the present program but extension to larger number of groups is easy (in principle). Consider a neutron balance taken over the volume element shown in Fig. 2. The number of neutrons entering at M and traveling in direction μ_j is

$$N_g(x_1, \mu_j) dA \quad (\mu_j = \cos^{-1}\alpha). \quad (a)$$

The number leaving at $x + \Delta x$ is

$$N_g(x_{1+1}, \mu_j) dA. \quad (b)$$

The number of neutrons removed from direction μ_j is taken as

$$\frac{[N_g(x_1, \mu_j) + N_g(x_{1+1}, \mu_j)]}{2} \Sigma_{Tg}(\Delta x/\mu_j) dA. \quad (c)$$

The number of neutrons scattered into direction μ_j in the volume element which were moving in other directions is

$$\sum_{p=1}^n \frac{[N_g(x_1, \mu_p) + N_g(x_{1+1}, \mu_p)]}{2} \Sigma_s(\mu_p \rightarrow \mu_j) \frac{\Delta x}{\mu_j} dA. \quad (d)$$

The number of neutrons born from fission in the volume element which take direction μ_j is

$$\lambda \chi_g \sum_{g=1}^2 \sum_{p=1}^n \frac{[N_g(x_1, \mu_p) + N_g(x_{1+1}, \mu_p)]}{2n} \nu \Sigma_{fg} \frac{\Delta x}{\mu_j} dA. \quad (e)$$

Isotropic generation of fission neutrons is assumed. (In the present program $\chi_1 = 1.0$ and $\chi_2 = 0.0$.)

The number of neutrons scattered from the other groups into group g is

$$\sum_{p=1}^n \frac{N_{g'}(x_i, \mu_p) + N_{g'}(x_{i+1}, \mu_p)}{2} \Sigma_R(g' \rightarrow g, \mu_p \rightarrow \mu_j) \frac{\Delta x}{\mu_j} dA. \quad (f)$$

The balance equation for a given group, direction, and space interval, $(g, \mu_j, \text{ and } x_i \text{ to } x_{i+1})$ is then, canceling the factor dA ,

$$\begin{aligned} N_g(x_{i+1}, \mu_j) &= N_g(x_i, \mu_j) - \frac{N_g(x_i, \mu_j) + N_g(x_{i+1}, \mu_j)}{2} \Sigma_{Tg} \frac{\Delta x}{\mu_j} \\ &+ \sum_{p=1}^n \frac{N_g(x_i, \mu_p) + N_g(x_{i+1}, \mu_p)}{2} \Sigma_s(\mu_p \rightarrow \mu_j) \frac{\Delta x}{\mu_j} \\ &+ \lambda \chi_g \sum_{g'=1}^2 \sum_{p=1}^n \frac{N_{g'}(x_i, \mu_p) + N_{g'}(x_{i+1}, \mu_p)}{2n} \nu \Sigma_{fg} \frac{\Delta x}{\mu_j} \\ &+ \sum_{p=1}^n \frac{N_{g'}(x_i, \mu_p) + N_{g'}(x_{i+1}, \mu_p)}{2} \Sigma_R(g' \rightarrow g, \mu_p \rightarrow \mu_j) \frac{\Delta x}{\mu_j}. \quad (1) \end{aligned}$$

If there are two energy groups, n angular increments, and k space intervals, there are a total of $2nk$ balance equations like (1).

III. The Iterative Procedure

The iterative procedure used to find the angular flux distribution is basically the same as that used in EQUIPOISE.¹ An important modification has been made by the introduction of a form of block relaxation. The procedure consists of rewriting Eq. (1) in the form:

$$N_g^{t+1}(x_{i+1}, \mu_j) = \left(1 + \frac{\Sigma_T \Delta x}{2\mu_j}\right)^{-1} \left[N_g^{t+1}(x_i, \mu_j) \left(1 - \frac{\Sigma_T \Delta x}{2\mu_j}\right) + (d) + (e) + (f) \right], \quad (2)$$

where the superscript t refers to the iteration number. The program is written so that the most recently computed values of fluxes are always used. Equation (2) is used for the values of $\mu_j > 0$. For values of $\mu_j < 0$ the equation used is:

$$N_g^{t+1}(x_i, \mu_j) = \left(1 - \frac{\Sigma_T \Delta x}{2\mu_j}\right)^{-1} \left[N_g^{t+1}(x_{i+1}, \mu_j) \left(1 + \frac{\Sigma_T \Delta x}{2\mu_j}\right) + (d) + (e) + (f) \right] \quad (3)$$

The restriction is made that

$$\Delta x < \frac{2}{n\Sigma_T}. \quad (4)$$

The program assumes a uniform angular flux distribution initially. In eigenvalue problems, a value of λ is then estimated by adding up all the equations and solving for λ , which is equivalent to writing

$$\lambda = \frac{\text{Absorptions} + \text{Leakage}}{\text{Productions}}. \quad (5)$$

This value of λ is then used wherever applicable in the equations for one "mesh sweep". The sweep is conducted by proceeding from one side of the slab to the other and returning. The angular fluxes in all positive μ directions at point 2 are computed from those at point 1, those at 3 from those at 2, etc. On reaching the other side of the slab (point $k + 1$), the angular fluxes in all negative μ directions are computed at point k from those of $k + 1$, those at $k - 1$ from those at k , etc., until point 1 is reached again. When these computations have been completed for both groups, the new set of angular fluxes is used

to obtain a new estimate of λ . The process is repeated until the values of the angular flux cease to change within some preset convergence criterion.

Subject to the restriction of inequality (4), it is seen that a set of positive fluxes inserted in the right-hand side of the iteration Eqs. (2) and (3) will always produce a new set of positive fluxes. Further, use of a set of positive fluxes in (5) will always produce a positive eigenvalue estimate. The iterative procedure represented by Eqs. (2), (3), and (5), which is called here the EQUIPOISE method, is believed to be stable and always convergent because of these two facts. While no proof presently exists for this conjecture, an impressive mass of empirical evidence exists to support it.

Unlike the diffusion codes, no over-relaxation is used. It was found empirically that suitable over-relaxation coefficients were close to one and difficult to estimate accurately. (The work of Hageman³ in this connection is of special interest.) Further, the speed of the program was sufficiently great in eigenvalue problems that there appeared to be little need to accelerate convergence. Non-eigenvalue problems, such as Milne's problem, proved to be quite another matter. The same procedure that produced convergence in 10 iterations in an eigenvalue problem appeared to converge with extreme slowness for fixed incoming current problems. This same difficulty appears in heat conduction problems as well as neutron diffusion problems. The remedy employed in SWAPS is an extremely simple but highly effective form of block relaxation. The technique consists of finding a number by which all the neutron fluxes in a given region and group* must be multiplied to provide a neutron balance. As the problem converges, this number becomes 1. The number is found as follows. Let $\Phi(\text{IN})$ denote fluxes inside a region in a given group and $\Phi(\text{OUT})$ denote fluxes in other adjacent regions or in the same region but other groups. The "driving factor" DF is found by obtaining the ratio

* In the SWAPS program, both groups were lumped together for the block relaxation procedure for simplicity.

$$DF = \frac{DF \left\{ \Phi(OUT) \right\} + SD \left\{ \Phi(OG) \right\}}{R \left\{ \Phi(IN) \right\} + LO \left\{ \Phi(IN) \right\}}, \quad (6)$$

where

$LI \left\{ \Phi(OUT) \right\}$ = the formula for calculating the current of neutrons into the region. It is a function of fluxes outside the region, $\Phi(OUT)$.

$SD \left\{ \Phi(OG) \right\}$ = the formula for calculating slowing down into the group inside the region. It is a function only of fluxes in other groups, $\Phi(OG)$.

$R \left\{ \Phi(IN) \right\}$ = the formula for calculating removals by absorption and slowing down inside the region. It depends only on fluxes in the group or region under consideration, $\Phi(IN)$.

$LO \left\{ \Phi(IN) \right\}$ = the formula for calculating the flow of neutrons out of the region. It depends only on the fluxes inside the region.

The driving factors are used to multiply all the fluxes in a given region. It is used only for regions in which there is no fissionable material. (Fissionable regions are omitted because the driving factor could conceivably become negative in such regions.) In SWAPS, "driving" is done region by region in the following fashion. Suppose a 50-point reactor is composed of two materials, one of which covers points 1-17 and the other from 17-50. Region 1-17 could be divided up into two regions, 8-17 and 1-17, while the other region might be divided 38-50, 21-50, 17-50. A factor is found for points 8-17 and all fluxes in this range are multiplied by it; another factor is found for points 1-17 and all fluxes from 1 to 17 are multiplied by it. Similarly, factors are found for 38-50, 21-50, and 17-50 and superimposed on one another in the same way. Disposition and the frequency of use of the driving

regions is at the discretion of the user of the program. The authors' practice has been to use regions about 10 mean free paths thick and about every 10 iterations. There is no theoretical reason why the "driving" regions should coincide with material regions; they happen to do so in this program as a matter of convenience only. It is worth noting that in certain simple problems, the "driving" procedure, sufficiently elaborated, could lead to an exact solution to the finite difference equations in a finite number of steps. An exact solution is not obtainable, however, in more than one dimension by this means.

While the distribution of the driving function regions has been left to the user, there is nothing of a crucially optimal nature in laying out these areas. The effect of their use is to affect parts of the reactor distant from the boundaries as quickly as possible and to force a condition that must be true at convergence. This condition is that any subregion of the reactor must satisfy a neutron balance. The suggested procedure is generally applicable and should prove useful in more than one dimension, to heat conduction problems as well as to neutron diffusion problems. Problems such as Milne's problem, previously quite intractable, are now solvable in a reasonable amount of machine time.

IV. Program Speed

At the present time the program takes 0.001875 sec per point per angular increment per iteration for isotropic problems. For an anisotropic scattering problem the computing rate is 0.009 to 0.016 sec per point per iteration. These computing rates could doubtless be improved, but the present program is only a prototype and does not warrant refinements. Some statistics concerning mesh sweeps required for convergence are of interest and may be found in Table 1. Comparison with one version of DSN is also given. Cases 3 and 4 are Milne's problem cases, where it is desired to find the angular flux distribution in a very thick slab having an isotropic source on one face. The effect of using driving regions is evident.

Table 1. Convergence Rates in SWAPS and Comparison with Other Programs

Problem	Number of Mesh Points	Number of Angles	Number of "Driving Regions"	Anisotropic Scattering	Eigenvalue Problem	Convergence Level	Number of Iterations
1	100	16	5	No	Yes	6×10^{-7}	12
2	400	16	0	No	Yes	8×10^{-4}	15
3	400	4	0	No	No	2×10^{-2}	200
4	400	4	8	No	No	8×10^{-4}	90
5	300	16	0	No	Yes	$1 \times 10^{-4}{}^a$	8
6	Same as 5 but on DSN program					$2 \times 10^{-3}{}^a$	56
7	101	16	1	No	No	$5 \times 10^{-7}{}^b$	160
8	Same as 7 but on DSN program					$10^{-5}{}^b$	435
9	51	16	0	Yes	Yes	2×10^{-4}	7
10	51	16	0	Yes	Yes	3×10^{-5}	7
11	51	16	0	Yes	Yes	4×10^{-5}	11
12	101	16	0	Yes	Yes	2×10^{-4}	60

^aThe type of convergence level cited is not exactly the same in SWAPS and DSN but is sufficiently close to be comparable. The number of iterations cited for DSN are inner iterations.

^bThe convergence level cited for SWAPS refers to convergence of the individual angular fluxes. The program had apparently reached the limit of machine numerical significance at this convergence level. The DSN convergence is convergence on the integral of the flux.

V. The Treatment of Anisotropic Scattering and of Anisotropy
in the Cross Sections for Group-to-Group Removal

Anisotropy is accounted for by assuming that the cross section for transfer from one direction to another is a cubic polynomial in the cosine of the angle between the entering and leaving direction of the colliding neutron. It follows that if $N(x, \mu_i)$ neutrons per cm^2 per second are traveling in a cone having direction μ_i in the range $\mu_i - \Delta\mu_i/2$ to $\mu_i + \Delta\mu_i/2$, the number of such neutrons having an angle ϕ_i (see Fig. 1) which will be scattered into direction ϕ_j and μ_j per unit path length is expressed by the formula

$$\frac{N(x, \mu_i)}{2\pi \Delta\mu_i} [a_0 + a_1\mu' + a_2\mu'^2 + a_3\mu'^3] \frac{d\phi_i d\phi_j d\mu_i d\mu_j}{4\pi}, \quad (7)$$

where $\mu' = \mu_i\mu_j + \sqrt{1 - \mu_i^2} \sqrt{1 - \mu_j^2} \cos(\phi_i - \phi_j)$ is the cosine of the angle between the initial and final directions. If (7) is integrated over μ_i from $\mu_i - \Delta\mu_i/2$ to $\mu_i + \Delta\mu_i/2$, over μ_j from $\mu_j - \Delta\mu_j/2$ to $\mu_j + \Delta\mu_j/2$, and ϕ_i and ϕ_j from 0 to 2π , assuming $N(x, \mu_i)$ is constant over the interval of integration, there results the formula

$$\begin{aligned} N(x, \mu_i) \sum(\mu_i \rightarrow \mu_j) &= N(x, \mu_i) \frac{\Delta\mu_j}{2} \left\{ a_0 + a_1 \mu_i \mu_j \right. \\ &+ a_2 \left[\left(\mu_i^2 + \frac{\Delta\mu_i^2}{12} \right) \left(\mu_j^2 + \frac{\Delta\mu_j^2}{12} \right) + \frac{1}{2} \left(1 - \mu_i^2 - \frac{\Delta\mu_i^2}{12} \right) \left(1 - \mu_j^2 - \frac{\Delta\mu_j^2}{12} \right) \right] \\ &\left. + a_3 \mu_i \mu_j \left[\left(\mu_i^2 + \frac{\Delta\mu_i^2}{4} \right) \left(\mu_j^2 + \frac{\Delta\mu_j^2}{4} \right) + \frac{3}{2} \left(1 - \mu_i^2 - \frac{\Delta\mu_i^2}{4} \right) \left(1 - \mu_j^2 - \frac{\Delta\mu_j^2}{4} \right) \right] \right\}, \end{aligned} \quad (8)$$

where $\sum(\mu_i \rightarrow \mu_j)$ is the cross section for scattering from a cone having angle $\cos^{-1}\mu_i$ to a cone having an angle $\cos^{-1}\mu_j$.

The input numbers to the program which are to be employed to characterize the scattering or the removal cross sections are a_0 , a_1 , a_2 , and a_3 . Calculation of anisotropic scattering is carried out in the program according to formula (8). Note that if the scattering or removal is linear, then a_0 is the total cross section for the process.

(If a P_n expansion had been used, this would have been true for any degree of non-linearity.) In SWAPS, $\Delta\mu_i = \Delta\mu_j$ and $2/\Delta\mu_i$ is the number of angular increments used.

VI. Checking the Program for Accuracy Against Known Analytic Solutions

A. Milne's Problem Comparison

The program has been checked against Milne's problem by using the case of a slab about 78 mean free paths thick with no absorption and with an isotropic plane source of neutrons at one face and zero incoming current at the other. Four angular increments were used. The emergent angular flux of the face of zero incoming current and the total flux are compared in Table 2 with results obtained by the Wiener-Hopf method.^{4,5} The agreement is excellent considering that only four angular increments were used.

Table 2. Comparison of Results Obtained for Milne's Problem
Using Four Angular Increments with Theoretical Answer

Distance from Boundary, Mean Free Paths	SWAPS Result	Wiener-Hopf	Percent Error
<u>a. Total Flux</u>			
0	1	1	--
0.2	1.4445	1.4714	-1.8
0.4	1.8491	1.8587	-0.5
0.6	2.2320	2.2271	+0.22
0.8	2.6031	2.5868	+0.63
1.0	2.9680	2.9419	+0.89
2.0	4.7609	4.6902	+1.51
<u>b. Emergent Angular Flux</u>			
$-\mu$			
0.25	0.76422	0.773	-1.1
0.75	1.23578	1.232	+0.306
$-\mu_{avg}$	0.55894	0.5774	-3.2
$-(\mu^2)_{avg}$	0.37144	0.4102	-9.4

B. Isotropic and Linear Anisotropic Scattering Eigenvalue Problems

Carlson² and Dresner⁶ have published results concerning the critical thickness of slabs in which scattering was isotropic or linearly anisotropic. Table 3 compares the results they obtained using variational methods with those obtained using the SWAPS program.

Table 3. Comparison of Variational Estimates of Critical Thickness in Slabs with SWAPS Calculation

Total Slab Thickness, Mean Free Paths	Secondaries per Collision	
	Analytical Methods ²	SWAPS
<u>a. Isotropic Scattering</u>		
5.665	1.02	1.020
0.7366	1.4	1.400
0.3108	2.0	2.003
<u>b. Anisotropic Scattering</u>		
$\bar{\mu} = 0.3$		
where	$\bar{\mu} = \frac{\int_{-1}^1 \mu(\nu\sigma_f + \sigma_s) d\mu}{\int_{-1}^1 (\nu\sigma_f + \sigma_s) d\mu}$	
Total Slab Thickness, Mean Free Paths	Critical Number of Secondaries per Collision	
	Variational Estimate ⁶	SWAPS ^a
0.2	3.931	3.99456
0.4	2.601	2.61314
1.0	1.667	1.67240
2.0	1.312	1.31627
4.0	1.127	1.13077
8.0	1.044	1.04641
20.0	1.009	1.00969

^aA small amount of interpolation was used to place the answers at $\bar{\mu} = 0.3$.

C. Thermal Utilization Problem

An ad hoc version of the SWAPS code was used to solve the problem of thermal utilization in a slab lattice referred to in Table 18.4, p. 642, of Weinberg and Wigner.⁴ Using 400 points and 16 angular increments, a value of 0.8557 was obtained, which is in excellent agreement with the text answer of 0.8560.

VII. Conclusions

A simple and efficient method of computing the flux distribution and critical eigenvalue in slab geometry using a numerical solution of the Boltzmann equation has been devised. The iteration procedures used should be applicable to more elaborate programs involving more energy groups and dimensions.

Table of Notation

x, y, z	Cartesian coordinates.
α	Angle between a line intersecting the x axis and the positive x direction.
Δx	Increment of distance along x axis, cm.
n	Number of intervals into which the range $-1 \leq \cos \alpha \leq 1$ is divided.
k	Number of intervals into which the thickness of the slab reactor along the x axis is divided.
μ_j	$(\cos \alpha)_j$, where the subscript j denotes one of the n angular intervals; $\Delta \mu = 2/n$.
M, P	Points in Fig. 2.
dA	Differential element of area, cm^2 .
x_i	The distance along the x axis from the origin to the ith space interval, cm.
$N_g(x_i, \mu_j)$	Angular neutron flux, neutrons per cm^2 per second moving in direction μ_j at point x_i in neutron velocity group g.
Σ_{Tg}	Total cross section for group g, reciprocal centimeters.
$\Sigma_s(\mu_p \rightarrow \mu_j)$	Cross section for scattering from direction μ_p into direction μ_j .
ν	Number of neutrons produced per fission.
λ	Eigenvalue; the number by which ν must be multiplied to make an assembly critical; the reciprocal of the effective multiplication constant.
χ_g	The fraction of neutrons generated by fission which are born into group g. In the present program $\chi_1 = 1.0$ and $\chi_2 = 0.0$.
Σ_{fg}	Fission cross section for group g, reciprocal centimeters.
$\Sigma_R(g' \rightarrow g, \mu_p \rightarrow \mu_j)$	Removal cross section from group g' to g from direction μ_p into direction μ_j .
μ'	Cosine of the angle between the initial and final directions of a neutron which has undergone a scattering collision.
ϕ	The angle made by the projection of the direction of neutron motion upon the y-z plane with the positive z direction.

APPENDIX

Code Operation

SWAPS was programmed in FORTRAN to be run under control of the IBM-7090 FORTRAN Monitor System. The only tapes used by the program are tape 9 for output and tape 10 for input.

Input

Figure A.2 is a SWAPS input form filled out for the sample problem. In the instructions given below, the number formats are given in FORTRAN nomenclature and are written in parenthesis immediately following the input number symbol.

Card 1 - Title Card

Column 1 - blank.

Columns 2 through 72 - any desired information.

Card 2 - Control Card

Columns 1 through 3 - $ANG(I3) \leq 16$: number of angles for which the fluxes are to be computed.

Columns 4 through 6 - $PTS(I3) \leq 400$: total number of points. The mesh runs from left to right beginning with 1 for the left-most point and ending with PTS.

Columns 7 through 9 - $REG(I3) \leq 100$: the number of regions into which the mesh is divided.

Columns 10 through 12 - $MAT(I3) \leq 20$: the number of different materials that are specified below.

Columns 13 through 15 - $LBI(I3)$: left-hand boundary condition indicator. If LBI is 0 or blank, the left-hand boundary is a zero return current boundary. If LBI is +1, the left-hand boundary is a zero net current boundary. A -1 for LBI specifies an arbitrary incoming current boundary condition which is specified below.

Columns 16 through 18 - $RBI(I3)$: right-hand boundary condition indicator. The right-hand boundary conditions are specified in the

same manner as that given above for the left boundary.

Columns 19 through 21 - FXI(I3): previous flux indicator. If FXI is a 0 or blank, the code supplies an initial flat flux guess. A +1 for FXI indicates that the initial flux guess is taken from the preceding problem. The preceding problem must have the same number of points and angles, and the same boundary conditions as this problem.

Columns 22 through 24 - ITR(I3): the total number of iterations the problem is to be run. If a problem has not converged before ITR is reached, it is terminated automatically and the normal output is written. Most problems converge in fewer than 100 iterations.

Columns 25 through 27 - DRV(I3): the block relaxation iteration cycle. The calculation proceeds normally (point relaxation) for DRV iterations, at which time the block relaxation procedure is applied to all specified (see below) non-source regions. This cycle is repeated until the problem reaches convergence. A value of 10 appears to be reasonable for this number.

Columns 28 through 30 - OUT(I3): output information indicator. Convergence information, the eigenvalue, the total flux at each mesh point, and the neutron balance are always printed out. OUT indicates other output that may be desired. A 0 or blank for this number indicates no additional output. If OUT is +1, the directional fluxes will be included in the output. If OUT is -1, the directional fluxes plus the angular dependent macroscopic removal and scattering cross sections will be printed out.

Columns 31 through 48 - FACTOR(E12.6): normalization factor. For output, the total fluxes are normalized by multiplying each flux value by FACTOR/S, where S is the total source,

$$S = \sum_g \sum_{x_i} \sum_{\mu_j} \nu \Sigma_{fg} [N_g(x_i, \mu_j) + N_g(x_{i+1}, \mu_j)] \frac{\Delta x}{2}.$$

The angular dependent fluxes are not normalized for output.

Columns 49 through 52 - EPI(E10.4): convergence criterion. The calculation stops when both of the following conditions are satisfied.

$$\left| \frac{\lambda^{t-\text{DRV}}}{\lambda^t} - 1.0 \right| < \text{EPI, and}$$

$$\left| \frac{N_g^{t-1}(x_i, \mu_j)}{N_g^t(x_i, \mu_j)} - 1.0 \right|_{\max} < \text{EPI,}$$

where t is the iteration number and DRV is as defined above.

Columns 53 through 62, and 63 through 72 - $\beta_1(\text{E}10.4)$, and $\beta_2(\text{E}10.4)$: extrapolated Liebmann coefficients for groups 1 and 2. If these numbers are 0 or blank, the code uses values of 1.0 for β_1 and β_2 ; otherwise, the input values are used. It is strongly recommended that these numbers be left blank for input.

Cards 3 and 4

These two cards are used to specify values of constant incoming angular fluxes if LBI (Control Card) is -1. If LBI is 0 or +1, omit these cards.

Columns 1 through 9, 10 through 18, etc., supply values of the group 1 angular fluxes (E9.5) for all $\mu_j > 0$ using card 3. Repeat for group 2 using card 4. For a two angle problem, only one number on each card would be written in columns 1 through 9 corresponding to the constant angular flux for μ_2 . For a six angle problem, three numbers corresponding to μ_4 , μ_5 , and μ_6 would be written in columns 1 through 27 for each group.

Cards 5 and 6

These two cards are used only if RBI is -1. In this case the numbers are specified as above and apply to the right boundary. These angular fluxes correspond to all $\mu_j < 0$.

Cards 7+ - Mesh Specification Cards

The regions are specified beginning with region number 1 (the left-most region) and ending with region number REG (the right-most region).

Each card specifies three regions.

Columns 1 through 3 - LPT(I3): left mesh point number of the region.

Columns 4 through 6 - RPT(I3): right mesh point number of the region.

Columns 7 through 9 - SUB(I3): subregions for block relaxation. This number may be ignored for regions which have a value of $\nu\Sigma_f$. For regions which have no fissionable material, a 0 or blank for SUB specifies that this region is not to be "driven". If $SUB > 0$, the region will be divided into SUB subregions and the "driving factors" computed and applied as described earlier. SUB must be less than $RPT - LPT$.

Columns 10 through 12 - MNO(I3): material number of the region. The material constants are specified below and are numbered from 1 to MAT.

Columns 13 through 24 - REG WIDTH(El2.8): the total width of the region. The restriction on this number is

$$\frac{(\text{REG WIDTH})}{(RPT - LPT)} < \frac{2}{\text{ANG}[\Sigma_{T_g}(\text{Reg})]}.$$

Repeat the above specifications using columns 25 through 48 and columns 49 through 72 for the next two regions, and continue with the next card until all regions have been specified.

Cards 8 and 9+ - Material Specification Cards

Two cards are required to specify the constants for each different material and group. For the first card, specify:

Columns 1 through 3 - MAT NO(I3): material number. The materials are numbered beginning with 1 and ending with MAT; however, the pairs of cards specifying each material and group may be in any order in the deck.

Columns 4 through 6 - GRP NO(I3): the group number.

Columns 8 through 16 - $\Sigma_a(\text{El0.6})$: the macroscopic absorption cross section for this material and group.

Columns 17 through 26 - $\nu\Sigma_f(\text{El0.6})$: ν times the macroscopic fission cross sections for this material group.

For the second card of the pair specify:

Columns 1-9, 10-18, 19-27, 28-36 - R_0, R_1, R_2, R_3 (E9.5): the constants used in Eq. (8) to compute the angular dependent removal cross section ($\Sigma_R(g' \rightarrow g, \mu_p \rightarrow \mu_j)$) for this material and group.

Columns 37-45, 46-54, 55-63, 64-72 - S_0, S_1, S_2, S_3 (E9.5): the constants used in Eq. (8) to compute the angular dependent scattering cross section ($\Sigma_S(\mu_p \rightarrow \mu_j)$) for this material and group. If $R_1 = R_2 = R_3 = S_1 = S_2 = S_3 = 0$, then the problem is assumed to be isotropic and the angular independent removal and scattering cross section are computed by:

$$\Sigma_R(g', \mu_1 \rightarrow g, \mu_j) = R_0 / \text{ANG},$$

$$\Sigma_S(\mu_1 \rightarrow \mu_j) = S_0 / \text{ANG}.$$

Successive Cases

Successive cases may be run simply by stacking the case data decks. To end the calculation, follow the data deck with two blank cards.

Sample Problem

The diagram of the sample is shown in Fig. A.1. The sample problem input is shown in Fig. A.2, and the output is shown in Fig. A.3.

Fig. A.1. Diagram of Sample Problem

Punch only those cards having data in columns 73-80

SWAPS INPUT FORM-1

REQUEST No.

[illegible]

Fig. A.2. Input for Sample Problem

Punch only those cards having data in columns 73-80

REQUEST No

2 CARDS PER MATERIAL-Grp	CARD 1	→ MAT.No, GRP.No, Σ_d , $v\Sigma_f$,	→ FORMAT (2I3, 2E10.6)
	CARD 2	→ R_0 , R_1 , R_2 , R_3 , S_0 , S_1 , S_2 , S_3	→ FORMAT (8E9.5)

24

Fig. A.2 (continued)

SWAPS CODE SAMPLE PROBLEM FOR REPORT

REACTOR SPECIFICATIONS

SI (6) CALC 100 MESH PTS 4 REG 3 COMP BND(1, 0) NORM 1.0000E 00 EPI 10.000E-06 BETAI 1.000 BETA2 1.00
 LENGTH 7.5000E 01

REGION SPECIFICATIONS

JLFT	JRIT	COMP	REG WIDTH	MESH WIDTH
1	50	1	2.500E 01	5.102E-01
50	60	2	1.000E 01	1.000E 00
60	70	3	1.000E 01	1.000E 00
70	100	2	3.000E 01	1.000E 00

COMPOSITION SPECIFICATIONS

COMP	GRP	SIGA	NUXSIGF	A0(SIGR)	A1(SIGR)	A2(SIGR)	A3(SIGR)	A0(SIGS)	A1(SIGS)	A2(SIGS)	A3(SIGS)
1	1	1.100E-04	2.100E-04	1.833E-05	3.500E-06	5.167E-07	6.833E-08	1.833E-05	2.000E-06	2.167E-07	2.33E-08
	2	2.200E-04	4.200E-03	2.000E-05	3.667E-06	5.333E-07	7.000E-08	2.000E-05	2.333E-06	2.667E-07	3.00E-08
2	1	2.100E-03	0.	5.167E-04	0.	0.	0.	5.333E-04	0.	0.	0.
	2	3.200E-03	0.	5.333E-04	0.	0.	0.	5.500E-04	0.	0.	0.
3	1	3.100E-05	0.	7.333E-05	9.000E-06	0.	0.	9.000E-05	1.067E-05	0.	0.
	2	6.200E-05	0.	1.067E-04	1.233E-05	0.	0.	1.400E-03	0.	0.	0.

Fig. A.3. Output for Sample Problem

SWAPS CODE SAMPLE PROBLEM FOR REPORT

CONVERGENCE LEVELS EVERY 2 ITERATION

ITER	FLUX CCNVR	LAMBDA CCNVR	LAMBDA	DRIVE REG	SUB REG	SUBREG BNDS	DRIVE FACTOR
2	1.1600E 00	9.0076E-01	1.0076E C1	4	1	(90, 100)	9.82945E-01
				4	2	(80, 100)	9.79149E-01
				4	3	(70, 100)	9.77569E-01
				3	1	(65, 70)	9.86964E-01
				3	2	(60, 70)	9.86815E-01
				2	1	(55, 60)	9.87801E-01
				2	2	(50, 60)	9.88382E-01
4	1.3931E-01	1.4655E-01	1.1807E C1	4	1	(90, 100)	9.96857E-01
				4	2	(80, 100)	9.98482E-01
				4	3	(70, 100)	9.98173E-01
				3	1	(65, 70)	9.99132E-01
				3	2	(60, 70)	9.99211E-01
				2	1	(55, 60)	9.99083E-01
				2	2	(50, 60)	9.98969E-01
6	1.4026E-02	1.6859E-02	1.2009E C1	4	1	(90, 100)	9.99877E-01
				4	2	(80, 100)	9.99895E-01
				4	3	(70, 100)	9.99800E-01
				3	1	(65, 70)	9.99910E-01
				3	2	(60, 70)	9.99921E-01
				2	1	(55, 60)	9.99895E-01
				2	2	(50, 60)	9.99887E-01
8	1.4039E-03	1.8787E-03	1.2032E C1	4	1	(90, 100)	9.99986E-01
				4	2	(80, 100)	9.99981E-01
				4	3	(70, 100)	9.99977E-01
				3	1	(65, 70)	9.99990E-01
				3	2	(60, 70)	9.99992E-01
				2	1	(55, 60)	9.99988E-01
				2	2	(50, 60)	9.99987E-01
10	2.0367E-04	2.1282E-04	1.2034E C1	4	1	(90, 100)	9.99998E-01
				4	2	(80, 100)	9.99998E-01
				4	3	(70, 100)	9.99997E-01
				3	1	(65, 70)	9.99999E-01
				3	2	(60, 70)	9.99999E-01
				2	1	(55, 60)	9.99999E-01
				2	2	(50, 60)	9.99999E-01
12	3.0912E-05	2.4877E-05	1.2035E C1	4	1	(90, 100)	10.00000E-01
				4	2	(80, 100)	10.00000E-01
				4	3	(70, 100)	10.00000E-01
				3	1	(65, 70)	10.00000E-01
				3	2	(60, 70)	10.00000E-01
				2	1	(55, 60)	10.00000E-01
				2	2	(50, 60)	10.00000E-01
14	5.5209E-06	2.9355E-06	1.2035E C1				

Fig. A.3 (continued)

APS CODE SAMPLE PROBLEM FOR REPORT

AST FLUX(J),J#1,100

NORMALIZATION FACTOR 7.09307E-02

4.4186E 01	4.4186E 01	4.4185E 01	4.4184E 01	4.4182E 01	4.4179E 01	4.4176E 01	4.4173E 01	4.4168E 01
4.4164E 01	4.4159E 01	4.4153E 01	4.4146E 01	4.4140E 01	4.4132E 01	4.4124E 01	4.4116E 01	4.4107E 01
4.4097E 01	4.4087E 01	4.4076E 01	4.4065E 01	4.4053E 01	4.4041E 01	4.4028E 01	4.4014E 01	4.4000E 01
4.3986E 01	4.3971E 01	4.3955E 01	4.3939E 01	4.3922E 01	4.3905E 01	4.3887E 01	4.3868E 01	4.3849E 01
4.3830E 01	4.3810E 01	4.3789E 01	4.3768E 01	4.3746E 01	4.3724E 01	4.3701E 01	4.3678E 01	4.3654E 01
4.3630E 01	4.3605E 01	4.3579E 01	4.3553E 01	4.3526E 01	4.2212E 01	4.0949E 01	3.9735E 01	3.8567E 01
3.7444E 01	3.6364E 01	3.5324E 01	3.4323E 01	3.3359E 01	3.2430E 01	3.2322E 01	3.2213E 01	3.2105E 01
3.1998E 01	3.1890E 01	3.1783E 01	3.1677E 01	3.1571E 01	3.1465E 01	3.1360E 01	3.0496E 01	2.9663E 01
2.8859E 01	2.8083E 01	2.7334E 01	2.6610E 01	2.5911E 01	2.5234E 01	2.4580E 01	2.3946E 01	2.3333E 01
2.2739E 01	2.2163E 01	2.1604E 01	2.1062E 01	2.0535E 01	2.0024E 01	1.9527E 01	1.9043E 01	1.8673E 01
1.8114E 01	1.7668E 01	1.7232E 01	1.6807E 01	1.6392E 01	1.5986E 01	1.5589E 01	1.5200E 01	1.4819E 01
1.4446E 01								

Fig. A.3 (continued)

SWAPS CODE SAMPLE PROBLEM FOR REPORT

SLOW FLUX(J),J#1,100			NORMALIZATION FACTOR 7.09307E-02						
7.3251E 00	7.3251E 00	7.3251E 00	7.3252E 00	7.3252E 00	7.3252E 00	7.3252E 00	7.3252E 00	7.3252E 00	7.3252E 00
7.3252E 00	7.3252E 00	7.3252E 00	7.3252E 00	7.3252E 00	7.3252E 00	7.3252E 00	7.3252E 00	7.3253E 00	7.3253E 00
7.3253E 00	7.3253E 00	7.3253E 00	7.3253E 00	7.3253E 00	7.3254E 00	7.3254E 00	7.3254E 00	7.3254E 00	7.3255E 00
7.3255E 00	7.3255E 00	7.3255E 00	7.3256E 00	7.3256E 00	7.3256E 00	7.3256E 00	7.3256E 00	7.3257E 00	7.3257E 00
7.3257E 00	7.3258E 00	7.3258E 00	7.3258E 00	7.3258E 00	7.3259E 00	7.3259E 00	7.3260E 00	7.3260E 00	7.3260E 00
7.3261E 00	7.3261E 00	7.3262E 00	7.3262E 00	7.3263E 00	7.3190E 00	7.3044E 00	7.2829E 00	7.2549E 00	
7.2209E 00	7.1813E 00	7.1365E 00	7.0867E 00	7.0322E 00	6.9735E 00	6.9178E 00	6.8640E 00	6.8118E 00	
6.7613E 00	6.7124E 00	6.6651E 00	6.6193E 00	6.5751E 00	6.5322E 00	6.4908E 00	6.4447E 00	6.3943E 00	
6.3399E 00	6.2817E 00	6.2200E 00	6.1550E 00	6.0868E 00	6.0156E 00	5.9416E 00	5.8649E 00	5.7856E 00	
5.7039E 00	5.6198E 00	5.5335E 00	5.4450E 00	5.3543E 00	5.2616E 00	5.1668E 00	5.0701E 00	4.9713E 00	
4.8706E 00	4.7679E 00	4.6632E 00	4.5566E 00	4.4479E 00	4.3372E 00	4.2244E 00	4.1095E 00	3.9924E 00	
3.8730E 00									

Fig. A.3. (continued)

SWAPS CODE SAMPLE PROBLEM FOR REPORT

NEUTRON BALANCE

REGION ABSORPTIONS AND PRODUCTIONS

REG	FAST ABSORP	SLOW ABSORP	FAST PROD	SLOW PROD	TOTAL
1	1.20907E-01	4.02903E-02	2.30822E-01	7.69178E-01	1.16120E 00
2	7.90132E-01	2.30300E-01	0.	0.	1.02043E 00
3	9.88650E-03	4.16586E-03	0.	0.	1.40524E-02
4	1.36506E 00	5.14586E-01	0.	0.	1.87965E 00
TOTALS	2.28598E 00	7.89342E-01	2.30822E-01	7.69178E-01	4.07533E 00

BOUNDARY LEAKAGES

	FAST LEAK	SLOW LEAK	TOTAL
LFT	0.	0.	0.
RIT	7.11485E 00	1.84444E 00	8.95929E 00
TOTALS	7.11485E 00	1.84444E 00	8.95929E 00

62

Fig. A.3 (continued)

SWAPS CODE SAMPLE PROBLEM FOR REPORT

DIRECTIONAL FAST FLUX(MU,J),J#1,100

MU(1)

4.4190E C1	4.3497E 01	4.2804E 01	4.2111E 01	4.1418E 01	4.0725E 01	4.0031E 01	3.9338E 01	3.8644E 01
3.7951E C1	3.7257E 01	3.6563E 01	3.5869E 01	3.5175E 01	3.4480E 01	3.3786E 01	3.3092E 01	3.2397E 01
3.1702E C1	3.1007E 01	3.0313E 01	2.9618E 01	2.8922E 01	2.8227E 01	2.7532E 01	2.6837E 01	2.6141E 01
2.5446E C1	2.4750E 01	2.4054E 01	2.3358E 01	2.2663E 01	2.1967E 01	2.1271E 01	2.0575E 01	1.9878E 01
1.9182E C1	1.8486E 01	1.7790E 01	1.7093E 01	1.6397E 01	1.5700E 01	1.5004E 01	1.4307E 01	1.3610E 01
1.2914E C1	1.2217E 01	1.1520E 01	1.0823E 01	1.0126E 01	9.7736E 00	9.4292E 00	9.0927E 00	8.7639E 00
8.4424E C0	8.1280E 00	7.8203E 00	7.5193E 00	7.2245E 00	6.9359E 00	6.6641E 00	6.4032E 00	6.1511E 00
6.7299E C0	6.6789E 00	6.6281E 00	6.5774E 00	6.5270E 00	6.4767E 00	6.4266E 00	6.3766E 00	6.3266E 00
5.6204E C0	5.3620E 00	5.1083E 00	4.8594E 00	4.6149E 00	4.3749E 00	4.1391E 00	3.9075E 00	3.6799E 00
3.4562E C0	3.2362E 00	3.0200E 00	2.8074E 00	2.5982E 00	2.3925E 00	2.1901E 00	1.9910E 00	1.7951E 00
1.6023E C0	1.4126E 00	1.2259E 00	1.0421E 00	8.6134E-01	6.8343E-01	5.0836E-01	3.3612E-01	1.6667E-01

0.

MU(2)

7.1736E C1	7.0590E 01	6.9445E 01	6.8299E 01	6.7152E 01	6.6006E 01	6.4859E 01	6.3711E 01	6.2563E 01
6.1415E C1	6.0266E 01	5.9118E 01	5.7968E 01	5.6819E 01	5.5669E 01	5.4518E 01	5.3368E 01	5.2217E 01
5.1066E C1	4.9914E 01	4.8762E 01	4.7610E 01	4.6457E 01	4.5304E 01	4.4151E 01	4.2998E 01	4.1844E 01
4.0690E C1	3.9536E 01	3.8381E 01	3.7226E 01	3.6071E 01	3.4915E 01	3.3759E 01	3.2603E 01	3.1447E 01
3.0290E C1	2.9133E 01	2.7976E 01	2.6819E 01	2.5661E 01	2.4503E 01	2.3345E 01	2.2187E 01	2.1028E 01
1.9869E C1	1.8710E 01	1.7550E 01	1.6391E 01	1.5231E 01	1.4072E 01	1.2913E 01	1.1755E 01	1.0596E 01
1.0223E C1	1.0237E 01	1.1928E 01	1.1495E 01	1.1069E 01	1.0652E 01	1.0236E 01	1.0492E 01	1.0413E 01
1.0333E C1	1.0255E 01	1.0176E 01	1.0098E 01	1.0019E 01	9.9416E 00	9.8640E 00	9.7864E 00	9.7088E 00
8.6641E C0	8.3038E 00	7.9294E 00	7.5609E 00	7.1979E 00	6.8403E 00	6.4878E 00	6.1402E 00	5.7974E 00
5.4591E C0	5.1253E 00	4.7957E 00	4.4702E 00	4.1486E 00	3.8308E 00	3.5167E 00	3.2062E 00	2.8992E 00
2.5955E C0	2.2950E 00	1.9978E 00	1.7036E 00	1.4124E 00	1.1242E 00	8.3894E-01	5.5650E-01	2.7686E-01

0.

MU(3)

1.9555E C2	1.9224E 02	1.8892E 02	1.8560E 02	1.8228E 02	1.7896E 02	1.7563E 02	1.7230E 02	1.6896E 02
1.6563E C2	1.6229E 02	1.5894E 02	1.5559E 02	1.5224E 02	1.4889E 02	1.4553E 02	1.4217E 02	1.3881E 02
1.3544E C2	1.3207E 02	1.2870E 02	1.2532E 02	1.2194E 02	1.1855E 02	1.1517E 02	1.1178E 02	1.0839E 02
1.0499E C2	1.0159E 02	9.8188E 01	9.4782E 01	9.1373E 01	8.7962E 01	8.4547E 01	8.1128E 01	7.7707E 01
7.4283E C1	7.0855E 01	6.7425E 01	6.3991E 01	6.0554E 01	5.7114E 01	5.3671E 01	5.0225E 01	4.6776E 01
4.3324E C1	3.9869E 01	3.6411E 01	3.2950E 01	2.9485E 01	2.6027E 01	2.2570E 01	1.9112E 01	1.5654E 01
2.5672E C1	2.4958E 01	2.4258E 01	2.3572E 01	2.2878E 01	2.2235E 01	2.1602E 01	2.1009E 01	2.0416E 01
2.1544E C1	2.1372E 01	2.1200E 01	2.1028E 01	2.0857E 01	2.0685E 01	2.0514E 01	1.9844E 01	1.9181E 01
1.8523E C1	1.7871E 01	1.7224E 01	1.6579E 01	1.5938E 01	1.5298E 01	1.4660E 01	1.4022E 01	1.3383E 01
1.2743E C1	1.2101E 01	1.1456E 01	1.0807E 01	1.0153E 01	9.4937E 00	8.8200E 00	8.1550E 00	7.4739E 00
6.7636E C0	6.0833E 00	5.3720E 00	4.6487E 00	3.9124E 00	3.1622E 00	2.3970E 00	1.6156E 00	8.1698E-01

0.

MU(4)

1.9555E C2	1.9886E 02	2.0216E 02	2.0546E 02	2.0876E 02	2.1205E 02	2.1534E 02	2.1863E 02	2.2192E 02
2.2520E C2	2.2847E 02	2.3175E 02	2.3502E 02	2.3829E 02	2.4155E 02	2.4481E 02	2.4807E 02	2.5132E 02
2.5457E C2	2.5782E 02	2.6106E 02	2.6430E 02	2.6753E 02	2.7077E 02	2.7400E 02	2.7722E 02	2.8044E 02
2.8366E C2	2.8688E 02	2.9009E 02	2.9330E 02	2.9650E 02	2.9970E 02	3.0290E 02	3.0609E 02	3.0928E 02
3.1247E C2	3.1565E 02	3.1883E 02	3.2200E 02	3.2518E 02	3.2834E 02	3.3151E 02	3.3467E 02	3.3783E 02
3.4098E C2	3.4413E 02	3.4728E 02	3.5042E 02	3.5356E 02	3.5670E 02	3.5985E 02	3.6299E 02	3.6613E 02
2.8427E C2	2.7224E 02	2.6075E 02	2.4977E 02	2.3929E 02	2.2928E 02	2.2021E 02	2.1114E 02	2.0207E 02
2.2501E C2	2.2395E 02	2.2290E 02	2.2186E 02	2.2082E 02	2.1978E 02	2.1875E 02	2.1771E 02	2.1668E 02
1.9263E C2	1.8469E 02	1.7711E 02	1.6986E 02	1.6293E 02	1.5631E 02	1.4999E 02	1.4394E 02	1.3816E 02
1.3264E C2	1.2735E 02	1.2230E 02	1.1747E 02	1.1285E 02	1.0843E 02	1.0419E 02	1.0015E 02	9.6272E 01
9.2563E 01	8.9011E 01	8.5611E 01	8.2354E 01	7.9234E 01	7.6244E 01	7.3379E 01	7.0633E 01	6.7999E 01
6.5473E C1								

Fig. A.3 (continued)

MU(5)

7.1736E 01	7.2880E 01	7.4025E 01	7.5169E 01	7.6313E 01	7.7456E 01	7.8599E 01	7.9741E 01	8.0883E 01
8.2025E 01	8.3166E 01	8.4307E 01	8.5448E 01	8.6588E 01	8.7727E 01	8.8866E 01	9.0005E 01	9.1143E 01
9.2281E 01	9.3419E 01	9.4556E 01	9.5692E 01	9.6828E 01	9.7964E 01	9.9099E 01	1.0023E 02	1.0137E 02
1.0250E 02	1.0363E 02	1.0477E 02	1.0590E 02	1.0703E 02	1.0816E 02	1.0929E 02	1.1042E 02	1.1155E 02
1.1268E 02	1.1381E 02	1.1494E 02	1.1607E 02	1.1720E 02	1.1832E 02	1.1945E 02	1.2058E 02	1.2170E 02
1.2283E 02	1.2395E 02	1.2507E 02	1.2620E 02	1.2732E 02	1.2845E 02	1.2958E 02	1.3070E 02	1.3183E 02
1.3295E 02	1.3407E 02	1.3520E 02	1.3632E 02	1.3745E 02	1.3857E 02	1.3970E 02	1.4083E 02	1.4195E 02
1.4308E 02	1.4420E 02	1.4533E 02	1.4645E 02	1.4758E 02	1.4870E 02	1.4983E 02	1.5095E 02	1.5208E 02
1.5320E 02	1.5432E 02	1.5545E 02	1.5657E 02	1.5770E 02	1.5883E 02	1.5995E 02	1.6108E 02	1.6220E 02
1.6333E 02	1.6445E 02	1.6558E 02	1.6670E 02	1.6783E 02	1.6895E 02	1.7008E 02	1.7120E 02	1.7233E 02
1.7345E 02	1.7458E 02	1.7570E 02	1.7683E 02	1.7795E 02	1.7908E 02	1.8020E 02	1.8133E 02	1.8245E 02
1.8358E 02	1.8470E 02	1.8583E 02	1.8695E 02	1.8808E 02	1.8920E 02	1.9033E 02	1.9145E 02	1.9258E 02
1.9370E 02	1.9483E 02	1.9595E 02	1.9708E 02	1.9820E 02	1.9933E 02	2.0045E 02	2.0158E 02	2.0270E 02
2.0383E 02	2.0495E 02	2.0608E 02	2.0720E 02	2.0833E 02	2.0945E 02	2.1058E 02	2.1170E 02	2.1283E 02
2.1395E 02	2.1507E 02	2.1620E 02	2.1732E 02	2.1845E 02	2.1958E 02	2.2070E 02	2.2183E 02	2.2295E 02
2.2407E 02	2.2520E 02	2.2632E 02	2.2745E 02	2.2857E 02	2.2970E 02	2.3083E 02	2.3195E 02	2.3308E 02
2.3420E 02	2.3533E 02	2.3645E 02	2.3758E 02	2.3870E 02	2.3983E 02	2.4095E 02	2.4208E 02	2.4320E 02
2.4433E 02	2.4545E 02	2.4657E 02	2.4770E 02	2.4883E 02	2.4995E 02	2.5108E 02	2.5220E 02	2.5333E 02
2.5445E 02	2.5558E 02	2.5670E 02	2.5783E 02	2.5895E 02	2.6008E 02	2.6120E 02	2.6233E 02	2.6345E 02
2.6458E 02	2.6570E 02	2.6683E 02	2.6795E 02	2.6908E 02	2.7020E 02	2.7133E 02	2.7245E 02	2.7358E 02
2.7470E 02	2.7583E 02	2.7695E 02	2.7808E 02	2.7920E 02	2.8033E 02	2.8145E 02	2.8258E 02	2.8370E 02
2.8483E 02	2.8595E 02	2.8708E 02	2.8820E 02	2.8933E 02	2.9045E 02	2.9158E 02	2.9270E 02	2.9383E 02
2.9495E 02	2.9608E 02	2.9720E 02	2.9833E 02	2.9945E 02	3.0058E 02	3.0170E 02	3.0283E 02	3.0395E 02
3.0507E 02	3.0620E 02	3.0732E 02	3.0845E 02	3.0958E 02	3.1070E 02	3.1183E 02	3.1295E 02	3.1407E 02
3.1520E 02	3.1632E 02	3.1745E 02	3.1857E 02	3.1970E 02	3.2083E 02	3.2195E 02	3.2308E 02	3.2420E 02
3.2533E 02	3.2645E 02	3.2758E 02	3.2870E 02	3.2983E 02	3.3095E 02	3.3208E 02	3.3320E 02	3.3433E 02
3.3545E 02	3.3657E 02	3.3770E 02	3.3883E 02	3.3995E 02	3.4108E 02	3.4220E 02	3.4333E 02	3.4445E 02
3.4558E 02	3.4670E 02	3.4783E 02	3.4895E 02	3.5008E 02	3.5120E 02	3.5233E 02	3.5345E 02	3.5458E 02
3.5570E 02	3.5683E 02	3.5795E 02	3.5908E 02	3.6020E 02	3.6133E 02	3.6245E 02	3.6358E 02	3.6470E 02
3.6583E 02	3.6695E 02	3.6808E 02	3.6920E 02	3.7033E 02	3.7145E 02	3.7258E 02	3.7370E 02	3.7483E 02
3.7595E 02	3.7708E 02	3.7820E 02	3.7933E 02	3.8045E 02	3.8158E 02	3.8270E 02	3.8383E 02	3.8495E 02
3.8608E 02	3.8720E 02	3.8833E 02	3.8945E 02	3.9058E 02	3.9170E 02	3.9283E 02	3.9395E 02	3.9507E 02
3.9620E 02	3.9732E 02	3.9845E 02	3.9958E 02	4.0070E 02	4.0183E 02	4.0295E 02	4.0407E 02	4.0520E 02
4.0632E 02	4.0745E 02	4.0857E 02	4.0970E 02	4.1083E 02	4.1195E 02	4.1308E 02	4.1420E 02	4.1533E 02
4.1645E 02	4.1758E 02	4.1870E 02	4.1983E 02	4.2095E 02	4.2208E 02	4.2320E 02	4.2433E 02	4.2545E 02
4.2658E 02	4.2770E 02	4.2883E 02	4.2995E 02	4.3108E 02	4.3220E 02	4.3333E 02	4.3445E 02	4.3558E 02
4.3670E 02	4.3783E 02	4.3895E 02	4.4008E 02	4.4120E 02	4.4233E 02	4.4345E 02	4.4458E 02	4.4570E 02
4.4683E 02	4.4795E 02	4.4908E 02	4.5020E 02	4.5133E 02	4.5245E 02	4.5358E 02	4.5470E 02	4.5583E 02
4.5695E 02	4.5808E 02	4.5920E 02	4.6033E 02	4.6145E 02	4.6258E 02	4.6370E 02	4.6483E 02	4.6595E 02
4.6708E 02	4.6820E 02	4.6933E 02	4.7045E 02	4.7158E 02	4.7270E 02	4.7383E 02	4.7495E 02	4.7608E 02
4.7720E 02	4.7833E 02	4.7945E 02	4.8058E 02	4.8170E 02	4.8283E 02	4.8395E 02	4.8507E 02	4.8620E 02
4.8732E 02	4.8845E 02	4.8958E 02	4.9070E 02	4.9183E 02	4.9295E 02	4.9407E 02	4.9520E 02	4.9632E 02
4.9745E 02	4.9857E 02	4.9970E 02	5.0083E 02	5.0195E 02	5.0308E 02	5.0420E 02	5.0533E 02	5.0645E 02
5.0758E 02	5.0870E 02	5.0983E 02	5.1095E 02	5.1208E 02	5.1320E 02	5.1433E 02	5.1545E 02	5.1658E 02
5.1770E 02	5.1883E 02	5.1995E 02	5.2108E 02	5.2220E 02	5.2333E 02	5.2445E 02	5.2558E 02	5.2670E 02
5.2783E 02	5.2895E 02	5.3008E 02	5.3120E 02	5.3233E 02	5.3345E 02	5.3458E 02	5.3570E 02	5.3683E 02
5.3795E 02	5.3908E 02	5.4020E 02	5.4133E 02	5.4245E 02	5.4358E 02	5.4470E 02	5.4583E 02	5.4695E 02
5.4808E 02	5.4920E 02	5.5033E 02	5.5145E 02	5.5258E 02	5.5370E 02	5.5483E 02	5.5595E 02	5.5708E 02
5.5820E 02	5.5933E 02	5.6045E 02	5.6158E 02	5.6270E 02	5.6383E 02	5.6495E 02	5.6608E 02	5.6720E 02
5.6833E 02	5.6945E 02	5.7058E 02	5.7170E 02	5.7283E 02	5.7395E 02	5.7507E 02	5.7620E 02	5.7732E 02
5.7845E 02	5.7958E 02	5.8070E 02	5.8183E 02	5.8295E 02	5.8407E 02	5.8520E 02	5.8632E 02	5.8745E 02
5.8857E 02	5.8970E 02	5.9083E 02	5.9195E 02	5.9308E 02	5.9420E 02	5.9533E 02	5.9645E 02	5.9758E 02
5.9870E 02	5.9983E 02	6.0095E 02	6.0208E 02	6.0320E 02	6.0433E 02	6.0545E 02	6.0658E 02	6.0770E 02
6.0883E 02	6.0995E 02	6.1108E 02	6.1220E 02	6.1333E 02	6.1445E 02	6.1558E 02	6.1670E 02	6.1783E 02
6.1895E 02	6.2008E 02	6.2120E 02	6.2233E 02	6.2345E 02	6.2458E 02	6.2570E 02	6.2683E 02	6.2795E 02
6.2908E 02	6.3020E 02	6.3133E 02	6.3245E 02	6.3358E 02	6.3470E 02	6.3583E 02	6.3695E 02	6.3808E 02
6.3920E 02	6.4033E 02	6.4145E 02	6.4258E 02	6.4370E 02	6.4483E 02	6.4595E 02	6.4708E 02	6.4820E 02
6.4933E 02	6.5045E 02	6.5158E 02	6.5270E 02	6.5383E 02	6.5495E 02	6.5608E 02	6.5720E 02	6.5832E 02
6.5945E 02	6.6058E 02	6.6170E 02	6.6283E 02	6.6395E 02	6.6507E 02	6.6620E 02	6.6732E 02	6.6845E 02
6.6958E 02	6.7070E 02	6.7183E 02	6.7295E 02	6.7408E 02	6.7520E 02	6.7633E 02	6.7745E 02	6.7858E 02
6.7970E 02	6.8083E 02	6.8195E 02	6.8308E 02	6.8420E 02	6.8533E 02	6.8645E 02	6.8758E 02	6.8870E 02
6.8983E 02	6.9095E 02	6.9208E 02	6.9320E 02	6.9433E 02	6.9545E 02	6.9658E 02	6.9770E 02	6.9883E 02
6.9995E 02	7.0108E 02	7.0220E 02	7.0333E 02	7.0445E 02	7.0558E 02	7.0670E 02	7.0783E 02	7.0895E 02
7.1008E 02	7.1120E 02	7.1233E 02	7.1345E 02	7.1458E 02	7.1570E 02	7.1683E 02	7.1795E 02	7.1908E 02
7.2020E 02	7.2133E 02	7.2245E 02	7.2358E 02	7.2470E 02	7.2583E 02	7.2695E 02	7.2808E 02	7.2920E 02
7.3033E 02	7.3145E 02	7.3258E 02	7.3370E 02	7.3483E 02	7.3595E 02	7.3708E 02	7.3820E 02	7.3932E 02
7.4045E 02	7.4158E 02	7.4270E 02	7.4383E 02	7.4495E 02	7.4608E 02	7.4720E 02	7.4833E 02	7.4945E 02
7.5058E 02	7.5170E 02	7.5283E 02	7.5395E 02	7.5507E 02	7.5620E 02	7.5732E 02	7.5845E 02	7.5958E 02
7.6070E 02	7.6183E 02	7.6295E 02	7.6408E 02	7.6520E 02	7.6633E 02	7.6745E 02	7.6858E 02	7.6970E 02
7.7083E 02	7.7195E 02	7.7308E 02	7.7420E 02	7.7533E 02	7.7645E 02	7.7758E 02	7.7870E 02	7.7983E 02
7.8095E 02	7.8208E 02	7.8320E 02	7.8433E 02	7.8545E 02	7.8658E 02	7.8770E 02	7.8883E 02	7.8995E 02
7.9108E 02	7.9220E 02	7.9333E 02	7.9445E 02	7.9558E 02	7.9670E 02	7.9783E 02	7.9895E 02	8.0007E 02
8.0120E 02	8.0233E 02	8.0345E 02	8.0458E 02	8.0570E 02	8.0683E 02	8.0795E 02	8.0908E 02	8.1020E 02
8.1133E 02	8.1245E 02	8.1358E 02	8.1470E 02	8.1583E 02	8.1695E 02	8.1808E 02	8.1920E 02	8.2032E 02
8.2145E 02	8.2258E 02	8.2370E 02	8.2483E 02	8.2595E 02	8.2708E 02	8.2820E 02	8.2933E 02	8.3045E 02
8.3158E 02	8.3270E 02	8.3383E 02	8.3495E 02	8.3608E 02	8.3720E 02	8.3833E 02	8.3945E 02	8.4058E 02
8.4170E 02	8.4283E 02	8.4395E 02	8.4507E 02	8.4620E 02	8.4732E 02	8.4845E 02	8.4958E 02	8.5070E 02
8.5183E 02	8.5295E 02	8.5408E 02	8.5520E 02	8.5633E 02	8.5745E 02	8.5858E 02	8.5970E 02	8.6083E 02
8.6195E 02	8.6308E 02	8.6420E 02	8.6533E 02	8.6645E 02	8.6758E 02	8.6870E 02	8.6983E 02	8.7095E 02
8.7208E 02	8.7320E 02	8.7433E 02	8.7545E 02	8.7658E 02	8.7770E 02	8.7883E 02	8.7995E 02	8.8107E 02
8.8220E 02	8.8333E 02	8.8445E 02	8.8558E 02	8.8670E 02	8.8783E 02	8.8895E 02	8.9008E 02	8.9120E 02
8.9233E 02	8.9345E 02	8.9458E 02	8.9570E 02	8.9683E 02	8.9795E 02	8.9908E 02	9.0020E 02	9.0133E 02
9.0245E 02	9.0358E 02	9.0470E 02	9.0583E 02	9.0695E 02	9.0808E 02	9.0920E 02	9.1033E 02	9.1145E 02
9.1258E 02	9.1370E 02	9.1483E 02	9.1595E 02	9.1708E 02	9.1820E 02	9.1933E 02	9.2045E 02	9.2158E 02
9.2270E 02	9.2383E 02	9.2495E 02	9.2608E 02	9.2720E 02	9.2833E 02	9.2945E 02	9.3058E 02	9.3170E 02
9.3283E 02	9.3395E 02	9.3508E 02	9.3620E 02	9.3733E 02	9.3845E 02	9.3958E 02	9.4070E 02	9.4183E 02
9.4295E 02	9.4408E 02	9.4520E 02	9.4633E 02	9.4745E 02	9.4858E 02	9.4970E 02	9.5083E 02	9.5195E 02
9.5308E 02	9.5420E 02	9.5533E 02	9.5645E 02	9.5758E 02	9.5870E 02	9.5983E 02	9.6095E 02	9.6208E 02

SWAPS CODE SAMPLE PROBLEM FOR REPORT

DIRECTIONAL SLOW FLUX(MC,J),J#1,100

MU(1)

1.0600E 01	1.0594E 01	1.0589E 01	1.0584E 01	1.0578E 01	1.0573E 01	1.0568E 01	1.0562E 01	1.0557E 01
1.0552E 01	1.0547E 01	1.0541E 01	1.0536E 01	1.0531E 01	1.0526E 01	1.0520E 01	1.0515E 01	1.0510E 01
1.0505E 01	1.0499E 01	1.0494E 01	1.0489E 01	1.0484E 01	1.0479E 01	1.0474E 01	1.0468E 01	1.0463E 01
1.0458E 01	1.0453E 01	1.0448E 01	1.0443E 01	1.0437E 01	1.0432E 01	1.0427E 01	1.0422E 01	1.0417E 01
1.0412E 01	1.0407E 01	1.0402E 01	1.0397E 01	1.0392E 01	1.0387E 01	1.0382E 01	1.0376E 01	1.0371E 01
1.0366E 01	1.0361E 01	1.0356E 01	1.0351E 01	1.0346E 01	1.0340E 01	9.7055E 00	9.3961E 00	9.0939E 00
8.7985E 00	8.5096E 00	8.2271E 00	7.9507E 00	7.6802E 00	7.4154E 00	7.2923E 00	7.1693E 00	7.0464E 00
6.9234E 00	6.8005E 00	6.6774E 00	6.5543E 00	6.4309E 00	6.3075E 00	6.1837E 00	5.9237E 00	5.6685E 00
5.4180E 00	5.1721E 00	4.9305E 00	4.6932E 00	4.4599E 00	4.2307E 00	4.0053E 00	3.7836E 00	3.5655E 00
3.3510E 00	3.1398E 00	2.9320E 00	2.7274E 00	2.5259E 00	2.3275E 00	2.1321E 00	1.9396E 00	1.7500E 00
1.5631E 00	1.3790E 00	1.1976E 00	1.0188E 00	8.4269E-01	6.6912E-01	4.7808E-01	3.2957E-01	1.6354E-01

0.

MU(2)

1.5270E 01	1.5264E 01	1.5257E 01	1.5250E 01	1.5244E 01	1.5237E 01	1.5230E 01	1.5224E 01	1.5217E 01
1.5210E 01	1.5204E 01	1.5197E 01	1.5190E 01	1.5184E 01	1.5177E 01	1.5170E 01	1.5164E 01	1.5157E 01
1.5150E 01	1.5144E 01	1.5137E 01	1.5131E 01	1.5124E 01	1.5117E 01	1.5111E 01	1.5104E 01	1.5098E 01
1.5091E 01	1.5085E 01	1.5078E 01	1.5072E 01	1.5065E 01	1.5059E 01	1.5052E 01	1.5045E 01	1.5039E 01
1.5032E 01	1.5026E 01	1.5020E 01	1.5013E 01	1.5007E 01	1.5000E 01	1.4994E 01	1.4987E 01	1.4981E 01
1.4974E 01	1.4968E 01	1.4962E 01	1.4955E 01	1.4949E 01	1.4942E 01	1.4935E 01	1.4928E 01	1.4922E 01
1.4915E 01	1.4908E 01	1.4902E 01	1.4895E 01	1.4888E 01	1.4881E 01	1.4874E 01	1.4867E 01	1.4860E 01
1.4853E 01	1.4846E 01	1.4839E 01	1.4832E 01	1.4825E 01	1.4818E 01	1.4811E 01	1.4804E 01	1.4797E 01
1.4790E 01	1.4783E 01	1.4776E 01	1.4769E 01	1.4762E 01	1.4755E 01	1.4748E 01	1.4741E 01	1.4734E 01
1.4727E 01	1.4720E 01	1.4713E 01	1.4706E 01	1.4699E 01	1.4692E 01	1.4685E 01	1.4678E 01	1.4671E 01
1.4664E 01	1.4657E 01	1.4650E 01	1.4643E 01	1.4636E 01	1.4629E 01	1.4622E 01	1.4615E 01	1.4608E 01
1.4601E 01	1.4594E 01	1.4587E 01	1.4580E 01	1.4573E 01	1.4566E 01	1.4559E 01	1.4552E 01	1.4545E 01
1.4538E 01	1.4531E 01	1.4524E 01	1.4517E 01	1.4510E 01	1.4503E 01	1.4496E 01	1.4489E 01	1.4482E 01
1.4475E 01	1.4468E 01	1.4461E 01	1.4454E 01	1.4447E 01	1.4440E 01	1.4433E 01	1.4426E 01	1.4419E 01
1.4412E 01	1.4405E 01	1.4398E 01	1.4391E 01	1.4384E 01	1.4377E 01	1.4370E 01	1.4363E 01	1.4356E 01
1.4349E 01	1.4342E 01	1.4335E 01	1.4328E 01	1.4321E 01	1.4314E 01	1.4307E 01	1.4300E 01	1.4293E 01
1.4286E 01	1.4279E 01	1.4272E 01	1.4265E 01	1.4258E 01	1.4251E 01	1.4244E 01	1.4237E 01	1.4230E 01
1.4223E 01	1.4216E 01	1.4209E 01	1.4202E 01	1.4195E 01	1.4188E 01	1.4181E 01	1.4174E 01	1.4167E 01
1.4160E 01	1.4153E 01	1.4146E 01	1.4139E 01	1.4132E 01	1.4125E 01	1.4118E 01	1.4111E 01	1.4104E 01
1.4097E 01	1.4090E 01	1.4083E 01	1.4076E 01	1.4069E 01	1.4062E 01	1.4055E 01	1.4048E 01	1.4041E 01
1.4034E 01	1.4027E 01	1.4020E 01	1.4013E 01	1.4006E 01	1.4000E 01	1.3993E 01	1.3986E 01	1.3979E 01
1.3972E 01	1.3965E 01	1.3958E 01	1.3951E 01	1.3944E 01	1.3937E 01	1.3930E 01	1.3923E 01	1.3916E 01
1.3909E 01	1.3902E 01	1.3895E 01	1.3888E 01	1.3881E 01	1.3874E 01	1.3867E 01	1.3860E 01	1.3853E 01
1.3846E 01	1.3839E 01	1.3832E 01	1.3825E 01	1.3818E 01	1.3811E 01	1.3804E 01	1.3797E 01	1.3790E 01
1.3783E 01	1.3776E 01	1.3769E 01	1.3762E 01	1.3755E 01	1.3748E 01	1.3741E 01	1.3734E 01	1.3727E 01
1.3720E 01	1.3713E 01	1.3706E 01	1.3699E 01	1.3692E 01	1.3685E 01	1.3678E 01	1.3671E 01	1.3664E 01
1.3657E 01	1.3650E 01	1.3643E 01	1.3636E 01	1.3629E 01	1.3622E 01	1.3615E 01	1.3608E 01	1.3601E 01
1.3594E 01	1.3587E 01	1.3580E 01	1.3573E 01	1.3566E 01	1.3559E 01	1.3552E 01	1.3545E 01	1.3538E 01
1.3531E 01	1.3524E 01	1.3517E 01	1.3510E 01	1.3503E 01	1.3496E 01	1.3489E 01	1.3482E 01	1.3475E 01
1.3468E 01	1.3461E 01	1.3454E 01	1.3447E 01	1.3440E 01	1.3433E 01	1.3426E 01	1.3419E 01	1.3412E 01
1.3405E 01	1.3398E 01	1.3391E 01	1.3384E 01	1.3377E 01	1.3370E 01	1.3363E 01	1.3356E 01	1.3349E 01
1.3342E 01	1.3335E 01	1.3328E 01	1.3321E 01	1.3314E 01	1.3307E 01	1.3300E 01	1.3293E 01	1.3286E 01
1.3279E 01	1.3272E 01	1.3265E 01	1.3258E 01	1.3251E 01	1.3244E 01	1.3237E 01	1.3230E 01	1.3223E 01
1.3216E 01	1.3209E 01	1.3202E 01	1.3195E 01	1.3188E 01	1.3181E 01	1.3174E 01	1.3167E 01	1.3160E 01
1.3153E 01	1.3146E 01	1.3139E 01	1.3132E 01	1.3125E 01	1.3118E 01	1.3111E 01	1.3104E 01	1.3097E 01
1.3090E 01	1.3083E 01	1.3076E 01	1.3069E 01	1.3062E 01	1.3055E 01	1.3048E 01	1.3041E 01	1.3034E 01
1.3027E 01	1.3020E 01	1.3013E 01	1.3006E 01	1.3000E 01	1.2993E 01	1.2986E 01	1.2979E 01	1.2972E 01
1.2965E 01	1.2958E 01	1.2951E 01	1.2944E 01	1.2937E 01	1.2930E 01	1.2923E 01	1.2916E 01	1.2909E 01
1.2902E 01	1.2895E 01	1.2888E 01	1.2881E 01	1.2874E 01	1.2867E 01	1.2860E 01	1.2853E 01	1.2846E 01
1.2839E 01	1.2832E 01	1.2825E 01	1.2818E 01	1.2811E 01	1.2804E 01	1.2797E 01	1.2790E 01	1.2783E 01
1.2776E 01	1.2769E 01	1.2762E 01	1.2755E 01	1.2748E 01	1.2741E 01	1.2734E 01	1.2727E 01	1.2720E 01
1.2713E 01	1.2706E 01	1.2699E 01	1.2692E 01	1.2685E 01	1.2678E 01	1.2671E 01	1.2664E 01	1.2657E 01
1.2650E 01	1.2643E 01	1.2636E 01	1.2629E 01	1.2622E 01	1.2615E 01	1.2608E 01	1.2601E 01	1.2594E 01
1.2587E 01	1.2580E 01	1.2573E 01	1.2566E 01	1.2559E 01	1.2552E 01	1.2545E 01	1.2538E 01	1.2531E 01
1.2524E 01	1.2517E 01	1.2510E 01	1.2503E 01	1.2496E 01	1.2489E 01	1.2482E 01	1.2475E 01	1.2468E 01
1.2461E 01	1.2454E 01	1.2447E 01	1.2440E 01	1.2433E 01	1.2426E 01	1.2419E 01	1.2412E 01	1.2405E 01
1.2398E 01	1.2391E 01	1.2384E 01	1.2377E 01	1.2370E 01	1.2363E 01	1.2356E 01	1.2349E 01	1.2342E 01
1.2335E 01	1.2328E 01	1.2321E 01	1.2314E 01	1.2307E 01	1.2300E 01	1.2293E 01	1.2286E 01	1.2279E 01
1.2272E 01	1.2265E 01	1.2258E 01	1.2251E 01	1.2244E 01	1.2237E 01	1.2230E 01	1.2223E 01	1.2216E 01
1.2209E 01	1.2202E 01	1.2195E 01	1.2188E 01	1.2181E 01	1.2174E 01	1.2167E 01	1.2160E 01	1.2153E 01
1.2146E 01	1.2139E 01	1.2132E 01	1.2125E 01	1.2118E 01	1.2111E 01	1.2104E 01	1.2097E 01	1.2090E 01
1.2083E 01	1.2076E 01	1.2069E 01	1.2062E 01	1.2055E 01	1.2048E 01	1.2041E 01	1.2034E 01	1.2027E 01
1.2020E 01	1.2013E 01	1.2006E 01	1.2000E 01	1.1993E 01	1.1986E 01	1.1979E 01	1.1972E 01	1.1965E 01

0.

MU(3)

2.5766E 01	2.5761E 01	2.5755E 01	2.5750E 01	2.5745E 01	2.5739E 01	2.5734E 01	2.5729E 01	2.5724E 01
2.5718E 01	2.5713E 01	2.5708E 01	2.5702E 01	2.5697E 01	2.5692E 01	2.5687E 01	2.5681E 01	2.5676E 01
2.5671E 01	2.5666E 01	2.5660E 01	2.5655E 01	2.5650E 01	2.5645E 01	2.5639E 01	2.5634E 01	2.5629E 01
2.5624E 01	2.5619E 01	2.5614E 01	2.5608E 01	2.5603E 01	2.5598E 01	2.5593E 01	2.5588E 01	2.5583E 01
2.5578E 01	2.5573E 01	2.5568E 01	2.5563E 01	2.5558E 01	2.5553E 01	2.5548E 01	2.5543E 01	2.5538E 01
2.5533E 01	2.5528E 01	2.5523E 01	2.5518E 01	2.5513E 01	2.5508E 01	2.5503E 01	2.5498E 01	2.5493E 01
2.5488E 01	2.5483E 01	2.5478E 01	2.5473E 01	2.5468E 01	2.5463E 01	2.5458E 01	2.5453E 01	2.5448E 01
2.5443E 01	2.5438E 01	2.5433E 01	2.5428E 01	2.5423E 01	2.5418E 01	2.5413E 01	2.5408E 01	2.5403E 01
2.5398E 01	2.5393E 01	2.5388E 01	2.5383E 01	2.5378E 01	2.5373E 01	2.5368E 01	2.5363E 01	2.5358E 01
2.5353E 01	2.5348E 01	2.5343E 01	2.5338E 01	2.5333E 01	2.5328E 01	2.5323E 01	2.5318E 01	2.5313E 01
2.5308E 01	2.5303E 01	2.5298E 01	2.5293E 01	2.5288E 01	2.5283E 01	2.5278E 01	2.5273E 01	2.5268E 01
2.5263E 01	2.5258E 01	2.5253E 01	2.5248E 01	2.5243E 01	2.5238E 01	2.5233E 01	2.5228E 01	2.5223E 01
2.5218E 01	2.5213E 01	2.5208E 01	2.5203E 01	2.5198E 01	2.5193E 01	2.5188E 01	2.5183E 01	2.5178E 01
2.5173E 01	2.5168E 01	2.5163E 01	2.5158E 01	2.5153E 01	2.5148E 01	2.5143E 01	2.5138E 01	2.5133E 01
2.5128E 01	2.5123E 01	2.5118E 01	2.5113E 01	2.5108E 01	2.5103E 01	2.5098E 01	2.5093E 01	2.5088E 01
2.5083E 01	2.5078E 01	2.5073E 01	2.5068E 01	2.5063E 01	2.5058E 01	2.5053E 01	2.5048E 01	2.5043E 01
2.5038E 01	2.5033E 01	2.5028E 01	2.5023E 01	2.5018E 01	2.5013E 01	2.5008E 01	2.5003E 01	2.5000E 01
2.4993E 01	2.4988E 01	2.4983E 01	2.4978E 01	2.4973E 01	2.4968E 01	2.4963E 01	2.4958E 01	2.4953E 01
2.4948E 01	2.4943E 01	2.4938E 01	2.4933E 01	2.4928E 01	2.4923E 01	2.4918E 01	2.4913E 01	2.4908E 01
2.4903E 01	2.4898E 01	2.4893E 01	2.4888E 01	2.4883E 01	2.4878E 01	2.4873E 01	2.4868E 01	2.4863E 01
2.4858E 01	2.4853E 01	2.4848E 01	2.4843E 01	2.4838E 01	2.4833E 01	2.4828E 01	2.4823E 01	2.4818E 01
2.4813E 01	2.4808E 01	2.4803E 01	2.4798E 01					

MU(5)

1.5270E 01	1.5277E 01	1.5284E 01	1.5290E 01	1.5297E 01	1.5304E 01	1.5311E 01	1.5317E 01	1.5324E 01
1.5331E 01	1.5337E 01	1.5344E 01	1.5351E 01	1.5358E 01	1.5364E 01	1.5371E 01	1.5378E 01	1.5384E 01
1.5391E 01	1.5398E 01	1.5405E 01	1.5411E 01	1.5418E 01	1.5425E 01	1.5432E 01	1.5438E 01	1.5445E 01
1.5452E 01	1.5458E 01	1.5465E 01	1.5472E 01	1.5479E 01	1.5485E 01	1.5492E 01	1.5499E 01	1.5505E 01
1.5512E 01	1.5519E 01	1.5526E 01	1.5532E 01	1.5539E 01	1.5546E 01	1.5552E 01	1.5559E 01	1.5566E 01
1.5572E 01	1.5579E 01	1.5586E 01	1.5592E 01	1.5599E 01	1.6030E 01	1.6435E 01	1.6813E 01	1.7166E 01
1.7496E 01	1.7803E 01	1.8088E 01	1.8352E 01	1.8596E 01	1.8821E 01	1.8821E 01	1.8818E 01	1.8814E 01
1.8807E 01	1.8798E 01	1.8787E 01	1.8774E 01	1.8759E 01	1.8743E 01	1.8725E 01	1.8911E 01	1.9080E 01
1.9234E 01	1.9372E 01	1.9495E 01	1.9605E 01	1.9701E 01	1.9785E 01	1.9856E 01	1.9915E 01	1.9963E 01
2.0000E 01	2.0027E 01	2.0043E 01	2.0050E 01	2.0048E 01	2.0037E 01	2.0017E 01	1.9990E 01	1.9954E 01
1.9911E 01	1.9860E 01	1.9803E 01	1.9739E 01	1.9668E 01	1.9591E 01	1.9509E 01	1.9420E 01	1.9325E 01
1.9226E 01								

MU(6)

1.0600E 01	1.0605E 01	1.0610E 01	1.0616E 01	1.0621E 01	1.0626E 01	1.0632E 01	1.0637E 01	1.0642E 01
1.0648E 01	1.0653E 01	1.0658E 01	1.0664E 01	1.0669E 01	1.0674E 01	1.0680E 01	1.0685E 01	1.0691E 01
1.0696E 01	1.0701E 01	1.0707E 01	1.0712E 01	1.0717E 01	1.0723E 01	1.0728E 01	1.0734E 01	1.0739E 01
1.0744E 01	1.0750E 01	1.0755E 01	1.0761E 01	1.0766E 01	1.0772E 01	1.0777E 01	1.0782E 01	1.0788E 01
1.0793E 01	1.0799E 01	1.0804E 01	1.0810E 01	1.0815E 01	1.0820E 01	1.0826E 01	1.0831E 01	1.0837E 01
1.0842E 01	1.0848E 01	1.0853E 01	1.0858E 01	1.0864E 01	1.1178E 01	1.1478E 01	1.1763E 01	1.2035E 01
1.2293E 01	1.2538E 01	1.2770E 01	1.2991E 01	1.3200E 01	1.3398E 01	1.3457E 01	1.3514E 01	1.3570E 01
1.3623E 01	1.3674E 01	1.3724E 01	1.3772E 01	1.3818E 01	1.3862E 01	1.3905E 01	1.4073E 01	1.4231E 01
1.4379E 01	1.4518E 01	1.4649E 01	1.4771E 01	1.4885E 01	1.4991E 01	1.5089E 01	1.5180E 01	1.5264E 01
1.5341E 01	1.5410E 01	1.5474E 01	1.5531E 01	1.5582E 01	1.5627E 01	1.5668E 01	1.5700E 01	1.5728E 01
1.5751E 01	1.5769E 01	1.5782E 01	1.5789E 01	1.5793E 01	1.5791E 01	1.5785E 01	1.5775E 01	1.5760E 01
1.5741E 01								

Fig. A.3 (continued)

WAPS CODE SAMPLE PROBLEM FOR REPORT

FAST GROUP SIGR(COMP,N),N#1, 21

COMP 1

2.1073E-05	1.9957E-05	1.8911E-05	1.7930E-05	1.7012E-05	1.6151E-05	1.9399E-05	1.8820E-05	1.8225E-05
1.7620E-05	1.7012E-05	1.8673E-05	1.8474E-05	1.8225E-05	1.7930E-05	1.8673E-05	1.8820E-05	1.8911E-05
1.9399E-05	1.9957E-05	2.1073E-05						

COMP 2

5.1667E-04	5.1667E-04	5.1667E-04	5.1667E-04	5.1667E-04	5.1667E-04	5.1667E-04	5.1667E-04	5.1667E-04
5.1667E-04	5.1667E-04	5.1667E-04	5.1667E-04	5.1667E-04	5.1667E-04	5.1667E-04	5.1667E-04	5.1667E-04
5.1667E-04	5.1667E-04	5.1667E-04						

COMP 3

7.9583E-05	7.7083E-05	7.4583E-05	7.2083E-05	6.9583E-05	6.7083E-05	7.5583E-05	7.4083E-05	7.2583E-05
7.1083E-05	6.9583E-05	7.3583E-05	7.3083E-05	7.2583E-05	7.2083E-05	7.3583E-05	7.4083E-05	7.4583E-05
7.5583E-05	7.7083E-05	7.9583E-05						

Fig. A.3 (continued)

SWAPS CODE SAMPLE PROBLEM FOR REPORT

SLOW GROUP SIGR(COMP,N),N#1, 21

COMP 1									
2.2865E-05	2.1698E-05	2.0603E-05	1.9577E-05	1.8613E-05	1.7710E-05	2.1114E-05	2.0507E-05	1.9884E-05	
1.9250E-05	1.8613E-05	2.0352E-05	2.0144E-05	1.9884E-05	1.9577E-05	2.0352E-05	2.0507E-05	2.0603E-05	
2.1114E-05	2.1698E-05	2.2865E-05							
COMP 2									
5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	
5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	
5.3333E-04	5.3333E-04	5.3333E-04							
COMP 3									
1.1523E-04	1.1181E-04	1.0838E-04	1.0495E-04	1.0153E-04	9.8102E-05	1.0975E-04	1.0769E-04	1.0564E-04	
1.0358E-04	1.0153E-04	1.0701E-04	1.0632E-04	1.0564E-04	1.0495E-04	1.0701E-04	1.0769E-04	1.0838E-04	
1.0975E-04	1.1181E-04	1.1523E-04							

Fig. A.3 (continued)

WAPS CODE SAMPLE PROBLEM FOR REPORT

FAST GROUP SIGS(COMP,N),N#1, 21

COMP 1

1.9849E-05	1.9235E-05	1.8649E-05	1.8091E-05	1.7558E-05	1.7051E-05	1.8912E-05	1.8581E-05	1.8244E-05
1.7902E-05	1.7558E-05	1.8491E-05	1.8378E-05	1.8244E-05	1.8091E-05	1.8491E-05	1.8581E-05	1.8649E-05
1.8912E-05	1.9235E-05	1.9849E-05						

COMP 2

5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04
5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04	5.3333E-04
5.3333E-04	5.3333E-04	5.3333E-04						

COMP 3

9.7407E-05	9.4444E-05	9.1481E-05	8.8519E-05	8.5556E-05	8.2593E-05	9.2667E-05	9.0889E-05	8.9111E-05
8.7333E-05	8.5556E-05	9.0296E-05	8.9704E-05	8.9111E-05	8.8519E-05	9.0296E-05	9.0889E-05	9.1481E-05
9.2667E-05	9.4444E-05	9.7407E-05						

Fig. A.3 (continued)

SWAPS CODE SAMPLE PROBLEM FOR REPORT

SLOW GROUP SIGS(COMP,N),N#1, 21

COMP 1

2.1777E-05	2.1056E-05	2.0371E-05	1.9719E-05	1.9099E-05	1.8510E-05	2.0681E-05	2.0295E-05	1.9901E-05
1.9501E-05	1.9099E-05	2.0190E-05	2.0058E-05	1.9901E-05	1.9719E-05	2.0190E-05	2.0295E-05	2.0371E-05
2.0681E-05	2.1056E-05	2.1777E-05						

COMP 2

5.5000E-04	5.5000E-04	5.5000E-04	5.5000E-04	5.5000E-04	5.5000E-04	5.5000E-04	5.5000E-04	5.5000E-04
5.5000E-04	5.5000E-04	5.5000E-04	5.5000E-04	5.5000E-04	5.5000E-04	5.5000E-04	5.5000E-04	5.5000E-04
5.5000E-04	5.5000E-04	5.5000E-04						

COMP 3

1.4000E-03	1.4000E-03	1.4000E-03	1.4000E-03	1.4000E-03	1.4000E-03	1.4000E-03	1.4000E-03	1.4000E-03
1.4000E-03	1.4000E-03	1.4000E-03	1.4000E-03	1.4000E-03	1.4000E-03	1.4000E-03	1.4000E-03	1.4000E-03
1.4000E-03	1.4000E-03	1.4000E-03						

Fig. A.3 (continued)

References

¹M. L. Tobias and T. B. Fowler, "EQUIPOISE - An IBM-704 Code for the Solution of Two-Group, Two-Dimensional, Neutron Diffusion Equations in Cylindrical Geometry," ORNL-2967 (Oct. 17, 1960).

²B. G. Carlson and G.I. Bell, "Solution of the Transport Equation by the S_n Method," P/2386, Second International Conference on the Peaceful Uses of Atomic Energy, Geneva (1958).

³L. A. Hageman, "On a Numerical Approximation to the Solution of the One-Dimensional, One-Velocity Transport Equation with Isotropic Scattering," WAPD-T-706 (Jan., 1959).

⁴A. M. Weinberg and E. P. Wigner, The Physical Theory of Neutron Chain Reactors, University of Chicago Press, 1958.

⁵K. M. Case, F. de Hoffmann, and G. Placzek, Introduction to the Theory of Neutron Diffusion, Vol. 1, p. 148, Los Alamos Scientific Laboratory (June 1953).

⁶L. Dresner, "On the Validity of the Second Fundamental Theorem in a Medium with Anisotropic Scattering," Nuclear Sci. and Eng. 7, 419-424 (1960).

Internal Distribution

1. L. G. Alexander	37. B. Maskewitz (K-25)
2. V. E. Anderson (K-25)	38. A. J. Miller
3. S. E. Beall	39. E. A. Nephew
4. M. Bender	40. C. W. Nestor, Jr.
5. L. L. Bennett	41. C. E. Newlon (K-25)
6. A. L. Boch	42. A. M. Perry
7. W. L. Breazeale	43. P. H. Pitkanen
8. R. B. Briggs	44. C. A. Preskitt
9. R. S. Carlsmith	45. B. E. Prince
10. W. L. Carter	46. M. W. Rosenthal
11. R. D. Cheverton	47. T. H. Row
12. H. C. Claiborne	48. J. E. Rowe (K-25)
13. A. L. Colomb	49. H. W. Savage
14. R. R. Coveyou	50. A. W. Savolainen
15. J. G. Delene	51. E. G. Silver
16. A. C. Downing	52. M. J. Skinner
17. J. R. Engel	53. O. L. Smith
18-22. T. B. Fowler	54. I. Spiewak
23. A. P. Fraas	55. J. G. Sullivan
24. E. H. Gift	56. J. A. Swartout
25. D. R. Gilfillan	57-61. M. L. Tobias
26. E. E. Gross	62. D. B. Trauger
27. P. N. Haubenreich	63. M. E. Tsagaris
28. A. S. Householder	64. R. Van Winkle
29. W. H. Jordan	65. D. R. Vondy
30. P. R. Kasten	66-70. Laboratory Records Department
31. T. W. Kerlin	71. Laboratory Records, LRD-RC
32. W. E. Kinney	72-74. Y-12 Document Reference
33. J. A. Lane	Section, DRS
34. R. N. Lyon	75-76. Central Research Library, CRL
35. H. G. MacPherson	77-78. Reactor Division Library
36. W. D. Manly	79. SHARE Library (K-25)

External Distribution

80. C. P. Bhalla, Westinghouse Electric Corporation, Atomic Power Department, Pittsburgh, Pa.
81. L. R. Blue, Atomic International, Canoga Park, Calif.
82. W. Cartwell, System Analysis and Computation, IBM, Owego, New York
83. R. L. Crowther, Atomic Power Department, General Electric Co., San Jose, Calif.
84. E. M. Gelbard, Westinghouse Electric Corporation, Bettis Plant, Pittsburgh, Pa.
85. D. H. Groelsema, AEC, Washington
86. Haig Iskenderian, Argonne National Laboratory
87. D. Jacobson, Argonne National Laboratory
88. Seymour Jaye, General Atomic, San Diego, Calif.
89. W. B. Lee, Lockheed Nuclear Products, Atlanta, Georgia

- 90. D. J. Mallon, Allison Division, General Motors Corp.,
Indianapolis, Indiana
- 91. T. F. McKiernan, Pratt & Whitney Aircraft, Hartford, Conn.
- 92. B. H. Mount, Westinghouse Electric Corp., Bettis Plant,
Pittsburgh, Pa.
- 93. W. Sangren, General Atomic, San Diego, Calif.
- 94. D. M. Shapiro, Internuclear Company, Clayton, Missouri
- 95. D. W. Thomas, Aerojet-General Nucleonics, San Ramon, Calif.
- 96-110. Division of Technical Information Extension, DTIE
- 111. Research and Development Division, ORO
- 112-113. Reactor Division, ORO

2

2

2

2