**Development of An Advanced, Continuous Mild Gasification
Process for the Production of Co-Products (Task 4.7),
Volume III**

Final Report

**R.A. Knight
J.L. Gissy
M. Onischak
S.P. Babu
R.H. Carty
R.G. Duthie (Bechtel Group, Inc.)
J.M. Wootten (Peabody Holding Co. Inc.)**

September 1991

Work Performed Under Contract No.: DE-AC21-87MC24266

**For
U.S. Department of Energy
Office of Fossil Energy
Morgantown Energy Technology Center
Morgantown, West Virginia**

**By
Institute of Gas Technology
Chicago, Illinois**

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

This report has been reproduced directly from the best available copy.

Available to DOE and DOE contractors from the Office of Scientific and Technical Information, P.O. Box 62, Oak Ridge, TN 37831; prices available from (615)576-8401, ~~888-686-8401~~.

Available to the public from the National Technical Information Service, U. S. Department of Commerce, 5285 Port Royal Rd., Springfield, VA 22161.

**Development of An Advanced, Continuous Mild Gasification
Process for the Production of Co-Products (Task 4.7),
Volume III**

Final Report

**R.A. Knight
J.L. Gissy
M. Onischak
S.P. Babu
R.H. Carty
R.G. Duthie (Bechtel Group, Inc.)
J.M. Wootten (Peabody Holding Co. Inc.)**

Work Performed Under Contract No.: DE-AC21-87MC24266

**For
U.S. Department of Energy
Office of Fossil Energy
Morgantown Energy Technology Center
P.O. Box 880
Morgantown, West Virginia 26507-0880**

**By
Institute of Gas Technology
IIT Center, 3424 S. State Street
Chicago, Illinois 60616**

September 1991

Volume I

Project Summary

**Literature Survey of Mild Gasification Processes,
Co-Product Upgrading and Utilization, and Market
Assessment (Program Task 1)**

Volume II

**Mild Gasification Technology Development:
Process Research Unit Tests Using Slipstream Sampling
(Program Task 2)**

**Bench-Scale Char Upgrading Study
(Program Task 3)**

**Mild Gasification Technology Development:
System Integration Studies
(Program Tasks 4.1 to 4.6)**

Volume III

**Mild Gasification Technology Development:
24 Ton Per Day Process Development Unit Design
and Cost Estimates (Program Task 4.7)**

TABLE OF CONTENTS

	<u>Page</u>
INTRODUCTION	III-1
MILD GASIFICATION UNIT CONCEPTUAL DESIGN	III-2
<u>Design Basis</u>	III-2
System Capacity	III-4
Design Operating Parameters	III-4
Yields and Compositions	III-5
<u>Process Description</u>	III-6
Coal Feed and Drying	III-26
Gasification and Heat Supply	III-27
Liquids Recovery System	III-29
Emission Control and Char Handling	III-30
Liquids Storage and Handling	III-32
Material Balances	III-32
Energy Balances	III-33
<u>Utilities Requirement</u>	III-34
<u>Normal Operation and Controls</u>	III-35
Char Recycle Control	III-35
Gasifier Fluidized Bed Temperature Control	III-37
Gasifier Entrained Bed Temperature Control	III-37
Gasifier Pressure Control	III-38
Coal Drying and Preheating	III-38
Emission System Control	III-38
Safety	III-39
Environmental Controls	III-40
<u>Startup Procedures</u>	III-40
<u>Standby</u>	III-41
<u>Shutdown</u>	III-42

TABLE OF CONTENTS, Cont.

	<u>Page</u>
<u>Approach to Steady State Following Startup and/or Feed Change</u>	III-42
<u>Special Equipment Designs</u>	III-43
Coal Dryer and Preheater	III-43
Gasifier	III-43
Hot Gas/Char Fines Separation	III-43
Char Heater	III-45
Thermal Cracker	III-45
Tar Recovery	III-45
FORM COKE PROCESS CONCEPTUAL DESIGN	III-46
<u>Design Basis</u>	III-46
System Capacity	III-46
Design Operating Parameters	III-46
Yields and Compositions	III-46
<u>Process Description</u>	III-49
Feed Preparation	III-49
Material Balance	III-56
Energy Balance	III-56
<u>Utilities Requirements</u>	III-57
Normal Operation and Controls	III-58
Mixer/Heater Temperature Control	III-60
Calciner Temperature Control	III-60
Incinerator Temperature Control	III-60
Pressure Control	III-61
<u>Startup Procedures</u>	III-61
<u>Standby</u>	III-62
<u>Shutdown</u>	III-63
<u>Special Equipment Designs</u>	III-63
Mixer/Heater	III-63
Hot Roll Briquetter	III-63
Calciner	III-64

TABLE OF CONTENTS, Cont.

	<u>Page</u>
CAPITAL COST ESTIMATE	III-65
OPERATING COST ESTIMATE	III-69
<u>Operations Staff Requirements</u>	III-69
<u>Test Program Operating Cost</u>	III-69
DETAILED ENGINEERING	III-72
<u>Piping and Instrumentation Diagrams</u>	III-72
<u>Electrical Single-Line Diagram</u>	III-74
<u>Additional Information Required for Final Engineering</u>	III-74
APPENDIX A. Material Balances for Two Alternative Hot Char Recycle Rates	III-A-1
APPENDIX B. Equipment List	III-B-1
APPENDIX C. Piping and Instrumentation Drawings and Electrical One-Line Drawing	III-C-1
APPENDIX D. PDU Cost Savings Opportunities	III-D-1

LIST OF FIGURES

<u>Figure No.</u>		<u>Page</u>
III-1	Mild Gasification Overall Block Diagram	III-3
III-2	Process Flow Diagram Coal Feed and Drying Unit	III-9
III-3	Process Flow Diagram Gasification and Heat Supply System	III-11
III-4	Process Flow Diagram Liquids Recovery System	III-13
III-5	Process Flow Diagram Char Storage/Handling and Emission Control System	III-15
III-6	Process Flow Diagram Liquids Storage and Handling System	III-17
III-7	Mild Gasification Control Diagram	III-36
III-8	Mild Gasification Vessel -- 24 tpd PDU	III-44
III-9	Form Coke Production Block Diagram	III-47
III-10	Process Flow Diagram Form Coke Production	III-51
III-11	Form Coke Production Control Diagram	III-59
III-12	Preliminary layout -- 24 tpd Process Demonstration Facility (Side View)	III-67
III-13	Preliminary Layout -- 24 tpd Process Demonstration Facility (Perspective View)	III-67
III-14	PDU Equipment Elevations Relative to the Existing High Bay Building	III-68

LIST OF TABLES

<u>Table No.</u>		<u>Page</u>
III-1	Design Operating Parameter Ranges for the Mild Gasification Unit Conceptual Design	III-4
III-2	Coal Properties of Feed Coal, Illinois No. 6	III-5
III-3	Oil and Tar Composition	III-5
III-4	Gasification Product Composition	III-6
III-5	Weight Percent of Oils and Tars for Several Values of TBP	III-7
III-6	Gas Analysis	III-7
III-7	IGT-PDU Material Balance (1:1 Char:Coal Recycle) for Streams 1 through 80	III-19
III-8	Overall Energy Balance Mild Gasification	III-33
III-9	Operating Parameter Ranges for the Form Coke Process	III-48
III-10	Composition in Weight Percent of the Coal Feed, Gasifier Char, and the Form Coke Product	III-48
III-11	IGT -- Form Coke Process Material Balance for Streams 1 through 26	III-53
III-12	Overall Energy Balance Form Coke Production	III-57
III-13	24 tpd PDU Estimated Capital Cost (1st Quarter 1991 10 ⁶ \$)	III-66
III-14	PDU Test Program -- Staff Requirement for a 15-Month Test Program and Documentation	III-70
III-15	PDU Operating Costs for a 12-Month Test Program	III-71
III-16	Preliminary P&IDs	III-73

INTRODUCTION

The focus of this task is the preparation of (1) preliminary piping and instrument diagrams (P&IDs) and single line electrical diagrams for a site-specific conceptual design and (2) a factored cost estimate for a 24 ton/day (tpd) capacity mild gasification process development unit (PDU) and an associated form coke preparation PDU. The intended site for this facility is the Illinois Coal Development Park at Carterville, Illinois, which is operated by Southern Illinois University at Carbondale.

The basis for the PDU process design was derived from operating data obtained from the 100 lb/hr capacity process research unit (PRU) operated by IGT at its Energy Development Center in Chicago. The form coke facility configuration is based on the recommendations of IGT and its consultants. The conceptual-level cost estimate was developed from equipment costs and installation factors derived largely from Bechtel in-house data.

MILD GASIFICATION UNIT CONCEPTUAL DESIGN

Design Basis

An overall block diagram for the continuous mild gasification process development unit (PDU) is shown in Figure III-1.

The mild gasification process selected is an advanced fluidized bed concept for low-temperature carbonization of coal. Gasification is carried out at temperatures of 1000°F to 1500°F and pressures of 0 to 50 psig to convert crushed coal (or coal fines) to char and coal-derived liquids.

The design coal feed, which consists of wet -6 mesh x 0 fines from a coal cleaning plant, is first dried and preheated and then fed directly to the fluidized bed of the gasifier vessel. The fluidized bed is heated to 1200°F and fluidized by a recycle gas stream which has been heated to 2000°F to 2500°F. Heat to the gasifier is supplied via a combination of hot char and hot gas recycle. Hot recycle char is supplied by partial combustion of a portion of the fluidized bed char. Hot recycle gas is produced by partial combustion of the noncondensable gas from liquids recovery. The unit is designed to permit the relative amounts of heat supplied by hot char and hot gas recycle to be varied. A greater hot char recycle rate results in less nitrogen dilution and a higher heating value of the noncondensable gas.

The design includes optional thermal cracking of the product vapor at temperatures up to 1,800°F before condensation. The retort product vapor is processed in conventional cyclones to remove entrained char fines. In the condensation step, product vapor is cooled and compressed to recover tar, middle oil, light oil, and water. The noncondensable gas is either recycled to the gasifier or incinerated. The coarse char is removed from the fluidized bed. Both the char fines and coarse char streams are cooled for storage and/or subsequent briquetting.

Gas streams exiting from the char heater, coal dryer, and liquids recovery section are incinerated and subsequently scrubbed to control sulfur emissions. In addition, the small quantity of sour water from liquids recovery may also be incinerated. Heat recovered from the incinerator flue gas is used to preheat both recycle gas for gasifier fluidization and clean flue gas for coal drying/preheating.

Figure III-1. MILD GASIFICATION OVERALL BLOCK DIAGRAM

System Capacity

The normal capacity of the mild gasification unit has been specified as 24 tpd of moisture-free coal (Illinois No. 6). This capacity of the process system and corresponding design of the equipment is selected to:

- Provide an adequate scale for equipment and process demonstration and to develop an adequate basis for the design of a commercial-scale facility
- Maintain a manageable and cost-effective scale for establishing design parameters and for product property and use testing

Design Operating Parameters

The ranges of the design operating parameters have been selected by IGT for the test operation. These parameters, along with their maximum, nominal, and minimum values, are listed in Table III-1.

Table III-1. DESIGN OPERATING PARAMETER RANGES FOR THE
MILD GASIFICATION PDU

Parameter	Maximum	Nominal	Minimum
Operating Pressure, psia	50.0	30.0	12.0
Operating Temperature, °F			
Fluidized Bed	1300	1100	1000
Entrained Bed (In)	1300	1100	1000
Entrained Bed (Out)	1300	1000	900
Gas Velocities, ft/sec			
Fluidized Bed Inlet	9.0	8.0	6.0
Fluidized Bed	4.5	4.0	3.5
Entrained Bed	16.0	14.2	12.0
L/D Ratio			
Fluidized Bed Inlet	N/A	1	N/A
Fluidized Bed	2	1	0.5
Entrained Bed	--	16	--
Bed Residence Time			
Fluidized Bed (min)	14.8	6.3	2.5
Entrained Bed (sec)	1.3	1.1	1.0
Hot Char Recycle (60+ mesh)			
Char/Coal Ratio	2	1	0
Temperature, °F	2200	1800	1400
Hot Gas Recycle			
Gas Temperature, °F	2500	2000	1500
Coal Feed (MF) Basis			
Fluidized Bed (+100 mesh)	1600 lb/hr		
Entrained Bed (100 mesh x 0)	400 lb/hr		

Coal is delivered by truck as wet fines. Onsite feed coal storage is provided for 200 tons.

Yields and Compositions

An illustrative yield structure for mild gasification was derived from IGT's process research unit (PRU) Run MG-12. Gas and liquid compositions were obtained directly from run data for MG-12. The product yields were adjusted to give a conservative estimate of valuable product yields based on data accumulated for several runs. Run MG-12 employed a sample of Illinois No. 6 coal fines provided by Peabody Coal Company. The coal properties and the measured yields of char, and net volatile products are summarized in Table III-2. The bulk elemental analysis of oils and tars were assumed to be as shown in Table III-3.

Table III-2. COAL PROPERTIES OF FEED COAL, ILLINOIS NO. 6

<u>Item</u>	<u>Wt %</u>
Proximate Analysis	
Moisture	3.32
Volatile	35.23
Fixed Carbon	47.34
Ash	<u>14.11</u>
Total	100.00
	11,520
Ultimate Analysis	
Carbon	65.43
Hydrogen	4.43
Oxygen	10.49
Nitrogen	1.28
Sulfur	3.81
Ash	<u>14.56</u>
Total	100.00
HHV = 11,520 Btu/lb	
Overall Yields	
Char	66.6
Oils and Tars	18.3
Gas	10.3
Water	<u>4.8</u>
Total	100.00

Table III-3. OIL AND TAR COMPOSITION

<u>Item</u>	<u>Wt %</u>
Carbon	74.24
Hydrogen	6.74
Oxygen	16.22
Nitrogen	0.78
Sulfur	1.61
Ash	<u>0.42</u>
Total	100.00

The component analyses of the full-range oils and tars are expanded into the following four fractions expressed as weight percent of the total oils and tars.

Table III-4. GASIFICATION PRODUCT COMPOSITION

Item	Wt %
Light oil product	
Benzene	1.2
Toluene	1.3
Xylenes	0.8
Ethylbenzene	0.6
Indene	0.4
Styrene	0.3
Other light oils	<u>4.3</u>
Total light oil	8.9 ^a
Middle oil product	
Phenols	1.0
Cresols	1.4
Xylenols	0.6
Naphthalene	0.5
Other middle oils	<u>11.8</u>
Total middle oils	15.3 ^b
Heavy oil product	
Heavy oil	11.7 ^c
Pitch	<u>64.1^d</u>
Total	100.00

^a Atmospheric boiling point less than 360°F.

^b Atmospheric boiling point 360°F to 590°F.

^c Atmospheric boiling point 590°F to 750°F.

^d Atmospheric boiling point greater than 750°F.

For more precise modeling of the performance of the condensing train, the IGT-simulated distillation curves for the heavy oil and pitch were used to develop the petroleum-type true boiling point (TBP) distribution breakdown for the combined heavy oil and pitch fraction as shown in Table III-5.

The net makeup of noncondensable gas from mild gasification has the estimated volumetric composition (expressed as mol%) given in Table III-6.

Process Description

The proposed process flow scheme for the 24 tpd mild gasification process is divided into the following five major sections:

- Coal feed and drying
- Gasification and heat supply
- Liquids recovery system
- Emission control and char handling
- Liquids storage and handling

Table III-5. WEIGHT PERCENT OF OILS AND TARS FOR SEVERAL VALUES OF TBP

<u>TBP (°F)</u>	<u>Wt %</u>
333	2.0
438	2.1
544	2.5
649	2.5
754	2.6
860	6.2
965	5.3
1070	5.7
1176	5.9
1281	6.0
1386	6.1
1492	6.3
1597	<u>22.6</u>
Total	75.8

Table III-6. GAS ANALYSIS

<u>Mol% in Gas, Component</u>	<u>Nitrogen Free</u>
Hydrogen	37.5
Carbon Monoxide	16.1
Carbon Dioxide	8.7
Methane	23.3
Ethylene	6.3
Ethane	2.5
Propylene	2.1
Propane	0.2
Hydrogen Sulfide	<u>3.3</u>
Total	100.0

Each section is described below with reference to its specific process flow diagrams (Figures III-2 through III-6). A base case material balance keyed to the flow diagrams and based on a hot recycle char to coal ratio of 1:1 is included as Table III-7 following Figure III-6. Two additional balances differing in the quantity of hot char recycle employed for gasification heat input have also been developed.

Figure III-3. PROCESS FLOW DIAGRAM GASIFICATION AND HEAT SUPPLY SYSTEM

Figure III-4. PROCESS FLOW DIAGRAM LIQUIDS RECOVERY SYSTEM

Figure III-5. PROCESS FLOW DIAGRAM CHAR STORAGE/HANDLING AND EMISSION CONTROL SYSTEM

Figure III-6. PROCESS FLOW DIAGRAM LIQUIDS STORAGE AND HANDLING SYSTEM

Table III-7, Part 1. IGT-PDU MATERIAL BALANCE (1:1 CHAR:COAL RECYCLE)
FOR STREAMS 1 THROUGH 20

Item	1	2	3	4	5	6	7	8	9	10	11	12
	Wet Feed Coal	Flue Gas to Coal Dryer	Dried Feed Coal	Flue Gas from Coal Dryer	Dryer Recycle to Coal Preheater	Dryer Vent Gas to Incinerator	Hot Gas to Coal Preheater	Preheated Coal/Gas to Cyclones	Preheated Coal Fines	Preheated Coarse Coal	Gas from Booster Htr to Gasifier	Air to Booster Htr
Pressure, psia	15	36	36	36	39	15	39	37	37	37	39	40
Temperature, °F	60	532	192	192	212	212	666	532	532	532	2,000	890
Total flow, lb/hr	2,500	5,945	2,014	6,431	3,100	3,251	5,851	7,945	400	1,600	1,236	734
acfh		61,103		45,396	20,820	56,762	62,877	59,451			28,918	9,202
scfh		78,461		88,690	42,755	44,832	77,059	78,461			16,222	9,647
Solids flow, lb/hr	2,000.0		2,000.0					2,000.0	400.0	1,600.0		
Coal (MAF) (a)	1,710.0		1,710.0					1,710.0	342.0	1,368.0		
Char (MAF)	290.0		290.0					290.0	58.0	232.0		
Gas/liquid flows, lb/hr	500.0	5,944.8	14.2	6,430.6	3,100.0	3,250.6	5,850.6	5,944.8			1,236.2	734.1
N2		4,066.3		4,066.3	1,960.3	2,055.5	4,015.7	4,066.3			880.0	563.0
O2		10.4		10.4	5.0	5.3	10.3	10.4				171.0
CO		1,288.5		1,288.5	621.2	651.3	1,272.5	1,288.5			239.5	
CO2		579.3	14.2	1,065.1	513.5	538.4	551.8	579.3			102.8	
H2O	500.0											
H2												
CH4												
C2H4												
C2H6												
C3H6												
C3H8												
Light oil												
Middle oil												
Tar/heavy oil												
SO2		0.2		0.2	0.1	0.1	0.2	0.2			13.9	
H2S												
NaOH												
Na2SO3												

(a) MAF - moisture- and ash-free

Table III-7, Part 2. IGT-PDU MATERIAL BALANCE (1:CHAR:COAL RECYCLE)
FOR STREAMS 1 THROUGH 20

Item	13	14	15	16	17	18	19	20	21	22	23	24
	Hot Recycle Gas to Booster Htr	Hot Recycle Gas Bypass	Air to Char Htr	Recycle Gas to Char Htr	Flue Gas from Char Htr	Char from Htr Cyclone	Flue Gas from Htr Cyclone	Char Gas to Incinerator	Hot Gas to Coal Preheater	Air to Gasifier Heaters	Hot Recycle Gas to Gasifier	Recycle Gas to Heat Recovery
Pressure, psia	40	40	40	40	37	37	37	15	40	42	40	40
Temperature, °F	1,200	1,200	890	1,200	2,000	2,000	2,000	1,200	1,200	200	1,200	100
Total flow, lb/hr	502	969	1,286		3,286	1,875	1,411	1,411	2,751	2,020	1,471	1,471
acfh	8,200	15,813	16,122		32,503		32,503	54,101	40,234	33,698	24,014	8,101
scfh	6,992	13,483	16,903		17,298		17,298	17,298	34,304	26,550	20,475	20,475
Solids flow, lb/hr					1,875.0	1,875.0						
Coal (MAF) (a)					1,394.5	1,394.5						
Char (MAF)					480.5	480.5						
Ash												
Gas/liquid flows, lb/hr	502.3	968.6	1,286.3		1,411.3		1,411.3	1,411.3	2,750.6	2,020.4	1,470.9	1,470.9
N ₂	316.8	610.9	986.3		986.3		986.3	986.3	2,055.5	1,549.3	927.8	927.8
O ₂			300.0						5.3	471.0		
CO	19.2	37.0			58.3		58.3	58.3			56.2	56.2
CO ₂	102.7	198.0			366.7		366.7	366.7	651.3		300.7	300.7
H ₂ O	14.1	27.2							38.4		41.3	41.3
H ₂	3.2	6.2									9.4	9.4
CH ₄	15.9	30.6									46.5	46.5
C ₂ H ₄	7.5	14.5									22.0	22.0
C ₂ H ₆	3.2	6.2									9.4	9.4
C ₃ H ₆	3.8	7.2									11.0	11.0
C ₃ H ₈	0.4	0.7									1.1	1.1
Light oil	4.9	9.5									14.5	14.5
Middle oil	1.2	2.3									3.5	3.5
Tar/heavy oil												
SO ₂	4.7	9.0							0.1		13.7	13.7
H ₂ S	4.8	9.2									14.0	14.0
NaOH												
Na ₂ SO ₃												

(a) MAF = moisture- and ash-free

Table III-7, Part 3. IGT-PDU MATERIAL BALANCE (1:1 CHAR:COAL RECYCLE)
FOR STREAMS 1 THROUGH 20

Item	25 Char to Char Htr	26 Recycle Gas to Gasifier (Coal Fines)	27 Recycle Gas to Gasifier (Coarse Coal)	28 Recycle Gas to Gasifier (Char Inject)	29 Recycle Gas to Char Recycle	30 Coarse Char Product	31 Gasifier Flue Gas	32 Gas to Thermal Cracking	33 Char Fines Product	34 Heavy Oil/ Tar to Storage	35 Gas from Heavy Oil/ Tar Separator	36 Gas from Middle Oil Separator
Pressure, psia	37	40	40	40	40	15	35	34	15	15	33	32
Temperature, °F	1,100	100	100	100	100	140	925	925	140	450	450	170
Total flow, lb/hr	2,000	26	26	75	75	935	3,272	3,000	272	242	2,758	2,679
acth		144	144	413	413		43,122	44,390			29,810	21,208
scfh		363	363	1,044	1,044		38,558	38,558			38,251	38,116
Solids flow, lb/hr	2,000.0					935.4	271.6		271.6			
Coal (MAF) (a)												
Char (MAF)	1,519.5					710.7	206.3		206.3			
Ash	480.5					224.7	65.3		65.3			
Gas/liquid flows, lb/hr		26.1	26.1	75.0	75.0		3,000.0	3,000.0		242.2	2,757.8	2,679.3
N2		16.5	16.5	47.3	47.3		1,571.1	1,571.1			1,571.1	1,571.1
O2												
CO		1.0	1.0	2.9	2.9		95.2	95.2			95.2	95.2
CO2		5.3	5.3	15.3	15.3		508.8	508.8			508.8	508.8
H2O		0.7	0.7	2.1	2.1		229.6	229.6			229.6	229.6
H2		0.2	0.2	0.5	0.5		15.8	15.8			15.8	15.8
CH4		0.8	0.8	2.4	2.4		78.7	78.7			78.7	78.7
C2H4		0.4	0.4	1.1	1.1		37.2	37.2			37.2	37.2
C2H6		0.2	0.2	0.5	0.5		15.8	15.8			15.8	15.8
C3H6		0.2	0.2	0.6	0.6		18.6	18.6			18.6	18.6
C3H8		0.0	0.0	0.1	0.1		1.9	1.9			1.9	1.9
Light oil		0.3	0.3	0.7	0.7		43.4	43.4		0.1	43.2	38.0
Middle oil							58.6	58.6		1.1	57.5	20.6
Tar/heavy oil		0.1	0.1	0.2	0.2		277.4	277.4		241.0	36.5	
SO2		0.2	0.2	0.7	0.7		24.1	24.1			24.1	24.1
H2S		0.2	0.2	0.7	0.7		23.7	23.7			23.7	23.7
NaOH												
Na2SO3												

(a) MAF = moisture and ash-free

Table III-7, Part 4. IGT-PDU MATERIAL BALANCE (1:1 CHAR:COAL RECYCLE)
FOR STREAMS 1 THROUGH 20

Item	37	38	39	40	40A	41	42	43	44	45	46	46A	47
	Middle Oil	Gas to	Light Oil	Sour Water	Gas from	Water	Cautic	Concentrated	Liquid	Air	Recycle Gas	Total Vent	Sodium
	to	Light Oil	to	to	Light Oil	to Gas	to Gas	Sulfide Sol.	from	to	Vent to	Gas to	Sulfide to
	Storage	Quench	Storage	Storage	Separator	Scrubber	Scrubber	Sulfide Sol.	Scrubber	Incinerator	Incinerator	Incinerator	Storage
Pressure, psia	15	42	15	15	40	24	12	25	35	40	15	15	15
Temperature, °F	170	209	100	100	100	60	60	180	180	60	100	400	100
Total flow, lb/hr	78	2,679	28	160	2,491	100	128	218	437	1,840	893	5,555	218
acfh		17,158			13,719					8,884	13,112	120,806	
scfh		38,116			34,672					24,182	12,427	74,557	
Solids flow, lb/hr													
Coal (MAF) (a)													
Char (MAF)													
Ash													
Gas/liquid flows, lb/hr	78.5	2,679.3	28.2	159.8	2,491.3	100.0	127.6	218.4	436.8	1,840.1	893.2	5,555.0	218.4
N2		1,571.1			1,571.1					1,411.4	563.1	3,604.9	
O2										428.8		5.3	
CO		95.2			95.2						34.1	92.4	
CO2		508.8			508.8						182.1	1,200.1	
H2O		229.6		159.8	69.8	100.0	95.7	168.2	336.4		25.0	563.4	168.2
H2		15.8			15.8						5.7	5.7	
CH4		78.7			78.7						28.2	28.2	
C2H4		37.2			37.2						13.3	13.3	
C2H6		15.8			15.8						5.7	5.7	
C3H6		18.6			18.6						6.7	6.7	
C3H8		1.9			1.9						0.7	0.7	
Light oil	5.2	38.0	13.5		24.5						8.8	8.8	
Middle oil	36.8	20.6	14.7		5.9						2.1	2.1	
Tar/heavy oil	36.5												
SO2		24.1			24.1						9.2	9.3	
H2S		23.7			23.7						8.5	8.5	
NaOH													
Na2SO3													
(a) MAF = moisture- and ash-free													

Table III-7, Part 5. IGT-PDU MATERIAL BALANCE (1:1 CHAR:COAL RECYCLE)
FOR STREAMS 1 THROUGH 20

Item	48 Sour Water to Incinerator	49 Natural Gas to Incinerator	50 Clean Gas from Scrubber	51 Effluent from Incinerator	52 Dryer Recycle Gas for Fluidization	53 Fluidized Coal Fines to Gasifier	54 Fluidized Coarse Coal to Gasifier	55 Recycle Gas for Coal Injection	56 Cracked Gas to Liquid Recovery	57 Natural Gas Makeup to Recycle	58 Off Gas from Briquetting	59 Combined Gas to Scrubber
Pressure, psia	25	40	12	14	39	37	37	40	34	40	15	15
Temperature, °F	100	60	160	790	212	532	532	100	1,800	60		790
Total flow, lb/hr	160	20	9,008	7,575	80	426	1,626	52	3,000			7,575
acfh		174	192,794	256,094	537	275	275	287	72,434			239,021
scfh		474	132,035	101,490	1,103	363	363	727	38,558			101,490
Solids flow, lb/hr						400.0	1,600.0					
Coal (MAF) (a)						342.0	1,368.0					
Char (MAF)						58.0	232.0					
Ash												
Gas/liquid flows, lb/hr	159.8	20.0	9,007.7	7,575.3	80.0	26.1	26.1	52.2	3,000.0			7,575.3
N ₂						16.5	16.5	32.9	1,571.1			5,016.4
O ₂			5,016.4	5,016.4	50.6							12.9
CO			12.9	12.9	0.1	1.0	1.0	2.0	95.2			1,589.9
CO ₂			1,589.9	1,589.9	16.0	5.3	5.3	10.7	508.8			930.4
H ₂ O			2,388.2	930.4	13.3	0.7	0.7	1.5	229.6			
H ₂	159.8					0.2	0.2	0.3	15.8			
CH ₄						0.8	0.8	1.6	78.7			
C ₂ H ₄		20.0				0.4	0.4	0.8	37.2			
C ₂ H ₆						0.2	0.2	0.3	15.8			
C ₃ H ₆						0.2	0.2	0.4	18.6			
C ₃ H ₈						0.0	0.0	0.0	1.9			
Light oil						0.3	0.3	0.5	43.4			
Middle oil						0.1	0.1	0.1	58.6			
Tar/heavy oil									277.4			
SO ₂			0.3	25.8		0.2	0.2	0.5	24.1			25.8
H ₂ S						0.2	0.2	0.5	23.7			
NaOH												
Na ₂ SO ₃												

(a) MAF = moisture- and ash-free

Table III-7, Part 6. IGT-PDU MATERIAL BALANCE (1:1 CHAR:COAL RECYCLE)
FOR STREAMS 1 THROUGH 20

Item	60	61	62	63	64	65	66	67	68	69	70	71	72
	Water Quench to Scrubber Feed	Feed Gas to Scrubber	Scrubber Recycle	Clean Gas to Stack	Heavy Oil/Tar from Separator	Tar Quench Recycle	Sludge to Gasifier	Middle Oil from Separator	Middle Oil Quench Recycle	Stream to Middle Oil Cooler	Coarse Char To Briquetting	Char Fines to Briquetting	Nitrogen to Char Transport
Pressure, psia	24	14	14	15	33	34	37	32	32	33	15	15	20
Temperature, °F	60	180	180	200	450	291	450	170	170	225	140	140	116
Total flow, lb/hr	1,423	8,998	218	5,316	18,242	18,000		8,178	8,100	10,858	935	272	48
acfh	169,833			96,893						30,647			532
scfh	131,454			77,919						52,241			654
Solids flow, lb/hr											935.4	271.6	
Coal (MAF) (a)													
Char (MAF)													
Ash													
Gas/liquid flows, lb/hr	1,423.1	8,998.4	218.4	5,316.2	18,242.2	18,000.0		8,178.5	8,100.0	10,857.8	710.7	206.3	48.3
N2		5,016.4		2,960.9						1,571.1			
O2		12.9		7.6									
CO										95.2			
CO2		1,589.9		938.6						508.8			
H2O	1,423.1	2,353.5	168.2	1,408.9						229.6			
H2										15.8			
CH4										78.7			
C2H4										37.2			
C2H6										15.8			
C3H6										18.6			
C3H8										1.9			
Light oil					9.5	9.3		542.2	537.0	580.3			
Middle oil					86.0	84.9		3,836.8	3,800.0	3,857.4			
Tar/heavy oil					18,146.7	17,905.7		3,799.5	3,763.0	3,799.5			
SO2		25.8		0.2						24.1			
H2S										23.7			
NaOH													
Na2SO3													
(a) MAF - moisture- and ash-free													

Table III-7, Part 7. IGT-PDU MATERIAL BALANCE (1:1 CHAR:COAL RECYCLE)
FOR STREAMS 1 THROUGH 20

Item	73 Nitrogen to Coarse Char Transport	74 Nitrogen to Char Fines Transport	75 Makeup Nitrogen	76 Nitrogen Recycle	77 Fuel Gas to Briquetting Operation	78 Clean Flue Gas to Recycle	79 Compressed Gas after Water K.O.	80 Recovered Viscous	Natural Gas to Thermal Cracker Heater	Air to Thermal Cracker Heater	Flue Gas from Thermal Cracker Heater
Pressure, psia	20	20	15	15	40	15	40	40	40	15	40
Temperature, °F	116	116	60	140	100	201	100	100	60	60	100
Total flow, lb/hr	37	11	1	48		3,692	2,751	941	68	1,167	1,235
acfh	412	120	16	739		67,395	13,573		592	15,030	6,707
scfh	506	147	16	654		54,116	34,304		1,611	15,341	16,952
Solids flow, lb/hr											
Coal (MAF) (a)											
Char (MAF)											
Ash											
Gas/liquid flows, lb/hr	37.4	10.9	1.2	48.3		3,691.5	2,750.6	940.9	67.9	1,167.4	1,235.4
N ₂	37.4	10.9	1.2	48.3		2,055.5	2,055.5			895.4	895.4
O ₂						5.3	5.3			272.0	
CO											
CO ₂											
H ₂ O											
H ₂											
CH ₄											
C ₂ H ₄											
C ₂ H ₆											
C ₃ H ₆											
C ₃ H ₈											
Light oil											
Middle oil											
Tar/heavy oil											
SO ₂											
H ₂ S											
NaOH											
Na ₂ SO ₃											
(a) MAF = moisture- and ash-free											

These balances, based on 0.5 and 2 tons of hot char recycle/ton of dry coal feed, are included for reference in Appendix A. The temperatures shown in the flow diagrams are nominal values used for equipment specification and differ in some instances from those determined for the three illustrative material balances.

Coal Feed and Drying

The coal feed and drying unit is shown on Figure III-2 and described below.

Coal Supply

The wet coal feed, which consists of -6 mesh x 0 fines from a coal cleaning plant, is received by truck and dumped into a storage pile. Coal from this pile is transferred by a front-end loader to the crushed coal bunker (T-101), which has a capacity of 16 tons. Coal is fed by a belt feeder (T-102) and a lift belt (T-103), which intermittently delivers coal to the coal feed hopper (Y-104). From this hopper, a preset charge of coal is added to the feed lock hopper (C-101). The lock hopper in turn discharges to a coal surge vessel (C-102), from which the coal is fed to the coal dryer by a screw conveyor (T-104).

The coal feed rate is set by the variable speed screw conveyor. The conveyor speed is adjusted automatically based on the lock hopper cycle time whose dump cycle is controlled by low level in the coal surge vessel. The coal feed hopper is mounted on weigh cells to permit accurate metering of coal into the unit.

Coal Drying, Preheating, and Fines Separation

The coal feed is first dried and then preheated in two entrained-flow vertical lift-pipes (C-103 and C-104). The heating medium is scrubbed flue gas reheated by heat recovery with incinerator offgas. The flue gas supplied to the coal preheater is maintained below 5 vol% oxygen content, and its temperature entering the coal preheater is limited to 700°F by recycle of cool wet gas from the dryer exit. Independent temperature and fluidization control is provided for the dryer and preheater through appropriate bypass lines.

In operation, the unit coal feed is elevated and dried in the dryer lift pipe (C-103) by hot gas exiting the coal fines cyclone (Y-103). The dried

coal is separated from the wet flue gas in the dryer cyclone (Y-101) and moved via dense-phase fluidization to the coal preheater lift pipe (C-104). A surge vessel (C-105) is provided to minimize process upsets and to maintain a seal leg of solids between the dryer cyclone and preheater.

The dried coal is elevated and preheated by a stream of hot flue gas. The coarse fraction of the preheated coal is recovered by the preheater classifier (Y-102). Flue gas and fines from the classifier are separated in the coal fines cyclone (Y-103). Coarse coal and coal fines are collected in the classifier surge vessel (C-106) and the fines surge vessel (C-107), respectively, then conveyed to the gasifier via dense-phase fluidization using recycle gas from liquids recovery.

Gasification and Heat Supply

The gasification and heat supply is shown on Figure III-3 and described below.

Mild Gasification

The preheated (500°F) coarse coal (about 80% of the total coal feed) is fed to the fluidized bed (lower) section of the mild gasification vessel (C-201). The coal fines (remaining 20%) are fed separately to the entrained bed (upper) section of the vessel. The fluidized bed is heated to the gasification temperature of 1000°F to 1200°F and fluidized by an inlet gas stream which has been heated to 2000°F to 2500°F.

The finest fraction (-60 mesh) of the coarse coal feed tends to separate from the fluidized bed and, together with the fine coal feed, is carried upward through the entrained flow section of the vessel. This section is sized to provide adequate time for gasification of the entrained fines before they separate from the hot gas and product vapors in the two exit cyclones (Y-202 and Y-203).

The net production of coarse char is removed from the fluidized bed by overflow into a short-residence-time standpipe. From there, the char is removed and cooled by intermittent operation of the char discharge cooler conveyor (T-201). This conveyor operates as needed to fill the coarse char blow case (C-202) from which the char is intermittently transferred via dense-phase fluidization to storage using a closed-loop recycled nitrogen stream.

The bulk of the char fines from the char fines primary cyclone is similarly cooled and discharged from the cyclone dipleg by the char fines cooler conveyor (T-203). This char and the small quantity of fines accumulated from the secondary cyclone are combined into the char fines blowcase (C-203), from which char fines are intermittently transferred to storage via dense-phase fluidization with recycled nitrogen.

Heat Supply

Recycle Gas Heating. Recycle gas from the liquids recovery section provides a combustible fuel for heat input as well as a gas flow to heat and fluidize the gasifier. Hot recycle gas (2000°F to 2500°F) is produced by (1) preheating the gas by heat exchange with incinerator offgas, (2) boosting its temperature by combusting a portion of the recycle gas with air in the booster heater (F-201), and (3) combining the combustion products with the remaining (uncombusted) recycle gas. Partial combustion of the entire recycle gas stream is less desirable since oxygen-deficient combustion is likely to produce unwanted products (e.g., aldehydes).

Char Heating. To reduce heating gas requirements for the mild gasification, provision is made to supply a portion of the gasifier heat input by hot char recycle. Char is withdrawn from the fluidized bed by a screw conveyor (T-202) and fed at a controlled rate to a char heater lift pipe (F-202). The char is elevated and heated by partial combustion (gasification) with air. The heated char at an exit temperature of 1800°F to 2000°F is separated from the gas by the char heater cyclone (Y-201) and returned to the gasifier. The gas leaving the char heat cyclone is combustible (low-Btu gas) and contains char fines. A portion of the heat from this hot flue gas is recovered in the air preheater (E-201), which serves to preheat combustion air for the char heater and gasifier booster heater.

Thermal Cracking

Thermal cracking has been proposed as a means of improving the properties of recovered tar products produced by mild gasification. The design includes a thermal cracker (Y-204) capable of operating at temperatures up to 1800°F. Flue gas exiting the secondary cyclone is thermally cracked before being sent to liquids recovery. An appropriate bypass line permits direct flow from the secondary cyclone to liquids recovery without thermal cracking.

Optional Hot Gas Filtering

The proposed unit has been designed to accommodate small amounts of char fines to be entrained into the liquids recovery section. In a large-scale commercial operation, hot gas filtering may prove to be an economical means of fines removal. Filters for this type of application are now being developed under sponsorship of the U.S. Department of Energy's Morgantown Energy Technology Center. The PDU may provide a means of evaluating this developing technology by filtering a slip stream of hot gas.

Liquids Recovery System

The liquids recovery system is shown in Figure III-4 and described below. The liquids recovery train condenses three boiling ranges of products by cooling the gas stream to successively lower temperatures.

Tar Recovery

The first high-temperature tar condensation is carried out by contacting the gas stream with a cooled tar quench stream. The temperature is controlled to the maximum that will yield a fluid condensate of heavy tar and pitch. The initial condensation is carried out in a wetted wall quench condenser (C-304), selected to minimize fouling which might be produced at the point of initial condensation of the highest boiling point tars (aggravated by the possible presence of char fines). A wall scraper may also be needed at the hot-cold interface at the inlet to the quench. The recycled tar is cooled in the tar quench air cooler (E-301).

The tar condensate and vapors are separated in the tar separator (C-301). The tar quench is recycled by means of the tar quench recycle pump (P-301). The recycled tar is filtered by the quench bypass filter (Y-302) to prevent accumulation of entrained char fines in the recycled tar quench stream. A continuous cleaning edge-type filter is proposed for this application with intermittent blowdown for sludge removal. A sludge pump (P-303) provides a means for disposal of the sludge by recycling the accumulated material back to the gasifier. Tar product filters (Y-401 A/B) are included for trace solids removal from the net condensed tar.

Middle Oil Recovery

The second-stage condensation is carried out at a temperature just above the temperature at which the water condenses. This is done in order to avoid the formation of difficult-to-separate water in oil emulsion and results in recovery of a dry middle oil fraction. The vapors from the tar separator are cooled by the middle oil quench air cooler (E-302), and the condensed liquids are separated in the middle oil separator (C-302). The middle oil quench pump (P-302) causes oil to recirculate through the air cooler to prevent the accumulation of condensed tars on heat transfer surfaces.

Light Oil Recovery

The vapors and gases from the second stage are compressed slightly to furnish the necessary pressure for gas recycle and then cooled with cooling water (E-303). Condensed light oil and water are recovered and separated in the light oil separator (C-303). Because of the large flow of recycle gas, hydrocarbons lighter than benzene are not recovered in substantial quantity. Yields of uncondensed products are determined through gas analysis and flow measurements. The recovered light oil and sour water are discharged to their respective storage tanks.

Emission Control and Char Handling

The emission control and char handling system is shown in Figure III-5 and described below.

Emission Control

The incinerator (F-401) provides a means for total oxidation of all waste combustible gases and liquids, including their contained sulfur species. In addition, the incinerator is an integral part of the unit heat balance. Surplus recycle gas from the light oil condensation, together with the vent gases from the coal dryer and the char heater, is burned to convert the sulfur compounds (largely H_2S) to SO_2 . Sour water from storage can also be injected into the incinerator to oxidize dissolved ammonia, phenols, and sulfur species. The hot incinerator off gases are contacted in a convective heat transfer zone to reheat recycle gas (E-401) to the gasifier and to reheat clean flue gas (E-404) for heat supply for coal drying and preheating.

After heat exchange, the incinerator flue gas is partially cooled by water injection and then contacted with caustic and water in the scrubber (C-401). The spent caustic is discharged as a concentrated stream of sodium sulfite solution and transported offsite for disposal (or possible use). A pump (P-401) serves to recirculate sodium sulfite solution within the lower section of the column and to transfer the net product to storage. Before being sent to storage, the sodium sulfite solution is cooled with water (E-402).

The scrubber and incinerator operate at slightly below atmospheric pressure, as maintained by the induced draft blower (K-101). The induced-draft blower discharges gas to the stack with a portion of the gas recycled for heat integration. The recycled flue gas is compressed (K-403) above the operating pressure of the coal preheater and water-cooled (E-405) to condense water. The condensed water is removed in the water knockout drum (C-402). The flue gas is then reheated in a convective coil (E-404) located in the incinerator discharge.

To prevent overheating of the furnace tubes, a minimum flow of flue gas is maintained through E-404. Excess preheated flue gas is spilled to the stack to reheat and minimize the amount of water from the vent gases. To protect the heat exchange surface from overheating, a minimum flow of recycle gas is maintained through E-404. The excess recycle gas is spilled back to the liquids recovery section and is processed, along with the gasifier flue gas. This flow is normally zero.

Char Handling

The cooled coarse and fine char products from the gasification are pneumatically conveyed to their respective storage hoppers (D-401 and D-402) using a closed-loop nitrogen recycle system. Fines are removed from the recycled nitrogen by gas filters (Y-401 and Y-402). Recycled nitrogen is water-cooled (E-403) and recirculated by the nitrogen recycle blower (K-402). To maintain atmospheric pressure, makeup nitrogen is added to the storage hoppers. The coarse and fine char products can be discharged from their respective hoppers into containers (T-401 and T-402) for offsite use or disposal. Alternatively, the char products can be accumulated for a 24-hour period for feed to the briquetting operation.

Liquids Storage and Handling

The liquids storage and handling system is shown in Figure III-6 and described below.

Caustic is transferred from truck delivery to the caustic storage tank (D-501) and pumped to the vent gas scrubber by the caustic feed pump (P-501). Spent caustic from the scrubber is returned to the spent caustic storage tank (D-502). From there, it is fed to drum or truck loading by the spent caustic pump (P-502).

Sour water (condensate containing phenol and ammonium sulfide) from liquids recovery is stored in the condensate storage tank (D-503). It may then be pumped to the incinerator by the sour water transfer pump (P-503) if the quantity is small or to drum or tank truck loading for offsite disposal.

There are two storage tanks for each of the three primary hydrocarbon liquids. Each product has an associated run tank equipped with load cells for recovery and measurement of products produced during a 24-hour test period (D-507, D-508, and D-509). In addition, long-term storage (D-504, D-505, and D-506) is provided to accommodate the products produced during the first 6 months of operation. The long-term storage was considered necessary to permit adequate analysis of the hydrocarbon products and to accumulate them for bulk delivery to a potential user.

Material Balances

Table III-7 presents a material balance for the mild gasification unit based on a 1:1 char recycle to coal feed and the product yields and compositions listed in Section 2.1.3. The stream numbers in Table III-7 are keyed to the process flow diagrams in Figures III-2 through III-6.

As discussed above, the fraction of the gasifier heat supplied by char recycle affects the product gas composition. For the base case (1:1 char recycle to coal feed), approximately half of the gasifier energy is supplied by the recycled char. Appendix A presents material balances for 0.5:1 and 2:1 char recycle to coal feed ratios. The 2:1 char recycle to coal feed ratio is illustrative of the extreme, where all the gasifier heat is supplied by char recycle and therefore there is no nitrogen dilution of the product gases.

Energy Balances

The thermal efficiency of the mild gasification process was estimated at 80%, based on the higher heating value (HHV) of the feeds and products. This high thermal efficiency is attainable through heat recovery from the incinerator flue gas. The details of the energy balance are summarized in Table III-8.

Table III-8. OVERALL ENERGY BALANCE MILD GASIFICATION^a

<u>Item</u>	<u>Flow Rate, lb/hr</u>	<u>HHV,^b Btu/lb</u>	<u>HHV, MM Btu/hr</u>
Input			
Coal (MF) ^c	2000	11,520	23.0
Methane	88	23,860	<u>2.1</u>
Total Input			25.1
Output			
Char	1207	10,920	13.2
Light Oil	28	20,000	0.6
Middle Oil	78	20,000	1.6
Heavy Oil	242	20,000	<u>4.8</u>
Total Output			20.2
Net Efficiency			80.5%

^a Excludes heat losses compensated for by additional methane consumption.

^b HHV = higher heating value.

^c MF = moisture-free.

Heat recovered from the incinerator flue gas is used to supply hot gases for drying coal and for reducing the heat duty of the gasifier char and booster heaters. Thermal cracking of the gasifier product gas imposes a 5% penalty on thermal efficiency. A portion of this energy can be recovered through proper heat integration of the thermal cracker with the gasifier; however, such an integration scheme would reduce the operating flexibility for evaluating the benefits of thermal cracking and has not been incorporated in the PDU.

Only about 6% of the total energy input to the gasification unit is in the form of natural gas (methane). About 80% of the natural gas is consumed by the thermal cracker; the remainder is consumed in the incinerator. If desired, the natural gas demand for the gasification process can be eliminated by substituting product oils (light oil and middle oil) for natural gas.

At this stage of the process design, no allowance has been made for heat losses from the equipment to the atmosphere. During detailed design, equipment and pipe insulation will be specified so as to minimize heat losses. An estimate of the expected heat losses will then be made and the methane consumption adjusted accordingly.

Utilities Requirements

In addition to the gasification process equipment, the process development unit requires the following process support and utilities facilities.

- Air Supply. Air for the booster heater and char heater is provided by the process air compressor (K-201)
- Natural Gas. Natural gas is required at the site to support the combustion in the incinerator and thermal cracker. For startup, natural gas is used to pressurize the gasifier and as makeup to the recycle gas. The gas is required at a pressure of 40 psia.
- Cooling Water. The PDU mild gasification facility requires cooling water for the cooler-conveyors and for the light oil condenser. The mix of water and air cooling will be defined during the final design and construction.
- Plant Air. Dried instrument and service air is supplied from the existing systems available at the PDU site or from new facilities.
- Steam. There is no process steam in this preliminary design. If steam is needed for gasifier injection facilities will be added during the detailed design.
- Inert Gas Supply. Nitrogen for startup and shutdown purging is supplied from high-pressure cylinder trucks or from a rented liquid nitrogen system. Nitrogen is also used for pneumatic transport of char from the char lock hoppers to storage in a closed-loop system.

The preliminary estimates for utilities requirements for the mild gasification process are as follows:

• Cooling water	260 gpm*
• Electricity	150 kW, 3,600 kWh/24 hr-day
• Steam	0
• Natural gas	
Normal	35 scfm
Startup	80 scfm
• Plant air	20 scfm
• Nitrogen	
Normal	7.5 scfm
Startup	2400 scf

Normal Operation and Controls

The general operation of the PDU is described previously in the Process Description section. The normal operating adjustments and functions of the major gas distribution and heat balance controls are described below. An overall controls diagram is presented in Figure III-7.

Char Recycle Control

A portion of the heat input to the gasifier is derived by withdrawing char from the fluidized bed, heating it by partial combustion, separating the resulting gases, and returning the heated char to the bed. This cycle is controlled as follows:

- The char is withdrawn from the bed at a manually set flow rate (nominally some fraction of the coal feed rate).
- The withdrawn char is hot enough to sustain partial combustion as it is contacted with a controlled stream of air (which also serves to lift the char to the char cyclone for separation of the flue gas from the hot char).
- A controller monitors the temperature of hot char being returned to the gasifier and modulates the amount of air required for combustion in the char heater to achieve the desired char temperature.

* A higher temperature air-cooled, closed-loop cooling water system will be acceptable.

Gasifier Fluidized Bed Temperature Control

Char recycle supplies only a portion of the gasifier heat demand. The remaining portion of the heat demand is supplied by combusting a portion of the recycle gas used for fluidization. A controller monitors the temperature of the fluidized bed and simultaneously adjusts the recycle gas and airflow rates to the booster heater.

Gasifier Entrained Bed Temperature Control

The temperature of the entrained bed is regulated by the amount of coal fines fed to the entrained bed. Coal fines introduced to the entrained bed quench the exiting gas. The split of coal fines between the fluidized bed and the entrained bed affects the temperature of the exiting gases. The cycle is as follows:

- A differential temperature controller monitors the temperature difference between the fluidized bed and the exit temperature of the entrained bed.
- The controller acts to regulate the split of coal fines between the fluidized bed and the entrained bed to reach a desired differential temperature set point.
- Fines in excess of the controlled flow of fines to the entrained bed are combined with the coarse char feed to the fluidized bed.

The degree of fluidization depends on the amount of total hot gases introduced in the bottom of the gasifier. A flow controller on the recycle gas to the gasifier is used to set the total flow of recycle gas regardless of flow going to the booster heater. Combustion of recycle gas leads to dilution with air and an increase in gas flow to the gasifier. The heat demand of the gasifier varies the amount of recycle gas combusted in the booster heater (as controlled by the fluidized bed temperature). Fluidization in the gasifier therefore varies with temperature control. Control of fluidization is as follows:

- Differential pressure measurements on the fluidized bed indicate the degree of fluidization within the gasifier.
- The flow of recycle gas is set to achieve the desired degree of fluidization.
- Heat demand in the gasifier causes a fluctuation in the amount of fluidization gas. At steady state, this fluctuation should be small.

- Differential pressure measurements are checked routinely, and the appropriate change in recycle gas flow rate will be set on the flow controller.

Gasifier Pressure Control

The pressure of the gasifier cannot exceed the pressure of the recycle gas that is used for fluidization and injection of coal and char into the gasifier. The recycle gas pressure is maintained by back pressure control. Excess recycle gas is vented to the incinerator, and any shortfall of recycle gas pressure is made up by natural gas.

The pressure in the char heater is regulated by venting the char heater offgas on back pressure control to the incinerator after the offgas has been reduced in temperature by heat exchange with incoming combustion air.

Coal Drying and Preheating

The pressure in the coal drying and preheating section is regulated by back pressure control with excess gas being vented to the incinerator. The temperature of the gas exiting the coal preheater is monitored and used to control the amount of hot flue gas introduced to the coal preheater. The setting for the total flow of gases to the preheater is independent of preheater temperature. Dryer recycle gas is regulated to achieve the desired flow rate to the preheater.

Gas at a fixed temperature (that exiting the coal preheater) is sent to the coal dryer. The flow of gas to the coal dryer is independent of the flow rate in the preheater. Excess gas from the preheater is vented to the incinerator and any shortfall of dryer gas is made up by recycling dryer vent gas.

Emission System Control

The incinerator is used to convert all sulfur containing species to SO_2 . Heat is recovered from the hot incinerator flue gases for preheating and drying coal and for heating recycle gas to the incinerator. The partially cooled incinerator flue gas is quenched and scrubbed with caustic to remove SO_2 . A portion of the scrubbed flue gas serves as the heat carrier to the coal preheating and drying section. Systems controls include the following:

- The temperature and the oxygen content in the incinerator are maintained at 1400°F and 3%, respectively, to ensure complete oxidation of sulfur-

containing species. The incinerator temperature controller regulates the amount of natural gas necessary to achieve the desired temperature. An oxygen analyzer in the flue gas stream regulates the amount of air introduced to the incinerator.

- The heat recovery tubes in the incinerator are protected from overheating by ensuring that a minimum flow of gas is maintained through the tubes. A minimum flow of scrubbed flue gas that is recycled for heat recovery is maintained by venting excess heated gas to the stack. Likewise, a minimum flow of recycle gas for heat recovery is maintained by venting excess heated gas to the liquids recovery section for heat removal. During normal operation, this flow is zero.
- The temperature of the incinerator flue gas going to the scrubber is monitored and regulated by water injection.
- The concentration of SO_2 in the effluent from the caustic scrubber is controlled by the addition rate of caustic to the absorption section of the scrubber.
- The concentration of sodium sulfite leaving the scrubber is controlled by the flow of wash water added to the top of the scrubber.

Safety

The potential safety hazards for the PDU are typical for gasification and hydrocarbon handling systems. Operating procedures and controls are designed to ensure that explosive concentrations of air and gases do not develop within the process lines and storage vessels. Nitrogen is used for purging oxygen from the system and for blanketing storage vessels. After purging with nitrogen, natural gas is used to pressurize the gasifier and the liquid recovery system. Low-oxygen-content flue gas is employed for coal and char transport and for blanketing.

Gasifier product gas and recycle gas contain both H_2S and CO . Care must be exercised to prevent exposure of operating personnel to these toxic gases. Proper ventilation is required, especially near rotating equipment, which is prone to leakage around seals. Area sensors for hydrocarbons, CO , and H_2S should be installed in key areas around the unit.

High-temperature streams are handled in the unit, and process lines need to be properly insulated for personnel protection.

All liquid product vessels are blanketed with nitrogen and vented to the incinerator. All liquid products, most notably the tar product, contain aromatic compounds. Proper personal safety equipment should be used when

handling the liquids. The PDU has been designed to minimize exposure of operating personnel to process liquids.

Environmental Controls

The PDU has been designed to meet tight emissions guidelines. All process gases are incinerated and scrubbed before being released to the atmosphere. Incineration is the most effective means of eliminating potentially hazardous organic compounds. Hydrocarbons are oxidized to CO_2 and H_2O , and all sulfur species are converted to SO_2 . Caustic scrubbing of the incinerated gases permits removal of SO_2 down to low levels.

All liquid products are stored in closed vessels, with vent gases being sent to the incinerator. The unit provides for onsite disposal of sour water by injection into the incinerator. If necessary, middle oil and light oil products can also be disposed of in the incinerator and used to reduce or eliminate the need for natural gas. Final cleanout of the liquid containing equipment prior to decommissioning will involve thorough washing with light oil to remove tars. Washings will be incinerated and the equipment purged with heated nitrogen followed by air to remove all trace volatiles.

Startup Procedures

The startup of the system from cold is conducted as follows:

- The coal dryer, preheater, gasifier, and the gas condenser train systems are purged with nitrogen to reduce the oxygen content below 1 percent volume (at ambient pressure).
- The gasifier and liquid recovery systems are brought up to operating pressure with natural gas.
- Oil circulation and cooling then begin in the liquid recovery train.
- The induced gas blower is started to lower the pressure in the incinerator below atmospheric pressure.
- The recycle gas compressor and the flue gas recycle compressor are started to establish flow through the incinerator heat recovery section.
- Gas firing of the incinerator is initiated to generate heat for coal drying/preheating and gasifier preheat.
- Gas scrubbing operations are initiated.

- Gas recycle for the gasifier is established at the rate required to fluidize the fluidized bed.
- Gas recycle is established in the dryer/preheater loop at the rate needed for the required gas lifts.
- Hot flue gas is introduced to the coal preheater/dryer to establish a temperature of 500°F at the coal preheater exit.
- A noncaking coke or char, sized to that of the selected feed coal, is fed to the dryer/preheater to establish a normal char level in the gasifier.
- The char recycle loop is started and circulated using recycle gas for gas lift.
- The recycle booster heater is fired to bring the gasifier to operating temperature. Natural gas may be introduced to increase the heating value of the recycle gas.
- Coke feed is continued, and normal char product offtake and system temperatures and pressures are established.
- A 1:1 mixture of coal and coke is introduced to the gasifier through the dryer/preheat system. The coke is gradually replaced with coal (the process typically taking 1 hour) until the unit is operating on coal feed only.
- The coal feed rate is gradually increased to establish the desired flow rate.
- As combustible pyrolysis gas enters the recycle and char heater, the heating value of the recycle gas increases and natural gas addition to the recycle gas is reduced or eliminated.
- As coal-derived liquids displace any startup liquids in the condensing train, normal product offtake is begun.

The above sequence completes the normal startup of the gasification process.

Standby

Once operation of the gasification system has been established, feed may be interrupted and the unit held in hot standby to facilitate a restart. This is accomplished in the following way:

- The screw feeder transferring coal to the dryer is halted, and fluidization of preheater coarse and fine coal to the gasifier is stopped. Coal is retained in the dryer and preheater surge vessels.
- The gasifier char discharge cooler/conveyor is shut down.

- The recycle gas flow to the gasifier is reduced to minimize char entrainment from the bed.
- Natural gas is automatically introduced to the inlet of the recycle gas booster burner so that combustion may be continued as needed to retain the gasifier bed temperature.
- The temperature control setting on the outlet gas from the coal preheater is reduced to that of the normal dryer outlet temperature.
- Tar and middle oil circulation is stopped to reduce its evaporative carryover. (Gas cooling is maintained by the middle oil and light oil quench coolers.)
- Incinerator firing is maintained at a low level to accommodate any minor emissions.

The gasification system can be held in this mode for an extended period and, since the components are maintained near operating temperatures, it can be restarted quickly with introduction of coal feed.

Shutdown

Shutdown, which may be required for maintenance access, follows the procedure for standby, except that:

- The char contents of the gasifier are discharged through the bottom dump valve of the gasifier.
- The system is allowed to cool, and the gaseous contents are purged with nitrogen through the incinerator.
- Coal contained in the seal legs of the dryer and in the preheated coarse and fine coal cyclones is discharged from the bottom dump valve on the dryer and preheater lift pipes.
- Liquid inventories are pumped to storage.
- When free of hydrocarbon, the systems are purged with air prior to being cleared for entry.

Approach to Steady-State Following Startup and/or Feed Change

Steady-state operating conditions in the gasifier are approached as the fluidized bed contents are replaced with equilibrium char representative of the coal feedstock. Based on IGT experience with its 100 lb/hr PRU, six to seven bed turnovers are necessary to replace 99+% of the initial char inventory with char that is characteristic of the new coal feed. This number of bed turnovers corresponds to a time period of about 9 hours under typical PDU operating conditions.

The approach to steady state in the liquid product recovery section involves the replacement of liquid inventories in product receivers and recirculation lines. Liquid holdup in the tar/heavy oil quench system accounts for most of the liquid inventory and is therefore the controlling factor in the approach to steady state of the liquid product recovery section. Steady-state concentrations are reached in the tar/heavy oil quench system after 8 hours of flushing by new products.

When coal feeds are switched, steady-state conditions for the combined system (gasifier and product recovery section) are controlled principally by the time for the gasifier to attain equilibrium. The PDU will attain equilibrium within 10 hours (eight to nine gasifier volumes) under typical conditions after the new coal feedstock is introduced.

Special Equipment Designs

Coal Dryer and Preheater

The coal dryer and preheater are two 8 in. dia. lift pipes, 60 feet high. Coal is fed to the dryer lift pipe at its base by a compacting screw feeder. This compacted feed, together with the static inventory of coal in the screw feeder and surge vessel, provides a gas seal. The hot gas introduced at the bottom of the lift pipe entrains the coal and heats it. The gas and coal are then separated in a cyclone. Dried coal accumulated in the coal dryer surge vessel is transported to the preheater lift pipe via dense phase fluidization. The inventory in the dryer surge vessel provides a gas seal between the dryer cyclone and the preheater. The key design parameters are the residence time of the coal in the lift pipe and the temperature and the velocity of the hot gas.

Gasifier

Figure III-8 shows the proposed mild gasifier. This vessel is configured according to the design parameters described in the section on system capacity. The inventory in the coal feed surge vessels and the char withdrawal screw conveyors (char recycle and char removal) provides the required gas seal for the gasifier.

Hot Gas/Char Fines Separation

The hot gas and char fines leaving the gasifier pass through two cyclones before entering the thermal cracker. The cyclones separate most of the char

Figure III-8. MILD GASIFIER VESSEL -- 24 tpd PDU

from the hot gas. Very fine char passes through the cyclones and the thermal cracker into the liquids recovery system.

Char Heater

The char heater is a 12 in. dia., 60-foot-high ceramic-lined lift pipe in which the air for partial combustion serves as the fluidizing medium. Warm char is injected into the lift pipe/burner by a compacting screw feeder. The heated char is separated from the partial combustion gases by a refractory-lined cyclone and returned through a seal leg to the gasifier.

Thermal Cracker

The thermal cracker consists of a gas-fired indirect heater with a residence time loop. The residence time and temperature are the key design parameters for the thermal cracker. A removable refractory-lined residence time loop allows the residence time of gases to be varied before the gases are quenched in the liquids recovery section.

Tar Recovery

The tar recovery system permits the gas to be cooled quickly while avoiding plugging due to buildup of condensed tar on cool surfaces. In addition, the tar quench system must handle char fines entrained through gasifier cyclones. Tar is recovered via direct quench of the flue gas with recirculated product tar. To prevent plugging of the inlet gas nozzle, the high inlet gas velocity to the tar quench condenser is maintained. Gas is introduced tangentially to maintain a high velocity at the walls. Recirculated tar product is sprayed into the gas, and surfaces are maintained wetted to wash away condensed solids. Perforated plates provide gas-liquid mixing and a wetted surface area for condensation.

Fines entrained into the quench condenser end up as suspended solids in the tar product. A fines bypass filter removes the bulk of the fines from the recirculated tar. Product filters provide a means for removal of residual fines from the tar product.

An air-cooled exchanger has been proposed for cooling the recycle tar. During the final design, this cooler will be reexamined with a view to reducing the tar inventory. The intent is to accelerate the approach to steady state of the tar recovery system.

FORM COKE PROCESS CONCEPTUAL DESIGN

Design Basis

The overall block diagram for the form coke process is illustrated in Figure III-9. The feed to the form coke process is char from the mild gasification process and dried coal. The feed mixture is first ground and heated to 1000°F. Heating produces a plastic mass which is thoroughly mixed to achieve uniformity and subsequently formed into briquettes and calcined at temperatures up to 1800°F. Coal volatiles driven off in the calciner and the mixer/heater are incinerated and sent to the scrubber in the mild gasification process. The calcined briquettes are cooled and screened to remove fines. Lignosulfonate solution may be applied to the form coke product to increase abrasion resistance and to reduce water adsorption.

System Capacity

The form coke process has been designed to accept 28 tpd of mixed char and coal feed. The capacity of the process was selected to meet the following criteria:

- Adequate storage and capacity to process char produced by the mild gasification process
- Storage capacity and processing capacity to produce form coke from a 1:1 mixture of coal to char

Design Operating Parameters

The form coke process is designed to operate independently of the coal drying and gasification processes. This independence of operation is one of the design operating parameters that have been selected by IGT for the test operation. The other parameters, along with their maximum, base case, and minimum values, are listed in Table III-9.

Yields and Compositions

A yield structure for the form coke process was developed on the basis of the volatiles content of the coal feed, gasifier char, and the form coke product. The char volatiles content depends on the gasifier operating conditions. The compositions shown in Table III-10 were assumed for the base case design.

Figure III-9. FORM COKE PRODUCTION BLOCK DIAGRAM

Table III-9. OPERATING PARAMETER RANGES FOR THE FORM COKE PROCESS

<u>Parameter</u>	<u>Maximum</u>	<u>Base Case</u>	<u>Minimum</u>
Calciner Operating Pressure, psia	20	15	12
Char/Coal Feed Ratio, lb/lb	1	1	0.5
Total Feed, lb/hr	2400	2400	
Feed Size, Mesh		6 X 0	
Ground Feed Size, Mesh			
Residence Time, min			
Mixer/heater		TBD	
Calciner		120	
Temperature, °F			
Mixer/heater	1000	1000	N/A
Calciner	2000	1800	1200

Table III-10. COMPOSITION IN WEIGHT PERCENT OF THE COAL FEED, GASIFIER CHAR, AND THE FORM COKE PRODUCT

<u>Item</u>	<u>Moisture</u>	<u>Volatile Matter</u>	<u>Carbon</u>	<u>Ash</u>
Coal Feed (Illinois No. 6)	3.32	35.23	47.34	14.11
Gasifier Char (1:1 char recycle)	0	14.94	60.93	24.13
Form Coke Product	0	1	By material balance	By material balance

Process Description

Figure III-10 shows the proposed process flow for form coke production. The base case material balance in Table III-11 is keyed to the flow diagram.

Feed Preparation

The briquetting operation has been designed to run independently of the gasifier; however, the gasification section emissions control and char handling system must be operated to supply necessary heat and to provide adequate environmental control. Feeds to the briquetting operation consist of coarse and fine char from gasification, along with dried coal. The char feeds are accumulated batchwise from operation of the gasifier. Dry coal feed for form coke production is obtained by operating the coal feed and drying section of the PDU and storing the dried coal in the dry coal storage vessel (D-601). The PDU could permit simultaneous operation of both the briquetting and mild gasification operations with slight modification. The modification would require additional coal drying capacity or purchase of predried coal for form coke production.

The feed grinder (Y-602) accepts coarse char, char fines, and dry coal to prepare a finely ground coal/char mixture. The feeds are metered into the grinder by rotary feeders, and flow rates are determined from weight loss of the storage vessels. An elevating screw conveyor (Y-603) transports the ground feed to the mixer/heater (Y-604).

The mixer/heater uses a gas-fired burner to indirectly heat the feed to 1000°F while providing mixing to produce a uniform composition. A portion of the heat supplied in the mixer/heater is from direct contact of hot calciner offgases, which are passed through the mixing chamber. Devolatilization of the coal feed takes place in the mixer/heater, and the coal volatiles are vented, along with the calciner offgases, to the incinerator (F-602).

The heated coal/char mixture flows by gravity into the hot roll briquetter (Y-605), which compresses the mixture into briquettes at 1,000°F. The hot briquettes drop directly from the briquetter into the vertical shaft calciner (C-601).

The briquettes travel downward as a moving bed through two zones in the vertical shaft calciner. In the top zone, the briquettes are heated to 1800°F with a countercurrent flow of flue gas at 2000°F; in the bottom zone, heat is

Figure III-10. PROCESS FLOW DIAGRAM FORM COKE PRODUCTION

Table 11, Part 1. IGT -- FORM COKE PROCESS MATERIAL BALANCE FOR
STREAMS 1 THROUGH 26

Item	1 Char Fines from Storage	2 Coarse Char from Storage	3 Dried Coal from Storage	4 Coal/Char to Mixer/Heater	5 Mixer/Heater Offgases to Incinerator	6 Feed to Briquette	7 Hot Gas to Calciner	8 Cool Gas to Calciner	9 Calciner Offgases to Mixer/Heater
Pressure, psia	15	15	15	15	14	14	17	20	14
Temperature, °F	100	100	100	100	1,000	1,000	2,000	100	1,100
Total flow, lb/hr	272	935	1,207	2,414	2,409	1,988	597	1,225	1,983
adfh							33,285	12,575	76,658
scfh							7,974	15,569	23,849
Solids flow, lb/hr	271.6	935.4	1,207.0	2,414.0	0.0	1,987.7	0.0	0.0	0.0
Coal (MAF) (a)			1,030.8	1,030.8		1,520.3			
Char (MAF)	206.0	709.7		915.8		467.4			
Ash	65.5	225.7	176.2	467.4					
Gas/liquid flows, lb/hr	0.0	0.0	0.0	0.0	2,409.4	0.0	596.8	1,225.0	1,983.2
N2					1,328.5		436.9	891.6	1,328.5
O2					5.5		3.2	2.3	5.5
CO2					383.7		102.7	281.0	383.7
H2O					104.1		54.1	50.0	104.1
CH4							0.0	0.0	0.0
Coal volatiles					587.7		0.0	0.0	161.4
Lignosulfonate solution									
SO2									

(a) MAF = moisture- and ash-free.

Table 11, Part 2. IGT -- FORM COKE PROCESS MATERIAL BALANCE FOR
STREAMS 1 THROUGH 26

Item	10	11	12	13	14	15	16	17	18
	Calcined Briquettes	Product Briquettes	Lignosulfonate Solution	Hot Flue Gas from E-404	Flue Gas from K-401	Natural Gas to Heater	Air to Heater	Heater Flue Gas	Flue Gas from E-601
Pressure, psia	15	15	25	40	15	40	15	17	20
Temperature, °F	200	195	60	1,200	200	60	60	3,500	100
Total flow, lb/hr	1,826	1,704	60	167	1,600	23	407	430	1,600
acfh				2,494	29,784	204	5,345	39,580	18,953
scfh				2,083	23,466	545	5,345	5,890	23,466
Solids flow, lb/hr	1,826.3	1,643.7	0.0	0.0	0.0	0.0	0.0	0.0	0.0
Coal (MAF) (a)									
Char (MAF)	1,358.9	1,223.0							
Ash	467.4	420.7							
Gas/liquid flows, lb/hr	0.0	60.3	60.3	167.0	1,600.0	23.0	406.7	429.8	1,600.0
N2				124.9	891.6		311.9	311.9	891.6
O2				0.3	2.3		94.8	2.8	2.3
CO2				39.4	281.0			63.3	281.0
H2O				2.3	425.0			51.8	425.0
CH4								0.0	
Coal volatiles									
Lignosulfonate solution		60.3	60.3						
SO2									

(a) MAF = moisture- and ash-free.

Table 11, Part 3. IGT -- FORM COKE PROCESS MATERIAL BALANCE FOR
STREAMS 1 THROUGH 26

Item	19	20	21	22	23	24	25	26
	Recycled Water	Briquette Fines	Air to Mixer/Heater Burner	Natural Gas to Mixer/Heater Burner	Burner Vent Gas to Stack	Air to Incinerator	Natural Gas to Incinerator	Vent Gas to Scrubber
Pressure, psia	15	15	15	40	15	15	40	15
Temperature, °F	100	195	60	60	1,200	60	60	1,400
Total flow, lb/hr	375	183	810	46	856	6,191	0	8,603
acfh	8,504		10,643	407	37,438	81,356		407,502
scfh	7,897		10,643	1,085	11,728	81,356		113,925
Solids flow, lb/hr	0.0	182.6	0.0	0.0	0.0	0.0	0.0	0.0
Coal (MAF) (a)		135.9						
Char (MAF)		46.7						
Ash								
Gas/liquid flows, lb/hr	375.0	0.0	809.9	45.8	855.7	6,190.8	0.0	8,602.6
N2					621.2	4,748.3		6,122.6
O2			621.2		5.5	1,442.4		43.3
CO2			188.7		126.0			1,490.7
H2O					103.1			799.3
CH4							0.0	
Coal volatiles	375.0			45.8				
Lignosulfonate solution								
SO2								146.7

(a) MAF = moisture- and ash-free.

recovered from the briquettes with countercurrent flow of flue gas at 100°F. Briquettes exit the calciner at 200°F through a lock hopper (C-602). The hot flue gas for calcining the briquettes is obtained by boosting the temperature of recycled flue gas obtained from the incinerator (F-401) in the emissions control and char handling system. The flue gas temperature is boosted from 1200°F to 2000°F by introducing heat from a direct-fired gas heater (F-601). Natural gas is burned in the gas heater, and an air blower (K-601) supplies the necessary air for combustion. Clean flue gas from the scrubber is cooled to 100°F with cooling water (E-601), and condensed water is separated in a water knockout drum (C-603). The cool gas blower (K-602) causes flue gas to circulate from the scrubber to the calciner.

Briquettes leaving the lock hopper are conveyed to a transport container (T-603) by means of a vibrating screen feeder (Y-606), which separates the form coke product from fines. To increase the briquettes' resistance to abrasion and water adsorption, a lignosulfonate solution may be sprayed on the form coke product exiting the screen. A pump (P-601) furnishes the required pressure to move the lignosulfonate solution from storage (D-602) through the spray nozzle.

Material Balance

Table III-11 presents a material balance for the form coke production process for the base case design. The stream numbers in Table III-11 are keyed to the process flow diagram in Figure III-10. The base case design assumes form coke production from a 1:1 coal/char feed mixture.

Energy Balance

An overall energy balance was performed for the form coke process, assuming the higher heating value of the feeds and products. The net thermal efficiency was estimated to be 66%. The details of the energy balance are summarized in Table III-12.

The thermal efficiency of the form coke process is considerably lower than that of the gasification process (66% versus 81% for gasification). Hot flue gas leaving the incinerator accounts for over 20% of the energy input. Incineration was chosen for disposal of the coal volatiles to permit operating flexibility and to reduce capital expenses. Increased thermal efficiency can be attained through heat recovery from the incinerator effluent

Table III-12. OVERALL ENERGY BALANCE FORM COKE PRODUCTION^a

<u>Item</u>	<u>Flow Rate, lb/hr</u>	<u>HHV,^b Btu/lb</u>	<u>HHV, MM Btu/hr</u>
Input			
Coal (MF) ^c	1207	11,520	13.9
Char (MF)	1207	10,920	13.2
Methane	69	23,860	<u>1.6</u>
Total Input			28.7
Output			
Briquettes	1644	10,400	17.1
Briquette Fines	183	10,400	<u>1.9</u>
Total Output			19.0
Net Efficiency (HHV)			66.2%

^a Excludes heat losses compensated for by additional methane consumption.

^b HHV = Higher heating values.

^c MF = moisture-free.

in a manner similar to that employed for the gasification process. The heating value of the coal volatiles generated by the process is in excess of that for the natural gas requirement for the process. A commercial plant would benefit by recovery of heat from the incineration of the coal volatiles or through use of the coal volatiles in fired equipment (i.e., the gas heater and screw mixer/heater).

Utilities Requirements

In addition to the process equipment described above, the form coke process requires the following support and utilities facilities:

- Air Supply. Air for the gas heater is provided by the process air blower (K-601).
- Natural Gas. Natural gas is required for indirect heating of the mixer/heater and direct heating for the calciner gas heater. At steady state, the heating value of the coal volatiles evolved by the process is

adequate to supply the necessary heat for the incinerator. For startup, natural gas is used in the incinerator. The gas is required at a pressure of 25 psia.

- Cooling Water. The form coke process requires cooling water only for the gas cooler.
- Plant Air. Dried instrument and service air is supplied from the existing systems available at the PDU site or from new facilities.
- Steam. There is no process steam in this preliminary design.
- Inert Gas Supply. Nitrogen for startup and shutdown purging is supplied from high-pressure cylinder trucks or from a rented liquid nitrogen system.

The preliminary estimates for utilities requirements for the form coke process are as follows:

• Cooling water	<5 gpm*
• Electricity	80 kW, 1,920 kWh/24 hr-day
• Steam	0
• Natural Gas**	
Normal	30 scfm
Startup	30 scfm
• Plant air	5 scfm
• Nitrogen	
Normal	4 scfm
Startup	450 scf

* A higher temperature air-cooled, closed-loop cooling water system will be acceptable.

** This includes the emission control system requirement.

Normal Operation and Controls

The general operation of the form coke process was described previously in the Process Description section. The normal operating adjustments and functions of the major gas distribution and heat balance controls are described below. An overall controls diagram for the form coke is presented in Figure III-11.

Figure III-11. FORM COKE PRODUCTION CONTROL DIAGRAM

Mixer/Heater Temperature Control

The primary mode of heat input to the mixer/heater is through indirect heating with natural gas. The temperature of the plastic mass exiting to the briquetter is maintained by modulating the flow rate of natural gas to the indirect heater. The natural gas is combusted with excess air, and the hot gases pass through the mixer/heater shell to supply heat through the mixer/heater walls.

A small portion of heat is supplied to the mixer/heater through direct contact of hot calciner vent gas with plastic mass inside the mixer/heater. The temperature control mechanism described above controls the additional heat input required.

Calciner Temperature Control

The calciner is a vertical shaft furnace with heating and cooling zones. Heat to the mixer heater is supplied by passing hot flue gas countercurrent to a moving bed of briquettes. Hot flue gas at 1200°F is supplied to the form coke process from the gasification incinerator (F-401). The hot flue gas temperature is boosted to about 2000°F with a direct-fired gas heater. The temperature of hot gas to the calciner is controlled by modulating the flow of natural gas to the direct heater. Excess air to the direct heater is kept to a minimum by adjusting the airflow on the basis of the oxygen content of the hot flue gas.

Cool flue gas is introduced in the bottom of the calciner to cool the briquettes and to recover heat for calcination. After recovering heat from the exiting briquettes, this flue gas combines with the hot flue gas (2000°F) to supply heat to the incoming briquettes. Temperature measurements inside the calciner help the operator establish the proper flow of hot and cool gases necessary for calcination and cooling. The flow rates of hot and cool gases are adjusted independently with separate flow controllers.

Incinerator Temperature Control

A flue gas temperature in excess of 1400°F is specified for the incinerator to ensure that all hazardous compounds are properly oxidized. Under normal conditions, combustion of the coal volatiles in the incinerator feed should supply the heat requirement of the incinerator. Natural gas is used to make up any shortfall of heat required in the incinerator and is

controlled through temperature measurement of the exiting flue gas. The air required for combustion is modulated on the basis of the measured oxygen content in the flue gas.

Pressure Control

A pressure controller is necessary to provide adequate back-pressure on the mixer/heater to avoid gas flow between the feed preparation equipment (grinder and screw conveyor) and the mixer/heater. Excess pressure in the mixer/heater can cause backflow of combustible gases (i.e., coal volatiles) into the screw conveyor, leading to the formation of an explosive gas mixture in the feed preparation equipment and/or leakage to the environment. Likewise, subatmospheric pressure in the mixer/heater is possible and can lead to the drawing in of air from the screw conveyor to form an explosive gas mixture in the mixer heater.

Startup Procedures

Operation of the form coke process depends on operation of the PDU emission control system. The emission control system is designed to run independently of the gasifier and is brought on line during the first phase of gasification process startup.

The startup of the form coke process is conducted as follows:

- The PDU emission control system is started up following the steps summarized for the gasification process. These startup steps are followed up to and including startup of the gas scrubber. Inert purging and initial pressurization of the coal dryer/preheater and the gasifier are not necessary for stand-alone operation of the form coke process.
- The unit is purged with nitrogen at atmospheric pressure to reduce the oxygen content to less than 1%.
- The incinerators are started up using supplemental natural gas.
- The unit is brought to operating pressure by introducing cool flue gas via the cool gas blower. Startup of the cool gas blower requires initiation of cooling water flow through the gas cooler and establishing a liquid level in the water knockout drum.
- The screw mixer/heater is slowly warmed by burning natural gas in the indirect heater.
- The calciner is brought up to operating temperature by introducing hot flue gas from the emissions control section. Once gas flow has been initiated, the desired temperature of the hot gas is attained by startup of the direct gas heater and the associated air blower.

- The grinder is started, and the various feeds are introduced.
- The operating speeds of the mixer/heater and briquetter are adjusted to correspond to the feed rate.
- The vertical shaft is first filled with form coke; then an appropriate timing sequence is initiated for the lock hopper operation.

Standby

Once operation of the form coke process has begun, briquette production may be put into hot standby for intervals of minutes to hours at a time. In hot standby sampling, minor equipment troubleshooting and other tasks may be performed, with the process unit available for an immediate restart. The process is brought to the hot standby condition in the following way:

- The coal and char feeds and the feed grinder and the screw conveyor are stopped. Coal is retained in the screw lift conveyor.
- The screw mixer/heater is stopped, and the burner heat output is brought to a low level. The briquetter is stopped after it and the screw mixer/heater have been emptied of feed.
- The calciner hot flue gas stream is shut down with the stoppage of the screw mixer/heater. The low level of volatile emissions will be retained by the cooling briquettes and equipment.
- The gas heater is brought to a low firing level (or turned off).
- The cool gas blower is operated at a low flow setting to maintain a temperature gradient in the calciner.
- After the coal inventory in the screw mixer/heater and the calciner has been emptied, the form coke incinerator can be shut down (if required)
- Incinerator (F-401) firing is maintained at a low level to accommodate any minor emissions.

The guidelines given above will facilitate a rapid restart of the form coke process after minor maintenance and sampling have been performed. Most operations requiring that the form coke production process be brought to hot standby may be done while the inventories in the screw mixer/heater are being depleted. Specific actions to achieve a hot standby condition in response to scheduled activities and process upsets will be developed through final design and will be included in a PDU operating plan.

Shutdown

Shutdown is carried out using the same procedure as above for standby except:

- Coal continues to be ground and fed into the the screw mixer/heater until the screw conveyor is empty.
- The burner for the screw mixer/heater is shut off when it has no coal.
- The calciner operates until the calcining section is emptied of briquettes. The gas heater is then shut off, and the hot flue gas is turned down to low heat.
- When all briquettes have been discharged out of the calciner, then the emission control section, the incinerator, and all associated equipment can be shut down.
- The system is allowed to cool, and the gaseous contents are purged with nitrogen through the incinerator.
- When free of hydrocarbon, the system is purged with air prior to being cleared for entry if personnel access is required.

Special Equipment Designs

Mixer/Heater

The screw mixer/heater thoroughly mixes the coarse char, char fines, and coal feed while these are being heated to 1000 °F. The design of the unit includes a system of three screws for conveying and mixing, and a burner that indirectly heats the mass up to temperature. Two of the three screws move solids in the direction of the process flow, and the third moves solids in the reverse direction to provide the mixing action. The heat input is controlled by varying natural gas and air to the external burner to maintain the outlet solids at the desired temperature. Volatiles leaving the coal/coke mixture are removed in a disengaging space, vented to an incinerator, and then scrubbed in the emission control section.

Hot Roll Briquetter

The hot, plastic mass output of the screw mixer/heater is formed into briquettes in a hot roll briquetter. Since the feed to this unit is already at an elevated temperature, a great amount of pressure for forming briquettes is not required.

Calciner

The calciner completes the conversion of the briquettes into form coke. This unit is designed to provide 1 hour of retention for calcining followed by 1 hour of cooling. The calciner has an internal diameter of 3.1 feet and internal height of 12.5 feet. It is refractory-lined and has an outlet lock hopper.

CAPITAL COST ESTIMATE

The capital cost estimate for the 24 tpd PDU and the associated form coke equipment is based on the conceptual design described previously. A detailed listing of the PDU equipment and details of the capital cost components is included in Appendix B. The cost estimate, which is summarized in Table III-13, assumes construction on the site of the Illinois Coal Development Park in Carterville, Illinois operated by Southern Illinois University, Carbondale, Illinois. It also reflects the preliminary facility layout illustrated in Figures III-12 and III-13. The illustrative major equipment elevations are shown in Figure III-14.

A high bay facility is available at the site, together with an extensive laboratory and personnel-related facilities. For this reason, only a nominal allowance has been made in the estimate for support facilities. The exact utilization of these existing facilities and the need for supplementing them will be determined during detailed design. It appears at this time that the major PDU equipment will be located in a separate structure from the high bay building, but that its controls and laboratory support facilities may be housed within the existing building.

Assuming that the PDU facility will be retained for use at the Illinois Coal Development Park beyond the proposed test period, no allowance has been included for demolition and site restoration. Nor has the scrap value of the equipment been considered in the cost estimate. Should demolition and site restoration be necessary the equipment scrap value has been estimated to totally offset the additional costs. No specific allowance has been included for unusual environmental permitting, although the allowance for engineering includes standard construction permitting.

The pricing of the major equipment is based on Bechtel in-house data; the pricing for bulk materials are factored based on Bechtel in-house data for similar projects. Direct manual manhours are developed using Bechtel's standard unit manhours as determined by historical data. The composite wage rate for union labor is based on in-house data for the Chicago, Illinois, area. Costs are expressed in 1st quarter 1991 dollars with no escalation.

Table III-13. 24 tpd PDU ESTIMATED CAPITAL COST
(1st Quarter 1991 10⁶\$)

Item	Plants 1 Through 5	Plant 6	Total, Plants 1 Through 6
Major Equipment	1.240	0.571	1.811
Bulk Materials and Subcontract	1.860	0.800	2.660
Direct Labor	<u>1.270</u>	<u>0.534</u>	<u>1.804</u>
Total Direct Cost	4.37	1.91	6.28
Field Indirect Cost	<u>0.896</u>	<u>0.373</u>	<u>1.269</u>
Total Field Cost	5.27	2.28	7.55
Engineering and Procurement	1.147	0.495	1.642
Construction Management	<u>0.264</u>	<u>0.114</u>	<u>0.378</u>
Subtotal Without Fee	6.68	2.89	9.57
Fee	<u>0.231</u>	<u>0.100</u>	<u>0.331</u>
Total Project Cost	6.91	2.99	9.90

Figure III-12. PRELIMINARY LAYOUT -- 24 tpd PROCESS DEMONSTRATION FACILITY

Figure III-13. PRELIMINARY LAYOUT -- 24 tpd PROCESS DEMONSTRATION FACILITY (Perspective View)

Figure III-14. PDU EQUIPMENT ELEVATIONS RELATIVE TO THE EXISTING
HIGH BAY BUILDING

OPERATING COST ESTIMATE

The following estimate of the PDU operating costs envisions a 12-month period of operation followed by a 2-month period for mechanical inspection of the unit and data evaluation and documentation. The 12-month operating period consists of 2 months for startup and shakedown followed by 10 months of intensive parametric testing employing a variety of coals.

Operations Staff Requirements

The estimated staffing requirements for the operation are defined in Table III-14. As indicated, a 5 day/wk operation is assumed, with 3 shifts operating per day (24 hours). With allowance for postoperation inspection, data assessment, and offsite analytical support, the total labor requirement is about 23,000 manhours.

Test Program Operating Cost

The estimated cost for the 12-month operating program and 3-month period for data analysis and documentation is presented in Table III-15. The total cost of \$2.9 million reflects an estimate of fully overheaded staff salaries and includes an allowance for travel and subsistence for IGT/Bechtel technical support during the startup and during postoperation inspection.

Table III-14. PDU TEST PROGRAM
Staffing Requirement for a 15-Month Test Program
and Documentation*

Test Staff	Shifts/		Day	No. of		Length of Time	Manhours (MH)	Comments
	Day	Week	Day	Staff	Staff			
PDU Shakedown, Startup, and Operation								
Test Manager	1	5		1		13 mo.	2080	
Technical Supervisor	1	5		1		12 mo.	1920	
Shift Engineer	1	5		1		3 mo.	480	
No. 1 Operator	3	5		3		11 mo.	5280	
No. 2 Operator	3	5		3		11 mo.	5280	
Offsite Analyst							200	As required (MH)
Chemical Consultant							300	On call (MH)
Maintenance Mechanic	1	5		1		11 mo.	1760	
Controls Technician	1	5		1		11 mo.	1760	
Major Maintenance							1000	As required
Subtotal							20,060	
Postoperation PDU Inspection								
Test Manager	1	5		1		2 wk.	80	
Technical Supervisor	1	5		1		2 wk.	80	
Technical Specialist	2	5		2		2 wk	160	
Maintenance Support							500	
Subtotal							820	
Data Assessment and Process Evaluation								
Project Manager	1	5		1		3 mo.	480	
Technical Specialist	2	5		2		3 mo.	960	
Cost Estimator	1	5		1		1 mo.	160	
Subtotal							1600	
Total							22,480	

* 2-month startup, 10-month intensive testing, 3-month evaluation, and documentation.

Table III-15. PDU OPERATING COSTS FOR A 12-MONTH TEST PROGRAM*

Item	Amount	Unit Cost (\$/Unit)	Total Cost (10 ³)
Materials			
Feed Coal	6000 tons	30	180.0
Sodium Hydroxide	25 kgal	0.2	5.0
Nitrogen	2100 kscf	2	4.2
Natural Gas	9000 kscf	2	18.0
Utilities			
Electric Energy	1259 MWh	50	62.9
Domestic Water	90 kgal	0.2	0.0
Cooling Water	14,000 kgal	0.2	2.8
Waste Disposal	100 tons	15	1.5
Maintenance			
Material and Labor (10%/yr Facility Capital)			312.0**
Plant Change Allowance (10%/yr Facility Capital)			460.0
Operating Labor	4472 MH	90	402.5
Technical and Supervision	12,728 MH	35	445.5
Operating Nontechnical			
Support Activities			
Analytical (allowance) and Postoperation Inspection	500 MH	75	37.5
Travel, Subsistence, and Technical Support	600 MH	85	51.0
Mobile Equipment Rental (allowance)	360 days	100	36.0
Other Rentals (Analytical Equipment, etc. (allowance)	400 days	100	40.0
Site Rental (allowance)			30.0
Operating Insurance (10 months) (allowance)			100.0
Subtotal			2188.9
Administration and Support Costs			688.5
Total			2877.4

* 2-month start-up, 10-month test program.

** Includes maintenance manhours.

DETAILED ENGINEERING

Preliminary piping and instrumentation diagrams (P&IDs) and electrical single-line diagrams for the 24 tpd process development unit are described in this section. The drawing package is included in Appendix C.

The P&IDs and electrical drawings provide an added level of detail to the gasification and form coke production units. These drawings are preliminary in nature and should not be used for construction purposes. Additional site-specific information required for bringing these drawings to the level of detail required for final engineering is also discussed.

Piping and Instrumentation Diagrams

Preliminary P&IDs were prepared to further detail the schematic representation of the piping, ductwork, material flow, process control, and instrumentation for the mechanical systems of the process. The process equipment is generally grouped by function. The groupings are also made with the intent to facilitate layout and grouping of equipment according to area electrical classification requirements.

Development and review of the preliminary P&ID drawing package also provided an added level of review of the proposed process configuration. This resulted in a number of recommendations to improve unit operations and/or reduce costs. A summary of these recommendations are given in Appendix D.

The preliminary P&IDs included in Appendix C are listed in Table III-16.

Table III-16 gives the preliminary hazardous area classification designations for the equipment shown in the drawing. The Class I areas shown above can be further defined as Class I, Division 2, indicating that equipment in the area handles combustible vapors in sealed, inert-blanketed, vessels such that the vapors are not normally present in air. Class II areas shown can also be further defined as, Division I, Group F, which indicates that the area is exposed to coal or coke dusts which may be present in combustible concentrations in the atmosphere. Equipment in use in areas with both area classification designations must satisfy the requirements of both classifications (i.e., equipment must be both explosion-proof (Class I) and dust-tight (Class II)).

Table III-16. PRELIMINARY P&IDs

<u>No.</u>	<u>Description</u>	<u>Classification</u>
A-00	Symbols and Legend	N/A
A-01	Coal Handling	II
A-02	Coal Drying	II
A-03	Gasifier Heat Supply	I & II
A-04	Gasifier	I & II
A-05	Hot Gas Fines Removal	I & II
A-06	Heavy Oil/Tar Recovery	I
A-07	Middle and Light Oil Recovery	I
A-08	Incinerator	UNC, I & II
A-09	Emission Control	UNC
A-10	Chemical and Solution Storage and Handling	UNC
A-11	Coal Oil Products Storage and Handling	I
A-12	Char and Coal Storage and Handling	II
A-13	Briquette Forming	I & II
A-14	Briquette Calcining	I & II
A-15	Calciner Air and Heat Supply	I & II
A-16	Process Utilities	UNC
	UNC -- Unclassified	

A determination of the specific classification area requirement will require an equipment layout adequate to identify the location of the equipment items and establish the boundaries of the classified areas. This design will be performed to minimize the equipment procurement and installation costs, and to simplify PDU operation requirements.

Electrical Single-Line Diagram

An electrical single-line diagram, Drawing E-01, was also developed and is included in the drawing package, Appendix C. This drawing shows all of the electrical loads of the PDU unit, including all utility requirements. The drawing is also preliminary in nature. Power distribution may be significantly altered if skid-mounted units or other types of material-handling equipment are selected during final design (e.g., venturi feeders instead of rotary air lock valves or pneumatic pumps instead of electric-motor-driven pumps).

The electrical loads shown in Drawing E-01 permit the electrical feeder requirements to be estimated. The PDU electrical system has a total connected load of 431 kVA, and the projected power demand is estimated to be 393 kVA. This system, therefore, requires a single 480 Vac, 3-phase, 4-wire, 600 A feeder. This feeder will allow for about 20 hp in future load growth without having to discount demand based on load duty or make other provisions for electrical power.

Electrical schematics, control logic, wiring diagrams, and other electrical details will be developed during final design.

Additional Information Required for Final Engineering

At this level of design, several question arise which must be resolved before a final engineering package can be produced. Final engineering for construction will require the following:

- Verification of site resources and availability of:
 - Utilities
 - Buildings and personnel facility
 - Preferred siting and access for the PDU, with special attention to truck access and routing
 - Soil characteristics

- Selection of mechanical equipment accompanied by process adjustment to match the equipment requirements
- Coordination with the proposed operations staff to accommodate its specific test program and operating preferences
- Design adjustment to support and accommodate special environmental permitting requirements
- Screening of DOE surplus equipment for possible use on the project

APPENDIX A. Material Balances for Two Alternative
Hot Char Recycle Rates

Table A-1, Part 1. IGT -- PDU MATERIAL BALANCE (0.5:1 Char:Coal Recycle)
FOR STREAMS 1 THROUGH 80

Item	1	2	3	4	5	6	7	8	9	10	11	12	13
	Wet Feed	Flue Gas	Dried	Flue Gas	Dryer Recycle	Dryer Vent	Hot Gas	Preheated	Preheated	Preheated	Gas from	Air to	Hot Recycle
	Coal	to	Feed	from	to Coal	Gas to	to Coal	Coal/Gas to	Coal	Coarse	Booster Htr	Booster Htr	Gas to
		Coal Dryer	Coal	Coal Dryer	Preheater	Incinerator	Preheater	Cyclones	Fines	Coal	to Gasifier	Booster Htr	Booster Htr
Pressure, psia	15	36	36	36	39	15	39	37	37	37	39	40	40
Temperature, °F	60	532	192	192	212	212	666	532	532	532	2000	890	1200
Total flow, lb/hr	2,500	5,849	2,014	6,335	3,100	3,155	5,755	7,849	400	1,600	1,991	987	1,005
acfh		60,592		45,060	20,979	55,508	62,335	58,954			46,351	12,368	15,899
scfh		77,805		88,034	43,081	43,841	76,395	77,805			26,001	12,967	13,556
Solids flow, lb/hr	2000.0		2000.0					2000.0	400.0	1600.0			
Coal (MAF) (a)	1710.0		1710.0					1710.0	342.0	1368.0			
Char (MAF)	290.0		290.0					290.0	58.0	232.0			
Ash													
Gas/liquid flows, lb/hr	500.0	5848.9	14.2	6334.7	3100.0	3154.7	5754.7	5848.9			1991.1	986.7	1004.6
N2		4040.8		4040.8	1977.4	2012.3	3989.7	4040.8			1425.6	756.8	668.7
O2		9.9		9.9	4.9	4.9	9.8	9.9				229.9	
CO													25.0
CO2		1194.9		1194.9	584.7	595.1	1179.8	1194.9			390.6		204.4
H2O	500.0	603.1	14.2	1088.9	532.9	542.3	575.2	603.1			152.3		34.4
H2													4.2
CH4													20.7
C2H4													9.8
C2H6													4.2
C3H6													4.9
C3H8													0.5
Light oil													8.5
Middle oil													2.6
Tar/heavy oil													
SO2		0.2		0.2	0.1	0.1	0.2	0.2			22.7		10.7
H2S													6.2
NaOH													
Na2SO3													

(a) MAF = moisture- and ash-free

Table A-1, Part 2. IGT -- PDU MATERIAL BALANCE (0.5:1 Char:Coal Recycle)
FOR STREAMS 1 THROUGH 80

Item	14	15	16	17	18	19	20	21	22	23	24	25	26
	Hot Recycle Gas Bypass of Booster Htr	Air to Char Htr	Recycle Gas to Char Htr	Flue Gas from Char Htr	Char from Char Htr Cyclone	Flue Gas from Char Htr Cyclone	Char Htr Flue Gas to Incinerator	Hot Gas to Coal Preheater	Air To Gasifier Heaters	Hot Recycle Gas to Gasifier	Recycle Gas to Heat Recovery	Char Htr to Char Htr	Recycle Gas to Gasifier (Coal Fines)
Pressure, psia	40	40	40	37	37	37	15	40	42	40	40	37	40
Temperature, °F	1200		1200	2000	2000	2000	1200	1200	200	1200	100	1100	100
Total flow, lb/hr		643		1,643	938	706	706	2,655	1,630	1,005	1,005	1,000	26
acth		8,061		16,251		16,251	27,050	39,072	27,185	15,899	5,363		139
scfh		8,451		8,649		8,649	8,649	33,314	21,419	13,556	13,556		352
Solids flow, lb/hr				937.5	937.5							1000.0	
Coal (MAF) (a)				709.1	709.1							771.6	
Char (MAF)				228.4	228.4							228.4	
Ash													
Gas/liquid flows, lb/hr		643.1		705.6		705.6	705.6	2654.7	1629.9	1004.6	1004.6		26.1
N2				493.1		493.1	493.1	2012.3	1250.0	668.7	668.7		17.4
O2		493.1				29.2	29.2	4.9	379.9		25.0		0.6
CO		150.0		29.2		183.3	183.3	595.1		25.0	204.4		5.3
CO2				183.3				42.3		34.4	34.4		0.9
H2O										4.2	4.2		0.1
H2										20.7	20.7		0.5
CH4										9.8	9.8		0.3
C2H4										4.2	4.2		0.1
C2H6										4.9	4.9		0.1
C3H6										0.5	0.5		0.0
C3H8										8.5	8.5		0.2
Light oil										2.6	2.6		0.1
Middle oil										10.7	10.7		0.3
Tar/heavy oil								0.1		6.2	6.2		0.2
SO2													
H2S													
NaOH													
Na2SO3													

(a) MAF = moisture- and ash-free

Table A-1, Part 3. IGT -- PDU MATERIAL BALANCE (0.5:1 Char:Coal Recycle)
FOR STREAMS 1 THROUGH 80

Item	27	28	29	30	31	32	33	34	35	36	37	38	39
	Recycle Gas to Gasifier (Coarse Coal)	Recycle Gas To Gasifier (Char Inject)	Recycle Gas To Char Recycle	Coarse Char Product	Gasifier Flue Gas	Gas To Thermal Cracking	Char Fines Product	Heavy Oil/ Tar To Storage	Gas From Heavy Oil/Tar Separator	Gas From Middle Oil Separator	Middle Oil To Storage	Gas To Light Oil Quench	Light Oil To Storage
Pressure, psia	40	40	40	15	35	34	15	15	33	32	15	42	15
Temperature, °F	100	100	100	140	925	925	140	450	450	170	170	209	100
Total flow, lb/hr	26	38	38	984	3,034	2,749	286	242	2,507	2,431	76	2,431	25
acfh	139	200	200		38,354	39,482			26,488	18,840		15,243	
scfh	352	506	506		34,295	34,295			33,988	33,860		33,860	
Solids flow, lb/hr				983.9	285.6		285.6						
Coal (MAF) (a)													
Char (MAF)				759.1	220.4		220.4						
Ash				224.7	65.3		65.3						
Gas/liquid flows, lb/hr	26.1	37.5	37.5		2748.8	2748.8		242.2	2506.7	2430.9	75.8	2430.9	24.5
N2	17.4	25.0	25.0		1,485.3	1,485.3			1,485.3	1,485.3		1,485.3	
O2													
CO	0.6	0.9	0.9		55.5	55.5			55.5	55.5		55.5	
CO2	5.3	7.6	7.6		454.1	454.1			454.1	454.1		454.1	
H2O	0.9	1.3	1.3		251.3	251.3			251.3	251.3		251.3	
H2	0.1	0.2	0.2		9.2	9.2			9.2	9.2		9.2	
CH4	0.5	0.8	0.8		45.9	45.9			45.9	45.9		45.9	
C2H4	0.3	0.4	0.4		21.7	21.7			21.7	21.7		21.7	
C2H6	0.1	0.2	0.2		9.2	9.2			9.2	9.2		9.2	
C3H6	0.1	0.2	0.2		10.9	10.9			10.9	10.9		10.9	
C3H8	0.0	0.0	0.0		1.1	1.1			1.1	1.1		1.1	
Light oil	0.2	0.3	0.3		33.3	33.3			33.2	29.2	4.0	29.2	10.4
Middle oil	0.1	0.1	0.1		56.2	56.2		0.1	55.1	19.8	35.3	19.8	14.1
Tar/heavy oil					277.4	277.4		241.0	36.5	23.7	36.5	23.7	
SO2	0.3	0.4	0.4		23.7	23.7			23.7	23.7		23.7	
H2S	0.2	0.2	0.2		13.8	13.8			13.8	13.8		13.8	
NaOH													
Na2SO3													

(a) MAF = moisture- and ash-free

Table A-1, Part 4. IGT -- PDU MATERIAL BALANCE (0.5:1 Char:Coal Recycle)
FOR STREAMS 1 THROUGH 80

Item	40	40A	41	42	43	44	45	46	46A	47	48	49	50
	Sour Water To Storage	Gas From Light Oil Separator	Water To Gas Scrubber	Caustic to Gas Scrubber	Concentrated Sodium Sulfide Sol	Liquid from Scrubber	Air to Incinerator	Recycle Gas Vent to Incinerator	Total Vent Gas to Incinerator	Conc. Sodium Sulfide to Storage	Sour Water to Incinerator	Natural Gas to Incinerator	Clean Gas from Scrubber
Pressure, psia	15	40	24	12	25	35	40	15	15	15	25	40	12
Temperature, °F	100	100	60	60	180	180	60	100	400	100	100	60	160
Total flow, lb/hr	175	2,231	100	128	219	438	1,571	1,137	4,998	219	175	20	8,196
acfh		11,914					7,587	16,190	109,915			174	178,776
scfh		30,111					20,650	15,345	67,835			474	122,435
Solids flow, lb/hr													
Coal (MAF) (a)													
Char (MAF)													
Ash													
Gas/liquid flows, lb/hr	174.9	2231.5	100.0	127.9	219.0	438.1	1571.4	1137.2	4997.6	219.0	174.9	20.0	8196.2
N2		1485.3					1205.2	756.9	3262.3				4467.7
O2							366.1		4.9				11.0
CO		55.5						28.3	57.5				
CO2		454.1						231.4	1009.8				1321.4
H2O	174.9	76.4	100.0	96.0	168.7	337.3		39.0	581.2	168.7	174.9		2395.9
H2		9.2						4.7	4.7				
CH4		45.9						23.4	23.4			20.0	
C2H4		21.7						11.1	11.1				
C2H6		9.2						4.7	4.7				
C3H6		10.9						5.5	5.5				
C3H8		1.1						0.6	0.6				
Light oil		18.9						9.6	9.6				
Middle oil		5.7						2.9	2.9				
Tar/heavy oil													0.3
SO2		23.7						12.1	12.2				
H2S		13.8						7.0	7.0				
NaOH				32.0	50.4	100.8							
Na2SO3										50.4			

(a) MAF = moisture- and ash-free

Table A-1, Part 5. IGT -- PDU MATERIAL BALANCE (0.5:1 Char:Coal Recycle)
FOR STREAMS 1 THROUGH 80

Item	51	52	53	54	55	56	57	58	59	60	61	62	63
	Effluent from Incinerator	Dryer Recycle Gas for Fluidization	Fluidized Coal Fines to Gasifier	Fluidized Coarse Coal To Gasifier	Recycle Gas for Coal Injection	Cracked Gas Recovery to Liquid	Natural Gas Makeup to Recycle	Off Gas from Briquetting	Combined Gas to Scrubber	Water Quench to Scrubber	Feed Gas to Scrubber	Scrubber Recycle	Clean Gas to Stack
Pressure, psia	14	39	37	37	40	34	40	15	15	24	14	14	15
Temperature, °F	790	212	532	532	100	1800	60		790	60	180	180	200
Total flow, lb/hr	6,764	80	426	1,626	52	2,749			6,764	1,423	8,187	219	4,505
acfh	231,881	541	267	267	279	64,425			216,422		157,436		83,678
scfh	91,894	1,112	352	352	704	34,295			91,894		121,858		67,292
Solids flow, lb/hr			400.0	1600.0									
Coal (MAF) (a)			342.0	1368.0									
Char (MAF)			58.0	232.0									
Ash													
Gas/liquid flows, lb/hr	6764.2	80.0	26.1	26.1	52.2	2748.8			6764.2	1423.1	8187.3	219.0	4504.7
N ₂	4467.7	51.0	17.4	17.4	34.7	1485.3			4467.7		4467.7		2455.4
O ₂	11.0	0.1							11.0		11.0		6.0
CO			0.6	0.6	1.3	55.5							
CO ₂	1321.4	15.1	5.3	5.3	10.6	454.1					1321.4		726.3
H ₂ O	938.3	13.8	0.9	0.9	1.8	251.3					2361.4	168.7	1316.9
H ₂			0.1	0.1	0.2	9.2							
CH ₄			0.5	0.5	1.1	45.9							
C ₂ H ₄			0.3	0.3	0.5	21.7							
C ₂ H ₆			0.1	0.1	0.2	9.2							
C ₃ H ₆			0.1	0.1	0.3	10.9							
C ₃ H ₈			0.0	0.0	0.0	1.1							
Light oil			0.2	0.2	0.4	33.3							
Middle oil			0.1	0.1	0.1	56.2							
Tar/heavy oil						277.4							
SO ₂	25.8		0.3	0.3	0.6	23.7			25.8				0.1
H ₂ S			0.2	0.2	0.3	13.8							
NaOH													
Na ₂ SO ₃												50.4	

(a) MAF = moisture- and ash-free

Table A-1, Part 6. IGT -- PDU MATERIAL BALANCE (0.5:1 Char:Coal Recycle)
FOR STREAMS 1 THROUGH 80

Item	64	65	66	67	68	69	70	71	72	73	74	75	76
	Heavy Oil/Tar from Separator	Tar Quench Recycle	Sludge to Gasifier	Middle Oil from Separator	Middle Oil Quench Recycle	Stream To Middle Oil Cooler	Coarse Char to Briquetting	Char Fines to Briquetting	Nitrogen to Char Transport	Nitrogen to Coarse Char Transport	Nitrogen to Char Fines Transport	Makeup Nitrogen	Nitrogen Recycle
Pressure, psia	33	34	37	32	32	33	15	15	20	20	20	15	15
Temperature, °F	450	291	450	170	170	225	140	140	116	116	116	60	140
Total flow, lb/hr	18,242	18,000		8,176	8,100	10,607	984	286	51	39	11	1	51
acfh						27,974			559	434	126	17	777
scfh						47,686			687	533	155	17	687
Solids flow, lb/hr							983.9	285.6					
Coal (MAF) (a)													
Char (MAF)							759.1	220.4					
Ash							224.7	65.3					
Gas/liquid flows, lb/hr	18242.2	18000.0		8175.8	8100.0	10606.7			50.8	39.4	11.4	1.3	50.8
N2						1485.3							
O2						55.5							
CO						454.1							
CO2						251.3							
H2O						9.2							
H2						45.9							
CH4						21.7							
C2H4						9.2							
C2H6						10.9							
C3H6						1.1							
C3H8						460.6							
Light oil	7.3	7.2		431.4	427.4								
Middle oil	82.6	81.5		3811.1	3775.8								
Tar/heavy oil	18152.3	17911.3		3933.3	3896.8								
SO2						23.7							
H2S						13.8							
NaOH													
Na2SO3													

(a) MAF = moisture- and ash-free

Table A-1, Part 7. IGT -- PDU MATERIAL BALANCE (0.5:1 Char:Coal Recycle)
FOR STREAMS 1 THROUGH 80

Item	77	78	75	80	77	78	75	80	77	78	75	80	77	78	75	80
	Fuel Gas to	Clean Flue	Compressed	Recovered	Natural Gas	Alr to	Flue Gas									
	Briquetting	Gas to	Gas after	Water	to Thermal	Thermal	from Thermal									
	Operation	Recycle	Water K.O.		Cracker Heater	Cracker Heater	Cracker Heater									
Pressure, psia	40	15	40	40	40	15	40									
Temperature, °F	100	201	100	100	60	60	100									
Total flow, lb/hr		3,692	2,655	1,037	68	1,167	1,235									
acfh		68,675	13,181		592	15,030	6,707									
scfh		55,143	33,314		1,611	15,341	16,952									

Solids flow, lb/hr

Coal (MAIF) (a)
Char (MAF)
Ash

Gas/liquid flows, lb/hr

N2	3691.5	2654.7	1036.8	67.9	1167.4	1235.4
O2	2012.3	2012.3			895.4	895.4
CO	4.9	4.9			272.0	
CO2	595.1	595.1				187.0
H2O	1079.1	42.3	1036.8			153.0
H2						
CH4				68.0		
C2H4						
C2H6						
C3H6						
C3H8						
Light oil						
Middle oil						
Tar/heavy oil						
SO2	0.1	0.1				
H2S						
NaOH						
Na2SO3						

(a) MAF = moisture- and ash-free

Table A-2, Part 1. IGT -- PDU MATERIAL BALANCE (2:1 Char:Coal Recycle)
FOR STREAMS 1 THROUGH 80

Item	1	2	3	4	5	6	7	8	9	10	11
Wet Feed Coal		Flue Gas to Coal Dryer	Dried Feed Coal	Flue Gas from Coal Dryer	Dryer Recycle to Coal Preheater	Dryer Vent Gas to Incinerator	Hot Gas to Coal Preheater	Preheated Coal/Gas to Cyclones	Preheated Coal Fines	Preheated Coal Coarse	Gas from Booster Htr to Gasifier
Pressure, psia	15	36	36	36	39	15	39	37	37	37	39
Temperature, °F	60	532	192	192	212	212	666	532	532	532	2000
Total flow, lb/hr	2,500	6,074	2,014	6,560	3,100	3,380	5,980	8,074	400	1,600	
acfh		61,732		45,809	20,600	58,372	63,546	60,063			
scfh		79,269		89,498	42,302	46,104	77,878	79,269			
Solids flow, lb/hr	2,000.0		2,000.0					2,000.0	400.0	1,600.0	
Coal (MAF) (a)	1,710.0		1,710.0					1,710.0	342.0	1,368.0	
Char (MAF)	290.0		290.0					290.0	58.0	232.0	
Ash											
Gas/liquid flows, lb/hr	500.0	6,073.8	14.2	6,559.6	3,100.0	3,379.6	5,979.6	6,073.8			
N2		4,079.1		4,079.1	1,928.2	2,101.1	4,029.4	4,079.1			
O2		11.1		11.1	5.2	5.7	10.9	11.1			
CO											
CO2		1,433.7		1,433.7	676.8	739.5	1,416.3	1,433.7			
H2O	500.0	549.6	14.2	1,035.4	489.7	533.1	522.8	549.6			
H2											
CH4											
C2H4											
C2H6											
C3H6											
C3H8											
Light oil											
Middle oil											
Tar/heavy oil											
SO2		0.2		0.2	0.1	0.1	0.2	0.2			
H2S											
NaOH											
Na2SO3											

(a) MAF = moisture- and ash-free

Table A-2, Part 2. IGT -- PDU MATERIAL BALANCE (2:1 Char:Coal Recycle)
FOR STREAMS 1 THROUGH 80

Item	12	13	14	15	16	17	18	19	20	21	22
	Air to Gasifier Booster Htr	Hot Recycle Gas to Booster Htr	Hot Recycle Gas Bypass of Booster Htr	Air to Char Htr	Recycle Gas to Char Htr	Flue Gas from Char Htr	Char from Htr Cyclone	Flue Gas from Char Htr Cyclone	Char Htr Flue Gas to Incinerator	Hot Gas to Coal Preheater	Air to Gasifier Heaters
Pressure, psia	40	40	40	40	40	37	37	37	15	40	42
Temperature, °F	890	1200	1200	890	1200	2000	2000	2000	1200	1200	200
Total flow, lb/hr			2,204	2,573		6,573	3,750	2,823	2,823	2,880	2,573
acfh			55,130	32,245		65,005		65,005	108,201	41,725	42,907
scfh			47,005	33,806		34,595		34,595	34,595	35,576	33,806
Solids flow, lb/hr						3,750.0	3,750.0				
Coal (MAF) (a)											
Char (MAF)						2,677.9	2,677.9				
Ash						1,072.1	1,072.1				
Gas/liquid flows, lb/hr			2,204.4	2,572.5		2,822.5		2,822.5	2,822.5	2,879.6	2,572.5
N2											
O2											
CO			547.1	1,972.5		1,972.5		1,972.5	1,972.5	2,101.1	1,972.5
CO2			482.3	600.0						5.7	600.0
H2O			34.1								
H2			91.0								
CH4			452.4								
C2H4			214.1								
C2H6			91.0								
C3H6			107.0								
C3H8			10.7								
Light oil			32.3								
Middle oil			5.2								
Tar/heavy oil											
SO2			1.0								
H2S			136.2								
NaOH											
Na2SO3											
											0.1

(a) MAF = moisture- and ash-free

Table A-2, Part 3. IGT -- PDU MATERIAL BALANCE (2:1 Char:Coal Recycle)
FOR STREAMS 1 THROUGH 80

Item	23	24	25	26	27	28	29	30	31	32	33
	Hot Recycle Gas to Gasifier	Recycle Gas to Heat Recovery	Char to Char Htr	Recycle Gas to Gasifier (Coal Fines)	Recycle Gas to Gasifier (Coarse Coal)	Recycle Gas to Gasifier (Char Inlet)	Recycle Gas to Char	Coarse Char Product	Gasifier Fine Gas	Gas to Thermal Cracking	Char Fines Product
Pressure, psia	40	40	37	40	40	40	40	15	35	34	15
Temperature, °F	1200	100	1100	100	100	100	100	140	925	925	140
Total flow, lb/hr	2,204	2,204	4,000	26	26	150	150	839	3,318	3,075	243
acfh	55,130	18,598	4,000	220	220	1,266	1,266		65,311	67,232	
scfh	47,005	47,005		557	557	3,198	3,198		58,399	58,399	
Solids flow, lb/hr			4,000.0					838.5	243.4		243.5
Coal (MAF) (a)											
Char (MAF)			2,927.9					613.8	178.2		178.2
Ash			1,072.1					224.7	65.3		65.3
Gas/liquid flows, lb/hr	2,204.4	2,204.4		26.1	26.1	150.0	150.0		3,074.6	3,074.6	
N2											
O2	547.1	547.1		6.5	6.5	37.2	37.2		650.6	650.6	
CO	482.3	482.3		5.7	5.7	32.8	32.8		571.8	571.8	
CO2	34.1	34.1		0.4	0.4	2.3	2.3		133.2	133.2	
H2O	91.0	91.0		1.1	1.1	6.2	6.2		108.2	108.2	
H2	452.4	452.4		5.4	5.4	30.8	30.8		538.0	538.0	
CH4	214.1	214.1		2.5	2.5	14.6	14.6		254.6	254.6	
C2H4	91.0	91.0		1.1	1.1	6.2	6.2		108.2	108.2	
C2H6	107.0	107.0		1.3	1.3	7.3	7.3		127.3	127.3	
C3H6	10.7	10.7		0.1	0.1	0.7	0.7		12.7	12.7	
C3H8	32.3	32.3		0.4	0.4	2.2	2.2		67.8	67.8	
Light oil	5.2	5.2		0.1	0.1	0.4	0.4		61.7	61.7	
Middle oil									277.4	277.4	
Tar/heavy oil									1.0	1.0	
SO2	136.2	136.2		0.0	0.0	0.1	0.1		161.9	161.9	
H2S				1.6	1.6	9.3	9.3				
NaOH											
Na2SO3											

(a) MAF = moisture- and ash-free

Table A-2, Part 4. IGT -- PDU MATERIAL BALANCE (2:1 Char:Coal Recycle)
FOR STREAMS 1 THROUGH 80

Item	34 Heavy Oil Tar to Storage	35 Gas from Heavy Oil/Tar Separator	36 Gas from Middle Oil Separator	37 Middle Oil to Storage	38 Gas to Light Oil Quench	39 Light Oil to Storage	40 Sour Water to Storage	40A Gas from Light Oil Separator	41 Water to Gas Scrubber	42 Caustic to Gas Scrubber	43 Concentrated Sodium Sulfide Sol.
Pressure, psia	15	33	32	15	42	15	15	40	24	12	25
Temperature, °F	450	450	170	170	209	100	100	100	60	60	180
Total flow, lb/hr	242	2,832	2,749	83	2,749	37	93	2,620	100	125	213
acfh		45,273	32,239		26,083			22,110			
scfh		58,092	57,942		57,942			55,880			
Solids flow, lb/hr											
Coal (MAF) (a)											
Char (MAF)											
Ash											
Gas/liquid flows, lb/hr	242.4	2,832.2	2,748.9	83.4	2,748.9	36.6	92.7	2,619.5	100.0	124.7	213.4
N2											
O2		650.6	650.6		650.6			650.6			
CO		571.8	571.8		571.8			571.8			
CO2		133.2	133.2		133.2		92.7	40.5	100.0	93.5	164.3
H2O		108.2	108.2		108.2			108.2			
H2		538.0	538.0		538.0			538.0			
CH4		254.6	254.6		254.6			254.6			
C2H4		108.2	108.2		108.2			108.2			
C2H6		127.3	127.3		127.3			127.3			
C3H6		12.7	12.7		12.7			12.7			
C3H8		67.6	59.5	8.1	59.5	21.1		38.4			
Light oil	0.2	60.5	21.7	38.8	21.7	15.5		6.2			
Middle oil	1.2	36.5	1.0	36.5	1.0			1.0			
Tar/heavy oil	241.0	161.9	161.9		161.9			161.9			
SO2										31.2	49.1
H2S											
NaOH											
Na2SO3											

(a) MAF = moisture- and ash-free

Table A-2, Part 5. IGT -- PDU MATERIAL BALANCE (2:1 Char:Coal Recycle)
FOR STREAMS 1 THROUGH 80

Item	44	45	46	46A	47	48	49	50	51	52	53
	Liquid from Scrubber	Air to Incinerator	Recycle Gas to Vent to Incinerator	Total Vent Gas to Incinerator	Conc. Sodium Sulfide to Storage	Sour Water to Incinerator	Natural Gas to Incinerator	Clean Gas from Scrubber	Effluent from Incinerator	Dryer Recycle Gas for Fluidization	Fluidized Coal Fines to Gasifier
Pressure, psia	35	40	15	15	15	25	40	12	14	39	37
Temperature, °F	180	60	100	400	100	100	60	160	790	212	532
Total flow, lb/hr	427	2,256	213	6,415	213	93		10,198	8,764	80	426
acfh		10,991	4,815	138,154				212,468	290,005	532	422
scfh		29,643	4,564	85,263				145,508	114,928	1,092	557
Solids flow, lb/hr											400.0
Coal (MAF) (a)											342.0
Char (MAF)											58.0
Ash											
Gas/liquid flows, lb/hr	426.8	2,255.7	212.9	6,415.0	213.4	92.7		10,198.3	8,763.8	80.0	26
N2		1,730.1		4,073.7				5,803.8	5,803.8	49.8	
O2		525.6		5.7				15.8	15.8	0.1	
CO			53.3	170.0							6.5
CO2			45.3	1,518.1							5.7
H2O	328.6		3.3	536.4	164.3	92.7		2,043.8	2,043.8	17.5	0.4
H2			8.9	8.9				2,334.6	875.3	12.6	1.1
CH4			44.1	44.1							5.4
C2H4			20.9	20.9							2.5
C2H6			8.9	8.9							1.1
C3H6			10.4	10.4							1.3
C3H8			1.0	1.0							0.1
Light oil			3.1	3.1							0.4
Middle oil			0.5	0.5							0.1
Tar/heavy oil											
SO2			13.3	0.1				0.3	25.2		0.0
H2S				13.3							1.6
NaOH											
Na2SO3	98.2				49.1						

(a) MAF = moisture- and ash-free

Table A-2, Part 6. IGT -- PDU MATERIAL BALANCE (2:1 Char:Coal Recycle)
FOR STREAMS 1 THROUGH 80

Item	54 Fluidized Coarse Coal to Gasifier	55 Recycle Gas for Coal Injection	56 Cracked Gas to Liquid Recovery	57 Natural Gas Makeup to Recycle	58 Off Gas from Briquetting	59 Combined Gas to Scrubber	60 Water Quench to Scrubber Feed	61 Feed Gas to Scrubber	62 Scrubber Recycle	63 Clean Gas to Stack	64 Heavy Oil/Tar from Separator
Pressure, psia	37	40	34	40	15	15	24	14	14	15	33
Temperature, °F	532	100	1800	60	790	790	60	180	180	200	450
Total flow, lb/hr	1,626	52	3,075		8,764	8,764	1,423	10,187	213	6,507	18,242
acfh	422	440	109,707		270,671	270,671		187,195		115,443	
scfh	557	1,113	58,399		114,928	114,928		144,893		92,837	
Solids flow, lb/hr	1,600.0										
Coal (MAF) (a)	1,368.0										
Char (MAF)	232.0										
Ash											
Gas/liquid flows, lb/hr	26.1	52.2	3,074.6		8,763.8	8,763.8	1,423.1	10,186.9	213.4	6,506.8	18,242.4
N2											
O2	6.5	13.0	650.6								
CO	5.7	11.4	571.8								
CO2	0.4	0.8	133.2								
H2O	1.1	2.2	108.2								
H2	5.4	10.7	538.0								
CH4	2.5	5.1	254.6								
C2H4	1.1	2.2	108.2								
C2H6	1.3	2.5	127.3								
C3H6	0.1	0.3	12.7								
C3H8	0.4	0.8	67.8								
Light oil	0.1	0.1	61.7								
Middle oil			277.4								
Tar/heavy oil			1.0								
SO2	0.0	0.0	161.9								
H2S	1.6	3.2									
NaOH											
Na2SO3											
(a) MAF = moisture- and ash-free											

Table A-2, Part 7. IGT -- PDU MATERIAL BALANCE (2:1 Char:Coal Recycle)
FOR STREAMS 1 THROUGH 80

Item	65	66	67	68	69	70	71	72	73	74	75
	Tar Quench Recycle	Sludge to Gasifier	Middle Oil from Separator	Middle Oil Quench Recycle	Stream to Middle Oil Cooler	Coarse Char to Briquetting	Char Fines to Briquetting	Nitrogen to Char Transport	Nitrogen to Coarse Char Transport	Nitrogen to Char Fines Transport	Makeup Nitrogen
Pressure, psia	34	37	32	32	33	15	15	20	20	20	15
Temperature, °F	291	450	170	170	225	140	140	116	116	116	60
Total flow, lb/hr	18,000		8,183	8,100	10,932	839	243	43	34	10	1
acfh					42,650			477	370	107	14
scfh					72,702			586	454	132	15
Solids flow, lb/hr						838.5	243.5				
Coal (MAF) (a)											
Char (MAF)						613.8	178.2				
Ash						224.8	65.3				
Gas/liquid flows, lb/hr	18,000.0		8,183.4	8,100.0	10,932.2			43.3	33.5	9.7	1.1
N2								43.3	33.5	9.7	1.1
O2											
CO					650.6						
CO2					571.8						
H2O					133.2						
H2					108.2						
CH4					538.0						
C2H4					254.6						
C2H6					108.2						
C3H6					127.3						
C3H8					12.7						
Light oil	14.6		798.7	790.6	858.2						
Middle oil	89.4		3,806.0	3,767.3	3,827.8						
Tar/heavy oil	17,896.0		3,578.6	3,542.1	3,578.6						
SO2					1.0						
H2S					161.9						
NaOH											
Na2SO3											

(a) MAF = moisture- and ash-free

Table A-2, Part 8. IGT -- PDU MATERIAL BALANCE (2:1 Char:Coal Recycle)
FOR STREAMS 1 THROUGH 80

Item	76 Nitrogen Recycle	77 Fuel Gas to Briquetting Operation	78 Clean Flue Gas to Recycle	79 Compressed Gas after Water K.O.	80 Recovered Water	Natural Gas to Thermal Cracker Heater	Air to Thermal Cracker Heater	Flue Gas from Thermal Cracker Heater
Pressure, psia	15	40	15	40	40	40	15	40
Temperature, °F	140	100	201	100	100	60	60	100
Total flow, lb/hr	43		3,692	2,880	812	68	1,167	1,235
acfh	662		65,597	14,076		592	15,030	6,707
scfh	586		52,672	35,576		1,611	15,341	16,952

Solids flow, lb/hr

Coal (MAF) (a)
Char (MAF)
Ash

Gas/liquid flows, lb/hr

N2	43.3	3,691.5	2,879.6	811.9	67.9	1,167.4	1,235.4
O2	43.3	2,101.1	2,101.1			895.4	895.4
CO		5.7	5.7			272.0	
CO2		739.5	739.5				187.0
H2O		845.1	33.1	811.9			153.0
H2							
CH4							68.0
C2H4							
C2H6							
C3H6							
C3H8							
Light oil							
Middle oil							
Tar/heavy oil		0.1					
SO2							
H2S							
NaOH							
Na2SO3							

(a) MAF = moisture- and ash-free

APPENDIX B. Equipment List

Pressure Vessels and Drums

Item No.	Item Name	Qty	Service	Capacity	Design Conditions		Material	Shape	Maximum Dimensions		Minimum Thickness	Weight (lb)
					Pres. (psig)	Temp. (°F)			I.D. (ft)	Ht. (ft)		
C-101	Coal Feed Lock Hopper	1	Coal	1,000 lb	42	100	SA-516-70	Cyl	2.5	4.9	0.25	790
C-102	Feed Surge Vessel	1	Coal	2,000 lb	42	100	SA-516-70	Cyl	3.1	6.2	0.25	1,250
C-103	Coal Dryer	1	Coal/Gas	2,000 lb/hr	40	500	Sch 40 Pipe	Cyl	0.665	60	0.32	1,450
C-104	Coal Preheater	1	Coal/Gas	2,000 lb/hr	40	500	Sch 40 Pipe	Cyl	0.665	60	0.32	1,450
C-105	Preheater Surge Vessel	1	Coal	1,000 lb	42	500	SA-516-70	Cyl	2	7.9	0.25	740
C-106	Classifier Surge Vessel	1	Coal	1,000 lb	42	500	SA-516-70	Cyl	2	7.9	0.25	740
C-107	Fines Surge Vessel	1	Coal	1,000 lb	42	500	SA-516-70	Cyl	2	7.9	0.25	740
C-201	Retort Gasifier	1	Coal/Gas	2,000 lb/hr	50	2,000	Carbon Steel	Irreg	See Diagram		0.375	4,000
	(Refractory-Lined)						Refractory	Irreg	See Diagram		12	12,000
C-202	Coarse Char Blowcase	1	Char	700 lb/hr	41	1,000	SA-516-70	Cyl	2.2	4.4	0.25	640
C-203	Char Fines Blowcase	1	Char	200 lb/hr	41	1,000	SA-516-70	Cyl	1.5	2.9	0.25	270
C-301	Tar Separator	1	Tar/H.O.	40 lb	40	1,000	Sch 40 Pipe	Irreg	1.6	5	0.32	630
C-302	Middle Oil Separator	1	Mid Oil	13 lb	40	500	Sch 40 Pipe	Irreg	1.2	3	0.28	290
C-303	Light Oil Separator	1	Oil/H2O	3 lb	40	200	Sch 40 Pipe	Irreg	1.1	5.5	0.24	240
C-304	Tar Quench Condenser	1	Tar/Gas	21,000 lb/hr	40	1,300	High Alloy	Irreg	2.6	3	0.375	480
	Incl. Perforated Plates	6							3.1	30	0.375	4,000
C-401	Scrubber	1	Caustic	1,400 lb/hr	15	200	Carbon Steel	Cyl				
C-402	Incl. Bubble Cap Trays	10	Gas	9,000 lb/hr			Stainless Trays					
D-401	Water Knockout Drum	1	Water	80 lb	40	100	SA-516-70	Cyl	1.1	3.3	0.25	200
D-402	Char Fines Storage	1	Char	7,800 lb	20	200	SA-516-70	Cyl	4.9	9.8	0.25	3,100
D-501	Coarse Char Storage	1	Char	27,000 lb	20	200	SA-516-70	Cyl	7.4	14.8	0.25	7,050
D-502	Caustic Storage Tank	1	Caustic	6,000 gal	15	100	CS, Rub. Lined	Cyl	10.1	10.1	0.25	9,700
D-503	Spent Caustic Storage	1	Caustic	6,000 gal	15	100	CS, Rub. Lined	Cyl	10.1	10.1	0.25	9,700
D-504	Sour Water Storage Tank	1	Water	1,500 gal	15	100	Carbon Steel	Cyl	6.3	6.3	0.25	3,870
D-505	Tar Product Storage Tank	1	Tar/H.O.	32,000 gal	15	100	Carbon Steel	Cyl	17.6	17.6	0.25	30,000
D-506	Middle Oil Storage Tank	1	Mid Oil	12,000 gal	15	100	Carbon Steel	Cyl	12.7	12.7	0.25	15,500
D-507	Light Oil Storage Tank	1	Li. Oil	5,200 gal	15	100	Carbon Steel	Cyl	9.6	9.6	0.25	8,860
D-508	Tar Product Run Tank	1	Tar/H.O.	600 gal	15	100	Carbon Steel	Cyl	3.7	7.4	0.25	1,760
D-509	Middle Oil Run Tank	1	Mid Oil	250 gal	15	100	Carbon Steel	Cyl	2.8	5.5	0.25	980
C-601	Light Oil Run Tank	1	Li. Oil	100 gal	15	100	Carbon Steel	Cyl	2	4.1	0.25	530
	Vertical Shaft Calciner	1	Form Coke	4,030 lb	25	2,000	Carbon Steel	Cyl	4.1	12.5	0.25	1,900
	(Refractory-Lined)						Refractory	Cyl	3.1	12.5	6	3,300
C-602	Lock Hopper	1	Form Coke	1,120 lb	20	500	Carbon Steel	Cyl	2.6	5.1	0.25	850
C-603	Water Knock Out Drum	1	Water	30 lb	25	200	Carbon Steel	Cyl	1	2	0.25	120
D-601	Dry Coal Storage	1	Coal	34,760 lb	20	200	Carbon Steel	Cyl	8.1	16.2	0.25	120
D-602	Lignosulfonate Storage	1	Solution	500 gal	15	100	Carbon Steel	Cyl	4.4	4.4	0.25	120

Atmospheric Tanks and Bins

Item No.	Item Name	Qty	Service	Capacity	Design Temp. (°F)	Material	Type	Maximum Dimensions			Minimum Thickness		Weight (lb)
								L (ft)	W (ft)	H (ft)	Thickness		
											H (in.)		
T-101	Crushed Coal Bunker	1	Coal	16 tons		SA-516-70	Bin	10	9	12	0.25	8,400	
Y-104	Coal Feed Hopper	1	Coal	2 tons	100	SA-516-70	Bin	4	4	10	0.25	1,640	
T-401	Char Fines Transport Container	1	Char		140	CS	Dumpster						
T-402	Coarse Char Transport Container	1	Char		140	CS	Dumpster						
T-601	Dry Coal Transport Container	1	Coal		140	CS	Dumpster						
T-602	Fines Transport Container	1	Form Coke		140	CS	Dumpster						
T-603	Briquette Transport Container	1	Form Coke		140	CS	Cargo Container						

Materials Handling

Item No.	Item Name	Qty	Service	Design Conditions				Material	Feed		Product		Driver (hp)
				Capacity	Pres. (psig)	Temp. (°F)	Type		Size	Size	Size	Size	
Y-602	Feed Grinder	1	Coal/Char	2 tph	atm	200	Roller Crusher		6mx0	28mx0			20
Y-605	Hot Roll Briquetter	1	Coal/Char		15	1,000	Roll Briquetter		N/A	1"			50
Y-606	Vibrating Feeder	1	Form Coke		atm	200	Vibrating Screen	Carbon Steel	1"x0	1"x1/4"			2

Material Handling: Conveyors and Feeders

Item No.	Item Name	Qty	Service	Capacity	Design Conditions		Materials	Duty (Btu/hr)	Comments	Driver (hp)
					Pres. (psig)	Temp. (°F)				
T-102	Coal Feed Conveyor	1	Coal	2 tph	atm			N/A		1
T-103	Coal Lift Conveyor	1	Coal	2 tph	atm			N/A	20 ft lift	1
T-104	Feed Screw Conveyor	1	Coal	2 tph	atm		SA-516-70	N/A	6 in. dia.	1
T-201	Char Discharge Cooler/ Conveyor	1	Char	2 tph	40	1,250	SA-516-70	1.7 MM Cooling	Water-Cooled Screw	0.5
T-202	Char Heater Screw Feeder	1	Char	2 tph	40	1,250	Stainless Steel	N/A	Compression Screw	0.5
T-203	Char Fines Cooler/ Conveyor	1	Char	1 tph	40	1,000	SA-516-70	0.63 MM Cooling	Water-Cooled Screw	0.25
Y-603	Screw Lift Conveyor	1	Coal/Char	2 tph	atm		Carbon Steel	N/A		1
Y-604	Screw Mixer/Heater	1	Coal/Char	1.2 tph		120	High Alloy Steel	0.86 MM Heating	Gas-Fired	20

Materials Handling: Cyclones and Filters

Cyclones

Item No.	Item Name	Qty	<u>Design Conditions</u>		Material	<u>Maximum Dimensions</u>		<u>Minimum Thickness</u>	Weight (lb)
			Pres. (psig)	Temp. (°F)		I.D. (ft)	Ht. (ft)		
Y-101	Dryer Cyclone	1	40	700	SA-516-55	2	8	0.25	600
Y-102	Preheater Classifier	1	40	700	SA-516-55	2	8	0.25	600
Y-103	Coal Fines Cyclone	1	40	700	SA-516-55	2	8	0.25	600
Y-201	Char Heater Cyclone	1	40	2,200	CS, Refractory	1.7	6.8	0.25	1,170
Y-202	Primary Cyclone	1	40	1,200	CS, Refractory	2	7.9	0.25	800
Y-203	Secondary Cyclone	1	40	1,200	CS, Refractory	2	7.9	0.25	800

Filters

Item No.	Item Name	Qty	<u>Design Conditions</u>		Capacity	<u>Maximum Dimensions</u>		Description
			Pres. (psig)	Temp. (°F)		I.D. (ft)	Ht. (ft)	
Y-301	Tar Product Filters	2	80	450	10 gpm	0.1		Cartridge, SS Screen
Y-302	Quench Bypass Filter	1	80	450		1	2	Edge Type, Lube Oil
Y-401	Char Fines Dust Filter	1	0	200	1,000 scfh			
Y-402	Coarse Char Dust Filter	1	0	200	1,000 scfh			
Y-602	Dry Coal Dust Filter	1	0	200	2,000 scfh			

Fired Heaters

Item No.	Item Name	Qty	Heat Duty (Btu/hr)	Design Temp. (°F)	Design Pres. (psig)	Furnace Material	Comments	Approx. Wt (lb)
F-201	Gasifier Booster Heater	1	1.0 MM	3,000	40	CS, Refractory	Pressurized Burner	7,780
F-202	Char Heater	1	1.2 MM	2,200	40	CS, Refractory	1.0 ft I.D. x 60 ft Ht.	40,000
F-401	Incinerator	1	2.6 MM	1,400	15	CS, Refractory	Atmospheric Furnace	
F-601	Gas Heater	1	1.0 MM	3,300	20	CS, Refractory	Pressurized Burner	32,400
F-602	Incinerator	1	7.6 MM	1,400	15	CS, Refractory	Atmospheric Furnace	
Y-204	Thermal Cracker	1	1.2 MM	2,000	40	CS, Refractory	2,000 sq ft High Alloy Tubing	

Heat Exchangers and Air Coolers

Heat Exchangers

Item No.	Item Name	Qty	Type	Heat Duty (Btu/hr)		Tube Temp. (°F)		Tube Material	Surface Area (sq ft)	Shell Temp. (°F)		Shell Material
				In	Out	In	Out			In	Out	
E-201	Air Preheater	1	Shell/Tube	0.36 MM	200	890		Stainless	85	2,000	1,200	CS, Refractory
E-303	Light Oil Quench Cooler	1	Shell/Tube	0.25 MM	90	120		Admiralty	350	290	100	Carbon Steel
E-401	Recycle Gas Heat Recy	1	Furnace Tubes	0.50 MM	100	1,200		18 Cr-8 Ni	570	1,400	790	
E-402	Sodium Sulfite Cooler	1	Double Pipe	21.3 M	90	120		18 Cr-8 Ni	38	180	100	18 Cr-8 Ni
E-403	Nitrogen Cooler	1	Double Pipe	1.0 M	90	120		Carbon Steel	17	140	100	Carbon Steel
E-404	Dryer Gas Heat Recy	1	Furnace Tubes	1.0 MM	100	1,200		18 Cr-8 Ni	1,150	1,400	790	
E-405	Flue Gas Cooler	1	Shell/Tube	1.4 MM	90	120		Admiralty	800	430	100	Carbon Steel
E-601	Gas Cooler	1	Shell/Tube	0.50 MM	90	120		Admiralty	260	276	100	Carbon Steel

Air Coolers

Item No.	Item Name	Qty	Type	Heat Duty (Btu/hr)		Tube Temp. (°F)		Tube Material	Surface Area (sq ft)	Fan Driver (hp)	
				In	Out	In	Out				
E-301	Tar Quench Air Cooler	1	Induced Draft	1.58 MM	450	290		Carbon Steel	1,020	1	
E-302	Middle Oil Quench Cooler	1	Induced Draft	0.25 MM	450	170		Carbon Steel	664	0.25	

Pumps and Compressors

Item No.	Item Name	Qty	Service	Type	Capacity	Design Conditions					Driver (hp)
						Suct. Pres. (psia)	Discharge Pres. (psia)	Temp. (°F)	Δ P (psi)	Material	

Compressors

K-101	Dryer Recycle Blower	1	Flue Gas	Centrifugal	88.7 Mscfh	36	40	100	4	Carbon Steel	16
K-201	Air Compressor	1	Air	Centrifugal	26.5 Mscfh	15	42	240	27	Carbon Steel	45
K-301	Recycle Gas Compressor	1	Recy Gas	Reciprocating	37.0 Mscfh	32	40	210	8	Carbon Steel	15
K-401	Induced Draft Blower	1	Flue Gas	Centrifugal	132.0 Mscfh	12	15	200	3	Carbon Steel	52
K-402	Nitrogen Blower	1	Nitrogen	Centrifugal	0.65 Mscfh	14	20	116	6	Carbon Steel	0.5
K-403	Flue Gas Recy Compressor	1	Recy Gas	Reciprocating	54.0 Mscfh	15	42	427	27	Carbon Steel	118
K-601	Air Blower	1	Air	Centrifugal	2.3 Mscfh	15	22	120	7	Carbon Steel	1.5
K-602	Cool Gas Blower	1	Recy Gas	Centrifugal	23.0 Mscfh	15	22	276	7	Carbon Steel	13

Pumps

P-301	Tar Quench Pump	1	Tar	Reciprocating	40.0 gpm	33	83	450	50	Carbon Steel	2
P-302	Middle Oil Product Pump	1	Mid Oil	Centrifugal	20.0 gpm	33	62	170	29	Carbon Steel	0.5
P-303	Sludge Pump	1	Sludge	Reciprocating	0.5 gpm	80	100	450	20	Carbon Steel	0.25
P-401	Sodium Sulfite Soln Pump	1	Sod Sulf.	Metering	1.0 gpm	15	25	200	10	Plastic	0.25
P-501	Caustic Feed Pump	1	Caustic	Metering	1.0 gpm	0	15	60	15	Plastic	0.25
P-502	Spent Caustic Pump	1	Sod.Sulf.	Metering	1.0 gpm	0	15	100	15	Plastic	0.25
P-503	Sour Water Transfer Pump	1	Water	Centrifugal	20.0 gpm	15	25	100	10	Carbon Steel	0.25
P-504	Tar Product Transfer Pump	1	Tar/H.O.	Screw	30.0 gpm	15	35	500	20	Carbon Steel	0.5
P-505	Middle Oil Transfer Pump	1	Mid Oil	Centrifugal	20.0 gpm	15	25	200	10	Carbon Steel	0.25
P-506	Light Oil Transfer Pump	1	Lt. Oil	Centrifugal	20.0 gpm	15	25	100	10	Carbon Steel	0.25
P-601	Lignosulfonate Pump	1	Soln	Centrifugal	1 gpm	15	45	60	30	Carbon Steel	0.25

**APPENDIX C. Piping and Instrumentation Drawings and
Electrical One-Line Drawing**

PIPING AND INSTRUMENTATION DRAWINGS AND
ELECTRICAL ONE-LINE DRAWING

<u>Dwg. No.</u>	<u>Name</u>	<u>Revision</u>
A-00	Symbols and Legends	A
A-01	Coal Handling	B
A-02	Coal Drying	B
A-03	Gasifier Heat Supply	B
A-04	Gasifier	B
A-05	Hot Gas Fines Removal	B
A-06	Heavy Oil/Tar Recovery	B
A-07	Middle and Light Oil Recovery	B
A-08	Incinerator	B
A-09	Emission Control	B
A-10	Chemical Solution Storage and Handling	B
A-11	Coal-Oil Products Storage and Handling	B
A-12	Char and Coal Storage and Handling	B
A-13	Briquette Forming	B
A-14	Briquette Calcining	B
A-15	Calciner Air and Heat Supply	B
A-16	Process Utilities	
E-01	Preliminary Single-Line Diagram	A

This drawing and the design it covers are property of BECHTEL. They are hereby loaned and on the borrower's express agreement that they shall not be reproduced, copied, imitated, altered, or used except in the limited way and private use permitted by any written consent given by the lender to the borrower.

III-C-5

LEGEND

EQUIPMENT AND DRAWING INDEXES

INSTRUMENTATION

GROUP LETTER	GROUP	DESCRIPTION
A	GENERAL	PLOT PLAN, P&ID DIAGRAMS, MAPS, BASIC ENGINEERING DATA SHEETS, INDEXES
B	PROCESS	PROCESS DESIGN, FLOW DIAGRAMS, PROCESS DATA SHEETS, ETC.
C	COLUMNS AND PRESSURE VESSELS	PRESSURE VESSELS OF ANY PRESSURE DESIGNED IN ACCORDANCE WITH THE ASME CODE INCLUDING TOWERS, COLUMNS, REACTORS, REGENERATORS, SPHERES, DRUMS, ETC., INCLUDING TRAYS, LINERS, LINING, PACKING, INTERNALS AND APPURTENANCES.
D	TANKS	ALL STORAGE VESSELS OTHER THAN ASME CODE VESSELS. INCLUDES API ATMOSPHERIC OR LOW PRESSURE STORAGE TANKS, BINS, SPHEROIDS, HOPPERS, SILOS, ETC., INCLUDING INTERNALS AND APPURTENANCES.
E	EXCHANGERS	HEAT TRANSFER EQUIPMENT SUCH AS TUBULAR EXCHANGERS, CONDENSERS, EVAPORATORS, REBOILERS, COOLERS, FIN-FAN COOLERS AND COOLING TOWERS; EXCLUDES FIRED HEATERS.
F	FIRED HEATERS	FIRED HEATERS, FURNACES OVENS, BOILERS, FIRED KILNS AND DRYERS, INCLUDING SUPER-HEATERS, AIR PREHEATERS, TUBES, HEADERS, SETTINGS, BURNERS, STACKS, FLUES, INCLUDES FLARE STACKS AND FRAMEWORK, INCINERATORS.
G	PUMPS AND DRIVERS	INCLUDES ALL PUMPS AND THEIR DRIVERS. EQUIPMENT DRIVERS ARE NUMBERED GT OR GM DEPENDING ON WHETHER TURBINE OR MOTOR IS DRIVER.
J	INSTRUMENTS	ALL INSTRUMENTS AND CONTROL EQUIPMENT (EXCEPT ELECTRIC POWER SWITCHBOARDS, CONTROLS AND METERS), INCLUDING SAFETY (RELIEF) VALVES, MEASURING DEVICES, CONTROLLERS, CONTROL VALVES, INDICATORS, SIGHT GLASSES, ALARMS, INSTRUMENT PANELS, FITTINGS, CONTROL SIGNAL PNEUMATIC TUBING, AIR PIPING AND FILTERS, AND WINTERIZATION OF INSTRUMENTATION.
K	COMPRESSORS & DRIVERS	COMPRESSORS, EXPANDERS, BLOWERS, FANS, GEARS AND THEIR DRIVERS. SIMILAR TO LETTER G. EQUIPMENT DRIVERS ARE NUMBERED KT TO KM.
P	ELECTRICAL	ALL ELECTRICAL EQUIPMENT AND MATERIAL (EXCEPT PROCESS INSTRUMENTATION COVERED UNDER J GROUP). INCLUDES GENERATORS AND DRIVERS, MOTOR CONTROLS, SWITCHGEAR, TRANSFORMERS, CONVERTERS, RECTIFIERS, TRANSMISSION AND DISTRIBUTION, COMMUNICATION SYSTEMS, LIGHTING, GROUNDING, ALL NECESSARY WIRE AND CATHODIC PROTECTION.
T	MATERIAL HANDLING EQUIPMENT	BUCKET ELEVATOR, CONVEYORS, CRANES, HOISTS, CHUTES, FEEDERS, BAG HOUSES, WEIGHING DEVICES AND HOPPERS, SCALES, PACKAGING DEVICES, STAR VALVES, SLIDE VALVES, PNEUMATIC CONVEYORS AND ASSOCIATED EQUIPMENT.
V	PACKAGE UNITS	INCLUDES INTEGRAL 'PACKAGE' UNITS, SUCH AS AIR DRIERS, REFRIGERATION SYSTEMS, ETC., WHERE APPLICABLE. (A PACKAGE UNIT MR IS A 'V' MR BUT CAN CONTAIN ITEMS THAT ARE DESIGNATED ON EQUIPMENT LISTS UNDER OTHER LETTERS, E.G. CORROSION INHIBITOR PACKAGE CONTAINS PUMPS 'G' ITEMS.)
Y	PROCESSING	CRUSHERS, PULVERIZERS, BLENDERS, SCREENS, SEPARATORS, CYCLONES, FILTERS, CENTRIFUGES, MIXERS, GRINDERS, DRIERS (NOT FIRED) EXTRUDERS AND SIMILAR MACHINERY INCLUDING DRIVERS.
Z	WATER AND WASTE TREATMENT	ALL EQUIPMENT INTENDED SPECIFICALLY FOR TREATMENT OF WATER FOR GENERAL SUPPLY, COOLING WATER, BOILER FEED WATER, ETC., OR FOR TREATMENT OF WASTE WATER FOR POLLUTION CONTROL. INCLUDES CLARIFIERS, REACTORS, ION EXCHANGE EQUIPMENT, CHEMICAL FEEDERS, MIXERS, AGITATORS, STORAGE HOPPERS, LIQUID FILTERS, SETTLERS, CYCLE TIMER AND SPECIALTY CONTROLS.

FIRST LETTER

A - ANALYZER
F - FLOW
H - HAND
L - LEVEL
M - MOTOR
P - PRESSURE
S - SPEED
T - TEMPERATURE
U - MULTI-FUNCTION
V - VARIABLE
W - WEIGHT
Z - POSITION

FIRST LETTER MODIFIERS

D - DIFFERENTIAL
EXAMPLE: DPI-DIFFERENTIAL PRESSURE INDICATOR

SUCCEEDING LETTERS

A - ALARM
C - CONTROL(LER)
D - DRIVE, DAMPER
E - SENSING ELEMENT
G - GAUGE, GAUGE BOARD
H - HIGH, OPEN
I - INDICATOR
L - LOW, CLOSED, LIQUID
R - RECORDER
S - SWITCH, SPEED, SOLIDS
T - TRANSMITTER
V - VALVE
Y - SOLENOID

△																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																	
---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

DELIVERED CRUSHED COAL
(6 MESH X 0)

A simple line drawing of a truck with a crane arm. The truck has a rectangular body, two large circular wheels, and a crane arm extending from the back. The crane arm is composed of two segments: a longer one connected to the truck body and a shorter one at the end, which holds a rectangular weight.

FRONT END LOADER

T-101

T-103

T-102
COAL FEED CONVEYOR
TYPE: BELT-DRAG FEED
CAPACITY: 2 TPH
HP: 1

T-103
COAL LIFT CONVEYOR

CAPACITY:	2 TPH
LIFT:	20 FT
WIDTH:	6 INCH
SPEED:	150 FPM
HP:	1

This drawing and the design it covers are property of BCDITEL. They are hereby leased and on the borrower's express agreement that they will not be reproduced, copied, loaned, exhibited nor used in any way without the express written consent of BCDITEL. The borrower shall indemnify and hold BCDITEL harmless from and against all claims, damages, losses and expenses, including reasonable attorney's fees, which may be asserted against or incurred by BCDITEL as a result of the borrower's use of the design or design drawings. The borrower shall not make any copies of the design or design drawings for any other person or entity. The borrower shall not use the design or design drawings for any other purpose than that for which they were originally intended. The borrower shall not use the design or design drawings for any other purpose than that for which they were originally intended. The borrower shall not use the design or design drawings for any other purpose than that for which they were originally intended.

CAPACITY: 1 TON
PRESS. 42 PSIG
TEMP. 100°F
MATERIAL: SA-516-70
SIZE: 3'-1" DIA x 6'-2" T-T
WEIGHT: 1250 LBS

1. ALL MAJOR EQUIPMENT TO HAVE LOCAL JOG / EMERGENCY STOP.
2. ALL VENT AND DRAIN CONNECTIONS OPEN TO ATMOSPHERE SHALL BE CAPPED OR PLUGGED.

SECRET

	9-25 -91	ISSUED FOR DRAFT FINAL REPORT							
	2-13 -91	ISSUED FOR INTERNAL REVIEW							
NO.	DATE		BY	CHKD	RECD	FILED	INDEXED	SEARCHED	SERIALIZED
NONE		AMS		YS/ACAD					
BECHTEL NATIONAL, INC.									
SAN FRANCISCO									
IGT PROCESS DEVELOPMENT UNIT									
MILD GASIFICATION AND FORM COKE PRODUCTION									
PIPING AND INSTRUMENT DIAGRAM									
COAL HANDLING									
	JOB NO.		DRAWING NO.				REV.		
	19369		A-01				B		

Y-101 DRYER CYCLONE

SIZE: 2'-0" DIA x 8' H
PRESS: 40 PSIG
TEMP: 700°F
MATERIAL: SA-516-55
INLET PRESS: 21 PSIG
INLET VELOCITY: 60 F/S
PRESS DROP: 0.5 PSI
WEIGHT: 600 LBS

C-103 COAL DRYER

CAPACITY: 1 TPH
PRESS: 40 PSIG
TEMP: 500°F
MATERIAL: 8" SCH 40 PIPE
SIZE: 8' I.D. x 60' H
WEIGHT: 1450 LBS

C-105 PREHEATER SURGE VESSEL

CAPACITY: 0.5 TONS
SIZE: 2'-0" DIA x 7'-11" H
PRESS: 42 PSIG
TEMP: 500°F
MATERIAL: SA-516-70
WEIGHT: 740 LBS

C-104 COAL PREHEATER

CAPACITY: 1 TPH
PRESS: 40 PSIG
TEMP: 500°F
MATERIAL: 8" SCH 40 PIPE
SIZE: 8' I.D. x 60' H
WEIGHT: 1450 LBS

Y-102 PREHEAT

SIZE: 2'-0" DIA x 8' H
PRESS: 40 PSIG
TEMP: 700°F
MATERIAL: SA-516-55
INLET PRESS: 21 PSIG
INLET VELOCITY: 60 F/S
PRESS DROP: 0.5 PSI
WEIGHT: 600 LBS

used except in the limited way and private use permitted by any written consent given by the lender to the borrower.

TPH
3 PSIG
20°F
- SCH 40 PIPE
- I.D. x 60' H
- 50 LBS

PREHEATER CLASSIFIER

SIZE:	2'-0" DIA x 8' F
PRESS:	40 PSIG
TEMP:	700°F
MATERIAL:	SA-516-55
INLET PRESS:	24 PSIG
INLET VELOCITY:	60 F/S
PRESS DROP:	0.5 PSI
WEIGHT:	600 LBS

CLASSIFIER SURGE VES
CAPACITY: 0.5 TONS
SIZE: 2'-0" DIA x 7'-11" H
PRESS: 42 PSIG
TEMP: 500°F
MATERIAL: SA-516-70
WEIGHT: 740 LBS

COAL FINES CYCLONE

SIZE:	2'-0" DIA x 1'
PRESS:	40 PSIG
TEMP:	700°F
MATERIAL:	SA-516-55
INLET PRESS:	24 PSIG
INLET VELOCITY:	60 F/S
PRESS DROP:	0.5 PSI
WEIGHT:	600 LBS

FINES SURGE VESSEL

CAPACITY:	0.5 TONS
SIZE:	2'-0" DIA x 7'-11" H
PRESS:	42 PSIG
TEMP:	500°F
MATERIAL:	SA-516-70
WEIGHT:	740 LBS

1. ■ DENOTES DRIVER SUPPLIED WITH VALVE
2. ALL VENT AND DRAIN CONNECTIONS OPEN TO THE ATMOSPHERE SHALL CAPPED OR PLUGGED.
3. CONTROL VALVE BYPASS ARRANGEMENT TYPICAL FOR FCV-103, TCV-201, FCV-103, FCV-104A & B, AND FCV-101.

PRELIMINARY

[illegible]

E-201 AIR PREHEATER

HEAT DUTY: 0.36 MM BTU/HR
TUBE TEMP: IN 200°F/OUT 890°F
SHELL TEMP: IN 2000°F/OUT 1200°F
SHELL MATL: CS. REF. LINED
TUBE MATL: SA-240.316SS
SURFACE AREA: 85 SQ. FT.

F-202 CHAR HEATER

HEAT DUTY: 1.2 MM BTU/HR
PRESS: 40 PSIG
TEMP: 2200°F
MATERIAL: 12" SCH 40 PIPE
LINING: 3'-6" CASTABLE REF.
SIZE: 1' I.D. x 50' H
WEIGHT: 5000 LBS REFRACTORY

Y-201 CHAR HEATER CYCLONE

PRESS: 40 PSIG
TEMP: 2200°F
MATERIAL: CS.
LINING: 3" CASTABLE REF.
SIZE: 1'-8" I.D. x 6'-10" H
WEIGHT: 700 LBS W/REF.

This drawing and the design it covers are property of BECHTEL. They are hereby loaned and on the borrower's express agreement that they will not be reproduced, copied, loaned, exhibited, nor used except in the limited way and private use permitted by any written consent given by the lender to the borrower.

This drawing and the design it covers are property of BECHTEL. They are hereby loaned and on the borrower's express agreement that they will not be reproduced, copied, loaned, exhibited nor used except in the limited way and private use permitted by any written consent given by the lender to the borrower.

C-201 RETORT GASIFIER

ENTRAINED SECTION: 1'-3" ID x 16'-0" H
BUBBLING BED: 2'-6" ID x 25'-0" H
BASE: 1'-3" ID
MAT'L'S: CS/REF. LINING
WEIGHT: 12,000 LBS

INING

CAPACITY: 700 LBS
PRESS: 41 PSIG
TEMP: 1,000°F
MATERIAL: SA-516-70
SIZE: 2'-2" ID x 4'-5" H
WEIGHT: 640 LBS

NOTES:

1. PURGE SYSTEM PROVIDED WITH ALL NECESSARY VALVES, ROTAMETERS AND OTHER ITEMS.

P R E L I M I N A R Y

	3-25 -91	ISSUED FOR DRAFT FINAL REPORT				07M	M 66
	2-13 -91	ISSUED FOR INTERNAL REVIEW				AMS	
IN	DATE		BY	REVIEW	CHECKED	APPROVED	
CODE	NONE	PROCESS	AMS	SUBJECT	YS/ACAD	GROUP	
BECHTEL NATIONAL, INC. SAN FRANCISCO							
IGT PROCESS DEVELOPMENT UNIT MILD GASIFICATION AND FORM COKE PRODUCTION							
PIPING AND INSTRUMENT DIAGRAM GASIFIER							
	JOB NO.	DRAWING NO.	REV				
	19369	A-04	B				

1007065.DVG 1

Y-202 PRIMARY CYCLONE

PRESS: 40 PSIG
TEMP: 1200°F
MATERIAL: CS
LINING: 3" CASTABLE REF.
SIZE: 1'-5" ID x 5'-8" H
WEIGHT: 500 LBS REF.

Y-203 SECONDARY CYCLONE

PRESS: 40 PSIG
TEMP: 1200°F
MATERIAL: CS
LINING: 3" CASTABLE REF.
SIZE: 1'-5" ID x 5'-8" H
WEIGHT: 500 LBS REF.

C-203 CHAR FINES BLOWCASE

CAPACITY: 204 LBS
PRESS: 41 PSIG
TEMP: 1000°F
MATERIAL: SA-516-70
SIZE: 1'-6" ID x 2'-11" H
WEIGHT: 270 LBS

This drawing and the design it covers are property of BECHTEL. They are hereby loaned and on the borrower's express agreement that they will not be reproduced, copied, loaned, emitted, nor used except in the limited way and private use permitted by any written consent given by the lender to the borrower.

DUTY: 1.2 MMBTU/HR
PRESS: 40 PSIG
TEMP: 2000°F
TUBE MATL: HI ALLOY STEEL
SA: 2000 SQ FT

DUTY: 1.2 MMBTU/HR
PRESS: 40 PSIG
TEMP: 2000°F
TUBE MATL: HI ALLOY STEEL
SA: 2000 SQ FT

NOTES:

1. ALL VENT AND DRAIN CONNECTIONS OPEN TO THE ATMOSPHERE SHALL CAPPED OR PLUGGED.
2. LENGTH OF LOOP CHANGEABLE TO MEET RESIDENCE TIME REQUIREMENTS.
3. SPACE RESERVED FOR FUTURE DEMONSTRATION OF HOT GAS FILTERING.

PRELIMINARY

[illegible]

C-304

TAR QUENCH CONDENSER
 PRESS: 40 PSIG
 TEMP: 1800°F
 MATERIAL: HIGH ALLOY STEEL
 SIZE: 2'-6" ID x 0'-8" H (TOP)
 1'-0" ID x 2'-6" H (BOTTOM)
 WEIGHT: 480 LBS

C-301

TAR SEPARATOR
 CAPACITY: 40 LBS
 PRESS: 40 PSIG
 TEMP: 1000°F
 MATERIAL: SCH 40 PIPE
 SIZE: 1'-7" ID x 3'-0" H (TOP)
 0'-8" ID x 2'-0" H (BOTTOM)
 WEIGHT: 630 LBS

E-301

TAR QUENCH AIR COOLER
 HEAT DUTY: 1.58 MM BTU/HR
 TUBE TEMP: IN 450°F/OUT 290°F
 TUBE MATL: CS
 SA: 1020 SQ FT
 HP: 1

Y-302

QUENCH
 TYPE:
 CAPACITY:
 PRESS:
 TEMP:
 SIZE:

This drawing and the design it covers are property of BCHILL. They are merely loaned and on the borrower's express agreement to return them to the lender. They are not to be reproduced, copied, or otherwise used except in the limited way and provide use permitted by any written consent given by the lender to the borrower.

Y-301A/B
TAR PRODUCT FILTERS

TYPE:	CARTRIDGE
SIZE:	1" PIPE SIZE
FILTER MATL:	SS
PRESS:	80 PSIG
TEMP:	450°F

NOTES:

1. ALL VENT AND DRAIN CONNECTIONS OPEN TO THE ATMOSPHERE SHALL CAPPED OR PLUGGED.
2. CONTROL VALVE BYPASS ARRANGEMENT TYPICAL FOR PCV-302 & PCV-303.
3. INTERMITTENT MANUAL OPERATION AS INDICATED BY PI-304.
4. FILTERS ARE CYCLED DURING OPERATION FOR CLEANING AS INDICATED BY PI-305. FILTERS ARE STANDARD MANUAL SWITCHING DUPLEX FILTERS WITH HYDROCARBON CARTRIDGES.
5. ■ INDICATES INSTRUMENTS AND/OR CONTROLS SUPPLIED WITH EQUIPMENT.
6. PRESSURE DROP COIL IS USED TO INDICATE THAT ALL SLUDGE IS PUMPED OUT OF Y-302.

PRELIMINARY

	3-23 -91	ISSUED FOR DRAFT FINAL REPORT				CAL	JL
	2-13 -91	ISSUED FOR INTERNAL REVIEW				AMS	
IN	DATE		BY	NAME	REVIEW	DATE	REV
NO.	NONE	AMC	YS/MAD				
BECHTEL NATIONAL, INC.							
SAN FRANCISCO							
IGT PROCESS DEVELOPMENT UNIT							
MILD GASIFICATION AND FORM COKE PRODUCTION							
PIPING AND INSTRUMENT DIAGRAM							
HEAVY OIL / TAR RECOVERY							
	JOB NO.	DRAWING NO.				REV	
	19369	A-06				B	

E-302
MIDDLE QUENCH AIR COOLER
DUTY: 247 MM BTU/HR
TUBE TEMP: IN 450°F/OUT 170°F
TUBE MATL: CS
SA: 664 SQ FT
HP: 1/4

C-302
MIDDLE OIL SEPARATOR
CAPACITY: 13 LBS.OIL
TEMP: 500°F
PRESS: 40 PSIG
MATERIAL: SCH 40 PIPE
SIZE: 1'-2" ID x 2'-0" H (TOP)
0'-6" ID x 1'-0" H (BOTTOM)
WEIGHT: 290 LBS

C-303
LIGHT OIL SEPARATOR
CAPACITY: 18 LBS/WATER
TEMP: 200°F
PRESS: 40 PSIG
MATERIAL: SCH 40 PIPE
SIZE: 1'-2" ID x 2'-0" L (TOP)
0'-4" ID x 3'-6" H (BOTTOM)
WEIGHT: 240 LBS

This drawing and the design it covers are property of McMillan. They are hereby loaned and on the condition that they are not to be used except in the limited way and private use permitted by any written consent given by the lender to the borrower.

This drawing and the design it covers are property of MCWETEL. They are hereby loaned and on the borrower's express agreement that they will not be reproduced, copied, loaned, exhibited nor used except in the limited way and private use permitted by any written consent given by the lender to the borrower.

K.O. DRUM
80 LBS
40 PSIG
100°F
SA-S16-70
1'-2" ID x 3'-3" H
200 LBS

E-405
FLUE GAS COOLER
DUTY: 1.36 MM BTU/HR
PRESS: 45 PSIG
SHELL MATL: CS
TUBE MATL: ADMIRALITY
SA: 800 SQ FT

C-401 SCRUBBER

PRESS: ATM
TEMP: 200°F
SIZE: 3'-2" ID x 30'-0" H
MATL: SS (TRAY)/CS (COLUMN)
WEIGHT: 4000 LBS

P-401
SODIUM SULFITE
SOLUTION PUMP
TYPE: METERING
CAPACITY: 1 GPM
DELTA P: 10 PSI
HP: 1/4

This drawing and the design it covers are property of ALLIANCE. It may not be copied, reproduced, or used except in the limited way and private use permitted by any written consent given by the lender to the borrower.

DUTY: 21.3 MDTU/HR
TEMP: 140°F/100°F (SHELL
90°F/120°F (TUBE)
MATL: 1B CR-8 NI (SA-240)
SA: 38 SQ FT

1. ALL VENT AND DRAIN CONNECTIONS OPEN TO THE ATMOSPHERE SHALL CAPPED OR PLUGGED.
2. CONTROL VALVE BYPASS ARRANGEMENT TYPICAL FOR FCV-405, LCV-403A & LCV-403B

PRELIMINARY

[illegible]

BECHTEL NATIONAL, INC.
SAN FRANCISCO

IGT PROCESS DEVELOPMENT UNIT
MILD GASIFICATION AND FORM COKE PRODUCTION

PIPING AND INSTRUMENT DIAGRAM EMISSION CONTROL

JOB NO.	DRAWING NO.	REV.
	19369	A-09	B

1008063.DWG 1

D-501
CAUSTIC STORAGE TANK
CAPACITY: 6,000 GAL
PRESS: ATM
TEMP: 100°F
MATL: CS/RUBBER LINED
SIZE: 10'-2" ID x 10'-2" H
WEIGHT: 9,700 LBS

D-502
SPENT CAUSTIC STORAGE TANK
CAPACITY: 6,000 GAL
PRESS: ATM
TEMP: 100°F
MATL: CS/RUBBER LINED
SIZE: 10'-2" ID x 10'-2" H
WEIGHT: 9,700 LBS

D-503
SOUR WATER
CAPACITY: 1,500
PRESS: ATM
TEMP: 200
MATL: CS
SIZE: 6'-0"
WEIGHT: 3,800

This drawing and the design it covers are property of ALKALINE. They are not to be used or reproduced in any way without the written consent given by the lender to the borrower.

D-503
SOUR WATER STORAGE TANK
CAPACITY: 1500 GAL
PRESS: ATM
TEMP: 200°F
MATL: CS
SIZE: 6'-4" ID x 6'-4" H
WEIGHT: 3870 LBS

D-602
LIGNOSULFONATE SOLUTION
STORAGE TANK
CAPACITY: 500 GAL
PRESS: 15 PSIG
TEMP: 100°F
MATL: CS
SIZE: 4'-5" ID x 4'-5" H
WEIGHT: 1860 LBS

P-503
SOUR WATER
TRANSFER PUMP
CAPACITY: 20 GPM
DELTA P: 25 PSI
H.P.: 1/4

P-601
LIGNOSULFONATE
SOLUTION PUMP
CAPACITY: 30 GPM
DETLA P: 30 PSI
HP: 1

TRUCK DELIVERY

NOTES:

1. ALL VENT AND DRAIN CONNECTIONS OPEN TO THE ATMOSPHERE SHALL CAPPED OR PLUGGED.

PRELIMINARY

	3-25 -91	ISSUED FOR DRAFT FINAL REPORT						AMS	70% 60%
	2-13 -91	ISSUED FOR INTERNAL REVIEW						AMS	
REV	DATE			BY	AMT	DESIGN REPLY		CHECKED	APPROVED
SCALE	NONE	SHEETING	AMS	DRAWING	YS/ACAD				
BECHTEL NATIONAL, INC. SAN FRANCISCO									
IGT PROCESS DEVELOPMENT UNIT MILD GASIFICATION AND FORM COKE PRODUCTION									
PIPING AND INSTRUMENT DIAGRAM CHEMICAL SOLUTION STORAGE AND HANDLING									
	JOB NO.	DRAWING NO.						REV.	
	19369	A-10						B	

1010065.DWG 1

D-507
TAR PRODUCT RUN TANK
 CAPACITY: 600 GAL
 PRESS: ATM
 TEMP: 500°F
 MATL: CS
 SIZE: 3'-8" ID x 7'-5" H
 WEIGHT: 1760 LBS

D-504
TAR PRODUCT STORAGE TANK
 CAPACITY: 32,000 GAL
 PRESS: ATM
 TEMP: 500°F
 MATL: CS
 SIZE: 17'-7" ID x 17'-7" H
 WEIGHT: 30,000 LBS

D-508
MIDDLE OIL RUN TANK
 CAPACITY: 250 GAL
 PRESS: ATM
 TEMP: 500°F
 MATL: CS
 SIZE: 2'-10" ID x 5'-6" H
 WEIGHT: 980 LBS

D-505
MIDDLE OIL
 CAPACITY: 12,000
 PRESS: ATM
 TEMP: 500°F
 MATL: CS
 SIZE: 12'-6" ID x 17'-7" H
 WEIGHT: 15,500

This drawing and the design it covers are property of the lender to the borrower. It is to be used except in the limited way and private use permitted by any written consent given by the lender to the borrower.

CAPACITY: 12,000 GAL
 PRESS: ATM
 TEMP: 500°F
 MATL: CS
 SIZE: 12'-8" ID x 5'-6" H
 WEIGHT: 15,500 LBS

CAPACITY: 100 GAL
PRESS: ATM
TEMP: 200°F
MATL: CS
SIZE: 2'-0" ID x 4'-11" H
WEIGHT: 530 LBS

CAPACITY: 5,200 GAL
PRESS: ATM
TEMP: 200°F
MATL: CS
SIZE: 9'-7" ID x 4'-7" H
WEIGHT: 8.860 LBS

1. ALL VENT AND DRAIN CONNECTIONS OPEN TO THE ATMOSPHERE SHALL BE CAPPED OR PLUGGED.
2. PUMP SUCTION PREHEATER, TIC-501, PROVIDED WITH P-504 COMPLETE WITH ALL CONTROLS.
2. HEAT TRACING SHALL KEEP PROCESS FLUID AT 250°F.

LIBRARY

	3-25 -91	ISSUED FOR DRAFT FINAL REPORT							
	2-13 -91	ISSUED FOR INTERNAL REVIEW							
DATE	APPROVED BY	REVIEWED BY	DATE	APPROVED BY	REVIEWED BY	DATE	APPROVED BY	REVIEWED BY	DATE
NONE	AHS	YS/ACAD							
BECHTEL NATIONAL, INC. SAN FRANCISCO									
IGT PROCESS DEVELOPMENT UNIT MILD GASIFICATION AND FORM COKE PRODUCTION									
PIPING AND INSTRUMENT DIAGRAM COAL OIL PRODUCTS STORAGE AND HANDLING									
	JOB NO.	DRAWING NO.	REV.						
	19369	A-11	B						

CAPACITY: 20 GPM
DETLA P: 10 PSI
H.P.: 1/4

CAPACITY: 20 GPM
DETLA P: 10 PSI
H.P.: 1/4

Y-601
DRY COAL DUST FILTER
 CAPACITY: 2000 SCFH
 PRESS: 12"VC
 TEMP: 200°F
 SIZE:
 MATERIAL:
 WEIGHT:

D-601
DRY COAL STORAGE
 CAPACITY: 17.4 TONS
 PRESS: 20 PSIG
 TEMP: 200°F
 SIZE: 8'-1" ID x 17'-0" H
 MATERIAL: SA-516-70
 WEIGHT: 120 LBS

Y-401
CHAR FINES FILTER
 CAPACITY: 5000 SCFH
 PRESS: 12"VC
 TEMP: 200°F
 SIZE:
 MATERIAL:
 WEIGHT:

D-401
CHAR FINES SURGE HOPPER
 CAPACITY: 3.9 TONS
 PRESS: 20 PSIG
 TEMP: 200°F
 SIZE: 4'-11" ID x 9'-10" H
 MATERIAL: SA-516-70
 WEIGHT: 3,100 LBS

This drawing and the design it covers are property of the lender to the borrower. used except in the letter way and private use permitted by any written consent given by the lender to the borrower.

T-601
DRY COAL TRANSPORT CONTAINER
 TYPE: DUMPSTER
 CAPACITY: 140°F
 TEMP:
 SIZE:

T-401
CHAR FINES TRANSPORT CONTAINER
 TYPE: DUMPSTER
 CAPACITY: 140°F
 TEMP:
 SIZE:

T-402
COARSE CHAR CONTAINER
 TYPE: DUMPSTER
 CAPACITY: 140°F
 TEMP:
 SIZE:

E-403
NITROGEN COOLER
DUTY: 1 MBTU/HR
PRESS: 40 PSIG

T-402
COARSE CHAR TRANSPORT
CONTAINER
TYPE: DUMPSTER
CAPACITY:
TEMP: 140°F
SIZE:

K-402
NITROGEN BLOWER
CAPACITY: 650 SCFH
DELTA P: 6 PSI
HP: 1/2

NOTES:

1. ALL INSTRUMENTS CONTROLS AND VALVES PROVIDED WITH EQUIPMENT ITEM.
2. ■ DENOTES ITEM IS PROVIDED WITH EQUIPMENT ITEM.
3. ALL VENT AND DRAIN CONNECTIONS OPEN TO THE ATMOSPHERE SHALL CAPPED OR PLUGGED.

APPENDIX

[illegible]

This drawing and the design it covers are property of MECHEL. They are hereby loaned and on the borrower's express agreement that they will not be reproduced copied loaned exhibited nor used except in the limited way and private use permitted by any written consent given by the lender to the borrower.

Y-602
FEED GRINDER
CAPACITY: 2 TPH
TEMP: 200°F
MATL:
SIZE:
HP: 20

Y-604
SCREW MIXER/HEAT
CAPACITY: 1.2 TPH
DUTY: 0.66 MBTU/HR
MATL: HIGH ALLOY ST
SA: 300 SQ FT
HP: 20

Y-603
SCREW LIFT CONVEYOR
CAPACITY: 2 TPH
LIFT:
H.P.: 1

8

7

6

5

MIXER/HEATER
1.2 TPH
0.66 MBTU/HR
HIGH ALLOY STEEL
300 SQ FT
20

Y-605
HOT ROLL BRIQUETTER
CAPACITY:
PRESS: ATM
TEMP: 1000°F
MATL:
SIZE:
HP: 50

PRELIMINARY

△									
△									
△									
△	3-25	ISSUED FOR DRAFT							
△	-91	FINAL REPORT							
△	2-13	ISSUED FOR INTERNAL REVIEW							
△	-91								
△	NONE	AMC			YS/ACAD				
BECHTEL NATIONAL, INC. SAN FRANCISCO									
IGT PROCESS DEVELOPMENT UNIT MILD GASIFICATION AND FORM COKE PRODUCTION									
PIPING AND INSTRUMENT DIAGRAM BRIQUETTE FORMING									
BECHTEL	JOB NO.	DRAWING NO.		REV.					
	19369	A-13		B					

1013065.dwg 1

This drawing and the design it covers are property of BECHTEL. They are hereby loaned and on the borrower's express agreement that they will not be reproduced, copied, loaned, exhibited nor used except in the limited way and private use permitted by any written consent given by the lender to the borrower.

C-601
VERTICAL CALCINER
 CAPACITY: 2 TONS
 PRESS: 25 PSIG
 TEMP: 200°F
 MATL: CS (REFRACTORY LINED)
 SIZE: 3'-2" ID x 12'-6" H
 WEIGHT: 3,300 LBS

Y-606
VIBRATING FEEDER
 CAPACITY:
 TEMP:
 MATL: CS
 SIZE: 2
 HP: 2

T-602
FINES TRANSPORT CONTAINER
 CAPACITY:
 TYPE: DUMPSTER
 MATL: CS
 SIZE:

T-603
BRIQUETTE TRANSPORT CONTAINER
 CAPACITY:
 TYPE: CARGO CONTAINER
 MATL: CS
 SIZE:

C-602
LOCK HOPPER
CAPACITY: 0.56 TONS
PRESS: 20 PSIG
TEMP: 500°F
MATL: CS
SIZE: 2'-7" ID x 5'-2" H
WEIGHT: 850 LBS

	3-25 -91	ISSUED FOR DRAFT FINAL REPORT						OK'd J160
	2-13 -91	ISSUED FOR INTERNAL REVIEW						AMS
DATE	TIME		BY	RECD	FILED	INDEXED	SERIALIZED	APPROVED
NAME	NONE	NUMBER	AMS	NUMBER	YS/ACAD			
BECHTEL NATIONAL, INC.								
SAN FRANCISCO								
IGT PROCESS DEVELOPMENT UNIT								
MILD GASIFICATION AND FORM COKE PRODUCTION								
PIPING AND INSTRUMENT DIAGRAM								
BRIQUETTE CALCINING								
	JOB NO.	DRAWING NO.					REV.	
	19369	A-14					B	

F-602 INCINERATOR

DUTY: 7.6 MM BTU/HR
TEMP: 1400°F
MATL: CS/REFRACTORY LINED
SIZE: 32,400 LBS

F-601 GAS HEATER

DUTY: 1 MM BTU/HR
TEMP: 3,300°F
MATL: CS/REFRACTORY LINED
SIZE: 6'-4"L x 6'-4"W x 10'-10"H
WEIGHT: 8,000 LBS

This drawing and the design it covers are the property of the lender and its use is permitted by any written consent given by the lender to the borrower.

K-601 AIR BLOWER

CAPACITY: 2.3 MSCFH
DELTA P: 7 PSI
TEMP: 120°F
H.P.: 1.5

DUTY: 0.5 MM BTU/HR
TEMP: 90°F/120°F TUBE
270°F/100°F SHELL
MATL: CS SHELL
ADMIRALTY TUBE
SA: 260 SQ FT

WATER SEPARATOR

CAPACITY:	30 LBS
PRESS:	20 PSIG
TEMP:	500°F
MATL:	CS
SIZE:	2'-8" ID x 6'-2" H
WEIGHT:	120 LBS

1. CONTROL VALVE BYPASS ARRANGEMENT
TYPICAL FOR FCV-601, FCV-602 & FCV-605

DEKLY

[illegible]

This drawing and the design it covers are property of McMillan. They are hereby loaned and not to be reproduced or used except in the limited way and private use permitted by any written consent given by the lender to the borrower.

POWER & LIGHTING

SERVICE

T-203	CHAR FINE COOLER CONVEYOR
P-303	SLUDGE PP
P-501	CAUSTIC FD METERING PP
P-503	SOUR WATER TXFR PP
SPARE	
SPARE	
SOLENOIDS - PLANTS 1 & 2	
PDU RECEPTACLES #1	
LIGHTING #1	
LIGHTING - EXTERIOR	
SPARE	
SPARE	
HVAC UNIT #1 (IN WALL)	
K-901 PLANT AIR COMPRESSOR	
SPARE	
SPARE	
SPARE	
TXFR AND PANEL OUTSIDE MCC-"1"	

INSTRUMENT & COMP

SERVICE

COMPUTER #1
INSTRUMENTS #1
ANALYZERS #1
SPARE
SPARE
TXFR AND PANEL OUTSIDE MCC-"1"

1

APPENDIX D. PDU Cost Savings Opportunities

PDU COST SAVINGS OPPORTUNITIES

During the development of the P&IDs, modifications with a potential for reducing the procurement, installation, and operating costs of the PDU were noted. These modifications are documented below and should be considered in the final facility design.

Modifications	Remarks
1. Eliminate the coal feed lock hopper (C-101) and use the coal feed hopper (Y-104) as a loss-in-weight feeder to the system	Coal can be metered into the system with sufficient accuracy for material balance calculations from the feed hopper. The coal feed lock hopper is then redundant and can be eliminated
2. Procure the coal and char handling, drying, preheating, and storage as packaged units	Delivering feed to gasifier at the required temperature and pressure will present a significant engineering challenge. Procuring these units as systems will allow a greater degree of participation by vendors in the design phase and thereby make better use of their experience
3. Replace the coal-oil product storage tanks (D-504, D-505, and D-506) with DOT-approved trailers. Trailers may also be provided by the refinery/research organization investigating the commercial use of the products as a part of a separate agreement. Otherwise, an allowance for trailer rental will need to be added.	<p>Reduces capital costs and space requirements</p> <p>Allows for an easier permitting of facility operating since products are not stored on site</p> <p>Storage, evaluation, and disposal of products can probably be done better at an existing refinery and/or hydrocarbon research center. Early identification of such a facility eliminates the possibility that no such facility can be found after PDU operation and that the material (especially tar/pitch product) will then have to be disposed of as hazardous waste</p>

Modifications	Remarks
4. If Recommendation 3 is not acceptable, reduce the requirement for 6 months of storage capacity of coal-oil products at the site	Reduce capital costs, notably of that of the tar product storage tank (D-504)
	May ease permitting requirements if these are defined as a function of duration and/or amount of storage
	Reduces the potential for work needed to separate gasification products from products suitable for sale or use by others. This is accomplished by not mixing products of startup from those intended for commercial use
5. Use the cooled combustion products out of the water knowkout drum (C-402) for purging, gas blanketing, and other inert gas service	Reduces or eliminates the need for nitrogen
	A larger flue gs cooler (E-405) and a new receiver may be required
6. Investigate the use of DOE excessed property	May reduce cost, but costs for reconditioning equipment and availability of the equipment must be considered

**DATE
FILMED
06/30/92**