**Idaho
National
Engineering
Laboratory**

*Managed
by the U.S.
Department
of Energy*

*Work performed under
DOE Contract
No. DE-AC07-76ID01570*

EGG-SSRE-9549
November 1983

APR 27 1992
1992/04/27

COMPONENT EXTERNAL LEAKAGE AND RUPTURE FREQUENCY ESTIMATES

S. A. Eide
S. T. Khericha
M. B. Calley
D. A. Johnson
M. L. Marteeny

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

This document contains new concepts or the author(s) interpretation of new calculations and/or measurements; accordingly, EG&G Idaho, Inc. is required by the United States Government to include the following disclaimer:

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product or process disclosed, or represents that its use would not infringe privately owned rights. References herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

EGG-SSRE--9639

DE92 012357

COMPONENT EXTERNAL LEAKAGE AND RUPTURE FREQUENCY ESTIMATES

S. A. Eide, S. T. Khericha,
M. B. Calley, D. A. Johnson,
and M. L. Marteeny

November 1991

Idaho National Engineering Laboratory
EG&G Idaho, Inc.
Idaho Falls, Idaho 83415

Prepared for the
U.S. Department of Energy
Under DOE Contract No. DE-AC07-76ID01570

REGISTER

ds
DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

EXECUTIVE SUMMARY

In order to perform detailed internal flooding risk analyses of nuclear power plants, external leakage and rupture frequencies are needed for various types of components - piping, valves, pumps, flanges, and others. However, there appears to be no up-to-date, comprehensive source for such external leakage and rupture frequency estimates. This report attempts to fill that void. Based on a comprehensive search of Licensee Event Reports (LERs) contained in Nuclear Power Experience, and based on estimates of component populations and exposure times, component external leakage and rupture frequencies were generated. Results are presented in Table ES-1.

Review of the LER data indicated the following:

- There appears to be no significant difference in external leakage or rupture frequencies between piping with diameters less than three inches and larger piping.
- There appears to be no significant difference between pressurized water reactor (PWR) and boiling water reactor (BWR) component external leakage and rupture frequencies.
- It is possible to distinguish between external rupture frequencies for components in primary coolant systems (PCSs) and external rupture frequencies for components in other systems. This difference may be the result of better inspection and leak detection methods for PCS components. (No significant difference in external leakage frequencies exists between the two classes of components.)
- External rupture frequencies generally are factors of 25 or 100 times lower than external leakage frequencies and are dependent on the type of component and whether the component is in the PCS.

Table ES-1. Recommended component external leakage and rupture frequencies

<u>Component/Failure Mode</u>	<u>Mean Frequency (Error Factor)</u>
Piping (including elbows)	
Leakage	3.0E-9/h-ft(10)
Rupture	1.2E-10/h-ft(30)(non-PCS) ^a 3.0E-11/h-ft(30)(PCS) ^b
Valve	
Leakage	1.0E-8/h(10)
Rupture	4.0E-10/h(30)(non-PCS) 1.0E-10/h(30)(PCS)
Pump	
Leakage	3.0E-8/h(10)
Rupture	1.2E-9/h(30)(non-PCS) 3.0E-10/h(30)(PCS)
Flange	
Leakage	1.0E-8/h(10)
Rupture	1.0E-10/h(10)(non-PCS and PCS)
Heat exchanger	
Tube	
Leakage	1.0E-7/h(10)
Rupture	4.0E-9/h(30)(non-PCS) 1.0E-9/h(30)(PCS)
Shell	
Leakage	1.0E-8/h(10)
Rupture	4.0E-10/h(30)(non-PCS) 1.0E-10/h(30)(PCS)
Tank	
Leakage	1.0E-8/h(10)
Rupture	4.0E-10/h(30)(non-PCS) 1.0E-10/h(30)(PCS)
a. For components not in the primary coolant system b. For components in the primary coolant system	

- The reduced reporting requirements for LERs, initiated in 1981, affects the number of events being reported each year. Therefore, external leakage and rupture frequency estimates are based on data from 1960 through 1983.

In order to correctly use the information in Table ES-1, the following definitions should be kept in mind:

- External leakage and rupture refer to events in which the coolant within the component escapes to the outside environment. (Events involving coolant leakage past a closed valve disk are not found in this report. Such events are termed internal leakages.)
- External rupture is defined as a leakage greater than 50 gpm or a complete severance of a pipe.
- External leakages range from 50 gpm to a lower limit (not well defined) above which an LER would be submitted.
- External leakages or ruptures in welded or threaded connections between piping and components are associated with the component. (However, flanges are covered separately.)
- Elbow events are combined into the piping data.

CONTENTS

EXECUTIVE SUMMARY	iii
INTRODUCTION	1
DATA SEARCH	2
DATA ANALYSIS	3
DATA COMPARISON	13
DISCUSSION	17
SUMMARY	19
REFERENCES	20

TABLES

1. External rupture and leakage event summaries	4
2. External rupture probabilities given an external leakage or rupture event	7
3. Piping (including elbows) external leakage frequencies	10
4. Component external leakage and rupture frequencies	14
5. Pump and valve external leakage frequency estimates from LER summary reports	16

COMPONENT EXTERNAL LEAKAGE AND RUPTURE FREQUENCY ESTIMATES

INTRODUCTION

In order to perform detailed internal flooding risk analyses of nuclear power plants, external leakage and rupture frequencies are needed for various types of components - piping, valves, pumps, flanges, and others. However, there appears to be no up-to-date, comprehensive source for such frequency estimates. This report attempts to fill that void. Based on a comprehensive search of Licensee Event Reports (LERs) contained in Nuclear Power Experience (NPE), and estimates of component populations and exposure times, component external leakage and rupture frequencies were generated.

The remainder of this report covers the specifics of the NPE search for external leakage and rupture events, analysis of the data, a comparison with frequency estimates from other sources, and a discussion of the results.

DATA SEARCH

External leakage and rupture events for components in nuclear power plants were identified by searching the NPE data base. NPE is mainly a compilation of LERs from U.S. commercial nuclear power plants. However, the descriptions of events are often given in more detail in NPE compared with the actual LERs. The computer data base for NPE was searched using the key words internal leak, external leak, unspecified, flooding, and crack/indication. The search covered the period September 1960 through June 1990. Events identified from the search were reviewed in detail to 1) determine if the event actually involved an external leakage or rupture and 2) classify the event by plant, component and system, failure mode and cause, leakage (if known), and piping size. The external leakage or rupture events identified are presented in Appendix A. External rupture events (leakage greater than 50 gpm or complete severance of a pipe) are summarized in Appendix B. Appendix C contains the external leakage and rupture events from Appendix A that occurred in primary coolant systems (PCSs). Finally, Appendix D contains explanations of abbreviations used in the other appendices.

DATA ANALYSIS

The external leakage and rupture events presented in the appendices were converted to component leakage and rupture frequencies in a three-step process. First, the ratios of external rupture events to external leakage and rupture events were examined for various components, component sizes, and systems to decide how to group the data. Then, the final probabilities of an external rupture, given an external leakage or rupture event, were determined. Finally, by estimating component populations and exposure time, the external leakage and rupture frequencies were obtained.

Ratios of external rupture events to external leakage and rupture events for components are presented in Table 1. Inspection of Table 1 results in the following general observations:

- There is no consistent pattern in ratios (external rupture events divided by external leakage and rupture events) between components less than three inches in diameter and greater than three inches.
- There have been no PCS component external ruptures, but there have been many external ruptures in components in other systems.
- For non-PCS components, the ratios are similar (0.03 to 0.05) except for tanks (with very few events) and flanges.

Based on the Table 1 information, the following groupings of components appear to be reasonable:

- Non-PCS components
  - Piping and elbows
  - Valves, pumps, heat exchangers and tanks
  - Flanges

Table 1. External rupture and leakage event summaries

Grouping	Piping	Elbow	Valve	Pump	Flange	External Rupture Events/External Leakage and Rupture Events (1960 - June 1990)		
						Heat Tubes	Exchanger Shell	Tank
All	15/526 (0.03) ^a	2/65 (0.03)	7/170 (0.04)	2/50 (0.04)	1/167 (0.01)	1/60 (0.02)	0/2 (0.00)	2/12 (0.17)
Non-PCS ^b	15/467 (0.03)	2/64 (0.03)	7/141 (0.05)	2/46 (0.04)	1/47 (0.01)	1/60 (0.02)	0/2 (0.00)	2/11 (0.18)
PCS	0/59 (0.00)	0/1 (0.00)	0/29 (0.00)	0/4 (0.00)	0/20 (0.00)	0/0 (-)	0/0 (-)	0/1 (0.00)
<3 in. ^c	9/200 (0.05)	0/26 (0.00)	6/40 (0.15)	2/4 (0.50)	0/18 (0.00)	-	-	-
>3 in. ^c	5/104 (0.05)	2/20 (0.10)	1/9 (0.11)	0/3 (0.00)	1/34 (0.03)	-	-	-
Unknown Size	1/222 (0.00)	0/19 (0.00)	0/121 (0.00)	0/43 (0.00)	0/115 (0.00)	-	-	-

a. External rupture events divided by external leakage and rupture events, rounded off to two decimal places.

b. PCS = primary coolant system.

c. Refers to size of piping connecting to valve, pump, or flange.

- PCS components
  - Piping and elbows
  - Valves, pumps, flanges, heat exchangers, and tanks.

Grouping of components is necessary because in some cases not enough data are available for a single component, especially for PCS components.

Using the component groupings described above, probabilities of external rupture, given an external leakage or rupture event, were calculated. A Bayesian update of a noninformative prior was used to calculate the mean probability²:

$$P_R = (2n + 1)/(2D + 2)$$

where

P_R = mean probability of an external rupture, given an external leakage or rupture event

n = number of external ruptures

D = number of external leakages and ruptures.

This methodology has the advantage of predicting mean values even if no external ruptures have occurred. In contrast, the Chi Square² approach only predicts a 95% value if no events have occurred. A noninformative prior was used because the NPE search covered all commercial reactor experience, and no other information is believed to be applicable (for generating an informative prior). Results are presented in Table 2. For piping (including elbows), the external rupture probability given that an external leakage or rupture has occurred is 0.04 (one in 25 events) for non-PCS systems and 0.01 (one in 100 events) for the PCS. Results are similar for valves, pumps, heat exchangers, and tanks (0.04 for non-PCS and 0.01 for PCS). Finally, for flanges the probability is 0.01 for all types of systems.

The final step in estimating external leakage and rupture frequencies involved estimating component populations and exposure durations appropriate for the U.S. commercial nuclear power plants covered by LERs. For piping, the

Table 2. External rupture probabilities given an external leakage or rupture event

<u>System/Component</u>	<u>External Ruptures</u>	<u>External Leakages and Ruptures</u>	<u>Conditional Mean Rupture Probability^a</u>	<u>Recommended Conditional Mean Rupture Probability^b</u>
Non-PCS				
Piping (including elbows)	17	531	0.033	0.04
Valve, pump, heat exchanger, tank	14	279	0.052	0.04
Flange	1	147	0.010	0.01
PCS				
Piping (including elbows)	0	60	0.008	0.01
Valve, pump, flange, heat exchanger, tank	0	54	0.009	0.01

a. Bayesian update of a noninformative prior. Mean = $(2n+1)/(2D+2)$, where n=ruptures and D=ruptures and leakages.

b. Rounded off to two decimal places. Results for non-PCS components (other than flanges) combined.

report Pipe Break Frequency Estimation for Nuclear Power Plants³ was used to estimate PCS and non-PCS piping footage. For pressurized water reactors (PWRs), Table B-2 of that report indicates approximately 2500 feet of PCS piping per plant. Also, non-PCS piping totals approximately 36,000 feet per plant. Total U.S. commercial PWR-years of experience is 783 for 1960 through June 1990 (434 for 1960 through 1983). From the same report, boiling water reactors (BWRs) involve approximately 600 feet of PCS piping (including main steamlines up to the main steam isolation valves) and 19,000 feet of non-PCS piping per plant. Total U.S. BWR-years of experience is 486 for 1960 through June 1990 (288 for 1960 through 1983).

Given the piping footage estimates and years of operation for BWRs and PWRs, piping external leakage frequency estimates were calculated for various combinations of types of reactors, types of systems, and years of operation. Again, a Bayesian update of a noninformative prior was used:

$$F_L = (2n + 1)/2T$$

where

F_L = mean external leakage frequency

n = number of external leakages and ruptures

T = component exposure time.

Results are presented in Table 3. All frequency estimates are in the range of $1.6E-9$ to $4.2E-9$ /h-ft. This indicates that the piping external leakage frequency is approximately independent of the type of system and type of reactor. Results are presented for the period 1960 through 1983 and 1960 through June 1990. These two periods were used because the reporting requirements for LERs were changed in 1984. The net effect of the changes was a reduction in the number of events reported each year, starting in 1984. Comparison of results for 1960 through 1983 and 1960 through June 1990 indicate consistently lower frequencies estimated for the longer period. This would be expected, given the reduced reporting requirements starting in 1984. Therefore, it was decided to calculate the piping external leakage frequency based on 1960 through 1983 data. Combining PCS and non-PCS data (the

Table 3. Piping (including elbows) external leakage frequencies

System	External Leakage Frequency Estimate ^a			
	1960 - June 1990 All Reactors	1960 - 1983 All Reactors	1960 - 1983 PWRs	1960 - 1983 BWRs
PCS	3.0E-9/h-ft	3.9E-9/h-ft	4.2E-9/h-ft	2.3E-9/h-ft
Non-PCS	1.6E-9/h-ft	2.3E-9/h-ft	1.9E-9/h-ft	3.4E-9/h-ft
All	1.7E-9/h-ft	2.4E-9/h-ft	2.1E-9/h-ft	3.4E-9/h-ft

a. Bayesian update of a noninformative prior. The mean is $(2n + 1)/(2T)$, where n is the number of events (external leakages and ruptures) and T is the piping foot-hours of operation.

differences indicated in Table 3 are minor), the result is $2.4\text{E-}9/\text{h-ft}$ for piping external leakages. (Actually, this result is for piping leakage or rupture. However, correcting by subtracting out the rupture contribution, 1 or 4%, would not significantly change the estimate.) This value was rounded off to $3.0\text{E-}9/\text{h-ft}$ to be consistent with the rounding scheme used in the report Generic Component Failure Data Base for Light Water and Liquid Sodium Reactor PRAs.⁴ (In that report, all recommended failure rates were rounded off to $1.0\text{E-}?$, $3.0\text{E-}?$, or $5.0\text{E-}?$) The external rupture frequency was then calculated by multiplying by 0.04 (non-PCS piping) or 0.01 (PCS piping). The external rupture frequency was not rounded off, in order to preserve the rupture ratios calculated previously (Table 2).

Valve external leakage and rupture frequency estimation requires the numbers of valves in PWRs and BWRs (whose failures may result in LERs) and their exposure times (plant lifetime). Valve population estimates were obtained from the In-Plant Reliability Data (IPRD) report on valves.⁵ From Appendices A and B of Reference 5, there are approximately 2500 valves of interest for PWRs and 1500 for BWRs. Using the plant years of operation through 1983, the total valve years of operation is

$$(2500 \text{ valve/PWR})(434 \text{ PWR-yr}) + (1500 \text{ valve/BWR})(288 \text{ BWR-yr}) = \\ 1.52\text{E}6 \text{ valve-yr.}$$

From Table A-4 of Appendix A, there have been 124 external leakages and 7 external ruptures in valves, resulting in a total of 131 events. A Bayesian update of a noninformative prior, given 131 events in $1.52\text{E}6$ valve-yr, results in a valve external leakage frequency of $9.9\text{E-}9/\text{hr}$. This was rounded off to $1.0\text{E-}8/\text{hr}$. External rupture frequency estimates are then $4.0\text{E-}10/\text{h}$ for valves in non-PCS systems (leakage frequency multiplied by 0.04) and $1.0\text{E-}10/\text{h}$ for valves in the PCS.

Similar to valves, pump population estimates were also obtained from the IPRD effort. From Table 1 of the IPRD report on pumps⁶, there are approximately 250 pumps of interest in PWRs and BWRs. Therefore, the total pump-years of operation is

$(250 \text{ pumps/plant})(434 \text{ PWR-yr} + 288 \text{ BWR-yr}) = 1.81\text{E}5 \text{ pump-yr}.$

Given 43 external leakages and two external ruptures in pumps (Table A-4 of Appendix A), the external leakage frequency estimate is $2.9\text{E}-8/\text{h}$. This was rounded off to $3.0\text{E}-8/\text{h}$. External rupture frequencies are then $1.2\text{E}-9/\text{h}$ (non-PCS pumps) and $3.0\text{E}-10/\text{h}$ (PCS pumps).

For flanges, no source was found for estimating the total number per plant. An estimate of 1000 flanges (of interest) per plant was used. This results in $7.22\text{E}5$ flange-yr of operation. Given 116 external leakages and one external rupture (Table A-4 in Appendix A), the resulting frequency estimate is $1.9\text{E}-8/\text{h}$. This was rounded off to $1.0\text{E}-8/\text{h}$. The external rupture frequency estimate is then $1.0\text{E}-10/\text{h}$ for flanges in both the PCS and other systems.

For heat exchangers, no source was found for estimating the total number of components of interest per plant. A total of 50 heat exchangers per plant was assumed resulting in $3.61\text{E}4$ heat-exchanger-yr of operation. Concerning heat exchanger tubes, there have been 59 leakage and one rupture events. The tube leakage frequency estimate is then $1.9\text{E}-7/\text{h}$. This was rounded off to $1.0\text{E}-7/\text{h}$. Tube rupture frequencies are $4.0\text{E}-9/\text{h}$ (non-PCS heat exchangers) and $1.0\text{E}-9/\text{h}$ (PCS heat exchangers).

The other type of heat exchanger event of concern involves external leakage or rupture of the shell. From Table A-4 of Appendix A, there have been two shell external leakages and no external ruptures. Given two events in $3.61\text{E}4$ heat-exchanger-yr of operation, the shell external leakage frequency is $7.9\text{E}-9/\text{h}$. This was rounded off to $1.0\text{E}-8/\text{h}$. Shell external rupture frequencies are then $4.0\text{E}-10/\text{h}$ (non-PCS) and $1.0\text{E}-10/\text{h}$ (PCS).

Finally, for tanks an estimate of 100 per plant was assumed. This results in $7.22\text{E}4$ tank-yr of operation. Given eight leakages and one rupture, the external leakage frequency is $1.3\text{E}-8/\text{h}$. This was rounded off to $1.0\text{E}-8/\text{h}$. External rupture frequency estimates are then $4.0\text{E}-10/\text{h}$ (non-PCS tanks) and $1.0\text{E}-10/\text{h}$ (PCS tanks).

All of the recommended component leakage and rupture frequency estimates are presented in Table 4. Also shown in Table 4 are the recommended error factors (EFs). All leakage estimates were assigned EFs of 10, and all rupture estimates, 30. These EFs were not derived from the data analysis. Rather the EFs are based on judgement and the belief that rupture frequency estimates are more uncertain than leakage frequency estimates. A lognormal distribution is suggested for the frequency estimates.

Table 4. Component external leakage and rupture frequencies

Component and Failure Mode	Recommended	External Leakage and Rupture Mean Frequency Estimates			LER Reports ^c	Piping Study ^a
		WASH-1400 ^a	Seabrook PRA	Shoreham PRA ^b		
Piping (includes elbows) Leakage	3.0E-9/h-ft(10) ^a	8.5E-9/h-ft(<3in) ^a or 8.5E-10/h-ft(>3in)	-	8.5E-11/h-ft(<3in) or 8.5E-12/h-ft(>3in)	-	9.5E-11/h-ft
Rupture	1.2E-10/h-ft(30) (non-PCS) 3.0E-11/h-ft(30) (PCS)	4.3E-10/h-ft(<3in) or 4.3E-11/h-ft(>3in)	-	4.3E-12/h-ft(<3in) or 4.3E-13/h-ft(>3in)	-	-
Valve Leakage	1.0E-8/h(10)	2.7E-8/h	-	2.7E-8/h	2.5E-8/h to 1.3E-7/h	-
Rupture	4.0E-10/h(30) (non-PCS) 1.0E-10/h(30) (PCS)	-	-	1.4E-9/h	-	-
Pump Leakage	3.0E-8/h(10)	-	-	3.0E-9/h	4.3E-7/h to 3.5E-6/h	-
Rupture	1.2E-9/h(30) (non-PCS) 3.0E-10/h(30) (PCS)	-	-	1.5E-10/h	-	-
Flange Leakage	1.0E-8/h(10)	2.5E-6/h	-	-	-	-
Rupture	1.0E-10/h(30) (non-PCS and PCS)	-	-	-	-	-
Heat Exchanger Tube Leakage	1.0E-7/h(10)	-	1.9E-6/h	-	-	-
Rupture	4.0E-9/h(30) (non-PCS) 1.0E-9/h(30) (PCS)	-	-	-	-	-

Table 4. (continued)

Component and Failure Mode	Recommended	External Leakage and Rupture Mean Frequency Estimates			
		WASH-1400 ^a	Seabrook PRA	Shoreham PRA ^b	Piping Study ^d
Heat Exchanger (continued) Shell Leakage	1.0E-8/h(10)	-	-	-	-
	4.0E-10/h(30) (non-PCS)	-	-	-	-
	1.0E-10/h(30) (PCS)	-	-	-	-
Tank Leakage	1.0E-8/h(10)	-	-	-	-
	4.0E-10/h(30) (non-PCS)	-	2.7E-8/h	-	-
	1.0E-10/h(30) (PCS)	-	-	-	-

a. Median values in report converted to means using the reported error factors (range factors) and assuming a lognormal distribution.

b. From Appendix G of the Shoreham PRA.

c. See Table 5 for a summary of estimates derived from these reports.

d. From data in Table 15 of Reference 3, assuming 36,000 ft of non-PCS piping in PWRs and 19,000 ft in BWRs.

e. Suggested error factor in parentheses. A lognormal distribution is suggested.

f. PCS = primary coolant system.

g. Assumes 20 feet per section of pipe. Leakage value is rupture value times 20.

DATA COMPARISON

The recommended component external leakage and rupture frequency estimates derived in this report are compared with other estimates in Table 4. Shown in Table 4 are estimates from WASH-1400⁷, the Seabrook PRA⁸, the Shoreham PRA⁹, LER reports^{10 and 11}, and the EG&G Idaho piping study.³ Although the LER reports do not explicitly present leakage frequencies, such estimates can be obtained from a review of the event summaries in the appendices. Results of such a review are presented in Table 5. Finally, the EG&G Idaho piping study does not explicitly present a pipe leakage frequency. However, using data from Table 15 of that report, and assuming 36,000 ft of non-PCS piping in PWRs and 19,000 ft in BWRs, a leakage frequency can be calculated. The result, with 19 external leakage events in 2.05E11 h-ft of exposure, is 9.5E-11/h-ft. This mean frequency is for non-PCS piping leakages greater than 1 gpm.

A review of the external leakage and rupture frequencies in Table 4 indicates that, in general, the recommended values derived in this report are similar to or lower than existing estimates. Also, the entries in the table from other sources are not nearly as complete in terms of component coverage.

Table 5. Pump and valve external leakage frequency estimates from LER summary reports

	Motor-Driven Pump ^a		Turbine-Driven ^a		Diesel-Driven ^a		Valve ^b		
	Running	Alternating	Standby	Pump	Pump	Manual	Motor-Operated	Air-Operated	Check
Events ^c	26	67	24	1	0	3	312	2	5
Exposure	7.61E6h	2.65E7h	2.26E7h	3.47E6h	1.54E5h	1.38E8h	1.24E8h	1.93E7h	1.02E8h
External Leakage Frequency ^d	3.5E-6/h	2.5E-6/h	1.1E-6/h	4.3E-7/h	3.2E-6/h	2.5E-8/h	1.0E-7/h	1.3E-7/h	5.4E-8/h

a. From Reference 10.

b. From Reference 11.

c. Obtained from review of event descriptions found in appendices to References 10 and 11.

d. Bayesian update of a non-informative prior. Mean = $(2n+1)/(2T)$, when n = leakage events and T = exposure hours.

DISCUSSION

The recommended component external leakage and rupture frequency estimates presented in Table 4 are based on a search of NPE and on component population estimates from other sources. This approach has several shortcomings. First, NPE does not include all LERs. This implies that not all external leakage and rupture events, even if reported in LERs, are in NPE. Therefore, the total number of events may be underestimated. Second, the computerized search of NPE for leakage and rupture events was performed based on key words assigned to each event. If the key word internal leak, external leak, unspecified, flooding, or crack/indication was not used, then the computerized search would miss the event. This uncertainty in the assignment of key words to events also tends to underestimate the actual number of events. Third, each NPE event identified in the search had to be reviewed and classified (if not discarded as inappropriate) by component, system, leakage size, and other factors. This review and classification process was not always clear cut; at times judgement had to be used. This uncertainty could result in either under- or overprediction of the number of events. Finally, NPE does not contain population estimates for the components covered by LERs. Therefore, other sources had to be used for estimating component populations. Because these populations should include only components whose failure might result in an LER, the component populations of interest are subsets of the entire populations at a plant. When obtaining component population estimates from other sources, this distinction had to be kept in mind. For example, the piping footage estimates were obtained from Reference 3. However, piping with diameters less than two inches was not included in Reference 3, although the LER events in NPE included pipe leakage or rupture events involving smaller diameter piping. This underprediction of the piping footage increases the leakage and rupture frequency estimates.

In spite of the uncertainties and potential inconsistencies described above, the recommended frequency estimates in Table 4 are believed to be more accurate than past estimates. This is because of the extensive data search of LERs (September 1960 through June 1990) and the consistent

approach used in classifying the events identified. Also, the recommended EFs are believed to cover any uncertainties in the methodology.

It should be kept in mind that the external rupture events include any leakage greater than 50 gpm. Therefore, most of the external ruptures identified in NPE do not involve complete pipe severance or catastrophic failure of a valve or pump body. The frequencies for such catastrophic rupture events should be lower than those presented in this report.

Finally, because the actual external leakage and rupture events are presented in the appendices, it is possible to generate plant-specific estimates by eliminating events that cannot occur at the plant in question. For example, some of the rupture events involve freezing of the coolant in the component. For some plants, this failure cause may not be possible. This process of plant-specific estimation may result in leakage and rupture frequencies lower than the generic values presented in this report.

SUMMARY

External leakage and rupture frequencies have been generated in a consistent manner from LERs covering U.S. commercial nuclear reactor experience. Recommended frequencies cover a wide variety of components: piping (and elbows), valves, pumps, flanges, heat exchangers, and tanks. The individual failure events are summarized in the appendices, so the data supporting each estimate can be reviewed. This comprehensive coverage of components, with leakage and rupture frequency estimates based on extensive and traceable plant data, is a significant advance over existing data sources and should be a valuable reference for PRA analysts.

REFERENCES

1. Nuclear Power Experience, S. M. Stoller Corporation, Boulder, CO.
2. PRA Procedures Guide, NUREG/CR-2300, January 1983.
3. R. E. Wright, J. A. Stevenson, and W. F. Zuroff, Pipe Break Frequency Estimation for Nuclear Power Plants, NUREG/CR-4407, May 1987.
4. S. A. Eide, S. V. Chmielewski, and T. D. Swantz, Generic Component Failure Data Base for Light Water and Liquid Sodium Reactor PRAs, EGG-SSRE-8875, February
5. R. J. Borkowski et al., The In-Plant Reliability Data Base for Nuclear Plant Components: Interim Data Report - The Valve Component, NUREG-CR-3154, December 1983.
6. J. P. Drago et al., The In-Plant Reliability Data Base for Nuclear Plant Components: Interim Data Report - The Pump Component, NUREG/CR-2886, December 1982.
7. Reactor Safety Study: An Assessment of Accident Risks in U. S. Commercial Nuclear Power Plants, WASH-1400 (NUREG 75/014), October 1975.
8. Public Service Company of New Hampshire, Seabrook Station Probabilistic Safety Assessment, December 1983.
9. Long Island Lighting Company, Probabilistic Risk Assessment Shore Lam Nuclear Power Station, 1983.
10. M. Trojovsky, Data Summaries of Licensee Event Reports of Pumps at U.S. Commercial Nuclear Power Plants, NUREG/CR-1205, Revision 1, January 1982.
11. C. F. Miller et al., Data Summaries of Licensee Event Reports of Valves at U.S. Commercial Nuclear Power Plants, NUREG/CR-1363, Revision 1, October 1982.

APPENDIX A
NPE LEAKAGE AND RUPTURE EVENTS

CONTENTS

Table A-1. BWR leakage and rupture events.	A-3
Table A-2. PWR leakage and rupture events.	A-19
Table A-3. Summary of leakage and rupture events (9/60 - 6/90) . . .	A-53
Table A-4. Summary of leakage and rupture events (9/60 - 12/83). . .	A-56

Table A-1. BWR leakage and rupture events

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Comp Size (diam)	Classification ^a	
									size	cnt
Dresden 3	Sep-76	B.6.D.28	CCW	elbow	crack	fatigue			U	1
Dresden 3	Nov-78	B.6.D.34	MSS	elbow	crack	erosion			U	2
Monticello	Apr-83	B.6.E.168	AFW	elbow	crack	erosion			U	3
Dresden 2	Mar-79	B.7.D.180	RHR	elbow	crack	installer			U	4
Dresden 2	Apr-81	B.7.D.264	SI-LPSI	elbow	crack	th crack			U	5
Oyster Cr	May-84	B.7.F.265		elbow	crack	IGSCC			U	6
Oyster Cr	Dec-72	B.12.16	WST	elbow	leak	erosion	2.5 gpm		U	7
Dresden 2	Jun-83	B.5.C.390	MSS	elbow	crack	fatigue		3/4"	S	1
V Yankee	Jan-83	B.5.D.60	CRDM	elbow	crack	IGSCC		2"	S	2
Monticello	Dec-79	B.6.E.119	CDS	elbow	crack	erosion		1"	S	3
Dresden 2	Mar-77	B.7.D.120	RHR	elbow	crack	bad weld		1"	S	4
Monticello	Aug-76	B.8.C.87	TBN	elbow	crack	erosion		1"	S	5
Monticello	May-78	B.8.C.136	SI-HPCI	elbow	crack	erosion		1"	S	6
Monticello	Jul-78	B.8.C.141	TBN	elbow	crack	erosion		1"	S	7
Willstone	Jul-77	B.8.C.144	CRDM	elbow	crack			2"	S	8
Monticello	Nov-78	B.8.C.159	SI-HPCI	elbow	crack	erosion		1"	S	9
Monticello	Jan-79	B.8.C.165	TBN	elbow	crack	erosion		1"	S	10
Monticello	Apr-79	B.8.C.175	RCIC	elbow	crack	erosion		1"	S	11
Monticello	Dec-79	B.8.C.195	RCIC	elbow	crack	erosion		1"	S	12
Monticello	Aug-80	B.8.C.211	RCIC	elbow	crack	erosion		1"	S	13
Dresden 2	Dec-73	B.7.E.21	SI-HPCI	elbow	p hole	erosion		1"	S	14
Monticello	May-78	B.8.C.136	RCIC	elbow	p hole	crevice		1"	S	15
Dresden 3	Apr-82	B.7.D.300	SI-LPSI	elbow	weld	fatigue		3/4"	S	16

Table A-1. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Comp Size (diam)	Classification ^a	
									size	cnt
Bruns 2	Oct-77	B.7.C.74	CRDM	elbow	crack	corrosion	seepage	>3"	L	1
Bruns 2	Oct-77	B.7.C.74	CRDM	elbow	crack	corrosion	seepage	>3"	L	2
Bruns 2	Oct-77	B.7.C.74	CRDM	elbow	crack	corrosion	seepage	>3"	L	3
2 Cities 2	Mar-80	B.7.C.88	CRDM	elbow	crack	IGSCC		>3"	L	4
Pilgrim	Mar-86	B.7.D.402	RHR	elbow	crack	vibration		4"	L	5
Dresden 2	Nov-78	B.12.93	WST	elbow	hole	corrosion		30"	L	6
Monticello	Aug-77	B.8.C.111	SI-HPCI	elbow	leak	erosion		3"	L	7
Arnold	Mar-79	B.8.A.54	RVCU	elbow	p hole	IGSCC		>3"	L	8
Bruns 2	Sep-79	B.8.C.186	SSWS	elbow	pitting	corrosion		>3"	L	9
Cooper	Apr-78	B.4.B.76	CRDM	flange	leak	installer			U	1
G Gulf 1	Nov-84	B.7.A.205	ROIC	flange	leak				U	2
0 Cities 2	Oct-82	B.7.E.282	SI-HPCI	flange	leak	fatigue			U	3
Bruns 1	Jan-88	B.8.A.270	RVCU	flange	leak		lg. leak		U	4
Bruns 1	Jan-88	B.8.A.270	RVCU	flange	leak		lg. leak		U	5
Bruns 1	Jan-88	B.8.A.270	RVCU	flange	leak		lg. leak		U	6
Bruns 1	Jan-88	B.8.A.270	RVCU	flange	leak		lg. leak		U	7
Bruns 1	Jan-88	B.8.A.270	RVCU	flange	leak		lg. leak		U	8
Millstone	Sep-88	B.6.C.407	SSWS	flange	leak	erosion			U	9
Bruns 2	Nov-75	B.7.E.75	SI-HPCI	flange	leak	erosion			U	10
Bruns 2	Nov-75	B.7.E.75	SI-HPCI	flange	leak	erosion			U	11
Fitzpatrick	Nov-79	B.4.B.97	CRDM	flange	leak				U	12
Fermi	Dec-86	B.8.A.235	RVCU	flange					U	13

Table A-1. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Comp Size (diam)	Classification ^a	
									size	cnt
Bruns 2	Sep-88	B.8.C.408	SSWS	flange	hole	corrosion		3/4"	S	1
Monticello	Aug-76	B.9.C.87	TBN	flange	leak			1"	S	2
V Yankee	Jan-79	B.8.A.56	RWCU	flange	p hole	IGSCC		2"	S	3
LaSalle 1	Jun-82	B.7.D.310	RHR	flange	leak	loose		>3"	L	1
Bruns 1	Apr-88	B.8.C.402	SSWS	flange	p hole			>3"	L	2
Br Ferry 1	Jan-74	B.7.D.113	RHR	flange-ht x	leak				U	1
Br Ferry 1	Jan-74	B.7.D.113	RHR	flange-ht x	leak				U	2
Br Ferry 1	Jan-74	B.7.D.113	RHR	flange-ht x	leak				U	3
Pilgrim	Aug-82	B.7.E.286	SI-HPCI	flange-ht x	leak	erosion			U	4
S Gulf 1	Jan-88	B.6.C.94	CCW	flange-ht x	leak	installer		>3"	L	1
2-mile Pt 1	Mar-84	B.4.B.199	CRDM	flange-pump	crack	IGSCC	0.001 gpm		U	1
Oyster Cr	Jan-85	B.9.D.111	CRDM	flange-pump	leak				U	2
Millstone	May-72	B.6.C.3	CRDM	flange-pump	leak				U	3
Hatch 2	Jun-79	B.7.E.192	SI-HPCI	flange-pump	leak				U	4
Hatch 1	Sep-85	B.8.A.175	RWCU	flange-pump	leak				U	5
Hope Cr	Nov-86	B.8.A.230	DWIN	flange-pump	leak				U	6
LaSalle 1	Jun-83	B.4.B.182	CRDM	flange-tank	leak	wear	drops		U	1
Riv Bend	Jul-86	B.6.D.55	MSS	flange-tank	leak	installer			U	2

Table A-1. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Comp Size (diam)	Classification ^a	
									size	cnt
Fermi 2	Jul-88	B.9.E.1065	PCS	flange-tank	leak		sm leak		U	3
Cooper	Apr-88	B.5.C.523	MSS	flange-valve	leak				U	1
Hatch 2	May-80	B.7.D.220	SI-HPCI	flange-valve	leak				U	2
Hatch 2	May-80	B.7.E.199	SI-HPCI	flange-valve	leak				U	3
Hatch 2	May-80	B.7.E.203	SI-HPCI	flange-valve	leak	defective			U	4
Hatch 1	Jan-80	B.8.C.194	MSS	flange-valve	leak				U	5
Cooper	Sep-77	B.8.C.116	SSWS	flange-valve	p hole	erosion			U	6
Bruns 1	Aug-86	B.6.D.56		flange-valve	leak			1/2"	S	1
Bruns 1	Jul-77	B.8.C.110	SSWS	flange-valve	leak			>3"	L	1
Dresden 2	Mar-78	B.7.E.145	SI-HPCI	flange-valve	leak	erosion		10"	L	2
9-Mile Ft 1	May-77	B.7.F.730	DHR	ht xchanger	crack(?)				U	1
WNP 2	Feb-85	B.14.B.616	HVCS	ht xchanger	leak(T)				U	2
Millstone	May-72	B.6.C.3	CRDM	ht xchanger	leak(T)				U	3
Dresden 3	Oct-70	B.12.4	WST	ht xchanger	leak(T)				U	4
Dresden 3	Oct-70	B.12.4	WST	ht xchanger	leak(S)				U	1
Dresden 2	Jul-82	B.6.E.160	APW	ht xchanger	crack(?)	vibration		<3"	S	1
Dresden 2	Dec-82	B.6.E.160	APW	ht xchanger	crack(?)	vibration		<3"	S	2
Dresden 2	Jul-82	B.6.E.160	APW	ht xchanger	crack(?)	vibration		<3"	S	3

Table A-1. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leak	Pipe/Comp Size (diam)	Classification ^a	
									size	cnt
Dresden 2	Jul-82	B.6.E.160	AFW	ht xchanger	crack(?)	vibration		<3"	S	4
Dresden 2	Jan-83	B.6.E.160	AFW	ht xchanger	crack(?)	vibration		<3"	S	5
Sr Ferry 2	Jul-81	B.7.D.275	RHR	ht xchanger	crack(T)			<3"	S	6
Dresden 3	Jun-77	B.6.C.44		ht xchanger	leak(?)	vibration		2"	S	7
Bruns 2	Jun-75	B.11.A.93	DG	ht xchanger	leak(?)	corrosion		<3"	S	8
G Gulf 1	Jan-88	B.6.D.8	CCW	ht xchanger	crack(T)	installer		8"	L	1
Pilgrim 1	Sep-75	B.8.A.29	RVCU	ht xchanger	crack(?)	IGSCC		>3"	L	2
Dresden 3	Sep-81	B.8.A.110	RVCU	ht xchanger	p hole(?)	IGSCC		6"	L	3
Fitzpatrick	Jun-83	B.4.B.177	CRDM	pipe	crack	IGSCC			U	1
Sr Ferry 2	Feb-85	B.5.B.68	CRDM	pipe	crack	IGSCC			U	2
Monticello	Jun-74	B.6.E.28	AFW	pipe	crack	th stress	0.2 gpm		U	3
Monticello	Apr-83	B.6.E.158	AFW	pipe	crack	erosion			U	4
Monticello	Apr-83	B.6.E.168	AFW	pipe	crack	erosion			U	5
LaSalle 2	Dec-81	B.7.A.142	RCIC	pipe	crack	fatigue			U	6
Sr Ferry 1	Mar-84	B.7.A.196	RCIC	pipe	crack	erosion			U	7
Fitzpatrick	Dec-86	B.7.F.340		pipe	crack	fatigue			U	8
Hope Cr	Nov-86	B.8.A.230	RVCU	pipe	crack				U	9
P Bottom 2	Feb-78	B.8.C.131	RHR	pipe	crack	vibration			U	10
Sr Ferry	Mar-85	B.9.E.1008	PCS	pipe	crack	TGSCC			U	11

Table A-1. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Comp Size (diam)	Classification ^a	
									size	cnt
Fitzpatrick	Apr-76	B.12.37	WST	pipe	crack				U	12
Cyster Cr	Apr-78	B.12.57	WST	pipe	crack	low temp	990 gal		U	13
9-Mile Pt 1	Mar-70	B.3.4	CDW	pipe	crack	stress			U	14
9-Mile Pt 1	Mar-70	B.3.4	CDW	pipe	crack	stress			U	15
P Bottom 2	Mar-82	B.3.47	CDW	pipe	crack	IGSCC			U	16
Dresden 3	Sep-81	B.5.C.340	ADS	pipe	leak				U	17
Dresden 1	May-75	B.6.A.29	TBN	pipe	leak	erosion			U	18
Bruns 1	Sep-86	B.6.C.86	CCW	pipe	leak	corrosion			U	19
LaSalle 1	Dec-82	B.7.A.165	ROIC	pipe	leak				U	20
Dresden 1	Jun-74	B.7.F.22		pipe	leak	stress			U	21
Dresden 1	Jun-74	B.7.F.22		pipe	leak	stress			U	22
Bruns 2	May-85	B.9.C.23	PCS	pipe	leak				U	23
Arnold	Nov-86	B.9.E.1102	SI-HPCI	pipe	leak				U	24
Cyster Cr	Dec-85	B.9.E.1117	PCS	pipe	leak				U	25
Bruns 2	Aug-87	B.9.F.86	RVCU	pipe	leak		0.003 gpm		U	26
Hatch 2	Jun-82	B.9.G.512	PCS	pipe	leak				U	27
Dresden 1	Mar-87	B.12.12	WST	pipe	leak	corrosion			U	28
Dresden 3	Jun-77	B.6.D.24	CCW	pipe	p hole	fatigue			U	29
Dresden 2	Aug-74	B.5.E.32	APW	pipe	p hole	erosion			U	30
Dresden 3	Nov-74	B.6.E.37	APW	pipe	p hole	erosion			U	31
Dresden 3	Dec-74	B.6.E.37	APW	pipe	p hole	erosion			U	32
Dresden 3	Dec-74	B.6.E.37	APW	pipe	p hole	erosion			U	33
Dresden 3	Nov-79	B.6.E.120	APW	pipe	p hole	erosion			U	34

Table A-1. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Comp Size (diam)	Classification ^a	
									size	cnt
Dresden 1	Jan-74	B.7.C.11	CRDM	pipe	p hole	corrosion			U	35
Dresden 1	Oct-74	B.7.C.21	CRDM	pipe	p hole	corrosion			U	36
Dresden 1	Oct-76	B.7.C.56	CRDM	pipe	p hole	installer			U	37
Oyster Cr	Oct-73	B.7.D.151		pipe	pitting	corrosion			U	39
Pilgrim	Mar-86	B.3.48	PCS	pipe	crack	stress	2 gpm	2"	S	1
Oyster Cr.	Nov-80	B.4.B.136	CRDM	pipe	crack	vibration		1 1/2"	S	2
Oyster Cr.	Nov-80	B.4.B.136	CRDM	pipe	crack	stress		1 1/2"	S	3
Annand	Nov-88	B.4.B.244	CRDM	pipe	crack	TSSCC		1"	S	4
B. Ferry 1	Dec-74	B.5.B.11	CRDM	pipe	crack	vibration		1"	S	5
B. Ferry 1	Dec-74	B.5.B.11	CRDM	pipe	crack	fatigue		1"	S	6
B. Ferry 2	Oct-74	B.5.B.12	CRDM	pipe	crack	vibration		2"	S	7
Brous 2	Dec-73	B.5.B.35	CRDM	pipe	crack			3/4"	S	8
Dresden 2	Nov-81	B.5.B.36	CRDM	pipe	crack	stress		3/4"	S	9
Hatch 2	Aug-87	B.5.B.61	CRDM	pipe	crack	IGSCC		1"	S	10
Monticello	Nov-87	B.5.B.82	CRDM	pipe	crack	fatigue		2"	S	11
LaSalle 1	Apr-83	B.5.C.414	MSS	pipe	crack	bad weld		1"	S	12
Coogan	Apr-84	B.5.D.67	CRDM	pipe	crack	bad weld		3/4"	S	13
Dresden 3	Oct-83	B.5.D.69	CRDM	pipe	crack	fatigue		3/4"	S	14
Hore Cr	Feb-87	B.5.D.85	CRDM	pipe	crack			3/4"	S	15
Monticello	Jun-77	B.6.D.25	CCW	pipe	crack	installer		1"	S	16
LaSalle 1	Sep-82	B.6.D.43	APW	pipe	crack	installer		1 1/4"	S	17
Dresden 3	Jul-74	B.6.E.27	APW	pipe	crack	installer		3/4"	S	18

Table A-1. (continued)

Plant Name ^e	Date	API Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Comp Size (diam)	Classification ^a	
									size	cnt
Dresden 3	Dec-74	B.6.E.86	AFW	pipe	crack	vibration	6 gal	3/4"	S	19
C. Cycles 1	Jun-74	B.6.E.45	AFW	pipe	crack	fatigue		3/4"	S	20
C. Cycles 2	Jun-74	B.6.E.45	ROIC	pipe	crack	fatigue		3/4"	S	21
LaSalle 1	Nov-82	B.6.E.162		pipe	crack	bad weld		3/4"	S	22
Dresden 1	Apr-76	B.7.C.34	CDWM	pipe	crack	fatigue		3/4"	S	23
Oyster Cr	Apr-76	B.7.C.49	CDWM	pipe	crack	fatigue		1/2"	S	24
Oyster Cr	Oct-80	B.7.C.97	CDWM	pipe	crack			1/4"	S	25
9-mile Pt 1	Nov-83	B.7.C.124	CDWM	pipe	crack			3/4"	S	26
P Bottom	Nov-75	B.7.D.77	RHR	pipe	crack	vibration		3/4"	S	27
P Bottom	Nov-75	B.7.D.77	RHR	pipe	crack	vibration		1"	S	28
Monticello	Nov-75	B.7.D.78	RHR	pipe	crack	vibration		1"	S	29
Coccon	Feb-77	B.7.D.161	RHR	pipe	crack	vibration		1"	S	30
Sr Ferry 1	Jun-80	B.7.F.93		pipe	crack			1/2"	S	31
Monticello	Aug-75	B.8.A.22	RUCU	pipe	crack	fatigue		1/2"	S	32
Dresden 3	Oct-80	B.8.A.70	RUCU	pipe	crack			2"	S	33
Pilgrim	Nov-80	B.8.A.72	RUCU	pipe	crack	fatigue		2"	S	34
V Yankee	May-81	B.8.A.86	RUCU	pipe	crack	IGSCC		1"	S	35
V Yankee	Jun-81	B.8.A.86	RUCU	pipe	crack	IGSCC		1"	S	36
Sr Ferry 1	Mar-82	B.8.A.100	RUCU	pipe	crack	vibration	12 gpm	3/4"	S	37
Pilgrim	Oct-82	B.8.A.104	RUCU	pipe	crack	bad weld		3/4"	S	38
Monticello	Sep-76	B.8.C.89	AFW	pipe	crack	vibration		<3"	S	39
Dresden 2	Aug-78	B.8.C.146	CDWM	pipe	crack	stress		2"	S	40
Dresden 3	Nov-78	B.8.C.160	AFW	pipe	crack	installer		<3"	S	41

Table A-1. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Comp Size (diam)	Classification ^a	
									size	Cnt
Monticello	Nov-78	B.8.C.163	TBN	pipe	crack	erosion		2"	S	42
Custer Cr	Jun-79	B.8.C.181	SSWS	pipe	crack			3/4"	S	43
Custer Cr	Jun-79	B.8.C.192	SSWS	pipe	crack			3/4"	S	44
Monticello	Oct-80	B.8.C.216	RCIC	pipe	crack	erosion		1"	S	45
Monticello	Jul-81	B.8.C.251	RCIC	pipe	crack	erosion		1"	S	46
Dresden 2	May-82	B.12.83	WST	pipe	crack	corrosion		2 1/2"	S	47
Q Cities 1	Jun-83	B.15.402	AUX	pipe	hole	corrosion		2"	S	48
Arnold	Jan-80	B.7.E.189	SI-HPCI	pipe	leak			1/2"	S	49
Q Cities 2	Jun-80	B.7.E.205	SI-HPCI	pipe	leak	fatigue		3/4"	S	50
Fermi 2	May-83	B.6.A.278	RWCU	pipe	leak			5/8"	S	51
Fermi 2	Jul-88	B.6.A.282	RWCU	pipe	leak	installer		5/8"	S	52
LaSalle	Oct-81	B.15.C.1351	PCS	pipe	leak	installer		<3"	S	53
Q Cities 2	Jun-74	B.6.E.45	APW	pipe	leak	fatigue		3/4"	S	55
Q Cities 2	Feb-82	B.4.B.157	CRDM	pipe	p hole	pitting	0.25 gpm	3/4"	S	56
Q Cities 1	May-83	B.5.D.62	CIS	pipe	p hole	bad weld		2"	S	57
Dresden 2	Jun-82	B.7.E.292	SI-HPCI	pipe	p hole	erosion		1"	S	58
Dresden 3	May-79	B.6.A.55	RWCU	pipe	p hole	erosion		2"	S	59
Coeber	Aug-77	B.6.C.114	PCS	pipe	p hole	installer		2"	S	60
Q Cities 1	Aug-82	B.6.C.295	SSWS	pipe	p hole	stress		1/2"	S	61
Q Cities 1	Aug-82	B.6.C.295	SSWS	pipe	p hole	stress		1/2"	S	62
Brunns. 2	Mar-88	B.4.B.243	CRDM	pipe	pitting	TGSOC		3/4"	S	63
Brunns. 2	Mar-88	B.4.B.243	CRDM	pipe	pitting	TGSOC		1"	S	64
Dresden 2	Sep-75	B.7.E.93	SI-HPCI	pipe	pitting	corrosion		<3"	S	65

Table A-1. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Comp Size (diam)	Classification ^a	
									size	cnt
Dresden 2	Sep-76	B.7.E.93	SI-HPCI	pipe	pitting	corrosion	5 gpm	<3"	S	66
Q Cities 2	Aug-75	B.6.E.45	AFW	pipe	rupture	vibration	8500 gal	3/4"	S	1
Q Cities 2	Aug-75	B.6.E.45	AFW	pipe	rupture	vibration		3/4"	S	2
Dresden 2	Jan-81	B.6.E.142	CDS	pipe	rupture	vibration		3/4"	S	3
Pilgrim	Sep-81	B.7.D.284	RHR	pipe	rupture	vibration		1"	S	4
Dresden 1	Apr-77	B.8.C.105	SFP	pipe	rupture	corrosion	2000 gal	<3"	S	5
Cooper	Dec-76	B.8.C.103	SSWS	pipe	rupture	corrosion		<3"	S	6
V. Vankee	May-74	B.4.B.25	CRDM	pipe	crack	stress		3"	L	1
Dresden 2	Sep-74	B.5.B.10	CRDM	pipe	crack	stress	1.5 gpm	4"	L	2
Dresden 2	Sep-74	B.5.B.10	CRDM	pipe	crack	stress		4"	L	3
Q Cities 2	Sep-74	B.5.B.10	CRDM	pipe	crack	stress		4"	L	4
Willstone 1	Sep-74	B.5.B.10	CRDM	pipe	crack	stress		4"	L	5
Arnold	Jun-76	B.5.B.29	CRDM	pipe	crack	IGSCC	3 gpm	10"	L	6
Monticello	Oct-82	B.5.B.40	CRDM	pipe	crack	IGSCC		22"	L	7
Monticello	Nov-82	B.5.B.40	CRDM	pipe	crack	IGSCC		22"	L	8
Bruns 1	Jan-83	B.5.B.42	CRDM	pipe	crack	IGSCC		22"	L	9
Monticello	May-84	B.5.B.56	CRDM	pipe	crack	IGSCC		22"	L	10
Bruns 1	Jul-85	B.5.B.69	CRDM	pipe	crack	IGSCC		>3"	L	11
Bruns 1	Jul-85	B.5.B.69	CRDM	pipe	crack	IGSCC		>3"	L	12
Bruns 1	Jul-85	B.5.B.69	CRDM	pipe	crack	IGSCC		>3"	L	13
Bruns 1	Jul-85	B.5.B.69	CRDM	pipe	crack	IGSCC		>3"	L	14

Table A-1. (continued)

Plant Name ²	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Comp Size (diam)	Classification ^a	
									size	cnt
Bruns 1	Jul-85	B.5.B.69	CRDM	pipe	crack	IGSCC		>3"	L	15
Q Cities 2	Apr-85	B.5.B.70	CRDM	pipe	crack	IGSCC	seeping	>3"	L	16
Bruns 2	Jan-86	B.5.B.74	CRDM	pipe	crack	IGSCC		>3"	L	17
Bruns 2	Jan-86	B.5.B.74	CRDM	pipe	crack	IGSCC		>3"	L	18
Bruns 2	Jan-86	B.5.B.74	CRDM	pipe	crack	IGSCC		>3"	L	19
Bruns 2	Jan-86	B.5.B.74	CRDM	pipe	crack	IGSCC		>3"	L	20
Bruns 2	Jan-86	B.5.B.74	CRDM	pipe	crack	IGSCC		>3"	L	21
Dresden 1	Oct-78	B.6.D.33	TBN	pipe	crack	erosion		4"	L	22
Dresden 1	Oct-78	B.6.D.33	TBN	pipe	crack	erosion		4"	L	23
Hatch 2	Apr-86	B.6.G.3	APW	pipe	crack	erosion		20"	L	24
Cooper	Jul-83	B.7.C.113	CRDM	pipe	crack	IGSCC		10"	L	25
LaSalle 1	May-85	B.7.C.145	HPCS	pipe	crack	corrosion	500 gpm	>3"	L	26
Millstone 1	Nov-76	B.7.D.105	RHR	pipe	crack	fatigue		6"	L	27
Bruns 2	Dec-76	B.7.D.111	RHR	pipe	crack	installer		4"	L	28
Bruns 2	Jul-77	B.7.D.133	RHR	pipe	crack	installer		4"	L	29
Fitzpatrick	Mar-79	B.7.D.205	RHR	pipe	crack	fatigue		4"	L	30
Dresden 2	Mar-76	B.7.E.83	SI-HPCI	pipe	crack	IGSCC		14"	L	31
9-Mile Pt 1	Mar-76	B.8.A.26	RVCU	pipe	crack	stress		6"	L	32
9-Mile Pt 1	Mar-76	B.8.A.26	RVCU	pipe	crack	stress		6"	L	33
9-Mile Pt 1	Nov-75	B.8.A.26	RVCU	pipe	crack	stress		6"	L	34
Dresden 1	Sep-75	B.8.A.27	RVCU	pipe	crack	fatigue		6"	L	35
Millstone	Jan-79	B.8.A.51	RVCU	pipe	crack	IGSCC		8"	L	35
V Yankee	Oct-80	B.8.A.71	RVCU	pipe	crack			4"	L	37

Table A-1. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Comp Size (diam)	Classification ^a	
									size	cnt
V Yankee	Oct-80	B.8.A.71	RWCU	pipe	crack			4"	L	38
Q Cities 2	Jan-82	B.8.A.81	RWCU	pipe	crack	IGSCC	<2 gpm	6"	L	39
Dresden 2	Dec-82	B.8.A.122	RWCU	pipe	crack	IGSCC		8"	L	40
Q Cities 2	May-88	B.8.A.280	RWCU	pipe	crack	IGSCC		6"	L	41
Bruns 2	Jun-76	B.8.C.75	SSWS	pipe	crack			>3"	L	42
Cooper	Jul-77	B.8.C.104	SSWS	pipe	crack	erosion		>3"	L	43
Dresden 2	Apr-74	B.12.22	WST	pipe	crack	corrosion		3"	L	44
Dresden 2	Nov-78	B.12.63	WST	pipe	crack	corrosion		4"	L	45
Dresden 2	Aug-81	B.12.60	WST	pipe	crack	corrosion		6"	L	46
Q Cities 2	Jul-75	B.6.E.45	AFW	pipe	crack	fatigue		4"	L	47
Monticello	May-83	B.6.D.44	MSS	pipe	hole	erosion		6"	L	48
P Bottom 2	Jun-86	B.8.C.377	SSWS	pipe	hole	pitting		3"	L	49
Q Cities 2	Apr-84	B.5.B.57	CRDM	pipe	p hole	IGSCC	seeping	12"	L	50
Q Cities 2	Apr-84	B.5.B.57	CRDM	pipe	p hole	IGSCC	seeping	12"	L	51
Q Cities 2	Apr-84	B.5.B.57	CRDM	pipe	p hole	IGSCC	seeping	12"	L	52
Q Cities 2	Apr-84	B.5.B.57	CRDM	pipe	p hole	IGSCC	seeping	12"	L	53
Q Cities 2	Apr-84	B.5.B.57	CRDM	pipe	p hole	IGSCC	seeping	12"	L	54
Q Cities 2	Apr-84	B.5.B.57	CRDM	pipe	p hole	IGSCC	seeping	12"	L	55
Q Cities 2	Apr-84	B.5.B.57	CRDM	pipe	p hole	IGSCC	seeping	12"	L	56
Q Cities 2	Apr-84	B.5.B.57	CRDM	pipe	p hole	IGSCC	seeping	12"	L	57
Q Cities 2	Apr-84	B.5.B.57	CRDM	pipe	p hole	IGSCC	seeping	12"	L	58
Q Cities 2	Nov-86	B.5.B.77	CRDM	pipe	p hole	IGSCC		12"	L	59
Dresden 3	Jan-75	B.6.E.57	AFW	pipe	p hole	erosion		6"	L	60

Table A-1. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Comp Size (diam)	Classification ^a	
									size	cnt
Dresden 3	Jun-77	B.6.E.83	AFW	pipe	p hole	erosion		6"	L	61
Dresden 3	Mar-78	B.6.E.90	AFW	pipe	p hole	erosion		6"	L	62
Dresden 3	Jun-78	B.6.E.93	AFW	pipe	p hole	erosion		6"	L	63
Dresden 3	Sep-78	B.6.E.103	AFW	pipe	p hole	erosion		6"	L	64
Dresden 3	Sep-78	B.6.E.103	AFW	pipe	p hole	erosion		6"	L	65
Br Ferry 2	Sep-82	B.7.F.178		pipe	p hole	pitting		3"	L	66
Br Ferry 2	Oct-82	B.7.F.178		pipe	p hole	pitting		3"	L	67
Cooper	Jun-83	B.8.A.114	RWCU	pipe	p hole	IGSCC		6"	L	68
Cooper	Jun-83	B.8.A.114	RWCU	pipe	p hole	IGSCC		6"	L	69
Bruns 1	Nov-84	B.8.A.135	RWCU	pipe	p hole	IGSCC		>3"	L	70
Cooper	Oct-75	B.8.C.86	SSWS	pipe	p hole	erosion		18"	L	71
Oyster Cr	Jan-80	B.6.E.124	CDS	pipe	pitting	corrosion		6"	L	72
Oyster Cr	Jan-80	B.6.E.124	AFW	pipe	pitting	corrosion		10"	L	73
Perry 1	Apr-87	B.5.B.78	MSS	pipe	rupture	vibration		3"	L	1
Dresden 2	May-71	B.12.4	SI-IL	pipe	rupture	hi press		18"	L	2
9-mile Pt 1	Mar-82	B.5.B.39	CRDM	pump	crack		weeping		U	1
9-mile Pt 1	Mar-82	B.5.B.39	CRDM	pump	crack		weeping		U	2
Dresden 3	Feb-75	B.6.E.38	AFW	pump	crack	fatigue			U	3
Hatch 1	Oct-85	B.12.105	WST	pump	crack				U	4
Cooper	Jan-79	B.8.C.189	SSWS	pump	leak	erosion			U	5
p Bottom	Jan-74	B.11.A.45	SG	pump	leak				U	6

Table A-1. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Comp Size (diam)	Classification ^a	
									size	cnt
Susquehanna 2	Jan-88	B.7.E.443	SI-HPCI	pump	leak				U	7
Dresden 2	Sep-74	B.6.E.33	APW	pump	rupture	vibration		<1"	S	1
Q Cities 1	Aug-82	B.8.C.295	SSWS	pump	rupture	stress		1/2"	S	2
Dresden 3	Jun-79	B.7.C.81	CRDM	pump	leak			>3"	L	1
Oyster Cr	Sep-82	B.12.85	WST	tank	crack	corrosion			U	1
Millstone 1	Dec-75	B.12.36	WST	tank	hole	corrosion	7000 gal		U	2
Fitzpatrick	Jan-76	B.13.53	WST	tank	hole	corrosion			U	3
Oyster Cr	Oct-78	B.6.E.104	CDS	tank	pitting	corrosion			U	4
9-Mile Pt 2	Nov-87	B.6.E.272	CDS	tank	rupture	installer	400 gpm		U	1
LaSalle 1	Oct-82	B.6.E.158		valve	crack	vibration			U	1
9-Mile Pt 1	Jul-77	B.7.F.74		valve	crack				U	2
P Bottom 2	Nov-75	B.7.D.77	RHR	valve	crack				U	3
Arnold	Dec-80	B.8.A.74	RWCU	valve	crack	erosion			U	4
Dresden 2	Nov-72	B.7.E.22	SI-HPCI	valve	leak				U	5
Cooper	Nov-76	B.5.D.26	CRDM	valve	leak				U	6
Pilgrim	Sep-73	B.5.C.53	PCS	valve	leak	erosion			U	7
Arnold	Aug-80	B.5.C.278	MSS	valve	leak				U	8
Hatch 1	May-86	B.5.D.83	MSS	valve	leak				U	9

Table A-1. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Comp Size (diam.)	Classification ^a	
									size	cnt
Q Cities 2	Mar-86	B.6.E.276	APW	valve	leak				U	10
Hatch 2	Apr-86	B.6.G.4	APW	valve	leak				U	11
Bruns 2	Aug-75	B.7.A.30	RCIC	valve	leak				U	12
Pilgrim	Apr-83	B.7.A.169	RCIC	valve	leak				U	13
LaSalle 1	Mar-84	B.7.A.260	RCIC	valve	leak				U	14
Q Cities 2	May-89	B.7.A.261	RCIC	valve	leak				U	15
Dresden 2	Jun-83	B.7.D.330	SI-HPCI	valve	leak				U	16
Dresden 2	May-80	B.7.E.198	SI-HPCI	valve	leak				U	17
Dresden 3	Nov-81	B.7.E.253	SI-HPCI	valve	leak				U	18
Pilgrim	Oct-82	B.7.E.289	SI-HPCI	valve	leak				U	19
Dresden 2	Jul-82	B.7.E.298	SI-HPCI	valve	leak	loose			U	20
Fitzpatrick	Mar-86	B.7.E.387	SI-HPCI	valve	leak				U	21
Oyster Cr	May-75	B.7.F.42	CDS	valve	leak				U	22
P Bottom 2	Jun-75	B.8.A.21		valve	leak				U	23
LaSalle 1	Aug-83	B.8.A.116	RWCU	valve	leak				U	24
Hatch 1	May-85	B.8.A.156	RWCU	valve	leak				U	25
Hatch 1	May-85	B.8.A.156	RWCU	valve	leak				U	26
Dresden 2	Jun-77	B.8.C.107	TBN	valve	leak				U	27
Dresden 1	Jun-77	B.8.C.108	MSS	valve	leak				U	28
Bruns 2	Apr-83	B.9.B.240	PCS	valve	leak				U	29
Dresden 1	Feb-75	B.12.31	WST	valve	leak	th stress	6 gpm		U	30
Dresden 1	Feb-76	B.9.F.10	CS	valve	leak				U	31
Limerick 1	Oct-89	B.11.A.903	RWCU	valve	leak				U	32

Table A-1. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Comp Size (diam)	Classification ^a	
									size	cnt
Limerick 1	Oct-89	B.11.A.903	RWCU	valve	leak				U	33
Fitzpatrick	Aug-89	B.7.E.472	SI-HPCI	valve	leak				U	34
Millstone 1	Oct-71	B.5.C.4	PCS	valve	open	erosion	2500 gpm		U	35
LaSalle 1	Feb-83	B.5.C.371	HSS	valve	crack	bad weld		2"	S	1
LaSalle 1	Feb-83	B.5.C.371	HSS	valve	crack	bad weld		2"	S	2
Dresden 3	Jun-82	B.6.E.159	AFW	valve	crack	th stress		1"	S	3
Dresden 3	Nov-82	B.6.E.159	AFW	valve	crack	th stress		1"	S	4
LaSalle 1	Oct-82	B.6.E.162		valve	crack	instaler		3/4"	S	5
Br Ferry 1	Dec-75	B.7.C.26	CRDM	valve	crack	vibration		3/4"	S	6
Br Ferry 1	Dec-82	B.7.C.108	CRDM	valve	crack	vibration		1/2"	S	7
Dresden 2	Dec-74	B.7.D.53	RHR	valve	crack	stress		1"	S	8
Dresden 2	May-80	B.7.D.238	SI-LPSI	valve	crack	fatigue		3/4"	S	9
Arnold	Nov-81	B.8.A.85	RWCU	valve	crack	IGSCC		<3"	S	10
Dresden 2	May-80	B.7.D.238	SI-HPCI	valve	crack	fatigue		3/4"	S	11
S-Hile Pt 1	Sep-85	B.8.A.176	RWCU	valve	leak			1"	S	12
Oyster Cr	Jun-82	B.6.E.157	CDS	valve	rupture	vibration	160 gpm	1/2"	S	1
Arnold	Mar-78	B.8.A.48	RWCU	valve	crack	IGSCC		4"	L	1
Dresden 2	Aug-77	B.7.E.119	SI-HPCI	valve	leak			14"	L	2
Monticello	Nov-78	B.8.C.159	SSHS	valve	p hole	erosion		10"	L	3

a. See Appendix D for explanations of abbreviations.

b. B.6.D.26 indicates BWR volumes, system category VI, system D, and event 28 in NPE.

Table A-2. PWR Leakage and rupture events

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Palladas	Mar-70	P.8.A.4	CVCS-CH	elbow	crack	vibration			U	1
P. Calhoun	May-78	P.8.A.283	CVCS-CH	elbow	crack	vibration			U	2
Crystal R 3	Aug-79	P.8.A.391	CVCS-MJ	elbow	crack	vibration			U	3
Sienna	Jul-85	P.8.D.421	SG	elbow	hole	erosion			U	4
St Lucie 1	Dec-80	P.8.B.353	SSWS	elbow	leak	corrosion			U	5
Indian Pt 3	Feb-86	P.9.D.385	MSSS	elbow	leak				U	6
Cal Clute 1	Dec-75	P.5.D.134	SG	elbow	leak	erosion			U	7
Rancho S 1	Oct-82	P.8.A.646	BAS	elbow	leak	corrosion			U	8
Rancho S 1	Oct-82	P.8.A.646	BAS	elbow	leak	corrosion			U	9
Indian Pt 2	Sep-78	P.8.B.210	RHR	elbow	leak	erosion			U	10
Clinta	Dec-76	P.8.A.226	SSWS	elbow	p hole				U	11
Indian Pt 2	Mar-79	P.8.A.354	PCS	elbow	p hole	pitting	0.017 gpm		U	12
Yankee R	Sep-83	P.8.D.296	TSN	elbow	crack	erosion		2"	S	1
Indian Pt 2	Mar-77	P.8.A.193	CVCS-CH	elbow	crack	vibration		2"	S	2
CT Yankee	Apr-77	P.8.A.292	BAS	elbow	crack	corrosion		2"	S	3
CT Yankee	Apr-77	P.8.A.292	PAS	elbow	crack	corrosion		2"	S	4
CT Yankee	Oct-75	P.8.A.357	BAS	elbow	crack	corrosion		2"	S	5
Arkansas 2	Jul-80	P.8.A.450	CVCS-CH	elbow	crack	vibration		1"	S	6
Indian Pt 3	May-86	P.8.A.685	CVCS-CH	elbow	crack	vibration		3/4"	S	7
Sienna	Dec-76	P.8.A.172	CVCS-LD	elbow	p hole			2"	S	8
Rancho S	Feb-86	P.8.B.688	RHR	elbow	p hole	erosion	1 gal	1"	S	9
Rancho S	Feb-86	P.8.B.688	DHR	elbow	p hole	erosion	1 gpm	1"	S	10

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
3-Mile Is 1	Nov-76	P.8.B.113	SSWS	elbow	crack	installer		24"	L	1
St. Louis 1	Feb-80	P.8.B.301	SSWS	elbow	crack			40 1/2"	L	2
Conoco 3	Dec-86	P.8.D.408	SG	elbow	hole	erosion		10"	L	3
Sunny 1	Dec-86	P.8.E.735	APW	elbow	hole	erosion		18"	L	4
Crystall R 3	Aug-86	P.8.B.730	SSWS	elbow	leak	erosion		14"	L	5
Crystall R 3	Aug-86	P.8.B.730	SSWS	elbow	leak	erosion		14"	L	6
Crack 2	Nov-79	P.8.E.211	APW	elbow	leak	crack		16"	L	7
Crystall R 3	Aug-86	P.8.B.730	SSWS	elbow	p hole	erosion		14"	L	8
Crystall R 3	Aug-86	P.8.B.730	SSWS	elbow	p hole	erosion		14"	L	9
Cal Cluff 1	Nov-84	P.8.E.580	TBN	elbow	rupture	erosion		>3"	L	1
Occree 2	Jun-82	P.8.D.252	TBN	elbow	rupture	erosion		24"	L	2
Pt Beach	Apr-70	P.8.A.12	CVCS-CH	flange	crack	installer			U	1
Pt Beach	Apr-70	P.8.A.12	CVCS-CH	flange	crack	installer			U	2
Catawba 1	Jun-86	P.8.A.765	CVCS	flange	crack	vibration	1.5 gpm		U	3
Turkey Pt 3	Jan-76	P.9.F.7	PCS	flange	crack	stress	12 gpm		U	4
Turkey Pt 3	Jan-76	P.9.F.7	PCS	flange	crack	stress			U	5
Sunny 1	Jul-81	P.8.E.361	APW	flange	failed	erosion			U	6
Cal Cluff 1	Apr-74	P.3.12	PCS	flange	leak				U	7
Prattville 1	Jan-76	P.3.18	PCS	flange	leak				U	8
Sunny 3	Aug-75	P.7.A.95	BAS	flange	leak	corrosion			U	9
Beaver V 1	Mar-78	P.7.A.228	BAS	flange	leak				U	10

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Y Anna 1	Sep-79	P.7.B.69	DSS	flange	leak	deterior.			U	11
Salem 1	Nov-84	P.8.B.600	SSWS	flange	leak	corrosion			U	12
Salem 1	Nov-84	P.8.B.600	SSWS	flange	leak	corrosion			U	13
Robinson 2	Jun-87	P.8.B.760	RR	flange	leak	installer			U	14
Yorkee 2	Apr-88	P.8.A.13	TRN	flange	leak	erosion			U	15
Wallstone 2	Jan-91	P.11.A.477	CS	flange	leak	installer			U	16
Indian Pt C	Oct-93	P.8.B.678	SSWS	flange	p hole	corrosion	1 gpm		U	17
Wallstone 2	Jun-81	P.7.A.390	SI	flange	crack	stress		1 1/2"	S	1
3-Mile Is 1	Jan-81	P.8.A.505	CVCS-MU	flange	crack	fatigue		1"	S	2
Salem 2	Aug-82	P.5.F.37	DSS	flange	leak		0.35 gpm	<3"	S	3
Salem 2	Oct-82	P.7.C.110	SSWS	flange	leak	installer	0.5 gpm	<3"	S	4
Salem 1	Jul-81	P.8.B.410	SSWS	flange	leak	fatigue	0.025 gpm	3/4"	S	5
Robinson 2	Nov-87	P.8.B.926	SSWS	flange	leak	corrosion		2"	S	6
Sigma 1	Mar-91	P.8.A.696	SAS	flange	p hole	ISCC		2"	S	7
Yorkee 2	May-82	P.7.E.135	FWTR	flange	blown			8"	L	1
3-Mile Is 1	Jan-79	P.8.18	PCS	flange	leak	lead inst		>3"	L	2
Turkey Pt 3	Jun-85	P.8.30	PCS	flange	leak			>3"	L	3
North Anna	Aug-89	P.5.E.112	PRR	flange	leak		2.6 gpm	3"	L	4
Trojan	May-77	P.8.A.015	CVCS	flange	leak	crack		12"	L	5
Seaver V 1	Sec-92	P.7.E.145	FWTR	flange	rupture	stress		12"	L	1

Table A-2. (continued)

Plant Name ^a	Date	APE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com size (diam)	Classification ^a	
									size	ent
Ballast	10-00	P. 6.6.4.82	CVCS-10	flange-ht x	crack	corrosion			U	1
Crack Co 1	01-00	P. 6.6.4.20	SS	flange-ht x	leak	th fatigue			U	2
Crack Co 2	01-00	P. 6.6.4.20	SS	flange-ht x	leak	th fatigue			U	3
Salem 0	Aug-01	P. 6.6.4.12	SSWS	flange-ht x	leak				U	4
Salem 3	May-02	P. 6.6.4.20	SSWS	flange-ht x	leak	erosion			U	5
Salem 3	May-02	P. 6.6.4.20	SSWS	flange-ht x	leak	erosion			U	6
S. Crack 1	01-04	P. 6.6.4.20	CRW	flange-ht x	leak	erosion	15 gpm		U	7
S. Crack 1	01-04	P. 6.6.4.20	CRW	flange-ht x	leak	erosion	15 gpm		U	8
Rockwell 2	Nov-07	P. 6.6.4.20	SSWS	flange-ht x	leak	corrosion		2"	U	1
Crack 2	10-08	P. 6.6.4.20	CRW	flange-ht x	crack			>3"	U	1
Crack 2	09-09	P. 6.6.4.22	SS	flange-ht x	leak	loose		18"	U	2
St. Louis 1	Apr-07	P. 6.6.4.20	SS	flange-ht x	leak	corrosion		>3"	U	3
Rockwell 2	01-01	P. 6.6.4.21	SS	flange-ht x	leak	erosion	3.4 gpm	>3"	U	4
Rockwell	01-02	P. 6.6.4.12	SS	flange-ht x	leak			>3"	U	5
Rockwell	01-04	P. 6.6.4.12	SS	flange-ht x	leak			>3"	U	6
Seaver VI	Nov-08	P. 6.6.4.20	SS	flange-ht x	leak	plugged		>3"	U	7
Rockwell	09-08	P. 6.6.4.21	CVCS-CH	flange-pump	crack	vibration			U	1
Rockwell 1	09-09	P. 6.6.4.20	CRW	flange-pump	leak	corrosion			U	2
Rockwell 1	09-09	P. 6.6.4.21	AFW	flange-pump	leak				U	3
Seaver VI	01-09	P. 6.6.4.20	ST-101	flange-pump	leak	installer			U	4

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cat
Beaver V 1	Aug-65	P.8.A.60	SLPSI	flange-pump	leak	installer			U	5
Cooney 2/3	Aug-60	P.8.A.97	PS	flange-pump	leak	corrosion	0.5 gpm		U	6
Kearney	Dec-60	P.8.A.45	BIS	flange-pump	leak				U	7
McGuire 1	Nov-62	P.8.A.63	COV	flange-pump	leak				U	8
OT Yankee	Oct-65	P.8.A.65	CUCS-CH	flange-pump	leak				U	9
Surry 2	Jun-75	P.8.B.54	SSWS	flange-pump	leak				U	10
Surry 1	Oct-73	P.8.B.24	CS	flange-pump	leak				U	11
Turkey 2/4	Sep-75	P.8.B.25	SSCS	flange-pump	leak				U	12
Robinson 2	Nov-61	P.8.B.46	RR	flange-pump	leak		4 gpm		U	13
Yankee 2	Sep-60	P.8.A.19	CS	flange-pump	leak				U	14
Kearney	Aug-62	P.8.A.60	BIS	flange-pump	leak	corrosion			U	15
Robinson 2	Nov-76	P.8.17	CCOV	flange-pump	p hole	degradation			U	16
Salem 1	Sep-76	P.8.B.19	SSWS	flange-pump	leak	corrosion		>20"	L	1
Salem 1	Sep-76	P.8.B.19	SSWS	flange-pump	leak	corrosion		>20"	L	2
Salem 1	Sep-76	P.8.B.19	SSWS	flange-pump	leak	corrosion		>20"	L	3
Salem 1	Sep-76	P.8.B.19	SSWS	flange-pump	leak	corrosion		>20"	L	4
Salem 1	Sep-76	P.8.B.19	SSWS	flange-pump	leak	corrosion		>20"	L	5
Salem 1	Sep-76	P.8.B.19	SSWS	flange-pump	leak	corrosion		>20"	L	6
F. Calhoun 1	Mar-60	P.8.A.69	PS	flange-pump	leak			>3"	L	7
Kearney 1	Mar-75	P.8.B.31	RR	flange-tank	leak		0.8 gpm		U	1
OT Yankee	Feb-77	P.12.A.67	RTT	flange-tank	leak	corrosion	1000 gal		U	2

Table A-2. (continued)

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^c	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Woolfite 1	May-91	P.7.A.319	SI	flange-valve	leak				U	20
Arkansas 1	Oct-99	P.7.A.502	SI-HP01	flange-valve	leak		1 gpm		U	21
Kewaunee	Apr-94	P.7.D.103	CVCS	flange-valve	leak				U	22
Kewaunee	Apr-94	P.7.D.103	CVCS	flange-valve	leak				U	23
Cr. Yankee	May-76	P.8.A.021	CVCS-CH	flange-valve	leak	erosion			U	24
Doonee 1	Aug-79	P.8.A.381	PCS	flange-valve	leak				U	25
Kewaunee	Jan-91	P.8.A.536	BAS	flange-valve	leak	corrosion			U	26
Cock 1	Oct-91	P.8.A.554		flange-valve	leak	corrosion			U	27
Cock 2	Jan-82	P.8.B.463	RDR	flange-valve	leak				U	28
Palo Verde 3	Mar-87	P.8.B.691	DHR	flange-valve	leak				U	29
Palo Verde 3	Mar-88	P.8.B.691	DHR	flange-valve	leak				U	30
Palo Verde 3	Jun-88	P.8.B.861	DHR	flange-valve	leak		20 gpm		U	31
Pt. Beach 1	Sec-82	P.13.A.122		flange-valve	leak	fatigue			U	32
Rockwood 2	Mar-85	P.13.C.2591	SG	flange-valve	leak				U	33
N. Anna 2	Jan-83	P.15.D.393	SS	flange-valve	leak				U	34
Yankee 3	Apr-83	P.15.E.157	PCS	flange-valve	leak				U	35
Wattsstone 2	Jul-92	P.15.E.168	PCS	flange-valve	leak		>1 gpm		U	36
Doonee 2	Oct-80	P.16.E.301	POSV	flange-valve	leak				U	37
Cal. Cluff 1	May-78	P.16.A.285	CVCS-CH	flange-valve	p. hole	fatigue			U	38
Salem 2	May-83	P.16.B.571	SSWS	flange-valve		erosion			U	39
N. Anna 2	Jan-82	P.16.D.341	SG	flange-valve					U	40
Wattsstone 2	Jan-76	P.16.A.159	CVCS-CH	flange-valve	crack	fatigue		3/4"	S	1

Table A-2. (continued)

Event Name	Date	Vessel	System	Component	Failure Mode	Failure Cause	Leakage	Pipe/Con Size (dia)	Classification	
									Size	Out
Crack	5/1/83	0.0.0.00	000-00	Stage-valve	Crack	Fatigue		3/4"	3	2
Leak	5/1/83	0.0.0.00	MS	Stage-valve	Leak			3/4"	3	3
Leak	5/1/83	0.0.0.00	000-00	Stage-valve	Leak		13.4 gpm	3/4"	3	4
Crack	5/1/83	0.0.0.00	000-00	Stage-valve	Crack	Vibration		3/4"	3	5
Leak	5/1/83	0.0.0.00	000-00	Stage-valve	Leak		5 gpm	<3"	3	6
Crack	5/1/83	0.0.0.00	000-00	Stage-valve	Leak	Corrosion		18"	1	1
Crack	5/1/83	0.0.0.00	000-00	Stage-valve	Leak	Corrosion		3"	1	2
Crack	5/1/83	0.0.0.00	000-00	Stage-valve	Leak			6"	1	3
Crack	5/1/83	0.0.0.00	000-00	Stage-valve	Leak			6"	1	4
Crack	5/1/83	0.0.0.00	000-00	Stage-valve	Leak			6"	1	5
Crack	5/1/83	0.0.0.00	000-00	Stage-valve	Leak	Corrosion		6"	1	6
Crack	5/1/83	0.0.0.00	000-00	Stage-valve	Leak					
Crack	5/1/83	0.0.0.00	000-00	Stage-valve	Crack (T)	SSCC			3	1
Crack	5/1/83	0.0.0.00	000-00	Stage-valve	Crack (T)				3	2
Crack	5/1/83	0.0.0.00	000-00	Stage-valve	Crack (T)	Fatigue			3	3
Crack	5/1/83	0.0.0.00	000-00	Stage-valve	Leak (T)		<1 gpm		3	4
Crack	5/1/83	0.0.0.00	000-00	Stage-valve	Leak (T)		<1 gpm		3	5
Crack	5/1/83	0.0.0.00	000-00	Stage-valve	Leak (T)		Subcritical		3	6
Crack	5/1/83	0.0.0.00	000-00	Stage-valve	Leak (T)				3	7
Crack	5/1/83	0.0.0.00	000-00	Stage-valve	Leak (T)				3	8
Crack	5/1/83	0.0.0.00	000-00	Stage-valve	Leak (T)				3	9
Crack	5/1/83	0.0.0.00	000-00	Stage-valve	Leak (T)				3	10

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Salem 1	Sep-81	P.8.B.426	SSWS	ht xchanger	leak (T)		0.5 gpm		U	11
Salem 2	Sep-81	P.8.B.426	SSWS	ht xchanger	leak (T)		0.5 gpm		U	12
Salem 1	Sep-81	P.8.B.426	SSWS	ht xchanger	leak (T)		0.5 gpm		U	13
Salem 1	Sep-81	P.8.B.426	SSWS	ht xchanger	leak (T)		0.5 gpm		U	14
Robinson 2	Jul-83	P.8.B.583	SSWS	ht xchanger	leak (T)	erosion			U	15
Robinson 2	Jul-83	P.8.B.583	SSWS	ht xchanger	leak (T)	erosion			U	16
Robinson 2	Jul-83	P.8.B.583	SSWS	ht xchanger	leak (T)	erosion			U	17
Robinson 2	Jul-83	P.8.B.583	SSWS	ht xchanger	leak (T)	erosion			U	18
Robinson 2	Jul-83	P.8.B.583	SSWS	ht xchanger	leak (T)	erosion			U	19
Robinson 2	Jul-83	P.8.B.583	SSWS	ht xchanger	leak (T)	erosion			U	20
Salem 1	Jul-85	P.8.B.655	SSWS	ht xchanger	leak (T)	loose	1.3 gpm		U	21
Cal Cliff 2	May-84	P.8.B.620	CSS	ht xchanger	leak (?)	corrosion			U	22
Indian Pt 2	Aug-82	P.8.B.678	SSWS	ht xchanger	leak (T)	corrosion			U	23
Indian Pt 2	Sep-82	P.8.B.678	SSWS	ht xchanger	leak (T)	corrosion	1 gpm		U	24
Indian Pt 2	Sep-82	P.8.B.678	SSWS	ht xchanger	leak (T)	corrosion	1 gpm		U	25
Salem 2	Sep-82	P.11.A.714	D5	ht xchanger	leak (?)	erosion			U	26
Oconee 1	Jul-79	P.16.C.878	SI-LPSI	ht xchanger	leak (T)				U	27
Kewaunee	Dec-83	P.8.B.588	SSWS	ht xchanger	leaks (T)	erosion			U	28
Salem 1	Jul-85	P.8.B.655	SSWS	ht xchanger	loose (T)				U	29
Salem 1	Aug-81	P.8.B.420	SSWS	ht xchanger	p hole (T)		0.5 gpm		U	33

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Salem 1	Sep-81	P.8.B.420	SSWS	ht xchanger	p hole (T)		1 gpm		U	31
Salem 1	Mar-81	P.7.C.65	SSWS	ht xchanger	p hole (T)		1 gpm		U	32
Salem 1	Apr-81	P.7.C.67	SSWS	ht xchanger	leak (T)			3/4"	U	33
Cal Cliff 1	Jul-76	P.8.B.130	CSS	ht xchanger	leak (?)				U	34
Indian Pt 1	Dec-72	P.9.B.20	PRZR	ht xchanger	(C)				U	35
Ginna	Feb-81	P.7.C.64	SSWS	ht xchanger	rupture (T)	plug lost			U	2
Yankee R	Sep-80	P.5.D.22	SG	ht xchanger	crack (S)	loose		1"	S	1
Salem 1	Feb-84	P.7.C.117	SSWS	ht xchanger	crack (T)	corrosion		3/4"	S	1
Salem 2	Aug-82	P.7.C.110	SSWS	ht xchanger	leak (T)	erosion		1/2"	S	2
Salem 2	Aug-82	P.7.C.110	SSWS	ht xchanger	leak (T)	erosion		1/2"	S	3
Salem 2	Aug-82	P.7.C.110	SSWS	ht xchanger	leak (T)	erosion		1/2"	S	4
Salem 2	Aug-82	P.7.C.110	SSWS	ht xchanger	leak (T)	erosion		1/2"	S	5
Salem 2	Aug-82	P.7.C.110	SSWS	ht xchanger	leak (T)	erosion		1/2"	S	6
Salem 2	Aug-82	P.7.C.110	SSWS	ht xchanger	leak (T)	erosion		1/2"	S	7
Salem 2	Aug-82	P.7.C.110	SSWS	ht xchanger	leak (T)	erosion		1/2"	S	8
Salem 2	Aug-82	P.7.C.110	SSWS	ht xchanger	leak (T)	erosion		1/2"	S	9
Salem 2	Aug-82	P.7.C.110	SSWS	ht xchanger	leak (T)	erosion		1/2"	S	10
Salem 2	Sep-82	P.7.C.110	SSWS	ht xchanger	leak (T)	erosion		1/2"	S	12
Salem 2	Sep-82	P.7.C.110	SSWS	ht xchanger	leak(T)	erosion		1/2"	S	12
Salem 2	Sep-82	P.7.C.110	SSWS	ht xchanger	leak(T)	erosion		1/2"	S	13

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Salem 2	Sep-82	P.7.C.110	SSWS	ht xchanger	leak(T)	erosion		1/2"	S	14
Salem 2	Sep-82	P.7.C.110	SSWS	ht xchanger	leak(T)	erosion		1/2"	S	15
Salem 2	Oct-82	P.7.C.110	SSWS	ht xchanger	leak(T)	erosion		1/2"	S	16
Salem 2	Oct-82	P.7.C.110	SSWS	ht xchanger	leak(T)	erosion		1/2"	S	17
Salem 2	Oct-82	P.7.C.110	SSWS	ht xchanger	leak(T)	erosion		1/2"	S	18
Salem 2	Oct-82	P.7.C.110	SSWS	ht xchanger	leak(T)	erosion		1/2"	S	19
Salem 2	Oct-82	P.7.C.110	SSWS	ht xchanger	leak(T)	erosion		1/2"	S	20
Salem 2	Oct-82	P.7.C.110	SSWS	ht xchanger	leak(T)	erosion		1/2"	S	21
Salem 2	Nov-82	P.7.C.110	SSWS	ht xchanger	leak(T)	erosion		1/2"	S	22
Salem 2	Nov-82	P.7.C.110	SSWS	ht xchanger	leak(T)	erosion		1/2"	S	23
Salem 2	Aug-82	P.7.C.72	SSWS	ht xchanger	rupture (T)	vibration	12,000 gal	1/2"	S	1
Salem 1	Nov-82	P.8.D.517	SSWS	ht xchanger	crack(?)			24"	L	1
Yankee R	Aug-84	P.9.G.86	ACC	pipe	blown	instal er		3/8"	U	1
Beaver V 1	Sep-83	P.8.A.694	ACC	pipe	broke	fatigue			U	2
Surry 1	Oct-78	P.7.A.189	BAS	pipe	crack	corrosion			U	3
Arkansas 1	Nov-79	P.7.A.236	SI-LPSI	pipe	crack	fatigue			U	4
Arkansas 1	Nov-74	P.7.B.15	CSS	pipe	crack	IGSCC			U	5
Arkansas 1	Nov-74	P.7.B.15	CSS	pipe	crack	IGSCC			U	6
Arkansas 1	Nov-74	P.7.B.15	CSS	pipe	crack	IGSCC			U	7
Crystal R 3	Jan-77	P.7.B.33	CSS	pipe	crack	stress			U	8
Crystal R 3	Jan-77	P.7.B.33	CSS	pipe	crack	stress			U	9
Indian Pt 2	Jul-79	P.7.B.63	CSS	pipe	crack	vibration			U	10
H Anna 1	Sep-84	P.7.B.156	CSS	pipe	crack				U	11

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Salem 1	Aug-78	P.7.C.39	SSWS	pipe	crack	corrosion			U	12
Salem 1	Aug-78	P.7.C.39	SSWS	pipe	crack	corrosion			U	13
Pt Beach	Jan-79	P.8.A.12	CVCS-CH	pipe	crack	vibration			U	14
Pt Beach	Jan-79	P.8.A.12	CVCS-CH	pipe	crack	vibration			U	15
Kewaunee	Apr-74	P.8.A.44	CVCS-CH	pipe	crack	vibration	spray		U	16
Indian Pt 2	Jul-75	P.8.A.93	CVCS-CH	pipe	crack	vibration			U	17
Yankee R	Feb-76	P.8.A.120	CVCS-CH	pipe	crack	vibration			U	18
Rancho S	Mar-76	P.8.A.128	CVCS	pipe	crack	bad weld			U	19
Yankee R	Sep-76	P.8.A.154	CVCS-CH	pipe	crack	bad weld			U	20
Palisades	Dec-76	P.8.A.166	CVCS-CH	pipe	crack	vibration	<0.3 gpm		U	21
Cal Cliff 2	Dec-76	P.8.A.184	CVCS-CH	pipe	crack	fatigue			U	22
Cal Cliff 2	Jan-77	P.8.A.184	CVCS-CH	pipe	crack	fatigue			U	23
Cal Cliff 2	Jan-76	P.8.A.184	CVCS-CH	pipe	crack	fatigue			U	24
Cal Cliff 2	Jan-76	P.8.A.184	CVCS-CH	pipe	crack	fatigue			U	25
F Calhoun	Feb-78	P.8.A.259	CVCS-CH	pipe	crack	vibration			U	26
Cal Cliff 2	Jan-78	P.8.A.264	CVCS-CH	pipe	crack	vibration			U	27
Cal Cliff 2	Feb-78	P.8.A.265	CVCS-CH	pipe	crack	vibration			U	28
Cal Cliff 2	Feb-78	P.8.A.265	CVCS-CH	pipe	crack	vibration			U	29
Cal Cliff 2	Feb-78	P.8.A.265	CVCS-CH	pipe	crack	vibration			U	30
F Calhoun	Apr-78	P.8.A.280	CVCS-CH	pipe	crack	vibration			U	31
Turkey Pt 4	Mar-78	P.8.A.283	CVCS-CH	pipe	crack	vibration			U	32
CT Yankee	May-78	P.8.A.289	CVCS-CH	pipe	crack	fatigue			U	33
Arkansas 1	Sep-79	P.8.A.312	CVCS-WU	pipe	crack	stress			U	34

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Indian Pt 2	Nov-76	P.S.A.319	PCS	pipe	crack	vibration	0.083 gpm		U	35
Cal Cliff 2	Dec-76	P.S.A.329	CVCS-CH	pipe	crack	fatigue	>0.3gpm		U	36
Cal Cliff 1	Feb-79	P.S.A.336	AUX	pipe	crack				U	37
N Anna 1	May-79	P.S.A.359	CVCS-CH	pipe	crack	fatigue			U	38
Indian Pt 3	Jan-80	P.S.A.407	CVCS-CH	pipe	crack				U	39
Arkansas 2	May-80	P.S.A.435	CVCS-CH	pipe	crack	vibration			U	40
Arkansas 2	Aug-80	P.S.A.453	CVCS-CH	pipe	crack	vibration			U	41
Arkansas 2	Apr-80	P.S.A.472	CVCS-MU	pipe	crack	vibration			U	42
F Calhoun	Oct-80	P.S.A.474	CVCS-CH	pipe	crack	vibration			U	43
F Calhoun	Dec-80	P.S.A.481	CVCS-CH	pipe	crack	vibration			U	44
Robinson 2	Dec-80	P.S.A.484	CVCS-CH	pipe	crack	vibration			U	45
N Anna 2	Dec-80	P.S.A.486	CVCS-CH	pipe	crack	vibration			U	46
3-Mile Is 1	Jan-81	P.S.A.505	CVCS-MU	pipe	crack	pitting			U	47
Turkey Pt 4	Feb-81	P.S.A.514	PCS	pipe	crack	vibration			U	48
Zion 1	Jan-81	P.S.A.539	CVCS-CH	pipe	crack	vibration			U	49
Cal Cliff 2	Jul-81	P.S.A.543	CVCS-CH	pipe	crack	bad weld			U	50
Arkansas 2	Feb-82	P.S.A.595	CVCS-CH	pipe	crack	vibration	0.0003 gpm		U	51
Turkey Pt 3	Mar-82	P.S.A.605	CVCS-CH	pipe	crack	vibration			U	52
Arkansas 1	Apr-82	P.S.A.617	CVCS-CH	pipe	crack	vibration			U	53
Crystal R 3	Jan-83	P.S.A.664	CVCS-CH	pipe	crack				U	54
Kavanaugh	Oct-83	P.S.A.697	CVCS	pipe	crack	fatigue			U	55
Arkansas 2	Apr-82	P.S.A.704	CVCS-CH	pipe	crack	vibration			U	56
Crystal R 3	Feb-82	P.S.A.715	CVCS-MU	pipe	crack	vibration			U	57

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	ent
Crystal R 3	Oct-83	P.8.A.718	CVCS-WU	pipe	crack	fatigue			U	58
Secoyah 2	Jul-85	P.8.A.813	CVCS	pipe	crack	fatigue			U	59
Secoyah 1	Aug-85	P.8.A.813	CVCS	pipe	crack	fatigue			U	60
Arkansas 1	Jun-74	P.8.B.34	RHR	pipe	crack	vibration			U	61
Yankee R	Feb-75	P.8.B.45	RHR	pipe	crack				U	62
Yankee R	Mar-75	P.8.B.45	RHR	pipe	crack				U	63
Arkansas 2	May-88	P.9.E.1102	ACC	pipe	crack	bad weld			U	64
Beaver V 1	Jan-82	P.5.D.342	SG	pipe	crack	froze			U	65
Turkey Pt 3	Jan-89	P.9.A.316	CRDM	pipe	crack	TSDC	12 dcm		U	66
Turkey Pt 3	Jan-89	P.9.A.316	CRDM	pipe	crack	TSDC	12 dcm		U	67
Turkey Pt 3	Jan-89	P.9.A.316	CRDM	pipe	crack	TSDC	12 dcm		U	68
F. Calhoun	Mar-79	P.11.A.299	SG	pipe	crack		0.12 gpm		U	69
Sunny 2	Aug-81	P.8.B.421	SSWS	pipe	Flood				U	70
Catawaba	Jan-88	P.9.A.295	QDS	pipe	fracture	low temp			U	71
Salem 2	Aug-82	P.5.F.37	SG	pipe	leak		0.25 gpm		U	72
N. Anna 2	Jun-80	P.7.A.259	SI-LPSI	pipe	leak				U	73
Arkansas 1	May-88	P.8.A.834	CVCS	pipe	leak	installer			U	74
Salem 1	Aug-80	P.8.B.331	SSWS	pipe	leak	corrosion			U	75
Ginna 1	Apr-81	P.8.B.391	RHR	pipe	leak	worn out			U	76
Salem 1	Nov-84	P.8.B.630	SSWS	pipe	leak	corrosion			U	77
Salem 1	Nov-84	P.8.B.630	SSWS	pipe	leak	corrosion			U	78
Salem 2	Jan-89	P.8.B.698	SSWS	pipe	leak	corrosion			U	79
Salem 2	Jan-89	P.8.B.698	SSWS	pipe	leak	corrosion			U	80

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Surry 2	Jun-86	P.8.B.715	SSWS	pipe	leak	corrosion	1 gpm		U	81
Rancho S	Jul-86	P.8.B.723	DHR	pipe	leak	erosion			U	82
Salton 1	Jan-89	P.8.B.893	SSWS	pipe	leak	corrosion			U	83
Turkey Pt 3	Jan-89	P.9.A.315	CRDM	pipe	leak	TGSOC	0.0005 gpm		U	84
Turkey Pt 3	Jan-89	P.9.A.316	CRDM	pipe	leak	TGSOC	0.0005 gpm		U	85
Turkey Pt 3	Jan-89	P.9.A.316	CRDM	pipe	leak	TGSOC	weeping		U	86
Secoyah 1	Jan-81	P.9.D.163	CDS	pipe	leak	loose			U	87
Arkansas 2	May-83	P.9.E.1102	ACC	pipe	leak	loose			U	88
Secoyah 1	May-80	P.9.F.55	PRZR	pipe	leak	loose	10 gpm		U	89
Arkansas 2	May-79	P.9.F.59	PCS	pipe	leak		0.25 gpm		U	90
Arkansas 2	Dec-82	P.9.F.105	HVCS	pipe	leak				U	91
Secoyah 1	Dec-89	P.9.F.159	CVCS-VC	pipe	leak	erosion			U	92
Catawba 1	Oct-84	P.9.H.792	PCS	pipe	leak	installation	5 gpm	5/6"	U	93
Indian Pt 1	Aug-69	P.5.A.23	PCS	pipe	leak				U	94
Indian Pt 1	Sep-71	P.5.A.23	PCS	pipe	leak	crack	0.7 gpm	3/4"	U	95
Prairie 1 1	Jan-83	P.5.B.32	BAS	pipe	leak	corrosion			U	96
Surry 2	Dec-75	P.5.D.74	SG	pipe	leak				U	97
Pallades	Jan-76	P.5.D.89	SG	pipe	leak		very low		U	98
Arkansas 2	Apr-82	P.5.D.367	SS	pipe	leak	erosion			U	99
Arkansas 2	Apr-87	P.5.E.119	PCS	pipe	leak	corrosion	100 gpm		U	100
Ca' Cliff 2	May-89	P.5.E.137	PCS	pipe	leak	corrosion			U	101
S. Croftre 3	Feb-86	P.5.E.137	PCS	pipe	leak	corrosion	0.15 gpm		U	102
Kewaunee	Aug-85	P.6.D.366	AFM	pipe	leak	ruptured			U	103

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Diablo Can 2	Oct-67	P.7.A.577	ECOS	pipe	leak	IGSCC			U	104
W. Yankee	Jan-75	P.8.A.100	CS3	pipe	leak				U	105
3-Mile Is	Jan-75	P.8.A.153	AUX	pipe	leak	erosion			U	106
Trotter	Nov-77	P.8.A.252	CVCS	pipe	leak	installer			U	107
F. Calhoun	Dec-79	P.8.A.430	CVCS	pipe	leak	crack			U	108
McGuire 1	Aug-87	P.8.B.332	PCS	pipe	leak	fatigue	40 gpm		U	109
Cal Cluff 1	Jun-74	P.8.B.68		pipe	leak	erosion			U	110
Cal Cluff 1	Jun-74	P.8.B.68		pipe	leak	erosion			U	111
Cal Cluff 1	Mar-75	P.8.B.84	SSVS	pipe	leak	erosion			U	112
Cal Cluff 1	May-75	P.8.B.84	SSVS	pipe	leak	erosion			U	113
Cal Cluff 1	Jun-76	P.8.B.92	SSVS	pipe	leak	erosion			U	114
Cal Cluff 1	Dec-76	P.8.B.123	SSVS	pipe	leak				U	115
Cal Cluff 2	Jun-77	P.8.B.131	SSVS	pipe	leak	corrosion			U	116
Arkansas 1	May-77	P.8.B.195	SFCS	pipe	leak				U	117
Arkansas 1	May-77	P.8.B.195	SFCS	pipe	leak				U	118
Arkansas 1	May-77	P.8.B.195	SFCS	pipe	leak				U	119
3-Mile Is	Feb-79	P.8.B.257	SFCS	pipe	leak	IGSCC			U	120
Willstore 2	Nov-80	P.8.B.343	SSVS	pipe	leak	corrosion			U	121
Willstore 2	Jun-81	P.8.B.405	SSVS	pipe	leak	corrosion			U	122
Salem 1,2	Dec-81	P.8.B.451	SSVS	pipe	leak	corrosion			U	123
Willstore 2	Apr-82	P.8.B.479	SSVS	pipe	leak	corrosion			U	124
Salem 1	Aug-82	P.8.B.503	SSVS	pipe	leak	erosion			U	125
Salem 2	Sep-85	P.8.B.657	SSVS	pipe	leak	corrosion			U	126

Table A-2. (continued)

Plant Name ^a	Date	NRC Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Keweenaw	Oct-83	P.8.B.793	SSWS	pipe	leak	erosion			U	127
Indiantown 1	Feb-89	P.8.B.919	SSWS	pipe	leak	corrosion			U	128
Surry 2	Oct-75	P.8.B.106	PCS	pipe	leak				U	129
Surry 2	Oct-75	P.8.B.106	PCS	pipe	leak				U	130
Salem 2	Jul-91	P.8.B.536	AFW	pipe	leak				U	131
McGuire 2	Oct-83	P.8.B.1135	PRCR	pipe	leak	loose			U	132
Salem 2	Jul-89	P.8.D.275	AFW	pipe	leak	hole			U	133
Flora 1	Aug-88	P.8.D.281	WSS	pipe	leak				U	134
W Area 1	Feb-80	P.8.E.356	RWST	pipe	leak	corrosion			U	135
Cal Cliffe 1	May-82	P.10.A.85	RWST	pipe	leak				U	136
Cal Cliffe 1	Aug-82	P.10.A.90	RWST	pipe	leak				U	137
Palisades	Jul-91	P.11.A.540	DS	pipe	leak				U	138
Millstone 1	Apr-76	P.12.A.55	WST	pipe	leak	corrosion			U	139
Millstone 2	May-76	P.12.A.55	WST	pipe	leak	corrosion			U	140
Millstone 2	May-76	P.12.A.55	WST	pipe	leak	corrosion			U	141
Trojan	Feb-77	P.12.A.53	WST	pipe	leak	corrosion			U	142
Trojan	Jan-77	P.12.A.55	WST	pipe	leak	corrosion			U	143
3-Mile Is	May-80	P.12.A.107	CSK	pipe	leak				U	144
Millstone 2	Nov-79	P.12.A.120	WST	pipe	leak	TGSOC			U	145
Millstone 2	Jan-81	P.6.C.1234	SI	pipe	leak	fatigue			U	146
3-Mile Is 2	Feb-80	P.6.A.410	CVCS-MU	pipe	loose				U	147
S Onondaga 1	Aug-81	P.6.A.546	CVCS-CH	pipe	loose				U	148
S Onondaga 1	Aug-81	P.6.A.546	CVCS-CH	pipe	loose				U	149

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	ent
Indian Pt 2	Feb 79	P. 8. A. 203	PCS	pipe	p hole				U	160
Indian Pt 2	Feb 79	P. 8. A. 203	PCS	pipe	p hole				U	151
Indian Pt 2	May 79	P. 8. A. 203	PCS	pipe	p hole	corrosion			U	162
Indian Pt 2	June 79	P. 8. A. 203	PCS	pipe	p hole		1 spot		U	163
Indian Pt 2	Oct 81	P. 8. A. 203	PCS/CH	pipe	p hole	bad weld			U	164
Indian Pt 2	Jan 84	P. 8. C. 424	SS	pipe	p hole	corrosion			U	165
Indian Pt 2	Jan 85	P. 8. E. 435	AW	pipe	p hole	crack			U	166
Indian Pt 2	Jan 85	P. 8. E. 435	AW	pipe	p hole				U	167
Indian Pt 2	Jan 85	P. 8. E. 435	AW	pipe	p hole				U	168
Indian Pt 2	Mar 77	P. 8. A. 16	PCS/CH	pipe	p hole	erosion			U	169
Indian Pt 2	Mar 77	P. 8. E. 435	PCS/CH	pipe	p hole	erosion			U	170
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	171
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	172
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	173
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	174
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	175
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	176
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	177
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	178
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	179
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	180
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	181
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	182
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	183
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	184
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	185
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	186
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	187
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	188
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	189
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	190
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	191
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	192
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	193
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	194
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	195
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	196
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	197
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	198
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	199
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	200
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	201
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	202
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	203
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	204
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	205
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	206
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	207
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	208
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	209
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	210
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	211
Indian Pt 2	Mar 81	P. 8. E. 435	SS	pipe	p hole	corrosion			U	212

(U) (S) (C) (U) (S) (C)

00000000

Plant Name	Date	Age Reference	System	Component	Failure Mode	Failure Cause	Leakage	Pipe/Com Size (diam)	Classification	
									Size	cm
2	2000	0.00000001	SSS	pipe	pipe	erosion			U	173
2	2000	0.00000001	SSS	pipe	pipe				U	174
2	2000	0.00000002	SS	pipe	pipe	corrosion			U	175
2	2000	0.00000004	SSS	pipe	pipe	corrosion			U	176
2	2000	0.00000006	SSS	pipe	pipe	corrosion			U	177
2	2000	0.00000009	SSS	pipe	pipe	erosion			U	178
2	2000	0.00000006	SSS	pipe	pipe				U	179
2	2000	0.00000007	SSS	pipe	pipe		break		U	181
2	2000	0.00000010	SSS	pipe	pipe				U	182
2	2000	0.00000011	SSS	pipe	pipe				U	183
2	2000	0.00000012	SSS	pipe	pipe				U	184
2	2000	0.00000013	SSS	pipe	pipe				U	185
2	2000	0.00000014	SSS	pipe	pipe				U	186
2	2000	0.00000015	SSS	pipe	pipe				U	187
2	2000	0.00000016	SSS	pipe	pipe				U	188
2	2000	0.00000017	SSS	pipe	pipe				U	189
2	2000	0.00000018	SSS	pipe	pipe				U	190
2	2000	0.00000019	SSS	pipe	pipe				U	191
2	2000	0.00000020	SSS	pipe	pipe				U	192
2	2000	0.00000021	SSS	pipe	pipe				U	193
2	2000	0.00000022	SSS	pipe	pipe				U	194
2	2000	0.00000023	SSS	pipe	pipe				U	195
2	2000	0.00000024	SSS	pipe	pipe				U	196
2	2000	0.00000025	SSS	pipe	pipe				U	197
2	2000	0.00000026	SSS	pipe	pipe				U	198
2	2000	0.00000027	SSS	pipe	pipe				U	199
2	2000	0.00000028	SSS	pipe	pipe				U	200
2	2000	0.00000029	SSS	pipe	pipe				U	201
2	2000	0.00000030	SSS	pipe	pipe				U	202
2	2000	0.00000031	SSS	pipe	pipe				U	203
2	2000	0.00000032	SSS	pipe	pipe				U	204
2	2000	0.00000033	SSS	pipe	pipe				U	205
2	2000	0.00000034	SSS	pipe	pipe				U	206
2	2000	0.00000035	SSS	pipe	pipe				U	207
2	2000	0.00000036	SSS	pipe	pipe				U	208
2	2000	0.00000037	SSS	pipe	pipe				U	209
2	2000	0.00000038	SSS	pipe	pipe				U	210
2	2000	0.00000039	SSS	pipe	pipe				U	211
2	2000	0.00000040	SSS	pipe	pipe				U	212
2	2000	0.00000041	SSS	pipe	pipe				U	213
2	2000	0.00000042	SSS	pipe	pipe				U	214
2	2000	0.00000043	SSS	pipe	pipe				U	215
2	2000	0.00000044	SSS	pipe	pipe				U	216
2	2000	0.00000045	SSS	pipe	pipe				U	217
2	2000	0.00000046	SSS	pipe	pipe				U	218
2	2000	0.00000047	SSS	pipe	pipe				U	219
2	2000	0.00000048	SSS	pipe	pipe				U	220

Table A-2. (continued)

Plant Name ^a	Date	Ref ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Con Size (diam)	Classification ^a	
									size	cat
Advantage 1	Oct-71	P.5.B.3	POS	pipe	crack		4 gpm	1 1/2"	S	10
Advantage 1	Oct-71	P.5.B.8	POS	pipe	crack		2.5 gpm	1 1/2"	S	11
Advantage 1	Jan-76	P.5.B.9	POS	pipe	crack	stress	0.1 gpm	1"	S	12
Advantage 1	Jan-77	P.5.B.13	POS	pipe	crack	fatigue	<1 gpm	1"	S	13
Beaver V 1	Feb-81	P.5.B.14	POS	pipe	crack	corrosion	2.7 gpm	1"	S	14
Cal Cliffs 1	Aug-85	P.5.B.29	POS	pipe	crack	vibration	<tech sp	1"	S	15
Cal Cliffs 2	Aug-81	P.5.B.33	POS	pipe	crack	vibration		3/4"	S	16
Cal Cliffs 3	Aug-81	P.5.B.33	POS	pipe	crack	vibration		3/4"	S	17
Cal Cliffs 1	Jun-83	P.5.B.35	POS	pipe	crack		1.2 gpm	<3"	S	18
Cal Cliffs 2	Feb-83	P.5.B.36	POS	pipe	crack	fatigue		<3"	S	19
Cal Cliffs 3	Feb-83	P.5.B.36	POS	pipe	crack	corrosion		<3"	S	20
Cal Cliffs 4	Oct-83	P.5.B.33	SS	pipe	crack	anhydron		1"	S	21
Cal Cliffs 5	Oct-83	P.5.B.33	SS	pipe	crack	bad weld		1"	S	22
Cal Cliffs 6	Oct-83	P.5.B.33	SS	pipe	crack	bt press		1"	S	23
China 1	Jun-83	P.5.E.67	PZB	pipe	crack	th fatigue	0.0003 gpm	3/8"	S	24
Beaver V 1	Nov-83	P.5.E.63	POS	pipe	crack	stress		<3"	S	25
Coconino 2	May-74	P.7.A.49	POS	pipe	crack	vibration	weep	3/4"	S	26
Turkey Pt 4	Oct-74	P.7.A.76	POS	pipe	crack	install er		3/4"	S	27
Beaver V 1	Jun-75	P.7.A.92	SI	pipe	crack	vibration		3/4"	S	28
St. Lucie	Sept-75	P.7.A.125	SI	pipe	crack	vibration		1"	S	29
St. Lucie	May-77	P.7.A.142	SI	pipe	crack	bad weld		1"	S	30
Cal Cliffs 2	May-77	P.7.A.167	SI-LPSI	pipe	crack			1/2"	S	31
Advantage 1	Aug-79	P.7.A.192	SI-LPSI	pipe	crack	fatigue		1"	S	32

Table A-2. (continued)

Plant Name	Date	NDE Reference ^b	System ^a	Component	Failure Mode	Failure Cause	Leakage	Pipe/Con Size (diam)	Classification	
									size	cnt
Valve 1	May-90	2.7.A.037	SI	pipe	crack			2"	S	88
Valve 2	Jul-90	2.7.A.038	SI	pipe	crack	fatigue		1"	S	89
Valve 3	Jul-90	2.7.A.039	SI	pipe	crack	stress		2 1/2"	S	90
Valve 4	Aug-90	2.7.A.040	SI-HCI	pipe	crack			3/4"	S	91
Valve 5	May-90	2.7.A.041	SI-HCI	pipe	crack	vibration	0.25 gpm	1"	S	92
Valve 6	Feb-90	2.7.E.064	FWT	pipe	crack	freeze		1 1/2"	S	93
Valve 7	Jan-74	2.8.A.044	CVCS-CH	pipe	crack	vibration	spray	3/8"	S	94
Valve 8	Jan-74	2.8.A.044	CVCS-CH	pipe	crack	vibration	spray	3/8"	S	95
Valve 9	Jul-74	2.8.A.055	CVCS-CH	pipe	crack	fatigue		3/4"	S	96
Valve 10	Jul-74	2.8.A.056	CVCS-CH	pipe	crack	fatigue		3/4"	S	97
Valve 11	Aug-74	2.8.A.058	CVCS-CH	pipe	crack	fatigue		3/4"	S	98
Valve 12	Jan-75	2.8.A.063	CVCS-CH	pipe	crack	vibration		3/4"	S	99
Valve 13	Nov-75	2.8.A.064	CVCS-CH	pipe	crack	vibration	10 gpm	3/4"	S	100
Valve 14	Oct-74	2.8.A.064	CVCS-CH	pipe	crack	vibration	1 gpm	3/4"	S	101
Valve 15	Dec-74	2.8.A.064	CVCS-CH	pipe	crack	vibration	1 gpm	3/4"	S	102
Valve 16	Nov-74	2.8.A.064	CVCS-CH	pipe	crack	vibration	0.001 gpm	3/4"	S	103
Valve 17	Feb-76	2.8.A.070	CVCS-CH	pipe	crack			<3"	S	104
Valve 18	Oct-76	2.8.A.078	CVCS-CH	pipe	crack	vibration	0.5 gpm	3/4"	S	105
Valve 19	Oct-76	2.8.A.081	CVCS	pipe	crack	fatigue		3/4"	S	106
Valve 20	Dec-74	2.8.A.081	CVCS-CH	pipe	crack	fatigue		3/4"	S	107
Valve 21	Apr-76	2.8.A.081	CVCS-CH	pipe	crack	fatigue	0.5 gpm	3/4"	S	108
Valve 22	Feb-76	2.8.A.100	CVCS-CH	pipe	crack	vibration		2 1/2"	S	109
Valve 23	Jul-76	2.8.A.156	CVCS-MU	pipe	crack			3/4"	S	110

Table A-2. (continued)

Plant Area ^a	Date	API Reference ^b	System ^a	Component	Failure Mode	Failure Cause ^a	Leakage	Pipe/Conn. Size (diam)	Classification ^c	
									size	cnt
Process 1	06-03-83	P. 0.4.157	CVCS-WO	pipe	crack	vibration		3/4"	S	56
Process 2	06-03-83	P. 0.4.159	CVCS-CH	pipe	crack	fatigue		3/4"	S	57
Process 3	06-03-83	P. 0.4.164	CVCS-CH	pipe	crack	fatigue		3/4"	S	58
Process 4	06-03-83	P. 0.4.177	CVCS-CH	pipe	crack	vibration		3/4"	S	59
Process 5	06-03-83	P. 0.4.200	CVCS-CH	pipe	crack	fatigue		1"	S	60
Process 6	06-03-83	P. 0.4.212	PCS	pipe	crack			2"	S	61
Process 7	06-03-83	P. 0.4.265	PCS	pipe	crack	corrosion		1"	S	62
Process 8	06-03-83	P. 0.4.264	CVCS-CH	pipe	crack	vibration		2"	S	63
Process 9	06-03-83	P. 0.4.274	CVCS-CH	pipe	crack	vibration		3/4"	S	64
Process 10	06-03-83	P. 0.4.200	CVCS-WO	pipe	crack		0.2 gpm	1"	S	65
Process 11	06-03-83	P. 0.4.200	CVCS-WO	pipe	crack			1"	S	66
Process 12	06-03-83	P. 0.4.200	CVCS-WO	pipe	crack	vibration		1"	S	67
Process 13	06-03-83	P. 0.4.225	CVCS-WO	pipe	crack	vibration		1 1/2"	S	68
Process 14	06-03-83	P. 0.4.164	CVCS-CH	pipe	crack	vibration		<3"	S	69
Process 15	06-03-83	P. 0.4.194	CVCS-CH	pipe	crack	vibration		<3"	S	70
Process 16	06-03-83	P. 0.4.194	CVCS-CH	pipe	crack	vibration		<3"	S	71
Process 17	06-03-83	P. 0.4.236	CVCS-CH	pipe	crack	vibration		1/2"	S	72
Process 18	06-03-83	P. 0.4.237	CVCS-CH	pipe	crack			3/4"	S	73
Process 19	06-03-83	P. 0.4.247	CVCS-CH	pipe	crack	vibration		3/4"	S	74
Process 20	06-03-83	P. 0.4.236	PCS	pipe	crack	PSOC		2"	S	75
Process 21	06-03-83	P. 0.4.176	CVCS-CH	pipe	crack	fatigue	15 gpm	3/4"	S	76
Process 22	06-03-83	P. 0.4.176	CVCS	pipe	crack	fatigue		3/4"	S	77
Process 23	06-03-83	P. 0.4.176	PCS	pipe	crack			3/4"	S	78

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Indian Pt 2	Oct-73	P.8.B.15	RHR	pipe	crack	vibration		3/4"	S	79
Indian Pt 2	Jan-74	P.8.B.94	RHR	pipe	crack			3/4"	S	80
Indian Pt 3	Jan-76	P.8.B.144	RHR	pipe	crack	fatigue		3/4"	S	81
Trotan	Jun-85	P.8.B.652	CSS	pipe	crack	fatigue		3/4"	S	82
S. Orefre 3	Mar-86	P.5.E.113	PCS	pipe	crack	IGCSS		3/4"	S	83
Palo Verde	Mar-87	P.5.F.66	PCS	pipe	crack	fatigue	0.5 gpm	<3"	S	84
F. Calhoun	Oct-76	P.5.A.61	PCS	pipe	crack	vibration	0.2 gpm	<3"	S	85
F. Calhoun	Feb-79	P.5.A.75	PCS	pipe	crack	vibration	0.2 gpm	<3"	S	86
Salem 1	Jan-77	P.9.B.268	PCS	pipe	failed			3/8"	S	87
Arkansas 1	Jan-82	P.5.A.110	PCS	pipe	leak	loose blt	1.4 gpm	<3"	S	88
Cal Cliffe 2	Jul-86	P.5.A.146	PCS	pipe	leak	loose fit	>1 gpm	<1"	S	89
Catawba	Jan-87	P.5.E.116	PCS	pipe	leak	installer	6 gpm	1/2"	S	90
Callaway	Apr-87	P.5.E.118	PRZR	pipe	leak	loose		<3"	S	91
Catawba	Oct-85	P.5.F.49	PCS	pipe	leak	vibration	0.6 gpm	1/2"	S	92
Arkansas 2	Nov-82	P.6.E.423	AFW	pipe	leak			<3"	S	93
Turkey Pt 3	Apr-86	P.6.F.110	SSWS	pipe	leak	corrosion		<3"	S	94
Turkey Pt 4	Apr-85	P.7.D.90	PRZR	pipe	leak			<3"	S	95
Salem 1	Sec-81	P.7.E.110	FWTR	pipe	leak	vibration		1"	S	96
Ginna	Jul-74	P.8.A.56	CVCS-CH	pipe	leak	IGSCC		3/4"	S	97
CT Yankee	Dec-83	P.8.B.867	SSWS	pipe	leak	corrosion		3/4"	S	98
Oconee 2	Sep-81	P.9.B.615	PCS	pipe	leak			<3"	S	99
McGuire 1	Jun-82	P.9.B.715	PCS	pipe	leak	loose		<3"	S	100
McGuire 2	Oct-83	P.9.B.1135	PRZR	pipe	leak	loose		<3"	S	101

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
McGuire 2	Oct-83	P.9.B.1113	PRR	pipe	leak	loose		<3"	S	102
McGuire 2	Oct-83	P.9.B.1113	PRR	pipe	leak	loose		<3"	S	103
Trojan	Mar-77	P.9.A.215	SFP	pipe	leak	crack		2"	S	104
Arkansas 1	Aug-76	P.8.B.98	SSVS	pipe	leak	crack		1 1/2"	S	105
Gienna 1	Oct-76	P.8.B.99	RPR	pipe	leak	installer		3/4"	S	105
Arkansas 1	Dec-79	P.8.B.103	SFCS	pipe	leak	ISCC		2"	S	107
Arkansas 1	Dec-76	P.8.B.108	SFCS	pipe	leak	ISCC		1 1/2"	S	108
Palladas	Feb-77	P.11.A.176	CS	pipe	leak			1/4"	S	109
Wittstone 2	Nov-79	P.12.A.61	NST	pipe	leak	corrosion		1 1/2"	S	110
Salon 2	Jul-81	P.9.B.585	AFW	pipe	loose			<3"	S	111
Salon 2	Jul-81	P.9.B.586	AFW	pipe	loose			<3"	S	112
Arkansas 1	Jan-75	P.8.A.117	CVCS	pipe	oper			1/2"	S	113
George 3	Dec-74	P.5.A.39	PCS	pipe	p hole			1 1/2"	S	114
Arkansas 1	Jan-77	P.5.A.54	PCS	pipe	p hole		0.5 gpm	<3"	S	115
3-Mile Is 1	Jul-75	P.8.A.81	CVCS	pipe	p hole	fatigue		3/4"	S	116
Arkansas 1	Jul-75	P.8.A.90	CVCS	pipe	p hole	pitting		3/4"	S	117
Gienna	Nov-75	P.8.A.111	CVCS-CH	pipe	p hole	bad weld		3/4"	S	118
Gienna	Dec-75	P.8.A.111	CVCS-CH	pipe	p hole	bad weld		1/2"	S	119
Arkansas 1	Dec-76	P.8.A.156	CVCS-WU	pipe	p hole	pitting		3/4"	S	120
Sunny 1	Apr-75	P.8.A.160	CVCS-CH	pipe	p hole	erosion		2"	S	121
Gienna	Dec-77	P.8.A.294	CVCS-CH	pipe	p hole	fatigue		3/4"	S	122
Rancho S	Jul-86	P.8.B.723	DNR	pipe	p hole	erosion	< 1 gpm	1"	S	123
Rancho S	Dec-86	P.8.B.766	DNR	pipe	p hole	erosion		1"	S	124

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Indian Pt 2	Aug-81	P.8.B.431	SSWS	pipe	p hole	erosion		2"	S	125
Beaver V 1	Jun-78	P.5.B.10	POS	pipe	leak	stress	<15 gpm	1/2"	S	125
Salem 1	Jan-77	P.8.A.176	CURS-LO	pipe	rupture	vibration	2400 gal	3/4"	S	1
CT Yankee	Mar-85	P.6.E.556	AFW	pipe	rupture	erosion		2 1/4"	S	2
S Onofre	Jun-84	P.7.E.210	FWTR	pipe	break	fatigue		>3"	L	1
V Yankee	Jan-82	P.6.D.262	SG	pipe	crack	erosion		12"	L	2
Zion 1	Feb-82	P.6.D.262	SG	pipe	crack	erosion		24"	L	3
Cock 1	Mar-77	P.6.E.110	SG	pipe	crack	WH	mist	>3"	L	4
St. Lucie 1	Jul-75	P.6.F.26	SSWS	pipe	crack	stress		3"	L	5
Indian Pt 3	Sep-78	P.7.A.125	BAS	pipe	crack	corrosion		6"	L	6
Arkansas 1	Jan-80	P.7.B.76	CSS	pipe	crack	IGSCC		10"	L	7
Arkansas 1	Jan-80	P.7.B.76	CSS	pipe	crack	IGSCC		10"	L	8
Arkansas 1	Jan-80	P.7.B.76	CSS	pipe	crack	IGSCC		10"	L	9
3-Mile Is 1	Nov-76	P.8.B.113	SSWS	pipe	crack	instaler		30"	L	10
3-Mile Is 1	Nov-76	P.8.B.113	SSWS	pipe	crack	instaler		20"	L	11
Salem 1	Jan-82	P.8.B.458	SSWS	pipe	leak	corrosion		6"	L	12
Cock 1	Jan-82	P.8.B.464	SSWS	pipe	leak	erosion		>3"	L	13
Diablo Can 1	Mar-77	P.6.E.211	AFW	pipe	leak	crack		16"	L	14
Arkansas 1	Mar-73	P.7.B.6	CSS	pipe	leak	IGSCC		8"	L	15
Yankee 3	Feb-79	P.7.E.49	FWTR	pipe	leak			8"	L	16
S Onofre 1	Oct-78	P.8.A.323	SI	pipe	leak	IGSCC		3"	L	17

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
S. Onofre 1	Oct-78	P.8.A.320	SI	pipe	leak	TSSOC		3"	L	18
Millstone 2	Oct-79	P.8.A.336	WST	pipe	leak	crack		3"	L	19
Millstone 2	Aug-75	P.8.B.53	SSWS	pipe	leak	corrosion		6"	L	20
Arkansas 1	Aug-76	P.8.B.96	SSWS	pipe	leak	crack	2 qom	10"	L	21
Salem 1	Aug-78	P.8.B.197	CFDU	pipe	leak	corrosion		10"	L	22
Cal Cluff 1	Aug-82	P.10.A.90	RWST	pipe	leak			4"	L	23
Ginna	Dec-73	P.8.A.56	CVCS-CH	pipe	p hole			3"	L	24
Ginna 1	Jan-82	P.8.A.553	PCS	pipe	p hole			6"	L	25
N Anna 1	Dec-81	P.8.B.449	SSWS	pipe	p hole	corrosion		3"	L	26
Beaver V 1	Oct-81	P.7.E.145	FWTR	pipe	rupture	corrosion		12"	L	1
Trojan	Mar-85	P.6.E.559	TBN	pipe	rupture	erosion		14"	L	2
Arkansas 2	Apr-89	P.6.E.923	TBN	pipe	rupture	erosion		14"	L	3
Arkansas 1	May-76	P.7.E.24	FWTR	pump	clog	crack			U	1
Pt Beech 2	Aug-76	P.8.A.144	CVCS-CH	pump	crack	corrosion			U	2
F Cathoun	Apr-78	P.8.A.290	CVCS-CH	pump	crack	vibration		-	U	3
F Cathoun	Dec-78	P.8.A.333	CVCS-CH	pump	crack	vibration			U	4
F Cathoun	Dec-78	P.8.A.333	CVCS-CH	pump	crack	vibration			U	5
Kewaunee	Aug-81	P.8.A.550	BAS	pump	crack	corrosion			U	6
Ticon 1	Sep-82	P.7.B.129	SI-LPSI	pump	crack	corrosion			U	7
Indian Pt 2	May-75	P.8.B.61	RHR	pump	leak				U	8
F Cathoun	Mar-76	P.8.B.80	SSWS	pump	leak	corrosion			U	9

Table A-2. (continued)

Plant Name ²	Date	NFE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Robinson 2	Apr-75	P.5.A.40	PCS	pump	leak		>6 gpm		U	10
V Anna 1	Dec-80	P.5.A.95	PCS	pump	leak		13 gpm		U	11
Willstone 2	Jun-79	P.6.E.220	AFW	pump	leak	packing			U	12
S-Mite Is 1	Apr-77	P.6.F.52		pump	leak				U	13
Indian Pt 1	Feb-72	P.8.A.25	CVCS-WU	pump	leak				U	14
Prattville 1	Jan-75	P.8.A.206	BAS	pump	leak				U	15
Beaver V 1	Dec-76	P.8.A.254	CVCS-CH	pump	leak	erosion			U	16
Surry 1	Nov-79	P.8.A.394	BAS	pump	leak				U	17
Surry 1	Dec-79	P.8.A.394	BAS	pump	leak				U	18
Turkey Pt 3	Dec-80	P.8.A.493	BAS	pump	leak				U	19
Salem 1	Jun-82	P.8.A.533	CVCS-CH	pump	leak	corrosion			U	20
Turkey Pt 4	May-78	P.8.B.193	SFCS	pump	leak		50 gal		U	21
Oconee 1-3	Mar-79	P.8.B.244	HPSW	pump	leak				U	22
Oconee 2	Jun-79	P.8.B.263	HPSW	pump	leak	erosion			U	23
Oconee 2	Jul-79	P.8.B.258	HPSW	pump	leak	erosion			U	24
Oconee 2	Dec-79	P.8.B.267	HPSW	pump	leak	erosion			U	25
Oconee 1-3	Feb-80	P.8.B.320	HPSW	pump	leak	erosion			U	26
Oconee 1-3	Jun-80	P.8.B.320	HPSW	pump	leak	erosion			U	27
Oconee 1-3	Jun-80	P.8.B.320	HPSW	pump	leak	erosion			U	28
Oconee 1	Jul-80	P.8.B.324	HPSW	pump	leak	erosion			U	29
Oconee 1	Aug-80	P.8.B.328	SSWS	pump	leak	erosion			U	30
Salem 2	Sep-82	P.8.B.505	SSWS	pump	leak	erosion			U	31
Turkey Pt 4	Aug-89	P.10.A.127	SFP	pump	leak	installer	64 gpm		U	32

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^c	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Secaucus 1	Mar-83	P.12.A.136	AUX	pump	leak	hi pH			U	33
Bruck 1	Jan-86	P.12.A.151		pump	leak				U	34
Georgetown 1-3	Sep-79	P.8.B.270	HPSW	pump	p hole	erosion			U	35
F. Calhoun	May-80	P.5.E.34	PCS	pump					U	36
N. Anna 1	Sep-85	P.5.E.47	PCS	pump	leak		15.5 gpm	1 1/2"	S	1
Pt Beach 2	Jul-70	P.3.8	ORDW	pump	p hole		0.22 gpm	<3"	S	2
Arkansas 2	Dec-80	P.8.A.530	CVCS-CH	pump	crack	vibration		4"	L	1
Gina	Oct-76	P.7.A.134	SI	pump	crack	corrosion		8"	L	2
Arkansas 2	Apr-87	P.5.E.119	PCS	tank	leak	corrosion	60 dpm		U	1
Rancho S	Nov-86	P.10.A.111	SFP	tank	leak				U	2
Millsboro 2	Apr-76	P.12.A.44	VST	tank	leak	corrosion			U	3
Cal Cliff 1	May-77	P.15.A.91	VST	tank	leak	corrosion	5 gpm		U	4
Cal Cliff 1	Jul-77	P.15.A.97	VST	tank	leak	corrosion	1 gpm		U	5
Millsboro 2	Nov-77	P.12.A.85	VST	tank	rupture	hi press			U	1
Zion 1	Mar-81	P.7.A.300	BAS	tank	leak	ISSCC		1/8"	S	1
Yerkee R	Aug-75	P.8.A.120	CVCS-CH	valve	crack	vibration			U	1
Indian Pt 3	Apr-76	P.8.A.125	CVCS-CH	valve	crack	vibration			U	2

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Yankee R	May-76	P.8.A.130	CVCS-CH	valve	crack	bad weld	100 gal		U	3
Millstone 2	Dec-76	P.8.A.175	CVCS-CH	valve	crack	vibration			U	4
Indian Pt 2	Feb-77	P.8.A.186	PCS	valve	crack	vibration			U	5
Indian Pt 2	Mar-77	P.8.A.204	CVCS-CH	valve	crack	vibration			U	5
Yankee R	Feb-77	P.8.A.209	CVCS-CH	valve	crack	fatigue			U	7
Cal Cliffs 1	Nov-76	P.8.A.238	CVCS-CH	valve	crack	fatigue			U	8
Indian Pt 3	Sep-76	P.8.A.243	CVCS-CH	valve	crack	vibration			U	9
Indian Pt 3	Jan-78	P.8.A.259	CVCS	valve	crack	fatigue			U	10
F Calhoun	Jan-78	P.8.A.259	CVCS-CH	valve	crack	vibration			U	11
F Calhoun	Feb-78	P.8.A.259	CVCS-CH	valve	crack	vibration			U	12
Cal Cliffs 2	Jul-78	P.8.A.290	CVCS	valve	crack	fatigue			U	13
Cal Cliffs 1	Mar-79	P.8.A.344	CVCS	valve	crack	fatigue	1.8 gpm		U	14
Crystal R 3	Jul-79	P.8.A.364	CVCS-MU	valve	crack	vibration			U	15
Crystal R 3	Oct-79	P.8.A.388	CVCS-MU	valve	crack	vibration			U	16
Cal Cliffs 2	Feb-80	P.8.A.417	CVCS-CH	valve	crack	vibration			U	17
Cal Cliffs 2	Apr-80	P.8.A.429	CVCS-CH	valve	crack	vibration			U	18
Yankee R	Jul-80	P.8.A.441	CSS	valve	crack	corrosion			U	19
Yankee R	Jul-80	P.8.A.441	CSS	valve	crack	corrosion			U	20
Indian Pt 3	Jul-80	P.8.A.445	CVCS	valve	crack	fatigue			U	21
Kewaunee	Dec-81	P.8.A.576	CVCS-CH	valve	crack	vibration			U	22
Crystal R 3	May-82	P.8.A.631	CVCS-MU	valve	crack	vibration			U	23
Crystal R 3	May-82	P.8.A.631	CVCS-MU	valve	crack	vibration			U	24
Cook 1	Mar-77	P.8.E.119	AFV	valve	crack				U	25

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Salem 1	Feb-80	P.7.A.248	BS	valve	drip				U	25
Arkansas 2	Sep-87	P.11.B.1022	TSV	valve	failure	installer			U	27
S. Orefine 1	Aug-85	P.10.A.147		valve	flood				U	28
Farley 1	Mar-83	P.8.C.35	PCS	valve	leak	loose	1.75 gpm		U	29
Palo Verde 1	Apr-87	P.9.B.1138	SFCS	valve	leak	fatigue	0.5 gpm		U	30
Farley Pt 4	Aug-83	P.4.B.97	PCS	valve	leak				U	31
Bygon 1	Jul-88	P.5.C.102	PCS	valve	leak	packing	0.5 gpm		U	32
Farley Pt 4	Sep-88	P.5.C.458	SS	valve	leak				U	33
Watt Store 2	Jul-82	P.5.E.68	PCS	valve	leak		>1 gpm		U	34
Watt Store 2	Jul-82	P.5.E.68	PCS	valve	leak		>1 gpm		U	35
Trojan Pt 3	Sep-78	P.5.F.26	PCS	valve	leak	packing	2.4 gpm		U	36
Trojan Pt 3	Sep-78	P.5.F.26	PCS	valve	leak	packing	2.4 gpm		U	37
OT Yankee	Nov-72	P.6.A.16		valve	leak				U	38
Pt Beach 1	Jan-70	P.6.D.18	SS	valve	leak	corrosion			U	39
Trojan	Sep-77	P.6.E.134	AFM	valve	leak				U	40
Oroore 1-3	Dec-78	P.6.E.120	SS	valve	leak				U	41
Oroore 1-3	Dec-78	P.6.E.120	PCS	valve	leak				U	42
Oroore 2	Oct-80	P.6.E.301	PCRV	valve	leak				U	43
Oroore 1	Dec-81	P.6.E.397	AFM	valve	leak				U	44
Crystal 1-3	Mar-83	P.6.E.444	AFM	valve	leak				U	45
Crystal 1-3	Mar-83	P.6.E.444	AFM	valve	leak				U	46
Cock 1	Apr-84	P.6.E.450	AFM	valve	leak	erosion			U	47
Module 2	Aug-84	P.6.E.521	AFM	valve	leak				U	48

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Palo Verde 2	Nov-88	P.6.E.911	PCS	valve	leak	erosion			U	49
Watts Store 3	Apr-88	P.6.F.103	SSWS	valve	leak				U	50
Prairie 1 1	Jun-74	P.7.A.51	BAS	valve	leak				U	51
Ition 1	Nov-74	P.7.A.72	BAS	valve	leak				U	52
Kewaunee	Mar-91	P.7.A.209	SI	valve	leak	corrosion			U	53
Arkansas 2	Jun-80	P.7.A.622	SI	valve	leak	IGSCC			U	54
Sunny 2	May-73	P.7.B.74	CSS	valve	leak		5 gal		U	55
OT Yankee	Mar-74	P.7.C.3	CSS	valve	leak	obstruction			U	56
Kewaunee	Jun-75	P.8.A.79	SSWS	valve	leak				U	57
Kewaunee	Jun-75	P.8.A.79	SSWS	valve	leak				U	58
Kewaunee	Jun-75	P.8.A.79	SSWS	valve	leak				U	59
Occochee 1	Aug-79	P.8.A.381	PCS	valve	leak				U	60
Ition 1	Nov-82	P.8.A.690	BAS	valve	leak	corrosion			U	61
Cock 2	Oct-88	P.8.A.713	CVCS-ID	valve	leak				U	62
Pallisades	Jul-74	P.8.B.31	SSWS	valve	leak	erosion			U	63
Salem 1	Sep-81	P.8.B.492	SSWS	valve	leak				U	64
S. Shore 2	Aug-87	P.8.B.804	DHR	valve	leak		100 gpm		U	65
W. Shore 1	Nov-89	P.8.B.1135	PRR	valve	leak	loose			U	66
Callaway	Aug-88	P.9.C.352	PCS	valve	leak		2.7 gpm		U	67
Sequoyah 1	Oct-82	P.9.D.247	APW	valve	leak	installer			U	68
McGuire 1	Apr-88	P.9.D.550	SSWS	valve	leak	packing			U	69
McGuire 1	Jul-88	P.9.E.839	FWR	valve	leak				U	70
Robinson 2	Nov-89	P.9.D.1181	PCS	valve	leak		22 gpm		U	71

Table A-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^c	Component	Failure Mode ^d	Failure Cause	Leakage	Pipe/Comp Size (diam)	Classification ^e	
									size	cnt
Valley 1	Feb-81	P.7.B.100	SSS	valve	leak				U	72
Valley 2	Oct-81	P.7.C.110	SSS	valve	leak		1.0 gpm		U	73
Conoco 1	Apr-79	P.5.B.200	SSS	valve	leak		1 gpm		U	74
Beaver V 1	Feb-81	P.5.F.300	PCS	valve	leak		2.0 gpm		U	75
Conoco 2	Oct-75	P.5.F.40	PCS	valve	leak				U	76
Conoco 3	Oct-75	P.5.F.40	PCS	valve	leak				U	77
Beaver V	Oct-87	P.5.F.64	PCS	valve	leak		1.5 gpm		U	78
Beaver V	Oct-87	P.5.F.64	PCS	valve	leak		1.5 gpm		U	79
Beaver V	Oct-87	P.5.F.64	PCS	valve	leak		1.5 gpm		U	80
Cal. Beach 1	Jun-77	P.9.G.6	PCS	valve	leak	stress	8 gpm	3/8"	U	81
Cal. Clive 1	Jul-79	P.8.A.369	CVCSCCH	valve	p hole	vibration			U	82
Cal. Valley	Oct-82	P.8.A.643	CVCSCCH	valve	p hole				U	83
Sony 2	Jun-88	P.8.B.715	SSS	valve	p hole	corrosion	1 gpm		U	84
Tulley 24 1	Jul-83	P.5.E.109	PRR	valve	p hole				U	85
Cock 2	Apr-79	P.8.F.209	APW	valve	p hole				U	86
Valley R	Jul-83	P.5.D.94	PCS	valve	crack	bad weld		1"	S	1
Zion	Jun-73	P.8.A.34	CVCSCCH	valve	crack	vibration	200 gal	3/2"	S	2
Millstone 2	Jan-76	P.8.A.189	CVCSCCH	valve	crack	fatigue		3/2"	S	3
Cal. Clive 1	Jul-79	P.8.A.239	CVCSCCH	valve	crack	fatigue		3/2"	S	4
Cal. Clive 1	Nov-73	P.8.A.239	CVCSCCH	valve	crack	fatigue		3/2"	S	5
Cal. Clive 1	Sep-77	P.8.A.239	CVCSCCH	valve	crack	fatigue		3/2"	S	6
Cal. Clive 1	Jul-79	P.8.A.374	CVCSCCH	valve	crack	vibration		2"	S	7

Table A-2. (continued)

Part Name ^a	Date	NDE Reference ^b	System ^c	Component	Failure Mode ^d	Failure Cause ^e	Leakage	Pipe/Com Size (diam)	Classification	
									size	cnt
Cal. Core 2	Mar-80	P.B.A.403	CVCS-CH	valve	crack	vibration		3/4"	S	8
Cal. Core 3	Apr-83	P.B.A.465	CVCS-CH	valve	crack	vibration		3/4"	S	9
Cal. Core 4	Jun-86	P.B.A.465	CVCS-CH	valve	crack	vibration		3/4"	S	10
Core 1	Dec-82	P.B.A.466	PAS	valve	crack	bad weld		2"	S	11
Core 2	Oct-83	P.B.A.473	CVCS-CH	valve	crack	fatigue		1"	S	12
Core 3	Dec-82	P.B.A.466	PAS	valve	crack	fatigue		1"	S	13
Core 4	Jan-83	P.B.A.466	TBY	valve	crack	TSSCC	1 gpm	2 1/2"	S	14
Core 1	Apr-79	P.B.E.47	POS	valve	leak	packing	2.5 gpm	2"	S	15
Core 1	Dec-86	P.B.E.47	POS	valve	leak		16.5 gpm	1 1/2"	S	16
Core 2	Apr-87	P.B.A.474	POS	valve	leak		1.8 gpm	1 1/2"	S	17
Core 1	Oct-85	P.B.E.49	POS	valve	leak			2"	S	18
Core 1	Oct-85	P.B.E.49	PRR	valve	leak			2"	S	19
Core 1	May-79	P.B.A.481	CVCS-CH	valve	p hole	erosion		2"	S	20
Core 1	Apr-89	P.B.A.486	PAS	valve	p hole	TSSCC		3/4"	S	21
Core 1	Dec-78	P.B.E.49	PRR	valve				3/4"	S	22
Core 1	Dec-80	P.B.A.494	CVCS-CH	valve	rupture			3/4"	S	23
Core 1	May-81	P.B.A.496	CVCS-CH	valve	rupture	hi press	100 gpm	3/4"	S	24
Core 1	Feb-89	P.B.E.494	PRR	valve	rupture	frost		1 1/2"	S	25
Core 1	Oct-79	P.B.A.496	CVCS-CH	valve	rupture	hi press	70 gpm	<3"	S	26
Core 1	May-79	P.B.E.496	PRR	valve	rupture			1 1/2"	S	27
Core 1	May-80	P.B.E.496	PRR	valve	leak	corrosion		8"	L	28

Table A-3. Summary of leakage and rupture events (9/60 - 6/90)

Component	BWR		PWR		Total BWR/PWR	
	leakage	rupture	leakage	rupture	leakage	rupture
Elbow						
Unknown	7	0	12	0	19	0
<3"	14	0	10	0	24	0
>=3"	9	0	9	2	18	2
Total	32	0	31	2	63	2
Flange						
Unknown	13	0	17	0	30	0
<3"	3	0	7	0	10	0
>=3"	2	0	5	1	7	1
Total	18	0	29	1	47	1
Flange (ht exchanger)						
Unknown	4	0	8	0	12	0
<3"	0	0	1	0	1	0
>=3"	1	0	7	0	8	0
Total	5	0	16	0	21	0
Flange (pump)						
Unknown	6	0	16	0	22	0
<3"	0	0	0	0	0	0
>=3"	0	0	7	0	7	0
Total	6	0	23	0	29	0

Table A-3. (continued)

Component	BWR		PWR		Total BWR/PWR	
	leakage	rupture	leakage	rupture	leakage	rupture
Flange (tank)						
Unknown	3	0	2	0	5	0
<3"	0	0	0	0	0	0
>=3"	0	0	3	0	3	0
Total	3	0	5	0	8	0
Flange (valve)						
Unknown	6	0	40	0	46	0
<3"	1	0	6	0	7	0
>=3"	2	0	6	0	8	0
Total	9	0	52	0	61	0
Flange (all flanges)						
Unknown	32	0	83	0	115	0
<3"	4	0	14	0	18	0
>=3"	5	0	28	1	33	1
Total	41	0	125	1	166	1
Heat Exchanger						
Unknown	10	0	6	0	16	0
Tube	5	0	53	2	58	2
Shell	1	0	1	0	2	0
Total	16	0	60	2	76	2

Table A-3. (continued)

Component	BWR		PWR		Total BWR/PWR	
	leakage	rupture	leakage	rupture	leakage	rupture
Pipe						
Unknown	38	0	183	1	221	1
<3"	66	6	126	2	192	8
>=3"	73	2	26	3	99	5
Total	177	8	335	6	512	14
Pump						
Unknown	7	0	36	0	43	0
<3"	0	2	2	0	2	2
>=3"	1	0	2	0	3	0
Total	8	2	40	0	48	2
Tank						
Unknown	4	1	5	1	9	2
<3"	0	0	1	0	1	0
>=3"	0	0	0	0	0	0
Total	4	1	6	1	10	2
Valve						
Unknown	35	0	86	0	121	0
<3"	12	1	22	5	34	6
>=3"	3	0	5	1	8	1
Total	50	1	113	6	163	7

Table A-4. Summary of leakage and rupture events (9/60 - 12/83)

Component	BWR		PWR		Total BWR/PWR	
	leakage	rupture	leakage	rupture	leakage	rupture
Elbow						
Unknown	6	0	10	0	16	0
<3"	16	0	7	0	23	0
>=3"	8	0	3	1	11	1
Total	30	0	20	1	50	1
Flange	BWR		PWR		Total BWR/PWR	
	leakage	rupture	leakage	rupture	leakage	rupture
Unknown	5	0	13	0	18	0
<3"	2	0	6	0	8	0
>=3"	1	0	3	1	4	1
Total	8	0	22	1	30	1
Flange (ht exchanger)	BWR		PWR		Total BWR/PWR	
	leakage	rupture	leakage	rupture	leakage	rupture
Unknown	4	0	6	0	10	0
<3"	0	0	0	0	0	0
>=3"	0	0	6	0	6	0
Total	4	0	12	0	16	0
Flange (pump)	BWR		PWR		Total BWR/PWR	
	leakage	rupture	leakage	rupture	leakage	rupture
Unknown	2	0	12	0	14	0
<3"	0	0	0	0	0	0
>=3"	0	0	7	0	7	0
Total	2	0	19	0	21	0

Table A-4. (continued)

Component	BWR		PWR		Total BWR/PWR	
	leakage	rupture	leakage	rupture	leakage	rupture
Flange (tank)						
Unknown	1	0	2	0	3	0
<3"	0	0	0	0	0	0
>=3"	0	0	2	0	2	0
Total	1	0	4	0	5	0
Flange (valve)						
Unknown	5	0	28	0	33	0
<3"	0	0	4	0	4	0
>=3"	2	0	5	0	7	0
Total	7	0	37	0	44	0
Flange (all flanges)						
Unknown	17	0	61	0	78	0
<3"	2	0	10	0	12	0
>=3"	3	0	23	1	26	1
Total	22	0	94	1	116	1
Heat Exchanger						
Unknown	10	0	5	0	15	0
Tube	3	0	50	2	53	2
Shell	1	0	1	0	2	0
Total	14	0	56	2	70	2

Table A-4. (continued)

Component	BWR		PWR		Total BWR/PWR	
Pipe	leakage	rupture	leakage	rupture	leakage	rupture
Unknown	28	0	148	1	177	1
<3"	55	6	104	1	159	7
>=3"	46	1	25	1	71	2
Total	129	7	277	3	406	10
Pump	BWR		PWR		Total BWR/PWR	
	leakage	rupture	leakage	rupture	leakage	rupture
Unknown	5	0	34	0	39	0
<3"	0	2	1	0	1	2
>=3"	1	0	2	0	3	0
Total	6	2	37	0	43	2
Tank	BWR		PWR		Total BWR/PWR	
	leakage	rupture	leakage	rupture	leakage	rupture
Unknown	4	0	3	1	7	1
<3"	0	0	1	0	1	0
>=3"	0	0	0	0	0	0
Total	4	0	4	1	8	1
Valve	BWR		PWR		Total BWR/PWR	
	leakage	rupture	leakage	rupture	leakage	rupture
Unknown	24	0	65	0	89	0
<3"	11	1	18	5	29	6
>=3"	3	0	3	1	6	1
Total	38	1	86	6	124	7

APPENDIX B
RUPTURE EVENTS

CONTENTS

Table B-1. Rupture Events for BWRs B-3

Table B-2. Rupture events for PWRs B-4

Table B-1. Rupture events for BWRs

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Comp Size (diam)	Classification ^a	
									size	event
O. Cities 2	Aug-75	B.6.E.145	APW	pipe	rupture	vibration	8500 gal	3/4"	S	1
O. Cities 2	Aug-75	B.6.E.145	APW	pipe	rupture	vibration		3/4"	S	2
Dresden 2	Jan-81	B.6.E.142	CDS	pipe	rupture	vibration		3/4"	S	3
Pilgrim	Sep-81	B.7.D.294	RHR	pipe	rupture	vibration		1"	S	4
Dresden 1	Apr-77	B.8.C.105	SFP	pipe	rupture	corrosion	2000 gal	<3"	S	5
Cooper	Dec-75	B.8.C.103	SSWS	pipe	rupture	corrosion		<3"	S	6
Perry 1	Apr-87	B.6.B.78	MSS	pipe	rupture	vibration		3"	L	1
Dresden 2	May-71	B.12.4	SI-TL	pipe	rupture	hi press		18"	L	2
Dresden 2	Sep-74	B.6.E.33	APW	pump	rupture	vibration		<1"	S	1
O. Cities 1	Aug-82	B.8.C.295	SSWS	pump	rupture	stress		1/2"	S	2
9-Mile Pt 2	Nov-87	B.6.E.272	CDS	tank	rupture	installer	400 gpm		U	1
Oyster Cr	Jun-82	B.6.E.157	CDS	valve	rupture	vibration	160 gpm	1/2"	S	1

a. See Appendix D for explanations of abbreviations.

b. B.6.E.145 indicates BWR volumes, system category VII; system E, and event 45 in NPE.

Table B-2. Rupture events for PWRs

Plant Name ^a	Date	NRC Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^c	
									size	cnt
Cal Cliffe 1	Nov-81	P.6.E.580	TBN	elbow	rupture	erosion		>3"	L	1
Coconee 2	Jun-82	P.6.D.262	TBN	elbow	rupture	erosion		24"	L	2
Beaver V 1	Dec-82	P.7.E.145	FWTR	flange	rupture	stress		12"	L	1
Salton 2	Aug-82	P.7.C.72	SSXS	ht exchanger	rupture(T)	vibration	12,000 gal	1/2"	S	1
Glenn	Feb-81	P.7.C.64	SSXS	ht exchanger	rupture(T)	plug lost			U	1
Palisades	Dec-79	P.7.E.44	FWTR	pipe	rupture	froze			U	1
Salton 1	Jan-77	P.8.A.175	CVCS-ID	pipe	rupture	vibration	2400 gal	3/4"	S	2
CT Yankee	Mar-85	P.6.E.556	AFW	pipe	rupture	erosion		2 1/4"	S	3
Beaver V 1	Oct-81	P.7.E.145	FWTR	pipe	rupture	corrosion		12"	L	1
Trotter	Mar-85	P.6.E.553	TBN	pipe	rupture	erosion		14"	L	2
Arkansas 2	Apr-85	P.6.E.823	TBN	pipe	rupture	erosion		14"	L	3
Millstone 2	Nov-77	P.12.A.88	WST	tank	rupture	hi press			U	1
Salton 1	Dec-80	P.8.A.491	CVCS-ID	valve	rupture			3/4"	S	1
Robinson 2	May-81	P.8.A.496	CVCS-ID	valve	rupture	hi press	100 gpm	3/4"	S	2

Table B-2. (continued)

Plant Name ^a	Date	NRC Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Saville Is 2	Feb-80	P.7.E.184	RWR	valve	rupture	frcze		1/2"	S	3
Turkey Pt 4	Oct-79	P.6.A.68	CVCS-C4	valve	rupture	hi press	70 gal	<3"	S	4
Pt Beach 1	Mar-79	P.5.E.25	PRZR	valve	rupture			1/2"	S	5
F. Calhoun	Sep-79	P.6.D.69	S6	valve	rupture	vibration		8"	L	1

a. See Appendix D for explanations of abbreviations.

b. P.6.E.180 indicates PWR volumes, system category VII, system E, and event 530 in WPE.

APPENDIX C
PCS LEAKAGE AND RUPTURE DATA

CONTENTS

Table C-1.	BWR PCS leakage and rupture events	C-3
Table C-2.	PWR PCS leakage and rupture events	C-4
Table C-3.	Summary of PCS leakage and rupture events (9/60 - 6/90)	C-10
Table C-4.	Summary of PCS leakage and rupture events (9/60 - 12/83).	C-13

Table C-1. BUR PCS Leakage and rupture events

Plant Name ^a	Date	BWR Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Comp Size (diam)	Classification ^a	
									size	cat
Plant C	Jul-88	E.B.E.1005	PCS	flange-tank	leak		sm leak		U	1
Plant F	Mar-88	E.B.E.1005	PCS	pipe	crack	RGSC	3.5E-5 gpm		U	1
Plant G	May-88	E.B.C.23	PCS	pipe	leak				U	2
Plant H	Dec-88	E.B.E.1117	PCS	pipe	leak				U	3
Plant I	Jun-89	E.B.C.512	PCS	pipe	leak				U	4
Plant J	Mar-89	E.B.43	PCS	pipe	crack	stress	2 gpm	2"	S	1
Plant K	Oct-81	E.B.C.1351	PCS	pipe	leak	installer		13"	S	2
Plant L	Aug-77	E.B.C.114	PCS	pipe	p hole	installer		2"	S	3
Plant M	Sep-73	E.B.C.53	PCS	valve	leak	erosion			U	1
Plant N	Apr-83	E.B.C.240	PCS	valve	leak				U	2
Plant O	Oct-71	E.B.C.4	PCS	valve	open	erosion	2500 gpm		U	3

a. See Appendix D for explanations of abbreviations.

b. E.B.E.1005 indicates BWR volumes, system category IX, system E, and event 1065 in NPE.

Table C-2. PWR PCS leakage and rupture events

Event Name	Date	NRC Reference	System	Component	Failure Mode	Failure Cause	Leakage	Pipe/Com Size (dia)	Classification	
									size	oil
Leakage Event	10/1/00	0.0.0.004	PCS	elbow	pin hole	stress	0.017 gpm		U	1
Leakage Event	10/1/00	0.0.0.004	PCS	flange	crack	stress	12 gpm		U	1
Leakage Event	10/1/00	0.0.0.004	PCS	flange	crack	stress			U	2
Leakage Event	10/1/00	0.0.0.004	PCS	flange	leak				U	3
Leakage Event	10/1/00	0.0.0.004	PCS	flange	leak				U	4
Leakage Event	10/1/00	0.0.0.004	PCS	flange	leak	inad inst		>3"	1	1
Leakage Event	10/1/00	0.0.0.004	PCS	flange	leak			>3"	1	2
Leakage Event	10/1/00	0.0.0.004	PCS	flange-pump	leak	corrosion	0.5 gpm		U	1
Leakage Event	10/1/00	0.0.0.004	PCS	flange-pump	leak			>3"	1	1
Leakage Event	10/1/00	0.0.0.004	PCS	flange-valve	leak	loose nut			U	1
Leakage Event	10/1/00	0.0.0.004	PCS	flange-valve	leak				U	2
Leakage Event	10/1/00	0.0.0.004	PCS	flange-valve	leak				U	3
Leakage Event	10/1/00	0.0.0.004	PCS	flange-valve	leak		>1 gpm		U	4
Leakage Event	10/1/00	0.0.0.004	PCS	flange-valve	leak					
Leakage Event	10/1/00	0.0.0.004	PCS	flange-valve	leak		13.4 gpm	3/4"	S	1
Leakage Event	10/1/00	0.0.0.004	PCS	flange-valve	leak		5 gpm	<3"	S	2
Leakage Event	10/1/00	0.0.0.004	PCS	flange-valve	leak	corrosion		3"	1	1
Leakage Event	10/1/00	0.0.0.004	PCS	flange-valve	leak			3"	1	2

Table C-2. (continued)

Chart Name	Date	NPE Reference	System	Component	Failure Mode	Failure Cause	Leakage	Pipe/Con Size (diam)	Classification	
									size	cnt
COX 01	Feb-93	0.5.A.133	PCS	flange-valve	leak			3"	U	3
COX 2	Dec-94	0.5.A.145	PCS	flange-valve	leak			3"	U	4
W. Area 1	Dec-92	0.7.A.136	PCS	flange-valve	leak	corrosion		6"	U	6
COX 01	Feb-78	0.3.A.119	PCS	pipe	crack	vibration	0.03 gpm		U	1
COX 01	Feb-91	0.3.A.114	PCS	pipe	crack	vibration			U	2
COX 01	Feb-78	0.3.A.113	PCS	pipe	leak		0.25 gpm		U	3
COX 01	Dec-94	0.3.A.132	PCS	pipe	leak	installer	5 gpm	5/8"	U	4
COX 01	Feb-93	0.3.A.123	PCS	pipe	leak				U	5
COX 01	Dec-71	0.3.A.103	PCS	pipe	leak	crack	0.7 gpm	3/4"	U	6
COX 02	Feb-97	0.3.A.115	PCS	pipe	leak	corrosion	100 gpm		U	7
COX 03	Feb-99	0.3.A.137	PCS	pipe	leak	corrosion			U	8
COX 03	Feb-99	0.3.A.137	PCS	pipe	leak	corrosion			U	9
COX 01	Feb-97	0.3.A.134	PCS	pipe	leak	corrosion	0.15 gpm		U	10
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak	fatigue	40 gpm		U	11
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	12
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	13
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	14
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	15
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	16
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	17
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	18
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	19
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	20
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	21
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	22
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	23
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	24
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	25
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	26
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	27
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	28
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	29
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	30
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	31
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	32
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	33
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	34
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	35
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	36
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	37
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	38
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	39
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	40
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	41
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	42
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	43
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	44
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	45
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	46
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	47
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	48
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	49
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	50
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	51
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	52
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	53
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	54
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	55
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	56
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	57
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	58
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	59
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	60
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	61
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	62
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	63
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	64
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	65
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	66
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	67
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	68
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	69
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	70
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	71
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	72
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	73
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	74
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	75
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	76
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	77
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	78
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	79
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	80
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	81
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	82
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	83
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	84
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	85
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	86
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	87
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	88
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	89
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	90
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	91
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	92
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	93
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	94
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	95
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	96
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	97
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	98
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	99
COX 01	Feb-75	0.3.A.116	PCS	pipe	leak				U	100

Table C-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Saccharat 1	Oct-80	P.5.A.93	PCS	pipe	crack	vibration		<3"	S	2
Vankee 5	Oct-82	P.5.A.115	PCS	pipe	crack	corrosion		1"	S	3
Cal Cliff 2	Jul-74	P.5.A.122	PCS	pipe	crack	vibration	1 gpm	<3"	S	4
Sumner	May-87	P.5.A.156	PCS	pipe	crack	bad weld		<1"	S	5
Millstone 3	Sep-75	P.5.B.5	PCS	pipe	crack	stress	0.5 gpm	1"	S	6
Millstone 2	Oct-75	P.5.B.7	PCS	pipe	crack	stress		1"	S	7
Arkansas 1	Oct-74	P.5.B.8	PCS	pipe	crack		4 gpm	1 1/2"	S	8
Arkansas 1	Oct-74	P.5.B.8	PCS	pipe	crack		2.5 gpm	1 1/2"	S	9
Millstone 2	Jul-76	P.5.B.9	PCS	pipe	crack	stress	0.1 gpm	1"	S	10
Millstone 2	Apr-77	P.5.B.13	PCS	pipe	crack	fatigue	<1 gpm	1"	S	11
Seaver V 1	Feb-81	P.5.B.14	PCS	pipe	crack	corrosion	2.7 gpm	1"	S	12
Cal Cliff 2	Apr-83	P.5.B.29	PCS	pipe	crack	vibration	<tech sp	1"	S	13
Pat'seeds	Aug-84	P.5.B.33	PCS	pipe	crack	vibration		3/4"	S	14
Pat'seeds	Aug-84	P.5.B.33	PCS	pipe	crack	vibration		3/4"	S	15
Robinson 2	Jun-83	P.5.B.36	PCS	pipe	crack		1.2 gpm	<3"	S	16
Robinson 2	Feb-89	P.5.B.45	PCS	pipe	crack	fatigue		<3"	S	17
Beaver V 1	Nov-88	P.5.F.69	PCS	pipe	crack	stress		<3"	S	18
Coonee 2	May-74	P.7.A.49	PCS	pipe	crack	vibration	weep	3/4"	S	19
Turkey Pt 4	Oct-74	P.7.A.76	PCS	pipe	crack	installer		3/4"	S	20
CT Yankee	Mar-79	P.8.A.342	PCS	pipe	crack			2"	S	21
S Croft 3	Mar-86	P.5.E.113	PCS	pipe	crack	IGCSS		3/4"	S	22
Palo Verde	Mar-87	P.5.F.56	PCS	pipe	crack	fatigue	0.5 gpm	<3"	S	23
F Dalhous	Oct-79	P.5.A.51	PCS	pipe	crack	vibration	0.2 gpm	<3"	S	24

Table C-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
F. Calhoun	Feb-72	P.5.A.75	PCS	pipe	crack	vibration	0.2 gpm	<3"	S	25
Salmon 1	Jan-77	P.9.B.288	PCS	pipe	failed			3/8"	S	26
Arkansas 1	Jan-82	P.5.A.110	PCS	pipe	leak	loose bit	1.4 gpm	<3"	S	27
Cap Cliff 2	Jul-88	P.5.A.146	PCS	pipe	leak	loose fit	>1 gpm	<1"	S	28
Catevba	Jan-87	P.5.E.118	PCS	pipe	leak	installation	6 gpm	1/2"	S	29
Catevba	Oct-85	P.5.F.49	PCS	pipe	leak	vibration	0.6 gpm	1/2"	S	30
Goosee 2	Sep-81	P.9.B.815	PCS	pipe	leak			<3"	S	31
Goosee 1	Jun-82	P.9.B.715	PCS	pipe	leak	loose		<3"	S	32
Goosee 3	Sep-74	P.5.A.88	PCS	pipe	p hole			1 1/2"	S	33
Arkansas 1	Jan-77	P.5.A.54	PCS	pipe	p hole		0.5 gpm	<3"	S	34
Stone 1	Jan-82	P.8.A.588	PCS	pipe	p hole			6"	L	1
Robinson 2	Apr-75	P.5.A.40	PCS	pump	leak		>6 gpm		U	1
N. Anna 1	Dec-80	P.5.A.95	PCS	pump	leak		13 gpm		U	2
F. Calhoun	May-80	P.5.F.34	PCS	pump					U	3
N. Anna 1	Sep-85	P.5.F.47	PCS	pump	leak		16.5 gpm	1 1/2"	S	1
Arkansas 2	Apr-87	P.5.E.119	PCS	tank	leak	corrosion	60 dpm		U	1

Table C-2. (continued)

Plant Name ^a	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Indian Pt. C	Feb-77	P.8.A.198	PCS	valve	crack	vibration			U	1
Farley I	May-83	P.8.C.35	PCS	valve	leak	loose	1.75 gpm		U	2
Turkey Pt. I	Aug-83	P.4.B.97	PCS	valve	leak				U	3
Bayton I	Jul-88	P.5.C.102	PCS	valve	leak	packing	0.5 gpm		U	4
Wittetstone I	Jul-82	P.5.E.88	PCS	valve	leak		>1 gpm		U	5
Wittetstone I	Jul-82	P.5.E.88	PCS	valve	leak		>1 gpm		U	6
Indian Pt. C	Sep-70	P.5.E.28	PCS	valve	leak	packing	2.4 gpm		U	7
Indian Pt. C	Sep-78	P.5.E.28	PCS	valve	leak	packing	2.4 gpm		U	8
Sevier I-3	Dec-76	P.6.E.190	PCS	valve	leak				U	9
Sevier I-3	Nov-88	P.6.E.91	PCS	valve	leak	erosion			U	10
Corcoran I	Aug-79	P.8.A.381	PCS	valve	leak				U	11
Callaway	Aug-88	P.9.C.382	PCS	valve	leak		2.7 gpm		U	12
Callaway I-2	Nov-82	P.6.C.1181	PCS	valve	leak		22 gpm		U	13
Sevier V-1	Feb-81	P.5.E.50	PCS	valve	leak		2.0 gpm		U	14
Callaway I	Oct-85	P.5.E.49	PCS	valve	leak				U	15
Sevier V	Oct-87	P.5.E.64	PCS	valve	leak		1.5 gpm		U	16
Sevier V	Oct-87	P.5.E.64	PCS	valve	leak		1.5 gpm		U	17
Sevier V	Oct-87	P.5.E.64	PCS	valve	leak		1.5 gpm		U	18
St. Beath I	Jun-77	P.9.C.6	PCS	valve	leak	stress	3 gpm	3/8"	U	19
Sevier I-3	Jul-80	P.5.C.84	PCS	valve	crack	bad weld		1"	S	1
Sevier I	Aug-75	P.5.E.17	PCS	valve	leak	packing	2.5 gpm	2"	S	2
Sevier I	Sep-85	P.5.E.47	PCS	valve	leak		16.5 gpm	1 1/2"	S	3

Table C-2. (continued)

Plant Name ^c	Date	NPE Reference ^b	System ^a	Component	Failure Mode ^a	Failure Cause ^a	Leakage	Pipe/Com Size (diam)	Classification ^a	
									size	cnt
Catawba 2	Apr-87	P.E.A.794	PCS	valve	leak		1.8 gpm	1/2"	S	4
Catawba 1	Oct-85	P.E.F.49	PCS	valve	leak			2"	S	5
Indian Pt 2	Jan-76	P.E.B.77	PCS	valve	leak		11 gpm	14"	L	1
A Area 1	Sep-85	P.E.F.49	PCS	valve	leak		17 gpm	8"	L	2

a. See Appendix D for explanations of abbreviations.

b. P.E.A.354 indicates BWR volumes, system category VIII, system A, and event 354 in NPE.

Table C-3. Summary of PCS leakage and rupture events (9/60 - 6/90)

Component	BWR		PWR		Total BWR/PWR	
	leakage	rupture	leakage	rupture	leakage	rupture
Elbow						
Unknown	0	0	1	0	1	0
<3"	0	0	0	0	0	0
>=3"	0	0	0	0	0	0
Total	0	0	1	0	1	0
Flange						
Unknown	0	0	4	0	4	0
<3"	0	0	0	0	0	0
>=3"	0	0	2	0	2	0
Total	0	0	6	0	6	0
Flange (ht exchanger)						
Unknown	0	0	0	0	0	0
<3"	0	0	0	0	0	0
>=3"	0	0	0	0	0	0
Total	0	0	0	0	0	0
Flange (pump)						
Unknown	0	0	1	0	1	0
<3"	0	0	0	0	0	0
>=3"	0	0	1	0	1	0
Total	0	0	2	0	2	0

Table C-3. (continued)

Component	BWR		PWR		Total BWR/PWR	
	leakage	rupture	leakage	rupture	leakage	rupture
Flange (tank)						
Unknown	1	0	0	0	1	0
<3"	0	0	0	0	0	0
>=3"	0	0	0	0	0	0
Total	1	0	0	0	1	0
Flange (valve)						
Unknown	0	0	4	0	4	0
<3"	0	0	2	0	2	0
>=3"	0	0	5	0	5	0
Total	0	0	11	0	11	0
Flange (all flanges)						
Unknown	1	0	9	0	10	0
<3"	0	0	2	0	2	0
>=3"	0	0	8	0	8	0
Total	1	0	19	0	20	0
Heat Exchanger						
Unknown	0	0	0	0	0	0
Tube	0	0	0	0	0	0
Shell	0	0	0	0	0	0
Total	0	0	0	0	0	0

Table C-3. (continued)

Component	BWR		PWR		Total BWR/PWR	
	leakage	rupture	leakage	rupture	leakage	rupture
Pipe						
Unknown	4	0	17	0	21	0
<3"	3	0	35	0	38	0
>=3"	0	0	1	0	1	0
Total	7	0	53	0	60	0
Pump						
Unknown	0	0	3	0	3	0
<3"	0	0	1	0	1	0
>=3"	0	0	0	0	0	0
Total	0	0	4	0	4	0
Tank						
Unknown	0	0	1	0	1	0
<3"	0	0	0	0	0	0
>=3"	0	0	0	0	0	0
Total	0	0	1	0	1	0
Valve						
Unknown	3	0	19	0	22	0
<3"	0	0	5	0	5	0
>=3"	0	0	2	0	2	0
Total	3	0	26	0	29	0

Table C-4. Summary of PCS leakage and rupture events (9/60 - 12/83)

Component	BWR		PWR		Total BWR/PWR	
	leakage	rupture	leakage	rupture	leakage	rupture
Elbow						
Unknown	0	0	1	0	1	0
<3"	0	0	0	0	0	0
>=3"	0	0	0	0	0	0
Total	0	0	1	0	1	0
Flange						
Unknown	0	0	4	0	4	0
<3"	0	0	0	0	0	0
>=3"	0	0	1	0	1	0
Total	0	0	5	0	5	0
Flange (ht exchanger)						
Unknown	0	0	0	0	0	0
<3"	0	0	0	0	0	0
>=3"	0	0	0	0	0	0
Total	0	0	0	0	0	0
Flange (pump)						
Unknown	0	0	1	0	1	0
<3"	0	0	0	0	0	0
>=3"	0	0	1	0	1	0
Total	0	0	2	0	2	0

Table C-4. (continued)

Component	BWR		PWR		Total BWR/PWR	
	leakage	rupture	leakage	rupture	leakage	rupture
Flange (tank)						
Unknown	0	0	0	0	0	0
<3"	0	0	0	0	0	0
>=3"	0	0	0	0	0	0
Total	0	0	0	0	0	0
Flange (valve)						
Unknown	0	0	4	0	4	0
<3"	0	0	0	0	0	0
>=3"	0	0	4	0	4	0
Total	0	0	8	0	8	0
Flange (all flanges)						
Unknown	0	0	9	0	9	0
<3"	0	0	0	0	0	0
>=3"	0	0	6	0	6	0
Total	0	0	15	0	15	0
Heat Exchanger						
Unknown	0	0	0	0	0	0
Tube	0	0	0	0	0	0
Shell	0	0	0	0	0	0
Total	0	0	0	0	0	0

Table C-4. (continued)

Component	BWR		PWR		Total BWR/PWR	
	leakage	rupture	leakage	rupture	leakage	rupture
Pipe						
Unknown	1	0	12	0	13	0
<3"	2	0	25	0	27	0
≥3"	0	0	1	0	1	0
Total	3	0	38	0	41	0
Pump						
Unknown	0	0	3	0	3	0
<3"	0	0	0	0	0	0
≥3"	0	0	0	0	0	0
Total	0	0	3	0	3	0
Tank						
Unknown	0	0	0	0	0	0
<3"	0	0	0	0	0	0
≥3"	0	0	0	0	0	0
Total	0	0	0	0	0	0
Valve						
Unknown	3	0	12	0	15	0
<3"	0	0	2	0	2	0
≥3"	0	0	1	0	1	0
Total	3	0	15	0	18	0

APPENDIX D

NOMENCLATURE USED IN LEAKAGE AND RUPTURE TABLES

CONTENTS

Table D-1.	Plant names	D-3
Table D-2.	System names.	D-5
Table D-3.	Failure modes	D-7
Table D-4.	Failure causes.	D-8
Table D-5.	Classification.	D-10

Table D-1. Plant names

Pressurized Water Reactors

Arkansas One 1,2	Prairie Island (Prairie I)
Beaver Valley 1 (Beaver V)	Rancho Seco (Rancho S)
Bryon	Robinson 2
Callaway	Salem 1,2
Calvert Cliffs 1,2,3 (Cal Cliff)	San Onofre (S Onofre)
Catawba 1	Sequoyah 1,2
Connecticut Yankee (CT Yankee)	St. Lucie 1
Cook 1,2	Summer
Crystal River 3 (Crystal R)	Surry 1,2
Diablo Canyon 1,2 (Diablo Cn)	Three Mile Island 1,2 (3-Mile Is)
Farley	Trojan
Fort Calhoun (F Calhoun)	Turkey Point 3,4 (Turkey Pt)
Ginna	Vermont Yankee (V Yankee)
Indian Point 1,2,3 (Indian Pt)	Waterford
Kewaunee	Wolf Creek
Maine Yankee (M Yankee)	Zion 1,2
McGuire 1	
Millstone 2	
North Anna 1,2 (N Anna)	
Palisades	
Oconee 1,2,3	
Palo Verde 2,3 (Palo Ver)	
Point Beach 1 (Pt Beach)	

Table D-1. (continued)

Boiling Water Reactors

Arnold

Brown's Ferry (Br Ferry)

Brunswick 2 (Bruns)

Couper

Dresden 1,2,3

Fermi 1,2

Fitzpatrick

Grand Gulf (G Gulf)

Hatch 1,2

Hope Cr (Hope Creek)

La Salle 1

Millstone

Monticello

Oyster Creek (Oyster Cr)

Peach Bottom (P Bottom)

Quad Cities 2 (Q Cities)

River Bend (Riv Bend)

Susquahanna (Susqua.)

Vermont Yankee (V Yankee)

Washington Nuclear Project - 2 (WNP-2)

Table D-2. System names

ACC - Accumulator System
ADS - Automatic Depressurizer System
AFW - Auxiliary Feedwater or Feedwater
AUX - Auxiliary System
BAS - Boric Acid System
CCW - Component Cooling Water
CDS - Condensate System
CIS - Containment Isolation System
CPPS - Containment Pressure Suppression System
CRDM - Control Rod Drive Mechanism
CS - Core Spray (BWR)
CSK - Cask System
CSS - Containment Spray (PWR)
CVCS - Chemical Volume Control System
CH - Charging System
LD - Let Down
MU - Makeup
VC - Volume Control Tank
DMIN - Demineralized Water System
DG - Diesel Generator
DHR - Decay Heat Removal System
ECCS - Emergency Core Cooling System
FWTR - Fire Water
HPCS - High Pressure Core Spray
HPSW - High Pressure Service Water
HVCS - Heating and Ventilation Cooling System
MSS - Main Steam System

Table D-2. (continued)

NSSS	- Nuclear Steam Supply System
PCS	- Primary Coolant System
PORV	- Power Operated Relief Valve
PRZR	- Pressurizer
RCIC	- Reactor Core Isolation Cooling
RHR	- Residual Heat Removal
RTT	- Recycle Test Tank
RWCU	- Reactor Water Cleanup Unit
RWST	- Radioactive Waste Storage Tank
SFCS	- Spent Fuel Coolant System
SFP	- Spent Fuel Pool
SG	- Steam Generator
SI	- Safety Injection
	LPSI - Low Pressure Safety Injection
	HPCI - High Pressure Safety Injection
	TL - Low Pressure Test Line
SSWS	- Station Service Water System
TBN	- Turbine System
WST	- Waste Storage Systems

Table D-3. Failure modes

---

blown	
broken	
break	
crack	
clog	
drip	
failed	
failure	
flood	
fracture	
leak	
loose	
open	
pitting	
plug	
p hole	- pin hole leak
rupture	
split	
weld	
weep	
op er	- operator error

For heat exchangers, (T) next to the failure mode indicates a failure in the tube side. (S) indicates a failure in the shell. (?) indicates that there was not enough information to determine if the failure involved the shell or the tubes.

Table D-4. Failure causes

---

bad weld	-	improper welding, i.e. human error
corrosion		
crevice		
defective		
degredation		
deterior.	-	deterioration
environ	-	environment
erosion		
fatigue		
froze		
hi pH	-	high pH
hi press	-	high pressure
IGSCC	-	Intergranular Stress Corrosion Cracking
inad inst	-	inadequate instrumentation
instal er	-	installation error cause leak or rupture
loose		
loose nut		
loose bolt		
loose fit		
low temp	-	low temperature caused leak or rupture
obstruction		
packing		
pinched		
plug lost		
pr excur	-	pressure excursion

Table D-4. (continued)

---

stress

TGSCC - Thermogranular Stress Corrosion Cracking

th fatigue - thermal fatigue

th stress - thermal stress

vibration

wear

worn out

WH - water hammer caused leak or rupture

Table D-5. Classification

The Classification category in tables listing NPE events is broken into three subcategories: size, count, and location. Size refers to the size classification of the piping or component, and is divided into the following groups:

U - unknown size

S - small, less than 3" in diameter

L - large, greater than or equal to 3" in diameter

Count merely numbers the events by component type, failure mode (leak or rupture), and by size.

END

**DATE
FILMED**

6 / 15 / 92