DOE/CE/15387--T13

DOE/CE/15387--T13

DE92 004946

**FINAL TECHNICAL REPORT
FOR A QUIET OPERATING I.C. ENGINE
WITH COMPLETE HIGHLY EFFICIENT EXPANSION CYCLE**

GRANT NO. DE-FG01-88CE-15387

**PREPARED FOR
THE DEPARTMENT OF ENERGY
WASHINGTON D.C. 20585**

DECEMBER 2, 1991

**PREPARED BY
ENGINE RESEARCH ASSOCIATES, INC.
2610 BOSWORTH DRIVE
FORT WAYNE, IN 46805
219-483-2093**

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

MASTER

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

TABLE OF CONTENTS

<u>SECTION</u>	<u>TITLE</u>	<u>PAGE</u>
	List of Illustrations	i
1.0	Introduction	1
2.0	Program Accomplishments and Problems Encountered	1
2.1	Program Accomplishments Under ERA Funding	2
3.0	Engine Specifications and Configuration	3
4.0	Pictures and Associated Description	4
5.0	Testing Methodology	6
6.0	Testing Results	7
6.1	Description of Test Equipment	7
6.2	Calibration of Load Cell and RPM Circuits	7
6.3	Torque and Horsepower Data	7
6.4	Brake Specific Fuel Consumption	8
6.5	Operating Temperatures	9
6.6	Interpretation of Data and Conclusions	9
6.7	Exhaust Noise	10
6.8	Torque Curve Fall Off	10
7.0	Recommendations and Commercialization Effort	10
8.0	Facilities and Personnel	11

LIST OF ILLUSTRATIONS

<u>FIGURE</u>	<u>TITLE</u>	<u>PAGE</u>
1	Engine Mounted to Dynamometer	4
2	Engine Component Parts	5
3	Engine Attached to Lawn Mower Deck	5
4	Torque and Power versus RPM	8
5	Torque Comparison - MCC versus OVE	9

<u>TABLE</u>	<u>TITLE</u>	<u>PAGE</u>
1	Table of Torque, Horsepower and RPM Data	7

1.0 INTRODUCTION

A program for the development of a quiet operating internal combustion engine with complete highly efficient expansion cycle was administered by the Department of Energy on June 14, 1988 through December 13, 1989. An extension, modification M001 to the contract allowed up to June 12, 1991 to complete this work. The extension was granted in order for Engine Research Associates, Inc. (ERA) to continue the development of the engine on its own funds to a level of performance required for an independent testing facility to test and report on the engine's performance. As it turned out, we were not able to complete all of the detailed development work under ERA, Inc. funding necessary to bring the engine up to a sufficient development status to allow an independent test lab to complete the full-up performance testing on the engine. However, we have incorporated enough refinements to be able to complete a somewhat restricted dynamometer test program on the engine using the ERA acquired dynamometer. A discussion of these refinements and how we were able to conduct a refined test is discussed under program accomplishments.

For a complete review of the program's progress and accomplishments, please refer to the twelve quarterly reports as submitted to the DOE.

2.0 PROGRAM ACCOMPLISHMENTS AND PROBLEMS ENCOUNTERED

The following accomplishments were completed along with a description of the problems encountered under the DOE funding segment of the program.

1. A full up 6.25 cubic inch MCC full expansion engine was designed using a computer microcadam drafting system. This design included a self contained cooling fan and housing assembly, a pedestal and bearing assembly to mount the engine to a lawn mower deck, and a complete exhaust system to vent the exhaust gas under the deck. Also, a custom designed inductive ignition system with hall effect sensors was eventually incorporated into the engine to eliminate ignition problems encountered with an initial CD system.
2. Two sets of engine parts were ordered from outside vendors. All of the power block components were either plaster mold cast from 356 aluminum or sand cast from 390 high silicon aluminum. ERA made the wooden patterns for sand casting the orbiting piston and combustion chamber member. The remainder of the parts were machined from bar stock aluminum or brass.
3. Final assembly grinding and final assembly of the two engines was completed after ERA fabricated the fixtures and tooling required to accomplish this. Initial test runs were completed on a special fabricated run fixture.
4. A dynamometer was acquired from the Naval Surface Weapons Center. Title to the dynamometer was transferred to the DOE from NSWC and the unit was shipped to ERA to be used for validation testing. ERA performed a complete overhaul on the unit and had to order missing hardware consisting of the control console which housed the torque and RPM sensor equipment. The dynamometer was otherwise useless without these repairs.

5. The first engine which was set-up for testing on the dynamometer self destructed due to faulty chrome plating. Eventually a switch to a flame sprayed TRIBALLOY coating was applied to the second engine and solved the problem. An inordinate amount of time was required to solve the plating problems and ignition difficulties. The U.S. Chrome Company of Ohio was especially uncooperative in helping us solve the peel off problem with their hard chrome plating. We also had to retain an ignition expert in order to adapt an existing inductive system to the engine to eliminate missing problems. These problems added significant cost to the program. The problems were eventually solved and yielded an engine with very good operational performance considering it to be a first existence prototype design of this size.

6. The final completed engine was subjected to a series of dynamometer tests which illustrated that the engine did suffer a thermal problem. This problem was related to the cooling system's inability to maintain adequate heat removal during full load testing without suffering from thermal overheating and consequent power loss. The off-the-shelf fan selected was of insufficient design to remove the necessary amount of rejected heat. The design was adequate for operating the engine on a lawn mower at relatively low power levels as mowers normally operate. Witness to this was the fact that the mower was used to mow the entire backyard at the ERA headquarters facility without suffering from the thermal difficulty. However, additional design engineering will be required to incorporate an adequate cooling system.

7. Even though the design suffered from the thermal problem it had sufficient performance to demonstrate the engine's viability. The engine was adapted to a special Toro mower deck and was then demonstrated to a number of major lawn mower manufacturers including Toro, B & S and Kubota. The engine was well received and we are continuing discussions with a couple of the companies regarding developing and commercialization of the engine. We have found, however that marketing to companies that have tooled production engines is difficult even if the engine offers performance and cost advantages.

2.1 Program Accomplishments Under ERA Funding

A point was reached in which ERA had used up most of the DOE grant funding of approximately \$54,538 by the end of 1989. This left \$8,947 for funding an outside test lab to complete an independent performance evaluation (This funding was never used). The object was to continue working on the engine using ERA funding to advance the design to the point in which the engine's thermal problems could be minimized and it could then be turned over to a test lab for performance testing. Due to other program commitments and fiscal constraints, we were unable to bring the engine up to a development level sufficient for a test lab evaluation in the overall time frame given to us by DOE. However, we have been able to complete several important upgrades to the engine under ERA funding and will continue to improve the design as funding may become available through venture partners or other sources.

Several improvements made to the engine under ERA funding and some commercialization activities funded by ERA are included as follows:

1. Clearance adjustments - involved regrinding the O.P. and CCM surfaces several times.
2. Adaptation of a special wear strip to the CCM end clearance.
3. Designed, fabricated and installed a very compact recoil pull starter to the lower crankshaft of the engine (inside the pedestal cavity). This was difficult due to the space available. This made demonstration of the engine on the lawn mower deck a practical reality.
4. Redesigned the exhaust hose to vent above the deck to illustrate how quiet the venting exhaust was to prospective customers.
5. Adapted a float type carburetor to the engine to replace a diaphragm carburetor found to be incompatible with the low pressure induction pulses of the engine.
6. Commercialization activity included a trip to B & S to demonstrate the engine to approximately ten engineers and their R & D director. Also, a paper was presented to the SAE Off-Highway Conference in Milwaukee on September 13, 1989 and a booth was acquired to promote the engine. An overwhelming response was received on the paper and at the booth.

3.0 ENGINE SPECIFICATIONS AND CONFIGURATION

The engine type developed under the Department of Energy grant is an MCC (Migrating Combustion Chamber) full expansion engine which is defined in its new cycle of operation by seven methods claims in Patent No. 4,325,331. Also, Patent No. 4,437,437 describes the MCC mechanism used to accomplish this cycle. The basic specifications for the engine developed under this grant is given as follows:

- Total swept intake volume = 6.25 cubic inches.
- Total expansion volume = 21.87 cubic inches.
- Measured horsepower @ 3,000 RPM = 3.6 H.P.
- Maximum torque = @ 3,000 RPM = 6.3 ft lbs.
- BSFC = .79 lbs/BHP-HR @ WOT conditions.
- Compression ratio = 8 to 1.
- Total weight including cooling system, pedestal mount for lawn mower attachment, pull starter assembly and ignition systems is 17 pounds.
- Size = 8 inches diameter x 7 inches long.
- Mechanism consists of an orbiting piston (OP) with rotatable connection to a crankshaft which causes the OP to move in a pure orbital motion. The orbiting piston slides back and forth inside a combustion chamber member (CCM) in turn causing the CCM to slide back and forth inside a fixed power block. The combined motion of the OP and CCM produces four variable volume chambers of which two chambers inside the CCM separated by the OP are combustion chambers and two chamber inside the power block

separated by the CCM are secondary expansion chambers. (Refer to SAE paper 891792 in the Appendix A)

4.0 PICTURES AND ASSOCIATED DESCRIPTION

Figure 1 illustrates the 6.25 engine on the dynamometer. Note, the engine itself is mounted on a plate which is part of the mower deck. The engine shaft attaches to the load pump by a flexible coupling inside the dynamometer housing. This large housing contains five gallons of hydraulic fluid which absorbs the heat of power absorption until the fluid temperature reaches

Figure 1. Engine Mounted Dynamometer

160°F. The starter motor in the rear couples to a large sprocket and roller clutch (shown inside the three stand offs). Note, the instrument box in front of the dynamometer provides RPM on the left meter and load on the right meter. The exhaust pipe is a long rubber hose shown attached to the top of the engine and vents to the outside.

Figure 2 illustrates the component parts of the engine and Figure 3 shows the engine as attached to the lawn mower deck in its operational configuration. Appendix A of this report includes a copy

of SAE paper 891792 which contains additional information on this engine plus a description of its operating cycle.

Figure 2. Component Parts of Engine

Figure 3. Engine Mounted To Lawn Mower Deck

5.0 TESTING METHODOLOGY

A final series of tests were conducted in November 1991 using the dynamometer at ERA. These tests included all of the refinements to date and basically consisted of obtaining a torque versus RPM curve using a somewhat restricted procedure because of the thermal dissipation problem as described previously. Under a normal testing situation, a certified testing lab will record a torque curve with the engine operating at 100% Wide Open Throttle (WOT) conditions throughout the entire torque curve. Since the present engine will overheat under these conditions with a consequent loss of power (and an overall poor showing) a revised procedure was incorporated. This procedure was set up to conduct a series of torque spot checks over a range of RPM values. The engine was operated until the engine block was stabilized at a normal temperature of about 325°F. Then the throttle was advanced under load to a WOT condition for a short time in which mixture and spark timing were optimized to obtain maximum torque. After the torque and RPM reading was recorded the throttle was reduced until the engine block returned to 325°F. The load was then changed and the procedure was repeated until a complete torque/RPM curve was obtained.

This procedure kept the engine block temperature at an optimum point so that each spot torque check would yield a value more consistent with what the unit would achieve had it been equipped with an adequate cooling system.

A technique for calculating the BSFC in lbs per BHP hour was also devised to reduce the time the engine was operating at the WOT condition. This procedure also involved a short term advancement of the throttle to the WOT condition. Once the engine speed stabilized under load, a set quantity of fuel was measured by a stopwatch. The fuel level was monitored as it flowed out of a calibrated burette in which the time for the fuel level to descent five cubic centimeters was measured a number of times by stop watch and averaged. These readings were taken during full load conditions around 3,000 RPM. The average time for using the five cc of fuel at WOT conditions was approximately ten seconds. This time was short enough so that the block did not get hot enough to unduly influence the test.

The torque and brake specific fuel consumption data was not corrected for standard atmospheric temperature and pressure. Although both were noted to be very close to the standard values.

The basic objective of this test was to illustrate that although the engine is still in a very early stage of development, it has some very important performance features that even this early model exhibits. The next section outlines the actual test data and illustrates a very flat torque curve from 1,200 to 3,200 RPM which is made possible by the full expansion process and appropriate port timing.

6.0 TEST RESULTS

6.1 Description of Test Equipment

Dynamometer - Power Shop SE-25, Model 6032 manufactured by Technical Systems, Inc. of St. Paul, Minnesota. (Uses a throttled hydraulic pump to adjust the load - refer to photograph- Figure 1.)

Temperature - Thermal couples monitored block and exhaust temperature, using Model 80-TK fluke thermocouple module.

Fuel Consumption - Standard burette calibrated in cubic centimeters plus a digital stop watch.

Sound Level Meter - REALISTIC MODEL NO. 33-2050

Electric Starter - Standard 12 volt small automotive type starter (capable of rotating the engine at 900 RPM).

Ignition System - Modified Harley Davidson system using computer module to switch timing point at 1,800 RPM - high capacity inductive system.

Fueling System - Standard float type small carburetor. Fed by gasoline tank mounted at higher level.

6.2 Calibration of Load Cell and RPM Circuit

The dynamometer used a standard load cell in which the moment arm had an extension to which a precision tension scale could be connected to calibrate the circuit. Also, an electronic RPM meter was calibrated by motoring the dynamometer while adjusting a potentiometer to agree with a precision digital tachometer. The torque was calculated as the product of the load times the moment arm length of .525 feet. The horsepower was thus calculated as $= 2 \times 3.1416 \times \text{load} \times .525 \times \text{RPM}$ divided by 33,000.

6.3 Data

A summary of the averaged performance data is recorded in Table 1 from the laboratory log dated November 23, 1991 and November 24, 1991.

Table 1 Torque and Horsepower Data (See Torque & Power Curves - Figure 4)

ID	Lbs LOAD	Torque Ft-Lbs *	RPM	Corrected RPM	Horsepower
1	2	1.05	4000	4500	0.80
2	8	4.20	3600	3600	2.88
3	12	6.30	2500	3000	3.60
4	12	6.30	2100	2400	2.87
5	11	5.77	2000	2300	2.53
6	11	5.77	1800	1800	1.98
7	11	5.77	1500	1500	1.65
8	11	5.77	1200	1200	1.32
9	0	0	4700	4700	0

* Torque = Load $\times$ Moment Arm Length (.525 Ft)

6.4 Brake Specific Fuel Consumption (BSFC)

BSFC was observed at the best power point with several readings of fuel consumption taken around 3,000 RPM at a power level of 3.6 HP. Fuel consumption was recorded as 5 cc per 10 seconds.

Figure 4 - Torque and Horsepower vs RPM for 6.25 IN³ MCC Full Expansion Engine.

Figure 5 - Torque Comparison of MCC 6.25 IN³ Engine with 10.00 IN³ 5 HP OHV 4 - Stroke Engine. In normal operating range.

This is equal to 2.85 lb/HR divided by 3.596 HP = .79 lb/BHP-HR.

This value is about the same as typical four stroke engines in this size and power category. We are very optimistic that further development will decrease the BSFC in the range of .55 to .65 (for this size engine).

6.5 Operating Temperatures

Maximum operating temperature of the power block was 375°F and 300°F for the exhaust gas under full load conditions.

6.6 Interpretation of Data and Conclusions

Notice that from 1,200 RPM to 3,000 RPM the torque is very flat. As a matter of fact the torque in this region is very competitive with a standard five HP overhead valve engine (OVE) used in the top of the line deluxe lawn mowers. Figure 5 illustrates that the MCC full expansion engine had improved torque over the OVE in the lower end of its normal operating range which is beneficial in keeping the mower from stalling out in high grass or under sudden loading conditions.

6.7 Exhaust Noise

Since the MCC engine has no exhaust blow down noise, the exhaust gas exits the engine by forced ejection which results in a low acoustic signature. Sound level meter readings were recorded with the MCC engine mounted to the Toro lawn mower deck. Considering the relatively high level of mechanical noise, the readings were relatively low due primarily to the absence of hot-high pressure exhaust noise associated with standard mowers equipped with mufflers.

The sound level readings observed were recorded on August 4, 1990 from the lab data book. These readings were:

- Meter located close to the operator's ears or approximately five feet behind mower = 82 DB on A scale.
- Meter located 50 feet from the lawn mower, the meter reading was 68 DB. A Lawnboy mower readings were 88 DB and 74 DB, respectively for the same distances.

6.8 Power Curve Fall Off

Although the torque is nearly constant from 1,200 through 3,000 RPM (see Figure 4), a rather rapid fall off begins to occur soon after the speed passes 3,000 RPM. This should not be a cause for alarm. Port timing for the 6.25 lawn mower engine has been specifically selected to give a flat high torque up to 3,000 RPM. Since operation above this speed is not necessary for the lawn and garden equipment application, the port timing was tailored to produce maximum torque in this speed range with a consequent rapid fall off in torque over 3,000 RPM. For higher power applications, other full expansion designs incorporate port timing to enhance good torque up to 6,000 RPM, with a resultant power to size ratio exceeding 1 HP per cubic inch displacement. The migrating combustion chamber mechanism used for the full expansion operation is ideally suited for customizing the torque/speed characteristics because of the ability to change the induction opening and closing times totally independent of each other and also independent relative to the opening of the secondary expansion chamber. This feature is made possible due to the non symmetrical porting provided by the movement of the migrating combustion chamber past these ports in one direction and the movement of the orbiting piston past these same ports in the other direction perpendicular to the first direction. This results from the capability of being able to open any specific side port by one member and then being able to close this same port with the other member.

7.0 RECOMMENDATIONS AND COMMERCIALIZATION EFFORT

The subject MCC full expansion engine will continue to be developed under ERA funding as these funds are made available through commercial licenses and also by voluntary labor by ERA personnel. The areas in which further development is needed is listed as follows:

1. Design of a high efficiency cooling system which would be specifically designed for this engine and application.

2. Further refinement in sealing, materials and coatings to improve heat transfer, control thermal expansion and maintain good sealing at WOT conditions without the mechanism overheating.
3. Development of a speed control governor for lawn care equipment applications.
4. Develop a production prototype with the associated tooling to build a number of field test models.

The present engine has generated a high degree of interest within the engineering circles of several major small engine manufacturers. We have also just found out that a smaller MCC full expansion engine which was tested by Southwest Research Institute last year has demonstrated significantly less exhaust emissions (particularly hydrocarbon emissions) than comparable size off-the-shelf two stroke engines used in lawn care equipment. And even though the MCC engine emission performance was better, the thing that impressed us was the fact that during this test, the carburetion had to be set very rich in order to keep the diaphragm in the standard carburetor pumping. Converting the 6.25 engine to a standard float carburetor has totally solved this fuel feed problem as explained in the previous section on engine refinements.

We are confident that this new data will find accelerating interest in light of the more stringent emissions requirements being imposed by the California Air Resources Board (CARB). We will continue to use every avenue possible to us to promote, develop and eventually commercialize the MCC full expansion engine. Any interest generated from DOE contacts would be appreciated.

8.0 FACILITIES AND PERSONNEL

All work on the 6.25 engine was accomplished at the ERA computer center, machine shop and laboratory. Our facility is located at 2610 Bosworth Drive, Fort Wayne, Indiana.

The specific duties of the dedicated employees during the development period are given as follows:

Fred Erickson - Principal Investigator

Responsible for all technical and fiscal effort of the program, including scheduling, preparing quarterly technical and financial reports and directing all aspects of the program including the design and development of the MCC engine.

Rick Erickson - Design Engineer

Responsible for the engine data and drawing package using the Micro CADAM computer drafting system.

Jeff Erickson - Production Manager

Responsible for coordinating the fabrication of the two engines during the program. He coordinated all casting activity, plating and machining of the bar stock components. He also fabricated the final assembly

tooling and fixtures. He procured and custom modified the lawn mower deck for the MCC engine and assisted in the testing activity.

Bruce Smith - Ignition System Designer

Coordinated the integration of the ignition components necessary to adapt a credible inductive ignition system to the MCC engine. He provided design of the computer module to achieve correct timing advance and also provided operational check out support.

George Lewis -

Assisted in preparing the final draft of all technical progress and fiscal reports. Also provided much pre-award customer interface effort required to help acquire the grant.

Janet Lewis - Secretarial Assistance

Provided typing and transmission of the technical and fiscal correspondence with the Department of Energy.

LuAnn Erickson

Also provided secretarial assistance.

**DATE
FILMED
3/3/92**

I