DOE/CE/15412--T3

FINAL REPORT

on

DOE/CE/15412--T3

DE92 004945

**THE META-LAX METHOD OF
STRESS REDUCTION IN WELDS
DE-FGO1-89CE15412**

to

**JACK AELLEN CE-122
LISA TILLMAN MA-453.2
UNITED STATES DEPARTMENT OF ENERGY**

by

**WELDING CONSULTANTS, INC.
889 NORTH 22nd STREET
COLUMBUS, OH 43219**

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

MASTER

Handwritten signature

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

Table of Contents

1 EXECUTIVE SUMMARY	1
2 INTRODUCTION	5
3 PROGRAM OBJECTIVE	5
4 WORK PLAN	5
5 PROJECT STATUS	5
5.1 Selection and Procurement of Test Materials.	5
5.2 Preparation of Test Assemblies	5
5.3 Test Assembly Identification	6
5.4 Welding of Test Assemblies	7
6 TEST STATUS AND RESULTS	7
6.1 Tensile Test Results	7
6.2 Charpy Impact Test Results	9
6.3 Microstructural Analysis	17
7 CONCLUSION	33
7.1 HAZ Impact Test Conclusions:	33
7.2 Weld Metal Impact Test Conclusions:	33
7.3 Microhardness Testing	34
7.4 Subjective Analysis	34
7.5 Missing Elements	35
8 RECOMMENDATIONS	35
9 APPENDIX I - PHOTOS	36

1 EXECUTIVE SUMMARY

The preliminary project to evaluate the possibility of replacing or reducing thermal stress relief and preheat with sub-resonant vibration has been completed. Bonal Technologies manufactures the Meta-Lax system of sub-resonant vibration for use in industry and has met with success on many occasions. The uses are varied and cross into many industries, including fabrication, foundries, and marine construction. However, the specific engineering or scientific basis for the successes has proven to be very elusive. The purpose of this preliminary evaluation of the Meta-Lax system was to try and determine what is happening when sub-resonant vibration is introduced during and/or after welding operations. The final goal is to determine if this process can replace or reduce thermal stress relief and preheat now required on many welded assemblies. The potential savings could be enormous.

PROCESS PRESENT VALUE

There have been many successes across a range of applications using sub-resonant vibration while welding. This process has reduced distortion, increased production, extended the life cycle of engine blocks, reduced machining on weld overlay applications, and eliminated preheat and thermal stress relief in some applications. The ability to predict when and where it will work is very uncertain, however. Determining what makes this process work could broaden the energy savings.

PROJECT STATUS:

The project includes working with two materials, ASTM A36 carbon steel, and AISI 4140 high strength steel. All work defined by this project has been completed.

THE TESTING:

Testing on both materials includes tension specimens to measure the strength and ductility of the welds, impact testing to screen the notch toughness, and analysis of the grain structure through microhardness testing and comparison of grain structures under a microscope.

A36 RESULTS:

The results of the testing give reason to believe that the sub-resonant vibration process does cause changes in the grain structure similar to those that arise due to thermal stress relief, and produces related changes to the physical performance of the material. However the results, though promising, are inconclusive and have a tendency to be erratic. The grain structure of the A36 material does appear to change in the same manner with sub-resonant vibration as it does with thermal treatment. When comparing the photomicrographs there is a resemblance of grain structure that is decidedly different from the as welded plates. The Charpy impact testing also shows significant differences in the heat affected zone that seem to correlate to these grain structure changes.

The problem is defining the indisputable reasons for these changes. All testing in the project was done on welded assemblies that contained multiple pass welds. The multiple pass procedure is common in industry, so it was used in this project. The test was designed to try to answer the questions with one basic set of test specimens. This, unfortunately, leaves open the possibility of misinterpreting some of the results. When

welding is done in multiple layers, as in this test, ensuing passes will temper the passes that are under, and beside, the new weld beads being added. Are the changes seen in the grain structure directly related to the sub-resonant vibration and thermal stress relief, are they directly related to interpass tempering, or have both of them interacted to cause the changes noted, or are they related to the base metal microstructure? The use of a Scanning Electron Microscope (SEM) may help answer these questions, but that is beyond the scope and funding of this project phase.

4140 RESULTS

Where the data collected from A36 was erratic, in particular the microhardness data, the 4140 was much more consistent. The microhardness readings all followed a recognizable pattern that was typical of a hardness traverse. The sub-resonant vibrated plate showed lower weld metal values than the as welded or the thermally stress relieved in the 4140. where in the A36 the thermal specimens had the lowest values. Both materials had better impact resistance in the heat affected zone (HAZ) with the sub-resonant vibrated samples.

CONCLUSIONS:

There are changes taking place when using the Meta-Lax system that seem to be similar in nature to the changes resulting from thermal stress relief in the A36 materials. However, the possibility exists that these changes could have been impacted by, or caused by, the multiple layer weld joint chosen for this phase of study, or by the base metal differences. It will take further effort to determine what is happening.

It appears that the sub-resonant vibration has more effect on the lower alloy, less refined materials than on the high strength materials. There have been a number of successes in industry that involve iron and steel castings that could be the result of this affect on lower alloys. One area where sub-resonant vibration seems to have a positive effect on both materials is in the improved toughness of the HAZ.

Subjectively there is evidence of differences when welding with the sub-resonant vibration system in operation. The weld metal flows better, there is less grinding required between passes, and there is slightly less filler metal required to complete the weld. Couple this with the objective analysis and there is reason to believe that the Meta-Lax system is causing positive results that seem to be comparable to thermal treatment. This could be the result of better and faster heat transfer occurring when sub-resonant vibration is used while welding.

RECOMMENDATIONS:

The data presently collected indicates that a second more detailed phase of research is appropriate. However, there are further tests that could be done, for much less cost than a full phase two. These tests could generate more positive information on which to base a conclusion about a full scale phase two. For instance, one test would be designed to eliminate the possibility of interpass tempering causing the grain structure changes. Running a weld bead on plate or single pass weld on thin material would eliminate this variable. Another test would be the blind hole drilling method of measuring residual stress

detailed in the enclosed appendix. The easiest thing that could be done is to expand this testing to include SEM work on the samples already prepared for this project. This could provide better direction to plan further studies.

Should it be determined there should be a second long term study it could be approached in three alternate ways:

- 1) A pure research project that investigates in detail the metallurgical changes that are occurring and determines exactly what phenomena causes these changes. This would require state of the art metallurgical equipment and technicians to operate it. This type of effort should be performed by a high tech R&D lab.
- 2) A more practical approach: Identify areas where thermal stress relief or preheating are the only answers to distortion or weld cracking problems, and design a program that deals with those broader issues. This should be done by a lab more in tune with the everyday issues associated with welding, and perhaps developing an interested industry partner.
- 3) Develop a program with elements from 1 and 2 above having the two labs work in conjunction to find a practical way of using or developing what is learned by the R&D labs. Here again it could be beneficial to involve at least one industry partner.

THIS PAGE
INTENTIONALLY
LEFT BLANK

2 INTRODUCTION

When metals are used for the fabrication of components, welding is commonly used to join the individual pieces. However, conditions such as material type or thickness will often dictate the need for thermal treatments, including: preheat, postheat, thermal stress relief, etc. The cost of these thermal treatments, in terms of energy expended, will exceed millions of dollars each year, in this country alone.

The Meta-Lax process, developed by Bonal Technologies, Inc., is reported to be quite effective for accomplishing the desirable results obtained when using the various thermal treatments; however, in doing so, it utilizes only a fraction of the energy required by those high temperature methods.

The energy savings offered by the Meta-Lax process result in a twofold manner. First, the only energy input required is the small amount of 110 volt household current necessary to run an electric motor which drives the vibrator. Secondly, the time required to accomplish the necessary effect is minimal compared to the time and related costs for an equivalent thermally-induced effect.

3 PROGRAM OBJECTIVE

The objective of this program was to study the ability of the Meta-Lax process to replace thermal treatments commonly employed during welded fabrication of metals. This was done following the approved work plan.

4 WORK PLAN

1. Selection and Procurement of Test Materials.
2. Preparation of Test Assemblies
3. Welding of A36 Test Assemblies
4. A36 Examination
5. Welding of High Strength Crack Sensitive Steel
6. High Strength Crack Sensitive Steel Examination
7. Reporting of Study Results

5 PROJECT STATUS

5.1 Selection and Procurement of Test Materials.

The materials were selected, purchased, and work has been completed. The steels selected were A36 carbon steel, and 4140 high strength steel. The welding process used was Flux Cored Arc Welding (FCAW) The welding consumables were AWS E70T-1, for the carbon steel plates, and AWS E110T5-K4 for the high strength test plates.

5.2 Preparation of Test Assemblies

All the test plates have been assembled and were mounted in fixtures as shown in Figure 1.

FIGURE 1: FIXTURING AND APPROXIMATE BEAD SEQUENCE

5.3 Test Assembly Identification

A brief explanation is needed about the numbering system on the attached graphs and charts. There are eight (8) sets of tests, each consisting of three separate test plates. The eight sets are lettered A through H, with three plates within each set, numbered 1 through 3.

Set A represents testing done on as welded A36 plates; set B is sub-resonant vibration conditioned (*vibrated during welding*) and sub-resonant vibration stress relieved (*vibrated after welding*); set C is sub-resonant vibration stress relieved only; set D is thermally stress relieved; and Set E is preheated only.

Set F represents testing as welded 4140 plates, preheated to 200oF; set G is preheated to 200oF, sub-resonant vibration conditioned and stress relieved, and ; set G is preheated to 200oF and thermally stress relieved. It should be pointed out that the 200oF preheat is much lower than recommended for welding 4140. This was done to create conditions more severe then recommended practice, for visual observations while welding. There is additional identification for the microhardness testing done to the 4140, which will be explained in the 4140 results section of this report.

Plate 1 of each set is left in the fixture for 48 hours before cutting apart, plate 2 is left for 14 days, and plate 3 is left in the fixture for a period of 30 days.

Based on this identification process, each test specimen is assigned a number. For instance, specimen A1 T1 is test set A, plate 1, tensile specimen 1 of 2. There are two areas that get the charpy test, the heat affected zone, or HAZ, and the weld metal. There are five specimens of each area. These specimens are identified as CH and CW so that A1 CH4 is the fourth HAZ specimen from set A, plate 1. Plate A1-MH indicates the microhardness specimen. In this test five readings are made in the base metal, HAZ, and weld metal. The Knoop microhardness method was utilized with a load of 500g.

The testing consisted of tensile tests for ultimate strength, charpy V-notch for toughness, microhardness to determine any differences in the hardness, and visual microstructure analysis.

5.4 Welding of Test Assemblies

Welding has been completed on all of the test plates.

6 TEST STATUS AND RESULTS

Testing has been completed on all the samples and the results are as follows:

6.1 Tensile Test Results

The Transverse Tensile test is used to determine basic information on the strength and ductility of the base material in relation to the weld metal deposited. Generally, the weld metal deposit is stronger, therefore the specimen is expected to break in the base metal. This test was conducted to determine if any of the stress relief or conditioning processes adversely altered the expected results. A typical transverse tensile specimen is shown in Figure 2.

FIGURE 2: TYPICAL TENSILE

The tensile testing showed no unusual differences in the A36 test plates, although, it should be noted the thermally stress relieved set, D, produced lower averages, see Table 1. All samples broke in the base metal, with expected results.

TABLE 1.1: RESULTS OF TENSILE TESTS ON A-36 SAMPLES		
SAMPLE NO.	T1 ULTIMATE TENSILE, PSI	T2 ULTIMATE TENSILE, PSI
A36-A1	76,500	76,000
A36-A2	77,000	76,500
A36-A3	77,500	77,000
A36-B1	76,000	75,500
A36-B2	76,000	76,500
A36-B3	76,300	76,600
A36-C1	77,000	76,000
A36-C2	76,500	76,500
A36-C3	76,500	77,000
A36-D1	72,500	72,000
A36-D2	73,500	73,500
A36-D3	67,000	66,500
A36-E1	77,000	76,000
A36-E2	70,000	71,000
A36-E3	70,500	70,500

TABLE 1.2: RESULTS OF TENSILE TESTS ON 4140 SAMPLES		
SAMPLE NO.	T1 ULTIMATE TENSILE, PSI	T2 ULTIMATE TENSILE, PSI
4140-F1	97,500	98,500
4140-F2	96,000	96,000
4140-F3	98,000	97,500
4140-G1	96,000	96,000
4140-G2	97,500	97,000
4140-G3	85,000	88,000
4140-H1	97,000	95,500
4140-H2	94,000	96,000
4140-H3	97,000	97,500

The 4140 tensile specimens also fractured in the base metal, however, there was a noticeable difference in the failure location and manner. The thermally stress relieved plates fracture mode was more ductile in nature, and most of the fractures initiated well into the base metal. Both the as welded and the sub-resonant vibrated exhibited a more brittle fracture mode, and most of these fractures initiated at the HAZ - base metal intersection of the final layer of weld. See Figure 3.

FIGURE 3: REDUCED SECTION TENSILE BREAK MODE

There is a difference in the grain structure when comparing the thermally stress relieved plates, H series, to the as welded, F series, and the sub-resonant vibrated plates, G series. The HAZ in the H series shows areas of tempered martensite while in the other series have areas of untempered martensite. These regions of untempered martensite would explain the more brittle fracture mode seen in the F and G series of tensile tests. See photos F3, G3, and H3M HAZ.

6.2 Charpy Impact Test Results

The Charpy Impact test is usually used as a screening test for evaluating toughness changes in the material as a result of physical changes in the grain structure and size. In this program these changes would be the result of the welding operations that were conducted. The method of testing is to prepare a specimen by machining and notching to exacting tolerance to control the location of the break¹. The specimen is placed on an anvil to prevent movement away from the impact of a hammer on a pendulum that swings through the specimen to be fractured. The amount of energy required to break the specimen is measured in foot pounds and is recorded on a gauge. The higher the energy, the tougher the material. See Figure 4.

FIGURE 4: CHARPY V-NOTCH EQUIPMENT ARRANGEMENT

¹ Specimen prepared in accordance with ASTM E23

Impact tests were done on the heat-affected zone (HAZ) and the weld metal of all the samples. Each plate had five charpy bars machined from the weld metal and the HAZ. As noted earlier, each variation of treatment had three plates, numbered 1, 2, and 3. The only difference between these three was the amount of time left in the welding fixture. Plates numbered 1 were cut apart after 2 days, plate 2 after 14 days, and plate 3 after 30 days. The purpose was to determine if "curing" caused any changes. There were no conclusive differences noted², so for purposes of comparison all three were considered the same.

The charpy testing shows differences in the heat-affected zone samples of the A36 steel. The differences in the A36 weld metal were apparent but less remarkable, except for the thermally heat treated sample.

Table 2 lists the results of the tests on the A36 weld metal, Figure 5 graphically shows the results. There is a pattern, in that the plates that had any treatment performed during or after welding had lower impact values than specimen A plates. Using specimen A, the as welded plates, as the basis for comparison, test specimen B, sub-resonant vibrated during and after welding, had results that averaged 8% lower than specimen A. Specimen C, sub-resonant vibrated after welding only, showed an average 10% reduction from specimen A. Specimen D, thermally stress relieved, averaged a very substantial 38% reduction from the as welded specimen, A. Specimen E, preheated only, averaged 13% lower than specimen A. As noted, the thermally stress relieved specimens are much lower. Depending on the design requirements, this reduction in the toughness of the weld metal could be cause for concern. The testing and evaluation techniques of this study cannot explain this substantial loss in impact resistance. There is a way to determine why this reduction occurred, *Scanning Electron Microscopy, (SEM)*, but it is beyond the scope, and financing, of this phase of the study.

² There could be variations in hydrogen diffusion as a result of the "cure" but that is not part of this test. Should there be further study, this should be considered as part of the study.

TABLE 2: A36 WELD METAL CHARPY TEST RESULTS IN Ft. lbs @ -20oF										
SPECIMEN	A1/A3	AVG	B1/B3	AVG	C1/C3	AVG	D1/D3	AVG	E1/E3	AVG
x1-W1	46.2	41.84	34	36.24	40.1	44.36	24	26	45	40.2
x1-W2	37.7		34.7		47.5		22		41	
x1-W3	39.5		36		46		26.5		28.5	
x1-W4	41.9		35.5		42		28.5		43.5	
x1-W5	43.9		41		46.2		29		43	
x2-W1	44	43.9	35	39.3	29	33.6	28.5	28.5	33	33.7
x2-W2	44.5		45		33		34.5		33.5	
x2-W3	46		38.5		40		27		30.5	
x2-W4	44.5		43		35		29		33	
x2-W5	40.5		35		31		23.5		38.5	
x3-W1	36	36.3	37.5	37.2	30.5	31.7	19.5	21.5	30.5	32.2
x3-W2	34.5		36		31.5		21		33.5	
x3-W3	36.5		39		32.5		19		30	
x3-W4	37		39		33		21		36	
x3-W5	37.5		34.5		31		27		31	
Average	40.7		37.6		36.6		25.3		35.4

FIGURE 5: AVERAGED A36 WELD METAL CHARPY TEST RESULTS

TABLE 3: A36 HAZ CHARPY TEST RESULTS in Ft. lbs. @ -20o F										
SPECIMEN	A1/A3	AVG	B1/B3	AVG	C1/C3	AVG	D1/D3	AVG	E1/E3	AVG
x1-H1	8	6.3	4	4.9	10	11.2	5	5.4	9	8
x1-H2	6.5		4		12		5		9	
x1-H3	5.5		7		15.5		5		9	
x1-H4	5.5		4		11		6		9	
x1-H5	6		5.5		7.5		6		6.5	
x2-H1	6	5.6	10.5	10.4	4.5	5.2	8	10	5.5	5.6
x2-H2	6		9.5		5		8		7	
x2-H3	7		9		5		13		5	
x2-H4	4		12		6		11		4.5	
x2-H5	5		11		5.5		10		5	
x3-H1	5.5	6.4	11	11.2	12	12	16	14.1	6.5	6.1
x3-H2	7		12		11		14.5		6	
x3-H3	6.5		12		11		16.5		6.5	
x3-H4	5.5		10.5		11.5		13		6.5	
x3-H5	7.5		10.5		14.5		10.5		5	
Average	6.1		8.8		9.6		9.8		6.7	
			44%		56%		61		10%

FIGURE 6: AVERAGED A36 HAZ CHARPY TEST RESULTS

Table 3 has the results of the impact testing on the A36 HAZ. These results give much stronger indications of changes in the properties of specimens B, C, and D. Again all 15 were averaged. This time there was also a pattern, all the results were higher than the as welded specimens. Test specimen B, sub-resonant vibrated during and after welding, had results that averaged 44% higher than specimen A, no treatment. Specimen C, sub-resonant vibrated after welding only, showed an average 56% increase from specimen A. Specimen D, thermally stress relieved, showed a 61% increase from the as welded specimen. Specimen E, preheated only, averaged 10% higher than specimen A. The difference between the sub-resonant vibrated and thermally treated specimens, in the worst case, was only 10% while the preheated only specimens, E, were little changed from specimen A.

There were some unusual results in three of the A36 test specimens. Specimen B, Plate 1, specimen C, plate 2, and specimen D, plate 1 had values that were inconsistent with the other two plates in each set. These were significantly lower in each case. They are highlighted by shading in Table 3. Further evaluation of these samples using a microscope indicated that all of these tests fractured principally in the base metal. This can occur in V-groove joint preparations because of the shape of the HAZ. When charpy bars are machined, the location of the HAZ is determined by etching the bars, and the notch machined. Nevertheless, if the shape of the HAZ is irregular and the break starts toward the base or weld metal, the break can occur primarily in the wrong area. Figure 7 illustrates how this can happen.

FIGURE 7: CHARPY V-NOTCH PROBLEM

For this reason the averages were calculated using only two sets of data and again comparing the results. The differences between the as-welded and preheated plates, when compared to the sub-resonant vibration and thermally stress relieved plates were even greater. Plate B was 69% higher than A, C was 81% higher, and D was 87% higher.

When matching the sub-resonant vibrated plates to the thermally relieved, differences existed, but they do not approach the range seen in the first comparison. The difference between specimen B and D was 10%, and between C and D, only 3%.

The results of the Charpy testing on the 4140 materials was not consistent with the results of the A36 materials. In fact the test data for the weld metal impacts did a complete reversal. Table 4 has the results tabulated. Where there was little significant difference in the weld metal impact values in the A36, the 15 sub-resonant vibrated specimens of the 4140 weld metal averaged 39% lower than the as welded specimens, and the thermally stress relieved only averaged 5% better than the as welded tests. There is a tolerance of ± 3 ft. lbs. at the high range exhibited by the F and H samples so this 5% is probably meaningless. Taking away the high and low of each set of five, to balance the tolerance error, these differences remain about the same.

This difference may be explained by microstructure analysis. There are regions of what may be an alloy carbide observed in the weld metal of the sub-resonant vibrated samples, G, that could result in the lower impact resistance. These are not seen in the F and H specimens. See photos F3, G3, and H3M WELD. Why these are present in the G series and not in the others can only be theorized with the degree of work completed in this initial investigation. One possibility is a difference in the base materials.

Another possibility is the added energy from the sub-resonant vibration causes more excited movement of the molecules. This migration then allows them to come into contact with the carbon atoms more frequently, thus causing more rapid nucleation of the alloy molecules with the carbon molecules. This would create the alloy carbides and also bring about faster cooling. These reactions could result in the lower impact values noted in the sub-resonant vibrated specimens. This is pure conjecture at this point, but if in fact this type of phenomenon is occurring, quantifying it should be part of any further work on this process. It could lead to controlling the process and creating more predictable results.

TABLE 4: 4140 WELD METAL CHARPY TEST RESULTS (Ft. lbs @ -20oF)						
SPECIMEN	F1/F3	AVG	G1/G3	AVG	H1/H3	AVG
x1-W1	64	62.5	25	30.0	59	59.8
x1-W2	62		27		58	
x1-W3	61.5		30		56	
x1-W4	64.5		32		62	
x1-W5	60.5		36		64	
x2-W1	56	58.3	34	37.2	60	59.8
x2-W2	61		36		65	
x2-W3	60		39		53	
x2-W4	55.5		37		59	
x2-W5	59		40		62	
x3-W1	61	55.8	39	39.4	61	66.4
x3-W2	55		42		66	
x3-W3	57.5		38		66	
x3-W4	56		39		68	
x3-W5	49.5		39		71	
Average	58.7		35.5			62
			39%			6%

TEST PLATES F 1, 2, & 3 TO H 1, 2, & 3

FIGURE 8: AVERAGED 4140 WELD METAL CHARPY TEST RESULTS

The heat affected zone impact results have the same trend as the tests from the A36, but not quite as significant. Again the sub-resonant vibrated specimens were higher than the as welded and the thermally stress relieved. The 15 specimen average of the vibrated plates is 25% better than the as welded and 43% better than the thermally stress

relieved. Taking away the high and low of each set of five, to balance the tolerance error, these differences show the G series 39% better than the F series and 31% better than the H series. The as welded plates, F, exhibit 7% better values than the thermally stress relieved, not a very remarkable difference. Table 5 tabulates the results.

TABLE 5: 4140 HAZ CHARPY TEST RESULTS (Ft. lbs @ -20oF)						
SPECIMEN	F1/F3	AVG	G1/G3	AVG	H1/H3	AVG
x1-H1	12	14	28	28.8	25	23.8
x1-H2	10.5		32		26	
x1-H3	11		27		25	
x1-H4	11		28		19	
x1-H5	12.5		29		24	
x2-H1	13	16.4	23	24.8	17	15.0
x2-H2	17		26		13	
x2-H3	13.5		24		13	
x2-H4	17		28		14	
x2-H5	21.5		23		18	
x3-H1	36	28.9	21	20.8	9	13.2
x3-H2	40.5		21		11	
x3-H3	25.5		19		14	
x3-H4	20		22		17	
x3-H5	22.5		21		15	
Average	19.7		24.8		17.3	

TEST PLATES F 1, 2, & 3 TO H 1, 2, & 3

FIGURE 9: AVERAGED HEAT AFFECTED ZONE CHARPY TEST RESULTS

6.3 Microstructural Analysis

The microstructure was analyzed by performing microhardness testing and visually comparing the structure of the grains in each plate. When welding takes place there are three distinct zones created by the process: the weld metal, the base metal, and the heat-affected zone (HAZ) between these two areas. These three zones can be visually identified by the differences in grain structure which exist. The microhardness testing and grain structure examination were done to determine if the sub-resonant vibration conditioning, sub-resonant vibration stress relief, thermal stress relief, and preheating resulted in any changes to the two areas of primary concern, the weld metal and HAZ. A traverse from the weld metal, through the HAZ, and into the unaffected base metal was made on all the samples. Figure 10 shows the location of the removed specimen and the location of the hardness readings. The same specimen was used for the visual microstructure comparison. Table 6.1, 6.2, and 6.3 list the results of the microhardness testing on the A36 material. Figure 11 contains all the A36 graphs on one page to make comparison easier, Figures 11 through 13 graphically show the results for each set of A36 data.

FIGURE 10: MICROHARDNESS INDENTATION LOCATION

FIGURE 11: A36 MICROHARDNESS COMPARISON

The microhardness results were very scattered in the A36 test plates. The exception is the A36 C set, the sub-resonant vibration stress relieved set of plates. Figure 11 has the results separated by the different test sets of the A36 material. It is clear that the only set producing any trend or pattern were the plates that were sub-resonant vibration stress relieved, C1, C2, and C3. D1 and D2, thermally stress relieved plates show the same pattern as the C series, but D3 falls out of this pattern. Data from the other three sets is scattered over the range of hardness. This inconsistency may be the result of the multiple pass welding that was used in this test program, or simply from the base metal structure.

When this program was established, a weld joint configuration was selected that would be representative of the welds most commonly used in fabrication. The idea was to come up with a test that could be used to determine many different things. Unfortunately this joint configuration may be the reason there is such a scatter in the microhardness results. When a weld is made on top of or beside another weld, tempering of the one weld by welds that follow is not much different than a heat treatment process. As more weld is deposited on top of the second weld, the first pass sees further tempering, while the second pass receives the first tempering operation. This process continuously changes the grain structure with subsequent layers of weld. What does all of this mean to this research?

It means that in testing such a weldment, it could be possible to find a number of different results depending upon where the sample was taken. In this study all of the A36 samples compared were from approximately the same area, see Figure 10. Therefore, there is reason to believe the data compared from one test plate to another is the same, but this cannot be expressed as absolute. Within the small area where the microhardness tests and grain structure comparisons were made it is possible to obtain different results that may be due to the tempering effects of multiple pass welds, or the grain structure of the base metal. It could also be the result of the sub-resonant vibration and thermal treatments that were used. Finally, and most likely, it could be the effects of all of these variables that account for the results in the microhardness tests.

GRAIN STRUCTURE COMPARISON

When making grain structure comparisons, interpass tempering can make the results inconclusive. The photographs on the following pages show the grain structure for each of the test sets. There is similarity in the grain structure of the A36 base material sub-resonant vibration conditioned and stress relieved test plates, B, the sub-resonant vibration stress relieved plates, C, and the thermally stress relieved plates, D. The structure of these three is different than the structure of the as-welded plates, and the preheated plate is somewhere in-between them. Test plates B, C, and D have a smaller, more refined grain structure than the as-welded plate. This is most noticeable in the heat-affected zone. In particular note the resemblance of photo B2-7 and D2-7. Such a refined structure in the HAZ probably accounts for the significant differences noted in the

Charpy impact results. The average HAZ impact results for these plates were over 80% better than the as welded plates, Photo A2-7. All of the photomicrographs are not included because the results seen here are typical of all test plates done so far.

TABLE 6.1: MICROHARDNESS READINGS WELDS A1 TO E1															
TEST AREA	WELD					HAZ					BASE				
PART NO.	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
A1	108	125	128	128	129	206	174	203	201	187	202	190	184	195	168
B1	128	120	123	124	117	104	114	190	201	175	152	103	111	116	118
C1	181	206	216	226	212	196	215	188	197	195	176	194	192	184	233
D1	220	209	237	231	208	205	179	186	185	198	154	161	177	146	142
E1	220	234	244	229	215	207	224	217	185	203	225	196	193	197	186

FIGURE 12: WELDS A1 TO E1 MICROHARDNESS TRAVERSE

TABLE 6.2: MICROHARDNESS READINGS WELDS A2 TO E2															
TEST AREA	WELD					HAZ					BASE				
PART NO.	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
A2	221	185	237	241	238	238	229	220	205	182	194	186	187	205	221
B2	183	142	144	201	149	195	249	213	229	205	178	187	186	192	176
C2	242	237	226	227	229	219	206	212	158	216	168	184	177	168	192
D2	239	249	230	257	239	167	199	179	184	201	192	191	161	183	178
E2	210	227	242	161	147	134	131	126	116	122	117	119	111	107	103

FIGURE 13: WELDS A2 TO E2 MICROHARDNESS TRAVERSE

TABLE 6.3: MICROHARDNESS READINGS WELDS A3 TO E3															
TEST AREA	WELD					HAZ					BASE				
PART NO.	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
A3	126	146	118	128	145	176	152	128	130	125	97	112	119	105	106
B3	227	225	233	263	208	212	164	214	182	202	219	225	183	209	174
C3	226	263	233	241	226	209	203	188	220	219	203	201	213	170	230
D3	148	153	153	164	154	249	154	155	150	156	129	174	112	159	142
E3	227	241	234	244	275	158	159	116	145	212	186	214	171	186	158

FIGURE 14: WELDS A3 TO E3 MICROHARDNESS TRAVERSE

THIS PAGE
INTENTIONALLY
LEFT BLANK

FIGURE 15: 4140 MICROHARDNESS COMPARISON

As stated earlier there is a different identification system for the 4140 microhardness samples. Due to the inconsistent results of the A36 it was decided that taking two sets of microhardness from the 4140 could be beneficial. Therefore one set was taken from the middle of the weld, as in the A36, and a second set was made on the final pass made on the cap, or surface, of the test plates. Figure 15 has the two sets of data for each series positioned side by side. Those with a C designation were taken at the cap or final weld, those with an M, from the middle of the weld. Notice that the cap of the as welded, F1C to F3C, and the cap of the sub-resonant vibration treated, G1C to G3C, reveal the typical bell shaped pattern of a harder HAZ. The cap from the thermally stress relieved set does not display this pattern. Another observation that can be made, the hardness traverse taken from the middle of all of the samples indicates that the interpass tempering of subsequent weld beads has the same effect on hardness as the thermal stress relief operation.

The microhardness results for the 4140 were much different than that of the A36. The obvious, and expected result, are the harder values. The other thing noticeably different is the relative consistency of the readings between the plates within each series and between each series taken from the middle of the weld as shown in Figure 10. Figure 15 has six graphs, each comparing the 3 specimens from the same series, ie F1 to F3 etc.. Figures 15 to 21 have graphs that compare one series to another, ie F1 to G1 to H1 etc.. Looking at these charts makes it very evident that there is a predictable pattern to the hardness relationships that only existed in one case with the A36 material.

TABLE 7.1: MICROHARDNESS READINGS WELDS F1M TO H1M															
TEST AREA	WELD					HAZ					BASE METAL				
PART NO.	-.100	-.075	-.050	-.025	.000	.010	.020	.030	.040	.050	.075	.100	.125	.150	.175
F1M	269	289	272	263	340	358	254	261	249	221	197	202	207	173	179
G1M	282	291	299	278	290	271	291	298	287	228	192	203	205	205	207
H1M	281	287	294	300	311	375	302	298	235	217	203	209	207	209	209

FIGURE 16: WELDS F1M TO H1M MICROHARDNESS TRAVERSE

TABLE 7.2: MICROHARDNESS READINGS WELDS F2M TO H2M															
TEST AREA	WELD					HAZ					BASE METAL				
PART NO.	-.100	-.075	-.050	-.025	.000	.010	.020	.030	.040	.050	.075	.100	.125	.150	.175
F2M	271	262	237	252	287	357	336	300	248	244	221	201	215	211	215
G2M	286	276	278	310	269	335	297	273	219	201	199	186	177	182	194
H2M	303	319	308	314	326	396	329	345	293	265	210	210	210	209	207

FIGURE 17: WELDS F2M TO H2M MICROHARDNESS TRAVERSE

TABLE 7.3: MICROHARDNESS READINGS WELDS F3M TO H3M															
TEST AREA	WELD					HAZ					BASE METAL				
PART NO.	-.100	-.075	-.050	-.025	.000	.010	.020	.030	.040	.050	.075	.100	.125	.150	.175
F3M	273	256	290	281	311	388	355	319	361	280	238	210	205	212	205
G3M	263	264	270	323	278	286	282	284	269	230	170	198	179	189	205
H3M	309	319	314	310	294	392	380	339	301	252	215	215	223	223	221

FIGURE 18: WELDS F3M TO H3M MICROHARDNESS TRAVERSE

TABLE 7.4: MICROHARDNESS READINGS WELDS F1C TO H1C															
TEST AREA	WELD					HAZ							BASE METAL		
PART NO.	-.100	-.075	-.050	-.025	.000	.010	.020	.030	.040	.050	.075	.100	.125	.150	.175
F1C	286	300	298	275	289	506	550	541	481	517	343	255	209	208	202
G1C	315	298	317	335	316	453	527	522	524	486	486	295	283	210	211
H1C	275	275	281	277	277	328	349	343	331	337	259	220	191	193	195

FIGURE 19: WELDS F1C TO H1C MICROHARDNESS TRAVERSE

TABLE 7.5: MICROHARDNESS READINGS WELDS F2C TO H2C															
TEST AREA	WELD					HAZ							BASE METAL		
PART NO.	-.100	-.075	-.050	-.025	.000	.010	.020	.030	.040	.050	.075	.100	.125	.150	.175
F2C	289	290	275	289	289	525	511	473	489	416	305	252	209	199	199
G2C	338	342	345	329	354	536	536	537	534	514	386	278	220	204	204
H2C	233	258	259	257	329	322	351	309	345	321	333	257	225	185	198

FIGURE 20: WELDS F2C TO H2C MICROHARDNESS TRAVERSE

TABLE 7.6: MICROHARDNESS READINGS WELDS F3C TO H3C															
TEST AREA	WELD					HAZ							BASE METAL		
PART NO.	-.100	-.075	-.050	-.025	.000	.010	.020	.030	.040	.050	.075	.100	.125	.150	.175
F3C	291	281	284	275	278	496	515	490	529	439	413	287	223	210	213
G3C	328	326	326	324	344	517	507	496	477	495	328	256	203	204	212
H3C	179	173	243	251	261	248	316	292	325	281	215	186	187	202	188

FIGURE 21: WELDS F3C TO H3C MICROHARDNESS TRAVERSE

THIS PAGE
INTENTIONALLY
LEFT BLANK

7 CONCLUSION

The results of this preliminary work indicate that sub-resonant vibration could create metallurgical changes similar to thermal stress relief, particularly in low alloy materials.

However, the results of the testing are widely scattered and variable in the case of the lower alloy A36 steel, while more consistent in the higher alloy 4140. There is uncertainty about the causes of some of the changes noted, in particular the grain structure changes and microhardness readings of the A36. The choice of multiple pass weldments makes it difficult to pinpoint the exact reason, or reasons, for the changes. When a weld is made on top of or beside another weld there is a tempering of the first weld bead that is little different than a heat treatment process. This can be clearly seen in the 4140 microhardness results, Figure 15. As more weld is laid down the first pass is further tempered, while the second pass receives the first tempering operation. This process continuously changes the grain structure with subsequent layers of weld. This grain structure change is more apparent in the A36 and may be the result of the interbead tempering, the sub-resonant vibration process, or a combination of the two. The inconsistency in most of the A36 microhardness readings appears to be associated with the inconsistency of the base materials. This reasoning is based upon the very constant results observed in the 4140 material. The following paragraphs make assumptions based on the results of the individual tests.

7.1 HAZ Impact Test Conclusions:

In spite of the doubts noted, there is evidence that the Meta-Lax system is performing comparable to the thermal stress relief process on A36 carbon steel. There is measurable improvement, over the as welded condition, in impact resistance of the sub-resonant vibration conditioned/stress relieved plates, the sub-resonant vibration stress relieved plates, and the thermally stress relieved plates. This improvement is most noticeable in the heat affected zone (HAZ). There is, in the order listed above, a 69%, 81%, and an 87% improvement over the as welded plates. The preheated plates showed some improvement, but remained close to the results of the as welded condition. In the 4140 plates this improvement in the HAZ impact resistance is also apparent in the sub-resonant vibrated plate, but it is very hard to determine a reason. The improvement in the A36 HAZ impact resistance can be linked to the similarity in the grain structure of the three test sets. They all have a smaller, more refined grain structure, when compared to the as welded test plates. This type of structure would have the effect of increasing the impact resistance. In the 4140 test plates the sub-resonant vibrated specimen HAZ, G, is also considerably improved over the as welded, F, and the thermally stress relieved specimen, H. There is little difference between F and H. Like the A36 there is a 39% improvement in the G specimens, but an obvious reason for it is not apparent in the grain structure. It will take SEM or TEM work to determine why this occurred.

7.2 Weld Metal Impact Test Conclusions:

There are very different results between the low alloy A36 and the 4140 when analyzing the results of the impact testing in the weld metal. The A36 test plates show little difference in the weld metal Charpys. The only noticeable result was a reduction in the

impact resistance of the thermally stress relieved samples. The 4140 results were much more apparent and moved in the opposite direction as the A36. The as welded and thermally treated 4140 plates were about the same, while the sub-resonant vibrated plates were approximately 40% lower than the other two. Looking at the grain structure, there appear to be alloy carbides that could account for this reduction, as explained earlier. What caused this reduction for sure is unknown, but it does lead to the conclusion that sub-resonant vibration while welding does effect the weld metal. It is interesting to note that the thermal stress relief had the same effect to the A36 that the sub-resonant vibration had to the 4140, that is a reduction in weld metal impact results. There needs to be further work to understand what is occurring. Further work should also require all-weld-metal tensile testing to see if the reduced impact specimens reflect improved elongation.

7.3 Microhardness Testing

There is also indication of a relationship between the sub-resonant vibration stress relieved and the thermally stress relieved plates in the microhardness pattern of the A36. These two test sets are the only ones showing any consistency within the three plate sets tested, although one of the thermally stress relieved plates is out of line with the other two.

The 4140, on the other hand is very consistent across all of the plates. This indicates that the sub-resonant vibration process may have a stabilizing effect on the low alloy materials, where the base metal microstructure and chemical make-up are more random than in the higher alloys, and have less effect on higher quality, better controlled materials.

7.4 Subjective Analysis

Subjectively there is also evidence that Meta-Lax conditioning during the welding improves the flow of the weld metal. It was noted during welding that the sub-resonant vibration conditioned test plates required less grinding and slightly less filler metal to complete the weld. This was especially true during the welding of the 4140 plates.

The 4140 plates not sub-resonant vibrated during welding were cracking at the weld crater at the end of each pass made. This did not occur when sub-resonant vibrating. This could be very significant when welding high strength materials where there are weld starts and stops in the middle of a welded assembly. Failure to see and repair such cracks before further welding could lead to serious problems that would not be corrected by thermal stress relief.

Another observation made on sub-resonant vibrated assemblies is that it was not necessary to change welding parameters when moving from a flat position weld to welds out-of-position. This is unusual, and further investigation about using higher heat inputs while sub-resonant vibrating should be considered. One explanation of this could be

better, more uniform heat transfer when sub-resonant vibration is present during welding, and at the same time more rapid cooling, that allows the weld metal to solidify quicker.

7.5 Missing Elements

There are two areas of importance to the welding industry where, unfortunately, no conclusions can be made. These areas are the effects of sub-resonant vibration on actual relief of stress built up by the welding, and the effects of sub-resonant vibration on distortion while welding.

It was hoped that the information obtained from the physical testing would allow some projections as to the residual stress relieving abilities of sub-resonant vibration while welding. This did not happen. The data collected is too erratic to draw any positive conclusions about the stress relieving properties of sub-resonant vibration. Attached to this report is an appendix that describes a method of measuring the residual stress present in a material. Any further research or study of this process should include this or some other type of stress measurement. As in this experiment, plates should be fully restrained, multipass welded, and then have this measurement made before any other testing is done.

The second area where no data was collected is the measurement of the distortion control ability of sub-resonant vibration when welding. It was an area that data was to be developed by measuring the amount of movement observed when the restraints were removed. Quite unexpectedly, there was no significant movement measured on any of the samples after restraint removal. Distortion is presently controlled through the use of preheat, prebending, and fixturing. All of these are quite expensive and not always predictable. If sub-resonant vibration can control distortion it could be very cost effective for the production process. Any further testing should include the measuring of the distortion of multipass welds that are free of restraint, allowed to move at will.

8 RECOMMENDATIONS

There is enough evidence from the testing done to argue for further evaluation of the effects of sub-resonant vibration during and after welding. The potential savings in energy from reducing or eliminating preheating and post weld thermal stress relief is enormous. Listed below are four possible alternative future approaches that must be considered at this time:

1. Stopping the effort is always a choice to be considered. The data collected leaves open the possibility that there is potential for sub-resonant vibration, particularly in the lower alloy steels. However, at best this data is sketchy and inconsistent. Before making this decision, it is recommended that some preliminary SEM be done on the existing samples. This could help a great deal in the decision making process.

2. Develop a long term research project that will include very detailed analysis of the grain structure with SEM and TEM. This must include all known variables, a wide range of materials including non-ferrous, and test multiple welding procedures, fixturing etc.. This would be best done by a sophisticated and well equipped research lab that has the ability to structure the testing required, perform the testing, have the proper equipment and the technicians to properly use it, be capable of quantitative metallurgy and statistical analysis. It would not be unreasonable to expect such a project to take two or three years.

3. Develop a project designed for a more practical evaluation of the process. This type of project would be more concerned with identifying those real world problems now being resolved with preheating and/or thermal stress relief. Based on this then develop a program designed to determine if the sub-resonant vibration process can reduce or eliminate the need for the thermal processes. This work should include the residual stress measurements, distortion control testing, determination of the velocities and amplitudes that have positive effects, computer analysis of sound transfer through different sections to measure changes in the velocities and amplitudes as they relate to shape and size, and evaluate the effects of higher heat inputs from higher welding amps and volts. This work should be done by a lab accustomed to practical industry requirements and perhaps in concert with an industry partner. With energy savings that could be enormous if the sub-resonant vibration process could be clarified and controlled, it is difficult to ignore the potential of the process.

4. The fourth approach to future work is a project that combine the pure research of number 2 and the practical approach of 3. This project should combine the strengths and abilities of the two types of labs with an industry partner and could go a long way toward answering the questions that exist about sub-resonant vibration technology.

This final report completes the project.

Submitted 12/91	Project Manager
	Lance Soisson
Approved 12/91	Project Director
	Richard Holdren

A3 HAZ 600X #1

B3 HAZ 600X #1

D3 #1 600X HAZ

F1 #7 602X HAZ

END

**DATE
FILMED**

2 / 27 / 92