390-48-28 (3)
4-8-85

Energy

**F
O
S
S
I
L**

Dr. 0941-5

DOE/BC/10033-9-Vol.3
(DE85007363)

**CHEM2D: A TWO-DIMENSIONAL, THREE-PHASE, NINE-
COMPONENT CHEMICAL FLOOD SIMULATOR**
Volume III: CHEM2D Appendices and Phase Behavior Calculation
Program

By
John R. Fanchi

April 1985
Date Published

Work Performed Under Contract No. AC19-80BC10033

Keplinger & Associates, Inc.
Tulsa, Oklahoma

MASTER

Technical Information Center
Office of Scientific and Technical Information
United States Department of Energy

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

This report has been reproduced directly from the best available copy.

Available from the National Technical Information Service, U. S. Department of Commerce, Springfield, Virginia 22161.

Price: Printed Copy A03
Microfiche A01

Codes are used for pricing all publications. The code is determined by the number of pages in the publication. Information pertaining to the pricing codes can be found in the current issues of the following publications, which are generally available in most libraries: *Energy Research Abstracts (ERA)*; *Government Reports Announcements and Index (GRA and I)*; *Scientific and Technical Abstract Reports (STAR)*; and publication NTIS-PR-360 available from NTIS at the above address.

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency Thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

DISCLAIMER

Portions of this document may be illegible in electronic image products. Images are produced from the best available original document.

CHEM2D:

A TWO-DIMENSIONAL, THREE-PHASE, NINE-COMPONENT
CHEMICAL FLOOD SIMULATOR

VOLUME III: CHEM2D APPENDICES AND PHASE BEHAVIOR CALCULATION PROGRAM

By

JOHN R. FANCHI
KEPLINGER AND ASSOCIATES, INC.
TULSA, OKLAHOMA

FRED W. BURTCH, TECHNICAL PROJECT OFFICER
BARTLESVILLE ENERGY TECHNOLOGY CENTER
BARTLESVILLE, OKLAHOMA

Work Performed for the Department of Energy
Under Contract No. DE-AC19-80BC10033

FEBRUARY, 1984

VOLUME III: APPENDICES AND PHASE BEHAVIOR CALCULATION PROGRAM

TABLE OF CONTENTS

	<u>Page No.</u>
APPENDIX A. Cation Exchange	A.1.0
APPENDIX B.1. Calculation of Phase Diagrams	B.1.0
B.1.1. Parameter Estimation	B.3.0
B.1.2. Type III	B.6.0
B.1.2.1. Left Node	B.6.0
B.1.2.2. Right Node	B.8.0
APPENDIX B.2. Summary of Calculation Procedure	B.9.0
APPENDIX C. PHASE: A Ternary Phase Calculation Program	C.1.0
C.1. PHASE Program Code	
C.2. An Example PHASE Run	

APPENDIX A. Cation Exchange*

A cation exchange model presented by Hirasaki (1982) is applied and extended to multiple phases. This model calculates the transport of sodium and calcium through porous media in the presence of clays and surfactant. The exchange of cation with both clays and the micelles is assumed to be entirely due to electrostatic association. The cation exchange is modelled as follows:

Calcium C_6 and sodium C_9 exchange by mass action**

$$\frac{\bar{C}_9^2}{\bar{C}_6} = \beta^c Q_v \frac{(C_{9l}^0)^2}{C_{6l}^0} \quad \text{for clay} \quad (\text{A.1})$$

$$\frac{(C_{9l}^s)^2}{C_{6l}^s} = \beta^s C_{3l} \frac{(C_{9l}^0)^2}{C_{6l}^0} \quad \text{for micelles} \quad (\text{A.2})$$

$$l = 1, 2, 3$$

where Q_v is cation exchange capacity, and the superscripts 0, s represent free ions and ions associated with surfactant (counter-ions on micelle). It is assumed that the adsorbed surfactant ($\hat{C}_3$) associates sodium ($\hat{C}_9^s$) and calcium ($\hat{C}_6^s$) in the same way as the micelles, e.g.

$$\frac{\hat{C}_9^s}{\hat{C}_6^s} = \frac{C_{9l}^s}{C_{6l}^s} \quad (\text{A.3})$$

* Except for minor editorial changes, this Appendix is a reproduction of C. H. Hong's Ph.D. Dissertation, Section 5.10 (1982).

** All concentrations are expressed in milliequivalents/gram for the cation exchange calculations. The concentrations are converted to volume fractions when the cation exchange calculations are completed.

From electrical neutrality, we obtain the following equations

$$C_{6\ell}^s + C_{9\ell}^s = C_{3\ell} \quad (\text{A.4})$$

$$C_{6\ell}^0 + C_{9\ell}^0 = C_{5\ell} \quad (\text{A.5})$$

$$\hat{C}_6^s + \hat{C}_9^s = \hat{C}_3 \quad (\text{A.6})$$

$$\bar{C}_6 + \bar{C}_9 = Q_v \quad (\text{A.7})$$

$$\ell = 1, 2, 3$$

The material balance equation for calcium C_6 is

$$\bar{C}_6 = \sum_{\ell=1}^3 S_{\ell} C_{6\ell} + \bar{C}_6 + \hat{C}_6^s = \sum_{\ell=1}^3 S_{\ell} (C_{6\ell}^0 + C_{6\ell}^s) + \bar{C}_6 + \hat{C}_6^s \quad (\text{A.8})$$

We also assume

$$C_{53} = \left(\frac{C_5}{C_1} \right) C_{13} \quad (\text{A.9})$$

$$C_{61}^0 = \left(\frac{C_{63}^0}{C_{13}} \right) C_{11} \quad (\text{A.10})$$

$$C_{62}^0 = \left(\frac{C_{63}^0}{C_{13}} \right) C_{12} \quad (\text{A.11})$$

$$C_{61}^s = \left(\frac{C_{63}^s}{C_{13}} \right) C_{31} \quad (\text{A.12})$$

$$C_{62}^s = \left(\frac{C_{63}^s}{C_{33}} \right) C_{32} \quad (\text{A.13})$$

$$\hat{C}_6^s = \left(\frac{C_{63}^s}{C_{33}} \right) \hat{C}_3 \quad (\text{A.14})$$

Given $S_1, S_2, S_3, C_{53}, C_{11}, C_{12}, C_{13}, C_{31}, C_{32}, C_{33}, \hat{C}_3$ from the old time step value, we calculate $C_{63}^0, \bar{C}_6, \hat{C}_6^s, C_{63}^s$ for the new time step as follows.

A function of C_{63}^0 is defined as

$$F(C_{63}^0) = \sum_{l=1}^3 S_l (C_{6l}^0 + C_{6l}^s) + \bar{C}_6 + \hat{C}_6^s - \bar{C}_{6N} \quad (\text{A.15})$$

where C_{6N} is the new time step value just calculated by the convection-diffusion equations (explicit solution). C_6 and C_6^s are calculated by equations (A.1) through (A.7)

$$\bar{C}_6 = \frac{1}{2} \left(2Q_s + R_{96}^c - \sqrt{(R_{96}^c)^2 + 4R_{96}^c Q_v} \right) \quad (\text{A.16})$$

where

$$R_{96}^c = \beta^c Q_v \frac{(C_{53} - C_{63}^0)^2}{C_{63}^0} \quad (\text{A.17})$$

$$C_{63}^s = \frac{1}{2} \left(2C_{33} + R_{96}^s - \sqrt{(R_{96}^s)^2 + 4R_{96}^s C_{33}} \right) \quad (\text{A.18})$$

where

$$R_{96}^s = \beta^s C_{33} \frac{(C_{33} - C_{63}^0)^2}{C_{63}^0} \quad (\text{A.19})$$

The Newton-Raphson iteration method is used to solve the nonlinear equation

$$F(C_{63}^0) = 0 \quad (A.20)$$

We then calculate C_{6l} , C_{9l} , $\bar{C}_6$, $\bar{C}_9$, $\hat{C}_6$, and $\hat{C}_9$ at the new time step by equations (A.1) through (A.3).

The iteration converges when $F(C_{63}^0)$ is less than a specified tolerance where C_{3l} , S_l , $\hat{C}_3$ are considered known. However, strictly speaking, the phase behavior routine should be in the loop because the new value of C_{6l} obviously strongly affects C_{3l} , S_l , $\hat{C}_3$. One could iterate, calling one routine, then the other, successively until they converge. This is not done at present.

APPENDIX B.1. Calculation of Phase Diagrams*

We can qualitatively depict the phase diagram as shown in Figure B.1. All features vary in a continuous way with an effective ionic strength ("salinity"), C_{SE} . This includes specifically the binodal curve, tie lines, plait points (left P_L and right P_R) and invariant point, M. We make the basic assumption that the binodal curve is the same function of C_{SE} for all three types of diagrams, so that all that distinguishes the Type III diagrams is the three phase triangle located by the Point M, and the left and right node tie lines.

The basic idea is to model the diagrams with modified Hand equations, which in turn are based upon the observation that the phase boundary (binodal curve) and distribution curve (tie lines) plot as straight lines on log plots as shown on Figure B.2.

For either Type II(-) or Type II(+) we have only two phases below the binodal curve. The two basic equations are

$$\frac{C_{3\ell}}{C_{2\ell}} = A \left(\frac{C_{3\ell}}{C_{1\ell}} \right)^B \quad (B.1)$$

$\ell = 1, 2$

$$\frac{C_{32}}{C_{22}} = E \left(\frac{C_{31}}{C_{11}} \right)^F \quad (B.2)$$

These are equations for the binodal curve and distribution curve, respectively. The parameters A, B, E, and F must be estimated as a function of C_{SE} as discussed below. We also know that

* Except for minor editorial changes, this Appendix is a reproduction of C. H. Hong's Ph.D. Dissertation, Appendix F (1982).

$$C_{11} + C_{21} + C_{31} = 1 \quad (\text{B.3})$$

$$C_{12} + C_{22} + C_{32} = 1 \quad (\text{B.4})$$

Equation (B.1) applies to either phase 1 or phase 2, i.e., either to the left or right of the plait point. Thus, we have five equations in six unknowns (the $C_{k\ell}$, $k = 1, 2, 3$, $\ell = 1, 2$). So we have one degree of freedom, as expected. We can take any one concentration, such as C_{21} , and give it values between 0 and 1 and sweep out the phase diagram. We do this explicitly later, but for now we take a ratio defined below as our one degree of freedom.

$$\text{Let } R_{ij}^{\ell} = C_{i\ell} / C_{j\ell} \quad (\text{B.5})$$

Let R_{31}^1 be taken as independent. The following set of equations then yield the $C_{k\ell}$ without iteration:

$$R_{32}^1 = A(R_{31}^1)^B \quad (\text{B.6})$$

$$C_{11} = \frac{R_{32}^1}{R_{31}^1 + R_{31}^1 R_{32}^1 + R_{32}^1} \quad (\text{B.7})$$

$$C_{21} = 1 - (R_{31}^1 + 1)C_{11} \quad (\text{B.8})$$

$$C_{31} = 1 - C_{11} - C_{21} \quad (\text{B.9})$$

$$R_{32} = C(R_{31}^1)^F \quad (\text{B.10})$$

$$C_{12} = \frac{R_{32}^2}{R_{31}^2 + R_{31}^2 R_{32}^2 + R_{32}^2} \quad (\text{B.11})$$

$$C_{22} = 1 - (R_{31}^2 + 1)C_{12} \quad (\text{B.12})$$

$$C_{32} = 1 - C_{12} - C_{22} \quad (\text{B.13})$$

R_{31}^1 varies between zero and infinity.

B.1.1. Parameter Estimation

5 The basic input is the set of three parameters C_{3MAX0} , C_{3MAX1} , and C_{3MAX2} . These are physically the maximum in the binodal curve (the "height" of the two phase region) at $C_{SE} = 0, 1$, and 2 , respectively. These are values easily visualized and obtained from even limited phase data and do not vary widely from case to case, so reasonable values can be assumed in the absence of any data (caution: some data are needed to support the assumption that the system fits the qualitative trends depicted, so having some data is highly desirable). The values do matter, however, because the extent of the single phase region directly affects the degree of miscibility. Thus, once again, some data are highly desirable.

We now use this interpolation scheme for A:

$$A_0 = \left(\frac{2 C_{3MAX0}}{1 - C_{3MAX0}} \right)^2 \quad (B.14)$$

$$A_1 = \left(\frac{2 C_{3MAX1}}{1 - C_{3MAX1}} \right)^2 \quad (B.15)$$

$$A_2 = \left(\frac{2 C_{3MAX2}}{1 - C_{3MAX2}} \right)^2 \quad (B.16)$$

$$A = A_0 + (A_1 - A_0) C_{SE} \quad C_{SE} \leq 1 \quad (B.17)$$

$$A = A_1 + (A_2 - A_1)(C_{SE} - 1) \quad C_{SE} \geq 1 \quad (B.18)$$

Recall that C_{SE} is in optimal salinity units (effective salinity divided by optimal effective salinity).

We assume B and F are constants. The most flexible scheme allows B and F to be arbitrary. However, many times the binodal curve is known but the tie lines are not. Thus, we can get B, but not F, from the data available. In such cases, we will take $F = -1/B$ by analogy with those

cases where we do have data, since this relationship tends to hold approximately. Furthermore, many times we do not have enough data to even estimate B properly. In such cases, we take $B = -1$. This gives a symmetrical binodal curve. The deviation of most actual curves from this symmetry is probably not significant. The type of phase diagram (II(-), III, II(+)) and the extent of the single phase region are the most important factors. It seems unlikely that the detailed shape of the curve is significant. Also, recall that since we are dealing with pseudo-ternary diagrams, the curves themselves shift around depending on the exact overall composition (especially with respect to alcohol), so it makes no sense at all to try to describe them in great detail with high precision, even in the rare circumstances when we have the large amount of data required to do so.

Let us return to parameter estimation. We still need E. We estimate E from the location of the plait point. This is done once again because it is a method easy to visualize and apply, and it has a direct physical meaning. Since equations (B.1) and (B.2) must apply at the plait point, denoted by subscript p, we have

$$\frac{C_{3p}}{C_{2p}} = E \left(\frac{C_{3p}}{C_{1p}} \right)^F \quad (B.19)$$

$$\frac{C_{3p}}{C_{2p}} = A \left(\frac{C_{3p}}{C_{1p}} \right)^B \quad (B.20)$$

$$C_{1p} + C_{2p} + C_{3p} = 1 \quad (B.21)$$

Given A, B, and F from above, these equations can be used to calculate E as a function of C_{2p} . For the special case of $B = -1$ and $F = +1$, we calculate all the phase concentrations ($C_{k\ell}$) explicitly. From Equation (B.1) we solve for C_{31} ($\ell = 1$)

$$C_{31} = \frac{1}{2} \left(-AC_{21} + \sqrt{(AC_{21})^2 + 4AC_{21}(1 - C_{21})} \right) \quad (B.22)$$

and

$$C_{11} = 1 - C_{21} - C_{31} \quad (B.23)$$

From equation (B.19), we calculate

$$E = C_{1p}/C_{2p} \quad (B.24)$$

where

$$C_{3p} = \frac{1}{2} \left(-AC_{2p} + \sqrt{(AC_{2p})^2 + 4AC_{2p}(1 - C_{2p})} \right) \quad (B.24a)$$

and

$$C_{1p} = 1 - C_{2p} - C_{3p} \quad (B.24b)$$

Note that C_{2p} is an input parameter.

From equation (B.2), we have

$$C_{32} = h C_{22} \quad (B.25)$$

where

$$h = EC_{31}/C_{11} \quad (B.26)$$

is known. Substituting this into equation (B.1) with $j = 1$ and solving for C_{22}

$$C_{22} = \frac{A}{h^2 + Ah + A} \quad (B.27)$$

then

$$C_{32} = h C_{22} \quad (B.28)$$

and

$$C_{12} = 1 - C_{22} - C_{32} \quad (B.29)$$

We now know all C_{kl} .

The only difference between Type II(-) and II(+) is that for II(-) we input C_{2PR} and for II(+) C_{2PL} . The limits on II(-) are $0 \leq C_{SE} \leq C_{SEL}$ and on II(+) are $C_{SEU} \leq C_{SE} \leq 2$.

In summary, for II(-), we increment C_{SE} up to C_{SEL} and for each C_{SE} we increment C_{21} from 0 to C_{2PR} . The input parameters are C_{3MAX0} , C_{3MAX1} , and C_{2PR}^* . The C_{ij} are calculated from equations (B.22) through (B.29). For II(+), we increment C_{SE} from C_{SEU} to 2.0, and for each C_{SE} , we increment C_{21} from 0 to C_{2PL}^* . The C_{kl} are calculated from the same equations as before.

B.1.2. Type III

For Type III, we must calculate the left node and the right node separately. First, we calculate the invariant point (M) as a function of C_{SE} from

$$C_{2M} = \frac{C_{SE} - C_{SEL}}{C_{SEU} - C_{SEL}} \quad (B.30)$$

$$C_{3M} = \frac{1}{2} \left(-AC_{2M} + \sqrt{(AC_{2M})^2 + 4AC_{2M}(1 - C_{2M})} \right) \quad (B.31)$$

$$C_{1M} = 1 - C_{2M} - C_{3M} \quad (B.32)$$

B.1.2.1. Left Node

The plait point must vary between zero and the II(-) value C_{2PL}^* . By interpolation

$$C_{2PL} = C_{2PL}^* + \frac{C_{2PL}^*}{C_{SEU} - C_{SEL}} (C_{SE} - C_{SEU}) \quad (B.33)$$

We now do a coordinate rotation as shown in Figure B.3. This enables us to apply the Hand equation in the new coordinate system as

$$\frac{C'_{32}}{C'_{22}} = E \frac{C'_{31}}{C'_{11}} \quad (B.34)$$

where

$$C'_{2l} = C_{2l} \sec \theta \quad (\text{B.35})$$

$$C'_{3l} = C_{3l} - C_{2l} \tan \theta \quad (\text{B.36})$$

$$C'_{1l} = 1 - C'_{2l} - C'_{3l} \quad (\text{B.37})$$

Define two parameters α and β as

$$\beta = \sec \theta = \sqrt{C_2^2 + C_{3M}^2} / C_{2M} \quad (\text{B.38})$$

$$\alpha = \tan \theta = C_{3M} / C_{2M} \quad (\text{B.39})$$

Again taking $F = 1$, we calculate E explicitly from

$$E = C'_{1p} / C'_{2p} = \frac{1 - (\beta - \alpha)C_{2p} - C_{3p}}{\beta C_{2p}} \quad (\text{B.40})$$

where

$$C_{2p} = C_{2p1}$$

and C_{1p} and C_{3p} are given by equations (B.24a) and (B.24b) as before. We calculate C_{31} and C_{11} as before and solve equation (B.34) for C_{22}

$$C_{22} = \frac{A}{h'^2 + Ah' + A} \quad (\text{B.41})$$

where

$$h' = \frac{\beta E C'_{31}}{C'_{11}} + \alpha \quad (\text{B.42})$$

and then

$$C_{32} = h' C_{22} \quad (\text{B.43})$$

$$C_{12} = 1 - C_{22} - C_{32} \quad (\text{B.44})$$

We now know all C_{kl} for the left node. We increment C_{21} from zero to C_{2PL} for each C_{SE} as before.

B.1.2.2 Right Node

The process is almost the same as for the left node except we calculate C_{2PR} from

$$C_{2PR} = C_{2PR}^* + \frac{1 - C_{2PR}^*}{C_{SEU} - C_{SEL}} (C_{SE} - C_{SEL}) \quad (B.45)$$

We first calculate C_{32} from

$$C_{32} = \frac{1}{2} \left(-AC_{12} + \sqrt{(AC_{12})^2 + 4AC_{12}(1 - C_{12})} \right) \quad (B.46)$$

and

$$C_{22} = 1 - C_{12} - C_{32} \quad (B.47)$$

Note that C_{12} is incremented rather than C_{21} (this is simply more convenient).

Let

$$h' \equiv \frac{\beta C_{32}'}{E C_{11}'} + \alpha \quad (B.48)$$

then

$$C_{11} = \frac{A}{h'^2 + Ah' + A} \quad (B.49)$$

$$C_{31} = h' C_{11} \quad (B.50)$$

$$C_{21} = 1 - C_{11} - C_{31} \quad (B.51)$$

where

$$\alpha = C_{3M}/C_{1M} \quad (B.52)$$

$$\beta = \sqrt{C_{3M}^2 + C_{1M}^2} / C_{1M} \quad (B.53)$$

$$C'_{1\ell} = \beta C_{1\ell} \quad (B.54)$$

$$C'_{3\ell} = C_{3\ell} - \alpha C_{1\ell} \quad (B.55)$$

$$C'_{2\ell} = 1 - C'_{1\ell} - C'_{3\ell} \quad (B.56)$$

$$E = C'_{1p}/C'_{2p} \quad (B.57)$$

and C'_{1p} and C'_{2p} are calculated using equations (B.54) to (B.56) and (B.24a) and (B.24b). We now know all $C_{k\ell}$ for the right node.

B.2. Summary of Calculation Procedure

I. Given: C_{3MAX1} , C_{3MAX0} , C_{3MAX2} = height of binodal curve when $C_{SE} = 1, 0$, and 2

C_{SEL} , C_{SEU} = minimum and maximum effective salinities for Type III

C_{2PR}^* , C_{2PL}^* = oil coordinate of plait point in Type II(-) and Type II(+) regions

Seven input parameters

II. For $C_{SE} < C_{SEL}$: Type II(-)

1. Calculate parameter A from (B.17)
2. Calculate C_{3PR}^* and C_{1PR}^* from (B.24a) and (B.24b) using C_{2PR}^*
3. Calculate E from (B.24) and C_{1PR}^* and C_{2PR}^*
4. Pick C_{21} , calculate C_{31} and C_{11} from (B.22) and (B.23)
5. Calculate h from (B.26)
6. Calculate C_{22} , C_{32} , C_{12} from (B.27) through (B.29)

III. For $C_{SE} > C_{SEU}$: Type II(+)

1. Calculate parameter A from (B.18)
2. Calculate C_{3PL}^* and C_{1PL}^* from (B.24a) and (B.24b) using C_{2PL}^*
3. Calculate E from (B.24) and C_{1PL}^* and C_{3PL}^*
4. Pick C_{21} , calculate C_{31} and C_{11} from (B.22) and (B.23)
5. Calculate h from (B.26)
6. Calculate C_{22} , C_{32} , C_{12} from (B.27) through (B.29)

IV. For $C_{SEL} < C_{SE} < C_{SEU}$: Type III

1. Calculate C_{2M} from (B.30)
2. Calculate A from (B.17) or (B.18)
3. Calculate C_{3M} and C_{1M} from (B.31) and (B.32)
4. Left Node - Type II(+)
 - a. Calculate α and β from (B.38) and (B.39)
 - b. Calculate C_{2PL} from (B.33)
 - c. Calculate C_{3PL} and C_{1PL} from (B.24a) and (B.24b) using C_{2PL}
 - d. Calculate E from (B.40)
 - e. Pick C_{21} , calculate C_{31} and C_{11} from (B.22) and (B.23)
 - f. Calculate h' from (B.42)
 - g. Calculate C_{32} , C_{12} , and C_{22} from (B.41) through (B.44)
5. Right Node - Type II(-)
 - a. Calculate α and β from (B.52) and (B.53)
 - b. Calculate C_{2PR} from (B.45)
 - c. Calculate C_{3PR} and C_{1PR} from (B.24a) and (B.24b) using C_{2PR}
 - d. Calculate E from (B.40)
 - e. Pick C_{12} , calculate C_{32} and C_{22} from (B.46) and (B.47)
 - f. Calculate h' from (B.48)
 - g. Calculate C_{31} , C_{11} , C_{21} from (B.49) through (B.51)

FIGURE B.1: Ternary Phase Diagrams

FIGURE B.2: Hand Plot

FIGURE B.3: Coordinate Rotation

APPENDIX C: PHASE: A Ternary Phase Calculation Program

A short FORTRAN program called PHASE has been written to provide the CHEM2D user with a tool for looking directly at the phase behavior of a system. PHASE is the phase behavior calculation of CHEM2D coupled with a driving program for generating ternary phase behavior input data and for outputting tabular results.

PHASE can be used to compute:

1. phase concentrations and saturations as a function of effective salinity and total component concentrations; and
2. phase saturations (relative volumes) as a function of effective salinity for a fixed set of total component concentrations.

The latter capability is particularly useful for preparing phase volume versus effective salinity diagrams (Figure C.1).

Any CHEM2D data set may be run with PHASE (on a DEC 2060, TOPS 20 operating system or other compatible configuration) without modification if:

1. the first five columns of the title card for the Phase Behavior Data section (see Volume II of this report) are P H A S E; and
2. no other title card of the CHEM2D input data set begins with the five letters P H A S E.

Other data required by PHASE are input interactively.

The FORTRAN code for the program PHASE is reproduced in Section C.1. An example run is reproduced in its entirety in Section C.2. All underlined values are input by the user during an interactive session. For Type II(-) systems the aqueous phase saturation of the output represents the microemulsion phase of Figure C.1, while for Type II(+) systems the microemulsion phase of Figure C.1 is represented by the oleic phase saturation.

FIGURE C.1: Phase Volume vs. Effective Salinity

Total Water Concentration = 0.475
Total Oil Concentration = 0.475
Total Surfactant Concentration = 0.050

```

SECTION C.1:  PHASE Program Code

00010  C
00020  C      PHASE  PHASE BEHAVIOR CALCULATION PROGRAM
00025  C      JOHN R  FANCHI
00030  C      OCTOBER, 1983
00040  C
00050      COMMON /HH1/  CTOT(11,11,9),C(121,9,3),CSE(11,11),S(11,11,3)
00060      COMMON /HH2/  CSEL,CSEU,C2PLC,C2PRC,A11,A12,A21,A22,B1,B2,B3,(
00070      1G3,F1,F2,F3,G11,G12,G13,G21,G22,G23,XIFTW,CSEOPT
00080      COMMON /HH3/  IJ1,I,J,NP,NPHASE(11,11),XIFT1,XIFT2,XIFT3,ALPHA
00090      1,SR1,SR2,SR3
00100      COMMON /HH4/  A,B,G,F,IFX,XR,XL
00110      COMMON /HH7/  IERROR
00120      DOUBLE PRECISION INDAT,OUTDAT
00130      DIMENSION PRIVAR(11,11),TITLE(48),CSEO(7)
00140      DATA LINSUM/0/
00150      DATA ICOUNT,FC/0,1 0/
00160      DATA NX,NY,N/1,1,3/
00170  C      OPEN FILES FOR I/O ON DEC 2060, KCS, HOUSTON
00180      WRITE ( 5,3)
00190      3 FORMAT(1X,'ENTER INPUT DATA FILE NAME .      ',%)
00200      READ(5,5) INDAT
00210      5 FORMAT(A10)
00220      OPEN(UNIT=20,DEVICE='DSK',MODE='ASCII',ACCESS='SEQIN',
00230      & FILE=INDAT,DISPOSE='SAVE')
00240      WRITE ( 5,7)
00250      7 FORMAT(1X,'ENTER OUTPUT DATA FILE NAME .      ',%)
00260      READ(5,5) OUTDAT
00270      OPEN(UNIT=21,DEVICE='DSK',MODE='ASCII',ACCESS='SEQOUT',
00280      & FILE=OUTDAT,DISPOSE='SAVE')
00290  C      END OF OPEN FILES
00300      WRITE ( 5,2001)
00310      2001 FORMAT(/T30,69('*'),/T30,'*',T98,'*',/T30,'*',T98,'*')
00320      WRITE ( 5,2002)
00330      2002 FORMAT(T30,'*',T61,' PHASE ',T98,'*',/T30,'*',T50,
00340      & 'TERNARY PHASE CALCULATION',T98,
00350      & ' ',/T30,'*',T58,'(VERSION 1 0)',T98,'*')
00360      WRITE ( 5,2003)
00370      2003 FORMAT(T30,'*',T98,'*',/T30,'*',T98,'*',/T30,69('*'),/T30,69('*'),/T30,69('*'),/T30,69('*'))
00380  C      TITLE OF INPUT DATA SET
00390  C
00400      WRITE(5,2010)
00410      2010 FORMAT(1X,'TERNARY PHASE CALC OR PHASE VOLUME?',
00420      & /,1X,'ENTER 0 FOR TERNARY PHASE CALC,',
00430      & /,1X,'ENTER 1 FOR PHASE VOLUME ',%)
00440      READ(5,*) ICODE
00450      10 CONTINUE
00460  C
00470      READ (20,1090) (TITLE(I),I=1,16)
00480      IF(TITLE(1) NE 5HPHASE) GO TO 10
00490  C
00500  C      PHASE BEHAVIOR DATA

```

Sheet 2

```

00510      C          SECTION C.1: PHASE Program Code
00520      READ (20,*) CSELI, CSEUI, CSEOPT
00530      READ (20,*) C2PLC, C2PRC
00540      READ (20,*) C3MAX0, C3MAX1, C3MAX2
00550      READ (20,*) B1, B2, B3
00560      READ (20,*) F1, F2, F3
00570      C
00580      AA0=((2. *C3MAX0)/(1. -C3MAX0))**2
00590      AA1=((2. *C3MAX1)/(1. -C3MAX1))**2
00600      AA2=((2. *C3MAX2)/(1. -C3MAX2))**2
00610      A21=AA0
00620      A22=(AA1-AA0)
00630      A11=2. *AA1-AA2
00640      A12=(AA2-AA1)
00650      WRITE ( 5,1340)
00660      WRITE ( 5,1350)
00670      WRITE ( 5,1360) CSELI, CSEUI, CSEOPT
00680      WRITE ( 5,1380)
00690      WRITE ( 5,1360) C2PLC, C2PRC
00700      WRITE ( 5,1390)
00710      WRITE ( 5,1360) C3MAX0, C3MAX1, C3MAX2
00720      WRITE ( 5,1400)
00730      WRITE ( 5,1360) B1, B2, B3
00740      WRITE ( 5,1410)
00750      WRITE ( 5,1360) F1, F2, F3
00760      CSEL=CSELI
00770      CSEU=CSEUI
00780      C
00790      C
00800      C -----
00810      C SET INITIAL VALUE
00820      C -----
00830      C
00840      IF(ICODE.NE.0) GO TO 2105
00850      CSE0(1)=0.5*CSEL
00860      CSE0(2)=0.95*CSEL
00870      CSE0(3)=1.0-0.95*(1.0-CSEL)
00880      CSE0(4)=1.0
00890      CSE0(5)=1.0+0.95*(CSEU-1.0)
00900      CSE0(6)=1.05*CSEU
00910      CSE0(7)=1.5*CSEU
00920      C
00930      DO 1040 INDEX=1,7
00940      C3MAX=C3MAX1
00950      IF(INDEX.LT.3) C3MAX=C3MAX0
00960      IF(INDEX.GT.5) C3MAX=C3MAX2
00970      170 DO 190 J=1,NY
00980      DO 190 I=1,NX
00990      WRITE(5,1034) CSE0(INDEX)
01000      1034 FORMAT(/,5X,120(' '),/,10X,'CSE =',F10.6,/)

```

```

01010 C
01020 DO 190 INDTOT=1,4
01030 CTOT(I,J,3)=(INDTOT)*0.25*C3MAX
01040 WRITE(5,1036)
01050 DO 190 JNDTOT=1,9
01060 WRITE(5,1038)
01070 1038 FORMAT(/,7X,' K CTOT(K) C(K,1) C(K,2) C(K,3)
01080 & ' S(K)')
01090 CTOT(I,J,1)=0.1*JNDTOT
01100 IF((CTOT(I,J,3)+CTOT(I,J,1)).GT.1.0) CTOT(I,J,1)=1.-CTOT(I,
01110 CTOT(I,J,2)=1.-CTOT(I,J,1)-CTOT(I,J,3)
01120 C
01130 CSE(I,J)=CSE0(INDEX)*CSEOPT
01140 DO 180 L=1,3
01150 DO 180 K=1,9
01160 180 C(IJ1,K,L)=0.
01170 CALL PHCOMP
01180 DO 25 K=1,3
01190 WRITE(5,26) K, CTOT(I,J,K), (C(IJ1,K,L),L=1,3),S(I,J,K)
01200 26 FORMAT(5X,15,6F10.6)
01210 25 CONTINUE
01220 190 CONTINUE
01230 1036 FORMAT(/,5X,120(' '),/)
01240 C
01250 1040 CONTINUE
01260 GO TO 2004
01270 C
01280 C
01290 C PHASE VOLUME CALC
01300 C
01310 C
01320 2105 CONTINUE
01330 I=1
01340 J=1
01350 WRITE(5,2110)
01360 2110 FORMAT(/1X,'ENTER TOTAL WATER CONC (FR) ',*)
01370 READ(5,*) CTOT(I,J,1)
01380 WRITE(5,2120)
01390 2120 FORMAT(1X,'ENTER TOTAL OIL CONC (FR) ',*)
01400 READ(5,*) CTOT(I,J,2)
01410 CTOT(I,J,3)=1.-CTOT(I,J,1)-CTOT(I,J,2)
01420 WRITE(5,2130) CTOT(I,J,3)
01430 2130 FORMAT(1X,'TOTAL SURF CONC (FR) =',F10.6)
01440 DO 3000 JVOL=1,20
01450 DCSE=CSEU-CSEL
01460 CSE(I,J)=CSEOPT+CSEOPT*DCSE*(1.-(20-JVOL)*2./19.)
01470 CALL PHCOMP
01480 WRITE(5,2150)
01490 2150 FORMAT(/,7X,' K CTOT(K) C(K,1) C(K,2) C(K,3)
01500 & ' S(K) CSE(OSU)')

```

```

01510      DO 3025 K=1,3
01520      CSEOUT=CSE(I,J)/CSEOPT
01530      WRITE(5,26) K,CTOT(I,J,K),(C(IJ1,K,L),L=1,3),S(I,J,K),CSEOUT
01540      3025 CONTINUE
01550      3000 CONTINUE
01560      WRITE(5,3110)
01570      3110 FORMAT(//1X,'ANOTHER PHASE VOLUME CALC? (Y/N) ',*)
01580      READ(5,3120) PVCALC
01590      3120 FORMAT(A5)
01600      IF(PVCALC.EQ.5HN .OR. PVCALC.EQ.5HNO ) GO TO 2004
01610      GO TO 2105
01620      2004 WRITE(5,2005)
01630      2005 FORMAT(//,50('*'),T55,'RUN TERMINATED',T73,50('*'),//)
01640      C      CLOSE I/O FILES FOR DEC 20/60
01650      CLOSE(UNIT=20)
01660      CLOSE(UNIT=21)
01670      C      END OF CLOSE FILES
01680      STOP
01690      C
01700      1090 FORMAT(16A5)
01710      1095 FORMAT (16A5)
01720      1340 FORMAT(///,5X,'PARAMETERS FOR PHASE DIAGRAM')
01730      1350 FORMAT(/,8X,'CSELI',7X,'CSEUI',6X,'CSEOPT')
01740      1360 FORMAT (5X,10G12.4)
01750      1370 FORMAT (8X,I3,9X,I3,4X,5G12.4)
01760      1380 FORMAT (/,8X, 5HC2PLC,7X, 5HC2PRC)
01770      1390 FORMAT (/,8X, 6HC3MAX0,6X, 6HC3MAX1,6X, 6HC3MAX2)
01780      1400 FORMAT (/,10X, 2HB1,10X, 2HB2,10X, 2HB3)
01790      1410 FORMAT (/,10X, 2HF1,10X, 2HF2,10X, 2HF3)
01800      1920 FORMAT (///,5X, 8HSALINITY)
01810      1930 FORMAT (///,5X, 32HTOTAL CONCENTRATION OF COMPONENT,I3)
01820      1940 FORMAT (///,5X, 26HCONCENTRATION OF COMPONENT,I3, 9H IN PHA
01830      C
01840      END

```

```

01850 C.
01860 SUBROUTINE PHCOMP
01870 C
01880 C
01890 C
01900 C THIS SUBROUTINE IS USED TO FIND THE PHASE ENVIRONMENT AND
01910 C TO CALCULATE THE PHASE COMPOSITIONS AND SATURATIONS
01920 C
01930 C
01940 C
01950 COMMON /HH1/ CTOT(11,11,9),C(121,9,3),CSE(11,11),S(11,11,3)
01960 COMMON /HH2/ CSEL,CSEU,C2PLC,C2PRC,A11,A12,A21,A22,B1,B2,B3,
01970 1G3,F1,F2,F3,G11,G12,G13,G21,G22,G23,XIFTW,CSEOPT
01980 COMMON /HH3/ IJ1,I,J,NP,NPHASE(11,11),XIFT1,XIFT2,XIFT3,ALPH
01990 1,SR1,SR2,SR3
02000 COMMON /HH4/ A,B,G,F,IFX,XR,XL
02010 COMMON /HH7/ IERROR
02020 C
02030 IJ1=1
02040 I=1
02050 J=1
02060 C
02070 IF (CTOT(I,J,7).GE.1.0E-8) RSA=CTOT(I,J,3)/CTOT(I,J,7)
02080 C
02090 C COMBINE SURFACTANT AND ALCOHOL TOGETHER AS COMPONENT THREE
02100 C
02110 CTOT(I,J,3)=CTOT(I,J,3)+CTOT(I,J,7)
02120 C
02130 C EFFECTIVE SALINITY CSE(I,J) IS CONVERTED TO OPTIMAL SALINI-
02140 C TIES BY DIVIDING BY OPTIMAL SALINITY CSEOPT IN SUB PHCOMP
02150 C CSEOPT IS IN VOL FRAC UNITS.
02160 C
02170 IF ((CSE(I,J)/CSEOPT).LT.CSEU) GO TO 80
02180 C
02190 C TYPE II(+) BEHAVIOR HIGH SALINITY
02200 C
02210 A1=A11+A12*(CSE(I,J)/CSEOPT)
02220 IF (CTOT(I,J,2).LT.0.0010) GO TO 60
02230 R32=CTOT(I,J,3)/CTOT(I,J,2)
02240 R31=(R32/A1)**(1.0/B1)
02250 C(IJ1,1,2)=R32/(R32+R32*R31+R31)
02260 C(IJ1,2,2)=1.0-(R31+1.0)*C(IJ1,1,2)
02270 C(IJ1,3,2)=1.0-C(IJ1,1,2)-C(IJ1,2,2)
02280 IF (C(IJ1,3,2).LT.CTOT(I,J,3)) GO TO 60
02290 NPHASE(I,J)=2
02300 NP=1
02310 IF (ABS(C2PLC).GT.00001 AND ABS(F1).GT.00001) GO TO 20
02320 C(IJ1,1,1)=1.0
02330 C(IJ1,2,1)=0.0
02340 C(IJ1,3,1)=0.0
02350 GO TO 30

```

```

02360      20 A=A1
02370      B=B1
02380      F=F1
02390      C3PLC= 5*(-A*C2PLC+((A*C2PLC)**2+4.*A*C2PLC*(1 -C2PLC))**.5.
02400      G=(1 -C3PLC-C2PLC)/C2PLC
02410      C
02420      C      CALCULATE R31 ,R32 AT PLAIT POINT
02430      C
02440      XR=C3PLC/C2PLC-.0000001
02450      XL=.0000001
02460      C
02470      C      CALCULATE THE CONCENTRATIONS OF COMPONENTS OF TWO PHASES
02480      C
02490      CALL TIELIN
02500      IF (IERROR.EQ 1) RETURN
02510      30 DO 40 K=1,9
02520      40 C(IJ1,K,3)=0.0
02530      DO 50 K=5,9
02540      DO 50 L=1,2
02550      50 C(IJ1,K,L)=CTOT(I,J,K)*C(IJ1,1,L)/CTOT(I,J,1)
02560      S(I,J,1)=(CTOT(I,J,1)-C(IJ1,1,2))/(C(IJ1,1,1)-C(IJ1,1,2))
02570      S(I,J,2)=1.-S(I,J,1)
02580      S(I,J,3)=0.0
02590      GO TO 350
02600      60 NPHASE(I,J)=1
02610      DO 70 K=1,9
02620      C(IJ1,K,1)=CTOT(I,J,K)
02630      C(IJ1,K,2)=0.
02640      70 C(IJ1,K,3)=0.
02650      S(I,J,1)=1.
02660      S(I,J,2)=0.
02670      S(I,J,3)=0.
02680      GO TO 350
02690      80 IF ((CSE(I,J)/CSEOPT).GT.CSEL) GO TO 150
02700      C
02710      C      TYPE II(-) BEHAVIOR LOW SALINITY
02720      C
02730      A2=A21+A22*(CSE(I,J)/CSEOPT)
02740      R31=CTOT(I,J,3)/CTOT(I,J,1)
02750      R32=A2*R31**B2
02760      C(IJ1,1,1)=R32/(R32+R32*R31+R31)
02770      C(IJ1,2,1)=1.0-(R31+1.0)*C(IJ1,1,1)
02780      C(IJ1,3,1)=1.0-C(IJ1,1,1)-C(IJ1,2,1)
02790      IF (C(IJ1,3,1) LT CTOT(I,J,3)) GO TO 130
02800      NPHASE(I,J)=2
02810      NP=2
02820      IF (ABS(C2PRC) LT 1.0 AND ABS(F2) GT .000001) GO TO 90
02830      C(IJ1,1,2)=0.0
02840      C(IJ1,2,2)=1.0
02850      C(IJ1,3,2)=0.0

```

```

02860      GO TO 100
02870      90 A=A21+A22*(CSE(I,J)/CSEOPT)
02880      B=B2
02890      F=F2
02900      C3PRC=.5*(-A*C2PRC+((A*C2PRC)**2+4.*A*C2PRC*(1.-C2PRC))**.5)
02910      G=(1.-C3PRC-C2PRC)/C2PRC
02920      XR=G*R31**F
02930      XL=.0000001
02940      C
02950      C      CALCULATE THE CONCENTRATIONS OF COMPONENTS OF TWO PHASES
02960      C
02970      CALL TIELIN
02980      100 DO 110 K=1,9
02990      110 C(IJ1,K,3)=0.0
03000      DO 120 K=5,9
03010      DO 120 L=1,2
03020      120 C(IJ1,K,L)=CTOT(I,J,K)*C(IJ1,1,L)/CTOT(I,J,1)
03030      S(I,J,1)=(CTOT(I,J,1)-C(IJ1,1,2))/(C(IJ1,1,1)-C(IJ1,1,2))
03040      S(I,J,2)=1.-S(I,J,1)
03050      S(I,J,3)=0.
03060      GO TO 350
03070      130 NPHASE(I,J)=1
03080      DO 140 K=1,9
03090      C(IJ1,K,2)=0.0
03100      C(IJ1,K,1)=CTOT(I,J,K)
03110      140 C(IJ1,K,3)=0.
03120      S(I,J,1)=1.0
03130      S(I,J,2)=0.0
03140      S(I,J,3)=0.0
03150      GO TO 350
03160      C
03170      C      TYPE III BEHAVIOR: INTERMEDIATE SALINITY
03180      C
03190      150 C2M=((CSE(I,J)/CSEOPT)-CSEL)/(CSEU-CSEL)
03200      IF ((CSE(I,J)/CSEOPT)-.5*(CSEU+CSEL)) 160,160,170
03210      160 A3=A21+A22*(CSE(I,J)/CSEOPT)
03220      GO TO 180
03230      170 A3=A11+A12*(CSE(I,J)/CSEOPT)
03240      180 A=A3
03250      B=B3
03260      F=F3
03270      C3M=.5*(-A*C2M+((A*C2M)**2+4.*A*C2M*(1.-C2M))**.5)
03280      C1M=1.-C2M-C3M
03290      IF (C2M.LT.1.0E-10) C2M=1.0E-10
03300      IF (C1M.LT.1.0E-10) C1M=1.0E-10
03310      IF (CTOT(I,J,2).GT.C2M) GO TO 250
03320      C
03330      C      TEST FOR THREE PHASES
03340      C
03350      IF (CTOT(I,J,3).LT.C3M*CTOT(I,J,2)/C2M) GO TO 300

```



```

03360 C
03370 C PHASES 1 AND 2 -- LEFT NODE AND ONE PHASE REGION
03380 C
03390 IF (CTOT(I,J,2).LE 0.001) GO TO 230
03400 NPHASE(I,J)=2
03410 NP=1
03420 R32=CTOT(I,J,3)/CTOT(I,J,2)
03430 R31=(R32/A3)**(1.0/B3)
03440 C(IJ1,1,2)=R32/(R32+R32*R31+R31)
03450 C(IJ1,2,2)=1.0-(R31+1.0)*C(IJ1,1,2)
03460 C(IJ1,3,2)=1.0-C(IJ1,1,2)-C(IJ1,2,2)
03470 IF (C(IJ1,3,2).LT.CTOT(I,J,3)) GO TO 230
03480 IF (ABS(C2PLC).GT.1.0E-10) GO TO 190
03490 C(IJ1,1,1)=1.0
03500 C(IJ1,2,1)=0.0
03510 C(IJ1,3,1)=0.0
03520 GO TO 200
03530 190 C2PL=C2PLC+((CSE(I,J)/CSEOPT)-CSEU)*C2PLC/(CSEU-CSEL)
03540 C3PL=.5*(-A*C2PL+((A*C2PL)**2+4.*A*C2PL*(1.-C2PL))**.5)
03550 C1PL=1.-C2PL-C3PL
03560 ALPHA=C3M/C2M
03570 BETA=SQRT(C2M**2+C3M**2)/C2M
03580 G=(1.+(ALPHA-BETA)*C2PL-C3PL)/(BETA*C2PL)
03590 XR=C3PL/C1PL-.0000001
03600 XL=.0000001
03610 CALL TIELIN
03620 IF (IERROR.EQ.1) RETURN
03630 200 DO 210 K=1,9
03640 210 C(IJ1,K,3)=0.0
03650 IF (CTOT(I,J,3).GT.C(IJ1,3,2)) GO TO 230
03660 DO 220 K=5,9
03670 DO 220 L=1,2
03680 220 C(IJ1,K,L)=CTOT(I,J,K)*C(IJ1,1,L)/CTOT(I,J,1)
03690 S(I,J,1)=(CTOT(I,J,1)-C(IJ1,1,2))/(C(IJ1,1,1)-C(IJ1,1,2))
03700 S(I,J,2)=1.0-S(I,J,1)
03710 S(I,J,3)=0.0
03720 GO TO 350
03730 C
03740 C SINGLE PHASE
03750 C
03760 230 NPHASE(I,J)=1
03770 DO 240 K=1,9
03780 C(IJ1,K,2)=0.
03790 C(IJ1,K,3)=0.
03800 240 C(IJ1,K,1)=CTOT(I,J,K)
03810 S(I,J,1)=1.0
03820 S(I,J,2)=0.0
03830 S(I,J,3)=0.0
03840 GO TO 350
03850 250 IF (CTOT(I,J,3).LT C3M*CTOT(I,J,1)/C1M) GO TO 300

```

```

03860 C
03870 C PHASES 1 AND 2 -- RIGHT NODE AND ONE PHASE REGION
03880 C
03890 NPHASE(I,J)=2
03900 NP=2
03910 R31=CTOT(I,J,3)/CTOT(I,J,1)
03920 R32=A3*R31**B3
03930 C(IJ1,1,1)=R32/(R32+R32*R31+R31)
03940 C(IJ1,2,1)=1.0-(R31+1.0)*C(IJ1,1,1)
03950 C(IJ1,3,1)=1.0-C(IJ1,1,1)-C(IJ1,2,1)
03960 IF (CTOT(I,J,3).GT.C(IJ1,3,1)) GO TO 230
03970 IF (ABS(C2PRC).LT.1.) GO TO 260
03980 C(IJ1,1,2)=0.0
03990 C(IJ1,2,2)=1.0
04000 C(IJ1,3,2)=0.0
04010 GO TO 270
04020 260 C2PR=C2PRC+(1.-C2PRC)*((CSE(I,J)/CSEOPT)-CSEL)/(CSEU-CSEL)
04030 C3PR=.5*(-A*C2PR+((A*C2PR)**2+4.*A*C2PR*(1.-C2PR))**.5)
04040 C1PR=1.-C2PR-C3PR
04050 ALPHA=C3M/C1M
04060 BETA=SQRT(C3M**2+C1M**2)/C1M
04070 G=BETA*C1PR/(1.+(ALPHA-BETA)*C1PR-C3PR)
04080 XR=G*R31**F-.0000001
04090 XL=.0000001
04100 CALL TIELIN
04110 IF (IERROR.EQ.1) RETURN
04120 270 DO 280 K=1,9
04130 280 C(IJ1,K,3)=0.0
04140 DO 290 K=5,9
04150 DO 290 L=1,2
04160 290 C(IJ1,K,L)=CTOT(I,J,K)*C(IJ1,1,L)/CTOT(I,J,1)
04170 S(I,J,2)=(CTOT(I,J,2)-C(IJ1,2,1))/(C(IJ1,2,2)-C(IJ1,2,1))
04180 S(I,J,1)=1.0-S(I,J,2)
04190 S(I,J,3)=0.0
04200 GO TO 350
04210 C
04220 C THREE PHASES
04230 C
04240 300 NPHASE(I,J)=3
04250 C(IJ1,1,1)=1.0
04260 C(IJ1,2,1)=0.0
04270 C(IJ1,3,1)=0.0
04280 C(IJ1,1,2)=0.0
04290 C(IJ1,2,2)=1.0
04300 C(IJ1,3,2)=0.0
04310 C(IJ1,1,3)=C1M
04320 C(IJ1,2,3)=C2M
04330 C(IJ1,3,3)=C3M
04340 DO 310 L=1,3
04350 DO 310 K=5,9

```

SECTION C.1: PHASE Program Code

Sheet 10

```
04360      310 C(IJ1,K,L)=CTOT(I,J,K)*C(IJ1,1,L)/CTOT(I,J,1)
04370          S(I,J,2)=((CTOT(I,J,1)-C(IJ1,1,3))*C(IJ1,2,3)+(1.0-C(IJ1,1,3))
04380      & *(CTOT(I,J,2)-C(IJ1,2,3)))/(1.0-C(IJ1,1,3)-C(IJ1,2,3))
04390          S(I,J,1)=((CTOT(I,J,1)-C(IJ1,1,3))*C(IJ1,2,3)+(CTOT(I,J,2)
04400      & -C(IJ1,2,3))*C(IJ1,1,3))/(1.0-C(IJ1,1,3)-C(IJ1,2,3))
04410          DO 315 L=1,2
04420          IF(S(I,J,L).LT.0.0) S(I,J,L)=0.0
04430          IF(S(I,J,L).GT.1.0) S(I,J,L)=1.0
04440      315 CONTINUE
04450          S(I,J,3)=1.-S(I,J,1)-S(I,J,2)
04460          GO TO 350
04470      316 CONTINUE
04480      350 CONTINUE
04490          RETURN
04500      C
04510          END
```

```

04520 C      .....TIELIN
04530 SUBROUTINE TIELIN
04540 C
04550 C      -----
04560 C
04570 C      USING HALF INTERVAL METHOD TO FIND THE CORRECT ANSWER
04580 C      OF C31/C21
04590 C
04600 C      -----
04610 C
04620 COMMON /HH1/ CTOT(11,11,9),C(121,9,3),CSE(11,11),S(11,11,3)
04630 COMMON /HH4/ A,B,G,F,IFX,XR,XL
04640 COMMON /HH7/ IERROR
04650 EPS=0.0001
04660 IFX=0
04670 CALL TRY (XR,FXR)
04680 IF (IERROR.EQ.1) RETURN
04690 CALL TRY (XL,FXL)
04700 IF (IERROR.EQ.1) RETURN
04710 10 APP=(XL+XR)/2.
04720 CALL TRY (APP,FXAPP)
04730 IF (IERROR.EQ.1) RETURN
04740 IF (FXAPP*FXL) 20,40,30
04750 20 XR=APP
04760 FXR=FXAPP
04770 IF (ABS(XR-XL).LE.EPS) GO TO 40
04780 GO TO 10
04790 30 XL=APP
04800 FXL=FXAPP
04810 IF (ABS(XR-XL).LE.EPS) GO TO 40
04820 GO TO 10
04830 40 CONTINUE
04840 RETURN
04850 C
04860 END

```

```

04870 C          ... .. TRY
04880 SUBROUTINE TRY (X,FX)
04890 C
04900 C -----
04910 C
04920 C USING EQUATION OF DISTRIBUTION CURVE AND EQUATION OF BINODAL
04930 C CURVE TO CALCULATE PHASE COMPOSITIONS
04940 C
04950 C -----
04960 C
04970 COMMON /HH1/ CTOT(11,11,9),C(121,9,3),CSE(11,11),S(11,11,3)
04980 COMMON /HH3/ IJ1,I,J,NP,NPHASE(11,11),XIFT1,XIFT2,XIFT3,ALPHA,B
04990 1,SR1,SR2,SR3
05000 COMMON /HH4/ A,B,G,F,IFX,XR,XL
05010 COMMON /HH7/ IERROR
05020 IFX=IFX+1
05030 IF (IFX.LE.100) GO TO 10
05040 IERROR=1
05050 WRITE ( 5,30) X,FX
05060 RETURN
05070 10 IF (NP.EQ.2) GO TO 20
05080 C
05090 C      C      Y=R32(1) X=R31(1) W=R32(2) Z=R31(2)
05100 C      C      LEFT NODE
05110 C
05120      Y=A*X**B
05130      C(IJ1,2,1)=X/(X+X*Y+Y)
05140      C(IJ1,3,1)=C(IJ1,2,1)*Y
05150      C(IJ1,1,1)=1.-C(IJ1,2,1)-C(IJ1,3,1)
05160      P=G*((C(IJ1,3,1)-C(IJ1,2,1)*ALPHA)/(1.-C(IJ1,3,1)+C(IJ1,2,1)*(A
05170 1A-BETA))))**F
05180      W=BETA*P + ALPHA
05190      IF(W.LE.0.0) GO TO 11
05200      Z=(W/A)**(1./B)
05210      C(IJ1,2,2)=Z/(Z+Z*W+W)
05220      C(IJ1,3,2)=C(IJ1,2,2)*W
05230      C(IJ1,1,2)=1.-C(IJ1,2,2)-C(IJ1,3,2)
05240      GO TO 15
05250 C
05260 11 CONTINUE
05270      C(IJ1,2,2)=1.
05280      C(IJ1,3,2)=0.
05290      C(IJ1,1,2)=0.
05300 C
05310 15 FX=(C(IJ1,3,2)-CTOT(I,J,3))*(C(IJ1,2,1)-CTOT(I,J,2))-(C(IJ1,3,1
05320 1TOT(I,J,3))*(C(IJ1,2,2)-CTOT(I,J,2))
05330      RETURN
05340 C
05350 C CALCUTE THE CONC OF WATER, OIL, SURFACTANT IN EACH PHASE
05360 C AT RIGHT NODE (TYPE III, II(-)) PHASE BEHAVIOR
05370 C X=R32(2) Y=R31(2) W=R32(1) Z=R31(1)

```

```

05380 C
05390 20 Y=(X/A)**(1./B)
05400 C(IJ1,2,2)=Y/(X+Y*X+Y)
05410 C(IJ1,3,2)=C(IJ1,2,2)*X
05420 C(IJ1,1,2)=1.-C(IJ1,2,2)-C(IJ1,3,2)
05430 P=((C(IJ1,3,2)-ALPHA*C(IJ1,1,2))/G/(1.+C(IJ1,1,2)*(ALPHA-BETA)
05440 1J1,3,2)))*(1./F)
05450 Z=BETA*P + ALPHA
05460 IF(Z.LE.0.0) GO TO 21
05470 W=A*(Z**B)
05480 C(IJ1,2,1)=Z/(Z+Z*W+W)
05490 C(IJ1,3,1)=C(IJ1,2,1)*W
05500 C(IJ1,1,1)=1.-C(IJ1,2,1)-C(IJ1,3,1)
05510 GO TO 25
05520 C
05530 21 CONTINUE
05540 C(IJ1,1,1)=1.0
05550 C(IJ1,2,1)=0.
05560 C(IJ1,3,1)=0.
05570 C
05580 25 FX=(C(IJ1,3,2)-CTOT(I,J,3))*(C(IJ1,2,1)-CTOT(I,J,2))-(C(IJ1,3,1
05590 1TOT(I,J,3))*(C(IJ1,2,2)-CTOT(I,J,2))
05600 C
05610 RETURN
05620 C
05630 30 FORMAT (1X, 8HIERROR=1,/, 4HR32=,E16.5, 3HFX=,E16.5)
05640 C
05650 END

```

PHASE

ENTER INPUT DATA FILE NAME ... CHMC12

ENTER OUTPUT DATA FILE NAME ... OUT

```

*****
*
*
*          PHASE:
*    TERNARY PHASE CALCULATION
*          (VERSION 1.0)
*
*
*****

```

TERNARY PHASE CALC OR PHASE VOLUME?

ENTER 0 FOR TERNARY PHASE CALC

ENTER 1 FOR PHASE VOLUME: 1

PARAMETERS FOR PHASE DIAGRAM

CSEL1 CSEUI CSEOPT
0.8000 1.200 0.3640E-02

C2FLC C2PRC
0.5000E-01 0.9500

C3MAX0 C3MAX1 C3MAX2
0.3000 0.1000 0.3000

B1 B2 B3
-1.000 -1.000 -1.000

F1 F2 F3
1.000 1.000 1.000

ENTER TOTAL WATER CONC (FR) 0.475

ENTER TOTAL OIL CONC (FR) 0.475

TOTAL SURF CONC (FR) = 0.050000

K	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	CSE(OSU)
1	0.475000	1.000000	0.000001	0.000000	0.474999	0.600000
2	0.475000	0.000000	0.999395	0.000000	0.525001	0.600000
3	0.050000	0.000000	0.000304	0.000000	0.000000	0.600000

K	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	CSE(OSU)
1	0.475000	1.000000	0.000001	0.000000	0.474999	0.642105
2	0.475000	0.000000	0.999350	0.000000	0.525001	0.642105
3	0.050000	0.000000	0.000649	0.000000	0.000000	0.642105

K	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	CSE(OSU)
1	0.475000	1.000000	0.000002	0.000000	0.474999	0.684211
2	0.475000	0.000000	0.999246	0.000000	0.525001	0.684211
3	0.050000	0.000000	0.000752	0.000000	0.000000	0.684211

K	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	CSE(OSU)
1	0.475000	1.000000	0.000003	0.000000	0.474999	0.726316
2	0.475000	0.000000	0.999179	0.000000	0.525001	0.726316
3	0.050000	0.000000	0.000818	0.000000	0.000000	0.726316

SECTION C.2: An Example PHASE Run

C.16.0

K	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	CSE(OSU)
1	0.475000	1.000000	0.000000	0.000000	0.474998	0.768421
2	0.475000	0.000000	0.999098	0.000000	0.525002	0.768421
3	0.050000	0.000000	0.000873	0.000000	0.000000	0.768421
K	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	CSE(OSU)
1	0.475000	0.857187	0.000001	0.000000	0.534099	0.810526
2	0.475000	0.052771	0.999682	0.000000	0.445901	0.810526
3	0.050000	0.090042	0.000317	0.000000	0.000000	0.810526
K	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	CSE(OSU)
1	0.475000	1.000000	0.000000	0.000000	0.167810	0.852632
2	0.475000	0.000000	1.000000	0.131579	0.420880	0.852632
3	0.050000	0.000000	0.000000	0.121163	0.411309	0.852632
K	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	CSE(OSU)
1	0.475000	1.000000	0.000000	0.238647	0.241322	0.894737
2	0.475000	0.000000	1.000000	0.236842	0.386962	0.894737
3	0.050000	0.000000	0.000000	0.134511	0.371717	0.894737
K	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	CSE(OSU)
1	0.475000	1.000000	0.000000	0.128452	0.270855	0.936842
2	0.475000	0.000000	1.000000	0.342105	0.243845	0.936842
3	0.050000	0.000000	0.000000	0.129433	0.386300	0.936842
K	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	CSE(OSU)
1	0.475000	1.000000	0.000000	0.410495	0.278591	0.978947
2	0.475000	0.000000	1.000000	0.447368	0.275524	0.978947
3	0.050000	0.000000	0.000000	0.112137	0.445884	0.978947
K	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	CSE(OSU)
1	0.475000	1.000000	0.000000	0.338167	0.320154	1.021053
2	0.475000	0.000000	1.000000	0.552632	0.221567	1.021053
3	0.050000	0.000000	0.000000	0.109202	0.457869	1.021053
K	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	CSE(OSU)
1	0.475000	1.000000	0.000000	0.224289	0.378947	1.063158
2	0.475000	0.000000	1.000000	0.657895	0.194128	1.063158
3	0.050000	0.000000	0.000000	0.117116	0.426926	1.063158
K	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	CSE(OSU)
1	0.475000	1.000000	0.000000	0.127923	0.416277	1.105263
2	0.475000	0.000000	1.000000	0.763158	0.124669	1.105263
3	0.050000	0.000000	0.000000	0.108920	0.439074	1.105263
K	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	CSE(OSU)
1	0.475000	0.999409	0.062682	0.000000	0.440168	1.147368
2	0.475000	0.000002	0.847917	0.000000	0.559832	1.147368
3	0.050000	0.000588	0.089100	0.000000	0.000000	1.147368
K	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	CSE(OSU)
1	0.475000	0.995494	0.050314	0.000000	0.449316	1.189474
2	0.475000	0.000108	0.861542	0.000000	0.550684	1.189474
3	0.050000	0.004375	0.038143	0.000000	0.000000	1.189474
K	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	CSE(OSU)
1	0.475000	0.000003	0.737988	0.000000	0.546704	1.231579
2	0.475000	0.857642	0.000630	0.000000	0.453096	1.231579
3	0.050000	0.094355	0.011332	0.000000	0.000000	1.231579
K	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	CSE(OSU)
1	0.475000	0.070003	0.737779	0.000000	0.545600	1.273684
2	0.475000	0.849665	0.000618	0.000000	0.453400	1.273684
3	0.050000	0.100332	0.012023	0.000000	0.000000	1.273684

	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	ISE(OSU)
1	0.475000	0.050003	0.986750	0.000000	0.546305	1.315789
2	0.475000	0.844081	0.000609	0.000000	0.453695	1.315789
3	0.050000	0.105917	0.012641	0.000000	0.000000	1.315789

	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	ISE(OSU)
1	0.475000	0.050003	0.986159	0.000000	0.546017	1.357895
2	0.475000	0.838827	0.000603	0.000000	0.453981	1.357895
3	0.050000	0.111170	0.013238	0.000000	0.000000	1.357895

	CTOT(K)	C(K,1)	C(K,2)	C(K,3)	S(K)	ISE(OSU)
1	0.475000	0.050003	0.985584	0.000000	0.545740	1.400000
2	0.475000	0.833857	0.000599	0.000000	0.454260	1.400000
3	0.050000	0.116141	0.013817	0.000000	0.000000	1.400000

ANOTHER PHASE VOLUME (AIC? (Y/N) N

, **

RUN TERMINATED

End of Location

C.18.0

SECTION C.2: An Example PHASE Run

Sheet 3