118
12/5/91 JS (13)

High-Speed Tapping for N/C Machining Centers

J. P. Friend

KCP-613-4478

Published November 1991

Final Report

Prepared for the United States Department of Energy Under Contract Number DE-ACO4-76-DP00613.

Allied-Signal Aerospace Company
Kansas City Division

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

Printed in the United States of America.

This report has been reproduced from the best available copy.

Available to DOE and DOE contractors from the Office of Scientific and Technical Information, P. O. Box 62, Oak Ridge, Tennessee 37831; prices available from (615) 576-8401, FTS 626-8401.

Available to the public from the National Technical Information Service, U. S. Department of Commerce, 5285 Port Royal Rd., Springfield, Virginia 22161.

A prime contractor with the United States
Department of Energy under Contract Number
DE-ACO4-76-DP00613.

Kansas City Division
P.O. Box 419159
Kansas City, Missouri
64141-6159

KCP-613-4478
Distribution Category UC-706

KCP--613-4478

DE92 003679

HIGH-SPEED TAPPING FOR N/C MACHINING CENTERS

J. P. Friend

Published November 1991

Final Report
J. P. Friend, Project Leader

Technical Communications
Kansas City Division

Allied-Signal Aerospace Company

MASTER

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

EB

HIGH-SPEED TAPPING FOR N/C MACHINING CENTERS

KCP-613-4478, Final Report, Published November 1991

Prepared by J. P. Friend

Through a series of experiments, a new high-speed tapping technique was developed for N/C machining centers. The new technique produces high quality threads in a fraction of the time previously required, using the same equipment. Threads are produced to precise size and depth in a single pass at speeds up to 5000 rpm. Thread sizes ranged from 0.80 UNM (Unified Miniature Thread Series) (0.0315 in. major diameter) to 0.250-20 UN (Unified Screw Threads) in both blind and through-hole applications. The materials tapped included 17-4 PH stainless steel, 300 series stainless steel, and 6061-T6 aluminum.

CONTENTS

Section	Page
SUMMARY	5
DISCUSSION	6
SCOPE AND PURPOSE	6
ACTIVITY	6
<u>Advantages</u>	8
<u>Disadvantages</u>	10
<u>N/C Programming</u>	13
<u>Hardware</u>	14
ACCOMPLISHMENTS	14

ILLUSTRATIONS

Figure		Page
1	Typical Tapping Attachments as Used on a Drill Press Line	7
2	Production Part Material 6061-T6511 Aluminum	8
3	Production Part Material 356 Aluminum Casting	9
4	Miniature Production Part Material 303 SE Stainless Steel	10
5	Cross Section View of Tapping Attachment in Drive Mode	11
6	Cross Section View of a Tapping Attachment in Reverse Mode	12
7	Typical Torque Bar Arrangement	13
8	Typical Torque Bar Arrangement on a Machining Center	14
9	Illustration of a Through-Hole Application	15
10	Illustration of a Blind-Hole Application	16

SUMMARY

In the past, tapping has been one of the least efficient elements of any N/C machining operation. Typically, threads were started on the machining center but were tapped to finished depth by hand after the part was removed from the machine. The most common tapping attachments used to start these threads were the non-reversing compression/tension type. These attachments provided a degree of axial float which is required for tapping, but also required the machine to reverse spindle rotation to remove the tap from the hole. Tapping speeds were limited to 200 rpm to facilitate this reversal. The combined effects of the slow cutting speed and the insensitivity of the attachment's axial float usually resulted in broken taps, torn threads, over high limit (OHL) or under low limit (ULL) threads, insufficient thread depth in blind holes and inadequate surface finishes.

As a result of this study, self-reversing tapping attachments were found to provide a solution to each of these common tapping problems. They eliminated the need for reversing the machine spindle, provided very sensitive axial float, and allowed tapping speeds up to 5000 rpm. Quality threads were produced in both blind and through-hole applications in sizes from 0.80 UNM (0.0315 in. major diameter) to 0.250- 20 UN. Materials successfully tapped included 17-4 PH stainless steel, 300 series stainless steel, and 6061 T6 aluminum.

Utilization of the new tapping process reduced rework and scrap associated with threaded holes, increased productivity, and reduced the flow time required for each part evaluated within this effort.

DISCUSSION

SCOPE AND PURPOSE

The purpose of this project was to develop a method for using high-speed tapping attachments on N/C machining centers. The new method is to provide a reliable means of producing quality threads to the required depth during the normal machine cycle.

ACTIVITY

Self-reversing tapping attachments have been used successfully on drill press operations for many years (Figure 1). They provide a method to produce quality threads in both blind and through-hole applications. Unfortunately, the drill press represents a secondary machining operation within an environment that is rapidly moving toward the more productive "one step machining" concept. Thus, the goal of this project was to develop a method for utilizing these attachments on the machining centers to produce quality threaded holes without adding operations.

As a result of this study, a method was successfully developed and incorporated to utilize these attachments as a part of the normal "one step machining" process. This accomplishment provided a solution to the many rejections associated with tapped holes during inspection.

The first evaluation of the new method was performed on a 6061-T6511 aluminum part. The problems associated with this part were OHL threads and insufficient thread depth in the blind holes. (Hand tapping was the only method available to obtain the required depth in the blind holes.) The thread sizes were #2-56, #4-40 and #4-48. A combination of blind and through holes were tapped. Tapping speeds were increased from 150 rpm to 1400 rpm on the #4-40 and #4-48 holes and from 150 rpm to 1767 rpm on the #2-56 holes. Hand tapping was completely eliminated and no thread defects were found on the first 100 parts submitted to inspection (Figure 2).

The torn threads, OHL threads, and hand tapping normally associated with tapping a 356 aluminum casting were eliminated by utilizing the self-reversing attachments. Tapping speeds were increased from 143 to 1100 rpm, and all 37 blind holes were tapped to the required depth on the machining center. The thread sizes were #6-32 helicoil and #10-32 (Figure 3).

Prior to utilizing the self-reversing attachments, hand tapping was required to obtain the specified thread depth in the blind holes of a cast 17-4 PH stainless steel part. These holes were located in the thin-wall sections of the casting, which limited the depth of the drilled holes. To obtain the required thread depth, the tap was hand driven to within 0.025 in. of the bottom of the drilled hole. This often resulted in OHL threads and/or broken taps. The self-reversing attachments provided the precise depth control required to tap the holes to depth during the normal machine

Figure 1. Typical Tapping Attachments as Used on a Drill Press Line

cycle. All hand tapping was eliminated. The thread sizes were #4-40, #8-32, and #10-32. The tapping speeds ranged from 425 to 700 rpm.

The additional operations required to tap 0.8 UNM threads in 303 SE stainless steel parts were eliminated by utilizing the self-reversing attachments. (The major diameter of this miniature thread is only 0.031 in. and it has 127 threads per inch.) In the past, the only methods available for producing threads this small were hand tapping and the use of a manually operated sensitive tapping machine. Both of these methods required an additional operation exclusively for tapping. Incorporating the self-reversing tapping attachments on four- and five-axis machining centers provided a means for producing many miniature parts in only one operation. The miniature threads are now efficiently produced at 2000 rpm (Figure 4).

Figure 2. Production Part Material 6061-T6511 Aluminum

To access the speed capability of the tapping attachments, a series of #4-40 blind-holes were tapped at the attachments maximum rated speed of 5000 rpm. This provided a cutting speed of 147 sfm and required a feedrate of 125 in./min. The material used for the evaluation was 304 stainless steel. The results were gage perfect threads produced nine full turns deep in a total of 46 holes. Although the cutting speed was excessive for 304 stainless, this evaluation clearly illustrated the capability of the attachments to tap the difficult-to-produce small thread sizes at high speeds.

Advantages

Self-Reversing Capability

When using a compression/tension type tap driver, the reverse rotation required to remove the tap from a hole is provided by the machine spindle (which requires slow tapping speeds). When using the self-reversing attachments, the machine spindle is not reversed because reverse rotation is provided by the attachment (providing tapping speeds to 5000 rpm).

Figure 3. Production Part Material 356 Aluminum Casting

Reverse rotation is accomplished via a ring and planetary gear arrangement within the attachment. When the drive spindle inside the attachment is engaged in the upper set of gears (driving the tap into the hole), it rotates in the same direction as the machine spindle (Figure 5); when engaged in the lower set of gears (Figure 6), the rotation is reversed (to remove the tap from the hole). Between the upper and lower ring gears is a neutral zone where the attachments spindle is disengaged from the rotation of the machine spindle. The neutral area allows the drive spindle to stop rotating before reversing and also provides reliable and precise depth control.

Figure 4. Miniature Production Part Material 303 SE
Stainless Steel

The movement of the drive spindle within the attachment (shifting from the drive gear to the reverse gear) is provided and controlled by the vertical movements of the machine spindle.

Sensitive Axial Float Capability

The attachment's spindle also provides sensitive axial float in both compression and tension. The sensitivity of the float is provided by a virtually friction free, ball- drive mechanism. The spindle is engaged with the ring gears by way of hardened steel balls which roll up and down within the ring gears as the spindle moves axially inside the attachment. This allows the tap to follow its own lead without the axial interference normally encountered when using compression/tension style tap drivers.

Disadvantages

Required Changes to the Machine Tool

Before a self-reversing attachment can be utilized on an N/C machining center, a torque bar must be installed on the machine (Figure 7). The torque bar holds the outer case of the attachment stationary during use, which allows the ring and planetary gears to function properly. The design and installation of the torque bar varies according to the configuration of the machine tool, but is usually a simple, one time alteration. Figure 8 shows a torque bar installed in a machining center.

Figure 5. Cross Section View of Tapping Attachment in Drive Mode

Figure 6. Cross Section View of a Tapping Attachment in Reverse Mode

Figure 7. Typical Torque Bar Arrangement

Limited Tapping Depth Capability

The self-reversing tapping attachments are not recommended for use in holes less than 0.100 in. deep.

N/C Programming

1. Utilize the drill or bore cycle of the machine.
2. Rapid approach to a clearance plane (0.300 in.) above the hole to be tapped.
3. Feed into the hole at approximately 95 percent of the calculated feedrate for the specific thread pitch used. ($\text{rpm} \times \text{pitch of thread} = \text{calculated feedrate}$.)
4. For through-holes (or blind-holes of sufficient depth), simply machine feed to the desired thread depth and immediately retract to the clearance plane. Dwell above the hole for one half second to allow the tap to clear the hole (Figure 9).
5. For blind holes, machine feed to the calculated partial depth (desired thread depth minus the self-feed of the tapping attachment), dwell until the attachments drive mechanism releases into the neutral position, then retract to the clearance plane. Dwell above the hole for one-half second to allow the tap to clear the hole (Figure 10).

Figure 8. Typical Torque Bar Arrangement on a Machining Center

Hardware

The attachments utilized in this study were from the Tapmatic Corporation, Irvine, California. The model number of the attachments used were 100XB, SPD-3, R3 and N/C-ROO.

ACCOMPLISHMENTS

The self-reversing tapping attachments provide a reliable method for tapping on N/C machining centers. Threads may be produced in blind and through-hole applications at speeds up to 5000 rpm using the correct tap and tap drill size. Spiral flute taps are recommended for blind-holes and spiral point taps for through-holes. Larger diameter tap drills should be used as the thread depth-to-diameter ratio increases, and all holes should be chamfered before tapping.

Figure 9. Illustration of a Through-Hole Application

On the basis of the aforementioned conclusions, process engineering is strongly encouraged to incorporate the self-reversing tapping attachments on all current and new tapping operations performed on N/C machining centers. Use of this tapping concept will contribute significantly toward reducing flow time, reducing rework and scrap, improving product quality, and increasing productivity.

Figure 10. Illustration of a Blind-Hole Application

END

DATE
FILMED
01/16/92

I