Technical Progress Report

to

United States Department of Energy
Pittsburgh Energy Technology Center

Attention: Mr. James D. Hickerson, Program Officer
David Hunter, Contract Specialist
Richard Rogus, Contract Officer

MOLTEN IRON OXYSULFIDE AS A SUPERIOR SULFUR SORBENT

DOE/DE-FG22-89PC89778

by

Malcolm T. Hepworth
Principal Investigator

Period Covered:
December 1, 1990 - February 28, 1991

MINERAL RESOURCES RESEARCH CENTER

DEPARTMENT OF CIVIL AND MINERAL ENGINEERING

UNIVERSITY OF MINNESOTA

ABSTRACT*

Slagging combustors with injected lime or limestone are being considered as replacements for conventional coal burners. They have advantages in that they can be staged to reduce NO_x and SO_x emissions. Iron oxide, as an alternative to lime or limestone may be effective not only as a desulfurizing agent, but under the right conditions of oxygen potential and after combination with sulfur, the reaction products of coal gases with iron oxide can act as a flux to produce a fluid phase. The thermodynamic conditions for determining the most effective operating conditions of the first stage of a combustor are calculated for an Illinois coal. The conditions studied during this quarter were for contact of a coal gas with a liquid iron oxysulfide phase for one temperature: 1200°C , for which data in the literature were available. The calculations are in terms of the expected pounds of SO_2 per million Btu of heat evolution calculated for complete combustion of the coal. The calculations indicate that the lowest sulfur levels in the off-gas occur in contact with iron in contact with a liquid phase containing 49.0 atom% iron, 29.5 atom% oxygen and 21.5 atom% sulfur. Under these conditions, the stack gas emerging from the second stage of combustion under stoichiometric conditions would contain 0.59 pounds of SO_2 per million BTU's of heat generated.

The results of the calculations are reported both in tabular form and in three-dimensional representation. Lowest values occur as a "trough" on the iron-oxygen-sulfur isotherm at compositions at the phase boundary of the oxysulfide liquid region in equilibrium with iron.

*Underlined are key words.

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

INTRODUCTION

In the prior quarterly reports, the combustion conditions were calculated on six Illinois Basin coals to determine what dosage of iron oxide and combustion stoichiometries are required in order to achieve a high degree of sulfur removal. Several sorbent systems were considered. These included the calcium-based system under reducing conditions to produce the phases $\text{CaS}/\text{CaO}/\text{gas}$ and under oxidizing conditions to produce $\text{CaSO}_4/\text{CaO}/\text{gas}$ as well as an iron-based system. This latter system is the primary subject of this research program. Prior calculations were for the four-phase equilibrium $\text{Fe}/\text{FeO}/\text{liquid (iron oxysulfide)}/\text{gas}$, for which data on the calculations were available in the literature.^{1,2} These calculations were part of an interactive program which enabled the coal combustion conditions to be entered by an operator. The program then calculated the optimum conditions of air dosage to achieve desulfurization with lime or iron oxides.

SUMMARY AND CONCLUSIONS

- Using a solution model and existing data on the Fe-O-S system at 1200° C, activity data on sulfur and oxygen have been calculated for a range of compositions in the oxysulfide single phase region. These calculations extend the data which were determined in the prior quarterly report.
- From the above data, a contour map was calculated of sulfur dioxide levels which would be produced upon burning an Illinois Coal (IBC -102C) to stoichiometric combustion with the first stage of the combustor (reducing state) operating at the calculated conditions of oxygen and sulfur activities.
- The most favorable conditions for lowest sulfur levels occur at compositions close to iron saturation. For example: an SO_2 level of 0.644 lbs/millions Btu's occurs at an oxysulfide concentration of 49.3 atom % iron, 27.2 atom% oxygen and 23.5 atom % sulfur. This represents an added magnetite level of 8.34% and an air rate of 410 liters STP per 100 g of dry coal. Increasing the sulfur content by only 3% nearly doubles the SO_2 level.

PLANS FOR NEXT QUARTER

In the next quarter, effort will be directed to developing experimental data on the Fe-S-O system both at 1200°C to overlap and check calibrations with existing data in the literature and also to extend the temperature range to 1300 and 1400° C in order to determine the viability of the iron oxysulfide phase as a sulfur sorbent.

THERMODYNAMIC ANALYSIS

1. Liquid in Equilibrium with Iron:

In this current period, attention was given entirely to the iron-oxygen-sulfur system but this time without the restriction requiring the liquid phase to be both in equilibrium with wustite and iron. Data from the literature³ is tabulated in Table 1. This table reports the compositions as atom percents of iron, oxygen, and sulfur in equilibrium with iron. It includes values of chemical potentials of oxygen (O_2) and sulfur ($S_{2(gas)}$), with these latter two expressed as common logarithms of the pressure in atmospheres.

TABLE 1

Data for Fe-Liquid in the Fe-S-O System at 1200°C

Fe%	O%	S%	$\lg(P_{O_2})^*$	$\lg(P_{S_2})^*$
57.00	7.84	35.16	-12.860	-5.631
56.00	10.00	34.00	-12.678	-5.603
55.00	11.96	33.04	-12.511	-5.732
54.00	14.71	31.29	-12.388	-5.752
53.00	17.35	29.65	-12.301	-5.775
52.00	19.80	28.20	-12.203	-5.772
51.00	23.00	26.00	-12.130	-5.757
50.00	25.53	24.47	-12.063	-5.745
49.00	29.47	21.53	-12.010	-5.786
48.53	32.20	19.27	-11.301	-5.245

* Pressure in atmospheres

The pressures of sulfur are seen to range in logarithmic values from -5.245 to -5.772.

The data in Table 1 was used in conjunction with the previously developed computer program (See report of previous quarter: Appendix C) to determine the levels of sulfur dioxide which would occur upon complete combustion of a selected coal. The conditions imposed upon these calculations are that the coal gas produced in a prior reducing stage of a combustor is in equilibrium at 1200°C with iron oxysulfide liquid of a given composition and also solid iron. The composition of the coal chosen for these

calculations was for a Western Illinois #2 Coal (Colchester), designated IBC-(Illinois Basin Coal) 102 having the analysis given below. The analyses which were incorporated into the calculations are for 100g of dry coal plus 14.2 g moisture:

Constituent % by Wt of IBC 102C Coal.

Carbon	73.92
Hydrogen	5.29
Nitrogen	1.52
Total sulfur	3.29
Oxygen	9.02 (not included in ash)
Ash	<u>6.9</u>
Total	100.0 (dry basis)
Moisture	14.2
BTU/lb	13,582

The results of these calculations are given in Table 2. This table is an extension of Table 1 for the same compositions as reported by Stofko et al³ as summarized in Table 1. However in Table 2, the pounds of SO₂ per million Btu, magnetite dosage and air requirements are determined by calculation. The fourth column is the pounds of SO₂ per million Btu's for combustion of the above coal which would result in the flue gas burned under stoichiometric conditions emerging from a combustor in which the prior stage (reduction stage) exhibited equilibrium of gas with liquid of the reported composition. The fifth column is the grams of magnetite which must be added to 100 grams of coal to produce a liquid of this alloy composition. The final column is volume of air required to produce the necessary sub-stoichiometric conditions in the first stage of the combustor.

TABLE 2

Calculations on Conditions for Combustion Gases from IBC -102 Coal in Contact with the Liquid Phase plus Solid Iron at 1200°C for the Given Compositions

Fe%	O%	S%	SO ₂ [*]	Fe ₃ O ₄ ^{**}	Air [†]
57.00	7.84	35.16	0.940	6.021	325.39
56.00	10.00	34.00	0.850	6.220	339.60
55.00	11.96	33.04	0.761	6.447	354.23
54.00	14.71	31.29	0.713	6.756	366.52
53.00	17.35	29.65	0.674	7.060	376.08
52.00	19.80	28.20	0.651	7.321	387.24
51.00	23.00	26.00	0.643	7.802	396.59
50.00	25.53	24.47	0.633	8.144	405.45
49.00	29.47	21.53	0.590	9.158	414.01
48.53	32.20	19.27	0.760	9.756	509.00

^{*}SO₂ - Concentration: lb/mm BTU
^{**}Fe₃O₄ - Dosage: g/100g Dry Coal
[†]Air - Dosage: liter STP/100g Dry Coal

Figure 1 is an isothermal of the Fe-O-S system at 1200°C showing the phase boundary between iron and iron oxysulfide phase. The circles represent this boundary. The iron-wustite equilibrium contact occurs at the extreme right of the diagram at approximately 32 atomic percent oxygen and 19.5% sulfur. Superimposed upon this diagram is the calculated SO₂ content of the combustion gases (triangular points) which would be produced if the coal gas emerging from the equilibrium between gas/iron/liquid were to undergo complete combustion. Note that the minimum in the SO₂ content is near to but less than wustite saturation (i.e., approximately at an oxygen level of 2.5 atomic % less than saturation). The lowest value of SO₂ content is approximately 0.59 lbs SO₂/million Btu for the coal used in this calculation (IBC-102C).

Figure 2 represents the magnetite and air dosage required to produce the necessary conditions represented by the prior figure, i. e. for iron saturation.

Figure 1. Isothermal Section Fe-O-S System at 1200°C along a Path of Iron-Saturation. Calculated Concentrations of SO₂ are for Conditions of Stoichiometric Combustion of IBC -102 Coal.

Figure 2. Isothermal Section Fe-O-S System at 1200°C along a Path of Iron-Saturation. Dosages of Magnetite (g/100 g dry coal) and Air Volumes (SCF/100 g dry coal) are those Required to Maintain the Iron-Saturation Conditions shown in Figure 1.

2. Liquid Oxysulfide Without the Restriction of the Presence of Iron.

It is possible to extend the data from the literature by use of a regular solution model as described in Appendix A of this report. Extending the original data to a total of 57 points makes it possible to map more completely the entire range of compositions which could be encountered in the ternary system Fe-O-S. The range of these points is shown in Figure 3. In this figure, the heavy solid diagonal line running from upper left to lower right is the limit of the single phase liquid in contact with solid iron (Labeled "Sat. Fe"). At the extreme lower right-hand corner of this region is saturation with magnetite (Fe_3O_4). The other lines are compositional limits marked $S = 43 - O$ and $S = 53 - O$, where S and O are atom percents sulfur and oxygen, respectively. These construction lines represent arbitrary cut-offs into regions of the liquid phase where the sulfur activities are too high to be of value for this study. The crossed-circles are for a combination of experimental and calculated data points. These data are summarized in Table 3.

TABLE 3

Literature Data and Interpolations for Fe-S-O System at 1200°C

Fe%	O%	%S	$\log(P_{\text{O}_2})$	$\log(P_{\text{S}_2})$
56.040	9.548	34.412	-12.699	-5.563
56.040	7.938	36.022	-12.777	-5.482
56.040	5.825	38.135	-13.000	-5.131
55.020	12.059	32.921	-12.523	-5.692
55.020	10.395	34.585	-12.620	-5.491
55.020	7.573	37.407	-12.745	-5.291
55.020	4.660	40.320	-13.000	-5.111
53.740	15.012	31.248	-12.398	-5.762
53.740	13.287	32.973	-12.432	-5.575
53.740	10.388	35.872	-12.509	-5.230
53.740	7.767	38.493	-12.620	-5.008
53.740	5.146	41.114	-12.796	-4.797
53.740	2.813	43.447	-13.000	-4.515

Fe%	O%	%S	log(P _{o2})	log(P _{s2})
52.340	17.894	29.766	-12.252	-5.708
52.340	16.110	31.550	-12.284	-5.542
52.340	14.078	33.582	-12.337	-5.233
52.340	10.388	37.272	-12.409	-4.955
52.340	7.379	40.281	-12.523	-4.681
52.340	3.883	43.777	-12.678	-4.213
51.230	20.878	27.892	-12.161	-5.743
51.230	19.054	29.716	-12.155	-5.501
51.230	15.922	32.848	-12.204	-5.194
51.230	13.107	35.663	-12.252	-4.877
51.230	9.515	39.255	-12.319	-4.603
51.230	5.922	42.848	-12.420	-4.192
51.230	3.883	44.887	-12.538	-3.807
50.000	24.391	25.609	-12.066	-5.661
50.000	22.804	27.196	-12.046	-5.443
50.000	19.223	30.777	-12.076	-5.113
50.000	15.631	34.369	-12.092	-4.769
50.000	12.233	37.767	-12.114	-4.496
50.000	8.350	41.650	-12.149	-4.093
50.000	4.369	45.631	-12.260	-3.499
49.320	27.167	23.513	-12.027	-5.717
49.320	25.937	24.743	-12.009	-5.563
49.320	24.067	26.613	-12.022	-5.393
49.320	21.068	29.612	-12.027	-5.069
49.320	17.176	33.204	-12.032	-4.725
49.320	13.883	36.797	-12.032	-4.444
49.320	10.000	40.680	-12.041	-4.064
49.320	5.340	45.340	-12.060	-3.421
48.613	30.266	21.121	-11.523	-5.244
48.613	29.050	22.337	-11.301	-4.903
48.613	27.818	23.569	-11.125	-4.607
48.613	25.938	25.449	-11.097	-4.385

Fe%	O%	%S	log(P _{O2})	log(P _{S2})
48.613	22.816	28.571	-11.046	-4.046
48.613	19.126	32.261	-11.000	-3.649
48.613	14.272	37.115	-10.979	-3.391
48.613	11.165	40.222	-10.699	-2.753
48.277	32.700	19.023	-10.699	-4.643
48.277	30.971	20.752	-10.301	-3.935
48.277	29.981	21.742	-10.155	-3.667
48.277	28.738	22.985	-10.046	-3.452
48.277	26.990	24.733	-10.000	-3.224
48.277	24.466	27.257	-10.000	-2.965
48.277	20.000	31.723	-10.000	-2.647
48.277	16.505	35.218	-10.000	-2.398

The conditions of iron addition and air rate required to produce the SO₂ levels shown in Table 4 were calculated for IBC -102 Coal from the composition points represented in Figure 3.

TABLE 4

Calculated Conditions for Combustion of IBC - 102 Coal in Contact with the Liquid Phase at 1200°C for the Given Compositions

Fe%	O%	S%	SO ₂ *	Fe ₃ O ₄ **	Air***
56.040	9.548	34.412	0.977	5.995	337.848
56.040	7.938	36.022	1.095	5.565	331.654
56.040	5.825	38.135	1.725	4.437	316.573
55.020	12.059	32.921	0.799	6.415	353.225
55.020	10.395	34.585	1.038	5.771	344.631
55.020	7.573	37.407	1.353	4.925	334.371
55.020	4.660	40.320	1.766	4.071	316.622

Fe%	O%	S%	SO ₂ *	Fe ₃ O ₄ **	Air***
53.740	15.012	31.248	0.708	6.741	365.705
53.740	13.287	32.973	0.889	6.127	362.088
53.740	10.388	35.872	1.357	5.010	354.581
53.740	7.767	38.493	1.813	4.106	344.761
53.740	5.146	41.114	2.422	3.140	331.036
53.740	2.813	43.447	3.512	1.777	317.800
52.340	17.894	29.766	0.715	6.881	381.423
52.340	16.110	31.550	0.876	6.255	377.564
52.340	14.078	33.582	1.276	5.325	371.697
52.340	10.388	37.272	1.806	4.139	364.138
52.340	7.379	40.281	2.571	2.949	353.523
52.340	3.883	43.777	4.619	0.545	341.283
51.230	20.878	27.892	0.662	7.274	392.296
51.230	19.054	29.716	0.873	6.505	392.304
51.230	15.922	32.848	1.271	5.335	386.039
51.230	13.107	35.663	1.869	4.154	380.418
51.230	9.515	39.255	2.632	2.892	373.178
51.230	5.922	42.848	4.397	0.781	363.609
51.230	3.883	44.887	5.139	0.000	354.206
50.000	24.391	25.609	0.699	7.668	404.568
50.000	22.804	27.196	0.892	6.907	406.045
50.000	19.223	30.777	1.325	5.480	401.222
50.000	15.631	34.369	1.989	4.052	398.451
50.000	12.233	37.767	2.758	2.786	395.432
50.000	8.350	41.650	4.489	0.686	391.463
50.000	4.369	45.631	5.139	0.000	381.386
49.320	27.167	23.513	0.644	8.340	410.515
49.320	25.937	24.743	0.764	7.715	411.875
49.320	24.067	26.613	0.935	6.891	409.299
49.320	21.068	29.612	1.365	5.559	407.427
49.320	17.476	33.204	2.041	4.068	405.740

Fe%	O%	S%	SO ₂ *	Fe ₃ O ₄ **	Air***
49.320	13.883	36.797	2.835	2.729	405.035
49.320	10.000	40.680	4.450	0.734	403.657
49.320	5.340	45.340	5.139	0.000	402.773
48.613	30.266	21.121	0.863	8.705	476.611
48.613	29.050	22.337	1.136	7.706	506.181
48.613	27.818	23.569	1.462	6.708	529.777
48.613	25.938	25.449	1.883	5.499	532.423
48.613	22.816	28.571	2.783	3.543	537.888
48.613	19.126	32.261	4.511	0.831	542.850
48.613	14.272	37.115	5.139	0.000	545.431
48.613	11.165	40.222	5.139	0.000	586.247
48.277	32.700	19.023	1.156	8.939	591.329
48.277	30.971	20.752	2.857	4.690	637.125
48.277	29.981	21.742	4.432	1.380	652.256
48.277	28.738	22.985	5.139	0.000	663.474
48.277	26.990	24.733	5.139	0.000	688.000
48.277	24.466	27.257	5.139	0.000	670.786
48.277	20.000	31.723	5.139	0.000	678.090
48.277	16.505	35.218	5.139	0.000	688.940

*SO₂ - Concentration: lb/mm BTU
 **Fe₃O₄ - Dosage: g/100g Dry Coal
 ***Air - Dosage: liter STP/100g Dry Coal

The results of the calculations are represented in a three-dimensional plot in Figure 4. In this plot the front corner of the diagram is the iron-corner with sulfur contents increasing from right to left and oxygen contents increasing from left to right. The vertical axis represents the calculated locus of off-gas sulfur concentrations. The lowest values of SO₂ contents is seen to be in the leading edge of the surface, which is also the limit of the liquid phase where it is in equilibrium with iron. Only here are values of SO₂ concentrations significantly below unity. For concentrations moving toward the back of the diagram, the sulfur contents are seen to rise dramatically. Clearly there is a narrow region of optimum composition.

Figure 3. Isothermal Section of Fe-O-S System at 1200°C Showing Region of Iron Oxysulfide Liquid Reported by Data in Tables 3 and 4.

Figure 4. Isothermal Section of Fe-O-S System at 1200°C in Three-Dimensional Representation. Calculated Concentrations of SO₂ are for Conditions of Stoichiometric Combustion of IBC-102 Coal.

EXPERIMENTAL STUDIES

Experimental studies have already begun; however, initial work was temporarily suspended until an improved ventilation system was developed to avoid the possibility of leaks in the gas system which contains hydrogen and hydrogen sulfide. These modifications have been completed, and studies are now continuing with emphasis on extending the temperature range to higher values such as 1300° and 1400°C.

It was decided to employ only hydrogen, water vapor and hydrogen sulfide in the gas stream and producing the necessary components for equilibration with iron.

Figure 5 is a schematic diagram of the apparatus which is being used. The ratio of hydrogen flow rates to hydrogen sulfide is carefully monitored by calibrated flowmeters, and the hydrogen is water saturated in a constant temperature bath to the required dewpoint to produce a desired oxygen potential according to the reaction:

where $\underline{\text{O}}$ represents oxygen dissolved in the oxysulfide phase.

On-stream determination of the sulfur and water contents is accomplished by a gas chromatograph. The gases are then passed into a tube furnace in which the sample is equilibrated. Samples are quenched in argon and analyzed for their composition. Off gases are passed through a copper sulfate scrubber and vented from the system.

Figure 5. Schematic Diagram Fe-O-S Equilibration System.

REFERENCES

1. Turkdogan, E.T. and Kor, G.J.W., "Sulfides and Oxides in the Fe-Mn Alloys: Part I, Phase Relations in the Fe-Mn-S-O System," Metallurgical Transactions, Vol. 2, June 1971, pps. 1561-1578.
2. Turkdogan, E.T., "Physico-Chemical Properties of Molten Slags and Glasses, The Metals Society, London (1983), pps. 143-151.
3. Stofko, M., Schmiedl, J., and Rozenqvist, T., "Thermodynamics of Iron-Sulfur-Oxygen Melts at 1200° C," Scand. J. Metallurgy, Vol. 3, (1974), pps. 113-118.

APPENDIX A

Calculations:

Extrapolation of Data using Regular Solution Model

[2] Regular Solution Model

Definition: Entropy of mixing is equal to the ideal configurational entropy.

The enthalpy of mixing varies with composition for a ternary system:

$$\Delta H = \frac{a_{12}n_1n_2 + a_{13}n_1n_3 + a_{23}n_2n_3}{n_1 + n_2 + n_3}$$

n_1, n_2, n_3 - moles of components 1, 2 and 3 per unit volume of solution.

a_{12}, a_{13}, a_{23} - constants for the binary systems 1-2, 1-3, and 2-3 at constant temperature and pressure.

Partial differentiation:

$$\left(\frac{\partial H}{\partial n_1}\right)_{n_2, n_3} = \frac{-a_{23}n_2n_3 + (n_2 + n_3)(a_{12}n_2 + a_{13}n_3)}{(n_1 + n_2 + n_3)^2}$$

Since the entropy of mixing is assumed to be ideal, the partial molar excess free energy of solution of components 1, 2, 3 are given:

$$RT \ln \gamma_1 = a_{12}X_2^2 + a_{13}X_3^2 + (a_{12} + a_{13} - a_{23})X_2X_3$$

$$RT \ln \gamma_2 = a_{12}X_1^2 + a_{23}X_3^2 + (a_{12} + a_{23} - a_{13})X_1X_3$$

$$RT \ln \gamma_3 = a_{13}X_1^2 + a_{23}X_2^2 + (a_{13} + a_{23} - a_{12})X_1X_2$$

where the activity coefficients γ_i are relative to the pure liquid components are X_i the mole fraction $X_i = n_i / (n_1 + n_2 + n_3)$.

[3] Analysis of Best Fit

Designating: 1 - S, 2 - O, 3 - Fe

For the reactions:

$$a_{\text{FeS}} = K_s a_{\text{Fe}} a_{\text{S}} = K_s \gamma_{\text{Fe}} X_{\text{Fe}} \gamma_{\text{S}} X_{\text{S}}$$

$$a_{\text{FeO}} = K_o a_{\text{Fe}} a_{\text{O}} = K_o \gamma_{\text{Fe}} X_{\text{Fe}} \gamma_{\text{O}} X_{\text{O}}$$

$$P_{\text{O}_2} = K_{\text{O}_2}^2 a_{\text{O}} = K_{\text{O}_2}^2 \gamma_{\text{O}}^2 X_{\text{O}}^2$$

For simplification, the data was only fitted for a_{FeS} .

$$RT \ln a_{FeS} = RT \ln K_s + RT \ln X_{Fe} X_S + (a_{12} + a_{23}) X_O^2 + a_{13} (X_S^2 + X_{Fe}^2) \\ + (a_{12} + a_{13} - a_{23}) X_O X_{Fe} + (a_{13} + a_{23} - a_{12}) X_O X_S$$

Putting the above equation and 32 point data from Stofko³ into a best fit program, one obtains the constants K_s , a_{12} , a_{13} , and a_{23} at the temperature of 1200 °C.

$$\ln a_{FeS} = 0.60169 + \ln X_{Fe} X_S + 2.322832 X_O^2 + 1.421125 (X_S^2 + X_{Fe}^2) \\ + 0.736121 X_O X_{Fe} + 2.106129 X_O X_S$$

Through a comparison of calculated results with the data, one sees that when $X_{Fe}=0.5$, the pseudo-binary system FeS-FeO yields a good fit of the data.

$X_{Fe} > 0.5$, there are some negative deviations.

$X_{Fe} < 0.5$, there are some positive deviations.

[4] The data for calculation

From the reactions:

$$P_{S_2} = \left(\frac{K_2}{K_1} \right)^2 \left(\frac{a_{FeS}}{a_{FeO}} \right)^2 P_{O_2}$$

Under different composition of Fe-S-O system, Using the data P_{O_2} , a_{FeS} , and a_{FeO} , calculate the pressure of sulfur: P_{S_2} .

[5] Calculation of Fe-Liquid (Fe-S-O) as a sorbent of sulfur in coal:

Tables 1 and 2.

Figures 1 and 2

[6] Through analysis, we know that the systems FeO-Liquid and Fe_3O_4 -Liquid as sorbents are not suitable for our research.

[7] Calculation of Liquid as a sorbent at 1200°C.

Tables 3 and 4

Figure 3 and 4

END

**DATE
FILMED
9/22/92**