370
6/24/85

Operated by
Westinghouse
Hanford Company
for the USDOE

A subsidiary of
Westinghouse Electric
Corporation

NE Standards Transmittal

A subsidiary of
Westinghouse Electric
Corporation

P. O. Box 1970
Richland, WA 99352

Hanford Engineering Development Laboratory

NE-F--11-3T-Rev.3/85

DE93 011212

DISTRIBUTION	DATE May 29, 1985		NO. 287	
	RETURN COMMENTS TO	TYPE SUBMISSION	TYPE ACTION	
	J.J. McCown Westinghouse Hanford Co. P.P. Box 1970 Richland, WA 99352	☐ 1. PRELIMINARY ☐ 2. DRAFT ☒ 3. TENTATIVE ☐ 4. FINAL ☒ 5. REVISION	☐ A. APPROVAL ☐ B. INFORMATION ☐ C. COMMENTS ☒ D. TRIAL USE ☐ E.	
	NOT LATER THAN			
List 01 05	NUMBER	DESCRIPTION		ACTION
		NE F 11-3T Analytical Chemistry Methods for Metallic Core Components. March 1985		D

MASTER

REPRODUCTION OF THIS DOCUMENT IS UNLIMITED

SIGNATURE

Roger G. Imada

FOREWORD

This standard supersedes the September 1975 issue and Amendment 1 (4/25/77) of RDT F 11-3T and incorporates those changes that were approved for publication in this revision. These changes are identified by the following marginal notations:

A1	Amendment 1, (4-25-77)
C	Change approved 3-27-85
D	Deletion approved 3-27-85
N	Addition approved 3-27-85

Editorial changes that were made during preparation of this revision are not identified.

The methods in this revision are presented in one of the following forms:

1. Referenced to appropriate ASTM standard(s),
2. Kept intact as existing in the September 1975 issue and Amendment 1, or
3. Revision of the September 1975 method.

Five methods are in Category 1. Four are in Category 2 because they do not exist in appropriate ASTM standards. One existing method is revised by referencing sections to appropriate sections in another method.

March 1985

i

i

ANALYTICAL CHEMISTRY METHODS FOR METALLIC CORE COMPONENTS

TABLE OF CONTENTS

	<u>Page</u>	
1. SCOPE	1	
2. APPLICABLE DOCUMENTS	1	
3. GENERAL REQUIREMENTS	2	
4. CHROMIUM	4	
5. NICKEL	9	
6. CARBON	10	
7. ANALYSES BY X-RAY FLUORESCENCE SPECTROMETRY	10	
8. ANALYSES BY DIRECT READING EMISSION SPECTROSCOPY	14	
9. NITROGEN	20	
10. PHOSPHORUS	20	
11. SULFUR	20	
12. SURFACE CHLORIDE AND FLUORIDE USING THE SWAB TEST	20	A1
13. SURFACE CHLORIDE AND FLUORIDE BY WASH METHOD	30	C
14. ORDERING DATA CHECKLIST	35	

March 1985

1

35

ANALYTICAL CHEMISTRY METHODS FOR METALLIC CORE COMPONENTS

1. SCOPE

This standard provides analytical chemistry methods for the analysis of alloys used to fabricate core components. These alloys are 302, 308, 316, 316-Ti, and 321 stainless steels and 600 and 718 Inconels and they may include other 300-series stainless steels.

2. APPLICABLE DOCUMENTS

The following documents are a part of this standard to the extent specified herein. The issue of a document in effect on the date of the invitation to bid, including any amendments also in effect on that date, shall apply unless otherwise specified. Where this standard appears to conflict with the requirements of a reference document, such conflicts shall be brought to the attention of the purchaser for resolution.

2.1 American Society for Testing and Materials (ASTM) Standards.

ASTM E 55	Sampling Wrought Nonferrous Metals and Alloys for Determination of Chemical Composition
ASTM E 59	Sampling Steel, Cast Iron, Open-Hearth Iron, and Wrought Iron for Determination of Chemical Composition
ASTM E 116	Recommended Practice for Photographic Photometry in Spectrochemical Analysis
ASTM E 200	Preparation, Standardization and Storage of Standard Solutions for Chemical Analysis
ASTM E 350	Standard Methods for Chemical Analysis of Carbon Steel, Low-Alloy Steel, Silicon Electrical Steel, Ingot Iron, and Wrought Iron
ASTM E 354	Standard Methods for Chemical Analysis of High-Temperature, Electrical, Magnetic, and other Similar Iron, Nickel, and Cobalt Alloys

2.2 National Bureau of Standards (NBS).

NBS Circular 547	Section 1, Precision Laboratory Standards of Mass and Laboratory Weights
NBS Circular 602	Testing of Glass Volumetric Apparatus

NNN-P-390 Pipet, Volumetric; Micro, Kirk Design

ANSI/ASME NQA-1 Quality Assurance Program Requirements for Nuclear
Facilities

3.1 Analytical Methods. The analytical methods in this standard are approved methods and they describe acceptable equipment and procedures for use by trained analysts. Other methods approved by the purchaser may be used. Identification of brand names and model numbers are for information; equivalent equipment may be used instead. Special safety precautions are noted where appropriate.

3.2 Tolerances. Unless otherwise specified, all values for measurements stated in the methods (volume, weight, time, temperature, etc.) are nominal values. The actual measurements used, however, shall be within +5 % of the stated value. For example, "add 20 mL" means that a volume between 19 and 21 mL shall be added. Required tolerances are specified in one of the two following ways:

1. Tolerance limits are given with the value. For example, 15 ± 0.1 mL, $1 \text{ h} \pm 10 \text{ min}$, or "take a 50-mg sample weighed to ± 0.1 mg."
2. When one or more significant figures are given to the right of the decimal point, the tolerance limit is ± 5 in the next digit located beyond the last one stated. For example, 5.0 mL means 5.0 ± 0.05 mL.

3.3 Laboratory Qualification. The qualification of an analytical laboratory shall be based upon its demonstrated competence to do the specified analyses of metallic core components. Specific requirements shall be agreed to between purchaser and supplier.

3.4 Quality Assurance. Each analytical laboratory shall maintain its own internal quality assurance program that is designed to unequivocally demonstrate that it is in control of its methods at all times. An analytical laboratory quality assurance program shall contain written procedures for implementation of 3.4.1, 3.4.2, 3.4.3, 3.4.4, and 3.4.5 as a minimum. The quality assurance program shall be based on ANSI/ASME NQA-1 Basic Requirements 1, 2, 5, 6, 8, 9, 10 and 12 through 17.

3.4.1 Documentation. A system of documentation shall be established to record all actions taken relating to quality assurance and to provide for traceability of each reported analysis back to the raw laboratory data from which the analysis was obtained. The system shall

provide for identification and control of each sample from the time it is received by the laboratory until all required analyses are completed. All data obtained from calibration and quality control standards shall be recorded and shall be easily retrievable. Records shall be retained a minimum of 3 years.

3.4.2 Quality Control. Each analytical laboratory shall have an internal system of quality control covering the analytical methods used, unless the purchaser imposes a quality control system. A purchaser quality control system imposed by the contract shall supersede a supplier's quality control system. If not otherwise stated in a method herein, calibration standard(s) and calibration frequency shall be agreed to between purchaser and supplier for each method.

3.4.3 Qualification of Analysts. The qualification of each analyst in the analytical laboratory to perform analyses shall be certified by laboratory supervision. Criteria shall be established governing qualifications for using the analytical methods and each analyst shall be evaluated and certified accordingly.

3.4.4 Equipment. Equipment that could affect the quality of measurements shall be calibrated and controlled. Analytical balances shall be maintained on a routine calibration schedule and shall be calibrated with weights meeting the tolerances of Class S weights (NBS Circular 547). Unless otherwise specified in a method, volumetric glassware such as volumetric flasks, transfer pipets, and burets shall meet the tolerance requirements specified by NBS Circular 602. Rules for manipulation relating to the calibration of volumetric glassware are given in Circular 602 and these rules, when applicable, shall be observed in using volumetric glassware for analyses. Micro (lambda) pipets shall meet tolerances specified in Federal Specification NNN-P-390.

3.4.5 Reagents and Standards. When reagents and standards are prepared, provisions for preparation found in ASTM E 200 shall be followed.

a. Quality of Chemicals. Unless otherwise specified in a method, all chemicals used shall be reagent grade or equivalent. All water used for preparation of reagents shall be distilled or deionized reagent water meeting ASTM D1193, Type IV. Where a method has special requirements for a specific constituent, the use of Type IV water shall be extended by adding to the specification a maximum concentration for that constituent.

b. Labeling. All reagents and standards shall be labeled with the following information:

1. Name.
2. Concentration.

3. Matrix (if other than water).
4. Date prepared and by whom.
5. Special limitations, such as storage stability.

Improperly labeled reagents and standards shall be discarded.

c. Storage. Reagents shall be stored in containers that do not affect the quality. Particular care shall be taken to use containers that do not affect concentration by evaporation or transpiration and that prevent contamination.

3.5 Sampling and Sample Preparation.

3.5.1 Sampling. Unless otherwise specified in a method, sampling shall be in accordance with ASTM E 55 or E 59 as appropriate.

3.5.2 Sample Preparation. Except for Methods 12 and 13, samples shall be cleaned prior to analysis to remove possible foreign materials such as oil, grease, and dirt. The samples shall be washed with a suitable organic solvent, rewashed with alcohol, and then dried at room temperature either by evaporation in air or under vacuum. C

4. CHROMIUM

4.1 Application. This method is generally applicable to 300-series stainless steels and Inconels 600 and 718. The amount of sample recommended for analysis is between 0.2 and 0.3 g.

4.2 Summary. Samples are dissolved in appropriate acid mixtures. The chromium is oxidized to the hexavalent state with ammonium persulfate using silver as a catalyst, after which any permanganate and manganese dioxide present are reduced with hydrochloric acid. The hexavalent chromium is titrated potentiometrically with standard ferrous ammonium sulfate solution.

4.3 Interferences. Vanadium, if present, will be titrated with chromium. At the specification limit of 0.2 % maximum for vanadium in the applicable steels, the effect of vanadium is equal to 0.068 % chromium ($V, \% \times 0.34 = Cr, \%$) which is a significant error in the chromium analysis. Below 0.1 % vanadium, however, the error becomes insignificant and can be disregarded. Carbides, if present, must be completely dissolved during dissolution of the samples to avoid low results for chromium.

4.4 Apparatus.

a. Buret. Each buret used shall be calibrated to meet the specification requirements of NBS Circular 602 or its replacement. Subdivisions in millilitres shall be no larger than 0.1 mL for 25-mL and larger

burets and they shall be no larger than 0.05 mL for burets smaller than 25 mL.

b. Calomel electrode.

c. pH meter, capable of measuring ± 1 mv. The specific instrument used depends upon the mode of titration and end point detection.

d. Platinum electrode.

4.5 Reagents and Standards.

a. Ammonium persulfate.

b. Ferrous ammonium sulfate, 0.1N, standardized. Dissolve 39.2 g of ferrous ammonium sulfate in 500 mL of cold 1M sulfuric acid, dilute to 1 litre with 1M sulfuric acid, and mix thoroughly.

c. Hydrochloric acid, 3M.

d. Hydrofluoric acid, 28M (48%).

e. Nitric acid, 15.6M (70%).

f. Perchloric acid, 11.6M (70%).

g. Phosphoric acid, 14.7M (85%).

h. Potassium dichromate, 0.1N. Dissolve in water about 4.9 g of potassium dichromate (NBS SRM 136C or its replacement) weighted to ± 0.1 mg, dilute to 1 litre with water, and mix thoroughly. Calculate the normality according to Equation 3.

i. Potassium permanganate, 0.16M (25 g/L).

j. Silver nitrate, 0.06M (10 g/L).

k. Sulfuric acid, 3.6M and 9M.

l. Steel standard, NBS SRM 160 or its equivalent.

4.6 Calibration. The 0.1N ferrous ammonium sulfate shall be standardized against the 0.1N potassium dichromate prepared from NBS SRM 136. A standardization shall be done each 8-h shift in which chromium analyses are made and shall consist of at least four titrations, with a standard deviation no larger than 0.0001N. In addition, the NBS SRM 160 steel standard or its equivalent shall be analyzed at least once each 8-h shift according to 4.7.1. If the result does not agree to within ± 0.2 % (absolute) of the NBS certified value, investigate and correct the problem before continuing the analysis of samples. Standardize the ferrous ammonium sulfate as follows:

- a. Assemble the electrodes and pH meter.
- b. Turn on the meter and allow the system to stabilize (meter stops drifting).
- c. Add 350 mL of water and 75 mL of 3.6M H_2SO_4 to a 600-mL beaker.
- d. Add an accurately measured volume of at least 10 mL of 0.1N potassium dichromate.
- e. Place the electrodes into the solution.
- f. Stir the solution and titrate to a potentiometric end point with the 0.1N ferrous ammonium sulfate.
- g. Calculate the normality of the ferrous ammonium sulfate according to Equation 2.

4.7 Analysis.

4.7.1 Stainless Steel Analysis.

- a. Prepare a sample according to 3.5 and add to a 600-mL beaker between 0.2 and 0.3 g weighed to ± 0.1 mg.
- b. Add 75 mL of the 3.6M H_2SO_4^* to the beaker.
- c. Cover the beaker with a cover glass; place it on a hot plate and heat until the sample dissolves completely.

Sufficient heat should be used to keep the solution boiling slowly.

- d. Remove the cover glass, rinsing the underside with a small amount of water to wash the condensate into the beaker.
- e. Evaporate the solution just to the point that either fumes of H_2SO_4 or salts begin to form; remove the beaker from the hot plate and cool to room temperature.
- f. Carefully add 50 mL of water and warm the solution if necessary to dissolve any salts.

*The mixture of HCl and HNO_3 used in the nickel method (5.) can be used to dissolve steel samples for the chromium analysis. After dissolution, the solution must be taken to fumes of H_2SO_4 to remove chloride prior to the addition of silver nitrate (Step j).

If the salts do not dissolve, discard the sample and begin again. Prolonged evaporation at Step e can cause the formation of basic sulfate salts that do not dissolve readily.

- g. Carefully add 2 mL of 15.6M HNO_3 and 3 or 4 drops of 28M HF.
- h. Evaporate until the H_2SO_4 just starts to fume.

If a dark residue is evident, carbides may not have dissolved. To dissolve the residue, carefully add 50 mL of water to the cooled solution and 10 mL of 15.6M HNO_3 . Boil the solution until the residue is dissolved and then evaporate just to fumes of H_2SO_4 . Continue at next step (Step i).

- i. Cool the beaker and its contents to room temperature and then carefully add 300 mL of hot water.

- j. Add 10 mL of 0.06M silver nitrate and 15 g of ammonium persulfate; boil the solution for at least 15 min.

In this step, chromium is oxidized to the hexavalent state. Excess ammonium persulfate must be added. The excess is destroyed by boiling the solution. Boiling as long as 30 min does no harm,* although the volume of solution should be maintained around 300 mL.

The formation of the typical permanganate color or manganese dioxide from the manganese in the steel indicates that oxidation has occurred. If the H_2SO_4 concentration exceeds about 10 mL per 100 mL of solution, the oxidation of chromium will be retarded.* The use of old ammonium persulfate will also retard the oxidation.

- k. Add 5 mL of 3M HCl and continue to boil the solution for 5 min after the permanganate color disappears.

If the permanganate color or manganese dioxide does not disappear after about 10 min, add another 2 or 3 mL of HCl and continue boiling.

- l. Cool the solution to room temperature and add 100 mL of water.
- m. Place the electrodes into the solution.

At this point the electrodes and pH meter should be assembled, the meter turned on, and the system stabilized from the prior standardization of the titrant. See 4.6.

*G. E. F. Lundell, J. I. Hoffman, and H. A. Bright. Chemical Analysis of Iron and Steel, John Wiley & Sons, Inc., N.Y., p. 292, 1931.

n. Stir the solution and titrate the hexavalent chromium to a potentiometric end point with 0.1N ferrous ammonium sulfate.

o. Record the volume of titrant used.

4.7.2 Inconel Analysis.

a. To a 500-mL Erlenmeyer flask, add between 0.2 and 0.3 g of sample weighed to ± 0.1 mg.

The sample is taken and prepared according to 3.5.

b. Add 10 mL of 11.6M HClO₄ and 10 mL of 14.7M H₃PO₄.

c. Heat the acid mixture on a hot plate to dense fumes and continue heating for 3 or 4 min after the sample has dissolved.

Fuming with perchloric acid will oxidize most of the chromium to the hexavalent state.

Chloride must be absent to avoid volatilizing chromium as chromium oxychloride.

d. Cool the solution to room temperature and transfer it to a 600-mL beaker using 100 mL of hot water.

e. Cover the beaker with a cover glass and boil the solution on a hot plate for several minutes to expel free chlorine.

f. Remove the beaker from the hot plate and add 20 mL of 9M H₂SO₄ and 5 mL of 15.6M HNO₃.

g. Add 150 mL of hot water and continue the analysis at Step j through Step o of 4.7.1 with the following exceptions at Step j:

1. Add also 5 or 6 drops of the 0.16M potassium permanganate solution.
2. Add only 3 g of ammonium persulfate.

Most of the chromium is already at the hexavalent state from fuming the sample in perchloric acid at Step c.

4.8 Calculation. Calculate the concentration of chromium in the sample and the normality of the ferrous ammonium sulfate and potassium dichromate using the appropriate equation below.

a. Concentration of chromium in sample.

$$\text{Chromium} = \frac{VNE}{W} \times 100 \quad (1)$$

where

Chromium = weight percent chromium in sample

V = millilitres of ferrous ammonium sulfate (Step o of 4.7.1)

N = normality of ferrous ammonium sulfate

E = milliequivalent weight of chromium (0.01733)

W = sample weight in g.

b. Normality of ferrous ammonium sulfate.

$$N = \frac{AB}{C} \quad (2)$$

where

N = normality of ferrous ammonium sulfate

A = millilitres of potassium dichromate (Step d of 4.6)

B = normality of potassium dichromate

C = millilitres of ferrous ammonium sulfate (Step f of 4.6).

c. Normality of potassium dichromate.

$$B = \frac{w}{ev} \quad (3)$$

where

B = normality of potassium dichromate

w = weight of potassium dichromate used in g

e = equivalent weight of potassium dichromate
(49.0320)

v = volume of solution used (1 litre).

4.9 Precision. The relative standard deviation of the method is 0.5 % or less.

5. NICKEL

This method for determining nickel in stainless steel and Inconel shall be in accordance with ASTM E 354.

C

nuclear
ASTM E 354-70

6. CARBON

This method for determining carbon in stainless steel and Inconel shall be in accordance with ASTM E 354.

C

7. ANALYSES BY X-RAY FLUORESCENCE SPECTROMETRY

7.1 Application. This method is for the determination of columbium, tantalum, and arsenic in stainless steels and for columbium and tantalum in Inconel 718. Concentrations from about 0.01 % to several percent can be measured depending upon the selection of suitable standards.

7.2 Summary. A sample with a clean and uniform surface is irradiated by a high intensity X-ray beam. The secondary X-rays produced are dispersed by a crystal and their intensities are measured at selected wavelengths. Concentrations of elements are determined from a calibration curve that relates X-ray intensities to concentration.

7.3 Interferences. The arsenic $K\alpha$ line is seriously overlapped by the lead $L\alpha_1$ line and the tantalum $L\beta_1$ line is overlapped by the tungsten $L\beta_1, \beta_4$ lines. Lead and tungsten, therefore, are serious interferences.

7.4 Apparatus.

- a. Belt (or disc) sander, with 80-to 120-grit and 400-to 600-grit abrasive paper.
- b. X-ray spectrometer, having the following components:
 1. Analyzing crystal, lithium fluoride.
 2. Collimator. Sufficient collimation is required before and after the analyzing crystal to obtain complete resolution of two strong lines separated by a 2θ angle of 0.80° .
 3. Detector, scintillation counter.
 4. Goniometer, a wide-range goniometer providing a 2θ angular scan from 0 to 165° .
 5. Optical path, air. Vacuum or helium will increase intensity of Ta slightly.
 6. Pulse height discriminator.
 7. Sample holder, in which samples can be positioned reproducibly under a mask which allows the same amount of surface from each sample to be exposed to the X-ray beam and collimators.

8. X-ray generator, with full wave rectified or constant potential power supply.
9. X-ray tubes, tungsten and molybdenum anodes. Use the tungsten tube for the columbium analyses and the molybdenum tube for the arsenic and tantalum analyses.

7.5 Reagents and Standards.

7.5.1 Reagents. None are required.

7.5.2 Standards. Standards shall have a composition similar to that of the samples analyzed and the same metallurgical history as the samples. The definition of similar shall be agreed upon by the supplier and purchaser. Whenever possible, standards shall be appropriate NBS SRMs. Where an appropriate NBS SRM is not available, the supplier shall provide a suitable standard from another source, subject to the purchaser's approval. The source and history of each non-NBS standard shall be provided to the purchaser.

7.6 Calibration. A standard is analyzed according to 7.7, either immediately following a sample or midway in a series of samples. The calibration coefficient is calculated for each element according to Equation 4. See 7.8 (c) 2 and 4 for special measurements.

7.7 Analysis. The size of each sample and standard shall be sufficient to fit the particular sample holder used. Samples in the form of small pieces or wire shall be arc melted according to 8.7 to give a single piece of appropriate size. Sampling shall be in accordance with 3.5.

a. Prepare a clean and smooth surface on the samples and standards using 80- to 120-grit abrasive paper first and then finish with 400- to 600-grit paper.

Standards are repolished as needed to remove oxidized surfaces.

b. Turn on the X-ray generator and the X-ray beam using the following conditions as guidelines:

Constant Potential

33KV, 60MA

Full-Wave Rectification

50KV, 40MA

The generator should be turned on 30 min and the X-ray beam 15 to 20 min before starting analyses to stabilize temperature and X-ray intensity.

c. Check as follows the exact 2θ angles at which Cb, Pb, As, and Ta fluorescences reach their maximum, using any materials containing rather high concentrations of the elements as samples:

1. Move the goniometer manually while scanning across a fluorescence peak from part way down one side of the peak to an equal distance down the other side.
2. Average the angular readings on each side of the peak at which the intensities are the same. Use these averages as the goniometer setting for analyses.

Once these settings are established, it may be sufficient to check only the Cb setting each day analyses are made. If this setting changes, then the settings for the other elements and backgrounds should be changed an equal amount.

d. Adjust the high voltages so that the fluorescence energies from the Cb, Pb, As, and Ta peaks fall in the middle of the 5-V window of the pulse height discriminator.

e. Place a sample into the sample holder and measure the X-ray intensities at the appropriate goniometer settings using the following condition as guidelines:

Pulse height window, 5V
 Counting time, 30 s
 Order of reading, see Table 1

7.8 Calculation. Calculate the calibration coefficients and concentration of elements in the sample using the appropriate equations below.

a. Calibration coefficient

$$C = \frac{S}{I_s - B_s} \quad (4)$$

where

C = calibration coefficient for an element

S = weight percent of that element in the standard

I_s = intensity (counts) obtained for that element from the standard

B_s = background (counts) for that element from the standard (see 7.8 (c) below).

b. Concentration of element in sample.

$$E = (I_u - B_u) C \quad (5)$$

Table 1. Reading Conditions

Reading	2 Angle	Wavelength (Å)	Typical Intensity ^a (c/s)	Number of Repeated Counts ^b
Background 1	19.50	0.682	150	3
Cb, K α	21.40	0.748	1,850	3
Background 2	22.35	0.780	140	3
Background 3	27.40	0.954	120	4
Pb, L $\beta_{1,2}$	28.25	0.982	530	4
Background 4	29.10	1.012	90	4
Background 5	33.20	1.150	55	4
As, K α	34.00	1.177	700	4
Background 6	34.80	1.204	45	4
Ta, L β_1	38.48	1.327	90	5
Background 7	40.00	1.361	45	4

^aBased on 316 stainless steel.

^bExcept for very low count rates, the largest source of variation is usually fluctuations in the intensity of the primary X-ray beam. Therefore, it is better to take several short counts instead of one long count to observe the reproducibility of the counts. This column suggests the number of repeated counts for each reading, although more may be required to obtain average values of higher reliability.

where

E = weight percent of an element in the sample

I μ = intensity (counts) obtained for that element from the standard

B μ = background (counts) for that element from the sample (see 7.8 (c) below).

C = calibration coefficient for that element.

In addition to subtracting B μ , I μ for arsenic must be corrected for lead (see 7.8 c).

c. Special notes on background.

1. Columbium. The fluorescence peak is on top of a sloping background that makes it necessary to measure the background on each side. Since background 1 (see 7.7 e) is twice as far from the Cb peak as background 2, the background at the Cb peak is equal to $Bkg\ 2 + 1/3 (Bkg\ 1 - Bkg\ 2)$.
2. Lead. The Pb $L_{\beta 1,2}$ line (see 7.7 e) is measured to determine the Pb $L_{\alpha 1}$ overlap at the As peak. The background to subtract from the Pb $L_{\beta 1,2}$ measurement is equal to $1/2 (Bkg\ 3 + Bkg\ 4)$. The relationship between Pb $L_{\alpha 1}$ overlap at the As peak (34.00°) to the Pb $L_{\beta 1,2}$ peak is established with a lead-containing standard during calibration.
3. Arsenic. The background at the As peak has a slight slope. Accuracy is not significantly affected by making only one background measurement at 33.20° (background 5, see 7.7 e). If background 6 is smaller than background 5, use the average of the two for background correction. If background 6 is not smaller than background 5, use only background 5. Correct the arsenic intensity for the calculated overlap from the lead $L_{\alpha 1}$ line.
4. Tantalum. Background 7 is used with the tantalum $L_{\beta 1}$ line.

7.9 Precision. The relative standard deviations for the analyses are 5 % or less, depending upon such factors as concentration levels and the condition of sample surfaces.

8. ANALYSES BY DIRECT READING EMISSION SPECTROSCOPY

8.1 Application. This method is for the determination of various elements in 300-series stainless steels and in Inconels 718 and 600 as specified by the purchaser. Elements included are aluminum, boron, cobalt, copper, iron, manganese, molybdenum, silicon, titanium, and vanadium. The concentration ranges covered vary between 0.001 and several weight percent, depending upon the element, available standards, and specification requirements.

8.2 Summary. Elements are determined by a direct reading emission spectrometer interfaced with a computer. The Point-to-Plane technique* is used in which the sample becomes an electrode in a spark or uni-arc discharge. The computer controls calibration and computes concentrations in weight percents, which are printed on a teletypewriter.

*See ASTM E 327 as a general reference.

8.3 Interferences. In general, with the materials stated in 8.1, interferences are not expected.

8.4 Apparatus.

- a. Arc melting furnace.¹
- b. Belt (or disc) sander, with 50- to 100-grit sanding paper.
- c. Computer, PDP 8/L, Digital Equipment Corp or its equivalent.
- d. Counter electrodes, a hemispherical tipped graphite rod for spark discharge (Ultra 132307 or its equivalent) and a 3.2-mm diameter graphite rod for uni-arc discharge (Ultra 110402 or its equivalent).
- e. Direct reading optical emission spectrometer with a high speed digital readout system and a power supply.² The spectrometer should have a reciprocal linear dispersion in the first order of 5Å/mm or less.
- f. Teletypewriter, Teletype Corp (Model ASR 35) or its equivalent.
- g. Ultrasonic cleaner.

8.5 Reagents and Standards.

8.5.1 Reagents.

- a. Argon, prepurified grade³ or equivalent.
- b. Isopropyl alcohol.

8.5.2 Standards. When the specification for an element covers a concentration range from a lower to an upper limit, calibration shall be made with at least three standards to give calibration points that cover the specification range. When a maximum concentration limit is specified for an element, at least two calibration standards shall be used. One standard shall provide a calibration point that is between 10 % (relative) below and a factor of 2 above the maximum limit and another standard shall provide a point that is at least one fourth of

¹A furnace made by the Pitchford Manufacturing Corp (Model 701) has been used successfully.

²Baird-Atomic equipment has been used successfully. That consists of a spectrometer (Model HB-2), a readout system (Model RS-1), and a source (Model RE-1).

³Matheson Gas Data Book, The Matheson Co., Inc., East Rutherford, N.J., 4th Ed., 1966.

the limit. For stainless steels, the standards shall have the composition of a 300-series stainless steel. For the Inconels, the compositions of the standards shall be similar to the composition of the particular Inconel being analyzed. The definition of similar shall be agreed upon by supplier and purchaser. Whenever possible, standards shall be appropriate NBS standards. Where an appropriate NBS standard is not available, the supplier shall provide a suitable standard from another source, subject to the purchaser's approval. The source and history of each non-NBS standard shall be provided to the purchaser.

8.6 Calibration. Standards are analyzed according to 8.7. If the physical form of a standard does not meet the size requirements given in 8.7, the standard is melted into a button of appropriate size. If samples are melted into buttons, then the calibration standards used should be treated the same regardless of size measurements. Calibrate as follows:*

8.6.1 Initial Calibration.

- a. Analyze the appropriate number of calibration standards for each element (see 8.5.2) and the selected reference materials (see the first note of Step a of 8.6.2).

Separate calibrations are made for spark and uni-arc analyses.

- b. Store the calibration data in the computer.

8.6.2 Daily Standardization and Calibration Check.

- a. Standardization. Standardize the instrument in each 8-h shift during which samples are analyzed using a designated reference material in Standard Block 1 for spark analyses and in Standard Block 2 for uni-arc analyses.

Reference materials shall be similar in composition to the sample materials. Samples can be used for references. If a single reference material contains measurable amounts of each element being determined, only one reference is needed. Otherwise, a combination of reference materials are required to cover all elements being determined. The reference materials shall be analyzed at the time of initial calibration (see Step a of 8.6.1).

*The calibration Steps are based upon the Baird-Atomic direct reader, Model HB-2, interfaced with a computer. If other instruments are used, calibration techniques may vary. Regardless of the technique used, calibration shall be checked in each 8-h shift during which samples are analyzed and if it differs from the initial calibration at the 0.05 significance level, the problem shall be resolved before analyzing samples.

The computer adjusts the instrument calibration according to the results from the analysis of the reference materials.

b. Calibration Check. Analyze a sufficient number of calibration standards after standardization (Step a of 8.6.2) to give at least one result for each element being determined. If a result differs from the previous calibration at the 0.05 significance level, investigate and resolve the problem before completing the analysis of samples.

8.7 Analysis.* Samples and standards shall be at least 0.62-cm thick with a flat surface at least 2.5-cm by 1.3-cm (or 2.5-cm diameter). A minimum thickness is required to dissipate the heat formed during the spark or uni-arc discharge. Maximum dimensions are 3.8-cm thick and 15-cm by 10-cm (or 10-cm diameter). For samples that meet the above size requirement, start the analysis at Step e. Samples and standards that do not meet the above size requirements shall be arc melted into a button of appropriate size by starting at Step a. Sampling shall be in accordance with 3.5.

a. Add 45 to 50 g of material to the sample cup, using pieces weighing no more than 5 g each.

This amount of material will give a button about 3 cm in diameter and 0.6-cm thick.

b. Place the cup containing the material into the furnace.

c. Close the furnace, flush the system with argon, and turn on the furnace for 20 to 30 s or until the material has melted completely.

d. Let the button cool to room temperature before removing it from the furnace.

Removing the button while hot may cause the material to oxidize.

e. Grind the flat surface of the sample (or standard) to a smooth finish using the belt (or disc) sander.

Grinding should be done until all visible pits and roughness are removed.

*The analysis is based upon the Pitchford Manufacturing Corp arc furnace, Model 701 and the Baird-Atomic direct reading emission spectrometer, Model HB-2. If other equipment is used, follow the manufacturers' recommended procedures.

f. Clean the sample (or standard) for 2 to 3 min in the ultrasonic cleaner containing water; repeat with isopropyl alcohol and air dry the sample.

g. Place the sample (or standard) into the spectrometer.

h. Make duplicate exposures using the conditions found in Table 2 as guidelines.

The second exposure is made on a fresh portion of the surface. The analytical lines in Table 3 are used.

Table 2. Instrument Settings and Conditions

	Spark Analyses	Uni-arc Analyses
Reference voltage	A	A
Flush	5 s	5 s
Preburn	10 s	5 s
Exposure	15 s	10 s
Sample identification	MD	MD
Background subtract	Off	Off
Program sequence	B	C
Matrix	2	2
Source selection	Spark	Uni
Spark power	Spark	Uni
Ignition	Continuous	Continuous
Capacitance	0.0075 μ f	0.0025 μ f
Analytical gap	4 mm	2 mm
Argon flow	15 cfh	none
Counter electrode	Ultra 132307	Ultra 110402
Elements analyzed	Co, Cu, Fe, Mn, Mo, Ti (Inconel), V	Al, B, Si, Ti (Stainless Steel)

8.8 Calculation. The computer makes all calculations. Report the values obtained directly from the printout on the teletypewriter. The results will be in weight percent.

Table 3. Analytical Lines

Element	Line	Concentration Range, Weight Percent	
		Stainless Steel	Inconel
Al	3082	.003-.04	.05-2
B	2496	.0005-.005	.002-.005
Co	3405	.01-.5	.02-20
Cu	3274	.01-.5	.02-.4
Fe	2599	--	.4-20
Fe	2714	INT. STD.	--
Mn	2933	1-2	.1-.6
Mo	2775	.1-3	2-10
Ni	3492	--	INT. STD.
Si	2881	.3-.8	.07-1
Ti	3596	.02-.5	.1-4
V	3102	.03-.15	--

8.9 Precision. Based upon 316 stainless steel, the precision expected at given concentration levels is given in Table 4. For other alloys and concentration levels, the required levels of precision shall be as specified in the Ordering Data.

Table 4. Precision Expected Based Upon 316 Stainless Steel

Element	Concentration (Wt%)	Relative Standard Deviation (%)
Al	0.05	15
B	0.001	25
Co	0.05	15
Cu	0.1	10
Mn	1 to 2	3
Mo	2 to 3	3
Si	0.75	5
V	0.2	10

9. NITROGEN

This method for determining nitrogen in stainless steel and Inconel shall be in accordance with ASTM E 350.

10. PHOSPHORUS

This method for determining phosphorus in stainless steel and Inconel shall be in accordance with ASTM E 354.

11. SULPHUR

This method for determining sulphur in stainless steel and Inconel shall be in accordance with ASTM E 354.

12. SURFACE CHLORIDE AND FLUORIDE USING THE SWAB TEST

12.1 Application. This method is applicable to the determination of water soluble halides (chloride and fluoride) on metal surfaces. The detection limits per test are about 5 μg chloride and 0.3 μg fluoride on the swabs, which correspond to 0.035 and 0.002 $\mu\text{g}/\text{in.}^2$ (54 and 3 $\mu\text{g}/\text{m}^2$) over a 1 ft^2 (0.093 m^2) of surface for chloride and fluoride respectively.

12.2 Summary. One ft^2 (0.093 m^2) of surface is swabbed alternately with wet and dry gauze pads to remove soluble halides. The pads are washed free of the halides by forcing water through them in a hypodermic syringe. The wash water (test solution) is analyzed for chloride by constant current coulometry and for fluoride by specific ion electrode potentiometry.

12.3 Interferences. Bromide, iodide, sulfide, and other ions that form insoluble silver compounds are measured as chloride. Variations in pH and ionic strength between standards and test solutions adversely affect the fluoride measurement. Therefore, a buffering solution is used to control these variables.

12.4 Apparatus.

1. Automatic chloride titrator.¹
2. Fluoride electrode, specific-ion/reference combination.²

¹An Aminco-Cotlove, chloride titrator has been found satisfactory for this method.

²An Orion 96-09 combination fluoride electrode has been used satisfactorily for this purpose.

3. Forceps, 10 in. (250 mm).

Rinse thoroughly with deionized or distilled water and store in polyethylene bags.

4. Gauze pads, 3 in. by 3 in. (75 mm by 75 mm) 12-ply.¹

These pads must be washed before use to remove chloride and fluoride contamination. Prepare as follows:

a. Set up the wash tube (Item 16) with the pull-up screen near the bottom of the tube.

b. Remove the gauze pads from their envelopes and using forceps, place the pads as flat as possible on the screen in the tube.

c. Fill the tube until the pads are about 20 mm from the top and then put the top screen in place. The tube will hold more than 100 pads.

d. Pass deionized or distilled water up through the pads for 20 min.

e. Remove four pads and check their chloride and fluoride content by analysis beginning at 12.7.2.

If the chloride and fluoride found is equal or less than 5 μg and 0.3 μg respectively, this washing step is complete. If not, repeat Steps d and e until the above criteria are met.

f. Cover the top of the tube with tissue paper and then turn the 3-way stopcock to let vacuum pull the residual water from the tube and pads.

The cover on the tube filters the air passing through as the water is removed.

g. Remove the cover and slowly pour 1 litre of acetone over the pads with the vacuum still pulling air during this step.

h. Replace the cover and continue pulling air through the tube for about 2 h, or until the pads are dry.

i. Remove four pads and repeat Step e.

¹Johnson and Johnson STERI-PAD gauze pads have been used in this method.

If the criteria in Step e are met, this drying step is complete. If not, repeat Steps d through i.

A1

j. Place two pads in each of 1 oz (30 mL) and 8 oz (225 mL) polyethylene bottles.

k. Add 10 mL of deionized water to the 1 oz (30 mL) bottles and place caps on all bottles.

5. Graduated cylinders, glass stoppered, 25 mL.

6. Hypodermic syringe, 30 mL.

7. Magnetic stirrer.

8. Magnetic stir bar, glass coated, 8-mm long.

9. pH/mV meter.¹

10. Plastic or rubber gloves.

Rinse outside of gloves thoroughly with deionized or distilled water and store in polyethylene bags.

11. Polyethylene bags, about 150 by 240 mm.

12. Polyethylene bottles and caps, 1 oz (30 mL) and 8 oz (225 mL).

These bottles must be leached and then rinsed with deionized or distilled water before use.

13. Plastic ruler, flexible.

14. Porcelain crucible, low form, size 000, set in plastic.² See Fig. 1.

15. Wash bottle.

16. Wash tube for gauze pads.

A vertical glass tube, 600 mm-long by 60 mm-outside diameter, with an 8-mm outside diameter outlet at the bottom is connected to a 3-way stopcock. The apparatus is built so that, with the

¹A Leads and Northrup meter, Model 7413, has been used in this method.

²Quickmount, obtained from the Fulton Metallurgical Products Corp, Pittsburg, PA, has been used for this purpose.

Fig. 1. Electrode Apparatus.

|A1

stopcock in one position, water can flow up the tube and overflow into a container, whereas with the stopcock in the other position vacuum can draw air down the tube. An aspirator flask is placed in the vacuum system so that any residual water in the tube pulled out by the vacuum will be trapped in the flask. A coarse, circular plastic screen (with about 7 mm holes) attached to two stiff wires is used to draw pads up the tube. Another piece of screen at the top of the tube holds the pads in place while water flows through the tube.

A1

12.5 Reagents and Standards.

1. Acetone.
2. Deionized water, chloride-free ($<0.1 \mu\text{g/mL}$).
3. Gelatin solution.

See the operations manual for the chloride titrator.¹

4. Nitric-acetic acid solution, 1M nitric acid-4M acetic acid containing 20 to 30 $\mu\text{g Cl/mL}$ of solution.

Prepare by adding 20 to 30 mL of the 1 mg/mL chloride standard to each litre of the nitric-acetic acid solution. Mix thoroughly.

5. Silver cleaning paste.

See the operations manual for the chloride titrator.¹

6. Total Ionic Strength Adjustment Buffer (TISAB).

Add 57 mL of glacial acetic acid, 58 g of sodium chloride and 2 g of 1,2-cyclohexylene dinitrilo tetraacetic acid (cyclohexane diamine tetraacetic acid)² to 500 mL of deionized water in a 1 litre beaker. Stir to dissolve and cool to room temperature. Adjust the solution pH to 5.3 ± 0.2 with 5M sodium hydroxide (about 150 mL), which has been prepared with deionized water. Transfer the solution to a 1 litre volumetric flask and dilute to volume with deionized water.

¹Aminco-Cotlove chloride titrator.

²Mathiesen, Coleman and Bill, Cat. No. P8661; or Merck-Titriplex IV; or Baker Cat. No. G083.

7. Chloride standard, 1000 $\mu\text{g Cl/mL}$.

Dissolve 1.6485 g of sodium chloride, previously dried at 110°C , in deionized water and dilute to 1 litre with deionized water.

8. Fluoride standards.

Prepare a stock solution of 400 $\mu\text{g F/mL}$ by dissolving 0.8840 g of sodium fluoride, previously dried at 110°C , in deionized water and dilute to 1 litre. Prepare a set of calibration standards of 4.0, 0.40, 0.20, and 0.02 $\mu\text{g F/mL}$ by appropriate dilutions of the stock solution. Use 0.001M potassium acetate and 0.001M acetic acid in deionized water as the diluent.

12.6 Calibration.

12.6.1 Chloride Titrator. Calibration involves the determination of a calibration blank and a calibration factor. Base values are determined for both by making at least nine measurements of each over a period of three working days or more. The base value is the average value obtained. The base values are used in calculations.

a. Calibration Blank. Determine the blank according to 12.7.3 using 4.00 mL of deionized water at Step 4 in place of a sample. At least three blanks shall be determined at the start of each 8-h shift during which chloride titrations are made. If the average of the three blanks is within ± 1.0 s of the base value, proceed with determination of the calibration factor, (b). If not, investigate and correct the problem before proceeding.

b. Calibration Factor. Determine the calibration factor according to 12.7.3 using 50.0 μL of the calibration standard and 4.00 mL of deionized water at Step 4 instead of a sample solution. The calibration factor shall be determined at least once each month during which chloride titrations are made. If the result is not within $\pm 1\%$ of the base value, investigate and correct the problem before proceeding with the samples.

12.6.2 Fluoride Electrode. The fluoride electrode shall be calibrated within 2 h of making fluoride measurements because the calibration may drift with time. Calibrate the electrode as follows:

1. Assemble the electrode apparatus (Fig. 1).
2. Turn on the stirrer and adjust it to a moderate speed.
3. Rinse the electrode with deionized water. Pipet 1.00 mL of TISAB and 1.00 mL of 0.02 $\mu\text{g F/mL}$ standard into the crucible. Place the electrode in the solution and let it soak until a stable reading is obtained.

A1

4. Remove the standard solution from the crucible and rinse the crucible with deionized water. Repeat Step 3. The reading should stabilize within 5 min and it must agree within 2 mV of the reading in Step 3. If so, record the reading; if not repeat Step 3.
5. Repeat Step 4 with the 0.20, 0.40, and 4.0 $\mu\text{g F/mL}$ calibration standards (in that order) and record these readings.
6. Plot the calibration readings from Steps 4 and 5 on 3 cycle semilog graph paper with fluoride concentration on the log scale.

A1

12.7 Analysis. Extreme care shall be taken to prevent extraneous chloride and fluoride contamination of reagents and equipment. Wash (test) solutions shall be analyzed for fluoride within 2 h of preparing the calibration curve because the fluoride calibration may drift with time.

12.7.1 Removal of Chloride and Fluoride from Test Surface.

Each test requires four pads, two wet ones in the 1 oz (30 mL) bottle and two dry ones in the 8 oz (225 mL) bottle. The person doing this work must wear prewashed plastic or rubber gloves.

1. Measure a test area of about 1 ft^2 (0.093 m^2).

For large, flat surfaces this can be done with a template. On other surfaces, the area measurement can be done using the plastic ruler.

2. Remove a wet pad from the 1 oz (30 mL) bottle and swab the test surface firmly. Place the pad in an empty 8 oz (225 mL) bottle.

If the surface being swabbed is not horizontal, care must be taken to avoid excess water from the pad running out of the test area and being lost.

3. Swab the area next with a dry pad and place this pad in the 8 oz (225 mL) bottle containing the first (wet) pad.
4. Repeat Steps 2 and 3 with new wet and dry pads.
5. Record the area of the surface tested (in square inches) and describe the test area.

12.7.2 Separation of Chloride and Fluoride from Pads. The graduated cylinders and syringe used in this separation must be reserved solely for this purpose. When not in use, the cylinders should be filled with 0.1M nitric acid and the syringe should be stored in 0.1M nitric acid.

1. Remove the four pads from the bottle with clean forceps and place them in the 30 mL syringe.
2. Rinse the bottle with about 5 mL of deionized water and pour the rinse into the syringe.
3. Insert the plunger into the syringe and squeeze the water into a clean 25 mL graduated cylinder.
4. Remove the plunger and add sufficient deionized water to the syringe so that 25 mL will be collected.
5. Replace the plunger and squeeze the water into the same graduated cylinder (Step 3).
6. Dilute to volume with deionized water. Place the glass stopper in the cylinder and mix thoroughly.

The body of the glass stopper must not be touched with bare skin or any other potential source of chloride or fluoride contamination.

12.7.3 Chloride Measurement. * If the silver electrodes are not bright, start at Step 1; otherwise start at Step 2.

1. Clean the silver electrodes with silver cleaning paste and wash thoroughly with deionized water.

The first one or two chloride measurements made after the cleaning step may not be satisfactory. Clean only if necessary.

2. Pipet 4.00 mL of sample solution from Step 6 of 12.7.2 into the titration cell.
3. Pipet 1.00 mL of the nitric-acetic acid solution containing chloride into a clean 10 mL titration cell.

Because this chloride constitutes a significant blank, the amount of acid solution added must be accurately pipetted. Chloride is added to improve the sensitivity of the titration by providing sufficient chloride to exceed the solubility product of silver chloride. Otherwise, a significant error occurs when titrating a few micrograms of chloride.

*This procedure is based upon use of the Aminco-Cotlove chloride titrator. If another instrument is used, follow the manufacturer's recommended procedure.

A1

4. Add 3 drops of the gelatin solution.
5. Rinse the electrodes with deionized water.
6. Place the titration cell into position on the chloride titrator.
7. Begin stirring by turning the titrate switch to the "Reset" position.
8. Set the time counter to zero.
9. Set the adjustable (red) pointer on the Meter-Relay 10 divisions above the indicator (black) pointer.

The operations manual* has instructions for the initial setting of the indicator pointer.

10. Begin the titration by turning the titrate switch to the "Titrator" position.
11. Record the time when the counter stops.

This is the titration time for the sample (T_s), calibration standard (T_{st}), or calibration blank (T_{cb}), depending upon what is being determined.

12.7.4 Fluoride Measurement.

1. Prepare the electrode for the fluoride measurement by following Steps 1 and 2 of 12.6.2 and then rinse the electrode with deionized water.
2. Pipet 1.00 mL of sample solution and 1.00 mL of TISAB into the crucible of the electrode apparatus.
3. Place the electrode into the solution and record the millivolt reading after a stable reading is obtained.
4. Obtain the micrograms per millilitre of fluoride from the calibration curve.

12.8 Calculations. Calculate the chloride calibration factor, the micrograms per millilitre of chloride titrated, and the concentration of chloride and fluoride on the sample using 12.8.1, 12.8.2, or 12.8.3.

*This procedure is based upon use of the Aminco-Cotlove chloride titrator. If another instrument is used, follow the manufacturer's recommended procedure.

12.8.1 Chloride Calibration Factor. The chloride calibration factor is calculated from Equation 6. A1

$$F = \frac{Cl}{T_{st} - T_{cb}} \quad (6)$$

where

F = calibration factor, micrograms of chloride per second

Cl = micrograms of chloride added from the chloride standard
(Step 2 of 12.6.1)

T_{st} = titration time of standard (Step 11 of 12.7.3)

T_{cb} = titration time of calibration blank (Step 11 of 12.7.3).

12.8.2 Concentration of Chloride on the Surface of Sample. The chloride concentration is calculated from Equation 7.

$$C_a = \frac{F (T_s - T_{cb}) V}{SA} \quad (7)$$

where

C_a = micrograms chloride per square inch of surface

F = calibration factor

T_s = titration time of sample (Step 11 of 12.7.3)

T_{cb} = titration time of calibration blank

A = sample aliquot, normally 4.00 mL

S = area of test in square inches

V = total volume of solution collected, usually 25.0 mL.

12.8.3 Concentration of Fluoride on the Surface of Sample. The fluoride concentration is calculated from Equation 8.

$$F_a = \frac{F V}{S} \quad (8)$$

where

F_a = micrograms fluoride per square inch of surface

F_c = micrograms fluoride per millilitre from Step 4 of 12.7.4

S = area of test in square inches

V = total volume of solution collected, usually 25.0 mL.

12.9 Precision. Pads spiked with known amounts of chloride and fluoride were analyzed and the results are given in Table 5.

Table 5. Chloride/Fluoride Test Precision

	Spike Level			
	50 $\mu\text{g Cl}$	500 $\mu\text{g Cl}$	5 $\mu\text{g F}$	50 $\mu\text{g F}$
Relative Standard Deviation, %	12	6	4	2
Recovery of Spike, %	104	100	91	95

13. SURFACE CHLORIDE AND FLUORIDE BY WASH METHOD

13.1 Application. This method is used to determine water-soluble chloride and fluoride on surfaces of metallic components too small for the Swab Test. The detection limits are 0.04 μg of Cl and 0.002 μg F per square inch on a 100-in.² sample.

13.2 Summary. Residual chloride and fluoride are removed from component surfaces by washing with a hot, halide-free detergent solution. The wash solution is evaporated to a smaller volume and it is analyzed for chloride by constant current coulometry and for fluoride by specific-ion electrode potentiometry.

13.3 Interferences. Because variations in pH and ionic strength of solutions affect the response of the fluoride electrode to ion activity, standard and sample measurements are made in equivalent detergent solutions. Care must be taken at all times to prevent contamination from extraneous chloride and fluoride.

13.4 Apparatus.

- a. Automatic chloride titrator.*
- b. Evaporating apparatus, see Fig. 2.
 1. Aluminum plate, 30.5 by 30.5 by 0.32 cm.
 2. Blower or compressed air source, to blow air across the sample.

*An Aminco-Cotlove chloride titrator has been found satisfactory for this method.

Fig. 2. Evaporating Apparatus.

3. Glass or metal cylinder, 13.7-cm outside diameter by 9.5-cm high with a 0.64-cm inside diameter tubulure at a height of 4.4 cm from the bottom.
4. Glass tube, filled with glass wool, connected between the tubulure on the cylinder and the blower or compressed air source.
5. Infrared lamp, 250 W.
6. Porcelain dish, size 2 (10.5-cm outside diameter).
7. Ring stand and clamp, for supporting the lamp¹
- c. Fluoride electrode, specific-ion/reference combination.² i c
- d. Heating tape, used to heat the wash tube.
- e. Magnetic stirrer.
- f. pH meter (millivolt meter).³
- g. Porcelain crucible, low-form, size 000, preferably set in plastic such as Quickmount.⁴ See Fig. 1.
- h. Stirring bar, glass coated, 0.8-cm long.
- i. Stopwatch.
- j. Vacuum apparatus. Filter flask, 1- or 2-litre, arranged with a stopper and connection for rubber tubing and connected to a source of vacuum to withdraw solution from the crucible.
- k. Wash tube, having a length sufficient to hold a cladding tube and a diameter that is 0.32 to 0.64 cm larger than the cladding tube. The wash tube should have a Teflon stopcock at one end and a standard taper glass stopper at the other end.

¹A Fisher Infra-Radiator, Catalog No. 11-504-5, has been used satisfactorily for this purpose.

²An Orion 96-09 combination fluoride electrode has been used in this method.

³An Orion pH meter, Model 801, has been used for this purpose.

⁴This plastic material can be obtained from the Fulton Metallurgical Products Corp., Pittsburgh, Pa.

13.5 Reagents and Standards.

a. Detergent solution. A 0.2 % solution of Tergitol 15-S-7,¹ sp gr of 0.988, in distilled water. Add 14 mL of the detergent to 7L of distilled water and mix thoroughly. Adjust the pH of the solution to between 4.5 and 5.5 with sodium carbonate. Likewise, prepare a 2 % solution by adding 14 mL of the detergent to 700 mL of distilled water. Avoid contact of concentrated detergent with skin and eyes.

b. Gelatin solution. (See Operations Manual for the chloride titrator.)²

c. Nitric acid-acetic acid solution, 1M HNO₃-4M acetic acid containing 20 to 30 µg Cl/mL of solution. Prepare by adding 20 to 30 mL of the 1 mg/mL chloride standard to each litre of the nitric acid-acetic acid solution. Mix thoroughly.

d. Silver cleaning paste. (See the Operations Manual for the chloride titrator.)²

e. Chloride standard, about 1 mg Cl/mL. Prepare a solution with a precisely known concentration using sodium chloride, previously dried at 110°C, and distilled water.

f. Fluoride standard, 0.100M (1.90 g F/L). Dissolve 4.199 g of sodium fluoride, previously dried at 110°C, in distilled water and dilute to 1 litre. Store in a plastic container.

g. Calibration standards. Prepare a set of calibration standards for the fluoride electrode as indicated in Table 6. Use the 0.2 % detergent solution to make all dilutions. Store in plastic containers.

Table 6. Fluoride Calibration Standards

Standard Required (<u>M</u>)	Standard to Dilute	Amount (mL)	Make-Up Volume (mL)
10 ⁻³	0.100 <u>M</u>	1	100
10 ⁻⁴	10 ⁻³ <u>M</u>	10	100
10 ⁻⁵	10 ⁻³ <u>M</u>	1	100
10 ⁻⁶	10 ⁻⁴ <u>M</u>	1	100

¹Tergitol 15-S-7 is a product of the Union Carbide Corp.

²An Aminco-Cotlove, AMINCO, chloride titrator.

13.6 Calibration.

13.6.1 Chloride Titrator. Follow instructions given in 12.6.1, using the 0.2 % detergent solution in place of the deionized water.

13.6.2 Fluoride Electrode. Follow instructions given in 12.6.2, using 0.2 % detergent solution in place of deionized water.

13.7 Analysis. Extreme care shall be taken to prevent chloride contamination of reagents and laboratory equipment. Sample solutions shall be measured for fluoride within 2 h of preparing the calibration curve because the fluoride calibration tends to drift with time.

13.7.1 Removal of Chloride and Fluoride from Surface.

- a. Select a sample to give a minimum total of 50-in.² (3.2 x 10⁻² m²) surface area.

A sampling plan for core components shall be submitted by the supplier and approved by the purchaser. Samples shall not be precleaned before removal of chloride and fluoride.

- b. Place the sample in an appropriate container.

Cladding tubes are placed in the wash tube. Samples of other shapes and sizes are placed in glass or plastic containers that minimize the amount of wash solution required to cover the samples.

Extreme care shall be taken in handling samples to prevent chloride contamination. Do not handle samples with bare hands; use gloves that have been washed and rinsed thoroughly to minimize the chloride content.

- c. Add a minimum volume of 0.2 % detergent solution, sufficient to immerse all surfaces of the sample.

- d. Heat the solution at 80 to 90°C for 30 min.

- e. Measure the volume of the wash solution after it cools and transfer up to 100 mL to the porcelain dish in the evaporating apparatus (Fig. 2).

If the volume exceeds 100 mL, transfer only 100 mL.

- f. Evaporate the wash solution to 5 mL.

g. Quantitatively transfer the evaporated solution to a 10-mL volumetric flask, using 1-mL rinses of the 2 % detergent solution when the volume of wash solution evaporated was $\leq$ 75 mL; otherwise, rinse with distilled water.

h. Dilute to 10 mL with the rinse solution used in Step g and mix thoroughly.

13.7.2 Chloride Measurement. Follow instructions given in 12.7.3. |C

13.7.3 Fluoride Measurement. Follow instructions given in 12.7.4. |C

13.8 Calculation. Calculate the chloride calibration factor, the micrograms per millilitre of chloride titrated, and the concentration of chloride and fluoride on the sample using the appropriate equations in 12.8. |C

13.9 Precision. For 100 in.² ($6.5 \times 10^{-2} \text{ m}^2$) of sample surface containing 20- to 50- μg of chloride and 10- to 50- μg of fluoride, the relative standard deviation is 10 % or less.

14. ORDERING DATA CHECKLIST

The following technical and procurement data will be furnished by the purchaser. If not furnished with the purchase documents, the supplier shall request any necessary data before submitting his bid.

<u>Item</u>	<u>Refer to Paragraph</u>
1. Specific steel and Inconel alloys	1.
2. Purchaser quality control system	3.4.2
3. Elements required by Direct Reading Emission Spectroscopy	8.1
4. Precision requirements for alloys other than 316 stainless steel	8.9

|D

END

DATE
FILMED

5/04/93