**TRIBOLOGY OF IMPROVED
TRANSFORMATION-TOUGHENED CERAMICS-
HEAT ENGINE TEST**

E. Lilley, G. A. Rossi, and P. J. Pelletier

Date Published-April 1992

FINAL REPORT

**Prepared by Norton Company
Advanced Ceramics
Goddard Road
Northboro, Massachusetts 01532-1545
86X-SG372V**

**Funded by
Office of Transportation Materials
Office of Transportation Technologies
the Assistant Secretary for Conservation and Renewable Energy
U.S. Department of Energy
EE 51 01 00 0**

**for
OAK RIDGE NATIONAL LABORATORY
Oak Ridge, Tennessee 37831
managed by
MARTIN MARIETTA ENERGY SYSTEMS, INC.
for the
U.S. DEPARTMENT OF ENERGY
under Contract DE-AC05-84OR21400**

MASTER

TABLE OF CONTENTS

Executive Summary	
Abstract.	1
1. Introduction.	1
2. Materials for Evaluation	2
3. Materials Preparation	3
4. Tribological Testing.	4
5. Results	5
5.1 Microstructure	5
5.2 Mechanical Properties.	7
5.3 Tribological Testing Results	8
5.4 X-Ray Diffraction of the Wear Surfaces	11
6. Discussion.	11
7. Summary and Conclusions	12
8. Acknowledgements.	13
9. References.	13
Appendix A	
Cam Roller Follower Dimension Specifications.	15
Appendix B	
Tribology Testing of Cam Roller Follower at The Torrington Company by J.F. Braza.	17

EXECUTIVE SUMMARY

1. Tribology tests have been performed at the Torrington Company under subcontract to Norton to simulate wear of cam roller followers made of (i) ceria zirconia toughened alumina (Ce-ZTA) (ii) yttria stabilized transformation toughened zirconia (TTZ) and (iii) HIP Si_3N_4 . All three types of ceramics made and developed by Norton's Advanced Ceramic Division revealed no significant wear after special short time tests making them candidates for cam roller followers in engines. This result is encouraging because in the past oxide materials have not fared as well as Si_3N_4 .

2. A tribological test assembly was used to conduct single element rolling/sliding tests in an environment chosen to closely duplicate that in a valve train of an engine. The normal load was 1557N (350 lbs.) The rolling velocity was 2.0 m/s and the lubricant was Mobil 5W-30 run at 93.5°C. The mating driving ring was a through hardened 52100 steel simulating a cam lobe and ground to an R_a between 0.125 and 0.175 microns (5-7 micro inches). The test was designed with a 1% sliding component to better simulate roller follower conditions. Tests were run for 1 and 5 hours and the wear was measured by weight loss. Profilometer and SEM studies were performed to study surface roughness.

3. Frictional forces measured continuously during the test showed that these are due to shearing of the lubricant film rather than the shearing of the steel or ceramic asperities after the initial run-in period.

4. Because of the minute amount of wear found, it was not possible to deduce any wear mechanism and relate it to the physical properties measured such as MOR, K_{IC} hardness, grain size, porosity, etc.

5. Phase transformation induced by rolling and/or wear has been a concern in transformation toughened ceramics since it can increase the brittleness of the material. Little transformation of the zirconia in the TTZ from tetragonal to monoclinic was found. However in the case of some of the Ce-ZTAs considerable transformation occurred. The degree of phase transformation depended upon composition and grain size as qualitatively predicted by transformation toughening theory.

6. The experimental results in this report indicate little or no wear in 1 to 5 hour simulated roller follower tests for oxide materials which could be lower cost alternatives to Si_3N_4 . Longer time testing preferably on engine dynamometers, is now required to validate these results for life time engine use, followed by 500-1000 vehicle pilot evaluation to verify cost effectiveness and performance in actual engines.

Research sponsored by the U.S. Department of Energy, Assistant Secretary for Conservation and Renewable Energy, Office of Transportation Technologies, as part of the Ceramic Technology Project of the Advanced Materials Development Program, under contract DE-AC05-84OR21400 with Martin Marietta Energy Systems, Inc.

TRIBOLOGY OF IMPROVED TRANSFORMATION
TOUGHENED CERAMICS - HEAT ENGINE SCREENING TEST

E. Lilley, G.A. Rossi, P.J. Pelletier

ABSTRACT

A short term study has been carried out to evaluate the suitability as cam roller followers of three ceria zirconia toughened aluminas and two yttria stabilized tetragonal zirconias (YTZPs) previously enhanced in programs supported by ORNL. Norton Si_3N_4 (NBD-100) was also included in this study as a reference material, because it was known from work at Northwestern University that Si_3N_4 to experienced little or no wear in this application, and NBD-100 is currently a successful commercial bearing material.

The tribological studies were subcontracted to the Torrington Company. They found that in cam roller follower simulated tests that there was essentially no wear after 1 hour and 5 hours of testing detectable by weighing and concluded that all of these ceramics are, therefore, candidate materials. Because of the minute amounts of wear it was not possible to identify the wear mechanism or to make any correlations with the other physical properties which were evaluated such as MOR, K_{IC} hardness, density and grain size.

Phase transformation during rolling has been of interest in the tribology of zirconia contain materials. The least stable of the ceria zirconia toughened aluminas resulted in as much as 33% monoclinic phase after testing whereas the yttria stabilized (TTZ) contained very little of this transformed phase.

The results of this study show that oxide materials can now be considered as candidates for cam roller followers in heat engines.

1. INTRODUCTION

Norton Company has participated in the ORNL Ceramic Technology for Advanced Heat Engines (CTAHE) Project by developing two kinds of materials (a) Y-TZP and (b) Ce-ZTA. The producing and mechanical testing of these two kinds of ceramics was reported in the ORNL publications^{1,2}. Materials have been developed which are more resistant to low temperature degradation.

In light of this previous progress a short research program was proposed to ORNL for Norton to test these materials in a heat engine application such as a cam roller follower. An incentive for this study was that a series of tribology studies of ceramics had been performed at Northwestern University and specific studies had been made on cam roller followers³. The most encouraging results were found for silicon nitride

rollers against lubricated steel cam lobes. Even after 900 hours virtually no wear of the silicon nitride was found. Unfortunately silicon nitride is not cost competitive with steel rollers so it is of interest to test lower cost ceramics such as zirconias and zirconia toughened aluminas. Tests made by Braza et al⁴ revealed virtually no wear for Toshiba silicon nitride ($8 \times 10^{-5} \text{g}$) whereas Coors magnesia stabilized zirconia had much more wear ($222 \times 10^{-5} \text{g}$) after 100 hours. It was anticipated that the finer grained materials of Norton Company would have less wear than the coarse grained magnesia stabilized zirconia.

However, there was also a concern that the roller surface would phase transform during rolling, thereby increasing their brittleness and the wear rate on both the ceramic and metal surfaces.

It was, therefore, proposed that "test procedures and materials should be chosen to 1) obtain speedy but reliable information on the inherent suitability of zirconia based materials, 2) give probable wear and failure mechanisms, and 3) demonstrate whether compositional, microstructural, or processing modifications will result in improved performance."⁵ The cam roller follower can also be considered as a model component in the application of high performance ceramics. Wear results obtained in this study could give indication of the suitability of these transformation toughened materials in other applications.

There are two major reasons for fabricating roller followers out of ceramic materials. One reason is to eliminate the needle rollers thereby reducing the number of components to two, the ceramic roller and the tappet shaft thereby simplifying the design and assembly. Secondly, in diesel engines, the debris (soot) acts as an abrasive particle that can cause excessive wear on the 52100 steel tappet shaft over long time periods. The ceramic roller follower is a journal bearing, and when properly designed, the "soot" debris will not be able to enter the journal and hence, abrade the tappet shaft.

In order to execute the tribological testing, Norton has subcontracted this part of the work to the Torrington Company in Connecticut. Dr. J.F. Braza, previously at Northwestern University, and now the tribologist at Torrington brings a special expertise to this screening process. In fact, a major part of this report (see the Appendix B) has been written by Braza.

2. THE MATERIALS FOR EVALUATION

Three types of ceramics were investigated as candidates for wear applications which include two types of yttria stabilized zirconia, three types of $\text{CeO}_2\text{-ZrO}_2$ aluminas and MgO doped silicon nitride. The latter ceramic was included as a reference material. The materials tested and their chemical compositions are listed in Table 1.

Table 1

MATERIAL	CODE	MgO wt%	CeO ₂ wt%	Y ₂ O ₃ wt%	ZrO ₂ wt%	Al ₂ O ₃ wt%	Si ₃ N ₄ wt%
ZTA	Z18Ce60A	-	6.8	-	31.2	62	-
	Z12Ce70A	-	3.6	-	26.4	70	-
	Z12Ce70A-T2	-	3.6	-	26.4	70	-
TTZ	MG-026	-	-	5.4	94.6	-	-
	YZ-110	-	-	4.8	96.	-	-
Si ₃ N ₄	NBD-100	1.0	-	-	-	-	99

3. MATERIALS PREPARATION

The yttria doped zirconia crude was prepared by melting and rapid solidification. The YZ-110 and MG026 powders were prepared by Sweco milling this crude in water to an average particle size of 0.7 microns as measured with a sedigraph. The CeO₂-ZrO₂-Al₂O₃ crude were made by a rapid solidification method developed at Norton Plasma Materials. This crude was calcined at 1250°C to crystallize the amorphous Al₂O₃ and retard its reactivity in H₂O and then milled in a planetary mill in H₂O with PSZ containers and Y-TZP media. The slurry was dispersed at a pH of ~3.0 with HNO₃ during milling. There are two ceria doping levels in the zirconia phase; 18wt% (13.6m¹%) and 12wt% (9m%).

The powders were analyzed for particle size distribution by sedigraph and for phase content by XRD. All powders were dried at 100°C to constant weight.

Four cam roller followers were made from each material. The cam roller followers were fabricated by CIP'ing the powders at 30 ksi in 2" high by 2" diameter cylindrical urethane molds followed by green machining to near net shape form allowing for shrinkage. Billets were made for each material in a stainless steel split mold of dimensions 3.5" x 1.5" x .25", die-pressed at 9.5 ksi and CIP'ed at 30 ksi. These billets were prepared for mechanical property testing and for ORNL wear test samples. The CeO₂-ZrO₂-Al₂O₃ powders that were either die-pressed/CIP'ed or CIP'ed were fired in air to 1600°C/1 hour and HIP'ed at 1500°C/.75 hour at 30 ksi to theoretical density. The TTZ powders were treated the same except they were sintered at 1500°C before HIP'ing. NDB-100 samples were machined out of HIP'ed rods supplied by CERBEC Company, East Granby, CT.

The Z12Ce70A-T2 material was colloiddally consolidated to produce a finer microstructure. The slurry after milling was electrostatically restabilized at a pH of 3.0, ultrasonicated at 50% of the duty cycle and filtered through a 5 μ filter to remove any agglomerates or contaminants.

The slurry was then deaired under vacuum and colloiddally cast under a pressure of 65 psi. The cam roller followers were pressure cast in a 2" diameter mold and the billets were casted in a 2-3/4" x 2-3/4" x 1.00" mold. Samples were allowed to dry in air for 24 hours and then were slowly dried to 90°C in an oven. These pressure cast specimens were pressureless sintered in air to 1500°C/1 hour and then HIP'ed to 1500°C/.75 hour. All the $\text{CeO}_2\text{-ZrO}_2\text{-Al}_2\text{O}_3$ materials were annealed at 1000°C/3 hours in air to improve their machining ability.

Strength was measured at RT in a 4 point bend test on 3 x 4 x 50 mm mil. spec. bars. Hardness was measured by microindentation. The grain size distribution was measured on polished and thermally etched samples using the line intercept method. SEM and XRD analysis was performed on all the cam roller followers before and after the simulated valve train tests. The fracture toughness was measured by the indentation strength method⁶.

All MOR bars and ORNL wear test samples were machined in-house. The cam roller followers were machined by Chand/Kare Inc. The dimensions of the cam roller follower are shown in appendix A. The surface finish of the cam roller followers was measured before and after testing by a profilometer.

4. TRIBOLOGICAL TESTING (AT TORRINGTON COMPANY)

Torrington Company agreed to evaluate the tribological performance of three types of zirconia toughened alumina and two types of transformation toughened zirconia ceramics, plus NBD-100 Si_3N_4 , in simulated valve train tests. These simulated valve train tests were conducted using the Torrington tribological tester, which consisted of two mating components: a tappet roller and a cylindrical shaped specimen. The test conditions were as follows:

- . Rolling speed - 2.0 m/sec (78.7 in/sec)
- . Slide-to roll ratio - 0.005 to 0.01
- . Maximum contact stress - 1.38 Gpa (200 ksi) or 1557 N (350 lbs) normal load, stress depends on elastic modulus of ceramic material
- . Lubricant - SAE 5W-30
- . Lubricant temperature - 93.3°C (200°F)
- . Test duration - 1 hour

In Torrington's experience serious wear is revealed in the first hour of testing. For each of the specimens tested the following were performed:

- . Surface profile trace (pre-test)
- . Cleaning and weight measurement (pre-test)
- . Optical and SEM microscopy (pre-test)
- . Testing
- . Cleaning and weight measurement (post-test)
- . Surface profile trace (post-test)
- . Optical and SEM microscopy (post-test)

The following objectives were achieved:

1. Measured and recorded the friction force (i.e., friction coefficient) traces for the different ceramic materials.
2. Photographed the wear of the mating specimens after the specified test interval to observe the wear process.
3. Measured the weight loss and surface profile for each type of ceramic and determined wear rates for the above test conditions.
4. Conducted SEM post-test evaluation of the ceramics to determine the mechanism of wear.

5. RESULTS

5.1 MICROSTRUCTURE

Polished and thermally etched microstructures are shown in Figure 1 (a to d) for Z18CE60A, Z18CE70A, Z12CE70A-T2 and MGO26, which is virtually identical with YZ110, after HIP'ing at 1500°C. The grain size of each sample was determined from the average line intercept multiplied by 1.56. The values are listed in Table 2. In the ZTA the two phase system restricts the grain growth especially of the alumina phase. Grain growth of tetragonal zirconia grains is relatively slow. The lower sintering temperature of the Z12CE70-T2 (1500°C) has led to a finer grain size for both alumina and zirconia.

(a)

(b)

(c)

(d)

Figure 1. SEM micrographs of four of the ceramics used in this study.
(a) Z18CE60A (b) Z12CE70A (c) Z12CE70A-T2 (d) MG026.

HIP'ing of all the materials yielded densities very close to the theoretical densities. e.g. Z18CE60A 4.75, Z12CE70A 4.55, MgO26 6.08, YZ110 6.08 and NDB100 3.21 g/cm³.

Table 2

MATERIAL	CODE	GRAIN SIZE (MICRONS)			ZIRCONIA MONOCLINIC %
		ZIRCONIA	ALUMINA	Si ₃ N ₄	
ZTA	Z18CE60A	1.66	1.70		0
	Z12CE70A	1.15	1.90		1
	Z12CE70A-T2	0.84	1.55		2
TTZ	MG-026	1.08	-		0
	YZ-110	1.08	-		0
Si ₃ N ₄	NBD-100	1.00	-	1.0	-

The monoclinic content was established with XRD using the formula of Toraya et al⁷. Diffraction from polished and thermally etched surfaces at 1400°C, revealed no observable monoclinic except for the two lower doped ceria ZTA's.

5.2 MECHANICAL PROPERTIES

Mil-spec bars were tested for modulus of rupture at a cross head speed of 0.02 inches/min and for indentation/strength K_{IC} measurements. Typically 8 bars of each material were used for MOR tests and 3 of each for K_{IC} tests. An indentation load of 10 kgm was used for the ZTA ceramics and 40 kgm for the TTZ ceramics, under oil, with a Vickers hardness machine. To measure the K_{IC} , Vickers hardness measurements were performed at 1 kg load, averaging 5 measurements. The results of these experiments are tabulated in Table 3.

Table 3 MOR Hardness and toughness

MATERIAL TYPE	CODE	MOR		K_{IC} MPa m ^{1/2}	HARDNESS GPa
		(MPa)	(ksi)		
ZTA	Z18CE60A	826	119	5.9	14.9
	Z12CE70A	700	101	4.8	14.4
	Z12CE70-T2	1076	155	7.9	15.0
TTZ	MG026	1180	170	7.3	13.5
	YZ110	1260	181	6.2	13.5
Si ₃ N ₄	NBD100	760	110	5	16.5

Clearly the HIPed TTZ's are stronger than the ZTA's but the latter have greater hardness through the presence of alumina. The magnitude of the three ZTA average MOR values correlates with the K_{IC} values as expected from the Griffith equation.

5.3 TRIBOLOGICAL TESTING RESULTS

These are reported in considerable detail in Appendix B. However, an abbreviated description will be presented here along with an XRD analysis of the worn ceramic surface and a discussion.

The Torrington tester was used to conduct these single element rolling/sliding tests. The test environment was chosen to closely duplicate the valve train, where the normal load was 1557 N (350 lbs), the rolling velocity was 2.0 m/s (78.7 in/sec), the sliding component was approximately 1% of the rolling velocity, the lubricant type and temperature was Mobil 5W-30 and 93.3°C (200°F), respectively. The mating driving ring specimen was a through hardened 52100 steel that was circumferentially ground to comparable roughness levels of cam lobes used in Ford Modular engines (R_a varied between 0.125 and 0.175 μ m [5 and 7 μ in]).

The testing assembly to simulate the motion of a cam roller in an engine is drawn schematically in Figures 7 and 8 of Appendix B.

The most important results of the tribological testing are presented in Table 4. Here are listed the applied force, the coefficient of friction, the percentage slipping and the change in weight for the one hour test performed on three rollers of each material and a subsequent four hour test on one of each roller for each material. In several cases there is an increase in weight which is due to metallic pick-up from the steel driving ring. What is most encouraging is the fact that for all the materials tested there is no more than 10^{-4} gm of ceramic removed after 5 hours of wear testing. Note there is some weight gain in the first hour that is lost in the subsequent four hours. Most of these measurements are close to the limit of resolution for weight changes.

Past experience has shown that Si_3N_4 has excellent resistance as cam roller followers but these tests show comparable performance for the TTZ and Ce-ZTA ceramics. It is note worthy in the study of Gangopadhyay et al⁸ that the greatest wear occurs at the shortest testing times.

The weight loss of 10^{-4} gm corresponds to about 0.03 microns of uniform wear from the contact surface. At this level it is very difficult to observe a wear mechanism by SEM, even though one does not necessarily expect it to be uniform across the surface. Profilometer measurements are given in Table 3 of Appendix B, but not surprisingly, no measurable change was found in surface roughness after testing. The R_a and P-V (peak to valley) distances due to the original finishing vary somewhat between the materials but they fall mainly between 5 and 9 and between 40 and 60 micro inches respectively. (An R_a of 8 microinches had been specified to an outside machine shop).

The SEM does show, however, that the finishing does cause some grain pull-out in the ZTA's whereas the TTZ's experience more plastic deformation leading to furrows. Si_3N_4 also did not show any grain pullout.

The driving ring component was a through hardened 52100 steel. Surface roughness measurements before and after testing reveal that the ZTA ceramics caused the greatest amount of wear followed closely by the Si_3N_4 ceramics. No perceptible change in surface roughness was measured (by profilometer) or observed (with optical microscope) on the steel rings tested against the TTZ ceramics. The steel ring experienced a polishing wear mode, which was similar to rings that were tested against tumbled tappet rollers in a previous Torrington project. However, it is felt that this wear is not detrimental to the performance of this system, since it is only a run-in wear phenomena. In the subsequent four hour tests, the steel rings did not experience any polishing or change in roughness.

The coefficient of friction was found to be similar for all of the materials studied, falling between 0.05 and 0.07, although there was a slight increase in the four hour test. At this level the friction is primarily associated with the oil film as discussed in Appendix B.

Table 4 Ceramic roller tribology data

			ONE HOUR TESTS			
MATERIAL	CODE	#	F _f (LBS)	μ	% SLIP	Δ WT. x10 ⁻⁵ g
ZTA	Z18CE60A	1	21.50	.061	.47	+6
		2	24.95	.071	.40	+14
		3	23.84	.068	.53	+15
	Z12CE70A	1	17.14	.049	.55	+9
		2	16.30	.047	.82	+6
		3	18.54	.053	.54	+8
	Z12CE70-T2	1	22.94	.066	.56	-10
		2	22.64	.065	.80	-10
		3	22.10	.063	.94	-6
TTZ	MG-026	1	21.20	.061	1.3	-4
		2	17.74	.051	.60	+10
		3	15.60	.045	.30	+3
	YZ-110	1	20.00	.057	.83	+7
		2	20.80	.059	1.0	-2
		3	22.10	.063	.21	-3
Si ₃ N ₄		1	17.40	.050	.69	+6
	NBD-100	2	17.44	.050	.69	+2
		3	17.44	.050	.64	+8
STEEL	BUFFED	16	21.30	.061	.81	N/A
	TUMBLER	14	19.54	.056	.89	N/A
			SUBSQ FOUR HOUR TESTS			
ZTA	Z18CE60A	2	22.14	.063	.48	-9
	Z12CE70A	2	24.40	.070	.60	+12
	Z12CE70-T2	1	22.64	.065	.75	+12
TTZ	MG-026	2	25.50	.073	.66	-21
	YZ-110	2	25.70	.073	.75	-16
Si ₃ N ₄	NBD-100	3	25.00	.071	.73	-8

5.4 X-RAY DIFFRACTION OF THE WEAR SURFACES

XRD scans were made of a roller surface of each kind of material using $\text{CuK}\alpha$ radiation: (a) as polished and thermally etched, (b) as machined (c) after 1 hour wear testing and (d) after a total of 5 hours of wear testing. The interesting feature is the partial transformation of zirconia from the tetragonal to the monoclinic phase. The equation of Toraya et al⁷ was used to calculate the monoclinic %. The results are presented in Table 5.

Table 5

MATERIAL	CODE	MONOCLINIC %			
		POLISHED	MACHINED	1 HR WEAR	5 HRS WEAR
ZTA	Z18CE60A	0	4	8	17
	Z12CE70A	1	21	33	33
	Z12CE70-T2	3	13	16	23
TTZ	MG-026	0	1.5	1.5	3
	YZ-110	0	4	3	6

The Ce-ZTA ceramics are less stable under stress with respect to the transformation to monoclinic than the TTZ's and the higher cerias (18 wt% in ZrO_2) are more resistant to transformation than the lower one (12 wt% in ZrO_2). Likewise, MG-026 with 5.4 wt% Y_2O_3 transforms less readily than the YZ-110 with 4.8 wt% Y_2O_3 . Additionally, the finer grain size Z12CE70A-T2 (see Table 2) transforms less readily than the coarser Z12CE70A as expected from transformation toughening theory.

It is worth bearing in mind that because of absorption the XRD effectively samples only the first 3 microns of the surface layer⁹ so there remains a question of how deep the transformation layers are.

6. DISCUSSION

The principal result of this study is that very little wear was observed after the one or five hour test interval for all three types of ceramics. It is, therefore, not possible to distinguish between them in any detail, for example in wear mechanisms, except to say that the harder alumina containing materials are expected to have somewhat greater wear on the steel mating surface. However this is not expected to be a problem in engines.

Rolling contact fatigue studies^{10,11} of Si_3N_4 indicate that wear is strongly dependent upon surface finish. Since the cam rollers here have greater surface roughness than is found with ball bearings, wear

associated with finishing could have been anticipated, however, the contact stresses are much lower for rollers than for ball bearings so it may be in this application that larger R_a values are acceptable. If so, then this would be of considerable advantage from a cost of finishing point of view. This concept of surface characteristics vs. tribological performance is critical for cost effective use of ceramics and merits further study.

One variation in the performance of the materials that stands out in this simulated test is the different degree of transformation from the tetragonal to the monoclinic phase. The ZTA's transform more than the TTZ's through machining or after the one and five hour tests. This transformation forms a compressive surface layer and it is conceivable that this could make the surface more resistant to wear.

On the other hand, as the surface transforms more and more to the monoclinic phase it may ultimately become more brittle and cause increased wear. Consequently, at longer testing times the ZTA ceramics could suffer greater wear through this embrittlement. The TTZ's in contrast transformed much less with the higher yttria MG026 showing the least percentage transformation.

7. SUMMARY AND CONCLUSIONS

1. One test condition was used in this test procedure in order to evaluate the ceramic rollers. The normal load was 1557 N (350 lbs), a rolling velocity of 2.0 m/s ($n_{ring} = 775$ rpm), and a lubricant temperature of a 93.3°C (200°F - lubricant kinematic viscosity is approximately 10.4 cSt), with a slide-to-roll ratio ranging from 0.005 to 0.01 (percent slippage ranging from 0.5 to 1%) between the ceramic roller and the driving steel ring.

2. These short time tests, according to Dr. Braza of the Torrington Company indicate that all of these ceramics would not suffer significant wear in life time experiments and are candidates for cam roller followers although this needs to be validated.

3. Typically less than 10^{-4} gm loss in weight was measured after 1 and 5 hours of testing (which is barely measurable) for the 3 kinds of ceramics.

4. This small weight loss of the ceramic rollers upon testing is an encouraging result because in the past, magnesia stabilized zirconias have not performed nearly as well as Si_3N_4 as cam roller followers.

5. Little can be said about the wear mechanism since so little material was removed in these tests nor could any correlations be made with MOR, K_{IC} , hardness, grain size, density, etc. which were measured.

6. The coefficient of friction in all cases was between 0.05 and 0.07 which is primarily associated with the lubricating oil film.

7. The wear testing caused very little phase transformation of the TTZ but much more for the Ce-ZTA's. The degree of transformation depends on the chemical stabilization by yttria and ceria and on the grain size as quantitatively predicted from transformation toughening theory.

8. ACKNOWLEDGEMENTS

To J.F. Braza of Torrington for performing the tribology testing. R.H. Licht and J.N. Panzarino for assistance, administration and technical discussion and J.W. Lucek for advice and discussions.

9. REFERENCES

1. GARossi, JBBlum, CEKnapp and KEManwiller, Processing of Sinterable Transformation Toughened Ceramics for Application in Ceramic Technology for Advanced Heat Engine Project. Final report ORNL/Sub/85-22031/1. (1988).
2. E.Lilley and GARossi, Processing of Sinterable Transformation Toughened Ceramics for Application in Ceramic Technology for Advanced Heat Engine Project. Phase IIA. Completed 1990 to be published.
3. Braza, J.F., Cheng, H.S., Fine, M.E., Gangopadhyay, A., Keer, L.M., and Worden, R.E., "Mechanical Failure Mechanisms in Ceramic Sliding and Rolling Contacts, "Tribology Trans., 32, 1, pp 1-8 (1989).
4. Braza, J.F., Cheng, H.S., and Fine, M.E., "Wear of Partially Stabilized Zirconia: Sliding vs. Rolling Contact," Scripta Metallurgical, 21, pp 1705-1710 (1987).
5. Proposal follow-on, No GP-895-Rev-B. Tribology of Improved Transformation Toughened Ceramics - Phase IIB, Ceramic Heat Engine Component Screening Test. (1990).
6. P. Chantikul, G.R. Anstis, B.R. Lawn, and D.B. Marshall, "A Critical Evaluation of Indentation Techniques for Measuring Fracture Toughness: II, Strength Method," J. Am. Ceram. Soc., 64 [9] 539-43 (1981).
7. H. Toraya, M.Yoshimura and S. Somiya, "Quantitative Analysis of Monoclinic-Tetragonal ZrO_2 System by X-ray Diffraction", J. Am. Ceram. Soc. 67 c 119-121 (1984)
8. Gangopadhyay, A., Cheng, H.S., Harman, S.T., and Corwin, J.M., "Evaluation of Tribological Performance of Ceramic Roller Followers," Presented at SAE Advanced Mobility Land Sea Air and Space Conf. at Detroit, MI, (Reprint #900401 Warrendale, PA), Feb. 26-Mar. 2, (1990).

9. E. Lilley, Review of Low Temperature Degradation in Zirconia (Y-TZP). Corrosion and Corrosive Degradation of Ceramics. Ceramic Transactions, V.10, Edited by R. Tressler and M. McNallan. (1990)
10. Zaretsky, E.V., "Ceramic Bearings for Use in Gas Turbine Engines," J. of Eng. for Gas Turbine and Power, 111, pp 146-157 (1989).
11. Bhushan, B. and Sibley, L.B., "Silicon Nitride Rolling Bearings for Extreme Operating Conditions," ASLE Trans., 25, 4, pp 417-428, (1982).

APPENDIX A

Cam Roller Follower Dimension Specifications

APPENDIX B

Tribology Testing of Cam Roller Follower

at The Torrington Company

by Joseph F. Braza

ZIRCONIA TAPPET - TRIBOLOGY TESTS

Research Project 30885

Joseph F. Braza

Advanced Technology Center

May 6, 1991

Prepared For: Torrington Contracts Department and
Norton Company

CONTENTS

1.	Executive Summary	
2.	Abstract	1
3.	Problem Statement	2
4.	Objectives	2
5.	Introduction	3
5.1	Material Processing, Mechanical Properties, and Microstructural Evaluation of the Ceramics	5
5.2	Microscopy of Unworn Surfaces	5
5.3	Test Apparatus	10
5.4	Preparation and Post-Examination Procedures	10
5.5	Test Procedure	13
5.6	Test Conditions	14
5.7	Film Thickness and Contact Stress Calculations	14
5.8	Roughness and Other Profilometer Data	15
6.	Results	16
6.1	Wear of Ceramic Roller	16
6.1.1	One Hour Test Results	16
6.1.2	Wear of the Steel Ring Surface	19
6.2	Friction Forces and Coefficients	26
6.3	Subsequent 4 Hour Tests	26
6.4	Effect of the Grinding Operation in the Ceramic Rollers	27

CONTENTS CONTINUED

7.	Conclusions	29
8.	Recommendations	30
9.	Acknowledgements	31
10.	References	31
	Figures	34
	Tables	37
	Appendix I Profilometer data of the ceramic rollers and mating steel rings before and after testing (see additional volume)	

1. EXECUTIVE SUMMARY

In this experimental investigation, the Torrington Company was subcontracted by the Norton Company to conduct a tribological investigation of several types of ceramic materials to determine their plausibility in a simulated roller follower/cam lobe system. The Torrington tester, located within the ATC, was used to conduct these single element rolling/sliding tests. The test environment was chosen to closely duplicate the valve train, where the normal load was 1557 N (350 lbs), the rolling velocity was 2.0 m/s (78.7 in/sec), the sliding component was approximately 1% of the rolling velocity, the lubricant type and temperature was Mobil 5W-30 and 93.3°C (200°F), respectively. Three types of ceramic materials were evaluated: three variations of zirconia toughened alumina (ZTA), two variations of transformation toughened zirconia (TTZ), and NBD-100 silicon nitride (Si_3N_4). The mating driving ring specimen was a through hardened 52100 steel that was circumferentially ground to comparable roughness levels of cam lobes used in Ford Modular engines (R_a varied between 0.125 and 0.175 μm [5 and 7 μin]).

On each ceramic type, three tests were conducted for a one hour interval. (Previously it was observed that this test length produced wear scars on the simulated cam lobe that adequately correlated with wear scars on cam lobes in valve train tests). With the exception of several TTZ ceramics, all of the ceramic rollers gained weight (order of magnitude of 10^{-5} gms) due to the transferring of steel to the surface. This transfer film was observed by viewing uncoated rollers in the scanning electron microscope. A polishing wear mode occurred on the steel rings tested against the ZTA and Si_3N_4 ceramics, while very little wear was observed on the steel rings tested against the TTZ ceramics. However, this polishing wear was not detrimental to the performance of this tribological system (friction coefficients generated with the ZTA rollers were equivalent to the friction coefficients generated with the TTZ rollers), and in fact, is similar to tests conducted against tumbled finished steel tappet rollers.

Subsequent four hour interval tests produced a weight loss on the ceramic roller (order of magnitude of 10^{-4} gms), which is due in part to the loss of the transfer film. This weight loss translates to less than 0.25 μm (10 μin) radial reduction in the roller diameter, which only accounts for the tips of the asperities, since no change in topography was observed or measured by profilometry. Also, the steel rings had no change in appearance after these subsequent four hour tests.

The friction forces (friction coefficients) were measured continuously on a strip chart recorder during the tests. The values of the friction coefficients ranged between 0.041 and 0.071, with an average value of 0.054. They correlate very well with the predicted values (approximately 0.064) obtained from EHL models. Also, there was not any relationship between the weight gain (or loss) and the friction coefficient or slide-to-roll ratios. This result confirms the theory that the friction force is due to the shearing of the lubricant film rather than the shearing of the steel or ceramic asperities, essentially after the initial run-in period.

On the as-ground surfaces of the ceramic rollers, each type of ceramic material exhibited a similar characteristic appearance: grain pullout on the ZTA ceramics, metallic-type grinding furrows on the TTZ ceramics, and an isotropic polishing with very faint grinding furrows on the Si_3N_4 NBD-100 ceramics. On several of the ceramic rollers, large surface defects were created during the finishing operation. However, these defects did not affect the performance of the ceramic rollers by producing a greater weight loss or causing more wear on the steel driving ring. This results suggests that a more aggressive grinding procedure can be utilized with faster feed rates and larger one-pass stock removal. Secondly, the ceramic roller roughness levels, which ranged between 0.125 to 0.2 μm (5 to 8 μin), were not detrimental to the performance of the simulated roller follower/cam lobe system.

2. ABSTRACT

Three types of ceramic materials were evaluated in a simulated tappet roller/cam lobe contact: zirconia toughened alumina (ZTA), transformation toughened zirconia (TTZ), and silicon nitride (Si_3N_4). The tribological evaluation of these materials was conducted with a single element tester using one test condition: normal load, 1557 N (350 lbs); rolling velocity, 2.0 m/sec (78.7 in/sec); test interval, 1 hour; lubricant type and temperature, Mobil 5W-30 and 93.3°C (200°F), sliding component, approximately 1%, and the steel mating roller component (AISI 52100 steel) was hardened and circumferentially ground to R_a 0.125 to 0.175 μm (5 to 7 μin). Weight loss and friction force measurements revealed that during this one hour test interval, steel was transferred to the ceramic roller, thereby producing a weight gain on the roller (order of magnitude of 10^{-5} gms). The steel driving ring had no measurable weight loss (from profilometer measurements), although it was observed that on the rings tested against the ZTA and Si_3N_4 ceramics exhibited a greater amount of polishing wear. This wear mode is not felt to be detrimental to the performance of this tribological system. Optical and scanning electron microscopy also confirmed that metal was transferred to the ceramic roller, and that no perceptible weight loss occurred on the ceramic roller specimens. It was observed that the finishing operation produced a characteristic surface texture on each ceramic material, and furthermore, large surface defects, generated by the finishing operation, did not affect the performance of this system.

3. PROBLEM STATEMENT

The Department of Energy (DOE) awarded the Norton Company a contract to investigate the tribological performance of various toughened zirconia and alumina ceramics as ceramic rollers in the valve train of a diesel engine. The major advantage of these ceramics over Si_3N_4 (NBD-100 or NBD-200) is their lower processing and powder costs. Although these types of ceramics are inferior to Si_3N_4 in high-Hertzian-contact-stress, single-element-rolling-contact-fatigue (RCF) tests, they have the potential to perform well at the lower contact stress levels of the application. (Our present RCF tests are conducted at contact stresses greater than 5.93 GPa (860 ksi), which depends upon the modulus of elasticity of the test specimens). Maximum Hertzian contact stresses on actual tappet roller/cam lobe contacts are usually less than 1.38 GPa (200 ksi) at the cam lobe tip. It is the purpose of this project to investigate these ceramics in a single element tester at contact stresses, speeds, and environments that closely duplicate the tappet roller/cam lobe system. These more realistic experimental tests will provide information into the performance and applicability of these ceramics for actual full-scale valve train tests.

There are two major reasons for fabricating roller followers out of ceramic materials. One reason is to eliminate the needle rollers thereby reducing the amount of components to two: the ceramic roller and the tappet shaft. Thus, the staking operation of the tappet shaft into the rocker arm assembly can be accomplished less precisely, without concern over losing the needle rollers from improper alignment of the shaft with the hole. Secondly, in diesel engines, the debris (soot) acts as an abrasive particle that can cause excessive wear on the 52100 steel tappet shaft over long time periods. The ceramic roller follower is a journal bearing, and when properly designed, the "soot" debris will not be able to enter the journal and hence, abrade the tappet shaft.

As a sub-contractor to this DOE funded project, Torrington will conduct the sliding/rolling tests, along with pre- and post-test evaluation of the ceramics. The tests will be conducted in the ATC using the Torrington tester, and will evaluate the ceramics in a rolling/sliding lubricated contact. The materials will be processed by the Norton Company, and they will also will have the ceramics specimens ground to the final geometry.

4. OBJECTIVES

The major objective of this study is to evaluate the tribological performance of three types of zirconia toughened alumina and two types of transformation toughened zirconia ceramics, plus NBD-100 Si_3N_4 , in simulated valve train tests. These simulated valve train tests will be conducted using the Torrington tester in the ATC, which consists of two mating components: a tappet roller and a cylindrical shaped specimen.

The test conditions are as follows:

- * Rolling speed - 2.0 m/sec (78.7 in/sec)
- * Slide-to roll ratio - 0.005 to 0.01
- * Maximum contact stress - 1.38 GPa (200 ksi) or 1557 N (350 lbs) normal load, stress depends on elastic modulus of ceramic material
- * Lubricant - SAE 5W-30
- * Lubricant temperature - 93.3°C (200°F)
- * Test duration - 1 hour

For each of the specimens tested the following will be performed:

- * Surface profile trace (pre-test)
- * Cleaning and weight measurement (pre-test)
- * Optical and SEM microscopy (pre-test)
- * Testing
- * Cleaning and weight measurement (post-test)
- * Surface profile trace (post-test)
- * Optical and SEM microscopy (post-test)

The following objectives are to be achieved:

- 1) Measure and record the friction force (i.e., friction coefficient) traces for the different ceramic materials.
- 2) Photograph the wear of the mating specimens after the specified test interval to observe the wear process.
- 3) Measure the weight loss and surface profile for each type of ceramic and determine wear rates for the above test conditions.
- 4) Conduct SEM post-test evaluation of the ceramics to determine the mechanism of wear.

5. INTRODUCTION

Although ceramics have high hardness, low density, and are more chemically inert compared to ferrous alloys, they have an inherently low fracture toughness, which limits their use in applications where stresses (bending or shear) are large or not easily isolated and contained. Additionally, impurities and pores created during the processing or flaws generated during the final grinding (or lapping) operation reduce the performance of the ceramic component. If these defects are in a highly stressed region, cracks can potentially initiate and propagate¹.

The inherent low fracture toughness is alleviated in zirconia ceramics by a phenomena called transformation toughening. The addition of a stabilizing refractory (such as magnesia (MgO) or yttria (Y₂O₃), lime (CaO)², cerium oxide [CeO₂]) in zirconia up to 5 to 20 weight percent, will increase its toughness considerably. These refractories stabilize the ordinarily metastable tetragonal phase at room temperature. This

tetragonal phase will transform into the monoclinic phase, particularly in the vicinity of a propagating crack. A volume expansion occurs during this transformation, which retards or blunts crack growth³. The fracture toughness of these transformation toughened zirconia ceramics is often reported to be two to three times larger than other ceramics⁴.

These other ceramics, such as silicon nitride, silicon carbide, or alumina, do not have this advantageous inherent transformation feature. This quality is shown to be beneficial in tribological contacts, as enumerated in various sliding wear studies⁴⁻⁷, where zirconia ceramics exhibited a high wear resistance. However, the major drawback of these tribological tests is that they simulate only low-speed, sliding, unlubricated applications, since the majority of experimental investigations were oriented toward high temperature environments.

Recently, an auto manufacturer (i.e., Chrysler) has shown a strong desire to replace the current steel tappet rollers with ceramic roller followers in gas or diesel engines. Extensive effort has been spent on evaluating the performance of ceramic roller followers in single element tests^{8,9} and in full-valve train tests^{10,11}. In the single element tests, which simulates a roller follower/cam lobe environment, results showed that partially stabilized zirconia (MgO stabilized PSZ) did not perform as well as silicon nitride⁸, although it produced a better sliding wear resistance. The inadequate performance of this MgO stabilized zirconia is primarily attributed to its large grain size (i.e., 60 μm), and secondly to the large quantity and size of pores in the material.

In a thesis by Braza⁹, grain size was found to be directly proportional to the wear rate, and that by reducing the grain size, the rolling contact behavior would be directly improved. This grain size reduction could be accomplished by utilizing a different processing technique or starting with a smaller powder size. In the case of partially stabilized zirconia, the grains (cubic) are approximately 60 μm in size. On the other hand, smaller grain size zirconia ceramics (the TTZ ceramics) can be fabricated by using stabilizing additives, such as Y_2O_3 or CeO_2 , that consist completely of 100% tetragonal phase with a much smaller grain structure, less than 3 μm . Furthermore, HIP'ing these TTZ ceramics on top of the sintering process further decreases the amount of pores and nucleation sites for crack propagation. This latter type of TTZ ceramic is favored over the former larger grain structure PSZ in rolling contact fatigue applications.

In motorized valve train tests^{10,11}, the cam roller followers were fabricated out of $\text{Al}_2\text{O}_3\text{-TiC}$, Y_2O_3 stabilized ZrO_2 , and two types of Si_3N_4 , along with 52100 steel rollers, which acted as the baseline material. The cam lobe material was nodular cast iron with a hardness of 630 Knoop_{500 gm} (55 HRC). Tests were conducted at intervals of 100 hours for a total test time of 900 hours. Measurements of the cam lobe tip showed that the reduction of the cam lobes tested against the ceramic roller followers was insignificant compared to the lobes tested against the steel rollers. It was interesting to observe that after 400 hours, the cam roller followers did not experience any material loss, and in fact, showed slight weight gains due to transfer of iron onto the surface.

This program will investigate three types of ceramics: zirconia toughened alumina (ZTA), transformation toughened zirconia (TTZ), and silicon nitride (NBD-100). The silicon nitride functions as the baseline

ceramic, since the performance of the TTZ and the ZTA ceramics will be compared to it. The ceramics will be evaluated in a simulated cam lobe environment, in which the ceramic specimen will be predominately rolling (with a small percent slippage) against a hardened steel ring. The results of the test will be ceramic roller weight loss, steel ring weight loss, and friction coefficients.

5.1 MATERIAL PROCESSING, MECHANICAL PROPERTIES, AND MICROSTRUCTURAL EVALUATION OF THE CERAMICS

The types of ceramics that were evaluated in this program are: two types of yttria stabilized zirconia (Y_2O_3 - ZrO_2), three types of cerium oxide stabilized zirconia (CeO_2 - ZrO_2), and silicon nitride (NBD-100). The processing methods, associated grain size, and weight percentages are listed as follows:

Z18CE60A Contains 62 wt% Al_2O_3 and the remainder is cerium oxide stabilized zirconia, CeO_2 - ZrO_2 . In the tetragonal ZrO_2 phase, 18.0 wt% (13.6 m%) CeO_2 is added for stabilization. Cold isostatic pressed, sintered, then HIP'ed at a temperature of 1600°C. Grain size 1-2 μm . The CeO_2 - ZrO_2 is dispersed in the Al_2O_3 matrix.

Z12CE70A Contains 70 wt% Al_2O_3 and remainder CeO_2 - ZrO_2 (composition and processing the same as Z18CE60A).

Z12CE70A Contains 70 wt% Al_2O_3 with remainder CeO_2 - ZrO_2 . The -T2 starting particle size is finer than Z12CE70A, but is processed differently.

YZ-110 Contains 4.8 wt% Y_2O_3 , grains are tetragonal in phase, 0.8 μm in size, sintered in air at 1500°C and HIP'ed at 1500°C.

MG-026 Contains 5.4 wt% Y_2O_3 , same processing as YZ-110. Note that slightly larger Y_2O_3 content increases the stability of the tetragonal phase.

NBD-100 HIP'ed Si_3N_4 powder, produced by CERBEC.

Bulk mechanical and thermal properties were not measured for each ceramic type; however, typical values of these ceramics are listed in Table 1.

5.2 MICROSCOPY OF UNWORN SURFACES

The ground surfaces of the ceramics are shown in Figs. 1-5, in which (a) is an optical photomicrograph at 100X, and (b) and (c) are scanning electron micrographs at 1000X and 5000X, respectively. The

final grinding operation produced different textures on the surface of each ceramic type. In the ZTA ceramics, Figs. 1a

Table 1. Physical properties of the ceramics.

Ceramic Type	E (GPa)	Poisson's ratio	α_{th} exp. ($\times 10^{-6}/^{\circ}\text{C}$)	Density (gm/cc)	K_{Ic} ($\text{MPa}\cdot\text{m}^{1/2}$)	H (GPa)
Z18CE60A	320	0.25	*	4.75	5.9	14.9
Z12CE70A	>320	0.25	*	4.55	4.8	14.4
Z12CE70A	>320	0.25	*	4.55	7.9	15.0
-T2						
YZ-110	220	0.22	11	6.08	7.3	13.5
MG-026	220	0.22	11	6.08	6.2	13.5
NBD-100	310	0.28	3.5	3.2	5	16.5

*Not measured at this time.

through 3b, the circumferential grind grooves are not nearly as distinct as the grooves in the TTZ ceramics, Figs. 4a through 5b.

In the Si_3N_4 ceramic rollers, very faint furrows are visible. SEM micrographs show considerable pullout of the grains in the ZTA ceramics, Figs. 1b, 1c, 2b, 2c, 3b, and 3c, which occurred uniformly over the entire surface (although more extensively in the Z12CE70A-T2 ceramics, which were not ground in the same batch with the other ceramic rollers). Alumina or alumina containing ceramics generally have poor grain boundary strength and fail by this mechanism, as observed by Swain¹² and later by Ajayi and Ludema¹³ during the dry sliding of a diamond tipped stylus across Al_2O_3 ceramics.

In the Y_2O_3 stabilized ZrO_2 , the furrows were much more prominent compared to the ZTA ceramics; however, grain pullout was not evident in these ceramics, although some brittle fracture occurred next to the deeper grinding grooves, Figs. 4b, 4c, 5b, and 5c. The grinding furrows in the TTZ ceramics are similar in morphology to the grinding grooves in the buffed-finished tappet rollers. (They exhibit a metal-like deformation behavior). Ajayi and Ludema¹³, similarly observed this plastic deformation wear mode in sintered Y_2O_3 stabilized ZrO_2 (13) during multiple-pass diamond tipped abrasion. The white specks in Figures 4b, 4c, 5b and 5c were later found to be removable with cleaning and are, therefore, assumed to be debris.

Unlike the other ceramics, the grinding grooves in the Si_3N_4 surface where very faint, Fig. 6a, and even hard to discern in higher magnification SEM micrographs, Fig. 6b and 6c. The finished ground Si_3N_4 rollers did not exhibit any brittle fracture mode; it was dominated by plastic deformation processes. This cutting mode was previously observed by Larchuk et al.¹⁴ on Si_3N_4 , where they modelled the single point grinding of glass, SiC, and Si_3N_4 .

Figure 1. Optical photomicrograph (a) and scanning electron micrographs at 1000X (b) and 5000X (c) of the Z18CE60A # 1 (ZTA) ceramic roller surface. Circumferential direction is oriented vertically.

Figure 2. Optical photomicrograph (a) and scanning electron micrographs at 1000X (b) and 5000X (c) of the Z12CE70A # 1 (ZTA) ceramic roller surface. Circumferential direction is oriented vertically.

Figure 3. Optical photomicrograph (a) and scanning electron micrographs at 1000X (b) and 5000X (c) of the Z12CE70A-T2 # 1 (ZTA) ceramic roller surface. Circumferential direction is oriented vertically.

Figure 4. Optical photomicrograph (a) and scanning electron micrographs at 1000X (b) and 5000X (c) of the YZ-110 # 2 (TTZ) ceramic roller surface. Circumferential direction is oriented vertically.

Figure 5. Optical photomicrograph (a) and scanning electron micrographs at 1000X (b) and 5000X (c) of the MG-026 # 1 (TTZ) ceramic roller surface. Circumferential direction is oriented vertically.

Figure 6. Optical photomicrograph (a) and scanning electron micrographs at 1000X (b) and 5000X (c) of the NBD-100 # 1 (Si_3N_4) ceramic roller surface. Circumferential direction is oriented vertically.

5.3 TEST APPARATUS

The Torrington tester was used to conduct these wear tests on the tappet rollers. This tester has been previously described in the closing report of project # 30770. Figures 7 and 8 show the schematic overview of the test apparatus and test configuration, respectively, which consists of the tappet roller and the driving ring specimen. The driving ring specimen is clamped onto a spindle drive unit, which is controlled by a variable speed drive. The tappet roller is mounted onto a shaft and held fixed to it by a retaining ring and collar unit. The opposite end of this shaft is placed through an air engine, which provides the slippage between the tappet roller and the driving ring. The speeds of the tappet roller and driving ring are measured by two separate tachometers that digitally display the speed in revolutions per minute. The slide-to-roll ratio can be determined from these readings, which is defined as,

$$S/R = \frac{2(v_{ring} - v_{cr})}{(v_{ring} + v_{cr})}$$

where v_{cr} = velocity of the ceramic roller, and
 v_{ring} = velocity of the driving steel ring.

The signals from the friction force and the normal load force transducers were displayed on a strip chart recorder for each test. The coefficient of friction was therefore obtained by dividing the friction force by the normal load. The reported value of the friction force was taken at the end of the test interval.

5.4 PREPARATION AND POST-EXAMINATION PROCEDURES

In order to assess the tribological behavior of the ceramic, the following preparation and post-examination was conducted on the ceramic rollers:

1. Trace the surfaces of the unworn tappet roller and driving ring with a profilometer.
2. Clean with acetone and coat the roller surface with germanium (Ge).

Fig. 7. Schematic drawing of the test apparatus.

Fig. 8. Specimen configuration.

3. Photograph surface with SEM at 1000X, 2000X, and 5000X.
4. Optically photograph the ceramic rollers and steel rings at 100X and 400X.
5. Remove Ge coating with diamond paste, clean roller in acetone, and bake for 1 hour at 300°F.
6. Cool for 1 hour in desiccator.
7. Weigh roller 5 times to obtain an average.
8. Test with 350 lbs normal load, with approximately 1 % slippage between ceramic roller and driving ring.
9. Disassemble from test assembly.
10. Clean in acetone and bake for 1 hour at 300°F.
11. Cool for 1 hour in desiccator.
12. Weigh roller 5 times and average them.
13. Photograph worn surface with the SEM (1000X, 2000X, and 5000X), and pre-coat it with Ge and optical microscope (100X and 400X).
14. Photograph the worn driving ring at 100X and 400X.
15. Trace the worn surface of ceramic roller and driving ring with a profilometer.
16. Calculate μ , slide-to-roll ratio, and % slippage from the acquired data.

5.5 TEST PROCEDURE

The test procedure consisted of assembling the test specimens onto the spindles, starting the lubrication system (this includes the heating element), bringing the driving ring up to the desired speed, applying the normal load, and adjusting the exit air flow of the air motor to obtain the appropriate slide-to-roll ratio. After the specified test interval (one hour), the reverse procedure was conducted. The worn region of the ceramic roller was then examined in the SEM to observe and photograph the wear mode.

5.6 TEST CONDITIONS

One test condition was used in this test procedure in order to evaluate the ceramic rollers. The normal load was 1557 N (350 lbs), a rolling velocity of 2.0 m/s ($n_{ring} = 775$ rpm), and a lubricant temperature of a 93.3°C (200°F - lubricant kinematic viscosity is approximately 10.4 cSt), with a slide-to-roll ratio ranging from 0.005 to 0.01 (percent slippage ranging from 0.5 to 1%) between the ceramic roller and the driving steel ring. The lubricant, Mobil 5W-30 engine oil, was heated and dripped onto the steel ring at an approximate rate of 1 drop/sec. The speed chosen for the driving ring was lower than the average operating speed of a cam lobe in the valve train. This was deliberately done to lower the film thickness and produce greater asperity contact. This effect was also achieved by heating the oil near the inlet zone and thus lowering its viscosity.

In the original contract proposal to ORNL (Oak Ridge National Laboratory), we proposed to (a) use a straight weight mineral oil, 10W and (b) test with a 0.003 slide-to-roll ratio. However, it was decided to use a 5W-30 multi-grade oil (Mobil) to better correlate the test results with those published in the literature and in-house data of simulated tappet roller tests. Furthermore, the 5W-30 oil was chosen, because automobile manufacturers, such as Chrysler, recommend the use of this oil in their 2.2 and 2.5 liter engines. In the second alteration, we originally proposed to use a slide-to-roll ratio of 0.003 (or 0.3% slippage), but we decided to use a larger value (approximately 1 %) that would better simulate the tappet roller/cam lobe system.

5.7 FILM THICKNESS AND CONTACT STRESS CALCULATIONS

In order to calculate the minimum film thickness, contact stress, friction forces (i.e., coefficient of friction), and various other parameters, a computer program called, General Elastohydrodynamic Lubrication (GEHLC), developed at the Center for Engineering Tribology at Northwestern University was used¹⁵. GEHLC is a FORTRAN based program that can be used for a multiplicity of tribological contacts such as: gear teeth, rolling bearings, cam roller followers, traction drives, etc. It adopts Dowson's¹⁶ and Chittenden's¹⁷ formulae to evaluate isothermal film thickness and Cheng's¹⁸ theory of the thermal correction factor. Also, by using Bair and Winer's¹⁹ analysis, a viscoelastic fluid model was employed that predicted the shear stresses and friction force of the contact zone. Table 2 lists the maximum Hertzian contact stress, P_{Max} , film thickness, h_{min} , friction force, F_f , and the accompanied coefficient of friction, μ , for the various ceramic roller types (the percent slippage is 1% in this calculation). The film thickness was constant for all the ceramic types, since it is primarily governed by the lubricant viscosity and oil temperature than the material type. The maximum Hertz pressure depends upon the elastic modulus and Poisson's ratio of the ceramic roller.

Table 2. Contact stress and film thickness of the ceramic roller/steel ring contact.

Ceramic Type	P _{Max} GPa (ksi)	h _{min} μm (μin)	F _f N (lbs)	μ
ZTA	1.45 (210.6)	0.12 (4.6)	102.3 (23.0)	0.066
Y ₂ O ₃ -ZrO ₂	1.29 (187.5)	0.12 (4.6)	97.4 (21.9)	0.062
NBD-100	1.44 (209.8)	0.12 (4.6)	101.8 (22.9)	0.065

5.8 ROUGHNESS AND OTHER PROFILOMETER DATA

Table 3 lists the roughness (R_a), peak-to-valley (P to V), and the bearing length ratio at 60% (t_p) for the ceramic rollers, with a 0.030" cutoff. (Appendix I lists other surface characterization parameters from the Form Talysurf profilometer). In some of the ceramics, large defects were observed on the ceramic roller surface; consequently the peak-to-valley was very erratic, as was measured in the NBD-100 #2 specimen.

Table 3. Profilometer measurements of the ceramic rollers.

Ceramic Type	#	R _a (μin)	P to V* (μin)	T _p (μin)
Z18CE60A	1	7.5	50.6	21.2
	2	8.1	53.3	27.2
	3	6.3	48.7	24.2
Z12CE70A	1	9.7	78.2	37.6
	2	6.8	52.4	21.5
	3	12.9	84.2	44.2
Z12CE70A -T2	1	4.4	37.6	14.9
	2	4.9	41.6	21.6
	3	6.5	43.6	19.6
MG-026	1	5.9	50.9	13.9
	2	5.8	45.7	14.5
	3	7.2	64.6	28.5
YZ-110	1	6.5	37.4	17.5
	2	5.0	47.1	17.6
	3	5.3	41.4	15.0
NBD-100	1	8.2	57.2	32.4
	2	8.4	160.3	32.7
	3	9.2	53.3	31.9

6. RESULTS

The major objective of this program is to experimentally determine in short interval tests whether the toughened zirconia ceramics will perform as well as Si_3N_4 , which is the standard ceramic material for hybrid ball bearings^{20,21}. In Table 4, the results of these tests are presented, which includes: the friction force and coefficient, speeds of the ceramic roller and driving ring, and weight loss of these two components. The friction force, the speeds of the ceramic roller and driving ring, and the slide-to-roll ratio are the values obtained at the end of the test intervals. The weight loss of the ceramic roller was measured at the end of the interval by the use of an analytical single pan balance, Mettler AE 240, which has an accuracy of 0.02 mg.

6.1 WEAR OF CERAMIC ROLLER

6.1.1 One Hour Test Results

The most significant and promising result of these tests is that a weight gain (instead of a weight loss) occurred on the majority of the ceramic rollers. On the average, the ZTA ceramics showed the largest amount of weight gain (with the exception of the Z12CE70A-T2 ceramic rollers due to improper grinding; the unworn surface of these rollers had a brownish hue, unlike the others two ZTA ceramics), followed by the Si_3N_4 ceramics, and thirdly by the TTZ ceramics. Although, several of the TTZ ceramics exhibited a small weight loss. This weight gain is due to the formation of a surface film on the ceramic roller surface during testing, where the frictional force shears the steel ring asperity tips. This shearing action causes some of the steel to be transferred to the ceramic roller surface by an adhesive smearing process.

This smeared surface film is best demonstrated by placing the tested ceramic rollers in the SEM without depositing any type of conductive coating (such as Au, C, or Ge) on the surface. Regions existed on the ceramic roller surface, where charging did not occur as observed on the Z18CE60A #1 roller specimen, as shown in Fig. 9. In Fig. 9b, excellent resolution was obtained at 1000X magnification of the thin surface film and the underlying untouched alumina (dark patches) and zirconia (light regions) grain structure. This transfer surface film was also observed on uncoated TTZ ceramics, MG-026 (Fig. 10a) and YZ-110 (Figs. 10b and 10c).

Table 4. Ceramic Roller Data

Material Type	Roller Type	#	One Hour Tests						
			F _F (lbs)	μ	N _{ring} (rpm)	N _{cr} (rpm)	S/R $\times 10^{-3}$	% Slip	Δ Wt. $\times 10^{-5}$ g
ZTA	Z18CE60A	1	21.50	.061	776	1664	4.7	.47	+6
		2	24.95	.071	775	1663	4.0	.40	+14
		3	23.84	.068	776	1663	5.3	.53	+15
	Z12CE70A	1	17.14	.049	779	1669	5.6	.55	+9
		2	16.30	.047	775	1656	8.2	.82	+6
		3	18.54	.053	777	1665	5.4	.54	+8
	Z12CE70-T2	1	22.94	.066	772	1651	5.6	.56	-10
		2	22.64	.065	772	1650	8.0	.80	-10
		3	22.10	.063	775	1654	9.4	.94	-6
TTZ	MG-026	1	21.20	.061	780	1658	13.5	1.3	-4
		2	17.74	.051	770	1649	6.0	.60	+10
		3	15.60	.045	770	1654	3.0	.30	+3
	YZ-110	1	20.00	.057	762	1628	8.4	.83	+7
		2	20.80	.059	782	1668	10.0	1.0	-2
		3	22.10	.063	780	1677	2.1	.21	.3
Si ₃ N ₄	NBD-100	1	17.40	.050	774	1656	6.9	.69	+6
		2	17.44	.050	774	1656	6.9	.69	+2
		3	17.44	.050	768	1644	6.4	.64	+8
Steel	Buffed	16	21.30	.061	774	1654	8.2	.81	N/A
	Tumbled	14	19.54	.056	784	1674	9.0	.89	N/A

			Subseq Four Hour Tests						
ZTA	Z18CE60A	2	22.14	.063	770	1651	4.8	.48	-9
	Z12CE70A	2	24.40	.070	777	1664	6.0	.60	+12
	Z12CE70-T2	1	22.64	.065	767	1640	7.6	.75	+12
TTZ	MG-026	2	25.50	.073	770	1648	6.6	.66	-21
	YZ-110	2	25.70	.073	774	1655	7.5	.75	-16
Si ₃ N ₄	NBD-100	3	25.00	.071	778	1664	7.3	.73	-8

Figure 9. Uncoated SEM micrograph of Z18CE60A # 1 roller after 1 hour testing showing (a) the smeared transfer layer and (b) higher magnification 1000X micrograph revealing the grain structure under the film.

Figure 10. SEM micrographs of transfer films on tested and uncoated ceramic rollers MG-026 # 3 (a), YZ-110 #3 at 100X (b) and 400X (c) magnification.

For the majority of the ceramic rollers, the worn ceramic rollers needed to be coated to observe the surface in the SEM. Figures 11-16 (a and b) are micrographs of representative worn surfaces after the one hour tests. The original grinding furrows and surface defects (from pulled out grains) is still evident in the ZTA ceramics, Figs. 11-13. Similarly, in the TTZ ceramics, Figs. 14 and 15, the grinding grooves are still present, but in these worn surfaces, the white spectacles are no longer evident, as they were on the ground surfaces, Figs. 3b, 3c, 4b, and 4c. There was also no perceptible wear on the NBD-100 rollers, Fig. 16, in fact, it was difficult to find any regions that could be considered to have experienced wear. Figure 17 (a and b) shows one possible region on the MG-026 roller surface, although it is possible that this damage could have occurred during the finishing operation.

Profilometer measurements were made on the worn ceramic surfaces and are listed in Appendix I. There were no measurable changes in surface roughness from the unworn surface of the ceramic rollers, consequently they are not tabulated within the text.

6.1.2 Wear of the Steel Ring Surface

Profilometer traces were conducted on the unworn and worn surfaces of the driving ring surface. Table 5 lists the surface roughness, peak-to-valley, and the bearing ratio at 60% for each ring, along with the average surface roughness before/after ratio. The steel rings tested against the ZTA ceramics show the largest change in roughness, followed by the steel rings tested against Si_3N_4 , while the rings tested against the TTZ ceramics exhibited little wear. Photomicrographs of the steel rings before and after testing against a representative ceramic type are shown in Figs. 18-20 (a and b), respectively. Figure 18 corresponds to the steel ring tested against Z12CE70A #2 (ZTA); Fig. 19 corresponds to the steel ring tested against YZ-110 #3 (TTZ); Fig. 20 corresponds to the steel ring tested against NBD-100 #2 (Si_3N_4). The steel rings tested against the ZTA ceramics show a greater amount of polishing wear, followed by the rings tested against the Si_3N_4 ceramics, with little to no observable wear on the driving ring that was tested against the YZ-110 roller.

The degree of polishing on the ring can be related to (a) the modulus of elasticity and (b) the surface texture of the ceramic rollers. The higher modulus ZTA ceramics produced a slightly greater Hertzian contact stress (and smaller contact area) on the steel driving ring compared to the TTZ ceramics (see Table 2).

Figure 11. Worn SEM micrographs of Z18CE60A # 1 (ZTA) ceramic roller surface after 1 hour testing at (a) 1000X and (b) 5000X magnification.

Figure 12. Worn SEM micrographs of Z12CE70A # 1 (ZTA) ceramic roller surface after 1 hour testing at (a) 1000X and (b) 5000X magnification.

Figure 13. Worn SEM micrographs of Z12CE70A-T2 # 1 (ZTA) ceramic roller surface after 1 hour testing at (a) 1000X and (b) 5000X magnification.

Figure 14. Worn SEM micrographs of YZ-110 # 3 (TTZ) ceramic roller surface after 1 hour testing at (a) 1000X and (b) 5000X magnification.

(a)

(b)

Figure 15. Worn SEM micrographs of MG-026 # 1 (TTZ) ceramic roller surface after 1 hour testing at (a) 1000X and (b) 5000X magnification.

(a)

(b)

Figure 16. Worn SEM micrographs of NBD-100 # 3 (Si_3N_4) ceramic roller surface after 1 hour testing at (a) 1000X and (b) 5000X magnification.

This higher contact stress causes a greater amount of wear. Secondly, the ground surfaces of the ZTA ceramics exhibited a substantial amount of grain pullout that leaves sharp exposed edges (Figs. 1-3), whereas the ground surfaces of the TTZ (Figs. 4 and 5) and Si_3N_4 ceramics (Fig. 6) do not have regions of grain pullout and the concomitant sharp edges. The rough edges that border the regions of the regions of pulled out grains penetrate through the lubricant film and polish off the steel asperity tips in the run-in period.

Table 5. Before and after profilometer measurements on the steel driving ring specimens (units are μin).

Ceramic Type	#	R_a	P to V*	T_p
		Before(After)	Before(After)	Before(After)
Z18CE60A	1	6.2(4.7)	67.9(70.4)	30.0(22.3)
	2	7.1(5.1)	72.1(54.6)	29.1(18.0)
	3	6.1(4.7)	48.2(47.2)	23.1(13.8)
	Average	6.5(4.8)=1.35		
Z12CE70A	1	6.3(4.5)	64.2(34.9)	32.8(12.5)
	2	6.7(5.8)	60.4(42.2)	24.3(22.5)
	3	4.3(3.2)	36.6(35.2)	14.1(13.5)
	Average	5.8(4.5)=1.29		
Z12CE70A -T2	1	5.6(4.5)	63.6(47.7)	23.8(18.7)
	2	6.0(5.6)	55.5(50.3)	20.9(15.5)
	3	5.6(5.2)	55.2(51.4)	20.5(17.2)
	Average	5.7(5.1)=1.12		
MG-026	1	5.0(4.6)	39.1(56.6)	16.0(14.1)
	2	5.9(5.9)	47.2(43.0)	18.6(17.5)
	3	5.8(5.6)	59.1(59.6)	23.6(16.3)
	Average	5.6(5.4)=1.04		
YZ-110	1	5.5(5.2)	52.0(41.9)	19.8(16.1)
	2	4.7(5.7)	41.2(53.3)	15.2(18.2)
	3	6.5(5.3)	73.5(48.7)	29.0(17.5)
	Average	5.6(5.4)=1.04		
NBD-100	1	5.3(5.0)	57.6(55.1)	28.0(13.6)
	2	5.8(4.5)	63.0(44.3)	38.6(18.8)
	3	6.4(5.2)	64.2(50.8)	27.0(17.2)
	Average	5.8(4.9)=1.18

Figure 17. A damaged zone on the MG-026 # 3 ceramic roller surface after testing, which may have been caused during the finishing operation
(a) 1000X and (b) 5000X magnification.

Figure 18. Photomicrographs of the steel ring tested against the Z12CE70A # 2 ceramic roller
(a) before and (b) after testing. This polishing wear is representative of the steel rings tested against the other ZTA ceramics.

Figure 19. Photomicrographs of the steel ring tested against the YZ-110 # 3 ceramic roller (a) before and (b) after testing. Very little wear occurred on the rings tested against the TTZ ceramics.

Figure 20. Photomicrographs of the steel ring tested against the NRD-100 # 2 ceramic roller (a) before and (b) after testing. The polishing wear mode of the rings tested against the Si_3N_4 rollers were similar appearance to the rings tested against the ZTA rollers.

6.2 FRICTION FORCES AND COEFFICIENTS

In the test configuration, Fig. 8, the ceramic roller is mounted onto a shaft, which is connected to an air motor by a flexible coupling. By restricting the exit air flow of the air motor, the ceramic roller speed is reduced, and a traction (or friction force) is created in the contact zone. (Table 4 lists the slide-to-roll ratios for each test, and the resulting friction force and coefficient). It was attempted to obtain a slide-to-roll ratio of 0.01 for each test condition, but with the current tester, it was difficult to obtain this value. (This limitation will be rectified in the future by incorporating a computer controlled metering valve). The speeds of the ceramic roller and the driving ring are not completely independent of each other. In other words, when the rotational speed of the ceramic roller is reduced, the driving ring speed is also reduced, and thus the slide-to-roll ratio remains nearly the same. More importantly, the slide-to-roll ratio remained very constant for each test, even though there existed variation between tests. However, in the majority of tests, the resulting slide-to-roll ratio was higher than the original proposed value of 0.3% slippage, giving a more severe test condition.

The friction coefficients correlate very well with the predicted values in Table 2 and analytical EHL models that are concisely defined in Cheng²². The friction force is due to the shearing of the lubricant in the contact zone, not the asperity contact, since after initial run-in wear, little steel/ceramic asperity contact occurs. The friction forces and resulting coefficients are strongly dependent upon the viscosity of the lubricant, sliding velocity, lubricant temperature, and contact stress, while it is moderately dependent on the material properties of the rubbing components. Also, there is not any relationship between the slide-to-roll ratio and the weight gain (or loss) of the ceramic roller, which further confirms that little asperity contact occurs after the run-in.

6.3 SUBSEQUENT 4 HOUR TESTS

According to the original contract, the test interval was only to be conducted for a one hour test interval, which adequately screens the rollers as shown in previous steel tappet roller tests (Project # 30830). Nonetheless, subsequent 4 hour tests were conducted on one of the ceramic rollers of each type. The results of these tests are given in Table 4, which shows that a weight loss occurred for all the ceramic types, with the exception of the Z12CE70A roller. This weight loss is not detrimental, since it accounts for less than $0.03 \mu\text{m}$ ($0.1 \mu\text{in}$) radial reduction of the ceramic roller (note: the peak to valley measurements, as listed in Table 3, are greater than $1 \mu\text{m}$ [$40 \mu\text{in}$]). Secondly, it is possible this weight loss is due to the loss of the surface film that formed on the roller during the initial run-in. Furthermore, there was no perceptible increase in wear on the steel ring or change in its surface roughness after this four hour interval.

6.4 EFFECT OF THE GRINDING OPERATION ON THE CERAMIC ROLLERS

Since the grinding of the rollers were contracted to a outside machine shop, the finishing procedure of the ceramic rollers is not known. On several of the rollers, large surface defects (greater than 200 μm in length) were observed as shown in Figs. 21 and 22 (a and b), which are optical and SEM micrographs of MG-026 #3 and NBD-100 #2, respectively. Surface defects of this size are very undesirable, since they are potential sites for crack initiation or regions where localized stresses can enlarge the defect. However, there is not any evidence that these defects were detrimental to the roller performance, since there was not any associated weight loss or noticeable increase in their size (even though these defects were not photographed before testing). These results suggest that the finishing operation can be more aggressive (i.e., faster feed rates, greater stock removal on each grind pass, etc.), since it is not so necessary to produce a defect free surface.

Secondly, it is generally felt that poor finishing practices will significantly reduce the strength and RCF life of ceramics²⁵, particularly in ball bearing applications, since they fail by the spalling fatigue mechanism²¹. However, these tests have proven that roughness levels approaching 0.25 μm (10 μin) are not detrimental to the performance of the ceramic roller/driving ring system, and furthermore, the wear (if it occurs) is not by a spalling mechanism, but rather by a fine scale microchipping mechanism⁸⁻¹¹. In the roller follower/cam lobe system, the ceramic component is not subjected to such high localized Hertzian contact stresses on the micro-asperity scale (as is developed in other single element testers or in some ball bearing applications), therefore the lower cost finishing processes can be utilized.

Figure 21. Surface defects on the MG-026 # 3 ceramic roller generated by the finishing operation, (a) optical photomicrograph, 200X before testing and (b) scanning electron micrograph, 1000X, after testing.

Figure 22. Surface defects on the NBD-100 # 2 ceramic roller generated by the finishing operation, scanning electron micrographs after testing at (a) 1000X and (b) 5000X magnification.

7. CONCLUSIONS

Simulated roller follower/cam lobe tests have been conducted with a single element tester, where the roller follower is fabricated out of three types of ceramic materials: zirconia toughened alumina, yttria stabilized zirconia, and silicon nitride. Tests conditions were chosen to adequately simulate this tribological system. The normal load was 1557 N (350 lbs) (contact stresses ranged from 1.29 to 1.45 GPa (187 to 210 ksi), rolling speed was 2.0 m/sec (78.7 in/sec), oil temperature was 93.3°C (200°F), and average percent slippage was 0.6%. These ceramic rollers were processed at the Norton Company and finished at an outside machine shop. Weight measurements after one hour interval tests showed that the majority of the rollers experienced a weight gain (order of magnitude of 10^{-5} gms), which is due to the formation of a transfer film (probably an iron oxide). This transfer film was observed in the SEM without previously coating the roller surface. Subsequent four hour tests produced a small weight loss on the ceramic roller (order of magnitude of 10^{-4} gm); however, it is insignificant and probably due to the removal of the transfer film.

The driving ring component was a through hardened 52100 steel. Surface roughness measurements before and after testing reveal that the ZTA ceramics caused a greater amount of wear followed closely by the Si_3N_4 ceramics. No perceptible change in surface roughness was measured (by profilometer) or observed (with optical microscope) on the steel rings tested against the TTZ ceramics. The steel ring experienced a polishing wear mode, which was similar to rings that were tested against tumbled tappet rollers in a previous project (# 30830). However, it is felt that this wear is not detrimental to the performance of this system, since it is only a run-in wear phenomena. In the subsequent four hour tests, the steel rings did not experience any polishing or change in roughness.

The values of the friction coefficients ranged between 0.041 and 0.071, with an average value of 0.054. They correlate very well with the predicted values (approximately 0.064) obtained from EHL models. Also, there was not any relationship between the weight gain (or loss) and the friction coefficient or slide-to-roll ratios. This result confirms the theory that the friction force is due to the shearing of the lubricant film rather than the shearing of the steel or ceramic asperities, particularly after the initial run-in wear.

The finishing operation produced a different surface appearance for each ceramic type. Grain pullout occurred in the ZTA ceramics, but was not observed in the TTZ or Si_3N_4 ceramics. The ground surfaces of the TTZ ceramics had an appearance similar to ground steel surfaces with deep grinding furrows. In the Si_3N_4 rollers, the surfaces exhibited an isotropic appearance, with very faint grinding grooves. On several of the TTZ rollers and on one of the Si_3N_4 rollers, large surface defects and score marks were observed on the as-ground surface. However, these surface defects did not seemingly affect the performance of the rollers in these tests.

8. RECOMMENDATIONS

The ceramic "tappet roller" design (also called cam roller followers) consists of two components: a ceramic roller and a steel shaft - essentially a 360° journal bearing. This roller follower design would eliminate the roller pins, alleviate manufacturing assembly complications, and diminish shaft wear. A strong proponent behind this design is Chrysler Corporation; however, Ford and GM have recently shown strong interest in this design. This roller follower design has shown successful performance at Northwestern University (and recently within the ATC), as well as in engine tests at Chrysler and Northwestern University.

The major limiting factor of the ceramic roller followers is their high material and processing cost, particularly silicon nitride (Si_3N_4) ceramics. However, lower cost ceramics, such as zirconia toughened alumina (ZTA) or transformation toughened zirconia (TTZ) ceramics, need to be more thoroughly examined in this application. The low cost of Al_2O_3 in the ZTA composite (which can contain up to 80% Al_2O_3) and the potential elimination of the hot isostatic pressing (HIP) process make the ZTA ceramic material the most cost competitive material option.

In previous test results obtained on single element tests at Northwestern University, ZTA and TTZ ceramics have not performed as well as Si_3N_4 ceramics. However, the reported weight loss is insignificant, since no reduction in diameter occurred. Second, the ZTA and TTZ ceramics tested in those studies were inferior in quality compared to Norton's current materials. Third, the tester did not incorporate a traction force between the roller follower and the simulated cam ring (this tester was designed and built by J.F. Braza for his Ph.D. thesis).

The successful performance of the ZTA and TTZ ceramics in this project are encouraging, since they prove that less expensive ceramic materials (ZTA and TTZ) could be cost competitive with our current steel tappet rollers. The missing pieces of this work and the goals of this program are to develop finishing technology, particularly the crown grinding operation, and to evaluate the tribology of these ceramic roller followers in single element and full engine tests.

9. ACKNOWLEDGEMENTS

The author would like to thank the Norton Company for the DOE subcontracted project. He also expresses deep gratitude to Mr. Shea R. Jefferson and Mr. Donald T. Church for all their valuable laboratory work.

10. REFERENCES

- (1) Braza, J.F., Cheng, H.S., Fine, M.E., Gangopadhyay, A., Keer, L.M., and Worden, R.E., "Mechanical Failure Mechanisms in Ceramic Sliding and Rolling Contacts," *Tribology Trans.*, 32, 1, pp 1-8 (1989).
- (2) Garvie, R.C., Hannink, R.H.J., and Pascoe, R.T., "Ceramic Steel," *Nature (London)*, 258 [5537], pp 703-704 (1975).
- (3) Pascoe, R.T., Hannink, R.H.J., and Garrie, R.C., Science of Ceramics, Vol. 9, 1977.
- (4) Hannink, R.H.J., Murray, M.J., and Scott, H.G., "Friction and Wear of Partially Stabilized Zirconia: Basic Science and Practical Applications," *Wear*, 100, pp 355-366 (1984).
- (5) Trabelsi, R., Treheux, D., Orange, G., Fantozzi, G., Homerin, P., and Thevenot, F., "Relationship Between Mechanical Properties and Wear Resistance of Alumina-Zirconia Ceramic Composites," *Tribology Trans.*, 32, 1, pp 77-84 (1989).
- (6) Aronov, V. and Mesyef, T., "Wear in Ceramic/Ceramic and Ceramic/Metal Reciprocating Sliding Contact, Part 1," *ASME Trans., J. Tribology*, 108, pp 16-27 (1986).
- (7) Fischer, T.E., Anderson, M.P., Jahanmir, S., and Salher, R., "Friction and Wear of Tough and Brittle Zirconia in Nitrogen, Air, Water, Hexadecane and Hexadecane Containing Steric Acid," Wear of Materials, K.C. Ludema, ed., pp 257-266 (1987).
- (8) Braza, J.F., Cheng, H.S., and Fine, M.E., "Wear of Partially Stabilized Zirconia: Sliding vs. Rolling Contact," *Scripta Metallurgical*, 21, pp 1705-1710 (1987).
- (9) Braza, J.F., "Wear of Ceramics in Lubricated Sliding and Rolling Contact," Ph.D. Thesis, Northwestern Univ., Evanston, Il, (June, 1988).

- (10) Gangopadhyay, A., Cheng, H.S., Harman, S.T., and Corwin, J.M., "Evaluation of Tribological Performance of Ceramic Roller Followers," Presented at SAE Advanced Mobility Land Sea Air and Space Conf. at Detroit, MI, (Reprint # 900401 Warrendale, PA), Feb. 26-Mar. 2, 1990.
- (11) Gangopadhyay, A., Cheng, H.S., Braza, J.F., Harman, S.T., and Corwin, J.M., "Tribological Performance of Ceramic Cam Roller Followers," Wear of Ceramics, ed. S. Jahanmir, Marcel Dekker, New York (to be published in 1991).
- (12) Swain, M.V., "Microscopic Observations of Abrasive Wear of Polycrystalline Alumina," Wear, 35, pp 185-189 (1975).
- (13) Ajayi, O.O. and Ludema, K.C., "Surface Damage of Structural Ceramics: Implications for Wear Modeling," Wear of Materials, ASME, New York, Ed. K.C. Ludema, pp 349-360 (1987).
- (14) Larchuk, T.J., Conway, J.C., and Kirchner, H.P., "Crushing as a Mechanism of Material Removal During Abrasive Machining," J. Am. Cer. Soc., 68, 4, pp 209-215 (1985).
- (15) Zhu, D. and Cheng, H.S., "An Analysis and Computational Procedure for EHL Film Thickness, Friction and Flash Temperature in Line and Point Contact," Tribology Trans., 32, 3, pp 364-370 (1989).
- (16) Dowson, D. and Toyoda, S., "A Central Film Thickness Formula for Elastohydrodynamic Line Contacts," Proceedings 5th Leeds Lyon Symposium on Tribology, pp. 60-65 (1978).
- (17) Chittenden, R.J., Dowson, D., Dunn, J.F., and Taylor, C.M., "A Theoretical Analysis of the Isothermal Elastohydrodynamic Lubrication for Concentrated Contacts," (Part I and Part II), Proceedings of the Royal Society, London, Series A, Vol. 397, pp 245-294 (1985).
- (18) McGreen, J.M., Gu, A., Cheng, H.S., and Murray, S.F., "Elastohydrodynamic Lubrication - Preliminary Design Manual," Technical Report AFAPL-TR-70-27, Aero Propulsion Laboratory, Air Force Systems Command, Wright-Patterson Air Force Base, Ohio (Nov. 1970).
- (19) Bair, S. and Winer, W.O., "A Rheological Model for Elastohydrodynamic Contacts Based on Primary Laboratory Data," J. of Lub. Tech., Trans. ASME, Series F, Vol. 101, No. 3, pp 258-265, (1979).

- (20) Aramaki, H., Shoda, Y., Morishita, Y., and Sawamoto, T.,
"The Performance of Ball Bearings with Silicon Nitride Ceramic
Balls in High Speed Spindles for Machine Tools," J. of Trib.,
110, pp 693-698 (1988).
- (21) Zaretsky, E.V., "Ceramic Bearings for Use in Gas Turbine
Engines," J. of Eng. for Gas Turbines and Power, 111, pp 146-157
(1989).
- (22) Cheng, H.S., "Elastohydrodynamic Lubrication," Handbook of
Lubrication, Vol. II, CRC Press, ed. E.R. Boose, Boca Raton,
FL, pp 139-162 (1984).
- (23) Bhushan, B. and Sibley, L.B., "Silicon Nitride Rolling
Bearings for Extreme Operating Conditions," ASLE Trans.,
25, 4, pp 417-428, (1982).

LIST OF FIGURES

- Figure 1. Optical photomicrograph (a) and scanning electron micrographs at 1000X (b) and 5000X (c) of the Z18CE60A # 1 (ZTA) ceramic roller surface. Circumferential direction is oriented vertically ... 7
- Figure 2. Optical photomicrograph (a) and scanning electron micrographs at 1000X (b) and 5000X (c) of the Z12CE70A # 1 (ZTA) ceramic roller surface. Circumferential direction is oriented vertically ... 7
- Figure 3. Optical photomicrograph (a) and scanning electron micrographs at 1000X (b) and 5000X (c) of the Z12CE70A-T2 # 1 (ZTA) ceramic roller surface. Circumferential direction is oriented vertically ... 8
- Figure 4. Optical photomicrograph (a) and scanning electron micrographs at 1000X (b) and 5000X (c) of the YZ-110 # 2 (TTZ) ceramic roller surface. Circumferential direction is oriented vertically ... 8
- Figure 5. Optical photomicrograph (a) and scanning electron micrographs at 1000X (b) and 5000X (c) of the MG-026 # 1 (TTZ) ceramic roller surface. Circumferential direction is oriented vertically ... 9
- Figure 6. Optical photomicrograph (a) and scanning electron micrographs at 1000X (b) and 5000X (c) of the NBD-100 # 1 (Si_3N_4) ceramic roller surface. Circumferential direction is oriented vertically ... 9
- Figure 7. Schematic drawing of the test apparatus 11
- Figure 8. Specimen configuration 12
- Figure 9. Uncoated SEM micrograph of Z18CE60A # 1 roller after 1 hour testing showing (a) the smeared transfer layer and (b) higher magnification 1000X micrograph revealing the grain structure under the film 18
- Figure 10. SEM micrographs of transfer films on tested and uncoated ceramic rollers MG-026 # 3 (a), YZ-110 #3 at 100X (b) and 400X (c) magnification 18
- Figure 11. Worn SEM micrographs of Z18CE60A # 1 (ZTA) ceramic roller surface after 1 hour testing at (a) 1000X and (b) 5000X magnification 20

FIGURES CONTINUED

- Figure 12. Worn SEM micrographs of Z12CE70A # 1 (ZTA) ceramic roller surface after 1 hour testing at (a) 1000X and (b) 5000X magnification 20
- Figure 13. Worn SEM micrographs of Z12CE70A-T2 # 1 (ZTA) ceramic roller surface after 1 hour testing at (a) 1000X and (b) 5000X magnification 21
- Figure 14. Worn SEM micrographs of YZ-110 # 3 (TTZ) ceramic roller surface after 1 hour testing at (a) 1000X and (b) 5000X magnification 21
- Figure 15. Worn SEM micrographs of MG-026 # 1 (TTZ) ceramic roller surface after 1 hour testing at (a) 1000X and (b) 5000X magnification 22
- Figure 16. Worn SEM micrographs of NBD-100 # 3 (Si_3N_4) ceramic roller surface after 1 hour testing at (a) 1000X and (b) 5000X magnification 22
- Figure 17. A damaged zone on the MG-026 # 3 ceramic roller surface after testing, which may have been caused during the finishing operation (a) 1000X and (b) 5000X magnification 24
- Figure 18. Photomicrographs of the steel ring tested against the Z12CE70A # 2 ceramic roller (a) before and (b) after testing. This polishing wear is representative of the steel rings tested against the other ZTA ceramics 24
- Figure 19. Photomicrographs of the steel ring tested against the YZ-110 # 3 ceramic roller (a) before and (b) after testing. Very little wear occurred on the rings tested against the TTZ ceramics 25
- Figure 20. Photomicrographs of the steel ring tested against the NBD-100 # 2 ceramic roller (a) before and (b) after testing. The polishing wear mode of the rings tested against the Si_3N_4 rollers were similar appearance to the rings tested against the ZTA rollers 25

FIGURES CONTINUED

- Figure 21. Surface defects on the MG-026 # 3 ceramic roller generated by the finishing operation, (a) optical photomicrograph (200X) before testing and (b) scanning electron micrograph (1000X) after testing 28
- Figure 22. Surface defects on the NBD-100 # 2 ceramic roller generated by the finishing operation, scanning electron micrographs after testing at (a) 1000X and (b) 5000X magnification 28

LIST OF TABLES

Table 1.	Physical Properties of the Ceramics	6
Table 2.	Contact Stress and Film Thickness of the Ceramic Roller/Steel Ring Contact	15
Table 3.	Profilometer Measurements of the Ceramic Rollers	15
Table 4.	Ceramic Roller Data	17
Table 5.	Before and After Profilometer Measurements on the Steel Driving Ring Specimens	23

INTERNAL DISTRIBUTION

1-2.	Central Research Library	42.	M. G. Jenkins
3.	Document Reference Section	43.	D. R. Johnson
4-5.	Laboratory Records Department	44.	W. F. Jones
6.	Laboratory Records, ORNL RC	45.	D. Joslin
7.	ORNL Patent Section	46.	R. R. Judkins
8-10.	M&C Records Office	47.	M. A. Karnitz
11.	L. F. Allard, Jr.	48.	M. R. Kass
12.	L. D. Armstrong	49-53.	B. L. P. Keyes
13.	P. F. Becher	54.	H. D. Kimrey, Jr.
14.	R. F. Bernal	55.	T. G. Kollie
15.	T. M. Besmann	56.	K. C. Liu
16.	P. J. Blau	57.	E. L. Long, Jr.
17.	A. Bleier	58.	W. D. Manly
18.	E. E. Bloom	59.	R. W. McClung
19.	K. W. Boling	60.	D. J. McGuire
20.	R. A. Bradley	61.	J. R. Merriman
21.	C. R. Brinkman	62.	D. L. Moses
22.	V. R. Bullington	63.	T. A. Nolan
23.	R. S. Carlsmith	64.	A. E. Pasto
24.	P. T. Carlson	65.	J. L. Rich
25.	G. M. Caton	66.	C. R. Richmond
26.	S. J. Chang	67.	J. M. Robbins
27.	R. H. Cooper, Jr.	68.	M. L. Santella
28.	B. L. Cox	69.	A. C. Schaffhauser
29.	D. F. Craig	70.	S. Scott
30.	S. A. David	71.	G. M. Slaughter
31.	J. H. DeVan	72.	E. J. Soderstrom
32.	J. L. Ding	73.	D. P. Stinton
33.	M. K. Ferber	74.	R. W. Swindeman
34.	F. M. Foust	75.	V. J. Tennery
35.	W. Fulkerson	76.	T. N. Tiegs
36.	R. L. Graves	77.	J. R. Weir, Jr.
37.	D. L. Greene	78.	B. H. West
38.	M. H. Harris	79.	F. W. Wiffen
39.	E. E. Hoffman	80.	S. G. Winslow
40.	C. R. Hubbard	81.	J. M. Wyrick
41.	M. A. Janney	82.	C. S. Yust

EXTERNAL DISTRIBUTION

83. James H. Adair
University of Florida
Materials Science and
Engineering
317 MAE Bldg.
Gainesville, FL 32611-2066
84. Donald F. Adams
University of Wyoming
Mechanical Engineering
Department
P. O. Box 3295
Laramie, WY 82071
85. Jalees Ahmad
AdTech Systems Research, Inc.
1342 North Fairfield Road
Dayton, OH 45432-2698
86. Yoshio Akimune
NISSAN Motor Co., Ltd.
Materials Research Laboratory
1 Natsushima-Cho
Yokosuka 237
JAPAN AIR MAIL
87. Mufit Akinc
Iowa State University
322 Spedding Hall
Ames, IA 50011
88. Ilhan A. Aksay
University of Washington
Materials Science and Engineering
Department, FB-10
Seattle, WA 98195
89. R. G. Alexander
BASE
26 Malvern Close
Kettering Northants NN16 8JP
UNITED KINGDOM AIR MAIL
90. Richard L. Allor
Ford Motor Company
Material Systems
Reliability Department
20000 Rotunda Drive
P.O. Box 2053, Room S-2031
Dearborn, MI 48121-2053
91. Richard T. Alpaugh
U.S. Department of Energy
Advanced Propulsion Division
CE-322, Forrestal Building
Washington, DC 20585
92. Joseph E. Amaral
Instron Corporation
Corporate Engineering Office
100 Royale Street
Canton, MA 02021
93. Edward M. Anderson
Aluminum Company of America
North American Industrial
Chemicals Division
P.O. Box 300
Bauxite, AR 72011
94. Norman C. Anderson
Ceradyne, Inc.
Ceramic-to-Metal Division
3169 Redhill Avenue
Costa Mesa, CA 92626
95. Don Anson
Battelle Columbus Laboratories
Thermal Power Systems
505 King Avenue
Columbus, OH 43201-2693
96. Thomas Arbanas
G.B.C. Materials Corporation
580 Monastery Drive
Latrobe, PA 15650-2698
97. Frank Armatis
3M Company
3M Center
Building 60-1N-01
St. Paul, MN 55144-1000
98. Everett B. Arnold
Detroit Diesel Corporation
Mechanical Systems Technology
13400 Outer Drive, West
Detroit, MI 48239-4001
99. Richard M. Arons
PA Consulting Group
279 Princeton Road
Hightstown, NJ 08550

100. Bertil Aronsson
Sandvik AB
S-12680
Stockholm Lerkrogsvagen 19
SWEDEN AIR MAIL
101. Dennis Assanis
University of Illinois
Department of Mechanical
Engineering
1206 W. Green Street
Urbana, IL 61801
102. William H. Atwell
Dow Corning Corporation
3901 South Saginaw Road
MS:540
Midland, MI 48686-0995
103. V. S. Avva
North Carolina A&T State
University
Department of Mechanical
Engineering
Greensboro, NC 27411
104. Patrick Badgley
Adiabatics, Inc.
3385 Commerce Drive
Columbus, IN 47201
105. Sunggi Baik
Pohang Institute of Science
& Technology
Department of Materials
Science and Engineering
P.O. Box 125
Pohang 790-600
KOREA AIR MAIL
106. John M. Bailey
Caterpillar, Inc.
Technical Center
Building L
P.O. Box 1875
Peoria, IL 61656-1875
107. Bob Baker
Ceradyne, Inc.
3169 Redhill Avenue
Costa Mesa, CA 92626
108. Frank Baker
Aluminum Company of America
Alcoa Technical Center
Alcoa Center, PA 15069
109. J. G. Baldoni
GTE Laboratories Inc.
40 Sylvan Road
Waltham, MA 02254
110. Clifford P. Ballard
Allied-Signal, Inc.
Ceramics Program
P.O. Box 1021
Morristown, NJ 07962-1021
111. M. Balu
Amoco Performance Products Inc.
4500 McGinnis Ferry Road
Alpharetta, GA 30202
112. B. P. Bandyopadhyay
Toyohashi University of Technology
School of Production Systems
Engineering
Tempaku-Cho Toyohashi 440
JAPAN AIR MAIL
113. P. M. Barnard
Ruston Gas Turbines Limited
Metallurgical Laboratory
P. O. Box 1
Lincoln LN2 5DJ
ENGLAND AIR MAIL
114. Harold N. Barr
Hittman Corporation
9190 Red Branch Road
Columbia, MD 21045
115. Renald D. Bartoe
Vesuvius McDanel
510 Ninth Avenue
Box 560
Beaver Falls, PA 15010-0560
116. Donald M. Bartos
Dow Corning Corporation
Advanced Ceramics Program
Midland, MI 48686-0995

117. David L. Baty
Babcock & Wilcox-LRC
P.O. Box 11165
Lynchburg, VA 24506-1165
118. Donald F. Baxter, Jr.
ASM International
Advanced Materials and
Processes
Materials Park, OH 44073-0002
119. M. Brad Beardsley
Caterpillar, Inc.
Advanced Materials Technology
Technical Center Bldg. E
P.O. Box 1875
Peoria, IL 61656-1875
120. Robert Beck
Teledyne CAE
Materials Engineering/Programs
1330 Laskey Road
P.O. Box 6971
Toledo, OH 43612
121. John C. Bell
Shell Research Limited
Thornton Research Centre
P.O. Box 1
Chester, Ch1 3SH
ENGLAND AIR MAIL
122. Albert H. Bell, III
General Motors Technical Center
30200 Mound Road
Engineering Building/W3 Turbine
Warren, MI 48090-9010
123. M. Bentele
Xamag, Inc.
259 Melville Avenue
Fairfield, CT 06430
124. Larry D. Bentsen
BF Goodrich Company
R&D Center
9921 Brecksville Road
Brecksville, OH 44141
125. Joseph C. Bentz
ENCERATEC
2525 Sandcrest Drive
Columbus, IN 47203
126. Louis Beregszazi
Defiance Precision Products
P.O. Drawer 428
Defiance, OH 43512
127. Tom Bernecki
Northwestern University
BIRL
1801 Maple Avenue
Evanston, IL 60201-3135
128. Charles F. Bersch
Institute for Defense Analyses
1801 North Beauregard Street
Alexandria, VA 22311
129. Ram Bhatt
NASA Lewis Research Center
21000 Brookpark Road
Cleveland, OH 44135
130. Deane I. Biehler
Caterpillar, Inc.
Engineering and Research
Materials
Technical Center, Building E
P.O. Box 1875
Peoria, IL 61656-1875
131. John. W. Bjerklie
Consolidated Natural Gas
Service Co., Inc.
Research Department
CNG Tower
Pittsburgh, PA 15222-3199
132. William D. Bjorndahl
TRW, Inc.
One Space Park
Building 01, Room 2040
Redondo Beach, CA 90278
133. Keith A. Blakely
Advanced Refractory
Technologies, Inc.
699 Hertel Avenue
Buffalo, NY 14207
134. Edward G. Blanchard
Netzsch Inc.
119 Pickering Way
Exton, PA 19341

135. Keith Blandford
Boride Products, Inc.
2879 Aero Park Drive
Traverse City, MI 49684
136. Bruce Boardman
Deere and Company Technical
Center
3300 River Drive
Moline, IL 61265
137. Russell Bockstedt
Hoechst Celanese Corporation
150 JFK Parkway
Short Hills, NJ 07078
138. M. Boehmer
DLR German Aerospace Research
Establishment
Postfach 90 60 58
D-5000 Köln 90
GERMANY AIR MAIL
139. Lawrence P. Boesch
EER Systems Corp.
1593 Spring Hill Road
Vienna, VA 22182-2239
140. Donald H. Boone
Boone & Associates
2412 Cascade Drive
Walnut Creek, CA 94598-4313
141. Tom Booth
Allied-Signal Aerospace
Company
AiResearch Los Angeles
Division
2525 West 190th Street
Torrance, CA 90509-2960
142. Tibor Bornemisza
Sundstrand Power Systems
4400 Ruffin Road
San Diego, CA 92186-5757
143. J.A.M. Boulet
University of Tennessee
Department of Engineering
Science and Mechanics
310 Perkins Hall
Knoxville, TN 37996-2030
144. H. Kent Bowen
Massachusetts Institute of
Technology
77 Massachusetts Avenue
Room E40-434
Cambridge, MA 02139
145. Leslie J. Bowen
Materials Systems
53 Hillcrest Road
Concord, MA 01742
146. Steven C. Boyce
Air Force Office of
Scientific Research
AFOSR/NA Bldg. 410
Bolling AFB DC 20332-6448
147. Gary L. Boyd
CEC
400 Howell Avenue, No. 4
Warland, WY 82401
148. Steve Bradley
UOP Research Center
50 East Algonquin Road
Des Plaines, IL 60017-6187
149. Michael C. Brands
Cummins Engine Company, Inc.
P.O. Box 3005
Mail Code 50179
Columbus, IN 47201
150. Raymond J. Bratton
Westinghouse Science and
Technology Center
1310 Beulah Road
Pittsburgh, PA 15235
151. John J. Brennan
United Technologies Corporation
Research Center
Silver Lane, MS:24
East Hartford, CT 06108
152. Jeff D. Bright
Ceramatec, Inc.
2425 South 900 West
Salt Lake City, UT 84108

153. Terrence K. Brog
Coors Ceramics Company
Corporate Development and
Technology
4545 McIntyre Street
Golden, CO 80403
154. Gunnar Broman
317 Fairlane Drive
Spartanburg, SC 29302
155. Al Brown
High-Tech Materials Alert
P.O. Box 882
Dayton, NJ 08810
156. Jesse Brown
Virginia Polytechnic Institute
and State University
Center for Advanced Ceramic
Materials
Blacksburg, VA 24061-0256
157. Sherman D. Brown
University of Illinois
Materials Science and
Engineering Department
105 South Goodwin Avenue
204 Ceramics Building
Urbana, IL 61801
158. S. L. Bruner
Ceramatec, Inc.
2425 South 900 West
Salt Lake City, UT 84119
159. Adolfo Brusaferro
Keramont Corporation
4231 South Fremont Avenue
Tucson, AZ 85714
160. W. Bryzik
U.S. Army Tank Automotive
Command
R&D Center
Propulsion Systems Division
Warren, MI 48397-5000
161. S. T. Buljan
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
162. S. J. Burden
GTE Valenite
1711 Thunderbird
Troy, MI 48084
163. Curt V. Burkland
AMERCOM, Inc.
8928 Fullbright Avenue
Chatsworth, CA 91311
164. Bill Bustamante
AMERCOM, Inc.
8928 Fullbright Street
Chatsworth, CA 91311
165. Oral Buyukozturk
Massachusetts Institute of
Technology
77 Massachusetts Avenue
Room 1-280
Cambridge, MA 02139
166. David A. Caillet
Ethyl Corporation
451 Florida Street
Baton Rouge, LA 70801
167. Frederick J. Calnan
Heany Industries, Inc.
249 Briarwood Lane
P.O. Box 38
Scottsville, NY 14546
168. Roger Cannon
Rutgers University
Ceramics Department
P.O. Box 909
Piscataway, NJ 08855-0909
169. Scott Cannon
P.O. Box 567254
Atlanta, GA 30356
170. Harry W. Carpenter
19945 Acre Street
Northridge, CA 91324
171. David Carruthers
Kyocera Industrial Ceramics
Company
P.O. Box 2279
Vancouver, WA 98668-2279

172. Calvin H. Carter, Jr.
Cree Research, Inc.
2810 Meridian Parkway
Durham, NC 27713
173. J. David Casey
35 Atlantis Street
West Roxbury, MA 02132
174. Jere G. Castor
J. C. Enterprise
5078 North 83rd Street
Scottsdale, AZ 85250
175. James D. Cawley
Case Western Reserve University
Materials Science and
Engineering Department
Cleveland, OH 44106
176. Thomas C. Chadwick
Den-Mat Corporation
P.O. Box 1729
Santa Maria, CA 93456
177. Ronald H. Chand
Chand Kare Technical Ceramics
2 Coppage Drive
Worcester, MA 01603
178. Robert E. Chaney
EG&G Idaho, Inc.
Idaho National Engineering
Laboratory
P.O. Box 1625
Idaho Falls, ID 83415-3525
179. Frank C. Chang
U.S. Army Materials
Technology Laboratory
AMTL-EMM
405 Arsenal Street
Watertown, MA 02172
180. Robert M. Chapman
Allied-Signal Aerospace
Company
1530 Wilson Boulevard,
10th Floor
Arlington, VA 22209
181. William Chapman
Williams International
Corporation
2280 West Maple Road
Walled Lake, MI 48390-0200
182. Charlie Chen
LECO Corporation
P.O. Box 211688
Augusta, GA 30917
183. Albert A. Chesnes
U.S. Department of Energy
Transportation Technologies
CE-30, Forrestal Building,
6B-094
Washington, DC 20585
184. Kaiyin Chia
Carborundum Company
P.O. Box 832
Niagara Falls, NY 14302
185. Frank Childs
EG&G Idaho, Inc.
Idaho National Engineering
Laboratory
P.O. Box 1625
Idaho Falls, ID 83415-3527
186. William J. Chmura
Torrington Company
59 Field Street
Torrington, CT 06790-4942
187. Tsu-Wei Chou
University of Delaware
Center for Composite
Materials
201 Spencer Laboratory
Newark, DE 19716
188. R. J. Christopher
Ricardo Consulting Engineers
Bridge Works
Shoreham-By-Sea West Sussex
BN43 5FG
ENGLAND AIR MAIL
189. Joel P. Clark
Massachusetts Institute of
Technology
Room 8-409
Cambridge, MA 02139

190. Giorgio Clarotti
Commission of the European
Communities
DGXII-C3, M075, 1-53;
200 Rue de la Loi
B-1049 Brussels
BELGIUM AIR MAIL
191. W. J. Clegg
ICI Advanced Materials
P.O. Box 11
The Heath, Runcorn Cheshire
WA7 4QE
ENGLAND AIR MAIL
192. Joseph Cleveland
GTE Products Corporation
Hawes Street
Towanda, PA 18848-0504
193. Gloria M. Collins
ASTM
1916 Race Street
Philadelphia, PA 19103
194. William C. Connors
Sundstrand Aviation Operations
Materials Science and
Engineering Department
4747 Harrison Avenue
P.O. Box 7002
Rockford, IL 61125-7002
195. John A. Coppola
Carborundum Company
P.O. Box 156
Niagara Falls, NY 14302
196. Normand D. Corbin
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
197. Douglas Corey
Allied-Signal Aerospace
Company
2525 West 190th Street
MS:T52
Torrance, CA 90504-6099
198. Keith P. Costello
Chand/Kare Technical Ceramics
2 Coppage Drive
Worcester, MA 01603-1252
199. Ed L. Courtright
Pacific Northwest
Laboratory
MS:K3-59
Richland, WA 99352
200. Anna Cox
Mitchell Market Reports
P.O. Box 23
Monmouth Gwent NP5 4YG
UNITED KINGDOM AIR MAIL
201. Thomas Coyle
Unocal Corporation
Unocal Science & Technology
Division
376 South Valencia Avenue
Brea, CA 92621
202. Art Cozens
Instron Corporation
3414 Snowden Avenue
Long Beach, CA 90808
203. Robert C. Craft
American Ceramic
Society, Inc.
757 Brooksedge Plaza Drive
Westerville, OH 43081
204. Mark Crawford
New Technology Week
4604 Monterey Drive
Annandale, VA 22003
205. Richard A. Cree
Markets & Products, Inc.
P.O. Box 14328
Columbus, OH 43214-0328
206. Les Crittenden
Vesuvius McDanel
Box 560
Beaver Falls, PA 15010

207. William J. Croft
U.S. Army Materials
Technology Laboratory
405 Arsenal Street
Watertown, MA 02172
208. M. J. Cronin
Mechanical Technology, Inc.
968 Albany-Shaker Road
Latham, NY 12110
209. Gary M. Crosbie
Ford Motor Company
1430 Culver Avenue
S-2079, SRL Building
Dearborn, MI 48121-4036
210. Floyd W. Crouse, Jr.
U.S. Department of Energy
Morgantown Energy
Technology Center
Collins Ferry Road
P.O. Box 880
Morgantown, WV 26505
211. John Cuccio
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
P.O. Box 5227, MS:1302-20
Phoenix, AZ 85010
212. Raymond Cutler
Ceramatec, Inc.
2425 South 900 West
Salt Lake City, UT 84119
213. Charles D'Angelo
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02154
214. Stephen C. Danforth
Rutgers University
Ceramic Engineering Department
P.O. Box 909
Piscataway, NJ 08855-0909
215. Sankar Das Gupta
Electrofuel Manufacturing
Co., Ltd.
9 Hanna Avenue
Toronto Ontario MGK-1W8
CANADA AIR MAIL
216. Charles Davis
Sverdrup Technology,
Inc., MSFC
620 Discovery Drive
Huntsville, AL 35806
217. Frank Davis
Allied Signal Aerospace Co.
7550 Lucerne Dr., # 203
Middleburg Heights, OH 44130
218. Robert F. Davis
North Carolina State
University
Materials Engineering
Department
229 Riddick Laboratory
P.O. Box 7907
Raleigh, NC 27695
219. Thomas DeAngelis
Carborundum Company
Niagara Falls R&D Center
P.O. Box 832
Niagara Falls, NY 14302
220. George DeBell
Ford Motor Company
Material Systems Reliability
Department
20000 Rotunda Drive
P.O. Box 2053, Room S-2023
Dearborn, MI 48121-2053
221. Michael DeLuca
AMP-AKZO
West Lane
Aquebogue, NY 11931
222. Gerald L. DePoorter
Colorado School of Mines
Metallurgical and Materials
Engineering Department
Golden, CO 80401

223. J. F. DeRidder
Omni Electro Motive, Inc.,
12 Seely Hill Road
Newfield, NY 14867
224. Nick C. Dellow
Materials Technology
Publications
40 Sotheron Road
Watford Herts WD1 2QA
UNITED KINGDOM AIR MAIL
225. L. R. Dharani
University of Missouri-Rolla
224 M.E.
Rolla, MO 65401
226. Douglas A. Dickerson
Union Carbide Specialty
Powders
1555 Main Street
Indianapolis, IN 46224
227. John Dodsworth
Vesuvius Research &
Development
Technical Ceramics Group
Box 560
Beaver Falls, PA 15010
228. B. Dogan
Institut fur Werkstofforschung
GKSS-Forschungszentrum
Geesthacht GmbH
Max-Planck-Strasse
D-2054 Geesthacht
GERMANY AIR MAIL
229. Jean-Marie Drapier
FN Moteurs S.A.
Material and Processing
B-4041 Milmort (Herstal)
BELGIUM AIR MAIL
230. Kenneth C. Dreitlein
United Technologies
Research Center
Silver Lane
East Hartford, CT 06108
231. Robin A.L. Drew
McGill University
Department of Mining and
Metallurgical Engineering
3450 University Street
Montreal Quebec H3A 2A7
CANADA AIR MAIL
232. Winston H. Duckworth
BCL
Columbus Division
505 King Avenue
Columbus, OH 43201-2693
233. Edmund M. Dunn
Texel Company
6 Third Street
Lexington, MA 02173
234. Bill Durako
Sundstrand Aviation Operations
Department 789-6
4747 Harrison Avenue
P.O. Box 7002
Rockford, IL 61125-7002
235. Ernest J. Duwell
212 Elm Street
Hudson, WI 54016
236. Chuck J. Dziedzic
Coors Ceramics Company
Structural Products Group
17750 West 32nd Avenue
Golden, CO 80401
237. Robert J. Eagan
Sandia National Laboratories
Engineered Materials &
Processes Center
Org 1700
P.O. Box 5800
Albuquerque, NM 87185-5800
238. Jeffrey Eagleson
Lanxide Corporation
1001 Connecticut Avenue, N.W.
Washington, DC 20036

239. Harry E. Eaton
United Technologies Corporation
Research Center
Silver Lane
East Hartford, CT 06108
240. Harvill C. Eaton
Louisiana State
University
Office of Research
and Economic Development
240 Thomas Boyd Hall
Baton Rouge, LA 70803
241. Christopher A. Ebel
Carborundum Company
Technology Division
P.O. Box 337
Niagara Falls, NY 14302
242. J. J. Eberhardt
U.S. Department of Energy
Office of Transportation
Materials
CE-34, Forrestal Building
Washington, DC 20585
243. Jim Edler
Eaton Corporation
26201 Northwestern
Highway
P.O. Box 766
Southfield, MI 48037
244. William A. Ellingson
Argonne National Laboratory
Materials Science & Technology
Division
9700 South Cass Avenue
Argonne, IL 60439
245. William S. Ellis
Machined Ceramics
629 N. Graham St.
N. Industrial Park
Bowling Green, KY 42101
246. Glen B. Engle
Nuclear & Aerospace Materials
Corporation
16716 Martincoit Road
Poway, CA 92064
247. Jeff Epstein
Ceramic Technologies, Inc.
2107 Jamara Lane
Houston, TX 77077
248. Kenneth A. Epstein
Dow Chemical U.S.A.
Ceramics and Advanced
Materials
800 Building
Midland, MI 48667
249. Art Erdemir
Argonne National Laboratory
Materials and Components
Technology Division
9700 South Cass Avenue
Argonne, IL 60439
250. E. M. Erwin
Lubrizol Corporation
1819 East 225th Street
Euclid, OH 44117
251. Kenji Esaki
Toyota Technical Center
U.S.A., Inc.
2000 Town Center, Suite 500
Southfield, MI 48075
252. Jose L. Escalante
Anglo-Mex-Tech. Inc.
3923 N.W. 24th Street
Miami, FL 33142
253. John N. Eustis
U.S. Department of Energy
Industrial Energy Efficiency
Division
CE-221, Forrestal Building
Washington, DC 20585
254. Robert C. Evans
NASA Lewis Research Center
Terrestrial Propulsion Office
21000 Brookpark Road, MS:86-6
Cleveland, OH 44135
255. W. L. Everitt
Kyocera International, Inc.
8611 Balboa Avenue
San Diego, CA 92123

256. Gordon Q. Evison
332 South Michigan Avenue
Suite 1730
Chicago, IL 60604
257. John W. Fairbanks
U.S. Department of Energy
Advanced Propulsion Division
CE-322, Forrestal Building
Washington, DC 20585
258. Tim Fawcett
Dow Chemical Company
Central Research, Advanced
Ceramics Laboratory
1776 Building
Midland, MI 48674
259. Robert W. Fawley
Sundstrand Power Systems
Division of Sundstrand
Corporation
4400 Ruffin Road
P.O. Box 85757
San Diego, CA 92186-5757
260. John J. Fedorchak
GTE Products Corporation
Hawes Street
Towanda, PA 18848-0504
261. Jeff T. Fenton
Vista Chemical Company
900 Threadneedle
Houston, TX 77079
262. Larry Ferrell
Babcock & Wilcox
Old Forest Road
Lynchburg, VA 24505
263. Raymond R. Fessler
BIRL
Industrial Research Lab
1801 Maple Avenue
Evanston, IL 60201
264. Michelle Finch
E. I. DuPont de Nemours &
Company, Inc.
Experimental Station
Information Center E302/301
Wilmington, DE 19898
265. Arthur D. Fine
United Technologies Corporation
Pratt & Whitney Aircraft
400 Main Street
MS:163-10
East Hartford, CT 06108
266. Ross F. Firestone
Ross Firestone Company
188 Mary Street
Winnetka, IL 60093-1520
267. Sharon L. Fletcher
Arthur D. Little, Inc.
15 Acorn Park
Cambridge, MA 02140-2390
268. Thomas F. Foltz
Textron Specialty Materials
2 Industrial Avenue
Lowell, MA 01851
269. Renee G. Ford
Materials and Processing Report
P.O. Box 72
Harrison, NY 10528
270. John Formica
Supermaterials
2020 Lakeside Avenue
Cleveland, OH 44114
271. Jennifer M. Fox
Dyson Refractories Limited
R&D Laboratory
Owler Bar
Sheffield S17 3BJ
UNITED KINGDOM AIR MAIL
272. Edwin Frame
Southwest Research Institute
Division 2
P.O. Drawer 28510
San Antonio, TX 78284
273. Armanet Francois
French Scientific Mission
4101 Reservoir Road, N.W.
Washington DC 20007-2176
274. R. G. Frank
Technology Assessment Group
10793 Bentley Pass Lane
Loveland, OH 45140

275. David J. Franus
Forecast International
22 Commerce Road
Newtown, CT 06470
276. Marc R. Freedman
NASA Lewis Research Center
21000 Brookpark Road
MS:49-3
Cleveland, OH 44135
277. Douglas Freitag
LTV Missiles Division
P.O. Box 650003
MS:WT-21
Dallas, TX 75265
278. Brian R.T. Frost
Argonne National Laboratory
9700 South Cass Avenue
Building 900
Argonne, IL 60439
279. Lawrence R. Frost
Instron Corporation
100 Royall Street
Canton, MA 02021
280. George A. Fryburg
Norton/TRW Ceramics
7A-4 Raymond Avenue
Salem, NH 03079
281. Xiren Fu
Shanghai Institute of Ceramics
Chinese Academy of Sciences
1295 Ding-xi Road
Shanghai 200050
CHINA AIR MAIL
282. John Gahimer
P.O. Box 1302
Dublin, OH 43017
283. J. P. Gallagher
University of Dayton Research
Institute
300 College Park, JPC-250
Dayton, OH 45469-0120
284. Tom Garritano
University of Tennessee
Science Alliance
101 South College
Knoxville, TN 37996-1328
285. Joy A. Garwood
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
286. H. Maury Gatewood
Reynolds Metals Company
Corporate R&D
Fourth and Canal Streets
P.O. Box 27003
Richmond, VA 23261
287. L. J. Gauckler
ETH-Zurich
Sonneggstrasse 5
CH-8092 Zurich 8092
SWITZERLAND AIR MAIL
288. Peter A. Gaydos
Battelle Columbus Laboratories
505 King Avenue
Columbus, OH 43201
289. George E. Gazza
U.S. Army Materials
Technology Laboratory
Ceramics Research Division
405 Arsenal Street
Watertown, MA 02172-0001
290. D. Gerster
CEA-DCOM
33 Rue De La Federation
Paris 75015
FRANCE AIR MAIL
291. John Ghinazzi
Coors Technical Ceramics
Company
1100 Commerce Park Drive
Oak Ridge, TN 37830

292. Robert Giddings
General Electric Company
Research Laboratory
P.O. Box 8
Schenectady, NY 12301
293. A. M. Glaeser
University of California
Materials Science and Mineral
Engineering
Lawrence Berkeley Laboratory
Hearst Mining Building
Berkeley, CA 94720
294. Paul Glance
Concept Analysis
R&D
950 Stephenson Highway
Dupont Automotive Development
Building
Troy, MI 48007-7013
295. Joseph W. Glatz
Naval Air Propulsion Center
Systems Engineering Division
P.O. Box 7176, PE24
Trenton, NJ 08628
296. W. M. Goldberger
Superior Graphite Company
R&D
2175 East Broad Street
Columbus, OH 43209
297. Allan E. Goldman
U.S. Graphite, Inc.
907 West Outer Drive
Oak Ridge, TN 37830
298. Stephen T. Gonczy
Allied Signal Research
P.O. Box 5016
Des Plaines, IL 60017
299. Jeffrey M. Gonzales
GTE Products Corporation
Hawes Street
Towanda, PA 18848-0504
300. Robert J. Gottschall
U.S. Department of Energy
ER-131, MS:G-236
Washington, DC 20545
301. Earl Graham
Cleveland State University
Department of Chemical
Engineering
Euclid Avenue at
East 24th Street
Cleveland, OH 44115
302. William A. Graham
Lanxide Corporation
P.O. Box 6077
Newark, DE 19714-6077
303. Robert E. Green, Jr.
Johns Hopkins University
Materials Science and
Engineering Department
Baltimore, MD 21218
304. Lance Groseclose
General Motors Corporation
Allison Gas Turbine Division
P.O. Box 420, MS:W-5
Indianapolis, IN 46206
305. Mark F. Gruninger
Union Carbide Corporation
Specialty Powder Business
1555 Main Street
Indianapolis, IN 46224
306. Ernst Gugel
Cremer Forschungsinstitut
GmbH&Co.KG
Oeslauer Strasse 35
D-8633 Roedental 8633
GERMANY AIR MAIL
307. Donald L. Guile
Corning Glass Works
SP-DV-1-9
Corning, NY 14831
308. Bimleshwar P. Gupta
Solar Energy Research
Institute
Mechanical and Industrial
Technology Division
1617 Cole Boulevard
Golden, CO 80401

309. John P. Gyekenyesi
NASA Lewis Research Center
21000 Brookpark Road, MS:6-1
Cleveland, OH 44135
310. Nabil S. Hakim
Detroit Diesel Corporation
13400 West Outer Drive
Detroit, MI 48239
311. Philip J. Haley
General Motors Corporation
Vehicular Engineering
P.O. Box 420, MS:T12A
Indianapolis, IN 46236
312. Judith Hall
Fiber Materials, Inc.
Biddeford Industrial Park
5 Morin Street
Biddeford, ME 04005
313. Y. Harada
IIT Research Institute
Nometallic Materials and
Composites
10 West 35th Street
Chicago, IL 60616
314. R. A. Harmon
25 Schalren Drive
Latham, NY 12110
315. Amy Harmon-Barrett
Martin Marietta Laboratories
1450 South Rolling Road
Baltimore, MD 21227
316. Norman H. Harris
Hughes Aircraft Company
P.O. Box 800520
Saugus, CA 91380-0520
317. Alan Hart
Dow Chemical Company
Advanced Ceramics Laboratory
1776 Building
Midland, MI 48674
318. Pat E. Hart
Battelle Pacific Northwest
Laboratories
Ceramics and Polymers
Development Section
P.O. Box 999
Richland, WA 99352
319. Stephen D. Hartline
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
320. Michael H. Haselkorn
Caterpillar, Inc.
Engineering Research Materials
Technical Center, Building E
P.O. Box 1875
Peoria, IL 61656-1875
321. N. B. Havewala
Corning, Inc.
SP-PR-11
Corning, NY 14831
322. John Haygarth
Teledyne WAA Chang Albany
P.O. Box 460
Albany, OR 97321
323. Norman L. Hecht
University of Dayton Research
Institute
300 College Park
Dayton, OH 45469-0172
324. Peter W. Heitman
General Motors Corporation
Allison Gas Turbine Division
P.O. Box 420, MS:W-5
Indianapolis, IN 46206-0420
325. Robert W. Hendricks
Virginia Polytechnic Institute
and State University
Materials Engineering
Department
210 Holden Hall
Blacksburg, VA 24061-0237

326. Wynne Henley
Hertel Cutting Technologies, Inc.
1000 Clearview Court
Oak Ridge, TN 37830
327. Thomas L. Henson
GTE Products Corporation
Chemical & Metallurgical
Division
Hawes Street
Towanda, PA 18848
328. Thomas P. Herbell
NASA Lewis Research Center
21000 Brookpark Road
MS:49-3
Cleveland, OH 44135
329. Marlene Heroux
Rolls-Royce, Inc.
2849 Paces Ferry Road
Suite 450
Atlanta, GA 30339-3769
330. Robert L. Hershey
Science Management Corporation
1255 New Hampshire Ave., N.W.
Suite 1033
Washington, DC 20036
331. Hendrik Heystek
Bureau of Mines
Tuscaloosa Research Center
P.O. Box L
University, AL 35486
332. Wallace C. Higgins
Norwal Unlimited
P.O. Box 1258
Alfred, NY 14802
333. Robert V. Hillery
GE Aircraft Engines
One Neumann Way, M.D. H85
Cincinnati, OH 45215
334. Arthur Hindman
Instron Corporation
100 Royall Street
Canton, MA 02021
335. Jon Hines
American Ceramic Society, Inc.
757 Brooksedge Plaza Drive
Westerville, OH 43081-6136
336. Hans Erich Hintermann
CSEM
Materials and Micromechanics
Division
Rue Breguet-2
Neuchatel 2000
SWITZERLAND AIR MAIL
337. Shinichi Hirano
Mazda R&D of North
America, Inc.
1203 Woodridge Avenue
Ann Arbor, MI 48105
338. Tommy Hiraoka
NGK Locke, Inc.
1000 Town Center
Southfield, MI 48075
339. John M. Hobday
U.S. Department of Energy
Morgantown Energy Technology
Center
Collins Ferry Road
P.O. Box 880
Morgantown, WV 26507
340. Greg Hoenes
Vista Chemical Company
900 Threadneedle
P.O. Box 19029
Houston, TX 77079-2990
341. Clarence Hoenig
Lawrence Livermore National
Laboratory
P.O. Box 808, Mail Code L-369
Livermore, CA 94550
342. Thomas Hollstein
Fraunhofer-Institut fur
Werkstoffmechanik IWM
Wohlerstrabe 11
D-7800 Freiburg
GERMANY AIR MAIL

343. Richard Holt
National Research Council
of Canada
Structures and Materials
Laboratory
Ottawa Ontario K1A 0R6
CANADA AIR MAIL
344. Joseph Homeny
University of Illinois
Department of Materials Science
and Engineering
105 South Goodwin Avenue
Ceramics Building
Urbana, IL 61801
345. A. T. Hopper
Battelle Columbus
Laboratories
Metals and Ceramics Department
505 King Avenue
Columbus, OH 43201-2693
346. Michael Horgan
Materials Engineering Magazine
1100 Superior Avenue
Cleveland, OH 44114
347. Woodie Howe
Coors Technical Ceramics
Company
1100 Commerce Park Drive
Oak Ridge, TN 37830
348. Stephen M. Hsu
National Institute of
Standards and Technology
Gaithersburg, MD 20899
349. Hann S. Huang
Argonne National Laboratory
9700 South Cass Avenue
Argonne, IL 60439-4815
350. Gene Huber
Precision Ferrites & Ceramics
5576 Corporate Drive
Cypress, CA 90630
351. M. L. Huckabee
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
352. Harold A. Huckins
Princeton Advanced
Technology, Inc.
56 Finley Road
Princeton, NJ 08540
353. Fred R. Huettig
Advanced Magnetics, Inc.
45 Corey Lane
Mendham, NJ- 07945
354. Bill Huffman
Zircar
110 North Main Street
Florida, NY 10921
355. Brian K. Humphrey
Lubrizol Petroleum
Chemicals Co.
3000 Town Center, Suite 1340
Southfield, MI 48075-1201
356. Robert M. Humrick
Dylon Ceramic Technologies
3100 Edgehill Road
Cleveland Heights, OH 44118
357. Lorretta Inglehart
National Science Foundation
Division of Materials Research
1800 "G" Street, N.W.,
Room 408
Washington, DC 20550
358. Michael S. Inoue
Kyocera International, Inc.
KII Library
8611 Balboa Avenue
San Diego, CA 92123-1580
359. Osama Jadaan
University of Wisconsin-
Platteville
General Engineering Division
1 University Plaza
Platteville, WI 53818
360. Curtis A. Johnson
General Electric Company
Corporate R&D
Room MB-187
P.O. Box 8
Schenectady, NY 12301

361. Sylvia Johnson
SRI International
333 Ravenswood Avenue
Menlo Park, CA 94025
362. Thomas A. Johnson
Lanxide Corporation
1300 Marrows Road
P.O. Box 6077
Newark, DE 19714-6077
363. W. S. Johnson
Indiana University
One City Centre, Suite 200
Bloomington, IN 47405
364. Jill E. Jonkouski
U.S. Department of Energy
9800 South Cass Avenue
Argonne, IL 60439-4899
365. L. A. Joo
Great Lakes Research
Corporation
P.O. Box 1031
Elizabethton, TN 37643
366. A. D. Joseph
SPX Corporation
700 Terrace Point
Muskegon, MI 49443
367. Adam Jostsons
Australian Nuclear Science &
Technology Organization
Lucas Heights Research
Laboratories
New Illawarra Road
Lucas Heights New South Wales
AUSTRALIA AIR MAIL
368. Matthew K. Juneau
Ethyl Corporation
451 Florida Street
Baton Rouge, LA 70801
369. Hartmut Kainer
Didier-Werke AG
Anlagentechnik Wiesbaden
Abraham-Lincoln-Str. 16
D-62 Wiesbaden
GERMANY AIR MAIL
370. Tom Kalamasz
Norton/TRW Ceramics
7A-4 Raymond Avenue
Salem, NH 03079
371. Lyle R. Kallenbach
Phillips Petroleum Company
R&D
Mail Drop:123AL
Bartlesville, OK 74004
372. Nick Kamiya
Kyocera Industrial Ceramics
Corporation
2700 River Road
Des Plaines, IL 60018
373. Roy Kamo
Adiabatics, Inc.
3385 Commerce Park Drive
Columbus, IN 47201
374. S. Kang
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
375. Chih-Chun Kao
Industrial Technology Research
Institute
Materials Research
Laboratories
195 Chung-Hsing Road, Sec. 4
Chutung Hsinchu 31015 R.O.C.
TAIWAN AIR MAIL
376. Keith R. Karasek
Allied-Signal, Inc.
Engineered Materials Research
Center
50 East Algonquin Road
P.O. Box 5016
Des Plaines, IL 60017-5016
377. Robert E. Kassel
Ceradyne, Inc.
3169 Redhill Avenue
Costa Mesa, CA 92626
378. Allan Katz
Wright Laboratory
Metals and Ceramics Division
WL/MLLM
Wright-Patterson AFB, OH 45433

379. R. Nathan Katz
Worcester Polytechnic
Institute
Dept. of Mechanical
Engineering
100 Institute Road
Worcester, MA 01609
380. Ted Kawaguchi
Tokai Carbon America, Inc.
375 Park Avenue, Suite 3802
New York, NY 10152
381. Noritsugu Kawashima
TOSHIBA Corporation
Mechanical Engineering
Laboratory
4-1 Ukishima-Cho
Kawasaki-Ku Kawasaki 210
JAPAN AIR MAIL
382. Lisa Kempfer
Penton Publishing
Materials Engineering
1100 Superior Avenue
Cleveland, OH 44114-2543
383. Frederick L. Kennard, III
General Motors Corporation
AC Rochester
Department 32-24, EB
1300 North Dort Highway
Flint, MI 48556
384. David O. Kennedy
Lester B. Knight Cast
Metals Inc.
549 West Randolph Street
Chicago, IL 60661
385. George Keros
Photon Physics
3175 Penobscot Building
Detroit, MI 48226
386. Pramod K. Khandelwal
General Motors Corporation
Allison Gas Turbine
Division
P.O. Box 420, MS:W05
Indianapolis, IN 46206
387. Jim R. Kidwell
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
P.O. Box 5227
Phoenix, AZ 85010
388. Han J. Kim
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
389. Shin Kim
Korea Institute of Machinery
& Metals
66 Sangnam-dong, Changwon
Kyungnam 641-010
KOREA AIR MAIL
390. W. C. King
Mack Truck, Z-41
1999 Pennsylvania Avenue
Hagerstown, MD 21740
391. Carol Kirkpatrick
MSE, Inc.
CDIF Technical Library
P.O. Box 3767
Butte, MT 59702
392. Tony Kirn
Caterpillar, Inc.
Defense Products Department, JB7
Peoria, IL 61629
393. James D. Kiser
NASA Lewis Research Center
21000 Brookpark Road, MS:49-3
Cleveland, OH 44135
394. Max Klein
Gas Research Institute
Thermodynamics
8600 West Bryn Mawr Avenue
Chicago, IL 60631
395. Richard N. Kleiner
Coors Ceramics Company
4545 McIntyre Street
Golden, CO 80403

396. Stanley J. Klima
NASA Lewis Research Center
21000 Brookpark Road
MS:6-1
Cleveland, OH 44135
397. Chris E. Knapp
Norton Advanced Ceramics
of Canada Ltd.
8001 Daly Street
Niagara Falls, Ontario L2G 6S2
CANADA AIR MAIL
398. Albert S. Kobayashi
University of Washington
Mechanical Engineering
Department
MS:FU10
Seattle, WA 98195
399. Shigeki Kobayashi
Toyota Central Research
Labs, Inc.
Nagakute Aichi 480-11
JAPAN AIR MAIL
400. Richard A. Kole
Z-Tech Corporation
8 Dow Road
Bow, NH 03304
401. E. Kostiner
University of Connecticut
Chemistry Department, U-60
Storrs, CT 06269-3060
402. Kenneth A. Kovaly
Technical Insights, Inc.
P.O. Box 1304
Fort Lee, NJ 07024-9967
403. Ralph G. Kraft
Spraying Systems Company
North Avenue at Schmale Road
Wheaton, IL 60189-7900
404. Saunders B. Kramer
U.S. Department of Energy
Advanced Propulsion Division
CE-322, Forrestal Building
Washington, DC 20585
405. Arthur Kranish
Trends Publishing, Inc.
1079 National Press Building
Washington, DC 20045
406. A. S. Krieger
Radiation Science, Inc.
P.O. Box 293
Belmont, MA 02178
407. Pieter Krijgsman
Ceramic Design International
Holding B.V.
P.O. Box 68
Hatten 8050-AB
THE NETHERLANDS AIR MAIL
408. Waltraud M. Kriven
University of Illinois
Materials Science and
Engineering Department
105 South Goodwin Avenue
Urbana, IL 61801
409. Edward J. Kubel, Jr.
ASM International Advanced
Materials & Processes
Materials Park, OH 44073
410. Dave Kupperman
Argonne National Laboratory
9700 South Cass Avenue
Argonne, IL 60439
411. Oh-Hun Kwon
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
412. W. J. Lackey
Georgia Institute of Technology
Materials Science and
Technology
Atlanta, GA 30332
413. Jai Lala
Tenmat Ltd.
40 Somers Road
Rugby Warwickshire CV22 7DH
ENGLAND AIR MAIL

414. Hari S. Lamba
General Motors Corporation
Electro-Motive Division
9301 West 55th Street
LaGrange, IL 60525
415. Richard L. Landingham
Lawrence Livermore National
Laboratory
Ceramics, Corrosion, and
Thermochemistry
P.O. Box 808, L-369
Livermore, CA 94550
416. Charles J. Landry
Chand Kare Technical Ceramics
712 Flat Hill Road
Lumburg, MA 01462
417. Manfred W. Langer
Volkswagen AG
Material Technology
3180 Wolfsburg 1
GERMANY AIR MAIL
418. James Lankford
Southwest Research Institute
Department of Materials
Sciences
6220 Culebra Road
San Antonio, TX 78228-0510
419. Stanley B. Lasday
Business News Publishing Co.
Manor Oak One
1910 Cochran Road, Suite 630
Pittsburgh, PA 15220
420. Mark S. Laser
Solar Turbines, Inc.
2211 Erie Street
San Diego, CA 92110
421. S. K. Lau
Carborundum Company
Technology Division
P.O. Box 832, B-100
Niagara Falls, NY 14302
422. Edward A. Lauder
Advanced Composite Materials
Corporation
1525 South Buncombe Road
Greer, SC 29651-9208
423. J. Lawrence Lauderdale
Babcock & Wilcox
Contract Research Division
1850 "K" Street, Suite 950
Washington, DC 20006
424. Harry A. Lawler
Carborundum Company
Technology Division
P.O. Box 832
Niagara Falls, NY 14302
425. Jean F. LeCostaouec
Textron Speciality Materials
2 Industrial Avenue
Lowell, MA 01851
426. Benson P. Lee
Interscience, Inc.
9718 Lake Shore Boulevard
Cleveland, OH 44108
427. Burtrand I. Lee
Clemson University
Department of Ceramic
Engineering
Olin Hall
Clemson, SC 29634-0907
428. June-Gunn Lee
KIST
Structural Ceramic Lab
P.O. Box 131, Cheong-Ryang
Seoul 130-650
KOREA AIR MAIL
429. Ran-Rong Lee
Ceramics Process Systems
Corporation
155 Fortune Boulevard
Milford, MA 01757
430. Stan Levine
NASA Lewis Research Center
21000 Brookpark Road
MS:49-3
Cleveland, OH 44135
431. Alan V. Levy
Lawrence Berkeley Laboratory
One Cyclotron Road, MS:62-203
Berkeley, CA 94720

432. Ai-Kang Li
Materials Research
Laboratories, ITRI
195-5 Chung-Hsing Road, Sec. 4
Chutung Hsinchu 31015 R.O.C.
TAIWAN AIR MAIL
433. Winston W. Liang
Hong Kong Industrial
Technology Centre Co. Ltd.
78 Tat Chee Avenue
4/F, HKPC Building
Howloon
HONG KONG AIR MAIL
434. Robert Licht
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
435. E. Lilley
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
436. Laura J. Lindberg
Allied-Signal Aerospace
Company
Garrett Fluid Systems Division
1300 West Warner
MS: 93-901-1207-4TT
P.O. Box 22200
Tempe, AZ 85284-2200
437. Leonard C. Lindgren
General Motors Corporation
Allison Gas Turbine Division
P.O. Box 420, Speed Code:T-20A
Indianapolis, IN 46206-0420
438. Hans A. Lindner
Cremer Forschungsinstitut
GmbH&Co.KG
Oeslauer Strasse 35
D-8633 Rodental 8866
GERMANY AIR MAIL
439. Ronald E. Lochman
Sandia National Laboratories
Chemistry & Ceramics
Department 1840
P.O. Box 5800
Albuquerque, NM 87185
440. Jeffrey C. Logas
Winona State University
Composite Materials
Engineering
115 Pasteur Hall
Winona, MN 55987
441. Bill Long
Babcock & Wilcox
P.O. Box 11165
Lynchburg, VA 24506
442. William D. Long
Wacker Chemicals (USA), Inc.
ESK Engineered Ceramics
50 Locust Avenue
New Canaan, CT 06840
443. L. A. Lott
EG&G Idaho, Inc.
Idaho National Engineering
Laboratory
P.O. Box 1625
Idaho Falls, ID 83415-2209
444. Raouf O. Loutfy
MER Corporation
7960 South Kolb Road
Tucson, AZ 85706
445. Gordon R. Love
Aluminum Company of America
Alcoa Technical Center
Alcoa Center, PA 15069
446. Lydia Luckevich
Ortech International
2395 Speakman Drive
Mississauga Ontario L5K 1B3
CANADA AIR MAIL

447. James W. MacBeth
Carborundum Company
Structural Ceramics Division
P.O. Box 1054
Niagara Falls, NY 14302
448. H. MacLaren
General Electric Company
Thomson Laboratory, Materials
Engineering 36807
1000 Western Avenue
Lynn, MA 01910
449. George Maczura
Aluminum Company of America
Industrial Chemicals Division
670 One Allegheny Square
Pittsburgh, PA 15212
450. David Maginnis
Tinker AFB
OC-ALC/LIIRE
Tinker AFB OK 73145-5989
451. Frank Maginnis
Aspen Research, Inc.
220 Industrial Boulevard
Moore, OK 73160
452. Tai-il Mah
Universal Energy Systems, Inc.
Ceramics and Composites
Research
4401 Dayton-Xenia Road
Dayton, OH 45432
453. Kenneth M. Maillar
Barbour Stockwell Company
83 Linskey Way
Cambridge, MA 02142
454. Lorenzo Majno
Instron Corporation
100 Royall Street
Canton, MA 02021
455. S. G. Malghan
National Institute of Standards
and Technology
I-270 & Clopper Road
Gaithersburg, MD 20899
456. Lars Malmrup
United Turbine AB
Box 13027
Malmo S-200 44
SWEDEN AIR MAIL
457. John Mangels
Ceradyne, Inc.
3169 Redhill Avenue
Costa Mesa, CA 92626
458. Russell V. Mann
Matec Applied Sciences, Inc.
75 South Street
Hopkinton, MA 01748
459. William R. Manning
Champion Aviation Products
Division
Old Norris Road
P.O. Box 686
Liberty, SC 29657
460. Ken Marnoch
Amercom, Inc.
8928 Fullbright Avenue
Chatsworth, CA 91311
461. Robert A. Marra
Aluminum Company of America
Alcoa Technical Center
Advanced Ceramics Center - E
Alcoa Center, PA 15069
462. Chauncey L. Martin
3M Company
3M Center, Building 60-1N-01
St. Paul, MN 55144
463. Steven C. Martin
Advanced Refractory
Technologies, Inc.
699 Hertel Avenue
Buffalo, NY 14207
464. Kelly J. Mather
Williams International
Corporation
2280 West Maple Road
P.O. Box 200
Walled Lake, MI 48088

465. James P. Mathers
3M Company
3M Center
Building 201-3N-06
St. Paul, MN 55144
466. Marshall Mayer
Instron Corporation
3815 Presidential Parkway,
Suite 100
Atlanta, GA 30340
467. Ron Mayville
Arthur D. Little, Inc.
15-163 Acorn Park
Cambridge, MA 02140
468. F. N. Mazadarany
General Electric Company
Research Laboratory
Building K-1, Room MB-159
P.O. Box 8
Schenectady, NY 12301
469. James W. McCauley
Alfred University
NYS College of Ceramics
Binns-Merrill Hall
Alfred, NY 14802
470. Carolyn McCormick
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
Bldg. 1303-206
P.O. Box 5227, MS:9317-2
Phoenix, AZ 85010
471. Louis R. McCreight
2763 San Ramon Drive
Rancho Palos Verdes, CA 90274
472. Colin F. McDonald
McDonald Thermal Engineering
1730 Castellana Road
La Jolla, CA 92037
473. B. J. McEntire
Norton Company, TRW Ceramics
Goddard Road
Northboro, MA 01532-1545
474. Chuck McFadden
Coors Ceramics Company
600 9th Street
Golden, CO 80401
475. Henry McFadden
Magnetic Bearings, Inc.
Engineering Library
609 Rock Road
Radford, VA 24141
476. Thomas D. McGee
Iowa State University
Materials Science and
Engineering Department
110 Engineering Annex
Ames, IA 50011
477. Carol McGill
Corning Inc.
Sullivan Park, FR-02-08
Corning, NY 14831
478. T. C. McLaren
Cameron Forged Products
Company
P.O. Box 1212
Houston, TX 77251-1212
479. James McLaughlin
Sundstrand Power Systems
4400 Ruffin Road
P.O. Box 85757
San Diego, CA 92186-5757
480. Arthur F. McLean
6225 North Camino Almonte
Tucson, AZ 85718
481. Matt McMonigle
U.S. Department of Energy
Improved Energy Productivity
Division
Forrestal Building,
CE-231
Washington, DC 20585
482. Dennis McMurtry
EG&G Idaho, Inc.
Idaho National Engineering
Laboratory
P.O. Box 1625
Idaho Falls, ID 83415

483. D. B. Meadowcroft
National Power Technology
and Environmental Centre
Kelvin Avenue
Leatherhead Surrey
KT22 7SE
ENGLAND AIR MAIL
484. Jo Meglen
11004 Birdfoot Court
Reston, VA 22091
485. Pankaj K. Mehrotra
Kennametal, Inc.
P.O. Box 639
Greensburg, PA 15601
486. Joseph J. Meindl
Reynolds International, Inc.
6603 West Broad Street
P.O. Box 27002
Richmond, VA 23261-7003
487. Michael D. Meiser
Allied-Signal Aerospace Company
Garrett Ceramic Components
Division
19800 South Van Ness Avenue
Torrance, CA 90509
488. George Messenger
National Research Council of
Canada
Engine Laboratory
Building M-7
Ottawa Ontario K1A 0R6
CANADA AIR MAIL
489. D. Messier
U.S. Army Materials Technology
Laboratory
SLCMT-EMC
405 Arsenal Street
Watertown, MA 02172-0001
490. Gary L. Messing
Pennsylvania State University
Ceramic Science and Engineering
Department
119 Steidle Building
University Park, PA 16802
491. Arthur G. Metcalfe
Arthur G. Metcalfe and
Associates, Inc.
2108 East 24th Street
National City, CA 91950
492. R. Metselaar
Eindhoven University
Centre for Technical Ceramics
P.O. Box 513
Eindhoven 5600 MB
THE NETHERLANDS AIR MAIL
493. Nancy S. Meyers
U.S. Department of Energy
Transportation Technologies
CE-30, Forrestal Building
6B-094
Washington, DC 20585
494. David J. Michael
Harbison-Walker Refractories
Company
P.O. Box 98037
Pittsburgh, PA 15227
495. Ken Michaels
Chrysler Motors Corporation
Ceramics Development
Metallurgical Processes
P.O. Box 1118, CIMS:418-17-09
Detroit, MI 48288
496. Bernd Michel
Institute of Mechanics
Fracture and Micromechanics
Department
P.O. Box 408
D-9010 Chemnitz
GERMANY AIR MAIL
497. David E. Miles
Commission of the European
Communities
rue de la Loi, 200
B-1049 Brussels
BELGIUM AIR MAIL
498. John V. Milewski
Superkinetics, Inc.
P.O. Box 8029
Santa Fe, NM 87504

499. Carl E. Miller
AC Rochester
1300 North Dort Highway,
MS:32-31
Engineering Building B
Flint, MI 48556
500. Mike Miller
McGraw-Hill Aviation Week
Performance Materials
1156 15th Street, N.W.
Washington, DC 20005
501. Charles W. Miller, Jr.
Centorr Furnaces/Vacuum
Industries
542 Amherst Street
Nashua, NH 03063
502. R. Mininni
Enichem America
2000 Cornwall Road
Monmouth Junction, NJ 08852
503. Michele V. Mitchell
Allied-Signal Aerospace
Company
Garrett Ceramic Components
Division
19800 South Van Ness Avenue
Torrance, CA 90501-1149
504. Howard Mizuhara
GTE - WESGO
477 Harbor Boulevard
Belmont, CA 94002
505. Helen Moeller
Babcock & Wilcox
P.O. Box 11165
Lynchburg, VA 24506-1165
506. Francois R. Mollard
Metalworking Technology, Inc.
1450 Scalp Avenue
Johnstown, PA 15904
507. Phil Mooney
Panametrics
NDE Division
221 Crescent Street
Waltham, MA 02254
508. Thomas Morel
Ricardo North America
645 Blackhawk Drive
Westmont, IL 60559
509. Geoffrey P. Morris
3M Company
3M Traffic Control Materials
Division
Bldg. 209-BW-10, 3M Center
St. Paul, MN 55144-1000
510. Jay A. Morrison
Rolls-Royce, Inc.
Engineering and Information
Center, Overlook 1
2849 Paces Ferry Road,
Suite 450
Atlanta, GA 30339-3769
511. Joel P. Moskowitz
Ceradyne, Inc.
3169 Redhill Avenue
Costa Mesa, CA 92626
512. Brij Moudgil
University of Florida
Material Science and
Engineering
Gainesville, FL 32611
513. Christoph J. Mueller
Sprechsaa Publishing
Group
P.O. Box 2962, Mauer 2
D-8630 Coburg
GERMANY AIR MAIL
514. Thomas W. Mullan
Vapor Technologies Inc.
345 Route 17 South
Upper Saddle River, NJ 07458
515. M. K. Murthy
MKM Consultants International
10 Avoca Avenue, Unit 1906
Toronto Ontario M4T 2B7
CANADA AIR MAIL
516. Solomon Musikant
TransCon Technologies, Inc.
Materials Science & Engineering
1508 Waynesboro Road
Paoli, PA 19301

517. David L. Mustoe
Custom Technical Ceramics
8041 West I-70 Service Road,
Unit 6
Arvada, CO 80002
518. Curtis V. Nakaishi
U.S. Department of Energy
Morgantown Energy Technology
Center
Collins Ferry Road
P.O. Box 880
Morgantown, WV 26507-0880
519. Yoshio Nakamura
Faicera Research Institute
2-5-8 Hiyakunin-cho Shinjuku-Ko
Tokyo
JAPAN AIR MAIL
520. K. S. Narasimhan
Hoeganaes Corporation
River Road
Riverton, NJ 08077
521. Samuel Natansohn
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
522. Robert Naum
Applied Resources, Inc.
P.O. Box 241
Pittsford, NY 14534
523. Malcolm Naylor
Cummins Engine Company, Inc.
P.O. Box 3005, Mail Code 50183
Columbus, IN 47202-3005
524. Jeffrey Neil
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
525. Fred A. Nichols
Argonne National Laboratory
9700 South Cass Avenue
MCT - Building 212
Argonne, IL 60439
526. H. Nickel
Forschungszentrum Jülich (KFA)
P.O. Box 1913
Jülich 1-5170 BRD NRW
GERMANY AIR MAIL
527. Dale E. Niesz
Rutgers University
Center for Ceramic Research
P.O. Box 909
Piscataway, NJ 08855-0909
528. David M. Nissley
United Technologies Corporation
Pratt & Whitney Aircraft
400 Main Street, MS:163-10
East Hartford, CT 06108
529. Richard D. Nixdorf
ReMaxCo Technologies, Inc.
11317 Snyder Road
Knoxville, TN 37932
530. Bernard North
Kennametal, Inc.
P.O. Box 639
Greensburg, PA 15601
531. Bruce E. Novich
Ceramics Process Systems
Corporation
155 Fortune Boulevard
Milford, MA 01757
532. Daniel Oblas
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
533. Don Ohanehi
Magnetic Bearings, Inc.
1908 Sussex Road
Blacksburg, VA 24060
534. Robert Orenstein
General Electric Company
55-112, River Road
Schenectady, NY 12345

535. Norb Osborn
Aerodyne Dallas
151 Regal Row,
Suite 120
Dallas, TX 75247
536. A. M. Paddick
BP International Limited
BP Research Centre, Main
Library
Chertsey Road
Sunbury-on-Thames
Middlesex TW16 7LN
UNITED KINGDOM AIR MAIL
537. Russell J. Page
Kanthal-Artcor
3001 Redhill Avenue, II-109
Costa Mesa, CA 92705
538. Richard Palicka
Cercom, Inc.
1960 Watson Way
Vista, CA 92083
539. Muktesh Paliwal
GTE Products Corporation
Hawes Street
Towanda, PA 18848
540. Joseph E. Palko
General Electric Company
55-113, River Road
Schenectady, NY 12345
541. Hayne Palmour, III
North Carolina State
University
Materials Science and
Engineering Dept.
Raleigh, NC 27605-7905
542. Joseph N. Panzarino
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
543. Pellegrino Papa
Corning Inc.
MP-WX-02-1
Corning, NY 14831
544. E. Beth Pardue
Technology for Energy
Corporation
One Energy Center
P.O. Box 22996
Knoxville, TN 37933-0996
545. Soon C. Park
3M Company
3M Center - -
Building 142-4N-02
P.O. Box 2963
St. Paul, MN 55144
546. Hartmut Paschke
Schott Glaswerke
Christoph-Dorner-Strasse 29
D-8300 Landshut
GERMANY AIR MAIL
547. Marina R. Pascucci
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
548. James W. Patten
Cummins Engine
Company, Inc.
Materials Engineering
P.O. Box 3005, Mail
Code 50183
Columbus, IN 47202-3005
549. Robert A. Penty
Eastman Kodak Company
KAD/D73 - 35612
901 Elmgrove Road
Rochester, NY 14653
550. Robert W. Pepper
Textron Specialty Materials
2 Industrial Avenue
Lowell, MA 01851
551. Peter Perdue
Detroit Diesel Corporation
Research Advanced Development
Group
13400 West Outer Drive,
Speed Code A-07
Detroit, MI 48239-4001

552. Bruce Peters
Dow Chemical Company
Building 52
Midland, MI 48667
553. John J. Petrovic
Los Alamos National Laboratory
Group MST-4, MS:6771
Los Alamos, NM 87545
554. Frederick S. Pettit
University of Pittsburgh
Pittsburgh, PA 15261
555. Ben A. Phillips
Phillips Engineering Company
721 Pleasant Street
St. Joseph, MI 49085
556. Richard C. Phoenix
Ohmtek, Inc.
2160 Liberty Drive
Niagara Falls, NY 14302
557. Bruce J. Pletka
Michigan Technological
University
Metallurgical and Materials
Engineering Department
Houghton, MI 49931
558. John P. Pollinger
Garrett Ceramic Components
19800 Van Ness Avenue
Torrance, CA 90501
559. P. Popper
High Technology Ceramics
International Journal
22 Pembroke Drive
Westlands Newcastle-under-Lyme
Staffs ST5 2JN
ENGLAND AIR MAIL
560. F. Porz
Universitat Karlsruhe
Institut fur Keramik Im
Maschinendau
Postfach 6980
D-7500 Karlsruhe
GERMANY AIR MAIL
561. Harry L. Potma
Royal Netherlands Embassy
Science and Technology
4200 Linnean Avenue, N.W.
Washington, DC 20008
562. Bob R. Powell
General Motors Research
Laboratories
Metallurgy-Department
30500 Mound Road
Box 9055
Warren, MI 48090-9055
563. Stephen C. Pred
ICD Group, Inc.
1100 Valley Brook Avenue
Lyndhurst, NJ 07071
564. Karl M. Prewé
United Technologies Research
Center
411 Silver Lane
MS:24
East Hartford, CT 06108
565. Peter E. Price
Industrial Materials
Technology, Inc.
P.O. Box 9565
Andover, MA 01810
566. Joseph M. Proud
GTE Laboratories, Inc.
Materials Science Laboratory
40 Sylvan Road
Waltham, MA 02254
567. Vimal K. Pujari
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
568. George Quinn
National Institute of
Standards and Technology
Ceramics Division, Bldg. 223
Gaithersburg, MD 20899

569. Ramas V. Raman
Ceracon, Inc.
1101 North Market Boulevard,
Suite 9
Sacramento, CA 95834
570. Charles F. Rapp
Owens Corning Fiberglass
2790 Columbus Road
Granville, OH 43023-1200
571. Dennis W. Readey
Colorado School of Mines
Department of Metallurgy
and Materials Engineering
Golden, CO 80401
572. Wilfred J. Rebello
PAR Enterprises, Inc.
12601 Clifton Hunt Lane
Clifton, VA 22024
573. Harold Rechter
Chicago Fire Brick Company
R&D
7531 South Ashland Avenue
Chicago, IL 60620
574. Robert R. Reeber
U.S. Army Research Office
P.O. Box 12211
Research Triangle Park, NC 27709
575. K. L. Reifsnider
Virginia Polytechnic Institute
and State University
Department of Engineering
Science and Mechanics
Blacksburg, VA 24061
576. Paul E. Rempes
McDonnell Douglass Missile
Systems Company
P.O. Box 516,
Mail Code: 1066086
St. Louis, MO 63166-0516
577. Gopal S. Revankar
John Deere Company
Metals Research
3300 River Drive
Moline, IL 61265
578. K. T. Rhee
Rutgers University
Mechanical Engineering
P.O. Box 909
Piscataway, NJ 08854
579. James Rhodes
Advanced Composite Materials
Corporation
1525 South Buncombe Road
Greer, SC 29651
580. Roy W. Rice
W. R. Grace and Company
7379 Route 32
Columbia, MD 21044
581. David W. Richerson
2093 East Delmont Drive
Salt Lake City, UT 84117
582. Tomas Richter
J. H. France Refractories
1944 Clarence Road
Snow Shoe, PA 16874
583. Michel Rigaud
Ecole Polytechnique
Campus Universite De Montreal
P.O. Box 6079, Station A
Montreal, P.Q. Quebec H3C 3A7
CANADA AIR MAIL
584. R. E. Riman
Rutgers University
Ceramics Engineering
Department
P.O. Box 909
Piscataway, NJ 08855-0909
585. Barry Ringstrom
Superior Graphite Company
P.O. Box 2373
Smyrna, GA 30081
586. John E. Ritter
University of Massachusetts
Mechanical Engineering
Department
Amherst, MA 01003

587. Frank L. Roberge
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
P.O. Box 5227
Phoenix, AZ 85010
588. W. Eric Roberts
Advanced Ceramic
Technology, Inc.
990 "F" Enterprise Street
Orange, CA 92667
589. Martha Rohr
U.S. Department of Energy
DOE Oak Ridge Field Office
Building 4500N
P.O. Box 2008, MS:6269
Oak Ridge, TN 37831-6269
590. Y. G. Roman
TNO TPD Keramick
P.O. Box 595
Eindhoven 5600 AN
HOLLAND AIR MAIL
591. Mark D. Roos
Carborundum Company
P.O. Box 156
Niagara Falls, NY 14302
592. Michael Rossetti
Arthur D. Little, Inc.
15 Acorn Park
Cambridge, MA 01240
593. Barry R. Rossing
Lanxide Corporation
1300 Marrows Road
Newark, DE 19714-6077
594. Steven L. Rotz
Lubrizol Corporation
29400 Lakeland Boulevard
Wickliffe, OH 44092
595. Bruce Rubinger
Global Competitiveness, Inc.
One Devonshire Place,
Suite 1011
Boston, MA 02109
596. Robert Ruh
Wright Laboratory
WL/MLLM
Wright-Patterson AFB, OH 45433
597. Robert J. Russell
17 Highgate Road
Framingham, MA 01701
598. L. William Sahley
Supermaterials Company
24400 Highland Road
Richmond Heights, OH 44143
599. Jon Salem
NASA Lewis Research Center
21000 Brookpark Center
Cleveland, OH 44135
600. W. A. Sanders
NASA Lewis Research Center
21000 Brookpark Road,
MS:49-3
Cleveland, OH 44135
601. J. Sankar
North Carolina A&T State
University
Department of Mechanical
Engineering
Greensboro, NC 27411
602. Yasushi Sato
NGK Spark Plugs (U.S.A.), Inc.
1200 Business Center Drive,
Suite 300
Mt. Prospect, IL 60056
603. Maxine L. Savitz
Allied-Signal Aerospace
Company
Garrett Ceramic Components
Division
19800 South Van Ness Avenue
Torrance, CA 90501
604. Ashok Saxena
Georgia Institute of
Technology
Materials Engineering
Atlanta, GA 30332-0245

605. David W. Scanlon
Instron Corporation
100 Royall Street
Canton, MA 02021
606. Charles A. Schacht
Schacht Consulting Services
12 Holland Road
Pittsburgh, PA 15235
607. James Schienle
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
2739 East Washington Street
P.O. Box 5227, MS:1302-2P
Phoenix, AZ 85010
608. John C. Schneider
San Juan Technologies
P.O. Box 49326
Colorado Springs, CO 80949-9326
609. Gary Schnittgrund
Rocketdyne, BA05
6633 Canoga Avenue
Canoga Park, CA 91303
610. Mark Schomp
Lonza, Inc.
Corporate Headquarters
17-17 Route 208
Fair Lann, NJ 07410
611. Joop Schoonman
Delft University of Technology
Laboratory for Inorganic
Chemistry
P.O. Box 5045
2600 GA Delft
THE NETHERLANDS AIR MAIL
612. John Schuldies
Industrial Ceramic
Technology, Inc.
37 Enterprise Drive
Ann Arbor, MI 48103
613. Robert B. Schulz
U.S. Department of Energy
Office of Transportation
Materials
CE-34, Forrestal Building
Washington, DC 20585
614. Murray A. Schwartz
Materials Technology
Consulting, Inc.
30 Orchard Way, North
Potomac, MD 20854
615. Peter Schwarzkopf
SRI International
333 Ravenswood Avenue
Menlo Park, CA 94025
616. Thomas C. Schweizer
Princeton Economic
Research, Inc.
12300 Twinbrook Pkwy.,
Suite 650
Rockville, MD 20852
617. William T. Schwessinger
Multi-Arc Scientific
Coatings
1064 Chicago Road
Troy, MI 48063-4297
618. W. D. Scott
University of Washington
Materials Science Department
Mail Stop:FB10
Seattle, WA 98195
619. Nancy Scoville
Thermo Electron Technologies
74 West Street
P.O. Box 9046
Waltham, MA 02254-9046
620. Brian Seegmiller
Coors Ceramics Company
600 9th Street
Golden, CO 80401

621. T. B. Salover
AICRE/DIPPR
3575 Traver Road
Shaker Heights, OH 44122
622. J. H. Selverian
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
623. Charles E. Semler
Semler Materials Services
4160 Mumford Court
Columbus, OH 43220
624. Thomas Service
Service Engineering Laboratory
324 Wells Street
Greenfield, MA 01301
625. Kish Seth
Ethyl Corporation
R&D Laboratories
P.O. Box 341
Baton Rouge, LA 70821
626. Karleen Seybold
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
P.O. Box 5227
Phoenix, AZ 85010
627. William J. Shack
Argonne National Laboratory
9700 South Cass Avenue
Building 212
Argonne, IL 60439
628. Peter T. B. Shaffer
Technical Ceramics
Laboratories, Inc.
4045 Nine/McFarland Drive
Alpharetta, GA 30201
629. Richard K. Shaltens
NASA Lewis Research Center
21000 Brookpark Road,
MS:301-2
Cleveland, OH 44135
630. Robert S. Shane
238 Hemlock Road
Wynnewood, PA 19096
631. Daniel Shanefield
Rutgers University
Ceramics Engineering
Department
P.O. Box 909
Piscataway, NJ 08855-0909
632. Ravi Shankar
Chromalloy
Research and Technology
Division
Blaisdell Road
Orangeburg, NY 10962
633. Terence Sheehan
Alpex Wheel Company
727 Berkley Street
New Milford, NJ 07646
634. Dinesh K. Shetty
University of Utah
304 EMRO, Dept. of Materials
Science and Engineering
Salt Lake City, UT 84112
635. Masahide Shimizu
Ceramic Society of Japan
2-2-503 Takiyama 6-chome
Higashikurume-Shi Tokyo 203
JAPAN AIR MAIL
636. John Shipinski
Toyota Technical Center
U.S.A., Inc.
Technical Research Department
2000 Town Center, Suite 500
Southfield, MI 48075
637. Thomas Shreves
American Ceramic Society, Inc.
Library
757 Brooksedge Plaza Drive
Westerville, OH 43081-2821
638. Jack D. Sibold
Coors Ceramics Company
Contracts for Corporate
Technology
4545 McIntyre Street
Golden, CO 80403

705. Janet Wade
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division, Department 93-772
P.O. Box 5227, MS:1303-2
Phoenix, AZ 85010
706. Richard L. Wagner
Ceramic Technologies, Inc.
537 Turtle Creek South Drive,
Suite 24D
Indianapolis, IN 46227
707. J. Bruce Wagner, Jr.
Arizona State University
Center for Solid State
Science
Tempe, AZ 85287-1704
708. Daniel J. Wahlen
Kohler, Co.
444 Highland Drive
Kohler, WI 53044
709. Ingrid Wahlgren
Royal Institute of Technology
Studsvik Library
S-611 82 Nykoping
SWEDEN AIR MAIL
710. Ron H. Walecki
Allied-Signal Aerospace
Company
Garrett Ceramic Components
Division
19800 South Van Ness Avenue
Torrance, CA 90501
711. Michael S. Walsh
Vapor Technologies Inc.
2100 Central Avenue
Boulder, CO 80301
712. Chien-Min Wang
Industrial Technology Research
Institute
Materials Research Laboratories
195 Chung-Hsing Road, Sec. 4
Chutung Hsinchu 31015 R.O.C.
TAIWAN AIR MAIL
713. Robert M. Washburn
ASMT
11203 Colima Road
Whittier, CA 90604
714. Gerald Q. Weaver
Carborundum Specialty Products
42 Linus Allain Avenue
Gardner, MA 01440-2478
715. Karen E. Weber
Detroit Diesel Corporation
Technology and Planning
13400 West Outer Drive
Detroit, MI 48239-4001
716. R. W. Weeks
Argonne National Laboratory
MCT-212
9700 South Cass Avenue
Argonne, IL 60439
717. Ludwig Weiler
ASEA Brown Boveri AG
Corporate Research
Eppelheimer Str. 82
D-6900 Heidelberg
GERMANY AIR MAIL
718. James Wessel
Dow Corning Corporation
1800 "M" Street, N.W.,
Suite 325 South
Washington, DC 20036
719. Robert D. West
Therm Advanced Ceramics
P.O. Box 220
Ithaca, NY 14851
720. Thomas J. Whalen
Ford Motor Company
26362 Harriet
Dearborn Heights, MI 48127
721. Ian A. White
Hoeganaes Corporation
River Road
Riverton, NJ 08077

689. L. J. Trostel, Jr.
Box 199
Princeton, MA 01541
690. W. T. Tucker
General Electric Company
Corporate R&D
Building K1-4C35
P.O. Box 8
Schenectady, NY 12301
691. Masanori Ueki
Nippon Steel Corporation
Central R&D Bureau
1618 Ida
Nakahara-Ku Kawasaki 211
JAPAN AIR MAIL
692. Filippo M. Ugolini
ATA Studio
Via Degli Scipioni, 268A
ROMA 00192
ITALY AIR MAIL
693. Donald L. Vaccari
Allison Gas Turbines
P.O. Box 420
Speed Code S49
Indianapolis, IN 46206-0420
694. Carl F. Van Conant
Boride Products, Inc.
2879 Aero Park Drive
Traverse City, MI 49684
695. Marcel H. Van De Voorde
Commission of the European
Communities
Institute for Advanced
Materials
Joint Research Centre
P.O. Box 2
1755 ZG Petten
THE NETHERLANDS AIR MAIL
696. O. Van Der Biest
Katholieke Universiteit Leuven
Departement Metaalkunde en
Toegepaste
de Croylaan 2
B-3030 Leuven
BELGIUM AIR MAIL
697. Michael Vannier
Washington University,
St. Louis
Mallinckrodt Institute of
Radiology
510 South Kings Highway
St. Louis, MO 63110
698. Stan Venkatesan
Southern Coke & Coal
Corporation
P.O. Box 52383
Knoxville, TN 37950
699. V. Venkateswaran
Carborundum Company
Niagara Falls R&D Center
P.O. Box 832
Niagara Falls, NY 14302
700. Dennis Viechnicki
U.S. Army Materials Technology
Laboratory
405 Arsenal Street
Watertown, MA 02172-0001
701. Ted Vojnovich
U.S. Department of Energy
Office of Energy Research,
ER-42
Washington, DC 20585
702. John D. Volt
E. I. DuPont de Nemours &
Company, Inc.
P.O. Box 30262
Wilmington, DE 19880
703. John B. Wachtman
Rutgers University
Ceramics Department
P.O. Box 909
Piscataway, NJ 08855
704. Shigetaka Wada
Toyota Central Research
Labs, Inc.
Nagakute Aichi 480-11
JAPAN AIR MAIL

672. Patrick L. Sutton
U.S. Department of Energy
Advanced Propulsion Division
CE-322, Forrestal Building
Washington, DC 20585
673. Willard H. Sutton
United Technologies
Corporation
Research Center, MS:24
Silver Lane
East Hartford, CT 06108
674. Ron Sviben
100 Indel Avenue
Rancocas, NJ 08073
675. J. J. Swab
U.S. Army Materials Technology
Laboratory
Ceramics Research Division
SLCMT-EMC
405 Arsenal Street
Watertown, MA 02172
676. Robert E. Swanson
Metalworking Technology, Inc.
1450 Scalp Avenue
Johnstown, PA 15904
677. Scott L. Swartz
Battelle Columbus
Laboratories
Metals and Ceramics
505 King Avenue
Columbus, OH 43201
678. Steve Szaruga
Air Force Wright Aeronautical
Laboratory
Materials Directorate
WL/MLBC
Wright-Patterson
AFB, OH 45433-6533
679. Yo Tajima
NGK Spark Plug Company, Ltd.
NTK Technical Ceramic Division
2808 Iwasaki
Komaki-shi Aichi-ken 485
JAPAN AIR MAIL
680. Fred Teeter
5 Tralee Terrace
East Amherst, NY 14051
681. Monika O. Ten Eyck
Carborundum Company
Technology Division
P.O. Box 832
Niagara Falls, NY 14302
682. David F. Thompson
Corning Glass Works
SP-DV-02-1
Corning, NY 14831
683. Merle L. Thorpe
Hobart Tafa Technologies, Inc.
146 Pembroke Road
Concord, NH 03301
684. Eberhard Tiefenbacher
Daimler-Benz AG Abt. F1S
Mercedes-Strabe 136
Stuttgart 60
GERMANY AIR MAIL
685. T. Y. Tien
University of Michigan
Materials Science and
Engineering Department
Dow Building
Ann Arbor, MI 48103
686. Julian M. Tishkoff
Air Force Office of Scientific
Research
AFOSR/NA
Bolling AFB, DC 20332-6448
687. D. M. Tracey
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
688. Dick Trippett
General Motors Corporation
Allison Gas Turbine Division
P.O. Box 420, MS:W-16
Indianapolis, IN 46206-0420

639. George H. Siegel
Point North Associates, Inc.
P.O. Box 907
Madison, NJ 07940
640. Richard Silberglitt
Technology Assessment and
Transfer, Inc.
133 Defense Highway, #212
Annapolis, MD 21401
641. Mary Silverberg
Norton Company
Advanced Ceramics Library
Goddard Road
Northboro, MA 01532-1545
642. Gurpreet Singh
Department of the Navy
Internal Combustion & Gas
Turbine Engine Division
Code 56X31
Washington, DC 20362-5101
643. Maurice J. Sinnott
University of Michigan
Chemical and Metallurgical
Engineering
5106 IST Building
Ann Arbor, MI 48109-2099
644. John Skildum
3M Company
3M Center
Building 224-2S-25
St. Paul, MN 55144
645. David P. Smith
Hoskins, Rees & Smith
1910 Cochran Road
Manor Oak II, Suite 658
Pittsburgh, PA 15220
646. Richard H. Smoak
Smoak & Associates
3554 Hollislope Road
Altadena, CA 91001-3923
647. Jay R. Smyth
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
2739 East Washington Street
P.O. Box 5227
MS:93-173/1303-207
Phoenix, AZ 85010
648. Edward A. Snajdr
Premier Refractories
and Chemicals, Inc.
P.O. Box 392
Findlay, OH 44815
649. Rafal A. Sobotowski
British Petroleum Company
Technical Center, Broadway
3092 Broadway Avenue
Cleveland, OH 44115
650. A. G. Solomah
SAC International Ltd.
1445 Bonhill Road, # 13
Mississauga Ontario L5T 1V3
CANADA AIR MAIL
651. S. Somiya
Nishi Tokyo University
3-7-19 Seijo, Setagaya
Tokyo 157
JAPAN AIR MAIL
652. Boyd W. Sorenson
DuPont Lanxide Composites
1300 Marrows Road
P.O. Box 6077
Neward, DE 19707
653. Charles A. Sorrell
U.S. Department of Energy
Advanced Industrial
Concepts Division
CE-232, Forrestal
Building
Washington, DC 20585

654. C. Spencer
EA Technology
Capenhurst Chester
CH1 6ES
UNITED KINGDOM AIR MAIL
655. Allen Spizzo
Hercules, Inc.
Hercules Plaza
Wilmington, DE 19894
656. Richard M. Spriggs
Alfred University
Center for Advanced Ceramic
Technology
Alfred, NY 14802
657. Charles Spuckler
NASA Lewis Research Center
21000 Brookpark Road
MS: 5-11
Cleveland, OH 44135-3191
658. M. Srinivasan
Material Solutions
P.O. Box 663
Grand Island, NY 14702-0663
659. Gordon L. Starr
Cummins Engine Company, Inc.
Design & Technology
P.O. Box 3005
Mail Code 50182
Columbus, IN 47202-3005
660. Jim Stevenson
Windrock, Incorporated
154 Fairbanks Plaza
Oak Ridge, TN 37830
661. Tom Stillwagon
Allied-Signal Aerospace
Company
Garrett Ceramic Components
Division
19800 South Van Ness Avenue
Torrance, CA 90501
662. Harold L. Stocker
General Motors Corporation
Allison Gas Turbine Division
P.O. Box 420
Indianapolis, IN 46206
663. Paul D. Stone
Dow Chemical USA
1776 "Eye" Street, N.W.,
Suite 575
Washington, DC 20006
664. Roger S. Storm
Carborundum Company
Technology Division
P.O. Box 337
Niagara Falls, NY 14302-0337
665. Peter A. Stranges
4 Chittenden Lane
Owings Mills, MD 21117
666. F. W. Stringer
Aero & Industrial
Technology Ltd.
P.O. Box 46, Wood Top
Burnley Lancashire BB11 4BX
UNITED KINGDOM AIR MAIL
667. Thomas N. Strom
NASA Lewis Research Center
21000 Brookpark Road
MS:86-6
Cleveland, OH 44135
668. M. F. Stroosnijder
Institute for Advanced
Materials
Joint Research Centre
21020 Ispra (VA)
ITALY AIR MAIL
669. Karsten Styhr
30604 Ganado Drive
Rancho Palos Verdes, CA 90274
670. T. S. Sudarshan
Materials Modification, Inc.
2929-P1 Eskridge Center
Fairfax, VA 22031
671. M. J. Sundaresan
University of Miami
Mechanical Engineering
Department
P.O. Box 248294
Coral Gables, FL 33124

722. Alan Whitehead
General Electric Company
1 River Road, 55-111
Schenectady, NY 12345
723. Sheldon M. Wiederhorn
National Institute of
Standards and Technology
Building 223, Room A329
Gaithersburg, MD 20899
724. John F. Wight
Alfred University
McMahon Building
Alfred, NY 14802
725. D. S. Wilkinson
McMaster University
Materials Science and
Engineering Department
1280 Main Street, West
Hamilton Ontario L8S 4L7
CANADA AIR MAIL
726. James C. Williams
General Electric Company
Engineering Materials
Technology Labs
One Neumann Way
Mail Drop: H85
Cincinnati, OH 45215-6301
727. Janette R. Williams
Kollmorgen Corporation
PCK Technology Division
150 Motor Parkway, # 262
Hauppauge, NY 11788-5108
728. Steve J. Williams
RCG Hagler Bailly, Inc.
1530 Wilson Boulevard,
Suite 900
Arlington, VA 22209-2406
729. Craig A. Willkens
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
730. Roger R. Wills
TRW, Inc.
Valve Division
1455 East 185th Street
Cleveland, OH 44110
731. David Gordon Wilson
Massachusetts Institute of
Technology
Mechanical-Engineering
Department
77 Massachusetts Avenue,
Room 3-455
Cambridge, MA 02139
732. Matthew F. Winkler
Seaworthy Systems, Inc.
P.O. Box 965
Essex, CT 06426
733. Gerhard Winter
Hermann C. Starck Berlin GmbH,
Werk Goslar
P.O. Box 25 40
D-3380 Goslar 3380
GERMANY AIR MAIL
734. W. L. Winterbottom
Ford Motor Company
Material Systems Reliability
Department
20000 Rotunda Drive
SRL, Room E-3182
P.O. Box 2053
Dearborn, MI 48121
735. David G. Wirth
Coors Ceramics Company
600 9th Street
Golden, CO 80401
736. Thomas J. Wissing
Eaton Corporation
Engineering & Research Center
P.O. Box 766
Southfield, MI 48037
737. James C. Withers
MER Corporation
7960 South Kolb Road
Building F
Tucson, AZ 85706

738. Dale E. Wittmer
Southern Illinois University
Mechanical Engineering
Department
Carbondale, IL 62901
739. Warren W. Wolf
Owens Corning Fiberglass
2790 Columbus Road, Route 16
Granville, OH 43023
740. George W. Wolter
Howmet Turbine Components
Corporation
Technical Center
699 Benston Road
Whitehall, MI 49461
741. James C. Wood
NASA Lewis Research Center
21000 Brookpark Road
MS:86-6
Cleveland, OH 44135
742. Marrill Wood
LECO Corporation
Augusta Division
P.O. Box 211688
Augusta, GA 30917-1688
743. Wayne L. Worrell
University of Pennsylvania
Department of Materials
Science and Engineering
3231 Walnut Street
Philadelphia, PA 19104
744. John F. Wosinski
Corning Inc.
ME-2 E-5 H8
Corning, NY 14830
745. Ian G. Wright
Battelle Columbus Laboratories
505 King Avenue
Columbus, OH 43201
746. Ruth Wroe
ERDC
Metals & Materials Industries
Division
Capenhurst Chester CH1 6ES
ENGLAND AIR MAIL
747. Bernard J. Wrona
Advanced Composite Materials
Corporation
1525 South Buncombe Road
Greer, SC 29651
748. Carl C. M. Wu
Naval Research Laboratory
Ceramic Branch, Code 6373
Washington, DC 20375
749. John C. Wurst
University of Dayton Research
Institute
300 College Park
Dayton, OH 45469-0101
750. Neil Wyant
ARCH Development Corp.
9700 South Cass Avenue
Building 202
Argonne, IL 60439
751. Roy Yamamoto
Texaco Inc.
P.O. Box 509
Beacon, NY 12508-0509
752. John Yamanis
Allied-Signal, Inc.
Ceramics Program
P.O. Box 1021
Morristown, NJ 07962-1021
753. Harry C. Yeh
Allied-Signal Aerospace
Company
Garrett Ceramic Components
Division
19800 South Van Ness Avenue
Torrance, CA 90509
754. Hiroshi Yokoyama
Hitachi Research Lab
4026 Kuji-Cho
Hitachi-shi Ibaraki 319-12
JAPAN AIR MAIL
755. Thomas M. Yonushonis
Cummins Engine Company, Inc.
P.O. Box 3005
Mail Code 50183
Columbus, IN 47202-3005

756. Thomas J. Yost
Corning, Inc.
Technical Products Division,
Main Plant 21-1-2
Corning, NY 14831
757. Jong Yung
Sundstrand Aviation
Operations
Department 789-6
4747 Harrison Avenue
Rockford, IL 61125
758. A. L. Zadoks
Caterpillar Inc.
Technical Center, Building L
P.O. Box 1875
Peoria, IL 61656-1875
759. Avi Zangvil
University of Illinois
Materials Research Laboratory
104 South Goodwin Avenue
Urbana, IL 61801
760. Charles H. Zenuk
Transtech
6529 East Calle Cavalier
Tucson, AZ 85715
761. Anne Marie Zerega
U.S. Department of Energy
Office of Energy Research,
ER-42
Washington, DC 20585
762. Ken Zillmer
Applied Test Systems, Inc.
2571 Mt. Gallant Road
Rock Hill, SC 29730
763. Carl Zweben
General Electric Company
P.O. Box 8555, VFSC/V4019
Philadelphia, PA 19101
764. Klaus M. Zwilsky
National Research Council
National Materials
Advisory Board
2101 Constitution Avenue
Washington, DC 20418
765. Department of Energy
DOE Field Office, Oak Ridge
Assistant Manager for Energy
Research and Development
P.O. Box 2001
Oak Ridge, TN 37831-8501
- 766-775. Department of Energy
Office of Scientific and
Technical Information
Office of Information
Services
P.O. Box 62
Oak Ridge, TN 37831
- For distribution by microfiche
as shown in DOE/OSTI-4500,
Distribution Category UC-332
(Ceramics/Advanced Materials).

END

**DATE
FILMED**

10 / 28 / 92