Received by OSTI
DEC 01 1992

ORNL/TM-12232

**OAK RIDGE
NATIONAL
LABORATORY**

MARTIN MARIETTA

**Evaluation of Criticality Alarm
Response at the WEMCO
Fernald Site**

B. L. Broadhead
R. L. Childs
R. M. Westfall
C. V. Parks

MANAGED BY
MARTIN MARIETTA ENERGY SYSTEMS, INC.
FOR THE UNITED STATES
DEPARTMENT OF ENERGY

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

This report has been reproduced directly from the best available copy.

Available to DOE and DOE contractors from the Office of Scientific and Technical Information, P.O. Box 62, Oak Ridge, TN 37831; prices available from (615) 576-8401, FTS 626-8401.

Available to the public from the National Technical Information Service, U.S. Department of Commerce, 5285 Port Royal Rd., Springfield, VA 22161.

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

**EVALUATION OF CRITICALITY ALARM RESPONSE AT THE
WEMCO FERNALD SITE**

B. L. Broadhead, R. L. Childs, R. M. Westfall, and C. V. Parks
Computing and Telecommunications Division
at Oak Ridge National Laboratory
P.O. Box 2008
Oak Ridge, TN 37831-6370

Date Published: November 1992

Prepared by the
OAK RIDGE NATIONAL LABORATORY
managed by
MARTIN MARIETTA ENERGY SYSTEMS, INC.
for the
U.S. DEPARTMENT OF ENERGY
under contract DE-AC05-84OR21400

MASTER

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

ja

CONTENTS

	<u>Page</u>
LIST OF FIGURES	iv
LIST OF TABLES	v
ACKNOWLEDGMENTS	vii
ABSTRACT	ix
INTRODUCTION	1
RADIATION SOURCE TERMS	2
EVALUATION OF CRITICALITY ALARM LOCATIONS FOR BUILDING 6	3
ANALYSIS OF ADDITIONAL SHIELD CONFIGURATIONS	10
ACCIDENT CONSEQUENCES	10
REFERENCES	18

LIST OF FIGURES

<u>Figure</u>	<u>Page</u>
1. A side view of Building 6	4
2. Total gamma dose distribution inside Building 6	7
3. Total gamma dose distribution throughout entire system	8
4. Thermal neutron flux distribution throughout entire system	9
5. Generic configuration No. 1	11
6. Generic configuration No. 2	12
7. Generic configuration No. 3	13
8. Generic configuration No. 4	14
9. Generic configuration No. 5	15
10. Generic configuration No. 6	16

LIST OF TABLES

<u>Table</u>	<u>Page</u>
1. Material number densities used in analysis	6
2. Building 6 dose profiles (U_3O_8 source)	6
3. Doses from a 1-D calculation containing drums as modeled in Fig. 8	17
4. Activities of important nuclides released from postulated criticality accident with $\text{U}_3(4.46)\text{O}_8$	18

ACKNOWLEDGMENTS

The work performed by the staff at Westinghouse Environmental Management Company of Ohio (WEMCO), including Ron Marble, Dave Lindenschmidt (formerly of WEMCO), and Chris Miller, is hereby acknowledged. Special thanks to Ron Marble who patiently handled the financial aspects of establishing a purchase order.

The technical input of W. C. Jordan and C. M. Hopper of ORNL is also greatly appreciated. Special thanks to Joe Turner for the production of several figures in this report. The careful preparation of the manuscript by Lindy Norris is gratefully acknowledged.

This work was performed under WEMCO Purchase Order 623129.

ABSTRACT

This work quantifies the expected dose rates at a series of criticality alarm locations due to several postulated criticality accidents at the Westinghouse Environmental Management Company of Ohio (WEMCO) Fernald site. One- and two-dimensional discrete-ordinates calculations were performed for seven different shielding configurations using leakage spectra corresponding to two specific postulated critical events.

In addition, an estimate of the gaseous fission products released during the hypothetical accident was made using the ORIGEN-S point-depletion code.

INTRODUCTION

This report documents work performed at the Oak Ridge National Laboratory (ORNL) to evaluate the radiation dose and fission-product release from a hypothetical criticality accident at the Fernald site, operated by Westinghouse Environmental Management Company of Ohio (WEMCO). The work was performed under WEMCO Purchase Order 623129 and includes several subtasks:

1. determination of the limiting radiation source terms from postulated criticality accidents,
2. calculation of the dose rate that would be seen by the criticality alarms in Building 6 using the postulated accident source terms,
3. calculation of the dose attenuation from the accident source for a number of generic configurations existing at Fernald, and
4. analysis of the consequences of a criticality event in accordance with Regulatory Guide 3.34.¹

The American National Standard ANSI/ANS-8.3-1979² entitled "Criticality Accident Alarm System" generally provides guidance for the establishment and maintenance of such systems in facilities engaged in the processing of fissionable materials. Section 5.2 of the Standard addresses the question of the minimum accident of concern:

5.2 Detection Criterion. Criticality alarm systems shall be designed to detect immediately the minimum accident of concern. For this purpose, in areas where material is handled or processed with only nominal shielding, the minimum accident may be assumed to deliver the equivalent of an absorbed dose in free air of 20 Rad at a distance of 2 m from the reaction material in 60 s.

This criterion establishes the reference criticality incident for this study. In terms of average dose rate, the event generates 1200 R/h (Rad/hour) of combined neutron and photon (gamma ray) absorbed dose at positions 2 m from the surface of the critical volume. The Henderson³ free-in-air tissue dose factors are suitable response functions for the dose specified in this criterion.

The motivation for this study arose from the interest in establishing the photon radiation levels at the photon-sensitive criticality alarm detector positions in several storage areas at the Fernald facility with an assumed incident radiation corresponding to the minimum accident of concern. The hypothetical incident occurring in Building 6 was located in the analytical model such that the detector positions would be subject to a maximum shielding effect from neighboring storage-drum arrays containing little or no fissile material.

The following types of fissile materials are currently stored at the Fernald site in large enough quantities to cause criticality concerns: 14,000 kg of $U(1.25)F_4$, 600 kg of $U_3(4.46)O_8$, and 1600 kg of $U(3.9)O_2$ pellets. After careful study of these potential criticality materials, the first two were selected for spectrum characterization such that their relative attenuation in the Building 6 geometry could be evaluated. The source with the minimum total photon dose contribution at the location corresponding to the Building 6 criticality alarm was then used in

the evaluation of several generic shielding situations corresponding to other storage areas at the Fernald site.

The final task consisted of the estimation of the postulated criticality accident yield and corresponding fission-product releases in accordance with Regulatory Guide 3.34. The characteristics of criticality accidents involving both $U(1.25)F_4$ and $U_3(4.46)O_8$ were analyzed, and maximum fission yields and corresponding releases of the gaseous fission products were estimated.

RADIATION SOURCE TERMS

Radiation source terms from a postulated criticality accident were needed for this project in order to evaluate the dose that would be measured by photon-sensitive detector alarms. Fissile material in the form of $U(1.25)F_4$ and $U_3(4.46)O_8$ is stored at the Fernald site in sufficient quantity that a criticality event could occur if substantial moderation, presumably by water, were provided to a hypothetical configuration. To ensure activation of the photon-sensitive detectors for all conceivable criticality accidents, it is necessary to develop a "conservative" radiation source term that produces a minimal photon component. Because water preferentially reduces neutron leakage, it was assumed that the maximum neutron leakage (and thus minimum photon component) would result from a critical system with a minimal amount of internal moderation by water [i.e., a system with a minimum hydrogen/uranium (H/U) ratio].

For the $U(1.25)F_4$ system, guidance to develop the critical system was received from ref. 4, where the effects of water content on critical mass were studied. Two physical densities (2.5 and 4.0 g/cm³) for the UF_4 were considered. At a water volume fraction of 0.4, each system has a critical mass of approximately 14,000 kg. However, the H/U ratio for the higher density fuel is only 0.625 of the value for the lower density fuel. Therefore, the higher density material will produce the relatively higher neutron leakage component.

System Description: ~ 14,000 kg of $U(1.25)F_4$ at $\rho = 4.0$ g/cm³ and H_2O at $\rho = 0.4$ g/cm³.

Number Densities (atoms/b-cm): $^{235}U = 9.6 \times 10^{-5}$, $^{238}U = 7.6 \times 10^{-3}$, $F = 3.1 \times 10^{-2}$,
 $H = 2.6 \times 10^{-2}$, $O = 1.3 \times 10^{-2}$.

At least 600 kg of $U_3(4.46)O_8$ fuel is located at the Fernald site. This fuel was used to perform critical experiments at the Rocky Flats plant in the 1970s.⁵ One of the latest series of critical experiments used dampened fuel with an H/U ratio of 2.03 and a 0.93-cm-thick piece of Plexiglas uniformly dispersed between the fuel cans. The hydrogen in the Plexiglas is equivalent to a uniformly distributed H/U value of 1.0. Thus, the total moderation, neglecting the carbon and oxygen in the Plexiglas, corresponds to an H/U of 3.03.

System Description: 600 kg of $U_3(4.46)O_8$ at $\rho = 4.8$ g/cm³ and additional H_2O to reach H/U = 3.03 (0.46246 g/cm³ of H_2O).

Number Densities (atoms/b-cm): $^{235}U = 4.6 \times 10^{-4}$, $^{238}U = 9.8 \times 10^{-3}$, $H = 3.09 \times 10^{-2}$,
 $O = 4.3 \times 10^{-2}$.

A critical radius search was performed for each system using the XSDRNPM module of SCALE.⁶ The SCALE 27-neutron 18-gamma-group library was the basis for these calculations,

as well as all others in this study. Each system was reflected by 1.27 cm of water. The calculated critical radii for spheres of these materials are 129.6 cm for the UF_4 system and 32.2 cm for the U_3O_8 system. Because the U_3O_8 system is much smaller, the leakage per fission is much larger for this system. However, ANSI/ANS-8.3, "Criticality Alarm Systems," specifies that the minimum accident of concern has a total neutron plus photon dose of 1200 R/h at 2 m from the surface of the system. The SAS1X control module of SCALE was used to calculate 2-m doses for each system. Each fission source was then normalized such that the 2-m dose would equal 1200 R/h. After this normalization, the 2-m photon dose is 265 R/h for the U_3O_8 system vs 343 R/h for the UF_4 system. The relative system sizes cause the normalized UF_4 system to have a much higher fission rate than the normalized U_3O_8 system.

The overall result of the source normalization is that the U_3O_8 source gives smaller photon doses for all the shielding cases considered. Therefore, all the results presented herein were calculated using the radiation source spectra from the U_3O_8 system. The results for the UF_4 source are roughly a factor of 2 higher in each case.

As noted in the Introduction, there are 1600 kg of $\text{U}(3.9)\text{O}_2$ pellets at the Fernald site. The opinion of the ORNL staff before and after the completion of this work is that the UF_4 and U_3O_8 systems provide adequate bounding sources in terms of fuel enrichment and water moderation effects.

EVALUATION OF CRITICALITY ALARM LOCATIONS FOR BUILDING 6

The preceding sources were used in a radiation transport analysis of Building 6 to evaluate the effectiveness of the criticality alarms in place at Fernald. A side view of the Building 6 layout is shown in Fig. 1. A decision was made early in the project to perform the radiation transport calculations using the DORT⁷ discrete-ordinates code with an R-Z geometry model. R-Z geometry can accurately model the penetration through the stacked drum units as well as the transport through the roof and air scattering above the roof. However, because of the azimuthal symmetry inherent in an R-Z model, gamma-ray and neutron particles that may reach the detector by scattering around the array of stacked drums are not accounted for correctly. The dose at the detector is underestimated since all particles are forced to go through or over the array. The R-Z model used in this study also does not account for streaming down hallways between stacks of drums, which would effectively increase the dose at the criticality alarm. Although a Monte Carlo radiation transport code would enable a more-detailed geometric model, the large source-to-detector distance and intermediate shield material, coupled with the potential importance of secondary gamma rays, could make it extremely difficult to obtain an accurate result from a Monte Carlo code.

The plausible location for a criticality accident is the enriched storage area of Building 6. The R-Z DORT model, using an S_{10} angular quadrature, was developed with a point radiation source within the enriched storage area located at the center of the model. This central point was modeled 5 ft from the concrete wall and 4 ft above the concrete floor, shown in Fig. 1. The energy spectrum for the point source was consistent with the leakage spectrum from the spherical critical system model. The first collision source code, GRTUNCL,⁷ was used to create a distributed (i.e., distributed throughout the R-Z model) first-collision source for the DORT analysis.

Fig. 1. A side view of Plant 6.

The walls and drums stored in Building 6 were modeled at the locations shown in Fig. 1. The stacks of drums were modeled as solid steel in order to obtain (conservatively) more shielding than is actually present. The pitched roof shown in Fig. 1 was modeled as a simple flat roof of 3/8-in. transite located 28 ft above the floor. The air above the roof was also included in the model to a height of 443 ft above the floor. The concrete floor was modeled as 1-ft thick to account for an assumed 2- to 3-in.-thick floor, with the remaining concrete approximating ground materials under the floor. The air, concrete floor, and roof were extended beyond the wall behind the detector to a distance of 400 ft from the source. Within the radiation detection alarm (RDA) station, the detector was located in this model at 42 in. from the transite wall and 61 in. above the floor. The number densities for all materials used in this work are given in Table 1. The total photon dose at the detector location is 75.8 mR/h with 9.9 mR/h from primary photons and 65.9 mR/h from secondary gamma rays produced from (n, γ) reactions. The dose 14 ft above the floor at the detector location is 101.0 mR/h. The total gamma dose levels at other locations are given in Table 2. These locations correspond to the center of hallway or gap regions between drum arrays as shown in Fig. 1. These gamma dose rates are given for two heights: one at the detector height (61 in. above the floor) and the other 14 ft above the floor. The total gamma dose rates are also plotted in Figs. 2 and 3. Figure 2 plots lines of constant gamma dose for the regions inside Building 6. Figure 3 indicates lines of constant gamma dose for the entire geometry as modeled.

The information shown in Fig. 3 is useful both to present the dose over the entire region and to aid in interpretation of the physics of the calculation. The "fingers" shown in the air above the building are numerical anomalies called ray effects. Their effect on the dose predictions at the detector is expected to be minimal due to canceling high and low contributions from scattering in the air. Additionally, the gamma rays that transport through the air are augmented by local gamma production due to thermal neutron capture in the steel drums and concrete floor. Figure 4 shows the distribution of thermal neutron flux throughout the system lacks the ray effect anomalies present in the gamma-ray doses. This gives added confidence to the RDA location results. The DORT model was revised several times to ensure that a reasonably accurate spatial mesh was used. The uncertainty of these calculated doses is less than a factor of 2. The possibility of reducing this uncertainty with additional analyses is unlikely.

One issue raised in the review of this project work was that the calculated total dose at the detector consists of 87% secondary gamma rays resulting from neutron interactions. Thus, there is the possibility that a critical system with a **minimum** neutron leakage would produce the most conservative (lowest) dose for the minimal accident of concern. Although a curious issue, the conclusion of the authors is that the approach that was taken is prudent because of the following:

1. Minimizing the neutron source component would require much more water. Mechanistically, this is a less-likely accident scenario.
2. If the neutron dose at 2 m is minimized, the primary photon dose would increase. To first order the authors' opinion is that the total photon dose at the detector would remain approximately the same, except there would be more primary gammas and less secondary gammas.

Table 1. Material number densities used in analysis

Material	Isotope	Number density
Steel	Fe	8.34982E-2
	C	3.92503E-3
Air	N	3.57000E-5
	O	7.84000E-6
Concrete	H	1.37437E-2
	O	4.60675E-2
	Al	1.74537E-3
	Ca	1.52055E-3
	Fe	3.47236E-4
	Si	1.66199E-2
	Na	1.74722E-3
Transite	H	1.77736E-2
	O	3.94997E-2
	Al	4.92095E-4
	Mg	7.06053E-3
	K	6.40687E-5
	Ca	4.28157E-3
	Fe	6.59446E-4
	C	3.89351E-3
	N	5.70880E-3

Table 2. Building 6 dose profiles (U_3O_8 source)

Dose rate at detector height ^a	Dose rate 14 ft above floor	Radial location ^b
23.6 R/h	26.1 R/h	Center of 9-ft aisle
819.4 mR/h	1257.3 mR/h	Center of 13-ft aisle
397.8 mR/h	594.0 mR/h	Center of 21-ft aisle
150.1 mR/h	390.8 mR/h	Center of 8-ft aisle
74.6 mR/h	150.7 mR/h	Center of 8.5-ft aisle
75.8 mR/h	101.0 mR/h	RDA detector

^a61 in. above floor.

^bSee Fig. 1.

PLOT OF FERNALD GAMMA DOSE

Fig. 2. Total gamma dose distribution inside Building 6.

RZ PLOT FOR FERNALD GAMMA DOSE

Fig. 3. Total gamma dose distribution throughout entire system.

ANALYSIS OF ADDITIONAL SHIELD CONFIGURATIONS

The results from additional shielding calculations performed for geometries typical of those found at Fernald are shown in Figs. 5 through 10. The case with sources above an 8-in. concrete slab (Fig. 5) were done in R-Z geometry using the same methods applied for the Building 6 calculation. The other results were obtained from one-dimensional (1-D) transport calculations in spherical geometry using the SCALE module, SAS1. The concrete, steel, transite, and air number densities used in the 1-D calculations were identical to those used in the Building 6 calculations shown in Table 1. For the two geometries containing drums, the drums were modeled as pure MgF_2 with a density of 3.148 g/cm^3 . The thickness of each drum in these calculations was 35.72 cm. Dose, as a function of distance into the drums in Fig. 8, is given in Table 3.

ACCIDENT CONSEQUENCES

The final task consisted of estimating the releases of fission products from a postulated criticality accident. The two criticality accidents postulated were caused by $\text{U}(1.25)\text{F}_4$ and $\text{U}_3(4.46)\text{O}_8$ materials. Of these two potential accidents, the $\text{U}_3(4.46)\text{O}_8$ should be the most severe since larger reactivities are more likely due to the smaller system size and higher enrichments. However, the local conditions of the storage of these materials should limit the magnitude of potential excursions. The fissile materials are in a passive storage condition with no continuous water source (i.e., sprinklers) available. A criticality event would require several simultaneous low-probability actions to occur (i.e., rapid movement of several drums, rupture of outer packaging and favorable geometry assembly of fissile materials in the presence of sufficient quantities of water). Since the occurrence of recriticality is assumed to have a very low probability, only an initial fission pulse of 10^{18} fissions is assumed. The duration of this pulse was assumed to be 200 s using the largest postulated fission rate from the criticality alarm analysis. This postulated event duration should have little or no impact as compared with a 0.5-s duration, except for ^{89}Kr and ^{137}Xe . The curie levels for these isotopes would increase by factors of 2.1 and 1.8, respectively.

The fission products released (per Regulatory Guide 3.34) from the above postulated accident are given in Table 4. These estimates were obtained using the ORIGEN-S code.³ The data in Table 4 do not include the iodine reduction factor as allowed in the Guide.

Fig. 5. Generic configuration No. 1.

Generic Configuration 2

Fig. 6. Generic configuration No. 2.

Generic Configuration 3

Fig. 7. Generic configuration No. 3.

Generic Configuration 4

Fig. 8. Generic configuration No. 4.

Generic Configuration 5

Fig. 9. Generic configuration No. 5.

Generic Configuration 6

Fig. 10. Generic configuration No. 6.

Table 3. Doses from a 1-D calculation containing drums as modeled in Fig. 8

Radius (cm)	Dose (R/h)
4.41981E+02	3.37612E+02
4.61707E+02	2.83580E+02
4.66714E+02	2.28461E+02
4.71722E+02	1.85764E+02
4.76729E+02	1.54134E+02
4.81737E+02	1.29984E+02
4.86744E+02	1.10618E+02
4.91752E+02	9.44088E+01
4.96759E+02	8.04595E+01
5.01767E+02	6.82933E+01
5.06774E+02	5.76512E+01
5.11781E+02	4.83746E+01
5.16789E+02	4.03444E+01
5.21796E+02	3.34520E+01
5.26804E+02	2.75890E+01
5.31811E+02	2.26451E+01
5.36819E+02	1.85102E+01
5.41826E+02	1.50775E+01
5.46834E+02	1.22466E+01
5.51841E+02	9.92518E+00
5.56849E+02	8.03090E+00
5.61856E+02	6.49135E+00
5.66864E+02	5.24413E+00
5.71871E+02	4.23622E+00
5.76879E+02	3.42311E+00
5.81886E+02	2.76786E+00
5.86894E+02	2.24006E+00
5.91901E+02	1.81487E+00
5.96909E+02	1.47212E+00
6.01916E+02	1.19548E+00
6.06924E+02	9.71840E-01
6.11931E+02	7.90638E-01
6.16939E+02	6.43417E-01
6.21946E+02	5.23396E-01
6.26953E+02	4.25144E-01
6.31961E+02	3.44304E-01
6.36968E+02	2.77377E-01
6.41976E+02	2.21551E-01
6.46983E+02	1.74570E-01
6.51991E+02	1.34628E-01
6.56998E+02	1.00309E-01
6.62006E+02	7.05341E-02
6.67013E+02	4.44965E-02
6.78660E+02	2.10193E-02

Table 4. Activities of important nuclides released from postulated criticality accident with $U_3(4.46)O_8$

Nuclide	Radioactivity (curies)
Kr-83m	3.0E-2
Kr-85m	2.9E+0
Kr-85	1.4E-6
Kr-87	5.1E+1
Kr-88	4.1E+1
Kr-89	2.0E+3
Xe-131m	2.2E-7
Xe-133m	1.5E-3
Xe-133	3.0E-4
Xe-135m	1.5E+1
Xe-135	3.1E-1
Xe-137	2.8E+3
Xe-138	1.0E+3
I-131	2.0E-3
I-132	1.8E-1
I-133	7.4E-1
I-134	2.9E+1
I-135	4.1E+1

REFERENCES

1. Regulatory Guide 3.34, *Assumptions Used for Evaluating the Potential Radiological Consequences of Accident Nuclear Criticality in a Uranium Fuel Fabrication Plant*, U.S. Nuclear Regulatory Commission, Washington, D.C., July 1979.
2. *American National Standard Criticality Accident Alarm System*, ANSI/ANS-8.3-1979, American Nuclear Society, 1979.
3. P. J. Henderson, *Conversion of Neutron and Gamma-Ray Flux to Absorbed Dose Rate*, XDC-59-8-179 (August 1959).
4. J. J. Taylor, *Criticality Safety Calculations for Drum Storage at the Feed Materials Production Center*, WINCO-1084, Westinghouse Idaho Nuclear Company, Inc., Idaho Falls, Idaho, January 1991.
5. R. E. Rothe, G. R. Goebel, *Critical Experiments on Low-Enriched Uranium Oxide Systems with H/U = 2.03*, NUREG/CR-2500 (RFP-3277), Rockwell International Energy Systems Group, February 1982.

6. *SCALE: A Modular Code System for Performing Standardized Computer Analyses for Licensing Evaluation*, NUREG/CR-0200, Rev. 4 (ORNL/NUREG/CSD-2/R4), Vols. I, II, and III (draft March 1992). Available from Radiation Shielding Information Center, Oak Ridge National Laboratory, as CCC-545.
7. W. A. Rhoades and R. L. Childs, *Two- and Three-Dimensional Discrete Ordinates Transport*, January 1992. Available from Radiation Shielding Information Center, Oak Ridge National Laboratory, as CCC-543-TORT-DORT; see also W. A. Rhoades and R.L. Childs, *An Updated Version of the DOT 4 One- and Two-Dimensional Neutron/Photon Transport Code*, ORNL-5851, Union Carbide Corp., Nucl. Div., Oak Ridge Natl. Lab., 1982.

INTERNAL DISTRIBUTION

1.	J. S. Baker	17-21.	C. V. Parks
2.	S. M. Bowman	22-24.	C. H. Shappert
3-7.	B. L. Broadhead	25.	J. S. Tang
8.	R. L. Childs	26.	H. Taniuchi
9.	H. L. Dodds, Jr.	27.	J. C. Turner
10.	H. R. Dyer	28.	R. M. Westfall
11.	O. W. Hermann	29.	G. E. Whitesides
12.	C. M. Hopper	30.	Laboratory Records Dept.
13.	D. T. Ingersoll	31.	Laboratory Records, ORNL-RC
14.	W. C. Jordan	32.	Document Reference Section
15.	L. F. Norris	33.	Central Research Library
16.	J. V. Pace	34.	ORNL Patent Section

EXTERNAL DISTRIBUTION

35. T. Brown, Westinghouse Environmental Management Co., P.O. Box 398704, Cincinnati, Ohio 45239-8704
36. M. J. Galper, Westinghouse Environmental Management Co., P.O. Box 398704, Cincinnati, Ohio 45239-8704
- 37-41. R. C. Marble, Westinghouse Environmental Management Co., P.O. Box 398704, Cincinnati, Ohio 45239-8704
42. J. C. Mincey, Savannah River Laboratory, P.O. Box 616, Bldg. 773-22A, Aiken, South Carolina 29802
43. Office of Assistant Manager for Energy Research and Development, DOE Field Office, Oak Ridge, P.O. Box 2001, Oak Ridge, TN 37831
- 44-45. Office of Scientific and Technical Information, P.O. Box 2001, Oak Ridge, TN 37831
46. J. F. Zino, Savannah River Laboratory, P.O. Box 616, Bldg. 773-22A, Aiken, South Carolina 29802

END

DATE
FILMED

2/12/93