10
9-30-92 JS ①

ORNL/Sub/86-95906/2

**OAK RIDGE
NATIONAL
LABORATORY**

MARTIN MARIETTA

Material Development in the Si_3N_4 System
Using Glass Encapsulated Hip'ing

Final Report

N. D. Corbin, G. J. Sundberg, K. N. Siebein,
C. A. Willkens, V. K. Pujari, G. A. Rossi, J. S. Hansen,
C. L. Chang, and J. L. Hammarstrom

Prepared by Norton Company
Advanced Ceramics
Goddard Road
Northboro, Massachusetts 01532-1545

CERAMIC TECHNOLOGY FOR
ADVANCED HEAT ENGINES

MANAGED BY
MARTIN MARIETTA ENERGY SYSTEMS, INC.
FOR THE UNITED STATES
DEPARTMENT OF ENERGY

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

This report has been reproduced directly from the best available copy.

Available to DOE and DOE contractors from the Office of Scientific and Technical Information, P.O. Box 62, Oak Ridge, TN 37831; prices available from (615) 576-8401, FTS 626-8401.

Available to the public from the National Technical Information Service, U.S. Department of Commerce, 5285 Port Royal Rd., Springfield, VA 22161.

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

MATERIAL DEVELOPMENT IN THE Si_3N_4 SYSTEM
USING GLASS ENCAPSULATED HIP'ING

N. D. Corbin, G. J. Sundberg, K. N. Siebein,
C. A. Willkens, V. K. Pujari, G. A. Rossi, J. S. Hansen,
C. L. Chang, and J. L. Hammarstrom

Date Published-April 1992

FINAL REPORT - Phase II

Prepared by Norton Company
Advanced Ceramics
Goddard Road
Northboro, Massachusetts 01532-1545
Subcontract No. 86X-95906C

Funded by
Office of Transportation Materials
Office of Transportation Technologies
the Assistant Secretary for Conservation and Renewable Energy
U.S. Department of Energy
EE 51 01 00 0

for
OAK RIDGE NATIONAL LABORATORY
Oak Ridge, Tennessee 37831
managed by
MARTIN MARIETTA ENERGY SYSTEMS, INC.
for the
U.S. DEPARTMENT OF ENERGY
under Contract DE-AC05-84OR21400

MASTER

TABLE OF CONTENTS

PAGE

TABLE OF CONTENTS	
EXECUTIVE SUMMARY	
LIST OF FIGURES	
LIST OF TABLES	
ABSTRACT	1
1.0 INTRODUCTION	2
2.0 PROCEDURES	3
- MICROSTRUCTURAL EVALUATION	3
- CHEMICAL EVALUATION	4
- PROPERTY EVALUATION	6
- STRENGTH	6
- FRACTURE TOUGHNESS	6
- ROOM TEMPERATURE TOUGHNESS COMPARISON	8
- STRESS RUPTURE/OXIDATION	8
- COMPOSITE FABRICATION	8
3.0 REINFORCEMENTS	11
- WHISKER SOURCES	11
- ASPECT RATIO	15
- CARBON FIBER	16
- DISPERSION BEHAVIOR	16
4.0 GREEN BODY/FORMING	20
- PURITY EFFECTS	20
- WHISKER ORIENTATION	22
- DISTORTION	26
5.0 INTERFACE EFFECTS	30
- OXIDE INTERFACES	30
- CARBON, SINGLE COATING	34
- CARBON WITH PROTECTIVE COATINGS	38
- BORON NITRIDE, SINGLE COATING	41
- BORON NITRIDE WITH PROTECTIVE COATINGS	49
- AUGER ANALYSIS OF COMPOSITE INTERFACES	51
- METAL/ALLOY	53
- INTERFACIAL STRESSES	55
6.0 PROPERTY PROGRESS	59
- MATERIALS SUPPLIED TO ORNL	59
- HIGH TEMPERATURE EVALUATIONS	60
- FRACTURE TOUGHNESS	60
- OXIDATION	60
- STRESS RUPTURE	62
7.0 SUMMARY/HIGHLIGHTS	66
8.0 RECOMMENDATIONS	67
9.0 ACKNOWLEDGMENTS	69
10.0 REFERENCES	70

EXECUTIVE SUMMARY

This report covers a two-year program to develop fully dense Si_3N_4 matrix SiC whisker composites with enhanced properties over monolithic Si_3N_4 materials. The primary goal was to develop a composite with a fracture toughness $> 10 \text{ MPa}\sqrt{\text{m}}$ capable of operating up to 1400°C . Materials were densified using high pressure glass encapsulated HIP'ing.

The emphasis of this project is to determine the processing/microstructure/property relations in this system. Of particular emphasis were; the interface between the SiC whiskers and the Si_3N_4 matrix, whisker orientation, whisker aspect ratio, and intergranular phase composition and content.

The matrix used in this program is a HIP'ed Si_3N_4 with 4 w/o Y_2O_3 . This composition shows much promise for advanced heat engine applications at 1370°C as a monolith material. Its major drawback is having a fracture toughness of only $5.5 \text{ MPa}\sqrt{\text{m}}$. This program's goal is to improve the fracture toughness of this monolith material to $> 10 \text{ MPa}\sqrt{\text{m}}$ by incorporating SiC whiskers.

This program has demonstrated that improvements in fracture toughness can be made in high temperature (1370°C) Si_3N_4 materials. Highest toughness materials ($\sim 7.0 \text{ MPa}\sqrt{\text{m}}$) are obtained with uniaxially oriented carbon coated SiC whiskers. It should be noted that these toughness values fall below the program goal of $10 \text{ MPa}\sqrt{\text{m}}$. Obtainment of higher toughnesses than the current $7.0 \text{ MPa}\sqrt{\text{m}}$ will be difficult without further development of improved strength SiC whiskers.

A summary of other developments and observations from this program include:

- 1) Stoichiometric microcrystalline and thin ($\sim 4.0 - 150\text{nm}$) boron nitride coatings were successfully applied to SiC whiskers using a CVD process. A pyrolysis process was used to deposit a thin ($\sim 35\text{nm}$) and amorphous boron-nitrogen-carbon containing coating onto whiskers.
- 2) Carbon coatings were successfully applied to whiskers by either a proprietary thermal treatment method or CVD. With the CVD method a dual layer of SiC over carbon was deposited on the whiskers.
- 3) It was observed that as the quantity of carbon on a whisker increases the fracture toughness of the composite increases.

- 4) The use of a boron nitride interface did not improve the fracture toughness of SiC whisker reinforced Si_3N_4 . The cause for this is unclear but likely related to either spalling of the coating during processing or a small quantity of B_2O_3 associated with the coating.
- 5) No significant effect of sintering aid concentration nor composition on fracture toughness was observed.
- 6) Distortion in a whisker reinforced material is significantly reduced when the composite is processed using a HIP'ed reaction-bonding approach rather than a HIP'ed Si_3N_4 powder process. The reduced distortion is a direct result of the improved pre-HIP densities resulting from the reaction-bonding route.
- 7) The reaction-bonding approach results in the deterioration of both carbon and boron nitride whisker coatings. It will be necessary to utilize a barrier coating over the BN or carbon debonding layers to protect them during the reaction-bonding step.
- 8) Neither accelerated nor catastrophic oxidation were observed in silicon nitride reinforced with carbon coated SiC whiskers at 1370°C in air for exposures to 100 hrs.

LIST OF TABLES

		<u>Page</u>
Table 1	Microstructural Features in $\text{Si}_3\text{N}_4/\text{SiC}$ Composites	3
Table 2	Comparison of room temperature fracture toughness as determined by different methods	10
Table 3	Bulk chemical analysis of SiC whiskers	12
Table 4	ESCA data on SiC whiskers	12
Table 5	Auger analysis of individual SiC whiskers	13
Table 6	Composite toughness as a result of whisker source	13
Table 7	Effect of whisker diameter on composite fracture toughness	17
Table 8	Fracture Toughness comparison between a carbon fiber reinforced Si_3N_4 and a Si_3N_4 Monolith	17
Table 9	Concentration of ions detected by atomic absorption spectrophotometry in effluent from acid soaking American Matrix SiC whiskers	18
Table 10	Impurity contents of SiC and Silicon materials used for purity study	21
Table 11	Properties of materials evaluated to determine the effect of impurities	21
Table 12	Whiskers available for bridging in composites with randomly oriented whiskers	24
Table 13	Influence of sintering aid content and composition on toughness	32
Table 14	Fracture toughness data on materials with oxide modified interfaces	33

	<u>Page</u>
Table 15 Comparison of SiC/C dual coatings	40
Table 16 Auger analysis of the BN coating applied to SiC grit by CVD at Norton Company	44
Table 17 Composite interfaces by Auger analysis	52
Table 18 Layered structure materials	54
Table 19 Composites with metal interfaces	54
Table 20 Material properties and geometry constraints used for the calculation of the residual stresses	57
Table 21 Thermal Expansion Coefficients for Potential Phases in $\text{Si}_3\text{N}_4/\text{SiC}_{(w)}$ Composites	58
Table 22 Fracture toughness of composites before and after liquid nitrogen treatment	58
Table 23 Composite materials supplied to ORNL	60
Table 24 Chevron notch fracture toughness as a function of temperature for specimens with 3 x 4 mm cross-section	62
Table 25 Chevron notch fracture toughness as a function of temperature for specimens with a 6x6mm cross section	63
Table 26 Comparison of composite properties before and after oxidation	64
Table 27 Large batch material - Vintage Aug. 87	65

LIST OF FIGURES

		<u>Page</u>
Figure 1	Set up used for the Auger Analysis of SiC whiskers.	5
Figure 2	Specimen geometry and loading configuration used for determining fracture toughness by the chevron notch method. $\alpha=a/W$; $\alpha_0=a_0/W$; $\alpha_1=a_1/W$.	9
Figure 3	Auger Analysis of a typical ACMC SiC whisker.	14
Figure 4	Bright field TEM micrograph of an American Matrix whisker in a HIP'ed SRBSN matrix composite showing planar faulting.	14
Figure 5	Fracture surface of a chopped carbon fiber reinforced HIP'ed Si_3N_4 .	18
Figure 6	Relative Acoustophoretic Mobility (RAM) vs. pH for Treated American Matrix Inc. SiC whiskers.	19
Figure 7	Effect of the angle between whisker axis (flow direction) and crack plane on the fracture toughness of SiC whisker reinforced Si_3N_4 .	23
Figure 8	Fracture toughness of Si_3N_4 monoliths with elongated grain structures and SiC whisker reinforced Si_3N_4 's as a function of the volume % elongated grain or SiC whiskers with their axis ± 15 degrees to the crack plane.	24
Figure 9	Microstructure of an injection molded 30 v/o Advanced Composite Materials SiC whisker reinforced Si_3N_4 parallel to the flow direction.	25

	<u>Page</u>
Figure 10 Effect of forming process (whisker orientation) on composite fracture toughness.	25
Figure 11 Percent theoretical densities for powder blends after dewaxing and after presintering/nitridation.	28
Figure 12 Percent linear shrinkage for injection molded powder blends from the mold size to the densified size.	28
Figure 13 Comparison of the angle change for as molded and HIP'ed materials. a=as molded, b=HIP'ed Si_3N_4 , c=HIP'ed $\text{Si}_3\text{N}_4/\text{SiC(w)}$, d=HIP'ed SRBSN/ SiC(w) .	29
Figure 14 Percent angle change from the as-molded 90 degree angle to the post densification angle for different powder blends.	29
Figure 15 Interface between a SiC whisker and Si_3N_4 grain as determined by TEM lattice imaging on a composite with an unmodified interface. (Courtesy Reference 32)	31
Figure 16 TEM of a crack in a $\text{SiC-w/Si}_3\text{N}_4$ composite showing debonding and bridging. (Courtesy Reference 32)	32
Figure 17 Bright field electron micrograph showing the silica coating applied by a solution method onto an AMI SiC whisker.	33
Figure 18 TEM micrographs of two whiskers from a batch of as-received carbon coated American Matrix Inc. SiC whiskers.	36
Figure 19 TEM of a carbon coated American Matrix SiC whisker in a HIP'ed Si_3N_4 matrix composite.	35

	<u>Page</u>
Figure 20 "Free" carbon content of American Matrix SiC(w) vs. the resulting composite fracture toughness.	37
Figure 21 The effect of carbon coatings applied at Norton Company on composite fracture toughness.	37
Figure 22 TEM Micrograph of an American Matrix SiC whisker with a carbon debonding layer and a continuous fine SiC particulate overcoating.	39
Figure 23 STEM/TEM analysis of the morphology and composition (Si, C, O) of dual coated SiC whiskers.	40
Figure 24 Crack interactions with BN coated and uncoated SiC grains in HIP'ed Si ₃ N ₄ .	44
Figure 25 Typical Auger electron spectroscopy of BN coatings on AMI SiC whiskers applied by CVD at Norton Company.	45
Figure 26 TEM Micrograph of the BN coating on an AMI SiC whisker applied by CVD at Norton Company.	45
Figure 27 Bright field TEM micrograph of a BN coating/SiC whisker interface in a HIP'ed Si ₃ N ₄ matrix composite. The coating is approximately 50 nm thick in this area.	46
Figure 28 Evidence of debonding in the HIP'ed Si ₃ N ₄ matrix composite reinforced with CVD BN coated AMI SiC whiskers prepared at Norton Company.	46
Figure 29 American Matrix SiC whiskers coated with thin CVD BN coatings at Norton Company. A) ~15nm coating thickness B) ~70 nm coating thickness	47

	<u>Page</u>
Figure 30 Bulk oxygen content of CVD BN coatings vs. calculated coating thickness.	48
Figure 31 Bright field TEM micrograph of an AMI SiC whisker with a BN coating applied by a polymer pyrolysis method.	48
Figure 32 SEM of dual coated Tateho SiC whiskers as applied by CVD.	50
Figure 33 Auger analysis of a dual coated Tateho SiC whisker as-applied by CVD.	50
Figure 34 The composite cylinder model used to calculate residual stress from thermal expansion mismatches.	56
Figure 35 Maximum residual tensile stress as a function of intergranular phase thermal expansion coefficient and thickness.	57
Figure 36 Chevron notch fracture toughness from room temperature to 1370°C.	63
Figure 37 Oxidation resistance of a composite with 20 v/o carbon coated AMI SiC whiskers.	64
Figure 38 Relationship between failure stress, surface crack size, and fracture toughness.	69

MATERIAL DEVELOPMENT IN THE $\text{Si}_3\text{N}_4/\text{SiC(w)}$ SYSTEM
USING GLASS ENCAPSULATED HIP'ING - PHASE II

N. D. Corbin, G. J. Sundberg, K. N. Siebeln,
C. A. Willkens, V. K. Pujari, G. A. Rossi, J. S. Hansen,
C. L. Chang and J. L. Hammarstrom. (Norton Company)

ABSTRACT

This report covers a two-year program to develop fully dense Si_3N_4 matrix SiC whisker composites with enhanced properties over monolithic Si_3N_4 materials. The primary goal was to develop a composite with a fracture toughness $> 10 \text{ MPa}\sqrt{\text{m}}$, capable of operating up to 1400°C . Materials were densified using high pressure glass encapsulated HIP'ing.

Coating methods were developed to apply thin ($<150\text{nm}$) stoichiometric BN layers to SiC whiskers and also to apply a dual coating of SiC over carbon to the whiskers. Fracture toughness of the composites was determined to increase as the quantity of whiskers (or elongated grains) with their axis perpendicular to the crack plane increased. Of the interface compositions evaluated in this effort, carbon was determined to be the most effective for increasing toughness. The highest toughnesses ($6.8\text{--}7.0 \text{ MPa}\sqrt{\text{m}}$) were obtained with uniaxially aligned carbon coated whiskers. There was no evidence of the carbon coating compromising the oxidation resistance of the composites at 1370°C .

Research sponsored by the U.S. Department of Energy, Assistant Secretary for Conservation and Renewable Energy, Office of Transportation Technologies, as part of the Ceramic Technology Project of the Advanced Materials Development Program, under contract DE-AC05-84OR21400 with Martin Marietta Energy Systems, Inc., Work Breakdown Structure Subelement 1.2.2.4.

1.0 INTRODUCTION

In the literature one can find reference to tough (>6.5 MPa $\sqrt{m}$) Si_3N_4 monoliths (including Sialons).^{1,2,3} Tough silicon nitride monoliths are generally prepared by utilizing large quantities of sintering aid (in sialon up to 20 v/o) which promote grain growth and result in thick intergranular regions or by hot pressing which promotes grain growth perpendicular to the applied pressure direction. Neither of these methods are appropriate for preparing the desired high temperature and complex shaped materials required for advanced heat engine applications. High sintering aid contents generally limit use to below 1200°C and hot pressing is limited to simple shapes. Silicon nitrides prepared for use at high temperatures generally contain small quantities of refractory sintering aids resulting in the use of high pressures and/or temperatures to promote densification. The result is a strong high temperature material with low fracture toughness. The low toughness is a result of relatively small, low aspect ratio grains and a small quantity of intergranular phase. One way to improve the fracture toughness of these high temperature materials is to artificially introduce an elongated microstructure. This can be done by incorporating fine SiC whiskers into the matrix.

To properly develop SiC whisker reinforced Si_3N_4 matrix composites the processing/microstructure/property relationships need to be evaluated. For example, key microstructural features in this composite system are listed in Table 1. Many of these features are process interdependent. One example is the SiO_2 content. This will vary depending on starting raw materials and processing procedures. Differences in SiO_2 will effect the intergranular phase composition and content, the thickness of intergranular grain boundaries and triple points, the size and shape of the Si_3N_4 grains which form, and the bonding at the SiC/ Si_3N_4 interface. This project emphasized the processing/microstructure/property relations in this system. Of particular emphasis were; the interface between the SiC whiskers and the Si_3N_4 matrix, whisker orientation, whisker aspect ratio, and intergranular phase composition and content.

Results from Phase I of this program were previously reported.⁴ Highlights from the earlier effort include:

1. The development of a processing method to uniformly blend different SiC whiskers into a Si_3N_4 matrix,
2. Utilizing the ASEA HIP technology for fully densifying composites,
3. Obtaining higher fracture toughnesses by increasing the oxygen content of the composites and,
4. Preparing composites with fracture toughnesses 20-40% higher than monolith materials.

Table 1 Microstructural Features in $\text{Si}_3\text{N}_4/\text{SiC}$ Composites

SiC WHISKER	Si_3N_4 MATRIX	INTERGRANULAR PHASES
DIAMETER*	VOL. FRAC.*	Y_2O_3 *
VOL. FRAC.*	SIZE	VOL. FRAC.
LENGTH	SHAPE	SiO_2
TOTAL#		THICKNESS
SPACING		CRYSTALLINE
ASPECT RATIO		AMORPHOUS
ORIENTATION		DISTRIBUTION

*Processing Independent Variable

The matrix used in this program is a HIP'ed Si_3N_4 with 4 w/o Y_2O_3 . This composition shows much promise for advanced heat engine applications at 1370°C as a monolith material.⁵ Its major drawback is having a fracture toughness of only $5.5 \text{ MPa}\sqrt{\text{m}}$. This program's goal is to improve the fracture toughness of this monolith material to $> 10 \text{ MPa}\sqrt{\text{m}}$ by incorporating SiC whiskers.

This report is divided into four technical sections; Reinforcements, Green Body/Forming, Interface Effects, and Property Progress. Each section contains information on the starting materials, their processing, and evaluation of the densified composites. As such, each section or subsection can be reviewed independently.

2.0 PROCEDURES

MICROSTRUCTURE EVALUATION

Powder and whisker morphology was observed using standard Scanning Electron Microscopy (SEM) techniques. Silicon powder size distributions were determined by a sedimentation technique (Micromeritics Model #5000ET). Surface areas were determined by a BET nitrogen adsorption method (Micromeritics Model Digisorb 2600). Samples were prepared for metallographic examination

by polishing to a 1.0 μ m diamond finish. These surfaces were used for microstructural evaluations and indentation fracture toughness measurements.

Transmission Electron Microscopy (TEM) specimens were prepared by slicing bulk samples with a low speed diamond saw to a thickness of ~0.5mm. The slices were ground to 125 μ m thickness using 20 μ m diamond disks. Three millimeter diameter disks were cut from the slices with an ultrasonic disk cutter. The specimens were then dimple ground with 3.0 μ m diamond past to a thickness of ~10.0 μ m in the center of the specimen. The samples were ion milled with argon gas at 6 kev and a 15° tilt. The samples were analyzed using both TEM (JOEL 200X) and Scanning Transmission Electron Microscopy (STEM) (Vacuum Generators HB5).

CHEMICAL EVALUATIONS

Bulk oxygen and nitrogen analyses were obtained on raw materials and densified products using a combustion/infrared technique (LECO TC-136). Emission spectroscopy (Baird HA12 Spectromet) was used to determine bulk impurities in the starting powders and whiskers. The accuracy of emission spectroscopy is $\pm$ ~5.0% for impurities $>$ 20 ppm and $\pm$ ~30% for impurities $<$ 10 ppm. "Free" carbon content was determined on whiskers and composites (LECO Model DC-12).

Microchemical analysis was determined by energy dispersive analysis (EDS) attachments to electron microscopy apparatus. Scanning Auger Microanalysis (SAM or AUGER) was conducted on whiskers (JOEL model JAMP-10S) and composites (PHI model 660) to determine near surface compositions. Atomic concentrations were determined by normalizing peak heights with their respective sensitivity factors⁵ for a primary beam of 10 Kev. Accuracy is estimated to be $\pm$ 20% in the worse case when several phases are present. Depth profiles were determined on whiskers by removing material with an argon ion gun to expose successive surfaces. The carbon, silicon, oxygen, nitrogen and boron concentrations were monitored as a function of sputtering depth. The depth of penetration depends on the sputtering rate of the species removed. Because of the lack of accurate sputtering rate information on SiC, carbon, and BN, sputtering depths were estimated by using the sputtering rate of SiO₂ (200Å/min). Beam diameter was approximately .3 micron. The technique used for determining the surface composition of individual SiC whiskers by Auger consisted of dispersing the whiskers on a copper grid. This eliminated sample charging problems. The portion of the whiskers suspended into the grid holes away from the copper were analyzed as shown in Figure 1. This allowed sputtering of the whiskers to proceed without contamination from the substrate.

Analysis by ESCA (PHI model #555) was conducted to determine the binding energies of surface constituents. In many instances these energies can be related to chemical species (ex. oxide, nitride, carbide) through the use of reference data.⁷ Semiquantitative chemical analysis of the surface (~20Å depth) was obtained by utilizing integrated peak heights and appropriate sensitivity factors for the elements under evaluation.⁷ The accuracy of the results are expected to be $\pm 10\%$ of the total concentration. For ESCA, analysis is taken from a relatively large sample area (~2mm x 2mm). Therefore, the data is collected from many whisker surfaces.

Phase analysis was conducted by standard x-ray powder diffraction methods using Cu K α radiation. (Philips Model #APD3720).

Figure 1 Set up used for the Auger Analysis of Sic whiskers.

PROPERTY EVALUATIONS

Strength - Flexural strengths at room temperature were determined using 4-point testing configurations. Two test configurations were used depending on material availability. The preferred method used a 3x4mm cross-section specimen with chamfered edges and a surface finished with a 320 grit grinding wheel. The preferred test span was 40x20mm. These test procedures are recommended in the literature.⁸ Specimens with a 3.1x3.0mm cross-section were tested with a 25.4x12.7mm test span if there was a limited availability of material. For high temperature testing, the fixtures had 20x40mm testing spans and the samples had 3x4mm cross-sections. Samples were allowed to equilibrate approximately 10 min. prior to testing at high temperature. Cross-head speed was .51mm/min. for all tests.

Fracture Toughness - Three fracture toughness measurement techniques were utilized. An indentation method⁹ was used for qualitative K_{Ic} determinations on small specimens. Five measurements were made using 10 kg loads with Vickers indents. The resulting crack lengths and impression sizes were measured at 400X. Hardness values taken from the 10 kg indent were used to calculate the respective K_{Ic} .

The second technique was a controlled flaw method¹⁰ which was used when larger quantities of material were available. For this method, flexure specimens having either of the configurations described for room temperature strength analysis were used. One 10 kg vickers indentation was inserted onto the tensile side of the specimen through a drop of oil. The oil (#M3000, Stephens Scientific) was used to eliminate the influence of laboratory humidity. Three to five specimens were tested and averaged for K_{Ic} .

In the third technique room and elevated temperature fracture toughness measurements were conducted using a chevron notch method. A four point bending configuration was selected because it allows for easier specimen alignment since a constant moment is applied between the inner load points. Fracture toughness is calculated by:

(equation #1)

$$K_{Ic} = P_{max} \left[\frac{Y'}{B W^5} \right]$$

where P_{max} is the maximum test load, B is the specimen width, W is the specimen thickness and Y' is dependent on the specimen geometry and the manner of specimen loading. The value of Y' can be calculated using either the straight through crack assumption (STCA)¹¹:

(equation #2)

$$Y^* = (2.92 + 4.52\alpha_0 + 10.14\alpha_0^2) \left[\frac{S_2 - S_2}{W} \right] \left[\frac{(\alpha_1 - \alpha_0)}{(1 - \alpha_0)} \right]^{1/2}$$

or the Bluhm Slice Model¹²:

(equation #3)

$$Y^* = (3.08 + 5.00\alpha_0 + 8.33\alpha_0^2) \left[\frac{S_1 - S_2}{W} \right] \left[1.0 + .007 \left[\frac{S_1 S_2}{W^2} \right]^{1/2} \left[\frac{\alpha_1 - \alpha_0}{1 - \alpha_0} \right] \right]$$

where the variables are presented in Fig. 2.

Initial data was collected on a Si_3N_4 monolith with known fracture toughness (NC-132) to qualify the test procedure for using bars with 3mm x 4mm cross-sections. The chevron notch geometry had an $\alpha_0 = 0.55$ and $\alpha_1 = 1.0$. The cross head speed was 0.012 mm/min. Tests were performed on an Instron 4206 unit. A SiC test fixture with a 5mm top span and 40mm lower span was used. Specimens with a 40.9° notch resulted in load/deflection curves exhibiting non-linear behavior and noncatastrophic failure. This failure mode is required for an accurate K_{Ic} determination. The resulting fracture toughness was $4.7 \pm .1 \text{ MPa}\sqrt{\text{m}}$ which is in excellent agreement with literature values taken by the chevron notch method ($4.7 \text{ MPa}\sqrt{\text{m}}$).¹³

As the program evolved the chevron test method was modified to a two-step process. Initially a slow cross head speed of .005mm/min was used to precrack the specimen followed by a faster cross head speed of 0.5mm/min, for fracture. This two step procedure was recommended in the literature because it induces subcritical precracking followed by stable crack growth and fracture.¹⁴ Comparison of the results obtained using the single and double cross head speed techniques were similar for a Si_3N_4 monolith ($\text{Si}_3\text{N}_4 + 4 \text{ w/o } \text{Y}_2\text{O}_3$). The advantage of the two-step process is that a greater number of valid toughness tests are performed than with the single speed technique.

Room Temperature Toughness Comparison - Because the major emphasis of this program was to improve fracture toughness we conducted a comparison of various test methods for determining K_{Ic} at room temperature. This comparison consisted of literature data, analyses at Norton Company, and analyses conducted at other facilities. A hot pressed Si_3N_4 with an MgO sintering aid (NC-132) was selected along with a SiC whisker reinforced Si_3N_4 . This task was initiated to determine the influence of test method on fracture toughness values. As shown in Table 2 there is a significant variability in toughness depending on the test method.¹⁵⁻²¹ This data demonstrates that great care should be exercised in comparing fracture toughness values from different analysis methods. In lieu of a standard testing procedure, it is recommended that the fracture toughness of a readily available material which has been extensively evaluated in the literature (for example NC-132) be tested and reported as a normalization factor when determining the fracture toughness of new materials. For all our fracture toughness measurements we include data obtained on NC-132 as a normalization factor.

Stress Rupture and Oxidation - High temperature stress rupture was conducted in air using 3mmx4mm bars and 20x40mm upper and lower spans. Testing conditions are similar to that described by Quinn.^{22,23}

Selected materials were oxidized at 1370°C for various times and evaluated at room temperature for strength retention.

COMPOSITE FABRICATION

The matrix composition used in this program is Si_3N_4 with 4 w/o Y_2O_3 and native SiO_2 associated with the precursor powders unless otherwise noted. Twenty and thirty volume percent whisker loadings were investigated. Two processing routes were investigated. One utilized Si_3N_4 powder whereas the other used silicon powder. In the first case, high alpha Si_3N_4 powder was wet blended with the sintering aids and SiC whiskers. After drying, this blend was formed by cold isostatic pressing or blended with binders for extrusion or injection molding. If blended with binders they were removed prior to densification. Materials were densified by Hot Isostatic Pressing (HIP) using the ASEA process.^{23b} Full density was routinely obtained. Materials processed in this fashion are noted as HIP'ed Si_3N_4 in this report. In the second case, silicon powder was wet blended with sintering aids and SiC whiskers. After drying, this blend was formed by cold isostatic pressing or blended with binders for extrusion or injection molding. If blended with binders they were removed prior to further processing. These blends were nitrided after

Figure 2 Specimen geometry and loading configuration used for determining fracture toughness by the chevron notch method. $\alpha = a/W$; $\alpha_0 = a_0/W$; $\alpha_1 = a_1/W$.

forming to convert the silicon powder to Si_3N_4 . After nitridation, the materials were HIP'ed using the ASEA process. Full density was routinely obtained. Materials processing in this fashion are marked as HIP'ed SRBSN in this report. For both processes the resulting material contains 4 wt % Y_2O_3 with Si_3N_4 in the matrix. As further discussed in this report, both processes are compared as to their advantages and disadvantages for preparing Si_3N_4 matrix composites.

Table 2 Comparison of room temperature fracture toughness as determined by different methods

Method (Reference)	Monolith $\text{Si}_3\text{N}_4^{(A)}$ NC-132 (MPa $\sqrt{\text{m}}$)	Composite $\text{Si}_3\text{N}_4/\text{SiC}^{(B)}$ 7XO14 (MPa $\sqrt{\text{m}}$)
Indentation methods of Anstis		
* in reference (9)	4.0	--
* Norton determination	3.5	4.2
Control flaw method of Chantikul		
* in reference (10)	5.0	--
* Norton determination	4.6	5.2
* ORNL determination (15)	5.0	--
Control flaw method of Cook (16)		
* ORNL determination (15)	6.3	--
Control flaw method by flaw size		
* ORNL determination (15)	4.6	--
Chevron Notch methods		
* NASA determination (17)	--	5.41
* Norton determination	4.3	4.6
* in reference (13)	4.7	--
Double Cantilever beam		
* Case Western determination (18)	--	6.4
* in reference (19)	4.0	--
Double torsion		
* Norton determination (4)	6.0	--
Bridge indentation method (20)	3.9	--
* Worcester Polytechnic determination (21)		

(A) NC132 is a hot pressed Si_3N_4 with ~1.0 wt % MgO

(B) 7XO14 is a HIP'ed composite with 30 v/o SiC whiskers in a matrix of Si_3N_4 + 4 w/o Y_2O_3 .

3.0 REINFORCEMENTS

WHISKER SOURCES

Silicon Carbide whiskers from various manufacturers were evaluated during the course of this contract. Bulk chemical analysis of the as-received SiC whiskers were performed. The presence of strength limiting SiC particulate grit associated with the whiskers was readily determined by incorporating the whiskers into a Si_3N_4 matrix and determining room temperature strength. Selective evaluations of whisker surface chemistry, morphology, and dispersion behavior were also performed.

Table 3 lists the impurity contents by emission spectroscopy for various whisker sources evaluated in this program. Impurity levels of Fe, Al and Ca are relatively high. From the Table one can observe the catalyst or precursor for whisker growth used by the different manufacturers for developing whisker morphologies. For example, Tokai Carbon uses titanium, carbon and aluminum whereas American Matrix uses boron, magnesium and calcium. High levels of aluminum and calcium may degrade high temperature strength and stress-rupture performance of the composite.

The surface chemistry of various whisker sources were evaluated by ESCA (Table 4). Several of the materials were carbon coated by the manufacturer. Although not all materials were intentionally carbon coated it appears they are all carbon rich ($\text{C}:\text{Si} > 1.0$). Surface composition is expected to influence dispersion behavior and possibly composite fracture toughness.

Data obtained from Auger analysis shows a variation in whisker surface composition from whisker to whisker within the same lot. Examples of this variation are given in Table 5. Data from individual Advanced Composite Materials whiskers consistently show 100% carbon on their surfaces. Figure 3 is an Auger analysis of an ACMC whisker. It should be noted that ESCA and Auger data are not identical. The reason for this is unclear but may be related to electron beam heating in Auger which may cause desorption of hydrated species. Also the spacial resolution of Auger (0.3 μm diameter) is much smaller than ESCA ($\sim 3\text{mm}^2$).

Table 6 compares the fracture toughness of composites reinforced with different SiC(w). An unreinforced monolith and 20% v/o Tateho T44 composite were also made for baseline comparison. Although not a significant improvement, there was an encouraging trend of higher toughness values for both the Tokai Grade 3, and the ACMC material relative to the unreinforced monolith.

American Matrix SiC whiskers (rec. 7/87) were evaluated by TEM to determine their structure. Evaluations on Tateho, Advanced Composite Materials, and Huber whiskers were reported earlier.⁴ The whiskers were incorporated into a dense Si_3N_4 matrix for evaluation. They contain many planar faults and twins perpendicular to the growth axis. A longitudinal view of

Table 3 Bulk chemical analysis of SiC whiskers

Source	Grade	Date rec.	O	N	Free C	Fe	Ca	Al	Mg	Na	K	Ti	Cr	B	Ni	Co	Mn
Tateho	T44	11/86	0.4	0.9	0.38	340	810	3100	84						30		
Tateho	U.85	11/87	0.51	0.61	0.24	730	713	300	350	30	46	22	240	16	100		
Huber	XPHZ	5/87	0.1	0.9	6.16	1000	11	10	45	3	17	4	270	11	670		
Shin-Etsu		11/87	4.21	0.1	0.43	1.29	492	10	68	29	49	109	30	10	12		
Tokai		7/87	0.24	0.66	0.32	63	26	46	34	4	18	149	67	10	9		
Tokai		7/86			0.25	66	24	39	33	4	0	0	64	0	10	243	
Tokai	Grade 3	12/87	0.27	0.87	0.30	143	593	300	39	13	18	124	48	10	10		
Tokai	C-coated	12/87	0.67	0.81	1.43	200	847	300	57	10	15	132	87	13	19		
Tokai	300C	9/88	0.55		1.24	181	431	1500	9					10	9		
Tokai	400	9/88	0.17		0.170	99	60	1050	11					10	11		
ACMC		1/88	1.26	3.06	0.26	149	1414	1741	349	40	97	8	24	<10	7		722
AMI	G3	7/87	0.77	0.05	0.09	180	606	100	610	99	22	8	100	1000	180		
AMI	G4	2/88	1.48	0.74	0.09	170	730	470	390	18	16	19	100	1000	180		
AMI	C-coated	11/87	1.19	0.08	1.36	254	1046	251	281	5	12	18	92	1000	135		
AMI	C-coated	8/88	1.00	1.77	0.40	151	814	543	576	5	7	9	95	1000	169		
AMI	10060105	11/88	1.08	0.07	0.09	161	580	325	302	27	22	8	108	1000	161		
AMI	HFTreat	11/88	0.88	0.07	0.11	22	823	325	413	19	18	5	39	1000	22		

* Cu, V, Li all < 5ppm

Table 4 ESCA data on SiC whiskers

	Advanced ⁽¹⁾ Composite Materials	American ⁽²⁾ Matrix	Tateho ⁽³⁾ 0.8 um	Tateho ⁽⁴⁾ T44	AMI ⁽⁵⁾ C-coated	Tokai ⁽⁶⁾ 1.0 um	Tokai ⁽⁷⁾ C-coated
Oxygen (A/O)	41.5	45.5	19.6	24.0	22.9	17.8	12.6
Carbon (A/O)	32.7	31.4	49.7	49.1	48.4	46.0	76.6
Silicon (A/O)	24.9	22.0	28.2	26.8	20.1	34.1	14.4
Other (A/O)	0.6	0.9	2.3	--	8.2	1.9	1.1

- (1) Advanced Composite Materials, Rec. 1/88
(2) American Matrix, Generation 4, Rec. 2/88
(3) Tateho 0.8 um, SCW #1-S105, Lot 1020, Rec. 11/87
(4) Tateho T44, SCW #1-S105, Lot S178, Rec. 11/86
(5) American Matrix, Carbon Coated Whisker, Rec. 8/88
(6) Tokai Carbon, 1.0um Whisker, Grade 400, Rec. 9/88
(7) Tokai Carbon, Carbon Coated Whisker, Grade 300c, Rec. 9/88

Table 5 Auger analysis of individual SiC whiskers

	American Matrix ⁽¹⁾			Tateho ⁽²⁾			ACMC ⁽³⁾		
	A	B	C	A	B	C	A	B	C
Oxygen (A/O)	54.9	13.8	34.4	-	12.5	-	-	-	-
Carbon (A/O)	33.9	57.4	35.2	54.5	70.9	100	100	100	100
Silicon (A/O)	11.1	28.8	30.4	45.5	16.6	-	-	-	-

(1) American Matrix, Generation 4, Rec. 2/88

(2) Tateho 0.8 um, SCW #1-S-105, Lot 1020, Rec. 11/87

(3) Advanced Composite Materials, Rec. 1/88

Table 6 Composite toughness as a result of whisker source

<u>Whisker*</u>	(MPa√m)	<u>Specimen Code</u>
	<u>Controlled Flaw Toughness</u>	
Monolith	4.6 ± 0.1	2139-38
Tateho T44 ^(h)	5.1 ± 0.1	2138-38
Tokai - Grade 3 ^(a)	5.4 ± 0.2	2134-38
Shin Etsu ^(b)	4.9 ± 0.2	2137-38
ACM ^(c)	5.4 ± 0.2	2132-38
Kobe ^(d)	4.9 ± 0.2	2100-30
Nikkei ^(e)	4.4 ± 0.4	2104-30
American Matrix ^(f)	5.0 ± 0.2	2101-30

a - Tokai Carbon Co., Tokyo, Japan

b - Shin-Etsu Chemical Co., Japan

c - Advanced Composite Materials (formerly Arco) Greer, SC

d - Kobe Steel, Kobe, Japan

e - Nikkei Techno Research Co., Shinozuoko, Japan

f - American Matrix Inc., TN, Rec 7/87

h - Tateho Chemical Ind. Co., JAPAN

* - Composites made with 20 v/o SiC whiskers, CIP/HIP

Figure 3 Auger Analysis of a typical ACMC SiC whisker.

Figure 4 Bright field TEM micrograph of an American Matrix whisker in a HIP'ed SRBSN matrix composite showing planar faulting.

an American Matrix whisker is presented in Figure 4. The core of the whisker contained many small cavities. The cavities have been attributed to gas bubble evolution during whisker growth.²⁴ Partially crystalline impurity bearing inclusions have also been identified in the whisker cores.^{24b} The whiskers appear similar in structure to materials prepared from rice hull processes^{4,24,24b} and were dissimilar to the previously reported structure of the Huber product.⁴ The American Matrix whiskers were large by comparison. SEM photomicrographs show them to have diameters between 1-3 micron which is in agreement with the product literature.

ASPECT RATIO

The effect of whisker aspect ratio on toughness was evaluated by utilizing different diameter whiskers. These were either supplied from the manufacturer or classified at Norton Company into different size classes. Fine particle classification techniques were utilized to separate Huber SiC whiskers into a coarse fraction ($d_{50} \sim 1.5 \mu\text{m}$) and a fine fraction ($d_{50} \sim 0.4 \mu\text{m}$).⁴ These were incorporated into Si_3N_4 matrix composites at a 20 v/o loading. The tiles were formed by cold isostatic pressing with the intent of achieving a random whisker distribution. The controlled flaw fracture toughness of composites made with the fine and coarse whiskers were not significantly different. (Table 7)

Tateho SiC whiskers of different diameters were also been evaluated under similar processing conditions (isotropic orientation, unmodified interface, HIP'ed SRBSN route) with no significant influence of mean whisker diameter between 0.4 and 0.8 micron on toughness. (Table 7)

The final experiment in this evaluation used carbon coated SiC whiskers and injection molding to orient the whiskers approximately parallel to bar length. Toughness was determined perpendicular to the whisker orientation. Fracture toughness results are reported in Table 7. There were no significant differences between the two diameter Kobe-Kenebo products.

CARBON FIBER

Carbon fiber was used as a model material for reinforcing Si_3N_4 . This fiber was selected because it can be obtained in larger diameters than the SiC(w) and it has a documented tensile strengths above 1.0 GPa. It has been demonstrated in the literature that fully dense Si_3N_4 matrix carbon fiber composites can be prepared using the ASEA HIP process.²⁵ Our composite was prepared by blending 30% chopped carbon fiber (Union Carbide P55S, 1.8 GPa tensile strength) having a diameter of 11.0 μm with a Si_3N_4 matrix containing 5 wt% MgO . After blending, a sample was removed and analyzed by optical microscopy to estimate fiber length. Fiber length was ~ 50 μm . The composite blend was uniaxially pressed into tiles ~64x64x10mm and HIP'ed to greater than 99% of theoretical density using the ASEA process. The dense material was machined into chevron notch specimens and tested for fracture toughness at room temperature. A toughness of 8.2 $\text{MPa}\sqrt{\text{m}}$ was obtained. Table 8 compares this composite with a Si_3N_4 monolith evaluated in the same manner. The fracture surface of this material is shown in Figure 5. There is much evidence of pullout and debonding. These results demonstrate that significant improvements in fracture toughness for Si_3N_4 can be obtained with an appropriate reinforcement.

DISPERSION BEHAVIOR

American Matrix SiC whiskers were evaluated to determine the possibility of leaching off impurities by soaking in acidic solutions. The analysis was conducted by determining relative acoustophoretic mobility (RAM) (Pen Kem Inc. Model 700, comparable to zeta potential analysis). Results are illustrated in Figure 6. Figure 6a shows that in deionized water at a pH~6 the as-received whiskers possess a negative surface charge. An acid titration decreases the negative charge until the isoelectric point (IEP) of ~ 3.2 is reached. Below this point, the whiskers become positively charged. This behavior is similar to that for SiO_2 , which has an IEP of 2.0. The reverse (base) titration shows a marked hysteresis when returning to a pH of ~ 6.0. This phenomenon is better illustrated in Figure 6b where the whiskers were soaked at low pH overnight. Upon reverse titration the surface charge does not change and remains positive even at high pH. This procedure has been shown to dissolve many surface impurities from the whiskers. Table 9 lists the concentration of ions present in the effluent from HNO_3 washing of these SiC whiskers. Our experience with SiC powders has indicated that the presence of Ca^{++} and Mg^{++} ions (hydroxides having IEPs ~ 12.5) result in RAM behavior characteristic of the data in Figures 6a and 6b. Thus, these ionic impurities control the whisker dispersion behavior and the impurities can be particularly removed by soaking whiskers in HNO_3 .

Table 7 Effect of whisker diameter on composite fracture toughness

Whisker Source	Diameter ⁽¹⁾ (μm)	Loading (vol %)	Whisker Orientation	Whisker Surface	Matrix ⁽²⁾	Toughness ⁽³⁾ $\text{MPa}\sqrt{\text{m}}$	Specimen Code
Tateho	0.4	20	random	uncoated	SRBSN	5.1 $\pm$.1	2138-38
Tateho	0.4	30	random	uncoated	SRBSN	5.2 $\pm$.1	2122-32
Tateho	0.6	20	random	uncoated	SRBSN	5.4 $\pm$.3	2073-22
Tateho	0.8	30	random	uncoated	SRBSN	4.9 $\pm$.1	2176-44
Kobe-Kanebo	1.2 $\pm$ 0.7	30	uniaxial	carbon	Si_3N_4	5.4 $\pm$.2	2273-74
Kobe-Kanebo	2.9 $\pm$ 1.0	30	uniaxial	carbon	Si_3N_4	5.8 $\pm$.2	2272-74
Huber ⁽⁴⁾	1.5 μm	20	random	uncoated	SRBSN	5.0 $\pm$.3	2131-38
Huber	0.5 μm	20	random	uncoated	SRBSN	4.9 $\pm$.3	2131-38

(1) As supplied by manufacturer

(2) Si_3N_4 = processing using Si_3N_4 powder prior to HIP'ing
 SRBSN = processing with silicon powder followed by reaction-bonding prior to HIP'ing

(3) By Chantikul control flow method

(4) This whisker product was separated into two size classes at Norton Company

Table 8 Fracture Toughness comparison between a carbon fiber reinforced Si_3N_4 and a Si_3N_4 Monolith

Material	K_{Ic} ($\text{MPa}\sqrt{\text{m}}$) ^(A)	Sample Code
Si_3N_4 monolith	4.3 $\pm$.1	NC-132
30 v/o C-fiber reinforced Si_3N_4	8.2 $\pm$.6	2191-48

(A) Chevron notch testing method: 3x4 mm cross section

Composite $S_1 = 25.7$ mm, $S_2 = 5$ mm, 30° notch angle

Monolith $S_1 = 40.0$ mm, $S_2 = 5$ mm, 41° notch angle

Figure 5 Fracture surface of a chopped carbon fiber reinforced HIP'ed Si_3N_4 .

Table 9 Concentration of ions detected by atomic absorption spectrophotometry in effluent from acid soaking American Matrix SiC whiskers

Ca	420 ppm
Mg	124 ppm
Al	180 ppm
Fe	45 ppm
Cr	10 ppm
Ni	100 ppm
B	Not Detected

a) As received AMI whiskers,
Acid-Base Titration

b) As received AMI whiskers
Acid Titration and 24 hr
acid soak followed by base
Titration

Figure 6 Relative Acoustophoretic Mobility (RAM) vs. pH for Treated American Matrix Inc. SiC whiskers.

4.0 GREEN BODY/FORMING

In the research reported in this section we evaluate the effect of whisker orientation on fracture toughness, processing routes to minimize distortion during densification, and the effect of precursor purity on properties. The topics will be discussed separately.

PURITY EFFECTS

Our experience has shown that the impurity content of Si_3N_4 materials has a significant effect on high temperature ($>1300^\circ\text{C}$) mechanical properties. As compared to Si_3N_4 the SiC whiskers contain relatively high impurity contents. A study was initiated to determine if the whisker impurities are affecting high temperature properties.

This study compared a standard and high purity matrix, a standard purity SiC whisker (Tateho T44), a high purity SiC whisker (Tokai) and a high purity SiC particulate (see Table 10). The impurities of particular interest are iron, calcium, and aluminum. It should be noted that there is considerable lot-to-lot variation in the purity of SiC whiskers and we have chosen specific lots to conduct this evaluation. The particulate possessed a 2μ average particle size.

The mechanical property results are compared in Table 11. The composite 1370°C fast fracture strength was more influenced by the purity of the matrix than the reinforcement. When the high purity matrix was used a strength at 1370°C of 544 MPa (~ 80 ksi) was obtained. The standard matrix produced composites of 421 and 407 MPa (~ 60 ksi) which are significantly lower in strength. This lower strength occurs when either standard purity or high purity reinforcements are utilized. A similar trend is observed when comparing the high purity monolith to the standard grade monolith. The importance of the matrix purity on composite properties is most likely a result of its prominence (70-80 w/o) in the composite. It should be noted that the monolith strengths are higher than the composite with the corresponding matrix (634 vs. 544, high purity and 517 vs. 421 and 407 Std. purity). Therefore, the incorporation of SiC whiskers lowers the elevated temperature strengths.

The fracture toughness of the composite made with SiC whiskers was 20% higher than that of the composites made with SiC particulate (5.3 vs. 4.4). This is consistent with the work of Faber and Evans showing whisker morphologies to be more effective than particulates in toughening.²⁶ It is worth noting that the fracture toughness of the monolith is improved when the higher purity matrix precursors are used.

Table 10 Impurity contents of SiC and Silicon materials used for purity study

Material		Fe	Ca	Al
Tateho T44	SiC(w) (Rec. 11/86)	340	810	3100
Tokai	SiC(w) (Rec. 7/87)	63	26	46
Nissorundum	SiC(p) GMF5H2	17	1	30
High Purity Silicon	--	90	18	30
Std. Purity Silicon	--	260	33	130

Table 11 Properties of materials evaluated to determine the effect of impurities

Matrix ^(C)	Reinforcement	Toughness ^(A)	1370°C Strength ^(B)	Specimen Code
High Purity	--	5.4±.2	92±5 (634±34)	2154M-43
Standard	--	4.2±.2	75±9 (517±62)	3X015
High Purity	20% Standard (Tateho T44)	5.3±.3	79±4 (544±28)	2154C-43
Standard	30% Standard (Tateho T44)	5.2±.1	61±3 (421±21)	7X014
Standard	30% High Purity (Tokai 7/87)	5.3±.1	59±2 (407±14)	2206-51
Standard	30% High Purity (SiC Powder)	4.4±.2	61±1 (421±7)	2207-51

(A) Control flaw method of Chantikul (MPa√m)

(B) MIL-STD 1942 3x4mm in Ksi (MPa)

(C) HIP SRBSN (4% V₂O₃) matrix

WHISKER ORIENTATION

The influence of whisker orientation on fracture toughness was determined by using different forming processes to align the whiskers. For random orientation composites are formed by die pressing into ~76x76x6mm tiles and cold isostatically pressing. For uniaxial alignment the composites were injection molded into MOR test specimens, or extruded into rectangular bars.

We have reported the details of the analysis used to determine the effect of orientation on toughness in the literature.²⁷ As shown in Figure 7, fracture toughness is maximized when the whisker axes are 90 degrees to the crack plane for a composite with approximately uniaxially aligned whiskers. If one uses a range for optimum orientation for toughness improvements e.g. 90 ± 15 degrees), knows the quantity of whiskers in the composite (volume % loading) and knows the orientation of whiskers in the composite (random, planar, uniaxial), then the quantity of whiskers in the optimum orientation can be calculated from simple geometry. This is done in Table 12 for the case of random whisker alignment in a composite with different whisker loadings and different ranges for optimum orientation. As shown, the quantity of whiskers perpendicular to the crack plane is much lower than the whisker loading in the composite. For example, in a composite with 40 v/o whisker randomly oriented only 1.4 volume percent will be 90 ± 15 degrees to the optimum toughness orientation for a planar crack. The influence of the quantity of whiskers (or elongated grains) perpendicular to the crack plane on fracture toughness has been experimentally determined and reported elsewhere.²⁸ Figure 8 reveals that fracture toughness increases with increasing whisker (or elongated grain) content perpendicular to the crack plane. Considering this, major increases in the fracture toughness of composites with random whisker orientation will be difficult and may need toughening mechanisms in addition to whisker bridging for improving fracture toughness. It is anticipated that mechanisms such as ligament formations as observed in coarse grained alumina²⁹ would be beneficial for Si_3N_4 based composite systems.

A direct comparison was made of microstructures produced by injection molding and extruding using 30% ACMC $\text{SiC-w/Si}_3\text{N}_4$ composites. Both produce highly oriented microstructures. (Figure 9) The alignment of whiskers in the injection molded bars were more uniform through the cross-section as compared to the extruded rods. Extruded bars showed islands of swirled regions in the cross-section. This is explained by the higher back-pressure and stepped changes in cross-section (velocity) that occur for injection molding, which tend to force a more

uniform whisker alignment. These materials were used to study the effect of whisker orientation on fracture toughness for the 30% ACMC/ Si_3N_4 material. Figure 10 shows the effect of orientation on toughness as measured using the controlled flaw technique. The injection molded bars had a value of $6.9 \text{ MPa}\sqrt{\text{m}}$, our highest value obtained using the controlled flaw technique.

Figure 7 Effect of the angle between whisker axis (flow direction) and crack plane on the fracture toughness of SiC whisker reinforced Si_3N_4 .

Table 12 Whiskers available for bridging in composites with randomly oriented whiskers

Optimum Toughness Range	Whisker Loading in Composite		
	100 v/o SiC	40 v/o SiC	20 v/o SiC
90 ± 15 degrees	3.4% v/o	1.4 v/o	0.7 v/o
90 ± 30 degrees	13.4% v/o	5.4 v/o	2.7 v/o
90 ± 45 degrees	29.3% v/o	11.7 v/o	5.9 v/o

Figure 8 Fracture toughness of Si_3N_4 monoliths with elongated grain structures and SiC whisker reinforced Si_3N_4 's as a function of the volume % elongated grain or SiC whiskers with their axis ± 15 degrees to the crack plane.

Figure 9 Microstructure of an injection molded 30 v/o Advanced Composite Materials SiC whisker reinforced Si_3N_4 parallel to the flow direction.

Figure 10 Effect of forming process (whisker orientation) on composite fracture toughness.

DISTORTION

It has been reported that the use of whiskers in a composite mixture can result in distorted specimens after densification.^{30,31} To address this problem we conducted an investigation to maximize the composite pre-HIP green density which is expected to minimize differential shrinkage and hence distortion. A variety of approaches to maximize pre-HIP density were evaluated including; optimizing the matrix packing density, modifying the whisker size (length), and utilizing an SRBSN approach. Use of an SRBSN matrix can result in lower shrinkage during densification by HIP as compared to a Si_3N_4 powder matrix. This is because on nitriding the silicon powder undergoes a 22% volume increase with no change in the original compact dimensions.

For this investigation a monolith was prepared from Si_3N_4 powder, a composite was prepared using Si_3N_4 powder as the matrix precursor, and a composite was prepared via an SRBSN approach. For the SRBSN approach silicon was blended with the SiC whiskers then nitrided. Both composites were prepared such that the final dense (after HIP) materials contain 20 v/o American Matrix SiC whiskers with a 4 w/o Y_2O_3 sintering aid in the matrix. All three materials were specifically selected so they result in optimum green body packing. The shrinkage/distortion results are therefore representative of best-case scenarios. For this study materials were injection molded into ~ 6 x 8 x 65mm bars and "L" shaped rods. Molding was performed such that material flow was parallel to the long axis of the shape. The result is an approximately uniaxial whisker alignment parallel to the axis of the parts. Specimens were measured after each stage of processing namely; molding, dewaxing, presinter/nitridation and HIP'ing. Length, width, thickness, and bulk density measurements were determined for the bars. For the "L" shaped rods, the intersection angle was measured with reference to the starting angle of ~ 90°.

In Figure 11 the volume percent ceramic for the three materials are compared after the dewaxing and presinter/nitridation steps. There is a very small increase (~ 1.0 v/o) for the Si_3N_4 powder based materials after presinter due to a slight increase in bulk density. A significant increase is observed when the silicon matrix is nitrided to Si_3N_4 for the SRBSN composite material (6.8 v/o).

Figure 12 compares the percent linear shrinkage for the length, width, and the thickness of the bars from the mold size to the final HIP size. The shrinkages measured after dewaxing and presinter/nitridation for all the three materials are relatively small as compared to the shrinkage measured after HIP'ing. Prior to HIP'ing, the shrinkages were uniform in all the three dimensions. After HIP'ing, as evidenced in Figure 12, the monolith shows a fairly uniform shrinkage in all three

dimensions. On the other hand, the two HIP'ed composite materials have a much smaller shrinkage in length (~ 10%) as compared to their width and thickness (range 15-20%). The smaller length shrinkage is attributed to preferential orientation of the whiskers. It is also interesting to note the fairly uniform shrinkages along width and thickness dimensions for both composite materials. The SRBSN based composite, as expected, measures smaller shrinkages in all three dimensions as compared to the other two compositions. When compared to the Si_3N_4 matrix composite the SRBSN material has a 25% reduction in the amount of shrinkage associated with it in the thickness dimensions (20% vs. 15%). In spite of non-uniform shrinkage (length < width and thickness) the composites are no more distorted than the monolith. This is because the one dimensional whisker orientation (uniaxial alignment) results in the three dimensions shrinking independently and uniformly.

For the L-shaped specimen, whiskers are oriented roughly parallel to the length of the two legs. However, at the intersecting joint (knee) the whisker orientation will change as a result of the component design. Based on the observation from our analysis of bars, one would expect no distortion in the two legs of the L-shaped piece. This is exactly the case observed. As observed in Figure 13 each leg of the L-shaped piece remains straight after HIP'ing. The change in angle (from 90° to acute) is caused by the non-uniform shrinkage of the knee. The cross-section of the knee is not free to shrink independently of the two legs due to differential whisker orientation. As shown in Figure 14, the use of an SRBSN processing route reduces the percent change in angle observed for the Si_3N_4 matrix composite. The distortion in the HIP'ed SRBSN composite is 45% of that observed for the HIP'ed Si_3N_4 material. This is a direct result of the reduced shrinkage needed to HIP a part to full density when the SRBSN route is used as observed in Figures 11 and 12.

In summary;

- i) For a one dimensional shape (bar, rod) distortion will not be expected provided all the whiskers are oriented preferentially in one dimension irrespective of non-uniform shrinkage.
- ii) Differential whisker orientation at an intersecting cross-section of a part will result in part distortion.
- iii) The results suggest that specific shapes from whisker reinforced composites can be made provided that the whiskers in each section are aligned in one direction and that no differential orientation exists at any intersecting cross-sections in the part. This can be achieved by joining individual dense composite segments where each segment contains aligned whiskers.

Figure 11 Percent theoretical densities for powder blends after dewaxing and after presintering/nitridation.

Figure 12 Percent linear shrinkage for injection molded powder blends from the mold size to the densified size.

Figure 13 Comparison of the angle change for as molded and HIP'ed materials. a=as molded, b=HIP'ed Si_3N_4 , c=HIP'ed $\text{Si}_3\text{N}_4/\text{SiC}(w)$, d=HIP'ed SRBSN/ $\text{SiC}(w)$.

Figure 14 Percent angle change from the as-molded 90 degree angle to the post densification angle for different powder blends.

5.0 INTERFACE EFFECTS

OXIDE INTERFACES

Materials under development in this program use Y_2O_3 and SiO_2 as sintering aids. The SiO_2 is on the surfaces of the starting Si, Si_3N_4 and SiC materials. During densification and subsequent cooling the sintering aids segregate to Si_3N_4/Si_3N_4 grain boundaries, triple points, and the Si_3N_4/SiC whisker interface. Upon cooling the intergranular phase can either crystallize or remain amorphous at the grain boundaries. In Figure 15 an amorphous interface ~2 nm thick was observed between a SiC whisker and a Si_3N_4 grain.³² Fracture toughness of composite materials with this characteristic tend to be ~5.0 MPa $\sqrt{m}$. TEM evaluations on these materials have shown that debonding and crack bridging can occur (Figure 16) even with the thin glassy interface present.³²

Previous results have shown fracture toughness to be effected by the bulk oxygen content of composites.⁴ As a result we conducted a study to determine the effect of sintering aid composition ($Y_2O_3:SiO_2$) and quantity ($Y_2O_3 + SiO_2$) on composite fracture toughness. Table 13 contains the fracture toughness results from this study. An improvement of 15% was obtained over standard materials by modifying the sintering aid.

An attempt to obtain a local increase of SiO_2 at the whisker/matrix interface was pursued to further augment the toughening effect. Silica was applied to SiC whiskers by a solution coating method. American Matrix Inc. SiC whiskers were used for this study. The coating applied by a solution/precipitation method was examined by TEM. Bright field TEM of the coated whisker exhibited a microcrystalline, continuous coating between 10 nm to 20 nm thick (Figure 17). A Si_3N_4 (4 wt % Y_2O_3) matrix was reinforced with 20 volume % of these whiskers. The composite was injection molded to uniaxially align the whiskers and HIP'ed to full density using the ASEA process. The controlled flaw fracture toughness for this material was 6.8 MPa $\sqrt{m}$ which is a significant improvement over more typical materials (~ 5.5 MPa $\sqrt{m}$). TEM analysis of the SiC whisker/matrix interface revealed that the coating was not discernible on the whiskers after densification, therefore it cannot explain the toughness increase. The coating may have dissolved into the glassy phase. Auger analysis of this sample revealed that a carbon rich surface originally on the whisker prior to coating may be the cause for the improvement. This is further discussed in the section "Auger analysis of Interfaces" in this report.

Table 14 lists the fracture toughness of composites modified with oxides to change the $\text{Si}_3\text{N}_4/\text{SiC}$ interface chemistry. This effort was conducted to alter the interface properties which govern debonding, such as thermal expansion, elastic modulus, and shear strength. Two approaches were investigated, application of the oxide to the whisker surface and changing the sintering aid composition. The toughness data does not exhibit a significant improvement as a result of these oxide interfaces. A B_2O_3 coating was investigated to determine how its presence in BN coatings would effect K_{Ic} . The results show B_2O_3 will significantly reduce toughness.

Figure 15 Interface between a SiC whisker and Si_3N_4 grain as determined by TEM lattice imaging on a composite with an unmodified interface.
(Courtesy Reference 32)

Figure 16 TEM of a crack in a SiC-w/Si₃N₄ composite showing debonding and bridging. (Courtesy Reference 32)

Table 13 Influence of sintering aid content and composition on toughness

v/o SiC ⁽¹⁾	Matrix Composition ⁽²⁾		$K_{Ic}^{(3)}$	% $\Delta^{(4)}$	SAMPLE CODE
	Molar % Y ₂ O ₃ + SiO ₂	Molar Ratio SiO ₂ /Y ₂ O ₃			
30	50	9:1	4.4 ± .5	-15.4	2166 #40
30	55	2.7:1	4.1	-21.2	2170 #40
30	55	1.2:1	5.4 ± .3	+ 3.8	2168 #40
20	37	17.5:1	5.6 ± .1	+ 7.8	2097 #27
20	27	12.5:1	6.0 ± .1	+15.4	2096 #27
20	36	2.6:1	5.8 ± .5	+11.5	2126 #32
30	8.9	2.6:1	5.2 ± .1	--	7x014(5)

1 - Tateho T44 whisker

2 - Si₃N₄ powder used

3 - Control flaw by Chantikul method

4 - % change in toughness from standard 4 w/o Y₂O₃ material

5 - SRBSN matrix

Figure 17 Bright field electron micrograph showing the silica coating applied by a solution method onto an AMI SiC whisker.

Table 14 Fracture toughness data on materials with oxide modified interfaces

COATING ^(a)	SINTERING AID	VOL %		$K_{Ic}^{(b)}$ MPa $\sqrt{m}$	SPECIMEN CODE
		SiC	FORMING		
Y ₂ O ₃ (sol coat)	4 w/o Y ₂ O ₃	30	Inj. Mold	5.3 ± .3	2270-75
SiO ₂ (sol coat)	4 w/o Y ₂ O ₃	30	Inj. Mold	5.1 ± .2	2278-75(74)
ZrO ₂ (sol coat)	4 w/o Y ₂ O ₃	30	Inj. Mold	5.3 ± .4	2270-74(75)
B ₂ O ₃ (sol coat)	4 w/o Y ₂ O ₃	20	CIP	4.0 ± .2	2280-77
--	RE(I) ^(c)	30	CIP	4.8 ± .3	2275-74(75)
--	RE(II)	30	CIP	5.5 ± .2	2276-74
--	RE(III)	30	CIP	5.6 ± .1	2277-74
--	Mixed Oxide ^(d)	30	CIP	6.0 ± .3	2269D-77
SiO ₂ (oxidation)	4 w/o Y ₂ O ₃	20	Inj. Mold	5.9 ± .7	2194IM-52
SiO ₂ (sol)	4 w/o Y ₂ O ₃	20	Inj. Mold	6.8 ± .3	2195IM-53

* - American Matrix SiC whisker (rec. 2/88) used in all materials

o - Si₃N₄ powder used as matrix precursor

a - Coating on whisker surface

b - By control flow method of Chantikul

c - Proprietary blend of Rear Earth oxide sintering aids

d - Proprietary blend of oxide sintering aids

CARBON, SINGLE COATING

It has been demonstrated that SiC whiskers with carbon rich surfaces improve the fracture toughness of alumina³³ and spinel³⁴ matrix composites. Whiskers with thin (5-10 nm) carbon surfaces are currently available from several manufacturers. A discussion of Si₃N₄ matrix composites reinforced with carbon coated SiC whiskers follows.

Advanced Composite Materials Corporation whiskers were evaluated for surface composition by Auger. The results showed that a pure carbon surface approximately 160 nm thick is on these whiskers (Figure 3). TEM examination revealed a continuous and amorphous surface coating ranging in thickness from ~ 2-4 nm. A Si₃N₄ with 4 wt% Y₂O₃ matrix was reinforced with 30 volume percent of these whiskers. The powder blend was combined with binders and injection molded into test bars to uniaxially align the whiskers. After dewaxing, the bars were HIP'ed to full density. The fracture toughness of the composite perpendicular to the whisker axis was 6.9±0.2 MPa√m as determined by the control flow method. This value is one of the highest fracture toughness obtained in this program. The carbon coating was not detected by TEM analysis of the dense composite. The carbon loss may have been a result of either dissolving into the glassy phase, or reacting with the oxide sintering aid to form CO(g). The intergranular thickness between SiC and Si₃N₄ was ~ 2-4 nm as observed in TEM. Auger analysis of this material revealed a carbon rich surface on whiskers exposed at a fracture surface. Details of this analysis and comparison to other composites are in the section "Auger Analysis of Interfaces" of this report. Carbon coated whiskers were also supplied by American Matrix Inc. TEM was used to observe the coatings. Figure 18 compares two whiskers taken from this batch of material. Both coated and uncoated materials were present. Si₃N₄ reinforced with 20 vol % of these carbon coated whiskers had the highest fracture toughness (6.5±0.2 MPa√m) obtained in this study for composites with randomly oriented whiskers. Transmission electron microscopy was conducted with a similarly prepared composite to determine if the carbon coating remained on the whiskers in the densified composite. Most of the whiskers in the composite had a discontinuous, crystalline coating on their surface. The coating morphology was thin and layered with a thickness that ranged from approximately 10 nm to 30 nm. The TEM resolution was not sufficient to determine the composition and crystal structure of the coating. It was assumed to be carbon due to the coating structure and the analysis conducted prior to processing. The morphology of the apparently crystalline film on the whiskers is illustrated by the whisker/matrix interface (Figure 19). This coating is similar to the graphitized film observed by M. Yamamoto et. al.³⁴ in a spinel matrix composite reinforced with an initially amorphous carbon coated silicon carbide whisker.

The effect of carbon content on toughness was evaluated with American Matrix SiC whiskers. Three lots of SiC whiskers with different quantities of carbon were received from the manufacturer. The batch with the lowest carbon content was prepared at Norton Company by a proprietary process. As shown in Figure 20, the fracture toughness of Si_3N_4 reinforced with the carbon coated SiC whiskers is sensitive to the quantity of carbon on the whisker surface. The "free" carbon content is the amount of combustible carbon (not bonded to Si and SiC) associated with the whiskers. Earlier TEM analysis had confirmed the presence of thin carbon layers on these materials. Although not confirmed, it is assumed that the different carbon contents are a result of different carbon layer thicknesses on the whiskers. An increase in the carbon content by a factor of ten results in a toughness increase from ~ 4.8 to $\sim 6.4 \text{ MPa}\sqrt{\text{m}}$. For this evaluation the SiC whiskers had a random orientation within the Si_3N_4 matrix.

The application of carbon coatings to various SiC whiskers at Norton Company was successful in increasing fracture toughness. As shown in Figure 21 the treated whiskers (carbon coated) result in higher toughness composites independent of the whisker source used.

Figure 19 TEM of a carbon coated American Matrix SiC whisker in a HIP'd Si_3N_4 matrix composite.

Figure 18 TEM micrographs of two whiskers from a batch of as-received carbon coated American Matrix Inc. SiC whiskers.

Figure 20 "Free" carbon content of American Matrix SiC(w) vs. the resulting composite fracture toughness.

Figure 21 The effect of carbon coatings applied at Norton Company on composite fracture toughness.

CARBON WITH PROTECTIVE COATING

Initial work to dual coat SiC whiskers with a carbon layer and a protective overcoating was investigated and reported in Phase I of this project.⁴ The coated whiskers were incorporated into a Si_3N_4 matrix at a 20 v/o loadings and HIP'ed to full density early in Phase II. The fracture toughness results were $4.7 \pm .2 \text{ MPa}\sqrt{\text{m}}$ for a coating of SiC over carbon and $4.9 \pm .3 \text{ MPa}\sqrt{\text{m}}$ for Si_3N_4 over carbon. These values are the same as unreinforced monolith material ($4.6 \pm .7 \text{ MPa}\sqrt{\text{m}}$).

The lack of toughness improvement could be a result of the non-uniform composition or deposition of the coatings as reviewed in Phase I.⁴ It has been reported that a carbon layer on a reinforcement will deteriorate during a reaction bonding process for Si_3N_4 .³⁵ Therefore it is necessary to develop a protective coating scheme for preparing toughened composites using a reaction-bonding process. Literature data have shown that SiC overcoatings on carbon are an effective way of reducing the deterioration of the carbon layer during processing of titanium matrix composites.³⁶

As a result of the need for a dual coating, we have continued to refine the coating process at Norton Company to improve morphology and composition. The coating is applied by the decomposition of methyltrichlorosilane at elevated temperature. Three batches of CVD coated whiskers having carbon as the debonding layer and SiC as the protective layer were evaluated by STEM and TEM. Table 15 compares the coating thickness of the three batches evaluated. The calculated coating thickness was determined from the weight gain of the whiskers during CVD. In general, four different coating morphologies were observed. The majority of whiskers had a thin continuous coating of fine SiC nodules over the carbon underlayer. Figure 22 is an example of this coating on a SiC whisker. As listed in Table 15 the diameter of the fine SiC nodules are similar in all three whisker batches (40-100nm). The thickness of this fine nodular layer increases from a single layer of particles (60-100nm) to multiple particle layers (100-300nm) as the calculated coating increases. Another coating morphology observed consists of a discontinuous layer of coarse SiC nodules over the carbon layer. Table 15 lists the thickness and length of the large nodules observed in the different batches. The larger and thicker nodules are observed in the material with the thicker calculated coating. In addition to the coatings just described, there were also uncoated whiskers and carbon coated whiskers without the SiC overcoating.

The elemental composition of the coatings were confirmed by STEM analysis. Figure 23 is a composite photograph for a dual coated whisker showing the surface morphology by TEM and dot map analyses for silicon, carbon, and oxygen. The nodules contain both silicon and carbon. There is a thin coating of carbon evident on the whisker surface. The oxygen dot map shows an oxygen rich layer on the surface of the whisker. There is also some oxygen present within the coatings.

These dual coated whiskers were incorporated into an SRBSN matrix to determine if the SiC protects the carbon and if an improvement in fracture toughness results. The coated reinforcement loading used was 20 v/o. Fracture toughness results did not show an improvement over composite material prepared in the same manner with uncoated whiskers (5.1±.2 vs.

5.2±.2). TEM analysis revealed that the SiC overcoating was removed from the whisker surface during processing. Nodules of SiC were present in the matrix separated from the SiC/Si₃N₄ interface. As a result, the carbon underlayer was no longer present. The microscopy also revealed the presence of many intergranular voids. This would be consistent with a reduction of sintering aid content due to the loss of SiO₂ from the reaction:

Results from SEM analysis of the fracture surface were consistent with the toughness values, limited pullout/debonding was observed. Although special precautions were taken to minimize coating damage during processing it appears alternative processing methods need to be developed to minimize coating damage.

Figure 22 TEM Micrograph of an American Matrix SiC whisker with a carbon debonding layer and a continuous fine SiC particulate overcoating.

Table 15 Comparison of SiC/C dual coatings

Specimen Code	Total Coating Thickness (nm)		Continuous Fine SiC Coating (nm)		Discontinuous Coarse SiC Nodules (nm)	
	Calculated*	Microscopy				
			diameter	thickness	thickness	length
5-2	44	60-125	60-100	60-100	125	300
6-3	90	75-170	40-100	60-300	125	300
6-5	230	100-350	70-100	100-300	325	900

*Calculated from weight gain from CVD processing

Figure 23 STEM/TEM analysis of the morphology and composition (Si, C, O) of dual coated SiC whiskers.

BORON NITRIDE, SINGLE COATING

Boron nitride has been shown to act as a debonding layer in fiber reinforced composites.³⁷ Considering this, we evaluated it as a debonding layer in SiC(w) reinforced Si_3N_4 . Our effort included developing methods for applying thin (<150nm) stoichiometric BN coatings to SiC whisker surfaces. Coating methods were developed by vendors^{38,39,40} and within Norton Company. Chemical Vapor Deposition (CVD) and non-CVD methods were investigated.

Norton Company's CVD effort involved modifying an in-house fluidized bed reactor for the deposition of BN. Initial work used 100um SiC grit. Table 16 lists Auger analysis of the coating. The stoichiometry is ~1:1 (B:N) with carbon and oxygen also detected. X-ray diffraction results on the coating matches well with hexagonal BN (PDF#34-421). The coating was continuous.

The BN coated SiC grit was incorporated into both Si_3N_4 and SRBSN matrices, and then HIP'ed to full density. This was to compare the effect of different processing routes on the resulting interface structure. Evaluation of the interface was conducted by optical microscopy on polished specimens. The material prepared with Si_3N_4 powder did not show interface deterioration during processing. The coating remained on the SiC grain and was of uniform thickness and continuous. It was noted that the BN at the interface promotes debonding when an indentation crack interacts with the interface. This is clearly demonstrated in Figure 24 where cracks interact with coated and uncoated grains. Results showed that the BN interface deteriorates during the reaction-bonding process. The coating is no longer continuous on the grains and appears to migrate into the matrix. The cause for this is unclear but may be a result of the oxygen content (~ 7 atomic %) of the coating being in the form of B_2O_3 . This oxide would melt and flow at typical nitridation temperatures (~ 1400°C). These results demonstrate the need for protective overcoatings to limit degradation of BN when the composite undergoes a nitridation step.

With the successful deposition of BN on 100µm SiC grit in a fluidized bed the CVD effort switched to coating American Matrix SiC whiskers. To accomplish this, the CVD reactor was redesigned into a stationary bed configuration. This redesign was necessary because fine whiskers cannot be fluidized. Through a series of proprietary process optimizations the whiskers were successfully coated with a BN coating. Analysis of the coating revealed hexagonal BN (PDF#34-421) by XRD and a stoichiometric B:N ratio with 10-15 atomic percent carbon (Figure 25). TEM reveals the coating to be ~ 150-300nm thick, crystalline, and contain a whiskery (or platey) morphology oriented perpendicular to the whisker surface (Figure 26).

These whiskers were incorporated into a Si_3N_4 matrix. Because the "as-coated" whiskers were bonded together by the BN coating they were lightly ground in a mortar and pestle to separate. After deagglomeration the material was evaluated by optical microscopy. The whisker morphology of the SiC was still apparent after the grinding process. A loading of 15 wt. percent coated SiC whiskers was blended with Si_3N_4 powder having 4 wt% Y_2O_3 . After HIP'ing, the interface was evaluated by TEM to determine morphology, crystallinity and survivability. In most cases the BN coating remained at the SiC whisker/matrix interface but there was evidence of it also in the matrix. Its presence in the matrix is attributed to flaking of the coating during grinding to break up whisker agglomerates. The BN whisker morphology present on the as coated SiC whiskers was not evident after HIP densification of the composite. After densification, the structure is a mix of microcrystalline and amorphous BN. The thickness of the BN interface varied greatly and the coating was not continuous. The coating thickness ranges from 0 nm to over 3.0 microns. Figure 27 is a bright field transmission electron micrograph of the whisker BN interface. The BN coating is approximately 50-75 nm thick in this area. In most areas the coating did not appear well bonded to the whiskers nor was it fully dense; that is, it contained voids within the BN layers. Figure 28 is a photomicrograph of the interaction of a crack with a BN coated whisker in the HIP'ed material. The BN interface allows debonding to occur at the interface. The fracture toughness of this material was $4.8 \pm 0.2 \text{ MPa}\sqrt{\text{m}}$ by the control flaw method. This result shows no improvement over monolith materials. Due to the limited supply of material, strength was not determined. One possible explanation is the potential damage done to the coating and whiskers during the grinding operation. This information was used to further develop the CVD coating process to prepare thinner coatings which would reduce the BN bonding between whiskers.

Thinner BN coatings were applied to the whisker as a result of additional proprietary process changes. Coating thickness ranged from 4.0 to 260 nm depending on the location within the CVD reactor chamber. The weight gain during deposition was used to determine the average coating thickness. The calculated thicknesses are in very good agreement with TEM observations as shown in Figure 29. The oxygen content of selected whiskers are reported as a function of coating thickness in Figure 30. Except for one sample, the oxygen content increased with coating thickness. TEM analysis revealed the coatings were relatively uniform and continuous. All of the whiskers examined were coated. As with the previous coating the BN morphology was platelike and oriented perpendicular to the whisker surface. The platelets were between 1.0-5.0 nm in diameter. A selected

area diffraction (SAD) pattern obtained on an agglomerate of the coating was indexed as microcrystalline BN. The average composition of the coating as determined by Auger was 29 a/o C, 6 a/o O, 34 a/o B, 32 a/o N. The N:B ratio is 0.94. The carbon content may be a result of the graphite heating element used in the CVD apparatus.

These thinner BN coated whiskers were incorporated into a Si_3N_4 matrix. For this composite whiskers ranging in coating thicknesses from 4.0 nm to 80.0 nm were used. The whiskers were wet blended with Si_3N_4 powder having 4 wt % Y_2O_3 . After drying, this mix was blended with waxes so that injection molded test bars could be prepared with approximately uniaxial whisker alignment. After dewaxing, the injection molded bars were HIP'ed. The oversized test bars were machined into MIL-STD (B) size specimens for control flaw toughness analysis. The resulting toughness was $4.0 \pm 0.1 \text{ MPa}\sqrt{\text{m}}$. Fractograph analysis by SEM agree with the toughness data. This sample showed minimal whisker pullout and debonding. The cause for the low toughness value is undetermined. It may be that the increased oxygen content of the coated whiskers (Figure 30) over the uncoated whiskers ($1.48 \pm 0.03 \text{ wt } \%$) may be as B_2O_3 . This oxide would tend to form a glass which will effect the interfacial bond strengths between the SiC whiskers and Si_3N_4 matrix. As noted earlier in this report (Table 14) when B_2O_3 coated SiC(w) are inserted into a Si_3N_4 matrix a low fracture toughness of $4.0 \pm 0.2 \text{ MPa}\sqrt{\text{m}}$ results. TEM analysis of this composite revealed that the BN coating remained on the SiC whiskers.

Boron nitride coatings were also applied to SiC whiskers using a polymer pyrolysis process. This work was performed in conjunction with UCLA³⁹ and Callery Chemical Company.⁴⁰ Analysis by TEM showed the coating to be relatively uniform, continuous, and present on all the whiskers examined. In most areas the coating thickness ranged from approximately 30-35 nm. Figure 31 is a bright field micrograph of a typical BN coated whisker. There were some large areas of coating on the whiskers with thickness up to 350 nm. The BN coating was amorphous as determined by selected area diffraction. The average composition of the coating as determined by Auger analysis was: ~ 2 atomic percent (a/o) Si, 28 a/o C, 7 a/o O, 31 a/o B, and 33 a/o N. The ratio N:B = 1.06. The high carbon content is either residual from the polymer or due to absorption from exposure to the atmosphere.

Table 16 Auger analysis of the BN coating applied to SiC grit by CVD at Norton Company

		Grit "B"	Grit "C"	Grit "D"
Atomic percent	Boron	42.4) 1.0	42.4) 1.2	45.0) 1.1
	Nitrogen	43.0)	36.0)	41.3)
	Carbon	10.7	13.0	6.9
	Oxygen	3.9	8.9	6.9

Figure 24 Crack interactions with BN coated and uncoated SiC grains in HIP'ed Si_3N_4 .

Figure 25 Typical Auger electron spectroscopy of BN coatings on AMI SiC whiskers applied by CVD at Norton Company.

Figure 26 TEM Micrograph of the BN coating on an AMI SiC whisker applied by CVD at Norton Company.

Figure 27 Bright field TEM micrograph of a BN coating/SiC whisker interface in a HIP'ed Si_3N_4 matrix composite.

Figure 28 Evidence of debonding in the HIP'ed Si_3N_4 matrix composite reinforced with CVD BN coated AMI SiC whiskers prepared at Norton Company.

Figure 29 American Matrix SiC whiskers coated with thin CVD BN coatings at Norton Company.
A) ~15nm coating thickness
B) ~70 nm coating thickness

Figure 30 Bulk oxygen content of CVD BN coatings vs. calculated coating thickness.

Figure 31 Bright field TEM micrograph of an AMI SiC whisker with a BN coating applied by a polymer pyrolysis method.

BORON NITRIDE, WITH PROTECTIVE COATINGS

As previously noted, when an SRBSN processing route is used there has been evidence of deterioration of the BN coating. To alleviate this problem a multiple coating scheme where the BN is protected by an outer layer of either SiC or Si₃N₄ was evaluated.

Two batches of CVD coated SiC whiskers prepared at a vendor³⁸ were received. Initial coatings were applied to Tateho SiC whiskers. Figure 32 is an SEM photograph showing that a coating was deposited on these whiskers. The bulk oxygen content was significantly lower than observed in similar material prepared in Phase I (3.2 vs. 8.1%).⁴ Auger analysis was conducted to determine composition as a function of depth. The results in Figure 33 show that both carbon and BN were deposited on the whiskers. The data does not represent the desired multilayer configuration of SiC over BN. It appears as though carbon and BN were co-deposited on the whiskers.

A second batch of material utilized American Matrix SiC whiskers. Auger analysis of four different whiskers within the lot revealed that surface composition varied greatly from whisker to whisker. For example, one whisker had boron and nitrogen at the surface which gradually changed to silicon and carbon with depth. Another whisker only had a small quantity of boron and nitrogen at the surface with the balance being carbon. The different results demonstrate the difficulty in uniformly coating all whiskers within a batch. As with the other batch of coated whisker just described, it appears that carbon rather than SiC was deposited on the whiskers as the protective overcoating.

The dual coating of SiC over BN was also attempted at Norton Company since as previously discussed both SiC and BN were successfully deposited to the surface of the whiskers. As with the materials coated at the outside vendor, the in-house effort to apply this particular coating sequence was unsuccessful. It was found that the boron nitride layer reacted during the SiC coating process. TEM observations and Auger analysis could not detect the presence of a dual coating. There appears to be a chemical reaction between BN and the MTS used for SiC deposition.

Figure 32 SEM of dual coated Tateho SiC whiskers as applied by CVD.

Figure 33 Auger analysis of a dual coated Tateho SiC whisker as-applied by CVD.

AUGER ANALYSIS OF INTERFACES

Five composite materials with a range in fracture toughness were evaluated by Auger analysis to determine the chemical composition of the SiC/Si₃N₄ interface. The goal was to relate the interface composition to fracture toughness. Auger analysis was conducted at the Oak Ridge National Laboratory HTML facility.⁴¹ Composite samples were fractured within the Auger high vacuum chamber followed by the analysis of individual debonded whisker surfaces present on the fracture surface. A 0.25μm² area was used to collect data from a whisker surface. Whisker diameters are approximately 1.0μm. An accelerating voltage of 10kv with a beam current ranging from .002 to .010μA was used for analysis of the composite specimens. Five or six whisker surfaces were evaluated per material. Polished specimens of SiC and Si₃N₄ monoliths were used as references to check the tabulated sensitivity factors. The results on SiC were in excellent agreement with tabulated data. Silicon nitride was difficult to analyze due to charging problems. For Si₃N₄ the analysis was conducted at 3kv. Data could only be obtained on as-polished surfaces with residual carbon and oxygen present. The ratio of silicon to nitrogen in this sample, calculated from tabulated sensitivity factors, is in very good agreement to theory (40.2:59.8 vs. 42.9:57.1). Due to the rough morphology of the composite fracture surface, there is a potential source of analysis error. It is likely that the spectra collected on the whisker surfaces may also include data from the Si₃N₄ matrix. However, due to the similar whisker size and fracture surface morphologies of the composites we feel confident in our ability to observe differences between samples.

The results on the five composite materials are listed in Table 17. Upon review of the data there are some clear trends. Whisker surfaces in composites with the higher fracture toughnesses (≥ 6.4) have excess carbon (Si:C, <0.70), contain more silicon and carbon on their surface (Si+C, >60 atomic %), and are lower in nitrogen (<20 atomic %) than the low toughness materials (≤ 4.8). There is no obvious trend of the interface oxygen content with fracture toughness. The yttrium content of the interface was not determined. These results further substantiate that the presence of an enriched carbon surface on the whiskers in a composite improves fracture toughness.

Three apparent inconsistencies between the nominal whisker coatings and the Auger analysis of the whisker/matrix interface were noted (See Table 17). In the first case; although whiskers were coated with SiO₂ the Auger results revealed a carbon enriched interface. Further investigation revealed that the as-received whiskers tend to have a carbon rich surface. Since the SiO₂ coating was applied by a solution method rather than an oxidative process, it was applied over the carbon coating.

In this instance the original carbon surface is controlling fracture toughness behavior and not the SiO_2 overcoating. In the second case; the material was reinforced with BN coated whiskers. Auger results of the interface reveal that the composition was predominately boron and nitrogen (atomic % B + atomic % N = 76%). It was anticipated that the presence of BN would increase fracture toughness but this sample had a relatively low toughness. A possible explanation could be the presence of B_2O_3 within the BN (7.2 % oxygen) which resulted in a strong interfacial bond. In the third case; the Tateho whiskers, which initially had a carbon rich surface, do not show a carbon enhancement in the composite. It is unexplained as to why the carbon layer on these whiskers are removed when it remains on other materials. The low toughness is consistent with the lack of excess carbon at the interface.

In summary, the Auger analysis of the composites clearly demonstrated the sensitivity of fracture toughness to interface structure and that the interface structure which results during densification may differ significantly from that anticipated when using coated whiskers.

Table 17 Composite interfaces by Auger analysis

WHISKER SOURCE	PREHIP SiC SURFACE	FORMING	SPECIMEN CODE	$K_{Ic}^{(1)}$ MPa $\sqrt{\text{m}}$	ATOMIC PERCENT					Si:C	O:N	Si + C
					Si	C	N	O	B			
AMI	SiO_2	Inj. Mold	2195-53	6.8 ± .3	24.2	37.4	19.5	19.0	0	.65	.97	61.6
AMI	C	CIP	2148-39	6.4 ± .2	24.3	45.7	18.6	11.5	0	.53	.62	70.0
AMI	C	CIP	2197-49	6.5 ± .1	10.4	72.1	10.2	7.3	0	.14	.72	82.5
TATEHO	C	CIP	3019-22	4.1 ± .4	27.0	28.2	31.4	13.4	0	.96	.43	55.2
AMI	BN	CIP	2250C-68	4.8 ± .2	8.4	8.5	34.6	7.2	41.4	.99	.21	16.9
--	--	HP	SiC(NC-203)	--	47.3	51.0	0	1.7	0	--	--	--
--	--	CIP	Si_3N_4 (XL-144) ⁽²⁾	--	13.3	11.0	19.8	55.9	0	--	--	--

o $\text{Si}_3\text{N}_4 + 4 \text{ w/o } \text{Y}_2\text{O}_3$ as Matrix

[1] By control 'flaw method of Chantikul

[2] An acceleration voltage of 3Kv was used

METAL/ALLOY

Metallic interfaces between SiC reinforcements and Si_3N_4 were evaluated to further define the interface properties necessary for improved fracture toughness. Although many of the selected metals or alloys may not be practical for high temperature application, insight can be provided into the effect of the interface on fracture toughness.

The use of metals and alloys as interface coatings may be divided into four categories.

1. Layered structures (eg. GaS, Si_2Te_3 , WSe_2)
2. Ductile layers (eg. gold, silver)
3. Brittle layers (eg. silicon, germanium, tungsten)
4. Reactions for in-situ carbon layers (eg. chromium, nickel)

In the category of layered structured materials, a literature review was conducted to find other materials with similar mechanical properties to BN and carbon. The layered structure materials of interest have weak interplanar forces. These weak layers will promote debonding and sliding at an interface. There are some obvious silicates such as talc and mica which in principle fulfill this requirement, however their high temperature instabilities and anticipated reactivities with Si_3N_4 and/or its sintering aids eliminate them from consideration. Many other layered structured materials exist that fall into the general classes listed in Table 18.⁴² Unfortunately, many of these materials become unstable above $\sim 500^\circ\text{C}$. Those which have better high temperature stability contain tellurium and selenium which are toxic. Toxicity severely limits their practical study and use. No practical materials with layered structures which would be appropriate for the interface between Si_3N_4 and SiC have been found by the literature review.

Table 19 lists metallic coatings that have been evaluated. These coatings fall into categories 2, 3 and 4 previously mentioned. The coatings were applied to either SiC grain or whiskers by either PVD, CVD or electrolytic methods. The coated SiC was mixed with Si_3N_4 having 4 w/o Y_2O_3 sintering aid and HIP'ed. The effectiveness of the coating was determined by insertion of indentation cracks into polished sections and observing crack interactions with the microstructure. The results of the coatings are summarized in Table 19. Several coatings (W, Au, Ag) did show evidence of enhanced debonding and/or blunting at the interface. Although these material show the promise of metal interfaces in these composites they are not practical for the high temperatures required in advanced gas turbine applications.

Table 18 Layered structure materials

- o Bivalent Metal Hydroxides
Mg(OH)₂, Mn(OH)₂
- o Transition Metal Dichalcogenides
MCh₂ (M = Ti, Zr, Nb, Mo, W; Ch = Se, Te, S)
- o III - VI Compounds
GaS, GaSe, GaTe, InSe
- o IV - VI Compounds
PbO, Si₂Te₃, SnS₂, SnO
- o Carbon, Boron Nitride

Table 19 Composites with metal interfaces

Metal Coating	SiC	Composite Code	Observations
Ni(B)	grain	(2256#58)	Coating diffused away from the interface during HIP'ing. Reaction with SiC produced Ni ₃ Si ₂ .
Cr	powder	(2229#53)	Coating diffused away from the interface during HIP'ing. Cr reacted with SiC to produce CrSiC.
Si	whisker	(2231A#53)	Coating diffused away from the interface during HIP'ing.
W	grain	(2228#58)	Coating remained at interface, evidence of crack blunting.
Au	grain	(2258#58)	Coating remained at interface, some evidence of enhanced debonding.
Ag	grain	(2262#64)	Coating present at interface, debonding evidence.

INTERFACIAL STRESSES

Multiphase materials are known to develop residual stresses as a result of differential thermal expansion mismatch between the components. The presence of these stresses have been used to explain fracture toughness variations in Si_3N_4 monoliths with different secondary phases.⁴³ Experimental quantification of these stresses are difficult but have been obtained for the $\text{Al}_2\text{O}_3/\text{SiC}(w)$ system by an x-ray diffraction method.⁴⁴ Different models exist to calculate the anticipated residual stresses in various composite systems.^{45,46} Recent work by Hsueh et. al.⁴⁶ has incorporated the presence of an interfacial film into their models. They use a cylinder composite model to determine the residual stress which developed upon cooling.

Calculations were performed at Norton Company to estimate residual stresses in the $\text{Si}_3\text{N}_4/\text{SiC}(w)$ system. A composite cylinder model containing an intergranular phase between the Si_3N_4 and SiC (Figure 34) was selected. Stresses were calculated by finite element analysis methods. End effects were not considered in these calculations. The material properties and geometry constraints are listed in Table 20. The effect of inter- granular phase thickness and intergranular phase coefficient of thermal expansion (CTE) on the maximum principle tensile stress within the system is exhibited in Figure 35. Interfacial tensile stresses greater than 800 MPa can occur within the intergranular phase when the intergranular phase has a $\text{CTE} \geq 7.0 \times 10^{-6}$. For CTE values of the intergranular phase $\leq 5.0 \times 10^{-6}$ the maximum principal tensile stress occurs in the SiC whisker. There was little effect of changing the intergranular phase thickness from 10 nm to 50 nm.

It has been observed that the intergranular phases in a Si_3N_4 monolith can form large single crystals which encompass multiple grain boundaries and triple points and essentially surround Si_3N_4 grains.⁴⁷ As a result, it is necessary to know the CTE's of the intergranular phases as a function of crystallographic orientation. This is necessary because the Si_3N_4 grains or SiC whiskers may be in contact with each of the crystallographic orientations of the intergranular phase. The expansion data for delta $\text{Y}_2\text{Si}_2\text{O}_7$ and yttrium apatite $\text{Y}_5(\text{SiO}_4)_3\text{N}$ which can be present in Si_3N_4 were not available in the literature. The values were determined by a joint effort between Norton Company and the HTML facility at Oak Ridge National Laboratory.⁴⁸ In brief, the two phases were synthesized by blending the appropriate quantities of Si_3N_4 , Y_2O_3 , and SiO_2 and firing at 1650°C in 1-atm of nitrogen. Thermal expansion was determined by measuring lattice parameters from room temperature to 1200°C . The thermal expansion coefficients are listed in Table 21. The lattice expansions for delta $\text{Y}_2\text{Si}_2\text{O}_7$

were highly anisotropic and differ significantly from the reported bulk expansion.⁴⁹ The expansion of the apatite phase is only slightly anisotropic as is typical for silicate apatites⁵⁰ and in very good agreement with the reported bulk data.⁵¹

The compilation in Table 21 reveals that a large range in thermal expansion coefficients exist for intergranular phases observed in Si_3N_4 .^{43,48-58} It was expected that these expansion coefficients will effect the residual stress and fracture toughness of composites. During our study of composites with Y_2O_3 and SiO_2 as the sintering aid we have not been successful in relating fracture toughness to the presence or absence of a particular phase.

An attempt was made to increase the residual stress at $\text{SiC/C/Si}_3\text{N}_4$ interfaces in composites by immersion into liquid nitrogen (-200°C). It was thought that the additional stresses may debond the interface at -200°C and enhance room temperature toughness. By debonding the interface prior to testing a more extensive pullout may occur upon fracture. As shown in Table 22 no effect was observed as a result of the liquid nitrogen treatment.

Figure 34 The composite cylinder model used to calculate residual stress from thermal expansion mismatches.

Table 20 Material properties and geometry constraints
used for the calculation of the residual stresses

Materials Properties

Si_3N_4 : $E = 300 \text{ GPa}$, Poisson ratio = 0.3, $\text{CTE} = 3.5 \times 10^{-6}/^\circ\text{C}$

SiC : $E = 440 \text{ GPa}$, Poisson ratio = 0.3, $\text{CTE} = 4.5 \times 10^{-6}/^\circ\text{C}$

Inter
Granular

Phase: $E = 186 \text{ GPa}$, Poisson ratio = 0.3, $\text{CTE} = 3.0 \text{ to } 12.0 \times 10^{-6}/^\circ\text{C}$

Geometric Conditions

30 volume percent SiC

SiC diameter = $0.5 \text{ } \mu\text{m}$

Change in Temperature = 1000°C

Intergranular Phase Thickness = 10 nm , 50 nm

Figure 35 Maximum residual tensile stress as a function
of intergranular phase thermal expansion
coefficient and thickness.

Table 21 Thermal Expansion Coefficients for Potential Phases in $\text{Si}_3\text{N}_4/\text{SiC}_{(w)}$ Composites

Expansion $\times 10^{-6}$	Temperature Range	Direction	Phase	Reference
-17.5	0-1100°C	a	$\beta\text{-LiAlSiO}_4$	43
- 2.0	25-1100°C	a	$\beta\text{-LiAlSi}_2\text{O}_6$	43
0.6	RT-200°C	[100]	Y_2SiO_5	52
1.26	0-1000°C	a	Si_2ON_2	58
2.5	--	Bulk	$\text{Mg}_2\text{Al}_4\text{Si}_5\text{O}_{18}$	57
-2.6	25-1200°C	Bulk	$\text{MgAl}_2\text{Si}_4\text{O}_6\text{N}_4$	57
2.9	RT-1200°C	(010)	$\delta\text{Y}_2\text{Si}_2\text{O}_7$	48
3.23	0-1000°C	a	$\beta\text{Si}_3\text{N}_4$	58
>3.5	N/A	--	Y-Si-Al-O-N glass	54
3.61	0-1000°C	a	$\alpha\text{Si}_3\text{N}_4$	58
3.70	0-1000°C	c	$\alpha\text{Si}_3\text{N}_4$	58
3.72	0-1000°C	c	$\beta\text{Si}_3\text{N}_4$	58
3.89	0-1000°C	b	Si_2ON_2	58
3.8-4.1	RT-1300°C	Bulk	$\text{Y}_2\text{Si}_2\text{O}_7$	49
3.99	0-1000°C	c	Si_2ON_2	58
4.06	20-1000°C	α_{33}	SiC (4H)	45
>4.1	N/A	--	Mg-Si-AL-O-N glass	54
4.4-4.5	N/A	--	SiC cubic (3C)	45
4.47	20-1000°C	α_{11}	SiC (4H)	45
4.55	0-1000°C	a	Silicon	58
5.8	20-1000°C	Bulk	$\text{Y}_2\text{Si}_3\text{O}_3\text{N}_4$	51
6.0	RT-900°C	Bulk	Y-Si-Al-O-N glass	49
6.5	25-1100°C	c	$\beta\text{-LiAlSi}_2\text{O}_6$	43
6.6	20-1000°C	Bulk	$\text{Y}_8\text{Si}_4\text{O}_{14}\text{N}_4$	51
<7.0	N/A	--	Y-Si-Al-O-N glass	55
7.6	RT-600°C	c	$\text{Y}_5(\text{SiO}_4)_3\text{N}$	48
7.8	0-1100°C	a	$\beta\text{-LiAlSiO}_4$	43
8.2	20-1000°C	Bulk	$\text{Y}_5(\text{SiO}_4)_3\text{N}$	51
8.3	RT-600°C	a	$\text{Y}_5(\text{SiO}_4)_3\text{N}$	48
>8.5	N/A	--	Ca-Na-Si-O-N glass	54
8.6	RT-1400°C	--	$\text{Y}_3\text{Al}_5\text{O}_{12}$	56
10.2	RT-1200°C	(100)	$\delta\text{Y}_2\text{Si}_2\text{O}_7$	48
10.7	RT-1200°C	(001)	$\delta\text{Y}_2\text{Si}_2\text{O}_7$	48
11.4	RT-200°C	[100]	Y_2SiO_5	52

Table 22 Fracture toughness of composites before and after liquid nitrogen treatment

30 v/o Carbon Coated Tokai SiC(w) (Code: 2254-62)

as HIP'ed 5.6 $\pm$.2
 LN₂ treated 5.3 $\pm$.1

30 v/o ACMC SiC(w) (Code: 2247C-68)

as HIP'ed 5.6 $\pm$.2
 LN₂ treated 5.8 $\pm$.2

* Toughness by Chantikul control flaw method

* Matrix composition of $\text{Si}_3\text{N}_4 + 4 \text{ w/o } \text{Y}_2\text{O}_3$

6.0 PROPERTY PROGRESS

MATERIALS SUPPLIED TO ORNL

Our milestones for this project included forwarding composite materials to Oak Ridge National Laboratories. During the course of this project seven different materials were sent. Table 23 lists the properties of the materials as determined at Norton Company. Composites with room temperature fracture toughnesses of 6.7 and 7.1 were prepared with uniaxially aligned Advanced Composite Materials SiC whiskers. These values are respectively 46% and 54% increases over the baseline monolith available at the beginning of our project (4.6 MPa $\sqrt{m}$). Composite materials with room temperature strengths >800 MPa (>115,000 psi) and 1370°C strengths >400 MPa (>61,000 psi) were also prepared and forwarded to ORNL.

Also shown in Table 23 the fracture toughness of the recent Si₃N₄ reinforced with uniaxially aligned APMC whiskers is 26% higher than for the same material with randomly aligned whiskers. Room temperature fracture strength is also greater for the injection molded material. The increased strength is a result of the higher fracture toughness. This can be demonstrated assuming the two materials have the same size and location of flaw origins. This is a reasonable assumption since they were prepared from the same powder blend and machined into test specimens at the same facility.

$$\sigma_f = K_{Ic} \frac{1}{\sqrt{CY}} \quad (\text{Griffiths equation})$$

$$\frac{\sigma_{f(a)}}{K_{Ic(a)}} = \frac{1}{\sqrt{CY}} = \frac{\sigma_{f(b)}}{K_{Ic(b)}} \quad (\text{Equation \#5})$$

where: $\sigma_{f(a)}$ = fracture strength resulting from $K_{Ic(a)}$

$\sigma_{f(b)}$ = fracture strength resulting from $K_{Ic(b)}$

$\frac{1}{\sqrt{CY}}$ = Constant for same crack size at the same location

The properties of the composite with random APMC SiC whiskers are:

$$\sigma_f = 805 \text{ MPa and } K_{Ic} = 5.3 \text{ MPa}\sqrt{m}$$

If the fracture toughness of this material were increased to 6.7 the resulting strength would be 1018 MPa as determined using Equation 5. This is within 8.0% of the strength obtained for the tougher material as listed in Table 23. Therefore, it appears that the increased strength can be fully accounted for by the toughness increase.

Table 23 Composite materials supplied to ORNL

Material Code	7X014	2154C43	2261-66	2274EX-68	2206-51	22875B-80	2287SIM-80
SiC Whisker	Tateho T44	Tateho T44	C-coated AMI	ACMC	Tokai	ACMC	ACMC
Whisker Orientation	Random	Random	Random	Uniaxial	Random	Random	Uniaxial
Volume %	30	20	20	30	30	30	30
Matrix ^(A)	SRBSN ^(B)	SRBSN	Si ₃ N ₄	Si ₃ N ₄	SRBSN	Si ₃ N ₄	Si ₃ N ₄
Strength ^(C) (MPa)							
22°C	772 ± 55	848 ± 96	635 ± 41	809	803 ± 90	805 ± 18	958 ± 117
1370°C	420 ± 21	547 ± 26	370 ± 32	247 ± 10	405 ± 12	452 ± 2	425 ± 28
Toughness ^(D) (MPa√m):							
Room Temperature	5.2 ± .1	5.3 ± .4	6.1 ± .1	7.1 ± .1	5.3 ± .1	5.3 ± .4	6.7 ± .3

A - Matrix has 4 w/o Y₂O₃

B - Si₃N₄ = prepared from Si₃N₄ powder,

SRBSN = prepared from Si + SiC blend,

followed by nitridation and HIP

C - MIL-STD-1942 (MR) 3x4 mm bar 40/20 mm span

D - Chantikul et. al. method, 10 kg indent in oil on Mil-Std Bar

HIGH TEMPERATURE EVALUATIONS

During the course of this project composite materials exhibiting promising properties in the screening studies were prepared into large batches for further analysis. Of particular interest were their high temperature properties including fracture toughness, oxidation, and stress rupture life.

Fracture Toughness - A chevron notch method was utilized to determine the high temperature fracture toughness of composite materials. High temperature fracture toughness results are listed in Table 24 for materials tested with a 3mm x 4mm test bar cross section. Two Si₃N₄ monolith materials are listed for comparison. The three composites with carbon coated SiC whiskers in a Si₃N₄ matrix have the higher fracture toughnesses from room temperature to 1370°C. This is readily observed in Figure 36. These results are consistent with the results reported earlier where composites with carbon coated whiskers result in the higher fracture toughness. Specimens were also tested having 6mm x 6mm cross sections. The results for this configuration are given in Table 25. The composite and monolith have similar toughness to 1200°C. At

1370°C the composites have significantly higher toughnesses. The fracture toughness at elevated temperature for the monolith is slightly higher when a 6x6mm cross section is used rather than a 3x4mm cross section. This later result shows that further refinement of fracture toughness testing methods may be warranted and the need to have internal standards for normalization purposes.

Oxidation - A composite specimen that contained 20 volume % carbon coated AMI SiC whiskers in a $\text{Si}_3\text{N}_4 + 4 \text{ w/o } \text{Y}_2\text{O}_3$ matrix, was oxidized at 1000°C and 1400°C for 10 hours in air to determine the oxidation resistance of a material with carbon coated whiskers. Room temperature MOR testing was performed on unoxidized and oxidized samples. Phase analysis was performed using x-ray diffraction on the specimen oxidized at 1400°C for 10 hours.

The effect of oxidation on room temperature strength is presented in Figure 37. The room temperature strength of the material is 92.1 ksi. The material was not greatly affected by the treatment at 1000°C for 10 hours. The room temperature strength after oxidation was 90.1 ksi and oxidation products were not visible on the surface of the test bars. The 1400°C treatment for 10 hours did oxidize the material, the room temperature strength after this treatment was 66.9 ksi and oxidation products were visible on the surface of the test bars. Phase analysis of the oxidized test bar surface contained: beta silicon nitride, alpha silicon nitride, SiC, and alpha cristabolite. The crystalline oxidation product is alpha cristabolite. These oxidation results are encouraging because this composite material contained carbon coated whiskers and did not catastrophically oxidize at 1100°C or 1400°C due to the presence of carbon. Catastrophic oxidation due to residual carbon has been reported in the literature.⁵⁹

Two sets of MOR bars reinforced with 30 v/o APMC whiskers were oxidized in air at 1370°C for between 100-150 hrs. After this treatment the tension side of the bars were remachined with ~0.03 mm of material removed. The oxidized materials were evaluated for retained high temperature strength and room temperature toughness. The results are listed in Table 26 along with data on preoxidized samples. The high temperature strengths were improved by the oxidation treatment. Prior to the oxidation treatment strength at 1200°C and 1370°C were 62 to 65 ksi (427 to 448 MPa). After the oxidation treatment strengths improved to 73 to 80 ksi (503 to 552 MPa). The CIP'ed composite increased in toughness from 5.3 to 6.7 MPa√m as a result of the oxidation treatment whereas the injection molded material decreased in toughness from 6.7 to 5.7 MPa√m. The reasons for the differences in fracture toughness are unknown at this time.

Stress-Rupture - A monolith and composite prepared by the HIP'ed SRBSN route were evaluated for stress rupture life. The properties for these materials are listed in Table 27. Stress rupture life was determined at 1370°C. The monolith could survive a 250 MPa load for 200 hrs with the composite able to withstand a 225 MPa load for 260 hrs. Testing was suspended after these respective times. Identical stress rupture testing conditions resulted in the composite undergoing more deformation than the monolith. Considering the whiskers used in this composite have a rather high concentration of aluminum, calcium, and iron (see Table 3) it is not surprising that more deformation occurred in the composite. These impurities are known to lower the high temperature performance of Si_3N_4 based materials.

Stress rupture testing of a composite with uniaxially aligned ACMC SiC whiskers was also conducted (code 2287SIM-80). The basic properties of this material are listed in Table 23. The specimen survived 200 hrs. with a 250 MPa load at 1370°C. The improved toughness of this material (6.7) over the earlier tested product (5.2) (see Table 27) may be the reason for improved performance since both materials have identical 1370°C strength (~425 MPa).

Table 24 Chevron notch fracture toughness as a function of temperature for specimens with 3 x 4 mm cross-section

Material Code	Matrix ^(A)	SiC(w)	RT	1000°C	1200°C	1370°C
NC132	Si_3N_4 + 1% MgO	---	4.3±.1	---	3.9±.5	---
--	Si_3N_4 + 4% Y_2O_3	---	4.7±.2	4.1±.2	3.7±.2	4.1±.1
7X014	SRBSN	30 v/o Tateho	4.6±.1	---	3.9±.5	4.1±.3
2154C#43	SRBSN	30 v/o Tateho	4.8±.3	---	3.5±.1	4.5±.1
2197#50*	Si_3N_4	30 v/o AMI	5.8±.2	5.2±.1	5.6±.2	4.7±.3
2247#57*	Si_3N_4	30 v/o ACMC	4.9±.2	---	6.0±.2	4.9±1.1
2287SIM*	Si_3N_4	30 v/o ACMC	5.0±.1	4.8±.2	4.3±.2	6.0±1.3

- o All composite samples have 4 w/o Y_2O_3 in matrix
- o Two or three specimens averaged for each determination
- o Calculated by Bluhm Slice Model
- A - SRBSN = composites prepared by blending SiC(w) with silicon, and sintering aid, nitriding, then HIP'ing to full density
- Si_3N_4 = blending Si_3N_4 powder with Sintering aid and whiskers prior to HIP'ing

* Composites with Carbon Coated SiC whiskers

Figure 36 Chevron notch fracture toughness from room temperature to 1370°C.

Table 25 Chevron notch fracture toughness as a function of temperature for specimens with a 6x6mm cross section

Material Code	SiC(w)	RT	1000°C	1200°C	1370°C
22878-81	ACMC (8/89)	5.2±.3	5.1±.5	5.3±.2	6.6±1.5
2254B-81	Tokai (9/88)	4.6±.1	4.9±.2	4.8±.1	7.2±1.0
Monolith	---	4.9±.3	5.0±.1	4.5±.3	4.9±.8

- o All materials have a matrix of $\text{Si}_3\text{N}_4 + 4 \text{ w/o } \text{Y}_2\text{O}_3$
- o Whiskers have random orientation, 30 v/o loading, carbon coated

Figure 37 Oxidation resistance of a composite with 20 v/o carbon coated AMI SiC whiskers.

Table 26 Comparison of composite properties before and after oxidation

Forming Method	As HIP'ed		Post Oxidation*	
	CIP	IM	CIP	IM
Room Temp. Strength	117±3	137±26	---	---
1200°C Strength	---	65±24	92±7	76±6
1370°C Strength	65.6±.3	62±4	80±2	73±1
Room Temp. Toughness	5.3±.4	6.7±.3	6.7±.3	5.7±.2

CIP = Forming by Cold Isostatic Pressure (code 2287SR-81)

IM = Forming by Injection Molding (code 2287SIM-80)

* - Oxidation treatment 100-150 hrs in Air at 1370°C

* - Samples remachined to remove oxide layer prior to testing

Table 27 Large batch material - Vintage Aug. 87

	<u>Monolith (3x015)</u>	<u>Composite (7x014)</u>
$R_T^{(a)}$	662 $\pm$ 14 MPa (3)*	772 $\pm$ 55 MPa (3)
1370°C ^(a)	517 $\pm$ 62 MPa (3)*	420 $\pm$ 21 MPa (3)
K_{Ic} (CF) ^(b)	4.2 $\pm$.3 MPa $\sqrt{m}$ (3)	5.2 $\pm$.1 MPa $\sqrt{m}$ (3)
K_{Ic} (IN) ^(c)	3.9 $\pm$.1 MPa $\sqrt{m}$	4.2 $\pm$.1 MPa $\sqrt{m}$
Hardness ^(d)	16.0 $\pm$.2 GPa	18.4 $\pm$.3 GPa
Density	3.24 g/cc	3.23 g/cc
Oxygen	2.5 w/o	1.7 w/o
Nitrogen	37.0 w/o	27.8 w/o
XRD (major)	β -Si ₃ N ₄	β -Si ₃ N ₄ , β -SiC
XRD (trace)	Y ₂ Si ₂ O ₇	α -Si ₃ N ₄

Stress rupture life at 1370°C

Load

225 MPa	N/A	>260 hrs.
250 MPa	>200 hrs.	5.2 hrs.
275 MPa	~150 hrs.	N/A
300 MPa	3.5 hrs.	N/A

- 4% Y₂O₃ in matrix, 30 v/o Tateho T44 SiC(w)

* number of data points in parenthesis

a - Mil-STD-1942 (MR), 3x4mm bar, 40/20 span

b - Chantikul et. al., J. Amer. Cer. Soc. 64, #9, p539 (1981)
with 10 kg indent and MIL-STD-1942 (MR) bar

c - Antis et. al., J. Amer. Cer. Soc. 64, #9, p533 (1981),
with 10 kg indent, average of five indents, crack length
measured at 400x magnification

d - Vickers indent at 10 kg

7.0 SUMMARY/HIGHLIGHTS

This program has demonstrated that improvements in fracture toughness can be made in high temperature (1370°C) Si_3N_4 materials. Highest toughness materials ($\sim 7.0 \text{ MPa}\sqrt{\text{m}}$) are obtained with uniaxially oriented carbon coated SiC whiskers. It should be noted that these toughness values fall below the program goal of $10 \text{ MPa}\sqrt{\text{m}}$. Obtainment of higher toughnesses than the current $7.0 \text{ MPa}\sqrt{\text{m}}$ will be difficult without further development of improved strength SiC whiskers. A summary of other developments and observations from this program include:

- 1) Stoichiometric microcrystalline and thin ($\sim 4.0 - 150\text{nm}$) boron nitride coatings were successfully applied to SiC whiskers using a CVD process. A pyrolysis process was used to deposit a thin ($\sim 35\text{nm}$) and amorphous boron-nitrogen-carbon containing coating onto whiskers.
- 2) Carbon coatings were successfully applied to whiskers by either a proprietary thermal treatment method or CVD. With the CVD method a dual layer of SiC over carbon was deposited on the whiskers.
- 3) It was observed that as the quantity of carbon on a whisker source increases the fracture toughness of the composite increases.
- 4) The use of a boron nitride interface did not improve the fracture toughness of SiC whisker reinforced Si_3N_4 . The cause for this is unclear but likely related to removal of the coating during processing or a small quantity of B_2O_3 associated with the coating.
- 5) No significant effect of sintering aid concentration nor composition on fracture toughness was observed.
- 6) Distortion in a whisker reinforced material is significantly reduced when the composite is processed using a HIP'ed reaction-bonding approach rather than a HIP'ed Si_3N_4 powder process. The reduced distortion is a direct result of the improved pre-HIP densities resulting from the reaction-bonding route.
- 7) The reaction-bonding approach results in the deterioration of both carbon and boron nitride whisker coatings. It will be necessary to utilize a barrier coating over the BN or carbon debonding layers to protect them during the reaction-bonding step.
- 8) Neither accelerated nor catastrophic oxidation were observed in silicon nitride reinforced with carbon coated SiC whiskers at 1370°C in air for exposures to 100 hrs..

8.0 RECOMMENDATIONS

The room temperature fracture toughness of commercial monolithic Si_3N_4 for 1370°C applications has been reported as 5.5 $\text{MPa}\sqrt{\text{m}}$. Although this is an improvement over earlier materials of similar grade, further improvements in fracture toughness are warranted. As shown in Figure 38 increases in toughness will result in a more flaw tolerant material. A material with a toughness of $>10 \text{ MPa}\sqrt{\text{m}}$ would greatly increase the flaw tolerance of Si_3N_4 . To further increase fracture toughness additional research and development efforts would be necessary. Recommendations as to future needs are summarized below.

REINFORCEMENT

- 1) There is a continued need for a stable source of commercially available SiC whiskers. Currently there are only two commercially available sources of SiC and both are owned by Japanese Corporations. During the course of our 3 year project at least 15 different suppliers of SiC whiskers were evaluated. The instability of this field makes it difficult to develop composite materials.
- 2) As reported by Tiegs et. al.⁶⁰ the currently available SiC whiskers are not defect free. As a result their strength is compromised. There is a need for an improved SiC whisker with high strength. Without the high strength whisker, further improvements in the fracture toughness of ceramic matrix composites will be limited.
- 3) We have demonstrated that carbon fiber can be used to toughen Si_3N_4 . Although it will have high temperature limitations, the system of carbon fiber reinforced Si_3N_4 can be further evaluated to determine reinforcement requirements for toughening Si_3N_4 . Carbon fiber is available in a range of diameters, moduli, and strengths. This data could then be used as a guide for SiC whisker development.
- 4) Another reinforcement which should be reevaluated for its effectiveness in toughening Si_3N_4 is the Los Alamos Laboratory SiC whisker material. This whisker with its known high strength would be valuable in determining reinforcement property requirements for toughening Si_3N_4 .

INTERFACE

- 1) The deposition of a thin (~35nm) amorphous boron-nitrogen-carbon containing layer onto SiC whiskers by a polymer pyrolysis route was demonstrated in this program. At this time there is a very limited quantity of the polymer precursor available. Because of the potential for much lower cost when compared to CVD, this coating technique should be further developed and evaluated for its potential as a debonding interface layer.
- 2) There is still a need to determine if other interface materials besides BN and carbon will improve the toughness of SiC whisker reinforced Si_3N_4 . Initial screening studies in this project showed that ductile interfaces can blunt cracks. Further efforts in this area are warranted.

OTHER

- 1) Recent developments in high temperature Si_3N_4 monoliths have demonstrated fracture toughness up to $\sim 6.0 \text{ MPa}\sqrt{\text{m}}$.⁵ Three years ago comparable materials had a fracture toughness of $4.6 \text{ MPa}\sqrt{\text{m}}$. Considering this progress, it would be worthwhile to further investigate increasing the fracture toughness of HIP'ed Monolithic materials through process modifications.
- 2) In addition to the need for toughened Si_3N_4 materials there is also a need for a material with non-catastrophic failure. A program to develop such a material with a discontinuous reinforcement phase would be valuable to the aerospace industries.

Figure 38 Relationship between failure stress, surface crack size, and fracture toughness.

9.0 ACKNOWLEDGMENTS

We would like to acknowledge Ms. R. Harrington, Mr. N. Arsenault, Mr. L. Ton, Mr. P. Gulati, Mr. P. Pelletier and Mr. D. Truedson for their technical support in the areas of material processing and Norton Company's analytical support groups for materials evaluations. Auger Chemical Analysis was performed at Geller Microanalytical Laboratories and Oak Ridge National Laboratories. ESCA Analysis was performed at Photometrics Incorporated.

Discussion and guidance by Dr. S. D. Hartline and R. L. Yeckley were very helpful in understanding the complexities of these materials. Preparation of the manuscript by Ms. R. Gordon is greatly appreciated.

The research was sponsored by the U.S. Department of Energy, Assistant Secretary for Conservation and Renewable Energy, Office of Transportation Systems, as part of the Ceramic Technology for Advanced Heat Engines Project of the Advanced Materials Development Program, under contract DE-AC05-84OR21400 with Martin Marietta Energy Systems, Inc.

10.0 REFERENCES

1. L. M. Sheppard, "Sialon", Adv. Mat. and Proc., 35-39 (January 1986).
2. M. Iwasa, and T. Watanabe, "Effects of MgO Content on properties of Hot Pressed Silicon Nitride," Yogyo-Kyokai-Shi, 95, 6, 652 (1987).
3. G. Wotting and G. Ziegler, "Characterization of Microstructural Variables of Sintered, Hot-Pressed, and Hot-Isostatically Pressed Si_3N_4 and their Correlation with Mechanical Properties," Science of Ceramics 12, edited by P. Vincenzini, 361-370 (1983).
4. N. D. Corbin and C. A. Willkens, "Development of Toughened Si_3N_4 Composites by Glass Encapsulated Hot Isostatic Pressure Final Report," ORNL/SUB/86-95906/1 (August 1988).
5. B. J. McEntire, et. al., "Silicon Nitride Component Development for Advanced Gas Turbine Engines," to be published in the Proceedings of the 27th Automotive Technology Development Contractors' Coordination Meeting, P-230, SAE International, Warrendale, PA, p.341 (April 1990).
6. L. E. Davis, et. al., "Handbook of Auger Electron Spectroscopy 2nd Edition," Published by Physical Electronics Div. of Perkin-Elmer, Eden Prairie, MN (1978).
7. Handbook of X-ray Photoelectron Spectroscopy, Ed. G. E. Muilenberg, Pub. Perkin-Elmer Corp., Eden Prairie, MN.
8. MIL-STD-1942 (MR), "Flexural Strengths of High Performance Ceramics at Ambient Temperature," (November 21, 1983).
9. G. Antis, et. al., "A Critical Evaluation of Indentation Techniques for Measuring Fracture Toughness: I, Direct Crack Measurements," J. Amer. Ceram. Soc., 64, 9, 533-538 (September 1981).
10. P. Chantikul, et. al., "A Critical Evaluation of Indentation Techniques for Measuring Fracture Toughness: II, Strength Method," J. Amer. Ceram. Soc., 64, 9, 539-543 (September 1981).
11. J. E. Srawley and B. Gross, "Cracks and Fracture," STP 601, ASTM, Philadelphia, PA, 559-579 (1976).
12. J. Bluhm, "Slice Synthesis of a Three Dimentional Work of Fracture Specimen," Eng. Frac. Mech., 2, Pergamon Press, Great Britain, 593-604 (1978).

13. J. A. Salem and J. L. Shannon, Jr., "Fracture Toughness of Si_3N_4 measured with short bar chevron notched specimens," J. Mat. Sci., 22, 321-324 (1987).
14. J. Sung and P. S. Nicholson, "Valid K_{Ic} Determination Via In-Test Subcritical Precracking of Chevron Notch Bend Bars," J. Am. Ceram. Soc., 72, 6, 1033-1036 (1989).
15. Courtesy of M. Ferber, Oak Ridge National Laboratory, Oak Ridge, TN (January 1990).
16. R. F. Cook and B. R. Lawn, "A Modified Indentation Toughness Technique," Comm. Amer. Ceram. Soc., 11, C200-C2011 (1983).
17. N. J. Shaw and J. A. Salem, "Toughened Ceramics Life Prediction," Ceramic Technology for Advanced Heat Engines Project Semiannual Progress Report for April through September 1988, ORNL/TM-1116, 322-329 (March 1989).
18. Courtesy of A. H. Heuer, Case Western Reserve University, Cleveland, OH (November 18, 1988).
19. A. G. Evans and E. A. Charles, "Fracture Toughness Determinations by Indentation," J. Amer. Cer. Soc., - Discussions and Notes, 59, 7-8, 371-2 (1976).
20. T. Nose and T. Fujii, "Evaluation of Fracture Toughness for Ceramic Materials by a Single-Edge-Precracked-Beam Method," J. Amer. Cer. Soc., 71, 5, 328-33 (1988).
21. Courtesy of I. Bar-on, Worcester Polytechnic Institute, Worcester, MA (August 2, 1989).
22. G. D. Quinn, "Guide to the Construction of a Simple 1500°C Test Furnace," U. S. Army Materials Technology Laboratory, AMMRC, TR83-1, NTIS ADA 125636 (January 1983).
23. G. D. Quinn, "Characterization of Turbine Ceramics after Long-Term Environment Exposure," U. S. Army Materials Technology Laboratory, AMMRC, TR80-15, AD A117463 (April 1983).
- 23b. H. Larker et. al., "Method of Manufacturing an Object of Metallic or Ceramic Material," U.S. Patent # 4,446,100, May 1, 1984.
24. S. R. Nutt, "Defects in Silicon Carbide Whiskers," J. Amer. Ceram. Soc., 67, 6, 428-431 (June 1984).
- 24b. S. R. Nutt, "Microstructure and Growth Model for Rice-Hull-Derived SiC Whiskers," J. Am. Ceram. Soc., 71, [3], 149-56 (1988).

25. R. Lundberg, R. Pompe, and R. Carlsson, "HIP'ed Carbon Fiber Reinforced Silicon Nitride Composites," Cer. Eng. Sci. Proc., 9, 7-8, 901-906 (1988).
26. K. T. Faber and A. G. Evans, "Crack Deflection Processes - I. Theory," Acta. Metall., 31, 4, 565-576 (1983).
27. C. A. Willkens, et. al., "The Influence of Microstructure Orientation on the Fracture Toughness of Si_3N_4 Based Materials," Cer. Eng. and Sci. Proc., 9, 9-10, 1367 (1988).
28. N. D. Corbin, et. al., "The Influence of Reinforcement Orientation on the Toughness of Si_3N_4 Matrix Composites," in The conference Proceedings of Whisker and Fiber Toughened Ceramics, E. R. Bradley, et. al., ASM International, 131 (1988).
29. P. L. Swanson, et. al., "Crack-Interface Grain Bridging as a Fracture Resistance Mechanism in Ceramics: I, Experimental Study on Alumina," J. Amer. Ceram. Soc., 70, 4, 279-89 (1987).
30. V. K. Pujari, et. al., "Injection Molding of Si_3N_4 -SiC Whisker Composites," presented at The 89th Annual Meeting of the Amer. Cer. Soc., Pittsburgh, PA, paper 37-C, (April 27, 1987).
31. S. T. Buljan, et. al., "SiC Whisker-Reinforced Si_3N_4 ," in conference Proceedings of the 25th Automotive Technology Development Contractors' Coordination Meeting, P-209, published by SAE, Warrendale, PA, 137 (1988).
32. Courtesy of Prof. M. Ruhle and G. Campbell, University of California - Santa Barbara.
33. T. N. Tiegs, et. al., "Interfaces in Alumina-SiC Whisker Composites," ORNL Report #CONF-860714-3 (1986).
34. M. Yamamoto, et. al., "Characterization of Surface-Coated Carbide Whiskers for Toughening Ceramics," in the conference Proceedings of Whisker and Fiber Toughened Ceramics, Published by ASM International, Edited by R. A. Bradley, et. al., 73-79 (1988).
35. N. D. Corbin, et. al., "Microstructure/Property Relationships for SiC Filament-Reinforced RBSN," Cer. Eng. Sci. Proc., 7, 7-8, 958-968 (1986).
36. H. Landis, et. al., "Effect of Metal Coatings on Silicon Carbide Fiber Strength," SAMPE Quarterly, 19 (July 1981).

37. R. W. Rice, "BN Coating of Ceramic Fibers for Ceramic Fiber Composites," U. S. Patent #4,642,271 (February 10, 1987).

38. Synterials, Herndon, VA.

39. M. F. Hawthorne, Department of Chemistry, University of California at Los Angeles.

40. L. H. Jansen, Callery Chemical Company Div. of Mine Safety Appliances, Pittsburg, PA.

41. Courtesy of R. Padgett, High Temperature Materials Laboratory, Metals and Ceramics Division, Oak Ridge National Laboratory, Oak Ridge, TN.

42. R. M. A. Lieth, Ed., Preparation and Crystal Growth of Materials with Layered Structures, D. Reidel Publishing Company, Dordrecht, Holland (1977).

43. J. K. Kim, P. Greil and G. Petzow, "Formation and Characteristics of Silicon Nitride-Lithium Aluminum Silicate Ceramics: Part I. Sintering and Microstructure," v. Ceram. Mat., 2, 4, 817-821 (1987).

44. P. Predecki, A. Abuhosan, C. S. Barnett, to be published in Advances in X-ray Analysis.

45. Z. Li and R. C. Bradt, "Micromechanical Residual Stresses in SiC whisker reinforced Mullite Matrix and Si_3N_4 Matrix Composites," in the Proceedings of Whisker- and Fiber-Toughened Ceramics, Published by ASM International, Editors R. A. Bradley, et. al., 289-298 (June 7-9, 1988).

46. C. Hsueh, P. F. Becher, P. Angelini, "Effects of Interfacial Films on Thermal Stresses in Whisker Reinforced Ceramics," J. Amer. Ceram. Soc., 71, 11, 929-33 (1988).

47. K. N. Siebein and R. L. Yeckley, "Electron Microscopy Techniques for the Microstructural Characterization of Silicon Nitride," in Proceedings of the Gas Turbine and Aeroengine Congress, Amsterdam, The Netherlands, ASME New York (June 6-9, 1988).

48. C. R. Hubbard, et. al., "Anisotropic Thermal Expansion of $\text{Y}_2\text{Si}_2\text{O}_7$ and $\text{Y}_5(\text{SiO}_4)_3\text{N}$ by High Temperature X-ray Diffraction," presented at The 38th Denver X-ray Conference, Denver, CO (August 4, 1989).

49. J. T. Smith and C. L. Quackenbush, "Phase Effects in Si_3N_4 Containing Y_2O_3 or CeO_2 : I, Strength," Cer. Soc. Bull., 59, 5, 529 (1980)
50. D. Taylor, "Thermal Expansion Data XIII. Complex Oxides with Chain, Ring and Layer Structures and the Apatites," Brit. Ceram. Trans. and Journal, 8, 3, 81-110 (1987).
51. R. R. Wills, et. al., "Phase Relationships in the System Si_3N_4 - Y_2O_3 - SiO_2 ," J. Mat. Sci., 11, 1305-1309 (1976).
52. H. M. O'Bryan, P. K. Gallagher, and G. W. Berkstresser, "Thermal Expansion of Y_2SiO_5 Single Crystals," J. Am. Ceram. Soc., 17, 1, C42-C43 (1988).
53. Z. Li, R. C. Bradt, "Thermal Expansion of the Hexagonal (4H) Polytype of SiC ," to be published in the Journal of Applied Physics.
54. D. R. Messier, "Review of Oxynitride Glasses," Revue de Chimie Minerale, 22, 518-533 (1985).
55. R. E. Loehman, "Preparation and Properties of Yttrium-Silicon-Aluminum Oxynitride Glasses," J. Amer. Ceram. Soc., 62, 9-10, 491-494 (1979).
56. D. Taylor, "Thermal Expansion Data-XI. Complex Oxides, A_2BO_5 , and the Garnets," Trans. J. Brit. Ceram. Soc., 86, 1, 1-6 (1987).
57. S. D. Nunn and T. Y. Tien, "Fabrication of $\text{Si}_3\text{N}_4/\text{SiC}$ Composites by Transient Liquid Phase Sintering," to be published in The Ceramic Technology for Advanced Heat Engines Project Semiannual Progress Report for April 1989 through September 1989, Oak Ridge National Laboratory.
58. C. M. B. Henderson and D. Taylor, "Thermal Expansion of the Nitrides and Oxynitride of Silicon in Relation to Their Structures," Trans. J. Brit. Cer. Soc., 74, 49-53 (1975).
59. H. Knoch and G. Gazza, "Carbon Impurity Effect on the Thermal Degradation of a Si_3N_4 - Y_2O_3 Ceramic," AMMRC TR #79-27, Army Materials and Mechanics Research Center, Watertown, MA (May 1979).
60. T. Teigs, "Identification and Development of Optimum SiC Whiskers for Si_3N_4 Matrix Composites," Published in Proceedings of the 27th Automotive Technology Development Contractors' Meeting, P-230, SAE International, Warrendale, PA, April, p.167 (1980).

INTERNAL DISTRIBUTION

1-2.	Central Research Library	42.	M. G. Jenkins
3.	Document Reference Section	43.	D. R. Johnson
4-5.	Laboratory Records Department	44.	W. F. Jones
6.	Laboratory Records, ORNL RC	45.	D. Joslin
7.	ORNL Patent Section	46.	R. R. Judkins
8-10.	M&C Records Office	47.	M. A. Karnitz
11.	L. F. Allard, Jr.	48.	M. R. Kass
12.	L. D. Armstrong	49-53.	B. L. P. Keyes
13.	P. F. Becher	54.	H. D. Kimrey, Jr.
14.	R. F. Bernal	55.	T. G. Kollie
15.	T. M. Besmann	56.	K. C. Liu
16.	P. J. Blau	57.	E. L. Long, Jr.
17.	A. Bleier	58.	W. D. Manly
18.	E. E. Bloom	59.	R. W. McClung
19.	K. W. Boling	60.	D. J. McGuire
20.	R. A. Bradley	61.	J. R. Merriman
21.	C. R. Brinkman	62.	D. L. Moses
22.	V. R. Bullington	63.	T. A. Nolan
23.	R. S. Carlsmith	64.	A. E. Pasto
24.	P. T. Carlson	65.	J. L. Rich
25.	G. M. Caton	66.	C. R. Richmond
26.	S. J. Chang	67.	J. M. Robbins
27.	R. H. Cooper, Jr.	68.	M. L. Santella
28.	B. L. Cox	69.	A. C. Schaffhauser
29.	D. F. Craig	70.	S. Scott
30.	S. A. David	71.	G. M. Slaughter
31.	J. H. DeVan	72.	E. J. Soderstrom
32.	J. L. Ding	73.	D. P. Stinton
33.	M. K. Ferber	74.	R. W. Swindeman
34.	F. M. Foust	75.	V. J. Tennery
35.	W. Fulkerson	76.	T. N. Tiegs
36.	R. L. Graves	77.	J. R. Weir, Jr.
37.	D. L. Greene	78.	B. H. West
38.	M. H. Harris	79.	F. W. Wiffen
39.	E. E. Hoffman	80.	S. G. Winslow
40.	C. R. Hubbard	81.	J. M. Wyrick
41.	M. A. Janney	82.	C. S. Yust

EXTERNAL DISTRIBUTION

83. James H. Adair
University of Florida
Materials Science and
Engineering
317 MAE Bldg.
Gainesville, FL 32611-2066
84. Donald F. Adams
University of Wyoming
Mechanical Engineering
Department
P. O. Box 3295
Laramie, WY 82071
85. Jalees Ahmad
AdTech Systems Research, Inc.
1342 North Fairfield Road
Dayton, OH 45432-2698
86. Yoshio Akimune
NISSAN Motor Co., Ltd.
Materials Research Laboratory
1 Natsushima-Cho
Yokosuka 237
JAPAN AIR MAIL
87. Mufit Akinc
Iowa State University
322 Spedding Hall
Ames, IA 50011
88. Ilhan A. Aksay
University of Washington
Materials Science and Engineering
Department, FB-10
Seattle, WA 98195
89. R. G. Alexander
BASE
26 Malvern Close
Kettering Northants NN16 8JP
UNITED KINGDOM AIR MAIL
90. Richard L. Allor
Ford Motor Company
Material Systems
Reliability Department
20000 Rotunda Drive
P.O. Box 2053, Room S-2031
Dearborn, MI 48121-2053
91. Richard T. Alpaugh
U.S. Department of Energy
Advanced Propulsion Division
CE-322, Forrestal Building
Washington, DC 20585
92. Joseph E. Amaral
Instron Corporation
Corporate Engineering Office
100 Royale Street
Canton, MA 02021
93. Edward M. Anderson
Aluminum Company of America
North American Industrial
Chemicals Division
P.O. Box 300
Bauxite, AR 72011
94. Norman C. Anderson
Ceradyne, Inc.
Ceramic-to-Metal Division
3169 Redhill Avenue
Costa Mesa, CA 92626
95. Don Anson
Battelle Columbus Laboratories
Thermal Power Systems
505 King Avenue
Columbus, OH 43201-2693
96. Thomas Arbanas
G.B.C. Materials Corporation
580 Monastery Drive
Latrobe, PA 15650-2698
97. Frank Armatiss
3M Company
3M Center
Building 60-1N-01
St. Paul, MN 55144-1000
98. Everett B. Arnold
Detroit Diesel Corporation
Mechanical Systems Technology
13400 Outer Drive, West
Detroit, MI 48239-4001
99. Richard M. Arons
PA Consulting Group
279 Princeton Road
Hightstown, NJ 08550

100. Bertil Aronsson
Sandvik AB
S-12680
Stockholm Lerkrogsvagen 19
SWEDEN AIR MAIL
101. Dennis Assanis
University of Illinois
Department of Mechanical
Engineering
1206 W. Green Street
Urbana, IL 61801
102. William H. Atwell
Dow Corning Corporation
3901 South Saginaw Road
MS:540
Midland, MI 48686-0995
103. V. S. Avva
North Carolina A&T State
University
Department of Mechanical
Engineering
Greensboro, NC 27411
104. Patrick Badgley
Adiabatics, Inc.
3385 Commerce Drive
Columbus, IN 47201
105. Sunggi Baik
Pohang Institute of Science
& Technology
Department of Materials
Science and Engineering
P.O. Box 125
Pohang 790-600
KOREA AIR MAIL
106. John M. Bailey
Caterpillar, Inc.
Technical Center
Building L
P.O. Box 1875
Peoria, IL 61656-1875
107. Bob Baker
Ceradyne, Inc.
3169 Redhill Avenue
Costa Mesa, CA 92626
108. Frank Baker
Aluminum Company of America
Alcoa Technical Center
Alcoa Center, PA 15069
109. J. G. Baldoni
GTE Laboratories Inc.
40 Sylvan Road
Waltham, MA 02254
110. Clifford P. Ballard
Allied-Signal, Inc.
Ceramics Program
P.O. Box 1021
Morristown, NJ 07962-1021
111. M. Balu
Amoco Performance Products Inc.
4500 McGinnis Ferry Road
Alpharetta, GA 30202
112. B. P. Bandyopadhyay
Toyohashi University of Technology
School of Production Systems
Engineering
Tempaku-Cho Toyohashi 440
JAPAN AIR MAIL
113. P. M. Barnard
Ruston Gas Turbines Limited
Metallurgical Laboratory
P. O. Box 1
Lincoln LN2 5DJ
ENGLAND AIR MAIL
114. Harold N. Barr
Hittman Corporation
9190 Red Branch Road
Columbia, MD 21045
115. Renald D. Bartoe
Vesuvius McDanel
510 Ninth Avenue
Box 560
Beaver Falls, PA 15010-0560
116. Donald M. Bartos
Dow Corning Corporation
Advanced Ceramics Program
Midland, MI 48686-0995

117. David L. Baty
Babcock & Wilcox-LRC
P.O. Box 11165
Lynchburg, VA 24506-1165
118. Donald F. Baxter, Jr.
ASM International
Advanced Materials and
Processes
Materials Park, OH 44073-0002
119. M. Brad Beardsley
Caterpillar, Inc.
Advanced Materials Technology
Technical Center Bldg. E
P.O. Box 1875
Peoria, IL 61656-1875
120. Robert Beck
Teledyne CAE
Materials Engineering/Programs
1330 Laskey Road
P.O. Box 6971
Toledo, OH 43612
121. John C. Bell
Shell Research Limited
Thornton Research Centre
P.O. Box 1
Chester, Ch1 3SH
ENGLAND AIR MAIL
122. Albert H. Bell, III
General Motors Technical Center
30200 Mound Road
Engineering Building/W3 Turbine
Warren, MI 48090-9010
123. M. Bentele
Xamag, Inc.
259 Melville Avenue
Fairfield, CT 06430
124. Larry D. Bentsen
BF Goodrich Company
R&D Center
9921 Brecksville Road
Brecksville, OH 44141
125. Joseph C. Bentz
ENCERATEC
2525 Sandcrest Drive
Columbus, IN 47203
126. Louis Beregszazi
Defiance Precision Products
P.O. Drawer 428
Defiance, OH 43512
127. Tom Bernecki
Northwestern University
BIRL
1801 Maple Avenue
Evanston, IL 60201-3135
128. Charles F. Bersch
Institute for Defense Analyses
1801 North Beauregard Street
Alexandria, VA 22311
129. Ram Bhatt
NASA Lewis Research Center
21000 Brookpark Road
Cleveland, OH 44135
130. Deane I. Biehler
Caterpillar, Inc.
Engineering and Research
Materials
Technical Center, Building E
P.O. Box 1875
Peoria, IL 61656-1875
131. John. W. Bjerklie
Consolidated Natural Gas
Service Co., Inc.
Research Department
CNG Tower
Pittsburgh, PA 15222-3199
132. William D. Bjorndahl
TRW, Inc.
One Space Park
Building 01, Room 2040
Redondo Beach, CA 90278
133. Keith A. Blakely
Advanced Refractory
Technologies, Inc.
699 Hertel Avenue
Buffalo, NY 14207
134. Edward G. Blanchard
Netzsch Inc.
119 Pickering Way
Exton, PA 19341

135. Keith Blandford
Boride Products, Inc.
2879 Aero Park Drive
Traverse City, MI 49684
136. Bruce Boardman
Deere and Company Technical
Center
3300 River Drive
Moline, IL 61265
137. Russell Bockstedt
Hoechst Celanese Corporation
150 JFK Parkway
Short Hills, NJ 07078
138. M. Boehmer
DLR German Aerospace Research
Establishment
Postfach 90 60 58
D-5000 Koln 90
GERMANY AIR MAIL
139. Lawrence P. Boesch
EER Systems Corp.
1593 Spring Hill Road
Vienna, VA 22182-2239
140. Donald H. Boone
Boone & Associates
2412 Cascade Drive
Walnut Creek, CA 94598-4313
141. Tom Booth
Allied-Signal Aerospace
Company
AiResearch Los Angeles
Division
2525 West 190th Street
Torrance, CA 90509-2960
142. Tibor Bornemisza
Sundstrand Power Systems
4400 Ruffin Road
San Diego, CA 92186-5757
143. J.A.M. Boulet
University of Tennessee
Department of Engineering
Science and Mechanics
310 Perkins Hall
Knoxville, TN 37996-2030
144. H. Kent Bowen
Massachusetts Institute of
Technology
77 Massachusetts Avenue
Room E40-434
Cambridge, MA 02139
145. Leslie J. Bowen
Materials Systems
53 Hillcrest-Road
Concord, MA 01742
146. Steven C. Boyce
Air Force Office of
Scientific Research
AFOSR/NA Bldg. 410
Bolling AFB DC 20332-6448
147. Gary L. Boyd
CEC
400 Howell Avenue, No. 4
Warland, WY 82401
148. Steve Bradley
UOP Research Center
50 East Algonquin Road
Des Plaines, IL 60017-6187
149. Michael C. Brands
Cummins Engine Company, Inc.
P.O. Box 3005
Mail Code 50179
Columbus, IN 47201
150. Raymond J. Bratton
Westinghouse Science and
Technology Center
1310 Beulah Road
Pittsburgh, PA 15235
151. John J. Brennan
United Technologies Corporation
Research Center
Silver Lane, MS:24
East Hartford, CT 06108
152. Jeff D. Bright
Ceramatec, Inc.
2425 South 900 West
Salt Lake City, UT 84108

153. Terrence K. Brog
Coors Ceramics Company
Corporate Development and
Technology
4545 McIntyre Street
Golden, CO 80403
154. Gunnar Broman
317 Fairlane Drive
Spartanburg, SC 29302
155. Al Brown
High-Tech Materials Alert
P.O. Box 882
Dayton, NJ 08810
156. Jesse Brown
Virginia Polytechnic Institute
and State University
Center for Advanced Ceramic
Materials
Blacksburg, VA 24061-0256
157. Sherman D. Brown
University of Illinois
Materials Science and
Engineering Department
105 South Goodwin Avenue
204 Ceramics Building
Urbana, IL 61801
158. S. L. Bruner
Ceramatec, Inc.
2425 South 900 West
Salt Lake City, UT 84119
159. Adolfo Brusaferro
Keramont Corporation
4231 South Fremont Avenue
Tucson, AZ 85714
160. W. Bryzik
U.S. Army Tank Automotive
Command
R&D Center
Propulsion Systems Division
Warren, MI 48397-5000
161. S. T. Buljan
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
162. S. J. Burden
GTE Valenite
1711 Thunderbird
Troy, MI 48084
163. Curt V. Burkland
AMERCOM, Inc.
8928 Fullbright Avenue
Chatsworth, CA 91311
164. Bill Bustamante
AMERCOM, Inc.
8928 Fullbright Street
Chatsworth, CA 91311
165. Oral Buyukozturk
Massachusetts Institute of
Technology
77 Massachusetts Avenue
Room 1-280
Cambridge, MA 02139
166. David A. Caillet
Ethyl Corporation
451 Florida Street
Baton Rouge, LA 70801
167. Frederick J. Calnan
Heany Industries, Inc.
249 Briarwood Lane
P.O. Box 38
Scottsville, NY 14546
168. Roger Cannon
Rutgers University
Ceramics Department
P.O. Box 909
Piscataway, NJ 08855-0909
169. Scott Cannon
P.O. Box 567254
Atlanta, GA 30356
170. Harry W. Carpenter
19945 Acre Street
Northridge, CA 91324
171. David Carruthers
Kyocera Industrial Ceramics
Company
P.O. Box 2279
Vancouver, WA 98668-2279

172. Calvin H. Carter, Jr.
Cree Research, Inc.
2810 Meridian Parkway
Durham, NC 27713
173. J. David Casey
35 Atlantis Street
West Roxbury, MA 02132
174. Jere G. Castor
J. C. Enterprise
5078 North 83rd Street
Scottsdale, AZ 85250
175. James D. Cawley
Case Western Reserve University
Materials Science and
Engineering Department
Cleveland, OH 44106
176. Thomas C. Chadwick
Den-Mat Corporation
P.O. Box 1729
Santa Maria, CA 93456
177. Ronald H. Chand
Chand Kare Technical Ceramics
2 Coppage Drive
Worcester, MA 01603
178. Robert E. Chaney
EG&G Idaho, Inc.
Idaho National Engineering
Laboratory
P.O. Box 1625
Idaho Falls, ID 83415-3525
179. Frank C. Chang
U.S. Army Materials
Technology Laboratory
AMTL-EMM
405 Arsenal Street
Watertown, MA 02172
180. Robert M. Chapman
Allied-Signal Aerospace
Company
1530 Wilson Boulevard,
10th Floor
Arlington, VA 22209
181. William Chapman
Williams International
Corporation
2280 West Maple Road
Walled Lake, MI 48390-0200
182. Charlie Chen
LECO Corporation
P.O. Box 211688
Augusta, GA 30917
183. Albert A. Chesnes
U.S. Department of Energy
Transportation Technologies
CE-30, Forrestal Building,
6B-094
Washington, DC 20585
184. Kaiyin Chia
Carborundum Company
P.O. Box 832
Niagara Falls, NY 14302
185. Frank Childs
EG&G Idaho, Inc.
Idaho National Engineering
Laboratory
P.O. Box 1625
Idaho Falls, ID 83415-3527
186. William J. Chmura
Torrington Company
59 Field Street
Torrington, CT 06790-4942
187. Tsu-Wei Chou
University of Delaware
Center for Composite
Materials
201 Spencer Laboratory
Newark, DE 19716
188. R. J. Christopher
Ricardo Consulting Engineers
Bridge Works
Shoreham-By-Sea West Sussex
BN43 5FG
ENGLAND AIR MAIL
189. Joel P. Clark
Massachusetts Institute of
Technology
Room 8-409
Cambridge, MA 02139

190. Giorgio Clarotti
Commission of the European
Communities
DGXII-C3, M075, 1-53;
200 Rue de la Loi
B-1049 Brussels
BELGIUM AIR MAIL
191. W. J. Clegg
ICI Advanced Materials
P.O. Box 11
The Heath, Runcorn Cheshire
WA7 4QE
ENGLAND AIR MAIL
192. Joseph Cleveland
GTE Products Corporation
Hawes Street
Towanda, PA 18848-0504
193. Gloria M. Collins
ASTM
1916 Race Street
Philadelphia, PA 19103
194. William C. Connors
Sundstrand Aviation Operations
Materials Science and
Engineering Department
4747 Harrison Avenue
P.O. Box 7002
Rockford, IL 61125-7002
195. John A. Coppola
Carborundum Company
P.O. Box 156
Niagara Falls, NY 14302
196. Normand D. Corbin
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
197. Douglas Corey
Allied-Signal Aerospace
Company
2525 West 190th Street
MS:T52
Torrance, CA 90504-6099
198. Keith P. Costello
Chand/Kare Technical Ceramics
2 Coppage Drive
Worcester, MA 01603-1252
199. Ed L. Courtright
Pacific Northwest
Laboratory
MS:K3-59
Richland, WA 99352
200. Anna Cox
Mitchell Market Reports
P.O. Box 23
Monmouth Gwent NP5 4YG
UNITED KINGDOM AIR MAIL
201. Thomas Coyle
Unocal Corporation
Unocal Science & Technology
Division
376 South Valencia Avenue
Brea, CA 92621
202. Art Cozens
Instron Corporation
3414 Snowden Avenue
Long Beach, CA 90808
203. Robert C. Craft
American Ceramic
Society, Inc.
757 Brooksedge Plaza Drive
Westerville, OH 43081
204. Mark Crawford
New Technology Week
4604 Monterey Drive
Annandale, VA 22003
205. Richard A. Cree
Markets & Products, Inc.
P.O. Box 14328
Columbus, OH 43214-0328
206. Les Crittenden
Vesuvius McDanel
Box 560
Beaver Falls, PA 15010

207. William J. Croft
U.S. Army Materials
Technology Laboratory
405 Arsenal Street
Watertown, MA 02172
208. M. J. Cronin
Mechanical Technology, Inc.
968 Albany-Shaker Road
Latham, NY 12110
209. Gary M. Crosbie
Ford Motor Company
1430 Culver Avenue
S-2079, SRL Building
Dearborn, MI 48121-4036
210. Floyd W. Crouse, Jr.
U.S. Department of Energy
Morgantown Energy
Technology Center
Collins Ferry Road
P.O. Box 880
Morgantown, WV 26505
211. John Cuccio
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
P.O. Box 5227, MS:1302-2Q
Phoenix, AZ 85010
212. Raymond Cutler
Ceramatec, Inc.
2425 South 900 West
Salt Lake City, UT 84119
213. Charles D'Angelo
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02154
214. Stephen C. Danforth
Rutgers University
Ceramic Engineering Department
P.O. Box 909
Piscataway, NJ 08855-0909
215. Sankar Das Gupta
Electrofuel Manufacturing
Co., Ltd.
9 Hanna Avenue
Toronto Ontario MGK-1W8
CANADA AIR MAIL
216. Charles Davis
Sverdrup Technology,
Inc., MSFC
620 Discovery Drive
Huntsville, AL 35806
217. Frank Davis
Allied Signal Aerospace Co.
7550 Lucerne Dr., # 203
Middleburg Heights, OH 44130
218. Robert F. Davis
North Carolina State
University
Materials Engineering
Department
229 Riddick Laboratory
P.O. Box 7907
Raleigh, NC 27695
219. Thomas DeAngelis
Carborundum Company
Niagara Falls R&D Center
P.O. Box 832
Niagara Falls, NY 14302
220. George DeBell
Ford Motor Company
Material Systems Reliability
Department
20000 Rotunda Drive
P.O. Box 2053, Room S-2023
Dearborn, MI 48121-2053
221. Michael DeLuca
AMP-AKZO
West Lane
Aquebogue, NY 11931
222. Gerald L. DePoorter
Colorado School of Mines
Metallurgical and Materials
Engineering Department
Golden, CO 80401

223. J. F. DeRidder
Omni Electro Motive, Inc.,
12 Seely Hill Road
Newfield, NY 14867
224. Nick C. Dellow
Materials Technology
Publications
40 Sotheron Road
Watford Herts WD1 2QA
UNITED KINGDOM AIR MAIL
225. L. R. Dharani
University of Missouri-Rolla
224 M.E.
Rolla, MO 65401
226. Douglas A. Dickerson
Union Carbide Specialty
Powders
1555 Main Street
Indianapolis, IN 46224
227. John Dodsworth
Vesuvius Research &
Development
Technical Ceramics Group
Box 560
Beaver Falls, PA 15010
228. B. Dogan
Institut fur Werkstofforschung
GKSS-Forschungszentrum
Geesthacht GmbH
Max-Planck-Strasse
D-2054 Geesthacht
GERMANY AIR MAIL
229. Jean-Marie Drapier
FN Moteurs S.A.
Material and Processing
B-4041 Milmort (Herstal)
BELGIUM AIR MAIL
230. Kenneth C. Dreitlein
United Technologies
Research Center
Silver Lane
East Hartford, CT 06108
231. Robin A.L. Drew
McGill University
Department of Mining and
Metallurgical Engineering
3450 University Street
Montreal Quebec H3A 2A7
CANADA AIR MAIL
232. Winston H. Duckworth
BCL
Columbus Division
505 King Avenue
Columbus, OH 43201-2693
233. Edmund M. Dunn
Texel Company
6 Third Street
Lexington, MA 02173
234. Bill Durako
Sundstrand Aviation Operations
Department 789-6
4747 Harrison Avenue
P.O. Box 7002
Rockford, IL 61125-7002
235. Ernest J. Duwell
212 Elm Street
Hudson, WI 54016
236. Chuck J. Dziedzic
Coors Ceramics Company
Structural Products Group
17750 West 32nd Avenue
Golden, CO 80401
237. Robert J. Eagan
Sandia National Laboratories
Engineered Materials &
Processes Center
Org 1700
P.O. Box 5800
Albuquerque, NM 87185-5800
238. Jeffrey Eagleson
Lanxide Corporation
1001 Connecticut Avenue, N.W.
Washington, DC 20036

239. Harry E. Eaton
United Technologies Corporation
Research Center
Silver Lane
East Hartford, CT 06108
240. Harvill C. Eaton
Louisiana State
University
Office of Research
and Economic Development
240 Thomas Boyd Hall
Baton Rouge, LA 70803
241. Christopher A. Ebel
Carborundum Company
Technology Division
P.O. Box 337
Niagara Falls, NY 14302
242. J. J. Eberhardt
U.S. Department of Energy
Office of Transportation
Materials
CE-34, Forrestal Building
Washington, DC 20585
243. Jim Edler
Eaton Corporation
26201 Northwestern
Highway
P.O. Box 766
Southfield, MI 48037
244. William A. Ellingson
Argonne National Laboratory
Materials Science & Technology
Division
9700 South Cass Avenue
Argonne, IL 60439
245. William S. Ellis
Machined Ceramics
629 N. Graham St.
N. Industrial Park
Bowling Green, KY 42101
246. Glen B. Engle
Nuclear & Aerospace Materials
Corporation
16716 Martincoit Road
Poway, CA 92064
247. Jeff Epstein
Ceramic Technologies, Inc.
2107 Jamara Lane
Houston, TX 77077
248. Kenneth A. Epstein
Dow Chemical U.S.A.
Ceramics and Advanced
Materials
800 Building
Midland, MI 48667
249. Art Erdemir
Argonne National Laboratory
Materials and Components
Technology Division
9700 South Cass Avenue
Argonne, IL 60439
250. E. M. Erwin
Lubrizol Corporation
1819 East 225th Street
Euclid, OH 44117
251. Kenji Esaki
Toyota Technical Center
U.S.A., Inc.
2000 Town Center, Suite 500
Southfield, MI 48075
252. Jose L. Escalante
Anglo-Mex-Tech. Inc.
3923 N.W. 24th Street
Miami, FL 33142
253. John N. Eustis
U.S. Department of Energy
Industrial Energy Efficiency
Division
CE-221, Forrestal Building
Washington, DC 20585
254. Robert C. Evans
NASA Lewis Research Center
Terrestrial Propulsion Office
21000 Brookpark Road, MS:86-6
Cleveland, OH 44135
255. W. L. Everitt
Kyocera International, Inc.
8611 Balboa Avenue
San Diego, CA 92123

256. Gordon Q. Evison
332 South Michigan Avenue
Suite 1730
Chicago, IL 60604
257. John W. Fairbanks
U.S. Department of Energy
Advanced Propulsion Division
CE-322, Forrestal Building
Washington, DC 20585
258. Tim Fawcett
Dow Chemical Company
Central Research, Advanced
Ceramics Laboratory
1776 Building
Midland, MI 48674
259. Robert W. Fawley
Sundstrand Power Systems
Division of Sundstrand
Corporation
4400 Ruffin Road
P.O. Box 85757
San Diego, CA 92186-5757
260. John J. Fedorchak
GTE Products Corporation
Hawes Street
Towanda, PA 18848-0504
261. Jeff T. Fenton
Vista Chemical Company
900 Threadneedle
Houston, TX 77079
262. Larry Ferrell
Babcock & Wilcox
Old Forest Road
Lynchburg, VA 24505
263. Raymond R. Fessler
BIRL
Industrial Research Lab
1801 Maple Avenue
Evanston, IL 60201
264. Michelle Finch
E. I. DuPont de Nemours &
Company, Inc.
Experimental Station
Information Center E302/301
Wilmington, DE 19898
265. Arthur D. Fine
United Technologies Corporation
Pratt & Whitney Aircraft
400 Main Street
MS:163-10
East Hartford, CT 06108
266. Ross F. Firestone
Ross Firestone Company
188 Mary Street
Winnetka, IL 60093-1520
267. Sharon L. Fletcher
Arthur D. Little, Inc.
15 Acorn Park
Cambridge, MA 02140-2390
268. Thomas F. Foltz
Textron Specialty Materials
2 Industrial Avenue
Lowell, MA 01851
269. Renee G. Ford
Materials and Processing Report
P.O. Box 72
Harrison, NY 10528
270. John Formica
Supermaterials
2020 Lakeside Avenue
Cleveland, OH 44114
271. Jennifer M. Fox
Dyson Refractories Limited
R&D Laboratory
Owler Bar
Sheffield S17 3BJ
UNITED KINGDOM AIR MAIL
272. Edwin Frame
Southwest Research Institute
Division 2
P.O. Drawer 28510
San Antonio, TX 78284
273. Armanet Francois
French Scientific Mission
4101 Reservoir Road, N.W.
Washington DC 20007-2176
274. R. G. Frank
Technology Assessment Group
10793 Bentley Pass Lane
Loveland, OH 45140

275. David J. Franus
Forecast International
22 Commerce Road
Newtown, CT 06470
276. Marc R. Freedman
NASA Lewis Research Center
21000 Brookpark Road
MS:49-3
Cleveland, OH 44135
277. Douglas Freitag
LTV Missiles Division
P.O. Box 650003
MS:WT-21
Dallas, TX 75265
278. Brian R.T. Frost
Argonne National Laboratory
9700 South Cass Avenue
Building 900
Argonne, IL 60439
279. Lawrence R. Frost
Instron Corporation
100 Royall Street
Canton, MA 02021
280. George A. Fryburg
Norton/TRW Ceramics
7A-4 Raymond Avenue
Salem, NH 03079
281. Xiren Fu
Shanghai Institute of Ceramics
Chinese Academy of Sciences
1295 Ding-xi Road
Shanghai 200050
CHINA AIR MAIL
282. John Gahimer
P.O. Box 1302
Dublin, OH 43017
283. J. P. Gallagher
University of Dayton Research
Institute
300 College Park, JPC-250
Dayton, OH 45469-0120
284. Tom Garritano
University of Tennessee
Science Alliance
101 South College
Knoxville, TN 37996-1328
285. Joy A. Garwood
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
286. H. Maury Gatewood
Reynolds Metals Company
Corporate R&D
Fourth and Canal Streets
P.O. Box 27003
Richmond, VA 23261
287. L. J. Gauckler
ETH-Zurich
Sonneggstrasse 5
CH-8092 Zurich 8092
SWITZERLAND AIR MAIL
288. Peter A. Gaydos
Battelle Columbus Laboratories
505 King Avenue
Columbus, OH 43201
289. George E. Gazza
U.S. Army Materials
Technology Laboratory
Ceramics Research Division
405 Arsenal Street
Watertown, MA 02172-0001
290. D. Gerster
CEA-DCOM
33 Rue De La Federation
Paris 75015
FRANCE AIR MAIL
291. John Ghinazzi
Coors Technical Ceramics
Company
1100 Commerce Park Drive
Oak Ridge, TN 37830

292. Robert Giddings
General Electric Company
Research Laboratory
P.O. Box 8
Schenectady, NY 12301
293. A. M. Glaeser
University of California
Materials Science and Mineral
Engineering
Lawrence Berkeley Laboratory
Hearst Mining Building
Berkeley, CA 94720
294. Paul Glance
Concept Analysis
R&D
950 Stephenson Highway
Dupont Automotive Development
Building
Troy, MI 48007-7013
295. Joseph W. Glatz
Naval Air Propulsion Center
Systems Engineering Division
P.O. Box 7176, PE24
Trenton, NJ 08628
296. W. M. Goldberger
Superior Graphite Company
R&D
2175 East Broad Street
Columbus, OH 43209
297. Allan E. Goldman
U.S. Graphite, Inc.
907 West Outer Drive
Oak Ridge, TN 37830
298. Stephen T. Gonczy
Allied Signal Research
P.O. Box 5016
Des Plaines, IL 60017
299. Jeffrey M. Gonzales
GTE Products Corporation
Hawes Street
Towanda, PA 18848-0504
300. Robert J. Gottschall
U.S. Department of Energy
ER-131, MS:G-236
Washington, DC 20545
301. Earl Graham
Cleveland State University
Department of Chemical
Engineering
Euclid Avenue at
East 24th Street
Cleveland, OH 44115
302. William A. Graham
Lanxide Corporation
P.O. Box 6077
Newark, DE 19714-6077
303. Robert E. Green, Jr.
Johns Hopkins University
Materials Science and
Engineering Department
Baltimore, MD 21218
304. Lance Groseclose
General Motors Corporation
Allison Gas Turbine Division
P.O. Box 420, MS:W-5
Indianapolis, IN 46206
305. Mark F. Gruninger
Union Carbide Corporation
Specialty Powder Business
1555 Main Street
Indianapolis, IN 46224
306. Ernst Gugel
Cremer Forschungsinstitut
GmbH&Co.KG
Oeslauer Strasse 35
D-8633 Roedental 8633
GERMANY AIR MAIL
307. Donald L. Guile
Corning Glass Works
SP-DV-1-9
Corning, NY 14831
308. Bimleshwar P. Gupta
Solar Energy Research
Institute
Mechanical and Industrial
Technology Division
1617 Cole Boulevard
Golden, CO 80401

309. John P. Gyekenyesi
NASA Lewis Research Center
21000 Brookpark Road, MS:6-1
Cleveland, OH 44135
310. Nabil S. Hakim
Detroit Diesel Corporation
13400 West Outer Drive
Detroit, MI 48239
311. Philip J. Haley
General Motors Corporation
Vehicular Engineering
P.O. Box 420, MS:T12A
Indianapolis, IN 46236
312. Judith Hall
Fiber Materials, Inc.
Biddeford Industrial Park
5 Morin Street
Biddeford, ME 04005
313. Y. Harada
IIT Research Institute
Nometallic Materials and
Composites
10 West 35th Street
Chicago, IL 60616
314. R. A. Harmon
25 Schalren Drive
Latham, NY 12110
315. Amy Harmon-Barrett
Martin Marietta Laboratories
1450 South Rolling Road
Baltimore, MD 21227
316. Norman H. Harris
Hughes Aircraft Company
P.O. Box 800520
Saugus, CA 91380-0520
317. Alan Hart
Dow Chemical Company
Advanced Ceramics Laboratory
1776 Building
Midland, MI 48674
318. Pat E. Hart
Battelle Pacific Northwest
Laboratories
Ceramics and Polymers
Development Section
P.O. Box 999
Richland, WA 99352
319. Stephen D. Hartline
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
320. Michael H. Haselkorn
Caterpillar, Inc.
Engineering Research Materials
Technical Center, Building E
P.O. Box 1875
Peoria, IL 61656-1875
321. N. B. Havewala
Corning, Inc.
SP-PR-11
Corning, NY 14831
322. John Haygarth
Teledyne WAA Chang Albany
P.O. Box 460
Albany, OR 97321
323. Norman L. Hecht
University of Dayton Research
Institute
300 College Park
Dayton, OH 45469-0172
324. Peter W. Heitman
General Motors Corporation
Allison Gas Turbine Division
P.O. Box 420, MS:W-5
Indianapolis, IN 46206-0420
325. Robert W. Hendricks
Virginia Polytechnic Institute
and State University
Materials Engineering
Department
210 Holden Hall
Blacksburg, VA 24061-0237

326. Wynne Henley
Hertel Cutting Technologies, Inc.
1000 Clearview Court
Oak Ridge, TN 37830
327. Thomas L. Henson
GTE Products Corporation
Chemical & Metallurgical
Division
Hawes Street
Towanda, PA 18848
328. Thomas P. Herbell
NASA Lewis Research Center
21000 Brookpark Road
MS:49-3
Cleveland, OH 44135
329. Marlene Heroux
Rulls-Royce, Inc.
2849 Paces Ferry Road
Suite 450
Atlanta, GA 30339-3769
330. Robert L. Hershey
Science Management Corporation
1255 New Hampshire Ave., N.W.
Suite 1033
Washington, DC 20036
331. Hendrik Heystek
Bureau of Mines
Tuscaloosa Research Center
P.O. Box L
University, AL 35486
332. Wallace C. Higgins
Norwal Unlimited
P.O. Box 1258
Alfred, NY 14802
333. Robert V. Hillery
GE Aircraft Engines
One Neumann Way, M.D. H85
Cincinnati, OH 45215
334. Arthur Hindman
Instron Corporation
100 Royall Street
Canton, MA 02021
335. Jon Hines
American Ceramic Society, Inc.
757 Brooksedge Plaza Drive
Westerville, OH 43081-6136
336. Hans Erich Hintermann
CSEM
Materials and Micromechanics
Division
Rue Breguet-2
Neuchatel 2000
SWITZERLAND AIR MAIL
337. Shinichi Hirano
Mazda R&D of North
America, Inc.
1203 Woodridge Avenue
Ann Arbor, MI 48105
338. Tommy Hiraoka
NGK Locke, Inc.
1000 Town Center
Southfield, MI 48075
339. John M. Hobday
U.S. Department of Energy
Morgantown Energy Technology
Center
Collins Ferry Road
P.O. Box 880
Morgantown, WV 26507
340. Greg Hoenes
Vista Chemical Company
900 Threadneedle
P.O. Box 19029
Houston, TX 77079-2990
341. Clarence Hoenig
Lawrence Livermore National
Laboratory
P.O. Box 808, Mail Code L-369
Livermore, CA 94550
342. Thomas Hollstein
Fraunhofer-Institut für
Werkstoffmechanik IWM
Wohlerstrabe 11
D-7800 Freiburg
GERMANY AIR MAIL

343. Richard Holt
National Research Council
of Canada
Structures and Materials
Laboratory
Ottawa Ontario K1A 0R6
CANADA AIR MAIL
344. Joseph Homeny
University of Illinois
Department of Materials Science
and Engineering
105 South Goodwin Avenue
Ceramics Building
Urbana, IL 61801
345. A. T. Hopper
Battelle Columbus
Laboratories
Metals and Ceramics Department
505 King Avenue
Columbus, OH 43201-2693
346. Michael Horgan
Materials Engineering Magazine
1100 Superior Avenue
Cleveland, OH 44114
347. Woodie Howe
Coors Technical Ceramics
Company
1100 Commerce Park Drive
Oak Ridge, TN 37830
348. Stephen M. Hsu
National Institute of
Standards and Technology
Gaithersburg, MD 20899
349. Hann S. Huang
Argonne National Laboratory
9700 South Cass Avenue
Argonne, IL 60439-4815
350. Gene Huber
Precision Ferrites & Ceramics
5576 Corporate Drive
Cypress, CA 90630
351. M. L. Huckabee
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
352. Harold A. Huckins
Princeton Advanced
Technology, Inc.
56 Finley Road
Princeton, NJ 08540
353. Fred R. Huettig
Advanced Magnetics, Inc.
45 Corey Lane
Mendham, NJ- 07945
354. Bill Huffman
Zircar
110 North Main Street
Florida, NY 10921
355. Brian K. Humphrey
Lubrizol Petroleum
Chemicals Co.
3000 Town Center, Suite 1340
Southfield, MI 48075-1201
356. Robert M. Humrick
Dylon Ceramic Technologies
3100 Edgehill Road
Cleveland Heights, OH 44118
357. Lorretta Inglehart
National Science Foundation
Division of Materials Research
1800 "G" Street, N.W.,
Room 408
Washington, DC 20550
358. Michael S. Inoue
Kyocera International, Inc.
KII Library
8611 Balboa Avenue
San Diego, CA 92123-1580
359. Osama Jadaan
University of Wisconsin-
Platteville
General Engineering Division
1 University Plaza
Platteville, WI 53818
360. Curtis A. Johnson
General Electric Company
Corporate R&D
Room MB-187
P.O. Box 8
Schenectady, NY 12301

361. Sylvia Johnson
SRI International
333 Ravenswood Avenue
Menlo Park, CA 94025
362. Thomas A. Johnson
Lanxide Corporation
1300 Marrows Road
P.O. Box 6077
Newark, DE 19714-6077
363. W. S. Johnson
Indiana University
One City Centre, Suite 200
Bloomington, IN 47405
364. Jill E. Jonkouski
U.S. Department of Energy
9800 South Cass Avenue
Argonne, IL 60439-4899
365. L. A. Joo
Great Lakes Research
Corporation
P.O. Box 1031
Elizabethton, TN 37643
366. A. D. Joseph
SPX Corporation
700 Terrace Point
Muskegon, MI 49443
367. Adam Jostsons
Australian Nuclear Science &
Technology Organization
Lucas Heights Research
Laboratories
New Illawarra Road
Lucas Heights New South Wales
AUSTRALIA AIR MAIL
368. Matthew K. Juneau
Ethyl Corporation
451 Florida Street
Baton Rouge, LA 70801
369. Hartmut Kainer
Didier-Werke AG
Anlagentechnik Wiesbaden
Abraham-Lincoln-Str. 16
D-62 Wiesbaden
GERMANY AIR MAIL
370. Tom Kalamasz
Norton/TRW Ceramics
7A-4 Raymond Avenue
Salem, NH 03079
371. Lyle R. Kallenbach
Phillips Petroleum Company
R&D
Mail Drop:123AL
Bartlesville, OK 74004
372. Nick Kamiya
Kyocera Industrial Ceramics
Corporation
2700 River Road
Des Plaines, IL 60018
373. Roy Kamo
Adiabatics, Inc.
3385 Commerce Park Drive
Columbus, IN 47201
374. S. Kang
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
375. Chih-Chun Kao
Industrial Technology Research
Institute
Materials Research
Laboratories
195 Chung-Hsing Road, Sec. 4
Chutung Hsinchu 31015 R.O.C.
TAIWAN AIR MAIL
376. Keith R. Karasek
Allied-Signal, Inc.
Engineered Materials Research
Center
50 East Algonquin Road
P.O. Box 5016
Des Plaines, IL 60017-5016
377. Robert E. Kassel
Ceradyne, Inc.
3169 Redhill Avenue
Costa Mesa, CA 92626
378. Allan Katz
Wright Laboratory
Metals and Ceramics Division
WL/MLLM
Wright-Patterson AFB, OH 45433

379. R. Nathan Katz
Worcester Polytechnic
Institute
Dept. of Mechanical
Engineering
100 Institute Road
Worcester, MA 01609
380. Ted Kawaguchi
Tokai Carbon America, Inc.
375 Park Avenue, Suite 3802
New York, NY 10152
381. Noritsugu Kawashima
TOSHIBA Corporation
Mechanical Engineering
Laboratory
4-1 Ukishima-Cho
Kawasaki-Ku Kawasaki 210
JAPAN AIR MAIL
382. Lisa Kempfer
Penton Publishing
Materials Engineering
1100 Superior Avenue
Cleveland, OH 44114-2543
383. Frederick L. Kennard, III
General Motors Corporation
AC Rochester
Department 32-24, EB
1300 North Dort Highway
Flint, MI 48556
384. David O. Kennedy
Lester B. Knight Cast
Metals Inc.
549 West Randolph Street
Chicago, IL 60661
385. George Keros
Photon Physics
3175 Penobscot Building
Detroit, MI 48226
386. Pramod K. Khandelwal
General Motors Corporation
Allison Gas Turbine
Division
P.O. Box 420, MS:W05
Indianapolis, IN 46206
387. Jim R. Kidwell
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
P.O. Box 5227
Phoenix, AZ 85010
388. Han J. Kim
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
389. Shin Kim
Korea Institute of Machinery
& Metals
66 Sangnam-dong, Changwon
Kyungnam 641-010
KOREA AIR MAIL
390. W. C. King
Mack Truck, Z-41
1999 Pennsylvania Avenue
Hagerstown, MD 21740
391. Carol Kirkpatrick
MSE, Inc.
CDIF Technical Library
P.O. Box 3767
Butte, MT 59702
392. Tony Kirn
Caterpillar, Inc.
Defense Products Department, JB7
Peoria, IL 61629
393. James D. Kiser
NASA Lewis Research Center
21000 Brookpark Road, MS:49-3
Cleveland, OH 44135
394. Max Klein
Gas Research Institute
Thermodynamics
8600 West Bryn Mawr Avenue
Chicago, IL 60631
395. Richard N. Kleiner
Coors Ceramics Company
4545 McIntyre Street
Golden, CO 80403

396. Stanley J. Klima
NASA Lewis Research Center
21000 Brookpark Road
MS:6-1
Cleveland, OH 44135
397. Chris E. Knapp
Norton Advanced Ceramics
of Canada Ltd.
8001 Daly Street
Niagara Falls, Ontario L2G 6S2
CANADA AIR MAIL
398. Albert S. Kobayashi
University of Washington
Mechanical Engineering
Department
MS:FU10
Seattle, WA 98195
399. Shigeki Kobayashi
Toyota Central Research
Labs, Inc.
Nagakute Aichi 480-11
JAPAN AIR MAIL
400. Richard A. Kole
Z-Tech Corporation
8 Dow Road
Bow, NH 03304
401. E. Kostiner
University of Connecticut
Chemistry Department, U-60
Storrs, CT 06269-3060
402. Kenneth A. Kovaly
Technical Insights, Inc.
P.O. Box 1304
Fort Lee, NJ 07024-9967
403. Ralph G. Kraft
Spraying Systems Company
North Avenue at Schmale Road
Wheaton, IL 60189-7900
404. Saunders B. Kramer
U.S. Department of Energy
Advanced Propulsion Division
CE-322, Forrestal Building
Washington, DC 20585
405. Arthur Kranish
Trends Publishing, Inc.
1079 National Press Building
Washington, DC 20045
406. A. S. Krieger
Radiation Science, Inc.
P.O. Box 293
Belmont, MA 02178
407. Pieter Krijgsman
Ceramic Design International
Holding B.V.
P.O. Box 68
Hattem 8050-AB
THE NETHERLANDS AIR MAIL
408. Waltraud M. Kriven
University of Illinois
Materials Science and
Engineering Department
105 South Goodwin Avenue
Urbana, IL 61801
409. Edward J. Kubel, Jr.
ASM International Advanced
Materials & Processes
Materials Park, OH 44073
410. Dave Kupperman
Argonne National Laboratory
9700 South Cass Avenue
Argonne, IL 60439
411. Oh-Hun Kwon
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
412. W. J. Lackey
Georgia Institute of Technology
Materials Science and
Technology
Atlanta, GA 30332
413. Jai Lala
Tenmat Ltd.
40 Somers Road
Rugby Warwickshire CV22 7DH
ENGLAND AIR MAIL

414. Hari S. Lamba
General Motors Corporation
Electro-Motive Division
9301 West 55th Street
LaGrange, IL 60525
415. Richard L. Landingham
Lawrence Livermore National
Laboratory
Ceramics, Corrosion, and
Thermochemistry
P.O. Box 808, L-369
Livermore, CA 94550
416. Charles J. Landry
Chand Kare Technical Ceramics
712 Flat Hill Road
Lumburg, MA 01462
417. Manfred W. Langer
Volkswagen AG
Material Technology
3180 Wolfsburg 1
GERMANY AIR MAIL
418. James Lankford
Southwest Research Institute
Department of Materials
Sciences
6220 Culebra Road
San Antonio, TX 78228-0510
419. Stanley B. Lasday
Business News Publishing Co.
Manor Oak One
1910 Cochran Road, Suite 630
Pittsburgh, PA 15220
420. Mark S. Laser
Solar Turbines, Inc.
2211 Erie Street
San Diego, CA 92110
421. S. K. Lau
Carborundum Company
Technology Division
P.O. Box 832, B-100
Niagara Falls, NY 14302
422. Edward A. Lauder
Advanced Composite Materials
Corporation
1525 South Buncombe Road
Greer, SC 29651-9208
423. J. Lawrence Lauderdale
Babcock & Wilcox
Contract Research Division
1850 "K" Street, Suite 950
Washington, DC 20006
424. Harry A. Lawler
Carborundum Company
Technology Division
P.O. Box 832
Niagara Falls, NY 14302
425. Jean F. LeCostaouec
Textron Speciality Materials
2 Industrial Avenue
Lowell, MA 01851
426. Benson P. Lee
Interscience, Inc.
9718 Lake Shore Boulevard
Cleveland, OH 44108
427. Burtrand I. Lee
Clemson University
Department of Ceramic
Engineering
Olin Hall
Clemson, SC 29634-0907
428. June-Gunn Lee
KIST
Structural Ceramic Lab
P.O. Box 131, Cheong-Ryang
Seoul 130-650
KOREA AIR MAIL
429. Ran-Rong Lee
Ceramics Process Systems
Corporation
155 Fortune Boulevard
Milford, MA 01757
430. Stan Levine
NASA Lewis Research Center
21000 Brookpark Road
MS:49-3
Cleveland, OH 44135
431. Alan V. Levy
Lawrence Berkeley Laboratory
One Cyclotron Road, MS:62-203
Berkeley, CA 94720

432. Ai-Kang Li
Materials Research
Laboratories, ITRI
195-5 Chung-Hsing Road, Sec. 4
Chutung Hsinchu 31015 R.O.C.
TAIWAN AIR MAIL
433. Winston W. Liang
Hong Kong Industrial
Technology Centre Co. Ltd.
78 Tat Chee Avenue
4/F, HKPC Building
Howloon
HONG KONG AIR MAIL
434. Robert Licht
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
435. E. Lilley
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
436. Laura J. Lindberg
Allied-Signal Aerospace
Company
Garrett Fluid Systems Division
1300 West Warner
MS: 93-901-1207-4TT
P.O. Box 22200
Tempe, AZ 85284-2200
437. Leonard C. Lindgren
General Motors Corporation
Allison Gas Turbine Division
P.O. Box 420, Speed Code:T-20A
Indianapolis, IN 46206-0420
438. Hans A. Lindner
Cremer Forschungsinstitut
GmbH&Co.KG
Oeslauer Strasse 35
D-8633 Rodental 8866
GERMANY AIR MAIL
439. Ronald E. Loehman
Sandia National Laboratories
Chemistry & Ceramics
Department 1840
P.O. Box 5800
Albuquerque, NM 87185
440. Jeffrey C. Logas
Winona State University
Composite Materials
Engineering
115 Pasteur Hall
Winona, MN 55987
441. Bill Long
Babcock & Wilcox
P.O. Box 11165
Lynchburg, VA 24506
442. William D. Long
Wacker Chemicals (USA), Inc.
ESK Engineered Ceramics
50 Locust Avenue
New Canaan, CT 06840
443. L. A. Lott
EG&G Idaho, Inc.
Idaho National Engineering
Laboratory
P.O. Box 1625
Idaho Falls, ID 83415-2209
444. Raouf O. Loutfy
MER Corporation
7960 South Kolb Road
Tucson, AZ 85706
445. Gordon R. Love
Aluminum Company of America
Alcoa Technical Center
Alcoa Center, PA 15069
446. Lydia Luckevich
Ortech International
2395 Speakman Drive
Mississauga Ontario L5K 1B3
CANADA AIR MAIL

447. James W. MacBeth
Carborundum Company
Structural Ceramics Division
P.O. Box 1054
Niagara Falls, NY 14302
448. H. MacLaren
General Electric Company
Thomson Laboratory, Materials
Engineering 36807
1000 Western Avenue
Lynn, MA 01910
449. George Maczura
Aluminum Company of America
Industrial Chemicals Division
670 One Allegheny Square
Pittsburgh, PA 15212
450. David Maginnis
Tinker AFB
OC-ALC/LIIRE
Tinker AFB OK 73145-5989
451. Frank Maginnis
Aspen Research, Inc.
220 Industrial Boulevard
Moore, OK 73160
452. Tai-il Mah
Universal Energy Systems, Inc.
Ceramics and Composites
Research
4401 Dayton-Xenia Road
Dayton, OH 45432
453. Kenneth M. Maillar
Barbour Stockwell Company
83 Linskey Way
Cambridge, MA 02142
454. Lorenzo Majno
Instron Corporation
100 Royall Street
Canton, MA 02021
455. S. G. Malghan
National Institute of Standards
and Technology
1-270 & Clopper Road
Gaithersburg, MD 20899
456. Lars Malmrup
United Turbine AB
Box 13027
Malmo S-200 44
SWEDEN AIR MAIL
457. John Mangels
Ceradyne, Inc.
3169 Redhill Avenue
Costa Mesa, CA 92626
458. Russell V. Mann
Matec Applied Sciences, Inc.
75 South Street
Hopkinton, MA 01748
459. William R. Manning
Champion Aviation Products
Division
Old Norris Road
P.O. Box 686
Liberty, SC 29657
460. Ken Marnoch
Amercom, Inc.
8928 Fullbright Avenue
Chatsworth, CA 91311
461. Robert A. Marra
Aluminum Company of America
Alcoa Technical Center
Advanced Ceramics Center - E
Alcoa Center, PA 15069
462. Chauncey L. Martin
3M Company
3M Center, Building 60-1N-01
St. Paul, MN 55144
463. Steven C. Martin
Advanced Refractory
Technologies, Inc.
699 Hertel Avenue
Buffalo, NY 14207
464. Kelly J. Mather
Williams International
Corporation
2280 West Maple Road
P.O. Box 200
Walled Lake, MI 48088

465. James P. Mathers
3M Company
3M Center
Building 201-3N-06
St. Paul, MN 55144
466. Marshall Mayer
Instron Corporation
3815 Presidential Parkway,
Suite 100
Atlanta, GA 30340
467. Ron Mayville
Arthur D. Little, Inc.
15-163 Acorn Park
Cambridge, MA 02140
468. F. N. Mazadarany
General Electric Company
Research Laboratory
Building K-1, Room MB-159
P.O. Box 8
Schenectady, NY 12301
469. James W. McCauley
Alfred University
NYS College of Ceramics
Binns-Merrill Hall
Alfred, NY 14802
470. Carolyn McCormick
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
Bldg. 1303-206
P.O. Box 5227, MS:9317-2
Phoenix, AZ 85010
471. Louis R. McCreight
2763 San Ramon Drive
Rancho Palos Verdes, CA 90274
472. Colin F. McDonald
McDonald Thermal Engineering
1730 Castellana Road
La Jolla, CA 92037
473. B. J. McEntire
Norton Company, TRW Ceramics
Goddard Road
Northboro, MA 01532-1545
474. Chuck McFadden
Coors Ceramics Company
600 9th Street
Golden, CO 80401
475. Henry McFadden
Magnetic Bearings, Inc.
Engineering Library
609 Rock Road
Radford, VA 24141
476. Thomas D. McGee
Iowa State University
Materials Science and
Engineering Department
110 Engineering Annex
Ames, IA 50011
477. Carol McGill
Corning Inc.
Sullivan Park, FR-02-08
Corning, NY 14831
478. T. C. McLaren
Cameron Forged Products
Company
P.O. Box 1212
Houston, TX 77251-1212
479. James McLaughlin
Sundstrand Power Systems
4400 Ruffin Road
P.O. Box 85757
San Diego, CA 92186-5757
480. Arthur F. McLean
6225 North Camino Almonte
Tucson, AZ 85718
481. Matt McMonigle
U.S. Department of Energy
Improved Energy Productivity
Division
Forrestal Building,
CE-231
Washington, DC 20585
482. Dennis McMurtry
EG&G Idaho, Inc.
Idaho National Engineering
Laboratory
P.O. Box 1625
Idaho Falls, ID 83415

483. D. B. Meadowcroft
National Power Technology
and Environmental Centre
Kelvin Avenue
Leatherhead Surrey
KT22 7SE
ENGLAND AIR MAIL
484. Jo Meglen
11004 Birdfoot Court
Reston, VA 22091
485. Pankaj K. Mehrotra
Kennametal, Inc.
P.O. Box 639
Greensburg, PA 15601
486. Joseph J. Meindl
Reynolds International, Inc.
6603 West Broad Street
P.O. Box 27002
Richmond, VA 23261-7003
487. Michael D. Meiser
Allied-Signal Aerospace Company
Garrett Ceramic Components
Division
19800 South Van Ness Avenue
Torrance, CA 90509
488. George Messenger
National Research Council of
Canada
Engine Laboratory
Building M-7
Ottawa Ontario K1A 0R6
CANADA AIR MAIL
489. D. Messier
U.S. Army Materials Technology
Laboratory
SLCMT-EMC
405 Arsenal Street
Watertown, MA 02172-0001
490. Gary L. Messing
Pennsylvania State University
Ceramic Science and Engineering
Department
119 Steidle Building
University Park, PA 16802
491. Arthur G. Metcalfe
Arthur G. Metcalfe and
Associates, Inc.
2108 East 24th Street
National City, CA 91950
492. R. Metselaar
Eindhoven University
Centre for Technical Ceramics
P.O. Box 513
Eindhoven 5600 MB
THE NETHERLANDS AIR MAIL
493. Nancy S. Meyers
U.S. Department of Energy
Transportation Technologies
CE-30, Forrestal Building
6B-094
Washington, DC 20585
494. David J. Michael
Harbison-Walker Refractories
Company
P.O. Box 98037
Pittsburgh, PA 15227
495. Ken Michaels
Chrysler Motors Corporation
Ceramics Development
Metallurgical Processes
P.O. Box 1118, CIMS:418-17-09
Detroit, MI 48288
496. Bernd Michel
Institute of Mechanics
Fracture and Micromechanics
Department
P.O. Box 408
D-9010 Chemnitz
GERMANY AIR MAIL
497. David E. Miles
Commission of the European
Communities
rue de la Loi, 200
B-1049 Brussels
BELGIUM AIR MAIL
498. John V. Milewski
Superkinetics, Inc.
P.O. Box 8029
Santa Fe, NM 87504

499. Carl E. Miller
AC Rochester
1300 North Dort Highway,
MS:32-31
Engineering Building B
Flint, MI 48556
500. Mike Miller
McGraw-Hill Aviation Week
Performance Materials
1156 15th Street, N.W.
Washington, DC 20005
501. Charles W. Miller, Jr.
Centorr Furnaces/Vacuum
Industries
542 Amherst Street
Nashua, NH 03063
502. R. Mininni
Enichem America
2000 Cornwall Road
Monmouth Junction, NJ 08852
503. Michele V. Mitchell
Allied-Signal Aerospace
Company
Garrett Ceramic Components
Division
19800 South Van Ness Avenue
Torrance, CA 90501-1149
504. Howard Mizuhara
GTE - WESGO
477 Harbor Boulevard
Belmont, CA 94002
505. Helen Moeller
Babcock & Wilcox
P.O. Box 11165
Lynchburg, VA 24506-1165
506. Francois R. Mollard
Metalworking Technology, Inc.
1450 Scalp Avenue
Johnstown, PA 15904
507. Phil Mooney
Panametrics
NDE Division
221 Crescent Street
Waltham, MA 02254
508. Thomas Morel
Ricardo North America
645 Blackhawk Drive
Westmont, IL 60559
509. Geoffrey P. Morris
3M Company
3M Traffic Control Materials
Division
Bldg. 209-BW-10, 3M Center
St. Paul, MN 55144-1000
510. Jay A. Morrison
Rolls-Royce, Inc.
Engineering and Information
Center, Overlook 1
2849 Paces Ferry Road,
Suite 450
Atlanta, GA 30339-3769
511. Joel P. Moskowitz
Ceradyne, Inc.
3169 Redhill Avenue
Costa Mesa, CA 92626
512. Brij Moudgil
University of Florida
Material Science and
Engineering
Gainesville, FL 32611
513. Christoph J. Mueller
Sprehsaal Publishing
Group
P.O. Box 2962, Mauer 2
D-8630 Coburg
GERMANY AIR MAIL
514. Thomas W. Mullan
Vapor Technologies Inc.
345 Route 17 South
Upper Saddle River, NJ 07458
515. M. K. Murthy
MKM Consultants International
10 Avoca Avenue, Unit 1906
Toronto Ontario M4T 2B7
CANADA AIR MAIL
516. Solomon Musikant
TransCon Technologies, Inc.
Materials Science & Engineering
1508 Waynesboro Road
Paoli, PA 19301

517. David L. Mustoe
Custom Technical Ceramics
8041 West I-70 Service Road,
Unit 6
Arvada, CO 80002
518. Curtis V. Nakaishi
U.S. Department of Energy
Morgantown Energy Technology
Center
Collins Ferry Road
P.O. Box 880
Morgantown, WV 26507-0880
519. Yoshio Nakamura
Faicera Research Institute
2-5-8 Hiyakunin-cho Shinjuku-Ko
Tokyo
JAPAN AIR MAIL
520. K. S. Narasimhan
Hoeganaes Corporation
River Road
Riverton, NJ 08077
521. Samuel Natansohn
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
522. Robert Naum
Applied Resources, Inc.
P.O. Box 241
Pittsford, NY 14534
523. Malcolm Naylor
Cummins Engine Company, Inc.
P.O. Box 3005, Mail Code 50183
Columbus, IN 47202-3005
524. Jeffrey Neil
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
525. Fred A. Nichols
Argonne National Laboratory
9700 South Cass Avenue
MCT - Building 212
Argonne, IL 60439
526. H. Nickel
Forschungszentrum Jülich (KFA)
P.O. Box 1913
Jülich 1-5170 BRD NRW
GERMANY AIR MAIL
527. Dale E. Niesz
Rutgers University
Center for Ceramic Research
P.O. Box 909
Piscataway, NJ 08855-0909
528. David M. Nissley
United Technologies Corporation
Pratt & Whitney Aircraft
400 Main Street, MS:163-10
East Hartford, CT 06108
529. Richard D. Nixdorf
ReMaxCo Technologies, Inc.
11317 Snyder Road
Knoxville, TN 37932
530. Bernard North
Kennametal, Inc.
P.O. Box 639
Greensburg, PA 15601
531. Bruce E. Novich
Ceramics Process Systems
Corporation
155 Fortune Boulevard
Milford, MA 01757
532. Daniel Oblas
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
533. Don Ohanehi
Magnetic Bearings, Inc.
1908 Sussex Road
Blacksburg, VA 24060
534. Robert Orenstein
General Electric Company
55-112, River Road
Schenectady, NY 12345

535. Norb Osborn
Aerodyne Dallas
151 Regal Row,
Suite 120
Dallas, TX 75247
536. A. M. Paddick
BP International Limited
BP Research Centre, Main
Library
Chertsey Road
Sunbury-on-Thames
Middlesex TW16 7LN
UNITED KINGDOM AIR MAIL
537. Russell J. Page
Kanthal-Artcor
3001 Redhill Avenue, II-109
Costa Mesa, CA 92705
538. Richard Palicka
Cercom, Inc.
1960 Watson Way
Vista, CA 92083
539. Muktesh Paliwal
GTE Products Corporation
Hawes Street
Towanda, PA 18848
540. Joseph E. Palko
General Electric Company
55-113, River Road
Schenectady, NY 12345
541. Hayne Palmour, III
North Carolina State
University
Materials Science and
Engineering Dept.
Raleigh, NC 27605-7905
542. Joseph N. Panzarino
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
543. Pellegrino Papa
Corning Inc.
MP-WX-02-1
Corning, NY 14831
544. E. Beth Pardue
Technology for Energy
Corporation
One Energy Center
P.O. Box 22996
Knoxville, TN 37933-0996
545. Soon C. Park
3M Company
3M Center .-
Building 142-4N-02
P.O. Box 2963
St. Paul, MN 55144
546. Hartmut Paschke
Schott Glaswerke
Christoph-Dorner-Strasse 29
D-8300 Landshut
GERMANY AIR MAIL
547. Marina R. Pascucci
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
548. James W. Patten
Cummins Engine
Company, Inc.
Materials Engineering
P.O. Box 3005, Mail
Code 50183
Columbus, IN 47202-3005
549. Robert A. Penty
Eastman Kodak Company
KAD/D73 - 35612
901 Elmgrove Road
Rochester, NY 14653
550. Robert W. Pepper
Textron Specialty Materials
2 Industrial Avenue
Lowell, MA 01851
551. Peter Perdue
Detroit Diesel Corporation
Research Advanced Development
Group
13400 West Outer Drive,
Speed Code A-07
Detroit, MI 48239-4001

552. Bruce Peters
Dow Chemical Company
Building 52
Midland, MI 48667
553. John J. Petrovic
Los Alamos National Laboratory
Group MST-4, MS:6771
Los Alamos, NM 87545
554. Frederick S. Pettit
University of Pittsburgh
Pittsburgh, PA 15261
555. Ben A. Phillips
Phillips Engineering Company
721 Pleasant Street
St. Joseph, MI 49085
556. Richard C. Phoenix
Ohmtek, Inc.
2160 Liberty Drive
Niagara Falls, NY 14302
557. Bruce J. Pletka
Michigan Technological
University
Metallurgical and Materials
Engineering Department
Houghton, MI 49931
558. John P. Pollinger
Garrett Ceramic Components
19800 Van Ness Avenue
Torrance, CA 90501
559. P. Popper
High Technology Ceramics
International Journal
22 Pembroke Drive
Westlands Newcastle-under-Lyme
Staffs ST5 2JN
ENGLAND AIR MAIL
560. F. Porz
Universitat Karlsruhe
Institut für Keramik im
Maschinendau
Postfach 6980
D-7500 Karlsruhe
GERMANY AIR MAIL
561. Harry L. Potma
Royal Netherlands Embassy
Science and Technology
4200 Linnean Avenue, N.W.
Washington, DC 20008
562. Bob R. Powell
General Motors Research
Laboratories
Metallurgy Department
30500 Mound Road
Box 9055
Warren, MI 48090-9055
563. Stephen C. Pred
ICD Group, Inc.
1100 Valley Brook Avenue
Lyndhurst, NJ 07071
564. Karl M. Prewé
United Technologies Research
Center
411 Silver Lane
MS:24
East Hartford, CT 06108
565. Peter E. Price
Industrial Materials
Technology, Inc.
P.O. Box 9565
Andover, MA 01810
566. Joseph M. Proud
GTE Laboratories, Inc.
Materials Science Laboratory
40 Sylvan Road
Waltham, MA 02254
567. Vimal K. Pujari
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
568. George Quinn
National Institute of
Standards and Technology
Ceramics Division, Bldg. 223
Gaithersburg, MD 20899

569. Ramas V. Raman
Ceracon, Inc.
1101 North Market Boulevard,
Suite 9
Sacramento, CA 95834
570. Charles F. Rapp
Owens Corning Fiberglass
2790 Columbus Road
Granville, OH 43023-1200
571. Dennis W. Readey
Colorado School of Mines
Department of Metallurgy
and Materials Engineering
Golden, CO 80401
572. Wilfred J. Rebello
PAR Enterprises, Inc.
12601 Clifton Hunt Lane
Clifton, VA 22024
573. Harold Rechter
Chicago Fire Brick Company
R&D
7531 South Ashland Avenue
Chicago, IL 60620
574. Robert R. Reeber
U.S. Army Research Office
P.O. Box 12211
Research Triangle Park, NC 27709
575. K. L. Reifsnider
Virginia Polytechnic Institute
and State University
Department of Engineering
Science and Mechanics
Blacksburg, VA 24061
576. Paul E. Rempes
McDonnell Douglass Missile
Systems Company
P.O. Box 516,
Mail Code:1066086
St. Louis, MO 63166-0516
577. Gopal S. Revankar
John Deere Company
Metals Research
3300 River Drive
Moline, IL 61265
578. K. T. Rhee
Rutgers University
Mechanical Engineering
P.O. Box 909
Piscataway, NJ 08854
579. James Rhodes
Advanced Composite Materials
Corporation
1525 South Buncombe Road
Greer, SC 29651
580. Roy W. Rice
W. R. Grace and Company
7379 Route 32
Columbia, MD 21044
581. David W. Richerson
2093 East Delmont Drive
Salt Lake City, UT 84117
582. Tomas Richter
J. H. France Refractories
1944 Clarence Road
Snow Shoe, PA 16874
583. Michel Rigaud
Ecole Polytechnique
Campus Universite De Montreal
P.O. Box 6079, Station A
Montreal, P.Q Quebec H3C 3A7
CANADA AIR MAIL
584. R. E. Riman
Rutgers University
Ceramics Engineering
Department
P.O. Box 909
Piscataway, NJ 08855-0909
585. Barry Ringstrom
Superior Graphite Company
P.O. Box 2373
Smyrna, GA 30081
586. John E. Ritter
University of Massachusetts
Mechanical Engineering
Department
Amherst, MA 01003

587. Frank L. Roberge
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
P.O. Box 5227
Phoenix, AZ 85010
588. W. Eric Roberts
Advanced Ceramic
Technology, Inc.
990 "F" Enterprise Street
Orange, CA 92667
589. Martha Rohr
U.S. Department of Energy
DOE Oak Ridge Field Office
Building 4500N
P.O. Box 2008, MS:6269
Oak Ridge, TN 37831-6269
590. Y. G. Roman
TNO TPD Keramick
P.O. Box 595
Eindhoven 5600 AN
HOLLAND AIR MAIL
591. Mark D. Roos
Carborundum Company
P.O. Box 156
Niagara Falls, NY 14302
592. Michael Rossetti
Arthur D. Little, Inc.
15 Acorn Park
Cambridge, MA 01240
593. Barry R. Rossing
Lanxide Corporation
1300 Marrows Road
Newark, DE 19714-6077
594. Steven L. Rotz
Lubrizol Corporation
29400 Lakeland Boulevard
Wickliffe, OH 44092
595. Bruce Rubinger
Global Competitiveness, Inc.
One Devonshire Place,
Suite 1011
Boston, MA 02109
596. Robert Ruh
Wright Laboratory
WL/MLLM
Wright-Patterson AFB, OH 45433
597. Robert J. Russell
17 Highgate Road
Framingham, MA 01701
598. L. William Sahley
Supermaterials Company
24400 Highland Road
Richmond Heights, OH 44143
599. Jon Salem
NASA Lewis Research Center
21000 Brookpark Center
Cleveland, OH 44135
600. W. A. Sanders
NASA Lewis Research Center
21000 Brookpark Road,
MS:49-3
Cleveland, OH 44135
601. J. Sankar
North Carolina A&T State
University
Department of Mechanical
Engineering
Greensboro, NC 27411
602. Yasushi Sato
NGK Spark Plugs (U.S.A.), Inc.
1200 Business Center Drive,
Suite 300
Mt. Prospect, IL 60056
603. Maxine L. Savitz
Allied-Signal Aerospace
Company
Garrett Ceramic Components
Division
19800 South Van Ness Avenue
Torrance, CA 90501
604. Ashok Saxena
Georgia Institute of
Technology
Materials Engineering
Atlanta, GA 30332-0245

605. David W. Scanlon
Instron Corporation
100 Royall Street
Canton, MA 02021
606. Charles A. Schacht
Schacht Consulting Services
12 Holland Road
Pittsburgh, PA 15235
607. James Schienle
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
2739 East Washington Street
P.O. Box 5227, MS:1302-2P
Phoenix, AZ 85010
608. John C. Schneider
San Juan Technologies
P.O. Box 49326
Colorado Springs, CO 80949-9326
609. Gary Schnittgrund
Rocketdyne, BA05
6633 Canoga Avenue
Canoga Park, CA 91303
610. Mark Schomp
Lonza, Inc.
Corporate Headquarters
17-17 Route 208
Fair Lann, NJ 07410
611. Joop Schoonman
Delft University of Technology
Laboratory for Inorganic
Chemistry
P.O. Box 5045
2600 GA Delft
THE NETHERLANDS AIR MAIL
612. John Schuldies
Industrial Ceramic
Technology, Inc.
37 Enterprise Drive
Ann Arbor, MI 48103
613. Robert B. Schulz
U.S. Department of Energy
Office of Transportation
Materials
CE-34, Forrestal Building
Washington, DC 20585
614. Murray A. Schwartz
Materials Technology
Consulting, Inc.
30 Orchard Way, North
Potomac, MD 20854
615. Peter Schwarzkopf
SRI International
333 Ravenswood Avenue
Menlo Park, CA 94025
616. Thomas C. Schweizer
Princeton Economic
Research, Inc.
12300 Twinbrook Pkwy.,
Suite 650
Rockville, MD 20852
617. William T. Schwessinger
Multi-Arc Scientific
Coatings
1064 Chicago Road
Troy, MI 48083-4297
618. W. D. Scott
University of Washington
Materials Science Department
Mail Stop:FB10
Seattle, WA 98195
619. Nancy Scoville
Thermo Electron Technologies
74 West Street
P.O. Box 9046
Waltham, MA 02254-9046
620. Brian Seegmiller
Coors Ceramics Company
600 9th Street
Golden, CO 80401

621. T. B. Selover
AICRE/DIPPR
3575 Traver Road
Shaker Heights, OH 44122
622. J. H. Selverian
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
623. Charles E. Semler
Semler Materials Services
4160 Mumford Court
Columbus, OH 43220
624. Thomas Service
Service Engineering Laboratory
324 Wells Street
Greenfield, MA 01301
625. Kish Seth
Ethyl Corporation
R&D Laboratories
P.O. Box 341
Baton Rouge, LA 70821
626. Karleen Seybold
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
P.O. Box 5227
Phoenix, AZ 85010
627. William J. Shack
Argonne National Laboratory
9700 South Cass Avenue
Building 212
Argonne, IL 60439
628. Peter T. B. Shaffer
Technical Ceramics
Laboratories, Inc.
4045 Nine/McFarland Drive
Alpharetta, GA 30201
629. Richard K. Shaltens
NASA Lewis Research Center
21000 Brookpark Road,
MS:301-2
Cleveland, OH 44135
630. Robert S. Shane
238 Hemlock Road
Wynnewood, PA 19096
631. Daniel Shanefield
Rutgers University
Ceramics Engineering
Department
P.O. Box 909
Piscataway, NJ 08855-0909
632. Ravi Shankar
Chromalloy
Research and Technology
Division
Blaisdell Road
Orangeburg, NY 10962
633. Terence Sheehan
Alpex Wheel Company
727 Berkley Street
New Milford, NJ 07646
634. Dinesh K. Shetty
University of Utah
304 EMRO, Dept. of Materials
Science and Engineering
Salt Lake City, UT 84112
635. Masahide Shimizu
Ceramic Society of Japan
2-2-503 Takiyama 6-chome
Higashikurume-Shi Tokyo 203
JAPAN AIR MAIL
636. John Shipinski
Toyota Technical Center
U.S.A., Inc.
Technical Research Department
2000 Town Center, Suite 500
Southfield, MI 48075
637. Thomas Shreves
American Ceramic Society, Inc.
Library
757 Brooksedge Plaza Drive
Westerville, OH 43081-2821
638. Jack D. Sibold
Coors Ceramics Company
Contracts for Corporate
Technology
4545 McIntyre Street
Golden, CO 80403

639. George H. Siegel
Point North Associates, Inc.
P.O. Box 907
Madison, NJ 07940
640. Richard Silberglitt
Technology Assessment and
Transfer, Inc.
133 Defense Highway, #212
Annapolis, MD 21401
641. Mary Silverberg
Norton Company
Advanced Ceramics Library
Goddard Road
Northboro, MA 01532-1545
642. Gurpreet Singh
Department of the Navy
Internal Combustion & Gas
Turbine Engine Division
Code 56X31
Washington, DC 20362-5101
643. Maurice J. Sinnutt
University of Michigan
Chemical and Metallurgical
Engineering
5106 IST Building
Ann Arbor, MI 48109-2099
644. John Skildum
3M Company
3M Center
Building 224-2S-25
St. Paul, MN 55144
645. David P. Smith
Hoskins, Rees & Smith
1910 Cochran Road
Manor Oak II, Suite 658
Pittsburgh, PA 15220
646. Richard H. Smoak
Smoak & Associates
3554 Hollyslope Road
Altadena, CA 91001-3923
647. Jay R. Smyth
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
2739 East Washington Street
P.O. Box 5227
MS:93-173/1303-207
Phoenix, AZ 85010
648. Edward A. Snajdr
Premier Refractories
and Chemicals, Inc.
P.O. Box 392
Findlay, OH 44815
649. Rafal A. Sobotowski
British Petroleum Company
Technical Center, Broadway
3092 Broadway Avenue
Cleveland, OH 44115
650. A. G. Solomah
SAC International Ltd.
1445 Bonhill Road, # 13
Mississauga Ontario L5T 1V3
CANADA AIR MAIL
651. S. Somiya
Nishi Tokyo University
3-7-19 Seijo, Setagaya
Tokyo 157
JAPAN AIR MAIL
652. Boyd W. Sorenson
DuPont Lanxide Composites
1300 Marrows Road
P.O. Box 6077
Neward, DE 19707
653. Charles A. Sorrell
U.S. Department of Energy
Advanced Industrial
Concepts Division
CE-232, Forrestal
Building
Washington, DC 20585

654. C. Spencer
EA Technology
Capenhurst Chester
CH1 6ES
UNITED KINGDOM AIR MAIL
655. Allen Spizzo
Hercules, Inc.
Hercules Plaza
Wilmington, DE 19894
656. Richard M. Spriggs
Alfred University
Center for Advanced Ceramic
Technology
Alfred, NY 14802
657. Charles Spuckler
NASA Lewis Research Center
21000 Brookpark Road
MS: 5-11
Cleveland, OH 44135-3191
658. M. Srinivasan
Material Solutions
P.O. Box 663
Grand Island, NY 14702-0663
659. Gordon L. Starr
Cummins Engine Company, Inc.
Design & Technology
P.O. Box 3005
Mail Code 50182
Columbus, IN 47202-3005
660. Jim Stevenson
Windrock, Incorporated
154 Fairbanks Plaza
Oak Ridge, TN 37830
661. Tom Stillwagon
Allied-Signal Aerospace
Company
Garrett Ceramic Components
Division
19800 South Van Ness Avenue
Torrance, CA 90501
662. Harold L. Stocker
General Motors Corporation
Allison Gas Turbine Division
P.O. Box 420
Indianapolis, IN 46206
663. Paul D. Stone
Dow Chemical USA
1776 "Eye" Street, N.W.,
Suite 575
Washington, DC 20006
664. Roger S. Storm
Carborundum Company
Technology Division
P.O. Box 337
Niagara Falls, NY 14302-0337
665. Peter A. Stranges
4 Chittenden Lane
Owings Mills, MD 21117
666. F. W. Stringer
Aero & Industrial
Technology Ltd.
P.O. Box 46, Wood Top
Burnley Lancashire BB11 4BX
UNITED KINGDOM AIR MAIL
667. Thomas N. Strom
NASA Lewis Research Center
21000 Brookpark Road
MS:86-6
Cleveland, OH 44135
668. M. F. Stroosnijder
Institute for Advanced
Materials
Joint Research Centre
21020 Ispra (VA)
ITALY AIR MAIL
669. Karsten Styhr
30604 Ganado Drive
Rancho Palos Verdes, CA 90274
670. T. S. Sudarshan
Materials Modification, Inc.
2929-P1 Eskridge Center
Fairfax, VA 22031
671. M. J. Sundaresan
University of Miami
Mechanical Engineering
Department
P.O. Box 248294
Coral Gables, FL 33124

672. Patrick L. Sutton
U.S. Department of Energy
Advanced Propulsion Division
CE-322, Forrestal Building
Washington, DC 20585
673. Willard H. Sutton
United Technologies
Corporation
Research Center, MS:24
Silver Lane
East Hartford, CT 06108
674. Ron Sviben
100 Indel Avenue
Rancocas, NJ 08073
675. J. J. Swab
U.S. Army Materials Technology
Laboratory
Ceramics Research Division
SLCMT-EMC
405 Arsenal Street
Watertown, MA 02172
676. Robert E. Swanson
Metalworking Technology, Inc.
1450 Scalp Avenue
Johnstown, PA 15904
677. Scott L. Swartz
Battelle Columbus
Laboratories
Metals and Ceramics
505 King Avenue
Columbus, OH 43201
678. Steve Szaruga
Air Force Wright Aeronautical
Laboratory
Materials Directorate
WL/MLBC
Wright-Patterson
AFB, OH 45433-6533
679. Yo Tajima
NGK Spark Plug Company, Ltd.
NTK Technical Ceramic Division
2808 Iwasaki
Komaki-shi Aichi-ken 485
JAPAN AIR MAIL
680. Fred Teeter
5 Tralee Terrace
East Amherst, NY 14051
681. Monika O. Ten Eyck
Carborundum Company
Technology Division
P.O. Box 832
Niagara Falls, NY 14302
682. David F. Thompson
Corning Glass Works
SP-DV-02-1
Corning, NY 14831
683. Merle L. Thorpe
Hobart Tafa Technologies, Inc.
146 Pembroke Road
Concord, NH 03301
684. Eberhard Tiefenbacher
Daimler-Benz AG Abt. F15
Mercedes-Strabe 136
Stuttgart 60
GERMANY AIR MAIL
685. T. Y. Tien
University of Michigan
Materials Science and
Engineering Department
Dow Building
Ann Arbor, MI 48103
686. Julian M. Tishkoff
Air Force Office of Scientific
Research
AFOSR/NA
Bolling AFB, DC 20332-6448
687. D. M. Tracey
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
688. Dick Trippett
General Motors Corporation
Allison Gas Turbine Division
P.O. Box 420, MS:W-16
Indianapolis, IN 46206-0420

689. L. J. Trostel, Jr.
Box 199
Princeton, MA 01541
690. W. T. Tucker
General Electric Company
Corporate R&D
Building K1-4C35
P.O. Box 8
Schenectady, NY 12301
691. Masanori Ueki
Nippon Steel Corporation
Central R&D Bureau
1618 Ida
Nakahara-Ku Kawasaki 211
JAPAN AIR MAIL
692. Filippo M. Ugolini
ATA Studio
Via Degli Scipioni, 268A
ROMA 00192
ITALY AIR MAIL
693. Donald L. Vaccari
Allison Gas Turbines
P.O. Box 420
Speed Code S49
Indianapolis, IN 46206-0420
694. Carl F. Van Conant
Boride Products, Inc.
2879 Aero Park Drive
Traverse City, MI 49684
695. Marcel H. Van De Voorde
Commission of the European
Communities
Institute for Advanced
Materials
Joint Research Centre
P.O. Box 2
1755 ZG Petten
THE NETHERLANDS AIR MAIL
696. O. Van Der Biest
Katholieke Universiteit Leuven
Departement Metaalkunde en
Toegepaste
de Croylaan 2
B-3030 Leuven
BELGIUM AIR MAIL
697. Michael Vannier
Washington University,
St. Louis
Mallinckrodt Institute of
Radiology
510 South Kings Highway
St. Louis, MO 63110
698. Stan Venkatesan
Southern Coke & Coal
Corporation
P.O. Box 52383
Knoxville, TN 37950
699. V. Venkateswaran
Carborundum Company
Niagara Falls R&D Center
P.O. Box 832
Niagara Falls, NY 14302
700. Dennis Viechnicki
U.S. Army Materials Technology
Laboratory
405 Arsenal Street
Watertown, MA 02172-0001
701. Ted Vojnovich
U.S. Department of Energy
Office of Energy Research,
ER-42
Washington, DC 20585
702. John D. Volt
E. I. Dupont de Nemours &
Company, Inc.
P.O. Box 80262
Wilmington, DE 19880
703. John B. Wachtman
Rutgers University
Ceramics Department
P.O. Box 909
Piscataway, NJ 08855
704. Shigetaka Wada
Toyota Central Research
Labs, Inc.
Nagakute Aichi 480-11
JAPAN AIR MAIL

705. Janet Wade
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division, Department 93-772
P.O. Box 5227, MS:1303-2
Phoenix, AZ 85010
706. Richard L. Wagner
Ceramic Technologies, Inc.
537 Turtle Creek South Drive,
Suite 24D
Indianapolis, IN 46227
707. J. Bruce Wagner, Jr.
Arizona State University
Center for Solid State
Science
Tempe, AZ 85287-1704
708. Daniel J. Wahlen
Kohler, Co.
444 Highland Drive
Kohler, WI 53044
709. Ingrid Wahlgren
Royal Institute of Technology
Studsvik Library
S-611 82 Nykoping
SWEDEN AIR MAIL
710. Ron H. Walecki
Allied-Signal Aerospace
Company
Garrett Ceramic Components
Division
19800 South Van Ness Avenue
Torrance, CA 90501
711. Michael S. Walsh
Vapor Technologies Inc.
2100 Central Avenue
Boulder, CO 80301
712. Chien-Min Wang
Industrial Technology Research
Institute
Materials Research Laboratories
195 Chung-Hsing Road, Sec. 4
Chutung Hsinchu 31015 R.O.C.
TAIWAN AIR MAIL
713. Robert M. Washburn
ASMT
11203 Colima Road
Whittier, CA 90604
714. Gerald Q. Weaver
Carborundum Specialty Products
42 Linus Allain Avenue
Gardner, MA 01440-2478
715. Karen E. Weber
Detroit Diesel Corporation
Technology and Planning
13400 West Outer Drive
Detroit, MI 48239-4001
716. R. W. Weeks
Argonne National Laboratory
MCT-212
9700 South Cass Avenue
Argonne, IL 60439
717. Ludwig Weiler
ASEA Brown Boveri AG
Corporate Research
Eppelheimer Str. 82
D-6900 Heidelberg
GERMANY AIR MAIL
718. James Wessel
Dow Corning Corporation
1800 "M" Street, N.W.,
Suite 325 South
Washington, DC 20036
719. Robert D. West
Therm Advanced Ceramics
P.O. Box 220
Ithaca, NY 14851
720. Thomas J. Whalen
Ford Motor Company
26362 Harriet
Dearborn Heights, MI 48127
721. Ian A. White
Hoeganaes Corporation
River Road
Riverton, NJ 08077

722. Alan Whitehead
General Electric Company
1 River Road, 55-111
Schenectady, NY 12345
723. Sheldon M. Wiederhorn
National Institute of
Standards and Technology
Building 223, Room A329
Gaithersburg, MD 20899
724. John F. Wight
Alfred University
McMahon Building
Alfred, NY 14802
725. D. S. Wilkinson
McMaster University
Materials Science and
Engineering Department
1280 Main Street, West
Hamilton Ontario L8S 4L7
CANADA AIR MAIL
726. James C. Williams
General Electric Company
Engineering Materials
Technology Labs
One Neumann Way
Mail Drop: H85
Cincinnati, OH 45215-6301
727. Janette R. Williams
Kollmorgen Corporation
PCK Technology Division
150 Motor Parkway, # 262
Hauppauge, NY 11788-5108
728. Steve J. Williams
RCG Hagler Bailly, Inc.
1530 Wilson Boulevard,
Suite 900
Arlington, VA 22209-2406
729. Craig A. Willkens
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
730. Roger R. Wills
TRW, Inc.
Valve Division
1455 East 185th Street
Cleveland, OH 44110
731. David Gordon Wilson
Massachusetts Institute of
Technology
Mechanical-Engineering
Department
77 Massachusetts Avenue,
Room 3-455
Cambridge, MA 02139
732. Matthew F. Winkler
Seaworthy Systems, Inc.
P.O. Box 965
Essex, CT 06426
733. Gerhard Winter
Hermann C. Starck Berlin GmbH,
Werk Goslar
P.O. Box 25 40
D-3380 Goslar 3380
GERMANY AIR MAIL
734. W. L. Winterbottom
Ford Motor Company
Material Systems Reliability
Department
20000 Rotunda Drive
SRL, Room E-3182
P.O. box 2053
Dearborn, MI 48121
735. David G. Wirth
Coors Ceramics Company
600 9th Street
Golden, CO 80401
736. Thomas J. Wissing
Eaton Corporation
Engineering & Research Center
P.O. Box 766
Southfield, MI 48037
737. James C. Withers
MER Corporation
7960 South Kolb Road
Building F
Tucson, AZ 85706

738. Dale E. Wittmer
Southern Illinois University
Mechanical Engineering
Department
Carbondale, IL 62901
739. Warren W. Wolf
Owens Corning Fiberglass
2790 Columbus Road, Route 16
Granville, OH 43023
740. George W. Wolter
Howmet Turbine Components
Corporation
Technical Center
699 Benston Road
Whitehall, MI 49461
741. James C. Wood
NASA Lewis Research Center
21000 Brookpark Road
MS:86-6
Cleveland, OH 44135
742. Marrill Wood
LECO Corporation
Augusta Division
P.O. Box 211688
Augusta, GA 30917-1688
743. Wayne L. Worrell
University of Pennsylvania
Department of Materials
Science and Engineering
3231 Walnut Street
Philadelphia, PA 19104
744. John F. Wosinski
Corning Inc.
ME-2 E-5 H8
Corning, NY 14830
745. Ian G. Wright
Battelle Columbus Laboratories
505 King Avenue
Columbus, OH 43201
746. Ruth Wroe
ERDC
Metals & Materials Industries
Division
Capenhurst Chester CH1 6ES
ENGLAND AIR MAIL
747. Bernard J. Wrona
Advanced Composite Materials
Corporation
1525 South Buncombe Road
Greer, SC 29651
748. Carl C. M. Wu
Naval Research Laboratory
Ceramic Branch, Code 6373
Washington, DC 20375
749. John C. Wurst
University of Dayton Research
Institute
300 College Park
Dayton, OH 45469-0101
750. Neil Wyant
ARCH Development Corp.
9700 South Cass Avenue
Building 202
Argonne, IL 60439
751. Roy Yamamoto
Texaco Inc.
P.O. Box 509
Beacon, NY 12508-0509
752. John Yamanis
Allied-Signal, Inc.
Ceramics Program
P.O. Box 1021
Morristown, NJ 07962-1021
753. Harry C. Yeh
Allied-Signal Aerospace
Company
Garrett Ceramic Components
Division
19800 South Van Ness Avenue
Torrance, CA 90509
754. Hiroshi Yokoyama
Hitachi Research Lab
4026 Kuji-Cho
Hitachi-shi Ibaraki 319-12
JAPAN AIR MAIL
755. Thomas M. Yonushonis
Cummins Engine Company, Inc.
P.O. Box 3005
Mail Code 50183
Columbus, IN 47202-3005

756. Thomas J. Yost
Corning, Inc.
Technical Products Division,
Main Plant 21-1-2
Corning, NY 14831
757. Jong Yung
Sundstrand Aviation
Operations
Department 789-6
4747 Harrison Avenue
Rockford, IL 61125
758. A. L. Zadoks
Caterpillar Inc.
Technical Center, Building L
P.O. Box 1875
Peoria, IL 61656-1875
759. Avi Zangvil
University of Illinois
Materials Research Laboratory
104 South Goodwin Avenue
Urbana, IL 61801
760. Charles H. Zenuk
Transtech
6529 East Calle Cavalier
Tucson, AZ 85715
761. Anne Marie Zerega
U.S. Department of Energy
Office of Energy Research,
ER-42
Washington, DC 20585
762. Ken Zillmer
Applied Test Systems, Inc.
2571 Mt. Gallant Road
Rock Hill, SC 29730
763. Carl Zweben
General Electric Company
P.O. Box 8555, VFSC/V4019
Philadelphia, PA 19101
764. Klaus M. Zwilsky
National Research Council
National Materials
Advisory Board
2101 Constitution Avenue
Washington, DC 20418
765. Department of Energy
DOE Field Office, Oak Ridge
Assistant Manager for Energy
Research and Development
P.O. Box 2001
Oak Ridge, TN 37831-8501
- 766-775. Department of Energy
Office of Scientific and
Technical Information
Office of Information
Services
P.O. Box 62
Oak Ridge, TN 37831
- For distribution by microfiche
as shown in DOE/OSTI-4500,
Distribution Category UC-332
(Ceramics/Advanced Materials).

END

**DATE
FILMED**

10 / 26 / 92