ANL/ESD/TM-42

Interim Progress Report — Geophysics: Building E5440 Decommissioning, Aberdeen Proving Ground

by L.D. McGinnis, S.F. Miller, M.D. Thompson, and M.G. McGinnis

Reclamation Engineering and Geosciences Section, Energy Systems Division,
Argonne National Laboratory, 9700 South Cass Avenue, Argonne, Illinois 60439

November 1992

Work sponsored by United States Army, Aberdeen Proving Ground, Maryland

MASTER

REPRODUCTION OF THIS DOCUMENT IS UNLIMITED

Preface

This report is one of a series on geophysical surveys around perimeters of buildings in the Canal Creek and Westwood areas of the Edgewood section of Aberdeen Proving Ground. The series was initiated in 1991 at Building E5032, where geophysical techniques were tested and a design for the surveys was established. The series continued in 1992, when surveys of Buildings E5190, E5282, E5375, E5440, E5476, E5481, E5485, E5487, E5489, E5974, and E5978 were completed. The surveys and reports were done sequentially, with lowest building numbers being completed first. For this reason, deeper insight into the magnetic, electrical, and radar imagery characteristics of the Canal Creek area was gained with progressively increasing building numbers. A survey at the Building 103 Dump, also completed during the spring of 1992, was not specifically designed to assist building decommissioning, but is included in the series because it was conducted by our geophysics team using techniques and procedures identical to those for the building decommissioning surveys.

-32

Contents

Abstract.....	1
1 Introduction.....	1
1.1 History of Building E5440	2
1.2 Site Reconnaissance.....	2
1.3 Geology and Physiographic Setting	6
1.4 Surveys.....	7
1.5 Survey Grid and Locations of Observations	8
2 Instrumentation.....	9
2.1 Magnetic Gradiometer and Cable Locator	9
2.2 Magnetometer/Gradiometer	9
2.3 Direct-Current Electrical Resistivity Meter	10
2.4 Ground-Penetrating Radar System	10
3 Geophysical Measurements and Surveys.....	12
3.1 Magnetometer Measurements	12
3.2 Direct-Current Electrical Resistivity Measurements.....	14
3.3 Ground-Penetrating Radar Measurements.....	16
4 Discussion	20
5 Conclusions	22
6 References	23
Appendix A: Electrical Depth-Sounding Curves	25
Appendix B: Ground-Penetrating Radar Line Coordinates	33

Tables

1 Lithologic Log of Borehole at Site No. 25	7
2 Approximate Two-Way Travel Times for Various Materials	11
A.1 Location of Centers of Stations and Orientations of Electrode Arrays for Schlumberger Electrical Depth Soundings at APG	27
A.2 Resistivity Models Calculated from Electrical Depth Soundings	28

Figures

1	General Site Map of the Canal Creek Area, Aberdeen Proving Ground, Md.	3
2	General Location Map of Building E5440	4
3	Geophysical Survey Boundaries for Building E5440	5
4	Map of Total Magnetic Field Intensity for Building E5440.....	13
5	Apparent Resistivity Profiles for Building E5440	15
6	Ground-Penetrating Radar Profiles for the Southeast Corner of the Building E5440 Study Area.....	17
7	West-East Ground-Penetrating Radar Profile for the Area Southwest of Building E5440	19
8	Color Map of Total Magnetic Field Intensity for Building E5440	21
A.1	Electrical Depth-Sounding Curve near Building E5282.....	29
A.2	Electrical Depth-Sounding Curve near Building E5440.....	30
A.3	Electrical Depth-Sounding Curve near Building E5481.....	31
A.4	Electrical Depth-Sounding Curve near Building E5974.....	32

**Interim Progress Report – Geophysics:
Building E5440 Decommissioning,
Aberdeen Proving Ground**

by

L.D. McGinnis, S.F. Miller,
M. D. Thompson, and M.G. McGinnis

Abstract

Building E5440 was one of ten potentially contaminated sites in the Canal Creek and Westwood areas of the Edgewood section of Aberdeen Proving Ground examined by a geophysical team from Argonne National Laboratory in April and May 1992. Noninvasive geophysical surveys, including magnetics, electrical resistivity, and ground-penetrating radar (GPR), were conducted around the perimeter of the building to guide a sampling program prior to decommissioning and dismantling. The results show several complex geophysical signatures. Isolated, one-point, magnetic anomalies surrounding the building may be associated with construction fill. A 10-ft-wide band of strongly magnetic positive anomalies bordering the north side of the building obliterates small magnetic sources that might otherwise be seen. A prominent magnetic "nose" extending northward from this band toward a standpipe at 100N,63E may be connected to an underground tank. The southeast corner of the site is underlain by a rectangular, magnetized source associated with strong radar images. A magnetic lineament extending south from the anomaly may be caused by a buried pipe; the anomaly itself may be caused by subsurface equipment associated with a manhole or utility access pit. A 2,500-gamma, positive magnetic anomaly centered at 0N,20E, which is also the location of a 12 Ω -m resistivity minimum, may be caused by a buried vault. It appears on radar imaging as a strong reflector.

1 Introduction

Aberdeen Proving Ground (APG), in the state of Maryland, is currently managing a comprehensive Installation Restoration Program involving more than 360 solid-waste managing units contained within 13 study areas. The Edgewood section and two landfills in the Aberdeen area appear on the National Priority List under the Comprehensive Environmental Response, Compensation, and Liability Act. Therefore, APG has entered into an Interagency Agreement with the U.S. Environmental Protection Agency to address the listed areas.

The West Branch of the Canal Creek area (Figure 1), located within the Edgewood section, is one of the areas that requires a Source Definition Study because there is an ongoing release of volatile organic compounds into the creek. A report prepared by EAI Corporation (1989) included a list of 29 potentially contaminated buildings in the Edgewood section. Sixteen of the buildings contain known contaminants, nine buildings contain unknown contaminants, and four of the buildings are potentially clean. The EAI report recommended that a sampling and monitoring program be established to verify contamination levels in and around each building. Thirteen of the potentially contaminated buildings, including Building E5440 (Figure 2), located between N Street and Williams Road, are in the West Branch of the Canal Creek area and are potential sources of volatile organic compounds. Operations have ceased and the buildings have been abandoned, but processing equipment, sumps, drains, ventilation systems, and underground storage tanks remain. These appurtenances may contain liquid, solid, or vapor contaminants of unknown nature.

Aberdeen Proving Ground is proceeding with a program to decommission the buildings, which will eliminate the actual or potential release of contaminants into the environment of the West Branch of the Canal Creek and other sites within the Edgewood area. Argonne National Laboratory has been assigned the task of developing a plan and scope of work for the proposed decommissioning. Argonne has determined that the first step in this decommissioning process, where it is technically feasible, should be a noninvasive geophysical survey around building exteriors (see Figure 3 for the boundaries of the study area for Building E5440).

1.1 History of Building E5440

According to records examined by the EAI Corporation (1989), Building E5440 was constructed in 1918. The three-story structure was built for the production of mustard and consists of the original building, measuring 140 ft × 61 ft, and one addition, measuring 21 ft × 12 ft. Production continued intermittently until 1923, when renovations were made to accommodate chloroacetophenone (CN) production, which continued until 1936. In 1940, a small-scale operation for filling mustard bombs was started. Then, in 1941, the building was used for the production, manufacturing, and packaging of CN, o-chlorobenzylidene malononitrile (CS), and 10-chloro-5,10-dihydrophenarazine (DM) hand grenades. This operation continued until 1978, when the building was placed in a standby condition. Major renovation of the building occurred at least three times in the past 70 years.

1.2 Site Reconnaissance

The geophysical survey program design for Building E5440 was based upon results from a similar study completed between April 8 and April 19, 1991, for Building E5032 (McGinnis and Miller 1991), which is also located in the Canal Creek area (Figure 1). The initial evaluation was enhanced by a November 1991 site visit and by inspection of aerial photos. Several associated buildings that appeared on 1964 photos have since been removed. The building is located on level

FIGURE 1 General Site Map of the Canal Creek Area, Aberdeen Proving Ground, Md.

FIGURE 2 General Location Map of Building E5440

FIGURE 3 Geophysical Survey Boundaries for Building E5440

terrain, and the grounds are generally well-maintained, providing good access. Structurally, parts of the building are near collapse, particularly the southwest exterior wall. Surface features observed at the site include (1) a former storage and staging area on the south side of the building, (2) an old torpedo or bomb located in an outside tank on the west side, (3) a steel underground vault near the southwest corner, and (4) steel overhead pipes extending into the building from the south.

In addition to surface conditions at the site, subsurface characteristics were considered in planning the geophysical surveying:

1. Surficial sediments consist of estuarine silts, sands, and clays that have intermediate resistivities and are nonmagnetic. The underlying soil properties are expected to vary both horizontally and vertically in the proximity of the site, depending on naturally occurring conditions and on the presence of building excavations and operations.
2. Buildings and other attributes of the Edgewood section of Aberdeen, such as radio and radar transmissions, will contribute to interference of magnetic and electrical fields and will cause electromagnetic surveying (an easily applied, low-cost method that is frequently used to identify buried conductive objects) to be generally inapplicable (AEHA 1989).
3. Multiple sources, such as iron-rich magnetized objects, nonmagnetic objects, subsurface channels containing contaminants, and plumes of contaminants of variable resistivity, may be present in the subsurface.

Multiple working technologies were utilized in the program design to mitigate interference and to either directly detect or provide inferential data on subsurface characteristics.

1.3 Geology and Physiographic Setting

The site is contained in the topographically low and flat terrain of the Coastal Plain physiographic province. The Canal Creek area is underlain by alluvial and estuarine sands, silts, and clays. A thin veneer of sediments of the Talbot Formation of Pleistocene age overlies unconsolidated sediments of the Potomac Group of Cretaceous age (Oliveros and Gernhardt 1989). The water table is less than 10 ft from the surface, and groundwater has measurable concentrations of contaminants (USGS 1992).

Lithologies at the site were determined from the sample study of a borehole (site No. 25) drilled approximately 100 ft west of Building E5440. The descriptive log given in Table 1 was part of a hydrogeologic study of the Canal Creek area performed by the U.S. Geological Survey (Oliveros and Gernhardt 1989). Facies represented include soils and a clayey fill material,

TABLE 1 Lithologic Log of Borehole at Site No. 25

Description	Depth (ft)	Thickness (ft)
Soil zone, brown	0.6	0.6
Fill material, brown to gray; with clay, sand and gravel	4.0	3.4
Silt, clayey, orange-brown and gray mottled	11.5	7.5
Sand, clayey, light gray and orange mottled, [mL]; ^a with red-black concretions	14.0	2.5
Sand, white to gray and orange, clean, well-sorted [mL-mU]; with red-black concretions and thin clay lenses	17.3	3.3
Sand, clayey, light gray, [mU]; with small red-black concretions and some clay coatings on grains	19.0	1.7
Sand, tan, wet, clean, well-sorted [mU]; with small, white clay lenses, and sand turning gray near bottom	29.0	10.0

^a Codes enclosed in brackets at selected horizons refer to color designations as specified in the Munsell Soil Color Chart (1975).

followed by thin beds of varying stratigraphy consisting primarily of sands to a depth of 29 ft. The single unit of greatest thickness (10 ft) was a tan sand at a depth of 19.0–29.0 ft. This sand is part of the Canal Creek Aquifer (USGS 1992).

Building E5440 is located near the south end of the area of study and is adjacent to other buildings not included in the survey. Initial construction probably involved considerable amounts of excavation and use of fill material, so that most of the shallow sediment at the site is reworked.

1.4 Surveys

The geophysical phase of the building decommissioning program at Building E5440 was carried out as planned during the period April 6 to May 8, 1992. Geophysical measurements conformed to the work plan (McGinnis et al. 1992), which called for magnetics, ground-penetrating radar (GPR), and horizontal direct-current electrical resistivity (DCER) surveys. An addition to the plan was the use of a magnetic gradiometer/metal detector to ensure detection of anomalies between survey profiles and grid stations. Seismic imaging information was not required at the site. Each technique had its own specific objectives:

- Gradiometer/metal detector sweep — to provide a rapid, 100% sweep of the site;

- Magnetometer measurements — to determine the location of such buried, iron-rich objects as tanks, pipes, debris, etc.;
- Horizontal DCER survey — to establish the regional conductive nature of the subsurface and to identify contaminant plumes to depths of approximately 10 ft; and
- Ground-penetrating radar survey — to determine the geometry of, and to find the approximate depth to, buried objects.

The following data were acquired during field operations: (1) nonpermanent ground markings of magnetic objects, (2) 1,258 magnetic observations, (3) 93 horizontal DCER observations, and (4) 3,283 (linear) ft of GPR profile along 48 lines. Field operations required a total of three days for a four-person team. On-site personal computers (both notebook and desktop), interactive software, field equipment designed specifically for Aberdeen, and an all-terrain vehicle were used to expedite data acquisition and processing.

1.5 Survey Grid and Locations of Observations

Prior to geophysical surveying, wooden stakes were placed at the site corners to mark the area to be surveyed so that its sides were approximately parallel to the sides of the building. The DCER measurements were limited to one or two profiles around the building because of the character of the surface surrounding the building, which included an aboveground tank and coarse gravel surface on the west, a pavement roadway and overhead pipes paralleling the exterior wall on the south, drainage ditches on the north, and pavement and trees on the east. Grid spacing for magnetics and GPR measurements was at 5-ft intervals. The zero coordinate was at the southwest corner of the surveyed area. Positive numbers are measured north and east of the zero coordinate, whereas negative coordinates are measured south and west. The building is not perfectly aligned north-south and east-west.

2 Instrumentation

2.1 Magnetic Gradiometer and Cable Locator

The Schonstedt MAC-51B magnetic gradiometer and cable locator is a dual-mode instrument designed for detecting shallow buried iron and steel objects and tracing underground cables and pipes. The system consists of a transmitter and a dual-function receiver designed to detect anomalous magnetic gradients.

Maps or models are not constructed from observations made with the MAC-51B because it is not a calibrated system. The MAC-51B is an audio device used only for rapid detection of magnetic materials for further analysis with complementary instrumentation. Anomalies are identified by changes in sound amplitude and frequency and are marked on the ground surface prior to the initiation of other surveys. If anomalies detected with the MAC-51B cannot be verified with the magnetometer (see section on magnetometer), the anomaly is assumed to be insignificant.

Application of the MAC-51B in its receiver mode was the first geophysical operation following establishment of survey limits. A qualitative description of the site with 100% ground coverage is achieved using the gradiometer, whereas the results obtained with other techniques, although more quantitative, are spatially limited to single-point, survey-grid observations or to continuous readings along spaced profiles.

2.2 Magnetometer/Gradiometer

Magnetics is the best technique for identifying such buried magnetized objects as tanks, drums, and small iron-rich debris. The EDA OMNI IV magnetometer/gradiometer is a total-field, proton-precession, microprocessor-based instrument that can also measure magnetic gradients. Internal software permits down-loading directly into an on-site computer.

Total-field magnetic observations were made at 5-ft and smaller intervals along profiles, yielding a grid of data that was contoured using the SURFER V. 4.0 software by Golden, Inc. (1991), to identify potential sources of contaminants and to distinguish them from background. The SURFER software was incorporated into the field acquisition procedure, so that daily map outputs were available for observation and interpretation.

The earth's magnetic field is reasonably well-known at a given time and place, although small changes in the field occur continuously, with larger changes occurring during magnetic storms. To adjust for field changes, the instrument has internal calibration to correct observations made at cross lines and base stations. Repeat readings were used to correct data for diurnal field fluctuations.

2.3 Direct-Current Electrical Resistivity Meter

Data on the electrical properties of soils at APG may permit detection of abnormally conductive or nonconductive liquid or solid contaminants. Most of the electrical properties of sedimentary materials are a product of the chemistry of interstitial fluids. Consequently, resistivity data can be diagnostic and complement magnetic and radar measurements. Direct-current electrical resistivity measurements have been incorporated into the APG study to take the place of conductivity measurements using electromagnetic methods that are typically made for investigations of this type. Electromagnetic methods could not be used because of previously reported interference problems (AEHA 1989).

Resistivity equipment used on the Aberdeen project consisted of an ABEM Terrameter and Booster, model SAS 300C, that utilized a variety of electrode configurations. A modified, eight-electrode Wenner array was the configuration selected, and it was towed behind an all-terrain vehicle. Profiles were coincident with GPR and magnetic lines, and data were recorded at 5-ft intervals along the lines. Consistency of repeat observations over a test profile and over known electrical anomalies provided assurance of relative data quality and variations. Data were contoured using SURFER software as described in the magnetics section.

Electrical depth-sounding curves using a Schlumberger electrode array were also determined in the Canal Creek area to add a three-dimensional view to horizontal mapping. Each sounding curve was interpreted using the RESIX PLUS software package written by Interpex (1988). Resistivities of undisturbed soils were comparable with those observed at Building E5032, which averaged 60 Ω -m.* (See Appendix A for further information.)

2.4 Ground-Penetrating Radar System

Ground-penetrating radar surveying was accomplished using a Geophysical Survey Systems, Inc. (GSSI), model SIR-3 radar connected to a transceiver with a cable approximately 300 ft long. Data were recorded on a digital audio tape to permit playback and computer processing. The control unit/graphic recorder was located in the transport vehicle. An IBM-compatible processing computer was located in a field office, so that the radar operator could down-load, check data-tape quality, and do preliminary processing after a day's run. Radan I computer software written by GSSI was used for processing the GPR data.

Wave-velocity characteristics of materials to be found at the Aberdeen/Edgewood area were derived from known positions of buried objects. Internal calibration was run at least twice each day to ensure that the graphic record of the range setting was consistent. Studies conducted during

* Resistivity data acquisition and processing were done using the metric system of measurement. To convert from meters to feet, multiply values given in meters by 3.28.

the 1991 field season suggest wave velocities of $6-7 \times 10^{-9}$ s/ft for near-surface sediment at Aberdeen; however, characteristics vary with the heterogeneity of the subsurface. Typical wave velocities for different materials are shown in Table 2.

Ground-penetrating radar is probably the best method available to determine depth and geometry of objects buried near the surface. The weakness of the method is its limited depth of exploration due to wave-propagating constraints imposed by the electrical properties of soils. The maximum depth of penetration with GPR at Building E5440 was approximately 8 ft below the ground surface.

TABLE 2 Approximate Two-Way Travel Times for Various Materials

Material	Two-Way Travel Time (10^{-9} s/ft)	Material	Two-Way Travel Time (10^{-9} s/ft)
Air	2	Marshy forested land	7
Fresh water	18	Rich agricultural land	8
Sea water	18	Fresh-water ice	4
Sand (dry)	4.5	Granite (dry)	4.5
Sand (saturated)	11	Limestone (dry)	5
Silt (saturated)	6	Concrete	5
Clay (saturated)	6	Asphalt	4 - 5
Dry, sandy, coastal land	6		

Source: Geophysical Survey Systems, Inc. (1987).

3 Geophysical Measurements and Surveys

3.1 Magnetometer Measurements

Total magnetic field observations were made at 1,258 stations for use in construction of the magnetic map shown in Figure 4. Station spacing was normally 5 ft; however, where the presurvey scan identified anomalous zones, stations were read at intervals as small as 1 ft. Peaks and troughs of positive and negative anomalies were truncated to permit a clearly displayed visual representation of the magnetic field. Thus, anomaly interiors are depicted as "white-outs".

A 10-ft-wide band of high-intensity, positive anomalies, which are produced primarily by "building effect," borders Building E5440 on the north. This band may be caused by a combination of structural-steel building supports and buried ferrous objects. Seven, small, point-source anomalies are strung along the northern edge of the surveyed area and are possibly associated with construction fill underlying the building driveway. A linear anomaly projecting from the northeast corner of the building could be caused by a drain.

The high-density station grid on the east side of the building was established in response to a complex magnetic field detected during the gradiometer sweep. Two anomalies were observed that are building-related: the first protrudes east from the building at 70N,173E, and the second is located along the north wall of the small building addition. The first anomaly is near an iron ladder that extends from the ground to the roof of the building; however, this anomaly is elongated north-south and may also have an underground source.

Point-source anomalies to the southeast of the building are probably due to construction fill. However, two "connected," rectangular anomalies in the southeast quadrant are too large to be explained by fill-like material. The southernmost of these two anomalies also has a southern extension from its southwest corner.

A large anomaly jutting to the south from the building at 25N,160E is due to metal plates over brick-lined vaults, as shown on the map in Figure 3. A linear feature extending south from this anomaly is suggestive of a metal pipe.

An area of intense but unstable magnetic field is observed in the southwest corner of the building. Because of the instability of the field, data in the southwest corner could not be contoured on a tight grid. It is believed that an electrical grounding cable with substantial power surges is causing the unusual magnetic field in this area. A positive anomaly at 00N,20E, opening to the south, may be produced by a buried tank or vault.

Two anomalies are observed west of the building. The source of the one on the west margin of the survey area may be construction debris, whereas the second, at 50N,25E, is produced by aboveground metal racks and a metal door to the building.

FIGURE 4 Map of Total Magnetic Field Intensity for Building E5440

3.2 Direct-Current Electrical Resistivity Measurements

Because of limited access and surface conditions incompatible with electrode placement, DCER data acquisition was limited to five profiles around the building; therefore, the data are shown in profile form rather than as a map. Profiles taken from 93 measurements are shown in Figure 5. The electrode spacing was 2 m, a configuration that provides an average resistivity for materials lying between the surface and a depth of about 3 m. At Building E5440 these materials would include construction fill; a brown-to-gray clay, sand, and gravel; and most of the thickness of the Upper Confining Unit (Oliveros and Gernhardt 1989), which is a silty clay.

In previous work (McGinnis and Miller 1991), background resistivities for these fine-grained, organic-rich, clayey materials were found to range from 50 to 150 Ω -m. As a basis for comparison with minima observed in other areas, a value of 6 Ω -m was observed over the "bare spot", a suspected buried tank at Building E5032, and high resistivities of up to 180 Ω -m were observed in the vicinity of a suspected old railroad bed. Electrical depth-sounding curves collected for background in the Edgewood area indicate that resistivity values normally decrease with depth, probably due to increasing saturation. Where anomalous materials are present, this generalization is not valid.

Data from an electrical depth-sounding station centered 150 ft north of the northeast corner of Building E5440 are shown in Appendix A. Inversion of the curve results in an interpreted model where the upper 1.2 m of earth, which is construction fill, has a surficial resistivity of 269 Ω -m. From 1.2 to 10.2 m, a section consisting primarily of sand (as identified on the drillers log), the mean resistivity is 14 Ω -m. Below this depth, the interpreted resistivity is 11,525 Ω -m. These resistivity values are not representative of undisturbed, natural, saturated materials. The sounding station was located in a grassy, cleared area, north of a circular driveway. The material beneath the construction fill is unusually conductive, whereas the apparent high resistivity value below 10 m may be an artifact created when electrodes cross tunnels or vertical boundaries produced by metallic and nonmetallic fill material.

Resistivities acquired using horizontal profiling techniques at the Building E5440 site generally increase from the southwest to the northeast. Apparent resistivity values range from a minimum of 12 Ω -m at 10N,20E near the southwest corner of the building to 460 Ω -m near the northeast corner. Resistivity values ranging upward from about 200 Ω -m are unusual in a fine-grained, clayey environment with a shallow water table such as the Canal Cr area. The high resistivities observed near the northeast corner of this site are probably due to dry, coarse-grained construction fill. The low resistivity near the southwest corner is probably due to an underground storage tank.

a. Profile along 05E

b. Profile along 185E

c. Profile along 190E

FIGURE 5 Apparent Resistivity Profiles for Building E5440

d. Profile along 10N

e. Profile along 100N

FIGURE 5 (Cont.)

3.3 Ground-Penetrating Radar Measurements

Ground-penetrating radar measurements around the building perimeter were made at 5-ft intervals over 3,283 ft of traverse along 48 individual profiles, coincident with magnetic profiles. The lines are numbered in sequence and are listed in Appendix B, along with the beginning and ending positions relative to the grid survey. Prior to running the production lines for the survey, replicate runs were made over the same line to determine which of the three transceivers — the 80-, 300-, or 500-MHz antenna — was best suited to study the terrain surrounding the site. The transceiver providing the best penetration and resolution of buried objects was the 300-MHz unit. Different range settings were also tested over the same transect to determine the optimum resolution and depth of penetration. A range setting of 90 ns was used for the entire survey at a scan rate of 16 scans/s. Antennas were pulled by hand at approximately 3 ft/s. Figures 6 and 7 show GPR

a. South-North Profile for Line No. 4

b. South-North Profile for Line No. 48

c. West-East Profile for Line No. 13

d. West-East Profile for Line No. 15

FIGURE 6 Ground-Penetrating Radar Profiles for the Southeast Corner of the Building E5440 Study Area (Refer to Figure 3 for the location of the lines.)

profiles taken at Building E5440. The vertical scale is shown on the right side of the profile, whereas lines are marked at 10-ft intervals on the horizontal scale.

Without verification by another technique or by passing the antenna over a known buried object, characteristics of radar anomalies may only be inferred. However, where anomalies are also seen with magnetic or resistivity profiling, a diagnostic interpretation of the radar anomaly is possible. Good penetration was observed over most of the site, with resolution down to about 8 ft below the ground surface.

GPR surveying is heavily dependent on the state of the ground surface. Because of the diverse surface conditions around the perimeter of Building E5440, the character of the radar signal changed rapidly and often. Although point-source reflectors are observed along some of the profiles, particularly the east-west profiles on the north side of the building, the most common feature of the profiles is signal change due to change in surface conditions. Grassy terrain is generally accompanied by a chaotic radar image, whereas concrete and asphalt surfaces without underlying steel reinforcement support a more coherent subsurface image. Passing the antenna over a steel cover results in a strongly ringing image.

Strong reflectors are observed in several GPR profiles made in the southeast corner of the survey area. Two south-north profiles and two west-east profiles are shown in Figure 6. The strong reflectors are probably associated with a manhole or utility access pit located in the dense bushes just east of the survey area. Ground-penetrating radar lines 4 and 48, which are shown in Figures 6a and 6b, are both south-north lines that reveal a ferromagnetic object extending from the building to the manhole or to the utility access pit located southeast of the building. West-east GPR lines 13 and 15 (Figures 6c and 6d) also show this object. All obvious reflectors on these lines are buried at a depth of approximately 2-2.5 ft below the ground surface.

A second, strong, flat-lying GPR reflector is observed in the southwest corner of the survey area. This reflector is seen in a west-east profile (line 11) and is shown in Figure 7. The anomaly is at a depth of approximately 2.5 ft below the ground surface and is located between grid coordinates 00N,20E and 00N,25E. The shape and size are unknown, but this anomaly is not seen in the profile at line 12, which was collected west-east at 05N. This anomaly could be associated with a brick-lined vault located at grid coordinates 20N,00E.

FIGURE 7 West-East Ground-Penetrating Radar Profile for the Area Southwest of Building E5440 (The location of this profile is shown in Figure 3 as line No. 11.)

4 Discussion

Only the magnetics data set was of mappable quality, and the magnetics map is strongly influenced by building anomalies and by steel fixtures extending from the building (see Figure 8). A resistivity minimum at 10N,20E is associated with a moderate magnetic anomaly; however, the magnetic data quality in the southwest corner of the building was degraded because of large-amplitude magnetic noise. A coherent radar image is also present over this anomaly. The northern edge of the mapped area contains seven isolated one-point magnetic anomalies believed to be associated with construction fill. A multipoint magnetic anomaly in the northeast corner is not identified. A small magnetic complex centered at 70N,173E may be caused, in part, by a steel ladder extending from the ground to the roof of the building. The anomaly is tightly constrained and is elongated north-south, which suggests that it has an additional subsurface contribution. No radar image is associated with this feature. A resistivity profile 10 ft east of the anomaly indicates that this anomaly is not associated with an equivalent electrical feature.

Because of complex magnetic gradients observed in the southeast corner, a 1-ft grid of magnetic stations was established. The magnetic field measured from this dense station network displays five anomalies, ranging from the most northerly one, which has a horizontal dimension of 1 ft, to two multipoint, rectangular anomalies in the southeast corner. The smaller anomalies are interpreted as being caused by shallow ferrous debris, because of their associated high magnetic gradients and their isolated character. Sources producing the larger anomalies are also shallow, but the angular shapes of the anomalies, and the fact that strong, ringing radar reflectors are also associated with them, would argue against their characterization as fill-like material. These anomalies appear to be associated with the manhole or utility access pit southeast of the building.

A magnetic anomaly on the west side of the building is caused by a steel, overhead rail extending from a set of double doors. Two additional single-point anomalies are probably due to ferrous debris, because they are not associated with resistivity or radar anomalies.

FIGURE 8 Color Map of Total Magnetic Field Intensity for Building E5440

5 Conclusions

Specific conclusions drawn from site surveys are as follows:

1. Isolated, one-point magnetic anomalies surrounding the building are believed to be associated with construction fill.
2. A 2,500-gamma, positive magnetic anomaly at coordinates 00N,20E has a 12 Ω -m resistivity value, suggesting a possible buried vault. Strong GPR reflectors are also observed over this feature. The GPR profile shows that the feature is buried at a depth of approximately 2.5 ft.
3. Two rectangular, high-amplitude magnetic anomalies in the southeast corner are associated with strong, ringing radar reflectors. The magnetic anomalies are joined by a linear extension. A secondary magnetic feature extends to the south from the southwest corner of the southern rectangular anomaly. The extensions, also observed on radar imaging profiles, may be produced by buried pipes associated with a manhole or utility access pit located several feet east of the surveyed area.

6 References

AEHA: see U.S. Army Environmental Hygiene Agency.

EAI Corporation, 1989, *Historical Records Search and Site Survey of Edgewood Area Buildings, Final Report*, prepared for U.S. Army Chemical Research, Development, and Engineering Center, Aberdeen Proving Ground, Md., under contract No. DAA15-87-D0021.

Geophysical Survey Systems, Inc., 1987, *Operations Manual for Subsurface Interface Radar (SIR System-3)*.

Golden Software, Inc., 1991, *SURFER Version 4*, Golden, Colo.

Interpex Limited, 1988, *RESIX PLUS User's Manual*, Golden, Colo.

McGinnis, L.D., and S.F. Miller, 1991, *Interim Progress Report - Geophysics: Building E5032 Decommissioning, Aberdeen Proving Ground*, report ANL/ESD/TM-20, Argonne National Laboratory, Argonne, Ill.

McGinnis, L.D., S.F. Miller, M.G. McGinnis, and M.D. Thompson, 1992, unpublished information, Argonne National Laboratory, Argonne, Ill.

Munsell Soil Color Charts, 1975, Macbeth, a division of Kollmorgen Corp., Baltimore, Md.

Oliveros, J.P., and P. Gernhardt, 1989, *Hydrogeologic Data for the Canal Creek Area, Aberdeen Proving Ground, Maryland, April 1986-March 1988*, U.S. Geological Survey Open-File Report 89-387.

U.S. Army Environmental Hygiene Agency, 1989, *RCRA Facility Assessment Report, Edgewood Area, Aberdeen Proving Ground, Maryland*.

U.S. Geological Survey, 1992, *Contamination of Groundwater, Surface Water, and Soil, and Evaluation of Selected Pumpage Scenarios in the Canal Creek Area of Aberdeen Proving Ground, Maryland*, draft open-file report.

USGS: see U.S. Geological Survey.

11-11-11

1

Appendix A:
Electrical Depth-Sounding Curves

Appendix A:

Electrical Depth-Sounding Curves

Four Schlumberger electrical depth soundings near buildings in the Edgewood area provide a depth dimension to resistivities of soils, sediment, and anomalous unidentified materials. Soundings were made near Buildings E5282, E5440, E5481, and E5974. Locations of centers of stations and orientations of electrode arrays are listed in Table A.1, and the curves are shown at the end of Appendix A as Figures A.1-A.4.

Inversion of these curves using the Interpex code, RESIX PLUS (Interpex Limited 1988), indicates that resistivity of dry soils is from 200 to 300 Ω -m;* saturated sediments, about 100 Ω -m; saturated, organic-rich sediments, about 200 Ω -m; and anomalous materials range from less than 10 to 10,000 Ω -m. Maximum current electrode spacings (AB/2) ranged from 40 to 100 m, providing information to depths of about 50 m.

Normal undisturbed curves were observed at Buildings E5282 and E5481. These stations were located in topographically low areas where the water table lies within 3 m of the surface.

A reasonable interpretation of the curve at Building E5440, which was centered in an open area northeast of the building, is not feasible without more historical information about the site. Former roads, landfills, and other subsurface artifacts could explain the orders of magnitude change in resistivity values from 15 Ω -m to 10,000 Ω -m at a depth of 11 m.

TABLE A.1 Location of Centers of Stations and Orientations of Electrode Arrays for Schlumberger Electrical Depth Soundings at APG

Station Center	Array Orientation	Maximum Electrode Spacing (m)
Northeast of Building E5282	E-W	50
Northeast of Building E5440	NW-SE	40
North of Building 5481	E-W	80
Northwest of Building E5974	NW-SE	100

* Electrical depth soundings were measured in the unit of Ω -meter. Thus, discussion of electrical depth soundings in this report gives depths measured in meters. To convert from meters to feet, multiply depths in meters by 3.28.

The sounding curve at Building E5974 displays the most unusual surface resistivities. A 2.7-m-thick layer of extraordinarily high resistivity (3,055 Ω -m) near the surface is underlain by a layer having a higher than normal value (440 Ω -m) extending to a depth of 50 m. This is underlain by a layer having normal resistivities of near 123 Ω -m.

Earth resistivity models calculated from inversion of the sounding curves are shown in Table A.2.

TABLE A.2 Resistivity Models Calculated from Electrical Depth Soundings

Station	Resistivity (Ω -m)	Thickness (m)	Depth (m)
E5282	108	0.4	0.4
	244	4.5	4.9
	95	unknown	unknown
E5440	269	1.2	1.2
	14	10.1	11.3
	11,525	unknown	unknown
E5481	366	4.1	4.1
	105	unknown	unknown
E5974	783	0.9	0.9
	3,055	2.7	3.6
	440	46.4	50.0
	123	unknown	unknown

FIGURE A.1 Electrical Depth-Sounding Curve near Building E5282

FIGURE A.2 Electrical Depth-Sounding Curve near Building E5440

FIGURE A.3 Electrical Depth-Sounding Curve near Building E5481

Appendix B:
Ground-Penetrating Radar Line Coordinates

Appendix B:**Ground-Penetrating Radar Line Coordinates**

Line No.	<u>Start Coordinates</u>		<u>End Coordinates</u>	
	North	East	North	East
1	105	00	105	190
2	100	00	100	190
3	95	00	95	190
4	00	190	110	190
5	00	185	110	185
6	48	180	110	180
7	48	175	110	175
8	50	170	110	170
9	80	169	80	190
10	60	170	60	190
11	00	00	00	190
12	05	00	05	190
13	10	14	10	190
14	15	00	15	190
15	20	7	20	190
16	25	14	25	190
17	00	00	105	00
18	26	05	105	05
19	20	10	110	10
20	10	15	110	15
21	10	20	110	20
22	10	25	60	25
23	88	140	110	140
24	88	105	110	105

Line No.	<u>Start Coordinates</u>		<u>End Coordinates</u>	
	North	East	North	East
25	88	40	110	40
26	00	35	25	35
27	00	40	25	40
28	00	45	25	45
29	00	50	25	50
30	00	55	25	55
31	00	60	25	60
32	00	65	25	65
33	00	70	25	70
34	00	75	22	75
35	00	80	25	80
36	00	85	25	85
37	00	90	25	90
38	00	95	25	95
39	00	100	25	100
40	00	105	25	105
41	00	120	25	120
42	00	130	25	130
43	00	145	25	145
44	00	150	25	150
45	00	165	25	165
46	00	170	25	170
47	00	175	25	175
48	00	180	26	180

END

DATE
FILMED

6 / 24 / 93