001123

1 OF 1

**DOE/MC/26044-3048
(DE92001123)**

**WEAR MECHANISM AND WEAR PREVENTION IN COAL-FUELED DIESEL
ENGINES**

**Task III: Traditional Approaches to Wear Prevention
Topical Report**

**By
J. A. Schwalb**

June 1991

Work Performed Under Contract No. AC21-89MC26044

**For
U.S. Department of Energy
Morgantown Energy Technology Center
Morgantown, West Virginia**

**By
Southwest Research Institute
San Antonio, Texas**

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

This report has been reproduced directly from the best available copy.

Available to DOE and DOE contractors from the Office of Scientific and Technical Information, P.O. Box 62, Oak Ridge, TN 37831; prices available from (615)576-8401, FTS 626-8401.

Available to the public from the National Technical Information Service, U. S. Department of Commerce, 5285 Port Royal Rd., Springfield, VA 22161.

**Wear Mechanism and Wear Prevention in
Coal-Fueled Diesel Engines
Task III: Traditional Approaches to Wear Prevention**

Topical Report

J.A.Schwalb

Work Performed Under Contract No.: DE-AC21-89MC26044

**For
U.S. Department of Energy
Office of Fossil Energy
Morgantown Energy Technology Center
P.O. Box 880
Morgantown, West Virginia 26507-0880**

**By
Southwest Research Institute
Engine, Fuel, and Vehicle Research Division
6220 Culebra Road
San Antonio, Texas 78228-0510**

June 1991

TABLE OF CONTENTS

	Page
ABSTRACT	vi
I. INTRODUCTION	1
II. BACKGROUND	1
III. EXPERIMENTAL APPARATUS AND PROCEDURES	3
A. The Cameron-Plint High Frequency Friction Machine	3
B. Analysis of Ash Contaminant	6
C. Test Matrices	9
1. <i>Surface Finish Tests</i>	9
2. <i>Tests With Various Slot Configurations</i>	10
3. <i>Lubricant Formulation Investigations</i>	10
IV. EXPERIMENTAL RESULTS	11
A. Surface Finish Tests	11
1. <i>Mass Loss of Cylinder and Ring Specimens</i>	13
2. <i>Electrical Resistance Data</i>	13
3. <i>Friction Force Data</i>	16
4. <i>Photomicroscopic Observations</i>	18
5. <i>Observations of Wear Particles</i>	18
6. <i>Profilometric Data</i>	22
B. Slot Configuration Tests	22
1. <i>Mass-Loss of Cylinder and Ring Specimens</i>	22
2. <i>Photomicroscopic Data</i>	27
3. <i>Electrical Resistance Data</i>	31
4. <i>Friction Force Data</i>	32
C. Lube-Oil Additive Test	32
1. <i>Mass-Loss of Cylinder and Ring Specimens</i>	32
2. <i>Photomicroscopic Data</i>	32
3. <i>Electrical Resistance Data</i>	36
4. <i>Friction Force Data</i>	36
5. <i>Ferromagnetic Data</i>	36
6. <i>Profilometric Data</i>	36
V. DISCUSSION	39
A. Surface Finish Investigations	39

TABLE OF CONTENTS (Continued)

	Page
B. Slotted Specimen Data	39
C. Lube-Oil Additive Investigations	40
VI. CONCLUSIONS	40
VII. RECOMMENDATIONS	41
VIII. REFERENCES	43
APPENDIX	47

LIST OF ILLUSTRATIONS

Figure No.		Page
1	Cameron-Plint High Frequency Friction Machine	4
2	Mass Loss of Ring Specimens as a Function of Surface Roughness	14
3	Mass Loss of Cylinder Specimens as a Function of Surface Roughness	15
4	Oscilloscope Trace of Friction Force; 20° Cross-Hatch Angle, 0.4-mm Roughness Average and Clean Oil Case	17
5	Photomicrographs of Ring Specimens for 0° Cross-Hatch, 2.1 μm Surface Roughness Cases	19
6	Photomicrographs of Cylinder Specimens for 0° Cross-Hatch, 2.1 μm Roughness Cases	20
7	Wear Particles Generated by Ash Contaminant (Photomicrographs at 1000 X Magnification)	21
8	Wear Particles Generated With Clean Baseline Oil (Photomicrograph at 1000 X Magnification)	23
9	Spherical-Shaped Wear Particles (Photomicrographs at 500 X Magnification)	24
10	Longitudinal Wear Scars, 0° Cross-Hatch Angle, 2.1 μm Ra	25
11	Mass Loss of Cylinder Specimen (mg)	26
12	Photomicrographs of Cylinder Specimen With 0.15-mm Wide Circumferentially Oriented Slot - Specimen Worn in Clean Lubricant (500 X Magnification)	28
13	Photomicrograph of Cylinder Specimen With 0.15-mm Wide Circumferentially Oriented Slot - Specimen Worn in Lubricant/5% Ash Contaminant Mixture (The slot width shown above is considerably smaller than the original slot width, because the wear scar has almost reached the bottom of the slot.) (500 X Magnification)	29

LIST OF ILLUSTRATIONS (Continued)

Figure No.		Page
14	Photomicrograph of Ring Specimen Worn With 0.15-mm Wide, Longitudinal Slots in the Cylinder Specimen (Specimen Worn in Clean Lubricant) (100 X Magnification)	30
15	Photomicrograph of Cylinder Specimen Corresponding to the Ring Specimen in Figure 14 Above, (0.15-mm Longitudinal Slots) (100 X Magnification)	30
16	Average Friction Coefficient For Slotted Specimen Tests	33
17	Lube-Oil Additive Effects on Wear	34
18	Photomicrographs of Cylinder Specimens Used in Tests With Baseline Lubricant/Dispersant Additive Mixtures	35
19	Cylinder Specimen Longitudinal Wear Scar Profiles	37
20	Cylinder Specimen Circumferential Wear Scar Profiles	38

LIST OF TABLES

Table No.		Page
1	Cameron-Plint Configuration	5
2	Properties of Baseline Oil	6
3	Proximate Analysis of Contaminants	7
4	Particle Size Averages	7
5	Analysis of Contaminant Ash	8
6	Surface Finish Conditions	9
7	Cylinder Specimen Groove Configuration	10
8	Lube-Oil Additives	11
9	Analysis of Additive/Base Oil Mixture	12
10	Non-Zero Electrical Resistance Traces	31

ABSTRACT

Contamination of the lube-oil with hard abrasive particles leads to a three-body abrasive wear mechanism that highly accelerates piston ring/cylinder liner wear in coal-fueled diesel engines. One approach to reducing that wear is to modify the size and orientation of surface asperities on the cylinder to enhance the formation of a hydrodynamic film, and to provide avenues of escape for particles that would otherwise be trapped in the wear zone. Another approach is to introduce additives into the contaminated lube-oil that further enhance hydrodynamic film formation, form chemical films on the wearing surfaces, or form films on the contaminant particles. This work focuses on defining the effects of cylinder liner surface finish, various configurations of slots in the cylinder liner surface, and various additives in the contaminated lube-oil on the wear process. Wear tests were initiated in a bench apparatus using coal-ash contaminated lube-oil to test the various wear configurations.

The results of these tests indicate that the formation of a hydrodynamic film between the ring and cylinder specimens is enhanced by increasing surface roughness, and by orienting the surface asperities normal to the direction of ring travel, but modifications to the cylinder liner surface did not greatly reduce the wear rate. Additives to the lubricant seemed to have a much more significant effect on wear, with a dispersant additive highly accelerating the wear, while a detergent additive was able to reduce the wear almost to the rate achieved when there was no contaminant.

I. INTRODUCTION

This report covers Task 3 of a seven-task program entitled "Wear Mechanisms and Wear Prevention in Coal-Fueled Diesel Engines." The program is a study of piston ring and cylinder liner wear, in support of the DOE line programs at General Electric and A.D. Little/Cooper Bessemer to develop commercially viable coal/water slurry fueled locomotive and stationary diesel engines. Overall, the line programs have concentrated their efforts on developing harder liner and ring materials or coatings. This program, on the other hand, looks at alternative strategies for wear prevention. It was outlined to provide a more fundamental understanding of the wear processes (already completed in Task 1), to investigate novel design approaches to wear prevention (Task 2), to investigate traditional approaches to wear prevention (reported here in Task 3), and to refine and present the most promising wear prevention strategy (Tasks 4 - 6). Task 7 was recently added as a parallel study of wear in a locomotive engine fueled with a coal-derived liquid fuel.

Task 3, entitled "Traditional Approaches to Wear Prevention," focussed on determining the effects of the following three parameters on wear in the abrasive coal/water slurry fueled engine environment.

- Cylinder Surface Finish Conditions
- Various Configurations of Slots in the Cylinder Surface
- Various Additives to the Lube-Oil

After presenting some background information on the nature of the wear problem, this report will describe the experiments performed to study each of the above items.

II. BACKGROUND

Interest continues in the development of coal/water slurry fueled diesel engines that could utilize the large U.S. coal reserves and reduce dependence on foreign oil. Among the obstacles to development is accelerated wear of piston rings and cylinder liners, reported to be as high as 150 times that of engines running on conventional diesel fuel (Kamo and Valdmanis, 1988; Clingenpeel, et al., 1984; Prater and Courtright, 1985; Nydick, et al., 1987; Hsu, 1988; Leonard, et al., 1989; Rao, et al., 1988; Kakwani and Kamo, 1988; Pratt, 1982). This project is an effort to define the mechanisms causing accelerated wear, and to find commercially acceptable means of reducing or preventing it. A previous paper (Schwalb, et al., 1990) analyzed the literature in this subject, and concluded that, although a significant amount of work had been done and a general understanding of the effects of contaminated lube-oil has been obtained, there was still a need for a detailed understanding of the wear mechanism. An in-depth investigation was outlined involving bench scale wear tests with various coal-related contaminants introduced into the lube-oil. The results revealed a complex wear mechanism involving soft abrasive "polishing" type wear caused by carbon particles, and hard abrasive three-

body wear caused by hard minerals in the coal. The carbon wear process was significant, but seemed to be self-limiting, while the hard abrasive process continued to increase with concentration of abrasive. This seems consistent with the literature that indicates that carbon can be of concern (Yahagi (1987) and Berbezier, et al. (1986) are examples of studies concerned with accelerated wear caused by soot) but that the harder minerals found in the ash are the primary focus of most of the engine test research. Flynn, et al. (1989) present an example of the type of wear observed in engine tests where a nitrided cylinder surface appeared polished after wearing. Aghan and Samuels (1970) suggest that this is an abrasive wear mechanism, identical to the mechanism caused by larger particles which result in much rougher surfaces. It should be noted that adhesive wear also remains a possibility. Rabinowicz and Mutis (1965) and Sudarshan and Bhaduri (1983) reiterate the fact that adhesive wear commonly occurs at TDC in engines operating on diesel fuel, and may be occurring in conjunction with abrasive wear in the coal-fueled engines.

Having established some understanding of the wear mechanisms, the question remains of how to reduce or eliminate the accelerated wear process in a way that is economically acceptable. Typically, researchers (Kamo and Valdmanis, 1988; Prater and Courtright, 1985; Mehan, 1988; Flynn, et al., 1989) have concentrated on hardening the liners and rings, making them more resistant to the wear process. Hardening has reduced wear, but serious questions remain about the economic feasibility of the various hardening processes. The approach of this study was to look at more conventional approaches which depend on the unique interactions of particle size, hydrodynamic film thickness, surface finish, surface geometry, and lubricant formulation.

For example, it is known that particles much larger than the hydrodynamic film thicknesses do not participate in the wear process because they simply cannot get into the wear zone (Fitzsimmons and Clevenger (1975), Ives, et al. (1988) and Mehan (1988) observed this phenomenon). One might conclude that it is advantageous to have a thin hydrodynamic film and somehow eliminate smaller particles from the contaminant. On the other end of the spectrum, it is known that particles much smaller than the hydrodynamic film thicknesses do not cause significant wear either. If this is the case, then it may be advantageous to maximize hydrodynamic film thickness while minimizing the particle size.

Wear will also be influenced by changing surface finish. Traditionally, surface finish practices have been determined by trial and error experience over the years (Hesling, 1963). Plateau hones in the range of $R_a = 0.5$ to 0.75 micron and cross-hatch angles from 22° - 32° were the generally accepted specifications, chosen because it was felt they accomplished the following goals.

- As suggested by Sreenath and Raman (1976), they provide a fairly rough initial surface that promotes quick conformance ("seating") of the ring to the cylinder geometry.

- The large grooves store oil to prevent scuffing at start-up and at times of overloading.
- There is a hydrodynamic effect caused by thermal expansion of oil in the grooves.
- It was speculated that the grooves act as a repository for wear particles (Barber, et al., 1987).

How can surface finish be used to reduce wear? For one thing, the items listed above suggest that large grooves might provide repositories, or avenues of escape for abrasive particles that might otherwise enter the wear zone. Also, Janczak and Wisniewski (1987) and Richez, et al. (1983) suggest that increased surface asperity height can increase the hydrodynamic film thickness. On the other hand, rougher surface finish increases the risk of adhesive wear, and could allow more and larger abrasive particles into the wear zone.

The above discussions illustrate some of the tradeoffs that exist between particle size, hydrodynamic film thickness, and surface finish. The approach of this study was to investigate those interactions in a bench scale simulation of the engine wear environment. Tests were completed under varying conditions of contaminant particle size, cylinder liner surface roughness, orientation of asperities on the surface, cylinder surface slot configurations, and lubricant formulations. Comparisons were made based on detailed analysis of the wear specimens.

III. EXPERIMENTAL APPARATUS AND PROCEDURES

A. The Cameron-Plint High-Frequency Friction Machine

The apparatus chosen for these tests is the Cameron-Plint high frequency friction machine. The commercially available machine, shown schematically in Figure 1, provides a reciprocating motion through a scotch yoke drive mechanism that simulates the relative motion of the piston ring and cylinder liner in a diesel engine. A specimen of piston ring material is mounted to the bottom of a reciprocating arm where it can rub against a rigidly mounted cylinder liner specimen. Both the ring and cylinder specimens are immersed in a bath containing the contaminated lubricant being tested. Above the reciprocating arm is a spring tensioned bar that applies a force normal to the direction of travel. The arm is also instrumented to measure friction force (force in the direction of ring travel) and electrical resistance between the ring and cylinder specimens (an indication of the thickness of the hydrodynamic film). Friction force and electrical resistance measurements were monitored for some cases on an oscilloscope where cycle resolved information was obtained, and for all cases on a strip-chart recorder where a time-averaged signal was recorded. Details of how the Cameron-Plint machine was configured for all the tests reported here are contained in Table 1.

Figure 1. Cameron-Plint High Frequency Friction Machine

Table 1. Cameron-Plint Configuration	
Normal Load	200 N
Frequency of Stroke	17 Hz (1020 RPM)
Ring Piece:	
Source	89 mm O.D. cast iron ring
Size	Wedge-shaped piece approximately 3 mm base x 1 mm top x 5 mm wide x 2 mm thick
Approx. Weight	0.3 g
Wear Surf. Area	2 mm ²
Loading	100 MPa
Cylinder Liner Piece:	
Source	96.5 mm I.D. cylinder liner for Labeco CLR engine
Size	55 mm x 25 mm x 3-5 mm thick (thickness varies because of the curvature of the liner).
Approximate Weight	37 g

Test specimens were chosen to represent typical cast-iron materials used in diesel engines. Cylinder pieces were cut from the 96.5 mm I.D. cylinder liners of a Labeco CLR engine. Each piece was machined to dimensions of 55 mm x 25 mm, flattened on the back so that it varies from 3 - 4 mm thick and weighing approximately 37 grams. Ring specimens were cut from 89 mm D x 2 mm thick cast iron rings and were ground into a wedge shape, 1 mm at the face expanding to 3 mm wide at the base, and weighing approximately 0.3 grams. The wearing surface of 1 mm x 2 mm is exposed to a normal force of 200 N, resulting in 100 MPa contact pressure (approximately an order of magnitude higher than the maximum pressure seen in actual diesel engines). With a stroke of 17 mm, the maximum velocity of the ring specimen is approximately 0.9 m/s. This information, along with information on the geometry of the wear specimens was input into a hydrodynamic flow model to calculate Hertzian stress and hydrodynamic film thickness assuming an elliptical contact region (Harris, 1984, Dawson and Higginson, 1977, Chittenden, et al., 1985, and Johnson 1985 provide detailed descriptions of the model).

The result of those calculations was a maximum film thickness about 0.34 micrometers. Surface roughness for the tests in this program varied from 0.12 to 2.1 micrometers, so it seems apparent that at almost all times, the wear specimens are in the boundary lubrication regime (indicating there is probably some contact of asperities always) as opposed to hydrodynamic lubrication. This does not preclude the possibility of hydrodynamic effects in which wear is reduced because part of the load is being born by a thin hydrodynamic film.

Details of the baseline lube-oil properties are contained in Table 2. The oil was chosen as representative of typical diesel lube-oil properties, but without any additives.

Table 2. Properties of Baseline Oil	
40° C Viscosity	143.88 cSt
100° C Viscosity	13.99 cSt
V.I.	93
API Gravity	28.6 @ 15.6° C
T.A.N.	0.01
T.B.N.	0.09
Flash Point	293° C
%N	0.012
%Ca	N.D.
%Zn	N.D.
%P	<0.01
%S	0.21

B. Analysis of Ash Contaminant

Proximate analyses of the contaminants used in this program are included in Table 3, and particle size analyses in Table 4. The contaminants were originally chosen to represent a range of carbon versus ash content. Since the intent for this Task of the program was to study particle size and surface finish effects, only the Kentucky Splint ash (after fluid-energy mill grinding) was used. Table 5 contains the results of X-ray fluorescence analysis on that ash which confirms that silicon, aluminum, iron and calcium

Table 3. Proximate Analysis of Contaminants

Description	Feed Stock	Ash	Vol. Matter	Fixed Carbon
Low-Ash Coal	Unknown	1.00%	34.51%	64.14%
Carbon Black	Mogul-L	0	0	100%
High-Ash Coal	Kentucky Splint	22.9%	30.5%	46.6%
Cleaned Coal	Kentucky Splint	0.38%	37.73%	61.88%
Ash Product	Kentucky Splint	85.3%	10.6%	4.1%

Table 4. Particle Size Averages

Contaminant	Number Weight Averages		Volume Weighted Averages	
	Arith. Mean	Log Mean	Arith. Mean	Log Mean
Low-Ash Coal	4.8	4.1	13.8	11.5
Carbon Black	3.9	3.1	9.9	9.0
Raw Kentucky Splint Coal	4.1	3.1	15.1	13.2
Cleaned Kentucky	5.5	4.1	18.9	16.7
Ash From Kentucky Splint Coal	13.7	12.5	33.4	27.2
Ash From Kentucky Splint Coal Ground in Fluid Energy Mill	2.8	1.9	9.2	8.3
Syloid 63 Silica	2.4	1.6	10.6	0.6

seem to be the major elements present, although the form of those elements is not so certain. A brief review of the literature on coal ash mineralogy (Mitchell and Gluskoter, 1976; Tsai, 1982; Jones, et al., 1985; Wilson, et al., 1986; Unsworth, et al., 1987; Unsworth, et al., 1988) indicates that silicon is most likely present in quartz. Aluminum might be present as alumina, but is more likely to be found with silicon in aluminosilicate compounds. Iron is predominantly in some form of pyrite, and calcium can be present as calcite, bassanite, or dolomite. The heat of combustion will, of course alter those compounds, primarily in the dehydration of various silicate materials, the release of CO₂ from carbonates, and the oxidation of pyrites to iron oxides. For wear processes, the hard minerals, quartz, alumina, and pyrite primarily are of the most concern.

Table 5. Analysis of Contaminant Ash					
	(Weight Percent of Ash)				
	Cleaned K.S. Coal	Low-Ash Coal	Raw K.S. Coal	Ash From K.S. Coal	Syloid 63 Silica
SiO ₂	39.42	41.72	60.85	65.31	98.58
Al ₂ O ₃	14.55	29.20	23.78	22.09	1.18
Fe ₂ O ₃	25.40	14.77	5.34	3.55	0.18
CaO	5.15	8.66	2.06	1.57	0
MgO	1.72	0.92	1.42	1.88	0
Na ₂ O	0.13	0.07	0	0	0
K ₂ O	0.78	1.94	4.20	4.78	0.06
Ti ₂ O	6.17	1.03	0.70	0.82	0
Cr ₂ O ₃	0.37	0.04	0.61	0	0
NiO	3.82	0.19	0.94	0	0
CuO ₂	0.72	0.27	0.10	0	0
SO ₃	1.77	1.19	0	0	0

C. Test Matrices

1. Surface Finish Tests

Machining of the cylinder specimen faces was done using honing, lapping and milling processes as outlined in Table 6 so that a range of different surface roughness and cross-hatch orientations could be obtained. Some of the processes were done on individual specimens while others were done on whole cylinders before they were cut into pieces, but it is felt that they all represent fairly common machining practices which could be easily adapted for large scale processes. As is conventionally done, the roughness values are presented as " R_a ", an arithmetic average of the magnitude of peaks and valleys in the roughness profile. Caution should be used, however, in interpreting these values since R_a says nothing about the spacing, symmetry, or distribution of grooves in the surface. Lapped surfaces, for example, appear quite different from honed or milled surfaces under the microscope (they tend to have short, overlapping scratches rather than continuous grooves) even though they may have similar R_a values. The other concern is the fact that specimens with 90° cross-hatch angles (axially oriented machining marks) could not be measured with the existing profilometer equipment because the orientation of the grind marks (referred to as the "lay" of the surface finish) is parallel to the direction of travel of the profilometer stylus.

Table 6. Surface Finish Conditions	
R_a (microns)	Cross-Hatch Angle
0.65	0
1.80	0
2.10	0
0.18	20
0.43	20
1.62	20
0.42	25
1.80	25
0.62	90
0.80	90

2. Tests With Various Slot Configurations

Table 7 lists the different slot configurations machined into the surface of the cylinder specimens. The basic idea behind using slots in cylinder liners was that they might enhance the formation of a hydrodynamic film, while providing avenues of escape for wear particles that would otherwise be dragged over or along the entire stroke of the ring piece. Slots were provided both longitudinally (in line with the direction of ring travel) and circumferentially (normal to the direction of ring travel). The spacings were chosen to provide comparisons of various slot widths with equivalent surface area as well as various surface areas at equivalent slot width. Because of the Cameron-Plint configuration it was not possible to measure the ring sealing, although it is recognized that blow-by could be a serious concern, especially with the longitudinal slots.

Table 7. Cylinder Specimen Slot Configuration			
Number of Slots	Slot Width (mm)	Spacing Between Slots (mm)	Slot Orientation (Circumferential or Longitudinal)
90	0.15	0.30	C
12	0.15	0.30	L
60	0.15	0.50	C
8	0.15	0.50	L
60	0.25	0.50	C
8	0.25	0.50	L
60	0.35	0.50	C
8	0.35	0.50	L
2	0.25	10.00	C

3. Lubricant Formulation Investigations

For coal-fueled diesel engine applications, it may be possible to reduce wear by tailoring the lubricant formulation to handle abrasive contaminants. It was beyond the scope of this project to do a thorough study of the many available lubricant additives and the many combinations of additives that are possible. Instead, a few additives were chosen from the general classifications and were tested individually, when mixed in an

additive-free baseline lubricant. The results could not be used to optimize lubricant formulation, but they would indicate the magnitude of the effect of lubricant formulation, and give at least a qualitative feel for how different classes of additives affect the wear process. Wear tests were performed with clean additive/oil mixture, and with a 5 percent concentration of coal ash contaminant in the mixture. Descriptions of the additive/oil mixtures are included in Table 8.

Table 8. Lube-Oil Additives	
Additive	Concentration (% by mass)
Highly Basic Calcium Sulfonate Detergent	19
Ashless Dispersant	5.2
Alkyl Zinc Dithiophosphate	0.630 (approx. 0.1 % Zn)
Aryl Zinc Dithiophosphate	0.466 (approx. 0.1 % Zn)
Non-Dispersant Olefin Co-polymer (VI Improver)	10
Olefin Thickener	10

Further analysis of the additive/oil mixtures has been performed, and the results are outlined in Table 9.

IV. EXPERIMENTAL RESULTS

A. Surface Finish Tests

The following data was compiled for the test matrix described above.

- Mass Loss of Cylinder and Ring Specimens
- Electrical Resistance Between Ring and Cylinder Specimens as a Function of Time During Each Test

- Friction Force as a Function of Time During Each Test
- Photomicroscopic Observations of the Cylinder and Ring Specimens
- Observations of Wear Particles Using a Ferrographic Technique
- Profilometric Data

Table 9. Analysis of Additive/Base Oil Mixtures							
	Baseline Oil	19% Calcium Sulfonate Detergent	5.2% Ashless Dispersant	0.47% Aryl Zinc Dithio-phosphate	0.63% Alkyl Zinc Dithio-phosphate	10% Non-Dispersant Olefin Co-polymer	10% Olefin Thickener
Kinematic Viscosity at 40° C (cSt)	143.9	163.1	160.9	144.9	143.5	260.3	184.8
Kinematic Viscosity at 100° C (cSt)	13.99	14.98	15.69	13.97	13.88	24.89	17.53
Viscosity Index	93	90	99	92	93	122	99
API Gravity (at 15.6° C)	28.6	20.1	27.3	28.2	28.2	28.6	28.9
TAN	0.01	1.18	0.12	0.28	0.90	0.04	0.06
TBN	0.09	79.61	0.30	0.27	0.45	0.24	0.15
Flash Point (° C)	293	260	266	254	268	257	274
% N	0.012	0.009	0.026	0.012	0.012	0.010	0.010
% Ca	N.D.	0.897	0.008	0.007	0.007	0.006	0.007
% Zn	N.D.	0.0002	0.3 ppm	0.019	0.074	0.002	0.002
% P	<0.01	0.007	0.012	0.012	0.021	0.010	0.014
% S	0.21	0.487	0.279	0.329	0.431	0.312	0.269

1. Mass Loss of Cylinder and Ring Specimens

Figures 2 and 3 present mass loss of ring and cylinder specimens as a function of average surface roughness for cross-hatch angles of 0°, 20°, 25°, and 90° (it should be noted that the 0° case represents all circumferential grind marks while the 90° case represents all axially oriented marks). Data is presented for tests run with baseline oil alone (labeled on the graph as the "0 % Ash" case) and for those run with a 5 percent mixture of ground Kentucky Splint ash. The following observations can be made about these graphs.

- The variation of surface roughness and cross-hatch orientation did not significantly degrade the wear performance under clean oil conditions.
- There was an effect of cross-hatch angle on wear. Although there is not a clear trend, the smaller angles (0° and 20°) cause slightly less wear.
- The general trend is for wear to increase with surface roughness, although that trend is not so obvious for the 0° case.
- There is a notable increase in wear for the smoothest finish in both the clean oil and 5 percent ash tests.

As surface finish becomes smoother and smoother, one might expect that the effect of groove orientation would disappear, and that all the 5 percent ash curves in Figures 2 and 3 should converge to a single value at zero roughness. Assuming this is true, the trend established by the smoothest data points (plotted in Figures 2 and 3 on the 20° cross-hatch angle curves) suggests that wear starts out at a high value, reaches a minimum somewhere in the 0.4 - 0.8 micron range, and then increases again. Again, the 0° curves are somewhat of an exception to this trend since they seem to be leveling off at higher surface roughness. At any rate, an important point to make is that there appears to be no advantage in going to extremely smooth cylinder surfaces.

2. Electrical Resistance Data

Electrical resistance between the ring and cylinder specimens was recorded for the four hour duration of each of the tests described above. For most of these tests, resistance was zero on both the oscilloscope trace and the strip-chart recording for the entire duration. In those cases where ash contaminant was added to the lube-oil, the readings may be in question because of the conductive properties of the contaminant, but for the clean oil tests there must be some degree of metal to metal contact at all times.

Figure 2. Mass Loss of Ring Specimens as a Function of Surface Roughness

Figure 3. Mass Loss of Cylinder Specimens as a Function of Surface Roughness

The interesting aspect about this data, however, is those few cases where a finite resistance was measured, confirming the formation of a complete film. The only case that consistently registered finite resistance measures was with the 0° cross-hatch and 2.1 micron R_a . This seems to confirm that rougher surfaces can, in fact, enhance the formation of the hydrodynamic film as proposed by Janczak and Wisniewski, and Richez, et al. The film formation process, however, is also dependent on the orientation of the surface grooves relative to the ring motion. Other cases where films were seen include the 0°, 0.4 micron case and the 90°, 0.4 micron case, but these did not form consistently in all test repeats. In all cases where a film formed, the resistance measurement started at zero and fluctuated, but steadily increased over the four hour test.

3. Friction Force Data

Friction force was also recorded over the four hour duration of each of the tests performed. In some cases, the friction force signal was monitored on an oscilloscope as well. Figure 4 is a photograph of a typical oscilloscope trace. This trace happens to be for a test with clean baseline oil, and using a 20° cross-hatch, 0.4 micron roughness cylinder specimen, but the shape of all the friction force traces did not vary significantly from this basic outline. The shape of the trace indicates an initial spike as the ring specimen breaks away from the static position at the ring reversal point. The force then drops to a fairly constant value with a few oscillations for the remainder of the stroke. The next ring reversal is characterized by a change in sign, and a similar shaped curve is traced on the negative side. The fact that the trace is symmetrical, and that the force is constant for most of the stroke gives confidence that the normal force is being applied uniformly over the duration of the cycle.

The strip-chart recordings of cycle-averaged friction force have been analyzed as well. A few conclusions can be drawn from that analysis.

- All tests exhibited some initial transient behavior (a kind of "break-in" period), but settled to an established trend within the first half hour of testing.
- Tests performed with clean lube-oil had a fairly constant friction force for the entire duration.
- Tests performed with ash contaminant had constant, or slowly increasing friction force throughout the test duration.
- Tests with ash contaminant exhibited high frequency oscillations in the friction force trace that make it appear much rougher than the corresponding clean-oil traces.

Figure 4. Oscilloscope Trace of Friction Force; 20° Cross-Hatch Angle, 0.4-mm Roughness Average, and Clean Oil C

- Magnitude of friction force was 1.5 - 2.0 times higher for the ash contaminated oil than for the clean oil.

4. *Photomicroscopic Observations*

Ring and cylinder specimen wear scars were observed using light microscopy for several of the test conditions. Figures 5 and 6 are photomicrographs of ring and cylinder specimens (0° cross-hatch, 2.1 micron surface roughness cases run with the clean oil, and with the ash-contaminated oil). Comparing clean oil to contaminated oil cases reveals the difference in wear mechanisms. Clean oil resulted in smoothing over of the surface, gradually removing the original surface finish. Figure 6 shows some of the original finish is still present in the form of large vertical gouges, but the spaces in between have been smoothed by the wear process. Contaminated oil, as in the previous study (Schwalb, et al., 1990) resulted in deep, sharp grooves in both the cylinder and ring pieces. In all cases with contaminated oil, the original finish was completely removed by the end of the test.

The wear scars presented in Figures 5 and 6 were typical for all the original surface finish conditions tested. This indicates that the finish has not significantly affected the wear mechanism in the clean oil cases. The contaminated oil cases are more difficult to interpret. Since the wear in all cases was enough to remove the entire original surface finish, it is not surprising that there is little difference in the appearance of wear scars. On the other hand, since the wear magnitude was significantly affected by original surface finish, the finish must have had an effect, at least in the initial stages of the wear process.

5. *Observations of Wear Particles*

Wear particles were deposited onto a microscope slide for several cases using the ferrography technique described by Anderson (1982). The technique involves taking a sample of the lubricant/contaminant combination used in the wear test, and allowing it to flow slowly over a slightly inclined microscope slide that is located in a magnetic field. Ferrous particles will be attracted by the magnet, and will deposit on the slide while non-ferrous particles are more likely to remain suspended in the oil, or will deposit at a location farther downstream. The ferrous particles can also be identified because of their tendency to line up in straight lines along the magnetic field lines.

As it turned out, the technique was not effective for the cases where ground Kentucky Splint ash was used. There were simply too many non-ferrous ash particles in the sample that deposited uniformly over the whole slide and made it impossible to pick out the wear particles. The technique was effective, however, for the unground Kentucky Splint ash, and photomicrographs of two types of wear particles are presented in Figure 7. The platelets shown in Figure 7 were the predominant type of particle seen. They are definitely ferrous as evidenced by the way they line up, and appear similar to wear particles seen in normal rubbing wear which has been accelerated by a three-body abrasive mechanism. A few large flakes were also seen, although it cannot be confirmed

(a) Clean Oil

(b) 5% Kentucky Splint Ash

Figure 5. Photomicrographs of Ring Specimens for 0° Cross-Hatch, 2.1 μm Surface Roughness Cases

(a) Clean Oil

(b) 5% Kentucky Splint Ash

Figure 6. Photomicrographs of Cylinder Specimens for 0° Cross-Hatch Angle, 2.1 μm Roughness Cases

Small Platelets

Large Flake

Figure 7. Wear Particles Generated by Ash Contaminant (Photomicrographs at 1000 X Magnification)

that they are ferrous wear particles. This type of particle is more typically seen in rolling wear applications where fatigue is a problem, so it is unclear why it would be present in these cases.

The technique was also used for a clean oil case, the results of which are shown in Figure 8. Again, the predominant wear particles were small platelets typical of normal rubbing wear, while a few large, thin flakes also appeared. It is interesting to compare these particles with those produced when a more carbonaceous contaminant was introduced into the oil. Figure 9 shows photomicrographs of wear particles obtained when carbon black and low-ash coal were used as contaminants (these tests were run during the previous study (Task 1) and data for them is presented in Schwalb, et al. (1990), and in the topical report for Task 1). The carbon black photomicrograph shows a scattered range of particles, some of which appear spherical, but they are not lined up enough to determine whether they are ferrous wear particles. The low-ash coal photomicrograph reveals some particles that are definitely ferrous, and are spherical. The spherical type particles are also typical of a rolling fatigue type wear, so it is interesting that they appear in what should be exclusively sliding wear.

6. Profilometric Data

Profiles of the cylinder specimen wear scar surfaces have been obtained for each test using a Talysurf 10 profilometer. The profiles were recorded at two positions in the longitudinal direction (the direction of ring travel) and three positions (evenly spaced) in the crosswise direction. Examples of longitudinal profiles for a few cases are shown in Figure 10. The profiles show the original surface finish, and how it is smoothed by clean oil wear. They also show how the entire surface finish is removed during the ash-contaminated oil test, confirming what was seen in the photomicrographic data. Also of note is the characteristic shape of the scars that reach their deepest points at the ring reversal locations. This characteristic shape was noted for all the tests presented here which had a significant amount of wear, and is consistent with what was seen in the previous study (Schwalb, et al., 1990). It indicates that the wear is definitely dependent on the dynamic motion of the ring, and suggests that there is a hydrodynamic effect at the center of travel of the ring that breaks down at its reversal points.

B. Slot Configuration Tests

1. Mass-Loss of Cylinder and Ring Specimens

Table 7 lists the different slot configurations that were machined into the surface of cylinder specimens for testing on the Cameron-Plint Machine. Each of the configurations listed in Table 7 was tested twice with clean baseline oil and twice with 5 percent ground Kentucky Splint ash contaminant in the oil. The mass-loss wear results (averaged over the two test repeats at each condition) are presented in the bar chart in Figure 11. A few general conclusions can be made about these results.

**Figure 8. Wear Particles Generated With Clean Baseline Oil
(Photomicrograph at 1000 X Magnification)**

Carbon Black

Low-Ash Coal

Figure 9. Spherical-Shaped Wear Particles (Photomicrographs at 500 X Magnification)

Figure 10. Longitudinal Wear Scars, 0° Cross-Hatch Angle, 2.1 μm Ra

Figure 11. Mass Loss of Cylinder Specimen (mg)

- All the configurations displayed at least as much, if not more wear than the un-slotted specimens.
- With one exception, longitudinal slots had slightly more wear than circumferential slots of the same width and spacing.
- Generally, wear increased with slot width
- There was not a clear correlation of slot spacing (or number of slots in the ring travel area) with wear. In fact, a configuration with only two circumferential slots (the 0.25 mm wide, 10.0 mm spacing configuration) had even more wear than a configuration with 34 circumferential slots in the ring travel area (the 0.25 mm wide, 0.5 mm spacing configuration).

2. *Photomicroscopic Data*

Under a photomicroscope, the slotted specimens revealed the same wear patterns as were seen in the un-slotted specimens; long straight grooves that became sharper and deeper when an ash contaminant was mixed with the lube-oil. Figures 12 and 13 are sample photomicrographs of cylinder specimens worn without and with ash contaminant, respectively. The large gray area running horizontally through the middle of each photomicrograph is a circumferential slot, while the vertical light and dark lines are wear grooves parallel to the direction of ring travel. It is apparent from the figures that wear grooves that begin on one side of the slot continue on the other, indicating (as expected) that there must be some degree of conformity between the wear groove pattern on the ring and the pattern on the cylinder. Figures 14 and 15 are photomicrographs of the ring/cylinder specimens used when longitudinal slots were cut into the cylinder specimen. This time, the large dark bands running parallel to the wear scar marks are the slots. Conformity is even more apparent in Figure 14. The photomicrograph of the ring specimen shows alternating bands of worn versus unworn material directly corresponding to the slot spacing.

It seems apparent from this data that the introduction of slots, either longitudinally or circumferentially has not reduced the magnitude of the wear, nor has it changed the appearance of the worn areas. The fact that wear grooves continue from one side of a slot to another gives testament to the statistical nature of the wear process, and the natural tendency for wearing pieces to conform to one another. Apparently, the actual abrasive wear occurs on a smaller scale than the easily visible grooves in the wear scar, and occurs with enough frequency that a fairly smooth, continuous wear scar is produced.

Figure 12. Photomicrograph of Cylinder Specimen With 0.15 mm Wide Circumferentially Oriented Slot - Specimen Worn in Clean Lubricant (500 X Magnification)

Figure 13. Photomicrograph of Cylinder Specimen With 0.15-mm Wide Circumferentially Oriented Slot - Specimen Worn in Lubricant/5% Ash Contaminant Mixture (The slot width shown above is considerably smaller than the original slot width because the wear scar has almost reached the bottom of the slot.) (500 X Magnification)

Figure 14. Photomicrograph of Ring Specimen Worn With 0.15-mm Wide, Longitudinal Slots in the Cylinder Specimen (Specimen Worn in Clean Lubricant) - 100 X Magnification

Figure 15. Photomicrograph of Cylinder Specimen Corresponding to the Ring Specimen in Figure 14 Above, (0.15-mm Longitudinal Slots) - 100 X Magnification

It is significant, however, that in comparing Figures 12 and 13, the piece worn with the ash contaminant appears rougher and fuzzier between the wear grooves. That roughness may be the accumulation of many individual gouges caused by small abrasive particles.

While the introduction of slots does not significantly change the wear mechanism, it might still reduce the magnitude of the wear rate by channeling abrasive particles away and/or diluting the concentration of particles in the wear zone. The current Cameron-Plint test is not a fair indicator of this process since the entire wear zone is immersed in a bath of constant concentration particles. If there were any channeling or dilution effect, the removed particles would simply be replaced by new particles of the same concentration. In the engine, on the other hand, the ring/cylinder zone is constantly supplied from one side by relatively clean oil. Future studies may look at modifications to the current Cameron-Plint configuration to allow for the introduction of clean oil to one side of the wear zone.

3. *Electrical Resistance Data*

As in all the Cameron-Plint tests performed for this study, the electrical resistance between ring and cylinder specimens was monitored continuously throughout each wear test. The presence of a resistance is significant since the measurement of a non-zero resistance indicates the developed hydrodynamic film or a chemical film. In most of the cases tested in this study, the resistance went to zero and stayed there for the entire duration of the test, but with the slotted specimens, there were a few cases where a finite resistance was measured. Table 10 outlines the conditions where a finite resistance occurred. All of them were cases in which no contaminating additive was present.

Table 10. Non-Zero Electrical Resistance Traces		
Test Number	Slot Width/Spacing (mm/-mm)	Slot Orientation
T121	0.15/0.30	Circumferential
T131	0.25/0.50	Circumferential
T143	0.35/0.50	Circumferential

Generally the traces started at zero and gradually developed a finite resistance as the test went on. The trace was generally rough with high frequency oscillations that sometimes dropped the trace back into a zero resistance mode. Also of note is the fact that all the cases listed in Table 10 had circumferential slots. Evidence was presented in the previous section that orienting grind marks (comprising the surface finish) normal to the direction of ring travel enhanced the formation of a hydrodynamic film. It seems

likely that orienting the much larger slots normal to the direction of ring travel has the same effect. In either case, however, the effect was not enough to significantly reduce the wear.

4. Friction Force Data

A time averaged friction force was also recorded over the duration of each test. In general, following some transient behavior in the first 30 minutes of the test, the traces leveled off to a fairly constant value. Traces for tests with ash contaminant were overall rougher than their corresponding clean-oil cases, and sometimes exhibited a general trend to increase or decrease slightly over the duration of the test. Figure 16 shows the approximate friction coefficient data for all the slotted specimen tests. The magnitude of the coefficient data indicates that adhesive wear is, at least, a possibility. Also, most of the data indicates a marginal increase in friction force with the ash contaminant.

C. Lube-Oil Additive Tests

1. Mass-Loss of Cylinder and Ring Specimens

Figure 17 presents the averaged cylinder specimen mass-loss data that was obtained when testing various additive packages. The matrix, of course, was not meant to be an all-inclusive study of available additives, but it did allow for testing of at least one additive from several of the major categories. The results presented in Figure 17 show a dramatic reduction of wear with the calcium sulfonate detergent, a dramatic increase of wear with the ashless dispersant, and a less significant increase of wear with the remaining additives (although that increase is probably within the variability of the data).

2. Photomicroscopic Data

For most of the cases, observations of the wear scars revealed the same predominant wear patterns as were observed in the "no-additive" cases; long, straight grooves which became much sharper and deeper when ash contaminant was added to the mixture. The detergent/contaminant case was an exception in that it did not show obvious differences between clean lubricant and contaminated lubricant cases. Another slight exception to this trend was the dispersant/no contaminant case shown in Figure 18 that had a highly polished surface, similar to the surfaces seen in the previous study where lubricant was contaminated with carbon black. Whatever the difference was, however, it did not seem to affect the wear process when ash contaminant was present. The ash contaminated case is shown also in Figure 18 that confirms the long straight groove wear pattern. As in all cases observed in this program, there was little evidence of particles sticking in either wear specimens, again confirming that this is probably not a two-body mechanism. The size of grooves in the photomicrographs is approximately 10 micron and smaller, indicating that the grooves roughly correlate with the size of the particles.

Figure 16. Average Friction Coefficient For Slotted Specimen Tests

Figure 17. Lube-Oil Additive Effects on Wear

Clean Lubricant-Worn Specimen(500 X Magnification)

**Lubricant + 5% Ash Worn Specimen
(500 X Magnification)**

**Figure 18. Photomicrographs of Cylinder Specimens Used in Tests
With Baseline Lubricant/Dispersant Additive Mixtures**

3. Electrical Resistance Data

Except for the Syton 100 thickener runs, all the clean lubricant tests exhibited a measurable resistance between the wear specimens. This is not particularly surprising since most of the additives are designed to have some surface reactivity. Once ash contaminant was added to the lubricant mixture, however, that measurable resistance quickly went to zero for all cases except the calcium sulfonate detergent runs. They exhibited a widely fluctuating, but finite electrical resistance measurement even when ash contaminant was present in the mixture. This is quite significant because of all the tests done in this study, including variations of additives, surface slot configurations, surface finish parameters, and contaminant composition it was the only condition that resulted in a non-zero resistance in an ash-contaminated test. Clearly this indicates the existence of a much thicker hydrodynamic film, or a much more durable surface coating, which may explain the significant wear reduction.

4. Friction Force Data

Friction coefficient for tests with the additives was 0.15 - 0.18 for the clean lubricant tests and rising to 0.25 - 0.28 for tests with ash contaminant in the lubricant. (Tests with the clean baseline oil without any additives were in the 0.15-0.18 friction coefficient range also.) The one exception to this trend was the detergent additive, for which the friction coefficient stayed at approximately 0.18 even though an ash contaminant was present.

5. Ferromagnetic Data

The ferromagnetic technique for separating wear particles was also employed on lubricant samples following tests with the calcium sulfonate detergent and the ashless dispersant. Once again the ferrograms revealed small rounded platelets that are typical of both normal rubbing wear and three-body abrasion. No cutting wear particles were observed.

6. Profilometric Data

Profiles of the cylinder specimen wear scars are shown in Figure 19 for the longitudinal direction and Figure 20 for the circumferential direction. The two profiles shown in each figure represent cases where the detergent additive was used with and without ash contaminant in the lube-oil. The traces are shown as examples of the type of data that was obtained, but also illustrate the fact that, even though the magnitude of wear was similar between the two cases, there were slight differences in the wear scar produced. Traces for the other additives were not significantly different from the "no-additive" case.

a. Clean Oil/Detergent Mixture

b. Ash Contaminated Oil/Detergent Mixture

Figure 19. Cylinder Specimen Longitudinal Wear Scar Profiles

a. Clean Oil/Detergent Mixture

B. Ash Contaminated Oil/Detergent Mixture

Figure 20. Cylinder Specimen Circumferential Wear Scar Profiles

V. DISCUSSION

A. Surface Finish Investigations

The study reveals some useful information about how surface finish can be used to enhance the formation of a hydrodynamic film, and thus reduce, or at least minimize the rate of increase of wear rate. It was shown that film formation depends, not only on asperity height, but also on the orientation of surface grooves relative to the direction of ring travel. While it would take more data to prove it absolutely, the existing data does suggest that film formation is enhanced by having the surface finish grooves oriented normal to the direction of ring travel. Sadeghi and Sui (1989) present a numerical solution of compressible elastohydrodynamic lubrication that agrees with these results. It was also shown that the ability to form that film under clean-oil conditions increases the resistance to wear under contaminated oil conditions.

B. Slotted Specimen Data

The basic idea behind using slots in cylinder liners was that they might enhance the formation of a hydrodynamic film, while providing avenues of escape for wear particles that would otherwise be dragged the entire stroke of the ring piece. There is some evidence that slots do, in fact, enhance hydrodynamic film formation. In several of these a finite resistance was measured between the ring and cylinder-liner wear specimens. Since that resistance was zero for the unslotted specimen, there must be a thicker film formed with the slotted specimens. That film seems to be enhanced by orienting slots normal to the ring travel direction (as observed with the surface finish grind marks). Perhaps this also explains why a specimen with only two slots had more wear than a specimen with 34 slots in the same space (assuming the 34-slot specimen was able to sustain a hydrodynamic film while the 2-slot specimen was not). Typically film thickness can only be increased by increasing viscosity or the relative speed between the ring and liner, but in this case, the presence of slots change the flow dynamics between the two wearing specimens such that the film thickness is enhanced.

There was little evidence, however that the slots were effective in allowing particles caught in the wear zone to escape. Photomicrographs indicated that wear grooves starting on one side of the slot simply continue on the other. This suggests that the visible grooves are really a conforming of the mating wear specimens. The real wear process occurs on a smaller scale that involves thousands of repeated wear events. Apparently, there are a statistically large number of particles available so that as soon as one particle is released, another is there to take its place. Individual particles would play a role only in the immediate area they are located. If this is the case, then the presence of a circumferential slot would serve to interrupt the wear process only for as long as the ring surface is above the slot itself. Once the ring reaches the opposite side of the slot, the wear process would pick up where it left off.

It also seems evident, however, that the existing Cameron-Plint configuration is not adequate to test the channeling or dilution effect of the slots. In the engine, the wear zone is supplied from one side by relatively clean oil, and on the other by the contaminated oil. Slots might enhance the dilution of the contaminant particles by clean oil and aid in channeling the particles out of the wear zone. A test configuration that supplies clean oil to one side of the rings, and contaminated oil to the other would be a more accurate simulation of the real engine environment.

C. Lube-Oil Additive Investigations

The most promising wear reduction obtained in this program so far was the result of mixing 19 % calcium sulfonate detergent in the lube oil. The additive resulted in a thick hydrodynamic or chemical film (as evidenced by the measurement of resistance between the wear specimens), a reduction in friction force, and most importantly a reduction in wear almost to the clean lubricant level. It is, of course, recognized that actual engine lubricants must contain a mix of many additives (including several of the additives tested here) whose interactions cannot be predicted. Finding a workable lubricant formulation must involve testing with the fully formulated product rather than individual additive components as was done here. Still, the results of this investigation do say some important things about the sensitivity of the wear process to additive formulation. In all the surface finish and slotted specimen tests, there was not one configuration that decreased wear as much as the detergent did, or increased wear as much as the dispersant did.

VI. CONCLUSIONS

The following conclusions can be drawn from the results of this study.

- Varying surface roughness and cross-hatch orientation over a wide range did not significantly change the wear rate under clean-oil conditions.
- There is evidence that using rougher surfaces with grooves oriented normal to the direction of ring travel can enhance the formation of a hydrodynamic film.
- The ability to form a hydrodynamic film under clean-oil conditions increases the wear resistance under contaminated oil conditions as well.
- Orienting cylinder surface slots normal to the direction of ring travel enhances hydrodynamic film formation.
- Wear was highly sensitive to additive formulation.

- A 19 percent mixture of calcium sulfonate detergent reduced the contaminated lubricant wear to almost the clean lubricant wear level.

It seems apparent from the results so far that lube-oil additives had the most significant effect on wear. Surface finish and slots in the cylinder surface affected the hydrodynamic film formation process, but there was not an obvious affect on wear as seen in the mass-loss wear results. It should also be said, however, that the test conditions chosen for the previous tasks were, out of necessity, fairly severe. They were effective in screening a large number of contaminant variations, specimen surface variations, and lubricant mixtures, but they may not have been sensitive to subtle effects such as the effect of cylinder surface condition on hydrodynamic films. Examples of the possible insensitivity of the tests can be seen most clearly in some of the cases where the entire surface finish had been completely removed. In addition, the use of a somewhat high ring loading (approximately an order of magnitude higher than the maximum loading in the engine) may have introduced a larger proportion of adhesive wear, and changed the dynamics by which lube-oil additives affect wear. A separate issue concerns the way lubricant is supplied to the wear zone, especially as it pertains to slotted specimen tests. Since part of the purpose of slots was to allow for highly contaminated oil to be diluted and/or flushed out of the wear zone, it is not fair to test those configurations in a constant concentration lubricant bath. A configuration where fresh oil is supplied on one side and contaminated oil on the other side of the ring would provide a more accurate test.

VII. RECOMMENDATIONS

The purpose of future work in Task 4, will be to further investigate questions raised in Task 3 to allow for more specific recommendations as to the appropriate wear prevention strategies. The task will involve wear tests at lower load conditions (those approaching actual engine loads) in which only minimal damage is done to the surface finish on the wear specimens. Wear evaluations will be made based on profilometric and microscopic observations rather than weight-loss measurements. The intent of these tests will be to identify any differences in wear processes between these and the high load cases so that appropriate adjustments can be made to the interpretation of high-load data. One special area of focus will be cases run with a detergent/baseline oil/contaminant mixture. These will be tested at several different load conditions to determine whether detergent plays the same role in preventing wear at low loads as it did in the high-load cases. Similar tests will also be done with various surface finishes to see if correlations exist which the high-load tests were not sensitive to. Finally, some tests will be performed with slotted specimens in which clean baseline oil is steadily dripped on one side of the ring, while contaminated oil is dripped on the other side. Once again the intent will be to stop testing before significant damage has been done to either wear specimen, and evaluations will be made based on profilometric and microscopic observations.

One other issue that Task 4 will investigate concerns the correlation of particle size with the size of grooves in the wear specimens. Photomicroscopic observations of wear

specimens (Figure 18 for example) indicate wear grooves of the order of 10 microns wide and smaller, but profilometric traces such as Figure 20 indicate that those grooves can be superimposed on larger grooves of the order of 100 microns. The larger grooves are apparent in both the clean oil and the contaminated oil cases, indicating they may have more to do with an adhesive or normal rubbing wear process than the abrasive process. These issues will be explored in more detail in Task 4.

VIII. REFERENCES

Aghan, R.L., and Samuels, L.E., 1970, "Mechanisms of Abrasive Polishing," *Wear*, Vol. 16, pp. 293-301.

Anderson, Daniel P., 1982, "Wear Particle Atlas (Revised)," Prepared for: Advanced Technology Office Support Equipment Engineering Department, Naval Air Engineering Center, Lakehurst, New Jersey, Report NAEC-92-163.

Barber, G.C., Lee, J.C., and Ludema, K.C., 1987, "Materials and Surface Finish Effects in the Breaking-in Process of Engines," *Transactions of the ASME*, Vol. 109, pp. 380-387.

Berbezier, I., Martin, J.M., and Kapsa, Ph., 1986, "The role of carbon in lubricated mild wear," *Tribology International*, Vol. 19, No.3, pp. 115-122.

Cameron, A., and Pumphrey, G., 1983, "Assessment of Bore Polishing Properties of Lubricating Oils by Bench Tests," Esslingen Conference, W. German, Testing and Evaluation of Motor Oils.

Chittenden, R.J., Dowson, D., Dunn, J.A., and Taylor, C.M., 1985, "A Theoretical Analysis of Isothermal EHL Concentrated Contracts - Parts I and II," *Proc. R. Soc. Lond. A387*, pp. 245-269 and pp. 271-294.

Clingenpeel, J.M., Gurney, M.D., and Eccleston, D.B., 1984, "A Combustion and Wear Analysis of a Compression-Ignition Engine Using Coal Slurry Fuels," ASME Paper No. 84-DGP-8.

Czichos, Horst, and Habig, Karl-Heinz, 1986, "Wear of Medium Carbon Steel: A Systematic Study of the Influences of Materials and Operating Parameters," *Wear*, 110, pp. 389-400.

Danyluk, S., and Reaves, R., 1982, "Influence of Fluids on the Abrasion of Silicon by Diamond," *Wear*, Vol. 77, pp. 81-87.

Dowson, D., and Higginson, G.R., 1977, *Elastohydrodynamic Lubrication*, Pergamon Oxford.

Fitzsimmons, B., and Clevenger, H.D., 1975, "Contaminated Lubricants and Tapered Roller Bearing Wear," *ASLE Transactions*, Vol. 20, 2, pp. 97-107.

Flynn, P.L., Leonard, G.L., and Mihan, R.L., 1989, "Component Wear in Coal-Fueled Diesel Engines," *Journal of Engineering for Gas Turbines and Power*, Vol. 111, pp. 521-529.

VIII. REFERENCES (Continued)

- Harris, T.A., 1984, *Rolling Bearing Analysis*, 2nd Ed., John Wiley & Sons.
- Hesling, D.M., 1963, "A Study of Typical Bore Finishes and Their Effects on Engine Performance," 1963 Annual Meeting, ASLE, New York.
- Hsu, B.D., 1988, "Progress on the Investigation of Coal-Water Slurry Fuel Combustion in a medium-Speed Diesel Engine: Part 1 and 2, Ignition Studies and Preliminary Fuel Load Tests," ASME Papers 88-ICE-4, 88-ICE-5.
- Imai, Masaya, Teramoto, Hitoshi, Shimauchi, Yoshinori, and Tonegawa, Etsuo, 1986, "Effect of Oil Supply on Fretting Wear," *Wear*, 110, pp. 217-225.
- Ives, L.K., Peterson, M.B., and Whitenton, E.P., 1988, "NIST-3-Mechanisms of Galling and Abrasive Wear," Semi-annual Progress Report for the U.S. DOE Fossil Energy Advanced Research and Technology Development Fossil Energy Materials Program.
- Janczak, K.J., and Wisniewski, M.R., 1987, "Influence of Surface Roughness Parameters on Elastohydrodynamic Film Thickness," *Wear*, Vol 115, pp. 75-82.
- Johnson, K.L., 1985, *Contact Mechanics*, Cambridge University Press, Cambridge.
- Jones, R.B., McCouet, C.B., Morley C., and King, K., 1985, "Maceral and rank influences on the morphology of coal char," *Fuel*, Vol. 64, pp. 1406-1467.
- Kakwani, R.M., and Kamo, R., 1988, "Combustion Characteristics of Dry Coal Powder Fueled Adiabatic Diesel Engine," 1988 ETCE, New Orleans.
- Kamo, Roy, and Valdmanis, Edgers, 1988, "Tribological Properties of Some Selected materials in a Coal-Fired Environment," *Journal of the Society of Tribologists and Lubrication Engineers*, Vol. 45, No. 7, pp. 417-423.
- Kayaba, T., Hokkirigawa, K., and Kato, K., 1986, "Analysis of the Abrasive Wear mechanism by Successive Observations of Wear Processes in a Scanning Electron Microscope," *Wear*, 110, pp. 419-430.
- Leonard, G., Hsu, B., and Flynn, P., 1989, "Coal-Fueled Diesel Technology Development," Final Report, Work Performed Under Contract No. DE-AC21-85-MC22181 for U.S. DOE Office of Fossil Energy by General Electric Company, Research and Development Center, DOE/MC/22181-2694 (DE89000984).
- Likos, W.E., and Ryan, III, T.W., 1988, "Experiments with Coal Fuels in a High Temperature Diesel Engine," ASME 88-ICE-29.
- Lustgarten, G.A., and Aeberli, K., 1988, "Improved Liner and Ring Wear Properties of Two-Stroke Diesels," *Diesel and Gas Turbine Worldwide*, Vol. 20, No. 3, pp. 45-48.

VIII. REFERENCES (Continued)

Mayville, R.A., 1989, "Abrasive Concentration Effects on Wear Under Reciprocating Conditions," Submitted to the International Conference on Wear of Materials, Denver, CO.

Mehan, Richard L., 1988, "The Wear of Selected Materials in Mineral Oil Containing a Solid Contaminant," *Wear*, 124, pp. 65-85.

Mitchell, Richard S., and Gluskoter, Harold J., 1976, "Mineralogy of ash of some American coals: variations with temperature and source," *Fuel*, Vol. 55, pp. 90-96.

Nydick, S.E., Porchet, F., and Steiger, H.A., 1987, "Continued Development of a Coal/Water Slurry-Fired Slow-Speed Diesel Engine: A Review of Recent Test Results," *Journal of Engineering for Gas Turbines and Power*, Vol. 109, pp. 465-476.

Prater, J.T., and Courtright, E.L., 1985, "Material and Coating Development Alternative Fuel Applications," Prepared for the U.S. DOE Report No. PNL-5259.

Pratt, T.N., 1982, "The EMD Engine and Blended Fuels--A Progress Report," Electro-Motive Division, General Motors Corporation.

Rabinowicz, E., and Mutis, A., 1965, "Effect of Abrasive Particle Size on Wear," *Wear*, Vol. 8, pp. 381-390.

Rao, A.K., Melcher, C.L., Shaub, F.S., Kimberley, J.A., Wilson, R.P., Balles, E.N., 1988, "Operating Results of the Cooper-Bessemer JS-1 Engine on Coal-Water Slurry," 1988 ETC, New Orleans, LA.

Rao, A.K., Wilson, R.P., Balles, E.N., Mayville, R.A., McMillian, M.H., and Kimberley, J.A., 1989, "Cooper Bessemer Coal-Fueled Engine System--Progress Report," *Journal of Engineering for Gas Turbines and Power*, Vol. 111, pp. 498-506.

Richez, Martin, Winquist, Knut, and Storment, John O., 1983, "Theoretical and Experimental Study of Ring-Liner Friction," Final Report SwRI Project 05-9300, Prepared for Advisory Committee for Research, Southwest Research Institute.

Sadeghi, F., and Sui, P.C., "Compressible Elastohydrodynamic Lubrication of Rough Surfaces," *Transactions of the ASME*, Vol. 111, January 1989, pp. 56-62.

Schwalb, J.A., Ryan, III, T.W., and Smith, W.C., 1990, "Lube Oil Contamination Induced Wear in Coal-Fueled Diesel Engine," ASME Paper, ICE-Vol. 12, Coal-Fueled Diesel Engines, Book No. 600507.

Sreenath, A.V., and Raman, N., 1976, "Running-In Wear of a Compression Ignition Engine: Factors Influencing the Conformance Between Cylinder Liner and Piston Rings," *Wear*, Vol. 38, pp. 271-289.

VIII. REFERENCES (Continued)

Sudarshan, T.S., and Bhaduri, S.B., 1983, "Wear in Cylinder Liners, Wear, Vol. 91, pp. 269-279.

Tsai, S.C., 1982, Fundamentals of Coal Beneficiation and Utilization, Elsevier Scientific Publishing Company, New York.

Unsworth, John F., Barratt, David J., Park, David, and Titchener, Keith J., 1988, "Ash formation during pulverized coal combustion; 2. The Significance of crystalline anorthite in boiler deposits," Fuel, Vol. 67, pp. 632-641.

Unsworth, John F., Cunliffe, Frank, Graham, Stephen, C., and Morgan, Paul A., 1987, "Ash formation during pulverized coal combustion 1: Aerodynamic influences," Fuel, Vol. 66, pp. 1672-1679.

Wilson, Michael A., Heng, Sammy, Fredericks, Peter M., Collin, Philip J., and Vassallo, Anthony M., 1986, "The Chemical and Physical Structure of Hydrogenation Residues of Maceral Concentrates," Fuel Processing Technology, 13, Elsevier Science Publishers B.V., pp. 243-260.

Yahagi, Y., 1987, "Corrosive wear of diesel engine cylinder bore," Tribology International, Vol. 20, No. 6, pp. 365-373.

APPENDIX

A. D. Little Memorandum

Memorandum

Date: December 18, 1990

To: Ron Mayville
cc: Bob Wilson/ADL
Eric Balles
Charles Melcher, Cooper-Bessemer Reciprocating
Tom Ryan, SWRI

From: Kate Adams/R. Mayville
Loc: 15/165
Ext: 2757

Subject: Detergent Oil Wear Tests

The following test results were logged on the reciprocating benchtop tester at Arthur D. Little with cast iron specimens and a 1.8 weight percent $5\mu\text{m SiO}_2$ /98.2 weight percent oil¹:

<u>Lubricant</u>	<u>Ring Wear Rate (mg/hr)</u>	<u>Liner Wear Rate (mg/hr)</u>
Oilzum 10W (ADL Standard Lube)	12.4	15.2
AL-162327-L (SWRI Standard)	17.29	19.43
81% AL-16237-L/19% Lubrizol 78 (SWRI high detergent)	12.01	13.83

¹500 RPM, 20 drops/min, constantly stirred slurry, 160 psi load

Southwest Research Institute reported an 87% reduction in wear over unmodified AL-16237-L when the Lubrizol 78 was added (see attached plot). Using the same lubricant and detergent additive, I recorded only a 30% wear rate reduction for specimens worn with the oil/detergent/silica solution compared to those worn with the AL-16237-L/silica slurry. Furthermore, little difference is noted between the wear rates for our baseline 10W oil and the detergent oil, although the detergent oil slurry was significantly more viscous.

These results suggest that the detergent additive does not cause a substantial reduction in wear.

LUBE-OIL ADDITIVE EFFECTS ON WEAR

END

DATE
FILMED
4 129192