12
3-13-92 JSD①

PNL-7658
UC-350

Collection and Analysis of Existing Data for Waste Tank Mechanistic Analysis

Progress Report - December 1990

R. T. Allemann
Z. I. Antoniak
J. R. Friley

C. E. Haines
L. M. Liljegren
S. Somasundaram

December 1991

Prepared for the U.S. Department of Energy
under Contract DE-AC06-76RLO 1830

Pacific Northwest Laboratory
Operated for the U.S. Department of Energy
by Battelle Memorial Institute

PNL-7658

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor Battelle Memorial Institute, nor any of their employees, makes **any warranty, expressed or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights.** Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof, or Battelle Memorial Institute. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

PACIFIC NORTHWEST LABORATORY
operated by
BATTELLE MEMORIAL INSTITUTE
for the
UNITED STATES DEPARTMENT OF ENERGY
under Contract DE-AC06-76RLO 1830

Printed in the United States of America

Available to DOE and DOE contractors from the
Office of Scientific and Technical Information, P.O. Box 62, Oak Ridge, TN 37831;
prices available from (615) 576-8401. FTS 626-8401.

Available to the public from the National Technical Information Service,
U.S. Department of Commerce, 5285 Port Royal Rd., Springfield, VA 22161.

PNL--7658

DE92 009028

COLLECTION AND ANALYSIS OF
EXISTING DATA FOR WASTE
TANK MECHANISTIC ANALYSIS

PROGRESS REPORT - December 1990

R. T. Allemann
Z. I. Antoniak
J. R. Friley
C. E. Haines
L. M. Liljegren
S. Somasundaram

December 1991

Prepared for
the U.S. Department of Energy
under Contract DE-AC06-76RLO 1830

Pacific Northwest Laboratory
Richland, Washington 99352

MASTER

EP

SUMMARY

Pacific Northwest Laboratory (PNL)^(a) is conducting this study for Westinghouse Hanford Company (Westinghouse Hanford), a contractor for the U.S. Department of Energy (DOE). The purpose of the work is to study possible mechanisms and fluid dynamics contributing to the periodic release of gases from the double-shell waste storage tanks at the Hanford Site in Richland, Washington. This interim report emphasizing the modeling work follows another interim report, *Mechanistic Analysis of Double-Shell Tank Gas Release Progress Report -November 1990*, that emphasized data correlation and mechanisms.

The approach in this study has been to

- assemble and compile data that are pertinent to the mechanisms
- analyze the data
- evaluate physical properties and parameters
- evaluate hypothetical mechanisms
- develop mathematical models of the mechanisms.

Analyses of various types have been performed using the data recently obtained from Westinghouse Hanford from their monitoring of tank 101-SY. The major new data are temperature data for short time intervals obtained by an automatic data logger system.

The new data provide evidence that the Reynolds Model R-1 (total sludge buoyancy) would be a likely vehicle for producing dynamic temperature profiles (Allemann et al. 1991). However, there exists an inconsistent, unexplained lack of heat balance for the roll-over.

Much effort has been spent to obtain and correlate the data from the October 24, 1990, gas release in order to provide accurately recorded data times by different means for temperature, level change, pressure, and gas flow. The temperature data could not be resolved to better than ± 1 min, hence

(a) PNL is operated for the U.S. Department of Energy by Battelle Memorial Institute.

there is allowance for more than one mechanistic theory of the gas release. Better data time recording and synchronization methods are needed.

Heat transfer analyses of the temperature profiles have eliminated heat conduction along the probe as being significant. Analyses have also indicated that the lower layer of the sludge may also be producing heat.

Many questions remain unanswered in the heat transfer analysis. The best way to resolve them would be through a combination of thermal modeling and more precise and frequent temperature measurement recordings.

Detailed modeling of the tank slurry behavior may have to include effects of the compounds present; non-Newtonian effects; variation in heat generation rate; and bubble generation, growth, rise, and release mechanisms.

Photograph analysis suggests certain crust behavior patterns. Mechanism analyses of the bent lances within the tank indicate that the bending was not caused by buckling but could have been caused by hydrodynamic forces that developed when gases were passing up through cracks in the crust.

The rate of gas production, as a function of temperature measured in synthetic waste, gives a slurry temperature of 133°F at the gas production rate in tank 101-SY when compared to an average sludge temperature of 129°F. This temperature suggests that the reaction rate should be included in the thermal profile modeling.

A simple dynamic roll-over calculation provides times for the transport of buoyancy-driven sludge to the top waste under the crust. These times are on the order of the times observed for the temperature inversion in the October 24, 1990, vent.

Some investigations of bubble motions were performed to evaluate the possibilities of a bubble separation model in which the bubbles move out of the bottom sludge. These investigations demonstrated that the possibility of bubble separation is low, as the bubbles would not grow and move rapidly enough to match the release time. Sludge rheology data, which are important to this model and to the mechanism of bubble separation after roll-over, are not yet available.

CONTENTS

SUMMARY	iii
1.0 INTRODUCTION	1.1
2.0 DATA ADDITIONS	2.1
2.1 SOURCE OF DATA	2.1
2.2 PRESSURE CHANGES	2.2
2.3 FLOW RATES	2.3
2.4 HYDROGEN CONCENTRATION	2.5
2.5 SURFACE LEVEL CHANGES	2.6
2.6 TEMPERATURE PROFILES	2.8
2.7 TIME ADJUSTMENTS	2.17
2.7.1 Surface Level Changes	2.18
2.7.2 Pressure, Flow Rate, and Thermal Conductivity	2.19
2.7.3 Time Adjustment for the Temperature Profiles	2.22
2.8 TIME RELATION BETWEEN CHANGES IN PRESSURE, FLOW RATE, HYDROGEN CONCENTRATION, AND TEMPERATURE PROFILE	2.24
3.0 HEAT TRANSFER MODELING	3.1
3.1 HEAT TRANSFER OBSERVATIONS	3.1
3.2 EFFECT OF TEMPERATURE ON GAS-VOLUME PRODUCTION	3.3
4.0 HEAT BALANCE OF ROLL-OVER	4.1
5.0 ESTIMATE OF ROLL-OVER DYNAMICS	5.1
6.0 PHOTOGRAPHIC ANALYSIS RESULTS	6.1
7.0 ANALYSIS OF BENT LANCES IN TANK 101-SY	7.1
7.1 FLUID FORCES ON BENT LANCES IN TANK 101-SY	7.1
7.2 BUCKLING OF LANCES FROM CRUST RISE IN TANK 101-SY	7.4

8.0 BUBBLE DYNAMICS 8.1

9.0 REFERENCES 9.1

APPENDIX A: ROLL-OVER DYNAMICS A.1

APPENDIX B: LATERAL FORCE ON A FLOATING BLOCK OF CRUST B.1

FIGURES

2.1	Head-Space Pressure Between 6:00:00 and 6:12:00 on 10/24/90 . .	2.2
2.2	Head-Space Pressure Between 5:30:00 and 7:00:00 on 10/24/90 . .	2.3
2.3	Ventilation Line Flow Rate Between 5:30:00 and 6:12:00 on 10/24/90	2.4
2.4	Ventilation Line Flow Rate Between 5:30:00 and 7:00:00 on 10/24/90	2.4
2.5	Hydrogen Concentration of Air in the Ventilation Line on 10/24/90	2.5
2.6	Change in Surface Level Between 6:00:00 and 6:12:00 on 10/24/90	2.7
2.7	Change in Surface Level Between 5:00:00 and 12:00:00 on 10/24/90	2.7
2.8	Manual Temperature Profiles for Tank 101-SY and Pre- and Post-Burp Profile on 8/5/90	2.9
2.9	Similarity of Temperature Profiles Before the Gas Release . . .	2.10
2.10	Temperature Profile Showing First Sign of Change	2.13
2.11	Temperature Profile During First 40 Seconds of Gas Release . .	2.13
2.12	Temperature Profile During Second 40 Seconds of Gas Release . .	2.15
2.13	Temperature Profile During Later Stages of Gas Release	2.15
2.14	Temperature Profile During Final Period of Gas Release	2.16
2.15	Temperature Profiles at 1-Minute Intervals During Gas Release	2.16
2.16	Rendering of Three-Color Strip Chart Used to Record the Measurements During the Gas Release Event on 10/24/90	2.20
2.17	Surface Level, Pressure, Flow Rate, and Thermal Conductivity from 6:00:00 a.m. to 6:12:00 a.m. on 10/24/90	2.25
2.18	Surface Level, Pressure, Flow Rate, and Thermal Conductivity from 6:00:00 a.m. to 6:30:00 a.m. on 10/24/90	2.26
3.1	Volume Change of Simulated Waste	3.3

4.1	Short-Term Heat Balance of Liquid Roll-Over of Tank 101-SY on 10/24/90	4.2
4.2	Long-Term Heat Balance of Liquid Roll-Over of Tank 101-SY from 10/24/90 to 10/31/90	4.3
5.1	Acceleration of Liquid by Buoyancy of Gas for Tank 101-SY . . .	5.1
5.2	Patterns of Roll-Over in Vertical Cylinders	5.3
6.1	Map of Upper Surface of Waste Crust from Photographs Taken of Tank 101-SY on 4/12/89	6.2
7.1	Diagram of Variables in the Theory of Lateral Force Created by Gas Passing Through Cracks Around a Floating Block of Crust	7.3
7.2	Diagram of Lateral Force Per Foot Width Calculated Using Various Parameters	7.3

TABLES

2.1	Height Correction for Tilted Thermocouple Probe	2.11
7.1	Column Buckling Results for 2-Inch Pipes in Tank 101-SY with a 4-Foot Crust	7.6

1.0 INTRODUCTION

Safe management of Hanford waste depends on an accurate understanding of the chemical and physical mechanisms that take place in the waste tanks. One example of this need has been noted through observations of tank 101-SY and its recent abnormal venting. The waste inside the tank is generating and periodically releasing potentially flammable gases into the tank's vent system according to observations. Questions scientists are trying to answer are:

1) How are these gases generated? 2) How did these gases become trapped?
3) What causes the periodic gas releases? 4) And, what is the mechanism of the gas releases? To develop a safe mitigation strategy, possible physical mechanisms for the periodic release of flammable gases need to be understood.

The Westinghouse Hanford Company (Westinghouse Hanford) commissioned Pacific Northwest Laboratory (PNL)^(a) to develop an understanding of the processes taking place below the crust in the double-shell waste tanks (such as tank 101-SY). PNL is striving to mathematically model and thus explain the physical mechanisms giving rise to the accumulation and periodic release of flammable gases from some of these waste tanks.

During initial work, PNL has obtained, correlated, analyzed, and compared data with expected physical properties; defined mechanisms; and prepared initial models of gas formation and retention. This is the second interim report summarizing the status of the work done to date.

This report contains nine sections. Discussions of the new data and heat transfer analysis are in Sections 2.0 and 3.0, respectively. Sections 4.0 and 5.0 discuss the heat balance of the roll-over model and an estimate of the roll-over dynamics. The results of the photograph analysis are given in Section 6.0. Analyses of the forces required to bend the lances in the tanks are provided in Section 7.0. Section 8.0 provides some of the initial theory on bubble dynamics in the waste. The changes in the temperature, head-space pressure, flow rate, and hydrogen concentration monitored during the gas

(a) PNL is operated for the U.S. Department of Energy by Battelle Memorial Institute.

release will be discussed in this section. All times mentioned are those recorded by the Computer Automated Surveillance System (CASS). Only the level change information was recorded by the CASS; all other information was recorded using instruments having independent clocks. The reconciliation between these instruments and the CASS clocks was performed after the gas-release event. The methods used to determine the time adjustments have an effect on the interpretation of the results; these methods are discussed in Section 2.8.

2.0 DATA ADDITIONS

New data, particularly for the gas release on October 24, 1990, in tank 101-SY, have been received from Westinghouse Hanford and are being analyzed and compiled.

2.1 SOURCE OF DATA

Detailed data describing the changes which occurred during the temperature level drop on October 24, 1990, were obtained from Westinghouse Hanford, primarily through E. I. Husa.^(a) Files containing information describing the head-space pressure in the tank, the flow rate in the ventilation lines, the hydrogen concentration of the gas, and the level of the tank contents were sent in file form through a local area network. The information in the file had been provided to E. I. Husa through sources at Westinghouse Hanford.

Pressure, flow, and hydrogen concentration, as measured using a thermal conductivity probe, were read from the original single strip chart by K. G. Carothers.^(b) Hydrogen concentration, as measured using a gas chromatograph, also was reported by K. G. Carothers.

The surface level information was recorded at approximately 1-min intervals by the CASS using the Food Instrument Corporation (FIC) surface level probe. Measurement times were recorded to the minute (not to the second). Occasionally, two measurements were recorded during the same minute; in some cases there were minutes during which no measurement was recorded.

Most temperature data presented here were obtained by E. I. Husa from data files on a Westinghouse Hanford computer server. These temperatures were obtained using a data logger and provide temperature readings taken at 10-sec intervals during the gas release event of October 24, 1990. Some temperature data on this release event were provided in graphical form in a data set compiled and distributed by D. G. Baide.^(c) Other available files contain

(a) E. I. Husa, Westinghouse Hanford Company, private communication.

(b) K. G. Carothers, Westinghouse Hanford Company, private communication.

(c) D. G. Baide, Westinghouse Hanford Company, private communication.

data describing the August 1990 temperature level drop. These other two data files are currently being examined and compared with data describing what occurred during other events.

2.2 PRESSURE CHANGES

The pressure in the head space of tank 101-SY began to increase from a baseline level of -2.9-in. water gage at approximately 6:04:29 a.m. CASS time on October 24, 1990. The head-space pressure continued to increase for 2 min, 11 sec, reaching a maximum of 2.3-in. water gage at approximately 6:06:40 a.m. The pressure then decreased rapidly, falling to -2.5-in. water gage by 6:12:25 a.m., less than 8 min after the onset of the pressure rise. A detailed graph illustrating the changes in the head-space pressure between 6:00:00 a.m. and 6:12:00 a.m. is displayed in Figure 2.1. The pressure, which

FIGURE 2.1. Head-Space Pressure Between 6:00:00 and 6:12:00 on 10/24/90

returned to the baseline level of -2.9-in. water gage at 6:52:16 a.m., was observed approximately 48 min after the initial increase. The changes in the pressure between 5:30:00 a.m. and 7:00:00 a.m. are illustrated in Figure 2.2.

2.3 FLOW RATES

The initial increase in the gas flow rate in the ventilation line was detected at the same time the increase in the head-space pressure was detected. The flow rate increased from a baseline value of 600 cubic feet per minute (cfm) to more than 1212 cfm in 37 sec. No higher flow rates were detected because the maximum detectable flow rate for the strip chart used to record the flow rate was 1212 cfm. The strip chart recorder needle remained at the maximum value for 42 min and 36 sec. The flow rate then decreased rapidly, and returned to a baseline value of approximately 600 cfm by 6:12 a.m. A detailed graph of the flow rate can be seen in Figure 2.3. The change in the flow rate over a longer period of time is illustrated in Figure 2.4.

FIGURE 2.2. Head-Space Pressure Between 5:30:00 and 7:00:00 on 10/24/90

FIGURE 2.3. Ventilation Line Flow Rate Between 5:30:00 and 6:12:00 on 10/24/90

FIGURE 2.4. Ventilation Line Flow Rate Between 5:30:00 and 7:00:00 on 10/24/90

2.4 HYDROGEN CONCENTRATION

The hydrogen concentration in the head space was monitored with the use of a thermal conductivity probe; the output of this probe was recorded using the same strip chart recorder used to record the flow rate and head-space pressure. The thermal conductivity probe provided accurate time measurement of the hydrogen concentration in the ventilation lines. The hydrogen concentration was also monitored with a gas chromatograph. Gas chromatograph data are available at approximate 4-min intervals between 6:08 a.m. and 6:32 a.m. The concentration measurements using both the thermal conductivity probe and the gas chromatograph are in excellent agreement, as can be seen in Figure 2.5. Later, samples were taken at longer gas release intervals.

A detectable increase in hydrogen concentration was measured at 6:06 a.m. The pressure in the head space at that time was near its maximum value of 2.3-in. water gage. The hydrogen concentration had increased until it exceeded 4.5% at 6:12 a.m., as the head-space pressure and flow rate had returned to baseline values by that time.

FIGURE 2.5. Hydrogen Concentration of Air in the Ventilation Line on 10/24/90

2.5 SURFACE LEVEL CHANGES

The changes in the surface level which occurred between 6:00:00 a.m. and 6:12:00 a.m. on October 24, 1990, are illustrated in Figure 2.6. Surface level changes between 5:00:00 a.m. and 12:00:00 a.m. are illustrated in Figure 2.7 using an extended time scale. The surface level remained virtually unchanged between 5:00:00 a.m. and 6:01:00 a.m., maintaining a baseline level between 412.1 in. and 412.4 in. The majority of readings recorded during this period were 412.2 in., which will be considered the baseline level here. The recorded surface level at 6:02:00 a.m. was 412.5 in. This reading might represent a slight increase above the baseline level of 412.2 in. The measured level returned to 412.2 in. at 6:03:00 a.m. The surface increased from 412.2 in. to 413.2 in. between 6:06:00 a.m. and 6:07:00 a.m., and then decreased rapidly. The level reading had fallen to 407.8 in. by 6:12:00 a.m., which is 4.4 in. lower than the baseline level of 412.2 in. The surface level ultimately decreased a total of 9.3 in. All measurements after 14:18:00 a.m. were within the range of 403 in. and 402.8 in.

The variability in the surface level measurements reported prior to the gas release was slightly larger than the variability in the measurements reported after the gas release. The standard deviation of the surface level measurement for the 67 measurements taken between 5:00 a.m. and 6:06 a.m. was 0.088 in. The standard deviation for the 219 measurements taken between 14:18 a.m. and 17:59 a.m. was 0.036 in. The difference in the two standard deviations is significant to at least the 95% confidence level.

The standard deviation in the measurements taken after the level drop represents the limit of resolution of the instrument used to measure the surface level. The standard deviation for the measurements made after the gas release consist almost entirely of fluctuations in the reading between 403 in. and 402.9 in. This type of measurement is consistent with a surface level that remained constant, as the difference in the readings could represent round-off error. During the measurements just prior to the gas release, the surface level was reported to vary between 412.1 in. and 412.5 in.

FIGURE 2.6. Change in Surface Level Between 6:00:00 and 6:12:00 on 10/24/90

FIGURE 2.7. Change in Surface Level Between 5:00:00 and 12:00:00 on 10/24/90

Because the standard deviation during this period is significantly larger than that measured after the drop, trembling of the surface level during the period before the gas release has been suggested as one possible explanation.

The surface level fluctuates somewhat prior to a gas release. This observation is important for two reasons. The first is that it may be possible to anticipate the occurrence of level drops by calculating the standard deviation of the surface level over approximately 1-h periods. Level drops may be more likely when the standard deviation in the surface level increases beyond some value. This idea requires further investigation to determine if there was a sudden increase in the variability of the measured surface level prior to other level drops. Further analysis would also determine whether or not the level drops occurred soon after the increase in the variability of the surface level readings.

The second reason this observation is important is because the slight fluctuations in surface level measurements may indicate that some action was taking place below the crust during the hour prior to the major event. Motion occurring below the crust does not appear to have affected any observable temperature or pressure measurements. This suggests a physical mechanism involving the rapid growth of small, nearly imperceivable disturbances which culminate in the rapid overturn of the tank contents.

2.6 TEMPERATURE PROFILES

Temperatures along the thermocouple probe in the tank were sampled at 10-sec intervals using a data logger during the gas release of October 24, 1990. Measurements were also taken manually at longer intervals. Temperature data taken manually and distributed by D. G. Baide^(a) regarding the October 24, 1990 event, indicate temperatures were approximately 3°F cooler than the temperatures recorded by the data logger. The profile read at 3 a.m. (prior to the gas-release; measurements taken manually) indicates a maximum temperature of 137°F and is illustrated in Figure 2.8. A profile measurement taken with the data logger indicates a maximum temperature of 140°F prior to

(a) D. G. Baide, Westinghouse Hanford Company, private communication.

FIGURE 2.8. Manual Temperature Profiles for Tank 101-SY and Pre- and Post-Burp Profile on 8/5/90

the gas release (see Figure 2.9). The difference in the temperatures recorded using the two methods appears to occur consistently. K. L. Englehardt^(a) of Westinghouse Hanford confirms that there is a discrepancy in temperature and states that the exact reason for the discrepancy is not known. Because of the existence of this discrepancy, care must be taken to use data from a single source, either the data logger or the manual system, when comparing data to results of thermal analyses.

During the gas release period, the data logger recorded temperatures and scan numbers but not times. The data logger clock was read later when the data file was retrieved; this reading was subsequently used to identify a time with each scan number. However, only the hour and minute were read; consequently, the time associated with each scan number was identified only to the correct minute. Other difficulties associated with the time at which the data were recorded are discussed in Section 2.8. Relevant profiles in this section

FIGURE 2.9. Similarity of Temperature Profiles Before the Gas Release

(a) K. L. Englehardt, Westinghouse Hanford Company, private communication.

have been identified with the appropriate scan number. The time at which each scan occurred falls within approximately 30 sec of the time noted on each figure.

As mentioned in the earlier progress report (Allemann et al. 1991), the thermocouple probe is bent, the probable thermocouple locations are provided in Table 2.1. These thermocouple locations were used to plot the temperature as a function of height above the bottom of the tank.

The temperature profile obtained before the gas release is displayed in Figure 2.9. The location of the upper crust surface before the gas release was 412 in. and is indicated in Figures 2.7 and 2.8. The temperature readings from the lower 16 thermocouples on the probe correspond to temperatures below the crust. The uppermost two thermocouples are located above the crust and register temperatures below 100°F. The third thermocouple from the top

TABLE 2.1 Height Correction for Tilted Thermocouple Probe

<u>Thermocouple Number</u>	<u>As-Built Height (ft)</u>	<u>Height (ft)</u>	<u>ΔHeight (ft)</u>	<u>ΔHeight (in.)</u>
1	0.5	0.93	0.43	5.2
2	2.5	2.91	0.41	5.0
3	4.5	4.89	0.39	4.7
4	6.5	6.87	0.37	4.5
5	8.5	8.86	0.36	4.3
6	10.5	10.84	0.34	4.0
7	12.5	12.82	0.32	3.8
8	14.5	14.8	0.30	3.6
9	16.5	16.78	0.28	3.3
10	18.5	18.76	0.26	3.1
11	20.5	20.74	0.24	2.9
12	22.5	22.72	0.22	2.6
13	24.5	24.7	0.20	2.4
14	26.5	26.68	0.18	2.2
15	28.5	28.66	0.16	1.9
16	30.5	30.64	0.14	1.7
17	34.5	34.6	0.10	1.2
18	38.5	38.56	0.06	0.8

(No. 16) is located at 367 in., which is below the upper crust surface. The location of the lower crust surface is not known. However, thermocouple No. 16 is in a constant temperature region. This constant temperature is thought to occur as a result of natural convection in a layer of supernatant liquid, which lies above a settled solids layer. Consequently, the temperature profile suggests that the lower crust surface lies above thermocouple No. 16; this indicates that the crust is less than 45 in. thick. The temperature profile in the lower 17 ft of the tank waste appears to be parabolic, except for the bottom thermocouple. It has been suggested, on the basis of the temperature profile, that an interface between a layer of settled solids and a layer of supernatant liquid exists at about the 17-ft level. The temperature was constant below the 3-ft level, but the bottom thermocouple changed temperature rapidly along with the second thermocouple. This may be due to a thermocouple error or offset in the bottom couple. This profile is typical of profiles reported prior to previous gas-release events.

Detectable changes in the temperature profile were recorded on scan No. 13509. This temperature profile was compared to the profiles recorded in scan Nos. 13507 and 13508 in Figure 2.10. Only 16 of the lower thermocouples are displayed in the figures that indicate changes in the temperature profile during the level drop; thus allowing features to be seen in greater detail. The temperature of the uppermost thermocouple (in the air space) increased approximately 2°F over a 10-min period. The temperature at the top of the tank increased approximately 2°F in the 10 sec following scan No. 13508. The temperature at the bottom of the tank decreased approximately 1°F; it appears that the temperatures in the midlevels of the tank did not change during this time.

The changes in the temperature profile detected between scan Nos. 13509 and 13512, which took place over the course of 40 sec, are illustrated in Figure 2.11. The temperature just below the crust continued to rise, while the temperature in the lower region fell. Generally, the upper region in which the temperature increased, indicated an increasingly larger maxima and increased in size with time. Meanwhile, the temperature profile in the lower parabolic region first flattened as temperatures approached a constant value

FIGURE 2.10. Temperature Profile Showing First Sign of Change (Lower 16 thermocouples shown)

FIGURE 2.11. Temperature Profile During First 40 Seconds of the Gas Release

in height, then temperatures fell and maintained a relatively flat profile. A steep temperature gradient was observed between 13 ft and 17 ft.

One minor deviation from this general description was the appearance of a relative maximum or spike in the temperature profile at the 20-ft level. This relative maximum persisted for 40 sec as seen in Figure 2.12. A prominent spike can be seen near the 20-ft level (thermocouple No. 11) at the time when scan number No. 13515 was recorded.

The location of the relative maximum rose from its original level of approximately 20 ft to a level of approximately 25 ft. The new location of the spike can be seen in Figure 2.13, where the changes that occurred between scan No. 13515 and scan No. 13521 are illustrated. The rate at which the profile was changing slowed drastically by the time the second scan was taken. The profiles provided in this figure were recorded at 20-sec intervals. Profiles recorded at 10-sec intervals are also available.

The appearance of temperature spikes may imply that hot material rising in the tank was momentarily delayed, first near the 20-ft level and then near the 25-ft level. Less prominent temperature spikes appear near thermocouple Nos. 4 and 7 between scan No. 13512 and 13515, which tends to reinforce the idea that masses of hot material rose and were hindered momentarily at different levels in the tank. However, mechanisms consistent with this type of behavior have not been explored. It is possible that there are other explanations (such as circulation patterns) for the spikes in the temperature profiles.

Minor changes which occurred between scan No. 13523 and 13535 are indicated in Figure 2.14. The temperatures in the lower portion of the tank fell approximately 1°F during this 40-sec period. Meanwhile, the temperature in the spike near the 25-ft level continued to increase, and the temperature near thermocouple No. 15 at the 29-ft level decreased significantly between scan No. 13527 and 13531.

The changes in the temperature profile that occurred between scan No. 13500 and 13505 are displayed in Figure 2.15. This figure displays profiles at 1-min intervals for a total of approximately 8 min.

FIGURE 2.12. Temperature Profile During Second 40 Seconds of Gas Release (Lower 16 thermocouples shown)

FIGURE 2.13. Temperature Profile During Later Stages of Gas Release (Lower 16 thermocouples shown)

FIGURE 2.14. Temperature Profile During Final Period of Gas Release (Lower 16 thermocouples shown)

FIGURE 2.15. Temperature Profiles at 1-Minute Intervals During Gas Release

2.7 TIME ADJUSTMENTS

Official reporting times for the data-described events that occurred in tank 101-SY were recorded by the CASS. Frequently, instruments used to record events had their own clocks, which had not been synchronized with the CASS clock. Time adjustments were determined by Westinghouse Hanford personnel after the event occurred. The times stated in this report have been adjusted to reflect information provided verbally by Westinghouse Hanford personnel.

The sequence in which events took place is important for the accurate development of an overturn model. Because the recording instruments were not synchronized, there exists some uncertainty as to the actual sequence of events. This uncertainty could lead to a potentially incorrect hypothesis regarding the gas release. The magnitude of the adjustments for each instrument and the method by which the adjustments were made will be discussed here. The time adjustment for temperature data recommended by two sources at Westinghouse Hanford differed by 1 min and 5 sec on one occasion. A difference of this magnitude led to significantly different interpretations of the sequence of events occurring during the level drop. The use of one value made it appear that the maximum pressure occurred before any changes in the temperature profile were detected. The other value of time adjustment indicates that the temperature profile inverted before the maximum pressure was achieved. Entirely different mechanisms would be required to explain the two types of events.

Comparison of the results of analytical and physical models to the data describing actual level drops requires accurate knowledge of the sequence of events as they occurred in the tank. Consequently, the time at which measurements were taken is considered crucial to the understanding of events that occurred in tank 101-SY. Confusion over the times at which the data were collected should now be eliminated. Two steps were taken to minimize or eliminate confusion regarding data collection times from the gas release of October 24, 1990, and more important, to prevent the reoccurrence of this confusion.

1. The time adjustments and the methods used to determine them should be reported in written form by Westinghouse Hanford. Confirmation of time

adjustments and descriptions of methods used by Westinghouse Hanford to determine time adjustments should be required to ensure accuracy. This would reduce the potential of errors made as a result of miscommunication.

2. Some method of synchronizing times on various clocks should be implemented to allow relative time between clocks to be known with a greater degree of certainty. Methods used to determine time adjustments may be subject to human error in some cases, particularly since final determination of the time at which each temperature profile was measured requires three separate operations. Data measurement times should be recorded along with the data to the maximum possible resolution. It seems likely that all times can be recorded to a resolution of 1 sec; thus, none of the recorded times should be truncated to a resolution of only 1 min.

2.7.1 Surface Level Changes

The surface level information is monitored and recorded on the CASS, which is considered by Westinghouse Hanford to provide the official time for all events during the level drop and gas release. Consequently, the level information does not require a time adjustment. However, the resolution of the level information in time is not known. Truncation error for the time stamp is probably the major factor affecting the precision with which the time is reported. Initially, the description of the procedure used to measure the surface level appeared to indicate that the level was sampled at exactly 1-min intervals. However, the data record indicated that occasionally two measurements were taken during the same minute, and occasionally no measurements were taken during a particular minute. This type of record is not consistent with the sampling that occurred precisely at 1-min intervals. It is likely that the time stamp associated with each level location is truncated and represents a 60-sec window.

It is also possible that the surface level changed significantly during the period between measurements. Consequently, the time at which the surface level reached a maximum and the height of the maximum are not necessarily the actual combined time and level of the maximum. The time at which the maximum level occurred is only known within 60 sec at best.

It is recommended that the time stamp (associated with the appropriate level of information) retain a record of postmeasurement seconds. This would

allow for a more accurate comparison of the time at which the level drop occurred and the time at which the pressure changes occurred.

It is also recommended that data be taken at shorter intervals if possible. This recommendation is based on the appearance of the prelude rise which had a duration of less than 1 min. It would be useful to verify whether this rise is common or an unusual event. Because the rise may last for a very short period, it may not always be possible to detect rises that occur when sampling is carried out at intervals of 1 min. If measurement of the surface level at shorter intervals is not possible using the installed measurement devices, the use of other devices should be investigated.

2.7.2 Pressure, Flow Rate, and Thermal Conductivity

The pressure in the head space, the flow rate in the ventilation lines, and the thermal conductivity of the gas (which is used to monitor the hydrogen concentration) are all recorded using one strip chart recorder.

A reproduction of the strip chart recorded during the gas release event which occurred October 24, 1990, is provided in Figure 2.16. Different ink colors were used to record each of the three measurements on the original strip chart; this allowed the different signals to be interpreted.

Two time stamps indicating date, hour, and minute were used to record each of the three measurements on the original strip chart, which allowed the different signals to be interpreted on the strip chart. The time stamps indicate that the information was recorded on October 16, 1990, at 5:14 a.m. and 5:29 a.m. (The actual date was October 24, 1990, and the first pressure upturn occurred at 06:04:19 [see Figure 2.16].) A Westinghouse Hanford engineer states that the time stamps are associated with the dotted line immediately below the printed information and that both the dotted lines and the time stamps are applied by the recording device.

The strip chart was programmed to use a slow paper speed initially, and to change speeds when the pressure in the head space exceeded -2.5-in. water gage. A signal was simultaneously sent to the CASS, and the time was recorded by the CASS. The speed reverted to the initial slow speed after the head-space pressure fell below the -2.5-in. pressure threshold again. The paper

FIGURE 2.16. Rendering of Three-Color Strip Chart used to Record the Measurements During the Gas Release Event on 10/24/90

locations which correspond to the high-speed feed rate are indicated by a bold wiggly line on the left border of the chart.

The time when the pressure exceeded -2.5-in. water gage was recorded by the CASS. This information was used to determine the time adjustment between the level information recorded on the CASS and the flow, pressure, and thermal conductivity recorded on the strip chart. The currently recommended method for adjusting the times on the strip chart to CASS time is to add 8 days, 53 min, and 16 sec to the time recorded on the strip chart. Previously, an adjustment time of 8 days, 53 min, and 28 sec was recommended for the pressure and thermal conductivity data, and an adjustment of 8 days, 53 min, and 16 sec was recommended for the flow. The two recommended adjustment times are within the limits of resolution with which time can be read, and are not significant.

However, the same adjustment time should be used for all three plots to avoid misinterpretation of the relation between the changes in the pressure and the flow rate.

The pressure, flow, and thermal conductivity of the gas recorded on the strip chart reported by Westinghouse Hanford were read manually. The limit of resolution of the readings was not reported. However, because the three strip chart recorder pens must be free to pass by each other, it is unlikely that the spatial resolution for the readings is better than a three-pen width. Assuming that the pen diameters are approximately three times the diameter of the ink line, this would equal about 3 mm. As a result, the best resolution to be expected in the high-speed region would be about 1.6 sec and 16 sec in the low-speed region.

Because the point on the paper corresponding to the time at which the signal was sent to the CASS borders the slow- and fast-speed regions, the poorer resolution of 16 sec is the more realistic value for determining the accuracy of the time adjustment required to translate strip chart times to CASS times. Consequently, the time adjustment for the pressure, flow rate, and thermal conductivity data should be interpreted as being identified with a precision of approximately 16 sec.

A second factor, which may further degrade the accuracy with which the time adjustment is determined, is the time required for the strip chart recorder to change speeds. It is unlikely that the strip chart recorder accuracy is degraded by more than a second, as the recorder changes speed relatively quickly.

The method for determining the time adjustment for the flow rate and pressure data is adequate, in the sense that the procedure used should produce an unbiased time adjustment. However, the fact that a time adjustment is needed introduces the possibility that misunderstanding of the magnitude of the time adjustment could arise and cause serious misinterpretation of the data. In addition, time is wasted whenever differing time adjustments are reported.

It is recommended that a method be found which will allow all data to be recorded using a single, redundant data logger. Data describing the head-space pressure, flow rate, waste temperature, and level drop could be recorded on one data logger rather than on separate instruments. If safety considerations require continued use of the current monitoring systems, then each reading could be monitored simultaneously by two systems. The surface level reading, for example, could be recorded by the CASS and the data logger. The head-space pressure could also be monitored on the strip chart and the data logger. This additional monitoring would allow the relative times at which all events took place to be determined without recourse to time adjustments.

2.7.3 Time Adjustment for the Temperature Profiles

The temperature data are acquired by a data logger and transferred to a microcomputer. Three adjustments were required to determine the correct time associated with each scan number recorded by the data logger and the correct CASS time. The first adjustment was the determination of the time adjustment between the microcomputer and the CASS. The second adjustment was the determination of the time adjustment between the data logger and the microcomputer. The third adjustment was the determination of the time at which each scan was taken. The following information was obtained through conversations with K. G. Carothers and R. J. McCarthy.^(a)

The method for determining the time adjustment between the microcomputer time and the time recorded by the CASS clock follows:

1. A watch was set to read the hour, minute, and second displayed by the microcomputer which stores the temperature data.
2. The watch was carried to the CASS which was set to print out the time. The time on the watch and the time printed out by the CASS were read simultaneously.

These steps indicated that the CASS clock read 49 sec faster than the microcomputer time. The accuracy of this method might be affected if the printout of the time lags behind the actual CASS time slightly, or if

(a) K. G. Carothers, Westinghouse Hanford Company, private communication.
R. J. McCarthy, Westinghouse Hanford Company, private communication.

operators have some difficulty reading both the watch and the CASS printout simultaneously. It seems likely that the accuracy for this time adjustment should be within 1 to 2 sec.

The method for determining the time adjustment between the microcomputer and the data logger was uncomplicated. The time on the watch was synchronized with the microcomputer time. Then, the time displayed by the data logger and that displayed by the microcomputer were read simultaneously.

R. J. McCarthy^(a) states that when the data logger read 13:34:00 a.m., the microcomputer read 1:31:16 a.m. Thus, the data logger time was 2 min and 44 sec faster than the microcomputer time. It is unlikely that the time displayed on the microcomputer screen significantly differentiated from the internal clock time, but it was probably difficult for the operator to read two times simultaneously. Because the time reads out to seconds only, it is probably reasonable to assume that the resolution is within 1 to 2 sec. The time recorded by the CASS was determined to lag behind the data logger time by 1 min and 55 sec.

The lack of resolution in the relation between the scan number and the time is the most serious factor affecting the accuracy with which the time for the temperature profiles are known. Because the data logger used to measure time can be programmed to allow the time to be recorded with each reading, there does not appear to be any reason for the scan numbers and time to not have been recorded. However, the times were not recorded during the October 24, 1990, gas-release event. Consequently, it was necessary to determine the relation between the scan number and the data logger time.

The relation was determined by reading the time appearing on the data logger screen as the final scan number on the tape was being recorded. However, the time on the screen was read to the hour and minute only; the seconds were truncated. Thus, the time for the last scan falls in a 60-sec window. If it is assumed that the actual time the last scan number was recorded occurred in the middle of a minute (i.e., xx hours, yy min, and

(a) R. J. McCarthy, Westinghouse Hanford Company, private communication.

30 sec), then the resolution of the time was 30 sec, as the actual time may have been as much as 30 sec earlier or later.

Currently, information provided by Westinghouse Hanford states that the data logger time associated with scan No. 13505 is 6:05:00 a.m. This time was determined by assuming that the time read off the data logger coincided to the second with the internal microcomputer clock. That is, it was assumed that when the data logger time was read to be xx hours and yy min, the internal clock read xx hours, yy min, and 0 sec. Thus, the time at which scan No. 13505 was taken may fall between 6:05:00 a.m. and a fraction of a second before 6:06:00 a.m. This report will assume the time to be 6:05:30 a.m. ± 30 sec when applying the time adjustment results in a CASS time at 6:03:35 a.m. The lack of resolution of the final value dominates the level of accuracy with which the final time adjustment is known. Assuming that the potential degree of inaccuracy is the square root of the sum of the squares of all of the component inaccuracies, the time is known within 30.1 sec.

2.8 TIME RELATION BETWEEN CHANGES IN PRESSURE, FLOW RATE, HYDROGEN CONCENTRATION, AND TEMPERATURE PROFILE

The mechanism by which the level drop occurs affects the rate at which gas is released. This in turn affects the magnitude of the pressure changes, the hydrogen concentration, and the temperature profiles in the tank. It is desirable to determine the relation between all these changes in order to allow various proposed mechanisms to be evaluated.

The relation between the flow rate, the pressure changes, and the surface level changes between 6:00 a.m. and 6:12 a.m., and 6:00 a.m. and 6:30 a.m. are indicated in Figures 2.17 and 2.18. The first indication of a gas release occurred just after 6:04:19 a.m. CASS time, when both the flow rate in the ventilation lines and the pressure in the tank began to increase. The hydrogen concentration at that time was negligible, and the surface level indication of the crust had not changed. The crust level remained unchanged for the next two measurements. This strongly suggests that some gas is released prior to any marked changes in crust level.

FIGURE 2.17. Surface Level, Pressure, Flow Rate, and Thermal Conductivity from 6:00:00 a.m. to 6:12:00 a.m. on 10/24/90

Both the fluid flow rate in the ventilation lines and the pressure in the tank increased rapidly. It should be noted that pressure readings less than 1-in. water gage and those greater than 1-in. water gage were read by separate instruments. The strip chart displayed in Figure 2.16 was used for readings of less than 1-in. water gage. Those above 1-in. water gage were read from a chart capable of a maximum reading of 80-in. water gage. Consequently, the resolution for both the time and the pressure reading obtained for the peak values may differ markedly from those determined for the lower pressures.

FIGURE 2.18. Surface Level, Pressure, Flow Rate, and Thermal Conductivity from 6:00:00 a.m. to 6:30:00 a.m. on 10/24/90

The flow rate in the ventilation line reached the maximum value recordable on the strip chart within 10 sec of the initial rise; the maximum readout was 1212 cfm. When the flow rate first exceeded the maximum readable value, the pressure reading had not yet exceeded -2.0-in. water gage, which is less than 1-in. water gage above the baseline reading. The pressure reached its maximum value of approximately 2.3-in. water gage near 6:06:40 a.m. It is not known what the maximum flow rate was during the gas release. However, because approximately 80% of the pressure rise occurred after the flow exceeded the maximum value, the flow rate probably exceeded 1212 cfm.

Interpretation of the changes in the crust level requires caution, as the crust level was sampled at 1-min intervals and at only one location in the tank. Consequently, it is possible that the change in the crust level may represent either motion of the crust as a whole or just motion in the vicinity of the probe. A 1-in. increase in the crust surface level was recorded at approximately the same time the maximum pressure was recorded. It is possible that the maximum level occurred as long as 59 sec prior to or after the time when the maximum level was recorded, because the level is sampled at 1-min intervals, and the rate of change of the surface level between samples is not known. In addition, it appears that the time at which the surface level measurements occurred were truncated to the minute. Extremely high rates of change in the surface level would be required to allow the maximum pressure to occur at either extreme of this interval. However, the maximum possible rate of change is not known, because the maximum possible force exerted by the fluid on the crust is not known. Additionally, if the crust moves as a whole, greater forces are required to achieve accelerations of the crust. However, if the crust fragments and portions of the crust rise, considerable acceleration could be achieved locally. Additionally, if the resolution for the pressure and flow data is (thought to be) 16 sec, then the maximum crust level, at least in the vicinity of the measurement probe, may have occurred as long as 76 sec before or after, or been simultaneous with the maximum pressure. A possible interpretation of the increase in the crust level is that gases trapped in lower layers of waste begin to rise and expand with decreasing hydrostatic pressure; thus the expansion would raise the crust level.

At the time the maximum pressure and flow rate were achieved and the rise in the crust level was detected, the hydrogen level in the tank had risen to a concentration of approximately 0.5%. This percentage was only a small fraction of the ultimate concentration of 4.5%, which was achieved much later, near 6:12 a.m.

The low level of hydrogen detected in the ventilation line early in the event does not imply that no hydrogen was being released into the tank head space. It is likely that the air entering the ventilation ducts came from the region near the duct inlet. Some time is required for the hydrogen to mix

with the gas in the tank and arrive at a sampler in the ventilation lines.^(a) Consequently, the hydrogen concentration would be expected to lag the actual introduction of the slurry gases by a period of time which is related to the mixing time for gases in the tank head space.

The first sign of change in the temperature profile was seen in scan No. 13509. This change occurred at approximately 6:04:15 a.m. $\pm$ 30 sec CASS time, which is very near the time (6:04:19 a.m. $\pm$ 16 sec) when the pressure and flow rate first began to increase. However, it is possible that the temperature changes occurred as early as 6:03:45 a.m. or as late as 6:04:45 a.m. CASS time. The change in the first case would indicate that the temperature profile began to change before any flow or pressure changes were detected. The change in the second case would indicate that the temperature profile changed after the flow rate and pressure changes were detected.

Because of the lack of resolution of the time at which the temperature data were taken, it is difficult to identify specific temperature profile times. It is not possible to determine whether detectable changes in the temperature profile below the crust occurred prior to or after changes that took place in the head-space pressure or the flow rate in the ventilation line. Many of the physical models investigated for the gas-release events suggest that the self-induced motion of the waste below the crust lead to release of gas. Generally, these models are consistent with temperature changes that occurred below the crust prior to the changes in the pressure and flow rate above the crust. However, a model has been proposed in which crust rupture could induce a pressure pulse that would trigger the motion of waste below the crust. The current data may be interpreted in either manner and consequently cannot be used to state which hypothesis is more likely.

The temperature profile continued to evolve over the course of several minutes. It is not certain which scan was recorded at the time when the maximum pressure was detected (6:06:40 a.m. $\pm$ 26 sec) or the time when the maximum surface level was measured. The temperature profile changed dramatically from its preevent shape by the time scan No. 13520 was recorded; thus, it is clear

(a) FATHOMS analyses indicate ~2-min delay.

that a sizeable temperature change occurred before the maximum pressure in the head space was achieved. During scan No. 13520, the maximum temperature was near thermocouple No. 15, just below the crust. A small temperature spike appeared near thermocouple No. 13. If this spike represents hot waste containing gas, then it is possible that the rise in the crust level is associated with the expansion of gas which has risen from the bottom of the tank to near thermocouple No. 15.

The temperature profile taken at scan No. 13527 was similar to that recorded at scan No. 13520. The major difference between the two profiles was that the temperature in the spike near thermocouple No. 15 had increased. This difference might imply that more hot material was accumulating in this region. Additionally, if scan No. 13527 occurred at the time of maximum pressure, it would indicate that the temperature profiles began to change approximately 1 min before the pressure and crust level began to change.

A decrease in the temperature measured with thermocouple No. 15 was detected between scan No. 13523 and 13531. The majority of this change occurred between scan No. 13527 and 13531. It may be that either hot waste or hot gas was trapped under the crust prior to the time at which scan No. 13523 was taken. A sudden rupture of the crust near scan No. 13527 could release the hot gases, which would explain the sudden decrease in temperature. A sudden rupture might also explain the sudden increase in the observed flow as well as the increase in the pressure.

However, it is also possible that gases which were trapped in hot waste were released at the time of scan No. 13527 causing the waste to become more dense and sink. This type of behavior would not necessarily be associated with a sudden gas release. If the relation between the time at which the two events occurred was known more precisely, then it might be possible to determine the relation between the changes in the temperature profiles and the surface level.

While it is clear there is an association between the level drop, pressure changes, and hydrogen concentration of the gases, it is not currently possible to precisely determine when the slurry temperature changes occurred relative to the other changes detected in the tank on October 24, 1990. This

problem stems from the low resolution of the time adjustment required to determine the time at which the temperature scans were taken. It is not possible to state that any temperature changes occurred prior to or after the increase in head-space pressure associated with the gas-release event. Better accuracy in the determination of the time stamps for the temperature data is required if the correct sequence of events is to be reconstructed.

Whatever the mechanism causing the level drop was, temperature changes occurred very rapidly; the temperature profile appears to invert completely over a 6-min period or less with the bulk of the change occurring during a 2-min period between scan No. 13506 and 13518 (Figure 2.18). The rapidity of the changes in the temperature profile were not observed during previous release events because, in most cases, sampling was done either daily or at intervals exceeding 1 h.

3.0 HEAT TRANSFER MODELING

Given the paucity of data and the apparent complex behavior observed from the slurry in tank 101-SY, many models having a range of credibility can be proposed. Some of the models, mechanisms, and theories regarding the heat transfer in tank 101-SY will be listed and briefly discussed below. Many questions still remain unanswered. The best way to resolve the complex slurry tank issues would be through a combination of thermal modeling and more precise and frequent temperature measurements.

3.1 HEAT TRANSFER OBSERVATIONS

Pre- and post-burp heat balance is not preserved, thus leaving about 80% of the heat remaining after the burp (see Section 4.0). Information has been based on the single thermocouple probe.

Hypothesis: Heat losses during overturn make up the difference in temperature.

Calculation of the heat lost to the free-volume space indicates significant variation in heat loss over time as operators balance flows among tanks. This heat loss amounts to an average of about 7% of the heat generated, and an insignificant fraction of the thermal capacitance of the overturn (20% loss). Heat lost through the tank sides cannot be estimated well at the present time, as side thermocouple data are not being recorded. However, it would be a small amount in the time frame of an overturn. A similar calculation of the heat lost with the emitted gases indicated that <1% of the thermal capacitance would be lost in this manner.

Hypothesis: Horizontal variation in properties and/or temperatures, which is not measured by the single thermocouple lance, accounts for the heat balance anomaly.

This explanation is likely, given the manner in which the temperature profiles decay after the overturn. Thus, horizontal temperature inhomogeneities were present, and they are manifested in the vertical temperature profiles.

Temperature profiles differ among burps.

Hypothesis: Better and more frequent measurements gave data that account for the most recent slurry tank behavior on October 24, 1990.

This hypothesis is probably correct, but there are presumably unique features to each burp. The anomalous behavior and slopes of the temperature profiles during earlier burps may be real or may be the result of instrument error. It should be noted that the axial temperature differences being observed are small, and much is being inferred.

Hypothesis: Each slurry tank burp is different, hence the different temperature profiles and gas generation rates are to be expected.

This theory is likely to be true to an extent. Better and more frequent measurements will uncover the extent of the variability. The correct theory will be based on the measurement similarities, yet may also explain the differences.

Hypothesis: The bottom-most layer does not generate heat.

Some temperature profiles, as noted above, seem to bear this theory out by displaying a linear profile near the bottom three thermocouples. Computer codes using this assumption also display bottom linearity. However, the most recent temperature profile prior to the burp was almost fully parabolic throughout (Figure 2.8) the entire nonconvecting layer, suggesting that heat was generated throughout the entire lower-slurry layer. The bottom thermocouple temperature varies when a burp occurs so the bottom "isothermal" region may be due to a malfunctioning thermocouple at the bottom.

Hypothesis: The pipe supporting the thermocouples (thermocouple probe), conducts a significant amount of heat, thus locally cooling the slurry and depressing the temperatures from the actual fluid value.

Calculations indicate that heat conducted along the thermocouple pipe is insignificant (about 2 Btu/h) when compared to the heat generation rate and would provide an insignificant thermocouple error.^(a) Other calculations

(a) Z. I. Antoniuk, hand calculation on November 1, 1990, based on October 24, 1990, data.

indicate that radioactive heating of the thermocouple would not provide significant errors ($<0.01^{\circ}\text{F}$) in thermocouple readings.^(a)

3.2 EFFECT OF TEMPERATURE ON GAS-VOLUME PRODUCTION

Data from a Westinghouse Hanford employee,^(b) as displayed in Figure 3.1, indicate that the reaction rate of gas production can be expressed as an Arrhenius-type equation

$$\dot{V} = 1.113 \times 10^{18} \exp(-24,308/T)$$

where $\dot{V}$ = volume % increase per month

T = temperature, [$^{\circ}\text{R}$]

FIGURE 3.1. Volume Change of Simulated Waste
(Data from "Untitled Data No. 1")

-
- (a) R. T. Allemann, hand calculation on September 6, 1990.
(b) C. Delegard, Westinghouse Hanford, internal report.

Calculations assuming an overall gas production rate of slurry growth (based on a 9.2-in.-level drop in tank 101-SY after 11 weeks, as in the October 24, 1990, release) indicate that the total slurry volume fraction of the gas produced is 0.01566 or 1.57% of the sludge volume. Figure 3.1 and the equation above suggest that an average temperature of about 133°F would cause this volume increase. The average sludge temperature was about 129°F.

The close agreement of these temperatures suggests that the combination of gas production as a function of temperature, and the thermal transport properties as a function of the gas contained, should allow a calculation of the gas production in the tank sludge as well as the sludge temperature profile. This work is ongoing.

4.0 HEAT BALANCE OF ROLL-OVER

The temperature profiles before and after a gas release are displayed in Figures 2.11 through 2.15. These profiles indicate that the hot material that was on or near the bottom of the tank rose to the top, just below the crust (where the sharp temperature drop in the upper gas temperature occurred), and the cooler liquid moved to the bottom of the tank. The material at the bottom of the tank is thought to be a nonconvective sludge that is generating heat and gas. The temperature profiles that occurred shortly before gas release are indicative of the characteristic profile of a heat-generating slab with heat transported by conduction to the top and bottom of the slab. The constant temperature of the material above the sludge region has the characteristic of a convective liquid. Although heat is expected to be generated in the liquid layer as well, convection equalizes the temperature throughout this layer. The rate of heat generation is estimated to raise the temperature of the tank contents slowly - on the order of $0.1^{\circ}\text{F}/\text{day}$. This heat generation does not account for heat lost through the boundaries of the tank and the ventilation air flow. Hence, because the "roll-over" occurs in an order of minutes, there is a negligible change in temperature from the heat generation or boundary heat loss (see Section 3.1). The phenomenon referred to as a roll-over originates from the concept of a fluid dynamic motion of sludge material rising up within the boundaries of the tank while upper fluid descends. Any heat lost by the release of gas would be a very small fraction (less than 0.0001) of the heat contained in the tank contents when the heat content is referenced to the prerelease liquid-layer temperature (about 121°F) for the October 24, 1990, release.

Considering the temperature of the liquid layer as the reference temperature prior to gas release, the liquid will have no heat content above that reference temperature, and the sludge will have some heat content by virtue of it being warmer than the reference temperature liquid. If the volumetric heat capacities of the two layers were the same, then the temperature profiles could be integrated over the height to give a measure of the heat content, and these temperatures could be normalized by dividing by the prerelease content temperature. This method has been used for two sets of temperature-profile

data. Figure 4.1 indicates the normalized fraction of the initial temperature (heat) content above 121°F, as calculated from data logger temperature information. This information indicates that a high fraction of the initial temperature can be accounted for in the first few minutes after a roll-over. The location of the temperature peaks suggests that the waste layers were highly stratified before and after the gas release. A second heat balance data set has been calculated (taken manually over a longer time interval), and the results are displayed in Figure 4.2. These results indicate an initially high recovery or heat balance lasting several hours as a result of the initial heat content. Yet, at longer time intervals (and also at some shorter intervals), the temperature recovery rate was only 70% to 80% of the initial heat content.

FIGURE 4.1. Short-Term Heat Balance of Liquid Roll-Over of Tank 101-SY on 10/24/90

FIGURE 4.2. Long-Term Heat Balance of Liquid Roll-Over of Tank 101-SY from 10/24/90 to 10/31/90

The manual data, used in Figure 4.2, which extend up to one week after the gas release, suggest one of two things: 1) either the material below the crust was not stratified, such that the temperature profile at the location of the probe was not representative of the total area of the tank as has been assumed in the calculation, or 2) the volumetric heat capacities of the two layers are significantly different.^(a)

(a) Vaporization due to pressure reduction on the hot fluid would result in temperature loss only in the short term.

The temperature balance indicated at early times in Figures 4.1 and 4.2 does not seem to continue. It may be that the initial balance is in error from the dynamic motion of the waste in the region of the thermocouple probe, and thus has indicated a heat balance where it could have displayed a highly unbalanced thermal profile.

5.0 ESTIMATE OF ROLL-OVER DYNAMICS

The thermocouple readings taken during the October 24, 1990, gas release from tank 101-SY suggest that the sludge in the bottom of the tank rises to the top, just below the crust. A rough estimate has been made of the speed of the sludge rise or roll-over in model R-1 once the buoyancy of the gas in the sludge is sufficient to bring the waste sludge into motion (Allemann et al. 1991). The buoyancy may have to overcome yield strength and shear strength factors before it can begin lifting the sludge. These factors, along with the possible effects of viscosity, have been neglected in the simplified analysis discussed in Appendix A. The results of the buoyancy analysis for a few parameter variations are displayed in Figure 5.1.

FIGURE 5.1. Acceleration of Liquid by Buoyancy of Gas for Tank 101-SY

The analysis indicates that the motion begins slowly and accelerates as the gas buoyancy increases. The results provide an order of magnitude estimate of the time that a roll-over would occur in the tank. Starting from a depth of 22 ft for the middle curve with a typical gas release of 6000 ft³, the time necessary for the gas to rise about 22 ft to the bottom of the crust is approximately 50 sec. Similar orders of magnitude have been obtained for other combinations of parameters.

This order of magnitude of time necessary for the gas to rise to the surface is consistent with the data provided in Section 2.0. The release of gas detected by the flow sensors in the off-gas system is on the order of a minute after the temperature elements began to indicate a rapid change in the thermal profile in the waste (although the temporal accuracy is uncertain).

The actual pattern of the roll-over is difficult to predict. The instability criterion represented by a Rayleigh number in a heated convection roll-over has been used to define different modes of roll-over in cylindrical vessels (Neumann 1990). A high Rayleigh number seems to promote a roll-over from one side of the tank to the other. Lower Rayleigh numbers give bisymmetrical or radially symmetrical (toroidal) roll-overs as indicated in Figure 5.2. Analytical results of the buoyancy of gas trapped in the sludge may enable scientists to predict the roll-over that would occur in tanks such as 101-SY and others with smaller gas-release volumes. These analyses would indicate how the buoyancy affects the stability of the data criteria used.

(a) Streamlines of axisymmetric convection in a shear-free cylinder for $a = h/d$, adiabatic sidewall, $R = 700$, and $P=1$.

(b) Profile of the vertical velocity component and corresponding isotaches in the horizontal midplane ($z = 0.5$) for $a = 1$, adiabatic sidewall, $R = 17,500$, and $P = 6.7$

FIGURE 5.2. Patterns of Roll-Over in Vertical Cylinders

6.0 PHOTOGRAPHIC ANALYSIS RESULTS

Photographic mapping of the surface of the tank has been helpful in analyzing the waste crust. This procedure records the position of a notable feature in a photograph and measures and converts the feature's coordinates on the upper surface of the waste crust. This process is accomplished by analyzing photographs to determine the tilt and polar angle of the camera at the time the photograph was taken. Known features of the tank are used as fiducial marks, and the overlaps of the photographs are used to incorporate all the photographs into the analysis. Corrections are made for camera lens aberration. The procedure has been simplified to some extent, to a random sample of surface features, by mapping a grid from each photograph onto the surface illustration and drawing the features on the mapped grids by hand.

Figure 6.1 is a sketch of the surface that has been mapped to date from the April 12, 1989, photographs of tank 101-SY. The notable features are the locations of the bent lances (1A and 17C) and the bent thermocouple probe (4A) (which are bent in different amounts somewhat toward the southwest), and the changed position of the hanging cables (17B and 23A). The head of the arrow is the location of the probe or cable at the crust surface.

The pattern of the very dark gray, liquid-like material overflowing the white, crusty material has been the secondary subject of the mapping effort. This pattern appears to have occurred mainly on one side of the tank, suggesting crust depressions in these regions. (Liquid would have to flow over lower, depressed regions.) A dry, medium-gray region, which can be interpreted as a crust shelf from a superficial look at the photographs, is an extensive region mostly on the northeast side of the tank near the wall. Some ridges or areas where the crust is pushed up are also noted.

FIGURE 6.1. Map of Upper Surface of Waste Crust from Photographs Taken of Tank 101-SY on 4/12/89

7.0 ANALYSIS OF BENT LANCES IN TANK 101-SY

Photographs from inside tank 101-SY have displayed bent lances. Knowledge of the mechanisms that caused these lances to bend may be important for the understanding of gas-release phenomenon, future stabilization, and safety issues.

7.1 FLUID FORCES ON BENT LANCES IN TANK 101-SY

The lances were not all bent in the same tangential direction, indicating that the crust did not rotate as a single plate. One hypothesized mechanism is that the dynamic fluid friction of the liquid moving or rolling under the crust drags the crust blocks along and moves them in random directions. (This idea has not yet been evaluated.) The idea that lances are bent from the jet action of the air flow (when the lances were operated) does not seem credible for two reasons: 1) the reaction forces would not have been strong enough to bend the lances, and 2) the thermocouple probe is also bent.

Another suggestion explaining the bent lances originates with the potential that the rising crust might have buckled the lances, but the discussion in Section 7.2 indicates that the strength of the crust is probably insufficient for that to have occurred. Also, that occurrence would not explain the transverse location of some of the hanging cables in the tank.

A third hypothesis discussed is that the gas release passes unequally through cracks in or around the crust, which results in lateral forces on floating blocks of crust. These forces are strong enough to move the blocks of crust and imbedded cables, and plastically bend the imbedded lances.

Analyses indicate that the mechanism of a floating block of crust with gas flow through the crack on one side and stagnant liquid on the other side could produce forces strong enough to bend the lances.

In this mechanism, gas rises from the sludge in the lower part of the waste tank and expands from the decreasing hydrostatic head. This expansion causes the waste level to swell and the crust to be lifted, which in turn, causes stresses that perhaps result in breaking the crust into blocks of some

considerable size and distribution across the tank. The bending and breaking of the crust could then be caused by the unsymmetrical location of the rising gas.

The rising gas could come up against the crust and, in some cases, move toward one side of a block more than another and begin to exit to the head space through a crack on one side of the block more than the other. If the gas passed through the crust around a floating block of crust, then a lateral force would be developed as indicated in Appendix B. Figure 7.1 illustrates the lateral force in this situation and defines some of the variables.

The analysis described in Appendix B results in lateral forces as indicated in Figure 7.2. The magnitude of the calculated forces ranges from 100 to 900 pounds per ft width and are about 400 pounds per ft width for estimated realistic values of the parameters. Such forces are sufficient for blocks wider than approximately 1 ft to provide a yield stress moment on the 2-in., Schedule-40 lances. With the crust pushing sideways on the lance at a distance of 11 ft from the bottom of the entry riser in the dome, the yield force would be about 127 pounds (J. R. Friley letter-report 2, November 1990).^(a)

Further development of this hypothesis is needed to consider the velocity of the block and to consider how sufficient deflection of the lances is achieved to yield the pipe within the tank. An estimated yield deflection at the crust level (9 to 11 ft below the dome) is about 4 to 6 in. This is equivalent to a bend angle of 2 to 3 degrees. The measured bend angles, as obtained from photographic analysis, range from 8 to greater than 20 degrees. Hence, the blocks either moved a great deal in a single event or have been able to ratchet the lances into large deflections with a series of movements of greater than 4 to 6 in.

Furthermore, another mechanism needed for this general hypothesis is that the moving blocks must first make the crust compress, override, or subduct in order to accommodate the change in block position. Realistically, the crust has not moved as a single plate, and it is topologically impossible to move part of the crust without deformations of the types mentioned. If the gas

(a) J. R. Friley, Westinghouse Hanford Company, private communication.

FIGURE 7.1. Diagram of Variables in the Theory of Lateral Force Created by Gas Passing Through Cracks Around a Floating Block of Crust

FIGURE 7.2. Diagram of Lateral Force Per Foot Width Calculated Using Various Parameters

preferentially came through a gap on one side of a block, then the block would be lifted or tilted up on that side by the higher hydrostatic pressure. This lift is demonstrated in Figure 7.1 where the gas bubble has the pressure of its maximum depth, and the liquid-side of the block has the hydrostatic pressure of the head that is needed to float the block.

The lifting of the block on the gas side, combined with the lateral force toward the gas side, would tend to close the gap and drive the block upward onto the relatively fixed crust on that side. The crust block could thus become tilted further, resulting in a rough and raised crust surface on the gas side toward which the lances are bent. This action would result in a depressed surface on the other side of the crust. The depressed surface could allow more liquid to run over the top if the density ratio was high enough to allow the crust to float low on the liquid. Photographs display some evidence of this phenomena, because a dark liquid surface appears generally on the side from which the lances bend away (see Figure 6.1).

7.2 BUCKLING OF LANCES FROM CRUST RISE IN TANK 101-SY

Photographs taken April 1990 from inside the head space of tank 101-SY reveal that two lances and a thermocouple probe have been plastically bent from a vertical position. These probes are made of 2-in., Schedule-40 steel pipe and are hung through 4-in. risers at the top of the tank. One hypothesis for the bending is that the crust became bonded to these pipes as the waste level swelled and rose, thus providing a force sufficient to cause column buckling. The residual stress in the plastically bent pipe could have resulted in its observed displacement where it passes into the top of the crust. Movement of the crust at this location would also have resulted in the pipe being bent.

Considering the likely strength of the crust material, it appears that bending of the lance pipes was caused by the horizontal motion of the crust as localized plates rather than the vertical motion of the crust. This type of pressure would cause pipe buckling and horizontal plastic deflection.

The buckling force on the 2-in. pipes in the 9-ft space between the crust and the tank dome ranges from 4,000 to 67,000 psi, depending on the assumption

of a free or ideally clamped pipe end in the crust. The required buckling forces would actually be less than this range in tank 101-SY, because the tops of the pipes are not ideally clamped. Bonding shear strength or crust shear strength required to provide these forces with a 4-ft-thick crust are 12 to 190 psi, respectively.

The vertical force is considered to be supplied by either 1) the flotation force of the crust as the level rises in the tank after the crust has bonded to the pipe, 2) a friction force of the crust as the crust rises a few inches just before gas is released and then settles again, or 3) a pinching action that grips the pipe by a tilted crust plate that rises (or later by the fact that the pipe is tilted through the crust). The estimated area of the crust plate providing the flotation force is 200 to 3500 ft².

End loads necessary to cause buckling of 2-in. pipes were calculated and are listed in Table 7.1. The values in Table 7.1 are higher than actually required because the tops of the 2-in. pipes are not truly clamped, but pinned at the top flange of the 4-in. riser pipes.

The crust area required to produce the respective forces was estimated assuming a crust specific gravity of 1.2, and a liquid specific gravity of 1.57. The entire area of the tank is about 4400 ft², so the forces could be produced by flotation if the crust acted as a unit and could sustain the shear loads. Shear crust strengths are not available. The crust is thought to be a salt or perhaps a mixture of sodium nitrate and aluminates. Without having

TABLE 7.1. Column Buckling Results for 2-Inch Pipes
in Tank 101-SY with a 4-Foot Crust

<u>End-Load to Buckle (pounds)</u>	<u>Pipe Conditions</u>		<u>Estimated Crust Area at 10-in. Float (ft²)</u>	<u>Required Crust or Bond Shear Strength (psi)</u>
	<u>Top</u>	<u>Bottom</u>		
4,000	clamped	free	200	12
35,000	clamped	pinned	1,800	100
67,000	clamped	clamped	3,500	190

data on the specific strength of the crust, only an estimate of the strength can be made. If the crust were as strong as plaster of Paris (hydrous calcium sulfate), then it would have a shear strength of about 70 to 100 psi. Surely the crust would not be as strong as concrete with a shear strength estimated to be equal to its tensile strength of about 300 psi (Baumeister and Marks 1967).

The plastic collapse load of the pipe is 32,000 psi. A fairly high bond/shear strength of the crust would be required to collapse the pipe. If friction provided the upward force either by sliding or by a pinching action of a tilting crust plate, then the shear strength would still represent an approximate limitation to the applied vertical force.

Table 7.1 displays the calculated buoyancy force by assuming the specific gravity of the crust to be 1.2 and that of the liquid to be 1.57. If the force produced by a 10-in. rise in liquid level were caused by a level swell prior to a gas release, then the force would be as follows:

$$F = g (d_l - d_c) h A$$

where F = force

g = gravitational acceleration

d = density of liquid and crust

h = height of crust movement

A = area of crust plate

so,

$$A \text{ <ft}^2\text{>} = F \text{ <lb>} / (1.57 - 1.2) * 10/12 \text{ <ft>} * 62.4 \text{ <}\frac{\text{lb}}{\text{ft}^3}\text{>}$$

The approximate shear stress (T) required to produce a vertical force (F) by a crust bonded to the 2-in. pipe for a length (H) is obtained from

$$F <lb> = T <psi> * pi * D <in.> * H <in.>$$

where D is the diameter of the pipe (see Table 7.1).

With the limitations on shear strength, the pipe would buckle only if the crust was allowed to move sideways; the free-end condition. Considering the bonding strength required for this case, it would not appear likely that the crust would allow a sideways motion, as the plate would have to generate a magnified side force to cause movement. The bonding stress would be sufficient to keep the crust plate immobile and necessitate the clamped-clamped condition. But, in the clamped-clamped condition, the crust-yield strength is insufficient. Therefore, it is much more likely that the pipes have become bent because of horizontal motions of the crust rather than vertical crust motion. Vertical crust motion would cause a buckling of the pipe and a sideways motion of the local crust plate.

8.0 BUBBLE DYNAMICS

Two proposed mechanisms of gas release are 1) model R-1 (total sludge buoyancy), where gas is trapped in the sludge and separates from the sludge after lifting it to the top of the liquid waste by buoyancy, and 2) model R-3 (bubble separation from sludge), where bubbles move from the sludge without lifting it. The more recent data obtained from the October 24, 1990, gas release suggest that model R-1 is more likely than model R-3 but some aspects of bubble dynamics may be important in either case.

The following discusses an initial literature review of the physics of bubble motion. The review was conducted to determine if some of the observed phenomena could be explained by bubble dynamics.

The classical theory of Stokes flow and experimental relations presents the velocity of bubbles of various shapes in simple Newtonian fluids such as water.

The rise velocities of bubbles in viscous and non-Newtonian water-based media are always smaller than in water alone. Experiments made using non-Newtonian liquids such as polyethylene oxide display an abrupt change in velocity with bubble size. The velocity data indicate a velocity change from about 0.48 to about 2 cm/sec (a factor of four) at a critical bubble size of about 0.27-cm diameter. There is a shape change in the bubbles at the critical size that, along with the viscoelasticity of the medium, contributes to a lower drag effect. A possible explanation of a critical bubble size is the transition from the Stokes flow (solid body) to the Hadamard-Rybczynski (circulating body) flow regime. This explanation involves a transition from a no-slip condition to a free-shear condition at the bubble boundary. Another explanation would be the development of a cusp at the rear pole of the bubble therefore resulting in a lower drag coefficient. A stagnation point at the rear of the bubble may promote the accumulation of surface-active impurities causing immobilization of the surface, high shear conditions, and high drag coefficient.

The effect of a non-Newtonian, shear-dependent viscosity (in the absence of any elastic effects) would produce a terminal velocity ratio much closer to

1.5 than the observed values of four or more. (The ratio of the Hadamard-R. velocity to the Stokes velocity for a Newtonian liquid is 1.5.) Hence, it appears that the elastic effects must be included in a successful explanation of the magnitude of the velocity jump. An analysis of the bubble separation from the sludge may also require treatment of the elastic effects of the sludge. Details of the rheology of the sludge are not known, but some aspects may be learned from simulation experiments in progress at PNL.

The bubble discussion reiterates the fact (particularly in model R-3) that when the bubbles are just forming they are very small ($<10^{-3}$ cm). Bubbles do not move in the slurry medium or coalesce until they grow large with the infusion of more generated gases. Bubble sizes approach a critical diameter when they begin to rise slowly at first and then faster as the jump in terminal velocity occurs. At this phase of development, coalescence from differing speeds may occur. If this was happening in the bottom sludge layer at an average velocity of .2 cm/sec, then the bubbles could traverse the sludge thickness on the order of 3 to 4 min. If bubble motion triggered a reduction in viscosity or shear strength, then bubble motion would cascade and result in a relatively sudden and large release that would allow the liquid level to collapse by the equivalent volume of the bubbles released. Estimates of gas solubility in the liquid indicate that bubbles would not grow significantly large during the rise by the scavenging of dissolved gas from the liquid through which they pass.

The dynamic bubble theory and calculation are still being pursued, as the traditional form for a separate gas phase is that of bubbles. One important aspect of the mechanism of release has to do with gas separation. The separation of gas from the risen sludge in model R-1 must occur rapidly because the gas release is closely associated with the temperature-profile overturn. The rapid separation suggests that expansion growth of the bubbles is enough to bring them to a high velocity regime. The rapid separation could also suggest that the sludge changes to a lower viscosity or lower shear strength after rising to the top. Again, characteristics of the sludge may be obtained from in situ data or from experiments with synthetic waste.

9.0 REFERENCES

Allemann, R. T., Z. I. Antoniak, J. R. Friley, C. E. Haines, L. M. Liljegren, and S. Somasundaram. 1991. Mechanistic Analysis of Double-Shell Tank Gas Release Progress Report - November 1990. PNL-7657, Pacific Northwest Laboratory, Richland, Washington.

Baumeister, T., and L. S. Marks. 1967. Standard Handbook for Mechanical Engineers. McGraw-Hill, Inc., New York.

Delegard, C. 1980. Laboratory Studies of Complexed Waste Slurry Volume Growth in Tank 241-S4-101. RHO-LD-124, Informal Report, Rockwell Hanford Operations, Richland, Washington.

Neumann, G. 1990. "Three-Dimensional Numerical Simulation of Buoyancy-Driven Convection in Vertical Cylinder Heated from Below." J. Fluid Mech. 214:559-578.

APPENDIX A

ROLL-OVER DYNAMICS

APPENDIX A

ROLL-OVER DYNAMICS

Below is an order-of-magnitude analysis to estimate the time and velocity of a sludge roll-over driven by the buoyancy of trapped gases.

1. Assume that the two regions of sludge are made of roughly the same density, but a small difference exists which is sufficient to cause motion to start. The buoyancy force of the lower layer overcomes the density difference and any yield or shear strength factors that may repress the motion.
2. The sludge and fluid, which are assumed to make up the waste volume, fill the entire space below the crust. Thus, moving any part of the fluid means another part must be displaced. If the rising material comes from some depth, h , the displaced material descends to approximately the same depth. The distance moved by an average particle in the tank depends on the mode of overturn. A gross overturn might result in an average particle travel distance, S_m , on the order of

$$S_m \approx \sqrt{(\text{depth} \cdot \text{tank radius})}$$

3. The driving force at zero time is the buoyancy of the bottom sludge.

$$F_0 g_c = g \Delta \rho_0 V_s$$

where F_0 = force of buoyancy at initial time

g_c = conversion constant

g = gravitational acceleration

ρ_0 = density at initial time

V_s = volume of buoyant sludge

4. As the motion proceeds, the force gets larger. The gas expands as it rises into less hydrostatic pressure, and the force changes proportionally to the distance moved.

$$F g_c = [S/S_m (\Delta \rho_m - \Delta \rho_0) + \Delta \rho_0] V_s g$$

where F = force of buoyancy
 gc = conversion constant
 ρ_m = density of sludge after rising to the top
 S = distance particles moved after initial time onset
 S_m = maximum distance particles moved
 V_s = volume of buoyant sludge
 g = gravitational acceleration

5. The equation of motion for the entire mass in the tank volume, V_t , can then be written as

$$d^2S/dt^2 = [S/S_m (\Delta\rho_m - \Delta\rho_o) + \Delta\rho_o] V_s/V_t g/\rho$$

where t = time
 V_t = volume of mobile sludge and liquid in tank below the crust

6. The solution of the above differential equation is

$$S = b/a \cdot [\cosh(\sqrt{a} t) - 1] \text{ or the inverse}$$

$$t = 1/\sqrt{a} \log_e [p + \sqrt{p^2 - 1}]$$

where $p = aS/b + 1$
 $a = (\Delta\rho_m - \Delta\rho_o)/S_m \cdot V_s/V_t \cdot g/\rho$
 $b = \Delta\rho_o \cdot V_s/V_t \cdot g/\rho$

7. The calculations of the above equation for time and distance have been carried out for typical parameters such as

$$V_s/V_t = \text{height of sludge/height of waste} \approx 15 \text{ ft}/30 \text{ ft} = 0.5$$

$$S = \text{distance moved, 15 to 25 ft}$$

$$V_g = \text{volume of gas released at 1 atmosphere} = 6000 \text{ ft}^3$$

$$\Delta\rho_o = \rho - \rho/[1 + v_g/v_s/(1 + \rho g h \cdot 144/14.7)]$$

$$\Delta\rho_m = \rho - \rho/[1 + v_g/v_s]$$

$$\rho = 1.6 \times 62.4 \text{ lbm/ft}^3$$

Illustrated calculation results for the acceleration of liquid by buoyancy of gas for tank 101-SY are found in Figure 5.1.

8. These calculations have neglected to consider viscosity effects. Also, they do not treat the cohesive effects of the sludge, the multiplicity of possible modes of the roll-over phenomenon, or the flow regimes which may range from laminar to turbulent. However, the calculations give an order-of-magnitude estimation of the time scale of the phenomenon.

APPENDIX B

LATERAL FORCE ON A FLOATING BLOCK OF CRUST

APPENDIX B

LATERAL FORCE ON A FLOATING BLOCK OF CRUST

The pressure per unit width is on the liquid side of the block (see Figure 7.1),

$$p_f = \int_0^h (P - \rho_f hb \text{ g/gc} - \rho_f y \text{ g/gc}) dy$$

where P = the pressure of the gas = $(h + hb) \rho_f \text{ g/gc}$
 ρ_f = density of the fluid
 hb = depth of gas bubble
 y = vertical distance above the bottom of the block
 g = gravitational acceleration
 gc = conversion constant
 h = depth of floating block

Solving the above equation gives

$$p_f = \rho_f h^2/2 \text{ g/gc}$$

The gas is blown through the gap by pressure P on the gas side of the block. Considering the entry as a contraction loss for gas flow, neglecting the hydrostatic pressure of the gas, and assuming the entrance velocity is zero, the change in static pressure is

$$P - P_g = \frac{1}{2} \rho_g U^2 / gc + \frac{1}{2} K \rho_g U^2 / gc$$

where P = the pressure of the gas = $(h + hb) \rho_f \text{ g/gc}$
 P_g = the pressure in the gap
 U = velocity of the gas in the gap
 K = entrance loss coefficient

gc = conversion constant
g = gravitational acceleration
 ρ_g = density of gas.

Assuming the square corner entry, $K = 0.5$, the static pressure after entry (P_g), is used up as a friction pressure drop through the gap.

$$P_g = f T U^2 \rho_g / (2 gc D)$$

where P_g = pressure in the gap
f = a friction factor
D = hydraulic diameter of the crack through which the gas flows
T = thickness of block or length of crack where gas flows
U = velocity of the gas in the gap
gc = conversion constant
 ρ_g = density of gas.

The combined pressure drop allows the equation for flow velocity to be written as

$$U^2 = P / [f T \rho_g / (2 gc D) + 0.75 \rho_g / gc]$$

Assuming linear pressure drop through the gap, the lateral force per unit width on the block on the gas side is

$$P_g = T P_f / 2$$

Combining the above equations where $P = \rho_f (h + hb) \cdot g$ gives

$$P_g = T/2 [\rho_f (h + hb) \cdot g / gc] [1 - 0.75 / (f T/2 D + 0.75)]$$

The lateral force per unit width is the difference between the force by the fluid side and the gas-side gaps

$$F_w = P_f - P_g$$

These algebraic equations have been calculated for a range of parameters

density ratio crust/fluid	0.5 to 1.0
crust thickness	4 to 6 ft
gas gap width	0.5 to 0.1 in.
fluid specific gravity	1.3 to 1.5
friction factor in gap	.01 and .02

Figure 7.2 indicates that the calculated lateral forces of some of these parameters varied. Note the forces are calculated to be in the range of hundreds of pounds per foot of width of the block.

DISTRIBUTION

No. of
Copies

No. of
Copies

OFFSITE

12 DOE Office of Scientific and
Technical Information

E. C. Ashby
225 North Avenue
Boggs Chemistry Building
Georgia Institute of
Technology
Atlanta, GA 30332

N. E. Bibler
Westinghouse Savannah River
Co.
Bldg 773A, Room B132
Box 616
Aiken, SC 29802

G. R. Choppin
Department of Chemistry B-164
The Florida State University
Tallahassee, FL 32306

C. Grelecki
Hazards Research Corporation
200 Valley Road, Suite 301
Mt. Arlington, NJ 07856

E. P. Horwitz
Chemistry Division
Argonne National Laboratory
9700 Cass Avenue
Argonne, IL 60439-4831

B. R. Kowalski
Chemistry Department BG-10
University of Washington
Seattle, WA 98195

D. Meisel
Chemistry Department
Argonne National Laboratory
9700 Cass Avenue
Argonne, IL 60439-4831

F. L. Parker
Vanderbilt University
P.O. Box 1596, Station B
Nashville, TN 37235

G. Powers
Design Science Inc.
163 Witherow Road
Sewickley, PA 15143

G. A. Russell
Professor of Chemistry
Iowa State University
Gilman Hall
Ames, IA 50011-3111

A. Schneider
Massachusetts Institute of
Technology
Department of Nuclear
Engineering
Room 24-1098
77 Massachusetts Avenue
Cambridge, MA 02139

W. W. Schulz
727 Sweetleaf Drive
Wilmington, DE 19808

D. D. Siemer
WINCO
IRC MS 2207
Idaho Falls, ID 83403

W. J. Thomson
Dept. of Chemical Engineering
Washington State University
Pullman, WA 99164

J. Tseng
U.S. Department of Energy
EM-35
Trevion II
Washington, DC 20585-0002

No. of
Copies

G. Wallis
Associate Dean
Thayer School of Engineering
Dartmouth College
Hanover, NH 03755

ONSITE

3 DOE Richland Field Office

R. F. Christensen, A4-02
R. E. Gerton, A5-21
G. W. Rosenwald, A5-21

33 Westinghouse Hanford Company

J. Allen-Floyd, R2-31
H. Babad, B2-15
D. G. Baide, R1-51
M. L. Bell, T5-50
R. M. Black, R1-19
R. J. Bliss, B3-04
H. R. Brager, L5-03
W. F. Brehm, H5-67
T. M. Burke, H0-34
R. J. Cash, R2-31
D. L. Deichman, H0-03
G. L. Dunford, R1-51
K. A. Gasper, B3-68
W. H. Hamilton, R2-40
D. L. Herting, T6-50
R. C. Hill, H4-23
J. Jewett, T6-50
G. D. Johnson, L5-03 (2)
N. W. Kirch, R2-11
J. W. Lentsch, R2-31
R. D. Marusich, H5-32
D. Ogden, H0-34
D. A. Reynolds, R2-11 (5)
W. G. Ruff, R2-53
M. H. Shannon, B1-35
D. D. Stepnewski, N1-31
R. E. Vandercook, S6-07
D. D. Wodrich, R2-23

No. of
Copies

43 Pacific Northwest Laboratory

R. T. Allemann, K5-19 (5)
Z. I. Antoniak, K7-15
J. A. Bamberger, K7-15
J. M. Bates, K7-15
J. B. Colson, K5-10
T. H. Dunning, K2-18
J. R. Friley, K5-22
C. E. Haines, K7-28
R. T. Hallen, K2-12
M. S. Hanson, K1-51
B. M. Johnson, Jr., K5-02 (5)
M. R. Kreiter, K6-35 (5)
D. K. Lemon, K2-28
L. M. Liljegren, K7-15
G. B. Mellinger, K1-78
L. G. Morgan, P8-07
L. R. Pederson, K2-44
J.T.A. Roberts, K1-73
R. D. Scheele, P7-25
S. Somasundaram, K5-19
J. C. Spanner, K2-31
D. M. Strachan, K2-44
R. W. Stromatt, P7-22
D. S. Trent, K1-82
H. H. Van Tuyl, P7-22
Publishing Coordination
Technical Report Files (5)

END

**DATE
FILMED**

4 / 09 / 92