DOE/CE/28313--T2

DE93 006139

**SMALL COMMERCIAL PROGRAM
DOE PROJECT**

IMPACT EVALUATION

-- Final Report --

Submitted to:
WASHINGTON ELECTRIC COOPERATIVE

Submitted by:
Ron Bathgate and Steve Faust
ENERGY & SOLID WASTE CONSULTANTS

August 12, 1992

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

MASTER

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

TABLE OF CONTENTS

1. EXECUTIVE SUMMARY	1
2. PROGRAM OVERVIEW	2
Program Objectives	2
Program Description	2
3. EVALUATION PURPOSE	3
4. METHODOLOGY	3
5. DATA SOURCES	4
6. RESULTS	6
7. CONCLUSIONS AND RECOMMENDATIONS.....	22
APPENDIX 1 - Equipment Matrix	
APPENDIX 2 - Metering Matrix	
APPENDIX 3 - kWh Comparison 1991 - 1992	
APPENDIX 4 - Weather Data	
APPENDIX 5 - WEC kW Peaks	
APPENDIX 6 - Store vs. System Peaks Graph	
APPENDIX 7 - Store vs. System Peaks Table	
APPENDIX 8 - On-Peak vs. Off-Peak kWh	
APPENDIX 9 - Store kW Peaks	
APPENDIX 10 - Table of Significant Dates	
APPENDIX 11 - Duty Cycles	
APPENDIX 12 - Walk-in Cooler Savings: Joe's Pond Store	
APPENDIX 13 - Walk-in Cooler Savings: Hastings Store	
APPENDIX 14 - VEIC Audit Reports, Recommendations, Summaries	

1. EXECUTIVE SUMMARY

In 1991, Washington Electric Cooperative (WEC) implemented a Department of Energy grant to conduct a small commercial energy conservation project. The small commercial 'Mom and Pop' grocery stores within WEC's service territory were selected as the target market for the project.

This report documents Energy & Solid Waste Consultant's (E&SWC) Impact Evaluation. The evaluation was based on data gathered from a variety of sources, including load profile metering, kWh submeters, elapsed time indicators, and billing histories. Five stores were selected to receive measures under this program: Waits River General Store, Joe's Pond Store, Hastings Store, Walden General Store, and Adamant Cooperative. Specific measures installed in each store and description of each can be found in Appendix 1.

The significant conclusions from the Impact Evaluation are:

- The outside ambient air (OAE) measures showed potential for energy savings as predicted;
- The evaporator fan controls, in combination with the OAE, appear to demonstrate potential savings;
- Changes in duty cycle in lieu of adequate metering data indicate savings potential on refrigeration measures;
- There was not sufficient metering time to obtain data on the effectiveness of the door heater controls;
- Although lighting measures were not metered, assuming no changes in duty cycle, savings should be as predicted;
- Some metering changes are recommended for more accurate data on various measures;
- A full year's monitoring on installed measures is needed for leveled data; and
- Changes in kWh use fluctuate on a monthly basis.

In essence this Impact Evaluation is an interim report. Given the somewhat delayed installation of equipment and the insufficient monitoring periods, pre and post, it is recommended that WEC continue collecting data and conduct an impact study in the summer of 1993. The engineering studies for

the conservation measures were computed on an annual basis. Given the short monitoring period of five months total with just two months post installation, an accurate comparison using annualized results is impossible. A full year of monitoring will verify persistence of savings over time.

2. PROGRAM OVERVIEW

The Department of Energy (DOE)-funded Rural Cooperative Demand Control Project was undertaken by WEC as an adjunct demonstration project to its small commercial demand side management (DSM) program. The DSM program will capture cost effective conservation resources by retrofitting energy efficiency measures to equipment in existing small commercial buildings and facilities in WEC territory.

Program Objectives

- Assess various equipment options in order to facilitate the DSM program;
- Provide systematic, defensible, and objective data on actual savings versus predicted savings for the various conservation measures;
- Assist WEC in evaluating the cost effectiveness of measures and their usefulness in achieving the objectives of the DSM program;
- Compare the pilot store load curves with the system;
- Identify factors that may influence savings, eg. operational or weather changes; and
- Provide useful data on payback for evaluation of incentive levels offered in the DSM small commercial program.

The last objective is most important since WEC intends to ensure a one year payback on member investments for the installation of energy efficient measures under the DSM small commercial program.

Program Description

This program was designed to install energy efficiency measures in selected small grocery stores to maximize energy conservation without affecting store operation. The results of this effort will improve the effectiveness of WEC's small commercial DSM program. E&SWC was contracted to conduct monitoring and evaluation of this program. Vermont Energy Investment Corp. (VEIC) was the selected auditing contractor.

The small grocery store market was selected because it is a small portion of WEC's membership, just ten stores, and therefore an easy market segment to target. All have similar equipment installed and are similar operationally. Overall there is not a great deal of difference in the ten stores other than four larger stores with monthly kWh averages ranging from 4500 - 8500. The smaller stores range from 850 to 5000 kWh per month. As noted in the Process Evaluation of this program, only five stores were selected to receive conservation measures. Since funds were limited, it was decided to do a more comprehensive job on fewer stores and include the remainder in the DSM program at a later date. This would mean that the participating stores would not have to be revisited for other measure installation and would be treated as comprehensively as stores falling under the DSM program.

It will be pointed out in this report where the data indicate that savings are noteworthy even after such a short monitoring period. For example, the refrigeration measures installed in the Hastings Store showed 49% kWh savings over the short monitoring period (Appendix 13). Problems arose with metering and data collection that affected the data from several stores. However, the data available demonstrate the potential for savings with several of the installed measures.

3. EVALUATION PURPOSE

This evaluation effort was undertaken to verify the predicted savings for the selected energy conservation measures. It will also identify barriers to savings, problems related to data gathering, and make recommendations on how to improve data collection, including metering changes and additions. Variables affecting energy consumption and data collection will also be identified.

4. METHODOLOGY

Submetering of specific end uses before and after measure installation was determined to be the most appropriate means of obtaining data on actual savings (Appendix 2). At the five selected stores refrigeration and lighting measures were determined to be the most cost effective and estimated to provide the most savings. The refrigeration-related measures are the most important end uses to target since the lighting measures have no significant changes in duty cycle over the course of a year.

For the OAE measures it was anticipated that sufficient pre and post installation metering time would be obtained to provide an accurate picture of potential savings. However, since 35°F is the operative temperature with this measure (OAE operates at or below 35°F) and due to the late winter installation, not enough data was available. We recommend a full year's metering to provide annualized data.

The door heater controls also presented a difficult monitoring problem in that they are normally disconnected for up to six months during the fall and winter. Although the elapsed time indicators showed actual run time, a minimum of six months monitoring is required in order to obtain seasonal data that can be compared to the previous 100% duty cycle during the summer months.

Despite the difficulty in obtaining accurate volt/amp readings on the lighting in all the stores, the estimated savings are fairly accurate based upon the fact that the duty cycles change little over a year. We do recommend, however, that a data recorder be used on at least one store to verify the predicted savings. A week's worth of data would be adequate.

5. DATA SOURCES

Metering

Where possible (selected cooler compressors, and one attached apartment) standard kWh submeters were installed. Load Profile Recorders (LPRs) with 2 and 3 channel hook-ups were installed on two stores, and the remaining three stores had Sangamo digital display meters installed to monitor the whole store. Choices for end-use metering were limited for a number of reasons. Availability of sophisticated recording meters was hindered initially because of the unavailability of the type of meter selected (Appendix 2). Since funds were also limited the purchase of new meters was limited. WEC owns enough LPRs that all participating stores could have had one installed but current metering needs precluded moving these meters. Software for the data translation from the LPRs was not available to WEC and this was contracted out to Green Mountain Power.

Elapsed time indicators were chosen as an inexpensive and effective means of tracking actual run time for the door heater controls, evaporator fans, and OAE measures. As noted elsewhere, one-time volt/amp readings on

the lighting (comparing before and after) were not possible due to circuit contamination. Most stores had wiring that had many different end uses on the same circuit.

Data Collection

Store billing data is used to determine consumption patterns and changes as well as kW peaks for comparison with system peaks. kWh data has been adjusted according to varying meter read dates.

The metering matrix outlines the originally planned metering configuration and specific meters to be used. Amp/volt readings on door heater controls, lighting, and evaporator fans were obtained, but due to the complexity of the wiring the readings were contaminated. In all stores only the compressors are wired separately. All other pieces of equipment are wired in a variety of combinations. Therefore, accurate one-time amp/volt draw for end uses, particularly overhead lighting and door heater controls, the latter wired with the door lights, are not included in the data.

The monitoring period included time when ambient temperatures were fluctuating above and below 35°F (the temperature at which OAE equipment begins and stops operating) with most of the post-installation time showing daily temperatures above 35°. However, comparing duty cycles for this equipment is a reasonable means of showing operational differences between pre and post-installation. The duty cycles will increase over the warmer months to approximately 50 to 60%, but during months of colder weather will operate at cycles ranging down to approximately 20%.

In the summer of 1993 data will have been collected for an entire year, thus providing sufficient information to make reasonable comparisons to historical data and engineering estimates. A full year's monitoring will also allow for tracking of weather and humidity variables which impact specifically on the OAE and door heater control measures. To aid in the accuracy of a future impact study it would also be useful to conduct monthly or quarterly interviews with store owners to determine operational changes in stores and factors affecting apartment usage.

At Waits River General Store the load profile recorder (LPR) meter had one channel set on the apartment, one on a display freezer, and one channel as main meter for the entire store. The apartment channel is redundant with the kWh submeter already in place, and the freezer channel is also redundant and further, had no conservation measures installed. This error was not discovered until after all the data was collected. One channel should have been dedicated to an end use in the new walk-in as noted on the metering matrix (Appendix 2) and the second channel set to monitor one of the lighting applications.

Historic data from billing records are the only data used for the Walden Store. The billing data showed an increase in kWh consumption over the entire monitoring period compared to the same time period the previous year. Since an interview with the store owner turned up no significant operational changes, only a full year's monitoring period may provide an accurate picture of savings.

Estimating annual savings for the door heater controls at Joe's Pond and Hastings is impossible due to several variables. Previous to installation it was estimated that the door heaters were run during the warmer months (3 - 6 months) for 24 hours per day. Humidity levels within each store had no direct effect on consumption. The controls now operate the heaters based upon relative humidity near the doors. Short run times during the monitoring period are also a variable. See the section below on recommendations for further monitoring and evaluation.

6. RESULTS

Historic Data

All ten stores are included in the historic overview of energy consumption. The five stores not participating in this project (Maple Corner, Duxbury, O.J.'s, West Topsham, and Crossroads) serve as a comparison group. These stores are not considered as a control group since no load profile data was available. Historic data consist of billing records on each store.

In reviewing the data for a full year, it is not surprising that nearly all stores, with the exception of O.J.'s, and West Topsham, showed higher monthly kWh use during the summer months. All store owners report summer as their busiest time of the year. Reasonably, this higher use might be attributed to

the increased refrigeration load during these months. However, O.J.'s, and West Topsham showed no appreciable increase in summer consumption. West Topsham has a refrigeration load comparable to other stores while O.J.'s has a smaller load. We can find no apparent reason for why these two stores showed lower summer consumption other than more dispersed loads and equipment differences. None of the other stores have exceptional summer loads such as might be caused by air conditioning.

Historic to Current kWh Usage Comparisons

The following comparisons are made store by store. They compare kWh data recorded from January through May 1991 to the kWh data recorded for January through May 1992. This was the monitoring period for the five stores that received equipment and special metering and therefore represents the only currently suitable period of time for purposes of comparison (Appendix 3). Please note that the data recorded in one month refer to the usage in the previous month. Thus, March's data are showing the usage during February, April's for March, etc.

The comparisons are made in an effort to provide WEC staff with the information upon which to make a decision to conduct further research into the causes of these historic fluctuations and/or to continue monitoring these store's kWh usage for a full year's time, as recommended in this report. It is beyond the scope of this study to research the reasons for any of the changes in kWh usage during these time periods. A few obvious explanations have been offered, yet due to the wide month to month fluctuations at all stores except Joe's Pond, no clear predictions can be made on future usage patterns.

During the five month monitoring period four out of the five participating stores lowered their average electric consumption from the previous year. Waits River is the exception with a modest 1.8% increase. The Adamant Coop showed a 12% increase in January 1992 compared to January 1991 and in the next three months of 1992 realized reductions of 21, 11, and 23% respectively over 1991. Lighting improvements were completed on April 13 and April's readings are the last full month of kWh data available as of July 1, 1992. It appears as though the management of the Adamant Coop is making a successful effort over and above the lighting changes, to reduce their electrical energy needs. Their daily kWh consumption is down 10% from 1991.

Of the participating stores, Joe's Pond store shows the most solid trend towards reducing its electrical energy consumption. The January through May period, representing December through April kWh consumption, shows reductions of 7, 13, 15, 23, and 27% with an overall drop of 17.4% for this period from 1991 to 1992. Adjusted daily kWh consumption is down 17.3% from 1991.

A comparison of the kWh data for the Waits River store presents a picture of large increases and decreases of average electrical consumption. Data showed a 9% increase in January, a 19% increase in February, a 22% decrease in March, followed by a 19% increase in April, and May recorded a 7% decrease. On a monthly basis this averages out to a barely noticeable 1.8% increase over this period. Looking at kWh/day, adjusted for variances in reading dates, daily consumption for the period was up to 236.2 kWh/day in 1992 from 231.9 kWh/day in 1991, a 1.8% increase.

Hasting's store data showed a modest, averaged reduction of 6% over this same time period, yet February's data recorded a substantial 23% decrease over the same period in 1991. In January 1992 the store consumed 1,100 kWh's less than in the previous January. Daily kWh consumption went down 7% over the same period in 1991.

Over the monitoring period the Walden General store showed a modest reduction of 2.7%. Like Hasting's store, a nearly 31% decrease showed up on the February data. Interestingly, their new refrigeration equipment was operational as of March 19 of this year, yet the April and May data showed increases of 9 and 13% respectively. Daily consumption shows a 3% decline over 1991.

Of the non-participating stores, the Crossroads Trading Post showed the highest drop in kWh use, 22%, during the same 5 months in 1992 compared to the same time period in 1991. Yet, this store's data also showed a significant swing. January's usage was 17% less, February's was 20% greater, and March and April showed decreases of 33 and 37% respectively.

Consumption at the Maple Corner store was consistently less during the months of January, February, March, and April. The owners are hopefully enjoying the commendable, averaged 8.5% overall reduction in kWh for the period. Adjusted kWh/day average was 9% less than 1991.

From the survey results it appears as though the owner of OJ's General Store is not particularly knowledgeable of, or interested in, energy conservation. In spite of this, the averaged data showed a 3% reduction in usage overall and in kWh/day. The kWh data for this period of time showed a fairly consistent usage pattern, compared to all of the other stores, with the largest month to month fluctuation being 8% up or down. An 8% fluctuation for this store represents a usage of only 340 to 460 kWh.

West Topsham recorded reductions of 15, 19, and 22% in January, February, and March respectively. A 6% increase was shown in April and a 3.5% reduction in May. An overall 11% reduction was realized over the monitoring period, 12% in adjusted kWh/day.

For the Duxbury store only the data recorded in February showed an increase in kWh usage. The smallest decrease, 2%, was recorded in May and the largest, 13%, in March. The trend toward reduced kWh usage for this store averaged out to a 5% overall reduction for the period, 6% in daily consumption.

All of the stores, with the exception of O.J.'s and Duxbury, have attached apartments which may have an influence on changes in the overall consumption. It is worth noting that the average temperatures (Appendix 4) during the monitoring period were higher for January and February and slightly lower for March and April compared to the same time period in 1991. Since the temperature was up slightly and overall use down, it could be concluded that the weather had a slight impact. However, with no significant weather variations no direct influence on overall consumption can be identified.

Store Vs. System Peaks

WEC's highest peak loads occur during the winter months of December through March. Looking at all ten stores we can see that, except for Adamant, they tend to use more kWh in the summer. Most stores clearly showed a decrease in consumption during the winter months when the Co-op hits its peaks. No load data are available on the non-participating stores. All ten of the "Mom and Pop" grocery stores in WEC's service territory appear to impact the system since their hours of operation (12 - 16 hours/day seven days/week) include the system on-peak hours.

WEC's is generally an evening peaking system (Appendix 5), with the highest peaks usually recorded between 6 and 7. The only exception occurring during 1991 was a July morning peak. In 1992 both April and May peaked in the morning. The Co-op's peak hours are 6 - 11 am and 5 - 10 pm.

In November of 1991 Hastings and Waits River Stores peaked at the same time as the system peak, though not coincidentally on the same day (Appendix 6). Joe's Pond and Adamant peaked at the same time as the system in March of 1992, but not coincidentally on the same day. In May of 1992 Adamant, Joe's Pond, Hastings, and Walden all peaked in the morning as did the system, but not coincidentally on the same day. Waits River peaked during the evening that month.

Some historic data for the five participating stores were missing from the seven months of data available as noted in the overview (Appendix 7). However, from the data we have it appears that Waits River and Hastings tend to be morning peaking. Walden is clearly a morning peaking store, having no evening peaks during the monitoring period. This store's morning peaks fall within WEC's daily morning peak hours. Joe's Pond and Adamant may be afternoon or evening peaking, the latter being most likely as it does most of its business in late morning through the afternoon. None of the stores' peaks coincided exactly to the day with the system's peaks.

Since data were available only for November 1991 through May of 1992 store peaks can not be compared with WEC's summer peaks. However, since these stores tend to be high users during the summer months it could be concluded that they are summer peaking compared to WEC being winter peaking. Overall, these stores do contribute to the system load, but are not coincidentally peaking with the system.

Four of the participating stores showed kW peak loads within the same range of 12 to 18 (Appendix 8). Adamant Co-op has a smaller load with its peaks no higher than 4 kW. Since the other five stores that did not receive any equipment under this grant all have similar installed loads, it can be assumed that their peak loads would coincide with the four stores noted here.

Looking at kWh on and off-peak (Appendix 9), the trend for all stores is in the range of 30 to 40% on-peak and 60 to 70% off-peak. All five of the participating stores use more kWh off-peak than on-peak, without exception. This is a bit surprising since the normal operating hours for the stores coincides with WEC's daily peak hours, the only off-peak operating hours being 11 am to 5 pm. Lighting is on all day and appliances related to food preparation operate most of the time and certainly during meal times which fall during

peak time. It could also be expected that refrigeration use would be up during store hours. However, since these stores operate seven days a week, weekend off-peak consumption may be higher thus slightly skewing the overall pattern.

The LPR and digital meters were not installed at the participating stores until November of 1991. With no summer data for comparison, it is not possible to compare these stores' kW peaks with the systems' annual peak months. It is recommended that the meters be left in place for one year to obtain long term data.

Although these stores impact the system, it does not appear to be a significant enough impact to pursue load shifting should that become an option for WEC. Operationally, these small stores do not have any deferrable loads.

Store Summaries

Monitoring periods for the stores vary depending upon the dates of equipment installations (Appendix 10) and type of meters installed. Data used in this report are taken from the meters that provide the most accurate picture of use. Actual number of days in monitoring periods are noted where appropriate and vary from store to store.

Appendix 14 contains audit report summaries and recommendations as taken from the VEIC audit reports.

Waits River General Store

This store is located approximately 50 miles southeast of West Danville. It received the most comprehensive energy conservation measures of any of the five stores. The store owner is very conscientious about energy use and was meticulous in logging submeter readings on a weekly basis. The data for this store are accurate and well documented.

Metering consisted of kWh submeters installed on the apartment (house), beer cooler, reach-in display freezer, and walk-in cooler compressors. Meters were installed at the end of December and read and logged weekly. An LPR meter was installed in November. Channel 1 is the master meter, channel 2 reads the reach-in display freezer, and channel 3 reads the apartment. Channels 2 & 3 are redundant with the kWh submeters.

One channel should have been set to read store overhead lighting, or individual fixtures, and the second another end use such as walk-in evaporator fans. For this report, both LPR and kWh submeter data will be used, the latter noted where appropriate.

The house use for the monitoring period (160 days on the kWh submeter and 137 days on the LPR) averaged 12.8 kWh per day. This would extrapolate out to an annual use of 4,508 kWh compared to the 5,274 estimated in the audit, or a difference of 14.5%. It could be assumed that winter consumption may rise and bring the two numbers closer together, but the data from January through March showed no significant variation in the daily kWh consumption. Therefore it is estimated that the actual kWh use for the apartment will be about 10% below the engineering estimate.

The LPR meter showed average kW for the apartment of 1.4 over the 121 days of recorded data. Looking at the apartment kW for just 98 days prior to the store equipment installation, we see an average kW of 1.4. The store (including apartment) overall showed average kW for the pre-installation period of 14. Therefore the apartment represents just 10% of the total load. Comparing kWh consumption, the apartment represents just over 7% of total store consumption.

The display beer cooler compressor, bundled into the new walk-in display, used 607 kWh (kWh submeter) total for an average of 6.7 kWh/day during the monitoring period (91 days) prior to its removal. This would extrapolate to 2,434 kWh/year or 41% less than the engineering estimate of 4,130 kWh/year. However, seasonal sales and warmer weather would probably account for an increase in use during the summer. Daily kWh consumption steadily increased during the 91 days indicating a trend toward higher warm weather usage (see Appendix 6). The calculated duty cycle for this appliance during the monitoring period is 29%. Engineering estimate for an annual duty cycle is 50%. Thus, actual use will most likely approach the engineering estimate.

The old walk-in cooler compressor used 996 kWh during the pre-installation monitoring period of 91 days (kWh submeter). This translates to 3,994 kWh/year or 53% less than the engineering estimate of 8,462. But here also we need to account for a seasonal increase in consumption. Because the cooler was old and deteriorating (during removal it was discovered that the insulation was wet and some framing had rotted) it was leaky and no doubt consumed much more electricity during the summer.

Data showed a 37% increase in consumption over the monitoring period as outside temperatures began to increase. Calculated duty cycle for this cooler during the monitoring period is 28%. Engineering estimate for an annual duty cycle is 60%, thus reinforcing the projected summer increase in kWh consumption which would bring annual consumption closer to the engineering estimate.

The bundling included removal of the beer cooler and two beverage display boxes as well as the old walk-in and combining them in a new walk-in display cooler. The new cooler compressor used 423 kWh during the monitoring period of 28 days. This is 15 kWh/day compared to the old cooler's use of 10.9 kWh/day or a 28% increase in use over the old cooler. Duty cycle for the old walk-in on an annual basis is estimated to be 60%. During the 125 days of monitoring before it was removed it operated at a 28% duty cycle (Appendix 11). During the 28 days of monitoring of the new compressor the duty cycle calculates out at 22%, a drop of 22%. Clearly, although the new compressor is larger, it is more efficient and will result in overall savings compared to the total use for the old appliances that have been bundled into it. The old compressor was rated at 2.3 hp with an R12 coolant system. The new cooler is rated at 3 hp with an R22 coolant system.

The owner noted that even with the normal seasonal increase, beverage sales appear to be higher than last year probably due, he believes, to the better display with the new cooler. The average total kWh/day for the old appliances was 80. The new cooler compressor averaged 15 kWh/day over the 28 days after installation. Data on the evaporator fans (installed with controls) and door heaters was not available. However, even when factoring in these two aspects, the average daily consumption would not be a great deal higher. Length of metering time and time of year are variables that influence this comparison. At best, this indicates that potential savings are considerable and may exceed the engineering estimates.

The reach-in display freezer compressor is a high user. Monitoring over the period of 126 days (kWh submeter) shows 52 kWh/day for a projected annual use of 16,443. The LPR meter shows 49 kWh/day of use over 137 days with an average kW of 2.4. This figure is within about 2% of the engineering estimate of 16,622. The kW load for this appliance is 17% of the total store load. The store owner noted that no increase or decrease in customer use of the unit from summer to winter has been seen and so this estimate of use is reasonable. There may be some increase in summer compressor run time, but the difference in ambient temperature around the box probably is not signifi

cant. The recommended measure for this unit was installation of floating head pressure control, but this was not carried out due to the fact that the technology is new to the northeast as a retrofit.

Overall, the store's total consumption over 108 days of pre-installation monitoring (LPR data) shows total use of 23,800 kWh or an average of 220 kWh/day. Average kW for the same period is 14. Looking at 29 days of data following installation of equipment, the total consumption was 7,112 kWh or 245 kWh/day. This expresses an increase in use of 10%. Average daily kW dropped to 13, a 7.2% drop from pre-installation. When we take an equal number of days from pre- and post-installation and compare the figures we see an 11% drop in kWh consumption for the entire store. A 1,000-watt hot dog steamer was installed on April 24. This unit runs 13 hours per day seven days a week and accounts for 10-13 kWh/day additional consumption (assuming that it is thermostatically controlled). This would account for an increase in consumption for the monitoring period and would negate some of the savings from the new measures. It is noteworthy that the store owner informed us of this addition as he is very conscious of energy use and was aware of the affect of this appliance.

We estimate that consumption will drop substantially during the colder months when the OAE is operating. No estimates for annual savings can be made at this time since the monitoring period does not show any seasonal differences nor is it possible to isolate or predict lighting savings.

Joe's Pond (Moran Enterprises)

Joe's Pond Store is next door to Hastings Store in West Danville. The energy conservation measures installed in this store are nearly identical to those at Hastings: OAE on the walk-in display cooler, evaporator fan and door heater controls on the same unit, store lighting changes to T-8 fluorescent lamps and electronic ballasts, compact fluorescents replacing incandescents, replacement of incandescent flood lights with tungsten halogen bulbs, and replacement of mercury vapor lamps with high pressure sodium. (Appendix 1)

Metering for this store was identical to Hastings with a submeter (kWh meter) on the walk-in compressor and elapsed time indicators on the door heater controls, evaporator fans in the walk-in cooler, and the OAE unit. A digital display meter was installed on the whole store as opposed to an LPR as on Hastings Store.

This store kept an accurate log of compressor submeter readings and so the pre-installation data are accurate on a weekly basis. It should be noted that one of the logged reading dates was changed from February to January. However, this did not coincide with the meter readings and was subsequently changed back by the monitoring and evaluation contractor to the original February reading date.

Prior to installation of the OAE, the compressor was averaging 19.2 kWh/day during the 81 day monitoring period. After installation kWh use totaled 1105 or 14.4/day for the 77 days of monitoring, a 25% reduction. This represents a significant decline in compressor consumption particularly considering the higher average temperatures after installation (see Weather Summary below). Since the elapsed time meter was not installed at the time of equipment installation, no complete consumption (compressor, evaporator fans, and OAE fans) can be calculated.

The duty cycle for the compressor in the engineering report was 40% on an annualized basis. The duty cycle during the 81 day monitoring period (late winter) prior to equipment installation was 57% compared to a 28% engineering estimate for winter duty cycle (Appendix 12). Post-installation duty cycle calculates out to 37% or 35% less than pre-installation. The outside temperature differences between pre and post-installation are fairly significant with higher ambient temperatures after installation. Considering that the OAE unit was operational for a portion of the monitoring period, this reduction in duty cycle is significant in demonstrating the potential savings.

No valid extrapolation can be made from the kWh data because of the variables involved. The pre-installation metering period was during a time when the ambient temperature was below 35° most of the time. The OAE unit was installed at a time when daily temperatures were beginning to fluctuate and included days when, due to relatively warm outside temperatures, it was not operational at all. Also, summer use of the display cooler is higher and so the compressor run time will be higher. A full year's operating data must be collected in order to make any valid estimates on actual savings. Comparison of actual use should be for the same time periods and include accurate temperature data.

It is noteworthy that this walk-in is a site-built unit as opposed to a prefab unit such as at Hastings Store. According to VEIC's engineer, site-built walk-ins can be slightly less efficient than prefab units due to air tightness factors. However, this unit is larger than that at Hastings with

nine doors as opposed to six. Any comparison of energy consumption between the two coolers would not be worthwhile since the estimated compressor duty cycle at Joe's Pond is twice that of Hastings Store.

The OAE elapsed time indicator was not installed at the time the unit was installed. Therefore, no OAE run time data are available for this store. This should be tracked closely, however, since there are several variables in comparing this OAE unit to the one in Hastings Store. This unit is located low to the ground on the southwest side of the store where it will be in direct sunlight during winter. The store owners have made provisions for good drainage and note that wind usually keeps snow clear on this side of the store. The unit at Hastings is located high on a wall in the rear (north) of the store and will not be affected by sunlight, wind, or snow. In fact, the rear of Hastings Store faces a steep embankment and so with snow and ice retention at this location, the ambient temperature will probably be lower than around the Joe's Pond unit.

Elapsed time indicator for the evaporator fans in the Joe's Pond walk-in showed actual use of 346.7 hours over the 76 day monitoring period. This translates to 4.6 hours per day compared to 24 hours per day prior to equipment installation. If we consider the pre-installation duty cycle of 100% (engineering estimates are for 24 hour per day run times) we have a post-installation duty cycle of 19%, a very significant 81% drop (Appendix 12). The run time will increase during the summer months, to be sure, but if we assume that it operates in the range of 50% then annualized savings for this measure may be higher than the engineering estimate of 25%.

The door heater controls at this store operated for a total of .7 hour for the 76 day monitoring period. Because the monitoring period was outside of the summer months, where humidity would tend to be higher causing the door heaters to operate for extended periods of time, this data cannot be extrapolated or interpreted in any meaningful way. Prior to installation, the owner ran the heaters for 24 hours per day over the three warmest months. These door heaters' usage should be tracked for a full year along with humidity readings inside the store. The humidity set point may need to be adjusted up or down depending upon condensation or frost accumulation on the doors during warm weather. If left on year round, the set point may need adjusting again when cooler weather comes in the fall and should be included as part of a regular operating and maintenance schedule. Maximizing savings from this measure will require some tinkering and may mean monitoring for more than a one year period with careful tracking of set point adjustments.

Hastings General Store

This store is located in West Danville next to the Joe's Pond Store. Measures installed were an OAE on the walk-in display cooler, evaporator fan control on the walk-in display cooler, humidity controller for the walk-in display cooler door heaters, lower wattage fluorescent lights in place of primary overhead tubes, compact fluorescent lamps in place of incandescent bulbs, and high pressure sodium lights in place of the outside quartz flood units. (Appendix 1)

Metering for this store included a kWh submeter on the walk-in display cooler compressor, elapsed time indicators on the evaporator fans in the walk-in, door heater controls, and OAE unit, and an LPR meter with channels recording the walk-in compressor and total store.

The early pre-installation data from the kWh meter were logged inaccurately. However, it was possible to obtain two weeks of accurate usage data just prior to equipment installation. The gross data from the 82 days of pre-installation monitoring appear to be accurate since the meter readings just prior to installation were checked for accuracy.

The OAE equipment was installed near the end of the winter season when daily temperatures fluctuated above and below 35°F. Results showed that for 44 days prior to installation of the OAE equipment (LPR data), the average weekly kWh consumption for the compressor only was 13 kWh/day with average weekly temperatures of 12°F. After equipment installation, the weekly average kWh for the metering period of 93 days was 9 kWh/day with average weekly temperatures of approximately 37°. This represents a 31% reduction in kWh consumption. Based upon the metered compressor run time, annual use would be 7,313 kWh, which appears to be just about on target with the engineering estimate of 7,238. However, increased summer run time is not accounted for in the extrapolated estimate. Data from the kWh submeter indicate consumption in excess of 250 kWh/week in the weeks approaching summer and so annual usage will most likely exceed the engineering estimate.

Looking at duty cycle (Appendix 13) for the walk-in compressor, VEIC estimated 21% for winter use. Metered data (from LPR) showed 18% during the 44 day winter monitoring period prior to equipment installation. This represents 15% lower use than estimated. After equipment installation the

duty cycle was 11% reflecting a 39% reduction in duty cycle. Compared to the engineering estimate of 21%, the reduction in duty cycle is 48%. A good part of this reduction must be accounted for by the evaporator fan controls. Our purpose here is only to indicate some potential savings, but no conclusions can be drawn concerning persistence of savings or annual savings. This data will need to be levelized over a full year to include seasonal variations and verify actual savings.

LPR data showed an average of 1.1 kW for 44 days prior to equipment installation. Post-installation data showed 1.4 kW, a 22% increase. However, it should be pointed out again that outdoor temperatures were consistently above 35°F and so the OAE unit was working very little. We can not determine why the kW average is up while kWh average consumption is down during the post-installation monitoring period.

The total kWh consumption for compressor and evaporator fans for 82 days prior to equipment installation was 943 (Appendix 13). After the OAE was installed, total consumption for the compressor, evaporator fans, and OAE fans over 79 days was 481 kWh. The door heater consumption from the monitoring period, .4 kWh, was negligible. This represents a 44% drop in use. Once summer use is factored in actual savings may be close to the engineering estimate of 20%.

The evaporator fans were estimated to run 24 hours per day prior to installation of the controls. After installation, the elapsed time indicator showed daily run times of 4.5 hours per day for the 78 day monitoring period. As with the Joe's Pond Store, pre-installation duty cycle was 100%. Post-installation duty cycle for the period was 34.8%. This showed a reduction of 65.2% in duty cycle. Fan run time will increase over the summer months with higher temperatures and more frequent opening of the cooler doors. If it is assumed that the summer duty cycle will be in the range of 50 - 60%, then actual savings may exceed the engineering estimate of 25%.

The elapsed time meter on the OAE at this store showed a total run time of 262.1 hours over the 94 days after installation. This would give it a duty cycle of 11.6%. Unfortunately, there are no comparison data with the Joe's Pond Store and no baseline data with which to compare this. Once the temperature drops next fall, the run time will increase and over the winter the duty cycle for the OAE fan will increase considerably while compressor run time decreases.

The Hastings Store walk-in display door heater controls ran for one (1) hour during the monitoring period of 76 days. Here also we see that the run time has no significance when compared to the engineering estimate for savings. These door heater controls were estimated to have been on for 24 hours per day for six months from April through September. The monitoring period was clearly not long enough to obtain significant data on the control devices. It should be pointed out that the humidity control for the door heaters may have to be adjusted up or down depending upon their effectiveness and it should be noted in the tracking when an acceptable set point has been reached.

Walden General Store

This store is located a few miles west of the Hastings and Joe's Pond stores in West Danville. Weather and temperature are consistent with the the other stores. Measures installed at this store are an OAE on the walk-in display cooler, evaporator fan cycling controls on the walk-in cooler, T-8 tubes with electronic ballasts in place of the overhead fluorescents lights, and photo cell controls on the outside sign and soffit lights. (Appendix 1).

Submetering for this store was a standard kWh meter installed on the walk-in cooler compressor. It was installed on December 30, 1991. As noted in the Process Evaluation section of this report, this store did not log weekly readings from that meter because they had received the log for another store, they returned it to WEC, and no other log sheet was sent to them. The readings obtained by WEC proved to be questionable and therefore unusable.

In calculating a duty cycle for the compressor based upon the gross kWh readings from the submeter we get a duty cycle before installation of the OAE equipment of just over 100%. Post-installation data showed a duty cycle of over 140%. Since this is impossible, we must conclude that the data are, in fact, unusable.

Post-installation data also showed an average weekly kWh use ranging from 163.5 to over 300 with average daily temperature readings ranging from 15 to 51°F. Comparing this pre and post data shows an increase in compressor kWh use. Engineering estimates predicted a 41% annual reduction in use. The digital meter recording use for the entire store and apartment showed a more than 12% increase in use post-installation. Since the submeter data are invalid and from a period when the OAE was not operative for extended periods, no savings trend or estimate can be predicted.

Lighting data could not be broken out individually from total store consumption as both the OAE and evaporator fan control measures would also account for a percentage of any savings and as noted elsewhere in this report, amp/volt readings on lighting were not possible due to circuit contamination. Lighting changes were made in mid April and therefore not enough post-installation data are available to indicate savings. Use of lights does not vary at this store. Given no changes in operating procedures the savings from lighting improvements should be close to the engineering estimates.

The summary of kWh use as reported by the digital meter on this store (Appendix 3) showed steady increases in consumption during the months of March, April, and May, with a total for these months of 16,462 kWh. The total for the three previous months is 13,341 or 19% less than after the conservation measures were installed. Conversation with the store owner revealed no significant changes in store operations or in the apartment. However, two video games were installed with rated wattage of about 350 each. These games should have amp/volt readings taken to determine their contribution to store consumption. The addition of the games was discovered only after the evaluation contractor contacted the store owners to query the increased consumption. We recommend that annual visits to these stores cover operating and maintenance schedules and a discussion of how store owners can maximize energy savings while not sacrificing income enhancing operations. In this instance, the video games could be placed on timers so that power is shut off to them when the store is closed.

As noted under the section on Historic Data, this store showed several monthly increases in consumption for 1992 over 1991. As noted in Appendix 5 the monthly use also fluctuates and thus makes it difficult to predict savings or increases in use. Combined with the unusable submeter data, no reasons for this store's increase in consumption can be determined.

ADAMANT

This small cooperative located just outside Montpelier had only lighting measures installed. No special metering was put in place other than a digital whole-store meter.

The historic data showed an almost 10% decrease in kWh consumption between similar billing periods in 1991 and 1992. Since the lighting measures were installed in mid April, only a few weeks of post-installation history is available. Engineering predictions are that the new lighting will save approximately 2.16 kWh per day. If no other changes are made at this store over the next year, historic data should show the actual savings.

LIGHTING

As far as outdoor lighting measures are concerned, there is no way to verify predicted savings since the monitoring period spanned standard time and daylight savings. It was not possible on any of the stores to isolate or break out actual savings from these measures due to contamination by savings from other measures and the inability to obtain clean amp/volt readings. Also, since the measures were not installed until mid April, only a few weeks of actual use is covered by the billing data and less than two months by metered data.

WEATHER

Since the OAE equipment was installed in mid March, the weather was changing from winter to spring with daily temperatures fluctuating above and below 35°F, the point below which the OAE units start operation.

Because of this, the units did not run often enough to demonstrate potential savings. Temperatures are noted in Appendix 4, but it is clear from the data available that the weather had little affect on this evaluation other than the normal warming temperature trend during this time of year and that it allowed for little OAE operation. Since the equipment needs a full year of monitoring, temperatures will play a more significant role during the coldest months.

Humidity levels will need to be tracked inside those stores that have door heater controls. This would prove useful not only in verifying on times, but might prove useful in control adjustment for maximum efficiency.

General weather conditions, such as sunny versus cloudy days, will prove useful over the winter in comparing the OAE units at Hastings and Joe's Pond stores. As noted above, the location of the units at each store may have some influence on run times.

CONCLUSIONS & RECOMMENDATIONS

Overall the data showed potential savings for OAE and evaporator fan controls. The door heater controls did not show any savings as of the completion of data gathering for this report. Lighting will most likely show savings as predicted given that the duty cycles do not change significantly.

As noted throughout this report, E&SWC recommends monitoring the participating stores for a period of one full year. The OAE, door heater controls, and evaporator fan controls are all affected by seasonal changes and a year's profile will provide accurate savings data. The door heater controls will be affected by humidity levels inside the stores and will need adjusting over the course of the year to obtain optimum levels of performance without allowing condensation or frost on the doors. The same may be true of the evaporator fan controls. Should there be frost build-up on the coils, the controls will have to be adjusted for longer fan run time.

General

- It is recommended that one of the stores in West Danville, either Hastings or Joe's Pond, unplug the door heaters at the time they usually did before the controls were installed. This will eliminate the possibility of higher consumption should the humidity set point not be adjusted to avoid on-time when historically they were disconnected. After the year's monitoring, the store may choose to leave them plugged in all year and adjust the controls seasonally. By following this procedure an accurate picture of actual savings will be possible without operational changes that may affect consumption over the same period. The two stores can be compared to determine whether any further savings are possible by maintaining the procedure of disconnection at the end of the summer. The elapsed time meters at both stores will provide accurate data with which to make this evaluation.

It is recommended that WEC track humidity readings both outside and inside the two West Danville stores. This variable may verify fluctuations in run time and serve as a comparison between winter and summer levels. Monitoring humidity levels over a full year may help determine that the actual run time for door heaters is longer than actually needed and would provide useful information in determining the set point for the controls.

- During the winter when the average ambient outside temperature remains below 35°F we recommend that one or more of the stores with OAE measures have a flip-flop comparison done on run time. Each unit could be carefully monitored for a one to two week period with the OAE measure operating and using the elapsed time meters for exact data. The equipment can then be turned off for an equivalent period of time and the results compared using daily temperatures as a variable. This procedure would also indicate exact increases in compressor run time as a function of the OAE disconnection.

This same type of comparison could be accomplished during the summer on the door heater controls. The variable would be monitoring of indoor and outdoor humidity during the period.

Metering

- Since lighting measure savings could not be accurately determined, an inexpensive data logger (if no other means is available) should be used to track actual on-time over a set time period of one to two weeks, for example. This could be done on each store with lighting measures installed and would not involve an extraordinary amount of time or resources. Returning to each store during standard time periods in mid winter for a similar monitoring period would provide useful data for estimating annual consumption.

- To help avoid the take-back effect we recommend that WEC visit each store once or twice annually with recommendations and reminders for a regular operation and maintenance schedule in order to assure persistence of savings. It is an issue with store owners that income enhancing operations/equipment not be affected by conservation efforts. WEC should work with this audience to maximize energy savings without interfering with income producing operations. As an example, the Walden store owners could install timers on the video games so that they draw no power during hours when the store is closed. These games represent an idling load that is not necessary when the store is closed.

- It is recommended that the following changes for accurate and economical monitoring of equipment be done over the next year:

1. Install kWh submeters or elapsed time meters (or change one channel on an LPR) on lighting only at Hastings and Waits River stores. It is understood that there are problems in isolating the lighting, but it may be possible to isolate a percentage of the lights or even an individual unit in order to obtain accurate consumption data. The data can be compared to engineering estimates of pre-installation use and predicted savings.
 2. Dedicate one LPR channel at the Waits River Store to the evaporator fan controls. Channels 2 and 3 are redundant with the kWh submeters currently in place on the apartment and large display freezer.
 3. WEC purchase or borrow an inexpensive data logger such as the Rustrak Ranger II. This is a versatile instrument and can be used for a wide variety of metering and data logging functions. For purposes of this program, we recommend using it for readings on such equipment as the video games, hot dog steamer, and other equipment that was installed after the conservation measures were put in place. The logger can be set up to monitor any piece of equipment with a variety of outputs and thus would provide very detailed information on any equipment directly affecting this program's results. Specifically, WEC could get a profile of kW on each significant end use and thus obtain a more accurate load profile on any or all stores.
- For future consideration, WEC should consider a comparison of two stores with door heaters, one store with air conditioning and no heater controls and one without air conditioning and heater controls in place. There may be some differences in the usefulness of door heater controls if a store is air conditioned and has lower humidity levels during the summer than a non-air conditioned store. Air conditioning may be a variable that affects the cost effectiveness of door heater controls.

**DATE
FILMED**

2 / 9 / 93