MAY 22 1997
Station 34

21

ENGINEERING DATA TRANSMITTAL

Page 1 of 1
1. EDT 616479

2. To: (Receiving Organization) BUILDING 324		3. From: (Originating Organization) BUILDING 324 PROJECTS		4. Related EDT No.:	
5. Proj./Prog./Dept./Div.: B CELL CLEANOUT PROJECT		6. Design Authority/ Design Agent/Cog. Engr.: JM TANKE		7. Purchase Order No.:	
8. Originator Remarks: QAPP for B Cell Cleanout Project. (Non-Engineering EDT)				9. Equip./Component No.:	
				10. System/Bldg./Facility: Building 324	
				12. Major Assm. Dwg. No.:	
11. Receiver Remarks: 11A. Design Baseline Document? ☐ Yes ☒ No				13. Permit/Permit Application No.:	
				14. Required Response Date:	

15. DATA TRANSMITTED					(F)	(G)	(H)	(I)
(A) Item No.	(B) Document/Drawing No.	(C) Sheet No.	(D) Rev. No.	(E) Title or Description of Data Transmitted	Approval Designator	Reason for Transmittal	Originator Disposition	Receiver Disposition
1	HNF-SD-SPJ-QAPP-004		0	B Cell Cleanout Project Quality Assurance Program Plan	ESQ	1		

16. KEY					
Approval Designator (F)		Reason for Transmittal (G)		Disposition (H) & (I)	
E, S, Q, D or N/A (see WHC-CM-3-5, Sec.12.7)		1. Approval 2. Release 3. Information		4. Review 5. Post-Review 6. Dist. (Receipt Acknow. Required)	
				1. Approved 2. Approved w/comment 3. Disapproved w/comment	
				4. Reviewed no/comment 5. Reviewed w/comment 6. Receipt acknowledged	

17. SIGNATURE/DISTRIBUTION (See Approval Designator for required signatures)											
(G) Reason	(H) Disp.	(J) Name	(K) Signature	(L) Date	(M) MSIN	(G) Reason	(H) Disp.	(J) Name	(K) Signature	(L) Date	(M) MSIN
		Design Authority				1	1	JM Tanke		5/14/97	LS-65
		Design Agent				1	1	JM Steffen		5/14/97	N1-47
		Cog. Eng. J.M. Tanke (See right column)				1	1	PJ Weaver		5/14/97	LI-02
		Cog. Mgr. P.J. Weaver (See right column)				1	1	GO Hayner		5/14/97	LS-65
1	1	QA - DG Farwick		5/13/97		R3-56					
1	1	Safety - AH Horner		5/12/97							
1	1	Env. - DE Rasmussen		5/12/97		LI-03					

18. P.J. Weaver Signature of EDT Originator 5/14/97		19. MS Wright Authorized Representative Date for Receiving Organization 5/12/97		20. P.J. Weaver Design Authority/ Cognizant Manager 5/14/97		21. DOE APPROVAL (if required) Ctrl. No. ☐ Approved ☐ Approved w/comments ☐ Disapproved w/comments	
---	--	--	--	--	--	---	--

Quality Assurance Program Plan for 324 Building B Cell Safety Cleanout Project (BCCP)

J. M. Tanke
B&W Hanford Company, Richland, WA 99352
U.S. Department of Energy Contract DE-AC06-96RL13200

EDT/ECN: 616479 UC: 2050
Org Code: 19200 Charge Code: K4022
B&R Code: EX3120020 Total Pages: 14

Key Words: QAPP, B Cell, Cleanout, BCCP

Abstract: This QAPP implements the Quality Assurance Program Plan for the 324 Building B Cell Safety Cleanout Project.

TRADEMARK DISCLAIMER. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors.

Printed in the United States of America. To obtain copies of this document, contact: Document Control Services, P.O. Box 950, Mailstop H6-08, Richland WA 99352, Phone (509) 372-2420; Fax (509) 376-4989.

Karen J. Noland
Release Approval

5/22/97
Date

Release Stamp

Approved for Public Release

324 BUILDING B-CELL SAFETY CLEANOUT PROJECT
QUALITY ASSURANCE PROGRAM PLAN

TABLE OF CONTENTS

1.0 PURPOSE	2
2.0 SCOPE	2
3.0 GENERAL	3
4.0 QUALITY ASSURANCE CRITERIA	3
4.1 MANAGEMENT - Program	3
4.2 MANAGEMENT - Personnel Training and Qualification	4
4.3 MANAGEMENT - Quality Improvement	4
4.4 MANAGEMENT - Documents and Records	5
4.5 PERFORMANCE - Work Processes	6
4.6 PERFORMANCE - Design	7
4.7 PERFORMANCE - Procurement	7
4.8 PERFORMANCE - Inspection and Acceptance Testing	8
4.9 ASSESSMENT - Management Assessment	9
4.10 ASSESSMENT - Independent Assessment	9

LIST OF TABLES

Table 1 Quality Assurance Program Index	11-13
---	-------

324 BUILDING B-CELL SAFETY CLEANOUT PROJECT QUALITY ASSURANCE PROGRAM PLAN

1.0 PURPOSE

This Quality Assurance Program Plan (QAPP) provides information on how the Quality Assurance Program is implemented for the 324 Building B-Cell Safety Cleanout Project (BCCP). This QAPP is responsive to the Westinghouse Hanford Company Quality Assurance Program and Implementation Plan, WHC-SP-1131, for 10 CFR 830.120, "Nuclear Safety Management, Quality Assurance Requirements"; and DOE Order 5700.6C, "Quality Assurance". This QAPP supersedes PNNL PNL-MA-70 QAP "Quality Assurance Plan No. WTC-050 Rev. 2", issue date May 3, 1996.

2.0 SCOPE

This QAPP has been developed specifically for the BCCP. It applies to those items and tasks which affect the completion of activities identified in the work breakdown structure of the Project Management Plan (PMP). These activities include all aspects of decontaminating B-Cell and project related operations within the 324 Building as it relates to the specific activities of this project. General facility activities (i.e. 324 Building Operations) are covered in the Building 324 QAPP. In addition, this QAPP supports the related quality assurance activities addressed in CM-2-14, Hazardous Material Packaging and Shipping, and HSRCM-1, Hanford Site Radiological Control Manual.

The 324 Building is currently transitioning from being a Pacific Northwest National Laboratory (PNNL) managed facility to a B&W Hanford Company (BWHC) managed facility. During this transition process existing, PNNL procedures and documents will be utilized until replaced by BWHC procedures and documents. These documents conform to the requirements found in PNL-MA-70, Quality Assurance Manual and PNL-MA-81, Hazardous Materials Shipping Manual.

The Quality Assurance Program Index (QAPI) contained in Table 1 provides a matrix which shows how project activities relate to 10 CFR 830.120 and 5700.6C criteria. Quality Assurance program requirements will be addressed separate from the requirements specified in this document. Other Hanford Site organizations/companies may be utilized in support of this project and the subject organizations are to implement applicable Quality Assurance requirements consistent with this QAPP.

324 BUILDING B-CELL SAFETY CLEANOUT PROJECT
QUALITY ASSURANCE PROGRAM PLAN

3.0 GENERAL

Quality assurance requirements are to be applied to specific items within each of the major activities identified in the work breakdown structure. These specific items have been identified in the "Applicability" section of each requirement.

4.0 QUALITY ASSURANCE CRITERIA

4.1 MANAGEMENT - Program

4.1.1 Requirement

A written Quality Assurance Program (QAP) shall be developed, implemented, and maintained. The QAP shall describe the organizational structure, functional responsibilities, levels of authority, and interfaces for those managing, performing, and assessing the work. The QAP shall describe management processes, including planning, scheduling, and resource considerations.

4.1.2 Implementation

The site QAP is described in WHC-SP-1131 and is based on 10 CFR 830.120. The QAP provides methods and procedures to verify compliance with quality requirements. This QAPP implements the QAP for work activities affecting completion of the BCCP consistent with the scope of this project. Project-specific procedures are to be used to implement quality requirements when established standards and site procedures do not provide sufficient direction.

The project manager has overall responsibility for compliance with the QA program. Project personnel at all levels are responsible for planning, implementing and assessing programs for design, construction, and operation of systems controlling project activities.

Various site contractors and subcontractors are involved in the activities associated with this project. The PMP identifies the project participants and their responsibilities and interfaces. Additional responsibilities or new activities not described in the PMP are to be defined and detail provided in specific plans and procedures or use the requirements provided herein.

4.1.3 Applicability

This QAPP provides overall guidance and quality requirements for the project. The development of other project-specific quality assurance project plans is not required.

324 BUILDING B-CELL SAFETY CLEANOUT PROJECT QUALITY ASSURANCE PROGRAM PLAN

4.2 MANAGEMENT - Personnel Training and Qualification

4.2.1 Requirement

Personnel shall be trained and qualified to ensure they are capable of performing their assigned work. Personnel shall be provided continuing training to ensure that job proficiency is maintained.

4.2.2 Implementation

The training tracking system(s) provide management with a method to ensure that personnel qualifications are current. Personnel performing normal operational tasks (i.e. operating the hot cell equipment) are required to meet the training requirements usually associated with that work. Records documenting this training are to be maintained and be available for review by project management.

Organizations performing special project-specific tasks/processes are to define and/or provide personnel training and qualification in these processes. These personnel are to be qualified prior to performing these tasks. Records documenting the training are to be maintained by personnel designated in the applicable qualification procedures.

4.2.3 Applicability

Personnel are to be trained and qualified for the following tasks.

- Operation of size reduction equipment
- Operation of decontamination equipment
- Loading material into containers
- Loading containers into casks

4.3 MANAGEMENT - Quality Improvement

4.3.1 Requirement

Processes to detect and prevent quality problems shall be established and implemented. Items, services, and processes that do not meet established requirements shall be identified, controlled, and corrected according to the importance of the problem and the work affected. Correction shall include identifying the causes of problems and working to prevent recurrence. Item characteristics, process implementation, and other quality-related information shall be reviewed and the data analyzed to identify items, services, and processes needing improvement.

**324 BUILDING B-CELL SAFETY CLEANOUT PROJECT
QUALITY ASSURANCE PROGRAM PLAN**

4.3.2 Implementation

Direct observation and review of ongoing work, tests, completed work, or modifications is to be conducted to detect and prevent errors and problems. Nonconformance, Surveillance and Occurrence Reports are also to be used to reveal conditions adverse to project quality requirements. Procedures are to provide a systematic means for obtaining commitments for corrective action from responsible management and for follow-up to verify the completion and effectiveness of the action. When adverse conditions are identified emphasis is to be placed on implementation of corrective action to prevent recurrence, not just remedial action which only corrects the specific deficiency.

4.3.3 Applicability

Existing nonconformance and corrective action management systems are to be used. Nonconformance reports and corrective actions will be tracked on the Hanford Action Tracking System (HATS). The development of new project-specific system is not required.

4.4 MANAGEMENT - Documents and Records

4.4.1 Requirement

Documents shall be prepared, reviewed, approved, issued, used, and revised to prescribe processes, specify requirements, or establish design. Records shall be specified, prepared, reviewed, approved, and maintained.

4.4.2 Implementation

All documents that are used to perform administrative, design, construction, inspection, testing, operating, and maintenance activities are to be prepared, issued, and changed in accordance with approved procedures.

Records that are used to document the performance of administrative, design, construction, inspection, testing, operating, and maintenance activities are to be prepared, reviewed, approved and changed in accordance with approved procedures.

Existing document and records management systems are to be used. The development of a new project-specific system is not required.

324 BUILDING B-CELL SAFETY CLEANOUT PROJECT
QUALITY ASSURANCE PROGRAM PLAN

4.4.3 Applicability

Document and records control is required, as appropriate, for the following anticipated activities.

- Surveillance reports
- Inspection and testing reports
- Shipping, handling and storage documentation/procedures
- Work & test plan(s)/procedures

4.5 PERFORMANCE - Work Processes

4.5.1 Requirement

Work shall be performed to established technical standards and administrative controls using approved instructions, procedures, or other appropriate means. Items shall be identified and controlled to ensure their proper use. Items shall be maintained to prevent their damage, loss, or deterioration. Equipment used for process monitoring or data collection shall be calibrated and maintained.

4.5.2 Implementation

Policies and procedures are to be established to ensure that the quality of the work being performed is in compliance with applicable standards, regulations, and codes. The level of detail of work instructions is to be consistent with the items' complexity and the consequence of failure.

Packaging, handling, shipping, and storage of materials and equipment is to be done by qualified project and support personnel. Items are to be controlled to prevent damage or loss and to provide adequate safety of personnel involved.

Existing work control systems are to be used. The development of new project-specific work control systems are not required, however, project-specific work documents are to be developed and utilized as necessary.

4.5.3 Applicability

Work process controls are required, as appropriate, for the following activities.

- Operational testing of hot cell equipment
- Loading material into containers
- Transport of containers

324 BUILDING B-CELL SAFETY CLEANOUT PROJECT QUALITY ASSURANCE PROGRAM PLAN

4.6 PERFORMANCE - Design

4.6.1 Requirement

Items and processes shall be designed using sound engineering/scientific principles and appropriate standards. Design work, including changes, shall incorporate applicable requirements and design bases. Design interfaces shall be identified and controlled. The adequacy of design products shall be verified or validated by individuals or groups other than those who performed the work. Verification and validation work shall be completed before approval and implementation of the design.

4.6.2 Implementation

Design control requirements for the project are implemented through site manuals and procedures. No project-specific documents/procedures are required. Qualified project and support personnel are to initiate and support design activities in accordance with site manuals and procedures.

4.6.3 Applicability

Design control is required, as a minimum, for the following activities.

- Container design
- Design of special equipment/processes

4.7 PERFORMANCE - Procurement

4.7.1 Requirement

Procured items and services shall meet established requirements and perform as specified. Prospective suppliers shall be evaluated and selected on the basis of specified criteria. Processes to ensure that approved suppliers continue to provide acceptable items and services shall be established and implemented.

4.7.2 Implementation

Procurement requirements are implemented through site manuals and procedures. Project-specific documents/procedures apply to control of material after receipt on site. Personnel assigned to support the project are to initiate and support procurement activities in accordance with site manuals.

324 BUILDING B-CELL SAFETY CLEANOUT PROJECT

QUALITY ASSURANCE PROGRAM PLAN

Procurement requisitions are to be reviewed to assure that appropriate quality assurance requirements and procurement clauses are specified. These clauses include control of purchased items, supplier performance, evaluation, acceptance of the item or service, supplier audits, and records confirming that specified requirements are obtained.

4.7.3 Applicability

Procurement control is required, as appropriate, for the following activities.

No special procurement is anticipated

4.8 PERFORMANCE - Inspection and Acceptance Testing

4.8.1 Requirement

Inspection and testing of specified items, services, and processes shall be conducted using established acceptance and performance criteria. Equipment used for inspections and tests shall be calibrated and maintained.

4.8.2 Implementation

Inspections of ongoing work, completed work, or modifications are to be conducted by qualified/certified project and support personnel. Inspection for acceptance is to be performed by qualified inspection personnel. Inspections are to be performed in accordance with inspection criteria included in work plans and related documents.

4.8.3 Applicability

Inspection and acceptance testing is required, as appropriate, for the following activities.

Inspection of containers

Transportation activities

Inspection of containers prior to transport

324 BUILDING B-CELL SAFETY CLEANOUT PROJECT QUALITY ASSURANCE PROGRAM PLAN

4.9 ASSESSMENT - Management Assessment

4.9.1 Requirement

Managers shall assess their management processes. Problems that hinder the organization from achieving its objectives shall be identified and corrected.

4.9.2 Implementation

Project Management is to regularly assess the adequacy of management systems and processes to ensure effective implementation. These assessments are to include the participation of project management and project team personnel. Team members are to take responsibility for their work and critically assess their efforts to determine if they have met their task objectives. Management is to identify problems and barriers that hinder the project from achieving project objectives. Project Management is to determine what response actions are appropriate, and implement corrective actions based on the impact of the assessment results on safety and project deliverables.

4.9.3 Applicability

Due to the transition from PNNL to BWHC procedures management assessments will be scheduled. Senior management will determine the scope of the assessments for the project. In addition, assessment of activities will be a part of project status meetings and carried out as a part of inspection and testing.

4.10 ASSESSMENT - Independent Assessment

4.10.1 Requirement

Independent assessments shall be planned and conducted to measure item and service quality, to measure the adequacy of work performance, and to promote improvement. The group performing independent assessments shall have sufficient authority and freedom from the line to carry out its responsibilities. Persons conducting independent assessments shall be technically qualified and knowledgeable in the areas assessed.

4.10.2 Implementation

Planned and scheduled independent assessments are to be performance based and performed to measure item and service quality, the adequacy of work performance, compliance

324 BUILDING B-CELL SAFETY CLEANOUT PROJECT
QUALITY ASSURANCE PROGRAM PLAN

with all aspects of the Quality Assurance Program and to determine its effectiveness, and to promote improvement.

4.10.3 Applicability

Due to the short duration of this project it is not anticipated that any formal independent assessments will be scheduled or performed on the project. An independent assessment of the Facility is scheduled for October 1997 and will provide overall assessment of operations that include the B-Cell Cleanout Project.

HNF-SD-SPJ-QAPP-004**Rev. 0****324 BUILDING B-CELL SAFETY CLEANOUT PROJECT
QUALITY ASSURANCE PROGRAM PLAN**

Table 1 Quality Assurance Program Index

(Page 1 of 3)

10CFR 830.120/ SP-1131 QA CRITERIA SECTIONS	SITE WIDE (HNF Manuals)		B-CELL CLEANOUT PROJECT
	QA POLICY AND IMPLEMENTING DOCUMENTS CM-4-2	Others (Used when applicable)	
(1) MANAGEMENT			
(1)(I) Program	QR 1.0, QR 2.0 QI 2.1, QI 2.2	CM-1, CM-1-3 CM-1-5, CM-2-14 CM-3-5, CM-4-46 CM-6-1, CM-6-2 CM-7-5, EP-0063	Building 324 QAPP, 4.1.3 of this QAPP
(1)(ii) Personnel Training and Qualification	QR 2.0, QI 2.6 QR 9.0, QR 10.0	CM-2-14, CM-2-15 CM-4-5, CM-4-39 CM-7-5, EP-0063 IP-1184	Building 324 QAPP, 4.2.3 of this QAPP
(1)(iii) Quality Improvement	QR 15.0, QI 15.1 QI 15.2, QI 15.6 QR 16.0, QI 16.1	CM-1-3, CM-1-4 CM-1-5, CM-6-1 CM-6-2, CM-7-5	Building 324 QAPP, 4.3.3 of this QAPP
(1)(iv) Documents and Records	QR 6.0, QR 17.0 QI 17.1, QI 17.2 QR 19.0	CM-1-3, CM-2-14 CM-2-15, CM-3-4 CM-3-5, CM-3-8 CM-3-10, CM-4-5 CM-6-1, CM-6-2 CM-7-5, CM-8-7 EP-0063	Building 324 QAPP, 4.4.3 of this QAPP

324 BUILDING B-CELL SAFETY CLEANOUT PROJECT QUALITY ASSURANCE PROGRAM PLAN

Table 1. Quality Assurance Program Index
(Page 2 of 3)

10CFR 830.120/ WHC-SP-1131 QA CRITERIA SECTIONS	SITE WIDE		B-CELL CLEANOUT PROJECT
	QA POLICY & IMPLEMENTATION DOCUMENTS CM-4-2	Others (Used when applicable)	
(2) PERFORMANCE			
(2)(I) Work Processes	QR 5.0, QR 8.0 QR 9.0, QI 9.1 QI 9.2, QR 11.0 QR 12.0, QI 12.2 QI 12.3, QI 12.4 QI 12.5, QI 12.6 QI 12.7, QR 13.0 QI 13.3, QI 13.4 QR 14.0, QI 14.1 QR 19.0	CM-1-3, CM-1-5 CM-1-8, CM-1-10 CM-2-1, CM-2-2 CM-2-3, CM-2-4 CM-2-14, CM-3-5 CM-4-5, CM-4-38 CM-4-39, CM-4-41, CM-5-4 CM-5-16, CM-6-1 CM-6-2, CM-6-10 CM-7-7, CM-8-7 DOE-RL-92-36 HSRCM-1	Building 324 QAPP, 4.5.3 of this QAPP
(2)(ii) Design	QR 3.0, QR 5.0 QR 19.0	CM-1-3, CM-1-8 CM-2-14, CM-3-5 CM-3-10, CM-4-5 CM-4-46, CM-6-1 CM-6-2, EP-0063	Building 324 QAPP, 4.6.3 of this QAPP
(2)(iii) Procurement	QR 4.0, QI 4.1 QR 7.0, QI 7.1 QI 7.2, QI 7.3 QI 7.6, QR 15.0, QR 15.6	CM-1-3, CM-2-1 CM-2-2, CM-2-3 CM-3-5, CM-4-5 CM-6-1, CM-6-2	Building 324 QAPP, 4.7.3 of this QAPP
9(2)(iv) Inspection and Acceptance Testing	QI 7.4, QR 10.0, QI 10.2 QR 11.0, QR 12.0 QI 12.2, QI 12.3 QI 12.4, QI 12.5 QI 12.6, QI 12.7 QR 14.0, QR 19.0	CM-1-3, CM-1-4 CM-1-8, CM-2-14 CM-3-5, CM-4-5 CM-4-41, CM-5-4 CM-6-1, CM-6-2 EP-0063	Building 324 QAPP, 4.8.3 of this QAPP

HNF-SD-SPJ-QAPP-004

Rev. 0

**324 BUILDING B-CELL SAFETY CLEANOUT PROJECT
QUALITY ASSURANCE PROGRAM PLAN**

10CFR 830.120/ WHC-SP-1131 QA CRITERIA SECTIONS	SITE WIDE		B-CELL CLEANOUT PROJECT
	QA POLICY & IMPLEMENTATION DOCUMENTS CM-4-2	Others (Used when applicable)	
(3) ASSESSMENT			
(3)(I) Management Assessment	QR 16.0, QI 16.1	CM-1-3, CM-1-4 CM-1-5, CM-4-5 CM-7-5	Building 324 QAPP, 4.9.3 of this QAPP
(3)(ii) Independent Assessment	QR 18.0, QI 18.1	CM-1-3, CM-1-4 CM-4-5, CM-4-6 CM-6-1, CM-6-2 CM-7-5	Building 324 QAPP, 4.10.3 of this QAPP