DOE/PC/92530--T2

DOE/PC/92530--T2

DE93 012566

Bed Material Agglomeration During
Fluidized Bed Combustion

Technical Progress Report for the Period
Sept. 30, 1992 - Dec. 31, 1992

Robert C. Brown, M. Robert Dawson, and Shawn Noble

Iowa State University
Ames, IA 50011

Work Performed Under Grant
No. DE-FG22-92PC92530

Date Transmitted: February, 1993

Prepared for: U.S. Department of Energy
Pittsburgh Energy Technology Center
Pittsburgh, PA

Project Monitor: Wu Lan

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

MASTER

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

Bed Material Agglomeration During Fluidized Bed Combustion

Technical Progress Report

Sept. 30, 1992 - Dec. 31, 1992

Robert C. Brown and M. Robert Dawson
Iowa State University Ames, IA 50011

Abstract

This project started during the month of September 1992 of the fourth quarter of FY 1991-92. During the first month a NEPA report was prepared and submitted to DOE as required by the grant and graduate student was selected to perform work for this project. The first quarter of FY 1992-93 focused on preparing and conducting a survey of fluidized bed combustor operators and modifying the laboratory scale fluidized bed combustor located at Iowa State University, Ames, Iowa.

Objective

The purpose of this project is to determine the physical and chemical reactions which led to the undesired agglomeration of bed material during fluidized bed combustion and to relate these reactions to specific causes.

Progress

Task 1:

A survey of industrial-scale fluidized bed combustors is being conducted to determine the occurrence of bed agglomeration and the circumstances under which agglomeration took place. This task should be finished by the end of February. Samples of bed material, agglomerate material, and boiler deposits are being requested from boiler operators as part of the survey. Once received, these samples will be analyzed to determine chemical and mineralogic composition. The bulk chemical determination will be performed using x-ray fluorescence (XRF) and inductively coupled plasma-optical emission (ICP). Mineralogy will be determined by x-ray diffraction (XRD). Chemical and mineral reactions will be determined by scanning electron microscopy, optical microscopy, and electron microprobe.

Task 2:

The goal of this task is to modify the combustor to simulate the hydrodynamic and chemical conditions found in the dense phase regions of circulating and bubbling fluidized bed combustors. Control of the fluidization regime in the reactor required the addition of pressure taps and

transducers. During this quarter, a pressure measurement system was added to the laboratory fluidized bed combustor. A differential pressure transducer connected to a data acquisition program was designed and is being installed. With these modifications, agglomerate growth can be related to differential pressure fluctuations within the bed.

Three pressure taps were placed in the bed and spaced a nominal two inches apart in a vertical plane. The taps are constructed of stainless steel and have screens placed on the tips to prevent bed materials from filling the taps and for thermal considerations. Once the taps were installed, the range necessary for the pressure transducer was determined by connecting a pressure gage across two adjacent pressure taps and the outer pressure taps and taking readings as the flow rate of primary air was increased. The differential pressure across adjacent taps was 2.5 inches of water column and across the outer pressure taps it was 5.0 inches of water column. The differential pressures were independent of primary air flow rate. With these experimental results, it was decided that the differential pressure transducer required should be capable of a measurement of 0-5 inches of water column.

The differential pressure transducer selected for the project was ordered from Davis Instruments. This transducer measures 0-5 inches of differential water column to 1% full scale accuracy. The transducer is being connected to two adjacent pressure taps and wired into the computer data acquisition program.

Some of the planned experiments include substoichiometric combustion conditions. Combustion at this condition is known to produce tar in the exhaust gases. Tar deposits can damage exhaust gas analyzers. Accordingly, a tar trap was built and installed to protect the analyzers. This trap was constructed of PVC pipe packed with fiberglass. Exhaust gases from the combustor enter the trap and the tar is entrained and adheres to the fiberglass. The outlet of the trap is connected to the gas analyzers. With this assembly, fiberglass can be replaced when it becomes saturated with tar.

An additional modification involves replacement of LP gas with natural gas for combustor start-up. The use of LP gas requires frequent tank refilling and presents a greater explosion hazard than natural gas in the enclosed environment of the laboratory. The natural gas line in the laboratory delivered gas at too low of a pressure to be directly piped into the plenum of the fluidized bed. We made attempts to alleviate this problem by using a venturi to introduce the natural gas into the plenum. These attempts were unsuccessful. The gas lines are currently being replaced to provide a pressure of 8 psig. This work has been approved and is in the process.

Future Work

Work for the next quarter includes completion of combustor modifications to monitor pressure fluctuations. Coal samples for combustion experiments will be prepared. For the initial set of experiments we intend to use Illinois No. 6 coal. Additional samples of coal will be solicited as described in Task 3 of our project proposal. A test matrix will be completed and preliminary testing of changes in combustion parameters will begin.

Appendix A

Telephone Survey of Fluidized Bed Combustors for agglomeration Problems

Ask to speak to the Facilities Engineer, be certain to record his name, phone number, and title.

1. (Introduction) Hello, my name is _____ and I'm in the Department of Mechanical Engineering at Iowa State University. Our research group is studying relationships between pressure and temperature fluctuations and bed quality in fluidized bed combustors. Specifically we are trying to determine: (1) if agglomeration of bed particles is a problem and (2) if poor bed quality produces inconsistent performance of the boiler and poses a problem. What we are doing now is trying to get some feeling from fluidized bed operators to see if bed quality is actually causing any day to day problems in boiler operation, so we are doing an informal survey of FBC operators and engineers. Could I ask you some questions regarding your own person experiences with fluidized bed combustors?

Just as a brief background about our experiences, we have been working with Iowa and Illinois coals in laboratory-scale fluidized combustors and have found that bed particles can agglomeration, or "stick together", even when bed temperature are below ash fusion temperatures, when certain conditions exist in the bed. What we are doing at this point is trying to determine to what extent agglomeration and temperature and pressure fluctuations have been a problem in commercial-scale combustors.

2. (Questions, pressure fluctuations) Have they ever had experiences with pressure fluctuations during operation? If so could you relate these fluctuations any specific cause? (e.g., temperature, alkali elements in the fuel, low-rank fuels).
3. (Problems with large particles) Have they ever experienced problems with large particles in the bed?
- 3A. If there are occurrences of larger bed particles: Are any particles larger than the feed size of the coal? Do they think any of the particles in the bed formed by smaller particles sticking together? Are the larger particles friable, meaning can they easily break into smaller particles?

4. (Deposit formation) Have there been experiences of deposit formation? (Near coal feed locations, on side walls, in cyclone, or in the return loop of a circulating fluidized bed boiler.

- 4A. If problems, then what fuel is being used? What is the ash content of fuel? If biomass, is the fuel briquetted before it is sent to the boiler and what species of biomass fuel is used?

5. (If anything looks interesting...) In a very nice way, ask if it would be possible to get a representative sample of boiler deposits, agglomerates, bed or cooler ash, and a sample of the feed and sorbent if any. Is a coal analysis available?

6. Do they have any suggestions for monitors that would improve the operation of the combustor. (Feed composition, bed height, bed quality)

7. Give your name and phone number so they may contact you in the future with further comments.

NAME: _____
TITLE: _____
FACILITY: _____
PHONE: _____

2.

TEMPERATURE: ☐ yes ☐ no

COMMENTS:

ALKALI ELEMENTS: ☐ yes ☐ no

COMMENTS:

LOW-RANK FUELS: ☐ yes ☐ no

COMMENTS:

3.

LARGE PARTICLES PROBLEMS: ☐ yes ☐ no

COMMENTS:

3A.

LARGER THAN FEED SIZE: ☐ yes ☐ no

COMMENTS:

FORMATION BY STICKING: ☐ yes ☐ no

COMMENTS:

FRIABLE: ☐ yes ☐ no

COMMENTS:

4.

DEPOSIT FORMATION: ☐ yes ☐ no

coal feed: ☐ yes ☐ no

side walls: ☐ yes ☐ no

cyclone: ☐ yes ☐ no

return loop: ☐ yes ☐ no

COMMENTS:

4A.

FUEL:

ASH CONTENT:

IF BIOMASS

BRIQUETTING: ☐ *yes* ☐ *no*

BIOMASS SPECIES:

5.

SAMPLES:

BOILER DEPOSITS: ☐ *yes* ☐ *no*

BED/COOLER ASH: ☐ *yes* ☐ *no*

FEED AND SORBENT: ☐ *yes* ☐ *no*

COAL ANALYSIS: ☐ *yes* ☐ *no*

6.

COMMENTS:

END

**DATE
FILMED**

6 / 1 / 93