NOTICE

**CERTAIN DATA
CONTAINED IN THIS
DOCUMENT MAY BE
DIFFICULT TO READ
IN MICROFICHE
PRODUCTS.**

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

ORNL/RAP/Sub--86-72139/2

DE93 000502

PRELIMINARY GEOHYDROLOGIC SITE CHARACTERIZATION AND PROPOSED WATER QUALITY WELL LOCATIONS FOR WAG 7, WAG 8 AND WAG 9

Daniel C. Baughn

NOTICE

This report contains information of a preliminary nature and was prepared primarily for internal use at the originating installation. It is subject to revision or correction and therefore does not represent a final report. It is passed to the recipient in confidence and should not be abstracted or further disclosed without the approval of the originating installation or USDOE Office of Scientific and Technical Information, Oak Ridge, TN 37830.

September, 1987

Report Prepared by:
MCI Consulting Engineers, Inc.
10628 Dutchtown Road
P. O. Box 23010
Knoxville, Tennessee 37933-1010

under
Subcontract No. 30X-72139C

for the
ENERGY DIVISION
Oak Ridge National Laboratory
Oak Ridge, Tennessee 37831
operated by
Martin Marietta Energy Systems, Inc.
for the
U.S. DEPARTMENT OF ENERGY
under Contract No. DE-AC05-84OR21400

MASTER

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

jsu

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendations, or favoring by the United States Government or any agency thereof. The view and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

SECRET

TABLE OF CONTENTS

	<u>PAGE</u>
List of Figures	vi
List of Tables	viii
List of Appendices	ix
Abstract	x
1.0 Introduction	1
2.0 Technical Approach	4
2.1 General Geology	5
2.1.1 Melton Valley Geology	5
2.1.2 Haw Ridge Geology	7
2.1.3 Bethel Valley Geology	8
2.2 Generalized Conceptual Groundwater Models	9
2.2.1 Melton Valley	9
2.2.2 Haw Ridge	12
2.2.3 Bethel Valley	13
3.0 Waste Area Grouping 7	16
3.1 Site Location, Description and Background	16
3.1.1 The Pits and Trenches	18
3.1.1a Pit 1	18
3.1.1b Pit 2	19
3.1.1c Pit 3	21
3.1.1d Pit 4	21
3.1.1e Trench 5	23
3.1.1f Trench 6	23
3.1.1g Trench 7	26
3.1.2 ILLW Lines and Leak Sites	27
3.1.2a ILLW Line Leak Site	28
3.1.2b Leak Site Southeast of Trench 6	28
3.1.2c Access Road Leak Site at the End of Trench 7	29
3.1.3 Other Inactive Facilities	30
3.1.3a Decontamination Facility - Building 7819	30
3.1.3b Homogeneous Reactor Experiment (HRE) Fuel Wells	30
3.1.3c Hydrofracture Experimental Site 1 - Soil Contamination	32
3.1.3d The Shielded Transfer Tanks	33
3.2 Topography	34

TABLE OF CONTENTS - cont'd

	<u>PAGE</u>
3.3 Soils	34
3.4 Geology	38
3.5 Surface Hydrology	44
3.6 Groundwater	46
3.6.1 Existing Groundwater Monitoring System	46
3.6.2 Groundwater Quality	49
3.6.3 Hydrology	54
3.7 Data Gaps and Recommendations	60
3.7.1 Data Gaps	60
3.7.2 Recommendations	60
4.0 Waste Area Grouping 8	65
4.1 Site Location, Description and Background	65
4.1.1 HIFR/TRU Waste Collection Basins	67
4.1.1a Basin 7905	69
4.1.1b Basin 7906	69
4.1.1c Basin 7907	71
4.1.1d Basin 7908	74
4.1.2 LLW Line and Leak Sites	74
4.1.2a The Melton Valley Transfer Line	76
4.1.2b Melton Valley Drive Leak Site	77
4.1.2c Melton Valley Drive and SWSA 5 Access Road Leak Site	77
4.1.2d 7500 Area Leak Site	79
4.1.2e Leak Site West of Melton Valley Pumping Station	80
4.1.2f Building 7920 and Melton Valley Pumping Station Area Leak Sites	80
4.1.2g Building 7920 Ditch Line Leak Site	80
4.1.3 Active LLW Tanks	84
4.1.3a LLW Collection and Storage Tank (WC-20)	84
4.1.3b LLW Collection/Storage Tank (HIFR)	84
4.1.3c LLW Collection/Storage Tanks (T-1, T-2)	85
4.1.4 Other Facilities	85
4.1.4a Hydrofracture Experimental Site 2, Soil Contamination	85
4.1.4b Hazardous Waste Storage Facility 7507 ...	88
4.1.4c Mixed Waste Storage Pad 7507W	88
4.1.4d Sewage Treatment Plant (7904)	89
4.1.4e Silver Recovery Process	90

TABLE OF CONTENTS - cont'd

	<u>PAGE</u>
4.2 Topography	90
4.3 Soils	92
4.4 Geology	98
4.5 Surface Hydrology	103
4.6 Groundwater	104
4.6.1 Existing Groundwater Monitoring System	104
4.6.2 Groundwater Quality	106
4.6.3 Hydrology	108
4.7 Data Gaps and Recommendations	116
4.7.1 Data Gaps	116
4.7.2 Recommendations	118
5.0 Waste Area Grouping 9	121
5.1 Site Location, Description and Background	121
5.1.1 HRT Pond	125
5.1.2 LLW Collection and Storage Tanks (7560, 7562)	126
5.1.3 Septic Tank (7501)	128
5.2 Topography	129
5.3 Soils	129
5.4 Geology	135
5.5 Surface Hydrology	135
5.6 Groundwater	137
5.6.1 Existing Groundwater Monitoring System	137
5.6.2 Groundwater Quality	139
5.6.3 Hydrology	145
5.7 Data Gaps and Recommendations	148
5.7.1 Data Gaps	148
5.7.2 Recommendations	149

LIST OF FIGURES

<u>FIGURE NUMBER</u>	<u>TITLE</u>	<u>PAGE</u>
1-1	General Site Location Map	2
1-2	Relationship of Study Areas To Other WAGs	3
2-1	General Site Geologic Map	6
3-1	WAG 7 Solid Waste Management Units	17
3-2	WAG 7 Pumping Test, Pit 4 Aug. 31 - Sept. 10, 1955	24
3-3	WAG 7 Typical Waste Disposal Trench	25
3-4	WAG 7 Shielded Transfer Tank Model II	35
3-5	WAG 7 Shielded Transfer Tank Model III	36
3-6	WAG 7 Geologic Structure Four Acre Site	40
3-7	WAG 7 Geologic Structure Road Cut East Of Trench 7	41
3-8	WAG 7 Geologic Map	42
3-9	WAG 7 Wells In The Vicinity Of The Waste Pit Disposal Area	47
3-10	WAG 7 Wells In The Vicinity Of Trench 7	48
3-11	WAG 7 Phreatic Surface Map.....	55
3-12	WAG 7 Potentiometric Map For The Vicinity of Trench 7	57
3-13	WAG 7 Water Table Contour Map - January 10, 1958, Vicinity Of Pits 2, 3 & 4	58
3-14	WAG 7 Seep Location Map For The Pits and Trenches Area	59
3-15	WAG 7 Proposed Water Quality Well Locations	62

LIST OF FIGURES - cont'd

<u>FIGURE NUMBER</u>	<u>TITLE</u>	<u>PAGE</u>
4-1	WAG 8 Solid Waste Management Units	66
4-2	WAG 8 Schematic Of The 7900 Area Process Waste System	68
4-3	WAG 8 Location of LLW Collection/ Storage Tanks T-1 and T-2	86
4-4	WAG 8 RCRA Monitoring Well Borehole Locations	94
4-5	WAG 8 Fence Diagram And Drill Logs For The 7900 Area RCRA Monitoring Wells	95
4-6	WAG 8 Drill Log For RCRA Monitoring Well 32004	96
4-7	WAG 8 Geologic Map	99
4-8	WAG 8 Piezometer Locations And Phreatic Surface Map	105
4-9	WAG 8 Phreatic Surface Map Enlargement	110
4-10	WAG 8 Phreatic Surface RCRA Well Data	111
4-11	WAG 8/SWSA 1 Phreatic Surface Map	117
4-12	WAG 8 Proposed Water Quality Well Locations	119
5-1	WAG 9 Solid Waste Management Units	122
5-2	WAG 9 Shallow Soil Sampling Locations	131
5-3	WAG 9 Deep Soil Sampling Locations	133
5-4	WAG 9 Geologic Map	136
5-5	WAG 9 Location Of Driven Wells	138
5-6	WAG 9 Phreatic Surface Map	141
5-7	WAG 9 Phreatic Surface Map 1985 Water Level Data	147
5-8	WAG 9 Proposed Water Quality Well Locations	150

LIST OF TABLES

<u>TABLE NUMBER</u>	<u>TITLE</u>	<u>PAGE</u>
3-1	Field Determined kd Values For Silt Samples Collected From Wells T7-3 And T7-13	38
3-2	Radionuclide Activity Ranges In Stream Sediments	45
3-3	Elemental Concentrations And Radionuclide Values In Nine Wells At The Pits And Trenches Area	51
3-4	Average Groundwater Composition (1981-1982) For Wells Near Trench 7	53
4-1	WAG 8 Maximum Metal And Pesticide Concentrations In EP Toxicity Extracts From Basin 7905 Sediments	70
4-2	WAG 8 Maximum Metal and Pesticide Concentrations In EP Toxicity Extracts From Basin 7906 Sediments	72
4-3	WAG 8 Maximum Metal and Pesticide Concentrations In EP Toxicity Extracts From Basin 7907 Sediments	73
4-4	WAG 8 Maximum Metal and Pesticide Concentrations In EP Toxicity Extracts From Basin 7908 Sediments	75
4-5	WAG 8 Average kd Values	98
4-6	WAG 8 Water Quality Data For Seven Wells In The HFIR Area	107
4-7	WAG 8 Water Level Data	108
4-8	WAG 8 Hydraulic Conductivity Values	113
4-9	WAG 8 WAG 8/SWSA 1 Water Level Data	115
5-1	WAG 9 Radionuclide Concentrations Of Contaminated Soil Samples From 0-12 Inches ..	132
5-2	WAG 9 Radionuclide Concentrations In Deep Soil Samples	134
5-3	WAG 9 Summary Of HRT Pond Monitoring Well Construction Details	140
5-4	WAG 9 Groundwater Quality - Four Wells At The HRT Pond	143

LIST OF APPENDICES

1. Appendix I Example of Piezometer
Drill Log And Construction
Schematic
2. Appendix II Water Quality Well Construction
Schematics
3. Appendix III Proposed Water Quality Well Design
Criteria, Design Coordinates And
Estimated Completion Depths
4. Appendix IV Partial Inventory Of Preremedial
Action Program Wells - WAG 7
5. Appendix V Bibliography

ABSTRACT

The Oak Ridge National Laboratory (ORNL) site began operations in 1943. The facility had a planned operating life of 1 year which was later extended by 2 - 3 years, and ultimately, ORNL became a permanent nuclear research facility. From its inception, the facility has utilized its vast acreage and relative isolation for subsurface storage/disposal of both solid and radioactively contaminated wastes. During the site's early operating history, the environmental risks posed by subsurface waste disposal were not clearly understood. Today, it is recognized that waste constituents may be mobilized when ground water comes in contact with abandoned disposal sites. In view of this, the ORNL Environmental Restoration and Facilities Upgrade program has identified the need for an extensive water quality well network. The wells will gather water quality data around groups of solid waste management units that are collectively termed Waste Area Groupings (WAGs).

This document recommends a total of twenty-nine water quality well locations distributed among Waste Area Groupings (WAGs) 7, 8, and 9. For WAG 7, sixteen water quality wells are recommended. Supplementary groundwater data may be available from existing hydrostatic head well clusters, at two locations within the WAG 7 boundary. For WAG 8, nine water quality wells are recommended. Supplementary data from within the WAG boundary are available from eight existing water quality wells that were installed around the HFIR/TRU Waste Collection Basins. For WAG 9, four water quality wells are recommended. Supplementary water quality data from within the WAG boundary are available from four wells that monitor the inactive HRT Pond.

1.0 Introduction

The purpose of this report, the second in a series, is to assess general site conditions and to recommend water quality well locations at three Waste Area Groupings (WAGs) within the Oak Ridge National Laboratory (ORNL) complex. The subject sites are WAGs 7, 8 and 9 each of which is identified on the general site location map included as Figure 1-1. For reference, the relationship of the subject sites to other WAGs are shown on Figure 1-2. WAGs are regions prescribed by Martin Marietta throughout the ORNL complex that require environmental assessment. WAGs contain solid waste management units such as Solid Waste Storage Areas (SWSAs), as well as pipelines, spill sites, buildings, ponds and experimental test sites. These solid waste management units are considered to be potential sources of contamination. The WAG boundaries describe the areal limits of specific waste management operations as well as currently known areas of waste constituent migration.

Because solid waste management units within WAGs 7, 8 and 9 may continue to release waste constituents to the environment, the existing groundwater monitoring systems is being upgraded. This report recommends locations for water quality wells which will be installed at these three WAG boundaries in order to gather water quality data. The proposed well locations are shown in Figures 3-15, 4-12, and 5-8. Water quality well design coordinates (ORNL grid) and estimated completion depths are given in Appendix III.

FIGURE 1-1
GENERAL SITE LOCATION MAP
 STUDY AREAS-WAGS 7, 8 AND 9
 TAKEN FROM BETHEL VALLEY, TN. U.S.G.S. QUAD. 130 NE, 1968
 SCALE: 1"=2000'

MCI/CONSULTING ENGINEERS, INC.
 NASHVILLE KNOXVILLE HUNTSVILLE LOUISVILLE

FIGURE 1-2 RELATIONSHIP OF STUDY AREAS TO OTHER WAGS

TAKEN FROM BETHEL VALLEY, TN. U.S.G.S. QUAD. 130 NE, 1968
SCALE: 1" = 2000'

MCI/CONSULTING ENGINEERS, INC.
NASHVILLE KNOXVILLE HUNTSVILLE LOUISVILLE

2.0 Technical Approach

As the second report in a series, this document borrows heavily on the format and, where appropriate, the descriptive language used in the first report. The focus of this report is on water quality well site selection based upon geology and hydrology. Many of the terms and concepts are explained in the text; however, the report is intended for use by geologists and engineers and assumes a fundamental understanding of hydrogeology on the part of the reader.

The report's level of detail varies significantly from section to section and this reflects the availability of information during the report's preparation, as well as the historical nature of the subject sites.

The technical approach used in designing the proposed water quality well system included a review of site history, consideration of site specific geology, evaluation of available groundwater data and preparation of general conceptual models for groundwater occurrence and movement (Section 2.2). The models are presented as a basis for forming an understanding of shallow groundwater flow in Melton Valley, Bethel Valley and Haw Ridge. Although they are only qualitative models, they are founded in the basic tenets of geology and hydrology; as such, the models may represent a reasonable approximation of the area's geohydrology.

The well design criteria were provided by Martin Marietta Energy Systems, Inc. and reflect the possibility that some of these wells may be used to gather data for RCRA monitoring.

With the exception of geologic structure descriptors, the directional references used throughout the text of this report are taken from ORNL grid north which is 34°12'51" west of true north.

2.1 General Geology

2.1.1 Melton Valley Geology

WAGs 7, 9 and the majority of 8^{*} are located in Melton Valley, which is underlain by the Conasauga Group (See Figure 2-1, by W.M. McMaster - 1958). Three separate phases have been identified in the Conasauga Group in eastern Tennessee; a northwestern phase, a central phase, and a southeastern phase (Rodgers - 1953). The central phase occurs beneath the Oak Ridge Reservation (Haase - 1985), and it is composed of six formations. These formations are (from oldest to youngest) the Pumpkin Valley shale, the Rutledge limestone, the Rogersville shale, the Maryville limestone, the Nolichucky shale and the Maynardville limestone.

Within the project area the geologic structure in the Conasauga appears to be consistent with the regional structure with the strata striking about 56° northeast and dipping about 30° to 40° southeast (Webster - 1976). Approximately 1,300 feet north of WAG 7 and about 1,600 feet north of WAG 9 and the majority of WAG 8, is the trace of the Copper Creek fault. The Copper Creek is one of the major thrust faults in the area, obliquely traversing almost all of eastern Tennessee from near the Georgia line and into Virginia. Fault blocks of this type are believed to be relatively thin (a few thousand feet thick), and to have been sheared along an

* A portion of WAG 8 extends north over Haw Ridge and terminates in Bethel Valley. Haw Ridge and Bethel Valley are underlain by the Rome Formation and the Chickamauga limestone, respectively.

FIGURE 2-1 GENERAL SITE GEOLOGIC MAP

TAKEN FROM THE GEOLOGIC MAP OF THE
OAK RIDGE AREA GEOLOGY BY W.M.
McMASTER U.S. GEOLOGICAL SURVEY, 1958
SCALE: 1"=2640'

—LEGEND—

CHICKAMAUGA LIMESTONE	Och
KNOX GROUP	Ock
CONASAUGA GROUP	Cc
ROME FORMATION	Er
GEOLOGIC CONTACT	- - - -
COPPER CREEK FAULT	- - - -

MCI/CONSULTING ENGINEERS, INC.
NASHVILLE KNOXVILLE HUNTSVILLE LOUISVILLE

incompetent zone and then displaced horizontally. Each fault block has overridden other strata as it was displaced to the northwest; the dip of the fault plane is commonly greatest near the surface, decreasing with depth. The forces necessary to create a structure of the magnitude of the Copper Creek fault also commonly overcame the internal integrity of weaker strata (i.e., shale) within the thrust block. Fractures, folds and complex imbricate structures are exhibited a considerable distance from the trace of the thrust fault.

Weathering of the Conasauga is aided by the moist climate of the Oak Ridge area where precipitation typically exceeds 50 inches per year. The abundant rainfall increases erosion as well as chemical processes that leach soluble constituents from the rock. Weathering and erosion of the Conasauga Group produces an irregular top of rock surface geometry; local deviations are dependent on variations in geochemical composition, stress history and past exposure to weathering agents. The siltstone strata of the Conasauga are more resistant to weathering than the shale (Stockdale - 1951) and typically form low chains of hills.

2.1.2 Haw Ridge Geology

A portion of WAG 8 extends across Haw Ridge which is underlain by the Rome Formation (W.M. McMaster - 1958/Figure 2-1). The Rome comprises a variety of lithologies; in order of decreasing abundance they are: sandstone, shale, siltstone and carbonate. These rock types are commonly interbedded and individual strata are frequently of limited lateral extent. On the Oak Ridge Reservation, C.S. Haase, et al. - 1985, has divided the Rome into upper and lower portions, primarily on the basis of structure. A more detailed discussion of Haase's work is given in Section 4.4.

The Rome formation underlying Haw Ridge is the lowermost rock unit in the Copper Creek thrust block. Some of the general features of large scale thrust blocks have been described in Section 2.1.1. For the most part the Rome's structure conforms to regional strike and dip, although portions nearer the fault zone tend to be highly deformed and may exhibit a wide variety of structures.

The various lithologies of the Rome formation exhibit differing weathering rates, although as a whole the Rome is relatively resistant and it is expressed topographically as an extended linear ridgeline. The sandstone and siltstone strata of the Rome, being more resistant to weathering than the shale and carbonate lithologies commonly give these ridges an irregular or knobby appearance. The soil and bedrock interface may be irregular but the soil is generally less than eight feet in depth. In many areas, weathered bedrock is exposed at the ground surface.

2.1.3 Bethel Valley Geology

The northernmost portion of WAG 8 is located in Bethel Valley which the geologic map of the Oak Ridge area (W.M. McMaster, 1958/ Figure 2-1) indicates is underlain by the Chickamauga group. The Chickamauga has been defined as the sequence of gray limestones and red mudstones overlying the Cambro-Ordovician dolostones of the Beekmantown and Knox Groups (Kenneth R. Walker, 1985). Within the Oak Ridge Reservation, Stockdale (1951) subdivided the Chickamauga into eight mappable units. The units are designated A through H in ascending order in the stratigraphic column. Lithological descriptions of the units pertinent to WAG 8 are given in Section 4.4.

The Chickamauga Group underlying Bethel Valley is within the White Oak Mountain thrust block. The strata of the Chickamauga generally conform to the regional strike of about 56° northeast and exhibit a moderate dip of 30° to 40° southeast (Webster, 1976). Deformation of the uppermost unit of the Chickamauga (the unit underlying the northern portion of WAG 8) should probably be associated with past movement of the Copper Creek thrust block as it overrode the White Oak Mountain thrust block.

Weathering of the Chickamauga limestone is abetted by the humid climate of East Tennessee where heavy precipitation promotes physical erosion and chemical weathering of the rock units. The Chickamauga, being predominantly a carbonate unit, is subject to solution. The result is an irregular bedrock surface that contains solutionally enlarged features (joints and bedding planes). In general, the purer the limestone the greater is the tendency for solution activity. The Chickamauga contains some relatively pure limestone sequences, but overall it is moderately silty and argillaceous, factors which may impede the chemical weathering of these strata.

2.2 Generalized Conceptual Groundwater Model

2.2.1 Melton Valley Groundwater Model

The occurrence and movement of groundwater in the Conasauga can be broken into two unique regimes (Webster - 1976); a residuum system and a bedrock system. Though considered herein as separate entities, the two regimes are believed to be hydraulically connected by a transition zone consisting of several feet of variably weathered rock.

The residuum is composed primarily of unconsolidated clay and silt with some isolated bedrock fragments; it has a primary permeability consisting of interconnected, intergranular voids. The residuum's secondary permeability consists of relict geologic structures (such as fractures) retained by the residuum after the bedrock has weathered as well as voids left after roots and other organic materials have decayed. The primary system's greater total volume of interconnected void space probably represents the majority of the residuum's storage capacity. However, the role of the storage capacity in the hydrologic system is largely dependent on the storage media. For example, coarse grained sediments typically exhibit high specific yields while fine grained clays and silts, such as are found in the Conasauga's residuum, typically exhibit low yields (i.e., have high specific retention). Therefore, groundwater stored in these finer grained sediments may only be available for evapotranspiration.

The bedrock aquifer is thought to consist primarily of interbedded shales, siltstones and limestones that apparently have no primary permeability. The secondary permeability consists of fractures that both cut across and are coincident with bedding plane partings the latter which develop as the result of preferential weathering and of strata unloading (overburden relief). At depth, the openings along these fractures are thought to be restricted because of greater overburden pressure.

Fractures also form an important part of the secondary permeability system. The Conasauga, having a significant shale component, is not a structurally competent unit and is subject to both ductile and brittle deformation. For example, when this type of lithology is compressed horizontally it may

form a fold, buckling normal to the direction of applied force. As the fold is propagated, longitudinal tension fractures form around the external radius of the fold hinge. Longitudinal shear fractures form around the internal radius of the fold hinge and along bedding laminae in the limbs of the fold.

These three types of fractures, as well as the bedding plane fractures described earlier, are typically oriented approximately parallel to geologic strike. Also of significance is the down dip orientation of the bedding plane fractures. Another component of the bedrock's secondary permeability system (which can be predicted from basic structure principles) is a set of orthogonal fractures, oriented about 45 degrees to the direction of principal force. Presuming that the principal tectonic force acted from southeast to northwest, then these fractures should cut across the strike-oriented fracture system described earlier and provide a greater degree of interconnection within the bedrock aquifer. Other fracture systems may also occur; however, those described above can be reasonably predicted. The overall result may resemble an irregular and incomplete lattice-like secondary permeability system composed of relatively short but interconnected fractures. The Conasauga Group contains several limestone intervals that may exhibit some of the characteristics of carbonate aquifers. However, the more significant aspect of the secondary permeability system may be the shale intervals' influence on deformation styles.

The depth of fresh water circulation is unknown. In an earlier study of selected core holes (Stockdale - 1951) it was suggested that the sandstones of the Rome formation and the presumably tightly cemented gouge of the Copper Creek fault

were impervious and acted as barriers to groundwater movement. According to this hypothesis, the base of the Pumpkin Valley shale would be the effective lower limit of the Melton Valley bedrock aquifer. However, this conclusion cannot be corroborated without additional field study and subsequent analysis.

Generally, it can be presumed that groundwater within the ORNL area flows from the potentiometric highs on ridge crests to the potentiometric lows on valley floors and that the surface water system (White Oak Creek and its tributaries) serves as a constant head discharge boundary.

Phreatic surface contour maps can be constructed for interpreting the general groundwater flow direction. However, these maps rely on assumptions that must be taken into account in some hydrologic systems. For example, in ridge and valley terrain, the streams on valley floors may serve as groundwater discharge areas. Shallow wells completed on the valley floor will exhibit less hydrostatic head than a deep well. If this aspect is not taken into account when preparing a potentiometric surface contour map, the shallow well will appear as an isolated low in the water table. Flow diagrams must also reflect variations in hydraulic conductivity with flow direction (anisotropy), as well as variations at different points within the aquifer (heterogeneity). If an aquifer is anisotropic and heterogeneous, such as when flow is fracture controlled, then groundwater flow may not be normal to the potentiometric isopleths.

2.2.2 Haw Ridge Groundwater Model

Most groundwater studies at ORNL have focused on the Conasauga shale and the Chickamauga limestone. There is an absence of

hydrologic literature and data for the Rome formation. In view of this, the conceptual groundwater model for the Rome is limited to a few basic elements.

The Rome's residuum is thin, typically less than eight feet in depth. A residuum groundwater system is presumed to be absent; although if such a system is present it would probably function similarly to the system described for the Conasauga's residuum. The Rome formation has been extensively deformed and probably has some capacity for recharge by way of its secondary permeability. The recharge from Haw Ridge is conceptualized as a lens of fresh water extending to some unspecified depth below the base elevation of the ridge. As was noted earlier in Section 2.2.1, P.B. Stockdale's 1951 study of core holes led him to the conclusion that the sandstones of the Rome and the gouge of the Copper Creek fault were impediments to groundwater movement. Whether the Rome behaves as a recharge zone or an aquitard will have to be determined by additional field work and analysis.

2.2.3 Bethel Valley Ground Water Model

There are fundamental differences in the geology underlying Melton Valley, Haw Ridge and Bethel Valley, consequently the differences in the groundwater flow regime at the soil-bedrock interface require the development of a separate model for Bethel Valley. Like the models for Melton Valley and Haw Ridge, this hypothesis utilizes basic geologic and hydrologic principles to form a basis for conceptualizing shallow ground water movement and occurrence. Like the Melton Valley model, this hypothesis separates the ground water regime into residuum and bedrock systems, realizing of course that the two systems are hydraulically connected.

The conceptual model for the Chickamauga's residuum groundwater system is similar to that described for the Conasauga with the following additional descriptors. Relatively rapid vertical infiltration of meteoric waters is thought to take place at shallow depths. After moving through this upper zone of relatively higher permeability, vadose water may begin to move laterally but at a slower rate. The weathered upper surface of the more carbonate beds of the Chickamauga probably exhibit a decrease in hydraulic conductivity when compared to the hydraulic conductivity of the residuum. The decrease in hydraulic conductivity coupled with differences in local hydraulic gradients and wide spatial distribution of secondary openings in the bedrock may produce discrete lateral flow zones at the soil and bedrock interface. However, this zone may be altogether absent where there is a high degree of hydraulic connection between the residuum and bedrock groundwater regimes.

The bedrock aquifer is composed primarily of limestone containing clay and shale partings, but there are also interbeds of calcareous siltstone and shale. These lithologies generally have tightly bonded matrixes and insignificant intergranular permeability. However, a moderately well-developed secondary permeability system provides for significant transmission of groundwater within the bedrock. Principles of structural geology are useful in predicting the types of features that form the secondary permeability system. The limestone portions of the Chickamauga are not as flexible as the adjacent shale units. When stressed, these limestone units of the Chickamauga are likely to behave in a brittle manner, and develop fractures. Because the Chickamauga forms the footwall of the Copper Creek fault in this terrane it is reasonable to expect the occurrence of orthogonal fracture sets oriented about 45° to

the direction of principal force. In response to tensional forces created by unloading, bedding planes exposed at the upper bedrock surface part to form the beginnings of down-dip flowpaths subject to solutional enlargement. Stockdale's 1951 geologic report on the Bethel Valley Chickamauga strike belt describes the terrane's bedding as monotonous and uniform in dip. While there may be significant structural features in the Chickamauga, fractures sets and bedding plane partings are believed to be the most common. These features are subject to continuing chemical weathering and corrasion resulting in the formation of discrete solution channels within the bedrock.

During the formation of fracture controlled and stratigraphically controlled solution channels, the rate of weathering is accelerated as the cross-sectional area of the solution channel increases (A.N. Palmer, et al., 1982). As the cross-sectional area increases and turbulent flow conditions become dominant, the effects of corrasion become an important mechanism for channel enlargement. This action may result in a few solution channels becoming dominant as they carry increasingly larger volumes of water. In view of the above, the general morphology of the Chickamauga's secondary permeability system may include a relatively few large solution openings fed by a system of fractures and smaller solution channels. The secondary permeability system should have high hydraulic conductivity along strike and down dip, resulting from solution within a particular stratum or along bedding planes. Hydraulic conductivity across bedding and oblique to dip may be less since it is dependent on solution of fractures that cross lithologies having variable rates of weathering.

3.0 Waste Area Grouping 7

3.1 Site Location, Description and Background

WAG 7 is located in Melton Valley and consists of approximately 116 acres (Figure 3-1) which is predominantly woodland. The subject area is irregularly shaped and is bounded to the south, southwest and southeast by White Oak Lake and the floodplain of White Oak Creek (WAG 2). To the east the site is bordered by uplands which drain towards White Oak Creek, and to the northeast Solid Waste Storage Area (SWSA) 4 adjoins the site. Lagoon Road parallels the northern limit of the site which lies on the footslopes of Haw Ridge. On its western flank the subject site is adjoined by WAG 2 and the head of a north-south draw which drains toward White Oak Lake.

WAG 7 contains 18 solid waste management units which are divided into the following three groups.

I. The Pits and Trenches

- a) Pit 1
- b) Pit 2
- c) Pit 3
- d) Pit 4
- e) Trench 5
- f) Trench 6
- g) Trench 7

II. ILLW Lines and Leak Sites

- a) ILLW Line Leak Site
- b) Leak Site Southeast of Trench 6
- c) Access Road Leak Site at the End of Trench 7

APPROXIMATE LOCATION OF
SHIELDED TRANSFER TANKS
ST1, ST2, ST3, ST4 AND ST5

+

N19000

+

E25000

TRUE GRID NORTH

NORTH

34°12'51"

INJEC

AL
AL

BUIL

STR/L

POW

MAF

SEC

CON

5 FE

LOCATION OF HRE FUEL
WELLS S-1 THROUGH S-7

WAG 7
BOUNDARY

CTURE
ELL HEAD

JRE

E27000

E28000

DECONTAMINATION
BUILDING 7819

WAG 7
BOUNDARY

WAG 7 SOLID WASTE MANAGEMENT UNITS

SCALE: 1" = 200'

—LEGEND—

7819

BUILDING

STREAM

POWER POLE

MARSHY AREA

SECONDARY ROAD

CONTOUR INTERVALS 800
FEET

APPROXIMATE LOCATION OF
MANAGEMENT UNITS

NOTES:

1. TOPOGRAPHY DIGITIZED FROM A BASE
MAP PREPARED BY ACCU-AIR SURVEYS,
INC. SEYMOR, INDIANA-WHITE OAK
CREEK WATERSHED MAP SERIES,
PHOTO DATE 3/29/78, MSL DATUM 1929.
2. TOPOGRAPHIC AND SITE SPECIFIC
INFORMATION PROVIDED BY MARTIN
MARIETTA ENERGY SYSTEMS, INC.

E29000

WAG 7
BOUNDARY

III. Other Inactive Facilities

- a) Decontamination Facility - Building 7819
- b) Homogeneous Reactor Experiment (HRE) Fuel Wells
- c) Hydrofracture Experimental Site 1 -
Soil Contamination
- d) Shielded Transfer Tanks ST 1, ST 2, ST 3, ST 4 and
ST 5

The locations of these solid waste management units are shown in Figure 3-1.

3.1.1 The Pits and Trenches

During the period from 1951 through 1966 ORNL disposed of Intermediate Level Liquid Wastes (ILLW) by means of shallow seepage pits and trenches (C.R. Olsen, et al. - 1983). The liquid wastes were generated as part of the routine plant operations and were stored and treated with a caustic precipitant in gunite tanks located in the main plant area.

Initially these wastes were hauled from the gunite tanks to the pits in a tank truck but later were piped to the pits and trenches after construction of the ILLW lines in 1954 (B.P. Spalding - 1987). The pits were open-topped earthen impoundments and were numbered 1, 2, 3 and 4. The trenches were long, narrow trackhoe excavations that were backfilled with crushed stone and covered with an earthen cap. Wastes were delivered throughout the trenches via an internal system of feeder pipes. The numbering sequence used for the pits was carried over to the trenches which are designated 5, 6 and 7.

3.1.1a Pit 1

Pit 1 was constructed just west of SWSA 4 and south of Lagoon Road in July of 1951. The pit was about 100 feet long by 20

feet wide by 15 feet deep and had a capacity of about 180,000 gallons (B.P. Spalding - 1987). Pit 1 was excavated into the residual soils and weathered bedrock of the Conasauga Group and was built without a liner. This type of construction was consistent with engineering practices of the day and reflected the prevailing opinion (now known to be incorrect) that the Conasauga Group was an impermeable rock formation.

About 123,000 gallons of liquid waste were placed in the pit during its period of operation. The waste reportedly had a pH of about 12.5; ^{137}Cs and ^{106}Ru were its principal radionuclide constituents, although operating records indicate that 196 kg of uranium and 266 mg of plutonium were also disposed of in Pit 1 (B.P. Spalding - 1987). In October of 1951 the pit was closed to ILLW disposal after a ruthenium contaminated seep was discovered. However, Pit 1 did receive additional waste in the form of drain discharge from Decontamination Building 7819. This latter waste disposal practice began in 1962 and continued at least until 1964, but may have continued until as recently as 1981. The nature and duration of the decontamination buildings' discharges are not clearly documented, but the total amount of activity from this source is thought to be low because the decontamination procedures did not require the shielding associated with higher activity materials.

Pit 1 was filled with Conasauga shale and a sloping asphalt cap was placed over it in 1981. Presently the site is fenced and appropriately posted to prevent unauthorized entry.

3.1.1b Pit 2

Pit 2 is located on a hill about 1,400 feet south of Pit 1. It was constructed in 1952 and had dimensions of 200 feet by 100 feet by 15 feet deep; it had sloping sides and a flat base

(B.P. Spalding - 1987). Pit 2 had a holding capacity of 1,000,000 gallons at a stage of twelve feet and it received ILLW which was brought in by tank trucks until completion of the ILLW pipeline. The pipeline was constructed in 1954 and was used to transfer ILLW directly from the gunite tanks to Pit 2. However, a tank truck continued to be used for transporting inactive chemical wastes, primarily aluminum and ammonium nitrates to Pit 2 for disposal. The amount of active waste disposed of in Pit 2 is difficult to assess because overflow from Pit 2 was routed to Pits 3 and 4. Pit 3 and Pit 4 were opened for operation in 1955 and 1956 respectively. Pit 3 received the initial ILLW discharge and after reaching its capacity, any surplus was piped to Pit 2 which discharged through an overflow pipe to Pit 4. Therefore, the relative distribution of ILLW between these three pits is not known but the total quantity for all three is estimated at 21,000,000 gallons (B.P. Spalding - 1987).

The principal waste constituents disposed of in all three pits were ^{137}Cs , ^{106}Ru , ^{90}Sr and the trivalent rare earths (N.T. Edwards - 1986). In 1957 sludge from the old process waste water treatment plant was transferred by tank truck to Pits 2 and 4 for disposal. The sludge constituents were primarily illitic clays and calcium carbonate with comparatively small amounts of radioactivity.

During the years 1959 and 1961, considerable amounts of ^{106}Ru were discharged to the pits and a seep contaminated with ^{106}Ru was discovered on the west side of Pit 2. A trench was excavated at this location to intercept and collect the seep discharge which was then pumped back into Pit 2. Sodium sulfide was added to Pit 2 in an effort to reduce the flux of ^{106}Ru but this was ineffective and subsequently the levels of ruthenium discharged from the plant were decreased. Pit 2 was closed by gradually backfilling it with soil as it continued

to drain over the period from November, 1962 to late 1963. Final grading was completed in late 1963 and a sloping asphalt cap was placed over the pit in 1970. The asphalt cap is well maintained and the site is currently fenced and posted.

3.1.1c Pit 3

Pit 3 is located on the same hill as Pit 2 and is immediately northeast (upslope) of Pit 2. It was constructed in January of 1955 and has the same dimensions and holding capacity as Pit 2. As stated earlier, Pit 3 became the initial discharge point for the ILLW pipeline and it was designed to overflow through a pipe into Pit 2. The principal radionuclides disposed of in Pit 3 were ^{137}Cs , ^{106}Ru and the trivalent rare earths, as well as the chemical constituents sodium and nitrate from the treatment process in the gunite tanks. Other radionuclides disposed of in lesser amounts in Pit 3 included ^{89}Sr , ^{90}Sr , ^{60}Co and ^{125}Sb (B.P. Spalding - 1987). Seepage from Pit 3 was observed on its eastern side but the flow was relatively small compared to the seep at Pit 2 and no corrective measures were taken. In September of 1961, Pit 3 was closed out and backfilled, then covered with an asphalt cap. Presently the asphalt cap appears well maintained and a fence has been erected and the area appropriately posted.

3.1.1d Pit 4

The ILLW production rate in 1955 was greater than the operating capacity of Pits 2 and 3 and a fourth pit was constructed. Pit 4 was sited south (immediately downslope) of Pit 3 and had the same dimensions and storage capacity (1,000,000 gallons) as Pits 2 and 3. The new pit went into operation in April, 1956 when it began to receive the ILLW overflow piped in from Pit 2.

Pit 4 proved to be more permeable than its predecessors, and an increase in Ruthenium discharges to the pits in 1959 apparently resulted in a contaminated seep on the eastern side of Pit 4. An interception/collection trench ten feet deep and one hundred seventy-five feet long was excavated along the eastern side of Pit 4. The trench was part of a two fold remediation effort that included pumping the accumulated contamination back into the pit and the addition of copper compounds to Pit 4 in hopes of immobilizing the Ruthenium.

Ultimately the Ruthenium discharges to the pits were discontinued but it took some time for the seepage to abate. During this time period, another interception/collection trench was excavated on the west side of Pit 4 and ten tons of sodium sulfide were added to the pits to reduce the mobility of Ruthenium. In spite of its operational problems, Pit 4 remained in service even after the closure of Pits 2 and 3 and the advent of the disposal trenches. However, such service was limited, and Pit 4 was used primarily as a backup system and for disposal of sludge from the old process waste treatment plant. Pit 4 was gradually backfilled beginning in 1976 and received an asphalt cap in 1980.

Of all the pits constructed, Pit 4 was probably the most thoroughly planned. The planning included a pump test using four observation wells, two along strike and one up-dip and one down-dip. The data from this test, which are presented graphically in Figure 3-2, indicate that the down-dip well (#75) exhibited maximum drawdown and response rates an order of magnitude greater than the other wells. The data also indicate a curious positive head response in the up-dip well (#77) at the outset of the test followed by a drawdown response that continued after pumping had stopped. The two observation wells located along strike exhibited relatively uniform drawdown and recovery response curves.

3.1.1e Trench 5

Trench 5 was constructed in May of 1960 (B.P. Spalding - 1987) and is located on a hill about seven hundred and thirty feet east of Pit 4. The design of Trench 5 is markedly different from that of the pits, reference Figure 3-3. This design was intended to minimize worker exposure and reduce the amount of meteoric water collected. The design also called for the trenches to be oriented perpendicular to geologic strike which would enhance their seepage capacity since most of the seepage was believed to occur along strike via bedding planes. The trench was three hundred feet long by fifteen feet deep and was wider at the top than at the base. After completion the trench was tested with water to determine its seepage rate, which was calculated to be about 4,000 gallons per day. Before the trench was put into use it was treated with about 1,800 pounds of copper sulfate and about 1,000 pounds of sodium sulfide in hopes of reducing the mobility of ^{106}Ru . Trench 5 operated near its seepage capacity for a period of about six years (N.T. Edwards - 1986) and ultimately received about 9.5 million gallons of waste which contained ^{89}Sr , ^{90}Sr , ^{137}Cs , ^{106}Ru and ^{60}Co . In 1966 Pit 5 stopped receiving ILLW discharges and in 1970 it received an asphalt cap which is currently well maintained.

3.1.1f Trench 6

ILLW production rates continued to exceed the disposal system's capacity, so Trench 6 was constructed in 1961. Trench 6 is located about 1,500 feet north of Trench 5 on a hillcrest above a draw. Unlike its predecessor, Trench 6 was not sited completely perpendicular to geologic strike. Because this trench is roughly U-shaped portions of it probably are normal to strike while others definitely are not. The trench was treated with about 20,000 pounds of copper

FIGURE 3-2 WAG 7

Pumping Test, Pit 4, Aug. 31 - Sept. 10, 1955.

FIGURE 3-3 WAG 7

ORNL-LR-DWG 62129

Typical Waste Disposal Trench.

sulfate prior to beginning waste disposal in order to reduce the mobility of ^{106}Ru . However, little more than one month after coming on line Trench 6 was removed from service because of seepage outbreaks contaminated with ^{90}Sr and ^{137}Cs (B.P. Spalding, 1987). Only about 130,000 gallons of ILLW discharge containing ^{90}Sr , ^{137}Cs , ^{106}Ru and ^{60}Co were disposed of in Trench 6 during its brief period of operation. In 1981 this trench received an asphalt cap and the area is fenced and appropriately posted.

3.1.1g Trench 7

The last of the ILLW disposal trenches is located about 800 feet east of Trench 5 and it was completed in August, 1962. This trench was designed with three separate segments, only two of which were built because shallow groundwater was discovered beneath the site of the proposed third section during the site investigation phase (B.P. Spalding and W.J. Boegly, Jr. - 1985). Trench 7 was oriented perpendicular to geologic strike and consisted of two segments one hundred feet long and about fifteen feet deep. Before waste disposal commenced Trench 7 was treated with 50,000 gallons of four percent sodium hydroxide. This trench received about nine and one-half million gallons of ILLW discharge containing ^{90}Sr , ^{137}Cs , ^{106}Ru and ^{60}Co and operated until 1966 when the hydrofracture system became the preferred method of disposal. The operation of Trench 7 resulted in only one documented seep which occurred on its eastern side. The seep contained relatively low levels of ^{106}Ru and no remedial measures were taken. Trench 7 was not used for waste disposal after 1966 and was paved with asphalt in 1970. In 1985, the asphalt cap was expanded to enhance runoff and decrease surface water infiltration. Site reconnaissance in April, 1987 revealed the

asphalt cap to be well maintained. Finally, a grout curtain was installed at varying depths on the northern and eastern sides of the trench in 1985 and 1986. The grout curtain was not intended to completely seal off the trench from lateral groundwater movement but rather was designed to plug preferred migration routes. The grout was put in place at 100 psi with a hammer driven injection pipe (B.P. Spalding - 1987).

3.1.2 ILLW Lines and Leak Sites

The liquid waste system at ORNL was formerly called the Intermediate Level Liquid Waste (ILLW) system but it is now referred to as the Low Level Waste (LLW) system because the waste stream has been reclassified. However, the pipe network and leak sites described in this section of the report were active and occurred prior to the reclassification. Accordingly, the waste stream is referred to herein as ILLW.

The ILLW system has evolved through the years to accommodate changes in plant operations and disposal techniques. The system's components include: collection tanks in the main plant area and in Melton Valley, an evaporator in the main plant area (used to reduce the waste's volume) and a piping network used to transfer waste within the main plant area and to the disposal sites in Melton Valley. Two of the leak sites in WAG 7 were associated with the piping network and a brief description of this network follows.

The first section of the ILLW line was constructed in June of 1954 (H.J. Grimsby - 1986). The line was fabricated out of two inch cast iron pipe and ran underground from the main plant area in Bethel Valley through the gap in Haw Ridge to its discharge point at Pit 2 in Melton Valley. In 1960 the line was extended to Trench 5 with additional extensions to

Trenches 6 and 7 in 1961 and 1962, respectively. In 1966 the first hydrofracture facility became operational and the ILLW line was extended to the southeast from Trench 7 to the hydrofracture site. This extension was also constructed of cast iron but was replaced in 1971 with stainless steel. The new steel line was installed next to the abandoned section.

Although the ILLW line was later extended to other locations, the leak sites in WAG 7 occurred along the routes described above and shown in Figure 3-1.

3.1.2a ILLW Line Leak Site

This leak site is the result of waste seepage from a coupling in the ILLW line. The waste was reported to have spread laterally over a small area, but a radiologic survey of the area indicated the presence of contaminated sediment extending all the way to White Oak Creek. The principal contaminants were ^{90}Sr , ^{137}Cs and ^{244}Cm with minor activity attributed to ^{241}Am , ^{238}Pu and ^{239}Pu (H.J. Grimsby, 1986). Three ground water monitoring wells were installed at the leak site and the monitoring results indicated contamination, thereby dictating the removal of 364 cubic yards of contaminated soil. Subsequent ground water monitoring showed significant decreases in radiologic activity but a surface survey indicated the presence of contamination, leaving some question about the effectiveness of the clean-up and/or the integrity of the ILLW line. Information regarding the location and construction of the three monitoring wells mentioned above was not available at the time this report was prepared.

3.1.2b Leak Site Southeast of Trench 6

This leak site is located about one hundred and fifty feet

south of Trench 6 (H.J. Grimsby - 1986) and contamination has been documented by two radiological surveys of the ILLW line. The first survey of this area was conducted by ORNL's Environmental Sciences Division in 1973. This survey noted that a leak had occurred at an earlier date but that the ILLW line had been repaired. Later in 1979, after this section of the ILLW line was no longer in service, ORNL's Industrial Safety and Applied Health Physics Division conducted another survey. The surveys indicated that the contamination had spread downslope to the southwest over several feet. The principal contaminants were ^{137}Cs , ^{90}Sr , ^{244}Cm , ^{241}Am , ^{238}Pu and ^{239}Pu (H.J. Grimsby - 1986). Soil samples indicated beta-gamma activity ranging from .01 to 50 uCi/g and alpha activity of about 1 uCi/g. Based on the findings of these surveys remedial measures were taken to restrict the infiltration of surface water.

The leak site was cleared of vegetation and both contaminated soil (about one hundred cubic yards) and the ILLW line were removed. Clean clay fill was placed over the spill area and mixed with bentonite then graded. Following this, six inches of crushed stone were applied then the entire area was capped with asphalt. A site reconnaissance in March of 1987 revealed the asphalt cap to be in good condition.

3.1.2c Access Road Leak Site at the End of Trench 7

Less detailed information is available for this leak which occurred when a plastic pipeline ruptured releasing about 3,000 gallons of ILLW. The incident which is documented in a waste disposal operations report occurred just north of Trench 7 and the principal contaminants were Cesium, Cerium

and Strontium. Remediation at this leak site consisted of applying five feet of graded clay cover.

3.1.3 Other Inactive Facilities

Three additional sites, Decontamination Building 7819, the Homogeneous Reactor Experiment (HRE) Fuel Wells and soil contamination at the First Hydrofracture Experiment, are also located within WAG 7. These facilities are all presently inactive. A summary of each facility's operating history follows.

3.1.3a Decontamination Facility - Building 7819

This facility is located on the northern side of Lagoon Road near the western corner of SWSA 4. It was used during the early 1960's through the late 1970's for unshielded decontamination operations. The decontamination techniques included acid baths, sandblasting and other unspecified procedures. The residual contamination on site includes portions of the building, equipment contained inside the building and sandblasting sand located about one hundred feet north of the building. Radiological surveys of this facility document beta-gamma exposure rates ranging from 3.4 R/hr to less than 10 mR/hr inside the building. The sandblasting sand located outside the building has a maximum exposure rate of 2 mR/hr (F.G. Taylor - 1986).

3.1.3b Homogeneous Reactor Experiment (HRE) Fuel Wells

There are reportedly seven HRE Fuel Wells located just south of Trench 5, although field reconnaissance of the area in April of 1987 could only confirm the location of four. The wells are actually auger holes twelve inches in diameter, that are reported to be seventeen feet deep and about ten feet

apart which were used to dispose of the HRE liquid fuel. The fuel consists of uranium in solution with four molar sulfuric acid. Some fission products are also present, predominantly Strontium and Ruthenium.

Intra laboratory correspondence documents the disposal of ninety-seven gallons of fuel solution distributed between wells S-3, S-4, S-5, S-6 and S-7 during the period from March 18, 1964 to April 1, 1964. The record is not clear about when wells S-1 and S-2 were used. The fuel was transported to the disposal site in a twenty-three gallon transfer vessel fitted for either pressurized or vacuum emptying. A filter was placed over the hole to protect workers from any gases that might have formed from the reaction of the acid in the fuel with the carbonate in the shale. A plastic transfer line was run to the bottom of the auger hole and the fuel discharged. Afterwards the plastic line was lowered into the hole and the well was backfilled with earth. The auger holes were marked with a concrete cap fitted with a brass plaque inscribed with the following information:

* WELL NO. S-1
DWG. NO. E 38204
COORDINATES; N 17293.40 E 26728.25
6 BOTTLES 6.1, 10.0, 8.81 LITERS SOLUTION
92, 148, 79 g U 235

WELL NO. S-2
DWG. NO. E 38204
COORDINATES; N 17289.95 E 26716.61
60.7 LITERS SOLUTION 528 g U 235

WELL NO. S-3
DWG. NO. E 38204
COORDINATES; N 17285.78 E 26704.82
82.5 LITERS SOLUTION 704 g U 235

WELL NO. S-4
DWG. NO. E 38204
COORDINATES; N 17284.34 E 26693.26
82.5 LITERS SOLUTION 704 g U 235

WELL NO. S-5
DWG. NO. E 38204
COORDINATES; N 17287.20 E 26681.22
84.0 LITERS SOLUTION 717 g U 235

* WELL NO. S-6
COORDINATES; N 17291.50 E 26669.70
65.0 LITERS SOLUTION 730 g U 235

* WELL NO. S-7
COORDINATES; N 17295.24 E 26658.46
85.0 LITERS SOLUTION 286 g U 235

* Monument not found - unable to verify well location or plaque inscription during field reconnaissance on April 20, 1987.

3.1.3c Hydrofracture Experimental Site 1 - Soil Contamination

Hydrofracture Experimental Site 1 is located near the northwestern corner of WAG 7, just southwest of Lagoon Road (Figure 3-1). This area was also known as the four acre site when it was used as a study area for gathering geologic field data relative to the pits and trenches. This earlier work provided detailed geologic structural information for the hydrofracture work.

In October, 1959, the first hydrofracture experiment was conducted to determine the orientation of hydraulically initiated fractures. The experimental procedure used a borehole cased to three hundred feet, a slot was cut in the casing with a high pressure water-sand jet at two hundred and ninety feet and a fracture was initiated with a water sand mix at a pressure of 3,000 psi. The day after the fracture was established, 27,000 gallons of water, cement, diatomaceous earth and a fluid loss additive were pumped into the fractured shale. The grout mixture was tagged with a radioactive tracer, thirty-five curies of ¹³⁷Cs and eight and seven tenths

curies of ^{144}Ce . The tracer could be detected with gamma-ray logs of coreholes drilled through the fracture zone and the orientation of the grout sheet inferred.

After the grout had been pumped into the shale, the injection well was flushed with four hundred gallons of water. Towards the end of the flushing operation grout was observed flowing out of a three-inch diameter corehole one hundred ninety-nine feet north of the injection well (Figure 3-1). Pumping was immediately stopped but grout continued to flow out for a period of several hours. The following morning clear water was issuing from the corehole and this continued, although with gradually decreasing volume, for about two months. The flow of water was directed to, and was contained in a dug pit which was later filled in. The grout and adjoining soil were dug up after the grout had cured and were disposed of in SWSA 5 (B.P. Spalding - 1987).

3.1.3d Shielded Transfer Tanks

There are five heavily shielded transfer tanks designated ST 1, ST 2, ST 3, ST 4 and ST 5 located above ground in a storage area about five hundred feet north of Pit 3. These tanks were originally used to transfer low concentrations of aqueous Cesium and Strontium waste from Arco, Idaho to ORNL in the late 1950's (N.T. Edwards and F.G. Taylor, Jr. - 1986). Later during the 1960's the tanks were used for the transfer of cesium loaded ion exchange resins from Hanford, Washington to ORNL. In 1967 all the tanks except one were taken out of service. The single active tank was used at ORNL in 1970 and 1971 for the transfer of a caustic solution bearing a high-level fission product waste (N.T. Edwards and F.G. Taylor, Jr. - 1986). All of the tanks are now inactive but contain residual contamination, principally ^{137}Cs . The tanks

are of two different designs (Figures 3-4 and 3-5) and presently none of the tanks are known to be leaking.

3.2 Topography

Two draws divide the majority of WAG 7 into three southerly trending lobes. The northwestern corner of the site is bisected by a southerly trending draw that joins a larger drainage system just southwest of the WAG boundary. The aforementioned draws receive drainage from numerous smaller draws that dissect the uplands, giving the overall landform an irregular, "knobby" appearance.

Slopes range from less than one percent on the site's western uplands in the vicinity of Pits 2, 3 and 4 to greater than fifty percent on the flanks of the draws that drain the site. Maximum relief is about one hundred and fifteen feet, with elevations ranging from a high of 870 feet on the site's east-central border to a low of 755 feet near the floodplain of White Oak Creek.

3.3 Soils

Soils derived from the Conasauga Group are typically yellowish-brown to reddish-brown, silty clays interspersed with weathered shale fragments. Drill logs from the ORNL piezometer installation project (December, 1985 to the present) describe the soils and subsoils in WAG 7 as medium brown to red silty clays with shale float. The drill logs record soil depths ranging from four and one-half feet on the lower elevations near the White Oak Creek floodplain to twenty-two feet on the slopes below Pit 6. These logs suggest that the transition from soil to bedrock is gradational in shale lithologies, but it is more distinct when limestone is present.

UNCLASSIFIED
ORNL-LR-DWG 63529R

FIGURE 3-4 WAG 7
SHIELDED TRANSFER TANK MODEL II

response that continued after pumping had stopped. The two observation wells located along strike exhibited relatively uniform drawdown and recovery response curves.

-36-

FIGURE 3-5 WAG-7

ORNL-DWG 79-20020

DOT SP 5174

SHIELDED TRANSFER TANK-MODEL III

WEIGHT — 42,000 lb.
AUTHORIZED CONTENTS — 90,000 Ci ^{137}Cs .

Webster - 1976 identified the principal clay minerals in the Conasauga Group as illite and vermiculite. These clays are important geochemical factors in controlling the migration of some waste constituents that may leach from the disposal sites. The clay minerals occur in the residuum as innumerable, microscopic, plate-like particles that, when taken as a whole, have an extremely large surface area. They retard migration of certain waste constituents by four mechanisms: 1) mechanical filtering; 2) adsorption of electrochemically charged particles on the clays' surface; 3) absorption of ionic species that fit within the clays' mineralogical lattice, and 4) ion exchange processes, whereby "incoming" charged particles replace those already adsorbed on the clays' surface. The efficiency of the adsorption mechanisms differ for various waste constituents and may be greatly affected by carbonate or organic complexing (C.R. Olsen, et al. - 1983). Laboratory tests can determine the relative adsorptive efficiency of a given clay mineral for a specific electrolyte and such tests yield a parameter known as the distribution coefficient, designated k_d . The distribution coefficient is calculated by dividing the mass of the solute adsorbed per unit mass of clay by the solute concentration. This parameter is usually expressed in units of ml/g.

Field-determined apparent k_d values for several radionuclides have been published in a detailed study of radionuclide migration from Trench 7 (C.R. Olsen, et al. - 1983). These values are presented in Table 3-1 and were calculated from silt and water samples collected from wells T7-3 and T7-13 located on the eastern side of Trench 7.

TABLE 3-1

Field-Determined Apparent k_d Values For
Silt Samples Collected From Wells T7-3 And T7-13
ml/g

Radionuclide	Sample Location	k_d Values
^{238}Pu	T7-3	330,000
^{238}Pu	T7-13	18,000
^{241}Am	T7-13	24,000
^{244}Cm	T7-13	18,000

Olsen, et al. - 1983 concluded that these radionuclides are relatively immobile, which interpretation is consistent with earlier observations that the highest concentrations of these nuclides occur in the soils and weathered rock nearest the trench.

3.4 Geology

According to the geologic map of the Oak Ridge Area (W.M. McMaster, 1958 - Figure 2-1) WAG 7 is underlain by the Conasauga Group. The contact between the base of the Conasauga Group and the upper portion of the Rome Formation is subparallel to Lagoon Road and occurs upslope of the road on the flanks of Haw Ridge. The small portion of the site that extends north of Lagoon Road to encompass Decontamination Building 7819 approaches this contact. The Conasauga Group's upper contact with the Knox Group occurs about 1,740 feet southeast of WAG 7 on the slopes of Copper Ridge.

Portions of WAG 7, specifically the area of first experimental hydrofracture site, the area of Pits 2, 3 and 4 and the area

just east of Trench 7, have been mapped structurally in some detail (Figures 3-6 and 3-7). Each of the areas mapped exhibit some degree of conformance with regional geologic structure; in general bedding strikes to the northeast and dips to the southeast. However, the mapping also indicates that a high degree of structural variability occurs throughout the site; several anticlines and synclines have been identified as well as locations of suspected faults.

A draft geologic map of the Conasauga Group's stratigraphy within WAG 7 is shown in Figure 3-8. This figure is based on preliminary work by Ranaye Dreier and Kathleen Boedoin - Martin Marietta Energy Systems Geologists and was prepared from core hole data from which cross-sections were constructed, spatially correlated and adjusted for topographic inflections. The map indicates that the Pumpkin Valley shale, Rutledge limestone, Rogersville shale and Maryville limestone underlie the subject site and that they are offset to the northeast by a tear fault. Descriptions of these formations are given below and were summarized from a detailed work on Conasauga stratigraphy by C.S. Haase, et al., 1985. These formations occur in succession from oldest to youngest in a traverse from north to south across WAG 7.

The Maryville Limestone is subdivided into upper and lower members. The upper member contains intraclastic limestone conglomerate interstratified with calcareous mudstone, micrite, and coarse grained limestone with a micrite matrix. The relative abundance of conglomerate decreases towards the bottom of the member. The lower member of the Maryville consists of interbedded calcareous mudstone and siltstone with discrete beds of coarse grained limestone. The limestone constitutes the uppermost strata in a cyclic upward coarsening sequence. The Maryville's contact with the Rogersville is identified as the lowermost ooid bearing upward coarsening sequence.

MARYVILLE LIMESTONE-CONASAUGA GROUP

FIG 3-7 WAG 7
GEOLOGIC STRUCTURE
ROAD CUT EAST OF TRENCH 7

E26000

E25000

N19000 + CPV

+

CIRCUIT NO. 6

Crt

Cm

PIT NO. 3

PIT NO. 1

WHITE

E28000

E27000

WAG 7 GEOLOGIC MAP

SCALE 1" = 200'

FIGURE 3-8

SHEET

OF

—LEGEND—

BUILDING		PUMPKIN VALLEY SHALE	Epv
STREAM		RUTLEDGE LIMESTONE	Ert
POWER POLE		ROGERSVILLE SHALE	Erg
MARSHY AREA		MARYVILLE SHALE	Ecm
SECONDARY ROAD		NOLICHUCKY SHALE	En
CONTOUR INTERVALS 5 FEET		UPTHROWN SIDE OF FAULT	U
		GEOLOGIC CONTACT
		FAULT

WORK BY RANAYE DREIER AND
KATHLEEN BOEDDIN—MMES
GEOLOGISTS.

BOUNDARY

DWN	CKD	APPD	DATE	PROJ

NOTES:

1. TOPOGRAPHY DIGITIZED FROM A BASE
MAP PREPARED BY ACCU-AIR SURVEYS,
INC. SEYMOR, INDIANA-WHITE OAK
CREEK WATERSHED MAP SERIES,
PHOTO DATE 3/29/78, MSL DATUM 1929.

2. TOPOGRAPHIC AND SITE SPECIFIC
INFORMATION PROVIDED BY MARTIN
MARIETTA ENERGY SYSTEMS, INC.

3. GEOLOGIC CONTACTS BASED ON
WORK BY RANAYE DREIER AND
KATHLEEN BOEDDIN-MMES
GEOLOGISTS.

G 7
UNDARY

The Rogersville Shale is characterized by massive to laminated mudstone, subarkosic siltstone and calcarenite (a carbonate lithology composed of sand sized grains in a calcite matrix). This member also contains a widely recognized stratigraphic marker, the Craig member. The Craig is the dominant carbonate lithology in the Rogersville and is about 9 feet thick, it occurs in the upper portion of the formation. The Rogersville's contact with the Rutledge is marked by an abrupt transition from mudstone to the limestones of the Rutledge.

The Rutledge Limestone can be subdivided into three members in the Oak Ridge Reservation. The upper member is predominantly micrite (an extremely fine grained carbonate rock type composed of limey mud), which may locally grade into coarser grained limestone with a micrite matrix. This member is commonly thin-bedded with a nodular to ribboned appearance. The central member of the Rutledge has a higher clastic fraction and is characterized by interbedded siltstones, mudstones and shales. The lower member is composed of coarser grained limestone with a micrite matrix interbedded with shale and mudstone. This lower member contains a 20 feet thick sequence of three limestone strata separated by mudstone; the lowermost limestone in this sequence forms the boundary between the Rutledge limestone and the Pumpkin Valley shale.

The Pumpkin Valley Shale is divided into upper and lower members on the Copper Creek fault block within the Oak Ridge Reservation. The upper member consists of mudstone and shale interbedded with subarkosic siltstone. The mudstone is massive to thin bedded with a variable silt fraction. The siltstone strata commonly occur in lenses that may locally grade into one another. Glauconite occurs as isolated pellets within the rock mass and along bedding planes. The lower member of the Pumpkin Valley contains slightly more siltstone which exhibits bioturbated horizons and glauconite

mineralization along bedding planes. Interbedded with this lithology are mudstone and siltstone similar to those described for the upper member.

3.5 Surface Hydrology

WAG 7 is located in the Melton Valley sub-basin of White Oak Creek's drainage basin. The majority of runoff from WAG 7 is collected by two southerly trending draws (identified in Table 3-2 as the central and east tributaries) that carry the drainage to White Oak Creek. During April of 1987, flow was observed in both of the draws even after approximately one week of dry weather. A third draw in the northwest corner of the site carries surface flow southward from a drainage diversion project, the latter which captures runoff from Haw Ridge and diverts it around SWSA 4. This drainage flows into a large southerly trending draw that runs subparallel to and just outside the western border of WAG 7. The stream that flows through this large draw (identified in Table 3-2 as the west tributary) passes within one hundred and fifty to two hundred and fifty feet of the WAG 7 boundary and discharges into White Oak Lake.

On the southern border of the site, White Oak Creek flows within about forty to six hundred and forty feet of the site. The stream gradient along this reach is less than two percent. The three major tributaries in WAG 7 have stream gradients of five percent or less.

The stream sediments in White Oak Creek and the three tributaries in WAG 7 were analyzed for radionuclides as part of a basin wide study by T.E. Cerling and B.P. Spalding - 1981. The study characterized activity levels in stream sediments for the radionuclides ^{60}Co , ^{137}Cs and ^{90}Sr and identified localized contaminant sources. Ranges of activity for these nuclides per tributary are given in Table 3-2 below.

TABLE 3-2
WAG 7
Radionuclide Activity Ranges
In Stream Sediments
Excerpted From ORNL/TM-7318, T.E. Cerling and B.P. Spalding - 1981
Radionuclide Activity Expressed In
Disintegrations Per Minute Per Gram of Sediment

Sample Source	^{60}Co	^{137}Cs	^{90}Sr
White Oak Creek	218.0- 594.0	2160.0-8840.0	16.0-59.4
West Tributary	0.0- 885.0	0.3- 200.0	1.6-846.7
Central Tributary	8.3-3990.0	0.2- 77.0	0.0- 8.2
East Tributary	0.0- 809.0	0.0-1500.0	1.0-154.6

Two additional papers by T.E. Cerling and B.P. Spalding - 1979 and 1982 document some of the geochemical relations between the radionuclides and stream sediments. These papers conclude that each of the three radionuclides is adsorbed by a different mechanism which is generally related to distinct mineral phases. For example, cobalt appeared to be associated with manganese oxide components in the stream sediments. Cesium, on the other hand, was retained by illitic clay components in the sediments and could only be leached in significant amounts by an extraction agent that altered the structural character of crystalline clay minerals. Strontium occurred primarily as an exchangeable cation although a small fraction was held in nonexchangeable form by manganese oxides.

These absorption mechanisms both influence and are influenced by surface water quality. For example, stream reaches with redox potentials that cause the dissolution of manganese oxides probably also bring ^{60}Co into solution. Alternatively,

stream reaches which are sufficiently saturated with calcium to cause it to precipitate may coprecipitate ⁹⁰Sr.

3.6 Groundwater

3.6.1 Existing Groundwater Monitoring System

A partial inventory of existing groundwater monitoring wells in WAG 7 is given by Appendix IV, and most of these wells are shown in Figures 3-9 and 3-10. The construction characteristics of these wells are not fully documented, but field observations indicate that the wells are constructed primarily of corrugated steel casing and PVC casing. Other wells were observed with protective outer casings of mild steel. Many of the wells shown on the maps are still in service; however, some have been destroyed and then replaced at a slightly different location.

Recently eight new piezometers were installed in WAG 7 (676, 678, 679, 718, 719, 720, 778 and 779). These piezometers were carefully designed and the installation procedures documented. Drilling for the new piezometer network utilized 6-inch diameter continuous flight augers in soil and 6 3/4-inch diameter air rotary techniques when rock was encountered. The only drilling fluid used was potable water to assist in removing drill cuttings. The piezometer well casings are constructed of 2-inch to 4-inch ID, flush threaded, schedule 40 PVC. The screened intervals are also PVC and have .010 inch factory machined slots. An inert silica sand was used for the sandpack, covered by at least one foot of bentonite as a seal. The bentonite was charged with potable water prior to grouting the annulus above. All the piezometers have PVC caps

FIGURE 3-9 WAG 7

UNCLASSIFIED
ORNL-LR-DWG 11924A

WELLS IN THE VICINITY OF THE
WASTE PIT DISPOSAL AREA

ORNL-DWG 76-1519

FIGURE 3-10 WAG 7
WELLS IN VICINITY OF TRENCH 7

and protective steel well covers. A typical drill log and construction diagram are included in Appendix I. The locations of the WAG 7 piezometers are shown in Figure 3-1 and a Table of as-built coordinates is given in Appendix III.

In addition to the eight piezometers, three hydrostatic well clusters consisting of a deep, intermediate and shallow well have been installed in WAG 7. The well cluster locations are shown in Figure 3-14. The deepest well in each cluster is about four hundred feet deep. The construction depths of the hydraulically open intervals for the intermediate and shallow wells were determined from geophysical logs from the deep well. The well clusters in WAG 7 are part of a larger network that will obtain head data from distinct hydrostratigraphic units and provide information on the vertical and lateral distribution of head throughout the ORNL complex (R.B. Dreier - personal communication).

3.6.2 Groundwater Quality

Information regarding ground water quality for WAG 7 is available in a summary document describing the ORNL Contaminant Scoping Survey (T.W. Doyle and F.G. Taylor - 1986). Excerpts and data from this document pertinent to WAG 7 follow.

Nine older wells in WAG 7 (Numbers 84, 95, 96, 98, 99, 124, WT7-7, WT7-3 and T6-7) were sampled. With the exception of well T6-7, these sampling stations are shown in Figures 3-9 and 3-10. Prior to sampling, the wells were purged of a volume of water equivalent to between 1 to 3 times the volume of water standing in the well. Most of the wells were allowed to recharge completely before samples were taken, but some

wells with low yields were sampled before they completely recovered. Three 1 liter samples were taken per well. Shallow wells were sampled with a peristaltic pump while those deeper than 24.9 feet were hand bailed. The bailer was cleaned between samples with 0.1 normal HNO_3 , then rinsed with distilled water and dried with paper towels. Nitric acid was used to "preserve" two of the samples from each well while the third received no additive.

The analytical methods employed were largely those prescribed by USEPA documents SW-846 and EPA-600/4-79-020.* Analyses were performed for radionuclides, metals and 118 organic compounds. The results of the radionuclide and metals analyses are shown in Table 3-3. The volatile extraction and liquid chromatography procedures for organic compounds and herbicides, detected none of the 118 parameters analyzed.

The analyses indicate that ^{60}Co is present in all nine wells sampled in WAG 7. ^{90}Sr was present in eight of the wells while ^{137}Cs and ^{125}Sb were found in wells T6-7 and 84, respectively. ^3H was not above the detection limits at any of the sample points. The low levels of radioactivity in the ground water of WAG 7 appear to be due primarily to ^{60}Co and ^{90}Sr .

*The parameters cadmium and lead were analyzed using both inductively coupled plasma (ICP) spectroscopy and polarography. The polarography method is reportedly more sensitive and is reported in parts per billion in this report. The ORNL Contaminant Scoping Survey document, from which this data was excerpted, reported the polarography values in parts per million. However, an oral communication with one of the authors, F.G. Taylor, on 02/20/87 disclosed that this was a typographical error and that the polarography analyses should have been reported in parts per billion.

-51-
TABLE 3-3
WAG 7
Elemental Concentrations And Radionuclide Values
In Nine Wells At The Pits And Trenches Area
Elemental Values Reported In PPM Except As Noted Otherwise
Radionuclide Values Reported In Bq/l

Element	Well Number								
	95	84	124	99	98	96	WT7-7	WT7-3	T6-7
Ag									
Al		0.23			0.3		0.6		0.57
As									
B									
Ba	0.059	0.048	0.063	0.2	0.062	0.066	0.054	0.094	0.16
Be									
Ca	53.0	26.0	85.0	88.0	96.0	84.0	56.0	100.0	3.4
Cd							0.0076		0.0054
Co	0.10	0.015			0.026	0.065			0.012
Cr									
Cu				0.048	0.025	0.022		0.06	0.087
Fe	0.14	0.31	0.12	27.0	2.4	0.57	0.60		140.0
Ga									
Li								6.0	
Mg	6.0	3.9	9.8	14.0	8.2	17.0	4.6	0.1	1.2
Mn	0.15	1.3	0.042	0.042	1.1	0.58	0.036		0.74
Mo							0.099	12.0	
Na	230.0	160.0	41.0	8.2	8.1	120.0	0.76		2.7
Ni	0.12					0.067			
P		0.43					0.33		
Pb									
Sb									
Se									
Si	4.3	3.2	2.1	7.3	3.9	2.9	3.4	4.7	6.7
Sr	0.059	0.033	0.077	0.13	0.084	0.13	0.034	0.068	0.0059
Ti									
V	0.014	0.018	0.023	0.028	0.021	0.034	0.12	0.015	
Zn	0.05	0.046	0.30	0.86	0.59	0.13	7.1	0.35	1.4
Zr									
⁹⁰ Sr	3.2	0.36	1.4	0.50	0.34		0.23	0.49	54.0
¹³⁷ Cs									180.0
⁶⁰ Co	120.0	23.0	4.4	0.83	1.8	47.0	0.32	0.40	2.7
¹²⁵ Sb		2.5							
Cd*						1.0			
Pb*				10.0	5.0	5.0			7.0

* Indicates use of polarography analytical techniques - values reported in PPB.

Additional information regarding groundwater quality for WAG 7 is available from a field study of monitoring wells in the vicinity of Trench 7 (C.R. Olsen, et al. - 1983). The following data and text have been condensed from the publication by Olsen.

Table 3-4 compiles averaged groundwater quality data for the 1981 and 1982 record period from twelve wells, one soil boring and one seep near Trench 7. The data suggests that at the time the samples were collected the trench was still having an impact on groundwater quality. This is particularly evident for the nitrate, sulfate and radionuclide analytical results.

In addition to characterizing groundwater quality, the field study evaluated the vertical distribution of gamma activity in six wells (T7-20, T7-21, T7-22, T7-23, T7-24 and T7-25). The gamma logs identified activity peaks down to a depth of about fifty feet with most of the peaks occurring between twenty and forty feet. These peaks have been interpreted to represent former migration paths. An important observation in support of the above interpretation was that those wells with inferred migration paths coincident with or below the water table also have higher radionuclide concentrations.

The field study by Olsen, et al. documents increases in pH and radionuclide concentrations which correspond to seasonal rises in the water levels of wells T7-3 and T7-13. This may be an indication that waste constituents are being leached from the former disposal site when seasonal recharge causes the water table to intercept former migration pathways or the trench itself.

TABLE 3-4
WAG 7
Average Groundwater Composition (1981-1982) for
Wells Near Trench 7
Excerpted From C.R. Olsen, et al. 1983

Well No.	Total Alk (ug/mL)	NO ₃ ⁻ (ug/mL)	SO ₄ ⁻ (ug/mL)	Cl ⁻ (ug/mL)	Na ⁺ (ug/mL)	K ⁺ (ug/mL)	Mg ⁺⁺ (ug/mL)	Ca ⁺⁺ (ug/mL)	Org C (ug/mL)	Total P (ug/mL)	³ H (Bq/L)	⁹⁰ Sr (Bq/L)	⁶⁰ Co (Bq/L)	²³³ U (Bq/L)
T7-2	38	0.1	16	- ^a	4	1.6	5.7	85	19.0	0.01	170	2,350	ND ^a	< 0.01
T7-3	263	31	152	6.3	198	2.4	4.0	35	2.0	0.20	7,640	0.6	1,075	5.6
T7-10	177	4	23	4.3	18	2.9	7.1	108	10.2	0.02	3,170	2.6	275	0.13
T7-13	358	79	98	6.0	302	3.6	1.0	5	5.8	0.65	6,810	0.3	1,080	9.4
T7-15	37	2	42	2.5	20	0.7	1.7	14	1.9	0.01	-	-	20	< 0.01
T7-20	292	19	139	6.0	183	4.9	4.8	28	6.6	2.70	5,100	1.0	790	12.9
T7-21	251	135	678	22.0	271	5.2	32.0	207	4.1	0.04	27,300	0.7	2,040	0.6
T7-22	289	67	218	15.3	241	5.2	9.2	57	5.9	0.28	14,000	0.3	1,040	2.7
T7-23	134	0.5	82	37	14	5.8	11.6	72	8.6	0.02	10,700	0.8	ND	< 0.1
T7-24	288	63	170	10.9	213	3.7	6.7	33	7.5	0.48	8,490	0.4	1,315	9.4
T7-25	284	58	129	9.1	188	3.7	3.9	26	5.5	0.34	5,960	2.1	1,030	12.3
T7-26	200	-	13	2.6	6	2.6	6.6	60	4.5	0.11	85	67.6	14	< 0.1
SB-1	-	-	< 25	< 5.0	6	3.9	7.3	99	-	< 0.3	210	3.9	ND	< 0.04
Seep	135	78	279	5.5	171	2.6	46.2	87	19.0	0.04	-	-	880	1.8

^aDash (-) indicates not analyzed; ND indicates not detected.

3.6.3 Hydrology

In its reaches adjacent WAG 7, White Oak Creek is probably effluent with respect to groundwater (J.W. Boyle, et al. - 1982); this conforms with regional hydrologic patterns. Field reconnaissance of the three major tributaries draining WAG 7 in April, 1987 indicated that these water courses are not directly dependent on precipitation to sustain flow. However, the amount of base flow they receive may diminish during late summer and fall.

A phreatic surface map for the southern portion of WAG 7 has been prepared from preliminary water level data collected from preremedial action program wells on July 7 and 9, 1987 (Figure 3-11). The phreatic surface is segmented reflecting well distribution and the availability of water level data. The water table contours generally conform to topography but are 25 feet to 30 feet below ground level at upper elevations and 1 foot to 10 feet below ground level at lower elevations. Beneath the slopes of the site, there appears to be a transition zone where the depth to water increases in direct proportion to increases in topographic elevation. The hydraulic gradient is greatest where this transition zone is foreshortened by steep slopes, typically in the draws that drain the site. The gradient ranges from about 12.5 percent in the draw east of Pit 4 to about 2 percent in the vicinity of Trench 7.

Some of the possible directions of shallow groundwater movement are indicated by arrows on the phreatic surface map. The arrows suggest that groundwater moves from areas of greatest hydraulic potential to areas of lower hydraulic potential. Because the draws that drain the site are coincident with local hydraulic lows, the points where the

E25C11

N19000 +

WAG
BOL

E28000

E27000

PHREATIC SURFACE MAP

FIGURE 3-11
WAG 7

SHEET

OF

—LEGEND—

BUILDING

STREAM

POWER POLE

MARSHY AREA

SECONDARY ROAD

CONTOUR INTERVALS
5 FEET

PRE-REMEDIAL ACTION
PROGRAM WELL
(WATER LEVEL ELEV.
768.03)

77-24
• 768.03

PHREATIC SURFACE
ISOPLETH

POSSIBLE GROUNDWATER
FLOW DIRECTION

VAG 7 BOUNDARY

3. PHREATIC SURFACE CONTOURS BASED ON
PRELIMINARY WATER LEVEL DATA FOR THE
PERIOD JULY 7, 1987 THROUGH JULY 9, 1987

OWN
CKD
APPD
DATE
PROJ

NOTES:

1. TOPOGRAPHY DIGITIZED FROM A BASE
MAP PREPARED BY ACCU-AIR SURVEYS,
INC. SEYMOR, INDIANA-WHITE OAK
CREEK WATERSHED MAP SERIES,
PHOTO DATE 3/29/78, MSL DATUM 1929.
2. TOPOGRAPHIC AND SITE SPECIFIC
INFORMATION PROVIDED BY MARTIN
MARIETTA ENERGY SYSTEMS, INC.
3. PHREATIC SURFACE CONTOURS BASED ON
PRELIMINARY WATER LEVEL DATA FOR THE
PERIOD JULY 7, 1987 THROUGH JULY 9, 1987

**AG 7
BOUNDARY**

E29000

draws intersect the WAG boundary provide excellent locations for water quality wells.

Previous geohydrologic work in the vicinity of Pits 2, 3 and 4 and Trench 7 resulted in the phreatic surface maps shown in Figures 3-12 and 3-13. These figures are in general agreement with Figure 3-11 and depict a water table that generally conforms to the morphology of the land surface and have gradients ranging from fifteen percent near Pits 2, 3 and 4 to about 1 percent near Trench 7.

The phreatic surface maps are in agreement with the conceptual model for shallow groundwater flow (Section 2.2). The model suggests that shallow groundwater flow is from the potentiometric highs on the hilltops of WAG 7 to the potentiometric lows on the floodplain of White Oak Creek and its tributaries. This description is probably reasonably accurate for groundwater movement in the saturated residuum.

The bedrock aquifer is believed to be anisotropic and heterogeneous and the direction of groundwater flow in this medium probably reflects both the hydraulic gradient and the orientation of structural features comprising the bedrock's secondary permeability system. As discussed earlier, many of these structural features trend northeast to southwest, consistent with geologic strike. This correlates well with observations made during operation of the pits and trenches when it was noted that seepage rates could be enhanced by orienting the excavation normal to geologic strike. This orientation exposed the maximum possible number of beds and structural elements providing the maximum number of migration pathways. Another observation that corroborates this general description of groundwater flow is that many of the contaminated seeps occur along geologic strike from the pits and trenches (Figure 3-14). Olsen, et al. - 1983 suggested

FIGURE 3-12 WAG 7

ORNL-DWG 85-17019

POTENTIOMETRIC MAP FOR THE VICINITY OF TRENCH 7

FIGURE 3-13 WAG 7

BASE: STONE & WEBSTER, 1943

FIGURE 3-14 WAG 7
SEEP LOCATION MAP
FOR THE PITS AND TRENCHES AREA

that the contaminated seep east of Trench 7 is related to a fault zone that projects through the trench (Figure 3-7). On the basis of this information, a significant percentage of the groundwater flowpaths in the bedrock at WAG 7 are presumed to be along strike and either to the northeast or southwest depending on local hydraulic gradients.

3.7 Data Gaps and Recommendations

3.7.1 Data Gaps

The groundwater data base for WAG 7 could be improved by conducting an inventory of all existing wells. The inventory should document as much information as possible regarding well construction. This will aid in determining which wells will yield reliable water level data and supplemental water quality data. The vertical gradient in WAG 7 should be evaluated further by installing paired shallow and deep water quality wells and comparing their static water levels.

3.7.2 Recommendations

The history of waste disposal at WAG 7, coupled with the present regulatory climate and available ground water quality data, indicates the need for a new water quality well system. In keeping with Martin Marietta Energy Systems' plans to monitor specific Waste Area Groupings, water quality wells are proposed at locations where estimated groundwater flowpaths from individual solid waste management units (SWMUs) intersect the WAG boundary.

Well siting criteria included the estimated direction of ground water flow in both the regolith and bedrock, as well as the possible occurrence of shallow flow paths suggested by

seep locations. Well spacing considerations included the locations of existing and proposed hydrostatic head well clusters and establishing an areal distribution that adequately monitors the entire site.

Two types of wells are recommended: 1) shallow wells, about 15 feet to 25 feet in depth, monitoring the upper saturated zone in the residuum or weathered to fresh shale, and 2) deeper wells, about 55 feet to 70 feet in depth, to monitor the deeper flow regime. Both types of wells will be used for upgradient and downgradient monitoring. Well construction details are shown in Appendix II.

The single shallow well, numbered 1071 east of Decontamination Building 7819 (Figure 3-15), will monitor this facility's impact on shallow groundwater quality. On the northern side of Lagoon Road, shallow and deep wells numbered 1072 and 1073, respectively, will provide background water quality information. Along the western border of the site are three shallow and deep well pairs, numbers 1074 and 1075, 1076 and 1077, and 1078 and 1079. These wells will monitor both shallow flow influenced by the local hydraulic gradient as well as deeper strike oriented flow. Note that two of the well pairs are located near the mouths of draws which are hydraulic lows and may serve as collection outlets for contaminants. The three shallow wells and two shallow and deep well pairs (numbered in series from 1080 - 1086) along the southern border of the site are intended to monitor both shallow groundwater flowpaths that may provide base flow to White Oak Creek and potential deeper, strike-oriented flowpaths that may occur in the bedrock.

Design criteria based on available piezometer data as well as design coordinates and estimated completion depths for the

151

BOL

PIT NO. 1

TRENCH NO. 6

WHITE

SH 1086

SH 961

SH 962

SH 949

SH 948

ROAD

OAK

775

800

850

850

825

800

850

825

800

850

850

825

800

850

850

850

E27000

E28000

850

SH DP
950 951

825

7819

1201 HS

PIT NO. 1

949 SH
946 SH

825

800

850

775

WAG 7
BOUNDARY

WAG 7 PROPOSED WATER QUALITY WELL LOCATIONS

FIGURE 3-15

SHEET

OF

—LEGEND—

BUILDING		PROPOSED WATER QUALITY WELL LOCATIONS		SH
STREAM		SHALLOW COMPLETION		DP
POWER POLE		DEEP COMPLETION		
MARSHY AREA		EXISTING HYDROSTATIC HEAD WELL CLUSTERS
SECONDARY ROAD		PLANNED HYDROSTATIC HEAD WELL CLUSTERS
CONTOUR INTERVALS 5 FEET		PROPOSED WATER QUALITY WELL LOCATIONS FOR WAG 4 BORDERING ON WAG 7		DP 959
		PROPOSED WATER QUALITY WELL LOCATIONS FOR WAG 6 BORDERING ON WAG 7.		840

WN
KD
PPD
ATE

WAG 7

BOUNDARY $\oplus$ SH956

$\oplus$ DP957
 $\oplus$ SH958

$\oplus$ SH959 $\oplus$ DP959

CREEK

LLW

APPROXIMATE ROUTE
OF LLW LINE

MCI

NOTES:

1. TOPOGRAPHY DIGITIZED FROM A BASE
MAP PREPARED BY ACCU-AIR SURVEYS,
INC. SEYMOR, INDIANA-WHITE OAK
CREEK WATERSHED MAP SERIES,
PHOTO DATE 3/29/78, MSL DATUM 1929.
2. TOPOGRAPHIC AND SITE SPECIFIC
INFORMATION PROVIDED BY MARTIN
MARIETTA ENERGY SYSTEMS, INC.

E29000

DP 953
952 SH

AG 7

BOUNDARY SH 956

+

DP 957
SH 958

proposed water quality wells are given in Appendix III. The suggested completion depths should be treated as best estimates for use in costing and project planning. The actual completion depths will be based on an evaluation of water level data from existing wells and field information obtained and evaluated by experienced hydrogeologists at the time of the drilling.

Materials for well screens and casings must be able to meet three basic performance standards: 1) long-term structural integrity, 2) compatibility with the geochemical environment, and 3) capability to yield unbiased ground water samples. The Environmental Protection Agency's Ground Water Technical Enforcement Guidance Document recognizes the use of a wide variety of well screen and casing materials. Each material has advantages and disadvantages based on site specific geochemistry and the type of analytical work to be conducted.

Two of the more versatile screen and casing materials are Teflon (Registered Trademark - Dupont) and stainless steel (304, 316 or 2205). Teflon generally meets all three performance standards, but some ground water professionals feel that it can be difficult to work with because: 1) it is relatively soft, 2) the couplings can be cross-threaded, and 3) its slick surface can be difficult to hold onto during installation. However, if properly handled, Teflon is a suitable casing material. Stainless steel generally meets all three performance standards provided that the geochemical environment is non-corrosive. Based on past experience in similar geologic terrane, the soil and ground water pH in Melton Valley are expected to range from mildly alkaline to mildly acidic and therefore such an environment should not pose a corrosion problem for stainless steel. Therefore, both Teflon and stainless steel are technically sound well screen

and casing materials and Martin Marietta Energy Systems, Inc. may exercise their preference on the basis of material cost and availability. The length of the well screen should be limited to about 10 to 20 feet, to minimize vertical dispersion of potential waste constituents and the related problem of effectively compositing samples when using a long screened interval. The shallow wells should be screened within the zone of seasonal water table fluctuations. This screen placement depth may allow the detection of contaminants leached from the capillary fringe as well as those already in solution in the ground water.

4.0 Waste Area Grouping 8

4.1 Site Location, Description and Background

WAG 8 encompasses approximately 34 acres, the majority of which is located in Melton Valley. Irregular in shape, the site has two sinuous extensions from its northern end that contain the LLW transfer lines. One of the lines extends northwest and crosses Haw Ridge, the other runs parallel to Melton Valley Drive up to its juncture with another line at Lagoon Road (Figure 4-1). To the east, the site is bordered by two draws that contain tributaries of Melton Branch and the floodplain of Melton Branch borders the site to the south. On its western side WAG 8 is flanked by a low southwesterly trending knoll. Portions of the two aforementioned tributaries and the floodplain of Melton Branch constitute the upper reaches of WAG 2 (Figure 1-2).

WAG 8 contains twenty solid waste management units that can be divided into four groups:

I. HFIR/TRU Waste Collection Basins

- a) Basin 7905
- b) Basin 7906
- c) Basin 7907
- d) Basin 7908

II. LLW Line Leak Sites

- a) The Melton Valley Transfer Line
- b) Melton Valley Drive Leak Site
- c) Melton Valley Drive and SWSA 5 Access Road Leak Site
- d) 7500 Area Leak Site
- e) Leak Site West of Melton Valley Pumping Station
- f) Building 7920 and Melton Valley Pumping Station Area Leak Sites
- g) Building 7920 Ditch Line Leak Site

WHITE OAK CREEK

E31000

F32000

VALLEY DRIVE
TE (APPROXIMATE
N)

MELTON VALLEY
TRANSFER LINE
ACTIVE SECTION
INACTIVE SECTION

7500 AREA

UNDOCUMENTED
LEAK SITE 2
(APPROXIMATE LOCATION)

~~UNDOCUMENTED~~ LOCATION OF
CONTAMINATED AREA)

UNDOCUMENTED
LEAK SITE 1
(APPROXIMATE
LOCATION)

BUILDING 7920 AND MELTON
PUMPING STATION LEAK
AND
BUILDING 7920 DITCH
LINE LEAK SITE
(APPROXIMATE LOCATION
CONTAMINATED AREA)

WAG 8 ———
BOUNDARY

HYDROFRACTURE EXPERIMENTAL
SITE 2 SOIL CONTAMINATION
(APPROXIMATE LOCATION)

MELTON

MELTON

LOCATION)

**SILVER RECOVERY
PROCESS 7904
(APPROXIMATE
LOCATION)**

N17000

**SEWAGE TREATMENT
PLANT 7904**

BASIN 7905

MELTON

MELTON

NOTES:

1. TOPOGRAPHY DIGITIZED FROM A BASE MAP PREPARED BY ACCU-AIR SURVEYS, INC. SEYMOUR, INDIANA - WHITE OAK CREEK WATERSHED MAP SERIES. PHOTO DATE 3/29/78, MSL DATUM 1929.
2. TOPOGRAPHIC AND SITE SPECIFIC INFORMATION PROVIDED BY MARTIN MARIETTA ENERGY SYSTEMS, INC.
3. LOCATIONS OF LOW LEVEL WASTE LINES (LLW) ARE APPROXIMATE AND WERE DIGITIZED FROM AN ORNL ATLAS MAP "MELTON VALLEY (DRAFT)" DATED 8/13/85.

-LEGEND-

BUILDING

LLW (AREA

STREAM

SOLID MANA

POWER POLE

FENCE

SECONDARY ROAD

CONTOUR INTERVALS
5 FEET

LOW LEVEL WASTE
LINE (LLW)

LLW LINE DOUBLE
CONTAINED SECTION

SHEET

OF

FIGURE 4-1

WAG 8 SOLID WASTE MANAGEMENT UNITS

SCALE: 1" = 200'

MARTIN MARIETTA ENERGY SYSTEMS

ACTIVE LLW COLLECTION/
STORAGE TANK HIFR
(APPROXIMATE LOCATION)

+

+

D

TS

X

-X-X-

OWN
CKD
APPD
DATE
PROJ
SCALE

MCI

Consulting Engineers, Inc.

NASHVILLE

KNOXVILLE

HUNTSVILLE

LOUISVILLE

III. Active LLW Tanks

- a) Active LLW Collection/Storage Tank WC-20
- b) Active LLW Collection/Storage Tank (HFIR)
- c) Active LLW Collection/Storage Tanks (T-1, T-2)

IV. Other Facilities

- a) Hydrofracture Experimental Site 2, Soil Contamination
- b) Hazardous Waste Storage Facility 7507
- c) Mixed Waste Storage Pad 7507 W
- d) Sewage Treatment Plant
- e) Silver Recovery Process

The locations of these solid waste management units are shown in Figure 4-1.

WAG 8 also contains an area of fill material located in the narrow finger-like extension of the WAG boundary north of the site of the second hydrofracture experiment (Figure 4-1). Construction rubble, a concrete tank and some scrap metal were observed during field reconnaissance of this area on July 30, 1987. Field reconnaissance also located a seep below HFIR/TRU Waste Collection Basins 7907 and 7908. These areas are not designated solid waste management units but are pointed out here as minor environmental influences in WAG 8.

4.1.1 The HFIR/TRU Waste Collection Basins

There are four surface impoundments located south of the High Flux Isotope Reactor (HFIR) facility in WAG 8. Two of the impoundments, 7905 and 7906, receive process waste streams from the HFIR facility. Impoundments 7907 and 7908 receive process waste streams from the Thorium-Uranium Facility (TURF) and the Trans-Uranic Processing Facility (TRU) (MCI - 1985). A schematic of the process waste flow is shown in Figure 4-2. Based on topography, it appears that all four basins were constructed by excavation and that some of the excavated material was used to construct berms around the basins. All four basins are lined with an estimated two feet of rock rip-rap on their interior slopes.

FIGURE 4-2
WAG 8 SCHEMATIC OF THE 7900 AREA
PROCESS WASTE SYSTEM
 FIGURE ADAPTED FROM THE RCRA MONITORING
 WELL INSTALLATION REPORT SURFACE
 IMPOUNDMENTS 3524, 3529, 3540, 7905, 7906, 7907,
 AND 7908

4.1.1a Basin 7905

This basin was placed into service in 1965. It has a flat base (40 feet by 70 feet) with two horizontal to one vertical side slopes (2H:1V) and is seven feet deep (F.G. Taylor - 1986). The design capacity is approximately 240,000 gallons. The HFIR facility's process wastes that are discharged to Basin 7905 consist of floor drains, laboratory drains, steam condensate and process vessel cooling water. Additionally, the basin receives radiologically contaminated blowdown water from the cooling tower in Building 7902. This latter waste stream is routed to the basin periodically on an as needed basis. The basin's discharge is monitored and provided that it is free of contamination it is released to Melton Branch, if it does contain contaminants it is routed to Basin 3524 in the main plant in Bethel Valley for further treatment.

Approximately twelve inches of sediment have accumulated on the base of this impoundment. EP Toxicity extracts of these sediments have been analyzed for metals and pesticides, as shown by Table 4-1. These analyses indicate that the basin's sediments do not exhibit any of the characteristics of EP Toxicity. However, chloroform and methylene chloride were identified above the analytical detection limits with mean concentrations of 6.0 and 5.7 ug/l, respectively. The principal radionuclide contaminant is reportedly ⁶⁰Co although no analytical results were reported (F.G. Taylor - 1986).

4.1.1.b Basin 7906

Basin 7906 is located adjacent Basin 7905 and also came on line in 1965. This is a larger impoundment with basal dimensions of 121 feet by 70 feet and a design capacity of 500,000 gallons. This basin receives HFIR facility process wastes but can also receive waste streams diverted from the

TABLE 4-1

WAG 8

Maximum Metal And Pesticide Concentrations
In EP Toxicity Extracts From Basin 7905 Sediments
Excerpted From F.G. Taylor - 1986
(Values Report In PPB)

Ag < 0.0500

As < 0.1000

Ba 0.7300

Cd 0.3600

Cr < 0.0400

Hg < 0.0001

Pb < 0.2000

Se < 0.2000

Endrin < 0.20

Lindane < 2.0

Methoxychlor < 8.0

2,4-D < 10.0

2,4,5-TP Silvex 23.0

Toxaphene < 5.0

TRU and TURF facilities. The principal radionuclide contaminant in the HFIR waste stream is ^{60}Co while plutonium and its daughter products are likely to be present in the TRU and TURF wastes (F.G. Taylor - 1986). If testing indicates contamination, the basin's contents are pumped to Basin 3524 in the main plant area; otherwise they are released to Melton Branch.

Approximately eight inches of sludge has accumulated in the basin. EP extraction procedures indicate that the sediment does not exhibit any of the characteristics of EP Toxicity, Table 4-2. However, the following volatile organic compounds were detected (excerpted from F.G. Taylor - 1986).

Average Concentrations Reported in PPB			
Chloroform	4.5	Tetrachloroethylene	42.4
Methylene Chloride	7.0	Trichloroethylene	2.9

4.1.1c Basin 7907

In 1965 this basin was placed in service to receive process waste from the TRU facility. This basin is approximately twelve feet deep and has a capacity of 50,000 gallons. Basin 7907 presently receives process waste streams from the TRU and TURF facilities. These wastes are derived from floor drains, laboratory drains, steam condensates and process vessel cooling waters (F.G. Taylor - 1986). Uncontaminated water from the basin discharges to Melton Branch, however, if radioactive contamination is present, the discharge is pumped to Basin 3524 in the main plant area.

The average sediment depth in the basin is 2.4 inches. These sediments have been analyzed according to the EP extraction procedure and were not found to exhibit any of the characteristics of EP Toxicity, as summarized in Table 4-3.

TABLE 4-2

WAG 8

Maximum Metal And Pesticide Concentrations
In EP Toxicity Extracts From Basin 7906 Sediments
Excerpted From F.G. Taylor - 1986
(Values Reported In PPB)

Ag < 0.0500

As < 0.1000

Ba 1.6000

Cd 0.1000

Cr 0.0970

Hg < 0.0001

Pb < 0.2000

Se < 0.2000

Endrin < 0.20

Lindane < 2.0

Methoxychlor < 8.0

2,4-D < 10.0

2,4,5-TP Silvex < 10.0

Toxaphene < 5.0

TABLE 4-3

WAG 8

Maximum Metal And Pesticide Concentrations
In EP Toxicity Extracts From Basin 7907 Sediments
Excerpted From F.G. Taylor - 1986
(Values Reported In PPB)

Ag < 0.0500

As 0.7400

Endrin < 0.20

Ba 1.7000

Lindane < 2.0

Cd 0.0240

Methoxychlor < 8.0

Cr < 0.0400

2,4-D < 10.0

Hg < 0.0001

2,4,5-TP Silvex 11.0

Pb 0.5000

Toxaphene < 5.0

Se < 0.2000

Activity levels for radionuclides were not reported in the available literature for this basin, but the principal radionuclide in the process waste stream is curium-244.

4.1.1d Basin 7908

Basin 7908 shares the same dimensions, waste streams, and operating procedures as Basin 7907, except that it is filled and emptied alternately with its sister basin. The sediments in this basin have been tested according to the EP Toxicity procedures and are not EP Toxic (Table 4-4). However, methylene chloride was detected and exhibited an average concentration of 15.2 ug/L.

The 7900 series basins are monitored by a groundwater monitoring well network described in Section 4.6.1 of this report.

4.1.2 LLW Line Leak Sites

Six of the seven leak sites included in WAG 8 occurred along the sections of pipeline that transferred waste from the HFIR, TURF and TRU facilities to the Melton Valley pumping station and then to the south tank farm in Bethel Valley. The one leak site that did not occur on this section of line is believed to have taken place on the original transfer line that ran from the south tank farm to the pits and trenches area (Personal Communication - L.C. Lasher, June, 1987). Both of these lines are presently inactive.

Currently, waste classed as Low Level Waste (LLW) is transferred from the HFIR, TURF and TRU facilities via stainless steel pipeline across Haw Ridge to the main plant in Bethel Valley. This section of LLW transfer line is also included in WAG 8 and for simplicity references to all

TABLE 4-4

WAG 8

Maximum Metal And Pesticide Concentrations
In EP Toxicity Extracts From Basin 7908 Sediments
Excerpted From F.G. Taylor - 1986
(Values Reported In PPB)

Ag < 0.0500

As < 0.1000

Ba 0.5000

Cd < 0.0050

Cr < 0.0400

Hg < 0.0001

Pb < 0.2000

Se < 0.2000

Endrin < 0.20

Lindane < 2.0

Methoxychlor < 8.0

2,4-D < 10.0

2,4,5-TP Silvex 18.0

Toxaphene < 5.0

sections of the transfer lines and leak sites will acknowledge the current LLW classification. However, it should be recognized that operation of the now abandoned sections of the transfer line and the leak events probably took place during the period when the wastes were classed as Intermediate Level Liquid Wastes (ILLW).

The information available for the leak sites varied from detailed accounts of spill events written shortly after they occurred to oral accounts of incidents that took place seventeen to twenty-seven years ago. In view of this, the level of detail varies, and in some instances accounts of a given leak event could not be positively matched to documented leak locations. Leak site locations were digitized from ORNL Engineering Division Drawing (DWG. A-90015-0-063-F REV. 5, dated 8/4/81) using MCI's AutoCad system. A review of ORNL background documents failed to find a second source that could corroborate the leak site locations given by DWG. A-90015-0-063-F REV. 5. In view of this, all LLW line leak site locations are labeled as approximate on Figure 4-1.

4.1.2a Melton Valley Transfer Line

Both sections of the Melton Valley LLW transfer line are included in WAG 8 as a single solid waste management unit. The older section of the transfer line ran from the Melton Valley pumping station along the northern side of Melton Valley Drive and crossed to the southern side of the road just west of the access road to SWSA 5. From there the line continued along the southern side of Melton Valley Drive, then crossed White Oak Creek and Lagoon Road to its junction with the original transfer line that ran between the main plant area and the pits and trenches (DWG. A-90015-0-063-F REV. 5 - 8/4/81). The line was constructed of two-inch mild steel with mechanical joints and was routed underground in the same trench with the six-inch diameter mild steel process waste

line (L.C. Lasher, Personal Communication - June, 1987). This older section of LLW line was reportedly replaced in 1973 with a cathodically protected two-inch stainless steel line, portions of which are double contained (F.T. Binford and S.S. Orfi - 1979). The new line follows a more direct route to the main plant area by crossing over Haw Ridge (Figure 4-1). The original sections of piping from the HFIR and TRU facilities that carried waste to the collection tanks were three-inch and two-inch lines, respectively. These lines were buried in the same trench as the six-inch process waste line (L.C. Lasher - Personal Communication, June, 1987).

4.1.2b The Melton Valley Drive Leak Site

This incident was recorded in a Reactor Operations and Radioactive Waste Operations quarterly report for April-June, 1960, and presumably occurred during this time period. The incident was actually not a leak but was a break, probably in the original two-inch transfer line that led to the pits and trenches area, not in the line that connected the Melton Valley pumping station to the main plant area (Personal Communication - L.C. Lasher, June, 1987). The break was caused by the operation of heavy equipment, however no wastes were being transferred at the time the line was damaged. The break's location was near the 7500 bridge where the line crosses White Oak Creek. The quarterly report states that an inspection of the line at this location "indicated that there may have been other potential leaks in the line". Aside from repairing the line there is no record of any remedial measures taken at this location.

4.1.2c Melton Valley Drive And SWSA 5 Access Road Leak Site

This leak occurred on July 9, 1970 during a transfer of waste from Melton Valley to the tank farm (T.J. Burnett - July, 1970). The leak site is located south of Melton Valley Drive

and just west of the entrance to the SWSA 5 access road (Figure 4-1). The leak was described as "...liquid coming out of the ground and running west along the shoulder of the road and southwest in the grass" (J. Burden - July, 1970). It was estimated that approximately two hundred square feet were contaminated and activity readings ranged from 200-300 mR while alpha activity was greater than 100,000 c/m. Over the next few days contaminated pavement and soil were excavated and disposed of by burial. The transfer line was then exposed and a neoprene gasketed pipe joint was determined to be the source of the leak. The faulty joint was repaired and pressure tested; and as a precautionary measure, the next joints eastward were given a visual inspection and pressure tested. No further leaks were found and restoration of the area was completed (T.J. Burnett - July, 1970).

Another leak site in the same general area is indicated in DWG. A-90015-0-063-F REV. 5, issue date 8-4-81. The site is located about three hundred feet east of the previously described site on the northern side of Melton Valley Drive and is labeled on Figure 4-1 as Undocumented Leak Site. Written documentation for this site was not found during the literature search for leak sites.

Other leak sites without written documentation may have occurred. In general, leaks occurred at the mechanical joints in the transfer line during the late 1960's to early 1970's. The leaks frequently took place during an LLW transfer and were identified by observation of liquid at the ground surface or by volume discrepancies. Typically the waste and some contaminated earth were cleaned up by excavation to residual levels of about .5 mR/hr (Larry Lasher - Personal Communication - June, 1987).

4.1.2d 7500 Area Leak Site

Intra-Laboratory Correspondence dated August 14, 1969 by T.J. Burnett documents this leak site as follows:

"On July 21, 1969, at approximately 3:00 p.m., a leak (visible as seepage out of the dirt bank) was discovered in the intermediate-level liquid waste transfer line which serves the Melton Valley area. The leak was located between Building 7500 and Building 7503 alongside the ditch immediately on the north side of Melton Valley Drive. An analysis of a sample of the liquid showed 2×10^5 alpha dis/min/ml, and 10^5 beta, gamma dis/min/ml, identified as predominantly ^{244}Cm and fission products. The total volume of the leak was estimated at 2,100 gallons. Most of the activity appeared to have been absorbed in the earth since waste samples in the lower elevations showed very low counts in comparison.

Action to remove the high level contaminated dirt to the burial ground was promptly initiated. After most of the high level contamination was removed from the area, the leak was repaired on July 25, 1969. The major part of the contaminated earth was removed by July 28, 1969, and replaced. Some low-level contamination still remains in the swampy area on the south side of Melton Valley Drive, but the area has been posted with radiation signs and should present no particular problems."

The above description does not positively identify the leak site location, however the heading on this correspondence gives the location as "Near Bldg. 7500". It is presumed that this description fits the leak site location shown in Figure 4-1 which location was digitized from DWG. A-90015-0-063-F REV. 5, issue date 8-4-81.

4.1.2e Leak Site West Of Melton Valley Pumping Station

On January 15, 1971, a leak developed while waste was being transferred from Melton Valley to the tank farm. The affected area, about one hundred square feet located west of the pumping station, was cleaned up by excavation. The Radioactive Waste Disposal Operations Report dated March 22, 1971 states that "there was no spread of contamination outside the immediate area and no contamination of personnel nor exposures beyond normal working limits".

Additional written documentation for this site was not found in LLW incident reports, operations division reports, nor health physics log books. However, based on review of drawing DWG. A-90015-0-063-F REV. 5 and discussions with L.C. Lasher, the location shown in Figure 4-1 best fits the available documentation.

4.1.2f Building 7920 And Melton Valley Pumping Station Leak Site

AND

4.1.2g Building 7920 Ditch Line Leak Site

These two leak sites are probably the same event although an earlier inventory of line leak sites (H.J. Grimsby - 1986) identifies them as separate incidents. The assertion that the two sites are actually one and the same is supported by their written descriptions which are presented in unabridged form below:

Building 7920 and Melton Valley Pumping Station Leak Site
Documentation: Intra-Laboratory Correspondence dated
September 15, 1970 by T.J. Burnett

"Time: Approx. 3:00 p.m.

Date: 7/31/70

Place: Road Side Ditch, West
of Building 7920

Subject: Leakage of Waste Transfer Line

A release of liquid waste from a junction flange contaminated a drainage ditch and adjacent soil surface west of Building 7920. This was observed by two employees alerted by PRM signals. Shoe and floor contamination was minimal. With appropriate precautions the area was subsequently excavated and decontaminated without significant exposure or contamination of personnel. Despite repairs effected, the use of this waste transfer line was discontinued due to unsatisfactory pressure test results. Additional details are given below.

On Friday afternoon, July 31, 1970, W. D. Burch, PR No. 7941, and J. L. Matherne, PR No. 7713, both with the Chemical Technology Division, were approaching Building 7920 on the access sidewalk. Being alerted to an unusual condition by PRM signals, they noted visible quantities of liquid on the soil surface and in a drainage ditch near the roadway west of Building 7920. Both men found their shoes contaminated when they reached the building and notified Health Physics.

The subsequent survey and investigation disclosed gross contamination in the outside area. Soil surface contamination ranged up to 10^5 alpha d/m and approximately 30 mrad/hr at six inches; edges of the road surface and spots on the sidewalk up to 8×10^4 alpha d/m. No significant contamination was found in Buildings

7900, 7910, 7920, or the parking area. Some transferable contamination (up to 300 alpha d/m) was found in Building 7930. A sample of the liquid in the ditch was taken and analyzed by T. G. Scott, PR No. 11404. The results showed 1.1×10^5 alpha d/m/ml, and the activity was identified as ^{244}Cm . The beta, gamma component was identified as ruthenium.

The ditch was filled with crusher-run stone to absorb and immobilize the liquid. All contaminated areas and the rock fill surface were then sprayed with asphalt to prevent weathering over the weekend. Samples from Melton Branch and White Oak Lake were analyzed at increased frequencies over the weekend. The results indicated that the quantity of material reaching the lake would present no problem.

Decontamination of floors in Building 7930 was accomplished on the following Monday, August 3, 1970. Cleanup of the contaminated ditch and surrounding areas was initiated on the same date.

Although repairs were effected, the results of pressure tests of the line were unsatisfactory and it was decided to discontinue its use. Final cleanup restored all accessible areas to an uncontaminated status except for the interior of a culvert under the road between Buildings 7920 and 7930 which has been suitably marked with a plaque. External exposures received by those performing decontamination and/or repair work were well within permissible limits. Bio-assay samples to determine internal exposures to those directly engaged in the work were requested but the results are not available as of this writing."

Building 7920 Ditch Line Leak Site

Documentation: The Tabulation Of Contaminated Ground Areas In
ORNL, Bethel Valley And Melton Valley
Facilities General Engineering Division
document dated January 31, 1972, revised
August 8, 1975

"A leak in the ILW line from Bldg. 7920 contaminated the ditch line along the high flux isotope reactor access road. The liquid from this leakage crossed under the road through the culverts and flowed along the natural drainage parallel to Melton branch circle in a southerly direction."

The latter description is firmly tied by the Engineering Division's leak site numbering system to a location given in DWG. A-90015-0-063-F REV. 5; this location is shown in Figure 4-1. The record shows only one leak site in the general vicinity of Building 7920. This location also corresponds to L.C. Lasher's estimated location of the Building 7920 And Melton Valley Pumping Station Leak Site. Because of the circumstances described above and because of the similar written site descriptions, it would appear that the two sites are actually one.

There is a seventh leak site identified on DWG. A-90015-0-063-F REV. 5. Written documentation for this site was not found in the available literature. However, L.C. Lasher believes that the leak occurred where the discharge line exited the Melton Valley Pumping Station pumphouse. The location of this leak site is given in Figure 4-1 and is labeled Undocumented Leak Site 2.

4.1.3 Active LLW Tanks

There are four underground tanks which are used to collect low level wastes in Melton Valley. Each tank is equipped with a sampling device, liquid level instrumentation and a filtered vent to the atmosphere or to the off gas system of the facility it serves. Three of the tanks (T-1, T-2 and the HFIR tank) are singly contained units which rest on concrete pads fitted with a sump which has a sampling portal. These tanks are surrounded by gravel backfill and covered with earth. The remaining tank is double contained.

4.1.3a LLW Collection/Storage Tank WC-20

Tank WC-20 is doubly contained with a concrete vault and has a built-in sump which is equipped with a pump. The tank is located about two hundred and fifty feet northwest of Building 7503 on the northern side of Melton Valley Drive and the top of the tank is buried about seven and one-half feet below grade. The tank has a diameter of ten feet, a length of nineteen and one-half feet and a volume of ten thousand gallons (MCI, 1985). Tank WC-20 receives wastes from Building 7920 and discharges the wastes to Building 7567 where they are pumped to the south tank farm in Bethel Valley.

4.1.3b LLW Collection/Storage Tank (HFIR)

The HFIR tank is located about one hundred and sixty feet southeast of Building 7900 and the top of the tank is buried about nineteen feet below the ground surface. With a capacity of thirteen thousand gallons, the tank is eight feet in diameter and thirty-five feet in length (MCI, 1985). This tank collects LLW from Building 7900 through a six-inch diameter stainless steel line. The HFIR tank discharges to tanks T-1 and T-2 through a three-inch diameter cast iron, mechanically jointed line.

4.1.3c LLW Collection/Storage Tanks T-1 and T-2

These tanks are located southwest of Building 7567 (Figure 4-3) and are buried about six and one-half feet deep (depth to top of tanks). Both tanks have the same capacity (15,000 gallons) and have the same dimensions (10 feet in diameter and 27.5 feet in length). The tanks are operated alternately to collect wastes from Buildings 7500, 7502, 7503 and the HFIR tank via three-inch diameter cast iron mechanical joint lines. The wastes are discharged to the central pumping station from which they are pumped to the south tank farm in Bethel Valley (MCI - 1985).

4.1.4 Other Facilities

4.1.4a Hydrofracture Experimental Site 2, Soil Contamination

The second hydrofracture experiment took place in the southwestern corner of WAG 8 (Figure 4-1). The experiment was conducted in September, 1960 and determined such factors as pressures achieved in the fracture zone, the effects of friction losses on pumping efficiencies, the feasibility of multiple injection zones, the extent of surface uplift and the orientation of the grout sheets.

The experiment was begun by drilling a three-inch diameter observation core-hole 1,050 feet deep about 30 feet west of the proposed location of the injection well (W. de Laguna, et al. - 1968). The core-hole was cased and grouted to a depth of about 890 feet. Below this depth a small diameter pipe string, perforated at one-foot intervals, was set to the core-hole's completion depth. The injection well was also drilled to a depth of 1,050 feet and a four-inch casing was grouted in place. A slot was cut in the casing at 934 feet and the fracture initiated with water. After about 850

FIGURE 4-3

WAG 8 LOCATION OF LLW COLLECTION / STORAGE
TANKS T-1 & T-2

FIGURE ADAPTED FROM THE ORNL COMPUTER LLW ATLAS

APPROX. SCALE: 1" = 14'

to 900 gallons of water had been pumped, the fracture intersected the nearby observation well. Subsequently, the water was bled back out of the injection well and the injection of grout begun. A mixture of water, cement and bentonite (91,567 gallons) tagged with twenty-five curies of ^{137}Cs were injected into the fracture zone (W. de Laguna, et al. - 1968). Upon completing the injection the well was plugged with a neat cement grout extending upward to a depth of 700 feet.

The grout was allowed to cure for six days then a second slot was cut in the casing at a depth of 694 feet. A fracture was again initiated with water by injecting about 10,300 gallons over a period of two days. On the second day of fracturing (September 10, 1960) 132,700 gallons of grout tagged with twenty-five curies of ^{137}Cs were injected into the fracture zone. Later, an array of twenty-four core-holes were drilled around the injection well. Geophysical logs of the core-holes indicated that the grout sheets generally followed bedding although there was a tendency for the grout to break upward as it moved away from the injection point (W. de Laguna, et al. - 1968).

The literature search for the second hydrofracturing experiment found no documentation of surface soil contamination at this site. However, the following excerpt from W. de Laguna, et al. suggests that some contamination may have occurred:

"The mixes used in the two injections of the second experiment were not designed, however, to retain all the water; in fact, later work shows that the solids would settle in such a mix, leaving clear water on top after the cement had hardened. The first core-hole, but only the first, drilled into the upper grout sheet six to eight weeks after the injection flowed slowly for a long time".

It is not clear from this description if the flow was contaminated, and if it was, if it was contained or cleaned up. The present status and exact location of the first core-hole is not known, although the injection well has reportedly been covered over by a road (ORNL RCRA Facilities Assessment, 1987).

4.1.4b Hazardous Waste Storage Facility 7507

This building is located south of Melton Valley Drive and just west of Building 7503 (Figure 4-1). The structure was erected in the 1950's and encloses approximately 1,400 square feet. In the early 1980's the building was converted to a hazardous waste storage facility. The conversion included construction of a 6-inch concrete dike to contain seepage in the event of a leaking container (Personal Communication, Butch Edgemon, June, 1987). Building 7507 stores a variety of hazardous wastes segregated into storage bays by hazardous characteristic, e.g., oxidizer, poison, corrosive.

Presently this facility operates in accordance with RCRA interim status standards as a hazardous waste storage facility. ORNL personnel conduct daily inspections of Building 7507 and state and federal regulatory personnel conduct periodic compliance inspections. A recent federal inspection conducted in March, 1987 noted no deficiencies (EPA Inspection Report, March, 1987). This facility is scheduled to be replaced during the summer of 1987 by a newer storage facility permitted in accordance with RCRA.

4.1.4c Mixed Waste Storage Pad 7507W

The Mixed Waste Storage Pad is located just west of Building 7507 (Figure 4-1). This facility is a concrete pad about 40 feet by 40 feet in area surrounded by a concrete dike. The pad is sloped to drain towards its center where a sump with an

estimated 60 gallon capacity (Personal Communication, Butch Edgemon, June, 1987) catches rainfall and potential leakage from waste containers. The sump's contents are periodically analyzed for contamination (a contingency plan to sample the sump contents after a leaking container is observed is also in force) and at the time of this writing no contaminants have been detected (Personal Communication, Butch Edgemon, June, 1987).

This facility receives ORNL mixed wastes which meet the definition of hazardous waste and which are co-contaminated with radioactive materials (principally scintillation fluids). The wastes are contained in 55 gallon drums which are covered with a tarp. There have not been any documented releases to the environment from this facility and it is scheduled to be replaced by a new storage facility late in the summer of 1987.

4.1.4d Sewage Treatment Plant 7904

The 7900 area sewage treatment plant is located about 200 feet south of Building 7900 (Figure 4-1). This solid waste management unit was a small package plant designed by EIMCO Engineering for aerobic digestion of sewage. The plant consists of a 7,500 gallon capacity in-ground collection tank and digester as well as an operations building which houses the switch boxes and some piping (Personal Communication, Vern Carmony, June, 1987).

The tank is of metal construction and is fitted with cathodic protection. It has an exterior coating of coal tar primer and coal tar enamel with asbestos felt and it is finished with a single layer of Kraft paper. The tank was installed in 1962 by Rust Engineering.

The package plant began operations in 1962, but its discharge did not meet the environmental standards established in the

early 1970's. In 1977, the plant's digester was shut down although the collection tank continues to be used as a collection point for sewage from the 7900 area. Currently a tank truck is stationed beside the collection tank and receives waste transferred by float-tripped pumps. The truck then transports the waste to the sewage treatment plant in the main plant area, making an average of 11 trips per month.

The tank itself is not known to leak; however, after a heavy rain the liquid level in the tank rises, suggesting that the piping may leak (Personal Communication, Vern Carmony, June, 1987).

4.1.4e Silver Recovery Process

The Silver Recovery Process is located in a prefabricated metal building (Number 7934) just west of the TURF facility (Figure 4-1). The recovery process treats about four hundred gallons of photographic waste per week which is generated by the ORNL, Y-12 and K-25 facilities (Personal Communication, Mike Morris, June, 1987). The subject facility recovers silver from photographic waste solutions by a batch-type chemical process. Sodium hydrosulfite and sodium hydroxide are added to the waste solution and heated in a two hundred gallon reaction tank. This causes the silver to precipitate and the supernatant is filtered into a pH adjustment tank. The silver precipitant is dewatered by centrifuge then sold to a contractor for further reclamation and resale. The supernatant is transferred to the main wastewater treatment plant and gradually released into the system. No releases to the environment have resulted from operation of this facility.

4.2 Topography

For descriptive purposes, it is convenient to divide WAG 8 into three sections, a main portion containing the 7900 area

and two northern sections that encompass the LLW transfer lines and their ancillary equipment.

The main portion of WAG 8 is located on a hill (graded by past construction activities) located just north of Melton Branch. The hill ranges in elevation from 790 feet near Melton Branch's floodplain to about 845 feet on the areas graded by construction. West of the hill, the site is dissected by two draws that carry drainage towards Melton Branch. The floor of the westernmost draw has been raised an estimated ten to fifteen feet by past fill operations (refer to Section 4.1 of this report).

North of the main portion of the site, the WAG boundary encompasses the route of the HFIR and TRU LLW transfer lines and it extends north through a natural drainageway between two hills. The WAG boundary then splits into two "legs" at the base of Haw Ridge. These "legs" follow the routes of both the active and the abandoned Melton Valley LLW transfer lines. One "leg" bears west, along the base of Haw Ridge, gradually losing elevation (from about 840 feet to 775 feet with slopes of less than 10 percent) as it approaches White Oak Creek. This "leg" of the site crosses White Oak Creek and ends on the creek's western side.

The other "leg" of the site extends to the north across Haw Ridge. This portion of the site begins at an elevation of about 840 feet at the base of Haw Ridge then proceeds up slopes ranging from 12 to 20 percent. The WAG boundary crosses the crest of the ridge at an elevation of about 1,020 feet then follows along the side of a draw down to where Haw Ridge gives way to the floor of Bethel Valley. The overall relief across WAG 8 is about 245 feet ranging from an elevation of 775 feet near the floodplain of White Oak Creek at the site's western extremity to about 1,020 feet on the crest of Haw Ridge.

4.3 Soils

The soils in WAG 8 are derived (i.e., are residual in origin) from three different geologic units; the Conasauga shale, the Rome Formation and the Chickamauga limestone. Accordingly, the following soils descriptions are grouped by geologic unit. Detailed soils information was available for Conasauga-derived soils and to a lesser extent Chickamauga derived soils. However, due to a distinct lack of information for Rome-derived soils, these materials are only given very general treatment.

The Conasauga soils in WAG 8 have been described in drill logs from the recent piezometer installation program as reddish-brown to brownish-gray silty clays containing shale fragments and in one instance root horizons. In the 7900 area, the drill logs document the presence of fill material consisting of clayey soils containing gravel and wood. The lateral extent of the fill has not been defined, but it is presumed to be associated with areas of past building and road construction. In undisturbed areas, soil depths apparently ranged from 10 to 18 feet. The role that clay minerals play in selectively retarding the migration of waste constituents (refer to Section 3.3) can also be expected to be an active factor in WAG 8.

Additional information for Conasauga soils in the vicinity of the 7900 ponds is available from a RCRA monitoring well installation report (MCI - March, 1986); excerpts and diagrams from this report follow.

"The soil and weathered bedrock sampled at the 7900 area consisted primarily of medium dense, orange to brown to gray silty clay with chips of weathered shale and occasional laminae of highly plastic blue, yellow and tan clay. A few lenses of weathered, sandy siltstone, approximating an inch in thickness were also noted.

Interlayered with the clay were variably weathered shale strata which sometimes were highly contorted, and unweathered to slightly weathered limestone lenses, typically less than one foot in thickness. The shale was bluish-gray in color, although a few maroon strata were observed. Iron stains, indicating groundwater movement, and black mottling were frequently observed on bedding planes and fracture faces of the shales. Larger cuttings of the bluish-gray, fine-grained limestone frequently contained calcite-filled fractures, which cut across the bedding planes."

Wood fragments and rootlets, observed in borings 33003 and 33002 at depths of approximately eight feet, indicate that these areas may contain fill material. These drill hole locations, and others, are shown in Figure 4-4. Drill logs for all of the borings excepting 32004 are shown graphically as part of a fence diagram for the 7900 area in Figure 4-5. Boring 32004 was part of a second phase of drilling and its log is shown in Figure 4-6.

Soils derived from the Rome formation have been described by J. Rodgers, 1953 as follows:

"The different rock types of the Rome formation weather differently, but ordinarily the sandstone and siltstone beds dominate the residuum and soil, which is only a shallow mantle full of rock chips. The carbonate rocks weather more deeply and locally form bodies of yellow, generally silty clay with a red-brown soil layer."

Field observations corroborate this description although there is a general lack of detailed field work for soils derived from the Rome formation.

NOTES

1. * indicates Phase I wells.
2. • indicates Phase II wells.
3. Well locations are approximate, not surveyed.
4. See Exhibit 3 for the wells' 5-digit map number.

FIGURE 4-4

**WAG 8 RCRA MONITORING WELL
BORE-HOLE LOCATIONS 7900 AREA**
FIGURE ADAPTED FROM THE RCRA MONITORING
WELL INSTALLATION REPORT SURFACE
IMPOUNDMENTS 3524, 3529, 3540, 7905, 7906, 7907,
AND 7908

**LOCATIONS OF RCRA MONITORING WELLS
7900 PERMIT AREA
OAK RIDGE NATIONAL LABORATORY
OAK RIDGE, TENNESSEE**

SCALE: 1" = 100'

**PREPARED FOR
MARTIN MARIETTA ENERGY SYSTEMS, INC.**

MCI/CONSULTING ENGINEERS, INC.
NASHVILLE KNOXVILLE HUNTSVILLE LOUISVILLE

PROJ 2279430 DATE 3/19/86 SHEET 1 OF 1

13-
810.0 ▽

19

32-003
EL 806.4

1	2	3
2-4-6-8	10-22-30-20	10-22-32-18/17

CL, SLTY W/CHT GVL & IRON ST, ORNG-BR.

CL, HD, FRBL W/IRON ST, YEL,
& WEA SH, HD, THIN BED, DRY.

SURF

5-25-35-15 SAT LZ of SOY SH/SLTST.

LS, MED GR-BLSH GR, F GRND, HD W/CALCITE VEINS,
INT RBD W/CALC SH, BLSH-GR W/OCC LZ of CL.
SAT ZNS at 10.2 & 240.

43-7-9

784.5

80/1.5

80/1.5

80/2.5

80/3.5

80/3.5

784.8

ESTIMATED TOP OF WEATHERED BEDROCK

TTTS, MST & SH

BLSH & ORNG

ST W/
ENCL, MST.

4

33-002
EL 8038

33-002
EL 8038

NOTES:

- 1) 4-8-9-12 ARE
- 2) ▽ INDICATES
- 3) THE ESTIMATE BY THE WAY WHICH THE

32-001
EL. 813.8

SH, V WEA, SLTY, YL SH - BR W/IRON ST
W/LZ of HIGH PL CL, DRY.

SH, WEA, SLTY, GR-YL SH BR, W/IRON ST & MOTTS
W/LZ of HIGH PL CL, W/LZ of SDY SLTST, MST.

SAT LZ of SDY SH/SLTST.

LS, MED GR-BL SH GR, F GRND, HD W/CALCITE VEINS,
INTRBD W/CALC SH, BL SH-GR W/OCC LZ of CL.
SAT ZNS of 16.2 & 24.0.

7955

ESTIMATE

SURFACE

GROUND

APPROXIMATE

TOP

A, BLSH GR, FSL, NO IRON ST, DRY.

H GR.

- 1

FIGURE 4-5

WAG 8 FENCE DIAGRAM AND DRILL LOGS FOR THE 7900 AREA RCRA MONITORING WELLS

FIGURE ADAPTED FROM THE RCRA MONITORING WELL INSTALLATION REPORT SURFACE IMPOUNDMENTS 3524, 3529, 3540, 7905, 7906, 7907, AND 7908

OAK RIDGE NATIONAL LABORATORY
OAK RIDGE, TENNESSEE

SCALE: AS SHOWN

PREPARED FOR:

MARTIN MARIETTA ENERGY SYSTEM

MCI/CONSULTING ENGINEERS,
NASHVILLE KNOXVILLE HUNTSVILLE LOUIS

PROJ. 2279430

DATE 3/19/86

SHEET 01

LEGEND

1 - BORING NUMBER

32-001 - MAP NUMBER OF WELL

EL. 813.8 - GROUND ELEVATION OF WELL

SAMPLE NUMBER

LITHOLOGIC SEPARATION

GROUNDWATER ELEVATION

4-8-9-12

810.0

2 A 2-FOOT SPLIT BARREL SAMPLER.

EV. ON JANUARY 3, 1986.

LY WEATHERED BEDROCK WAS DETERMINED
OW COUNTS AND THE DIFFICULTY WITH

ABBREVIATIONS

abu - abundant
bed - bedded
blk - black
blsh - bluish
bp - bedding plane
br - brown
calc - calcareous
cht(y) - chert(y)
cl(y) - clay(ey)
cnch - conchoidal
cntc - contact
cntd - contorted
d - dense
dk - dark
d.o. - ditto
dpth - depth
f - fine
fld - filled
foss - fossils
frac(s) - fracture(s)
fracd - fractured
frag(s) - fragment(s)
frbl - friable
frm - firm
fls - fissile

gr - gray
grnd - grained
gvl - gravel
hd - hard
incl - inclusions
intrbd - interbedded
lgt - light
ls - limestone
lz - lenses
mat - material
med - medium
mrn - maroon
mst - moist
mott - mottles
occ - occasional
opn - openings
org - organic
orng - orange
pl - plastic
plb - pliable
rdsh - reddish
recd - recovered
rk - rock
rts - roots
sat - saturated

sbsl - subsoil
scatt - scattered
sd(y) - sand(y)
sh(y) - shale(y)
sl - slightly
slks - slickensides
slst - siltstone
slt(y) - silt(y)
soln - solution
ss - sandstone
st - stains
strg(s) - stringer(s)
styl - stylites
svrly - severely
tpsl - topsoil
trvs - transverse
undl - underlain
v - very
vert - vertical
w/ - with
wea - weathered
yel - yellow
ylsh - yellowish
zn(s) - zone(s)

-96-

GROUND SURFACE (803.6)

WELL NO. 32-004
LOCATION HFIR
SCALE: 1" = 5'

SOIL & SUBSOIL - CLAY, REDDISH-BR, PLASTIC, HARD,
MOIST W/ LS & CHERT CHIPS THROUGHOUT, OCC
WOOD FRAGS THROUGHOUT

ELEVS. SHOWN IN
PARENTHESIS ARE
MEAN SEA LEVEL

14.0

SH & LS INTERBEDDED

LS - MED GRY, FRIABLE, OCC CALCITIC, FE
STAINS, WEATHERED, MED HARD

SH - LT TO MED GRY, SOFT, FRIABLE,
WEATHERED, SLICKENSIDES THROUGHOUT

EXHIBIT 8 A

51.0 (752.6)

FIGURE 4-6

WAG 8 DRILL LOG RCRA MONITORING
WELL 32004

FIGURE ADAPTED FROM THE RCRA MONITORING
WELL INSTALLATION REPORT SURFACE
IMPOUNDMENTS 3524, 3539, 3540, 7905, 7906, 7907,
AND 7908

MCI/CONSULTING ENGINEERS, INC.
NASHVILLE KNOXVILLE HUNTSVILLE LOUISVILLE

The soils on the portion of WAG 8 that is underlain by the Chickamauga Limestone are probably a mixture of colluvium from the slopes of Haw Ridge and residuum derived from the Chickamauga. Drill logs from piezometers installed in the vicinity of the subject area characterize the soil and residuum as medium brown to gray silty clays with gravel disseminated throughout; locally there are zones of abundant chert fragments. Soil depths from the nearby piezometer borings ranged from one foot at higher elevations to about seven feet at lower elevations. This relationship of soil depth relative to topographic position is the reverse of what is generally expected for Chickamauga soils and may reflect the accumulation of colluvium at the base of the slopes.

Clay mineral constituents of the Chickamauga's residual soils are predominantly kaolinite and illite, although some of the individual units within the Chickamauga weather to form a clay containing a significant montmorillonite component (Webster, 1976). Kaolinite and montmorillonite have their own unique capacities for retarding waste constituent migration by the same mechanisms previously described for illite and vermiculite in Section 3.3. Averaged distribution coefficients (k_d) of several radionuclides for kaolinite and montmorillonite are summarized in Table 4-5 (Webster, 1976). These k_d values are based on standard clays tested under laboratory conditions and may not be representative of field conditions.

TABLE 4-5

WAG 8
Average kd Values
Excerpted from Webster, 1976

<u>Clay Mineral</u>	<u>kd Values by Element</u>			
	Cs	Co	⁸⁵ Sr	⁹⁵ Zr-Nb
Kaolinite	2,200	3,100	4,000	56,000
Montmorillonite	1,000	1,700	2,100	540

The values reported above are for standard kaolinite and montmorillonite clays which were tested under laboratory conditions. Therefore, these values should not be construed as representative of field conditions.

4.4 Geology

According to a recently drafted geologic map (1987) prepared by Ranaye Dreier and Kathleen Boedoin - Martin Marietta Energy Systems geologists, WAG 8 is underlain by three geologic units (Figure 4-7). Traversing the site from south to north these units and their members which are present beneath the site are:

Unit I. The Conasauga Group

1. Nolichucky Shale
2. Maryville Limestone
3. Rogersville Shale
4. Rutledge Limestone
5. Pumpkin Valley Shale

Unit II. The Rome Formation

Unit III. The Chickamauga Limestone

1. Unit H (Stockdale's nomenclature, 1951)
inclusive of the Moccasin limestone (Campbell's nomenclature for equivalent beds in Scott County, Va. 1894).

E33000

TRUE GRID NORTH
ORNL

NORTH

34°12'51"

N20000

WAG 8 ———
BOUNDARY

NOTES:

1. TOPOGRAPHY DIGITIZED FROM A BASE MAP PREPARED BY ACCU-AIR SURVEYS, INC. SEYMOUR, INDIANA - WHITE OAK CREEK WATERSHED MAP SERIES. PHOTO DATE 3/29/78, MSL DATUM 1929.
2. TOPOGRAPHIC AND SITE SPECIFIC INFORMATION PROVIDED BY MARTIN MARIETTA ENERGY SYSTEMS, INC.
3. LOCATIONS OF LOW LEVEL WASTE LINES (LLW) ARE APPROXIMATE AND WERE DIGITIZED FROM AN ORNL ATLAS MAP "MELTON VALLEY (DRAFT)" DATED 8/13/85.
4. GEOLOGIC CONTACTS BASED ON WORK BY RANAYE DREIER AND KATHLEEN BOEDDIN - MMES GEOLOGISTS.

-LEGEND-

BUILDING		CHICKAMAUGA LI
STREAM		ROME FORMATION
POWER POLE		PUMPKIN VALLEY
SECONDARY ROAD		RUTLEDGE LIMEST
CONTOUR INTERVALS 5 FEET		ROGERSVILLE SHA
LOW LEVEL WASTE LINE (LLW)		NOLICHUCKY SHA
LLW LINE DOUBLE CONTAINED SECTION		MARYVILLE LIMES
		GEOLOGIC CONTA
		COPPER CREEK 7
		FAULT
		SUSPECTED TEAR

FIGURE 4-7

WAG 8 GEOLOGIC MAP

SCALE: 1" = 200'

MARTIN MARIETTA ENERGY SYSTEMS

D
C
A
D

+

+

ONE Och
 Cr
 1LE Cpv
 Crt
 Crg
 Cnl
 Cm

IST ▼-----▼

ULT ?-----?

Enl

N16000

MCI
Consulting Engineers, Inc.

NASHVILLE KNOXVILLE HUNTSVILLE LOUISVILLE

Unit I

Detailed descriptions of the lower four members of the Conasauga Group have already been given (reference Section 3.4 of this report). According to C.S. Haase, et al. - 1985, the Nolichucky shale on the Oak Ridge Reservation can be divided into an upper member, a middle member (designated the Bradley Creek member which occurs in the upper 100 feet of the formation on the Reservation) and a lower member. The upper member is composed of coarse grained limestone and evenly bedded mudstone interstratified with siltstone. The limestone has fine-bedding laminae, resulting in a ribboned appearance. The Bradley Creek is predominantly a coarse grained, algal limestone interbedded with shaley fine-grained limestone. Both lithologies exhibit lenticular bedding. The lower member consists of a complex cyclic sequence of interbedded shale and limestone. The Nolichucky's contact with the underlying Maryville is gradational.

Unit II

The report by Haase, et al., 1985, also provides a detailed description of the Rome Formation which is summarized below. The report presents core-hole data for the Copper Creek thrust block on the Oak Ridge Reservation which indicates that the Rome Formation is about 617 feet thick. The thickness data must be qualified because the lower portion of the Rome Formation is terminated by the Copper Creek fault probably providing an incomplete section. There are also several lesser faults which may have caused some stratigraphic intervals to be repeated or removed. In either case, Haase has divided the Rome Formation into a lower section (328 feet thick) and an upper section (289 feet thick).

The base of the Rome Formation corresponds with the stratigraphic position of the Copper Creek fault. The fault is characterized by a 3.3 foot thick zone composed of two 7.8

inch mylonites. The fault zone also marks a change in lithology and attitude of bedding. Above the fault zone, lithologies characteristic of the Rome Formation exhibit highly variable and steep dip angles, while below the fault zone lithologies of the Chickamauga limestone exhibit shallow dip angles ranging from 0° to 10°.

The lithology of the lower Rome Formation is similar to that of upper portion, the principal distinction of the lower Rome being its degree of deformation. A preliminary analysis of the structural features of the lower Rome Formation suggests that it may consist of slices and fragments of the lithologies that compose the upper part of the formation. These fragments are so complexly imbricated that it has not been determined which portions of the upper Rome Formation are represented in the lower portion. However, it is possible that a large section of the lower Rome Formation represents severely deformed lithologies that occur stratigraphically below the upper Rome Formation.

The upper Rome Formation consists of about 60 to 80 percent massive to medium-bedded, subarkosic to quartz arenitic sandstones. The remainder of the upper portion consists of medium bedded sandstones and siltstones interbedded with thin-bedded silty mudstones and shales.

Thinly-bedded shaley siltstones and mudstones, about 3 feet in thickness occur nearest the base of the upper section of the Rome Formation. These lithologies may be bioturbated and the siltstone strata locally exhibits upward fining cycles within the mudstone. A massive to thickly-bedded maroon to brownish-gray, subarkosic sandstone also occurs in the Rome Formation. This lithology grades into a thinly-bedded sandstone that alternates with massive to irregularly-bedded maroon sandstones that contain shale rich intervals up to

about 6 inches thick. These intervals exhibit lenticular bedding and may be bioturbated resulting in a mottled appearance. Discontinuous, wavy laminae of maroon mudstone and shaley limestone are disseminated throughout this lithology.

The uppermost portion of the Rome Formation is composed of a massive gray to green quartz arenite. This massive sandstone is interbedded with thinly bedded sandstone which exhibits upward fining cycles with scour bases and mudstone drapes. Wavy shale laminae occur within the upward fining cycles. Locally a dolomitic, shaley sandstone occurs near the top of the Rome Formation and it represents the only significant occurrence of a carbonate lithology observed within the core.

Unit III

The third geologic unit underlying WAG 8 is the Chickamauga limestone - Unit H according to Stockdale's 1951 nomenclature or its equivalent, the Moccasin limestone according to Campbell's 1894 nomenclature. Stockdale described the upper 80 feet of Unit H as: "siltstone, calcareous, gray, olive, maroon; with shaley partings and thin limestone lenses". This is followed by a 180 feet thick sequence of rock described by Stockdale as: "Limestone of varied types, gray olive-gray buff, drab; mostly thin bedded; with argillaceous partings; weathers to shaley appearance; with fossiliferous zones". The lower 35 feet of Unit H was characterized as: "Limestone, argillaceous (calcareous siltstone), gray, olive-gray, "pinkish" maroon; even bedded, with shale partings".

In Haase's core-hole study, only the upper eighty feet of the siltstone rich portion of Unit H occurred. Haase describes the rock as interbedded, calcareous siltstones and shaley limestones. The siltstones are maroon-gray and medium to thinly bedded with wavy to lenticular stratification. The

thinly bedded limestones are gray to maroon micrites, wackestones and calcarenites* with wavy, irregular and lenticular stratification. Localized intraformational conglomerates also occur in the limestone.

The piezometer drill logs in the vicinity of the subject site describe the Chickamauga limestone as crystalline limestone, medium gray to brown/yellow with gray to yellowish shale interbeds. One of the piezometer logs (No. 571) indicates that a 2 foot interval of rock was encountered from 5 feet to 7 feet followed by 7 feet of clay before re-encountering rock. This description suggests that either large fragments of rock may be suspended in the soil or that Unit H is variably weathered and contains clay-filled solution cavities in this area.

4.5 Surface Hydrology

WAG 8 is located in the White Oak Creek drainage basin. Runoff from the main body of WAG 8 enters Melton Branch directly via general sheet runoff and by way of two tributaries. The portions of the site that extend along route of the LLW lines ultimately drain into Melton Branch and White Oak Creek.

Melton Branch flows to the west, roughly parallel to and within about 170 to 240 feet of the southern border of WAG 8. The stream gradient is less than two percent adjacent to the site. A draw, east of the main body of WAG 8, carries

* Micrite - an extremely fine-grained carbonate rock type composed of limey mud.
Wackestone - mud supported limestone containing greater than 10 percent sand size or larger particles.
Calcarenite - a carbonate lithology composed of sand sized grains in a calcite matrix.

runoff to one of the tributaries which flows to the south and joins Melton Branch about 240 feet south of the WAG boundary. This tributary also has a gradient of less than two percent. The other tributary that carries runoff from WAG 8 to Melton Branch flows south from within WAG 8 and discharges about 150 feet south of the WAG boundary. This tributary's gradient is about two and one-half percent. The portion of WAG 8 that contains the Melton Valley pumping station drains via general sheet runoff which is eventually captured by a draw to the west of the site and channeled south towards Melton Branch.

The western extension of WAG 8 that follows the route of the LLW lines also drains via general sheet runoff. This surface runoff is transported to both Melton Branch and White Oak Creek, there being a small drainage divide near the 7500 area (WAG 9). The northeastern extension of WAG 8 follows the LLW line over Haw Ridge; on the south side of Haw Ridge the site drains into Melton Branch, while on the north side of the ridge it drains into White Oak Creek.

4.6 Groundwater

4.6.1 Existing Groundwater Monitoring System

There are eight water quality wells and thirteen piezometers in WAG 8 with four additional piezometers located just outside the site's southern boundary. Details of the piezometer installation program have already been described in Section 3.6.1; the locations of 11 of the WAG 8 piezometers are shown in Figure 4-8. The water quality wells were installed during July, August, October and November 1985, their locations are shown in Figure 4-4 and a typical well construction schematic is given in Appendix II.

E31000

WHITE OAK CREEK

775

800

825

850

875

900

925

1000

1000

975

950

975

1000

E32000

E33000

N20000

WAG 8 —————
BOUNDARY

1031
W.L. 841.9

7508
7500
7505

850

825

875

850

850

825

825

1RY

MELTON

BRANCH

WAG 8 GEOLOGIC MAP

SCALE: 1" = 200'

MARTIN MARIETTA ENERGY SYSTEMS

AI
D.

MELTON

MELTON

NOTES:

1. TOPOGRAPHY DIGITIZED FROM A BASE MAP PREPARED BY ACCU-AIR SURVEYS, INC. SEYMOUR, INDIANA - WHITE OAK CREEK WATERSHED MAP SERIES. PHOTO DATE 3/29/78, MSL DATUM 1929.
2. TOPOGRAPHIC AND SITE SPECIFIC INFORMATION PROVIDED BY MARTIN MARIETTA ENERGY SYSTEMS, INC.
3. LOCATIONS OF LOW LEVEL WASTE LINES (LLW) ARE APPROXIMATE AND WERE DIGITIZED FROM AN ORNL ATLAS MAP "MELTON VALLEY (DRAFT)" DATED 8/13/85.
4. PIEZOMETERS 1032 AND 1034 ARE NOT SHOWN ON THIS MAP BECAUSE THEY HAD NOT BEEN SURVEYED AT THE TIME THIS FIGURE WAS DRAFTED.

-LEGEND-

BUILDING		PIEZ
STREAM		WATE
POWER POLE		PHRE
SECONDARY ROAD		POSS FLOW
CONTOUR INTERVALS 5 FEET		FENC
LOW LEVEL WASTE LINE (LLW)
LLW LINE DOUBLE CONTAINED SECTION

SHEET

OF

FIGURE 4-8

WAG 8 PHREATIC SURFACE MAP PIEZOMETER LOCATIONS

SCALE: 1" = 200'

MARTIN MARIETTA ENERGY SYSTEMS

+ WATER LEVEL ELEVATION		
WELL NO.	ELEVATION IN FEET (MSL)	DATE
657	793.11	JUL
658	808.77	JUL
659	796.28	JUL
660	791.00	L.A. OF
661	794.04	JUL
662	786.41	L.A. OF
663	790.79	L.A. OF
1029	*	JUL
1030	835.42	JUL
1031	841.94	JUL
1033	817.05	JUL

* THE WATER LEVEL IN THE RISER PIPE OF WELL WAS ABOVE THE GROUND SURFACE ELEVATION

WATER LEVEL ELEVATIONS

	ELEVATION IN FEET (MSL)	DATE OF MEASUREMENT
	793.11	JUNE 3, 1987
	808.77	JUNE 3, 1987
	796.28	JUNE 3, 1987
	791.00	LAST WEEK OF MAY 1987
	794.04	JUNE 3, 1987
	786.41	LAST WEEK OF MAY 1987
	790.79	LAST WEEK OF MAY 1987
	*	JUNE 3, 1987
	835.42	JUNE 3, 1987
	841.94	JUNE 3, 1987
	817.05	JUNE 3, 1987

WATER LEVEL IN THE RISER PIPE OF WELL 1029
ABOVE THE GROUND SURFACE ELEVATION OF 858.30.

MCI

Consulting Engineers, Inc.

MADISONVILLE KNOXVILLE MEMPHISVILLE CHATTANOOGA

Water level data from the water quality wells and the new piezometers will be used to evaluate changes in head across WAG 8. It has not been determined whether there are any older wells in existence in WAG 8 and whether or not there is usable data from such wells.

4.6.2 Groundwater Quality

The only source of groundwater quality data for WAG 8 that was discovered during the literature search for this report is the water quality well data base for the HFIR area. This data was obtained from sample analyses of seven of the eight wells described earlier in Section 4.6.1. Table 4-6 compiles the water quality data from June, 1986. These analyses indicate that only well number 33001 exceeded the drinking water standard for any of the metals (chromium at .15 mg/l - the standard being .05 mg/l). Well 33001 is upgradient of the 7900 series ponds and the reason for its elevated chromium content is still under evaluation.

Two of the wells, 33002 and 33003, had gross alpha values (0.66 Bq/l and 2.08 Bq/l, respectively) above the drinking water standard of 0.56 Bq/l. Six of the wells, 32001, 32003, 32005, 33001, 33002, and 33003, exceeded the gross beta drinking water standard and well 33003 exceeded the drinking water standard for radium. Wells 32001 and 33001 are upgradient wells which indicates that there is some form of beta emitting contamination upgradient of the 7900 series ponds, possibly one of the LLW line leak sites. In general, there is a slight decrease in water quality in wells 33002 and 33003 compared to the other wells. This is particularly evident for the parameters nitrate, gross alpha sodium and sulfate, although wells 32005 and 33001 also exhibited elevated sulfate levels and well 33001 exhibited elevated chlorides.

TABLE 4-6
WAG 8
Water Quality Data For Seven Wells In The HFIR Area
(Concentrations Reported in PPM Except As Noted Otherwise)

Parameter	Sample Date and Well Number						
	6/24/86 32001	6/18/86 32002	6/18/86 32003	6/24/86 32005	6/18/86 33001	6/18/86 33002	6/24/86 33003
Specific Conductance, mMHOS/cm (Avg. of Four)	.01	.09	.06	.01	.24	.16	.18
Temperature, Degrees C (Avg. of Four)	17.0	18.0	18.0	17.5	19.75	19.25	20.0
pH (Avg. of Four)	7.40	7.58	7.58	7.40	7.20	7.30	7.23
2,4,5-TP Silvex	<.01	<.01	<.01	<.01	<.01	<.01	<.01
2,4-D	<.01	<.01	<.01	<.01	<.01	<.01	<.01
Endrin	<.0002	<.0002	<.0002	<.0002	<.0002	<.0005	<.0002
Lindane	<.002	<.002	<.002	<.002	<.002	<.002	<.002
Methoxychlor	<.008	<.008	<.008	<.008	<.008	<.008	<.008
Toxaphene	<.005	<.005	<.005	<.005	<.005	<.005	<.005
Fecal Coliform	< 1.0	< 1.0	< 1.0	< 1.0	< 1.0	< 1.0	< 1.0
NO ₃	< 5.0	< 5.0	< 5.0	< 5.0	< 5.0	49.0	57.0
F	< 1.0	< 1.0	< 1.0	< 1.0	< 1.0	< 1.0	< 1.0
Cl	6.1	19.0	2.4	13.0	62.0	16.0	16.0
Phenols	.001	<.001	<.001	.001	.001	<.001	.001
SO ₄	19.0	16.0	5.0	43.0	64.0	72.0	140.0
TOC (Avg. of Four)	0.64	0.72	0.67	0.84	0.65	0.66	0.59
TOX	<.01	<.01	<.01	<.01	<.01	<.01	<.01
Ag	<.005	<.005	<.005	<.005	<.005	<.005	<.005
As	<.01	<.01	<.01	<.01	<.01	<.01	<.01
Ba	< 1.0	< 1.0	< 1.0	< 1.0	< 1.0	< 1.0	< 1.0
Cd	<.002	<.002	<.002	<.002	<.002	<.002	<.002
Cr	<.02	<.02	<.02	<.02	.15	<.02	<.02
Hg	<.0001	<.0001	<.0001	<.0001	<.0001	<.0001	<.0001
Pb	<.02	<.02	<.02	<.02	<.02	<.02	<.02
Se	<.005	<.005	<.005	<.005	<.005	<.005	<.005
Fe	0.05	0.08	0.30	0.36	0.51	0.48	0.24
Mn	0.12	0.07	0.10	0.45	0.08	0.33	0.04
Na	3.30	5.40	3.50	6.50	6.50	18.0	43.0
Gross Alpha Bq/l	0.15	0.079	0.13	0.066	0.067	0.66	2.0
Gross Beta Bq/l	2.0	0.24	0.34	0.45	0.24	11.0	37.0
Ra Bq/l	0.0021	0.067	<.004	0.053	<.005	<.008	1.5

4.6.3 Hydrology

Groundwater level data will be gathered from 17 new piezometers that have been installed in and around WAG 8 (Figure 4-8). Currently, groundwater level data for the last week of May, 1987 and June 3, 1987 is available for eleven piezometers (657, 658, 659, 660, 661, 662, 663, 1029, 1030, 1031 and 1033). Water levels from the remaining piezometers are not available due to lack of a survey datum or incomplete data collection. Areal distribution of the piezometers provides coverage of the southeastern portion of WAG 8 and four isolated points along the abandoned LLW line. The available water level data is shown below in Table 4-7.

TABLE 4-7
WAG 8
WATER LEVEL DATA

<u>Piezometer #</u>	<u>Water Level*</u>	<u>Date of Measurement**</u>
657	793.11	06/03/87
658	808.77	06/03/87
659	796.28	06/03/87
660	791.00	Last Week of May, 1987
661	794.04	06/03/87
662	786.41	Last Week of May, 1987
663	790.79	Last Week of May, 1987
1029	+858.30	06/03/87
1030	835.42	06/03/87
1031	841.94	06/03/87
1033	817.05	06/03/87

*Water level measurements reported in feet above MSL.

**Measurement dates may vary because newly installed piezometers may not be on the routine water level check program.

The piezometers' screened intervals vary in elevation and they monitor water levels in both the residuum and bedrock. Groundwater levels on the southern portion of the site are roughly consistent with the topographic positions of the

piezometers regardless of which aquifer media they monitor. The piezometer drill logs do not indicate the presence of a confining strata. These two factors suggest that there may be hydraulic communication between residuum and bedrock and that groundwater may occur under water table conditions.

A phreatic surface map based on the May-June water level data is shown in Figure 4-8 and a portion of this map is depicted at a larger scale in Figure 4-9. This figure gives an approximation of head changes that occur across the southeastern portion of WAG 8. The spacing of the piezometers and their respective water levels results in a progressively broader separation of the potentiometric isopleths from east to west in the vicinity of the HIFR/TRU basins. This is in sharp contrast to an earlier phreatic surface map (Figure 4-10) that was based on 1986 water level data from seven of the water quality wells. This earlier map shows a similar separation of isopleths progressing from west to east. The differences between the two maps are probably the result of: 1) for the recent map, there are no available water level data in the area where the isopleth separation is broadest, 2) the water quality wells used in the earlier map are more closely spaced than are the piezometers and give a more localized sense of head changes, 3) water level data for the water quality wells was collected during a period of drought, whereas the piezometer data was collected during a period of more normal rainfall, 4) the water quality wells are generally located closer to the 7900 ponds than are the piezometers and as such may be influenced by local recharge from the ponds, and 5) differences in the interpretive approach used in construction of the phreatic surface.

Either map's applicability to the evaluation of groundwater movement is limited by the heterogeneous nature of the residuum and bedrock. Groundwater movement in the residuum may be roughly normal to the potentiometric isopleths as shown by the flow arrows in Figures 4-8 and 4-9; however, it will also

FIGURE 4-9
WAG 8 PHREATIC SURFACE MAP
ENLARGEMENT
 SCALE: 1" = 100'
 MARTIN MARIETTA ENERGY SYSTEMS

be influenced by recharge from the 7900 ponds, changes in permeability in fill areas and relict bedrock features preserved in the residuum. The bedrock aquifer's complex secondary porosity system is believed to be anisotropic and heterogeneous. While groundwater within the bedrock will ultimately flow from potentiometric highs to potentiometric lows, individual flow-paths are probably controlled by fracture and bedding plane orientations.

Hydraulic conductivity values for eight of the piezometers on the southern portion of the site are shown in Table 4-8. These values were obtained by G. Moore - University of Tennessee in the Spring of 1987. Data was collected by injecting a known volume of potable water into an individual piezometer and recording the subsequent decline of the water level through time with a Druck transducer. The data was evaluated by the Bouwer and Rice method for partially or completely penetrating wells.

Hydraulic conductivity values for the eight water quality wells are also presented in Table 4-8. These values were calculated by MCI Consulting Engineers, Inc. in the latter half of 1985. Data collection utilized Well Wizard pumps to draw down the water levels in the wells and after the water levels had stabilized from the evacuation line drain-back, water level measurements were initiated. The measurements were taken at twenty second intervals for a period of 300 to 360 seconds depending on the well's recovery rate. The data from this procedure was also evaluated using the Bouwer and Rice method for partially or completely penetrating wells.

The hydraulic conductivity values calculated for the water quality wells show a higher degree of variability than do those calculated for the piezometers. Sample standard deviation for the water quality wells is 1.1×10^{-4} as compared to 2.0×10^{-5} for the piezometers.

Although the sample standard deviation between the two data sets differs by an order of magnitude, the mean for each population is within the same order of magnitude (8.0×10^{-5} water quality wells, 3.0×10^{-5} piezometers). The variance between the two data sets may be related to natural phenomenon or reflect the fact that the water quality wells were developed and the piezometers were not.

TABLE 4-8
WAG 8
HYDRAULIC CONDUCTIVITY VALUES

<u>Piezometer #</u>	<u>Hydraulic Conductivity-cm/s</u>
658	3.2×10^{-5}
657	4.5×10^{-5}
659	4.3×10^{-5}
660	6.7×10^{-5}
661	3.0×10^{-5}
662	1.74×10^{-5}
663	2.0×10^{-5}
664	2.0×10^{-5}

<u>Water Quality Well #</u>	<u>Hydraulic Conductivity-cm/s</u>
32001	4.2×10^{-5}
32002	9.5×10^{-5}
32003	2.3×10^{-5}
32004	1.0×10^{-4}
32005	5.3×10^{-5}
33001	3.9×10^{-6}
33002	7.0×10^{-6}
33003	3.6×10^{-4}

-114-

Six piezometers have been installed on the northern portion of the site but only four are presently providing groundwater data. Piezometers 1030 (46.5 feet deep) and 1033 (18 feet deep) have water levels below the ground surface while piezometers 1029 (98 feet deep) and 1031 (65 feet deep) exhibited water levels above the ground surface. The artesian pressure in piezometers 1029 and 1031 may be a reflection of their deeper completion depths where they may intercept recharge from the upper elevations of Haw Ridge. However, this is just one possible explanation of the artesian pressure in these piezometers and additional field work will have to be carried out before the cause is determined.

There is an absence of groundwater data for the central portion of WAG 8 and the northern leg of the site that crosses Haw Ridge. In view of this, an estimate of groundwater movement for these portions of the site must be inferred from other sources. The work conducted at the Engineer Test Facility (ETF) provides a detailed study of ground water movement within a geohydrologic environment similar to that of the central portion of WAG 8. The ETF is located on the Copper Creek thrust block and it is also underlain by a structurally deformed unit of the Conasauga Group. It has similar soil depths, ranging from 6 to 30 feet (E.C. Davis, W.J. Boegley, Jr., et al. - 1984). Pump tests were conducted at the ETF which generated elongate cones of depression with the main axis trending along geologic strike. Evaluation of the pump test data indicated increased transmissivity to the east-northeast, roughly coincident with strike, which is consistent with other pump test and dye tracing studies (R.H. Kettle - 1986, D.D. Huff - 1986) conducted in Bear Creek Valley and Bethel Valley. On the basis of this information (and until aquifer tests are conducted in WAG 8), ground water movement in bedrock within the central portion of the subject site is presumed to be to the northeast, roughly parallel to geologic strike.

Groundwater movement in the bedrock forming Haw Ridge is not well understood. The most reasonable approach to discussing this area is in the general terms of the conceptual model described in Section 2.2.3. If the Rome formation has developed a fracture controlled secondary porosity system, then Haw Ridge may supply recharge to the adjoining valleys; piezometers 1029 and 1031 may suggest this. Melton Valley would be the principal recipient of deep recharge because the Rome formation dips to the southeast beneath this valley. Bethel Valley could potentially receive recharge from groundwater flow along the soil-bedrock interface. However, flow along the soil bedrock interface would be minimal because the Rome's residuum is probably too thin to support a significant residuum aquifer. Recharge to Bethel Valley via groundwater communication across the Copper Creek fault is dependent on the permeability of the fault zone which has not been determined in the area of WAG 8.

The small portion of WAG 8 (the northernmost extension of the LLW line) that is underlain by the Chickamauga Limestone is very close to Solid Waste Storage Area (SWSA) 1. Groundwater levels (Table 4-9) in the vicinity of SWSA 1 are monitored by four piezometers which are also the only source of groundwater data for the northernmost extremity of WAG 8.

TABLE 4-9
WAG 8/SWSA 1
WATER LEVEL DATA

<u>Well No.</u>	<u>Water Level</u>	<u>Date of Measurement</u>
569	772.62	11/17/86
570	774.16	11/17/86
571	779.01	11/17/86
580	783.30	11/17/86

-116-

A phreatic surface map based on this data depicts a hydraulic gradient of about 5 feet/100 feet and suggests that groundwater movement is to the north (Figure 4-11). As noted in previous sections of this report, the phreatic surface is only intended to apply to shallow groundwater movement in the saturated zone of the residuum. Groundwater movement that may occur in the bedrock's solutionally enlarged secondary permeability system is thought to be too complex to be represented by the interpretive techniques applied above.

4.7 Data Gaps and Recommendations

4.7.1 Data Gaps

Data distribution and availability for piezometers in WAG 8 should be improved. The northern "leg" of the site that crosses Haw Ridge requires additional investigation before its geohydrology can be described in detail. Water levels in the water quality wells around the 7900 ponds should be checked with the same frequency and on the same dates as the nearby piezometers and recorded in the same data base as the piezometers. A field survey of any older existing wells should be conducted and any unusable wells should be decommissioned to prevent conducting surface contaminants into the groundwater system. The vertical hydraulic gradient should be defined by installing shallow and deep water quality well pairs and comparing their static water levels. Seasonal water table fluctuations should be evaluated by constructing hydrographs of a full year's water level data using all the piezometers and water quality wells. Finally, field investigations should be conducted for the fill area north of the second hydrofracture site and the seep below HFIR/TRU Waste Collection Basins 7907 and 7908 (reference Section 4.1).

- NOTES:
1. TOPOGRAPHY AND SITE SPECIFIC INFORMATION PROVIDED BY MARTIN MARIETTA ENERGY SYSTEMS, INC.
 2. WATER LEVEL DATA COLLECTED BY MARTIN MARIETTA ENERGY SYSTEMS, INC. NOVEMBER 17, 1986.

FIGURE 4-11

WAG 8/SWSA 1 APPROXIMATE PHREATIC SURFACE

SCALE: 1" = 200'

MARTIN MARIETTA ENERGY SYSTEMS

MCI
Consulting Engineers, Inc.
NASHVILLE KNOXVILLE HUNTSVILLE LOUISVILLE

4.7.2 Recommendations

A water quality monitoring well system is recommended for the following portions of the WAG 8: 1) the abandoned section of the Melton Valley LLW transfer line, 2) the Melton Valley pumping station, and 3) the outlet for the shallow draw that drains the majority of the site.

The 7900 ponds already have an adequate groundwater monitoring system and the well locations are also suitable for monitoring transport of pipeline leaks from the 7900 Sewage Treatment Plant. The remaining solid waste management units are not known to have had releases to the environment and groundwater monitoring for these sites is not recommended.

Water quality well locations for WAG 8 are shown in Figure 4-12. The recommendations regarding well siting criteria, well configurations (Appendix II) and well construction for WAG 8 are the same as those previously described for WAG 7. Proposed design criteria and design coordinates for water quality wells are given in Appendix III.

A series of shallow (15 to 30 feet in depth) and deep (55 to 70 feet in depth) wells are proposed to monitor groundwater quality at the WAG 8 boundary. The series of wells numbered 1087, 1088, and 1091 are intended to monitor shallow groundwater quality adjacent to leak sites along the abandoned section of the Melton Valley LLW transfer line. The shallow and deep well pair numbered 1089 and 1090 are upgradient wells which will provide background water quality data. Shallow and deep well pair 1092 and 1093 will monitor the Melton Valley pumping station. Another shallow and deep well pair, numbers 1094 and 1095, at the site's southern boundary, will monitor groundwater quality from the central portion of WAG 8 as groundwater exits

E33000

N20000

WAG 8 —
BOUNDARY

1092
825
1093 SH

7516
7555
7507
7503
7509
850

875

875

N18000

825

7914
7914A
7915

7930

7920

7912

7900

7901

7910

800

N17000

7904

7903

7902

15

TOPOGRAPHY DIGITIZED FROM A BASE MAP PREPARED BY ACCU-AIR
VEYS, INC. SEYMOUR, INDIANA - WHITE OAK CREEK WATERSHED
SERIES. PHOTO DATE 3/29/78, MSL DATUM 1929.

TOPOGRAPHIC AND SITE SPECIFIC INFORMATION PROVIDED BY
TIN MARIETTA ENERGY SYSTEMS, INC.

POSITIONS OF LOW LEVEL WASTE LINES (LLW) ARE APPROXIMATE
WERE DIGITIZED FROM AN ORNL ATLAS MAP "MELTON VALLEY
FT)" DATED 8/13/85.

-LEGEND-

LOADING		PROPOSED WATER QUALITY WELL LOCATIONS & NUMBERS:
TEAM		SHALLOW COMPLETION
WATER POLE		DEEP COMPLETION
SECONDARY ROAD		EXPLORATORY BORINGS FOR THE ACTIVE LLW LINE
TOUR INTERVALS FEET		PROPOSED WATER QUALITY WELL LOCATIONS FOR WAG 9 AND SWSA 1 BORDERING ON WAG 8
LEVEL WASTE (LLW)		
LINE DOUBLE CONTAINED SECTION		

FIGURE 4-12
**8 PROPOSED WATER QUALITY
WELL LOCATIONS**

SCALE: 1" = 200'
MARTIN MARIETTA ENERGY SYSTEMS

DWN
CKD
APPD
DATE
PROJ
SCALE

⊕ DP 1099

ITY
'AG
ING

**Mc
Co
NASHV**

MCI

Consulting Engineers, Inc.

NASHVILLE

KNOXVILLE

HUNTSVILLE

LOUISVILLE

the site near the mouth of a large draw.

Additional characterization of the active section of the LLW line is recommended. Such characterization should include a walkover GM survey of the line and drilling of three exploratory boreholes in the LLW line trench backfill. Recommended locations for the boreholes are shown in Figure 4-12. The borings should be sampled using a continuous split spoon method. Prior to backfilling the boreholes, Martin Marietta Energy Systems may wish to evaluate the option of converting the boreholes to piezometers.

5.0 Waste Area Grouping 9

5.1 Site Location Description and Background

WAG 9 encompasses about 3 acres and is located west of the main portion of WAG 8 and south of Melton Valley Drive (Figure 5-1). WAG 9 was the site of Homogeneous Reactor Experiment 1 (HRE 1) and later the Homogeneous Reactor Test (HRT), sometimes referred to as Homogeneous Reactor Experiment 2. Both reactors were fueled by enriched U^{235} in an aqueous phase of partial composition U_2SO_4 . HRE 1 operated intermittently from 1951 through 1954 and was subsequently decommissioned and decontaminated. Following this, construction was begun on a new containment cell for the HRT which first reached criticality in December, 1957; it operated until 1961. After the HRT was shut down some of the facilities were converted for use by the Nuclear Safety Pilot Plant (NSPP), which continues to operate today. The site contains four solid waste management units: 1) the Homogeneous Reactor Experiment (HRE) Pond, 2&3) LLW Collection and Storage Tanks 7560 and 7562, and 4) the Nuclear Safety Pilot Plant Septic Tank. The locations of all four units are shown in Figure 5-1.

There are several additional potential environmental influences in WAG 9 that are not presently identified as solid waste management units. The first of these is the reported release of purge water from the hot storage pool in Building 7500 (R. Lee - 1986). Neither the volume or the radioactive content of this release are known, however, based on the following description it is presumed that the release was to the tributary in the drainageway east of Building 7500.

"The purge water from the hot storage pool in Building 7500 was discharged to the ground and flowed along natural drainage east of Building 7500" (The Tabulation

**WAG 9
BOUNDARY**

NOTES:

1. TOPOGRAPHY DIGITIZED FROM A BASE MAP PREPARED BY ACCU-AIR SURVEYS, INC. SEYMOUR, INDIANA - WHITE OAK CREEK WATERSHED MAP SERIES. PHOTO DATE 3/29/78, MSL DATUM 1929.
2. TOPOGRAPHIC AND SITE SPECIFIC INFORMATION PROVIDED BY MARTIN MARIETTA ENERGY SYSTEMS, INC.
3. LOCATIONS OF LOW LEVEL WASTE LINES (LLW) ARE APPROXIMATE AND WERE DIGITIZED FROM AN ORNL ATLAS MAP "MELTON VALLEY (DRAFT)" DATED 8/13/85.
4. TANK LOCATIONS WERE APPROXIMATED FROM SKETCH MAP, ORNL DWG 83-18177

E32000

-LEGEND-

STREAM	— . . . —
POWER POLES	○
BUILDING 7500
SECONDARY ROAD	— — — — —
CONTOUR INTERVALS 5 FEET	— 850 —
FENCE	— x x x x —
LOW LEVEL WASTE LINES (LLW)	— . . . —

FIGURE 5-1

WAG 9 SOLID WASTE
MANAGEMENT UNITS
SCALE: 1" = 200'
MARTIN MARIETTA ENERGY SYSTEMS

MCI
Consulting Engineers, Inc.
NASHVILLE KNOXVILLE HUNTSVILLE LOUISVILLE

of Contaminated Ground Areas In ORNL, Bethel Valley And Melton Valley Facilities; General Engineering Division document dated January 31, 1972, revised August 8, 1975).

The second potential environmental influence is the presence of seven buried 55 gallon stainless steel drums. The drums are believed to contain contaminated valves, pump heads and other components from the HRE. The drums are thought to be buried in a north-south line along the western edge of the HRT pond's asphalt cap, with the top of each drum flush with the ground surface (W.R. Reed - 1984). A third potential environmental influence is the discharge from sumps in the lower north sub-level of Building 7500. The sumps were designed to eliminate any water that might accumulate on the floor of the north sub-level. During operation of the HRT, the sump lines discharged to the HRT Pond. After the HRT Pond was closed and the NSPP began operating out of the old HRT facilities, the sump piping was rerouted to an unspecified location (Richard Lee, Personal Communication - July, 1987). Information about the remaining potential environmental influences was limited to the following facility descriptions which are quoted from the Preliminary Radiological Characterization Of The Homogeneous Reactor Experiment No. 2 (HRE-2) by S.G. Huang, et al. - 1984. Most of these features are identified on Figure 5-3.

"DECONTAMINATION PAD

Located south of Building 7500, the Decontamination Pad is a low-roofed shed measuring approximately 3 X 20 m (9.8 x 66 feet). It was used to store and decontaminate "hot" equipment. The east half of it has a floor lined with stainless steel and is equipped with drains for decontamination work.

RADIOACTIVE WASTE PROCESS LINES

Most radioactive waste process lines at HRE-2 are inactive and probably are still underground.

BURIAL GROUND

This area was located in the south yard of the decontamination pad. Unknown quantities of contaminated waste and equipment were packed in 193-L (50 gallon) drums and buried there. [It is not clear whether this is a reference to the seven 55 gallon drums described earlier or if it is a description of a different burial area.]

CHARCOAL ADSORBER PIT

This structure, the major part of the underground off-gas system, is located approximately 30 m east of Building 7500 and is buried under 3 m of earth. Pipes from this system are underground, extending from the east valve pit to the absorber and then from the absorber to the stack pad.

EVAPORATOR LOADING PIT

This pit, located outside the east wall of waste evaporator Building 7502, is inactive.

WASTE VALVE PIT

The waste valve pit is located in the east yard, approximately midway between the waste evaporator and the waste pond. It contains waste and vent piping from all of the waste system components.

LOADING PIT

Located at the south porch of 7500, this pit was once used for transporting carriers containing HRE fuel solution or chemical plant dissolved solids and later it housed the NSPP metering tanks.

DEMINERALIZED WATER SYSTEM

The above ground portion of this system, located outside the west wall of Building 7500, has been removed."

There are other HRE-2 support facilities that are described in the report by S.F. Huang, et al. - 1984. However, these facilities are not cited above, reflecting the writer's opinion that they have limited potential for adverse environmental impact because they are located inside buildings.

5.1.1 The HRT Pond

The HRT Pond is located on a hillside about 80 feet south of Building 7500 (Figure 5-1). It was constructed in 1955 by excavation and forming an embankment of the soils and weathered rock of the Conasauga Group. As designed, the pond had an average depth of 12.5 feet (F.G. Taylor - 1986), had a flat base (45 X 50 feet) and steeply sloping sides (1.5 H : 1 V). The "shoreline" dimensions of the pond were 75 X 80 feet which gave it a capacity of about 300,000 gallons (W.R. Reed - 1984). Inlet piping from the HRT entered the pond in its northwestern corner and the outlet piping was located in the pond's southeastern corner. The outlet piping led to a weir box located about 40 feet from the pond. The weir box discharged via an 8-inch line to a nearby but unspecified creek,* presumably the creek that appears in Figure 5-1 just southeast of the pond. Part of the way through the pond's service life (the exact date is unknown) the liquid level in the pond was lowered and an asphaltic sealer was spray applied. Some reports suggest that the pond may have been sealed with asphalt twice although this has not been adequately documented.

* HRE 1 operated prior to construction of the HRT Pond and it is thought that its discharges also went to an unidentified creek (W.R. Reed - 1984).

The pond served as a retention/settling basin for liquid radioactive wastes from the HRT from 1958 through 1961. Early in the pond's service life it received evaporator condensate from the process liquid waste system and later on it received shield water that had been exposed to the reactor circuits during routine maintenance. Contaminants from these waste streams were flocculated in the pond and the treated water was discharged to the weir box (R.G. Stansfield and C.W. Francis - 1985). The principal contaminants are Cs^{137} and Sr^{90} with trace amounts of Pu^{238} , Pu^{239} , Am^{241} and Cm^{244} (RCRA Facilities Assessment, Oak Ridge National Laboratory - 1987).

In 1970, the HRT Pond was closed by backfilling it with soil and weathered shale. At this time an observer of the closure operation noted that the pond was approximately half filled with sludge and clay (W.R. Reed - 1984). Presumably the clay portion had eroded and slumped from the pond's steep banks. After the backfill was in place, about 1,100 lb of sodium borate were added as a herbicide. Following this an 8-inch layer of crushed stone was applied and a 1½-inch asphaltic concrete cap was placed over the site. Later, several observation wells were driven through the cap and in 1987, 7 piezometers were installed around the cap (see Section 5.6.1).

5.1.2 LLW Collection and Storage Tanks 7560 and 7562

There are two buried tanks that were utilized in the HRT waste processing system. Both tanks apparently have ORNL facility identification numbers (7560 and 7562) but available records do not indicate which tank has been assigned which number. One tank has a 1,000 gallon capacity and the other a 12,000 gallon capacity; therefore, in the remainder of this report the tanks will be identified on the basis of their capacities.

The 1,000 gallon tank is located south of the waste evaporator (Building 7502) as shown in Figure 5-1. The tank was constructed of stainless steel and reportedly has a diameter of 4 feet and a length of 11 feet. There are conflicting reports about how deep the tank is buried. A decommissioning study for the HRT (ORNL/CF-76/66) states that "the tank is covered with about 20 feet of earth". A more recent document that describes the preliminary radiological characterization of the HRT (ORNL/CF-84/201) states the tank "is buried to a depth of about 1.5 meters" (4.9 feet) and additional information regarding the tank's burial depth was not available. The 1,000 gallon tank was used from 1957 to 1961 to collect condensate from the HRT waste evaporator cell in Building 7502. The tank's contents were sampled periodically and depending on the level of radioactivity, the waste was either discharged to the HRT Pond or shunted to the 12,000 gallon tank for recycling. The 1,000 gallon tank has been out of service since 1961 and there have been no known releases to the environment from this unit.

The 12,000 gallon tank is located about 15 feet north of the HRT Pond's asphalt cap (Figure 5-1). The tank is constructed of steel with a diameter of 10 feet and a length of 21 feet. The tank is "covered with about 15 feet of earth for shielding" (ORNL/CF-76/66). The 12,000 gallon tank was originally used to store "high level" HRT waste prior to sending the waste to the evaporator loading pit. After the HRT was removed from service, The Nuclear Safety Pilot Plant (NSPP) moved into the former HRT facilities and used the 12,000 gallon tank "for the disposal of depleted uranium" (R. Lee - in press). Two other documents describe the tank's function after shut-down of the HRT as follows: 1) the tank serves as a "reservoir for a radioactivity decontamination pad" (ORNL/CF-85/415) and, 2) the tank serves "the Radioactive Materials Handling Laboratory located southwest of Building 7500" (ORNL/CF-84/201). In any event, the tank is reportedly

inactive after being taken out of service in 1986 (RCRA Facilities Assessment - Oak Ridge National Laboratory - 1987).

Analyses of the wastes in the tanks are not available, but the primary contaminants are believed to be Sr^{90} , Cs^{137} and Transuranics. Lesser amounts of uranium and plutonium isotopes combined with various short half-life radionuclides may also be present. Release data for the tank reports that a spill occurred during a transfer of LLW from the 12,000 gallon tank. Soil samples in this vicinity indicate contamination by Sr^{90} and Cs^{137} .

5.1.3 Septic Tank 7501

Septic Tank 7501 is located approximately 55 feet east of Building 7505 (Figure 5-1). The tank was put in service in 1950 (RCRA Facilities Assessment, Oak Ridge National Laboratory - 1987) to treat domestic sewage from Building 7500 (Drawing No. C-7020, dated 1950) and it is still in operation. The design drawing for this unit indicates that it was to be constructed of concrete reinforced with $\frac{1}{2}$ inch diameter steel bar. The tank has a capacity of 1,400 gallons and it is divided into two sections separated by a baffle, each section having its own access manhole.

The effluent from Septic Tank 7501 may be to one of the nearby drainageways in WAG 9. This possibility is suggested by the following factors: 1) background documents and drawings for this unit do not describe or depict a drainage field, and 2) a note on the design drawing states - "Laboratory standard chlorinator house and equipment to be installed by others". Because chlorinators are commonly associated with discharges to surface water systems it is probable that Septic Tank 7501 discharges to a drainageway in WAG 9, but additional field work is required to confirm this assumption. In any event,

the tank is thought to receive only domestic sewage not hazardous or radioactive wastes (RCRA Facilities Assessment, Oak Ridge National Laboratory - 1987).

5.2 Topography

As shown in Figure 5-1, WAG 9 is located on a low knoll just south of the toe of Haw Ridge. The eastern and southern portions of the site slope into a southwesterly trending draw that bears a tributary of Melton Branch. The head of this draw lies to the east of the site and it carries runoff from WAG 8.

Immediately west of WAG 9 is the head of another draw that trends to the west and contains a tributary of White Oak Creek.

Slopes range from less than 2 percent, near the crest of the knoll where the site has been graded, to slopes of about 15 percent near the site's southwestern border. Maximum relief is about 45 feet, ranging from a low of about 800 feet at the site's southern boundary to a high of approximately 845 feet along its western boundary.

5.3 Soils

Soils in WAG 9 are derived from the Rogersville Shale, the Rutledge Limestone, the Pumpkin Valley Shale and colluvial materials from the Rome Formation. These soils have been described in drill logs from the recent piezometer installation program (1985-1987) as brown to yellowish-brown and gray to greenish gray clays. The soil contains numerous rock fragments that may exhibit a gray to maroon coloration and which weather to a shaley appearance. Two of the piezometer drill logs (Nos. 670 and 671) record crushed stone in the upper 2 to 5 feet. This suggests that there may be fill areas in WAG 9, but the depth and lateral extent of the fill cannot be assessed from this limited

drilling information. Soil depths were recorded from a minimum of 8 feet to a maximum of 19 feet, and the distribution of soil depths indicates that the soil-bedrock interface has an irregular surface geometry.

Information on soil contamination is available from a radiological survey of the HRT; Huang et al. - 1984. The survey procedures involved the layout of a grid pattern using wooden stakes and string. A walkover radiological survey of the area identified 8 grid cells as potential sources of contamination. Shallow (12-inch) soil samples were then collected from the center of the eight grid cells and analyzed for radionuclides. The locations of the soil samples are shown in Figure 5-2 and the analytical results are given in Table 5-1.

The radiological survey of the HRT also included a series of 21 deep (average depth 11.5 feet) soil corings. One hundred eight split spoon soil samples were collected during the coring. Gamma screening of all the samples combined with their geologic characteristics resulted in the selection of forty-six samples for quantitative radionuclide analysis. The locations of these soil samples are shown in Figure 5-3 and the analytical results are given in Table 5-2.

The shallow soil sampling indicates that Sr^{90} and Cs^{137} are the primary contaminants. The areas of highest activity are grid cells 13-Q and 11-S southeast of the HRT Pond, 12-J on the northeast corner of the HRT Pond's asphalt cap, 6H just north of the decontamination pad and 3-K south of the decontamination pad. Significant Sr^{90} activity was detected in grid cell 9-H which is in the general area of the 1,000 gallon and 12,000 gallon LLW collection/storage tanks.

FIGURE 5-2 WAG 9
SHALLOW SOIL SAMPLING LOCATIONS

ORNL-DWG 83-18118

TABLE 5-1
WAG 9

Radionuclide Concentrations Of Contaminated
Soil Samples From 0-12 Inches
Excerpted From The Preliminary Radiological Characterization
Of The Homogeneous Reactor Experiment No. 2 (HRE-2)
by Huang et al. - 1984

Grid Sample Identi- fication	Radioactivities (Bq/g) ^a						
	¹³⁷ Cs	⁶⁰ Co	⁹⁰ Sr	²³⁹ Pu	²³⁸ Pu	²⁴¹ Am	²⁴⁴ Cm
6H	43	ND ^b	10	0.25X10 ⁻³	< 0.3 X10 ⁻³	0.31X10 ⁻²	0.46X10 ⁻³
9H	1.6	ND	14	0.15X10 ⁻²	0.62X10 ⁻³	0.22X10 ⁻²	0.19X10 ⁻²
8F	5.7	0.01	1.2	0.62X10 ⁻²	0.4 X10 ⁻³	0.38X10 ⁻²	0.38X10 ⁻³
12G	4.8	ND	1.1	0.29X10 ⁻³	< 0.4 X10 ⁻³	0.73X10 ⁻²	0.13X10 ⁻³
12J	160	0.05	8.4	9.0	1.2	0.4	0.4
3K ^c	48	0.01	0.48	1.9	0.6	< 0.1	0.4
13Q	14	ND	8.2	< 0.3 X10 ⁻³	0.11X10 ⁻²	0.13X10 ⁻²	0.58X10 ⁻²
11S	48	0.13	24	1.5	0.2	0.6	15

^a 1 Bq/g = 27 pCi/g.

^b ND indicates nondetectable.

^c Contains ¹³⁴Cs (0.037 Bq/g).

FIGURE 5-3 WAG 9
DEEP SOIL SAMPLING LOCATIONS

ORNL-DWG 83-18117

TABLE 5-2
WAG 9

Radionuclide Concentrations In Deep Coring Soil Samples
Excerpted From The Preliminary Radiological Characterization
Of The Homogeneous Reactor Experiment No. 2 (HRE-2)
by Huang, et al. - 1984

Core Sample Identi- fication	^{137}Cs (Bq/g) ^a	^{90}Sr (Bq/g) ^a	Sample Identi- fication	^{137}Cs (Bq/g)	^{90}Sr (Bq/g)
1-3	0.7×10^{-2}	0.25×10^{-1}	15-6 ^b	0.11	45
1-4	ND ^c	0.16×10^{-1}	15-8	ND	0.27
1-5	0.4×10^{-2}	0.11×10^{-1}	16-3 ^b	0.33	12
1-6	0.7×10^{-2}	0.11	16-4 ^b	0.20	12
2-3 ^d	ND	0.3×10^{-1}	16-5 ^b	0.15×10^{-1}	1.1
2-5 ^d	ND	0.7×10^{-1}	16-6	0.15×10^{-1}	0.18
2-6 ^d	ND	0.74×10^{-1}	17-1 ^b	5.9	2.4
3-3	0.7×10^{-2}	0.4×10^{-1}	17-2 ^b	5.2	2.2
6-3	0.8×10^{-1}	0.13	17-3 ^b	3.0	2.3
7-4 ^d	ND	0.3×10^{-2}	17-4 ^b	0.29	0.61
8-4 ^d	ND	0.78×10^{-1}	17-5 ^b	0.29	24
9-2	0.7×10^{-1}	0.7×10^{-2}	17-6 ^b	ND	3.9
11-3	0.8×10^{-1}	0.1	18-1 ^b	0.2	0.65
12-3 ^b	0.15	0.2	18-4 ^s	ND	0.36
13-2	0.4×10^{-1}	0.6×10^{-2}	18-5 ^d	ND	0.17
13-3	0.54	0.17	19-4	0.6×10^{-1}	0.89×10^{-1}
13-5	0.9×10^{-1}	0.78×10^{-1}	19-7 ^d	ND	0.14
13-6	ND	0.35×10^{-1}	20-5 ^d	ND	0.3×10^{-1}
14-3 ^b	0.48	0.16	20-6	0.1×10^{-1}	0.84×10^{-1}
14-6	ND	15	20-9 ^d	0.3×10^{-2}	0.1
14-7	ND	0.21	21-3	ND	0.84×10^{-1}
15-3 ^b	2.2	0.51	21-5 ^d	ND	0.18
15-5 ^b	0.03	0.15	21-7 ^d	ND	0.17
DOE Guide	0.75	0.75		0.75	0.75

^a 1 Bq = 27 pCi/g.

^b Contained uranium activity.

^c ND - Nondetectable.

^d The ^{90}Sr result is from Cerenkov counting.

The split spoon samples from the deep soil cores appear to confirm that Sr^{90} and Cs^{137} are the primary contaminants. The greatest activity occurred in soil cores 14, 15, 16 and 17. Cores 14, 15 and 16 pierced the HRT Pond's asphalt cap and core 17 is located just off the southern edge of the cap.

Radioactivity was found in both shallow and deep soil samples at a variety of locations around the HRT area; however, the sampling implicates the HRT Pond as the major source of contamination.

5.4 Geology

Based on a recently drafted geologic map (R. Dreier and K. Boedoin - 1987), WAG 9 is underlain by three members of the Conasauga Group (Figure 5-4). These members dip to the southeast and from youngest to oldest are: the Rogersville Shale, the Rutledge Limestone and the Pumpkin Valley Shale. The contact between the Rogersville Shale and the Rutledge Limestone occurs near the site's southern tip, while the Rutledge Limestone/Pumpkin Valley Shale contact occurs just south of Building 7500. The Rogersville Shale underlies the southernmost portion of WAG 9, the Rutledge Limestone underlies the site's south central portion (including the HRT Pond) and the Pumpkin Valley Shale underlies the site's northern portions. Lithologic descriptions for these three members can be found in Section 3.4 of this report.

5.5 Surface Hydrology

WAG 9 is located in the Melton Valley sub-basin of the White Oak Creek drainage basin. Runoff from the site is borne by two unnamed tributaries of, one of Melton Branch and one of White Oak Creek. Near the southern tip of WAG 9 the headwaters of the tributary of Melton Branch separate into 3 prongs. One of the prongs bears to the northwest and drains

WAG 9
BOUNDARY

N19000

N18000

E31000

NOTES:

1. TOPOGRAPHY DIGITIZED FROM A BASE MAP PREPARED BY ACCU-AIR SURVEYS, INC. SEYMOUR, INDIANA - WHITE OAK CREEK WATERSHED MAP SERIES. PHOTO DATE 3/29/78, MSL DATUM 1929.
2. TOPOGRAPHIC AND SITE SPECIFIC INFORMATION PROVIDED BY MARTIN MARIETTA ENERGY SYSTEMS, INC.
3. LOCATIONS OF LOW LEVEL WASTE LINES (LLW) ARE APPROXIMATE AND WERE DIGITIZED FROM AN ORNL ATLAS MAP "MELTON VALLEY (DRAFT)" DATED 8/13/85.
4. GEOLOGIC CONTACTS BASED ON WORK BY RANAYE DREIER AND KATHLEEN BOEDDIN - MMES GEOLOGISTS.

-LEGEND-

STREAM	— . . . —
POWER POLES	○
BUILDING 7500	7500
SECONDARY ROAD	— — — — —
CONTOUR INTERVALS 5 FEET	850
FENCE	* * * * *
LOW LEVEL WASTE LINES (LLW)	— . . . —
ROME FORMATION	Er
PUMPKIN VALLEY SHALE	Epv
RUTLEDGE LIMESTONE	Ert
ROGERSVILLE SHALE	Erg
MARYVILLE LIMESTONE	Em
GEOLOGIC CONTACT	— — —

FIGURE 5-4

WAG 9 GEOLOGIC MAP

SCALE: 1" = 200'
MARTIN MARIETTA ENERGY SYSTEMS

MCI Consulting Engineers, Inc.
NASHVILLE KNOXVILLE HUNTSVILLE LOUISVILLE

the southwestern portion of the site. The second prong bears north along the eastern border of WAG 9 and drains the south central and eastern portion of the site. The third prong extends to the east where it picks up drainage from WAG 8 and carries it to its confluence with the other two prongs. These three prongs combine to form a southwesterly flowing tributary of Melton Branch, with Melton Branch being located about 1,920 feet south of WAG 9.

The headwaters of a tributary of White Oak Creek receive runoff from the northwestern portion of WAG 9. The confluence of this tributary with White Oak Creek is about 2,000 feet west of WAG 9.

Field reconnaissance of both tributaries was carried out on July 29 and 30, 1987, after a 9 day period without precipitation. The tributary of Melton Branch and its three prongs all contain water. The tributary of White Oak Creek was dry, but it had a well defined channel indicating that at times it carries significant flow.

5.6 Groundwater

5.6.1 Existing Groundwater Monitoring System

Background documents for WAG 9 describe the installation of three separate groundwater monitoring systems. The first of these systems is thought to have been installed a short time after the HRT Pond was backfilled and covered with an asphalt cap. This system consisted of nine wells fitted with pointed drive shoes, eight of which were driven through the perimeter of the asphalt cap and a single well driven through the center of the cap (Figure 5-5). The well casings were reportedly perforated by holes greater than 1 inch in diameter, spaced several feet apart along their length (R.G. Stansfield and C.W. Francis - 1985). Because the design and construction of

FIGURE 5-5 WAG 9
LOCATION OF DRIVEN WELLS

ORNL-DWG 85-13716C

these wells do not appear to meet present day standards they are not considered suitable for gathering water quality data or water levels.

Another monitoring system consisting of four wells was installed in late February and early March, 1985 (Figure 5-5). The wells were constructed of 3 inch diameter fiberglass casing and screen. The screens are 10 feet long with two rows slots. A medium-grained quartz sandpack was placed around the screened section which was sealed with at least 1 foot of bentonite. The remainder of the annulus was backfilled with portland cement and a protective casing was set around the well riser pipe. A summary of the well construction details is given in Table 5-3. These wells appear to be constructed properly and should be considered capable of yielding reliable water quality and water level data.

In January and March of 1987 a network of seven piezometers was installed in WAG 9 (Figure 5-6). Four of the piezometers (Nos. 673, 674, 675 and 898) are sited along the southeastern, northeastern, and southern sides of the HRT Pond. Two piezometers (Nos. 671 and 672) are located in the yard west of the HRT Pond and a single piezometer (No. 670) is located in the vicinity of the LLW collection/storage tanks. Construction details for the piezometer installation program are described in Section 3.6.1 of this report.

5.6.2 Groundwater Quality

Groundwater quality information for WAG 9 is available from the 4 fiberglass wells that monitor groundwater in the vicinity of the HRT Pond. Groundwater data from these wells is compiled in an MMES Environmental Sciences Division report titled Characterization Of The Homogeneous Reactor Experiment No. 2 (HRE) Impoundment (R.G. Stansfield and C.W. Francis - 1985). Excerpts and data from the above referenced document

TABLE 5-3
WAG 9
Summary Of HRT Pond Monitoring Well
Construction Details
Excerpted From The Characterization Of The
Homogeneous Reactor Experiment No. 2 (HRE) Impoundment
by R.G. Stansfield and C.W. Francis - 1985

	MW-1	MW-2	MW-3	MW-4
NORTH ORNL GRID COORDINATE (FT)	18634.87	18581.39	18518.64	18515.45
EAST ORNL GRID COORDINATE (FT)	31422.87	31533.62	31525.86	31444.65
TOP OF WELL CASING EL. (FT)	827.03	815.71	810.81	816.10
HEIGHT OF CASING ABOVE GROUND (FT)	3.8	2.3	2.7	3.0
GROUND SURFACE EL. (FT)	823.2	813.4	808.1	813.1
TOP OF WELL SCREEN EL. (FT)	807.0	800.7	795.8	804.4
BOTTOM OF WELL SCREEN EL. (FT)	797.0	790.7	785.8	794.4
TOP OF SAND PACK EL. (FT)	815.2	805.4	800.1	805.1
BOTTOM OF WELL HOLE EL. (FT)	793.5	788.5	783.4	788.4
DIAMETER OF WELL PIPE/SCREEN (IN)	3.0	3.0	3.0	3.0
TYPE MATERIAL OF PIPE/SCREEN	FIBER- GLASS	FIBER- GLASS	FIBER- GLASS	FIBER- GLASS
WIDTH OF SCREEN OPENING (IN)	0.02	0.02	0.02	0.02
WATER LEVEL EL. (FT) 4-8-85	814.79	808.20	803.95	805.34
WATER LEVEL EL. (FT) 5-20-85	813.58	807.44	803.40	805.50
WATER LEVEL EL. (FT) 6-04-85	813.64	806.97	803.26	805.35
WATER LEVEL EL. (FT) 7-01-85	815.32	808.10	803.95	805.37

All Measurements Are In Feet Unless Otherwise Noted.

*WAG 9
BOUNDARY*

NOTES:

1. TOPOGRAPHY DIGITIZED FROM A BASE MAP PREPARED BY ACCU-AIR SURVEYS, INC. SEYMOUR, INDIANA - WHITE OAK CREEK WATERSHED MAP SERIES. PHOTO DATE 3/29/78, MSL DATUM 1929.
2. TOPOGRAPHIC AND SITE SPECIFIC INFORMATION PROVIDED BY MARTIN MARIETTA ENERGY SYSTEMS, INC.
3. LOCATIONS OF LOW LEVEL WASTE LINES (LLW) ARE APPROXIMATE AND WERE DIGITIZED FROM AN ORNL ATLAS MAP "MELTON VALLEY (DRAFT)" DATED 8/13/85.
4. WATER LEVEL MEASUREMENTS TAKEN DURING THE LAST WEEK OF MAY, 1987.

E32000

-LEGEND-

- STREAM
- POWER POLES
- BUILDING 7500
- SECONDARY ROAD
- CONTOUR INTERVALS 5 FEET
- PIEZOMETER LOCATION
- PHREATIC SURFACE ISOPLETH
- POSSIBLE GROUNDWATER FLOW DIRECTION
- FENCE
- LOW LEVEL WASTE LINES (LLW)

WATER LEVEL ELEVATIONS	
WELL NUMBER	ELEVATION
670	813.10
671	814.10
672	806.00
673	806.84
674	808.38
675	802.19
898	808.19

FIGURE 5-6
WAG 9

PHREATIC SURFACE MAP
SCALE: 1" = 200'
MARTIN MARIETTA ENERGY SYSTEMS

are presented in Table 5-4.

The 4 HRT monitoring wells were sampled quarterly over a 12 month period from February, 1985 to January, 1986. Prior to sampling, the wells were purged of a volume of water equivalent to five times the volume of water contained inside the well screen and casing. Groundwater samples were collected with a bottom loading stainless steel bailer. Between wells the bailer was disassembled and rinsed with detergent and hot water, then rinsed with methanol* followed by distilled water rinses. As an additional precaution against the potential for cross contamination, the nylon retrieval line was replaced between wells.

Sampling protocol included appropriate sample preservation methods, e.g., acidification of metals samples and refrigeration of samples that had to be stored prior to analysis. Chain of custody procedures for sample handling were also maintained. The analytical methods employed were those described in USEPA methods manuals SW-846, 1982 and EPA-600/4-79-020, 1983. The results of the analyses for the June 5, 1985 quarterly samples are shown in Table 5-4.

The analyses indicate that the principal groundwater contaminants are Sr^{90} and H^3 , both of which are beta emitters. Elevated gross alpha activity in monitoring wells 1 and 2 appear anomalous when compared with sample analyses of the HRT Pond backfill, the latter which do not indicate significant quantities of alpha emitting TRU wastes. Concentrations of Cs^{137} in groundwater are low compared to samples of soil and the HRT Pond backfill. This may reflect the soil's ability to retain Cs^{137} within the mineralogical structure of illite.

* During the first quarter of sampling a dilute nitric acid rinse was used in place of the methanol rinse.

TABLE 5-4
WAG 9
Groundwater Quality - Four Wells At The HRT Pond
Excerpted From The Characterization Of The
Homogeneous Reactor Experiment No. 2
(HRE) Impoundment
Sample Date May 21 & 22, 1985

		Monitoring			
		Well #1	Monitoring	Monitoring	Monitoring
Parameter		(Upgradient)	Well #2	Well #3	Well #4
Ag	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
Al	mg/L	2.810	1.5200	1.8200	17.8000
As	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
B	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
Ba	mg/L	0.1200	0.1630	0.1050	0.4940
Be	mg/L	< 0.0001	< 0.0001	< 0.0001	0.0022
Ca	mg/L	95.1000	130.0000	130.0000	188.0000
Cd	mg/L	< 0.0001	< 0.0001	0.0035	0.0035
Co	mg/L	< 0.0001	< 0.0001	< 0.0001	0.0255
Cu	mg/L	< 0.0001	< 0.0001	< 0.0001	0.0320
Cr	mg/L	< 0.0001	< 0.0001	0.0212	0.0591
F	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
Fe	mg/L	4.5900	2.8800	4.1400	29.0000
Ga	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
Hf	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
Hg	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
K	mg/L	1.4000	4.0000	3.9000	3.8000
Li	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
Mg	mg/L	17.2000	20.0000	20.2000	27.1000
Mn	mg/L	0.1980	0.7890	0.1800	1.7500
Mo	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
Na	mg/L	6.8000	12.7000	21.7000	5.6500
Ni	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
P	mg/L	< 0.0001	< 0.0001	< 0.0001	0.3230
Pb	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
Sb	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001

TABLE 5-4 Cont'd

		Monitoring	Monitoring	Monitoring	Monitoring
		Well #1	Well #2	Well #3	Well #4
Parameter		(Upgradient)			
Se	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
Si	mg/L	7.8600	11.7000	14.4000	25.2000
Sr	mg/L	0.0858	0.1480	0.3450	0.1780
Ti	mg/L	0.0329	0.0215	0.0229	0.0514
V	mg/L	0.0308	0.0326	0.0353	0.0668
Zn	mg/L	< 0.0001	< 0.0001	< 0.0001	0.0831
Zr	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
Chloride	mg/L	7.0000	5.0000	4.0000	4.0000
Sulfate	mg/L	42.0000	55.0000	43.0000	34.0000
Phenol	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
PCB	mg/L	< 0.0001	0.0001	0.0001	0.0001
Endrin	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
Lindane	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
Methoxychlor	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
2,4-D	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
2,4,5-TP	mg/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
pH		6.9000	6.7250	6.6000	6.6250
(Mean Of 4 Replicate Samples)					
TOC	mg/L	6.4750	Not Reported	Not Reported	Not Reported
(Mean Of 4 Replicate Samples)					
Specific					
Conductance	umhos/cc	522.2500	715.0000	284.7500	562.2500
(Mean Of 4 Replicate Samples)					
Gross Alpha	Bq/L	0.9000	5.6000	0.1000	0.1000
Gross Beta	Bq/L	3.500	950.0000	3.6000	210.0000
Cs ¹³⁷	Bq/L	< 0.0001	< 0.0001	< 0.0001	0.1517
H ³	Bq/L	20.0000	230.0000	370.0000	37.0000
Ra ²²⁶	Bq/L	< 0.0001	< 0.0001	< 0.0001	< 0.0001
Sr ⁹⁰	Bq/L	0.2600	540.0000	1.3000	0.5800
Coliform	co/100ml	4.0000	< 0.0001	2.0000	6.0000

Perhaps most significant is the occurrence of radionuclides in monitoring well number 1 (the upgradient well), suggesting that contaminants may be leaching from other facilities in WAG 9. For this particular sampling event, the only other contaminants of note are chromium at .0591 mg/l in well 4 and coliform bacteria at 4.0, 2.0 and 6.0 colonies/100 ml in wells 1, 3 and 4, respectively.

In addition to the sampling and analytical work described above an electromagnetic conductivity survey of the HRT Pond was conducted. This geophysical method has the potential to detect contaminant plumes of high ionic strength by registering their higher conductivity. The instrumentation was configured so that its effective subsurface range was about 15 feet deep. The results of the survey did not indicate conductivity anomalies of a magnitude that would indicate the presence of a contaminant plume.

5.6.3 Hydrology

There are no stream gaging stations in WAG 9 and hence no quantitative streamflow data is available. Information on the occurrence of groundwater in WAG 9 is available from the network of 7 piezometers on the southern portion of the site and from earlier work based on water levels in the 4 HRT Pond monitoring wells.

Of the 7 piezometers in WAG 9, 3 are screened entirely within bedrock (Nos. 670, 671 and 673), 2 have screens that transect the soil-bedrock interface (Nos. 672 and 675^{*}) and 2 are screened entirely within the soil column (Piezometer Nos. 674^{**} and 898).

^{*} Only the last 0.77 ft. of piezometer number 675 penetrated bedrock.

^{**} Piezometer number 674 is constructed with the base of its screen at the same elevation as the top of bedrock.

Regardless of which aquifer media the piezometers monitor, their static water levels all occur within the soil column; and variations in their relative head elevations generally reflect variations in the piezometers' relative topographic positions.

Water level data from the 7 piezometers were used to construct a phreatic surface map for the eastern and southern portions of WAG 9 (Figure 5-6). The map depicts an apparent hydraulic gradient ranging from about 5 percent on the site's northeastern portion to about 25 percent near the site's southwestern border. Water level elevations in the piezometers gradually decrease from northwest to southeast as the site gradually slopes into a draw to the southeast.

Figure 5-6 is in general agreement with an earlier phreatic surface map by R.G. Stansfield - 1985 (Figure 5-7). The 1985 map was based on water level data from the 4 fiberglass wells that monitor the HRT Pond. Water levels for these wells are given in Table 5-3. The earlier map (Figure 5-7) depicts a decrease in the hydraulic head from the northwest to the southeast. The gradient shown is gradual beneath the HRT Pond's asphalt cap. However, the gradient increases markedly near the edge of the asphalt cap then becomes gradual again as it approaches the draw southeast of the HRT Pond. Evaluation of the 1985 water level data suggests that the differences between the two maps are largely the result of the interpretive approach used in constructing the phreatic surface.

Groundwater moves from potentiometric highs towards potentiometric lows. However, this generality should be applied with caution when inferring groundwater flow directions in the Melton Valley geohydrologic setting.

FIGURE 5-7 WAG 9
PHREATIC SURFACE MAP
1985 WATER LEVEL DATA

ORNL-DWG 85-13716AB

GRID
NORTH

TRUE
NORTH

--- WATER TABLE CONTOUR

..... INSIDE POND (BOTTOM)

FEET
0 50 100
0 10 20 30
METERS

Groundwater movement in the soil may be to the southeast, approximating the direction of the flow arrows drawn normal to the potentiometric contours of Figure 5-6. If this is the case, then shallow groundwater movement could be described by relatively short flowpaths that begin in recharge areas at higher elevations and terminate in streams on the valley floors. However, the soils in WAG 9 are not a uniform media through which groundwater may flow unimpeded. Excavation and backfilling of the HRT Pond as well as natural variations in soil structure and texture may cause deviations from the general interpretation offered above.

Groundwater movement in the bedrock aquifer medium is thought to be governed by a structurally dependent secondary porosity system. Until additional hydrologic studies are conducted, the direction of groundwater movement in bedrock is presumed to be controlled by fractures, many of which trend along geologic strike to the northeast and southwest.

5.7 Data Gaps and Recommendations

5.7.1 Data Gaps

An in depth review of background documents should be conducted for the 8 facilities listed as potential environmental influences in Section 5.1. These facilities should be thoroughly researched and characterized with regard to their potential for adversely impacting the environment and any history of past releases to the environment. Water levels in the 4 HRT Pond monitoring wells should be checked on the same date as the water levels in the 7 piezometers in WAG 9. Plugging and abandonment methods should be evaluated for the 9 driven well points that penetrate the HRT Pond's asphalt cap.

The direction of groundwater flow in bedrock should be defined by pump-tests and/or tracer tests and the vertical hydraulic gradient should be evaluated by installing shallow and deep water quality well pairs and comparing their static water levels. Seasonal water table fluctuations should be documented by constructing hydrographs of a full year's water level data from the 7 piezometers and the 4 HRT Pond monitoring wells.

5.7.2 Recommendations

Radiological surveys and groundwater monitoring data have documented the presence of radionuclide contamination in WAG 9. In view of this, a water quality well monitoring system is recommended for this site. Water quality well locations for WAG 9 are shown in Figure 5-8. The recommendations concerning well siting criteria, well design (Appendix II) and well construction for WAG 8 are the same as those described for the previous two subject sites. Proposed water quality well design coordinates are given in Appendix III.

Background water quality for WAG 9 will be determined by a shallow and deep well pair (Nos. 1089 and 1090), which also serve as background wells for WAG 8. Downgradient water quality for WAG 9 will be monitored by 3 shallow wells (5 to 15 feet deep) and one deep well (55 to 70 feet deep). The wells are located where suspected groundwater flowpaths intersect the WAG boundary. The shallow well numbered 1096 will monitor potential strike oriented groundwater flow on the eastern WAG boundary. A single shallow well, number 1097, on the southeastern WAG boundary will monitor groundwater that may carry contamination from the HRT Pond toward the southwesterly flowing tributary of Melton Branch. Well pair numbered 1098 and 1099 will monitor shallow and deep groundwater movement at the southern tip of WAG 9.

FIGURE 5-8

APPENDIX I

Example of Piezometer Drill Log And Construction Schematic

MCI
Consulting Engineers, Inc.

10628 Dutchtown Road, P.O. Box 23010
Knoxville, Tennessee 37933-1010
615 966-9788

Engineering, Planning, Landscape Architecture

WELL LOG

WELL NUMBER 1031

DATE 4/14/87

DRILLER GARY RAGSDALE

MAP NUMBER _____

HELPER DONNIE WALDO

RIG INGERSOL T4

H.P. P. ELDRIDGE

STATIC WATER LEVEL _____

LOGGED BY M.L. EBERS & C.W. STANLEY

LOCATION MELTON VALLEY ROAD

PLANT COORDINATES N _____ E _____

DEPTH (FT)		DESCRIPTION	CONTAMINATION
0	7	CLAY, MEDIUM REDDISH BROWN, DRY, WITH ABUNDANT WEATHERED RED SHALE	
7	8	CLAY, LIGHT BROWN, DRY - AUGER REFUSAL @ 8'	
8	47	SHALE, LIGHT BROWN AND REDDISH BROWN, HEAVILY WEATHERED	
47	65'	INTERBEDDED SILTSTONE, GRAYISH GREEN AND SHALE, GRAYISH RED	
	65'	TOTAL DEPTH	
		AUGER 0-8', TRICONE WITH AIR FROM 8 TO 65'. DRILLED TO 30' AND 47'. WAITED 15' EACH TIME, BLEW HOLE - NO WATER BLEW HOLE AFTER 15', HAD 2' WATER + PENCIL SIZE STREAM	
		20' x 2" SLOTTED PVC SCREEN FROM 45' TO 65'	
		50' x 2" PVC CASING FROM 0 TO 45' WITH 2' STICKUP (CUT OFF 3')	
		4 SACKS SAND FROM 42' TO 65'	
		1/2 BUCKET BENTONITE FROM 40 TO 42'	

PIEZOMETER CONSTRUCTION IN ROCK

WELL NO. 1031

DATE INSTALLED: 4/14/87

MAP NO. _____

LOCATION NORTH: _____

EAST: _____

NOTE: ALL DEPTHS ARE RELATIVE TO TOP OF GROUND.

DRAWING NOT TO SCALE.

MCI/CONSULTING ENGINEERS, INC.
NASHVILLE KNOXVILLE HUNTSVILLE LOUISVILLE

APPENDIX II

Water Quality Well Construction Schematics

TYPE A MONITORING WELL

TYPE B MONITORING WELL

OPTIONAL FLUSH MOUNT WELL COVER
(FOR PLACEMENT OF WELLS IN HIGH TRAFFIC AREAS)

APPENDIX III

Proposed Water Quality Well Design Criteria,
Design Coordinates And
Estimated Completion Depths

APPENDIX III

Proposed Water Quality Well Design Criteria And Estimated Completion Depths

WAG 7

<u>Well No.</u>	<u>Estimated Depth to Rock*</u>	<u>Estimated Maximum And Minimum Depths To Groundwater*</u>	<u>Estimated Completion Depth And Screened Interval</u>
1071	15 - 17 ft.	16 - 11 ft.	20 ft./10 - 20 ft.
1072	5 - 15 ft.	10 - 15 ft.	70 ft./55 - 70 ft.
1073	5 - 15 ft.	10 - 15 ft.	25 ft./10 - 25 ft.
1074	5 - 15 ft.	9 - 15 ft.	20 ft./10 - 20 ft.
1075	5 - 15 ft.	9 - 15 ft.	70 ft./55 - 70 ft.
1076	5 - 15 ft.	9 - 15 ft.	25 ft./10 - 25 ft.
1077	5 - 15 ft.	9 - 15 ft.	70 ft./55 - 70 ft.
1078	10 - 20 ft.	15 - 20 ft.	25 ft./10 - 25 ft.
1079	10 - 20 ft.	15 - 20 ft.	70 ft./55 - 70 ft.
1080	10 - 12 ft.	2 - 3.5 ft.	15 ft./ 5 - 15 ft.
1081	10 - 12 ft.	2 - 3.5 ft.	70 ft./55 - 70 ft.
1082	10 - 12 ft.	2 - 3.5 ft.	15 ft./ 5 - 15 ft.
1083	6 - 12 ft.	1.5 - 4.5 ft.	15 ft./ 5 - 15 ft.
1084	5 - 10 ft.	2 - 5 ft.	15 ft./ 5 - 15 ft.
1085	5 - 10 ft.	2 - 5 ft.	70 ft./55 - 70 ft.
1086	7 - 9 ft.	5 - 15 ft.	20 ft./ 5 - 20 ft.

* Estimated depth to rock and maximum and minimum depths to groundwater are based on available piezometer data through July, 1987.

674 and 698).

- * Only the last 0.77 ft. of piezometer number 675 penetrated bedrock.
- ** Piezometer number 674 is constructed with the base of its screen at the same elevation as the top of bedrock.

APPENDIX III

Proposed Water Quality Well Configuration Types And Design Coordinates

WAG 7

<u>Well No. And Configuration Type</u>		<u>Estimated Coordinate (ORNL Grid-Feet)</u>
1071	Type A	E 27,184 N 19,256
1072	Type B	E 26,120 N 19,170
1073	Type B	E 26,084 N 19,196
1074	Type A	E 25,814 N 18,203
1075	Type B	E 25,778 N 18,167
1076	Type B	E 25,868 N 17,899
1077	Type B	E 25,838 N 17,840
1078	Type A	E 25,645 N 17,502
1079	Type B	E 25,631 N 17,467
1080	Type A	E 25,975 N 16,847
1081	Type B	E 26,301 N 17,023
1082	Type A	E 26,300 N 16,988
1083	Type A	E 27,208 N 17,003
1084	Type A	E 27,867 N 17,295
1085	Type B	E 27,876 N 17,327
1086	Type A	E 28,211 N 17,521

APPENDIX III

Proposed Water Quality Well Design Criteria And Estimated Completion Depths

WAG 8

<u>Well No.</u>	<u>Estimated Depth to Rock*</u>	<u>Estimated Maximum And Minimum Depths To Groundwater*</u>	<u>Estimated Completion Depth And Screened Interval</u>
1087	11 - 20 ft.	8 - 12 ft.	20 ft./10 - 20 ft.
1088	18 - 22 ft.	15 - 25 ft.	30 ft./15 - 30 ft.
1089	10 - 20 ft.	10 - 25 ft.	30 ft./15 - 30 ft.
1090	10 - 20 ft.	10 - 25 ft.	70 ft./55 - 70 ft.
1091	8 - 12 ft.	5 - 10 ft.	15 ft./ 5 - 15 ft.
1092	5 - 15 ft.	15 - 25 ft.	70 ft./55 - 70 ft.
1093	5 - 15 ft.	15 - 25 ft.	30 ft./15 - 30 ft.
1094	6 - 8 ft.	3 - 6 ft.	70 ft./55 - 70 ft.
1095	6 - 8 ft.	3 - 6 ft.	15 ft./ 5 - 15 ft.

* Estimated depth to rock and maximum and minimum depths to groundwater are based on available piezometer data through July, 1987.

APPENDIX III

Proposed Water Quality Well Configuration Types And Design Coordinates

WAG 8

<u>Well No. And Configuration Type</u>		<u>Estimated Coordinate (ORNL Grid-Feet)</u>
1087	Type A	E 29,503 N 19,970
1088	Type B	E 30,350 N 19,179
1089	Type B	E 31,425 N 19,170
1090	Type B	E 31,467 N 19,200
1091	Type A	E 32,186 N 18,887
1092	Type B	E 32,421 N 18,766
1093	Type B	E 32,453 N 18,755
1094	Type B	E 31,319 N 16,644
1095	Type A	E 31,292 N 16,620

APPENDIX III

Proposed Water Quality Well Design Criteria And Estimated Completion Depths

WAG 9

<u>Well No.</u>	<u>Estimated Depth to Rock*</u>	<u>Estimated Maximum And Minimum Depths To Groundwater*</u>	<u>Estimated Completion Depth And Screened Interval</u>
1089**	10 - 20 ft.	10 - 25 ft.	30 ft./15 - 30 ft.
1090**	10 - 20 ft.	10 - 25 ft.	70 ft./55 - 70 ft.
1096	8 - 12 ft.	2 - 4 ft.	15 ft./ 5 - 15 ft.
1097	14 - 20 ft.	4 - 8 ft.	15 ft./ 5 - 15 ft.
1098	12 - 18 ft.	4 - 8 ft.	15 ft./ 5 - 15 ft.
1099	12 - 18 ft.	6 - 10 ft.	70 ft./55 - 70 ft.

* Estimated depth to rock and maximum and minimum depths to groundwater are based on available piezometer data through July, 1987.

** These wells are to be installed as part of the WAG 8 monitoring system but will also serve as upgradient wells for WAG 9.

APPENDIX III

Proposed Water Quality Well Configuration Types And Design Coordinates

WAG 9

<u>Well No. And Configuration Type</u>		<u>Estimated Coordinate (ORNL Grid-Feet)</u>
1089*	Type B	E 31,425 N 19,170
1090*	Type B	E 31,467 N 19,200
1096	Type A	E 31,553 N 18,670
1097	Type A	E 31,516 N 18,495
1098	Type A	E 31,407 N 18,468
1099	Type B	E 31,385 N 18,495

- * These wells are to be installed as part of the WAG 8 monitoring system but will also serve as upgradient wells for WAG 9.

APPENDIX IV

Partial Inventory Of Preremedial Action
Program Wells - WAG 7

APPENDIX IV

Partial Inventory Of Preremedial Action Program Wells - WAG 7

<u>Well #</u>	<u>Easting</u>	<u>Northing</u>
SB-1	27,631	17,594
SB-2	27,630	17,619
SB-20	27,636	17,430
SB-4	27,685	17,583
SB-6	27,531	17,625
T403	25,917	17,703
T404	25,857	17,619
T405	26,098	17,556
T408	26,185	17,502
T411	25,798	17,299
T412	25,687	17,309
T416	26,100	17,264
T418	26,548	17,400
T419	26,564	17,342
T5-4	26,749	17,340
T6-1	27,795	18,731
T6-3	28,005	18,691
T7-10	27,729	17,385
T7-21	27,729	17,383
T7-22	27,725	17,395
T7-23	27,720	17,419
T7-24	27,714	17,443
T7-25	27,709	17,483
T7-27	27,702	17,532
T7-29	27,698	17,638
T7-3	27,659	17,468
T7-4	27,632	17,351
T7-5	27,540	17,376
T7-6	27,567	17,549
T7-7	27,590	17,575

APPENDIX IV (Con't.)

<u>Well #</u>	<u>Easting</u>	<u>Northing</u>
T7-9	27,656	17,369
WT5-1	26,361	17,169
WT5-3	26,439	17,358
WT5-5	26,489	17,492
WT5-8	26,328	17,065
WT7-2	27,762	17,160
WT7-3	27,785	17,223
WT7-5	27,811	17,384
WT7-5A	27,820	17,415
WT7-6	27,818	17,443
WT7-6A	27,820	17,481
WT7-7	27,822	17,512
WT7-8	27,617	17,336
0065	25,945	18,988
0066	25,932	18,867
0067	26,136	18,468
0070	25,834	18,719
0083	26,191	17,285
0084	26,224	17,162
0093	25,984	17,058
0094	25,985	16,960
0096	26,251	17,498
0097	26,453	17,598
0098	26,531	17,715
0099	26,575	17,777
0103	25,760	17,074
0104	25,660	16,957
0114	26,433	18,148
0124	26,079	17,916
0125	25,995	17,874
0187	27,544	18,786

APPENDIX V
BIBLIOGRAPHY

APPENDIX V
Bibliography

1. Acree, E.H. - December 11, 1963, Intra-Laboratory Correspondence, Disposal Of Residual HRT Fuel.
2. Beall, S.E. - April 2, 1964, Intra-Laboratory Correspondence, HRT Fuel Solution, Transfer And Disposal Of.
3. Beatty, G. - 1987, RCRA Inspection Report; EPA.
4. Boyle, J.W., et al. - 1982, Environmental Analysis Of The Operation Of Oak Ridge National Laboratory (X-10 Site); ORNL-5870.
5. Brogan, D. - * Intra-Laboratory Correspondence, Disposal Of Residual HRT Fuel.
6. Bruce, F.R. - January 31, 1964, Intra-Laboratory Correspondence, Disposal Of Residual HRT Fuel.
7. Burnett, T.J. - July 20, 1970, Intra-Laboratory Correspondence, Leak In Liquid Waste Transfer Line.
8. Burnett, T.J. - August 14, 1969, Intra-Laboratory Correspondence, Leak In Intermediate-Level Liquid Waste Transfer Line.
9. Burnett, T.J. - September 15, 1970, Intra-Laboratory Correspondence, Leakage Of Waste Transfer Line.
10. Cagle, C.D. and Pugh, L.P. - 1976, Decommissioning Study For The Homogeneous Reactor Experiment No. 2 (HRE-2); ORNL/CF-76/66.

* Date Not Legible.

Bibliography - Page 2

11. Cerling, T.E. and Spalding, B.P. - 1981, Areal Distribution Of Co^{60} , Cs^{137} and Sr^{90} In Streambed Gravels Of White Oak Creek Watershed, Oak Ridge, Tennessee; ORNL/TM-7318.
12. Cerling, T.E. and Spalding, B.P. - 1982, Distribution And Relationship Of Radionuclides To Streambed Gravels In A Small Watershed; Environmental Geology 4:99-116.
13. Davis, E.C., et al. - 1984, Site Characterization Techniques Used At A Low Level Shallow Land Burial Field Demonstration Facility; ORNL/TM-9146.
14. de Laguna, W., et al. - 1968, Engineering Development Of Hydraulic Fracturing As A Method For Permanent Disposal Of Radioactive Wastes; ORNL-4259.
15. Doyle, T.W. and Taylor, F.G. - 1986, ORNL Contaminant Scoping Survey; RAP86-48.
16. Dreier, R.B. - 1987, Summary Of Geological Data In The Vicinity Of The Hydrofracture Facilities; ORNL/RAP/LTR-87/26.
17. Edgemon, B. - June 15, 1987, Personal Communication.
18. Edwards, N.T. - 1986, Inventory Of ORNL Remedial Action Sites: 2. LLW Seepage Pits And Trenches; RAP86-27/R1.
19. Edwards, N.T. - 1986, Inventory Of ORNL Remedial Action Sites: 8. Radioisotope Processing Facilities; RAP86-37/R1.
20. Francis, C.W. and Stansfield, R.G. - 1986, Ground Water Monitoring At Three Oak Ridge National Laboratory Inactive Waste Impoundments; ORNL/TM-10193.

Bibliography - Page 3

21. Grimsby, H.J. - 1986, Identification Of Low-Level Waste Line Leak Sites At Oak Ridge National Laboratory; Letter Report RAP86-8.
22. Haase, C.S., et al. - 1985, Stratigraphic And Structural Data For The Conasauga Group And The Rome Formation On The Copper Creek Fault Block Near Oak Ridge, Tennessee: Preliminary Results From Test Borehole, ORNL-JOY No. 2; ORNL/TM-9159.
23. Huang, S.G., et al. - 1984, Preliminary Radiological Characterization Of The Homogeneous Reactor Experiment No. 2 (HRE-2); ORNL/CF-84/201.
24. Huff, D.D. - 1985, Summary Of Dry-Weather Dye Tracing Activities; Letter Report.
25. Ketelle, R.H. - 1986, Ground Water System Characterization, ORNL Letter Report; RAP86-75.
26. Lasher, L.C. - June 10, 1987, Personal Communication.
27. Lee, R. - July, 1987, Personal Communication.
28. Lee, R. - In Preparation, Environmental Data Package For Waste Area Grouping 9: The Homogeneous Reactor Experiment.
29. Lyon, R.W. - * Intra-Laboratory Correspondence, Recommendations Of The Waste Effluents Committee On Disposal Of Residual HRT Fuel Waste.
30. MCI Consulting Engineers, Inc. - 1985, Liquid Low Level Waste System, Active Storage Tanks, Closure Plan.

* Date Not Legible.

Bibliography - Page 4

31. MCI Consulting Engineers, Inc. - 1985, Liquid Low Level Waste System, Active Storage Tanks, Ground Water Monitoring Plan.
32. MCI Consulting Engineers, Inc. - 1986, RCRA Monitoring Well Installation Report Surface Impoundments 3524, 3539, 3540, 7905, 7906, 7907, 7908.
33. McMasters, W.M. - 1958, Geologic Map Of The Oak Ridge Area.
34. Morris, M. - June 15, 1987, Personal Communication.
35. Olsen, C.R., et al. - 1983, Chemical, Geological and Hydrological Factors Governing Radionuclide Migration From A Formerly Used Seepage Trench: A Field Study; ORNL/TM-8839.
36. ORNL General Engineering Division - January 31, 1972 Revised September 8, 1975, The Tabulation Of Contaminated Ground Areas In ORNL, Bethel Valley And Melton Valley.
37. ORNL - 1987, RCRA Facilities Assessment (RFA) - Oak Ridge National Laboratory; ORNL/RAP-12/V1.
38. Palmer, A.N. - 1981, Hydrochemical Factors In The Origin Of Limestone Caves, in B.F. Beck, ed., Proc. Of The Eighth International Congress Of Speleology, Bowling Green Kentucky: National Speleological Society, Huntsville, Alabama.
39. Reed, W.R. - 1984, Preliminary Decommissioning Study Reports Volume 6: Homogeneous Reactor Test; X-OE-231, Vol. 6.
40. Reed, W.R. - 1984, Preliminary Decommissioning Study Reports Volume 12: HRT Retention Pond; X-OE-231, Vol. 12.

Bibliography - Page 5

41. Rodgers, J. - 1953, Geologic Map Of East Tennessee With Explanatory Text; Bulletin 58, Part II - State of Tennessee, Department of Conservation, Division of Geology.
42. Schaich, R.W. - February 12, 1964, Intra-Laboratory Correspondence, Disposal Of HRT Fuel Waste.
43. Spalding, B.P. and Cerling, T.E. - 1979, Association Of Radionuclides With Streambed Sediments In White Oak Creek Watershed; ORNL/TM-6895.
44. Spalding, B.P. and Boeghy, W.J., Jr. - 1985, ORNL Radioactive Liquid Waste Disposal Pits And Trenches: History, Status And Closure Characterization Needs; ORNL/CF-85/70.
45. Spalding, B.P. - 1987, Environmental Data Package For The ORNL Seepage Pits And Trenches Waste Area Grouping; ORNL/RAP-10.
46. Stansfield, R.G. and Francis, C.W. - 1985, Characterization Of The Homogeneous Reactor Experiment No. 2 (HRE) Improvement; ORNL/CF-85/415.
47. Stockdale, P.B. - 1951, Geologic Conditions At the Oak Ridge National Laboratory (X-10) Area Relative to the Disposal of Radioactive Waste.
48. Taylor, F.G. - 1986, Inventory Of ORNL Remedial Action Sites: 3. Process Ponds; Letter Report RAP86-14/R1.
49. Taylor, F.G. - 1986, Inventory Of ORNL Remedial Action Sites: 10. Radwaste Facilities; Letter Report RAP86-22/R1.

Bibliography - Page 6

50. Walker, K.R., et al. - 1985, The Geologic History Of The Thorn Hill Paleozoic Section (Cambrian-Mississippian), Eastern Tennessee, SE-GSA Field Trip 6; University of Tennessee, Knoxville Publication R01-1040-03-002-85.
51. Webster, D.A. - 1976, A Review Of Hydrologic And Geologic Conditions Related to the Radioactive Solid Waste Burial Ground At Oak Ridge National Laboratory, Tennessee; USGS Open-File Report 76-727.

INTERNAL DISTRIBUTION

1. J. S. Baldwin
2. T. W. Burwinkle
3. K. E. Cook
4. D. D. Huff
5. L. D. Hyde
6. R. H. Ketelle
7. J. R. Lawson
8. G. K. Moore
9. J. B. Murphy
10. T. E. Myrick
11. C. E. Nix
- 12-15. P. T. Owen
16. T. P. A. Perry
17. L. E. Stratton
18. J. R. Trabalka
19. L. D. Voorhees
20. Central Research Library
21. ORNL Patent Section
- 22-24. Laboratory Records Department
25. Y-12 Technical Library

EXTERNAL DISTRIBUTION

26. Assistant Manager, Energy Research and Development Department,
Department of Energy, Oak Ridge Operations, P. O. Box E, Oak
Ridge, Tennessee 37831.
27. J. Nemec, BNI, Oak Ridge, Tennessee.
- 28-29. Technical Information Center, P. O. Box 62, Oak Ridge, Tennessee
37831.

END

**DATE
FILMED**

11 / 23 / 92