WSRC-RP--91-1151

DE92 040047

**SPRAY NOZZLE PATTERN TEST FOR THE DWPF HEME
TASK TECHNICAL PLAN(U)**

by

L. Lee

Westinghouse Savannah River Company
Savannah River Site
Aiken, South Carolina 29808

Received by OSTI

AUG 31 1992

This report was prepared in connection with work done under Contract No. DE-AC09-89SR18035 with the U.S. Department of Energy. By acceptance of this report, the publisher and/or recipient acknowledges the U.S. Government's right to retain a nonexclusive, royalty-free license in and to any copyright covering this report, along with the right to reproduce and to authorize others to reproduce all or part of the copyrighted report.

MASTER

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

This report has been reproduced directly from the best available copy.

Available to DOE and DOE contractors from the Office of Scientific and Technical Information, P.O. Box 62, Oak Ridge, TN 37831; prices available from (615) 576-8401, FTS 626-8401.

Available to the public from the National Technical Information Service, U.S. Department of Commerce, 5285 Port Royal Rd., Springfield, VA 22161.

Westinghouse Savannah River Company
Savannah River Laboratory

WSRC-RP-91-1151

Keywords: HEME, HEPA,
Spray Pattern,
Spray Nozzle

Retention Period: permanent

CC E. W. Holtzscheiter, 773-A
T. K. Snyder, 704-T
R. E. Roaden, 704-T
J. F. Sides, 679-T
P. R. Burket, 704-27S
L. A. Patterson, 704-30S
SRL Records (4)

To: C. T. Randall, 704-T

From: L. Lee, 704-T *Lee*

November 15, 1991

SPRAY NOZZLE PATTERN TEST FOR THE DWPF HEME
TASK TECHNICAL PLAN (U)

INTRODUCTION:

The DWPF melter off-gas systems have two High-Efficiency Mist Eliminators (HEME) upstream of the High-Efficiency Particulates Air filters (HEPA) to remove fine droplets and particulates from the off-gas. The HEMEs consist of three filter candles. Each filter candle consists of a 0.5" layer of 30 micron diameter glass fiber on the upstream face followed by a 2.5" layer of 8-micron-diameter glass fiber packed at 11 lbs per cubic foot. The coarse 30-micron filter serves as a prefilter and extends the life of the HEME filter. To have an acceptable filter life and an efficient HEME operation, air atomized water is sprayed into the off-gas stream entering the HEME and onto the HEME surface. The water spray keeps the HEME wet which would dissolve the soluble particulates and enhance the HEME efficiency. A properly designed spray nozzle should wet the three candles of the HEME filter completely.

Authorized Derivative Classifier:

C. T. Randall

This task was requested by DWPF Technical because the nozzle provided for the DWPF melter off-gas HEMEs has a published minimum water flow rate approximately 4X that specified by SRL in the DWPF Basic Data Report (BDR). It is believed that the water flow can be throttled back and an acceptable spray will still be produced. Atomizing air conditions to produce this spray at the reduced water rate are sought.

TASK DELIVERABLE:

A preliminary report stating whether or not the current nozzle is acceptable and specifying any nozzle, piping or instrumentation changes required will be issued by December 6, 1991.

A ~~final~~ report specifying the alternate air pressure operating range will be issued after completion of the task. The report will be issued by 2/92.

The customer will be kept informed about the progress of this task. Inputs from customer before and during the test will be incorporated into the task. Any revision to the BDR will be clearly stated in the final report to facilitate its revision by the proper DWPF authority.

TASK PREREQUISITES:

Since the air pressure and flow rate to generate the desired spray pattern are not known before hand, this task will include two stages. The first stage involves preliminary experiments to map out the general operating region which envelops the conditions to produce the desired spray conditions. The results of these preliminary experiments will be used to select the optimal ranges of flow meters and pressure gages for the testing facility. They will also be used to determine if the current DWPF nozzle and the DWPF HEME spray system can be used at the BDR specified water flow rate. This information will be used in the second stage to fine tune the air flow rate and pressure and identify the precise conditions under which the spray nozzle is to be operated.

TASK REQUIREMENTS:

According to the BDR, the water flow rate is 0.3 GPH. This will be the basis for experiments described here. However, the customer expressed his desire to run the experiment at a water flow rate of 1.1 GPH also, which is the minimum water flow rate suggested by the nozzle manufacturer. The spray nozzle to be tested was supplied by the customer. It is one of the actual nozzles to be used in the DWPF.

An acceptable spray has been established by DWPT and DWPF Technical. The water should be atomized completely into a very fine mist. The fine mist will be carried along by the off-gas and will wet the HEME. The purpose of this task is to determine the air flow rates and pressures which will deliver an acceptable spray which is indicated by the fineness and dispersion of the atomized water and an absence of water drip at the nozzle. The fineness of the mist and the dispersion will be observed by the task leader and the customer and judged acceptable if the combination will obviously wet the HEME element. Since the available plant air supply is about 90 psig, the air pressure to give acceptable spray pattern must be below 90 psig, or preferably below 60 psig.

Since air is compressible, the pressure at the rotameter has to be measured in order to calculate the air flow rate. Also, an air pressure gage is required between the needle valve, which regulates air flow rate, and the spray nozzle. The last pressure gage gives air pressure at the inlet of the spray nozzle, ie. the pressure which is actually available for atomizing the water. The customer has indicated his desire to use this pressure as an indicator of air flow rate instead of using a rotameter.

Customer review of this document shall signify concurrence with the statement of task requirements above.

TASK ACTIVITY:

The spray nozzle to be tested, spray nozzle jumper and two Hanford connectors are supplied by the customer. Fabrication of the Spray Nozzle Test Facility at TNX shall be completed by the TOS Works Engineering based on the input supplied by the DWPT task leader. Prior to the first stage of the task, a safety review will be performed by the SRL safety engineer, TOS Works Engineering, TOS Operations Support Group and the task leader. Under the guidance of the task leader the TOS Operations Group shall be responsible for the operation of the facility. After the preliminary tests the flow meters and pressure gages shall be changed to give the optimal measurements around the conditions which produce an acceptable spray. The customer will be invited to witness the test.

JOB PLANS:

DWPT shall be responsible for the preparation and issuance of job plans for the operation of the Spray Nozzle Test Facility.

OPERATIONS SUPPORT:

The TOS Operations Group shall be responsible for providing operator coverage for the spray nozzle test facility.

TESTING AND DATA EVALUATION:

The DWPT task leader shall be responsible for providing test conditions. The DWPT task leader shall be responsible for data evaluation and recommending conditions which give an acceptable spray pattern. The DWPT task leader is also responsible for reporting the findings and recommendations to the customer.

CHANGES TO THE TASK TECHNICAL PLAN:

Minor changes to this task technical plan will be noted in laboratory notebook #58091.

Review and Approvals:

Reviewed By:

Paul Burket 12/6/91
P. R. Burket, Manager Senior Engineer Date
DWPf Technical

Approved By:

C. T. Randall 12/4/91
C. T. Randall, Manager Date
Process Modeling & Control Group

Service Organization Concurrence:

R. E. Roaden 12/4/91
R. E. Roaden, Manager Date
TOS Works Engineering

J. F. Sides 12/4/91
J. F. Sides, Manager Date
TOS Operations Group

END

**DATE
FILMED**

10 / 15 / 92