20-92 JS①

ORNL/Sub/89-SE500/1

**OAK RIDGE
NATIONAL
LABORATORY**

MARTIN MARIETTA

**Evaluation and Silicon Nitride
Internal Combustion Engine
Components**

Final Report

W. Voldrich

**CERAMIC TECHNOLOGY FOR
ADVANCED HEAT ENGINES**

**MANAGED BY
MARTIN MARIETTA ENERGY SYSTEMS, INC.
FOR THE UNITED STATES
DEPARTMENT OF ENERGY**

This report has been reproduced directly from the best available copy.

Available to DOE and DOE contractors from the Office of Scientific and Technical Information, P.O. Box 62, Oak Ridge, TN 37831; prices available from (615) 576-8401, FTS 626-8401.

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

EVALUATION OF SILICON NITRIDE
INTERNAL COMBUSTION ENGINE COMPONENTS

W. Voldrich

Date Published-April 1992

FINAL REPORT, PHASE I

Prepared by
Garrett Ceramic Components Division
Allied-Signal Aerospace Company
Torrance, California 90509
86X-SE500V

Funded by
Office of Transportation Materials
Office of Transportation Technologies
the Assistant Secretary for Conservation and Renewable Energy
U.S. Department of Energy
EE 51 01 00 0

for
OAK RIDGE NATIONAL LABORATORY
Oak Ridge, Tennessee 37831
managed by
MARTIN MARIETTA ENERGY SYSTEMS, INC.
for the
U.S. DEPARTMENT OF ENERGY
under Contract DE-AC05-84OR21400

MASTER

TABLE OF CONTENTS

Section

	LIST OF FIGURES	.iii
	LIST OF TABLES	iv
1.	INTRODUCTION AND SUMMARY	1
2.	EXPERIMENTAL	3
	2.1 CERAMIC COMPONENT SELECTION	3
	2.2 COMPONENT FABRICATION	3
	2.3 COMPONENT EVALUATION	6
3.	RESULTS AND DISCUSSION	7
	3.1 GS-44 SILICON NITRIDE COMPONENT PROPERTIES	7
	3.2 COMPONENT TESTING	8
	3.2.1 Valve Spring Retainer	8
	3.2.2 Tappet Rollers	9
	3.2.3 Fuel Pump Push Rod End	9
4.	CONCLUSIONS	.11
5.	POSSIBLE FUTURE PROGRAMS	.12
6.	APPENDICES	.13
	1. COMPONENT PRINTS	.14
	2. COMMUNICATIONS/REPORTS	.18

LIST OF FIGURES

Figure	Page
2.1. GS-44 Silicon Nitride Process Flow Chart	4
2.2. Photograph of a GS-44 Silicon Nitride Valve Spring Retainer	5
2.3. Photograph of a GS-44 Silicon Nitride Tappet Roller . . .	5
2.4. Photograph of a GS-44 Silicon Nitride Fuel Pump Push Rod End	6

LIST OF TABLES

Table	Page
3.1. SINTERED DENSITY OF FINISHED COMPONENTS	7
3.2. FLEXURE STRENGTH, FRACTURE TOUGHNESS, WEIBULL MODULUS . . .	8

EVALUATION OF SILICON NITRIDE INTERNAL COMBUSTION ENGINE COMPONENTS

W. Voldrich

ABSTRACT

Feasibility of silicon nitride (Si_3N_4) use in internal combustion engines was studied by testing three different components for resistance and lower reciprocating mass. The information obtained from these preliminary spin rig and engine tests indicates several design changes are necessary to survive high-stress engine applications. The three silicon nitride components tested were valve spring retainers, tappet rollers, and fuel pump push rod ends.

'Ceramtec Ceramic Components' gas-pressure sinterable Si_3N_4 (GS-44) was used to fabricate the above components. Components were finally made from densified blanks that had been green formed by isostatic pressing of GS-44 granules.

Spin rig testing of the valve spring retainers indicated that the Si_3N_4 components could survive at high RPM levels (9,500) when tested with silicon nitride valves and lower spring tension than standard titanium components. Silicon nitride tappet rollers showed no wear on roller O.D. or I.D. surfaces, steel axles and lifters; however, due to the uncrowned design of these particular rollers the cam surfaces indicated wear after spin rig testing. Fuel pump push rod ends were successful at reducing wear on the cam lobe and rod end when tested on spin rigs and in real-world race applications.

INTRODUCTION AND SUMMARY

Silicon nitride (Si_3N_4) has emerged as the leading candidate material for selected components in Internal Combustion Engines (ICE). However, commercialization of this technology has been very slow due to high component cost, and lack of production experience and reliability data in actual applications.

Automobile racing has long been used as a fast test bed for new technology and components which, at a later date, found their way to mass-produced engines and vehicles. Although this is a much smaller market than that for passenger cars, it is a good niche market to introduce ceramic engine components. Production experience

Revised and sponsored by the U.S. Department of Energy, Assistant Secretary for Conservation and Renewable Energy, Office of Transportation Technologies, as part of the Ceramic Technology for Advanced Heat Engines Project of the Advanced Materials Development Program under contract DE-AC02-81-OR21400 with Martin Marietta Energy Systems, Inc.

obtained in this market would lead to faster scale-up when the mass market opens up for these components.

The objective of this program was to fabricate several ceramic components and to evaluate them in an internal combustion engine application. By using silicon nitride components as direct replacements of metal components, specific benefits could be gained in terms of less component wear (tappet roller and fuel pump push rod end) or lower reciprocating mass (valve spring retainer and tappet roller).

This research was sponsored by DOE/ORNL under the "Ceramic Technology for Advanced Heat Engines Program", Subcontract No. 86X-SE500V. This subcontract consisted of two technical tasks. Task 1 focused on the fabrication of the three selected components using Garrett Ceramic Components' GS-44 silicon nitride material. The GS-44 granulated silicon nitride material was processed in January, 1990, while the spray dried GS-44 was processed in June and July 1990. The objective of Task 2 was to have representative samples of the silicon nitride components evaluated in high-speed spin fixtures, followed by testing in race car engines if the fixture testing was successful. Testing by American Ceramic Engine Company and other end users started in June, 1990 and was completed by July 1991, with one component (fuel pump push rod end), used in competition race engines from February 1991, to September 1991. Three components were fabricated by Garrett Ceramic Components using gas-pressure sintered GS-44 silicon nitride: valve spring retainers, tappet rollers, and fuel pump push rod ends. The fabrication method was to machine components from simple-shape blanks which were cold isopressed from either hand-granulated or spray dried granules of GS-44 powder.

The components fabricated under Task 1 were provided to American Ceramic Engine Company (ACE) to perform and/or arrange for the actual performance testing at no cost to the contract.

The GS-44 silicon nitride valve spring retainer in combination with a silicon nitride valve gave improved valve motion control as well as less closed seat pressure when tested on an Optron spin fixture. Failure did not occur until an RPM level much higher (9,600 RPM) than that usually encountered in NASCAR racing (8,500 RPM) was reached. The prime cause was the small contact area at the bottom of the tapered spring retainer I.D./valve keeper interface.

Tappet roller tests on spin fixtures indicated there was no wear on the GS-44 roller O.D. or I.D. as well as the steel axle and lifter. However, due to the hardness of the GS-44 silicon nitride roller and the absence of a crown on the roller O.D. there was wear on the cam lobes. Future rollers should be crowned to minimize cam lobe wear.

Fuel pump push rod ends tested on spin rigs, dynamometer engine tests, and real world race applications achieved the desired result of minimal wear on the fuel pump cam lobe and rod end. There was only one silicon nitride rod end failure (on a spin rig test) and its reason for chipping has not been determined. It is felt that as a result of the above experience with the GS-44 silicon nitride rod end, it is the component closest to suitability for commercial production.

EXPERIMENTAL

2.1 CERAMIC COMPONENT SELECTION

Three components were selected for evaluation in this program. The components were: valve spring retainers, tappet rollers, and fuel pump push rod ends. Silicon nitride components were used in place of metal components because of two important performance considerations. The reduction of reciprocating mass in valve trains would be helped with the use of GS-44 valve spring retainers and tappet rollers. Lower component wear would be the prime contribution of silicon nitride tappet rollers and fuel pump push rod ends. Appendix 1 contains the prints for the selected components which were fabricated from GS-44 silicon nitride.

2.2 COMPONENT FABRICATION

Garrett Ceramic Components' GS-44 silicon nitride, a gas-pressure sinterable material was used for this program. The fabrication method was to machine components from simple-shape blanks after densification. The blanks were formed by high pressure wet-bag isostatic pressing of GS-44 granules. Pressed shapes were rods ($3/4$ " dia. x 6" long), billets (2" dia. x 3" long), and tubes (1" dia. x 4" long and $2\frac{1}{2}$ " dia. x $3\frac{1}{4}$ " long).

The GS-44 silicon nitride granules used to fabricate the automotive components for testing by American Ceramic Engine Company (ACE) were processed using typical ceramic wet processing methods to obtain a granule that could be pressed into blanks that would then receive additional heat treatment prior to final machining. The process flow chart is shown in Figure 2.1. Over the course of the program, the process progressed from a hand granulation of -50 mesh bulk dried material to use of a spray dryer for rapid drying of aqueous slurry to obtain flowable granules.

There was no change in the raw materials used to produce either hand granulated or spray dried granules that were then cold isostatic pressed into the shapes used to fabricate finished components.

Final machining of all GS-44 silicon nitride components was done at Advanced Ceramic Technology, Orange, California. All finished parts were tested for density by the Archimedes density method as well as visually inspected and dimensionally checked. The surface finish for the valve spring seat, the fuel pump push rod end friction surface, and the cam roller O.D. was typically 8-16 microinches. Figures 2.2 to 2.4 show examples of the components evaluated in this program.

A total of twenty fuel pump push rod ends, one hundred tappet rollers, and ninety-six valve spring retainers were delivered to American Ceramic Engine Company for evaluation. It is from these components that the test data was gathered by ACE. Eighteen fuel pump push rod ends, five tappet rollers, and three valve spring retainers were evaluated during the program.

POWDER BATCHING:

☐ Silicon Nitride, Sinter Aids, Binders, D I Water

POWDER WET MIXING

☐ Process Checks pH, Viscosity, Specific Gravity

SPRAY DRYING/HAND GRANULATION

☐ Process Checks RPM-Atomizer, Chamber Temperature (Spray Dry)

☐ Process Checks Drying Oven Temperature & Hold Time (Hand Granulation)

SCREENING

☐ Spray Dried Material Scalp Under/Over Size
Hand Granulated Material -50 Mesh

ISOPRESS

☐ Process Checks Pressure, Time

PRE-HEAT TREATMENT

☐ Process Checks Weight Loss, Visual Inspection

SINTERING

☐ Process Checks Density, Shrinkage, Visual Inspection

MACHINING

☐ Process Checks Dimensions, Surface Roughness

FINAL INSPECTION

☐ Density, Visual Inspection, Flexure Strength,
Fracture Toughness, Hardness

Figure 2.1. GS-44 Silicon Nitride Process Flow Chart

Figure 2.2. Photograph of GS-44 Silicon Nitride Valve Spring Retainers

Figure 2.3. Photograph of a GS-44 Silicon Nitride Tappet Roller.

Figure 2.4. Photograph of GS-44 Silicon Nitride Fuel Pump Push Rod Ends

2.3 COMPONENT EVALUATION

Selected components delivered to American Ceramic Engine Company were evaluated in spin test fixtures and/or in race car engines. In general, the tests focused on wear resistance (fuel pump push rod, tappet rollers) or strength at high RPM (valve spring retainers). Spin test fixtures were of the Optron type or proprietary design while race engine evaluations were on high compression, high RPM V-8 engines.

RESULTS AND DISCUSSION

3.1 GS-44 SILICON NITRIDE COMPONENT PROPERTIES

The silicon nitride blanks from which the components were machined were fabricated using Garrett Ceramic Components' standard processes and process monitoring methods. Multiple batches of material were processed in fabricating the parts. All batches used in the fabrication of the components achieved a density greater than 98.6% of theoretical. Table 3.1 shows the average Archimedes densities of the dense, fully machined components.

Table 3.1
Sintered Density of Finished Components

GS-44 BATCH ID	PROCESS	NO.	DENSITY	STD.DEV.
FUEL PUMP PUSH ROD END 90A-044	Granulate	23	3.206 g/cc	0.005
TAPPET ROLLER 90A-044	Granulate	100	3.203 g/cc	0.017
VALVE SPRING RETAINER 90B-128	Granulate	35	3.221 g/cc	0.004
VALVE SPRING RETAINER 90F-483 & 90G-591	Spray Dry	71	3.224 g/cc	0.004

Mechanical properties including 4-point flexure strength, Chevron notch fracture toughness and Weibull modulus were measured at room temperature for each batch. The results are presented in Table 3.2.

The spray drying process for GS-44 has been refined and modified over the past year with new dispersants, binders, and plasticizers. These changes have given Garrett Ceramic Components the capacity to produce spray dried material with uniform flexure strength (138.3 ksi +/- 5.5 ksi) batch to batch. Further process improvements are being tested to both improve performance and uniformity.

Table 3.2
Flexure Strength, Fracture Toughness, Weibull Modulus

BATCH I.D.	PROCESS	FLEX. STRENGTH	WEIBULL	FRACTURE TOUGHNESS
90A-044	Granulate	125.4 ksi	8.64	4.46 MPa m ^{1/2}
90B-128	Granulate	112.0 ksi	----	----
90C-206	Granulate	105.7 ksi	6.61	----
90G-591	Spray Dry	132.8 ksi	13.71	6.28 MPa m ^{1/2}

3.2 COMPONENT TESTING

American Ceramic Engine Company performed or arranged for all the component testing performed under this subcontract. This section summarizes the test results. The test reports received from ACE are in Appendix 2.

3.2.1 Valve Spring Retainer

The valve spring retainer tested at the Chevrolet Race Shop gave better valve motion control when teamed with a light weight silicon nitride valve compared to standard titanium valves and retainers over the RPM range of 2000-9500 RPM. This control was achieved even though the silicon nitride valve train used a spring set-up that had 40% less seat pressure (156 pounds total) and 30% less open pressure (182 pounds total). Although this silicon nitride spring retainer/valve assembly broke at the retainer-lock interface at 9600 RPM, R.P. Larsen, of ACE, was of the opinion this was "---excellent performance for the first test of this component." An unplanned benefit of using the GS-44 seat was a "noticeably reduced" disassembly effort [refer to Appendix 2A].

The broken retainer was examined and a contact band was observed only 1/16" up and 1/32" wide from the bottom of the I.D. where the metal lock contacted the GS-44 spring retainer. This would indicate a need to redistribute the stresses across a broader area of the tapered retainer I.D. by redesigning the lock/retainer interface.

In tests at ACE with a high speed spin test rig the GS-44 silicon nitride spring retainers survived a three hour run at 7000 RPM when a single spring assembly was used. However, when tested at 7000 RPM with a two spring assembly the GS-44 retainer broke after less than one minute. In analyzing the results of the ACE spin rig test, R. Sekar stated, "Race cars generally use the double spring assembly with higher spring tension. Therefore this part, as it is currently

produced, is not strong enough in racing applications." The spring tension of the two spring ACE rig was higher (260 pounds) than that of the Chevrolet Race Shop test.

In the future, it should be possible to increase the strength of valve spring retainers by providing a larger radius at all O.D.-flange junctions and replace the 18 degree countersink at the top of the retainer with a blended radius to provide a thicker cross-section of silicon nitride material. This would allow successful completion of the above test. These changes should not necessitate redesign of other systems or components.

3.2.2 Tappet Roller

With respect to tappet rollers, R. Sekar of ACE outlined the primary problem of high performance component suppliers to race engine manufacturers "...is rapid wear of the steel roller axle, followed by failure of the needle bearings between the axle and metal roller" [refer to Appendix 2B]. In tests at Crane Cams GS-44 silicon nitride rollers with a 0.002"-0.003" axle to roller I.D. clearance were run for six hours at 3500 to 7500 RPM in a spin fixture with a stock car roller cam profile of the type used in oval track racing. There was no wear on the GS-44 rollers but the steel cam lobes "...showed definite tracks...the width of the rollers." The steel axle showed no wear from the silicon nitride roller I.D., "...and the lifter was in excellent shape" [refer to Appendix 2C].

In a separate test at ACE the GS-44 rollers were run on a spin fixture for three hours at a constant 7000 RPM. As with the Crane test, this second test with a stock car roller cam profile showed no wear on the roller O.D., however, there was "...significant wear...on the acceleration ramp of the cam...". Once again the steel roller axle and lifter did not show wear [refer to Appendix 2C].

At the conclusion of both roller tests it was felt that a crowned silicon nitride roller is necessary to avoid premature cam wear. Crane Cams was encouraged by the lack of wear at the steel axle/GS-44 roller interface and indicated an interest in doing further testing and development based on these initial results [refer to Appendix 2C].

3.2.3 Fuel Pump Push Rod End

Both ACE test reports dealing with fuel pump push rod ends were very positive after spin fixture testing and NASCAR race engines used them in competition to test resistance to wear. A spin rig test ran for more than five hundred hours at Competition Cams and "...was a complete success" [refer to Appendix 2B and 2D]. Tests by other engine component suppliers have had the same general success with an ACE spin test of five fuel pump push rod ends showing "...good initial results" after eight to sixteen hours at 8000 RPM. A sixth rod end tested at ACE was run for only 2.5 hours before the silicon nitride rod end on the cam side broke at the edge and sides [refer to Appendix 2B]. No reason for this failure was determined.

ACE feels : the GS-44 silicon nitride fuel pump push rod ends are ready for luction in terms of wear resistance and race experience.

Mr. Ben Ba, a Winston Cup engine builder was of the opinion that "it was test new component he ever had and plans to continue to use it throught the 1991 race season" [refer to Appendix 2B]. Two push rods : been alternated in one engine since February 1991.

CONCLUSIONS

The three components tested during this evaluation program proved they could provide usable improvements in performance. These tests also indicated that at least one design change could improve the reliability, strength, or cost effectiveness of valve spring retainers, fuel pump push rod ends, and cam rollers. A longer term series of dynamometer engine durability tests should be considered to prove the true level of serviceability of these components as well as test new designs based on the following recommendations.

In the case of the valve spring retainer, design changes to give the cross section a more robust character with a minimum increase in weight are possible. The design of a valve stem lock that distributes stress across a broader area of the tapered I.D. would also increase the performance limits of the silicon nitride valve spring retainer.

The tappet roller would benefit most directly by having a crown machined on the O.D. to reduce grooving of the cam lobes to acceptable levels. A concurrent test to make the surface of the cam lobes more resistant to the action of silicon nitride rollers could also be considered.

The most important change to the fuel pump push rod end design would be to simplify its cross-section in order to make the tooling needed to produce it less-expensive and its final assembly into the push rod less cumbersome.

POSSIBLE FUTURE PROGRAMS

Several design modifications to the components were discussed in this report. A Phase II program should be pursued to improve the robustness and to reduce component costs. Following fabrication, these parts should be evaluated to demonstrate their reliability.

The move toward cleaner burning, domestic source fueled engines provides a good real-world laboratory to test advanced materials in new applications. The use of silicon nitride components in internal combustion alternative fuel vehicles is a potential area where useful performance gains might be realized. Fuels such as methanol can be very corrosive to fuel delivery systems and can contaminate lubrication and lessen its friction reduction capabilities. Silicon nitride components could be placed in Championship Auto Racing Teams (CART) high performance engines (Indianapolis type) to test their resistance to wear in a methanol environment. Long term tests of these components in fleets of multi-fueled vehicles would also be an excellent reservoir of data for silicon nitride component durability and performance enhancement.

APPENDICES

APPENDIX

1

COMPONENT PRINTS

- A). Valve Spring Retainer; P/N P-90-006
- B). Tappet Roller; P/N E-89-012A
- C). Fuel Pump Push Rod End; P/N E-89-012D

P/N P-90-0006

THE AMERICAN CERAMIC ENGINE CO.
AN ILLINOIS CORPORATION

MADE BY	ELS	DATE	5/19/78	TITLE	VALVE SPRING RETAINER
DESIGNED BY	RPL	DATE	11/9/78		
APPROVED					
APPROVED					
INTERNAL				SCALE	QUANTITY ORDERED
SILICON NITRIDE				2 = 1	VSR-06889
					YES

APPENDIX

2

COMMUNICATIONS/REPORTS FROM AMERICAN CERAMIC ENGINE COMPANY

- A). 6/28/90: R.P. Larsen, Valve Seat Retainer Test Results,
Chevrolet Engine Race Shop
- B). 1/20/91: R. Sekar, Fuel Pump Push Rod Ends, Valve Spring
Seat Retainer, Tappet Rollers
- C). 6/20/91: R. Sekar, Tappet Rollers
- D). 6/25/91: R. Sekar, Fuel Pump Push Rod Ends
- E). 6/27/91: R. Sekar. Valve Spring Seat Retainers

AMERICAN CERAMIC ENGINE CO.

351 Gehrig Circle, Bolingbrook, Illinois 60439 • Phone: (312) 759-8989
June 28, 1990

Mr. Mike Heiser
Garrett Ceramic Components Division
19800 S. Van Ness Ave.
Torrance, CA 90509

Dear Mr. ^{Mike} Heiser:

This letter is the first in a series of progress reports on the testing of prototype silicon nitride engine components fabricated by Garrett under contract from Oak Ridge National Laboratory for application in high performance production-based American engines.

After taking delivery of twenty fuel pump push rod ends and 100 rollers for tappets in April, we have initiated a multi-phase testing program. Ten fuel pump push rods (FPPR) were fabricated and endurance testing began at Competition Cams in Memphis, Tenn. After initial screening on a spin fixture showed good performance, five FPPR's were sent to racing programs, including the Chevrolet Race Shop and several Winston Cup teams, for extensive field evaluations.

A number of the rollers have been selected for testing and been assembled in production Competition Cam roller lifter bodies. The four rollers that were machined to have various pin diameters are scheduled for the first series of tests to determine the tolerances appropriate for production. Also selected for the first series of tests were a pair of rollers with what we consider to be optimum tolerances. All of these rollers will be run on a typical steel core cam with an aggressive grind for sixteen hours.

Once the rollers have demonstrated their wear properties, they will be subjected to an overspeed or float test. In this severe segment of testing, the rollers will experience abusive conditions greater than those likely to be encountered in the field. The impact strength of the material will be explored by operating the test rig at speeds in excess of 10,000 rpm in ever increasing time increments. It is likely that some or all of the parts will fail sometime during this part of the testing. However, we must determine if the components will stand up to the rigors of competition, and some of this will include periods of abuse. The tests on the rollers will begin in July, probably concluding in early August.

Several weeks after the arrival of the initial components, you delivered three examples of the spring seat designed to be used with our ceramic valves. Each of the seats had small flaws from the fabrication process. However, we selected the best one (with a small

chip on the outside edge of the bottom surface away from the valve stem) and sent it to the Chevrolet Race Shop for testing on an optron spin fixture along with several of our silicon nitride intake valves. The seat was tested with our lightest valve and proved to provide a significant improvement at several key resonant rpm and much better valve motion control across the operating range. The normal operating range for the type of valve train tested is about 8,200 rpm. The valve and retainer combination gave excellent performance to 9,600 rpm, 300 rpm above the speed that the normal titanium valve and seat floated out of control even though it employed a spring that was 40% lighter in seat pressure and 30% lighter in open pressure.

When the test was continued above 9,600 rpm, the retainer broke. However, I consider this to be excellent performance for the first test of this component. I am enclosing the remains of the seat and the valve keepers for your analysis. When the seat broke, it broke the tip of the valve; there may be some pieces of this material in with that from the seat. Pending your analysis of the remains of the seat, we need to discuss possible modifications to the design. For your reference, I am enclosing the valve and two new valve springs as used in the test. One area we might want to investigate is the fit of the seat onto the springs. Be aware that the diameter of the springs vary with production tolerances, but the large majority of the springs used in racing applications share the dimensions of the samples enclosed. I am enclosing copies of the test data from the three optron tests that you may have interest in: the baseline titanium set up; the light valve and titanium seat with the light spring; and the light valve and spring with the ceramic seat.

An unanticipated side benefit of use of the ceramic seat was that it greatly facilitated the disassembly of the valve and keeper set up. With the use of a titanium seat, the high clamping force of the design has made disassembly very difficult. With the ceramic seat, however, the difficulty of this process was very noticeably reduced.

Another progress report will follow within six weeks. Contact me with any questions you have.

Sincerely,

Robert P. Larsen
President

enclosures

V-6 OPTRON
CERAMIC VALVE EXAMINATION
TEST INDEX

TEST#	DESCRIPTION OF SET-UP
#249	INTAKE - BASELINE TEST - 1X162560 CAMSHAFT, ISKY 1241 OFFSET LIFTER, DIAMOND 6.350"-.005" W.H.I. PUSHROD, ROCKWELL REV-KIT SPRING, 23 CYL. HEAD, FALCONER .200" LEFT OFFSET ROCKER ARM, TITANIUM VALVE & RETAINER, ASSOCIATED 1021 VALVE SPRING INST. @ 1.950", .012" LASH VALVE - 77.6 grams RETAINER/LOCKS 14.0g/7.2g. VALVE ASSEMBLY - 98.8 grams
#250	INTAKE - SET-UP SAME AS TEST #249, EXCEPT VALVE & VALVE SPRING. SWITCH TO HEAVY CERAMIC VALVE AND ASSOCIATED 1093 VALVE SPRING INST. @ 1.985". ALL ELSE REMAINS UNCHANGED. VALVE - 59.6 grams RETAINER/LOCKS 21.2 gr./4.0 gr. VALVE ASSEMBLY - 84.8 grams
#251	INTAKE - SET-UP SAME AS TEST #250, EXCEPT FOR VALVE SPRING AND SPRING INST. HGT. SWITCH TO ASSOCIATED 1021 INST. @ 1.940". ALL ELSE REMAINS UNCHANGED.
#252	INTAKE - SET-UP SAME AS TEST #249, EXCEPT VALVE AND VALVE SPRING. SWITCH TO LIGHT CERAMIC VALVE AND ASSOCIATED 1093 VALVE SPRING INST. @ 1.965". ALL ELSE REMAINS UNCHANGED. VALVE - 55.8 grams RETAINER/LOCKS 21.2 gr./4.0 gr. VALVE ASSEMBLY - 81.0 grams
#253	INTAKE - SET-UP SAME AS TEST #252, EXCEPT FOR VALVE SPRING AND SPRING INST. HGT. SWITCH TO ASSOCIATED 1021 INST. @ 1.940". ALL ELSE REMAINS UNCHANGED.
#254	INTAKE - SET-UP SAME AS TEST #252, EXCEPT VALVE SPRING RETAINER SWITCH TO ACE. CERAMIC RETAINER. ALL ELSE REMAINS UNCHANGED. VALVE - 55.8 grams RETAINER/LOCKS 15.3g/4.0 gr. VALVE ASSEMBLY - 75.1 grams

V-6 OPTRON
CERAMIC VALVE EXAMINATION

COMPONENT WEIGHTS

DEL WEST TITANIUM VALVE (INT.)	77.6 GRAMS
A.C.E. HEAVY CERAMIC VALVE (INT.)	59.6 GRAMS
A.C.E. LIGHT CERAMIC VALVE (INT.)	55.8 GRAMS
HOWARD STEWART TITANIUM RETAINER	14.0 GRAMS
10° LOCKS	7.2 GRAMS
A.C.E. TITANIUM RETAINER	21.2 GRAMS
7° LOCKS	4.0 GRAMS
A.C.E. CERAMIC RETAINER	15.3 GRAMS

V-6 OPTRON
CERAMIC VALVE EXAMINATION
BASELINE TEST

1X162560 CAMSHAFT, ISKY 1241 OFFSET LIFTER, DIAMOND 6.35" - .080" WALL
PUSHROD, ROCKWELL REV-KIT SPRINGS, 23° CYL. HEAD, FALCONER
.200" OFFSET ROCKER ARM, TITANIUM VALVE & RETAINER,
ASSOCIATED 1021 VALVE SPRING
LASHED @ .012" .644" VALVE LIFT

START: 172 Lbs. @ 1.950"
529 Lbs. @ 1.305"
C.B. @ 1.160"

<u>FILE #</u>	<u>RPM</u>	
RPMX58	2000	
•RPMX59	5500	- SLIGHT DEVIATION - NOISE & SEAT
•RPMX60	6000	- SMOOTHED OUT
•RPMX61	6200	- DEVIATES @ PEAK
•RPMX62	6400	
•RPMX63	6600	
•RPMX64	6800	- VERY SLIGHT BOUNCE ON SEAT
•RPMX65	7000	- SMOOTHED OUT
•RPMX66	7200	
•RPMX67	7400	
•RPMX68	7600	
•RPMX69	7800	- PEAK IS FLATTENING
•RPMX70	8000	- PEAK IS FLAT
•RPMX71	8200	- FLUCTUATES - SMALL BOUNCE NOT SHOWN
•RPMX72	8400	- " " - INCREASE IN BOUNCE (FLUTTER)
•RPMX73	8600	- SAME
•RPMX74	8800	- INCREASE IN NOISE
•RPMX75	9000	
•RPMX76	9200	- INCREASE IN NOISE & BOUNCE (SLIGHT INCREASE)
•RPMX77	9300	- SEVERE RUNNING FLOAT

END: 162 Lbs. @ 1.950"
519 Lbs. @ 1.305"

TEST # 253 - INTAKE

V-6 OPTRON
CERAMIC VALVE EXAMINATION

SET-UP SAME AS TEST #252, EXCEPT FOR VALVE SPRING &
 SPRING INST. HGT. SWITCH TO ASSOCIATED 1021
 INST. @ 1.940". ALL ELSE REMAINS UNCHANGED.
 LASHED @ .012" .644" VALVE LIFT

(USED) START: 165 Lbs. @ 1.940"
 514 Lbs. @ 1.295"
 C.B. @ 1.160"

END: 155 Lbs. @ 1.940"
 505 Lbs. @ 1.295"

FILE #	RPM
RPMx40	2000
• RPMx41	5500 - DEVIATES SLIGHTLY - NOISE & SEAT
• RPMx42	6000
• RPMx43	6200
• RPMx44	6400 - SMOOTHED OUT
• RPMx45	6600 - GOOD
• RPMx46	6800
• RPMx47	7000
• RPMx48	7200
• RPMx49	7400
• RPMx50	7600 - DEVIATES @ PEAK
• RPMx51	7800 - " "
• RPMx52	8000 - PEAK IS FLAT
• RPMx53	8200
• RPMx54	8400 INCREASE IN NOISE - DEVIATES @ PEAK & CLOSE
• RPMx55	8600 - SAME
• RPMx56	8800 - LOOKS GOOD
• RPMx57	9000 - SMALL BOUNCE
• RPMx58	9200 - INCREASED DEVIATION - PEAK & SEAT
• RPMx59	9400 - INCREASED DEVIATIONS & NOISE
• RPMx60	9600 - SAME

TEST #254 - INTAKE

V-6 OPTRON
CERAMIC VALVE EXAMINATION

SETUP SAME AS TEST #252, EXCEPT FOR VALVE SPRING RETAINER
SWITCH TO A.C.E. CERAMIC RETAINER (15.3gr. vs. 21.2 gr. for TITANIUM)
ALL ELSE REMAINS UNCHANGED.
LASHED @ .012" .644" VALVE LIFT

(USED) START: 102 Lbs. @ 1.965"
380 Lbs. @ 1.320"
C.B. @ 1.110"

END: 100 Lbs. @ 1.965"
380 Lbs. @ 1.320"

FILE #	RPM
RPMx61	2000
•RPMx62	5500 - 6000
•RPMx63	6000
•RPMx64	6200
•RPMx65	6400
•RPMx66	6600
•RPMx67	6800
•RPMx68	7000
•RPMx69	7200
•RPMx70	7400
•RPMx71	7600
•RPMx72	7800
•RPMx73	8000
•RPMx74	8200 - DEVIATES OVER NOSE
•RPMx75	8400 - INCREASED DEVIATION & NOISE
•RPMx76	8600
•RPMx77	8800 - SMOOTHING OUT
•RPMx78	9000 - "
•RPMx79	9200 - SLIGHT DEVIATION of SEAT
•RPMx80	9400 - SLIGHT INCREASE in NOISE - CURVE IS CLEAN
RPMx81	

9600 RPM WAS NEXT SPEED TO BE RECORDED.
AT 9400 RPM ON APPROACH TO 9600, THE
CERAMIC RETAINER DISINTEGRATED, ENDING TEST.

STATUS OF ENGINE COMPONENT EVALUATION
GARRETT CERAMIC COMPONENT DIVISION'S GS-44 MATERIAL
American Ceramic Engine Company
January 20, 1991

I. Fuel Pump Push Rod Ends

20 GS--44 silicon nitride ends were received from GCC and assembled into ten fuel pump push rods (FPPRs). Extensive spin fixture tests were performed on several on these components before they were tested in engines. The longest test, in excess of 500 hours, was performed at Competition Cams in Memphis, Tenn., and was a complete success. Additional spin fixture examinations were performed at KaTech, a prime contractor to the Chevrolet Race Shop, in Mt. Clemens, Mich., and by the Hendricks Motor Sports racing team in Harrisburg, No. Carolina. The spin fixture tests are continuing at KaTech, however this component has successfully been used on the dynamometer in Winston Cup engines both by Hendricks and by Ben Barnes, an Winston Cup engine builder in Atlanta, Ga. Mr. Barnes had been experiencing severe fuel pump cam lobe wear on his engines, used by top-ranked independent Winston Cup driver Dave Marcis. Mr. Marcis successfully used the FPPR in part of the 1990 Winston Cup season (in about seven races). This FPPR has been in five different race engines and has delivered superior performance. Mr. Barnes stated it was the best new component he ever had and plans to continue to use it throughout the 1991 season. Based on this experience, it is believed that this component is market-ready if price, quality, and availability arrangements can be made with GCC.

Other FPPRs were sent to Crane Cams and Reed Cams for evaluation and possible marketing arrangements. Crane Cams continues to evaluate this product, and has indicated an interest in marketing it if technical and cost benchmarks can be reached. Reed Cams has agreed to put the ACE FPPR in their 1991 catalogue; Competition Cams agrees that the component is ready to go into production, but difficulties in reaching a business agreement have nearly eliminated this avenue of commercialization.

ACE's own spin testing of the FPPR showed good initial results, with five FPPRs being tested at high speed (a constant 8,000 rpm) for eight to sixteen hours each. However, the sixth FPPR tested resulted in a broken tip that was in contact with the cam after about 2 hours and 30 minutes of testing. This component is being returned to GCC for evaluation, pending the results of this analysis, a decision regarding the next step in bringing this component to the market will be made.

II. Valve Spring Seals

GCC delivered three early spring seats that were tested on the KaTech Optron spin fixture along with an ACE ceramic valve. The combination of the lighter spring seat and valve produced a substantial improvement in valve control using a spring that had one-third less closed seat pressure. This combination gave 500 rpm greater float protection than the standard titanium valve and spring seat. However, as reported earlier, the spring seat broke at a speed in excess of 9,000 rpm before float set in. It was determined in subsequent analysis of the spring seat by GCC that the failure was due to excessive point loading of the component by the valve keepers. The ACE valve keepers are precision CNC machined components using a hard (Rockwell C of >40) steel. Apparently, only a narrow contact area near the base of the spring seat was achieved, leading to the failure.

Subsequently, a new batch of spring retainers were received from GCC for testing. These spring seats had noticeably better machining and attention paid to having smooth radii in all corners. Several of these seats were sent out for further evaluation to KaTech, Crane Cams, and Reed Cams. Crane Cams appears to be the most interested party at this point, with a series of tests on the seat planned for the end of January. First, they will perform a "pull test," where the spring seat is assembled with valve keepers on a fixture and a progressively higher pulling force is applied until the part breaks. With years of experience in the design and testing of spring seats, Crane thinks this is the best way to evaluate the likelihood of success of this component. Special softer steel keepers are being fabricated by Crane to insure contact along a large portion of the inner hole of the seat. The results of this test should be available by early February. If the results are encouraging, extensive spin fixture endurance testing will follow. Finally, engine testing at a Winston Cup team will be performed if the results warrant it.

ACE is performing its own spin fixture evaluation of the spring seat using Winston Cup valve springs and a titanium valve (the most likely combination of its first use). These tests are scheduled for the last week in January and will be run at a continuous 6,000 rpm and 8,000 rpm. If the results are encouraging, higher speeds will be attempted. Since we are not concerned with the fatigue of silicon nitride, these tests are aimed at proof-testing the strength of the material, the ACE design, and the interface of the ceramic material with the top of the valve spring. Efforts will also be made to encourage the testing of the spring seat by KaTech and Reed Cams.

III. Tappet Rollers

A substantial number of tappet rollers were received from GCC for testing, including a number of specially machined rollers designed to investigate the appropriate axle-to-roller tolerances. Some of these rollers were outside the dimensions specified by ACE and some had machining flaws, the great majority of which were recognized by GCC, thus accounting for the large number of components. Carefully selected pairs of rollers were sent out for testing to a number of cam companies and interested racing programs. Although no results have yet been received, Crane Cams is initiating a program of spin fixture endurance testing and strength evaluation this month. Typically, the strength evaluation simulates an over-rev condition of float in the valve train. It is produced on the test stand by opening the valve lash such that the roller experiences a severe pounding by the cam. Although typically more severe than actually seen in service, this test is the benchmark qualification for racing and production applications. This type of test is the one that has been most difficult for ceramic rollers to pass; it requires substantial initial strength and a sufficiently high Weibull modulus such that strength-reducing flaws do not occur frequently enough to cause immediate failure.

Crane is very interested in this component for high volume application. The problem they most often see is rapid wear of the axle, followed by failure of the needle bearings between the axle and metal roller. These bearings require a constant stream of high pressure, clean oil for proper lubrication to avoid high rates of wear and eventual failure. Use of ceramic material in this application holds great promise for improved reliability and lower engine and warranty costs. This same objective is recognized by the vehicle OEM's, indications are that success in testing with Crane can interest several major OEM suppliers in the application of ceramic material for wear reduction.

ACE has begun testing of GCC ceramic tappet rollers on its spin fixture. Initial results indicate that axle wear is very low, but some unusual wear near the tip of the cam lobe is occurring. Since the cam profile selected for this test is a very high ramp design more typical of drag racing, it is not yet known whether this wear will stabilize or continue to get worse. One of the open issues these tests are trying to answer is what is the proper surface finish for the cam rollers to ensure low wear on the cam lobe. There is some speculation that even the direction of machining of the lobe can impact the rate of cam lobe wear. We will continue to investigate this factor and others, since this component appears to hold the best promise for widespread, high volume application in engines, both in high performance and OEM applications.

IV. Acknowledgment

ACE would like to thank the Garrett Ceramic Components Division for their cooperation and willingness to develop and test these engine components. It has been a pleasure to work with GCC personnel at all levels. ACE reaffirms its intention to move as many of these components into production as is economically and technically feasible in the near future. Although initial production levels may be small compared to the volume required to serve the OEM marketplace, we believe the experience, both in production techniques and from having engines on the race track using ceramic components, will be very beneficial to GCC.

ACE would also like to thank the U.S. Department of Energy and Oak Ridge National Laboratory for their support of GCC's effort to develop production ceramic engine components.

AMERICAN CERAMIC ENGINE COMPANY
Prototype Component Testing Summary
June 20, 1991

Component: Garrett Ceramic Components Division (GCCD) Cam Roller

Experimental Setup: Four rollers were assembled into two standard Crane lifter bodies. These bodies feature hardened steel wheel shafts and direct oiling of the roller assembly by a small hole drilled from the oil galley bypass to the shaft/roller area. Rollers were selected to give a 0.002" to 0.003" pin to roller ID clearance.

Two separate tests were run on two spin fixtures using one of the assembled lifters: one at Crane Cams and one on the ACE test rig. Both tests used typical oval track (stock car racing) roller cam profiles on a steel cam core. A valve train typical of those used for this application was used: titanium valves and spring retainers, roller 1.5:1 rocker arms, and dual valve springs with a damper. Valve spring rates were about 170 lbs. closed and about 530 lbs. open. This setup was deemed a representative test for these parts.

Results of Tests: The Crane test lasted for a little less than six hours at speed between 3,500 rpm and 7,500 rpm. The rollers had no apparent wear, but the cam showed definite tracks worn into the face of the lobes the width of the rollers. Tracks had also begun to appear on the base circle of the cam. Upon disassembly, the pin that the rollers rode on showed no wear and the lifter was in excellent shape.

The ACE test was run at a constant 7,000 rpm for three hours. The rig was shut down and the cam and lifter inspected every hour. At the three hour mark, significant wear was detected on the acceleration ramp of the cam between its beginning and the nose of the cam. The wear was characterized by two grooves in the lobe the width of the roller with some lesser scuffing between the two grooves. The wear marks seemed to be located at the peak area of lift acceleration and mechanical stress of the cam. The test was discontinued at this point as the results showed higher-than-acceptable levels of cam wear. However, there was no apparent wear on the roller; the pin and lifter also showed no wear.

Discussion of Test Results: Both tests resulted in premature cam wear from the hardness of the silicon nitride material. Even with the radiused edges of the ACE design, it is apparent that the roller profiles need to be crowned. ACE had attempted to avoid the extra cost and complexity of crowning, but all available test results, including these, indicate it is a necessity. The good news is that the area of greatest concern, the wear on the lifter pin, was shown to be very low. Currently, pin wear is excessive due to heat and

frictional wear generated by the needles in the bearing used with conventional metal rollers. These results are sufficiently encouraging to Crane Cams that they are interested in continuing to test and develop this component for possible production.

Recommendation: Further testing using existing GCCD rollers with crowns machined on them should be conducted. Other tests using crowned silicon nitride rollers have shown very low cam wear and excellent lifter life. The most recent data from Detroit Diesel has demonstrated that under certain condition, ceramic rollers do not even rotate; their superior wear and friction properties yield impressively low wear rates either in roller or sliding situations. Rollers of this type are definitely headed toward large-scale OEM production. Since Crane is the largest aftermarket supplier of valve train parts, using suppliers such as Eaton and Rockwell, commercializing ceramic rollers for high performance aftermarket applications appears to be an attractive way to build sufficient production volume and experience in order to tap the OEM market.

AMERICAN CERAMIC ENGINE COMPANY
Prototype Component Testing Summary
June 25, 1991

Component: Garrett Ceramic Components Division (GCCD) Fuel Pump Push Rod End-Tips

Experimental Setup: Fuel pump push rod ends have a wear problem at the cam end as well as the fuel pump end. In order to reduce the wear rate end tips made from silicon nitride were proposed. Eighteen prototype silicon nitride end-tips were received from GCCD. These were assembled into nine FPPRs for testing. Two were tested in the ACE test rig. The rest were sent to other component suppliers to the racing industry for tests. At least one, perhaps two, has been run in a real engine. ACE test rig consists of a small block Chevrolet engine cam and valve train operated by an electric motor. The FPPR and other valve train components can be tested at an engine speed of up to 10,000 rpm. Most of the race car engines operate at about 7,000 rpm. Competition Cams and Crane Cams are the two companies who tested the FPPR in their test rigs as well as engines.

Results of Tests: The first FPPR was tested in the ACE rig for 8 hours at a steady, 7,000 rpm, engine speed. The test was completed without any incident. Examination of the FPPR and the cam showed no visible wear or any other damage. This test is considered to be a success. Race car cam manufacturers use this as a screening test before installing the component into an engine. The second FPPR sample was damaged after 3 hours of test. The ceramic end on the cam side broke on the edge and the sides. This damaged part is being sent back to GCCD separately for failure analysis. ACE did not have much control over the other FPPR pieces tested by race car customers. However the feedback that we received was that the FPPR performed well in rig tests and in engine tests.

Conclusion: The FPPR as tested with these samples is ready for production. The cause of the one failure should be determined and corrective action should be taken. If the failure analysis shows any design related defect, new samples should be tested.

AMERICAN CERAMIC ENGINE COMPANY
Prototype Component Testing Summary
June 27, 1991

Component: Garrett Ceramic Components Division (GCCD) Valve Spring Retainer

Experimental Setup: Using silicon nitride material instead of steel for the valve spring retainer material reduces the mass of the reciprocating valve assembly. This is very critical in high performance engines which operate at 7,000 - 8,000 rpm speeds compared to passenger car engines which normally operate at 4,000 rpm or less. GCCD produced a few prototype silicon nitride spring retainers for test by ACE. Two of these retainers were installed in the ACE high speed spin test rig. One was tested with VASCOJET spring which had an inner diameter of 0.645 in. and 1.9000 in. installed spring height. The tension of this single spring assembly was 170 lb. The second ceramic retainer was installed with a double spring assembly with the same installed height. The spring tension in this case was 260 lb. The wire diameter in both cases was 0.125 in. The tests were run at 7,000 rpm engine speed.

Results of Tests: The first retainer assembly was tested in the ACE rig for 3 hours at a steady, 7,000 rpm, engine speed. The test was completed without any incident. Examination of the ceramic part and the spring showed no visible wear or any other damage. At this point, the second double spring assembly was also installed in the test fixture and a test run of both ceramic pieces together was started. However, the ceramic part in the double spring assembly failed and broke into several pieces in less than one minute of test run at 7,000 rpm. This totally destroyed the cam and the rig became inoperable. The first ceramic retainer was not damaged. Race cars generally use the double spring assembly with higher spring tension. Therefore, this part, as it is currently produced, is not strong enough in racing applications. This damaged part is being sent back to GCCD separately for failure analysis. Based on the failure analysis, GCCD should redesign and produce new prototypes for rig tests.

INTERNAL DISTRIBUTION

1-2.	Central Research Library	42.	M. G. Jenkins
3.	Document Reference Section	43.	D. R. Johnson
4-5.	Laboratory Records Department	44.	W. F. Jones
6.	Laboratory Records, ORNL RC	45.	D. Joslin
7.	ORNL Patent Section	46.	R. R. Judkins
8-10.	M&C Records Office	47.	M. A. Karnitz
11.	L. F. Allard, Jr.	48.	M. R. Kass
12.	L. D. Armstrong	49-53.	B. L. P. Keyes
13.	P. F. Becher	54.	H. D. Kimrey, Jr.
14.	R. F. Bernal	55.	T. G. Kollie
15.	T. M. Besmann	56.	K. C. Liu
16.	P. J. Blau	57.	E. L. Long, Jr.
17.	A. Bleier	58.	W. D. Manly
18.	E. E. Bloom	59.	R. W. McClung
19.	K. W. Boling	60.	D. J. McGuire
20.	R. A. Bradley	61.	J. R. Merriman
21.	C. R. Brinkman	62.	D. L. Moses
22.	V. R. Bullington	63.	T. A. Nolan
23.	R. S. Carlsmith	64.	A. E. Pasto
24.	P. T. Carlson	65.	J. L. Rich
25.	G. M. Caton	66.	C. R. Richmond
26.	S. J. Chang	67.	J. M. Robbins
27.	R. H. Cooper, Jr.	68.	M. L. Santella
28.	B. L. Cox	69.	A. C. Schaffhauser
29.	D. F. Craig	70.	S. Scott
30.	S. A. David	71.	G. M. Slaughter
31.	J. H. DeVan	72.	E. J. Soderstrom
32.	J. L. Ding	73.	D. P. Stinton
33.	M. K. Ferber	74.	R. W. Swindeman
34.	F. M. Foust	75.	V. J. Tennery
35.	W. Fulkerson	76.	T. N. Tiegs
36.	R. L. Graves	77.	J. R. Weir, Jr.
37.	D. L. Greene	78.	B. H. West
38.	M. H. Harris	79.	F. W. Wiffen
39.	E. E. Hoffman	80.	S. G. Winslow
40.	C. R. Hubbard	81.	J. M. Wyrick
41.	M. A. Janney	82.	C. S. Yust

EXTERNAL DISTRIBUTION

83. James H. Adair
University of Florida
Materials Science and
Engineering
317 MAE Bldg.
Gainesville, FL 32611-2066
84. Donald F. Adams
University of Wyoming
Mechanical Engineering
Department
P. O. Box 3295
Laramie, WY 82071
85. Jalees Ahmad
AdTech Systems Research, Inc.
1342 North Fairfield Road
Dayton, OH 45432-2698
86. Yoshio Akimune
NISSAN Motor Co., Ltd.
Materials Research Laboratory
1 Natsushima-Cho
Yokosuka 237
JAPAN AIR MAIL
87. Mufit Akinc
Iowa State University
322 Spedding Hall
Ames, IA 50011
88. Ilhan A. Aksay
University of Washington
Materials Science and Engineering
Department, FB-10
Seattle, WA 98195
89. R. G. Alexander
BASE
26 Malvern Close
Kettering Northants NN16 8JP
UNITED KINGDOM AIR MAIL
90. Richard L. Allor
Ford Motor Company
Material Systems
Reliability Department
20000 Rotunda Drive
P.O. Box 2053, Room S-2031
Dearborn, MI 48121-2053
91. Richard T. Alpaugh
U.S. Department of Energy
Advanced Propulsion Division
CE-322, Forrestal Building
Washington, DC 20585
92. Joseph E. Amaral
Instron Corporation
Corporate Engineering Office
100 Royale Street
Canton, MA 02021
93. Edward M. Anderson
Aluminum Company of America
North American Industrial
Chemicals Division
P.O. Box 300
Bauxite, AR 72011
94. Norman C. Anderson
Ceradyne, Inc.
Ceramic-to-Metal Division
3169 Redhill Avenue
Costa Mesa, CA 92626
95. Don Anson
Battelle Columbus Laboratories
Thermal Power Systems
505 King Avenue
Columbus, OH 43201-2693
96. Thomas Arbanas
G.B.C. Materials Corporation
580 Monastery Drive
Latrobe, PA 15650-2698
97. Frank Armatis
3M Company
3M Center
Building 60-1N-01
St. Paul, MN 55144-1000
98. Everett B. Arnold
Detroit Diesel Corporation
Mechanical Systems Technology
13400 Outer Drive, West
Detroit, MI 48239-4001
99. Richard M. Arons
PA Consulting Group
279 Princeton Road
Hightstown, NJ 08550

100. Bertil Aronsson
Sandvik AB
S-12680
Stockholm Lerkrogsvagen 19
SWEDEN AIR MAIL
101. Dennis Assanis
University of Illinois
Department of Mechanical
Engineering
1206 W. Green Street
Urbana, IL 61801
102. William H. Atwell
Dow Corning Corporation
3901 South Saginaw Road
MS:540
Midland, MI 48686-0995
103. V. S. Avva
North Carolina A&T State
University
Department of Mechanical
Engineering
Greensboro, NC 27411
104. Patrick Badgley
Adiabatics, Inc.
3385 Commerce Drive
Columbus, IN 47201
105. Sunggi Baik
Pohang Institute of Science
& Technology
Department of Materials
Science and Engineering
P.O. Box 125
Pohang 790-600
KOREA AIR MAIL
106. John A. Bailey
Caterpillar, Inc.
Technical Center
Building L
P.O. Box 1875
Peoria, IL 61656-1875
107. Bob Eaker
Ceracyne, Inc.
3169 Redhill Avenue
Costa Mesa, CA 92626
108. Frank Baker
Aluminum Company of America
Alcoa Technical Center
Alcoa Center, PA 15069
109. J. G. Baldoni
GTE Laboratories Inc.
40 Sylvan Road
Waltham, MA 02254
110. Clifford P. Ballard
Allied-Signal, Inc.
Ceramics Program
P.O. Box 1021
Morristown, NJ 07962-1021
111. M. Balu
Amoco Performance Products Inc.
4500 McGinnis Ferry Road
Alpharetta, GA 30202
112. B. P. Bandyopadhyay
Toyohashi University of Technology
School of Production Systems
Engineering
Tempaku-Cho Toyohashi 440
JAPAN AIR MAIL
113. P. M. Barnard
Ruston Gas Turbines Limited
Metallurgical Laboratory
P. O. Box 1
Lincoln LN2 5DJ
ENGLAND AIR MAIL
114. Harold N. Barr
Hittman Corporation
9190 Red Branch Road
Columbia, MD 21045
115. Renald D. Bartoe
Vesuvius McDanel
510 Ninth Avenue
Box 560
Beaver Falls, PA 15010-0560
116. Donald M. Bartos
Dow Corning Corporation
Advanced Ceramics Program
Midland, MI 48686-0995

117. David L. Baty
Babcock & Wilcox-LRC
P.O. Box 11165
Lynchburg, VA 24506-1165
118. Donald F. Baxter, Jr.
ASM International
Advanced Materials and
Processes
Materials Park, OH 44073-0002
119. M. Brad Beardsley
Caterpillar, Inc.
Advanced Materials Technology
Technical Center Bldg. E
P.O. Box 1875
Peoria, IL 61656-1875
120. Robert Beck
Teledyne CAE
Materials Engineering/Programs
1330 Laskey Road
P.O. Box 6971
Toledo, OH 43612
121. John C. Bell
Shell Research Limited
Thornton Research Centre
P.O. Box 1
Chester, Ch1 3SH
ENGLAND AIR MAIL
122. Albert H. Bell, III
General Motors Technical Center
30200 Mound Road
Engineering Building/W3 Turbine
Warren, MI 48090-9010
123. M. Bentele
Xamag, Inc.
259 Melville Avenue
Fairfield, CT 06430
124. Larry D. Bentsen
BF Goodrich Company
R&D Center
9921 Brecksville Road
Brecksville, OH 44141
125. Joseph C. Bentz
ENCERATEC
2525 Sandcrest Drive
Columbus, IN 47203
126. Louis Beregszazi
Defiance Precision Products
P.O. Drawer 428
Defiance, OH 43512
127. Tom Bernecki
Northwestern University
BIRL
1801 Maple Avenue
Evanston, IL 60201-3135
128. Charles F. Bersch
Institute for Defense Analyses
1801 North Beauregard Street
Alexandria, VA 22311
129. Ram Bhatt
NASA Lewis Research Center
21000 Brookpark Road
Cleveland, OH 44135
130. Deane I. Biehler
Caterpillar, Inc.
Engineering and Research
Materials
Technical Center, Building E
P.O. Box 1875
Peoria, IL 61656-1875
131. John. W. Bjerklie
Consolidated Natural Gas
Service Co., Inc.
Research Department
CNG Tower
Pittsburgh, PA 15222-3199
132. William D. Bjorndahl
TRW, Inc.
One Space Park
Building 01, Room 2040
Redondo Beach, CA 90278
133. Keith A. Blakely
Advanced Refractory
Technologies, Inc.
699 Hertel Avenue
Buffalo, NY 14207
134. Edward G. Blanchard
Netzsch Inc.
119 Pickering Way
Exton, PA 19341

135. Keith Blandford
Boride Products, Inc.
2879 Aero Park Drive
Traverse City, MI 49684
136. Bruce Boardman
Deere and Company Technical
Center
3300 River Drive
Moline, IL 61265
137. Russell Bockstedt
Hoechst Celanese Corporation
150 JFK Parkway
Short Hills, NJ 07078
138. M. Boehmer
DLR German Aerospace Research
Establishment
Postfach 90 60 58
D-5000 Koln 90
GERMANY AIR MAIL
139. Lawrence P. Boesch
EER Systems Corp.
1593 Spring Hill Road
Vienna, VA 22182-2239
140. Donald H. Boone
Boone & Associates
2412 Cascade Drive
Walnut Creek, CA 94598-4313
141. Tom Booth
Allied-Signal Aerospace
Company
AiResearch Los Angeles
Division
2525 West 190th Street
Torrance, CA 90509-2960
142. Tibor Bornemisza
Sundstrand Power Systems
4400 Ruffin Road
San Diego, CA 92186-5757
143. J.A.M. Boulet
University of Tennessee
Department of Engineering
Science and Mechanics
310 Perkins Hall
Knoxville, TN 37996-2030
144. H. Kent Bowen
Massachusetts Institute of
Technology
77 Massachusetts Avenue
Room E40-434
Cambridge, MA 02139
145. Leslie J. Bowen
Materials Systems
53 Hillcrest Road
Concord, MA 01742
146. Steven C. Boyce
Air Force Office of
Scientific Research
AFOSR/NA Bldg. 410
Bolling AFB DC 20332-6448
147. Gary L. Boyd
CEC
400 Howell Avenue, No. 4
Warland, WY 82401
148. Steve Bradley
UOP Research Center
50 East Algonquin Road
Des Plaines, IL 60017-6187
149. Michael C. Brands
Cummins Engine Company, Inc.
P.O. Box 3005
Mail Code 50179
Columbus, IN 47201
150. Raymond J. Bratton
Westinghouse Science and
Technology Center
1310 Beulah Road
Pittsburgh, PA 15235
151. John J. Brennan
United Technologies Corporation
Research Center
Silver Lane, MS:24
East Hartford, CT 06108
152. Jeff D. Bright
Ceramatec, Inc.
2425 South 900 West
Salt Lake City, UT 84108

153. Terrence K. Brog
Coors Ceramics Company
Corporate Development and
Technology
4545 McIntyre Street
Golden, CO 80403
154. Gunnar Broman
317 Fairlane Drive
Spartanburg, SC 29302
155. Al Brown
High-Tech Materials Alert
P.O. Box 882
Dayton, NJ 08810
156. Jesse Brown
Virginia Polytechnic Institute
and State University
Center for Advanced Ceramic
Materials
Blacksburg, VA 24061-0256
157. Sherman D. Brown
University of Illinois
Materials Science and
Engineering Department
105 South Goodwin Avenue
204 Ceramics Building
Urbana, IL 61801
158. S. L. Bruner
Ceramatec, Inc.
2425 South 900 West
Salt Lake City, UT 84119
159. Adolfo Brusaferro
Keramont Corporation
4231 South Fremont Avenue
Tucson, AZ 85714
160. W. Bryzik
U.S. Army Tank Automotive
Command
R&D Center
Propulsion Systems Division
Warren, MI 48397-5000
161. S. T. Buljan
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
162. S. J. Burden
GTE Valenite
1711 Thunderbird
Troy, MI 48084
163. Curt V. Burkland
AMERCOM, Inc.
8928 Fullbright Avenue
Chatsworth, CA 91311
164. Bill Bustamante
AMERCOM, Inc.
8928 Fullbright Street
Chatsworth, CA 91311
165. Oral Buyukozturk
Massachusetts Institute of
Technology
77 Massachusetts Avenue
Room 1-280
Cambridge, MA 02139
166. David A. Caillet
Ethyl Corporation
451 Florida Street
Baton Rouge, LA 70801
167. Frederick J. Calnan
Heany Industries, Inc.
249 Briarwood Lane
P.O. Box 38
Scottsville, NY 14546
168. Roger Cannon
Rutgers University
Ceramics Department
P.O. Box 909
Piscataway, NJ 08855-0909
169. Scott Cannon
P.O. Box 567254
Atlanta, GA 30356
170. Harry W. Carpenter
19945 Acre Street
Northridge, CA 91324
171. David Carruthers
Kyocera Industrial Ceramics
Company
P.O. Box 2279
Vancouver, WA 98668-2279

172. Calvin H. Carter, Jr.
Cree Research, Inc.
2810 Meridian Parkway
Durham, NC 27713
173. J. David Casey
35 Atlantis Street
West Roxbury, MA 02132
174. Jere G. Castor
J. C. Interprise
5078 North 83rd Street
Scottsdale, AZ 85250
175. James D. Cawley
Case Western Reserve University
Materials Science and
Engineering Department
Cleveland, OH 44106
176. Thomas C. Chadwick
Den-Mat Corporation
P.O. Box 729
Santa Maria, CA 93456
177. Ronald H. Chand
Chand Kare Technical Ceramics
2 Coppage Drive
Worcester, MA 01603
178. Robert E. Chaney
EG&G Idaho, Inc.
Idaho National Engineering
Laboratory
P.O. Box 1625
Idaho Falls, ID 83415-3525
179. Frank C. Chang
U.S. Army Materials
Technology Laboratory
AMTL-EMM
405 Arsenal Street
Watertown, MA 02172
180. Robert M. Chapman
Alliec-Signal Aerospace
Company
1530 Wilson Boulevard,
10th Floor
Arlington, VA 22209
181. William Chapman
Williams International
Corporation
2280 West Maple Road
Walled Lake, MI 48390-0200
182. Charlie Chen
LECO Corporation
P.O. Box 211688
Augusta, GA 30917
183. Albert A. Chesnes
U.S. Department of Energy
Transportation Technologies
CE-30, Forrestal Building,
6B-094
Washington, DC 20585
184. Kaiyin Chia
Carborundum Company
P.O. Box 832
Niagara Falls, NY 14302
185. Frank Childs
EG&G Idaho, Inc.
Idaho National Engineering
Laboratory
P.O. Box 1625
Idaho Falls, ID 83415-3527
186. William J. Chmura
Torrington Company
59 Field Street
Torrington, CT 06790-4942
187. Tsu-Wei Chou
University of Delaware
Center for Composite
Materials
201 Spencer Laboratory
Newark, DE 19716
188. R. J. Christopher
Ricardo Consulting Engineers
Bridge Works
Shoreham-By-Sea West Sussex
BN43 5FG
ENGLAND AIR MAIL
189. Joel P. Clark
Massachusetts Institute of
Technology
Room 8-409
Cambridge, MA 02139

190. Giorgio Clarotti
Commission of the European
Communities
DGXII-C3, M075, 1-53;
200 Rue de la Loi
B-1049 Brussels
BELGIUM AIR MAIL
191. W. J. Clegg
ICI Advanced Materials
P.O. Box 11
The Heath, Runcorn Cheshire
WA7 4QE
ENGLAND AIR MAIL
192. Joseph Cleveland
GTE Products Corporation
Hawes Street
Towanda, PA 18848-0504
193. Gloria M. Collins
ASTM
1916 Race Street
Philadelphia, PA 19103
194. William C. Connors
Sundstrand Aviation Operations
Materials Science and
Engineering Department
4747 Harrison Avenue
P.O. Box 7002
Rockford, IL 61125-7002
195. John A. Coppola
Carborundum Company
P.O. Box 156
Niagara Falls, NY 14302
196. Normand D. Corbin
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
197. Douglas Corey
Allied-Signal Aerospace
Company
2525 West 190th Street
MS:T52
Torrance, CA 90504-6099
198. Keith P. Costello
Chand/Kare Technical Ceramics
2 Coppage Drive
Worcester, MA 01603-1252
199. Ed L. Courtright
Pacific Northwest
Laboratory
MS:K3-59
Richland, WA 99352
200. Anna Cox
Mitchell Market Reports
P.O. Box 23
Monmouth Gwent NP5 4YG
UNITED KINGDOM AIR MAIL
201. Thomas Coyle
Unocal Corporation
Unocal Science & Technology
Division
376 South Valencia Avenue
Brea, CA 92621
202. Art Cozens
Instron Corporation
3414 Snowden Avenue
Long Beach, CA 90808
203. Robert C. Craft
American Ceramic
Society, Inc.
757 Brooksedge Plaza Drive
Westerville, OH 43081
204. Mark Crawford
New Technology Week
4604 Monterey Drive
Annandale, VA 22003
205. Richard A. Cree
Markets & Products, Inc.
P.O. Box 14328
Columbus, OH 43214-0328
206. Les Crittenden
Vesuvius McDanel
Box 560
Beaver Falls, PA 15010

207. William J. Croft
U.S. Army Materials
Technology Laboratory
405 Arsenal Street
Watertown, MA 02172
208. M. J. Cronin
Mechanical Technology, Inc.
968 Albany-Shaker Road
Latham, NY 12110
209. Gary M. Crosbie
Ford Motor Company
1430 Culver Avenue
S-2079, SRL Building
Dearborn, MI 48121-4036
210. Floyd W. Crouse, Jr.
U.S. Department of Energy
Morgantown Energy
Technology Center
Collins Ferry Road
P.O. Box 880
Morgantown, WV 26505
211. John Cuccio
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
P.O. Box 5227, MS:1302-2Q
Phoenix, AZ 85010
212. Raymond Cutler
Ceramatec, Inc.
2425 South 900 West
Salt Lake City, UT 84119
213. Charles D'Angelo
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02154
214. Stephen C. Danforth
Rutgers University
Ceramic Engineering Department
P.O. Box 909
Piscataway, NJ 08855-0909
215. Sankar Das Gupta
Electrofuel Manufacturing
Co., Ltd.
9 Hanna Avenue
Toronto Ontario MGK-1W8
CANADA AIR MAIL
216. Charles Davis
Sverdrup Technology,
Inc., MSFC
620 Discovery Drive
Huntsville, AL 35806
217. Frank Davis
Allied Signal Aerospace Co.
7550 Lucerne Dr., # 203
Middleburg Heights, OH 44130
218. Robert F. Davis
North Carolina State
University
Materials Engineering
Department
229 Riddick Laboratory
P.O. Box 7907
Raleigh, NC 27695
219. Thomas DeAngelis
Carborundum Company
Niagara Falls R&D Center
P.O. Box 832
Niagara Falls, NY 14302
220. George DeBell
Ford Motor Company
Material Systems Reliability
Department
20000 Rotunda Drive
P.O. Box 2053, Room S-2023
Dearborn, MI 48121-2053
221. Michael DeLuca
AMP-AKZO
West Lane
Aquebogue, NY 11931
222. Gerald L. DePoorter
Colorado School of Mines
Metallurgical and Materials
Engineering Department
Golden, CO 80401

223. J. F. DeRidder
Omni Electro Motive, Inc.,
12 Seely Hill Road
Newfield, NY 14867
224. Nick C. Dellow
Materials Technology
Publications
40 Sotheron Road
Watford Herts WD1 2QA
UNITED KINGDOM AIR MAIL
225. L. R. Dharani
University of Missouri-Rolla
224 M.E.
Rolla, MO 65401
226. Douglas A. Dickerson
Union Carbide Specialty
Powders
1555 Main Street
Indianapolis, IN 46224
227. John Dodsworth
Vesuvius Research &
Development
Technical Ceramics Group
Box 560
Beaver Falls, PA 15010
228. B. Dogan
Institut fur Werkstofforschung
GKSS-Forschungszentrum
Geesthacht GmbH
Max-Planck-Strasse
D-2054 Geesthacht
GERMANY AIR MAIL
229. Jean-Marie Drapier
FN Moteurs S.A.
Material and Processing
B-4041 Milmort (Herstal)
BELGIUM AIR MAIL
230. Kenneth C. Dreitlein
United Technologies
Research Center
Silver Lane
East Hartford, CT 06108
231. Robin A.L. Drew
McGill University
Department of Mining and
Metallurgical Engineering
3450 University Street
Montreal Quebec H3A 2A7
CANADA AIR MAIL
232. Winston H. Duckworth
BCL
Columbus Division
505 King Avenue
Columbus, OH 43201-2693
233. Edmund M. Dunn
Texel Company
6 Third Street
Lexington, MA 02173
234. Bill Durako
Sundstrand Aviation Operations
Department 789-6
4747 Harrison Avenue
P.O. Box 7002
Rockford, IL 61125-7002
235. Ernest J. Duwell
212 Elm Street
Hudson, WI 54016
236. Chuck J. Dziedzic
Coors Ceramics Company
Structural Products Group
17750 West 32nd Avenue
Golden, CO 80401
237. Robert J. Eagan
Sandia National Laboratories
Engineered Materials &
Processes Center
Org 1700
P.O. Box 5800
Albuquerque, NM 87185-5800
238. Jeffrey Eagleson
Lanxide Corporation
1001 Connecticut Avenue, N.W.
Washington, DC 20036

239. Harry E. Eaton
Unitec Technologies Corporation
Research Center
Silver Lane
East Hartford, CT 06108
240. Harvill C. Eaton
Louisiana State
University
Office of Research
and Economic Development
240 Thomas Boyd Hall
Baton Rouge, LA 70803
241. Christopher A. Ebel
Carborundum Company
Technology Division
P.O. Box 337
Niagara Falls, NY 14302
242. J. J. Eberhardt
U.S. Department of Energy
Office of Transportation
Materials
CE-34, Forrestal Building
Washington, DC 20585
243. Jim Edler
Eaton Corporation
26201 Northwestern
Highway
P.O. Box 756
Southfield, MI 48037
244. William A. Ellingson
Argonne National Laboratory
Materials Science & Technology
Division
9700 South Cass Avenue
Argonne, IL 60439
245. William S. Ellis
Machined Ceramics
629 N. Graham St.
N. Industrial Park
Bowling Green, KY 42101
246. Glen B. Engle
Nuclear & Aerospace Materials
Corporation
16716 Martincoit Road
Poway, CA 92064
247. Jeff Epstein
Ceramic Technologies, Inc.
2107 Jamara Lane
Houston, TX 77077
248. Kenneth A. Epstein
Dow Chemical U.S.A.
Ceramics and Advanced
Materials
800 Building
Midland, MI 48667
249. Art Erdemir
Argonne National Laboratory
Materials and Components
Technology Division
9700 South Cass Avenue
Argonne, IL 60439
250. E. M. Erwin
Lubrizol Corporation
1819 East 225th Street
Euclid, OH 44117
251. Kenji Esaki
Toyota Technical Center
U.S.A., Inc.
2000 Town Center, Suite 500
Southfield, MI 48075
252. Jose L. Escalante
Anglo-Mex-Tech. Inc.
3923 N.W. 24th Street
Miami, FL 33142
253. John N. Eustis
U.S. Department of Energy
Industrial Energy Efficiency
Division
CE-221, Forrestal Building
Washington, DC 20585
254. Robert C. Evans
NASA Lewis Research Center
Terrestrial Propulsion Office
21000 Brookpark Road, MS:86-6
Cleveland, OH 44135
255. W. L. Everitt
Kyocera International, Inc.
8611 Balboa Avenue
San Diego, CA 92123

256. Gordon Q. Evison
332 South Michigan Avenue
Suite 1730
Chicago, IL 60604
257. John W. Fairbanks
U.S. Department of Energy
Advanced Propulsion Division
CE-322, Forrestal Building
Washington, DC 20585
258. Tim Fawcett
Dow Chemical Company
Central Research, Advanced
Ceramics Laboratory
1776 Building
Midland, MI 48674
259. Robert W. Fawley
Sundstrand Power Systems
Division of Sundstrand
Corporation
4400 Ruffin Road
P.O. Box 85757
San Diego, CA 92186-5757
260. John J. Fedorchak
GTE Products Corporation
Hawes Street
Towanda, PA 18848-0504
261. Jeff T. Fenton
Vista Chemical Company
900 Threadneedle
Houston, TX 77079
262. Larry Ferrell
Babcock & Wilcox
Old Forest Road
Lynchburg, VA 24505
263. Raymond R. Fessler
BIRL
Industrial Research Lab
1801 Maple Avenue
Evanston, IL 60201
264. Michelle Finch
E. I. DuPont de Nemours &
Company, Inc.
Experimental Station
Information Center E302/301
Wilmington, DE 19898
265. Arthur D. Fine
United Technologies Corporation
Pratt & Whitney Aircraft
400 Main Street
MS:163-10
East Hartford, CT 06108
266. Ross F. Firestone
Ross Firestone Company
188 Mary Street
Winnetka, IL 60093-1520
267. Sharon L. Fletcher
Arthur D. Little, Inc.
15 Acorn Park
Cambridge, MA 02140-2390
268. Thomas F. Foltz
Textron Specialty Materials
2 Industrial Avenue
Lowell, MA 01851
269. Renee G. Ford
Materials and Processing Report
P.O. Box 72
Harrison, NY 10528
270. John Formica
Supermaterials
2020 Lakeside Avenue
Cleveland, OH 44114
271. Jennifer M. Fox
Dyson Refractories Limited
R&D Laboratory
Owler Bar
Sheffield S17 3BJ
UNITED KINGDOM AIR MAIL
272. Edwin Frame
Southwest Research Institute
Division 2
P.O. Drawer 28510
San Antonio, TX 78284
273. Armanet Francois
French Scientific Mission
4101 Reservoir Road, N.W.
Washington DC 20007-2176
274. R. G. Frank
Technology Assessment Group
10793 Bentley Pass Lane
Loveland, OH 45140

275. David J. Franus
Forecast International
22 Commerce Road
Newtown, CT 06470
276. Marc R. Freedman
NASA Lewis Research Center
21000 Brookpark Road
MS:49-3
Cleveland, OH 44135
277. Douglas Freitag
LTV Missiles Division
P.O. Box 650003
MS:WT-21
Dallas, TX 75265
278. Brian R.T. Frost
Argonne National Laboratory
9700 South Cass Avenue
Building 900
Argonne, IL 60439
279. Lawrence R. Frost
Instron Corporation
100 Royall Street
Canton, MA 02021
280. George A. Fryburg
Norton/TRW Ceramics
7A-4 Raymond Avenue
Salem, NH 03079
281. Xiren Fu
Shanghai Institute of Ceramics
Chinese Academy of Sciences
1295 Ding-xi Road
Shanghai 200050
CHINA AIR MAIL
282. John Gahimer
P.O. Box 1302
Dublin, OH 43017
283. J. P. Gallagher
University of Dayton Research
Institute
300 College Park, JPC-250
Dayton, OH 45469-0120
284. Tom Garritano
University of Tennessee
Science Alliance
101 South College
Knoxville, TN 37996-1328
285. Joy A. Garwood
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
286. H. Maury Gatewood
Reynolds Metals Company
Corporate R&D
Fourth and Canal Streets
P.O. Box 27003
Richmond, VA 23261
287. L. J. Gauckler
ETH-Zurich
Sonneggstrasse 5
CH-8092 Zurich 8092
SWITZERLAND AIR MAIL
288. Peter A. Gaydos
Battelle Columbus Laboratories
505 King Avenue
Columbus, OH 43201
289. George E. Gazza
U.S. Army Materials
Technology Laboratory
Ceramics Research Division
405 Arsenal Street
Watertown, MA 02172-0001
290. D. Gerster
CEA-DCOM
33 Rue De La Federation
Paris 75015
FRANCE AIR MAIL
291. John Ghinazzi
Coors Technical Ceramics
Company
1100 Commerce Park Drive
Oak Ridge, TN 37830

292. Robert Giddings
General Electric Company
Research Laboratory
P.O. Box 8
Schenectady, NY 12301
293. A. M. Glaeser
University of California
Materials Science and Mineral
Engineering
Lawrence Berkeley Laboratory
Hearst Mining Building
Berkeley, CA 94720
294. Paul Glance
Concept Analysis
R&D
950 Stephenson Highway
Dupont Automotive Development
Building
Troy, MI 48007-7013
295. Joseph W. Glatz
Naval Air Propulsion Center
Systems Engineering Division
P.O. Box 7176, PE24
Trenton, NJ 08628
296. W. M. Goldberger
Superior Graphite Company
R&D
2175 East Broad Street
Columbus, OH 43209
297. Allan E. Goldman
U.S. Graphite, Inc.
907 West Outer Drive
Oak Ridge, TN 37830
298. Stephen T. Gonczy
Allied Signal Research
P.O. Box 5016
Des Plaines, IL 60017
299. Jeffrey M. Gonzales
GTE Products Corporation
Hawes Street
Towanda, PA 18848-0504
300. Robert J. Gottschall
U.S. Department of Energy
ER-131, MS:G-236
Washington, DC 20545
301. Earl Graham
Cleveland State University
Department of Chemical
Engineering
Euclid Avenue at
East 24th Street
Cleveland, OH 44115
302. William A. Graham
Lanxide Corporation
P.O. Box 6077
Newark, DE 19714-6077
303. Robert E. Green, Jr.
Johns Hopkins University
Materials Science and
Engineering Department
Baltimore, MD 21218
304. Lance Groseclose
General Motors Corporation
Allison Gas Turbine Division
P.O. Box 420, MS:W-5
Indianapolis, IN 46206
305. Mark F. Gruninger
Union Carbide Corporation
Specialty Powder Business
1555 Main Street
Indianapolis, IN 46224
306. Ernst Gugel
Cremer Forschungsinstitut
GmbH&Co.KG
Oeslauer Strasse 35
D-8633 Roedental 8633
GERMANY AIR MAIL
307. Donald L. Guile
Corning Glass Works
SP-DV-1-9
Corning, NY 14831
308. Bimleshwar P. Gupta
Solar Energy Research
Institute
Mechanical and Industrial
Technology Division
1617 Cole Boulevard
Golden, CO 80401

309. John P. Gyekenyesi
NASA Lewis Research Center
21000 Brookpark Road, MS:6-1
Cleveland, OH 44135
310. Nabil A. Hakim
Detroit Diesel Corporation
13400 West Outer Drive
Detroit, MI 48239
311. Philip J. Haley
General Motors Corporation
Vehicular Engineering
P.O. Box 420, MS:T12A
Indianapolis, IN 46236
312. Judith Hall
Fiber Materials, Inc.
Biddeford Industrial Park
5 Morin Street
Biddeford, ME 04005
313. Y. Harada
IIT Research Institute
Nometallic Materials and
Composites
10 West 35th Street
Chicago, IL 60616
314. R. A. Harmon
25 Schalren Drive
Latham, NY 12110
315. Amy Harmon-Barrett
Martin Marietta Laboratories
1450 South Rolling Road
Baltimore, MD 21227
316. Norman H. Harris
Hughes Aircraft Company
P.O. Box 800520
Saugus, CA 91380-0520
317. Alan Hart
Dow Chemical Company
Advanced Ceramics Laboratory
1776 Building
Midland, MI 48674
318. Pat E. Hart
Battelle Pacific Northwest
Laboratories
Ceramics and Polymers
Development Section
P.O. Box 999
Richland, WA 99352
319. Stephen D. Hartline
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
320. Michael H. Haselkorn
Caterpillar, Inc.
Engineering Research Materials
Technical Center, Building E
P.O. Box 1875
Peoria, IL 61656-1875
321. N. B. Havewala
Corning, Inc.
SP-PR-11
Corning, NY 14831
322. John Haygarth
Teledyne WAA Chang Albany
P.O. Box 460
Albany, OR 97321
323. Norman L. Hecht
University of Dayton Research
Institute
300 College Park
Dayton, OH 45469-0172
324. Peter W. Heitman
General Motors Corporation
Allison Gas Turbine Division
P.O. Box 420, MS:W-5
Indianapolis, IN 46206-0420
325. Robert W. Hendricks
Virginia Polytechnic Institute
and State University
Materials Engineering
Department
210 Holden Hall
Blacksburg, VA 24061-0237

326. Wynne Henley
Hertel Cutting Technologies, Inc.
1000 Clearview Court
Oak Ridge, TN 37830
327. Thomas L. Henson
GTE Products Corporation
Chemical & Metallurgical
Division
Hawes Street
Towanda, PA 18848
328. Thomas P. Herbell
NASA Lewis Research Center
21000 Brookpark Road
MS:49-3
Cleveland, OH 44135
329. Marlene Heroux
Rolls-Royce, Inc.
2849 Paces Ferry Road
Suite 450
Atlanta, GA 30339-3769
330. Robert L. Hershey
Science Management Corporation
1255 New Hampshire Ave., N.W.
Suite 1033
Washington, DC 20036
331. Hendrik Heystek
Bureau of Mines
Tuscaloosa Research Center
P.O. Box L
University, AL 35486
332. Wallace C. Higgins
Norwal Unlimited
P.O. Box 1258
Alfred, NY 14802
333. Robert V. Hillery
GE Aircraft Engines
One Neumann Way, M.D. H85
Cincinnati, OH 45215
334. Arthur Hindman
Instron Corporation
100 Royall Street
Canton, MA 02021
335. Jon Hines
American Ceramic Society, Inc.
757 Brooksedge Plaza Drive
Westerville, OH 43081-6136
336. Hans Erich Hintermann
CSEM
Materials and Micromechanics
Division
Rue Breguet-2
Neuchatel 2000
SWITZERLAND AIR MAIL
337. Shinichi Hirano
Mazda R&D of North
America, Inc.
1203 Woodridge Avenue
Ann Arbor, MI 48105
338. Tommy Hiraoka
NGK Locke, Inc.
1000 Town Center
Southfield, MI 48075
339. John M. Hobday
U.S. Department of Energy
Morgantown Energy Technology
Center
Collins Ferry Road
P.O. Box 880
Morgantown, WV 26507
340. Greg Hoenes
Vista Chemical Company
900 Threadneedle
P.O. Box 19029
Houston, TX 77079-2990
341. Clarence Hoenig
Lawrence Livermore National
Laboratory
P.O. Box 808, Mail Code L-369
Livermore, CA 94550
342. Thomas Hollstein
Fraunhofer-Institut fur
Werkstoffmechanik IWM
Wohlerstrabe 11
D-7800 Freiburg
GERMANY AIR MAIL

343. Richard Holt
National Research Council
of Canada
Structures and Materials
Laboratory
Ottawa Ontario K1A 0R6
CANADA AIR MAIL
344. Joseph Homeny
University of Illinois
Department of Materials Science
and Engineering
105 South Goodwin Avenue
Ceramics Building
Urbana, IL 61801
345. A. T. Hopper
Battelle Columbus
Laboratories
Metals and Ceramics Department
505 King Avenue
Columbus, OH 43201-2693
346. Michael Horgan
Materials Engineering Magazine
1100 Superior Avenue
Cleveland, OH 44114
347. Woodie Howe
Coors Technical Ceramics
Company
1100 Commerce Park Drive
Oak Ridge, TN 37830
348. Stephen M. Hsu
National Institute of
Standards and Technology
Gaithersburg, MD 20899
349. Hann S. Huang
Argonne National Laboratory
9700 South Cass Avenue
Argonne, IL 60439-4815
350. Gene Huber
Precision Ferrites & Ceramics
5576 Corporate Drive
Cypress, CA 90630
351. M. L. Huckabee
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
352. Harold A. Huckins
Princeton Advanced
Technology, Inc.
56 Finley Road
Princeton, NJ 08540
353. Fred R. Huettig
Advanced Magnetics, Inc.
45 Corey Lane
Mendham, NJ- 07945
354. Bill Huffman
Zircar
110 North Main Street
Florida, NY 10921
355. Brian K. Humphrey
Lubrizol Petroleum
Chemicals Co.
3000 Town Center, Suite 1340
Southfield, MI 48075-1201
356. Robert M. Humrick
Dylon Ceramic Technologies
3100 Edgehill Road
Cleveland Heights, OH 44118
357. Lorretta Inglehart
National Science Foundation
Division of Materials Research
1800 "G" Street, N.W.,
Room 408
Washington, DC 20550
358. Michael S. Inoue
Kyocera International, Inc.
KII Library
8611 Balboa Avenue
San Diego, CA 92123-1580
359. Osama Jadaan
University of Wisconsin-
Platteville
General Engineering Division
1 University Plaza
Platteville, WI 53818
360. Curtis A. Johnson
General Electric Company
Corporate R&D
Room MB-187
P.O. Box 8
Schenectady, NY 12301

361. Sylvia Johnson
SRI International
333 Ravenswood Avenue
Menlo Park, CA 94025
362. Thomas A. Johnson
Lanxide Corporation
1300 Marrows Road
P.O. Box 6077
Newark, DE 19714-6077
363. W. S. Johnson
Indiana University
One City Centre, Suite 200
Bloomington, IN 47405
364. Jill E. Jonkouski
U.S. Department of Energy
9800 South Cass Avenue
Argonne, IL 60439-4899
365. L. A. Joo
Great Lakes Research
Corporation
P.O. Box 1031
Elizabethton, TN 37643
366. A. D. Joseph
SPX Corporation
700 Terrace Point
Muskegon, MI 49443
367. Adam Jostsons
Australian Nuclear Science &
Technology Organization
Lucas Heights Research
Laboratories
New Illawarra Road
Lucas Heights New South Wales
AUSTRALIA AIR MAIL
368. Matthew K. Juneau
Ethyl Corporation
451 Florida Street
Baton Rouge, LA 70801
369. Hartmut Kainer
Didier-Werke AG
Anlagentechnik Wiesbaden
Abraham-Lincoln-Str. 16
D-62 Wiesbaden
GERMANY AIR MAIL
370. Tom Kalamasz
Norton/TRW Ceramics
7A-4 Raymond Avenue
Salem, NH 03079
371. Lyle R. Kallenbach
Phillips Petroleum Company
R&D
Mail Drop:123AL
Bartlesville, OK 74004
372. Nick Kamiya
Kyocera Industrial Ceramics
Corporation
2700 River Road
Des Plaines, IL 60018
373. Roy Kamo
Adiabatics, Inc.
3385 Commerce Park Drive
Columbus, IN 47201
374. S. Kang
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
375. Chih-Chun Kao
Industrial Technology Research
Institute
Materials Research
Laboratories
195 Chung-Hsing Road, Sec. 4
Chutung Hsinchu 31015 R.O.C.
TAIWAN AIR MAIL
376. Keith R. Karasek
Allied-Signal, Inc.
Engineered Materials Research
Center
50 East Algonquin Road
P.O. Box 5016
Des Plaines, IL 60017-5016
377. Robert E. Kassel
Ceradyne, Inc.
3169 Redhill Avenue
Costa Mesa, CA 92626
378. Allan Katz
Wright Laboratory
Metals and Ceramics Division
WL/MLLM
Wright-Patterson AFB, OH 45433

379. R. Nathan Katz
Worcester Polytechnic
Institute
Dept. of Mechanical
Engineering
100 Institute Road
Worcester, MA 01609
380. Ted Kawaguchi
Tokai Carbon America, Inc.
375 Park Avenue, Suite 3802
New York, NY 10152
381. Noritsugu Kawashima
TOSHIBA Corporation
Mechanical Engineering
Laboratory
4-1 Ukishima-Cho
Kawasaki-Ku Kawasaki 210
JAPAN AIR MAIL
382. Lisa Kempfer
Penton Publishing
Materials Engineering
1100 Superior Avenue
Cleveland, OH 44114-2543
383. Frederick L. Kennard, III
General Motors Corporation
AC Rochester
Department 32-24, EB
1300 North Dort Highway
Flint, MI 48556
384. David O. Kennedy
Lester B. Knight Cast
Metals Inc.
549 West Randolph Street
Chicago, IL 60661
385. George Keros
Photon Physics
3175 Penobscot Building
Detroit, MI 48226
386. Pramod K. Khandelwal
General Motors Corporation
Allison Gas Turbine
Division
P.O. Box 420, MS:W05
Indianapolis, IN 46206
387. Jim R. Kidwell
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
P.O. Box 5227
Phoenix, AZ 85010
388. Han J. Kim
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
389. Shin Kim
Korea Institute of Machinery
& Metals
66 Sangnam-dong, Changwon
Kyungnam 641-010
KOREA AIR MAIL
390. W. C. King
Mack Truck, Z-41
1999 Pennsylvania Avenue
Hagerstown, MD 21740
391. Carol Kirkpatrick
MSE, Inc.
CDIF Technical Library
P.O. Box 3767
Butte, MT 59702
392. Tony Kirn
Caterpillar, Inc.
Defense Products Department, JB7
Peoria, IL 61629
393. James D. Kiser
NASA Lewis Research Center
21000 Brookpark Road, MS:49-3
Cleveland, OH 44135
394. Max Klein
Gas Research Institute
Thermodynamics
8600 West Bryn Mawr Avenue
Chicago, IL 60631
395. Richard N. Kleiner
Coors Ceramics Company
4545 McIntyre Street
Golden, CO 80403

396. Stanley J. Klima
NASA Lewis Research Center
21000 Brookpark Road
MS:6-1
Cleveland, OH 44135
397. Chris E. Knapp
Norton Advanced Ceramics
of Canada Ltd.
8001 Daly Street
Niagara Falls, Ontario L2G 6S2
CANADA AIR MAIL
398. Albert S. Kobayashi
University of Washington
Mechanical Engineering
Department
MS:FU10
Seattle, WA 98195
399. Shigeki Kobayashi
Toyota Central Research
Labs, Inc.
Nagakute Aichi 480-11
JAPAN AIR MAIL
400. Richard A. Kole
Z-Tech Corporation
8 Dow Road
Bow, NH 03304
401. E. Kostiner
University of Connecticut
Chemistry Department, U-60
Storrs, CT 06269-3060
402. Kenneth A. Kovaly
Technical Insights, Inc.
P.O. Box 1304
Fort Lee, NJ 07024-9967
403. Ralph G. Kraft
Spraying Systems Company
North Avenue at Schmale Road
Wheaton, IL 60189-7900
404. Saunders B. Kramer
U.S. Department of Energy
Advanced Propulsion Division
CE-322, Forrestal Building
Washington, DC 20585
405. Arthur Kranish
Trends Publishing, Inc.
1079 National Press Building
Washington, DC 20045
406. A. S. Krieger
Radiation Science, Inc.
P.O. Box 293
Belmont, MA 02178
407. Pieter Krijgsman
Ceramic Design International
Holding B.V.
P.O. Box 68
Hattem 8050-AB
THE NETHERLANDS AIR MAIL
408. Waltraud M. Kriven
University of Illinois
Materials Science and
Engineering Department
105 South Goodwin Avenue
Urbana, IL 61801
409. Edward J. Kubel, Jr.
ASM International Advanced
Materials & Processes
Materials Park, OH 44073
410. Dave Kupperman
Argonne National Laboratory
9700 South Cass Avenue
Argonne, IL 60439
411. Oh-Hun Kwon
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
412. W. J. Lackey
Georgia Institute of Technology
Materials Science and
Technology
Atlanta, GA 30332
413. Jai Lala
Tenmat Ltd.
40 Somers Road
Rugby Warwickshire CV22 7DH
ENGLAND AIR MAIL

414. Hari S. Lamba
General Motors Corporation
Electro-Motive Division
9301 West 55th Street
LaGrange, IL 60525
415. Richard L. Landingham
Lawrence Livermore National
Laboratory
Ceramics, Corrosion, and
Thermochemistry
P.O. Box 808, L-369
Livermore, CA 94550
416. Charles J. Landry
Chand Kare Technical Ceramics
712 Flat Hill Road
Lumburg, MA 01462
417. Manfred W. Langer
Volkswagen AG
Material Technology
3180 Wolfsburg 1
GERMANY AIR MAIL
418. James Lankford
Southwest Research Institute
Department of Materials
Sciences
6220 Culebra Road
San Antonio, TX 78228-0510
419. Stanley B. Lasday
Business News Publishing Co.
Manor Oak One
1910 Cochran Road, Suite 630
Pittsburgh, PA 15220
420. Mark S. Laser
Solar Turbines, Inc.
2211 Erie Street
San Diego, CA 92110
421. S. K. Lau
Carborundum Company
Technology Division
P.O. Box 832, B-100
Niagara Falls, NY 14302
422. Edward A. Lauder
Advanced Composite Materials
Corporation
1525 South Buncombe Road
Greer, SC 29651-9208
423. J. Lawrence Lauderdale
Babcock & Wilcox
Contract Research Division
1850 "K" Street, Suite 950
Washington, DC 20006
424. Harry A. Lawler
Carborundum Company
Technology Division
P.O. Box 832
Niagara Falls, NY 14302
425. Jean F. LeCostaouec
Textron Speciality Materials
2 Industrial Avenue
Lowell, MA 01851
426. Benson P. Lee
Interscience, Inc.
9718 Lake Shore Boulevard
Cleveland, OH 44108
427. Burtrand I. Lee
Clemson University
Department of Ceramic
Engineering
Olin Hall
Clemson, SC 29634-0907
428. June-Gunn Lee
KIST
Structural Ceramic Lab
P.O. Box 131, Cheong-Ryang
Seoul 130-650
KOREA AIR MAIL
429. Ran-Rong Lee
Ceramics Process Systems
Corporation
155 Fortune Boulevard
Milford, MA 01757
430. Stan Levine
NASA Lewis Research Center
21000 Brookpark Road
MS:49-3
Cleveland, OH 44135
431. Alan V. Levy
Lawrence Berkeley Laboratory
One Cyclotron Road, MS:62-203
Berkeley, CA 94720

432. Ai-Kang Li
Materials Research
Laboratories, ITRI
195-5 Chung-Hsing Road, Sec. 4
Chutung Hsinchu 31015 R.O.C.
TAIWAN AIR MAIL
433. Winston W. Liang
Hong Kong Industrial
Technology Centre Co. Ltd.
78 Tat Chee Avenue
4/F, HKPC Building
Howloon
HONG KONG AIR MAIL
434. Robert Licht
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
435. E. Lilley
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
436. Laura J. Lindberg
Allied-Signal Aerospace
Company
Garrett Fluid Systems Division
1300 West Warner
MS: 93-901-1207-4TT
P.O. Box 22200
Tempe, AZ 85284-2200
437. Leonard C. Lindgren
General Motors Corporation
Allison Gas Turbine Division
P.O. Box 420, Speed Code:T-20A
Indianapolis, IN 46206-0420
438. Hans A. Lindner
Cremer Forschungsinstitut
GmbH&Co.KG
Oeslauer Strasse 35
D-8633 Rodental 8866
GERMANY AIR MAIL
439. Ronald E. Loehman
Sandia National Laboratories
Chemistry & Ceramics
Department 1840
P.O. Box 5800
Albuquerque, NM 87185
440. Jeffrey C. Logas
Winona State University
Composite Materials
Engineering
115 Pasteur Hall
Winona, MN 55987
441. Bill Long
Babcock & Wilcox
P.O. Box 11165
Lynchburg, VA 24506
442. William D. Long
Wacker Chemicals (USA), Inc.
ESK Engineered Ceramics
50 Locust Avenue
New Canaan, CT 06840
443. L. A. Lott
EG&G Idaho, Inc.
Idaho National Engineering
Laboratory
P.O. Box 1625
Idaho Falls, ID 83415-2209
444. Raouf O. Loutfy
MER Corporation
7960 South Kolb Road
Tucson, AZ 85706
445. Gordon R. Love
Aluminum Company of America
Alcoa Technical Center
Alcoa Center, PA 15069
446. Lydia Luckevich
Ortech International
2395 Speakman Drive
Mississauga Ontario L5K 1B3
CANADA AIR MAIL

447. James W. MacBeth
Carborundum Company
Structural Ceramics Division
P.O. Box 1054
Niagara Falls, NY 14302
448. H. MacLaren
General Electric Company
Thomson Laboratory, Materials
Engineering 36807
1000 Western Avenue
Lynn, MA 01910
449. George Maczura
Aluminum Company of America
Industrial Chemicals Division
670 One Allegheny Square
Pittsburgh, PA 15212
450. David Maginnis
Tinker AFB
OC-ALC/LIIRE
Tinker AFB OK 73145-5989
451. Frank Maginnis
Aspen Research, Inc.
220 Industrial Boulevard
Moore, OK 73160
452. Tai-il Mah
Universal Energy Systems, Inc.
Ceramics and Composites
Research
4401 Dayton-Xenia Road
Dayton, OH 45432
453. Kenneth M. Maillar
Barbour Stockwell Company
83 Linskey Way
Cambridge, MA 02142
454. Lorenzo Majno
Instron Corporation
100 Royall Street
Canton, MA 02021
455. S. G. Malghan
National Institute of Standards
and Technology
I-270 & Clopper Road
Gaithersburg, MD 20899
456. Lars Malmrup
United Turbine AB
Box 13027
Malmo S-200 44
SWEDEN AIR MAIL
457. John Mangels
Ceradyne, Inc.
3169 Redhill Avenue
Costa Mesa, CA 92626
458. Russell V. Mann
Matec Applied Sciences, Inc.
75 South Street
Hopkinton, MA 01748
459. William R. Manning
Champion Aviation Products
Division
Old Norris Road
P.O. Box 686
Liberty, SC 29657
460. Ken Marnoch
Amercom, Inc.
8928 Fullbright Avenue
Chatsworth, CA 91311
461. Robert A. Marra
Aluminum Company of America
Alcoa Technical Center
Advanced Ceramics Center - E
Alcoa Center, PA 15069
462. Chauncey L. Martin
3M Company
3M Center, Building 60-1N-01
St. Paul, MN 55144
463. Steven C. Martin
Advanced Refractory
Technologies, Inc.
699 Hertel Avenue
Buffalo, NY 14207
464. Kelly J. Mather
Williams International
Corporation
2280 West Maple Road
P.O. Box 200
Walled Lake, MI 48088

465. James P. Mathers
3M Company
3M Center
Building 201-3N-06
St. Paul, MN 55144
466. Marshall Mayer
Instron Corporation
3815 Presidential Parkway,
Suite 100
Atlanta, GA 30340
467. Ron Mayville
Arthur D. Little, Inc.
15-163 Acorn Park
Cambridge, MA 02140
468. F. N. Mazadarany
General Electric Company
Research Laboratory
Building K-1, Room MB-159
P.O. Box 8
Schenectady, NY 12301
469. James W. McCauley
Alfred University
NYS College of Ceramics
Binns-Merrill Hall
Alfred, NY 14802
470. Carolyn McCormick
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
Bldg. 1303-206
P.O. Box 5227, MS:9317-2
Phoenix, AZ 85010
471. Louis R. McCreight
2763 San Ramon Drive
Rancho Palos Verdes, CA 90274
472. Colin F. McDonald
McDonald Thermal Engineering
1730 Castellana Road
La Jolla, CA 92037
473. B. J. McEntire
Norton Company, TRW Ceramics
Goddard Road
Northboro, MA 01532-1545
474. Chuck McFadden
Coors Ceramics Company
600 9th Street
Golden, CO 80401
475. Henry McFadden
Magnetic Bearings, Inc.
Engineering Library
609 Rock Road
Radford, VA- 24141
476. Thomas D. McGee
Iowa State University
Materials Science and
Engineering Department
110 Engineering Annex
Ames, IA 50011
477. Carol McGill
Corning Inc.
Sullivan Park, FR-02-08
Corning, NY 14831
478. T. C. McLaren
Cameron Forged Products
Company
P.O. Box 1212
Houston, TX 77251-1212
479. James McLaughlin
Sundstrand Power Systems
4400 Ruffin Road
P.O. Box 85757
San Diego, CA 92186-5757
480. Arthur F. McLean
6225 North Camino Almonte
Tucson, AZ 85718
481. Matt McMonigle
U.S. Department of Energy
Improved Energy Productivity
Division
Forrestal Building,
CE-231
Washington, DC 20585
482. Dennis McMurtry
EG&G Idaho, Inc.
Idaho National Engineering
Laboratory
P.O. Box 1625
Idaho Falls, ID 83415

483. D. B. Meadowcroft
National Power Technology
and Environmental Centre
Kelvin Avenue
Leatherhead Surrey
KT22 7SE
ENGLAND AIR MAIL
484. Jo Meglen
11004 Birdfoot Court
Reston, VA 22091
485. Pankaj K. Mehrotra
Kennametal, Inc.
P.O. Box 639
Greensburg, PA 15601
486. Joseph J. Meindl
Reynolds International, Inc.
6603 West Broad Street
P.O. Box 27002
Richmond, VA 23261-7003
487. Michael D. Meiser
Allied-Signal Aerospace Company
Garrett Ceramic Components
Division
19800 South Van Ness Avenue
Torrance, CA 90509
488. George Messenger
National Research Council of
Canada
Engine Laboratory
Building M-7
Ottawa Ontario K1A 0R6
CANADA AIR MAIL
489. D. Messier
U.S. Army Materials Technology
Laboratory
SLCMT-EMC
405 Arsenal Street
Watertown, MA 02172-0001
490. Gary L. Messing
Pennsylvania State University
Ceramic Science and Engineering
Department
119 Steidle Building
University Park, PA 16802
491. Arthur G. Metcalfe
Arthur G. Metcalfe and
Associates, Inc.
2108 East 24th Street
National City, CA 91950
492. R. Metselaar
Eindhoven University
Centre for Technical Ceramics
P.O. Box 513
Eindhoven 5600 MB
THE NETHERLANDS AIR MAIL
493. Nancy S. Meyers
U.S. Department of Energy
Transportation Technologies
CE-30, Forrestal Building
6B-094
Washington, DC 20585
494. David J. Michael
Harbison-Walker Refractories
Company
P.O. Box 98037
Pittsburgh, PA 15227
495. Ken Michaels
Chrysler Motors Corporation
Ceramics Development
Metallurgical Processes
P.O. Box 1118, CIMS:418-17-09
Detroit, MI 48288
496. Bernd Michel
Institute of Mechanics
Fracture and Micromechanics
Department
P.O. Box 408
D-9010 Chemnitz
GERMANY AIR MAIL
497. David E. Miles
Commission of the European
Communities
rue de la Loi, 200
B-1049 Brussels
BELGIUM AIR MAIL
498. John V. Milewski
Superkinetics, Inc.
P.O. Box 8029
Santa Fe, NM 87504

499. Carl E. Miller
AC Rochester
1300 North Dort Highway,
MS:32-31
Engineering Building B
Flint, MI 48556
500. Mike Miller
McGraw-Hill Aviation Week
Performance Materials
1156 15th Street, N.W.
Washington, DC 20005
501. Charles W. Miller, Jr.
Centorr Furnaces/Vacuum
Industries
542 Amherst Street
Nashua, NH 03063
502. R. Mininni
Enichem America
2000 Cornwall Road
Monmouth Junction, NJ 08852
503. Michele V. Mitchell
Allied-Signal Aerospace
Company
Garrett Ceramic Components
Division
19800 South Van Ness Avenue
Torrance, CA 90501-1149
504. Howard Mizuhara
GTE - WESGO
477 Harbor Boulevard
Belmont, CA 94002
505. Helen Moeller
Babcock & Wilcox
P.O. Box 11165
Lynchburg, VA 24506-1165
506. Francois R. Mollard
Metalworking Technology, Inc.
1450 Scalp Avenue
Johnstown, PA 15904
507. Phil Mooney
Panametrics
NDE Division
221 Crescent Street
Waltham, MA 02254
508. Thomas Morel
Ricardo North America
645 Blackhawk Drive
Westmont, IL 60559
509. Geoffrey P. Morris
3M Company
3M Traffic Control Materials
Division
Bldg. 209-BW-10, 3M Center
St. Paul, MN 55144-1000
510. Jay A. Morrison
Rolls-Royce, Inc.
Engineering and Information
Center, Overlook 1
2849 Paces Ferry Road,
Suite 450
Atlanta, GA 30339-3769
511. Joel P. Moskowitz
Ceradyne, Inc.
3169 Redhill Avenue
Costa Mesa, CA 92626
512. Brij Moudgil
University of Florida
Material Science and
Engineering
Gainesville, FL 32611
513. Christoph J. Mueller
Sprehsaal Publishing
Group
P.O. Box 2962, Mauer 2
D-8630 Coburg
GERMANY AIR MAIL
514. Thomas W. Mullan
Vapor Technologies Inc.
345 Route 17 South
Upper Saddle River, NJ 07458
515. M. K. Murthy
MKM Consultants International
10 Avoca Avenue, Unit 1906
Toronto Ontario M4T 2B7
CANADA AIR MAIL
516. Solomon Musikant
TransCon Technologies, Inc.
Materials Science & Engineering
1508 Waynesboro Road
Paoli, PA 19301

517. David L. Mustoe
Custom Technical Ceramics
8041 West I-70 Service Road,
Unit 6
Arvada, CO 80002
518. Curtis V. Nakaishi
U.S. Department of Energy
Morgantown Energy Technology
Center
Collins Ferry Road
P.O. Box 880
Morgantown, WV 26507-0880
519. Yoshio Nakamura
Faicera Research Institute
2-5-8 Hiyakunin-cho Shinjuku-Ko
Tokyo
JAPAN AIR MAIL
520. K. S. Narasimhan
Hoeganaes Corporation
River Road
Riverton, NJ 08077
521. Samuel Natansohn
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
522. Robert Naum
Applied Resources, Inc.
P.O. Box 241
Pittsford, NY 14534
523. Malcolm Naylor
Cummins Engine Company, Inc.
P.O. Box 3005, Mail Code 50183
Columbus, IN 47202-3005
524. Jeffrey Neil
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
525. Fred A. Nichols
Argonne National Laboratory
9700 South Cass Avenue
MCT - Building 212
Argonne, IL 60439
526. H. Nickel
Forschungszentrum Jüelich (KFA)
P.O. Box 1913
Jüelich 1-5170 BRD NRW
GERMANY AIR MAIL
527. Dale E. Niesz
Rutgers University
Center for Ceramic Research
P.O. Box 909
Piscataway, NJ 08855-0909
528. David M. Nissley
United Technologies Corporation
Pratt & Whitney Aircraft
400 Main Street, MS:163-10
East Hartford, CT 06108
529. Richard D. Nixdorf
ReMaxCo Technologies, Inc.
11317 Snyder Road
Knoxville, TN 37932
530. Bernard North
Kennametal, Inc.
P.O. Box 639
Greensburg, PA 15601
531. Bruce E. Novich
Ceramics Process Systems
Corporation
155 Fortune Boulevard
Milford, MA 01757
532. Daniel Oblas
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
533. Don Ohanehi
Magnetic Bearings, Inc.
1908 Sussex Road
Blacksburg, VA 24060
534. Robert Orenstein
General Electric Company
55-112, River Road
Schenectady, NY 12345

535. Norb Osborn
Aerodyne Dallas
151 Regal Row,
Suite 120
Dallas, TX 75247
536. A. M. Paddick
BP International Limited
BP Research Centre, Main
Library
Chertsey Road
Sunbury-on-Thames
Middlesex TW16 7LN
UNITED KINGDOM AIR MAIL
537. Russell J. Page
Kanthal-Artcor
3001 Redhill Avenue, II-109
Costa Mesa, CA 92705
538. Richard Palicka
Cercom, Inc.
1960 Watson Way
Vista, CA 92083
539. Muktesh Paliwal
GTE Products Corporation
Hawes Street
Towanda, PA 18848
540. Joseph E. Palko
General Electric Company
55-113, River Road
Schenectady, NY 12345
541. Hayne Palmour, III
North Carolina State
University
Materials Science and
Engineering Dept.
Raleigh, NC 27605-7905
542. Joseph N. Panzarino
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
543. Pellegrino Papa
Corning Inc.
MP-WX-02-1
Corning, NY 14831
544. E. Beth Pardue
Technology for Energy
Corporation
One Energy Center
P.O. Box 22996
Knoxville, TN 37933-0996
545. Soon C. Park
3M Company
3M Center -
Building 142-4N-02
P.O. Box 2963
St. Paul, MN 55144
546. Hartmut Paschke
Schott Glaswerke
Christoph-Dorner-Strasse 29
D-8300 Landshut
GERMANY AIR MAIL
547. Marina R. Pascucci
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
548. James W. Patten
Cummins Engine
Company, Inc.
Materials Engineering
P.O. Box 3005, Mail
Code 50183
Columbus, IN 47202-3005
549. Robert A. Penty
Eastman Kodak Company
KAD/D73 - 35612
901 Elmgrove Road
Rochester, NY 14653
550. Robert W. Pepper
Textron Specialty Materials
2 Industrial Avenue
Lowell, MA 01851
551. Peter Perdue
Detroit Diesel Corporation
Research Advanced Development
Group
13400 West Outer Drive,
Speed Code A-07
Detroit, MI 48239-4001

552. Bruce Peters
Dow Chemical Company
Building 52
Midland, MI 48667
553. John J. Petrovic
Los Alamos National Laboratory
Group MST-4, MS:6771
Los Alamos, NM 87545
554. Frederick S. Pettit
University of Pittsburgh
Pittsburgh, PA 15261
555. Ben A. Phillips
Phillips Engineering Company
721 Pleasant Street
St. Joseph, MI 49085
556. Richard C. Phoenix
Ohmtek, Inc.
2160 Liberty Drive
Niagara Falls, NY 14302
557. Bruce J. Pletka
Michigan Technological
University
Metallurgical and Materials
Engineering Department
Houghton, MI 49931
558. John P. Pollinger
Garrett Ceramic Components
19800 Van Ness Avenue
Torrance, CA 90501
559. P. Popper
High Technology Ceramics
International Journal
22 Pembroke Drive
Westlands Newcastle-under-Lyme
Staffs ST5 2JN
ENGLAND AIR MAIL
560. F. Porz
Universitat Karlsruhe
Institut fur Keramik Im
Maschinendau
Postfach 6980
D-7500 Karlsruhe
GERMANY AIR MAIL
561. Harry L. Potma
Royal Netherlands Embassy
Science and Technology
4200 Linnean Avenue, N.W.
Washington, DC 20008
562. Bob R. Powell
General Motors Research
Laboratories
Metallurgy Department
30500 Mound Road
Box 9055
Warren, MI 48090-9055
563. Stephen C. Pred
ICD Group, Inc.
1100 Valley Brook Avenue
Lyndhurst, NJ 07071
564. Karl M. Prewo
United Technologies Research
Center
411 Silver Lane
MS:24
East Hartford, CT 06108
565. Peter E. Price
Industrial Materials
Technology, Inc.
P.O. Box 9565
Andover, MA 01810
566. Joseph M. Proud
GTE Laboratories, Inc.
Materials Science Laboratory
40 Sylvan Road
Waltham, MA 02254
567. Vimal K. Pujari
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
568. George Quinn
National Institute of
Standards and Technology
Ceramics Division, Bldg. 223
Gaithersburg, MD 20899

569. Ramas V. Raman
Ceracon, Inc.
1101 North Market Boulevard,
Suite 9
Sacramento, CA 95834
570. Charles F. Rapp
Owens Corning Fiberglass
2790 Columbus Road
Granville, OH 43023-1200
571. Dennis W. Readey
Colorado School of Mines
Department of Metallurgy
and Materials Engineering
Golden, CO 80401
572. Wilfred J. Rebello
PAR Enterprises, Inc.
12601 Clifton Hunt Lane
Clifton, VA 22024
573. Harold Rechter
Chicago Fire Brick Company
R&D
7531 South Ashland Avenue
Chicago, IL 60620
574. Robert R. Reeber
U.S. Army Research Office
P.O. Box 12211
Research Triangle Park, NC 27709
575. K. L. Reifsnider
Virginia Polytechnic Institute
and State University
Department of Engineering
Science and Mechanics
Blacksburg, VA 24061
576. Paul E. Rempes
McDonnell Douglass Missile
Systems Company
P.O. Box 516,
Mail Code:1066086
St. Louis, MO 63166-0516
577. Gopal S. Revankar
John Deere Company
Metals Research
3300 River Drive
Moline, IL 61265
578. K. T. Rhee
Rutgers University
Mechanical Engineering
P.O. Box 909
Piscataway, NJ 08854
579. James Rhodes
Advanced Composite Materials
Corporation
1525 South Buncombe Road
Greer, SC 29651
580. Roy W. Rice
W. R. Grace and Company
7379 Route 32
Columbia, MD 21044
581. David W. Richerson
2093 East Delmont Drive
Salt Lake City, UT 84117
582. Tomas Richter
J. H. France Refractories
1944 Clarence Road
Snow Shoe, PA 16874
583. Michel Rigaud
Ecole Polytechnique
Campus Universite De Montreal
P.O. Box 6079, Station A
Montreal, P.Q. Quebec H3C 3A7
CANADA AIR MAIL
584. R. E. Riman
Rutgers University
Ceramics Engineering
Department
P.O. Box 909
Piscataway, NJ 08855-0909
585. Barry Ringstrom
Superior Graphite Company
P.O. Box 2373
Smyrna, GA 30081
586. John E. Ritter
University of Massachusetts
Mechanical Engineering
Department
Amherst, MA 01003

587. Frank L. Roberge
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
P.O. Box 5227
Phoenix, AZ 85010
588. W. Eric Roberts
Advanced Ceramic
Technology, Inc.
990 "F" Enterprise Street
Orange, CA 92667
589. Martha Rohr
U.S. Department of Energy
DOE Oak Ridge Field Office
Building 4500N
P.O. Box 2008, MS:6269
Oak Ridge, TN 37831-6269
590. Y. G. Roman
TNO TPD Keramick
P.O. Box 595
Eindhoven 5600 AN
HOLLAND AIR MAIL
591. Mark D. Roos
Carborundum Company
P.O. Box 156
Niagara Falls, NY 14302
592. Michael Rossetti
Arthur D. Little, Inc.
15 Acorn Park
Cambridge, MA 01240
593. Barry R. Rossing
Lanxide Corporation
1300 Marrows Road
Newark, DE 19714-6077
594. Steven L. Rotz
Lubrizol Corporation
29400 Lakeland Boulevard
Wickliffe, OH 44092
595. Bruce Rubinger
Global Competitiveness, Inc.
One Devonshire Place,
Suite 1011
Boston, MA 02109
596. Robert Ruh
Wright Laboratory
WL/MLLM
Wright-Patterson AFB, OH 45433
597. Robert J. Russell
17 Highgate Road
Framingham, MA 01701
598. L. William Sahley
Supermaterials Company
24400 Highland Road
Richmond Heights, OH 44143
599. Jon Salem
NASA Lewis Research Center
21000 Brookpark Center
Cleveland, OH 44135
600. W. A. Sanders
NASA Lewis Research Center
21000 Brookpark Road,
MS:49-3
Cleveland, OH 44135
601. J. Sankar
North Carolina A&T State
University
Department of Mechanical
Engineering
Greensboro, NC 27411
602. Yasushi Sato
NGK Spark Plugs (U.S.A.), Inc.
1200 Business Center Drive,
Suite 300
Mt. Prospect, IL 60056
603. Maxine L. Savitz
Allied-Signal Aerospace
Company
Garrett Ceramic Components
Division
19800 South Van Ness Avenue
Torrance, CA 90501
604. Ashok Saxena
Georgia Institute of
Technology
Materials Engineering
Atlanta, GA 30332-0245

605. David W. Scanlon
Instron Corporation
100 Royall Street
Canton, MA 02021
606. Charles A. Schacht
Schacht Consulting Services
12 Holland Road
Pittsburgh, PA 15235
607. James Schienle
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
2739 East Washington Street
P.O. Box 5227, MS:1302-2P
Phoenix, AZ 85010
608. John C. Schneider
San Juan Technologies
P.O. Box 49326
Colorado Springs, CO 80949-9326
609. Gary Schnittgrund
Rocketdyne, BA05
6633 Canoga Avenue
Canoga Park, CA 91303
610. Mark Schomp
Lonza, Inc.
Corporate Headquarters
17-17 Route 208
Fair Lann, NJ 07410
611. Joop Schoonman
Delft University of Technology
Laboratory for Inorganic
Chemistry
P.O. Box 5045
2600 GA Delft
THE NETHERLANDS AIR MAIL
612. John Schuldies
Industrial Ceramic
Technology, Inc.
37 Enterprise Drive
Ann Arbor, MI 48103
613. Robert B. Schulz
U.S. Department of Energy
Office of Transportation
Materials
CE-34, Forrestal Building
Washington, DC 20585
614. Murray A. Schwartz
Materials Technology
Consulting, Inc.
30 Orchard Way, North
Potomac, MD 20854
615. Peter Schwarzkopf
SRI International
333 Ravenswood Avenue
Menlo Park, CA 94025
616. Thomas C. Schweizer
Princeton Economic
Research, Inc.
12300 Twinbrook Pkwy.,
Suite 650
Rockville, MD 20852
617. William T. Schwessinger
Multi-Arc Scientific
Coatings
1064 Chicago Road
Troy, MI 48083-4297
618. W. D. Scott
University of Washington
Materials Science Department
Mail Stop:FB10
Seattle, WA 98195
619. Nancy Scoville
Thermo Electron Technologies
74 West Street
P.O. Box 9046
Waltham, MA 02254-9046
620. Brian Seegmiller
Coors Ceramics Company
600 9th Street
Golden, CO 80401

621. T. B. Selover
AICRE/DIPPR
3575 Traver Road
Shaker Heights, OH 44122
622. J. H. Selverian
GTE Laboratories, Inc.
40 Sylvan Road
Waltham, MA 02254
623. Charles E. Semler
Semler Materials Services
4160 Mumford Court
Columbus, OH 43220
624. Thomas Service
Service Engineering Laboratory
324 Wells Street
Greenfield, MA 01301
625. Kish Seth
Ethyl Corporation
R&D Laboratories
P.O. Box 341
Baton Rouge, LA 70821
626. Karleen Seybold
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
P.O. Box 5227
Phoenix, AZ 85010
627. William J. Shack
Argonne National Laboratory
9700 South Cass Avenue
Building 212
Argonne, IL 60439
628. Peter T. B. Shaffer
Technical Ceramics
Laboratories, Inc.
4045 Nine/McFarland Drive
Alpharetta, GA 30201
629. Richard K. Shaltens
NASA Lewis Research Center
21000 Brookpark Road,
MS:301-2
Cleveland, OH 44135
630. Robert S. Shane
238 Hemlock Road
Wynnewood, PA 19096
631. Daniel Shanefield
Rutgers University
Ceramics Engineering
Department
P.O. Box 909
Piscataway, NJ 08855-0909
632. Ravi Shankar
Chromalloy
Research and Technology
Division
Blaisdell Road
Orangeburg, NY 10962
633. Terence Sheehan
Alpex Wheel Company
727 Berkley Street
New Milford, NJ 07646
634. Dinesh K. Shetty
University of Utah
304 EMRO, Dept. of Materials
Science and Engineering
Salt Lake City, UT 84112
635. Masahide Shimizu
Ceramic Society of Japan
2-2-503 Takiyama 6-chome
Higashikurume-Shi Tokyo 203
JAPAN AIR MAIL
636. John Shipinski
Toyota Technical Center
U.S.A., Inc.
Technical Research Department
2000 Town Center, Suite 500
Southfield, MI 48075
637. Thomas Shreves
American Ceramic Society, Inc.
Library
757 Brooksedge Plaza Drive
Westerville, OH 43081-2821
638. Jack D. Sibold
Coors Ceramics Company
Contracts for Corporate
Technology
4545 McIntyre Street
Golden, CO 80403

639. George H. Siegel
Point North Associates, Inc.
P.O. Box 907
Madison, NJ 07940
640. Richard Silberglitt
Technology Assessment and
Transfer, Inc.
133 Defense Highway, #212
Annapolis, MD 21401
641. Mary Silverberg
Norton Company
Advanced Ceramics Library
Goddard Road
Northboro, MA 01532-1545
642. Gurpreet Singh
Department of the Navy
Internal Combustion & Gas
Turbine Engine Division
Code 56X31
Washington, DC 20362-5101
643. Maurice J. Sinnott
University of Michigan
Chemical and Metallurgical
Engineering
5106 IST Building
Ann Arbor, MI 48109-2099
644. John Skildum
3M Company
3M Center
Building 224-2S-25
St. Paul, MN 55144
645. David P. Smith
Hoskins, Rees & Smith
1910 Cochran Road
Manor Oak II, Suite 658
Pittsburgh, PA 15220
646. Richard H. Smoak
Smoak & Associates
3554 Hollyslope Road
Altadena, CA 91001-3923
647. Jay R. Smyth
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division
2739 East Washington Street
P.O. Box 5227
MS:93-173/1303-207
Phoenix, AZ 85010
648. Edward A. Snajdr
Premier Refractories
and Chemicals, Inc.
P.O. Box 392
Findlay, OH 44815
649. Rafal A. Sobotowski
British Petroleum Company
Technical Center, Broadway
3092 Broadway Avenue
Cleveland, OH 44115
650. A. G. Solomah
SAC International Ltd.
1445 Bonhill Road, # 13
Mississauga Ontario L5T 1V3
CANADA AIR MAIL
651. S. Somiya
Nishi Tokyo University
3-7-19 Seijo, Setagaya
Tokyo 157
JAPAN AIR MAIL
652. Boyd W. Sorenson
DuPont Lanxide Composites
1300 Marrows Road
P.O. Box 6077
Neward, DE 19707
653. Charles A. Sorrell
U.S. Department of Energy
Advanced Industrial
Concepts Division
CE-232, Forrestal
Building
Washington, DC 20585

654. C. Spencer
EA Technology
Capenhurst Chester
CH1 6ES
UNITED KINGDOM AIR MAIL
655. Allen Spizzo
Hercules, Inc.
Hercules Plaza
Wilmington, DE 19894
656. Richard M. Spriggs
Alfred University
Center for Advanced Ceramic
Technology
Alfred, NY 14802
657. Charles Spuckler
NASA Lewis Research Center
21000 Brookpark Road
MS: 5-11
Cleveland, OH 44135-3191
658. M. Srinivasan
Material Solutions
P.O. Box 663
Grand Island, NY 14702-0663
659. Gordon L. Starr
Cummins Engine Company, Inc.
Design & Technology
P.O. Box 3005
Mail Code 50182
Columbus, IN 47202-3005
660. Jim Stevenson
Windrock, Incorporated
154 Fairbanks Plaza
Oak Ridge, TN 37830
661. Tom Stillwagon
Allied-Signal Aerospace
Company
Garrett Ceramic Components
Division
19800 South Van Ness Avenue
Torrance, CA 90501
662. Harold L. Stocker
General Motors Corporation
Allison Gas Turbine Division
P.O. Box 420
Indianapolis, IN 46206
663. Paul D. Stone
Dow Chemical USA
1776 "Eye" Street, N.W.,
Suite 575
Washington, DC 20006
664. Roger S. Storm
Carborundum Company
Technology Division
P.O. Box 337
Niagara Falls, NY 14302-0337
665. Peter A. Stranges
4 Chittenden Lane
Owings Mills, MD 21117
666. F. W. Stringer
Aero & Industrial
Technology Ltd.
P.O. Box 46, Wood Top
Burnley Lancashire BB11 4BX
UNITED KINGDOM AIR MAIL
667. Thomas N. Strom
NASA Lewis Research Center
21000 Brookpark Road
MS:86-6
Cleveland, OH 44135
668. M. F. Stroosnijder
Institute for Advanced
Materials
Joint Research Centre
21020 Ispra (VA)
ITALY AIR MAIL
669. Karsten Styhr
30604 Ganado Drive
Rancho Palos Verdes, CA 90274
670. T. S. Sudarshan
Materials Modification, Inc.
2929-P1 Eskridge Center
Fairfax, VA 22031
671. M. J. Sundaresan
University of Miami
Mechanical Engineering
Department
P.O. Box 248294
Coral Gables, FL 33124

672. Patrick L. Sutton
U.S. Department of Energy
Advanced Propulsion Division
CE-322, Forrestal Building
Washington, DC 20585
673. Willard H. Sutton
United Technologies
Corporation
Research Center, MS:24
Silver Lane
East Hartford, CT 06108
674. Ron Sviben
100 Indel Avenue
Rancocas, NJ 08073
675. J. J. Swab
U.S. Army Materials Technology
Laboratory
Ceramics Research Division
SLCMT-EMC
405 Arsenal Street
Watertown, MA 02172
676. Robert E. Swanson
Metalworking Technology, Inc.
1450 Scalp Avenue
Johnstown, PA 15904
677. Scott L. Swartz
Battelle Columbus
Laboratories
Metals and Ceramics
505 King Avenue
Columbus, OH 43201
678. Steve Szaruga
Air Force Wright Aeronautical
Laboratory
Materials Directorate
WL/MLBC
Wright-Patterson
AFB, OH 45433-6533
679. Yo Tajima
NGK Spark Plug Company, Ltd.
NTK Technical Ceramic Division
2808 Iwasaki
Komaki-shi Aichi-ken 485
JAPAN AIR MAIL
680. Fred Teeter
5 Tralee Terrace
East Amherst, NY 14051
681. Monika O. Ten Eyck
Carborundum Company
Technology Division
P.O. Box 832
Niagara Falls, NY 14302
682. David F. Thompson
Corning Glass Works
SP-DV-02-1
Corning, NY 14831
683. Merle L. Thorpe
Hobart Tafa Technologies, Inc.
146 Pembroke Road
Concord, NH 03301
684. Eberhard Tiefenbacher
Daimler-Benz AG Abt. F1S
Mercedes-Strabe 136
Stuttgart 60
GERMANY AIR MAIL
685. T. Y. Tien
University of Michigan
Materials Science and
Engineering Department
Dow Building
Ann Arbor, MI 48103
686. Julian M. Tishkoff
Air Force Office of Scientific
Research
AFOSR/NA
Bolling AFB, DC 20332-6448
687. D. M. Tracey
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
688. Dick Trippett
General Motors Corporation
Allison Gas Turbine Division
P.O. Box 420, MS:W-16
Indianapolis, IN 46206-0420

689. L. J. Trostel, Jr.
Box 199
Princeton, MA 01541
690. W. T. Tucker
General Electric Company
Corporate R&D
Building K1-4C35
P.O. Box 8
Schenectady, NY 12301
691. Masanori Ueki
Nippon Steel Corporation
Central R&D Bureau
1618 Ida
Nakahara-Ku Kawasaki 211
JAPAN AIR MAIL
692. Filippo M. Ugolini
ATA Studio
Via Degli Scipioni, 268A
ROMA 00192
ITALY AIR MAIL
693. Donald L. Vaccari
Allison Gas Turbines
P.O. Box 420
Speed Code S49
Indianapolis, IN 46206-0420
694. Carl F. Van Conant
Boride Products, Inc.
2879 Aero Park Drive
Traverse City, MI 49684
695. Marcel H. Van De Voorde
Commission of the European
Communities
Institute for Advanced
Materials
Joint Research Centre
P.O. Box 2
1755 ZG Petten
THE NETHERLANDS AIR MAIL
696. O. Van Der Biest
Katholieke Universiteit Leuven
Departement Metaalkunde en
Toegepaste
de Croylaan 2
B-3030 Leuven
BELGIUM AIR MAIL
697. Michael Vannier
Washington University,
St. Louis
Mallinckrodt Institute of
Radiology
510 South Kings Highway
St. Louis, MO 63110
698. Stan Venkatesan
Southern Coke & Coal
Corporation
P.O. Box 52383
Knoxville, TN 37950
699. V. Venkateswaran
Carborundum Company
Niagara Falls R&D Center
P.O. Box 832
Niagara Falls, NY 14302
700. Dennis Viechnicki
U.S. Army Materials Technology
Laboratory
405 Arsenal Street
Watertown, MA 02172-0001
701. Ted Vojnovich
U.S. Department of Energy
Office of Energy Research,
ER-42
Washington, DC 20585
702. John D. Volt
E. I. Dupont de Nemours &
Company, Inc.
P.O. Box 80262
Wilmington, DE 19880
703. John B. Wachtman
Rutgers University
Ceramics Department
P.O. Box 909
Piscataway, NJ 08855
704. Shigetaka Wada
Toyota Central Research
Labs, Inc.
Nagakute Aichi 480-11
JAPAN AIR MAIL

705. Janet Wade
Allied-Signal Aerospace
Company
Garrett Auxiliary Power
Division, Department 93-772
P.O. Box 5227, MS:1303-2
Phoenix, AZ 85010
706. Richard L. Wagner
Ceramic Technologies, Inc.
537 Turtle Creek South Drive,
Suite 24D
Indianapolis, IN 46227
707. J. Bruce Wagner, Jr.
Arizona State University
Center for Solid State
Science
Tempe, AZ 85287-1704
708. Daniel J. Wahlen
Kohler, Co.
444 Highland Drive
Kohler, WI 53044
709. Ingrid Wahlgren
Royal Institute of Technology
Studsvik Library
S-611 82 Nykoping
SWEDEN AIR MAIL
710. Ron H. Walecki
Allied-Signal Aerospace
Company
Garrett Ceramic Components
Division
19800 South Van Ness Avenue
Torrance, CA 90501
711. Michael S. Walsh
Vapor Technologies Inc.
2100 Central Avenue
Boulder, CO 80301
712. Chien-Min Wang
Industrial Technology Research
Institute
Materials Research Laboratories
195 Chung-Hsing Road, Sec. 4
Chutung Hsinchu 31015 R.O.C.
TAIWAN AIR MAIL
713. Robert M. Washburn
ASMT
11203 Colima Road
Whittier, CA 90604
714. Gerald Q. Weaver
Carborundum Specialty Products
42 Linus Allain Avenue
Gardner, MA 01440-2478
715. Karen E. Weber
Detroit Diesel Corporation
Technology and Planning
13400 West Outer Drive
Detroit, MI 48239-4001
716. R. W. Weeks
Argonne National Laboratory
MCT-212
9700 South Cass Avenue
Argonne, IL 60439
717. Ludwig Weiler
ASEA Brown Boveri AG
Corporate Research
Eppelheimer Str. 82
D-6900 Heidelberg
GERMANY AIR MAIL
718. James Wessel
Dow Corning Corporation
1800 "M" Street, N.W.,
Suite 325 South
Washington, DC 20036
719. Robert D. West
Therm Advanced Ceramics
P.O. Box 220
Ithaca, NY 14851
720. Thomas J. Whalen
Ford Motor Company
26362 Harriet
Dearborn Heights, MI 48127
721. Ian A. White
Hoeganaes Corporation
River Road
Riverton, NJ 08077

722. Alan Whitehead
General Electric Company
1 River Road, 55-111
Schenectady, NY 12345
723. Sheldon M. Wiederhorn
National Institute of
Standards and Technology
Building 223, Room A329
Gaithersburg, MD 20899
724. John F. Wight
Alfred University
McMahon Building
Alfred, NY 14802
725. D. S. Wilkinson
McMaster University
Materials Science and
Engineering Department
1280 Main Street, West
Hamilton Ontario L8S 4L7
CANADA AIR MAIL
726. James C. Williams
General Electric Company
Engineering Materials
Technology Labs
One Neumann Way
Mail Drop: H85
Cincinnati, OH 45215-6301
727. Janette R. Williams
Kollmorgen Corporation
PCK Technology Division
150 Motor Parkway, # 262
Hauppauge, NY 11788-5108
728. Steve J. Williams
RCG Hagler Bailly, Inc.
1530 Wilson Boulevard,
Suite 900
Arlington, VA 22209-2406
729. Craig A. Willkens
Norton Company
Advanced Ceramics
Goddard Road
Northboro, MA 01532-1545
730. Roger R. Wills
TRW, Inc.
Valve Division
1455 East 185th Street
Cleveland, OH 44110
731. David Gordon Wilson
Massachusetts Institute of
Technology
Mechanical-Engineering
Department
77 Massachusetts Avenue,
Room 3-455
Cambridge, MA 02139
732. Matthew F. Winkler
Seaworthy Systems, Inc.
P.O. Box 965
Essex, CT 06426
733. Gerhard Winter
Hermann C. Starck Berlin GmbH,
Werk Goslar
P.O. Box 25 40
D-3380 Goslar 3380
GERMANY AIR MAIL
734. W. L. Winterbottom
Ford Motor Company
Material Systems Reliability
Department
20000 Rotunda Drive
SRL, Room E-3182
P.O. Box 2053
Dearborn, MI 48121
735. David G. Wirth
Coors Ceramics Company
600 9th Street
Golden, CO 80401
736. Thomas J. Wissing
Eaton Corporation
Engineering & Research Center
P.O. Box 766
Southfield, MI 48037
737. James C. Withers
MER Corporation
7960 South Kolb Road
Building F
Tucson, AZ 85706

738. Dale E. Wittmer
Southern Illinois University
Mechanical Engineering
Department
Carbondale, IL 62901
739. Warren W. Wolf
Owens Corning Fiberglass
2790 Columbus Road, Route 16
Granville, OH 43023
740. George W. Wolter
Howmet Turbine Components
Corporation
Technical Center
699 Benston Road
Whitehall, MI 49461
741. James C. Wood
NASA Lewis Research Center
21000 Brookpark Road
MS:86-6
Cleveland, OH 44135
742. Marrill Wood
LECO Corporation
Augusta Division
P.O. Box 211688
Augusta, GA 30917-1688
743. Wayne L. Worrell
University of Pennsylvania
Department of Materials
Science and Engineering
3231 Walnut Street
Philadelphia, PA 19104
744. John F. Wosinski
Corning Inc.
ME-2 E-5 H8
Corning, NY 14830
745. Ian G. Wright
Battelle Columbus Laboratories
505 King Avenue
Columbus, OH 43201
746. Ruth Wroe
ERDC
Metals & Materials Industries
Division
Capenhurst Chester CH1 6ES
ENGLAND AIR MAIL
747. Bernard J. Wrona
Advanced Composite Materials
Corporation
1525 South Buncombe Road
Greer, SC 29651
748. Carl C. M. Wu
Naval Research Laboratory
Ceramic Branch, Code 6373
Washington, DC 20375
749. John C. Wurst
University of Dayton Research
Institute
300 College Park
Dayton, OH 45469-0101
750. Neil Wyant
ARCH Development Corp.
9700 South Cass Avenue
Building 202
Argonne, IL 60439
751. Roy Yamamoto
Texaco Inc.
P.O. Box 509
Beacon, NY 12508-0509
752. John Yamanis
Allied-Signal, Inc.
Ceramics Program
P.O. Box 1021
Morristown, NJ 07962-1021
753. Harry C. Yeh
Allied-Signal Aerospace
Company
Garrett Ceramic Components
Division
19800 South Van Ness Avenue
Torrance, CA 90509
754. Hiroshi Yokoyama
Hitachi Research Lab
4026 Kuji-Cho
Hitachi-shi Ibaraki 319-12
JAPAN AIR MAIL
755. Thomas M. Yonushonis
Cummins Engine Company, Inc.
P.O. Box 3005
Mail Code 50183
Columbus, IN 47202-3005

756. Thomas J. Yost
Corning, Inc.
Technical Products Division,
Main Plant 21-1-2
Corning, NY 14831
757. Jong Yung
Sundstrand Aviation
Operations
Department 789-6
4747 Harrison Avenue
Rockford, IL 61125
758. A. L. Zadoks
Caterpillar Inc.
Technical Center, Building L
P.O. Box 1875
Peoria, IL 61656-1875
759. Avi Zangvil
University of Illinois
Materials Research Laboratory
104 South Goodwin Avenue
Urbana, IL 61801
760. Charles H. Zenuk
Transtech
6529 East Calle Cavalier
Tucson, AZ 85715
761. Anne Marie Zerega
U.S. Department of Energy
Office of Energy Research,
ER-42
Washington, DC 20585
762. Ken Zillmer
Applied Test Systems, Inc.
2571 Mt. Gallant Road
Rock Hill, SC 29730
763. Carl Zweben
General Electric Company
P.O. Box 8555, VFSC/V4019
Philadelphia, PA 19101
764. Klaus M. Zwilsky
National Research Council
National Materials
Advisory Board
2101 Constitution Avenue
Washington, DC 20418
765. Department of Energy
DOE Field Office, Oak Ridge
Assistant Manager for Energy
Research and Development
P.O. Box 2001
Oak Ridge, TN 37831-8501
- 766-775. Department of Energy
Office of Scientific and
Technical Information
Office of Information
Services
P.O. Box 62
Oak Ridge, TN 37831
- For distribution by microfiche
as shown in DOE/OSTI-4500,
Distribution Category UC-332
(Ceramics/Advanced Materials).

**DATE
FILMED
1 110193**