87
10/3/78

DR. 555

COO-4066-2
PNL-2488
UC-78

MASTER

MASTER

Fuel Performance Improvement Program

Consumers
Power
Company

EXXON NUCLEAR
COMPANY, Inc.

Battelle

Pacific Northwest Laboratory

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency Thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

DISCLAIMER

Portions of this document may be illegible in electronic image products. Images are produced from the best available original document.

NOTICE

This report was prepared as an account of work sponsored by the United States Government. Neither the United States nor the Department of Energy, nor any of their employees, nor any of their contractors, subcontractors, or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness or usefulness of any information, apparatus, product or process disclosed, or represents that its use would not infringe privately owned rights.

The views, opinions and conclusions contained in this report are those of the contractor and do not necessarily represent those of the United States Government or the United States Department of Energy.

Work on this program is performed for the
UNITED STATES DEPARTMENT OF ENERGY
by

CONSUMERS POWER COMPANY and EXXON NUCLEAR COMPANY, INC.

Under Contract EY-76-C-02-4066

and by

PACIFIC NORTHWEST LABORATORY, *Operated by* BATTELLE MEMORIAL INSTITUTE,

Under Contract EY-76-C-06-1830

Printed in the United States of America

Available from

National Technical Information Service

United States Department of Commerce

5285 Port Royal Road

Springfield, Virginia 22151

Price: Printed Copy \$____*; Microfiche \$3.00

*Pages	NTIS Selling Price
001-025	\$4.00
026-050	\$4.50
051-075	\$5.25
076-100	\$6.00
101-125	\$6.50
126-150	\$7.25
151-175	\$8.00
176-200	\$9.00
201-225	\$9.25
226-250	\$9.50
251-275	\$10.75
276-300	\$11.00

FUEL PERFORMANCE IMPROVEMENT PROGRAM

State-of-the-Technology Review of Fuel-Cladding Interaction

W. J. Bailey
C. L. Wilson
L. J. MacGowan
P. J. Pankaskie

December 1977

This report was prepared for the
U.S. Department of Energy by
Pacific Northwest Laboratory, Operated by
Battelle Memorial Institute, under Contract
EY-76-C-06-1830.

Pacific Northwest Laboratory
Richland, Washington 99352

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

CONTENTS

1.0	SUMMARY	1
2.0	INTRODUCTION.	3
3.0	CONCLUSIONS	5
4.0	DISCUSSION	9
4.1	Experience with Power-Ramped Fuel	9
4.2	Fuel-Cladding Mechanical Interaction Precursors	19
4.2.1	Fuel Movement	19
4.2.2	Creep of the Cladding Due to the Coolant System Pressure.	32
4.3	Fuel-Cladding Mechanical Interaction	36
4.3.1	Fuel Pellet Thermal Distortion ("Hourglassing")	37
4.3.2	Ratchetting	40
4.3.3	Strain Concentration Effects at Fuel Interfaces and Cracks.	41
4.3.4	Fuel-Cladding Bonding.	43
4.4	Stress-Corrosion Cracking (SCC) and Cladding Embrittlement	45
4.4.1	SCC Mechanisms	48
4.4.2	Stress	53
4.4.3	Fission Products	55
4.4.4	Cladding Metallurgical State	61
4.4.5	Cladding Embrittlement	61
4.5	Remedial Actions	64
4.5.1	Remedial Actions for Thermal-Mechanical Interactions	64
4.5.2	Remedial Actions for Chemical Reactions	76
4.6	Fuel-Cladding-Interaction Mechanistic Considerations	81
4.6.1	Thermal-Mechanical Interactions	81
4.6.2	Chemical Reaction-Related Considerations	85
4.7	Ongoing Programs	87
4.8	Patents of Interest	91
5.0	REFERENCES	95
6.0	APPENDIX (HYDRIDING)	107

THIS PAGE
WAS INTENTIONALLY
LEFT BLANK

CONVERSION TABLE FOR SI UNITS^(a)

	To convert from	to	Use equation or multiply by
Temperature	degree Fahrenheit (°F)	degree Celsius (°C)	$^{\circ}\text{C} = (^{\circ}\text{F} - 32)/1.8$
	degree Fahrenheit (°F)	kelvin (K)	$\text{K} = (^{\circ}\text{F} + 459.67)/1.8$
	degree Celsius (°C)	kelvin (K)	$\text{K} = ^{\circ}\text{C} + 273.15$
Time	hour (hr)	second (s)	3.600×10^3
	day (d or day)	second (s)	8.640×10^4
Length	inch (in.)	metre (m)	2.540×10^{-2}
Area	inch ² (in. ²)	metre ² (m ²)	6.452×10^{-4}
Volume	inch ³ (in. ³)	metre ³ (m ³)	1.639×10^{-5}
Pound-Mass	lbm	kilogram (kg)	4.536×10^{-1}
Pound-Force	lbf	newton (N)	4.448
Pressure or stress	psi (lbf/in. ²)	pascal (Pa)	6.895×10^3
Energy ^(b)	British thermal unit (Btu)	joule (J)	1.055×10^3
	calorie (cal)	joule (J)	4.187
	watt-second (W-s)	joule (J)	1.000
Linear Heat Rating	kilowatts/ft (kW/ft)	kilowatts/metre (kW/m)	3.281
Burnup	megawatt-day/metric ton of heavy metal ^(c) (MWd/MTM)	gigajoule/kg of heavy metal ^(c) (GJ/kgM)	8.640×10^{-2}

(a) Conversions are based on ASTM Metric Practice Guide E380-74. Four of the prefixes (*) are to be avoided where possible.

Prefix	SI Symbol	Multiplication Factors
tera	T	$1\,000\,000\,000\,000 = 10^{12}$
giga	G	$1\,000\,000\,000 = 10^9$
mega	M	$1\,000\,000 = 10^6$
kilo	k	$1\,000 = 10^3$
hecto*	h	$100 = 10^2$
deka*	da	$10 = 10^1$
deci*	d	$0.1 = 10^{-1}$
centi*	c	$0.01 = 10^{-2}$
milli	m	$0.001 = 10^{-3}$
micro	μ	$0.000\,001 = 10^{-6}$
nano	n	$0.000\,000\,001 = 10^{-9}$
pico	p	$0.000\,000\,000\,001 = 10^{-12}$
femto	f	$0.000\,000\,000\,000\,001 = 10^{-15}$
atto	a	$0.000\,000\,000\,000\,000\,001 = 10^{-18}$

(b) 10^6 Btu = 1.055 GJ = 0.17 barrels of oil = 100 kW-hr, assuming one barrel of oil = 42 gallons and the conversion efficiency from heat to electricity is 0.33.

(c) M is normally the SI symbol for mega; an exception in this report is the additional use of M in burnup units to denote heavy metal.

LIST OF PREVIOUSLY PUBLISHED REPORTS

C00-4066-1	<u>Quarterly Progress Report, April-June 1977, July 1977</u>
C00-4066-3/PNL-2490	<u>Assessment of Fuel Concepts (to be published)</u>
C00-4066-4	<u>Quarterly/Annual Progress Report, April-September 1977, November 1977.</u>

1.0 SUMMARY

The Fuel Performance Improvement Program recently initiated by the Energy Research and Development Administration (now the Department of Energy) has as its objective the identification and demonstration of fuel concepts with improved power-ramp performance. The results of the overall program will be used to establish the technical bases for the design of such fuels. Consumers Power Company, Exxon Nuclear Company, and Battelle, Pacific Northwest Laboratories are the three participants in the program.

The objective of Task 1 under the program is to assess the state of the technology of fuel-cladding interaction and to identify fuel concepts with potential for improved power-ramping capabilities in order to provide direction and technical support for the program scope.

Task 1 consists of two activities. The first activity involved a literature survey and a summarization of postulated fuel-cladding-interaction mechanisms and associated supportive data. The results of that activity are described in this report and include comments on experience with power-ramped fuel, fuel-cladding mechanical interaction, stress-corrosion cracking and fission-product embrittlement, potential remedial actions, fuel-cladding-interaction mechanistic considerations, other ongoing programs, and related patents of interest. The second activity provides an assessment of the candidate fuel concepts to be evaluated as part of this program. The results of the assessment are presented in a separate report, which contains the supportive information and rationale for the selection of the primary fuel concepts to be evaluated in this program.

THIS PAGE
WAS INTENTIONALLY
LEFT BLANK

2.0 INTRODUCTION

Power ramping and the rates at which reactor power level is increased from partial to full power can have an adverse effect on nuclear fuel performance in commercial light water reactors (LWRs). Experience with Zircaloy-clad UO_2 fuels having substantial burnup indicates that a rapid power increase (ramp) may result in failure of the cladding. Such failures are attributed to fuel-cladding interaction and have occurred in boiling water reactors (BWRs), CANDU reactors, and, in some cases, in pressurized water reactors (PWRs). Hence, fuel-cladding interaction appears to be a generic fuel failure mechanism for BWR and PWR Zircaloy-clad UO_2 fuel rods.

The limited power-ramping capabilities of current fuel designs have resulted in fuel-related constraints on the rates at which power-level changes may be made in LWRs. By imposing power-ramping restrictions, fuel reliability has been improved. However, as a result, operational flexibility is reduced and a loss of existing nuclear generating capacity of about 2.5 full-power days is sustained on each startup of a plant. Clearly, there is a need and incentive for a fuel development program to develop improved designs that would ultimately allow a utility to operate a reactor subject to systems-related rather than fuel-related limitations.

Accordingly, the Fuel Performance Improvement Program (FPIP) was initiated by the Energy Research and Development Administration (now the Department of Energy). Consumers Power Company (CPC), Exxon Nuclear Company (ENC), and Battelle, Pacific Northwest Laboratories (PNL) are the three principal participants in the program. This program is directed by Consumers Power Company under prime contract to the Department of Energy. The program is managed by ENC under subcontract to CPC and involves task assignments at PNL and ENC.

The objective of the FPIP is to identify and demonstrate LWR fuel concepts which have the potential for improved power-ramping performance.

The program includes out-of-reactor studies, in-reactor experiments, and in-reactor demonstrations of the selected concepts.

Though many possible concepts appear to exhibit the potential for improved power-ramping capability, from a practical point of view, the number that can be evaluated is limited. The basis for the evaluation and selection of those fuel concepts with potential for improved power-ramping capabilities for evaluation in this program is provided by the Task 1 activities. Task 1 consists of two activities. Included in the first activity were a literature search and a presentation of postulated fuel-cladding interaction mechanisms and the associated supportive data. The results of the effort on this activity are described in this report. The second activity involves the qualitative assessment of the merits of the primary fuel concepts selected for evaluation as part of the FPIP and presents the rationale and supportive information considered in that selection. Results from the second activity are described in a separate report (C00-4066-3/PNL-2490).

This report includes the major results of an earlier study performed by PNL for ENC in 1974. An effort was made in this report to 1) describe mechanisms and associated parameters involved in the fuel-cladding-interaction phenomenon, 2) indicate ongoing programs that are relevant to this program, and 3) concentrate on incorporating information from those areas of the technology that have recently received the most attention [e.g., stress-corrosion cracking (SCC), fission-product embrittlement (FPE) of the cladding, and Zircaloy fracture mechanics]. (a)

Interpretive comments and conclusions by the authors of this report are italicized.

(a) Embrittlement as considered in this report is limited to interactions with certain fission-product species which may embrittle or, by virtue of experimental observations, are known to embrittle the Zircalloys used for fuel cladding. See Section 4.4.5.

3.0 CONCLUSIONS

The Zircaloy cladding on irradiated UO_2 fuel is sometimes breached as a consequence of fuel-cladding interaction when the power is rapidly increased. However, fuel temperature^(a) rather than power is the key variable. The probability for a fuel-cladding-interaction (FCI) defect to occur appears to increase with power, amount of power increase, rate of power increase, dwell time at the high power, and burnup.

For fuel that fails due to fuel-cladding interaction during normal operation, including anticipated transients associated with power ramps, the principal mode of failure appears to be stress-corrosion cracking (SCC). Fuel-cladding interaction in Zircaloy-clad UO_2 fuel rods appears to be a mechanism for failure that is generic to both BWR and PWR fuel. In general, it appears that stress (a mechanical process) and fission-product availability (a chemical process) are reciprocal. It also appears that a pin-hole-type failure may be the result of a high fission-product concentration and a low stress in the cladding, while an axial-split-type cladding failure may be the result of high stress and low fission-product concentration. It is difficult to separate an SCC failure from a purely mechanical failure; however, crack shape and morphology should indicate the relative roles played by the mechanical and chemical processes. If the threshold stress is low, the cracks tend to be straight with the predominant failure mode being transgranular cleavage. If the threshold stress is high, more crack branching and more fracture-surface fluting should be observed.

(a) As indicated by Fuhrman et al. (EPRI NP-218), a fuel temperature increase resulting from a decrease in fuel-cladding heat transfer can be a major contributor to fuel-cladding interaction. *Reducing the temperature within the fuel has the effect of reducing the thermal-mechanical driving force for fuel-cladding interaction, as well as reducing the release of aggressive fission products from the fuel.*

It has not yet been clearly shown experimentally which material parameter --stress, strain, strain rate--most uniquely defines the threshold for SCC. The current data base supports a threshold-stress concept (i.e., a sustained critical tensile stress in a sustained environment of aggressive fission-product species). Some plastic tensile strain is needed for SCC but there is doubt as to whether a critical strain is a prerequisite for SCC. Studies indicate that SCC of Zircaloy is strain-rate dependent; studies on materials other than Zircaloy indicate that SCC occurs within a narrow range of strain rates.

A biaxial-stress state appears to enhance SCC. Evidence indicates that SCC can occur at stresses ranging from close-to-the-yield stress to a fraction ($\sim 1/3$)-of-the-yield stress. Depending on the fission-product species and concentrations, the data suggest that such a threshold range is likely to exist.

Crack nucleation in the Zircaloy cladding is the key step in fuel-cladding interaction failures. Some investigators indicate that once the oxide film on the inner surface of the cladding is fissured, small cracks [$\sim 10 \mu\text{m}$ ($\sim 0.00039 \text{ in.}$)] appear to develop in the metal at preferred sites (e.g., second-phase particles, slip-band intersections, slip-band grain boundary intersections where the orientation is unfavorable for slip across the grain boundary, or combinations thereof). The mechanism for the breakdown of the protective oxide film on the inner surface of the cladding is unknown. A critical stress is required for growth [to $\sim 20 \mu\text{m}$ ($\sim 0.00079 \text{ in.}$)] of the cracks. Once formed, the cracks propagate fairly rapidly, predominantly by transgranular cleavage. If the tensile stress or aggressive fission-product environment is not sustained, propagation of the cracks will proceed at a slower rate (intergranular characteristics are favored in this case) and the crack may arrest. Hence, evaluating intergranular areas at the crack front might be employed as a means of determining whether fuel-cladding-interaction damage is cumulative.

Sensitivity of Zircaloy to embrittlement by fission products and impurities which deposit at the fuel-cladding interface of irradiated LWR fuel rods is generally unknown. The likely aggressive fission-product species of concern are iodine vapor (released from CsI), *cadmium vapor and/or* liquid cadmium, and *cesium vapor and/or* liquid cesium, in that order. Characteristics of the cladding, fuel pellet, and fuel rod that may influence SCC are identified in this report.

At present, the detailed characteristics of the power changes that are normally required of reactors are not sufficiently well known to permit a fundamental understanding of the fuel-cladding-interaction phenomenon. There is also a distinct difference between test reactors and power reactors in the absolute heat rating conditions required to produce comparable power-ramping effects. The operating environments and fuel designs (e.g., length) utilized in the two reactor types are different; however, it has also been postulated that a contributing factor to this difference may be the disturbance of the fuel-cladding interface during manipulation of the fuel rods during the conduct of the irradiations in a test reactor.

Results of the state-of-the-technology evaluation show that the following remedial actions are likely to alleviate the fuel-cladding interaction problem:

- *Eliminate or impede contact and/or condensation of those fission products that promote stress-corrosion cracking (e.g., iodine) or embrittlement (e.g., cadmium and cesium) of the Zircaloy in the fuel-cladding interface region.*
- *Minimize or eliminate stress and/or strain localization in the cladding resulting from pellet/cladding thermal-mechanical interaction. For instance, minimizing the radial temperature gradient in the fuel would have the effect of reducing the thermal-mechanical driving force for fuel-cladding interaction, as well as reducing the release of aggressive fission products from the fuel.*

These results, which pertain to LWR fuel operating in both BWR and PWR environments, were used to establish the criteria employed to select the primary fuel concepts for evaluation as part of this program.

4.0 DISCUSSION

Figure 1 illustrates the sequence involved with a fuel rod as it undergoes normal power operation, fuel-cladding interaction, and cladding breach.

One activity under Task 1 of the Fuel Performance Improvement Program involved a state-of-the-technology review of fuel-cladding interaction and the identification of fuel concepts with the potential for improved power-ramping capabilities in order to provide direction and technical support for the overall program scope. This activity included conducting a literature survey, summarizing postulated fuel-cladding-interaction mechanisms and associated supportive data. The purpose of the activity is to provide a basis for selection of candidate fuel concepts that appear to have potential for improved power-ramping capabilities for evaluation as part of this program. The results of this activity are discussed below and include sections on: experience with power-ramped fuel, fuel-cladding mechanical interaction precursors, fuel-cladding mechanical interaction, stress-corrosion cracking (SCC) and cladding embrittlement, remedial actions, fuel-cladding-interaction mechanistic considerations, ongoing programs (i.e., other current relevant programs in the U.S. and elsewhere), and patents of interest.

4.1 Experience with Power-Ramped Fuel

As noted by Roberts et al.,⁽¹⁾ Ranjan and Smith,⁽²⁾ and Smith et al.,⁽³⁾ experience with Zircaloy-clad UO_2 fuel rods having sufficiently high burnup has shown that a sudden power increase (ramp) can result in failure of the cladding because of fuel-cladding interaction. They indicated that this problem occurs mainly with BWR and CANDU fuel; however, some failures of this type have occurred in PWR fuel. Fuel-cladding-interaction failures in BWRs have been described by Proebstle et al.⁽⁴⁾ and Holzer et al.⁽⁵⁾ CANDU fuel failures have been discussed by Robertson.⁽⁶⁾ It was presumed in the three papers⁽¹⁻³⁾ that this problem is not as extensive in PWRs because the associated power changes are not so abrupt. Fuel failures of this type in PWR fuel have been reported by Boman et al.,⁽⁷⁾

Strasser and Lindquist,⁽⁸⁾ Holzer et al.,⁽⁵⁾ and Knudsen et al.⁽⁹⁾

It thus appears that the fuel-cladding interaction is a failure mechanism generic to fuel employing Zircaloy as a cladding material.

These fuel rod failures have been attributed to fuel-cladding interaction that can be mechanical and/or chemical in nature because results show that such failures can occur with or without the aid of SCC. In the past, the purely mechanical aspects of the fuel-cladding-interaction phenomenon were emphasized. Smith et al.⁽³⁾ indicated that fission-product release during the power ramp also plays a major role and that stress and fission-product availability may be generally reciprocal. Fuel-cladding interaction apparently does not cause fuel rod failures early in life in power reactors; such failures typically occur in fuel rods that are subjected to power increases after they have attained medium to high burnup. As a result, fuel rod modifications to decrease cladding strain early in life may not be effective in the long run in power reactors unless the modifications made can be shown to reduce the probability of fuel failure at higher burnup.

Fuel experience in test reactors and power reactors is discussed below and there is an important distinction: Experiments in test reactors seek to determine failure thresholds--fuel irradiations in power reactors do not.

At the time of the earlier study (1974), it was still uncertain whether the fuel rod failures associated with power increases were of a random or systematic character. Experimental results reported in 1971 by Mogard et al.⁽¹⁰⁾ from irradiation tests in test reactors involving fuel rod power increases indicated that, regardless of other factors, a linear heat-generation rate of ~ 50 kW/m (15.2 kW/ft) was required to produce rod failure. Data from over-power ramp tests reported by Aas et al.,⁽¹¹⁾ in 1973 indicated that it was the increment in power which determined fuel rod failure and not the absolute power. Their experiments showed that the critical power increment is determined

by the last preceding "dominating" linear heat-generation rate. Mogard et al.⁽¹⁰⁾ and Bain et al.⁽¹²⁾ have found evidence that a delay can occur between the power increase and the detection of fuel rod defection. This suggests that a time-dependent mechanism may be involved.

In 1975, Locke⁽¹³⁾ reviewed water reactor fuel performance in power reactors for the 1968-1973 period. He concluded that the local power change which occurs during load following or startup is the main operating parameter causing pellet-cladding interactions. He also indicated that fission products and stress contribute to fuel power ramp failures, but that their relative contributions are unknown.

At Salzburg in May 1977, Mogard et al.⁽¹⁴⁾ described experimental investigations on the power ramp failure propensity of light water reactor fuel. Results from many tests in the R2 reactor indicate that fuel rod failures only occur at significant [~ 20 kW/m (~ 6.1 kW/ft)] ramp-steps above the previously experienced linear heat rating. This means the cladding stress just about approaches the yield stress level at failure because the associated permanent strains are as low as about 0.05%. *The investigators reported that there is a distinct difference between the linear heat ratings required to produce similar power-ramping results from test reactors and from power reactors--even though the failure mechanism is the same.* However, it is difficult to estimate with certainty what the magnitudes of the ramp steps are that the fuel in operating power reactors actually experiences, but it appears that such ramp steps to failure can be quite low and sometimes significantly less than 20 kW/m (6.1 kW/ft). As Mogard et al. point out, Eickelpasch et al.⁽¹⁵⁾ have observed fuel failures as a result of fast power changes of modest magnitudes and Penn et al.⁽¹⁶⁾ have observed fuel failures as a result of very low ramp steps. The fission-product inventory can affect the results (see p. 15). But the most significant data stem from BWR power-ramp tests performed by ASEA-ATOM in Oskarshamn I in 1975, reported by Junkrans and Värnild,⁽¹⁷⁾ which showed fuel failures occurring with ramp steps significantly less than 20 kW/m (6.1 kW/ft). As to the

cause of the large difference, Mogard et al.⁽¹⁴⁾ speculated that it may involve whether or not the in situ, fuel-cladding interfacial condition established during long-term, steady-state irradiation in the power reactor is maintained immediately prior to the power ramp. They felt it is conceivable that handling and transport of the fuel could lead to breaking up, displacing, or mismatching of those interfaces and result in fuel-cladding interactions occurring in ramp tests in test reactors under quite different and less severe frictional conditions. The postulated interfacial effects on ramp results need to be explored further, which is being done in the current Inter-Ramp Project.

In May 1977, Mogard⁽¹⁸⁾ reported that stress-strain analyses supported by a few power-ramp tests at Studsvik, Sweden, show that undulating the inside surface of the Zircaloy cladding suppresses pellet-cladding interaction induced defects. Such cladding may have 30 regular longitudinal undulations about 20 μm (0.00079 in.) high introduced around the bore circumference. Mogard stated that there are three main defect-initiation mechanisms that occur consecutively during a normal, fast power increase. The first occurs while the cladding stress is still in the elastic range and is associated with static friction or bonding between the pellet and cladding. Cracks nucleate as asperities are sheared off. Stresses will relax slowly because the stresses are in the elastic range. This provides time for SCC to occur. The second mechanism concerns plastic cladding strain that rapidly leads to cladding failure. The third mechanism involves the cladding stretching or bending that occurs when pellet chips are located between the pellet and cladding. Under normal reactor operation the first mechanism is of primary concern.

According to Bain et al.⁽¹²⁾ fuel integrity may be critically affected by increasing the linear heat-generation rate of the fuel rod above some prior steady operating level (e.g., by shuffling fuel or by manipulating control rods or blades). Cherry et al.⁽¹⁹⁾ reported that pellet-cladding interaction fuel failures in BWRs are caused

by power increases associated with control-blade movements that occur in discrete, rather coarse jumps. Multer⁽²⁰⁾ reported that large power increases can also occur in PWRs because of control-rod movements, even in a PWR that uses moderator poison for fine control. Cherry et al.⁽¹⁹⁾ also found that of the fuel bundles irradiated in the United States prior to 1975, 10-20% defected. A large fraction of those defects were known to occur predominantly at corner positions near cruciform control rods (maximum power changes of up to 50% can occur on insertion and withdrawal). Holzer et al.⁽⁵⁾ pointed out that some new BWR plants have control-rod drive mechanisms that permit smaller single steps. In situ power ramps associated with control-rod movements in some PWRs can cover a wide range of power-ramp rates with maximums up to 10 kW/m-min (3 kW/ft-min) locally; ramp rates of only about 0.02 kW/m-min (0.006 kW/ft-min) may be caused by xenon oscillations.

A recent paper by Cordall et al.⁽²¹⁾ indicated that Dodewaard fuel failures were a consequence of power ramping [mean burnup of the fuel assemblies was 1285 GJ/kgU (14,870 MWd/MTU)^(a)]. Repatterning of the control-blade movements in this BWR caused local power increases of between 20 and 150% at the failure location. A nonpenetrating crack that was undetected by eddy-current testing was located in the nonfailed Dodewaard fuel rod that underwent the largest power increase. The characteristics of that crack were the same as those in the failed fuel rods. Cordall et al. pointed out that the maximum rate of power change experienced by a fuel pellet, because of control-blade movements, was ~ 3 kW/m-s (~ 0.91 kW/ft-s). This is because the pellet power change is limited by the fuel-time constant rather than the blade-movement rate. The investigators also noted that two Dodewaard fuel assemblies were in symmetrical positions in the core and should have undergone similar power increases, yet fuel rods failed near the control-blade corner in one but not the other. Calculational studies to investigate the differences in failed pin location between the nominally identical fuel

(a) MWd/MTU = megawatt-days/metric ton of uranium

assemblies to establish the sensitivity to operating conditions and small perturbations in fuel dimensions were suggested but not performed by Cordall et al. Similar power upratings made in 1972 led to fuel failures but neither reactor operating histories nor postirradiation examination results could determine which series of control-blade movements caused the fuel failures.

Davies et al.⁽²²⁾ have described in-reactor tests that were aimed at determining the pellet-cladding-interaction mechanism in BWR fuel rods. Average power-ramp rates for the fuel rods were 16-69 kW/m-hr (4.9-21.0 kW/ft-hr) and maximum ramp rates were 77.8-571 kW/m-hr (23.7-174 kW/ft-hr). The main variables leading to failure were power increase, peak power after the increase, and exposure. Tests were performed using combinations of irradiated and nonirradiated fuel and cladding. These tests showed that loss in cladding ductility due to irradiation was not sufficient to cause failure on a power increase. Apparently fission products were the primary exposure-dependent variable. Also, susceptibility to failure is not a strong function of conventional design variables (e.g., cladding thickness).

Wood and Hardy⁽²³⁾ recently analyzed in-reactor and laboratory test results to suggest mechanisms by which UO_2 fuel rods with Zircaloy or Zr-2.5% Nb alloy cladding fail when subjected to a power ramp. They indicate that for a given change in power, the defect probability decreases with faster power changes suggesting two defect mechanisms: 1) rapid mechanical rupture due to metal-substrate straining (corresponding to rapid power increases), and 2) time-dependent, stress-assisted, fission-product-induced attack at points of ZrO_2 weakness (i.e., over intermetallic precipitates). *High strain rates tend to result in an effective strengthening of the cladding. At operating temperatures and fluxes, low strain rates tend to promote cladding straining by thermal- and neutron- (fast flux) activated creep as well as provide the opportunity for iodine-induced, stress-corrosion cracking.* Wood and Hardy also stated that a power-ramp defect,

fuel-burnup threshold exists. A threshold power exists that is closely related to fission-product concentration and a threshold stress exists that is related to the power increase. Moisture was found to be a defect inhibitor.

Extensive data on Canadian fuel performance were analyzed by Penn et al.⁽¹⁶⁾ They concluded that the majority of fuel-cladding defects occurred due to a power ramp for two reasons. One reason was SCC due to fission products, i.e., iodine. (There was a time delay after the power ramp before fuel rod failure in this case.) The second reason was mechanical overloading of irradiation-embrittled cladding subjected to tensile stresses and strain concentrations during the power ramp. (In this case fuel rod failure occurred within a few minutes of the power ramp.) The CANDU fuel uses UO_2 pellets and nonfreestanding Zircaloy cladding; this fuel is more susceptible to power-ramp failure after burnups of 108-144 GJ/kgU (30-40 MWhr/kgU or 1250-1670 MWd/MTU). The investigators note that fission-product release from the cladding to the coolant is dependent on the final ramped power, the power change, the fuel burnup and the time at final power. Fuelograms were generated showing the probabilities of failure as a function of power change, power level, burnup and time at power. The analysis was limited to burnups of 144-864 GJ/kgU (40-240 MWhr/kgU or 1670-10,000 MWd/MTU), dwell times of 0.3 to about 2000 hr, fuel rod powers of 34-60 kW/m (10-18 kW/ft), and changes in fuel rod powers of 9-50 kW/m (2.7-15 kW/ft).

From the large quantity of fuel-performance data obtained from CANDU reactors during the 1970-1975 period, J. C. Wood of AECL indicated that it is clear that fuel defection does not occur under certain conditions. These conditions are: 1) when the fuel is irradiated at constant power or steadily decreasing power [it has been demonstrated many times that fuel can be satisfactorily irradiated to burnups over 864 GJ/kgU (240 MWhr/kgU or 10,000 MWd/MTU) at ratings to 70 kW/m (21 kW/ft), provided power changes (ripples) are no more than 5-10% of previously experienced power levels], 2) when the fuel is ramped

to a power level less than a threshold value of 31 kW/m (9.4 kW/ft), and 3) when the fuel is ramped in power to the same linear heat-generation rate previously experienced or to lower rate after a reactor trip or a burnup up to 108 GJ/kgU (30 MWhr/kgU) at a lower linear heat generation rate.

Wood and Hardy⁽²³⁾ noted that a General Electric Company spokesman indicated that LWR fuel could be ramped safely if the ramp rates were less than 0.9 W/m-sec (0.1 kW/ft-hr).

If the cladding is insufficiently free-standing at operating temperatures, fatigue-type loadings can be imposed on the cladding by the cycle of tensile strain followed by reduction in cladding diameter, according to Lustman.⁽²⁴⁾ Although fuel rod-failures in power reactors have not been attributed to fatigue, failures of that type may become of more concern when greater numbers of fuel rods are involved in load-following reactors. The thicker the cladding, the less likely fatigue loadings will occur.⁽²⁴⁾ However, the effect of irradiation on the cladding properties has to be considered. Aas⁽²⁵⁾ has noted that failure by strain fatigue is of particular concern with PWR fuel rods. *Fracture studies on many metal alloys clearly show that fatigue enhances the propensity for SCC and SCC rates.*

"Power Shock Failure" is the name assigned by Scandpower to the pellet-cladding interaction mechanism which has been responsible for a majority of fuel failures. The Scandpower brochure⁽²⁶⁾ indicates that longitudinal cracks are produced by cladding strain arising from thermal expansion and shape distortion of fuel pellets when they are subjected to rapid increases (power shocks) above previous powers.

"Bamboo ridges" in the cladding are caused by the "hourglass" deformation of fuel pellets under power and lead to axial localization of strain at pellet joints. As a result, cracks form at the intersections between bamboo ridges and hoop strain concentrations. It is also thought that aggressive fission products might accelerate the cracking. Since the regions of highest strain and the most aggressive corrosion coincide

in location, Scandpower states that it is difficult to determine the cause (i.e., it is hard to separate an SCC failure from pure mechanical failure). There is a pertinent question: Does the strain (and/or "prestrain") associated with ridging promote SCC failure, or is failure at ridges enhanced because the pellet-pellet interface functions effectively to release iodine and other objectional fission products and, together with radial pellet cracking at the pellet-pellet interface, tend to concentrate fission products at this location?⁽²⁷⁾

Wood⁽²⁸⁾ has described studies that were conducted to show the similarities between iodine-induced SCC and the ramping defects. (See Section 4.4.)

Aas⁽²⁵⁾ has noted evidence that axial cladding strains can be substantially lowered if the linear heat-generation rate is raised slowly enough so that plastic flow of the fuel can occur and cladding stresses can be relaxed. However, complete relaxation of cladding stresses will not occur. Cladding stresses can be partially relieved by fuel pellet deformation, according to Lustman.⁽²⁴⁾ Wood,⁽²⁹⁾ Aas,⁽²⁵⁾ Kjaerheim and Rolstad⁽³⁰⁾ have found that the force system, which compresses the fuel column and stretches the cladding, apparently causes the fuel column to deform plastically. A recent study by Gittus⁽³¹⁾ indicates that stress relaxation is time-dependent and is the main reason for more fuel-rod failures at higher power-increase rates.

Failed experimental encapsulated mixed-oxide fuel rods ($\text{UO}_2\text{-PuO}_2$ fuel in stainless-steel cladding) recently discovered in the EBR II have been analyzed by Patel and Murata.⁽³²⁾ The principal cause of failure was concluded to be fuel-cladding mechanical interaction due to differential thermal expansion during a power increase (the power increases ranged from approximately 23% to 135% for the observed failure regions in the rods analyzed). The analysis indicated that the extent of damage due to the change in power is dependent on the operating temperature and the magnitude of the temperature change. For the

power changes considered, the analysis shows that rods operating at high temperatures are liable to fail at the top by thermal creep deformation while rods operating at lower temperatures are liable to fail at the bottom by plastic deformation.

4.2 Fuel-Cladding Mechanical Interaction Precursors

Before fuel-cladding mechanical interaction (Figure 2) can occur, the fuel must radially relocate so as to contact the cladding and/or the cladding contract to contact the fuel. Factors contributing to fuel and cladding movement are described in Sections 4.2.1 and 4.2.2.

4.2.1 Fuel Movement

Five major mechanisms affect fuel-pellet movement (radial relocation or expansion): thermal expansion, cracking, swelling, creep, and densification. These mechanisms are discussed in the following sections.

4.2.1.1 Fuel Thermal Expansion

As the fuel rod heats up, the thermal expansion of the fuel pellet tends to close the fuel-cladding gap. Aas⁽²⁵⁾ pointed out that the coefficient of thermal expansion of UO_2 is greater than that of Zircaloy; the respective coefficients are approximately $11 \times 10^{-6} \text{ } ^\circ\text{C}^{-1}$ ($6.1 \times 10^{-6} \text{ } ^\circ\text{F}^{-1}$) and $6.2 \times 10^{-6} \text{ } ^\circ\text{C}^{-1}$ ($3.4 \times 10^{-6} \text{ } ^\circ\text{F}^{-1}$). Also, the UO_2 fuel pellet is at a considerably higher temperature than the Zircaloy cladding.

Lustman⁽²⁴⁾ stated that when the oxide fuel pellet (in the uncracked, as-fabricated state) is first brought to power, the pellet expands at a rate that is controlled by the volume-averaged temperature. When pellet radial cracking occurs, the pellet expansion then becomes controlled by the integrated linear

FIGURE 2. Fuel Rod Interactions and, in Particular, Phenomena* Principally Involved with Fuel-Cladding Mechanical Interactions

temperature between the pellet center and surface. As a result, the thermal expansion of the pellet in the radial direction has been noted to increase by as much as 30%.⁽²⁴⁾

Aas⁽²⁵⁾ noted that thermal expansion of the fuel can result in uniform circumferential plastic deformation of the cladding. However, Lyons et al.⁽³³⁾ indicate that the temperature distribution within the pellet and external restraints influence the uniform radial expansion of the pellet. Kjaerheim and Rolstad⁽³⁰⁾ reported that the elongation of flat-ended pellet fuel is governed by the central fuel temperature while that of packed-particle fuel is more dependent on the average fuel temperature. In estimating plastic circumferential deformation of the cladding, it is particularly difficult to determine fuel expansion. This difficulty is due to the temperature gradient and the associated variation in fuel plasticity across the fuel cross-section. Because diametral and longitudinal expansions are interdependent, plastic deformation predictions should be verified by experiment.

Lowering fuel temperatures within the fuel reduces the thermal expansion and therefore the thermal-mechanical driving force for fuel-cladding interaction.

4.2.1.2 Fuel Cracking

Radial relocation of cracked fuel is believed to be one of the two dominant factors associated with closure of the fuel-cladding gap, according to Hann et al.;⁽³⁴⁾ the other dominant factor is fuel swelling. Roberts and Wrona⁽³⁵⁾ indicated that fuel cracking will influence the mechanical interaction

of the fuel and cladding and the fuel fission gas release behavior (cracking increases fuel surface area).

Kjaerheim and Rolstad⁽³⁰⁾ pointed out that pellet cracking is a function of pellet properties (e.g., strength, creep, surface flaws, impurities, and fabricated porosity), fuel temperature and temperature gradient, and stress conditions; thus, the amount of tensile stress the pellet can sustain is not known. Roberts and Wrona⁽³⁵⁾ have noted that fissioning may also affect the fracture process.

According to Robertson et al.,⁽³⁶⁾ most of the cracks in the outer portion of the pellet are formed during the initial startup and cracks in the grain-growth regions occur during the last shutdown. However, the analysis of Guha et al.⁽³⁷⁾ apparently showed that circumferential cracks in the pellets develop during heating rather than during cooling as commonly assumed. Experiments, noted by Robertson et al.,⁽³⁶⁾ show that on reirradiation, the outer annulus of the pellet does not undergo further cracking even at significantly higher power.

Hoppe and Verbeek⁽³⁸⁾ have reported that fuel pellets normally crack under the thermal stresses encountered in power reactors due to nonuniform thermal expansion. As noted by Lustman,⁽²⁴⁾ Robertson et al.,⁽³⁶⁾ Belle,⁽³⁹⁾ and Notley et al.,⁽⁴⁰⁾ pellets have been shown by calculation and experimentation to crack when subjected to a temperature differential of 80°C (144°F) when the fuel surface temperature is 20°C (68°F), or a differential of 150°C (270°F) when the fuel surface temperature is 800°C (1470°F). Roberts and Wrona⁽³⁵⁾ have stated that in order for

cracking to occur: a) the principal stresses in the fuel must be tensile and equal to or greater than the fracture stress, and b) the temperature of a particular zone boundary in the fuel must be equal to or less than T_c , which is the brittle-to-ductile transition temperature. It has been indicated that once a crack starts, it is very difficult to stop and that present computer models with distributed cracks in the pellet do not follow the fracture process. Pellet cracking can also be a consequence of handling and shipping of the fuel element. However, the cracking caused by this means is infrequent and unpredictable. Chubb et al.⁽⁴¹⁾ have found that in order for cracks to be effective as distributed voidage and in reducing cladding-stress concentrations, the cracks have to be wide enough so they are not easily healed. The cracked fuel segments must be small enough so that they do not localize stresses in the cladding. Robertson et al.⁽³⁶⁾ have noted evidence that fuel cracks heal within a radius which is slightly greater than that for just-discernable grain growth. According to Lyons et al.,⁽³³⁾ temperature, fission sintering, hot pressing, and plasticity influence crack healing.

It might be possible to promote fuel cracking (and, in turn, reduce stress concentrations in the cladding) by weakening the pellet through control of the iron content. Roberts and Wrona⁽³⁵⁾ have suggested that another approach would be to optimize the fuel-pellet microstructure to control crack propagation, an important characteristic of the fuel. Results reported by Coleman⁽⁴²⁾ from out-of-reactor tests indicate that one needs at least a certain number

(e.g., 16) of radial cracks in the fuel to alleviate stress concentrations in the cladding. It appears desirable to form at least this minimum number of effective radial cracks in the fuel on the initial startup.

Chubb et al.⁽⁴¹⁾ have found that cracking of the fuel can influence the external swelling rate. Evidence exists that the external behavior of the fuel is altered if the crack width changes by orders of magnitude [i.e., from a hairline crack 1 μm (3.9×10^{-5} in.) wide to a slit 500 μm (0.020 in.) wide]. There is also evidence from Hargreaves and Collins⁽⁴³⁾ that during the time it takes a crack to heal, the crack can support no compressive stress across it because crack healing occurs at fuel temperatures high enough for rapid fuel creep; hence, local swelling in the vicinity of the crack cannot be transmitted to the cladding to produce external swelling and cladding strain.

A small number of cracks appear less desirable than either no cracks or a substantial number of cracks.

4.2.1.3 Fuel Swelling

Fuel swelling occurs when fission products are formed. Aas⁽²⁵⁾ and Lyons et al.⁽³³⁾ have reported that fuel swelling is generally a function of burnup, fission rate, temperature, and temperature gradient. Of the factors (besides the rate of fission gas atom generation) that influence the rate of fission-gas (xenon, krypton) swelling, the fuel temperature is the most important. Chubb et al.⁽⁴¹⁾ have noted that fission gas swelling occurs in UO_2 at $\sim 1100^\circ\text{C}$ ($\sim 2010^\circ\text{F}$).

Lyons et al.⁽³³⁾ indicated that included among the other factors are: temperature gradient, burnup, bubble size, pore-closure rate, fission-gas release, stoichiometry, neutron flux, and stress. Gas bubbles migrating to and growing on grain boundaries have been considered by Chubb et al.⁽⁴¹⁾ to be a major source of fuel swelling in the equiaxed grain region. According to Hargreaves and Collins,⁽⁴³⁾ at ~ 1000 - 1600°C (1830 - 2910°F) equiaxed grain growth occurs, as has been shown by metallographic examination, and grain boundaries become nucleation sites or collection sites after migration of gas bubbles with diameters in the range of a few tenths of a μm to $\sim 5 \mu\text{m}$ ($\sim 2 \times 10^{-4}$ in.). Only small [~ 50 - μm (0.0020 -in.) diameter] bubbles are detected within the grain boundaries. Columnar grain growth caused by migration of lenticular-shaped pores up the temperature gradient occurs at temperatures greater than 1600°C (2910°F).⁽⁴³⁾ Lyons et al.⁽³³⁾ also indicated that the parameters which influence solid fission-product swelling include: fuel temperature, burnup, chemical (oxidation) state of the fission product, fission rate, stoichiometry, plasticity, atomic volume, vacancy availability, and pore-closure rate. Regarding the fission rate, Harrison and Davies⁽⁴⁴⁾ found that cesium formation is affected by neutron flux and low flux results in more swelling. Aas et al.⁽¹¹⁾ have also noted evidence that UO_2 can swell almost instantly when the power level is increased.

Fuel swelling is also influenced by fuel strength. Although temperature has a primary effect on fuel strength, there are other factors that affect fuel strength. Chubb et al.⁽⁴¹⁾ have described some of

these factors (grain size, distributed voidage and basic refractory nature) in their paper on swelling of irradiated fuel where cladding surface temperatures were very high, i.e., 1000 to 1900°C (1830 to 3450°F); in conventional fuel the value is less than 350°C (660°F). Reduction in fuel strength because of distributed voidage may increase or decrease the fuel swelling rate. Fuel strength is closely related to the basic refractory nature of the fuel, which can be altered by alloying. However, this technique involves many hazards. Diluents (the common ones are poisons, voids, and conductive metals and ceramics) are a special type of alloying agent, are essentially not soluble in the basic fuel, and are added to modify reactivity (e.g., lowering fission density reduces the local concentration of fission gas), thermal conductivity, or strength.

Aas⁽²⁵⁾ indicated that fuel swelling is hardly appreciable below burnups of 1730 GJ/kgM (20,000 MWd/MTM).^(a) Above that burnup, the fuel radial expansion is about 0.2% per 1730 GJ/kgM (20,000 MWd/MTM).

One fuel configuration exhibited zero swelling at a burnup of 1.7×10^{20} fissions/cm³ or about 500 GJ/kgU. As noted by Chubb et al.,⁽⁴¹⁾ an essential part of this experiment was the restraint of the enriched hot weak annular fuel by the surrounding cold annulus of depleted fuel.

With fuel at elevated temperature, fission-gas release occurs by bubble migration. Hence, according to

(a) kgM = kilogram of heavy metal; MTM = metric ton of heavy metal.

Lustman,⁽²⁴⁾ at a temperature that is dependent on the specific properties of the fuel and the burnup, fission-gas swelling is no longer important and only solid fission-product swelling needs to be taken into account. Hargreaves and Collins⁽⁴³⁾ have reported that at lower temperatures the gas is transported to the grain boundaries by diffusion.

Below $\sim 1000^{\circ}\text{C}$ ($\sim 1830^{\circ}\text{F}$), the influence of fission-product gas on swelling is small and the swelling is caused by only solid fission products (rate is ~ 1 vol% per atom percent burnup).

Frost⁽⁴⁵⁾ reported that solid fission-product swelling would be negligible if one could induce the cesium and rubidium to be expelled from the fuel. Lyons et al.⁽³³⁾ noted that compound formation could also lead to a substantial reduction in the solid fission-product swelling. They also pointed out that solid fission-product swelling may be sensitive to changes in the fuel stoichiometry.

It is generally undesirable to weaken the fuel. In some cases, strengthening the cladding and/or weakening the fuel can improve the external dimensional stability of a fuel rod according to Chubb et al.⁽⁴¹⁾

Fuel swelling is not appreciable until a substantial burnup has been attained (see comment by Aas, above). Fuel swelling could be reduced by expelling the gaseous fission products from the fuel, by expelling certain solid fission products from the fuel or having them form compounds, or by altering the radial temperature profile in the fuel.

4.2.1.4 Fuel Creep

Homan⁽⁴⁶⁾ noted that reducing the uncertainty in fuel creep data is an important factor in calculating the extent of fuel-cladding mechanical interaction. Seltzer et al.⁽⁴⁷⁾ have reported evidence that at low stresses the steady-state creep rate is directly proportional to the applied stress, σ , while at high stresses the creep rate is directly proportional to the applied stress raised to a power ranging from four to five. This study also pointed out one area in which information is lacking. This area is the effect of porosity on creep rates, both in low-stress and high-stress creep regions. The study also indicated that stoichiometry will be the dominant factor regulating creep.

Armstrong and Irvine⁽⁴⁸⁾ studied the effects of adding CaO , Y_2O_3 , ZrO_2 , and SiO_2 to urania-base solid solutions. While the first three depressed the creep rate, SiO_2 enhanced it because of the second phase at the grain boundaries.

In a theoretical study by Singh,⁽⁴⁹⁾ the effects of fission-induced impurities on the creep behavior of mixed-oxide fuel were assessed. Discussed in the report were the effects of fission products on important physical properties of the materials (e.g., diffusion and dislocation motion). The relationship of those properties to creep were then described in terms of the generation of both localized lattice strain and lattice defects and the physical state and location of fission-product clusters.

In fuel-cladding mechanical interaction computations, it is important to reduce the fuel creep data uncertainties (see comment by Homan, above). Both additions to the fuel and fission-product forms can either increase or decrease the creep rate.

4.2.1.5 Fuel Densification

Chubb et al.⁽⁴¹⁾ have stated that in-reactor sintering (densification) may, or may not, be harmful, depending on the amount of shrinkage that results.

Opening of the fuel-cladding gap could ease the mechanical interaction problem, but cause other problems (e.g., increases in fuel temperatures). Densification is a potential cause of increased fuel-cladding gap and may be the result of a combination of the following mechanisms: 1) irradiation-induced sintering due to porosity annihilation, 2) thermal sintering, and 3) pellet-cladding interaction due to irradiation-enhanced and/or -induced creep.

In a recent PNL study by Freshley et al.⁽⁵⁰⁾ on irradiation-induced densification of sintered pellets, the largest changes in density occurred in pellets characterized by a combination of small grain and pore sizes and low initial density. Fuels prone to densification that were irradiated at fuel temperatures $>910^{\circ}\text{C}$ ($>1670^{\circ}\text{F}$) densified rapidly; the associated linear heat-generation rate was 20.7 kW/m (6.31 kW/ft). Some fuels approached their maximum density at burnups as low as 86 GJ/kgM (1000 MWd/MTM). Maximum densities as high as 97.8% TD were reached and increases in density of over 7% TD were observed. Densification occurred more slowly at temperatures $<710^{\circ}\text{C}$ ($<1310^{\circ}\text{F}$); the

associated linear heat-generation rate was 11.6 kW/m (3.54 kW/ft). Irradiation did not increase the grain size. The volume fraction of pores that were initially 1-10 μm (4×10^{-5} - 3.9×10^{-4} in.) in diameter first increased and then decreased. Pellets with large grain size and/or an average pore diameter greater than 1 μm (4×10^{-5} in.) were stable under irradiation. However, some fuel types with smaller grain and pore size characteristics were also stable. Prepressurization with helium (under conditions which were typical of those in current PWR fuel rods) was found in the PNL study to have no effect on densification.

In 1973, Hann et al.⁽³⁴⁾ found little evidence in the literature that irradiation-induced densification of the fuel actually produces a larger fuel-cladding diametral gap. The investigators also noted that few, if any, failures had been attributed to fuel densification.

Fuhrman⁽⁵¹⁾ reported that some fuel recently irradiated in Maine Yankee Core 1 densified from 2.5 to 5.5% TD. Densification and fission-gas release are temperature dependent; in this case, fuel rods exhibiting low releases of fission gas had 1.5% TD lower densification than those rods with high releases of fission gas. The pellets with low initial density densified to a greater degree. Postirradiation examination results showed that equiaxed grain growth, an indication of higher operating temperatures, was found only in the UO_2 in the higher gas release fuel rods. This densification is thought to have caused an increase in the pellet-cladding gap, a decrease

in the heat transfer across the gap, and thus an increase in fuel temperature and enhanced grain growth.

In the spring of 1972, fuel densification led to the formation of large axial gaps in the fuel columns of Ginna fuel and resulted in flattening of the cladding because of cladding creep, as reported by Jordan.⁽⁵²⁾ Subsequent fuel designs employed higher density fuel (95% TD) that was less prone to densification than previous fuel designs (90% TD). Flattening of fuel-rod cladding has also been observed at several other reactors, including: Beznau-1, Mihama-1, Point Beach-1, and Robinson-2. Corrective action includes increasing the fuel density, increasing the principal sintering temperatures for pellets above 1700°C (3100°F), and increasing the level of prepressurization.

Locke⁽¹³⁾ has reviewed the 1968-1973 experience with water reactor fuels. A discussion of densification is included in his paper.

Meyer⁽⁵³⁾ has described a new Nuclear Regulatory Commission (NRC) densification model that has been developed. The model is based on a 1700°C (3100°F), 24-hr resintering anneal and a noninstantaneous kinetics expression derived from Halden data. Isotropy assumptions of the prior AEC densification model, as noted by the USAEC Regulatory Staff,⁽⁵⁴⁾ are retained in the new NRC model; however, the assumption of 96.5% TD (geometric) as a maximum density for all fuel types is no longer recommended.

It is important to have a stable fuel, i.e., one that does not undergo densification to a significant extent during irradiation causing possible enlargement

of the fuel-cladding gap and a reduction in heat transfer across the gap.

4.2.2 Creep of the Cladding Due to the Coolant System Pressure

The two principal factors involved in cladding creep are the creep properties of the cladding and the pressure differential across the cladding. The latter involves the difference between the primary coolant-system pressure [typically 15.5 MPa (2250 psi) for a PWR and 6.9 MPa (1000 psi) for a BWR] and the fuel rod internal pressure. Hann et al.⁽³⁴⁾ have reported that cladding creep, fuel radial relocation, and fuel swelling are the mechanisms that have the greatest effects on gap closure; however, as previously indicated, the latter two are the dominant factors. The trend of cladding creep is known, but uncertainties (e.g., in initial ovality, temperature, axial power profile) still exist in the data. Cladding creep typically accounts for a maximum decrease in cladding inside diameter of about 0.050 to 0.125 mm (0.002 to 0.005 in.) with unpressurized fuel rods which initially had imperfectly round cladding. [This would be equivalent to a uniform diameter decrease of roughly 0.025 mm (0.001 in.) for round cladding.] The major factors associated with cladding-creep properties and the fuel rod internal pressure are described in the following subsections.

4.2.2.1 Cladding Creep Properties

Creep is defined as the strain induced under constant stress as a function of time. Irradiation influences the creep rate of Zircaloy cladding. According to Pickman,⁽⁵⁵⁾ irradiation generally produces the following effects: 1) the creep rate is increased significantly, often by an order of magnitude, 2) the secondary creep rate tends to be more nearly constant than is the case with unirradiated Zircaloy,

and 3) the creep under irradiation tends to lack a well-defined tertiary stage, yet in spite of this, the rupture ductility tends to be rather large. (This depends somewhat on the creep rate.) It is not known in detail why the creep rate is increased under irradiation. However, the high ductility is certainly caused by the low stress sensitivity which applies to the range of stresses occurring in fuel rod cladding due to coolant pressures.⁽⁵⁵⁾

Cladding creep is of more concern in a PWR fuel rod than in a BWR fuel rod. Aas⁽²⁵⁾ noted that if the creep strength of PWR fuel rod cladding is inadequate to prevent collapse, then prepressurization becomes mandatory.

Lustman⁽²⁴⁾ indicated that since the plastic strains of interest are in the range of less than 1%, primary creep, rather than secondary creep, is important. Little relevant in-reactor or out-of-reactor data on Zircaloy primary creep exist. Pankaskie⁽⁵⁶⁾ has recently reviewed the irradiation effects on the mechanical properties of zirconium and dilute zirconium alloys and has included a discussion of creep and an indication of the small amount of available data on primary creep. Pankaskie⁽⁵⁶⁾ and Fidleris⁽⁵⁷⁾ have reported that, in general, with annealed zirconium and dilute zirconium alloys, the primary creep strains tend to decrease with increasing fast flux intensity, whereas, in cold-worked materials, the fast flux intensity has little or no effect. *Improved zirconium alloys with superior in-reactor creep strengths (e.g., Zr-1% Nb or Zr-2.5% Nb) would be expected to reduce cladding strain and,*

possibly, the propensity for SCC and/or FPE.

However, it has been suggested that increased creep strength may not be desirable because it may result in less creep reduction of stresses over a pellet crack or a pellet interface.

4.2.2.2 Fuel Rod Internal Pressure

One factor affecting the fuel-cladding contact pressure is the net pressure differential. For a given external pressure, an increase in the fuel rod internal pressure reduces the fuel-cladding contact pressure and, in turn, the fuel-cladding mechanical interaction. The net pressure differential on the cladding can vary over a wide range during the lifetime of a fuel rod [e.g., from about 13.8 MPa (2000 psi) inward to nearly zero]. Sources of gases to produce the internal pressure include: fission-gas release (a function of fuel temperature), release of volatile impurities from the fuel, and the initial backfill gas. As noted by Lyons et al.,⁽³³⁾ fuel rods release most of the fission gas discontinuously. The release tends to occur during changes in power (primarily when power is decreased); the gas pressure also tends to decrease slightly during operation at constant power. The fuel surface area is found to be the primary control on fission-gas release at temperatures up to 1500°C (2730°F).⁽³³⁾ The recent study by Hann et al.⁽³⁴⁾ indicated that the bulk of the fission-gas release data for thermal-reactor

fuel suggests that 100% release of the fission gases occurs above a temperature of 1600 to 1700°C (2910-3090°F). For the range of burnups applicable to LWRs, the effect of burnup on fission-gas release is masked by other factors (e.g., uncertainties in densities, temperatures, etc.).⁽³³⁾ A recent study indicated no discernible effect of burnup on fission-gas release for burnups below about 3100 GJ/kgU (15,000 MWd/MTM). Because of temperature and burnup, the fuel surface area increases during extended irradiation which results in increased fission-gas release rates.⁽³³⁾ Fuel swelling due to gaseous fission products precedes any significant amount of gas release, according to Chubb et al.⁽⁴¹⁾

According to Hann et al.,⁽³⁴⁾ release of volatile impurities presents several problems: 1) the release can significantly affect calculated fuel temperatures, 2) uncertainties in gas content, composition, and release rates can be encountered, 3) after release, the disposition of the gases is poorly understood, and 4) some of the gases (hydrogen, oxygen, water vapor, CO, and CO₂) probably react with the fuel or cladding, while nitrogen, argon, and some hydrogen mix with the fill gas (usually helium).

A KWU study by Holzer et al.⁽⁵⁾ found that prepressurized fuel rods show less propensity for fuel-cladding-interaction

defects than nonprepressurized fuel rods under comparable conditions.

It was concluded from Section 4.2.2 that
1) changing the creep strength of the
cladding may or may not be beneficial, and
2) prepressurization appears to help in
reducing fuel-cladding interaction.

4.3 Fuel-Cladding Mechanical Interaction

Once fuel and/or cladding movement, as described in Section 4.2 and shown in Figures 1 and 2, results in fuel-cladding contact or interaction, differential expansion (interference) strains can result. This interference can also produce strain concentrations because of pellet thermal distortion ("hourglassing" can lead to cladding ridging), ratchetting, fuel cracks, fuel-cladding bonding, or fuel chips between the fuel and cladding.

The differential expansion strain produced by the interaction of the fuel with the cladding occurs because the fuel expands more than the cladding; as noted by Aas,⁽²⁵⁾ the fuel is hotter, it cracks, and it swells. Fuel-cladding mechanical interaction apparently does not result in fuel-rod failure early in life. Such failures occur with power increases after intermediate or high burnup.

The configuration of the pellet end can lead to cocking of the pellet in the cladding. Chernock and Stewart⁽⁵⁸⁾ have reported that out-of-reactor tests to study the effect of pellet end-face perpendicularity on loading resistance show that pellets with nonperpendicular ends can result in mechanical interaction forces that can produce cladding axial growth.

It is uncertain when fuel-rod deformation takes place; as pointed out by Aas,⁽²⁵⁾ this makes it very difficult to develop a truly quantitative understanding of the effects and their relationships. Kjaerheim

and Rolstad⁽³⁰⁾ have reported evidence that suggests that as the fuel rod heats up, the onset of the gradual deviation of measured cladding elongation from predicted values is probably due to cladding ovality, fuel cracking, or small fuel particles wedged between the fuel and cladding surfaces.⁽³⁰⁾ Aas⁽²⁵⁾ noted evidence that the effect of the initial diametral gap may disappear. (With time a fuel pellet adjusts itself to the cladding and fills up the gap.) He also indicated that this may not necessarily cause additional strain. (Fuel expansion may be accommodated by a center hole in the fuel or by the increased void volume.) One defect-initiation mechanism considered by Mogard⁽¹⁸⁾ involves cladding stretching or bending that occurs when pellet chips are located between the pellet and cladding.

Work compiled by Meinhardt⁽⁵⁹⁾ indicated that the actual stress at the fuel-cladding interface is one of the most important variables involved in predicting the design life characteristics of the cladding. The investigators also indicated that this stress has to be inferred from a fuel-element performance model because it is impractical to measure the stress at the fuel-cladding interface.

4.3.1 Fuel Pellet Thermal Distortion ("Hourglassing")

As noted by Kjaerheim and Rolstad,⁽³⁰⁾ when a cylindrical elastic body is subjected to a parabolic temperature gradient (typical for reactor fuel), it will deform to an hourglass shape. Lustman⁽²⁴⁾ pointed out that in the presence of such a thermal gradient, a fuel pellet deforms to the hourglass shape which may produce strain concentrations in the cladding and result in circumferential ridging of the cladding. According to Hoffman et al.,⁽⁶⁰⁾ ridges are of particular concern because they make that part of the cladding most susceptible to failure (e.g., from low cycle fatigue or other stress-dependent mechanisms). The concern about ridges stems from the fact that all three types of strain concentrations meet at ridge locations and cladding failures can occur in either the axial

or transverse direction.⁽³⁰⁾ (The three types of strain concentration are: axial strain concentration, hoop strain from longitudinal cracks in the fuel surface, and hoop strain from ridging.) *So far it appears that no one has made any study of the effects of "prestrain" in Zircaloy on the strain to failure in either the irradiated or nonirradiated condition. One would also be interested in learning whether "prestrain" might influence the strain for "dislocation channeling" and/or microcracking.*

Kjaerheim and Rolstad⁽³⁰⁾ pointed out that applying axial forces at the center of a cylindrical elastic body causes the body to assume a barrel shape with concave ends. According to Lyons et al.,⁽³³⁾ an axial force can develop at the center line of flat-ended pellets when the power is increased after fuel-cladding contact is established and could produce such a shape. This force, which is associated with nondished pellets, will reduce the tendency for fuel pellets to acquire the hourglass shape. Applying axial forces along the edge of a cylindrical elastic body also causes the body to deform to an hourglass shape.⁽³⁰⁾ Such an axial force system can be present in fuel rods which contain pellets with dished ends.

According to Aas⁽²⁵⁾ and Kjaerheim and Rolstad,⁽³⁰⁾ the circumferential ridge height is generally proportional to the linear heat-generation rate; however, ridging can also be influenced by pellet geometry. Lyons et al.⁽³³⁾ have noted that long pellets (within limits) form larger circumferential ridges than short pellets, while circumferential ridges are higher with dished pellets than with flat-ended pellets. Secondary ridges may form if long pellets are used. Apparently, ridging is reduced if the pellets are chamfered. Frictional forces that develop between the fuel and cladding during, or after, a power increase may tend to reduce pellet hourglassing.

However, there is apparently more reduction for flat-ended pellets than for dished pellets.

According to Hoffman et al.,⁽⁶⁰⁾ it is likely that ridging of the cladding by the fuel pellets occurs primarily during startup to full power (i.e., when pellets are relatively rigid and unmelted). The experimenters found that with annular pellet fuel the maximum ridging in a very high-performance fuel rod [~ 174 kW/m (~ 53 kW/ft)] did not differ significantly with that observed in fuel rods operated at conventional linear heat-generation rates [~ 56 kW/m (~ 17 kW/ft)]. The former rod operated with a fraction of the fuel molten. It was obvious that at some point in the irradiation, the annular pellets ceased to support the cladding, apparently resulting in the start of cladding-creep collapse.

In 1966, Hoffman et al.⁽⁶⁰⁾ noted that profilometry scans of irradiated fuel rods involved in direct comparison tests showed severe ridging with solid pellets, less extensive ridging with annular pellets, and virtually total absence of localized cladding deformation with powder fuel. The investigators indicated that the annular configuration apparently affects the hourglassing of the cylindrical body in some manner that is not well understood. They also noted that in the powder-fuel case there are occasional nonperiodic irregularities in an otherwise smooth profile.

The circumferential and axial strains associated with cladding ridges are additive to the strains resulting from thermal expansion and fuel swelling. Kjaerheim and Rolstad⁽³⁰⁾ reported that a bending stress in the axial direction is also produced by the ridges because of the cladding-wall radial deformation. This bending stress is independent of the axial forces.

Theoretical analysis to predict in-reactor pellet shape and ridge height on cladding is complex. Very moderate temperature gradients have been known to produce large ridges, according to Aas.⁽²⁵⁾ For reliable calculations one needs accurate ridge dimensional data and these are not always available. There is no valid reason for assuming symmetry of local surface profiles and work compiled by Meinhardt⁽⁵⁹⁾ suggested that there exists considerable evidence against it. As noted by Aas,⁽²⁵⁾ fuel rods, involved in irradiation tests in the Halden BWR, have been observed which had a very asymmetrical distribution of ridging around the cross section resulting in large strains on one side of the fuel rod.

Pickman⁽⁵⁵⁾ reported that the stress state at a circumferential ridge might be associated with a biaxiality ratio of one; hence, the possibility of reduced cladding ductility should not be ignored.

Fuel thermal distortion and the associated cladding ridging can apparently be reduced by using short pellets, chamfered pellets, annular pellets, or packed-particle fuel.

4.3.2 Ratchetting

Aas⁽²⁵⁾ reported that the elongation of the cladding by a ratchetting mechanism is associated with cyclic conditions of fuel-rod power and coolant-system pressure. Axial power peaking can cause local locking of fuel pellets to the cladding in the region of higher linear heat generation rates. In a later report, Aas⁽⁶¹⁾ found that this locking (i.e., interference) can prevent axial sliding of other pellets, increasing axial stress and forcing greater radial expansion. Fuel stresses and expansion can vary depending upon cladding ovality, fuel crack patterns, and the skewed axial alignment of fuel pellets.

Evidence for the existence of ratchetting has been noted. Axial deformation by ratchetting is a possibility, especially if the cladding is nonfreestanding. Ratchetting in the radial direction is also conceivable.⁽²⁵⁾

4.3.3 Strain Concentration Effects at Fuel Interfaces and Cracks

In the earlier review of the fuel-cladding-interaction mechanisms associated with fuel rod failures caused by power ramps, two areas of uncertainty were apparent. One area involved the question raised in 1971 by Mogard et al.⁽¹⁰⁾ about the dominant failure mechanism. In some cases, cladding-strain concentration was the dominant mechanism. In other cases, general straining was the dominant mechanism with strain concentrations essentially determining only the location of cracks in the cladding. The former mechanism is not easily amenable to prediction by calculational means, while the latter is if the fracture ductility of the cladding is known. Therefore, it was apparent that reducing strain concentrations is important because it would reduce the severity of the fuel-cladding-interaction problem and aid in the application of predictive methods. The second and more important area was the uncertainty as to whether the fuel rod failures associated with power increases were of a random or systematic nature.

According to Scandpower, Inc.,⁽²⁶⁾ Kjaerheim and Rolstad,⁽³⁰⁾ and Bobe,⁽⁶²⁾ the force distribution during a positive power ramp is very unfavorable because all axial cladding strain can be expected to occur locally at pellet-pellet interfaces. Aas⁽²⁵⁾ reported that localized straining of the cladding, even to failure, can occur over interfaces or cracks in the fuel when friction between the fuel and cladding is large enough to prevent sliding between the fuel and cladding. Aas further noted that, with respect to cladding instability, the maximum tolerable strain is usually taken to be equal to the

strain-hardening coefficient. Gittus⁽³¹⁾ has found that increasing the number of pellet cracks, increasing the strain-hardening coefficient, and decreasing the friction coefficient between the fuel and cladding all tend to increase the maximum tolerable cladding strain. Cladding stresses are almost equibiaxial at the ends of pellets, so failure is most likely to occur at these locations.⁽³¹⁾ In fast power ramps, there is insufficient time for the fuel to creep (except near the center of the pellet) so the pellet's thermal expansion opens fuel cracks which in turn may propagate cracks in the cladding.⁽³¹⁾

It was shown in a theoretical study by Gittus⁽⁶³⁾ that the most likely location for failure of the cladding was at the intersection of a radial pellet crack and the end of a pellet. At these locations the stresses are the greatest and are approximately biaxial. The worst possible case would be where two adjacent pellets have connecting radial cracks so that there is no force to restrain them from opening.

In considering cladding failure related to the strain concentration in the cladding regions associated with pellet cracks during or after a power ramp, Gittus⁽³¹⁾ found that the worst conditions are when the pellet-cladding-friction coefficient is high and the cladding work-hardening coefficient is low. Interfaceons (interfacial dislocations) are not a contributor to cladding failure.

It has been shown that friction, due to contact of a pellet with an adjacent cracked pellet, can propagate the crack across the interface. Hence, according to Gittus,⁽⁶³⁾ a reduction of the friction at the pellet-pellet interface might reduce interface crack propagation and thus fuel-cladding mechanical interaction. As noted by Mogard

et al.,⁽¹⁴⁾ cracks in the cladding correspond 80% of the time with cracks in the fuel even when the pellet cracks are closely spaced.

Reducing the localized axial and circumferential strain concentrations appears to decrease the fuel-cladding-interaction phenomenon and remove some of the calculational uncertainties.

4.3.4 Fuel-Cladding Bonding

Fuhrman and Pasupathi⁽⁶⁴⁾ and Fuhrman et al.⁽⁵¹⁾ reported that as part of the Joint CE/EPRI Fuel Performance Evaluation Program, fuel rods from the Maine Yankee Core I were examined at poolside and some hot cell examinations were performed. The Batch-B rods exhibited fission-gas release values of <1% or 11.3-13.5%. Fuel density measurements indicated an apparent densification of up to about 5% in one of the rods. Results showed that equiaxed UO_2 grain growth, indicative of higher operating temperatures, was found only in the higher gas-release rods. The most probable cause of cladding penetration was a pellet-cladding interaction mechanism in which cracking was promoted by fission products (e.g., iodine and/or cesium) because the scanning electron microscope (SEM) fractography indicated that no plastic deformation had occurred [*or (?) that the plastic deformation was quite uniform*]. Primary hydriding, on the other hand, did not appear to be a cause of initial cladding penetration [however, one perforated rod (Batch C) had localized primary hydriding]. Fuel-cladding bonding was observed primarily at pellet-pellet interfaces and the composition of the bonding material was determined to be a mixture of cesium, uranium, zirconium and oxygen.

A theoretical study was conducted by Smith et al.⁽³⁾ and described by Roberts et al.⁽¹⁾ on the fracture of Zircaloy cladding on LWR fuel rods caused by stress-corrosion cracking

that is associated with an increase in fuel rod power after a substantial burnup. The plane strain Mode I (tensile opening mode) analysis indicates two possible ways for crack propagation, depending on the value of stress intensification, K_{ISCC} , at the tip of the cladding crack. If K_{ISCC} for irradiated Zircaloy is very low [i.e., about 2.2 to 3.3 MN/m^{3/2} (2 to 3 ksi $\sqrt{\text{in.}}$)], the results imply a mechanism by which cracks propagate easily. On the other hand, if K_{ISCC} is relatively large, the results indicate that a likely cause for cladding fracture would be a high interfacial friction coefficient and, in particular, fuel-cladding bonding. Investigators have observed only a limited number of cladding cracks, which indicates that it is difficult to nucleate sharp cracks 8 to 10 μm (0.00031 to 0.00039 in.) deep. Based on the experimental evidence and anticipating that K_{ISCC} is low, Smith and Ranjan⁽⁶⁵⁾ have taken the position that crack nucleation in the Zircaloy metal is the critical step in the cladding fracture process.

According to Mogard et al.,⁽¹⁴⁾ commercial reactor power-ramp failures occur at smaller ramps than in test reactors. This could be due to the strong adhesion or bonding between interacting pellets and cladding, possibly caused by the long-term, steady-state irradiations in commercial reactors.

Interfacial bonding of fuel to the cladding could concentrate stresses enough for nucleation of cracks in the cladding.⁽¹⁴⁾ Lustman⁽²⁴⁾ pointed out that formation of ZrO_2 on the cladding inner surface can lead to a partial bond between fuel and cladding which may result in the transfer of localized strains to the cladding. If a perfect bond exists between the fuel and cladding, the cladding would fracture when a fuel crack opens. Aas⁽²⁵⁾ noted that, in most cases, some sliding occurs, which results in a stress gradient in the cladding with a maximum occurring over the fuel cracks. Examination of

UO₂-PuO₂ fuel rods irradiated in Saxton Core III [peak burnups of 3460-4410 GJ/kgU (40,000 to 51,000 MWd/MTM)] showed progressive gap closure and increasingly more fuel-to-cladding bonding; however, according to Smalley,⁽⁶⁶⁾ these phenomena apparently had no adverse effect on overall fuel performance or dimensional stability.

KWU fuel studies by Holzer et al.⁽⁵⁾ on defective Obrigheim and Gundremmingen fuel rods could not confirm that bonding of the fuel to the cladding is a prerequisite for pellet-cladding interaction failures as supposed by Smith.⁽⁶⁷⁾ On the contrary, cracks in defective Gundremmingen fuel rods were found in the studies to be in free-standing cladding wall arching over an area of the fuel where UO₂ chips are missing.

Fuel is sometimes observed in postirradiation examinations to be firmly adhering to the cladding; however, Garlick and Gravenor⁽⁶⁸⁾ noted that it is not clear whether this bonding is present under operating conditions. They suggested that the interface layer could be soft when the fuel rod is at power and could be less effective as a bonding medium. It is difficult to experimentally evaluate fuel-cladding bonding during irradiation; however, there are data from SGHWR standard fuel that indirectly indicate that there is some adhesion when more highly rated fuel is at power.⁽⁶⁸⁾

It appears desirable to reduce the amount of fuel-cladding bonding.

4.4 Stress-Corrosion Cracking (SCC) and Cladding Embrittlement

According to work by Wood⁽²⁹⁾ and Holzer et al.,⁽⁵⁾ there appear to be at least three prerequisites for cladding deterioration due to SCC.

- Sustained tensile stress. This can be caused by the power level or a power change resulting in pellet-cladding mechanical interaction. [A threshold-stress level is likely to exist; time is required for the two-step fracture process (i.e., crack nucleation and subsequent propagation).]
- Chemically-active fission products. These must be present but are dependent upon operating power, change in power, and burnup. (A threshold level for aggressive fission products may exist.)
- Susceptible cladding metallurgical state. This is influenced by intermetallic precipitates, cladding embrittlement due to irradiation ("irradiation damage"), or by fission products (such as iodine, liquid cadmium, liquid cesium, etc.).

In 1972/1973, Wood⁽²⁹⁾ stated that of the three prerequisites, only the third had been proven. It was noted by Cox and Wood⁽⁶⁹⁾ in 1974 and by Cubicciotti and Jones^(70,71) and Videm and Lunde⁽⁷²⁾ in 1977 that the data base from power reactor fuel examinations, laboratory studies, and analyses support the concept of a sustained critical stress in the cladding wall in the presence of active fission-product species. Holzer et al.⁽⁵⁾ and Smith⁽⁶⁷⁾ indicated that fuel-cladding bonding may not necessarily be a prerequisite for SCC.

Gelhaus⁽⁷³⁾ stated that cladding failure involves three major steps: 1) fissure of the oxide layer, 2) initiation of a substrate flaw (i.e., nucleation of a crack), and 3) flaw extension through the cladding wall. Cubicciotti et al.⁽⁷⁴⁾ indicated that cracking or other disruption of the protective zirconia surface could be an important first step in SCC. Penn et al.⁽¹⁶⁾ and Cox and Wood⁽⁶⁹⁾ stated that rupture of the protective ZrO_2 layer on the cladding inner surface is a tentative prerequisite for SCC because there is evidence that fission products (e.g., iodine) can some way penetrate the ZrO_2 under static stress conditions. *There appears to be a basis to*

question whether or not crack nucleation in the metal precedes the fissuring of the oxide film. Cubicciotti and Jones⁽⁷⁰⁾ reported that stress rather than strain appears to be the critical parameter in crack formation; however, some strain--and, in particular, localized strain in irradiated cladding--is a necessary condition for cracking.

Ranjan and Smith⁽²⁾ and Cubicciotti and Jones⁽⁷⁰⁾ concluded that the key step in pellet-cladding-interaction failures is crack formation (i.e., crack nucleation) in the cladding metal; this step is equivalent to very early stage propagation. Apparently many cracks [$\sim 10 \mu\text{m}$ ($\sim 0.00039 \text{ in.}$)] form in the cladding at artifacts (e.g., pits, second-phase particles, or grain boundaries), once the oxide layer is fissured. Smith and Ranjan⁽⁶⁵⁾ noted that subsequent growth of these cracks, to $\sim 20 \mu\text{m}$ ($\sim 0.00079 \text{ in.}$),⁽⁹⁾ requires a critical stress to rupture the intervening group of grains, i.e., the ligament. If chemical corrosion (cleavage) occurs easily, a smaller group of grains is involved and this means a lower stress. According to Miller et al.⁽⁷⁵⁾ and several other sources,^(70,72,76) crack growth is fairly rapid once the crack has formed to $\sim 20 \mu\text{m}$ ($\sim 0.00079 \text{ in.}$) and the growth is predominantly transgranular cleavage. Miller et al.⁽⁷⁵⁾ also indicate that if the stress or fission-product environment is not sustained (e.g., stress relaxation of the cladding by creep will definitely alter crack growth), propagation of the crack will slow and the crack can arrest. Because slow propagation favors an intergranular path, intergranular regions on the crack front could be employed to determine whether pellet-cladding interaction is cumulative.

A number of investigators concluded that certain features of the Zircaloy cladding may influence SCC and these include: oxide film characteristics,^(23,68,69,71,77) local texture of the inner surface,^(65,69,72,75) yield stress (particularly as it is affected by irradiation),^(65,69) and inside surface features (e.g., second-phase particle distribution).^(65,71,75)

SCC mechanisms, stress, fission products, cladding metallurgical state, and cladding embrittlement are discussed in the following parts of this section.

4.4.1 SCC Mechanisms

Stress-corrosion cracking (SCC) of Zircaloy is reported by a number of investigators^(1,21,23,28,51,78) to be, the principal mode of failure in pellet-cladding interaction during normal fuel-rod operations (including anticipated transients). Garlick and Wolfenden⁽⁷⁹⁾ have pointed out that stress-corrosion cracking involving transgranular cracking is widely believed to be an intermittent, predominantly mechanical, fracture process in which the role of corrosion is to spasmodically trigger further fracture by removing obstacles to crack growth.

In analyzing failures of power-ramped fuel rods, it is difficult to separate the failures due to SCC from the purely mechanical failures because, as Scandpower, Inc.⁽²⁶⁾ has noted, the regions of highest strain and most aggressive corrosion coincide. A number of investigators^(1,65,68,69) concluded that the shape and morphology of the cladding cracks should indicate how the crack propagation is proportionally shared by the mechanical and chemical processes. The crack is straighter and transgranular cleavage should predominate if the stress is low. If high stresses are involved, there should be more crack branching and more fluting on the fracture surface. *It should be noted that crack branching also may easily occur in the absence of an SCC environment whenever the strain energy in the component exceeds that necessary for simple crack extension and under these circumstances crack branching is the process by which "excess" strain energy is dissipated.* An example of the fluted fracture surface markings that support the SCC mechanism was shown in the paper by

Pickman.⁽⁸⁰⁾ Holzer et al.⁽⁵⁾ indicated that it could well be that fission-product availability and stress generally are reciprocal. According to Fuhrman et al.,⁽⁸¹⁾ fuel-cladding interaction-mechanisms exist which apparently range from those influenced by high stress (associated with a large and fast power ramp) to those influenced by a high concentration of chemicals (associated with a large fission-gas release).

It has not yet been clearly shown experimentally which material parameter--stress, strain, strain rate (creep)--most uniquely defines the threshold for SCC. See comments on stress under Section 4.4.2 below. As discussed earlier, the data base supports a threshold-stress concept, although some plastic strain is needed for SCC. Apparently there is little information available to aid in establishing whether or not there may be a critical strain for crack initiation. In a number of experiments, sample deformation was not measured or, if it was, it was not reported. Wood and Hardy⁽²³⁾ have expressed doubt that attaining a critical strain is a prerequisite for SCC crack initiation.

At the cladding temperatures of interest to this program, the cladding is very susceptible to creep (strain rate). Studies by Reinoehl and Boyd⁽⁸²⁾ and Wearmouth et al.⁽⁸³⁾ on materials other than Zircaloy indicated that SCC only occurs within a narrow range of strain rates. As reported by Wood and Hardy,⁽²³⁾ and Garlick and Gravenor,⁽⁶⁸⁾ Canadian, UK, and US studies have indicated that iodine SCC of Zircaloy is strain-rate dependent. Strains to failure generally decrease with a decrease in hoop strain rates in range of 10^{-3} to 10^{-6} s^{-1} . However, Wood and Hardy⁽²³⁾ found a reversal of that trend when very slow deformation rates were used (i.e., strains to failure began to increase below 10^{-7} s^{-1}) and low-strain specimens were free of defects at strain rates below 10^{-8} s^{-1} . Wood and Hardy have speculated that at those low strain rates,

the cladding deforms by creep below the critical stress for SCC. Reinoehl and Boyd⁽⁸²⁾ suggest that at very low strain rates, the crack surfaces may passivate and thereby virtually eliminate SCC as a mechanism contributing to failure.

Zircaloy-cladding corrosion can generally be classified as hydriding or stress-corrosion cracking assisted by fission products. Hydriding is discussed briefly in Section 6.1 of the Appendix because it does not relate directly to the fuel-cladding-interaction mechanism. Roberts et al.⁽⁸⁴⁾ indicated that laboratory and test data support the concept that SCC has three stages: crack initiation at the cladding inner surface, initial crack propagation, and final crack propagation. The relative contributions of stress and chemistry to SCC are not well defined. These authors have also stated that several indications favor SCC over mechanical failure or embrittled Zircaloy: Cracks are normal to the cladding surface and crack surfaces are macroscopically flat; tight natural-penetration cracks are frequently observed; microscopic fracture surfaces are similar to iodine SCC laboratory results in that they both have flat cleavage planes and fluted regions; there is a lack of necking of the cladding or general deformation; there is a delay time of several hours between the increase in power and the failure signal; power increases in new fuel with irradiated cladding do not cause defects (fission-product concentration is low); and cracks are initiated at the inner surface even when pellet chips produce the maximum stress on the cladding OD.

Wood and Hardy⁽²³⁾ have reported on Canadian power-ramping defects. After a fuel is ramped and before a defect signal is observed, there is usually a time delay of about 5 ks; however, occasionally time lapses as low as a few seconds or up to 500 ks have occurred. In several cases, fuel rods with Zircaloy and Zr-2.5 wt% Nb alloy cladding defected during irradiation, released a short burst of

fission products, and then re-sealed themselves. (The defects were definitely confirmed by neutron radiography.) Postirradiation examination of those rods showed narrow through-wall cracks that were heavily oxidized. Inspections of other Canadian power-ramped fuel (power reactor and experimental type) that defected showed SCC-type cracks, starting at the cladding inside surface, that were narrow and often branched. The cracking was observed to be a mixture of transgranular cleavage and intergranular cracking. Except for a few, the cracks were radially oriented and incipient cracks (i.e., cracks that penetrated ~80% of the wall) were not associated with any discernible necking. The mode of failure of through-wall cracks usually changed: Within the last 10% or so of wall thickness the mode changed from SCC type to ductile shear (shear deformation yields the characteristic "X" markings on the cladding outer surface). The Canadian experience also suggests that the threshold power for SCC is closely related to fission-product availability, and, conversely, that the threshold-stress level is closely related to the power increase. In testing doped rods (irradiated cladding, fresh UO_2 pellets, iodine or cesium iodide, and with or without moisture), Wood and Hardy found moisture to be a defect inhibitor.

Wood and Hardy⁽²³⁾ made a tentative interpretation of their ramped-fuel experience and suggested two alternative ZrO_2 surface oxide breakdown mechanisms. The two are described in Section 4.1, above.

Penn et al.⁽¹⁶⁾ indicated that power-ramp defects are attributable to one or both of the two mechanisms mentioned in Section 4.1, above.

Three main defect-initiation mechanisms proposed by Mogard⁽¹⁸⁾ to occur consecutively during a normal fast power increase were discussed in Section 4.1, above.

Cubicciotti and Jones⁽⁸⁵⁾ have studied the crack-initiation process of Zircaloy-4 in an iodine atmosphere and have proposed

a possible mechanism for SCC. In that mechanism, plastic strains in the cladding lead to the mechanical rupture of the oxide film. Second-phase particles (mainly Al, Si, Cr, and Fe), whose locations happen to coincide with the cracks in the oxide, are exposed to the aggressive environment. Chemical attack occurs either at the particles themselves or at the particle-matrix interface (highly stressed). Wedging stresses due to a bulky reaction product initiate the formation of a small crack, which exposes more particles to react. Alternatively, local removal of material might be accomplished by a volatile reaction product and could lead to a chemically sharpened crack nucleus. These processes would continue until the stress intensity exceeds K_{ISCC} , where transgranular cleavage becomes possible, and leads to eventual failure. [K_{ISCC} is the stress intensity factor for Mode I (tensile opening mode) under SCC conditions.]

It has been suggested that plastic deformation concentration in the cladding provides "nascent" (i.e., fresh nonoxidized) material which is vulnerable to physical-chemical action by aggressive species (e.g., fission products). This promotes stress concentration by the development of microcracks, which use up the local ability of the Zircaloy structure to accommodate the applied stress field through deformation.

Cox and Wood⁽⁶⁹⁾ have reviewed iodine-induced cracking of Zircaloy cladding, including the effects of coldworking, irradiation hardening, crystallographic texture, surface oxide conditions, and residual stresses. The review included results of tests at 300°C (570°F) on various types of cladding (Zircaloy, Zr-2.5 wt% Nb alloy, Ozhennite and Zr-Cr-Fe alloys). They stated that there are three steps to cracking. First, mechanical or chemical interaction exposes the cladding to iodine; second, the chemical environment leads to the formation

of a sharp notch below the oxide layer; and third, an absorption mechanism causes the crack to propagate.

4.4.2 Stress

According to Wood⁽⁸⁶⁾ and Robertson,⁽⁸⁷⁾ a biaxial stress is necessary for SCC. In their 1977 paper, Knudsen et al.⁽⁹⁾ indicated that laboratory tests have shown that a biaxial stress state in the cladding is more likely to cause failure than a uniaxial stress state.

Apparently SCC can begin at stresses less than the yield stress. The yield stress for Zircaloy cladding at the nominal fuel surface operating temperature [$\sim 315^{\circ}\text{C}$ ($\sim 600^{\circ}\text{F}$)] is 414-517 MPa ($\sim 60,000$ -75,000 psi) for stress relieved cladding and 172-241 MPa ($\sim 25,000$ -35,000 psi) for fully annealed cladding. Knudsen et al.⁽⁸⁸⁾ indicated that SCC seems to begin at stresses close to the yield stress. Wood⁽²⁸⁾ reported that for iodine-induced SCC to occur, a sustained stress of sufficient magnitude (less than half the yield stress for 100 hours) is necessary. Cubicciotti and Jones⁽⁸⁹⁾ reported that tests with artificially defected Zircaloy-4 showed that a threshold stress of 275 MPa ($\sim 40,000$ psi) is required before an iodine-induced stress-corrosion crack forms and propagates at 360°C (680°F).

Garlick and Gravenor⁽⁶⁸⁾ recently reported on SCC tests in connection with fuel for the Winfrith Steam Generating Heavy Water Reactor and indicated that a critical stress level for cracking exists and that the laboratory results show iodine stress-corrosion cracking occurring at 350°C (660°F) and 345-414 MPa (50,000-60,000 psi). With nonirradiated, heavily cold-worked Zircaloy tubing subjected to short-term (<4 hr) pressurization, Garlick and Gravenor⁽⁶⁸⁾ and Garlick⁽⁹⁰⁾ found that a stress of 500 MPa (72,500 psi) was required to initiate SCC. Lacking comparative data for irradiated cladding, UK

investigators assumed 500 MPa as the critical stress for ramp defects in their modeling codes. The predictions were found to provide a useful indication of defect probability under reactor service conditions.⁽⁶⁸⁾ According to Wood and Hardy,⁽²³⁾ a stress threshold could exist that is related to the power increase. Penn et al.⁽¹⁶⁾ reported that there is a critical stress for crack initiation and propagation; sheath strain may be required to rupture the protective ZrO_2 layer on the inside surface of the cladding.

Experiments by AECL, WAPD, and EPRI/SRI on iodine-induced SCC (I_2 SCC) suggest that if there is a unique stress threshold for I_2 SCC in Zircaloy, that threshold is most likely a function of the strength of the material.^(a) To date, the I_2 SCC threshold observed in AECL experiments is greater than the 0.2% yield strength; WAPD experiments suggest that the I_2 SCC threshold is about 152-165 MPa (22,000-24,000 psi). The EPRI/SRI experiments suggest that the stress threshold is in the range 310 MPa (45,000 psi) to about 517 MPa (75,000 psi). If the concept of an I_2 SCC stress threshold is valid, the variations observed tend to suggest that the stress threshold may be proportional in some way to the strength of the cladding. If so, some advantage may be gained if the thermal-mechanical interaction stress levels can be controlled and held to low values.

A number of investigators^(2,5,75) concluded that a threshold-stress range is likely to exist. If fission-product availability is low (i.e., the fuel rod has operated at low power and/or has attained low burnup), high critical stresses will be required. With higher power and/or higher burnup levels, the critical stress will decrease significantly (e.g., from the yield stress

(a) It should be recognized that "radiation hardening" may override any strengthening that is attributable to cladding fabrication.

to perhaps one-third of the yield stress). Ranjan⁽²⁾ and Smith⁽⁶⁵⁾ also indicated that the effects of fuel-cladding friction are of secondary importance in regards to generating the critical stress.

4.4.3 Fission Products

Cubicciotti et al.⁽⁷⁴⁾ have extensively studied the reaction between fission products and Zircaloy cladding and indicate that the reaction kinetics is highly dependent upon their chemical state. For reaction to occur, the fission products must be transported to the cladding; temperature and oxygen potential gradient govern the rate and mechanism of transport. The oxygen potential controls the fission product chemical states which, in turn, determine the reactivity of the fission products with the cladding. Oxygen is slowly transported from the fuel to the inner surface of the cladding during irradiation. As reported by Cubicciotti et al.⁽⁷⁴⁾ and Adamson et al.⁽⁹¹⁾ the measured oxygen potential of irradiated fuel was found to be in the range -460 to -540 kJ/mole O_2 , with the more negative value associated with the central hotter fuel. Cesium (also rubidium, but to a lesser degree), which plays an important part in establishing the oxygen potential of the fuel, can be transferred within the fuel rod by vapor transport, and can deposit as compounds on the cladding. The fuel oxygen potential is probably buffered by molybdenum oxide.

Cubicciotti et al.,⁽⁷⁴⁾ also reported that examination of line and circular mound deposits on cladding inner surfaces of Maine Yankee Reactor Core I fuel showed the deposits to contain mainly cesium, iodine, and tellurium combined with uranium, zirconium and oxygen. Several mechanisms were proposed for the formation of those deposits. One involved having fuel pellets cracking and fuel particles breaking loose as dust from the pellet surface and depositing (line-like) on the cladding opposite the crack

mouth. Fission-product cesium vapor can react with the UO_2 at fuel operating temperatures by a reaction such as:

The $\text{Cs}_2\text{UO}_4\text{(s)}$ deposit can react with Zircaloy and may possibly render the ZrO_2 film less protective. The second mechanism involves the circular mound deposits. It was suggested that fission-product cesium in the form of gaseous Cs_2O was released when the fuel temperature increased. This deposited on the cladding and reacted with UO_2 fuel to form the Cs-U-O compounds that were observed. Across from pellet-pellet interfaces, the same mechanism is assumed to apply, due to the easy access to the hot central part of the fuel at pellet ends.

Cubicciotti et al.⁽⁷⁴⁾ speculated that cesium will react as follows: First, it will react with the fission-product iodine and tellurium (discussed later), then it will react with certain impurities (e.g., Al_2O_3 and SiO_2), and when these are exhausted, the cesium will react with the UO_2 .

Cubicciotti et al.^(70,71,77) and Roberts et al.⁽¹⁾ have concluded that the fission-product species that are most likely to be active are: iodine vapor (it is released from CsI), liquid cadmium, and liquid cesium, in that order. In their opinion, cesium is most likely combined in oxides or uranates, hence, its major contribution will be in the fuel-cladding bonding.

Wood and Hardy⁽²³⁾ have stated that a threshold power could exist that is related to the fission product concentration. Fuhrman et al.⁽⁸¹⁾ have found that a higher fuel temperature causes more release of fission gases and increases the susceptibility of the cladding to SCC.

Cubicciotti et al.⁽⁷⁴⁾ and Olander⁽⁹²⁾ have presumed that cesium is released from the hotter part of the fuel during temperature transients in a fashion similar to that of fission-gas (Xe, Kr) release. Fuel design (e.g., porosity, grain size, O/M ratio, density, cracking behavior) can influence the release of fission gases.^(5,33,35,93)

Penn et al.⁽¹⁶⁾ noted that a popular view has been that the iodine is released in a "sharp burst" during power increases; however, they indicated that Notly⁽⁹⁴⁾ has questioned this hypothesis. Notley's studies show that the release of fission gases (and by inference, iodine also) after the power ramping of fuel rods was very time-dependent.

Cox and Wood⁽⁶⁹⁾ have found that the distribution and chemical state of iodine inside operating fuel rods is of particular importance because it can cause SCC of Zircalloys. The zirconium-iodine system is unusual because cracks apparently propagate in the absence of an electrolyte.

A series of tests were performed by Lorenz et al.⁽⁹⁵⁾ whereby selected stable nuclides were implanted in Zircaloy-4 clad UO_2 pellets. Simulation of failed cladding during irradiation was accomplished by heating the rods [500-1100°C (930-2010°F)] and either perforating the cladding beforehand or internally pressurizing the fuel rod to induce rupture. In this way, the researchers could determine the amounts and identities of radiologically significant fission products that could be released in an accident. The behavior of the main fission products indicated by these tests was such that the tellurium transferred almost completely (96%) from the pellet to the cladding, iodine was split evenly and most of the cesium (65%) remained on the pellet. It was also noted that the Zircaloy-4 cladding itself was an effective getter of tellurium. The compound formed was Te_3ZrO_5 which is less volatile so that the

tellurium was retained. Penn et al.⁽¹⁶⁾ have found that a requirement for SCC is a high enough concentration of aggressive fission products (e.g., iodine, cesium, cadmium, and perhaps others). There is evidence reported by Penn et al.⁽¹⁶⁾ and Wood⁽²⁸⁾ that the iodine concentration required for SCC is small. Wood⁽⁹⁶⁾ reported that there seemed to be a threshold iodine concentration of 3 mg/cm^3 (0.19 lb/ft^3), above which fuel rod failures occurred within 100 hours. In a later paper,⁽²⁸⁾ he indicated an iodine vapor pressure of 10^{-2} MPa (1.5 psi) was required for fuel rod failure to occur in one hour. Busby et al.⁽⁹⁷⁾ observed that an iodine concentration of 0.04 mg/cm^2 ($8.2 \times 10^{-5} \text{ lb/ft}^2$) of Zircaloy surface was more than sufficient to cause cracking at 360°C (680°F) and 400°C (750°F).

Cubicciotti et al.⁽⁷⁴⁾ reported that tellurium and selenium (because it is assumed to behave like tellurium) are potentially reactive with zirconium and may be agents for SCC. Other elements noted by the authors as either observed at the cladding or postulated to be able (in volatile form) to reach the cladding are: 1) Pd, Mo, and Fe (all are potential embrittling agents for Zircaloy), 2) Cd, Sb, Al, Si, and Ag (these are suspected to be embrittling agents), 3) Ba, Ca, and Na (these might embrittle Zircaloy), and 4) Cl (this should behave like iodine but to a lesser degree). They concluded that a number of vaporized fission products might be anticipated to reach the cladding including: Cs (Rb) in compounds; I (Br) and Te (Se) in compounds with Cs; elemental Cd, Sb, Ag, Sn, and Pd; Ba, as BaO; and possibly MoO₂. Also noted by Cubicciotti et al. were the impurities and fission products that have been observed at the fuel-cladding interface or irradiated LWR fuel rods and these elements (associated chemical compounds not listed) are: Cs, Te, I, Pd, Ba, Fe, Cl, Si, Al, Ag, Na, and Ca. Cubicciotti et al. state that, in general, the sensitivity of Zircaloy to

embrittlement is unknown. During irradiation, CsI can liberate iodine which is known to embrittle Zircaloy. Other elements (Fe, Cd, others) located at the cladding may also act as agents for SCC.

An analysis of mixed-oxide ($\text{UO}_2\text{-PuO}_2$) fuel rods, irradiated in the EBR-II has been performed and fuel-cladding chemical reaction was observed in the 20% cold-worked, stainless-steel cladding by Ellis et al.⁽⁹⁸⁾ A significant finding was that the reaction increased with an increasing initial oxygen/metal (O/M) ratio. Rods with the same cladding temperature, power, and burnup [~ 3800 GJ/kgM (~ 5 at.%)] exhibited different pellet-cladding-interaction (PCI) characteristics with different O/M ratios. It was noted that extrapolation indicated an O/M of < 1.93 would be required to avoid pellet-cladding reaction.

In work reported by Ewart et al.,⁽⁹⁹⁾ four miniature fuel pins containing mixed-oxide fuel in stainless-steel cladding were irradiated in a thermal reactor. Fuels with initial O/M ratios ranging from 1.94 to 2.15 were involved. Both intergranular and "broad front" attack were observed and the results of these experiments support the suggestion that this cladding attack can be minimized by low oxygen potential conditions. The predominant species found in the pins was cesium, and observations indicate that cesium is compatible at a local oxygen potential of -545 kJ/mole (-130 kcal/mole) or less. A possible mechanism for broad front attack is that the cesium oxide interacts with the chromium, which could remove the protective oxide layer from the steel. The indications show that the oxygen potential in the body of the fuel seems to control the relative rates of release of tellurium and cesium. It is also noted that no cladding elements were found in the fuel matrix remote from the cladding in these experiments.

The nature of the chemical interaction between mixed-oxide ($\text{UO}_2\text{-PuO}_2$) fuel and the stainless-steel cladding of fast reactor fuel pins has been reviewed by Fee et al.⁽¹⁰⁰⁾ They discussed the four processes involved in the irradiation of a fuel pin: 1) development of a temperature gradient, 2) fuel restructuring, 3) fission-product buildup (affects the oxygen potential), and 4) fission-product migration. Processes 1 and 2 occur early in the life of the fuel pin; 3 and 4 occur later. The authors discussed the chemistry of the corrosive attack processes in terms of observations (both in-reactor and out-of-reactor type), evaluated current models of cladding attack, and described the use of getters to control the oxygen potential as a means of eliminating cladding attack.

Javed and Roberts⁽¹⁰¹⁾ conducted transpiration experiments on $\text{UO}_2\text{-PuO}_2$ fuel and the chemical reaction products were analyzed. In the temperature range 1000-1700°C (1830-3090°F), cesium, rubidium and gaseous iodine are expected to be the volatile fission products. It was noted that iodine was not expected to attack the stainless-steel cladding aggressively in the presence of oxygen, though surface depletion of iron and chromium was possible. A possible mechanism for PCI would be that there is a precipitation of a second-phase material which could cause a volume change that would strain an already embrittled cladding and/or modify the fuel cracking behavior. The rate of cladding attack was sensitive to the condition of various corrosion compounds. It was suggested that a eutectic between Cs_2MoO_4 and MoO_3 has a low melting point so that a liquid film might develop on the inner surface and cause a stress sensitive mechanism. There was no attack observed at temperatures <500°C (<930°F) and the final conclusion was that at O/M >2.000, aggressive reactions could occur between the fuel, cladding, fission products and coolant.

4.4.4 Cladding Metallurgical State

For SCC to occur, there must be a certain combination of susceptible metallurgical structure in the alloy, sustained stress, and a mildly aggressive chemical environment. Statistical variations in the quality of the cladding and in the effects of irradiation are important, according to Aas et al.⁽¹¹⁾ Crystallographic orientation may have an effect on sensitivity of the cladding to SCC. Wood⁽²⁸⁾ and Wood and Hardy⁽²³⁾ indicate that Zircaloy cladding is in a metallurgically susceptible state when the fluence is 1.0×10^{24} neutrons/m² or greater. An earlier report by Wood⁽⁸⁶⁾ stated that Zircaloy cladding irradiated in an iodine vapor at 300°C (570°F) under static tensile stress in the proximity of UO₂ became susceptible to SCC after a fluence of 2.1×10^{24} neutrons/m², but was not susceptible to SCC when irradiated in air at the same temperature.

It has been indicated that cleavage in Zircaloy appears to be favored at, or near, the basal plane. Hence, a strong tangentially oriented texture (basal plane perpendicular to hoop stress, i.e., textural angle of ~90°) would favor SCC by hoop stress action.

4.4.5 Cladding Embrittlement

Aas⁽²⁵⁾ found that with unirradiated Zircaloy cladding, preferred orientation (i.e., texture) is the major contributor toward variations in properties (e.g., ductility, strength) which influence dimensional changes. Aas also noted that the strain-hardening coefficient of unirradiated Zircaloy can be significantly decreased by a small amount of cold work (e.g., 10%) and independent of texture.

Irradiation produces adverse effects in Zircaloy cladding properties including the following: 1) It decreases ductility and increases strength, as noted by Aas;⁽²⁵⁾ 2) it increases the

creep rate substantially, as noted by Pickman;⁽⁵⁵⁾ and 3) it produces a marked loss in strain-hardening capacity. The biaxial stress ratio can vary (e.g., if the linear heat-generation rate histories have been different) for the same rod or identical fuel rods. This affects the generalized cladding strain at failure and the life of the fuel rod may be limited by strain fatigue due to daily power cycling.

Aas⁽²⁵⁾ stated that the best ductility and highest strength combination appear to be associated with annealed Zircaloy having a texture where the basal poles are radially oriented. Pickman⁽⁵⁵⁾ noted that cladding, produced by fabrication techniques that yield the favored circumferential hydride orientation, is also characterized by having a texture where the basal (0001) poles are predominantly radially oriented. Hannerz and Vesterlund⁽¹⁰²⁾ indicated that all presently available information on BWR cladding mechanical properties supports the use of recrystallization annealed cladding with a texture angle of 30° between the basal poles and the surface normal for BWR fuel rod cladding. They also indicated that the tendency for creep collapse to occur can be somewhat lessened by using cladding with an appropriate texture; hence for PWR fuel, fully-annealed or cold-worked cladding with a texture angle of 45° would be favorable.

The conditions and/or environments which promote loss of general ductility due to hydriding and/or oxidation are not generally considered to be present as primary parameters in the fuel-cladding-interaction phenomenon. Also, the mechanisms of "irradiation damage" (embrittlement) are not sufficiently understood to enable the development of concepts for circumventing or mitigating irradiation damage. Irradiation damage can be removed by isothermal annealing; however, this appears impractical because irradiation damage saturation is approached at very low fluences, i.e., in the range $\sim 5 \times 10^{23}$ to $\sim 1 \times 10^{24}$

neutrons/m² [equivalent to burnups of about 90 to 130 GJ/kgM (1000 to 1500 MWd/MTM)].

Embrittlement, as considered in this report, will be limited to interactions with certain fission-product species which may embrittle or, by virtue of experimental observations by Grubb and Morgan⁽¹⁰³⁾ and Cubicciotti et al.,⁽⁷⁴⁾ are known to embrittle the Zircalloys used for fuel cladding. Among the principal and most prevalent fission products known to embrittle Zircaloy are cadmium and mixtures of cadmium and cesium. *Remedies which are effective against iodine SCC are also expected to be generally effective against fission-product embrittlement.*

Embrittling agents for Zircaloy were discussed in Section 4.4.3, above. The studies by Cubicciotti et al.⁽⁷⁴⁾ indicated that the most likely embrittling agents for Zircaloy are: iodine, cesium (by itself or combined with oxygen), tellurium, cadmium, iron, and perhaps others (e.g., Pd, Ba, Ag, Sn, Cl).

Experiments by Grubb and Morgan⁽¹⁰³⁾ showed that cadmium severely embrittles Zircaloy-2. Qualitatively, the results were similar for solid cadmium [300°C (570°F)], liquid cadmium [340°C (640°F)], and cadmium dissolved in cesium over a range of temperatures (mainly 300°C). There appears to be a need for studies on the strain-rate dependence of cadmium embrittlement of Zircaloy.

Syrett et al.⁽¹⁰⁴⁾ conducted tests to determine the effect of liquid cesium [at 300°C (570°F)] on Zircaloy cladding. Embrittlement occurred at 40°C (104°F) as well as at 300°C. However, the embrittlement occurred only if the cesium had a trace of iron and a low oxygen content. The low oxygen content could enhance embrittlement because a protective oxide layer on the cladding cannot form quickly enough. More research is needed to determine the contribution of iron to embrittlement. It is not

clearly understood what relative effects exist between iron and cesium on the embrittlement of Zircaloy-4.

To summarize, Section 4.4 indicates that the following remedial actions are likely to alleviate the stress-corrosion cracking and fission-product embrittlement problems:

- Eliminate or impede contact and/or condensation of those fission products that promote stress-corrosion cracking (e.g., iodine) or embrittlement (e.g., cadmium and cesium) in the Zircaloy cladding.
- Minimize or eliminate stress and/or strain localization in the cladding resulting from pellet-cladding thermal-mechanical interaction. For instance, minimizing the radial temperature gradient in the fuel would have the effect of reducing the release of aggressive fission products from the fuel, as well as reducing the thermal-mechanical driving force for fuel-cladding interaction.

4.5 Remedial Actions

Some of the investigators referred to in this report suggested remedial actions that might aid in reducing the fuel-cladding-interaction phenomenon. A number of their suggestions plus some additional ones are summarized below.

4.5.1 Remedial Actions for Thermal-Mechanical Interactions

According to Aas⁽²⁵⁾ and Kjaerheim and Rolstad,⁽³⁰⁾ if solid fuel pellets are to be employed, short pellets (e.g., length-to-diameter ratio of ~0.5 to 1.0) should reduce cladding ridging. They also note that chamfering of the solid pellets tends to reduce ridging.

Annular pellets are of interest because they produce less ridging than solid pellets under comparable thermal conditions, as noted by Hoffman et al.⁽⁶⁰⁾ Packed-particle fuel is also

of particular interest because those authors have found that localized cladding deformation is virtually absent with that type of fuel rod.

In-pile studies designed to investigate the influence of various pellet parameters on fuel-cladding interaction have been performed at Halden as reported by Rolstad et al.⁽¹⁰⁵⁾ The specific aim of this work was to investigate the effects of annular (cored) pellets. Tests were carried out to compare some solid, 90% TD pellets with annular pellets (95% TD pellets but with central holes of a size that gave an overall pellet density of 90% TD). The results showed that an annular pellet rod had an elongation twice that of a solid pellet rod. Mechanical interaction was appreciably smaller for low density and vibratory compacted fuels.

The maximum strain that the cladding can tolerate can be increased by increasing the number of fuel cracks, increasing the cladding strain-hardening coefficient, and decreasing the coefficient of friction between the fuel and cladding. The last two items will be discussed later. According to Roberts and Wrona,⁽³⁵⁾ a possible way to promote more fuel cracking is to weaken the fuel by controlling the iron content or by optimizing the fuel microstructure (i.e., controlling crack propagation in the fuel).

Fission-product-induced swelling of the fuel still remains unpredictable according to Lyons et al.⁽³³⁾ and the solid fission-product swelling may be sensitive to the fuel stoichiometry. Those authors, and Frost,⁽⁴⁵⁾ have noted that the solid fission-product swelling could be significantly reduced if one could induce the cesium and rubidium to be released from the fuel or if one could promote formation of compounds.

Hölzer et al.⁽⁵⁾ indicate that a fuel with a high plasticity and a low fission-product-release characteristic would be beneficial. Whether a reduction of the fission-product release (e.g., by modification of the fuel microstructure) under transient conditions is possible still needs to be verified. Grain Size and fission gas release measurements were made on Maine Yankee fuel and were reported by Fuhrman et al.,⁽⁵¹⁾ Fuhrman and Pasupathi⁽⁶⁴⁾ and Holzer et al.⁽⁵⁾ The results indicated that UO_2 with larger initial grain size tended to result in a smaller release of fission gas. The release of volatile fission products is usually assumed to be proportional to the release of fission gases.⁽⁵⁾

Chubb et al.⁽⁴¹⁾ have stated that it is generally undesirable to weaken the fuel, but in some cases fuel rod dimensional stability is improved by weakening the fuel and/or increasing the strength of the cladding. Robertson et al.⁽³⁶⁾ and Wood⁽⁸⁶⁾ reported that weakening the pellet could increase the number of pellet cracks, thus reducing the cladding stress concentration.

In a study by Roberts and Wrona⁽³⁵⁾ on the deformation and fracture behavior of mixed-oxide fuel, the authors pointed out the advantages of a weak fuel in a fast reactor. A strong fuel, they contend, may lead to explosive cracking which can be disastrous in maintaining fuel rod integrity. This explosive cracking may cause fragmentation and relocation of the fuel column, and exaggerated fuel-cladding mechanical interaction. They propose to use the inherent weaknesses of the fuel (impurities and porosity) to improve their thermal-shock-damage resistance. The ideal fuel then would have low values of strength and high values of Young's modulus of elasticity.

Although Aas⁽²⁵⁾ noted that one way to reduce the cladding circumferential strain may be to lower the pellet density,

a number of trade-offs would have to be evaluated before this method could be considered for use. It would be necessary to demonstrate the physical stability of any low density fuel concept because of the concern about densification.

Increasing the fuel density would lead to improved thermal conductivity, reducing fuel temperatures, fission-product release and stored energy. However, these advantages might be offset by the increase in fuel strength and decrease in creep rates which result in larger general cladding strains.

Chubb et al.⁽⁴¹⁾ have stated that pellets in which the enrichment is varied radially could lead to reduced swelling. Depending on the design, such a pellet could lead to lower fuel temperatures and reduced hourglassing.

Cladding with a ribbed inside surface was tested in the R2 Reactor at Studsvik. Mogard et al.^(14,18) have reported results which indicate that ribbing or undulating the cladding inside surface has the potential for reducing the fuel-cladding-interaction problem.

Cladding properties having a major influence on mechanical interaction include: strength, ductility, creep, strain hardenability, strain rate sensitivity, and ovality. Ideally the cladding should be strong enough to withstand the localized stresses but ductile enough to accommodate such stresses by yielding. According to Aas⁽²⁵⁾ and Pickman,⁽⁵⁵⁾ annealed Zircaloy with a texture where the basal poles are predominantly radially oriented has the best combination of strength and ductility. (This texture is associated with the favored circumferential hydride orientation.) Fully annealed, recrystallized Zircaloy cladding is discussed further in the following material.

Increasing cladding strength and improving the strain hardening properties are two methods of reducing the mechanical interaction problem; however, new alloys would have to be developed to achieve these goals. If cladding strength is increased, one model, reported by Notley, et al.⁽⁴⁰⁾ predicts diametral expansion of the fuel at the expense of axial expansion, although experimental evidence to support this is sparse. Section 4.4.2 suggests that the stress threshold for SCC may be proportional in some way to the strength of the cladding. In discussing cladding instability, Aas⁽²⁵⁾ indicated that the maximum tolerable strain is usually taken to be equivalent to the strain-hardening coefficient.

Cladding creep is of greater concern in PWR fuel rods than in BWR fuel rods. If the creep strength of PWR fuel-rod cladding is not sufficient to prevent cladding collapse then, as noted by Aas,⁽²⁵⁾ prepressurization becomes mandatory.

Ultimately it may turn out that strain-rate sensitivity (see Sections 4.2.2.1 and 4.4.1), rather than ductility, is the significant factor in cladding behavior during power ramps. A method for making strain rate sensitivity less of a problem might be to control the interstitial impurities. Such an impurity is oxygen; lowering the oxygen content lessens the strain-rate sensitivity problem but also reduces cladding strength.

Close control of cladding ovality would lessen the interaction problem, according to Aas.⁽²⁵⁾ Initial cladding ovality can affect how rapidly the cladding can creep down onto the fuel and can result in large strain increases for otherwise small power increases. Ovality has been noted in many cases (e.g., diameter increases of more than twice the average increase have occurred in some irradiated fuel). In such cases the maximum plastic strains are much larger.⁽²⁵⁾ In examining Obrigheim fuel rods that had been subjected to power ramps, no systematic correlation

to the failure probability was found by Holzer et al.⁽⁵⁾ except that fuel rods using a cladding lot with extremely low ovality after irradiation had no failures.

The cladding radius-to-wall thickness (r/t) ratio could be optimized principally in regard to time-independent strains (creep strains may not be changed significantly), if a number of technical trade-offs were considered. General and localized strains before and during a power ramp would be lowered with thicker cladding. According to Lustman,⁽²⁴⁾ the thicker the cladding the less likely fatigue loadings will occur. Davies et al.⁽²²⁾ and Bain et al.⁽¹⁰⁶⁾ indicated that changing to thick-walled cladding did not eliminate defects in U.S. reactors or change the circumstances under which they occurred.

The process (e.g., crack nucleation) by which the cladding ultimately develops a breach may be influenced by the initial, as-fabricated condition of the cladding. Three heat treatment possibilities are described below.

Stress-relieved (fully recovered), nonrecrystallized cladding has been heat treated for short times (2 to 4 hours) at temperatures sufficiently low [440°C (825°F)] to preclude any recrystallization and to increase the tensile ductility^(a) to a significant fraction of that of the fully annealed, fully recrystallized condition while preserving most of the tensile strengthening due to cold working.^(107,108) Fully recovered, noncrystallized cladding would have a higher strength and, possibly, a lower creep rate than stress-relieved, partially recrystallized cladding.^(56,57,107,108)

(a) It should be noted that the "total tensile elongation" and "reduction in cross-sectional area" do not differ greatly for any condition ranging from fully cold worked to fully recrystallized. The so-called uniform tensile elongation, however, may vary significantly.⁽⁵⁶⁾

However, there is some doubt as to whether the creep strength of fully recovered, nonrecrystallized cladding in a fast neutron flux environment is significantly different from cladding in either a partial or fully recrystallized condition.^(56,57,109) There is no evidence to suggest that at fluences greater than about 1×10^{24} neutrons/m² [for neutron energies ~ 0.16 pJ (~ 1 MeV)] that the susceptibility to iodine stress-corrosion cracking and/or fission-product embrittlement (by elements such as Cd, Cs, etc.) of this material is any different than that for cladding in the partial or fully recrystallized condition.^(29,69,90) "Radiation hardening" tends to saturate at fluences greater than about 1×10^{24} neutrons/m² [for neutron energies ~ 0.16 pJ (~ 1 MeV)] and tensile properties, as measured in postirradiation examinations, for this cladding do not differ significantly from those for irradiated cladding in the partially recrystallized condition.⁽⁵⁶⁾

Stress-relieved, partially recrystallized cladding has been heat treated for short times (~ 2 to 4 hours) at temperatures [$\sim 510^\circ\text{C}$ ($\sim 950^\circ\text{F}$)] where partial recrystallization of the cold-worked microstructure occurs and results in a further increase (i.e., compared to stress-relieved, nonrecrystallized cladding) in tensile ductility (see footnote, page 69) while still preserving much of the tensile strengthening due to cold working.^(107,108) Again, there is considerable doubt as to whether the creep strength of this cladding in a fast neutron [i.e., neutron energies ~ 0.16 pJ (~ 1 MeV)] environment is significantly different from that of cladding in the stress-relieved, nonrecrystallized or the fully annealed, recrystallized condition.^(56,57,109) Mogard et al.⁽¹⁴⁾ compared the ramp failure resistance of stress-relieved and recrystallized cladding and found no essential difference between the two heat treatments. Small temperature variations during heat treatment are of more concern with stress-relieved,

partially recrystallized cladding than with stress-relieved, nonrecrystallized or fully annealed, fully recrystallized cladding due to the possibility of introducing some variation in cladding properties (e.g., within a single piece of cladding or in a cladding lot). This possibility comes about because the slope of the curve of tensile strength versus heat treatment temperature is steeper in the region of $\sim 510^{\circ}\text{C}$ ($\sim 950^{\circ}\text{F}$) than in the regions near $\sim 440^{\circ}\text{C}$ ($\sim 825^{\circ}\text{F}$) or $\sim 565^{\circ}\text{C}$ ($\sim 1050^{\circ}\text{F}$).^(107,108) There is no evidence to suggest that this cladding is any more or less susceptible to iodine stress-corrosion cracking and/or fission-product embrittlement after irradiation to a fluence greater than about 1×10^{24} neutrons/m² [for neutron energies $\gtrsim 0.16$ pJ ($\gtrsim 1$ MeV)] than cladding in the nonrecrystallized or fully recrystallized condition. In regard to "radiation hardening," the tensile properties of this cladding, as measured in post-irradiation examinations, do not differ significantly from those of irradiated cladding in the stress-relieved, non-recrystallized condition.⁽⁵⁶⁾

Fully annealed, recrystallized cladding has been heat treated for short times (~ 1 to 4 hours) at temperatures [$\sim 565^{\circ}\text{C}$ ($\sim 1050^{\circ}\text{F}$) or greater] to cause full recrystallization of the cold-worked microstructure, resulting in maximum tensile ductility (see footnote, page 69) and minimum tensile strength. The creep strength of this cladding in a fast neutron [i.e., neutron energies $\gtrsim 0.16$ pJ ($\gtrsim 1$ MeV)] environment may, however, be as great as for cladding in any of the cold-worked and/or stress-relieved conditions.^(56,57,109) In regard to "radiation hardening," the "saturation" tensile strength may be somewhat less for this cladding than for the cladding in the cold-worked or stress-relieved conditions.⁽⁵⁶⁾ There is no evidence to suggest that cladding in this condition is any more or less susceptible to iodine stress-corrosion cracking and/or fission-product embrittlement. However, Pickman⁽⁸⁰⁾ indicated that

from a materials viewpoint, the measure that most likely will give maximum immunity to the fuel rod power-ramp problem involves using a high stress-relieving temperature [typically $>520^{\circ}\text{C}$ ($>970^{\circ}\text{F}$)] or full annealing and, for added benefit, using a surface protective coating (e.g., graphite). Studies by Hannerz and Vesterlund⁽¹⁰²⁾ indicated that the use of fully annealed cladding is favored. *In comparison to stress-relieved, partially recrystallized cladding, some improvement in resistance to SCC may be anticipated with fully annealed, recrystallized cladding.*⁽⁶⁹⁾

Zirconium alloys with superior in-reactor creep strength may be desirable because they would be expected to reduce cladding strain and, possibly, the SCC susceptibility. As reported by Liebowitz,⁽¹¹⁰⁾ Cubicciotti and Jones,⁽¹¹¹⁾ Reinoehl and Boyd,⁽⁸²⁾ and Wearmouth et al.,⁽⁸³⁾ there appears to be increasing evidence that inelastic straining--time dependent and/or time independent--is probably the mechanism by which cracks nucleate and subsequently grow in an aggressive chemical (e.g., iodine) environment. Based on these considerations and the fact that the creep strength of the Zircalloys is relatively low in a fast neutron [i.e., neutron energies >0.16 pJ (>1 MeV)] flux, any zirconium alloy with significantly superior in-flux creep strength may be less susceptible to iodine stress-corrosion cracking. Development and in-flux creep testing of potential candidate alloys would be expensive and time-consuming. There are no experimental data to suggest whether any candidate alloys would be less susceptible to fission-product embrittlement than the Zircalloys. It is suspected, however, that fission-product embrittlement may influence the mode of failure (i.e., axial split instead of pinhole) far more than the stress/strain threshold for failure.

Postirradiation examinations of cladding on fuel rods that failed because of fuel-cladding interaction frequently show

the presence of several to many part-through wall cracks that initiated at or near the ID surface of the cladding. Considering that the fuel-cladding-interaction failures appear to occur only on ramp increases in fuel-rod power, there is little doubt that the cracks observed occur as a result of tensile stresses/strains at the ID surface of the cladding. Crack growth and propagation are generally acknowledged to occur only under the action of tensile and/or shear forces. All experiments to date show iodine stress-corrosion cracking in the Zircalloys to occur only when stressed/strained in tension. Based on these considerations, the presence of a residual compressive stress state in the ID surface of the cladding may be expected to reduce the tendency for crack nucleation and growth at or near the ID surface, even in the presence of fission-product iodine or Zircaloy-embrittling, fission-product species.

Wood⁽⁸⁶⁾ indicated that treatments that decreased the tensile stresses at the cladding ID included roller straightening, shot peening, and irradiation to a low fluence of fast neutrons. The tendency for stress-corrosion cracking in iodine vapor was reduced by these treatments.

Fuel-cladding-interaction failure observations suggest that there may be two distinct types of failure. They are "pinhole" failures and "axial split" failures. Postirradiation examination efforts, to date, have given scant attention in such observations as to the physical attributes of the two (?)^(a) types of failures. There are some observations, however, which support the notion that the mode of failure may differ. X- and V-band markings on the cladding surface at pinhole failures suggest that the failure may be due to shear

(a) It is not clearly understood yet whether two distinct types of failures exist. It may be that "pinhole" failures are mini-"axial split" failures.

rupture. It is conceivable that manufacturing defects, even though they may be quite small, may in some cases be the site and origin of the pinhole type failure. There appears to be little question but that either the "pinhole" or "axial split" mode of failure occurs under tensile stress/strain conditions. If so, there appears to be some benefit in peening (e.g., shot-peening with nonabrasive materials) the ID surface of the cladding so as to attain a substantial residual compressive stress state. Considering the in-flux creep and stress-relaxation characteristics of the Zircalloys, shot-peening may begin to lose some of its effectiveness at intermediate and high burnups. Shot-peening methods, however, are simple and relatively cheap and may provide some other benefits (e.g., improved fatigue properties).

It has been shown by Gittus^(31,63) that friction, due to contact of a pellet with an adjacent cracked pellet, can propagate the crack across the interface. Therefore, a reduction of the friction at the pellet-pellet interface might reduce the interface crack propagation and thus the pellet-cladding interaction. Possible ways to reduce this friction as suggested by Gittus, were to coat pellet ends with graphite or siloxane coatings, or use a soft metal interlayer on the cladding ID.

According to Hardy et al.,⁽⁷⁸⁾ graphite coatings between the fuel and Zircaloy cladding have been employed in Canadian fuel. Siloxane coatings are also being studied. Graphite reduced the number of fuel-rod failures due to fuel-cladding interaction. The graphite layer functioned in several ways: the lubricating qualities lowered pellet-cladding friction and the resultant stress, fission products (e.g., iodine) were absorbed or adsorbed, and the layer formed a barrier to fission products. Thicker graphite coatings did more in the

way of reducing failures. Graphite and siloxane are suggested in Section 4.5.2 as means of inhibiting SCC.

According to Scandpower, Inc.,⁽²⁶⁾ using larger rod arrays of fuel to reduce the individual rod heat-rating is the most promising of corrections to reduce the number of fuel-rod failures.

One fuel assembly modification that apparently has not been given much consideration to date is the use of fuel-rods of different diameters in the same assembly.

Two carbide fuel assemblies were successfully tested in EBR-II as reported by Kerrisk et al.⁽¹¹²⁾ These assemblies were a new type, using shrouds. Earlier carbide fuel designs had a high frequency of cladding breach because the fuel tended to swell and strain the cladding. The shroud is a stainless-steel screen placed around the inside of the cladding. The screen prevents fuel from exerting any mechanical forces on the cladding that could lead to cladding failure.

The results of various remedial measures to prevent power-ramping defects have been reported by the Canadians Robertson and Bain et al. in 1972,⁽¹¹³⁾ 1973,⁽¹²⁾ and 1975.⁽⁸⁷⁾ Robertson⁽⁶⁾ reported in 1977 that there are four causes of pellet-cladding interaction (PCI). The four causes (also three manufacturing defects) and their remedies, as discussed by Robertson, are:

<u>PCI Causes</u>	<u>Remedies</u>
1. rod elongation	1. allow adequate space for elongation 2. distribute longitudinal clearance 3. fuel rod design modifications 4. control cladding texture
2. fuel densification	1. high fuel density 2. thick-wall cladding

	3. stable fuel structure
	4. internally pressurized rods
3. cladding fatigue	1. fuel rod design modifications
	2. limits on power cycling
4. power ramp failures	1. appropriate fuel management
	2. fuel rod design modifications
	3. internally pressurized rods
	4. modified fuel pellet geometry
	5. cladding annealing
	6. fuel-cladding interlayers

<u>Manufacturing Defects</u>	<u>Remedies</u>
1. faulty components	1. good quality control
	2. nondestructive testing
2. faulty contents	1. maintain cleanliness
	2. adequate drying of fuel
	3. hydrogen getters
3. faulty assembly	1. good quality control

Other remedial actions for fuel-cladding mechanical interaction are noted in Section 4.8 (e.g., patents on liners, coatings, additives). Remedial actions (e.g., buffers, barriers, getters) to reduce cladding susceptibility to stress-corrosion cracking and fission-product embrittlement are described in Section 4.5.2 and Section 4.8.

4.5.2 Remedial Actions for Chemical Reactions

It is important to eliminate or very substantially impede contact and/or condensation of those aggressive fission products which promote stress-corrosion cracking (iodine in particular) or are embrittling species (e.g., cadmium, cesium, etc.) on the Zircaloy in the fuel-cladding interface region. Remedies which are effective against SCC are also expected to be generally

effective against fission-product embrittlement. Minimizing or eliminating the stress and/or strain localization in the cladding resulting from fuel-cladding thermal-mechanical interaction is also important. However, some studies by Ranjan and Smith^(2,65) indicate that fuel-cladding friction effects, which lead to stress and/or strain localization, appear to be of second order importance in producing the threshold stress for SCC in the cladding. Minimizing the radial temperature gradient in the fuel would reduce the thermal-mechanical driving force for fuel-cladding interaction, as well as reduce the release of aggressive fission products from the fuel. Cubicciotti et al.⁽⁷⁴⁾ have stated that the release of fission products could be reduced by lowering fuel temperatures. Rod powers have been lowered recently by using 8 x 8 rod arrays in BWRs and 17 x 17 rod arrays in PWRs; however, further reducing of fuel rod powers to obtain lower fuel temperatures does not appear economically viable.

According to Holzer et al.,⁽⁵⁾ the release of fission gases (and presumably volatile fission products such as cesium) is influenced by fuel design. Changes in porosity, grain size, O/M ratio, density, or cracking behavior can alter the gas release. Of those, the first two are the easiest to put into practice.

Cubicciotti et al.⁽⁷⁴⁾ have suggested the inclusion of getters in the fuel rods for retaining aggressive fission products. However, there is a tendency for the getter materials to be effective for only specific fission products. Additives such as Al_2O_3 or TiO_2 might retain cesium. Cesium might also be retained in the fuel if additives were used to maintain a high oxygen potential. Molybdenum oxide probably buffers the fuel oxygen potential.

As noted by Foerthmann et al.,⁽¹¹⁴⁾ reduction in the amount of long-lived solid fission products such as barium, strontium

and cesium is very important in high temperature gas-cooled reactors (HTGRs) because these substances can react with the HTGR fuel particle cladding. It has been shown in two irradiation experiments that alumina-silica additives to pyrocarbon-coated particles can reduce the release of such harmful products by orders of magnitude. This retention of the fission products is accomplished by the formation of stable aluminosilicates: $\text{SrAl}_2\text{Si}_2\text{O}_8$, $\text{BaAl}_2\text{Si}_2\text{O}_8$, and $\text{CsAlSi}_2\text{O}_6$.

Cubicciotti et al.⁽⁷⁴⁾ indicate that getters for iodine are more difficult to devise because cesium itself is a metal which is very reactive towards iodine. One possibility would be to introduce an additive that forms a more radiation-stable iodide, possibly as a ternary compound with Cs and I (e.g., an added metal M might form a compound such as $\text{Cs}_x\text{M}_y\text{I}_z$ that combines the I in covalent bonds between M and I as contrasted to the ionic bonds in CsI). It may be possible to devise getters for other specific and potentially aggressive fission products, but even if these were retained there could be other aggressive agents present.

Gulbransen and Jansson.⁽¹¹⁵⁾ noted that Ta, Ti, Ce, Th, Hf and Zr are well known gettering materials.

Fee et al.⁽¹⁰⁰⁾ described the use of getters to control the oxygen potential as a means of eliminating attack on the stainless-steel cladding. As reported by Ewart et al.⁽⁹⁹⁾ for $\text{UO}_2\text{-PuO}_2$ fuel with stainless-steel cladding, oxygen potential tends to be the key parameter for controlling pellet-cladding chemical reaction.

Cubicciotti et al.⁽⁷⁴⁾ have suggested barriers to prevent deposition of fission products on the cladding. Liners, barriers, foils, coated liners, and cladding coatings have been patented.⁽¹¹⁹⁻¹²⁵⁾ Multifunctional coatings (graphite

and siloxane)^(a) have been used by the Canadians.⁽⁶⁹⁾ Lubricating layers have been patented by Klepfer.^(123,124) AECL studies, reported by Hardy et al.,⁽⁷⁸⁾ indicated that thicker graphite coatings on the cladding inner surface reduced the number of failures with power-ramped fuel. Pickman⁽⁸⁰⁾ noted that graphite and siloxane coatings tend to prevent SCC. It is suggested that the coatings inhibit SCC by metering the hydrogen that reach the cladding surface. [The hydrogen migrates to regions of high stress (e.g., at the tips of small cracks), reducing the stress and arresting crack growth.]

Another possible way of preventing aggressive fission product reaction with the cladding would be to retain the fission products in the fuel. Gibby and McClanahan of HEDL⁽¹²⁶⁾ have reported the development of a sputtering deposition process for applying metallic coatings (Cr, Nb, V, and Ti) on either the ends or circumferences of LMFBR UO_2 - PuO_2 fuel pellets. The TRISO fuel particles of interest to the HTGRs are fabricated with a SiC coating to retain the fission products.

Cubicciotti et al.⁽⁷⁴⁾ have noted that one solution might be to improve the protective capability of the oxide layer on the Zircaloy. The oxide layer is self-healing in an oxygen-rich environment; however, a fuel rod interior is oxygen poor. A possible remedial action is to devise an additive, inside the fuel rod, of a metal oxide that acts as buffer (i.e., keeps the oxygen potential sufficiently high that the oxide layer on the cladding maintains its protective characteristics.

Cladding with special ID surface properties may be helpful because fuel-cladding interaction appears to be initiated at

(a) The lubricant was silicone vacuum grease (polydimethyl-siloxane containing a suspension of finely divided silica).⁽⁶⁹⁾ Siloxanes are chain compounds consisting of Si-O backbones with two alkyl or aryl side chains attached to each Si atom.

the ID surface of the cladding. Based on this consideration, there may be ID surface treatments that would inhibit and/or retard the initiation of those mechanisms which ultimately lead to cladding failure. Potential ID surface treatments include:

- 1) elimination, by mechanical and/or chemical polishing, of ID surface imperfections which may act as the sites for crack nucleation and/or promote or otherwise enhance local chemical attack,*
- 2) microstructural and/or chemical alteration of the ID surface oxide film to impart plasticity and allow it to deform with the cladding without loss of integrity. [Tests conducted by Wood⁽⁸⁶⁾ (and noted by Pickman⁽⁸⁰⁾) with irradiated cladding suggest that the form of oxide on the bore surface influences cracking susceptibility.]*
- 3) surface coatings (mechanical and/or chemical) which may inhibit and/or retard local chemical attack.*

As yet there appear to be very few, if any, specific surface treatments, excluding coatings and barriers, which can be identified as providing any demonstrably significant inhibition to local chemical attack and/or otherwise reducing the probability of pellet-cladding interaction.

Analyses and a few power-ramp tests reported by Mogard⁽¹⁸⁾ indicated that undulating the cladding inner surface suppresses the formation of defects induced by pellet-cladding interaction.

In-reactor tests with BWR fuel rods, reported by Davies et al.,⁽²²⁾ showed that the susceptibility to pellet-cladding, interaction-induced failures is not a strong function of conventional design variables (e.g., cladding thickness).

According to Lustman,⁽²⁴⁾ the thicker the cladding, the less likely it is that fatigue loadings will occur.

The cladding stress threshold for SCC may be proportional to the strength of the cladding.

Optimizing the cladding texture might provide a useful increase in resistance to SCC. Studies (e.g., those by Garlick and Gravenor⁽⁶⁸⁾) have shown that the susceptibility of Zircaloy to SCC varies with texture (grain orientation).

4.6 Fuel-Cladding-Interaction Mechanistic Considerations

As can be noted elsewhere in this report, some investigators described areas that are particularly pertinent to an understanding of the mechanism(s) involved in the fuel-cladding-interaction phenomenon. Some of the more significant considerations are described below.

4.6.1 Thermal-Mechanical Interactions

4.6.1.1 Fuel-Related Considerations

In estimating the plastic circumferential deformation of the cladding, Kjaerheim and Rolstad⁽³⁰⁾ noted that it is particularly difficult to calculate the fuel expansion because of the temperature gradient and variation in fuel plasticity across the fuel cross-section. Deformation predictions should be verified by experiments because diametral and longitudinal expansions are interdependent.

The amount of tensile stress that a fuel pellet can sustain before cracking occurs is not well defined.⁽³⁰⁾ Pellet cracking due to handling and shipping of the fuel assembly is unpredictable.

Fission-product-induced swelling of the fuel is dependent upon the operating conditions, according

to Lyons et al.⁽³³⁾ The solid fission-product swelling may be sensitive to the oxygen-to-metal (O/M) ratio of the fuel.

In discussing gaseous fission-product swelling, Lyons et al.⁽³³⁾ indicated that each of the available fission-product swelling models utilizes material property data that may not be well defined and/or may have some mechanistic deficiency.

According to Holzer et al.,⁽⁵⁾ verification is required to show that a reduction in fission-product release during a transient is possible by modifying the fuel microstructure.

It is usually assumed that the release of volatile fission products (i.e., the aggressive ones of concern in SCC and/or FPE) is proportional to the release of fission gases.⁽⁵⁾

As noted by Homan,⁽⁴⁶⁾ an important factor in predicting the extent of fuel-cladding mechanical interaction is reducing the uncertainty in fuel creep data. As pointed out by Seltzer et al.,⁽⁴⁷⁾ another possible factor is the effect of porosity on fuel creep rates, both in low-stress and high-stress creep regions.

Hoffman et al.⁽⁶⁰⁾ studied annular pellet behavior and indicated that the annular configuration appeared to affect the shape distortion (hourglassing) of the cylindrical body in a manner that was different than that for solid pellets.

4.6.1.2 Cladding-Related Considerations

One computer model, reported by Notley et al.,⁽⁴⁰⁾ predicts diametral expansion of the fuel at the

expense of axial expansion if the cladding strength is increased.

Pickman⁽⁵⁵⁾ reported that the cladding creep rate increases under irradiation. The trend of the change in cladding creep properties is known, but uncertainties (e.g., an initial ovality, temperature, axial power profile) still exist in the data.

Primary, rather than secondary, creep is important in fuel-cladding-interaction analyses, according to Lustman⁽²⁴⁾ and Pankaskie.⁽⁵⁶⁾ More in-reactor and out-of-reactor data on Zircaloy primary creep are needed.

In comparing stress-relieved, nonrecrystallized, stress-relieved, partially recrystallized, and fully annealed, recrystallized cladding, there is some doubt as to whether there is any significant difference between their creep strengths in a fast neutron environment.

For fluences greater than about 1×10^{24} neutrons/m² [for neutron energies $\gtrsim 0.16$ pJ ($\gtrsim 1$ MeV)], there are no data to suggest that there is a difference in the susceptibility to SCC and/or FPE between stress-relieved, nonrecrystallized, stress-relieved, partially recrystallized, and fully annealed, recrystallized cladding.

Zirconium alloys with improved in-reactor creep strength may be helpful, but there are no data to indicate whether such alloys would be any less susceptible to FPE than the Zircaloys.

The actual stress in the cladding in the fuel-cladding interface region is one of the parameters used in cladding design life predictions. As

Meinhardt⁽⁵⁹⁾ points out, this stress is inferred from fuel-rod performance models because it is impractical to measure it.

In studies by Proebstle et al.⁽¹¹⁸⁾ on internal hydriding of Zircaloy cladding, it was indicated that the mechanism for the breakdown of the protective oxide film on the cladding inner surface is not well defined.

4.6.1.3 Fuel-Rod-Related Considerations

Hann et al.⁽³⁴⁾ reported that after volatile impurities are released inside the fuel rod, the disposition of those gaseous impurities is not well understood.

Aas⁽⁶¹⁾ concluded that an understanding of fuel-rod internal chemistry is important in order to evaluate fuel-cladding-interaction effects.

The conditions under which a fuel rod deforms and the cladding develops a breach are important to the quantitative understanding of the effects and their relationships, according to Aas.⁽²⁵⁾

Aas⁽²⁵⁾ and Meinhardt⁽⁵⁹⁾ concluded that for reliable analyses of the in-reactor pellet shape and cladding ridge heights, well-defined ridges and accurate ridge dimensional data are needed.

Postirradiation examinations of fuel rods that failed because of fuel-cladding interaction suggest that there may be two distinct types of failures, i.e., "pinhole" and "axial split," which may have different physical attributes. Holzer et al.⁽⁵⁾ indicate that

stress- and fission-product availability may be reciprocal, in general, and that a high concentration of fission products coupled with a low stress may lead to a pinhole failure, whereas a high-stress situation may produce a crack type failure (i.e., axial split).

Fuel-cladding interfacial bonding may affect the results of fuel-rod power-ramp tests, according to Aas.⁽⁶¹⁾

4.6.2 Chemical-Reaction-Related Considerations

Proebstle et al.⁽¹¹⁸⁾ reported that it has been unequivocally established that the fuel rod's internal chemical environment has an important influence on fuel-cladding interaction failures. Cubicciotti et al.⁽⁷⁴⁾ found that the cladding oxidation rate is affected by the conditions that are present in a fuel rod.

Data are being obtained on the chemical elements present on the inner surfaces of irradiated fuel-rod cladding.⁽⁷⁴⁾

It is difficult to separate an SCC failure from a purely mechanical failure because the regions of highest strain and the most aggressive corrosion coincide in location, as reported by Scandpower.⁽²⁶⁾

As noted in Section 4.4, the data base supports a threshold-stress concept, although some plastic strain is needed for SCC. *It has not yet been clearly shown experimentally which material parameter--stress, strain, strain rate (creep)--most uniquely defines the threshold for SCC. Apparently there is little information to determine whether or not there is a critical strain for crack initiation.* Reinoehl and Boyd⁽⁸²⁾ and Wearmouth et al.⁽⁸³⁾ reported that some data

(for materials other than Zircaloy) indicate that SCC only occurs within a narrow range of strain rates.

Roberts et al.⁽⁸⁴⁾ concluded that the relative contributions of stress and chemistry to SCC need better definition.

According to Cubicciotti et al.,⁽⁷⁴⁾ refinements in the thermodynamic data and in the present knowledge of the true chemical states of fission products in UO_2 will improve predictive capabilities.

There are few available measurements on the oxygen potential of the fuel.⁽⁷⁴⁾

In assessing the chemical states of fission products, calculations are based on the reaction between pure metal with oxygen at one atmosphere to form pure oxides. This may be different than the situation existing in the actual fuel rod (i.e., fission products in a UO_2 matrix).⁽⁷⁴⁾

It would be desirable to develop means to control the release of cesium. This would be affected by the chemical form of cesium when it is released. Data are being obtained on the aggressiveness of cesium vapor toward Zircaloy.

The chemistry of tellurium (also selenium) with respect to its behavior in fuel rods is not well defined.⁽⁷⁴⁾

Tellurium and selenium are most likely released from fuel as Cs_2Te and Cs_2Se .

If one exists, the threshold temperature(s) at which fuel releases fission products is not well defined.⁽⁷⁴⁾ Cubicciotti et al.⁽⁷⁴⁾ and Olander⁽⁹²⁾ presumed that fission products (e.g., cesium) are released during temperature transients in a fashion similar to that for fission gases (Xe, Kr).

Zircaloy is embrittled by some of those fission products and impurities observed to form at the fuel-cladding interface of irradiated LWR fuel rods.⁽⁷⁴⁾

The strain-rate dependence of cadmium embrittlement of Zircaloy is not well defined, according to Grubb and Morgan.⁽¹⁰³⁾

According to Syrett et al.,⁽¹⁰⁴⁾ the contribution of iron and the relative effects between iron and cesium on the embrittlement of Zircaloy-4 are not well defined.

Mogard et al.⁽¹⁴⁾ reported that there is a distinct difference between the linear heat ratings required to produce similar power ramping results from test reactors and from power reactors. Postulated fuel-cladding interfacial effects, described in Section 4.1, are being investigated (such a study is underway in the Inter-Ramp Project, described in Section 4.7, below).

At present, the changes in localized power which frequently occur in reactors are not monitored with sufficient accuracy to permit development of a detailed understanding of the fuel-cladding-interaction phenomenon or to accurately predict the effects of fuel-cladding interaction. Improved information on reactor operating histories and postirradiation examinations would be helpful; for example, it may permit determination of which series of BWR control blade movements lead to the observed fuel failures.

4.7 Ongoing Programs

Strasser and Linquist⁽⁸⁾ note that additional operating experience is being accumulated with the recently designed, reduced power BWR and PWR fuel rods. Current experience with such 8 x 8 as well as modified 7 x 7 fuel rod arrays in BWRs is based on about 250,000 fuel rods. Only a limited number of PWRs are operating with such

16 x 16 and 17 x 17 fuel rod arrays, and the current PWR experience base involves about 150,000 fuel rods.

The LWR Fuel Performance Program of the Electric Power Research Institute (EPRI) described by Roberts et al.⁽⁸⁴⁾ is of particular interest. The program involves 20 research projects and the research is limited to Zircaloy-clad UO_2 and UO_2 - PuO_2 fuel. The primary emphasis in the fuel rod studies is on pellet-cladding interaction.

Proebstle et al.⁽⁴⁾ indicate that one of the advanced concepts tested by General Electric Company is graphite-coated, fuel rod cladding. For the ramp-test sequence with zero-burnup fuel rods employed by GE in a particular test series, the graphite coating appeared to yield no beneficial effects; however, some other concepts in the series were tested and apparently did provide immunity to fuel-cladding interaction.

Pitek and Rolstad^(127,128) indicate that Northeast Utilities (NU) with its fuel suppliers and outside consultants are investigating operating strategies for its BWR and PWRs. NU and Sandpower, Inc., are cooperating on a study of the pellet-cladding-interaction problem that involves a power history tracking effort and predictions of the probability of failure of fuel based on the Scandpower fuel failure model, POSHO-1.

The Studsvik Inter-Ramp Project commenced in 1975 and is to last 3-1/2 years, according to Mogard et al.⁽¹⁴⁾ It is an international cooperative project involving overpower ramping tests with standard BWR-type fuel to investigate the failure propensity and characteristics of such fuel under those test conditions. The associated pre-ramp, steady-state irradiations and the ramping tests are being conducted in the Studsvik R2 Reactor.

Mogard et al.⁽¹⁴⁾ also indicate that the Studsvik Over-Ramp Project is presently being organized. It is another international cooperative project that will end in 1979 involving over-power ramping tests with standard PWR-type fuel, but differs from the Inter-Ramp Project in that the pre-ramp steady-state irradiation occurs in power reactors (Obrigheim and Br-3 presently involved).

Videm and Lunde⁽⁷²⁾ recently described studies underway at the Institute for Atomenergi in Norway. Stress-corrosion cracking of Zircaloy cladding under ramp tests and in laboratory tests is being investigated, and one tool being used is fractography. They also state that the Halden Project has drawn up a program to investigate initiation and growth of cracks as functions of operating conditions and design variables.

Ramp testing of BWR fuel (irradiated in Oskarshamn I) in the R2 reactor is still in progress according to Mogard et al.⁽¹⁴⁾ Also, the first phase of the program for the ramp testing of BWR fuel (irradiated in Kahl) has been terminated. Several fuel design concepts are also being ramp tested; one concept involves the internally ribbed cladding. Mogard⁽¹⁸⁾ recently described the study on suppressing pellet-cladding interaction (PCI) by incorporating ribs (i.e., light undulations) on the bore surface of the fuel-rod cladding.

A series of controlled power ramp tests with PWR test fuel rods are underway at RISØ in Denmark, and Knudsen et al.⁽⁹⁾ have reported on the results of two tests in that series. The investigators believe that these are the first published results from ramp tests with well-characterized, PWR-type fuel rods and a detailed post-test evaluation.

During the panel discussion, Knudsen⁽¹²⁹⁾ also mentioned that RISØ studies on the pellet-cladding-interaction phenomenon involve an investigation of a dual-enrichment fuel concept, the low-interaction (LOWI) pellet design.

Ramp tests with vipac fuel rods^(a) and high-burnup pellet fuel rods in the DR3 reactor were also described recently by Knudsen et al.⁽⁸⁸⁾ The results for vipac fuel rods are reported and evaluated in a fashion similar to that for pellet fuel to document ramp performance and feasibility of analysis for this type of fuel.

Junkrans and Värnild⁽¹⁷⁾ recently reported that the pellet-cladding-interaction research studies by ASEA-ATOM (mostly together with AB Atomenergi of Sweden) are continuing. More than 200 test rods of various designs were irradiated in the Agesta PHWR, and a large number of fuel rods (more than 20 different designs) have been irradiated so far in Oskarshamn-1. Ramp testing of the fuel rods has been performed in R2 at Studsvik and also in Oskarshamn-1. Current research is aimed at 1) optimizing fuel designs with regard to pellet-cladding interaction and refining operating recommendations, and 2) developing fuel designs that resist pellet-cladding interaction.

Hardy et al.⁽⁷⁸⁾ stated recently that AECL is pursuing a fuel development program for Canada Deuterium Uranium-Pressurized Heavy Water (CANDU-PHW) fuel and that over 200 fuel bundles and 400 individual fuel elements have been irradiated since 1967. Included in the testing was CANLUB fuel, i.e., fuel with a graphite coating on the inner surface of the cladding. Bain et al.⁽¹²⁾ reported in 1973 that CANLUB coating was specified for all Pickering reload fuel and fuel for the Bruce reactors. Wood and Hardy⁽²³⁾ indicated recently that AECL's Chalk River Laboratories have been conducting power-ramping tests and are currently studying the liquid-metal embrittlement of zirconium to determine its potential significance relative to SCC.

(a) Packed-particle fuel rods fabricated by the vibrational compaction process.

Holzer et al.⁽⁵⁾ indicate that Kraftwerk Union AG has a number of activities on ramp testing currently underway. The studies involve irradiations in the Obrigheim, Biblis-A, Würgassen, Petten, Studsvik R2, and Halden reactors.

Garlick and Gravenor⁽⁶⁸⁾ indicate that iodine pressurization tests have now begun in the UK with cladding that has a variety of bore defects.

4.8 Patents of Interest

In 1975, Ross and Williamson⁽¹¹⁶⁾ patented a getter that may be included inside a nuclear fuel element to reduce the amounts of water, water vapor, and gases such as hydrogen. The getter material is zirconium or a zirconium alloy (Zircaloy-2, -3 or -4) with fractions of niobium, titanium, nickel, yttrium or mixtures thereof. Because this getter material becomes coated with a zirconium-oxide film, which reduces the gettering efficiency, it is attached to a strip made of a metal substrate. The substrate contains nickel, a nickel alloy, a ferro-alloy, stainless steel, titanium or a titanium alloy. The getter material covers this substrate either partly or wholly on one or both sides. The substrate has a higher coefficient of thermal expansion than the getter material, to allow the zirconium-oxide film to be destroyed continuously and cracks to be formed in the coat. This reduces the negative effect on the efficiency of gettering.

In 1973, Grossman⁽¹¹⁷⁾ of General Electric Company patented an alloy of zirconium, nickel, and titanium as an addition to a fuel rod to aid in the nondestructive detection process. The alloy reacts with moisture and reactive gases and permits detection of those reaction products by neutron radiography. This class of alloys contains about 3-12 wt% Ni and about 3-30 wt% Ti with the balance being zirconium. The alloy reacts with water, water vapor, hydrogen-containing compounds such as hydrocarbons, and other gases (e.g., nitrogen, carbon dioxide, carbon monoxide, and oxygen).

In 1973, Gulbransen and Jansson⁽¹¹⁵⁾ of Westinghouse Electric Corporation patented a getter consisting essentially of a zirconium-base alloy with about 10 to about 30 weight percent tin. The alloy reacts with gases including oxygen, carbon dioxide, carbon monoxide, hydrogen, nitrogen and water vapor.

In 1977, Gordon and Cowan⁽¹¹⁹⁾ of the General Electric Company patented a nuclear fuel element with a metal liner and a diffusion barrier. Stainless steel, copper, copper alloys, nickel, and nickel alloys are the liner material choices. A chromium or chromium alloy coating is employed as the diffusion barrier either on the cladding inside surface or on the outside surface of the metal liner.

In 1976, Adamson, Aitken, and Rosenbaum⁽¹²⁰⁾ patented a coated metal liner for use in fuel elements. The metal lining (zirconium, molybdenum, tungsten, rhenium, niobium, or alloys thereof) has the surface facing the fuel coated with one or more additives. The additives could increase the fissile properties of the fuel (e.g., ²³⁹Pu, ²³⁵U, boron, gadolinium), control thermal properties (use getters like SiO₂ or SiO₂-Al₂O₃ compounds), or improve its mechanical properties.

In 1976, Thompson and Rowland⁽¹²¹⁾ patented a heat-conducting, fission-product-retaining, metal liner of a refractory metal incorporated in the fuel rod between the cladding and the nuclear fuel to inhibit mechanical interaction between the nuclear fuel and the cladding, to isolate fission products and nuclear fuel impurities from contacting the cladding and to improve the axial thermal peaking gradient along the length of the fuel rod. The metal liner can be in the form of a tube or hollow cylindrical column, a foil of single or multiple layers in the shape of a hollow cylindrical column, or a coating on the internal surface of the cladding. Preferred refractory metal materials are molybdenum, tungsten, rhenium, niobium and alloys of the foregoing metals.

In 1975, Thompson and Rowland⁽¹²²⁾ patented a fuel element (e.g., for a PWR or BWR) that contains an intermediate layer, e.g., a cylinder or a foil, between the fuel and the cladding. This intermediate layer inhibits the mechanical interaction between cladding and fuel, insulates the generated fission products from the cladding and improves the axial thermal gradient along the fuel rod. The intermediate layer or lining consists of a refractory metal, such as molybdenum, tungsten, rhenium, niobium, or their alloys. The cladding consists of zirconium, zirconium alloys, stainless steel, aluminum or aluminum alloys. With this combination of materials for cladding and lining, the fuel may consist of uranium compounds, plutonium compounds, or thorium compounds.

In 1975, Klepfer⁽¹²³⁾ patented a fuel element (e.g., for a PWR or BWR) that contains a lining and a lubricating layer between the fuel and the cladding. The lining consists of a material with a low neutron capture cross-section, such as zirconium, niobium or their alloys, and it serves as a preferred reaction site for volatile impurities or fission products from the fuel. The lubricating layer of graphite, molybdenum sulphide, or inorganic compositions with a laminar crystal structure reduces friction between the lining and cladding. There is no direct contact between the lubricating layer and the fuel, which consists of uranium or plutonium compounds, so excessive swelling or high internal gas pressure, due to carbon monoxide or dioxide, is prevented.

In 1974, Klepfer⁽¹²⁴⁾ patented a nuclear fuel element which comprises: 1) cladding, 2) a layer of high lubricity material disposed in and adjacent to the cladding, 3) a low neutron capture cross-section metal liner disposed in the cladding and adjacent to the layer, 4) a central core of a body of nuclear fuel material disposed in and partially filling the cladding and forming an internal cavity in the cladding, 5) an enclosure integrally secured and sealed at each end of the cladding, and 6) a nuclear fuel material-retaining means positioned in the cavity.

In 1974, Thompson and Rowland⁽¹²⁷⁾ patented a fuel element that involved a refractory metal liner.

There are some other patents that may be of some interest. Grossman, Kaznoff, and Clukey⁽¹³⁰⁾ of General Electric Company obtained a patent on the chemical immobilization of fission products reactive with nuclear reactor components (includes comments on additives, corrosion, inhibitors, fission products, etc.). Lysell⁽¹³¹⁾ obtained a patent on a method to avoid stress corrosion in fuel capsules in water-cooled reactors. A nuclear reactor fuel element and a process for its fabrication was patented by Spalthoff and Wilhelm⁽¹³²⁾ (includes comments on coatings). McDonald⁽¹³³⁾ obtained a patent on nuclear fuel elements (includes comments on coatings). Webb⁽¹³⁴⁾ patented a high-temperature, ceramic composition for hydrogen retention (includes comments on adsorption and coatings). Loriers et al.⁽¹³⁵⁾ have reported on the protection of zirconium and its alloys by metallic coatings.

5.0 REFERENCES

1. J. T. A. Roberts et al., "On the Pellet-Cladding Interaction Phenomenon." Nuclear Technology 35:131-144, 1977.
2. G. V. Ranjan and E. Smith, "Fracture of Zircaloy Cladding As a Consequence of Power Increases in Water Reactor Fuel Rods." Trans. of the 4th Int'l Conf. on Structural Mechanics in Reactor Technology, Paper C2/1, San Francisco, CA, 1977.
3. E. Smith, G. V. Ranjan, and R. C. Cipolla, Fracture of Zircaloy Cladding by Interactions with Uranium Dioxide Pellets in LWR Fuel Rods. EPRI NP-330, 1976.
4. R. A. Proebstle, W. E. Baily, and H. H. Klepfer, "Current Trends in Fuel Performance." Am. Nucl. Soc. Topical Meeting on Water Reactor Fuel Performance, St. Charles, IL, 1977.
5. R. Holzer et al., "Pellet-Clad Interaction: Experience, Testing, and Evaluation, A KWU Review." Am. Nucl. Soc. Topical Meeting on Water Reactor Fuel Performance, St. Charles, IL, 1977.
6. J. A. L. Robertson, "Nuclear Fuel Failures, Their Causes and Remedies." Proceedings of Joint Topical Meeting on Commercial Nuclear Fuel Technology Today, CNS ISSN 0068-8517 and 75-CNA/ANS-100, p. 2-3, Toronto, Canada, 1975.
7. L. H. Boman, T. E. Caye, and S. Cerni, "Fuel Operating Experience in W PWRs." Am. Nucl. Soc. Topical Meeting on Water Reactor Fuel Performance, St. Charles, IL, 1977.
8. A. A. Strasser and K. O. Lindquist, "Reliability and Operating Margins of LWR Fuels." Am. Nucl. Soc. Topical Meeting on Water Reactor Fuel Performance, St. Charles, IL, 1977.
9. P. Knudsen, C. Bagger, and M. Fishler, "Characterization of PWR Power Ramp Tests." Am. Nucl. Soc. Topical Meeting on Water Reactor Fuel Performance, St. Charles, IL, 1977.
10. M. Mogard, S. Aas and S. Junkrans, "Power Increases and Fuel Defection." Fourth Geneva Conference, Paper A/CONF-49/P-314, 1971.
11. S. Aas, K. D. Olhausen and K. Videm, "Fuel Failures, Caused by Overpower Ramps." BNES Conference on Nuclear Fuel Performances, Paper 55, 1973.
12. A. S. Bain, J. C. Wood and C. E. Coleman, "Fuel Designs to Eliminate Defects on Power Increases." BNES Conference on Nuclear Fuel Performance, Paper 56, 1973.

13. D. H. Locke, "Review of Experience with Water Reactor Fuels 1968-1973." Nuclear Engineering and Design 33(2):94-123, 1975.
14. H. Mogard et al., "Experimental Investigations of the Power Ramp Failure Propensity of LWR Fuel." International Conference on Nuclear Power and Its Fuel Cycle, Salzburg, Austria, 1977.
15. N. Eickelpasch, R. Seepolt, and U. Wolff, "Das Verhalten von SWR-Brennelementen bei Leistungsbetrieb - Grundlagen und Erkenntnisse." Atom & Strom, Frankfurt, Heft 9/10, 1974.
16. W. J. Penn, R. K. Lo and J. C. Wood, "CANDU Fuel - Power Ramp Performance Criteria." Symposium on Zirconium in the Nuclear Industry, Quebec, Canada, 1976.
17. S. Junkrans and O. Värnild, "ASEA-ATOM Research on PCI." Am. Nucl. Soc. Topical Meeting on Water Reactor Fuel Performance, St. Charles, IL, 1977.
18. H. Mogard, "Suppression of PCI Induced Defects by Lightly Undulating the Bore Surface of the Fuel Cladding." Am. Nucl. Soc. Topical Meeting on Water Reactor Fuel Performance, St. Charles, IL, 1977.
19. B. H. Cherry, M. Zukor and K. Osborne, "U.S. Operating Experience." Proceedings of Joint Topical Meeting on Commercial Nuclear Fuel Technology, CNS ISSN 0068-8517 and 75-CNA/ANS-100, pp. 1-2, Toronto, Canada, 1975.
20. I. Multer, "European Operating Experience." Proceedings of Joint Meeting on Commercial Nuclear Fuel Technology Today, CNS ISSN 0068-8517 and 75-CNA/ANS-100, pp. 1-24 through 1-37, Toronto, Canada, 1975.
21. D. Cordall, R. M. Cornell, K. W. Jones, and J. S. Waddington, "Fuel Failures in the Dodewaard Boiling Water Reactor." Nuclear Technology 34:438-448, 1977.
22. J. H. Davies et al., Irradiation Tests to Characterize the PCI Failure Mechanism, NEDO-21551, 1977; also referenced as J. S. Armijo et al., "Irradiation Tests to Characterize the PCI Failure Mechanism." Am. Nucl. Soc. Topical Meeting on Water Reactor Fuel Performance, St. Charles, IL, 1977.
23. J. C. Wood and D. G. Hardy, "Characteristics and Interpretation of Power Ramping Defects." Am. Nucl. Soc. Topical Meeting on Water Reactor Fuel Performance, St. Charles, IL, 1977.
24. B. Lustman, Fuel Clad Design Basis for Thermal Reactors. WAPD-T-1939, 1966.
25. S. Aas, "Mechanical Interaction Between Fuel and Cladding." Nuclear Engineering and Design 21(2):237-253, 1972.

26. ScP Incorporated, "Fuel Failure Avoidance," a brochure on Scandpower Services.
27. P. J. Pankaskie and R. O. Meyer, "AECL/PNL Cooperative PCI Program." BN-SA-789, presented at the Fifth Water Reactor Safety Research Information Meeting, Gaithersburg, MD, 1977.
28. J. C. Wood, "Environmentally Influenced Failure of UO₂-Zircaloy Fuel." Trans. Am. Nucl. Soc. 23:157, 1976.
29. J. C. Wood, "Factors Affecting Stress Corrosion Cracking in Iodine Vapour." J. Nucl. Matls. 45:105-122, 1972/1973.
30. G. Kjaerheim and E. Rolstad, "In-Core Study of the Mechanical Interaction Between Fuel and Cladding." Nuclear Applications and Technology 7:347-360, 1969.
31. J. H. Gittus, Theory of the Frictional Interaction Between Nuclear Fuel Cladding and a Cracked Ceramic Pellet. TRG-Report 2757(s), p. 2-6, 1976 (available from H. M. Stationery Office).
32. M. Pátel and R. E. Murata, Preliminary Analysis of the Cause of Failures of Experimental Mixed Oxide Fuel Rods in EBR-II. GEAP-14057, p. 36, July 1975 ("Applied Technology" restriction).
33. M. F. Lyons et al., "UO₂ Properties Affecting Performance," Nuclear Engineering and Design 21(2):167-199, 1972.
34. C. R. Hann, C. E. Beyer and L. J. Parchen, GAPCON-THERMAL-1: A Computer Program for Calculating the Gap Conductance in Oxide Fuel Pins. BNWL-1778, 1973.
35. J. T. A. Roberts and B. J. Wrona, Deformation and Fracture of UO₂-20 wt% PuO₂. ANL-7945, 1972.
36. J. A. L. Robertson et al., UO₂ Performance - The Importance of Temperature Distribution. AECL-2017, 1964.
37. R. M. Guha, J. L. Head, and J. R. Matthews, "Analysis of Crack Patterns in Fast Reactor Fuel Pellets." Trans. of the 4th Int'l Conf. on Structural Mechanics in Reactor Technology, Paper C2/7, San Francisco, CA, 1977.
38. N. Hoppe and P. Verbeek, Restructuring and Relocation in Oxide Fuels. BN 7610-04, Belgonucleaire, October 1976. A summary of this paper is also in Trans. Am. Nucl. Soc. 24:175-176, 1976.

39. Uranium Dioxide: Properties and Nuclear Applications. Published by Naval Reactors, Division of Reactor Development, USAEC, J. Belle, ed., 1961.
40. M. J. F. Notley, A. S. Bain and J. A. L. Robertson, The Longitudinal and Diametral Expansions of UO₂ Fuel Elements. AECL-2143, 1964.
41. W. Chubb, V. W. Storhok and D. L. Keller, "Factors Affecting the Swelling of Nuclear Fuels at High Temperatures." Nuclear Technology 18:231-256, 1973.
42. C. E. Coleman, "The Simulation of Interaction Between Cracked UO₂ Fuel and Zircaloy Cladding." International Conference on Physical Metallurgy of Reactor Fuels Elements, Berkeley Nuclear Laboratories, 1973.
43. R. Hargreaves and D. A. Collins, "A Quantitative Model for Fission Gas Release and Swelling in Irradiated Uranium Dioxide." J. Br. Nucl. Energy Society 15(4):312, 1976.
44. J. W. Harrison and L. M. Davies, "The Variation of Solid Fission Product and Gas Swelling in Uranium Compounds with Thermal Neutron Dose Rate," J. of Nucl. Mat. 27:239, 1968.
45. B. R. T. Frost, "Studies of Irradiation Effects in Ceramic Fuels at Harwell." Ceramic Nuclear Fuels, Proceedings of an International Symposium held by the American Ceramic Society in Washington, DC, pp. 225-243, 1969.
46. F. J. Homan, "A Parametric Analysis of Fuel-Cladding Mechanical Interactions." First International Conference on Structural Mechanics in Reactor Technology 2(Part C):209-222, Berlin, Germany, 1971.
47. M. Seltzer et al., Review of Out-of-Pile and In-Pile Creep of Ceramic Nuclear Fuels. BMI-1906, 1971.
48. W. M. Armstrong and W. R. Irvine, "Creep of Urania Base Solid Solutions." J. Nuclear Materials 12:261, 1964.
49. R. N. Singh, A Theoretical Assessment of Some of the Effects of Fission-Induced Impurities on the Creep Behavior of Mixed-Oxide Fuel. ANL-75-59, pp. 14-15, 1975 ("Applied Technology" restriction).
50. M. D. Freshley, D. W. Brite, J. L. Daniel and P. E. Hart, "Irradiation-Induced Densification of UO₂ Pellet Fuel." J. Nucl. Mater. 62:138-166, 1976.
51. N. Fuhrman et al., Evaluation of Fuel Rod Performance in Maine Yankee Core I. EPRI NP-218, pp. 2.1-2.5, Research Project 586-1, Final Report, 1976.

52. K. R. Jordan, "Densification and Fuel Rod Flattening--Reliability Impact." Proceedings of Joint Topical Meeting on Commercial Nuclear Fuel Today. CNS ISSN 0068-8517 and 75-CNA/ANS-100, pp. 2-86 to 2-104, Toronto, Canada, 1975.
53. R. O. Meyer, The Analysis of Fuel Densification. NUREG-0085, 1976.
54. USAEC Regulatory Staff, Technical Report on Densification of Light Water Reactor Fuels. WASH-1236, 1972.
55. D. O. Pickman, "Properties of Zircaloy Cladding." Nuclear Engineering and Design 21(2):212-236, 1972.
56. P. J. Pankaskie, Irradiation Effects on the Mechanical Properties of Zirconium Alloys. A Review. BN-SA-618, 1976. (The information in this report has been compiled for publication by the American Society for Metals in the forthcoming Volume 1 of the ninth edition of the Metals Handbook.)
57. V. Fidleris, "Summary of Experimental Results on In-Reactor Creep and Irradiation Growth of Zirconium Alloys." Atomic Energy Review 13(1): 51-80, 1975. Also referenced as AECL-4766.
58. W. P. Chernock and J. R. Stewart, "Axial Growth of Water Reactor Fuel Rods." Proceedings of the American Power Conference 34:163-168, 1972.
59. Steady-State and Defected Fuel Irradiation Testing Needs. Compiled by W. G. Meinhardt. GEAP-13637, 1970.
60. J. P. Hoffman, M. F. Lyons and B. Weidenbaum, Dimensional Changes in High Performance Powder and Pellet Fuel Rods - Profilometer Studies. GEAP-5100-8, 1966.
61. S. Aas, "Operating Conditions and Fuel Rod Behavior--A Revision." Proceedings of Joint Topical Meeting on Commercial Nuclear Fuel Technology Today, CNS ISSN 0068-8517 and 75-CNA/ANS-100, pp. 2-35 to 2-54, Toronto, Canada, 1975.
62. P. E. Bobe, Fuel Performance of Licensed Nuclear Power Plants Through 1974. NUREG-0032, 1976.
63. J. H. Gittus, "Theoretical Effects on Pellet Cracking of Friction at Pellet-Pellet Interfaces." Nuclear Engineering and Design 36:235, 1976, and "Theoretical Effects of a Soft Metal Interlayer upon Strains Produced in Fuel Cladding by the Expansion of Cracked Cylindrical Pellets," Nuclear Engineering and Design 30:295, 1974.
64. N. Fuhrman and V. Pasupathi, Joint CE/EPRI Fuel Performance Evaluation Program Task C Evaluation of Fuel Rod Performance in Maine Yankee Core 1. CENPD-221, 1975.

65. E. Smith and G. V. Ranjan, "A Criterion for Failure of Zircaloy Cladding in a Water Reactor Fuel Rod Subjected to Power Ramps." Am. Nucl. Soc. Topical Meeting on Water Reactor Fuel Performance, St. Charles, IL, 1977.
66. W. R. Smalley, Evaluation of Saxton Core III Fuel Materials Performance. WCAP-3385-7, 1974.
67. E. Smith, Symposium on Zirconium in the Nuclear Industry, Quebec, Canada, 1976.
68. A. Garlick and J. G. Gravenor, "A Criterion and Mechanism for Power Ramp Defects." Am. Nucl. Soc. Topical Meeting on Water Reactor Fuel Performance, St. Charles, IL, 1977.
69. B. Cox and J. C. Wood, "Iodine Induced Cracking of Zircaloy Fuel Cladding - A Review." Corrosion Problems in Energy Conversion and Generation, C. S. Tedmon, Jr., ed., The Electrochemical Society, pp. 275-321, 1974.
70. D. Cubicciotti and R. L. Jones, EPRI-NASA Cooperative Project on Stress Corrosion Cracking of Zircaloys, Eighth Quarterly Progress Report Covering the Period February 1, 1977 to April 30, 1977. EPRI Project RP 455, 1977.
71. D. Cubicciotti and R. L. Jones, EPRI-NASA Cooperative Project on Stress Corrosion Cracking of Zircaloys, Ninth Quarterly Progress Report Covering the Period May 1, 1977 to July 31, 1977. EPRI Project RP 455, 1977.
72. K. Videm and L. Lunde, "Stress Corrosion Cracking of Zircaloy Fuel Cladding Tubes Under Power Ramps and in Laboratory Tests." Am. Nucl. Soc. Topical Meeting on Water Reactor Fuel Performance, St. Charles, IL, 1977.
73. F. E. Gelhaus, The Cladding Flaw Growth Index: A Method for Core-Wide Fuel Rod Reliability Prediction. EPRI NP-324-SR, 1976.
74. D. Cubicciotti et al., The Nature of Fission Product Deposits Inside Light Water Reactor Fuel Rods. EPRI Project No. 455-1 (SRI Project No. 4197), 1976.
75. A. K. Miller, G. V. Ranjan, and E. Smith, Zircaloy Cladding Deformation and Fracture Analysis, First Quarterly Progress Report, Work Through July 31, 1977. EPRI Project No. RP-971, Task 2.
76. W. J. Penn, R. K. Lo, and J. C. Wood, "CANDU Fuel-Power Ramp Performance Criteria." Nucl. Tech. 34:249-268, 1977.

77. D. Cubicciotti et al., "The Nature of Fission-Product Deposits Inside LWR Fuel Rods." Am. Nucl. Soc. Topical Meeting on Water Reactor Fuel Performance, St. Charles, IL, 1977.
78. D. G. Hardy, A. S. Bain, and R. R. Meadowcroft, "Performance of CANDU Development Fuel in the NRU Reactor Loops." Am. Nucl. Soc. Topical Meeting on Water Reactor Fuel Performance, St. Charles, IL, 1977.
79. A. Garlick and P. D. Wolfenden, "Fracture of Zirconium Alloys in Iodine Vapor." J. Nucl. Matls. 41:274-292, 1971.
80. D. O. Pickman, "Internal Cladding Corrosion Effects." Nuclear Engineering and Design 33:141-154, 1975.
81. N. Fuhrman, V. Pasupathi, and L. V. Corsetti, "PCI Observation in a Combustion Engineering PWR." Am. Nucl. Soc. Topical Meeting on Water Reactor Fuel Performance, St. Charles, IL, 1977.
82. J. E. Reinoehl and W. K. Boyd, "The Use of Slow Strain Rate Experiments in Evaluating Resistance to Environmental Cracking." AGARD-CP-98, presented at the Structures and Materials AGARD, 33rd Meeting, Brussels, Belgium, 1971.
83. W. R. Wearmouth, G. P. Dean, and R. N. Parkins, "Role of Stress in the Stress Corrosion Cracking of Mg-Al Alloy." NACE 29(26), 1973.
84. J. T. A. Roberts et al., Planning Support Document for the EPRI Light Water Reactor Fuel Performance Program. EPRI NP-370-SR, pp. 1-1 to 2-11, 1977.
85. D. Cubicciotti and R. L. Jones, EPRI-NASA Cooperative Project on Stress Corrosion Cracking of Zircalloys, Fifth Quarterly Progress Report. EPRI Project No. RP 455 (SRI Project No. 4197), p. 17, 1976.
86. J. C. Wood, "Interactions Between Stressed Zirconium Alloys and Iodine at 300°C." Nuclear Technology 23:63-79, 1974.
87. J. A. L. Robertson, "Nuclear Fuel Failures: Their Causes and Remedies." Proceedings of Joint Topical Meeting on Commercial Nuclear Fuel Technology Today, CNS ISSN 0068-8517 and 75-CNA/ANS-100, Toronto, Canada, 1976.
88. P. Knudsen, C. Bagger, and N. Kjaer-Pedersen, "Performance Evaluation of UO₂-Zr Fuel in Power Ramp Tests," International Conference on Nuclear Power and Its Fuel Cycle, Salzburg, Austria, 1977.
89. D. Cubicciotti and R. L. Jones, EPRI-NASA Cooperative Project on Stress Corrosion Cracking of Zircalloys, Seventh Quarterly Progress Report Covering the Period November 1, 1976 to January 31, 1976. EPRI Project No. RP 455, 1977.

90. A. Garlick, J. Nucl. Mat. 49(2), 1974.
91. M. Adamson et al., "Oxygen Redistribution and Its Measurements in Irradiated Oxide Fuels." Proceedings of a Symposium on Thermodynamics of Nuclear Materials 1974. 1:59, IAEA, Vienna, 1975.
92. D. R. Olander, Fundamental Aspects of Nuclear Reactor Fuel Elements. TID 26711-Pl, Nat. Tech. Information Ser., Springfield, VA, 1976.
93. C. E. Beyer and C. R. Hann, Prediction of Fission Gas Release from UO₂ Fuel. BNWL-1875, 1974.
94. M. J. F. Notley, "Interaction of UO₂ Fuel and Fission Products with Zirconium Alloy Fuel Sheathing." Proceedings of Joint Topical Meeting on Commercial Nuclear Fuel Today, CNS ISSN 0068-8517 and 75-CNA/ANS-100, Toronto, Canada, 1975. (Based on AECL-4912, a report by F. R. Campbell, R. Deshaies and M. J. F. Notley, dated October 1974).
95. R. A. Lorenz et al., Quarterly Progress Report on Fission Product Release from LWR Fuel for the Period January-March 1976. ORNL/NUREG/TM-30, pp. 5, 9, and 23, 1976.
96. J. C. Wood, "Factors Affecting Stress Corrosion Cracking of Zircaloy in Iodine Vapor." J. of Nuclear Materials 45:121-122, 1972/73.
97. C. C. Busby, P. R. Tucker, and J. E. McCauley, "Halogen Corrosion Cracking of Zircaloy-4 Tubing." J. Nucl. Matls. 55:64, 1975.
98. J. A. Ellis et al., "Fast Flux Irradiation Data on the Stoichiometry Dependence of Fuel/Cladding Chemical Interaction in Mixed-Oxide Fuel Rods." Trans. Am. Nucl. Soc. 19:134, 1974.
99. F. T. Ewart et al., "The Chemical Effects of Composition Changes in Irradiated Oxide Fuel Materials - II - Fission Product Segregation and Equilibria." Journal of Nuclear Materials 61:267-269, 1976.
100. D. C. Fee et al., Chemical Interaction Between Fuel and Cladding in Stainless-Clad Fast Reactor Fuels. ANL-75-53, 1975 ("Applied Technology" restriction).
101. N. A. Javed and J. T. A. Roberts, Thermodynamic and Defect-Structure Studies in Mixed-Oxide Fuels. ANL-7901, pp. 16 and 18-20, 1972.
102. K. Hannerz and G. Vesterlund, "Zircaloy Cladding Mechanical Properties." Nuclear Engineering and Design 33:205-218, 1975.
103. W. T. Grubb and M. H. Morgan, III, "Cadmium Embrittlement of Zircaloy-2." Am. Nucl. Soc. Topical Meeting on Water Reactor Fuel Performance, St. Charles, IL, 1977.

104. B. C. Syrett, D. Cubicciotti, and R. L. Jones, "Embrittlement of Zircaloy-4 by Liquid Cesium at 300°C," 3rd International Conference on Zirconium in the Nuclear Industry, Quebec, Canada, 1976.
105. E. Rolstad et al., "Influence of Cored Pellets and Pellet Density on Mechanical Interaction." Trans. Am. Nucl. Soc. 15(1):219-221, 1972.
106. A. S. Bain et al., "The Performance and Evolutionary Development of CANDU Fuel." European Nuclear Conference, Paris, 1975.
107. C. L. Mohr, P. J. Pankaskie, and F. E. Panisko, A State-of-the-Art Report on the Anisotropic Deformation and Analysis of Zircaloy. Task D Topical Report, EPRI/MPC Zircaloy-LOCA Program (RP 251-1), 1976.
108. R. M. Berman et al., Properties of Zircaloy-4 Tubing. C. R. Woods, ed., WAPD-TM-585, 1966.
109. J. M. Frenkel and M. Weisz, "90. Influence of Various Metallurgical Parameters and Neutron Flux on Creep of Zircaloy 4 Cladding Tubes." Conference Internationale "Nuclear Fuel Performance", Londres, 1973.
110. Fracture, Volume 1: Microscopic and Macroscopic Fundamentals. H. Liebowitz, ed., Academic Press, 1968.
111. D. Cubicciotti and R. L. Jones, EPRI-NASA Cooperative Project on Stress Corrosion Cracking of Zircaloys, Sixth Quarterly Progress Report Covering the Period August 1 to October 31, 1976. EPRI Project No. RP 455, 1976.
112. J. F. Kerrisk, J. O. Barner, and R. L. Petty, "Design and Performance of Shroud-Tubes in Sodium-Bonded Advanced Fuel Elements." International Meeting on Advanced LMFBR Fuels, Tucson, AZ, 1977.
113. J. A. L. Robertson, "Improved Performance for UO₂ Fuel." Canadian Engineering Journal, 1972.
114. R. Foerthmann et al., Improvement in Retention of Solid Fission Products in HTGR Fuel Particles by Ceramic Kernel Additives. JUL-1226, pp. 27-28, 1975.
115. E. A. Gulbransen and S. A. Jansson, Westinghouse Electric Corporation, United States Patent No. 3,762,995, October, 1973.
116. W. T. Ross and H. E. Williamson. German (FRG) Patent No. 2,449,553, March 1975.
117. L. N. Grossman. General Electric Company. United States Patent No. 3,742,367, June 1973.

118. R. A. Proebstle et al., "The Mechanism of Defection of Zircaloy-Clad Fuel Rods by Internal Hydriding." Proceedings of Joint Topical Meeting on Commercial Nuclear Fuel Technology Today, CNS ISSN 0068-8517 and 75-CNA/ANS-100, pp. 2-15 to 2-29, Toronto, Canada, 1975.
119. G. M. Gordon and R. L. Cowan, II. General Electric Company, United States Patent No. 4,022,662, May 1977.
120. M. G. Adamson, E. A. Aitken, and H. S. Rosenbaum. German (FRG) Patent No. 2,527,686, January 1976.
121. J. R. Thompson and T. C. Rowland. United States Patent No. 3,969,186, July 1976.
122. J. R. Thompson and T. C. Rowland. German (FRG) Patent No. 2,501,309/A, August 1975.
123. H. H. Klepfer. German (FRG) Patent No. 2,501,505, August 1975.
124. H. H. Klepfer. Australian Patent No. 74/74,197, October 1974.
125. J. R. Thompson and T. C. Rowland. Australian Patent No. 74/74,198, October 1974.
126. R. L. Gibby and E. D. McClanahan, Deposition of Cr, Nb, V, and Ti, Coatings on UO₂-25 wt% PuO₂ Fuel Pellets by Sputtering. HEDL-SA-863, 1976.
127. M. T. Pitek, Utility Experience in LWR Fuel Performance. NUSCO-115, 1976.
128. M. T. Pitek and E. Rolstad, "Application of Performance Modeling to BWR Operations." Am. Nucl. Soc. Topical Meeting on Water Reactor Fuel Performance, St. Charles, IL, 1977.
129. "Panel Discussion on the Pellet-Cladding Interaction Problem: Its Causes and Solutions." Am. Nucl. Soc. Topical Meeting on Water Reactor Fuel Performance, St. Charles, IL, 1977. Moderator was B. Cox (AECL) and panel members were: N. Fuhrman (Combustion Engineering), A. Garlick (UKAEA Windscale), P. Knudsen (RISO National Laboratory, Denmark), E. Roberts (Westinghouse), G. A. Sofer (Exxon Nuclear), H. Stehle (KWU, Germany), K. Videm (IFA, Norway), and J. C. Wood (AECL).
130. L. N. Grossman, A. I. Kaznoff, and H. V. Clukey, General Electric Company. United States Patent No. 3,826,743, July 1974.
131. G. Lysell. Swedish Patent No. 360,491, January 1974.

132. W. Spalthoff and H. Wilhelm. German (FRG) Patent No. 1,639,249, April 1973.
133. G. E. McDonald, National Aeronautics and Space Administration. United States Patent No. 3,759,787, September 1973.
134. R. W. Webb, United States Atomic Energy Commission. United States Patent No. 3,784,384, January 1974.
135. H. Lories, A. Lafon, R. Darras, and P. Bacque, Protection of Zirconium and Its Alloys by Metallic Coatings. CEA-R-3612, 1968.
136. A. B. Johnson, Jr., "Review of Corrosion Phenomena on Zirconium Alloys Under Irradiation." Coatings and Corrosion I(4), 1975.

6.0 APPENDIX

6.1 Hydriding

Corrosion of Zircaloy cladding can generally be classified as hydriding or stress-corrosion cracking assisted by fission products. Stress-corrosion cracking is discussed in Section 4.4.1. Although hydriding may not relate directly to the fuel-cladding-interaction mechanism, evidence was found by Wood⁽⁸⁶⁾ that hydrided Zircaloy was less susceptible to stress-corrosion cracking in iodine vapor than unhydrided Zircaloy.

Pickman⁽⁵⁵⁾ notes that the performance of the cladding may be significantly changed if the hydride orientation is altered from circumferential to radial. He further indicates that a small quantity of the cladding near the fuel may undergo some hydride precipitation while under tensile stress during limited decreases in power. However, it is uncertain whether this has ever presented a problem of practical concern.

With nonhydrided Zircaloy cladding at normal operating conditions, the temperature is above the brittle-to-ductile transition temperature, while the temperature is probably in the region of the brittle-to-ductile transition temperature or perhaps below it with irradiated and hydrided cladding. From studies with other materials, it is known that the brittle-to-ductile transition temperature is sensitive to strain rate which may be an additional factor of significant importance.

Pickman⁽⁸⁰⁾ reported that prior to late 1974, the most persistent defect mechanism in water reactors was primary hydriding (i.e., hydriding occurring prior to a breach of cladding integrity). Since then, as reported by Roberts et al.,⁽⁸⁴⁾ primary hydriding has been essentially eliminated by changes in fuel manufacture and design. Such corrective actions included control of fuel density, use of hydrogen getters, and improved drying procedures.

Localized hydride attack can occur when the ZrO_2 protective oxide layer no longer protects the Zircaloy cladding. Proebstle et al.⁽¹¹⁸⁾ noted that the mechanism for breakdown of the protective oxide film on the cladding inner wall is unknown. Localized hydriding is caused by oxygen starvation and subsequent film breakdown. The protective oxide can also be broken down by aggressive chemicals (e.g., fission products) from the fuel, radiation effects or mechanical damage, with a low oxygen pressure preventing sufficient film repair. The main source of moisture, and thus H_2 , is moisture in the fuel pellets. If hydrocarbons are present, hydriding can occur helped by radiolytic decomposition. Pickman⁽⁸⁰⁾ concluded that internal hot spots, low O_2 partial pressure or local scratches can act as precursors to cladding attack.

Eliminating the source of moisture is the most effective way of eliminating hydride failures, as reported by Proebstle et al.,⁽¹¹⁸⁾ and one way to do this is by producing only low surface area fuel pellets, loading fuel pellets into Zircaloy tubes while the fuel is hot, and removing moisture by hot-outgassing the fuel rods. In addition, nonvolatile organic impurities can be eliminated by insuring absolute cleanliness. If H_2O or hydrocarbons contaminate the fuel due to low-level statistical tails in the processing, "getters" can be effectively used (ex-reactor tests by General Electric show no failures in fuel rods with "getters," even in rods with hydrogenous material additions). Ex-reactor tests are interpreted cautiously because they do not adequately model in-reactor conditions. Hydrofluoric acid is added in the presence of excess moisture in ex-reactor tests to cause hydriding which may lead to overemphasizing the effects of fluoride. Differences in cladding that has and has not been autoclaved are probably overemphasized in tests using pure hydrogen.

Johnson⁽¹³⁶⁾ reports that the role of nuclear fluxes in corrosion and hydriding processes has been investigated in several reactors,

with the major effort being placed on zirconium and its alloys. The corrosion of zirconium and its alloys has been shown to accelerate during irradiation under these conditions: 1) in oxygenated coolants when the fluence levels are sufficiently high, 2) in low-oxygen coolants after certain prefilm treatments, 3) in low-oxygen coolants at high fluences (corrosion rates mildly accelerated), 4) in proximity to certain other metals (e.g., Inconel, platinum, spacers) at sufficiently high fluences, 5) in crevices on coupons and possibly on fuel rods, and 6) with certain alloy compositions (zirconium is the most susceptible in oxygenated and low-oxygen exposures). Factors noted to decrease corrosion under irradiation were: 1) using Zr-2.5% Nb alloy in the quenched, cold-worked, annealed condition or in the quenched, annealed condition, 2) changing from oxygenated to a low-oxygen coolant when the zirconium oxides are relatively thin, and 3) exposing the specimens with relatively thick prefilms [$35\text{--}60\text{ mg/dm}^2$ ($7.2 \times 10^{-4} - 1.23 \times 10^{-4}\text{ lb/ft}^2$)] in oxygenated coolants. The general trends noted were these: Oxygen tends to accelerate the corrosion; there seems to be a threshold fluence (flux) at which corrosion accelerates; prefilms tend to cause accelerated corrosion; and primary performance problems seem to come from impurities on the fuel side rather than corrosion on the coolant side. Johnson also stated that the following factors accelerate hydriding under irradiation: 1) certain alloy compositions (e.g., Zr-Cu-Fe), 2) bonding to dissimilar metals (Zircaloy-2 explosively bonded to Inconel; Zircaloy-2 and Zr-2.5 Nb, electron-beam-welded to platinum), and 3) transferring of specimens with thick oxides to reducing environments. Conversely, the following factors tended to suppress radiation-induced hydriding: 1) certain alloy compositions (in particular Zr-2.5 Nb), and 2) operation under oxygenated conditions.

DISTRIBUTION

No. of
Copies

No. of
Copies

OFFSITE

2	A. A. Churm DOE Patent Division 9800 S. Cass Avenue Argonne, IL 60439	V. Stello U.S. Nuclear Regulatory Commission, Division of Operating Reactors Mail Stop 542 Washington, D.C. 20555	
	P. R. Clark DOE, Division of Naval Reactors Mail Stop H-404 Washington, D.C. 20545	4	S. J. Nowicki U.S. Nuclear Regulatory Commission, Division of Operating Reactors Mail Stop 542 Washington, D.C. 20555
	R. H. Steele DOE, Division of Naval Reactors Mail Stop H-404 Washington, D.C. 20545		D. L. Ziemann (Docket No.: 50-55, License DPR-6, Big Rock Point Plant) U.S. Nuclear Regulatory Commission, Division of Operating Reactors Mail Stop 542 Washington, D.C. 20555
	Director DOE, Division of Nuclear Power Development Mail Stop B-107 Washington, D.C. 20545		
3	Assistant Director for Light Water Reactor Development DOE, Division of Nuclear Power Development Mail Stop B-107 Washington, D.C. 20545		L. S. Tong U.S. Nuclear Regulatory Commission Division of Reactor Safety Research Mail Stop 1130SS Washington, D.C. 20555
	DOE, NASAP Control Office Mail Stop B-107 Germantown, MD 20767		Director U.S. Nuclear Regulatory Commission Office of Nuclear Reactor Regulation Washington, D.C. 20555
	DOE, Oak Ridge Operations Office P.O. Box X Oak Ridge, TN 37830		A. R. Barton Alabama Power Company P.O. Box 2641 600 N. 18th Street Birmingham, AL 35202
87	T. Abernathy DOE, Technical Information Center P.O. Box 62 Oak Ridge, TN 22161		

No. of
Copies

R. S. Hunter
American Electric Power Service
Corporation
2 Broadway
New York, NY 10004

H. Sobel
American Electric Power Service
Corporation
2 Broadway
New York, NY 10004

W. Lipinski
Argonne National Laboratory
9700 South Cass Avenue
Argonne, IL 60439

E. E. Van Brunt, Jr.
Arizona Public Service Company
411 North Central Avenue
Phoenix, AZ 85004

O. Cypret
Arkansas Power and Light Company
9th and Louisiana
Little Rock, AR 72203

J. D. Phillips
Arkansas Power and Light Company
9th and Louisiana
Little Rock, AR 72203

E. Chipman
Babcock and Wilcox Company
Nuclear Power Generation Division
P.O. Box 120
Lynchburg, VA 24505

G. E. Kulynych
Babcock and Wilcox Company
Nuclear Power Generation Division
P.O. Box 120
Lynchburg, VA 24505

J. S. Tulenko
Babcock and Wilcox Company
Nuclear Power Generation Division
P.O. Box 120
Lynchburg, VA 24505

No. of
Copies

J. W. Gore, Jr.
Baltimore Gas and Electric Company
Gas and Electric Building
Baltimore, MD 21203

Technical Files
Battelle Memorial Institute
505 King Avenue
Columbus, OH 43201

H. F. Brush
Bechtel Power Corporation
50 Beale Street
San Francisco, CA 94119

A. E. Swanson
Black and Veatch Consulting
Engineers
1500 Meadow Lake Parkway
Kansas City, MO 64114

B. A. Pasternak
Booz-Allen Applied Research
4330 East-West Highway
Bethesda, MD 20014

J. E. Howard
Boston Edison Company
800 Boylston Street
Boston, MA 02199

G. L. Morris
Brown and Root, Inc.
P.O. Box 3
Houston, TX 77001

S. Baron
Burns and Roe, Inc.
700 Kinderkamack Road
Oradell, NJ 07649

J. A. Jones
Carolina Power and Light Company
336 Fayetteville Street
Raleigh, NC 27602

No. of
Copies

W. H. Dickhoner
Cincinnati Gas and Electric Co.
139 East Fourth Street
Cincinnati, OH 45201

D. R. Davidson
Cleveland Electric Illuminating Co.
55 Public Square
Cleveland, OH 44101

F. Bevilacqua
Combustion Engineering, Inc.
1000 Prospect Hill Road
Windsor, CT 06095

W. Chernock
Combustion Engineering, Inc.
1000 Prospect Hill Road
Windsor, CT 06095

R. N. Duncan
Combustion Engineering, Inc.
1000 Prospect Hill Road
Windsor, CT 06095

W. B. Behnke, Jr.
Commonwealth Edison Company
P.O. Box 767
Chicago, IL 60690

W. M. Kiefer
Commonwealth Edison Company
P.O. Box 767
Chicago, IL 60690

D. R. O'Boyle
Commonwealth Edison Company
P.O. Box 767
Chicago, IL 60690

R. E. Jortberg
Commonwealth Research Corporation
One First National Plaza
P.O. Box 428
Chicago, IL 60690

No. of
Copies

D. Switzer
Connecticut Yankee Atomic Power
Company
P.O. Box 270
Hartford, CT 06141

W. Cahill
Consolidated Edison Company of
New York
4 Irving Place
New York, NY 10003

M. L. Lee
Consolidated Edison Company of
New York
4 Irving Place
New York, NY 10003

B. E. Wells
Daniel Construction Company
Daniel Building
Greenville, SC 29602

W. McCarthy
Detroit Edison Company
2000 Second Avenue
Detroit, MI 48226

D. B. Wehmeyer
Detroit Edison Company
2000 Second Avenue
Detroit, MI 48226

J. Korthever
Duke Power Company
P.O. Box 2178
Charlotte, NC 28342

W. O. Parker, Jr.
Duke Power Company
P.O. Box 2178
Charlotte, NC 28342

T. Snead
Duke Power Company
P.O. Box 2178
Charlotte, NC 28342

No. of
Copies

E. J. Woolever
Duquesne Light Company
435 Sixth Avenue
Pittsburgh, PA 15219

E. Borque
Ebasco Services, Inc.
2 Reactor Street
New York, NY 10006

W. D. Crawford
Edison Electric Institute
90 Park Avenue
New York, NY 10016

F. E. Gelhaus
Electric Power Research Institute
P.O. Box 10412
Palo Alto, CA 94303

M. Levenson
Electric Power Research Institute
P.O. Box 10412
Palo Alto, CA 94303

J. Prestele
Electric Power Research Institute
P.O. Box 10412
Palo Alto, CA 94303

J. T. A. Roberts
Electric Power Research Institute
P.O. Box 10412
Palo Alto, CA 94303

G. R. Thomas
Electric Power Research Institute
P.O. Box 10412
Palo Alto, CA 94303

R. Williams
Electric Power Research Institute
P.O. Box 10412
Palo Alto, CA 94303

E. L. Zebroski
Electric Power Research Institute
P.O. Box 10412
Palo Alto, CA 94303

No. of
Copies

R. Christensen
Entropy Limited
South Great Road
Lincoln, MA 01773

C. Rau
Failure Analysis Associates
750 Welch Road, #116
Palo Alto, CA 94304

J. R. Tomonto
Florida Power and Light Company
P.O. Box 013100
Miami, FL 33101

R. E. Uhrig
Florida Power and Light Company
P.O. Box 013100
Miami, FL 33101

M. F. Hebb, Jr.
Florida Power Corporation
3201 South 34th Street
P.O. Box 14042
St. Petersburg, FL 33733

W. Larkin
Fluor-Pioneer
200 W. Monroe
Chicago, IL 60606

S. Armijo
General Electric Company
175 Curtner Avenue
San Jose, CA 95125

P. Brag
General Electric Company
175 Curtner Avenue
San Jose, CA 95125

H. E. Stone
General Electric Company
175 Curtner Avenue
San Jose, CA 95125

No. of
Copies

G. Bond
General Public Utilities Service
Corporation (GPU)
260 Cherry Hill Road
Parsippany, NY 07054

R. L. Williams
General Public Utilities Service
Corporation (GPU)
260 Cherry Hill Road
Parsippany, NY 07054

M. Zukor
General Public Utilities Service
Corporation (GPU)
260 Cherry Hill Road
Parsippany, NY 07054

J. H. Miller, Jr.
Georgia Power Company
270 Peachtree Street N.W.
Atlanta, GA 30303

R. Gordon
Gibbs and Hill, Inc.
303 Seventh Avenue
New York, NY 10001

H. Lorenz
Gilbert Commonwealth
Power Engineering Division
525 Lancaster Avenue
Reading, PA 19603

S. L. Adams
Gulf States Utilities
285 Liberty Avenue
Beaumont, TX 77701

G. W. Oprea, Jr.
Houston Light and Power Company
P.O. Box 1700
Houston, TX 77001

No. of
Copies

L. J. Koch
Illinois Power Company
500 South 27th Street
Decatur, IL 62525

J. Dolan
Indiana and Michigan Power Company
AEP Corporation
2 Broadway
New York, NY 10004

L. Liu
Iowa Electric Light and Power Co.
200 First Street S.E.
Cedar Rapids, IA 52401

I. R. Finfrock, Jr.
Jersey Central Power and Light Co.
260 Cherry Hill Road
Parsippany, NJ 07054

D. T. McPhee
Kansas City Power and Light Co.
1330 Baltimore Avenue
Kansas City, MO 64141

E. Hall
Kansas Gas and Electric Company
201 North Market Street
Wichita, KS 67201

W. J. Tunney
Long Island Lighting Company
175 E. Old Country Road
Central Operations Headquarters
Hicksville, NY 11801

A. Wofford
Long Island Lighting Company
175 E. Old Country Road
Central Operations Headquarters
Hicksville, NY 11801

No. of
Copies

No. of
Copies

D. L. Aswell
Louisiana Power and Light Company
142 Delaronde Street
New Orleans, LA 70174

D. W. Edwards
Main Yankee Atomic Power Company
20 Turnpike Road
Westboro, MA 01581

J. E. Meyer
Massachusetts Institute of
Technology (MIT)
Department of Nuclear Engineering
77 Massachusetts Avenue
Cambridge, MA 01239

R. M. Lingaman
Metropolitan Edison Company
2800 Pottsville Pike
Reading, PA 19605

J. F. Vogt, Jr.
Middle South Utilities
225 Baronne Street
P.O. Box 61000
New Orleans, LA 70161

N. L. Stampley
Mississippi Power and Light Co.
P.O. Box 1640
Jackson, MS 39205

J. A. Gorman
MPR Associates
1140 Connecticut Avenue
Washington, D.C. 20036

L. D. Kunc1
Nebraska Public Power District
P.O. Box 499
Columbus, NE 68601

L. E. Bailey
New England Power Service Company
20 Turnpike Road
Westboro, MA 01581

G. L. Houston
New York State Electric and Gas
Corporation
4500 Vestal Parkway East
Binghamton, NY 19302

R. R. Schneider
Niagara Mohawk Power Corporation
300 Erie Boulevard West
Syracuse, NY 13202

S. W. Wilczek, Jr.
Niagara Mohawk Power Corporation
300 Erie Boulevard West
Syracuse, NY 13202

J. P. Cagnetta
Northeast Utilities Service Co.
P.O. Box 270
Hartford, CT 06101

R. A. Evans
Northwest Utilities Service
Corporation
Selden Street
Berlin, CT 06037

H. P. Lyle
Northern Indiana Public Service
Company
5265 Hohman Avenue
Hammond, IN 46320

A. V. Dienhart
Northern States Power Company
414 Nicollet Mall
Minneapolis, MN 55401

N. A. Petrick
Nuclear Projects, Inc.
5 Choke Cherry Road
Rockville, MD 20850

J. Hallam
Nuclear Services Corporation
1700 Dell Avenue
Campbell, CA 95008

No. of
Copies

S. Naymark
Nuclear Services Corporation
1700 Dell Avenue
Campbell, CA 95008

E. A. Saltarell
NUS Corporation
4 Research Place
Rockville, MD 20850

A. L. Lotts
Oak Ridge National Laboratory (ORNL)
P.O. Box X
Oak Ridge, TN 37830

T. Row
Oak Ridge National Laboratory (ORNL)
P.O. Box X
Oak Ridge, TN 37830

I. Spiewak
Oak Ridge National Laboratory (ORNL)
P.O. Box X
Oak Ridge, TN 37830

J. W. Junttila
Ohio Edison Company
76 South Main Street
Akron, OH 44308

L. C. Shalla
Omaha Public Power District
1623 Harney Street
Omaha, NE 68102

D. V. Kelley
Pacific Gas and Electric Company
77 Beale Street
San Francisco, CA 94106

N. W. Curtis
Pennsylvania Power and Light Co.
Two North Ninth Street
Allentown, PA 18101

No. of
Copies

V. S. Boyer
Philadelphia Electric Company
2301 Market Street
P.O. Box 8699
Philadelphia, PA 19101

G. F. Deabeler
Philadelphia Electric Company
2301 Market Street
P.O. Box 8699
Philadelphia, PA 19101

J. L. Williams
Portland General Electric Company
621 S.W. Alder Street
Portland, OR 97205

P. Lyon
Power Authority of the State of
New York
10 Columbus Circle
New York, NY 10019

J. E. Martin
Public Service Company of
Colorado
P.O. Box 840
Denver, CO 80201

W. C. Tallman
Public Service Company of
New Hampshire
1000 Elm Street
Manchester, NH 03105

G. W. Muench
Public Service Company of
Oklahoma
P.O. Box 201
Tulsa, OK 74102

R. M. Eckert
Public Service Electric and Gas
Company
80 Park Place
Newark, NJ 07101

No. of
Copies

K. Mahna
Public Service Electric and Gas
Company
80 Park Place
Newark, NJ 07101

R. R. O'Laughlin
Public Service Indiana
1000 East Main Street
Plainfield, IN 46168

R. C. Pattyn
Public Service Indiana
1000 East Main Street
Plainfield, IN 46168

W. R. Harris
Rand Corporation
1700 Main Street
Santa Monica, CA 90406

R. Kroprowski
Rochester Gas and Electric Corp.
89 East Avenue
Rochester, NY 14649

J. J. Mattimoe
Sacramento Municipal Utility Dist.
6201 S. Street
P.O. Box 15830
Sacramento, CA 95813

L. Bernath
San Diego Gas and Electric Co.
P.O. Box 1831
San Diego, CA 92112

J. A. Lindberg
Sandvik Special Metals Corporation
P.O. Box 6027
Kennewick, WA 99336

W. H. Chittenden
Sargent and Lundy Engineers
55 East Monroe
Chicago, IL 60603

No. of
Copies

P. Morris
Scandpower, Inc.
Suite B2
Triangle Towers
4853 Cordell Avenue
Bethesda, MD 20014

E. T. Rumble
Science Applications, Inc.
2680 Hanover Street
Palo Alto, CA 94304

E. Straker
Science Applications, Inc.
8400 Westpark Drive
McLean, VA 22101

A. A. Strasser
S. M. Stoller Corporation
1250 Broadway
New York, NY 10001

E. H. Crews, Jr.
South Carolina Electric and
Gas Company
328 Main Street
P.O. Box 764
Columbia, SC 29218

J. B. Moore
Southern California Edison Co.
P.O. Box 800
Rosemead, CA 91770

R. A. Thomas
Southern Services, Inc.
800 Shades Creek Parkway
P.O. Box 2625
Birmingham, AL 35202

D. Cubicciotti
Stanford Research Institute
333 Ravenswood Avenue
Menlo Park, CA 94025

No. of
Copies

A. Miller
Stanford University
Building 500
Stanford, CA 94305

W. Kennedy
Stone and Webster Engineering Corp.
P.O. Box 2325
Boston, MA 02107

J. R. Calhoun
Tennessee Valley Authority
716 Edney Building
Chattanooga, TN 37401

G. H. Kimmons
Tennessee Valley Authority
New Sprinkle Buildings
Knoxville, TN 37902

R. J. Mullin
Tennessee Valley Authority
1410 Commerce Union Bank Bldg
Chattanooga, TN 37402

J. D. Robertson
Tennessee Valley Authority
403 Power Building
Chattanooga, TN 37401

R. J. Gray
Texas Utilities Generating Co.
2001 Bryan Tower Building
Dallas, TX 75201

L. Roe
Toledo Edison Company
Edison Plaza
300 Madison Avenue
Toledo, OH 43632

J. K. Bryan
Union Electric Company
1 Memorial Drive
St. Louis, MO 63166

No. of
Copies

J. Crowley
United Engineers and Constructors
1401 Arch Street
Philadelphia, PA 19105

D. R. Olander
University of California, Berkeley
College of Engineering, Depart-
ment of Nuclear Engineering
Berkeley, CA 94720

D. R. Edwards
University of Missouri, Rolla
Building T-4
Rolla, MO 65401

C. M. Stallings
Virginia Electric and Power Co.
700 E. Franklin Street
Richmond, VA 23261

T. Hursen
Westinghouse Electric Corporation
Box 355
Pittsburgh, PA 15230

W. Jacobi
Westinghouse Electric Corporation
Box 355
Pittsburgh, PA 15230

R. S. Miller
Westinghouse Electric Corporation
Box 355
Pittsburgh, PA 15230

G. A. Reed
Wisconsin Electric Power Company
231 W. Michigan
Milwaukee, WI 53201

E. W. James
Wisconsin Public Service Corp.
600 North Adams
Green Bay, WI 54301

No. of
Copies

R. M. Grube
Yankee Atomic Electric Company
20 Turnpike Road
Westboro, MA 01581

L. Minnick
Yankee Atomic Electric Company
20 Turnpike Road
Westboro, MA 01581

ONSITE

DOE Richland Operations Office

H. E. Ransom

Hanford Engineering Development
Laboratory

R. Omberg

Washington Public Power Supply
System

D. L. Larkin
D. L. Renberger

INTERNAL

16 Consumers Power Company
1945 Parnall Road
Jackson, MI 49201

W. J. Beckius
F. W. Buckman
R. B. DeWitt
T. W. Elward
G. F. Pratt (10)
Library
Records File

35 Exxon Nuclear Company, Inc.
Richland, WA 99352

L. J. Brown
L. P. Bupp
G. J. Busselman
M. H. Campbell

No. of
Copies

D. L. Cornell
C. E. Crouthamel (10)
P. L. Farnsworth
J. W. Fredericks
K. P. Galbraith
W. L. Hampson
O. L. Kruger
K. R. Merckx
W. S. Nechodom
R. Nilson
J. F. Patterson
R. K. Robinson
P. G. Sarafian
G. A. Sofer
L. Van Swam
R. K. Welty
H. E. Williamson
K. E. Willis
K. N. Woods
Records File
Library

29 Pacific Northwest Laboratory
P.O. Box 999
Richland, WA 99352

W. J. Bailey
J. O. Barner
D. W. Brite
L. R. Bunnell
T. D. Chikalla
J. A. Christensen
E. L. Courtright
M. D. Freshley (5)
R. J. Guenther
C. R. Hann
P. E. Hart
R. P. Marshall
C. L. Mohr
F. E. Panisko
P. J. Pankaskie
R. E. Schreiber
S. R. Wagoner
R. D. Widrig
Publishing Coordination (2)
Technical Information Files (5)