HEALTH AND SAFETY RESEARCH DIVISION

Environmental Restoration and Waste Management Non-Defense Programs
(Activity No. EX 20 20 01 0; ADS3170000)

**Radiological Survey Results at Beverly Harbor,
Beverly, Massachusetts (VB025)**

R. D. Foley and C. A. Johnson

Date Issued —August 1992

Investigation Team

R. E. Swaja — Measurement Applications and Development Manager
W. D. Cottrell — FUSRAP Project Director
R. D. Foley — Survey Team Leader

Survey Team Members

J. F. Allred	M. E. Murray
A. C. Butler*	V. P. Patania
R. D. Foley	D. E. Rice
P. Blom†	D. A. Rose
W. H. Shinpaugh*	

*D. R. Stone and Associates, Inc.

†U.S. Department of Energy

Work performed by the
MEASUREMENT APPLICATIONS AND DEVELOPMENT GROUP

Prepared by the
OAK RIDGE NATIONAL LABORATORY
Oak Ridge, Tennessee 37831-6285
managed by
MARTIN MARIETTA ENERGY SYSTEMS, INC.
for the
U. S. DEPARTMENT OF ENERGY
under contract DE-AC05-84OR21400

WASTED

REPRODUCTION OF THIS DOCUMENT IS UNLIMITED

CONTENTS

LIST OF FIGURES.....	v
LIST OF TABLES.....	vii
ACKNOWLEDGMENTS.....	ix
ABSTRACT.....	xi
INTRODUCTION.....	1
SURVEY METHODS.....	2
SURFACE RADIATION MEASUREMENTS.....	2
SOIL AND BIOLOGICAL SAMPLING AND ANALYSES.....	2
SURVEY RESULTS.....	3
SURFACE RADIATION MEASUREMENTS.....	3
SOIL SAMPLES.....	3
Systematic	3
Biased	4
SHELLFISH SAMPLES	4
SIGNIFICANCE OF FINDINGS.....	5
REFERENCES.....	5

LIST OF FIGURES

1	Diagram showing general location of the former Ventron site and Beverly Harbor, Beverly, Massachusetts.....	6
2	View of the rear of the Ventron plant looking north from the tidal area of the harbor , Beverly, Massachusetts.....	7
3	View looking east from the rear of the Ventron plant towards the bridge, Beverly, Massachusetts	7
4	View looking north at the adjacent vicinity properties on the harbor west of the Ventron plant, Beverly, Massachusetts	8
5	Surface gamma exposure rates, and soil and biological sampling locations at Beverly Harbor, Beverly, Massachusetts.....	9

LIST OF TABLES

1	Applicable guidelines for protection against radiation.....	10
2	Background radiation levels and concentrations of selected radionuclides in soil in the Beverly, Massachusetts, area	11
3	Concentrations of radionuclides in soil samples from Beverly Harbor, Beverly, Massachusetts.....	12
4	Concentrations of radionuclides in lobster samples from Beverly Harbor, Beverly, Massachusetts	16

ACKNOWLEDGMENTS

Research for this project was sponsored by the Office of Environmental Restoration, U.S. Department of Energy, under contract DE-AC05-84OR21400 with Martin Marietta Energy Systems, Inc. The authors wish to acknowledge the contributions of R. F. Carrier, W. D. Cottrell, M. S. Uziel, D. A. Roberts, D. A. Rose, V. P. Patania, J. F. Allred, and T. R. Stewart of the Measurement Applications and Development Group for participation in the sample preparation and analyses, editing, graphics, and reporting of data for this survey.

ABSTRACT

At the request of the U.S. Department of Energy (DOE), a team from Oak Ridge National Laboratory conducted a radiological survey at Beverly Harbor, Beverly, Massachusetts. The survey was performed in May 1991. The purpose of the survey was to determine if uranium from work performed under government contract at the former Ventron facility had migrated off-site to the harbor and neighboring areas. The survey included a surface gamma scan and the collection of soil and biological samples for radionuclide analyses.

Results of the survey demonstrated isolated and spotty radionuclide concentrations in soil, and radiation measurements in excess of the DOE Formerly Utilized Sites Remedial Action Program guidelines.

RADIOLOGICAL SURVEY RESULTS AT BEVERLY HARBOR, BEVERLY, MASSACHUSETTS (VB025)*

INTRODUCTION

The Metal Hydrides Corporation facility in Beverly, Massachusetts (which became the Ventron Corporation in 1965), was one of many companies performing work during the 1940s associated with the development of nuclear energy for defense-related projects under contract to the Manhattan Engineer District (MED) and the Atomic Energy Commission (AEC). Operations conducted under government contract at such sites included the procurement, storage, and processing of uranium oxides, salts, and metals, and the subsequent machining of these products. As a result of activities involving these materials, equipment, buildings, and land at some of the sites became radiologically contaminated with small amounts of the material resulting in low levels of contamination on the properties. At contract termination, release limits and decontamination operations were typically applied in conformance with standards currently deemed adequate for purposes of health and environmental protection. Subsequent to original assessments and the release of these facilities, new research and information have resulted in the development of more stringent guidelines for release of such facilities for unrestricted use. Furthermore, in some instances, documentation is limited or nonexistent, and conditions at a specific site may be unknown. It is the policy of the Department of Energy (DOE) to verify that radiological conditions at such facilities comply with existing guidelines.¹ The Formerly Utilized Sites Remedial Action Program (FUSRAP) was established by DOE in 1974 to assist in assessment and cleanup activities at these sites.

The radiological survey detailed in this report was performed under the FUSRAP program and is one of several conducted in May, 1991, on properties in the vicinity of the former Ventron facility by members of the Oak Ridge National Laboratory (ORNL) at the request of DOE. The city of Beverly lies on Beverly Harbor approximately 15 miles northeast of the central Boston area. The former Ventron facility, now owned by Morton International, Inc., is located at the confluence of the Bass and Danvers rivers on Congress Street near the Beverly-Salem bridge (Fig. 1, p. 6).

From 1942 through 1948, the Metal Hydrides Corporation (later to become the Ventron facility), converted uranium oxide to uranium metal powder at the facility under contract to the MED in support of the war effort. Other operations conducted at the facility included the recovery of uranium from scrap uranium and turnings from the slug fabrication plant at Hanford, Washington. Contracts between Metal Hydrides and the government were completed in 1954.

*The survey was performed by members of the Measurement Applications and Development Group of the Health and Safety Research Division of Oak Ridge National Laboratory under DOE contract DE-AC05-84OR21400.

Following a radiological screening survey at the site in 1977, a comprehensive survey was performed in 1982.² In 1987, DOE contractors removed the uranium-contaminated roof from a Ventron building, which had begun to leak. Radioactive materials remaining on the site do not pose a health hazard under present use conditions, but could cause radiation exposure to workers if excavation or major renovation took place on the property. DOE plans a complete characterization study of the site in 1992 and the initiation of remedial action soon thereafter.

The survey of the property reported in this document and of other surrounding properties is part of DOE's continuing program to assess the former Ventron site and plan for remedial action. The objective of the surveys was to determine if uranium from plant operations had migrated offsite to neighboring areas including Beverly Harbor, and if so, to what degree. The relative location of the harbor to the former Ventron site is shown in Fig. 1. The radiological surveys consisted of measurements of radiation levels over the ground surface of the properties and analysis of soil, sediment, and other material samples for the presence of radionuclides in concentrations exceeding guidelines.

Photos of Beverly Harbor and the tidal area of the waters adjacent to the former Ventron plant site are shown in Figs. 2 - 4 (pp. 7-8).

SURVEY METHODS

A comprehensive description of the survey methods and instrumentation used in this survey is given in *Procedures Manual for the ORNL Radiological Survey Activities (RASA) Program*, ORNL/TM-8600 (April 1987).³

SURFACE RADIATION MEASUREMENTS

Gamma radiation levels were determined using a portable NaI gamma scintillation meter. Because NaI gamma scintillators are energy dependent, measurements of gamma radiation levels in counts per minute (cpm) are normalized to pressurized ionization chamber (PIC) measurements to estimate gamma exposure rates in $\mu\text{R/h}$.

SOIL AND BIOLOGICAL SAMPLING AND ANALYSES

Surface and subsurface soil samples were systematically collected near the Ventron property in a pattern sufficient to obtain a characterization of the radionuclide content of the soil. Surface and subsurface soil samples were also collected in areas of elevated gamma exposure rates. Such samples are referred to as biased samples and are more likely to contain elevated concentrations of radionuclides than are systematically chosen samples. Lobster samples were collected from the waters south of the Ventron site. All soil and biological samples were analyzed to determine ^{238}U , ^{232}Th , ^{226}Ra , ^{40}K , and ^{137}Cs concentrations.

SURVEY RESULTS

Current guidelines for sites included within the FUSRAP are summarized in Table 1 (p. 10). Typical background radiation levels for the Beverly, Massachusetts, area are presented in Table 2 (p. 11). These data are provided for comparison with the survey results presented in this section. All direct measurements presented in this report are gross readings; background radiation levels have not been subtracted. Similarly, background concentrations have not been subtracted from radionuclide concentrations in soil, debris, and other samples.

SURFACE RADIATION MEASUREMENTS

A general gamma scan was conducted of the tidal area of the harbor adjacent to the former Ventron plant site. On the back (south) and side (west) of the plant site are the tidal areas of the Danvers River on the south and the Bass River on the west. Results of gamma measurements taken around the plant site at the seawall and on the mud of the tidal area are shown on Fig. 5 (p. 9). Exposure rates at the ground surface ranged from 24 to 40 $\mu\text{R/h}$ at the southwest corner of the site (building labeled C-1, Fig.5), and 16 to 24 $\mu\text{R/h}$ on the south side of the plant (buildings B-1 and B-2), with a maximum of 60 $\mu\text{R/h}$ measured in one spot near the seawall behind building B-2. These values are higher than the typical background measurements in the Beverly area, and indicate the presence of residual radioactive contamination. Biased soil samples were not taken at all areas with elevated gamma measurements. Exposure rates further out from the buildings, in the tidal mud, ranged from 4 to 9 $\mu\text{R/h}$. These values are comparable to the background measurements in the Beverly area (Table 2).

SOIL SAMPLES

Systematic

Soil sample locations are shown in Fig. 5 and results of analyses are listed in Table 3 (pp. 12-15). Systematic soil samples were taken from the area close to the Ventron plant, and also up to the low tide water line in the harbor area west of the Ventron Plant on the adjacent vicinity properties VB011, VB012, and VB013. All soil samples are included in Table 3. In all the samples, maximum concentrations of ^{226}Ra and ^{232}Th in surface soil (0-15 cm) were 0.80 and 0.99 pCi/g, respectively. In all subsurface soil samples (15-60 cm), maximum values were 0.81 pCi/g for ^{226}Ra and 1.0 pCi/g for ^{232}Th . These values are comparable to typical background levels in the Beverly area (Table 2), and well below DOE guidelines (Table 1). Uranium-238 concentrations in all surface samples ranged from 0.84 to 12 pCi/g. In subsurface soil, ranges were from 0.81 to 8.1 pCi/g on the Ventron site, and from 2.4 to 7.7 pCi/g on the harbor tidal area of the adjacent properties, with a maximum of 40 pCi/g measured in the 15-30 cm portion of one sample (VB12S9B). With this one exception, all ^{238}U concentrations in these systematic samples were near or slightly above typical

background soil concentrations in the Beverly area (Table 2), but still below guidelines of 35 to 40 pCi/g that have been applied at other FUSRAP sites (Table 1).

Biased

Biased samples were taken in the areas of elevated gamma readings that were measured close to the Ventron buildings on the outside of the perimeter fence. (See Fig. 5). These samples, when analyzed for ^{238}U , contained concentrations ranging from 32 to 4600 pCi/g in surface soil. Sample B3C, also a surface sample taken after monitoring for spot contamination near the B3 sample location (see ** footnote, Table 3, p. 15), measured 22,000 pCi/g. Uranium-238 concentrations in subsurface soil ranged from 11 to 5500 pCi/g. Maximum ^{226}Ra and ^{232}Th concentrations in the biased samples were 1.2 and 21 pCi/g, respectively, in surface soil, and 1.6 and 27 pCi/g, respectively, in subsurface samples.

Sample B1A was subdivided until a metal fragment was isolated. The sample containing the metal fraction, labeled B1AM, measured 210,000 pCi/g of ^{238}U . Concentrations of ^{226}Ra and ^{232}Th in this sample were 27 and 42 pCi/g, respectively. Although neither potassium-40 (^{40}K) nor Cesium-137 (^{137}Cs) were associated with any MED operations or processing activities at the Ventron site, samples are routinely analyzed for their presence. These analyses showed that the B1AM sample contained 41 pCi/g ^{40}K and 15 pCi/g ^{137}Cs , while all other samples were well below guidelines for ^{40}K (Ref. 4) and ^{137}Cs (see Table 1). Potassium-40 is naturally occurring; worldwide the concentration of ^{40}K in soil ranges from 3.5 to 22 pCi/g, and an individual weighing 70 kg (~188 lb) would normally contain about 140 pCi/g.⁴ The concentration of ^{137}Cs in the sample is well below the guidelines.

SHELLFISH SAMPLES

Lobster traps were set in three locations in the waters of the harbor behind (to the south of) the former Ventron plant. For background readings, a fourth trap was set 3.25 nautical miles east of the plant at the Eagle Island Buoy (coordinates: 70°49'6" Longitude, 42°31'17" Latitude). Trap locations are indicated in Figs. 1 and 5 and results of analyses are given in Table 4. Each lobster was marked by color-coded bands attached to the claws to designate its location of capture, and shipped live to ORNL for analysis.

Three lobsters from each of the four locations were analyzed to determine ^{238}U , ^{232}Th , and ^{226}Ra concentrations. In two of the lobsters from each trap, the edible parts (tail and claws) were removed and combined for analysis. In the remaining lobster in each trap, the inedible parts (stomach and its contents, green gland, and carapace) were removed and combined for analysis. In all, eight lobsters were used for edible parts analysis, and four for inedible parts analysis.

Results of the analyses showed that there was no significant difference in ^{238}U , ^{232}Th , and ^{226}Ra concentrations between the background samples and any of the other samples (see Table 4) .

SIGNIFICANCE OF FINDINGS

The results of the radiological survey at Beverly Harbor, Beverly, Massachusetts, indicated the general elevation of uranium concentrations in soil and the presence of isolated spots of significantly elevated ^{238}U concentrations. The contamination occurs as both surface and subsurface contamination in spotty locations in the tidal areas of the harbor, usually within 50 ft of the plant sea wall.

The concentrations of residual radioactive material in the form of ^{238}U found in certain areas in the soils of the harbor around the Former Ventron site are in excess of concentration guidelines established by the Department of Energy.

REFERENCES

1. U.S. Department of Energy, *Radiological Control Manual*, DOE/EH-0256T (DOE N 5480.6), June 1992; U.S. Department of Energy, *A Background Report for the Formerly Utilized Manhattan Engineer District/Atomic Energy Commission Sites Program*, DOE/EV-0097, September 1980.
2. W. D. Cottrell and R. F. Carrier, *Results of the Radiological Survey at the Ventron Site, Beverly, Massachusetts*, ORNL/TM-10053, Martin Marietta Energy Systems, Inc., Oak Ridge Natl. Lab., May 1988.
3. T. E. Myrick, B. A. Berven, W. D. Cottrell, W. A. Goldsmith, and F. F. Haywood, *Procedures Manual for the ORNL Radiological Survey Activities (RASA) Program*, ORNL/TM-8600, Martin Marietta Energy Systems, Inc., Oak Ridge Natl. Lab., April 1987.
4. National Council on Radiation Protection and Measurements (NCRP) Report No. 50, December 27, 1976.

Fig. 1. Diagram showing general location of the former Ventron site and Beverly Harbor, Beverly, Massachusetts.

Fig. 2. View of the rear of the Ventrone area of the harbor, Beverly, Massachusetts.

Fig. 3. View looking east from the bridge, Beverly, Massachusetts.

ORNL-PHOTO 3986-92

Fig. 4. View looking north at the adjacent vicinity properties on the harbor west of the Ventron plant, Beverly, Massachusetts.

Fig. 5. Surface gamma exposure rates, and soil and biological sampling locations at Beverly Harbor, Beverly, Massachusetts.

Table 1. Applicable guidelines for protection against radiation
(Limits for uncontrolled areas)

Mode of exposure	Exposure conditions	Guideline value
Gamma radiation	Indoor gamma radiation level (above background)	20 $\mu\text{R}/\text{h}^a$
Radionuclide concentrations in soil (generic)	Maximum permissible concentration of the following radionuclides in soil above background levels, averaged over a 100-m ² area ^{226}Ra ^{232}Th ^{230}Th	5 pCi/g averaged over the first 15 cm of soil below the surface; 15 pCi/g when averaged over 15 cm-thick soil layers > 15 cm below the surface
Derived concentrations	^{238}U Concentration limit in surface soil above background levels based on dose estimates from major exposure pathways ^{137}Cs	Site specific ^b 80 pCi/g over a 100-m ² area of contamination ^c
Guideline for non-homogeneous contamination (used in addition to the 100-m ² guideline) ^d	Applicable to locations with an area ≤ 25 m ² , with significantly elevated concentrations of radionuclides ("hot spots")	$G_A = G_i (100/A)^{1/2}$ where G_A = guideline for "hot spot" of area (A) G_i = guideline averaged over a 100-m ² area

^aThe 20 $\mu\text{R}/\text{h}$ shall comply with the basic dose limit (100 mrem/yr) when an appropriate-use scenario is considered.

^bDOE guidelines for uranium are derived on a site-specific basis. Guidelines of 35-40 pCi/g have been applied at other FUSRAP sites. Sources: J. L. Marley and R. F. Carrier, *Results of the Radiological Survey at 4 Elmhurst Avenue, Colonie, New York (AL219)*, ORNL/RASA-87/117, Martin Marietta Energy Systems, Inc., Oak Ridge Natl. Lab., February 1988; B. A. Berven et. al., *Radiological Survey of the Former Kellex Research Facility, Jersey City, New Jersey*, DOE/EV-0005/29, ORNL-5734, Martin Marietta Energy Systems, Inc., Oak Ridge Natl. Lab., February 1982.

^cJ. W. Healy, J. C. Rodgers, and C. L. Wienke, *Interim Soil Limits for D&D Projects*, LA-UR-79-1865-Rev., Los Alamos Scientific Laboratory, Los Alamos, NM, 1979. Cited in U. S. Department of Energy, *Radiological Guidelines for Application to DOE's Formerly Utilized Sites Remedial Action Program*, ORO-831, March 1983.

^dDOE guidelines specify that every reasonable effort shall be made to identify and to remove any source which has a concentration exceeding 30 times the guideline value, irrespective of area. (adapted from *Revised Guidelines for Residual Radioactive Material at FUSRAP and Remote SFMP Sites*, April 1987).

Sources: Adapted from U.S. Department of Energy, *Radiation Protection of the Public and the Environment*, DOE Order 5400.5, April 1990 and U.S. Department of Energy, *Guidelines for Residual Radioactive Material at FUSRAP and Remote SFMP Sites*, Rev. 2, March 1987.

Table 2. Background radiation levels and concentrations of selected radionuclides in soil in the Beverly, Massachusetts, area

Type of radiation measurement or sample	Radiation level or radionuclide concentration	
	Range	Average
Gamma exposure rate at ground surface ($\mu\text{R/h}$) ^a	6-9	7
Concentration of radionuclides in soil (pCi/g) ^a		
²²⁶ Ra	0.70-0.94	0.84
²³² Th	0.76-0.94	0.84
²³⁸ U	0.69-1.05	0.89

^aValues obtained from three locations in the Beverly area.

Table 3. Concentrations of radionuclides in soil samples from Beverly Harbor, Beverly, Massachusetts

Sample number ^a	Depth (cm)	Radionuclide concentration (pCi/g) ^b		
		²²⁶ Ra	²³² Th	²³⁸ U
<i>Systematic samples^c</i>				
S1A	0-15	0.45 ± 0.01	0.52 ± 0.03	2.0 ± 0.4
S1B	15-25	0.46 ± 0.02	0.49 ± 0.02	1.7 ± 0.7
S2A	0-15	0.48 ± 0.02	0.55 ± 0.03	2.5 ± 0.8
S2B	15-30	0.56 ± 0.02	0.73 ± 0.03	4.4 ± 0.8
S2C	30-40	0.51 ± 0.02	0.57 ± 0.03	3.2 ± 0.4
S3A	0-15	0.51 ± 0.02	0.57 ± 0.03	3.1 ± 0.5
S3B	15-30	0.56 ± 0.02	0.63 ± 0.03	2.2 ± 0.5
S3C	30-40	0.61 ± 0.02	0.70 ± 0.03	5.9 ± 1
S4A	0-15	0.47 ± 0.02	0.48 ± 0.03	2.5 ± 0.7
S4B	15-30	0.47 ± 0.02	0.49 ± 0.02	1.6 ± 0.7
S4C	30-45	0.59 ± 0.02	0.61 ± 0.03	1.6 ± 0.6
S4D	45-60	0.46 ± 0.02	0.52 ± 0.03	1.5 ± 0.6
S5A	0-15	0.74 ± 0.02	0.99 ± 0.04	1.6 ± 1
S5B	15-30	0.61 ± 0.02	0.82 ± 0.03	0.81 ± 0.8
S6A	0-15	0.56 ± 0.03	0.74 ± 0.06	4.2 ± 0.5
S6B	15-30	0.58 ± 0.02	0.72 ± 0.03	3.0 ± 0.6
S7A	0-15	0.45 ± 0.02	0.50 ± 0.03	2.9 ± 0.6
S7B	15-30	0.56 ± 0.03	0.68 ± 0.06	4.6 ± 0.6
S8A	0-15	0.48 ± 0.02	0.59 ± 0.03	7.6 ± 0.6
S8B	15-30	0.73 ± 0.03	0.73 ± 0.03	8.1 ± 1

Table 3 (continued)

Sample number ^a	Depth (cm)	Radionuclide concentration (pCi/g) ^b		
		²²⁶ Ra	²³² Th	²³⁸ U
<i>Systematic samples^c</i>				
S9A	0-15	0.80 ± 0.03	0.97 ± 0.05	3.8 ± 0.5
S9B	15-30	0.52 ± 0.02	0.58 ± 0.03	6.7 ± 1
S10A	0-15	0.56 ± 0.02	0.62 ± 0.03	9.2 ± 0.9
S10B	15-30	0.53 ± 0.02	0.66 ± 0.03	3.4 ± 0.6
S11A	0-15	0.41 ± 0.02	0.40 ± 0.04	1.3 ± 0.6
S11B	15-30	0.54 ± 0.02	0.63 ± 0.03	3.2 ± 0.8
S12A	0-15	0.65 ± 0.03	0.73 ± 0.05	12.0 ± 1
S12B	15-30	0.53 ± 0.01	0.55 ± 0.02	4.5 ± 0.6
S13A	0-15	0.51 ± 0.02	0.60 ± 0.03	1.7 ± 1
S13B	15-30	0.55 ± 0.02	0.68 ± 0.04	4.2 ± 1
S14	0-15	0.60 ± 0.02	0.76 ± 0.03	5.5 ± 0.4
S15A	0-15	0.56 ± 0.03	0.58 ± 0.04	2.4 ± 1
S15B	15-30	0.53 ± 0.02	0.67 ± 0.04	2.6 ± 0.9
S16	0-15	0.54 ± 0.02	0.73 ± 0.03	11 ± 0.8
S17	0-15	0.55 ± 0.02	0.62 ± 0.03	1.6 ± 0.9
S18A	0-15	0.58 ± 0.02	0.59 ± 0.03	1.3 ± 0.5
S18B	15-30	0.61 ± 0.02	0.67 ± 0.03	2.2 ± 0.6

Table 3 (continued)

Sample number ^a	Depth (cm)	Radionuclide concentration (pCi/g) ^b		
		²²⁶ Ra	²³² Th	²³⁸ U
<i>Systematic samples^c</i>				
S19A	0-15	0.58± 0.02	0.65 ± 0.04	1.5 ± 0.8
S19B	15-30	0.68± 0.02	0.72 ± 0.03	1.6 ± 0.7
VB11S/A*	0-15	0.52± 0.02	0.60 ± 0.04	0.84±0.7
S2B	15-30	0.65± 0.02	0.80 ± 0.03	2.4 ±0.9
VB12S9A*	0-15	0.69± 0.02	0.74± 0.03	1.9± 0.4
S9B	15-30	0.81± 0.04	1.0 ± 0.07	40 ± 2
S9C*	30-45	0.81± 0.05	1.0 ± 0.07	7.7 ± 1
VB13S8A*	0-15	0.60± 0.02	0.69 ± 0.03	2.2 ± 0.5
S8B	15-20	0.65± 0.02	0.73 ± 0.03	4.1 ± 1
<i>Biased samples^d</i>				
B1A	0-15	0.77± 0.3	0.67 ± 0.4	4600± 90
B1AM	0-15	<27	<42	210000±1000
B1B	15-30	0.56± 0.05	0.56 ± 0.1	45± 3
B3A	0-15	0.71± 0.2	1.4 ± 0.4	2600± 200
B3B	15-30	0.74± 0.2	<0.7	1400± 30
B3C**	0-10	<1.1	<1.7	22000± 100
B4A	0-15	1.2 ± 0.1	9.9 ± 0.2	3000± 30
B4B	15-30	1.6 ± 0.3	27 ± 0.4	5500± 300

Table 3 (continued)

Sample number ^a	Depth (cm)	Radionuclide concentration (pCi/g) ^b		
		²²⁶ Ra	²³² Th	²³⁸ U
<i>Biased samples^d</i>				
B5A	0-15	1.2 ± 0.1	21 ± 0.5	230 ± 10
B5B	15-30	0.83± 0.1	7.7 ± 0.2	130 ± 8
B5C	30-45	0.48± 0.03	1.4 ± 0.07	25 ± 1
B6A	0-15	1.2 ± 0.2	1.8 ± 0.4	2000 ± 200
B6B	15-30	0.56± 0.09	1.2 ± 0.2	160 ± 7
B7A	0-15	0.63± 0.1	14 ± 0.5	32 ± 3
B7B	15-30	0.61± 0.05	4.0 ± 0.1	11 ± 2
B8A	0-15	0.46± 0.1	0.78± 0.2	620± 10
B8B	15-30	0.70± 0.1	0.69± 0.2	640± 20
B8C	30-45	0.50± 0.07	0.71± 0.1	160± 7

^aLocations of soil samples are shown on Fig .5

^bIndicated counting error is at the 95% confidence level (± 2σ).

^cSystematic samples are taken at locations irrespective of gamma exposure rates.

^dBiased samples are taken from areas with elevated gamma exposure rates.

*Samples from adjacent private properties VB11, VB12, VB13, taken from adjoining bay area.

**Sample B3C was taken ~1.5 ft east of B3A sample hole. Surface contamination was monitored with the gamma scintillator until primary contaminant was found.

Table 4. Concentration of radionuclides in lobster samples from Beverly Harbor, Beverly, Massachusetts

Location ^a	Sample number	Radionuclide concentration (pCi/g)		
		²²⁶ Ra	²³² Th	²³⁸ U
<i>Edible parts</i>				
1	F001	0.020±0.03	0.001 ±0.002	0.001±0.003
	F003	0.027±0.1	0.0004±0.0005	0.002±0.003
2	F010	0.024±0.03	0.0002±0.0004	0.002±0.002
	F011	0.038±0.05	0.001 ±0.001	0.002±0.003
3	F021	0.006±0.009	0.0003 ±0.001	0.003±0.002
	F022	0.070±0.1	0.00004±0.001	0.002±0.003
4	F031	0.011±0.02	0.0003±0.0004	0.006±0.004
	F032	0.032±0.04	0.0005±0.002	0.003±0.003
<i>Inedible parts</i>				
1	F002	0.032±0.04	0.0002 ±0.001	0.017±0.006
2	F012	0.038±0.03	0.00005±0.00009	0.002±0.002
3	F020	0.016±0.02	0.0003 ±0.001	0.004±0.002
4	F030	0.024±0.05	0.001 ±0.001	0.004±0.002

^a Trap Locations are shown on Figs. 1 and 5.

INTERNAL DISTRIBUTION

1. B. A. Berven	20. R. E. Rodriguez
2. R. F. Carrier	21. P. S. Rohwer
3. W. D. Cottrell	22-24. R. E. Swaja
4-9. R. D. Foley	25. M. S. Uziel
10. R. O. Hultgren	26. J. K. Williams
11-15. C. A. Johnson	27. Central Research Library
16. S. V. Kaye	28-29. Laboratory Records
17. M. E. Murray	30. Laboratory Records-RC
18. P. T. Owen	31. ORNL Patent Section
19. D. A. Roberts	32. ORNL Technical Library, Y-12
	33-38. MAD Records Center

EXTERNAL DISTRIBUTION

- 39. J. D. Berger, Oak Ridge Associated Universities, E/SH Division, Environmental Survey and Site Assessment Program, P.O. Box 117, Oak Ridge, TN 37831-0117
- 40. James J. Fiore, Director, Office of Eastern Area Programs, Office of Environmental Restoration, U.S. Department of Energy, (EM-42), Trevion II, Washington, DC 20585
- 41-43. G. K. Hovey, Bechtel National, Inc., FUSRAP Department, Oak Ridge Corporate Center, 151 Lafayette Drive, P.O. Box 350, Oak Ridge, TN 37831-0350
- 44. L. K. Price, Director, Former Sites Restoration Division, Oak Ridge Field Office, U.S. Department of Energy, P.O. Box 2001, Oak Ridge, TN 37831-8723
- 45. James W. Wagoner II, Director, Division of Off-Site Programs, Office of Eastern Area Programs, Office of Environmental Restoration, U.S. Department of Energy, (EM-421), Trevion II, Washington DC 20585
- 46-50. W. Alexander Williams, Designation and Certification Manager, Division of Off-Site Programs, Office of Eastern Area Programs, Office of Environmental Restoration, U.S. Department of Energy, (EM-421), Trevion II, Washington DC 20585
- 51. C. D. Young, Office of Technical Services, Roy F. Weston, Inc., 12800 Middlebrook Road, Suite 207, Germantown, MD 20874
- 52-56. Office of Scientific and Technical Information, U.S. Department of Energy, P.O. Box 62, Oak Ridge, TN 37831

END

**DATE
FILMED**

11 / 6 / 92