ORNL/RASA-95/16

**OAK RIDGE
NATIONAL
LABORATORY**

LOCKHEED MARTIN

**Results of the Independent
Radiological Verification Survey
at 4400 Piehl Road, Ottawa Lake,
Michigan (BTO002)**

**M. E. Murray
K. S. Brown**

MANAGED BY
LOCKHEED MARTIN ENERGY SYSTEMS, INC.
FOR THE UNITED STATES
DEPARTMENT OF ENERGY

UCN-13573 (36 6-85)

MASTER

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

This report has been reproduced directly from the best available copy.

Available to DOE and DOE contractors from the Office of Scientific and Technical Information, P.O. Box 62, Oak Ridge, TN 37831; prices available from (423) 576-8401, FTS 626-8401.

Available to the public from the National Technical Information Service, U.S. Department of Commerce, 5285 Port Royal Rd., Springfield, VA 22161.

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

HEALTH SCIENCES RESEARCH DIVISION
Environmental Restoration and Waste Management Non-Defense Programs
(Activity No. EX 20 20 01 0; ADS1310AA)

**Results of the Independent Radiological
Verification Survey at 4400 Piehl Road, Ottawa Lake,
Michigan (BTO002)**

M. E. Murray, K. S. Brown

Date Issued - April 1996

Investigation Team
R. D. Foley—Measurement Applications and Development Manager
M. E. Murray – Survey Team Leader

Survey Team Members

R. L. Coleman	D. E. Rice
R. C. Gosslee	D. A. Rose
S. P. McKenzie	P. F. Tiner

Work performed by the
MEASUREMENT APPLICATIONS AND DEVELOPMENT GROUP

Prepared by the
OAK RIDGE NATIONAL LABORATORY
Oak Ridge, Tennessee 37831-6285
managed by
LOCKHEED MARTIN ENERGY RESEARCH CORP.
for the
U. S. DEPARTMENT OF ENERGY
under contract number DE-AC05-96OR22464

CONTENTS

LIST OF FIGURES	v
LIST OF TABLES	vii
ACKNOWLEDGMENTS	ix
ABSTRACT	xi
INTRODUCTION	1
VERIFICATION PROCEDURES	2
VERIFICATION SURVEY RESULTS	2
CONCLUSIONS	3
REFERENCES	3

LIST OF FIGURES

- 1 Diagram of the property at 4400 Piehl Road, Ottawa Lake, Michigan
showing remediated areas south and northwest of the residence 4
- 2 Locations of verification systematic and biased samples south of the residence
at 4400 Piehl Road, Ottawa Lake, Michigan 5
- 3 Locations of verification systematic and biased samples northwest of the residence
at 4400 Piehl Road, Ottawa Lake, Michigan 6

LIST OF TABLES

1	Applicable guidelines for protection against radiation	7
2	Average background radiation levels for the Michigan area	8
3	Concentrations of radionuclides in soil verification samples from 4400 Piehl Road, Ottawa Lake, Michigan	9

ACKNOWLEDGMENTS

This project was sponsored by the Office of Environmental Restoration, U.S. Department of Energy, under contract DE-AC05-84OR21400 with Lockheed Martin Energy Systems, Inc. The authors wish to acknowledge the contributions of D. A. Rose, D. A. Roberts, J. M. Lovegrove and T. R. Stewart of the Measurement Applications and Development Group, Oak Ridge National Laboratory, for sample preparation and participation in the analyses, editing, graphics and reporting of data for this survey.

ABSTRACT

At the request of the U.S. Department of Energy (DOE), a team from Oak Ridge National Laboratory (ORNL) conducted an independent radiological verification survey at 4400 Piehl Road, Ottawa Lake, Michigan. The survey was performed in November and December of 1994. The purpose of the survey was to verify that the site was remediated to levels below DOE guidelines for FUSRAP sites.

Results of the independent radiological verification survey at 4400 Piehl Road, Ottawa Lake, Michigan confirm that the residual uranium contamination at the site is below DOE FUSRAP guidelines for unrestricted use.

**Results of the Independent Radiological Verification Survey
at 4400 Piehl Road, Ottawa Lake,
Michigan (BTO002)***

INTRODUCTION

During the early and mid-1940s, Baker Brothers, Inc., in Toledo, Ohio, fabricated uranium slugs from processed uranium metals under subcontract to the Manhattan Engineer District (MED). This commercial property consisted of several buildings and grounds covered with either asphalt or concrete, except for a dirt courtyard at the northwest end of the site. Results of a survey by Oak Ridge National Laboratory (ORNL) indicated partial contamination with ^{238}U , and the Baker property was officially included in the FUSRAP program in 1992.¹ Earlier that year the Baker Brothers assets were liquidated, and the property was divided and sold to two independent companies. One part of the property was resold in the summer of 1992. The new owner contacted ORNL and inquired about the radiological status of his property. Through this conversation it was learned that soil from the former Baker Brothers site may have been moved to a site in Michigan.²

In September of 1992 the Measurement Applications and Development Group at ORNL conducted a radiological survey at 4400 Piehl Road, Ottawa Lake, Michigan at the request of the Department of Energy (DOE), since soil had allegedly been hauled to this site from the former Baker property in Toledo, Ohio.² The property is in a semirural area approximately 15 miles northwest of Toledo, Ohio. An occupied residence, barn and pond are located on the site of approximately seven acres. Isolated spots of uranium contamination were identified in two general areas located to the northwest and south of the house where transported soil was allegedly placed.²

At the request of DOE, a team from ORNL conducted an independent radiological verification survey at 4400 Piehl Road, Ottawa Lake, Michigan. The survey was performed in November and December of 1994. The purpose of the survey was to verify that radioactivity from residues of ^{238}U was remediated to a level below acceptable DOE guideline levels for FUSRAP sites by Bechtel National, Inc. (BNI). Figure 1 is a diagram of the site overlaid by the grid used by ORNL for remediation activities.

*The survey was performed by members of the Measurement Applications and Development Group of the Health Sciences Research Division at Oak Ridge National Laboratory under DOE contract DE-AC05-84OR21400.

VERIFICATION PROCEDURES

A description of the typical survey methods and instrumentation providing guidance for the verification survey may be found in *Measurement Applications and Development Group Guidelines*, ORNL-6782 (January 1995).³

Gamma radiation levels were determined using portable NaI gamma scintillation meters; beta/gamma measurements were made with GM "pancake" probes. Samples were screened in the field laboratory using a gamma spectrometer and a shielded GM tube.

The survey of the property included the following:

- A gamma scan and measurement of beta-gamma radiation levels in the two contaminated areas south of the residence ("front area") and northwest of the residence ("back area") as shown in Fig. 1.
- Sampling and radionuclide analysis of verification systematic and biased samples from the front and back areas. Figure 2 is a diagram of sample locations in the front area south of the residence. Figure 3 is a diagram of sample locations in the back area northwest of the residence. Systematic samples were collected on a 5-meter grid. Biased samples were collected in areas where radiation was detected above background radiation.

A final gamma scan was performed around the perimeter of both areas. In addition to conducting independent radiological surveys, ORNL staff reviewed the radiological survey data resulting from BNI post-remedial action work.

VERIFICATION SURVEY RESULTS

DOE guidelines are summarized in Table 1. Typical background radionuclide concentrations for the Michigan area are presented in Table 2. These data are provided for comparison with survey results presented in this section. Background concentrations have not been subtracted from radionuclide concentrations measured in soil samples.

Where sample results indicated ^{238}U concentrations above the guideline, either the contaminated soil was subsequently removed, the "hot spot" criteria were not exceeded, or the average area "100-m²" concentration guideline was not exceeded. In most cases, BNI removed the contaminated soil.

The property at 4400 Piehl Road, Ottawa Lake, Michigan was verified to be within DOE guidelines at the end of the verification survey. Results of laboratory analysis of radionuclide concentrations of ^{238}U in verification systematic and biased soil samples are listed in Table 3.

CONCLUSIONS

Review of BNI survey results by ORNL, and the independent radiological verification survey by ORNL at 4400 Piehl Road, Ottawa Lake, Michigan, confirm that the site meets the DOE radiological guidelines for unrestricted use.

REFERENCES

1. R. D. Foley and L. M. Floyd, *Radiological Survey of the Former Baker Brothers, Inc. Site, 2551-2555 Harleau Place, Toledo, Ohio (BTO001)*, ORNL/RASA-90/8, Martin Marietta Energy Systems, Inc., Oak Ridge Natl. Lab., March 1992.
2. R. D. Foley and C. A. Johnson, *Radiological Survey Results at 4400 Piehl Road, Ottawa Lake, Michigan (BTO002)*, ORNL/RASA-93/1, Martin Marietta Energy Systems, Inc., Oak Ridge Natl. Lab., April 1993.
3. *Measurement Applications and Development Group Guidelines*, ORNL-6782, Martin Marietta Energy Systems, Inc., Oak Ridge Natl. Lab., January 1995.

Fig. 1. Diagram of the property at 4400 Piehl Road, Ottawa Lake, Michigan showing remediated areas south and northwest of the residence.

Fig. 2. Locations of verification systematic and biased samples south of the residence at 4400 Piehl Road, Ottawa Lake, Michigan.

Fig. 3. Locations of verification systematic and biased samples northwest of the residence at 4400 Piehl Road, Ottawa Lake, Michigan.

**Table 1. Applicable guidelines for protection against radiation
(Limits for uncontrolled areas)**

Mode of exposure	Exposure conditions	Guideline value
Total residual surface contamination ^a	²³⁸ U, ²³⁵ U, U-natural (alpha emitters)	
	Maximum	15,000 dpm/100 cm ²
	Average	5,000 dpm/100 cm ²
	Removable	1,000 dpm/100 cm ²
Derived concentrations	Total uranium	35 pCi/g ^{b, c}
Guideline for non-homogeneous contamination (used in addition to the 100-m ² guideline) ^d	Applicable to locations with an area ≤ 25 m ² , with significantly elevated concentrations of radionuclides ("hot spots")	$G_A = G_i(100/A)^{1/2}$, where G_A = guideline for "hot spot" of area (A) G_i = guideline averaged over a 100-m ² area

^aDOE surface contamination guidelines are consistent with *NRC Guidelines for Decontamination at Facilities and Equipment Prior to Release for Unrestricted Use or Termination of Licenses for By-Product, Source, or Special Nuclear Material*, May 1987.

^bMemo, J. W. Wagoner II, Director, Off-Site/Savannah River Programs Division, Office of Eastern Area Programs, Office of Environmental Restoration, U.S. DOE, to L. K. Price, Director, Former Sites Restoration Division, Oak Ridge Field Office, U.S. DOE, November 28, 1994.

^cSince the contaminant was normal uranium, the guideline value for ²³⁸U was 17.5 pCi/g.

^dDOE guidelines specify that every reasonable effort shall be made to identify and to remove any source that has a concentration exceeding 30 times the guideline value, irrespective of area (adapted from *Revised Guidelines for Residual Radioactive Material at FUSRAP and Remote SFMP Sites*, April 1987).

Sources: Adapted from U.S. Department of Energy, DOE Order 5400.5, April 1990, and U.S. Department of Energy, *Guidelines for Residual Radioactive Material at Formerly Utilized Sites Remedial Action Program and Remote Surplus Facilities Management Program Sites*, Rev. 2, March 1987; and U. S. Department of Energy Radiological Control Manual, DOE N 5480.6 (DOE/EH-256T), June 1992.

Table 2. Average background radiation levels for the Michigan area ^a

Type of radiation measurement or sample	Radiation level or radionuclide concentration
Gamma exposure rate at ground surface ($\mu\text{R/h}$)	no data
Concentration of radionuclides in soil (pCi/g) ^b	
²³² Th	0.5
²²⁶ Ra	1.0
²³⁸ U	0.8

^aSource: T. E. Myrick, B. A. Berven, and F. F. Haywood, *State Background Radiation Levels: Results of Measurements Taken During 1975–1979*, ORNL/TM-7343, Martin Marietta Energy Systems, Inc., Oak Ridge Natl. Lab., November 1981.

^bThese values represent the average normal radionuclide concentrations in the state of Michigan.

**Table 3. Concentrations of radionuclides in soil verification samples
at 4400 Piehl Road, Ottawa Lake, Michigan**

Sample ID ^a	Depth (cm)	Radionuclide concentration (pCi/g) ^b		
		²³⁸ U	²²⁶ Ra	²³² Th
Systematic samples ^c				
VS1	0-15	7.0 ± 1.5	0.4 ± 0.01	0.3 ± 0.02
VS2	0-15	6.0 ± 1.5	0.6 ± 0.1	0.3 ± 0.1
VS3	0-15	0.9 ± 0.3	0.5 ± 0.1	0.3 ± 0.1
VS4	0-15	0.4 ± 0.2	0.4 ± 0.1	0.3 ± 0.1
VS5	0-15	5.0 ± 1.0	0.4 ± 0.1	0.3 ± 0.1
VS6	0-15	0.8 ± 0.3	0.4 ± 0.04	0.2 ± 0.1
VS7	0-15	5.7 ± 0.8	0.4 ± 0.04	0.2 ± 0.1
VS8	0-15	6.5 ± 1.1	0.4 ± 0.04	0.3 ± 0.1
VS9	0-15	2.0 ± 0.2	0.3 ± 0.04	0.3 ± 0.1
VS10	0-15	0.8 ± 0.2	0.3 ± 0.1	0.3 ± 0.1
VS11	0-15	3.7 ± 0.2	0.5 ± 0.1	0.3 ± 0.1
VS12	0-15	1.6 ± 0.4	0.4 ± 0.1	0.3 ± 0.1
VS13	0-15	7.0 ± 2.0	0.4 ± 0.1	0.3 ± 0.1
VS14	0-15	0.6 ± 0.2	0.4 ± 0.1	0.4 ± 0.1
VS15	0-15	10 ± 2	0.5 ± 0.1	0.3 ± 0.1
VS16	0-15	1.5 ± 0.6	1.0 ± 0.1	0.3 ± 0.1
VS17	0-15	9.0 ± 2.0	0.5 ± 0.1	0.3 ± 0.1
VS18	0-15	0.5 ± 0.2	0.5 ± 0.1	0.4 ± 0.1
VS19	0-15	7.0 ± 1.0	0.5 ± 0.1	0.3 ± 0.1
VS20	0-15	10 ± 3	0.7 ± 0.1	0.3 ± 0.1
VS21	0-15	5.3 ± 1.1	0.5 ± 0.1	0.3 ± 0.1
VS22	0-15	0.7 ± 0.3	0.6 ± 0.1	0.4 ± 0.04
VS23	0-15	19 ± 2	0.4 ± 0.1	0.3 ± 0.1
VS24	0-15	5.0 ± 1.0	0.5 ± 0.1	0.3 ± 0.1

Table 3 (continued)

Sample ID ^a	Depth (cm)	Radionuclide concentration (pCi/g) ^b		
		²³⁸ U	²²⁶ Ra	²³² Th
VS25	0-15	1.6 ± 0.3	0.4 ± 0.1	0.2 ± 0.1
VS26	0-15	3.0 ± 1.5	0.5 ± 0.1	0.3 ± 0.1
VS27	0-15	7.0 ± 1.5	0.4 ± 0.1	0.3 ± 0.1
VS28	0-15	1.3 ± 0.4	0.4 ± 0.1	0.2 ± 0.1
VS29	0-15	0.5 ± 0.2	0.3 ± 0.1	0.2 ± 0.1
VS30	0-15	0.6 ± 0.2	0.4 ± 0.04	0.3 ± 0.1
VS31	0-15	0.6 ± 0.2	0.5 ± 0.1	0.3 ± 0.1
VS32	0-15	1.8 ± 0.5	0.4 ± 0.04	0.3 ± 0.1
VS33	0-15	1.4 ± 0.2	0.5 ± 0.1	0.3 ± 0.1
VS34	0-15	1.0 ± 0.3	0.5 ± 0.1	0.3 ± 0.1
VS35	0-15	1.3 ± 0.6	0.4 ± 0.04	0.2 ± 0.1
VS36	0-15	4.2 ± 0.7	0.5 ± 0.1	0.4 ± 0.1
VS37	0-15	1.5 ± 0.4	0.4 ± 0.04	0.3 ± 0.1
VS38	0-15	1.6 ± 0.4	0.6 ± 0.1	0.4 ± 0.1
VS39	0-15	1.2 ± 0.5	0.6 ± 0.1	0.2 ± 0.1
VS40	0-15	4.1 ± 0.8	0.4 ± 0.1	0.3 ± 0.1
VS41	0-15	0.5 ± 0.2	0.3 ± 0.04	0.2 ± 0.1
VS42	0-15	1.3 ± 0.2	0.5 ± 0.1	0.3 ± 0.1
VS43	0-15	1.4 ± 0.5	0.5 ± 0.1	0.3 ± 0.1
VS44	0-15	20 ± 1	0.4 ± 0.1	0.3 ± 0.1
VS45	0-15	1.2 ± 0.2	0.5 ± 0.1	0.3 ± 0.1
VS46	0-15	0.6 ± 0.2	0.6 ± 0.1	0.3 ± 0.1
VS47	0-15	3.7 ± 0.6	0.6 ± 0.1	0.2 ± 0.1
VS48	0-15	3.7 ± 0.6	0.5 ± 0.2	0.2 ± 0.1
VS49	0-15	2.2 ± 0.4	0.4 ± 0.1	0.1 ± 0.1

Table 3 (continued)

Sample ID ^a	Depth (cm)	Radionuclide concentration (pCi/g) ^b		
		²³⁸ U	²²⁶ Ra	²³² Th
VS50	0-15	43 ± 8	0.6 ± 0.1	0.5 ± 0.1
VS51	0-15	5.2 ± 0.6	0.4 ± 0.1	0.4 ± 0.1
VS52	0-15	1.8 ± 0.3	0.7 ± 0.1	0.3 ± 0.1
VS53	0-15	7.3 ± 0.6	0.5 ± 0.1	0.3 ± 0.1
VS54	0-15	5.8 ± 0.6	0.6 ± 0.1	0.1 ± 0.1
VS55	0-15	1.7 ± 0.4	0.2 ± 0.1	0.3 ± 0.2
VS56	0-15	1.8 ± 0.5	0.5 ± 0.2	0.1 ± 0.1
VS57	0-15	19 ± 1	0.7 ± 0.2	0.6 ± 0.2
VS58	0-15	1.8 ± 0.4	0.5 ± 0.1	0.3 ± 0.1
VS59	0-15	1.7 ± 0.4	0.4 ± 0.1	0.1 ± 0.04
VS60	0-15	2.2 ± 0.3	0.6 ± 0.1	0.1 ± 0.03
VS61	0-15	1.7 ± 0.4	0.3 ± 0.1	0.1 ± 0.04
VS62	0-15	17 ± 1	0.6 ± 0.2	0.2 ± 0.1
VS63	0-15	2.1 ± 0.4	0.6 ± 0.1	0.2 ± 0.1
VS64	0-15	1.0 ± 0.3	0.4 ± 0.2	0.2 ± 0.1
VS65	0-15	2.2 ± 0.5	0.3 ± 0.1	<0.2
VS66	0-15	3.4 ± 0.6	0.5 ± 0.2	0.1 ± 0.04
VS67	0-15	1.1 ± 0.3	0.5 ± 0.2	0.2 ± 0.04
VS68A	0-15	1.7 ± 0.4	0.5 ± 0.2	0.1 ± 0.04
VS68B	15-30	1.5 ± 0.4	0.4 ± 0.2	0.1 ± 0.1
VS69A	0-15	3.2 ± 0.5	0.4 ± 0.2	0.1 ± 0.04
VS69B	15-30	1.0 ± 0.3	0.6 ± 0.2	0.2 ± 0.1
VS70	0-15	1.4 ± 0.3	0.4 ± 0.1	0.3 ± 0.1
VS71A	0-15	56 ± 3	0.3 ± 0.2	0.3 ± 0.1
VS71B	15-30	7.0 ± 0.8	0.4 ± 0.1	0.3 ± 0.1
VS72	0-15	3.4 ± 0.5	0.5 ± 0.1	0.5 ± 0.1

Table 3 (continued)

Sample ID ^a	Depth (cm)	Radionuclide concentration (pCi/g) ^b		
		²³⁸ U	²²⁶ Ra	²³² Th
VS73	0-15	2.8 ± 0.5	0.7 ± 0.2	0.8 ± 0.2
VS74	0-15	4.7 ± 0.5	0.3 ± 0.1	0.2 ± 0.1
VS75	0-15	1.0 ± 0.3	0.3 ± 0.2	0.1 ± 0.1
VS76	0-15	7.8 ± 0.9	0.6 ± 0.2	0.3 ± 0.1
VS77	0-15	2.2 ± 0.4	0.6 ± 0.1	0.2 ± 0.1
VS78	0-15	1.3 ± 0.3	0.3 ± 0.1	0.2 ± 0.1
VS79	0-15	12 ± 2	0.6 ± 0.2	0.6 ± 0.2
VS80	0-15	0.8 ± 0.2	0.5 ± 0.2	0.2 ± 0.1
VS81	0-15	16 ± 1	0.7 ± 0.2	0.4 ± 0.1
VS82	0-15	7.2 ± 0.9	0.4 ± 0.2	0.2 ± 0.1
VS83	0-15	0.5 ± 0.2	0.3 ± 0.1	0.2 ± 0.1
VS84	0-15	1.3 ± 0.3	0.4 ± 0.1	0.4 ± 0.1
VS85	0-15	0.7 ± 0.2	0.4 ± 0.2	0.1 ± 0.03
VS86	0-15	1.5 ± 0.3	0.4 ± 0.1	0.3 ± 0.1
VS87	0-15	1.1 ± 0.3	0.2 ± 0.1	0.1 ± 0.1
VS88	0-15	1.1 ± 0.2	0.4 ± 0.1	0.2 ± 0.1
VS89	0-15	2.0 ± 0.2	0.3 ± 0.1	0.1 ± 0.1
VS90	0-15	1.5 ± 0.4	0.4 ± 0.2	0.2 ± 0.04
VS91	0-15	2.0 ± 0.4	0.4 ± 0.2	0.2 ± 0.04
VS92	0-15	0.8 ± 0.2	0.2 ± 0.1	0.1 ± 0.02
VS93	0-15	6.8 ± 0.8	0.5 ± 0.2	0.3 ± 0.2
VS94	0-15	25 ± 3	0.7 ± 0.1	0.4 ± 0.1
VS95	0-15	6.8 ± 0.8	0.6 ± 0.2	0.4 ± 0.1
<i>Biased samples^d</i>				
B1	0-15	25 ± 3	0.4 ± 0.1	0.3 ± 0.1

Table 3 (continued)

Sample ID ^a	Depth (cm)	Radionuclide concentration (pCi/g) ^b		
		²³⁸ U	²²⁶ Ra	²³² Th
B2	0-15	110 ± 30	0.4 ± 0.1	0.3 ± 0.1
B3	0-15	6.6 ± 1.2	0.4 ± 0.1	0.3 ± 0.1
B4	0-15	2.6 ± 0.5	0.5 ± 0.1	0.3 ± 0.1
B5	0-15	19 ± 1	0.5 ± 0.1	0.3 ± 0.1
B6	0-15	29 ± 2	0.6 ± 0.1	0.3 ± 0.1
B7	0-15	19 ± 2	0.3 ± 0.1	0.2 ± 0.1
B8	0-15	39 ± 5	0.6 ± 0.1	0.3 ± 0.1
B9	0-15	31 ± 1	0.5 ± 0.1	0.2 ± 0.1
B10	0-10	14 ± 1	0.5 ± 0.1	0.1 ± 0.1
B11	0-17	10 ± 2	0.7 ± 0.2	0.4 ± 0.1
B12	0-15	2.0 ± 0.3	0.6 ± 0.1	0.3 ± 0.1
B13	0-15	7.7 ± 0.6	0.6 ± 0.2	0.5 ± 0.1

^aSample locations are shown in Figs. 2 and 3.

^bIndicated counting error is at the 95% confidence level ($\pm 2\sigma$).

^cSystematic samples are taken at locations irrespective of gamma exposure rates. Sample values above guidelines, when averaged with surrounding samples, indicated concentrations within DOE guidelines.

^dBiased samples are taken from areas with elevated gamma exposure rates. Where sample results indicated ²³⁸U concentrations above the guideline, either the contaminated soil was subsequently removed, the "hot spot" criteria were not exceeded, or the average area "100-m²" concentration guideline was not exceeded. In most cases, BNI removed the contaminated soil.

INTERNAL DISTRIBUTION

1-2. K. J. Brown	12. R. E. Swaja
3. R. F. Carrier	13. M. S. Uziel
4. R. D. Foley	14. J. K. Williams
5. R. C. Gosslee	15-17. Laboratory Records
6. C. A. Johnson	18. Laboratory Records - RC
7-8. M. E. Murray	19. Central Research Library
9. P. T. Owen	20. ORNL Technical Library, Y-12
10. D. A. Roberts	21. ORNL Patent Section
11. R. E. Rodriguez	22-27. MAD Records Center

EXTERNAL DISTRIBUTION

- 28. D. G. Adler, Former Sites Restoration Division, Oak Ridge Field Office, U.S. Department of Energy, P. O. Box 2001, Oak Ridge, TN 37831-8723
- 29. W. L. Beck, ORISE, E/ESD, 1299 Bethel Valley Road, Oak Ridge, TN 37831
- 30. J. J. Fiore, Director, Office of Eastern Area Programs, Office of Environmental Restoration, Cloverleaf Bldg. (EM-24) U. S. Department of Energy, 19901 Germantown Rd., Germantown, MD 20874-1290
- 31. Jack Russell, 12850 Middlebrook Road, Suite 210, Germantown, MD 20874
- 32. A. G. Toddings, FUSRAP Project Administrator, Bechtel National, Inc., FUSRAP Department, Oak Ridge Corporate Center, 151 Lafayette Drive, P.O. Box 350, Oak Ridge, TN 37831-0350
- 33. FUSRAP Document Center, Science Applications International Corp., P.O. Box 2501, 301 Laboratory Road, Oak Ridge, TN 37831
- 34. L. K. Price, Director, Former Sites Restoration Division, Oak Ridge Field Office, U.S. Department of Energy, P.O. Box 2001, Oak Ridge, TN 37831-8723
- 35. Albert Johnson, Program Manager, Formerly Utilized Sites Remedial Action Program, EM-421, U.S. Department of Energy, Cloverleaf Building, 19901 Germantown Road, Germantown, MD 20874-1290
- 36-38. W. Alexander Williams, Designation and Certification Manager, FUSRAP Team, Office of Eastern Area Programs, Office of Environmental Restoration, U.S. Department of Energy, Cloverleaf Bldg. (EM-421), 19901 Germantown Road, Germantown, MD 20874-1290
- 39-41. Office of Assistant Manager, Energy Research and Development, DOE Oak Ridge Operations, P.O. Box 2001, Oak Ridge, TN 37831-8600
- 42-44. Office of Scientific and Technical Information, U.S. Department of Energy, P.O. Box 62, Oak Ridge, TN 37831