FEB 7 1997

SANDIA REPORT

SAND96-2629 • UC-900

Unlimited Release

Printed January 1997

Wellbore Enlargement Investigation: Potential Analogues to the Waste Isolation Pilot Plant During Inadvertent Intrusion of the Repository

D. M. Boak, L. Dotson, R. Aguilar, D. W. Powers, G. Newman

Prepared by
Sandia National Laboratories
Albuquerque, New Mexico 87185 and Livermore, California 94550
for the United States Department of Energy
under Contract DE-AC04-94AL85000

Approved for public release; distribution is unlimited.

RECEIVED

FEB 14 1997

OSTI

MASTER

Issued by Sandia National Laboratories, operated for the United States Department of Energy by Sandia Corporation.

NOTICE: This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, nor any of their contractors, subcontractors, or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government, any agency thereof or any of their contractors or subcontractors. The views and opinions expressed herein do not necessarily state or reflect those of the United States Government, any agency thereof or any of their contractors.

Printed in the United States of America. This report has been reproduced directly from the best available copy.

Available to DOE and DOE contractors from
Office of Scientific and Technical Information
PO Box 62
Oak Ridge, TN 37831

Prices available from (615) 576-8401, FTS 626-8401

Available to the public from
National Technical Information Service
US Department of Commerce
5285 Port Royal Rd
Springfield, VA 22161

NTIS price codes
Printed copy: A05
Microfiche copy: A01

SAND96-2629
Unlimited Release
Printed January 1997

Distribution
Category UC-900

Wellbore Enlargement Investigation: Potential Analogs to the Waste Isolation Pilot Plant During Inadvertent Intrusion of the Repository

D.M. Boak
WIPP Performance Assessment
Code Development Department
Sandia National Laboratories
P.O. Box 5800
Albuquerque, NM 87185

L. Dotson
Compliance Support Department
Sandia National Laboratories
P.O. Box 5800
Albuquerque, NM 87185

R. Aguilar
YMP System Performance Assessments Department
Sandia National Laboratories
P.O. Box 5800
Albuquerque, NM 87185

D.W. Powers
HC 12 Box 87
Anthony, TX 79821

G. Newman
GRAM Inc.
8500 Menaul, NE
Albuquerque, NM 87112

ABSTRACT

This study involved the evaluation and documentation of cases in which petroleum wellbores were enlarged beyond the nominal hole diameter as a consequence of erosion during exploratory drilling, particularly as a function of gas flow into the wellbore during blowout conditions. A

DISTRIBUTION OF THIS DOCUMENT IS UNLIMITED

primary objective was to identify analogs to potential wellbore enlargement at the Waste Isolation Pilot Plant (WIPP) during inadvertent human intrusion. Secondary objectives were to identify drilling scenarios associated with enlargement, determine the physical extent of enlargement, and establish the physical properties of the formation in which the enlargement occurred. No analogs of sufficient quality to establish quantitative limits on wellbore enlargement at the WIPP disposal system were identified. However, some information was obtained regarding the frequency of petroleum well blowouts and the likelihood that such blowouts would bridge downhole, self-limiting the surface release of disposal-system material. Further work would be necessary, however, to determine the conditions under which bridging could occur and the extent to which the bridging might be applicable to WIPP. In addition, data on casing sizes of petroleum boreholes in the WIPP vicinity support the use of a 12-1/4 inch borehole size in WIPP performance assessment calculations. Finally, although data are limited, there was no evidence of significant wellbore enlargement in any of three blowouts that occurred in wellbores in the Delaware Basin (South Culebra Bluff Unit #1, Energy Research and Development Administration (ERDA) 6, and WIPP 12).

DISCLAIMER

Portions of this document may be illegible in electronic image products. Images are produced from the best available original document.

EXECUTIVE SUMMARY

The primary objective of this study was to identify analogs to potential wellbore enlargement at the Waste Isolation Pilot Plant (WIPP) and predict the greatest likely wellbore enlargement that could occur at WIPP during inadvertent intrusion by exploratory drilling. Data in the petroleum industry that could be used to quantify the extent of borehole enlargement during a blowout were limited, and a quantitative prediction of the greatest likely wellbore enlargement could not be developed at this time. Other interesting data from the petroleum industry were discovered, however, that provide qualitative insights into the typical causes, frequency, and consequences of petroleum-related blowouts.

A blowout can occur when the in situ pressure of the drilled formation becomes greater than the hydrostatic head generated by the drilling fluid in the wellbore. Data on blowouts in Canada suggest that only a small number of petroleum boreholes experiencing influx of formation fluids (kicks and blows) become actual blowouts with significant fluid flow to the surface and also suggest that a petroleum-related blowout is considered a low-probability event. Data from studies of U.S. (the Gulf Coast and Outer Continental Shelf) and Canadian petroleum operations in the mid-1980s indicate that blowouts occurred in approximately 2 to 9 wells per 10,000 drilled in these areas. These studies also indicate that the frequencies of blowouts occurring in petroleum-bearing formations have tended to decline over time, suggesting ongoing improvements in drilling and blowout control techniques. Moreover, virtually all petroleum blowouts have occurred while drilling into gas-bearing formations; about half occurred in exploratory wells, and the other half occurred in development wells. Additionally, data in one report indicate that 70 to 80% of the blowouts in wells drilled in Texas and Louisiana were controlled within five days.

Finally, WIPP performance assessment calculations for the 1996 compliance certification application (CCA) used a single borehole size of 12-1/4 inches for exploratory wells. Preliminary data gathered in the course of this investigation suggest that this borehole size is reasonably representative of the majority of petroleum boreholes that have been drilled within a 10-mile radius of WIPP. Note, however, that the results of this investigation cannot be used to directly corroborate the Cuttings results for the 1996 WIPP CCA since the CCA calculations used different mechanisms for blowout release than those investigated in this study.

Intentionally Left Blank

CONTENTS

EXECUTIVE SUMMARY.....	iii
ACRONYMS	vii
1. INTRODUCTION.....	1
2. APPROACH	3
2.1. Criteria for Analogs to WIPP for Wellbore Enlargement.....	3
3. RESULTS	7
3.1. Likelihood, Causes, and Control of Blowouts	7
3.1.1. Frequency of Blowouts	7
3.1.2. Causes and Control of Blowouts.....	8
3.1.3. Self-Limiting Nature of Some Blowouts	9
3.2. Blowouts in Proximity to WIPP.....	9
3.3. Blowouts Outside the WIPP Area.....	10
3.4. Current Drilling Practices	12
3.4.1. Casing and Cementing Standards	12
3.4.2. GIS/ArcView Database and Analysis	12
3.5. Coal Gas Production and Other Erosion Research	21
4. CONCLUSIONS.....	23
5. REFERENCES	25
APPENDIX A: D.W. POWERS, "BLOWOUTS DURING OIL AND GAS EXPLORATION IN SOUTHEASTERN NEW MEXICO," LETTER REPORT TO L.R. HILL, JULY 24, 1995.....	A-1
APPENDIX B: TELEPHONE CONTACTS FOR WELLBORE ENLARGEMENT INVESTIGATION	B-1
APPENDIX C: DEVELOPMENT OF GIS DATABASE AND ANALYSIS OF PETROLEUM WELLS IN THE WIPP VICINITY.....	C-1

TABLES

1. Atoka Reservoir Information	10
--------------------------------------	----

FIGURES

1. Map of the Delaware Basin and surrounding areas showing the location of the WIPP site.....	4
2. Schematic profile of typical producing oil well in the Livingston Ridge/Lost Tank field.....	13
3. Distribution of WIPP characterization boreholes and petroleum wells (including exploratory, production, disposal, injection, and abandoned wells) within a 10-mile radius of WIPP.	14
4. Established petroleum (oil and gas) fields in the WIPP vicinity.....	15
5. Distribution of oil and gas wells drilled in the WIPP vicinity	17
6. Distribution of water disposal and injection wells in the WIPP vicinity associated with petroleum production	18
7. Summary of internal casing diameters for all 548 well records.....	19
8. Summary of internal casing diameters for oil wells within a 10-mile radius of WIPP.....	20
9. Summary of internal casing diameters for oil and gas wells with known casing size	20

ACRONYMS

BOP	Blowout Preventer
CCA	Compliance Certification Application
ERCB	Canadian Energy Resource Conservation Board
GIS	Geographic Information System
NMBMMR	New Mexico Bureau of Mines and Mineral Resources
OCD	New Mexico Oil Conservation Division
OCS	Outer Continental Shelf
SFL	Spherically-Focused Log
SPM-2	Systems Prioritization Method - Second Iteration
USGS	U.S. Geological Survey
WIPP	Waste Isolation Pilot Plant

Intentionally Left Blank

1. INTRODUCTION

This study involved the evaluation and documentation of cases in which petroleum wellbores were enlarged beyond the nominal bit size (hole diameter) as a consequence of erosion from a blowout¹ during exploratory drilling. The primary objective was to identify analogs to potential wellbore enlargement at the Waste Isolation Pilot Plant (WIPP) to predict the greatest likely wellbore enlargement that might occur at WIPP during inadvertent intrusion by exploratory drilling. Secondary objectives were to identify drilling scenarios associated with enlargement, determine the physical extent of enlargement, and establish the physical properties of the formation in which the enlargement occurred. It was assumed that future drillers at the WIPP site would use drilling practices consistent with those currently in use, and that drillers would be unaware of the WIPP repository. While enlargement can occur for many reasons, this task focused on cases of blowout resulting from drilling into gas-filled formations. While the focus of the study was on petroleum wells, erosion associated with coal gas production and other erosion research was also considered.

The approach following this introduction describes the specific subtasks of the study and sets forth the criteria that were used to identify the analogs. The next section discusses the results of the research. The report closes with a conclusions section.

¹ A *blowout* is defined as "[a] complete loss of control of a flow of fluids from a well. [C]ontrol can only be regained by the installation of equipment to shut in or kill the well [i.e., operation of the blowout preventer (BOP) system], or by drilling a relief well" (ERCB, 1990).

Intentionally Left Blank

2. APPROACH

Specific subtasks for this study were to:

1. Investigate the likelihood and causes of blowouts and the typical control procedures.
2. Examine documented blowout occurrences to identify analogs to wellbore enlargement at WIPP. Blowout occurrences both in proximity to the WIPP site and outside the WIPP area were examined. A blowout was considered to be in proximity to WIPP if it occurred in the Delaware Basin in southeastern New Mexico. See Figure 1 for a map showing the Delaware Basin and surrounding areas. Key criteria used to determine the degree to which a documented blowout occurrence would be an appropriate analog to wellbore enlargement at WIPP appear in Section 2.1.
3. Review current drilling practices near WIPP that could affect the likelihood or severity of a blowout. This involved the development of a Geographic Information System (GIS) database to analyze information on petroleum wells in the vicinity of WIPP within the Salado formation. This information included well category, depth, and casing size. An analysis of the casing size data on petroleum wells near the WIPP site was also performed.

2.1. Criteria for Analogs to WIPP for Wellbore Enlargement

Key criteria used to determine the degree to which a documented blowout occurrence would be an appropriate analog to wellbore enlargement at WIPP during inadvertent intrusion by future exploratory drilling are described below. Note that, although the criteria focus on petroleum wells, erosion associated with coal gas production was also considered.

1. Whether the wellbore enlargement is unexpected, as would occur in an exploration of a largely undrilled area or when drilling into new, untested horizons. This could include drilling in a developed field if the operator is unfamiliar with the area.
2. Whether the formation is gas-filled.
3. The availability of information on the quantitative characteristics of the formation (such as permeability, porosity, degree of consolidation, presence of fractures, clastic or carbonate matrix, initial reservoir pressure, drilling depth, availability of open-hole geophysical logs and/or core data).

TRI-6342-251-3

Figure 1. Map of the Delaware Basin and surrounding areas showing the location of the WIPP site.

4. The availability of information on drilling characteristics, such as casing program and mud type and density.
5. Proximity of the wellbore to the WIPP site; whether the wellbore is in the Delaware Basin.
6. Similarity of the overall geologic strata and general scenario to that associated with exploratory drilling at the WIPP site, which has entailed drilling through bedded salt to reach oil or gas in deeper horizons.
7. Capability of discussing the case in the open literature: some data may reside in confidential industry files.

Intentionally Left Blank

3. RESULTS

This section presents the results of investigations into 1) the likelihood and causes of blowouts and the procedures used to attempt to control them; 2) blowouts in proximity to the WIPP site; 3) blowouts outside the WIPP area; 4) current drilling practices near the WIPP site that could affect the likelihood or severity of a blowout; 5) and coal gas production and other erosion research.

3.1. Likelihood, Causes, and Control of Blowouts

3.1.1. Frequency of Blowouts

In general, a petroleum blowout is considered a low-probability event (Golob and McShea, 1981). Blowouts are dangerous and costly to the driller, and therefore every attempt is made to avoid them. As stated by Santos (1989), "[B]lowouts are catastrophic events....[M]illions of dollars are spent just bringing a blowing well under control."

Golob and McShea (1981) report that a U.S. Geological Survey (USGS) study of 7,553 wells drilled in the Outer Continental Shelf (OCS) found that 30 blowouts occurred over an eight-year period, a rate of five blowouts per year per 10,000 wells drilled. Blowout frequencies in 1984 (Hughes et al., 1990) were approximately two per 10,000 wells in Louisiana and nine per 10,000 in Texas.² The number of blowouts also declined in each state after 1978 when mandatory well control training became a requirement. Hughes et al. (1990) also reported approximately 27 blowouts per 10,000 wells in the OCS for this same period, suggesting that there is significantly greater risk involved with drilling in the OCS. Given the significant differences between deep, offshore drilling (typical of drilling in the OCS) and onshore drilling conditions in and around WIPP, however, OCS data are likely to be overly conservative and unrealistic if applied directly to WIPP.

USGS data on blowouts in oil and gas wells drilled in the OCS between 1971 and 1978 indicate that 56% of blowouts occurred in exploratory wells and 44% occurred in development wells; all of the blowouts occurred in gas wells (Golob and McShea, 1981). Hughes et al. (1990) found similar results in 425 Gulf Coast blowouts (predominantly in Texas, Louisiana, and the OCS) occurring between 1960 and 1985: 93% of blowouts in shallow wells (less than 3,280 feet) were in gas-bearing formations.

The Canadian Energy Resource Conservation Board (ERCB) published reports between 1989 and 1993 containing information on several blowouts in Canada, but no data on wellbore enlargement were provided. Several of the cases list quartzite or sandstone as the formation type, but very little information on reservoir characteristics appears in these reports. ERCB (1994) reported a blowout frequency of two blowouts per 10,000 wells drilled in Alberta, Canada, in

² Areas of Texas and Louisiana are noted for shallow, high-porosity, unconsolidated gas-bearing sandstones, which can cause blowouts.

1993; this is roughly equivalent to Louisiana blowout rates in 1986 (Hughes et al., 1990). Interestingly, the ERCB (1993) also reported a 10-year average of five blows³ per 10,000 wells drilled and a 10-year kick rate of 37 per 1,000 wells drilled. Thus, the ERCB data suggest that only a very small portion of petroleum boreholes experiencing influx of formation fluids (kicks and blows) become actual blowouts with significant fluid flow to the surface.

3.1.2. Causes and Control of Blowouts

A blowout can occur when the in situ pressure of the drilled formation becomes greater than the hydrostatic head generated by the drilling fluid in the wellbore. The blowout occurs when the drilling system (including whatever portion of the wellbore is cased) cannot mechanically control fluid flow from the formation. Blowouts are of two types, surface and underground (Moore, 1975). A surface blowout is one in which downhole fluids flow from a subsurface reservoir to the surface. Reservoir fluids reach the surface through the drill string, through the annulus between the drill string and any casing, or between the casing and the formation. An underground blowout is one in which reservoir fluids flow from a formation uphole or downhole and into another formation.

Rocha (1993) describes the differences between a kick and a blowout and provides some detail on the steps an operator would generally take to attempt to control the kick and then (if unsuccessful) control the blowout.⁴ The blowout might be "shut in" mechanically if the operator thought that a behind-casing failure could be avoided (for example, by having cased a significant portion of the wellbore and thus created a good bond between the casing and the upper formations). Alternatively, the operator might choose to divert (i.e., vent) the flow to the surface through the drill string, relieving the downhole pressure, if there is concern about casing failure. (Note: Rocha (1993) reports a U. S. Minerals Management Service study in which diverter systems failed 46% of the time when used to control gas flow.) A blowout might also be brought under control by weighting up the mud system and attempting to "kill" the flow. Finally, very serious blowouts may require control through the drilling of relief wells that are drilled from a safe surface location to a bottom hole target very close to the blowout zone; mud is then pumped downhole to kill the blowout in the vicinity of the first borehole.

According to Hughes et al. (1990), the formation fluid that caused most Gulf Coast wells to blow out was gas. Hughes et al. (1990) found that the most common operations associated with blowouts were 1) tripping (bringing the drill bit off the bottom and back to the surface) for 27% of Texas wells and 34% of shallow wells and 2) drilling (57% of Louisiana wells). It is important to note that the frequency of blowouts has decreased over the years, and that blowout prevention and control technology is expected to continue to improve (Hughes et al., 1990).

³ A *blow* is a flow of fluids (gas, oil, water, mud, etc.) to the atmosphere from a well, which can be or is brought under control in a very short time-frame by closing equipment (control is gained almost immediately). A *kick* is any entry of water, gas, oil, or other formation fluid into the wellbore. Therefore, a blowout is an uncontrolled blow or kick. The term *blow* is not widely used in the U.S.

⁴ Further detail on BOP systems and well control techniques is available in the International Association of Drilling Contractors *Drilling Manual* (IADC, 1992).

According to the ERCB in Calgary, the leading cause of blowouts in Alberta, Canada, from 1984 to 1993 was human error (e.g., failing to maintain hydrostatic pressure on the formation). Other causes of blowouts include equipment failure (e.g., damaged valves), inadequate well design (e.g., insufficient mud density), or encountering an abnormally pressurized formation.

3.1.3. Self-Limiting Nature of Some Blowouts

Downhole bridging⁵ is mentioned in numerous articles as a means by which blowouts can be self-limiting. Interestingly, Hughes et al. (1990) found that 51% of shallow blowouts, 55% of OCS blowouts, and 57% of Louisiana blowouts (of the 37% that were brought under control in one day) were self-limited by bridging off. Hughes et al. (1990) also found that 52% of Texas blowouts, 37% of Louisiana blowouts, and 49% of OCS blowouts were under control within one day. Eighty percent of Texas blowouts and 71% of Louisiana blowouts were controlled within five days. Golob and McShea (1981) describe the Funiwa 5, a development well in the Niger River delta that took three weeks to bridge off.

3.2. Blowouts in Proximity to WIPP

An information search was conducted on blowouts in the Delaware Basin in southeastern New Mexico. This search included investigation and documentation of blowouts that occurred during oil and gas exploration and during WIPP site exploration and characterization. The full report appears in Appendix A (D.W. Powers, "Blowouts During Oil and Gas Exploration in Southeastern New Mexico," letter report to L. R. Hill, July 24, 1995).

In his report, Powers first described the blowouts that occurred while drilling wellbores Energy Research and Development Administration (ERDA) 6 and WIPP 12 during WIPP site exploration and characterization, when pressurized brines were encountered in the Castile Formation. ERDA 6 was not equipped with a BOP, and a blowout occurred that lead to an uncontrolled discharge of brine. The wellbore diameter did not change significantly as a result of the incident. A blowout also occurred in WIPP 12, and the wellbore reportedly did enlarge somewhat in the lower Salado, but Powers noted that the enlargement was "not significant." Note that a blowout in a pressurized brine formation is not an accurate analogy to a blowout in a gas formation.

Powers also identified a blowout that occurred during gas exploration at the South Culebra Bluff Unit #1 in 1978, approximately 16 miles west-southwest of the WIPP site. This blowout did not appear to produce significant enlargement in the zones examined.⁶ The blowout occurred

⁵ Bridging has been described (Gatlin, 1960) as a process by which particles travel into a void space and accumulate to create a mechanical barrier to flow thereby sealing off the void space. Gatlin discusses the process mainly in terms of designing systems to seal off formations experiencing an unwanted loss of drilling mud through fractures, but the mechanism is applicable to blowouts as well.

⁶ Numerous geophysical logging runs were made in this borehole, but only the September 14, 1978, runs occurred in a portion of the borehole exposed to erosion during the blowout and were made at a time before the well was worked over. There are numerous minor problems with the geophysical logs, but it appears that the borehole was not significantly enlarged in the zones examined. Note in particular the zone between the depths of 11,250 feet and approximately 11,620, which is within

in the Atoka gas formation at a depth of 11,769 feet and continued for 11 days before being brought under control on January 14, 1978. The well was allowed to produce from the blowout zone, which exposed the open hole from the base of the casing (at a depth of 6,355 feet) to erosion for approximately eight months. The Atoka produced at an initial rate of approximately 50 million cubic feet of gas per day, a very substantial rate. A total of approximately four billion cubic feet of gas was produced from the hole over a five month period that ended in June 1978. Table 1 provides basic reservoir properties of the Atoka formation.

Table 1. Atoka Reservoir Information (from the New Mexico Bureau of Mines and Mineral Resources (NMBMMR) Reservoir Database included in the Atlas of Major Rocky Mountain Gas Reservoirs (NMBMMR, 1993))

Reservoir Characteristic	Values
Average porosity (percent)	4.5
Minimum porosity (percent)	5.0
Maximum porosity (percent)	8.5
Temperature (degrees Fahrenheit)	178.5
Initial reservoir pressure (psia)	9,664
Initial reservoir pressure gradient(psi/ft)	0.71

Powers (Appendix A) also searched the New Mexico Oil Conservation Division (OCD) files for the period 1991 through 1995, but found no corresponding records of blowouts in southeastern New Mexico.

In summary, data from wells in the Delaware Basin in southeastern New Mexico indicate that even rather prolonged blowouts did not seem to result in significant wellbore enlargement.

3.3. Blowouts Outside the WIPP Area

The investigation turned to potential analogs outside the Delaware Basin where shaley, unconsolidated sands that could better approximate the behavior of degraded waste might exist. Several prominent individuals in the petroleum industry were contacted by telephone in an attempt to obtain information on blowouts outside the WIPP area. Nineteen knowledgeable individuals in industry (including Amoco and Mobil), academia (including Louisiana State University, Colorado School of Mines, and the University of Texas), the Gas Research Institute, and various consulting firms were interviewed. Five of the individuals contacted are considered experts in the area of blowouts. A list of these telephone contacts appears in Appendix B. The information obtained is summarized below.

approximately 150 feet of the blowout interval feet (see Run Two of the Dual Laterolog Micro-Spherically-Focused Log (SFL) in Appendix A).

None of the individuals who were contacted had ever obtained (or were aware of) any wellbore erosion or enlargement data associated with blowouts. Included among the contacts were Dr. Dave Powley and Dr. John S. Bradley, both retired from Amoco Production Company; these two individuals spent their careers working on research related to blowouts, and both individuals are widely published. Dr. Tony Podio of the University of Texas Department of Petroleum Engineering, one of the coauthors of a report on 425 Gulf Coast blowouts, also had not seen wellbore erosion or enlargement data. Dr. Adam Bourgoyne of Louisiana State University, a prominent figure in the field of petroleum drilling with 20 years of experience, was not aware of any wellbore erosion data. Similarly, Dr. Bill Mitchell of the Colorado School of Mines was not aware of any wellbore erosion or enlargement data.

Most of the individuals contacted believed that wellbore enlargement resulting from a blowout would be minimal. When drilling an oil or gas well, some upper portion of the borehole would typically be cased. A blowout would only erode the lower (uncased) portion of the wellbore unless it occurred between the casing and the formation. The most likely scenario is that the wellbore would collapse, leaving a smaller, not a larger, hole. Gas would escape from the wellbore, and solids would settle to the bottom of the collapsed hole. Dr. Adam Bourgoyne noted that gas is far less erosive than liquid. Brian Tarr of Mobil Exploration stated that the enlargement would depend on how strong the rock is; if the formation doesn't collapse, for example, it is probably also strong enough to not erode.

Some of the individuals contacted were not sure to what extent a wellbore might erode and noted that borehole enlargement would be difficult or impossible to measure because the hole is usually "lost" during the attempt to control the blowout. That is, the fluid (drilling mud) used to control the blowout destroys the productive capacity of that portion of the hole experiencing the blowout. Moreover, wellbore erosion data is generally not available, according to Steve Melzer of the University of Texas, because it is generally too dangerous to run caliper logs after a blowout.⁷

According to Roger Anderson of the OCD in Santa Fe, New Mexico, blowouts that were not associated with a serious accident or that did not impact the ground water supply are not required to be reported. He also stated that information on wellbore enlargement would not be reported to the OCD.

It is clear from these interviews that quantitative information on wellbore enlargement resulting from blowouts is not commonly available in the petroleum industry. There is a consensus that caliper log data (an initial focus of the investigation) does not generally exist for downhole zones that have undergone blowout. Moreover, many of the individuals contacted expressed concern that, even if caliper logs did exist, the borehole size information would be limited to the maximum extended diameter of the caliper arms used, which might be less than the diameter of the enlarged borehole diameter. Under these circumstances, the maximum limits of enlargement would remain unknown.

⁷ See Section 3.2, for an example of a blowout for which both before- and after- caliper logs were available (South Culebra Bluff Unit #1).

Other than the investigations by Powers, time limitations precluded detailed investigation of wellbores outside the Delaware Basin.

3.4. Current Drilling Practices

3.4.1. Casing and Cementing Standards

Controls on current drilling practices near the WIPP site are more stringent than in many areas of the state because WIPP is located in proximity to an area of large potash reserves known as the Carlsbad Potash District (Barker and Austin, 1993). Oil and gas wells drilled in the Potash District must meet special casing and cementing standards to protect the salt strata (including the Salado and Castile formations) from water, oil, and gas intrusions. A typical producing oil well in the vicinity of WIPP has three casing strings, as shown in Figure 2. Casing strings are hung from the surface, and the annular space between the casing and the hole is filled with cement, providing multiple barriers that limit both the likelihood of kicks and the potential loss of fluids during secondary production or disposal operations.

3.4.2. GIS/ArcView Database and Analysis

Information on well category, depth, and casing size for petroleum wells drilled through the Salado formation was obtained from the commercially available Dwrights/Petroleum Information Discover Scout database. The petroleum well information was downloaded to a Windows Excel spreadsheet and then transferred into an ArcView GIS database containing data associated with surface characterization boreholes for the WIPP Project. (See Appendix C for a description of the development of the GIS database.) The GIS was used to generate information on well location distribution, category, depth, and casing size in the form of maps, statistical plots, and tables. The results of this effort are described in Appendix C. Considerable efforts were made to verify data on the WIPP characterization boreholes. The petroleum data, however, have only been verified at a preliminary level.

3.4.2.1. DISTRIBUTION OF WIPP CHARACTERIZATION SURFACE BOREHOLES AND PETROLEUM INDUSTRY WELLS

Figure 3 shows the distribution of surface boreholes drilled for the WIPP site characterization and petroleum industry (oil and gas) wells (including exploratory, production, disposal, injection, and abandoned wells) within a 10-mile radius of WIPP. The distribution pattern of the petroleum wells reflects their groupings within approximately twelve established industry fields, shown in Figure 4. For example, the cluster of wells to the northwest of the WIPP land withdrawal boundary in Figure 4 is associated with the Cabin Lake field. The cluster of wells aligned from north to south just east of WIPP is within the Livingston Ridge field. The WIPP surface boreholes, drilled to characterize the general geology, stratigraphy, and hydrology of the WIPP site, are fairly well distributed within and around WIPP. Note that Figure 3 shows several

TRI-6342-4697-0

Figure 2. Schematic profile of typical producing oil well in the Livingston Ridge/Lost Tank field. (Depths indicated are approximate and are in feet below ground level.)

Figure 3. Distribution of WIPP characterization boreholes and petroleum wells (including exploratory, production, disposal, injection, and abandoned wells) within a 10-mile radius of WIPP.

Figure 4. Established petroleum (oil and gas) fields in the WIPP vicinity.

characterization boreholes outside the WIPP land withdrawal area. These were drilled to investigate the presence or absence of specific geologic features or processes (e.g., regional faulting, anticlinal structures, breccia pipes, and salt dissolution in the rocks near the proposed repository) that might affect the performance of WIPP.

The distribution of oil- and gas-producing wells in the WIPP vicinity is shown in Figure 5. (Note that Figure 5 does not include other petroleum-related wells such as dry and abandoned, disposal, injection, plugged and abandoned, and shut-in wells.) Gas is produced in deeper formations (such as the Morrow and Atoka formations, about 14,000 ft deep) than oil, which is typically produced in the Delaware Mountain Group formations (such as Cherry Canyon and Brushy Canyon, about 7,000 to 8,300 ft deep) in the Livingston Ridge/Lost Tank field.

Figure 6 shows the distribution of the wells classified as injection and disposal wells. The three injection wells, located within the Cabin Lake, Livingston Ridge, and Livingston Ridge East oil fields, respectively, are those where brine or other waters are injected into oil-producing formations to stimulate production. Disposal wells are used by the various petroleum companies for discarding brine and other waters generated during the pumping of oil reserves. Disposal wells may be shared by several petroleum companies operating within one or more of the industry petroleum reservoir fields (see Figure 4).

3.4.2.2. CASING SIZES

Mean borehole diameters and casing sizes (nominal internal diameter) were calculated from data from 548 well records in the Dwights/Petroleum Information Discover Scout database. (See analysis in Appendix C.) The database included information on petroleum (oil and gas) exploratory, production, disposal, and injection wells. The analysis showed that the most typical casing diameter for wells drilled within a 10-mile radius of the WIPP is 8.625 inches (71.5% of all 548 well records) (see Figure 7). Three hundred and sixty-one of these are oil wells—88% of all oil wells in the database ($n = 409$) (see Figures 8 and 9). This casing size is approximately equivalent to a 12-1/4 inch wellbore in the Salado Formation at a depth of approximately 2,150 feet (the depth of the WIPP repository). Wellbore casing sizes identified in this study were not uniform. Rather, the casing sizes were not normally distributed, with a minimum of 5.5 inches and a maximum of 13.375 inches.

Performance assessment calculations for the 1996 WIPP compliance certification application (CCA) used a single borehole size of 12-1/4 inches for exploratory wells; this is consistent with the data from Dwights database for oil wells within a 10-mile radius of the WIPP. Note, however, that the results of this investigation cannot be used to directly corroborate the Cuttings results for the 1996 WIPP CCA since the CCA calculations used different mechanisms for blowout release than those investigated in this study.

Figure 5. Distribution of oil- and gas-producing wells drilled in the WIPP vicinity (not including exploratory, disposal, injection, and abandoned wells) (based on information from Dwights/Petroleum Information Discover Scout database).

Figure 6. Distribution of water disposal and injection wells in the WIPP vicinity associated with petroleum production (based on information from Dwights/Petroleum Information Discover Scout database).

Figure 7. Summary of internal casing diameters for all 548 well records (based on information from Dwights/Petroleum Information Discover Scout database, casing sizes for all 548 well records).

Figure 8. Summary of internal casing diameters for oil wells within a 10-mile radius of WIPP (based on information from Dwights/Petroleum Information Discover Scout database).

Figure 9. Summary of internal casing diameters for oil and gas wells with known casing size (based on information from Dwights/Petroleum Information Discover Scout database). (Note that the data for oil casing size 5.5 are questionable for six of the seven wells indicated.)

3.5. Coal Gas Production and Other Erosion Research

References on erosion during gas production from coal seams (Mavor, 1991a; Mavor et al., 1991; Mavor, 1991b; Mavor et al., 1992; and Mavor and Logan, 1994) were investigated. Although research in this area initially seemed promising, none of the material provided information that was directly relevant to this investigation.

More promising information was found in Rocha (1993), who mentions the potential for research in civil engineering on erosion of river bottoms to provide insights into erosion under blowout conditions. Kamphuis and Hall (1983) investigated the erosion of cohesive materials by unidirectional currents. Rocha also describes similar work by Gaylord (1983) on erosional effects of fluid flow on clay-containing materials. Gaylord (1983) showed that erosion first increases slowly with increasing fluid velocity and then increases rapidly after some critical velocity is reached. Further work may be warranted to address the implications of these studies.

Intentionally Left Blank

4. CONCLUSIONS

Petroleum analogs of sufficient data quality for establishing limits on wellbore enlargement during blowout at the WIPP disposal system resulting from inadvertent human intrusion by exploratory drilling were not identified in this investigation. However, qualitative information was obtained that provides some basis for concluding that petroleum blowouts can bridge downhole, self-limiting the blowout duration. Further work would be needed, however, to investigate the conditions under which bridging might occur and the extent to which this phenomenon might be applicable to predicted conditions in the WIPP disposal system. In addition, data gathered during the course of this investigation support the use of a 12-1/4 inch borehole for WIPP performance assessment calculations for the 1996 compliance certification application (CCA). Note, however, that the results of this investigation cannot be used to directly corroborate the Cuttings results for the 1996 WIPP CCA since the CCA calculations used different mechanisms for blowout release than those investigated in this study.

Finally, based on a review of three blowouts that occurred in the Delaware Basin, particularly at the South Culebra Bluff Unit #1, significant wellbore enlargement was not found.

Intentionally Left Blank

5. REFERENCES

- Barker, J.M., and G.S. Austin. 1993. "Economic Geology of the Carlsbad Potash District, New Mexico," *Carlsbad Region, New Mexico and West Texas, New Mexico Geological Society, Forty-fourth Annual Field Conference, Carlsbad, NM, October 6-9, 1993*. Eds. D.W. Love, J.W. Hawley, B.S. Kues, J.W. Adams, G.S. Austin, and J.M. Barker. [Socorro, NM: New Mexico Geological Society]. 283-292.
- ERCB (Energy Resources Conservation Board). 1990. *Oil and Gas Well Blowout Report: Events of 1989*. ST-90-46. Calgary, Alberta, Canada: Energy Resources Conservation Board.
- ERCB (Energy Resources Conservation Board). 1991. *Oil and Gas Well Blowout Report: Events of 1990*. ST-91-46. Calgary, Alberta, Canada: Energy Resources Conservation Board.
- ERCB (Energy Resources Conservation Board). [1993]. *Energy Resources Conservation Board 1992 Annual Blow/Blowout Report*. [Calgary, Alberta, Canada: Energy Resources Conservation Board].
- ERCB (Energy Resources Conservation Board). 1994. *Oil and Gas Well Blowout Report: Events of 1993*. Calgary, Alberta, Canada: Energy Resources Conservation Board.
- Gatlin, C. 1960. *Petroleum Engineering: Drilling and Well Completions*. Englewood Cliffs, NJ: Prentice-Hall, Inc.
- Gaylord, E.W. 1983. "A Laboratory Study of the Effects of Hydraulics on Hole Erosion," *Society of Petroleum Engineers of AIME, 58th Annual Technical Conference and Exhibition, San Francisco, CA, October 5-8, 1983*. SPE 12118. Richardson, TX: Society of Petroleum Engineers.
- Golob, R.S., and D.W. McShea. 1981. "Implications of the Ixtoc I Blow-out and Oil Spill," *Petroleum and the Marine Environment, Petromar 80, Eurocean, Association Europeenne Oceanique, Monaco, 1980*. London: Graham and Trotman. 743-759.
- Hughes, V.M.P., A.L. Podio, and K. Sepehrnoori. 1990. "A Computer-Assisted Analysis of Trends Among Gulf Coast Blowouts," *In Situ*. Vol. 14, no. 2, 201-228.
- IADC (International Association of Drilling Contractors). 1992. *Drilling Manual*. 11th ed. Houston, TX: International Association of Drilling Contractors.
- Kamphuis, J.W., and K.R. Hall. 1983. "Cohesive Material Erosion by Unidirectional Current," *Journal of Hydraulic Engineering*. Vol. 109, no. 1, 49-61.

- Mavor, M.J. 1991a. *Western Cretaceous Coal Seam Project: Evaluation of Coalbed Natural Gas Openhole Cavity Completion Productivity. Topical Report, November 1990-December 1991.* Prepared by Resource Enterprises, Inc. for the Gas Research Institute. GRI-91/0374. Chicago, IL: Gas Research Institute. (Available from the National Technical Information Service, Springfield, VA as PB93-114361/XAB.)
- Mavor, M.J. 1991b. *Western Cretaceous Coal Seam Project: 1991 Annual Report.* Prepared by Resource Enterprises, Inc. for the Gas Research Institute. GRI-92/0129. Chicago, IL: Gas Research Institute. (Available from the National Technical Information Service, Springfield, VA as PB93-114445/XAB.)
- Mavor, M.J., and T.L. Logan. 1994. "Recent Advances in Coal Gas-Well Openhole Well Completion Technology," *JPT, Journal of Petroleum Technology*. Vol. 46, no. 7, 587-593.
- Mavor, M.J., J.C. Close, and T.J. Pratt. 1991. *Western Cretaceous Coal Seam Project: Summary of the Completion Optimization and Assessment Laboratory (COAL) Site. Topical Report, November 1990-December 1991.* Prepared by Resource Enterprises, Inc., for the Gas Research Institute. GRI-91/0377. Chicago, IL: Gas Research Institute. Vols. 1-2. (Available from the National Technical Information Service, Springfield, VA as PB94-159639/XAB and PB94-159647/XAB.)
- Mavor, M.J., J.R. Robinson, T.J. Pratt, and J.C. Close. 1992. *Western Cretaceous Coal Seam Project: Summary of the Vertical COAL Site, San Juan Basin. Topical Report, September 1991-December 1992.* Prepared by Resource Enterprises, Inc., for the Gas Research Institute. GRI-92/0504. Chicago, IL: Gas Research Institute. (Available from the National Technical Information Service, Springfield, VA as PB94-169422/XAB.)
- Mavor, M.J., T.L. Logan, J.C. Close, T.J. Pratt, and J.R. Robinson. 1993. *Western Cretaceous Coal Seam Project: 1992 Annual Report.* Submitted to Gas Research Institute by Resources Enterprises, Inc. GRI-93/0245. Chicago, IL: Gas Research Institute. (Available from the National Technical Information Service, Springfield, VA as PB94-103744/XAB.)
- Moore, P.L. 1975. "Why Wells Blow Out Through Drill String," *The Oil and Gas Journal*. Vol. 73, no. 5, 104-105.
- New Mexico Bureau of Mines and Mineral Resources (NMBMMR). 1993. *Atlas of Major Rocky Mountain Gas Reservoirs.* Ed. C.A. Hjellming. Socorro, NM: New Mexico Bureau of Mines and Mineral Resources, New Mexico Institute of Mining and Technology.
- Rocha, L.A.S. 1993. "Mechanisms of Crater Formation While Drilling a Well." PhD dissertation. Baton Rouge, LA: Department of Petroleum Engineering, Louisiana State University. (Available from University Microfilms International, 1-800-521-0600, Order Number: AAD94-19922.)
- Rocha, L.A., and A.T. Bourgoyne. 1993. "Identifying Crater Potential Improves Shallow Kick Control," *The Oil and Gas Journal*. Vol. 91, no. 52, 93-97.

Santos, O.L.A. 1989. "A Dynamic Model of Diverter Operations for Handling Shallow Gas Hazards in Oil and Gas Exploratory Drilling." PhD dissertation. Baton Rouge, LA: Louisiana State University. (Available from University Microfilms International, 1-800-521-0600, Order Number: AAD90-02169.)

Intentionally Left Blank

APPENDIX A

**D. W. POWERS, "BLOWOUTS DURING OIL AND GAS EXPLORATION IN
SOUTHEASTERN NEW MEXICO," LETTER REPORT TO L. R. HILL, JULY 24, 1995**

Intentionally Left Blank

Dennis W. Powers, Ph.D.

Consulting Geologist
HC 12 Box 87
Anthony, TX 79821

Business: (915) 877-3929
Home: (915) 877-2417
Fax: (915) 877-3929

Environmental Geology
Evaporite Geology
Frontier Sulfur

FAX: (505) 848-0881

17 pages total

07/24/95

L.R. Hill
Department 6747 M.S. 1341

Dear Les:

This is a letter report on my initial findings on the data available from some sources on blowouts during oil and gas exploration in southeastern New Mexico.

Blowouts During Oil and Gas Exploration in Southeastern New Mexico

Summary

Purpose

The general purpose of examining blowouts is to determine the likely events that should be considered for drilling scenarios, conditions that are conducive to blowouts, and drillhole enlargements from these releases.

Objectives

There were several objectives for this activity:

- ▶ summarize some data on WIPP drilling of pressurized brine and gas reservoirs in the Permian Castile Formation,
- ▶ summarize some data on blowouts from oil and gas exploration in the Delaware Basin, and
- ▶ determine sources of information such that other staff members might be able to more efficiently collect and collate information.

Sources of Information

Waste Isolation Pilot Plant (WIPP) reports in the Sandia WIPP Central File (SWCF) provide most details about the drilling and testing of brine reservoirs in the Permian Castile Formation in the area of the WIPP. Alternative sources not yet checked include the Project Records System (PRS) of the WIPP located in Carlsbad and the WIPP library on site. My personal files include some of the same reports but do not contain additional information that I believe is relevant to this issue.

For oil and gas exploration, I examined maps from the Midland Map Company, log listings by Riley Electric Logs, and files for Eddy County drilling in the Artesia offices of the Oil Conservation Commission of New Mexico.

I also spoke to residents near Loving, NM, to obtain initial information and location of the South Culebra Bluff #1 blowout in 1978.

There are other sources not yet checked, pending a decision about who (e.g., Rich Aguilar, John Keesey, or I) should check further and obtain more information. The OCC office in Hobbs, NM, covers the Lea County area. The Texas Railroad Commission, Oil and Gas Division, has a field office at 2509 N. Big Spring in Midland (tel: 915/684-5581). It is responsible for 36 counties in west Texas adjacent to New Mexico or nearby. The Midland field office maintains files of Form D6, on which blowouts and other incidents are reported; the form gives basic information that is normally further reported in individual operator/well files. I spoke to Michael Pearson; the other knowledgeable person is Bill Hartsell. Norbert Rempe (Westinghouse) and Keith McKamey (NMED) were asked about their personal knowledge of blowouts in southeastern New Mexico. They had some general information; further discussion might yield additional details or specific events.

Summary of WIPP Brine Reservoir Information

Two drillholes, ERDA 6 and WIPP 12, encountered brine and gas in the upper Castile Formation during site exploration and characterization. Each had sufficient pressure to flow at the surface over extended testing periods. The Castile is not a hydrocarbon exploration target, and these occurrences are not taken as equivalent to a blowout from a high-pressure gas reservoir.

The principal sources of information on these events are data and analysis reports from project participants. Basic data and hole histories are included in Sandia National Laboratories and US Geological Survey (1983), Sandia National Laboratories and D'Appolonia Consulting Engineers (1982), Black (1982), and D'Appolonia Consulting Engineers, Inc. (1982). Further analyses of brine reservoirs are reported in Popielak and others (1983), Rose (1977), Register (1981), Powers and others (1978), Barr and others (1979), and Lambert and Harvey (1987), though this is not a complete list of references.

Pressurized brine and gas (including H_2S) were encountered at a depth of 2711 ft (in anhydrite from the Castile Formation) in ERDA 6 while drilling in 1975. Because the drillhole was not intended for exploration of hydrocarbon-bearing zones, it was not equipped for containing high-pressure brine and gas. The flow was eventually controlled with mud that at some times was increased to 13.8#. The hole history shows a variety of work and testing over a period of about a month in 1975 before a cement plug was placed. The hole was re-entered when WIPP 12 was being tested so that the ERDA 6 reservoir could be monitored and further tested.

Pressurized brine and gas in WIPP 12 were encountered in the Castile Formation during a second drilling phase to deepen the drillhole. The drilling was to examine evaporite deformation, and it was anticipated there would not be any pressurized brine because the evaporites were less deformed at WIPP 12. The basic data report on the testing of WIPP 12 and ERDA 6 shows the extensive activities, including episodes of geophysical logging.

The principal point I checked was whether there were sources of information that could indicate if borehole diameters were affected by flow episodes during testing of the brine reservoirs in ERDA 6 and WIPP 12. Caliper logs are available for checking. For ERDA 6, I found comparable caliper logs before and after flow (D'Appolonia Consulting Engineers, Inc., 1982; Activities 6.2 and 6.5). The problem is that there was also drilling between the caliper logs, and we cannot determine how much the drill string may have affected the borehole diameter. Large-format copies of these logs are

available from SWCF as WP03841 and 03842. WIPP 12 caliper logs (Activities 12.5 and 12.16) bracket about 30,000 bbls of flow during testing, with no drilling during this time. The earlier log was taken 11/27/81 and the later log was taken 1/1/82. It appears from the caliper logs that the drillhole diameter increased through the lower Salado (e.g., the vicinity of 2500 to 2700 ft depth) while borehole in the upper Salado (e.g., about 1000 ft) does not appear to have changed. The log scale differs, and we do not know the details of the caliper tool (3-arm, 4-arm, etc.). Nonetheless, these borehole character changes do appear to be significant in this instance.

Summary of Blowout at South Culebra Bluff Unit #1 (sec 23, T23S, R28E, 1980' fnl, 1650' fel)

At 10:30 am on January 3, 1978, Delta Drilling Company intercepted a high-pressure zone in the "Atoka" at a depth of 11, 769 ft in South Culebra Bluff Unit #1. The automatic choke failed, pressurizing the separator until it failed, disabling the choke and kill manifold. The crew was unable to get to the manifold valves to shut the well in. It ignited about 5:10 am on January 4, 1978, and the derrick fell 8:12 am on January 5, 1978. On January 11, a crew from Red Adair's company used 400# of nitroglycerine to blow off the damaged BOP and also blew out the fire. By January 14, the crew had regained control of the well and it was tested on the 18th. Gas was piped to an El Paso Natural Gas Company pipeline. Initial production estimates were 50 MMCFD. The well produced more than 4 billion cubic ft of gas from January 27 through June 7. The well was allowed to flow for several months because initial data indicated mud weights sufficient to control the gas flow would exceed the fracture gradient for the Bone Spring Limestone. In September, 1978, Delta plugged the hole to 11, 670 feet, installed additional casing, and drilled around the plug and drillpipe that had been left in the hole. The re-completed well tested 14.6 MMCFD.

Extensive records were available at the OCD office in Artesia relative to this blowout. I took additional notes, but they largely concern more details of actions and some of the institutional response. A form called "Notification of Fire, Breaks, Spills, Leaks, and Blowouts" was filed within a few hours of the occurrence. OCD keeps records by year of these forms. The drillhole file includes extensive correspondence and notification of the activities before and after the blowout occurred, and there are many details that can be added to my summary. There are several pages of test data, but I did not find any direct reference to the reservoir characteristics. OCD also maintains files of geophysical logs, and I am faxing a few pages from the relevant depths. The gamma and density logs show the shale zone over the producing horizon that likely cause over-pressuring, as commented on by both McKamey and Rempe.

The caliper logs for the South Culebra Bluff #1 appear to be composite logs from different episodes at different depths. There is limited information, probably of no value, about possible borehole enlargement during nearly uncontrolled high-pressure gas flow over a period of about 8 months. Any overlapping information is also likely to be suspect because of the workover required before it was possible to re-drill and log the lower part of the borehole.

Other Blowouts or Incidents

I inspected the annual records of "Notification of Fire, Breaks, Spills, Leaks, and Blowouts" for the years 1991 through 1995 and found no record of any blowouts

during that period. The records mainly include fires and spills when tank batteries are struck by lightning, pipeline breaks during construction, equipment failures at tank batteries, and human error incidents (valves left open, minor spills). With additional time, these records can be searched further. All of the equivalent files at the Hobbs office of the OCD remain to be checked for Lea County and the extreme eastern side of New Mexico. As a side note, the Artesia office of OCD charges \$0.25/page for copying.

I haven't inspected records at the Texas Railroad Commission Midland office, but they should be about the same as the NM OCD.

South Culebra Bluff #1 as an Analog for WIPP

Eight criteria were listed for analogs to WIPP. South Culebra Bluff #1 meets certain of these.

1. This was an unexpected encounter. The initial target was the Morrow, below the Atoka. Though the Atoka was known from other areas, this was not designated as a field or reservoir for the area. I haven't checked whether Delta was a new driller to the area, but I doubt it. Amoco was not a novice.

2. I don't know what the specific criteria are for a US independent. It's probably not relevant here.

3. The Atoka was principally a gas-producer, though there was apparently condensate as well. I don't have the data on proportions. I think the condensate must have been small to pipe the flow directly to EPNG's pipeline. Later tests undoubtedly determined the condensate.

4. Some of the data on the formation are available, and there is enough file data and geophysical log information that much of the required characteristics should be determinable within reason.

5. There is considerable information on mud programs and casing.

6. The South Culebra Bluff #1 well is about 16 miles from WIPP and is likely to be the nearest and best documented blowout in geology similar to that at the WIPP.

7. The geology is very similar to the WIPP, although the near-surface units have been more affected by dissolution.

8. The response at OCD was very good, and I don't think any of the information in the files I saw is confidential.

In summary, the South Culebra Bluff #1 well may be the best single analog available to WIPP. Additional information might be obtained, with permission, from Delta Drilling Company, Box 866, Odessa, TX 79760. The current operator of the well is RB Operating Company (Reading and Bates Petroleum Company), 2412 N. Grandview, Suite 201, Odessa TX 79761.

Meeting Objectives

I have summarized some data on WIPP drilling of pressurized brine and gas reservoirs in the Permian Castile Formation. There are additional data that may be useful for specific purposes in performance assessment, and some have been included in PA. Some information on borehole size changes were reviewed, and WIPP 12 may indicate changes in diameter with brine production.

With limited research, I was able to summarize data and events on a blowout from oil and gas exploration in the Delaware Basin near Loving, NM. I think there is little likelihood of getting borehole enlargement data, though a careful reconstruction of logging events might yield further possibilities. There is other information to be obtained about the geology, the specific events of this blowout, and both industry and institutional responses to the blowout.

From this brief foray, it is clear that sources of information exist in Artesia and Hobbs on New Mexico occurrences. In addition, the Midland office of the Oil and Gas Division of the Texas Railroad Commission has generally equivalent information. Sandia staff members could collect and collate this information, but there may need to be some training before someone without background in these areas attempts it.

My efforts are well within the estimates of time I gave for this task; there are some minimal expenses as well because I had to stay over an extra night in Carlsbad. I consider my efforts to end with this letter report unless you specifically direct that I should follow up on the information available in Artesia, Roswell, and Midland. I can do this if priorities under my existing contract change.

Attachments

I am attaching:

- a copy of part of the map from Midland Map Company so you can easily identify the South Culebra Bluff #1 location on your own MMC maps.
- 3 pages of information from the OCD files on South Culebra Bluff #1
- 4 legal size pages of part of the compensated neutron-formation density log from South Culebra Bluff #1.
- 3 legal size pages of part of the dual laterolog micro-sfl log from South Culebra Bluff #1.

References Cited

- Barr, G.E., Lambert, S.J., and Carter, J.A., 1979, Uranium isotope disequilibrium in groundwaters of southeastern New Mexico and implications regarding age-dating of waters: Isotope Hydrology 1978, proceedings of an International Symposium of Isotope Hydrology, Neuherberg, June 19-23, 1978, International Atomic Energy Agency, vol. 2, p. 645-660.
- Black, S.R., 1982, Basic data report borehole WIPP-12 deepening Waste Isolation Pilot Plant (WIPP) project southeastern New Mexico: TME 3148, US Department of Energy, Albuquerque, NM.
- D'Appolonia Consulting Engineers, Inc., 1982, Data file report, ERDA-6 & WIPP-12 testing: Westinghouse Electric Corporation, Albuquerque, NM, v. I-IVB.
- Lambert, S.J., and Harvey, D.M., 1987, Stable-isotope geochemistry of groundwaters in the Delaware Basin of southeastern New Mexico: SAND87-0138, Sandia National Laboratories, Albuquerque, NM.
- Popielak, R.S., Beauheim, R.L., Black, S.R., Coons, W.E., Ellingson, C.T., and Olsen, R.L., 1983, Brine reservoirs in the Castile Formation Waste Isolation Pilot Plant (WIPP) project, southeastern New Mexico: WTSD-TME-3153, US Department of Energy, Albuquerque, NM.

Powers, D.W., Lambert, S.J., Shaffer, S-E., Hill, L.R., and Weart, W.D., eds, 1978, Geological characterization report, Waste Isolation Pilot Plant (WIPP) site, southeastern New Mexico: SAND78-1596, Sandia National Laboratories, Albuquerque, NM, 2 vols.

Register, J.K., 1981, Brine pocket occurrences in the Castile Formation, southeastern New Mexico: TME 3080, US Department of Energy, Albuquerque, NM.

Rose, W., 1977, Development of a conceptual model to explain brine flowage into wells drilled through the Salado-Castile Formation contact in locations such as the ERDA6 site near Carlsbad in southeastern New Mexico: New Mexico Tech, Socorro, NM.

Sandia National Laboratories and D'Appolonia Consulting Engineers, 1982, Basic data report for drillhole WIPP 12 (Waste Isolation Pilot Plant - WIPP): SAND82-2336, Sandia National Laboratories, Albuquerque, NM.

Sandia National Laboratories and US Geological Survey, 1983, Basic data report for drillhole ERDA 6 (Waste Isolation Pilot Plant - WIPP): SAND79-0267, Sandia National Laboratories, Albuquerque, NM.

If there are clarifying data or points that you need, please don't hesitate to let me know. As I noted elsewhere, if priorities for my consulting for Sandia change and you want me to pursue some of these data and sources further, I will be glad to work out a program.

Sincerely,

Dennis W. Powers

please make copy for D. Boak

NEW MEXICO OIL CONSERVATION COMMISSION

NOTIFICATION OF FIRE, BREAKS, SPILLS, LEAKS, AND BLOWOUTS

Copy to DT
Dennis

NAME OF OPERATOR <u>Delta Drilling Company</u>					ADDRESS <u>Box 866 Odessa, TX 79760</u>		
REPORT OF	FIRE ☒	BREAK	SPILL	LEAK	BLOWOUT ☒	OTHER*	
TYPE OF FACILITY	DRLG WELL ☒	PROD WELL	TANK BTY	PIPE LINE	GASO PLNT	OIL RFY	OTHER*
NAME OF FACILITY <u>South Oulebra Bluff Unit #1</u>							
LOCATION OF FACILITY (QUARTER/QUARTER SECTION OR FOOTAGE DESCRIPTION)					SEC. 23	TWP. 23S	RGE. 28E
DISTANCE AND DIRECTION FROM NEAREST TOWN OR PROMINENT LANDMARK <u>2 miles East of Loving, N. M.</u>							
DATE AND HOUR OF OCCURENCE <u>10:30 A.M. January 3, 1978</u>					DATE AND HOUR OF DISCOVERY <u>Same</u>		
WAS IMMEDIATE NOTICE GIVEN?	YES ☒	NO	NOT RE-REQUIRED		IF YES, TO WHOM <u>Local Conservation Office</u>		
BY WHOM <u>Elmer Pope, Consultant</u>					DATE AND HOUR <u>3/78</u> <u>Approx. 1 P.M.</u>		
TYPE OF FLUID LOST <u>Gas</u>					QUANTITY OF LOSS <u>unknown</u>		VOLUME RECOVERED
DID ANY FLUIDS REACH A WATERCOURSE?	YES	NO ☒	QUANTITY				
IF YES, DESCRIBE FULLY**							
DESCRIBE CAUSE OF PROBLEM AND REMEDIAL ACTION TAKEN**							
See Attachment							
DESCRIBE AREA AFFECTED AND CLEANUP ACTION TAKEN**							
The burning gas posed no immediate danger to the surrounding area. Red Adair was called in to contain and control the well.							
DESCRIPTION OF AREA	FARMING ☒	GRAZING	URBAN		OTHER*		
SURFACE CONDITIONS	SANDY ☒	SANDY LOAM	CLAY	ROCKY	WET	DRY ☒	SNOW
DESCRIBE GENERAL CONDITIONS PREVAILING (TEMPERATURE, PRECIPITATION, ETC.)**							
Temperature approx. 45° and no precipitation.							
I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF							
SIGNED <u>Ron Lechwar</u> Ron Lechwar					TITLE <u>Projects Manager</u>		DATE <u>1-23-78</u>

*SPECIFY

**ATTACH ADDITIONAL SHEETS IF NECESSARY

ATTACHMENT

DRILLING AT 11,769 FEET, A HIGH PRESSURE GAS ZONE WAS ENCOUNTERED. BOP AND HYDRIL WERE CLOSED AND KICK WAS BEING CIRCULATED OUT WHEN THE AUTOMATIC CHOKE FAILED FOR REASONS UNKNOWN AT THIS TIME, ALLOWING THE FULL PRESSURE TO ENTER SEPARATOR.

THE SEPARATOR WAS UNABLE TO HANDLE THE FULL PRESSURE AND SUBSEQUENTLY FAILED, WHICH IN TURN DISABLED THE CHOKE AND KILL MANIFOLD. AT THIS TIME THE WELL WAS STILL UNLOADING WATER AND GAS. THE RIG CREW STATED THAT THEY WERE UNABLE TO REACH ANY OF THE FOUR VALVES GOING TO THE MANIFOLD FROM THE BOP TO SHUT THE WELL IN. THE CREW THEN LEFT THE LOCATION FOR A PLACE OF SAFETY. THE WELL CONTINUED TO BLOW GAS AND CONDENSATE UNTIL APPROXIMATELY 5:10 A.M. THE FOLLOWING MORNING, AT WHICH TIME IT IGNITED ITSELF.

RECEIVED DELTA DRILLING COMPANY

Box 2012 TELEPHONE 214 595-1911

JAN 26 1978

TYLER, TEXAS 75710

O. C. C.
ARTESIA, OFFICE

January 24, 1978

New Mexico Oil Conservation Commission
Drawer DD
Artesia, New Mexico 88210

RE: Report of Blowout
South Culebra Bluff No. 1 Well
Eddy County, New Mexico

Gentlemen:

This letter will confirm the prior notification given to Mr. Bill Gressett (Artesia office) and Mr. Dan Nutter (Santa Fe office) on January 4, 1978, concerning the blowout and subsequent fire at the Delta Drilling Company South Culebra Bluff No. 1 Well located 1980' FNL and 1650' FEL of Section 23, T23S, R28E, NMPM, Eddy County, New Mexico.

The South Culebra Bluff No. 1 Well was spudded by Amoco Production Company on November 6, 1977, pursuant to a Drilling Contract between Amoco Production Company, as Operator, and Brahaney Drilling Company, Inc., whose address is P. O. Box 1694, Midland, Texas, 79701, as Drilling Contractor.

On November 17, 1977, at 12:00 noon, Delta Drilling Company assumed operation of the well at a depth of approximately 4400' below the surface. Rig No. 7 of Brahaney Drilling Company, Inc. continued the drilling of such well until January 3, 1978, on which date such well, at a depth of 11,769' below the surface, encountered a gas kick, blew out and subsequently caught fire.

Operations for the drilling of a relief well and efforts to gain control of the well at the surface were commenced immediately. Control equipment has been installed on the wellhead and at present gas is being flared through two lines. Arrangements have been made to sell such gas to El Paso Natural Gas Company pursuant to an emergency gas sales contract, and it is anticipated that deliveries of such gas will be commenced on or about January 25, 1978.

Additional information concerning such well is being furnished to the New Mexico Conservation Commission pursuant to your forms C-103 and C-104.

Very truly yours,

Carl E. Haskett
Mgr. Corporate Engineering
and Research

cc: New Mexico Oil Conservation
Commission
P. O. Box 2088
Land Office Building
Santa Fe, New Mexico 87501

COUNTY		EDDY	
FIELD		WILDCAT	
LOCATION		SOUTH CULEBRA BLUFF	
WELL		UNIT #1	
COMPANY		DELTA DRILLING CO.	

LOCATION		COUNTY		WELL		FIELD	
1980° FNL & 1650° FEL		EDDY		STATE		NEW MEXICO	
API SERIAL NO.		SEC.		TWP.		RANGE	
23		23-S		28-E			

Other Services:	
BHC	
DLL-MSFL	
CYBERLOOK	

Permanent Datum:						G.L.	Elev.:			
Log Measured From						K.B.	K.B. 2017			
Drilling Measured from						K.B.	D.F. 2996			
						21	Ft. Above Perm. Datum			
Date	Run No.					ONE	9-14-78	9-30-78	10-12-78	R E C E I V E D
Depth- Driller						11677	11750	11873	11873	OCT 1 - 1978
Depth- Logger						11670	11754	11879	11879	
Btm- Log Interval						11658	11743	11877	11877	O.C.C.
Top Log Interval						6125	9743	9743	11746	O.C.C.
Coring- Driller						9 5/8 @ 358	9 5/8 @ 6350	7"	@ 11745	(FLOOR) OFFICE
Coring- Logger						6354		11746		
Bt Size						8 3/4	*	SALT GEL, STARCH	5.1/8	
Type Fluid in Hole						BRINE				
Dens. Visc.						10.2	28	10.4	38	11.6 48
pH Fluid loss						11	ml	12	10 ml	10.5 17.4ml
Source of Sample						PIT	PIT	PIT	PIT	
Rm @ Meets. Temp.						.041 @ 93 °F	.088 @ 73 °F	.059 @ 85 °F	.059 @ 85 °F	@ @
Rmf @ Meets. Temp.						.031 @ 93 °F	.078 @ 73 °F	.046 @ 85 °F	.046 @ 85 °F	@ @
Rmc @ Meets. Temp.						.062 @ 93 °F	.132 @ 73 °F	.089 @ 85 °F	.089 @ 85 °F	@ @
Source Rmf / Rmc						M	C	M	C	M
Rm @ BHT						.026 @ 145°F	.041 @ 154°F	.030 @ 167°F	.030 @ 167°F	@
Circulation Stopped								1200 9-30	1500 10-12	
Logger on Bottom						1930	0745	10-1	0600 10-13	
Max. Kc. Temp.						145 °F	154 °F	162 °F	162 °F	
Equip. Location						7721 HOBBS	8067 HOBBS	8042 HOBBS	8042 HOBBS	
Recorded by						DANIEL	THURSTON	MOBARAK	MOBARAK	
Witnessed by Mr.						OLSON	SMET	GALLICK	GALLICK	

FOLD HERE The well name, location and borehole reference data were furnished by the customer.

RUN NO.		ONE	TWO	THREE		Type Log	Depth		
Service Order No.		22229							
Fluid Level				FULL					
Salinity, PPM CL.		167000	147000	145000					
Speed - F.P.M.		30	30	30/60					
EQUIPMENT DATA									
Dens. Panel		1141	8067						
Dens. Cart.			"						
Dens. Skid.		1077	"	125					
Dens. Sonde		305	"						
Dens. Source		3334	"	3351					
Dens. Calibrator		696	"	1083					
Neut. Panel		652	"						
Neut. Cart.		485	"	1278					
Neut. Source		1441	"	2333					
Neut. Calibrator		549	"	1390					
GR Cart.			"						
Memorizer Panel		792							
Tape Recorder (TTR)		853							
Depth Encoder (DRE)		953							
Pressure Wheel (CPW)		1938							
Centralizers:		Type	★★						
Enter Spring,		No.	1 EACH						
Standoffs,		S. O. — Inches	ECCEN.						
In-line, or None									
CALIBRATION DATA									
GR		BKG. CPS	70	22	SEE CAL				
		Source CPS	530	186					
		Sens. - Cal	165	165	165				
		T. C. - Cal	6						
N.C.	Short Spacing - Before Log	RATIO	RATIO	SEE CAL					
	Long Spacing - Before Log	2.34	2.07						
	Short Spacing - After Log	RATIO	RATIO						
	Long Spacing - After Log	2.34	2.05						
R.C.	P ¹ — Before Log	126.1	335						
	P ² — Before Log	198.7	533						
	P ¹ — After Log	126	337						
	P ² — After Log	199	528						

REMARKS:	
RUN 1- RIG #2: K.B. = 3009	
CSG. = 6350	
TD = 11669	
** TYPE OF CENTRALIZERS	
USED: BOWSPRING AND CALIPER	
RUN 2- * TYPE FLUID IN HOLE	
SALT GEL. MYO GEL	
RUN 3- NO CENTRALIZERS USED	
DUE TO BOREHOLE SIZE	

LOGGING DATA

DEPTH		CNP			FDC				GR		
Top	Bottom	Porosity Scale	Matrix	Auto Corr. or Hole Size Setting	Porosity Scale	Grain Density	Liquid Density	Hole Fluid	Sens. Logged	T. C.	Zero. Div. Left
6354	11658	30 -10	LS-OH	AUTO	30 -10	2.71 -	1 -10	L10 -	100	2	n

FDC	P ₂ - Before Log	198.7	533		
	P ₁ - After Log	126	337		
	P ₂ - After Log	199	528		

LOGGING DATA											
DEPTH		CNP			FDC				GR		
Top	Bottom	Porosity Scale	Matrix	Auto Corr. or Hole Size Setting	Porosity Scale	Grain Density	Liquid Density	Hole Fluid	Sens. Logged	T. C.	Zero Div. Left
6354	11658	30 -10	LS-OH	AUTO	30 -10	2.71	1.10	L10.	100	2	0
6125	6354	30 -10	LS-CH						100	2	0
9743	11743	30 -10	LS-OH	AUTO	30 -10	2.71	1.10	L10.	165		0
11600	11746	30 -10	LS-CH	CH					100		0
11746	11877	30 -10	LS-OH	AUTO	30 -10	2.71	1.10	L10.	100		0

All interpretations are opinions based on inferences from electrical or other measurements and we cannot, and do not guarantee the accuracy or correctness of any in-
 pretations, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages or expenses incurred
 sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to Clause 4 of our Gen-
 eral Terms and Conditions as set out in our current Price Schedule.

RUN 1

CORRECTION GRAMS/CC

Use this scale when correction
 curve is presented in Track 2

BULK DENSITY GRAMS/CC

CNL POROSITY

6200

6300

Casing

6400

65

φ_{OH} Cased Hole

φ_{OH} Open Hole

φ_{CNL}

DETAIL LOG

Schlumberger

DUAL LATEROLOG
MICRO-SFL

COUNTY EDDY		WILDCAT	
FIELD SOUTH CULBERRA		BLUFF #1	
COMPANY DELTA DRILLING CO.			
LOCATION		1980' FNL & 1650' FEL	
WELL SOUTH CULBERRA BLUFF UNIT #1		FIELD WILDCAT	
COUNTY EDDY		STATE NEW MEXICO	
COMPANY DELTA DRILLING COMPANY		Other Services: CNL-FDC BHC CYBERLOOK	
Permanent Depth: G.L. Log Measured From: K.B. Drilling Measured From: K.B.		Elev.: 2996 K.B. 3017 D.F. 2996	
Run No. ONE		TWO	
Depth-Driller 6355		11669	
Depth-Logger (Schl) 6288		11657	
Btm. Log Interval 6286		11655	
Top Log Interval 415		6354	
Casing-Driller 133/8 @ 418		5358 @ 95/8	
Casing-Logger 415		6354	
Bit Size 121/4		8 3/4	
Type Fluid in Hole BRINE		* 8 3/4	
Dens. 10.1		10.2	
Visc. 27		28	
pH 8.5		11	
Source of Sample PIT		PIT	
Km @ Meas. Temp. .052 @ 60 °F		.088 @ 73 °F	
Km @ Meas. Temp. .031 @ 93 °F		.078 @ 73 °F	
Rmt @ Meas. Temp. .0615 @ 93 °F		.132 @ 73 °F	
Source: Km @ Time		.089 @ 85 °F	
Km @ BHT .03 @ 105 °F		.026 @ 145 °F	
Circulation Stopped 2100		1200	
Logger on Bottom 0115		1230	
Max. Rec. Temp. 105		154	
Equip. Location 7732		HOBBS 2721 HOBBS	
Recorded by SANCHEZ		DANIEL	
Witnessed by LECHMAN		OLSON	
		SWIFT	
		GALLICK	

FOLD HERE

The well name, location and borehole reference data were furnished by the customer.

Run No.	ONE	TWO	THREE	FOUR	SCALE CHANGES
Service Order No.	22229				Type Log Depth Scale Up Hole Scale D
Fluid Level				FULL	
Salinity, PPM CL	189000	167000	147000	145000	
EQUIPMENT DATA					
Panel (DLP)	808	965			
Panel (SRP)	970	945			
Cartridge (DLC)					
Cartridge (SRE)					
Sonde (DLS)			853	831	
Sonde (SRS)					
Lower Electrode (DLE)					REMARKS:
Memorizer Panel	792	792			RUN 1- ***- TYPE OF CENTRAL
Tape Recorder (TTR)	809	853			USED CME-H & CALIPER.
Depth Encoder (DRE)		953			
Pressure Wheel (CPW)	1473	1938			RUN 2- RIG # 2 K.B. 3029
Centralizers:	Type ***	CME-H	CME-H		CSG. 6359
Enter Spring,	No. 1	ONE	ONE		TD-11669
Standoffs,					RUN 3- * TYPE FLUID IN HOLE
In-line, or None	S.O. Inches	CENTERED	CENTERED		SALT GEL-MYLOGEL, NO MSFL DI
CALIBRATION DATA					
GR	BKG. CPS		54	SEE CAL	TO CSU PROBLEM, NO CALIPER I
	Source CPS		187		TO TOOL FAILURE.
LOGGING DATA					
GR	Sensitivity	165	165	165	RUN 4- NO CENTRALIZERS USED
	Scale -100 Div.	100	100	100	DUE TO BOREHOLE SIZE.
	T.C. - sec	1			** TYPE FLUID IN HOLE:
Speed FPM		40	50	40	SALT GEL STARCH.
BOTTOM HOLE TEMPERATURE					
Time Entering Hole	0100	1330		0030	
Time Bottom Reached	0130	1430		0230	
Time Last Off Bottom	0145	1500		0300	
Time Out of Hole	0445	1300		0530	
Distance TD to Therm.	32	37		37	
Thermometer #1	105 °F	145 °F		167 °F	
Thermometer #2					
Thermometer #3					
Rw FROM DRILL STEM TEST					
DST #1 - Rw @ 100 °F		ΩM	ΩM	ΩM	ΩM
DST #2 - Rw @ 100 °F		ΩM	ΩM	ΩM	ΩM

All interpretations are opinions based on inferences from electrical or other measurements and we cannot, and do not guarantee the accuracy or correctness of any interpretations, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to Clause 4 of our General Terms and Conditions as set out in our current Price Schedule.

GAMMA RAY

AD-18MTC

DE

DECIIVITY

Intentionally Left Blank

APPENDIX B

TELEPHONE CONTACTS FOR WELLBORE ENLARGEMENT INVESTIGATION^{1, 2}

1. Steve Melzer, University of Texas, Midland, TX, (915) 552-2477.
2. Dennis Beckman, Amoco Corporation, Tulsa, OK, (918) 660-4177.
3. Dr. Bill Mitchell,* Colorado School of Mines, Golden, CO, Department of Petroleum Engineering, (303) 273-3740.
4. Darien O'Brien, Solutions Engineering, Lakewood, CO, (303) 233-9185.
5. Dr. Adam T. Bourgoyne,* Louisiana State University, Baton Rouge, LA, (504) 388-3202.
6. Richard McBane, Gas Research Institute, Chicago, IL, (312) 399-8284.
7. Gene Schmidt, Amoco Research Center, Tulsa, OK, (918) 660-3424.
8. Brian Tarr, Mobil Exploration, Dallas, TX, (214) 951-2945.
9. Dr. Dave Powley (Retired),* Amoco Production Company, Tulsa, OK, (918) 494-4821.
10. Dr. John S. Bradley (Retired),* Amoco Production Company, Tulsa, OK, (918) 743-5283.
11. Dr. Tony Podio, University of Texas, Austin, Department of Petroleum Engineering, (512) 471-3260.
12. Dr. Martin Chenevert, University of Texas, Austin, Department of Petroleum Engineering, (512) 471-7270.
13. Dr. Jean-Claude Roegiers,* University of Oklahoma, Norman Department of Petroleum Engineering, (405) 325-2921.
14. Wolfgang Wawersik, Sandia National Laboratories, Albuquerque, NM, (505) 844-4342.
15. Lawrence Romero, Oil Conservation Division, Santa Fe, NM, (505) 827-7131.
16. Roger Anderson, Oil Conservation Division, Santa Fe, NM, (505) 827-7152.
17. Dr. Dennis W. Powers, Consulting Geologist, Anthony, TX, (915) 877-3929.

¹ An asterisk denotes an individual considered an expert in the area of petroleum blowouts.

² For a record of the telephone conversations, see Dotson, Lori J., "Draft Report on Borehole Enlargement Information Search," Sandia National Laboratories memorandum to Barry M. Butcher. (Copy on file in the Sandia WIPP Central Files, Sandia National Laboratories, Albuquerque, NM, as WPO#27412.)

18. John J. Keesey, Williamson Petroleum Consultants, Houston, TX, (713) 750-7215.
19. Dan Stoelzel, Sandia National Laboratories, Albuquerque, NM, (505) 848-0153.

APPENDIX C

DEVELOPMENT OF GIS DATABASE AND ANALYSIS OF DATA ON PETROLEUM WELLS IN THE WIPP VICINITY

Intentionally Left Blank

APPENDIX C

DEVELOPMENT OF GIS DATABASE AND ANALYSIS OF DATA ON PETROLEUM WELLS IN THE WIPP VICINITY

Introduction

An integrated graphic personal computer (PC) database platform using Environmental Systems Research Institute's products, Arc/Info and Arcview, and the Microsoft products Access, Excel, Powerpoint, and Word, was used to compile and manipulate data associated with Waste Isolation Pilot Plant (WIPP) Project surface characterization boreholes and petroleum industry wells within a 10-mile radius of WIPP. The petroleum well data was compiled and summarized to assist with the identification of analogs to potential wellbore enlargement at WIPP during inadvertent human intrusion. Arc/Info is a software tool used in geographic information system (GIS) applications that allows a user to design and automate spatial databases, link datasets, and create maps using line, point, and polygon topology. Arcview is a software tool that creates a computerized environment to display and query the contents of a spatial database created in Arc/Info.

The WIPP surface borehole drilling program, sponsored by the U.S. Department of Energy (DOE) and conducted between 1974 and 1995 primarily by Sandia National Laboratories (SNL), included exploratory drilling, hydrologic testing, and the use of geophysical techniques to determine the site's suitability for a nuclear waste repository. The information compiled from this program for the GIS database included hydrologic, geologic, geochemical, and environmental data, and well completion and status information. The data on petroleum wells within a 10-mile radius of WIPP were obtained from the commercially available Dwights/Petroleum Information Discover Scout database.

A user-interface communication screen was developed by Sandia for the Access database to allow the user to interactively query data (in both text and numerical form) for a particular surface borehole or petroleum well. Access data and spatial map display information created by Arc/Info were then linked to Arcview for visual inspection of their relationship to other boreholes, wells, or geographic features within the WIPP site. Additionally, spatial relationships among the various boreholes and surficial features in the vicinity of the WIPP site can be displayed and manipulated using Arcview. Using the commercial Microsoft PC software products in combination with the more complex ESRI Arc/Info and Arcview programs allows scientific data about any particular borehole or petroleum well in the database to be effectively and interactively communicated to interested users in varying degrees of detail and complexity.

Coverages

Arc/Info was used to generate information on petroleum wells within the Salado formation in the vicinity of the WIPP, including well category, depth, and casing size. Arc/Info generates points, lines, and polygons to represent various geographic features on a map. The information is arranged in "coverages," digital analogs of single map sheets that form the basic units of data storage in Arc/Info.

Township Range and Section Locations

Township, range, and section point locations for the WIPP characterization boreholes and the petroleum wells were generated in Arc/Info using information obtained from the U.S. Geologic Survey (USGS) digital file "Main.Rep." Main.Rep contains the state-plane coordinates for New Mexico's east zone for sections within the area consisting of Townships 20 through 26 south and Ranges 28 through 33 east. Figure C-1 is a section of the Main.Rep file and shows the data's format.

USGS SURVEY Water Resources Division				
Albuquerque, New Mexico				
NE Section coordinates in the Vicinity of WIPP 8/20/87				
Township Range Section (tt.rr.ss)	UTM X (meters)	UTM Y (meters)	State Plane X (feet)	State Plane Y (feet)
20.28.01	582,435	3,608,204	565,250	585,696
20.28.02	580,826	3,608,189	559,970	585,681
20.28.03	579,209	3,608,165	554,664	585,633
20.28.04	577,590	3,608,151	549,350	585,622
...to.....26.33.36	640,065	351,976	753,005	367,199

Figure C-1. USGS Main.Rep file format.

The WIPP borehole location data also appears in Gonzales (1989). New Mexico state-plane coordinates (in feet) for the northeast corners of each section were used as X and Y location points and were generated in Arc/Info to produce the point coverage "TRSpnts." The state-plane coordinates were used rather than the Universal Transverse Mercator (UTM) coordinates to make it easier to convert the borehole and well locations that were initially given in feet from the nearest quarter section lines.

Township/Range/Section Lines

Township, range, and section lines were generated in Arc/Info as a line coverage to accurately define the location of the WIPP characterization boreholes and the petroleum wells within a 10-mile radius of WIPP. The coverage name is "TRSlines."

WIPP Characterization Borehole Location Points

WIPP characterization borehole locations were initially compiled in spreadsheet format using Microsoft Excel. The spreadsheet digital information was obtained from numerous sources including the basic data reports for the characterization boreholes, hydrologic/hydraulic testing reports, potash resource test drilling reports, and other DOE, USGS, Sandia, and private industry reports (see Hill et al. (1997) for a comprehensive list of these sources). The Excel file was slightly modified to include a unique identification number for each borehole location point (consisting of an X and a Y value). The spreadsheet was then saved as a comma-delimited file and imported into Arc/Info to generate the point coverage "Borehole" (titled "SNL Boreholes" using Arcview software).

Petroleum Well Location Points

Petroleum well locations were also initially compiled in spreadsheet format using Excel. The information was obtained digitally from the Dwrights/Petroleum Information Discover Scout database in May 1995. The spreadsheet file contained the township, range, and section numbers for each well location and the distance in feet of the well location from the nearest north, south, east, or west section borderline. For example, the location of the *James Federal #6* well was given as *T22, R30, and S1*, and *2247 fsl* and *1558 fel*. (The *fsl* and *fel* units refer to the distance in feet from the section's south and east lines, respectively.)

Section boundary lines running north/south and east/west are not exactly parallel with the boundary lines of adjacent sections due to meridian convergence and error that occurred during the original surveys. Furthermore, the lines that converge along the boundaries of adjoining sections may not intersect at the same point because the surveys may have been completed at different times and by different surveyors. As a result, coordinates for sections along the same north/south or east/west axes deviate considerably from what would be expected from a perfectly rectangular grid. For example, T21, R31, S01 has a northeast X state-plane coordinate of 688,308, and T21, R31, S36, located approximately five miles (five sections) directly south of S01, has a northeast X state-plane coordinate of 688,460.

These inconsistencies made it difficult to accurately plot the well locations on a computer-generated map using the TRSlines coverage. To reduce plotting errors, location coordinates were assigned to each well using the nearest USGS-established northeast section corner in the file

“Main.Rep” as a reference point from which the distances (in feet) from the x- and y-axis section lines were calculated. To ensure that the appropriate section corner in the “Main.Rep” digital file was used, the section the well was located in was divided into four quadrants (labeled A, B, C, and D) (see Figure C-2).

Figure C-2. Example of township, range, and section quadrants used to define state-plane coordinates for well locations.

The following procedure was used to assign the location coordinates to each well:

If a well location was originally designated a certain distance from the section's north and east lines (e.g., Y-ft *fnl*, X-ft *fel*), the well was assumed to be located in that section's B quadrant. Thus, referring to the example in Figure C-2, the northeast corner of T22, R31, S31 would be used as the coordinate reference point. The coordinates for this point would be calculated as follows:

Section 31 northeast corner X coordinate - (X-ft *fel*) = X coordinate of well location,

and

Section 31 northeast corner Y coordinate - (Y-ft *fnl*) = Y coordinate of well location.

If a well location was originally designated a certain distance from the section's south and east lines (i.e., *fsl*, and *fel*), the well was assumed to be located in the section's quadrant D. Thus, again referring to Figure C-2, the northeast corner of Section 6 would be used as the reference point to determine the X and Y coordinates for the well. These would be calculated as follows:

Section 6 northeast corner X coordinate - (X-ft *fel*) = X coordinate of well location,

and

Section 6 northeast corner Y coordinate + (Y-ft *fsl*) = Y coordinate of well location.

If a well location was originally designated a certain distance from the north and west lines (*fnl*, *fwl*), the well was assumed to be located in quadrant A. Thus, using the northeast corner of Section 36 as the reference point, the well's X and Y coordinates would be calculated as follows:

Section 36 northeast corner X coordinate + (X-ft *fwl*) = X coordinate of well location,

and

Section 36 northeast corner Y coordinate - (Y-ft *fnl*) = Y coordinate of well location.

Finally, if a well location was originally designated a certain distance from the south and west lines (*fsl*, *fwl*), the well was assumed to be located in quadrant C. Thus, the northeast corner of Section 1 would be used as the reference point to determine the well's X and Y coordinates, as follows:

Section 1 northeast corner X coordinate + (X-ft *fwl*) = X coordinate of well location,

and

Section 1 northeast corner Y coordinate + (Y-ft *fsl*) = Y coordinate of well location.

It should be noted that, in some cases, the sections south or west of the well location were in a different Township or Range. This was taken into account in the calculations when determining the X and Y coordinates of these wells.

Data Reformatting and Standardization

Information from the 548 well records in the Dwights database was originally downloaded onto an Excel spreadsheet. Much of the information needed to be reformatted prior to importing to Arcview. Dates originally entered as string characters were reformatted to date values. Data strings consisting of numbers were reformatted to numeric values. In addition, elevation and depth fields were standardized so that all measurements were represented as feet below ground level rather than using the reference points in the Dwights database (kelly bushing (KB) and derrick floor). KB standard adjustment factors (see Table C-1) were used in calculating the new depths because many wells did not have recorded KBs. These adjustment factors were derived from typical rig sizes used to drill wells of various depths. New well depths and elevations were calculated as follows:

The KB adjustment was subtracted from the total depth recorded on the USGS spreadsheet. For example, a well with a depth recorded as 8,050 feet was assumed to have a KB height of 15 feet. The new depth would be calculated as 8,035 feet (8050 ft - 15 ft) below ground level. Similarly, the depth at the base of each casing string was converted into a depth below ground level.

Table C-1. KB Adjustment Factors Used to Standardize the Well Depths from the Dwights/Petroleum Information Discover Scout Database

Depth (ft)	KB Adjustment (ft)
0 - 7,000	11
7,001 - 9,999	15
10,000 - 13, 999	20
≥ 14,000	25

Analyses

Analyses were performed on the well data obtained from the Dwights/Petroleum Information Discover Scout database. This is the most comprehensive commercially available database available on petroleum wells drilled within a 10-mile radius of WIPP. Well data from Dwights was incorporated into a GIS for map display and query purposes using Arc/Info and Arcview software. The Dwights well data consisted of well category and hydrologic, geologic, geographic, and drilling parameters. Examples include total well depth, stratigraphic units encountered and their depths, porosity of the various strata, latitude and longitude coordinates, drilling company, dates of drilling activity, casing sizes, and depths installed.

Arcview allowed for defining the spatial relationships between attribute data in the Dwights database and provided a graphic interface that could be used to develop queries and display the well information in a variety of different formats. For example, it is possible to query information on oil, gas, and injection wells drilled to depths greater than 2,000 ft prior to 1990 within two miles of the WIPP repository and then display and print the results in a combination of formats (e.g., tables, bar-charts, pie-charts, line graphs, scatter plots) and/or as a map. Spatial relationships evaluated in this study included those for geographic references to various well categories, stratigraphic unit depths, and well casing sizes.

Dwights Database

The Dwights/Petroleum Information Discover Scout database contained 11 well types: 1) gas, 2) oil, 3) dry and abandoned, 4) disposal, 5) wells in progress (currently being drilled but not yet completed), 6) injection, 7) plugged and abandoned, 8) shut-in, 9) suspended, 10) canceled (permit issued but then canceled), and 11) unknown wells. The database contained 548 records for wells located within a 10-mile radius of WIPP. These 548 records consisted of 517 unique well locations. There were more well records than actual well locations for two reasons: 1) some wells were redrilled at later dates to greater depths, and 2) some wells were recharacterized after

drilling (e.g., some wells originally categorized as gas wells were later recategorized as oil wells if they were drilled to new horizons after depletion of the original reservoir). In either case, records pertaining to the same well location were assigned different names (e.g., American Petroleum Industry (API) numbers or Dwights ID). Information on all 548 well records can be plotted in the Arcview program so that if a specific well location is selected using Arcview's interface, data associated with several well records in the same location can be observed simultaneously.

Data on the total depths for each well type were generated directly from information queried through Arcview. The minimum and maximum total depths were recorded, and the median total depth for each well type and the standard deviations were calculated (see Table C-2). Note that approximately 5% (29 of 548) of the well records in the database did not have recorded total depths.

Table C-2. Summary of Well Types and Total Depths for Well Records in the Dwights Petroleum Well Database

Well Type	Number of Well Records			Well Total Depth Values for Wells with Depths > 0 (feet below ground level)			
	Total	Wells with Unrecorded Total Depth	Wells with Recorded Total Depth	Maximum Total Depth	Minimum Total Depth	Median Total Depth	Standard Deviation (feet)
Canceled	1	1	0	-	-	-	-
Dry & Abandoned	16	0	16	15,200	650	6,366	5,103
Disposal	8	0	8	15,935	5,040	8,435	3,518
Gas	49	1	48	17,624	8,877	14,786	1,027
In Progress	13	13	0	-	-	-	-
Injection	4	0	4	10,133	4,933	6,342	2,421
Oil	409	0	409	16,275	4,901	8,410	1,831
Plugged & Abandoned	25	1	24	15,375	44	8,120	4,387
Shut in	1	0	1	14,808	14,808	14,808	-
Suspended	5	0	5	14,690	6,371	9,035	3,052
Unknown	17	13	4	14,175	7,545	8,596	3,015
Total	548	29	519				

Well records in the ArcView database were summarized for each well category by maximum internal casing diameter in the Salado formation (the formation in which the WIPP repository is located). The following assumptions were made prior to performing the analysis:

- 1) The Salado formation exists between the depths of 1,500 and 4,500 feet below ground level within a 10-mile radius of WIPP.
- 2) All well depth values are measured from the KB.
- 3) The largest casing diameter per well also contains a nested set of smaller casings. The maximum well casing diameter that existed between the depths of 1,500 and 4,500 feet below ground level for each well record was used in the analyses.

Table C-3 shows the number of wells for each well type by maximum recorded internal casing diameter between the depths of 1,500 and 4,500 feet below ground level for well records in the database. As shown in Table C-3, 71% of the wells in Dwights database had a casing diameter of 8.625 inches between 1,500 and 4,500 feet below ground level, 8% had a casing diameter of 9.625 inches, and all known other casing diameters accounted for less than 12% of the total. Oil wells with a casing diameter of 8.625 inches accounted for 66% of the total well records in the database.

Bar graphs showing the number of wells for the various casing size categories are represented in Figures C-3 through C-6. Figures C-7 and C-8 are summary bar charts of all casing size categories for all 548 well records and for 409 oil well records, respectively. Figure C-9 summarizes the casing sizes for oil and gas wells of known casing size.

Note that, because the petroleum well data was compiled and summarized to assist with the identification of analogs to potential wellbore enlargement at WIPP during inadvertent intrusion, the use of the maximum recorded casing size was considered sufficient to generate this preliminary statistical information.

Table C-3. Number of Records for Each Well Type by Maximum Recorded Casing Size Between the Depths of 1,500 and 4,500 Feet Below Ground Level for Well Records from the Dwight's Petroleum Well Database

Well Type	Number of Well Records											
	Maximum Casing Size Between the Depths of 1,500 and 4,500 Feet Below Ground Level (inches)											
	Total	2.8	5.5	7	8.375	8.625	9.625	10.75	11	13.375	20	Casing Size Unknown
Canceled	1	-	-	-	-	1	-	-	-	-	-	-
Dry and Abandoned	16	1	-	-	-	1	-	-	1	3	1	9
Disposal	8	-	3	-	-	1	-	-	-	1	-	3
Gas	49	-	-	-	-	3	30	8	-	-	-	8
In Progress	13	-	2	-	-	2	-	-	-	-	-	9
Injection	4	-	1	-	-	2	-	-	-	-	-	1
Oil	409	-	7	1	1	361	8	8	-	2	-	21
Plugged & Abandoned	25	-	-	1	-	12	2	1	-	1	-	9
Shut-In	1	-	-	-	-	-	1	-	-	-	-	-
Suspended	5	-	1	-	-	2	1	-	-	-	-	1
Unknown	17	-	-	-	-	4	2	-	-	-	-	11
Total Number of Wells	548	1	14	2	1	389	44	17	1	7	1	72
Percent of Total	100	<1	3	<1	<1	71	8	3	<1	1	<1	13

Figure C-3. Number of disposal wells within a 10-mile radius of the WIPP site by internal casing diameter (based on information from Dwights/ Petroleum Information Discover Scout database).

Figure C-4. Number of gas wells within a 10-mile radius of the WIPP site by internal casing diameter (based on information from Dwights/ Petroleum Information Discover Scout database).

Figure C-5. Number of plugged and abandoned wells within a 10-mile radius of WIPP by internal casing diameter (based on information from Dwights/Petroleum Information Discover Scout database). Casing diameter is the largest recorded for each well record between 1,500 and 4,500 feet below ground level.

Figure C-6. Number of dry and abandoned wells within a 10-mile radius of WIPP by internal casing diameter (based on information from Dwights/Petroleum Information Discover Scout database). Casing diameter is the largest recorded for each well record between 1,500 and 4,500 feet below ground level.

Figure C-7. Summary of internal casing diameters for all 548 well records (based on information from Dwights/Petroleum Information Discover Scout database). Casing diameter is the largest recorded for each well record between 1500 and 4500 feet below ground level.

Figure C-8. Summary of internal casing diameter for oil wells within a 10-mile radius of WIPP (based on information from Dwights/Petroleum Information Discover Scout database). Casing diameter is the largest recorded for each well record between 1,500 and 4,500 feet below ground level.

Figure C-9. Summary of internal casing diameter for oil and gas wells with known casing size (based on information from Dwights/Petroleum Information Discover Scout database). Casing diameter is the largest recorded for each well record between 1,500 and 4,500 feet below ground level. (Note that the data for oil casing size 5.5 are questionable for six of the seven wells indicated.)

References

- Gonzales, M.M. 1989. *Compilation and Comparison of Test-Hole Location Surveys in the Vicinity of the Waste Isolation Pilot Plant Site*. SAND88-1065. Albuquerque, NM: Sandia National Laboratories.
- Hill, L.R., R. Aguilar, J.W. Mercer, and G. Newman. 1997. *Condensed Listing of Surface Boreholes at the Waste Isolation Pilot Plant Project through December 31, 1995*. SAND96-1960. Albuquerque, NM: Sandia National Laboratories.

WIPP
UC900-Distribution List
SAND96-2629

Federal Agencies

US Department of Energy
Office of Civilian Radioactive Waste
Management

Director, RW-4/5

Office of Strategic Planning and
International Programs Office of
External Relations

Forrestal Building
Washington, DC 20585

US Department of Energy
Albuquerque Operations Office
Attn: National Atomic Museum Library
PO Box 5400
Albuquerque, NM 87185

US Department of Energy
Office of Environmental Restoration and
Waste Management
Attn: C. Frank, EM-50
Washington, DC 20585

US Department of Energy (3)
Office of Environmental Restoration and
Waste Management
Attn: M. Frei, EM-34 / Trevion II
Director, Waste Management Projects
Washington, DC 20585-0002

US Department of Energy
Office of Environment, Safety and Health
Attn: R.P. Berube, EH-20
Washington, DC 20585

US Department of Energy (2)
WIPP Project Integration Office
Attn: S. Alcorn
L.W. Gage
PO Box 5400
Albuquerque, NM 87115-5400

US Department of Energy (4)
Carlsbad Operations Center
Attn: M. McFadden
PO Box 3090
Carlsbad, NM 88221-3090

US Department of Energy
Research & Waste Management Division
Attn: Director
PO Box 2001
Oak Ridge, TN 37831

US Department of Energy
Idaho Operations Office
Office of Waste Management
Attn: Jerry Wells
805 Energy Dr., MS-1118
Idaho Falls, ID 83402

US Department of Energy
Savannah River Operations Office
Defense Waste Processing
Facility Project Office
Attn: W.D. Pearson
PO Box A
Aiken, SC 29802

US Department of Energy
Yucca Mountain Project Office
Attn: Project Manager
PO Box 98608
Las Vegas, NV 89193-8608

US Department of Energy (2)
Technical Information Center
PO Box 62
Oak Ridge, TN 37831

US Department of Energy
Los Alamos Area Office
Attn: D. Bruce Lebrun
528 35th Street
Los Alamos, NM 87544

US Bureau of Land Management
Carlsbad Resource Area
PO Box 1778
Carlsbad, NM 88221-1778

US Bureau of Land Management
New Mexico State Office
PO Box 27115
Santa Fe, NM 87502-7115

US Environmental Protection Agency (2)
Radiation Protection Programs
Attn: Frank Marcinowski (6602J)
401 M Street, SW
Washington, DC 20460

US Environmental Protection Agency,
Region 6
Attn: C. Byrum, 6T-ET
1445 Ross Ave.
Dallas, TX 75202

Defense Nuclear Facilities Safety Board
Attn: D. Winters
625 Indiana Ave. NW, Suite 700
Washington, DC 20004

Nuclear Waste Technical Review Board
Attn: Library (2)
1100 Wilson Blvd., Suite 910
Arlington, VA 22209-2297

State Agencies

New Mexico Bureau of Mines and Mineral
Resources
Socorro, NM 87801

New Mexico Energy, Minerals and Natural
Resources Department
Attn: Librarian
2040 South Pacheco
Santa Fe, NM 87505

NM Radioactive Waste Consultation Task
Force (2)
(Governor's WIPP Task Force)
Attn: Jennifer Salisbury, Chairwoman
Chris Wentz, Senior Policy Analyst
2040 South Pacheco
Santa Fe, NM 87505

New Mexico Environment Department
Secretary of the Environment (1)
Attn: J. Espinosa
PO Box 968
1190 St. Francis Drive
Santa Fe, NM 87503-0968

New Mexico Environment Department
Attn: P. McCasland
WIPP Project Site Office
PO Box 3090
Carlsbad, NM 88221-3090

New Mexico State Engineer's Office
Attn: M. Chudnoff
PO Box 25102
Santa Fe, NM 87504-5102

Environmental Evaluation Group (5)
Attn: R. Neill
7007 Wyoming Blvd. NE, Suite F-2
Albuquerque, NM 87109

**WIPP Committee, National Research
Council's Board on Radioactive
Waste Management**

National Research Council (2)
Board on Radioactive Waste Management
Attn: Angela Taylor
2101 Constitution Ave. NW
Harris Bldg. HA 456
Washington, DC 20418

Howard Adler
Oxyrase, Inc.
7327 Oak Ridge Highway
Knoxville, TN 37931

Rodney C. Ewing
Department of Geology
University of New Mexico
Albuquerque, NM 87131

Charles Fairhurst
Dept. of Civil and Mineral Engineering
University of Minnesota
500 Pillsbury Dr. SE
Minneapolis, MN 55455-0220

B. John Garrick
PLG, Incorporated
4590 MacArthur Blvd., Suite 400
Newport Beach, CA 92660-2027

Leonard F. Konikow
US Geological Survey
431 National Center
Reston, VA 22092

Christopher G. Whipple
ICF Kaiser Engineers
1800 Harrison St., 7th Floor
Oakland, CA 94612-3430

Thomas A. Zordan
Zordan Associates, Inc.
3807 Edinburg Dr.
Murrysville, PA 15668

G. Ross Heath
College of Ocean & Fishery Sciences
University of Washington
1013 NE 40th Street
Seattle, WA 98105-6698

Robert J. Budnitz
President, Future Resources Associates, Inc.
2039 Shattuck Ave., Suite 402
Berkeley, CA 94704

**Corporations/Members
of the Public**

EG & G Idaho
1955 Fremont Street
Attn: T.I. Clements
Idaho Falls, ID 83415

Golder Associates, Inc.
Attn: R. Kossik
4104 148th Avenue NE
Redmond, WA 98052

John Hart and Associates, P.A.
Attn: J.S. Hart
2815 Candelaria Road NW
Albuquerque, NM 87107

INTERA, Inc.
Attn: A.M. LaVenue
1650 University Blvd. NE, Suite 300
Albuquerque, NM 87102

Lawrence Berkeley Laboratory
Attn: J. Long
Building 50 E
Berkeley, CA 94720

RE/SPEC, Inc. (2)
Attn: Angus Robb
4775 Indian School NE, Suite 300
Albuquerque, NM 87110

Southwest Research Institute
Nuclear Waste Regulatory Analysis (2)
Attn: P.K. Nair
Dr. Hersh K. Manaktala
6220 Culebra Road
San Antonio, TX 78228-0510

Tech Reps, Inc. (1)
Attn: J. Chapman
5000 Marble NE
Albuquerque, NM 87110

Westinghouse Electric Corporation (3)
Attn: Library
B.A. Howard
R.F. Kehrman
PO Box 2078
Carlsbad, NM 88221

Universities

University of California
Mechanical, Aerospace, and Nuclear
Engineering Department
Attn: D. Browne
5532 Boelter Hall
Los Angeles, CA 90024

University of California
Nuclear Engineering Department
Attn: W. Kastenber
4153 Etcheverry Hall
Berkeley, CA 94720-1730

University of California
Engineering and Applied Science
Attn: D. Okrent
48-121A Engineering IV
Los Angeles, CA 90024-1597

University of California
Mine Engineering Department
Rock Mechanics Engineering
Attn: N. Cook
Berkeley, CA 94720

University of Hawaii at Hilo
Business Administration
Attn: S. Hora
Hilo, HI 96720-4091

University of Illinois
Department of Geology
Attn: C. Bethke
1301 W. Green St.
Urbana, IL 61801

University of New Mexico
Geology Department
Attn: Library
Albuquerque, NM 87131

University of Wyoming
Department of Civil Engineering
Attn: V.R. Hasfurther
Laramie, WY 82071

Libraries

Thomas Brannigan Library
Attn: D. Dres
106 W. Hadley St.
Las Cruces, NM 88001

New Mexico State Library
Southwest Room
Attn: N. McCallan
325 Don Gaspar
Santa Fe, NM 87501-2777

New Mexico Tech Library
Government Documents
Campus Station
Socorro, NM 87801

New Mexico Junior College
Pannell Library
Library Acquisitions
Attn: Karen Elliott
5317 Lovington Highway
Hobbs, NM 88240

Carlsbad Museum
WIPP Public Reading Room
Attn: Pat Jablonsky
418 W. Fox Street
Carlsbad, NM 88220

University of New Mexico
Zimmerman Library
Government Publications Department
Albuquerque, NM 87131

**NEA/ Performance Assessment
Advisory Group**

A. E. Van Luik
Yucca Mountain Site Characterization
Office
PO Box 98608
Las Vegas, NV 89109

**NEA/Probabilistic System
Assessment Group (PSAG)**

Intera Information Technologies
Attn: M.J. Apted
3609 South Wadsworth Blvd.
Denver, CO 80235

US Nuclear Regulatory Commission (2)
Attn: R. Codell
N. Eisenberg
Mail Stop 4-H-3
Washington, DC 20555

Battelle Pacific Northwest Laboratories
Attn: P.W. Eslinger
MS K2-32
PO Box 999
Richland, WA 99352

Center for Nuclear Waste Regulatory
Analysis (CNWRA)
Southwest Research Institute
Attn: B. Sagar
PO Drawer 28510
6220 Culebra Road
San Antonio, TX 78284

**Geostatistics Expert Working Group
(GXG)**

Ghislain de Marsily (GXG Chairman)
Universite Pierre et Marie Curie
Laboratoire de Geologie Applique
4, Place Jussieu
T.26 - 5^e etage, Caba 123
75252 Paris Cedex 05
FRANCE

Dennis McLaughlin
Parsons Laboratory
Room 48-209
Department of Civil Engineering
Massachusetts Institute of Technology
Cambridge, MA 02139

Foreign Addresses

ONDRAF
Attn: P. Manfroy
Place Madou 1 B.24-25
B. 1030 Brussels
BELGIUM

Atomic Energy of Canada, Ltd. (2)
Chalk River Laboratories Waste
Management Operations
Attn: M.E. Stevens
B.W. Goodwin
Chalk River, Ontario, KOJ 1JO
CANADA

Juhani Vira
Teollisuuden Voima Oy (TVO)
Annankatu 42 C
SF-00100 Helsinki Suomi
FINLAND

Jean-Pierre Olivier
OECD Nuclear Energy Agency
Head, Radiation Protection & Waste
Management Division (2)
Le Seine St. Germain
12, Boulevard Des Iles
92130 Issy-les-Moulineaux
FRANCE

Claude Sombret
Centre D'Etudes Nucleaires
De La Vallee Rhone
CEN/VALRHO
S.D.H.A. B.P. 171
30205 Bagnols-Sur-Ceze
FRANCE

Bundesanstalt für Geowissenschaften
und Rohstoffe
Attn: M. Langer
Postfach 510 153
D-30631 Hannover
GERMANY

Gesellschaft für Anlagen und
Reaktorsicherheit (GRS) mbH
Attn: B. Baltes
Theodor-Hess-Str. 4
38122 Braunschweig
GERMANY

Wolfgang Muller
1 STEC
Abteilung Abfallbeseitigung
Schwertnergasse 1
D-50667 Köln
GERMANY

Institut für Bergbaukunde und
Bergwirtschaftslehre der Technischen
Universität Clausthal
Attn: K. Kuhn
Erzstrasse 20
D-38678 Clausthal Zellerfeld
GERMANY

Bundesamt für Strahlenschutz
Attn: P. Brenneke
PO Box 10 01 49
38201 Salzgitter
GERMANY

Shingo Tashiro
Radioactive Waste Management Center
Mori Building #15 8-10
Toranomon 2-Chrome
Minato-Ku, Tokyo, 105
JAPAN

Gesellschaft für Anlagen-und
Reaktorsicherheit (GRS) mbH
Library, Attn: Fr. Soelter
Postfach 2126
D-38011 Graunschweig
GERMANY

Netherlands Energy Research Foundation
Attn: T. Prij
3 Westerduingwed
PO Box 1
1755 Zg Petten
THE NETHERLANDS

Johan Andersson
 INTERA Information Technologies
 Vallvagen 22
 S-125 33 Alvsjö
 SWEDEN

Fred Karlsson
 Svensk Kärnbränsleforsörjning AB
 SKB Library
 Box 5864
 102 40 Stockholm
 SWEDEN

Nationale Genossenschaft für die
 Lagerung Radioaktiver Abfälle (2)
 Attn: S. Vomvoris
 P. Zuidema
 Hardstrasse 73
 CH-5430 Wettingen
 SWITZERLAND

AEA Technology
 Attn: J.E. Tinson
 B4244 Harwell Laboratory
 Didcot, Oxfordshire OX11 0RA
 UNITED KINGDOM

AEA Technology
 Attn: J.H. Rees
 B.424.4
 Harwell
 Oxon OX11 0RA
 UNITED KINGDOM

AEA Technology
 Attn: W.R. Rodwell
 O44/A31 Winfrith Technical Centre
 Dorchester
 Dorset DT2 8DH
 UNITED KINGDOM

Dr. G.M. Burney
 RWMAC Secretary
 A528 Romney House
 43 Marsham Street
 London SW1P 3PY
 UNITED KINGDOM

D. R. Knowles
 British Nuclear Fuels, plc
 Risley, Warrington
 Cheshire WA3 6AS, 1002607
 UNITED KINGDOM

Internal

<u>MS</u>	<u>Org.</u>	
0101	0001	C. Paul Robinson
1324	6115	P.B. Davies
1320	6831	E.J. Nowak
1322	6121	J.R. Tillerson
1395	6800	L.E. Shephard
1395	6811	S.Y. Pickering
1335	6000	W. D. Weart
1335	6801	M.Y. Chu
1345	6115	A.R. Lappin
1326	6117	L.S. Costin
1328	6849	D.R. Anderson
1328	6848	H.N. Jow
1395	6841	V.H. Slaboszewicz
1341	6832	J.T. Holmes
1343	6849	R.E. Thompson
1330	6811	K. Hart (2)
1330	4415	NWM Library (20)
9018	8940-2	Central Technical Files
0619	12630	Review & Approval Desk for DOE/OSTI (2)
1341	6832	B. Butcher
1341	6822	L. Dotson
1326	6851	R. Aguilar
1328	6849	D. Boak (10)